UNCLASSIFIED

AD NUMBER

AD829115

NEW LIMITATION CHANGE

TO

Approved for public release, distribution unlimited

FROM

Distribution authorized to U.S. Gov't. agencies and their contractors; Critical Technology; 17 JUL 1962. Other requests shall be referred to Space and Missile Systems Organization, Los Angeles, CA.

AUTHORITY

SAMSO USAF ltr, 28 Feb 1972

THIS PAGE IS UNCLASSIFIED



2//

11. Mail11 MISSILE 1F INVESTIGATION REPORT This document is subject Run S1-613-14-01 . 1 Controls and to 📬 🖉 🖉 _ .: ioreign ea 🗈 v a station -BOWLFILL --na. i.i. . . be made only Run Date: 13 May 1962 with pror approval of: GENERAL DYNAMICS ASTRONAUTICS Issue Date: 17 July 1962 JUL 20 1962 Attn: SMSD Report No. AC-62-0031 LIBRARY Copy No. 4 WS 107A (ATLAS) CLASSIFICATION CHANGED TO: э UNCLASSIFIED AUTHORIZED BY: AIR FORCE LETTER SAN BERNARDINO AIR MATERIEL AREA (SBAMA) s) J DATED 17 NOVEMBER 1965 э**r** ĴØĹ RECLASSIFIED BY: REE DEPT. 190-1 DATE 12-13 gèr Ass General Dynamics/Astronautics General Dynamics/Astronautics Durgede pluid on dr. by Security Dept., 112/66. An. D. M. McCray A. C. Chase Manager - STL Responsible Representative Sycamore Field Office Rocketdyne Field Office - Sycamore S. R. Simpson Acting Site Manager - Acoustica Associates Acoustica Field Office .. Sycamore meaning of the Esplorage La Marined person is prohibited rs, Title by law. This document centeles informati 18, U.S.C., Soction 793 and 794.



TABLE OF CONTENTS

Title Page

Table of Contents

Forward

List of Abbreviations

- 1.0 Introduction
- 2.0 Summary
- 3.0 Conclusions
- 4.0 Recommendations
- 5.0 Detailed Examination
 - 5.1 Data Examination
 - 5.2 Hardware Examination
 - 5.3 Engineering Film Examination
 - 5.4 Data Analysis
 - 5.5 Hardware Analysis
- 6.0 Enclosures

C

- 6.1 Command Net Voice Tap
- 6.2 Official Observer Reports
- 6.3 Photographs
- 6.4 Pertinent Data Traces
- 6.5 Fragmentation Survey
- 6.6 Site I and AMR Water Survey
- 6.7 Pertinent Correspondence
 - 6.7.1 Explosive Force and Yield Report 6.7.2 Acoustica Report
- 6.8 Missile History
- 6.9 Investigation Board and Committee Assignments
- 6.10 Witness Interrogation
- 7.0 listing of Damage
- 8.0 Distribution



This document contains information affecting the national defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.



FORWARD

This report presents the findings of the Accident Investigation Board investigating the explosion of Missile IF during static firing S1-613-14-01 at-Sycamore--Canyon Test Site S1. This report includes all pertinent information available to date, and will be appended as additional information becomes available.

The Board and Committee personnel assignments are presented in Section 6.9 of this report.

5

ŧ



This document contains information attacting the national defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C., Socilai:793 and 794, the transmission or revolution of which in any manner to an unsutherized person is prohibited by law.

4





ノヨーた

2

*

(



This decument contains information affecting the national defense of the United States within the meaning of the Espianage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unsutherized person is prohibited by law.

1.0-1



1.0 INTRODUCTION

C

()

Run S1-613-14-01 of Atlas Missile IF was conducted at 1347 hours, 13 May 1962, at Sycamore Test Stand Sl. The run was prematurely terminated after 1.77 seconds of engine operation by the automatic cutoff circuit monitoring redline recorder Pl325T, the Engine Compartment Ambient Temperature, when the indicated temperature exceeded the upper redline limit of 250 dgf. Visual evidence of fire in the vicinity of the missile thrust section was observed at this time and all emergency water systems were immediately activated in an effort to minimize additional damage. The flames, which had rapidly enveloped the missile lower tank section, continued to burn at a generally constant rate until, at 5.4 seconds, a high order explosion was apparent in the area of the thrust section. A final explosion, occurring at 6.4 seconds, completely destroyed the missile and missile service tower. The blast and subsequent fire severely damaged or destroyed the majority of equipment in the surrounding area, including the Atlas Utility Building, The blast also severely damaged Centaur vehicle C-3 and imparted minor damage to the Centaur Test Stand (S4) and the Centaur Utility Building. No personnel were injured as a result of the explosion of subsequent fire.

An Accident Investigation Board was formed, as a result of the explosion, to conduct a detailed examination and analysis of all data and recovered hardware. It is the intent of this report to document all pertinent findings of the Board, and to present those recommendations the Board considers necessary to prevent a possible recurrence of this nature.



This decement contains information affecting the national defense of the United States within the meaning of the Espionoge Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revolution of which in any manner to an unauthorized person is prohibited by law.



2.0 SUMMARY

()

()

Missile 1F, at Sycamore Static Test Stand SL, was destroyed by explosion during firing Run SL-613-14-01, conducted on 13 May 1962. This was the second firing of the Block III test program and the minth static firing of Missile 1F since erection on 7 March 1961. A previous attempt to conduct this test, on 12 May, was aborted 319.8 seconds after start countdown due to problems in the Rough Combustion Cutoff circuitry. These problems were unrelated to the events culminating in missile destruction.

Scheduled engine durations for this test were 40 seconds boosters, 60 seconds sustainer, and 65 seconds verniers. Actual durations were 1.77 seconds of booster 1 operation and 1.23 seconds of sustainer operation. Vernier engine ignition was not obtained. The booster 2 engine, due to loss of electrical control to the main lox valve solenoid, continued to operate until the first major explosion at 5.4 seconds. Bootstrap of the sustainer engine was not achieved due to abnormal engine head suppression valve.operation.

This run included a scheduled 60 minute hold at Ready for Commit to demonstrate the capability of entering the commit sequence after a prolonged hold period with lox aboard. Actual hold duration was 64.79 minutes.

Missile IF was an R & D missile functionally comparable to production F series missiles. Certain modifications were installed, however, including butterfly shutoff valves in the lox and fuel staging disconnects, R & D thrust section lift-off cameras, staging camera bracketry on the missile fuel tank, and a rotated sustainer lox regulator discharge elbow and vernier lox supply flex hose modification.

The investigation of the explosion was conducted under the direction of the accident Investigation Board. The following sections present the conclusions arrived at by the Board, and a detailed discussion of the examinations and analyses of the various Board Working Committees. The results of special investigations being conducted by North American Aviation's Rocketdyne Division and General Dynamics Astronautics were not complete at the time of publication of this report and will be issued, with comments from the Investigating Board, as a supplement at a future date.





This decument contains information affecting the national defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revolution of which in any manner to an unauthorized person is prohibited by law.

2.0-1



3.0 CONCLUSIONS

Analysis of all recorded data and recovered sustainer engine hardware indicates that missile destruction was the culmination of a sequence of events initiated by improper operation of the sustainer engine main lox valve (head suppression valve). The improper operation consisted of an approximate 350 millisecond delay in valveopening. Although laboratory tests have failed to exactly duplicate the problem, the most probable cause of valve opening delay (hesitation at the four degree open position) was shaft seizure resulting from the freezing of moisture and rust in the valve idler shaft bearing housing on the opposite end of the shaft from the valve actuator mechanism. When the valve began its opening movement. the sustainer pump was at its maximum spin charge speed. The abnormal loads thereby imposed on the pump shaft produced sufficient shaft deflection to allow the rotating impeller to contact the pump case wear ring. This rubbing generated a fire within the pump case, in the vicinity of the impeller upstream face, which created sufficient internal pressure to fracture the pump volute at its parting line and rapidly expel the forward portion from the main case. The resulting damage to the propellant and hydraulic ducting created an uncontrollable thrust section fire and subsequent explosion of the Missile.



This decument contains infermetion affecting the notional defense of the United States within the meaning of the Espionoge Luws, Title 18. U.S.C., Section 793 and 794, the transmission or revolution of which in any manner to an unauthorized person is prohibited by law.

3.0-1



4.0 RECOMPENDATIONS

()

The following recommendations were established by the Accident Investigation Board as a result of the Missile IF explosion:

- 1. Action be taken to determine a method for indicating or precluding the presence of moisture in the HS valve idler shaft bearing housing. Possible methods are:
 - a) Use of improved lip seal.
 - b) Use of a dessicant plug to absorb whatever moisture is ingested into the housing.
 - c) Procedure changes to preclude introduction of moisture into the HS valve bearing housing.
- 2. A study be conducted to determine whether increased ground hydraulic system pressure is advisable.
- 3. Further studies should be conducted on an urgent basis to determine the feasibility of precluding interference between the rotating and stationary elements in the lox pump. Some possible fixes that should be considered are:
 - a) A non-combustible liner such as teflon or Kel-F in the wear ring and inlet assembly which would not cause failure should rubbing occur.
 - b) Increased clearances to permit additional shaft deflections.
- 4. A method of accurate time correlation be provided on all motion picture data, (Accomplished for all future Sycamore Testing).
- 5. Conduct a detailed study of time and data correlation between all instrumentation recording channels and motion picture data.



This document conteins information affecting the notional defense of the Unifed States within the meaning of the Espienced Laws, Title 18. U.S.C., Section 793 and 794, the transmission or revolution of which in any manner to an unauthorized person is prohibited by law.

4.0-1



Page 5.1-1

5.0 DETAILED EXAMINATION

5.1 DATA EXAMINATION

()

1

The first indication of abnormal sustainer engine operation was noted at 0.680 seconds, following booster engine ignition, when the H.S. valve began its opening movement. The valve position data indicated movement from closed to the 5 degree open position by 0.55 seconds. The trace remained at this level until 1.03 seconds at which time the trace indicated valve opening movement at a normal rate. The valve reached the 38 degropen position at 1.37 seconds. After this time the valve position data indicated closing movement until 1.62 seconds, at which time the trace reached the approximate closed position where it remained until loss of data. As a consequence of the late opening movement of the H.S. valve, the P.U. valve did not begin its opening movement until 1.16 seconds. The valve opening rate was normal and the valve reached the full open position at 1.87 seconds. It remained full open until 1.97 seconds, at which time it began moving closed and reached an approximate 7 degree open position at 2.59 seconds.

Sustainer lox pump inlet pressure data indicated an increasing trend beginning at 1.29 seconds, reaching the off scale high (OSH) limit at 1.32 seconds. After this time, data was not recovered from this measurement. This lox system pressure surge was also observed in both booster lox pump inlet pressure traces, which reached the OSH limit at 1.33 seconds. Both of these measurements, however, re-entered the information band at 1.36 seconds and continued to record valid data until loss of the missile. Reflections of a lox system pressure surge were observed in the sustainer thrust chamber lox injection manifold pressure measurement at 1.34 seconds and in the sustainer gas generator lox regulater discharge pressure measurement at 1.35 seconds.

At 0.75 seconds the measurement sensing the sustainer gas generator lox injection pressure indicated a rise in pressure, reaching 60 psig by 1.40 seconds. It remained at this approximate level until 1.91 seconds, at which time it returned to approximately 0 psig.

At 1.65 seconds the sustainer gas generator blade valve closed micro switch deactivated and reactivated at 1.89 seconds. In the interval that the closed micro switch was deactivated there was no indication of activation of the valve open microswitch.

The sustainer lox pump seal cavity pressure measurement indicated abnormal data during the sustainer start sequence. The pressure increased from 0 psig at 0.6 seconds and reached 4.56 psig by 0.9 seconds. The pressure then decreased to 3.62 psig by 1.1 seconds and spiked to 12.8 psig at 1.6 seconds. The pressure had decayed to 0.8 psig by 1.95 seconds. Pressure increases of the magnitudes indicated were not observed on previous firings of this missile.



This deciment contains information affecting the national datance of the United States within the meaning of the Espionage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revolution of which in any menner to an unauthorized person is prohibited by law. The initial peak of the sustainer pump speed during solid propellant gas generator operation was approximately 1500 RPM higher than on past tests of this missile. Following 1.34 seconds, the speed data indicated an increase from 3,745 RPM to 10,125 RFM by approximately 1.85 seconds. The increasing speed trend over this time interval was not the result of bootstrap of the engine.

5.1-2

5.52

1.

For this test three accelerometers had been installed on the sustainer lox pump inlet flange to measure flange vibration along the missile X, Y, and Z axis. No data was recovered from the accelelerometer sensing vibration in the X axis. Low amplitude, high frequency vibration data appeared on both the Y and Z axis accelerometer at 0.56 seconds. A sharp increase in vibration intensity occurred at 0.68 seconds concurrent with the initial indicated opening movement of the H.S. valve. Between 0.68 and 0.77 seconds, maximum vibration levels were 45 g peak to peak at a predominant frequency between 675 and 725 cps. An unrealistic shock load was indicated on these measurements at 0.87 seconds. Average maximum vibration levels from .90 to 1.34 seconds varied between 20 and 80 g peak to peak. Since this was the first time these measurements were installed on Missile 1-F, comparison data is not available. Shock impulses and simultaneous loss of data occurred between 1.34 and 1.35 seconds on both flange measurements.

Thrust section ambient temperature data appeared normal until approximately 1.4 seconds, at which time the four ambient temperatures began increasing toward OSH. A cutoff signal was generated automatically by P1325T, the engine compartment ambient temperature, at 1.77 seconds when this measurement passed the upper redline limit of 250 dgf.

f 1

Data recorded by the four dual element (high and low temperature) thermisters during the firing was also normal until approximately 1.34 seconds. The four thermister temperature measurements (low temperature sensing elements) installed in the thrust section indicated a drop in engine conpartment ambient temperature starting at approximately T-18 seconds. This is coincident with the initiation of the 10 second engine compartment CO₂ purge.

The engine compartment ambient thermocouples verified the steady state levels of the thermister data. The thermocouples had too wide a range and too slow a response time to show the transients reflected by the thermister.

Measurement A1353T (Engine environment A-frame) showed a temperature drop from 33.5 dgf to 19.5 dgf at T-18 seconds. The temperature rose slowly to 21 dgf by T-10 seconds when a sudden increase to 27 dgf occurred. This temperature was maintained until ignition. This thermister was located on the staging rail support (A-frame) in Quad II at Station 1221. The A-frame was approximately 35 dgf from the missile Y-Y axis and the transducer for A1353T was 13.7 inches inboard of the point where the A-frame joined the rail.



This decument controlms information affecting the national defense of the Dhited States within the meaning of the Espionage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

Measurement Al361T showed a temperature decrease from 34.5 dgf to 27.5 dgf at T-18 seconds. This temperature was maintained until T-11 seconds when a sudden rise to 33.5 dgf was indicated. The temperature then decayed slowly to 31 dgf at ignition. The transducer for Al361T (Engine environment- Quad II rail) was located on the inboard side of the staging rail in Quad II at Station 1188. The rail was approximately 35 dgf from the Y-Y axis. Thermisters Al353T and Al361T were displaced from each other approximately 13 inches horizontally and 33 inches vertically.

At T-19 seconds thermister Al350T (Engine environment sustainer hydraulic panel) began a slow decline from 28.5 dgf reaching 23.5 dgf by T-11 seconds. The temperature increased to 24 dgf by ignition. This thermister was located on the staging rail A-frame in Quad IV, near Station 1221. The thermister installation was approximately 35 dgf from the Y-Y axis and 12 to 14 inches inboard from the point where the A-frame joined the staging rail.

Thermister Al363T (Engine environment-sustainer lube tank) indicated a rise from 18 dgf to 21 dgf between T-20 and T-17 seconds. The temperature then fell erratically to a minimum of 9 dgf at T-5 seconds when a slow rise began, reaching 15.5 dgf at ignition. The thermister for Al363T was attached to the sustainer lube oil tank at Station 1240 in Quad I.

The behavior of the four thermister temperature measurements beginning at T-18 seconds is believed to result from the engine compartment CO₂ purge. This purge was initiated at T-18 seconds and lasted for 10 seconds. It's purpose was to insure an inert atmosphere inside the thrust section during the captive firing. The CO₂ was introduced through two nozzles which extended through the fire shield (Station 1269). These nozzles were on the Y-Y axis, with one on each side of the sustainer engine. Both nozzles were fed by a common CO₂ supply and line. The line was "teed" at the fireshield to flow into the nozzles.

(]

Thermister data recorded during the Firing Acceptance Test (FAT) tanking were very similar in time and temperature to the firing test data. The thrust CO_2 purge was also activated at the same time and duration as used during the FAT tanking.

An attempt has been made to correlate the 1-F and 11-F thermister data. During the 11-F flight countdown the thermister equivalent to A1353T indicated a sharp drop and recovery. The magnitude of this drop was 27 dgf below the steadystate level of 88 dgf and it occurred at lox slug stop. There was no similar indication during the 1-F test at rapid topping complete.

The sustainer/vernier hydraulic system pressure data indicated a lower pressure drop than normal at the time the H.S. valve data indicated initial opening movement at 0.68 seconds. Normally this pressure will decrease 150 to 200 psig at this time. On this test the pressure decreased only 20 psig. The bootstrap trend of this measurement was normal until 1.24 seconds, after which time the measurement hesitated and then began an abnormal decay, reaching 0 psig by 2.1 seconds.



This decument contains information affecting the national defense of the United States within the movining of the Espionopol Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revolution of which in any monner to an unauthorized person is prohibited by law.



Abnormal data was observed in autopilot system performance at 1.15 seconds. At this time the yaw displacement gyro (YDG) output signal showed evidence of a disturbance which induced a 0.48 cps sinusoidal output (0.21 degrees peak-to-peak) on the YDG. At this approximete time, the booster engines were in the transition to mainstage operation. Investigations of displacement gyro data on previous firings of missile 1-F did not show this YDG disturbance. Normal data was recorded on remaining autopilot measurements until the 1.35 second time period.

The cutoff signal generated by the engine compartment ambient thermocouple (P1325T) at 1.77 seconds resulted in a normal shutdown of the B-l engine. The cutoff signal had no effect on the B-2 engine nor did the activation of the automatic cutoff backup signal at 2.30 seconds. The B-2 engine continued to operate at a near full thrust level until at least 5.4 seconds, approximately one second prior to loss of the missile. The majority of B-2 engine prarmeters were lost at 5.4 seconds. Final explosion of the missile did not occur until approximately 6.4 seconds, at which time all remaining instrumentation was lost.

Ě

()



This decument centains information attacting the national detense of the United States within the meaning of the Esplonage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

5.1-4



5.2 <u>HARDWARE EXAMINATION</u>

A thorough search of the area surrounding the test stand was initiated the day following the explosion in an effort to locate and identify all possible missile components. Recovery of hardware from the collapsed tower structure was delayed until the tower remains had been sufficiently shored to provide for the necessary personnel safety. All recovered fragments were tagged as to identity, their location noted on a dispersion chart, and then collected by missile system to facilitate examination and analysis of the hardware for the purpose of ascertaining the agent of missile destruction. Considerable emphasis was placed on obtaining comprehensive documentation of all fragments with regards to heat and smoke damage and nature of failure. Photographs of the collected hardware were also obtained to provide a permanent documentation.

Presented in this section are the condition of recovered hardware, significant hardware items that were not recovered or identified, and special items of interest with respect to hardware condition. Results and conclusions of the hardware analyses are presented in Sections 5.5.

5.2.1 PROPULSION SYSTEM HARDWARE

This section presents pertinent information concerning the condition of recovered propulsion system components. For clarity, the propulsion system is discussed by major sub-assembly with emphasis on sustainer engine components.

A. Sustainer Engine

- 1. Chamber The lox dome, injector, combustor section, and hydraulic manifold were found as one unit in the skim pond. The exhausterator and lower expansion section were separated from the main chamber below the throat area and also found in the skim pond. There was no evidence of chamber internal overpressurization.
- 2. Head Suppression and Ignitor Fuel Valves The HS valve was found attached to the lox dome inlet, although all mounting bolts were either stretched or missing. The ignitor fuel valve was separated from its linkage housing to the HS valve, with the ignitor valve cam follower locked in the full open position by deformation of the cam follower supports. These were pinched together by the deformation of the HS valve actuator linkage housing.
- 3. Propellant Utilization Valve The complete PU valve with majority of plumbing attached was intact on the sustainer combustion chamber.



This decument contains information affecting the notional defance of the United States within the meaning of the Espionage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revolution of which in any manner to an unauthorized person is prohibited by law.

5.2.1 (continued)

4. Ayuraulic weeks - we hydraulic control manifold including the FU and HS surve volves and vajority of plumbing sere intact on the main charber. Several manifold tub's sere severed at the lox pump support bracket.

5.2-2

- 5. Hypergol Ignitor Chamber Found attached to the main chamber with the retaining lin retracted from case.
- 6. Oxidizer Regulator Found intact although mounts were broken from pump attachment.
- 7. Fower Fackage The lox rump, fuel pump, and rearcase were found as a unit. The lox rump case was split at its maximum periphery over the entire circumference. The inlet side of the pump case was found separate from the power package east of the flame deflector spillway approximately 300 feet from the test stand with the inlet reapter, "Y" duct attaching flange, Bayco seal, and internal spring intact. The lox pump impeller and inducer remained attached to the pump but showed considerable evidence of heat. The impeller was burned and eroded both internally and externally with an erosion pattern indicating the heating occurred while the impeller was rotating. Both the lox pump wear ring and diverter lip were also extremely eroded. The hydraulic pump was broken from the georease at its weakest section.
- B. <u>Booster Engine #1</u> The majority of El engine components were dispersed east of the 'est stand or in the skim pond. The thrust chamber skirt section was separated from the injector and found with the dome/injector assembly in the skim pond. The main lox valve, lube oil tank, power package, and gas generator and turbine assembly were all located east of the tower. All Bl components showed external evidence of impact and fire damage.
- C. <u>Booster Engine #2</u> B2 engine components were dispersed over a wide area west of the test stand or in the skim pond. All recovered hardware indicated extreme damage, due mainly to failure of B2 engine to shut down prior to missile destruction. The following major comjonents were never located or identified: turbine exhaust heat exchanger, surge chamber, lox and fuel bootstrap lines, lox purge check valve, main lox valve, directional control valve, and ignitor fuel valve. The gimbal block, lube oil tank, main fuel valve, power package, and gas generator control assembly were all shattered into several pieces.
- D. <u>Vernicr Engines</u> The majority of vernier feed plumbing was not found. Both chambers showed impact damage and were separated from the propelant valve assemblies. Both solo tanks were found in pieces, due

This decement conteins information effecting the national defense of the United States within the meaning of the Esplonage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.



5.2.1 (Continued)

apparently to impact and not overpressurization. The lox and fuel flex lines were both attached to sustainer engine hardware.

5.2-3

- E. <u>Lox Topping System</u> Both topping check valve bodies were found intact although attached plumbing was severely damaged. Remainder of topping lines and hardware were found in several pieces and indicated impact and fire damage.
- F. <u>Sustainer Low Pressure Ducting</u> The flex joint immediately upstream of the lox pump inlet flange was found severely damaged with several bellows sections flattened. All remaining portions of the lox and fuel ducting which were identified indicated severe tearing and burning.
- G. <u>Booster Low Pressure Ducting</u> Most recovered ducting showed extreme impact and fire damage. The major pieces of all staging shutoff valves were recovered in various states of damage. Most duct flanges were broken or twisted indicating severe impact damage. The airborne portion of the lox fill and drain valve was almost completely destroyed although the 8" flex joint remained attached to the valve flange. The fuel fill and drain valve suffered a broken housing plus other impact and fire damage. All valve ducting was torn from the mounting flanges.
- 5.2.2 PNEUMATIC SYSTEM
 - A. <u>Area of Dispersion of Recovered Hardware</u> Components of the airborne pneumatics system recovered were found over a widely dispersed area. Nearly fifty per cent of the recovered components were in the remains of the test stand structure and one of the shrouded helium spheres was over 1000 feet from the stand. The location of the components recovered is essentially radially from their position on the missile. The boiloff valve was found in the remains of the tower structure,
 - B. <u>Condition of Recovered Hardware</u> Three of the helium spheres were intact, two of them having most of the shrouding attached. These had sustained minor apparent structural damage but the other shrouded spheres were fragmented into numerous pieces. The ambient helium sphere was ruptured into essentially two large pieces which evidenced fire damage as well as other visual structural damage. The boiloff valve was relatively undamaged. The flanges, bolts and casing were intact and appeared sound. A portion of the liquid oxygen tank forward bulkhead was still attached to the valve. Both high pressure helium check valves were recovered intact. The tubing had been extruded from the "B" nuts except for one short segment at the inlet of one valve. There was no evidence of fire on the valves themselves but the piece of tubing was covered with carbon. One of the valves was marred



This document centains information allecting the national detence of the United Statiss within the meaning of the Espionage Laws, Titie 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.



5.2.2 (Continued)

and gouged. The airborne pressurization regulators were damaged structurally but only the fuel regulator showed carbon deposits. The ducting had been torn from the components as was the tubing of the lox regulator. The fuel regulator still had a short length of tubing attached. The flange and bolts of the hardware joining the relief values to the regulators were intact on both regulators and most of the casting itself was still attached to the fuel relief valve. One stop valve cap had been sheared from each regulator as evidenced by the sheared retaining bolts. The main body was undamaged and the nameplates were readily discernible. The sensing controllers and other attached hardware were also torn from the main body. The relief valves were damaged more severely than the regulators. The fuel relief valve was heavily coated with carbon and the body was mashed on one side. The flange and bolts on the mounting bracket side were attached and undamaged. The ducting and tubing had been extruded from the nuts or sheared off at the valve. The nameplates were legible. The changeover valve was damaged structurally to a considerable extent but was relatively intact. The motor housing was bent, marred and gouged and three screws had been sheared from one of the valve side covers. The tubing had been extruded from the "B" nuts. Inspection at the side plate revealed that the valve was partly open. The oxidizer pressurization duct diffuser was clean and only slightly dented. The duct to and including the upper flange and bolts of the manual shutoff valve were attached. One of the valves with a small portion of housing was recovered as was a very small portion of the other housing with the nameplate attached. The bolts on the pieces of housings found were intact. Only miscellaneous pieces of tubing, LN2 shrouds and fill ducts were recovered. Those pieces found were twisted and mangled severely. The helium distribution manifold, located in Quad III was intact, burned and had only two short sections of line attached. The manifold was attached to a small portion of bulkhead. The Quadrant II staging disconnect was relatively intact, the Quadrant IV staging and III - IV riseoff disconnects, delta pressure switch and transducers were damaged and showed signs of fire damage.

5.2.3 <u>HYDRAULIC SYSTEM</u>

There appeared to be no damage to missile hydraulic components from sources other than external explosions.

The dispersion pattern of the recovered hardware locates them on radial lines outward from the Z axis of the missile, in line with their respective locations on the missile. Several parts were found in the spill pond, and appear to have been washed down the spillway and into the pond by the main flame deflector water flow. Evidence of scratch marks on these parts indicates they slid over the concrete spillway.



This decument contains information attecting the national advance of the United States within the meaning of the Espionage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.



5.2.3 (Continued)

The customer disconnect bracket with adjoining tubing and flex lines were damaged due to being torn away by the explosion. The only fire damage to these parts was a small burn hole 1/2" X 3/16" on the return line from the sustainer hydraulic pump to the customer disconnect bracket. The casing of the sustainer hydraulic pump was found in two pieces. The upper flanged section was still attached to the sustainer engine, and the lower body section appeared to have been sheared off, possibly while being washed down to the spill pond. These parts were sheared at the narrow neck between the flange and body section. The hydraulic manifold that is located at the apex had all tubing sheared off. None of these preceding parts appeared to have suffered fire damage. All above hardware was located in the spill pond.

Five identifiable parts were found from the two airborne hydraulic reservoirs. The top of the Bl hydraulic reservoir with the hydraulic piston in the up position appeared to have been separated from the remaining part of the reservoir by external blast. No visible fire damage was evident, and all tubing was sheared off. The top of the sustainer hydraulic reservoir had all tubing sheared and evidence of fire damage, probably as a result of being in the test stand area after the explosion. A piece of the sustainer hydraulic reservoir was found with a piece of shrapnel imbedded in the tank section. There was no visible fire damage. The hydraulic piston was in the down position. The bottom section of the booster hydraulic reservoir shows no fire damage.

The sustainer system 27-08650-5 check valve was found with all tubing sheared off, with no evidence of fire damage.

The V-1 pitch and yaw actuators were found near the spillway, and the V-2 pitch and yaw actuators were in the area of the lox farm. The servo valves were missing from all actuators except the V-2 pitch actuator. None of the actuators appeared to have suffered fire damage.

The four tooster and two sustainer engine actuators were found at varying locations around the test stand area. Two booster and both sustainer actuators appeared to have suffered fire damage, while the other two booster actuators showed no similar evidence. Both sustainer actuators had part of the brackets that connect to the cylinder end of the actuator still attached to the actuator although the brackets were sheared off as were the piston end of the actuators. A servo valve was missing from one of the actuators. The two booster actuators with no evidence of fire, had the piston end broken off. One servo valve was missing. Part of the bracket from the missile structure had been sheared off and was still attached to the cylinder end of these actuators. The two booster actuators that suffered fire damage had the cylinder end bent violently, although no part of the bracket was attached to the actuators. The piston end of one



This document contains information alfacting the national detense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law,

R

5.2-5

5.2.3 (Continued)

of the actuators was sheared off, the other was intact.

The sustainer and both booster accumulators were damaged by external forces, either by flying pieces or by hitting something while being propelled away by the force of the explosion. One booster accumulator and the sustainer accumulator was sheared off.

The sustainer system Sterer value appears to have suffered damage by external explosion. All tubing was sheared off although there was no evidence of fire damage. The booster system Sterer value was found in a badly mutilated condition. Again no fire damage was evident.

Several parts of the B-l hydraulic pump were found, and all parts appear to have suffered external blast damage with no evidence of fire damage. The pump attachment flange was still attached to the necessary drive pad, but the remaining parts of the pump were sheared or blasted off. Several of the parts have not been found or identified. The hydraulic piston assembly and the adjoining cylinder assembly were found separated from each other. Six of the nine pistons were damaged or sheared off, again probably due to the explosion.

Minor pieces of tubing, tube connections, and check valves were found, most of which was damaged beyond recognition.

5.2.4 AIRFRAME

The lox tank nose adapter 27-75005, while relatively undamaged, was separated from both the lox tank, and the nose handling adapter. Approximately 1/3 of the upper bulkhead was retained with the adapter, while the entire lox boil-off value mating ring was torn out. The Calmec boil-off value with the tank mating ring was apparently undamaged. There were alight carbon deposits on the adapter, but no evidence of heat damage.

The lox tank pressurization duct and diffuser installation 27-73127, complete with elbow and doublers on tank skin was intact although torn from the tank skin. There was no evidence of heat damage to this item.

Large portions of the lox tank remained in the tower after the incident. The largest section, from Station 664 forward about 7 feet, was complete, though buckled through Quad II - III area and carboned in the upper areas. A large section from Station 693 forward about 3 fcot showed heat discoloration and another large section at Station 896 centered on the Y axis in Quad IV - I area showed heat discoloration and carbon deposits.

A 2 foot by 5 foot section from the lox tank in the area of the Quad IV lox elbow shows evidence of heat discoloration. The lox elbow and bellows show heat distortion and discoloration. A pod fairing bracket adjacent to



This document contains information offecting the relience defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

X

5.2.4 (Continued)

the elbow has aluminium alloy slag in the hinge. A smaller portion of the lox tank with the lox elbow from Quad III showed no evidence of fire damage.

There are no identifiable portions of the missile fuel tank available, nor are there any fragments of the pod fairings or doors. Two small fragments (about 2 square feet) of intermediate bulkhead showed considerable heat discoloration.

A small fragment (18" X 24"), of what apparently is the anti-slosh baffle, was found and showed no heat discoloration.

The tank section Station 1133 mating ring was found in three sections, all considerably twisted and deformed. A strip of tank skin, welded to the ring, was intact throughout the ring's length, as failure was in the skin above and below the ring. The largest ring section, about 10 feet long, had been straightened and showed evidence of heat damage. As this section was found in the rear of the fire gutted Utility Building, heat damage may have occurred at this time. There were no attaching bolts remaining for the tank to thrust section rings, and all the holes had been elongated in a direction parallel to the tank surface. Only one or two small (3" or 4") sections of the booster 1133 ring were found.

A portion of the fuel tank apex, with the fuel staging disconnect flange was found. Failure was in the tank skin around the largest doubler, and it was noted that the flange had collapsed into itself, concertina fashion.

Several small portions of the externally reinforced section of the fuel tank apex, adjacent to the sustainer cone attachment flange were found.

Several pieces of thrust section longerons up to 30" long were found. One large piece of the Qued IV longeron indicates a web torn and displaced in a direction towards Quad III. All pieces were heavily carboned.

A 2 foot portion of the thrust section jettison track was found, and showed fire damage.

One section 20" long of the Station 1206 frame was found.

The thrust section nacelles and firewall were completely shattered, with no large sections found.

The thrust barrel was completely shattered, with the largest piece approximately 12" X 36" from the Quad III area above the fireshield.



This document contains information affecting the national defense of the United Stafes within the measing of the Espionage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law, 1

J.

â

5.2-8

5.2.4 (Continued)

A portion of the partial frame between the upper and lower He bottles in Qued III - IV, reveals a burnt and molten area, where the lox topping line passes through the frame.

5.2.5 <u>A/B ELECTRICAL HARDWARE</u>

The missile inverter was found approximately 40 feet from northeast corner of stand. All plug receptacles had been ripped away including internal wiring receptable to component. Internal condition, as viewed through the receptacle holes, seemed to be in fair condition although distorted from original configuration. The outer casing was blackened by fire and was ruptured at one point near the top center. The rupture appeared to have been caused by internal components pushing outward. Rupture was approximately 4 inches long and .1 inch wide at maximum point with slight bulging outward. One inspection plate on connector end was torn loose leaving broken mounting stud on the casing. It should be noted that the location of the inverter was 180 deg from the majority of other pod 2 components. The mounting legs and bolts held. Fieces of mounting rails were found still connected to the inverter mounts.

The Acoustica Propellant Utilization Computer casing was blown apart in numerous fragments. The canister and internal parts were burned, blackened and strewn out in a long line to the west of the stand or almost directly outward from Pod 2 where the canister was mounted. The majority of larger recognizable parts were found on the S-4 access road. There was no ground fire where majority of parts were found.

The only recognizable part of the engine relay box that was found was the canister cover. The cover was burned and blackened. All electrical receptacles were torn from the cover leaving only distorted mounted holes. The cover was found in Area 3? (#283) fuel farm, which is 180 deg out from where the engine relay box normal mounting is located (Pod 2).

The only recognizable part located of the battery simulator box was a Cannon plug with bits of wire attached. The plug was burned and physically damaged. It was found approximately 500 feet from missile on the S-4 access road. It is assumed that all other parts of the simulator box were destroyed beyond recognition or have not been found.

At this writing it is assumed that the power changeover switch was either destroyed beyond recognition or has not been found. Search parties have made special trips to locate the switch but so far have been unsuccessful.

The umbilical jacks suffered severe damage. The recognizable parts were located and the areas are recorded on the fragmentation survey charts. Three umbilical adapters were found approximately 500 feet west of the stand on the S-4 access road. The booster umbilical was found in front



This document contains information effecting the notional defense of the United States within the meaning of the Espionoge Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

Ż



5.2.5 (Continued)

Ĩ,

X

of the stand near the LN2 storage tank revetment. Indications are that the adapters were ripped away from the missile jacks. The adapters suffered extreme physical damage by the explosion and contact with the structure and ground at point of impact. The metal casing of one adapter was melted by the fire which prevailed after the initial explosion.

The airborne harnesses were destroyed beyond repair. The harnesses, including the plugs, were fragmented and burned. Identification of individual harnesses was impossible in 95% of the cases where harness pieces were found. The distribution was wide spread from the stand to the surrounding area.

5.2.6 FLIGHT CONTROL SYSTEM

Major damage or destruction was suffered by the majority of Flight Control system hardware. The servo amplifier canister was shattered and indication of severe burning were noticeable on the recovered fragments. The displacement gyro canister was also shattered although all four gyros were located intact in their cases. Three were located in the tower structure and one in the canyon south of the tower. The flight programmer canister suffered severe tearing and burning as did the 600Pl flight control umbilical. Relatively minor damage, consisting mainly of smoke deposits, was incurred by the booster gimbal blocks and the remote rate gyro package. Both gimbal blocks were still workable.





5.3 FNGINEERING FILE EXAMINATION

The detailed review of the five available items of film coverage has been completed. The 200 frame per second camera, located at the east spillway ledge, fell over prior to, or as the result of, the first major explosion and consequently the final explosion was not recorded on this camera. Steam and smoke from the flame bucket obscured the view of the stand and missile prior to the time the camera began falling so it cannot be determined exactly if it was the first major explosion shock which caused the camera to topple.

Three of the remaining four items of film coverage were compared by utilizing the final explosion (indicated by recorded data at approximately 6.4 seconds) as a base point after counting frames from the first indication of ignition seen on each camera to this common point. Satisfactory correlation of the first major explosion and the first appearances of abnormalities about the thrust section was obtained from these three items. The three items, a 128 frame/second camera to the west of the test stand in the canyon, and one each 24 frame/second cameras at both the north and south observer tanks, established the first indication of abnormal performance subsequent to 1.3 seconds after ignition start. This compared with the recorded test cate.

The final item of film coverage, a 24 frame/second camera also located in the vicinity of the north observer tank, did not correlate with the three previously mentioned. This camera did not record the final explosion but did record the first major explosion. This time was compared to the three other items of coverage and by so doing the first indication of abnormal performance was indicated as occurring prior to 1.3 seconds after ignition start. A re-calibration of camera frame speed revealed that the camera was not running at 24 frames/second but was in fact operating at an average frame speed of approxilately 27 frames/second. This was established by photographic department personnel. When the 27 frame/second rate was used to time the intervals between the recorded incidents the first indication of abnormal performance was established to be subsequent to 1.3 second after ignition start and in close agreement with the other three film items. The film became over exposed immediately after the occurrence of the first major explosion indicated by recorded data to have occurred at approximately 5.4 seconds.



This decument contains information affecting the national defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

Ĵ.



5.4 DATA ANALYSIS

A review of the data recorded during the test revealed that the head suppression valve (main lox valve of the sustainer engine) did not open in a manner consistant with its opening on the eight previous firings of Missile IF, as indicated by the valve position measurement P1529D. Prior to the occurrence of the indicated abnormal behavior of this valve, there is no valid indication of abnormalities elsewhere in recorded data.

The H.S. valve position data indicates that the valve began a movement toward open at a time that was consistant with its initial opening movement on the eight previous firings. However, on this firing the valve paused at the indicated 5 degree open position for approximately 350 milliseconds before continuing movement toward open. H.S. valve action of this nature was experienced once previously by GD/A during testing of Missile 2E at Sycamore Test Stand S2. On Test S2-505-A2-02, the H.S. valve paused at the 5 degree open position for approximately 840 milliseconds. The H.S. valve on that test then moved open normally and the test was terminated safely by observer cutoff when it became apparent that the sustainer engine was not operating. Following the Missile 2E test, the H.S. valve, the hydraulic control manifold, and the ignitor fuel valve were replaced and sent to Rocketdyne for failure analysis. During cold testing of the H.S. valve by Rocketdyne, the "hang up" of the valve was repeated. Disassembly of the valve revealed moisture in the shaft beering cavity on the opposite end of the shaft from the valve actuato: mechanism. The ignitor fuel valve and hydraulic control package were functionally tested satisfactorily. The failure of the head suppression value to function properly on that test was attributed to shaft seizure resulting from moisture freezing in the shaft bearing cavity. The major difference between the test of Missile 2E and this test of Missile 1F, regarding H.S. valve motion, was the length of time the valves "hung up" at the 5 degree open position.

A comparison of pump speed versus H.S. valve position between the two tests does not indicate any significant differences after the time on each test at which the H.S. valve began its major opening movement. On the Missile 1F test the pump speed began increasing from 8250 rpm. after the time that the H.S. valve reached the 33 degree open position. The pump speed on the test of Missile 2E, at the time the valve reached the 33 degree open position, was 8700 rpm.

On the Missile 1F test, the pump speed was 8850 rpm at the time that the H.S. valve reached its indicated maximum open position of 38 degrees (at 1.37 seconds). Hardware analysis indicates the valve actually opened to 45 ± 1 deg. On the Missile 2E test, the pump speed was 8050 rpm when the valve was at the 38 degree open position.



This decument contains information effecting the national detense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibiled by law.



5.4-2

5.4 <u>DATA ANALYSIS</u> (Continued)

÷

L

The indicated closing movement of the H.S. valve, after 1.37 seconds, is not believed to be valid data. If the valve were, in fact, closed after this time, and were the lox system intact, a pressure increase would have been indicated on the sustainer lox regulator discharge pressure, which appears to be recording valid data after 1.37 seconds. Since the pump speed is increasing at this time and both the lox regulator discharge pressure and thrust chamber lox manifold pressure are decreasing, it appears that the integrity of the lox system was lost prior to 1.37 seconds. The sustainer lox pump inlet pressure strain gage transducer measurement indicated OSH at 1.32 seconds and it is therefore concluded that the integrity of the lox system was lost within the time interval between 1.32 sec and 1.37 seconds due to an abnormal pressure surge within the lox system.

The P.U. value data does not react normally to the indicated closing movement of the H.S. value, subsequent to 1.38 seconds. Opening of this value requires igniter fuel system pressure within the hydraulic manifold and since the igniter fuel value is cam operated by the H.S. value, the P.U. value should have begun a closing movement prior to 1.65 seconds when the H.S. value reached the approximate closed position. Since the P.U. value did not begin to move toward closed until 1.97 seconds, it appears that the indicated closing movement of the H.S. value is invalid data.

The pressure surge indicated by the sustainer lox pump inlet pressure data and substantiated by the booster lox pump inlet pressures, supports a sustainer lox system detonation between the time interval of 1.32 and 1.37 seconds, with a resultant loss of lox system integrity.

The behavior of the sustainer gas generator lox injection pressure measurement remains unexplained. The trace should maintain a zero psig level until bootstrap of the engine, after which time this measurement will reflect lox pressure to the gas generator combustor. Premature pressure rise data have been occasionally recorded on this measurement at other test sites. However, these rises have been related to hot gas leakage past the GG lox poppet at ignition start and in none of the instances noted was unsatisfactory engine performances experienced. The data from this measurement during this test appears additionally unrealistic at the time that the "gas generator blade valve closed" microswitch deactivates at 1.65 seconds, in that there is no response on the trace. If the lox system was no longer intact at 1.65 seconds, the indicated trapped pressure between the poppet and the blade valve should have vented upstream thru the blade valve. Also if the lox system were intact at 1.65 seconds, some reaction from the trace would be expected when the blade valve opened.

UNCLASSIFIE

This decument contains infermation a the ting the netional defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.





5.4 <u>DATA ANALYSIS</u> (Continued)

¥.,

The indicated deactivation and reactivation of the "sustainer gas generator blade valve closed" microswitch between 1.65 seconds and 1.89 seconds appears to be normal under the circumstances. In order to open the blade valve, the fuel manifold pressure sensed at the hydraulic manifold must be approximately 450 psig, to shuttle the blade valve control valve in the hydraulic manifold. After 1.38 seconds a speed increase of the sustainer pump occurred which continued until burn out of the SPGG at 1.78 seconds. It appears that with the fuel jacket of the thrust chamber being primed since 1.16 seconds, when the PU value started open, and the overspeed trend of the pump following loss of lox system integrity of 1.38 seconds, sufficient manifold pressure was created in the fuel manifold to cause the blade valve to start open. Burn out of the SPGG at 1.78 seconds and consequent deacceleration of the pump resulted in loss of fuel pressure and prevented the blade valve from reaching the open position.

Investigation of the lox pump seal cavity pressure anomalies on this test revealed that a similar anomaly occurred on the test of Missile 2E, in which the H.S. valve also hung up. It appears that the cavity pressure increase is a result of the delay in opening of the H.S. valve.

The increase in sustainer pump speed which occurred starting in the vicinity of 1.34 seconds also supports the loss of integrity of the sustainer lox system. Such a speed trend would be expected in the event that the lox pump became unloaded. The continued integrity by the fuel side of the sustainer system was indicated by the fuel pump inlet pressure measurement. This data reacted in a normal manner to the closing of the P.U. valve and continued to record data until approximately 5.37 seconds. The "gas generater blade valve closed" microswitch activations, the gas generator lox injection pressure measurement did not indicate booststrap of the engine at the time the speed increase began.

Tests have been conducted in an effort to explain the apparent shock load on the sustainer lox pump inlet at 0.87 seconds. These tests consisted of bench tests utilizing a Gulton Accelerometer System. Vibration inputs were at frequencies below 20 cps. The results indicated that there is no apparent magnification of the input signal at this frequency range. The following conditions were found to simulate an output similar to that recorded on 1F.

- a. A slightly loose connection between the cable and the transducer, (highly improbable)
- b. A faulty or noisy cable as a result of a breakdown in its inner insulation. The output was simulated by slightly moving or whipping the cable.



This decument contains information alterring the national detents of the United States which the meaning of the Espianoge Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any majner to an unauthorized person is prohibited by law.



5.4 <u>DATA ANALYSIS</u> (Continued)

1

k

韵

Û

X

Ţ

c. The grounding of the transducer against a body containing a static charge, such as a piece of missile hardware. The piece of hardware would have to stay in contact with the transducer in order to simulate the output.

5.4-4

It is concluded that the outputs recorded on 1F do not represent quantitative valid data.



information effectuate the particular of the United States and the meaning of the

This document conteins information attacting the nurlexal analysis of the United States within the meaning of the Esplanage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revolution of which in one manner to an unoutherized berson is prohibited by law.

5.5 HARDWARE ANALYSIS

Analysis of recovered missile hardware verified the origin of explosion to be the sustainer engine lox pump. All damage incurred by hardware other than the sustainer was the results of heat and/or impact resulting from the subsequent fire and explosion.

5.5-1

Detailed teardown of the sustainer engine components was performed at Rocketdyne Canoga Park to derive maximum advantage from the available facilities. Teardown and inspection was performed by Rocketdyne personnel with the concurrance of hardware specialists from the Air Force Inspector General Office. Special tests were accomplished, as necessary, to provide additional background information or to attempt duplication of various hardware anomalies.

To eliminate unnecessary duplication in recording the results of hardware analysis, the reader is referred to the Hardware Investigation Tesm Report which is presented in full in the following rages.



This decument centeins information officing the national defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.



とないないです。

- 2002. Y

1000

Û

1

S.

5.5-2 6101-7519-TC-000

HARDWARE INVESTIGATION TEAM REPORT (U) SM-65F MISSILE TEST ACCIDENT ATLAS 1F, AFSN 60-5524 STAND S-1 SYCAMORE STATIC TEST SITE GENERAL DYNAMICS/ASTRONAUTICS SAN DIEGO, CALIFORNIA 13 MAY 1962



This document contains information affecting the national defense of the United States within the meaning of the Esplonage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

5**.**5-3 6101-7519-TC-000

The hardware investigation of this missile test accident was conducted and this report is submitted by:

udney D. Berman

Ĵ.

Sydney D. Berman, Team Chief Technical Director, DFS Deputy Inspector General for Safety OTIG, USAF

earles.

Charles W. Flanders Major, USAF Atlas Project Officer Deputy Inspector General for Safety OTIG, USAF

ja lan Hoyt/B. Grahem, Jr.

Atias Program Office

Joseph Green

Atlas Program Office Space Technology Laboratories

BBank

George Baird Senior Research Engineer Engineering Department Rocketdyne

Burdette T. Person Senior Research Engineer Engineering Department Rocketdyne

Ŧ



This document contains information affecting the national defense of the United States within the meaning of the Espionaga Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.



6101-7519-тс-000

5.5-4

•

,

- - -

.

TABLE OF CONTENTS

	Page
SEQUENCE OF EVENIS	1
TYPE OF ACCIDENT	2
INVESTIGATION AND ANALYSIS	
 General LOX Pump Volute Head Suppression Valve Head Suppression Valve Delay Internal Burning Pump Clearances Gas Generator Material in the LOX Dome 	2 3 7 8 10 10 11
CONCLUSIONS	11
CAUSE	12
RECOMMENDATIONS	12
ACTION TAKEN	13
APPENDIX A (Photographs)	A-0
APPENDIX B (Burning characteristics in a LOX pump)	B-1

Ĵ

R:



This document contains information attenting the national detents of the United States within the meaning of the Espionage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

.



5.5-5 6101-7519-1C-000 (Page 1)

A. SEQUENCE OF EVENTS

Atlas missile 1F, SN 60-5524, was destroyed by fire and explosion at stand S-1, Sycamore Static Test Facility, San Diego, Calif., 13 May 1962. Personnel injury and private property damage were not involved in this mishap. The accident occurred during static firing run number S1-613-14-01, the second static firing of Block III testing and the ninth static firing since the erection of this missile in stand S-1 on 7 March 1961. This firing was conducted to support missile and instrumentation changes planned for Pacific Missile Range flights. One of the test objectives was to evaluate LOX loading and launch control logic circuitry operation under a one hour hold condition at "Ready for Commit". Planned engine run times were 40 • seconds for the booster engines, 60 seconds for the sustainer engine, and 65 seconds for the vernier engines.

Countdown was started at approximately 1235 PDT, 13 May 1962, with a planned one hour hold with propellants loaded. The commit sequence was completed (T-O) at 1345 PDT. Sustainer engine ignition start signal occurred 0.54 seconds after booster engine ignition.* At 0.67 seconds, the head suppression valve data indicated that the valve started to open and then hesitated between 4 and 6 degrees open for 350 milliseconds. At 1.01 seconds, the valve started opening and reached 38 degrees open at 1.38 seconds. The valve data showed that the valve started closing at approximately 1.38 seconds. Pressure surges were observed in the sustainer LOX pump inlet pressure, booster LOX pump inlet pressure, sustainer thrust chamber LOX manifold pressure, and the sustainer LOX regulator discharge pressure; peaking at approximately 1.34 to 1.35 seconds. The three sustainer engine pressure measurements indicated loss of sustainer LOX system integrity between 1.34 and 1.38 seconds.

* Note that all times in this report are based on "quick look" data and subject to possible changes when instrumentation delay characteristics are taken, into acquit,



This document contains information diffecting the national defines (of the United States (within the maning of the Espionage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.



5.5-6 6101-7519-TC-000 (Page 2)

Loss of the missile sustainer hydraulic system coincided closely with the loss of sustainer engine LOX system integrity. The missile, missile service tower, and utility building were destroyed. Aerospace Ground Equipment and facility equipment around the service tower sustained major damage (Figs 1 and 2). Note that the skim pond where the sustainer was found had not been drained at the time the photographs were taken. Figure 3 shows the skim pond after draining.

B. TYPE OF ACCIDENT - DESTRUCTION OF MISSILE AND SUPPORT EQUIPMENT BY FIRE AND EXPLOSION.

C. INVESTIGATION AND ANALYSIS

1. General

ſ

Analysis of instrumentation data and films indicated that the initial abnormalities occurred in the LOX system of the sustainer engine. Therefore, the investigation was concentrated on recovered portions of the sustainer engine including the LOX turbopump, the head suppression valve, associated plumbing, and hydraulic control components.** Extensive damage and separation of portions of these subassemblies occurred during the explosion and subsequent ejection from the stand.

The sustainer thrust chamber was found with the head suppression (HS) valve body attached by the turnbuckles. The turbopump was torn from the pump mounts and the thrust chamber was separated at a plane just downstream of the throat (Figs 4 and 5). The sustainer engine turbopump assembly was recovered in several pieces. The turbine, gear case, RP-1 pump, approximately half of the LOX pump volute, impeller, inducer, and pump shaft were still joined as an assembly. A portion of the LOX pump volute, wear ring, inlet housing, RACO seal and the mating GD/A LOX duct

** Parts nomenclature used in this report conform to T.O. 2K-LR105-14, "Illustrated Parts Breakdown".



This document contains information '8. U.S.C. Section 793 and 794, the



6101-7519-TC-000 (Page 3)

flange (with a small piece of the bellows) were found as a unit (Figs 6 and 7). Two additional pieces of the pump volute were recovered segmately (Fig 8). A portion of the LOX pump volute was not recovered.

2. LOX Pump Volute

The fractured surfaces of the LOX pump volute exhibited a characteristic herringbone pattern showing that the volute had separated circumferentially approximately at the casting parting line, with both halves being propelled apart axially by a rapid onset of extreme over-pressure. Shearing of the LOX pump discharge flange attachment bolts at the mating surface between the flange and the head suppression valve housing, and brinelling of the bolt holes in the flange halves and valve housing confirmed the fore and aft axial movement of the two halves of the LOX pump volute (Fig 9). The energy level required to separate the volute with sufficient force to cause the resulting fractures of surrounding hardware, exceed that which could have been developed hydraulically, and could only have resulted from an explosion within the pump.

3. Head Suppression Valve Assembly

The HS valve actuator was separated from the valve by the forward movement of the front half of the LOX pump volute (Fig 10). The aft side of the actuator housing was deformed inward by the LOX pump discharge flange striking it as evidenced by matching brinelling on the edge of the flange and the deformed portion of the housing. Deformation inward of the actuator housing resulted in the brinelling of the interior of the housing against the fuel igniter valve cam attachment bolt (Fig 11). Comparison of the location of this brinell mark with layout drawings snowed that the head suppression valve was 45 ± 1 degrees open when the actuator housing was deformed during the LOX pump explosion.



meaning of the Espio

This document contains information "offecting the addised" defense fol the United States(we 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to

interesting and the

Y and an a shour the second the

いかいべつ

¢

the a second

A 20

¥.

~

Ĩ,


5.5-8 6101-7519-TC-000 (Page 4)

At that time, it should have been fully open (90°) . Separation of the accuator assembly from the valve housing, resulted in a bending fracture of the head suppression valve gate drive shaft at the mating surface between the actuator housing and the valve housing. The actuator housing cover plate, switch box and position potentiometer, and the fuel igniter valve were separated from the need suppression valve actuator housing during its deformation. The 45 degree valve position was also established by a brinell mark on the fuel igniter valve cam made by the cam follower.

The fuel igniter valve cam working face exhibited signs of what appeared to be abnormal wearing. There were numerous shallow crater-like depressions in the area over which the cam follower roller travels. The shape of the deformations did not conform to a typical corrosion pattern and there were no signs of oxidation residue. The deformations did not have the appearance of galling. Discussions with personnel who were familiar with this assembly indicated that similar wear patterns have been observed on cams that have beer in service for extended time periods. Damage sustained by the sustainer engine fuel igniter valve housing and cam follower during deformation of the HS valve actuator housing, showed that the fuel igniter valve was open at the time of the LOX pump explosion.

The HS valve actuator cylinder was dented on the forward side resulting in a shallow inward deformation of the cylinder wall. The anodized surface of the cylinder bore and a small metal chip was machined off the dented area by the outboard land of the actuator piston while it was moving in the closed direction. A portion of the chip was found between the teflon retainer outboard of the rubber O-ring packing and the inside face of the outboard piston land. The location of the brinell marks on the



his document contains information offering the fating of the chited stated within the meaning of the Espionage Laws, Title

ſ



3

Ţ

5.5-9 6101-7519-TC-000 (Page 5)

actuator piston and the sliced off portion of the dent in the cylinder wall indicated that if the actuator and head suppression valve gate were connected at the time of cylinder deformation, the gate would have been open approximately 54 degrees. This obviously occurred after the pump explosion, but the sequence of events is subject to speculation. A valve closing command was generated at ignition plus 1.73 seconds which was adequate time for the HS valve to reach the full open position. Assuming that the hydraulic lines were intact, and that the actuating cylinder was struck sometime after 1.73 seconds with the piston groove aligned with the area dented, the observed chip removal could be explained.

The head suppression valve drive shaft, idler shaft, and gate were disassembled. The bearing assemblies were free on the shaft and withdrew easily. The mylar lip seals used for excluding moisture from the valve drive shaft bearings were partially split in the seal radii. The idler shaft outboard seal was split in the same manner, while the inboard seal was intact at disassembly. It should be noted that the most likely point of moisture entry during a normal test run is through the seal that remained intact. Moisture was observed inside the seal retainer and vent valve assembly which is installed in the idler shaft housing. The idler shaft needle bearing assembly contained water and scaly rust deposits on the needle bearing tapered ends and outer bearing race. Several of the needles were galled on the inboard end (Fig 12). The polished surface of the idler shaft exhibited several types of deformation (Fig 13). Brinelling imprints of the needle bearings occurred on opposing sides of the idler shaft. Build up of metal in the brinelled areas of the idler shaft showed valve gate motion toward the closed position. Marks were also observed on the surface of the idler shaft which showed compression of a hard gritty substance between the needle bearings and the erial around these depressions shaft surface.



This document contains information diacting the national datates of the United States fithin the meaning of the Espicance Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manher to an unauthorized person is prohibited by law.



6101-7519-TC-000 (Page 6)

indicated shaft movement in both directions. One distinctive mark deeper than the other was observed with metal build up occurring in the direction of gate closing motion. The mating surfaces between the idler shaft square drive and the anodized valve gate exhibited a heavy coating of newly developed, finely textured ferrous oxide, probably the result of the assembly being submerged in the skim pond.

Although both of the mylar lip seals on the valve drive shaft were split, no evidence of moisture or oxidation was found in the drive shaft needle bearings. Heavy brinelling of the pclished bearing surface of the drive, shaft was evident on opposing sides of the shaft which coincided with the drive shaft needle bearings. This brinelling occurred during the bending fracture of the drive shaft initiated by the separation of the actuator assembly from the valve housing. Brinell marks resulted from instantaneous impact, hence showed no direction of rotation. A series of lightly brinelled lines corresponding to needle valve spacing was observed outboard of the bearing wear area extending under the outboard mylar lip seal. These marks were made on the shaft prior to final assembly since similar damage was not reflected in the mylar lip seal. They could have resulted from an attempt to fit an undersized or defective bearing on the drive shaft during assembly.

A section of the head suppression valve seal lip was broken away from the seal. Evidence of tension and compression stresses in the failed area showed that the missing portion of the seal had failed in bending toward the LOX dome which was opposite to the direction of loading had moisture frozen this portion of the seal to the gate. Tests conducted at Rocketdyne indicated that a lip seal frozen to the gate would break free when approximately 400 psi hydraulic pressure was applied to the opening side of the actuator piston. Furthermore, the test seal suffered no deformation.



This document contains information afforting the national defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C., Section 793 and 774, the transmission or availation of which in any manner to an unauthorized person is prohibited by law.



5.5-11 6101-7519-10-000 (Page 7)

The head suppression valve gate was deformed on the middle of the upstream edge. Pile up of metal in the deformed area indicated that the impact drove the gate toward the closed position and that the damage occurred after separation of the head suppression actuator assembly.

4. Head Suppression Valve Delay

1

Ţ.

It has been postulated that the missile IF HS valve hang up was due to freezing of moisture in the idler shaft bearing. The potentiometer mounted on the end of the drive shaft indicated a 4 to 6 degree opening. Since the measurement of deflection was made at the driven end, the apparent movement of the valve was attributed to torsional deflection of the drive shaft and gate linkage, primarily in the aluminum gate valve. One test run on Sycamore missile 2E exhibited a similar HS valve hangup for approximately 800 milliseconds. Prior to disassembly of the 2E valve, Rocketdyne laboratory tests confirmed freezing of the idler shaft and bearing assembly. Laboratory tests following the 1F incident showed that the gate valve could have hung up due to a combination of factors such as lip seal friction (1100 to 1200 psi actuating pressure), ice on the lip seal (up to 400 psi), and dirt and ice in the idler bearing (up to 800 psi). At the time of HS valve opening, the missile was operating on ground hydraulic supply (2000 psi). Recent Rocketdyne tests do not fully duplicate the 2E/1F valve behavior in that the maximum delay induced was not over 60 milliseconds. Rocketdyne tests are continuing and will be reported separately.

If the HS value idler shaft froze and broke loose, one would expect to see a spike on the value position trace as the shaft torque was released. Apparently, the reason why the HS value position trace does not jump at the start of opening is due to the restricter orifice in the hydraulic return line and to lip seal friction.



This document contains information affecting the notional defense of the Uniron States within the meaning of the Espionage Laws, Title 18, U.S.C., Sectian 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.



Other possible causes of the 1F HS valve behavior investigated were air in the system, contamination in the hydraulic package, and water in the HS valve actuating cylinder.

Rocketdyne tests (14 November 1960 memo) proved that the engine hydraulic system would bleed itself in one-half an hour under 2000 psi inlet pressure without actuation of the hydraulic system. The 1F hydraulic system was in operation more than one hour prior to engine start.

An HS value actuating cylinder was deliberately contaminated with water to see what would happen if the piston bleed orifice froze. In the final test, water was used without oil and did not freeze under the simulated hold conditions; i.e., 2000 psi and chilled with LN_2 .

The tear down inspection of the hydraulic control package showed adequate clearances and free movement of the servo valves. A microscopic examination of the "B" valve showed no sign of foreign object damage. The inlet filter was relatively clean. There was little contamination on the upstream side, no contamination on the downstream side, and no holes in the filter element.

5. Internal Burning

1)

Ľ

1.

The inside of the sustainer LOX pump exhibited metallic erosion, metallic deposits, and carbon deposits. The nature of the deposits indicated burning before and after the explosion. There was no visual physical evidence of rubbing; however, the surfaces were so badly damaged in the pertinent areas that rub marks would have been obliterated. The most severe burning occurred on the wear ring diverter lip and the matching impeller surface. The diverter lip was burned completely away for approximately 180° of the circumference. Steps on the wear ring labyrinth seal were also burned



This document contains information difficting the national deferse of the United Stokes within the meaning of the Espianage Laws, Title 18, U.S.C., Section 793 and 794, the lightmission or revelation of which in any manner 15 an unauthorized person is prohibited by law.



()

C

5**.5-13** 6101-7519-TC-000 (Page 9)

but less severely than the diverter lip. Burn patterns on the impeller are fairly uniform around the circumference of the shroud in the labyrinth seal area. Passages inside the impeller were severely burned, with three places on the impeller shroud burned away 1/2 to one inch back from the outside periphery. Flow patterns in this area conform to the direction of flow inside the impeller. There was no burning or rubbing on the back face (balance rib area) of the impeller. The inducer exhibited a limited amount of burning. Large pieces of the inducer blades were broken off on one side. Examination showed that these were cold breaks. Direction of motion during failure was upstream indicating separation after the initia' explosion. There was deep erosion in the inlet assembly progressing in the upstream direction. Fire developed in the gaseous boundary layer between the LOX and the inlet assembly interior face, and progressed from areas of higher to lower pressures (upstream). See Appendix B.

The RACO seal was intact but the steel expander was buckled inward in one place (Fig. 14). Moltan metal had flowed across the inlet housing and piled up on the Jownstream edge of the expander (Fig. 15). Heating of the steel expander, insulated from the inlet housing by the teflon portion of the seal, caused it to expand and buckle in compression pushing the aluminum slag built up on the ring away from the inlet housing. One side of the inner edge of the steel expander ring showed several hairline radial cracks in the buckled area. It was noted that although the steel and aluminum surrounding the teflon portion of the seal was severely burned and eroded adjacent to the teflon, the teflon seal material did not show any significant evidence of erosion (Fig. 16).

The bellows in the GD/A Y-duct was torn off the flange and badly mangled indicated mechanical lamage rather than failure due to internal pressure (Fig. 17).



This document contains information antiching the harchan abrends of the innead states within the meaning of the Espionage Laws, Jitle 16, USC, Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibiled by law.



The above observations indicate that burning originated at the leading edge of the impeller shroud, probably due to rubbing against the diverter lip.

6. Pump Clearances

The major portion of the turbopump assembly from the inducer, impeller, and aft portion of the LOX pump volute aft through the RP-1 pump, gearcase, and turbine was disassembled and checked against the last known build for proper shims and measurement of clearances. The assembly conformed to the last build, which showed a diverter lip to impeller clearance of 0.041 inch. Running clearance depending upon static and external effects, and dynamic effects without shaft bending could have resulted in a net diverter lip clearance of 0.032 to 0.017 inch. Calculated effects of pump operation against a closed or partially closed HS valve indicated a shaft deflection of 0.020 inch could be experienced due to unbalanced pressures in the volute. Tests conducted at Santa Susana on one pump with various delays in HS valve opening times, showed that in actual operation, larger shaft deflections than those calculated would be experienced, and would have resulted in severe rubbing. With the HS valve opening late, the area of minimum clearance was in a position which would have produced the wear ring damage observed on 1F. It is interesting to note that the area of maximum wear ring damage on 1F was approximately 180° from that experienced on 11F.

7. Gas Generator

The gas generator (GG) was separated from the turbine. The turbine inlet duct was broken just downstream of the flange, leaving the flange attached to the GG. The GG support brace was broken in compression, but remained attached to the GG. The GG dual gate valve and GG injector were found together but sheared off the combustor body. The propellant inlet adapters were broken off the valve. The GG valve actuator was broken off the valve and



This document contains information effecting the national defense of the United Flater within the meaning of the Espianage Laws, Title 18, U.S.C., Section 793 and 794, the manimistion of revelation of Amich in any manner to an unauthorized person is prohibited by law.



5.5-15 G101-7519-TC-000 (Page 11)

found dangling from the engine by the closing hydraulic line. The solid propellant gas generator (SPGG) with its heater were bolted to the GG flange but were separated at the weld to the GG outlet duct (Fig 18). This weld failed as a result of post accident damage, however, it was noted that the weld was substandard. There was no evidence of hot gas leaks prior to the fracture.

8. Material in the LOX Dome

An NAS 1144 bolt head, two pieces of the HS valve lip seal, and one piece of Cannon connector were found in the sustainer LOX dome together with dirt, fibrous material, and sand. This foreign material evidently entered the LOX dome after the explosion. The top of the bolt head had been subjected to heat, but the underside was still shiny. An examination of the bolt head showed that it failed due to bending during missile disintegration rather than from over torquing. The piece of Cannon connector showed signs of burning. The piece of lip seal was discolored and one edge showed some evidence of heating. The fibrous material was heavily sooted and burned. Similar fibrous material was found in the skim pond.

D. CONCLUSIONS

- 1. Conditions conducive to seizure existed within the head suppression valve idler shaft and bearing.
- 2. Late opening of the head suppression valve caused unbalanced dynamic loads on the LOX pump impeller resulting in excessive deflection of the pump shaft.
- 3. Rubbing occurred between the impeller and diverter lip as evidenced by excessive burning and erosion in that area.



This document contains information affecting the national different of the United States within the meaning of the Espionage Laws, Title 18. U.S.C. Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.



5.5-16 6101-7519-TC-000 (Page 12)

- 4. Impeller and diverter lip rubbing resulted in an uncontrolled LOX/aluminum alloy fire severely eroding the wear ring, impeller, and inlet assembly.
- 5. An explosion occurred in the LOX pump volute shortly after ignition of the LOX/aluminum alloy fire.
- 6. The head suppression value was open $45^{\circ} \pm 1^{\circ}$ at the time of LOX pump explosion.
- 7. The weld attaching the SPGG to the GG hot gas duct did not contribute to the accident.
- 8. The foreign material found in the LOX dome entered after the explosion.

E. CAUSE

£)

The most probable cause of this accident was freezing of the head suppression valve idler shaft and needle bearing assembly.

F. RECOMMENDATIONS

It is recommended that:

- A study be conducted to determine a method for precluding the presence of moisture in the HS valve idler shaft bearing housing. Possible methods are:
 - a) Use of improved lip seal.
 - b) Use of a dessicant plug to absorb whatever moisture is ingested into the housing.



This document contains information allecting the Northeat details of the United States which the meaning of the Espionage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.



5.5-17 6101-7519-TC-000 (Page 13)

- 2. A study be conducted to determine whether increased ground hydraulic system pressure is advisable.
- 3. Further studies should be conducted to determine the feasibility of precluding interference between the rotating and stationary elements in the LOX pump. Some possible fixes which should be considered are:
 - a) A non-combustible liner such as teflen or Kel-F in the wear ring and inlet assembly which would not cause failure should rubbing occur.
 - b) Increased clearances to permit additional shaft deflections.

G. ACTION TAKEN

4)

1

- Rocketdyne ECP MA3-186Rl was submitted for improved head suppression valve bearing lip seals and dessicant plugs for the head suppression valve idler shaft bearing housing.
- 2. Rocketdyne is conducting further studies for the above recommendation of developing a non-combustible liner for the LOX pump wear ring and inlet assembly.



This document contains information attenting the cestance descent destance described by the solar of the Espionage Laws, Title 18, U.S.C. Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.



5.5-18 6101-7519-TC-000 (Page A-0)

ĩ

,

-

APPENDIX A

 \mathbf{O}

2000

2.0.4.

2

ſ.

- --

FIGURE	TITLE	PAGE
1	View of Test Site	A-1
2	Service Tower	A-2
3	Skim Pond Debris	A-3
4	Front Three-quarter View of Sustainer	A-4
5	Aft Three-quarter View of Sustainer	A-5
6	Turbopump, Inlet End	A-6
7	Turbopump, Right Side	A-7
8	Recovered Parts of Pump Volute	A-8
9	Inlet Side of HS Valve	A-9
10	Reconstruction of HS Valve Damage	A-10
11	Brinelled HS Valve Actuator	A-11
12	HS Valve Idler Shaft	A-12
13	HS Valve Idler Shaft Bearing	A-13
14	Deformed Inlet Seal Expander	A-14
15	Deposits on Inlet Seal	A-15
16	Metallic Erosion Adjacent to Inlet Seal	A-16
17	Y-Duct Bellows	A-17
18	GG and SPGG Weld	A-18



This documer: contains information attesting the national astenes of the United States within the maaning of the Espionage Laws, Title 18, U.S.L., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.



5.5-19 6101-7519-TC-000 (Page B-1)

APPENDIX B FROM: K.'Rothe, Supervisor, Hydrodynamics Unit

SUBJECT: LOX Pump Explosion - Mk 4; Atlas 1-F Failure at Site S-1; Sycamore Canyon Static Test Site, San Diego, 13 May 1962

Per request of Major Flanders and Mr. S. Berman, a brief inspection of the Mk 4 hardware was made with the special purpose to explain the flame propagation traces found in the pump passages. The inspection of the hardware showed the following:

- 1) No severe burning of the inducer.
- 2) No severe burning of the impeller leading edges and impeller hub at the inlet.
- 3) No burning in the scroll passage with the exception of one spot approximately 40° to 90° downstream of volute tongue.
- 4) No burning or rubbing in balance rib area of impeller.
- 5) Severe burning in impeller wear ring area and in two passages of the impeller. In the impeller blade passage the fire progressed from impeller discharge towards the impeller inlet.
- 6) Severe burning of the housing surrounding the inducer. Here, also, the fire progressed upstream, showing most damage close to the impeller front wear ring and less damage at inducer inlet.

The fire pattern which can be detected from the burned hardware shows that the flames progressed in some areas upstream against the pumped LOX. This is true for the casing surrounding the inducer and for the traces found inside the impeller passages on the impeller back shroud.

Most likely the fire started in the impeller front shroud wear ring and diverter lip area (the area which experienced the most damage) due to rubbing. Wherever it started in this area, the fire proceeded towards the pump inlet and



This document contains information-withering the instance of the United States within the meaning of the Espionoge Laws, Title 18 USES, Section 793 and 794 and 794 the transmission or revelation of which is now meaner to an use prohibited by low



5,5-20 6101-7519-TC-000 (Page B-2)

impeller tip, the only direction in which the fire finds both oxygen and aluminum. Reaching the casting which surrounds the inducer, the fire will travel upstream in the direction of decreasing pressure along the boundary layer of the inducer tip area. It is that area where the inducer tip vortex already generates gaseous oxygen necessary to maintain the fire.

.

The second major damage occurred at several spots at the shroud of the impeller tip diameter. Here the shroud was locally completely destroyed. After destruction of the shroud, the fire reached the back shroud of the impeller. The developed heat gasefied the LOX and the fire proceeded along the boundary layer of the impeller back shroud in the direction of decreasing pressure and incoming LOX.

The traces left by the fire in the inlet duct, at the impeller inlet, at the inducer blades, and in the impeller front wear ring area only show the motion of the boundary layer in a pump under normal operation. They were formed during the time the fire developed. As soon as the fire was fully developed, normal pump operation was interrupted and no firm prediction can be made as to the direction in which the fire might proceed. In the discussed case it is felt that the rupture of the scroll due to increasing pressure interrupted the burning process as soon as the fire was fully developed.

The total time elapse from fire start to fully developed fire is estimated to be a few milliseconds, say 10/1000 to 20/1000.

Summarizing, it can be stated that the fire will always follow the boundary layer flow because

- 1) the boundary layer flow velocity is low;
- the direction of the boundary layer flow is always from high pressures to low pressures in stationary parts;
- 3) in rotating parts the statement under 2) is only true for gaseous boundary layer. In other words, the boundary layer starts to flow in the direction of lower pressure as soon as it has been gasefied.
- 4) Due to low flow velocities the LOX can be gasefied in the boundary layer without being carried away if enough heat input is provided.



This document contains information officething the inditional defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.





FIGURE 1 VIEW OF TEST SITE



SERVICE TOWER FIGURE 2











5.5-25

FIGURE 5 AFT THREE-QUARTER VIEW OF SUSTAINER



C



This document contains informative attactions the macine defendence of the United Grober which the meaning of the Espionage Laws, Title 18, U.S.C., Soction 793 and 794, the transmission or revolution of which in any manner to an unauthorized person is prahibiled by law.





5.5-27

FIGURE 7

TURBOPUMP, RIGHT SIDE



Ĺ



RECOVERED PARTS OF PUMP VOLUTE

FIGURE 8







- -

- -

.

-

FIGURE 9 INLET SIDE OF HS VALVE



FIGURE 10 RECONSTRUCTION OF HS VALVE DAMAGE









FIGURE 13 HS VALVE IDLER SHAFT BEA' ING



This document contains information-affecting the material detends of the United States within the meaning of the Espionage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.





5.:-34

6 Э



FIGURE 15 DEPOSITS ON INLET SEAL







1

6.1-1

:

6.0 <u>ENCLOSURES</u>

Z

1

....

6.1 <u>COMMAND NET VOICE TAPE</u>

The following tabulation presents a running account of voice communications during Run 613-14, as recorded from the Command Net. The tabulationstarts at X-12 minutes and includes the one hour hold period.

TIME	NAME	CONVERSATION
12/28/21	P.A.:	Mark X minus 12 minutes.
	P.A.:	Set condition red.
	P.A.:	Time is 12:29 PDST
	P.A.:	Start of countdown.
	P.A.:	All personnel remain in assigned blockhouse
		positions. Transfer room personnel clear the
		transfer room and report. Test Conductor?
	J. Stewart:	Go ahead.
	R. MaGuire:	Transfer room is cleared.
	J. Stewart:	Thank you.
	P.A.:	X minus 11 minutes 30 seconds, mark!
	T. Cross:	Airborne fill and drain valve in silo position.
	P.A.:	X minus 11 minutes 20 seconds, mark!
	D. Burgess:	Instrumentation on slow.
	P.A.:	X minus 11 minutes, mark!
	P.A.:	X minus 10 minutes 50 seconds, mark!
	N. Skow:	Acoustica ready.
	P.A.:	X minus 10 minutes 40 seconds, mark!
	D. Burgess:	Instrumentation ready.
	T, Cross:	Ground fill and drain valve open.



This decompar contains information allowing the obtained defance of the Utility Atoms within the meaning of the Espionese Leve, Title 18, U.B.C., Section 773 and 774, the transmission or revolution of which in any member to an uncutherized person is prohibited by lew.

6.1-2



COMMAND NET VOICE TAPE (Continued)

~

J

2

1

THE	NAHE	CONVERSATION
12/28/21 (Cont'd)		
	P.A.:	X minus 10 minutes 25 seconds, mark!
	R. Bray:	Pre-start ready.
	P.A.:	X minus 10 minutes 20 seconds, mark!
	D. Burgess:	There will be no standardization of Brown
		recorders.
	R. Bray:	Shutdown power on.
	P.A.:	T minus 10 minutes 10 seconds, mark!
12/30/04	R. Bray:	Silo operation.
	P.A.:	T minus 10 minutes 5 seconds, mark!
	P.A.:	T minus 10 minutes, mark!
	R. Maguire:	Instrumentation on.
12/30/23	P.A.	T minus 9 minutes 52 seconds, mark!
12/30/23	V. Speer:	Start countdown.
	P.A.:	Minus 9:50mark. Minus 9:49. Minus 9:47.
	J. Casto:	Hydraulic pressure ok.
,	P.A.:	Minus 9:42.
		Fox 1145 normal.
12/30/49	V. Speer:	Start lox chilldown.
		HCU bottle pressure normal.
	#==#=	Start 2 storage tank ullage normal.
1	P.A.:	T minus 9 minutes 17 seconds.



This designed contains information affecting the national default of the United States within the meaning of the Essionage Laws, Title 18, U.S.C., Section 773 and 774, the transmission or revelation of which in any memory to be unauthorized person is prohibited by law.



COMMAND NET VOICE TAPE (Continued)

TIME	NAME	CONVERSATION
12/30/49 (Con	t'd) .	
		Vent 2 pressure complete.
		Pump inlet normal.
	T. Cross:	Lox prefill switch on.
	P.A. 3	T minus 9 minutes 12 seconds
••		T minus 9 minutes 7 seconds
	J. Stewart:	Report any system No Go.
	P.A.:	T minus 9 minutes, mark!
	Inst:	Indication on Uncle 1080 Peter.
12/31/27	R. Bray:	Start rapid load.
		Garbled - (Two voices at same time)
	P.A.:	T minus 8 minutes 37 seconds, mark:
	P	Lox storage tank ullage normal.
	P.A. :	T minus 8 minutes 25 seconds, mark!
	R. Bray:	Engine timers ready.
		Mark 10 per cent.
	P.A.:	T minus 8 minutes, mark!
		Mark 20 per cent.
	P.A.:	T minus 7 minutes 52 seconds, mark!
	V. Speer:	Engine and missile power ready.
	دو ها هر ور ه	Camera power on.
	R. Killian:	Does that look good, Tim?



٢.

ing of the Esplo , Title This document controlse information 18, U.S.C., Section 793 and 794, the éct'e

6.1-3

1



COMMAND NET VOICE TAPE (Continued)

TIME	NAME	CONVERSATION
12/31/27 (Co	ont'd)	
	T. Cross:	It looks pretty fast for the first part.
	بر میچو می	Mark 30 per cent.
		Mark 40 per cent.
	P.A.:	T minus 7 minutes, mark!
		Mark 50 per cent.
	P.A. 8	T minus 6 minutes 52 seconds, mark!
		Mark 60 per cent.
	J. Stewart:	Slowing down.
	هند بين جو جو	Mark 70 per cent.
	P.A.:	T minus 6 minutes, mark!
		T minus 5 minutes 52 seconds, mark!
		Mark 80 per cent.
	P.A.:	T minus 5 minutes 32 seconds, mark!
		Mark 90 per cent.
	P.A.:	T minus 5 min. 22 seconds, mark!
		Nancy 1519 Peter 3 pounds.
	P.A.:	T minus 5 min. 12 seconds, mark!
12/34/59		95 per cent
		Garbled - (Indication on)
		L2 closed.

Nancy 1519 Peter, 2 pounds.



This decument contains informat 15, U.S.C., Section 793 and 794.

6.1-4



COMMAND NET VOICE TAPE (Continued)

C

(

.....

CONTAID REI VOICE IALE (CONCIMUED)			
TIME	NAME	CONVERSATION	
12/34/59 (Cont'd)			
	P.A.:	T minus 5 minutes, mark!	
	T. Cross:	Low topping.	
		Engine amiss, oops!	
12/35/24	T. Cross:	High topping.	
	P.A.:	T minus 4 minutes 37 seconds, mark!	
	C. Clayborne:	RCC active.	
	P.A.:	T minus 4 minutes 22 seconds, mark!	
	C. Hyde:	Test readiness measurements satisfactory.	
	V. Speer:	Flight control and R/V ready.	
	وهوا هيو شمالي والد	Fox 1952 Peter 120 pounds.	
	P.A.:	T minus 4 minutes 7 seconds, mark!	
	~~~~	Nancy 1530 Peter 9.4.	
12/36/15	P.A.:	T minus 3 minutes 57 seconds, mark and	
		holding.	
	J. Stewart:	Instrumentation prepare for test objective	
		PF30 and PF38.	
		Ready for commit.	
	J. Stewart:	Start the 1 hour hold and call out every	
		10 minutes.	
	T. Cross:	Peter 1682 Peter, what do you read?	
		1682 Peter is reading 1.4 psid.	
	T. Cross:	Roger。	



This decument contains information affecting the instituted defense of the initial States within the meaning of the Espinnesse Lews, Title 18, U.S.C., Section 793 and 794, the transmission or revolution of which in any menner to an unauthorized person is prohibited by lew.

-----

6.1-5

-


()

(]:

(

COMMAND NET V	OTCE TAPE (Cont.	imied)
TIME	NAME	CONVERSATION
 12/36/15 (Con	 t'd)	
		and going up a little.
		Fox 1952 Peter is slowly decreasing and
		it's now 105 pounds.
	T. Cross:	Roger.
	T. Cross:	Nancy 1519 Peter, what do you read?
		1.8 pounds.
T. Cross:		Roger.
	J. Stewart:	Observers can we have a report on the con-
		dition of the stand and the missile?
	G. Grande:	Everything normal at the South Tank.
		Everything appears normal at the Blockhouse.
	R. Smay:	North tank reports normal.
	J. Stewart:	Roger, thank you.
		Fox 1952 Peter is rapidly decreasing. It's
		now 60 pounds.
	T. Cross:	Roger.
	R. Killian:	Gentlemen, we would like to restrict the
		lunch eating to either the back bay areas
		or else the basement.
	R. Killian:	No, you're not. When Herb comes back, he
	,	will take over these two, ok. And when Rich

6.1-6



This decensent casheles information efforting the optional defense of the United States within the meaning of the Espionee," Laws, Title 18, U.S.C., Section 793 and 794, the traduction of protection of which in buy manner to or unautherized person is prehibited by law.



(Continued)

COMMAND NET VOICE TAPE

TIME

12/36/15

NAME CONVERSATION R. Killian: (Cont'd) comes back he'll take this one; and when Miller comes back he'll take this one. T. Cross: Test Conductor? R. Killian: Go ahead. T. Cross: We just got our first topping cycle at 6 minutes. R. Killian: Roger, good enough. T. Cross: Nancy 1524 Feter, what do you read? 25 pounds. T. Cross: Roger. C. Hyde: Tim, and 1501 is holding very steady at 149. T, Cross: Roger, thank you. R. Killian: Does that 1054 look OK? R. Killian: 1054 look OK during tanking? T. Cross: Peter 1682 Peter, what do you read? Peter 1682 Peter is reading 1.38. T. Cross: Roger. T. Cross: 1682 what do you read now? 1682 Peter is reading 1.4 psig. T. Cross: Roger, let me know at any time if it goes above 1.42.

UNCLASSIFIED

Will do.

is decument contains informatibut affecting the national defense of the United States within the meaning of the Espionage Lews, firm B, U.S.C., Section 793 and 794, the transmission revelation of which is non-memory-a an unauthorized person is prohibited by law.

î

6.1-7



COMMAND NET VOICE TAPE (Continued)

TIME

| >

(

NAME CONVERSATION 12/36/15 (Cont'd) P.A.: Stand by for hold plus 10 minutes. P.A.: Mark! Hold plus 10 minutes. T. Cross: Nancy 1530 Peter, what do you read? T. Cross: Nancy 1530 Peter, what do you read! Coming up. Nancy 1530 Peter reads 9 pounds. T. Cross: Roger P.A.: Stand by for hold plus 20 minutes. P.A.: Mark! Hold plus 20 minutes. T. Cross: Nancy 1530 Peter, what do you read? 8 point.....8.....(Comm trouble). I'll try to get it for you in a minute here. T. Cross: Roger. 8.18. T. Cross: Reger. P.A.: Standby for hold plus 30 minutes. P.A.: Mark! Hold plus 30 minutes. T. Cross: Nancy 1530 Peter, what do you read? 7.25. T. Cross: Roger. 1682, what do you read? T. Cross: 1.35



6.1-8



6.1-9

COMMAND NET	VOICE TAPE	(Continued)
TIME	NAME	CONVERSATION
12/36/15 (Q	ont'd)	
	T. Cross:	Roger.
	T. Cross:	82, what do you read?
		1.35.
	T. Cross	Roger.
	r.A.,	Standby for rold plus 40 minutes.
	T. Cross:	1582, what do you read?
		1.35.
	T. Cross:	Roger. Did you notice any flucttion at
		all?
	P.A.:	Mark! Hold plus 40 minutes.
		It's fluctuating slightly between 1.35,
		sometimes as high as 1.4.
	T. Cross:	Roger - Goodi
	T. Cross:	Nancy 1530 Peter, what do you read?
		6.5.
	T. Cross:	Roger,
	T. Cross:	Nancy 1524 Peter, what do you read?
		Zerc or very close to maybe a half a pound.
	T. Cross:	Roger.
	10 million (1994)	Nancy 1524 Peter is increased to about 4 pounds.
	T. Cross:	Roger. Will you let me know when it hits
		ten pounds?



(

This document contains informative attyction the notional setange of the United States within the meaning of the Espioneed Laws, Title 18, U.S.C., Section 793 and 764, the transmission of the Vision attraction of the set of the set



COMMAND NET VOICE TAPE (Continued)

TIME

NAME CONVERSATION 12/36/15 (Cont'd) Affirmative. Nancy 1524 Peter indicating 10 pounds. T. Cross: Roger, thank you. Nancy 1524 vented down to about 1 pound. T. Cross: Roger. T. Cross: Nancy 1501 Peter, what do you read? P.A. 2 Stendby for hold plus 50 minutes. Nancy 1501 Peter reads 155 pounds. T. Cross: Roger. P.A.: Mark! Hold plus 50 minutes. R. Killian: Oh, North Tank? R. Smay: North Tank. R. Killian: How's everything look? R. Smay: Everything's normal. South Tank? R. Killian: G. Grande: Everything's normal. Blockhouse? R. Killian: Appears normal from here. R. Killian: Roger. Periscope? Normal from here. R. Killian: OK.



6.1-10



6.1-11

÷

TIME	NAME	CONVERSATION
12/36/15 (0	Cont'd)	
	R, Killian:	We would like everyone to within the next
		5 minutes close out their lunch period an
		resume their countdown stations.
	R. Killian:	Would like hold time called out at hold
		plus 55 minutes, Murphy, and hold plus or
		hour.
		Nancy 1524 Peter indicates 10 pounds.
	T. Cross:	Roger.
	R. Killian:	At hold plus 55 minutes, I expect everyon
	•	to be on their countdown stations, on the
		job. I expect them to review all their
		console status as well as measurement sta
		Report anything which is of a questionable
		nature, so that at hold plus one hour we
		can pick up a systems readiness check.
	P.A.:	Mark! Hold plus 55 minutes.
	J. Stewart:	Instrumentation, did you get your FM tap
		changed all right?
	المرجع ويرجع والمرجع	All tapes changed. Instrumentation read
	r. Cross:	Nancy 1530 Peter, What do you read?
		5.4

This document contains information of the discovery discovery of the United State within the meaning of the Espionoge Lews, Title 10, U.S.C., Section 793 and 794, the transmission or revolution of which in any monner to an unauthorized person is prohibited by law.



1-

6.1-12

COMMAND NET	<u>COMMAND NET VCICE TAPE</u> (Continued)		
TIME	NAME	CONVERSATION	
12/36/15 (C	12/36/15 (Cont ⁱ d)		
		155 psi.	
	T. Cross:	Roger.	
		152, correction.	
	T. Cross:	Roger. Nancy 1530 Peter, what do you read?	
	<b></b>	5.4 on Nancy 1530 Peter.	
	T. Cross:	Roger.	
	T. Cross:	Fox 1952 Peter, what do you read?	
		2 pounds.	
	T. Cross:	Roger.	
	R. Killian:	South Tank, do you have LN2 vapors going	
		back up into the bucket?	
	G. Grande:	No, we don't Roy.	
	R. Killian:	North tank, do you have any evidence of vapors	
		coming out from underneath the thrust section?	
	R. Smay:	I see vapors around the LN2 overboard duct	
		and just about in the center between Quads	
		I and II.	
	R. Killian:	OK. Those are probably coming from the engine	
		control bottle.	
	R. Smay:	Right。	
	T. Cross:	Test Conductor?	
	J. Stewart:	Go ahead.	
LIN	LINCLASSIFIED		



This document contains information effecting the notional defence of the United Stuffs within the meaning of the Espionage Laws, Title 18. U.S.C., Section 793 and 784 the transmission or revelotion of which in one manner to an unsuffected person is prohibited by law.

.....



<u>COMMAND NET VOICE TAPE</u> (Continued)

TIME

CONVERSATION NAME 12/36/15 (Cont'd) T. Cross: Lox system is satisfactory. R. Killian: What does 1290 Tare read? J. Stewart: Thank you. Plus 50, Roy. R. Killian: Flus what? Plus 50 degrees. R. Killian: Roger. R. Killian: OK. We are getting kind of low on engine control supply pressure, I mean supply temperature. J. Stewarts Roger. Place the Step three permit override switch on. H. Lipp: Step three over-ride switch on. R. Killian: We should be watching or paying particular attention to 1474 Peter. Test readiness measurement satisfactory. R. Killian: With this cold temperature, particularly at the vernier tanks pressurized. J. Stewart: Could I have a report on the Nancy 1530 Peter? Nancy 1530 Peter 5.25. J. Stewart: Thank you. J. Stewart: Report system readiness when called out. UNCLASSIFIED

6.1-13



COMMAND NET VOICE TAPE (Continued)

TIME

CONVERSATION NAME 12/36/15 (Cont'd) J. Stewart: Facility Power? H. Taylor: Go! Missile Power? J. Stewart: H. Taylor: Go! Flame Deflector? J. Stewart: G. Richardson: Go! J. Stewart: Firex? G. Richardson: Go! Pneumatic? J. Stewart: R. Masters: Go! J. Stewart: Lox? Ge! T. Cross: J. Stewart: Fuel? T. Cross: Go! J. Stewart: Purge? E. Miller: Go! J. Stewart: Autopilot? J. Casto: Go! J. Stewart: Hydraulic?

> Go! J. Casto:

J. Stewart: Engine Test?

Go!

H. Lipp:



Title 18, U.S.C., Section 793

6.1-14



()

C

.

~

6.1-15

COMMAND NET VOICE TAPE (Continued)		
<u>TIME</u> <u>N</u>	IAME	CONVERSATION
12/36/15 (Cont'	d)	
ľ,	Stewart:	Auxiliary Control?
H	l. Lipp:	Gol
J	。 Stewart:	Test Conductor Console?
R	l. Bray:	Gol
J	. Stewart:	Launch Officer Console?
v	. Speer:	Go!
J	. Stewart:	Instrumentation?
R	. MaGuire:	Go !
J	. Stewart:	RCC?
C	. Clayborne:	Go!
J	. Stewart:	Acoustica?
N	. Skow:	Go!
Na	。Skow:	Acoustica dialed in sensor Station 2.
J	. Stewart:	Well, I didn't request it yet.
N	. Skow:	Are you going to request it?
G	Grande:	Test Conductor?
J.	Stewart:	Go ahead.
G.	, Grande:	We have an indication of heavy frost around
		the inside of the thrust section around the
		lower edge in Quad IV.
J.	Stewart:	Around the fireshield?
G.	Grande :	Roger。
UNCLASSIFIED		



defynes of the Unifed States within the meaning of the Espionage L. s. Title This document contains information affecting the netronal of 18, U.S.C., Section 793 and 784, the transfersion of restant

- - ----



(

6.1-16

ł

COMMAND NET VOICE TAPE (Continued)		
TIME	NAME	CONVERSATION
12/36/15 (Cont'd)		
	R. Killian:	Around the fireshield, George?
	G. Grande:	les, Roy.
	P.A.:	Standby for hold plus one hour.
	R. Killian:	OK, can you tell what the status of the
		vernier lox vent bleed is?
	G. Grande:	Seem to be getting
	P.A. :	Mark! Hold plus one hour.
	G. Grande:	We seem to be getting some liquid out of it.
	R. Killian:	Okay.
	R. Killian:	Do you see anyis it external on the
		thrust section in that area, George?
	G. Grande:	Well, it's hard to tell from here, Roy. It
		shows a heavy frost on the outside.
	R. Killian:	Well, what I'm trying to find out, is it
		right on the X-X axis in the area where the
		topping fill line goes in, or is it over in
		the Quad IV area between the Sustainer and
		the booster where the vernier lox vent line
		comes out?
	G. Grande:	Seems to run from Quad III all the way over to
		Quad IV, Roy.



This decement contains information whething the Instantial advanted of the United States within the meaning of the Espionage Lews, Title 18, U.S.C., Section 793 and 794, the transmission or revolution of which in any menner to an unautherized person is prohibited by lew.

**



6.1-17

#### COMMAND NET VOICE TAPE (Continued)

TIME

NAME CONVERSATION 12/36/15 (Cont'd) R. Killian: All the way from Quad III to Quad IV. Where does it start in Quad III? G. Grande: Approximately the lower camera area. R. Killian: Lower camera area and how far over into Quad IV? G. Grande: All the way over to the nacelle. R. Killian: All the way over to the nacelle? J. Stewart: Can we have the camera operator pan that camera over? R. Killian: Well, it's been some time since we held for an hour, George. Do you have any .... were you on any of the operations where we held for an hour? G. Grande: Yes, I was, Roy. I never noticed this before. J. Stewart: You'll have to pan it up there. R. Killian: No, I'd be particularly not, since we have held for an hour recently, George, but sometimes in the past whenever we had thrust section ambient in and we held for an hour,

> the Quad IV area always had a considerable habit of being extremely low. We have been



of the Espionage La This document contains information 18, U.S.C., Section 793 and 794. the rs, Title



(

<u>(</u>_-

Ĩ

6.1-18

COMMAND NET VOICE TAPE (Continued)			
TIME	NAME	CONVERSATION	
12/36/15 (Con	t'd)		
	R. Xillian: (Co	nt'd)	
		filling the IN2 shouds for sometime and	
		topping all this time.	
	G. Grande:	Roger.	
	R. Killian:	Plus the fact we have excellent observation	
		conditions today.	
	R. Killian:	How does the thrust section ambient look?	
•	متعلق ملك المراجع	Normal.	
·	R. Killian:	All normal?	
	<b></b>	All normal.	
	R. Killian:	Nothing at all that's lower than normal?	
	,	Or anusual on a short hold?	
		Nope, they are all normal.	
	R. Killian:	Dave, do we still have the instrumentation	
		in for the Support Rod in Quad IV that we used	
		on the Soak Evaluations?	
	D. Burgess:	Negative, I don't think we do.	
	R. Killian:	There are an awfully lot of ambients hangling	
		around up there, and I would like to know	
		what the status is of the circuitry. Far as	
		I know none of it has been pulled out.	



This document contains information affecting the notional detense of the United States within the meaning of the Espionage Laws, Titio 18, U.S.C., Section 793 and 794, the transmission or revolution of which in any manner to an enauthorized person is prohibited by law.



6.1-19

ŝ

f

COMMAN	ID NET VOICE TAPE (Cor	itinued)
TIME	NAME	CONVERSATION
12/36/	(15 (Cont'd)	
	W. Melendez:	This is correct, Roy, but they are still
		in for print, but not connected electrically
		on the 1800 series.
	R. Killian;	How far does it come to?
	R. Killian:	Is it disconnected the in J Box?
	W. Melendez:	It's disconnected electrically, right.
	R. Killien:	No, he can do it.
	R. Killian:	George, how far up on the barrel section
		does the frost go?
	G. Grande:	Approximately 18 inches, Roy.
	R. Killian:	OK.
	R. Killian:	Is it fairly heavy?
	G. Grande:	Not particularly heavy, just shows an
		indication of being white and frosted up.
	R. Killian:	OK.
	R. Killian:	You can't see any part of the fire shield
		underneath, can you?
	G. Grande:	No, I can't Roy.
	R. Killian:	How about the disconnect there? Is it
		heavily frosted? Should be.
	G. Grande:	Yes, there is quite a bit of frost there.
	R. Killian:	ok. 🏶
	UNCLASS	IFIED
	CONFIDEN	TIAL
This document contains information 18, U.B.C., Section 793 and 794,	en attactive the national deviates of the Un	nited Service within the meaning of the Espionage Laws, Title any memory of an interface person is prohibited by law.



6.1-20

í

rs, Titie hv law.

TIME	NAME	CONVERSATION
12/36/15	(Cont ⁱ d)	
	R. Killian:	OK, Jim, let's pick it up.
	J. Stewart:	OK, Tim, how's the lox level?
	T. Cross:	Nancy 1530 Peter?
		4.75
	T. Cross:	Roger, lox level satisfactory.
	J. Stewart:	Roger.
	J. Stewart:	Acoustica, dial in sensor station #2 and
		report. :
	N. Skow:	Sensor station #2 has been dialed in.
	J. Stewart:	Roger.
	J. Stewart:	Switch all instrumentation to fast and
		report.
	R. MaGuire:	All instrumentation on fast.
13/40/51	J. Stewart:	Press start commit.
	V. Speer:	Start commit power internal amber.
	V. Speer:	Power internal green.
	P.A.:	Mark T minus 3 minutes 43 seconds.
	R. Masters:	Step III Light.
	R. Masters:	Boiloff valve closed light.
	P.A.:	T minus 3 minutes 27 seconds, mark!
		T minus 3 minutes 24 seconds, mark!



This document contoins information within the notional define of the United States within the meaning of the Esple 18, U.S.C., Section 793 and 784, the transmission or revolution of which in diry memoryle-an inertherized person is pr

3

J



COMMAND NET VOICE TAPE (Continued) CONVERSATION TIME NAME 13/42/14 R. Masters Internal..... (simultaneously) J. Casto 011 evacuation ..... P.A.: Minus 3 minutes 20 seconds, mark! H. Taylor: Inverter on. T. Cross: Hi Topping. P.A.: T minus 3 minutes 12 seconds, mark! ____ 1582 reading 135 at high topping. P.A.: T minus 3 minutes, mark! P.A.: T minus 2 minutes 43 seconds, mark! P.A.: T minus 2 minutes 35 seconds, mark! T. Cross: 100% P.A.: T minus 2 minutes 33 seconds, mark! Missile lift up and locked in amber. T minus 2 minutes 30 seconds. R. MaGuire: T 3 on. R. Killian: Lock Topping tank is vented, Tim. T. Cross: Roger. P.A.: T minus 2 minutes 23 seconds, mark! Vapors to LN2 vent duct. P.A.: T minus 2 minutes, mark! R. Killian: Say it again, Smitty. Vapors to LN2 vent duct is venting the tank.

6.1-21



Ż.

This document contains informetted <u>(effecting the setional defense</u>) of the United States within the mounting of the Esplanage Lews, Title In 118 C. Section 792 and 794 the transmission of Partnerson which is new support to an unauthorized person is prohibited by low.

6.1-22



COMMAND NET VOICE TAPE (Continued)

TIME	NAME	CONVERSATION
13/42/14 (Cont'd)		
	R. Killian:	Roger.
	P.A.:	T minus 1 minute 50 seconds, mark!
	G. Richardson:	Start main deflector water.
	P.A.:	T minus 1 minute 42 seconds, mark!
	R. Killian:	Will that thing run on local? Will that
		recorder run on local? If it will put it
		on local and let's have local control.
	P.A.:	T minus 1 minute 25 seconds, mark!
		Won't run anyway.
	P.A.:	T minus 1 minute 18 seconds, mark!
	P.A.:	T minus 60 seconds, mark!
	G. Richardson;	Launcher coolant on. Start vernier flame deflector.
	R. Killian:	Remember, gentlemen, ignition start may
		occur before the time count runs out or
		slightly after. Do not panic.
	P.A.:	Minus 50 seconds.
	R. Smay:	North tank water ready.
	P.A.:	Minus 40 seconds.
	P.A.:	Minus 30 seconds.
	J. Stewart:	South tank, report water system.
	G. Grande:	Water OK.



-

This decument contains information affecting the optional decases of the Uplied States within the mouning of the Espionage Lews, Trite 18, U.S.C., Section 793 and 794, the transmission of structure of which in day standard to an unsuttarized person is prohibited by law.



6.1-23

۰ ، م^ر ۲

	COMMAND NE	<u>r voice tape</u> (Cont	tinueā)
	TIME	NAME	CONVERSATION
	13/42/14	(Cont'd)	
		P.A.:	Minus 20 seconds.
		P.A.:	Minus 18 seconds.
		G. Richardson;	Engine CO2 on.
		R. Killian:	Hey George, you'll have to speak up; we
			can barely hear you.
		PA. ;	Minus 15 sec.
		R. MaGuire:	T 2 on.
		P.A.:	Minus 10 seconds.
		P.A.:	Nine.
		P.A.:	Eight.
		P.A.:	Seven.
		P.A.:	Six.
		P.A.:	Five.
		R. MaGuire:	Run camera's on.
		P.A.:	Four.
		P.A.:	Three.
		P.A.:	Τωο
		P.A.:	One .
		P.A.:	Zero.
13/45/38	}	R. Killian:	Ignition Start.
		F.A.:	One.



t

This decument centeins information affecting the national defense of the United States which he meaning of the Espionage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revolution of which in any manner to an unauthorized person is prohibited by law.



COMMAND NET VOICE TAPE (Continued)

TIME NAME CONVERSATION 13/45/38 (Cont'd) P.A.: Two. Horn. R. Killian: Cutoff and all water on! All water on!! All water on!! All water on! All water on!! All water on!! 13/45/50 (Approximately) From this point on, many bits of conversation are on tape but quite unintelligible due to lack of volume and noise interference. R. Killian: Ready to explode !!!!!!! (Unintelligible talking and noise) Lost everything, we lost everything, tower and all. R. Killian: OK. Gil, will you call out the Fire Dept., please? H. Gillespie: Affirmative. R. Killian: Turn off tower fog. UNCLASSIFIED

CONFIDENTIAL

This decument centains information attacking the national defense of the United State within the meaning of the Espionage Laws, Title 18, U.S.C., Section 793 and 794, the transmission of revolution of which in any manner to an unauthorized person is prohibited by law.

6.1-24



COMMAND NET VOICE TAPE (Continued)

. چەربا

**E**,

I

TIME	NAME	CONVERSATION
13/45/50 Appro	oximately (Cent	'd)
	R. Killian:	Cutoff the topping tank.
	R. Killian:	Excuse me.
	R. Killian:	Leave the topping tank on.
	(Unintelligible	conversation)
	R. Killian:	No need to go to the Annex, just hold
		everything down, till Security's in the
		area.
	R. Killian:	Security - Security - Security Control!
		Will someone see if we have any telephone
		communications and get in contact with
		Security Control, please?
	H. Gillespie:	This is Security Control - Go ahead.
	- art 900 kits.20	Missile tank pressure has dropped off
		hit cutoff button
	معید کار در ا	Missile lox tank pressure has dropped off
		all water
	J. Stewart:	Instrumentation on slow.
	R. MaGuire:	Instrumentation on slow.
	T. Sickich:	Testing one, two, three, four,
	T. Sickich:	Testing one, two, three, four.
		59 huh?





United States withing the meaning of the Esplanage Laws, Title a any manner to an unauthorized person is prehibited by law. This document contains information officing the dotternal defense at the 18, U.S.C., Section 793 and 794, the transmission or revelation of which in

6.1-25

?



ي. م

\$

·. -

۶.

6.1-26

COMMAND NET VOICE TAPE (Con	tinued)
TIME NAME	CONVERSATION
13/45/38 Approximately (Con	t'd)
T. Sickich:	Let's see, John, help me get all these
	stand lines will ya? Get everything from
ĝ	60 down except don't touch 85; well, let's
•	see85's out there.
	Did you get Security yet?





This decument centains information attecting the national defence of the linited States within the meaning of the Esplonage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revolution of which in any manner to an unauthorized person is prohibited by law.



#### 6.2 OFFICIAL OBSERVERS REPORTS

Presented in this section are the official observer, console operator, recorder monitor, and countdown caller reports as presented to the test conductor subsequent to termination of the run. The reports have been transcribed from the command net voice tape and edited so as to include only pertinent conversation.

#### SOUTH TANK

(

Ē

ŧ

Jim Stewart: OK, South Tank would like to review once more what you observed. George Grande: At the time of ignition start, I observed fire which was a larger than usual fire; it seemed to be all about .. ...oops! think we're losing communication again. It seemed to be all about the bottom of the missile, lower edge of it, Jim, and it spread quite rapidly. As soon as I seen this I was sure I knew what was gonna happen so I ducked into the tank at the time I seen the fire and reported FIRE, and I no sooner got into the tank when it did explode and I yelled out EXPLOSION. Stewart: OK. Did you cut or press your cut-off button? Grande: No, Jim. As soon as I seen the fire I knew it was gonna happen so I ducked in. I didn't have time to even think about touching the button. Stewart: OK. And the condition of the silo topping tenk? Grande: At the time? Stewart: No, after the explosion. Grande: After the explosion it seemed to be all right. There's a...like I say ... part of the stand was down over the top of the

area there but it seems to be OK.



This document contains information affecting the institute defense of the United States within the researing of the Espienced Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unavitationed person is prohibited by law.

6.2-1



6.2 (Continued) OFFICIAL OBSERVERS REPORTS Stewart: And the condition of the rapid load tank? There is part of the, oh, stand and debris Grande: on top of the area but the tank itself seemed to be OK. Stewart: And the condition of the GN2 pre-fab? Grande: The GN2 pre-fab is in fairly good condition other than debris around it. Stevart: And the GN2 storage vessels? Grande: The GN2 storage vessels themselves are intact; the H---compressor has the...lids and stuff blown off of it. Stewart: The fuel transfer unit. Grande: It is OK. There's debris around the area, but other than that it seems to be OK. NORTH TANK Stewart: OK. North tank. You want to review your observations. Reginal Smay: At the time of ignition start; right at

ignition start it seemed like a normal ignition but this kept; this got larger until the flames billowed out under the thrust section and on the outside of the thrust section; at this time I realized it was an explosion, and I hollered EXPLOSION and reached for my cut-off button And at the same time, I dropped down into the tank and it exploded before I could actually push the cut-off button. In the explosion we had debris, we had one helium ball light on the hill up here and roll down next just on the other side of the escape road. It's laying down here in the canyon now. It seemed to be aflame as it rolled down. And I don't know how much other debris was in the air at the time.



This document contains information affecting the national datance of the United States of the Explanade Laws, Titio 18. U.S.C., Section 793 and 784, the transmission or revolution of which in any manner to an unauthorized person is prohibited by law.



6.2	OFFICIAL OBSERVERS REPORTS	(Continued)
	Stewart:	You didn't observe the verniers lighting off?
	Smay:	I saw no sign of vernier ignition. I believe the explosion was before time for vernier
	Stewart:	And the concentration of the explosion was at the bottom of the missile?
	Snay:	At the bottom of the missile. In fact I saw no
	Stewart:	initial explosion?
	Smay:	initial explosion from this side, it just looked like big flames had billowed out almost simultaneously with ignition; with ignition start.
	Stewart:	In your direction, right?
	Smay:	From this direction.
	Stewart:	OK. South tank?
	Grande:	Go ahead, Jim.
	Stewart:	Did you see flames from your direction or towards your direction:
	Grande:	You mean, at the explosion or the
	Stewart:	When you first noticed the flames and the fire.
	Grande:	No, Jim. They just seemed to spread rapidly, very rapidly out of the area from underneath the bottom part of the missile.
	Stewart:	Roger. Thank you.
	TEST CONDUCTOR CONSOLE OPE	RATOR

Royce Bray:

į

Observations from commit phase and start. Everything was normal up until ignition start. I was watching for the R&D operation light.



This decument contains information affecting the notative defance of the United States within the meaning of the Espionage Levre, Title 18, U.S.C., Section 793 and 794, the transmission or revelection of which in any menner to an unautherized person is prohibited by law.



6.2 OFFICIAL OBSERVERS REPORTS (Continued)

(

ſ

(Continued) Before the R&D operation light came on there was delta p and the explosion. I reached for the stop button, it was already red, it was already cut off. The light had not come on when I heard either the DP or the explosion. No, I don't know which I heard first. It probably came on with the cutoff.

Roy Killian: Jim, do you have any comments?

The only thing is I did observe the R&D light on after the explosion.

Killian: Which one?

The one on the Test Conductor's Console.

I will add something to that.

I mean which explosion?

Stewart: The second.

Killian: This before the shock wave?

Stewart: I can't recall.

Killian:

Royce Bray:

Stewart:

Stewart:

Killian:

LAUNCH OFFICERS CONSOLE CPERATOR

Verle Speers: All indications on the LOC was normal up until the time of the DPC sounded.
Killian: Do you have any recollection when the DP sounded, because I don't remember it sounding, but that's beside the point.
Speers: All I know, I got my engine start light normal and just hard to pin point any time.
Killian: Had you heard any buzzer yet to signify that we had gone back to R&D?

Speers:





This document contains information attaining the national defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any Manner to an unauthorized person is prohibited by law.



## 6.2 OFFICIAL OBSERVERS REPORTS

(Continued)

#### COUNTDOWN CALLER

Killian?

Charles Murphy:

Do you have anything as far as observations are concerned?

I did hear the buzzer on the LOC when it came on the delta p. I believe that was shortly after ignition, it sounded just prior to autopilot beginning to call run time.

#### MISSILE POWER FACILITY POWER MONITOR

Harley Taylor: Everything over here looked normal until explosion.

#### PNEUMATICS

Roy Masters:

Killian:

Masters:

Ð.

Were you looking at your tank pressure meters at all?

Everything on the pneumatics panel looked normal. I was watching the tank pressures up to the apparent explosion. At the same

Yes, I was and the tank pressures, the helium and delta p monitor all were normal.

time I observed emergency buttons.

#### LOX TANKING

Tim Cross:

Everything was normal. We seemed to have a normal rate decrease in lox. The explosion happened about lox topping drop out. We set up for a drain immediately after DP went off.

#### FUEL TANKING AND PURGE

Edward Miller:

On the fuel tanking, everything was normal. On the purge, I had a switch to turn on at three seconds and it seemed that at the time I reached for it everything happened.

#### HYDRAULICS AND AUTOPILOT

James Casto:

Hydraulics was normal. I remember that we did



This document contains information allocating the maintain defense of the United Stated within the meaning of the Explanate Late, it is 18, U.S.C., Section 793 and 794, the transmission or revolution of which in any member to an unauthorized person is prehibited by law.



# 6.2 <u>OFFICIAL OBSERVERS REPORTS</u> (Continued)

HYDRAULICS AND AUTOPILOT

James Casto:

Killian:

Casto:

(Continued)

(Continued) drop back to R&D control...it sounded like a normal start and except for that slight delay from zero time and then immediately after the explosion they dropped out missile AC and DC and we indicated a load on the panel by dim lights so we killed panel power at this time.

Jim, did you call any time second count at all?

Yes, it seems like I called up to about one or two numbers and that's when the explosion occurred. 1 or 2 seconds, I don't recall.

Autopilot seemed to be normal up until the time of ignition. Booster start transients appeared to be okay, but sustainer start transients went immediately off scale until the explosion and we lost everything. The time indicator on the test programmer is stopped at 2.3 seconds which may be an indication of the time the explosion actually occurred.

#### ENGINE TEST PANEL AND OBSERVER CONTROL - FACILITY POWER

Herbert Lipp:

Bill Middendorf:

On the auxiliary control we got a cutoff right after engine start and I hollered CUTOFF, and then the explosion, maybe about the same time.

INSTRUMENTATION CONTROL

Dave Burgess:

It just so happened, Roy, I was watching the TV screen at the time. Normally I don't, but I was at this time, and it appeared that there was just too much fire. Normally you can sense that the amount of fire is correct. But there was just too much fire and it was apparent that there was evidently a lox rich atmosphere or something that was causing extra flames.



This document contains information difecting the notional defense/of the United States within the meaning of the Espionage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.



6.2-7

. . .

3

.....

: ,

2

2

....

6.2	OFFICIAL OBSERVERS REPORTS	(Continued)
	INSTRUMENTATION CONTROL (C	ontinued)
	Killian:	I'd like to go around the thrust section ambients.
	Bill Melendez:	Red Lines - P1677 was normal throughout until the blast when it pegged up positive. 1712 was riding normal at all times until the blast. 1325 was riding normal at all times. On 1710 it was riding normal and before, oh, at commit start, ignition, it gave a very slight pip, oh, about one increment. Wasn't anything great, but that is the only thing I ever saw on it.
	Killian:	Did you ever have any response on any of them as far as fire?
	Melendez:	No, nothing. Oh, after the blast everything went up.
	Killian:	That's what I'm saying, but before that nothing. What do you have on 1711 and 1290 and indications?
	Ray Neises:	No, 1711 was okay, of course, until after, and 1290 also normal.
	Killian:	Okay. Do you have anything as far as 1474, 1027, 1030?
	Edward Leonard:	No, I watched 74 right up to ignition start, and it was normal and at ignition start I shifted over to these two red lines. They seemed to be working normal and then it happened so quick that they just went right down again.
	Killian:	How about the PU valve - Do you have anything as to how it responded.
	Leonard:	Yes, it started up, I don't think it went up as high as it usually does and then it started down into the red line lower reading line, but this time we had cutoffs etc.



This document contains information affecting the national defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

.....



6.2 OFFICIAL OBSERVERS REPORTS (Continued)

ON SUSTAINER TEAP AND SUSTAINER LUBE OIL

On sustainer temp, it went up banged out normal Tony Tangorra: and all the way to the end and then it went right down. Killian; About the lube oil. The lube I had got a good look at that because Tangorra: I was watching the two second ones first. Killian: You didn't see anything at all? Tangorra: No. Killian: How about B-1 combustion temp and lube oil? Joe Semancsin: B-1 and P1713T came up within two seconds and then somebody was hollering to put the water on it dropped down, dropping down, and P1714T came up too within time, but didn't go down right away. Killian: Okay. Did both of them appear normal at start for SPGG's, Joe? Semancsin: Well, I believe this one could have been a little bit sluggish, but they both came up. Killian: Okay. Had they come out of the red lines and started back in? Semancsin: They didn't go all the way to the 1300 dgf. They came up to about 1200 dgf and dropped a little bit. Killian: Started back to normal? Semancsin: That's right. Killian: Good. Lube oils. Arthur MacGregor: P1473, P1272P both started to rise, but we were only about  $2 \frac{1}{2}$  seconds, and we got an explosion, and they dropped right back.



This decument contains information alloching the restance of the Unned States within the meaning of the Espionage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to the unauthorized person is prohibited by law. 6.2-8

1



#### 6.2 OFFICIAL OBSERVERS REPORTS

1

1

Į .

(

(_____

(Continued)

HYRDRAULIC REFURN PRESSURE	
Paul Battenberg:	At your command of "all water on" sustainer hydraulic pressure spiked to the right.
Killien;	What happened at start, Paul, as far as the two hydraulic pressures. I mean the two hydraulic pressures?
Battenberg:	They were normal and about your command at "all water on" the sustainer spiked and that caught my attention and I didn't get the booster.
Killian:	Okay. How about the booster and sustainer hydraulic supply pressures?
Lee Smith:	They were normal up until start. Apparently at the same time you yelled, "water on" I caught a flash in my eyes and at this time before I could even turn to the window looking, one time the booster had started up and then down the other was spiking erratic, but it had not spiked erratic until your command of "all water on".
Killian:	Okay. Any other recorder monitors have anything to report?
Don Hart:	On the pump speeds, I was watching Bl and B2 and both of these came up and I think that B2 dropped out and Bl was still up.
Killian:	Records will verify. This is only for backup information - not for the purpose of determining whether anybody missed anything on their obser- vation etc. just to see if there is anything that people can add that will further add to the data.
Killian:	Do you have anything to report Charlie Oliver?
Charles Oliver:	Really not much in addition to what's been said. I was watching measurements generally not any in particular.
Killian:	How about the pump inlet temps?
Oliver:	Pump inlet temps - they were good at start - and they were well within. Generally start transients looked normal and that is about as far as they went.



This decument cento: as information attacting the national determines, U.S.C., Section 7:3 and 794, the transmission or revelation of Lishin the meaning of the Espionage Laws, Title to an unauthorized person is prohibited by law. ates which in any manh to

-------



## 6.2 OFFICIAL OBSERVERS REPORTS

(Continued)

#### HYDRAULIC RETURN PRESSURE

Charles	Hyde:	

Killian:

Killian:

Barhan:

Killian:

Bradsher:

Killian:

Bradsher:

Killian:

Bradsher:

Don Hass:

1

Sam Bradsher:

, Jay Barham: I was observing FlOOl and 1003 at start. I saw what I feel to be a normal transient. It seemed that start occurred approximately two seconds after the countdown caller had called zero time. I then observed the ambients after the explosion and all the ambients that I could see were pegged positive.

Is there anyone in the back-bay Brown CEC or FM and Sanborn that has anything to report? - with regards to the pump inlet pressures, PCU pressures, temps, etc.?

The lox pump inlet pressure seemed kind of sluggish, they came up and then they started back down. There was an engineer in here.

We can get that from Bill Sveitzer. How about any of the other temps or valve positions etc.?

Only at time of explosion did the new Pl098D pegged negative.

Lox pressure reg inlet temp seemed to be functioning normally until the time of the explosion.

F1115T.

It is clear.

Do you have ideas as to what it was reading?

Approximately 200 to 225 dgf.

Negative 200 to 225 dgf cr pcsitive?

Positive.

Sanborn measurements all seemed to go up to the time of firing and then after that we did get some vibrations.



This document contains information allocting the national defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

---

6.2-10

6,2-11

-----



6.2	OFFICIAL OBSERVERS REPORTS	(Continued)
	COMMUNICATIONS	
	Tom Sickish:	Everything was normal with me, until the vibration rather.
	Killian:	Okay, I just wondered if you heard anything.
	Sickish:	No, the boiloff valve was normal and every- thing else.
	Clarence Cleyborne:	This RCC - everything seemed normal at the initiation ignition and then about two seconds later all of the channels started counting and the only one that actually showed a cutoff light was B1 able. The one that was nervous yesterday.
	Killian:	Okay. Acoustica?
	N. M. Skows	Acoustica was normal right up to the explosion and then we lost power.
	Killian:	Okay. The only thing I have to add is what I think nothing I think the perform- ance was excellent, people.



This document contains information effecting the motional automa of the United States within the meaning of the Espioneed Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any menner to an unauthorized person is prohibited by law.

-----

مترابعته هيمه استابا بالالا

- - -

-*

. .

- --

## 6.3 PHOTOGRAPHS

14 × 14

£

, ) , ,

t

Presented in the following section are pertinent photographs of Sycamore Site 1 damage.

Figure	6.3-1	Test stand area from pipeline trestle.
Figure	6.3-2	View of service tower from parking lot behind lox
-		storage area.
Figure	6.3 <del>-</del> 3	Test stand area from fuel farm looking toward blockhouse.
Figure	6:3-4	View of the service tower and facility equipment.
Figure	6.3-5	Sita 1 Blockhouse Annex interior.
Figure	6.3-6	Site 4 Utility Building.
Figure	6.3-7	Sustainer combustion chamber as recovered from skim pond.
Figure	6'.3-8	Sustainer combustion chamber after partial clean-up.
Figure	6.3-9	Sustainer lox duct adapter and part of broken lox pump
		volute.
Figure	6.3-10	Portions of the sustainer low pressure ducting.
Figure	6.3-11	Sustainer turbopump.
Figure	6 <i>.3-</i> 12	Sustainer turbopump.
Figure	6.3-13	Head suppression valve actuator housing.
Figure	6.3-14	Head suppression valve actuator shown in position on the
		thrust chamber.
Figure	6.3-15	Booster injector plate and fuel staging disconnect -
		forward half.
Figure	6.3-16	Bl turbopump assembly found wedged into tower structure.
Figure	6.3-17	Damaged booster turbine assembly.
Figure	6.3-18	Parts of B2 turbopump.
Figure	6.3-19	B2 turbopump components
Figure	6.3-20	Damaged propulsion system hardware - primarily B2 components.
Figure	6.3-21	Airborne pneumatics hardware,



This document contains information affecting the national defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

-----

6.

i



FIGURE 6.3-2



VIEW OF SERVICE TOWER FROM PARKING LOT BEHIND LOX STORAGE AREA (Neg. No. 37779A)



ية. حلة

1979 1879

FIGURE 6.3-3



TEST SAND AREA FROM FUEL FARM LOOKING TOWARD BLOCKHOUSE. LOX CONTROL PREFAB VISIBLE NEAR SERVICE TOWER. (Neg. No. 87833A)




.

FIGURE 6.3-4

VIEW OF THE SERVICE TOWER AND FACILITY EQUIPMENT (Neg. No. 87773A)





SL BLOCKHOUSE ANNEX INTERIOR (Neg. No. 87642A)





< .

FIGURE 6.3-6

S4 UTILITY BUILDING (Neg. No. 87635A)





SUSTAINER COMBUSTION CHAMBER AS RECOVERED FROM SKIM POND (Neg. No. 87862A)



1



SUSTAINER COMBUSTION CHAMBER AFTER PARTIAL CLEAN-UP (Neg. No. 87864A)





SUSTAINER LOX DUCT ADAPTER AND PART OF BROKEN LOX PUMP VOLUTE (Neg. No. 87912A)





PORTIONS OF THE SUSTAINER LOW PRESSURE LOX DUCTING (Neg. No. 88024A)



SUSTAINER TURBOFUMP (Neg. No. 88029A)



Ţ

5

j

SUSTAINER TURBOFUMP (Neg. No. 88028A)





HEAD SUPPRESSION VALVE ACTUATOR HOUSING (Neg. No. 88022A)



J

ł

HAD SUPPRESSION VALVE ACTUATOR SHOWN IN FOSITION ON THE THRUST CHAMBER (Neg. No. 88021A)



3

BOOSTER INJECTOR PLATE AND FUEL STAGING DISCONNECT--FORWARD HALF (Neg. No. 87915A)





•••

FIGURE 6.3-16

B1 TURBOFUMP ASSEMBLY FOUND WEDGED INTO TOWER STRUCTURE (Neg. No. 87918A)





DAMAGED BOOSTER TURBINE ASSEMBLY (Neg. No. 87921A)



1. 1.





B2 TURBOPUMP COMPONENTS (Neg. No. 88557A)







A.S.

aller

88821



BO NOT USE FOR CAPITAL EQUIPHER





AIRBORNE PNEUMATICS HARDWARE (Neg. No. 88554A)



NFA DEAN NCI ASSIF C



UNCI ACCIFIED

NFID JF-M θ



· .

FIGURE 6.4-2

	LUUUIL	Luwi_	1 marth	_/_	_RARIA	1	a maili	і. Л	a ai ài M
							S	-613-A14-01	స్టార్షారా
	Search to Same						,1: .Pi	i May 1962 Populsion st	STEM
	L L.I			<u> </u>	1. 1. 1. 1. 1.	1	<u>,                                    </u>	DATA	
	·		1-1-1	+		- <u>i</u>			
	······································	EIGHEP	SUSTAMER LOX MAN	ZMLET		-91-3	금비금 눈님	十四	
	· · · · · · ·								百日
······································		* ; == ; == ; == ; == ;		ت <del>ب</del> جب ا					
	AN	· · · · · · · · · · · · · · · · · · ·				- 12.75		- in the second	
- + +		了。而且是		1		1.0		中世泰	
E.L. OF		I have a laber - to be a line	. 0.03	her ini		<b>THIP</b>	بتجرار المرابع	~~~~~	
11000,		+ ;+	··─; - <del>┦</del> ╁┝┯	f + t					Ψ,
· · · · · · · · · · · · · · · · · · ·		······································	······································	* ********** ** /				+!-++	
· · · · · · · · · · · · · · · · · · ·	45		NICE LOX REGULATION	i ovni e		44.	1045	H Fi	FF
	-1					11			HT
						+++			<u>str</u>
·						11	1.1.1.1	计计划	1.1
	<u> </u>		· · · · · · · · · · · · · · · · · · ·	· -+ •				+	<u>III</u>
		CUTOFF.		1	1.1.1.	1.	1 Section	) (-+)	
						<u></u>			<u>] [] ]</u>
	••••••••••••••••••••••••••••••••••••••			1-1-1-					
		- +++++++++++++++++++++++++++++++++++++		1.1					1.1
	F	711529 SUST	ER GAS GENERATOR		TOR PRESENT				
╺╾┶╼╅╦╺┽╺╷┽╴╺┽	+	4 11					1.1.1.		
	-+ ++		INSTRUMENTATION					and the fact	
	·	-, -, -, +	MALEUNCTION	-11		<u></u>			
	2	1 3		4	╪╾╵╴┝╍┥╼┷╶╻╼╊╕	in f		1	
2000		THEN	SECONDS FROM IGNIT	<b>IONISTAI</b>	T.	1			
	1 -+ -	+	╶─╾┞╼┥╎╌┥	+		41		4-14	FTTT
++++++++-++-++-++-++-+++-+++++++++	· + · · · · · ·								++++
	- +		UEL INCIDENTION MANNET						日日
									Filt-F
			╶┊┝┷╷┍┷┆┿						<u>III</u>
	- I I N			TT.				市生計	
	<u>†</u> - + - ₹		+++++++++++++++++++++++++++++++++++++++	<del></del>					
				1					
· + + + + + + + + + + + + + + + + + + +	1 -, t-, ' '			1 1					<u>etti</u>
		· · · · · · · · · · · · · · · · · · ·		+		4+		141	
		PISS/P. BOULD	K INJECTION MANEPOL	DISES					
	<b>.</b>	······································	الله تعبير چه ماه مستر السر ا	-+ ·	• •				- l-i
میں میں میں انھوں 								-11-1	
	All and an all and	· · · · · · · · · · · · · · · · · · ·		· · · · ·					
		main	m	سم	المنتبة سنتب	استهنها	المتباجهات	م. م	2,
المسترجع والمسترجع			₩						
· · · · · · · · · · · · · · · · · · ·	—, <u> </u>			,			1711	1-1-1-1	
		يتهي بينها والساد العام المحال التحال المحال المحال	•	: -+		11		4	
┲╡┰╧╷╶╧╌┲┷╴┎╧	· · · · · · ·							口正上	
		- <u>[</u>		<u>'</u>		11		<u> + 4 + 1</u>	4]  千
		┝┸╴┾┷┍┾┛		- +			141	11-1-1-	
			<u>++</u> +-		世世界	4	于日日	お日本	時日
	ġ=↓ - → ↓ '			•	中田司		FFF	무타	3-3-
I.	I		1			' <b> </b> -			
									-
		INN	ACOIT-		5				
	-		-1	1	U				



MURUK SI-SI3-AI4-OI 13 MAY 1962 PROPULSION SYSTEM (FM DATA anash_1_anash_1_anash_1 <u>ji ji</u> _xaxíx 2 製成皮質 ŧ 1 1 1 + PIZZE THI CHANNER PRESIDE BACKUP AND ALE DESTRUCT CUTOFT i PLOBAR TRI PLACE SPEED DATA HOISY 1 1 5 12 3 11 E1091P BI LOX INJECTION MANIFOLD PRESSURE , I E +-TT. UNCI ACCIFIED

MF

ñ





1

X





AS

M 22 H S1-613-A14-01 13 HAY 1962 PROPURSION SYSTEM FM DATA €, ARRÍE £ : اربر <u>pazsí</u> 2022 2221 2 문 2 년 PLASH B2 CHANNER PRESSURE Ð ÷Ð 1000 ------P1774 B2 CHAMEER PRESSURE BACKUR ۰. . Ĩ CUTOFF IMMER DESTRUCT ſ 1 - 10,000 PIOSSE Nº PUNP SPEED MALFUNCTION Min in with Address And Min -with 2002 أردرا :0 ż 0) . 1 ź T 5, TIME IN SECONDS FROM IGNITION START: -16 PLOSEP BE LOX INJECTION MANIFOLD PRI SSURE -**PSIG** ï ί. 7 **UNCLASSIFIED** CØN IÐE 

J.







SI-513-A14-01 13 MAY 1942 PROPULSION STSTEM 14 [FMCATA aaan _ aaam 1 S L RARIA র্ব্ববৃহ PIZZAP BZ 96 FLET WUNE BELET PREM œ e -1008 ---+aniou. -1000 PILMP BE OG LOK MALVE PILET PREMIME 5. Ĩ. Ŧ Ô THE IN SECONDS FROM KENTTON STATT ł. 1800 PIA20P HZ GE LOX INJECTION MANIFOLD PRESSURE? i de la -100 PI184P B2 GAS GENERATOR COMMUSTOR PRESSURE -11 • 🕑 , | 1 4 11 ŀ in a lini 1 -•;- <del>}</del>-----------**۰**۰. <u>.</u> ; ; 1-TTT . . . UNCLASSIFIED ØØŅFIÐEN

4



s

FIGURE 6.4-9





, ,

• >

FIGURE 6.4-10





																																									-
																																			,	91-61 13 W 78.7	2-414 UT 19 ULSE	101 22 21 51	STEN	l	
32	$\exists$		Ŧ	T	Ŧ	Ŧ	Ŧ	Ŧ	Ŧ	-	1		_		Ē	24	ie.			e l	-	τų.			ì	1		Ŀ.	-								2	1	-		<u>ب</u> ج:
•		7	7	ŧ	$\ddagger$	Ť	Ŧ	Ŧ	4	7	=	-	t) ,		Þ	-	-	Ì	ŧ	ţ		=	-	-	-																i N
<del>_12</del>	1	1	1	t	İ	i	T	Í	i						Ì	İ		t	İ	t	1		i	<u>_</u>				,** <b>*</b>						-	-	2	1		-	-	-
					0	•																																			`€
1080	$\square$	Ţ	Ţ	Ţ	Ţ	Ţ	Ţ	Ţ	1	1	1				ŗ	Ļ	-	÷		-		i l			ч -					. 1		۰.		۴,	<u>.</u>	·	-	-			
Ĩ			1	1	$\frac{1}{1}$	$\frac{1}{2}$	$\pm$	$\pm$	+		1			s [	<u> </u> 	;	1	1	Í	1	1				_	·	-	ì. T	÷,		5		i i								-
		- 1	+	+	$\frac{1}{1}$	1	1	+	!	+	1			<u> </u>	1	1	ŀ		ł	T	-+	۱ ا.د				. * •			с. Т					5 C 1 2					$\frac{\alpha}{C}$	2	÷.,
•	·																																								
125														<del></del>	-	. <u> </u>			ſ	-01		- <u>-</u>		÷.,				<u>.</u>			-				1	1-2		أنحم	5	<del></del>	<u> </u>
			4	÷	+	Ţ.		1	÷					i Tq	1	+	17	i i	4	-	-	ξ. A	3.   ).		21 A			Ē							- 4		:			2	ļŦ,
				77		;		;		-			) ;		, Ar	1	1		1	1	-	~	7 1 7 1			F -		Г ,													
-125	_			•	1 *	:	*	ł	_	Ì				-	(				1	4 4	Ţ		;		-		Ľ	52	<u>.</u>	13	5		<b>i</b>			<b>F</b> : -	· .				5
	0									-							n	HE	# SEI	CONO	s n	OMIC	MIX	DN ST	art fa																
1900		1	1	1		1	T	Ţ	Ţ					<u> </u>	Ţ_	1	1	i.	í	4													÷.,			<u> </u>	-		1		_
20	-		+	$\frac{1}{1}$	1	Ŧ	+		+	1	;		, .		Ŀ	1	1	1	+		$\frac{1}{2}$		+	+	÷				-		÷		÷1		••• •	<u> </u>			-	÷	-
-	, -				1	ļ		1	1	1		F	2	;		7 7	1	+			7	Ź		$\exists$	-	- - -	_			_			-		_	-	-			_	- 1
٠	<u>ن</u> ے	ن <b>ل</b> يب ا				<u>_</u>		- <b>i</b> -	÷					<u> </u>							<u> </u>		_				<u>م</u>				لم	~						2-4	źż	غيري	
						~	_	-								-			-		~ *			AP-17			-	•			• - • -	•~		•			• •	+	- 1		•
125			-	÷		1	7							-	<u>}</u>	4	i'r	-	2°	2 14		-	cui	.04	ur.	Ļ	1	Ì.					100						Ľ,	2	
•	-		Í	4	_	Ż	-				4	-		-	Ĵ,	<i>f</i> _	Ľ,	ţ	Å	ᅿ		5		Ż		<u> </u>	-		Ч.										2		11
			╶╋	1		1	÷	•					ł	<u>;</u>	Ŧ	<b></b> )	÷	Ŧ			÷				÷.								177		17. 17.	1			5		
-164		en 'n fei	- 44 - 141		<b></b>				1	~ ~ 1		<b>.</b>	<b>4</b>		1 i Po					 +	' €		~		<b>-</b>	*	-		<b>J</b> -14	<u>.</u>	4	<b></b>				. نيڪو آ		in all			
1000	· ·	<u> </u>	~~ <del>~</del>	<del>- Ţ</del>	-1-	-	-	-						1	T	1	Т			-							r-								. 1				1	[]	2
9	<u> </u>	++	+ +	1	1	+	+	1	+				<b> </b>		1	Ţ	1	1										ć	, 97			10						_	-		-
Ĩ		1-1	ţ	-+	1	Ì	İ	1	1			-		Ĺ	Ē	Ţ	+	+	1	1	1		1						- - -				Ĩ.			•••				_	<del></del>
¢	,				_!			<u> </u>		_	2	•		!		-											<u> </u>	<u> </u>					<u>'</u> ا			·			ł	لىسە	شده.

UNCLASSIFIED

NFIDENTIA



### 6.5 FRAGMENTATION SURVEY

Presented in the following is a tabulation, by system, of hardware dispersion. Included are three dispersion maps, indicating the location of recovered hardware relative to the test stand. Items recovered in the immediate area of the test stand have location designations by Quad number and are shown on Figure 6.5-1.

#### 6.5.1 PROPULSION

3

		Item Location
<u>Item No.</u>	Item Description	Sector
0012	Booster Turbopump	Quad I w'
0013	B-2 Fuel Duct & Prevalve -	Qued I
0014	Booster LCX Valve Actuator	Cuad T
238	Gimbal Block #201674-D401543	5 T 1'-
260	Bcoster Boot	3 P
271	Booster SFGG	30 . 20'
298	Part of Pump Housing	3 H
459	Ignitor Fuel Valve 4	1G -/
478	Tachometer #7740256	1 G
529	Low Press Gimbal Ring (	9 M
531	LOX Fump Piece o	2 U
536	Gimbal Block	2 บี
654	Kohler Valve #K 1247-10	4 I
676	V-1 Engine & Gimbal Mount	4 X
739	Tachometer P/N 562-815	4 T
875	Part of Booster #45582841	4 - 4 U
902	Turbine Assy S/N 248R	25 -
929	Pump Casing Part	15
1062	Fuel Pump Housing 1/2	1 S
1231	Heat Exchanger Part	2 D
1232	Turbopump Support	2 H
1250	Gimbal Block	2 11
1263	Gimbal Casting	ĩx
1286	Hypergol Container +	1 B
1287	Gear Drive & Shaft	1 B 4 - 1
1288	Pump Case & Gear With Shaft	1 T ->
1/01	Sustainer LOX Pump Inlet Adapter /	4 L
1403	Sustainer LOX "Y" Duct Flange !	5 L 40
1405	Sustainer Skirt & Exhausterator	7 M
1407	Booster Thrust Chamber	7 M (
1408	Part of Sustainer Engine	7 M .
1409	Gas Generator	10 5
1/20	Engine & Support Parts	7 L 🖅
1/.22	Booster Fuel Duct	lW
1510	Booster Exit Skirt	7 L
1519	Booster Main Fuel Actuator	7 M
5001	ED E BOOSTER PUMP : PUMP : PUMP	1 F .
	INCLASSIFIED	T

This decision contains information affecting the national defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revolution of which in any manner to an unauthorized person is prohibited by law.

6.5-1

* ••



6.5.1 (Continued)

		Itam Location
Item No.	Item Description	Sector
5007	Turbine & GG Assy	Quañ T
5011	Vernier Fuel Kanifold L	ייד פראי
5012	Fuel Prevalve	1 8 7 1
5013	Evergol Container +	16
5014	LOX Discharge Manifold >	1 G
5015	Turnerur Seater	קו
5016	Hi Press fuel Duct 4	1 7 201
5017	Fuel Steen & Shutoff Valve 4	16
5019	Booster Lox Dore Assy F	ገጥ
5021	Lube Oil Pump	
5022	LOX Inlet Elbow Piece	
5023	Bocster Turbopumps	1 T 35'
5028	Vernier Check Valve	ĪV
6000	Sustainer LCX Regulator	7 N 555
6002	Sustainer SRG	7 M
6004	Sustainer Combustion Chamber	7 N
6005	Sustainer GG Blade VIV & Injector Head	7 14
6007	Vernier Freu Ctl Kanifold	<u>7 ዜ</u>
6008	V-1 Thrust Chamber	7 M (= 5)
6009	Vernier IOX Solo Bottle	7 1
6017	Sustainer Engine Gimbal	7 T.
6012	Sustainer Pover Package	7 I.
6014	Ignitor Fuel Value	7 L
6015	Sustainan GG Pody	7 L
6076	Booster Dore & Injector	7 D 7 T
10010	Part of Fum Housing	
10010	SPC Gacing	4 2
12707	Booster Turbanuma Sunnort	4 % Guad II
12762	Burn Geen Beduction	Quad II
12710	Booster CC	Qued II
12715	Prorellart Control Value	June III
12716	Boostor Purn Induour Shaft /	Guad III
12726	Accessory Drive Pad (Hud)	Quad III
12728	Booster Dil Bump K	Queo I Gued I
12737	Booster Engine Fuel S/O Viv F	Quad IV Agr
12728	Boostar Loy Dome Inlet Value 3	Qued IV .
127/1	Sustairar Gumbal Block	WI beu
127//	Turbine Oversneed Assy	Qued IV
127/6	Gimbal Block Assy	Quad IV
127/8	Gimbal Block Assy	Qued IV
12751	Booster Hyd Pump Drive Sheft	Qued IV
12752	Booster Live Pump Drive Shaft	VI henQ
12798	Sustainer Hi Press Duct Fience	Quad IV
12851	P1/20P B-260 Toy In contin Man	Oned III
12853	Booston Tach & Duits	Quad II
128/9	I B I Ral Drichten Franzis	Qual II
20004/	UNUT NECTETED	wudu I c'
	TTTTTTTTTTTT	

92

بنه ن

> This document contains information attecting two national defense of the United States within the meaning of the Esplannye Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.



## 6.5.1 (Continued)

-	Item No.	Item Description	Item Location Sector
	14114	Piece of Engine	7 L
	14126	Fuel Valve	1 V 50'
	14129	Sustainer Turbine Part	2 B
	14137	Booster Reduction	3 A
	20002	LOX Topping Check Vlv. to Hi Press	
		Line-Elbow	7 L
	60004	Booster Tachometer	2 C
6.5.2	HYDRAULIC		
			Item Location
	Item No.	Item Description	Sector
	0010	Part of Booster Actuator	4 K
	323	B-l Hydraulic Panel	3 X
	512	V-1 Pitch Actuator	4 X
	606	Hydraulic Actuated Lock	4 G
	679	V-2 Pitch Actuator	4 W 550
	960	V-2 Yaw Actuator	2 U
	962	Booster Hydraulic Reservoir Part	1 A
	1348	V-1 Yaw Actuator	4 L
	1.424	Booster Hydraulic Reservoir Part	2 G
	5025	Booster Hydraulic Actuator	1 T
	6006	Sustainer Hydraulic Pump	7 L C
	6028	Sustainer Hydraulic Actuator	7 L
	12730	Booster Hydraulic Pump Cylinder	Quad IV
	12742	Booster Hydraulic Pump Cylinder	Quad IV
	12735	B-1 Hydraulic Accumulator	- Quad IV 17'
	12751	Booster Hydraulic Pump Drive Shaft	Quad IV
	12752	Booster Hydraulic Pump Drive Shaft	Quad IV
	12758	Sustainer Hydraulic Accum. Part	Quad IV
	12776	Booster Hydraulic Pump Casting	Quad IV
	12781	B-2 Hydraulic Accum.	Quad III 😪
	60007	Top of Booster Hydraulic Tank	Quad IV

## 6.5.3 <u>PNEUMATIC</u>

ç

Item No.	Item Description	Item Location Sector
0004 158	Lox Airborne Reg. Helium Bottle	2 F 4 A = 65
160 178 ·	Helium Bottle Helium Bottle Fuel Aisberge Berulater	4 A =
317 320 530	Regulator Piece Helium Bottle	ሪ ₩ 4 X ነ ጥ
684 780	Control Valve Changeover Valve	6 W 2 M
	CONFIDENTIAL	NCLASSIFIED

This desument contains information effecting the national defense of the United States within the meaning of the Espienage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any mannar to an unauthorized person is prohibited by law.



# 6.5.3 (Continued)

Item No.	Item Description	Item Location Sector
782	Helium Manifold	2 M 15.
789	Launcher Helium Heat Exchanger	7 N
912	Butterfly Valve	2 D
1002	Fuel Control Solendid Valve	11 .
1220	Helium Check Valve	2 V
1231	Heat Exchanger	2 F
1243	Helium Bottle Part	lW
1331	Helium Bottle Part	3 L
1334	Bellows, Helium Shroud	3 L
1336	Helium Bottle Part	2 L
1385	Helium Bottle Part	2 L
1406	Helium Bottle	7 M
1413	LOX Pneu. Vlv.	7 M
1416	Pneu. Actuator	7 M
1419	Duct With Flange	7 M
1471	Regulator Diaphragm	2 W
1520	Vernier Helium Bottle	7 M 450'
6007	Vernier Pneu Ctl. Man.	7 L
6022	IX 6 Actuator	7 L
10039	Helium Ball Half	40
12703	Helium Bottle Part	Quad I
12704	LN2 Shroud Dump	Quad I
12725	Lox Tank Relief Valve	Quad I
12739	Pneu. Check Valve	Quad IV
12792	Airborne Regulator Block	Quad IV
12816	Helium Bottle Pieces	Quad IV
12825	Helium Bottle Part	Quad III
12833	Airborne Regulator Block	Quad IV
12834	Airborne Regulator Block	Qued IV
12856	Lox Control Valve	Quad II
14112	Helium Bottle	8 L
14126	Fuel Relief Valve	Quad I
141 <u>3</u> 8	LN ₂ Shroud	2 X
14139	Helium Bottle Part	3 X
14140	Helium Bottle Part	2 A
14154	Helium Bottle Part	2 A
14155	Helium Bottle Part	2 A
20003	Relief Valve	7 L

## 6.5.4 ELECTRICAL

t

Ł

Item No.	Item Description	Item Location Sector
203 204	Cannon Plug & Harness #27-11665-805 Electrical Actuator Pin	8 w 6 x
254A	UNCLA IFIED	2 2
	-CONFIDENTIAL	

This decument centeins intermetion effecting the national defense of the United States within the meening of the Espicaced Lows, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by low.



]

•

### 6.5.4 (Continued)

A.A

T

I

Item No.	Item Description	Item Location Sector
279	Part of Umbilical	२ म
282	Umbilical Adapter	3 H
377-382	Stillyell Sections	2 T
385	Stillwell Sections	2 T
388-390	Stillwell Sections	2 T
403	Umbilical POD 2	5 ፹
404	Umbilical POD 2	5 T
451	Inverter Cannister	1 X
458	Part of Umbilical	lG
763	Cannister Assy.	5 R
765	Cannister Frinted Circuit Board	5 R
1020	Part of Umbilical	l H
1110	Umbilical	lW
1473	Stillwell Section	2 W
5030	Umbilical	l W
6003	Auto Pilot Box	7 M
10002	Piece of Cannister	3 S
12702	Auto Pilot Cannister	Quad I
12706	D.C. Power Plug POD 2	QUAD I
12868	Stillwell Sect. Attached to B.O. Vlv.	Quad I
12871	Cannister Assy.	Quad III
14111	27-41470-801 Printed Circuit	7 M
14158	Stillwell Section	2 X

### 6.5.5 STRUCTURE

Item No.	Item Description	Item Location Sector
0016	LOX Topping Flex Line #27-23562-7	Quad I
102	Small Piece of Skin	8 T
128	Small Piece of Skin	9 U
151	Small Piece of Skin	11 V
155	Missile Pin 27-72231-25-BlOl	5 X
161	Inside of Missile Tank	3 B 220
183	Small Piece of Skin	6 U
206	Piece of Heavy Alum with Hinge Pin	7 X
214	PT40 PSI TVA #688 7-76840-7-0	5 X
265	Pieces of Tank & Booster	2 Q
602	Large Piece of Msl. Skin #N27-72003-185	4 G · · · ·
683	Stainless Mtg. Bkt. #27-85321-807-01	3 W
685	Piece of Tank With IR #601766	3 X
729	Chunk of Casting #U27-41414-7	6 R
770	Missile Tank Skin	5 S
902 ·	Portion of Mating Ring	6 A 260'
804	Parts of Pod Access Doors	5 A
808	Skirt Section #27-45404-9	46
851	Part of Jettison Rail	4 T
	CONFIDENTIAL UNCI	ACCIFIED

This document contains information affecting the notional defense of the United States within the meaning of the Espisneed Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revolution of which in any monner to an unauthorized person is prohibited by lew.

•



÷. 1

## 6.5.5 (Continued)

	Item Location
Item Description	Sector
Butterfly Assy. for Valve	5 P
Part of Nose Adapter	2 S
Fill & Drain Valve	1 C 100'
6" Alum. Casting - Part of Msl. Tiedown	3 U
27-72227-1 A/B LO2 Duct W/Large Sect. S	kin 1 B
Booster SPGG Access Door	2 L
Part of Thrust Barrel Ring	3 L
Piece of Thrust Sect. & Flooring	3 L
Msl. Skin with Brace #7-73412-116/Cl	9 A
Missile Skin with Duct	9 X
Large Piece of Missile Structure	3 N 270'
Bulkhead Camera Mount Fitting & Sect.	30
Boiloff Valve	Quad I 25'
LO2 Tank Duct Diffuser	Quad I
Msl. Nose Cone Adapter	Quad III 77
Msl. Tank Skin	Quad III
Piece of Ducting	4 M
Piece of Ducting	4 M
Part of Missile Apex	3 A
	Item Description Butterfly Assy. for Valve Part of Nose Adapter Fill & Drain Valve 6" Alum. Casting - Part of Msl. Tiedown 27-72227-1 A/B LO ₂ Duct W/Large Sect. S Booster SPGG Access Door Part of Thrust Barrel Ring Piece of Thrust Sect. & Flooring Msl. Skin with Brace #7-73412-116/C1 Missile Skin with Duct Large Piece of Missile Structure Bulkhead Camera Mount Fitting & Sect. Boiloff Valve LO ₂ Tank Duct Diffuser Msl. Nose Cone Adapter Msl. Tank Skin Piece of Ducting Piece of Ducting Part of Missile Apex

3

6.5.6 TOWER

Item No.	Item Description	Item Location Sector
165	Part of Vernier Flame Bucket	5 B
255A	Half Level & Electrical "J" Box	20
517	Large Piece of Vernier Flame Bucket	5 W
601	Elevator Door	4 G
701	3 Ft. Sq. Deck Plate	7 X
986	Stand Deck	l D
1338	Topping Control Unit Cover	2 L
1343	Junction Box	3 K
1446	Fart of Vernier Flame Bucket	7 К
1476	V-2 Work Stand	2 X
5003	Vernier Deck Plate	lX
5004	Stand Deck	lX
6010	Vernier Flame Bucket	7 M



This document centains information alfecting the national defense of the United States within the meaning of the Esplonage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.






í

### 6.6 S1 AND AMR TOWER WATER SURVEY

Four separate water supplies are activated at Sycamore stand SI during each tanking or firing test. These consist of LN2 flushing water (activated at X-25 minutes), main flame deflector water (activated at X-1 minute 50 seconds), launcher coolant water, and vernier flame deflector water. The latter two supplies are activated at X-60 seconds. Water is not applied inside the thrust barrel during a normal operation. A thrust section firex water system is available for use during an emergency condition, however, this system has not been activated since Run S1-509-10-01 on 15 November 1961. Two successful firings (S1-610-10-01 on 28 November 1961 and S1-611-12-01 on 23 March 1962), have been accomplished since that date.

LN2 flushing water is menually activated by the last person to leave the stand area prior to condition red. This water is intended to protect the flame deflector and stand structure from the effects of cryogenic temperatures resulting from LN2 and lox drain or cryogenic leaks from supply ducting. Prior to installation of engine blowoff covers as standard equipment (25 September 1961), the main chambers were repeatedly subjected to spray from the LN2 flushing water nozzles. Since blowoff cover installation, however, entrance of water into the chembers was possible only when the covers inadvertently separated from the chambers during a tanking test. This has occurred on occassion, apparently due to water seeping past the covers in sufficient quantity to force the covers from the chambers. Under these circumstances, the possibility of water entering the injector did exist, although the probability of water passing upstream of this point was slight. To prevent further occurrences of this nature, the LN2 flushing water nozzles were repositioned to avoid excessive water spray contacting the chambers in the area of the blowoff covers. This modification was accomplished prior to the final firing of Missile 1F. There was no evidence of premature blowoff cover separation during this test.

AMR Complex 11 water supplies are activated at T-80 minutes (LN2 flushing water) and at T-1 minute 50 seconds (main flame deflector water). The LN2 flushing water nozzles are mounted below the main chambers on the launcher pedestal interface and are directed towards the flame bucket. Water, therefore, is not deliberately impinged on the main chambers, although minor amount of spray could be deflected upwards, particularly when the wind is blowing into the flame deflector mouth. To date, engine blowoff covers have not been installed on any "F" Series missile launch from Complex 11.



This document contains information allocking the national defense of the United States within the meaning of the Espionage Laws, Title 18. U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law. 6.6-1

6.7-1



### 6.7 PERTINENT CORRESPONDENCE

## 6.7.1 <u>YIELD AND EXPLOSIVE FORCES</u>

The following is a report by the Explosive Forces Investigating Team.

Film analysis of the missile 1-F explosion revealed that three explosions had occurred. Table I gives the times of these explosions along with other events, time zero being taken at the first explosion. The first minor explosion occurred at approximately 0.23 seconds after start of sustainer hypergol ignition. Following the first explosion was 4 seconds of burning in the propulsion area. The fuel for this burning more than likely came from the main sustainer fuel line which passes within 8 inches of the sustainer Icx pump. The second explosion, occurring 4 seconds after the first, was an explosion of considerably greater strength than the first but of lesser strength than the third explosion.

Film analysis revealed no structure damage to buildings at sites S-1 and S-4 as a result of the second explosion. The third and last explosion was the major explosion which caused the damage to sites S-1 and S-4. The third explosion occurred at approximately 5 seconds after the first explosion.

The major (third) explosion which occurred in missile 1-F is estimated to be of very low yield. Although visual observation of the destroyed S-1 test stand may lead one to expect a large yelld, the surrounding structures at sites S-1 and S-4 do not show the expected damage that would result from a large yield. Until otherwise proven, it appears that the greatest damage which occurred at site S-1 resulted mostly from heat damage due to the fire that lasted 5 seconds before and a long duration after the major explosion. The damaged structures at sites S-1 and S-4, which were not exposed to fire damage, were damaged by the weak shock wave* initiated by the major explosion.

There was no pressure instrumentation at either site S-1 or S-4, therefore, other means had to be used to estimate the resulting overpressures and ultimately the yield of the major explosion. The methods used to estimate the overpressures at various distances were:

- 1. Visual damage assessment of surrounding structures at sites S-1 and S-4
- 2. Calculated shock velocity from film analysis

By employing the years of experience at hand, the available data on blast effects to structures, it was possible to estimate approxi-

* Film analysis reveal a shock velocity which was a little greater than Mach INCI ACCILIED



This document contains information affecting the harianal astense of the United States winner the meaning of the Espionage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

#### 6.7.1 YIELD AND EXPLOSIVE FORCES (Continued)

mately by visual observation the overpressure required to cause a given amount of damage to a structure. Also, knowing the shock velocity at various distances, one may calculate overpressures at those distances from well-known relationships between pressure, velocity, and distance. Table II gives the estimated overpressures required to cause the damage inflicted upon the various structures at sites S-1 and S-4. Table II also includes calculated minimum pressures required to start deformation in the various structures.

The weight of TNT explosive required to give the estimated overpressures (based on shock velocity) at the distances recorded in Table II is 2150 pounds. Assuming an equivalence of 1 pound of lox -RP-1 mixture to 1 pound of TNT, this would give a yield of 2150 pounds of lox-RP-1 mixture or 0.85 per cent of the 250,000 pounds of propellant aboard missile 1-F. Caution must be used in assuming a one-for-one equivalence between INT and lox-RP-1 because the explosive potential of the lox-RP-1 mixture is a function of the unknown amount of mixing, etc.



This decument conteins information affecting the national defense of the United States within the meaning of the Espionogé Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

6.7-2

- Let dag gegen gehander and an an			ļ	<b>EO</b>		ÍĎ	ÉN	t,i,	4			a 6.7-3						
æ			t V 'l'Imo Seconds	-0.25		0	۳. ۱۹. ۱۹	NC		SIF	TEC	t Sever &						
2			Camere Frame Number	6128		6134	6228					ec S North						
			T T Lme Seconds	-0.227	-0 °164	0	3°89		4.898			: Frames/sec rames/sec						
			Camers Frame Number	5227	5235	5256	5754		5883			IV - 128 V - 24 F						
		сw	III Time Seconds	-0°-5	-0.167	0	0°7		5°042	5.125	5 °333	Camera Camera						
	TABLE I	SEQUENCE OF EVENTS AS RECORDED ON FII	DED ON FII	DED ON FIL	Camera Frame Number	326?	3269	3273	3369		3394	3396	3401	, second				
<b>*</b>			II Time * Seconds	-0,208 -0,185)		0	4°5 (4°0)	5 °125 (4 • 56)	5 °67 (5 °04)	5°75 (5°11)		frames pe t house						
-			SEQUENCE OF EVENTS	SEQUENCE OF EVENTS	SEQUENCE OF EVENTS	SEQUENCE OF EVENTS	SEQUENCE OF EVENTS	SEQUENCE OF EVENTS	Camera Frama Number	1704 (		60 <i>i</i> . I.	1817	1832	1845	1847		using 27 ame bucke ove block ank
									SEQUENCE	SEQUENCE	SEQUENCE	SEQUENCE	. I Time Seconds	-0.225	-0.165	0		
					Camera Frame Mumbar	643	655	688		gu			5	are calculate ec. 1 Soc sec. 1 Noi sec. 2				
				venu tart Sustainer Hyrærgol	nd Sustainer Hypergol	irst Explosion	eccnd Explosion	tart Missile 1-F Settli	hird Explosion	llevator House Hit By Shock Wave	3-4 Utility Bldg, Hit B. Shock Wave	* Times in parenthesis ( Samera I - 200 Frames/s Camera II - 24 Frames/s Camera III - 24 Frames/						
14 BB			;		3	Į <b>F</b>												

This document contains information direction the soliced datage for the university dataset in a solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the solice of the soli

.

ŝ

:

,



Ц	
TABLE	

I

47 13

;

* · ;;

\$

ESTIMATED OVERPRESSURES (Estimated Yield 2150 lb. TNT)

				Estimated (	Dverpressure, psi
	Structure	Distance, ft.	Minimum Pressure, psi*	ғтот Дашадә Азяовятетс	From Estimated Shock Veloc
ڻ 	-4 Utility Building	330 420	0,6 0,6	1。25-1。75 1。25-1,75	2°0 1°0
ა 7	-4 Steel Transfer Doors	400	0.5	1.5-2.0	1,6
ທ່ 7	-4 Guard House	450		0.5-1,0	: ;
ა 7	-4 Guard House	475		0.5-1.0	1,2
ڻ ا	4 Centaur Tank	500		0°1	1 • 1
ა —	-1 Block House Annex	410		1.25-7.75	1.52
<del>7</del>	Door				-
ა 7	-1 S.D.C. Building	100	0°8	4-5	±5°5**
~~~~		140	0°8	3-4	**O°.6
 	عطو والإعداقية المنظم طريبتها فالأرغاسا وماليا والالاليان المراحل والالمراجع والالالية والمراكلة والعارك				
7					

Trave are minimum pressures required to start deformation as calculated by the stress group

* These creminum pressures required to start deformation as calculated by the stress group * These pressures are too high as witnessed by S.D.C. Building. The shock wave muy be in a transient phase at this short distance which would not lend itself to the analysis.

6.7-4

Luni This decument centelns 18, U.S.C., Section 793 inf



6.7-5

Date: 21 May 1962

From: S. R. Simpson, Acting Site Manager

Subject: Damage to Missile 1-F Acoustica Equipment, in Compliance with Requests from Airborne and Facilities Hardware Committees

Captain L. F. Gifford,

United States Air Force

1.0 Examination of landline data and physical appearance of parts, indicate that the Acoustica computer and stillwells were blown from Missile 1-F about six (6) seconds after booster ignition. The following Acoustica equipment, in support of Missile 1-F, has been damaged beyond repair:

> Computer Assembly, CA-109, P/N 101720-1, S/N 0069 Lox Stillwell, SL-192A, P/N 101350-1, S/N 0252 Fuel Stillwell, SF-191, P/N 101340, S/N 0150 Signal Conversion Unit, SC-102, P/N 50007507, S/N 002 Fuel Alternate String Cable, P/N 50021146-5 LOX Alternate String Cable, P/N 50021146-6

- 1.1 Numerous pieces of the Acoustica Computer assembly were found between 200 and 400 feet southwest of the service tower. All sections of the computer assembly were badly burned.
- 1.2 All fourteen (14) sensors of the lox stillwell were located between twenty (20) and fifty (50) feet directly north of the service tower. The sensor backshells were found to be in tact and the secondary stillwells were still connected, but sections of the stillwell, which had fallen close to the tower, were badly burned.
- 1.3 Only three (3) sensor stations of the fuel stillwell have been located. They were found approximately fifty (50) feet north of the service tower and were not badly burned.
- 1.4 The signal conversion unit, containing twelve (12) sensor controls, was found approximately 100 feet southwest of the service tower, in a badly mangled and burned condition. This unit, which weighted about forty (40) pounds, had originally been mounted to the porth side of the gervice tower.



This decument contains information affacting this parlament defause of the United States within the meaning of the Espionage Laws, Title 18, U.S.C., Section 783 and 784, the transmission or revolution of which in any manner to an unauthorized person is prohibited by law.

5

6.7.2

To:

Q ~

- 1.5 Neither the fuel nor lox alternate string cables have been located and are assumed to have been consumed by the fire.
- 2.0 It is requested by Acoustica Associates, Inc. that all available sections of the lox stillwell and the fuel stillwell be forwarded to Acoustica Associates, Inglewood, California for quality and strength evaluation.
- 3.0 The Blockhouse Monitor, MD-200 MD-1, P/N 101394, S/N 006 and the Signal Output Panel, SP-102, P/N 5007508, S/N 002, were located in the blockhouse at the time Missile 1-F exploded, and thereby, escaped any apparent damage.

/S/ S. R. Simpson S. R. Simpson, Acting Site Manager A/A - Sycamore Static Test Site

6.7-6



CONFIDENTIAL

This document contains information affecting the optional defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C., Section 793 and 794, the transmission of revelation of which in any manner to an unauthorized person is prohibited by faw.

Ţ

*:

Ş

J.

T



6.8 MISSILE HISTORY

Presented in the following section is a chronological listing, by planning department completion dates, of BOI's, EO's, ClC's, Planning Cards and Procedures that were accomplished in the time interval between the completion of Test 12 and hot firing Sl-613-14-01. Also included are inspection IR's and NRD's, by initiation date, that were written against missile hardware and installations, and a listing of items that were officially planned by the Sycamore planning group but were not indicated as completed in the planning records.

Of possible interest are items relating to inspection and special testing of the sustainer "T" duct. All work was accomplished by site BOI between 1 and 3 May 1962. The testing included replacing the lox pump inlet Rayco seal, visually inspecting the impeller and wear ring for indications of rubbing (there was no such indication), and conducting gimbal tests to measure restraints imparted to the pump by the lox and fuel low pressure ducting. The above testing was accomplished in support of the Missile llF investigation and was performed under the supervision of Rocketdyne Canoga Park personnel.



CONFIDENTIAL

This decument contains information affecting the national defence of the United States within the meaning of the Espionage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.



Date Planned Date Complete

23 March 1962

								-		
27	93936	BK 1C	HYPERGOLIC SLUG INSTL	20	March	62	23	March	62	
BOI	1		FLAME DEFL PRESSURE METER	22	March	62	23	March	62	
BOI	<u>1</u>		XDCR FAILURE	23	March	62	23	March	62	
EOI	2		REMOVE NAC COVER TRIC CLEAN	22	March	62	23	March	62	
BOI	2		C/O INVERTER VOLTAGE	23	March	62	23	March	62	
BOI	3		FUEL SPLY IGNIFOR FUEL VLV C/O	22	March	62	23	March	62	
BOI	3		C/O PROPELLANT LEVEL XFER ROOM	23	March	62	23	March	62	
BOI	4		SUST ENG HYD LEAK CHECK	22	March	62	23	March	62	
BOI	5		LEAK CHECK F/D VLV INTERNAL LEAKAGE	22	March	62	23	March	62	
BOI	8		C/O EVACUATION CHAMBER	23	March	62	23	March	62	
BOI	9		C/O EVACUATION CHAMBER	23	March	62	23	March	62	

F & CD/IR: #711545 Date 3-23-62 P/N: 555022 - Viv Assy Volute Bleed. Next Assy: 401501 Problem: Flow rate reduced after hot firing. Disposition: Repaired and reinstalled.

F & CD/IR: #711551 Date 3-23-62 P/N: 555022 - Valve Assy. Next Assy: 401501 Prcolem: Volute Vlv. flow rate reduced after hot firing. Disposition: Repaired and reinstalled.

F & CD/IR: #711591 Date 3-23-62 Class Failure: Minor P/N: 27-77014-1 - Radiation Boot Assy. Next Assy: 27-77015 Problem: Sust. boot torn on seam of zipper flap Disposition: Replaced

24 March 1962

27 27	06191 06191	3 A 5 A	REMOVE GROUNI POWER SUPPLY	D STRAP	FM-28V	27 22	Feb. Feb.	62 62	24 24	March March	62 62
CIC	98295		27-06191-5A	VPM 2		22	Feb.	62	24	March	62

26 March 1962

1

27 27 27 27	93701 93857 93951	BK 1B BK 1A BK 2E	LN2 SHROUDS LEAK CHECK W/GN2 LOX TOPPING PRESSURIZATION SYSTEM BSTR & SUST TURBO PUMPS DIAYDACK TH FROM DACKID	26 26 26	March 62 March 62 March 62	 26 March 62 26 March 62 26 March 62 26 March 62 26 March 62
BOI	2		PLAYBACK FM FROM BACKUP	26	March 62	26 March 62



This document contains information affecting the individed defense of the United States within the meaning of the Esplonage Laws, Title 18, U.S.C., Socilon 793 and 794, the transmission or revolution of which in any manner to an unauthorized person is prohibited by law.



26 March 1962 (Continued)

()

ſ

3	SUPPORT C/O XDCR
4	POST CAL P1039P
5	CONDUCT DROP LEVEL TEST
5	FACILITY GAGE CAL
6	C/O HCU PRESSURE SWITCH
9	REPAIR VENT LINE
10	VERIFY WIRING SYST TO INST/N
10	REMOVE FISHER CONTROLLER
11	C/O VERN PNEU REG
12	C/O VERN ENG MOUNTING BOLTS
	3 4 5 6 9 10 10 11 12

F & CD/IR: #711548 Date: 3-26-52 Class Failure: Non-significant P/N: 6141-1 - Fuel Transfer Pump Next Assy: Fuel transfer unit Problem: Leaks Disposition: Design Review

F & CD/IR: #711546 Late: 3-26-62 Class Failure: Major P/N: 27-08554-3 - Accumulator (Bocster B-1) Next Assy: 27-85042-1 Problem: Leaking "O" ring - case pressure Disposition: Replaced

F & CD/IR: #711547 Date: 3-26-62 Class Failure: Major P/N: 27-08554-3F - Accumulator (Bocster B-2) Next Assy: 27-85052-1 Problem: Leaking "O" ring - case pressure Disposition: Replaced

27 March 1962

27	90583	BK 2A	SILO LOX STORAGE TANK	26 March 62	27 March 62
BOI	5		POST CAL FUNCTIONAL RECORDERS	27 March 62	27 March 62
BOI	8		REPLACE FUEL GROUND F/D VLV	26 March 62	27 March 62
BOI	9		REPLACE B1 & B2 HYD ACCUMULATORS	26 March 62	27 March 62
B01	13		INSTALL PCU SUPPLY RELIEF VLV	27 March 62	27 March 62
BOI	14		C/O FUEL LEAKAGE	27 March 62	27 March 62
BOI	15		VOLUTE BLEED VIN FLOW TEST	27 March 62	27 March 62
BOI	16		FLOW TEST IR'D VOLUIE BLEED VLV	27 March 62	27 March 62



This decument contains information affecting the national defense of the United States within the meaning of the Espionege Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

Date Planned	Date Complete
26 March 62	26 March 62
26 March 62	26 March 62
26 March 62	26 March 62
6 March 62	26 March 62
26 March 62	26 March 62
26 March 62	26 March 62
26 March 62	26 March 62
26 March 62	26 March 62
26 March 62	26 March 62
26 March 62	25 March 62



Date Planned Date Complete

22 March 62 28 March 62

21 March 62 23 March 62

24 March 62

28 March 62

26 March 62

28 March 62

28 March 62

28 March 62

2 March 62

15 March 62

21 March 62 22 March 62

2 Feb. 62

26 March 62

22 March 62

27 March 62

20 March 62

28 March 62

28 March 62 28 March 62

28 March 62

28 March 62

28 March 62

28 March 62

28 March 62

28 March 62

28 March 62

28 March 62

28 March 62 28 March 62

28 March 62

28 March 52

28 March 62

28 March 62

28 March 62

28 March 62



28 March 1962

7 27 BOI BOI BOI BOI BOI BOI BOI	18318 81002 3 4 6 6 8 10 17	500 1A 801 B	WIRE TAB J BOX A109 LOX TANK DUCT C/O KAPID LOAD GN2 DOME LEAK PREPARE LOGIC UNTT C/O TIMER SETTING C/O XDORS P1092P & P1232P ADJ & REPROGRAM AMPLIFIERS TOWER LOG NOZZLE SAFETY HAZARD REMOVE REG GN602 C/O PS 324
BOI	25		GROUND SPRAGUE FID UNIT C/O
BOI	44		PCJ PS 51 LOCKOUT C/C
BOI	94		TVA FOR LOX 2 PRESSURE VENT
BOI	96		INST TVA 2ND STORAGE REG
GMA	12565		RCC SYSTEM KIT
GMA	12565	A	MULTI-CHAMBER RCC C/O
CIC	13494	27-81002	2-801 CH3 B E.O.W.
ClC	16270	27-87041	E.O. 212498
CIC	38370	7-18318	3-500 1A D/C B

F & CD/IR: #711436 Date: 3-28-62 Class Failure: Minor P/N: 44-1505 - Valve Next Assy: Pneu Inst. Problem: Excessive Pressure Disposition: Design Review

F & CD/IR: #711550 Date 3-28-62 Class Failure: Minor P/N: GBX205-K2 - Regulator Next Assy: Tank Pressure Line Instl. Froblem: Leaks Disposition: Adjusted

F & CD/IR: #711554 Date: 3-28-62 Class Failure: Non-significant P/N: GBX205-K2 - Regulator Next Assy: Tank Pressure Line Instl. Problem: Leaks Disposition: Design Review



This document centains information affecting the national defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized persen is prohibited by lew.



TAB LIST WIRING

LOX F/D VLV C/O

LOX XFER LINES C/O

VERIFY CONTINUITY

C/O DIODE CONTINUITY

PROVIDE MATERIAL FOR REWORK

SETUP SYST REMOVAL CN602

EXAMINE SUST BYPASS VLV

6.8-5

29 March 1962

18695 500 1A

1 1F

14212 7-00008-501 D GMA 12565

28713 7-18695-500 1A 0/D

1 1A

27090

27092

13

17

18

20

21

7

27

27

BOI

BOI

BOI

BOI

BOI

ClC

ClC

Date Planned	Date Complete
Date Planned 22 March 62 9 March 62 9 March 62 28 March 62 29 March 62 28 March 62 29 March 62 29 March 62 29 March 62 29 March 62 29 March 62 29 March 62 29 March 62 29 March 62 29 March 62	Date Complete 29 March 62 29 March 62
23 Feb. 62 20 March 62	29 March 62 29 March 62
	-

F & CD/IR: #711438 Date: 3-29-52 Class Failure: Non-significant P/N: 7-01720-1 - Transducer Next Assy: 27-11651 Problem: Did not operate on proper curve - recheck ok. Disposition: Adjust.

F & CD/IR: #711557 Date: 3-29-62 Class Failure: Minor P/N: 6145-1 Problem: Supercedes 711548

30 March 1962

BOI 7 REPLACE IR'D XDCR 29 March 62 30 BOI 14 REMOVAL OF LV A34 28 March 62 30 BOI 22 LEAK C/12 OF LOX CONTROL VLVS 29 March 62 30 BOI 22 PROPULSION ELECTRICAL INITIATCR C/0 29 March 62 30 BOI 23 C/O VERN PNEU REG & XDCR 30 March 62 30 BOI 24 VLV N-50 RELAY C/O 30 March 62 30 C1C 14185 27-27092-1 1A E0212362 9 March 62 30	March 62
BOI14REMOVAL OF LV A3428 March 6230BOI22LEAK C/G OF LOX CONTROL VLVS29 March 6230BOI22PROPULSION ELECTRICAL INITIATCR C/O29 March 6230BOI23C/O VERN PNEU REG & XDCR30 March 6230BOI24VLV N-50 RELAY C/O30 March 6230Clc1418527-27092-11AE02123629 March 6230	March 62
BOI22LEAK C/4 OF LOX CONTROL VLVS29 March 6230BOI22PROPULSION ELECTRICAL INITIATION C/O29 March 6230BOI23C/O VERN PNEU REG & XDCR30 March 6230BOI24VLV N-50 RELAY C/O30 March 6230C1C1418527-27092-11AE02123629 March 6230	March 62
BOI 22 PROPULSION ELECTRICAL INITIATION C/O 29 March 62 30 30 BOI 23 C/O VERN PNEU REG & XDCR 30 March 62 30 30 BOI 24 VLV N-50 RELAY C/O 30 March 62 30 30 C1C 14185 27-27092-1 1A E0212362 9 March 62 30	March 62
BOI 23 C/O VERN PNEU REG & XDCR 30 March 62 30 BOI 24 VLV N-50 RELAY C/O 30 March 62 30 C1C 14185 27-27092-1 1A E0212362 9 March 62 30	March 62
BOI24VLV N-50 RELAY C/O30 March 6230C1C1418527-27092-11AE02123629 March 6230	March 62
C1C 14185 27-27092-1 1A E0212362 9 March 62 30	March 62
	March 62

F & CD/IR: #711559 Date: 3-30-62 Class Failure: Non-significant P/N: 555022 - Valve Assy. Next Assy: 401501 Problem: Vlv assy dropped - damaged fitting. Disposition: Repaired and reinstalled.



This document contains information affecting the national defense of the United States within the meaning of the Espionese Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revolution of which in any manner to an unautherized person is prohibited by isw.



Date Planned Date Complete

31 March 1962

(

1

BOI	27	RECONNECT INLET VLV L-60	31 March 62	31 March 62

1 April 1962

F & CD/IR: 588086 Date: 4-1-62 Class Failure: Non-significant P/N: 0-20T0100 - Gauge Next Assy: Pod cool syst. Problem: Threads stripped Disposition: Design Review

2 April 1962

BOI	20	CLEAN VOLUTE BLEED VLV	28 March 62	2 April 62
BOI	26	C/O VERN PNEU REG	30 March 62	2 April 62
BOI	28	REPAIR FLOWMETER LEAK	2 April 62	2 April 62
BOI	29	SUPPORT PROPULSION SYST C/O	2 April 62	2 April 62

F & CD/IR: #711443 Date: 4-2-62 Class Failure: Major P/N: 27-45045-5 - 2 rate gyro Next Assy: 27-62031 Problem: Schrader fitting loosened - No pressure in canister. Disposition: Failure Analysis

F & CD/IR: #711444 Date: L-2-62 Class Failure: Non-significant P/N: 650982-21 - Gas Generator Assy. Next Assy: 650040 Problem: Booster S.P.G.G. - Stud & finger loose Disposition: Held for repair

F & CD/IR: #711445 Date: 4-2-62 Class Failure: Non-significant P/N: 650988-21 - Gas Generator Assy. Next Assy: 650040 Problem: Sust S.P.G.G. - Outward dents in heater blanket corner Disposition: Replaced





This decument contains information affecting the national defense of the United States within the meaning of the Espianose Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unautherized person is prehibited by law.



ł

F & CD/IR: #711446 Date: 4-2-62 Class Failure: Non-significant P/N: 650988-21 - CG Assy. Next Assy: 650040 Problem. Sust SPGG - Outward dents in heater blanket corner Disposition: Replaced

F & CD/IR: #711447 Date: 4-2-62 Class Failure - Non-significant P/N: 650982-21 - GG Assy. Next Assy: 650040 Problem: Booster SPGG - Deep ding in heater blanket corner. Disposition: Replaced

F & CD/IR: #711448 Date: 4-2-62 Class Failure: Minor P/N: 7-320 - Galvanometer Next Assy: Bay Recorder Problem: Erratic Disposition: Design Review

F & CD/IR: #711560 Date: 4-2-62 Class Failure: Non-significant P/N: A67-09217 - 3/4" tube assy Next Assy: Compressor Problem: Dented Lisposition: Condemned

F & CD/IR: 711561 Date: 4-2-62 Class Failure: Minor P/N: L0900Al4X2 - Thermostat Next Assy: Air Cooling Unit Problem: Erratic Disposition: Design Review

F & CD/IR: #711562 Date: 4-2-62 Class Failure: Non-significant P/N: POR-372-1-A - Filter Next Assy: Fuel System Problem: Quarterly Cleaning Due Disposition: Held for Repair

F & CD/IR: #711589 Date: 4-2-62 P/N: 27-29082-801 - Valve Instl (Lox) Next Assy: Propellant Line Instl Problem: Leaks Disposition: Replaced



This decument centains information offecting the national aftence of the United State within the meaning of the Espionage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

CLASSIFI

F & CD/IR: #711590 Date: 4-2-62 P/N: 402238 - Clip Next Assy: 400120 Problem: Broken Disposition: Replaced

3 April 1952

()

7	19662	500 C	XDCR INSTL LINES LN2	3	April	62	3 April 62
27	24009	801 J	HOSE AND MANIFOLD INSTL	28	March	62	3 April 62
27	27090	<u>l 1</u> F	LOX XFER LINES C/O	3	April	62	3 April 62
27	68854	500 1A	RELAY PANEL LOX R & D	3	April	62	3 April 62
27	93951	BK 2E	BSTR & SUST TURBOPUMPS BEA	Ĭ4	April	62	3 April 62
27	94476	1	INSPECT ELECTRICAL CHEC.(LIST	2	April	62	3 April 62
EO	212560		LOX TOPPING C/O	2	April	62	3 April 62
EO	212600		CORRECT SILO R & D BUS	3	April	62	3 April 62
BOI	1		C/O P1506D FOR OPEN WIPER	3	April	62	3 April 62
BOI	7		ACCELEROMETER CALIBRATION	26	March	62	3 April 62
BOT	9		TIEBACK WIRE	29	March	62	3 April 62
BOI	10		Ploo3p pressure c/o	30	March	62	3 April 62
BOI	11		REWORK DIESEL GENERATOR UNIT	29	March	62	3 April 62
BOI	14		REPAIR PUMP LEAK	2	April	62	3 April 62
BOI	15		REMOVE TUBING	2	April	62	3 April 62
BOI	19		ACCOMPLISH PRE-RELEASE EO	29	March	62	3 April 62
BOI	30		DETERMINE LEAKAGE RATE AT V2	2	April	62	3 April 62
BOI	31		RTPLACE IR'D VLV	3	April	62	3 April 62
BOI	33		LEAN CHECK SUST LOX BELLOW	3	April	62	3 April б2
BOI	69		FABRICATE ORIFICE	20	March	62	3 April 62
BOI	90		INSTALL ORIFICE OVERBOARD BLEED	21	March	62	3 April 62
BOI	145		REMOVE F1105R FLOWMETER	23	Jan.	62	3 April 62
CIC	16518		27-29043 EO 212560	30	March	62	3 April 62
ClC	16559		27-68854-500 1A EO 219699	2	April	62	3 April 62
CIC	16701		27-61933 EO 212600	2	April	62	3 April 62
ClC	99418		27-24009-801 F EO S	15	Feb.	62	3 April 62

F & CD/IR: #711449 Date: 4-3-62 Class Failure: Minor P/N: 7-01414-1 - Transducer Next Assy: 27-17016 Problem: Output Signal Intermittant - Stable Input Disposition: Depot Repaired

UNCLASSIFIED



This decument contains information offsching the metional colories of the United States within the meaning of the Espionage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

6.8-8

Date Planned Date Complete

7)E UNCLASSIFIE

F & CD/IR: #711451 Date: 4-3-62 Class Failure: Non-significant. P/N: 27-62731-895 - Umbilical Harness Next Assy: 27-60926 Problem: Insulation skinned for several wires Disposition: Not Indicated

F & CD/IR: #711562 Date: 4-3-62 Class Failure: Non-significant P/N: 27-79081-151 - Door Assy Next Assy: 27-79081 Problem: B-1 nacelle door broken Disposition: Repaired in place

F & CD/IR: #711564 Date: 4-3-62 Class Failure: Minor P/N: 27-85107-493 - Tube Assy Next Assy: 27-85107 Problem: Cracked "B" nut Disposition: Replaced

F & CD/IR: #711565 Date: 4-3-62 P/N: 202766.21 - Thrust chamber assy Next Assy: 100116 Problem: Broken eyelet - Sust eng. chamber exit. Disposition: Repaired in place

4 April 1962

~~	01/00	005 5	
27	24009	805 C	VERNIER SYST HOSE INSTL
27	93,02	BK 2C	RCC SYST C/O
27	93951	BK 2E	BSTR & SUST TURBOPUMP C/O
EO	212531		DIAGRAM CKT PNEU CONTROL BOI 44
EO	21.2532		AUXILUARY CONTROL PANEL BOI 44
EO	212546		PCU PS-51 C/O
EO	212547		PCU PS-51 C/O
EO	212548		PCU PS-51 C/O
EO	212549		PCU PS-51 C/O
EO	212558		PCU FS-51 C/O
EO	212574		PANEL ASSY ENG UNIT 1
EO	212577		SWITCH BACK TO R & D
EO	219698		WIRING REVISION BOI 51
BOI	2		PCU PS-51 C/O
BOI	2		A/P GIMBALING TAPE
BOI	11		INSTL FUSE BOX
BOI	12		REPAIR & CAL P1175T XDCK
			LINCI ASSIEIED



CONFIDENTIAL

This decument contains information affecting the national defense of the United States within the maaning of the Espienage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.



PREVENT SWITCHING TO R&D CONTROL

REMOVE THERMOSTAT

REMOVE GYRO COVER

DELETE P1231X

REPLACE SEAL

REPAIR HARNESS

TIME LOX DELIVERY VALVE

SECURE PROPULSION SYST

C/O BSTR MAIN FUEL VLV

27-60491 ED 212531

27-62669 EO 212532 27-61944 EO 212545

27-16924 EO 212547

27-61915 ED 212549

27-61927 ЕО 212546

27-60491 EO 212548

27-68853 ED 219698

27-61929 во 212574

REPLACE WIRING SUPPORT BRACKET

REPLACE GASKET FOR LEAK CHECK

4 April 1962 (Continued)

12

13

15

30

31

32

32

35

37

39

40

16417

16417

16417

16417

16417

16417

16417

16559

16661

BOI

BOI

BOI

EOI

BOI

BOI

BOI

BOI

BOI

BOI

BOI

C1C

CIC

CIC

C1C

CLC

ClC

ClC

CIC

ClC

F & CD/IR: #711567 Date: 4-4-62 Class Failure: Non-significant P/N: 27-29098-31 - Gasket Next Assy: 27-29082 Problem: Gasket deformed Disposition: Condemned

F & CD/IR: #711588 Date: 4-4-62 Class Failure: Non-significant P/N: 83-67900-065 - Gasket Next Assy: 27-24009 Problem: One time use item Disposition: Condemned

5 April 1962

27	90390	BK 2À	FLUID SAMPLING PROCEDURE	4.	April	62	5 April 62
27	90574	BK lC	HYD SYST FILL AND BLEED	4	April	62	4 April 62
BOI	36		REPLACE IR'D TUBE	4	April	62	5 April 62
BOI	38		REMOVE VERN LOX REG	4	April	62	5 April 62
BOI	41		OVERNIGHT SECURE MISSILE		-		5 April 62
GMA	12972		SUST ENG INSTL CLC 12972	22	March	62	5 April 62
TVA	A1.6747	Е	CANCEL	5.	April	62	5 April 62
		1					





F & CD/IR: #7J1452 Date: 4-5-52 Class Failure: Minor P/N: 395220-4 - Patch Cord Next Assy: Access Recorder Problem: Open Disposition: Condenned

F & CD/IR: #711568 Date: 4-5-62 Class Failure: Non-significant P/N: X021-B - Flex Hose Next Assy: Line Instl. Problem: Ruptured Disposition: Condemned

F & CD/IR: #711569 Date: 4-5-62 Class Frilure: Mir.or P/N: 27-24046-7 - Distribution Manifold Next Assy: Purge Instl. Problem: Cracked Disposition: Condemned

F & CD/IR: #711587 Date: 4-5-62 Class Failure: Non-significant P/N: MS28741-8-1800 - Pneu. Hose Assy. Next Assy: Lox Pressurization Problem: "B"-nut cracked Disposition: Replaced

6 April 1962

27 BOI

BOI

BOI

ClC

90583 BK 2A

7

21

43

16417

	Date Planned	Date Complete
LOX STORAGE TANK	5 April 62	6 April 62
RUMOVE VERN CLAM SHELLS	26 March 62	6 April 62
REMOVE FLEX HOSE		6 April 62
FLEX LINE REPAIR		6 April 62
27-62042 EO 212558	3 April 62	6 April 62

F & CD/IR: #711570 Date: 4-6-62 P/N: 553500 - Regulator Next Assy: 551722 Problem: Unstable reg. - 566 psig to 590 psig. Disposition: Replaced



This decument centains information affecting the national defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unaythor.zed person is prohibited by law.

- ----



Date Planned Date Complete

9 April 1962

()

BOI BOI BOI BOI BOI BOI	2 4 4 5	INSPECTION OF BOOSTER REPAIR INSTL P1478T REPLACE VERN PNEU CONTROL C/O LOX SENSOR STATION CAL GAGES MWO 137649 REPLACE LOX DOME MANIFOLD	6 April 62 9 April 62 6 April 62 9 April 62 15 Feb. 62 6 April 62	9 April 62 9 April 62 9 April 62 9 April 62 9 April 62 9 April 62
BOI	5	REPLACE LOX DOME MANIFOLD	6 April 62	9 April 62
BOI	ć	PRESSURIZE MISSILE LOX TANK	6 April 62	9 April 62
BOI	11	CHECK STORAGE TANK BLANKET PRESSURE	9 April 62 9 April 62	9 April 62 9 April 62

F & CD/IR: #711572 Date: 4-9-62 Class Failure: Non-significant P/N: 27-02528-1 - Filter Next Assy: Line Instl. Problem: Metal Shavings Disposition: Repaired and reinstalled

F & CD/IR: #711571 Date: 4-9-62 Class Failure: Non-significant P/N: 27-08089-18 - Vent Duct and Relief Valve Next Assy: 27-81009 Problem: Misalignment - vent duct and relief vlv. Disposition: Replaced

F & CD/IR: #711573 Date: 4-9-52 Class Failure: Minor P/N: 27-85107-311 - Tube assy. sust. hyd. ground pressure. Next Assy: 27-85107 Problem: Cracked "B" nut Disposition: Replaced

F & CD/IR: #711586 Date: 4-9-62 Class Failure: Non-significant P/N: 27-02528-1 - Filter Next Assy: Fuel line instl. Problem: Threads damaged Disposition: Repair reinstalled

10 April 1962

 $\left(\right)$

27	68746	867 A	SEQUENCE & RESPONDER GROUP	
27	90534	BK lA	SILO LOX TOPPING TANK	נ
EO	212590		RELOCATE F1354T	
BOI	3		OPEN PODS AND NACELLES	
BOI	5		UPDATE LOGIC UNIT	2
			(IMI I WE SHEED	

2	April	62	10	April	62
10	April	62	10	April	62
9	April	62	10	April	62
6	April	62	10	April	62
24	March	62	10	April	62

This decument centains information alfecting the national defense of the United States within the meaning of the Esplanese Lews, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unautherized person is prohibited by law.



C/O SUST. PITCH ACTUATOR LEAKAGE

SET SPARE SUST PITCH ACTUATOR

CORRECT MISALIGNED CONDUIT

SECURE MISSILE OVERNIGHT

TACK WELD SUST DRAIN

REPAIR KELLOG PHONES

7-19634 EC 21.2590

REMOVE BROKEN FILTER PURGE PORT

27-61639-3 CHG 1A EO 213319-1

C/O RCC AMPLIFIER GAIN

ADD TV COVERAGE

PURGE TOPPING LINE

REPLACE IR'D TUEE

COMMUNICATIONS

6.8-13

10 April 1962 (Continued)

6

7

7

8

9

10

13

14

15

16

28

33

13494

13883

BOI

BOI

EOI

BOI

BOI

BOI

BOI

BOI

BOI

BOI

BOI

BOI

CIC

C1C

í

F & CD/IR: #711585 Date: L-10-62 P/N: 651133 - Igniter assy. Next Assy: 650040 Problem: Tube not crimped to body Disposition: Replaced

11 April 1962

7	18691	500 lA	VERIFY ALO3 TAB	22 March	1 62	11 April 62
27	93858	BK la	LEAK CHECK LOX TOPPING LOW PRESSURE	10 April	. 62	21 April 62
BOI	1		C/O MISSILE LIFT TIMER	9 April	. 62	11 April 62
BOI	8		ADJUST A/P AMPLIFIER	11 April	. 62	11 April 62
BOI	8		CAL GAGES	16 March	1 62	11 April 62
EOI	9		C/O LOX STATION 5 SENSOR	ll April	62	11 April 62
BOI	18		REPLACE LOX TOFPING GASKET	10 April	. 62	11 April 62
BOI	19		REMOVE NACELLE COVER	11 April	. 62	11 April 62
BOI	21		CHECK BOILOFF VLV LEAKAGE	ll April	. 62	11 April 62
BOI	22		CHECK ICE ON LOX TANK	11 April	. 62	11 April 62
BOI	32		REPAIR 25 HEADSETS SL	21 March	ı 62	11 April 62
ClC	01795		27-68746-867 CHG A EO BB	2 April	. 62	11 April 62
CIC	01805		27-68761-869 CHG A EO BD	9 April	. 62	11 April 62

F & CD/IR: #711456 Date: 4-11-62 Class Failure: Minor P/N: 55-01142-1 -Transducer-skin temperature Next Assy: TVA A21231 Problem: Transducer open Disposition: Condemned



This decument centains information affecting the national defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by lew.



F & CD/IR: #711575 Date: 4-11-62 Class Failure: Critical failure P/N: 27-02020 (Pl0) - Filter element Next Assy: Lox pre-fab Problem: Contaminated (PFAR S-290) Disposition: Failure Analysis

12 April 1962

27 27 801 801 801 801 801 801 801 801	60425 61656 68746 1 4 5 23 24 25	1 1B 3 1H 869 A	DIAGRAM CIRCUIT LAUNCH CONTROL REQUIREMENTS REWORK LSR PIAYBACK DATA INSPECT FILTER L-15 (LOX) REPROJRAM NACELLE DOOR WORK OFTAIN LOX SAMPLE INVESTIGATE LOX F/D VLV PROVIDE AMBIENT LOX TO TANKING RESET SILO AC VOLTAGE
BOI	25		RESET SILO AC VOLTAGE
BOI	26		SECURE MISSILE OVERNIGHT

F & CD/IR: #711459 Date: 4-12-62 P/N: 101350 - Stillwell assy. Next Assy: 27-72253-809 Problem: Open circuit Disposition: Repaired in place

> F & CD/IR: #711577 Date: 4-12-62 Class Failure: Non-significant P/N: 27-77014-1 -Radiation boot-sust. Next Assy: 27-77015-1 Problem: Damaged Disposition: Replaced

13 April 1962

27	60179	1 1C	DIAGRAM CIRCUIT	22 March 62	13 April 62
27	70468	500 lA	C/O PYROTECHNIC CABLE	12 April 62	13 April 62
27	90452	BK 1B	C/O GG IGNITOR	9 April 62	13 April 62
27	90534	BK la	SILO LOX TOPPING TANK C/O	9 April 62	13 April 62
27	90579	BK 1C	C/O SILO & R&D CONTINUITY	29 March 62	13 April 62
27	90597	BK l	C/O RAPID LOAD PREFABS	27 March 62	13 April 62



This decument centains information affecting the national defense of the United States within the meaning of the Espienope Laws, Title 18, U.S.C., Sectien 793 and 794, the transmission or revelation of which in any manner to an unauthorized persen is prohibited by law.

Date Planned Date Complete

12 April 62

12 April 62

12 April 62

12 April 62

12 April 62

12 April 62

12 April 62

12 April 62

12 April 62

12 April 62

12 Arril 62

10 April 62

10 April 62

9 April 62

6 April 62

10 April 62

12 April 62

12 April 62

11 April 62

11 April 62

11 April 62

11 April 62



L.

6.8-15

ļ

13 April	. 1962	(Continuo	ed)				
				Date Plan	ned I	Date Comp	lete
27 27 27	93612 93857 93857	BK 1C BK 1A BK 1A	ACOUSTICA CLOSED LOOP C/O LOX TOPPING TANK PRESSURIZATION C/O LOX TOPPING TANK PRESSURIZING	26 March 20 March	נ 62 נ 62	13 April 13 April	62 62
27 27 27 BOI BOI BOI BOI BOI BOI BOI	93057 93910 93917 94476 1 2 3 <u>4</u> 10 11 22	BK 1A BK 2B BK 2E BK 1B	LOX TOPPING TANK PRESSORIZING SYSTEM C/O GROUND & A/B PNEU SYST C/O PROPULSION MATED LEAK & FUNCTIONAL INSPECTION CHECK LIST PREPARE CABLE FOR TANK OBSERVER NULL AUTOPILOT DRAIN LOX STORAGE TANK CHECK LOX FILTER L-15 FLUSH LOX STORAGE TANK HYD SYST FILL & BLEED HELLUM SYST XDCR C/O	27 March 26 March 13 March 11 April 13 April 12 April 13 April 13 April 13 April 13 April 1 March	62 1 62 1 62 1 62 1 62 1 62 1 62 1 62 1	L3 April L3 April L3 April L3 April L3 April L3 April L3 April L3 April L3 April L3 April L3 April L3 April	62 62 62 62 62 62 62 62 62 62 62
F & CD/I Class Fa P/N: RV Next Ass Problem: Disposit	R: #71 Milure: 7061503A Sy: Com Crack Mion: C	1576 Da Minor - Hyd. H pressor ed condemned	te: 4-13-62 Relief Valve				
27 27 27 27 27 801 801 801 801	90534 90534 90574 93951 2 7 8	BK 1A BK 1B BK 1C BK 2E	LOX TOPPING SILO LOX TOPPING TANK FILL AND BLEED BSTR & SUST TURBOPUMP ACCOMPLISH HYD TEST OBJECTIVE PURGE LOX TANK REPLACE DIRTY LOX FILTERS	5 April 16 April 26 March 11 April 12 April 13 April 13 April	62 1 62 1 62 1 62 1 62 1 62 1 62 1	L4 April L4 April L4 April L4 April L4 April L4 April L4 April	^{-,2} 62 62 62 62 62 62
<u>16 April</u>	1962						
BOI BOI BOI BOI BOI BOI BOI BOI	₩ 4 5 5 6 6 7 8 13		C/O XDCR C/O LOX LOADING HIGH PRESSURE BOTTLE REMOVE XDCR CHECK PROPELLANT SENSOR REPAIR & C/O P1177T SUPPORT HYD TEST ANALYZE RAYCO SEAL REMOVE BOILOFF VLV C/O LOX STORAGE TANK	16 April E12 April 13 April 16 April 13 April 12 April 12 April 12 April 13 April	62 : 62 : 62 : 62 : 62 : 62 : 62 : 62 :	16 April 16 April 16 April 16 April 16 April 16 April 16 April 16 April 16 April	62 62 62 62 62 62 62 62 62



of the United States within the meaning of the Esplanage Laws, Title which in any monner to an unguthorized person is prohibited by law. This document contains information affecting the national defense 18, U.S.C., Section 793 and 794, the transmission or revolution of



Date Planned Date Complete

16 April 1962 (Continued)

()

BOI	14	REDUCE BOTTLE PRESSURE	13 April 62	16 April 62
BOI	17	ENTER MISSILE LOX TANK	14 April 62	16 April 62
BOT.	18	HYD FILL & BLEED	16 April 62	16 April 62
BOI	20	C/O BOILOFF VALVE	16 April 62	16 April 62

F & CD/IR: #711581 Date: 4-16-52 Class Failure: Non-significant P/N: 27-29098-45 - Gasket Next Assy: Lox Line Inst. Problem: Distorted, Contamineted (Human) Disposition: Condemned

F & CD/IR: #711578 Date: 4-16-62 Class Failure: Minor P/N: 27-23571-839 - Seal Next Assy: 27-21004 Problem: Seal leaking Disposition: Condemned

F & CD/IR: #711579 Date: 4-16-62 Class Failure: Non-significant P/N: 27-85322-9 - Fairing, V-2 Next Assy: 27-85017-7 Problem: End Damaged Disposition: Replaced

F & CD/IR: #711580 Date: 4-16-62 P/N: 204300 - Thrust chamber B-1 Next Assy: 100651 Problem: Ding in exterior of B-1 thrust chamber Disposition: Adjusted

17 April 1962

27	11651	807 1A	PANEL INSTL	22 Feb. 62	17 April 62
27	61182	1 1C	C/O AUXILIARY SDC PANEL	22 March 62	17 April 62
27	94476	BK 1B	ELECTRICAL CHECK LIST	16 April 62	17 April 62
EO	212533		YDCR PANEL INSTL	13 April 62	17 April 62
EO	289011	1	XDCR TRACK SUPPORT	16 March 62	17 April 62
BOI	1		COMPLETE HYL LEAK TEST	12 April 62	17 April 62
BOI	2		C/O POD COOLING SYST	12 April 62	17 April 62
BOI	3		PURGE LOX TANK	12 April 62	17 April 62
BOI	կ		REPAIR NACELLE DOOR	12 April 62	17 April 62



This decument centains information affecting the national defense of the United States within the meaning of the Espienose Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

- ----



Date Planned Date Complete

17 April 62

17 April 62 17 April 62 17 April 62

17 April 62 17 April 62

17 April 62

17 April 62

17 April 62

17 April 62

17 April 62

17 April 62

17 April 62

17 April 62

17 April 62

22 Feb. 62

14 April 62

17 March 62

17 April 62

26 March 62

13 April 62

13 April 62

13 April 62

16 April 62

16 April 62

16 April 62

15 March 62

17 April 1962 (Continued)

BOI	5	CALIBRATE GAGES
BOI	7	CHECK DEW POINT
BOI	42	SUPPORT PROPULSION C/O
BOI	44	TRIC FLUSH
BOI	76	SET UP FM FOR FUEL DETANKING
BOI	20	DAMAGED HOSE
BOI	7	ELIMINATE MOISTURE IN LOX TANK
BOI	9	UPDATE LSR
BOI	9	DRY LOX STORAGE TANK
BOI	12	C/O SUST LOX "Y" DUCT
BOI	12	PURGE LOX TANK
BOI	13	PREVENT ICE BUILDUP ON DUCT
BOI	14	CORRECT VACUUM PUMP LEAK
BOI	21	RESET LOX LOADING CONFIGURATION
BOI	68	CALIBRATE GAGES

F & CD/IR: #484003 Date: 4-17-62 Class Failure: Non-significant P/N: 1908 - Filter assy. Next Assy: Lox System Problem: Contaminated Disposition: Depot repaired

F & CD/IR: #711473 Date: 4-17-62 Class Failure: Minor P/N: 100937 - Mixer Amplifier Next Assy: Dac Bay Problem: No output Disposition: Design Review

F & CD/IR: #711474 Date: 4-17-62 Class Failure: Minor P/N: 100973 - Mixer Amplifier Next Assy: Dac Bay Problem: No output Disposition: Design Review

F & CD/IR: #484004 Data: 4-17-62 Class Failure: Non-significant P/N: 27-79081-173 - Seal Next Assy: 27-79081 Problem: Seal torn Disposition: Condemned



United States within the meaning of the Espionage Laws, Title any manner to an unauthorized person is prohibited by law. This decument contains information affecting the national def 18, U.S.C., Section 793 and 794, the transmission or revelation in any



F & CD/IR: #484005 Date: 4-17-62 Class Failure: Non-significant P/N: 27-79081-173 - Seal Next Assy: 27-79081 Problem: Seal torn Disposition: Condemned

F & CD/IR: #484006 Date: 4-17-62 Class Failure: Non-significant P/N: 27-23571-839 - Seal Next Assy: 27-21004 Problem: Seal distorted Disposition: Condemned

F & CD/IR: #484007 Date: 4-17-62 Class Failure: Non-significant P/N: 27-23571-839 - Seal Next Assy: 27-21004 Problem: Seal distorted Disposition: Condemned

F & CD/IR: #484008 Date: 4-17-62 Class Failure: Non-significant P/N: 27-23571-839 - Seal Next Assy: 27-21004 Problem: Spacer replaced per engineering directive Disposition: Repaired

18 April 1962

Û

				Date Planned	Date Complete
27	27089	1 1D	PREFAB INSTL	15 Feb. 62	18 April 62
BOL	1		TAKE SAMPLES	12 April 62	18 April 62
BOI	3		MODIFY ACOUSTICA LOX	14 April 62	18 April 62
BOI	3		C/O PNEU CONSOLE DP METER	2 April 62	18 April 62
BOI	8		A/P AMPLIFIER SPARES	18 April 62	18 April 62
BOI	9		PREVIOUS MISSILE DAMAGE	12 April 62	18 April 62
BOI	9		C/O AUDIO WARNING AMPLIFIER GAINS	18 April 62	18 April 62
BOI	10		LOX LOADING FLANGES C/O	13 April 62	18 April 62
BOI	11		RETURN LOX LOADING TO B/P	13 April 62	18 April 62
BOI	16		CORRECT ECP 1805	29 March 62	18 April 62
BOI	16		VENT LOX STORAGE VACUUM	13 April 62	18 April 62
BOI	17		REPAIR SURGE CHAMBER LEAK	18 April 62	18 April 62
BOI	21		ECN 28555 TO FOLLOW	13 April 62	18 April 62
BOI	22		REPLACE DAMAGED HOSE		18 April 62



This decument contains information attenting the notional defence of the United States within the meaning of the Espionese Lews, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an ungutharized person is prohibiled by tex.



Date Planned Date Complete

17 April 62

19 April 62

19 April 62

19 April 62

19 April 62

19 April 62

17 April 62

19 April 62

19 April 62

19 April 62

19 April 62

19 April 62

19 April 62

19 April 62

18 April 1962 (Continued)

BOI BOI BOI BOI BOI BOI BOI BOI ECN	22 23 24 25 26 27 77 79 28554 28555	PURGE LOX TANK INST HALLAMORE MOD KIT FILL TOPPING TANK MONITOR STORAGE TANK RAISE CHILLDOWN PRESSURE DEW POINT READING C/O INVESTIGATE PLAY IN SUST ECN 28354 TO FOLLOW EWR 33243 TO FOLLOW LINE INSTL TANK PRESSURE LINE INSTL LOX XFER	17 April 62 30 March 62 18 April 62 18 April 62 18 April 62 18 April 62 18 April 62 18 April 62 18 April 62 17 April 62 17 April 62	18 April 62 18 April 62 18 April 62 18 April 62 18 April 62 18 April 62 18 April 62 18 April 62 18 April 62 18 April 62 18 April 62 18 April 62
ECN	28555	LINE INSTL LOX XFER	17 April 62	18 April 62
CIC	14185	27-27089-1 1D EO 213603	18 April 62	18 April 62

F & CD/IR: #484002 Date: 4-18-62 Class Failure: Non-significant P/N: 202842 - Dome Next Assy: 100651 Problem: Two holes tapped wrong size Disposition: Repaired

F & CD/IR: #711477 Date: 4-18-62 Class Failure: Minor P/N: 27-12782-1 - Temperature Thermometer Next Assy: 27-12753 Problem: Open element Disposition: Depot Repair

19 April 1962

27	90452	BK 1B	GG & SPGG IGNITOR C/O
27	90583	BK 2A	SILO FILL PROCEDURE
BOI	1		CAL PC1 AND N2
BOI	1		DRAIN LOW PRESSURE FUEL DUCT
BOI	4		CHECK FOR H20 IN SUST ENGINE
BOI	5		SECURE PCU
BOT	16		INST DP GAGE

F & CD/JR: #484009 Date: 4-19-62 Class Failure: Non-significant P/N: 27-85314-11 - Tube Assy Next Assy: 27-85314 Problem: Gauges and surface scratches Disposition: Condemned



This decument contains information affecting the national defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in unv manner to an unauthorized person is prehibited by law.

t.»

ф *



20 April 1962

1

BOI

Date Planned Date Complete

19 April 62 20 April 62

F & CD/IR: #484011 Date: 4-20-62 Class Failure: Major P/N: 27-85314-817 - Sust Servo Cylinder Next Assy: 27-85010-813 Problem: Static leak @ 100 psi - 50 drops per 24 hrs. Disposition: Replaced

XDCR IR'D A1361T

F & CD/IR: #484012 Date: 4-20-52 Class Failure: Major P/N: 27-85311-807 - Sust Servo Cylinder Next Assy: 27-85011-803 Problem: Static leak @ 100 psi - 50 drops per 24 hrs. Disposition: Replaced

21 April 1962

BOI	l	LOX PURGE PARTS	13 April 62	21 April 62
BOI	2	INST/N ACTIVATOR CHANGE	20 April 62	21 April 62
BOI	7	IRL REQUIREMENTS		21 April 62
BOI	8	IRL REQUIREMENTS	6 April 62	21 April 62
BOI	12	DRAIN TOPPING TANK	20 April 62	21 April 62
ClC	13494	27-17016-801 CHG 1B ECN-28559	19 April 62	21 April 62
ClC	13494	27-11691-831 CHG 1A ECN 28541	19 April 62	21 April 62

F & CD/IR: #484014 Date: 4-21-62 Class Failure: Non-significant P/N: 1940-6 - Retainer ring Next Assy: 27-79082 Problem: 4 retainers missing Disposition: Replaced

F & CD/IR: #484015 Date: 4-21-62 Class Failure: Minor P/N: 1911-6-4 - Sleeve bolt Next Assy: 27-79082 Problem: 4 bolts worn and distorted Disposition: Replaced



This document contains information affecting the national defense of the United States within the meaning of the Espionoge Lews, Title 18, U.S.C., Section 793 and 794, the transmission or revolution of which in any manner to an unauthorized person is prohibited by law



Date Planned	Date Complete		
20 April 62 23 April 62 20 April 62 23 April 62	23 April 62 23 April 62 23 April 62 23 April 62 23 April 62		

24 April 62

24 April 62

24 April 62

24 April 62

24 April 62

24 April 62

24 April 62

24 April 62

24 April 62

24 April 62

24 April 62

24 April 62

24 April 62

24 April 62

24 April 62

24 April 62 24 April 62

23 April 1962

<1	TTOAT	OJI IA	XDCR INSTL
BOI	8		DETERMINE AMOUNT OF LEAK
27	17016	801 IB	GENERAL ARRANGEMENT INSTL
BOI	1		LEAK CHECK LOX LOADING SYST

F & CD/IR: #711481 Date: 4-23-62 Class Failure: Non-significant P/N: 55-01142-1 - Transducer skin temperature Next Assy: 27-17016 Problem: Broken lead from heat sensing element Disposition: Condemned

F & CD/IR: #484016 Date: 4-23-62 Class Failure: Major P/N: 59083 - Seal Lor Next Assy: 27-27867 Problem: Blowing leak (PFAR S-293) Disposition: Failure Analysis

24 April 1962

27	90534	BK 1B	LOX TOPPING LINE PROCEDURE	21 April 62
27	90574	BK 1C	HYD FILL AND BLEED	20 April 62
27	93951	BK 2E	ESTR & SUST TURBOPUMP	20 April 62
BOI	1		PC-3 ADJUSTMENT	21 April 62
BOI	2		REMOVE BSTR NAC COVER	19 April 62
BOI	3		REMOVE SUST BOOT	19 April 62
BOI	5		DUMP LN?	23 April 62
BOI	6		INSPECT Y DUCT	19 April 62
BOI	7		PURGE ENGINES	23 April 62
BOI	8		REPLACE IR'D HYD LINES	20 April 62
BOI	9		IR SUST PITCH ACTUATOR	20 April 62
BOI	10		IR V2 PITCH ACTUATOR	20 April 62
BOI	13		PC-3 ADJUSTMENT	21 April 62
BOI	14		TAKE LN2 SAMPLES	21 April 62
BOI	15		TAKE DEW POINT READING	23 April 62
BOI	62		MODIFY BL LOX DOME	15 March 62
GMA	8216		INST BSTR ENGINE	23 April 62

F & CD/IR: #484018 Date: 4-25-62 P/N: 242001-855-120 - Pneu Hose Assy Next Assy: Pneu test cart Problem: Ruptured Disposition. Condemned



This discument centains information affecting the actional dofense of the United States within the meaning of the Espienees Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any meaner to an unauthorized persen is prohibited by lew.

T

1 1 1



Date Planned Date Complete

ŝ

25 April 1962

7	08620	AI 918	DRAIN POP COOLING UNIT	21 March 62	25 April 62
BOI	1		PERMIT MISSILE WORK	25 AUTIL 62	25 April 62
BOI	1		RECORD SILO TANK	24 April 62	25 April 62
BOI	1		REPAIR WATER LEAK	25 April 62	25 April 62
BOI	2		DUMP IN2 FROM LOX TANK	24 April 62	25 April 62
BOI	2		MAKE & INST CAMERA BRACKET	24 April 62	25 April 62
BƏI	3		ADJUST CHILLDOWN PRESSURE	24 April 62	25 April 62
BOI	3		REPLACE SEAL AND POLT	24 April 62	25 April 62
BOI	3		CHECK INVERTER INSTL	24 April 62	25 April 62
BOI	4		REPLACE SEAL ASSY	24 April 62	25 April 62
BOI	75		ACCOMPLISH MWO 138200	2 April 62	25 April 62
<u>26 A</u> 1	orii 196	2			

21	90503	BK 54	C/O STORAGE TANK-LOX	25 April 62	20 April 02
27	90583	BK 2A	FILL LOX TANK	26 April 62	26 April 62
BOI	1		CAL N1530P	25 April 62	26 April 62
BOI	l		C/O P1177T	23 April 62	26 April 62
POI	1		FABRICATE CAMERA HOUSING	23 April 62	26 April 62
BUI	1		REMOVE ENG CONTROL PLUG	18 April 62	26 April 62
701	2		TORQUE RAPID LOAD BOLTS	25 April 62	26 April 62
BOI	3		C/O N1527T	26 April 62	26 April 62
BOI	5		C/O CAMERA ELECTRICAL	26 April 62	26 April 62
BOI	6		ACCOMPLISH NOISE CHECK	25 April 62	26 April 62
BOI	12		REPLACE CHECK VALVES	26 April 62	26 April 62
BOI	13		C/O VOLUTE VALVES	26 April 62	26 April 62
BOI	14		C/O BSTR TORQUE	26 April 62	26 April 62
EWR	33240		IDENTIFICATION PLATES	18 April 62	26 April 62
ClC	15016		7-08620-819 IA EO D	20 March 62	25 April 62

F & CD/IR: #484020 Date: 4-26-62 Class Failure: Non-significant >/N: 400964-7 - Body hypergol-sust. Next Assy: 400120 Problem: 3/8" outlet tube fitting torqued 300 in/lbs should be 180 in/lbs. Disposition: Adjusted

F & CD/IR: #711485 Date: 4-26-62 Class Failure: Minor P/N: 55-Oll12-3 - Temperature transducer Next Assy: Transducer installation Problem: Open Disposition: Design Review



This decument centains information affecting the national defense of the United States within the meaning of the Espionage Laws, 11the 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

<u>í</u> ----



F & CD/IR: #711486 Date: 4-26-62 Class Failure: Minor P/N: 4221 - Cable Next Assy: Headset Assy. Problem: Cords open Disposition: Condemned

27 April 1962

U /

i.

l

	1				
27	90534	BK 1B	LOX TOPPING TANK FILL	23 April 62	27 April 62
27	90534	BK 1B	TOPPING TANK C/O	25 April 62	27 April 62
27	93936	BK	HYPERGOL INSTL	26 April 62	27 April 62
BOI	4		RE-INSTL P1773P	27 April 62	27 April 62
EOI	8		INSTRUMENT SLAGING VLVS	29 April 62	27 April 62
BOI	12		INSTALL XDCR	27 April 62	27 April 62
BOI	17		C/O VERN VALVES	27 April 62	27 April 62
BOI	19		REMOVE VERN HYPERGOLS	27 April 62	27 April 62
BOI	20		REMOVE BSTR HYPERCOIS	27 April 62	27 April 62
ECN	28601		INSTL LUBE TEMPERATURE	26 april 62	27 April 62
ECN	28602		INSTL THERMISTOR	26 April 62	27 April 62
ECN	28603		INSTL THERMISTOR	26 April 62	27 April 62
ClC	90297		27-12751 ECN 28601	25 April 62	27 April 62
ClC	90297		27-12748 ECN 28602	25 April 62	27 April 62
CIC	90297		27-12753 ECN 28603	25 April 62	27 April 62

F & CD/IR: #484023 Date: 4-27-62 Class Failure: Major P/N: 27-02405-1 - Valve Assy - check Next Assy: 27-24009 Problem: Leak-body & flange - 300 psig-two 1/4" bubbles per/sec. Disposition: Replaced

F & CD/IR: #484024 Date: 4-27-62 P/N: 553700 - Regulator Next Assy: 554128 Problem: 300 psig input-erratic output - 150 psig low Disposition: Replaced

F & CD/IR: #484025 Date: 4-27-62 P/N: 305341 - Lox relief valve Next Assy: 650040 Problem: Relief vlv. sticks in open pos.-Lox solo bottle.



This decument contains information affecting the national defence of the Unifed States within the meaning of the Espionage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

6.8-23

Date Planned Date Complete



6.8-24.

	Date Planned	Date Complete
C/O P1771P	30 April 62	30 April 62
CHECK WIRE TAB LIST	30 April 62	30 April 62
LEAK CHECK VERM TIVS	27 April 62	30 April 62
REPLACE IS'D VIJ	27 April 62	30 April 62
REWORK DAMPENER ASSY	30 April 62	30 April 62
27-11690 ECN 28535	27 April 62	30 April 62

F & CD/IR: #565359 Date: 4-30-62 Class Failure: Non-significant P/N: 27-02405-1 - Vlv. Check Next Assy: 27-24009 Problem: Contaminates, received improperly packaged (No replacement) Disposition: Depot Repair

1 May 1962

1

30 April 1962

12

13

18

24

29 -3494

BOI

BOI

BOI

BOI

BOI

C1C

BOI	1	C/O SENSOR STATION 6	1	May	62	1	May	62
BOI	2	SIGNAL POWER SUPPLY	1	May	62	l	May	62
BOI	4	A/P SERVO HEATER	27	April	62	1	May	62
BOI	6	MISSILE LIFT TIMER	17	April	62	1	May	62
BOI	6	TEST OBJECTIVE PF102	30	April	62	1	May	62
BOI	7	IR RELIEF VLV	30	April	62	1	May	62
BOI	8	INST XDCR	17	April	62	1	May	62
BOI	8	LEAK CHECK VERN LOX VIV	30	April	62	1	May	62
BOI	9	REPLACE VERN PNEU REG	30	April	62	1	May	62
BOI	12	HPU PRESSURE	ī	May	62	1	May	62
BOI	18	REPLACE VERN SEAL	1	May	62	1	May	62
BOI	24	INST BRACKETS	30	March	62	1	May	62
BOI	25	INST THRUST SECTION INST/N	30	March	62	1	May	62
BOI	71	FABRICATE BRACKETS	30	March	62	1	May	б2
BOI	73	FABRICATE 4 CLAMPS	30	March	62	1	May	62
BOI	78	FABRICATE NUTS	11	April	62	1	May	62
ECN	28535	INST XDCR	30	April	62	l	May	62

F & CD/IR: #484026 - Date: 5-1-62 Class Failure: Non-significant P/N: 27-85107-821 - Tubing Instl. Hyd. Next Assy: 27-85100 Problem: MS 24393 Bulkhead unions (3) instld. wrong Disposition: Adjusted

F & CD/IR: #711498 Date: 5-1-62 Class Failure: Non-significant P/N: 55-01142-1 - Transducer skin temperature Next Assy: 27-17016 Problem: Lead broken during installation Disposition: Condemned



of the United States within the meaning of the Espionage Laws, Title which in any manner to an unauthorized person is prohibited by law. This document contains information affecting the national defense 18, U.S.C., Section 793 and 794, the transmission or revelation of



1 May 1962 (Jontinued)

F & CD/IR: #484030 Date: 5-1-62 Class Failure: Minor P/N: 242001-855-120 - Pneu. Hose Assy. Next Assy: Pneu Test Cart Problem: Ruptured Disposition: Condemned

F & CD/IR: #484027 Date: 5-1-62 Class Failure: non-significant P/N: 27-23571-839 - Seal Next Assy: 27-21004 Problem: One time use item Disposition: Condemned

F & CD/IR: #184028 Date: 5-1-62 Class Failure: Non-significant P/N: 27-23571-843 - Seal Next Assy: 2721004 Problem: One time use item Disposition: Condemned

F & CD/IR: $\#48\pm029$ Date: 5-1-62 Class Failure: Non-significant Γ/N : 27-23571-841 - Seal Next Assy: 27-21004 Problem: One time use item Disposition: Condemned

2 May 1962

í Ì

BOI	19	LEAK CHECK VERN LOX HOSE	
C1C	16240	IVA-A22888 A 7-65412	
ClC	16240	TVA-A23505 A 7-65412	
CIC	16240	TVA-A23578 A 27-61180	
ClC	16899	27-60177-1 1B ECN 28573	

F & CD/IR: #711500 Date: 5-2-62 Class Failure: Minor P/N: HR-16 - Solenoid Switch Next Assy: Launcher Boost Unit Problem: Intermittent Disposition: Condemned

F & CD/IR: #484031 Date: 5-2-62 Class Failure: Non-significant P/N: 83-67900-099 - Gasket Next Assy: 27-24009 Problem: Distorted UNCLASSIFIED Disposition: Condemned

This decument centains information affecting the national defense of the United States within the meaning of the Espionoge Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelution of which in any manner to an unauthorized persen is prohibited by law.

vate Planned	Date Complet
1 May 62	2 May 62
12 April 62	2 May 62
12 April 62	2 May 62
12 April 62	2 May 62
19 April 62	2 May 62



Dat	e Plan	mea	Date Complete					
26	April	62	3	May	62			
27	April	62	3	May	62			
21	April	62	3	May	62			
2	May	62	3	May	62			
2	Hay	62	3	May	62			
3	May	62	3	May	62			
12	April	62	3	May	62			

4 May 62

4 May 62

4 May 62

4 May 62

4 May 62

4 May 62

4 May 62

4 May 62

4 May 62

4 May 62 4 May 62

4 May 62

4 May 62

4 May 62

4 May

l May

23 Feb.

4 May

3 May

3 May

3 May

3 May

3 May

3 May

12 April 62

12 April 62

12 April 62

9 March 62

62

62

62

62

62

62

62

62

62

62

3 May 1962

()

ſ

21	90234	BV TD	PLLU DOX TANK
BOI	5		REMOVE SUSTAINER BOOT
BOI	5		RAPID LOX LOADING
BOI	24		HYD FILL AND BLEED
BOI	26		LOX REG EIBOW
BOI	29		ADJUST LOX DUCT STRUT
CLC	16240		27-60498-300 1B EO 213672

F & CD/IR: #48'>>>> Date: 5-3-62 Class Failure: Minor P/N: 27-06220-1 Part Name: Difl Press Indicator Next Assy: Pheu System Problem: Can't adjust to full scale Disposition: Design Review

4 May 1962

7	19634	1 <u>1</u> A	INST XDCR
27	27090	1 1F	LOX XFER LINES
BOI	1		Y DUCI GIMBAL CHECK
BOI	6		REMOVE XDCR
BOI	13		C/O PC-3
BOI	28		REMOVE FUEL VALVE
BOI	32		GIMBAL TEST PREPARATION
BOI	33		SUST PUMP ADAPTER
BOI	34		SUST LOX PUMP ADAPTER
BOI	37		FUEL PUMP INLET DUCT
BOI	39		HPU HYD FILL AND BLEED
TVA	A22888	А	SITE POWER SYSTEM
TVA	A23505	А	SITE POWER SYSTEM
TVA	A23578	Α	CANCEL

F & CD/IR: #484055 Date: 5-4-52 Class Failure: Minor P/N: 3L2104 - Belt Next Assy: 7-18137-1 Problem: Belt deteriorated Disposition: Condemned

F & CD/IR: #484032 Date: 5-4-62 Class Failure: Non-significant P/N: 27-23571-843 - Seal Next Assy: 27-21004 Problem: Gasket distorted Disposition: Condemned



This decument contains information diffecting the national detence of the United States within the meaning of the Septandes Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an undetholized person is prohibited by law.



Date Planned Date Complete



5 May 1962

()

Í

7	17053	508 03	INSTRUMENTALION	4	May	62	5	May	62	
$\dot{7}$	17053	508 04	INSTRUMENTATION	4	May	62	5	May	62	
7	17053	500 02	INSTRUMENTATION	4	May	62	5	May	62	
27	60498	500 1B	FIREX SYSTEM	13	April	62	5	May	62	
BOI	3	-	SUPPORT GIMEAL TEST	T	May	62	5	May	62	
BOI	ž		REPLACE CEECK VALVES	26	April	62	5	May	62	
BOI	ų		VERIFY INTEGRICY	25	April	62	5	May	62	
BOI	<u>4</u>		REMOVE HARNESS LACING	5	May	62	5	May	62	
BOI	5		REPLACE DEFECTIVE WIRE	5	May	62	5	May	62	
EOI	ó		VEN" 33052 TEST CARL	ĺ	May	62	5	May	62	
BOI	7		PREPARE FOR GIMBAL TEST	1	May	62	5	May	62	
BOI	7		REPAIR DOOR ON LAUNCHER BOOST UNIT	2	May	62	5	May	62	
BOI	ģ		RELOCATE P1504D	4	May	62	5	May	62	
BOI	9		PREPARE XON WIMBAL TEST	2	May	62	5	May	62	
BOI	10		GIMEAL TEST CRECK	3	May	62	5	May	62	
BOI	20		LEAK DECK BONNET GASKET	Ž	May	62	Ś	May	62	
BOI	13		BLEED SIIC IN2 SUPPLY	1	May	62	5	May	62	
BOI	14		SUPPOR ' INSTRUMENTATION	1	May	62	5	May	62	
BOI	<u>1</u> 4		DRAIN FUEL	4	May	62	5	May	62	
301	1.5		SUPPORT A/P	1	May	62	5	May	62	
301	19		SUPPORT 27-21003-502 ADJUSTMENT	- 5	May	62	.5	May	62	
BOI	21		C/O LAUNCHER BOOSTER UNIT	2	May	62	5	Maj	62	
BOI	22		SUPPORE 27-21001-501	5	May	62	5	May	62	
BOI	31		CLEAN SUST DUCT FIANCE	3	May	62	5	May	62	
BOT	36		BLANK FLANGE FJEL DUCT	3	May	62	5	May	62	
BOI	38		SUST TAMPER ASSY	3	May	62	5	May	62	
BOI	76		VERIMY CIRCLE READINGS	15	Jan.	62	5	May	62	
BOI	63		FABRICATE CAMERA BOXES	20	April	62	5	May	62	
BOI	82		FABRICATE BLANK FLANGE	2	May	62	5	May	62	
B01	83		CAMERAS	3	May	62	5	May	62	
BOI	81+		CAMERAS	3	May	62	5	May	62	
BOI	85		FABRICATE BRACKETS	3	May	62	5	May	62.	
BOI	89		FUEL STAGING VLV	3	May	62	5	May	62	
CIC	16876		27-21003-501 CH3. AH ECN 25431	2	May	62	5	May	62	
010	26876		27-21003-502 CEL. AJ ECN 25431	2	May	62	5	May	62	

F & CD/IR: #48h032 Date: 5-5-62 Class Failure: Minor P/N: 27-23545-801 - Dampener Assy Next Assy: 27-21004-51 Problem: Inconsistant static friction of 50 ± 5 lbs Disposition: Replaced



This dowment contains informatic.. affecting the national defense of the United States within the meaning of the Esplensee Laws, Title 18, U.S.C., Section 793 and 784, the transmission or revelation of which in any manner teran unauthorized person is prohibited by taw.

.



5.8-28

Date Planned Date Complete

6 May 62

6 May 62 6 May 62 6 May 62

6 May 62

6 May 62

6 May 62 6 May 62

6 May 62

5 May 1962 (Continued)

F & CD/IR: #484056 Date: 5-5-69 Class Failure: Non-significant P/N: 7-69507 - Electrical Harness Next Assy: Test Roll/Pitch Program Problem: Human error - Put 110 TAC on wire Disposition: Replaced

6 May 1962

()

ł

ł -

				_
27	21003	502 AJ	BI FUEL STADING SEUPOFF VLV	2 May 62
27	21003	501 Af	B2 FUEL STACING SHULOFF VLV	2 May 62
801	l		Y DUCT GIMBAL CHECK	4 May 62
BOI	3		REINFORCE ACCELEROMETER BRACKETS	5 May 62
BOI	6		REPLACE WIRE	5 May 62
BOI	7		REPLACE WIRE AND COMPONENTS	5 May 62
BOI	8		REPAIR EARNESS	5 May 62
BOI	9		REPLACE SPATION 7 SELECTOR SWITCH	6 May 62
BOI	18		SUPPORT 27-21003-501	5 May 62

F & CD/IR: #484034 Date: 5-6-62 Class Failure: Minor P/N: 27-23545-801 - Dampener Assy Next Assy: 27-21004-5 Problem: Erratic static friction of 35 to 60 lbs. Disposition: Not indicated

F & CD/IR: #484035 Date: 5-6-62 Class Failure: Minor P/N: TJL 1400 HG - Thermovalve Nexy Assy: Air cool system Problem: Can't adjust to full scale Disposition: Design Review

7 May 1962

7 27 27 301 BOI	17053 17053 21001 94476 5 10	508 05 508 2 501 Bl BK 1B	INSTRUMENTATION INSTRUMENTATION REMOJE LOX DUCT INSTL PRECOUNT OPERATIONS INSTL OF PO ^S ON LOX DUCT LAUNCHER BOOSTER UNIT SELECTOR	7 3 2 4 7	May May May May May	62 62 62 62 62	7 May 62 7 May 62 7 May 62 7 May 62 7 May 62 7 May 62
BOI BOI BOI BOI BOI BOI	11 12 13 13 14 15		SWITCH C/O LV P-10 BSTR OG LOX CHECK VLV LOX SYSTEM REWORK O/O POD COOLER THERMO VLVS REMOVE 27-27090-87 VENT MISSILE TANK PRESSURES	7 7 22 7 26 5	May May Feb May Feb May	62 62 62 62 62 62 62 62 62	7 May 62 7 May 62 7 May 62 7 May 62 7 May 62 7 May 62 7 May 62 7 May 62

CONFIDENTIALUNCLASSIFIED

This decument contains information affecting the national defense of the United States within the meaning of the Esplonage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unjuthorized person is prohibited by law.



REMOVE AND REPLACE 27-23545-801

REPPESSURIZE MUSSILE TAIKS

TENE SUST LOX DUCT

SCRIFE BERF FUEL VINS

6.8-29

7 May 1962 (Continue)

20

25

3C

36

BOI

50T

EOI

30T

Date Planned	Date Complete
5 May 62	7 May 62
5 May 62	7 May 62
3 May 62	7 May 62

F & CD/13. #165036 Thro. 3-7-02 Cluss Pailute: "nonignificant T/... 27-09107-613 - subs assy Nort result 27-09207 Problem: Firsts the sorat beu Disposition: Repaced

F & CD/IF: #0901 Dite. 5.7-62 thes Falture: Non-significant F/N: 27-20005. - Malve Sty. Non: Assy: 27-2000 Problem: Ditter Ny Six binding in assy. Disposition. Reported - tainsta. Med

F 2 OD/IF. (4840-0 Date: 5-7-60 Class Poiss: Diresignifican. P/D: 2(-22,03-1 - Roderosy. Dett/ssy. 97-20003 Froblem. I mput your/lbs 3 threads Jamaged Disposite. Reprires Inglase

F & CD/IR. (-34057 Ditc: 5-7-69 Class Fillure: Non-significant I't: R131031-1 - 4PD1 Kaley Wont Assy: A/F Pelsy Chariste Assy. Froblem: Duraged by 110 VAC on wire Disposition: Condennel

- -

8 May 1962

()

(

7	19637	500 IA	OBSERVER CUTOFF SYSTEM	9	March	62	9 May 62
27	21001	500 BN	BETLACE BI STABING SHUTOFF VLV.	2	May	62	8 May 62
27	23003	503 Q	STACENC SHIPTOFF VIN ACTUATOR	2	May	62	8 May 62
27	21004	501 A	STAGING SEUTOFF VLV ACTUATOR LUG	2	May	62	8 May 62
BOI	11		C/C XDCR P11771	27	April	62	8 May 62
BCI	21		SULFORT 27-21003-504	5	May	62	8 May 62
BOI	23		SUPFORT 27-21001-502	5	May	62	8 May 62
BOI	27		INST CAMERA SUPPORTS	6	May	62	8 May 62
BCI	30		BUJT BIEED PORT LEAK CHECK	7	May	62	3 May 62
BOI	32		LEAK CHECK MISSILE TANKS	?	May	62	8 May 62
DOI	35		CLETAINER TURESPULLES	3	May	62	8 May 62
			UNCLASSIFIED		-		

This document contains information attecting the halfand defense of the United States within the meaning of the Espionage Laws, Title 18, J.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

6.8-30



SUPPORT B2 STAGING VALVE

MODIFY FUEL STAGING VALVE

PRCVIDE 8 VOLT EXCITATION

27-21003-504 ECN 25431

MODIFY ACCELEROMETER

B1 LOX STAGING VALVE

VENT MISSILE TANK

LOX STAGING VALVE

REPLACE TUBE

REMOVE N1527T

Date	Planr	ned	Date Complete
7	May	62	8 May 62
7	May	62	8 May 62
7	May	62	8 May 62
7	May	62	8 May 62
8	May	62	8 May 62
8	May	62	8 May 62
27	April	62	8 May 62
4	May	62	8 May 62
8	May	62	8 May 62
2	Nay	62	8 May 62

F & CD/IR: #484042 Dates: 5-8-62 Class Failure: Non-significant P/N: 27-22006-1 - Viv. Assy. Next Assy: 27-21004 Problem: Leakage around flange and flange bolts Disposition: Fixed in place

<u>9 May 1962</u>

8 May 1962 (Continued)

35

36

37

38

39

41

77

78

91

16876

BOI

BOI

BOI

BOI

BOI

301

BOI BOI

BOI

OIC

17053	508 05	INSTRUMENTATION	9	May	62	9	May	62
2		REMOVE FORWARD NACELLES	1	Mey	62	9	May	62
5		FABRICATE HOUSING	30	April	62	9	May	62
6		CAL GAGES	6	March	62	9	May	62
7		REMOVE LOY TANK WIRES	3	May	62	9	May	62
8		REMOVE XDCR	4	May	62	9	May	62
8		R ESSURIZE LOX STORAGE TANK	2	May	62	9	May	62
9		LOX STAGING VALVE	8	May	62	9	May	62
10		REVIRE P1395S	4	May	62	9	May	62
12		CAMERA SUPPORT BRACKET	6	May	62	9	May	62
14		ASSIST STAGING VALVE REMOVAL	7	May	62	9	May	62
14		WELD CAMERA BOX	8	May	62	9	May	62
15		WELD MISSILE IN2 INLET	8	May	62	9	May	62
45		REPLACE SPGG	8	May	62	9	May	62
16495		27-27094-1 1A EO 212528	12	April	62	9	May	62
	17053 2 5 6 7 8 8 9 10 12 14 14 15 45 16495	17053 508 06 2 5 6 7 8 8 9 10 12 14 14 15 45 16495	1705350805INSTRUMENTATION2REMOVE FORWARD NACELLES5FABRICATE HOUSING6CAL GAGES7REMOVE LOY TANK WIRES8RFMOVE XDOR8RESSURIZE LOX STORAGE TANK9LOX STAGING VALVE10REWIRE P1395S12CAMERA SUPPORT BRACKET14ASSIST STAGING VALVE REMOVAL15WELD MISSILE LN2 INLET45REFLACE SFGG1649527-27034-11649527-27034-1	1705350805INSTRUMENTATION92REMOVE FORWARD NACELLES15FABRICATE HOUSING306CAL GAGES67REMOVE LON TANK WIRES38REMOVE LON TANK WIRES38REMOVE XDOR48RESSURIZE LOX STOPAGE TANK29LOX STAGING VALVE810REWIRE P1395S412CAMERA SUPPORT BRACKET614ASSIST STAGING VALVE REMOVAL714WELD CAMERA BOX815WELD MISSILE IN2 INLET845REFLACE SPGG81649527-27094-114 EQ 21252812	17053508 05INSTRUMENTATION9 May2REMOVE FORWARD NACELLES1 May5FABRICATE HOUSING30 April6CAL GAGES6 March7REMOVE LOV TANK WIRES3 May8REMOVE LOV TANK WIRES3 May8REMOVE LOV TANK WIRES3 May9LOX STAGING VALVE4 May9LOX STAGING VALVE8 May10REWIRE P1395S4 May12CAMERA SUPPORT BRACKET6 May14MELD CAMERA BOX8 May15WELD MISSILE IN2 INLET8 May45REFLACE SFGG8 May1649527-27034-1 1A E0 21252812 April	17053508 05INSTRUMENTATION9 May622REMOVE FORWARD NACELLES1 May625FABRICATE HOUSING30 April626CAL GAGES6 March627REMOVE LON TANK WIRES3 May628REMOVE LON TANK WIRES3 May628REMOVE XDCR4 May629LOX STAGING VALVE8 May6210REWIRE P1395S4 May6212CAMERA SUPPORT BRACKET6 May6214ASSIST STAGING VALVE REMOVAL7 May6214WELD CAMERA BOX8 May6215WELD MISSILE LN2 INLET8 May621649527-27034-1 1A E0 21252812 April62	17053508 05INSTRUMENTATION9 May6292REMOVE FORWARD NACELLES1 May6295FABRICATE HOUSING30 April6296CAL GAGES6 March6297REMOVE LON TANK WIRES3 May6298REMOVE LON TANK WIRES3 May6298REMOVE LON TANK WIRES3 May6299LON STAGING VALVE4 May6299LON STAGING VALVE8 May62910REWIRE P1395S4 May62912CAMERA SUPPORT BRACKET6 May62914ASSIST STAGING VALVE REMOVAL7 May62914WELD CAMERA BOX8 May62915WELD MISSILE IN2 INLET8 May6291649527-27094-11A EQ 21252812 April629	17053508 05INSTRUMENTATION9 May629 May2REMOVE FORWARD NACELLES1 May629 May5FABRICATE HOUSING30 April 629 May6CAL GAGES6 March 629 May7REMOVE LOY TANK WIRES3 May629 May8REMOVE LOY TANK WIRES3 May629 May8REMOVE LOY TANK WIRES3 May629 May9LOX STAGING VALVE4 May629 May9LOX STAGING VALVE8 May629 May10REWIRE P1395S4 May629 May12CAMERA SUPPORT BRACKET6 May629 May14MELD CAMERA BOX8 May629 May15WELD MISSILE IN2 INLET8 May629 May1649527-27034-11A EO 21252812 April 629 May

F & CD/IR: #484044 Date: 5-9-62 Class Failure: Non-significant P/N: 27-81059-801 - Bottle shroud asay Next Assy: 27-81031 Problem: Cracked Weld. Disposition: Repaired in place

kalan kara sa ma

F & CD/IR: #484045 Date: 5-9-62 Class Failure: Major P/N: 27-02102-23 - Valve assy - Lox F/D Next Assy: 27-21001 Problem: (2) cracks from bottom weld section Disposition: Failure Anaysis



This document contains information anothing in harianal dranse of the United States within the meaning of the Espionage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

Ţ



9 May 1962 (Continued)

F & CD/IR: #484064 Date: 5-9-62 Class Failure: Non-significant P/N: 27-0212-23 - valve assy - Lox F/D Next Assy: 27-21001-819 Problem: Pin F of Jl Receptable Disposition: act.

F & CD/IR: #484027 Date: 5-9-52 Class Failure: Non-significant P/N: 27-80249-7 - Gasket Next Assy: 27-81031 Problem: 4 gaskets out Disposition: Condemned

F & CD/IR: #484062 Date: 5-9-62 Class Failure: Non-significant P/N: KC3-21-30PN - Electric Connector Next Assy: A/P Monitor Problem: Wire broken Disposition: Repaired

10 May 1962

F & CD/IR: #484049 Date: 5-10-o2 Class Failure: Major P/N: 27-02102-23 - Vlv assy - Lox F/D Next Assy: 27-21001 Problem: Internal leakage when closed Disposition: Failure Analysis



This document contains information affecting the national defense of the United States within the meaning of the Espienage Laws, Title 18. U.S.C., Section 793 and 794, the transmission or revejation of which in any segment to as unauthorized person is prohibited by law.



۵

6.8-32



10 May 1962 (Continued)

L

2

X

.

んえんさい

F & CD/IR: #489197 Date: 5-10-62 Class Failure: Non-significant P/N: 27-23552-7 - Rcd End Next Assy: 27-23556 Problem: Rod end bent Disposition: Condemned

11 May 1962 Date Planned Date Complete 90574 BK 1C GROUND & AIRBORNE FILL & BLEED 27 3 May 11 May 62 62 27 93917 BK 2E PROPULCION MATED LEAK TEST 27 April 62 11 May 62 NRD 1 LN2 Flush iczzle, between the systainer and booster 1 engines in Quad I, issues a solid stream of water when the water is turned Cn. 11 May 62 11 May 62

12 May 1962

BOI	4	CHANGE CAMERA LIGHT	12 May	62	12 May 62
BOI	5	REPAIR HYD LINE	12 May	62	12 May 62
BOI	19	REPAIR ELECTRICAL HARNESS	12 May	62	12 May 62
BOI	46	B2 NACELLE	12 May	62	12 May 62
BOI	47	INSPECTOR AID TO ENGINEERING	12 May	62	12 May 62
BOI	48	C/O N1528T	12 May	62	12 May 62
BOI	49	C/O AIRBORNE LOX REGULATOR	12 May	62	12 May 62

IR 565380 - The R/D 10116 sustainer engine (S/N 222722) was damaged due to explosion of missile. No replacement was needed.

15 May 1962

BOI 76 MEASURE FLANGE

5 April 62 15 May 62

F & CD/IR: #484C17 Date: Not given Class Failure: Non-significant P/N: 56873 - Filter Next Assy: 901202 Problem: MWO change Disposition: Condemned



United States within the meaning of the Espionage Laws, Title any manner to an unauthorized person is prohibited by law. This document contains information affecting the r: 18, U.S.C., Section 793 and 794, the transmission or

6.8-33



Presented in the following is a chronological listing of items planned, but have no indicated completion date.

JOB TITLE

DATE PLANNED

TVA	A21283				REPLACE VALVE L-50	3-26-62
BOI	3				UPDATE RESPONDER UNIT	4- 4-62
27	18527	2	A		INSTALL XDCR	4- 6-62
27	27095	1	ID		TANK PRESSURE LINE INSTL	4-26-62
27	27096	ŗ]A		AUXILIARY LINE INSTL	4-26-62
ECN	28605				MISSILE LIFT PANEL A3SY	4-30-62
ECN	28611				INSTALL LOX CONTROLLER	4-30-62
27	49502	5	В		STRUCTURAL AND MECHANICAL	5- 1-62
BOI	1	2			REWORK 28 V RELAY	5- 1-62
27	93952	BK	2E		BOOSTER AND SUSTAINER	5- 3-62
BOI	12				XFER ROOM STEP 2 CUTPUT	5- 4-62
BOI	17				FUEL SHUTOFF VALVE	5- 4-62
BOI	16				SUPPORT 27-21004-801 A	5- 5-62
BOI	17				MOUNT CAMEPA	5- 5-62
BOI	24				RELOCATE CAMERA MOUNTING PLATE	5- 5-62
BOI	86				FABRICATE COVER PLATE	5- 5-62
BOI	25				MOUNT CAMERA	5 662
BOI	23				INSTALL CAMERA BRACKET	5- 6-62
BOI	6				RELOCATE P1479T	5- 7-62
BOI	29				SUSTAINER DUCT FLANGE	5- 7-62
BOI	31				HOLE IN CAMERA BOX	5- 7-62
BOI	85				FABRICATE ACCELEROMETER BRACKET	5 762
BOI	7				INSTALL ACCELEROMETER	5- 8-62
BOI	10				FUEL STAGING VALVE	5- 8-62
BOI	42				LOX STAGING VALVE	5- 8-62
BOI	43				FUEL STAGING VALVES	5- 8-62
BOI	92				FABRICATE PLATES	5- 8-62
BOI	94				FABRICATE BRACKETS AND PLATES	5- 8-62
BOI	95				FABRICATE BRACKETS AND PLATES	5- 8-52
BOI	96				FABRICATE BRACKET AND PLATES	5- 8-62
BOI	93				LOX STAGING VALVE	5- 9-62
27	90534	BK	B		LOX TOPPING TANK	5-11-62
BOI	9				LOX STAGING VALVE	5-11-62
TVA	21269		Α		CABLE UNAVAILABLE	5-11-62
TVA	21270		Α	,	CABLE NCC AVAILABLE	5-11-62
27	93910	BK	2B		GROUND A/B PNEUMATIC SYSTEM 1922	5-12-62
BOI	90					5-17-62
ECN	28609				TRANS INSTALLATION BOI 11, 19, 45	5-24-62
ECN	26560				TRANS INSTALLATION BOI 12	5-24-62



This document centains information affecting the national defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

X

:

*

¢

Theorem has been survey with any of a

ł

I

ASSIF

6.9 INVESTIGATION BOARD AND COMMITTEE ASSIGNMENTS

ł

1. S. W. C.

(and

At the request of Col. H. E. Moose, President of the Accident Investigation Board, formal working committees were formed in the following areas. Airborne Hardware, Documentation, Explosive Forces and Yield, TGSE and Facilities Hardware, and Data Investigation. Compiled in this section are a listing of the delegated committee members and their functions.



This document contains information allociting the instituted detense of the United States within the meaning of the Explorage Laws, Title 18, U.S.C., Section 793 and 793, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law. 6.9-1



ACCIDENT INVESTIGATION BOARD

X

C

8

Col H. E. Mcose, RWRU, President	Mr. F. T. Gardner, GD/A, Member
Lt Ccl C. W. Johnson, RWRUE, Member	Mr. S. Zeenkov, GD/A, Member
Maj F. A. Silvasy, RURUE, Investigation Officer	Mr. D. M. McGray, STL, Member
2 Lt L. R. White, NWRU-1, Recorder	Nr. A. Chase, Rocketdyne, Member
Maj C. W. Flanders, AFIMS; Member (NV)	Mr. S. Simpson, Accustica, Member
Mr. E. R. Roth, AFLMS, Member .NV)	
AIRBORNE HARDWARE COMMITTEE	
R. G. Killian - GD/A Chairman	C. O. Bennett - GD/A Design
Capt. L. F. Gifford - USAF - Go-Chairman	Designee Rechanical D. I. Goetting - GD/A Design
C. H. Oliver - GD/A Propulsion	R. F. Sprague - GD/A Designee Flight Control
R. E. Masters - GD/A Pneumatics	K. King - GD/A Prop. Design
P. R. Battenberg - GD/A Hydraulics Airframe	D. Hcward - GD/A Pneumatic Design
J. R. Rose - GD/A Electrical	R. Stocklosa - GD/A Hydraulic
D. W. Burright - GD/A Operations Support	A. Morse - GD/A Flt Control Design
L. P. Birse ~ GD/A Inspection	Dav: Bradley - GD/A
T. J. Collins - SFL	Hoyt Graham - STL
J. Ruppert - NAA/Rocketdyne	Joe Green - STL
G. Oethen - AFQC	Sidney Berman - AF1FS
S. Simpson - Acoustica Associates	Dcu Eddy - Rocketdyne
DOCUMENTATION COMMITTEE	
W. W. Johnston - GD/A - Chairman	
Capt. L. F. Gifford - USAF - Co-Grairman	
W. J. Sweitzer - GD/A	



This document contains information affecting the national defense of the United States within the meaning of the Esp.anage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

6.9-2



()

X

INVESTIGATION TEAM - EXPLOSIVE FORCES AND YIELD	
A. N. Hatch - GD/A 595-1 Aerothermo Dynamics	E. D. Frost - GD/A
L. V. Feigenbutz - GD/A 595-1 Aerothermo Dynamics	Don Endsley - AFIGS
W. M. Smalley - Aero Space Corp.	Gus S. Economy - DIG/Safety AFIMS
W. Pfanner - GD/A Structional Analysis	
TGSE AND FACILITIES HARDWARE COMMITTEE	
F. J. Stewart - GD/A Chairman	K. Cannestra - GD/A Electrical-
J. M. MacDonald - GD/A Co-Chairman	G. Oetken - AFQC
R. Richards - GD/A Material	J. H. Ruppert - NAA/Rocketdyne
C. L. Gould - GD/A Electrical - TGSE	S. Simpson - Acoustica Associates
D. W. McCallum - GD/A Mechanical - TGSE	T. J. Collins - STL
M. X. Dougherty - GD/A Design Electrical	J. W. Taylor/L. Birse - GD/A
F. A. Derango - GD/A Design Mechanical	S. Chavez - GD/A Plant Engineering
E. A. Zdvorak - GD/A Mechanical - Facilities	D. Morgan - GD/A Safety
	C. Frasher - GD/A S-4 Centaur
DATA COMMITTEE	
H. L. Obertreis - GD/A Test Evaluation - Chairman	C. L. Hyde - GD/A (Syc.)
A. Chase - NAA/Rocketdyne - Co-Chairman	E. J. Dubatówski - GD/A (Syc.)
G. G. Christ - GD/A Instrumentation	Airframe
I. F. Littman - STL	C. D. Westfall - GD/A (Syc.)
D. M. McCray -STL	V. C. Knarreborg - GD/A (Syc.)
D. W. Healy - GD/A Test Evaluation	Support - Instrumentation
S. Simpson - Acoustica Associates	Lt. L. B. Haws - AFPRO
G. Oetken - AFQC	K. King - GD/A Prop. Design
W. J. Sweitzer - GD/A (Syc.) Propulsion	D. Howard - GD/A Pneumatics Design
R. Stocklosa - GD/A Hydraulic Design	A. Morse - GD/A Flt Control Design

UNCLASSIFIED

This document contains information <u>attenting the national</u> defense of the United States within the meaning of the Espionage Laws, Title 19, U.S.C., Section 793 and 794, the transmission or revelation of which in any monner-ta-ma-enguinorized person is prohibited by law.

6.9-3

6.10-1



6.1.0 WITNESS INTERROGATION

1.

躗

This section is a documentation of the pertinent comments presented, by the witnesses of the Missile IF mishap, during a post run interrogation.

I was positioned directly behind the Launch Officer's Console with a view of the lower portion of the missile available to me through the blockhouse windows. LOC indicators appeared normal throughout "commit start" countdown until after the "T-O" callout. My attention shifted to the windows before ignition. Immediately after ignition, a billowing fire appeared on the left side of the booster section (as viewed from the blockhouse), cutoff and water were called for and the explosion(s) occurred. The subsequent shock-wave was prominent in the blockhouse.

Signed - Seymour Zeenkov Asst. Proj. Engineer 5/13/62

1. In Electronics Room

- 2. Acoustica Console
- 3. Everything normal, and on control

4. Explosion

Signed - W. M. Skov, Clock No. 83993 5/13/62

My Station - Esterline Angus Recorders in D0-34, 1 to 4, D0-35, 1 to 4. Eight (8) of the above recorders operated well throughout the run. From Commit Start to the time of the explosions, I was watching the recorders one (1) through four (4) in D0-34. I <u>did not</u> observe any cutoffs during this time. The records on EA's <u>may not</u> bear this out. The people in the back bay Browns were calm and stayed on their recorders until they were secured.

Signed - G. A. Theobald, Clock No. 89727 5/13/62

I was operating the communication console on this date, as marked above. Standing near the console, as I have in the past runs, everything seemed normal up to the time of the explosion, then I felt the concussion and it seemed to shake me up a little. Also, I heard the Transfer Room door shake, as I am located near the tunnel that runs to the Transfer Room. Then I heard the Kellogg selectors clicking quite fast. I reached over and switched the power off on our Kellogg power supply, switched off all the communications lines running to the stand and area. After removing the shorts from the outside area, I managed to get communications established between Security & Blockhouse area. I removed PA from SI area and switched in S4 after checking it out for operation. After communications were established I ran the remaining tape from the boiloff valve test tape and put on a new



6,10-2



roll after completing the rest of the Reel #1 Side 2. I also installed a 28 volt power supply to operate the console, after main 28 volt power went off, with the permission of my supervisor.

Signed - T. A. Sickich, Clock Nc. 83340 5/13/62

Autopilot Control Console & Hydraulic Console Operator - All observations on above consoles were normal and per countdown. All call-out commands were normal and on time. Programmer run time meter started running at ignition start and I started call-out time. As I recall, immediately after the count of two seconds, there were several call-outs either in the blockhouse or on the command net. At this time, I ceased the time call out and heard the explosion. To the best of my knowledge hydraulics returned to R&D before loss of power. After explosion, Missile AC & DC was turned off on the Missile Power Control Panel. At this time I observed the indicator lights on the Autopilot Control Panel were dim and requested to secure panel power. It was granted and panel power was secured.

Signed - James A. Casto, Clock No. 22634 5/13/62

I was stationed at the Auxiliary Control Panel and everything was normal. Ignition was approximately two seconds past zero time. Approximately one second after ignition start we had the cutoff lights appear upon the Auxiliary Control Panel. Approximately a second later there was an explosion.

Signed - Herbert P. Lipp, Clock No. 57588 5/13/62

I was Firex and Flame Deflector operator at the time of explosion. Everything was normal, until after the explosion, on both panels. I was watching the water pressure meters and could see nothing. I heard the test conductor call "all water on" just prior to the explosion and started all water that I could before and after the explosion.

Signed - George L. Richardson, Clock No. 76858 5/13/62

My assignment was Brown recorders. Location: back bay. D0-31, D0-32, D0-33 Measurement numbers: P1212D, N1515P, P1213D, P1002P, P1001P, P1098D, P1004P, P1003P, F1365T.

All measurements looked normal. As countdown monitor said "O", the lox pump inlet pressure began to rise and oscillate and appeared to be sluggish. At ignition start they dipped low in pressure. I heard loud screaming on command net and then an explosion. This was from 3 to 5 seconds after ignition start. After explosion all measurements went out. The blockhouse



X



6.10-3

shook and the air conditioning vent fell to the floor.

Signed - J. W. Barham, Clock No. 13798 5/13/62

At commit start I was watching the 6 Brown recorders in DO-23 & DO-25. All looked normal. At engine start I was watching the 2 redline measurements P1473P, Bl Lo Pr Lube Oil and P1279P, B2 Lo Pr Lube Oil. Both measurements started up scale. The light from the fire attracted my attention to look out the glass port in the blockhouse just as I felt the shock wave. I did not press the cutoff button.

Signed - A. R. MacGregor, Clock No. 59299 5/13/62

Fuel Tanking Panel Purge Panel

l

T

From commit start to ignition start everything was normal on both panels. At ignition start I was watching the TV monitor above the panel. I saw flames coming from the area around the engines and up the side of the booster section. I heard the call-outs for ignition start + 1 second, ± 2 seconds. I had to turn the purge panel power ON at ignition start + 3 seconds. The explosion occurred just prior to this time. All panel lights went dim and the TV monitor went to just a raster.

Signed - Edward Miller, Clock No. 64649 5/13/62

RCC Operator - Everything was normal on RCC between commit start and ignition. Seconds after ignition start, all binary counters commenced counting. Cutoff was observed on Channel BLA only. In my mind, this appeared after the explosion.

Signed - Clarence S. Clayborne, Clock No. 24070 5/13/62

I was observing two redlines P1709T (S. GG Combustor) and P1465P (S. Lo Pr Lube Oil Manifold) prior to start commit. During 10 sec. of start commit and after 10 seconds of start commit, the recorder for P1709T was reading normal at ignition start. It went up fast and hit the positive end of the recorder and came out of red normally until cutoff and then went negative. It operated normal in its two second limits. I did not observe P1465P due to it having 7 seconds to get out of red. Other measurements that I was observing, P1682P, U1080P, U1081P and P1341P all appeared normal prior to start commit. Then I focused my attention on the two redlines mentioned above.

Signed - A. V. Tangorra, Clock No. 89076 5/13/62



6.10-4



I was assigned to be the roving instrumentation technician in the front bay Brown area. At commit start I was looking at recorders in the general area of bay DO-18, DO-19 and DO-20. All measurements appeared normal until the explosion.

Signed - E. J. Smith, Clock No. 84533 5/13/62

During the hot run firing S-1-613-14-01, I was operating the Instrumentation Console. All instrumentation was on fast. At T-158S, run cameras switch T-2 was activated, soon afterwards at T-8S ignition, stage cameras T-1 switch was activated. Also, at T-5S, T/S camera T-4 switch was activated. All instrumentation prior to ignition start was GO over the command net. To me, ignition start sounded good and as I raised my eyes from the console a couple of seconds later, all I saw was a yellow flash at the blockhouse windows.

Signed - Ronald J. Maguira, Clock No. 59567 5/13/62

Assignment: Brown Recorders Location: D046, 47, 48, Back Bay Brown Area Measurement: F1368T, P1951T, F1356, P1096D, N1790T, F1353T, F1285P, F1286P, F1355P Up to commit start and after, all nine of these recorders were normal until the explosion, after which most went to zero. I observed nothing abnormal.

Signed - Fred Westfall, Clock No. 95902 5/13/62

From just before the countdown everything seemed normal. We went through commit start and the final countdown with nc holds. We got to zero and went past zero, 1 or 2 seconds and had ignition start. Everything seemed to be running OK. There was a cutoff and then there was an explosion.

My assignment was watching the back up FM tape in D076 and D077 bays also to watch the Sanborn recorder in bay D078. There were a number of STL people observing the measurements on the Sanborn recorder in D078. I was looking at Pl095D and Pl097D. I noticed slight oscillation on Pl095D but it was not close to being out of band and I believe Pl097D also had some oscillation. Also, during the three seconds we fired, neither was close to being out of band. Of course at the explosion, then both pegged out. The FM back up tapes operated OF all the time until we had power failure throughout the blockhouse.

When I was down in the Transfer Room, I noticed that the back of the RCC amplifier cabinet was closed. Now this was not normally left closed, so I estimate it was an hour and a half before this Run I created the back of the RCC cabinet. I always remember it being open before to give the ecuipment



71

ventilation and to let it run cooler. When I noticed it closed I opened the back door and I put my hand on one of the power chassis and it was hot. I could not leave my hand on it so I left the door open.

6.10-5

Signed - Bayard J. Rehkopf, Clock No. 76110 5/13/62

X

P

- 1. From curmit start to zero time, the 1st and 2nd stage hydraulics measurements H1033P and H11:0P were recording normal pressure of 2250 psig; well within design operating limits.
- 2. At zero time, I recall hearing the Autopilot Tape Reader function and perhaps 1 or 2 seconds later, simultaneous with the test conductor's command of "water on". A bright (whitish) light was perceived out of the corner of my eye.
- 3. At this moment HILLOF becaue erratic spiking upscale and H1033P spiking downscale. I actuated my cutoff button.
- 4. The blast wave hit the clockhouse and shortly thereafter power was shut down.

Signed - L. B. Smith, Clock No. 84772 5/13/62

Subject: Observations of Brown Recorders during Run S1-613-14-01 Ref: Méasurements P1232P, P1330D, P1529D, P1474P, P1027P & P1030P

During Run S1-613-14-01 I was observing the Brown recorders and the following is a statement of my observations:

All measurements were functioning normally from commit start until ignition start. From commit start until T-0, I was paying particular attention to P1474P (V control press regulator) to make sure it stayed within the limits of 555 to 625 psig. At T-0, I shifted my attention to my two redline cutoffs, P1232P and P1830D. At ignition start P1830D came off 0 deg and went up to approximately 75 deg, it then started on and then immediately after, the explosion took place.

Signed - E. A. Leonard, Clock No. 56761 5/13/62

1. I was assigned the following recorders for the subject run. F1011P Lox press discharge F1009P Fuel Press Disch N1530P Lox Topping Tank Level F1182P Lox Ullage Pressurs CP1017P S4 lox Boost Pump In CF1019P S4 LH2 Boost Pump In

2. All measurements were normal until the explosion. Then, all lost indication except JP1017P and CP1019P, which still indicated normal tank pressure until bay power was secured.





6.10-6

Signed - R. C. Palmer, Clock No. 70889 5/13/62

Measurements involveds

<u>.</u>

P1677T Edisor Loop ~ Normal (Redline) P1325T Eng. Comp. Anb. - Normal (Redline) P1712T B2 Nac. Amb. - Normal (Redline) N1508T Low Top Tk. Ctl. it - Pegged Neg. (-325 deg) All temps pegged positive at or about the same time of blast.

Signed - William Melender, Clock Nr. 53745 5/13/62

From start commit to ignition start everything seemed normal in FM area. I do not have any though measurement to look at except for all volume unit meters for signal level on all four FM taps recorders and like I stated before everything looked normal. After two or three seconds of ignition start the that become and at the same time all levels at volume unit meter dropped down, losing all signals.

Signed - N. D. LaGicia, Cluck No. 55230 5/13/62

Immediately before ignition start, I checked all front bay Brown recorders and TV systems and was satisfied that all were running properly. I noticed on the TV monitor, looking at the frict of the stand, flame which curled up and around the B-2 thrust thamber, which continued up to the explosion. Following the explosion I stated all TV systems to see if any could be used for surveillance of the space. All cameras were dead so I cut all power to the cameras and TV system.

Signed - John Jeffers, Jr., Clock No. 19513 5/13/62

From blockhouse observer's position, the test stand and missile appeared normal until the command of ignition start. There were some vapors appearing periodically from under the dissile in Quad 1 and 2 areas, which were also being observed on the TV monitor. At the command of ignition start, flames seemed to burst out all around the V2 engine, and B2 engine macelle. The B2 engine macalle then seemed to erupt in flames and the entire test stand was then lost of sight in flame and smoke. The V2 engine did not appear to have gained a started condition.

Signed - T. Jones, Blockhouse Observer 5/13/62



6.10-7



The missile and stand appeared normal in all respects through tanking and during the one hour hold before firing. At the time of engine start B-1 and B-2 apparently went into igniticn start normally then billowed into flames which seemed to roll, in both directions from B-2 under the entire thrust section and up around the sides of B-2 nacelle and then B-1 nacelle. This action was extremely fast and appeared as though it was an explosive action. At this time I yelled "Explosion" in the phones, dropped down into the tank, attempting to reach and push the cutoff button at the same time. I did not push cutoff as the missile exploded before I could push the button. My view of the sustainer was hampered by the V-2 stand and fuel swivel. I did not discern any V-2 ignition.

Signed - R. E. Smay, North Tank Observer, Clock No. 84224 5/13/62

At time count zero, there appeared to be a delay of ignition for several seconds. The first appearance of first appeared to be a lazy orange colored flame rolling from beneath the first value at B-2 engine. The first appeared to grow in intensity for 2 - 3 seconds completely covering Quad 1 & 2 - boiling as high as V-2 engine. Then came explosion, and immediately all vision was obscured in the smoke and flame. Observance of the missile up until the first appearance of flame, indicated all conditions were normal as seev from the periscope.

Signed - R. L. Woods, Clocx No. 98600 5/13/62

(1

4.8

I was in the front part of the tank looking out. Everything was normal until ignition start. After ignition, black smoke rolled out, like the engine started. Within just a second a flash of fire, coming on both sides of the smoke, like both boosters had caught on fire, with an explosion following immediately. This fire on the boosters looked like it was on the south side of the stand in Quad 3 and 4. I did not see the verniers start.

Signed - Jce Estebo, North Tank Observer, Clock No. 33529 5/13/62

During the one hour hold, ail indications on FlOOIP and FlOO3P were normal at step two pressures. The last 25 minutes of the one hour hold I was relieved for a lunch period. I returned to my blockhouse station about 5 minutes before the end of the one hour hold. The time count progressed and missile pressures were advanced to Step III pressures, normal. The time continued and missile pressures went to internal and still were normal. I heard ignition start and just a fraction of a second after, I heard cutoff and fire. Then I heard Roy Killian call for all water on. After that sentence, missile lox tark and fuel tank pressures started to drop at about the same time. When they got into the red zone, I hit the cutoff button. Until that time all indications were normal. After the one hour hold, the south tank reported frost at the missile around the Quad III and Quad IV area of



6.20-8



the outer thrust section of the missile, south side. It was reported that the frost was approximately 18" up the side of the thrust section. The test conductor said that we had this condition before. It was felt that this condition was OK, and the countdown was started again.

Signed - Frank T. Adonne. Jr., Recorder F.001P and F1003P, Clock No. 10420 5-13-52

It looked hims a normal firing of the booster engine then fire exploded all around the test stand. The version engine did not fire. No one in the sorth tank could not the futton. The fire and explosion went about 300 feet in the air and about 300 feet across.

Signed - 9. L. R. S. Stort Sleck No. 77836 5-43-62

During the ent here bould with true banks of the missile loaded with propeller's, and the district rescaling the countdown. I reported to the test conducts that there was an indication of frosting on the lover edge or the missil approximately 187 in beight, extending from the area of the lover momented camere that to the Q4 section of the nacelle.

The rest conductor asselnce if I had noticed this condition on the previous tanking test. a shirb'I replici "Negative". The test conductor then asked for a read cut in the innert section ambient temperature measurement. The reply was, "Temperature Normal".

The test conduction than asked we if I would detect any liquid draining from the area, to which I replied "Negative". The test conductor again asked for a read out on the thrust secular ambient temperature measurement, the reply was again "Temperature Normal".

The past conductor then Asawi me if I thought that this was not a normal fructing, due to the LM2 in the ballow shrouds sitting for an hour in this state, and due to the weather condition on this day, at which time the court was again records. At the command of vernier and main flame deflector water on, I observed the value from the buckets, and reported same to the test conductor. Shortly after this, as the Command Ignition Start was given, I was observing the lower testion of the missile and main flame deflector area through bits days. I observed the engines fire off, and at the same instant, the complete area around the lower section of the thrust section and launcher sected to ignite.

Seeing that this was not a normal start, I instantly thought of what may take place text. I durked down inside the tank and yelled "Fire", into my mouthpless. I had hardly gotten down when I heard and felt a tramendous explosion, and immediately yelled "Explosion" into my mouthplace. At that time, I looked through the observation window in the front of the tank and saw a hore ball of smoot and limb eround the stand area, with debris flying



6,10-9

in all directions. I could see that the test stand had fallen over. I immediately reprited into my mouthpiece, that we had lost the missile, test stand and everything. The time lapse between Ignition Start and the explosion was momentary.

Signed - George Grande, Clock No. 40161 5/13/62

C

(`*



This document contains information affecting the national defense of the United States within the meaning of the Espicnage Laws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

LISTING 0

7.0

1

The estimated - quiterents for the refurbishment of Sycamore SL to a condition lights for continuences of the static test program are preserved by . This estimate was established for planning purposes only.

Design Mailon. 5000 hours Vendor and She crillatter Costa \$1,282,500

Preserved in this section is a complete listing of damaged TGSE and facility equipment including an estimation of the degree of damage incurred by each item.

MEC TGS NAM	HANICAL E E	PART NO.	5 DAMAGE
1	= Rockatduma Samulaa Cant	G2000MB4X6	15
••	increatine bitvice data	GCOODELANO	
2.	Rocketdyno Pneu Test Unit	G3004	100
3.	Rocketdyne Pneu Test Console	9529-84180(G3052)	50
4.	Safety Net (two)	27-09722	100
5.	Flame Deflector Covers	27-09721	10
6.	Maín Flame Deflector	7-96015	5
7,	Vernier Flame Deflectors	7-96078 7-96011	100 100
8.	Vernier Flame Deflector Platform	27-96092	100
9.	Service Tower	7-96109	100
10.	Test Stand (Below Sta 17)	27-98959	25
11.	Helium Charge Unit (Installation)Distribution	27-08014 27-86111	100 80
12.	Hydraulic Pumping Unit (Installation)Distribution	27-08657 27-87041	50 100
13.	Pressurization Control Unit (Installation)	7-08432	50
14.	Launcher Booster Unit	7-08352	60
15.	LN2 Heat Exchanger (Helium)	27-08612	5
16.	Pod Cooling Unit (Duct Installation)	7-08620 27-80011	50 100
17.	Ullage Tank System (Lox)	7-08115	100
	CONFIDENTIAL	LINCLAS	SIFIED



(

₽ • • ,

7.0-2

MECH	ANICAL (Continued)		<i>d</i>
NAPH		PART NU.	<u>> DAMAGE</u>
18.	Ullage Tark System (Fuel)	7–08116	100
19.	Launcher	27-49500	90
20.	Stret a Sling	7-91060	50
21.	Thrust Section Heater (Duct Instl)	7-86304 &27-08138 27-80039	20 100
22.	Nose Handling Adapter	27–91049	10
23.	Nitrogen Gharge Panel	7-08411	100
24.	Erection Methan_sm	27-49519	100
25.	Canister Furge System	786105	5
26.	Fuel Transfer Unit	7-02221	5
27,	Lox Fransfer Unit (R&D)	7-02222	1
28.	Cox-Lox Table	7-21202	100
29.	Captive Firing Kit	27-24020	100
30.	Fuel Drain Kit	27-24508	100
31.	Erection Serec	27-95455	100
32.	Booster Tirbine Exnaust	27-96101	30
33.	Silo Low Topping Instl.	27–27038	65
34.	Silo Rapid : 🕫 Loading Instl.	27-27084	40
35.	Fuel Distribution System	7-86147	15
36.	Mass Flowmeter Instl.	27-86146 E0 204374	5
37.	Haskell Compressor	6550	10
38.	Tower Pressurization System	27-89045 7-89342	100



\$



C

<u>(</u>,

C

7.0-3

ህድሮዝ	RAUTCAT (Continued)		
NAM		PART NO.	% DAMAGE
39.	Anti-Fire System	27-96108	70
40.	Booster Coclant System	27-96107	100
41。	Firex Instl (Sile Low Fank)	27-27083	30
42.	Firex Institutor Topping Tank)	27-90114	15
43.	Monitor Nozzle System	7-09311	60
44.	Perimeter Fire System	27-98971	80
45.	Skirt Firex System	27-80187	100
46.	Verrier Firex System	27-09137	100
47.	Tower Pog System	PE-55-409-14-7	100
48.	Missile Deluge System	PE-55-409-M-7	90
49.	GN2 Distribution System	7-00139	60
Fac	ility		
١.	CO2 Unit Distribution Lines		10 50
2.	Utility Bldg		85
3.	SDC Blag		75
4.	Blockhouse Ancer		10
5.	Helium Distribution System		5
6.	LN2 Distribution System		5
7.	GN2 Distribution System		5
8.	Facility Water System		10
9.	Access Structures		20



9

2 UNCLASSIFIED

Ū

C

C

7.0-4

\$

÷

NAM		PART NO.	5 DAMAGE
1.	AC 400 Cycle Generator	AFS 6125-724-8941	2
2.	Energency Battery Instl	7-68269	50
3.	Acoustica Signal Conversion Unit	50097507	100
Ļ.	Acoustica Alternate String Cable	50021146-5-6	100
5.	Umbiliçal Cables	27-69709 •	100
6.	Site Control Wiring and Cabling	27-01641 27-61184 27-09150	10 30 30
7.	Silo Logic Equip	27-68746	1
8.	R & D Conscies and Racks	27-69903	1
9.	Terminal Boxes (Test Stand) Umbilical Junction Boxes Area Interconnecting Boxes	27-69903	60
10.	Battery Tester	7-68374	50
11.	Stretch Control Box	7-68260	100
12.	Local Purge Control Assy	27-68923	`50
13.	Battery Switch Box	7-68026	50
14.	Pneu Sequence Box	27-68973	15
15.	Missile Power Relay Box	27-69713	5
16.	Erection Control Assy	27-68660	100
Faci	lity		
1.	Lighting - Blockhouse Annex		80
2.	Lighting - Area		20
3.	60 Cycle Distribution System		15
4.	Regulated Power Distribution System		20

This document contains information affecting the national defense of the United Starts within the meaning of the Explored Jaws, Title 18, U.S.C., Section 793 and 794, the transmission or revelation of which in any menner to an unauthorized person is prohibited by law.

Z

IE IS Ĩ

Ũ

C

C

7.0-5.

ų.

2

1

<u>ELECTRICAL</u> (Continued) NAME	PART NO.	% DAMAGE	
5. Pod Air Cooling Otls.		.40	
6. SDC 60 Cycle Supply System		100	
7. Elevator and Hoist C. 1. rol (Si	IC)	30	
Ir struzentetion			
1. Umbilical Cables	7-19545	100	
2. Instrumentation Cal Card	7-18006	35	
3. S-1 IV System	7-18008	40	
4. Camera Pads Circuits	7-18008	60	
5. Communications System (Test Stand Area Circuits)	7–15002	50	
6. Area Instrumentation Circuits	7-17093	60	
7. Wind Speed Indicator	7-18309	50	
8. Terminal Boxes (Test Staná)	7-17090	95	
MOTION PICTURE CAMERA AND EQUIPMEN	ľ		
A Cameras (DBM - 4AM)			
1. 16 mm S/N 4339		20	
2. 16 mm S/N 4338		100	
3. 16 mm S/N 4432		40	
4. 16 mm S/N 4445		60	
5. 16 mm S/N 4447		. 100	
6. 16 mm S/N 4431		100	
B. Associated Equipment			
1. Magazine S/N 932		30	
2. Carrying Case S/N 5034		100	
UNCLASSIFI	ED	•	
CONICIDENT			

-CONFIDENT/AL	
UNCLASSIFIED	

C

()

C

í

7.0-6

!

.

	MOTI NAME	ON P	icture (AMERA AND EQUIPMENT (Contin	nued) PART NO.	% DAMAGE
	В.	Ass	ocisted	Equipment (Continued)	•	
		3.	Tripod	(2) Two		100
		4.	Iens (8	3) Eight		100
, ~ •	SEVE NAME	RABL	e and no	ON-CAPITAL EQUIPMENT	QUANTITY	<u>% DAMAGE</u>
	I.	Sev	erable H	Quipment		
		A.	'General	Dynamics/Astronautics		
			1. Fu	riture and Fixtures		
			a. b. c. d. s. f. s. h. j. k. 2. Pon a. b. c. c.	Chai.s Desks Work Bench File Cabinets Table Recording Time Clock Oscillator Wide Range Fire Extinguishers "17" Drill Press Bench Grinder Hand Combinator Table Tools Grinder Rivetar Hammer Drill Motors	12 6 1 6 1 1 1 21 1 1 1 1 1 7	100 100 109 100 100 100 100 100 100 100
		Β.	Governi	ment Equipment		
			1, Fu	cniture and Fixtures		
			a. b. c. d. e. î. g.	Work Benches Desks File Cabinet Chairs Storage Cabinets Steel Lockers Table	4 4 1 7 2 12 1	100 100 100 100 100 100 100
			UN	ICLASSIFIED		

		ONFIDENTIAL		7.0-7
	<u>SEVERABLE A</u> NAME	INCLASSIFIED	nued) OUANTITY	% DAMAGE
	I. Severa	ble Equipment (Continued)		
	B. Go	vernment Equipment (Continued)		
	1,	Furniture and Fixtures (Contin	nued)	
		 h. Power Supply (M.35) i. Hand Gart j. Video Amplifier k. Scopenobile Cart l. Water Gooler m. Acetylene Welding Cart n. Fire Extinguishers o. Airco Welder p. Schram Compressor 	1 1 1 1 1 7 1 1	100 100 100 100 100 100 100
	2,	Portable Tools		
0		 a. Transit Stand b. Grinder c. Hammer Pheu d. Skil Sander e. Drill Metor f. Jack Lift g. Fork Lift h. Tow Tractor 	1 3 3 1 3 2 1 1	100 - 100 - 100 - 100 - 100 - 100 - 5 5
	II. Non-Ca	pital Equipment		-
	A. PI	ant Equipment (Parishable)		
	1,	, Portable Wood Sheds	6	100
	2.	, Desks	2	100
	3.	, Specific Gravity Kit	1	100
	4.	, Aldis Lamp	1	100
	5.	Black Lamps	2	100
	6.	, Ohmeters	10	100
	7.	, Airmask Unit	2	100
	8,	, Fire Blankets	3	100
	-	UNCLASSIFIED		



Ø

C

٢

1

C

-

7.0-8

NAME	ARDIN AN	D RON-DEFILAD DUDIFALMI (CONCIMUED	QUAN'	<u>TITY</u>	8 DAMAGE
II.	Non-Car	sitel Equipment (Continued)			
	L. Pla	nt Equipment (Perishable) (Continu	led)		
	9.	50 lb. Recharge Power	1		100
	10.	Nozzles, Fire	8		100
	11.	Fire Hoses	2		100
	B. Per	ishable Tools			
	1.	Torque Wrenches	10	-	100
	2.	Open End Breakaway Wrenches	10		100
	3.	"B" Nut Wrenches	21		100
	4.	Non-Sparking Pipe Wrenches	8		100
	5.	Non-Sparking Open End Wrenches	18		100
	6.	Non-Sparking Box End Wrenches	12		100
	7.	Non-Sparking 1/2" Drive Socket Sa	t 1	Set	100
	8.	Non-Sparking 3/4" Drive Scoket Se	t 1	Set	100
	9.	Crow Foot	8	Sets	100
	10.	Double End Flare "B" Nut	2	Sets	100
	11.	Short Handle Combination "B" Nut	2	Sets	100
	12。	Heavy Duty Ratchet	2	Sets	100
	13。	Striking Box Sockets	1	Set	100
	. 14.	Extra Heavy Drive Sockets	1	Set	100
	15。	Cresent Wrenches	9		100
	16.	Pipe Wrenches	7		100
•	17.	Garpenters Hand Tools	31		100





C

C

C

7.0-9

1

:

SEV: NAME	<u>SEVERABLE AND NON-CAPITAL EQUIPMENT</u> (Continued) <u>NAME</u> <u>QUANTITY</u>					
п.	Non	-Capi				
	B.	Peri	shable Tools			
		18.	Sledge Henners	6	100	
		19.	Pliers	353	100	
		20.	C-Clamps	156	100	
		21.	Panches	30	100	
		22.	Hacksaw Elades	144	100	
		23.	Metal Hole Saw	2	100	
		24.	Metal Letter Stamps	12 Sets	100	
		25.	Visəs	12	100	
		26.	Steel Scales	7	100	
		27。	Steel Tapes	4	100	
		28.	Fishscales	2	100	
		29.	Snakes	2	. 100	
		30.	Plumb Bob	2	100	
		31.	Torque Driver #1500 Handles	36	100	
		32.	Tornue Tips	500	100	
		33.	Screw Drivers	4	100	
		34.	Gauges	9	100	
		35.	Tube Benders	6	100	
		36.	Flaring Tools	12 Sets	100	
		37。	Prs-Sets	4 Sets	100	
		38.	Handles	28	100	





0

.

0

T

7.0-10

ļ

SEVERABI	LE AND	NON-CAPITAL EQUIPMENT	(Continued) QUANT:	ITY	% DAMAGE
II. Nor	n-Capi	tal Equipment (Continue	ed)		
B.	Peri	shable Tools (Continued	i)		
	39.	Counter Bores	165		100
	<i>4</i> 0.	Counter Sinks	150		100
	41.	Drills Assortad	6500		100
	42.	Dr111 Attachments	24		100
	43.	Dies	5	Sets	100
	44.	Files-Hand	. 600		100
	43°	Reamers	5	Sets	100
	46.	Taps and Easy Cuts	110		100
	47.	Air Nozsles	15		100
	48.	Cutoff Blocks	6		100
	49。	Sliding Bar Extension	2		100
	50.	Embossing Tools	7		100
	51。	Flashlights	50		100
	52。	Prestolite Assorited	lips and Tank 2	Sets	100
	53。	Gasket Catter	2	Sets	100
	54.	Spanner Wrenches	112		100
	55.	Wire Strippers	48		100
	56.	Calipers	14		100
	57。	Micrometers	6		100
	58。	Soldering Irons	90		100
	59。	Amp Tools	50		100
	60. L	INCLASSIFIE	39 ED		100

NCLASSIFIED

0

C

T

7.Q-11

SEVERABLE AND NON-CAPITAL EQUIPMENT ((Continued) <u>QUANTITY</u>	3 DAMAGE
III. Personal Tools		
A. Tool Kits	45	100
CENERAL S-4 AREA		
NAME	PART NO.	% DAMAGE
1. Load Cell Instl	55-99011	10
2. Hydraulic Supply Unit	55-87201	1
3. Brine Chiller	55~08002	4
4. Air Handling Unit	55-08122	5
5. Stretch Sling	55-90013	1 -
6. Helium Reg Controller	(55–92030) 4150R	100
7. Helium Supply Line (S-1 Area)	55-92030	10
8. GN2 Supply Line (S-1 Area)	55-83035)	8
9. Stored Regulators (Two)	VN-50-967 (55-83035)	100
10. TV Cameras	7-18992	15
11. Lox Transfer Line	55-92031	10
Facility .		
1. Utility Bldg		70
2. Maintenance Bldg		20
3. Steam System		1
Missile (Centaur)	55-0501-3	Under Investigation

