

UNCLASSIFIED



AD NUMBER

AD-844 821

CLASSIFICATION CHANGES

TO UNCLASSIFIED

FROM SECRET

AUTHORITY

Air Force Ltr, San Bernardino Air Materiel Area (SBAMA);
Nov 17, 1965 by R.J. Cook IAW Document Markings

19991004284

THIS PAGE IS UNCLASSIFIED

UNCLASSIFIED



AD NUMBER

AD-844 821

NEW LIMITATION CHANGE

TO

DISTRIBUTION STATEMENT: A

Approved for public release; Distribution Unlimited.

LIMITATION CODE: 1

FROM

No Prior DoD Distr Scty Cntrl St'mt Assgn'd

AUTHORITY

SAMSO, USAF Ltr; Mar 20, 1972

THIS PAGE IS UNCLASSIFIED

~~SECRET~~

WD

AA 61-0189
30 November 1961

UNCLASSIFIED

WS 107A-1 FLIGHT TEST WORKING ~~SECRET~~

FLIGHT TEST REPORT

ATLAS MISSILE 4F

GIIIIIIID

GENERAL DYNAMICS | ASTRONAUTICS

23 November 1961

DDO
RECEIVED
DEC 18 1968
A

GENERAL DYNAMICS
ASTRONAUTICS

JAN 18 1962

LIBRARY

Log No. T 61-4304 Copy No. 47

AMR RANGE TEST NUMBER 3751

ASTRONAUTICS TEST NUMBER P1-601-00-4

SECURITY NOTICE

This document contains information affecting the National Defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C. Sections 793 and 794. The transmission or the revelation of its contents in any manner to an unauthorized person is prohibited by law.

This document is subject to special export controls and each transmittal to foreign governments or foreign nationals may be made only with prior approval of Hq. SAMS, IA., Ca. 90048
Attn: SMSD

compiled and published at AMR by

Reproduced From
Best Available Copy

WS 107A (ATLAS) CLASSIFICATION CHANGED TO:

UNCLASSIFIED

AUTHORIZED BY: AIR FORCE LETTER
SAN BERNARDINO AIR MATERIEL AREA (SBAMA)

DATED 17 NOVEMBER 1965

RECLASSIFIED BY: Rf Cook
DEPT. 130-1 DATE 12-13-65

UNCLASSIFIED

T 61-89260

DECLASSIFIED

ENGINEERING CORRESPONDENCE
GENERAL DYNAMICS/ASTRONAUTICS
POST OFFICE BOX 166
SAN DIEGO 12, CALIFORNIA
LOG TC 321

FOREWORD

This report has been prepared to present preliminary information relative to the flight of Atlas Missile No. 4F. The information presented is based on visual observation and data evaluation to the extent permitted by time limitations. It should be considered as preliminary only, and the final reports on this flight referenced for further information. The technical content has been prepared and jointly agreed upon by members of the WS 107A-1 Flight Test Working Group.

Prepared by: Data Operations, General Dynamics/Astronautics, AMR.

W. G. Donnellon
for E. V. Thatcher
Manager, WS 107A-1 Project Office
Space Technology Laboratories, Inc.
AMR, Florida

K. E. Newton
K. E. Newton
Chief of Test Operations, AMR
GD/Astronautics, A Division of
General Dynamics Corporation

L. D. Solid
for L. D. Solid
Responsible Representative
WS 107A
Rocketdyne, AMR, Florida

Peter Concio (son)
M. J. Swing
Manager, Field Test Engineering
General Electric (DSD)
AMR, Florida

W. H. Caldwell
for W. H. Caldwell
Manager, Test Operations
Burroughs Laboratories
Burroughs Corporation

O. M. Henriksen
O. M. Henriksen
Test Operations Section Head
American Bosch ARMA Corp.

P. R. Carden
for P. R. Carden
Test Operations Section Head
AVCO Corporation

T. F. Davidson
for T. F. Davidson
Site Manager, AMR
Acoustica Associates

F. W. Adkins
F. W. Adkins
Supervisor, Development Test, AMR
Aeronautic Division
Ford Motor Company

P. R. Wignall
for P. R. Wignall
Colonel, USAF
Commander
St. Cal US146

UNCLASSIFIED

Page No. iii
AA 61-0189

SUMMARY

Atlas Missile 4F, the second "F" Series Missile to be flight tested, was launched from Complex 11, AMR, at 1604 EST on 22 November 1961. The flight was successful and the Mark 5 Mod 2 Re-entry Vehicle impacted in the target area at a range of 4,388 nautical miles. MILS data placed impact within 1.2 nautical miles of the aim point.

Operation of all missile systems was satisfactory except that Umbilical 600U7 did not eject and was pulled out at liftoff, and re-entry vehicle playback data was not received after blackout.

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794, THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

FORM 81000-2

UNCLASSIFIED

TABLE OF CONTENTS

| | <u>Page</u> |
|---|-------------|
| FOREWORD | ii |
| SUMMARY | iii |
| TABLE OF CONTENTS | iv |
| FLIGHT TEST OBJECTIVES | 1 |
| FLIGHT TRAJECTORY | 4 |
| SYSTEM PERFORMANCE | 8 |
| Airframe | 9 |
| Propulsion System | 12 |
| Acoustics Propellant Utilization System | 17 |
| Pneumatic System | 19 |
| Hydraulic Systems | 22 |
| Missile Electrical System | 25 |
| Range Safety Command System | 26 |
| Asusa System | 27 |
| Penetration System | 28 |
| Flight Control System | 29 |
| Inertial Guidance System | 30 |
| Mod III Range Safety and Instrumentation System | 34 |
| Re-entry Vehicle | 36 |
| Propellant Tanking | 37 |
| Telemetry | 38 |
| Leadline Instrumentation | 40 |
| CONCLUSIONS AND RECOMMENDATIONS | 41 |
| COUNTDOWN TIME VERSUS EVENTS | 42 |
| MISSILE CONFIGURATION | 50 |
| HISTORY OF SM-65F MISSILE NO. 4F | 54 |

UNCLASSIFIED

ORDER YES NO PART COMMENT

OBJECTIVES

- 1 - First
- 2 - Second
- 3 - Third

Weapon System Objectives

| | <u>ORDER</u> | <u>YES</u> | <u>NO</u> | <u>PART</u> | <u>COMMENT</u> |
|--|--------------|------------|-----------|-------------|--------------------------------------|
| 1. Determine the performance and repeatability of the missile sub-system and associated ground equipment. | 2 | X | | | |
| 2. Evaluate the ability of the MAPCHE System and procedures to check out a missile and place it in a first readiness condition | 1 | X | | | |
| 3. Obtain radar and/or radiation data during re-entry. | 3 | | | | Awaiting delivery of downrange data. |
| 4. Obtain data on the Re-entry Vehicle impact location for the statistical determination of CEP. | 1 | X | | | |
| 5. Evaluate the performance of the Acoustica PU System. | 1 | X | | | |
| 6. Evaluate the ARMA Inertial Guidance System performance and accuracy. | 1 | X | | | |
| 7. Determine the flight performance of the fuel feed system. | 2 | X | | | |
| 8. Evaluate the performance of the penetration systems. | 2 | X | | | Awaiting delivery of downrange data. |

ORDER YES NO PART COMMENT

OBJECTIVES

| <u>ORDER</u> | <u>YES</u> | <u>NO</u> | <u>PART</u> | <u>COMMENT</u> |
|-------------------------------------|------------|-----------|-------------|-------------------------------------|
| 9. | | X | | |
| <u>Non-weapon System Objectives</u> | | | | |
| 1. | | 2 | X | Lost Link 255.1 mc during blackout. |
| 2. | | 2 | X | |
| 3. | | 2 | X | |
| 4. | | 2 | X | |
| 5. | | 2 | X | |

Demonstrate the launcher compatibility with the "F" Series missile.

Non-weapon System Objectives

1. Evaluate the Mark 5, Mod 2 Re-entry Vehicle ablation material performance during re-entry.

2. Determine the Mark 5, Mod 2 Re-entry aerodynamic heating, loading and stability during re-entry.

3. Determine the Mark 5, Mod 2 Re-entry Vehicle Separation and Arming and Fusing sub-systems performance.

4. Demonstrate the compatibility of the Mark 5, Mod 2 Re-entry Vehicle with the F Series missile, in particular, the Flight Control System.

5. Evaluate the performance of the Sandia warhead systems.

~~SECRET~~

Page No. 4
AA 61-0189

FLIGHT TRAJECTORY

The flight of Atlas Missile 4F was planned for a range of 4388 nautical miles downrange with impact in the center of Ascension Missile Impact Location System (MILS) area.

This was the first "F" Series missile to be flown with a lofted trajectory.

A tabulation of miss distances and a comparison of nominal flight performance parameters from Flight Trajectory E XII, and measured test values from Azusa and telemetry data at significant times along the trajectory are presented below.

Figure 1 presents impact points as determined from several sources.

Note: All times in this report are based upon Range Zero Time which occurred at 1604:11 EST. One Inch Motion occurred at 1604:11.46 EST.

| <u>Source</u> | <u>Miss Distance</u> | <u>95% Confidence Limits</u> |
|---|--------------------------------|--|
| Azusa Mk 11 | 1.57 nm Short 0.32 nm Right | Major Axis 0.239 nm Minor Axis 0.215 nm @ 123.45°T |
| Mod III | 1.23 nm Short 0.62 nm Right | Major Axis 0.42 nm Minor Axis 0.37 nm @ 123.1°T |
| Splash No. 2 | 1.14 nm Short 0.30 nm Right | 4 0.110 nm x 7 0.107 nm @ -60.7°T |
| SOFAR Bomb 1 | 1.17 nm Short 0.30 nm Right | 4 0.115 nm x 7 0.113 nm @ 27.6°T |
| Guidance/Mod III Velocity Comparison | 0.50 nm Short 0.20 nm Right | ----- |

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE Espionage Laws, TITLE 18, U.S.C., SECTIONS 793 AND 794, THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

FORM 4400-0

~~SECRET~~

~~SECRET~~

| <u>Item</u> | <u>Unit</u> | <u>Nominal</u> | <u>Measured</u> |
|-----------------------------|-------------|----------------|-----------------|
| Liftoff Weight | lbs | 268, 597 | - |
| Launch Azimuth | deg | 106.3 | 106.3 |
| BCO Weight | lbs | 67, 870 | - |
| BCO Velocity | ft/sec | 9, 035 | 9, 080 |
| BCO Altitude | ft | 205, 829 | 208, 484 |
| BCO Range | nm | 42.4 | 42.3 |
| BCO Time | sec | 125.7 | 125.8 |
| SCO Weight | lbs | 15, 513 | - |
| SCO Velocity | ft/sec | 20, 113 | 20, 126 |
| SCO Altitude | ft | 941, 657 | 951, 725 |
| SCO Range | nm | 384.5 | 375.8 |
| SCO Time | sec | 293.5 | 289.4 |
| VCO Weight | lbs | 15, 317 | - |
| VCO Velocity | ft/sec | 19, 992 | 19, 985 |
| VCO Altitude | ft | 1, 044, 120 | 1, 060, 967 |
| VCO Range | nm | 440.2 | 433.8 |
| VCO Time | sec | 311.2 | 307.8 |
| Impact Time | sec | 1, 954.1 | 1, 969.3 |
| Impact Range | nm | 4, 388 | 4, 387 |
| Impact Latitude (Geodetic) | deg S | 8°4.56' | 8°4.17' |
| Impact Longitude (Geodetic) | deg W | 14°44.69' | 14°45.83' |

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.


FORM 4000-0

~~SECRET~~

~~SECRET~~

IMPACT POINT COMPARISON

Page No. 6
AA 61-0189



SOUTH LATITUDE

WEST LONGITUDE

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

FORM 21000-6

~~SECRET~~

Note: Nominal times are corrected for the difference between Range Zero and One Inch Motion. Measured velocity, altitude, and range at booster, sustainer, and vernier cutoff, are from Azusa revised data. Impact range and co-ordinates are taken from MILS Splash Net Data. Measured times are taken from telemetry recordings of discrete generations. Impact time is taken from the loss of re-entry vehicle signal. Altitude is height above launch horizontal. Velocity is speed relative to the earth's surface. Range is measured horizontal from the launch pad with the exception of impact range which is measured along the surface.

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., CHAPTER 37B AND FOR THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

FORM 2000-0

SYSTEM PERFORMANCE

~~SECRET~~

Page No. 9
AA 61-0189

AIRFRAME

Missile structural integrity was satisfactorily maintained throughout powered flight and well beyond re-entry vehicle separation. Booster separation was satisfactorily initiated as recorded by M 32 X, Conax Valve Command. Re-entry vehicle separation and Atlas/Thor retro-rocket operation were satisfactory as indicated by M 79 A, Missiles Axial Acceleration Fine. ARMA data recorded peak axial acceleration values of 7.32 G's at BCO and 5.15 G's at SCO. Umbilical 600U7 did not eject either electrically or mechanically. A review of film data showed that separation was effected when the umbilical became taut. Before the umbilical came out the bulkhead at the aft end of the pod became widely separated from the pod. The bulkhead snapped back into place when the umbilical separated. There were no apparent detrimental effects on missile operation.

The two environmental temperature measurements in the engine compartment gave normal indications. A 638 T, Aft Side A Frame Q 2, recorded 112°F throughout booster phase and 93°F thereafter. P 671 T, Thrust Section Ambient Quad 4, remained steady throughout flight at 93°F. This was not typical of other flights as normally the temperature rises during sustainer phase.

The thermocouple reference junction in Pod 1, Measurement T 105 T, indicated an essentially constant temperature of 55°F.

Four temperature measurements were instrumented on the Thor retro-rocket. Three of the four measurements indicated valid data. However, M 177 T did not activate until 151 seconds. The maximum temperature recorded by each measurement is listed in the following table.

| <u>Measure- ment</u> | <u>Description</u> | <u>Maximum Temp in °F</u> | <u>Time in Seconds From Liftoff</u> |
|--------------------------|----------------------|-------------------------------|---|
| M 177 T | V1 Thor Retro Nozzle | 129 | 290 |
| M 178 T | V1 Thor Retro Case | 91 | 284 |
| M 179 T | V2 Thor Retro Nozzle | 122 | 280 |
| M 180 T | V2 Thor Retro Case | Deleted prior to launch | |

Five temperature measurements were instrumented on the missile skin near the Scientific Passenger Pod in order to study the skin heating characteristics due to aerodynamic flow in this area. The maximum temperature recorded by each measurement is listed in the following table.

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

FORM 44000-0

~~SECRET~~

~~SECRET~~

| <u>Measurement</u> | <u>Station</u> | <u>Maximum Temp in °F</u> | <u>Time in Seconds From Liftoff</u> |
|--------------------|----------------|-------------------------------|---|
| A 41 T | 1038 | 187 | 149 |
| A 42 T | 1048 | 187 | 149 |
| A 43 T | 1054 | 196 | 149 |
| A 44 T | 1062 | 169 | 149 |
| A 45 T | 1075 | 169 | 149 |

Four temperature measurements were instrumented in the V2 fairing area. These measurements were added in order to study the aerodynamic heating characteristics of the new fairing and to determine the environmental temperatures of the Thor retro-rockets. The fairing configuration was changed in order to house the added Thor retro-rockets. Measurement A 31 T, V2 Heat Shield, activated at 63 seconds, rose to a maximum temperature of 477°F at 93 seconds, then started a decrease and was indicating zero by 128 seconds. A 32 T, V2 Heat Shield Calorimeter, did not function throughout the flight. A 57 T, at the forward retro-rocket support, indicated a maximum temperature of 108°F at vernier cutoff. Measurement A 679 T, V2 Fairing Aft, began an increase at 68 seconds and indicated a maximum temperature of 284°F by 121 seconds.

The V2 clamshell was instrumented with two temperature measurements. Measurement A 142 T, V2 Pitch Feedback Electrical Connector, rose to a maximum temperature of 169°F at 116 seconds. A 143 T, V2 Clamshell Inner Surface, indicated 204° at booster cutoff and 302° at 270 seconds.

An accelerometer, Measurement A 36 A, was mounted on the booster thrust section to analyze the longitudinal motion of the thrust section as it jettisons. Any sudden impacts or hitches in the thrust section movement was to be revealed by this accelerometer. The accelerometer was attached to the booster thrust section and utilized an eight foot cable. No valid data was gathered from this measurement. The measurement apparently became inoperative immediately after liftoff.

Two other accelerometers were instrumented on the booster section jettison rail end in order to ascertain that the rail deflections are within specifications. One accelerometer was to measure acceleration in the tangential direction and the other was to measure acceleration in the radial direction. Measurement A 77 A, Jettison Rail End, Radial, apparently yielded invalid data.

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794, THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

~~SECRET~~

SECRET

Page No. 11
AA 61-0189

A 78 A, Jettison Rail End, Tangential, appeared to give valid indications, showing minor movement during staging. Further evaluation will be required to determine the value of the data recorded by this measurement.

At booster staging, a significant quantity of LO2 and fuel is trapped in the jettisoning thrust section. The trapped LO2 either quickly vaporizes or mixes with the fuel and actually explodes. The phenomenon may explain the observed missile nose-up which occurs right after the start of the booster jettison operation. Four measurements, two pressure transducers and two low mass thermistors, were provided in order to make a study of the above described phenomenon. The two pressure transducers, Measurements A 59 P, Ambient B1 LO2 Staging Disconnect, and A 60 P, Ambient B2 LO2 Staging Disconnect, indicated some pressure variation just prior to the telemetry blackout period. The two thermistors, Measurements A 35 T, Ambient B1 LO2 Staging Disconnect, and A 58 T, Ambient B2 LO2 Staging Disconnect, recorded temperature decreases at liftoff and at booster staging. It appears that the blips indicating temperature decreases at staging were followed by blips indicating increases. Further evaluation is required to determine the full significance of this data.

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE Espionage Laws, TITLE 18, U.S.C., SECTIONS 793 AND 794, THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

SECRET

~~SECRET~~

Page No. 12
AA 61-0189

PROPULSION SYSTEM

The Propulsion System performance was satisfactory throughout all phases of the flight. Engine thrust rises and decays appeared normal. Sustainer engine ignition delay time was not acquired due to the EA recorders being on slow time.

In order to evaluate sustainer engine performance during the staging black-out, a time delay recording of RF 1 was transmitted on RF 4. Also additional instrumentation was added which consisted of Sustainer Gas Generator (SGG) Fuel Check Valve Acceleration (P 531 O), Sustainer LO2 Regulator Output Pressure (P 967 P), SGG Fuel Injection Manifold (P 463 P), Sustainer Fuel Injection Manifold Pressure (P 517 P) and SGG LO2 Injection Manifold Pressure (P 337 P). No abnormal activity was noted on sustainer engine pressure measurements during staging.

Interpretation of the SGG fuel check valve acceleration data was difficult because of the large range of the accelerometer (300 G's). The average accelerations were 8 G's at liftoff, 10 G's prior to BCO, and 9 G's prior to SCO. The acceleration level remained fairly constant throughout sustainer engine firing at a frequency of 600 to 640 cycles per second.

A tabulation of Propulsion System telemetered data is presented on the following pages.

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

FORM 41000-6

~~SECRET~~

PROPULSION SYSTEM TIME SLICE DATA

| <u>Measure-</u> <u>ment No.</u> | <u>Description</u> | <u>Units</u> | <u>Nominal</u> <u>Values</u> | <u>L/L at</u> <u>Liftoff</u> | <u>TLM</u> <u>After</u> <u>Liftoff</u> | <u>TLM</u> <u>Prior</u> <u>to BCO</u> | <u>TLM</u> <u>Prior</u> <u>to SCO</u> | <u>TLM</u> <u>Prior</u> <u>to VCO</u> |
|------------------------------------|------------------------|--------------|---------------------------------|---------------------------------|--|---|---|---|
| <u>Booster Engines</u> | | | | | | | | |
| P 155 P | B1GG Combustor | psia | 478 | - | 480 | 520 | - | - |
| P 184 P | B2GG Combustor | psia | 478 | - | 480 | 520 | - | - |
| P 713 T | B1GG Combustor Temp | dgf | 1232* | - | 1230 | 1250 | - | - |
| P 714 T | B2GG Combustor Temp | dgf | 1275* | - | 1230 | 1230 | - | - |
| P 473 P | B1 Lo Pr Lube Oil Man | psia | - | - | 120 | 108 | - | - |
| P 279 P | B2 Lo Pr Lube Oil Man | psia | - | - | 150 | 141 | - | - |
| P 4 P | B2 Fuel Pump Inlet | psia | - | 72.8 | 67 | 54 | - | - |
| P 1025 T | B1 LO2 Pump Inlet Temp | dgf | - | -287 | - | - | - | - |
| P 1054 T | B2 LO2 Pump Inlet Temp | dgf | - | -286 | - | - | - | - |
| P 84 B | B1 Pump Speed | rpm | 6096* | - | 6110 | 6305 | - | - |
| P 83 B | B2 Pump Speed | rpm | 6184* | - | 6180 | 6378 | - | - |
| P 2 P | B1 Fuel Pump Inlet | psia | - | 62.7 | 69 | 53 | - | - |
| P 39 P | B1 Fuel Pump Disch | psia | 840* | - | 810 | 830 | - | - |
| P 38 P | B2 Fuel Pump Disch | psia | 841* | - | ** | ** | - | - |

THIS DOCUMENT CONTAINS UNCLASSIFIED INFORMATION EXCEPT WHERE SHOWN OTHERWISE BY THE MARKINGS ON THE INFORMATION CONTAINED HEREIN. IT IS THE POLICY OF THE NATIONAL AERONAUTICS AND SPACE ADMINISTRATION TO MAKE AVAILABLE TO THE PUBLIC THE INFORMATION CONTAINED HEREIN TO THE EXTENT PRACTICABLE AND WITHOUT REGARD TO THE RIGHTS OF ANY OTHER PERSON OR ORGANIZATION TO RECEIVE OR USE THE INFORMATION CONTAINED HEREIN.

SECRET

| Measure- ment No. | Description | Nominal Units | L/L at Liftoff | TLM After Liftoff | TLM Prior to BCO | TLM Prior to SCO | TLM Prior to VCO |
|-------------------------|-----------------------|------------------|-------------------|-------------------------|------------------------|------------------------|------------------------|
| P 91 P | B1 LO2 Inj Man | psia 677 | - | 660 | 700 | - | - |
| P 92 P | B2 LO2 Inj Man | psia 677 | - | 660 | 710 | - | - |
| P 66 P | B1 Thrust Chm | psia 573* | - | 560 | 592 | - | - |
| P 59 P | B2 Thrust Chm | psia 574* | - | 568 | 608 | - | - |
| P 1711 T | B1 Nacelle Ambient | dgf - | 74 | - | - | - | - |
| P 1712 T | B2 Nacelle Ambient | dgf - | 75 | - | - | - | - |
| <u>Sustainer Engine</u> | | | | | | | |
| P 337 P | SGG LO2 Inj Man | psia 850 | - | 880 | 900 | 870 | - |
| P 709 T | SGG Combustor Temp | dgf 1052 | - | 885 | 930 | 835 | - |
| P 341 P | S Lube Oil Man | psia - | - | 645 | 645 | 615 | - |
| P 56 P | S LO2 Pump Inlet | psia - | - | 67.5 | 111 | 78 | - |
| P 530 T | S LO2 Pump Inlet Temp | dgf - | - | ** | ** | ** | - |
| P 55 P | S Fuel Pump Inlet | psia - | 65.6 | 75 | 69 | 35 | - |
| P 349 B | Sus Pump Speed | rpm 10112* | - | 10155 | 10200 | 10350 | - |
| P 529 D | S Main LO2 Valve | deg - | - | ** | ** | ** | - |
| P 830 D | PU Valve | deg 27.3* | - | 29.5 | 22.5 | 27.0 | - |

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S. CODE, SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

SECRET

SECRET

| Measure- ment No. | Description | Nominal | | L/L at Liftoff | TLM After Liftoff | TLM Prior to BCO | TLM Prior to SCO | TLM Prior to VCO |
|------------------------|------------------------|---------|---------|-------------------|-------------------------|------------------------|------------------------|------------------------|
| | | Units | Values | | | | | |
| P 130 P | S Fuel Pump Disch | psia | 1000 | - | 960 | 960 | 930 | - |
| P 351 P | S LO2 Inj Man | psia | 806 | - | 810 | 850 | 800 | - |
| P 6 P | S Thrust Chamber | psia | 693* | - | 690 | 700 | 700 | - |
| P 1716 T | S Eng Environment | dgf | - | 84 | - | - | - | - |
| P 967 P | LO2 Regulator Out | psia | 886* | - | 880 | 880 | 880 | - |
| P 463 P | SCG Fuel Inj Man | psia | 845 | - | 830 | 820 | 820 | - |
| P 517 P | S Fuel Inj Man | psia | 757 | - | ** | ** | ** | - |
| <u>Vernier Engines</u> | | | | | | | | |
| P 1474 P | Vern Ctl Press Reg Out | psia | 605 | 601 | - | - | - | - |
| P 30 P | Vernier LO2 Tank | psia | 585 | - | 40 | 40 | 570 | 540 |
| P 27 P | Vernier Fuel Tank | psia | 585 | - | 100 | 630 | 640 | 540 |
| P 28 P | V1 Thrust Chamber | psia | 353/298 | - | 330 | 338 | 362 | 302 |
| P 29 P | V2 Thrust Chamber | psia | 353/298 | - | 337 | 337 | 362 | 302 |
| <u>Miscellaneous</u> | | | | | | | | |
| P 1325 T | Eng Comb Amb | dgf | - | 88 | - | - | - | - |

ALL INFORMATION CONTAINED HEREIN IS UNCLASSIFIED EXCEPT WHERE SHOWN OTHERWISE BY THE MARKING OF THIS DOCUMENT

SECRET

| Measure- ment No. | Description | Nominal Units | L/L at Liftoff | TLM After Liftoff | TLM Prior to BCO | TLM Prior to SCO | TLM Prior to VCO |
|----------------------|------------------------|------------------|-------------------|-------------------------|------------------------|------------------------|------------------------|
| P 671 T | Thrust Section Ambient | dgf | - | 78 | 74 | 86 | - |

* Value from Engine Acceptance Test Log.

** Instrumentation malfunction

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794, THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

FORM 100-1

~~SECRET~~

Page No. 17
AA 61-0189

PROPELLANT UTILIZATION

The Acoustica Propellant Utilization (PU) System performance was satisfactory. The PU valve positioned correctly in response to the error counter output voltage. The Head Suppression valve position data was not valid.

The monostable output Measurement ((U 135 X) indicated simultaneous uncovering of the LO2 and fuel sensors at Stations 2 and 6. At both stations the computer interpreted the signals as LO2 sensor only uncoverings. In both instances the system positioned the PU valve at the maximum open position until automatic computer reset. At reset, the fail-safe feature of the system positioned the PU valve at the nominal value angle until Station 3 sensor uncovering and SCO, respectively.

Sensor uncovering times and PU valve angle after positioning are shown in the following table

| <u>Station</u> | <u>LO2 * Sensor</u> | <u>Fuel * Sensor</u> | <u>PU Valve Angle</u> |
|----------------|-------------------------|--------------------------|---------------------------|
| 1 | 8.97 | 8.27 | 23.5 |
| 2 | 48.51 | 48.51 | 27.0 |
| 3 | 86.15 | 85.30 | 21.5 |
| 4 | 117.24 | 116.79 | 26.0 |
| 5 | 192.84 | 192.29 | 26.5 |
| 6 | 246.15 | 246.15 | 27.0 |

* Accuracy of times is ± 0.05 seconds.

Calculations of propellant residuals based on Head Sensing Port data indicated 755 pounds of fuel and 2055 pounds of LO2 remaining at SCO. This represents a LO2 excess of 340 pounds at SCO.

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794, THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

~~SECRET~~

~~SECRET~~

Page No. 18
AA 61-0189

The following constants were applicable for this flight:

CA 108 B Computer Serial Number 0086

PU Valve Angles

| | Calibrated Log book | |
|--------------|---------------------|--------|
| | Values | Values |
| Closed Limit | 22.0° | 22.5° |
| Nominal | 27.5° | 27.3° |
| Open Limit | 47.0° | 47.5° |

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., CHAPTER 110 AND FOR THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

FORM 8000-0

~~SECRET~~

~~SECRET~~

Page No. 19
AA 61-0189

PNEUMATIC SYSTEM

System performance was satisfactory. Telemetered data indicated that all pressurization and control functions were properly performed throughout flight.

Tank Pressurization System

Missileborne propellant tank pressures were satisfactorily maintained within respective LO2 and fuel tank pressure specifications of 23.0 to 25.5 psig and 57.0 to 62.0 psig until jettison of the Fluidgenics pressurization regulators with the booster section.

LO2 bolloff continued to maintain LO2 tank pressure at 25 to 26 psig during sustainer/vernier phase and until well after re-entry vehicle separation. Fuel tank pressure decayed from 59 psig at BCO to 40 psig at VCO, reflecting the bulkhead heat transfer rate associated with the uninsulated intermediate bulkhead.

The Pneumatic System configuration of "F" Series missiles utilizes 6 helium bottles for propellant tanks pressurization whereas only 5 are used for "E" Series missiles. The bottle was added since the operational "F" Series missile will have a shorter chilldown time and the final bottle temperature will be higher. However, since the bottles on Missile 4F were charged and cooled to nominal "E" Series R and D temperature and pressure, the expected excess stored helium was indicated at staging. Bottle pressure at that time was 1000 psia, or approximately 250 psi higher than on "E" Series flights. The bottle temperature decreased from -320°F at liftoff to -370°F at BCO.

The temperature increase effected in the helium when passing through the heat exchanger was 565°F at 5 seconds and 660°F at BCO. The maximum temperature rise of 755°F was recorded at 60 seconds when the LO2 pressurization regulator inlet temperature peaked at 403°F .

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

FORM 4000-1

~~SECRET~~

~~SECRET~~

Page No. 20
AA 61-0189

Control Pressurization System

Controls helium bottle discharge pressure data indicated that control pressure was properly maintained throughout flight. Landline measurements indicated bottle pressure and temperature of 3071 psia and 103°F at liftoff. Bottle pressure was 2920 psia at staging and normal decay occurred during vernier solo phase, reflecting a helium demand by the helium pressurized vernier engine solo propellant tanks.

Specific values from landline and telemetry data are presented on the following page.

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794, THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

FORM 41000-0

~~SECRET~~

PNEUMATIC SYSTEM TIME SLICE DATA

| <u>Measure- ment No.</u> | <u>Description</u> | <u>Units</u> | <u>Landline</u> | <u>After Liftoff</u> | <u>Prior to BCO</u> | <u>Prior to SCO</u> | <u>Prior to VCO</u> |
|------------------------------|----------------------|--------------|-----------------|--------------------------|-------------------------|-------------------------|-------------------------|
| F 1 P | LO2 Tank Helium | psia | 38.0 | 38 | 25 | 26 | 26 |
| F 3 P | Fuel Tank Helium | psia | 73.2 | 72 | 59 | 40 | 40 |
| F 246 P | B Tank He Bottles Hi | psia | 3066 | 2770 | 1050 | - | - |
| F 247 T | B Tank He Bottles | OF | - | -330 | -370 | - | - |
| F 115 T | LO2 Press Reg Inlet | OF | - | 235 | 290 | - | - |
| F 145 P | S Cd He Bd Disch | psia | 3071 | 2980 | 2920 | 2880 | 1890 |
| F 1290 T | S Cd He Botde | OF | 103 | - | - | - | - |
| F 1050 P | PCU LO2 Sensor Line | psia | 40.0 | - | - | - | - |
| F 1047 P | PCU Fuel Sensor Line | psia | 90.0* | - | - | - | - |
| F 1194 P | Facility GN2 Supply | psia | 1710 | - | - | - | - |

* Maximum value, data oscillating

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

HYDRAULIC SYSTEMS

Systems performance was satisfactory. Booster and Sustainer/Vernier System pressures were properly maintained throughout powered flight. All high and low system pressure instrumentation yielded valid data with the exception of Measurement H 130 P, Sustainer Hydraulic Pump Discharge Pressure.

Booster system hydraulic accumulator pressure reflected normal transfer from the ground booster Hydraulic Pumping Unit pressure of about 1900 psia to a missileborne level of about 3150 psia which was satisfactorily maintained until BCO.

Sustainer/Vernier System hydraulic pressure reflected normal transfer from the ground sustainer Hydraulic Pumping Unit pressure of about 1930 psia to a missileborne level of about 3020 psia which was satisfactorily maintained until SCO.

Measurement H 185 P, Sustainer Hydraulic Pump Inlet Pressure, reflected an abnormal 20 psi pressure increase to 100 psi at hydraulic pump shutdown coincident with SCO, where it remained for the remainder of telemetered data. Since the Vernier System return pressure did not reflect the increase but remained at proper levels throughout flight, the pump inlet data after SCO is considered questionable. Flight data from Missile 2F indicated the same type of failure at the same time.

After SCO, hydraulic pressure was maintained by the Vernier Solo Accumulator for 33 seconds, bottoming out at a pressure of 870 psia.

Sustainer hydraulic pump vibration measurements were included in system instrumentation. Laboratory tests have shown that the sustainer hydraulic pump case fractures under certain vibratory conditions. The four measurements, added to determine if critical levels were being approached during flight, were:

- H 426 O Sustainer Hydraulic Pump, Tachometer X-Axis
- H 427 O Sustainer Hydraulic Pump, Tachometer Y-Axis
- H 428 O Sustainer Hydraulic Pump, End X-Axis
- H 429 O Sustainer Hydraulic Pump, End Y-Axis

SECRET

Page No. 23
AA 61-0189

All four measurement yielded valid data. Measurement H 429 O consistently indicated the highest vibration levels with maximum noted values of 20 to 23 G's (RMS).

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTION 793 AND 794, THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

FORM 87-000-0

SECRET

HYDRAULIC SYSTEMS TIME SLICE DATA

| <u>Measure- ment No.</u> | <u>Description</u> | <u>Units</u> | <u>Landline</u> | <u>After Liftoff</u> | <u>Prior to BCO</u> | <u>Prior to SCO</u> | <u>Prior to VCO</u> |
|------------------------------|------------------------|--------------|-----------------|--------------------------|-------------------------|-------------------------|-------------------------|
| H 33 P | B1 Hyd Accumulator | psia | - | 3150 | 3150 | - | - |
| H 224 P | B Hyd Sys Low Press | psia | - | 86 | 90 | - | - |
| H 140 P | Sas/Vern Hyd Press | psia | - | 3020 | 3000 | 3020 | 1270 |
| H 191 P | S HI Press to Manifold | psia | - | 3050 | 3050 | 3050 | - |
| H 130 P | S Hyd Pump Disch | psia | - | * | * | * | * |
| H 185 P | S Hyd Pump Inlet | psia | - | 77 | 85 | 82 | 100 |
| H 212 P | Vernier Return | psia | - | 77 | 83 | 79 | 73 |
| H 1360 P | HPU Sustainer Return | psia | 81.0 | - | - | - | - |

* Instrumentation malfunction

SECRET

Page No. 25
AA 61-0189

MISSILE ELECTRICAL SYSTEM

System performance was satisfactory. Flight data indicated that electrical power was properly supplied to all user systems throughout flight and that all parameters remained within specification.

Measurement E 118 V, Engine Relay Box DC, was added to system instrumentation to monitor the dc voltage out of the engine relay box on a continuous telemetry channel to determine that no voltage interruptions occurred during flight. No voltage interruptions were indicated.

The following maximum and minimum values were recorded for the measurements listed below during the period from liftoff to after re-entry vehicle separation.

| <u>Measure-</u> <u>ment No.</u> | <u>Description</u> | <u>Units</u> | <u>Specification</u> | <u>Flight</u> <u>Min.</u> | <u>Flight</u> <u>Max.</u> |
|------------------------------------|---------------------------|--------------|----------------------|------------------------------|------------------------------|
| E 50 Q | 400 Cycle AC Power Supply | cps | 395 to 405 | 398.8 | 400.6 |
| E 28 V | Missile System Input | vdc | 25.2 to 30.8 | 27.3 | 28.3 |
| E 51 V | 400 Cycle AC Phase A | vac | 113 to 117 | 114.1 | 114.5 |
| E 53 V | 400 Cycle AC Phase C | vac | 113 to 117 | 114.0 | 115.0 |

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

SECRET

~~SECRET~~

Page No. 26
AA 61-0189

RANGE SAFETY COMMAND SYSTEM

Operation of the Range Safety Command System was satisfactory. Telemetered data indicated airborne received signal strength was adequate to ensure proper system operation until well beyond Nose Cone separation. The Automatic Sustainer Cutoff (ASCO) and Manual Fuel Cutoff (MFCO) signals were properly decoded by the missileborne system. Data indicated that sustainer cutoff was initiated by the Guidance System and not the ASCO signal.

The following times were obtained from the data. Signal D 1 V, RSC Cutoff Output, could only be measured with an accuracy of ± 0.1 seconds on a commutated channel monitoring this signal because the continuous channel did not function properly.

| | |
|----------------------------|-------------------|
| Sustainer Cutoff Discrete | 289.486 |
| Sustainer Cutoff Relay | 289.489 ± 0.1 |
| Automatic Sustainer Cutoff | 289.623 ± 0.1 |
| Manuel Fuel Cutoff | 331.461 ± 0.1 |

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE DEFENSE LIAISON, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

FORM 2100-2

~~SECRET~~

SECRET

Page No. 27
AA 61-0189

AZUSA SYSTEM

Operation of the Azusa System during flight was satisfactory. The telemetered air-borne receiver AGC data and the ground station receiver AGC data increased rapidly at launch but remained noisy until approximately 80 seconds due to flame effects, lobing, and multi-path reception. Thereafter AGC data were clean and adequate until well beyond nose cone separation.

The system was in the fine mode in Range at launch. Automatic Track was established at 4.55 seconds and the angle cosines were switched to the fine mode at 5.45 seconds. Intermediate Range was transmitted from 20.6 to 24.1 seconds and one ambiguity was resolved from the "L" angle cosine from 47.6 to 48.4 seconds. Data were then satisfactory until 466 seconds where all parameters needed resolution. Loss of signal occurred at 475 seconds. Data was reducible from 25 to 399 seconds.

The Automatic Data Select Function at the 7090 Computer selected Azusa data for IP information from 58.3 to 120.9 seconds and from 212.7 to 467 seconds. The following IP was provided.

| | <u>Miss Distance</u> | <u>95 % Confidence Limits</u> |
|------------|----------------------|-------------------------------------|
| Downrange | 1.57 nm Short | Major Axis 0.239 nm |
| Crossrange | 0.32 nm Right | Minor Axis 0.215 nm at 123.45° T |

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

SECRET

~~SECRET~~

Page No. 28
AA 61-0189

PENETRATION SYSTEM

A Mod I Pod, Serial Number 022, was flight tested on Atlas Missile 4F. The flight was completely successful. All of the Pod functions operated as planned.

The Baro Switch activated at 26.3 seconds providing voltage for instrumentation.

The sequence timer started at 292 seconds and supplied all the signals for fairing eject, tube unlatch and orient motor start.

The T2 signal was received from the flight programmer and initiated the canister ejection. The canister ejection velocity was approximately 10 ft/sec. The orient angle was approximately 82°.

| Event | Time |
|--------------------|-------|
| Fairing Eject | 292.6 |
| Tube Unlatch | 293.2 |
| Orient Motor Start | 294.0 |
| Canister Eject | 311.5 |

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTION 793 AND 794, THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

FORM 4100-0

~~SECRET~~

~~SECRET~~

Page No. 29
AA 61-0189

FLIGHT CONTROL SYSTEM

Performance of the Flight Control System was satisfactory. Data indicated that response to the guidance roll maneuver was satisfactory and that the pitch program was accomplished satisfactorily. All guidance discrete commands were acted upon properly and response to guidance steering commands was satisfactory. Data indicated that all programmer switch functions occurred properly. There were no missile bending mode buildups during the flight and propellant slosh during booster phase was moderate. Engine displacements at engine start were within the allowable tolerance of ± 0.6 degrees. The liftoff transient was larger than normal reaching 2.2 degrees peak displacement and a 4.8 deg/sec peak rate. This transient was comparable to that observed on Missile 16E. The staging transients and the staging sequence appeared normal. The vernier engine displacements reached 22 degrees to cause clockwise roll at approximately 47.5 seconds and moved to displacements of 7 degrees to cause counter-clockwise roll by 69.5 seconds. This unusual deflection at 69.5 seconds was comparable to that noted during the Missile 25E flight and was attributed to aerodynamic loading on the scientific passenger pods.

This was the first flight with Thor Retro-rockets closed-loop. These retro-rockets were fired simultaneously with the Atlas Retro-rockets by a separate programmer switch. Shorting of both the Atlas and the Thor Retro-rockets wiring resulted in the burnout of their respective programmer switch current limiters. The tank fragmentation signal instrumented in an open-loop configuration, occurred satisfactorily at 189.0 seconds after vernier cutoff.

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

FORM 4100-0

~~SECRET~~

INERTIAL GUIDANCE SYSTEM

Performance of the Inertial Guidance System was satisfactory. The roll maneuver and the pitch and yaw steering commands were properly generated. All discrettes were issued at the times called for by the equations. All Inertial Mode start occurred at 1604:05. 66 EST.

This was a lofted flight using Trajectory E-XII, with planned impact coordinates of 8.0760 degrees south latitude and 14.7450 degrees west longitude, a range of 4388 nautical miles. Target offsets of -0.0113 degrees latitude and +0.0078 degrees longitude were inserted in the Inertial Guidance System to compensate for nose cone parameters and vernier thrust decay.

Missile Behavior

Missile axial acceleration at sustainer cutoff was as follows:

| | <u>Nominal</u> | <u>Actual</u> |
|---------------------|----------------|---------------|
| Thrust Acceleration | 5.22 | 5.21 |
| Net Acceleration | 4.74 | 4.73 |

A comparison of the telemetered velocities and positions with those listed in Trajectory E-XII at the approximate time of guidance enable was as follows:

| <u>Function</u> | <u>Units</u> | <u>Actual</u> | <u>Nominal</u> | <u>Difference*</u> | <u>3 Sigma Limits</u> |
|-----------------|--------------|---------------|----------------|--------------------|-----------------------|
| Time** | sec | 137.8125 | 138.00 | -0.1875 | ± 6.5 |
| X | ft/sec | 9666.5 | 9666.5 | 0 | ± 70 |
| Y | ft/sec | 401.75 | 483.25 | -81.5 | ± 600 |
| Z | ft/sec | 4335.5 | 4233.0 | +102.5 | ± 900 |
| X | ft | 495,552 | 494,528 | +1024 | ± 19,500 |
| Y | ft | 56,064 | 58,304 | -2240 | ± 25,500 |

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794, THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

| <u>Function</u> | <u>Units</u> | <u>Actual</u> | <u>Nominal</u> | <u>Difference*</u> | <u>3 Sigma Limits</u> |
|-----------------|--------------|---------------|----------------|--------------------|-----------------------|
| Z | ft | 237,568 | 234,176 | +3392 | ± 28,500 |
| CEF | rad | -0.004638 | -0.00024 | -0.004398 | - |
| REF | rad | 3.983641 | 4.0156 | -0.031959 | - |

* Actual Minus Nominal

** Times Referenced to Inertial Mode Start.

Platform and Control

The roll maneuver as indicated on the azimuth resolver was executed properly during the 2 to 19 second period.

The pitch resolver came into the instrumented range at guidance enable minus 28.5 seconds and crossed over zero 22 seconds later. After the staging disturbance the resolver settled at zero at guidance enable plus 16 seconds.

All servo errors were normal and less than ± 0.8 minutes deviation.

Gyro drifts measured prior to launch were:

| | | |
|---------------|-----------|--------------|
| Gross Azimuth | -0.62°/Hr | Precountdown |
| Roll Fixed | +0.13°/Hr | Precountdown |
| Gross Pitch | +0.64°/Hr | Hangar N |

These values are consistent with previous measurements. Redundant gyro torquing currents were normal. Maximum amplitude oscillation of 67°/Hr peak to peak occurred at 230. This channel also indicated an oscillation of less than 1 cps at 26°/Hr peak to peak amplitude during the interval from internal power transfer to reset.

Gyro temperatures remained stable through the flight, with the following deviations from the buoyancy temperatures at launch:

~~SECRET~~

Page No. 32
AA 61-0189

| | | |
|--------------|-------|----------------------------|
| Roll/Azimuth | (602) | $\pm 0.45^{\circ}\text{C}$ |
| Pitch | (601) | $\pm 0.95^{\circ}\text{C}$ |

The binnacle heater measurement cycled twice from full on to off during the flight.

Accelerometer scale factors measured during the precount were as follows:

| <u>X</u> | <u>Y</u> | <u>Z</u> |
|----------|--------------|----------|
| 2.00052 | Not Measured | 1.99826 |

These values are consistent with previous measurements.

Computer

Computer operation was satisfactory. All discrettes were issued at the proper times. Computer voltages were normal. Computer temperature rose from 31°C to 37°C during the flight.

Yaw steering was normal. Missile yawed approximately 7° left with 2° right overshoot. Steering was essentially complete at guidance enable plus 38 seconds.

The data checker tests of the range tape recorded during the flight indicated that the computer operation was satisfactory. Four errors occurred and Data Bridge Correction was required at 115 seconds for approximately 2 seconds due to noise on RF No. 3.

Alignment Countdown Set

This missile was launched using the Lot III OGE. Operation of this equipment was normal up to step 6.19 of the precountdown. During this step a computer "No-Go" occurred. The computer received no inputs until 29 seconds after start. It was established that at initiation of countdown both the Standby and the ready mode relays were energized. Twenty-nine seconds after the computer test start, the system stepped normally to torque mode, de-energizing the ready mode relays and feeding the proper inputs to the computer. The system was returned to stand-by and another countdown initiated and the computer run was completed successfully. After the flight every attempt was made to

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

FORM 41000-0

~~SECRET~~

~~SECRET~~

Page No. 33
AA 61-0189

latch up this relay again and simulate the condition. This could not be accomplished. The condition is being investigated.

Accelerometer zeros were within the specified tolerances before launch, as measured with the A-CS, indicating proper operation of the zeroing loops.

| <u>Function</u> | <u>Nominal</u> | <u>Compensated Nominal</u> | <u>Measured</u> | <u>Error</u> |
|-----------------|----------------|--------------------------------|-----------------|--------------|
| X offset | 0.667 | 0.6684498 | 0.6627010 | -0.0057488 |
| X zero | 1.000 | - | Not measured* | - |
| Y zero | 1.000 | - | 0.99953856 | -0.00046144 |
| Z zero | 65.25407 | 65.19523 | 65.19701 | 0.00178 |

* X zero was not measured due to the ACS advancing to Step 14 before a reading was taken.

Instrumentation

All channels of the Analog Signal Converter operated satisfactorily. ASC temperature remained constant at 21.5°C throughout the flight.

The Digital Signal Converter performance was satisfactory.

Telemetry quality on this flight was fair. The normal drop at staging occurred and additional noise occurred on RF 3 at 115 seconds.

Four ASC channels had GD/A temperature monitoring signals mixed with them. Two of these, yaw steering and azimuth resolver, exhibited a bias of approximately 0.25 volts. The same bias was observed on Missile 32E, which also had this configuration.

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794, THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

FORM 24-20-6

~~SECRET~~

~~SECRET~~

Page No. 34
AA 61-0189

MOD III RANGE SAFETY AND INSTRUMENTATION SYSTEM

Performance of the Mod III System was satisfactory. During the minus count primary Range Safety was transferred to the Mod III System. In addition, it was the primary source for the generation of the ASCO discrete. A good IIP plot was presented to the Range Safety Officer from liftoff to approximately 382 seconds. The ASCO inhibit switch remained in the "OFF" position for the entire flight, and the ASCO discrete was generated properly at 289.397 seconds.

Telemetered data indicated satisfactory operation of the Missileborne Mod III E Beacons.

Performance of the individual subsystems was as follows:

Track Subsystem

The performance of the Track Subsystem was satisfactory. The missile was tracked off the pad in automatic monopulse mode as planned. Track lock was continuous from liftoff to 411 seconds when the limits of range tracking was reached. The operator immediately ran the track range gate back and succeeded in reacquiring the missile, tracking it for an additional 60 seconds.

During the sustainer phase the received signal strength average -55 dbm and the peak-to-peak tracking errors were 0.08 mils in azimuth and 0.05 mils in elevation.

Rate Subsystem

The performance of the Rate Subsystem was satisfactory.

From liftoff to approximately 50 seconds the received signal was noisy due to flame effects and multipath reception. Rate was locked on the missile at 9 seconds; however, due to the noisy signal the lateral rate flags were intermittent until 42 seconds. From this time, except for the usual loss of signal at staging, rate lock was continuous until 410 seconds.

During the sustainer phase the received signal strength average was -86 dbm and the lateral rate readout variation was the normal 2 bits peak-to-peak. The rate data provided the computer during powered flight was of good quality.

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE Espionage Laws, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

FORM 88000-0

~~SECRET~~

Mcd III Computer

The computer operated satisfactorily during the countdown and ensuing flight with no malfunctions observed. A simulated flight re-run was made with no deviations from the real time results.

Acceptable data for IIP calculations were received continuously from -6 seconds until switching from flight ready at 4382 seconds. The following impact point was calculated from data gathered between VCO and Retro-Rocket Firing.

| | <u>Mean Miss Distance</u> | <u>Standard Deviation</u> | <u>Deviation of the Mean</u> |
|-------------|-------------------------------|-------------------------------|----------------------------------|
| Cross Range | 0.62 NM Right | \pm 0.45 NM | \pm 0.17 NM |
| Down Range | 1.23 NM Short | \pm 0.39 NM | \pm 0.15 NM |

~~SECRET~~

Page No. 36
AA 61-0189

RE-ENTRY VEHICLE

A Mark 5 Mod 2 Re-entry Vehicle was flown on 4F and was the first re-entry vehicle of its type to be flight-tested on an Atlas.

The C-band beacon and Telemetry System operated satisfactorily until blackout. Link 255.1 was lost during blackout. This vehicle incorporated a record retransmit system and, therefore, did not have a recoverable data cassette. One apparent malfunction occurred approximately 80 seconds prior to re-entry vehicle separation. At this time the pre-arm, electrical disconnect and mechanical disconnect monitors operated. This problem area is being investigated. The physical separation monitor operated satisfactorily and at the proper time. From a quick-look basis, it appears that the re-entry vehicle test objectives were only partially satisfied.

The following is a chronology of re-entry vehicle in-flight events:

| <u>Function</u> | <u>Time</u> |
|-------------------------------------|-------------|
| Range Zero | 0 |
| Lockout Switch 2 | 65.7 |
| Lockout Switch 1 | 79.7 |
| Pre-arm (R/V Monitor) | 225.5 |
| Electrical Disconnect (R/V Monitor) | 225.5 |
| Mechanical Disconnect (R/V Monitor) | 225.5 |
| Pre-arm (ARMA Computer) | 308.7 |
| Physical Separation (R/V Monitor) | 312 |

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE SPYWARE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

FORM 8000-0

~~SECRET~~

PROPELLANT TANKING

Fuel tanking was accomplished on 18 November 1961. Flight level was obtained in the following manner. Fuel was tanked to the Level High Primary Probe plus 23 gallons at Sequence I (tanking pressure) and tanking secured. Fuel tank pressure was then increased to flight pressure, the pressure sensitive pre-valves were opened and the engine plumbing was filled. Tank pressure was then decreased to Sequence I and 33 gallons of fuel were added to return to the original level.

On 22 November 1961 the fuel level had decreased and 33 gallons of fuel were topped. This placed the fuel level 23 gallons above the Level Low Primary Probe prior to LO2 Tanking. The decrease in fuel level from 18 November to 22 November 1961 represents a level change of 102 gallons. This level decrease is too great to be attributed to a fuel density change. Since the fuel density at ignition cannot be determined, the ignition fuel weight of 76,200 pounds is based on tank volume and the 18 November fuel density of 49.88 lbs/ft³.

LO2 tanking was concluded with a successful LO2 slug transfer of 44.0 seconds duration as measured from the activation of the Topping High Probe to the activation of the 100 percent Slug Cutoff Probe. LO2 slug discharge pressure peaked at 346 psig and remained there until slug cutoff. The 100 percent slug uncovered 0.32 seconds prior to 1 Inch Motion indicating that the LO2 level at ignition was approximately 700 pounds above the 100 percent Slug Cutoff Probe.

Based on tank volume and an ignition LO2 density of 70.15 lbs/ft³ there were approximately 174,200 pounds of LO2 aboard at ignition.

Weather Data

| | <u>Fuel Tanking</u> | <u>Ignition</u> |
|-----------------------------|---------------------|---------------------|
| Ambient Temperature | 60.9°F | 73.8°F |
| Barometric Pressure | 29.930 Inches of Hg | 30.010 Inches of Hg |
| Relative Humidity | 86 Per cent | 62 Per cent |
| Wind Velocity and Direction | 3 Knots - N | 11 Knots - E-SE |
| Total Cloud Cover | 7/10 | 9/10 |

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE DEFENSE LIAISON ACT, TITLE 18, U.S.C., SECTIONS 793 AND 794, THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

TELEMETRY

Satisfactory data were obtained from the Telemetry System until well beyond powered flight. The usual dropout of the telemetry signal occurred after staging and lasted 0.5 seconds. Operation of RF No. 4 was satisfactory.

RF 1 Channel 11 temperature measurements yielded invalid data after plus 295 seconds. Channel 11 Segment 27 became noisy and below normal level from plus 295 seconds till loss of signal. Channel 11 Segment 25 became noisy and spiked below 100 per cent level from plus 296 seconds till loss of signal.

There were ~~fourteen~~ measurements that did not yield valid data throughout the flight.

| <u>Measurement</u> | <u>Description</u> | <u>Comment</u> |
|--------------------|--|--|
| A 77 A | Jettison Rail End Radial | Remained above 100 per cent after staging invalidating D I V on RF 1 Channel 6S. |
| M 177 T | V1 Thor Retro Nozzle | Below zero until plus 152 seconds, valid after 152 seconds. |
| M 180 T | V2 Thor Retro Case | Below Zero Prior to Launch. |
| A 36 A | Booster Thrust Section Longitudinal Acceleration | Failed at 0.5 seconds. |
| P 529 D | S. Main LO2 Valve | Failed at Plus 4 seconds. |
| H 130 P | S. Hyd Pump Discharge | Remained at zero. |
| P 38 P | B2 Fuel Pump Discharge | Remained at zero. |
| A 32 T | V2 Heat Shield Calorimeter | Remained at -2 per cent. |
| P 517 P | Sustainer Fuel Injection Manifold | Improper levels. |
| H 185 P | Sustainer Hydraulic Pump Inlet Pressure | Invalid after sustainer cutoff. |

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE Espionage LAWS, TITLE 18, U.S.C., SECTION 793 AND FOR THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

~~SECRET~~

Page No. 39
AA 61-0189

| <u>Measurement</u> | <u>Description</u> | <u>Comment</u> |
|--------------------|--------------------------|---|
| P 830 D | Sust PU Valve Position | Intermittent. |
| P 530 T | Sustainer LO2 Pump Inlet | Over 100 per cent. |
| P 531 C | SGG Fuel Check Valve | Bias level shifts occurred during flight. |

Missile 4F contained three Bendix Mod 7 FM Telemetry packages and one Time Transposition Telemetry package which included a Speidel Corp. Mod 003 Recorder-Reproducer System. Basic telemetry channel assignment is given in General Dynamics/Astronautics Report AE 61-0123-04.

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., CHAPTER 110 AND FOR THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

FORM 1000-7

~~SECRET~~

~~SECRET~~

Page No. 40
AA 61-0189

LANDLINE INSTRUMENTATION

The Landline Instrumentation System provided satisfactory data until liftoff.

Difficulty was encountered in obtaining accurate sequence data from the EA records as the records were not switched to fast time until one second prior to liftoff. The Brown records also were not switched until one second prior to liftoff.

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

FORM 41000-0

~~SECRET~~

CONCLUSIONS AND RECOMMENDATIONS

Conclusions

1. The flight was successful.
2. The re-entry vehicle telemetry playback transmitter signal was not received after blackout during re-entry.

Recommendations

1. Review pre-flight re-entry vehicle tests, flight data, and dynamic environment of lofted trajectory for possible explanation of loss of post blackout playback signal from the re-entry vehicle.

COUNTDOWN TIME VERSUS EVENTS

This test was scheduled for a 150 minute countdown and started at 1230 EST as planned. There were four holds totaling 64 minutes which resulted in a 214 minute countdown. These holds were as follows:

1. At -70 minutes (1430 EST), for 40 minutes, to remove and secure the service tower and for an apparent Guidance System problem. Service tower removal had been delayed in order to replace the jettison plug on Scientific Passenger Pod Serial No. 22 which would not properly mate with the connector. The jettison plug replacement was completed at -71 minutes (1349 EST). At 1405 EST the hold was extended in order to evaluate a possible Guidance computer problem. The Guidance System was reported "Go" at 1429 EST and the countdown was resumed at -70 minutes at 1430 EST.
2. At -45 minutes (1455 EST), for 15 minutes, to continue the investigation of the Guidance problem. The cause of the Guidance problem, improper mode sequencing, could not be determined and it was decided to continue the countdown with this condition existing. The countdown was resumed at -45 minutes at 1510 EST.
3. At -35 minutes (1520 EST), for 7 minutes, due to malfunction of a re-entry vehicle accelerometer. It was decided to launch without obtaining this accelerometer data and the countdown was resumed at -35 minutes at 1527 EST.
4. At -3 minutes 30 seconds (1558.30 EST), for approximately 90 seconds, to determine the status of the Azusa System. The Mark II Ground Station was unable to lock-on the transponder after it was turned on at -13 minutes (1549 EST). It was decided to launch without Azusa and the countdown was resumed at -3 minutes 30 seconds at 1600 EST. There were no further holds required.

The following notations were made by an observer in the blockhouse.

| <u>EST</u> | <u>Countdown Time</u> | <u>Countdown Procedure</u> | <u>Event</u> |
|------------|-----------------------|----------------------------|---|
| 1228 | T-152 | | Jettison Plug On Scientific Passenger Pod Serial No. 22 Will Not Mate With Connector. |

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

FORM 4200-2

~~CONFIDENTIAL~~

| <u>EST</u> | <u>Countdown Time</u> | <u>Countdown Procedure</u> | <u>Event</u> |
|------------|-----------------------|----------------------------|---|
| 1230 | T-150 | T-150 | Countdown Started. |
| | | T-150 | Propellant Utilization Sensor Response Checks Started. |
| | | T-150 | Re-entry Vehicle Telemetry and Beacon To "External". |
| 1234 | T-146 | | Propellant Utilization Sensor Response Checks Completed Satisfactorily. |
| 1240 | T-140 | T-140 | GAP Test Preparations Started. |
| 1243 | T-137 | | Jettison Plug Will Be Cut Off and Replaced. |
| 1245 | T-135 | | AIG Telemetry Check Completed. |
| 1247 | T-133 | T-134 | GAP Test Started. |
| 1248 | T-132 | T-130 | Re-entry Vehicle Telemetry and Beacon To "Internal". |
| 1257 | T-123 | | GAP Test Completed Satisfactorily. |
| 1259 | T-121 | T-131 | Telemetry Internal Battery Voltage Check Completed Satisfactorily. |
| 1301 | T-119 | T-120 | Range Safety Command Tests Started. |
| 1309 | T-111 | | Range Safety Command Tests Completed Satisfactorily. |
| 1310 | T-110 | T-110 | Electrical Connection of Red Destruct Box Started. |
| 1317 | T-103 | | Electrical Connection of Red Destruct Box Completed. |
| | | T-110 | Electrical Connection of Retro-rockets Started. |

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

~~CONFIDENTIAL~~

Page No. 44
AA 61-0189

| <u>EST</u> | <u>Countdown Time</u> | <u>Countdown Procedure</u> | <u>Event</u> |
|------------|---------------------------|--------------------------------|---|
| 1319 | T-101 | | Electrical Connection of Retro-rockets Completed. |
| 1323 | T-97 | | Measurement S 223 D Is Reading Zero. |
| 1327 | T-93 | T-105 | Guidance Accelerometer Measurement Started. |
| 1330 | T-90 | T-90 | Flight Control Systems Test Started. Service Tower Removal and Securing Delayed For Anticipated Hold At -70 Minutes. |
| 1335 | T-85 | T-85 | Helium Pressure Storage Preparation Started. |
| 1338 | T-82 | | AIGS Landlines May Be Removed. Estimate 15 Minutes To Replace Scientific Passenger Pod Plug. |
| 1341 | T-79 | | Flight Control Systems Test Completed. |
| 1346 | T-74 | | Will Hold At -70 Minutes For Estimated 15 Minutes. |
| 1349 | T-71 | | Scientific Passenger Pod Plug Work Completed. |
| 1350 | T-70H | | Holding to Remove Service Tower From Test Stand. |
| 1353 | | | Raising Service Tower Floors. |
| 1400 | | | Measurement S 223 D Is Operating Properly. |
| 1402 | | T-90 | Service Tower Removal Started. |

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

FORM 81200-0

~~CONFIDENTIAL~~

| <u>EST</u> | <u>Countdown Time</u> | <u>Countdown Procedure</u> | <u>Event</u> |
|------------|-----------------------|----------------------------|---|
| 1405 | | | Hold Extended Additional 10 Minutes To Evaluate Possible Guidance Computer Problem. Service Tower Will Be Held On Transfer Table Until Problem Is Resolved. |
| 1413 | | | Hold Extended Additional 15 Minutes For Guidance. |
| 1429 | | | Guidance Is "Go". |
| 1430 | T-70 | | Countdown Resumed. |
| 1435 | T-65 | T-65 | Landline Electrical Calibrations Started. |
| | | T-65 | Mod III E Beacon Checks Started. |
| 1443 | T-57 | | Will Attempt To Duplicate Guidance Problem - Personnel Dispatched To Transfer Room. |
| 1449 | T-51 | | Landline Electrical Calibrations Completed. T-50 Minute AIG Computer Check Will Be Delayed Until Completion of Guidance Investigation. |
| 1453 | T-47 | | Will Hold At -45 Minutes For Guidance. |
| 1455 | T-45H | | Holding For Guidance Problem - Estimate 10 Minute Hold Duration. |
| 1505 | | | Extend Hold Additional 5 Minutes. Will Not Continue Problem Investigation But Will Perform -105 Minute System Countdown Test. |
| 1510 | T-45 | | Countdown Resumed. |
| | | T-45 | LO2 Tanking Preparations Started. |

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

FORM 11500-0

CONFIDENTIAL

| <u>EST</u> | <u>Countdown Time</u> | <u>Countdown Procedure</u> | <u>Event</u> |
|------------|-----------------------|----------------------------|---|
| 1517 | T-38 | T-40 | AIG Computer and Programmer Check Started. |
| 1518 | T-37 | | Guidance Status "Go". |
| 1519 | T-36 | | LO2 System Ready For Tanking. |
| 1520 | T-35H | | Holding For Re-entry Vehicle Accelerometer Problem. |
| 1525 | | | AIG Computer and Programmer Check Completed Satisfactorily. |
| 1526 | | | Status Check - All Reports "Go". |
| 1527 | T-35 | | Countdown Resumed. |
| | | T-35 | Autopilot System Final Check Started. |
| | | T-35 | LO2 Tanking Started. |
| 1534 | T-28 | | Range Forecasts Clear Launch Area. |
| 1539 | T-23 | T-23 | Asusa Check Started. |
| 1540 | T-22 | T-22 | Range Safety Command Final Test Started. |
| 1541 | T-21 | | Five Glitches Observed On 95 Per cent Fuel Primary EA Pen. |
| 1542 | T-20 | T-20 | Telemetry Final Warmup Started. |
| | | T-20 | Re-entry Vehicle Beacon On External Power. |
| | | T-20 | Scientific Passenger Pod No. 3 Telemetry Warmup Started. |
| 1544 | T-18 | T-18 | AIG Computer Check Started. |
| | | T-35 | Holddown Hooks Retracted. |

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

~~CONFIDENTIAL~~

Page No. 47
AA 61-0189

| <u>EST</u> | <u>Countdown Time</u> | <u>Countdown Procedure</u> | <u>Event</u> |
|------------|-----------------------|----------------------------|--|
| 1548 | T-14 | | Autopilot System Final Check Completed. |
| 1549 | T-13 | | Asusa Ground Station Unable To Lock on Signal. |
| | T-12 | | AIG Computer Check Completed Satisfactorily. |
| 1550 | | T-12 | Re-entry Vehicle Telemetry On "External". |
| 1552 | T-10 | T-10 | Telemetry/Range Safety Command AGC Check Started. |
| | | T-10 | Final Propellant Utilization Check Started. |
| 1553 | T-9 | | Final Propellant Utilization Check Completed Satisfactorily. |
| | | | Telemetry/Range Safety Command AGC Check Completed Satisfactorily. |
| 1555 | T-7 | T-7 | Forecast Final Range Clearance From AMR. |
| 1556 | T-6 | T-6 | Scientific Passenger Pod No. 3 To "Internal". |
| 1557 | T-5 | T-5 | All Communications Switch to Channel 1. |
| | T-4:36 | | Asusa Reported "No-Go" By AMR. |
| | T-4:30 | T-4:30 | Squibs Disarm Switch to "Off". |
| | T-3:50 | T-3:50 | Status Check - All Reports "Go" Except Asusa "No-Go". |
| 1558:30 | T-3:30H | | Holding To Evaluate Asusa System Status. |
| 1600 | T-3:30 | | Countdown Resumed - Will Proceed With Asusa "No-Go". |

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

~~CONFIDENTIAL~~

~~CONFIDENTIAL~~

Page No. 48
AA 61-0189

| <u>EST</u> | <u>Countdown Time</u> | <u>Countdown Procedure</u> | <u>Event</u> |
|------------|-----------------------|----------------------------|--|
| | | T-3:30 | Telemetry to "Internal". |
| 1601 | T-3:00 | T-3:00 | Timer Off - Ready Switch to "Ready". |
| 1602 | T-2:45 | T-2:45 | Shutdown Power Switch to "Arm". |
| 1602 | T-2:15 | T-2:15 | Re-entry Vehicle Beacon and Telemetry To "Internal". |
| 1602 | T-2:05 | T-2:05 | Commands to "Internal". |
| 1603 | T-2:00 | T-2:00 | Re-entry Vehicle to "Ready". |
| 1603 | T-1:55 | T-1:55 | Autopilot to "Arm". |
| 1603 | T-1:50 | T-1:50 | Turning Water Systems "On". |
| 1603 | T-1:45 | T-1:45 | Commands to "Arm". |
| 1603 | T-1:40 | T-1:40 | Range Ready Switch "On". |
| 1603 | T-1:35H | T-1:35 | T-1 Minute 35 Seconds and Holding Momentarily. |
| | | T-1:35 | All Pre-start Lights Are Green. |
| | | T-1:35 | Slug Start. |
| 1603 | T-1:35 | T-1:35 | T-1 Minute 35 Seconds And Counting. |
| | | T-1:35 | Starting Flight Pressurisation. |
| 1603 | T-1:15 | T-1:15 | Autopilot Programmer Reset. |
| 1603 | T-1:10 | T-1:10 | Missile to Internal Power. |
| 1603 | T-1:05 | T-1:05 | Missile Helium to "Internal". |
| 1604 | T-0:60H | T-0:60 | T-60 Seconds And Holding Momentarily. |
| | | | Slug Complete. |

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

FORM 61000-0

~~CONFIDENTIAL~~

CONFIDENTIAL

Page No. 49
AA 61-0189

| <u>EST</u> | <u>Countdown Time</u> | <u>Countdown Procedure</u> | <u>Event</u> |
|------------|-----------------------|----------------------------|--|
| 1604 | T-0:60 | T-0:60 | T-60 Seconds And Counting. |
| 1604 | T-0:55 | T-0:55 | Water Full Flow. |
| 1604 | T-0:50 | T-0:50 | Status Check - All Reports "Go". |
| 1604 | T-0:30 | T-0:30 | Close LO2 Ground Fill and Drain Valve. |
| | | T-0:30 | All Launch Commit Lights Are Green. |
| 1604 | T-0:05H | T-0:05 | T-5 Seconds and Holding Momentarily. |
| | | T-0:05 | Commit Armed Light "On". |
| | | T-0:05 | All Recorders To "Fast". |
| | T-0:05 | T-0:05 | T-5 Seconds and Counting. |
| 1604:11 | | | Range Zero. |

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

CONFIDENTIAL

~~CONFIDENTIAL~~

Page No. 50
AA 61-0189

MISSILE CONFIGURATION

Airframe

"F" Series Airframe with no insulation bulkhead. Thor Retro-Rockets were installed in the vernier engine fairings. The missile 4F Airframe is essentially the same as "E" Series versions with two significant modifications.

A structural provision for one additional helium storage sphere has been incorporated in the booster section. Missile 4F was manufactured without the non-structural bulkhead and insulation pad to improve the overall missile reliability.

Azusa System

A type B-1A coherent carrier transponder operated in conjunction with the Mark II Ground Station. An elliptical horn antenna was mounted on the tripod boom in Missile Quad IV.

Electrical System

Missile Electrical power was supplied by a remotely activated, primary-type, Eagle-Picher main missile battery and Leland rotary inverter. Vernier Engine No. 2 had an unwrapped electrical harness with isolation resistors in the wiring to the servo valve.

Flight Control System

The square canister configuration with forward rate gyro canister containing pitch and yaw rate gyros was flown on Missile 4F. This was the second flight using the 27-41002-855 Gyro Canister which incorporated the Phase Rotation Detector System in addition to the Spin Motor Rotation Detector (SMRD) System (previously flown on Missile 32E). This was the sixth flight using the 27-45045-5 Forward Rate Gyro Canister (previously flown on Missiles 2F, 25E, 26E, 30E, 32E) and the fourth flight using the 27-41000-831 "Transistors" Servo Canister (previously flown on Missiles 25E, 30E, and 32E). This was the second flight using the 27-41001-933 Programmer Canister (previously flown on Missile 2F).

Guidance System

An ARMA Lot IV Missile Guidance Set (MGS) was flown on Missile 4F. Lot III Ground Equipment was used for preflight checkout of the MGS.

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

~~CONFIDENTIAL~~

~~CONFIDENTIAL~~

Page No. 51
AA 61-0189

Hydraulic System

The Hydraulic System is comprised of independent booster, sustainer/vernier, and vernier-solo sub-systems. These provide the power necessary to gimbal the thrust chambers during flight. Minor components such as flow limiters, relief valves, disconnects and associated plumbing are used in each system. The vernier-solo system incorporates an accumulator type hydraulic power supply.

Impact Predictors

Asusa System and Mod III Range Safety and Instrumentation System were utilized for impact prediction purposes.

Pneumatic System

An additional shrouded tank-pressurization helium storage sphere (or bottle) will be carried aboard Series F missiles. The additional sphere is required because of the short helium loading time in the Series F operational count-down. The 6 minute loading interval does not allow the helium to be chilled sufficiently by the liquid nitrogen shroud to store the required amount of helium in the five spheres used with Series E missiles. The additional bottle will be located in the Quad I and II area of the booster section. An AiResearch Series F boiloff valve was flown. Fluidgenics regulators were used to control pressures in the fuel and LO2 tanks.

Propellant Utilization System

The Acoustica Propellant Utilization System was utilized on this missile and is essentially the same as the system flown on Missiles 26E and on. This system uses a 400 cps signal for excitation of the PU valve position feedback transducer and a 5-card computer,

Propulsion System

Rocketdyne MA-3 Liquid Propulsion Engine System was flown.

Range Safety Command System

The standard system employed two ARW-62 Receivers, a power and signal control unit, arming switch, and destruct package. System electrical power was supplied by two manually-activated, secondary-type, Yardney batteries which were contained within a single canister.

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

~~CONFIDENTIAL~~

Telemetry

PAM/FM/FM System was comprised of four telemetry packages, three Bendix R and D telemetry packages and a one time transposition telemetry package which included a Speidel Corp. Recorder Reproducer System. One accessory package was carried to furnish transducer excitation and signal conditioning circuits, two diplexers, a ring coupler, and two cavity-type antennas.

Four airframe telemetry links were operational at 227.7, 229.9, 232.4 and 235.5 mc. System electrical power was supplied by three remotely-activated, primary-type, Eagle-Picher batteries.

Mod III Range Safety and Instrumentation System

The Missileborne Mod III E Instrumentation Beacon System operated in conjunction with the Mod III Ground Station. The missileborne antenna was mounted on the tripod boom in missile Quad IV.

Propellant Tanking

Astronautics "E" Series Propellant Tanking System incorporating four ultrasonic fuel sensors, four LO2/GO2 detectors, a Propellant Loading Control Unit (PLCU) in the blockhouse, and 200-400 gallon LO2 slug.

Re-entry Vehicle

A Mark 5, Mod 2 Re-entry Vehicle was flown with special adapter and a ballasted transition section incorporated to simulate weight of the Mark 4 Re-entry Vehicle. The re-entry vehicle carried two telemetry links, a Sandia simulated warhead and a playback recorder but no data cassette or recovery aids. The re-entry vehicle also carried a C-Band radar beacon and a one-pound SOFAR bomb.

Penetration System

This was the second "F" Series flight using the Mod I pod (previously flown on Missiles 18E, 21E, 90D and 2F). The pod consisted of a base structure; one 12-inch diameter launch tube; safety, arming and timing system; instrumentation; and a protective aerodynamic fairing. The pod electrical and instrumentation systems were powered by a secondary-type battery contained within the pod. The pod was mounted in Missile Quad II with its center line 31 degrees from the X axis of the missile.

~~CONFIDENTIAL~~

Page No. 53
AA 61-0189

Scientific Passenger Pods

SP Pod No. 3 was carried for 8 assigned experiments on geophysical studies.

SP Pod No. 22 was carried to obtain empirical data on fuel core heating rates for bodies of a given configuration and material during re-entry.

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

FORM 8880-10

~~CONFIDENTIAL~~

~~CONFIDENTIAL~~

Page No. 54
AA 61-0189

HISTORY OF SM-65F MISSILE NO. 4F

Atlas Missile 4F arrived at AMR by air on 12 August 1961. Transfer from the IOC trailer to the R and D trailer was completed and the missile was placed in the south bay of Hangar "J". On 14 August the missile was moved to Hangar "K" for MAPCHE Testing. Missile weighing was completed on 5 October, transfer to Complex 11 and erection were accomplished on 6 October. Pre-flight testing was accomplished in accordance with planning documented in Report AA 61-0102, Flight Test Directive, Atlas Missile 4F.

Significant events concerning Missile 4F from arrival at AMR to launch are delineated below:

| <u>Date</u> | <u>Event</u> |
|------------------|---|
| 23 October 1961 | Successful Propellant Tanking. |
| 13 November 1961 | Unsatisfactory Flight Acceptance Composite Test (due to problems with Autopilot, Guidance and Telemetry). |
| 18 November 1961 | Satisfactory FAC Test. |
| 25 November 1961 | Flight. |

Significant difficulties are presented by system below:

Landline Instrumentation

No significant problems were encountered.

Missile Electrical

IR No. 679499 written to replace diodes in inverter (CR-2). Results of the MAPCHE missile electrical test were used to test inverter after diode change.

Range Safety Command

No significant problems were encountered.

Azusa

IR No. 679455 written against Azusa Aljax broken at waveguide near V1 engine. Aljax was repaired using existing connector and new inter-seal.

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

~~CONFIDENTIAL~~

~~CONFIDENTIAL~~

Page No. 55
AA 61-0189

TVA A32684 Thor-Retro Rockets squib check-out was corrected due to a wrong callout.

Azusa transponder installed was found to be "NO GO" on missile FACT, with evidence of loss of phase lock or carrier frequency shift. The canister was replaced with same results. Antenna coupler installed and radiating horn directed to ground station indicated satisfactory results. Although possibility of multi-path interference existed, this transponder was also replaced.

During pre-count checks flight transponder check was satisfactory. During normal countdown operations, transponder was found to be "NO GO" prior to and at liftoff. Data Reports indicated later lock-in during launch plus time.

Telemetry

Accessory package circuits for BLIP module concerning Measurement D 1 V were found to have capacitor polarity reversal resulting in loss of signal and bias on channel. The capacitor was correctly installed.

Excessive operational problems were encountered with Measurement P 531 O, and A 36 A transducers due to sensitivity to ground external power and transducer failures. Transducer was replaced and Measurement A 36 A failed again during flight.

Short on Channel 2-4 circuit in accessory package causing component failure of ARMA M. G. S. This item was corrected.

Transducer failure on Measurements H 185 P, H 212 P, and H 224 P due to evident over-pressure prior to or after arrival at AMR. The transducer was replaced.

Incorrect weld joint used on Measurement A 32 T resulted in damage during functional check. This was corrected. A good deal of difficulty was encountered in getting Measurement P 830 D to work properly.

Flight Control

Upon applying power to the Autopilot System, it was noted that the programmer zero light was not on but all other high power switch lights were on. Power was turned off and back on and the programmer light was present with no other lights. When A/P power was turned back on the programmer would run only at X10. Since nothing was done to remedy this problem because it disappeared by itself, the X10 wires going to the programmer were cut at the programmer to prevent possible failure in flight.

During rework of ADF pod wiring an open solder joint was found in plug 305U31P1. This solder joint was repaired.

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANINGS OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

FORM 41500-0

~~CONFIDENTIAL~~

~~CONFIDENTIAL~~

Page No. 56
AA 61-0189

During the plus time of the FACT, it was noted that Switch No. 17 of the A/P programmer had an output which resembled the timing pulse. This indicated that 28 V was absent from the control diode. The programmer was replaced.

Mod III E Instrumentation Beacon

During the first FACT on 11-13-61, three problems were found. P 51, on the back of the console, was loose, and plug 304U1P1 pin D on the rate beacon was bent. The harness was IR'd (#650380) and dispositioned to straighten connector and remate; the rate beacon was removed and replaced with S/N 20 CG. The third problem was that the MIBITS equipment 14th pulse was adjusted out. This was readjusted correcting the problem.

Water was found in Umbilical 600U5 on 11-15-61 and was purged.

During the second FACT on 11-18-61, three problems were encountered. P 4, which is not properly wired causing low meter readings, was plugged in the MIBITS equipment. This was removed correcting the problem. The second problem was that Pin F 304U1P2 was intermittent. The plug was removed, the pin straightened, and the plug remated correcting the problem. The third problem was low power return from both beacons. A piece of tin foil was found in the coupler which was removed, correcting the problem.

Hydraulics

During MPACHE testing in the Hangar, V-2 engine developed a leak at the yaw gimbal shaft seal bleed port. After erection, V1 developed the same leak and both engines were subsequently replaced. Replacement engines contained the leather back-up rings. There was slight seepage from both new engines, but was well within 5 drops/5 minute specification.

All Clemco vernier actuators were replaced with reworked Clemco actuators, after receipt of missile at AMR. V2 yaw actuator failed during MAPCHE testing in the hangar, and was replaced.

The Royal Jet Hydraulic Unit was received at AMR with two outstanding IR's attached. Unit was rejected at AMR due to lack of evidence that cleanliness had been maintained on unit during removal and transportation to AMR. The hydraulic oil and filters were changed and fluid circulated using internal filters and external filter banks. The fluid was drained again and reservoir flushed with alcohol. After refilling unit the fluid was again circulated several hours before acceptable samples were obtained to support testing.

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

FORM APPROX-2

~~CONFIDENTIAL~~

CONFIDENTIAL

Page No. 57
AA 61-0189

The airborne sustainer hydraulic pump was changed due to leakage from vendors outlet pressure fitting.

V1 actuator hydraulic return line required replacing due to a broken "B" nut. Evidence indicated over-torque as its cause.

Propellant Utilization

No significant problems were encountered.

Propulsion

A major problem resulted from cleanliness not being maintained in the LO2 system. The San Diego torque paint on plugs of the following ducts was broken:

B-1 LO2 low pressure duct between staging disconnect and A/B fill and drain valve.

B-2 LO2 low pressure duct from staging disconnect to B-2 pump inlet.

B-2 low pressure duct, first section above staging disconnect.

These ducts were removed and sent to the lab for solvent extraction tests. The tests showed the ducts not to be contaminated. They were cleaned and replaced.

A major problem involved replacing the fuel staging valves because the flow fairing on the rear of the valve poppet came loose during a San Diego pet test.

Another problem was the replacement of the vernier fuel flex supply line because of a fatigue pet test failure in San Diego.

The pre valve bellows shields were replaced because they were not per B/P, which calls for fiberglass and the ones installed were asbestos.

On X-1 day, while inspecting the vernier engines, it was found that the V-2 flex conduit interfered with the vernier LO2 supply line. The AN 743-13 bracket on the clamshell was repositioned eliminating the interference.

Complex Mechanical

Prior to missile tanking tests, PCU checkout revealed a burned out 40940 RF filter to PCU valve No. 20. IR #679420 was written to replace this filter. Because of a previous filter failure, it was decided to replace all existing filters as parts became available. Failure of these filters have occurred on Complex 11 only and seem to be traced with excessive spraying of the PCU with water during a water test in February 1961. Failure of any of these filters can cause serious pressurization control problems.

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

FORM 89-10-1

CONFIDENTIAL

~~CONFIDENTIAL~~

Page No. 58
AA 61-0189

Complex Electrical

Upon rework of the Airesearch boil-off valve it was discovered that the feed thru connector required for probe installation had #20 sized pins while the wire from the LO2 probes was #16 AWG. Installation was IR'd to remove 9 of 19 strands to allow #16 gage wire to be installed in #20 pins.

The R/F filter on valve #20 of the PCU burned out. Due to moisture present all filters were IR'd and replacements were ordered. Filters on valves 20, 22, 24, and 25 have been replaced.

Umbilical 600U7 was found to be internally shorted on several pins.

During installation of the protection rubber guard on 600P12, moisture was found in the connector. An EO was written to drill drain holes in mounting bracket.

The fuel probe installed in the missile did not agree with available paper. P/C 27-72268-801B did not require a quick disconnect, but the disconnect was installed. Probe was reidentified to correct problem.

During LO2 Tanking (10-23-61) two problems occurred:

Operational power light could only be turned on with test position key. This was corrected by correcting wiring at MAPCHE hydraulic console.

There was no 95% indication at the LO2 console and pumps LA and LB did not turn off. This problem was caused by an incorrect cross-over setting in the PLCU cabinet due to a faulty test box (EWR 31268). The cross-over points were re-set and a set of K30 (LO2 low topping) contacts were installed in the LA-LB pump circuitry to provide secondary pump cut-off.

The circuit breaker on the prop. valve heater panel was broken. This was replaced per IR #650865.

Propellant Loading

No significant problems were encountered.

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

~~CONFIDENTIAL~~

CONFIDENTIAL

Page No. 59
AA 61-0189

Re-entry Vehicle

Significant pre-flight events:

| <u>Event</u> | <u>Date</u> |
|---|------------------|
| Mark 5 Mod 2-2 arrived at AMR. | 2 August 1961 |
| Final systems test accomplished. | 6 November 1961 |
| Re-entry vehicle accepted for flight by Air Force | 15 November 1961 |
| Re-entry vehicle mated to Atlas 4F | 20 November 1961 |

Airframe

Considerable rework was required on pod cooling ducts received for pod cooling modifications due to manufacturing errors and/or deviation from B/P specs.

Pneumatics

After Fuel Tanking Test Stage II pressure, fuel was observed leaking from 204U5J1-1, Acoustica Plug Boss. A Gasket was replaced after detanking. This boss again leaked after readiness tanking; however, leakage was stopped by torquing the nut per B/P specification.

Penetration

No significant problems were encountered.

Scientific Passenger Pods (SPP)

During launch precount, it was found that the plug on the squib cable (PB 5493-223-1) which mates with the connector on the conax valve were both female connectors. The cable plug was removed and a male connector added.

Inertial Guidance

On 22 August 1961 commenced Missile 4F MGS check out using CTP-40. Could not turn on ASC. ASC S/N 020 was replaced with ASC S/N 7150013.

On 12 and 13 October 1961 when attempting to start the airborne computer via MAPCHE, it was noticed that after completion of the computer drawer self-

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

FORM 89-10-6

CONFIDENTIAL

~~CONFIDENTIAL~~

Page No. 60
AA 61-0189

check, the computer did not start. Checks revealed that there was no 28 vdc at TB 29-1. Investigation revealed a wiring error in ECP-35 Drawer 1A2A1. The wiring error was corrected and the diodes which burned out were replaced due to this error. Results were then satisfactory. MAPCHE Checkout was conducted satisfactorily.

Three computer problems were run before supporting MAPCHE. A digital "NO-GO" was obtained on two Flight Board problems and one digital "NO-GO" was obtained on the IG Board problem. Commenced "NO-GO" indication investigation.

On 17 and 19 October 1961 ran four computer problems through the Flight Board. All were "GO's". Amp output was noticed when the system was first turned on. When the system warmed up, the magnetic amp output returned to normal. A load channel was suspected in the ASC. ASC S/N 7150013 was replaced with ASC S/N 7150047.

On 20 and 24 October 1961 the new ASC S/N 7150047 exhibited the same symptoms as the old ASC. When a computer problem was initiated, ASC Channels 11 and 18 would increase in steps as the discretes occurred. Pod wiring was checked and no discrepancies were found. Umbilical cable was found to be defective and was replaced.

On 13 November 1961 completed FAC Test. Computer failed during the two hold countdown problems, and Channel 27 of the ASC (Pitch Steering Resolver) read zero output even during gimbal travel. Z Accelerometer Scale Storage was out of tolerance.

Replaced Computer S/N 7230125 and ASC S/N 7150047 with Computer S/N 7230021 and ASC S/N 7150049. After replacing components, four computer problems were run with all "GO" results. The new ASC exhibited the same symptoms; no output from Channel 27. Investigation of this problem showed telemetry cable 302J6 was shorting the channel to ground. Repaired same, thereby rectifying the ASC problem.

On 17 November 1961 supported Integrated Test and obtained a YSS "NO-GO". Reran the problem and received two "GO's" and another "NO-GO". Checked the YSS amplifier for proper adjustment. The Z Scale Storage problem was traced to a slipping clutch on motor R10. The motor was replaced.

On 18 November 1961 conducted FAC Test, with system in a "GO" configuration. A YSS "NO-GO" indication was obtained during the GAP Test. It was found that the "NO-GO" logic was not giving a computer "NO-GO" indication when it occurs. The telemetry and sanborn runs were analysed and found the YSS levels were within tolerance. In checking the YSS amplifier, it was found to be adjusted too high.

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTION 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

~~CONFIDENTIAL~~

FORM 487-60

CONFIDENTIAL

Page No. 61
AA 61-0189

Re-adjusted to the proper value and ran integrated runs with A/P. Resulting in a "GO" condition.

On 20 November 1961 completed X-1 Day System Checks (CTP-37). It was discovered that when the SECO discrete button was depressed on the A/P monitor panel, during a GAP Test, the IAI Computer drawer sensed this as a premature SECO time and YSS "NO-GO" indication was generated, as the YSS level was not yet set up for SECO sample.

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES AND THE SECURITY OF THE UNITED STATES, TITLE 18, U.S.C., SECTIONS 793 AND 794, THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

FORM 88-6

CONFIDENTIAL

Page No. 1a
AA 61-0189

APPENDIX

~~CONFIDENTIAL~~

Page No. 2a
AA 61-0189

FLUID CHEMICAL ANALYSIS

| | <u>Unit</u> | <u>Sample</u> | <u>Specification</u> |
|----------------------|-------------|---------------|----------------------|
| <u>Liquid Oxygen</u> | | | |
| Purity | Per cent | 99.55 | 99.2 Minimum |
| Hydrocarbons | | | 75.0 Total Maximum |
| As Methane | ppm by vol. | 26 | 1.5 Maximum |
| As Acetylene | ppm by vol. | None | |
| Particle Count | | | 2 Maximum |
| 350 - 500 | Microns | 0 | 0 |
| 500 + | Microns | 0 | 0 |
| Fibers, 25 x 6000 | Microns | 0 | 2.5 Maximum |
| Total Solids | Microns | 0 | |

This item is within specifications.

Gaseous Helium

| | | | |
|--------------|-------------|--------|--------------------|
| Purity | Per cent | 99.95+ | 99.95 Minimum |
| Hydrocarbons | | | 75.0 Total Maximum |
| As Methane | ppm by vol. | None | 1.5 Maximum |
| As Acetylene | ppm by vol. | None | |

This item is within specifications.

Gaseous Nitrogen

| | | | |
|--------------|-------------|-------|--------------------|
| Purity | Per cent | 99.85 | 99.5 Minimum |
| Hydrocarbons | | | 75.0 Total Maximum |
| As Methane | ppm by vol. | None | 1.5 Maximum |
| As Acetylene | ppm by vol. | None | |

This item is within specifications.

Lubricating Oil

| | | | |
|--------------------|-------------|------|---|
| Viscosity at 100°F | Centistokes | 12.7 | 11.0 Minimum |
| Viscosity at 210°F | Centistokes | 3.3 | 3.0 Minimum |
| Flash Point | °F | 440 | 400.0 Minimum |
| Viscosity Index | | 149 | 80.0 Minimum |
| Appearance | | Pass | Uniform. No sediment or suspended matter. |

This item is within specifications.

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

~~CONFIDENTIAL~~

FORM 8000-6

| | <u>Unit</u> | <u>Sample</u> | <u>Specification</u> |
|--------------------------|-------------|---------------|----------------------|
| <u>Trichloroethylene</u> | | | |
| Appearance | | Pass | Clear |
| Color | | Pass | Not dyed. |
| Odor | | Pass | Characteristic |
| Specific Gravity | @68°/68°F | 1.470 | 1.454 to 1.476 |
| Distillation | | | |
| Initial | °C | 189 | 187.7 Minimum |
| Dry Point | °C | 189 | 190.4 Maximum |
| Water Content | @14.0°F | Pass | Cloudless |
| Non-volatile | Per cent | 0.001 | .002 Maximum |
| Hydrocarbons | Per cent | 0.0002 | |

This item is within specifications.

Fuel, RP-1

| | | | |
|-------------------|----------|------|----------------------|
| Initial Boiling | °F | 364 | Report |
| 10 Per cent | °F | 394 | 365 - 410 |
| 50 Per cent | °F | 421 | Report |
| 90 Per cent | °F | 458 | Report |
| End Point | °F | 486 | 525 Maximum |
| Residue | Per cent | 0.9 | 1.5 Maximum |
| Loss | Per cent | 0.6 | 1.5 Maximum |
| Flash Point | °F | 142 | 110 Minimum |
| Gravity | °API | 43.5 | 42.0 - 45.0 |
| Particle Count | | | |
| 350 - 500 | Microns | 0 | 20 per liter maximum |
| 500 / | Microns | 0 | 0 |
| Fibers, 25 x 6000 | Microns | 0 | 0 |
| Inert Solids | Microns | 1.0 | 1.5 Maximum |

This item is within specifications.

Hydraulic Fluid - Booster

| | | | |
|-------------|-------------|-------|-------------|
| Flash Point | °F | 215 | 200 Minimum |
| Color | | Clear | Clear |
| Viscosity | Centistokes | 8.3* | 8.5 Minimum |
| Dye | | Red | Red |

| | <u>Unit</u> | <u>Sample</u> | <u>Specification</u> |
|---|-------------|---------------|----------------------|
| <u>Hydraulic Fluid - Booster (con.)</u> | | | |
| Particle Count | | | |
| 10 - 25 | Microns | 1, 620 | 5, 500 Maximum |
| 26 - 50 | Microns | 420 | 1, 200 Maximum |
| 51 - 100 | Microns | 60 | 300 Maximum |
| 100 - 500 | Microns | 1 | 20 Maximum |
| 500 / | Microns | 0 | 0 Maximum |
| Fibers, 100 - 1000 | Microns | 1 | 20 Maximum |
| Fibers, 1000 / | Microns | 0 | 0 Maximum |

* This item is out of specifications.

Hydraulic Fluid - Sustainer

| | | | |
|-----------------------|-------------|--------|----------------|
| Flash Point | °F | 216 | 200 Minimum |
| Color | | Clear | Clear |
| Viscosity | Centistokes | 8.35* | 8.5 Minimum |
| Dye | | Red | Red |
| Particle Count | | | |
| 10 - 25 | Microns | 2, 520 | 5, 500 Maximum |
| 26 - 50 | Microns | 480 | 1, 200 Maximum |
| 51 - 100 | Microns | 120 | 300 Maximum |
| 100 - 500 | Microns | 4 | 20 Maximum |
| 500 / | Microns | 0 | 0 Maximum |
| Fibers, 100 - 1000 | Microns | 6 | 20 Maximum |
| Fibers, 1000 / | Microns | 0 | 0 Maximum |

* This item is out of specifications.

REFERENCE DOCUMENTS

| | |
|--|----------------------|
| Flight Test Plan - Missile 4F | AE 60-0141 |
| Flight Test Program - SM-65 Series F, R & D Missiles | AZC-27-005 |
| Detailed Test Requirements (AFBMD/STL) | STL-OR-60-0000-19028 |
| Flight Test Directive (FTWG) | AA 61-0102 |

Additional reports which may be referenced for further information regarding this missile are listed below:

| <u>Reports</u> | <u>Approximate Issue Date</u> (time after test) |
|---|--|
| General Dynamics/Astronautics, San Diego, Calif | |
| Flight Test Evaluation Report | 14 days |
| AFBMD/STL, Inglewood, Calif. | |
| Flight Summary Report | 8 - 12 weeks |
| ARMA, CCO | |
| CCO Quick Look Report | 7 - 10 days |
| American Bosch ARMA Co., Garden City, N. Y. | |
| Flight Test Evaluation Report | 30 days |
| AVCO RAD, Wilmington, Mass. | |
| Evaluation Report | 30 days |
| General Electric, Syracuse, N. Y. | |
| Evaluation Report of Mod III Instrumentation System with Missile 4F | 6 - 10 weeks |
| Acoustica Associates, Inc., Los Angeles, Calif. | |
| Flight Test Evaluation Report | 30 days |
| Aeronutronics, Newport Beach, Calif. | |
| Flight Test Report | 30 days |

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

~~CONFIDENTIAL~~

Page No. 6a
AA 61-0189

SERIAL NUMBERS OF SYSTEM COMPONENTS

Azusa Transponder

Canister, Serial No. 731-0097

Re-entry Vehicle

Mark 5 Mod 2-2, Serial No. L25929

Range Safety Command System

Range Safety Command Receiver No. 1, Serial No. AF 61-164
Range Safety Command Receiver No. 2, Serial No. AF 61-163
Range Safety Command Receiver No. 1, Battery, Serial No. 011-0507
Range Safety Command Receiver No. 2, Battery, Serial No. 011-0506
Range Safety Command Power and Signal Control Unit, Serial No. 011-0038

Propulsion System

Sustainer, Serial No. 222754
Booster No. 1, Serial No. 112817
Booster No. 2, Serial No. 112818
Vernier No. 1, Serial No. 332826
Vernier No. 2, Serial No. 332767

Electrical System

Main Missile Battery, Serial No. 105-0400
Inverter, Serial No. 007-0102
Power Changeover Switch, Serial No. 003-0042

Mod III E Instrumentation Beacon System

Rate Beacon, Serial No. 6E9020
Pulse Beacon, Serial No. 6E1038

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTION 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

CONFIDENTIAL

~~CONFIDENTIAL~~

Page No. 7a
AA 61-1089

Telemetry System

Telemeter RF No. 1, Serial No. 105-0016 (0874)
Telemeter RF No. 2, Serial No. 105-0011 (0816)
Telemeter RF No. 3, Serial No. 107-0019 (0873)
Telemeter RF No. 4, Serial No. 3
Telemeter RF No. 1, Battery, Serial No. 105-0571
Telemeter RF No. 2, Battery, Serial No. 105-0569
Telemeter RF No. 3, Battery, Serial No. 105-0570
Accessory Canister, Serial No. 104-0023

Flight Control System

Gyro Canister, Serial No. 107-0171 (206)
Forward Rate Gyro Canister, Serial No. 018-0102 (99)
Servo Canister, Serial No. 110-0127 (250)
Programmer Canister, Serial No. 010-0031 (258)

Propellant Utilization System

Computer, Serial No. ACA-0086
Stillwell-LO2, Model SL 191, Serial No. 0158
Stillwell-Fuel, Model SL 192, Serial No. 0158

Pneumatics System

LO2 Tank Pressure Regulator, Serial No. 107-0287
Fuel Tank Pressure Regulator, Serial No. 103-0243

Inertial Guidance System

Platform, Serial No. 7210009
Control, Serial No. 7220077
Computer, Serial No. 7230021
Analog Signal Converter, Serial No. 7150049
Digital Signal Converter, Serial No. 7140081

Penetration System

Pod, Serial No. 022

Scientific Passenger Pods, Serial No. 3 and Serial No. 22

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTION 793 AND FOR THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

FORM 8100-0

~~CONFIDENTIAL~~

SECRET

SIGNIFICANT DATES DURING TESTING OF "A" SERIES FLIGHT MISSILES AT AMR

| Missile Aerial Component | Event | FLR | Flight No. | AMR | Comments |
|--------------------------|----------|------------------------------------|------------|------|--|
| 4A | 12-9-56 | 6-3-57 | 6-11-57 | 096 | Engine shut down at 29.9 seconds of flight. Missile destroyed at 50.1 seconds. |
| 6A | 4-6-57 | 9-20-57 | 9-25-57 | 1022 | Engine shut down at 47.7 seconds of flight. Missile destroyed at 74 seconds. |
| 12A | 11-1-57 | 12-11-57 | 12-17-57 | 2108 | Successful flight. Impacted approximately 499 mm downrange. |
| 10A | 7-26-57 | 011-27-57 0012-19-57 11-4-57 | 1-19-58 | 10 | Successful flight. Impacted approximately 542 mm downrange. |
| 11A | 12-4-57 | 0001-11-58 | 2-7-58 | 222 | Engine shut down prematurely at 117.8 seconds of flight due to flight control system failure. Missile broke up at 167 seconds. |
| 11A | 12-20-57 | 2-8-58 | 2-20-58 | 499 | Engine shut down prematurely at 124 seconds of flight due to flight control system failure. Missile broke up at 126.5 seconds. |
| 15A | 1-4-58 | 3-22-58 | 6-8-58 | 634 | Engine shut down prematurely at 105 seconds of flight due to B1 turbopump failure. Missile remained intact and impacted approximately 209 miles downrange. |
| 16A | 2-8-58 | 0001-12-58 5-22-58 | 6-2-58 | 1261 | Successful flight. Impacted approximately 448 mm downrange. |

- Premature cutoff at 6 seconds. Both booster chambers damaged, necessitating replacement.
- Full duration, but damaged B1 chamber, necessitating replacement.
- FRP terminated prematurely, but considered satisfactory.
- Prematurely terminated due to APG shutdown.

THIS MATERIAL CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794, THE TRANSMISSION OR REVELATION OF WHICH IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

SECRET

SIGNIFICANT DATES DURING TESTING OF "B" SERIES FLIGHT MISSILES AT AMR

| Missile | Altitude | Commiss. | Excursion | FRE | Flight | AMR Range No. | Comments |
|---------|----------|----------|--|-------------------------------|--------------------|------------------|--|
| 30 | 6-12-50 | 11 | 5-29-50 | 6-23-50 6-27-50 7-9-50 | 6-13-50 7-19-50 | 1544 | Missile broke up at 42 seconds of flight. Due to failure of the yaw rate gyro. |
| 40 | 5-31-50 | 13 | 6-13-50 | 7-15-50 | 8-2-50 | 1303 | Successful flight. Impacted approximately 2345 mm downrange. |
| 50 | 5-30-50 | 11 | 7-22-50 | 8-20-50 | 8-29-50 | 1303 | Successful flight. Impacted approximately 2853 mm downrange. First completely closed loop guidance system flight. |
| 60 | 7-31-50 | 16 | 8-4-50 | 9-4-50 | 9-14-50 | 1511 | Successful flight. Impacted approximately 3151 mm downrange. |
| 60 | 7-17-50 | 13 | 8-16-50 | 9-10-50 | 9-18-50 | 1512 | B1 turbopump failed at 88.8 seconds after lift-off. Missile exploded two seconds later. |
| 90 | 8-7-50 | 11 | 9-12-50 8-30-50 8-31-50 8-27-50 | 8-10-50 8-10-50 8-27-50 | 11-17-50 | 1513 | Depletion of fuel supply caused simultaneous premature sustainer and warner shutdown. Missile impacted 800 to 900 mm short of intended impact point. First flight of modified booster turbopump. |
| 120 | 9-4-50 | 16 | 11-9-50 | 11-24-50 | 11-28-50 | 1730 | Successful flight. Impacted approximately 5506 mm downrange. |
| 180 | 10-22-50 | 11 | 11-28-50 12-1-50 12-12-50 | 12-10-50 12-12-50 | 12-18-50 | 1759 | Successful flight. Missile placed into orbit. |
| 130 | 12-4-50 | 16 | 12-6-50 | 12-22-50 | 1-19-59 | 30 | Flight prematurely terminated due to unexplained difficulties starting at 100 seconds after lift-off. Missile impacted 170 mm downrange. There was no telemetry system aboard this missile. |
| 110 | 8-22-50 | 11 | 12-23-50 | 1-20-59 | 2-4-59 | 29 | Successful flight. Impacted approximately 3122 mm downrange. |
| 0 | | | | | | | Automatic cutoff inhibited by sustainer overtemp/underspeed trip 1.96 seconds after BCG links break. |
| 00 | | | | | | | Automatic cutoff inhibited by sustainer overtemp/underspeed trip 1.88 seconds after BCG links break. |
| 000 | | | | | | | Prematurely terminated by an automatic cutoff 4.96 seconds after BCG links break. |
| 0000 | | | | | | | Warner ignition only. |
| 0 | | | | | | | Manual cutoff at 6.69 seconds. |
| 00 | | | | | | | After installation of "C" Series power pack in Stage "J". |
| 000 | | | | | | | Automatic cutoff inhibited by sustainer overtemp/underspeed trip 1.8 seconds after BCG links break. |
| 0000 | | | | | | | Full duration, but engine compartment fire delayed eutelside approximately 10 days. |

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR REVELATION OF WHICH IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

SIGNIFICANT DATES DURING TESTING OF "C" SERIES FLIGHT MISSILES AT AMB.

| Missile | Arrived Condition | Excursion | EMF | Flight Dates | AMB | Comments |
|---------|-------------------|---------------------|---------------------|---------------------|------|--|
| XC | 10-21-58 M | 11-4-58 01-25-58 | 12-17-58 | 12-23-58 | 2101 | Successful flight. Impacted approximately 1000 mm downrange. |
| GC | 11-9-58 M | 1-6-59 | 1-19-59 | 1-27-59 | 18 | Although impact was close to intended point, the guidance system did not function. |
| SC | 1-21-59 M | 2-6-59 | None | 4-20-59 | 25 | Missile exploded at 174 seconds due to a malfunction at staging. Probable cause was improper operation of the fuel staging valve. |
| TC | 4-12-59 M | 2-13-59 | None | 2-18-59 | 761 | Receiver engine shutdown prematurely at 131 seconds of flight. Missile was suitable for remainder of flight. |
| CC | 5-17-59 M | 5-28-59 | 06-22-59 07-9-59 | 07-13-59 7-21-59 | 203 | Successful flight. Impacted in target area 1100 mm downrange. RFX-2 Re-entry vehicle recovered. |
| BC | 7-25-59 M | 7-25-59 | 8-16-59 | 8-24-59 | 2121 | Successful flight. Impacted almost 5 miles long in MILS not due to residual thrust after vector ended. Re-entry vehicle was recovered. |

- After power pack modification.
- Two successful Flight Readiness Firings performed.
- Ignition cabinet tests. Missed cutoff for 1st attempt in vector ignition phase. Second attempt terminated by release flame.

THIS MATERIAL CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794, THE TRANSMISSION OR REVELATION OF WHICH IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

SIGNIFICANT DATES DURING TESTING OF "D" SERIES FLIGHT MISSILES AT AMS

| Missile Serial Number | Event | TIME | TIME | TIME | Comments |
|-----------------------|----------|---------------------------------|--------------------|------|--|
| 100 | 2-20-59 | 2-27-59 | 4-16-59 | 1000 | Booster section exploded 27 seconds after MILB due to failure of airframe LOS BLI and drain valve to close. Missiles destroyed at 37 seconds. |
| 101 | 2-20-59 | 4-11-59 | 4-15-59 5-10-59 | 1754 | Missile exploded at 45 seconds due to improper launcher operation which resulted in loss of fuel tank pressure. |
| 102 | 2-20-59 | 4-20-59 | 6-4-59 | 1753 | Missile exploded at 140 seconds due to a malfunction at staging. Probable cause was improper operation of the fuel staging valve. |
| 110 | 4-20-59 | 5-11-59 007-14-59 7-23-59 | 7-20-59 | 2000 | Successful flight. Impact at 4304 nm down-range less than 1/2 mile from target in MILB net. |
| 120 | 5-2-59 | 6-10-59 | 6-11-59 | 2000 | Successful flight. Impacted in MILB net less than 1 mile from target. |
| 170 | 5-27-59 | 9-17-59 | 9-16-59 | 2106 | Successful flight. Impacted 2 miles short of target in MILB net due to failure of ventral side hydraulic package. |
| 200 | 9-27-59 | 9-2-59 | 10-4-59 | 2120 | Successful flight. Impacted in MILB net less than 1/2 mile from target. |
| 200 | 9-28-59 | 9-23-59 | 10-9-59 | 2000 | Successful flight. Impacted in MILB net less than 1 1/2 miles from target. |
| 240 | 9-28-59 | 10-6-59 | 10-29-59 | 2300 | Due to malfunction of V2 engine at staging, impacted approximately 16 miles short of target point. |
| 200 | 9-28-59 | 10-10-59 | 11-4-59 | 4200 | Unsuccessful. A/B IP failure prevented Station 5 IP system from acquiring the missile. Range safety cutoff caused R/V to impact approximately 240 miles short of target. |
| 200 | 9-28-59 | 7-11-59 9-29-59 11-9-59 | 11-26-59 | 2100 | Successful although re-entry vehicle did not separate. Impacted in MILB net. |
| 200 | 10-10-59 | 11-20-59 | 12-8-59 | 4000 | Successful flight. Impacted 1/2 mile from target in MILB net. |

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., RELATING TO AND FOR THE TRANSMISSION OR REVELATION OF SUCH INFORMATION TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

SIGNIFICANT DATES DURING TESTING OF "D" SERIES FLIGHT MISSILES AT AMR (Cont'd)

| Missile Actual Count | Event | Event Date | Event Description | AMR Range No. | Comments |
|----------------------|----------|-----------------------|-------------------|---------------|---|
| 000 | 11-20-59 | 12-10-59 | Miss | 16 | Successful Flight. Delivered a Mk-2 Re-entry Vehicle within 3 mm of target over a 3500 nm range. |
| 000 | 10-0-59 | 10-20-59 | Miss | 22 | Successful Flight. Delivered a Mk-3 Re-entry Vehicle within 3 miles of target over a 3500 nm range. |
| 000 | 10-17-59 | 1-11-60 | Miss | 24 | Successful Flight. RYK6-A2 Re-entry Vehicle impacted approximately 1/2 mile from target in MILS net. |
| 000 | 1-2-60 | 1-20-60 | Miss | 250 | Successful Flight. Mk-3 Re-entry Vehicle impacted less than 1 1/2 nm from target over a 3500 nm range. |
| 000 | 10-0-59 | 02-4-60 2-23-60 | Miss | 17 | Successful Flight. First missile to use all-inertial guidance system open loop. |
| 000 | 1-20-60 | 2-10-60 | Miss | 775 | Destroyed by fire and explosion immediately after liftoff. |
| 000 | 2-10-60 | 2-10-60 | Miss | 301 | Destroyed in the stand by fire and explosion during a launch attempt. |
| 000 | 2-2-60 | 0000-12-60 2-20-60 | Miss | 1003 | Successful Flight. Delivered Mk-3 Re-entry Vehicle within 4 nm of target over an extended range of 7553 nm. |
| 000 | 2-20-60 | 2-11-60 | Miss | 619 | Successful Flight. Delivered Mk-3 Re-entry Vehicle 4300 nm downrange within 2.2 nm of target. First flight with AIO system providing active guidance functions. |
| 000 | 0-10-60 | 0-22-60 | Miss | 801 | Impacted approximately 18 nm long due to failure of the vernier engines to shutdown when the guidance cutoff discrete was received. |
| 000 | 0-27-60 | 0-27-60 | Miss | 1003 | Successful flight. Impacted within 1 nm of target in MILS net 4300 nm downrange. |
| 000 | 0-0-60 | 7-2-60 | Miss | 803 | Reduction in pressurization of the engine tanks caused premature depletion of central helium. Re-entry vehicle impacted 40 nm short. |
| 000 | 0-22-60 | 0000-2-60 0-9-60 | Miss | 1003 | Successful flight. Impacted within 4 nm of target in South Atlantic Ocean over the intermediate range of 6359 nm. |

THIS DOCUMENT CONTAINS UNCLASSIFIED INFORMATION EXCEPT WHERE SHOWN OTHERWISE BY THE MARKINGS ON THIS DOCUMENT. IT IS THE POLICY OF THE DEFENSE DEPARTMENT, THE ARMY, THE NAVY, THE AIR FORCE, AND THE SPACE FORCE TO MAKE UNCLASSIFIED INFORMATION AVAILABLE TO THE PUBLIC.

UNCLASSIFIED

SIGNIFICANT DATES DURING TESTING OF "D" SERIES FLIGHT MISSILES AT AMR (Cont'd)

| Missile | Arrival | Comments | ERF | Flight | AMR Range No. | Comments | |
|---------|----------|----------|------------------------------|--------|---------------|----------------------|--|
| 64D | 6-14-60 | 11 | 7-7-60 | None | 1004 | 0-12-60 | Successfully impacted re-entry vehicle within 2 nm of target. First Atlas to use AIG system with impact programmed for Station 12 MILS net. |
| 74D | 7-4-60 | 11 | 8-18-60 | None | 2817 | 9-16-60 | Successfully placed RVX-2A Re-entry Vehicle within 5 nm of target. Second Atlas to use AIG System with impact in Station 12 MILS net. |
| 74D | 7-12-60 | 14 | 8-26-60 | None | 808 | 009-18-60 9-19-60 | Successful flight. Second Atlas to deliver a Mark 3 Re-entry Vehicle to target over an extended range of 7863 nm. |
| 71D | 8-19-60 | 11 | 9-23-60 | None | 1582 | 10-13-60 | Successful flight. Impacted within 2 nm of target 4387 nm downrange. Last D-AIG Missile to be flight tested. RVX-2A Re-entry Vehicle recovered. |
| 84D | 2-27-60 | 12 | 2-7-60 8-24-60 10-2-60 | None | 613 | 10-22-60 | Successful flight. Impacted within 1 nm of target 4350 nm downrange. The missile was flown without insulation and insulation bulkhead at the inter-mediate bulkhead with no adverse results. |
| 84D | 10-6-60 | 12 | 10-27-60 | None | 3583 | 11-18-60 | Successful flight. Impacted less than 1 nm from target 4388 nm downrange. Data cassette recovered. |
| 94D | 12-16-60 | 12 | 12-28-60 | None | 3886 | 1-23-61 | Successful flight. Last of "D" Series Weapon System flights. Impacted MA-3 Mod 1B Re-entry Vehicle within 1/2 nm of target 4394 nm downrange. |
| 0 | | | | | | | Launch aborted due to faulty release timer which initiated automatic cutoff. |
| 00 | | | | | | | Test terminated by sustainer rough combustion cutoff circuitry. |
| 000 | | | | | | | Launch aborted 9.48 seconds after sustainer flight begins because no release signal was generated. |
| 0 | | | | | | | Reven due to Guidance System difficulties. |
| 04 | | | | | | | Engine cutoff prior to release due to erroneous signal in blockhouse. |
| 044 | | | | | | | Terminated by erroneous output from B2 primary RCC accelerometer. |
| 0444 | | | | | | | Terminated 1.93 seconds after sustainer flight begins by the sustainer RCC system. |

THIS REPORT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794, THE TRANSMISSION OR REVELATION OF WHICH IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

UNCLASSIFIED

UNCLASSIFIED

SIGNIFICANT DATES DURING TESTING OF "E" SERIES FLIGHT MISSILES AT AMR

| Missile | Arrival | Serials | Erstion | IAF | Flight | AMR | Comments |
|---------|----------|---------|----------|---------------------|----------|----------|--|
| | | | | | | Maneuver | |
| 3E | 5-19-60 | 13 | 7-29-60 | 09-23-60 10-3-60 | 10-11-60 | 1902 | Malfunction in sustainer hydraulic system caused loss of missile after staging. |
| 4E | 7-15-60 | 13 | 10-27-60 | None | 11-29-60 | 2800 | Sustainer hydraulic pressure was lost at 41 seconds and caused missile to become unstable at booster cutoff. Sustainer thrust was lost at about 150 seconds. |
| 8E | 10-25-60 | 13 | 12-5-60 | None | 1-24-61 | 3504 | Missile stability was not maintained after 161.8 seconds due to loss of engine servo control in flight control system. Sustainer engine shut-down at 249 seconds. |
| 9E | 11-11-60 | 13 | 1-30-61 | None | 2-26-61 | 3003 | Successful flight. Impacted Mark 3 Mod II B Re-entry Vehicle within 600 yds. of aim point. |
| 11E | 1-15-61 | 13 | 2-27-61 | None | 3-13-61 | 603 | Malfunction in PU system caused fuel depletion and premature shutdown of sustainer engine at 132 seconds. |
| 16E | 3-10-61 | 13 | 3-16-61 | None | 3-24-61 | 811 | Failed to justify the booster section because of premature depletion of engine control bottle helium pressure. |
| 12E | 12-20-60 | 11 | 2-16-61 | None | 5-12-61 | 424 | Successful flight. Impacted Mark 5 Mod I Re-entry Vehicle within 0.5 mile of target at a range of 4300 miles. First "E" Series from Complex II. |
| 18E | 3-30-61 | 13 | 6-6-61 | None | 8-20-61 | 813 | Successful flight. Impacted Mark 4 Mod IV Re-entry Vehicle 1 mile of target at a range of 4300 nautical miles. First "E" Series missile down without penetration and insulation bulkhead at the intermediate bulkhead with no adverse results. |
| 17E | 3-31-61 | 11 | 5-18-61 | None | 6-23-61 | 812 | Unsuccessful flight. Malfunction in the Flight Control System caused loss of missile after 181 seconds. |

• 23 into cell jump shaft observed. Test duration 16 seconds.

THIS MATERIAL CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 50, U.S.C., SECTIONS 793 AND 794, THE TRANSMISSION OR REVELATION OF WHICH IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

UNCLASSIFIED

SIGNIFICANT DATES DURING TESTING OF "E" SERIES FLIGHT MISSILES AT AMR

| Missile | Arrival | Complex | Erection | TRF | Flight | AMR Range No. | Comments |
|---------|---------|---------|-------------------|------|----------|---------------|---|
| 20E | 6-4-61 | 13 | 6-16-61 | None | 7-6-61 | 1251 | First "E" Series missile to be successfully flown to a maximum range target of 7863 nautical miles with impact within 2.1 nautical miles of target. |
| 21E | 6-24-61 | 11 | 7-5-61 | None | 7-31-61 | 1366 | Impacted a Mark 5 Mod I Re-entry Vehicle within 3.1 nautical miles of target at a range of 4368 nautical miles. |
| 24E | 7-7-61 | 13 | 8-9-61 | None | 9-8-61 | 1803 | Flight prematurely terminated when the sustainer engine shut down during booster jettison sequence. Operation of all other systems was satisfactory. |
| 25E | 7-18-61 | 11 | 8-16-61 9-7-61 | None | 10-2-61 | 1252 | Impacted a Mark 5 Mod I Re-entry Vehicle within 1.5 nautical miles of target. A scientific passenger pod containing Centaur Guidance System was carried for the first time. • Re-erected after complex modification to "F" Series. |
| 30E | 8-22-61 | 13 | 9-12-61 | None | 10-5-61 | 1804 | Fourteenth "E" Series missile to be flight tested at AMR. First flight for a Mark 4 Re-entry Vehicle to a long range target of 7539 nautical miles. All prime objectives were achieved. |
| 32E | 10-6-61 | 13 | 10-9-61 | None | 11-18-61 | | Unsuccessful flight due to a premature shutdown of the sustainer engine. Missile was destroyed by Range Safety Officer at 35 seconds. |

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE DEFENSE LIAISON, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

UNCLASSIFIED

SIGNIFICANT DATES DURING TESTING OF "F" SERIES FLIGHT MISSILES AT AMR

| DATE | ARRIVAL | STATUS | REVISION | TIME | AMR EXERCISE NO. | COMMENTS |
|------|---------|--------|----------|--------|---------------------|--|
| 20 | 7-3-61 | 13 | 7-12-61 | 8-8-61 | 1003 | First "F" Series Missile to be flight tested. Impacted Mark 3 Mod 1 Re-entry Vehicle 4386 nauti- cal miles within 2.1 nautical miles of aim point. |

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

FORM 8000-0

UNCLASSIFIED

UNCLASSIFIED

SIGNIFICANT DATES DURING TESTING OF MERCURY/ATLAS VEHICLES AT AMR

| Missile | Arrival | Commiss Exercise | EM | EMM | AMR Range No. | Comments |
|---------|---------|--------------------|----------|---------|---------------|--|
| 100 | 4-10-59 | 4-2-59 47-22-59 | 9-3-59 | 9-9-59 | 2119 | Successful flight although booster section failed to jettison. Project Mercury Capsule recovered. |
| 500 | 5-17-60 | 6-30-60 | 7-21-60 | 7-29-60 | 1500 | Unsuccessful. Missile apparently destroyed after 60 seconds of flight. Mercury Capsule remained intact until impact. |
| 670 | 7-8-60 | 11-4-60 | 11-19-60 | 2-21-61 | 419 | Successful MA-2 mission. Impacted Mercury Capsule as planned. First closed loop flight for AMR. Capsule recovered. |
| 1000 | 9-14-61 | 9-27-61 | None | 4-25-61 | 835 | Unsuccessful. Missile was destroyed by range safety action 40 seconds after lift-off. This action was necessitated by the absence of the roll and pitch-over maneuver. |
| 800 | 7-26-61 | 7-19-61 | None | 9-13-61 | 1254 | Flight was successful. Capsule was placed in orbit after one scheduled orbit capsule was recovered east of Bermuda. All objectives were satisfied. |

Returned to Range for booster power package replacement.

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

FORM 41000-2

UNCLASSIFIED

UNCLASSIFIED

SIGNIFICANT DATES DURING TESTING OF MIDAS VEHICLES AT AMR

| <u>Miscella</u> | <u>Arrival</u> | <u>Complex</u> | <u>Erection</u> | <u>ERT</u> | <u>Flight</u> | <u>AMR</u> <u>Range No.</u> | <u>Comments</u> |
|-----------------|----------------|----------------|-----------------|------------|---------------|--------------------------------|---|
| 290 | 10-10-69 | 16 | 1-18-60 | None | 2-24-60 | 304 | MIDAS I Booster shot. Atlas portion of flight was successful. |
| 450 | 1-26-60 | 16 | 3-3-60 | None | 3-24-60 | 619 | MIDAS II Booster shot. Atlas portion of flight completely successful. |

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794, THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

FORM A1000-0

UNCLASSIFIED

UNCLASSIFIED

SIGNIFICANT DATES DURING TESTING OF RANGER VEHICLES AT AMR

| <u>Month</u> | <u>Arrival</u> | <u>Completion</u> | <u>Erection</u> | <u>FLY</u> | <u>Flight</u> | <u>AMR Range No.</u> | <u>Comments</u> |
|--------------|----------------|-------------------|-----------------|------------|---------------|----------------------|---|
| 1119 | 9-27-61 | 12 | 9-29-61 | None | 9-23-61 | 5056 | Atlas/Agena Booster portion of flight was successful. Agena spacecraft orbit was not satisfied due to a malfunction in upper stage operation. |
| 1120 | 9-29-61 | 12 | 9-29-61 | None | 11-18-61 | 4587 | Atlas/Agena Booster portion of flight was successful. Agena spacecraft orbit was not satisfied due to a malfunction in upper stage operation. |

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTION 793 AND FOR THE TRANSMISSION OR THE RECEIPT OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

FORM 4000-6

UNCLASSIFIED




UNCLASSIFIED

SIGNIFICANT DATES DURING TESTING OF ATLAS/ABLE LUNAR PROBES AT AME

| Serial | Launch | Recovery | Flight | Altitude | Comments |
|--------|----------|----------|----------|----------|--|
| 101 | 9-1-59 | 9-1-59 | 9-1-59 | 2000 | Destroyed by fire and explosion following premature cutoff during flight readiness check. |
| 102 | 9-10-59 | 10-17-59 | 10-17-59 | 4128 | Atlas/Atlas IV Lunar Probe. Atlas portion of flight was successful. Parachute of Atlas failed at 47 seconds. |
| 103 | 9-10-59 | 9-10-59 | 10-10-59 | 2000 | Atlas/Atlas V Lunar Probe. Atlas portion of flight was successful. Second stage engine operation was satisfactory. |
| 104 | 10-15-59 | 11-17-59 | 11-17-59 | 4000 | Successful. Flight was terminated after 74.5 seconds when the vehicle destroyed itself. |

Serial 101 is a continuation of test and subsequent return to test for the storage.

UNCLASSIFIED



END
DATE
FILMED
1-9-69