

AD-A036 519

BELL HELICOPTER TEXTRON FORT WORTH TEX
FLIGHT TEST EVALUATION OF OH-58A TAILBOOM FAILURE DURING AUTORO--ETC(U)
MAR 73 T L SANDERS

F/G 1/3

DAAJ01-70-C-0057

UNCLASSIFIED

206-194-134

USAACOM-TR-77-14


NL

| OF |
AD
A036519



END

DATE
FILMED
3-77



MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A

ADA 036519

12
B.S.

**USAAVSCOM
REPORT - TR 77-14**

**FLIGHT TEST EVALUATION OF OH-58A
TAILBOOM FAILURE DURING AUTOROTATION
LANDINGS**

Thomas L. Sanders
BELL HELICOPTER COMPANY
Post Office Box 482
Fort Worth Texas 76101

14 March 1973
Final Report



APPROVED FOR PUBLIC RELEASE
DISTRIBUTION UNLIMITED

Prepared for
U.S. ARMY AVIATION SYSTEMS COMMAND
Maintenance Engineering Division
Post Office Box 209
St. Louis, MO 63166

054200

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER 193 USAACOM TR-77-14	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) FLIGHT TEST EVALUATION OF OH58A TAILBOOM FAILURE DURING AUTOROTATION LANDINGS.	5. TYPE OF REPORT & PERIOD COVERED Final rept.	
7. AUTHOR(s) THOMAS L. SANDERS	6. PERFORMING ORG. REPORT NUMBER 206-194-134	
9. PERFORMING ORGANIZATION NAME AND ADDRESS Bell Helicopter Company P.O. Box 486 Ft. Worth, TX 76101	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS DA Form 3149R Data Item 05-005	
11. CONTROLLING OFFICE NAME AND ADDRESS	12. REPORT DATE 11 14 Mar 1973	
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) Commander US Army Bell Plant Activity P.O. Box 1605 Ft. Worth, TX 76101	13. NUMBER OF PAGES 59	
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited	15. SECURITY CLASS. (of this report) UNCLASSIFIED	
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report) <i>MAR 1</i>	15a. DECLASSIFICATION/DOWNGRADING SCHEDULE	
18. SUPPLEMENTARY NOTES This report presents the results of Product Improvement Task 69-45. See USAACOM TR 77-10 for additional information.	19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Flight test, Ground tiedown evaluation, Instrumentation, Test Helicopter, Ground run results, Flight Results, Tailboom Failure Evaluation, Reduced Collective Evaluation, (USAACOM) Test Results.	
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) A flight program was initiated in September 1971 to investigate the causes of the model OH-58A tailboom failures occurring in service and to explore methods of eliminating this type of failure. From the results of this test it is concluded that the tailboom failures would not have occurred had proper autorotative techniques been observed.		



BELL
HELICOPTER COMPANY

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101 A **Textron** COMPANY

TECHNICAL DATA

MODEL OH-58A

No. of Pages 59 Size "A"

REPORT No. 206-194-134

DATE 3-14-73

TITLE

FLIGHT TEST EVALUATION OF OH-58A
TAILBOOM FAILURE DURING AUTOROTATION
LANDINGS

PREPARED UNDER CONTRACT DAAJ01-70-C-0057(2E)

PROPRIETARY RIGHTS NOTICE IS ON PAGE ii.

BY Thomas Sanders DATE 3-14-73
Senior Flight Test Engineer

CHECKED W.C. Denning DATE 3-14-73
Chief Flight Test Engineer

GROUP ENGR. W.C. Denning DATE 3-14-73
Chief Flight Test Engineer

PROJECT ENGR. C. Kennedy DATE 5-3-73

CHIEF of LABS* — DATE _____

D. E. R.* — DATE _____

— DATE _____

— DATE _____

— DATE _____

* WHEN APPLICABLE

BELL HELICOPTER COMPANY
POST OFFICE BOX 482 • FORT WORTH 1, TEXAS

PAGE 11

PROPRIETARY RIGHTS NOTICE

This data is furnished with unlimited data rights
to the U. S. Government in accordance with the
provisions of Contract No. DAAJ01-70-C-0057.

ACCESSION FORM	
NTIS	White Section <input checked="" type="checkbox"/>
BCC	Buff Section <input type="checkbox"/>
UNANNOUNCED	<input type="checkbox"/>
JUSTIFICATION.....	
BY.....	
DISTRIBUTION/AVAILABILITY CODES	
DIST.	AVAIL. AND OR SPECIAL
A	

LIST OF FIGURES

<u>Figure</u>		<u>Page</u>
1-10	Collective Stick Position Versus Main Rotor Speed During Run-On Auto Landing	11-20
11	Time History of Normal Autorotation Landing	21
12	Time History of Autorotation Landing with Tailboom Failure	22
13	Runway Contact During Autorotation Landing with Tailboom Failure	23
14-20	BHC Photographs of Tailboom Failure	24-27
21-22	Pylon Position During Tailboom Failure	28-29
23	Collective Cable Restraint as Installed on the Model OH-58A, S/N 41155	30
24	Collective Stick Position Versus Main Rotor Blade Angle	31
25-30	Time Histories of Autorotation Landings Obtained with FAA Runk Grid Camera	32-37
31	Time History of Autorotation Landing by USAASTA Test Team	38
32-34	Height-Velocity Time History Plots	39-41
35	Runway Gradient at Arlington Airport	42

LIST OF TABLES

<u>Table</u>		<u>Page</u>
I	Instrumentation Set-Up Sheets	43
II	Log of Flights	47
III	Oscillograph Parameters	49
IV	Height-Velocity and Runway Gradient Grid Camera Data	50

FLIGHT TEST EVALUATION OF OH-58A
TAILBOOM FAILURE DURING AUTOROTATION
LANDINGS

SUMMARY

A flight test program was initiated in September 1971, under Contract No. DAAJ01-70-C-0057(2E) and Product Improvement Task No. 69-45, to investigate the cause(s) of the Model OH-58A tailboom failures occurring in service and to explore methods of eliminating this type of failure.

A three phase company investigation was initiated and consisted of (1) a mathematical analysis and associated computer runs, (2) a series of ground vibration tests, and (3) a ground tiedown and flight test. The results of the flight evaluation, phase 3, are presented in this report.

Two Model OH-58A Helicopters, S/N's 41080 and 41155, were utilized during the evaluation.

With a telemetry capability of monitoring critical parameters, a series of tests were conducted and data obtained. Analysis of the data that were recorded during autorotations showed that when touchdowns were made at abnormally high speeds and at abnormally low rotor rpm, aft fuselage wrinkling and failure of the tailboom occurred. This damage occurred when loads were introduced into the fuselage at the pylon spike stops via the main rotor flapping stops. This was demonstrated during the evaluation when a tailboom failure was duplicated to study the influential circumstances associated with the failure.

Results of this test indicate that autorotation touchdown airspeeds in excess of 30 knots should be avoided and upon ground contact the collective should be smoothly reduced as soon as touchdown conditions permit. Also, tests conducted with the collective range reduced by approximately 20 percent showed a substantial reduction in main rotor flapping and pylon behavior.

From the results of this test, it is concluded that the tailboom failures experienced by the Army (which caused initiation of this test program) would not have occurred had proper autorotative techniques been observed. That is to say that primarily cyclic control should be utilized to flare the helicopter so as to arrest forward airspeed and initial rate of descent. Application of collective thereafter should occur and only in close proximity to the ground to arrest rate of descent for the last few feet of altitude until ground contact is made. Upon ground contact, collective should be smoothly reduced as soon as practical; not increased. This technique is recognized by helicopter pilots throughout the world as the safe and proper method of making a full autorotative landing. Conversely, a technique of flying the helicopter to the ground, primarily by the use of collective, is improper in that (1) it is inherently unsafe (miscalculation by the pilot can

SUMMARY - (cont)

result in the helicopter being too high off the ground with no arresting capabilities remaining), and (2) it results in abnormally high touchdown speeds and abnormally low rotor rpm. Other types of rotor systems for other helicopters flown in this manner are equally unforgiving.

Tests were conducted at the Bell Helicopter Company (BHC) Flight Research Center, Arlington, Texas.

FLIGHT TEST EVALUATION OF OH-58A
TAILBOOM FAILURE DURING AUTOROTATION
LANDINGS

INTRODUCTION

A flight test program was initiated to investigate U. S. Army reported OH-58A tailboom failures during autorotation touchdown landings. The intent of the investigation was to explore methods or techniques of eliminating these failures and make appropriate recommendations.

A standard Model OH-58A Helicopter, S/N 41080, was instrumented and several hypotheses were to be investigated. Test emphasis was directed towards the following ground and possible flight evaluations.

A. Ground Run Tiedown Evaluation of

1. Baseline pylon stability.
2. Effect of first and second drive system torsional mode on pylon damping.
3. Blade chord natural frequency and feedback at high collective pitch.
4. Damping of pylon fore and aft, lateral mode.
5. Coriolis Force Excitation.

B. Possible Flight Evaluation of

1. Binding of the main rotor flapping bearings under high collective pitch and low rotor speed resulting in an unstable rigid rotor effect producing pylon whirl and pylon stop contact.
2. Rotor blade resonant amplification (chord and/or beam) which could produce large pylon motions and high control loads.
3. The effect of significant rotor out-of-balance resulting in excessive pylon response and possible contact of the pylon stops as pylon modes are transitioned.
4. Pylon whirl induced by pylon stop contact with high rotor coning, sustained and amplified by symmetric chordwise deflection of the rotor blades.
5. High main rotor one-per-rev hub forces produced by Coriolis accelerations resulting from cyclic inputs in the presence of high rotor coning.

Additional tests were conducted on the Model OH-58A Helicopter, S/N 41155, to evaluate a reduction in the available collective range.

INTRODUCTION - (cont)

Flights were performed at the BHC Flight Research Center, Arlington, Texas. The first ground run was conducted on 20 September 1971 and the last flight was completed 24 November 1971.

The dynamic characteristics of the rotor, pylon, drive train, fuselage, and skid gear were evaluated in detail by the Dynamic Group and results are on file but not presented in this report.

INSTRUMENTATION

The airborne data acquisition system installed in the Model OH-58A Helicopter, S/N 41080, consisted of an oscilloscope recorder and a telemetry package.

The oscilloscope was a standard 18 channel Consolidated Electrodynamics Corporation Model S-114-P3 recorder with galvanometers. A calibrator equivalent was used to correlate the initial calibration with the data obtained.

The telemetry package consisted of BHC designed signal conditioning modules, vector voltage controlled oscillators, Model TL407, and a conic "L" band telemetry transmitter. The telemetry link had a maximum capacity of 13 data channels. The signal conditioning modules are the passive type, and insert a calibration signal at the end of each data point. The incoming telemetry multiplex signal includes a system status and reference signal which is recorded on magnetic tape in the Ground Data Center. Brush charts are used for real time display allowing data parameters to be reproduced as they occur.

Calibrations

Standard procedures were used by the BHC Standards and Calibration Laboratory to instrument the test helicopters. Table I presents a list of calibrated items and their respective calibration numbers.

Flight Log

A log of all ground runs and flights, listing the date, flight and/or ground run numbers, duration time and configuration, is shown in Table II.

TEST HELICOPTER

The test helicopters used during this test program were the Model OH-58A Bell S/N's 41080 and 41155.

S/N 41080: Prior to the test flight the aircraft was leveled and the following rigging measurements were obtained.

Main Rotor Mast	5° forward, 1° left
Swashplate	
F/A Cyclic (full throw)	+17.5° forward, +8.0° aft
Lateral Cyclic (full throw)	+5.5° right, +8.0° left
Collective Pitch (full throw)	-0.5° down, +16.6° up

S/N 41155: Aircraft was received, inspected, and instrumented. The collective pitch was measured at the main rotor hub and the minimum blade angle was +0.4 degrees and the maximum blade angle was +17.7 degrees.

RESULTS AND DISCUSSION

Ground Run Results

The aircraft was placed on tiedown and a series of ground runs were conducted. Cyclic inputs at approximately 1.0, 2.5, and 5.0 cps were made to obtain baseline pylon stability information and to determine the effect of first and second drive system torsional mode on pylon damping. During the evaluation, main rotor thrust was varied from zero to approximately 2410 pounds.

At a main rotor speed of 200 rpm and with 91 percent collective, the maximum main rotor blade chord excitation was $\pm 13,500$ inch-pounds. Efforts to determine the blade natural frequency were unsuccessful.

The lateral pylon stops could be contacted with a cyclic input at a main rotor rpm of 180 and 91 percent collective. Mast bumping could be induced with 100 percent collective and at a main rotor rpm of 240. Pylon contact or mast bumping did not reflect any unusual loads in the main rotor or fuselage. A maximum tailboom stress of only 4000 psi, which is a nominal load, was generated with a cyclic input of approximately 5.0 cps with a main rotor rpm of 270 and collective at 86 percent. To evaluate the Coriolis effect, cyclic inputs were made during a main rotor rpm sweep with a blade root collective of 10 degrees.

Results obtained during the ground runs did not offer any insight or peculiarities that might suggest tendencies that could result in high tailboom stresses. Also, it was very difficult to determine fuselage natural frequencies while the aircraft was secured during ground run. As a result, the decision was made to proceed to the flight evaluation.

Flight Results

Since the tiedown results were inconclusive, investigation efforts were directed towards duplicating the tailboom failures reported by the Army. With a telemetry capability of monitoring critical parameters, a series of hovering throttle chops and touchdown autorotations were conducted. During a variety of autorotational landings, various techniques of cyclic and collective application at a disparity of main rotor rpm's were investigated. Many of the basic hypotheses became inconsequential due to the following.

1. Pylon stop contact with high main rotor coning did not indicate pylon whirl tendencies. Lateral pylon spike contact could be obtained without too much difficulty; however, no unusual loads or peculiar tendencies were evident. Fore and aft pylon spike contact was very difficult to obtain.
2. At conditions of high collective pitch and low rotor speed, there was no evidence of binding in the main rotor flapping bearing.
3. There was no evidence of rotor blade resonant amplification that could result in large pylon motions and high control loads.

RESULTS AND DISCUSSION - (cont)

Flight Results - (cont)

4. Cyclic inputs during conditions of high main rotor coning did not appear to influence main rotor hub forces.

A total of 36 touchdown autorotation landings and 10 throttle chops were flown to obtain data. Analysis of autorotation data began to suggest certain trends of maximum main rotor flapping with high touchdown airspeeds at low main rotor speeds of 200 rpm or less, see Figures 1 through 10. During the third flight, a tailboom failure was duplicated to study the influential circumstances associated with the failure.

Tailboom Failure Evaluation

A review of the recorded data suggested that several factors contributed to the tailboom failure and the absence or reduction of any one factor was sufficient to prevent failure. The characteristics associated with the tailboom failure can be summarized as follows:

1. Prior to or at aircraft touchdown, the collective must be raised to the full up mechanical stop and allowed to remain at the up stop until the main rotor rpm decays to approximately 200 or less.
2. Touchdown airspeed must be sufficient to provide considerable rotor inflow.
3. Main rotor blade coning and flapping must be sufficient to produce fore and aft pylon stop contact.

The combinations of the above results in sufficient rotor-fuselage inertia to produce damaging fuselage stress loading.

Comparison of Figure 11, a time history of a normal touchdown autorotation, and Figure 12, a time history of the touchdown autorotation when the tailboom failure occurred, tend to substantiate the influence of main rotor flapping with collective position, main rotor speed, and pylon behavior associated with the failure.

Figure 13 shows aircraft ground contact and subsequent ground roll, and Figures 14 through 20 are photographs depicting test vehicle damage that occurred during the evaluation. Figures 21 and 22 depict the extent of the pylon motion during the failure.

Main rotor control and blade loads were normal during the autorotation landings and only increased after onset of the tailboom failure condition.

A vertical and roll acceleration of considerable amplitude, in excess of two g's, was observed in the cabin. At the conclusion of the landing, there was no doubt by the flight crew that damage of one form or

RESULTS AND DISCUSSION - (cont)

Tailboom Failure Evaluation - (cont)

another had been sustained. It is the further opinion of the flight crew that a pilot of even minimal experience would recognize that the aircraft had experienced an abnormal situation and would conduct an exterior safety of flight inspection prior to a takeoff.

Options Available for Failure Reduction: After careful review of available data, the following items were evaluated and considered as possible methods of eliminating or reducing the possibility of a failure.

1. Determine the technique the U. S. Army is using in the training of new and transition pilots, and the rationale for their techniques. Also, recommend modifications of existing techniques if deemed appropriate.
2. Provide cockpit indicator to indicate warning of excessively hard landings and potentially damaging tailboom vibrations.
3. Reduce the available collective range to avoid excessive dynamic loading and yet maintain adequate height-velocity margins.
4. Consider basic structural modifications to stiffen the critical areas, reduce stress levels, and/or produce changes in dynamic response characteristics and system coupling.
5. Provide mechanical fixes, such as pylon viscous or friction dampers, and fuselage impact and/or friction dampers.

Reduced Collective Evaluation: After reviewing the options available, indications were the best solution to the problem was that improper autorotative techniques needed revising. However, in the event the ship were landed improperly it was judged that a reduction of the collective range would be beneficial. As a result, a Model OH-58A Helicopter, S/N 41155, was instrumented and a series of tests were begun to determine the feasibility of limiting the available collective pitch during auto-rotation landings (Option 3). This reduction was accomplished by attaching an adjustable cable on the copilot collective stick that physically limited the maximum up position of the collective, see Figure 23. Figure 24 shows the results of a hangar calibration of collective stick position versus main rotor blade angle. A series of hovering throttle chops, slide on landings, and autorotation touchdowns at various percent of collective reduction were evaluated to determine if a reduction in the available collective would prohibit maintaining adequate height-velocity margins. During the hovering throttle chops at a gross weight (GW) of 3000 pounds, there was a definite change in the character of main rotor blade stall when the available collective blade angle was reduced to 75 percent; however, time airborne, which is an indicator of rotor capability, was also reduced. At 80 percent available collective the time airborne after throttle chop was adequate, 3.6 seconds, and pylon motion and main rotor flapping were greatly reduced.

RESULTS AND DISCUSSION - (cont)

Tailboom Failure Evaluation - (cont)

Reduced Collective Evaluation - (cont)

Six autorotation landings were accomplished with the available collective pitch reduced by approximately 20 percent, and Figures 25 through 30 present the data obtained by using the Federal Aviation Administration (FAA) Runk Grid Camera. Touchdown calibrated airspeed varied from 24 knots to 41 knots. Table III presents important oscillograph parameters recorded during the autorotation landings.

Test results indicate that the probability of tailboom failure, with the available collective range reduced by approximately 20 percent, is greatly decreased due to a reduction in main rotor flapping.

A mathematical analysis and associated computer study were conducted to evaluate the tailboom failure problem. The study was concentrated in the area of main rotor flapping versus main rotor blade angle and main rotor inflow during autorotation touchdown. Synopsis of the evaluation concluded that main rotor flapping benefits derived by the reduction of the main rotor blade angle can be reduced by an increase in rotor inflow. However, the touchdown airspeeds required to produce the mandatory rotor inflow are considered excessive and unrealistic for normal autorotation touchdowns. An autorotative touchdown in excess of 40 kts coupled with improper landing techniques is judged to be outside the reasonable and mandatory operating envelope of the helicopter. As a result, it can be concluded that the probability of a tailboom failure would be greatly reduced by improving autorotation techniques to avoid high speed touchdowns with high main rotor blade angles.

U. S. Army Aviation Systems Test Activity (USAASTA) Test Results

A flight evaluation of the Model OH-58A Helicopter, S/N 41155, with a reduced collective blade angle was conducted by an Army test team at the BHC Flight Research Center, Arlington, Texas, on 23 and 24 November 1971.

During the USAASTA evaluation the helicopter was first flown in the standard OH-58A configuration. The adjustable cable on the copilot collective stick was installed prior to the second flight to limit the maximum up position of the collective to 80 percent (13.6 degrees main rotor blade angle at the hub).

A series of touchdown landings were made utilizing techniques that had produced tailboom failures in the past. Figure 31 presents a time history of an autorotation touchdown landing that produced a considerably high level of vertical tailboom excitation with a near damaging stress of 17,586 psi. The pilot reported the touchdown airspeed was probably in excess of 40 knots indicated airspeed (KIAS). Visible airframe damage was limited to minor pylon upper cowling contact and

RESULTS AND DISCUSSION - (cont)

USAASTA Test Results - (cont)

cracked fiberglass fairing at the tailboom connection area. Aircraft damage was considered minor and tests continued. This documented autorotation landing incident is an additional substantiation of the computer study results.

The Army test team also conducted tests to determine if the present height-velocity margins could be maintained when the available collective range was reduced to avoid excessive dynamic loading. Data were obtained by using the FAA Runk Grid Camera and results are presented in Figures 32 through 34. Table IV presents the height-velocity time history data. Figure 35 shows the runway gradient at the test site. Maximum available collective was limited to 85 percent. Results of the evaluation indicated that the maximum collective utilized during the autorotation was 70 percent and as a result, shows that adequate collective is available to maintain present height-velocity margins at the altitude the test was conducted.

CONCLUSIONS

A flight test program to investigate OH-58A tailboom failures during autorotation landings and explore methods of eliminating these failures has been completed.

The following conclusions are made on the basis of the subject flight test program.

1. The results obtained during the ground run were inconclusive.
2. Efforts to duplicate a tailboom failure were successful and as a result, many of the original hypotheses to be investigated became inconsequential.
3. The combination of maximum main rotor blade angle and flapping, low rotor rpm, rotor inflow, and pylon contact (fore and aft) has sufficient rotor-fuselage inertia to produce damaging fuselage stress loading.
4. With the available collective range reduced by approximately 20 percent, test results indicate that the probability of tailboom failure, resulting from improper autorotation techniques, is greatly reduced due to the reduction in main rotor flapping.
5. The probability of tailboom failure would be eliminated by observing proper autorotation techniques, thereby avoiding high speed touchdowns with high main rotor blade angles.

BY
CHECKED

BELL HELICOPTER COMPANY
POST OFFICE BOX 121 • FORTH WORTH, TEXAS

MODEL OH-58A PAGE 11
BELL 41080 SFT 206-194-134
FLT. 1C
REC. 508




FIG. 1 COLL STK POSITION VS. M/R SPEED DURING RUN-ON
AUTO LANDING.

BY
CHECKED

BELL HELICOPTER COMPANY
POST OFFICE BOX 142 • FORT WORTH, TEXAS

MODEL OH-58A PAGE 11
BELL 41080 RPT 206-194-134
FLT. 1C
REC. 508





FIG. 1 COLL STK POSITION VS. M/R SPEED DURING RUN-ON
AUTO LANDING.




BY
CHECKEDBELL HELICOPTER COMPANY
POST OFFICE BOX 1000 • FORT WORTH, TEXASMODEL OH-58A PAGE 13
HELI 41080 RP 206-194-134FLT. 1
REC. 515

FIG. 3 COLL STK POSITION VS M/R SPEED DURING RUN-ON AUTO LANDING

BY
CHECKED

BELL HELICOPTER COMPANY
P.O. BOX 10000 • FORT WORTH, TEXAS

MODEL OH-58A PAGE 14
BELL 41080 RPT 206-194-134
FLT. 1C
REC. 516




FIG. 4 COLL STK POSITION Vs. M/R SPEED DURING RUN-ON
AUTO LANDING




FIG. 5 COLL STK POSITION VS M/R SPEED DURING RUN-ON
AUTO LANDING

BY
CHECKED

DELL HELICOPTER COMPANY
POST OFFICE BOX 8400 • FORT WORTH, TEXAS

MODEL OH-58A PAGE 16
HELI 41080 RPT 206-194-134
FLT. 1D
REC. 525




Fig. 16 COLL. STK. POSITION VS. M/R SPEED DURING RUN-ON
AUTO LANDING



BY _____
CHECKEDBELL HELICOPTER COMPANY
POST OFFICE BOX 4111 • FORT WORTH, TEXASMODEL OH-58A PAGE 17
HELI 41080 RPT 206-194-13FLT. ID
REC. 529

FIG. 7

COLL STK POSITION VS M/R SPEED DURING
RUN-ON AUTO LANDING



BY
CHECKED

ROBINS HELICOPTER COMPANY
THE ROBBINS CO. • ROBINS HELICOPTERS

MODEL OH-58A PAGE 19
HELI 41080 RPT 206-194-134

FLT. 3
CTR. 594

SYM OSC STRESS LEVEL
∅ ≤ 5000 PSI
◎ ≤ 10000 PSI
● ≥ 10000 PSI







FIG. 9 COLL STK POSITION VS M/R SPEED DURING
RUN-ON AUTO LANDING





PAGE 22
RPT 206-194-134



7072 55425






Fig. 14 Model OH-58A, S/N 41080, After Tailboom Failure, BHC Photo 284188




Fig. 15 Model OH-58A, S/N 41080, Right Aft View of Tailboom Failure at Fuselage Sta. 220, BHC Photo 284185




Fig. 16 Model OH-58A, S/N 41080, Tailboom Failure, Left Side, Fuselage Sta. 220, BHC Photo 284177



Fig. 17 Model OH-58A, S/N 41080, Tailboom Failure, Lower Surface, Fuselage Sta. 220, BHC Photo 284179



Fig. 18 Model OH-58A, Lower Transmission Case After Failure, BHC Photo 284118




Fig. 19 Model OH-58A, Pylon Area After Tailboom Failure, BHC Photo 284120




Fig. 20 Model OH-58A, Transmission Cowling,
Left Side, After Tailboom Failure,
BHC Photo 284183

BY
CHECKED

BELL HELICOPTER COMPANY
POST OFFICE BOX 10000 • SAN ANTONIO, TEXAS 78234

MODEL OH-58A PAGE 28
BELL 41080 RPT 206-194-1
FLT. 3
CTR. 595

PRINTED IN U.S.A. ON CLEARPRINT TECHNICAL PAPER NO. 1015

© 1972 BELL HELICOPTER CO.

CLEARPRINT PAPER CO. NO. C-19X MILLIMETERS 200 BY 250 DIVISIONS




FIG. 21 PYLON POSITION DURING TAILBOOM FAILURE

BY
CHECKEDBELL HELICOPTER COMPANY
1000 BELLINE AVENUE • DALLAS, TEXAS

BAE OH-58A PAGE 29

BELL 41080

HPI 206-194-134


FLT. 3
CTR. 595NOTE: ARROWS INDICATE TRAVEL
WILL GO TO STOP

FIG: 22 PYLON POSITION DURING TAILBOOM FAILURE



Fig. 23 Collective Cable Restraint as
Installed on the Model OH-58A,
S/N 41155

BY
CHECKED

BELL HELICOPTER COMPANY
FOOT BRIDGE STATION • DALLAS, TEXAS

MODEL OH-58A PART 31
BELL 41155 RPI 206-194-134

1970 BELL HELICOPTER COMPANY - ALL RIGHTS RESERVED

CONFIDENTIAL




FIG 24 COLLECTIVE STICK POSITION VS M/R BLADE ANGLE

SHIP NO. #1153	F/T NO. 5-3	FOR TAKE-OFF DISTANCE
CTR NO. 924	ACT. GROSS WT. 2936 LB.	OBS. F/T DIST. FT. TIME TO STOP AT. SEC.
GROUNDS LEVEL PRESS. ALT.	650 FT	NOMINAL ENGINE POWER. SHP.
GROUNDS LEVEL AMBIENT TEMP.	20 °C	FOR LANDING DISTANCE
ST. = .960; $\sqrt{57}$ = .980; DEG. ALT. 1386 FT.		TIME, SOFEET TO GROUND CONTACT 9.62 SEC.
Avg. WIND SPEED(Along Path) 11.0 FPS		ENTRY GROUND SPEED @ 50 FT. 82.5 FT/SEC.
		GROUND CONTACT GROUND SPEED 31.3 FT/SEC.
		RATE OF DESCENT AT STOP. 26.0 FT/SEC.
		OBSERVED AIR LANDING DIST. 477 FT.
		OBSERVED GROUND LANDING DIST. 163 FT.
NOTE: EVENT LIGHT NOT VISIBLE. T.D. LOCATED FROM OBS. DATA AND RUNWAY GRADIENT CORRELATION.		CALIBRATED AIR SPEED AT T.D. = 24.4 FT/S.

HORIZONTAL DISTANCE-FT & ENGINE POWER ~ SHP




FIG. 25 TIME HISTORY OF LANDING RUN NO. 10 ~ F/T NO. 5-3

04-58A 32
206-194-134

10 - 10 - 10 - 10

CIRK MILITARIA

SHIP NO. 41155	FLT NO. 5B	FOR TAKE-OFF DISTANCE		
CTR. NO. 925	ACT. GROSS WT. 2526 LB.	OBS. T.O. DIST.	FT.	TIME TO SOFT HT. SEC.
GROUNDS LEVEL PRESS. ALT.	650 FT	NOMINAL ENGINE POWER.		SHR
GROUNDS LEVEL AMBIENT TEMP.	20 °C	FOR LANDING DISTANCE		
σ' = .960 ; V ₀ = .860 ; DEM. ALT. /380 FT		TIME, 50 FEET TO GROUND CONTACT 7.23 SEC.		
Avg. WIND SPEED (ALONG PATH) 11.0 FPS		ENTRY GROUND SPEED @ SOFT. 79.0 FT/SEC.		
		GROUND CONTACT GROUND SPEED 47.5 FT/SEC.		
		RATE OF DESCENT AT SOFT. 24.4 FT/SEC.		
		OBSERVED AIR LANDING DIST. 433 FT		
		OBSERVED GROUND LANDING DIST. 365 FT		
		CALIBERATED AIR SPEED AT T.O. = 33.8 FT/S.		

NOTE: EVENT LIGHT NOT VISIBLE.
T.O. LOCATION FROM OBS DATA
AND RUNWAY GRADIENT CORRELATION.




FIG. 26 TIME HISTORY OF LANDING. RUN NO. 11 ~ FLT. NO. 5B

J.G. 10-27-71

SHIP NO. #1155	F/T NO. 5-B	FOR TAKE-OFF DISTANCE	
CTR. NO. 926	ACT. GROSS WT. 2921 LB.	OBS. T.O. DIST. FT.	FT. TIME TO SOFTEN SEC.
GROUND LEVEL PRESS.	ALT. 650 FT	NOMINAL ENGINE POWER.	SHP.
GROUND LEVEL AMBIENT TEMP. 50° F	TIME, SOFTEN TO GROUND CONTACT SEC.	FOR LANDING DISTANCE	
5° = .960 ; VST. 200, DEC. ALT. 1350 FT	ENTER GROUND SPEED @ 50 FT. 80.0 FT/SEC		
Avg. WIND SPEED(ACROSS PATH) 11.8 FPS	GROUND CONTACT GROUND SPEED 43.0 FT/SEC		
	RATE OF DESCENT AT 50 FT 21.9 FT/SEC		
	OBSERVED AIR LANDING DIST. 624 FT		
	OBSERVED GROUND LANDING DIST. 237 FT		
	CALCULATED AIR SPEED AT T.D. = 31.9 FT/SEC		
	STOP		

NOTE: LIGHT NOT VISIBLE
T.D. LOCATION FROM OBS. DATA
AND RUNWAY GRADIENT CORRECTION




CHART NO. 28




FIG. 28 Time History Of Landing Run No. 13 ~ Flt. No. 5B

C. V. S.




Fig. 29 TIME HISTORY OF LANDING RUN NO. 14 ~ FT. NO. 52B

C-249

SHIP NO. 41155 F/T NO. 5B
 CTR. NO. 929 ACT. GROSS WT. 2891 LB.
 GROUND LEVEL PRESS. ALT. 650 FT
 GROUND LEVEL AMBIENT TEMP. 20 °C
 $\sigma' = .960 ; \sqrt{\sigma'} = .960$; DEM. ALT. 1350 FT
 AVG. WIND SPEED (ALONG PATH) 16.0 FPS
 CALIBRATED AIRSPEED AT T.D. = 42.0 KTS.

HORIZONTAL DISTANCE - FT & ENGINE POWER - SHP

1400
 1200
 1000
 NOTE: TIME AT STOP = 25.24 SECONDS
 HORIZ. DIST AT STOP = 1262 FT.

NOTE: EVENT LIGHT NOT VISIBLE
 T.D. LOCATION FROM OBS. DATA
 AND RUNWAY GRADIENT CORRELATION
 SOFT



FIG. 30 TIME HISTORY OF LANDINGS RUN NO. 15 ~ F/T NO. 5-B

OH-58A

37
206-194-134

120-177-7

PAGE 38
RPT 206-194-134




FIG. 31 TIME HISTORY OF AUTOROTATION LANDING.

SHIP NO. 41155 DATE 10-26-69
 G.R.O.S. WEIGHING 2932 LBS
 OVER SPEED 95 MPH 200 FT.
 MAXIMUM THRUST 2000 LBS.
 DESIGN RATIO 1.021 100%
 DENSITY AIR 0.0705 - 900 FT.
 1934 NY PILOT JOE MARRSS.

ENTRY HEIGHT (AT T.C.) 96.0 FT.
ENTRY SPEED (AT T.C.)
 $\frac{dS}{dt} = 73.7 \text{ FPS} = 42.2 \text{ HTS. V.G.S.}$

$V_{H.G.} = 4.6 \text{ HTS.}$
 $V_{T.C.} = 4.9 \text{ HTS. V.G.S.}$
 $V_{T.C.} (V.G.S. + V_{H.G.}) = 48.8 \text{ HTS. V.G.S.}$
 $48.8 \text{ HTS.} \times 22.0 \text{ FPS} = 1.056 \text{ HTS. V.G.S.}$
 1.056 HTS. = 100% OF STD. TRAVEL




FIG. 32 Time History Of Horizontal Distance, Height Above Ground
 And Main Rotor RPM ~ Throttle Velocity Run No. 6

SHIP NO. 41155 DATE 11-24-71
 GROSS WEIGHT 2,852 LBS.
 PRESSURE ALTITUDE 200 FT
 AVERAGE TEMPERATURE 20.0
 DENSITY ALTITUDE 24.00 FT
 DENSITY ALTITUDE = 700 FT
 AIRWAY PILOT, JOE WATTS

ENTRY HEIGHT (AT TC) 88.0 FT
 ENTRY SPEED (AT TC)
 $\frac{L_s}{L_o} = \frac{65.0}{59.5} = 1.085 = 10.3$ HTS. V.G.S.
 $V_{W.C.} = 4.2$ HTS.
 $\sqrt{L_s} = (V_{G.S.} + V_{W.C.}) = 4.6$ HTS. V.G.S.
 GND. DISTANCE = 16.5 FT = 2.8 HTS. V.G.S.




Fig. 33 Time History of Horizontal Distance, Rotor RPM, Throttle Chop, and Vertical. Rotor RPM = 1600 RPM. Throttle Chop = 100% Open. Vertical = 100% Open. All curves start at 0 at 0 seconds.

34
CROSS

ROLL HELICOPTER COMPANY

04-04-58A 41
206-194-134

GROSS WEIGHT	4,160 LB.	DATA: 14.245 - 21.
BELLOWS ROLL AND WEIGHT	2,000 LB.	
COLLECTIVE THROTTLE POSITION	20.00	
DECELERATOR POSITION	1.021	DATA: 14.245 - 21.
DECELERATOR POSITION	1.025	DATA: 14.245 - 21.
ARMED POSITION	1.025	DATA: 14.245 - 21.

$$\text{ENTRY HEIGHT (AT T.C.)} = 85.5 \text{ FT.}$$

$$\text{ENTRY SPEED (AT T.C.)}$$

$$S = 620 \text{ FPS} = 36.7 \text{ MTS/SEC.}$$

$$\text{WEIGHT} = 4.2 \text{ MTS.}$$

$$\text{WEIGHT + VACUUM} = 4.3 \text{ MTS. VACUUM}$$

$$\text{GROSS WEIGHT} = 24.5 \text{ FPS} = 12.6 \text{ MTS. VACUUM}$$

$$\text{ARMED POSITION. } 10 \text{ SEC. TRAVEL}$$

$$\text{COLLECTIVE TRAVEL} = 67.0 \% \text{ (% OF STD. TRAVEL)}$$





FIG. 34 Time History of Horizontal Distance Traveled Above Ground
And Rotor RPM in Flight - Velocity Run Up S

NOTE: COPY OBTAINED FROM NAME
CARRIED IN NAME OF SIGHT
TOUCH AT VARIOUS ROADS
LOCATIONS USING THE RAD
GRID CHART

* AS READ FROM THE RAD GRID CHART



-20

4000

5000

7000

GRAD GRID
RAD GRID

30° VARIATION MEADING ~ 160°

OH-58A

42

206-194-134

Fig. 35 May 16-34 C. D. H. G. ④ GRANBURY MUNICIPAL AIRPORT, TEXAS

100-290-7

PRNG. NO. F0132 MODEL OH-58A
PROGRAM T/B FAILURE INVESTIGATION

S/N 41080 DATE 9-30-71 1ST RFC 0539
CHANGE LETTER B 1ST FLT 2

SET UP ITEM DESCRIPTION

DELTA CAL REF VALUE UNITS TRACK 1

TABLE I Sheet 1 of 4

01-01-0483	F101	M/R RED PITCH LINK	1234.21	0.00	LBS
01-02-0539	B103	M/R RED YOKE CHD BEND	107589.33	0.00	IN-LB
01-03-0539	B102	GROUND CONTACT INDICATOR	0.00000	0.00000	
01-04-0483	D104	M/R FLAPPING	184.48963	100.00001	%
01-05-0483	D021	F/A CYCLIC STK POSITION	99.90400	50.00000	%
01-06-0483	D022	LAT CYCLIC STK POSITION	75.79881	50.00000	%
01-07-0483	D023	CNLL STK POSITION	105.86958	0.00000	%
01-08-0483	D051	F/A PYLDN MOUNT MOTION	91.88653	60.55000	%
01-09-0483	D052	LAT PYLDN MOUNT MOTION	116.88656	28.30000	%
01-10-0483	S251	R/H LONGERON STRESS STA 176	24354.79	0.00	PSI
01-11-0483	S252	T/B LOWER SKIN STRESS STA 219	24350.70	0.00	PSI
01-12-0483	S253	L/H LONGERON STRESS STA 176	48810.96	0.00	PSI
01-13-0483	R018	M/R AZIMUTH	0.00000	0.00000	

Page 43
206-194-134

BY _____	BELL HELICOPTER COMPANY POST OFFICE BOX 482 • FORT WORTH 1, TEXAS			MODEL <u>OH-58A</u> PAGE <u>44</u>
CHECKED _____				RPT <u>206-194-134</u>
TABLE I Sheet 2 of 4 Instrumentation Set-Up Sheet, S/N 5610				
Purpose: Tailboom Evaluation	Chan. No.	Measured and Location	Sta.	Flight: 1 Lab No. C.E.
				Date: 9-29-71
				Ref.
1	Engine Torque Pressure	8761	100 K	psi
2	Hydraulic Pressure	8785	252.7	psi
3	Center of Gravity Vertical Acceleration	14649	1.09	g
4	C.L. Hub F/A Acceleration	2041	1.365	g
5	C.L. Hub Lateral Acceleration	2040	1.29	g
6	R/H Cyclic Boost Tube	5903C	731	lb
7	L/H Cyclic Boost Tube	5904C	751	lb
8	Collective Boost Tube	7557A	918	lb
9	M/R Feathering	7894	14.65	deg
13	M/R rpm (Linear)	-	-	rpm/in.
17	Skid Gear Ground Contact	-	-	-
18	N/R Azimuth	-	-	-

PROG. NO. F0132 MODEL OH-58A S/N 41155 DATE 10-9-71 1ST REC 0617
 PROGRAM TAILBOOM INVESTIGATION CHANGE LETTER C 1ST FLT 1 4
 SET UP ITEM DESCRIPTION DELTA CAT REF VALUE UNITS TRACK 1

TABLE I

Sheet 3 of 4

ITEM	DESCRIPTION	DELTA CAT	REF	VALUE	UNITS	TRACK 1
01-01-0617 B102 GROUND CONTACT INDICATOR				0.00000	0.00000	
01-02-0617 D104 M/R FLAPPING				145.79598	100.00001	%
01-03-0617 D023 COLLECTIVE STK POSITION				105.15599	0.00000	%
01-04-0617 D021 F/A CYCLIC STK POSITION				96.85609	50.00000	%
01-05-0617 D022 LAT CYCLIC STK POSITION				138.17599	50.00000	%
01-06-0617 D051 F/A PYLON POSITION				153.65130	39.41000	%
01-07-0617 D052 LAT PYLON POSITION				204.35375	71.70001	%
01-08-0617 B106 M/R MAST PARA BEND STA 18				42786.73	0.00	IN-LB
01-09-0617 B103 M/R RED YOKE CHORD BEND				110712.18	0.00	IN-LB
01-10-0617 B105 M/R RED BLADE BEAM BEND				20842.76	-3039.00	IN-LB
01-11-0617 S253 L/H LONGERON STRESS				49639.97	0.00	PSI
01-12-0617 S252 T/B LOWER SKIN STRESS STA 219				49783.66	0.00	PSI
01-13-0483 R018 M/R AZIMUTH				0.00000	0.00000	

Page 45
 Rept 206-194-134

TABLE I

Sheet 4 of 4

Instrumentation Set-Up Sheet, S/N 5632

Purpose: Tailboom Failure Investigation

Chan.

No. Measured and Location

Purpose:	Tailboom Failure Investigation	Sta.	Lab No.	Flight: 100 K	Date: 10-9-71	Ref.
				C.E.		
1	M/R Blade Angle	7894	7894	14.65	deg	-
2	M/R Pitch Link, Red	5875B	876	1b	0	
3	M/R Mast Parallel Bending	5865D-06	10,830	in.1b	0	
4	M/R Mast Perpendicular Bending	5865D-03	7082	in.1b	0	
5	Center of Gravity Vertical Accel.	14699	1.09	g	1.0	
6	90° Gear Box Vertical Acceleration	16950	4.748	g	1.0	
7	90° Gear Box Lateral Acceleration	5566	4.783	g	0	
8	Tailboom Skin Vertical Stress	228	7916A	16,768	psi	-
9	Tailboom Skin Lateral Stress		7916A	16,768	psi	-
10	R/H Longeron Stress		7915	16,768	psi	-
11	Ground Contact Indicator		-	-	-	-
12	Throttle Chop Event		-	-	-	-
13	M/R Azimuth		-	-	-	-

BY _____
CHECKED _____BELL HELICOPTER COMPANY
POST OFFICE BOX 482 • FORT WORTH, TEXASMODEL OH-58A PAGE 46
RPT 206-194-134

Sheet 1 of 2

TABLE <u>II</u>					
LOG OF FLIGHTS					
G. R. No.	Flt No.	Date	Time (hr)	G. W. (lb)	C. G. Sta.
OH-58A S/N 41080					Configuration/Purpose
1		9-20	0.3		Shakedown after build-up.
2A		9-21	0.3		To record data of rotor, pylon and airframe loads during rpm and collective sweeps.
2B		9-21	0.5		"
2C		9-21	0.5		"
3A		9-24	0.7		"
3B		9-24	0.4		"
4A		9-27	0.4		To obtain data of airframe and rotor vibrations during ground run.
4B		9-27	0.3		
1A		9-29	0.2	2710	109.9
1B		9-29	0.6	2710	109.9
1C		9-29	0.4	2710	109.9
1D		9-29	0.7	2710	109.9
2A		9-30	0.2	2710	109.9
2B		9-30	0.3	2710	109.9
3A		10-1	0.3	2710	109.9
OH-58A S/N 41155					Tailboom failure occurred.
1		10-14			
1		10-15	0.5	3000	109.1
2		10-19	1.4	2986	109.6

Shakedown after instrumentation changes.
 Record rotor rpm decay rate at limited collective.

"

MODEL OH-58A PAGE 47
 RPT 206-194-134

Sheet 2 of 2

TABLE II
LOG OF FLIGHTS

G. R. No.	Fit No.	Date	Time (hr)	G. W. (lb)	C. G. Sta.	Configuration/Purpose
<u>OH-58A S/N 41155 - (cont)</u>						
3A	10-20	0.5	2986	109.6		Record and evaluate a series of autorotation landings with collective up stop restricted to 85% or 14.7° main rotor blade angle.
4	10-21	0.4	2712	108.6		Continue autorotation landings with reduced available collective.
5A	10-25	0.5	2984	109.6		Autorotation landing with collective stop reduced to 80%.
5B	10-25	0.9	2984	109.6		"
5C	10-25	0.1	2984	109.6		"
6	11-19	0.3	2700	108.5		Shakedown for USAASTA Evaluation. Standard collective bellcrank.
7A	11-23	0.1	2700	108.6		Shakedown.
7B	11-23	0.4	2700	108.6		USAASTA Evaluation.
7C	11-23	0.4	2700	108.6		USAASTA Evaluation with 80% collective available.
8A	11-24	0.1	3000	109.6		USAASTA height-velocity evaluation.
8B	11-24	0.8	3000	109.6		"

BY _____
CHECKED _____

BELL HELICOPTER COMPANY
POST OFFICE BOX 482 • FORT WORTH, TEXAS

MODEL OH-58A PAGE 48
RPT 206-194-134

BY _____	BELL HELICOPTER COMPANY POST OFFICE BOX 482 • FORT WORTH, TEXAS	MODEL OH-58A PAGE 49 RPT 206-194-134
CHECKED _____		

TABLE III
OSCILLOGRAPH PARAMETERS
S/N: 41155 MODEL: OH-58A FLIGHT: 5B DATE: 22 OCT. 71

RUN NO.	CTR. NO.	GROUND CONTACT GROUND SPEED ~ KTS	COLLECTIVE POSITION @ CONTACT ~ %	F/A CYCLIC POSITION @ CONTACT ~ %	N _R @ CONTACT ~ RPM	N _R @ LOWERED COLLECTIVE ~ RPM	% OF FLAPPING @ CONTACT ~ %	% OF FLAPPING @ LOWERED COLLECTIVE ~ %
10	924	18.53	57.7	37.9	258	144	± 32.0	± 16.2
11	925	28.10	57.7	41.3	264	138	± 32.0	± 17.6
12	926	25.46	80.4	52.8	228	186	± 64.8	± 13.5
13	927	29.30	70.1	54.5	228	198	± 62.2	± 18.9
14	928	18.53	80.4	44.6	225	132	± 62.2	± 21.6
15	929	32.26	78.3	53.7	240	132	± 62.1	± 32.4

OTHER INFORMATION:

GROSS WEIGHT 2936 TO 2891 LBS. DURING RUNS 10-15
GROUND LEVEL H_D 1380 FT.

GROUND LEVEL AMBIENT TEMP. 20°C

BY _____	BELL HELICOPTER COMPANY POST OFFICE BOX 482 • FORT WORTH, TEXAS	MODEL OH-58A PAGE 50 RPT 206-194-134
CHECKED _____		

TABLE IV (SHEET 1 OF 3)
FAA GRID CAMERA DATA

TAKE OFF DISTANCE LANDING DISTANCE HEIGHT VELOCITY
BELL S/N 41155 LOCATION: ARLINGTON, TEXAS

FLT. NO.	RUN NO.	OBS. TIME SEC.	OBS. DISTANCE		VERTICAL READING (GRADIENT CORR. (NOTE: 1) FT.)	CORR. TIME (NOTE: 2) SEC.	CORR. DISTANCE		REMARKS
			VERT.	HORIZ.			VERT.	HORIZ. (NOTE: 2) FT.)	
ARMY	6	10.04	121	6583	21.5	0	98.5	0	
A	1	10.84	120	6526	6	0.80	98.5	57	
		11.64	119	6468	.	1.60	97.5	115	
		12.44	118	6408	.	2.40	96.5	175	
		13.24	117.5	6334	.	3.40	96	249	
		14.04	117.5	6276	.	4.80	96	307	
		14.64	117.5	6247	.	4.60	96	326	LIGHT ON
		15.44	117	6188	.	5.40	95.5	395	
		16.24	116.5	6130	.	6.80	95	453	
		17.24	112.5	6057	.	7.20	91	526	
		18.24	98	5984	.	8.80	76.5	599	
		19.24	72	5911	.	9.20	50.5	672	
		20.84	48	5842	.	10.20	26.5	741	
		21.24	33	5781	.	11.20	14.5	802	
		22.04	30	5738	.	12.80	8.5	845	
		23.04	27.5	5705	.	13.20	6.0	878	
		24.24	22	5679	.	14.20	0.5	804	
		25.25	22	5637	1	15.21	0.5	827	
		25.65	21.5	5647	21.5	15.61	0	936	LIGHT OUT
		26.65	21.5	5628	.	16.61	0	955	
V	7	27.86	21.5	5614	.	17.82	0	969	
	6	28.47	21.5	5613	.	18.43	0	970	STOP
	7	15.88	106	6401	21.5	0	84.5	0	
1	16.68	107	6348	1	0.80	85.5	53		
		17.68	108	6283	.	1.80	86.5	118	
		18.68	109	6218	.	2.81	87.5	183	
		19.48	109.5	6164	.	3.41	88	237	
		20.10	109.5	6123	.	4.22	88	277	
		20.49	109.5	6087	.	4.61	88	304	LIGHT ON
		21.10	109	6055	.	5.22	87.5	326	
		22.10	105	5987	.	6.22	83.5	414	
		23.10	93.5	5919	.	7.22	72	482	
		24.10	69	5849	.	8.22	47.5	552	
		25.11	44	5780	1	9.23	22.5	621	
ARMY	7	26.11	32	5792	21.5	10.23	10.5	679	

NOTE: (1) CORRECTION OF READING (MAST) TO GROUND (SKID-GEAR): 9.5 FT.
PLUS RUNWAY GRADIENT CORRECTION (FIG.) USING THE
TOUCHDOWN POINT FOR HEIGHT VELOCITY AND LANDING AND THE
HOVER POINT FOR TAKE-OFF.

(2) CORRECTED TIME ZERO AND HORIZONTAL DISTANCE ZERO TO BE START OF
TAKE-OFF RUN, APPROX. 1 SEC. PRIOR TO THROTTLE CHOP FOR HT. VELOCITY,
AND ANY TIME PRIOR TO 50 FT. HEIGHT FOR LANDING.

BY _____

CHECKED _____

BELL HELICOPTER COMPANY
POST OFFICE BOX 461 FORT WORTH 1, TEXAS

MODEL OH-58A PAGE 52

RPT 206-194-134

TABLE IV

(SHEET 3 OF 3)

FAA GRID CAMERA DATA RUNWAY GRADIENT

TAKE OFF DISTANCE LANDING DISTANCE HEIGHT VELOCITY
 BELL S/N 41155 LOCATION ARLINGTON, TEXAS

FLT. NO.	RUN NO.	OBS. TIME SEC.	OBS. DISTANCE		VERTICAL READING (GRADIENT COFR. (NOTE: 1) FT.)	CORR. TIME ① SEC.	CORR. DISTANCE	REMARKS
			VERT.	HORIZ.			② + ④	VERT. ③ (NOTE: 2) FT.
ARMY	9		30	3850	6		24	3850
		1	29.5	4000	1		23.5	4000
		28	4150				22	4150
		26	4300				20	4300
		24	4450				18	4450 M
		23	4600				17	4600 1
		22.5	4750				16.5	4750 N
		21.5	4900				15.5	4900 V
		21	5000				15	5000
		20.5	5100				14.5	5100
		20	5200				14	5200 R
		19.5	5300				13.5	5300 D
		19	5400				13	5400 E
		18.5	5500				12.5	5500 V
		18.5	5600				12.5	5600 G
		18	5700				12	5700 P
		17.5	5800				11.5	5800 Q
		17	5900				11	5900 G
		16.5	6000				10.5	6000
		16.5	6100				10.5	6100
		16	6200				10	6200
		16	6300				10	6300
		15.5	6400				9.5	6400 N
		14.5	6500				8.5	6500 X
		14.5	6600				8.5	6600 U
		14	6700				8	6700 R
		13.5	6800	1			7.5	6800
ARMY	9	12.5	6850	6			7.5	6850

NOTE: (1) CORRECTION OF READING (MAST) TO GROUND (SKID-GEAR): ____ FT.
 PLUS RUNWAY GRADIENT CORRECTION (FIG. ____) USING THE
 TOUCHDOWN POINT FOR HEIGHT VELOCITY AND LANDING AND THE
 HOVER POINT FOR TAKE-OFF.

(2) CORRECTED TIME ZERO AND HORIZONTAL DISTANCE ZERO TO BE START OF
 TAKE-OFF RUN, APPROX. 1 SEC. PRIOR TO THROTTLE CHOP FOR HT. VELOCITY,
 AND ANY TIME PRIOR TO 50 FT. HEIGHT FOR LANDING.

DISTRIBUTION LIST

1 - Kelley/Lynn/Library
1 - Flight Test
1 - 206 Project
1 - Galerstein
3 - USAAVSCOM
5 - USAMC
1 - BPA
~~2~~ - DDC
12

