

AD A 051 294

AD L 4110 3

AD


2

TECHNICAL REPORT ARLCB-TR-77043

TEMPER. EMBRITTLEMENT IN 4140 SEAMLESS TUBING

Steve Tauscher
Peter Thornton

November 1977



US ARMY ARMAMENT RESEARCH AND DEVELOPMENT COMMAND
 LARGE CALIBER WEAPON SYSTEMS LABORATORY
 BENÉT WEAPONS LABORATORY
 WATERVLIET, N. Y. 12189

AMCMS No. 3111.16.2223

PRON No. M1-7-RN114-01-M7-1A

DDC
 RECEIVED
 MAR 16 1978

[Handwritten signature]

AD NO. _____
 DDC FILE COPY

APPROVED FOR PUBLIC RELEASE; DISTRIBUTION UNLIMITED.

DISCLAIMER

The findings in this report are not to be construed as an official Department of the Army position unless so designated by other authorized documents.

The use of trade name(s) and/or manufacturer(s) does not constitute an official indorsement or approval.

DISPOSITION

Destroy this report when it is no longer needed. Do not return it to the originator.

18 SBIE 19 AD-E400 080

1. REPORT NUMBER ARLCB-TR-77/47		2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER	
4. TITLE (and Subtitle) TEMPER EMBRITTLEMENT IN 4140 SEAMLESS TUBING			5. TYPE OF REPORT & PERIOD COVERED Technical report	
7. AUTHOR(s) 10 Steve Tauscher Peter Thornton			8. CONTRACT OR GRANT NUMBER(s)	
9. PERFORMING ORGANIZATION NAME AND ADDRESS Benet Weapons Laboratory Watervliet Arsenal, Watervliet, N.Y. 12189 DRDAR-LCB-TL			10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS AMCMS No. 3111.16.2223 PRON No. M1-7-RN114-01-M7-1A	
11. CONTROLLING OFFICE NAME AND ADDRESS US Army Armament Research and Development Command Large Caliber Weapon Systems Laboratory Dover, New Jersey 07801			12. REPORT DATE 11 Nov 77	
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)			13. NUMBER OF PAGES 20 p.	
			18. SECURITY CLASSIFICATION of this report UNCLASSIFIED	
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited.			15a. DECLASSIFICATION/DOWNGRADING SCHEDULE	
			DDC RECEIVED MAR 16 1978 REGULATORY B	
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)				
18. SUPPLEMENTARY NOTES				
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Split Ring Temper Embrittlement Transition Temperature				
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) In November 1976, several 155mm Howitzer M185 split rings failed during various stages of manufacture. A failure analysis consisting of metallography, SEM, and mechanical testing, was undertaken. This investigation concluded that the heat treatment was responsible for embrittling the steel, thereby causing the failures. Furthermore, it was shown that the required hardness could not be achieved without seriously compromising the toughness of this material. 470 224				

TABLE OF CONTENTS

	Page
Introduction	1
Procedure	4
Results and Discussion	5
Conclusions	15

LIST OF ILLUSTRATIONS

Figure

1 Overall View of Split Ring. Segment Removed for Analysis	2
2 SEM Fractograph of Cracked Split Ring Showing Intergranular Mode of Fracture	2
3 Microstructure for 1000°F Temper - 1000X	8
4 Grain Boundary Precipitates - 1000X	8
5 SEM Micrograph Displaying Grain Boundary Voids Due to Carbide Precipitates - 750°F Temper - 6000X	9
6 SEM Fractograph Showing Cleavage Failure Mode - 1000°F Temper - 960X	11
7 SEM Fractograph Showing Cleavage and Intergranular Failure Modes - 750°F Temper - 900X	11
8 SEM Fractograph Showing Ductile Failure Mode - 1000°F Temper - 500X	12
9 SEM Fractograph Showing Ductile Failure Mode - 750°F Temper - 500X	12
10 Tempering Response of 4140 Steel	14

LIST OF TABLES

Table

1 Mechanical Properties	6
2 Chemical Analysis	6
3 Tempering Temperature Summary for 4140 Steel	13

File Section	<input checked="" type="checkbox"/>
Ref Section	<input checked="" type="checkbox"/>
PROPERTY CODES	
or SPECIAL	

A

INTRODUCTION

In early November 1976, several 155mm M185 split rings (Fig. 1) fabricated from SAE 4140 steel seamless tubing cracked during various stages of their manufacture. In all reported failures, the rings had been heat treated and "kinked", an operation whereby the component is plastically deformed and acquires a considerable residual tensile stress. This stress is necessary for the subsequent operation of the component.

Preliminary investigations revealed that the rings were of high hardness (R_c 49-51 versus R_c 43-48 specified) and had fractured in a brittle manner. The heat treatment specified a temper of 750°F (399°C) which is within the known temper embrittlement range for this alloy. SEM fractography revealed the primary mode of fracture to be intergranular (Fig. 2). This examination also revealed that the fracture likely initiated at a stringer-type non-metallic inclusion which intersected the metal surface. Accordingly, a metallographic inspection of a mounted specimen taken from the ring showed the microstructure to contain numerous stringers of non-metallic inclusions as well as globules of a second phase material (most likely carbide precipitates) in the grain boundaries. Surprisingly though, these grain boundary precipitates were not observed on the fracture surface during the scanning electron microscopy (SEM) examination.




Figure 1. Overall view of split ring: Segment removed for analysis.




Figure 2. SEM fractograph of cracked split ring showing intergranular mode of fracture.

Nevertheless, temper embrittlement was suspected, as this phenomenon manifests itself as a loss of toughness in a steel and a tendency to fracture along prior austenitic grain boundaries¹. In some cases, this embrittlement is viewed to be a manifestation (the result of a buildup) of impurities (such as Sb, Sn, a, P or Se) along grain boundaries as a result of the rejection of these elements from carbide precipitates in the boundaries². These characteristics of temper embrittlement (which parallel the previously mentioned conditions found in the steel) coupled with the fact that the components were tempered within a known embrittling range for SAE 4140 steel strongly suggested that temper embrittlement was indeed responsible for the failures.

An experiment was undertaken to fully assess the effects of tempering on the mechanical properties of this material and determine if the current thermal treatment was responsible for embrittling the steel. This work, accompanied by metallographic and SEM fractography of the fracture surface of test specimens established the susceptibility of SAE 4140 seamless tubing to embrittlement at various tempering temperatures.

-
1. McMahon, C.J., "Temper Embrittlement of Steel", ASM, 1964, p. 127
 2. Rellick, J.R. and McMahon, J., "Intergranular Embrittlement of Iron-Carbon Alloys by Impurities", METALLURGICAL TRANSACTIONS, 1974, vol. 5, p. 2449.

PROCEDURE

A section of the 4140 seamless tubing was cut into disks for tensile and Charpy impact (CVN) test coupons. These coupons were divided into five sets, each to receive a different tempering treatment. Each set was austenitized at 1550°F (843°C) for 1-1/2 hours immediately followed by an oil quench. The specimens were tempered for two hours as follows:

<u>Group</u>	<u>Tempering Temperature °F(°C)</u>	<u>Quench Method</u>
I	500 (260)	Water
II	600 (316)	Water
III	750 (399)	Air
IV	750 (399)	Water
V	800 (427)	Water
VI	900 (482)	Water
VII	1000 (538)	Water

Group III was considered the control group in the experiment as it approximates the reported heat treatment that the rings receive in manufacturing.

Impact tests (according to ASTM spec. A370-72a) were conducted over a temperature range from -150°F (-101°C) to +212°F (100°C) to obtain the ductile to brittle fracture transition behavior for each tempered condition. The impact toughness data were then plotted versus testing temperature for each of the five heat treatments. These graphs allow a reasonably accurate estimate of the transition temperature (T.T.), where the steel exhibits a change in fracture mode from ductile

to brittle. Ductile failure implies a mechanism where considerable energy is absorbed while a brittle failure process absorbs relatively little energy.

RESULTS AND DISCUSSION

The results of the mechanical property tests and chemical analysis are summarized in Tables 1 and 2. As expected, the transition temperature increased with decreasing tempering temperature. In fact, the T.T. was above room temperature for tempers of 800°F (427°C) and below. This is very undesirable and it is evident that the required hardness level in this alloy will consistently result in a high T.T. As a consequence, once a crack is initiated in this material, it meets very little resistance in propagating through the component as long as an applied stress is present. In this situation, the stress is available from the kinking operation which plastically deforms the material and results in a high residual stress in the piece. The tempers of 900°F (482°C) and 1000°F (538°C) markedly improved the T.T. property but did not meet the required hardness specification of R_c 43-48. Also, the -40° Charpy impact properties for the 750°F (399°C), 800°F (427°C) tempering temperatures were poor (6-6.5 ft-lbs). Again, the 900°F (482°C) and 1000°F (538°C) tempers improved this but, as previously mentioned, did not meet the hardness specification given for the split ring components.

TABLE 1. MECHANICAL PROPERTIES

TEMPERING TEMPERATURE °F(°C)	DUCTILE TO BRITTLE TRANSITION TEMP. °F(°C)	HARDNESS Rc	YIELD STRENGTH 0.1% (ksi)	-40°F CHARPY IMPACT(ft-lb)	K _{Ic} * (ksi-in ^{1/2})
500 (260)	200 (93)	50.5	219.1	3.5	-
600 (316)	200 (93)	49.0	209.1	3.2	-
750 (399)	94 (34)	45.5	203.8	6.5	36.5
750 (399)	82 (28)	46.0	201.0	6.5	44.3
800 (427)	74 (23)	44.0	185.4	6.0	79.0
900 (482)	18 (-8)	40.0	176.4	12.0	99.3
1000 (538)	-72 (-58)	37.0	150.8	24.5	128.7

*Predicted fracture toughness based on correlation of Barsom and Rolfe.

TABLE 2. CHEMICAL ANALYSIS

C	Mn	Si	Cr	Mo	Sb	Sn
.38	.84	.23	.98	.23	.08	trace

An estimate of fracture toughness for the thermal treatments was determined via a correlation of Barsom and Rolfe from the "high energy" impact toughness data³. As shown in Table 1, the 750°F (399°C) and 800°F (427°C) tempers produce poor fracture toughness properties with systematic improvements achieved by the 900°F (482°C) and 1000°F (538°C) tempers. This indicates that the stress necessary to cause failure and/or the defect size necessary to initiate a fracture is decreasing with lower tempering temperature. As previously mentioned, this steel contained numerous stringer type non-metallics which can act in the manner of a crack or flaw. The overall result is a material whose ability to resist crack initiation and propagation is seriously impaired.

Metallographic examination revealed a martensitic microstructure in all five heats as shown in Figure 3. This examination also revealed the presence of a precipitate in the grain boundaries (Figure 4). SEM examination complemented the optical microscopy by revealing the nodular voids left by chemically removing carbides from the austenitic grain boundaries (Figure 5).

3. Barsom, J. M., and Rolfe, S. T., "Impact Testing of Metals," STP 466, 1970.



Figure 3. Microstructure for 1000°F temper - 1000X.



Figure 4. Grain boundary precipitates - 1000X.




Figure 1. TEM micrograph displaying grain boundary
voids due to carbide precipitates - 750°F
temp. - 000X.

Fractographic examination of broken CVN bars indicates the increasing tendency towards "low energy" intergranular failure as opposed to "low energy" cleavage failure as the tempering temperature is lowered. The 1000°F (538°C) temper displays quasi-cleavage as the principal mode of failure (Figure 6). This mode, however, changes to a mixed mode of intergranular and quasi-cleavage in the 750°F (390°C) temper (Figure 7). The high energy mode of failure for both tempers was ductile fracture by microvoid coalescence (Figures 8-9).

It is important to note that the high hardness of the split rings investigated was obviously not achieved using the reported heat treatment the rings undergo. This was substantiated by conducting a series of heat treatments at lower tempering temperatures. Table 3 reveals the actual tempering temperature required to obtain Rc 50 hardness (in this steel) to be approximately 500°F (200°C) as opposed to the 750°F (399°C) temper reportedly given the split rings. The tempering response for 4140 steel is plotted in Figure 10.

The results of this investigation show 4140 steel tubing to be embrittled by the current tempering practice of 750°F - (399°C) air cool. Unfortunately, higher tempering temperatures will not yield the desired hardness level in this steel. Therefore, it is apparent that this particular lot of 4140




Figure 6. SEM fractograph showing cleavage failure mode - 1000°F temper - 960X.



Figure 7. SEM fractograph showing cleavage and intergranular failure modes - 750°F temper - 900X.



Figure 8. SEM fractograph showing ductile failure mode - 1000°F temper - 500X.



Figure 9. SEM fractograph showing ductile failure mode - 750°F temper - 500X.

TABLE 3. TEMPERING TEMPERATURE SUMMARY FOR 4140 STEEL

<u>Tempering Temperature °F (°C)</u>	<u>Hardness (R_C)</u>
1000 (538)	36
900 (482)	40
800* (427)	44
750* (399)	46
650* (343)	47.5
600 (316)	49
500 (260)	50.5
400 (204)	53
300 (149)	55

As Quenched

*Tempers which meet hardness specification R_C 43-48




Figure 10. Tempering response of 4140 steel.

tubing will not adequately meet all the requirements imposed on the split ring. This is partially a consequence of material cleanliness (numerous, large stringers) and heat treatment. Since 4140 steel has been used successfully in this application for previous split rings, it is likely that one or more of the factors involved, viz., non-metallics, residual stress, embrittling precipitates, etc., was not present in a critical capacity previously. However, this is a probabilistic situation and obviously can be easily upset by subtle changes in the variables.

CONCLUSIONS

1. SAE-4140 steel, tempered at 750°F and 800°F, exhibited relatively high ductile to brittle transition temperatures (72°F (22°C), 94°F (34°C) resp.) and low Charpy impact (-40°F) properties (6, 6.5 ft-lbs. resp.). The 1000°F and 900°F tempers improved both properties but failed to meet the split ring hardness specification.

2. The estimated fracture toughness of this steel decreases with lower tempering temperatures and is seriously degraded by the 750°F tempering treatment.

3. The microstructure was tempered martensite which contained numerous non-metallic stringers as well as a network

of carbide precipitate in the austenitic grain boundaries.

4. In the presence of high residual stress, SAE 4140 should not be used in this case unless the hardness requirement can be lowered. Otherwise, a change of alloy should be considered. Some potential candidates include; 4330 + V (Vac Arc), "Hy-Tuf" (7-550°F), 18% Ni MARAGE (200 or 250 Grade).

WATERVLIET ARSENAL INTERNAL DISTRIBUTION LIST

May 1976

	<u>No. of Copies</u>
COMMANDER	1
DIRECTOR, BENET WEAPONS LABORATORY	1
DIRECTOR, DEVELOPMENT ENGINEERING DIRECTORATE	1
ATTN: RD-AT	1
RD-MR	1
RD-PE	1
RD-RM	1
RD-SE	1
RD-SP	1
DIRECTOR, ENGINEERING SUPPORT DIRECTORATE	1
DIRECTOR, RESEARCH DIRECTORATE	2
ATTN: RR-AM	1
RR-C	1
RR-ME	1
RR-PS	1
TECHNICAL LIBRARY	5
TECHNICAL PUBLICATIONS & EDITING BRANCH	2
DIRECTOR, OPERATIONS DIRECTORATE	1
DIRECTOR, PROCUREMENT DIRECTORATE	1
DIRECTOR, PRODUCT ASSURANCE DIRECTORATE	1
PATENT ADVISORS	1

EXTERNAL DISTRIBUTION LIST

December 1976

1 copy to each

OFC OF THE DIR. OF DEFENSE R&E
ATTN: ASST DIRECTOR MATERIALS
THE PENTAGON
WASHINGTON, D.C. 20315

CDR
US ARMY TANK-AUTMV COMD
ATTN: AMDTA-UL
AMSTA-RKM MAT LAB
WARREN, MICHIGAN 48090

CDR
PICATINNY ARSENAL
ATTN: SARPA-TS-S
SARPA-VP3 (PLASTICS
TECH EVAL CEN)
DOVER, NJ 07801

CDR
FRANKFORD ARSENAL
ATTN: SARFA
PHILADELPHIA, PA 19137

DIRECTOR
US ARMY BALLISTIC RSCH LABS
ATTN: AMXBR-LB
ABERDEEN PROVING GROUND
MARYLAND 21005

CDR
US ARMY RSCH OFC (DURHAM)
BOX CM, DUKE STATION
ATTN: RDRD-IPL
DURHAM, NC 27706

CDR
WEST POINT MIL ACADEMY
ATTN: CHMN, MECH ENGR DEPT
WEST POINT, NY 10996

CDR
HQ, US ARMY AVN SCH
ATTN: OFC OF THE LIBRARIAN
FT RUCKER, ALABAMA 36362

CDR
US ARMY ARMT COMD
ATTN: AMSAR-PPW-IR
AMSAR-RD
AMSAR-RDG
ROCK ISLAND, IL 61201

CDR
US ARMY ARMT COMD
FLD SVC DIV
ARMCOM ARMT SYS OFC
ATTN: AMSAR-ASF
ROCK ISLAND, IL 61201

CDR
US ARMY ELCT COMD
FT MONMOUTH, NJ 07703

CDR
REDSTONE ARSENAL
ATTN: AMSMI-RRS
AMSMI-RSM
ALABAMA 35809

CDR
ROCK ISLAND ARSENAL
ATTN: SARRI-RDD
ROCK ISLAND, IL 61202

CDR
US ARMY FGN SCIENCE & TECH CEN
ATTN: AMXST-SD
220 7TH STREET N.E.
CHARLOTTESVILLE, VA 22901

DIRECTOR
US ARMY PDN EQ. AGENCY
ATTN: AMXPE-MT
ROCK ISLAND, IL 61201

EXTERNAL DISTRIBUTION LIST (Cont)

1 copy to each

CDR
US NAVAL WPNS LAB
CHIEF, MAT SCIENCE DIV
ATTN: MR. D. MALYEVAC
DAHLGREN, VA 22448

DIRECTOR
NAVAL RSCH LAB
ATTN: DIR. MECH DIV
WASHINGTON, D.C. 20375

DIRECTOR
NAVAL RSCH LAB
CODE 26-27 (DOCU LIB.)
WASHINGTON, D.C. 20375

NASA SCIENTIFIC & TECH INFO FAC
PO BOX 8757, ATTN: ACQ BR
BALTIMORE/WASHINGTON INTL AIRPORT
MARYLAND 21240

DEFENSE METALS INFO CEN
BATTELLE INSTITUTE
505 KING AVE
COLUMBUS, OHIO 43201

MANUEL E. PRADO / G. STISSER
LAWRENCE LIVERMORE LAB
PO BOX 808
LIVERMORE, CA 94550

DR. ROBERT QUATTRONE
CHIEF, MAT BR
US ARMY R&S GROUP, EUR
BOX 65, FPO N.Y. 09510

2 copies to each

CDR
US ARMY MOB EQUIP RSCH & DEV COMD
ATTN: TECH DOCU CEN
FT BELVOIR, VA 22060

CDR
US ARMY MAT RSCH AGCY
ATTN: AMXMR - TECH INFO CEN
WATERTOWN, MASS 02172

CDR
WRIGHT-PATTERSON AFB
ATTN: AFML/MXA
OHIO 45433

CDR
REDSTONE ARSENAL
ATTN: DOCU & TECH INFO BR
ALABAMA 35809

12 copies

CDR
DEFENSE DOCU CEN
ATTN: DDC-TCA
CAMERON STATION
ALEXANDRIA, VA 22314

NOTE: PLEASE NOTIFY CDR, WATERVLIET ARSENAL, ATTN: SARWV-RT-TP,
WATERVLIET, N.Y. 12189, IF ANY CHANGE IS REQUIRED TO THE ABOVE.