

AD-A058 847


NEW JERSEY STATE DEPT OF ENVIRONMENTAL PROTECTION TRENTON F/6 13/2
NATIONAL DAM SAFETY PROGRAM. WESTONS MILLS ARCH DAM (NJ 00382),--ETC(U)
AUG 78 F K JOLLS

DACW61-78-C-0124

NL

UNCLASSIFIED

1 of 1
AD
A058 847



END
DATE
FILMED
-11-78
DDC

Approved for public release;
distribution unlimited

LEVEL

(1)

RARITAN RIVER BASIN

LAWRENCE BROOK, MIDDLESEX COUNTY

NEW JERSEY


WESTONS MILLS ARCH DAM

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

AD A058847

DDC FILE COPY

NJ 00382



DEPARTMENT OF THE ARMY
PHILADELPHIA DISTRICT, CORPS OF ENGINEERS
CUSTOM HOUSE - 2D & CHESTNUT STREETS
PHILADELPHIA, PENNSYLVANIA 19106

005 223

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER NJ00382	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Inspection Report National Dam Safety Program Westons Mills Arch Dam Middlesex County, N.J.		5. TYPE OF REPORT & PERIOD COVERED (9) FINAL rept.
7. AUTHOR(s) F. Keith Jolls P.E.		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS Louis Berger & Associates Inc. 100 Halsted St. East Orange, N.J.		8. CONTRACT OR GRANT NUMBER(s) DACW61-78-C-0124
11. CONTROLLING OFFICE NAME AND ADDRESS U.S. Army Engineer District, Philadelphia Custom House, 2d & Chestnut Streets Philadelphia, Pennsylvania 19106		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS (12) 64p.
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		12. REPORT DATE Aug 78
		13. NUMBER OF PAGES
		15. SECURITY CLASS. (of this report) Unclassified
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited. National Dam Safety Program. Westons Mills Arch Dam (NJ00382), Raritan River Basin, Lawrence Brook, Middlesex County, New Jersey. Phase I. Inspection Report.		
17. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited. National Dam Safety Program. Westons Mills Arch Dam (NJ00382), Raritan River Basin, Lawrence Brook, Middlesex County, New Jersey. Phase I. Inspection Report.		
18. SUPPLEMENTARY NOTES Copies are obtainable from National Technical Information Service, Springfield, Virginia, 22151.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dams--New Jersey National Dam Safety Program Phase I Dam Safety Westons Mills Arch Dam N.J.		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report cites results of a technical investigation as to the dam's ade- quacy. The inspection and evaluation of the dam is as prescribed by the National Dam Inspection Act, Public Law 92-367. The technical investigation includes visual inspection, review of available design and construction records, and preliminary structural and hydraulic and hydrologic calculations, as applicable. An assessment of the dam's general condition is included in the report.		

DDC
RECEIVED
SEP 19 1978
F

NOTICE

THIS DOCUMENT HAS BEEN REPRODUCED
FROM THE BEST COPY FURNISHED US BY
THE SPONSORING AGENCY. ALTHOUGH IT
IS RECOGNIZED THAT CERTAIN PORTIONS
ARE ILLEGIBLE, IT IS BEING RELEASED
IN THE INTEREST OF MAKING AVAILABLE
AS MUCH INFORMATION AS POSSIBLE.

ACCESSION for	
NTIS	White Section <input checked="" type="checkbox"/>
DOC	B.M. Section <input type="checkbox"/>
UNANNOUNCED	<input type="checkbox"/>
DISTRIBUTION	
BY	
DISTRIBUTION/AVAILABILITY CODES	
01	SPECIAL
A	



IN REPLY REFER TO

NAPEN-D

DEPARTMENT OF THE ARMY
PHILADELPHIA DISTRICT, CORPS OF ENGINEERS
CUSTOM HOUSE - 2 D & CHESTNUT STREETS
PHILADELPHIA, PENNSYLVANIA 19106

Honorable Brendan T. Byrne
Governor of New Jersey
Trenton, New Jersey 08621

80 AUG 1978

Dear Governor Byrne:

Inclosed is the Phase I Inspection Report for Westons Mills Arch Dam in Middlesex County, New Jersey which has been prepared under authorization of the Dam Inspection Act, Public Law 92-367. A brief assessment of the dam's condition is given on the first four pages of the report.

Based on visual inspection, available records, calculations and past operational performance, Westons Mills Arch Dam, initially listed as a high hazard potential structure but reduced to a significant hazard potential structure as a result of this inspection, is judged to be in fair overall condition. However, the dam's spillway is considered seriously inadequate since 9 percent of the Spillway Design Flood (SDF) would overtop the dam. To insure adequacy of the structure, the following actions, as a minimum, are recommended:

a. The spillway's adequacy should be determined by a qualified professional consultant engaged by the owner using more precise and sophisticated methods procedures and studies within six months from the date of approval of this report. Any practicable remedial measures necessary to insure the adequacy of the spillway and to prevent overtopping should be initiated within calendar year 1979.

b. Within six months of the date of approval of this report, the owner should initiate necessary engineering studies to determine the foundation conditions and assess the structural stability of the dam. The studies should address the possible effects of the collapse of the dam downstream on the subject dam. These studies should also include a determination of the need to repair the destroyed sluice gate. Any remedial measures found necessary, should be initiated in calendar year 1979.

NAPEN-D

Honorable Brendan T. Byrne

c. During the next period of low flow, the reservoir should be drawn down as necessary to investigate the extent of spalling and surface deterioration of the concrete. Any remedial actions found necessary, should be initiated within six months of the drawdown.

d. Within one year of the date of approval of this report, the following actions should be initiated.

(1) Berms behind the abutments should be raised to at least abutment height and both the berms and abutments should be furnished with slope protection.

(2) Large debris and fallen trees should be removed from the upstream channel and reservoir.

(3) Initiate a system for recording operation and maintenance procedures.


A copy of the report is being furnished to Mr. Dirk C. Hofman, New Jersey Department of Environmental Protection, the designated State Office contact for this program. Within five days of the date of this letter, a copy will also be sent to Congressmen Frank Thompson, Jr. and Edward Patton of the Fourth and Fifteenth District, respectively. Under the provisions of the Freedom of Information Act, the inspection report will be subject to release by this office, upon request, thirty days after the date of this letter.

Additional copies of this report may be obtained from the National Technical Information Services (NTIS), Springfield, Virginia, 22161 at a reasonable cost. Please allow four to six weeks from the date of this letter for NTIS to have copies of the report available.

An important aspect of the Dam Safety Program will be the implementation of the recommendations made as a result of the inspection. We accordingly request that we be advised of proposed actions taken by the State to implement our recommendations.

Sincerely yours,

1 Incl
As stated


JAMES G. TON
Colonel, Corps of Engineers
District Engineer

Cy furn:
Mr. Dirk C. Hofman, P.E.
Department of Environmental Protection

WESTONS MILLS ARCH DAM (NJ00382)

CORPS OF ENGINEERS ASSESSMENT OF GENERAL CONDITIONS

This dam was inspected on 14 and 17 June 1978 and 19 July 1978 by Louis Berger and Associates, Inc. under contract to the State of New Jersey. The state, under agreement with the U. S. Army Engineer District, Philadelphia, had this inspection performed in accordance with the National Dam Inspection Act, Public Law 92-367.

Westons Mills Arch Dam, initially listed as a high hazard potential structure but reduced to a significant hazard potential structure as a result of this inspection, is judged to be in fair overall condition. However, the dam's spillway is considered seriously inadequate since 9 percent of the Spillway Design Flood (SDF) would overtop the dam. To insure adequacy of the structure, the following actions, as a minimum, are recommended:

a. The spillway's adequacy should be determined by a qualified professional consultant engaged by the owner using more precise and sophisticated methods, procedures and studies within six months from the date of approval of this report. Any practicable remedial measures necessary to insure the adequacy of the spillway and to prevent overtopping should be initiated within calendar year 1979.

b. Within six months of the date of approval of this report, the owner should initiate necessary engineering studies to determine the foundation conditions and assess the structural stability of the dam. The studies should address the possible effects of the collapse of the dam downstream on the subject dam. These studies should also include a determination of the need to repair the destroyed sluice gate. Any remedial measures found necessary, should be initiated in calendar year 1979.

c. During the next period of low flow, the reservoir should be drawn down as necessary to investigate the extent of spalling and surface deterioration of the concrete. Any remedial actions found necessary, should be initiated within six months of the drawdown.

d. Within one year of the date of approval of this report, the following actions should be initiated.

(1) Berms behind the abutments should be raised to at least abutment height and both the berms and abutments should be furnished with slope protection.

(2) Large debris and fallen trees should be removed from the upstream channel and reservoir.

(3) Initiate a system for recording operation and maintenance procedures.

APPROVED: _____

James G. Ton
JAMES G. TON
Colonel, Corps of Engineers
District Engineer

DATE: _____

30 Aug 78

PHASE I REPORT
NATIONAL DAM INSPECTION PROGRAM

Name of Dam Westons Mills Arch Dam NJ 00382

- State New Jersey
County Located Middlesex
Coordinates Lat.4029.0 - Long.7424.9
Stream Lawrence Brook
Date of Inspection 19 June 1978

ASSESSMENT OF
GENERAL CONDITIONS


Westons Mills Arch Dam is in fair condition but the spillway is seriously inadequate. Little engineering information is available and it is recommended that the owner provide, in the near future, detailed foundation investigations and engineering studies. Remedial actions recommended are:

- Construction of slope protection around the abutments.
- Removal of large debris in the upstream channel.


The spillway capacity for the downgraded significant hazard category is 8 percent of the design flood. No appreciable improvement can be made to the existing spillway capacity. A collapse of the Lower Dam 600 feet downstream could endanger the Westons Mills Arch Dam by causing a sweepout of the downstream channel riprap.



F. Keith Jolls P.E.
Project Manager



Rudolph Wrubel
Vice President, Engineering



JUNE 1978

OVERVIEW OF WESTONS MILLS ARCH DAM

TABLE OF CONTENTS

	<u>Page</u>
Assessment of General Conditions	
Overall View of Dam	
Section 1 - Project Information	1-4
Section 2 - Engineering Data	5-7
Section 3 - Visual Inspection	8-9
Section 4 - Operational Procedures	10
Section 5 - Hydraulic/Hydrologic	11-13
Section 6 - Structural Stability	14-15
Section 7 - Assessment/Recommendations/ Remedial Measures	16-18

FIGURES

- Figure 1 - Regional Vicinity Map
- Figure 2 - General Plan and Sections of Dam

APPENDIX

Check List - Visual Inspection	
Check List - Engineering Data	
Photographs	
Check List - Hydrologic and Hydraulic Data	
Computations	A1-A17

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM
NAME OF DAM: WESTONS MILLS ARCH DAM NJ 00382

SECTION 1 - PROJECT INFORMATION

1.1 GENERAL

a. Authority

This report is authorized by the Dam Inspection Act, Public Law 92-367, and has been prepared in accordance with contract FPM-36 between Louis Berger & Associates, Inc. and the State of New Jersey and its Department of Environmental Protection, Division of Water Resources. The State, in turn, is under agreement with the U.S. Army Corps of Engineers, Philadelphia to have this inspection performed.

b. Purpose of Inspection

The purpose of this inspection is to evaluate the structural and hydraulic condition of the Westons Mills Arch Dam and appurtenant structures, and to determine if the dam constitutes a hazard to human life or property.

1.2 DESCRIPTION OF PROJECT

a. Description of Dam and Appurtenances

Westons Mills Arch Dam is a unreinforced concrete arch dam with three sluice gates on the west end. Each gate consists of a 30 inch cast iron pipe with a hand cranked sluice gate bolted to its face. The spillway extends across the entire length of the crest. The crest of the dam is 200 feet long, with a radius of 160 feet. At each end there is a concrete abutment 24 feet by 10 feet with a top elevation 2.5 feet above the spillway

crest. The height from spillway crest to the downstream channel invert is about 9 feet.

b. Location

Westons Mills Arch dam is located at Westons Mills, in the City of New Brunswick, Middlesex County: 0.5 miles northwest of Interchange 9 of the New Jersey Turnpike. It is immediately south of the concrete arch bridge carrying Route 18 over Lawrence Brook.

c. Size Classification

The maximum height of the dam is approximately 17 feet and the conservation storage is estimated to be 1050 acre feet. Therefore the dam is in the intermediate size category.

d. Hazard Classification

The dam was originally classified as a high hazard by the Corps of Engineers but as a result of this inspection, it is recommended that it be downgraded to a significant hazard classification. The town of Westons Mills lies immediately downstream; however, the residential areas are approximately 20 to 30 feet above the elevation of the dam and should failure occur, it appears there would be only minor property damage, principally involving boating facilities. The bridge to the immediate north (on Burnet Street) which spans Lawrence Brook and the Route 18 bridge just below the dam would probably not be harmed should this dam fail.

e. Ownership

The dam is owned by the City of New Brunswick, City Hall, 78 Bayard Street, New Brunswick, New Jersey 08903.

f. Purpose of Dam

The dam is used to increase the reservoir capacity for the city water supply system.

g. Design and Construction History

Westons Mills Arch Dam was designed by F. W. Schwiers Co. and constructed by the B. C. Coon Construction Company of Luzerne, Pennsylvania. Construction was completed in January 1919.

h. Normal Operating Procedures

A water supply intake dam exists 600 feet downstream and the only operations carried on at Westons Mills Arch dam is to regulate the lower reservoir elevation during periods of low flow.

1.3 PERTINENT DATA

a. Drainage Area

The drainage area for the Westons Mills Arch Dam is 42.0 square miles.

b. Total spillway capacity at maximum pool elevation - 2290 c.f.s.

c. Elevation (M.S.L.)

Top of dam	-	21.09
Maximum pool	-	21.09
Recreation	-	18.43

d. Reservoir

Length of maximum pool	-	13500 feet
Length of recreation pool	-	12600 feet

e. Storage

Recreation pool	-	1050 acre feet
Top of dam	-	1600 acre feet

f. Reservoir Surface

Top of dam - 180 acres
Maximum pool - 180 acres
Recreation pool - 160 acres
Spillway crest - 160 acres

g. Dam

Type - Concrete arch dam
Length - 248 feet
Height - 17 feet (9 feet - spillway crest to downstream invert)
Top width - 3 feet
Zoning - No zoning information available

h. Diversion and Regulating Tunnel

None

i. Spillway

Type - narrow crest (radial)
Length of weir - 200 feet
Crest elevation - 18.43 feet

j. Regulating Outlets

Three 30 inch diameter pipes with sluice gates attached.

SECTION 2 - ENGINEERING DATA

2.1 DESIGN

The information available for review of the Westons Mills Arch Dam included:

- 1) Drawing entitled "Plan for Arched Dam" dated June 19, 1917, together with bidding documents and specifications (partially complete).
- 2) 1917-1919 correspondence between the City Engineer and the Consulting Engineer (numerous letters).
- 3) Partial stress calculations made by Consulting Engineer, F. W. Schwiers Jr. Co., 90 West Street, New York.
- 4) Photographs of dam during and after construction, 1918-1919.

2.2 CONSTRUCTION

The information regarding the original construction included photographs, progress reports and correspondence between the City Engineer and Consulting Engineer indicates the work was carried on in a controlled workmanlike fashion. The dam was built by the B. C. Coon Construction Company of Luzerne, Pennsylvania. An additional 18 inches of height was added to the contract plan height during construction when it was recorded that the rock bedding on which the dam is founded was located about one foot higher than the original plan elevation.

The dam immediately downstream was constructed prior to the study dam and replaced a wood structure which burned down.

2.3 OPERATION

See Section 4. An inspection was ordered by the New Jersey Bureau of Water Control in 1968 but according to Bureau correspondence of 3 August 1973 to Robert

C. Kane, City Engineer, the inspection had not been carried out as of that date. No records of subsequent inspections were located.

2.4 EVALUATION

a. Availability

The original engineering data reviewed indicates that the construction was carefully prosecuted and proper supervision was in evidence. Additional information required for a complete evaluation should include:

- 1) Concrete cores for strength evaluation.
- 2) Visual inspection (dewatering or with divers) of the dam foundations.

b. Adequacy

The concrete mix specified was 1:2.5:5 and in light of the visible portions viewed during the field inspection, was properly mixed and placed. No attempt was formulated in this phase regarding the present compressive strength. From a summary of quantities in the 1917 bid documents, the arch structure is not reinforced, hence shrinkage cracks could be expected in the arch ring.

The foundation conditions for this dam consist of a shallow depth of fine granular and fine grained material overlying shale bedrock. The dam is founded on the shale according to the design plans. It is unknown whether the base was keyed into the rock or cast directly on the surface.

The overburden soil is a silty sand to sandy silt with varying amounts of intermixed gravel. The depth to bedrock is estimated at less than ten feet and is described in general as thin to thick beds of soft shale, with occasional beds of fine-grained sandstone, all dipping gently to the northwest. The New Brunswick shales weather readily into small fragments and these quickly revert to silt and clay sized particles.

c. Validity

Based upon field observations, the existing engineering data appears valid insofar as the existing structure's configuration and condition. See Section 6 for comment on the structural stability regarding the width/height ratio.

SECTION 3 - VISUAL INSPECTION

3.1 FINDINGS

a. General

On-site inspections of the dam took place on June 14 and 27 and July 19, 1978. Although there are 1968 records of the NJDEP requesting the City of New Brunswick to inspect the dam, no evidence that this inspection was undertaken were available.

b. Dam

The concrete arch is in fairly good condition but appears to be stabilized to a considerable degree by heavy siltation and dumped riprap on both the upstream and downstream sides. There is evidence of minor reconstruction and asphalt patching of the berm on the upstream side of the west abutment. There was no evidence of major fractures, or pieces missing from the crest of the dam. The location or condition of construction joints in the crest arch are unknown as they were underwater at the time of inspection. There is considerable spalling and surficial deterioration of the exposed concrete. The 19 July reinspection was held to verify this condition and the material in the downstream channel.

c. Appurtenant Structures

One of the three 30 inch sluice gates appears to be destroyed but the remaining two are operable to control reservoir elevation for the water intake dam immediately downstream.

d. Reservoir Area

There is a fair amount of debris and several large fallen trees in both the upstream and downstream reservoirs. The Weston Mills Pond extends

several miles up Lawrence Brook to the dam at Farrington Lake but the reservoir width is quite restricted by the relatively steep natural banks and narrow stream channel. Much of the urban contiguous development is well above normal flood elevation.

Judging from the difficulty of access for dredging and the drainage, the inspection confirmed that the upstream reservoir is quite extensively silted.

e. Downstream Channel

The existing banks of lower reservoir between the two dams are also quite steep which, together with the Route 18 concrete arch bridge, seriously restrict the downstream channel hydraulic capacity. Immediately north of the lower dam, the flow is further restricted by a newer bridge (built in 1965) over Burnet Street.

3.2 EVALUATION

The major concern of the inspection team is the status of hydraulic conditions during periods of high flow and collapse possibilities should the dam immediately downstream rupture. From available photographs at the office of the City Engineer, the July 1975 flood did considerable damage to the lower dam water intake structure. Further structural investigation of the concrete spillway, jointery and foundations can only be made if the dam is dewatered (see Section 7).

SECTION 4 - OPERATIONAL PROCEDURES

4.1 PROCEDURES

Operational procedures were not observed by the inspection team. Because of the city water supply intake facilities at the dam immediately downstream, city personnel are normally on duty 24 hours a day. From discussions with the City Engineer, operational activity at the Westons Mills Arch dam consist primarily of periodic inspections and the removal of floating drift and debris when the sluice gates are adjusted to control the lower pool intake elevation. Water Department personnel also monitor the dam whenever there are major storms.

4.2 MAINTENANCE OF DAM

The dam is periodically inspected and repairs undertaken when required and funds are available. Several years ago, the dam was inspected by scuba divers and leaks were repaired. Additional riprap was also placed on the downstream side of the spillway.

4.3 MAINTENANCE OF OPERATING FACILITIES

The only operating facilities in use are the two 30 inch gate valves which are periodically inspected by the City.

4.4 DESCRIPTION OF WARNING SYSTEM

None exists except the monitoring by City personnel during major storms.

4.5 EVALUATION

The present operational procedures and safeguards during periods of heavy flows were deemed to be adequate.

SECTION 5 - HYDRAULIC/HYDROLOGIC

5.1 EVALUATION OF FEATURES

a. Design Data

Utilizing the Guidelines for the Safety Inspection of Dams, it has been determined that the dam at Westons Mills Arch Dam is intermediate in size and falls into the significant hazard category due to the presence of urban development immediately downstream. Accordingly, the spillway design flood (SDF) was determined to be one half the PMF and the inflow hydrograph was calculated from the probable maximum precipitation (PMP).

The entire 200' length of the arch dam functions as a spillway. Abutments on either side of the dam are 24 feet long and 2.5 feet higher than the spillway crest. The maximum discharge over the dam which does not overtop the abutments is 2290 cfs.

The PMF hydrograph for this drainage area was calculated using the SCS curvilinear unit hydrograph. Peak inflow to the reservoir for the PMF and 1/2 PMF was 62,000 cfs and 31,000 cfs respectively, indicating that the discharge capacity of the dam is significantly inadequate. The 1/2 PMF was routed through the reservoir and the discharge decreased insignificantly from 31,000 cfs to 29,000 cfs.

In accordance with Corps of Engineers, Philadelphia District, directives, the inflow hydrograph and flood routing was additionally derived utilizing the HEC-1 program. A slight reduction in the PMF and 1/2 PMF to 58,500 cfs and 29,200 cfs respectively was noted. Flood routing for 1/2 the PMF yielded a peak discharge of 27,340 cfs. Employing the routed SDF, the spillway discharge capacity will accommodate approximately 8% of the SDF.

Since the Lawrence Brook at this location is rather confined in a narrow channel between steep-sided banks, the overtopping discharge capacity was extrapolated to accommodate 1/2 the PMF. It was determined that a flood height 12 feet over the spillway crest (9.5 feet above the abutments) would result during a storm equivalent to 1/2 the PMF (assuming no tailwater control).

b. Experience Data

Although there is no recorded stream flow data immediately downstream from Westons Mills Arch Dam, there is a gaging station 4 miles upstream at the Farrington Dam. Log-Pearson type III flood frequency analyses were performed by the U.S. Geological Survey utilizing weighted WRC map skews on the historical data available from this station. The transposed 100 and 500-year floods are 5800 cfs and 9680 cfs respectively. Floods of these magnitudes would overtop the embankments by approximately 2.0 feet and 3.5 feet respectively. The period of record at Farrington is 50 years. Observations made by City personnel during the storm of July, 1975, (and confirmed by their photographs) indicate the river overtopped the embankments by about 2 to 3 feet. The only discerned damage resulting from that storm was some erosion of the west embankment. This area has since been backfilled with concrete slope protection.

c. Visual Observation

The most westerly of the three sluice gates is destroyed and the usefulness of the remaining sluices is inconsequential during the periods of high flow as they are submerged on both sides of the dam and would have little hydraulic capacity. Therefore, this dam has no drawdown capability.

d. Overtopping Potential

The spillway has a maximum capacity of 8% of the design flood (1/2 PMF) before overtopping the abutments and is clearly inadequate in the significant hazard category. As indicated above, 1/2 the PMF, when routed thru the reservoir, results in a overtopping of the dam by over 9 feet. There is hearsay evidence that this dam has been repeatedly overtopped in the past and the overtopping potential will continue to exist, regardless of the hazard category considered. Due to the present physical geometry, the overtopping potential cannot be related to hazard. However, it is felt that a failure of the dam would not significantly contribute to the downstream water surface elevation (hence the damage potential) as long as the lower dam does not collapse.

SECTION 6 - STRUCTURAL STABILITY

6.1 EVALUATION OF STRUCTURAL STABILITY

a. Visual Observations

The alignment of the concrete structure is plumb and true and no significant tilting or differential settlements were observed. It is noted that the entire spillway is continuously passing several inches of water hence close visual examination is limited.

b. Design and Construction Data

Referring to Section 2.4.b, only minor cracking and spalling were observed during the field check but because the structure is unreinforced, temperature, rib shortening and shrinkage cracks may be expected in the concrete arch. The reentrant corners of the abutments are deteriorated with the edges broken off but this is of minor consequence.

The original design computations for overturning and sliding stability were unavailable. Maximum concrete stresses appear to have been computed using a three foot hydraulic crest. Although there exists some knowledge of the engineering design techniques employed in 1917, the method actually used for deriving the stability of the dam is extremely questionable in view of the geometry of the structure. The height to base width ratio indicates that some arching action was taken into account in the original design but it appears to have been done on an intuitive basis rather than employing statical methods available in 1917. Based on the SDF head established in this study, the dam appears to be statically unstable and has a negative factor of safety. Without knowledge of the foundation

conditions, further stability investigations in this phase are conjectural.

If the dam is considered to be a gravity structure without arch action it is unstable. Its ability to sustain arch action is directly tied to the contact between the abutment and shale bedrock. Since the New Brunswick shales decompose readily when exposed to air and/or water; further geotechnical explorations must be made to evaluate its present rock supporting capability. It is thought that additional stability is being provided by the downstream face riprap.

c. Operating Records

Performance records are unavailable regarding the dam's stability under maximum loading conditions but it should be noted that the downstream New Brunswick water supply intake dam (just north of Route 18) maintains a tailwater within 4.5 to 5 feet of the spillway crest. The dam appeared to suffer little damage during the July 1975 flood.

d. Post Construction Changes

The only structural modification noted was the raising of the spillway crest by 18 inches during the initial construction (as noted in paragraph 2.2). There is evidence of patching on the structure and riprap has been placed by City forces a few years ago just below the spillway.

e. Seismic Stability

As the dam is located in Seismic Zone 1, little hazard exists from earthquake forces and the potential vulnerability is negligible. The inertial forces relating to Zone 1 earthquake coefficients should be taken into account in the structural analyses in further studies but from the consultant's experience with this type of dam geometry, it will have little effect on the calculated stability and factor of safety compliance relating to the shale foundations.

SECTION 7 - ASSESSMENTS/RECOMMENDATIONS/REMEDIAL MEASURES

7.1 DAM ASSESSMENT

a. Conditions

On the basis of the Phase I visual examination, the existing concrete dam appears to be in fair structural condition and functions adequately as part of the New Brunswick water supply system (although the spillway is extremely inadequate to pass the design flood). No detrimental findings, excepting the physical geometry/design characteristics which, in order to render a complete structural review and analysis, will require the further gathering of information and review, were revealed.

It is believed that the safety of this dam would be substantially decreased if the Lower Dam were to fail. This is due principally to the short 600 foot distance between them which maintains a tailwater on the study dam during overtopping flood conditions.

b. Adequacy of Information

The information gathered for Phase I is thought to be adequate but the available data is insufficient to fully evaluate the structural stability of the dam in detail. This will have to be done in further studies and will require geotechnical investigations of the foundation rock and visual inspection of the spillway and abutments.

c. Urgency

A collapse of the Lower Dam (north of Route 18) could endanger the integrity of the Westons Mills Arch dam by eventually causing a sweepout of the lower stream face channel bed fill material and riprap that is thought to presently help stabilize the dam.

Consequently, further investigations should be undertaken in the near future regarding the foundation conditions and stability of the dam.

d. Necessity for Further Study

The inspection indicates that improvements to the spillway are impractical although its capacity does not meet the requirements of the Recommended Guidelines for Safety Inspection of Dams, passing only 8 percent of the SDF. However, due to the unknown condition of the foundations and the concrete in the spillway structure, additional studies and structural analyses appear to be warranted.

7.2 RECOMMENDATIONS/REMEDIAL ACTIONS


a. Alternatives

Inasmuch as original stability analyses and design computations are unavailable and this dam is classified in the significant hazard category, it is recommended that further studies be undertaken regarding these aspects. It is recommended that the owner provide, at his own expense, stability computations, including a trial arch analysis, and additional investigative data on the foundation conditions. This information is considered essential to complete assess the continued stability and to determine if the dam constitutes a hazard to human life and property. Its structural condition is classified as questionable pending receipt of the further investigations.

Remedial measures recommended are the construction of concrete or riprap slope protection above and below the abutments and to remove the large debris presently in the upstream channel. The berms behind the abutments should be raised to at least the height of the abutments and protected.

b. O&M Maintenance and Procedures

Because the City of New Brunswick presently maintains a close monitoring of the Westons Mills Arch Dam, little is foreseen as improvements to O&M procedures. However, a check list should be developed for periodic maintenance inspections so records of conditions and repairs can be maintained.






FIGURE 2

SHEET 1

Check List
Visual Inspection
Phase 1

Name Dam Weston Mills Arch Dam County Middlesex State New Jersey Coordinators NJDEP

June 14, 19, 27

Date(s) Inspection July 19, 1978 Weather Clear Temperature 80°

Pool Elevation at Time of Inspection 18.6 M.S.L. Tailwater at Time of Inspection 14.0 M.S.L.

Inspection Personnel:

T. Chapter	K. Jolls
M. Carter	R. Lang
C. Hoffman	

K.F. Jolls Recorder

CONCRETE/MASONRY DAMS

SHEET 2

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SEEPAGE OR LEAKAGE	Unknown (entire spillway submerged)	Unreinforced concrete arch. There are some type of joints in structure (unknown)
STRUCTURE TO ABUTMENT/EMBANKMENT JUNCTIONS	Satisfactory. No seepage observed. Left embankment junction patched.	Berms behind abutments should be regraded up to abutment grade.
DRAINS	None	
WATER PASSAGES	None	
FOUNDATION	Unknown. Shale bedrock exists within 10-15 feet of ground. Steep banks indicate rock close to surface.	N. Brunswick Shale area.

CONCRETE/MASONRY DAMS

SHEET 3

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS CONCRETE SURFACES	Unknown in spillway. (Continuously submerged)	Concrete very old but only surface is eroded. Appears to be monolithically solid in interior. (Only abutments observed).
STRUCTURAL CRACKING	Unknown in spillway. (Continuously submerged)	
VERTICAL AND HORIZONTAL ALIGNMENT	Satisfactory. No differential settlement observed at top elevations.	Plans indicate foundation is on solid rock.
MONOLITH JOINTS	None observed.	
CONSTRUCTION JOINTS	Poor condition at abutments.	Joint deterioration not critical in abutments Spalling indicates concrete is not reinforced.

EMBANKMENT

SHEET 4

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS	N/A	Narrow berms at abutments. Except for slope protection, embankment minor concern re zoning and classification.
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	None	
SLOUGHING OR EROSION OF EMBANKMENT AND ABUTMENT SLOPES	Some erosion. Minor patching with concrete and asphalt at west abutment.	
VERTICAL AND HORIZONTAL ALIGNMENT OF THE CREST	N/A	
RIPPRAP FAILURES	Riprap dumped in channel. None behind abutments.	

EMBANKMENT

SHEET 5

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM	See page 2	
ANY NOTICEABLE SEEPAGE	No	
STAFF GAGE AND RECORDER	None	
DRAINS	None. Drains in concrete spillway only.	

OUTLET WORKS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	Unknown (continuously submerged)	
INTAKE STRUCTURE	3-30" Ø sluice gates.	2 gates operable. 1 vandalized. Temporary wood catwalk built over gates.
OUTLET STRUCTURE	30" Ø pipes (approximately 9' below spillway crest) at each gate.	
OUTLET CHANNEL	See page 7.	
EMERGENCY GATE	None	No drawdown capability.

UNCATED SPILLWAY

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE WEIR	Narrow crest (3' x 200') on 160' radius. Entire spillway built at same elevation.	Base width to height ratio small for gravity structure. Determine arching effect in further studies.
APPROACH CHANNEL	Natural stream channel confined by natural, rather steep river banks.	
DISCHARGE CHANNEL	See approach canal.	Stability depends on Lower Dam bridge. Danger of sweepout.
BRIDGE AND PIERS	None	

GATED SPILLWAY

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE SILL	N/A	
APPROACH CHANNEL	N/A	
DISCHARGE CHANNEL	N/A	
BRIDGE AND PIERS	N/A	
GATES AND OPERATION EQUIPMENT	N/A	

INSTRUMENTATION

VISUAL EXAMINATION MONUMENTATION/SURVEYS	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
	None	
OBSERVATION WELLS	None	
WEIRS	None	
PIEZOMETERS	None	
OTHER	There is a gage at Farrington dam (4 miles upstream).	Current records are available. New Jersey Water Resources U.S.G.S. Survey NJ-76-1.

RESERVOIR

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SLOPES	Length extends up Lawrence River approximately 5 miles. Slopes are steep in many areas.	Flow thru reservoir restricted by bridge at Ryder's Lane.
SEDIMENTATION	Unknown. Heavily silted up in upper reaches of pond but not near dam.	Difficult access due to residential areas for dredging and/or silt removal.

DOWNSTREAM CHANNEL

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONDITION (OBSTRUCTIONS, DEBRIS, ETC.)	Considerable debris (large trees) in channel.	Route 18 concrete arch bridge between study and lower dam. Minor hydraulic constriction.
SLOPES	Steep natural banks (rock apparently in close to surface).	Trees on sides in many areas.
APPROXIMATE NO. OF HOMES AND POPULATION	Very few homes in zones of flooding. There are boat basins and similar facilities below lower dam.	All residential areas are on sufficient high ground.

CHECK LIST
ENGINEERING DATA
DESIGN, CONSTRUCTION, OPERATION
WESTONS MILLS ARCH DAM

ITEM	REMARKS
PLAN OF DAM	Available for structural geometry; No details available.
REGIONAL VICINITY MAP	Available
CONSTRUCTION HISTORY	Partially available (photographs)
TYPICAL SECTIONS OF DAM	Available
HYDROLOGIC/HYDRAULIC DATA	Available at Farrington Dam gage
OUTLETS - PLAN	None
- DETAILS	
-CONSTRAINTS	
-DISCHARGE RATINGS	
RAINFALL/RESERVOIR RECORDS	Not available

ITEM	REMARKS
DESIGN REPORTS	Not available
GEOLOGY REPORTS	Not available
DESIGN COMPUTATIONS HYDROLOGY & HYDRAULICS DAM STABILITY SEEPAGE STUDIES	None available
MATERIALS INVESTIGATIONS BORING RECORDS LABORATORY FIELD	None available
POST-CONSTRUCTION SURVEYS OF DAM	None available
BORROW SOURCES.	Unknown

ITEM	REMARKS
MONITORING SYSTEMS	None
MODIFICATIONS	Unknown
HIGH POOL RECORDS	Not available
POST CONSTRUCTION ENGINEERING STUDIES AND REPORTS	None
PRIOR ACCIDENTS OR FAILURE OF DAM DESCRIPTION REPORTS	Not available
MAINTENANCE OPERATION RECORDS	Hearsay information from City of New Brunswick.

ITEM	REMARKS
------	---------

SPILLWAY PLAN

Available

SECTIONS


DETAILS

OPERATING EQUIPMENT
PLANS & DETAILS

None available



Downstream view of spillway



Dam downstream of study dam

CHECK LIST
HYDROLOGIC AND HYDRAULIC DATA
ENGINEERING DATA

DRAINAGE AREA CHARACTERISTICS: Area = 42.0 square miles

ELEVATION TOP NORMAL POOL (STORAGE CAPACITY): 18.43 (1050 acre-ft.)

ELEVATION TOP FLOOD CONTROL POOL (STORAGE CAPACITY): 21.09 (1600 acre-ft.)

ELEVATION MAXIMUM DESIGN POOL: 21.09

ELEVATION TOP DAM: 21.09

CREST: _____

- a. Elevation 18.43
- b. Type Narrow Crest Weir
- c. Width 3 ft.
- d. Length 200 ft.
- e. Location Spillover None
- f. Number and Type of Gates 3 - 18" Ø sluices

OUTLET WORKS: None

- a. Type _____
- b. Location _____
- c. Entrance inverts _____
- d. Exit inverts _____
- e. Emergency draindown facilities None

HYDROMETEOROLOGICAL GAGES: _____

- a. Type Water stage recorder
- b. Location Farrington Dam (4 mi. upstream)
- c. Records 1927 - present

MAXIMUM NON-DAMAGING DISCHARGE: 2290 c.f.s.

BY CH DATE 7-75

LOUIS BERGER & ASSOCIATES INC.

SHEET NO. A-1 OF

CHKD. BY DATE

Dam InspectionPROJECT J-225SUBJECT WARTON DAM - PRECIPITATION DATA FOR SYNTHETIC HYDROGRAPH

MPF HYDROGRAPH

Fig 1, P-29 Small Dams - Zone C - New Jersey

RMP 10 sq mi 6 hr duration = 2.6"

Fig 2, P-30 Zone C Drainage Area = 72 sq mi

Rainfall = $.87 \times 2.6 = 2.26$ "

Fig 4 Zone C Distribution of 6 hr rainfall

<u>Time</u>	<u>Dist %</u>	<u>Cumul.</u>	<u>ΔR</u>	<u>R Rearing</u>	<u>Rearing</u>	<u>Runoff</u>	<u>Δ Runoff</u>
	<u>of 6 hr</u>	<u>Runoff</u>		<u>(.87 x 2.6)</u>	<u>Cum.</u>	<u>C.F.S.</u>	
0.5	30	6.78	6.78	0.68	0.68	0	0
1.0	48	10.15	4.07	0.90	1.58	0.10	0.10
1.5	58	13.11	2.26	0.90	2.48	0.45	0.35
2.0	65	14.69	1.58	1.13	3.61	1.10	0.65
2.5	71	16.05	1.36	1.13	4.74	1.85	0.75
3.0	76	17.18	1.13	1.36	6.10	2.90	1.05
3.5	81	18.31	1.13	4.07	10.17	6.40	3.50
4.0	85	19.21	0.90	6.78	16.95	12.80	6.40
4.5	89	20.11	0.90	2.26	19.21	15.00	2.20
5.0	93	21.02	0.91	1.58	20.79	16.40	1.40
5.5	97	21.92	0.90	0.91	21.70	17.40	1.00
6.0	100	22.60	0.68	0.90	22.60	18.20	0.80

$$T_c = \left(\frac{L^2 \times C}{H} \right)^{0.385} \quad L = 11 \text{ mi.} \quad H = 70$$

$$T_c = 8.06 \text{ hr.}$$

$$T_p = \frac{D}{2} + 0.6 T_c = \frac{0.5}{2} + 0.6 (8.06) = 5.09 \text{ hr.}$$

$$T_b = 2.67 \times T_p = 13.58$$

$$q_p = \frac{484 \times A \times Q}{T_p} = 3094 \text{ cfs}$$

Above values utilized in derivation of synthetic hydrograph only.

BY _____ DATE _____

CHKD. BY _____ DATE _____

SUBJECT WESTONS MILL

DAM INSPECTION


HYDROGRAPH

PROJECT

C-222

(Triangular Method)

Ar



BY CH DATE 1-18

LOUIS BERGER & ASSOCIATES INC.

SHEET NO. A 3 OF

CHKD. BY _____ DATE _____

DAM INSPECTION

PROJECT C-222

SUBJECT WESTON MILL DAM

Location - on Lawrence Bk (Tributary of Raritan) at East Brunswick N.J.

Comp. 1917 Height = 17'± DRAINAGE AREA (PLANIMETERED) = 42.0 Mi²

Indicated Spillway L = 200' Q = 2290

Dam lies upstream from gravity dam which submerges all but about 6' of Weston Mill Dam.

AREA OF RECREATION POOL = 160 ACRES (PLANIMETERED) × AVG DEPTH (N. BRUNSWICK CITY DAM) = 1050 Acre

MIT Drawing available - Spillway

Shows 200' crest on 160' radius

Abutments 2.5' higher than crest ± 24' long

Abutments beyond dam - Foundation - ON ROCK

MA = 1600 "

A = 2.5' @ DAM

Size - Intermediate Hazard - Significant

Hydrograph 1/2 PMF to PMF

Log Pearson Frequency Q

(@ FARRINGTON DAM)

Area_{FARR} = $\frac{42.0}{34.1} = 1.22$


50 yr = 3770

100 yr = 4760 × 1.22 = 5800 cf

502 yr = 7930 × 1.22 = 9660 cf

TRANSPOSED
Q'S

Spillway discharges



over main crest - L = 200'

H	C	Q
0.5	2.9	205
1.0	2.9	580
1.5	2.9	1065
2.0	2.9	1640
2.5	2.9	2293
3.0	2.9	3014
3.5	2.9	3798
4.0	2.9	4640
5.0	2.9	6485
6.0	2.9	8525
8.0	2.9	13124
10.0	2.9	18341
12.0	2.9	24110
13.0	2.9	27185
14.0	2.9	30382

Over Abutments

H	C	Q	Total Q
			205
			580
			1065
			1640
0	2.5	0	2293
0.5	"	47	3061
1.0	"	134	3932
1.5	2.8	247	4887
2.5		531	7016
3.5		880	9405
5.5		1733	14857
7.5		2760	21100
9.5		3935	28045
10.5		4335	31380
11.5		5242	35624

Surcharge Capacity

Elevation Area Ave Area Δ Vol ± Vol

18.43

30

280

3240

3240

BY TS DATE 2-78 LOUIS BERGER & ASSOCIATES INC. SHEET NO. 11 OF 11
 CHKD. BY LAH DATE 11/25/85 PROJECT C-222
 SUBJECT Precipitation data for input to HEC-1

From "Small Dams":

PMF for 10 sq mi = 26" / 6 hr. ;

Reduction factor for 42 sq mi = 87%

thus: $.87 \times 26" = 22.6"$ rainfall

Zone C distribution of 6 hr rainfall

Time	Dist %	Cumul. R.	L.R.	R. Rearing	Rearing Cum.	Runoff S.N. 70	L. Runoff
1	48	10.85	10.85	1.58	1.58	0.10	0.10
2	65	14.69	3.84	2.03	3.61	1.10	1.0
3	76	17.18	2.49	2.49	6.10	2.90	1.8
4	85	19.21	2.03	10.85	16.95	12.80	9.9
5	93	21.02	1.81	3.84	20.79	16.40	3.6
6	100	22.60	1.58	1.81	22.60	18.2	1.8

$$T_c = \left(\frac{(11.9 \times L^2)^{.375}}{11} \right) \quad L = 1 \text{ mi.} \quad V = 70$$

$$T_c = 8.06 \text{ hr.}$$

Alternate determination of T_c per U.S. Army TR-55

$$\text{Channel slope} = \frac{70 \times 100}{11 \times 5280} = 0.12\%$$

min. avg. vel. for slopes $< 2\% = 2 \text{ ft/sec}$

$$\frac{11 \times 5280}{2 \times 3600} = 8.07 \text{ hr}$$

BY H.G. DATE _____

LOUIS BERGER & ASSOCIATES INC.

SHEET NO. A5 OF _____

CHKD. BY _____ DATE _____

WESTONS MILL DAMPROJECT C-222SUBJECT DIMENSIONLESS UNITGRAPH (1 HR)

$$\text{Unit Time } T_y = 1 \text{ hr}; \quad T_y = 5.09 \text{ hrs}; \quad L + \frac{D}{2} = \frac{5.09}{0.81} = 6.93 = T$$

$$\text{Area} = 26.89 \text{ mi}^2 \quad \text{DSF (2 in)} = 26.89 \times A = 1129.4$$

<u>Time</u>	<u>% T_y</u> <u>100/T_y (hr)</u>	<u>Dimensionless *</u> <u>Ordinate Q/T_yDSF</u>	<u>Q</u> <u>DSF/T_y (D.O.)</u>
1	14.43	0.9	147
2	28.85	4.2	684
3	43.29	9.2	1500
4	57.72	15.5	2526
5	72.15	19.6	3194
6	86.6	20.9	3406
7	101	19.6	3194
8	115	16.6	2705
9	130	13.2	2151
10	144	10.5	1711
11	159	8.2	1336
12	173	6.5	1059
13	188	5.0	815
14	202	3.8	619
15	216	3.0	489
16	231	2.28	372
17	245	1.68	274
18	260	1.3	212
19	274	1.0	163
20	289	0.78	127
21	303	0.6	95
22	317	0.4	65
23	332	0.3	49
24	346	0.28	45
25	361	0.23	38
26	375	0.2	33
27	390	0.17	27
28	404	0.14	23
29	418	0.11	18

* Value for Dimensionless Ordinate read from graph.

BY H. G. DATE _____

LOUIS BERGER & ASSOCIATES INC.

SHEET NO. A6

CHKD. BY _____ DATE _____

PROJECT C222

SUBJECT BUREAU OF RECLAMATION DEFINITION OF TERMS USED IN UNITGRA

L, LAG TIME AS DEFINED BY THE SCS IS THE TIME IN HOURS FROM THE MID OF EXCESS RAINFALL, TO THE TIME OF PEAK DISCHARGE.

L, LAG TIME AS DEFINED BY THE BUREAU OF RECLAMATION IS FROM THE CENTER OF MASS OF RAINFALL TO THE CENTER OF MASS OF RUNOFF.

E IS EQUAL TO $\left(\frac{11.9 L^3}{H}\right)^{0.385}$ FROM THE CALIFORNIA CULVERTS PRACTICE

SCS L IS APPROXIMATELY 0.6 T_c

EXAMPLES OF DETERMINING L (LAG) BY BUREAU OF RECLAMATION DEFINITION,

$$L = \frac{T_p - (D/2)}{0.85} \quad \text{WHERE } D \text{ IS THE TIME INTERVAL OF THE UNITG}$$

THE SCS CURVE LINEAR UNIT HYDROGRAPH CAN BE DERIVED BY FIRST TAKING BUREAU OF RECLAMATION L, (LAG) PLUS $\frac{D}{2}$ AFTER BEING DIVIDED BY 100, THEN

MULTIPLIED BY EACH ABSCISSA (IN HOURS) BY THE QUOTIENT. THEN READING THE DIMENSIONLESS ORDINATE FOR THE GIVEN PERCENTAGES FROM THE PREVIOUSLY DETERMINED SCS CURVE LINEAR DIMENSIONLESS GRAPH, (COPY ATTACHED)

TO OBTAIN Q IN CFS FOR EACH ORDINATE MULTIPLY EACH DIMENSIONLESS ORDINATE BY A FACTOR OBSERVED FOR ONE INCH,


$$26.89 \times \text{AREA}$$

A7

7.	0	1	2	3	4	5	6	7	8	9
0	60	60	61	61	62	62	63	63	63	64
10	64	65	66	67	67	68	68	69	69	70
20	70	71	72	73	74	74	75	76	76	77
30	77	78	79	80	81	81	82	83	84	84
40	85	86	87	88	89	90	90	91	92	93
50	94	95	96	97	98	99	100	101	102	103
60	104	105	106	107	108	109	110	111	112	113
70	114	115	116	117	118	119	120	121	122	123
80	124	125	126	127	128	129	130	131	132	133
90	134	135	136	137	138	139	140	141	142	143
100	144	145	146	147	148	149	150	151	152	153
110	154	155	156	157	158	159	160	161	162	163
120	164	165	166	167	168	169	170	171	172	173
130	174	175	176	177	178	179	180	181	182	183
140	184	185	186	187	188	189	190	191	192	193
150	194	195	196	197	198	199	200	201	202	203
160	204	205	206	207	208	209	210	211	212	213
170	214	215	216	217	218	219	220	221	222	223
180	224	225	226	227	228	229	230	231	232	233
190	234	235	236	237	238	239	240	241	242	243
200	244	245	246	247	248	249	250	251	252	253
210	254	255	256	257	258	259	260	261	262	263
220	264	265	266	267	268	269	270	271	272	273
230	274	275	276	277	278	279	280	281	282	283
240	284	285	286	287	288	289	290	291	292	293
250	294	295	296	297	298	299	300	301	302	303
260	304	305	306	307	308	309	310	311	312	313
270	314	315	316	317	318	319	320	321	322	323
280	324	325	326	327	328	329	330	331	332	333
290	334	335	336	337	338	339	340	341	342	343
300	344	345	346	347	348	349	350	351	352	353
310	354	355	356	357	358	359	360	361	362	363
320	364	365	366	367	368	369	370	371	372	373
330	374	375	376	377	378	379	380	381	382	383
340	384	385	386	387	388	389	390	391	392	393
350	394	395	396	397	398	399	400	401	402	403
360	404	405	406	407	408	409	410	411	412	413
370	414	415	416	417	418	419	420	421	422	423
380	424	425	426	427	428	429	430	431	432	433
390	434	435	436	437	438	439	440	441	442	443
400	444	445	446	447	448	449	450	451	452	453
410	454	455	456	457	458	459	460	461	462	463
420	464	465	466	467	468	469	470	471	472	473
430	474	475	476	477	478	479	480	481	482	483
440	484	485	486	487	488	489	490	491	492	493
450	494	495	496	497	498	499	500	501	502	503

SUMMARY OF HYDRAULIC CHARACTERISTICS

AS



BY TC DATE _____

LOUIS BERGER & ASSOCIATES INC.

SHEET NO. A9 OF _____

CHKD. BY _____ DATE _____

Dam InspectionPROJECT C-222SUBJECT Storage / Discharge Summary Sheet

<u>Elev (Ft. Above Crest)</u>	<u>Storage (Acrc ft.)</u>	<u>Discharge (cfs)</u>
1	275	580
2	550	1640
3	825	3061
4	1100	4887
5	1400	7016
6	1675	9405
7	1950	12750
8	2250	14857
9	2525	18600
10	2800	21100
11	3090	24500
12	3370	28045

FINAL RUN

THESEY VILVIL/4C/LVYII

NOTIFICATION - OF

	NO	NRE	NFIN	ICAY	IHR	IPIN	METRC	IPLI	IPRT	ASTAN
100		1	0	0	0	0	0	0	0	0

JOEY WAT

SUB-AREA RUNOFF COMPUTATION.

SECRET - NO FORN DISSEM

ISTAG	ICOMP	IECON	ITAPE	JPLY	JPRT	IVAME
5	0	0	0	2	0	1

HYDROGRAPH DATA

1995	1996	1997	1998	1999	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	2046	2047	2048	2049	2050	2051	2052	2053	2054	2055	2056	2057	2058	2059	2060	2061	2062	2063	2064	2065	2066	2067	2068	2069	2070	2071	2072	2073	2074	2075	2076	2077	2078	2079	2080	2081	2082	2083	2084	2085	2086	2087	2088	2089	2090	2091	2092	2093	2094	2095	2096	2097	2098	2099	2100	2101	2102	2103	2104	2105	2106	2107	2108	2109	2110	2111	2112	2113	2114	2115	2116	2117	2118	2119	2120	2121	2122	2123	2124	2125	2126	2127	2128	2129	2130	2131	2132	2133	2134	2135	2136	2137	2138	2139	2140	2141	2142	2143	2144	2145	2146	2147	2148	2149	2150	2151	2152	2153	2154	2155	2156	2157	2158	2159	2160	2161	2162	2163	2164	2165	2166	2167	2168	2169	2170	2171	2172	2173	2174	2175	2176	2177	2178	2179	2180	2181	2182	2183	2184	2185	2186	2187	2188	2189	2190	2191	2192	2193	2194	2195	2196	2197	2198	2199	2200	2201	2202	2203	2204	2205	2206	2207	2208	2209	2210	2211	2212	2213	2214	2215	2216	2217	2218	2219	2220	2221	2222	2223	2224	2225	2226	2227	2228	2229	2230	2231	2232	2233	2234	2235	2236	2237	2238	2239	2240	2241	2242	2243	2244	2245	2246	2247	2248	2249	2250	2251	2252	2253	2254	2255	2256	2257	2258	2259	2260	2261	2262	2263	2264	2265	2266	2267	2268	2269	2270	2271	2272	2273	2274	2275	2276	2277	2278	2279	2280	2281	2282	2283	2284	2285	2286	2287	2288	2289	2290	2291	2292	2293	2294	2295	2296	2297	2298	2299	2300	2301	2302	2303	2304	2305	2306	2307	2308	2309	2310	2311	2312	2313	2314	2315	2316	2317	2318	2319	2320	2321	2322	2323	2324	2325	2326	2327	2328	2329	2330	2331	2332	2333	2334	2335	2336	2337	2338	2339	2340	2341	2342	2343	2344	2345	2346	2347	2348	2349	2350	2351	2352	2353	2354	2355	2356	2357	2358	2359	2360	2361	2362	2363	2364	2365	2366	2367	2368	2369	2370	2371	2372	2373	2374	2375	2376	2377	2378	2379	2380	2381	2382	2383	2384	2385	2386	2387	2388	2389	2390	2391	2392	2393	2394	2395	2396	2397	2398	2399	2400	2401	2402	24
------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	----

PRECIP DATA

NO	STORM	DAJ	DAK
5	0.0	0.0	0.0

PRECIP PATTERN

LOSS DATA

STAGE	CLIP	RTOL	EPAT	STKS	RLOC	STATL	CNSTL	ALSMX	RTIMP
0.0	0.0	1.00	0.0	0.0	1.00	0.0	0.0	0.0	0.0
1.0	0.0	1.00	0.0	0.0	1.00	0.0	0.0	0.0	0.0

EVEN UNIT GRAPH. UJHGQ = 29

147.	484.	1800.	2225.	2154.	3406.	3194.	2705.	2151.	1711.
148.	1352.	215.	419.	649.	372.	274.	212.	163.	127.
149.	65.	40.	45.	24.	55.	27.	23.	18.	

RECEIVED MAY 19 1966

```

STRTC= 0.0      ZRCSN= 0.0      RTICR= 1.00

```

NOTES GOVERNMENT PRINTING OFFICE

TIME RAILY EXES COMD

15.

215.

1099.

4439.

12646.

25659 •

4111, •

53009. •

54434.

56022.

A 10

72	0.0	0.0	0.0	0.0
73	0.0	0.0	0.0	0.0
74	0.0	0.0	0.0	0.0
75	0.0	0.0	0.0	0.0
76	0.0	0.0	0.0	0.0
77	0.0	0.0	0.0	0.0
78	0.0	0.0	0.0	0.0
79	0.0	0.0	0.0	0.0
80	0.0	0.0	0.0	0.0
81	0.0	0.0	0.0	0.0
82	0.0	0.0	0.0	0.0
83	0.0	0.0	0.0	0.0
84	0.0	0.0	0.0	0.0
85	0.0	0.0	0.0	0.0
86	0.0	0.0	0.0	0.0
87	0.0	0.0	0.0	0.0
88	0.0	0.0	0.0	0.0
89	0.0	0.0	0.0	0.0
90	0.0	0.0	0.0	0.0
91	0.0	0.0	0.0	0.0
92	0.0	0.0	0.0	0.0
93	0.0	0.0	0.0	0.0
94	0.0	0.0	0.0	0.0
95	0.0	0.0	0.0	0.0
96	0.0	0.0	0.0	0.0
97	0.0	0.0	0.0	0.0
98	0.0	0.0	0.0	0.0
99	0.0	0.0	0.0	0.0
100	0.0	0.0	0.0	0.0

SUM 18.20 18.20 492854.

CEG	58434.	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
10-45		50135.	20278.	5845.	492854.
AC-17		11.10	10.05	18.19	18.19
		24372.	40440.	40753.	40753.

INFLOW(I), OUTFLOW(O) AND OBSERVED FLOW(O*)

[illegible]

A 13

INFLUX(I), OUTFLOW(O) AND OBSERVED FLOW(O)

[illegible]

A 14

STILLING COTTAGE

ITEM	QTY	UNIT	PRICE	TOTAL	TAX	STRT
ITEM 1	1	UNIT	0.00	0.00	0.00	0.00
ITEM 2	1	UNIT	0.00	0.00	0.00	0.00
ITEM 3	1	UNIT	0.00	0.00	0.00	0.00
ITEM 4	1	UNIT	0.00	0.00	0.00	0.00
ITEM 5	1	UNIT	0.00	0.00	0.00	0.00
ITEM 6	1	UNIT	0.00	0.00	0.00	0.00
ITEM 7	1	UNIT	0.00	0.00	0.00	0.00
ITEM 8	1	UNIT	0.00	0.00	0.00	0.00
ITEM 9	1	UNIT	0.00	0.00	0.00	0.00
ITEM 10	1	UNIT	0.00	0.00	0.00	0.00
ITEM 11	1	UNIT	0.00	0.00	0.00	0.00
ITEM 12	1	UNIT	0.00	0.00	0.00	0.00
ITEM 13	1	UNIT	0.00	0.00	0.00	0.00
ITEM 14	1	UNIT	0.00	0.00	0.00	0.00
ITEM 15	1	UNIT	0.00	0.00	0.00	0.00
ITEM 16	1	UNIT	0.00	0.00	0.00	0.00
ITEM 17	1	UNIT	0.00	0.00	0.00	0.00
ITEM 18	1	UNIT	0.00	0.00	0.00	0.00
ITEM 19	1	UNIT	0.00	0.00	0.00	0.00
ITEM 20	1	UNIT	0.00	0.00	0.00	0.00
ITEM 21	1	UNIT	0.00	0.00	0.00	0.00
ITEM 22	1	UNIT	0.00	0.00	0.00	0.00
ITEM 23	1	UNIT	0.00	0.00	0.00	0.00
ITEM 24	1	UNIT	0.00	0.00	0.00	0.00
ITEM 25	1	UNIT	0.00	0.00	0.00	0.00
ITEM 26	1	UNIT	0.00	0.00	0.00	0.00
ITEM 27	1	UNIT	0.00	0.00	0.00	0.00
ITEM 28	1	UNIT	0.00	0.00	0.00	0.00
ITEM 29	1	UNIT	0.00	0.00	0.00	0.00
ITEM 30	1	UNIT	0.00	0.00	0.00	0.00
ITEM 31	1	UNIT	0.00	0.00	0.00	0.00
ITEM 32	1	UNIT	0.00	0.00	0.00	0.00
ITEM 33	1	UNIT	0.00	0.00	0.00	0.00
ITEM 34	1	UNIT	0.00	0.00	0.00	0.00
ITEM 35	1	UNIT	0.00	0.00	0.00	0.00
ITEM 36	1	UNIT	0.00	0.00	0.00	0.00
ITEM 37	1	UNIT	0.00	0.00	0.00	0.00
ITEM 38	1	UNIT	0.00	0.00	0.00	0.00
ITEM 39	1	UNIT	0.00	0.00	0.00	0.00
ITEM 40	1	UNIT	0.00	0.00	0.00	0.00
ITEM 41	1	UNIT	0.00	0.00	0.00	0.00
ITEM 42	1	UNIT	0.00	0.00	0.00	0.00
ITEM 43	1	UNIT	0.00	0.00	0.00	0.00
ITEM 44	1	UNIT	0.00	0.00	0.00	0.00
ITEM 45	1	UNIT	0.00	0.00	0.00	0.00
ITEM 46	1	UNIT	0.00	0.00	0.00	0.00
ITEM 47	1	UNIT	0.00	0.00	0.00	0.00
ITEM 48	1	UNIT	0.00	0.00	0.00	0.00
ITEM 49	1	UNIT	0.00	0.00	0.00	0.00
ITEM 50	1	UNIT	0.00	0.00	0.00	0.00
ITEM 51	1	UNIT	0.00	0.00	0.00	0.00
ITEM 52	1	UNIT	0.00	0.00	0.00	0.00
ITEM 53	1	UNIT	0.00	0.00	0.00	0.00
ITEM 54	1	UNIT	0.00	0.00	0.00	0.00
ITEM 55	1	UNIT	0.00	0.00	0.00	0.00
ITEM 56	1	UNIT	0.00	0.00	0.00	0.00
ITEM 57	1	UNIT	0.00	0.00	0.00	

STAGE =	0	0	270	350	470	1110	1400	1675	3090	3370
CURLO =	0	0	500	1340	3051	4837	7015	7405	24000	24045

[illegible]

40	51.	0.	123.
41	43.	0.	103.
42	60.	0.	66.
43	53.	0.	72.
44	28.	0.	60.
45	28.	0.	51.
46	20.	0.	42.
47	17.	0.	35.
48	13.	0.	30.
49	12.	0.	25.
50	10.	0.	21.
51	8.	0.	17.
52	7.	0.	15.
53	6.	0.	12.
54	3.	0.	10.
55	4.	0.	9.
56	3.	0.	7.
57	3.	0.	6.
58	2.	0.	5.
59	2.	0.	4.
60	2.	0.	4.
61	1.	0.	3.
62	1.	0.	2.
63	1.	0.	2.
64	1.	0.	2.
65	1.	0.	1.
66	1.	0.	1.
67	0.	0.	1.
68	0.	0.	1.
69	0.	0.	1.
70	0.	0.	1.
71	0.	0.	0.
72	0.	0.	0.
73	0.	0.	0.
74	0.	0.	0.
75	0.	0.	0.
76	0.	0.	0.

246429.

ITEM	4-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CES	23546.	10045.	3423.	246429.
INCHES	5.24	8.90	9.10	9.10
AC-FI	11731.	19934.	20376.	20376.

STATION 55

INFLOW(I), OUTFLOW(O) AND OBSERVED FLOW(O*)

[illegible]

RUNOFF SUMMARY, AVERAGE FLOW

	PF4	6-HOUR	24-HOUR	72-HOUR	AREA
HYPERBOLIC	5	29217	25057	10189	42.60
ROULETTE	55	27339	23644	10045	42.00

A17