AD-	063 128	GAN NAT JUL	NETT FL	EMING	CORDOR	Y AND ON PROGR	ARPENT	ER INC	HARRI	SBURG I DAM NO DACW31	PA F DS ID N -78-C-0	/6 13/2 UMETC 046 NL	(U)
	OF AD AOB3128							ALCONTRACTOR	THE G	1		ESSENCE Internet Soldens generate	
Martin Control of Cont	Antonio de la constante de la				ECCUMAN MERICANNE MERICANNE MERICANNE MERICANNE								
	SSAMI GJORE			astreatur en yegende postantiere postantiere socialitése socialitése	ni Oklamatok Ni Oklamatok Solatikov	ALCONTRACT,						×.	
		No.			(1)有		Antonio Martino Antonio Antonio Antonio Antonio Antonio						
All and a second													
	Contraction of the second seco						- F	4			MK	1	
	ettimas <u>USSES</u> uttras	ESCENE private	END DATE FILMED 3-79 DDC										







FALLING SPRINGS CREEK, LACKAWANNA COUNTY

PENNSYLVANIA

FALLING SPRINGS DAM

NDS ID No. PA-00372 DER ID No. 35-39

PENNSYLVANIA GAS AND WATER COMPANY

PHASE I INSPECTION REPORT

NATIONAL DAM INSPECTION PROGRAM

Prepared by

GANNETT FLEMING CORDDRY AND CARPENTER, INC. Consulting Engineers P.O. Box 1963 Harrisburg, Pennsylvania 17105

Contract DACW31-78-C-0046

DL'PARTMENT OF THE ARMY Baltimore District, Corps of Engineers Baltimore, Maryland 21203



JULY 1978

Ω

79

Approved for public release; Distribution Unlimited

SUSQUEHANNA RIVER BASIN

FALLING SPRINGS CREEK, LACKAWANNA COUNTY

PENNSYLVANIA

FALLING SPRINGS DAM

NDS ID No. PA-00372 DER ID No. 35-39

PENNSYLVANIA GAS AND WATER COMPANY

PHASE I INSPECTION REPORT

NATIONAL DAM INSPECTION PROGRAM

JULY 1978

CONTENTS

Description

Page

Brief Assessment of General Condition	
and Recommended Action	a-1
Overview Photograph	b
SECTION 1 - Project Information	1
SECTION 2 - Engineering Data	7
SECTION 3 - Visual Inspection	11
SECTION 4 - Operational Procedures	18
SECTION 5 - Hydrology and Hydraulics	20
SECTION 6 - Structural Stability	23
SECTION 7 - Assessment, Recommendations, and	
Remedial Measures	25

PLATES

Plate

Title

-1-

- 1 Location Map. 2 Plan. Spillway - Plan and Profile. Spillway - Sections. 3 4

ACCESSION	
STIS	White Section X
-	Buti Section
GRANNOUNCE	• •
TIFICATIO	
tex	DDC LOLW 20
. On	File
	UN/AVAILABILITT GUES
Hat	AVAIL. and/or SPECIAL
A	

APPENDICES

Appendix	Title
A	Checklist - Engineering Data.
В	Checklist - Visual Inspection.
С	Hydrology and Hydraulics.
D	Photographs.
E	Geology.

PHASE I INSPECTION REPORT

NATIONAL DAM INSPECTION PROGRAM

BRIEF ASSESSMENT OF GENERAL CONDITION

AND

RECOMMENDED ACTION

Name of Dam:

Falling Springs Dam NDS ID No. PA-00372/ DER ID No. 35-39

Owner:

State Located:

County Located:

Stream:

Date of Inspection:

Inspection Team:

Pennsylvania Gas and Water Company

Pennsylvania

Lackawanna

Falling Springs Creek

5 June 1978

Gannett Fleming Corddry and Carpenter, Inc. P.O. Box 1963 Harrisburg, Pennsylvania 17105

Based on the visual inspection, available records, calculations, and past performance, Falling Springs Dam is judged to be in fair condition.

Under existing conditions, the spillway will not pass the Spillway Design Flood (SDF), which is one-half of the Probable Maximum Flood (PMF), without overtopping. Based on criteria established for these studies by the Department of the Army, Office of the Chief of Engineers (OCE), the spillway capacity is rated as inadequate. The existing spillway can accommodate a flood with a peak inflow of 74 percent of one-half of the PMF peak inflow and 112 percent of the 100year flood peak inflow. If the existing low areas were restored to design grade, the existing spillway could accommodate a flood with a peak inflow of 118 percent of one-half of the PMF peak inflow and the spillway would be rated as adequate.

In view of the concern for the safety of Falling Springs Dam, the following measures are recommended to be taken by the Owner as soon as practical:

(1) Develop a detailed emergency operation and warning system for Falling Springs Dam.

(2) Provide closure facilities for the outlet works on the upstream side of the main embankment for periodic inspection of the pipes and for emergency conditions.

In order to correct operational, maintenance and repair deficiencies, and to more accurately determine the condition of the dam, the following measures are recommended to be undertaken by the Owner in a timely manner:

(1) Perform additional studies to more accurately ascertain the spillway capacity required for Falling Springs Dam as well as the nature and extent of mitigation measures required to make the spillway hydraulically adequate. Also include provisions to repair the concrete of the spillway weir and right spillway abutment. If the existing low areas of the embankments are restored to design grade, the spillway capacity, according to the method used to analyze the spillway for this study, would be adequate. The filling in of low areas of the embankments could be considered a maintenance task.

(2) Remove brush and trees that are on or near the embankments. When the brush and trees are removed, the embankments should be inspected on a regular basis to check for wet areas or seepage.

(3) Install six or more observation wells, or other instrumentation, downstream of the axis of the main embankment. One well, or other instrumentation, should be located in the vicinity of each of the two wet areas. The others should be at appropriate locations to determine general water levels in the downstream main embankment. (4) Install six or more observation wells, or other instrumentation, downstream of the axis of the auxiliary embankment. Two wells, or other instrumentation, should be located in the general swampy area downstream of the toe. One well, or other instrumentation, should be located near the wet area at the left abutment. The others should be at appropriate locations to determine general water levels in the downstream auxiliary embankment.

(5) Data collected from observation wells or other instrumentation should be utilized in evaluating the stability of the structures and assessing piping potential in the future. Continue to observe wet areas and measure and record seepage downstream of embankments. If conditions worsen, appropriate action should be taken to control seepage with properly designed drains.

(6) Investigate surface runoff from left abutment. If it is determined that the wet area at the left abutment of the auxiliary embankment is caused by surface runoff from the left abutment, provide positive drainage for the runoff.

(7) Repair or replace the downstream value of the right outlet conduit. Maintain and operate the values on both outlet conduits on a regular basis.

(8) Repair the concrete of the left outlet channel wall.

(9) Investigate scour damage that could occur during periods of high discharge at downstream end of spillway apron.

(10) Improve damsite access road to ensure access to dam under adverse weather conditions. Provide vehicular access to outlet works.

In addition, the following operational measures are recommended to be undertaken by the Owner:

(1) Provide round-the-clock surveillance of Falling Springs Dam during periods of unusually heavy rains.

(2) When warnings of a storm of major proportions are given by the National Weather Service, the Owner should activate his emergency operation and warning system procedures.

Submitted by:

GANNETT FLEMING CORDDRY AND CARPENTER, INC.

Retooke

A. C. HOOKE Head, Dam Section

Date: 31 July 1978

Approved by:



Jacking Servings

DEPARTMENT OF THE ARMY BALTIMORE DISTRICT, CORPS OF ENGINEERS

G. K. WITHERS Colonel, Corps of Engineers District Engineer

Date: 31 July 1978



23- 455

SUSQUEHANNA RIVER BASIN

FALLING SPRINGS CREEK, LACKAWANNA COUNTY

PENNSYLVANIA

FALLING SPRINGS DAM

NDS ID No. PA-00372 DER ID No. 35-39

PENNSYLVANIA GAS AND WATER COMPANY

PHASE I INSPECTION REPORT

NATIONAL DAM INSPECTION PROGRAM

SECTION 1

PROJECT INFORMATION

1.1 General.

a. <u>Authority</u>. The Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of inspection of dams throughout the United States.

b. <u>Purpose</u>. The purpose of the inspection is to determine if the dam constitutes a hazard to human life or property.

1.2 Description of Project.

a. Dam and Appurtenances. Falling Springs Dam consists of two independent impoundment structures separated by high natural ground. Both impoundment structures are earthfill embankments with concrete core walls. The main embankment is 825 feet long and contains the outlet works. In the base of the core wall of the main embankment, there is a drainage gallery with a 20-inch diameter cast-iron outlet pipe that discharges into the outlet works channel. The auxiliary embankment is 570 feet long. The maximum height of the main embankment is 61 feet at streambed. The top width of the embankments is 10 feet and both the upstream and downstream slopes are 1V on 2H.

The outlet works is located near the left abutment of the main embankment. Intake facilities are submerged and the details are unknown. The valve house with gate valves to control the flow in the two 20-inch cast-iron outlet conduits is located at the downstream toe. Both outlet pipes discharge into the outlet works channel, which directs the flow back into the natural streambed of Falling Springs Creek.

The spillway is located at the right end of the main embankment. The concrete, free overfall spillway weir is 80 feet long and 3 feet high. The spillway crest elevation is 3.5 feet below the top of dam elevation. The spillway discharge passes over the weir and falls onto the spillway apron, which consists of hand-placed riprap. At the downstream end of the spillway apron, the discharge drops 6 feet through boulders and large rock into an earthen channel. The earthen channel empties into Falling Springs Creek about 0.25 mile downstream.

b. Location. The dam is located on Falling Springs Creek about 1.3 miles upstream from the confluence of Falling Springs Creek and the Susquehanna River. Falling Springs Dam is shown mainly on USGS Quadrangle, Ransom, Pennsylvania, and partly on USGS Quadrangle, Pittston, Pennsylvania, with coordinates N41 22'30" - W75 47'10" in Lackawanna County and is 7 miles southwest of Scranton, Pennsylvania. The location of Falling Springs Dam is shown on Plate 1.

-2-

c. Size Classification. Intermediate (61 feet high and 898 acre-feet capacity).

d. Hazard Classification. Significant hazard. Downstream conditions indicate that a significant hazard classification for Falling Springs Dam is warranted (Paragraph 5.1e.).

e. Ownership. Pennsylvania Gas and Water Company, Wilkes-Barre, Pennsylvania.

f. <u>Purpose of Dam</u>. Water supply for Pittston, Old Forge, and surrounding communities.

g. <u>Design and Construction History</u>. Falling Springs Dam was built in 1905 by the Spring Brook Water Supply Company. The design and construction supervision was performed by John H. Lance, Chief Engineer of the Spring Brook Water Supply Company. In 1922, a drainage ditch was built at the left end of the main embankment to remedy a swampy condition that had been experienced at the toe of the embankment near the left abutment. In 1929, the spillway was rebuilt. The length of the spillway was increased from 40 feet to 80 feet, and the spillway crest elevation was set at the former top of flashboards elevation at 1352.74. The top of the embankments were raised so that a freeboard of 3.5 feet was available on the new spillway crest.

h. Normal Operational Procedure. Excess reservoir inflow is discharged over the spillway. A portion of the flow in Falling Springs Creek is diverted 0.6 mile downstream of the dam into an earthen canal that feed into Campbell Ledge Storage Reservoir. Water is discharged from Campbell Ledge Storage Reservoir into Campbell Ledge Intake, where the water is distributed to Pittston, Old Forge, and Taylor. When the pool level at Campbell Ledge Storage Reservoir falls below the spillway crest elevation, additional water is released from Falling Springs Reservoir through the left outlet conduit to augment the flow into Campbell Ledge Storage Reservoir.

-3-

1.3 Pertinent Data.

- a. Drainage Area. 1.25 square miles.
- b. Discharge at Damsite. (cfs.)

Maximum known flood at damsite - 520 (estimated - August 1955).

Outlet works at maximum pool elevation - 27.

Spillway capacity at maximum pool elevation - 1,110.

c. Elevation. (Feet above msl.)⁽¹⁾

Design top of dam - 1356.2

Actual top of dam - varies 1356.2 to 1355.2.

Maximum pool - 1355.2.

Normal pool - 1352.74.

Upstream invert outlet works - 1287.0 (estimated).

Downstream invert outlet works - 1286.14.

Streambed at centerline of dam - 1285.0.

d. Reservoir Length. (Miles.)

Normal pool - 0.66.

Maximum pool - 0.71.

e. Storage. (Acre-feet.)

Normal pool (spillway crest) - 774. Maximum pool (top of dam) - 898.

 Datum used for elevations is based on approximate USGS datum. The datum used on the Owner's drawings is based on a different datum. The equivalence is Elevation 1352.74 (USGS) equals Elevation 517.0 (Drawings).

2 000 00

f. Reservoir Surface. (Acres.)

Normal pool (spillway crest) - 49. Maximum pool (top of dam) - 50.2.

g. Dam.

<u>Type</u> - Homogeneous earthfill structure with central concrete core wall.

Length - Main (right) embankment - 825 feet. Auxiliary (left) embankment - 570 feet.

Height - Main (right) embankment - 61 feet. Auxiliary (left) embankment - 18 feet.

Top width - 10 feet.

Slopes - Upstream 1V on 2H. Downstream 1V on 2H.

Zoning - Homogeneous earthfill. Central concrete core wall.

Cutoff - Concrete core wall founded on rock.

Grout curtain - None.

h. Diversion and Regulating Tunnel. None.

i. Spillway.

Type - Broad-crested weir (width 10 inches) with adverse approach slope 1V on 2H (total width 5 feet) and free overfall.

Length of weir - 80 feet.

Crest elevation - 1352.7.

Upstream channel - 1V on 2H rock-faced embankment to Elevation 1350.7.

Downstream channel - Hand-placed stone apron sloping gently away from spillway for 60 feet, then free overfall of 6 feet into rock-lined channel. j. Regulating outlets.

Type - Two low level 20-inch diameter castiron pipes. 2

Length - 290 feet.

Access - None.

Regulating facilities. - Two manually operated nonrising stem, enclosed 20-inch gate valves, with exposed 3 to 1 spur and pinion gear reducers.

AND A A BLACTOR HORE

there approach alone if on 19 (coopl with

SECTION 2

ENGINEERING DATA

2.1 Design.

a. <u>Data Available</u>. Very little engineering data was available for review for the original structures. In a study performed in 1914 by the Pennsylvania Water Supply Commission, an account of design concepts, geology, construction materials and methods, and design features was prepared for the structures from interviews with the Owner, visual inspection, and other sources. The 1914 study also included analyses for hydrology and hydraulics. A summary of the results of the analyses is on file. Subsequent studies and inspections by the Commission were the bases for the recommended improvements to the spillway that were made in 1929.

b. <u>Design Features</u>. Falling Springs Dam consists of two independent impoundment structures, the main embankment and the auxiliary embankment. The embankments are connected by high natural ground. The outlet works is located at the main embankment. The locations of the various features are shown on Plate 2. A discussion on geology is presented in Appendix E.

The main embankment consists of a 825-foot long earth embankment with a concrete core wall (Photographs A and B). In the base of the core wall is a drainage gallery with a 20-inch diameter cast-iron outlet pipe that discharges into the outlet works channel at the downstream toe of the main embankment. The maximum height of the main embankment is about 61 feet. The auxiliary embankment consists of a 570-foot long earth embankment with a concrete core wall (Photographs I and J). Foundation investigations made for the 1914 Commission Report indicate fairly hard shale near the surface with many outcrops. The right end of the main embankment abuts the spillway, and the left end of the main embankment ties into high natural ground. Both ends of the auxiliary embankment abut high natural ground. The embankments are 10 feet wide at the top. The bottom widths vary

to a maximum of 250 feet. The upstream slopes are paved with hand-placed riprap (Photograph K), and the downstream slopes are sodded. The slopes are 1V on 2H. A rock-lined drainage gutter was constructed in 1922 at the toe of the main embankment near the left abutment to alleviate a wet area that had existed for several years. The gutter discharges into the natural streambed of Falling Springs Creek about 180 feet downstream.

The spillway is located at the right end of the main embankment. The height of the concrete free overfall spillway is about 3 feet; the length is 80 feet; and the crest is at Elevation 1352.7 (Photographs C and D). The spillway crest is flanked by concrete abutments. Spillway plan, profile, and sections are shown on Plates 3 and 4. The present spillway replaced the original spillway in 1929. The original spillway was also a concrete, free overfall structure. Disintegration of the spillway and spillway abutment concrete had been extensive enough to require that the Owner make the repairs. At that time, it was decided to raise the spillway crest to the top of the 2-foot high flashboards that had been in use for years and to widen the spillway crest from 40 feet to 80 feet. It was also decided to raise the embankments to bring them to an elevation that is 3.5 feet above the present spillway crest. The spillway apron is a 60-foot long section of hand-placed riprap that is located immediately below the spillway crest (Photograph E). At the downstream end of the spillway apron, the invert drops sharply into an earthen channel (Photograph F). Flow from the spillway joins flow from the outlet works about 0.25 mile downstream of the dam.

The outlet works, which contains the reservoir drawdown facilities, is located near the left abutment of the main embankment. Intake structure conditions are unknown, other than the presence of steel screens in the reservoir. The 1914 Commission report does not mention any closure facilities for the outlet works on the upstream side of the embankment. The valve house with gate valves to control the flow in the outlet pipes is located at the downstream toe. Two 20-inch diameter cast-iron pipes can draw water from the reservoir. Each line has

-8-

two manually operated gate valves on it. Both lines discharge into the outlet works channel (Photograph G), which in turn discharges into the natural channel of Falling Springs Creek. About 0.6 mile downstream from Falling Springs Dam, water is diverted from Falling Springs Creek into an earthen canal for 0.3 mile into Campbell Ledge Storage Dam. Campbell Ledge Storage Dam supplies water to Campbell Ledge Intake Dam, which distributes water to Pittston, Old Forge, and Taylor.

Access to Falling Springs Dam is by a 2-mile unpaved road that belongs to the Owner. The access road leads to the left abutment of the auxiliary embankment, from where it proceeds across the crest of the auxiliary embankment to the high natural ground and then across the crest of the main embankment to the spillway. There is no access road to the outlet works.

2.2 Construction.

O

0

a. <u>Data Available</u>. Construction data available for review for the original structures was limited to information contained in the 1914 report prepared by the Pennsylvania Water Supply Commission. That information was obtained by interviews with the Owner, and it gives details of the construction. Details of the construction for the 1929 spillway modification are available.

Construction Considerations. The 1914 report and subsequent inspections by the Commission raised two concerns about the construction of Falling Springs Dam. The first concern was that shortly after the dam was constructed, several slides occurred in the embankments that indicated that the embankment material was not properly compacted. It was believed that some material was placed in freezing weather, which resulted in the formation of large clods that were never properly compacted. The slides were repaired, and no further movement in the embankment was noticed in the next several years. The second concern was that the downstream toe of the main embankment at the left abutment was saturated with water that probably came from the left abutment rock. The Commission required that a rocklined channel be constructed to drain the water so that the potential for a slide of the embankment would be reduced.

According to a 1917 report by the Commission, the material for the embankments was placed without rolling, which was not unusual for dams built by the Spring Brook Water Supply Company. Therefore, the likelihood of slides and settlement was high.

Review of the available information for the 1929 spillway modification did not yield pertinent information with respect to the character of that work.

2.3 Operation. No formal records of operation were reviewed. Based on information from the Owner and the caretaker of the dam, all structures have performed satisfactorily. The caretaker, who has been associated with Falling Springs Dam for 33 years, said that he could not recall when flow over the spillway exceeded 18 inches.

2.4 Other Investigations. No known investigations other than those previously described were reviewed.

2.5 Evaluation.

a. <u>Availability</u>. Engineering data was provided by the Division of Dams and Encroachments, Bureau of Water Quality Management, Department of Environmental Resources, Commonwealth of Pennsylvania, and by the Owner, Pennsylvania Gas and Water Company. The Owner made available an engineer and a caretaker for information and operating demonstrations during the visual inspection. The Owner also researched his files for additional information upon the request of the inspection team.

b. <u>Adequacy</u>. The type and amount of design data and other engineering data are limited, and the assessment must be based on the combination of available data, visual inspection, performace history, hydrologic assumptions, and hydraulic assumptions.

c. Validity. There is no reason to question the validity of the available data.

SECTION 3

VISUAL INSPECTION

3.1 Findings.

a. <u>General</u>. The general appearance of this project indicated that some project features have deteriorated with age and are in need of repair, while other project features have been properly maintained and are in good condition.

b. Dam.

(1) Main Embankment. The main embankment was generally in good condition from what could be seen. However, brush and young trees with an average height of about 12 feet were growing on the downstream slope of the embankment and hindered the inspection. The growth was quite dense in places, with the diameter of the trees varying to up to 3 inches. Results of the survey of the downstream slope indicate that the slope varies slightly, but not significantly, from the design slope of 1V on 2H. A fallen 50foot tree was decaying on the slope. There was a row of mature evergreen trees that were spaced at about 12-foot intervals at the toe of the embankment. Several trees of about 12-foot height and 4-inch diameter were grouped near the junction of the main embankment with the left end of the spillway. The riprap on the upstream face of the main embankment is generally in place and is in good condition. There is a general cover of light brush about 18 inches in height on the upstream slope above the normal pool elevation.

There were two wet areas at the downstream toe of the main embankment near the left abutment. The first wet area was the result of seepage through a 40foot by 100-foot portion of the vertical rock face immediately downstream of the left abutment. The seepage was collected by a rock-lined channel and joined the flow from the outlet channel about 180 feet downstream. The seepage was clear, and the flow in the rock-lined channel was about 5 to 10 gpm. The second wet area was observed about 20 feet to the right of the rock-lined channel and was approximately 3 feet wide and 15 feet long. The flow from the second wet area drained into the rock-lined channel and was estimated to be less than 0.5 gpm. The discharge from the second wet area was also clear.

The survey of the top of the main embankment revealed that the elevation along the top of dam was irregular. The lowest point on the top of dam was about 0.9 foot below design top of dam elevation.

(2) Auxiliary Embankment. The auxiliary embankment was generally in good condition from what could be seen. However, 3.5-foot high brush, growing on the downstream slope of the embankment, hindered the inspection. Results of the survey of the downstream slope indicate that the slope was slightly flatter than the design slope of 1V on 2H. The area immediately downstream of the toe was covered with mature broadleafed trees with an average height of about 60 feet. The riprap on the upstream face of the main embankment is generally in place and is in good condition. There is a general cover of light brush about 18 inches in height on the upstream slope above the normal pool elevation.

Two wet areas were observed near the auxiliary embankment. The first wet area was a general swampy area of triangular shape below the downstream toe near the middle of the auxiliary embankment. The length of the wet area along the toe was about 200 feet, and the standing water extended about 600 feet downstream of the toe. There was no outlet for the wet area, and there was no discernable flow. old cuttings of brush and small trees were lying in the swampy area near the toe. The second wet area was a small pool of standing water at the left abutment on the downstream side (Photograph L). The pool area was 6 feet long and 5 feet wide, and the pool was 0.5 foot deep. It appeared that the pool collected surface runoff that had drained along the access road to the dam. There was no discernable outflow from the pool.

The survey of the top of the auxiliary embankment revealed that the elevation along the top of dam was irregular. The lowest point along the top of dam was about 1.0 foot below design top of dam elevation.

c. Appurtenant Structures.

Spillway. In general, the concrete of the (1)spillway weir and spillway abutments was in satisfactory condition. Since water was flowing over the spillway crest, the downstream face of the spillway weir could not be closely inspected. It was observed, however, that moss was growing on the face and that coarse aggregate was exposed in several places across the face and crest. Concrete was spalled to an average distance into the reservoir of about 9 inches and to an average vertical depth of about 10 inches at three locations across the spillway Two of the spalled areas were at the monolith joints. crest. The joint filler was missing where the concrete was spalled at the joints. The third area of spalling was at a transverse or shrinkage crack 10 feet from the right abutment Two other transverse or shrinkage cracks were noted in the spillway weir. In general, the cracks were parallel with the flow and ran upstream for a distance of about 2 feet until observation was obstructed by the water in the res-ervoir. The cracks were about 1/4 inch wide and were probed to a depth of about 1/4 inch. No differential movement was noted at the cracks. Three small spalled areas and a small crack were observed on the spillway right abutment wall. The spalled areas were, on the average, about 5 inches wide, 6 inches long, and 3 inches deep. The vertical crack ran from the spillway crest to the top of the abutment wall. The crack was probed to a depth of about 1/4 inch. No differential movement was noted at the crack. There appeared to have been an attempt to patch the crack at one time.

The floor of the approach channel was covered with dead leaves. No obstructions were observed in the approach channel. The dry stone wall shown on the spillway plans at the right abutment upstream of the spillway crest was not found.

The spillway apron was generally in good condition. Grass was growing through the riprap cover over about 50 percent of the spillway apron. A 3-foot by 3-foot brush area was observed 2 feet downstream of the spillway weir. Minor debris had collected on the spillway apron. At the downstream end of the spillway apron, the channel invert drops 6 feet, nearly vertical, onto boulders, smaller rocks, and an earthen channel composed mostly of a hard clay. Construction methods for the channel were unknown, and the channel appeared to have been degrading for many years.

(2) Outlet Works. The outlet works was in fair condition. The intake facilities are submerged. The condition and nature of the intake facilities were unknown since the reservoir water level was at normal pool and no data is available for the design or construction of the intake facilities. The downstream valve of the 20-inch line on the right side was closed and was inoperable. The downstream valve of the 20inch line on the left side was partially opened by three men in 30 minutes. The packing leaked. The gear reducers were well rusted. All four valves were covered with sawdust.

The two 20-inch diameter cast-iron outlet pipes discharged into the outlet channel. A third 20-inch diameter cast-iron pipe connected to the drainage gallery located in the core wall of the main embankment and discharged into the outlet channel. This drainage pipe was discharging water with a depth of flow of about 1/2 inch in the pipe. A deposit of orange clay was noted directly beneath the core wall drain outlet. The floor and the right outlet channel wall were in good condition. There was a vertical crack in the right outlet channel wall from the channel floor to and through the 9-inch coping on top of the wall. The crack was 1/2 inch wide, 4.3 feet high, and 10 feet downstream from the valve house. It appeared that there was an attempt to patch the crack at one time. The left outlet channel wall was severely deteriorated and undermined (Photograph H). The concrete was disintegrated for about 2 feet immediately below the valve house. The wall was undermined at the junction of the wall and the floor for the entire length of the wall. The maximum distance of undermining into the wall was 14 inches; the maximum vertical distance of the affected area was 27 inches. The concrete coping and the vertical face of the wall was deteriorated at several places to a depth of 3 inches. The 9-inch coping and the top 2 feet of the end of the left outlet channel wall was disintegrated to a depth of 3 inches. There was There was evidence that repairs had been attempted in the past.

d. <u>Reservoir Area</u>. The reservoir slopes are covered with hardwoods and evergreens. No evidence was visible of creep, rock slides, or land slides. The Owner indicated that sedimentation is not a problem from the standpoint of reduced reservoir capacity. The watershed is primarily owned and controlled by Pennsylvania Gas and Water Company and is predominantly undeveloped.

e. <u>Downstream Channel</u>. The channel immediately below the spillway is roughly rectangular in shape and is composed of a hard clay and loose rocks and boulders. The slope of the channel is steep. At the time of the inspection, the flow in the channel below the spillway was about 3 cfs. The channel appeared to have been undergoing degradation for many years. A wooded area of hardwoods and evergreens starts immediately below the spillway apron. Some trees extend to the immediate overbanks of the channel. Flow from the spillway joins the flow from the outlet works about 0.25 mile downstream of the dam.

The channel immediately below the outlet works channel is the natural streambed of Falling Springs Creek. The bottom of the channel is covered with small, loose rock, and the channel slope is milder than the channel below the spillway. Flow in the outlet works channel was estimated to be less than 1 cfs. The streambed and banks appeared to be in a relatively stable condition.

Access Roads to Dam and Outlet Works. The conf. dition of the 2-mile unpaved access road was poor. Access to the dam was obtained by a two-wheel drive vehicle with high ground clearance. No rain was observed on the date of the inspection, but runoff from the hillside was flowing directly down the access road for a distance of about 2,000 feet. The road surface was very irregular with numerous holes and channels cut into the roadway. Access by rubbertired vehicle would be very time consuming, if not impossible, during periods of high runoff or during severe winter con-There is no access road to the outlet works. Acditions. cess is obtained by hiking through the wooded area that begins immediately below the toe of the dam or by making way through the heavy brush and small trees on the downstream slope of the main embankment.

3.2 Evaluation.

a. Dam.

(1) The continued growth of trees and brush on the embankment slopes and along the toe of the embankments is undesirable.

(2) The two wet areas of the main embankment were noted in inspection reports in 1921, 1933, 1934, 1941, and 1943. No mention was made of wet areas in the 1957 and 1965 inspection reports. The descriptions in the inspections are insufficient to determine if the areas under discussion are identical to the two wet areas observed during the inspection. The areas have apparently stabilized, but because of the potential seriousness of the problem, they are of general concern.

(3) The settling and resulting irregular elevation of the tops of embankments is of general concern, since the spillway capacity is reduced by the lower available head before overtopping. Flow over the low spots could quickly erode the earth embankments.

(4) The large triangular wet area at the toe of the auxiliary embankment is of general concern. The wet area was reported in the 1933 and 1941 inspections, but it was not mentioned in the later inspections in 1957 and 1965. The wet area has apparently stabilized, but because of the potential seriousness of the problem, the swampy condition should be monitored frequently. The small pool of standing water at the left abutment is not of major concern, although accumulation of water at the abutment is not desirable. Apparently surface runoff from above the left abutment is intercepted by the access road, and the flow collects in depressions on the road and along the shoulders of the road.

b. Appurtenant Structures.

(1) <u>Spillway</u>. The condition of the concrete of the spillway weir and spillway abutments is of slight concern at the present time. Additional spalling and surface cracking of the concrete could become more of a concern in the future. The spalling at the joints of the spillway weir could reduce the ability of the weir to act as a watertight structure. The conditions of the approach channel and the spillway apron are of little concern, although the debris, brush, and grass present are undesirable. There is general concern for the condition at the downstream end of the spillway apron, where the channel invert drops nearly vertical for a distance of about 6 feet. During larger discharges, considerable scouring could occur that might undermine the riprap apron and threaten the toe of the main embankment and the spillway.

(2) <u>Outlet Works</u>. There is concern for the condition of the downstream value of the right outlet pipe. All operating equipment should be in good condition so their use in not impaired when needed.

The left outlet channel wall was showing evidence of severe deterioration. Lack of maintenance may increase the deterioration and thereby threaten the stability of the wall. Continued deterioration and undermining of the wall could lead to a failure of the wall, which may threaten the toe of the main embankment.

c. <u>Reservoir Area</u>. No conditions were observed in the reservoir area that might present significant hazard to the dam.

d. <u>Downstream Channel</u>. Concern for scouring in the downstream channel below the spillway apron was expressed in Paragraph 3.2b.(1). No conditions were observed in the downstream channel below the outlet works that might present a significant hazard to the dam.

e. Access Roads to Dam and Outlet Works. During inclement weather conditions, access to the damsite by vehicle would be, at best, very time consuming. Access to the outlet works would be by foot through a wooded area, since there is no road or footpath to the valve house.

SECTION 4

23 minter 1

OPERATIONAL PROCEDURES

£.)

4.1 Procedure. The spillway is maintained at spillway crest Elevation 1352.7 with excess reservoir inflow dropping 3 feet over the concrete spillway weir onto the hand-placed riprap apron. The discharge joins the original Falling Springs Creek streambed about 0.25 mile downstream and then flows for about 0.3 mile to a 7-foot Water is diverted at the high masonry diversion dam. dam into an earthen canal that empties into Campbell Ledge Storage Reservoir. Falling Springs Creek continues down the steep, narrow valley and discharges into the Susquehanna River. When the water surface elevation at Campbell Ledge Dam drops below the spillway crest elevation, additional water is released from Falling Springs Reservoir through the left outlet conduit to increase the flow into Campbell Ledge Storage Reservoir. The right outlet conduit at Falling Springs Reservoir has not been used for many years. The two gate valves for each outlet conduit are protected by the valve house at the toe of the main embankment. Each upstream valve is normally open, and the downstream valve in the left outlet conduit is throttled for regulation of flow.

4.2 <u>Maintenance of Dam.</u> The dam is visited daily by a caretaker who records the reservoir elevation. The caretaker, who has been working for the Owner for 33 years, also checks the reservoir elevation and chlorination equipment at Campbell Ledge Storage Dam. Reports on daily water levels and any observed deficiences are mailed to the Owner's Engineering Department weekly. The report information is used by the Engineering Department for regulating flows in the distribution system. A Pennsylvania Gas and Water Company engineer makes a formal inspection of the dam each year, and the records are kept on file and are used for determining priority of repairs. Informal inspections are also made when the engineer is on the site for other reasons.

-18-

4.3 <u>Maintenance of Operating Facilities</u>. There is no known regular maintenance program for the operating facilities. Maintenance is apparently performed when deemed necessary.

3314

4.4 Warning Systems in Effect. The Owner furnished the inspection team with a chain of command diagram for Falling Springs Dam and a generalized emergency notification list that is applicable for all the Pennsylvania Gas and Water Company dams. The Owner said that during periods of heavy rainfall, available personnel are dispatched to the dams to observe conditions. All company vehicles are equipped with radios, and the personnel can communicate with each other and with a central control facility. Evaluation of risk is made by the Owner's Engineering Department. The Owner's Engineering Department is also responsible for notification of emergency conditions to the local authorities. Detailed emergency operational procedures have not been formally established for Falling Springs Dam but are as directed by the Owner's Engineering Department.

4.5 Evaluation. Except for not opening the values on a regular basis, the operational procedure is fair. Infrequent operation of the values could affect their functioning satisfactorily during emergency conditions. If augmentation of downstream flow is alternated between the left outlet conduit and the right outlet conduit, wear on the gate values caused by throttling would be minimized. Alternation would also reduce the deterioration and undermining of the left outlet channel wall. The procedures used by the Owner for inspecting the dam are adequate, but some needed repairs have not been made. In general, the warning system is adequate, but it is not in sufficient detail to alert the parties downstream that would be affected by a failure of Falling Springs Dam.

-19-

SECTION 5

HYDROLOGY AND HYDRAULICS

5.1 Evaluation of Features.

a. Design Data.

(1) No hydrologic and hydraulic analyses for the original Falling Springs Dam design were available for review. The spillway capacity has been estimated before and after the 1929 spillway modification.

(2) In the recommended guidelines for safety inspection of dams, the Department of the Army, Office of the Chief of Engineers (OCE), established the criteria for rating the capacity of spillways. The recommended Spillway Design Flood (SDF) for the size (intermediate) and the hazard (significant) classification of Falling Springs Dam is one-half of the Probable Maximum Flood (PMF) to the PMF. If the dam and spillway are not capable of passing the spillway design flood without overtopping failure, the spillway capacity is rated as inadequate. One-half of the PMF was selected as the SDF. If the spillway is not capable of passing one-half of the PMF without overtopping, the percentage of the 100year flood that the spillway could pass should be determined.

(3) The 1929 "Report upon the Application of the Scranton-Spring Brook Water Service Company" by the Water Supply Commission of Pennsylvania shows a spillway capacity of 800 cfs with 1.5 feet of freeboard. Calculations were performed for this study to determine the spillway capacity without freeboard. The spillway capacity for the design elevation of the dam without freeboard was found to be 1,830 cfs. However, low spots exist on the tops of the embankments that reduce the existing capacity of the spillway to 1,110 cfs at the point of initial overtopping of the dam. The computations are shown in Appendix C. (4) The Falling Springs Dam watershed is primarily owned by Pennsylvania Gas and Water Company. Most of the watershed is undeveloped, although portions are developed. Hydrologic analysis for this study was based on existing conditions, and the effects of future development of the watershed were not considered.

12342

b. Experience Data. For this study, a PMF peak previously calculated for hydrologically similar Fall Brook Reservoir watershed was transposed to the Falling Springs Reservoir watershed. The PMF peak inflow was estimated to be 3,720 cfs at Falling Springs Dam. The volume of the PMF inflow hydrograph was adjusted to approximate 26 inches of runoff over the entire watershed. The SDF is one-half the PMF or 1,860 cfs. The volume of the spillway design flood inflow hydrograph was adjusted to approximate 13 inches of runoff over the entire watershed. The 100-year flood was estimated from regionalized data obtained from "Hydrologic Study - Tropical Storm Agnes", North Atlantic Division, Corps of Engineers, December 1975. The 100year peak inflow was estimated to be 1,230 cfs. Hydrology computations are presented in Appendix C.

c. Visual Observations. On the date of the inspection, no conditions were observed that would indicate that the spillway capacity would be significantly reduced during a flood occurrence.

d. Overtopping Potential. For an occurrence of one-half of the PMF, the peak inflow of 1,860 cfs is greater than the spillway capacity of Falling Springs Dam. A check of the surcharge storage effect of Falling Springs Reservoir shows that the surcharge storage available is insufficient to contain an inflow with a peak of 1,860 cfs without overtopping the dam (Appendix C).

e. <u>Downstream Conditions</u>. A small diversion structure consisting of a 7-foot high masonry dam and headworks for a canal is located about 0.6 mile downstream of Falling Springs Dam (Photograph M). At that point, a portion of the flow from Falling Springs Creek is directed via an earthen canal for a distance of about 0.3 mile into Campbell Ledge Storage Dam. Campbell Ledge Storage Dam supplies water to Campbell Ledge Intake Dam, which distributes water to Pittston, Old Forge, and Taylor. The locations of the dams are shown on Plate 1.

Below the diversion structure, Falling Springs Creek drops very steeply through a narrow valley until it reaches the Susquehanna River valley. The creek crosses under a secondary highway and the tracks of the Coxton Yards of the Lehigh Valley Railroad immediately before emptying into the Susquehanna River (Photograph N) 1.3 miles below Falling Spring Dam.

A large discharge from Falling Springs Dam would almost entirely be confined to Falling Springs Creek valley. Damages could be incurred by one or two isolated homes, the secondary highway, the Lehigh Valley Railroad and public utilities. The downstream conditions indicate that a significant hazard classification is warranted for Falling Spring Dam.

f. Spillway Adequacy.

(1) The spillway will not pass one-half of the PMF without overtopping the dam under existing conditions. The 100-year flood is 1,230 cfs and is greater than the spillway capacity. A check of the surcharge storage effect of Falling Springs Dam shows that the existing surcharge storage available is sufficient to contain an inflow with a peak flow of 1,230 cfs without overtopping the dam (Appendix C).

(2) Based on established OCE criteria as outlined in Paragraph 5.1a.(2), the existing spillway capacity of Falling Springs Dam is rated as inadequate. Considering the effects of the surcharge storage of 124 acre-feet, the spillway discharge capacity of 1,110 cfs can accommodate a flood with a peak inflow of 1,340 cfs for a storm of the same duration as the PMF. This is 74 percent of one-half of the PMF peak inflow and 112 percent of the 100-year flood peak inflow.

(3) If the low areas of the embankments were to be brought up-to-grade, which could be considered a maintenance task, the spillway capacity of Falling Springs Reservoir would be increased to 1,830 cfs. This would permit the accommodation of a flood with a peak inflow of approximately 2,200 cfs or 118 percent of the Falling Springs Dam one-half PMF peak inflow. The spillway capacity of Falling Springs Dam would then be rated as adequate.

SECTION 6

STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability.

a. Visual Observations.

(1) <u>General</u>. The visual inspection of the dam resulted in a number of observations relevant to structural stability. These observations are listed herein for various features.

(2) <u>Main Embankment</u>. Two wet areas were observed at the toe of the main embankment near the left abutment. Evidence of settlement of the embankment was also observed. The detailed description and evaluation of the conditions are in Paragraphs 3.1b.(1), 3.2a.(2), and 3.2a.(3).

(3) Auxiliary Embankment. A large swampy area was observed at the toe of the auxiliary embankment and a small pool of standing water was observed near the left abutment. Evidence of settlement of the embankment was also observed. The detailed description and evaluation of the conditions are in Paragraphs 3.1b.(2), 3.2a.(3), and 3.2a.(4).

(4) <u>Spillway</u>. Surface cracks and small spalls were observed on the spillway weir and spillway abutments. The detailed description and evaluation are in Paragraphs 3.1c.(1) and 3.2b.(1).

b Design and Construction Data. No record of design data or stability analysis for the original structures or subsequent modifications was available for review. The structure was studied in 1914 by the Pennsylvania Water Supply Commission. No stability analysis for the structures, as they then existed, was performed.

The existing spillway weir is 3 feet high. During a review of the spillway section (Plate 4), it was judged that the structure would be stable for the expected loads. Stability analyses are not usually performed on structures this small. c. Operating Records. According to the 1914 Pennsylvania Water Supply Commission Report, a number of local slides in the embankment and settlement of the crest were experienced in the first season the dam was in operation. The slides and settlement were thought to have been caused by improper compaction. The slides were repaired immediately, but the top of dam elevation remains uneven. Other than the sliding and settlement that were experienced during the first season of operation, there is no evidence that the spillway or embankments have experienced stability problems.

d. <u>Post-Construction Changes</u>. Adequate information is available concerning modifications made to Falling Springs Dam after 1914.

e. <u>Seismic Stability</u>. Falling Springs Dam is located in Seismic Zone 1. Normally, it can be considered that if a dam in this zone is stable under static loading conditions, it can be assumed safe for any expected earthquake loading. However, since there are no formal static stability analyses, and since there is the potential of earthquake forces moving or cracking the concrete core wall, the theoretical seismic stability of this dam cannot be assessed.

or subservent sodifications was available to revisit "to structure with scudied in 1514 of the somewivenue water supply formination for scabific scaled to for the origination

the externs solliesy solv is I for either builde

SECTION 7

ASSESSMENT, RECOMMENDATIONS, AND REMEDIAL MEASURES

7.1 Dam Assessment.

a. Safety.

(1) Based on the visual inspection, available records, calculations, and past operational performance, Falling Springs Dam is judged to be in fair condition. However, deficiencies of varying degree of importance were noted. A summary of the features and observed deficiencies is listed below:

Feature and Location

Main Embankment: Top of Dam CARAGES BUSIESSES

Observed Deficiencies

Uneven elevation, trees near junction with spillway.

Brush and young tree growth.

Two wet areas.

Auxiliary Embankment: Top of Dam

Downstream surface

Downstream surface

abutment

Downstream toe

Downstream side of left abutment

Downstream toe near left

Spillway: Concrete weir and right abutment

Spillway apron

Uneven elevation.

Brush and tree growth.

Wet area.

Wet area.

Spalling and surface cracking.

Brush, grass, and debris.

-25-
Feature and Location

Observed Deficiencies

Outlet Works: Operating equipment

Left outlet channel wall

Downstream Channel: Below spillway

Access Roads: Access to damsite

Access to outlet works

Inoperable valve; lack of regular maintenance.

Severe deterioration.

Scour potential during high discharges.

Unpaved road in poor condition.

Inaccessible by vehicle.

(2) The overtopping potential analysis shows that Falling Springs Dam will be overtopped by one-half of the PMF under existing condition. Based on OCE criteria as outlined in Paragraph 5.1a.(2), the spillway capacity is rated as inadequate. The existing spillway can accommodate a flood with a peak inflow of 74 percent of one-half of the PMF peak inflow and 112 percent of the 100-year flood peak inflow. If the existing low areas were restored to design grade, the existing spillway could accommodate a flood with a peak inflow of 118 percent of one-half of the PMF peak inflow and the spillway would be rated as adequate.

(3) Because of the low height of the spillway weir, no analysis was performed to calculate the stability. It was judged that the spillway weir should be stable.

b. Adequacy of Information. The information available is such that an assessment of the condition of the dam can be inferred from the combination of visual inspection, past performance, and computations performed prior to and as part of this study.

c. <u>Urgency</u>. The recommendations in Paragraph 7.2 should be implemented as soon as practical or in a timely manner as noted.

d. <u>Necessity for Further Investigations</u>. In order to accomplish some of the remedial measures outlined in Paragraph 7.2, further investigations will be required. 7.2 Recommendations and Remedial Measures.

a. In view of the concern for safety of Falling Springs Dam, the following measures are recommended to be undertaken by the owner as soon as practical:

(1) Develop a detailed emergency operation and warning system for Falling Springs Dam.

(2) Provide closure facilities for the outlet works on the upstream side of the main embankment for periodic inspection of the pipes and for emergency conditions.

b. In order to correct operational, maintenance, and repair deficiencies and to more accurately determine the condition of the dam, the following measures are recommended to be undertaken by the Owner in a timely manner:

(1) Perform additional studies to more accurately ascertain the spillway capacity required for Falling Springs Dam as well as the nature and extent of mitigation measures required to make the spillway hydraulically adequate. Also include provisions to repair the concrete of the spillway weir and right spillway abutment. If the existing low areas of the embankments are restored to design grade, the spillway capacity, according to the method used to analyze the spillway for this study, would be adequate. The filling in of the low areas of the embankments could be considered a maintenance task.

(2) Remove brush and trees that are on or near the embankments. When the brush and trees are removed, the embankments should be inspected on a regular basis to check for wet areas or seepage.

(3) Install six or more observation wells, or other instrumentation, downstream of the axis of the main embankment. One well, or other instrumentation, should be located in the vicinity of each of the two wet areas. The others should be at appropriate locations to determine general water levels in the downstream main embankment.

(4) Install six or more observation wells, or other instrumentation, downstream of the axis of the auxiliary embankment. Two wells, or other instrumentation, should be located in the general swampy area downstream of the toe. One well, or other instrumentation, should be located near the wet area at the left abutment. The others should be at appropriate locations to determine general water levels in the downstream auxiliary embankment.

(5) Data collected from observation wells or other instrumentation should be utilized in evaluating the stability of the structures and assessing piping potential in the future. Continue to observe wet areas and measure and record seepage downstream of embankments. If conditions worsen, appropriate action should be taken to control apparent seepage with properly designed drains.

(6) Investigate surface runoff from left abutment. If it is determined that the wet area at the left abutment of the auxiliary embankment is caused by surface runoff from the left abutment, provide positive drainage for the runoff.

(7) Repair or replace the downstream value of the right outlet conduit. Maintain and operate the values on both outlet conduits on a regular basis.

(8) Repair the concrete of the left outlet channel wall.

(9) Investigate scour damage that could occur during periods of high discharge at downstream end of spillway apron.

(10) Improve damsite access road to ensure access to dam under adverse weather conditions. Provide vehicular access to outlet works.

c. In addition, the following operational measures are recommended to be undertaken by the Owner:

(1) Provide round-the-clock surveillance of Falling Springs Dam during periods of unusually heavy rains.

(2) When warnings of a storm of major proportions are given by the National Weather Service, the Owner should activate his emergency operation and warning system procedures.

SUSQUEHANNA RIVER BASIN

0

0

FALLING SPRINGS CREEK, LACKAWANNA COUNTY

PENNSYLVANIA

FALLING SPRINGS DAM

NDS ID No. PA-00372 DER ID No. 35-39

PENNSYLVANIA GAS AND WATER COMPANY

PHASE I INSPECTION REPORT NATIONAL DAM INSPECTION PROGRAM

JULY 1978

PLATES





THIS PAGE IS BEST QUALITY PRACTICABLE FROM COPY FURNISHED TO DDC

THIS PAGE IS BEST QUALITY F FROM COPY FURNISHED TO DDC



THIS PAGE IS BEST QUALITY PRACTICABLE FROM COPY FURNISHED TO DDC

THIS PAGE IS BEST QUALITY PRACTICABLE FROM COPY FURNISHED TO DDC













SUSQUEHANNA RIVER BASIN

0

()

FALLING SPRINGS CREEK, LACKAWANNA COUNTY

PENNSYLVANIA

FALLING SPRINGS DAM

NDS ID No. PA-00372 DER ID No. 35-39

PENNSYLVANIA GAS AND WATER COMPANY

PHASE I INSPECTION REPORT NATIONAL DAM INSPECTION PROGRAM

JULY 1978

APPENDIX A

CHECKLIST - ENGINEERING DATA

CHECKLIST

0

ENGINEERING DATA

DESIGN, CONSTRUCTION, AND OPERATION PHASE I

NAME OF DAM: Falling Springs

0

1

NDS ID NO.: PA-00372 DER ID NO.: 35-39

Sheet 1 of 4

ITEM	REMARKS
AS-BUILT DRAWINGS	Construction drawings only for spillway modification in 1929.
REGIONAL VICINITY MAP	Project is shown on Pittston, PA - Quadrangle Sheet N4115-W7545/7.5, 1947 photorevised 1969; and Ransom, PA - Quadrangle Sheet N4122.5-W7545/7.5, 1946 photorevised 1969.
CONSTRUCTION HISTORY	Built in 1905 by Spring Brook Water Supply Company from design and under supervision of John H. Lance, Repairs in 1916. Modified in 1922 and in 1929.
TYPICAL SECTIONS OF DAM	None.
OUTLETS: Plan Details Constraints Discharge Ratings	No plans or discharge ratings available. Details given in 1914 report of Pennsylvania Water Supply Commission.

Sheet 2 of 4

0

0.

ITEM	REMARKS
RAINFALL/RESERVOIR RECORDS	None.
DESIGN REPORTS	Report on application for proposed 1929 spillway modification.
GEOLOGY REPORTS	None.
DESIGN COMPUTATIONS: Hydrology and Hydraulics Dam Stability Seepage Studies	1914 hydrology and hydraulics check and 1929 hydrology and hydraulics check for proposed spillway modification. No stability or seepage studies.
MATERIALS INVESTIGATIONS: Boring Records Laboratory Field	None.
POSTCONSTRUCTION SURVEYS OF DAM	None.

0

0

Sheet 3 of 4

	1
ITEM	REMARKS
BORROW SOURCES	Unknown.
MONITORING SYSTEMS	Caretaker visits dam daily to observe and record water level.
MODIFICATIONS	1922 drainage ditch built at left end of main embankment to remedy swampy conditions of the downstream slope at that point. 1929 spillway length increased from 40 to 80 feet. Spillway crest elevation set at former top of flashboards elevation at 1352.74 T.E. Top of embank- ment raised so that a freeboard of $3-1/2$ feet is avail- able on new spillway crest.
HIGH POOL RECORDS	None.
POSTCONSTRUCTION ENGINEERING STUDIES AND REPORTS	None.
PRIOR ACCIDENTS OR FAILURE OF DAM: Description Reports	First season that dam was in service, slides occurred in clay material on both upstream and downstream faces as described in 1914 Water Supply Commission report.

A-3

Sheet 4 of 4

1

Ó.

0.

Matt	BFMABKS
MAINTENANCE AND OPERATION RECORDS	No detailed operation records.
SPILLWAY: Plan Sections Details	Plans and sections of original and modified spillways shown on 1929 spillway modification drawings.
OPERATING EQUIPMENT: Plans Details	Unavailable.
PREVIOUS INSPECTIONS Dates Deficiencies	 1917 settlement of top of embankments. 1919 settlement of crest over the entire length. 1920 uneven and unfinished condition of top of embankment but was disrupted; saturated area at lower portion of main embankment on the left of the gatehouse; slight disintegration of the concrete in the abutments of the spillway. 1921 work of raising the top of the embankment and relaying the upper part of the paving has not been completed; saturated area at lower portion of the spillway. 1921 work of raising the top of the main embankment; deterioration of the concrete at the spillway. 1922 small amount of leakage through wall on right of spillway; raising of top of embankment has been completed; saturated area at lower portion of the spillway. 1924 same as 1922.

A-4

0

•

Sheet 4a of 4

0

TTEM	REMARKS
PREVIOUS INSPECTIONS (con't.)	1927 seepage at toe; concrete disintegration on spillway abutments; two openings of 4 feet by 12 inches in flash-
	boards; wall at the right of the spillway and the spillway abutments are badly disintegrated; work on the main em-
	bankment is finished but is rough.
	1949 concrete way on the right of the outlet is badly dis- integrated; construction material in spillway; work in pro-
	gress of rebuilding the spillway.
	1930 small stream from the toe at the left end of the main
	embankment.
	of the embankment: stream of a depth of 1-1/2 inches
	from the 20" C.I. core wall drain; leakage at the blowoff
	and in back of the valve house; considerable amount of
	water from blind drain along the left end of the main em-
	bankment and adjacent to the steep hillside; considerable
	amount of brush growing on the auxiliary embankment and
	there is a swampy area along the toe of the auxiliary em-
	Dankment near the left end.
	1-1/2 inches of water flowing from core wall drain: see-
	page from left hillside; small flow at end of blind drain
	at left end of toe and from point 10 feet to right.
	1941 number of stones from dry masonry wall at upstream
	edge of crest are displaced; slight flow from core wall
	drain; some flow from blowoff pipe; seepage between left
	and center pipe at valve house outlets; downstream slope
	was wet and swampy at Valve nouse; seepage Irom ledge rock of left billside near base of main embantment: small
	amount of leakage in several places at toe to left of valve
	house: toe of auxiliary embankment is wet and swampy
	over a length of about 150 feet; tree growth across lower
	end of wasteway; disintegration of concrete in pavement
	at lower end of blowoff pipes; pine trees along toe at in-
	tersection of dam and right hillside.
	1943 stones displaced from dry masonry wall upstream
	lace: seepage from shale rock ledge on left end near toe

)

-

0

(

Sheet 4a of 4	REMARKS	of embankment; slight flow from core wall drain; down- stream toe was swampy around valve house at toe; disin- tegration of concrete pavement and walls below blowoffs; pine trees along toe at intersection of embankment and right hillside.	1957 wasteway channel riprap is loose; torn-up dead trees in wasteway channel should be cleaned out; general need for maintenance. 1965 few small trees and brush on downstream face.		
ENGINEERING DATA	ITEM	PREVIOUS INSPECTIONS (cont'd.)			

CHECKLIST

ENGINEERING DATA

HYDROLOGY AND HYDRAULICS

DER

NDS

NAME OF DAM: Falling Springs ID NO.: PA-00372 ID NO.: 35-39

ELEVATION TOP NORMAL POOL (STORAGE CAPACITY): Elevation 1352.74

ELEVATION TOP FLOOD CONTROL POOL (STORAGE CAPACITY): Elevation 1356.24

ELEVATION MAXIMUM DESIGN POOL: Elevation 1356.24

ELEVATION TOP DAM: Elevation 1356.24

SPILLWAY CREST:

- a. Elevation 1352.74 T.E.
- Concrete, broad-crested weir. b. Type _____
- 1,0' c. Width
- 80.0' d. Length

e. Location Spillover _____ Right side of main embankment.

f. Number and Type of Gates None.

OUTLET WORKS:

- a. Type <u>Cast-iron pipe</u>. b. Location <u>Near left abutment of main embankment</u>.
- c. Entrance Inverts _ Elevation 1287.0 (estimated).
- d. Exit Inverts Elevation 1286.14.
- e. Emergency Draindown Facilities 2-20" cast-iron pipes.

HYDROMETEOROLOGICAL GAGES:

- a. Type None. b. Location None. c. Records None.

MAXIMUM NONDAMAGING DISCHARGE: 1,110 cfs.

SUSQUEHANNA RIVER BASIN

()

FALLING SPRINGS CREEK, LACKAWANNA COUNTY

PENNSYLVANIA

FALLING SPRINGS DAM

NDS ID No. PA-00372 DER ID No. 35-39

PENNSYLVANIA GAS AND WATER COMPANY

PHASE I INSPECTION REPORT

NATIONAL DAM INSPECTION PROGRAM

JULY 1978

APPENDIX B

CHECKLIST - VISUAL INSPECTION

CHECKLIST

0

0

VISUAL INSPECTION

PHASE I

•	nnsylvanta		ant	emperature: 71° F.		1: 1283.8 msl						
	Lackawanna State: Pe	(D No.: 35-39	Hazard Category: Signific	: Partly cloudy, warm Te		allwater at Time of Inspection		(PG&W)	(PG&W)	(PG&W)	(GFCC) Recorder	
1 100111	gs County:	DER 1	e core wall-2 embank 1	1978 ments. Weather		tion: <u>1352.8</u> msl/T		D. R. Kaufman	J. Skoritowski	E. Sharjolis	J. M. Crouse	
	Falling Sprin	PA-00372	h with concret	1: 5-6 Iune	ndition: Moist	Time of Inspec	nel:	(GFCC)	(GFCC)	(GFCC)	.	
	Name of Dam:	NDS ID No.:	Type of Dam: Eart	Date(s) Inspection	General Soil Coi	Pool Elevation at	Inspection Person	D. R. Ebersole	W. E. Seip	A. H. Whitman		

B-1

0

MAIN EMBANKMENT Sheet <u>1</u> of <u>2</u>

d. urface			small tracks	<pre>ment General cover of light brush over riprap. Brush is about 18" high 1 most places; at several locations brush is somewhat heavier and is about 3-1/2" high</pre>
OBSERVATIONS Upstream surface submerged No cracks on downstream su	None.	None.	Vertical: alignment uneven- pools of water stand in tire of roadway along dam crest Horizontal: no irregularities	Riprap on upstream embankn slope generally in good condition.
VISUAL EXAMINATION OF SURFACE CRACKS	UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	SLOUGHING OR EROSION: Embankment Slopes Abutment Slopes	CREST ALIGNMENT: Vertical Horizontal	RIPRAP FAILURES

.

EMBANKMENT Sheet 2 of 2

0

ł

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
JUNCTION OF EMBANKMENT WITH: Abutment Spillway Other Features	Several trees of about 12'height and 4" diameter at the junction of the main embankment with the left end of the spillway on the crest.	
ANY NOTICEABLE SEEPAGE	Clear seepage at vertical rock face 100' to left of valve house. Area of seepage is 100' x 40'. Second clear seepage area at toe 20' from rock cliff. Joins first seepage 15' D/S.	Seepage forms small stream in open channel. Total discharge 5-10 gpm. Seepage stream joins out- let works discharge about 180' D/S.
STAFF GAGE AND RECORDER	None.	
DRAINS	20" cast-iron pipe drain from longitudinal tunnel in the base of the core wall of the main embank- ment. Rock-lined open channel drain at lower portion of main em- bankment on left side of valve	Flow from core wall drain about 5 " wide-orange, fine, clayey material at outlet invert and in D/S channel. Flow in channel drain 5-10 gpm.
CONDITION OF DOWNSTREAM SLOPE OF EMBANKMENT	Brush over entire area about 3-1/2' high. Brush is more dense in places and is mixed with young trees up to 12' high and 3" diameter. Row of mature pine trees spaced at 12' at toe. Fall- en, rotting 50' tree on slope.	Beer cans and cutting debris scattered over slope area.

AUXILIARY EMBANKMENT

0

0

Sheet 1 of 2

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
URFACE CRACKS	Upstream surface submerged. No cracks on downstream surface.	
INUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	None.	
LOUGHING OR EROSION: Embankment Slopes Abutment Slopes	None.	
CREST ALIGNMENT: Vertical Horizontal	Vertical: alignment uneven-small pools of water stand in tire tracks of roadway along dam crest. Horizontal: no irregularities.	
uprap failures	Small, local displacements of riprap on upstream face. Riprap is generally in good condition.	Riprap is generally covered with small brush 18" high.

AUXILIARY EMBANKMENT

•

.

0

0

Sheet 2 of 2

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
JUNCTION OF EMBANKMENT WITH: Abutment Spillway Other Features	Small pool of standing water at left abutment on downstream face. Water probably from surface drain- age from access road.	Pool area is 6' long by 5' wide. Pool is 1/2 foot deep. No out- flow from pool.
ANY NOTICEABLE SEEPAGE	General wet area at toe of dam about 200' long. Swampy con- dition extends downstream about 600' and is roughly triangular in shape. No discernable flow. No outlet from swamp.	Old cuttings of brush and small trees lying in swampy area of toe.
STAFF GAGE AND RECORDER	None.	
DRAINS	None.	
CONDITION OF DOWNSTREAM SLOPE OF EMBANKMENT	Generally covered with brush with average depth of 3-1/2'. Broad- leafed trees 60' in height immed- iately below toe.	

)

B-5

OUTLET WORKS

0

0

Sheet 1 of 1

AMINATION OF ID SPALLING OF JRFACES IN DUIT	OBSERVATIONS Outlet conduits are cast-iron pipe.	REMARKS OR RECOMMENDATIONS
RUCTURE	Condition and design unknown.	
STRUCTURE	Valve house contains four gate valves with well-rusted gear reducers. Valves covered with sawdust. Core wall drain pipe runs under valve house.	
CHANNEL	Right channel wall: vertical crack 1/4" wide by 4-1/4" high from channel floor to and through top 9" coping. Crack is 10' down- stream from valve house.	Evidence of attempted repair at one time.
	Left channel wall: complete dis- integration of wall immediately below valve house-top width affected.	CONTINUED ON PAGE B-11
CY GATE	Three men opened left conduit downstream valve partially in 30 minutes-packing leaked. Three men tried unsuccessfully for 30 minutes to open right con- duit downstream valve.	Left downstream valve should be opened and lubricated. Valve should be used frequently. Foot- ing in valve house should be wooden floor instead of sawdust so more leverage can be applied to valves.

)

B-6

UNGATED SPILLWAY

0

0

Sheet 1 of 1

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE WEIR	Concrete is spalled at both mon- olith joints and at transverse crack 10' from right abutment. Depth affected is average of 9"	Moss growth on downstream face and crest. Exposed coarse aggregate entire wetted surfaces.
	and vertical height is 10". joint filler was missing at the monolith joints. Two other transverse sur- face cracks were observed.	CONTINUED ON PAGE B-11
APPROACH CHANNEL	No dry masonry wall on right side of approach channel as shown on plans. From 3' from crest on up- stream, approach channel floor is covered with dead leaves.	
DISCHARGE CHANNEL	Lined with hand-placed riprap for a distance of about 60 feet, transitions to width of about 14 feet, drops off a depth of 6', and returns to rock and hard clay channel.	Grass about 8" long over 50 per- cent of riprap-brush area 3'x3' that is 2' downstream of weir and 8' from left abutment. Minor de- bris below crest.
BRIDGE AND PIERS	None.	
RIGHT SPILLWAY ABUTMENT	Three small spalled areas about 5 "x6"x3" deep on vertical face and top of wall. Vertical surface crack from spillway crest to top of abutment wall. Width of crack 1/4"; depth of crack 1/4". No differential movement. Crack re- pair was attempted at one time.	Cred Flow Flow Flow

INSTRUMENTATION

0

0

Sheet 1 of 1

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
MONUMENTATION/SURVEYS	None.	
OBSERVATION WELLS	None.	
WEIRS	None.	
PIEZOMETERS	None.	
OTHER	None.	

B-8

RESERVOIR AND WATERSHED

0

1

0

Sheet 1 of 1

REMARKS OR RECOMMENDATIONS		ň		
OBSERVATIONS	Steep to moderate slopes; no evidence of creep, rock slides, or land slides.	No sediment problem reported b Owner.	Predominately controlled and forested; minor development.	
VISUAL EXAMINATION OF	SLOPES	SEDIMENTATION	WATERSHED DESCRIPTION	

DOWNSTREAM CHANNEL

0

1

0

Sheet 1 of 1

UAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
ON: ctions	Small amount of debris immedi- ately below spillway crest.	
	Moderate slope of riprap-lined channel to near vertical drop at downstream edge to steep chan- nel of rock and hard clay.	Downstream channel and banks show signs of erosion.
MATE NUMBER OF AND POPULATION	Only a few inhabitable structures would be affected by a large dis- charge from dam.	

REMARKS OR RECOMMENDATIONS		Apparent repair attempt was made some time in past.			
OBSERVATIONS	is 18", increases to 2 feet at base of wall, depth affected is 15" in- to wall. Channel face and lower portion of 9" concrete coping de- teriorated at several places to a depth of 3" and height of 6".	Base of wall disintegrated and un- dermined for entire length-maxi- mum depth into wall of 14" and maximum of 27" in vertical height. End of concrete wall disintegrated 3" in depth and 2 feet in vertical	height.	running into the reservoir for about 2'. The cracks were about 1/4" wide and 1/4" deep. No differential movement at any crack or joint.	
VISUAL EXAMINATION OF	OUTLET CHANNEL (cont'd. from B-6)			CONCRETE WEIR (cont'd. from B-7)	

0

0

M

SUSQUEHANNA RIVER BASIN

FALLING SPRINGS CREEK, LACKAWANNA COUNTY

PENNSYLVANIA

FALLING SPRINGS DAM

NDS ID No. PA-00372 DER ID No. 35-39

PENNSYLVANIA GAS AND WATER COMPANY

PHASE I INSPECTION REPORT NATIONAL DAM INSPECTION PROGRAM

JULY 1978

APPENDIX C

HYDROLOGY AND HYDRAULICS

N

GANNETT FLEMING CORDDRY AND CARPENTER, INC. HARRISBURG, PA. SUBJECT FALLING SMILINGS DAM (35-39) FILE NO. 7613.1R HYDRAVLICS ANALYSIS SHEET NO. 1 OF 6 SHEETS FOR USCE - BALTIAURE DISTRICT COMPUTED BY JMC DATE 11578 CHECKED BY DATE 0-78 (1455) FILE NO. 7613.1R HYDRAVLICS ANALYSIS SHEET NO. 1 OF 6 SHEETS COMPUTED BY JMC DATE 11578 CHECKED BY DATE 0-78
SIGNIFICANT HARARY, SINCE RELATIVELT FEW LIVES COULD BE LOST AND APPRECIACIE ECONOMIC LOSS (OVLD RESULT FROM A FAILURE OF THE DAM
INTERMEDIATE SIZE, SINCE HEIGHT = 61 FEET AND CAPACITY = 838 K-FT.
REFERENCE : " RECOMMENDED GUIDELLINES FOR SAFETY INSPECTION OF DAMS, " P. D-B
SPILLWAY DESIGN FLOOD (SDF) THE SDF SHAVLU BE & PAF TO PAF (FROM P. D-12 OF "REC. GUIDELLINES "). FROM THE BALTIMORE CONTACT, MIKE KANOWITZ, THE SPF IS & PMF.
HIDROLOSY AND HIDRAYLING ANALYSIG KEFERENCE : PHASE I PROCEDURE PACKARE II. A. 2. PMF INFLOW HIDROGRAPH NOT ANALYSIGE a. FRUM CONVENSATION OF MIRE KANONITE WITH ACH, PROMITE PARE AT FALLING SPRINGS D.A. = 1.25 SQ.MI., WITH PMF PEAK OF 9,700 CFS AT FALL, BROOK, D.A. = 9.14 SQ.MI.
$\frac{Q_1}{Q_2} = \left(\frac{D_1A_1}{D_1A_2}\right)^{0.8}$
$U_{k}, Q_{1} = Q_{2} (D.A_{.1} / D.A_{.2})^{0.8}$
$Q_1 = 9,700 (1.25/4.14)^{0.8}$ $Q_1 = 3,720 \text{ CFS} = PAF$ $\therefore \frac{1}{2} \text{ PMF} = 3,720 \text{ CFS}/2 = 1,860 \text{ CFS}$
EFFECT OF UPSTREAM RESERVOIRS NO VPSTREAM RESERVOIRS EXIST THIS PAGE IS BEST QUALITY PRACTICABLE FROM COPY FURNISHED TO DDG
D. ABULITY OF SPILLWART TO FAULT & PAULT 1. CAPACITY OF SPILLWART - REFERENCE, "REPORT UPON THE APPLICATION OF THE SCRAMON - STRUNG BROOK WITCH SERVICE CUMPANY," 19 SEPTEMBER 1923, WATER SUPPLY COMPLISSION OF PENNSYLVAMA.

C -1

-

GANNETT FLEMING CORDDRY AND CARPENTER, INC. HARRISBURG, PA.	SUBJECT TALLING SPRINGS DAM (35-33) FILE NO. 7613, IR HIDDRIDGY AND WIDPATIKS ANALYSIS SHEET NO. 2 OF 6 SHEETS FOR USEE - BALTIMORE DISTRICT COMPUTED BY JAC DATE 6/15/78 CHECKED BY DATE 6-76
D) X Site	I CAPACITY = 800 CTS WITH & HELLIT OF 2 FEET
OVER TH HAVE A WHDE	IE CREST. THE CONTRACT WERE TO BE DURT WILL TOTAL THERNESS OF S PERT, THE CREST ONE FOOT A SMALL I TOT SLOPE AT THE DOWNSTREAM EDGE
hno j	A 2 TO I APPROACH SLOVE
CALCULATE THE DISC	IN COLFFICENT USING THE GENERALIZED WELH EQUATION $(Q = CLH^{3/2})$ $C = Q/LH^{3/2}$ C = 3.54, SM 3.5, Which is ok for

FROM THE FIELD SURVEY CONDUCTED DURING THE VISUAL INSPECTION OF THE DAM, TWO LOW AREAS EXIST ON THE AUXILIARY EMBANKMENT AT ELEVATION 1,355,2" AND ONE LOW AREA EXISTS ON THE NOW EMBLINKMENT AT ELEVATION 1,355,3 SINCE THE SPILLINAT CREST ELENTION IS 1,352.74', THE MAXIAVM HEAD ON THE SPILLWAY BEFORE OVERTOPPING 15 1,355.2'- 1,352.74' = 2.46', SAY 2.5'. THEREFORE, THE SPILLINAT CAMACITY WITHOUT FREEDALD IS:

THE SPILLWAY APPROACH AND GEOMETRIC CONDITIONS

Q= (LH3/2. Q = (3.5) 80 (2.5) THIS PAGE IS BEST QUALITY PRACTICABLE FROM COPY FURNISHED TO DDC

2 PAF PLAK FLOW IS OREATER THAN THE SPILINAN CAPACITY (1,860 7 1,110)

- 6. ROVTING OF & PMF IS NOT AVAILABLE
 - (1.) THE SPILING WILL PALL (1,110/ 1,860) = 0,597 = p = 59.7% OF 2 PAT PEAK
 - (2.) INCLOSURE 3 METHOD TO ESTIMATE THE STORDAE EFFECT OF THE RESERVOIR
 - (a) TRUMSVING SHARE FOR 2 PMF HYDROIGAPH
 - (b.) FROM GRAPH OF TOTAL TIME YS. D.A. FOR THE SUJEVEHAMMA RIVER BASIN, TOTAL TIME - 20.4 NOWN .

RUNOFF ANOUNT = 10, 015 AC-IN = 23.5 INCHES

C-2

- CHELK INCLES OF RINOFF PROVISED BI THE PMF PLAK AND THE TOTAL TIME -RUNDEF VOLUME - \$ 64 = \$ (20.4 HOUR) (1,860 CFS) = 18,972 CFS HOURS 18,972 <u>FT</u> × HOURS × 3,600 AC-VLS × 121N = 18,815 AC-IN Sts × HOURS × 43,560 FT2-HRJ × 1PT CHAININE AREA = 1.25 SP. MI × (640 ACRE) / SP. MI.) = BOO ACRES
STOPACE REGIVERED = 345 AC-PT > STMARE AVAILABLE = 121 AC-PT \therefore The spectrum of palling spanic Dam is inadequate C-3

PLUGEMENTAL	STORAGE	= (Aithe) AV	THIS PAGE IS BEST QUALITY PRACTICABLE
INCREMENTAL	JORAGE	124 K-TT	

50.2 ACRES

	679, 413 FT	•
	Yi	2
the i	Ye	t
(24),1		3
AL	Az	:

Az

10 LOLED X +3560 FT: * Tr, * 679, 413 FT * n2

624.3 FT

 $r_i \uparrow \Delta H = r_i \uparrow \uparrow (\Delta v) = r_i \uparrow \uparrow (2s')$

πre= π(834,3') = 2,186,500 FT2

824.3' + 10 = 834.3'

ASSYME RESERVOR SIDE SLARS OF TH ON IV AND ASSUME CHICOLAR SHAPE

tide O subor	histrocc	P	have to	of competing	1.14	Jul - Ch - J
INATION						
HOLAL POOL	ELEVATION	= 58122	WAY CREST	ELEVATION	*	1352.74
MAX INVA POST.	ELEVATION	* Top	OT DAM EL	EVATION	*	1355.2 1
ALLES IT WES	diver the	N.S. C	SPILLWIN	CREST	2	to ACRES
HEL OF SE	HANN WA	W W,S. C	TOP OF D	in.	•	?

SUBJITUTING, DADC = (1-p) DAOB > (0,403) (867) = 349 K-FT REQUIRED STOLAGE = DADC = 319 AC-FT (C) INCREDIENTIA JORANE AVAILABLE BETWEEN NORAL POIL ELEVATION AND MANIMUM

 $\frac{10,100 \text{ AC-IN} \times \frac{177}{12 \text{ IN}} \times \frac{43,360 \text{ PT}^2 \text{ Hz}}{3,600 \text{ AC-SEC}} = 10,487 \text{ (FS}}{5,600 \text{ AC-SEC}} = 11.3 \text{ HOURS}$ $\frac{1}{h} = \frac{2 \text{ VOL}}{h} = \frac{2 \times 10,487 \text{ (FS-HWRS}}{1,860 \text{ CPS}} = 11.3 \text{ HOURS}$ $1 - p = 1 - 0.507 = 0.403 = \frac{2405}{3405}$ $\Delta A06 = \frac{1}{5}6h = \text{VOL} = 10,400 \text{ AC-IN} \times (177/(21N))^2 \text{ B67 AC-FT}$

OF KUNDTE THEORED BY IS INCLES OF RUNDER OVER THE DRAINAGE AREA, CALCULATE THE EQUIVALENT TOTAL TUNE OF 2 PANE HYDROBRAPH VOL = 2 bh ; b = 2 m VOL = 2 bh ; b = 2 m VOL = 13" RUNTE × 8 OU ARED = 10,400 AC-IN 10,400 AC-IN × 1FT IZIN × 43,560 PT = 10,400 AC-IN 10,400 AC-IN × 1FT IZIN × 43,560 PT = 10,487 (FS-WS)

COMPUTED BY JAC DATE 6/15/19 CHECKED BY DAW DATE 6-78 SINCE 23.5 INCH. IF LONOFF IS A WIGH VILVE FOR \$ PAF, REDUCL THE INCHES OF RUNOFF TO \$ = 13, AS PLR THE INSTRUCTIONS OF THE BUCHMONE (WILLT, MIKE KANOWITE. FROM \$ PAF PEAK AND THE VILWE OF RUNOFF PROVIDED BY 13 INCHES OF RUNOFF OVER THE DRAINAGE AREA,

_ FILE NO. _ 7613, 1R

SHEETS

SHEET NO.

GANNETT FLEMING CORDDRY SUBJECT 1 ALTING STRINGS DAM (35-39) AND CARPENTER, INC. HARRISBURG, PA.

POOL 1

GANNETT FLEMING CORDDRY AND CARPENTER, INC. HARRISBURG, PA.	SUBJECT FALLING JARING DAM (35-33) FILE NO. 7613 HIDLO 264 AND NTORAVULS AVAILID SHEET NO. 4 OF FOR VICE - BAUTIMME DISTORT COMPUTED BY JM DATE 6/15/78 CHECKED BY DAW	3.1K 6 sheets Date 4 78
4	HICENT OF & PANE THAT SPILLWAY CAN PASS	
	GENERAL FOLMULA	
%. UF 는 AMF THAT SI	PILLWAY CAN PASS = UT x 100%,	
MARTE	QT - QSPRIVAT + 25/Dt,	
	S = Sj For upprehm Reserving Cases	
P MC	T = EQUIVALENT TOTAL TUNE OF FMF HYDRIGANH	
い of 支 PAF =	1,110 + (<u>2x(124))C-PT</u> x <u>43,560 FT-NKS</u>) 1,110 + (<u>1,3 HOVRS</u> x <u>3,600 KC-SES</u>) x (00%) 1,860	
-	1,110 + 266 × 100%	
0 70 0F ± PMF =	74 % THIS PAGE IS BEST QUALITY PRACT	TICABLE
	CHECK 76 OF 100-YR FLOOD THAT SPILLWAY CAN PASS	
	100-YK PLODO PEAK ESTIMATE	
ELTERERICE : "HYD	ADDARE STUDY - TPOPICAL STORM AGNES, COTE, NAD, DELEAN	BER 1975
DRAINARE	AREA = 1.25 SR. MI A	
L06 10 .	m = Cm + 0.75 Lo6 (A)	
100 10-	$1 = 203 + 0.75 \log(125)$	
	= 2 153	
S = STAN	DALL DEVIATION " CS - U.D.S LOG (A)	
	FROM FILVRE 24, Cs = 0.358	
<u>`</u>	= 0.358 - 0.05 Lo6 (1.25)	
	= 0.353	
	FROM FIGHER CS SKEW COLFFICIENT = g = +0.45	
0	D) = 106 (10 -) + K (D -) <	
	1) = 2.153 + 2.6505 (D.353) = 3.089	
SP 11840A Q (1) = 1,226, SAY 1,230 CFS = 100-YR 72000 C-4	

GANNETT FLEMING CORDDRY SUBJECT FALLING JAINE, DAN (35-39) FILE NO. 7613, IR AND CARPENTER, INC. HARRISBURG, PA. To OF 193 TK THAT SPILWING ON PALL = QT/QND X 100% (SEE SHELL 4)

ASSUME T = EXEMPLENT TOTAL TIME OF PAPE HIDBONHAPA. A CONFERNATIVE ESTIMATE WILL RESULT SINCE THE TOTAL TIME OF 100-YR EVENT WOULD BE SOMEWHAT LESS THAN THE TATAL TIME OF PONF HIDDOWNAPH.

 $\frac{1}{100 \text{ of } 100 \text{ -YR}} = \frac{1}{100 \text{ + } \left(\frac{2 \times [101] \text{ K} \text{ - FT}}{11.3 \text{ WORS}} \times \frac{43,300 \text{ FT}^2 \text{ - W}}{3,000 \text{ K} \text{ - SECS}}\right)} \times [00\%]$

1,110 + 266	5
1,230	

90 OF 100 - 112 %

SPILLWAY CAPACITY THAT SHE BE REALIZED IF THE LABANKAENT ELEVATION WAS BROWNT UP TO THE DESIGN ELEVATION

DEJON ELEWITION OF EMBANKABONT	.:	1.356.24'
SPILLWALL CREDE ELEVATION	3	1.3 57.74
POTENTIAL AVAILABLE WEAD	-	3.5'

SPILUMA CHARTY INCLEASE $Q = C \ L \ H^{3/2}$ $Q = (3.5) \ 80 \ (3.5)^{3/2}$ $Q = 1,833 \ , 5 \ M \ 1,830 \ (FS)$

The OF 2 PAF THAT INCREASED SPULINAL CAPACITY CAN PASS = $\frac{Q_T}{Q_{2,MT}} \times (00\%)$ The OF 2 PAF WITH INCREASE = 1,830 + $(\frac{2 \times (3.5 \times 13.6) \text{ AC-FT}}{11.3 \text{ MOTHS}} \times \frac{13.500 \text{ FT}^2 + \text{Hxs}}{3.100 \text{ K}^{-3/T}})$

% OF 2 PAF WHILL W(RELLE = 1,830 + 372 1,660 THIS PAGE IS BEST QUALITY PRACTICABLE FROM COFY FURNISHED TO DDC C-S GANNETT FLEMING CORDORY AND CARPENTER, INC. MARRISBURG, PA. 10 UP 100-YK FLOOD THAT INCREME = <u>J. B30 + 372</u> X 1009. 1. OF 100-YK FLOOD WITH INCREME = <u>179 7.</u>

JUMMANY TABLE 7. PASSING WITHOUT OVERTOPPING DAM

EVENT	ARESENT CONDITION LOW POWTS IN Embankment	DESIGN CONDITION EMBANKAENT AT DENGN ELEVATION	
t PMF	74	118	
100-YEAR FLOOD,	112	179	

THIS PAGE IS BEST QUALITY PRACTICABLE FROM COPY FURNISHED TO DDQ

C-6

SUSQUEHANNA RIVER BASIN

0

(.)

FALLING SPRINGS CREEK, LACKAWANNA COUNTY

PENNSYLVANIA

FALLING SPRINGS DAM

NDS ID No. PA-00372 DER ID No. 35-39

PENNSYLVANIA GAS AND WATER COMPANY

PHASE I INSPECTION REPORT NATIONAL DAM INSPECTION PROGRAM

JULY 1978

APPENDIX D PHOTOGRAPHS



A. Main Embankment View from Right Abutment

0



B. Main Embankment View from Left Abutment



C. Spillway



0

D. Spillway Crest



E. Spillway Apron

0

0



F. Downstream Channel from Edge of Spillway Apron Looking Downstream

1

0

0

0



G. Core Wall Drain and Outlet Works from Downstream End of Outlet Channel



H. Undermining and Disintegration of Left Outlet Channel Wall from Upstream End of Outlet Channel

1

0



I. Upstream Face of Auxiliary Embankment from High Natural Ground Between the Embankments



J. Auxiliary Embankment View from Left Abutment





M. Diversion Structure Below Falling Springs Dam for Supply to Campbell Ledge Storage Dam



N. Outfall of Falling Springs Creek Under Road and Railroad Tracks into Susquehanna River

D-7

1

SUSQUEHANNA RIVER BASIN

FALLING SPRINGS CREEK, LACKAWANNA COUNTY

PENNSYLVANIA

FALLING SPRINGS DAM

NDS ID No. PA-00372 DER ID No. 35-39

PENNSYLVANIA GAS AND WATER COMPANY

PHASE I INSPECTION REPORT NATIONAL DAM INSPECTION PROGRAM

JULY 1978

<u>APPENDIX E</u> <u>GEOLOGY</u>

0

. .

1

.

APPENDIX E

GEOLOGY

1. General Geology. The damsite and reservoir are located in Lackawanna County. Lackawanna County was completely covered with ice during the last continental glaciation of Pleistocene time. The general direction of ice movement was $S 35^{\circ} - 40^{\circ}$ W. Glacial drift covers the entire County, except where subsequent erosion has removed it. Thick deposits of glacial outwash occur in many places along the Lackawanna River, and are 50 to 100 feet thick near Dickson, Scranton, and Moosic.

The only important structural feature in Lackawanna County is the Lackawanna Syncline, which traverses the County in a southwesterly direction. The syncline enters the County at the northeast corner as a narrow shallow trough, gradually deepens and broadens toward the southwest, and reaches its maximum development in Luzerne County. The rock formations exposed range from the post-Pottsville formations (youngest) through the Pottsville, Mauch Chunk shale, Pocono sandstone to the Damascus formation of the Catskill group (oldest). The rim rocks, the Pottsville formation and Pocono sandstone, have dips that rarely exceed 10° to 20° and form a rather simple syncline. The core rocks, the post-Pottsville formations, are folded into a series of minor anticlines and synclines which trend about N 70° E. The rocks in the northwestern and southeastern parts of the County, outside of the limits of Lackawanna Syncline, are generally horizontally stratified.

The Lackawanna River, in general, follows the axis of the Lackawanna Syncline. Southeast of the Lackawanna River, the rise in terrain in quite gradual and the crests of the high mountains are several miles from the Lackawanna River. Streams, such as Roaring Brook, Stafford Meadow Brook, and Spring Brook, have cut deep canyons through the mountains and follow a tortuous course to their confluence with the Lackawanna River near Scranton, Pennsylvania. Northwest of

E-1

Lackawanna River, the mountains rise abruptly to a sharp ridge which in most places is somewhat higher than the country to the northwest. Consequently, most of the drainage in this part of the County flow westward by way of Tunkhannock Creek. A few small tributary streams, however, such as Leggetts Creek, flow eastward from this area into Lackawanna River. In the area of interest, the Lackawanna River streambed is founded in post-Pottsville formations. Proceeding uphill from the river, the older Pottsville formation, Mauch Chunk shale, Pocono sandstone, and Catskill continental group are encountered in turn. The tributary streams, in flowing down the mountains, have generally cut through or around the hard sandstone and conglomerate members, and have eroded their streambed into the softer shales and glacial till. The Catskill continental group of rocks underlies the greater part of Lackawanna County.

Dian

2. Site Geology. The dam and reservoir are sited in nearly horizontally stratified gray Catskill sandy shale and Pocono sandstone, northwest of the Lackawanna Syncline and Lackawanna River and northeast of the Susquehanna River into which Falling Springs Creek flows. Whereas, other streams to the north of Falling Springs Creek, cut across the Pocono sandstone formation and drain into Lackawanna River, Falling Springs Creek generally follows the interface between the Catskill and Pocono formations, and parallels the Lackawanna River, to a confluence with the Susquehanna River. Rock at the damsite, whether it be Catskill sandy shale or Pocono sandstone, was hard, firm and close to the surface. The entire dam is founded upon rock.