

AD-A063 577

BAKER (MICHAEL) JR INC BEAVER PA  
NATIONAL DAM SAFETY PROGRAM. JAMES RIVER BASIN. SUGAR HOLLOW (I--ETC(U)  
SEP 78 M BAKER

F/G 13/2

DACW65-78-D-0016

NL

UNCLASSIFIED

| OF |  
ADA  
063577



END  
DATE  
FILED  
DDC

3 -79

JAMES RIVER BASIN

Name of Dam: Sugar Hollow

Location: Albemarle County, State of Virginia


Inventory Number: VA 00303



AD A063527

DDC FILE COPY  
DDC

# PHASE I INSPECTION REPORT NATIONAL DAM SAFETY PROGRAM



PREPARED FOR

NORFOLK DISTRICT CORPS OF ENGINEERS  
803 FRONT STREET  
NORFOLK, VIRGINIA 23510

PREPARED BY  
MICHAEL BAKER, JR., INC.  
BEAVER, PENNSYLVANIA 15009

This document has been approved  
for public release and sales; its  
distribution is unlimited.

79 01 16 199  
SEPTEMBER 1978

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER VA 00303	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Inspection Report National Dam Safety Program, James River Basin - Sugar Hollow (Inventory Number VA 00303), Albemarle County, State of Virginia.		5. TYPE OF REPORT & PERIOD COVERED (9) Final rep't,
7. AUTHOR(s) <b>10</b> Michael Baker, Jr. [redacted] Michael Baker III   15		6. PERFORMING ORG. REPORT NUMBER DACW 65-78-D-0016
9. PERFORMING ORGANIZATION NAME AND ADDRESS		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
11. CONTROLLING OFFICE NAME AND ADDRESS U. S. Army Engineering District, Norfolk 803 Front Street Norfolk, VA 23510		12. REPORT DATE (11) Sep [redacted] 1978
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) <b>12</b> 69p.		13. NUMBER OF PAGES 63
		15. SECURITY CLASS. (of this report) Unclassified
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report)  Approved for public release; distribution unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES  Copies are obtainable from National Technical Information Service, Springfield, Virginia 22151		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number)  Dams - VA National Dam Safety Program Phase I Dam Safety Dam Inspection		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number)  (See reverse side)		

420 795

## 20. Abstract

Pursuant to Public Law 92-367, Phase I Inspection Reports are prepared under guidance contained in the recommended guidelines for safety inspection of dams, published by the Office of Chief of Engineers, Washington, D. C. 20314. The purpose of a Phase I investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general conditions of the dam is based upon available data and visual inspections. Detailed investigation and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

Based upon the field conditions at the time of the field inspection and all available engineering data, the Phase I report addresses the hydraulic, hydrologic, geologic, geotechnic, and structural aspects of the dam. The engineering techniques employed give a reasonably accurate assessment of the conditions of the dam. It should be realized that certain engineering aspects cannot be fully analyzed during a Phase I inspection. Assessment and remedial measures in the report include the requirements of additional indepth study when necessary.

Phase I reports include project information of the dam and appurtenances, all existing engineering data, operational procedures, hydraulic/hydrologic data of the watershed, dam stability, visual inspection report and an assessment including required remedial measures.

PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM

CONTENTS

	<u>Page</u>
Brief Assessment of Dam. . . . .	1
Overall View of Dam. . . . .	3
Section 1: Project Information. . . . .	5
Section 2: Engineering Data . . . . .	9
Section 3: Visual Inspection. . . . .	11
Section 4: Operational Procedures . . . . .	15
Section 5: Hydraulic/Hydrologic Data. . . . .	17
Section 6: Dam Stability. . . . .	23
Section 7: Assessment/Remedial Measures . . . . .	25

Appendices

- I. Plates
- II. Photographs
- III. Check List - Visual Inspection
- IV. Check List - Engineering Data
- V. Boring Logs and Locations
- VI. Stability Analyses

NAME OF DAM: SUGAR HOLLOW

PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM

Name of Dam: Sugar Hollow  
State: Virginia  
County: Albemarle  
Stream: Moormans River  
Date of Inspection: 25 July 1978

This document has been approved  
for public release and sale; its  
distribution is unlimited.

BRIEF ASSESSMENT OF DAM

Sugar Hollow Dam is a gated concrete gravity structure, approximately 77 feet high and 480 feet long. The dam is owned and operated by the Rivanna Water and Sewer Authority for the water supply of the City of Charlottesville.

The gated spillway will pass 18 percent of the Probable Maximum Flood when closed, 62 percent of the Probable Maximum Flood when opened, and 80 percent of the Probable Maximum Flood with the gates removed. Therefore, the spillway is inadequate. Structural calculations indicate that the dam meets the stability requirements of the Recommended Guidelines for Safety Inspection of Dams with respect to overturning and sliding for the Probable Maximum Flood and normal pool conditions.


The owner should immediately conduct a detailed assessment of spillway capacity to pass the Probable Maximum Flood. This assessment should include the possibility of removing the spillway gates as well as other measures. Remedial work that can be performed as part of the annual maintenance program should include: monitoring clear minor seepage areas during higher reservoir levels, cleaning mud and debris from the drainage gallery, clearing plugged foundation drains, operating the lift gates to check for proper functioning, and repairing erosion on the left upstream shoreline.

MICHAEL BAKER, JR., INC.

SUBMITTED:

Original signed by  
JAMES A. WALSH

James A. Walsh  
Chief, Design Branch  
Original signed by  
ZANE M. GOODWIN

  
Michael Baker, III, P.E.  
Chairman of the Board and  
Chief Executive Officer

RECOMMENDED:


Zane M. Goodwin  
Original signed by:  
Chief, Engineering

APPROVED:


Douglas L. Haller

Douglas L. Haller  
Colonel, Corps of Engineers  
District Engineer

Date: SEP 28 1978 SdP 8 1978



NAME OF DAM: SUGAR HOLLOW



OVERALL VIEW OF DAM

79 01 16 199

PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM  
NAME OF DAM: SUGAR HOLLOW ID# VA 00303

SECTION 1 - PROJECT INFORMATION

1.1 General

- 1.1.1 Authority: Public Law 92-367, 8 August 1972 authorized the Secretary of the Army, through the Corps of Engineers to initiate a national program of safety inspections of dams throughout the United States. The Norfolk District has been assigned the responsibility of supervising the inspection of dams in the Commonwealth of Virginia.
- 1.1.2 Purpose of Inspection: The purpose is to conduct a Phase I inspection according to the Recommended Guidelines for Safety Inspection of Dams. The main responsibility is to expeditiously identify those dams which may be a potential hazard to human life or property.

1.2 Description of Project

- 1.2.1 Description of Dam and Appurtenances: Sugar Hollow Dam, also known as Moormans River Storage Dam, is a concrete gravity structure 480 feet long, as measured along the upstream arc. The 480 feet length consists of a 225 feet spillway, a 100.5 feet south bulkhead, and a 154.5 feet north bulkhead (see Plates 1 and 2). The maximum height of the dam is 77 feet. A drainage gallery extends from abutment to abutment with 3.5 inch diameter pipe foundation drains spaced at regular intervals throughout the gallery. The drains were observed during the inspection (see Plate 3).

A stilling pool located at the toe of the dam is impounded by a seven feet high concrete overflow dam (see Photo 3).

ACCESS		for
NTIS	White Section	<input checked="" type="checkbox"/>
DDC	B & W Section	<input type="checkbox"/>
UNANNOUNCED		<input type="checkbox"/>
JUSTIFICATION		
BY		
DISTRIBUTION/AVAILABILITY CODES		
Dist	AVAIL.	and/or SPECIAL
A		

To the left of the stilling pool at the toe of the dam is a 30 inch diameter blow off pipe and a 24 inch diameter water supply main which exits from the gallery tunnel and traverses the left bank of the downstream channel (see Plate 5).

NAME OF DAM: SUGAR HOLLOW

The spillway is of the gated crest type with eight gates approximately 25 feet long and five feet high. The individual gates are raised or lowered by a single electric motor driven gate hoist. The hoist is mounted on rails extending across the entire length of the spillway to permit access to each gate.

The intake tower is located adjacent to the left end of the spillway.

- 1.2.2      Location: Sugar Hollow Dam is located on Moormans River approximately five miles upstream from the Town of Whitehall, Virginia (population 55) and approximately 18.2 miles northwest of Charlottesville, Virginia (population 32,000). Camp Sugar Hollow, a summer camp for girl scouts, is located approximately 1.1 miles downstream from the dam and is occupied on a seasonal basis. The operator's residence for this dam is located several hundred feet downstream. A Location Plan is included in this report.
- 1.2.3      Size Classification: The maximum height of the dam is 77 feet. The reservoir volume to the gated spillway crest is 1667 acre-feet. Therefore, the dam is in the "intermediate" size category as defined by the Recommended Guidelines for Safety Inspection of Dams.
- 1.2.4      Hazard Classification: Due to the proximity of the Town of Whitehall, Virginia with a population of 55, the Girl Scout camp 1.1 miles downstream, and the dam operator's residence; many lives could be lost in the event of failure of the dam. Therefore the dam is considered in the "high" hazard category as defined by Section 2.1.2 of the Recommended Guidelines for Safety Inspection of Dams. The hazard classification used to categorize dams is a function of location only and has nothing to do with its stability or probability of failure.
- 1.2.5      Ownership: The Sugar Hollow Dam is owned by the Rivanna Water and Sewer Authority, Charlottesville, Virginia.
- 1.2.6      Purpose of Dam: The dam is used for water supply to the City of Charlottesville, Virginia. There is also limited recreational fishing on the reservoir.

NAME OF DAM: SUGAR HOLLOW

- 1.2.7      Design and Construction History: The existing facility was designed for the owner by Mr. Edward W. Saunders, Consulting Engineer, Charlottesville, Virginia in January 1946. The core borings were made in December 1944 and January 1945 by Mott Drilling Company, Huntingdon, West Virginia. The construction was done by Faulconer Construction Co. in 1950. No known construction has been undertaken since the dam was built.
- 1.2.8      Normal Operational Procedures: The reservoir is normally operated with pool level at the top of the spillway crest gates, elevation 975.0. Two 18 inch diameter intake pipes with invert elevations of 936.22 and 962.72 are located on the upstream face of the intake tower. Intakes connect to a 24 inch diameter waterline with invert elevation 913.79 which supplies the City of Charlottesville. A 30 inch diameter blow off line is located within the intake tower and has an invert elevation of 913.17.

There is no formal maintenance schedule at the dam site. However, there is a resident dam operator.

### 1.3 Pertinent Data

- 1.3.1      Drainage Area: The drainage area of Sugar Hollow Dam is approximately 17.2 square miles.
- 1.3.2      Discharge at Dam Site: The maximum flood at the dam site is not known.
- Gated Spillway  
Pool level at top of dam  
Gates closed. . . . . 5288 c.f.s.  
Gates opened. . . . . 17,928 c.f.s.  
Gates removed . . . . . 23,240 c.f.s.
- 1.3.3      Dam and Reservoir Data: Pertinent data on the dam and reservoir are shown in the following table:

NAME OF DAM: SUGAR HOLLOW

TABLE 1.1 DAM AND RESERVOIR DATA

Item	Elevation feet M.S.L.	Area acres (a)	Reservoir			Length feet
			Acre- feet (a)	Watershed inches (b)	Capacity	
Top of dam	980.0	53	1590	1.7	-	-
Gated spillway crest (c)	970.0	45	1105	1.2	2600	
	(d) 975.0	48	1320	1.4	-	-
Streambed at center- line of dam	915+	-	-	-	-	-

- (a) Total area and storage.  
(b) Based on 17.2 square miles.  
(c) Crest gates opened.  
(d) Crest gates closed.

NAME OF DAM: SUGAR HOLLOW

## SECTION 2 - ENGINEERING DATA

2.1 Design: The design data reviewed included the following:

- 1) Photocopies of the design plans prepared by Saunders and Wheeler Consulting Engineers in 1946 and furnished by the Rivanna Water and Sewer Authority (Plates 1 through 5).
- 2) Core borings performed by Mott Core Drilling Company in 1944 and 1945 (Appendix V).
- 3) Storage graphs were prepared by Polglaze and Basenberg Engineers, 1959.

No structural design calculations were available.

2.2 Construction: The construction of the dam was completed by Faulconer Construction Co. in 1950. Construction photos were taken and are available at the Rivanna Water and Sewer Authority's office.

2.3 Operation: The dam is operated and maintained by the Rivanna Water and Sewer Authority as part of its water supply system. There is a full time dam operator; however, no formal records of operation were available.

### 2.4 Evaluation

2.4.1 Design: The drawings provided by the Rivanna Water and Sewer Authority were adequate to review the design of the Sugar Hollow Dam. Although structural design calculations were not available, the layout and general dimensions of the dam did not indicate any obvious design deficiencies.

2.4.2 Construction: There were no as-built plans or concrete cylinder test results provided to adequately assess the quality of work performed. The design drawings were checked against the as-built conditions, and there appeared to be little or no deviation between the two.

2.4.3 Operation: Based on the visual inspection and the review of the design plans, the operation of the water supply facility by full time personnel is adequate.

## SECTION 3 - VISUAL INSPECTION

### 3.1 Findings

- 3.1.1 General: The dam and its appurtenant structures were found to be in good overall condition at the time of the inspection. The problems noted during the visual inspection of the dam do not require immediate remedial treatment but should be corrected as a part of a regular maintenance schedule. Noteworthy deficiencies are described briefly in the following paragraphs. A complete visual inspection check list is given in Appendix III.
- 3.1.2 Dam: Generally, all concrete structures appeared to be in good condition. However, minor spalling of the spillway beneath the main overflow section was observed.
- Evidence of spalling, cracking and seepage was observed on the downstream face of the left non-overflow section. Clear seepage was observed at the construction joints. Vegetation was observed to be growing on the downstream face of the left non-overflow section.
- The original intake dam which is now being used to impound the stilling basin is in fair condition. Spalled and cracked areas were noted sporadically along the crest of the small dam. Eroded areas in the concrete face were also noted with flow present in these areas (see Photo 3).
- Although the dam was grouted during construction, active seepage is present in the left abutment area near the toe of the dam adjacent to the 24 inch water supply line for a distance of approximately 40 feet in the downstream direction. Drainage was present from a four inch terra-cotta drain. Drainage and clear seepage amounted to approximately three g.p.m., two-thirds of which was drainage from the terra-cotta pipe.
- Within the gallery that extends through the dam, 3.5 inch foundation drains were present at regular intervals. The drains were full of water at the time of inspection. Water from the drains is collected by an overflow trough that extends the entire length of the

NAME OF DAM: SUGAR HOLLOW

gallery. Water was present in the overflow trough (see Plate 3). Part of the drainage system appeared to be functioning properly. Some of the drains in the right end of the gallery were covered with mud and debris, and were not functioning.

Within the gallery, spalling was evident at construction joints along with moisture and calcite deposits. This was typical for all construction joints.

- 3.1.3 Appurtenant Structures: Some minor spalling and surface cracks were present on the intake tower and the walkway along the crest of the dam. Neoprene sealant had been "squeezed" out of the expansion joints along the crest; approximately one-fourth to one-half of an inch of expansion material is remaining. The crest gates were in good condition with no leakage present. It was reported during the time of inspection that the gates were not regularly operated. This was verified by the fact that the tracked gate hoist had a light coating of rust on the tracks and the hoist.
- 3.1.4 Reservoir Area: Evidence of erosion in the left abutment area upstream of the dam was observed at the time of inspection. No other areas of erosion were observed. Minor sedimentation of the reservoir was present in the upstream end.
- 3.1.5 Downstream Channel: The streambed of the downstream channel consists of boulders, cobbles and sandy gravel. Some granite is also exposed. The stream channel is heavily overgrown with ground cover, and the presence of small trees two to three years old was evident at the time of inspection.
- 3.2 Evaluation
- 3.2.1 Dam: The concrete in the spillway and right non-overflow area is in good condition and requires no further investigation. The concrete in the left non-overflow area adjacent to the main spillway shows evidence of clear seepage. The Rivanna Water and Sewer Authority should monitor these seepage areas.

The foundation drains in the gallery which have been plugged with mud and debris should be cleaned to prevent hydrostatic pressure build-up in the foundation.

The entrance to the gallery in the right non-overflow area allows infiltration of mud and debris. To prevent future accumulations of mud and debris, a drainage ditch should be built to channel the runoff and mud away from this entrance. The gallery should also be cleaned.

The clear seepage at the toe of the dam in the right non-overflow area (three g.p.m.) and at the left abutment area (one g.p.m.) does not appear to be a serious problem at the present time. However, the Rivanna Water and Sewer Authority should also continue to monitor these seepage areas.

The outlet of the four inch terra-cotta drain should be uncovered, and a channel should be provided for flow. Also, the heavy growth should be cut.

3.2.2

Appurtenant Structures: The small original intake dam that is now impounding the stilling pool is cracking and spalling. At the present time, no detrimental effects to the stilling basin were observed. However, the condition should be observed in the future to insure that the deteriorated condition does not effect the efficiency of the stilling basin.

It was reported at the time of inspection and visually verified that the lift gates have not been operated for some time. It is recommended that regular operations of the lift gates' equipment be done to insure their working order.

3.2.3

Reservoir Area: The erosion of the left bank area 100 feet upstream of the dam should be controlled by placement of riprap to assure this erosion does not continue and eventually affect the stability in the left abutment area.

3.2.4

Downstream Channel: No further investigation is necessary.

## SECTION 4 - OPERATIONAL PROCEDURES

4.1 Procedures: Operational procedures are generally discussed in paragraphs 1.2.8 and 2.3. The normal reservoir elevation of 975.0 is controlled by the gated primary spillway overflow.

The dam is controlled by a resident operator and visited by maintenance personnel from the Rivanna Water and Sewer Authority.

Rapid emergency drawdown is controlled through the 30 inch diameter drawdown line (invert elevation of 913.17), which is located within the intake tower. The operating condition of the control valve for this line is unknown.

4.2 Maintenance of Dam: Because of its water supply function, the dam has an on site resident operator and is frequently visited by maintenance personnel. The dam is generally in good condition; except for minor spalling, cracking, clear seepage from some construction joints, and growth of vegetation.

4.3 Maintenance of Operating Facilities: Maintenance personnel of the Rivanna Water and Sewer Authority operate the two slide gates for the 18 inch discharge pipes into the intake tower for the 24 inch water supply line. The spillway crest gates appear to be in good condition but they are not operated regularly.

4.4 Warning System: At the present time, there is no warning system or evacuation plan in operation. It is recommended that a formal emergency procedure be prepared, and prominently displayed and furnished to all operating personnel. This should include:

- 1) How to operate the dam during an emergency.
- 2) Who to notify, including public officials, in case evacuation from the downstream area is necessary.
- 3) Procedures for evaluating inflow during periods of emergency operation.

4.5 Evaluation: Maintenance of the dam by personnel of the Rivanna Water and Sewer Authority is considered to be acceptable. However, the operating condition of the valve in the 30 inch drawdown line should be determined.

NAME OF DAM: SUGAR HOLLOW

## SECTION 5 - HYDRAULIC/HYDROLOGIC DATA

- 5.1 Design: A stage versus storage curve, received from the Rivanna Water and Sewer Authority, was the only design data available for use in the analyses of hydrologic and hydraulic conditions.
- 5.2 Hydrologic Records: Flood discharge information is available for the Whitehall stream gaging station from 1951 to date. The gage has a drainage area of 11.4 square miles and is located approximately 0.73 mile upstream of the dam on the North Fork Moormans River.
- 5.3 Flood Experience: No records are available.
- 5.4 Flood Potential: The flood potential of the dam was evaluated by routing various hydrographs as shown in Table 5.1.
- 5.5 Reservoir Regulation: Pertinent dam and reservoir data are shown in Table 1.1, paragraph 1.3.3.
- Flow from the reservoir is regulated by eight crest gates, five feet high, 25.5 feet wide. Crest elevation with gates opened is 970.0, and with gates closed is elevation 975.0. With the exceptions of discharge through the lake drain and water supply pipes, all outflow from the reservoir passes through the gated spillway.
- Outlet discharge capacity, reservoir area, and hydrograph and routing determinations were calculated as part of this report. The routing of the Probable Maximum Flood (P.M.F.), one-half P.M.F., and 100 year hydrographs began with the reservoir level at the spillway crest elevation 975.0 with the crest gates closed, at elevation 970.0 with the crest gates open, and at elevation 970.0 with the crest gates removed.
- 5.6 Overtopping Potential: The probable rise in the reservoir and other pertinent information on reservoir performance in various hydrographs are shown in the following table:

NAME OF DAM: SUGAR HOLLOW

TABLE 5.1 RESERVOIR PERFORMANCE

Item	Normal			100 Year			1/2 P.M.F.			P.M.F.		
	(a)	(b)	(c)	(a)	(b)	(c)	(a)	(b)	(c)	(a)	(b)	(c)
Hydrograph												
Peak flow, c.f.s.	-	-	-	7880	7880	7880	14507	14507	14507	29014	29014	29014
Inflow	-	-	-	7657	7743	7743	14360	14273	14316	28970	28560	28901
Outflow	-	-	-	980.8	974.6	974.6	982.5	977.2	976.4	985.4	983.1	981.3
Peak elev., ft. M.S.L.	975.0	970.0	970.0	980.8	974.6	974.6	982.5	977.2	976.4	985.4	983.1	981.3
Gated spillway	-	-	-	-	-	-	-	-	-	-	-	-
Depth of flow, ft. (d)	-	-	-	9.8	3.6	3.6	11.0	5.0(g)	5.9(g)	13.0	9.6	10.2
Average velocity, f.p.s. (e)	-	-	-	10.9	10.7	10.7	12.6	14.0	14.0	14.7	19.0	16.7
Non-overflow section (f)	-	-	-	-	-	-	1.5	-	-	-	-	-
Depth of flow, ft.	-	-	-	-	-	-	7.1	-	-	-	-	-
Average velocity, f.p.s.	-	-	-	-	-	-	6.2	-	-	-	-	-
Duration of overtopping, hrs.	-	-	-	-	-	-	-	-	-	-	-	-

- (a) Gates completely closed.
- (b) Gates completely open.
- (c) Gates removed.
- (d) Depth of flow over crest (elevation 970.0).
- (e) Weighted velocity over spillway and walkway.
- (f) Sections of dam on either side of spillway.
- (g) Orifice flow between dam crest and gate, and between dam crest and walkway.

NAME OF DAM: SUGAR HOLLOW

- 5.7 Reservoir Emptying Potential: The 30 inch cast-iron pipe entering at a low level below the spillway will permit withdrawal of about 163 c.f.s. with the reservoir level at the crest (elevation 970.0) and essentially dewater the reservoir in about five days.
- 5.8 Evaluation: Sugar Hollow Dam with an "intermediate" size-"high" hazard classification must pass a spillway design flood equal to the P.M.F. As shown in Table 5.1, the P.M.F. was routed and found to overtop the dam by an average depth of 1.8 feet with the crest gates open. The spillway passes the one-half P.M.F. with the gates open.

The P.M.F., one-half P.M.F., and 100 year flood were also routed with the gates closed, and all floods were found to overtop the dam. With the gates closed the spillway would pass 18 percent of the P.M.F. without overtopping. The spillway with the gates open will pass approximately 62 percent of P.M.F. With the gates completely removed, the spillway passes 80 percent of the P.M.F. Therefore, the spillway is inadequate.

It should be indicated that conclusions pertain to present day conditions, and that the effect of future development on the hydrology has not been considered.

## SECTION 6 - DAM STABILITY

6.1 Foundation and Abutments: The structure is founded on hard granite. Joints with a dip between 80° to 90° were observed in localized rock exposures. Some moderately dipping cleavage planes were also observed. Selected pervious rockfill was placed adjacent to the downstream face of the dam with a silty sand and gravel cover. Upstream of the dam, selected impervious fill with a 1.5 feet cover of riprap was indicated on the design drawings. This was not visible at the time of inspection.

Both abutments were founded on hard jointed granite with joint dips ranging from 80° to 90°. Clear seepage was observed along portions of the cleavage plane sloping downstream from the toe of the dam in the left abutment area.

### 6.2 Stability Analysis

6.2.1 Visual Observations: No unusual misalignment or structural cracking was observed during the visual inspection. A small amount of clear seepage from the granite joints in the left abutment area was noted. In addition to the clear seepage from the abutment area, some clear seepage was observed to be coming from the horizontal and vertical construction joints in the left abutment area.

6.2.2 Design Data: Since there were no design calculations available, stability analyses were performed on a full section through the dam (see Appendix VI). The stability computations were made in accordance with Gravity Dam Design, U.S. Army Corps of Engineers, Manual EM 1110-2-2200, 23 November 1960 (including Change 2) and ETL 1110-2-184, February 1974.

Stability analyses were completed for three cases:

I. Water level at normal pool (elevation 975.0) with ice load and normal tailwater of nine feet (the spillway gates were assumed to be closed).

II. Water level 3.1 feet over top of dam elevation 980.0 with no ice load and tailwater at elevation 914.0. (The 3.1 feet height was based on the calculated P.M.F. elevation. The spillway crest gates were assumed to be completely opened.)

NAME OF DAM: SUGAR HOLLOW

II. Water level again 3.1 feet over top of dam elevation 980.0 with no ice load. (However, the tailwater was estimated to be at elevation 920.0, and the spillway crest gates were assumed to be completely opened.)

The results of the stability analyses show the resultant force is within the middle one-third of the base and a factor of safety against sliding that is well above that required. The high values of angle of internal friction ( $\phi = 31^\circ$ ) and average shear strength ( $S_c = 1825$  p.s.i.) of the quartz monzonite are primarily responsible for the very large factor of safety against sliding.

The  $\frac{\Sigma H}{\Sigma V}$  for Case I normal conditions is 0.64 as compared to the allowable of 0.65.

The  $\frac{\Sigma H}{\Sigma V}$  for Case II is 0.79 as compared to the allowable of 0.65. However the factor of safety against sliding is very large.

The  $\frac{\Sigma H}{\Sigma V}$  for Case III is 0.81. However the factor of safety against sliding is again very large.

6.2.3 Operating Records: There is no instrumentation for indicating movement of the structure under prior maximum loading conditions.

6.2.4 Post-Construction Changes: No post-construction changes were observed.

6.3.5 Seismic Stability: The dam is located in Seismic Zone 2; therefore, the dam is considered to have no hazard from earthquakes provided static stability conditions are satisfactory and conventional safety margins exist.

6.3 Evaluation: Sugar Hollow Dam meets all stability requirements according to EM 1110-2-2200.

## SECTION 7 - ASSESSMENT/REMEDIAL MEASURES

7.1 Dam Assessment: Clear minor seepage and erosion were observed at Sugar Hollow Dam. The primary concern for Sugar Hollow Dam, however, is the spillway capacity. The spillway is gated and was evaluated for three operating conditions:

- 1) Gates closed.
- 2) Gates opened.
- 3) Gates removed.

With the gates closed, the spillway passes 18 percent of the P.M.F. With the gates opened, the spillway passes 62 percent of the P.M.F. With the gates removed, the spillway passes 80 percent of the P.M.F. Therefore, the spillway is inadequate.

The stability of Sugar Hollow Dam meets the criteria required by the Recommended Guidelines for Safety Inspection of Dams for normal pool with ice load and during the P.M.F.

The Rivanna Water and Sewer Authority provided design drawings which were adequate to conduct a Phase I evaluation.

7.2 Recommended Remedial Measures: The inspection and subsequent hydrologic/hydraulic analyses revealed work which should be done immediately by the owner. This is to perform a detailed investigation of spillway capacity with the aim of increasing the capacity by possibly removing the lift gates and lowering the normal pool to the spillway crest.

Lower priority items which should be performed as part of the maintenance program are:

- 1) Monitor clear seepage near the 24 inch water supply line and in the right abutment for a possible increase in flow, especially during higher reservoir levels.
- 2) Clear the plugged foundation drains in the gallery and clear the entire gallery of mud and debris.
- 3) Uncover the outlet of the four inch terra-cotta drain, provide a channel for flow, and remove the heavy growth.

- 4) Check concrete in the intake dam of the stilling pool for progressive deterioration.
- 5) Annually operate the lift gates to assure proper functioning.
- 6) Repair erosion of the left upstream shoreline.
- 7) Divert surface runoff from the gallery entrance.
- 8) The operating condition of the valve in the 30 inch drawdown line should be determined.

NAME OF DAM: SUGAR HOLLOW

**APPENDIX I**

**PLATES**

## **CONTENTS**

### **Location Plan**

**Plate 1: General Plan of Dam**


**Plate 2: Elevation of Dam**

**Plate 3: Galleries, Drains and Grout Pipes**

**Plate 4: Sections, Construction Joints, Water Stops and Spraywalls**


**Plate 5: Details of Intake Tower**

**NAME OF DAM: SUGAR HOLLOW**



LOCATION PLAN  
SUGAR HOLLOW

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDG




Note: Coordinates of center of curvature:  
3752.925  
5163.09 E

PLAN


Orig. Ground  
Elev. 803.07

SECT. D-D


SECTION F-F THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC



SECTION G-G



SECTION E-E  
THRU STILLING POOL



NOTE: Cost of paved ditches is to be absorbed in the unit price bid for Item 13 in the Schedule of Bid Items.

**THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDG**


NOTE:  Denotes monolith number.  
For more explicit instructions regarding construction of fills and placement of backfills see Specifications, also see "BACKFILL NOTE" on Sheet 7.


### PLATE 1

E. W. SAUNDERS  
CONSULTING ENGINEER  
CHARLOTTESVILLE, VIRGINIA  
  
F. W. WHEELER  
DESIGNING ENGINEER  
CHARLOTTESVILLE, VIRGINIA  
  
**CITY OF CHARLOTTESVILLE  
ALBEMARLE COUNTY, VIRGINIA  
MOORMAN'S RIVER STORAGE DAM  
GENERAL PLAN**

DRAWN BY	TRACED BY	SCALE	SHEET
T. E. M.	2012	1'-0"-0"	6
CHECKED BY			


RECOMMENDED FOR APPROVAL  
DATE APPROVED  
CITY MANAGER  
2012  
VIRGINIA





UPSTREAM

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC



DOWNS

Notation on this view indicates rods of track structure have been removed.

This view indicates fixed and expansion ends of structure beams. See Sheet 1B.

Piers Elev 977.50

Exp Fix Exp Fix Exp Fix Exp Fix Fix

Construction joints

Existing ground line

Top of backfill

Existing ground line

Core wall

Top of rock


Top of hard granite

Note: Face of all steps to be  
of unshattered rock

### UPSTREAM ELEVATION

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDG

1600



■ Denotes monolith number

PLATE 2

### DOWNSTREAM ELEVATION

In this view indicates fixed and expansion ends of walkway beams. See Sheet 15.

E. W. SAUNDERS  
CONSULTING ENGINEER

F. W. WHEELER  
DESIGNING ENGINEER

CHARLOTTESVILLE, VIRGINIA


CITY OF CHARLOTTESVILLE  
ALBEMARLE COUNTY  
MOORMAN'S RIVER STORAGE DAM  
ELEVATIONS

DRAWN BY Z. A. M. TRACED BY   CHECKED BY   SHEET 7  
SCALE 1:20'0"

RECOMMENDED FOR APPROVAL   APPROVED   MANAGER  


2


BY DATE CHARACTER APPROVED DATE APPROVED



THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDG


CUTAWAY PLAN OF DRAINAGE  
Scale: 1 in = 20'






THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDG

W OF DRAINAGE GALLERIES  
Scale: 1 in. = 20 ft.



SECTION ON E DRAINAGE GALLERY  
(DEVELOPED)  
Scale 1 in. = 20 ft.



SECTION 'HH'  
ON E DRAINAGE GALLERY  
Scale 1"-10'-0"

PLATE 3

SECTION 'DD'  
TYPICAL DETAIL OF STEPS  
SECTION 'CC'  
TYPICAL DETAIL OF STEPS  
Scale 8'-0"

E. W. SAUNDERS  
CONSULTING ENGINEER  
CHARLOTTESVILLE, VIRGINIA

F. W. WHEELER  
DESIGNING ENGINEER

CITY OF CHARLOTTESVILLE  
ALBEMARLE COUNTY, VIRGINIA





MOORMAN'S RIVER STORAGE DAM  
GALLERIES, DRAINS AND  
GROUT PIPES

DRAFT BY: J. C. S.  
TRACE BY: J. C. S.  
CHECKED BY: J. C. S.  
APPROVED DATE: APPROVED BY: APPROVED

SCALES  
AS NOTED


SHEET  
9


RECOMMENDED FOR APPROVAL  
CITY MANAGER  
J. C. S. a.m.




**TYPICAL DETAIL OF CONSTRUCTION JOINT  
ELL-HEAD SECTION  
Scale 1:10ft**

**THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC**







**APPENDIX II**

**PHOTOGRAPHS**


## CONTENTS

- Photo 1: View of Main Overflow Spillway Gate Hoist in Upper Right Corner
- Photo 2: Clear Seepage, Calcite Stains, Cracked and Spalled Areas of Non-Overflow Section
- Photo 3: Original Low Head Dam Downstream of Main Dam (Now serves as end sill of stilling basin for Sugar Hollow Dam.)
- Photo 4: View of Gate Hoist
- Photo 5: View of 30 Inch Blowoff Pipe (Left) and 24 Inch Water Supply Main (Right)
- Photo 6: View of 24 Inch Water Supply Main at Exit From Drainage Gallery
- Photo 7: Erosion of North Bank 100 Feet Upstream of Left Abutment
- Photo 8: Reservoir Looking Upstream From Dam
- Photo 9: View of Downstream Channel Beyond Stilling Pool

Note: Photographs were taken 25 July 1978.

NAME OF DAM: SUGAR HOLLOW

## SUGAR HOLLOW DAM



**PHOTO 1.** View of Main Overflow Spillway Gate Hoist in Upper Right Corner



**PHOTO 2.** Clear Seepage, Calcite Stains, Cracked and Spalled Areas of Non-Overflow Section

## SUGAR HOLLOW DAM




**PHOTO 3. Original Low Head Dam Downstream of Main Dam  
(Now serves as End Sill of Stilling Basin for Sugar Hollow Dam)**



**PHOTO 4. View of Gate Hoist**

## SUGAR HOLLOW DAM




**PHOTO 5.** View of 30 Inch Blowoff Pipe (Left) and 24 Inch Water Supply Main (Right)




**PHOTO 6.** View of 24 Inch Water Supply Main at Exit From Drainage Gallery

**SUGAR HOLLOW DAM**



**PHOTO 7. Erosion of North Bank 100 Feet Upstream of Left Abutment**



**PHOTO 8. Reservoir Looking Upstream From Dam**

**SUGAR HOLLOW DAM**



**PHOTO 9. View of Downstream Channel Beyond Stilling Pool**

**APPENDIX III**

**CHECK LIST - VISUAL INSPECTION**

Check List  
Visual Inspection  
Phase 1

Name Dam Sugar Hollow County Albemarle State Virginia Coordinates Lat. 3808.2 Long. 7844.3

Date Inspection 25 July 1978 Weather Cloudy Temperature 85°F.

Pool Elevation at Time of Inspection 975 M.S.L. Tailwater at Time of Inspection 912 M.S.L.

III-1

Inspection Personnel:

MICHAEL BAKER, JR., INC.:

M. Moore  
T. Dougan  
W. Sheaffer

VIRGINIA WATER CONTROL BOARD:

Bill Lorenz

T. Dougan Recorder

## CONCRETE/MASONRY DAMS

## SUGAR HOLLOW

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
BACKFILL ADJACENT TO DAM	According to the design drawings, selected rockfill was placed next to the downstream face with silty sand and gravel outside. 1.5 feet of riprap stone over nine inches of granular material overlying impervious fill on the upstream side is called for in the plans. The materials were observed downstream.	Drains in right concrete section should be cleared of mud and debris.
STRUCTURE TO ABUTMENT/EMBANKMENT JUNCTIONS	Both abutments of the structure are founded on hard granite with joints. One set of joints is approximately perpendicular to the axis of the dam and dips from 80° to 90°. Clear seepage was observed from the left side of the dam toe.	
DRAINS	Gallery drains are shown on design drawings. All drains in left concrete section appeared to be unclogged. All drains were full of water. Drains located in right concrete section had a mud cover. One-half of the drains in this area were not visible because of mud. They may be clogged.	
WATER PASSAGES	An arch culvert located at the toe of the dam in left abutment area carried a 24 inch water supply line. No flow was present in culvert. A trough was located in the gallery for collecting overflow from foundation drains. The trough had two to three inches of water for the entire length. The flow rate was minimal.	
FOUNDATION	Concrete section founded on hard granite as indicated by the borings. The foundation was stepped, only the top of the foundation was visible. Joints dipping 80° to 90° were observed in rock exposures in the vicinity. Some moderately dipping cleavage planes were also apparent. The rock is either the Marshall or Crozet Granite of the Precambrian Virginia Blue Ridge Crystalline Complex.	

## CONCRETE/MASONRY DAMS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS CONCRETE SURFACES	Surface cracks and spalls were present throughout the entire dam (superficial in nature--no repairs necessary). The crest of the spillway and the center gated section had considerable spalling due to constant overflow in this area.	
STRUCTURAL CRACKING	No structural cracking was present in the dam. Evidence of cracking was present in an appurtenant structure (walkway outlet culvert).	
VERTICAL AND HORIZONTAL ALIGNMENT	No misalignment was present in the dam structure.	
EXPANSION JOINTS	Expansion joints were in fair condition. Evidence of expansion and contraction was visible. Neoprene sealant was being "squeezed" from joints; one-half inch of sealant material remained.	
CONSTRUCTION JOINTS	Evidence of seepage was visible in the construction joints in the left concrete section adjacent to the main spillway. Calcite stains were present from longitudinal and transverse joints. Considerable spalling was evident in the same area near the 24 inch water supply line.	
SEEPAGE AND DRAINAGE	Drainage from a covered outlet of a four inch terra-cotta drain, leakage at several joints. Seepage at the downstream toe on the left side. The total flow was measured at three g.p.m., most of which apparently came from the terra-cotta drain.	It is recommended that the outlet of the terra-cotta drain be uncovered, a channel be provided for flow and heavy growth be cut.

OUTLET WORKS

SUGAR HOLLOW

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	Minor spalling was evident in the 30 inch outlet conduit at construction joints. Calcite stains and a small amount of seepage was observed. Condensation was present on both walls in the gallery.	
INTAKE STRUCTURE	The intake structure was in fair condition. Gates could not be observed or operated during the inspection.	
OUTLET STRUCTURE	Outlet structure consisted of a 30 inch diameter blow off pipe. No obstruction was observed at time of inspection.	
OUTLET CHANNEL	There is no outlet channel. The 30 inch blow off pipe is directed into the stilling pool.	
EMERGENCY GATE	This consists of the 24 inch cone valve on the blow off pipe. It was not operated during the inspection.	

## SUGAR HOLLOW

## GATED SPILLWAY

## VISUAL EXAMINATION OF                                   OBSERVATIONS

## REMARKS OR RECOMMENDATIONS

## CONCRETE SILL

A stilling pond is located at the toe of the dam and was impounded by means of an old concrete dam located downstream of present dam. Riprap was present on the bottom of the stilling pond. Stilling pond depth (7.5± feet).

## APPROACH CHANNEL

There is none.

## DISCHARGE CHANNEL

Discharged water flows into the Moormans River.

III-5

## BRIDGE AND PIERS

Piers between spillway gates are in good condition with some minor surface cracking.

## GATES AND OPERATION EQUIPMENT

Eight vertically hoisted gates were present. No leakage was evident. The gates are operated by a hoist on rails above the gates. They were not operated during inspection nor have they been operated recently.

Operate gates at least yearly to insure proper functioning.

INSTRUMENTATION

SUGAR HOLLOW	VISUAL EXAMINATION	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
MONUMENTATION/SURVEYS		U.S.G.S. Bench Mark.	
OBSERVATION WELLS		There are none.	
WEIRS		There are no flow measuring weirs.	
III-6			
PIEZOMETERS		There are none.	
OTHER			

RESERVOIR

SUGAR HOLLOW

VISUAL EXAMINATION OF

OBSERVATIONS

REMARKS OR RECOMMENDATIONS

SLOPES

Some erosion was visible in left bank just upstream of dam. The banks along the shore consist of silty sand with gravel, boulders and rock fragments. Soft to medium hard weathered granite is exposed in several areas. The slopes are moderately steep and wooded. Some wooden debris has been deposited on the shore.

SEDIMENTATION

Some sedimentation was evident last year when the lake level was drawn down 35 feet. Sedimentation was in upstream reaches.

DOWNSTREAM CHANNEL

SUGAR HOLLOW

VISUAL EXAMINATION OF  
OBSERVATIONS

CONDITION (OBSTRUCTIONS, DEBRIS, ETC.)	REMARKS OR RECOMMENDATIONS
Heavily overgrown with trees and brush in main channel. The streambed consists of boulders and cobbles with sandy gravel. Granite is exposed in some areas primarily near the stilling basin.	

SLOPES	The slopes consist of sand and gravel with cobbles in some areas, portions with hard granite exposed. There is some clear seepage along cleavage planes toward the stream from the hillside, primarily on the left side of the valley. Granite is at or near the surface of the valley slopes.
--------	--

APPROXIMATE NO. OF HOMES AND POPULATION	Eight to ten homes are located in immediate downstream area, with an approximate population of 35. A girl scout camp is also located approximately 1000 yards downstream and is a seasonal operation.
---	---

**APPENDIX IV**

**CHECK LIST - ENGINEERING DATA**

CHECK LIST  
ENGINEERING DATA  
DESIGN, CONSTRUCTION, OPERATION

SUGAR HOLLOW

<u>ITEM</u>	<u>REMARKS</u>
PLAN OF DAM	Enclosed with design drawings (see Plates 1 and 2).
REGIONAL VICINITY MAP	Enclosed (see Location Plan).
CONSTRUCTION HISTORY	Photos of construction are available from the Rivanna Water and Sewer Authority.
TYPICAL SECTIONS OF DAM	Enclosed in report (see Plate 4).
HYDROLOGIC/HYDRAULIC DATA	None was available.
OUTLETS - PLAN	Enclosed (see Plate 5).
- DETAILS	Enclosed (see Plate 5).
- CONSTRAINTS	Enclosed (see Plate 5).
- DISCHARGE RATINGS	Enclosed (see Plate 5).
RAINFALL/RESERVOIR RECORDS	None were available at the dam site.

<u>ITEM</u>	<u>REMARKS</u>
DESIGN REPORTS	None were available.
GEOLOGY REPORTS	None were available.
DESIGN COMPUTATIONS HYDROLOGY & HYDRAULICS DAM STABILITY SEEPAGE STUDIES	None were available.
IV-2	
MATERIALS INVESTIGATIONS BORING RECORDS LABORATORY FIELD	Boring records are available.
POST-CONSTRUCTION SURVEYS OF DAM	None were available.
BORROW SOURCES	No information on borrow source was available.

SUGAR HOLLOW		ITEM	REMARKS
MONITORING SYSTEMS	There are none.		
MODIFICATIONS	Information on modifications was not available.		
HIGH POOL RECORDS	None were available.		
POST-CONSTRUCTION ENGINEERING STUDIES AND REPORTS	None are available.		
PRIOR ACCIDENTS OR FAILURE OF DAM DESCRIPTION REPORTS	None were reported.		
MAINTENANCE OPERATION RECORDS	None were available.		

IV-3

ITEM	REMARKS
SPILLWAY PLAN	Enclosed (see Plates 1, 2, 3 and 4).
SECTIONS	
DETAILS	

OPERATING EQUIPMENT PLANS & DETAILS	Enclosed (see Plate 5).
--	-------------------------


CHECK LIST  
HYDROLOGIC AND HYDRAULIC DATA  
ENGINEERING DATA


DRAINAGE AREA CHARACTERISTICS: 17.2 square miles 970 (gates open) (1105 acre-feet)  
ELEVATION TOP NORMAL POOL (STORAGE CAPACITY): 975 (gates closed) (1320 acre-feet)  
ELEVATION TOP FLOOD CONTROL POOL (STORAGE CAPACITY): 980 (1460 acre-feet)  
ELEVATION MAXIMUM DESIGN POOL: 980  
ELEVATION TOP DAM: 980  
CREST: Gated Spillway  
a. Elevation 970  
b. Type Ogee shape with slide gates  
c. Width Eight sections at 25.5 feet each  
d. Length Not Applicable  
e. Location Spillover Center of dam  
f. Number and Type of Gates Eight crest gates operated by moveable lift  
OUTLET WORKS:  
a. Type 30 inch blow off pipe  
b. Location Gate house  
c. Entrance Inverts 914.4  
d. Exit inverts 914.4  
e. Emergency draindown facilities 30 inch diameter drain  
HYDROMETEOROLOGICAL GAGES:  
a. Type Streamflow gage  
b. Location Less than one mile upstream of dam on North Fork of Moormans River  
c. Records 1951 to date  
MAXIMUM NON-DAMAGING DISCHARGE Unknown

NAME OF DAM: SUGAR HOLLOW

**APPENDIX V**

**BORING LOGS AND LOCATIONS**






1000						900
975	25	33	63	75		
950	Elev. 970.5	Elev. 975.2 Fwd sandy col and boulders Elev. 969.2	Elev. 975.3 Sandy clay and boulders Elev. 969.2	Elev. 971.1 Brown sandy clay Elev. 967.3		
925	White and green sand Elev. 925.5	Boulders and brown sand Elev. 932.2	White and green sand Elev. 925.2	No core recovered Elev. 969.3		
900	Boulders and a few iron streaks Elev. 942.2 Granite Elev. 936.5	Elev. 948.8 Soft, decomposed granite Elev. 939.6 Soft, white granite (brown) Elev. 932.1	Elev. 948.8 Soft, decomposed granite Elev. 935.3 Soft granite Elev. 933.3	White and green sand 950 Elev. 942.9 Hard granite Elev. 931.6		
	Open seam lost water Elev. 936.5	67.10, medium hard granite Elev. 924.2		Open seam lost water Elev. 925 Hard granite Elev. 932.4		
		No loss of drill water				
875	800.5	800.5	750.5	700.5	650.5	600.5
900						
1000						
975	25	13		975		
950	Elev. 955.2 Red clay Elev. 900.2	Elev. 980.1 Yellow, sandy clay				
925	Yellow sand (mostly sand) Elev. 932.2	Elev. 964.6 White, coarse sand				
900	Green-brown sand Elev. 960.2 White and green sand Elev. 932.2 Soft, rotten granite Elev. 926.2 Granite Elev. 908.2	Elev. 989.1 Boulders and sand (brown) Elev. 934.1 Soft brown granite Elev. 924.1 Soft white granite Elev. 915.1 Hard brown granite Elev. 909.1				
875	800.5	800.5	750.5	700.5	650.5	600.5
850						
800						
750						
700						
650						
600						
550						
500						
450						
400						
350						
300						
250						
200						
150						
100						
50						
0						

LOG OF BORINGS IN RIDGE AT SOUTH  
END OF DAM

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC



LOCATION PLAN OF BORINGS IN RIDGE  
AT SOUTH END OF DAM

LEGEND

Boring No. 1X was by Southern Drilling Co. in 1931.  
Borings numbered 18 thru 73 and 1H were by Vass Core Drilling Co.,  
Huntington, W. Va. during December 1944 and January 1945.  
All cores were drilled with a 3" diamond bit.

E. W. SAUNDERS  
CONSULTING ENGINEER

CHARLOTTESVILLE, VIRGINIA

F. W. WHEELER  
DESIGNING ENGINEER

CITY OF CHARLOTTESVILLE  
ALBEMARLE COUNTY VIRGINIA

MOORMAN'S RIVER STORAGE DAM  
LOG BORINGS SOUTH OF DAM SITE

DRAWN BY [Signature] SCALES: 1/4" = 100' SHEET  
TRACED BY [Signature] 2  
CHECKED BY [Signature]

RECOMMENDED FOR APPROVAL, [Signature] MANAGER  
APPROVED [Signature] MAYOR

BY DATE CHARACTER APPROVED  
REASONS

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC

1000	LOG OF GROUTING OPERATIONS	LOG OF GROUTING OPERATIONS
990		HOLE 1H Date: Jan 22, 1945 First packer set at Elev. 902.2 At 160 sacks of 8 gal./sack grout grout appeared in hole 5H Hole 5H was plugged At 893 sacks of 8 gal./sack grout grout appeared in stream Date: Jan 29, 1945 Packer set at Elev. 902.2 pressure of 120 p.s.i. was held Raised packer to Elev. 912.2 Used 40 sacks of cement in 8 gal./sack grout; changed to 6 gal./sack grout.
980	For log of Hole 73 see Sheet 2	73 HOLE 2H Date: Feb. 3, 1945 Packer set at Elev. 932.2. 8 gal./sack grout was used. At 93 pressure rose and reduced to 125 p.s.i. Raised packer to 103 sacks of cement pressure was 35 p.s.i. Per out of Date: Feb. 5, 1945 Hole was plugged in 7H grout at Elev. 944.2.23 a result of grouting other holes.
970		1H Elev. 972.2
960		Brown, sandy 2H clay and gravel boulders Elev. 962.2
950		Elev. 956.2 White sand Sandy clay Elev. 949.2 3H Elev. 947.2 Hard blue granite Elev. 938.2 Hard blue granite Elev. 932.2 Open seam lost water Elev. 932.2 Hard blue granite Elev. 926.2
940		Hard blue granite Elev. 922.2 Decomposed soil Elev. 922.2 Long, thin soft, brown soil Elev. 920.2 soft, brown soil Elev. 907.2
930		
920		
910		
900		
890		
880		
870		
860		
850	6' 503	6' 003
		5' 503

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC

960	1H Elev. 958.2 Sandy clay Elev. 954.2
950	Soft brown Elev. 942.2 hard granite small, coarse Elev. 938.2
940	Open seam Elev. 932.2
930	Hard granite Elev. 922.2
920	

	LOG OF GROUTING OPERATIONS	LOG OF GROUTING OPERATIONS
west. At 3 socks of cement 1 pocket to Elev. 943.2 at Refusal. 5' cement.	HOLE SH Date: Jan. 22, 1945 Grout entered this hole from hole H1 and this hole was plugged.	HOLE AH Date: Jan. 23, 1945 Packer set at Elev. 290.6 34 socks of cement in 8 gal./sock grout Delivery pressure was 20 psi, changed to 6 psi. 1/2 sock grout. At 325 socks of cement, pressure was 35 psi. • 350 • • 350 • • 362 • • 362 • 70 -
OPERATIONS with grout 1 pocket 1 refusal 9163 9226 no grout.		Non out of cement. Remarks: This hole never held pressure, but it is apparent from the continued increase in delivery pressure that the hole was near refusal when the grouting was stopped.
LOG OF GROUTING OPERATIONS HOLE SH Date: Feb. 5, 1945 Hole was plugged with grout at Elev. 911.6 due to grouting other holes. This hole would not take grout.		
Elev. 947.6 Sand, clay and boulders Elev. 942.6 Overburden Soft, broken granite Elev. 933.1 Hard, broken granite Elev. 933.4 Lost water AH Elev. 929.6		950
Hard, blue granite Elev. 922.9 Decomposed grain Elev. 920.9 Lignite Elev. 920.0 Soft, brown grain Elev. 919.6 Hard, blue granite Elev. 902.5	Sandy clay Elev. 917.5 Overburden. Hard granite Elev. 910.0 Soft, rotten granite Elev. 910.0 Hard granite Elev. 910.1 Hard, broken granite Elev. 910.1 Hard granite Elev. 910.2 Soft, broken granite Elev. 910.6	920
Elev. 893.8 Hard, broken granite Elev. 883.3 Hard granite Elev. 880.6	SH Elev. 910.9 Sand and boulders Elev. 900.3 Overburden	910
50' 005	40' 503	40' 005
Elev. 862.6 Broken granite Elev. 860.0 Hard granite Elev. 857.9	Hard granite	30' 503 050
960		
Elev. 954.9 Sand, clay Elev. 951.6		
Soft brown, broken granite Elev. 942.9	LEGEND	
Hard granite with small, clay portions Elev. 935.9	Boulders and Sandy Clay overburden	E.W. SAUNDERS CONSULTING ENGINEER CHARLOTTESVILLE, VIRGINIA
Open seam, lost water Elev. 935.0	Sand	F.W. WHEELER DESIGNING ENGINEER CHARLOTTESVILLE, VIRGINIA
Hard granite Elev. 922.9	Broken granite	CITY OF CHARLOTTESVILLE ALBEMARLE COUNTY VIRGINIA
920	Soft, coarse-grained granite	MOORMAN'S RIVER STORAGE DAM LOG OF BORINGS ON DAM SITE
50' 005	Hard and dense granite	DRAWN BY: J. W. CORCORAN TRACED BY: J. W. CORCORAN CHECKED BY: J. W. CORCORAN
80' 505	BY DATE CHARACTER APPROVED	SCALES: 1/4" = 100' 0" 0"
		3
		RECOMMENDED FOR APPROVAL DATE: APR. 1945 APPROVED CT. MANAGER
		100' 0" 0"




1000	LOG OF GROUTING OPERATIONS	LOG OF GROUTING OPERATIONS	LOG OF GROUTING OPERATIONS	LOG OF GROUTING OPERATIONS
	HOLE 7H Date: Jan 25, 1945 Packer set at Elev. 896.2 2 socks of cement in Ego. 896.2 grout area used. Pressure held at 20 psig.	HOLE 8H Date: Jan. 28, 1945 Packer set at Elev. 896.0 3 socks of cement in Ego. 896.0 grout area used. Pressure held at 120 psig.	HOLE 9H Date: Feb. 3, 1945 Packer set at Elev. 893.1 Hole was tested with water and lost pressure held at 35 psig. Packer set at Elev. 903.1 Hole was tested with water and lost pressure slowly. Started grouting with 6gal/sock grout at 115 psig pressure. At 25 socks of cement pressure was 30 psig. At 38 " " " held at 30 psig.	HOLE 10H Date: Feb. 10, 1945 Packer set at Elev. 893.1 Used 6 1/2 socks Packer set at Elev. 903.1 Pressure at 11.75 psig Packer set at Elev. 896.0 At 20 psig At 30 psig used in which was used on
990				
970				
960				
950				
940			THIS PAGE IS BEST QUALITY PRACTICABLE FROM COPY FURNISHED TO DDG	
930				
920	7H	8H	9H	
910	Elev. 916.2	Elev. 918.0	Elev. 916.1 Hard broken granite Elev. 917.8 Hard granite Elev. 916.1 Hard broken granite Elev. 915.1 Hard granite Elev. 914.1 Hard broken granite Elev. 913.1 Hard granite Elev. 912.1 Hard broken granite Elev. 911.1 Hard granite Elev. 910.1 Hard broken granite Elev. 909.1 Hard granite Elev. 908.1 Hard broken granite Elev. 907.1 Hard granite Elev. 906.1 Hard broken granite Elev. 905.1	
900	Boulders and sand Elev. 900.7 Hard, blue-green granite Elev. 897.8 Soft, decomposed granite Elev. 896.2	Boulders and sandy clay Overburden Elev. 900.0 Broken, soft, brown granite Elev. 896.7	Blue, hard granite Elev. 888.7 Broken, brown granite Elev. 882.8	Very hard granite Elev. 866.1
890	Hard, blue-green granite Elev. 881.2	Blue, hard granite Elev. 866.0		
880				
870				
860				
850	8-50.3	8-00.9	8-50.3	
920	5.11	920		
910	Elev. 918.4	910		
900	Boulders and sand Elev. 908.7 Overburden Broken granite Elev. 906.1 Hard, blue-green granite Elev. 906.9 Broken, brown granite Elev. 906.6 Hard, blue-green granite Elev. 896.1 Soft, broken, decomposed granite Elev. 894.2 Brown, decomposed granite Elev. 892.9	900		
890		890		
880				
870				
860				
850	8-00.6	8-00.6	8-00.6	


LOG OF GROUTING OPERATIONS	LOG OF GROUTING OPERATIONS	LOG OF GROUTING OPERATIONS	
HOLE 10H Date: Jan. 20, 1965 Packer set at Elev. 908.2 Used 200 ft. rock grout. All 7 socks of cement pressure was 60 p.s.i. Packer set at Elev. 915.2 All 7 socks of cement pressure was 55 p.s.i. Packer set at Elev. 925.2 All 204 socks of cement no pressure developed. A total of 204 socks of cement were used in this hole, the last 64 socks of which were from the same lot as that used on holes 11H and 12H.	DATE: Jan. 20, 1965 Packer set at Elev. 939.5 Used 800 ft. rock grout. All 2 socks of cement pressure was 70 p.s.i. Packer set at Elev. 946.6 At 16 socks of cement there was no pressure rise. At 18 " " pressure held at 60 p.s.i. A total of 18 socks of cement were used in this hole. The cement was from the same lot as that used in hole 12H.	HOLE 12H Date: Jan. 20, 1965 Packer set at Elev. 945.6 Used 12 bags of cement in 1000 ft. rock grout. " 32 " " 600 ft. rock grout	1000
		Pressure rise was rapid and pressure held at 90 p.s.i. Packer was removed, cleaned and replaced, but hole refused to take more grout. All of the cement used was lumpy. The man in charge of the grouting believed that the poor quality of the cement affected the grouting adversely and that the hole was not successfully grouted to refusal.	990
		Elev. 970.8	980
		Boulders and Sandy Clay	970
11H			960
Elev. 933.5 Boulders and Sandy clay Elev. 929.4 Creathwagee Complete loss of water Elev. 926.2	Elev. 933.5 Overburden Elev. 932.0 Soft, coarse-grained granite Elev. 927.5 Hard, fine-grain granite Elev. 922.5 Packer, soft granite Elev. 922.5 Lost part of Elev. 922.5 Lost part of drill water lost oil of drill water Hard, fine-grain granite Elev. 926.2	Overburden Elev. 931.9 Soft, coarse-grained granite Elev. 924.4 Lost part of drill water Elev. 920.4 Complete loss of drill water Hard, fine-grain granite Elev. 926.2	950
10H			940
Elev. 936.2 Boulders and sandy clay Elev. 929.4 Creathwagee Complete loss of water Elev. 926.2	Elev. 936.2 Overburden Elev. 932.0 Soft, coarse-grained granite Elev. 922.5 Red crystalized granite (split) Elev. 902.6 Very hard granite Elev. 896.2	Hard, fine-grain granite Elev. 926.2	930
			920
			910
		THIS PAGE IS BEST QUALITY PRACTICABLE FROM COPY FURNISHED TO DDG	900
			890
			880
			870
			860
2-005	1-505	1-005	0-505 860

Logs of core borings shown on this sheet have been copied from the driller's reports and the logs of the grouting operations have been copied from daily reports by J.W. Carter, City Inspector. The holes were drilled with a 3 inch diamond bit; this work and the grouting having been done by the Mott Core Drilling Co., Huntington, W. Va. The cores are available for inspection.



LEGEND  
Boulders and sandy-clay overburden  
Broken granite  
Soft, coarse-grained granite  
Hard and dense granite

E. W. SAUNDERS CONSULTING ENGINEER CHARLOTTESVILLE, VIRGINIA	F. W. WHEELER. DESIGNING ENGINEER CHARLOTTESVILLE, VIRGINIA
CITY OF CHARLOTTESVILLE ALBEMARLE COUNTY VIRGINIA	
MOORMAN'S RIVER STORAGE DAM LOG OF BORINGS ON DAM SITE	
DRAWN BY: <i>[Signature]</i> TRACED BY: <i>[Signature]</i> CHECKED BY: <i>[Signature]</i>	SCALES: 1 IN. = 10 FT 0 5 10 4
RECOMMENDED FOR APPROVAL, <i>[Signature]</i> CITY MANAGER DATE: APRIL 1, 1965 APPROVED <i>[Signature]</i> VIRGINIA	





LINE OF "X" HOLES - ABOUT 1+40E



THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDG

Records of core borings shown on this sheet have been copied from Plate 8 of a report prepared by Saville and Williamson, Inc., Consulting Engineers, Richmond, Va., on the "Proposed Moorman's River Dam." This report is dated April 13, 1931. The borings were made by the Southern Drilling Co.

LEGEND

Boulders	[Blank]
Decomposed granite	[Blank]
Broken granite	[Blank]
Slightly Decomposed granite	[Blank]
Sand and clay	[Blank]
Granite	[Blank]

E.W. SAUNDERS F.N. WHEELER  
CONSULTING ENGINEER DESIGNING ENGINEER  
CHARLOTTESVILLE, VIRGINIA

CITY OF CHARLOTTESVILLE  
ALBEMARLE COUNTY VIRGINIA

MOORMAN'S RIVER STORAGE DAM  
GEOLOGICAL PROFILES & LOGS OF  
BORINGS DOWNSTREAM FROM DAM

DRAWN BY [Signature] SCALES 1:20,000 SHEET 5  
TRACED BY [Signature] 0 10 20 30 40 50  
CHECKED BY [Signature]

RECOMMENDED FOR APPROVAL  
DATE APR 13 1931 APPROVED

CITY MANAGER  
K. Adams  
MAYOR

2

BY	DATE	CHARACTER	APPROVED
BEVISON'S			

**APPENDIX VI**



**STABILITY ANALYSES**

## SUGAR HOLLOW

GRAVITY DAM DESIGN  
STABILITY ANALYSIS

ANALYSIS DONE ON X FULL SECTION PARTIAL SECTION  
 LOCATION OF SECTION Station 2+17 (see Plate 4)  
 ANALYSIS PREPARED BY M. Mill, Michael Baker, Jr., Inc.

LOADING CASE	ELEV HEAD WATER	ELEV. TAIL WATER	$\Sigma V$	$\Sigma H$	$\frac{\Sigma H}{\Sigma V}$	LOCATION RESULTANT FROM TOE	% BASE IN COMPRESSION	FACTOR SAFETY SLIDING	FOUNDATION PRESSURE
						FROM TOE	TOE	HEEL	
Case I Normal Pool Ice Load	975.0	912.0	224,807#	144,586#	0.64	23.1'	100	104 (1)	6186 PSF 1702 PSF
Case II P.M.F.	983.1	914.0	209,129#	165,116#	0.79	19.4'	100	91 (1)	7168 PSF 170 PSF
Case III P.M.F.	983.1	920.0	196,754#	159,936#	0.81	19.7'	100	94 (1)	6649 PSF 254 PSF



(1) Jointed Quartz Monzonite  
 $\theta = 31^\circ$   
 $S_o = 1825 \text{ psf}$   
 From ETL 1110-2-184