

AD-A063 859

NEW YORK STATE DEPT OF ENVIRONMENTAL CONSERVATION ALBANY F/G 13/2  
NATIONAL DAM SAFETY PROGRAM. CRANBERRY LAKE DAM (NY00397); ST. --ETC(U)  
SEP 78 J J WILLIAMS DACW51-78-C-0035


UNCLASSIFIED

NL

1 OF 1  
AD  
A063 859



END  
DATE  
FILMED  
3--79  
DDC



**LEVEL** # 1

5

ST. LAWRENCE RIVER BASIN

OSWEGACHIE RIVER, ST. LAWRENCE COUNTY

NEW YORK

AD A 0 6 3 8 5 9

# CRANBERRY LAKE DAM

## PHASE I INSPECTION REPORT

### NATIONAL DAM SAFETY PROGRAM

DDC FILE COPY

NY 00397

DDC  
RECEIVED  
JAN 29 1979  
A



DISTRIBUTION STATEMENT A  
Approved for public release  
Distribution Unlimited

DEPARTMENT OF THE ARMY  
NEW YORK DISTRICT, CORPS OF ENGINEERS  
26 FEDERAL PLAZA  
NEW YORK, NEW YORK 10007  
JULY 1978

020  
27  
10  
29  
07  
27  
020

DEPARTMENT OF THE ARMY  
U. S. ARMY ENGINEER DISTRICT, NEW YORK  
26 FEDERAL PLAZA  
NEW YORK, NEW YORK 10007

2 OCT 1978

NANEN-F

Honorable Hugh L. Carey  
Governor of New York  
Albany, New York 12224

Dear Governor Carey:

The purpose of this letter is to inform you of a clarification of the guidelines used by this office in assessing dams under the National Program of Inspection of Dams.

Office of the Chief of Engineers has recently provided a clarification that dams with seriously inadequate spillways are to be assessed as unsafe, non-emergency, until more detailed studies prove otherwise or corrective measures are completed.

The following dams in your state have previously been assessed as having seriously inadequate spillways, with capability to pass safely only the percentage of the probable maximum flood as noted in each report. They are now to be assessed as unsafe:

<u>I.D. NO.</u>	<u>NAME OF DAM</u>
N.Y. 59	Lower Warwick Reservoir Dam
N.Y. 4	Salisbury Mills Dam
N.Y. 45	Amawalk Dam
N.Y. 418	Jamesville Dam
N.Y. 685	Colliersville Dam
N.Y. 6	Delta Dam
N.Y. 421	Oneida City Dam
N.Y. 39	Croton Falls Dam
N.Y. 509	Chadwick Dam (Plattenkill)
N.Y. 66	Boyds Corner Dam
N.Y. 397	Cranberry Lake Dam
N.Y. 708	Seneca Falls Dam
N.Y. 332	Lake Sebago Dam
N.Y. 338	Indian Brook Dam
N.Y. 33	Lower(S) Wiccopee Dam (Lower Hudson W.S. for Peekskill)



NANEN-F  
Honorable Hugh L. Carey

<u>I.D. NO.</u>	<u>NAME OF DAM</u>
N.Y. 49	Pocantico Dam
N.Y. 445	Attica Dam
N.Y. 658	Cork Center Dam
N.Y. 153	Jackson Creek Dam
N.Y. 172	Lake Algonquin Dam
N.Y. 318	Sixth Lake Dam
N.Y. 13	Butlet Storage Dam
N.Y. 90	Putnam Lake (Bog Brook Dam)
N.Y. 166	Pecks Lake Dam
N.Y. 674	Bradford Dam
N.Y. 75	Sturgeon Pool Dam
N.Y. 414	Skaneateles Dam
N.Y. 155	Indian Lake Dam
N.Y. 472	Newton Falls Dam
N.Y. 362	Buckhorn Lake Dam

The classification of "unsafe" applied to a dam because of a seriously inadequate spillway is not meant to connote the same degree of emergency as would be associated with an "unsafe" classification applied for a structural deficiency. It does mean, however, that based on an initial screening, and preliminary computations, there appears to be a serious deficiency in spillway capacity so that if a severe storm were to occur, overtopping and failure of the dam would take place, significantly increasing the hazard to loss of life downstream from the dam.

Consequently, it is advisable to implement the recommendations previously furnished in the reports for the above-mentioned dams as soon as practicable.

It is requested that owners of these dams be furnished a copy of this letter and that copies be permanently appended to all reports previously furnished to you.

Sincerely yours,

CLARK H. BENN  
Colonel, Corps of Engineers  
District Engineer

ST. LAWRENCE RIVER BASIN

Name of Dam: Cranberry Lake Dam  
County and State: St. Lawrence County, New York State  
Inventory Number: NY 00397

PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM

Prepared by: O'Brien and Gere Engineers, Inc.

For: New York State  
Department of Environmental Conservation

Date: July 12, 1978

ACCESSION for	
NTIS	Write Section <input checked="" type="checkbox"/>
DGC	Self Section <input type="checkbox"/>
OR REORDERED	<input type="checkbox"/>
JUSTIFICATION	
BY	
DISTRIBUTION AVAILABILITY CODES	
Dist.	AVAIL. and/or SPECIAL
A	

79 01 25 020

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Inspection Report Cranberry Lake Dam St. Lawrence River Basin, St. Lawrence County, NY Inventory No. N.Y. 397		5. TYPE OF REPORT & PERIOD COVERED Phase I Inspection Report National Dam Safety Program
6. AUTHOR(s) 10 John J. Williams / E.E.		7. CONTRACT OR GRANT NUMBER(s) 15 DACW51-78-C-0035
9. PERFORMING ORGANIZATION NAME AND ADDRESS O'Brien and Gere Engineers, Inc. 1301 Buckley Road Syracuse, New York 13221		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
11. CONTROLLING OFFICE NAME AND ADDRESS New York State Department of Environmental Conservation / 50 Wolf Road Albany, New York 12233		12. REPORT DATE 11 21 September 1978
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) Department of the Army 26 Federal Plaza / New York District, CoE New York, New York 10007		13. NUMBER OF PAGES
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; Distribution unlimited. 12 75 p.		15. SECURITY CLASS. (of this report) UNCLASSIFIED
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
18. SUPPLEMENTARY NOTES 6 National Dam Safety Program, Cranberry Lake Dam (NY00397), St. Lawrence River Basin, Oswegachie River, St. Lawrence County, New York. Phase I Inspection Report.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dam Safety National Dam Safety Program Visual Inspection Hydrology, Structural Stability St. Lawrence County Cranberry Lake Dam Oswegachie River		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report provides information and analysis on the physical condition of the dam as of the report date. Information and analysis are based on visual inspection of the dam by the performing organization. Cranberry Lake Dam was judged unsafe, non-emergency due to a seriously inadequate spillway. S/C 393 970		

PHASE I REPORT  
NATIONAL DAM INSPECTION PROGRAM

Name of Dam: Cranberry Lake Dam

State Located: New York

County Located: St. Lawrence County

Stream: Oswegachie River

Date of Inspection: June 12, 1978

ASSESSMENT OF  
GENERAL CONDITIONS

Cranberry Lake Dam consists of a concrete gravity structure and a wide earthen embankment.

No serious structural deficiencies were noted during the visual inspection of the dam. However, seepage was observed on the downstream face of the spillway and in the toe area downstream of the left abutment. Settlement of backfill material along the training wall and a sinkhole-type depression were located in the embankment area.


Review of the stability analyses indicates that the structure is unstable for all loading conditions relative to sliding based on criteria established by the Department of the Army, Office of the Chief of Engineers. An investigation of the existing foundation would allow a more comprehensive evaluation of this condition.

Evaluation of the Hydraulics/Hydrologic analyses indicated that the spillway could pass approximately 18 per cent of the PMF without




overtopping of the non-overflow sections and earthen embankment. In accordance with Engineering Technical Letter No. 1110-2-234, the spillway capacity is considered seriously inadequate.

O'BRIEN & GERE, ENGINEERS, INC.

  
John J. Williams, P.E.  
Vice President



Approved by:




Clark H. Benn  
Colonel, Corps of Engineers  
District Engineer

Date:

21 September 78



OVERALL VIEW OF DAM



GATE HOUSE



## TABLE OF CONTENTS

<u>TEXT</u>	<u>PAGE</u>
Assessment of General Conditions	
Overall View of Dam	
Section 1 - Project Information	1 - 4
Section 2 - Visual Inspection	5 - 7
Section 3 - Hydraulic/Hydrologic	8
Section 4 - Structural Stability	9 - 10
Section 5 - Assessment/Recommendations/ Remedial Measures	11 - 12

## FIGURES

Figure 1 - Vicinity Map	
Figure 2 - Geologic Map	
Figure 3 - Elevation View of Dam	
Figure 4 - Plan of Dam	
Figure 5 - Cross Sectional View of Original Arch Construction	
Figure 6 - New Proposed Spillway for Cranberry Reservoir	

## APPENDIX

Photographs	A-1 - A-3
Field Inspection Report	A-4 - A-15
Hydrologic and Hydraulic Calculations	A-16 - A-34
Stability Analyses	A-35 - A-42

PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM  
NAME OF DAM CRANBERRY LAKE DAM ID# NY 00397

SECTION I - PROJECT INFORMATION

1.1 GENERAL

a. Authority - This report is authorized by the Dam Inspection Act, Public Law 92-367, and has been prepared in accordance with contract #1467-021 between O'Brien and Gere Engineers, Inc., and the New York State Department of Environmental Conservation.

b. Purpose of Inspection - The purpose of this inspection is to evaluate the structural and hydraulic conditions of Cranberry Lake Dam, and appurtenant structures, and to determine if the dam constitutes a hazard to human life or property.

1.2 PROJECT DESCRIPTION

a. General - Cranberry Lake Dam is located in St. Lawrence County on the Oswegatchie River about ten miles east of Newton Falls, New York. The dam is owned and operated by the Oswegatchie River - Cranberry Reservoir Commission (OR-CRC) and is used to regulate river flows for water supply, power development and recreation.

According to drawings provided by the New York State Department of Environmental Conservation (NYSDEC), initial construction of the dam took place in 1917; the dam in its present configuration was completed in 1956.

The dam consists of a concrete gravity structure and a wide earthen embankment. The earthen embankment is located between the north abutment and the concrete gravity section. A training wall, forming the north bank of the approach channel, is constructed adjacent to the embankment and ties into the gravity structure at its north end. A gatehouse and sluiceway is situated on the dam at this location.

An ungated spillway, about 110 feet long, extends from the gatehouse and sluiceway section towards the south abutment. The spillway is terminated by a non-overflow section which continues to the south abutment and appears to be keyed into bedrock.

b. Size and Hazard Classification - (from drawings and information provided by NYSDEC and OR-CRC) The maximum height of the non-overflow section of the dam is approximately twenty-four (24) feet. The reservoir volume to the spillway crest is about 57,400 acre-feet. According to the Recommended Guidelines for Safety Inspection of Dams, the dam is in the large size category.

Cranbery Lake Dam is located upstream of residential dwellings and loss of life and damage to property could reasonably be expected if the dam were to fail. Therefore, the dam is in the high hazard category as defined by the Recommended Guidelines for Safety Inspection of Dams. The spillway design flood required for hydraulic analysis is the Probable Maximum Flood (PMF).

1.3 PERTINENT DATA (based on information and drawings provided by the NYSDEC and the OR-CRC)

a. Drainage Area - 144 square miles

b. Discharge at Damsite - Reservoir stage readings and discharge through the gated openings are recorded daily by the OR-CRC.

c. Elevations (above MSL)

Top of non-overflow section - 1493.5  
Spillway Crest - 1490.0

d. Reservoir Data (at spillway crest elevation)

Storage - 57,400 acre-feet  
Surface Area - 10.9 square miles

e. Dam Data

Concrete gravity section  
Length - 210<sup>±</sup> feet  
Height - 24<sup>±</sup> feet

Earth embankment  
Length - 150<sup>±</sup> feet  
Height - 24<sup>±</sup> feet  
Top Width - 150<sup>±</sup> feet (maximum section)

f. Outlet Data

Gated Openings - Two 4' x 5' openings are located through the non-overflow structure at the base of the

gatehouse. The discharge invert is at elevation 1472.2. Both openings are fitted with manually operated sluice gates.

Sluiceways - Two sluiceways six feet wide and extending the full height of the dam are located adjacent to the gatehouse. The base elevation is at 1472.2. Both sluiceways are fitted with manually operated stoplog assemblies.

Ungated opening - An ungated opening is located immediately south of the gatehouse. The invert elevation is about 1490.0

Sluiceway - A 6 foot wide log sluice is located between the ungated opening and spillway. The log sluice is fitted with a manually operated stoplog assembly.

g. Spillway Data

Type - concrete weir  
Length - 110 feet

Crest elevation - 1490.0

Downstream Channel - A concrete apron is constructed immediately below the spillway. The apron extends about 20 feet downstream.

h. Flood Elevation of the Dam (MSL feet) - The flood crest elevation was determined for the Probable Maximum Flood.

PMF Elevation - 1496.0

i. Engineering Data - The engineering data provided by NYSDEC and OR-CRC for review of Cranberry Reservoir Dam included:

Plan set (4 sheets) - Concrete Bulkhead and Dam at Cranberry Lake, dated August 14, 1916.

Plan set (10 sheets) - Oswegatchie River - Cranberry Reservoir Commission, dated April 20, 1956.

1.4 OPERATING AND MAINTENANCE PROCEDURES

a. Operation - The dam is used to regulate river flows for water supply, power development and recreation. The reservoir is maintained at maximum pool during the recreational season. New York State requires that the maximum pool does not exceed a depth

of 9 inches above the spillway crest (Elevation 1490.75). A minimum discharge of 720 cfs is also required by the State.

b. Maintenance of Dam and Operating Facilities - The dam and operating facilities are maintained on an "as required" basis. According to the owner's representative, the dam is formally inspected about once every three years.

c. Flood Warning System - According to the owner's representative, no flood warning system is in effect.



## SECTION 2 - VISUAL INSPECTION

### 2.1 FINDINGS

a. General - The field inspection of Cranberry Lake Dam was conducted on June 12, 1978. At time of inspection, the water level was about one foot below the spillway crest. No underwater areas were inspected.

b. Earthen Embankment - A wide earthen embankment is located between the concrete gravity dam and the north abutment. A training wall, approximately 150 feet long, retains the embankment and forms the north bank of the approach channel. The training wall is tied into the gravity structure at the downstream end of the embankment.

Settlement in the material used to backfill the training wall was noted at several locations along the length of the wall. Indications of erosion were evident at the junction of the embankment with the concrete gravity structure.

The crest of the embankment is about 200 feet wide and is grass covered. A sinkhole-type depression was located in the embankment about 50 feet from the training wall and 100 feet from the upstream slope. The existence of a concrete cut-off wall (as shown on Figure 4) in the embankment could not be verified.

c. Gatehouse - The gatehouse is located on the north end of the concrete dam. Four openings, located in the non-overflow section below the gatehouse, are used for passing flows through the structure. Two of the openings are fitted with sluice gates; the remaining openings are fitted with stoplog assemblies. Although the stoplogs were in place during the inspection, significant leakage was observed through both stoplogs.

A sluiceway is positioned to the left of the gatehouse and is used for sluicing logs and debris. The stoplogs were in position and no leakage was observed.

All gates and stoplogs are manually operated. The gate and stoplog operating equipment appeared to be well maintained and in working condition.

Trash racks are located at the intakes to both gated openings; only minor indications of corrosion were noted on the structures. Some trash was accumulated on both racks.



## SECTION 2 - VISUAL INSPECTION

### 2.1 FINDINGS

a. General - The field inspection of Cranberry Lake Dam was conducted on June 12, 1978. At time of inspection, the water level was about one foot below the spillway crest. No underwater areas were inspected.

b. Earthen Embankment - A wide earthen embankment is located between the concrete gravity dam and the north abutment. A training wall, approximately 150 feet long, retains the embankment and forms the north bank of the approach channel. The training wall is tied into the gravity structure at the downstream end of the embankment.

Settlement in the material used to backfill the training wall was noted at several locations along the length of the wall. Indications of erosion were evident at the junction of the embankment with the concrete gravity structure.

The crest of the embankment is about 200 feet wide and is grass covered. A sinkhole-type depression was located in the embankment about 50 feet from the training wall and 100 feet from the upstream slope. The existence of a concrete cut-off wall (as shown on Figure 4) in the embankment could not be verified.

c. Gatehouse - The gatehouse is located on the north end of the concrete dam. Four openings, located in the non-overflow section below the gatehouse, are used for passing flows through the structure. Two of the openings are fitted with sluice gates; the remaining openings are fitted with stoplog assemblies. Although the stoplogs were in place during the inspection, significant leakage was observed through both stoplogs.

A sluiceway is positioned to the left of the gatehouse and is used for sluicing logs and debris. The stoplogs were in position and no leakage was observed.

All gates and stoplogs are manually operated. The gate and stoplog operating equipment appeared to be well maintained and in working condition.

Trash racks are located at the intakes to both gated openings; only minor indications of corrosion were noted on the structures. Some trash was accumulated on both racks.

## SECTION 2 - VISUAL INSPECTION

### 2.1 FINDINGS

a. General - The field inspection of Cranberry Lake Dam was conducted on June 12, 1978. At time of inspection, the water level was about one foot below the spillway crest. No underwater areas were inspected.

b. Earthen Embankment - A wide earthen embankment is located between the concrete gravity dam and the north abutment. A training wall, approximately 150 feet long, retains the embankment and forms the north bank of the approach channel. The training wall is tied into the gravity structure at the downstream end of the embankment.

Settlement in the material used to backfill the training wall was noted at several locations along the length of the wall. Indications of erosion were evident at the junction of the embankment with the concrete gravity structure.

The crest of the embankment is about 200 feet wide and is grass covered. A sinkhole-type depression was located in the embankment about 50 feet from the training wall and 100 feet from the upstream slope. The existence of a concrete cut-off wall (as shown on Figure 4) in the embankment could not be verified.

c. Gatehouse - The gatehouse is located on the north end of the concrete dam. Four openings, located in the non-overflow section below the gatehouse, are used for passing flows through the structure. Two of the openings are fitted with sluice gates; the remaining openings are fitted with stoplog assemblies. Although the stoplogs were in place during the inspection, significant leakage was observed through both stoplogs.

A sluiceway is positioned to the left of the gatehouse and is used for sluicing logs and debris. The stoplogs were in position and no leakage was observed.

All gates and stoplogs are manually operated. The gate and stoplog operating equipment appeared to be well maintained and in working condition.

Trash racks are located at the intakes to both gated openings; only minor indications of corrosion were noted on the structures. Some trash was accumulated on both racks.

## SECTION 2 - VISUAL INSPECTION

### 2.1 FINDINGS

a. General - The field inspection of Cranberry Lake Dam was conducted on June 12, 1978. At time of inspection, the water level was about one foot below the spillway crest. No underwater areas were inspected.

b. Earthen Embankment - A wide earthen embankment is located between the concrete gravity dam and the north abutment. A training wall, approximately 150 feet long, retains the embankment and forms the north bank of the approach channel. The training wall is tied into the gravity structure at the downstream end of the embankment.

Settlement in the material used to backfill the training wall was noted at several locations along the length of the wall. Indications of erosion were evident at the junction of the embankment with the concrete gravity structure.

The crest of the embankment is about 200 feet wide and is grass covered. A sinkhole-type depression was located in the embankment about 50 feet from the training wall and 100 feet from the upstream slope. The existence of a concrete cut-off wall (as shown on Figure 4) in the embankment could not be verified.

c. Gatehouse - The gatehouse is located on the north end of the concrete dam. Four openings, located in the non-overflow section below the gatehouse, are used for passing flows through the structure. Two of the openings are fitted with sluice gates; the remaining openings are fitted with stoplog assemblies. Although the stoplogs were in place during the inspection, significant leakage was observed through both stoplogs.

A sluiceway is positioned to the left of the gatehouse and is used for sluicing logs and debris. The stoplogs were in position and no leakage was observed.

All gates and stoplogs are manually operated. The gate and stoplog operating equipment appeared to be well maintained and in working condition.

Trash racks are located at the intakes to both gated openings; only minor indications of corrosion were noted on the structures. Some trash was accumulated on both racks.

The downstream face of the gatehouse and sluiceway is protected with a gunite surface treatment. The gunite surfacing has cracked over most of this area and spalled concrete was noted in a few of the areas where the gunite had scaled from the structure. Severe erosion of the gunite is evident at the base of the piers separating the individual gates and stoplog slots.

Immediately below the sluiceway, a large portion (approximately 10 feet by 6 feet) of the gunite material has scaled and dislodged from the structure. The gunite thickness is about two inches. The anchors and wire mesh used to secure the gunite to the structure are exposed in this location.

The concrete on the upstream side of the gatehouse appears to be in good condition. Some spalling of concrete was observed above the intakes to the gatehouse. The spalling is localized; no exposed reinforcing steel was noted.

d. Spillway - The upstream slope of the spillway is severely spalled below the water line. Large cracks are apparent throughout the portion of the slope which is visible. The concrete spillway crest shows no significant deterioration. There were no noticeable deviations in the crest alignment.

Seepage was observed on the downstream face of the spillway section occurring at a rate sufficient to keep the concrete surface moist. Sounding of the concrete surface revealed areas of "soft" and "drummy" or deteriorated concrete.

A concrete slab is located at the base of the spillway and extends downstream for about twenty feet. The joint between the slab and toe of the gravity section is open and filled with water. Reinforcing steel extending from both the slab and gravity section is exposed along this joint. Probing of the joint indicated a void area extending at least three feet into the gravity section. A bubbling action was noted at one place along this joint.

e. Non-Overflow Section - The spillway section terminates in a non-overflow section which extends about thirty feet to the south abutment. The concrete is spalled and reinforcing steel is exposed in the non-overflow section above the junction with the spillway. The non-overflow section appears to be keyed into a rock foundation.

Seepage was observed at the toe of the non-overflow section about 35 feet from the south abutment and at the toe of the overburden downstream of the south abutment. The seepage rates were estimated to be about 1 gpm. Approximately 100 feet downstream of the left abutment, pools of rusty colored water were located above the channel bank. No movement was observed in the pools.



f. Approach Channel - The approach channel to the dam is about 150 feet long. The north bank is protected by a training wall. The south side of the approach channel is unprotected and comprises natural slopes. No indications of slope instability were observed in this area.

g. Downstream Channel - The channel bottom downstream of the gatehouse is protected with rock set in place; the channel immediately below the spillway is protected by a concrete apron. No indications of erosion were observed at either location although the surface of the concrete slab is noticeably pitted and spalled.

The south bank of the channel is unprotected and comprises natural slopes. No erosion or slope instability was observed along this bank. The north bank is protected by riprap supported by steel rails and cribbing for about 100 feet below the gatehouse. Some erosion or slumping of bank and fill, in and behind the cribbing, was noted. A highway bridge is located about 300 feet downstream from the dam.

### SECTION 3 - HYDROLOGY AND HYDRAULICS

In accordance with the criteria published in the Recommended Guidelines for Safety Inspection of Dams, the Spillway Design Flood required for evaluation of the hydraulic capabilities of Cranberry Lake Dam is the Probable Maximum Flood (PMF). The PMF was calculated from probable maximum precipitation data published in Hydrometeorological Report No. 33.

Rainfall data was modified to account for basin size and storm characteristics by using standard reduction factors. The HEC-I computer program was used to develop the inflow hydrograph and flood route the PMF through the reservoir facility.

Peak inflow and outflow rates for the PMF were calculated to be 79,000 cfs and 16,800 cfs respectively. The PMF would increase the water surface to Elevation 1498.9, overtopping the spillway by 8.9 feet, and overtopping the non-overflow sections and training wall by 5.4 feet. Peak inflow and outflow rates for one-half of the PMF were calculated as 39,500 cfs and 6,400 cfs respectively. The dam could pass about 18 per cent of the PMF without overtopping the non-overflow sections and embankment. The spillway is "seriously inadequate" as cited in ETL 1110-2-234.

A drawdown analysis was performed to estimate the time required to drain the reservoir. The starting water surface elevation was assumed at the spillway crest and inflow to the reservoir was considered negligible. The two gates were also assumed to be completely open. Under these conditions, the estimated time to drain the reservoir is about fifty-three days. A shorter time could be attained by using the available sluiceways; however, downstream constraints such as safe velocities and flows must be considered before establishing any minimum time for the drawdown procedure.



## SECTION 4 - STRUCTURAL STABILITY

### 4.1 EVALUATION OF STRUCTURAL STABILITY

a. Visual Observations - No indications of structural instability were noted during the visual inspection of Cranberry Lake Dam.

b. Drawings - Design data and construction history relative to Cranberry Lake Dam were provided by NYSDEC and OR-CRC. The drawings consisted of two sets of design plans: original construction in 1917 and the major modifications made in 1956.

The more recent drawings (1956) do not confirm the construction of a key in the concrete gravity dam foundation. Also, a discrepancy was noted between the plans and actual conditions observed during the visual inspection relative to the downstream slope of the spillway section.

c. Operating Records - Reservoir stage readings and discharge through the gated openings are recorded daily by the OR-CRC. According to the owner's representative, ice thickness up to 40 inches in depth form on the reservoir surface.

d. Post Construction Changes - According to design drawings and data provided by NYSDEC, the original structure, constructed in 1917, was an Ambursen type dam. The structure was reconstructed as a gravity dam and the spillway raised to its present elevation in 1956. A gunite surface treatment was applied to the gatehouse and spillway in 1957.

e. Seismic Stability - According to the Geologic Map of New York (Adirondack sheet) dated 1970, Cranberry Lake Dam is founded on primarily granular, and bouldery glacial and alluvial deposits, the thickness of which cannot be ascertained from supplied design or construction drawings. The geologic map indicates the occurrence of gneissic bedrock in the vicinity of the left abutment. Rock outcroppings were observed at this location during the visual inspection.

Cranberry Lake Dam is situated in Zone 3 as shown on the Seismic Zone Map of Contiguous States and, therefore, could be subjected to major seismic activity. In view of this probability, the stability analyses considered the effect of seismic loading using the recommended coefficient for Zone 3 ( $a = 0.1 g$ ).

Detailed information pertaining to foundation investigations is not available. Therefore, design assumptions concerning foundation characteristics were based on information obtained from general geologic maps and field observations made during the course of the inspection.

f. Evaluation - Four loading conditions were analyzed in evaluating the structural stability of the spillway. The results of these analyses are summarized in the appendix. The safety factors developed for sliding stability do not meet the criteria presented in the Recommended Guidelines for Safety Inspection of Dams (... "computed sliding safety factors approximating 3 or more for all loading conditions without earthquake, and 1.5 including earthquake, should indicate satisfactory stability, depending upon the reliability of the strength parameters used in the analyses"). The reported foundation conditions indicate that the structure is not constructed on bedrock; therefore, shear strength was not included in the analysis of sliding stability.

Furthermore, the resultant of forces for the spillway section is located outside the middle third of the base width for the PMF and ice loading conditions.

STABILITY ANALYSES  
SUMMARY OF RESULTS

<u>Loading Condition</u>	<u>Factor of Safety</u>		<u>Bearing Pressure</u>	
	<u>Overturning</u>	<u>Sliding</u>	<u>Toe</u>	<u>Heel</u>
Normal Pool	2.05	1.84	17.8	1.4
PMF	1.41	1.15	16.0	-.3
Ice Load	1.35	1.04	27.2	-8.8
Earthquake	1.86	1.29	19.8	-.6

## SECTION 5 - ASSESSMENT/RECOMMENDATIONS/REMEDIAL MEASURES

### 5.1 ASSESSMENT

In accordance with Recommended Guidelines for Safety Inspection of Dams the concrete gravity spillway is structurally unstable relative to sliding for all loading conditions. Furthermore, the resultant falls outside the middle third of the base width for the PMF and ice loadings conditions.

The upstream slope of the spillway is significantly cracked and spalled. However, no indication of relative movement in the structure was evident. Separation of the concrete has occurred at the junction of the toe of the spillway with the downstream slab. A void area extends at least 3 feet into the spillway section.

Seepage was observed on the downstream face of the spillway and in the toe and overburden areas downstream of the non-overflow section. Small pools of discolored water were also located on the channel bank about 100 feet downstream of the south abutment.

Settlement and erosion in the backfill adjacent to the training wall and a sinkhole type depression in the embankment area behind the training wall were noted. These conditions have not been investigated.

The spillway is hydraulically incapable of passing the PMF without overtopping the non-overflow sections. The spillway is capable of passing 18 per cent of the PMF without overtopping the non-overflow sections.

The gunite surface treatment is significantly cracked and has separated from the structure in a number of places. This condition does not appear to have a detrimental effect on the stability of the structure.

### 5.2 RECOMMENDATIONS/REMEDIAL MEASURES

Additional investigations, remedial measures and recommended actions are as follows:

1. A boring program should be performed to:
  - a) Determine as built conditions.

b) Establish observation wells to monitor groundwater movement in the earthen embankment and north abutment.


c) Establish the existence of a keyway in the dam.

2. Further stability analysis should be performed based on the results of the boring program.

3. Develop an emergency drawdown procedure that could be accomplished in a minimum time taking into consideration all constraints relating to allowable downstream flows and velocities. This would include a flood warning system.

FIGURES






**FIGURE 1**  
**REGIONAL**  
**VICINITY MAP**  
 SCALE 1:24000







SOURCE: GEOLOGIC MAP OF NEW YORK  
ADIRONDACK SHEET 1970

LEGEND









-  amg · HORNBLLENDE AND QUARTZ GNEISS
-  hbg · BLACK MICA AND/OR GRANITE
-  hqs · QUARTZ SYENITIC GNEISS
-  lg · LEUCOGRANTIC GNEISS
-  mu · FRAGMENTED METAMORPHIC ROCK
-  mug · FRAGMENTED GRANITIC GNEISS
-  Q · GLACIAL AND ALLUVIAL DEPOSITS

FIGURE 2  
GEOLOGIC MAP



1


102'-4"

ELEV 14900

CREST OF DAM

SEE DETAIL

6'-0"



11'-6"

11'-9"

12'-0"

12'-0"


12'-0"

12'-0"

11'-9"

1472.20


2




OSWEGATCHIE RIVER - CRANBERRY RESERVOIR COMMISSION AE Building - W. 14th St. - Albany, N.Y. - ACS - 10 - 1000	
CRANBERRY RESERVOIR DAM CRANBERRY LAKE, N.Y. VIEW TO RIGHT	
DATE: 4-18-56	DWG. NO. 101
SCALE: $\frac{1}{8}'' = 1'-0''$	Designed by J.E. McNeil
Drawn by J.E. McNeil	Checked by J.E. McNeil

FIGURE 3







OLD DAM AND COFFER DAM  
 ELEV 1495.8 AV94  
 TO BE DEMOLISHED BY CONTRACTOR



STATE OF NEW YORK  
 DEPARTMENT OF ENVIRONMENTAL CONSERVATION  
 DIVISION OF WATER  
 WATER RESOURCES DIVISION  
 CANTON, NEW YORK  
 1984

FIGURE 4



F.S.P.  
1-5-20  
A.P.C.









FIGURE 6



NEW YORK STATE COMMISSION	
NEW PROPOSED SPILL	
FOR THE STATE RESERVOIR	
DATE: 4-10-57	FILE NO. 107
SCALE: 1/2" = 1'-0"	DR. BY: J. E. H. H. H.
TR. BY: J. E. H. H.	AS. BY: J. E. H. H.

FIGURE 6

2

APPENDIX

PHOTOGRAPHS

A-1






SPILLWAY CREST



GATE HOUSE PIERS



SETTLEMENT ALONG TRAINING WALL



DOWNSTREAM CHANNEL

FIELD INSPECTION REPORT

Check List  
Visual Inspection  
Phase 1

Mr. Maynard Miller  
Coordinators OR-CRC

Name Dam Cranberry Lake Dam State New York

County St. Lawrence

Mr. Maynard Miller  
Coordinators OR-CRC

Date(s) Inspection June 12, 1978 Weather Sunny Temperature 70° F

Pool Elevation at Time of Inspection 1489 ± M.S.L. Tailwater at Time of Inspection N/A M.S.L.

Inspection Personnel:

A-5 Mr. J. J. Williams Mr. J. V. Ryan

Mr. A. J. Depman \_\_\_\_\_

Mr. R. E. Horvath \_\_\_\_\_

Mr. R. E. Horvath Recorder

Accompanied by: Mr. Maynard Miller, Chairman, Oswegachie River-Cranberry Reservoir Commission



CONCRETE/MASONRY DAMS

VISUAL EXAMINATION OF

OBSERVATIONS

REMARKS OR RECOMMENDATIONS

SEEPAGE OR LEAKAGE

STRUCTURE TO  
ABUTMENT/EMBANKMENT  
JUNCTIONS

Settlement was observed in the backfill along the approach channel training wall and at the structure/embankment junction hole. A sink type depression was located in the embankment behind the training wall. Seepage was observed in the toe of the left abutment.

DRAINS

No drains were noted.

A-6

WATER PASSAGES

The gate controlled openings and sluiceway passages could not be inspected because of discharge. Minor cracking and spalling of the surface material in the log sluice and ungated opening were evident.

FOUNDATION

Not observed.

CONCRETE/MASONRY DAMS

VISUAL EXAMINATION OF

OBSERVATIONS

REMARKS OR RECOMMENDATIONS

SEEPAGE OR LEAKAGE

STRUCTURE TO  
ABUTMENT/EMBANKMENT  
JUNCTIONS

Settlement was observed in the backfill along the approach channel training wall and at the structure/embankment junction hole. A sink type depression was located in the embankment behind the training wall. Seepage was observed in the toe of the left abutment.

DRAINS

No drains were noted.

A-6

WATER PASSAGES

The gate controlled openings and sluiceway passages could not be inspected because of discharge. Minor cracking and spalling of the surface material in the log sluice and ungated opening were evident.

FOUNDATION

Not observed.

CONCRETE/MASONRY DAMS

REMARKS OR RECOMMENDATIONS

OBSERVATIONS

VISUAL EXAMINATION OF

UPPER SURFACE OF  
CONCRETE SURFACES

The upstream slope of the spillway is severely cracked and spalled. The severity of the cracking could not be determined. Some seepage was observed on the downstream face of the spillway.

STRUCTURAL CRACKING

See above.

VERTICAL AND HORIZONTAL  
ALIGNMENT

A-7

No significant deviations in the crest alignment of the spillway were evident. A slight but noticeable deviation in the horizontal alignment of the gatehouse piers was evident.

CONCRETE JOINTS

CONSTRUCTION JOINTS

EMBANKMENT

REMARKS OR RECOMMENDATIONS

OBSERVATIONS

VISUAL EXAMINATION OF

SURFACE CRACKS

None noted.

UNUSUAL MOVEMENT OR  
CRACKING AT OR BEYOND  
THE TOE

None noted.

SLUGHING OR EROSION OF  
EMBANKMENT AND ADJUTENT  
SLOPES

Erosion was observed on the  
downstream slope of the embank-  
ment at the junction with the  
concrete gravity dam. No seep-  
age was noted.

A-  
100

VERTICAL AND HORIZONTAL  
ALIGNMENT OF THE CREST

N/A

REFRAC FAILURES

N/A

OUTLET WORKS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
<p>CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT</p>	<p>The gunite surface treatment on the piers separating the discharge channels is cracked and has eroded along the base of the openings.</p>	
<p>INTAKE STRUCTURE</p>	<p>The concrete surface above the intakes is spalled. Minor corrosion was noted on the trash rack structure.</p>	
<p>OUTLET STRUCTURE A-9</p>	<p>N/A</p>	
<p>OUTLET CHANNEL The water passages discharge to the river. No erosion was evident.</p>	<p>N/A</p>	
<p>EMERGENCY GATE</p>	<p>N/A</p>	



UNGATED SPILLWAY

REMARKS OR RECOMMENDATIONS

OBSERVATIONS

VISUAL EXAMINATION OF

CONCRETE WEIR

The concrete weir appears to be in good condition. No spalling or cracking was noted.

APPROACH CHANNEL

The concrete approach slab is severely cracked and spalled. The extent and severity of the cracking could not be determined.

DISCHARGE CHANNEL

A-10

The spillway discharges to a concrete apron. The apron has separated from the spillway section and the surface is noticeably spalled and pitted.

BRIDGE AND PIERS

N/A

INSTRUMENTATION

REMARKS OR RECOMMENDATIONS

OBSERVATIONS

VISUAL EXAMINATION

MONUMENTATION/SURVEYS

None noted.

OBSERVATION WELLS

None noted.

WEIRS

A-11

None noted.

PIEZOMETERS

None noted.

OTHER

Staff Gage

A reservoir staff gage is located in the approach channel. According to the owner's representative, the gage reading is monitored and recorded daily.

RESERVOIR

REMARKS OR RECOMMENDATIONS

OBSERVATIONS

VISUAL EXAMINATION OF

SLOPES

No indication of slope instability or erosion were noted in the areas observed.

SEDIMENTATION

The degree of sedimentation could not be determined.

DOWNSTREAM CHANNEL

REMARKS OR RECOMMENDATIONS

VISUAL EXAMINATION OF

OBSERVATIONS

CONDITION  
(OBSTRUCTIONS,  
DEBRIS, ETC.)

A highway bridge is located about 300 feet downstream of the dam.

SLOPES

The slope on the right bank is protected with retained riprap for a distance of about 100 feet downstream of the dam. The remainder of the distance down to the highway bridge is protected with riprap. Some minor settlement of the riprap was noted on the right bank. The left bank is unimproved and comprises natural slopes. No indications of slope instability were noted.

APPROXIMATE NO.  
OF HOMES AND  
POPULATION

The area downstream of the dam is sparsely populated. However, the majority of the dwellings appear to be located adjacent to the riverbank.

ITEM

REMARKS

MONITORING SYSTEMS

- A reservoir staff gage is located in approach channel.

MODIFICATIONS

- The originally constructed spillway (ambursen type) was modified to a gravity structure in 1956. The spillway crest was also raised to its present elevation in 1956.

HIGH POOL RECORDS

- Reservoir staff readings are recorded daily.

POST CONSTRUCTION ENGINEERING  
STUDIES AND REPORTS

- None were made available.

A-14

PRIOR ACCIDENTS OR FAILURE OF DAM  
DESCRIPTION  
REPORTS

- None were made available.

MAINTENANCE  
OPERATION  
RECORDS

- None were made available. According to the owner's representative, maintenance is performed on an as-required basis.



CHECK LIST  
ENGINEERING DATA  
DESIGN, CONSTRUCTION, OPERATION

REMARKS

- Design drawings of the original construction (1917) and of the modifications (1956) were provided by NYSDEC and OR-CRC.

- Not made available.

- A verbal description of the construction history was provided by the owner's representative.

- Typical sections of the dam were included in the design drawings provided by NYSDEC and OR-CRC.

- Limited Hydrologic/Hydraulic data were made available.

- Not made available.

PLAN OF DAM

REGIONAL VICINITY MAP

CONSTRUCTION HISTORY

TYPICAL SECTIONS OF DAM

A-15

HYDROLOGIC/HYDRAULIC DATA

OUTLETS - PLAN

- DETAILS

- CONSTRAINTS  
- DISCHARGE RATINGS

WALL/RESERVOIR RECORDS

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC

HYDROLOGIC AND HYDRAULIC CALCULATIONS

NAME OF CLIENT SEPS OF ENGINEERS  
PROJECT CUMULY LAKES

WATERWAY AREA (CONTAINING ST.) = 144 SQ. MILES

L = 26 MILES

L<sub>CA</sub> = 8 MILES

AVERAGE TYPICAL COEFFICIENTS

C<sub>T</sub> = 0.625

C<sub>F</sub> = 2.0

$$t_T = C_T (L \times L_{CA})^2 = 2.0 (26 \times 8)^2 = 9.9$$

$$t_R = t_T / 5.5 = 1.8 \text{ HOURS}$$

$$t_R = 2.0 \text{ HRS}$$

$$t_{TR} = t_T + 2.5(t_R - t_T) = 9.9 + 2.5(2 - 1.8) = 10.0$$

6 HR. PMP = 21"

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC

REDUCTION DUE TO PROBABLE IMPERFECT FIT  
OF TRAIN WITH STORM IS HYDRAULIC 12%

6 HR. PMP = 18.5"

DEPTH-AREA-DURATION FOR PMP

$$6 \text{ HR. PMP} = 18.5" \times 0.72 = 13.3"$$

$$12 \text{ HR. PMP} = 18.5 \times 0.85 = 15.7"$$

$$15.7 - 13.3 = 2.4"$$

NAME OF CLIENT CORPS OF ENGINEERS  
 PROJECT RESERVOIR LAKE

PUMP DISTRIBUTION

TIME (HR)	PIPE SIZE	REMARKS
0-2	8.6"	(65% GHR. PMP)
2-4	2.7"	(20% GHR. PMP)
4-6	2.0"	(15% GHR. PMP)
6-8	.8"	} 12 HR. PMP - (GHR. PMP)
8-10	.8"	
10-12	.8"	

PIPE ROUTILE DISTRIBUTION

TIME (HR)	PIPE SIZE
0-2	.8"
2-4	.8"
4-6	2.0"
6-8	8.6"
8-10	2.7"
10-12	.8"

SUBJECT	SHEET	BY	DATE	JOB NO
CRANBURY LAKE DAM	4	REI	6/20/78	

Checked DBC

STAGE - DISCHARGE

- ASSUME SLUICE GATES OPEN (fully)

SLUICE GATES (2) - INV ELEVATION - 1472.2

- GATE SIZE - WIDTH = 5'

HEIGHT = 4'

ASSUME OUTLET CONTROL - W.S.E @ 1478 (avg for PMF condition)

uniform passage through gate house

Head LOSSES - ENTRANCE LOSS = .5

RACK LOSS = .15

$$n = .012$$

$$L \approx 15'$$

$$r = \frac{20}{18} = 1.11$$

$$H = \left( 1 + K_e + K_r + \frac{29n^2L}{r^{1.33}} \right) \frac{V^2}{2g} = (1.65 + .05) \frac{V^2}{2g}$$

$$H = (1.7) \frac{V^2}{2g}$$

$$V \approx \sqrt{38 H}$$



SUBJECT	SHEET	BY	DATE	JOB NO
CRATER LAKE DAM	5	RELL	6/20/78	

Checked DBC

STAGE - DISCHARGE (Cont)

- Assume stoplog gates and log sluice to be closed and ineffective in passing flows

- Spillway Capacity

Spillway Crest elev = 1490.0'  
Crest length = 110.0'  
Weir Coeff = 3.0

$$Q = CLH^{3/2} = 330H^{3/2}$$

- Above Elevation 1493.5 assume an additional  
Overflow Length  $\approx$  100 feet  $C = 2.6$

$$Q = CLH^{3/2} = 494H^{3/2} \quad \text{use } 500H^{3/2}$$

SUBJECT	SHEET	BY	DATE	JOB NO
CRANBERRY LAKE DAM	6	REL	6/29/73	

*Sneaked DBC*

STAGE - DISCHARGE RATING

Elev	(ft) HGATES	(ft) HSPILLWAY	(ft) Hoverflow	(cfs) Q <sub>G</sub>	(cfs) Q <sub>S</sub>	(cfs) Q <sub>O</sub>	(cfs) Q <sub>TOTAL</sub>
1490	Assumed closed @ start of PMF		0	0	0	0	say 0
1492	14	2	0	923	933	0	1856
1494	16	4	.5	986	2640	177	3803
1496	18	6	2.5	1046	4850	1976	7872
1498	20	8	4.5	1102	7467	4773	13342
1500	22	10	6.5	1157	10436	8286	19879
1502	24	12	8.5	1208	13718	12351	27317

JUSTIN & COURTNEY, INC.  
Division of O'Brien & Gere Engineers, Inc.  
PHILADELPHIA, PA

SHEET NO. 6A OF \_\_\_\_\_


DATE 6/23/78

COMP. BY DEL

CHECKED BY DBC

NAME OF CLIENT NYSDEC

PROJECT CRAWLEPPY LAKE DAM



SUBJECT CAMPBELL LAKE DAM	SHEET 7	BY R.E.H.	DATE 6/22/78	JOB NO
------------------------------	------------	--------------	-----------------	--------

Checked DBC

STAGE - STORAGE

Surface area at spillway crest = 7104 Ac (from USGS sheet 1:625,000 Scale)

Storage at Spillway crest = 57400 AcFt (from NWSDB)

Approx lake depth =  $\frac{7104 \times 10}{2}$   $d = 57400$   $d = 16.2'$

Assume Area varies w/ depth  $7104 / 16.2 = 438.5$  Ac/Ft

Above Spillway Crest - @ 1490 Area = 7104 Ac, @ 1500 Area = 11264 Ac

$\therefore A = 416 d$ , Storage =  $208 d^2 + 7104d$

Stage	Area (Ac)	INC Storage (AcFt)	Accum Stor (AcFt)	
1473.8	0	0	0	
1478.0	1841.8	3867.8	3867.8	
1482.0	3595.8	10875.2	14743.0	
1486.0	5349.9	17891.4	32634.4	AccStor
1490.0	7104.0	24907.8	57542.2	0
1492	7936.0		72582	15040
1494	8768.0		89286	31744
1496	9600.0		107654	50112
1498	10432.0		127686	70144
<u>1500</u>	<u>11264.0</u>		149382	91840
1502	12096.0		172742	115200

ABOVE SPILLWAY ELEV.

A-23

Planimeter check w/ USGS 1:625,000 Series - Lake Area @ El 1500  
 $= 1.1(16) \times \frac{5280^2}{43560} = 11,264$  Ac

JUSTIN & COURTNEY, INC.  
Division of O'Brien & Gere Engineers, Inc.  
PHILADELPHIA, PA

SHEET NO. 7A OF \_\_\_\_\_


DATE 6/29/78

COMP. BY REH

CHECKED BY DBC


NAME OF CLIENT NYSDEC.

PROJECT CRANBERRY LAKE DAM





NAME OF CLIENT NYSDEC  
 PROJECT Cranberry Lake



OBJECT	SHEET	BY	DATE	JOB NO
CRANBERRY LAKE DAM	8	REH	6/29/78	

Checked DJC

DRAWDOWN ANALYSIS

- Assume - 2 - 5' x 4' gates

fully open

- Water surface at spillway crest

Elev	Head	Vel (fps)	Area (sqft)	Q (cfs)
1490	13.8	22.9	40	916
1486	9.8	19.3	       Y	772
1482	5.8	14.8		592
1478	1.8	8.2		331
1473.8	0	0		0

Elev	to	Elev	Storage (CF)	AVG DIS (cfs)	TIME (Hrs)
1490	-	1486	$1085 \times 10^6$	844	357
1486	-	1482	$779 \times 10^6$	682	317
1482	-	1478	$642 \times 10^6$	462	386
1478	-	1473.8	$168 \times 10^6$	166	211

Time required  $\approx$  53 days

The results give a minimum time for drawdown using only the two gated openings for discharge. No consideration has been given to downstream constraints which might restrict discharge velocities and flows.

\*\*\*\*\*  
 HEG-1 VERSION DATED JAN 1973  
 UPDATED AUG 74  
 CHANGE NO. 01  
 \*\*\*\*\*

PHF ROUTING  
 CANNERY LAKE DAM  
 O'BRIEN + GEPE → JUSTIN + COURTNEY DIV

JOB SPECIFICATION  
 NO NHR NMIN IDAY IHR IMIN METRG IPLT IPRT NSTAN  
 48 2 0 1 0 0 0 0 0 0 2 0  
 JOPER 0 NMT 0  
 5 0

MULTI-PLAN ANALYSES TO BE PERFORMED  
 NPLAN= 1 NRTIO= 9 LPTIO= 1

RTIOS= .10 .20 .30 .40 .50 .60 .70 .80 1.00

SUB-AREA RUNOFF COMPUTATION

1STAG ICOMP IEGON ITAPE JPLT JPRT INAME  
 1 0 0 0 0 1 0 0

HYDROGRAPH DATA

IMYDG	IJHG	TAREA	SNAP	TRSDA	TRSPC	RATIO	ICSNOW	ISAVE	LOCAL
0	1	146.00	0.00	0.00	0.00	0.000	0	0	0

PRECIP DATA

MP	STORM	TAJ	DAK
5	0.00	0.00	0.00

PRECIP PATTERN  
 2.70 .80

LOSS DATA

STOKR	OLTKR	RTIOL	ERAIN	STRXS	RTIOK	STRIL	CNSTL	ALSMX	RTIMP
0.00	0.00	1.00	0.00	0.00	1.00	0.99	.10	0.00	0.00

UNIT HYDROGRAPH DATA  
 TP=10.00 GP=.63 NTA= 0

REGRESSION DATA

STAT9= 0.00 QPGSN= 0.00 RTIOR= 1.00  
 APPROXIMATE CLARK COEFFICIENTS FROM GIVEN SNYDER CP AND TP ARE IC= 5.81 AND R= 4.44 INTERVALS

UNIT HYDROGRAPH-27-END-OF-PERIOD ORIGINATES, LAG= 9.94 HOURS, CP= .62 VOL= 1.00	4947.	3946.	3147.	2509.
475.	1722.	3365.	4887.	5788.
2001.	1596.	1273.	1015.	810.
208.	166.	132.	106.	84.
			5771.	4947.
			515.	411.
			54.	327.
			67.	261.

END-OF-PERIOD FLOW

TIME	RAIN	EXCS	COMP	Q
1	2	0	.80	285.
			.60	170.

THIS PAGE IS BEST QUALITY PRACTICABLE  
 FROM COPY FURNISHED TO DDC

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC

1	14	0	0.00	0.00	0.00	67346.
1	16	0	0.00	0.00	0.00	78577.
1	18	0	0.00	0.00	0.00	79037.
1	20	0	0.00	0.00	0.00	69953.
1	22	0	0.00	0.00	0.00	57344.
2	2	0	0.00	0.00	0.00	45939.
2	4	0	0.00	0.00	0.00	36636.
2	6	0	0.00	0.00	0.00	29218.
2	8	0	0.00	0.00	0.00	23301.
2	10	0	0.00	0.00	0.00	18583.
2	12	0	0.00	0.00	0.00	14820.
2	14	0	0.00	0.00	0.00	11819.
2	16	0	0.00	0.00	0.00	9425.
2	18	0	0.00	0.00	0.00	7517.
2	20	0	0.00	0.00	0.00	59951.
2	22	0	0.00	0.00	0.00	4781.
3	0	0	0.00	0.00	0.00	3813.
3	2	0	0.00	0.00	0.00	3041.
3	4	0	0.00	0.00	0.00	2425.
3	6	0	0.00	0.00	0.00	1934.
3	8	0	0.00	0.00	0.00	1542.
3	10	0	0.00	0.00	0.00	1204.
3	12	0	0.00	0.00	0.00	935.
3	14	0	0.00	0.00	0.00	669.
3	16	0	0.00	0.00	0.00	174.
3	18	0	0.00	0.00	0.00	32.
3	20	0	0.00	0.00	0.00	0.
3	22	0	0.00	0.00	0.00	0.
4	2	0	0.00	0.00	0.00	0.
4	4	0	0.00	0.00	0.00	0.
4	6	0	0.00	0.00	0.00	0.
4	8	0	0.00	0.00	0.00	0.
4	10	0	0.00	0.00	0.00	0.
4	12	0	0.00	0.00	0.00	0.
4	14	0	0.00	0.00	0.00	0.
4	16	0	0.00	0.00	0.00	0.
4	18	0	0.00	0.00	0.00	0.
4	20	0	0.00	0.00	0.00	0.
4	22	0	0.00	0.00	0.00	0.
5	0	0	0.00	0.00	0.00	0.

SUM 15.70 14.50 670323.

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
79037.	75856.	49554.	18620.	670320.
INCHES	4.90	12.55	14.43	14.43
AC-FT	37634.	96354.	110854.	110854.

HYDROGRAPH AT STA 1 FOR PLAN 1, RTIO 1

29.	132.	391.	1204.	2612.	4859.	6735.	7958.	7904.	6995.
5734.	4596.	3664.	2922.	2310.	1858.	1492.	1182.	943.	752.
599.	478.	381.	304.	242.	193.	158.	120.	93.	67.
17.	3.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME					
7904.	7586.	4855.	1862.	67032.					
INCHES	4.43	1.25	1.44	1.44					
AC-FT	3763.	9635.	11085.	11085.					



35.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
HYDROGRAPH AT STA 1 FOR PLAN 1, RTIO 3														
396.	1172.	3613.	8436.	14577.	20204.	23711.	20986.	23711.	20986.	23711.	20986.	23711.	20986.	23711.
17203.	10991.	8765.	6930.	5575.	4466.	3546.	2828.	3546.	2828.	3546.	2828.	3546.	2828.	3546.
1798.	1434.	1144.	912.	727.	580.	453.	280.	453.	280.	453.	280.	453.	280.	453.
52.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
HYDROGRAPH AT STA 1 FOR PLAN 1, RTIO 4														
527.	1563.	4817.	11247.	19436.	26938.	31615.	27981.	31615.	27981.	31615.	27981.	31615.	27981.	31615.
22917.	19376.	14655.	11687.	9320.	7433.	5928.	3770.	7433.	5928.	7433.	3770.	5928.	3770.	5928.
2398.	1912.	1525.	1216.	970.	774.	617.	374.	970.	774.	617.	374.	970.	774.	617.
70.	13.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
HYDROGRAPH AT STA 1 FOR PLAN 1, RTIO 5														
143.	659.	1954.	6021.	14059.	24295.	33673.	39518.	33673.	39518.	33673.	39518.	33673.	39518.	33673.
28672.	22969.	18318.	14509.	11651.	9291.	7410.	4713.	11651.	9291.	7410.	4713.	11651.	9291.	7410.
2997.	2390.	1906.	1520.	1212.	967.	771.	467.	1212.	967.	771.	467.	1212.	967.	771.
87.	16.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
HYDROGRAPH AT STA 1 FOR PLAN 1, RTIO 6														
171.	791.	2345.	7225.	16871.	29158.	40408.	47422.	40408.	47422.	40408.	47422.	40408.	47422.	40408.
34436.	27563.	21982.	17531.	13981.	11150.	8892.	7091.	13981.	11150.	8892.	7091.	13981.	11150.	8892.
3597.	2868.	2288.	1824.	1455.	1160.	925.	723.	1455.	1160.	925.	723.	1455.	1160.	925.
105.	19.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
HYDROGRAPH AT STA 1 FOR PLAN 1, RTIO 7														
209.	923.	2735.	8430.	19683.	34013.	47142.	55326.	47142.	55326.	47142.	55326.	47142.	55326.	47142.
40141.	32157.	25645.	20452.	16311.	13008.	10374.	8273.	16311.	13008.	10374.	8273.	16311.	13008.	10374.
4198.	3347.	2669.	2128.	1697.	1350.	1090.	843.	2128.	1350.	1090.	843.	2128.	1350.	1090.
122.	23.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.



THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC

AC-FT 26344. 67448. 77598.

HYDROGRAPH AT STA 1 FOR PLAN 1; RTIO 9  
 228. 1055. 3126. 3634. 22495. 38872. 53877. 63230. 55963.  
 45875. 36751. 29309. 23374. 18641. 14866. 11856. 9455. 6013.  
 4795. 3925. 3050. 2432. 1940. 1547. 1234. 963. 740. 535.  
 133. 26. 0. 0. 0. 0. 0. 0. 0. 0.  
 0. 0. 0. 0. 0. 0. 0. 0. 0. 0.

PEAK 6-HOUR 24-HOUR 72-HOUR TOTAL VOLUME  
 JFS 63230. 60685. 18843. 14896. 538256.  
 INC4ES 3492 10.04 11.55 11.55  
 AC-FT 30107. 77083. 88683.

HYDROGRAPH AT STA 1 FOR PLAN 1; RTIO 9  
 285. 1319. 1908. 12042. 28119. 44590. 67346. 78577. 69953.  
 57344. 45939. 36836. 29214. 23301. 14583. 14820. 11819. 7517.  
 5995. 4781. 3013. 2425. 1934. 1542. 1204. 935. 669.  
 174. 32. 0. 0. 0. 0. 0. 0. 0. 0.  
 0. 0. 0. 0. 0. 0. 0. 0. 0. 0.

PEAK 6-HOUR 24-HOUR 72-HOUR TOTAL VOLUME  
 JFS 79037. 75856. 48554. 18620. 670320.  
 INC4ES 4498 12.55 14.43 14.43  
 AC-FT 37634. 96354. 110854.

\*\*\*\*\*

A-30

HYDROGRAPH ROUTING

INSTAQ	ICOMP	IECON	IYAPE	JPLT	JPRT	INAME
2	1	0	0	0	0	0
ROUTING DATA						
QLOSS	CLOSS	AVG	IPES	ISAME		
0.0	0.000	0.00	1	1		
STATION 2; PLAN 1; RTIO 1						
NSTPS	NSTOL	LAG	AMSKK	X	TSK	STORA
1	0	0	0.000	0.000	0.000	-1.
STORAGE=	0.	15040.	31744.	50112.	79144.	91840.
OUTFLOW=	0.	1896.	3803.	7872.	13342.	19879.
						115200.
						140224.
						35555.
						0.
						0.
29.	30.	34.	50.	89.	165.	279.
824.	912.	977.	1023.	1056.	1077.	1099.
1080.	1069.	1056.	1041.	1026.	1010.	993.
922.	904.	885.	868.	850.	833.	816.
752.	737.	722.	707.	693.	679.	665.
231.	233.	277.	402.	723.	1336.	2257.
6577.	7387.	7913.	8292.	9555.	9724.	8872.
4749.	8660.	8556.	8439.	8113.	8181.	8044.
7472.	7322.	7175.	7030.	6898.	6749.	6613.
6095.	5972.	5851.	5733.	5617.	5504.	5393.
4626.	8856.	7762.	6348.	5284.		
5752.	8816.	7619.	6220.			
3405.	8061.	7304.	6479.	5284.		
36789.	71.	5479.				
36789.	71.	5479.				
36789.	71.	5479.				
36789.	71.	5479.				

PEAK 6-HOUR 24-HOUR 72-HOUR TOTAL VOLUME  
 JFS 1094. 1092. 1056. 920. 36789.  
 INC4ES .07 .28 .71 .79  
 AC-FT 542. 2115. 5479. 6084.

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC

849. 1811. 1774. 1738. 1703. 1669. 1635. 1602. 1570. 1538.

1507. 1477. 1447. 1418. 1389. 1361. 1333. 1307.

462. 473. 555. 804. 1445. 2671. 4514. 6811. 9252. 11503.

13354. 14774. 15827. 16586. 17113. 17455. 17652. 17734. 17727. 17649.

17517. 17342. 17135. 16903. 16653. 16390. 16117. 15838. 15554. 15267.

14972. 14673. 14378. 14087. 13803. 13524. 13251. 12983. 12721. 12464.

12213. 11965. 11725. 11489. 11256. 11029. 10806. 10589.

PEAK 5-HOUR 24-HOUR 72-HOUR TOTAL VOLUME

JFS 2170. 2167. 2148. 2137. 2118. 1837. 73456.

INCHES .14 .55 1.42 1.58

AC-FT 1075. 4203. 10935. 12148.

STATION 2, PLAN 1, RTIO 3

86. 89. 103. 149. 268. 496. 836. 1261. 1713. 2114.

2438. 2687. 2972. 3006. 3099. 3160. 3195. 3210. 3197. 3197.

3175. 3145. 3110. 3070. 3027. 2982. 2935. 2887. 2838. 2788.

2737. 2686. 2635. 2584. 2487. 2439. 2393. 2347. 2302.

2254. 2215. 2173. 2131. 2091. 2051. 2012. 1973.

693. 718. 832. 1207. 2158. 4007. 6771. 10215. 13878. 17256.

20036. 22173. 23761. 24908. 25705. 26226. 26529. 26660. 26547.

26355. 26100. 25796. 25455. 25087. 24699. 24296. 23883. 23463.

22602. 22159. 21720. 20855. 20450. 20043. 19644. 19252. 18868.

18491. 18121. 17759. 17403. 17054. 16712. 16376. 16047.

PEAK 6-HOUR 24-HOUR 72-HOUR TOTAL VOLUME

JFS 3210. 3206. 3134. 2705. 2727. 109192.

INCHES .21 .81 2.11 2.35

AC-FT 1591. 6219. 16233. 18059.

STATION 2, PLAN 1, RTIO 4

114. 118. 137. 199. 357. 659. 1114. 1681. 2260. 2765.

3218. 3551. 3798. 4131. 4360. 4505. 4583. 4610. 4597. 4553.

4487. 4403. 4306. 4089. 3973. 3856. 3768. 3704. 3639.

3573. 3506. 3439. 3373. 3309. 3246. 3184. 3123. 3064.

2948. 2892. 2836. 2782. 2729. 2677. 2626. 2576.

924. 1109. 1509. 2891. 5343. 9029. 13621. 18506. 23014.

26726. 29581. 31704. 33225. 34260. 34912. 35255. 35386. 35327. 35131.

34831. 34452. 34016. 33580. 33035. 32513. 31991. 31442. 30895. 30341.

29773. 29195. 28622. 28059. 27507. 26965. 26433. 25912. 25401. 24899.

24407. 23925. 23451. 22987. 22531. 22085. 21646. 21216.

PEAK 6-HOUR 24-HOUR 72-HOUR TOTAL VOLUME

JFS 4610. 4595. 4402. 3670. 146646.

INCHES .30 1.14 2.45 3.16

AC-FT 2280. 8736. 21851. 24252.

STATION 2, PLAN 1, RTIO 5

143. 148. 171. 248. 446. 824. 1333. 2088. 2800. 3457.

4171. 4950. 5514. 5908. 6167. 6322. 6395. 6405. 6365. 6289.

6184. 6053. 5918. 5767. 5609. 5466. 5281. 5116. 4952. 4788.

4623. 4457. 4299. 4164. 3995. 3952. 3755. 3684. 3613. 3544.

3477. 3410. 3345. 3282. 3219. 3157. 3097. 3038.

1155. 1197. 1387. 2011. 3613. 5678. 11286. 17928. 23137. 28777.

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC

PEAK 6-HOUR 24-HOUR 72-HOUR TOTAL VOLUME  
6405. 6380. 6116. 4827. 191316.  
CFS 41 1.58 3.74 4.12  
INC-FEES 3169. 12136. 28735. 31639.AC-FE

STATION 2, PLAN 1, RTIO 6  
171. 177. 205. 238. 515. 989. 1671. 2485. 4417.  
5631. 6543. 7199. 7650. 7957. 8161. 8243. 8232. 8150.  
7846. 7680. 7486. 7301. 7097. 6889. 6679. 6468. 6051.  
5842. 5635. 5432. 5237. 5049. 4867. 4692. 4523. 4204.  
4053. 3907. 3734. 3541. 3571. 3503. 3436. 3354.  
1386. 1437. 1664. 2413. 4316. 8014. 13543. 20435. 34516.  
3998. 4413. 47072. 49111. 50425. 51170. 51470. 51129. 50634.  
4993. 49244. 44416. 47583. 46614. 45674. 44725. 42829. 41891.  
40950. 40012. 39099. 38217. 37367. 35548. 35758. 34996. 33554.  
32872. 32214. 31578. 30959. 30351. 29755. 29170. 28597.STOR

PEAK 6-HOUR 24-HOUR 72-HOUR TOTAL VOLUME  
8243. 8212. 7827. 6081. 239283.  
CFS 53 2.02 4.71 5.15  
INC-FEES 4074. 15533. 36201. 39571.  
AC-FE

STATION 2, PLAN 1, RTIO 7  
200. 207. 240. 347. 624. 1154. 1945. 2882. 5681.  
7079. 8181. 9096. 9712. 10094. 10296. 10357. 10312. 9997.  
9764. 9500. 9213. 8913. 8604. 8291. 7979. 7707. 7209.  
6960. 6712. 6471. 6239. 6014. 5798. 5590. 5399. 5008.  
4828. 4654. 4487. 4356. 4170. 4020. 3876. 3768. 3681.  
1617. 1676. 1341. 2816. 5059. 9349. 15800. 23843. 40221.  
46530. 51244. 54594. 58250. 58988. 59214. 59047. 58582. 57894.  
57042. 56074. 55024. 53923. 52731. 51647. 50504. 49366. 47114.  
45995. 44877. 43790. 42739. 41727. 40750. 39839. 38902. 37184.  
36371. 35587. 34832. 34104. 33401. 32725. 32072. 31440. 30227.STOR

PEAK 6-HOUR 24-HOUR 72-HOUR TOTAL VOLUME  
10357. 10322. 9787. 7430. 290676.  
CFS 67 2.53 5.76 6.26  
INC-FEES 5121. 19421. 44232. 48070.  
AC-FE

STATION 2, PLAN 1, RTIO 8  
228. 236. 274. 397. 713. 1319. 2208. 3280. 6930.  
8657. 10099. 11111. 11703. 12190. 12392. 12434. 12356. 11947.  
11658. 11334. 10985. 10621. 10249. 9874. 9499. 9128. 8405.  
8049. 7730. 7452. 7184. 6926. 6677. 6437. 6205. 5767.  
5560. 5360. 5167. 4981. 4802. 4629. 4463. 4302. 4180.  
1848. 1915. 2219. 3218. 5781. 10685. 18059. 27253. 45860.  
52488. 56267. 61973. 64835. 65926. 66684. 66820. 66533. 65009.  
63977. 62790. 61513. 60181. 58817. 57442. 56071. 54713. 52063.  
50759. 49469. 48216. 47007. 45841. 44716. 43633. 42588. 40610.  
39674. 38771. 37901. 37062. 36254. 35474. 34723. 33999. 32827.STOR

PEAK 6-HOUR 24-HOUR 72-HOUR TOTAL VOLUME  
12434. 12394. 11750. 8807. 343895.  
CFS 80 3.04 6.83 7.41  
INC-FEES 6149. 23317. 52431. 56871.  
AC-FE

5534.	15041.	14519.	13980.	13434.	12928.	12435.	11946.	11466.	10996.
10529.	10069.	9625.	9200.	8794.	8406.	8035.	7716.	7438.	7171.
6913.	6664.	6425.	6194.	5971.	5756.	5549.	5350.		
2319.	2394.	2773.	4022.	7227.	13356.	22576.	34053.	46144.	57072.
65781.	72159.	75568.	79415.	81047.	81743.	81721.	81155.	80101.	78909.
77420.	75784.	74051.	72262.	70448.	69630.	66821.	65033.	63275.	61551.
59842.	59156.	56532.	54976.	53449.	52067.	50708.	49407.	48154.	46947.
45783.	44661.	43579.	42536.	41531.	40562.	39627.	38727.		

STOR

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	16837.	16776.	15816.	11640.	452673.
INC-FE		1.08	4.99	9.02	9.75
AC-FI		9323.	31397.	69299.	74861.

\*\*\*\*\*

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC



PEAK FLOW SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS

OPERATION	STATION	PLAN	RATIOS APPLIED TO FLOWS								
			.10	.20	.30	.40	.50	.60	.70	.80	1.00
HYDROGRAPH AT	1	1	7904.	15807.	23711.	31615.	39518.	47422.	55326.	63230.	79037.
	2	2	0.	0.	0.	0.	0.	0.	0.	0.	0.
ROUTED TO	1	1	1094.	2170.	3210.	4610.	6405.	8243.	10357.	12434.	16837.
	2	2	0.	0.	0.	0.	0.	0.	0.	0.	0.

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC




STABILITY ANALYSES

A-35

SUBJECT	SHEET	BY	DATE	JOB NO.
CUNIZAWAY LAKE DAM	1	REL	7/3/78	NYSDES

SPILLWAY SECTION



Section developed from drawings provided by NYSDEC  
and OR-CRC and from visual observations

- Assumptions:
- Unit weight of concrete = 144 pcf
  - Unit weight of silt (wet) = 86 pcf
  - internal  $\angle$  of friction for silt =  $30^\circ$
  - ice pressure = 5 ksf (2 foot thickness) Assumed at dam location
  - $\angle$  of friction - concrete/foundation =  $30^\circ$
  - shear resistance - concrete/<sup>rock</sup> foundation = 100 psi
  - seismic coeff. of acceleration = .1g
  - negative pressures resulting from separation of lower nappe are beyond the scope of this phase of study and are not included.

SUBJECT CRANFORD LAKE DAM	SHEET 2	BY RFL	DATE 5/5/78	JOB NO
------------------------------	------------	-----------	----------------	--------

SPILLWAY STABILITY ANALYSES - SUMMARY

LOADING CONDITION	SF - OVERTURNING	SF - SLIDING	BEARING PRESSURES
NORMAL POOL	2.05	1.84	17.8 psi 1.4 psi
PMF	1.90	1.73	20.1 psi 4.6 psi
EARTHQUAKE	1.86	1.29	19.8 psi - .6 psi
ICE LOADING	1.35	1.04	27.2 psi - 8.8 psi

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC

Negative bearing pressures indicate tension developed in the upstream face.

7/12/73

.....  
 NATIONAL DAM INSPECTION PROGRAM CRANBERRY LAKE DAM  
 .....  
 SPILLWAY SECTION - NORMAL POOL EL: 1490  
 .....

.....  
 BASE ELEVATION= 1472.00FT. TOP ELEVATION= 1490.00FT. BASE WIDTH= 26.00FT. DENSITY= 144.00PCF  
 HEADWATER ELEVATION= 1490.00FT. TAILWATER ELEVATION= 0.00FT. EARTHQUAKE ACCELERATION= .000G (HORI) .000G (VERT)  
 SILT ELEVATION= 1481.00FT. SILT DENSITY(SURMERGED)= 86.00PCF SILT PRESSURE COEFFICIENT(K)= .33  
 SHEAR STRESS= 100.00PSI SHEAR WIDTH= 26.00FT. FRICTION FACTOR= .50  
 .....

LOADING	FORCE(KIPS)	ARM(FEET)	STABILIZING MOMENT	OVERTURNING MOMENT
HEIGHT OF DAM	36.94	10.01	369.64	
HEADWATER	10.11	5.99		60.59
UPLIFT	14.60	17.33		253.09
SILT	1.16	3.00		3.48
SILT SURCHARGE	3.40	23.00	78.20	
WATER SURCHARGE	10.10	20.00	202.00	
			649.84	117.17

.....  
 NET HORIZONTAL FORCE= 11.27 KIPS  
 NET VERTICAL FORCE= 35.03 KIPS  
 NET MOMENT= 332.72 KIP-FEET  
 X-BAR OF FOUNDATION REACTION= 9.28 FEET  
 ECCENTRICITY OF FOUNDATION REACTION FROM CENTER= 3.72 FEET  
 FOUNDATION REACTION PRESSURES\*\*\*\*\*TOE= 17.78 PSI\*\*\*\*\*HEEL= 1.37 PSI\*\*\*\*\*  
 OVERTURNING FACTOR OF SAFETY= 2.05  
 SLIDING FACTOR OF SAFETY= 1.84  
 DEVELOPED FRICTION FACTOR (NO SHEAR)= .31  
 SLIDING WITH SHEAR FACTOR OF SAFETY= 35.07(SHEAR ACROSS FULL GASE WIDTH)

THIS PAGE IS BEST QUALITY PRACTICABLE  
 FROM COPY FURNISHED TO DDC



\*\*\*\*\*  
 NATIONAL DAM INSPECTION PROGRAM -- CRAWBERRY LAKE DAM  
 SPILLWAY SECTION--FHF  
 \*\*\*\*\*

\*\*\*\*\*  
 BASE ELEVATION= 1472.00FT, TOP ELEVATION= 1490.00FT, BASE WIDTH= 26.00FT, DENSITY= 144.00PCF  
 HEADWATER ELEVATION= 1499.00FT, TAILWATER ELEVATION= 1482.00FT, EARTHQUAKE ACCELERATION= .000G (HOR1Z) .000G (VER1)  
 SILT ELEVATION= 1481.00FT, SILT DENSITY(SUBMERGED)= 86.00PCF, SILT PRESSURE COEFFICIENT(K)= .33  
 SHEAR STRESS= 100.00PSI, SHEAR WIDTH= 26.00FT, FRICTION FACTOR= .58  
 \*\*\*\*\*

LOADING	FORCE(KIPS)	ARM(FEET)	STABILIZING MOMENT	OVERTURNING MOMENT
WEIGHT OF DAM	36.94	10.01	369.68	151.63
HEADWATER	20.22	7.50		
TAILWATER	3.12	3.33	10.39	449.95
UPLIFT	30.01	14.99		3.48
SILT	1.16	3.00	78.20	
SILT SURCHARGE	3.40	23.00	396.87	
WATER SURCHARGE	22.46	17.67	396.87	
			855.14	605.06

\*\*\*\*\*  
 NET HORIZONTAL FORCE= 14.86 KIPS  
 NET VERTICAL FORCE= 29.38 KIPS  
 NET MOMENT= 250.08KIP- FEET  
 X-COR OF FOUNDATION REACTION= 8.51 FEET  
 ECCENTRICITY OF FOUNDATION REACTION FROM CENTER= 4.49 FEET  
 \*\*\*\*\*FOUNDATION REACTION NOT IN CENTRAL THIRD OF BASE\*\*\*\*\*TENSION AT HEEL OF DAM\*\*\*\*\*  
 FOUNDATION REACTION PRESSURES\*\*\*\*\*HEEL= 15.90 PSI\*\*\*\*\*HEEL= -.28 PSI\*\*\*\*\*  
 OVERTURNING FACTOR OF SAFETY= 1.41  
 SLIDING FACTOR OF SAFETY= 1.15  
 DEVELOPED FRICTION FACTOR (NO SHEAR)= .51  
 SLIDING WITH SHEAR FACTOR OF SAFETY= 26.35(SHEAR ACROSS FULL BASE WIDTH)  
 NUMBER OF STATIONS TO DESCRIBE DAM= 4  
 STATION ELEVATION  
 .00 1472.00  
 3.50 1490.00  
 6.00 1490.00  
 26.00 1472.00  
 \*\*\*\*\*

THIS PAGE IS BEST QUALITY PRACTICAL  
 FROM COPY FURNISHED TO DDC

\*STOP\* 0



NATIONAL DAM INSPECTION PROGRAM CRANBERRY LAKE DAM  
 SPILLWAY SECTION - EARTHQUAKE

BASE ELEVATION= 1472.00FT. TOP ELEVATION= 1490.00FT. BASE WIDTH= 26.00FT. DENSITY= 144.00PCF  
 HEADWATER ELEVATION= 1490.00FT. TAILWATER ELEVATION= 0.00FT. EARTHQUAKE ACCELERATION= .100G (HORIZ). .000G (VERT)  
 SILT ELEVATION= 1401.00FT. SILT DENSITY(SUBMERGED)= 86.00PCF SILT PRESSURE COEFFICIENT(K)= .33  
 SHEAR STRESS= 100.00PSI SHEAR WIDTH= 26.00FT. FRICTION FACTOR= .50

LOADING	FORCE(KIPS)	ARM(FEET)	STABILIZING MOMENT	OVERTURNING MOMENT
WEIGHT OF DAM	36.94	10.01	369.68	60.59
HEADWATER UPLIFT	10.11	5.99		251.09
EARTHQUAKE INDUCED LOADINGS	14.60	17.33		
INERTIA-WATER	1.10	7.20		7.93
HORIZONTAL INERTIA-DAM	3.69	6.53		24.11
SILT	1.16	3.00		3.48
SILT SURCHARGE	3.48	23.00	70.20	
WATER SURCHARGE	10.10	20.00	202.00	
			649.88	349.80

NET HORIZONTAL FORCE= 16.06 KIPS  
 NET VERTICAL FORCE= 35.83 KIPS  
 NET MOMENT= 300.60KIP-Feet  
 X-BAR OF FOUNDATION REACTION= 6.39 FEET  
 ECCENTRICITY OF FOUNDATION REACTION FROM CENTER= 4.61 FEET  
 FOUNDATION REACTION PRESSURES NOT IN CENTRAL THIRD OF BASE TENSION AT HEEL OF DAM  
 FOUNDATION REACTION PRESSURES AT TOE= 19.75 PSI AT HEEL= -.61 PSI  
 OVERTURNING FACTOR OF SAFETY= 1.86  
 SLIDING FACTOR OF SAFETY= 1.29  
 DEVELOPED FRICTION FACTOR (NO SHEAR)= .45  
 SLIDING WITH SHEAR FACTOR OF SAFETY= 24.60(SHEAR ACROSS FULL BASE WIDTH)

THIS PAGE IS BEST QUALITY PRACTICE  
 FROM COPY FURNISHED TO DDC

\*\*\*\*\*  
 NATIONAL DAM INSPECTION PROGRAM CRANBERRY LAKE DAM  
 SPILLWAY SECTION - ICE LOADING  
 \*\*\*\*\*

BASE-ELEVATION=1472.00FT. TOP-ELEVATION=1490.00FT. BASE-WIDTH= 26.00FT. DENSITY=144.00PCF  
 HEADWATER ELEVATION=1487.00FT. TAILWATER ELEVATION= 0.00FT. EARTHQUAKE ACCELERATION=0.000G (HORI)0.000G (VERT)  
 SILT ELEVATION= 1481.00FT. SILT DENSITY(SUBMERGED)= 86.00PCF SILT PRESSURE COEFFICIENT(K)= .13  
 SHEAR STRESS= 100.00PSI SHEAR-WIDTH= 26.00FT. FRICTION FACTOR= .50  
 \*\*\*\*\*

LOADING	FORCE(KIPS)	ARM(FEET)	STABILIZING MOMENT	OVERTURNING MOMENT
WEIGHT OF DAM	36.94	10.01	369.64	
HEADWATER	7.02	5.00		35.06
UPLIFT	12.17	17.33		210.91
SILT	1.16	3.00		3.48
SILT SURCHARGE	3.40	23.00	78.20	
WATER SURCHARGE	7.00	21.00	147.00	
ICE LOADING	15.00	16.50		247.50
			*****	*****
			596.88	496.96

\*\*\*\*\*  
 NET HORIZONTAL FORCE= 23.10-KIPS  
 NET VERTICAL FORCE= 35.17 KIPS  
 NET MOMENT= 97.93KIP-FEET  
 X-BAR OF FOUNDATION REACTION= 2.70- FEET  
 ECCENTRICITY OF FOUNDATION REACTION FROM CENTER= 10.22 FEET  
 \*\*\*\*\*FOUNDATION REACTION NOT IN CENTRAL THIRD OF BASE\*\*\*\*\*TENSTON AT HEEL OF DAM\*\*\*\*\*  
 FOUNDATION REACTION PRESSURES\*\*\*\*\*TOE= 31.54 PSI\*\*\*\*\*HEEL= -12.75 PSI\*\*\*\*\*  
 OVERTURNING FACTOR OF SAFETY= 1.20  
 SLIDING FACTOR OF SAFETY= .88  
 DEVELOPED-FRICTION FACTOR (NO-SHEAR)= .66  
 SLIDING WITH SHEAR FACTOR OF SAFETY= 17.03(SHEAR ACROSS FULL BASE WIDTH)  
 \*\*\*\*\*

THIS PAGE IS BEST QUALITY PRACTICAL  
 FROM COPY FURNISHED TO DDO

.....  
 NATIONAL DAM INSPECTION PROGRAM CRANBERRY LAKE DAM  
 SPILLWAY SECTION - ICE LOADING  
 .....

BASE ELEVATION=1472.00FT. TOP ELEVATION=1490.00FT. BASE WIDTH= 26.00FT. DENSITY= 144.00PCF  
 HEADWATER ELEVATION= 1488.00FT. TAILWATER ELEVATION= 0.00FT. EARTHQUAKE ACCELERATION=0.00G (HORIZ),0.00G (VERT)  
 SILT ELEVATION= 1481.00FT. SILT DENSITY(SUBMERGED)= 86.00PCF SILT PRESSURE COEFFICIENT(K)= .33  
 SHEAR STRESS= 100.00PSF SHEAR WIDTH= 26.00FT. FRICTION FACTOR= .58  
 .....

LOADING	FORCE (KIPS)	ARM (FEET)	STABILIZING MOMENT	OVERTURNING MOMENT
WEIGHT OF DAM	36.94	10.01	369.68	
HEADWATER UPLIFT	7.99	5.33		42.56
SILT	12.98	17.33		224.97
WATER SURCHARGE	1.16	3.00		3.48
ICE LOADING	3.40	23.00	78.20	
	7.00	21.00	147.00	
	10.00	17.00		170.00
			594.88	441.01

.....  
 NET HORIZONTAL FORCE= 19.15 KIPS  
 NET VERTICAL FORCE= 34.36 KIPS  
 NET MOMENT= 153.88 KIP-Feet  
 X-BAR OF FOUNDATION REACTION= 6.48 FEET  
 ECCENTRICITY OF FOUNDATION REACTION FROM CENTER= 6.52 FEET  
 FOUNDATION REACTION NOT IN CENTRAL THIRD OF BASE  
 FOUNDATION REACTION PRESSURES AT HEEL OF DAM= 27.22 PSI  
 FOUNDATION REACTION PRESSURES AT TOE= 0.07 PSI  
 OVERTURNING FACTOR OF SAFETY= 1.35  
 SLIDING FACTOR OF SAFETY= 1.04  
 DEVELOPED FRICTION FACTOR (NO SHEAR)= .56  
 SLIDING WITH SHEAR FACTOR OF SAFETY= 20.59 (SHEAR ACROSS FULL BASE WIDTH)  
 .....

THIS PAGE IS BEST QUALITY PRACTICABLE  
 FROM COPY FURNISHED TO DDC