

AD-A063 860


NEW YORK STATE DEPT OF ENVIRONMENTAL CONSERVATION ALBANY F/6 13/2
NATIONAL DAM SAFETY PROGRAM, STILLWATER RESERVOIR DAM (NY00316)--ETC(U)
SEP 78 J J WILLIAMS

DACW51-78-C-0035


NL

UNCLASSIFIED

| OF |
AD
A063860



END
DATE
FILMED
4 - 79
DDC



ADA063860

LEVEL

ST. LAWRENCE RIVER BASIN



BEAVER RIVER. HERKIMER COUNTY

NEW YORK

STILLWATER RESERVOIR DAM

PHASE I INSPECTION REPORT NATIONAL DAM SAFETY PROGRAM

NY 00316



DEPARTMENT OF THE ARMY
NEW YORK DISTRICT, CORPS OF ENGINEERS
26 FEDERAL PLAZA
NEW YORK, NEW YORK 10007
JULY 1978

79 01 25 021

DDC FILE COPY

DISCLAIMER NOTICE

**THIS DOCUMENT IS BEST QUALITY
PRACTICABLE. THE COPY FURNISHED
TO DDC CONTAINED A SIGNIFICANT
NUMBER OF PAGES WHICH DO NOT
REPRODUCE LEGIBLY.**

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

DD FORM 1 JAN 73 1473

EDITION OF 1 NOV 65 IS OBSOLETE

UNCLASSIFIED
SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

ST LAWRENCE RIVER BASIN

Name of Dam: Stillwater Reservoir Dam
County and State: Herkimer County, State of New York
Inventory Number: NY 00316

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

Prepared by: O'Brien and Gere Engineers, Inc.

For: New York State
Department of Environmental Conservation

Date: July 13, 1978

ACCESSION FOR	
NTIS	White Section <input checked="" type="checkbox"/>
CDC	Buff Section <input type="checkbox"/>
UNANNOUNCED <input type="checkbox"/>	
JUSTIFICATION	
BY	
DISTRIBUTION/AVAILABILITY CODES	
BEST	AVAIL. AND OR SPECIAL
A	23

70 01 25 021

PHASE I REPORT
NATIONAL DAM INSPECTION PROGRAM

Name of Dam: Stillwater Reservoir Dam

State Located: New York
County Located: Herkimer County
Stream: Beaver River
Date of Inspection: June 13, 1978

ASSESSMENT OF
GENERAL CONDITIONS


Stillwater Reservoir Dam is constructed across three valleys of various depths. The valleys are closed by two earthen embankments and a concrete spillway and non-overflow section.

No serious structural deficiencies were noted during the visual inspection. Pools of water were located on the downstream slopes of both earthen dams; however, no movement in the pools could be detected. Also, the downstream slopes of both dams and portions of the upstream slope and crest of the north dam were covered with trees and brush. Removal of this vegetation and the maintenance of a controlled vegetation cover are recommended.

Review of the stability analyses indicates that the resultant is located a significant distance outside the middle third of the base width for the normal and PMF loading conditions. The analyses considered a simple gravity structure. However, the structure is arched in plan. Further stability analyses evaluating the dam as an arched/gravity structure are recommended.

The discharge facilities are capable of passing 86 per cent of the PMF without overtopping the earthen non-overflow sections. The concrete non-overflow section is overtopped for floods exceeding approximately 30 per cent of the PMF. The flood crest elevation resulting from the PMF is approximately 1,688; the maximum discharge is about 40,770 cfs.

O'BRIEN & GERE ENGINEERS, INC.


John J. Williams, P.E.
Vice President

Approved by:


Clark H. Benn
Colonel, Corps of Engineers
District Engineer

Date:

21 September 78



CONCRETE SPILLWAY AND GATE HOUSE



SOUTH DAM LOOKING SOUTH

TABLE OF CONTENTS

<u>TEXT</u>	<u>PAGE</u>
Assessment of General Conditions	
Overall View of Dam	
Section 1 - Project Information	1-5
Section 2 - Visual Inspection	6-8
Section 3 - Hydraulic/Hydrologic	9
Section 4 - Structural Stability	10-11
Section 5 - Assessment/Recommendations/Remedial Measures	12-13

FIGURES

- Figure 1 - Regional Vicinity Map
- Figure 2 - Geologic Map
- Figure 3 - Plan and Profile
- Figure 4 - Details of Spillway
- Figure 5 - Details of Logway and Dams
- Figure 6 - Details of Outlet Works
- Figure 7 - Details of Outlet Works
- Figure 8 - Details of Auxiliary Spillway

APPENDIX

Photographs	A-1 - A-4
Field Inspection Report	A-5 - A-15
Hydrologic and Hydraulic Calculations	A-16 - A-35
Stability Analyses	A-36 - A-41

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
NAME OF DAM STILLWATER RESERVOIR DAM ID# NY 00316

SECTION I - PROJECT INFORMATION

1.1 GENERAL

a. Authority - This report is authorized by the Dam Inspection Act, Public Law 92-367, and has been prepared in accordance with contract #1467-021 between O'Brien and Gere Engineers, Inc. and the New York State Department of Environmental Conservation.

b. Purpose of Inspection - The purpose of this inspection is to evaluate the structural and hydraulic condition of Stillwater Reservoir Dam and appurtenant structures, and to determine if the dam constitutes a hazard to human life or property.

1.2 PROJECT DESCRIPTION (From drawings and information provided by NYSDEC and HR-BRRD)

a. General - Stillwater Reservoir Dam is located on the Beaver River in Herkimer County, New York, about $3\frac{1}{2}$ miles upstream of Moshier Dam and 24 miles east of the community of Lowville, New York. The dam is owned and operated by the State of New York, Hudson River-Black River Regulating District (HR-BRRD) and is used to regulate river flows for flood control and downstream power development. The dam was initially constructed around 1885; it was enlarged and raised to its present elevation in 1924.

The dam complex is constructed across three valleys or ravines of various depths.

The north valley is closed by an earth embankment (north dam) which is connected to a concrete gravity spillway and non-overflow section constructed across the center valley. A rock outcrop separates the concrete non-overflow section from the earth embankment (south dam) constructed across the south valley.

Normal discharges are released through four openings located in the non-overflow section upon which the gatehouse is constructed. Discharges through the openings are controlled with manually operated sluice gates.

Uncontrolled flood discharges pass over the concrete gravity spillway located in the center valley and an emergency spillway and channel constructed in the rock abutment about 1,000 feet south of the south dam. Both spillway crest elevations are raised by wood flashboards which are manually positioned and removed.

A sluiceway used to remove floating debris from the reservoir is located on the north end of the concrete spillway adjacent to the north dam.

b. Size and Hazard Classification - According to information provided by the New York State Department of Environmental Conservation (NYSDEC), the maximum height of the dam is about 55 feet (at the north dam) and the volume of the reservoir to the spillway crest is approximately 103,000 acre-feet. In accordance with the Recommended Guidelines for Safety Inspection of Dams, the dam is in the large size category.

Stillwater Reservoir Dam is located about $3\frac{1}{2}$ miles upstream of Moshier Dam, a power generating site for Niagra Mohawk Power Corporation. Some residential development is located downstream of Moshier Dam. Loss of life and damage to property could be expected if Stillwater Reservoir Dam were to fail. Therefore, the dam is in the high hazard category as defined by the Recommended Guidelines for Safety Inspection of Dams.

Accordingly, the spillway design flood required for hydraulic analysis is the Probable Maximum Flood (PMF).

1.3 PERTINENT DATA (from drawings and information provided by NYSDEC and HR-BRRD)

a. Drainage Area - The total drainage area contributing to Stillwater Reservoir is about 178 square miles. The majority of the drainage area is covered by mountain forest underlain predominantly by glacial granular deposits and bedrock.

b. Discharges at Damsite - The average annual discharge is 372 cfs. Discharges are varied daily based on recorded rainfall measurements and downstream water demand. The State of New York requires a minimum daily discharge of 50 cfs for river flow augmentation.

c. Elevation (feet above MSL)

Top of earth dam embankments (north and south dam) -
1687.3
Spillway crest (flashboards in place) - 1679.3
Spillway crest (flashboards removed) - 1677.3
Sluiceway Crest - 1674.3 (stoplogs removed)

d. Reservoir Data

Storage at spillway crest (el. 1679.3) - 103,300 ac.ft.
Surface area at spillway crest (el. 1679.3) - 10.5 sq.miles

e. Dam Data

Concrete Gravity Section

Type - concrete gravity/arch
Length - 320+ feet
Height - 40+ feet (non-overflow section)
Top Width - 8 feet at spillway section
Top width - 9½ feet at gatehouse section
Slopes - upstream - vertical, downstream - 2 vertical to 1 horizontal

Earth Embankments

South Dam

Type - earth embankment
Maximum Height - 22+ feet
Length - 300+ feet
Top width - 15+ feet
Side Slopes - 1 vertical to 2 horizontal (upstream and downstream)
Impervious Core - selected material
Cutoff - Selected material placed to a depth as ordered by the Engineer.

North Dam

Type - earth embankment
Maximum Height - 55+ feet
Length - 600+ feet
Top width - 15+ feet
Side Slopes - 1 vertical to 2 horizontal (downstream) - 1 vertical to 2½ horizontal (upstream)
Imperious Core - concrete core to elevation 1683.3
Cutoff - No information was made available.

f. Outlet Data

Non-overflow section (four gated opening)

1 - 5' x 2' opening, fitted with 2 - 2' x 2' sluice gates with a 12" separator.

1 - 3' x 3' opening, fitted with a 3' x 3' sluice gate.

1 - 4' x 5' opening, fitted with a 4' x 4' sluice gate

1 - 4' x 5' opening, fitted with a 4' x 3'10" sluice gate

A 5' x 4' stoplog assembly is available for placement in any one of the four water passages.

Sluiceway

Length - 10 feet

Gates - wooden stoplogs

Crest Elevation - 1674.3

Top Elevation - 1683.3 ±

g. Spillway Data

Spillway located in concrete gravity section

Type - concrete weir

Length - 245+ feet

Gates - flashboards

Crest Elevation - flashboards in place - 1679.3, flashboards removed - 1677.3

Downstream Channel - the downstream channel is formed in natural massive rock outcrops

Emergency spillway located about 1,000 feet south of South Dam

Type - concrete weir

Length - 200+ feet

Gates - flashboards

Crest Elevation - flashboards in place - 1679.3, flashboards removed - 1677.3

Downstream Channel - the downstream channel converges and flashboard leakage and low flows are discharged into three 21 inch diameter culverts constructed under a service road. The emergency spillway channel outlet to the river below the south dam is through a natural swamp area.

h. Flood Elevations at the Dam (Local Datum) - The flood elevation was computed for the Probable Maximum Flood with the flashboards in place (crest elevation 1679.3)

PMF Elevation (MSL - feet) - 1685.0

i. Engineering Data - The engineering data made available by NYSDEC for review of Stillwater Reservoir Dam included:

-Set of construction plans (9 sheets) for Stillwater Reservoir, dated September 22, 1923.

-Copy of "Dam Report" published by the State of New York Conservation Commission, dated August 29, 1917.

-Copy of "Application for the Construction or Reconstruction of a Dam", dated November 26, 1924.

-Copy of Dam Report from the Blackwater Regulating District, dated September 2, 1924.

-Copy of Dam Inspection Report, dated September 1, 1971.

1.4 OPERATING AND MAINTENANCE PROCEDURES

a. Operation - The dam is used to regulate river flows for flood control and downstream power development. Normal discharges are varied daily based on recorded rainfall and power generating requirements. New York State requires a minimum release of 50 cfs for river flow augmentation.

b. Maintenance of the Dam and Operating Facilities - Maintenance of the dam and operating facilities is performed on an "as required" basis. According to operating personnel, the dam is visually inspected on a daily basis.

c. Flood Warning System - A flood warning system operated through the facilities of local Civil Defense Offices is in effect.

SECTION 2 - VISUAL INSPECTION

2.1 FINDINGS

a. General - The field inspection for Stillwater Reservoir Dam was conducted on June 13, 1978. The temperature was about 50°F with overcast skies and light intermittent showers. The water surface elevation at the time of inspection was about one foot below the top of the flashboards (approximately el. 1678.3). No underwater areas were inspected.

b. South Dam - The south dam is an earthen embankment about 300 feet long, tied into massive rock outcrops at both abutments.

The downstream slope of the embankment is covered with a relatively dense growth of trees and brush for its entire length. Some riprap was noted interspaced along the slope. Pools of water were observed at three locations at the toe of the downstream slope, however, no movement which would indicate flow was detected in any of the pools. The upstream slope of the embankment is surfaced with riprap consisting of semi-angular granitic type rock weighing from about 75 to 300 pounds each. The riprap protection extends about six feet above the present water level. Vegetation along this slope is limited to a few small trees and brush. The embankment appears to be straight and no noticeable indications of settlement or erosion were noted.

The crest of the spillway located south of the South Dam appears to be in good condition. No significant indications of structural deterioration are apparent.

The downstream channel converges in plan and is covered with native grasses and vegetation. The area adjacent to either side of the spillway channel is well forested with large trees.

c. Concrete Gravity Dam - The concrete gravity dam is located between two massive rock outcrops and is curved upstream in plan. A gatehouse and spillway are constructed along its length.

Five manually controlled gate operators are located in the gatehouse. The gates are positioned by hoists which are operated from a common electric motor driven power shaft with individual clutches.

A steel stoplog assembly which can be placed in any of the four discharge openings is stored in the gatehouse. All equipment appears to be in good condition. According to the gatehouse superintendent, all the hoists are operable.

A reservoir stage recorder established by the United States Geological Survey (USGS) is also located in the gatehouse.

The downstream face of the non-overflow section shows signs of deterioration. A protective surface treatment (gunite) which was applied to the structure has weathered and cracked. Some spalling of the gunite was noted in the downstream slope of the non-overflow section.

The spillway is about 250 feet long. At time of the inspection, the flashboards were in place. They are individually secured by pins placed at intervals along the crest. Some minor leakage through the flashboards was observed during the inspection.

The concrete along the crest appears to be in good condition. A small crack in the surface, running parallel to the crest was located about 75 feet from the gatehouse. It is apparently superficial, no relative movement could be detected. The construction joints on the upstream side are open. No deterioration was observed in the joints. The joints on the downstream side are well maintained and have been filled with a sealer material.

The crest alignment appears to be excellent. No indication of horizontal or vertical movement was noticeable.

The downstream face of the spillway has also been surfaced with a protective material. A much more significant deterioration of the material than observed on the non-overflow section was evident. In areas where the material had dislodged from the structure, spalled concrete was again noted. No seepage was observed in the toe area of the gravity section.

The channel below the gatehouse and spillway is formed in natural massive rock outcrops. No erosion of the rock was observed.

A log sluiceway fitted with a stoplog assembly is constructed on the north side of the spillway. The stoplog assembly was in place during the inspection, no leakage was noted.

c. North Dam - The north dam is an earthen embankment extending about 600 feet from the concrete gravity dam to the north abutment.

The upstream slope is protected with a blanket of dumped granitic type riprap, ranging in nominal sizes from 4 inches to 24 inches. A significant growth of small sapling trees and brush are located along the crest and upstream slope. No significant settlement or erosion were observed along crest. Two capped galvanized metal pipes about two inches in diameter were located in the center of the crest. Operating personnel indicated no knowledge of these pipes or their function.

The downstream slope is well covered with a dense growth of large trees (diameter range in size from 3 inches to 12 inches) and brush. A small pool of water was located just downstream of the right abutment. The water was clear and no movement which might indicate flow was detected.

Backwater from the Beaver River was observed at the toe of the north dam. The embankment in this area is protected with a blanket of riprap.

d. The reservoir is bordered by property owned by the State of New York and is uninhabited. No indication of slope failure or bank erosion was noted in the areas observed.

e. The downstream channel appears to be formed in natural massive rock outcrops. The adjacent banks are heavily wooded and uninhabited. Moshier Dam is located about $3\frac{1}{2}$ miles downstream; the reservoir formed at Moshier Dam extends almost to Stillwater Reservoir Dam.

SECTION 3 - HYDROLOGY AND HYDRAULICS

In accordance with the criteria presented in the Recommended Guidelines for Safety Inspection of Dams, the spillway design flood required for evaluation of the hydraulic capabilities of Stillwater Reservoir Dam is the Probable Maximum Flood (PMF).

The PMF was calculated from probable maximum precipitation data published in Hydrometeorological Report No. 33. Rainfall data was modified to account for basin size, storm patterns and duration. The HEC-I computer program was used to develop the inflow hydrograph and flood route the PMF through the reservoir facility. Peak inflow and outflow rates for the PMF were calculated as 90,400 cfs and 40,800 cfs respectively. The spillway capacity was computed to be approximately 33,200 cfs. Peak inflow and outflow rates for one-half of the PMF were calculated as 45,200 cfs and 17,400 cfs respectively. The spillway is capable of discharging an inflow of 86 per cent of the PMF without overtopping. According to ETL 1110-2-234, the spillway is inadequate, but not "seriously inadequate."

A drawdown analysis was performed to estimate the time required to drain the reservoir. The four gated openings were used for the reservoir drain and inflow was assumed to be negligible. Under these conditions, approximately 45 days would be required to drain the reservoir. This represents a minimum time with no consideration given to safe discharge velocities or flows.

SECTION 4 - STRUCTURAL STABILITY

4.1 EVALUATION OF STRUCTURAL STABILITY

a. Visual Observation - No significant indications of structural deficiencies were noted during the inspection of the south dam, concrete gravity dam or north dam.

b. Design, Reports and Construction Data - Drawings and data relative to Stillwater Reservoir Dam were provided by the New York State, Department of Environmental Conservation and the Hudson River - Black River Regulating District.

c. Operating Records - According to records published by the United States Department of the Interior, Geological Survey, the maximum water elevation recorded at Stillwater Reservoir Dam is 1680.08 on May 20, 1969. The period of record is from 1908 through the current year. According to operating personnel, ice does not form at the concrete gravity section due to the influence of relatively warmer water rising from the reservoir bottom.

d. Post Construction Changes - Data pertaining to the construction of the original dam was not made available. Construction drawing and reports indicate that the dam was raised to its present elevation in 1924.

A dam inspection report published in 1971 states that a gunite cap was placed on the concrete gravity dam in 1969.

e. Seismic Stability - According to the Geologic Map of New York (Adirondack Sheet) dated 1970, Stillwater Reservoir Dam is founded on granitic-gneiss type rock. Massive rock outcrops were observed in both abutments of the concrete gravity dam and the south dam. The rock outcrops appear to be coarse grained in texture and display random fracturing patterns.

The geological map indicates a lineament, implying a faulted structure, paralleling the longitudinal axis of the reservoir terminating upstream of the dam. However, no evidence of seismic related stress was noted during the inspection of the dam.

Stillwater Reservoir Dam is located in seismic zone 3 as shown on the Seismic Zone Map of Contiguous States. Accordingly, a stability analysis was conducted using the coefficient associated with zone 3 as presented in the Recommended Guidelines for Safety Inspection of Dams.

Factual data pertaining to foundation investigations are not available. Therefore, design assumptions concerning foundation rock characteristics were based on information obtained from general geologic maps and field observations made during the course of the inspection.

f. Evaluation - The analyses of the structural stability of the concrete gravity spillway considered three loading conditions. The results of these loading conditions are summarized in the appendix.

A review of the results indicates that the resultant is located a significant distance outside of the middle third of the base for the normal and PMF loading conditions; the resultant of the seismic loading falls within the limits of the base width.

SECTION 5 - ASSESSMENT/RECOMMENDATIONS/REMEDIAL MEASURES

5.1 ASSESSMENT

A review of the stability analysis indicates that the spillway is structurally unstable relative to resultant location for normal and PMF loading conditions. However, in the analyses, the spillway was evaluated as a simple gravity structure; no consideration was given to the curvature of the spillway which could significantly improve the stability of the structure.

The north and south dams appear to be stable. The crests show no significant deviations in alignment; no signs of slope instability or erosion were noted.

Pools of standing water were located on the downstream slopes of both embankments, however, no discoloration or movement which might indicate flow could be detected in the pools. The pools may have resulted from surface runoff due to intermittent showeres which occurred before and during the inspection.

The slopes of both dams and the crest of the north dam support an uncontrolled growth of trees and brush. No maintenance program for removal was evident.

The concrete surface protection has cracked and spalled in several places on the downstream face of the gravity structure. However, this condition does not appear to adversely affect the stability of the structure.

A review of the flood routing performed indicates that the discharge facilities are hydraulically capable of passing the PMF without overtopping the earthen dam embankments. The concrete non-overflow section is overtopped for all floods exceeding approximately the $\frac{1}{2}$ PMF.

5.2 RECOMMENDATIONS/REMEDIAL MEASURES

Additional investigation, remedial measures and recommended actions are as follows:


1. Perform further stability analyses to evaluate the curvature effect of the concrete gravity structure.

2. Remove trees and brush from the slopes and crests of the earth dams and maintain a controlled vegetation. This maintenance program should also pertain to the spillway located to the south of the south dam.

3. Remove and replace the deteriorated concrete surface protection material as required.

FIGURES






LEGEND

- [Dotted Pattern] hbgs - BLACK MICA AND/OR GRANITE
- [Horizontal Line Pattern] mu - FRAGMENTED METAMORPHIC ROCK
- [Vertical Line Pattern] mug - FRAGMENTED GRANITE GNEISS
- [White Space] phgs - GRANITIC GNEISS
- [Diagonal Line Pattern] phqs - GRANULAR QUARTZ GNEISS

SOURCE: GEOLOGIC MAP OF NEW YORK
ADIRONDACK SHEET 1970

FIGURE 2
GEOLOGIC MAP

35c







FIGURE 3
STATE OF NEW YORK
BLACK RIVER REGULATING DISTRICT
STILLWATER RESERVOIR
PLAN AND PROFILE OF DAM SITE

H
58





Notes -
The bases of the structures shown on any of the plans of this contract shall be considered as approximate only and, if ordered in writing by the Engineer shall be of such elevation and of such dimensions as shall be necessary to provide a proper foundation.

If ordered in writing by the Engineer, one section of the spillway, 40 feet long, to be designated by the Engineer, shall be left at elev 1657.3 until all other work has been completed, and permission to complete the spillway has been given by the Engineer.

SECTION A-A

SCALE-FEET

0 5 10 15



FLASHBOARDS

SCALE-FEET

0 1 2 3 4

Design by *Morgan Johnson*
Asst. Engineer.
Approved by *C. J. Morgan*
Chief Engineer.

KEYWAY

SCALE-INCHES


0 6 12

Approved

SHEET 4

Notes -
The base of the structures shown on any of the plans of this contract shall be considered as approximate only and if ordered in writing by the Engineer shall be at such elevation and of such dimensions as shall be necessary to provide a proper foundation.


If ordered in writing by the Engineer, one section of the spillway, 40 feet long, to be designated by the Engineer, shall be left at elev 1657.3 until all other work has been completed, and permission to complete the spillway has been given by the Engineer.



KEYWAYS AT JOINTS

SCALE- FEET

0 5 10 15



KEYWAY

SCALE- INCHES

0 6 12

*Approved
Historical
Engineering
Department
1968*

FIGURE 4


STATE OF NEW YORK
BLACK RIVER REGULATING DISTRICT
STILLWATER RESERVOIR
DETAILS OF SPILLWAY
SCALES INDICATED
SEPTEMBER 22, 1968

ACM-340

2

4



SR



SECTION-NORTH DAM

STA. 10+50

SCALE-FEET




SECTION C-C - LOGWAY

SCALE-FEET



SECTION D-D LOGWAY


SCALE-FEET



SECTION - SOUTH DAM

STA. 2+50

SCALE-FEET




Design by W.H. Johnson
C.E. Engineer
Approved by C. E. Johnson
Ch. of Engineer.

Notes:-
The bases of the shown or any of
of this contract
considered as as
only and if order
by the Engineer, s
such elevation or
dimensions as as
necessary to pro
proper foundati

The north end of
shall be extended
to such distance
deemed necessary
Engineer to give
security

Approved

C




SECTION-NORTH DAM

ST4 10+50

SCALE-FOOT


0 5 10 20 30



SECTION D-D LOGWAY

SCALE-FEET

0 5 10 15



6' 0"

1679.87

T-1


5.5% Across
1620.3

1677.3

ELEVATION LOGWAY BULKHEAD

SCALE-FEET

0 5 10 15



285

The bases of the structures shown or any of the plans of this contract shall be considered as approximate only and, if ordered in writing by the Engineer, shall be at such elevation and of such dimensions as shall be necessary to provide a proper foundation.


The north end of the corewall
shall be extended into the bank
to such distance as may be
deemed necessary by the
Engineer to give proper
security.

Approach
of
the
Golds
-
geeked
-
-


FIGURE 5
STATE OF NEW YORK
BLACK RIVER REGULATING DISTRICT
STILLWATER RESERVOIR
DETAILS OF LOGWAY AND DAMS

SCALES INDICATED
SEPTEMBER 22, 1943.

ANNUAL



SHEET 7





GAGE WELL LADDER

SECTION F-F

SCALE- FEET


0 1 2 3 4 5



SECTIONS-C.J. SPACERS


SCALE-INCHES

0 1 2 3 4 5



PLAN-RACKS

+ sections like above required.



SECTION-RACKS

SCALE- FEET

0 1 2 3 4

FIGURE 6

STATE OF NEW YORK

BLACK RIVER REGULATING DISTRICT

STILLWATER RESERVOIR

DETAILS OF OUTLET WORKS



SCALES INDICATED

SEPTEMBER 22, 1963.

REC M-343


Approved
Historian
Jackie T.
TDR

2



SECTION G-G


SCALE- FEET





WALL PLAN - GATE HOUSE

Design by H. J. Johnson
Approved by A. C. Williams
Approved by Chief Engineer

Approved by W. L. Johnson
Approved by A. C. Williams
Approved by Chief Engineer



Walter C. Barnes
Architect
T. G. T. -



PROFILE
(Looking downstream)

Note:-
The bases of the structures shown on any of the plans of this contract shall be considered as approximate only and, if ordered in writing by the Engineer, shall be at such elevation and of such dimensions as shall be necessary to provide a proper foundation.

Design by H. C. Johnson
Asst. Engineer
Approved by C. H. Wallace
Chief Engineer

4100000 Walter Brown
Architect
Architect
T.D.A.

SHEET 9






FIGURE 8
STATE OF NEW YORK
BLACK RIVET REGULATING DISTRICT
STILLWATER RESERVOIR
DETAILS OF AUXILIARY SPILLWAY
SCALES INDICATED
SEPTEMBER 26, 1963

41-00000
Walter Soren
President
J. C. Bell
T. D. M.

Acc No. 343

APPENDIX


PHOTOGRAPHS

32.


A-1




VIEW OF CONCRETE SPILLWAY AND ROCK OUTCROP



DOWNSTREAM CHANNEL



DOWNSTREAM SLOPE OF SPILLWAY



DOWNSTREAM FACE OF GATE HOUSE



NORTH DAM (UPSTREAM SLOPE) LOOKING NORTH



CREST OF NORTH DAM LOOKING SOUTH

FIELD INSPECTION REPORT

Check List
Visual Inspection
Phase 1

Name Dam Stillwater Reservoir Dam County Oneida State New York Coordinators Mr. Lee Crostman

Date(s) Inspection June 13, 1978 Weather Showers Intermittant Temperature 50°

Pool Elevation at Time of Inspection 1678.3 M.S.L.

Tailwater at Time of Inspection N/A M.S.L.

Inspection Personnel:

A-6 Mr. J. J. Williams Mr. J. V. Ryan
Mr. A. J. Depman
Mr. R. E. Horvath Mr. R. E. Horvath Recorder

Accompanied by: Mr. Lee Crostman, Superintendent, Stillwater Reservoir Dam, Hudson River - Black River Regulating District.

CONCRETE/MASONRY DAMS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SEEPAGE OR LEAKAGE		
STRUCTURE TO ABUTMENT/ENTRANCE JUNCTIONS	No settlement or seepage was noted at the abutment junctions.	
DRAINS	A-7	No drains were noted. Operating personnel could provide no information relative to drains.
WATER PASSAGES		Water passages could not be inspected because of discharge.
FOUNDATION		Not observed.

CONCRETE/MASONRY DAMS

VISUAL EXAMINATION OF SURFACE CRACKS CONCRETE SURFACES	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
	A small crack was located in the spillway crest, about 75 feet from the gatehouse. The crack appeared to be superficial. A concrete surface protection which has been applied to the concrete has cracked and separated from the structure in several places.	
STRUCTURAL CRACKING	None noted.	
VERTICAL AND HORIZONTAL ALIGNMENT A-8	Vertical and horizontal alignment appear to be good. No noticeable deviations were observed.	
MONOLITH JOINTS	N/A	
CONSTRUCTION JOINTS	No relative movement was observed at the joints. The joints on the upstream face of the spillway are open. No deterioration was noted.	

EMBANKMENT

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS	No surface cracks were noted in either of the earth dam embankments.	
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	None noted.	
SLoughing or Erosion of Embankment and Abutment Slopes	None noted. A-9	
Vertical and Horizontal Alignment of the Crest	No significant deviation in crest alignment was noted in either earth dam.	
RIPRAP FAILURES	None noted.	

EMBANKMENT

**VISUAL EXAMINATION OF
EMBANKMENT**

OBSERVATIONS

REMARKS OR RECOMMENDATIONS

**JUNCTION OF EMBANKMENT
AND ABUTMENT, SPILLWAY
AND DAM**

No settlement was noted at the junctions
of the embankments and abutments.

ANY NOTICEABLE SEEPAGE

A-10

Pools of water were observed at about five
locations on the downstream slopes of the
earth dams. The source of the pools could
not be determined. The water was clear and
no movement was detected.

STAFF GAGE AND RECORDER

A reservoir stage recorder is located in the
gatehouse.

DRAINS

None noted.

OUTLET WORKS	OBSERVATIONS	REMARKS OR RECOMIE.
VISUAL EXAMINATION OF CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	Not observed.	
INTAKE STRUCTURE	Not observed.	
OUTLET STRUCTURE A-11	The protective surface treatment applied to the non-overflow section below the gatehouse is cracked over most of the downstream face.	
OUTLET CHANNEL	The outlet channel is formed in massive natural rock outcrops. No erosion was noted.	
EMERGENCY GATE	An emergency stoplog assembly is located in the gatehouse and can be placed in any of the gatehouse openings. The stoplog assembly appears to be in good condition.	

GATED SPILLWAY		REMARKS OR RECOMMENDATIONS
VISUAL EXAMINATION OF	OBSERVATIONS	
CONCRETE SILL	The concrete sill appears to be in good condition. A small crack about 75 feet from the gatehouse was noted. However, it does not appear to be structurally significant.	
APPROACH CHANNEL	Not observed.	
DISCHARGE CHANNEL	A-12	
BRIDGE AND PIERS	The bridge and supports located along spillway appear to be in good condition. Some minor corrosion was noted on the metalwork.	
GATES AND OPERATION EQUIPMENT	Flashboards are positioned along the spillway crest. They are secured by pins which extend above the concrete crest. Each flashboard is placed and removed manually. Minor leakage was noted occurring in some of the flashboard assemblies.	

	INSTRUMENTATION	REMARKS OR RECOMMENDATIONS
VISUAL EXAMINATION	OBSERVATIONS	
MONUMENTATION/SURVEYS	None Noted.	
OBSERVATION WELLS	Capped pipes (2), in the vertical position, were located along the crest of the north dam. Their function was unknown to operating personnel.	
WEIRS	A-13	
PIEZONETERS	None Noted.	
OTIER	N/A	

RESERVOIR	VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SLOPES		No indications of slope instability were noted in the areas observed.	
SEDIMENTATION		The degree of sedimentation could not be determined.	

A-14

DOWNSTREAM CHANNEL

REMARKS OR RECOMMENDATIONS

VISUAL EXAMINATION OF

OBSERVATIONS

CONDITION
(OBSTRUCTIONS,
DEBRIS, ETC.)

None Noted.

SLOPES

APPROXIMATE NO.
OF HOMES AND
POPULATION

A-15

No homes are located immediately below Stillwater Reservoir Dam. However, Moshier Dam, a power generating site operated by Niagara Mohawk Power Corporation is about $3\frac{1}{2}$ miles downstream.

HYDROLOGIC AND HYDRAULIC CALCULATIONS

JUSTIN & COURTNEY, INC.
Division of O'Brien & Gere Engineers, Inc.
PHILADELPHIA, PA

NAME OF CLIENT CORPS OF ENGINEERS

SHEET NO. 1 OF _____

DATE 5/31/78

COMP. BY DEC

PROJECT STILLWATER RESERVOIR

CHECKED BY REH

DRAINAGE AREA (BY PLANIIMETER) = 154 SQ. MILES.
DATA SHEETS = 178 SQ MILES ← USE

$$L = 28 \text{ MILES} \quad L_{CA} = 10 \text{ MILES}$$

INCORPORATE SNYDER COEFFICIENTS

$$C_f = .625 \quad C_d = 2.0$$

$$t_p = C_d (L \times L_{CA})^3 = 2.0 (28 \times 10)^3 = 10.8 \text{ HRS.}$$

$$t_p = t_p / 5.5 = 2.0 \text{ HRS}$$

$$6 \text{ HR PMP} = 21"$$

REDUCTION DUE TO PROBABLE MISFIT OF BASIN
WITH STORM HYDROGRAPHS IS 11.5%

$$6 \text{ HR PMP} = 18.6"$$

DEPTH - AREA - DURATION FOR PMP

$$6 \text{ HR. PMP} = 18.6" \times .7 = 13.1"$$

$$12 \text{ HR. PMP} = 18.6" \times .83 = 15.5" \quad 15.5" - 13.1" = 2.4"$$

A-17

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC

JUSTIN & COURTNEY, INC.
Division of O'Brien & Gere Engineers, Inc.
PHILADELPHIA, PA

SHEET NO. 2 OF _____
DATE 5/31/78
COMP. BY DGC
CHECKED BY REH

NAME OF CLIENT CORPS OF ENGINEERS
PROJECT STILLWATER RESERVOIR

PMP DISTRIBUTION

<u>TIME(HRS)</u>	<u>RAINFALL</u>
0-2	8.5" (65% 6HR. PMP)
2-4	2.6" (20% 6HR. PMP)
4-6	2.0" (15% 6HR. PMP)
6-8	.8")
8-10	.8" } 12 HR. PMP - 6 HR. PMP
10-12	.8")

THIRD QUARTILE DISTRIBUTION

<u>TIME(HRS)</u>	<u>RAINFALL</u>
0-2	.8"
2-4	.8"
4-6	2.0"
6-8	8.5"
8-10	2.6"
10-12	.8"

SUBJECT	SHEET	BY	DATE	JOB NO
STILLWATER RESERVOIR DAM	4	REH	6/6/78	333.023

Checked. SLC

STAGE - DISCHARGE

DISCHARGE - 4 GATES

Gate 1 5' x 4' INV @ 1641.8 r=1.11

Gate 2 5' x 4' INV @ 1641.8 r=1.11

Gate 3 3' x 3' INV @ 1642.8 r=.75

Gate 4 5' x 2' INV @ 1643.3 r=.71

Length of water passage through dam

$$= 14' + \frac{1}{2} (1674.3 - 1641.8)$$

$$= 14' + 16.25' = 30.25'$$

For Discharge through gates. Assume

a) pressure flat

b) tailwater at top elev of discharge conduit

c) common invert at elev 1641.8

d) common hydraulic radius = 9

e) $n = .015$

f) $L = 30'$

g) $K_C = 1.0$

h) Area = 50^{th} (total of four gates)

SUBJECT	SHEET	BY	DATE	JOB NO
STILLWATER Reservoir Dam	E	P.E.	6/6/72	

Checked DSC

$$H = \left(1 + K_c + \frac{29 n^2 L}{r^{1/3}} \right) \frac{V^2}{2g}$$

Assume $H = EL - 1646.8$

$$H = (1 + 1 + .22) \frac{V^2}{2g}$$

$$H = 2.22 \frac{V^2}{2g}$$

$$V = \sqrt{2gH} \quad Q = AV = 59V$$

- Assume leeway closed

- Spillway Discharges $Q = CLH^{3/2}$

Assume C for 245' spillway = 3.5

Assume C for 200' spillway = 2.6

$$Q = (3.5 \times 245' + 2.6 \times 200') H^{3/2} = 1377.5 H^{3/2}$$

$$\text{use } Q = 1378 H^{3/2}$$

- Discharge - overtopping (crest elevation = 1687.3)

Length ≈ 1000 feet

Assume $C=3$

$$\therefore Q = 3(1000) H^{3/2} = 3000 H^{3/2}$$

* Assume non-overflow section of gravity dam to be ineffective for flow area.



OBJECT	SHEET	BY	DATE	JOB NO
STILLWATER RESERVOIR DATA	6	REH	6/16/78	

Elev - Discharge (cfs)

Elev	Q _{gates}	Q _{gates+spill}	Q _{overtopping}	Q _{total}
1679.3	0	0	0	0
1681.3	1864	3826	0	5760
1683.3	1918	11020	0	12938
1685.3	1971	20245	0	22216
1687.3	2024	31169	0	33193
1689.3	2071	43560	8485	54114
1691.3	2118	57261	24000	83360

* Assume gates are opened at the beginning of PMF

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC

JUSTIN & COURTNEY, INC.
Division of O'Brien & Gere Engineers, Inc.
PHILADELPHIA, PA

SHEET NO. 6A OF _____

DATE 6/16/78

COMP. BY RFH


CHECKED BY _____

NAME OF CLIENT NYSEG

PROJECT STILLWATER RESERVOIR DIA

**THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC**

STAGE - DISCHARGE



SUBJECT	SHEET	BY	DATE	JOB NO
STILLWATER RESERVOIR DATA	7	R.E.H.	6/19/79	

Checked DBC

STAGE - STORAGE

Surface area @ Spillway Crest = 6720 Ac (Elev 1679.3)

Surface area @ Elev 1700 = 12698 Ac

Assume area varies linearly with stage

$$\therefore 5977.6 / 20.7 = 288.8 \text{ Ac/ ft}$$

$$A = 288.8 d + 6720 \quad d = 0 \text{ to } 1679.3$$

$$S = 144.4 d^2 + 6720d \text{ (above Spillway Crest)}$$

From	To	St	Inc St. (Ac.F.)	Accum Stg (Ac.F.)	(Ac.F.)	Accum Storage
	1658		1386.6	13,866		
	1660		4982	18,848		
	1665		16001	34,849		
	1670		20959	55,808		
	1675		25826	81,634		
	1680		31222	112,856		0 to 1679.3
	1681.3	7298		122,502		14018
	1683.3	7875		137,675		25190
	1685.3	8453		154,002		45518
	1687.3	9030		171,487		63002
	1689.3	9608		190,125		81640
	1691.3	10186		209,919		101434

JUSTIN & COURTNEY, INC.
Division of O'Brien & Gere Engineers, Inc.
PHILADELPHIA, PA

SHEET NO. 24 OF _____

DATE 6/19/78

COMP. BY JFH


CHECKED BY DBC

NAME OF CLIENT NYSDEC

PROJECT STILLWATER RESERVOIR

**THIS PAGE IS BEST QUALITY PRACTICABLE
 FROM COPY FURNISHED TO DDC**

Storage - Storage



JUSTIN & COURTNEY, INC.
Division of O'Brien & Gere Engineers, Inc.
PHILADELPHIA, PA

NAME OF CLIENT NYSDEC

PROJECT Stillwater Reservoir Dam


SHEET NO. _____ OF _____

DATE 8/28/78

COMP. BY DBC

CHECKED BY REH

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC



SUBJECT	SHEET	BY	DATE	JOB NO
SPILLWATER INVENTORY DATA	8	REL	7/10/78	

Checked DBC

DRAINAGE ANALYSIS

Assumptions

- water surface at spillway crest
- gates fully open
- inflow = 0

Elev	Head (ft)	Vel (f.p.s)	Q acc
1679.3	32.5	30.7	1811
1674.3	27.5	28.2	1664
1669.3	22.5	25.5	1505
1664.3	17.5	22.5	1323
1659.3	12.5	19.0	1121
1654.3	7.5	14.7	867
1649.3	2.5	8.5	502
1641.8	0	0	0

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC

SUBJECT		SHEET	BY	DATE	JOB NO
STILLWATER REACH IN T-411		5	FBI	7/10/73	

Checked DBC
(cfs)

Elev	Elev	Span (ft)	Avg Discharge (cfs)	Time (hrs)
1678.3	1674.3	1307×10^6	1738	208
1674.3	1669.3	958×10^6	1585	168
1669.3	1664.3	828×10^6	1417	162
1664.3	1659.3	784×10^6	1225	178
1659.3	1654.3	348×10^6	994	97
1654.3	1649.3	174×10^6	685	70
1649.3	1641.8	174×10^6	251	122

or 45 days

Calculations result in a minimum drawdown time of about 45 days. No consideration was given to downstream constraints such as safe discharge velocities and/or flows.

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC

NEC-1 VERSION DATED JAN 1973
UPDATED AUG 74
CHANGE NO. 01

PMF POLLUTING-COEFFS FL 1579.3

STILLWATER RESERVOIR NAME

GARRISON + GENE - JUSTIN + COUPNEY DIV

JOB SPECIFICATION

NO	NHQ	NMIN	IDAV	NPOLN= 1	LPTD= 1	NPOLN= 1	NPOLN= 1
43	2	0	1	.30	.40	.50	.60
				JNPERQ	NWT	0	0
						2	2
						0	0
						5	0

MULTI-PLAN ANALYSES TO BE PERFORMED

RTTOS=	.10	.20	.30	.40	.50	.60	.70	.80	1.00
--------	-----	-----	-----	-----	-----	-----	-----	-----	------

A-28

SUB-AREA RUNOFF COMPUTATION

ISTAQ	ICOMP	IECON	ITARE	JPLT	JPRV	I NAME
1	0	0	0	0	1	0

THYDG	TJHG	TAREA	SNAP	HYDROGRAPH DATA	RATIO	ISNOW	I NAME	LOCAL
0	1	178.00	0.90	TRSDA	TRSPC	0.000	0	0

PRECIP DATA	NP	STNOH	DAJ	DAK	NP	STNOH	DAJ	DAK
	6	0.00	0.00	0.00		6	0.00	0.00
PRECIP PATTERN								

UNIT HYDROGRAPH DATA	TP= 10.80	GP= .63	NIA= 0
----------------------	-----------	---------	--------

RECEDITION DATA

STEP0= C=0.00	OPCSN= 0.00	PTIND= 1.00
---------------	-------------	-------------

APPROXIMATE CLARK COEFFICIENTS FROM GIVEN SNYDER GP AND TP ARE TCE 5.3: AND Q= 4.90 INTERVALS

UNIT HYDROGRAPH 30 END-OF-PERIOD OPNTHATES	LA= 10.7A HJUDS, GP= .63 VNL= 1.00							
475.	1730.	3402.	SCAT.	6283.	5792.	6170.	5107.	4161.
2752.	2250.	1433.		1217.	931.	307.	659.	536.
356.	236.	132.		157.	128.	104.	85.	67.

TIME	RAIN	EXCT	CMPD Q
1	2	0	.80

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC

1 14	0	0.00	0.00
1 16	0	0.00	0.00
1 18	0	0.00	0.00
1 20	0	0.00	0.00
1 22	0	0.07	0.00
2 0	0	0.00	0.00
2 2	0	0.00	0.00
2 4	0	0.00	0.00
2 6	0	0.00	0.00
2 8	0	0.00	0.00
2 10	0	0.00	0.00
2 12	0	0.00	0.00
2 14	0	0.00	0.00
2 16	0	0.00	0.00
2 18	0	0.00	0.00
2 20	0	0.00	0.00
2 22	0	0.00	0.00
3 0	0	0.00	0.00
3 2	0	0.00	0.00
3 4	0	0.00	0.00
3 6	0	0.00	0.00
3 8	0	0.00	0.00
3 10	0	0.00	0.00
3 12	0	0.00	0.00
3 14	0	0.00	0.00
3 16	0	0.00	0.00
3 18	0	0.00	0.00
3 20	0	0.00	0.00
3 22	0	0.00	0.00
4 0	0	0.00	0.00
4 2	0	0.00	0.00
4 4	0	0.22	0.00
4 6	0	0.00	0.00
4 8	0	0.00	0.00
4 10	0	0.00	0.00
4 12	0	0.00	0.00
4 14	0	0.00	0.00
4 16	0	0.00	0.00
4 18	0	0.00	0.00
4 20	0	0.00	0.00
4 22	0	0.00	0.00
5 0	0	0.00	0.00

SU4 15.50 14.30 917756.

PEAK	5-HOUR	24-HOUR	TOTAL VOLUME
2FS 90420.	9507.	57304.	91756.
INCHES AC-FT	4.56	11.98	14.24
	43067.	11970.	135170.

HYDROGRAPH AT STA 1 END PLAN 1. RATIO 1

28.	373.	1215.	2844.	4961.	7042.	8479.
7240.	4960.	1960.	3226.	2628.	2141.	1158.
945.	764.	626.	510.	416.	374.	149.
119.	94.	68.	18.	3.	0.	0.
0.	0.	0.	0.	0.	0.	0.

PEAK	5-HOUR	24-HOUR	TOTAL VOLUME
2FS 9042.	9591.	5739.	91756.
INCHES AC-FT	4.5	1.20	1.42
	4307.	1177.	13517.

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC

235.	108.	137.	35.	7.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.

2FS	14094.	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
INCHES	14094.	17161.	11461.	4541.	163471.
AC-FT	9613.	91.	2440	245	245
		22744.	27934.	27034.	

HYDROGRAPH AT STA 1 FOR PLAN 1, RTIN 3

85.	397.	1180.	9533.	16844.	21127.	25565.	27126.
21719.	1781.	14582.	11880.	1678.	7085.	6426.	25476.
2430.	2305.	1478.	1510.	1247.	1016.	627.	3474.
356.	282.	205.	53.	10.	0.	0.	4474.
0.	0.	0.	0.	0.	0.	0.	0.

2FS	27126.	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
INCHES	27126.	26042.	17191.	6111.	24507.
AC-FT	12920.	1236.	3459.	427.	40551.
		34116.	40551.	40551.	

HYDROGRAPH AT STA 1 FOR PLAN 1, RTIN 4

116.	529.	1574.	4859.	13846.	28170.	34087.	36158.
28959.	23861.	13462.	15840.	12906.	10513.	8565.	5685.
3773.	3074.	2504.	2040.	1662.	1354.	1193.	6978.
475.	376.	273.	71.	13.	0.	0.	597.
0.	0.	0.	0.	0.	0.	0.	0.

2FS	36168.	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
INCHES	36168.	34723.	22922.	9082.	326462.
AC-FT	17227.	4181.	4179.	570.	570.
		45486.	54069.	54069.	

HYDROGRAPH AT STA 1 FOR PLAN 1, RTIN 5

142.	661.	2367.	6073.	14221.	24807.	35212.	42509.
36199.	23801.	2603.	14739.	16130.	13141.	10706.	42397.
4715.	5642.	3130.	25550.	2978.	1693.	1379.	5769.
594.	470.	362.	88.	17.	0.	0.	597.
0.	0.	0.	0.	0.	0.	0.	0.

2FS	45210.	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
INCHES	45210.	41504.	29552.	11352.	403678.
AC-FT	21534.	2027.	599.	712.	742.
		56860.	67585.	67585.	

HYDROGRAPH AT STA 1 FOR PLAN 1, RTIN 6

171.	794.	2360.	7288.	17065.	29769.	42256.	51130.
43454.	35761.	2464.	21759.	13157.	15770.	12847.	45252.
5660.	4611.	3757.	3060.	2493.	2031.	1655.	10667.
713.	564.	410.	105.	20.	0.	0.	1098.
0.	0.	0.	0.	0.	0.	0.	0.

2FS	54252.	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
INCHES	54252.	52094.	14387.	13623.	430413.
AC-FT	25840.	2672.	713.	954.	81102.
		58232.	81102.	81102.	

HYDROGRAPH AT STA 1 FOR PLAN 1, RTIN 7

199.	926.	2754.	4503.	1949.	27130.	49297.	59652.
50627.	41721.	30226.	27713.	2753.	14318.	14318.	4105.
6603.	5379.	4883.	1670.	2404.	2170.	1411.	1221.
931.	659.	479.	173.	24.	0.	0.	1044.
0.	0.	0.	0.	0.	0.	0.	0.

AC-FT 30167. 79504. 94617. 94619.

30147. 73604. 94617.

26610.

WILSON'S BIRDS OF THE PHILIPPINES

69174.	72336.	67228.
12956.	11370.	9263.
1798.	1464.	1193.
0.	0.	0.

2FS	72336.	b6446.	4544.51	1816.51	b7-14444
ACFES		36.63	11.91	3.39	
ACFES		36.66	9.75	1.36	

0944610 454630 1A163. 72

卷之三

HYDROGRAPH AT STA		FOR PLAN 1, RTD 9	
35.	1523.	3924.	12147.
			29442.
34.	59602.	4A606.	39509.
			32261.
33.	7645.	6264.	5101.
			4155.
32.	940.	683.	683.
			176.
31.	0.	0.	34.
			0.
30.	0.	0.	0.
			0.
			0.

AT SIA - 1 FOR PLAN 11 RTIG 9

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	90620.	46070.	57304.	22704.	817355.
INCHES	4.54	11.98	14.24	14.24	16.24
AC-FI	41057.	113720.	135179.	135179.	135179.

6-110112 24-H0112 72-H0112 101

VOLUME

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC

A-31

STORAGE = 0. 16109. 29130. 45519. 63007. 81640. 101434. 122392. 0.

223. 163. 826.

1779. \$1768. 2975.

545. 1134. 2019.

3132. 6334. 5449.

	PRAF	6-11004	26-44002	72-11012	total	VOLUN
2FR	3161.	\$128.	2910.	1061.	75067.	1.31
NC-HFS		*16	*61	1.23		

$$6 = 110010 \quad 2^6 = 110000 \quad 72 = 1100100$$

卷之三

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
SFS	6362.	6326.	5842.	3924.	150129.
INCHES		.33	1.22	2.46	2.62
AC-FT		3139.	11593.	23362.	24827.

	PEAK	6-HOUR	24-HOUR	48-HOUR	TOTAL	VOLUME
SFS	9179.	9326.	9036.	5915.	22585.	
INCHES						
AC-FT						

	PYAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	13441.	13359.	12239.	7923.	302053.
TNCHFS		.70	2.55	4.97	5.025
AC-FT		6629.	24286.	47169.	49952.
	STATION	PLAN 1,	PLAN 2,	PLAN 3,	
142.	159.	235.	1113.	234.	6122.
204.	15890.	16892.	17354.	17409.	17160.
704.	12271.	12160.	11455.	10763.	10001.
143.	6642.	5170.	5725.	5355.	5005.
522.	2328.	2121.	2121.	2226.	2569.
					2302
					2227
					11935.
					9326.
					15334.
					14536.
					8233.
					7677.
					3421.
					4799A.

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC

		PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME	
CFS	174093.	17108.	15676.	9960.	9960.	378909.	
INCHES	.90	.90	.90	6.25	6.25	6.60	
AC-FT	8577.	3109.	59294.			62562.	
STATION	2.	PLAN 1.	RTID 6				
171.	191.	282.	578.	1335.	2777.	4947.	7977.
17371.	19638.	20788.	21297.	21321.	20964.	20345.	19602.
16681.	15652.	14624.	13617.	12691.	11901.	11140.	10411.
8431.	7841.	7284.	6752.	6246.	5774.	5305.	5043.
4118.	3850.	3598.	3363.	3144.	2939.	2747.	2567.
STOP							
419.	469.	690.	1416.	3271.	6602.	12116.	18765.
37513.	40931.	43006.	43901.	43342.	43349.	42295.	40917.
35791.	33967.	32156.	30386.	24670.	27012.	25122.	23879.
19720.	18489.	17311.	16193.	15429.	14138.	13215.	12352.
10087.	9429.	8813.	9238.	7700.	7198.	6726.	6289.
PEAK	6-HOUR	24-HOUR	72-HOUR				
CFS	21321.	21200.	19203.	12014.			25876.
INCHES	1.01	4.01	7.53				32605.
AC-FT	10518.	36108.	74523.				37592.
STATION	2.	PLAN 1.	RTID 7				
199.	223.	329.	675.	1558.	3240.	5771.	9459.
21113.	23478.	24998.	25489.	25456.	24365.	24469.	23109.
19586.	18354.	17155.	15973.	14830.	13737.	12715.	11904.
9665.	8971.	9335.	7727.	7148.	6608.	6107.	5661.
4623.	4321.	4039.	3776.	3529.	3293.	3083.	2942.
STOP							
499.	547.	805.	1652.	3816.	7935.	14135.	21800.
43577.	47529.	49790.	50729.	50576.	43896.	48596.	46939.
40886.	38748.	36611.	34530.	32520.	30596.	28763.	27017.
22270.	20855.	19519.	19261.	17024.	15899.	14830.	13865.
11323.	10594.	9893.	9247.	8644.	8079.	7552.	7059.
PEAK	6-HOUR	24-HOUR	72-HOUR				
CFS	25688.	25302.	2278.	14084.			37694.
INCHES	1.32	4.76	8.83				43697.
AC-FT	12553.	45203.	83846.				20744.
STATION	2.	PLAN 1.	RTID 8				
221.	255.	376.	771.	1791.	3703.	6729.	10931.
24753.	27520.	23975.	23688.	29595.	28985.	28008.	26778.
22370.	20964.	19583.	18234.	16931.	15682.	14496.	13375.
10763.	10032.	9321.	8642.	7994.	7390.	6831.	6314.
5089.	4757.	4466.	4156.	3985.	3631.	3310.	3173.
STOP							
558.	625.	920.	1999.	4361.	3069.	16143.	24374.
49559.	53967.	56444.	57419.	57270.	56300.	54743.	52784.
45764.	43314.	40885.	38511.	36217.	34020.	31930.	29960.
24663.	23083.	21591.	20163.	19902.	17533.	16358.	15272.
12465.	11651.	10490.	10179.	9515.	9496.	8317.	7770.
PEAK	6-HOUR	24-HOUR	72-HOUR				
CFS	29649.	29451.	26416.				42927.
INCHES	1.54	5.52	10.14				46196.
AC-FT				26330.
							20097.
							11179.
							12114.
							23768.
							23350.
							23186.
							23499.
							10466.
							54446.
							13335.
							13268.
							11127.
							611837.

A-33

27652.	25768.	23914.	22124.	20555.	19049.	17616.	16260.	14984.	13749.
12744.	11832.	10998.	10198.	9434.	8721.	9051.	7451.	6987.	6366.
50661.	5683.	5125.	4790.	4478.	4195.	3912.	3557.		

STOP									
6984.	761.	1150.	2361.	5451.	41336.	20160.	31140.	42774.	53326.
61413.	66545.	69140.	69748.	63016.	67402.	65241.	62770.	60065.	57165.
56176.	51176.	69222.	65356.	42534.	39944.	37422.	35036.	32791.	30687.
28119.	26666.	25113.	23433.	21428.	20330.	18943.	17461.	16476.	15391.
14368.	13429.	12552.	11733.	10967.	10251.	9542.	9356.		

PEAK 6-HOUR 24-HOUR 72-HOUR TOTAL VOLUME									
CFS	40766.	40265.	36395.	20395.	769221.				
INCHES		2.10	7.19	12.79		13.60			
AC-FT		19976.	64956.	121415.		127210.			

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC

PEAK FLOW SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS

OPERATION	STATION	PLAN	RATIOS APPLIED TO FLOWS								
			.10	.20	.30	.40	.50	.60	.70	.80	
HYDROGRAPH AT	1	1	3042.	16084.	27126.	36166.	45210.	54252.	63296.	72336.	80420.
ROUTED TO	2	1	3143.	6362.	0.	0.	0.	0.	0.	0.	0.


THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDCI

STABILITY ANALYSES


A-36

SUBJECT	SHEET	BY	DATE	JOB NO
STILLWATER RESERVOIR L-111	1	ZEH	7/3/72	NYSDEC

SPILLWAY SECTION



section developed from
drawings provided by
NYSDEC and HRBRD



Assumptions: - gravity section

- unit weight of concrete = 14.1 psf
- unit weight of silt (wet) = 86 psf
- internal angle of friction (silt) = 30°
- angle of friction concrete/foundation = 30°
- shear resistance concrete/foundation = 100 psi
- seismic coeff of acceleration = .1g
- T.W elev (PMF) = 1646.3

The effect of negative pressure caused by separation of the nooks from the spillway is beyond the scope of this phase of study and is not considered in the analysis (PMF)



SUBJECT		SHEET	BY	DATE	JOB NO
STILLWATER RESERVOIR DATA		2	R.E.L.	7/3/78	NYSDE

SPILLWAY STABILITY ANALYSIS - SUMMARY

LOADING CONDITION	SF-AGGRAVATION	SF-SLICING	BEARING PRESSURES
NORMAL Pool	1.2	7.1	46.7 psi - 14.3 psi (Tension)
EARTHQUAKE	1.0	5.6	60.9 psi - 28.5 psi (Tension)
PMF	1.0	6.0	59.6 psi - 29.2 psi (Tension)

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC

NATIONAL DAM INSPECTION PROGRAM - STILLWATER RESERVOIR DAM
SPILLWAY SECTION - NORMAL POOL 1679.1 MFL SHADAMS

BASE ELEVATION= 1636.30FT, TOP ELEVATION= 1677.30FT, BASE WIDTH= 28.50FT, DENSITY= 1.0400PCF
HEADWATER ELEVATION= 1679.30FT, TAILWATER ELEVATION= 0.00FT, EARTHQUAKE ACCELERATION= 0.00G (HORZ) + 0.00G (VERT)
SILT ELEVATION= 1656.80FT, SILT DENSITY(SUBMERGED)= 86.00PCF, SILT PRESSURE COEFFICIENT(K)= .33
SHEAR STRESS= 100.00PSI, SHEAR WIDTH= 28.50FT, FRICTION FACTOR= .58

LOADING FORCE (KIPS) ARM(FEET) STABILIZING MOMENT OVERTURNING MOMENT

WEIGHT OF DAM	104.00	18.50	1962.91
HEADWATER UPLIFT	57.56	14.27	821.67
SILT	36.24	19.00	726.48
	6.02	6.03	4.412
			•••••
			1589.27

NET HORIZONTAL FORCE= 63.56 KIPS

NET VERTICAL FORCE= 66.56 KIPS

NET MOMENT= 353.0 KIP-FEET

X-BAR-OF-FOUNDATION REACTION= 5.31 FEET

ECCENTRICITY OF FOUNDATION REACTION FROM CENTER= 8.96 FEET

FOUNDATION REACTION NOT IN CENTRAL THIRD OF BASE ••• TENSION AT HEEL OF DAM •••••

FOUNDATION REACTION PRESSURE= 46.73 PSF

OVERTURNING FACTOR OF SAFETY= 1.22

SLIDING FACTOR OF SAFETY= .61

DEVELOPED FRICITION FACTOR (NO SHEAR)= .96

SLIDING WITH SHEAR FACTOR OF SAFETY= 7.06 (SHEAR ACROSS FULL BASE WIDTH)

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC

NATIONAL DAM INSPECTION PROGRAM - STILLWATER RESERVOIR DAM
SPILLWAY SECTION - NORMAL POOL 1679.3' WFLASHBOARDS = FARMHOUSE

BASE ELEVATION= 1636.58FT. TOP ELEVATION= 1677.430FT. BASE WIDTH= 26.50FT. DENSITY= 144.00PCF
HEADWATER ELEVATION= 1679.30FT. TAILWATER ELEVATION= 0.00FT. EARTHQUAKE ACCELERATION= .000G (VERT)
SILT ELEVATION= 1656.80FT. SILT DENSITY(SUBMERGED)= 86.00PCF SILT PRESSURE COEFFICIENT(K)= .33
SHEAR STRESS= 100.00PSI SHEAR WIDTH= 26.50FT FRICTION FACTOR=.750

LOADING	FORCE(kips)	ARM(feet)	STABILIZING MOMENT	OVERTURNING MOMENT
WEIGHT OF DRY	104.80	16.54	1942.91	
HEADWATER UPLIFT	57.56	14.27		821.67
EARTHQUAKE-INDUCED LOADINGS	36.24	19.00		726.48
INERTIA-WATER	6.14	17.20		105.58
HORIZONTAL-INERTIA-DRY	10.68	16.36		171.66
SILT	6.02	6.83		41.12
			1942.91	1666.32

NET HORIZONTAL FORCE= 80.20 KIPS
NET VERTICAL FORCE= 86.56-KIPS

NET MOMENT= 76.59KIP-FEET

X-BAR OF FOUNDATION REACTION= 1.15 FEET

ECCENTRICITY OF FOUNDATION REACTION FROM CENTER= 13.10 FEET

FOUNDATION REACTION NOT IN CENTRAL THIRD OF BASE****TENSION AT HEEL OF DAM*****

FOUNDATION REACTION PRESSURES***TOP= 60.94 PSI***HEEL= -24.51 PSI*****

OVERTURNING-FACTOR OF SAFETY= 1.04

SLIDING FACTOR OF SAFETY=.68

DEVELOPED FRICITION FACTOR (NO SHEAR)= 1.00

SLIDING WITH SHEAR FACTOR OF SAFETY= 5.61(SHAR) ACROSS FULL BASE WIDTH

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC

A-45

NATIONAL DAM INSPECTION PROGRAM--STILLWATER RESERVOIR DAM
SPILLWAY SECTION--PMF

BASE ELEVATION= 1636.30FT. TOP ELEVATION= 1677.30FT. BASE WIDTH= 28.50FT. DENSITY= 1.44.0pcf
HEADWATER ELEVATION= 1688.50FT. TAILWATER ELEVATION= 1646.20FT. EARTHQUAKE ACCELERATION***.000G (VERT)
SILT ELEVATION= 1656.80FT. SILT DENSITY(SUBMERGED)= B6.00pcf SILT PRESSURE COEFFICIENT(N)= .35

SHEAR STRESS= 100.00fpi SHEAR WIDTH= 28.50FT. FRICTION FACTOR= .58

LOADING	FORCE(KIPS)	ARM(FEET)	STARTLING MOMENT	OVERTURNING MOMENT
A-41				
WEIGHT OF DAM	104.80	18.54	1942.93	
HEADWATER	01.10	16.08		1304.18
TAILWATER	3.12	3.33		
OFLIFT	55.31	17.47		
SILT	6.03	6.03		
			1953.32	
				2311.70

NET HORIZONTAL FORCE= 84.00 KIPS
NET VERTICAL FORCE= 49.49 KIPS
NET MOMENT= -358.38kif-ft
X-LOC OF FOUNDATION REACTION= -7.24 FEET
ECCENTRICITY OF FOUNDATION REACTION FROM CENTER= 21.49 FEET
*****BURGULION REACTION NOT IN CENTRAL THIRD OF BASE****
COMBINATION REACTION PRESSURE***TOE= 65.62 Psi*****HEEL= -42.50 Psi****
OVERBURDEN PRESSURE OF SAFETY= .64
SLIDING FACTOR OF SAFETY= .34
DEVELOPED FRICTION FACTOR (NO SHEAR)= 1.70
SLIDING WITH SHEAR FACTOR OF SAFETY= 5.233 Shear across full base width
NUMBER OF STATIONS TO DESCRIBE DEM= 4
STATION ELEVATION
.00 1636.30
21.50 1677.30
20.50 1677.30
29.50 1636.30

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC