

AD-A066 031


NEW YORK STATE DEPT OF ENVIRONMENTAL CONSERVATION ALBANY F/G 13/2  
NATIONAL DAM SAFETY PROGRAM. POCANTICO LAKE DAM. (INVENTORY NUM--ETC(U)  
AUG 78 J B STETSON


DACW51-78-C-0035

NL

UNCLASSIFIED

| OF |  
AD  
A066031





ADA066031

LEVEL IV  
LOWER HUDSON RIVER BASIN  
**POCANTICO LAKE DAM  
WESTCHESTER COUNTY  
NEW YORK  
INVENTORY NO 49**



**PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM**

DDC FILE COPY

APPROVED FOR PUBLIC RELEASE;  
DISTRIBUTION UNLIMITED  
CONTRACT NO DACW 51-78-C-0035



National Dam Safety Program.  
Pocantico Lake Dam, Lower Hudson River  
Basin, Westchester County, New York  
(Inventory Number 49), Phase I  
Inspection Report.

*John B. Stetson*

NEW YORK DISTRICT CORPS OF ENGINEERS

(11) AUGUST 1978

(12) 94 P.

393970

79 03 15 047

B

DEPARTMENT OF THE ARMY  
U. S. ARMY ENGINEER DISTRICT, NEW YORK  
26 FEDERAL PLAZA  
NEW YORK, NEW YORK 10007

2 OCT 1978

NANEN-F

Honorable Hugh L. Carey  
Governor of New York  
Albany, New York 12224

Dear Governor Carey:

The purpose of this letter is to inform you of a clarification of the guidelines used by this office in assessing dams under the National Program of Inspection of Dams.

Office of the Chief of Engineers has recently provided a clarification that dams with seriously inadequate spillways are to be assessed as unsafe, non-emergency, until more detailed studies prove otherwise or corrective measures are completed.

The following dams in your state have previously been assessed as having seriously inadequate spillways, with capability to pass safely only the percentage of the probable maximum flood as noted in each report. They are now to be assessed as unsafe:

<u>I.D. NO.</u>	<u>NAME OF DAM</u>
N.Y. 59	Lower Warwick Reservoir Dam
N.Y. 4	Salisbury Mills Dam
N.Y. 45	Amawalk Dam
N.Y. 418	Jamesville Dam
N.Y. 685	Colliersville Dam
N.Y. 6	Delta Dam
N.Y. 421	Oneida City Dam
N.Y. 39	Croton Falls Dam
N.Y. 509	Chadwick Dam (Plattenkill)
N.Y. 66	Boys Corner Dam
N.Y. 397	Cranberry Lake Dam
N.Y. 708	Seneca Falls Dam
N.Y. 332	Lake Sebago Dam
N.Y. 338	Indian Brook Dam
N.Y. 33	Lower(S) Wicopee Dam (Lower Hudson W.S. for Peekskill)

NANEN-F

Honorable Hugh L. Carey

<u>I.D. NO.</u>	<u>NAME OF DAM</u>
N.Y. 49	Pocantico Dam
N.Y. 445	Attica Dam
N.Y. 658	Cork Center Dam
N.Y. 153	Jackson Creek Dam
N.Y. 172	Lake Algonquin Dam
N.Y. 318	Sixth Lake Dam
N.Y. 13	Butlet Storage Dam
N.Y. 90	Putnam Lake (Bog Brook Dam)
N.Y. 166	Pecks Lake Dam
N.Y. 674	Bradford Dam
N.Y. 75	Sturgeon Pool Dam
N.Y. 414	Skaneateles Dam
N.Y. 155	Indian Lake Dam
N.Y. 472	Newton Falls Dam
N.Y. 362	Buckhorn Lake Dam

The classification of "unsafe" applied to a dam because of a seriously inadequate spillway is not meant to connote the same degree of emergency as would be associated with an "unsafe" classification applied for a structural deficiency. It does mean, however, that based on an initial screening, and preliminary computations, there appears to be a serious deficiency in spillway capacity so that if a severe storm were to occur, overtopping and failure of the dam would take place, significantly increasing the hazard to loss of life downstream from the dam.

Consequently, it is advisable to implement the recommendations previously furnished in the reports for the above-mentioned dams as soon as practicable.

It is requested that owners of these dams be furnished a copy of this letter and that copies be permanently appended to all reports previously furnished to you.

Sincerely yours,

CLARK H. BENN  
Colonel, Corps of Engineers  
District Engineer

## TABLE OF CONTENTS

	<u>Page</u>
Assessment of General Conditions	i
Photographic Overview of Dam	ii-ix
Section 1 - Project Information	1-4
Section 2 - Engineering Data	5
Section 3 - Visual Inspection	6
Section 4 - Operational Procedures	7
Section 5 - Hydraulic/Hydrology	8-9
Section 6 - Structural Stability	10-12
Section 7 - Assessment/Remedial Measures	13

## FIGURES

- Figure 1 - Location Plan
- Figure 2 - Plan (May 1916)
- Figure 3 - Detail Plan and Sections (May 1916)
- Figure 4 - Topographical Plan
- Figure 5 - Plan for Raising Spillway
- Figure 6 - Schematic Profile (May 1963)

## APPENDIX

- Field Inspection Report
- Previous Inspection Reports/Relevant Correspondence
- Hydrologic and Hydraulic Computations
- References

A  
B  
C  
D

ACCESSION for		
NTIS	<input checked="" type="checkbox"/>	
DOC	<input type="checkbox"/>	
UNARMED	<input type="checkbox"/>	
JUSTICE	<input type="checkbox"/>	
BY		
DISTRIBUTION/REF ID: 10000000000000000000		
Date	Entered	
R		

PHASE I REPORT  
NATIONAL DAM SAFETY PROGRAM

Name of Dam Pocantico Dam NY49

State Located New York  
County Located Westchester  
Stream Pocantico River  
Date of Inspection July 26, 1978

ASSESSMENT OF  
GENERAL CONDITIONS


The Pocantico Dam is a water supply reservoir which has been discontinued as a source for water supply by the New Rochelle Water Company in 1977. At this time, routine maintenance of the facility is being performed by on-site personnel. The earthen dam does not show physical signs of distress. At the time of inspection, the reservoir water surface level was being kept well below the spillway elevation. A hydrologic investigation has determined the spillway to be seriously inadequate. Steps should be taken to insure the facility is at least capable of passing a 1/2 Probable Maximum Flood (PMF). Since the spillway has been found to be seriously inadequate it is recommended that immediately, during periods of unusually high runoff, the owner should provide around-the-clock surveillance and have a contingency plan in the event of overtopping. The spillway is currently only capable of passing 28 percent of the PMF. A rather sizable tourist area (Sleepy Hollow Restorations) exists downstream of the facility and reportedly receives 1400 visitors per week.



Approved By:  
Date:

Dale Engineering Company


  
John B. Stetson, President

  
Col. Clark H. Berlin  
New York District Engineer

19 September 1978



Overview of top of earthen dam.



1. View of riprap on face of dam.




2. View of intake tower on upstream face of dam.



F H

3. View of reservoir upstream of dam.



F

4. View of spillway structure with  
eight 8 X 4 sluice gates.



5. Manually operated gate equipment.




6. View of spillway from downstream channel.




7. Detail of spillway gate dividing wall showing cracks.



8. Detail of spillway floor slab.



9. Downstream channel.



10. Detail of embankment erosion in downstream channel.




F

11. Abandoned filtration plant below  
dam.



F

12. Cattails at toe of embankment near  
storage tank. Wetness from either  
seepage or poor surface drainage.



13. Outflow discharge pipe.



14. Cavity in east abutment embankment area  
below dam. Some water flowing.

PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM  
NAME OF DAM - POCANTICO ID# - NY49

SECTION 1 - PROJECT INFORMATION

1.1 GENERAL

a. Authority

Authority for this report is provided by the National Dam Inspection Act, Public Law 92-367 of 1972. It has been prepared in accordance with a contract for professional services between Dale Engineering Company and The New York State Department of Environmental Conservation.

b. Purpose of Inspection

The purpose of this inspection is to evaluate the structural and hydraulic condition of the Pocantico Dam and appurtenant structures, owned by the New Rochelle Water Company, and to determine if the dam constitutes a hazard to human life or property and to transmit findings to the State of New York.

This Phase I inspection report does not relieve an Owner or Operator of a dam of the legal duties, obligations or liabilities associated with the ownership or operation of the dam. In addition, due to the limited scope of services for these Phase I investigations, the investigators had to rely upon the data furnished to them. Therefore, this investigation is limited to visual inspection, review of data prepared by others, and simplified hydrologic, hydraulic and structural stability evaluations where appropriate. The investigators do not assume responsibility for defects or deficiencies in the dam or in the data provided.

1.2 DESCRIPTION OF PROJECT

a. Description of Dam and Appurtenances

The Pocantico Dam is an earth fill dam with a short concrete core wall which extends to approximately 14-1/2 feet below the top elevation of the dam. The width of the top of the dam is approximately 12 feet. The dam is approximatley 35 feet high and approximately 300 feet in total length. The upstream slope of the embankment is 2 feet horizontal on 1 foot vertical. The downstream slopes are 1-3/4 horizontal on 1 vertical. The upstream face of the embankment is riprapped at the waterline. The spillway is located near the west abutment of the main structure. The spillway is approximately 75 feet long and is controlled by eight 4 feet high by 8 feet wide sluice gates which are manually operated from a bridge across the spillway. The spillway is constructed on bedrock and discharges through a bedrock channel down to the Pocantico River.

The main drainline for the reservoir is a 24 inch pipe which is controlled from the intake structure and discharges downstream in the Pocantico River. The operator of the dam indicates that this drain is partially obstructed so that full outlet flow can not be obtained.

b. Location

Pocantico Lake Dam is located in the Town of Mount Pleasant in Westchester County, New York.

c. Size Classification

The maximum height of the dam is approximately 35 feet. The storage volume of the dam is approximatley 1,595 acre feet to the top elevation of the dam. Therefore, the dam is in the intermediate size category as defined by the Recommended Guidelines for Safety Inspection of Dams.

d. Hazard Classification

The Pocantico River, the receiving stream from the impoundment flows through Philipsburgh Manor, a portion of the Sleepy Hollow Restorations. This popular tourist area is open to the public and large numbers of tourist daily move about the area. The site receives 1400 visitors per week. Therefore, the dam is in the high hazard category as defined by the Recommended Guidelines for Safety Inspection of Dams.

e. Ownership

The dam is owned by the New Rochelle Water Company.

f. Purpose of Dam

The dam has recently been abandoned as a water supply reservoir for the New Rochelle Water Company. Therefore, the facility has at present no useful purpose except to maintain the environment that has existed in the area for many years. No significant recreational use is made of the facility at the present time.

g. Design and Construction History

No information was found to indicate the date of the original construction of the dam. Construction drawings dated May, 1916, indicate a reconstruction which took place during that time. The reconstruction consisted of the raising of the dam and the improvement of the spillway control. This project also indicates the construction of a core wall through the center of the embankment which extends only 14-1/2 feet below the top of the dam as it was reconstructed.

h. Normal Operational Procedures

The dam site is currently staffed by the Water Company. At this time, the status of operational procedures for the dam is not known. The dam is currently not operational (normal use).

1.3 PERTINENT DATA

a. Drainage Area

The drainage area of the Pocantico Dam is 10.48 square miles.

b. Discharge at Dam Site

No discharge records are available at this site.

Computed Discharges:

Spillway capacity, top of dam	4000 cfs
Spillway design flood, (with gates fully open)	6830 cfs (1/2 PMF)
	14000 cfs (PMF)

c. Elevation (feet above MSL)

Top of dam*	225.0
Spillway design flood - 1/2 PMF discharge	226.7
PMF discharge	229.2
Spillway crest	215.0
Stream bed at centerline of dam	185.0

d. Reservoir

Length of maximum pool	10000 feet
Length of normal pool	10000 feet

e. Storage

Top of dam	1595 acre feet
Normal pool	920 acre feet

f. Reservoir Surface

Top of dam	91.0 acre
Spillway pool	67.2 acre

g. Dam

Type - Earth fill with concrete core wall.  
Length - 300 feet.  
Height - 35 feet.

\*Plans in this report show various elevations, some related to proposed improvements.

Freeboard between normal reservoir and top of dam - 6 feet with  
gates closed, 10 feet with gates open.  
Top width - 6 feet, 6 inches.  
Side slopes - 2 horizontal to 1 vertical upstream.  
1-3/4 horizontal to 1 vertical downstream.  
Zoning - None indicated.  
Impervious core - Concrete core wall to elevation 223.  
Grout curtain - None indicated.

## SECTION 2 - ENGINEERING DATA

### 2.1 DESIGN

The information available for review for the Pocantico Dam included:

- 1) The plans reviewed are enclosed in this report in Figures 1 through 6.

### 2.2 CONSTRUCTION

No information available.

### 2.3 OPERATION

See Section 4.

### 2.4 EVALUATION

The data reviewed indicates that a number of structure modifications to the facility were either performed or planned. The construction documents infer that the dam was constructed prior to 1916 whereas the May 10, 1916 plans represent an improvement to the facility. In the information available for review, the dam lacks sufficient information to evaluate the construction records. It is not known if additional information on the dam exists or where it could be located. Due to the present status and condition of the facility, (with consideration given to the recommendations provided herein, See Section 7) it is not deemed necessary to try to locate additional data. The visual examination and the data reviewed were considered adequate for this Phase 1 investigation.

### SECTION 3 - VISUAL INSPECTION

#### 3.1 SUMMARY

##### a. General

The visual inspection of Pocantico Dam took place on July 26, 1978. The dam has functioned as a reservoir for a water treatment facility owned by the New Rochelle Water Company. In 1977 the use of the facility for water supply was abandoned. The property is currently staffed with water department employees utilizing the structure at the facility as a storage and maintenance facility. At time of inspection the water level was six feet below the spillway. See Section 6 for additional narrative information.

##### b. Dam

The dam and spillway visually conform to the plans as provided in this report. The embankment has tall grasses and small brush. It is generally in good condition with no areas of seepage or erosion found on the downstream face of the embankment. The low head in the reservoir could however, reduce or eliminate evidence of seepage at the time of inspection. Photograph 12 shows cattails at the toe of the embankment near the storage tank. This wetness could be from either seepage or poor surface drainage. Seepage has been noted before by the plant operator when the reservoir has a full normal head. Photograph 14 also shows some water flowing in a cavity or trench area of unknown origin in the east abutment which leads up to a pair of stilling basins. These areas should be checked for seepage again when the reservoir is known to have a significant head.

##### c. Spillway

The spillway concrete sill shown in Photograph 8 is in fair condition. Some wear of the surface material has taken place. One of the spillway's dividing wall and support frame for the sluice gates is cracked as shown in Photograph 7. The spillway gates, shown in Photograph 5, are reported to be operable but are not well maintained so as to be easily operated.

##### d. Appurtenant Structures

The drawdown and treatment plant intake structure is in the center of the upstream face of the dam. The rod for the draindown gate is broken off with the gate operating partially open. Therefore, the dam cannot be drawn down without repair of the control rod unless flows are directed through the filtration equipment. It is not known whether this is possible or practical.

##### e. Downstream Channel

The channel immediately below the spillway is shown in Photograph 6. It is largely exposed rock. Photograph 10 shows some embankment erosion further downstream. This is not considered serious.

## SECTION 4 - OPERATIONAL PROCEDURES

### 4.1 PROCEDURES

Operational procedures have not been documented or written up by the owner nor were they demonstrated to the inspection team. The lowest drawdown gate is presently inoperable. The spillway sluice gates were reported to be operable but are manually operated and cannot be turned very easily. The use of the dam and reservoir as a water supply source has been discontinued. At this time, the owner has no future intention of using the facility for a water supply.

### 4.2 MAINTENANCE

The facility currently has on-site staff personnel working in the shop and storage facilities in the plant. Currently, the embankment slopes and level of the reservoir are being maintained.

## SECTION 5 - HYDROLOGY AND HYDRAULICS

### 5.1 EVALUATION OF FEATURES

#### a. Design Data

For this report, no information relevant to the hydrologic and/or hydraulic design for the dam was available. The hydrologic and hydraulic analysis provided in Appendix C was performed utilizing information obtained from construction documents and other sources of information listed in the reference section of this report.

Pocantico Dam is an earthen type dam with a spillway structure containing eight (8) sluice gates. The dam is not readily accessible to the general public. The drainage area contributing to the reservoir is approximately 10.5 square miles including 0.167 square miles of reservoir water surface. The volume of the impoundment is purely a function of natural watershed. For the dams location, no information was available on historical flood events.

The purpose of this investigation is to evaluate the dam and spillway with respect to their flood control potential and/or adequacy. This potential was assessed in the development of the Probable Maximum Flood (PMF) for the watershed and a subsequent routing through the reservoir system. PMF is that hypothetical flow induced by the most critical combination of precipitation, minimum infiltration loss and concentration runoff of a specific location that is considered reasonably possible for a particular drainage area. Since this dam is in the intermediate category with a high hazard, the guidelines (Ref. 1) require the dam to pass the Probable Maximum Flood. The hydrologic analysis was performed using the unit hydrograph method to develop the flood hydrograph. In preparing the hydrograph, both Clark and Snyder coefficients were estimated. For the Clark Method values of  $T_c = 7.63$  and  $R = 4.88$  were computed. For the Snyder Method, values of  $T_{pr} = 2.73$  and  $CP = 0.625$  were computed. Two unit hydrographs were developed from these parameters and two sets of hydrographs were later computed for the purposes of comparison. The resulting computations were not similar. Since the Snyder parameter produced excessive PMF discharges for this size of a drainage basin, the Clark Method parameters were used for evaluation of the spillway capacity. The Probable Maximum Flood (PMF) hydrograph was determined using Probable Maximum Precipitation rainfall data obtained in Hydrometeorological Report No. 51. An index rainfall of 24 inches for 200 square miles for a period of 24 hours was used in the analysis. Both the PMF and 1/2 PMF were evaluated. The 1/2 PMF was assumed to be approximately the Standard Project Flood (SPF) in utilizing U.S. Army Corps of Engineers, Hydrologic Engineering Centers, Computer Program (UHCOMP). The peak discharges for the Clark Method were 6,831 cfs for the 1/2 PMF (SPF) and 14,000 cfs for the PMF. The peak discharges for the Snyder Method were 11,400 cfs for the 1/2 PMF (SPF) and 23,500 cfs for the PMF. Hydraulic studies were performed at the spillway structure. These computations, which assumed the sluice gates would remain open, are shown in Appendix C.

The U.S. Army Corps of Engineers, Hydrologic Engineering Centers, Program HEC-1 using the Modified Puls Method for flood routing was used to evaluate the structure and the reservoir. The peak flow discharges were not reduced by the storage effect of the reservoir. The spillway capacity with the gates fully opened is about 4000 cfs. The spillway capacity is 28 percent of the PMF. The analysis indicates the dam would be topped by 2 feet with the 1/2 PMF (SPF) event and by 4 feet with the PMF event. Further work should be performed to determine the accuracy of the computed discharges. Since the dam has been abandoned, removal of the spillway sluice gate works may provide sufficient discharge conveyance section to pass the 1/2 PMF (SPF). This investigation has been determined that due to the very small reduction of the peak discharge from the reservoir storage effect, drawing down the reservoir alone as a remedial measure will probably not be sufficient to prevent over-topping of the dam from 1/2 PMF (SPF).

b. Experience Data

The Owner's Representative at the site was not able to provide information relevant to performance of the spillway during extreme rainfall events.

## SECTION 6 - STRUCTURAL STABILITY

### 6.1 EVALUATION OF STRUCTURAL STABILITY

#### a. Visual Observations And Data Review

The reservoir dam (embankment section) shows no evidence of misalignment, sloughing, surface cracks or erosion of significance which would be indicative of structural movement or distress. The condition of riprap on the upstream face is rated fair to good. Some low vegetation, including small trees and shrubs, are growing along the top of the embankment and the upper upstream slope (generally above the riprap elevations). The embankments downstream face is covered with grasses and low vegetation, with a few small trees and shrubs at various locations. Large trees exist on the downstream slope in the vicinity of both the easterly and westerly abutments.

The spillway is a concrete gated structure. Eight sluice gates approximately four feet wide are provided. The reservoir was drawn down some 6 feet below its normal level at the time of the inspection, a condition which revealed the presence of considerable debris (tree branches, other miscellaneous waste items) against the spillway gates. The spillway's structural concrete components are generally in fair to good condition, although spalling is occurring at various locations, and some cracks exist.

The spillway discharge channel floor (to the Pocantico River) consists of bedrock. This discharge channel is provided with laid up stone sidewalls. Vegetation is growing in the channel floor (through rock seams and cracks) and the stone sidewalls.

Concrete water settling/treatment pools, now abandoned, remain immediately downstream of the dams easterly abutment, at a level approximately midway between the top and toe elevations of the embankment. A large ground level steel storage tank exists just below the downstream toe close to the easterly end of the dam, near the toe of slope of the area where the above mentioned settling tanks are located. The reservoir facilities pump house and an adjacent residential building are located immediately below the embankments westerly downstream toe. No water seepage through or beneath the dam was noted on the embankment slope and area below the downstream toe or in the basements of the pump house and residential building. However, cattails exist at the downstream toe of embankment adjacent to the ground level water storage tank. Operating personnel assigned to the reservoir indicate that a dampness/seepage condition typically develops along the westerly section of the embankments downstream toe in wet seasons.

Close examination of the area indicated no evidence of erosion or piping.

Some seepage was noted near the toe of the slope provided for the abandoned concrete settling tanks located immediately downstream of the dams easterly abutment. A low stone retaining wall has been constructed at the seepage location. The seepage condition apparently has been on-going for a considerable number of years. It appears that the seepage is from a spring or other source outside of the reservoir embankment area.

b. Geology and Seismic Stability

The New York State Geologic Map (1970) indicates the reservoir is situated on Fordham Gneiss. This foliated rock is composed of biotite, hornblende, quartz, and plagioclase. The 1916 reports indicate that the spillway is on natural rock, (gneiss).

Although gneiss has considerable strength and bearing capacity, weathering of the biotite and hornblende components of the rock may yield rotted seams conducive to seepage.

There are no known faults in the vicinity of the reservoir according to the New York State Geologic Survey (1977). The closest known fault shown is four miles west of the dam, across the Hudson River. Of earthquakes listed below, most of the epicenters are not located in the vicinity of any known faults.

Some of the earthquakes recorded for the area are tabulated below:

Date	Intensity-Modified Mercalli	Location Relative to Dam
1916	IV	8 mi. SSE
1933	III	8 mi. SSE
1936	IV	8 mi. E
1937	II	6 mi. NNE
1938 (2)	III	8 mi. NE
1941	III	5 mi. ENE
1964 (2)	II	8 mi. NE
1964	V	8 mi. NE
1967	V	6 mi. NNE

The reservoir dam is located in an area designated Zone 1 on the Seismic Probability Map.

c. Data Review and Stability Evaluation

Available design drawings imply that the dam consists of a homogeneous earth embankment.

The present dam is approximately ten feet higher, and greater in cross section, than the original dam constructed at this site. Additional work should be performed to determine exactly which plans are accurate to the site; a number of different elevations are referenced on different drawings for the elevation of the top of the dam.

Downstream and upstream slopes of approximately 2 to 1 (horizontal to vertical) are indicated. No information is available on the embankment foundation, make-up of the earthen interior, or method of soil placement and compaction.

At present, the embankment is considered to be in good structural condition with no indication of instability or deterioration. The reported past periodic seepage, which was not occurring at the time of inspection, has not had a significant effect on the condition of the embankment. To reduce hazards associated with future operations, trees on slopes of the dam should be removed to eliminate the potential for embankment seepage and structural damage which could occur from a storm-caused uprooting. Slope grasses should be mowed to enable rapid detection of possible seepage occurrences. It is anticipated that, properly maintained, this earthen embankment will continue to serve satisfactorily for future loading conditions which are similar to those of the past.

The spillway structure should be kept clear of debris which could interfere with proper operation of sluice gates and spillway flow. Repair of damaged/deteriorated concrete in the spillway structure should be undertaken to prevent progressive effects. The area downstream of the spillway should be kept clear of debris and plant growth which could interfere with rapid passage of waste water.

## SECTION 7 - ASSESSMENT/REMEDIAL MEASURES

### 7.1 DAM ASSESSMENT

On the basis of the Phase I visual examination, the earth embankment of the Pocantico Dam does not show any major signs of distress and in its present status, the dam is not deemed to be considered unsafe during periods of normal hydrologic conditions. Concern is given however, for the dams safety under the condition of a severe hydrologic event. In 1977 the owner of the dam discontinued use of the site as a water supply reservoir. At the time of inspection, the dam was drawn down six feet below the spillway. Since some minor seepage has been reported in the past, it is recommended that the reservoir level be kept well below the spillway. If for some reason the reservoir level is to be raised, the dam should be inspected again under a full head with the report amended with those visual observations. A number of small trees with shallow root systems on the embankment should be removed.

Mechanical appurtenances are reportedly operable, however, are in some need of repair. Due to the status of the facility, the utility of this equipment should be evaluated in regards to a commitment to continued maintenance and repair. The dam is in the intermediate size high hazard category, and the guidelines (Ref. 1) indicates the spillway should be able to pass the Probable Maximum Flood. The spillway has been found to be seriously inadequate and is not capable of passing the 1/2 Probable Maximum Flood (PMF). The spillway is capable of passing 28 percent of the PMF.

### 7.2 REMEDIAL MEASURES

The following remedial measures are recommended.

#### 1) Immediate Actions

The owner should continue to keep the reservoir head down at its present location and each of the sluice gates be made fully open. Since the spillway has been found to be seriously inadequate it is recommended that immediately, during periods of unusually high runoff, the owner should provide around-the-clock surveillance and have a contingency plan in the event of overtopping.

#### 2) Further Actions to be Taken Immediately

The facility should, at a minimum, be improved to be capable of passing the 1/2 PMF. Additional engineering studies should be prepared to obtain this level of safety. The hydrologic analysis performed herein should be refined. The correct elevations of the dam should be determined, since a number of different elevations have been noted in the plans provided herein. One remedial action which should be considered, would be to have the sluice gates and their concrete frames removed to enable the spillway to pass the 1/2 PMF. As mentioned above, this alternative would have to be evaluated.






FIGURE 1



## FIGURE 2

52-80H-25



PLAN OF NEW SPILLWAY

--

### *DOWNSRAME ELEVATION OF SP/4/TWAY*

The elevation drawing illustrates a bridge beam section. Key dimensions include a total width of 10'-0" (120"), a height of 10'-0" (120"), and a thickness of 10". The beam features a central vertical column labeled "10' 0" x 10' 0" x 10"". Reinforcement is indicated by a grid of bars: 4 #6 bars at the top, 4 #6 bars at the bottom, and 4 #4 bars running vertically through the center. A note specifies "To Beam at 10 min. Spacing". A vertical column on the left lists "10' 0" x 10' 0" x 10"" and "10' 0" x 10' 0" x 10"". A note at the bottom right states "ELEVATION OF TYPICAL BRIDGE BEAM".

۱۰۵

NEW SPILLWAY SECTION A

NEW CANTILEVER RETAINING WALL  
Scale 1:1.

**DETAIL PLAN AND SECTIONS  
OR SPILLWAY 6-53**

**FIGURE 3**

FIGURE

Sectional Area  
Opposite Bank

SECTIONAL PLAN  
Opposite Bank of Colorado  
WATERMASTER CO.

FIGURE 5





FIGURE 6



APPENDIX A  
FIELD INSPECTION REPORT

CHECK LIST  
VISUAL INSPECTION

PHASE 1

Name Dam POCANTICO DAM County WESTCHESTER State NEW YORK ID # NY 49  
Type of Dam EARTHEN Hazard Category HIGH  
Date(s) Inspection JULY 26, 1978 Weather SUNNY Temperature 70°

Pool Elevation at Time of Inspection 212 M.S.L. Tailwater at Time of Inspection --

Inspection Personnel:

N. F. DUNLEAVY  
D. F. McCARTHY  
F. W. BYSZEWSKI  
R. GAINER  
P. CARROL  
L. KOSILLA  
G. LORENZ

DALE ENGINEERING COMPANY  
DALE ENGINEERING COMPANY  
DALE ENGINEERING COMPANY  
NEW ROCHELLE WATER CO.  
NEW ROCHELLE WATER CO.  
NEW ROCHELLE WATER CO.  
NEW ROCHELLE WATER CO.  
N. F. DUNLEAVY

Recorder

CONCRETE/MASONRY DAMS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
ANY NOTICEABLE SEEPAGE	N/A	
STRUCTURE TO ABUTMENT/EMBANKMENT JUNCTIONS	N/A	
DRAINS	N/A	
WATER PASSAGES	N/A	
FOUNDATION	N/A	

CONCRETE/MASONRY DAMS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS CONCRETE SURFACES	N/A	
STRUCTURAL CRACKING	N/A	
VERTICAL & HORIZONTAL ALIGNMENT	N/A	
MONOLITH JOINTS	N/A	
CONSTRUCTION JOINTS	N/A	
STAFF GAGE OF RECORDER	N/A	

EMBANKMENT

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS	None observed.	At time of inspection, water level was 6 feet below spillway.
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	None observed.	
SLoughing or Erosion of Embankment and Abutment Slopes		Minor erosion at various locations downstream face.
Vertical and Horizontal Alignment of the Crest		No problems observed.
Riprap Failures		None.

EMBANKMENT

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM	No problem areas observed.	
ANY NOTICEABLE SEEPAGE	Wetness at toe of dam near water storage tank. A number of cattails growing. East abutment below toe next to stairs is a large cavity with some seepage. Clear water flowing.	
STAFF GAGE AND RECORDER	None.	
DRAINS	None.	

UNGATED SPILLWAY

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE WEIR	None.	
APPROACH CHANNEL	None.	
DISCHARGE CHANNEL	None.	
BRIDGE AND PIERS	None.	

GATED SPILLWAY

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE SILL	Fair condition - no problems.	
APPROACH CHANNEL	Front of dam, reservoir surface.	
DISCHARGE CHANNEL	Good condition.	
BRIDGE AND PIERS	Fair condition - no problems.	
GATES AND OPERATION EQUIPMENT	Not well maintained. Suspect sluice gates would be very difficult to operate in case of emergency. One sluice partially open, clogged with heavy debris.	

OUTLET WORKS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	None.	
INTAKE STRUCTURE	Blow-out control rod and fastener broken; is left open. Upper sluice front of structure corroded.	
OUTLET STRUCTURE	In stream bank; discharging approximately 4" deep through a 24" pipe. Drain valve or line is partially obstructed so that the drain will not allow full pipe capacity to flow.	
OUTLET CHANNEL	Good; clear.	
EMERGENCY GATE	None.	

DOWNSTREAM CHANNEL

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONDITION (OBSTRUCTIONS, DEBRIS, ETC.)	Good condition.	
SLOPES	Relatively flat.	
APPROXIMATE NO. OF HOMES AND POPULATION	Philips Restoration below dam. Average weekly visitors to restoration - 1400 people.	

INSTRUMENTATION

VISUAL EXAMINATION OF MONUMENTATION/SURVEYS	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
	None.	
OBSERVATION WELLS	None.	
WEIRS	None.	
PIEZOMETERS	None.	
OTHER	None.	

RESERVOIR

<u>VISUAL EXAMINATION OF</u>	<u>OBSERVATIONS</u>	<u>REMARKS OR RECOMMENDATIONS</u>					
SLOPES	No slope above reservoir.						
SEDIMENTATION	No observed condition.						

**CHECK LIST**  
**ENGINEERING DATA**  
DESIGN, CONSTRUCTION, OPERATION  
PHASE I

NAME OF DAM POCANTICO  
 ID # N.Y. 49

ITEM	REMARKS
AS-BUILT DRAWINGS	None.
REGIONAL VICINITY MAP	See this report.
CONSTRUCTION HISTORY	No data.
TYPICAL SECTIONS OF DAM	See this report.
OUTLETS - PLAN - DETAILS - CONSTRAINTS - DISCHARGE RATINGS	See this report.
RAINFALL/RESERVOIR RECORDS	At Water Plant. Plant has been abandoned. Records show maximum spillway flood 27" on 10/16/55. Rainfall for 12th thru 16th was 0.0, 0.38, 2.32, 6.08, and 0.56 inches. Maximum drawdown was 238" in 11/64.

ITEM	REMARKS
DESIGN REPORTS	None.
GEOLOGY REPORTS	None.
DESIGN COMPUTATIONS HYDROLOGY & HYDRAULICS DAM STABILITY SEEPAGE STUDIES	None.
MATERIALS INVESTIGATIONS BORING RECORDS LABORATORY FIELD	None.
POST-CONSTRUCTION SURVEYS OF DAM	None.
BORROW SOURCES	None disclosed.

ITEM	REMARKS
MONITORING SYSTEMS	None.
MODIFICATIONS	See plans in this report for available data.
HIGH POOL RECORDS	27 in. over spillway in 1955.
POST CONSTRUCTION ENGINEERING STUDIES AND REPORTS	None.
PRIOR ACCIDENTS OR FAILURE OF DAM DESCRIPTION REPORTS	None.
MAINTENANCE OPERATION: RECORDS	In water plant - abandoned plant.

ITEM	REMARKS
SPILLWAY PLAN	See this report.
SECTIONS	
DETAILS	
OPERATING EQUIPMENT PLANS & DETAILS	See this report for available data.

CHECK LIST  
HYDROLOGIC & HYDRAULIC  
ENGINEERING DATA

DRAINAGE AREA CHARACTERISTICS: 11-3/4 square miles

ELEVATION TOP NORMAL POOL (STORAGE CAPACITY): 221.77

ELEVATION TOP FLOOD CONTROL POOL (STORAGE CAPACITY): 221.77

ELEVATION MAXIMUM DESIGN POOL: 225.0

ELEVATION TOP DAM: 225.0

CREST:

- a. Elevation 221.77
- b. Type Concrete apron with chute spillway.
- c. Width -----
- d. Length 75 feet tapers
- e. Location Spillover West abutment
- f. Number and Type of Gates (8) 8'-0" x 4'-0" sluice gates

OUTLET WORKS: (Blow out/draw down pipe)

- a. Type 24" iron pipe
- b. Location Intake chamber thru gate house into stream
- c. Entrance Inverts 188.0 ±
- d. Exit Inverts -----
- e. Emergency Draindown Facilities None

HYDROMETEOROLOGICAL GATES:

- a. Type None
- b. Location None
- c. Records None

MAXIMUM NON-DAMAGING DISCHARGE: -----

APPENDIX B  
PREVIOUS INSPECTION REPORTS  
AND CORRESPONDENCE

SLEEPYHOLLOW RESTORATIONS

RECEIVED

WA 23 1978

AUGUST 23, 1978

August 23, 1978

Mr. Neal F. Dunlevy, P.E.  
Stetson, Dale  
Bankers Trust Building  
Utica, New York 13501

Dear Mr. Dunlevy:

It has come to my attention that you have recently been in our area doing an evaluation of the integrity of the dam of the New Rochelle Water Works Company.

We have always been concerned about the possibility of dam failure upstream from our Philipsburg Manor Restoration.

If you have any information with reference to our possible vulnerability, I would greatly appreciate it if you would share it with me.

Yours truly,

R. W. Doherty  
R. W. Doherty, Director  
Buildings and Grounds

RWD:ab

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDG

2 5 6 47  
2/14

## MEMORANDUM

### On Plans for Proposed Reconstruction of Pocantico Reservoir Dam at Tarrytown, N.Y.

The plans submitted for this dam provide for the raising of the flow line by 8 ft. The present earth dam will be increased by 8.5 ft., while the spillway will be raised 4 ft. by a masonry weir, and 4 ft. additional by eight 8' x 4' sluice gates seating on the crest of the masonry weir. The drainage area at this point as planimetered from U. S. G. S. maps is 12 square miles, and our records show that in this locality a run-off of at least 240 sec. ft. per square mile, or 2880 sec. ft., should be provided for.

With gates closed, the spillway as shown on the plans will have a discharging capacity of about 2140 sec. ft., with a depth of 4.58 ft. on the crest of the spillway. With the water level at the top of the earth dam, the discharging capacity of the spillway orifices would be about 2700 sec. ft. These discharges are both less than the estimated maximum run-off, but considering the pondage effect of the storage in the reservoir above the crest of the dam the out-flow from the reservoir will be greatly reduced.

Assuming a run-off of 10 sec. ft. per square mile from the tributary watersheds to continue at that rate for three hours, and then to gradually fall to a negligible amount within five or six hours, the maximum required discharging capacity of the spillway will be only about 2000 sec. ft. with an in-flow of 2880 sec. ft. Therefore, the spillway shown on the plans may be considered safe

against the greatest flood of which we have any record in this locality. As there are no settlements in the valley of this creek between the reservoir and the Hudson river, life would not be endangered and little property damage would result from the failure of the dam.

With a depth of 4.58 ft. of water on the top of the closed gates, the dam will be stable against overturning, and if the spill-way is set well down into the rock foundation it will be stable against sliding. With this depth of water the free-board of the earth section of the dam will be only 1' 4". This seems to the writer to be rather small, and I think the wall should be raised by at least 2 ft. Otherwise, I see no reason why the application should not be approved.

Yours very truly,

J. C. Cullings

ASSISTANT ENGINEER.

To Mr. A. R. McKim,

Inspector Docks & Dams.

June 12, 1816.

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC

**STATE OF NEW YORK**  
**DEPARTMENT OF STATE ENGINEER AND SURVEYOR**  
**TESTING LABORATORY**  
**A GUIDE**

Tests of Sand from \_\_\_\_\_ bank at \_\_\_\_\_ N. Y.  
 for use on Concrete ~~Standard~~, Res. No. at ~~Pleasant Lake~~ Canal, ~~Construction Com-~~ Division  
~~Conc. Com.~~  
 Contract Sample No. 50 taken \_\_\_\_\_; received at Laboratory July 8; made on July 11.  
 Sand is composed mainly of quartz with some feldspar, hornblende,  
 and glass grains. *Grade of Unica*  
 Percentage of Voids 30.6 ; Loam 3.1 ; Organic matter \_\_\_\_\_  
 Parts of sand to cement by ~~weight~~ <sup>bulk</sup> : 3 sand to 1 cement. Per cent water used 41.  
 Temperature of water used in mixing 79 Fahr. Briquettes kept in moist air 24 hours and then immersed.  
 Cement used in tests, "Standard" Blend. This cement tested as follows:  
 Sets (determined by Vicat needle): Initial, 1 in. 19.5 min. { hard, 1 in. 3.85 min. {  
                                  Minim. requirement, 30 min. } Requirement, 60 to 600 min. }  
 Constancy of Volume Tests:—Normal air Good; Normal water Good; Accelerated Good  
 Fineness (per cent passing sieve of 2,500 meshes per square inch) 99.6 (Requirement, 99%)  
 " (" " " " 10,000 " " " ") 97.4 (Requirement, 92%)

### Remarks:

*A Century that this is a true statement taken from the records of tests.*

July 18, 1926  
J. T. Thompson  
Resident Engineer in Charge of Test

Sketch showing the location of the dam, the river bed, the water level, the elevation of the dam, and the elevation of the water in the reservoir. Show particularly the dam, the river bed, and any area leading up to the dam.

2' 2"

1' to 1'

Dilled  
and fill

No spillway  
elevation

PLATE 1A EDITION

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC


Earth  
Bank

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC

Pocumtico Lake

← ----- 3 MILES ----- →

DA NAM DIV OF M.V.I.



S - C - P - T - O - C - H - E - D

B-12

Pocantico Reservoir  
Investigation of Dam

FILE NO. 13241

Acc. No. 6-2217

APP. 241

SHEET 2

COMPUTER DATE June 8 1962

CHECKED BY OF Planters June 9 1962

MADE IN CONNECTION WITH


REFERENCE

CONT'D FROM ACC. 6-2216

Stability about joint at top of spillway sill - El. 2.6

(No ice pressure - no uplift. Wg = 4)

$$M_o = f_x$$



$$P = \gamma (4.58 + \frac{4}{2}) \times 4 \quad \checkmark$$

$$x = \frac{8.58 + 8.58 \times 4}{3(8.58 + 4.58)} - 2 \times 4.58 = 1.79 \quad \checkmark$$

$$M_o = 1645 \times 1.79 = 2960 \text{ ft-lbf/in. ft.} \quad \checkmark$$

Overturning moment per section 9-7"

$$M_o = 2960 \times 9.58 = 28300 \text{ ft-lbf} \quad \checkmark$$

Resisting MomentTHIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC

$$\text{Loc. Pier } 1.0 \times 2.58 \times 1.58 \times \frac{4.5}{12} \times 4 \times \frac{4}{2} \quad \checkmark$$

$$10400 \quad \checkmark$$

$$5.17 \times 8.58 \times 1.58 \times 1.44 \times \left(4 + \frac{6.58}{2}\right) \quad \checkmark$$

$$66500 \quad \checkmark$$

$$1.75 \times 8.58 \times .75 \times 1.44 \times \left(\frac{10.05}{2} + \frac{4.5}{2}\right) \quad \checkmark$$

$$16300 \quad \checkmark$$

$$6.6 \times .33 \times 9.58 \times 1.44 \times 7.2 \quad \checkmark$$

$$21400 \quad \checkmark$$

$$\text{Floor } \checkmark$$

$$1.67 \times 5.8 \times 9.58 \times 1.44 \times 4.5 \quad \checkmark$$

$$2300 \quad \checkmark$$

$$1.67 \times 6.7 \times 9.58 \times 1.44 \times 8.5 \quad \checkmark$$

$$2300 \quad \checkmark$$

$$1.67 \times 5.8 \times 9.58 \times 1.44 \times 10.5 \quad \checkmark$$

$$700 \quad \checkmark$$

$$Mr = 123000 \text{ ft-lbf} \quad \checkmark$$

Cat. of gates over turnpike

$$\text{Uplift} - H_o = ? = 1645 \times 9.58 = 15750 \text{ ft-lbf} \quad \checkmark$$

$$V_c = 20200$$

$$f = \frac{15750}{20200} = 0.78 \quad \checkmark$$

$$\text{Shear} = \frac{15750}{14.5 / 1.3} = 739 \text{ ft-lbf} \quad \checkmark$$

(Concrete resistance 60.55 ft-lbf/cm<sup>2</sup>, gate 8 ft wide, 10 ft high)  
- must be reinforced

(Concrete resistance 60.55 ft-lbf/cm<sup>2</sup>, gate 8 ft wide, 10 ft high)

**Kocantico Reservoir**  
 SUBJECT: Investigation of proposed dam

FILE NO. D-500-100

ACC. NO. C-2214

SHEET 1

DATE: April 24, 1916  
 COMPUTER: E. Gullings, June 7, 1916  
 CHECKED BY: E. Gullings, June 9, 1916

MADE IN CONNECTION WITH

REFERENCE: Plans submitted by H. J. Ferguson

COPY'D FROM ACC.

Drainage area - estimated to be 12.1 sq. mi. (12.25 sq. miles from 1:250000 scale map)

Discharging capacity required by curve Rec.C1618, = 2400 sec. ft.

$$12.1 \times 240 = 2900 \text{ sec. ft. } \checkmark$$

Spillway - 68 ft long - 8-8 ft. spaces.  $\checkmark$

Proposed flow line, 2.19.0 = Top of gates (closed)  $\checkmark$


" sill 2.15.0  $\checkmark$

Present flow line 2.11.0  $\checkmark$

With sluice gates closed, flood discharge area is limited to 8 spaces 8 ft wide and 4.5 ft high.  $\checkmark$

Discharging capacity =  $64 \times 3.33 \times 4.5^{\frac{3}{2}} = 2100 \text{ sf. } \checkmark$   
 $= 173 \text{ sf. / sq. mi. } \checkmark$

Rather low for this location.



AC 104  
P 1W6

SUBJECT: Pocantico Reservoir  
Investigation of Dam

FILE NO. D-2218-HL

ACC. NO. G-2218

SHEET 3

COMPUTER: 16 June 9 1966 APP# 240  
CHECKED BY: J. - 10 10 16

MADE IN CONNECTION WITH:

REFERENCE:

CONT'D FROM APP# 217

Joint along base

$$M_o = \frac{62.5}{6} (12.58 - 4.5)^2 (12.58 + 2 \times 9.58) = 14400 \text{ ft-lb}$$

$$M_o = 14400 \times 9.58 = 138,700 \text{ ft-lb}$$

$$M_r = (\text{Acc. G-2217}) = 128,000 \text{ ft-lb}$$

$$+ 9.17 \times 4.0 \times 1.58 \times 144 \times (1.8 + \frac{9.17}{2}) = 53,500 \text{ ft-lb}$$

$$+ 1.75 \times 4.0 \times .75 \times 144 \times (11.0 + \frac{9.17}{2}) = 9,600 \text{ ft-lb}$$

(approximate)

$$+ 7 \times 3 \times 8 \times 144 \times 9 = 230,000 \text{ ft-lb}$$

$$\text{Total } M_r = 421,100 \text{ ft-lb OK}$$

Sliding

$$H_o = P = 8(12.58 - \frac{4.5}{2}) \times 7.0 \times 9.58 = 41300 \text{ ft-lb}$$

$$V_L = 2 \times 1.260 + 7350 + 810 - 2 + 200 + 1050 = 64120 \text{ cu ft}$$

$$62.5 \times 2 \times (7.58 + 11.58) \times 8 =$$

$$10200 \text{ ft-lb}$$

Gates, etc., say 8000 cu. ft.

$$\frac{8000}{64120} = 0.125$$

$$f = \frac{41300}{82320} = 0.5 \text{ O.K.}$$

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC

SUBJECT: Pocanfico Reservoir  
Investigation of Dam

FILE NO. 1016

ACQ. NO. C-2-164

Sheet 4

App #240

COMPUTER: Steelings June 9, 1916 CHECKED BY: J. M. JONES 10/16

MADE IN CONNECTION WITH:

REFERENCE:

Spillway

Area present reservoir (211.0) = 25 acres (Report of the Hilltop Engineers)

" proposed " (219.0) = 90 "

211.0 1,090,000 ✓

219.0 3,092,000 ✓

225.0 (Top dam) (estimated) 4,600,000 23,000,000 cu. ft. capacity between total gates and top of dam.

Assumed Capacity Curve of Res.

Area.

Elev.	Area	Vol.	Int. Vol.
219.0	3.10	0	0
221.0	3.67	6.77	6.77
223.0	4.24	7.81	"
225.0	4.81	14.58	"
		9.04	"
		23.62	"

Capacity

M.C.F. 50

Assumptions as to rainfa and run-off

Drainage Area - 12 sq. mi.

Max. distance from dam 6 mi.

Velocity of flow in creek 5' sec.

Time of max. concentration, 105 min, say 2 hr.

Rainfall - max. rainfall, 6 in. in 3 hr. (Res. E-2810)

Runoff, 50% = 3 in. in 3 h. = 11 in. per hr.

Max. rate of run-off - at end of

$$\frac{12 \times 27,000 \text{ cu. in.}}{3,600 \times 72} = 2 \text{ in.} = 7700 \text{ sec. ft.}$$

Hydrograph of assumed run-off.

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DOD

SUBJECT: Pocantico Reservoir  
Investigation of Dam

FILE NO. 6-2269

ACC. NO. 6-2270

APP # 240

SHEET 45

COMPUTER SITE June 9 1966

CHECKED BY

Editor June 11 1966

MADE IN CONNECTION WITH

CONT'D FROM APP C-7269

REFERENCE

Pondage effect on rate of spillway discharge


Spillway discharge computed from:  $Q = 3.4 L H^{1.7}$ ,  $L = 64$

$H = 0.1$	$Q = 6 \text{ sec. ft.}$
= 0.2	19 ✓
= 0.5	76 ✓
1.0	218 ✓
2.0	610 ✓
3.0	1130 ✓
4.0	1740 ✓
4.5	2140 ✓

$$Q = A(0.1 \cdot 1296)(h = 6.0 - 2.26 = 3.71) ( = 4.58 \cdot 8 \times 8 \times 0.6 \times 7.64 \cdot 3.71)$$

$$H = 6.0 \quad 2720$$

Curve showing rate of spillway discharge



THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC

217

SUBJECT: Pocantico Reservoir  
Investigation of Dam

FILE NUMBER

...ACQ. NO. C-2271

**August** 16.

APP #240

COMPUTER


June 9

CHECKED BY

MADE IN CONNECTION WITH

RECENTS

Assuming Max. Flood of 140 s.f./sq.mi. (7680 s.f.) at end of 2 hr  
Hydrograph of assumed inflow (Curve 'A', Acq. 4-22-59)



THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC

July 24, 1918.

Mr. Secretary of War:

Dear Sir:

Enclosed:

Enclosed is a copy of my report to the Lower Division

of the Bureau of Navigation and Personnel on duty

The report is composed of figures taken with some latitude,  
but based upon the best information available. The percentage  
of ships damaged, however, is probably fairly well graded.  
The number of ships damaged is not enough to give the average  
percentage of damage to all ships, but it is close to the average  
of ships damaged, and it is not far from the average of ships with a  
severe damage record. The average, say 10%, which gives a fair  
picture.

Very truly yours,

John D. Coffey, Commissioner,

Acting

Bureau of Navigation

Enc.

APPENDIX C  
HYDROLOGIC AND HYDRAULIC COMPUTATIONS

DALE

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC

## DESIGN BRIEF

DESIGNED BY JPGDATE 8-7-78

CHECKED BY \_\_\_\_\_

PAGE C-1 OF \_\_\_\_\_PROJECT NO. 2210 SHORT TITLE NY DAM INSPECTIONSNON SUBJECT POCANTICO LAKE DAM

REF. DWG#.

ESTIMATE OF CLARK'S PARAMETERESTIMATE OF  $T_C$  (BPR)

$$T_C = (11.9 L^{3/4})^{.375} = (11.9 (5.11)^3 / 411)^{.375} = 1.602 \text{ HR}$$

SCS

$$L = \frac{g^{.8} (341)^7}{1900 Y^{.5}} = \frac{(27000)^{.8} (3.8 \cdot 1)^7}{1900 (1.5)^5} \\ = \frac{10656.319}{2327.015} = 4.579$$

$$S = 1000 - 10 = 309 \\ Cu$$

$$T_C = L / 6 = 4.579 / 6 = 0.763 \text{ HR}$$

NORTH ATLANTIC DIV WATER RESOURCES STUDY (FEB 72)

$$(T_C + R) = 10 (a) (D_A/S)^{.5} \\ = 10 (1.82) (10.492 / 2)^{.25} = 15.30$$

$$R / (T_C + R) = .39$$

$$R / 15.30 = .39$$

$$R = 5.97$$

$$5.97 / (T_C + 5.97) = .39$$

$$5.97 = .39 (T_C + 5.97)$$

$$5.97 = .39 T_C + 2.33$$

$$9.33 = T_C$$

**DALE**THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC**DESIGN BRIEF**

DESIGNED BY \_\_\_\_\_

DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_

PAGE C-2 OF \_\_\_\_\_PROJECT NO. 2210SHORT TITLE NY DAM INSPECTIONDESIGN SUBJECT POCANTICO LAKE DAM

REF. DWUS. \_\_\_\_\_

ESTIMATE OF SNYDER'S PARAMETERS

$$640 \quad C_p =$$

$$C_p = 0.625$$

$$C_T = 1.2 \text{ assumed}$$

$$t_P = C_T (L \times L_C)^{0.3}$$

$$t_P = 1.2 (5.1 \times 2.6)^{0.3}$$

$$t_P = 2.6$$

$$t_r = t_P / 3.2 = .47$$

$$t_{Pr} = t_P + 0.25(t_r - t_P)$$

$$t_{Pr} = 2.6 + 0.25(0.5)$$

$$t_{Pr} = 2.73$$

SUMMARY OF PARAMETERSCLARK'S

BPR

$$T_E = 1.63 \text{ hours}$$

SCS (CN METHOD)

$$T_C = 7.63 \text{ hours}, R = 4.98$$

NORTH ATLANTIC DR

$$T_C = 7.53 \text{ hours}, R = 5.97$$

$$R / (T_C + R) = 0.39$$

SNYDER'S

$$t_{Pr} = 2.73$$

$$C_p = 0.625$$

DALE

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC

## DESIGN BRIEF

DESIGNED BY \_\_\_\_\_

DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_

PAGE C-3 OF \_\_\_\_\_PROJECT NO. 2210 SHORT TITLE NY DAM INSPECTIONSDESIGN SUBJECT POCANTICO LAKE DAM

REF. DWBS. \_\_\_\_\_

D-A-D - RELATIONSHIPSDURATIONDEPTH% OF INDEX

6 Hr.  
12 Hr.  
24 Hr.  
48 Hr.  
72 Hr.

25.<sup>"</sup>  
29.  
32.  
36.  
38.-?

107  
122  
137  
151  
159

Index is 1.0

240 .

Base Flow

200.19g. mi = 21 ft

Loss Rates

INITIAL LOSS = 1.0  
CONSTANT LOSS = 0.5

**DALE**

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC

**DESIGN BRIEF**

DESIGNED BY \_\_\_\_\_

DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_

PAGE C-4 OF \_\_\_\_\_

PROJECT NO. \_\_\_\_\_

SHORT TITLE \_\_\_\_\_

DESIGN SUBJECT \_\_\_\_\_

REF. DWGS. \_\_\_\_\_

Summary of "NCUW" 17-1

SPF	Clarks Parameters	TG 763, R 4.03	<u>6831</u>
	Snyder's "	TGF 3.13 R 2.19	<u>11400</u>
PMF	Clarks Parameters		<u>14000</u>
	Snyder's Parameters		<u>23500</u>

Prob.

UNIT GRAPH AND HYDROGRAPH COMP JULY 1966 (REVISED AUGUST 1974)  
HYDROLOGIC ENGINEERING CENTER (HEC)  
DAVIS, CA

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC

--- OPERATIONS AVAILABLE ---

TIME INT = SET TIME INTERVAL OF ALL COMPUTATIONS  
UNIT H = COMPUTE UH BY INPUT, CLARK, OR SNYDER  
RAIN = INPUT RAIN AND LOSS RATE DATA  
RUNOFF = INPUT BASEFLOW, COMPUTE & PRINT HYDROGRAPH  
PNT = PRINT UNIT HYDROGRAPH ONLY  
STOP = STOP EXECUTION OF PROGRAM

USER MUST SELECT OPERATION DESIRED  
MAY RETURN TO ANY OPERATION

SELECT 1-6 (1=TIME INT,2=UNIT H,3=RAIN,4=RUNOFF,5=PNT,'6=STOP) 1  
ENTER TIME INTERVAL(MIN)= 60.

SELECT 1-6 (1=TIME INT,2=UNIT H,3=RAIN,4=RUNOFF,5=PNT,'6=STOP) 2  
ENTER DRAINAGE AREA (SQMI) = 10.50  
SELECT 1-3 (1=INPUT UH, 2=CLARK, 3=SNYDER ) 2  
ENTER NUMBER OF TIME-AREA ORDINATES (0=NONE)= 0  
ENTER CLARKS TC AND R (HRS) = 7.63 4.88

TF	CP	TC	R
6.35	0.683	7.63	4.88

SELECT 1-6 (1=TIME INT,2=UNIT H,3=RAIN,4=RUNOFF,5=PNT,'6=STOP) 3  
ENTER RATIO IMPERVIOUS = 0.00  
SELECT 1-3 ( 1=RAIN, 2=SPS, 3=PLS ) 2  
ENTER SPS INDEX RAINFALL (IN) = 12.00  
ENTER TRSPC AND TRSDA (SQMI) = 1.00 10.50  
SELECT 1-3 (1=INIT+CONST, 2=ACUM LOSS, 3=SCS) 1  
ENTER INITIAL LOSS(IN), CONSTANT LOSS(IN/HR) = 1.00 0.10

SELECT 1-6 (1=TIME INT,2=UNIT H,3=RAIN,4=RUNOFF,5=PNT,'6=STOP) 4  
ENTER A TITLE PLEASE - POCANTICO SPP  
ENTER STRTQ, QRCSEN, AND RTIOR = 21.00 21.00 1.00

HR	MIN	RAIN	LOSS	EXCESS	UNIT HG	RECSN	FLOW
1	0	0.00	0.00	0.00	42.	21.	21.
2	0	0.00	0.00	0.00	154.	21.	21.
3	0	1.00	0.60	0.00	303.	21.	21.
4	0	0.00	0.00	0.00	465.	21.	21.
5	0	0.00	0.00	0.00	603.	21.	21.
6	0	0.00	0.00	0.00	699.	21.	21.
7	0	0.01	0.01	0.00	749.	21.	21.
8	0	0.01	0.01	0.00	611.	21.	21.
9	0	0.01	0.01	0.00	571.	21.	21.
10	0	0.01	0.01	0.00	469.	21.	21.
11	0	0.01	0.01	0.00	384.	21.	21.
12	0	0.01	0.01	0.00	311.	21.	21.
13	0	0.03	0.03	0.00	253.	21.	21.

C-5

15	0	1.05	0.05	0.00	168.	21.	21.
16	0	0.12	0.12	0.00	137.	21.	21.
17	0	0.04	0.04	0.00	112.	21.	21.
18	0	0.03	0.03	0.00	91.	21.	21.
19	0	0.01	0.01	0.00	74.	21.	21.
20	0	0.01	0.01	0.00	66.	21.	21.
21	0	0.01	0.01	0.00	49.	21.	21.
22	0	0.01	0.01	0.00	40.	21.	21.
23	0	0.01	0.01	0.00	33.	21.	21.
24	0	0.01	0.01	0.00	27.	21.	21.
25	0	0.02	0.02	0.00	22.	21.	21.
26	0	0.02	0.02	0.00	18.	21.	21.
27	0	0.02	0.02	0.00	15.	21.	21.
28	0	0.02	0.02	0.00	12.	21.	21.
29	0	0.02	0.02	0.00	10.	21.	21.
30	0	0.02	0.02	0.00	8.	21.	21.
31	0	0.04	0.04	0.00	7.	21.	21.
32	0	0.04	0.04	0.00		21.	21.
33	0	0.04	0.04	0.00		21.	21.
34	0	0.04	0.04	0.00		21.	21.
35	0	0.04	0.04	0.00		21.	21.
36	0	0.04	0.04	0.00		21.	21.
37	0	0.14	0.14	0.00		21.	21.
38	0	0.16	0.13	0.03		21.	22.
39	0	0.20	0.10	0.10		21.	30.
40	0	0.51	0.10	0.41		21.	63.
41	0	0.19	0.10	0.09		21.	132.
42	0	0.15	0.10	0.05		21.	226.
43	0	0.03	0.03	0.00		21.	328.
44	0	0.03	0.03	0.00		21.	419.
45	0	0.03	0.03	0.00		21.	479.
46	0	0.03	0.03	0.00		21.	498.
47	0	0.03	0.03	0.00		21.	472.
48	0	0.03	0.03	0.00		21.	413.
49	0	0.12	0.10	0.02		21.	347.
50	0	0.12	0.10	0.02		21.	291.
51	0	0.12	0.10	0.02		21.	248.
52	0	0.12	0.10	0.02		21.	217.
53	0	0.12	0.10	0.02		21.	196.
54	0	0.12	0.10	0.02		21.	184.
55	0	0.32	0.10	0.22		21.	185.
56	0	0.32	0.10	0.22		21.	212.
57	0	0.32	0.10	0.22		21.	269.
58	0	0.32	0.10	0.22		21.	360.
59	0	0.32	0.10	0.22		21.	480.
60	0	0.32	0.10	0.22		21.	618.
61	0	1.02	0.10	0.92		21.	792.
62	0	1.23	0.10	1.13		21.	1044.
63	0	1.54	0.10	1.44		21.	1416.
64	0	3.89	0.10	3.79		21.	2045.
65	0	1.43	0.10	1.33		21.	2997.
66	0	1.13	0.10	1.03		21.	4140.
67	0	0.20	0.10	0.10		21.	5296.
68	0	0.20	0.10	0.10		21.	6236.
69	0	0.20	0.10	0.10		21.	6767.
70	0	0.20	0.10	0.10		21.	6831.
71	0	0.20	0.10	0.10		21.	6428.
72	0	0.20	0.10	0.10		21.	5697.
73	0	0.01	0.01	0.00		21.	4873.
74	0	0.01	0.01	0.00		21.	4101.
75	0	0.01	0.01	0.00		21.	3436.
76	0	0.01	0.01	0.00		21.	2872.
77	0	0.01	0.01	0.00		21.	2391.
78	0	0.01	0.01	0.00		21.	1978.
79	0	0.02	0.12	0.00		21.	1626.

THIS PAGE IS BEST QUALITY PRACTICABLE  
PRINTED ON DRAFTING PAPER

80	0	0.02	0.02	0.00	21.	1331.
81	0	0.02	0.02	0.00	21.	1089.
82	0	0.02	0.02	0.00	21.	891.
83	0	0.02	0.02	0.00	21.	730.
84	C	0.02	0.02	0.00	21.	599.
85	C	0.05	0.05	0.00	21.	493.
86	C	0.06	0.06	0.00	21.	405.
87	C	0.08	0.08	0.00	21.	333.
88	0	0.20	0.10	0.10	21.	279.
89	0	0.07	0.07	0.00	21.	243.
90	C	0.06	0.06	0.00	21.	219.
91	0	0.01	0.01	0.00	21.	204.
92	0	0.01	0.01	0.00	21.	189.
93	0	0.01	0.01	0.00	21.	173.
94	0	0.01	0.01	0.00	21.	153.
95	0	0.01	0.01	0.00	21.	117.
96	C	0.01	0.01	0.00	21.	94.
97	0				21.	75.
98	0				21.	64.
99	0				21.	56.
100	0				21.	49.
101	0				21.	43.
102	0				21.	38.
103	0				21.	35.
104	0				21.	32.
105	0				21.	30.
106	0				21.	28.
107	C				21.	27.
108	C				21.	26.
109	0				21.	25.
110	0				21.	24.
111	0				21.	24.
112	0				21.	23.
113	0				21.	23.
114	0				21.	22.
115	0				21.	22.
116	0				21.	22.
117	0				21.	22.
118	0				21.	22.
119	0				21.	21.
120	0				21.	21.
121	0				21.	21.
122	0				21.	21.
123	0				21.	21.
124	0				21.	21.
125	0				21.	21.
126	0				21.	21.

TOTAL      17.10    4.70 12.40    67.0.      2646.      86877.

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC

SELECT 1-6 (1=TIME INT,2=UNIT H,3=RAIN,4=RUNOFF,5=PNT,'6=STOP) 1  
ENTER TIME INTERVAL(MIN)= 60.

SELECT 1-6 (1=TIME INT,2=UNIT H,3=RAIN,4=RUNOFF,5=PNT,'6=STOP) 2  
ENTER DRAINAGE AREA (SQMI) = 10.50

SELECT 1-3 (1=INPUT UH, 2=CLARK, 3=SNYDER) 3  
ENTER SNYDERS CP AND TP (HRS) = 0.62 2.73  
ENTER INITIAL EST. CLARKS TO & (HRS) (0=DEFAULT)= 0.00 0.00

TP	CP	TC	R
2.39	0.586	3.12	2.05
2.64	0.647	3.23	2.12
2.71	0.639	3.23	2.17
2.72	0.633	3.23	2.19
2.72	0.630	3.23	2.19

SELECT 1-6 (1=TIME INT,2=UNIT H,3=RAIN,4=RUNOFF,5=PNT,'6=STOP) 3  
ENTER RATIO IMPERVIOUS = 0.00  
SELECT 1-5 ( 1=RAIN, 2=SPS, 3=PMS ) 2  
ENTER SPS INDEX RAINFALL (IN) = 12.00  
ENTER TRFC AND TRSDA (SQMI) = 1.00 10.50  
SELECT 1-3 (1=INIT+CONST, 2=ACUM LOSS, 3=SCS) 1  
ENTER INITIAL LOSS(IN), CONSTANT LOSS(IN/HR) = 1.00 0.10

SELECT 1-6 (1=TIME INT,2=UNIT H,3=RAIN,4=RUNOFF,5=PNT,'6=STOP) 4  
ENTER A TITLE PLEASE - POCANTICO SFF  
ENTER STFTQ,QRCSEN,AND RTIOR = 21.00 21.00 1.00

HR	MIN	RAIN	LOSS	EXCESS	UNIT HG	RECSN	FLOW
1	0	0.00	0.00	0.00	306.	21.	21.
2	0	0.00	0.00	0.00	103..	21.	21.
3	0	0.00	0.00	0.00	156..	21.	21.
4	0	0.00	0.00	0.00	140..	21.	21.
5	0	0.00	0.00	0.00	91..	21.	21.
6	0	0.00	0.00	0.00	57..	21.	21.
7	0	0.01	0.01	0.00	36..	21.	21.
8	0	0.01	0.01	0.00	22..	21.	21.
9	0	0.01	0.01	0.00	143..	21.	21.
10	0	0.01	0.01	0.00	96..	21.	21.
11	0	0.01	0.01	0.00	57..	21.	21.
12	0	0.01	0.01	0.00	36..	21.	21.
13	0	0.03	0.03	0.00	23..	21.	21.
14	0	0.04	0.04	0.00	15..	21.	21.
15	0	0.05	0.05	0.00		21.	21.
16	0	0.12	0.12	0.00		21.	21.
17	0	0.04	0.04	0.00		21.	21.
18	0	0.03	0.03	0.00		21.	21.
19	0	0.01	0.01	0.00		21.	21.

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DOD

C-8

20	0	0.01	0.01	0.00	21.	21.
21	0	0.01	0.01	0.00	21.	21.
22	0	0.01	0.01	0.00	21.	21.
23	0	0.01	0.01	0.00	21.	21.
24	0	0.01	0.01	0.00	21.	21.
25	0	0.02	0.02	0.00	21.	21.
26	0	0.02	0.02	0.00	21.	21.
27	0	0.02	0.02	0.00	21.	21.
28	0	0.02	0.02	0.00	21.	21.
29	0	0.02	0.02	0.00	21.	21.
30	0	0.02	0.02	0.00	21.	21.
31	0	0.04	0.04	0.00	21.	21.
32	0	0.04	0.04	0.00	21.	21.
33	0	0.04	0.04	0.00	21.	21.
34	0	0.04	0.04	0.00	21.	21.
35	0	0.04	0.04	0.00	21.	21.
36	0	0.04	0.04	0.00	21.	21.
37	0	0.14	0.14	0.00	21.	21.
38	0	0.16	0.13	0.03	21.	30.
39	0	0.20	0.10	0.10	21.	63.
40	0	0.51	0.10	0.41	21.	297.
41	0	0.19	0.10	0.09	21.	671.
42	0	0.15	0.10	0.05	21.	939.
43	0	0.03	0.03	0.00	21.	698.
44	0	0.03	0.03	0.00	21.	670.
45	0	0.03	0.03	0.00	21.	453.
46	0	0.03	0.03	0.00	21.	294.
47	0	0.03	0.03	0.00	21.	193.
48	0	0.03	0.03	0.00	21.	129.
49	0	0.12	0.10	0.02	21.	95.
50	0	0.12	0.10	0.02	21.	91.
51	0	0.12	0.10	0.02	21.	106.
52	0	0.12	0.10	0.02	21.	124.
53	0	0.12	0.10	0.02	21.	135.
54	0	0.12	0.10	0.02	21.	139.
55	0	0.32	0.10	0.22	21.	206.
56	0	0.32	0.10	0.22	21.	417.
57	0	0.32	0.10	0.22	21.	733.
58	0	0.32	0.10	0.22	21.	1015.
59	0	0.32	0.10	0.22	21.	1200.
60	0	0.32	0.10	0.22	21.	1316.
61	0	1.02	0.10	0.92	21.	1603.
62	0	1.23	0.10	1.13	21.	2436.
63	0	1.54	0.10	1.44	21.	3873.
64	0	3.89	0.10	3.79	21.	6243.
65	0	1.43	0.10	1.33	21.	9349.
66	0	1.13	0.10	1.03	21.	11436.
67	0	0.20	0.10	0.10	21.	10947.
68	0	0.20	0.10	0.10	21.	8635.
69	0	0.20	0.10	0.10	21.	6118.
70	0	0.20	0.10	0.10	21.	4137.
71	0	0.20	0.10	0.10	21.	2860.
72	0	1.20	0.10	0.10	21.	2057.

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC

C-9

73	0	0.01	0.01	0.00	21.	1522.
74	0	0.01	0.01	0.00	21.	1161.
75	0	0.01	0.01	0.00	21.	738.
76	0	0.01	0.01	0.00	21.	467.
77	0	0.01	0.01	0.00	21.	289.
78	0	0.01	0.01	0.00	21.	156.
79	0	0.02	0.02	0.00	21.	94.
80	0	0.02	0.02	0.00	21.	57.
81	0	0.02	0.02	0.00	21.	43.
82	0	0.02	0.02	0.00	21.	34.
83	0	0.02	0.02	0.00	21.	28.
84	0	0.02	0.02	0.00	21.	25.
85	0	0.05	0.05	0.00	21.	22.
86	0	0.06	0.06	0.00	21.	21.
87	0	0.08	0.08	0.00	21.	21.
88	0	0.10	0.10	0.00	21.	52.
89	0	0.07	0.07	0.00	21.	124.
90	0	0.06	0.06	0.00	21.	178.
91	0	0.01	0.01	0.00	21.	161.
92	0	0.01	0.01	0.00	21.	113.
93	0	0.01	0.01	0.00	21.	79.
94	0	0.01	0.01	0.00	21.	57.
95	0	0.01	0.01	0.00	21.	44.
96	0	0.01	0.01	0.00	21.	35.
97	0				21.	30.
98	0				21.	27.
99	0				21.	25.
100	0				21.	23.
101	0				21.	22.
102	0				21.	21.
103	0				21.	21.
104	0				21.	21.
105	0				21.	21.
106	0				21.	21.
107	0				21.	21.
108	0				21.	21.
109	0				21.	21.

TOTAL      17.16    4.70    12.46      675.      2289.      86459.

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC

SELECT 1-6 (1=TIME INT, 2=UNIT H, 3=RAIN, 4=RUNOFF, 5=PNT, '6=STOP) 1  
ENTER TIME INTERVAL(MIN)= 60.

SELECT 1-6 (1=TIME INT, 2=UNIT H, 3=RAIN, 4=RUNOFF, 5=PNT, '6=STOP) 2  
ENTER DRAINTAGE AREA (SQMI) = 10.50

SELECT 1-3 (1=INPUT UH, 2=CLARK, 3=SNYDER ) 3

ENTER SNYDERS CP AND TP (HRS) = 0.62 2.73

ENTER INITIAL EST. CLARKS TO & (HRS) (0=DEFAULT)= 0.00 0.00

TP	CP	TC	R
2.39	0.586	3.12	2.05
2.64	0.647	3.23	2.12
2.71	0.639	3.23	2.17
2.72	0.633	3.23	2.19
2.72	0.630	3.23	2.19

SELECT 1-6 (1=TIME INT, 2=UNIT H, 3=RAIN, 4=RUNOFF, 5=PNT, '6=STOP) 3  
ENTER RATIO IMPERVIOUS = 1.00

SELECT 1-3 (1=RAIN, 2=SIS, 3=PMS ) 3

ENTER PMS INDEX RAINFALL (IN) = 4.00

ENTER R6, R12, R24, R48, R72, R96 = 107.00 122.00 137.00 151.00 159.00

ENTER TRSEC AND TRSDA (SQMI) = 0.00 10.50

SELECT 1-3 (1=INIT+CONST, 2=ACUM LOSS, 3=SCS) 1

ENTER INITIAL LOSS(IN), CONSTANT LOSS(IN/HR) = 1.00 0.10

SELECT 1-6 (1=TIME INT, 2=UNIT H, 3=RAIN, 4=RUNOFF, 5=PNT, '6=STOP) 4  
ENTER A TITLE PLEASE - POCAINTI PMF

ENTER STT10, QHCSN, AND RTTOR = 21.0 21.00 1.00

HR	MIN	RAIN	LOSS	EXCESS	UNIT HG	RECSN	FLCW
1	0	0.02	0.02	0.00	30.	21.	21.
2	0	0.02	0.02	0.00	103.	21.	21.
3	0	0.02	0.02	0.00	156.	21.	21.
4	0	0.02	0.02	0.00	140.	21.	21.
5	0	0.02	0.02	0.00	91.	21.	21.
6	0	0.02	0.02	0.00	57.	21.	21.
7	0	0.05	0.05	0.00	36.	21.	21.
8	0	0.05	0.05	0.00	22.	21.	21.
9	0	0.05	0.05	0.00	14.	21.	21.
10	0	0.05	0.05	0.00	9.	21.	21.
11	0	0.05	0.05	0.00	5.	21.	21.
12	0	0.05	0.05	0.00	3.	21.	21.
13	0	0.21	0.21	0.00	2.	21.	21.
14	0	0.25	0.25	0.00	1.	21.	21.
15	0	0.32	0.18	0.14		21.	64.
16	0	0.80	0.10	0.70		21.	380.
17	0	0.29	0.10	0.19		21.	1021.
18	0	0.23	0.10	0.13		21.	1550.
19	0	0.03	0.03	0.00		21.	1563.
20	0	0.03	0.03	0.00		21.	1213.

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DOQ

21	0	0.03	0.03	0.06	21.	831.
22	0	0.03	0.03	0.00	21.	535.
23	0	0.03	0.03	0.00	21.	344.
24	0	0.03	0.03	0.00	21.	224.
25	0	0.19	0.10	0.09	21.	177.
26	0	0.19	0.10	0.09	21.	222.
27	0	0.19	0.10	0.09	21.	333.
28	0	0.19	0.10	0.09	21.	441.
29	0	0.19	0.10	0.09	21.	510.
30	0	0.19	0.10	0.09	21.	549.
31	0	0.48	0.10	0.38	21.	666.
32	0	0.48	0.10	0.38	21.	985.
33	0	0.48	0.10	0.38	21.	1452.
34	0	0.48	0.10	0.38	21.	1867.
35	0	0.48	0.10	0.38	21.	2138.
36	0	0.48	0.10	0.38	21.	2308.
37	0	2.06	0.10	1.96	21.	2899.
38	0	2.47	0.10	2.37	21.	4724.
39	0	3.09	0.10	2.99	21.	7854.
40	0	7.82	0.10	7.72	21.	12829.
41	0	2.88	0.10	2.78	21.	19211.
42	0	2.26	0.10	2.16	21.	23446.
43	0	2.29	0.10	0.19	21.	22532.
44	0	0.29	0.10	0.19	21.	17798.
45	0	2.29	0.10	0.19	21.	12585.
46	0	2.29	0.10	0.19	21.	8464.
47	0	2.29	0.10	0.19	21.	5807.
48	0	2.29	0.10	0.19	21.	4137.
49	0	0.01	0.01	0.00	21.	3028.
50	0	0.01	0.01	0.00	21.	2172.
51	0	0.01	0.01	0.00	21.	1445.
52	0	0.01	0.01	0.00	21.	904.
53	0	0.01	0.01	0.00	21.	551.
54	0	0.01	0.01	0.00	21.	285.
55	0	0.03	0.03	0.00	21.	162.
56	0	0.03	0.03	0.00	21.	90.
57	0	0.03	0.03	0.00	21.	63.
58	0	0.03	0.03	0.00	21.	46.
59	0	0.03	0.03	0.00	21.	35.
60	0	0.03	0.03	0.00	21.	28.
61	0	0.12	0.10	0.02	21.	30.
62	0	0.14	0.10	0.04	21.	54.
63	0	0.16	0.10	0.06	21.	118.
64	0	0.46	0.10	0.36	21.	305.
65	0	0.17	0.10	0.07	21.	614.

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDG

66	0	0.13	0.10	0.03	21.	827.
67	0	0.02	0.02	0.00	21.	770.
68	0	0.02	0.02	0.00	21.	561.
69	0	0.02	0.02	0.00	21.	376.
70	0	0.02	0.02	0.00	21.	245.
71	0	0.02	0.02	0.00	21.	162.
72	0	0.02	0.02	0.00	21.	110.
73	0				21.	77.
74	0				21.	56.
75	0				21.	43.
76	0				21.	35.
77	0				21.	29.
78	0				21.	23.
79	0				21.	21.
80	0				21.	21.
81	0				21.	21.
82	0				21.	21.
83	0				21.	21.
84	0				21.	21.
85	0				21.	21.

TOTAL      30.60    4.90 25.70      6755.      1785.      175393.

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC

C-13

SELECT 1-6 (1=TIME INT, 2=UNIT H, 3=RAIN, 4=RUNOFF, 5=PNT, \*6=STOP) 1  
ENTER TIME INTERVAL(MIN)= 60.

SELECT 1-6 (1=TIME INT, 2=UNIT H, 3=RAIN, 4=RUNOFF, 5=PNT, \*6=STOP) 2  
ENTER DRAINAGE AREA (SQMI) = 10.50  
SELECT 1-3 (1=INPUT UH, 2=CLARK, 3=SNYDER ) 2  
ENTER NUMBER OF TIME-AREA ORDINATES (U=NONE)= C  
ENTER CLARKS TC AND R (HRS) = 7.63 4.68

TP	CP	TC	R
6.35	0.063	7.63	4.68

SELECT 1-6 (1=TIME INT, 2=UNIT H, 3=RAIN, 4=RUNOFF, 5=PNT, \*6=STOP) 3  
ENTER RATIO IMPERVIOUS = 0.00  
SELECT 1-3 ( 1=RAIN, 2=SFS, 3=PMIS ) 3  
ENTER PMIS INDEX RAINFALL (IN) = 24.00  
ENTER R6,R12,R24,R48,R72,R96 = 107.00 122.00 137.00 151.00 159.00  
ENTER TRFC AND TRSDA (SQMI) = 0.00 10.50  
SELECT 1-3 (1=INIT+CONST, 2=ACUM LOSS, 3=SCS) 1  
ENTER INITIAL LOSS(IN), CONSTANT LOSS(IN/HR) = 1.00 0.10

SELECT 1-6 (1=TIME INT, 2=UNIT H, 3=RAIN, 4=RUNOFF, 5=PNT, \*6=STOP) 4  
ENTER A TITLE PLEASE - POCANTICO PMF  
ENTER STETQ,QRCSN,AND RT10R = 21.00 21.00 1.00

HR	MIN	RAIN	LOSS	EXCESS	UNIT	IG	RECSN	FLOW
1	0	0.02	0.02	0.00	42.		21.	21.
2	0	0.02	0.02	0.00	15.		21.	21.
3	0	0.02	0.02	0.00	30.		21.	21.
4	0	0.02	0.02	0.00	46.		21.	21.
5	0	0.02	0.02	0.00	60.		21.	21.
6	0	0.02	0.02	0.00	69.		21.	21.
7	0	0.05	0.05	0.00	72.		21.	21.
8	0	0.05	0.05	0.00	68.		21.	21.
9	0	0.05	0.05	0.00	57.		21.	21.
10	0	0.05	0.05	0.00	46.		21.	21.
11	0	0.05	0.05	0.00	38.		21.	21.
12	0	0.05	0.05	0.00	31.		21.	21.
13	0	0.21	0.21	0.00	25.		21.	21.
14	0	0.25	0.25	0.00	20.		21.	21.
15	0	0.32	0.18	0.14	16.		21.	27.
16	0	0.80	0.10	0.70	137.		21.	72.
17	0	0.29	0.10	0.19	112.		21.	179.
18	0	0.23	0.10	0.13	91.		21.	333.
19	0	0.03	0.03	0.00	74.		21.	509.
20	0	0.03	0.03	0.00	60.		21.	672.
21	0	0.03	0.03	0.00	49.		21.	789.
22	0	0.03	0.03	0.00	40.		21.	838.
23	0	0.03	0.03	0.00	3.		21.	08.
24	0	0.03	0.03	0.00	2.		21.	714.
25	0	0.19	0.10	0.09	2.		21.	604.
26	0	0.19	0.10	0.09	18.		21.	513.
27	0	0.19	0.10	0.09	15.		21.	453.
28	0	0.19	0.10	0.09	12.		21.	423.
29	0	0.19	0.10	0.09	11.		21.	419.
30	0	0.19	0.10	0.09	1.		21.	434.
31	0	0.48	0.10	0.38	.		21.	473.
32	0	0.48	0.10	0.38	.		21.	548.
33	0	0.48	0.10	0.38	.		21.	662.

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC

C-14

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC

34	0	0.48	0.10	0.38	21.	818.
35	0	0.48	0.10	0.38	21.	1012.
36	0	0.48	0.10	0.38	21.	1229.
37	0	2.06	0.10	1.96	21.	1518.
38	0	2.47	0.10	2.37	21.	1986.
39	0	3.09	0.10	2.99	21.	2729.
40	0	7.02	0.10	7.72	21.	4025.
41	0	2.88	0.10	2.78	21.	6001.
42	0	2.20	0.10	2.10	21.	8383.
43	0	0.29	0.10	0.19	21.	10796.
44	0	0.29	0.10	0.19	21.	12757.
45	0	0.29	0.10	0.19	21.	13868.
46	0	0.29	0.10	0.19	21.	14006.
47	0	0.29	0.10	0.19	21.	13179.
48	0	0.29	0.10	0.19	21.	11674.
49	0	0.01	0.01	0.00	21.	9968.
50	0	0.01	0.01	0.00	21.	8372.
51	0	0.01	0.01	0.00	21.	6996.
52	0	0.01	0.01	0.00	21.	5836.
53	0	0.01	0.01	0.00	21.	4847.
54	0	0.01	0.01	0.00	21.	4003.
55	0	0.03	0.03	0.00	21.	3286.
56	0	0.03	0.03	0.00	21.	2685.
57	0	0.03	0.03	0.00	21.	2191.
58	0	0.03	0.03	0.00	21.	1790.
59	0	0.03	0.03	0.00	21.	1463.
60	0	0.03	0.03	0.00	21.	1196.
61	0	0.12	0.10	0.02	21.	980.
62	0	0.14	0.10	0.04	21.	806.
63	0	0.18	0.10	0.08	21.	672.
64	0	0.46	0.10	0.36	21.	587.
65	0	0.17	0.10	0.07	21.	556.
66	0	0.13	0.10	0.03	21.	560.
67	0	0.02	0.02	0.00	21.	584.
68	0	0.02	0.02	0.00	21.	598.
69	0	0.02	0.02	0.00	21.	592.
70	0	0.02	0.02	0.00	21.	557.
71	0	0.02	0.02	0.00	21.	467.
72	0	0.02	0.02	0.00	21.	387.
73	0				21.	312.
74	0				21.	257.
75	0				21.	213.
76	0				21.	176.
77	0				21.	146.
78	0				21.	122.
79	0				21.	102.
80	0				21.	87.
81	0				21.	75.
82	0				21.	65.
83	0				21.	57.
84	0				21.	50.
85	0				21.	45.
86	0				21.	40.
87	0				21.	37.
88	0				21.	34.
89	0				21.	32.

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC

90	0	21.	30.
91	0	21.	28.
92	0	21.	27.
93	0	21.	26.
94	0	21.	24.
95	0	21.	22.
96	0	21.	21.
97	0	21.	21.
98	0	21.	21.
99	0	21.	21.
100	0	21.	21.
101	0	21.	21.
102	0	21.	21.

TOTAL    30.60    4.90    25.70    67' 0.    2142.    175876.

C-16

**DALE**

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC

**DESIGN BRIEF**

DESIGNED BY NFO

DATE 8-7-78

CHECKED BY \_\_\_\_\_

PAGE 6-17 OF \_\_\_\_\_

PROJECT NO. \_\_\_\_\_ SHORT TITLE \_\_\_\_\_

DESIGN SUBJECT PC (initials)

REF. DWGS. \_\_\_\_\_

SPECIMEN PA. 3. CURVE

5. 1000 ft over bridge +  
Q = - 11.72

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

DALE

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDO

## DESIGN BRIEF

DESIGNED BY NFDDATE 8.7.78

CHECKED BY \_\_\_\_\_

PAGE C8 OF \_\_\_\_\_

PROJECT NO. \_\_\_\_\_ SHORT TITLE \_\_\_\_\_

DESIGN SUBJECT IMPS. HCU

REF. DWGS. \_\_\_\_\_

SPILLWAY N.ZNC - NOVEL

a. Design Curve Gate Con.

$$Q = 2/3 \sqrt{2g} CL$$

$$L = 38.8 = 6$$

$$1 + \frac{g/H_1}{C} = \frac{2/3 \sqrt{2g}}{L}$$

5.21

Total Head in feet

$$H_1 = H_2$$

$$A_1 = A_2 = 0$$

$$H_1^{3/2} H_2^{1/2} (H_1^{3/2} - H_2^{3/2}) Q$$

5  
1  
2  
3  
4  
5

6	.7	.64	211
7	.6	.65	223
8	.5	.67	231
9	.45	.67	232
10	.4	.68	233
11	.36	.68	234
12	.33	.69	235
13	.31	.69	237
14	.28	.69	237
15	.27	.69	237
16	.25	.70	240
17	.23	.70	240

14.7	2.8	11.9	2611
18.5	5.2	13.3	2961
22.6	8.0	14.0	33
27.0	1.2	15.5	36
31.2	14.7	16.5	39
36.0	13.5	18.0	42
41.6	22.6	19.0	4503
46.0	27.0	19.9	4716
51.2	31.6	20.8	4930
56.7	36.5	22.4	5309
64.0	41.6	22.4	5376
70.0	46.9	23.2	5563

**DALE**

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC

**DESIGN BRIEF**

DESIGNED BY NFD

DATE 8-7-78

CHECKED BY \_\_\_\_\_

PAGE C-19 OF \_\_\_\_\_

PROJECT NO. \_\_\_\_\_ SHORT TITLE \_\_\_\_\_

DESIGN SUBJECT 1 Can't REF. DWGS. \_\_\_\_\_

C. H. 1000 5000 10000 10000  
H E L H 2 G  
1 2.64 4K 1 1000  
L  
3  
4  
5  
6  
7

↓      ↓

2.6 3063  
5.2 5628  
8.0 8659  
11.2 12122  
14.7 16152  
18. 20024

**DALE**

**DESIGN BRIEF**

DESIGNED BY NFO

DATE 87-78

HECKED BY \_\_\_\_\_

PAGE C-20 OF \_\_\_\_\_

PROJECT NO. \_\_\_\_\_ SHORT TITLE \_\_\_\_\_


DESIGN SUBJECT FC ACT 71 D REF. DWGS. \_\_\_\_\_

STAGE - DISCHARGE

TOTAL AREA

DESC.	ELEV.	H	Q*	SP16	VARY	G	DAM	Q	TOT
	215	0						0	
	216	1	26					205	
	217	2	56					597	
	218	3	11					1131	
	219	4	17					1792	
	220	5	27					2576	
	221	6	26					2618	
	222	7	22					2966	
	223	8	33					335	
	224	9	36					3634	
TOT. CAV.	225	10	32					355	
	226	11	42				1182	5794	
	227	12	45				3663	7526	
	228	13	41				5628	10344	
	229	14	49				8619	13799	
	230	15	53				1222	17431	
	231	16	53				652	21528	
	232	17	55				2024	25592	

\* SLUICE GATES COMPLETE Y OPEN.



00100 A POCANTICO

0110 A RESERVOIR ROUTING OVER STRUCTURE OF SPF

0120 A SERVICE SPILLWAY ONLY - GATES FULLY OPEN

0130 B 60 1

0140 1 3

0150 K 0

0160 M -1 10.5

0170 N 21 22 30 63 132 226 328 419 479 498

0180 N 472 413 347 291 248 217 193 184 185 212

0190 N 269 360 480 618 798 1044 1416 2045 2997 4140

0200 N 5296 6236 6767 6831 6428 5697 4873 4101 3436 2872

0210 N 2391 1978 1626 1331 1089 891 730 599 493 405

0220 N 333 279 243 219 204 189 173 153 117 94

0230 K 1

0240 Y 1

0250 1 1 -1

0260 2 0 50 100 320 750 840 960 1020 1080 1120

0270 3 0 205 597 2576 5274 10344 13589 17431 21528 25592

0280 K 99

0290 A

0300 A

0310 A

00100 A POCANTICO

0110 RESERVOIR ROUTING OVER STRUCTURE OF PMF

0120 A SERVICE SPILLWAY ONLY - GATES FULLY OPEN

0130 B 60 1

0140 1 3

0150 K 0

0160 M -1 10.5

0170 N 21 27 72 179 333 509 672 789 838 888

0180 N 714 604 513 453 423 419 434 473 548 662

0190 N 818 1012 1229 1518 1986 2729 4025 6001 8383 10796

0200 N 12757 13868 14006 13179 11674 9968 8372 6996 5836 4847

0210 N 4003 3286 2685 2191 1790 1463 1196 980 806 672

0220 N 587 556 560 584 598 592 557 467 387 312

0230 K 1

0240 Y 1

0250 1 1 -1

0260 2 0 50 100 320 750 840 960 1020 1080 1120

0270 3 0 205 597 2576 5294 10344 13589 17431 21528 25592

0280 K 99

0290 A

0300 A

0310 A

#SAVE

C-22

PROJEC NO. 41

POCANTICO

RESERVOIR ROUTING OVER STRUCTURE OF SPF  
SERVICE SPILLWAY ONLY - GATES FULLY OPEN

## JOB SPECIFICATION

NO	NHR	NNIN	IDAY	IHR	IMIN	METRC	IPLT	IPRT	NSTAN
60	1	0	0	0	0	0	0	0	0
	JOPER	NWT							
	3	0							

## SUB-AREA RUNOFF COMPUTATION

ISTAQ	ICOMP	IECON	ITAPE	JPLT	JPRT	INAME
0	0	0	0	0	0	0

## HYDROGRAPH DATA

IHYDG	IUNG	TAREA	SNAP	TRSDA	TRSPC	RATIO	ISNOW	ISAME	LOCAL
-1	0	10.50	0.0	0.0	0.0	0.0	0	0	0

## INPUT HYDROGRAPH

21.	22.	30.	63.	132.	226.	328.	419.	479.	498.
472.	413.	347.	291.	248.	217.	193.	184.	185.	212.
269.	360.	480.	618.	798.	1044.	1416.	2045.	2997.	4146.
5296.	6236.	6767.	6831.	6428.	5697.	4873.	4101.	3436.	2872.
2391.	1978.	1626.	1331.	1089.	891.	736.	599.	493.	405.
333.	279.	243.	219.	204.	189.	173.	153.	117.	94.

CFS	PEAK	6-HOUR	2-HOUR	72-HOUR	TOTAL VOLUME
	6831.	6209.	51.	1420.	85221.
INCHES		5.50	11.17	12.58	12.58
AC-FT		3081.	4254.	7047.	7047.

## HYDROGRAPH ROUTING

ISTAQ	ICOMP	IECON	ITAPE	JPLT	JPRT	INAME
0	1	0	0	0	0	0

## ROUTING DATA

GLOSS	CLOSS	Avg	IRES	ISAME
0.0	0.0	0.0	1	0

NSTPS	NSTDL	LAG	AMSKK	X	TSK	STORA
1	0	0	0.0	0.0	0.0	-1.

STORAGE	0.	50.	100.	320.	750.	840.	960.	1020.	1080.	1120.
OUTFLOWS	0.	205.	597.	2576.	5294.	10344.	13589.	17431.	21528.	25592.

TIME	EOP STOR	Avg IN	EOP OUT
1	5.	21.	21.
2	5.	22.	21.
3	6.	26.	23.
4	7.	47.	29.
5	12.	98.	49.
6	21.	179.	87.
7	35.	277.	142.
8	51.	374.	212.
9	66.	449.	328.
10	76.	489.	406.

C-23

11	81.	485.	445.
12	80.	443.	444.
13	76.	380.	413.
14	71.	319.	367.
15	65.	270.	319.
16	59.	233.	277.
17	55.	205.	242.
18	51.	189.	216.
19	49.	185.	202.
20	49.	199.	201.
21	52.	241.	218.
22	58.	315.	265.
23	67.	420.	341.
24	80.	549.	443.
25	97.	708.	573.
26	118.	921.	759.
27	146.	230.	1014.
28	190.	731.	1402.
29	257.	521.	2009.
30	354.	1569.	788.
31	480.	4718.	1588.
32	623.	5766.	1490.
33	752.	6502.	5392.
34	787.	6799.	7358.
35	769.	6630.	6340.
36	762.	6063.	5952.
37	737.	5285.	5213.
38	690.	4487.	4912.
39	615.	3769.	4438.
40	530.	154.	3906.
41	447.	632.	3378.
42	369.	185.	2884.
43	300.	102.	2392.
44	245.	79.	1897.
45	203.	1210.	1525.
46	171.	990.	1235.
47	145.	811.	1005.
48	125.	65.	820.
49	108.	146.	672.
50	95.	449.	555.
51	83.	369.	464.
52	73.	306.	387.
53	65.	261.	325.
54	59.	231.	279.
55	55.	212.	246.
56	52.	197.	222.
57	50.	181.	203.
58	47.	163.	191.
59	43.	135.	175.
60	38.	106.	155.

SUN

84855.

C-24

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	7358.	5861.	3140.	1414.	84855.
INCHES		5.19	11.13	12.53	12.53
AC-FT		2908.	6232.	7016.	7016.

RUNOFF SUMMARY: AVERAGE FLOW

HYDROGRAPH AT ROUTED TO	PEAK	6-HOUR	24-HOUR	72-HOUR	AREA
0	6831.	6209.	3151.	1420.	10.50
0	7358.	5861.	3140.	1414.	10.50

POCANTICO  
RESERVOIR ROUTING OVER STRUCTURE OF PMF  
SERVICE SPILLWAY ONLY - GATES FULLY OPEN

## **JOB SPECIFICATION**

NO	NHR	NNIN	IDAY	IHF	IMIN	METRC	IPLT	IPRT	NSTAN
66	1	8	8	8	8	8	8	8	8
			JOPER		NWT				
				3	1				

#### **SUB-AREA RUMBLE COMPUTATION**

ISTAQ	ICOMP	IECON	IAPE	JPLT	JPRT	INAME
1	1	1	1	1	1	1

## **HYDROGRAPH DATA**

IHYDC IUHC TAREA SNAP HYDROGRAPHIC DATA TRSDA TRSPC RATIO ISNOW ISAME LOCAL

### **INPUT HYDROGRAPH**

21.	27.	72.	179.	333.	509.	672.	789.	838.	888.
714.	604.	513.	453.	423	419.	434.	473.	548.	662.
818.	1012.	1229.	1518.	1986.	2729.	4025.	6001.	8383.	10796.
12757.	13868.	14006.	13179.	11674.	9968.	8372.	6996.	5836.	4847.
4003.	3286.	2685.	2191.	1790.	1463.	1196.	980.	806.	672.
587.	556.	560.	584.	598.	592.	557.	467.	387.	312.

**PEAK      6-HOUR      1-HOUR      72-HOUR      TOTAL VOLUME**

	PERIOD	WATER	WATER	WATER	WATER
CFS	14866.	12713.	100.	396.	13763.
INCHES		11.26	1.68	5.66	25.66
AC-FT		6307.	100.	14368.	14368.

#### **HYDROGRAPHIC ROUTING**

HYDROGRAPHIC ROUTING  
ISTAQ ICOMP IECON I APE JPRT JPRT INAME

ROUTINE DATA

**GLOSS**   **CLOSS**   **WC**   **IRES**   **ISAMM**

MSTPS	MSTDL	LAG	MSKK	X	TSK	STORA
1	1	0	0.0	0.0	0.0	-1.

STORAGE# 0. 50. 100. 320. 750. 840. 960. 1020. 1080. 1120.  
OUTFLOW# 0. 105. 597. 2574. 294. 1344. 13589. 17431. 21528. 25592.

TIME	EOP	STOR	AVG IN	EOP OUT
1		5.	21.	21.
2		5.	24.	22.
3		7.	50.	36.
4		14.	126.	58.
5		28.	256.	115.
6		50.	421.	204.
7		74.	591.	392.
8		95.	731.	558.
9		111.	814.	692.
10		118.	823.	763.

C-76

11	118.	761.	762.
12	112.	659.	706.
13	103.	559.	626.
14	94.	483.	553.
15	87.	438.	497.
16	82.	421.	460.
17	80.	427.	443.
18	81.	454.	448.
19	85.	511.	479.
20	93.	605.	541.
21	105.	740.	643.
22	121.	915.	790.
23	141.	1121.	969.
24	166.	1374.	1188.
25	200.	1752.	1494.
26	252.	2358.	1962.
27	338.	3377.	2693.
28	491.	5013.	3654.
29	722.	7192.	5119.
30	857.	9590.	10803.
31	895.	11777.	11831.
32	953.	13313.	13395.
33	968.	13937.	14109.
34	954.	13593.	13422.
35	915.	12427.	12371.
36	854.	10821.	10735.
37	810.	9170.	8675.
38	786.	7684.	7290.
39	764.	6416.	6069.
40	739.	5342.	5222.
41	686.	4425.	4892.
42	605.	3645.	4375.
43	514.	2986.	3800.
44	424.	2438.	3236.
45	343.	1991.	2720.
46	275.	1627.	2172.
47	224.	1330.	1715.
48	187.	1088.	1375.
49	157.	893.	1114.
50	135.	739.	911.
51	118.	630.	758.
52	107.	572.	657.
53	101.	558.	603.
54	99.	572.	587.
55	99.	591.	589.
56	99.	595.	592.
57	98.	575.	583.
58	94.	512.	548.
59	86.	427.	489.
60	78.	350.	421.

SUM 172940.

CFS	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
INCHES	14109.	12655.	6380.	2882.	172940.
AC-FT		11.21	22.61	25.54	25.54
		6278.	12662.	14300.	14300.

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

C-27

RUNOFF SUMMARY AVERAGE FLOW

HYDROGRAPH AT ROUTED TO	PEAK	6-HOUR	24-HOUR	72-HOUR	AREA
	14006.	12713.	6400.	2896.	10.50
	14109.	12655.	6380.	2882.	10.50

c-28

APPENDIX D  
REFERENCES

## APPENDIX D

THIS PAGE IS BEST QUALITY PRACTICABLE  
FROM COPY FURNISHED TO DDC

REFERENCES

1. Department of the Army, Office of the Chief of Engineers. National Program of Investigation of Dams; Appendix D: Recommended Guidelines for Safety Inspection of Dams, 1976
2. The University of the State of New York - The State Education Department - State Museum and Science Service - Geological Survey: Geological Map of New York (1970)
3. U.S. Nuclear Regulatory Commission: Design Basis Floods for Nuclear Power Plants, Regulating Guide 1.59, Revision 2, August 1977
4. Water Resources Engineers, Inc., Lower Hudson River Basin, Hydrologic Flood Routing Model, January 1977
5. Linsley and Franzini: Water Resources Engineering, Second Edition, McGraw-Hill (1972)
6. Louis C. Schreiner and John T. Riedel: Hydrometeorological Report No. 51, U.S. Department of Commerce, National Oceanic and Atmospheric Administration National Weather Service, Office of Hydrology; Silver Springs, Maryland, September 1976
7. Ven Te Chow: Handbook of Applied Hydrology, McGraw-Hill, 1964
8. The Hydrologic Engineering Center: Computer Program 723-X6-L2010, HEC-1 Flood Hydrograph Package, User's Manual, Corps of Engineers, U.S. Army, 609 Second Street, Davis, California 95616, January 1973
9. The Hydrologic Engineering Center, Art Pabst: Computer Program UHCOMP, Unpublished, Corps of Engineers, U.S. Army, 609 Second Street, Davis, California 95616
10. North Atlantic Regional Water Resources Study Coordinating Committee: Appendix C, Climate, Meteorology and Hydrology, February 1972
11. Soil Conservation Service (Engineering Division): Urban Hydrology for Small Watersheds, Technical Release No. 55, U.S. Department of Agriculture, January 1975
12. Sherard, Woodward, Gizienski, Clevenger: Earth and Earth - Rock Dams, John Wiley and Sons, Inc., 1963
13. H.W. King, E.F. Brater: Handbook of Hydraulics, McGraw-Hill, 5th Edition, 1963

14. Ven Te Chow: Open Channel Hydraulics, McGraw-Hill, 1959
15. Bureau of Reclamation, United States Department of the Interior, Design of Small Dams: A Water Resources Technical Publication, Third Printing, 1965
16. Preliminary Brittle Structures Map of New York, New York State Geological Survey, 1977

