

AD-A070 835


O'BRIEN AND GERE ENGINEERS INC PHILADELPHIA PA JUSTIN--ETC F/G 13/2  
NATIONAL DAM INSPECTION PROGRAM. PENN LAKE DAM (NDI ID NUMBER P--ETC(U)  
MAR 79

DACW31-79-C-0010

NL

UNCLASSIFIED

1 OF 1  
AD  
A070 835



END  
DATE  
FILED

8 - 79  
DDC

**LEVEL**  
DELAWARE RIVER BASIN  
WRIGHT CREEK, LUZERNE COUNTY

B/S  
1

PENNSYLVANIA

**PENN LAKE DAM**

NDI-PA 00542  
PA DER 40-28


ADA070835  
**PHASE I INSPECTION REPORT**  
**NATIONAL DAM INSPECTION PROGRAM**



Distribution Unlimited  
Approved for Public Release  
Contract No. DACW31-79-C-0010



Prepared By  
**O'BRIEN & GERE**  
Justin & Courtney Division  
PHILADELPHIA, PENNSYLVANIA  
19103



FOR

DEPARTMENT OF THE ARMY  
BALTIMORE DISTRICT CORPS OF ENGINEERS  
BALTIMORE, MARYLAND  
21203

MARCH 19 1979 05 101

Accession For	
NTIS GRA&I	<input checked="" type="checkbox"/>
DDC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification _____	
By _____	
Distribution/ _____	
Availability Codes	
Dist	Avail and/or special
A	

DELAWARE RIVER BASIN

Name of Dam: Penn Lake Dam  
 County & State: Luzerne County, Pennsylvania  
 Inventory Number: PA 00542

(6) National Dam Inspection Program, Penn  
 Lake Dam (NDI ID Number PA-00542, DER  
 ID Number 48-28), Delaware River Basin,  
 Wright Creek, Luzerne County,  
 Pennsylvania, Phase I Inspection Report.

(11) Mar  
79

PHASE I INSPECTION REPORT  
 NATIONAL DAM INSPECTION PROGRAM

(12) Mar P.

(15) DACW34-79-C-0010

Prepared by:

O'BRIEN & GERE ENGINEERS, INC.  
 JUSTIN & COURTNEY DIVISION

For:

DEPARTMENT OF THE ARMY  
 Baltimore District, Corps of Engineers  
 Baltimore, MD 21203

410 760

slk

## PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigations, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected, and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the spillway design flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The spillway design flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

PHASE I REPORT  
NATIONAL DAM INSPECTION PROGRAM

Name of Dam: Penn Lake Dam ID # PA 00542  
State Located: Pennsylvania  
County Located: Luzerne  
Stream: Wright Creek  
Coordinates: Latitude  $41^{\circ} 05.4'$ , Longitude  $75^{\circ} 46.8'$   
Date of Inspection: December 14, 1979

ASSESSMENT

Penn Lake Dam, owned by Carolyn D. and Robert H. Raymond (Penn Lake Association), is an earth embankment approximately 350 feet long and 44 feet high at its maximum section. The spillway consists of twelve 42-inch diameter, 20-foot long pipes located approximately 1,000 feet left (looking downstream) of the dam. Earth swales on both sides of the battery of pipes function as auxiliary spillways. The 56 acre reservoir is used for recreation by members of the Penn Lake Association.

Examination of the results of the hydrologic and hydraulic analyses indicates that the spillway (pipes and swales) is capable of passing 48 per cent of the Probable Maximum Flood (PMF) without overtopping of the embankment. Failure of the dam would increase the hazard of loss of life downstream of the dam. The capacity of the spillway system is therefore classified as "Seriously Inadequate". The dam is considered to be unsafe (non-emergency).

Based on visual observations made during the date of the inspection, the dam is considered to be in poor condition. There are seeps and rust colored water along the toe of the downstream embankment slope. The entire region immediately downstream of the dam is swampy. Bulges, depressions and embankment sloughing are evident on the downstream slope of the embankment. There are cut brush, stumps, and debris over the entire downstream slope. The upstream slope of the embankment is covered with heavy brush and there is a depression (Plate 4, Appendix E) near the left abutment. The riprap protection on the upstream and downstream slopes of the embankment is poorly graded and sparse in many areas.

Recommendations and remedial measures are as follows:

a. Facilities

1. The capacity of the spillway system should be increased in accordance with the results of detailed hydrologic and hydraulic studies.

2. A subsurface investigation program should be initiated to determine the composition and in situ properties of the earth embankment and foundation materials and to determine the stability of the dam. The investigations should be supervised by a licensed professional engineer experienced in the design and construction of dams.

3. Piezometers should be installed in the boreholes to evaluate pore pressure development throughout the earth embankment and aid in determining the source of the seeps all along the toe of the downstream earth embankment slope.

4. The area at the downstream end of the reservoir drain system should be cleared of silt and debris. The drain system should then be appraised and repaired as needed. A means of positive closure at the upstream end of the reservoir drain system should be developed.

5. All brush, stumps, debris, etc. should be removed from the dam.

6. Decisions concerning the need to supplement the riprap protection, raise the top of the dam, and add additional spillway facilities, should await the results of the drilling program and further hydrologic/hydraulic analyses.

b. Operation and Maintenance Procedures

1. A downstream warning system should be developed; and during periods of heavy rainfall, the dam should be monitored and downstream residents alerted in the event of an impending failure.

2. The owner should develop and implement a maintenance and inspection checklist to insure that all items are maintained on a regular basis.

O'BRIEN & GERE ENGINEERS, INC.  
JUSTIN & COURTNEY DIVISION

Will M. Heiser  
Will M. Heiser, P.E.  
Vice-President  
Pennsylvania Registration # 0069264



Date: 16 Apr. 1979

Approved by:

G. R. Withers  
G. R. WITHERS  
Colonel, Corps of Engineers  
District Engineer

Date: 14 May 1979



UPSTREAM VIEW OF THE DAM



DOWNSRAME VIEW OF THE DAM

## TABLE OF CONTENTS

	<u>PAGE</u>
<b>SECTION 1 - PROJECT INFORMATION</b>	
1.1 General	1
1.2 Description	1
1.3 Pertinent Data	2
<b>SECTION 2 - ENGINEERING DATA</b>	
2.1 Design	4
2.2 Construction	4
2.3 Operation	4
2.4 Evaluation	4
<b>SECTION 3 - VISUAL INSPECTION</b>	
3.1 Findings	5
<b>SECTION 4 - OPERATIONAL FEATURES</b>	
4.1 Procedures	6
4.2 Maintenance of the Dam	6
4.3 Maintenance of Operating Facilities	6
4.4 Warning System in Effect	6
4.5 Evaluation	6
<b>SECTION 5 - HYDRAULICS AND HYDROLOGY</b>	
5.1 Evaluation of Features	7
<b>SECTION 6 - STRUCTURAL STABILITY</b>	
6.1 Evaluation of Structural Stability	8
<b>SECTION 7 - ASSESSMENT, RECOMMENDATIONS, PROPOSED REMEDIAL MEASURES</b>	
7.1 Dam Assessment	9
7.2 Recommendations, Remedial Measures	9

TABLE OF CONTENTS  
(Continued)

PLATES

APPENDIX A -	CHECKLIST, ENGINEERING DATA, DESIGN CONSTRUCTION, OPERATION, PHASE I
APPENDIX B -	CHECKLIST, VISUAL INSPECTION, PHASE I
APPENDIX C -	HYDROLOGIC & HYDRAULIC DATA
APPENDIX D -	PHOTOGRAPHS
APPENDIX E -	DRAWINGS
APPENDIX F -	SITE GEOLOGY

PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM  
PENN LAKE DAM  
NDI I.D. NO. PA-00542  
DER #40-28

SECTION 1  
PROJECT INFORMATION

1.1 General

a. Authority. The Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of inspection of dams throughout the United States.

b. Purpose of Inspection. The purpose of this inspection is to evaluate the structural and hydraulic conditions of the Penn Lake dam and appurtenant structures, and to determine if the dam constitutes a hazard to human life or property.

1.2 Description of Project (Information obtained from the Pennsylvania Department of Environmental Resources (DER), Dam Safety Division)

a. Penn Lake Dam is an earth embankment, approximately 350 feet in length with a maximum height of 44 feet. The dam impounds a reservoir with a surface area of 56 acres and a storage capacity of 246 acre-feet at normal pool level. The top of the dam is 20 feet wide, the downstream side slope is approximately 1.75 horizontal to 1.0 vertical (1.75H:1V), and the upstream side slope is approximately 3H:1V. No information is available concerning the properties of the embankment materials. The upstream and downstream slopes of the dam are riprapped with 12 to 18 inches of stone.

The spillway consists of a battery of twelve, 42-inch diameter, 20-foot long, steel pipes located approximately 1,000 feet left (looking downstream) of the dam. Earth swales on both sides of the battery of pipes function as auxiliary spillways. The road, which is located around the perimeter of the lake, extends over the spillway pipes and across the top of the dam.

The reservoir drain system consists of a 36-inch steel pipe with a sluice valve located at the downstream toe of the dam. The sluice valve is housed in a concrete block structure.

b. Location. Penn Lake Dam is located on Wright Creek at a point about 4 miles north of White Haven, in Dennison Township, Luzerne County, Pennsylvania. The dam site is shown on the USGS Quadrangle entitled "White Haven, Pennsylvania" at coordinates N 41° 05.4', W 75° 46.8'. A regional location plan of Penn Lake Dam is enclosed as Plate 1, Appendix E.

c. Size Classification. Penn Lake Dam has a storage capacity of 80 million gallons (246 acre-feet) and a maximum height of 44 feet. The structure is in the intermediate size category.

d. Hazard Classification. There are about 12 private residences in the valley between Penn Lake Dam and the Lehigh River (a distance of about  $2\frac{1}{2}$  miles). The topography downstream of the dam is such that flood waters would be directed towards these homes resulting in probable loss of lives and extensive property damage. Therefore, the structure is in the "High" hazard category.

e. Ownership. The dam is owned by Carolyn J. and Robert H. Raymond (Penn Lake Association), Star Route Box 226, White Haven, Pennsylvania, 18661.

f. Purpose of Dam. The dam was originally built in 1905 for ice pondage. The reservoir is now used for recreation by the members of the Penn Lake Association.

g. Design and Construction History. The dam was built in 1905 by S.S. Staples for ice pondage. H.S. Smith of Wilkes Barre was the designer.

h. Normal Operating Procedures. The lake is normally maintained at Elevation 1333.0. The owner was not available to operate the reservoir drain sluice valve during the day of inspection.

### 1.3 Pertinent Data (From information supplied by Pennsylvania DER & USGS)

a. <u>Drainage Area</u> (square miles)	7.0
b. <u>Discharge at Dam Site</u> (cfs)	
Reservoir drain system at normal pool Elev. 1333.0	130
Reservoir drain system at top of dam Elev. 1337.5	140
Ungated spillway at top of dam Elev. 1337.5	3,440
Total spillway capacity at top of dam Elev. 1337.5	3,580
c. <u>Elevation</u> (feet above MSL)	
Spillway crest (normal, recreation pool)	1333.0
Top of dam (at low point of top of dam)	1337.5
Reservoir Drain Invert (inlet)	1299.0
Reservoir Drain Invert (outlet)	1298.0 +
Streambed at centerline of dam	1298.0 +
Maximum tailwater	1305.0 +

d.	<u>Reservoir</u> (miles)	
	Length of normal, recreation pool	0.61
	Length of maximum non-overtopping pool	0.63
	Fetch at normal pool	0.33
e.	<u>Storage</u> (acre-feet)	
	Normal, recreation pool, Elev. 1333.0	246
	Top of dam at low point, Elev. 1337.5	500
f.	<u>Reservoir Surface Area</u> (acres)	
	Normal, recreation pool, Elev. 1333.0	56
	Top of dam at low point, Elev. 1337.5	71
g.	<u>Dam Data</u>	
	Type	Earth
	Length	350 feet
	Height	44 feet (maximum)
	Top width	20 feet
	Side Slopes	3H:1V (upstream); 1.75H:1V (downstream)
	Zoning	No
	Impervious core	No
	Cutoff	No
	Grout Curtain	No
h.	<u>Spillway</u>	
	Type	12, 42-inch steel pipes, Earth swales on each side of the steel pipe spillway acts as an auxiliary spillway.
	Width	42 feet at spring line of pipes plus swales 200 feet.
	Length	20 feet
	Crest elevation	1333.0+
	Gates	None
	Upstream channel	About 30 feet long, rock bottom, 2H:1V side slopes.
	Downstream channel	Follows a natural draw through a heavily wooded region.
i.	<u>Outlet Works</u>	
	Type	36-inch steel pipe
	Length	230 feet +
	Closure	Sluice valve at downstream end.
	Access	Intake is submerged; outlet structure and operating mechanism are at the downstream toe.
	Regulating facilities	Hand operated sluice valve.

SECTION 2  
ENGINEERING DATA

2.1 Design

a. Data Available. The information available for review of Penn Lake Dam includes the following (all information obtained from the Pennsylvania DER main office files in Harrisburg, Pennsylvania):

1. Dam inspection reports beginning in 1912 and through the following years.
2. Photographs beginning in 1912 and through the following years.
3. "Application for Permit to Draw Dam or Other Body of Water in Accordance with the Act of 12-15-59", 1971.
4. Miscellaneous correspondence.
5. Sheet showing shoreline of reservoir prepared in 1949.

b. Design Features. The design features are discussed in Section 1.2.a and shown on Plates 3, 4, and 5 of Appendix E.

2.2 Construction

The dam was built in 1905 by S.S. Staples for ice pondage. H.S. Smith of Wilkes Barre was the designer.

2.3 Operation

Operation procedures appear to be limited to those necessary to draw down the reservoir by means of the sluice valve located in a concrete block shed at the downstream toe of the dam. There is no evidence that operating procedures have been written for this structure.

2.4 Evaluation

a. Availability. Very limited material is available. The one sketch of the impoundment area is enclosed as Plate 2 in Appendix E.

b. Adequacy. Although design and construction information is minimal, a Phase I evaluation is considered reasonable based on the revealing conditions observed during the field inspection.

c. Validity. There appears to be no reason to question the validity of the limited data available.

## SECTION 3

### VISUAL INSPECTION

#### 3.1 Findings

a. General. The field inspection of the Penn Lake Dam took place on December 14, 1978. The reservoir water surface elevation was approximately 1333.0 during the inspection. No underwater areas were inspected. The observations and comments of the field inspection team are in the checklist which is Appendix B of this report. The appearance of the facility indicates that the dam and its appurtenances are marginally maintained.

b. Dam. There are numerous bulges and depressions of more than a foot which form an undulating pattern along both the upstream and downstream slopes and the top of the dam. A survey revealed that the top of the dam elevation varies as much as 4.5 feet along the 350-foot length of the embankment. There is also some embankment sloughing on the downstream slope. It is difficult to appraise the extent of the undulations, sloughing, and what is left of the riprap facing on both the upstream and downstream slopes of the dam because of cut trees and debris on the slopes. There are seeps and murky rust colored water along the toe of the downstream embankment slope. The entire region immediately downstream of the dam is swampy.

c. Appurtenant Structures. The spillway, which consists of a battery of twelve 42-inch diameter, 20-foot long pipes, located approximately 1,000 feet left (looking downstream) of the dam, is seriously inadequate. There are no trashracks upstream of the spillway pipes to prevent debris from reducing the flow. Earth swales on both sides of the battery of pipes function as auxiliary spillways.

The sluice valve of the reservoir drain system is assumed to be in a partially opened position judging from the amount of water flowing in the vicinity of the concrete block structure which houses the sluice valve.

d. Reservoir. Area reconnaissance of the reservoir disclosed no evidence of excessive siltation, slope instability, or other features that would significantly affect the storage capacity of the reservoir. The slopes along the perimeter of the reservoir are vegetated and on gradients of less than ten per cent.

e. Downstream Channel. For about 80 per cent of the 2.5 miles from Penn Lake Dam to the Lehigh River, Wright Creek flows through a heavily wooded region. The balance of the distance is through meadows. There is one highway bridge about 2 miles downstream of the dam. The channel gradient averages about 1.4 per cent for the entire 2.5 miles. There are about a dozen homes within the potential damage area along Wright Creek downstream of Penn Lake Dam.

## SECTION 4

### OPERATIONAL FEATURES

#### **4.1 Procedures**

Operational procedures have been covered in Section 1.2.h. Written operating procedures were not made available. Normal operating procedures for this structure do not require a dam tender.

#### **4.2 Maintenance of the Dam**

Attempts to contact the owner of the dam were unsuccessful. The dam appears to be marginally maintained.

#### **4.3 Maintenance of Operating Facilities**

No operating mechanism for the sluice gate was visible during the inspection. It is assumed that any operating mechanism would be housed in the inaccessible concrete block structure at the downstream end of the reservoir drain conduit. The sluice valve is maintained by the Penn Lake Association. Further discussion of the maintenance of the sluice valve is covered in Section 2.3.

#### **4.4 Warning System in Effect**

There is no evidence that a formal warning system or procedures to be followed during periods of exceedingly heavy rainfall is in effect.

#### **4.5 Evaluation of Operational Adequacy**

The operation and maintenance procedures appear to be marginal for the Penn Lake Dam. An operation and maintenance check list should be developed and implemented by the owner.

A formal warning system should be implemented because of the probability of loss of life and extensive property damage downstream in the event of a failure of the dam.

The dam is accessible under all weather conditions for inspection and emergency action.

SECTION 5  
HYDRAULICS AND HYDROLOGY

5.1 Evaluation of Features

a. Design Data. There is no original design information available. The drainage area contributing to Penn Lake Dam is about 4.5 miles long and averages about 1.5 miles wide. Ground elevations range from 2060 to 1333. The slopes of the watershed adjacent to the reservoir are all less than ten per cent. The watershed is nearly 100 per cent wooded. The runoff characteristics of the watershed may undergo change in the future as a result of development.

The spillways are capable of handling a discharge of 3440 cfs. However, the SDF for this "Intermediate" size dam, with a "High" hazard classification, is the PMF which has a peak inflow of 7690 cfs and a peak outflow of 7630 cfs. The PMF hydrograph was routed through the reservoir with the starting water surface elevation at the crest of the spillway, Elev. 1333.0. The maximum water surface elevation in the reservoir resulting from the PMF routing would be 5.6 feet above the spillway crest and 1.1 feet above the lowest point of the top of the dam.

For further information, refer to the computations, data, and printouts included in Appendix C.

b. Experience Data. There is no evidence that rainfall or water level records are kept for this dam.

c. Visual Observations. The major spillway elements, which consist of twelve, 42-inch steel pipes and adjacent earth swales, showed no visible signs of deterioration.

Further observations are given in Appendix B.

d. Overtopping Potential. The SDF is the PMF for this "Intermediate" size, "High" hazard structure. Examination of the results of the hydrologic and hydraulic analysis indicates that the spillways are capable of passing 48 per cent of the PMF without overtopping of the embankment. (See Appendix C for computations).

e. Spillway Adequacy. A dam break analysis was performed to evaluate the increased "hazard to loss of life downstream from the dam from that which would exist just before overtopping failure" (ETL 1110-2-234, 10 May, 1978). According to the analysis, failure of the Penn Lake Dam during the occurrence of 50 per cent of the PMF would increase the depth of overbank flow from 3.0 feet to 5.2 feet in the hazard area. The peak discharge at the hazard area would increase from 3,860 cfs to 11,150 cfs. Failure of the dam is considered to significantly increase the hazard to loss of life. Therefore, the spillway of the Penn Lake Dam is classified as "seriously inadequate".

## SECTION 6

### STRUCTURAL STABILITY

#### 6.1 Evaluation of Structural Stability

a. Visual Observations. There are surface undulations of more than a foot along the top of the dam and the side slopes of the embankment which could be the result of settlement or poor construction methods. The riprap facing on both the upstream and downstream slopes of the embankment is obscured by the cut trees and debris on the slopes. Seeps and rust colored water are evident along the toe of the downstream embankment slope. The entire region immediately downstream of the dam is swampy.

Due to the lack of information concerning the embankment and foundation materials, the stability of the dam cannot be properly assessed.

b. Design and Construction Data. There are no design and construction data available. It is known that the structure was originally designed in 1905 by H.S. Smith of Wilkes Barre and it was built by S.S. Staples during the same year.

c. Operating Records. There is no evidence that operating records are maintained at this structure.

d. Post Construction Changes. Since there are no records of the original design and construction, there is no way of knowing exactly what constituted the original structure. Sometime after the original construction, the dam was increased in height from 24 feet to 44 feet, and the spillway was developed approximately 1,000 feet left (looking downstream) of the dam. There is no documentation of when these modifications were made. From the DER files, information is available on maintenance repair work done on the dam through the years.

e. Seismic Stability. Penn Lake Dam is located in Seismic Zone 1 of the "Seismic Zone Map of Contiguous States". Normally, it can be considered that if a dam in this zone is stable under static loading conditions, it can be assumed safe for any expected Zone 1 earthquake conditions.

## SECTION 7

### ASSESSMENT, RECOMMENDATIONS, PROPOSED REMEDIAL MEASURES

#### 7.1 Dam Assessment

a. Evaluation. Based on visual observations made during the date of the inspection, the dam is considered to be in poor condition. There are seeps and murky rust colored water evident along the toe of the downstream embankment slope. The entire region immediately downstream of the dam is swampy. Bulges and depressions are evident on the downstream slope of the embankment and there is some embankment sloughing. There are cut brush, stumps, and debris over the entire downstream slope. The upstream slope of the embankment is covered with heavy brush and there is a depression (Plate 4, Appendix E) near the left abutment. The riprap protection on the upstream and downstream slopes is poorly graded and sparse in many areas.

The SDF is the PMF. Examination of the results of the hydrologic and hydraulic analysis indicates that the spillway is capable of passing 48 per cent of the PMF without overtopping of the embankment. Failure of the dam would increase the hazard to loss of life downstream of the dam. Therefore, the capacity of the drop spillway is classified as "seriously inadequate". The dam is considered to be unsafe (non-emergency).

It is assumed the sluice valve of the reservoir drain system is partially opened. This observation is based on the amount of water flowing in the vicinity of the concrete block structure at the toe of the downstream embankment slope which houses the sluice valve.

b. Adequacy of Information. Although design and construction information is minimal, a Phase I evaluation is considered reasonable based on the revealing conditions observed during the field inspection.

c. Urgency. The remedial measures recommended in Section 7.2 should be effected immediately.

d. Necessity for Further Evaluation. Further investigation should be performed to determine the source of the seeps, rust colored water, undulations, and sloughing of the embankment. Detailed hydrologic and hydraulic studies should be made to determine the necessity to increase the spillway system for this structure.

#### 7.2 Recommendations and Remedial Measures

##### a. Facilities.

1. The capacity of the spillway system should be increased in accordance with the results of detailed hydrologic and hydraulic studies.

2. A subsurface investigation program should be initiated to determine the composition and in situ properties of the earth embankment and foundation materials and to determine the stability of the dam. The investigations should be supervised by a licensed professional engineer experienced in the design and construction of dams.

3. Piezometers should be installed in the boreholes to evaluate pore pressure development throughout the earth embankment and aid in determining the source of the seeps all along the toe of the downstream earth embankment slope.

4. The area at the downstream end of the reservoir drain system should be cleared of silt and debris. The drain system should then be appraised and repaired as needed. A means of positive closure at the upstream end of the reservoir drain system should be developed.

5. All brush, stumps, debris, etc. should be removed from the dam.

6. Decisions concerning the need to supplement the riprap protection, raise the top of the dam, and add additional spillway facilities, should await the results of the drilling program and further hydrologic/hydraulic analyses.

b. Operation and Maintenance Procedures

1. Because there are about a dozen homes located along Wright Creek between Penn Lake Dam and the Lehigh River (a distance of about  $2\frac{1}{2}$  miles), a downstream warning system should be developed, and during periods of heavy rainfall, the dam should be monitored and downstream residents alerted in the event of an impending failure.

2. The owner should develop and implement a maintenance and inspection checklist to insure that all items are maintained on a regular basis.

APPENDIX

A

Check List Engineering Data  
Design, Construction, Operation  
Phase I

CHECK LIST  
ENGINEERING DATA  
DESIGN, CONSTRUCTION, OPERATION  
PHASE I

NAME OF DAM Penn Lake Dam  
ID # PA 00542

Sheet 1 of 4

REMARKS

"As-Built" drawings. The only drawing in the DER files is 3 sheet showing the shoreline of the reservoir prepared 2/49

Refer to Appendix E, Plate 2

ITEM  
AS-BUILT DRAWINGS

REGIONAL VICINITY MAP

CONSTRUCTION HISTORY

The dam was built in 1905 by J.C. Sparks and his associates for the purpose of securing ice bonds. The structure was designed by U.S. Army Corps of Engineers, 20.

TYPICAL SECTIONS OF DAM

OUTLETS - PLAIN	Not Available
DETAILS	
CONSTRAINTS	
DISCHARGE RATINGS	
RAINFALL/RESERVOIR RECORDS	Not Available

ITEM	REMARKS
DESIGN REPORTS	No design data available.
GEOLOGY REPORTS	None provided in DER files. Refer to Appendix F of this report.
DESIGN COMPUTATIONS	No data available
HYDROLOGY & HYDRAULICS	No data available
DAM STABILITY	No data available
SEEPAGE STUDIES	No data available
MATERIALS INVESTIGATIONS	No information available
BORING RECORDS	
LABORATORY	
FIELD	
POST-CONSTRUCTION SURVEYS OF DAM	None
BORROW SOURCES	There is no record of where borrow materials came from.

ITEM	REMARKS
MONITORING SYSTEMS	None
MODIFICATIONS	Sometime after the original construction the dam was modified in height from 34' to 44'. There is no documentation of when this was done. Sudden water level change approx. 1000 ft. left of the dam sometime after the original construction.
HIGH POOL RECORDS	None available
POST CONSTRUCTION ENGINEERING STUDIES AND REPORTS	None
PRIOR ACCIDENTS OR FAILURE OF DAM DESCRIPTION REPORTS	Letter written 12/29/91 warns of "overrunning" failure of the side. This led to state inspection of the dam and remedial repair in 1992.
Maintenance Operation Records	Correspondence through the years (from DER files) gives information about periodic maintenance work that was done on the structure. There are no operating records available.

ITEM	REMARKS
SPILLWAY PLAIN SECTIONS DETAILS	Refer to Appendix E for details

OPERATING EQUIPMENT  
PLANS & DETAILS      No information available

MISCELLANEOUS

Material in DER file:

1. Dam inspection reports through the years.
2. Photographs related to the structure from 1912 through 1965
3. "Application for Permit to Draw Dam or Other Body of Water" (1971)
4. Miscellaneous correspondence
5. Sheet showing elevation of reservoir prepared 1949.

**APPENDIX**

**B**

**Check List**

**Visual Inspection**

**Phase I**

**CHECK LIST  
VISUAL INSPECTION  
PHASE I**

Sheet 1 of 11

Name Dam Penn Lake Dam County Luzerne State Pennsylvania ID # PA-00542  
Type of Dam Earth Fill Hazard Category High  
Date(s) Inspection Dec 14, 1978 Weather Cloudy, Cold Temperature ~30° F  
National

Pool Elevation at Time of Inspection / 333 + M.S.L. Tailwater at Time of Inspection 1290 ± M.S.L.

### **Inspection Personnel:**

George C. Elkins

David B. Campbell

Leonard R. Beck

Recorder  
Leopold E. Beck

**Remarks:**

CONCRETE/MASONRY DAMS

Sheet 2 of 11

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
ANY NOTICEABLE SEEPAGE	N/A	
STRUCTURE TO ABUTMENT/EMBANKMENT JUNCTIONS	N/A	
DRAINS	N/A	
WATER PASSAGES	N/A	
FOUNDATION	N/A	

## CONCRETE/MASONRY DAMS

VISUAL EXAMINATION OF		OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS	CONCRETE SURFACES	N/A	
STRUCTURAL CRACKING		N/A	
VERTICAL AND HORIZONTAL ALIGIMENT		N/A	
MOMOLITH JOINTS		N/A	
CONSTRUCTION JOINTS		N/A	

Sheet 3 of 11

EMBANKMENT

Sheet 4 of 11

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS	Could not tell because there is so much cut trees and debris on the slopes and a hard surface road runs along the top of the bank.	Clean all of the cut trees and debris off the slopes of the dam.
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	None observed	None
SLoughing or Erosion of Embankment and Abutment Slopes	There appears to be sloughing occurring on the downstream slope. It is difficult to tell how much sloughing has occurred because there is so much cut trees and debris on the slopes.	A boring program should be installed to determine the composition and in situ properties of the embankment and foundation materials to determine the stability of the dam.
Vertical and Horizontal Alignment of the Crest	There are numerous bulges and depressions which form an irregular pattern along both the upstream and downstream slopes and the top of the dam.	Protectors should be installed in the bore holes to evaluate pore pressure development throughout the embankment.
RIPRAP FAILURES	It is difficult to tell exactly length of the riprap failure on both the upstream and downstream banks because of the cut trees and debris on the slopes.	

VISUAL EXAMINATION OF		OBSERVATIONS	REMARKS OR RECOMMENDATIONS
JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM		<p>It is difficult to assess the situation at the junction of the embankment and abutment because of the excessive debris and brush on the site. The situation is about 1000 feet east of the outlet channel.</p> <p>There is seepage of varying degrees off along the diversion line.</p>	<p>refer to comments on sheet 4/11</p> <p>refer to comments on sheet 4/11 • Considered should be given immediately to foundation and embankment protection &amp;/or a completed new internal drainage system.</p>
ANY NOTICEABLE SEEPAGE			None
STAFF GAGE AND RECORDER			None

None

None observed

OUTLET WORKS

Sheet 6 of 11

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	Outlet conduit cannot be observed.	Draw down impoundment so that outlet reservoir drain system can be examined.
INTAKE STRUCTURE	Intake structures could not be observed because of was major winter.	"
OUTLET STRUCTURE	Outlet of reservoir drain system could not be observed because it was made of below grade block structure.	"
OUTLET CHANNEL	Flow around through the works for about 200 feet before it joins the channel for the supply of discharge.	Should be realigned to flow directly away from the dam.
EMERGENCY GATE	It is observed the sluice valve is in permanent lift open position jacking down the dam part of water flowing in the vicinity of the concrete block structure which houses the gate.	Sluice valve should be examined and repaired as needed.

UNGATED SPILLWAY

Sheet 7 of 11

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE WEIR	Weir is destroying the invert of 12, 42 inch, 20 foot long pipes. The invert of the pipes are 1333.0 A road is built on top of the pipes. The surface of the road is about 5 feet above the pipe invert.	This spillway is of very limited capacity. Snakes or back sicks of sufficient pipes as auxiliary spillways.
APPROACH CHANNEL	Approach channel is only about 30 feet in length with numerous obstacles from timber bridge.	"
DISCHARGE CHANNEL	Follows natural draw through property wooded areas. Channel width is one about a 2 percent slopes.	Timbered draw presents too much of an obstruction to flow.
BRIDGE AND PIERS	Timber bridge (pedestrian traffic) and highway invert (12, 42 inch, 20 foot long pipe).	Restricts flow, needs to be removed up.

GATED SPILLWAY

Sheet 8 of 11

<u>VISUAL EXAMINATION OF</u>	<u>OBSERVATIONS</u>	<u>REMARKS OR RECOMMENDATIONS</u>
CONCRETE SILL	N/A	
APPROACH CHANNEL	N/A	
DISCHARGE CHANNEL	N/A	
BRIDGE AND PIERS	N/A	
GATES AND OPERATION EQUIPMENT	N/A	

INSTRUMENTATION

		Sheet 9 of 11	
VISUAL EXAMINATION	OBSERVATIONS	REMARKS OR RECOMMENDATIONS	
MONUMENTATION/SURVEYS	N/A		
OBSERVATION WELLS	N/A		
WEIRS	N/A		
PIEZOMETERS	N/A		
OTHER	N/A		

Sheet 10 of 11

VISUAL EXAMINATION OF		REMARKS OR RECOMMENDATIONS
	OBSERVATIONS	

RESERVOIR

SLOPES	All slopes are less than 10%. Entire shoreline of reservoir is residentially developed.	Note
--------	---	------

SEDIMENTATION	Probably won't see too much additional sediment accumulation because the entire shoreline is residentially developed. A certain amount of sediment probably will deposit in the reservoir when all the structures were built around the lake.	Note
---------------	---	------

DOWNSTREAM CHANNEL

Sheet 11 of 11

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONDITION (OBSTRUCTIONS, DEBRIS, ETC.)	For about 30% of the 2.5 miles from Penn Lake Dam to the bottom end of Wright creek flows through a heavily wooded region. The bottom of the ditch is through meadows. There is one highway bridge about 2.0 miles down- stream of Penn Lake Dam.	An estimated "3" value is about 0.06 for the entire 2.5 miles
SLOPES	The channel gradient averages about 1.4 % for the entire 2.5 miles from Penn Lake Dam to the confluence of Wright creek with the Little Pine River.	None
APPROXIMATE NO. OF HOMES AND POPULATION	There are about a dozen houses and approximately 60 people!	A formal warning system should be developed and implemented. Procedures for evacuating people within the potential flood area should be implemented.

**APPENDIX**

**C**

**Hydrologic & Hydraulic Data**



O'BRIEN & GERE  
ENGINEERS, INC.

SUBJECT

Penn Lake Dam

SHEET

BY

DATE

JOB NO

## Table of Contents APPENDIX C

### Hydraulics & Hydrologic Data

PMP Calculations	Sheet 1
Synder Coefficients	Sheet 1
Spillway Discharge Computations Through Pipes	Sheet 2
Spillway Discharge Flow Areas Through tanks	Sheets 2&3
Flow over Top of Dam	Sheet 3
Stage - Discharge Computations Summary	Sheet 4
Stage - Area, Stage - Storage Calculations	Sheet 5
Reservoir Dam Discharge ft-Sec. & Damage Area	Sheet 5
Stage - Area, Stage - Storage Plots	Sheet 6
HEC-I Dam Safety Version Computer Output	Sh. 7-11
HEC-I Dam Safety Version Computer Output with Dam Break	Sh. 12-18



O'BRIEN &amp; GERE

SUBJECT	SHEET	BY	DATE	JOB NO
PENN LAKE DAM	1	RRB	3/5/79	

13 3/5/79

HYDROLOGY CALC'S.

DRAINAGE AREA: 7.0 SQUARE MILES

PMP CALCULATIONS (HMS REPORT 33)

AREA IS IN ZONE 1

24 HR., 200 SQ. MI. RAINFALL = 22 "

HR.	%	RAINFALL	$\Delta RF$
6	111	24.4"	24.4"
12	123	21.1"	2.7"
24	133	29.3"	2.2"
48	142	31.2"	1.9"

SNYDER COEFFICIENTSFROM INFO. PROVIDED BY COE,  
FOR THE DELAWARE RIVER BASIN, ZONE 2:

$$C_p = 0.45$$

AND  $C_t = 2.1$ 

$$t_p = C_t (L \cdot L_{ca})^{0.3}$$

$$L \approx 5.3 \text{ miles}$$

$$L_{ca} \approx 2.8 \text{ miles}$$

$$t_p = 2.1 (5.3 \cdot 2.8)^{0.3} = 4.72 \text{ HR.}$$

SUBJECT	SHEET	BY	DATE	JOB NO
Penn Lake Dam, Stage II, Discharge	2	F	2/23/79	1R26 35779

12' Diam of Pipe

Pipe Flow between Pipe Invert El. 1332.0 (Normal Pool)

to El. 1334.5 (Gauge) at point of discharge

ES 97.3 ft (sec), NEH-D

$$\text{For } 150' \text{ of } H_2O \text{ in } 12' \text{ pipe } \frac{d}{D} = \frac{1.5}{3.0} = 0.42$$

For Normal Discharge

$$Q_{\text{ad}} = \frac{\pi D^2 L}{2g} = 0.178$$

$$Q_{\text{ad}} = 0.178 \times \frac{\pi D^2 L}{2g} = 0.178 \times \frac{\pi (3.0)^2 \times 150}{2 \times 0.0111} = 32.7 \text{ cfs}$$

$$Q_{\text{ad}} = 0.178 + 3.5 \times \frac{L}{D} + 2.01 \times \frac{L}{D^2} = 32.7 \text{ cfs} \approx 34 \text{ cfs}$$

$$\text{For 12 pipes } 34.12 = 473 \text{ cfs}$$

Full Pipe Flow

$$Q_p = C_p H_p^{1/2} \quad C_p = A_p \sqrt{\frac{2g}{1+K_e+K_o+K_w}}$$

Assume invert outlet El. 1332.8  $C_p = 115.44 \sqrt{\frac{64.4}{1+1.0+0.5+0.00784 \times 20}} = 115.44 \sqrt{\frac{64.4}{12.56}} = 568.4$

With  $H_2O \text{ at El. 1337.5 in reservoir}$   $K_p = 0.00154 \text{ (P12 with ES 42 sec)}$

$Q_p = 568.4 \times 2.95^{1/2} = 568.4 \text{ cfs}$

$$Q_p = 568.4 \times 3.45^{1/2} = 568.4 \text{ cfs}$$

$$Q_p = 568.4 \times 3.45^{1/2} = 568.4 \text{ cfs}$$

$$L_p = \text{Length of pipe}$$

$$A_p = 9.62 \times 12 = 115.44 \text{ ft}^2$$

Discharge Through Scales

Right Side Discharge

$H_2O$  to El. 1337.5 & 3 scale Invert El. 1334.5

Find equivalent rect. x-sec. of flow

Dimensions (ft)  $\times$  Sec. Area (ft<sup>2</sup>)

$$3 \times 4.8 = 72$$

$$50 \times \frac{2.7}{2} = 142.5$$

$$2.5 \times 10.2 = 25.5$$

$$\frac{353.6 \text{ ft}^2}{3 \text{ ft}^2 \text{ (discharge)}} = 117.8 \text{ ft}^2$$

Left side discharge

$H_2O$  to El. 1337.5 & 3 scale Invert El. 1334.5

Dimensions (ft)  $\times$  Sec. Area (ft<sup>2</sup>)

$$3 \times 4.8 = 64.8$$

$$25 \times \frac{2.7}{2} = 67.5$$

$$2.5 \times 4.8 = 60.0$$

$$\frac{193.3}{3} = 64.4 \text{ ft}^2$$

ft<sup>2</sup> of flow

SUBJECT	SHEET	BY	DATE	JOB NO
Twin Lakes Dam, Stage 1, Spillway	3	F	2/23/79	RRB 3/5/79

Discharge Through Spillway

Right Side Spillway

$H_2O \text{ to El. } 1340.0 + \text{ Spillway Head } El. 1334.5$

Dimension (ft) Y-sec Area (ft<sup>2</sup>)

$$\frac{2.4 + 5.5}{2} \times 50 = 187.5$$

$$\frac{5.5 + 5.2}{2} \times 50 = 267.5$$

$$\frac{5.2 \times 19.5}{2} = 507.0$$

$$\frac{972.0}{5.2} \approx 191.5 \text{ ft}$$

Left Side Spillway

$H_2O \text{ to El. } 1340.0 + \text{ Spillway Head } El. 1334.5$

Dimension (ft) Y-sec Area (ft<sup>2</sup>)

$$\frac{2 + 5.5}{2} \times 50 = 187.5$$

$$\frac{5.5 + 5}{2} \times 50 = 131.2$$

$$\frac{5 \times 9.6}{2} = 240.0$$

$$\frac{558.7}{5.2} \approx 102 \text{ ft.}$$

Flow Over Spillway

$H_2O \text{ to El. } 1340.0 + \text{ Spillway Over Depth } El. 1333.0 - El. 1332.6$

Ave H = 2.2', Width of Spill System 60'

Flow Over Top of Dam

$H_2O \text{ to El. } 1340.0 + \text{ Top of Dam } El. 1337.4$

$$\frac{2.3 \times 41}{2} = 54.0$$

$$\frac{2.3 + 2.6}{2} \times 50 = 122.5$$

$$\frac{2.6 + 1.1}{2} \times 50 = 92.5$$

$$\frac{1.1 + 2.5}{2} \times 50 = 40.0$$

$$\frac{0.5 \times 16}{2} = \frac{4.0}{313.0} \approx 120 \text{ ft.}$$



O'BRIEN & GERE  
ENGINEERS, INC.

SUBJECT

REMARKS  
Rim Lake Dam, Stage B. Damsite

SHEET

4

**DATE**

17

JOB NO

11 Sept. 6 - 1912

212

3) Grand Canyon's depth is  $\mathcal{C} = 2.60$  and its distance  $\mathcal{D} = 0.6 \text{ M}^{5/2}$

卷之三

卷之二

卷之三

Q  $L = 102$ ,  $1 \text{ cm}^2$  to  $5k\Omega$

W 1-109 refer to Sh 3

At first it went west  $l = 80^{\circ}$ , and got to  $\lambda = 3$

۱۲

SUBJECT

Ram Lake Dam, Stage vs. Storage

SHEET  
5

BY  
J. L.

DATE  
2-22-74

JOB NO

Stage

Surface Area (Ac)

Storage (Ac.Ft)

1293

0

0

1333 4

56

246 3

1340

84

736

1360

168

2416

11 Normal Reservoir surface elevation taken from USGS White Haven, Pa. 7 1/2' Quadrangle

21 Storage capacity supplies by OER (completely full = 24,400,000 ft<sup>3</sup>)

Rese. with Gate Undercharge.

$$C_F = k_F \sqrt{\frac{2g}{1 + K_E k_F + K_D}}$$

$$C_F = 7.07 \sqrt{\frac{2g}{1 + 0.5 + 0.07 \cdot 2.5}}$$

$$C_F = 7.07 \times 3.16$$

$$C_F = 22.34$$

With normal pool @ El. 1333.0

head to # gate valve = 1333.0 - 1238.5  
= 33.5'

$$\approx 7.07 \sqrt{2g}$$

$\approx 7.07 \sqrt{2g}$  (very little loss at very small head)

$K_E \approx 1.0$  (Entrance loss coeff.)

$K_D = 0.5$  (Exit loss coeff.)

$K_L = 0.0171$  (Pipe loss coeff., ES-42 5cc)

$L_F \approx 230'$

bottom most outlet = El. 1298.0

top of dam & outlet = El. 1342.0

use El. 1342.0


bottom # gate valve = El. 1299.5

$$Q_F = C_F H_F^{1/2}$$

$$Q_F = 22.34 \times 33.5^{1/2}$$

$$Q_F = 129.3 \text{ USE } 130 \text{ ft}^3/\text{s}$$

Cross-Section Downstream  
of Damage Area



SUBJECT

Penn Lake Dam

SHEET

BY


DATE

JOB NO

6

E

2/23/77



1487 MELVILLE, JOHN - 1910-1911  
1488 SAFETY, HENRY - 1910-1911  
1489 SCHAFFNER, ERNST - 1910-1911  
1490 SCHLESINGER, SAMUEL - 1910-1911

NATIONAL JAM INSPECTION PROGRAM

847

PLANO MEETING WITH GOVERNOR, STATE, 2-11  
DAM SAFETY EVALUATION  
LAST 24 HOURS

DATE: 03/05/72  
TIME: 0745Z

94 B

NATIONAL DAM INSPECTION PROGRAM  
PLAIN LAKE DAM  
PMF HYDROGRAPH

ITEM	NAME	NMIN	I DAY	J DAY	JUL SPECIFICATION	IPLT	IPRT	NSTAN
1	1	0	0	0	IMM 1MIN METRIC	0	-4	0
2	2	0	0	0	NWT LHOUT	0		
3	3	0	0	0	TRACE	0		

MULTI-PLAN ANALYSES TO BE PERFORMED

NPLAN= 1 NRATIO= 1 Lratio= 1  
\*40 \*50 .60 .70 .80 .90 1.00

\*\*\*\*\*  
SUBROUTINE MUNJUR COMPUTATION  
ROUTINE TO READ MUNJUR

ISTAB	ICOMP	ICON	ITAP	JPLT	JPRT	I NAME	I STAGE	I AUTO
A1	0	0	0	0	0	0	0	0
1	1.00	1.00	0.00	0.00	0.00	0.00	0	0

SURFACE DATA  
RHS H2O H2O H2O H2O H2O H2O R96

TYPE	RHS	RHS	RHS	RHS	RHS	RHS	RHS
LNG1	0.00	0.00	111.00	123.00	133.00	142.00	0.00
LNG2	0.00	0.00	0.00	0.00	0.00	0.00	0.00

THDPC COMPUTATION  
UNIT HYDROGRAPH DATA  
T2= 4.02 C2= .43 NTA= 0

RECESSION DATA  
UNCSV= -.05 HT10H= 2.00

ITEM	NAME	NMIN	I DAY	J DAY	JULS DATA	RTOK	STRL	CNSTL	ALSMX	RTIMP
1	1	0	0	0	0.00	1.00	1.00	.05	0.00	0.00
2	2	0	0	0	0.00	0.00	0.00			
3	3	0	0	0	0.00	0.00	0.00			

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00



S4/10

TABLE I  
SUMMARY FROM MULTIPLE PLANT-HATCH ECONOMIC COMPUTATIONS  
FLUID IN CUBIC FEET PER SECOND) (CUBIC METERS PER SECOND)  
AMOUNT OF SURFACE (END OF PUMP) (METERS)  
AMOUNT OF SURFACE (END OF PUMP) (KILOMETERS)

## SUMMARY OF IAM SAFETY ANALYSIS

94 21


PLATE	ELEVATION STRUCTURE OUTLINE	INITIAL VALUE	SPILLWAY CHEST		TOP OF DAM 1337.40 561. 3440.	TIME OF FAILURE HOURS	
			MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-T	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	MAX OUTFLOW HOURS
* 1.0	MAXIMUM HEADLEVEL OVER	1335.27	0.00	426.	1491.	0.00	45.00
* 2.0	1336.31	0.00	414.	2239.	0.00	45.00	0.00
* 3.0	1336.31	0.00	531.	2986.	0.00	45.00	0.00
* 4.0	1337.02	* 1.3	310.	3904.	3.00	45.00	0.00
* 5.0	1337.03	* 3.5	202.	474.	5.00	45.00	0.00
* 6.0	1337.03	* 5.2	227.	5338.	7.00	45.00	0.00
* 7.0	1336.92	* 7.4	513.	6136.	9.00	45.00	0.00
* 8.0	1336.92	* 7.4	685.	10.00	10.00	45.00	0.00
* 9.0	1336.94	* 7.4	7634.	11.00	11.00	45.00	
1.00	1336.04	1.14					

FLUID HYDROGRAPHIC POLYGRAPH (HFC-1)  
DAM SAFETY VERSION JULY 1975  
LAST MODIFICATION 05 SEP 78

NATIONAL DAM INSPECTION PROGRAM									
PENN LAKE DAM					PMF HYDROGRAPH				
1	A1	A2	A3	A4	10	0	0	-4	0
2									
3									
4									
5									
6									
7									
8									
9									
10									
11									
12									
13									
14									
15									
16									
17									
18									
19									
20									
21									
22									
23									
24									
25									
26									
27									
28									
29									
30									
31									
32									
33									
34									

## 0.5 PMF with Dam Break Ph II

Top width of Breach  $\approx 210'$



The portion of the dam assumed to be breached is based on the geometry of the site. The depth of flow over the top of the dam at which failure is initiated and the elapsed time to complete banking are based on the general experience and age of the structure. Consideration was given to the parameters used in the C.A.S. publication "Basic Concepts of Dam Breaks and Development of Dam Break Hydrographs".



## HYDROLOGIC COMPUTING

## ROUTING THROUGH DRINKIN LAKE

	ISTAU A2	ICOMP 1	IECON 0	ITAPT 0	JPLT 0	IPRT 0	INAME 1	ISAGE 0	IAUTO 0
ALL PLANS HAVE SAME ROUTING DATA									
LOSS 0.0	CLOSS 0.000	AUG 0.00	IRTS 1	ISAM 1	IOPT 0	IPMP 0	LSTR 0		
	NSTPS 1	NSTDL 0	LAG 0	WASKA 0.000	X	TSK 0.000	STORA -1333.	ISPRAT -1	
STAGt	1333.00	1337.50	1340.00	1350.00					
FLU <sub>n</sub>	0.00	40.00	3440.00	12000.00	150000.00				
CA-CACITY:	0.	246.	7.56.	2416.					
ELEVATION=	1243.	1333.	1340.	1360.					
	CHEL 1333.0	SPWU 0.1	CQW 0.0	EXP# G.U	TLEV 0.0	COUL 0.0	CAREA 0.0	EXPL 0.0	
					DAM DATA				
					TUPBL 1337.5	COUL 0.0	EXPD 0.0	DAMID	
								0.	

DAM FAILURE DATA  
1.00 1250.00 1.00 1333.00 1337.50

PEAK OUTFLUM IS 3935. AT TIME 44.50 HOURS


DAM BREAK DATA  
1.00 1250.00 1.00 1333.00 1337.50

SEEN DAM FAILURE AT 43.57 HOURS

PEAK OUTFLUM IS 14073. AT TIME 44.25 HOURS

SH 24

0.5 DAY WITH DAM BREAK



\*DNE\*

\*\*\*\*\*  
0.5PMF with Dam Break  
Shlf

HYDROGRAPH ROUTING							
ROUTING DOWNSTREAM							
STAO H	I CWP 1	IECON 0	ITAPT 0	JPLT 0	JPRF 0	I NAME I	I STAGE 0
ULoss 0.0	CLSS 0.000	Avg 0.00	TRTS 1	ISMT 1	TOPT 0	IPHP 0	LSTR 0
NSTPS 1	NSTDL 0	LAG 0.000	AMSKN X		TSK 0.000	STORA -1.	ISPRAT 0

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

NORMAL DEPTH CHANNEL ROUTING

UN(I)	UN(r)	UN(1)	ELNVT	ELMAX	RLNTM	SEL
0.00	0.00	0.000	1216.0	1240.0	7500.	01200

CROSS SECTION COORDINATES--STA.ELEV--tIC							
0.00	1240.00	175.00	1220.00	422.00	1218.00	427.00	1216.00
450.00	1218.00	375.00	1220.00	922.00	1240.00		
STORAGE	0.00	4.84	1130.89	1205.19	1466.70	252.10	356.52
JUTFLOW	0.00	125.55	432.46	1406.52	5075.17	1615.42	1791.36
STAGE	1216.00	1217.26	1218.53	1219.79	1221.05	1223.58	1226.11
FLOW	43056.00	53479.16	65050.65	77753.65	91732.03	106840.74	123295.52
MAXIMUM STAGE IS	1216.00						
MAXIMUM STAGE IS	1223.00						

\*\*\*\*\*  
\*\*\*\*\*  
\*\*\*\*\*  
\*\*\*\*\*  
\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

MEAN FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS  
 MEAN FLOWS IN CUBIC FEET PER SECOND (Cubic Meters per second)  
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATOR STATION AREA PLAN RATIO 1  
 .50

HYDROGRAPH AT	A1 ( 1d.13)	7.00	1 395H. ( 112.08) { 2 395H. ( 112.08) {
AUGUST 10	AS ( 1d.13)	7.00	1 3935H. ( 111.43) { 2 164.68. ( 465.99) {
MOUNTED TO	AS ( 1d.13)	7.00	1 3953H. ( 109.38) { 2 111.12. ( 413.80) {

25 PMF with Dam Break  
 8/27

## SUMMARY OF DAM SAFETY ANALYSIS

*0.5 PMP with Dam Break  
SH 18*

PLAN 1 *****	ELEVATION STORAGE OUTFLOW	INITIAL VALUE 1333.00 246. 0.	SPILLWAY CREST 1333.00 246. 0.	TOP OF DAM 1337.40 561. 344.0.	TIME OF FAILURE HOURS
RATIO OF PHF	MAXIMUM RESERVOIR A.S.ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE ACFT	DURATION OVER TOP HOURS	MAX OUTFLOW HOURS
.50	1337.64	.246	.270.	.3935.	.44.50
					0.00
PLAN 2 *****	ELEVATION STORAGE OUTFLOW	INITIAL VALUE 1333.00 246. 0.	SPILLWAY CREST 1333.00 246. 0.	TOP OF DAM 1337.50 561. 344.0.	TIME OF FAILURE HOURS
RATIO OF PHF	MAXIMUM RESERVOIR A.S.ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE ACFT	DURATION OVER TOP HOURS	MAX OUTFLOW HOURS
.50	1337.52	.12	.203.	.19673.	.25
					44.25
					43.67
PLAN 1	STATION B1				
RATIO	MAXIMUM FLOW.CFS	MAXIMUM STAGE.FT	MAXIMUM TIME HOURS		
.50	.3861.	1221.0	.45.00		
PLAN 2	STATION B1				
RATIO	MAXIMUM FLOW.CFS	MAXIMUM STAGE.FT	MAXIMUM TIME HOURS		
.50	.1115.	1223.2	.44.33		

APPENDIX

D

**Photographs**



VIEW OF THE RESERVOIR  
FROM THE TOP OF THE DAM



DOWNSTREAM FACE OF THE DAM  
SHOWING CUT BRUSH LEFT IN PLACE

D-1



VIEW FROM THE DOWNSTREAM FACE OF THE DAM  
SHOWING DISCHARGE FROM THE RESERVOIR  
DRAIN PIPE AND SEEPAGE



THE GATE VALVE SHELTER. DISCHARGE IS FROM  
THE RESERVOIR DRAIN PIPE AND SEEPAGE

D-2



APPROXIMATELY 10 G.F.S. DISCHARGE FROM  
RESERVOIR DRAIN PIPE AND SEEPAGE ABOUT  
50 FEET DOWNSTREAM FROM THE DAM



DISCOLORED SEEPAGE FLOW IMMEDIATELY  
DOWNSTREAM OF THE DAM



CLOSE UP OF THE SEEPAGE FLOW  
IMMEDIATELY DOWNSTREAM OF THE DAM



A PORTION OF THE SPILLWAY FLOW  
ABOUT 1000 FEET TO THE LEFT OF THE DAM

D-4

APPENDIX

E

Drawings



SUBJECT

Penn Lake Dam

SHEET

BY  
Ji

DATE

4/10/78

JOB NO

## Table of Contents APPENDIX E

Regional Location Map	Plate 1
Plan View of Impoundment	" 2
Dam & Spillway Profiles	" 3
Plan View of Dam Showing Problems	" 4
Cross Sections of Embankment & Spillway	" 5






PLATE 1  
REGIONAL  
VICINITY MAP  
SCALE 1:24000





**SUBJECT**

## Penn Lake Dam, A Dam & Reservoir Project

SHEET




BY

TE

2/21/79

JOB NO

PA-00542



SUBJECT

Penn Lake Dam, Plan View of Dam

SHEET


BY

DATE

2/21/79

JOB NO

PA-00452



SUBJECT

Penn Lake Dam, Cross Section, of Emb.

SHE

BY

DATE  
2/22/79

JOB NO.

76 0.0  
Spillway

76 0.0  
Spillway

1) Form "Report upon Three Dams on White Creek", 1/29/12  
TYPICAL SECTION OF DAM Scale 1" = 40'

سے  
جہاں

1) Form "Report upon Three Dams on Wright Creek", 4/29/12  
TYPICAL SECTION OF DAM Scale 1" = 40'

### TYPICAL SECTION OF DANI

## TYPICAL SECTION OF SPILLWAY

APPENDIX

F

Site Geology

SITE GEOLOGY

Penn Lake Dam

Penn Lake is located in a high plateau depression within the glaciated portion of the Appalachian Mountain section of the Valley and Ridge physiographic province. At the site sedimentary units of the predominantly red shales and sandstones of the Mississippian Mauch Chunk formation dip slightly northwest. Some thin deposits of rock debris, remnants of Pleistocene (Wisconsin) glaciation overlie the bedrock formations. No faults or major structural defects are noted in the vicinity of the dam or lake.

