

AD-A073 631

BAKER (MICHAEL) JR INC BEAVER PA
NATIONAL DAM SAFETY PROGRAM. LAKE OF THE WOODS, INVENTORY NUMBER--ETC(U)
MAR 79 M BAKER

F/G 13/2

DACW65-78-D-0016


NL

UNCLASSIFIED

1 OF 3

AD
A073631





RAPPAHANNOCK RIVER BASIN

Name Of Dam: Lake of the Woods

Location: Orange County, State of Virginia

Inventory Number: VA 13701

14
b.
LEVEL II


PHASE I INSPECTION REPORT NATIONAL DAM SAFETY PROGRAM

Lake of the Woods, Inventory Number:
VA13701. Rappahannock River Basin,
Orange County, State of Virginia.
Phase I Inspection Report.

9 Final rept.

10 Michael Baker, III

15 DACW65-78-D-0016



DACW-65-78-D-0016

11 MARCH 1979

12 1979 P.

PREPARED FOR

NORFOLK DISTRICT CORPS OF ENGINEERS
803 FRONT STREET
NORFOLK, VIRGINIA 23510

DDC FILE COPY

DISTRIBUTION STATEMENT A

Approved for public release
Distribution Unlimited

BY

MICHAEL BAKER, JR., INC.

BEAVER, PENNSYLVANIA 15009

410795 A
79 09 10 123 pt



DISCLAIMER NOTICE

**THIS DOCUMENT IS BEST QUALITY
PRACTICABLE. THE COPY FURNISHED
TO DDC CONTAINED A SIGNIFICANT
NUMBER OF PAGES WHICH DO NOT
REPRODUCE LEGIBLY.**

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER VA 13701	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Inspection Report National Dam Safety Program Lake of the Woods Orange County, Virginia		5. TYPE OF REPORT & PERIOD COVERED Final
7. AUTHOR(s) Michael Baker, Jr., Inc. - Michael Baker III		6. PERFORMING ORG. REPORT NUMBER DACW 65-78-D-0016
9. PERFORMING ORGANIZATION NAME AND ADDRESS		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
11. CONTROLLING OFFICE NAME AND ADDRESS U. S. Army Engineering District, Norfolk 803 Front Street Norfolk, VA 22510		12. REPORT DATE March 1979
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		13. NUMBER OF PAGES
		15. SECURITY CLASS. (of this report) Unclassified
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Copies are obtainable from National Technical Information Service, Springfield, Virginia 22151		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dams - VA National Dam Safety Program Phase I Dam Safety Dam Inspection		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) (See reverse side)		

20. Abstract

Pursuant to Public Law 92-367, Phase I Inspection Reports are prepared under guidance contained in the recommended guidelines for safety inspection of dams, published by the Office of Chief of Engineers, Washington, D. C. 20314. The purpose of a Phase I investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general conditions of the dam is based upon available data and visual inspections. Detailed investigation and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

Based upon the field conditions at the time of the field inspection and all available engineering data, the Phase I report addresses the hydraulic, hydrologic, geologic, geotechnic, and structural aspects of the dam. The engineering techniques employed give a reasonably accurate assessment of the conditions of the dam. It should be realized that certain engineering aspects cannot be fully analyzed during a Phase I inspection. Assessment and remedial measures in the report include the requirements of additional indepth study when necessary.

Phase I reports include project information of the dam and appurtenances, all existing engineering data, operational procedures, hydraulic/hydrologic data of the watershed, dam stability, visual inspection report and an assessment including required remedial measures.

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of the Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation and analyses involving topographic mapping, subsurface investigations testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established guidelines, the spillway design flood is based on the estimated "Probable Maximum Flood" for the region (flood discharges that may be expected from the most severe combination of critical meteorologic and hydrologic conditions that are reasonably possible), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the design flood should not be interpreted as necessarily posing a highly inadequate condition. The design flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

CONTENTS

	<u>Page</u>
Preface	i
Brief Assessment of Dam	1
Overall View of Dam	5
Section 1: Project Information	7
Section 2: Engineering Data	11
Section 3: Visual Inspection	13
Section 4: Operational Procedures	15
Section 5: Hydraulic/Hydrologic Data	17
Section 6: Dam Stability	21
Section 7: Assessment/Remedial Measures	25

Appendices

- I. Plates
- II. Photographs
- III. Check List - Visual Inspection
- IV. Check List - Engineering Data
- V. Inspection Reports
- VI. Report of Soils Exploration
- VII. Stability Analysis
- VIII. References

Accession For	
NTIS GRAI	
DDC TAS	
Unannounced	
Justification	
By _____	
Description	
Availability Codes	
Dist.	Avail and/or special
A	2B CP

NAME OF DAM: LAKE OF THE WOODS

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

Name of Dam: Lake of the Woods
State: Virginia
County: Orange
Stream: Flat Run
Date of Inspection: 29 November 1978

BRIEF ASSESSMENT OF DAM

Lake of the Woods Dam is an earthen dam approximately 65 feet high and 1475 feet long. The dam is owned, operated, and maintained by Lake of the Woods, Inc. and was designed by Bauer Engineering, Inc. The lake is used for recreation by Lake of the Woods residents. The visual inspection and review of engineering data, made in November 1978 and January 1979, indicate no deficiencies requiring emergency attention.


The spillway will pass 67 percent of the Probable Maximum Flood without overtopping the dam, which is considered inadequate but not seriously inadequate for the "intermediate" size- "high" hazard classification of Lake of the Woods Dam. Review of stability calculations and visual observations made in the field indicate no evidence of embankment instability or piping of an emergency nature. However, if an emergency condition developed that would require draining the reservoir; the inability of the reservoir drain to empty the reservoir in a reasonable period of time is considered an undesirable condition. A study should be instituted immediately to determine an alternate method to drain the reservoir.

It is recommended that the finger drain outlets at the toe be located and opened into the drainage channel along the toe of the dam. The epoxy patches in the spillway that are no longer adhering to the concrete should be repaired, especially around the sluice gate. Rock should be placed over the seepage and erosion area at the end of the right spillway wall beside the stilling basin. The area behind the left spillway wall, where settlement has occurred, should be filled with soil, compacted, and seeded. The following minor maintenance items should be accomplished as part of the yearly maintenance program: fill and seed bare areas on the embankment, remove small trees from the drainage ditch at the toe, replace dislodged or missing riprap, remove

NAME OF DAM: LAKE OF THE WOODS

any large debris from the reservoir area and spillway, and install a staff gage to monitor reservoir levels above normal pool.

MICHAEL BAKER, JR., INC.


Michael Baker, III, P.E.
Chairman of the Board and
Chief Executive Officer

SUBMITTED:

Original signed by
JAMES A. WALSH

James A. Walsh
Chief, Design Branch

Original signed by
ZANE M. GOODWIN

Zane M. Goodwin
Chief, Engineering


Original signed by:

APPROVED:

Douglas L. Haller
Colonel, Corps of Engineers
District Engineer

Date:

MAR 19 1979



NAME OF DAM: LAKE OF THE WOODS

OVERALL VIEW OF DAM



PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
NAME OF DAM: LAKE OF THE WOODS ID# VA 13701

SECTION 1 - PROJECT INFORMATION

1.1 General

- 1.1.1 Authority: Public Law 92-367, 8 August 1972 authorized the Secretary of the Army, through the Corps of Engineers to initiate a national program of safety inspections of dams throughout the United States. The Norfolk District has been assigned the responsibility of supervising the inspection of dams in the Commonwealth of Virginia.
- 1.1.2 Purpose of Inspection: The purpose is to conduct a Phase I inspection according to the Recommended Guidelines for Safety Inspection of Dams. The main responsibility is to expeditiously identify those dams which may be a potential hazard to human life or property.

1.2 Description of Project

- 1.2.1 Description of Dam and Appurtenances: Lake of the Woods Dam is a homogeneous earthfill dam approximately 1475 feet long and 65 feet high. Seepage control is provided by an 8 inch perforated C.M.P. which extends from abutment to abutment along the base of the dam approximately 30 feet downstream from the centerline (see Plate 2). A cutoff trench and filter drains provide additional seepage control at the downstream toe and beneath 12 inches of riprap on the upstream face.

The overflow spillway located in the left abutment area consists of a concrete ogee weir, 40 feet long and 6.5 feet high, with a paved chute spillway, approximately 135 feet long on a 3 horizontal to 1 vertical (3:1) slope. All outflow from the dam is through this overflow spillway. The chute spillway discharges into a 30 foot wide by 65 foot long stilling basin. The weir crest elevation is 317.5 feet M.S.L.

A two-foot-square sluice gate is located at the left end of the concrete weir and is used primarily to flush sediment that accumulates behind the weir.

NAME OF DAM: LAKE OF THE WOODS

The lake can be drained by means of a 12 inch ductile iron drainpipe which extends through the dam and outlets into a small stream at the downstream toe of the dam. The drain is controlled by a 12 inch plug valve located about 15 feet upstream of its outlet. The plan and typical sections of the dam are shown on Plates 1, 2, and 3.

- 1.2.2 Location: Lake of the Woods Dam is located on Flat Run just upstream of Virginia State Route 3, 7 miles northwest of Chancellorsville, Orange County, Virginia. A Location Plan is included in this report.
- 1.2.3 Size Classification: The maximum height of the dam is 65 feet above the old streambed of Flat Run. The reservoir volume to the top of the dam is 14,160 acre-feet. Therefore, the dam is in the "intermediate" size category as defined by the Recommended Guidelines for Safety Inspection of Dams.
- 1.2.4 Hazard Classification: A treatment plant is located in the floodplain approximately 0.4 mile downstream from the dam. Because of the proximity of this plant, loss of life could result in the event of failure of the dam. Therefore, the dam is considered in the "high" hazard classification as defined by Section 2.1.2 of the Recommended Guidelines for Safety Inspection of Dams. The hazard classification used to categorize dams is a function of location only and has nothing to do with its stability or probability of failure.
- 1.2.5 Ownership: Lake of the Woods Dam which is situated in a private residential community is owned, operated, and maintained by Lake of the Woods, Inc.
- 1.2.6 Purpose: Lake of the Woods Dam is a privately owned recreational facility.
- 1.2.7 Design and Construction History: The existing facility was designed for the owner by Bauer Engineering, Inc. of Chicago, Illinois and constructed by Shoosmith Bros., Inc.

NAME OF DAM: LAKE OF THE WOODS

1.2.8 Normal Operational Procedures: No formal operational procedures are followed for this dam since it is a recreational facility. Normal pool elevation of 317.5 feet M.S.L. is maintained by a concrete ogee overflow weir that is the only spillway. The two-foot-square sluice gate and the 12 inch reservoir drain are opened annually to flush out sediment deposits.

1.3 Pertinent Data

1.3.1 Drainage Area: The drainage area of the Lake of the Woods Dam is 7.23 square miles.

1.3.2 Discharge at Dam Site: The maximum discharge through the spillway is not known.

Spillway:

Pool level at top of dam 3801 c.f.s.

1.3.3 Dam and Reservoir Data: Pertinent data on the dam and reservoir are shown in the following table:

TABLE 1.1 DAM AND RESERVOIR DATA

Item	Elevation feet M.S.L.	Area acres	Reservoir Capacity		
			Acre- feet	Watershed inches	Length feet
Top of dam	325.0	625	14,160	36.7	14,600
Spillway crest	317.5	500	9880	25.6	13,400
Streambed at centerline of dam	260+	-	-	-	-

NAME OF DAM: LAKE OF THE WOODS

SECTION 2 - ENGINEERING DATA

2.1 Design: The design data reviewed included the following:

- 1) As-built drawings of the dam including plan, elevation, typical sections, structural details, boring logs, and test pits.
- 2) Partial construction report documents including revisions that were made to the side slopes and compaction requirements (Appendix V).
- 3) Final inspection report by the designer, Bauer Engineering, Inc., at time of construction completion (Appendix V).
- 4) Partial hydraulic and hydrologic design data by Bauer Engineering, Inc., including a flood routing for Probable Maximum Flood (PMF), was reviewed and is discussed further in Section 5.1.
- 5) Soils exploration reports by Dames and Moore (Appendix VI).
- 6) Stability analyses by Dames and Moore, and Bauer Engineering, Inc. are discussed further in Section 6.2.2 (Appendix VII).

All design data reviewed was borrowed from the owner.

2.2 Construction: The dam was built by the Shoosmith Bros., Inc. and was completed in March 1968. As-built drawings, change orders, and material requisitions were available for review. The as-built drawings were verified in the field.

According to correspondence reviewed from the owner's file; it is apparent that during construction of the embankment, 95% of modified density was difficult to maintain. It was decided that, although 95% compaction would be strived for, a lower limit for compaction of 92% to 93% would be permissible. Dames and Moore of Chicago, Illinois, performed field explorations and laboratory tests during construction. With the relaxation of compaction requirements, it was decided to flatten the final slopes to 4:1 upstream and 3.5:1 downstream. These were the final slopes as indicated on the as-built drawings. The final inspection of the dam, spillway, and appurtenant structures was made by the design engineer on 6 March 1968.

NAME OF DAM: LAKE OF THE WOODS

2.3 Operation: There is no formal operating procedure for this dam. However, the two-foot-square sluice gate located in the spillway is operated on an annual basis to flush out sediment deposits as is the 12 inch reservoir drain.

The filling of the reservoir commenced in 1967 according to the report by E. D'Appolonia in October 1969 (Appendix V, pp. 5-18). Although there was some concern about the "slow rate of filling of the reservoir," D'Appolonia felt that additional filling time should be allowed before concluding the lake would not reach its normal pool elevation without expensive remedial or artificial filling measures.

Bauer Engineering, Inc. conducted an inspection (see report and check list in Appendix V) in August 1970 at the request of the developer, Boise Cascade Corporation, and stated that in general the dam appeared to be in excellent condition.

2.4 Evaluation:

2.4.1 Design: The as-built drawings were adequate to aid in the assessment of the stability of the dam. Stability calculations for the earthen section of the dam are included in Appendix VII. Design calculations for different conditions were available for the concrete weir and adjoining retaining walls of the spillway.

2.4.2 Construction: The construction reports and correspondence reviewed indicated that construction methods used were in accordance with design criteria.

2.4.3 Operation: Operations performed by Lake of the Woods personnel are considered adequate for this structure.

SECTION 3 - VISUAL INSPECTION

3.1 Findings

3.1.1 General: The field investigation was made on 29 November 1978. The weather was cloudy and rainy. The lake was at elevation 317.0 feet M.S.L. (0.5 foot below normal pool). The embankment and the appurtenant structures were found to be in good overall condition and do not require immediate remedial action.

3.1.2 Dam: The embankment was in good condition except for small areas on the crest and downstream face which have sparse topsoil and vegetation. These areas should be topsoiled and seeded. There is scattered driftwood on the riprap which should be removed. The stone riprap dislodged in a few small areas should be replaced.

The wet areas at the toe of the dam and on the slopes of the collection ditch nearby are probably caused by the finger outlets from the filter drain being partially blocked by topsoil. The outlets should be cleaned out and extended to the ditch where necessary. Trees growing in the ditch and dumped tree stumps should be removed.

3.1.3 Appurtenant Structures: The intake portion of the reservoir drain is submerged. The plug valve and outlet pipe appear to be in good condition. There was no flow from the outlet pipe (Photo 1).

The concrete spillway functions adequately in spite of minor deterioration which includes epoxy patching in nine areas with clear leakage at two locations. There are small popouts of aggregate on the crest of the weir and in the spillway. Minor settlement (less than 2 feet) of the backfill adjacent to the left (north) wall should be corrected by the addition of compacted soil and seeding. The clear seepage and eroded area at the end of the right wall beside the stilling basin should be covered with rock to prevent further erosion. There is some clear leakage in the patched stem of the weir adjacent to the slide gate. Photos 2-6 show the deterioration of the spillway.

NAME OF DAM: LAKE OF THE WOODS

- 3.1.4 Reservoir Area: The slopes in the reservoir area are apparently well vegetated with minor erosion.
- 3.1.5 Downstream Channel: The outlet channels for the reservoir drain and spillway are in satisfactory condition. There is some minor erosion on the slopes where clear seepage is present downstream from the spillway.
- 3.2 Evaluation: None of the above items is serious enough to represent an emergency condition. However, the following items should be completed within a year from the date of this report. Erosion control and seeding of bare areas should be included in the annual inspection and maintenance program. The repair of the filter drain outlets, elimination of trees growing in the downstream drainage ditch, removal of the pile of tree stumps, and repairs in the spillway area should also be completed.

NAME OF DAM: LAKE OF THE WOODS

SECTION 4 - OPERATIONAL PROCEDURES

- 4.1 Procedures: Operational procedures are generally discussed in paragraphs 1.2.8 and 2.3. The owner opens the slide gate on the face of the concrete weir in the spillway and the reservoir drain annually to flush out sediments.
- 4.2 Maintenance of Dam: Maintenance of the dam is provided by personnel of Lake of the Woods, Inc.
- 4.3 Maintenance of Operating Facilities: Maintenance of the operating facilities is also provided by the owner. As previously mentioned, the slide gate on the weir in the spillway and the reservoir drain are operated and checked annually.
- 4.4 Warning System: At the present time, there is no formal warning system or evacuation plan in operation. It is recommended that a formal emergency procedure be prepared and prominently displayed, and furnished to all operating personnel. This should include:
 - 1) How to operate the dam during an emergency.
 - 2) Who to notify, including public officials, in case evacuation from the downstream area is necessary.
 - 3) Procedures for evaluating inflow during periods of emergency operation.
- 4.5 Evaluation: Operational procedures are considered adequate for the existing facilities at Lake of the Woods Dam.

NAME OF DAM: LAKE OF THE WOODS

SECTION 5 - HYDRAULIC/HYDROLOGIC DATA

- 5.1 Design: Partial hydrologic and hydraulic design calculations were obtained from the owner. According to the design calculations, dated October 1966, by Bauer Engineering, Inc., the dam and spillway will pass the PMF with a maximum reservoir elevation of 324.2 feet M.S.L. The spillway discharge capacity was computed by Bauer Engineering, Inc. using a weir coefficient of 4.0 for all reservoir heads and a weir length of 50 feet. This would yield a maximum discharge at the top of dam elevation of approximately 4100 c.f.s.
- 5.2 Hydrologic Records: No rainfall or stream flow records were available at the dam.
- 5.3 Flood Experience: No records of high stage were available for this report. However during the heavy rains of July 1969, the reservoir was being filled and rose an additional 6 inches as a result of this rainfall. (Appendix V, p. 10.)
- 5.4 Flood Potential: Performance of the dam and reservoir by routing the PMF, the 1/2 PMF, and the 100-year flood is shown in Table 5.1.
- Surface area and storage capacity data were obtained from the design data. Outlet discharge capacity hydrograph and routing determinations were computed as part of this report for comparison with design assumptions and calculations. Flood routings were started assuming the reservoir level was at normal pool (elevation 317.5 feet M.S.L.).
- 5.5 Reservoir Regulation: Pertinent dam and reservoir data are shown in Table 1.1, paragraph 1.3.3.
- Regulation of flow from the reservoir is automatic under normal conditions. Normal pool (elevation 317.5 feet) is maintained by the crest of the overflow weir in the spillway. Normal outflow from the reservoir passes through this spillway, except for flow through the reservoir drain and slide gate when opened.
- 5.6 Overtopping Potential: The overtopping potential was evaluated by combining three separate inflow hydrographs for each flood analyzed. One inflow hydrograph represented inflow produced by direct runoff from rainfall over the lake surface area of 0.78 square mile. A second inflow hydrograph represented 3.40 square miles of

NAME OF DAM: LAKE OF THE WOODS

watershed in the upper regions of the watershed, which was lagged 2 hours based on travel time behind the lake runoff hydrograph. A third inflow hydrograph represented the remaining 3.05 square miles of watershed, which included primarily the watershed around the lake. This watershed, having a short time of concentration, was lagged only 0.5 hour behind the lake runoff hydrograph. These three hydrographs were combined and routed through the reservoir to determine the outflow hydrograph.

The probable rise in the reservoir and other pertinent information on the reservoir performance in various hydrographs are shown in the following table:

TABLE 5.1 RESERVOIR PERFORMANCE

Item	Hydrographs				
	Normal	100 Year	1/2 PMF	PMF	PMF
Peak flow, c.f.s.					
Inflow	-	5996	12,609	25,218	
Outflow	-	543	2769	13,804	
Peak elev., ft. M.S.L.	317.5	319.6	323.6	326.7	
Spillway					
Depth of flow, ft. (a)	-	1.4	4.1	6.1	
Avg. velocity, f.p.s.	-	6.5	11.4	14.0	
Non-overflow section					
Depth of flow, ft.	-	-	-	-	1.7
Average velocity, f.p.s.	-	-	-	-	3.5
Duration of overtopping, hrs.	-	-	-	-	6.3
Tailwater elev., ft. M.S.L.	262.0	-	-	-	-

(a) Estimated depth at ogee weir based on critical depth.

5.7 Reservoir Emptying Potential: Neglecting inflow, the reservoir elevation may be lowered from normal pool (elevation 317.5 feet M.S.L.) to elevation 310.5 feet M.S.L. in approximately 45 days by use of the two-foot-square, sluice gate outlet on the face of the weir and the 12 inch diameter reservoir drain. The reservoir below the sluice gate invert of elevation 310.5 feet M.S.L. can only be lowered by use of the reservoir drain with a maximum discharge (pool level at elevation 310.5 feet M.S.L.) of 11 c.f.s. Again neglecting inflow, it would take 1 year to lower the reservoir from elevation 310.5 feet M.S.L. to the invert of the

reservoir at elevation 275.0 feet M.S.L. In the event of an emergency, the reservoir could not be emptied in a reasonable time because of the small size of the reservoir drain (12 inch diameter pipe).

- 5.8 Evaluation: Lake of the Woods Dam is classified according to COE criteria as an "intermediate" size-"high" hazard structure requiring passage of a spillway design flood equal to the PMF. The spillway will only pass about 67% of the PMF without overtopping.

However according to design data computed by Bauer Engineering, Inc., the spillway will pass the PMF with a maximum reservoir elevation about 0.8 foot below the top of dam. The differences between the computations for the design and the computations completed as part of this report can probably be attributed to methods of analyses, difference in weir length of spillway, and difference in peak and volume of hydrographs. The peak used for the design hydrograph was 19,300 c.f.s. compared to the 25,200 c.f.s. used for the hydrograph listed in Table 5.1. The assumptions used in computing the design hydrograph are not known.

Therefore, the hydrographs computed as part of this report (shown in Table 5.1) were used in the evaluation of the spillway adequacy because they were considered to more accurately depict the actual conditions found in the field.

The inability to empty the reservoir in a reasonable period of time is considered undesirable and an alternate means of draining the reservoir during an emergency condition should be investigated.

Conclusions pertain to present day conditions and the effect of the future development on hydrology has not been considered.

SECTION 6 - DAM STABILITY

6.1 Foundation and Abutments: There is 3 feet of alluvial, silty sand and gravel (SP/GP) in the bottom of the stream valley with 5 to 8 feet of sandy silt at higher elevations nearer the base of the hills overlying gray, highly weathered gneiss. The slopes in the abutment area are covered by 5 feet of reddish-brown, clayey silt overlying brown and gray, sandy silt with rock fragments (decomposed rock) to a maximum depth of 50 feet. The top of the bedrock is gray and brown, highly weathered gneiss.

6.2 Stability Analysis

6.2.1 Visual Observations: No evidence of instability in the embankment, cut slopes, or concrete structures was observed. The only deficiencies observed were the partial settlement of the backfill adjacent to the left wall of the concrete spillway, and clear seepage and erosion at the end of the wall on the right side (see Photo 6). The flow, from the filter drain and clear seepage in the vicinity of the toe of the dam and parallel drainage ditch, occurs in several areas to the right of the reservoir drain outlet apparently from the covered granular finger outlets. The flow from the collector ditch into the stilling basin for the spillway was measured at 4 g.p.m., which was not considered excessive.

6.2.2 Design Data: The slope stability was checked in 1967 by the Swedish Circle Method for the homogeneous dam embankment. The analysis was computed by Dames and Moore. The embankment section chosen for these analyses had a crest elevation of 325.0 feet M.S.L., upstream slope of 4:1 ratio, and a downstream slope of 3:1. The following shear strength parameters were assumed for the foundation and embankment soils:

	C \varnothing	(p.s.f.)	Unit Weight (p.c.f.)
Homogeneous Embankment	20°	200	115
Foundation (Assumed)	28°	300	120

NAME OF DAM: LAKE OF THE WOODS

The shear strengths for the embankment were determined from the consolidated, saturated, undrained, triaxial shear and direct shear tests. The embankment soil on the slopes was assumed to be saturated. The homogeneous soil was assumed to be compacted to 90% of the maximum dry density. The parameters of the foundation soil immediately underlying the embankment were assumed. The minimum safety factors computed by Dames and Moore for the homogeneous embankment were 1.66 for the upstream slope and 1.35 for the downstream slope. Computations for the downstream slope assumed steady seepage with a straight phreatic line extending from the water level (equal to the spillway crest) on the upstream slope to the filter drain which is based on an adequate performance of the drain. The filter drain is located on the foundation just downstream from the crest.

The upstream slope was also checked at a later date by Bauer Engineering, Inc. A factor of safety of 1.726 for an upstream slope of 3:1 was calculated by the method of slices for a 0.05g seismic factor.

There was no available explanation for the different slope stability criteria used by the two consultants.

The stability analyses data are presented in Appendix VII.

6.2.3 Operating Records: The reports of several inspections of the dam from 1969 to 1972 by engineering firms are included in Appendix V. A few clear seepage zones in the vicinity of the toe of the dam were observed along with erosion areas, slow filling of the reservoir due to possible water loss, clear leakage through cracks in the spillway, and other minor conditions. Remedial measures were recommended for the deficiencies and some were undertaken by the owner, as indicated by the epoxy patching applied to the cracks in the concrete weir.

6.2.4 Post-Construction Changes: No significant alterations to the dam were apparent since it was constructed.

6.2.5

Seismic Stability: Lake of the Woods Dam is located in Seismic Zone 2 near the line of demarcation with Seismic Zone 1. Therefore, it is considered to have no hazard from earthquakes according to the Recommended Guidelines for Safety Inspection of Dams, provided static stability conditions are satisfactory and conventional safety margins exist.

6.3 Evaluation: The embankment section chosen is similar to the as-built drawings except the downstream slope was constructed at a 3.5:1 ratio which would result in a higher safety factor than previously calculated (1.35) for steady state seepage with headwater at the spillway crest. None of the available calculations indicate that stability under rapid drawdown conditions was performed. The 4:1 slope on the upstream side is usually adequate except in cases where the soil strength is extremely low, which is not the case for Lake of the Woods Dam based on available information. However, good engineering practice requires that stability under rapid drawdown should be examined.

SECTION 7 - ASSESSMENT/REMEDIAL MEASURES

- 7.1 Dam Assessment: The dam will pass approximately 67% of the PMF without overtopping which is considered inadequate but not seriously inadequate according to criteria established by the Recommended Guidelines for the Safety Inspection of Dams for an "intermediate" size- "high" hazard category.

Stability analyses were available (Appendix VII) for review. The stability analyses indicated sufficient factors of safety. No evidence of sloughing or seepage indicating embankment distress was observed during the field inspection. The embankments appeared uniform in section with no bulging or areas of depression evident. The grass cover on the embankments was in good condition with the exception of a few small bare areas.

The spillway appears to be functioning adequately. Epoxy patching is leaking (clear) in several places on the weir. There are also small popouts of aggregate on the crest of the weir and in the spillway. These items are not considered to deter proper spillway operation.

- 7.2 Recommended Remedial Measures: It is recommended that continued maintenance of the concrete surfaces in the spillway be provided. The clear leaks in the weir and around the slide gate should be patched where the old epoxy patching is no longer adhering to the concrete.

An alternate means of draining the reservoir in case of an emergency should be investigated immediately by a consultant since the reservoir cannot be drained in a reasonable period of time. In addition, the stability of the upstream slope under rapid drawdown should be examined.

The finger outlets from the filter drain should be located, cleaned, and extended to the drainage ditch along the toe of the dam. The drainage ditch should be cleaned of the tree stumps and other debris, and maintained to provide adequate drainage away from the dam.

The inspection revealed certain preventative maintenance items which should be scheduled as part of an annual maintenance program. These are:

- 1) Rock should be placed over the seepage and erosion area at the end of the right spillway wall beside the stilling basin.

- 2) The area behind the left wall of the spillway where settlement has occurred should be filled with compacted soil and seeded.
- 3) Fill and seed all bare areas on the embankment.
- 4) Remove all trees along the drainage ditch at the toe of the dam.
- 5) Replace any dislodged or missing riprap along the upstream embankment and approach channel to the spillway.
- 6) Remove all driftwood and other debris from the reservoir area.
- 7) Install a staff gage to monitor reservoir levels above normal pool.

NAME OF DAM: LAKE OF THE WOODS

APPENDIX I

PLATES

CONTENTS


Location Plan

Plate 1: General Plan of Dam and Spillway


Plate 2: Sections of Dam


Plate 3: Plan and Profile of Spillway


NAME OF DAM: LAKE OF THE WOODS





LOCATION PLAN
LAKE OF THE WOODS DAM












1. New Retaining Wall - The contractor
will be responsible for the design, fabrication
and installation of the wall, including all labor
and equipment.

2. RETAINING WALL MATERIALS - The contractor
will supply all materials and labor for the construction of the
wall structure and foundation. The contractor will also supply
all the materials required for the backfill and
excavation shown in the plans.



AS BUILT

PLATE 3

VIRGINIA WILDLIFE CLUBS,
INC.

LAKE OF THE WOODS SPURRY

PLAN AND SECTIONS

BABCO ENGINEERING INC.

BY

ONCIAL, JAMES

REV. NO.

Approx. Half Scale

This drawing has been revised to
incorporate all changes during construction
to subsequent joints. Includes written notes
AS BUILT REVISIONS dated 2/27/66

APPENDIX II

PHOTOGRAPHS

CONTENTS

- Photo 1: Head Wall Containing Filter Drainpipe (Left Side of Photo) and Reservoir Drainpipe (Right Side of Photo)
- Photo 2: Discharge Channel for Concrete Spillway
- Photo 3: Riprapped Approach Channel, Concrete Overflow Weir, Lift Pedestal and Slide Gate
- Photo 4: Slide Gate on Downstream Face of Weir
- Photo 5: Spillway, Stilling Pool, and Downstream Channel
- Photo 6: Large, Wet Area on Left Abutment to Right of Spillway

Note: Photographs were taken on 29 November 1978.

NAME OF DAM: LAKE OF THE WOODS

LAKE OF THE WOODS DAM




PHOTO 1. Head Wall Containing Filter Drainpipe (Left Side of Photo) and Reservoir Drainpipe (Right Side of Photo)



PHOTO 2. Discharge Channel for Concrete Spillway

LAKE OF THE WOODS DAM




PHOTO 3. Riprapped Approach Channel, Concrete Overflow Weir, Lift Pedestal and Slide Gate



PHOTO 4. Slide Gate on Downstream Face of Weir.

LAKE OF THE WOODS DAM



PHOTO 5. Spillway, Stilling Pool and Downstream Channel



PHOTO 6. Large, Wet Area on Left Abutment to Right of Spillway

APPENDIX III

CHECK LIST - VISUAL INSPECTION

Check List
Visual Inspection
Phase 1

Name of Dam Lake of the Woods County Orange State Virginia Coordinates Lat. 3821.0
Long. 7745.3

Date Inspection 29 November 1978

Weather Rainy, Cloudy Temperature 50°F.

Pool Elevation at Time of Inspection 317.0 ft. M.S.L. Tailwater at Time of Inspection 262.0 ft. M.S.L.

HII-1

Inspection Personnel:
Virginia Water Control Board:

Roy Murphy
Tim Perry

Michael Baker, Jr., Inc.:

T. W. Smith
W. L. Sheaffer
T. J. Dougan

Owner's Representatives:

Arthur Warren
Dean Morley

I. W. Smith Recorder

EMBANKMENT		REMARKS OR RECOMMENDATIONS
VISUAL EXAMINATION OF	OBSERVATIONS	
SURFACE CRACKS	No surface cracks were observed.	
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	There was no movement or cracking observed.	
III-2 SLOUGHING OR EROSION OF EMBANKMENT AND ABUTMENT SLOPES	No sloughing or erosion of the embankment and abutment slopes was observed.	
VERTICAL AND HORIZONTAL ALIGNMENT OF THE CREST	Good	
RIPRAP FAILURES	The riprap on the upstream slope at normal pool elevation and on the approach channel slopes for the emergency spillway is functioning properly. A few small areas have been partially removed and placed in piles. Grass is growing among the stones in some areas. There is scattered driftwood.	The debris should be removed, and the riprap should be replaced.

EMBANKMENT

Name of Dam: LAKE OF THE WOODS

Sheet 2

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
FOUNDATION	The foundation consists of 3 ft. of alluvial, silty sand and gravel in the bottom of the stream valley with 5 to 8 ft. of sandy silt overlying highly weathered gneiss at higher elevations. On the slopes of the valley, 5 ft. of reddish-brown, clayey silt and silty clay cover brown and gray, sandy silt (decomposed rock) which extends to a maximum depth of 50 ft. The underlying bedrock is a highly weathered, brown and gray gneiss. The subsurface data was obtained from the Report of Soils Exploration prepared by Dames and Moore. The cutoff trench is shown to be 30 ft. wide x 5 ft. deep on the as-built cross-sections.	The bare areas should be seeded.
CONSTRUCTION MATERIALS AND SLOPES	The as-built typical sections and reports indicate that the compacted earthfill was unzoned and homogeneous with an appreciable quantity of silt. The soil observed on the surface consisted primarily of red, clayey silt with traces of rock fragments. Sandy silt and sand, and gravel were present in a few areas. The slopes (4:1 upstream and 3.5:1 downstream) were well-covered with grass, except for a few small bare areas which are primarily in the path on the crest and where some trees had been removed on the downstream slope. The compaction requirement was reduced from 95% to 88% of modified density.	

EMBANKMENT

Name of Dam: LAKE OF THE WOODS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM	The abutments are composed of reddish-brown, clayey silt (5 ft. average depth) overlying brown and gray, sandy silt with rock fragments (decomposed rock) to a maximum depth of 50 ft. The top of the bedrock is highly weathered gneiss. The slope gutters are unpaved and covered with grass. The left abutment slope is moderate with grass cover. A clubhouse is located nearby. There are pine trees with soil erosion on the hill near the approach channel on the left side.	The clear seepage and filter drainage do not appear to be excessive.
ANY NOTICEABLE SEEPAGE	Clear seepage was observed beside the ditch at the downstream toe in several areas apparently from the filter drain outlets. There is a seepage area (20 ft. diameter) extending 6 ft. up from the toe of the dam in the vicinity of the right abutment. The clear seepage may be caused by a partially blocked outlet from the filter drain or groundwater from the knoll at the abutment.	Install a staff gage to monitor reservoir levels above normal pool.
STAFF GAGE AND RECORDER	Water levels of 0.5 ft. are painted on the right spillway wall, immediately upstream of concrete weir.	
DRAINS	Plans show an 8 in. coated perforated filter drain extending along the length of dam from abutment to outletting alongside to the reservoir drainpipe. The 6 in. C.M.P. had 12 g.p.m. of clear flow indicating that the filter is functioning. The plans also show 6 sections of filter material extending from the 8 in. perforated filter drain and outletting at the toe of dam. These outlets appear to be covered by topsoil and grass. A gravel drain with a plastic cover was found at the ditch approximately 265 ft. to the right of the outlet pipe. The drainage ditch which collects the	(continued on next page)

EMBANKMENT

Name of Dam: LAKE OF THE WOODS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
DRAINS (continued)	water from the outlets of the filter drain empties into the stilling basin at the rate of 4 g.p.m. The slopes of the ditch are vegetated with some small trees. The clay and silt slopes are partially eroded at the filter outlets. The ditch near the right abutment area has clear seepage and is blocked with dumped boulders with tree stumps and wood at its upper end.	

Name of Dam: LAKE OF THE WOODS

OUTLET WORKS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	No severe or unusual cracking and spalling of the head wall at the outlet was observed.	
INTAKE STRUCTURE	Intake end of drainpipe was submerged by the reservoir. No observation was possible.	
OUTLET STRUCTURE	Consists of a concrete retaining wall with the 8 in. C.M.P. filter drain outlet and the 12 in. ductile iron outlet pipe. The drain had a clear flow of 12 g.p.m. into the stilling basin. The outlet pipe is controlled by a 12 in. plug valve located 15 ft. from the outlet in a roadway box. There is no flow from the outlet pipe. The outlet structure and stilling basin are shown in Photo 1.	
OUTLET CHANNEL	The outlet channel flows away from the toe of the dam and joins the spillway channel beyond the left abutment. The stilling basin is lined with riprap. A drainage ditch at the toe of the dam flows into the stilling basin. A stream parallel to the ditch flows into the outlet channel downstream.	
EMERGENCY GATE	The reservoir can be lowered by either of two drains:	
	1) The 12 in. reservoir drain could be used to completely drain the reservoir.	
	2) The 2-ft.-square sluice gate located on the face of the spillway weir can be used to drain the reservoir to an elevation of 310.5 ft. M.S.L.	

Name of Dam: LAKE OF THE WOODS

UNGATED SPILLWAY

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE WEIR	The concrete weir of the spillway crest was laid out on a 100-ft. radius and is 46 ft. long. The weir elevation is 317.5 ft. M.S.L. The weir has been patched with epoxy in 9 places; 2 of the patches are leaking. Small aggregate popouts are present in the crest of the ogee weir (see photos 3 and 4).	
APPROACH CHANNEL	The approach channel to the concrete spillway is approximately 50 ft. wide with the side slopes protected by riprap to 5 ft. above normal water level. Sedimentation is minor because the 2-ft.-square sluice gate on the face of the concrete weir is opened yearly to discharge sediment that has built up (see photo 3).	
DISCHARGE CHANNEL	The discharge channel has a 3:1 slope and exits into the stilling basin 150 ft. downstream from the weir. The granular filter drain under the spillway chute outlets through 2 pipes into the stilling basin.	The settlement depressions next to both walls should be back filled, compacted, and seeded. Rock riprap placed at the end of the right wall will prevent erosion in the seepage area.
III-7		The discharge channel has expansion-contraction cracks (photo 5) at approximate 25 ft. intervals. Aggregate popouts are present. There is settlement (up to 2 ft. deep) in the soil backfill behind the right wall in the lower portion with erosion at the end and settlement at the end on the left side. A seepage-erosion area of the end of the right wall is shown in photo 6.
BRIDGE AND PIERS		None
SLIDE GATE		The slide gate itself is in good condition. Some leakage in the stem of the weir section is present adjacent to the slide gate. The epoxy patchwork has lost its bonding ability and is separating from the concrete.

Name of Dam: LAKE OF THE WOODS

INSTRUMENTATION

<u>VISUAL EXAMINATION</u>	<u>OBSERVATIONS</u>	<u>REMARKS OR RECOMMENDATIONS</u>
MONUMENTATION/SURVEYS	None observed	
OBSERVATION WELLS	None	
WEIRS	None	
PIEZOMETERS	None	
OTHER		

RESERVOIR

Name of the Dam: LAKE OF THE WOODS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SLOPES	The slopes are gentle to steep and partially wooded. The area has some recreational facilities. There has been erosion in the steep weathered bedrock slopes for the marina and the soil slopes in some of the tributaries which had been noted in the inspection report by E. D'Appolonia in 1969. An increase in the erosion could affect the access roadway.	
SEDIMENTATION	Very minor sedimentation is located immediately upstream at the concrete weir along the right wall.	
GOLD MINE	The shaft of an old gold mine in the reservoir near the approach channel of the emergency spillway was filled with 10 c.y. of concrete and a reinforced concrete cap was placed at the entrance as shown on the as-built drawings (see Plate 1). No details concerning the extent of the mine are known. The maximum dimensions of the shaft are 8 ft. x 14 ft. x unknown depth. x	

Name of Dam: LAKE OF THE WOODS

DOWNSTREAM CHANNEL

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONDITION (OBSTRUCTIONS, DEBRIS, ETC.)	The channel is lined with riprap for a short distance downstream of the stilling basin and is generally free of obstructions and debris. Photos 5 and 6 show the downstream channel and a seepage area on the right side at the end of the spillway.	
SLOPES	The slopes are varied with some clear seeps and small springs. The springs are principally near the base of the left hillside, 300 ft. past the end of the concrete spillway. There is a steeply dipping exposure of weathered metamorphic bedrock (uncertain age) with igneous intrusions at approximately 400 ft. downstream where reeds have grown. A clear seep in the right bank has caused erosion in the clay, silt, and sand 500 ft. downstream. Soft bedrock is in the streambed.	
APPROXIMATE NO. OF HOMES AND POPULATION	A treatment plant for the development is located 500 ft. downstream of the dam.	A new development is planned directly downstream of the dam.

APPENDIX IV

CHECK LIST - ENGINEERING DATA

CHECK LIST
ENGINEERING DATA
DESIGN, CONSTRUCTION, OPERATION

Name of Dam:	LAKE OF THE WOODS	REMARKS
PLAN OF DAM	A complete set of as-built drawings are available from the owner. A plan view of the dam is included in this report as Plate 1.	
REGIONAL VICINITY MAP	is included in report as Location Plan.	
CONSTRUCTION HISTORY	The foundation investigation was done in 1966 by Dames and Moore. The dam was designed by Bauer Engineering, Inc. (Chicago, Illinois) in 1966 and constructed by Shoosmith Bros., Inc. in 1967 and 1968.	
IV-TYPICAL SECTIONS OF DAM	Typical section of the dam is enclosed in the Phase 1 Inspection Report as Plate 2.	
HYDROLOGIC/HYDRAULIC DATA	Partial hydrologic and hydraulic design data is available from the owner.	
OUTLETS - PLAN,		
DETAILS,		
CONSTRAINTS, and DISCHARGE RATINGS	are available from the owner.	
RAINFALL/RESERVOIR RECORDS	Rainfall and reservoir level records are available from the owner.	

Name of Dam: LAKE OF THE WOODS

<u>ITEM</u>	<u>REMARKS</u>
DESIGN REPORTS	Design reports, calculations, and specifications as prepared by Bauer Engineering, Inc. are available from the owner.
GEOLOGY REPORTS	A subsurface investigation consisting of test pits and test borings are part of the design documents. A report of soils investigation is available and enclosed in Appendix VI.
DESIGN COMPUTATIONS HYDROLOGY & HYDRAULICS DAM STABILITY SEEPAGE STUDIES	Dam stability analyses and seepage studies were available. Stability analyses are enclosed in Appendix VII.
MATERIALS INVESTIGATIONS BORING RECORDS LABORATORY FIELD	Materials investigations, boring records, laboratory test results, and field data were available.
POST-CONSTRUCTION SURVEYS OF DAM	Several inspections and reports were made between 1969 and 1972 by engineering firms (Appendix V). Remedial recommendations were prepared.
BORROW SOURCES	The borrow pit was located on the hillside upstream from the right abutment in the reservoir area as shown on the General Plan of the as-built drawings (Plate 1).

Name of Dam: LAKE OF THE WOODS

<u>ITEM</u>	<u>REMARKS</u>
MONITORING SYSTEMS	No monitoring system was designed into the dam.
MODIFICATIONS	Some relatively minor modifications which included surface maintenance were recommended after the inspections (Appendix V). It is not known whether all of them were carried out.
HIGH POOL RECORDS	No high water records were available.
POST-CONSTRUCTION ENGINEERING STUDIES AND REPORTS	Post-construction engineering studies and inspection reports were available (Appendix V).
PRIOR ACCIDENTS OR FAILURE OF DAM DESCRIPTION REPORTS	None
Maintenance OPERATION RECORDS	Recent inspection reports were not available.

Name of Dam: LAKE OF THE WOODS

<u>ITEM</u>	<u>REMARKS</u>
SPILLWAY PLAN,	
SECTIONS and DETAILS	Sections and details of the ungated concrete spillway are enclosed as Plate 3.
OPERATING EQUIPMENT PLANS & DETAILS	are contained in the as-built drawings.

CHECK LIST
HYDROLOGIC AND HYDRAULIC DATA
ENGINEERING DATA

DRAINAGE AREA CHARACTERISTICS: 7.23 sq.mi.

317.5 ft. M.S.L.

ELEVATION TOP NORMAL POOL (STORAGE CAPACITY): (9880 ac.-ft.)

325 ft. M.S.L.

ELEVATION TOP FLOOD CONTROL POOL (STORAGE CAPACITY): (14,160 ac.-ft.)

ELEVATION MAXIMUM DESIGN POOL: 324.2 ft. M.S.L.

ELEVATION TOP DAM: 325.0 ft. M.S.L.

CREST: Principal Spillway

- a. Elevation 317.5 ft. M.S.L.
- b. Type Overflow type concrete spillway
- c. Width 46 ft. crest width
- d. Length Approximately 210 ft.
- e. Location Spillover Outside left abutment
- f. Number and Type of Gates 1 slide gate (2-ft.-sq.) on left side of weir (elev. 310.5 ft. M.S.L.)

OUTLET WORKS: Reservoir Drain

- a. Type 12-in. diameter ductile iron pipe
- b. Location Exits at toe of dam near center of embankment
- c. Entrance inverts 275.0 ft. M.S.L.
- d. Exit inverts 265.7 ft. M.S.L.
- e. Emergency draindown facilities 2 x 2 ft. sluice gated outlet and 12 in. dia. blow-off pipe

HYDROMETEOROLOGICAL GAGES: None at dam site

- a. Type _____
- b. Location _____
- c. Records _____

MAXIMUM NON-DAMAGING DISCHARGE Unknown

Name of Dam: LAKE OF THE WOODS

APPENDIX V

INSPECTION REPORTS

BAUER ENGINEERING INC
CONSULTING ENGINEERS ENGINEERING HYDRAULICS
20 NORTH WACKER DRIVE
CHICAGO, ILLINOIS 60606

TELEPHONE
MURKIN 2-8800

TELETYPE
BAUEREN 2-CHICAGO

PROGRESS REPORT NO. 2

Lake of the Woods -- Dam Construction

As of April 21, 1967

After being closed for the winter months, construction on the main dam resumed April 12, 1967. Although the work proceeded slowly during the first week progress was steady.

Attaining the 95% (Modified AASHO) requirement remains a serious problem. Great effort is required by the contractor to dry and roll the variable soil encountered.

The compaction results indicate the following (as of 4/21/67):

Total tests taken -----	10
Range of test results -----	84% to 101%
Number of tests passing-----	3
Number of tests failing -----	7
Number of failing tests improved after rerolling -----	3
Moisture content range -----	18.3% to 26.6%
Average field moisture content -----	23.4%
Average optimum moisture-----	21.3%

With a concerted effort, the required densities on the average can be obtained.

The filter drain material was delivered and checked for gradation. The gradation indicates the material falls within the requirements and was approved.

The cutoff trench had been partially backfilled December, 1966 and through the winter months was saturated with water. This material was removed to the rock layer beneath and backfilled with selected soil.

Tests indicate 100% compaction achieved.

The temporary dam was completed during the winter and appears to be operating very well. Water has been impounded to the overflow elevation and the overflow pipe is operating as expected. No adverse effects were observed.

SUMMARY

Progress on the main dam is proceeding slowly. Complying with compaction requirements remains a problem. The Contractor will have to take extra care to insure the material being rolled has a low enough moisture content to achieve specified compaction, thus assuring a satisfactory end result.

Donald W. Wikan
Donald W. Wikan

DWW:fb

BAUER ENGINEERING, INC.
CONSULTING ENGINEERS. ENGINEERING HYDRAULICS
20 NORTH WACKER DRIVE
CHICAGO, ILLINOIS 60606

TELEPHONE
FRANKLIN 2-0666

CABLE ADDRESS
"BAUERENG CHICAGO"

March 21, 1968

RECEIVED
3-22-68

Mr. Wesley T. Butler
Virginia Wildlife Clubs, Inc.
United States Land, Inc.
P.O. Box 631
Springfield, Virginia 22150

J. KEATING
~~J. FORD~~

KA

Subject: Lake-of-the-Woods

Dear Mr. Butler:

On March 6, 1968 a final inspection of the dam, spillway and appurtenance work was made by me and Earl Turner, our engineer - inspector for the above project. We were accompanied by Mr. Jack Schaul of your organization and Mr. Bill Cantrell of Shoosmith Brothers.

We are pleased to report that the construction work is substantially completed in accordance with the plans and specifications except the fine grading, seeding and fertilizing in the spillway area beyond the chute and stilling basin walls, and in the vicinity of the plunge pool. This work should be completed soon after the backfill adjacent to the chute walls has subsided and been re-graded, and the weather permits.

We are preparing a set of as-built drawings and a tabulation of final quantities for the project, and hope to have this information in your hands in about a week.

Mr. Wesley T. Butler...Mar. 21, 1968...RLH...2

The dam and spillway present an excellent appearance,
and we believe that both United States Land and Shoosmith Brothers
can be proud of the fine results.

It has been a pleasure for our firm to be associated
with you on this project, and we send our best wishes for your
continued success.

Very truly yours,


R. L. Hall
Chief Engineer

RLH:db

cc: Mr. J. S. Keating
Mr. Jack Ford ✓
Mr. Jack Schaul
Mr. Gay Jones
Shoosmith Bros., Inc.

Project No. 69-181

**BOISE CASCADE PROPERTIES, INC.
CHICAGO, ILLINOIS**

**LETTER REPORT
INSPECTION OF DAM AND RESERVOIR
LAKE OF THE WOODS
ORANGE COUNTY, VIRGINIA**

**E. D'APPOLONIA
CONSULTING ENGINEERS, INC.
PITTSBURGH, PENNSYLVANIA**

OCTOBER 1969

V-5

E. D'APPOLONIA
CONSULTING ENGINEERS, INC.

October 27, 1969

15 OUFF ROAD
PITTSBURGH, PA. 15235

TELEPHONE
(412) 242-5107

Project No. 69-181

Mr. John Margosian
Boise Cascade Properties, Inc.
Lake of the Woods
P. O. Box 128
Springfield, Virginia 22401

Inspection of Dam and Reservoir
Lake of the Woods
Orange County, Virginia

Dear Mr. Margosian:

Enclosed are two copies of our letter report discussing the results of our inspection of the dam and reservoir at the Lake of the Woods project. We were initially requested to review the performance of the reservoir with respect to filling. However, as I have indicated in telephone conversations, certain other conditions at the site deserve discussion. Therefore, in addition to the section on filling, our letter report discusses other adverse conditions along with recommendations concerning remedial and preventive measures.

As requested, we are preparing a single invoice reflecting all of our costs on this project. The two previous, partial invoices should be ignored when the total invoice is submitted. I will include a description of the various cost items for your information.

Please feel free to call pertaining to any of the subjects discussed in the report.

Very truly yours,

Richard D. Ellison

Richard D. Ellison

RDE:pao

Enclosures

cc: Mr. J. W. Ford (2)

E. D'APPOLONIA
CONSULTING ENGINEERS, INC.

TABLE OF CONTENTS

Letter Report

Appendix A

Drawings (in folders)

E. D'APPOLONIA
CONSULTING ENGINEERS, INC.

October 25, 1969

15 DUFF ROAD
PITTSBURGH, PA. 15235

TELEPHONE
(412) 242-3107

Project No. 69-181

Mr. John Margosian
Boise Cascade Properties, Inc.
Lake of the Woods
P. O. Box 128
Springfield, Virginia 22401

Letter Report
Inspection of Dam and Reservoir
Lake of the Woods
Orange County, Virginia

Dear Mr. Margosian:

Pursuant to Mr. J. W. Ford's authorization in June, 1969, we conducted a visual inspection of the dam and reservoir at the subject site. Pertinent design and as-built drawings prepared by Bauer Engineering Company were also examined. Initially, the purpose of the examination was to assess the behavior of the dam and reservoir to date with respect to its filling rate and to make appropriate comments and observations. However, during the above examination and as subsequently discussed with Mr. Ford, additional conditions related to the condition of the dam and reservoir were noticed for which recommendations concerning remedial and preventive measures are also reported herein.

Description of Dam

The dam has a maximum height of almost 60 feet above the bed of Flat Run. It is of homogenous section except for the drainage system beneath the downstream portion of the embankment. The material in the dam was borrowed from the reservoir area immediately upstream of the dam. Examination of soils in the area indicates that this material contains an appreciable quantity of silt-sized particles and that its permeability when compacted is relatively low.

The downstream sub-embankment drainage system consists of a lateral filter, parallel to the dam axis, with embedded pipe draining from both sides towards the old bed of Flat Run. The system then runs along the creek bed and discharges at the toe of the dam. There is no indication that it is not functioning properly.

E. D'APPOLONIA
CONSULTING ENGINEERS, INC.

Mr. John Margosian

- 2 -

October 25, 1969

The lateral drain, which is located immediately downstream of the axis of the dam, is augmented by "fingers" of filter material running transverse to the axis of the dam and presumably draining towards the toe. The downstream ends of these drains have apparently been covered with topsoil.

The performance of these finger drains is not known. A narrow strip of wet soil, as discussed below, exists just downstream of the toe of the dam. This would seem to indicate that at least some of the drains are functioning properly. However, as will be discussed, this wet zone could have a different origin.

Two important changes were made to the embankment design during construction of the dam. First, impervious blankets were provided in two parts of the borrow areas. They were apparently in response to the porous nature of the bedrock. Second, the 3:1 design slopes were changed to 3.5:1 downstream and 4:1 upstream. The reasons for the slope changes are not known.

Another change made during construction was to provide a continuous filter system under the spillway chute. The water collected in this filter discharges through two pipes into the stilling basin. The pipes are presently discharging water which would indicate that the drainage system under the chute is operating.

The as-built drawings show an abandoned mine shaft just upstream of the spillway channel. The shaft is presently under water. No details concerning the extent of the mine are available.

A 6-inch pipe has been installed through the embankment adjacent to the right abutment. The pipe is close to the crest of the dam and serves no apparent purpose.

Performance of the Dam

The reservoir is presently being filled for the first time, and two seepage zones have appeared downstream of the dam. The approximate extent of the seepage zones as of August 17, 1969 is sketched in Drawing No. 69-181-El. At that time, the reservoir was 4.75 feet below design elevation. (We understand that the lake level rose an additional 1.0 to 1.5 feet during the heavy rains associated with Hurricane Camille during the week of August 17, 1969) No correlation between the height of the reservoir and the seepage phenomena is available.

One seepage zone, (A)*, is entirely in cut downstream of the spillway stilling basin. Because of the proximity of the drainage blanket under the spillway chute, it would appear that the seepage zone may be fed from deeper within the underlying rock.

*Letters designated as () correspond to similarly designated areas on Dwg. 69-181-El.

E. D'APPOLONIA
CONSULTING ENGINEERS, INC.

Mr. John Margosian

-3-

October 25, 1969

The other seepage zone, (B), is in undisturbed ground downstream of the right abutment. This zone has extended into the dam embankment along a distance of approximately 100 feet. The maximum intrusion up the embankment is about 8 feet measured vertically.

A portion of Seepage Zone (B) is located over one of the finger drains described above. The downstream end of the drain was not located in the field because it apparently was covered during dressing of the slope. If the finger drain were functioning properly it would be expected to yield some water flow.

Part of Seepage Zone (B) runs in a narrow strip parallel to the toe of the dam. It may be that this "wet" strip is caused by discharge from the finger drains and not from seepage through the foundation of the dam. The other portion of the seepage zone undoubtedly is affected by seepage from the reservoir through the bedrock since it is directly across the creek bed paralleling the toe of the dam. It is difficult to judge whether the source of this seepage is primarily from groundwater flow out of the knoll to the west or if it is primarily due to increased groundwater pressure resulting from the partially filled reservoir. Records of the preconstruction condition of this area would be valuable in determining the source of this seepage.

Several surface erosional features have appeared on and around the dam. Shallow gullies, (C), have developed on the entire lower portion of the downstream slope; along the toe of the dam on the north side of the discharge basin for the under drain discharge pipes (D); and north of and generally parallel to the excavation for the spillway discharge channel, (E).

The water in the reservoir immediately adjacent to the riprap on the upstream slope of the dam is reddish in color. This indicates that a certain amount of erosion is taking place. Since the reservoir at time of observation was 4.75 feet below design elevation, it is not known whether the erosion is taking place below the riprap or through the lower portion of the riprap.

Erosion, due to rainfall runoff, is present at the portion of the spillway approach channel not protected with riprap, (G). Additional erosion should be expected when the water level rises and continual flow occurs through the channel.

Performance of the Reservoir

Filling of the reservoir commenced in 1967. The water level on August 17, 1969 was 4.75 feet below the design elevation. Because the time of filling thus far is still in the range of the estimates made by Bauer Engineering Company (35 months) and E. D'Appolonia Consulting Engineers, Inc. (23 months), conclusions regarding the rate of filling cannot be made at this time. However, it is somewhat disturbing that it has been reported that the reservoir rose only about six inches during July, 1969, while the local rainfall was about twice that amount. The rate of filling should be observed, in

E. D'APPOLONIA
CONSULTING ENGINEERS, INC.

Mr. John Margosian

- 4 -

October 25, 1969

relation to rainfall, through the spring of 1970 prior to evaluating the time which will be required to fill the remainder of the lake.

An analysis of the flow into the reservoir was conducted on August 16 and 17, 1969. The flow into the lake was measured at each stream entering the lake at the locations shown on Dwg. 69-181-E2. The total inflow at the time of measuring was about 1.5 gallon per second. The total surface flow out of the reservoir was determined by measuring the flow in the discharge channel downstream from the dam. This flow was corrected to account for flow in the 36 inch diameter culvert located downstream from the south abutment as shown on Dwg. 69-181-E2. This analysis indicated that the reservoir on that date was filling at the rate of about 0.2 gallons per second; neglecting sub-surface inflow and outflow which cannot be measured. (Details of the analysis are presented in Appendix A). This amount of inflow would have a negligible effect on the lake level.

It should also be noted that due to the relatively large size of the lake, the measured amount of surface leakage will not seriously effect the lake level once it has filled to the planned normal pool elevation.

Miscellaneous Observations Pertaining to the Reservoir

Two less serious problems associated with the reservoir were observed on August 17, 1969.

First, gullies several feet in depth have been eroded into the steep slopes cut into weathered rock to form the boat marina. The incompetent nature of the weathered rock and the concentrated flows which occur in this area make this a progressive condition.

The second concerns erosion of the surficial soils at many of the tributaries into the lake. In several instances, this erosion has progressed to the point where the stability of the site roadway may be affected.

Recommendations for Remedial and Preventive Measures

1. Dam and Appurtenances

Both seepage zones downstream of the dam can be expected to increase in size and rate of discharge as the reservoir rises to design elevation. The correlation between seepage discharge and reservoir discharge is purely conjectural at this time. However, it is entirely possible that the discharge will increase significantly with the last few feet of head. The present rate of seepage will not significantly affect the lake level once it has reached the design normal pool elevation and should not be sufficient to pose a threat to the overall stability of the dam due to piping. However, it is recommended that size of the seepage zones and the seepage discharge be closely observed so that large changes will be recognized at an early date. Also, that portion

E. D'APPOLONIA
CONSULTING ENGINEERS, INC.

Mr. John Margosian

- 5 -

October 25, 1969

of the dam toe included in seepage zone (B) should be inspected regularly for evidence of piping or local shear failure.

As soon as possible the finger drains entering seepage zone (B) should be located and exposed to provide free flow of water from beneath this portion of the embankment. The flow from this finger drain as well as all other seepage from this zone should be collected into a well defined channel (F) and diverted to the old stream bed. This channel should be placed as far from the toe of the dam as possible.

If the condition of the toe of the dam deteriorates to the point where it poses a threat to stability, an inverted filter should be designed and placed over the significant portion of the seepage zone. This can be designed to protect against both piping failure and local shear failure.

It is not anticipated that seepage in the vicinity of the stilling basin will pose any threat to stability in the near future. However, it may be desirable for esthetic purposes and for prevention of problems with freezing behind the wall to provide drainage facilities behind the retaining walls of the stilling basin.

The erosion gullies do not at this time present any threat to the stability of the dam. However, due to the progressive nature of such erosion, it is prudent that preventive measures be taken as soon as possible. A shallow berm with paved gutters or half-round terra-cotta pipe gutters should be constructed about one-third way up the downstream face of the dam to collect runoff from the slope. Also, a lined terra-cotta pipe channel should be provided along the toe of the dam to the north of the discharge basin in the area designated as (D) on Dwg. 69-181-El. The shallow erosion gullies, (C), on the downstream slope should be filled and seeded. Remedial and preventive work on the erosional features to the north of the discharge channel can be postponed indefinitely, but periodic observations should be made for re-evaluation of this condition.

The riprap in the spillway approach channel, (G), should be extended to the concrete structure to prevent further erosion in this area.

It is not possible at this time to determine whether the erosion of the dam at the present water line is taking place through the riprap or at a lower elevation. No remedial work in this area is recommended until the reservoir level is raised and the behavior of the riprap can be observed further. However, if the reservoir is maintained at or near its present level for a considerable period of time, the upstream face of the dam below the riprap should be inspected by one of our engineers trained in scuba diving.

It is not expected that the pipe through the top of the dam, (H), will ever carry water. Nevertheless, it should be removed or permanently sealed.

E. D'APPOLONIA
CONSULTING ENGINEERS, INC.

Mr. John Margosian

- 5 -

October 25, 1969

of the dam toe included in seepage zone (B) should be inspected regularly for evidence of piping or local shear failure.

As soon as possible the finger drains entering seepage zone (B) should be located and exposed to provide free flow of water from beneath this portion of the embankment. The flow from this finger drain as well as all other seepage from this zone should be collected into a well defined channel (F) and diverted to the old stream bed. This channel should be placed as far from the toe of the dam as possible.

If the condition of the toe of the dam deteriorates to the point where it poses a threat to stability, an inverted filter should be designed and placed over the significant portion of the seepage zone. This can be designed to protect against both piping failure and local shear failure.

It is not anticipated that seepage in the vicinity of the stilling basin will pose any threat to stability in the near future. However, it may be desirable for esthetic purposes and for prevention of problems with freezing behind the wall to provide drainage facilities behind the retaining walls of the stilling basin.

The erosion gullies do not at this time present any threat to the stability of the dam. However, due to the progressive nature of such erosion, it is prudent that preventive measures be taken as soon as possible. A shallow berm with paved gutters or half-round terra-cotta pipe gutters should be constructed about one-third way up the downstream face of the dam to collect runoff from the slope. Also, a lined terra-cotta pipe channel should be provided along the toe of the dam to the north of the discharge basin in the area designated as (D) on Dwg. 69-181-El. The shallow erosion gullies, (C), on the downstream slope should be filled and seeded. Remedial and preventive work on the erosional features to the north of the discharge channel can be postponed indefinitely, but periodic observations should be made for re-evaluation of this condition.

The riprap in the spillway approach channel, (G), should be extended to the concrete structure to prevent further erosion in this area.

It is not possible at this time to determine whether the erosion of the dam at the present water line is taking place through the riprap or at a lower elevation. No remedial work in this area is recommended until the reservoir level is raised and the behavior of the riprap can be observed further. However, if the reservoir is maintained at or near its present level for a considerable period of time, the upstream face of the dam below the riprap should be inspected by one of our engineers trained in scuba diving.

It is not expected that the pipe through the top of the dam, (H), will ever carry water. Nevertheless, it should be removed or permanently sealed.

E. D'APPOLONIA
CONSULTING ENGINEERS, INC.

Mr. John Margosian

- 6 -

October 25, 1969

2. Reservoir filling

While concern over the slow filling rate of the reservoir is well founded, "filling time" calculations indicate that additional time should be allowed before concluding that the lake will not reach its normal pool elevation without expensive remedial or artificial filling measures. A rational decision on whether to implement such plans could be made after correlation of reservoir level, local rainfall data and seepage data this winter and spring (1969 - 1970). The present magnitude of surface seepage will not have a significant effect upon maintaining a relatively constant lake level.

3. Reservoir (Miscellaneous)


Riprap protection should be provided at the road culverts for any tributaries where the erosion may cause costly disturbance to the roadway or culvert. 

Finally, the cut slopes at the marina should be made flatter and/or a paved gutter should be provided along the top of the slope to retard the progressive erosion which is presently occurring. Also, riprap should be provided at the toe of the slope to eliminate erosion due to wave action which will occur when the lake level has reached its normal pool elevation. 

Data Required

Additional information which will be required prior to conducting a more detailed study and prior to undertaking the recommended preventive and remedial measures include geologic reports prior to construction, geologic data obtained during construction, engineering properties of embankment material, and details of the mine shaft at the north abutment. Also, plans showing the location of roads and utilities are required for locating these facilities in the construction area.

Respectfully submitted,


Richard D. Ellison

Attachments

RDE:db

APPENDIX A

V-15

E. D'APPOLONIA
CONSULTING ENGINEERS, INC.

Lake of the Woods
Summary of Measured Flows
August 16 and 17, 1969

I: Surface inflows (see Dwg. 69-181-E2 for Tributary Locations)

<u>Tributary Number</u>	<u>Remarks</u>	<u>Measured Flow in gallons/second</u>
1A		dry
1B		dry
1C	Erosion has occurred to a depth of two feet. Some groundwater seepage is noticeable.	0.10
1D	Very little flow from flat swamp area.	TSTM*
2	30" ϕ culvert with considerable erosion at its outlet.	TSTM
3	Kaolinite weathered gneiss.	TSTM
4	30" ϕ culvert with considerable erosion in weathered rock at the road embankment.	dry
5A	18" ϕ culvert.	dry
5B	Kaolinite weathered grey granite - gneiss.	0.05
6	Very weathered schists.	0.05
7	42" ϕ culvert.	0.10
8A		dry
8B		dry
9A		dry
9B		TSTM

*TSTM - Too small to measure.

E. D'APPOLONIA
CONSULTING ENGINEERS, INC.

2.

<u>Tributary Number</u>	<u>Remarks</u>	<u>Measured Flow in gallons/second</u>
10A		TSTM
10B	Some erosion has occurred in the weathered rock.	0.15
11	Erosion has occurred to a depth of 4 to 5 feet.	0.15
12		TSTM
13		0.05
14		0.50
15A		dry
15B		dry
15C		dry
15D		dry
16		0.05
17		TSTM
18	Erosion has occurred to a depth of 4 feet.	0.05
19		TSTM
20	Some ground water seepage noticeable.	TSTM
21	Erosion has occurred to a depth of 1.5 feet. Some ground water seepage is noticeable.	dry
22		dry
23A	Erosion is occurring in the weathered rock Some ground water seepage is noticeable	TSTM
23B	Erosion has occurred to a depth of 3 feet. Some ground water seepage is noticeable.	TSTM
24	36" φ culvert.	TSTM

E. D'APPOLONIA
CONSULTING ENGINEERS, INC.

3.

<u>Tributary Number</u>	<u>Remarks</u>	<u>Measured Flow in gallons/second</u>
<u>Tributary Number</u>	<u>Remarks</u>	
25		dry
26	Very little erosion	dry
27	Erosion has occurred to a depth of 2 feet	TSTM
28A		dry
28B		dry

Summary of Inflow

Tributaries 1 to 28B	1.20 gallon/second
+ 14 x TSTM	<u>0.30</u> gallon/second
Total surface inflow	1.50 gallon/second

II: Surface outflow

Flow at the local road downstream at the outflow channel	1.5 gallon/second
Flow through culvert ϕ 36" at south abutment	- <u>0.2</u> gallon/second
Total surface outflow	1.30 gallon/second

III: Net surface inflow = $1.50 - 1.30 = 0.20$ gallon/second.

RECEIVED

SEP 4 1970

OPERATIONS
E&E

BAUER ENGINEERING, INC.
CONSULTING ENGINEERS LAND AND WATER RESOURCES
20 NORTH WACKER DRIVE
CHICAGO, ILLINOIS 60606

TELEPHONE
(312) 641-0210

August 27, 1970

CABLE ADDRESS
BAUERENG CHICAGO

Mr. Dominic DiOrio
Eastern Region Operations Manager
Boise Cascade Corporation
10400 W. Higgins Road
Rosemont, Illinois 60618

Re: Inspection Report Dam at Lake
of the Woods 198.001

Dear Mr. DiOrio:

A thorough inspection of the main dam at Lake of the Woods, Virginia was made August 17, 1970 at your request. In general, the dam appeared to be in excellent condition.

The enclosed check list was used and appropriate comments made.

Please Note the following corrective actions are indicated as being necessary:

1. TOP OF DAM

The top of the dam appears to be irregular and rutted. A profile should be made along the center line of the dam to determine if the dam is at the designed grade. Since no bench marks may be available, I suggest the elevation of the spillway crest be used as elevation 317.5. The dam then should have an elevation no lower than 325 or 7.5 feet above the spillway crest. If it is found that the elevation of the top of dam is lower than elevation 325 material, either clay or well graded crushed rock, should be added. If clay is used the existing surface should be scarified and the new material rolled with a sheep's foot in layers not exceeding 8 inches thick.

If the elevation is found to be higher than 325, the top should be scarified and reshaped with a blade in order to obtain a uniform section which will drain (preferably into the lake) and which has no ruts.

2. ABUTMENTS

Generally the abutments are in excellent condition. No seepage was noted where the fill contacts the original ground. However, some erosion was noticed at the downstream slope of the north abutment. The grade is steep and a grass cover from seed will be difficult to grow. Sod is suggested here in order to stop further deterioration.

3. DOWNSTREAM SLOPE

This also appears to be in good condition. No adverse seepage is evident. One filter drain is flowing slowly, but this is normal and will cause no trouble. Some erosion was noticed. The downstream slope should be repaired and seeded such that a good stand of grass checks further erosion. Regular mowing should be done in order to prevent trees from growing.

A wrench should be provided for the outlet valve.

4. DOWNSTREAM FROM TOE

No problems noted.

5. SPILLWAY

Generally the spillway is in excellent condition. Some small hairline cracks were noted. These are simply shrinkage and in no way will impair the performance of the concrete. In time (2 or 3 years) these cracks may become larger. At that time they could require cleaning, widening and filling with a sealant. I suggest using "Sika Colma Joint Sealer - NS" in accordance with Manufacturer's instructions.


Mr. Dominic DiOrio

Page 3

This dam appears to be in excellent condition and is safe.


I hope this report serves your needs. If I can be of any more service please let me know.

Yours very truly,



D. W. Wikan P.E.
Chief Engineer

DWW:mb



W. J. Bauer
President

**ENGER
ENGINEERING,
INC.**

Job No. 198.001 Date 8/17/70
Job Name Lake of the Woods
Client Rois & Cascade

DAM INSPECTION CHECK LIST

UPSTREAM SLOPE

1. EROSION

1. A. SLOPE ABOVE WATER No erosion - good condition
1. B. SLOPE BELOW WATER Could not see below water line
1. C. RIPRAP Good condition
1. D. RIPRAP FILTER Good condition
1. E. ANIMAL BURROWS None seen
1. F. CRACKS None
1. G. SLIDES OR SLOUGHS None

5. REMARKS

Generally good condition

TOP OF EMBANKMENT

1. CRACKS

1. 2. SETTLEMENT (OR CONSOLIDATION) Some - check profile
1. 3. DRAINAGE OF TOP (EROSION, etc.) Poor - should fill & regrade to slope to Lake
1. 4. ANIMAL BURROWS None
1. 5. REMARKS Run profile, bring to planned elevation or higher throatout

ABUTMENTS

1. EROSION AT CONTACT OF EMBANKMENT & ABUTMENT Some (should sod)
2. SEEPAGE AT JUNCTION OF EMBANKMENT & ABUTMENT None
3. EROSION FROM SURFACE DRAINAGE Not serious
4. WET SPOTS AT ABUTMENT None
5. SPRINGS - GULLIES - BOILS - etc. None
6. REMARKS Generally in good condition

DOWNTREAM SLOPE

1. CRACKS None
2. SLIDES OR SLOUGHS None
3. SEEPAGE At drains only which is proper

DAUER
ENGINEERING,
INC.

Job No. _____ Date _____
Job Name _____
Client _____

DAM INSPECTION CHECK LIST (CONT'D)

4. BRUSH	None	
5. DAMP OR WET "BANDS"	None	
6. FILTER - FREE DRAINING?	Yes	IS WATER CLEAR? Yes
7. PIPE DRAIN - OBSTRUCTIONS?	None	VALVE No wrench to operate
8. SLOPE EROSION	Some -	should repair and seed or sod
9. REMARKS	In general looks good - slight erosion should be repaired. No need to worry about wet spots these will gradually diminish	
DOWNSTREAM FROM TOE		
1. BOILS	None	
2. EROSION GULLIES	None	
3. OTHER WET SPOTS	None noticed	
4. REMARKS	OK	
SPILLWAY		
1. COMPARE WITH PLANS	OK	
2. DEBRIS	None	Slight 1/8" to hairline, not serious at this time, eventually should be cleared
3. CRACKS	None	
4. HOLLOW CONCRETE	None	
5. SLIDE GATE	Leaks -	should adjust wedges
6. EROSION AROUND WALLS, etc.	None	
7. REINFORCING STEEL EXPOSED	None	
8. OUTLET CHANNEL	OK	Generally in excellent condition
9. REMARKS		

**CHIQUER
ENGINEERING,
INC.**

Job No. 193.001 Date 6/17/70
Job Name Lake of the Woods
Client Bois Cascade

DAM INSPECTION CHECK LIST

UPSTREAM SLOPE

1. EROSION

A. SLOPE ABOVE WATER No erosion - good condition

B. SLOPE BELOW WATER Could not see below water line

C. RIPRAP Good condition

D. RIPRAP FILTER Good condition

2. ANIMAL BURROWS None seen

3. CRACKS None

4. SLIDES OR SLOUGH'S None

5. REMARKS Generally good condition

TOP OF EMBANKMENT

1. CRACKS None

2. SETTLEMENT (OR CONSOLIDATION) Some - check profile

3. DRAINAGE OF TOP (EROSION, etc.) Poor - should fill & regrade to slope to lake

4. ANIMAL BURROWS None

5. REMARKS Run profile, bring to planned elevation or higher throughout

ABUTMENTS

1. EROSION AT CONTACT OF EMBANKMENT & ABUTMENT Some (should sod)

2. SEEPAGE AT JUNCTION OF EMBANKMENT & ABUTMENT None

3. EROSION FROM SURFACE DRAINAGE Not serious

4. WET SPOTS AT ABUTMENT None

5. SPRINGS - GULLIES - BOILS - etc.

6. REMARKS Generally in good condition

DOWNSTREAM SLOPE

1. CRACKS None

2. SLIDES OR SLOUGH'S None

3. SEEPAGE At drains only which is proper

DAUER
ENGINEERING,
INC.

Job No. _____ Date _____
Job Name _____
Client _____

DAM INSPECTION CHECK LIST (CONT'D)

4. BRUSH	None	
5. DAM OR WET BANDS*	None	
6. FILTER - FREE DRAINING?	Yes	IS WATER CLEAR? Yes
7. PIPE DRAIN - OBSTRUCTIONS?	None	VALVE No wrench to operate
8. SLOPE EROSION	Some - should repair and seed or cou	
9. REMARKS	In general looks good - slight erosion should be repaired. No need to worry about wet spots these will gradually diminish	
DOWNSTREAM FROM TOE		
1. BOILS	None	
2. EROSION GULLIES	None	
3. OTHER WET SPOTS	None noticed	
4. REMARKS	OK	
SPILLWAY		
1. COMPARE WITH PLANS:	OK	
2. DEER'S	None	
3. CRACKS	Slight 17/8" to 18" wide, not serious at this time, eventually filled	
4. HOLLOW CONCRETE	None	
5. SLIDE GATE	Locks - should adjust wedges	
6. EROSION AROUND WALLS, etc.	None	
7. REINFORCING STEEL EXPOSED	None	
8. OUTLET CHANNEL	OK	
9. REMARKS	Generally in excellent condition	

FACILITIES STUDY

**MARTIN, CLIFFORD & ASSOCIATES
STAFFORD, WILLIAMSBURG AND
CHARLOTTESVILLE, VIRGINIA**

SECTION IV

DAMS, SPILLWAYS AND LAKES

Situated within the confines of the Lake of the Woods development, are two lakes, one approximately 500 acres and the other 25 acres. The larger one is intended for water skiing, sailboating, swimming and other recreational purposes, whereas the smaller lake is mainly for fishing. The large lake was reviewed in two basic areas, lake portion and spillway and dam portion with the following appropriate comments:

Lake

One of the main concerns of the lake was the possibility of silt deposits. In order to evaluate this situation, fathometer readings were taken and recorded. See attached schedule and location map at the end of this section. Certain discrepancies were found between the readings taken and the topographical data that was made available. It is believed that this could be accountable to the fact that the topographical information was not "as-built", that is, up-dated after construction of the facility was completed.

The readings taken do not show an appreciable difference, or unexplainable difference between the topographical information and the soundings taken, but it must be borne in mind that the readings were taken on just one occasion, and as such, it is difficult to compare them with the information that was made available. Although a significant difference is not shown, these same readings should be taken on a periodic basis to insure that the build-up of silt is not occurring. It is interesting to note that of the twelve point samples taken, those in the finger areas where silting would seem to be occurring, such as in the vicinity of Tidewater Street, the difference between the topo and the soundings is negligible.

In certain areas of the shoreline, some of the lot owners have attempted to protect their banks by placing rip-rap. Normal water level being elevation 317.5, this rip-rap should be laid two feet above and below this level to assure sufficient coverage during anticipated variance. The sections covered in this manner noticeably prevented shortly, the effects of erosion of the property compared to the adjoining lots have none. The wave action from both the prevailing winds and the passage of speedboats will necessitate this or some other similar method be undertaken by all owners of waterfront lots. As the majority of this work could be done by a barge working from the lake, it would be an economic advantage to the owners to employ one contractor to do the entire undertaking.

Spillway and Dam

The major evaluation of this section was accomplished by reviewing the drawings prepared by the Bauer Engineering Company, and the files available at the office of the Attorney, Mr. Moore, in Orange County. The files included such items as design criteria and calculations; correspondence among the design engineer and the engineering firm employed to review their work, the developer and the contractor who performed the work; and daily time sheets of the inspector who was present during construction.

The files indicate that there were minor differences of opinion between the two engineering firms, but no significant differences concerning final plans on all major items. Our review of the plans indicate that all is according to sound engineering principals, and was executed in a professional manner. In calculation of a flood routing for a 100 year storm, the difference between their figure (320.0) and ours (319.5) was six inches. This is a relatively insignificant difference, and the discrepancies could be attributed to the method selected.

The crack in the spillway wall adjacent to the gate structure was inspected and it is reasonable to assume that it was caused by a temperature change. Over a period of time the entrance of water will cause freezing and thawing problems along with deterioration to the reinforcing steel. With this in mind, this crack will eventually have to be repaired.

The concrete walls of the spillway show practically no signs of wear. The spillway itself is spalling in some areas, but compared to the thickness of the concrete, it is of little consequence. Possibly after several years a thin coating of new concrete should be applied. This is frequently done with concrete structures and will restore the spillway to a new appearance after it has been exposed to the elements for many years.

The seeding of the bank of the dam was at one time somewhat of a problem to the maintenance people. With the advice and aid from the Soil Conservation Service, the crews are now conditioning the soil with lime and adding fertilization with noticeably good results. Assuming this plan is followed on a regular basis, adequate vegetation will remain on the banks.

On the down stream side of the dam there is a certain amount of moisture constantly present in two locations. One is located to the west of the outlet valve and the other is to the east of the bottom of the spillway. Although no soil borings were taken of the area, it was felt that both problems are attributable to the impermeability of the soil at these locations and not a fault of the dam. By providing drainage ditches or conduits the water can easily be directed to the water discharging from the outlet valve and the spillway.

On two separate occasions, samples were collected from the two lakes. The samples were taken directly to our water chemistry laboratory for analysis. The samples were preserved by refrigeration prior to testing.

APPENDIX VI

REPORT OF SOILS EXPLORATION

REPORT OF SOILS EXPLORATION

**PROPOSED DAM-LAKE OF THE WOODS RESERVOIR
ORANGE COUNTY, VIRGINIA**

FOR

BAUER ENGINEERING, INC.

5651-001-07



DAMES & MOORE
CONSULTANTS IN APPLIED EARTH SCIENCES
SOIL MECHANICS • ENGINEERING GEOLOGY • GEOPHYSICS

ATLANTA	NEW YORK
CHICAGO	PORTLAND
HONOLULU	SALT LAKE CITY
HOUSTON	SAN FRANCISCO
LOS ANGELES	SEATTLE
WASHINGTON, D.C.	MONTREAL, QUEBEC
MADRID, SPAIN	SAINT JOHN & S. LANADEA
TEHRAN, IRAN	

309 WEST JACKSON BOULEVARD • CHICAGO, ILLINOIS 60606 • 312-922-1772
PARTNERS: JAMES B. THOMPSON • GEORGE D. LEAL

October 21, 1966

Bauer Engineering, Inc.
20 North Wacker Drive
Chicago, Illinois 60606

Attention: Mr. William J. Bauer, President

Gentlemen:


Ten copies of our "Report of Soils Exploration, Proposed Dam-Lake of the Woods Reservoir, Orange County, Virginia" are herewith submitted.

The scope of our soils exploration was planned in collaboration with Messrs. William J. Bauer, Robert L. Hall, and D. R. Knouse of Bauer Engineering, Inc.

Preliminary data were provided to Messrs. Bauer, Hall and Knouse during the course of the investigation.

Yours very truly,

DAMES & MOORE


James B. Thompson

JBT:WJG:mf

VI-1

CABLE ADDRESS DAMEMORE

REPORT OF SOILS EXPLORATION
PROPOSED DAM-LAKE OF THE WOODS RESERVOIR
ORANGE COUNTY, VIRGINIA
FOR
BAUER ENGINEERING, INC.

INTRODUCTION

This report presents the results of our soils exploration performed at the site of the Proposed Dam-Lake of the Woods Reservoir to be constructed in Orange County, Virginia. The proposed dam will impound the water flowing in Flat Run Creek and the water derived from the upstream water shed area in the vicinity of the proposed dam. The proposed dam will be located approximately one-fifth of a mile upstream from where Flat Run Creek flows under Virginia State Highway 3. This is approximately 1 mile southeast of Flat Run, Virginia on Virginia State Highway 3.

The field explorations included the drilling of 18 test borings and the excavation of one test pit. The locations of the test borings and test pit are shown with respect to the proposed dam on Plate 1, Plot Plan.

SCOPE

The scope of our soils exploration were as follows:

- 1 - To explore the subsurface soil and water conditions at the dam site to the depths which will be influenced by the proposed construction.

2 - To determine the classification and pertinent physical characteristics including compaction and strength properties of representative materials encountered within the proposed borrow area.

GEOLOGY

The site of the Proposed Flat Run Creek Dam is located in an area known as the Piedmont Upland Province. This province is bordered on the west by the Appalachian Mountains and on the east by the Atlantic Coastal Plain. The typical landscape is a rolling surface of gentle slopes and no great relief. Average relief is approximately 50 to 100 feet.

The rock formations of the Piedmont Upland consist of gneisses, schists, slates and other metamorphic rocks, all of which have been deformed by mountain-making movements.

The soils of this area are basically residual with small areas of recent alluvial deposits around major streams. The residual soils are the products of weathering of the generally strong metamorphic rocks. The residual soil is quite thick in some localities and thus sound rock will usually be at considerable depths.

SURFACE CONDITIONS

The site of the proposed dam is located within a small broad valley which contains Flat Run Creek. The flow of Flat Run Creek is to the north. The maximum relief in the immediate area is approximately 85 feet. At the present time, the majority of the land around the proposed dam is wooded.

SUBSURFACE CONDITIONS

The subsurface conditions encountered at the site are as follows:

- 1 - Brown silty topsoil
- 2 - Reddish brown silty clay and clayey silt
- 3 - Mottled brown and gray sandy silt (decomposed rock)
- 4 - Highly weathered rock (gneiss)

All of the soils in the area investigated are basically residual in origin except for a few recent alluvial sand and gravel deposits along Flat Run Creek. The thickness of the topsoil varies throughout the site with greater depths being found on gentle slopes and flat areas. Underlying this topsoil is a reddish brown silty clay and clayey silt. The thickness of this soil is generally on the order of five feet. In the areas around Boring XIV and adjacent to Flat Run Creek this soil is absent. This absence is probably due to the erosional affect of Flat Run Creek. Underlying this stratum there is a layer of mottled brown and gray sandy silt (decomposed rock). The structure of the rock from which this residual soil has formed can still be seen in undisturbed samples obtained from this stratum. Below the mottled brown and gray sandy silt (decomposed rock) weathered gneiss is encountered. To assist you in visualizing the subsurface conditions encountered at the site of the proposed dam, graphical illustrations are presented on Plates 2A and 2B, Subsurface Sections.

--000--

The following Plates and Appendix are attached and complete this report:

Plate 1 - Plot Plan


Plate 2A - Subsurface Section A-A

Plate 2B - Subsurface Section B-B

Appendix - Explorations And Laboratory Tests

Respectfully submitted,

DAMES & MOORE



James B. Thompson

PLOT PLAN

卷之三


卷之三


14 AIR 1



SUBSURFACE SECTION A-A

0 100 200 300
FEET





AD-A073 631

BAKER (MICHAEL) JR INC BEAVER PA
NATIONAL DAM SAFETY PROGRAM. LAKE OF THE WOODS, INVENTORY NUMBER--ETC(U)
MAR 79 M BAKER

F/G 13/2

DACW65-78-D-0016

NL


UNCLASSIFIED

2 OF 3


AD
A073631

REF
LIBRARY





SUBSURFACE SECTION
VI-9



APPENDIX

EXPLORATIONS AND LABORATORY TESTS

EXPLORATIONS:

The subsurface conditions at the site of the proposed dam were investigated by drilling 18 test borings, which ranged in depth from approximately 11 to 56 feet below the existing ground surface, utilizing truck mounted rotary wash and rotary auger drilling equipment. One test pit was also excavated in the proposed borrow area of the proposed dam in order to visually inspect the subsurface soils to be used as borrow and to obtain a bulk sample for laboratory tests.

The drilling and test pit operations were supervised by one of our field engineers, who maintained a log of the borings and test pit and obtained undisturbed samples of soils and rock encountered in the borings. Graphical representation of the soils encountered in the borings and the test pit are shown on Plate A-1A through A-1F. The method utilized in classifying the soils is defined on Plate A-2, Unified Soil Classification System. Undisturbed samples of the soils penetrated by the borings were obtained in a soil sampler of the type illustrated on Plate A-3, Soil Sampler Type U. The rock was cored utilizing double tube core barrels and diamond bits. The boring locations were obtained in the field by representatives from the Prince William Engineering Co. The elevations of the borings were obtained from a topographic map of the area provided by Bauer Engineering, Inc. The ground surface elevation is presented above the log of each boring and these elevations refer to the U.S.G.S. Datum. Water levels recorded in the borings during our field investigation are presented on the Log of Borings.

LABORATORY TESTS:

Laboratory tests were performed on bulk samples of proposed borrow soil excavated from the test pit. The laboratory tests consisted of identification tests, compaction tests and strength tests.

Identification Tests - The Atterberg Limits and particle size distribution of the bulk samples of soil were determined to assist in the identification of the soil.

Atterberg Limits - The Atterberg Limits, consisting of the liquid limit, plastic limit, and plasticity index, were determined to facilitate the classification of the soil according to the Unified Soil Classification System. The method of performing the Atterberg Limits may be found in most standard Soil Mechanics texts. Briefly, the liquid limit of a soil is that moisture content at which the soil is practically liquid but presumably possesses the smallest shearing strength which may be measured by a standardized procedure. The plastic limit of a soil is the lowest moisture content of which a soil is plastic. The plasticity index is a measure of the plastic properties of soils and is defined as the range in moisture content between the plastic and liquid limits.

The Atterberg Limits are tabulated below:

ATTERBERG LIMITS

<u>TEST PIT AND DEPTH IN FEET</u>	<u>LIQUID LIMIT PERCENT*</u>	<u>PLASTIC LIMIT PERCENT*</u>	<u>PLASTICITY INDEX</u>	<u>UNIFIED SOIL CLASSIFICATION</u>
TP-1 @ 2½ to 3½	39	24	15	ML-CL

* Moisture content expressed as percent of the dry weight.

Particle Size Distribution - Determination of the particle size distribution of the proposed borrow soil obtained from the test pit was made to facilitate the classification of the soil and to aid in the design of the proposed dam. The particle size distribution curves are shown on Plate A-6.

Compaction Tests - A compaction test was performed on the bulk sample of proposed borrow soil to determine the relationship between moisture content and dry density under controlled conditions and to establish criteria for the placement and compaction of the soil in the construction of the proposed dam. The compaction test was performed in accordance with the AASHO* Compaction Test Designation T 180-57 which is described on Plate A-4, Method of Performing Compaction Tests. The results of the compaction test are presented on Plate A-7, Compaction Test Data.

Strength Tests - Direct shear tests were performed on compacted samples of the proposed borrow soil obtained from the test pit in the manner described on Plate A-5, Method of Performing Direct Shear and Friction Tests. Stress-strain curves were plotted for each strength test.

Six samples were compacted a little on the dry side of optimum moisture content to 90 percent maximum dry density and six samples were compacted a little on the dry side of optimum moisture content to 95 percent of maximum dry density. Direct shear tests were then performed, under different normal pressures, on half of the samples compacted to 90 percent of maximum dry density and half of the samples compacted to 95 percent of maximum dry density. The remaining samples were submerged under water and various surcharge pressures for five days prior to direct shear testing. Direct shear

* American Association of State Highway Officials

tests were also run on other samples that were compacted wet of optimum to 84 and 88 percent of maximum dry density. The results of these tests are plotted on Plate A-8, Direct Shear Test Results on Compacted Samples.

--000--

The following Plates are attached and complete this Appendix:

Plate A-1A - Log of Borings (Borings I, II, III and IV)

Plate A-1B - Log of Borings (Borings V, VI, and VII)

Plate A-1C - Log of Borings (Borings VIII and IX)

Plate A-1D - Log of Borings (Borings X, XI and XII)

Plate A-1E - Log of Borings (Borings XIII, XIV, XV and XVI)

Plate A-1F - Log of Borings and Test Pit (Borings XVII and XVIII and Test Pit 1)

Plate A-2 - Unified Soil Classification System

Plate A-3 - Soil Sampler Type U


Plate A-4 - Method of Performing Compaction Tests

Plate A-5 - Method of Performing Direct Shear and Friction Tests

Plate A-6 - Particle Size Distribution

Plate A-7 - Compaction Test Data

Plate A-8 - Direct Shear Test Results on Compacted Samples






LOG OF BORINGS

NOTES:
ELEVATIONS REFER TO U.S.G.S. DATUM.



I INDICATES DEPTH, LENGTH AND PERCENT
OF CORE RUN RECOVERED.
FIGURES UNDER THE BLOW COUNT COLUMN
INDICATE THE NUMBER OF BLOWS REQUIRED
TO DRIVE A DAVIES & MOORE SAMPLER
ONE-FOOT WITH A 300 LB. WEIGHT FALLING
18 INCHES.

DATE PLATE

RECEIVED BY DATE FILED
CHURCHILL COUNTY




LOG OF BORINGS






LOG OF BORINGS

BY _____ DATE _____
BY _____ DATE _____
PLATE _____
CHECKED BY _____ DATE _____




LOG OF BORINGS





LOG OF BORINGS



LOG OF TEST PIT

VI-19

DAMES & MOORE


PLATE A-1F

UNIFIED SOIL CLASSIFICATION SYSTEM

SOIL CLASSIFICATION CHART


NOTE: DUAL SYMBOLS ARE USED TO INDICATE BORONICINE SOIL CLASSIFICATIONS.

Coarse Grained Soils	CLAY GRAVELS (little or no fines)	No Fines
		POORLY-GRADED GRAVEL-SAND MIXTURES, LITTLE OR NO FINES GP
	GRAVELS WITH FINES (appreciable amount of fines)	SILTY GRAVELS, GRAVEL-SAND-SILT MIXTURES GM
	CLEAN SAND (little or no fines)	CLAYEY GRAVELS, GRAVEL-SAND-SILT MIXTURES GC
	more than 50% of material is coarse than No. 200 sieve size	WELL-GRADED SANDS, GRAVELLY SANDS, LITTLE OR NO FINES SW
	more than 50% of material is coarse than No. 4 sieve	POORLY-GRADED SANDS, GRAVELLY SANDS, LITTLE OR NO FINES SP
		SILTY SANDS, SAND-SILT MIXTURES SM
		CLAYEY SANDS, SAND-CLAY MIXTURES SC
		INORGANIC SILTS AND VARYING FINE SANDS, ROCK FLOUR, SILTY OR CLAYEY FINE SANDS OR CLAYEY SILTS WITH SLIGHT PLASTICITY ML
		INORGANIC CLAYS OF LOW TO MEDIUM PLASTICITY, GRAVELLY CLAYS, SANDY CLAYS, SILTY CLAYS, LEAN CLAYS CL
		ORGANIC SILTS AND ORGANIC SILTY CLAYS OF LOW PLASTICITY OL
	Liquid Limit less than 30	INORGANIC SILTS, MICAEOUS OR DIATOMACEOUS FINE SAND OR SILTY SOILS MH
		INORGANIC CLAYS OF HIGH PLASTICITY, FINE CLAYS CH
		ORGANIC CLAYS OF MEDIUM TO HIGH PLASTICITY, ORGANIC SILTS OH
		PEAT, HUMUS, SWAMP SOILS WITH HIGH ORGANIC CONTENTS PT
		HIGHLY ORGANIC SOILS




PLASTICITY CHART

REVISIONS
BY _____ DATE _____ TO GO _____
BY _____ FILE _____
BY _____ DATE _____ TO GO _____
BY _____ DATE _____ TO GO _____



SOIL SAMPLER TYPE U
FOR SOILS DIFFICULT TO RETAIN IN SAMPLER
U. S. PATENT NO. 2,318,062

ALTERNATE ATTACHMENTS




METHOD OF PERFORMING COMPACTION TESTS
(STANDARD AND MODIFIED A.A.S.H.O. METHODS)

IT HAS BEEN ESTABLISHED THAT WHEN COMPACTING EFFORT IS HELD CONSTANT, THE DENSITY OF A ROLLED EARTH FILL INCREASES WITH ADDED MOISTURE UNTIL A MAXIMUM DRY DENSITY IS OBTAINED AT A MOISTURE CONTENT TERMED THE "OPTIMUM MOISTURE CONTENT," AFTER WHICH THE DRY DENSITY DECREASES. THE COMPACTION CURVE SHOWING THE RELATIONSHIP BETWEEN DENSITY AND MOISTURE CONTENT FOR A SPECIFIC COMPACTING EFFORT IS DETERMINED BY EXPERIMENTAL METHODS. TWO COMMONLY USED METHODS ARE DESCRIBED IN THE FOLLOWING PARAGRAPHS.

FOR THE "STANDARD A.A.S.H.O." (A.S.T.M. D698-58T & A.A.S.H.O. T99-57) METHOD OF COMPACTION A PORTION OF THE SOIL SAMPLE PASSING THE NO. 4 SIEVE IS COMPACTED AT A SPECIFIC MOISTURE CONTENT IN THREE EQUAL LAYERS IN A STANDARD COMPACTION CYLINDER HAVING A VOLUME OF 1/30 CUBIC FOOT, USING TWENTY-FIVE 12-INCH BLOWS OF A STANDARD 5-1/2 POUND RAMMER TO COMPACT EACH LAYER.

IN THE "MODIFIED A.A.S.H.O." (A.S.T.M. D-1557-58T & A.A.S.H.O. T 180-57) METHOD OF COMPACTION A PORTION OF THE SOIL SAMPLE PASSING THE NO. 4 SIEVE IS COMPACTED AT A SPECIFIC MOISTURE CONTENT IN FIVE EQUAL LAYERS IN A STANDARD COMPACTION CYLINDER HAVING A VOLUME OF 1/30 CUBIC FOOT, USING TWENTY-FIVE 18-INCH BLOWS OF A 10-POUND RAMMER TO COMPACT EACH LAYER. SEVERAL VARIATIONS OF THESE COMPACTION TESTING METHODS ARE OFTEN USED AND THESE ARE DESCRIBED IN A.A.S.H.O. & A.S.T.M. SPECIFICATIONS.

FOR BOTH METHODS, THE WET DENSITY OF THE COMPACTED SAMPLE IS DETERMINED BY WEIGHING THE KNOWN VOLUME OF SOIL; THE MOISTURE CONTENT, BY MEASURING THE LOSS OF WEIGHT OF A PORTION OF THE SAMPLE WHEN OVEN DRIED; AND THE DRY DENSITY, BY COMPUTING IT FROM THE WET DENSITY AND MOISTURE CONTENT. A SERIES OF SUCH COMPACTIONS IS PERFORMED AT INCREASING MOISTURE CONTENTS UNTIL A SUFFICIENT NUMBER OF POINTS DEFINING THE MOISTURE-DENSITY RELATIONSHIP HAVE BEEN OBTAINED TO PERMIT THE PLOTTING OF THE COMPACTION CURVE. THE MAXIMUM DRY DENSITY AND OPTIMUM MOISTURE CONTENT FOR THE PARTICULAR COMPACTING EFFORT ARE DETERMINED FROM THE COMPACTION CURVE.



SOME APPARATUS FOR PERFORMING COMPACTION TESTS
Shows, from left to right, 5-1/2 pound rammer (sleeve controlling 12" height of drop removed), 1/30 cubic-foot cylinder with removable collar and base plate, and 10 pound rammer within sleeve.

REVISIONS
BY _____ DATE _____

FILE _____

DATE _____
CHECKED BY _____

METHOD OF PERFORMING DIRECT SHEAR AND FRICTION TESTS

DIRECT SHEAR TESTS ARE PERFORMED TO DETERMINE THE SHEARING STRENGTHS OF SOILS. FRICTION TESTS ARE PERFORMED TO DETERMINE THE FRICTIONAL RESISTANCES BETWEEN SOILS AND VARIOUS OTHER MATERIALS SUCH AS WOOD, STEEL, OR CONCRETE. THE TESTS ARE PERFORMED IN THE LABORATORY TO SIMULATE ANTICIPATED FIELD CONDITIONS.

EACH SAMPLE IS TESTED WITHIN THREE BRASS RINGS, TWO AND ONE-HALF INCHES IN DIAMETER AND ONE INCH IN LENGTH. UNDISTURBED SAMPLES OF IN-PLACE SOILS ARE TESTED IN RINGS TAKEN FROM THE SAMPLING DEVICE IN WHICH THE SAMPLES WERE OBTAINED. LOOSE SAMPLES OF SOILS TO BE USED IN CONSTRUCTING EARTH FILLS ARE COMPACTED IN RINGS TO PREDETERMINED CONDITIONS AND TESTED.



DIRECT SHEAR TESTING
& RECORDING APPARATUS

DIRECT SHEAR TESTS

A THREE-INCH LENGTH OF THE SAMPLE IS TESTED IN DIRECT DOUBLE SHEAR. A CONSTANT PRESSURE, APPROPRIATE TO THE CONDITIONS OF THE PROBLEM FOR WHICH THE TEST IS BEING PERFORMED, IS APPLIED NORMAL TO THE ENDS OF THE SAMPLE THROUGH POROUS STONES. A SHEARING FAILURE OF THE SAMPLE IS CAUSED BY MOVING THE CENTER RING IN A DIRECTION PERPENDICULAR TO THE AXIS OF THE SAMPLE. TRANSVERSE MOVEMENT OF THE OUTER RINGS IS PREVENTED.


THE SHEARING FAILURE MAY BE ACCOMPLISHED BY APPLYING TO THE CENTER RING EITHER A CONSTANT RATE OF LOAD, A CONSTANT RATE OF DEFLECTION, OR INCREMENTS OF LOAD OR DEFLECTION. IN EACH CASE, THE SHEARING LOAD AND THE DEFLECTIONS IN BOTH THE AXIAL AND TRANSVERSE DIRECTIONS ARE RECORDED AND PLOTTED. THE SHEARING STRENGTH OF THE SOIL IS DETERMINED FROM THE RESULTING LOAD-DEFLECTION CURVES.

FRICTION TESTS

IN ORDER TO DETERMINE THE FRICTIONAL RESISTANCE BETWEEN SOIL AND THE SURFACES OF VARIOUS MATERIALS, THE CENTER RING OF SOIL IN THE DIRECT SHEAR TEST IS REPLACED BY A DISK OF THE MATERIAL TO BE TESTED. THE TEST IS THEN PERFORMED IN THE SAME MANNER AS THE DIRECT SHEAR TEST BY FORCING THE DISK OF MATERIAL FROM THE SOIL SURFACES.

GRADATION CURVE

LOCATION	DEPTH	CLASSIFICATION			NAT.WC	LL	PL	PI
		COBBLES	GRAVEL	SAND				
TEST PIT 1	2.5' TO 3.5'	CL-ML	SILTY CLAY WITH SAND		39	24	15	




VI-24


DAMES & MOORE

PLATE A-6

SAMPLE NO. 1 DEPTH. 2.5' ELEVATION 269.5
SOIL REDDISH-BROWN SILTY CLAY WITH TRACE OF SAND
LOCATION TEST PIT 1
OPTIMUM MOISTURE CONTENT 13.0 %
MAXIMUM DRY DENSITY 116 LBS./CU. FT.
METHOD OF COMPACTION A.A.S.H.O. T180-57(METHOD A)



COMPACTION TEST DATA



DIRECT SHEAR TEST RESULTS ON COMPACTED SAMPLES

VI-26

JAMES G. MOORE
APPLIED EARTH SCIENCES

PLATE A-8

**REPORT - RESULTS OF THE FIELD EXPLORATIONS AND
LABORATORY TESTING**

**PROPOSED DAM - LAKE OF THE WOODS RESERVOIR
ORANGE COUNTY, VIRGINIA**

FOR

BAUER ENGINEERING, INC.

5651-003-07



DAMES & MOORE
CONSULTANTS IN APPLIED EARTH SCIENCES
SOIL MECHANICS • ENGINEERING GEOLOGY • GEOPHYSICS

- ATLANTA NEW YORK
CHICAGO PORTLAND
HONOLULU SALT LAKE CITY
HOUSTON SAN FRANCISCO
LOS ANGELES SEATTLE
WASHINGTON, D.C.
MADRID, SPAIN SAINT JOHN, N.B., CANADA
TEHRAN, IRAN

309 WEST JACKSON BOULEVARD • CHICAGO, ILLINOIS 60606 • 312-922-1772

PARTNERS: JAMES B. THOMPSON • GEORGE D. LEAL

ASSOCIATE: WILLIAM G. PARATORE

June 7, 1967

Bauer Engineering, Inc.
20 North Wacker Drive
Chicago, Illinois 60606

Attention: Mr. William J. Bauer, President

Gentlemen:

Report-Results of the Field Explorations and
Laboratory Testing
Proposed Dam - Lake of the Woods Reservoir
Orange County, Virginia
For Bauer Engineering, Inc.

INTRODUCTION AND SCOPE

This report presents the results of our field explorations and laboratory testing performed in connection with the Proposed Dam - Lake of the Woods Reservoir which is being constructed in Orange County, Virginia.

The scope of our field explorations and laboratory testing was planned in collaboration with Messrs. Robert L. Hall and Donald Wikan of Bauer Engineering, Inc., Messrs. Gay D. Jones and Jack W. Burke of Howard, Needles, Tammen & Bergendoff, and Messrs. John S. Keating and Robert L. Boone of United States Land, Inc. at a meeting held on May 10, 1967.

Bauer Engineering, Inc.
June 7, 1967
Page - 2

The scope of our services included:

- 1 - The supervision of the drilling and sampling of three exploration test borings drilled at approximately Station 7 + 25 within the partially constructed dam embankment. These operations were performed to obtain representative undisturbed samples of the embankment soils for laboratory testing.
- 2 - The performance of laboratory tests on the embankment soils and the presentation of the original laboratory test data to Bauer Engineering, Inc.

FIELD EXPLORATIONS

The subsurface soil conditions of the partially constructed dam embankment were explored by drilling three test borings with truck mounted, auger type caisson drilling equipment. The borings were 12 inches in diameter and penetrated through the embankment fill and into the underlying natural soils. Undisturbed soil samples were obtained from the test borings by hydraulically pushing a Dames & Moore Soil Sampler having a thin-wall bit extension. Two test pits were also excavated utilizing backhoe equipment. One test pit was excavated adjacent to Boring 1 and the other adjacent to Boring 3. Shelby tubes were hydraulically pushed into the sides of the test pits to obtain undisturbed samples of soil for horizontal permeability determinations.

The drilling and backhoe operations were supervised by one of our field engineers who maintained a log of the soils encountered. The location of the borings and test pits, and graphical representations of the soils penetrated by the borings are shown on Plate 1. The method utilized in classifying the soils is defined on Plate 2. The boring locations and elevations were provided to us by representatives of Bauer Engineering, Inc.

Bauer Engineering, Inc.
June 7, 1967
Page - 3

LABORATORY TESTS

Laboratory tests were performed on the soil samples obtained from the test borings and pits to obtain certain physical properties of the in-situ earth embankment. The following tests were performed:

1 - Triaxial Compression Tests

a - Consolidated - Undrained (Saturated)

b - Unconsolidated - Undrained (Field Moisture Content)

2 - Consolidation Tests (To determine horizontal and vertical permeabilities)

3 - Moisture-Density Tests

4 - Compaction Tests (AASHO T 180-57)

5 - Atterberg Limits and Grain Size Analyses

The above tests were performed utilizing conventional soil testing procedures. Copies of the original laboratory test data are presented in Attachments A through G.

It has been a pleasure to work with you on this project. Should you need any assistance in the interpretation of the laboratory test data, please do not hesitate to contact us.

--000--

Bauer Engineering, Inc.
June 7, 1967
Page - 4

The following Plates and Attachments are enclosed and complete this report:

Plate 1 - Plot Plan and Log of Borings

Plate 2 - Unified Soil Classification System

Attachment A - Triaxial Compression Tests
Consolidated - Undrained, Saturated

Attachment B - Triaxial Compression Tests
Unconsolidated - Undrained,
Field Moisture Content

Attachment C - Consolidation Tests For Vertical
Permeabilities

Attachment D - Consolidation Tests For Horizontal
Permeabilities

Attachment E - Supplementary Moisture-Density Tests

Attachment F - Compaction Test Data (AASHO T 180-57)

Attachment G - Atterberg Limits and Grain Size Analyses

Respectfully submitted,

DAMES & MOORE

William D. Paratore

William G. Paratore

WGP:MLK:mf

Four Copies Submitted



E OF DAM

STATION 8+00 ————— STATION 8+00

BORING 1 BORING 2 BORING 3
STATION 7+00 TEST PIT 1 TEST PIT 2 STATION 7+00


STATION 6+00 ————— STATION 6+00

PLOT PLAN




BORING 1

SURFACE ELEVATION 273.2



BORING 2

SURFACE ELEVATION 273.8



BORING 3

SURFACE ELEVATION 265.9

UPSTREAM

DEPTH IN FEET

LOG OF BORINGS

NOTES:

ELEVATIONS REFER TO U.S.G.S. DATUM.

ALL SOILS WERE CLASSIFIED IN ACCORDANCE
WITH THE UNIFIED SOIL CLASSIFICATION SYSTEM.

ALL SAMPLES WERE OBTAINED BY PUSHING HYDRAULICALLY
A DAMES & MOORE SOIL SAMPLER TYPE U WITH A THIN-WALLED
SAMPLING TUBE.


UNIFIED SOIL CLASSIFICATION SYSTEM

SOIL CLASSIFICATION CHART

NOTE: DUAL SYMBOLS ARE USED TO INDICATE BORDERLINE SOIL CLASSIFICATIONS.

GRAVEL AND GRAVELLY SOILS	GW	ALL-ROUND GRAVELLY, GRAVEL- SAND MIXTURES, LITTLE OR NO FINES
	GP	POLYGRADED GRAVELLY-GRAVEL- SAND MIXTURES, LITTLE OR NO FINES
SAND AND SANDY SOILS	GM	SILTY GRAVELS, GRAVEL-SAND- SILT MIXTURES
	GC	CLAY GRAVELS, GRAVEL-GRAN- CLAY MIXTURES
MORE THAN 50% OF COARSE FRAC- TION EXCEEDING NO. 4 SIEVE	SW	WELL-GRADED SANDS, GRAVELLY SANDS, LITTLE OR NO FINES
	SP	POORLY-GRADED SANDS, GRAVELLY SANDS, LITTLE OR NO FINES
MORE THAN 50% OF COARSE FRAC- TION EXCEEDING NO. 4 SIEVE	SM	SILTY SANDS, SAND-SILT MIXTURES
	SC	CLAYEY SANDS, SAND-CLAY MIXTURES
SILTS AND CLAYS	ML	INORGANIC SILTS AND VERY FINE SANDS, ROCK FLOUR, SILTY OR CLAYEY, FINE CLAYS, OR CLAYEY SILTS WITH SLIGHT PLASTICITY
LIMIT LESS THAN 50	CL	INORGANIC CLAYS OF LOW TO MEDIUM PLASTICITY, GRAVELLY CLAYEY, SAND CLAYS, SILTY CLAYS, LEAN CLAYS
SILTS AND CLAYS	OL	ORGANIC SILTS AND ORGANIC SILTY CLAYS OF LOW PLASTICITY
LIMIT LESS THAN 50	MH	INORGANIC SILTS, MICACEOUS OR DIATOMACEOUS, FINE SAND OR SILTY SOILS
SILTS AND CLAYS	CH	INORGANIC CLAYS OR HIGH PLASTICITY, FAT CLAYS
LIMIT LESS THAN 50	OH	ORGANIC CLAYS OF MEDIUM TO HIGH PLASTICITY, ORGANIC SILTS
GLEY ORGANIC SOILS	PT	PEAT, HUMUS, SWAMP SOILS WITH HIGH ORGANIC CONTENTS

PLASTICITY CHART



KEY TO TEST DATA

- INDICATES DEPTH OR UNDISTURBED SAMPLE
- INDICATES DEPTH OR DISTURBED SAMPLE
- INDICATES DEPTH OR SAMPLE AFTER WASHING
- △ INDICATES DEPTH OR SPILL-DRIVEN SAMPLE
- I INDICATES DEPTH AND LENGTH OF CORING ROD

ROCK COMPRESSION TESTS

TEST MATERIAL POSITION IN SOILS PER SOIL TEST (FROM MOST CIRCLE)
TEST MATERIAL POSITION EXPRESSED AS A PERCENTAGE OF THE ONE TESTED PER
TEST MATERIAL TESTED FROM WHICH CIRCLE TEST

TEST MATERIAL TESTED

ATTACHMENT A

TRIAXIAL COMPRESSION TESTS

CONSOLIDATED - UNDRAINED

SATURATED


JOB : 5651-003-07

OWNER Dowagiac Gas Co LOCATION Oceana County
 SOIL TYPE Rust Brown & yellow sandy, clayey silt, trace DEPTH 3.0
of decomposed shale (ML-Fill) SAMPLE # 23

SAMPLER X-P-12/67 SET-UP 5/19/67 TESTED 5/21/67 (SE OFFICE)

SATURATED TEST X	BEFORE	FIELD MOISTURE TEST □	TEST LATERAL PRESSURE 2250 PSF
TYPE OF TEST T/CU	AFTER	SOFTER & CLAYEYER 20%	SR = 0.005" / min
Weight soil & dish no.	<u>368</u>	<u>219.2</u>	Net diameter <u>D_o 2.42</u> in.
Dry weight soil & dish	<u>712</u>	<u>175.3</u>	Area <u>(0.785 D_o²)</u> <u>A_o 4.60</u> sq.in.
Net loss of moisture	<u>156</u>	<u>42.9</u>	Height <u>H_o 5.5</u> in.
Weight of dish only			Volume <u>(A_o H_o) + 1728</u> <u>V_o</u> cu.ft.
Net weight of dry soil			Volume <u>(A_o H_o) × 16.4</u> <u>V_o 437</u> cc
Moisture, % of dry weight	<u>21.9</u>	<u>24.5</u>	Specific gravity of solids <u>G_s</u>
Wt. solids + moisture	<u>W_o 268 gms. 326</u>		Volume of solids <u>W_s + G_s</u> <u>V_s</u> cc
W _o + 454	<u>W'</u>		(V _o - V _s) + V _s <u>V_i</u> cc
Weight solids	<u>W_s</u>		Initial burette reading <u>cc</u>
Wet density W' + V'	<u>124 pcf</u>	<u>127</u>	Burette reading under pressure <u>cc</u>
Dry density	<u>102 pcf</u>	<u>102</u>	(V _p - V _s) + V _s <u>V_p</u> cc

$$\frac{1}{d} d_{c,s,l} = \frac{1}{d} \frac{V_o}{V_c} = 102 \frac{437}{403} = 110 \text{ pcf}$$



BORING: 1 SAMPLE NO.: 2B DEPTH (FT): 3.0 TYPE OF TEST: ~~xx~~

SATURATION DATA								CONSOLIDATION DATA	
TIME DATE	CHAMBER (PSI)	BACK PRESS (PSI)	EXTERNAL BURETTE (CC)	SATURATION BURETTE (CC)	PORE PRESSURE (PSI)	Δ	B	ELAPSED TIME MIN.	INTERIOR VOL. BURETTE (CC)
2/19/57									
1730	25.0	22.0	-	-	22.0	-	-		
1930	30.0	C. 25.0	-	-	22.0/24.1	2.1	.52		
1920	40.0	37.0	-	-	37.0	-	-		
2/20/57									
1300	45.0	C. 37.0	-	-	37.0/41.2	4.2	.81		
1320	40.0	37.0	-	-	37.0	-	-		
1600	45.0	C. 37.0	-	-	37.0/41.2	4.2	.81		
Consolidation									
1530	2250 = 13.6 psi	0	-	-	-	-	-	0	109.0
(.1	111.6
)								.25	112.5
								.5	113.1
1531								1	115.0
1532								2	116.7
1534								3	119.1
1539								8.9	123.0
1546								1.6	125.2
1600								30	129.7
1630								60	133.6
1730								120	135.4
1930								240	133.6
2330								480	-
2/21 1530								1440	143.0

SAMPLE HEIGHT, AREA, AND VOLUME CORRECTIONS AFTER CONSOLIDATION

ORIGINAL SAMPLE HEIGHT (H_0)..... 5.300 IN.

INITIAL DIAL: 0.000 FINAL DIAL: 0.126, CHANGE IN HEIGHT (ΔH):.. 0.126 IN.

SAMPLE HEIGHT AFTER CONSOLIDATION (H_c) 5.671 IN.

PERCENTS DEFLECTION.(E).....2.28

ORIGINAL SAMPLE VOLUME (v_0)..... 437 CC.

INITIAL BURETTE: 109.0 FINAL BURETTE: 143.0, CHANGE IN VOLUME (ΔV)... -34 CC.

ORIGINAL SAMPLE AREA (A) 11 cm²

ORIGINAL SAMPLE AREA (A_0)..... 4.60 IN².
AREA CORRECTION:

$$\begin{aligned}
 A_e &= A_o \left(1 - \frac{\Delta V}{V_0} \right) \\
 &= \frac{4.60 \left(1 - \frac{34}{437} \right)}{1 - 0.022} \\
 &= \frac{4.60 (0.922)}{0.978} \\
 &= 4.54 \quad \text{SQ. IN.}
 \end{aligned}$$

TRIAXIAL COMPRESSION TEST DATA SHEET

JOB # 5651-003-07

OWNER BAYER SUGAR CO. LOCATION OCEAN COUNTY BORING # 1 *
 SOIL TYPE Red & Brown Clayey Sandy Silt with some gravel DEPTH 60'
gravel SAMPLE # 3A

SAMPLED JUL 6/12/67 SET-UP 5/19/67 TESTED 5/23/67 (SF OFFICE)

SATURATED TEST BEFORE FIELD MOISTURE TEST TEST LATERAL PRESSURE 3000 PSF

TYPE OF TEST IX/CM 236

Weight soil & dish no. 842 289.6

Dry weight soil & dish 697 234.4

Net loss of moisture 145 55.2

Weight of dish only

Net weight of dry soil

Moisture, % of dry weight 20.8 23.5

Wt. solids + moisture W_o 842 gms. 862

W_o + 454 lbs.

Weight solids W_s gms.

Wet density W_o + V' 125 pcf 128

Dry density 104 pcf 104



GEOMETRY

Net diameter D_o 2.42 in.

Area ($0.785 D_o^2$) A_o 4.60 sq.in.

Height H_o 5.6 in.

Volume ($A_o H_o$) V_o 26.8 cu.ft.

Volume ($A_o H_o$) V_o 436 cc

Specific gravity of solids G_s

Volume of solids $W_s + G_s$ V_s cc


$(V_o - V_s) + V_s$ V_i cc

Initial burette reading cc

Burette reading under pressure cc

$(V_p - V_s) + V_s$ V_p cc

Rep. to Fig. 2 #33 at 7.0'.



BORING: 7 SAMPLE NO.: 33 DEPTH (FT): 7-5 TYPE OF TEST: Tx/cu

SATURATION DATA								CONSOLIDATION DATA	
TIME DATE	CHAMBER (PSI)	BACK PRESS (PSI)	EXTERNAL BURETTE (CC)	SATURATION BURETTE (CC)	PORE PRESSURE (PSI)	△	B	ELAPSED TIME MIN.	INTERIOR VOL. BURETTE (CC)
5/21/61	3	0	-	-	-	-	-		
5/21/61									
11:00	30	27	-	-	27.0	-	-		
11:00	25	25	-	-	27.0 / 31.0	4.0	.80		
11:20	30	27	-	-	27.0	-	-		
5/22/61									
11:00	35	25	-	-	27.0 / 31.0	4.5	.90		
11:30	35	0	-	-	-	-	-	0	136.0
11:31								.1	137.5
11:32								.25	139.2
11:34								.5	139.9
11:39								1	140.5
11:40								2	141.2
11:45								4	142.5
11:50								8.5	145.0
11:55								16	147.5
12:00								30	148.5
12:05								60	151.0
12:10								120	154.2
12:15								240	157.0
12:30								480	161.2
12:45								1440	162.5

SAMPLE HEIGHT, AREA, AND VOLUME CORRECTIONS AFTER CONSOLIDATION

ORIGINAL SAMPLE HEIGHT (H_0)..... 5.600 IN.

INITIAL DIAL: 0.090 FINAL DIAL: 0.075, CHANGE IN HEIGHT (ΔH): .075 IN.

SAMPLE HEIGHT AFTER CONSOLIDATION (H_c)..... 5.525 IN.

PERCENTS DEFLECTION. (E)..... %

ORIGINAL SAMPLE VOLUME (V_0)..... 430.0 CC.

INITIAL BURETTE: 136.0 FINAL BURETTE: 162.5, CHANGE IN VOLUME (ΔV)... 26.5 CC.

SAMPLE VOLUME AFTER CONSOLIDATION (V_c)..... 403.5 CC.

ORIGINAL SAMPLE AREA (A_0)..... 4.60 IN².

AREA CORRECTION:

$$A_c = A_0 (1 - \Delta V / V_0 / 1 - E)$$

= SQ. IN.

SATURATION & CONSOLIDATION PHASE

VI-37 TRIAXIAL COMPRESSION TEST


JOB # 6551-003-07

OWNER Bauer Eng Co LOCATION Orange County BORING # 2
 SOIL TYPE Red brown very clayey sandy silt with DEPTH 1.5'
Siliceous gravel (M.L. - FILL) SAMPLE # 13

SAMPLED 5/12/67 SET-UP 5/21/67 TESTED 5/23/67 (IN OFFICE)

SATURATED TEST FIELD MOISTURE TEST TEST LATERAL PRESSURE 4500 PSF

TYPE OF TEST	T/CU	RECORD	ZEROS	SOFT EINE	
Weight soil & dish no.	361	316.2		D _o	2.42 in.
Dry weight soil & dish	68T	247.7		A _o	1.60 sq.in.
Net loss of moisture	174	68.5		H _o	6.0 in.
Weight of dish only				V _o	cu.ft.
Net weight of dry soil				V _o	453 cc
Moisture, % of dry weight	25.4	27.7		G _s	
Wt. solids + moisture			876	V _s	cc
W _o + 454				(V _o - V _s) + V _s	
Weight solids				e _i	
Wet density W _o ' + V _o '		119 pcf	122	Initial burette reading	cc
Dry density		95.4 pcf	95.4	Burette reading under pressure	cc
				(V _p - V _s) + V _s	e _p



SATURATION DATA								CONSOLIDATION DATA	
TIME DATE	CHAMBER (PSI)	PACK PRESS (PSI)	EXTERNAL BURETTE (CC)	SATURATION BURETTE (CC)	PORE PRESSURE (PSI)	△	B	ELAPSED TIME MIN.	INTERIOR VOL. BURETTE (CC)
5/21/67	5.0	0	5.0	5.0	-	-	-		
5/22 11:00	35.0	30	10	-	30.0	-	-		
12:30	40.0	40.0	-	-	30.0/34.1	4.1	.82		
13:30	35.0	30	-	-	30.0	-	-		
15:00	40.0	40.0	-	-	30.0/34.1	4.8	.91		
16:00	35.0	30	-	-	30.0	-	-		
17:00	20.0	20.0	-	-	30.0/34.8	4.8	.91		
- Consolidation -									
17:30	0	0	-	-	-	70.0	70.0		
			-	-	-	72.0	45.0	0	0
			-	-	-	71.8	45.0	.1	
			-	-	-	71.2	41.1	.25	
			-	-	-	70.9	41.1	.5	
17:31			-	-	-	70.8	41.0	1	
17:32			-	-	-	68.7	62.2	2	
17:34			-	-	-	67.2	63.2	3	
17:47			-	-	-	65.8	42.6	812	
17:48			-	-	-	64.8	79.7	16	
18:00			-	-	-	63.6	36.4	30	
18:23			-	-	-	62.7	34.6	60	
18:33			-	-	-	62.3	33.2	120	
19:30			-	-	-	62.0	31.8	240	
-			-	-	-	-	2.2	480	
5/23 17:00			-	-	-	61.8	52.8	1440	

SAMPLE HEIGHT, AREA, AND VOLUME CORRECTIONS AFTER CONSOLIDATION

ORIGINAL SAMPLE HEIGHT (H_0)..... 6.000 IN.
 INITIAL DIAL: 0.600 FINAL DIAL: 0.654, CHANGE IN HEIGHT (ΔH): 0.054 IN.
 SAMPLE HEIGHT AFTER CONSOLIDATION (H_c)..... 5.946 IN.
 PERCENTS DEFLECTION. (E)..... %

ORIGINAL SAMPLE VOLUME (V_0)..... 453.0 CC.
 INITIAL BURETTE: 11.0 FINAL BURETTE: 9.3, CHANGE IN VOLUME (ΔV)... 24.7 CC.
 SAMPLE VOLUME AFTER CONSOLIDATION (V_c)..... 428.3 CC.

ORIGINAL SAMPLE AREA (A_0)..... 4.60 IN².
 AREA CORRECTION:

$$A_c = A_0 (1 - \Delta V / V_0 / 1 - E)$$

$$= \underline{\hspace{10cm}}$$

$$= \underline{\hspace{10cm}}$$

$$= \underline{\hspace{10cm}} \text{ SQ. IN.}$$

JOB : 5631-003-07

BORING : 2

DEPTH : 4.5

SAMPLE : 2A

OWNER BAKER FLOOR CO. LOCATION ORANGE COUNTY

SOIL TYPE Red & yellow clayey Sandy Soil WITH

SCATTER GRAVELS (ML-FH)

SAMPLED 5/12/69 SET-UP 5/19/69 TESTED 5/22/69 (OFFICE)

SATURATED TEST FIELD MOISTURE TEST TEST LATERAL PRESSURE 1000 PSF

TYPE OF TEST D/CU

Weight soil & dish no. 924

Dry weight soil & dish 781

Net loss of moisture 143

Weight of dish only

Net weight of dry soil

Moisture, % of dry weight

BEFORE

AFTER

267

Wt. solids + moisture W_o 924 gms. 961W_o = 454 lbs.Weight solids W_s gms.Wet density W_o' + V_o' 129 pcf 126

Dry density pcf

Net diameter D = 3.42 in.


Area (0.785 D²) A = 4.60 sq.in

Height H = 6.0 in.

Volume (A_oH_o) + 1728Volume (A_oH_o) × 16.4Specific gravity of solids G_sVolume of solids W_s + G_s V_s cc(V_o - V_s) + V_s e_i cc

Initial burette reading cc

Burette reading under pressure cc

(V_p - V_s) + V_s e_p cc

DURING: ~ SAMPLE NO.: 1A DEPTH (F): 45 TYPE OF TEST: T-1

SATURATION DATA								CONSOLIDATION DATA	
TIME DATE	CHAMBER (PSI)	PACK PRESS (PSI)	EXTERNAL BURETTE (CC)	SATURATION BURETTE (CC)	PORE PRESSURE (PSI)	△	B	ELAPSED TIME MIN.	INTERIOR VOL. BUCKET (CC)
12/21/67	3.0	-	5.1	-	-	-	-	0	16.0
12/21/67	3.0	27	-	-	27.0	-	-	.1	15.9
12/21/67	3.5	-	-	-	27.0 / 31.2	4.2	.58	.25	15.8
12/21/67	3.0	27	-	-	27.0	-	-	.5	15.7
12/21/67	3.5	Cham. S	-	-	27.0 / 31.7	4.7	.4	1	15.6
12/21/67	3.0	27	-	-	27.0	-	-	2	15.5
12/21/67	3.5	Cham. S	-	-	27.0	-	-	4	15.4
12/21/67	3.0	27	-	-	27.0	-	-	8.5	-
12/21/67	3.5	Cham. S	-	-	27.0	-	-	16	-
12/21/67	3.0	27	-	-	27.0	-	-	30	15.3
12/21/67	3.5	Cham. S	-	-	27.0	-	-	60	15.2
12/21/67	3.0	27	-	-	27.0	-	-	120	15.1
12/21/67	3.5	Cham. S	-	-	27.0	-	-	240	15.0
12/21/67	3.0	27	-	-	27.0	-	-	480	-
12/21/67	3.5	Cham. S	-	-	27.0	-	-	1440	15.0

SAMPLE HEIGHT, AREA, AND VOLUME CORRECTIONS AFTER CONSOLIDATION

ORIGINAL SAMPLE HEIGHT (H_0)..... 6.000 IN.

INITIAL DIAL: 0.000 FINAL DIAL: 0.042, CHANGE IN HEIGHT (ΔH):.. 0.042 IN.

SAMPLE HEIGHT AFTER CONSOLIDATION (H_c)..... 5.958 IN.

PERCENTS DEFLECTION.(E)..... 0.70 %

ORIGINAL SAMPLE VOLUME (V₀)..... 453.9 CC.

INITIAL BURETTE: 16.5 FINAL BURETTE: 14.3, CHANGE IN VOLUME (ΔV)... 18.3 CC.

SAMPLE VOLUME AFTER CONSOLIDATION (V_e) 434.7 CC.

ORIGINAL SAMPLE AREA (A_0)..... 4.50 IN.

AREA CORRECTION:

$$A_e = A_0 \left(1 - \Delta V / V_0 \right) / (1 - E)$$

—


—

SQ. IN.

OWNER Bixler Eng Co LOCATION Orange County BORING # 3
 SOIL TYPE Yellow & Brown sandy clayey silt DEPTH 1-5'
With gravel & shale fragments (ML - FLL) SAMPLE # 13
 SAMPLED 1/22/69 SET-UP 5/22/69 TESTED 5/27/69 (S.F. OFFICE)

SATURATED TEST FIELD MOISTURE TEST TEST LATERAL PRESSURE 1500 PSF

TYPE OF TEST	TEST	TEST	TEST
	<u>106</u>		
Weight soil & dish no.	<u>933</u>	<u>126.7</u>	Net diameter <u>D_o 2.42</u> in.
Dry weight soil & dish	<u>806</u>	<u>241.4</u>	Area ($0.785 D_o^2$) <u>A_o 4.60</u> sq.in.
Net loss of moisture	<u>127</u>	<u>45.3</u>	Height <u>H_o 5.8</u> in.
Weight of dish only			Volume ($A_o H_o$) + 1728 <u>V_o _____ cu.ft.</u>
Net weight of dry soil			Volume ($A_o H_o$) = 16.4 <u>V_o 445 cc</u>
Moisture, % of dry weight	<u>15.8</u>	<u>18.8</u>	Specific gravity of solids <u>G_s _____</u>
Wt. solids + moisture	<u>W_o 833 gms.</u>	<u>955</u>	Volume of solids $W_s + G_s$ <u>V_s _____ cc</u>
$W_o + 454$	<u>W'_o _____ lbs.</u>		$(V_o - V_s) + V_s$ <u>e_i _____</u>
Weight solids	<u>W_s _____ gms.</u>		Initial burette reading <u>_____ cc</u>
Wet density $W_o + V_o$	<u>131 pcf</u>	<u>134</u>	Burette reading under pressure <u>_____ cc</u>
Dry density	<u>113 pcf</u>	<u>113</u>	$(V_p - V_s) + V_s$ <u>e_p _____</u>



BORING: 3 SAMPLE NO.: 13 DEPTH (FT): 15 TYPE OF TEST: T-1

SATURATION DATA								CONSOLIDATION DATA	
TIME DATE	CHAMBER (PSI)	BACK PRESS (PSI)	EXTERNAL BURETTE (CC)	SATURATION BURETTE (CC)	PORE PRESSURE (PSI)	△	B	ELAPSED TIME MIN.	INTERIOR VOL. BURETTE (CC)
5/22/61	0	0	-	-	25.0	-	-		
1700	32.0	25.0	-	-	25.0	-	-		
1800	22.0	15.0	-	-	21.0 / 24.0	2.0	.75		
1900	22.0	25.0	-	-	25.0	-	-		
2000	32.0	15.0	-	-	22.0 / 29.0	4.0	.96		
2100	22.0	25.0	-	-	25.0	-	-		
2200	22.0	15.0	-	-	26.0 / 21.0	4.0	.98		
1 min. 6 sec. time									
1800	1500 sec	0	-	-	-	-	-	0	14.0
								.1	1
								.25	1
								.5	1
								1	1
								2	1
								4	1
								8	1
								16	1
								30	1
								60	1
2000								120	155.0
.								240	1
5/24/61								480	1
1305								1440	166.6

SAMPLE HEIGHT, AREA, AND VOLUME CORRECTIONS AFTER CONSOLIDATION

ORIGINAL SAMPLE HEIGHT (H_0)..... 5.900 IN.

INITIAL DIAL: 0.000 FINAL DIAL: 0.046, CHANGE IN HEIGHT (Δh): 0.046 IN.

SAMPLE HEIGHT AFTER CONSOLIDATION (H_c) 5.254 IN.

PERCENTS DEFLECTION. (E).....

ORIGINAL SAMPLE VOLUME (v_0)..... 445.0 CC.

INITIAL BURETTE: 14.5 FINAL BURETTE: 153.5, CHANGE IN VOLUME (ΔV)... 14.6 CC.

SAMPLE VOLUME AFTER CONSOLIDATION (V_c) 130.4 CC.

ORIGINAL SAMPLE AREA (A_0) 1.60 IN².

$$A_s = A_{s_0} \left(1 - \Delta V / V_{s_0} \right) / (1 - \epsilon)$$

•

卷之三

DAMES & MOORE
MATERIAL SCIENCES

SATURATION & CONSOLIDATION PHASE

JOB # 2551-025-01

OWNER Beebe Soil Co. LOCATION Orange County BORING # 3
 SOIL TYPE Yellow-Brown Sandy G.H. with Decomposed DEPTH 3.0'
Stone & trace of Gravel (ML - FILL) SAMPLE # 23

SAMPLED 5/23/67 SET-UP 5/23/67 TESTED 5/25/67 (SF OFFICE)

SATURATED TEST DRY TEST FIELD MOISTURE TEST TEST LATERAL PRESSURE 2000 PSF


TYPE OF TEST T/Cu

Weight soil & dish no.	<u>932.0</u>	<u>213.1</u>
Dry weight soil & dish	<u>811.0</u>	<u>182.1</u>
Net loss of moisture	<u>121.0</u>	<u>31.0</u>
Weight of dish only		
Net weight of dry soil		
Moisture, % of dry weight	<u>14.9</u>	<u>17.1</u>



Wt. solids + moisture	<u>W_o</u>	<u>932</u> gms. <u>951</u>
W _o + 454	<u>W_{'o}</u>	lbs.
Weight solids	<u>W_s</u>	gms.
Wet density W' + V'	<u>131</u> pcf	<u>132</u>
Dry density	<u>114</u> pcf	<u>114</u>

Net diameter: D_o 2.62 in.
 Area ($0.785 D^2$) A_o 4.60 sq.in.
 Height H_o 5.0 in.
 Volume ($A_o H_o$) + 1728 V_o cu.ft.
 Volume ($A_o H_o$) × 16.4 V_{'o} cc
 Specific gravity of solids G_s
 Volume of solids W_s + G_s V_s cc
 ($V_o - V_s$) + V_s e_i
 Initial burette reading cc
 Burette reading under pressure cc
 ($V_p - V_s$) + V_s e_p



AXIAL STRESS IN LBS./SQ.FT. (X2.0 FOR HI-RANGE)

BORING: 3 SAMPLE NO.: 28 DEPTH (FT): 3.5 TYPE OF TEST:

SATURATION DATA								CONSOLIDATION DATA	
TIME DATE 1/22/57	CHAMBER (PSI)	BACK PRESS (PSI)	EXTERNAL BURETTE (CC)	SATURATION BURETTE (CC)	PORE PRESSURE (PSI)	△	B	ELAPSED TIME MIN.	INTERIOR VOL. BURETTE (CC)
1330	30.0	25.0	-	-	25.0	-	-	0	143.0
1500	35.0	Closed	-	-	25.0 / 27.9	2.9	.58	.1	145.5
1530	30.0	25.0	-	-	25.0	-	-	.25	145.8
1920	35.0	Closed	-	-	25.0 / 28.6	3.6	.72	.5	146.1
1950	37.0	25.0	-	-	25.0	-	-	1	146.3
2010	35.0	Closed	-	-	25.0 / 29.9	4.9	.99	2	146.5
Consolidation									
1430	30.0 06+	0						4	146.9
								8	1
								16)
								30	147.0
								60	148.2
								120	1
								240	1
								480)
								1440	147.4

SAMPLE HEIGHT, AREA, AND VOLUME CORRECTIONS AFTER CONSOLIDATION

ORIGINAL SAMPLE HEIGHT (H_0)..... 5.900 IN.

INITIAL DIAL: 0.350 FINAL DIAL: 0.052, CHANGE IN HEIGHT (ΔH): 0.298 IN.

SAMPLE HEIGHT AFTER CONSOLIDATION (H_c)..... 5.343 IN.

PERCENTS DEFLECTION. (E)..... %

ORIGINAL SAMPLE VOLUME (V_0)..... 445.0 CC.

INITIAL BURETTE: 145.0 FINAL BURETTE: 141.1, CHANGE IN VOLUME (ΔV)... 13.9 CC.

SAMPLE VOLUME AFTER CONSOLIDATION (V_c)..... 430.6 CC.

ORIGINAL SAMPLE AREA (A_0)..... 4.65 IN².

AREA CORRECTION:

$$A_c = A_0 (1 - \Delta V / V_0 / 1 - E)$$

= _____

= _____

= _____ SQ. IN.

ס. 55-005-15560 : בור

OWNER BAYER SEED CO. LOCATION ORANGE COUNTY BORING # 3
SOIL TYPE Red Gray & brown Sandy clay Silt DEPTH 9.0
SAMPLE # 4A

SAMPLED YR S/12/67 SET-UP C 5/24/67 TESTED C 5/25/67 (SF OFFICE)

SATURATED TEST FIELD MOISTURE TEST TEST LATERAL PRESSURE 400 PSF

TYPE OF TEST EX/CU 376

Weight soil & dish no.	929	304.6
Dry weight soil & dish	776	242.1
Net loss of moisture	153	54.8
Weight of dish only		
Net weight of dry soil		
Moisture, % of dry weight	19.7	22.0
Wt. solids + moisture	W _o 929 gms.	947
W _o + 454	W' _____ lbs.	
Weight solids	W _s _____ gms.	
Wet density W' _o + V' _o	129 pcf	132
Dry density	108 pcf	108

Net diameter D. 2.42 in.

TEST LATERAL PRESSURE 420 PSF

Net diameter D_o 2.42 in.

$$\text{Area} (0.785 D^2)$$

Height H 6.5 in

Valley (A.H.) : 1728

Volume ($A_0 H_0$) ÷ 1/28 V_0 _____ cu. ft.

$$\text{Volume } (\text{A}_0\text{H}_0) = 16.4 \quad V_0 = \underline{\hspace{2cm}} \text{cc}$$

Specific gravity of solids G_s _____


Volume of solids $W_s + G_s$ $V_s = \underline{\hspace{2cm}}$ cc

$$(Y_1 - Y_2) \pm Y$$

Initial burette reading

Initial burette reading _____ cc

Burette reading under pressure _____ cc



SHEET NO.: 1 DATE (FT): 3-0 TYPE OF TEST: Tc/cm

TIME DATE	CHAMBER (PSI)	BACK PRESS (PSI)	EXTERNAL BURETTE (CC)	SATURATION BURETTE (CC)		PORE PRESSURE (PSI)	Δ	B	CONSOLIDATION DATA	
				SATURATION BURETTE (CC)	EXTERIOR BURETTE (CC)				ELAPSED TIME MIN.	INTERIOR VOL. BURETTE (CC)
200	10.0	5.0	-	-	-	5.0	-	-		
250	7.0.0	25.0	-	-	-	25.0	-	-		
330	35.0	35.0	-	-	-	25.0 - 28.0	3.0	0.60		
400	37.0	25.0	-	-	-	25.0				
470	35.0	35.0	-	-	-	25.0 / 28.0	3.6	.72		
540	30.0	25.0	-	-	-	25.0	-	-		
570										
6100	35.0	35.0	-	-	-	25.0 / 29.0	4.8	.96		
61-7										
6200	45.0. 56.0	0							0	150.0
62-1									.1	
62-2									.25	
62-3									.5	
62-4									1	
62-5									2	
62-6									3	
62-7									8	
62-8									16	
62-9									30	
62-10									60	
62-11									120	
62-12									240	165.0
62-13									480	5
62-14									1440	153.2

SAMPLE HEIGHT, AREA, AND VOLUME CORRECTIONS AFTER CONSOLIDATIONORIGINAL SAMPLE HEIGHT (H_0)..... 6.000 IN.INITIAL DIAL: 0.000 FINAL DIAL: 0.000, CHANGE IN HEIGHT (ΔH): 0.000 IN.SAMPLE HEIGHT AFTER CONSOLIDATION (H_c)... 5.943 IN.

PERCENT DEFLECTION. (E)..... %

ORIGINAL SAMPLE VOLUME (V_0)..... 453.0 CC.INITIAL BURETTE: 150.0 FINAL BURETTE: 168.1, CHANGE IN VOLUME (ΔV)... 18.1 CC.SAMPLE VOLUME AFTER CONSOLIDATION (V_c)..... 434.6 CC.ORIGINAL SAMPLE AREA (A_0)..... 4.60 IN².

AREA CORRECTION:

$$A_c = A_0 \left(1 - \Delta V / V_0 / 1 - E \right)$$

= _____

= _____

= SQ. IN.

ATTACHMENT B
TRIAXIAL COMPRESSION TESTS
UNCONSOLIDATED - UNDRAINED
FIELD MOISTURE CONTENT

JOB: 5651-253-07

OWNER Bauer Eng Co LOCATION Orange County
 SOIL TYPE Red Clayey Sandy Silt, trace of DEPTH 1.0'
GRAVEL (ML-ELL) SAMPLE: 1A

SAMPLED JUN 12, 67 SET-UP / / TESTED 5.21.67 1 SE OFFICE

SATURATED TEST

FIELD MOISTURE TEST X

TYPE OF TEST T-1001

253

TEST LATERAL PRESSURE 1500 P.S.I.
SL. = 3.125" / MIN.

Weight soil & dish no.

320.5

D_o 2.45 in.

Dry weight soil & dish

266.7

A_o 4.60 sq.in.

Net loss of moisture

53.8

H_o 6.0 in.

Weight of dish only

—

Volume (A_oH_o) + 1723V_o cu.ft.

Net weight of dry soil

—

Volume (A_oH_o) = 16.4V_o cc

Moisture, % of dry weight

20.2

Specific gravity of solids: G_s

Wt. solids + moisture

W_o 904 gms.Volume of solids W_s + G_sV_s V_s ccW_o + 454

W' — lbs.

(V_o - V_s) + V_s V_i —

Weight solids

W_s — gms.

Initial burette reading


Wet density W_o + V_o

126 pcf

Burette reading under pressure

Dry density


105 pcf

(V_p - V_s) + V_s V_p —

IF HIGH RANGE MODE OF RECORDING DATA IS SET AT BEGINNING OF TEST,
OR IF RECORDER IS AUTOMATICALLY SET TO HIGH RANGE DURING TEST,
CHECK BOX 8c MULTIPLY AXIAL STRESS $\times 4$



SECTION OF
FAILURE



AXIAL STRESS
IN LBS 'SQ FT

5601-00 =
JCS NO.

12
BORING NO.

3.0
DEPTH

ML-FILL
SOIL TYPE

BY MCB / 5 /
TESTED

CHICAGO
OFFICE

4,500
CONFINING
PRESSURE

FIELD
MOISTURE

SATURATED
TEST

TX-QT.
TYPE OF TEST

NOTES

MOISTURE CONTENT	Dish No.	I	SAMPLE VOLUME	Net diameter	D_o _____ in.
	Wet weight soil & dish	139.0		Area $(0.785 D_o^2)$	A _____ sq.in.
	Dry weight soil & dish	118.4		Height	H_o 5.75 in.
	Net loss of moisture	20.6		Volume $(A_o H_o) \div 1728$	V_o _____ cu.ft.
	Weight of dish only	25.0		Volume $(A_o H_o) \div 16.4$	V_o _____ cc
	Net weight of dry soil	93.4		Specific gravity of solids	G_s _____
	Moisture, % of dry weight	22.0		Volume of solids $W_s - G_s$	V_s _____ cc
DRY DENSITY	Wt. solids + moisture	W_o 95.6 gms.	VOID RATIO	$(V_o - V_s) \div V_s$	e_i _____
	$W_o \div 454$	W_o _____ lbs.		Initial burette reading	_____ cc
	Weight solids	W_s _____ gms.		Burette reading under pressure	_____ cc
	Wet density $W_o' - V_o'$	123.2 pcf		$(V_p - V_s) \div V_s$	e_p _____
	Dry density	101 pcf			
			VI-50		

JOB NO.

3^{2A}

BORING NO.

3

DEPTH

DR CLS, w/
SO STRG

SOIL TYPE

BYR 4 6/1/6
TESTED


CH

OFFICE

4500

CONFINING
PRESSURE FIELD
MOISTURE SATURATED
TESTTRIAx U-U
TYPE OF TEST

IF HIGH RANGE MODE OF RECORDING DATA IS SET AT BEGINNING OF TEST,
 OR IF RECORDER IS AUTOMATICALLY SET TO HIGH RANGE DURING TEST,
 CHECK BOX & MULTIPLY AXIAL STRESS x 4

AXIAL STRESS
IN LBS/SQ FT

NOTES

MOISTURE CONTENT	Dish No.	Y	SAMPLE VOLUME	Net diameter	D _o _____ in.
	Wet weight soil & dish	158.5		Area (0.785 D _o ²)	A _____ sq.in.
	Dry weight soil & dish	136.5		Height	H _o _____ in.
	Net loss of moisture	22.0		Volume (A _o H _o) ÷ 1728	V _o _____ cu.ft.
	Weight of dish only	24.9		Volume (A _o H _o) × 16.4	V _o _____ cc
	Net weight of dry soil	111.7		Specific gravity of solids	G _s _____
DRY DENSITY	Moisture, % of dry weight	19.7		Volume of solids W _s = G _s V _s	V _s _____ cc
	Wt. solids - moisture	W _o 75.7 gms.		(V _o - V _s) = V _p	V _p _____ cc
	W _o + 454	W _o _____ lbs.		Initial burette reading	_____ cc
	Weight solids	W _s _____ gms.		Burette reading under pressure	_____ cc
	Wet density W' _o - V' o	129.5 pcf		(V _p - V _s) = V _e	V _e _____ cc
	Dry density	108 pcf	VI-51	ep _____	

5651-OC

JOB NO.

3

3

6.0

DEPTH

ML-FILL

SOIL TYPE

BY N 26 / 5 / TESTED

CHICAGO OFFICE

4500 CONFINING PRESSURE

 FIELD MOISTURE SATURATED TEST

TX-Q TYPE

IF HIGH RANGE MODE OF RECORDING DATA IS SET AT BEGINNING OF TEST,
 OR IF RECORDER IS AUTOMATICALLY SET TO HIGH RANGE DURING TEST,
 CHECK BOX 8c MULTIPLY AXIAL STRESS $\times 4$

SECTION OF
SAMPLE

AXIAL STRESS IN LBS/SQ FT

5000
4000
3000
2000
1000
0

0 .5 1.0 1.5 2.0

AXIAL DEFLECTION IN INCHES

AXIAL STRESS
IN LBS SQ FT

NOTES

MOISTURE CONTENT	Dish No.	<u>IV</u>	SAMPLE VOLUME	Net diameter	D_o _____ in.
	Wet weight soil & dish	<u>165.1</u>		Area $(0.785 D_o^2)$	A _____ sq.in.
	Dry weight soil & dish	<u>141.0</u>		Height	H_o <u>5.50</u> in.
	Net loss of moisture	<u>24.1</u>		Volume $(A_o H_o) \div 1728$	V_o _____ cu.ft.
	Weight of dish only	<u>24.5</u>		Volume $(A_o H_o) \div 16.4$	V_o _____ cc
	Net weight of dry soil	<u>116.5</u>		Specific gravity of solids	G_s _____
	Moisture, % of dry weight	<u>20.7</u>		Volume of solids $W_s + G_s$	V_s _____ cc
DRY DENSITY	Wt. solids - moisture	W_o <u>878.3</u> gms.	VOID RATIO	$(V_o - V_s) + V_s$	e_i _____
	$W_o + 454$	W_o _____ lbs.		Initial burette reading	_____ cc
	Weight solids	W_s _____ gms.		Burette reading under pressure	_____ cc
	Wet density $W_o - V_o$	<u>125.4</u> pcf		$(V_p - V_s) - V_s$	e_p _____
	Dry density	<u>104</u> pcf			
			VI-52		

5651-06
JOB NO.

3

3
BORING NO.

6.0'
DEPTH

JL-FILL
SOIL TYPE

BY NR 151
TESTED

CHICAGO
OFFICE

4500
CONFINING
PRESSURE

FIELD
MOISTURE


SATURATED
TEST

TX-Q TYPE
TYPE OF TEST

SELECTOR OF
FAILURE
IF HIGH RANGE MODE OF RECORDING DATA IS SET AT BEGINNING OF TEST,
OR IF RECORDER IS AUTOMATICALLY SET TO HIGH RANGE DURING TEST,
CHECK BOX & MULTIPLY AXIAL STRESS $\times 4$



AXIAL STRESS
IN LBS SQ FT



NOTES

MOISTURE CONTENT	Dish No.	Net diameter		D _o _____ in.
	Wet weight soil & dish	A _o (0.785 D _o ²)	H _o 5.50 in.	A _____ sq.in.
	165.1		V _o _____ cu.ft.	H _o 5.50 in.
	141.0		V _o _____ cc	G _s _____
	24.1		V _s _____ cc	(V _o - V _s) - V _s
	24.5		e _i _____	(V _o - V _s) / V _s
	116.5		cc	Initial burette reading
	20.7		cc	Burette reading under pressure
DRY DENSITY	Wt. solids + moisture	W _o 878.3 gms.	(V _p - V _s) + V _s	e _p _____
	W _o + 454	W _o _____ lbs.		
	Weight solids	W _s _____ gms.		
	Wet density W _o ' = V _o '	125.4 pcf		
	Dry density	104 oof		

VI-53

OWNER Baker Engr Co LOCATION Orange County BORING 3
 SOIL TYPE Brown, Red & Yellow clayey sandy DEPTH 13.5'
SILT (ML - FILL) SAMPLE 6A

SAMPLED 5/21/69 SET-UP 1 / 1 TESTED 5/21/69 (SF OFFICE)

SATURATED TEST

FIELD MOISTURE TEST

TEST LATERAL PRESSURE 1500 PSF

$$SR = 0.125 \text{ in./min.}$$

TYPE OF TEST IMUL

Weight soil & dish no.

104

Net diameter D_o

2.42 in.

Dry weight soil & dish

285.1

Area $(0.785 D_o^2)$

4.60 sq.in.

Net loss of moisture

40.2

Height H_o

5.10 in.

Weight of dish only

16.4

Volume $(A_o H_o) + 1728$

V_o cu.ft.

Net weight of dry soil

885 gms.

Volume $(A_o H_o) \times 16.4$

V_o cc

Moisture, % of dry weight

16.4

Specific gravity of solids G_s

V_s cc

Wt. solids + moisture

W_o + 454

$(V_o - V_s) + V_s$

e_i

Weight solids

W_s gms.

Initial burette reading

cc

Wet density $W_o' + V_o'$

129 pcf

Burette reading under pressure


cc

Dry density

111 pcf

$(V_p - V_s) + V_s$

e_p



OWNER Bauer Edge Co. LOCATION Orange County BORING # 3
 SOIL TYPE Red Brown & Yellow Sandy Clayey Silt DEPTH 16.0
With Gravel & Decomposed Stone Fragments (ML-Fill) SAMPLE # 7A
 SAMPLED 12/5/67 SET-UP 1 TESTED 5/21/67 IN OFFICE
 SATURATED TEST FIELD MOISTURE TEST TEST LATERAL PRESSURE 3000 PSF
 TYPE OF TEST T-111 372

Weight soil & dish no.

279.5

D_o 2.42 in.

Dry weight soil & dish

240.8

A_o 4.60 sq.in.

Net loss of moisture

38.7

H_o 6.0 in.

Weight of dish only

V_o cu.ft.

Net weight of dry soil

V_s cc

Moisture, % of dry weight

16.1

G_s



Wt. solids + moisture

W_o 91.3 gms.

Net diameter D_o
Area (0.785 D_o²)

W_o + 454

W_o lbs.

H_o

Weight solids

W_s gms.

V_o cu.ft.

Wet density W_o' + V_o'

127 pcf

V_s cc

Dry density

109 pcf

(V_o - V_s) + V_s

e_i

Initial burette reading


cc

Burette reading under pressure

cc

(V_p - V_s) + V_s


e_p



IF HIGH RANGE MODE OF RECORDING DATA IS SET AT BEGINNING OF TEST,
OR IF RECORDER IS AUTOMATICALLY SET TO HIGH RANGE DURING TEST,
CHECK BOX 8c MULTIPLY AXIAL STRESS $\times 4$



AXIAL STRESS
IN LBS/SQ FT



2601-003
JOB NO.

381
BORING NO.

18½
DEPTH

BR 11.6 S1
W/S 3A-6
SOIL TYPE

BY RT 6/1/57
TESTED

CH
OFFICE

3000
CONFINING
PRESSURE

FIELD
MOISTURE

SATURATED
TEST

TRIAx U-
TYPE OF TEST

NOTES

MOISTURE CONTENT	Dish No.	<u>R</u>	SAMPLE VOLUME	Net diameter	D_o _____ in.
	Wet weight soil & dish	<u>197.1</u>		Area $(0.785 D_o^2)$	A _____ sq.in.
	Dry weight soil & dish	<u>170.2</u>		Height	H_o <u>9.86</u> in.
	Net loss of moisture	<u>26.9</u>		Volume $(A_o H_o) = 1728$	V_o _____ cu.ft.
	Weight of dish only	<u>29.4</u>		Volume $(A_o H_o) = 16.4$	V_o _____ cc
	Net weight of dry soil	<u>145.8</u>		Specific gravity of solids	G_s _____
	Moisture, % of dry weight	<u>18.5</u>		Volume of solids $W_s + G_s$	V_s _____ cc
DRY DENSITY	Wt. solids - moisture	<u>W_o</u> <u>757</u> gms.	VOID RATIO	$(V_o - V_s) + V_s$	e_i _____
	$W_o \div 454$	<u>W_o</u> _____ lbs.		Initial burette reading	_____ cc
	Weight solids	<u>W_s</u> _____ gms.		Burette reading under pressure	_____ cc
	Wet density $W_o' = V_o'$	<u>130</u> pcf		$(V_p - V_s) - V_s$	e_p _____
	Dry density	<u>110</u> pcf			
			VI-56		

ATTACHMENT C
CONSOLIDATION TESTS
FOR VERTICAL PERMEABILITIES

JOB Pawnee, Experiments, 1-

DATE SAMPLED 5-15-87 10:00 A.M.

TEST STARTED BY

SOIL TYPE (if any, specify soil type and %)

CONSOLIDOMETER NO. 9 INITIAL SAMPLE HEIGHT 1.546

CONSEQUENCE NUMBER: _____ INITIAL SAMPLE HEIGHT: _____

MOISTURE & DENSITY DATA	BEFORE TEST	AFTER TEST
WT. OF RING(S) + SOIL	197.10	197.45
WT. OF RING(S) ONLY	45.10	45.10
WT. OF SOIL (NET)	152.00	152.35
WET DENSITY IN LBS/CU. FT.*	127	127
WT. OF WET SOIL + DISH NO. 405A	192.45	192.45
INT. OF DRY SOIL - DISH	176.36	171.60
WT. OF LOST MOISTURE	21.91	25.25
WT. OF DISH ONLY	56.13	45.10
WT. OF DRY SOIL	120.21	126.50
MOISTURE AS % OF DRY WT.	18.3	20.4
DRY DENSITY IN LBS/CU. FT.	127	106

TEST INSTRUCTIONS

LOAD CYCLE _____

16
3 H.T.

SPECIAL INSTRUCTION AND NOTES

Geographical Locality

Georgian All-Union

THE CLASSICAL LITERATURE

جعفر بن محبث

MULTIPLY WEIGHT OF SOIL IN GRAMS BY 0.332 WHEN ONE STANDARD D & M SAMPLE IS USED.

CONTINUED ON REVERSE SIDE

DATE	TIME	E-LAPSED TIME IN MINS.	LOAD (PSF)	DIAL READING (0.0001 IN.)	CONSOL. UNDER THIS LOAD	TOTAL CONSOL. IODATION
450						
1947	0		4556			
7	1		4446			
7	15		4435			
	20		4426			
7/11	1		4419			
7/11	2		4411			
7/11	4		4404			
7/11	9		4317			
7/11	15		4394			
10/10	3		4390			
10/10	6		4387			
11/10	12		4373			
13/10	24		4379		4765	
17/10	45		4374		4371	
5-22	10/10	12	4371		0294	
12,200						
17/40	0		41371			
7	6		41248			
7	15		41233			
	20		41219			
9/41	1		41204			
9/42	2		41182			
9/44	11		41174			
9/40	9		41164			
9/55	15		41160			
10/10	30		41155			
10/10	60		41151			
11/10	120		41147			
13/10	240		41144		4765	
17/10	45		41141		4135	
5-23	9/40	140	41135		0631	
25600						
9/45	0		3935			
7	6		3997			
7	15		3975			
	20		3954			
9/46	1		3929			
9/47	2		3901			
9/49	4		3890			
9/54	9		3863			
10/10	15		3856			
10/10	30		3850			
10/10	60		3845			
12/15	120		3835			
17/15	220		3825		0165	
17/15	45		3822		0727	
5-24	9/1	140	3821		932	
51200						
7	9/45	0	3827			
7	6		3822			
7	15		38142			
	20		38132			
9/46	1		38116			
9/11	2		3571			
9/11	4		3544			
9/54	6		3525			

DATE	TIME	E-LAPSED TIME IN MINS.	LOAD (PSF)	DIAL READING (0.0001 IN.)	CONSOL. UNDER THIS LOAD	TOTAL CONSOL. IODATION
10/10	15		3518			
10/15	30		3511			
10/45	60		3506			
11/45	120		3501			
13/45	240		3497		4765	
17/45	450		3493		3421	
5-25	9/40	140	3497		1078	
102400						
9/45	0		3487			
7	6		3350			
7	15		3318			
	30		3257			
9/46	1		3245			
9/47	2		3212			
9/49	4		3144			
9/54	7		3145			
10/0	15		3130			
10/15	30		3132			
10/45	60		3125			
11/45	120		3121			
13/45	240		3117		4765	
17/45	450		3113		3105	
5-26	9/40	140	3105		1650	
100						
9/46	1		3431			
14/00			2982			
18/00			4001			

WORK SHEET - SPECIFIC GRAVITY TESTS

Project: Sauri Engr. Co.		Job No. 521-005	Hole No. 1	Date 5/21/67
SPECIFIC GRAVITY OF SOLIDS (G_s)				
Sample No.	2A	253.0		
Flask No.	A			
Temperature of Water and Soil, T, °C	22.5			
Pan No.				
Pan + Dry Soil		446.03		
Pan		327.76		
Dry Soil	W _s	118.27		
Flask + Water at T, °C	W _{bw}	651.3%		
W _s + W _{bw}		770.03		
Flask + Water + Immersed Soil	W _{bws}	733.88		
Displaced Water, W _s + W _{bw} - W _{bws}		43.11		
Correction Factor	K	0.9996		
(W _s K) : (W _s + W _{bw} - W _{bws})	G _s	2.71		
APPARENT (G _a) AND BULK (G _m) SPECIFIC GRAVITY				Temp. Corr. Factor
Sample No.				°C K
Temperature of Water and Soil, T, °C			14	1.0010
Pan + Saturated Surface - Dry Soil			15	1.0009
Tare Weight			16	1.0007
Saturated Surface - Dry Soil	B		17	1.0006
(Wire Basket + Soil) in Water			18	1.0004
Wire Basket in Water			19	1.0002
Saturated Soil in Water	C		20	1.0000
Tare Weight + Dry Soil			21	0.9998
Tare Weight			22	0.9996
Dry Soil	A		23	0.9993
Correction Factor	K		24	0.9991
(A-K) : (A-C) (Apparent)	G _a		25	0.9988
(A-K) : (B-C) (Bulk)	G _m		26	0.9985
Remarks:			27	0.9983
			28	0.9980
			29	0.9977
			30	0.9974
			31	0.9971
Tested by: P.C	Computed by: B.C		Checked by: _____	

JOB NO. 2 Elevation 65JOB NO. 515-18-07

DATE SAMPLED

BORING NO. 9-1TEST STARTED 5-18-61 BY W.M. TEST FINISHED 5-19-61 BY W.M.SOIL TYPE Clean sand with some silt and gravelDEPTH 15'CONSOLIDOMETER NO. 14INITIAL SAMPLE HEIGHT 1.125

MOISTURE & DENSITY DATA	BEFORE TEST	AFTER TEST
WT. OF RING(S) - SOIL	<u>193.64</u>	<u>193.34</u>
WT. OF RING(S) ONLY	<u>44.90</u>	<u>44.90</u>
WT. OF SOIL (NET)	<u>148.74</u>	<u>148.44</u>
WET DENSITY IN LBS/CU. FT.*	<u>123.0</u>	<u>123.0</u>
WT. OF WET SOIL + DISH NO. <u>253</u>	<u>185.73</u>	<u>193.34</u>
INT. OF DRY SOIL + DISH	<u>161.15</u>	<u>165.00</u>
WT. OF LOST MOISTURE	<u>26.58</u>	<u>26.84</u>
WT. OF DISH ONLY	<u>55.04</u>	<u>44.90</u>
WT. OF DRY SOIL	<u>125.71</u>	<u>121.60</u>
MOISTURE AS % OF DRY WT.	<u>23.3</u>	<u>22.1</u>
DRY DENSITY IN LBS/CU. FT.	<u>100</u>	<u>101</u>

TEST INSTRUCTIONS

LOAD CYCLE

1000-1000-1000-10001000-1000-1000-10001000-1000-1000-10001000-1000-1000-1000SPECIAL INSTRUCTION AND NOTES
(1) 1000-1000-1000-1000
(2) 1000-1000-1000-1000
(3) 1000-1000-1000-1000
26-11-11-11-11-11-11

DATE	TIME	LAPSED TIME IN MINS.	LOAD (PSF)	DIAL READING (0.0001 IN.)	CONSOL. UNDER THIS LOAD	TOTAL CONSOL. IDATION
5-18			0			
	12-6		400	10		
			1000			
	3-5		400	13	0024	
			1000			
	1300		400	12		
			1000			
	1320		400	11		
			1000			
	1340		400	10		
			1000			
	1400		400	9		
			1000			
	1420		400	8		
			1000			
	1440		400	7		
			1000			
	1457		400	6		
			1000			
	1520		400	5		
			1000			
	1540		400	4		
			1000			
	1557		400	3		
			1000			
	1620		400	2		
			1000			
	1640		400	1		
			1000			
	1657		400	0		
			1000			
	1720		400	-1		
			1000			
	1740		400	-2		
			1000			
	1757		400	-3		
			1000			
	1820		400	-4		
			1000			
	1840		400	-5		
			1000			
	1857		400	-6		
			1000			
	1920		400	-7		
			1000			
	1940		400	-8		
			1000			
	1957		400	-9		
			1000			
	2020		400	-10		
			1000			
	2040		400	-11		
			1000			
	2057		400	-12		
			1000			
	2120		400	-13		
			1000			
	2140		400	-14		
			1000			
	2157		400	-15		
			1000			
	2220		400	-16		
			1000			
	2240		400	-17		
			1000			
	2257		400	-18		
			1000			
	2320		400	-19		
			1000			
	2340		400	-20		
			1000			
	2357		400	-21		
			1000			
	2420		400	-22		
			1000			
	2440		400	-23		
			1000			
	2457		400	-24		
			1000			
	2520		400	-25		
			1000			
	2540		400	-26		
			1000			
	2557		400	-27		
			1000			
	2620		400	-28		
			1000			
	2640		400	-29		
			1000			
	2657		400	-30		
			1000			
	2720		400	-31		
			1000			
	2740		400	-32		
			1000			
	2757		400	-33		
			1000			
	2820		400	-34		
			1000			
	2840		400	-35		
			1000			
	2857		400	-36		
			1000			
	2920		400	-37		
			1000			
	2940		400	-38		
			1000			
	2957		400	-39		
			1000			
	3020		400	-40		
			1000			
	3040		400	-41		
			1000			
	3057		400	-42		
			1000			
	3120		400	-43		
			1000			
	3140		400	-44		
			1000			
	3157		400	-45		
			1000			
	3220		400	-46		
			1000			
	3240		400	-47		
			1000			
	3257		400	-48		
			1000			
	3320		400	-49		
			1000			
	3340		400	-50		
			1000			
	3357		400	-51		
			1000			
	3420		400	-52		
			1000			
	3440		400	-53		
			1000			
	3457		400	-54		
			1000			
	3520		400	-55		
			1000			
	3540		400	-56		
			1000			
	3557		400	-57		
			1000			
	3620		400	-58		
			1000			
	3640		400	-59		
			1000			
	3657		400	-60		
			1000			
	3720		400	-61		
			1000			
	3740		400	-62		
			1000			
	3757		400	-63		
			1000			
	3820		400	-64		
			1000			
	3840		400	-65		
			1000			
	3857		400	-66		
			1000			
	3920		400	-67		
			1000			
	3940		400	-68		
			1000			
	3957		400	-69		
			1000			
	4020		400	-70		
			1000			
	4040		400	-71		
			1000			
	4057		400	-72		
			1000			
	4120		400	-73		
			1000			
	4140		400	-74		
			1000			
	4157		400	-75		
			1000			
	4220		400	-76		
			1000			
	4240		400	-77		
			1000			
	4257		400	-78		
			1000			
	4320		400	-79		
			1000			
	4340		400	-80		
			1000			
	4357		400	-81		
			1000			
	4420		400	-82		
			1000			
	4440		400	-83		
			1000			
	4457		400	-84		
			1000			
	4520		400	-85		
			1000			
	4540		400	-86		
			1000			
	4557		400	-87		
			1000			
	4620		400	-88		
			1000			
	4640		400	-89		
			1000			
	4657		400	-90		
			1000			
	4720		400	-91		
			1000			
	4740		400	-92		
			1000			
	4757		400	-93		
			1000			
	4820		400	-94		
			1000			
	4840		400	-95		
			1000			
	4857		400	-96		
			1000			
	4920		400	-97		
			1000			
	4940		400	-98		
			1000			
	4957		400	-99		
			1000			
	5020		400	-100		
			1000			

DATE	TIME	LAPSED TIME IN MINS.	LOAD (PSF)	DIAL READING (0.0001 IN.)	UNDER THIS LOAD	TOTAL CONSOL. IDATION
			3200	C. - 146 - 1		
5-22	1205	120	4761	4919		
	1205	240	4699	4919		
	1205	450	4696	0925	/	
5-22	1305	1912	4694			
		4400				
	1005	0	4694			
	7	6	4669			
	1	15	4664			
	1	30	4660			
	1006	1	4661			
	1007	2	4599			
	1008	4	4597			
	1016	9	4595			
	1030	15	4593			
	1030	30	4593			
	1105	60	4590			
	1205	140	4587			
	1405	240	4585	4919		
	1805	240	4583	4521		
5-22	1005	1020	4521	0930	/	
		1200				
	1005	0	4521			
	7	6	4471			
	1	15	4464			
	1	30	4458			
	1006	1	4453			
	1007	2	4450			
	1007	4	4447			
	1014	9	4443			
	1020	15	4443			
	1035	30	4439		/	
	1105	60	4437			
	1305	180	4433			
	1505	240	4431	4919		
	1805	240	4429	4422		
5-22	1005	1420	4427	0492	/	
		25400				
	1105	0	4427			
	7	6	4251			
	1	15	41742			
	1	30	4235			
	1006	1	4230			
	1007	2	4225			
	1029	11	4221			
	1014	0	4217			
	1030	15	4214			
	1035	30	4211			
	1105	60	4207			
	1204	180	4205			
	1405	240	4201	4919		
	1705	240	4198	4195		
5-23	1000	1420	4195	0924	/	

DATE	TIME	LAPSED TIME IN MINS.	LOAD (PSF)	DIAL READING (0.0001 IN.)	UNDER THIS LOAD	TOTAL CONSOL. IDATION
			51200	C. - 146 - 1		
	1000	0	4195			
	7	6	3975			
	1	15	3939			
	1	30	3938			
	1001	1	3914			
	1002	2	3911			
	1004	4	3905			
	1017	9	3990			
	1115	15	3995			
	1030	30	3990			
	1100	60	3987			
	1200	120	3983			
	1400	240	3970	4919		
	1800	480	3878	3972		
5-26	1000	1400	3872	1047		
		102000				
	1000	0	3872			
	7	6	3566			
	1	15	3512			
	1	30	3500			
	1001	1	3474			
	1002	2	3464			
	1004	4	3453			
	1009	9	3443			
	1015	15	3437			
	1030	30	3431			
	1100	60	3425			
	1200	120	3420			
	1400	240	3415			
	1800	480	3411			
5-27	1000	1400	3400			
	1801	1	3900			

WORK SHEET - SPECIFIC GRAVITY TESTS

Project: Brewster Edger Co Job No. 5421-202 Hole No. 3 Date 5/21/69

SPECIFIC GRAVITY OF SOLIDS (G_s)

Sample No.		1	C. 1.5			
Flask No.		C				
Temperature of Water and Soil, T, °C		22.5				
Pan No.						
Pan + Dry Soil		393.26				
Pan		283.07				
Dry Soil	W_s	110.19				
Flask + Water at T, °C	W_{bw}	651.29				
$W_s + W_{bw}$		761.48				
Flask + Water + Immersed Soil	W_{bws}	727.26				
Displaced Water, $W_s + W_{bw} - W_{bws}$		40.22				
Correction Factor	K	.9995				
$(W_s K) \div (W_s + W_{bw} - W_{bws})$	G_s	2.14				

APPARENT (G_a) AND BULK (G_m) SPECIFIC GRAVITY

Sample No.			Temp. °C	Corr. Factor K
Temperature of Water and Soil, T, °C			14	1.0010
Pan + Saturated Surface - Dry Soil			15	1.0009
Tare Weight			16	1.0007
Saturated Surface - Dry Soil	B		17	1.0006
(Wire Basket + Soil) in Water			18	1.0004
Wire Basket in Water			19	1.0002
Saturated Soil in Water	C		20	1.0000
Tare Weight + Dry Soil			21	0.9998
Tare Weight			22	0.9996
Dry Soil	A		23	0.9993
Correction Factor	K		24	0.9991
$(A-K) \div (A-C)$ (Apparent)	G_a		25	0.9988
$(A-K) \div (B-C)$ (Bulk)	G_m		26	0.9985
Remarks:			27	0.9983
			28	0.9980
			29	0.9977
			30	0.9974
			31	0.9971
Tested by: B		Computed by: F	Checked by: C	

ATTACHMENT D
CONSOLIDATION TESTS
FOR HORIZONTAL PERMEABILITIES

JOB Bauer Engineering

JOB NO. 5451-CP 3-C 7

BORING NO. TP 1 - 1

DATE SAMPLED

TEST STARTED 5-19-67 BY PTR TEST FINISHED 7-1-67 BY SH 6/7 DEPTH 2.0
SOIL TYPE 6, 1, 1 (L S.A. & S.L. - F.G.)

CONSOLIDOMETER NO. 52 **INITIAL SAMPLE HEIGHT** 1 mm - 6.

MOISTURE & DENSITY DATA	BEFORE TEST	AFTER TEST
WT. OF RING(S) + SOIL	- 199.5 -	- 200.7 -
WT. OF RING(S) ONLY	45.1	45.1
WT. OF SOIL (NET)	154.4	155.6
WET DENSITY IN LBS/CU. FT. [*]	128.3	120.3
-----	-----	-----
WT. OF WET SOIL + DISH NO. 372	193.2	200.7
INT. OF DRY SOIL + DISH	170.1	171.7
WT. OF LOST MOISTURE	23.6	22.0
WT. OF DISH ONLY	56.3	45.1
WT. OF DRY SOIL	113.8	124.1
MOISTURE AS % OF DRY WT.	20.2	23.0
DRY DENSITY IN LBS/CU. FT.	106.3	105.1

TEST INSTRUCTIONS

LOAD CYCLE _____

SPECIAL INSTRUCTION AND NOTES

- ① limited loadings
 - ② In general lighter
 - ③ do not allow updates

DATE	TIME	LAPSED TIME IN MINNS.	LOAD (PSF)	DIAL READING (.0001 IN.)	CONSOL. UNDER THIS LOAD	TOTAL CONSOL- IDATION
5-18-61			0			
	1355			5108		
			100			
	13-6			50.85		.0015
		SAT				
				50.86	61.2	
		200				
	1358			50.83		.0017
				50.84	64.0	
		400				
	1359			50.75		.0025
				50.76	64.0	
		850				
	1400			50.71		.0029
	1404			50.72	64.0	
		1600				
	1405			50.72		
	1406			50.72		.0048
	1511			50.53	64.0	
		3200				
	1542			50.25		
	1705			50.13		
E-10	830			50.10		.0090
		6400				
	1005	0		5010		
		6		4977		
	1	15		4966		
	↓	=n		4962		
	1006	1		4950		
	1007	2		4951		

MULTIPLY WEIGHT OF SOIL IN GRAMS BY 0.832 WHEN ONE STANDARD D & M SAMPLE IS USED.

ONE STANDARD D&G™ SAMPLE CONTAINER ON REVERSE SIDE

DATE	TIME	LAPSED TIME IN MINNS.	LOAD (IPSF)	GAUL READING 1.0301 IN.)	CONSOL. UNDER THIS LOAD	TOTAL CONSOL. IGATION
			12.5-00-C			
11-20	0			4753		
	1			4756		
	2			4743		
	3			4731		
0931	1			4717		
0932	2			4704		
0934	4			4695		
0937	7			4687		
0941	15			4684		
1042	30			4681		
1030	6			4678		
1130	120			4675		
1136	11			4671		5100
1130	11:50			4667		4664
F-21	1130	11:50		4664		0436
			513.00			
0930	0			4664		
	6			4558		
	15			4533		
	30			4514		
931	1			4488		
932	2			4462		
934	4			4442		
930	9			4428		
945	15			4424		
1000	30			4419		
1030	40			4415		
1130	120			4410		
1130	12:00			4406		5100
1130	12:00			4403		4397
5-23	930	1440		4397		0703
			102400			
930	0			4397		
	6			4270		
	15			4235		
	30			4204		
931	1			4160		
932	2			4112		
934	4			4065		
937	9			4033		
945	15			4028		
1000	30			4019		
1030	40			4012		
1130	120			4005		
1130	12:50			3978		5100
1130	13:00			3993		3986
5-24	930	13:40		3986		1114
			100			
931				4365		
1030				4179		
1130				4825		5100
F-25	930			4800		42919
				4870		421

WORK SHEET - SPECIFIC GRAVITY TESTS

Project: Bauer Engg. Co. Job No. 5651-0-3 Hole No. TP-1 Date 5/1/67

SPECIFIC GRAVITY OF SOLIDS (G_s)

Sample No.	1	$\text{at } 3.5$			
Flask No.	B				
Temperature of Water and Soil, T, °C	22.5				
Pan No.					
Pan + Dry Soil		440.30			
Pan		320.21			
Dry Soil	W_s	120.06			
Flask + Water at T, °C	W_{bw}	683.66			
$W_s + W_{bw}$		713.66			
Flask + Water + Immersed Soil	W_{bws}	731.87			
Displaced Water, $W_s + W_{bw} - W_{bws}$		40.59			
Correction Factor	K	0.9994			
$(W_s K) \div (W_s + W_{bw} - W_{bws})$	G_s	1.81			

APPARENT (G_a) AND BULK (G_m) SPECIFIC GRAVITY

Sample No.		Temp. °C	Corr. Factor K
Temperature of Water and Soil, T, °C		14	1.0010
Pan + Saturated Surface - Dry Soil		15	1.0009
Tare Weight		16	1.0007
Saturated Surface - Dry Soil	B	17	1.0006
(Wire-Basket + Soil) in Water		18	1.0004
Wire Basket in Water		19	1.0002
Saturated Soil in Water	C	20	1.0000
Tare Weight + Dry Soil		21	0.9998
Tare Weight		22	0.9996
Dry Soil	A	23	0.9993
Correction Factor	K	24	0.9991
$(AK) \div (A-C)$ (Apparent)	G_a	25	0.9988
$(AK) \div (B-C)$ (Bulk)	G_m	26	0.9986
Remarks:		27	0.9983
		28	0.9980
		29	0.9977
		30	0.9974
		31	0.9971

Tested by: B- Computed by: B- Checked by: C

JOB 5-17-1JOB NO. 5-17-1DATE SAMPLED 5-17-1BORING NO. 5-17-1TEST STARTED 5-17-1 BY 5-17-1 TEST FINISHED 5-17-1 BY 5-17-1SOIL TYPE Clayey sand, silt with gravel (less fine)CONSOLIDOMETER NO. 11 INITIAL SAMPLE HEIGHT 1.25

MOISTURE & DENSITY DATA	BEFORE TEST	AFTER TEST
WT. OF RING(S) + SOIL	<u>128.74</u>	<u>139.72</u>
WT. OF RING(S) ONLY	<u>23.0</u>	<u>44.90</u>
WT. OF SOIL (NET)	<u>105.74</u>	<u>94.82</u>
WET DENSITY IN LBS/CU. FT.	<u>119.4</u>	<u>120.0</u>
WT. OF WET SOIL + DISH NO. <u>125</u>	<u>202.86</u>	<u>139.72</u>
INT. OF DRY SOIL + DISH	<u>178.73</u>	<u>163.00</u>
WT. OF LOST MOISTURE	<u>24.13</u>	<u>26.75</u>
WT. OF DISH ONLY	<u>54.30</u>	<u>44.90</u>
WT. OF DRY SOIL	<u>122.43</u>	<u>118.10</u>
MOISTURE AS % OF DRY WT.	<u>19.4</u>	<u>22.7</u>
DRY DENSITY IN LBS/CU. FT.	<u>100</u>	<u>98.7</u>

TEST INSTRUCTIONS

LOAD CYCLE 1600 1600 1600 1600

SPECIAL INSTRUCTION AND NOTES

Test started at 10:00 AM
Test continued until 1:00 PM
Test stopped at 1:00 PM
Test resumed at 1:15 PM
Test completed at 2:00 PM

DATE	TIME	E-LAPSED TIME IN MINNS.	LOAD (PSF)	DIAL READING (.0001 IN.)	CONSOL. UNDER THIS LOAD	TOTAL CONSOL. IODATION
5-17						
			2			
10:00		0	-	-		
10:01		1	-	-		
10:02		2	-	-		
10:03		3	-	-		
10:04		4	-	-		
10:05		5	-	-		
10:06		6	-	-		
10:07		7	-	-		
10:08		8	-	-		
10:09		9	-	-		
10:10		10	-	-		
10:11		11	-	-		
10:12		12	-	-		
10:13		13	-	-		
10:14		14	-	-		
10:15		15	-	-		
10:16		16	-	-		
10:17		17	-	-		
10:18		18	-	-		
10:19		19	-	-		
10:20		20	-	-		
10:21		21	-	-		
10:22		22	-	-		
10:23		23	-	-		
10:24		24	-	-		
10:25		25	-	-		
10:26		26	-	-		
10:27		27	-	-		
10:28		28	-	-		
10:29		29	-	-		
10:30		30	-	-		
10:31		31	-	-		
10:32		32	-	-		
10:33		33	-	-		
10:34		34	-	-		
10:35		35	-	-		
10:36		36	-	-		
10:37		37	-	-		
10:38		38	-	-		
10:39		39	-	-		
10:40		40	-	-		
10:41		41	-	-		
10:42		42	-	-		
10:43		43	-	-		
10:44		44	-	-		
10:45		45	-	-		
10:46		46	-	-		
10:47		47	-	-		
10:48		48	-	-		
10:49		49	-	-		
10:50		50	-	-		
10:51		51	-	-		
10:52		52	-	-		
10:53		53	-	-		
10:54		54	-	-		
10:55		55	-	-		
10:56		56	-	-		
10:57		57	-	-		
10:58		58	-	-		
10:59		59	-	-		
10:50		60	-	-		
10:51		61	-	-		
10:52		62	-	-		
10:53		63	-	-		
10:54		64	-	-		
10:55		65	-	-		
10:56		66	-	-		
10:57		67	-	-		
10:58		68	-	-		
10:59		69	-	-		
10:50		70	-	-		
10:51		71	-	-		
10:52		72	-	-		
10:53		73	-	-		
10:54		74	-	-		
10:55		75	-	-		
10:56		76	-	-		
10:57		77	-	-		
10:58		78	-	-		
10:59		79	-	-		
10:50		80	-	-		
10:51		81	-	-		
10:52		82	-	-		
10:53		83	-	-		
10:54		84	-	-		
10:55		85	-	-		
10:56		86	-	-		
10:57		87	-	-		
10:58		88	-	-		
10:59		89	-	-		
10:50		90	-	-		
10:51		91	-	-		
10:52		92	-	-		
10:53		93	-	-		
10:54		94	-	-		
10:55		95	-	-		
10:56		96	-	-		
10:57		97	-	-		
10:58		98	-	-		
10:59		99	-	-		
10:50		100	-	-		
10:51		101	-	-		
10:52		102	-	-		
10:53		103	-	-		
10:54		104	-	-		
10:55		105	-	-		
10:56		106	-	-		
10:57		107	-	-		
10:58		108	-	-		
10:59		109	-	-		
10:50		110	-	-		
10:51		111	-	-		
10:52		112	-	-		
10:53		113	-	-		
10:54		114	-	-		
10:55		115	-	-		
10:56		116	-	-		
10:57		117	-	-		
10:58		118	-	-		
10:59		119	-	-		
10:50		120	-	-		
10:51		121	-	-		
10:52		122	-	-		
10:53		123	-	-		
10:54		124	-	-		
10:55		125	-	-		
10:56		126	-	-		
10:57		127	-	-		
10:58		128	-	-		
10:59		129	-	-		
10:50		130	-	-		
10:51		131	-	-		
10:52		132	-	-		
10:53		133	-	-		
10:54		134	-	-		
10:55		135	-	-		
10:56		136	-	-		
10:57		137	-	-		
10:58		138	-	-		
10:59		139	-	-		
10:50		140	-	-		
10:51		141	-	-		
10:52		142	-	-		
10:53		143	-	-		
10:54		144	-	-		
10:55		145	-	-		
10:56		146	-	-		
10:57		147	-	-		
10:58		148	-	-		
10:59		149	-	-		
10:50		150	-	-		
10:51		151	-	-		
10:52		152	-	-		
10:53		153	-	-		
10:54		154	-	-		
10:55		155	-	-		
10:56		156	-	-		
10:57		157	-	-		
10:58		158	-	-		
10:59		159	-	-		
10:50		160	-	-		
10:51		161	-	-		
10:52		162	-	-		
10:53		163	-	-		
10:54		164	-	-		
10:55		165	-	-		
10:56		166	-	-		
10:57		167	-	-		
10:58		168	-	-		
10:59		169	-	-		
10:50		170	-	-		
10:51		171	-	-		
10:52		172	-	-		
10:53		173	-	-		
10:54		174	-	-		
10:55		175	-	-		
10:56		176	-	-		
10:57		177	-	-		
10:58		178	-	-		
10:59		179	-	-		
10:50		180	-	-		
10:51		181	-	-		
10:52		182	-	-		
10:53		183	-	-		
10:54		184	-	-		
10:55		185	-	-		
10:56		186	-	-		
10:57		187	-	-		
10:58		188	-	-		
10:59		189	-	-		
10:50		190	-	-		
10:51		191	-	-		
10:52		192	-	-		
10:53		193	-	-		
10:54		194	-	-		
10:55		195	-	-		
10:56		196	-	-		
10:57		197	-	-		
10:58		198	-	-		
10:59		199	-	-		
10:50		200	-	-		
10:51		201	-	-		
10:52		202	-	-		
10:53		203	-	-		
10:54		204	-	-		
10:55		205	-	-		
10:56		206	-	-		
10:57		207	-	-		
10:58		208	-	-		
10:59		209	-	-		
10:50		210	-	-		
10:51		211	-	-		
10:52		212	-	-		
10:53		213	-	-		
10:54		214	-	-		
10:55		215	-	-		
10:56		216	-	-		
10:57		217				

DATE	TIME	E- LAPSED TIME IN MINS.	LOAD (IPSF)	DIAL READING 1.0001 IN.)	CONSOL- UNDER THIS LOAD	TOTAL CONSOL- IDATION
5-21-37			2500	Centrifuge		
	12:0	240		4430		4653
	1750	470		4427		4425
5-22-37	0730	1430		4425		.0221
			6450			
	1427	0		4425		
		6		4345		
	7	15		4331		
		21		4334		
	951	1		4321		
	952	2		4317		
	953	4		4334		
	954	0		4322		
	1005	15		4321		
	1020	21		4319		
	1050	60		4317		
	1147	130		4315		
	1247	260		4313		4653
	1750	670		4310		4307
5-23	1950	1440		4307		0346
			12,850			
	950	0		4157		
	7	6		4161		
		15		4154		
		30		4150		
	951	1		4146		
	952	2		4143		
	953	4		4140		
	954	9		4137		
	1005	15		4135		
	1020	30		4132		
	1050	60		4130		
	1250	180		4126		
	1350	240		4124		4653
	1750	1100		4122		4118
5-24	950	1310		4119		0335
			2560			
	950	0		4119		
	7	6		3896		
		15		3889		
		31		3882		
	951	1		3877		
	952	2		3872		
	953	4		3867		
	954	9		3863		
	1005	15		3860		
	1020	31		3856		
	1050	60		3853		
	1150	120		3850		
	1350	240		3846		4653
	1750	1100		3843		3837
5-25	950	1310		3838		0335

APPLIED EARTH SCIENCES

WORK SHEET - SPECIFIC GRAVITY TESTS

Project: Parker Engg. Co. Job No. 5651-003 Hole No. T-2 Date 5/21/67

SPECIFIC GRAVITY OF SOLIDS (G_s)

Sample No.	1	at 3.0		
Flask No.	D			
Temperature of Water and Soil, $T, ^\circ C$	22.5			
Pan No.				
Pan + Dry Soil	351.15			
Pan	260.20			
Dry Soil	W_s	93.95		
Flask + Water at $T, ^\circ C$	W_{bw}	643.66		
$W_s + W_{bw}$		142.51		
Flask + Water + Immersed Soil	W_{bws}	705.30		
Displaced Water, $W_s + W_{bw} - W_{bws}$		34.31		
Correction Factor	K	.9995		
$(W_s K) \div (W_s + W_{bw} - W_{bws})$	G_s	2.73		

APPARENT (G_a) AND BULK (G_m) SPECIFIC GRAVITY

Temp. Corr. Factor

Sample No.			°C	K
Temperature of Water and Soil, $T, ^\circ C$			14	1.0010
Pan + Saturated Surface - Dry Soil			15	1.0009
Tare Weight			16	1.0007
Saturated Surface - Dry Soil	B		17	1.0006
(Wire Basket + Soil) in Water			18	1.0004
Wire Basket in Water			19	1.0002
Saturated Soil in Water	C		20	1.0000
Tare Weight + Dry Soil			21	0.9998
Tare Weight			22	0.9996
Dry Soil	A		23	0.9993
Correction Factor	K		24	0.9991
$(A-K) \div (A-C)$ (Apparent)	G_a		25	0.9988
$(A-K) \div (B-C)$ (Bulk)	G_m		26	0.9986
Remarks:			27	0.9983
			28	0.9980
			29	0.9977
			30	0.9974
			31	0.9971
Tested by: BC	Computed by: BC	Checked by: <u> </u>		

ATTACHMENT E

SUPPLEMENTARY MOISTURE - DENSITY TESTS

MOISTURE AND DENSITY DETERMINATIONS

DAMES & MOORE

CLIENT BAUER ENGINEERING

JOB NO. 5551-003

LOCATION ORANGE COUNTY, VIRGINIA

PAGE 1 OF 3

BORING	1	1	1	1	2	2	2
SAMPLE NO.	1B	AA	5A	5B	1A	1C	3A
SAMPLE DEPTH	1.5	8.5	10.0	11.0	1.5	2.0	7.0
DATE SAMPLED BY	5-12	JAR					
DATE TESTED BY	MRR	5-17					
SOIL TYPE							
LABORATORY IDENTIFICATION							
NO. OF RINGS	6	6	4	3	THIN WALL 1/16 IN = 5.0"	3	4
WT. OF WET SOIL & RINGS	1141	1131	747	598	542	721	
WT. OF RINGS	2.70	2.70	180	135	135	180	
WT. OF WET SOIL					743.5		
WET DENSITY (LBS./CU.FT.)	120.9	119.5	118.0	128.4	123.2	112.4	
DRY DENSITY (LBS./CU.FT.)	97	95	94	107	101	88	91

MOISTURE CONTENT	DENSITY	WT. OF DRY SOIL & DISH	WT. OF WET SOIL & DISH	WT. OF DRY SOIL	WT. OF DISH	WT. OF DRY SOIL	DISH NO.
		180.1	157.5	167.9	144.5	132.0	1
		149.0	130.0	144.0	133.2	107.5	2
NET LOSS OF MOISTURE	31.1	27.5	25.5	23.9	23.3	29.5	
		22.5	21.4	24.3	24.5	22.4	3
		126.5	105.6	101.2	119.5	99.8	4
MOISTURE CONTENT (% DRY WT.)	24.7	26.0	25.2	20.0	22.4	28.8	21.4

CLIENT

JOB NO. 5651-303

LOCATION

PAGE 2 OF 4

		SAMPLE B SOIL TYPE									
BORING		2	2	2	3	3	3	3	3	3	3
SAMPLE NO.	4	5A	5B	1B	2A	3A	3B	4B	4B	4B	4B
SAMPLE DEPTH	9.0	11.5	11.7	1.0	3.5	6.5	6.8	8.5	8.5	8.5	8.5
DATE SAMPLED BY	JAR	5-12									
DATE TESTED BY	MRA	5-17									
SOIL TYPE											
LABORATORY IDENTIFICATION											
NO. OF RINGS	5	6	4	4	2	6	4	4	3	3	3
WT. OF WET SOIL & RINGS	912	12.31	72.8	72.2	301	1203	737	585	585	585	585
WT. OF RINGS	225	270	180	180	90	270	100	135	135	135	135
WT. OF WET SOIL											
WET DENSITY (LBS./CU.FT.)	114.3	133.3	14.0	12.8	120.9	129.5	116.0	129.8	129.8	129.8	129.8
DRY DENSITY (LBS./CU.FT.)	93	101	86	94	101	108	96	113	113	113	113
DISH NO.	2-10	4	V	2.0	N	18	6	17	17	17	17
WT. OF WET SOIL & DISH	133.5	137.5	171.9	155.9	152.0	149.3	135.1	143.8	143.8	143.8	143.8
WT. OF DRY SOIL & DISH	111.9	109.0	135.0	133.5	131.0	139.1	115.5	132.2	132.2	132.2	132.2
NET LOSS OF MOISTURE	21.6	20.5	36.9	22.4	21.0	24.4	19.6	11.6	11.6	11.6	11.6
WT. OF DISH	21.0	21.5	24.5	20.9	24.7	21.5	21.8	22.3	22.3	22.3	22.3
WT. OF DRY SOIL	90.9	87.5	110.5	112.6	106.3	118.4	93.7	109.9	109.9	109.9	109.9
MOISTURE CONTENT (% DRY WT.)	23.8	32.6	33.4	19.9	19.8	20.6	20.7	10.1	10.1	10.1	10.1

VI-73

MOISTURE AND DENSITY DETERMINATIONS

DAMES & MOORE

CLIENT.....

JOB NO. 5651-993

LOCATION.....

PAGE 3 OF 3

BORING	3	3	3	3	3	3	3	3
SAMPLE NO.	5-	6A	8A	8B	9A	9B	10	
SAMPLE DEPTH	11.0	14.0	18.5	18.7	21.0	21.4	22.0	
DATE SAMPLED BY	JBR	5-12						
DATE TESTED BY	MFB	5-17						
SOIL TYPE								
LABORATORY IDENTIFICATION								
NO. OF RINGS	2	3	6	1	5	4	6	
WT. OF WET SOIL & RINGS	373	598	1190	742	1026	816	1267	
WT. OF RINGS	90	135	270	190	225	180	220	
WT. OF WET SOIL								
WET DENSITY (LBS./CU.FT.)	117.5	128.5	127.4	116.8	133.2	132.3	138.3	
DRY DENSITY (LBS./CU.FT.)	96	105	104	97	116	115	121	
DISH NO.	M	N	III	I	VII	E	g	
WT. OF WET SOIL & DISH	140.5	111.2	165.0	153.1	176.9	172.9	155.0	
WT. OF DRY SOIL & DISH	119.3	95.5	139.2	131.1	157.5	153.7	139.5	
NET LOSS OF MOISTURE	21.2	15.7	25.8	22.0	19.4	19.7	16.5	
WT. OF DISH	25.4	24.2	25.0	25.0	25.2	21.6	22.2	
WT. OF DRY SOIL	93.9	71.3	114.2	106.1	132.3	131.6	117.3	
MOISTURE CONTENT (% DRY WT.)	22.6	22.1	22.6	20.8	14.5	14.9	14.1	

VI-74

ATTACHMENT F
COMPACTION TEST DATA
AASHTO T 180-57

F-1

COMPACTION TEST DATA

AASHO T 180-57

TEST PIT 1 @ A DEPTH OF 8.0 FEET

IN-SITU MOISTURE CONTENT = 24.1%

<u>DRY DENSITY</u> <u>LBS./CU. FT.</u>	<u>MOISTURE CONTENT</u> <u>PERCENT</u>
104.2	7.2
111.8	11.4
113.1	13.0
113.6	14.4
113.4	15.0
111.2	17.3
98.7	24.1
93.8	26.9

TEST PIT 2 @ A DEPTH OF 6.0 FEET

IN-SITU MOISTURE CONTENT = 16.3%

<u>DRY DENSITY</u> <u>LBS./CU. FT.</u>	<u>MOISTURE CONTENT</u> <u>PERCENT</u>
107.6	6.0
111.0	8.4
113.7	11.4
114.1	13.1
113.0	15.5
106.9	19.9

COMPACTION TEST DATA (CONT'D.)AASHO T 180-57BORROW AREA

IN-SITU MOISTURE CONTENT - NOT DETERMINED

<u>DRY DENSITY</u> <u>LBS./CU. FT.</u>	<u>MOISTURE CONTENT</u> <u>PERCENT</u>
114.0	9.5
115.2	12.0
115.3	12.8
113.8	15.5
108.4	17.9

ATTACHMENT G

ATTERBERG LIMITS AND GRAIN SIZE ANALYSES

ATTERBERG LIMITS

<u>LOCATION</u>	<u>DEPTH FEET</u>	<u>LIQUID LIMIT PERCENT</u>	<u>PLASTIC LIMIT PERCENT</u>	<u>PLASTICITY INDEX</u>
Boring 1	1.5	47	41	6
Boring 2	4.5	42	34	8
Boring 2	7.0	44	36	8
Boring 3	6.5	41	38	3
Boring 3	13.5	37	32	5
Boring 3	18.5	42	34	8
Test Pit 1	8.0	43	35	8
Test Pit 2	6.0	36	35	1
Borrow Area	---	34	32	2

GRAIN SIZE ANALYSES

<u>LOCATION</u>		Boring 2	Boring 3
<u>DEPTH - FEET</u>		4.5	13.5
<u>U.S. STANDARD SIEVE SIZE</u>	<u>SIEVE OPENING MM</u>	<u>PERCENT FINER BY WEIGHT</u>	<u>PERCENT FINER BY WEIGHT</u>
No. 10	2.00	100.0	100.0
No. 16	1.19	96.4	96.9
No. 20	0.841	94.6	95.1
No. 40	0.420	89.5	89.6
No. 50	0.297	86.8	86.1
No. 60	0.250	85.7	84.9
No. 100	0.149	81.0	80.2
No. 140	0.105	77.1	77.1
No. 200	0.074	73.6	74.4
No. 325	0.044	67.2	70.4
----	0.020	34.9	30.7
----	0.005	9.1	5.1
----	0.001	0.1	1.2

GRAIN SIZE ANALYSES

<u>LOCATION</u>		<u>Test Pit 1</u>	<u>Test Pit 2</u>	<u>Borrow Area</u>
<u>DEPTH - FEET</u>		8.0	6.0	-----
<u>U.S. STANDARD SIEVE SIZE</u>	<u>SIEVE OPENING MM</u>	<u>PERCENT FINER BY WEIGHT</u>	<u>PERCENT FINER BY WEIGHT</u>	<u>PERCENT FINER BY WEIGHT</u>
No. 10	2.00	100.0	100.0	100.0
No. 16	1.19	97.2	96.3	97.2
No. 20	0.841	95.0	92.4	93.8
No. 40	0.420	90.0	82.7	81.5
No. 50	0.297	87.1	78.1	75.2
No. 60	0.250	85.7	76.1	72.7
No. 100	0.149	79.8	69.9	65.3
No. 140	0.105	75.0	67.6	61.1
No. 200	0.074	71.2	64.3	58.7
No. 325	0.044	65.9	57.1	50.7
-----	0.020	38.2	24.6	18.2
-----	0.005	11.3	2.3	1.1
-----	0.001	0.2	0.1	0.0

APPENDIX VII

STABILITY ANALYSIS

REPORT - SOILS ENGINEERING SERVICES

**PROPOSED DAM - LAKE OF THE WOODS RESERVOIR
ORANGE COUNTY, VIRGINIA**

FOR

BAUER ENGINEERING, INC.

5651-002-07



DAMES & MOORE
CONSULTANTS IN APPLIED EARTH SCIENCES
SOIL MECHANICS • ENGINEERING GEOLGY • GEOPHYSICS

ATLANTA	NEW YORK
CHICAGO	PORTLAND
HONOLULU	SALT LAKE CITY
HOUSTON	SAN FRANCISCO
LOS ANGELES	SEATTLE
WASH. D.C.	SAINT JOHN N.B. CANADA
MADRID, SPAIN	TORONTO, CANADA

309 WEST JACKSON BOULEVARD • CHICAGO, ILLINOIS 60606 • 312-922-1772

PARTNERS: JAMES B. THOMPSON • GEORGE D. LEAL

ASSOCIATE: WILLIAM G. PARATORE

January 31, 1967

Bauer Engineering, Inc.
20 North Wacker Drive
Chicago, Illinois 60606

Attention: Mr. William J. Bauer

Gentlemen:

i Report - Soils Engineering Services
Proposed Dam - Lake of the Woods Reservoir
Orange County, Virginia
For Bauer Engineering, Inc.

This letter presents the results of our Soils Engineering Services performed in connection with the Proposed Dam - Lake of the Woods Reservoir to be constructed in Orange County, Virginia.

The scope of our Soils Engineering Services was planned in collaboration with Messrs. William J. Bauer and Robert L. Hall of Bauer Engineering, Inc. Soil strength parameters of proposed fill soils were provided to Bauer Engineering, Inc. on January 11, 1967. The results of our stability analyses were provided on January 12, 1967. An estimated coefficient of permeability equal to 0.2 feet per year for Material II compacted to 90 percent of the maximum dry density as determined in accordance with the AASHO T 180-57 Method of Compaction, was provided on January 23, 1967.

VII-1

The scope of our soils engineering services was as follows:

- 1 - The performance of laboratory tests to determine the strength characteristics of the remoulded compacted fill soils to be used to construct the Proposed Dam. The compacted fill soils were evaluated at the following density criteria: (a) 90 percent of the maximum dry density as determined in accordance with AASHO T 180-57 Method of Compaction, (b) 95 percent of the maximum dry density as determined in accordance with the ASTM D 698 Method of Compaction, and (c) 90 percent of the maximum dry density as determined in accordance with ASTM D 698 Method of Compaction. The laboratory strength tests consisted of triaxial tests and direct shear tests.
- 2 - Engineering analyses to evaluate the stability of two proposed dam embankments. One dam embankment is to consist entirely of soil compacted to 90 percent of the maximum dry density as determined in accordance with the AASHO T 180-57 Method of Compaction. The other embankment, as proposed by the Contractor, is to consist of a core approximately 50 feet wide, located near the center of the dam, compacted to 95 percent of the maximum dry density as determined in accordance with ASTM D 698 Method of Compaction. The soil to be placed on each side of the core will be compacted to 90 percent of the maximum dry density as determined in accordance with ASTM D 698 Method of Compaction. Both proposed embankments will have an upstream slope of one vertical to four horizontal and a downstream slope of one vertical to three horizontal.

3 - Additional engineering analyses, if required, for the proposed embankment consisting entirely of soil compacted to 90 percent of the maximum dry density as determined in accordance with AASHO T 180-57 Method of Compaction will be performed to determine the optimum design cross section with respect to slope stability and economy of known materials.

INTRODUCTION:

Representative bulk samples of the proposed borrow materials were obtained by our field engineer on December 20, 1966 from test pits excavated in the Proposed Borrow Pit. Test pit locations were established by Bauer Engineering, Inc.

The soil profile in the Proposed Borrow Pit area is similar to the soil profiles presented in our "Report of Soil Exploration, Proposed Dam - Lake of the Woods Reservoir, Orange County, Virginia for Bauer Engineering, Inc." dated October 21, 1966. The soils are residual in origin and were derived from the weathering of gneisses, schists, and other metamorphic rocks. The Proposed Borrow Pit is blanketed by topsoil and the topsoil is underlain by reddish brown silty clays, clayey silts, and silts with sand and clay which in turn are underlain by brown and gray sandy silts and sandy clays.

From visual inspection of the test pits and inspection of bulk samples in the laboratory, it was determined that the soils in the Proposed Borrow Pit consist essentially of three soil types. The three soil types and the coordinates of the respective test pits and depths at which bulk samples of the three soil types were obtained are as follows:

SOIL TYPE	COORDINATE OF TEST PITS	GROUND SURFACE		DEPTH OF BULK SAMPLE (FEET)
		ELEVATION AT TEST PIT (FEET)		
MATERIAL I	Reddish Brown Clayey Silt	K + 60 13 + 20	292	6
MATERIAL II	Reddish Brown Silt with Sand and Clay	K + 60 13 + 20	292	11.5
MATERIAL III	Brown Sandy Clay	L + 30 15 + 80	307	8

LABORATORY TESTS:

Two compaction tests were performed on each of the three soil types. One compaction test was performed in accordance with the AASHO T 180-57 Method of Compaction, and the second compaction test was performed in accordance with the ASTM D 698 Method of Compaction.

Remoulded samples of each soil type, compacted to 90 percent of the maximum dry density as determined in accordance with the AASHO T 180-57 Method of Compaction and to 95 percent and 90 percent of the maximum dry density as determined in accordance with the ASTM D 698 Method of Compaction, were then subjected to strength tests. The strength tests consisted of direct shear tests and undrained triaxial tests. The strength tests were performed on remoulded samples having a moisture content approximately equal to the anticipated fill moisture content at the time of placement and compaction of the fill and on saturated or near-saturated remoulded samples.

The Atterberg limits were determined for Materials I and II. Specific gravity determinations were performed on all three soil types and a grain size analysis was performed on Material II.

Laboratory test results are presented on Plates 1 and 2.

STABILITY ANALYSES:

Stability analyses were performed on the two proposed dam embankments. For each of the proposed dam embankments the stabilities of both upstream and downstream slopes were evaluated. The strength parameters used in the stability analyses were those of Material II. It is considered that the Proposed Dam will consist primarily of Material I and Material II. Material II has the lowest strength parameters of the three predominant soil types encountered in the Proposed Borrow Pit. It was judged advisable by Dames & Moore and Bauer Engineering, Inc. to use the lower of the strength parameters in the stability analyses. The phreatic line in both of the proposed dam embankments was assumed, for purposes of stability analyses, to be a straight line from the water level on the upstream slope to the filter drain. This assumption is based on a filter drain that is performing adequately. The soil on both the upstream and downstream slopes was assumed to be saturated. The proposed dam site is in a seismically active area and an earthquake loading equal to five percent of the acceleration due to gravity was utilized in the stability analyses.

The results of the stability analyses on the proposed homogeneous dam embankment consisting entirely of soil compacted to 90 percent of the maximum dry density as determined in accordance with the AASHO T 180-57 Method of Compaction are shown on Plate 3. The parameters of the foundation soil immediately underlying the dam embankment were assumed.

The results of the stability analyses on the proposed alternate dam embankment, as proposed by the Contractor, are shown on Plate 4.

This embankment contains a core approximately 50 feet wide compacted to 95 percent of the maximum dry density as determined in accordance with the ASTM D 698 Method of Compaction to 90 percent of the maximum dry density as determined in accordance with the ASTM D 698 Method of Compaction. Material II when compacted to 90 percent of the ASTM D 698 maximum dry density has a cohesion equal to zero and an angle of internal friction which is less than the slope angles of the embankment. Thus the side slopes of the embankment, as proposed by the Contractor, are unstable.

--oo--

The following Plates are attached and complete this report:

- Plate 1 - Summary of Laboratory Test Data
- Plate 2 - Gradation Curve of Material II
- Plate 3 - Results of Stability Analyses of Homogeneous Dam Embankment
- Plate 4 - Results of Stability Analyses of Proposed Alternate Dam Embankment.

Yours very truly,

DAMES & MOORE

William G. Paratore
William G. Paratore

James B. Thompson
James B. Thompson

WGP:JBT:DGS:ac
Ten Copies Submitted


PLATEAU I	972 PCF 6% 31.4 % WATER 1-13 GRAVITY = 2.73	64.7 PCF 6% 31.4 % WATER 1-13 GRAVITY = 2.73	30 - 50	65°	90.6	119	36	400	15
PLATEAU II				78°	75.8	109	35	600	23
PLATEAU III				78°	75.8	114	41	300	11
PLATEAU IV				78°	75.8	102	35	400	22
PLATEAU V				78°	75.8	111	47	200	8
PLATEAU VI				90	82.5	110	34	750	29
PLATEAU VII				90	82.5	115	40	200	20
PLATEAU VIII				90	82.5	105	40	500	24
PLATEAU IX				90	82.5	110	47	100	15
PLATEAU X				78°	75.5	100	41	350	21
PLATEAU XI				78°	75.5	108	51	0	13
PLATEAU XII				90	108.6	127	16	1200	26
PLATEAU XIII				90	108.6	133	21	400	19
PLATEAU XIV				90	104.5	124	19	700	20
PLATEAU XV				90	104.5	129	24	300	19
PLATEAU XVI				92°	99.6	119	19	800	20
PLATEAU XVII				92°	99.6	126	27	200	19


I. REACTIONS TO SOIL AT ANTICIPATED PLANT MOISTURE CONTENT

• 994 ASTH D93

SUMMARY OF LABORATORY TEST DATA

GRADATION CURVE FOR MATERIAL II






6-IIA

RESULTS OF STABILITY ANALYSES OF HOMOGENEOUS DAM FOUNDATION

PLATE 2



PЛАТЕ 4

**RESULTS OF STABILITY ANALYSES OF PROPOSED NUTCRACKER DAM A
EMBANKMENT**

BAUER
ENGINEERING
INC.
CHICAGO

SUBJECT Earth Dams: Stability

PROJECT Design Standards

COMPUTED Bauer CHECKED

FILE NO.

DATE 4-5-67 PAGE 1 OF 1



The purpose of this standard is to pull together the materials developed over a period of time regarding the design of earth dams as far as the stability of the slopes is concerned. Until superseded by another standard covering the same subject, this procedure will be used in the analysis of all earth dams which fall within the scope of this procedure.

Scope

under 100' in height

This standard procedure covers dams with the following characteristics:

1. The upstream and downstream slopes are uniform and approximately equal.
2. The foundation material is at least equal in strength to the compacted material comprising the embankment.
3. The strength of the material in shear may be described as a straight-line plot on a diagram as follows:



DEFINITION SKETCH

BAUER ENGINEERING INC. CHICAGO	SUBJECT <u>Earth Dams: Stability</u>	PROJECT <u>Design Standard</u>
	COMPUTED <u>Bauer</u>	CHECKED _____

Locus of Trial Centers

The location of the center of the slip circle of least Factor of Safety may be estimated with the aid of the Locus of Trial Centers shown on the Definition Sketch, which was obtained from Jumikis, Soil Mechanics, page 698. The values of angles BA and BB are estimated with the aid of the following table:

Z	THETA	BA	BB
1.732	60°	about 29°	about 40°
1.000	45°	about 28°	about 38°
0.667	33°41'	about 26°	about 35°
0.500	25°34'	about 25°	about 35°
0.333	18°26'	about 25°	about 35°
0.200	11°19'	about 25°	about 37°

BAUER ENGINEERING INC. CHICAGO	SUBJECT <u>Earth Dams: Stability</u>	PROJECT <u>Design Standard</u>
	COMPUTED <u>Bauer</u> CHECKED _____	FILE NO. <u>4-5-67</u> PAGE <u>3</u> OF <u>10</u> DATE _____

Seismic Factor

The horizontal acceleration is the primary factor to be considered. The ratio of this acceleration to the acceleration of gravity is the Seismic Factor, or SEIF in the program. Commonly, $SEIF = 0.10$, and this value shall be used unless a particular earthquake history indicates a greater or lesser value to be appropriate.

The water waves set up by an earthquake are generally small. For example, the wave height resulting from $SEIF = 0.1$ with a period of 0.25 seconds is on the order of 0.1 to 0.2 foot for a dam 50 feet high. This effect is usually ignored in earth dam stability computations.

BAUER ENGINEERING INC. CHICAGO	SUBJECT <u>Earth Dams: Stability</u>	PROJECT <u>Design Standard</u>
	COMPUTED <u>Bauer</u>	CHECKED <u></u>

FILE NO.
DATE 4-5-67 PAGE 4 OF _____ PAGES

Assumptions

The following assumptions are made in this procedure for small earth dams:

1. The piezometric gradient of internal pore pressure indicated on the Definition Sketch of page 1 as dh/ds is ignored. This is a substantial stabilizing force which would ordinarily be taken into account in designing higher dams. However, for dams under 100 feet in height, it may be safely ignored in the interests of conservatism and simplified design.
2. No cracks are assumed to exist. The embankment is considered to be homogeneous.
3. There is no problem of rapid drawdown, which is not more than compensated for by ignoring the dh/ds as explained in 1. preceding.

Computer Program

The following pages give the steps in the computer program:

BAUER ENGINEERING INC. CHICAGO	SUBJECT Earth Dams: Stability	PROJECT Design Standard
COMPUTED Bauer	CHECKED	FILE NO. 4-5-67 DATE PAGE OF 5

```

101.      PROGRAM NAMESTA
102.      DATA X(20),Y(20),FS(20),XF12(50),YF1(50),YF2(50)
103.      DATA 0,1,F1,Z,TOP1,XD,ZL,RL,SIN,CD,CW,SIN
104.      DATA ATAN(Z)
105.      DATA RA/57.295779
106.      DATA R0/57.295779
107.      DATA 3.1415926-TAN(RA-R)
108.      DATA SIN(TAN(RA))
109.      DATA S1*SIN(RA)/SIN(WGO)
110.      DATA X0=S1*COS(TAN(RA))-S2*COS(WGO)
111.      DATA Y0=S1*SIN(TAN(RA))+S2*SIN(WGO)
112.      DATA PLM=(IF1+Y0)/(X0-4.5*IF1)
113.      DATA ALB=Y0+X0*(Y0+IF1)/(4.5*IF1)-X0
114.      DATA XLIN=IF1/2+TOPW
115.      DATA RRAD 0,N,IM,NFLX
116.      DATA RFAN 0,N,SFIF
117.      DATA AI=1
118.      DATA M1=II+1
119.      DATA IF1=IW-0.767*SFIF*SFIF*IF1
120.      PRINT 4,IEM, TOPW,Z
121.      PRINT 5,GMMN,CD,SIN
122.      PRINT 6,X0,Y0
123.      PRINT 5,GMMW,CW,SIN
124.      PRINT 11
125.      PRINT 7,IM,SFIF
126.      PRINT 8,X0,Y0
127.      PRINT 1
128.      NO 28 I=1,H
129.      AI=1
130.      X(I)=X0-AI*NFLX
131.      Y(I)=Y0-AI*DF(X*PLM)
132.      R=X(I)**2+Y(I)**2
133.      R=SQRT(R)
134.      TF1P1=X(I)/R
135.      TF1P2=ABS(TF1P1)
136.      IF(TF1P1)>0,30,30
137.      20 ANG1=ATAN(TF1P2)
138.      GO TO 40
139.      30 ANG1=(ATAN(TF1P2))
140.      40 ALPM=ARCS((Y(I)-IF1)/R)-ANG1
141.      ANGL=PI*ALPM/R
142.      DIST=PI*ALPM/2
143.      ANGL=PI*ALPM/R
144.      XF12(1)=0,
145.      YF1(1)=0,
146.      YF2(1)=0,
147.      PH1=PI

```

BAUER ENGINEERING INC. CHICAGO	SUBJECT Earth Dams: Stability	PROJECT Design Standard
		FILE NO. 4-5-67
	COMPUTED Bauer	CHECKED
		DATE 4-5-67 PAGE 6 PAGE

```

1149.      SUNIT=0.
1150.      SUMT=0.
1151.      SUMD=0.
1152.      SUMT=0.
1153.      DO 26 J=2,11
1154.      P111=P111+0FLANG
1155.      XF12(J)=R*S11*(P111)+X(1)
1156.      YF1(1,J)=Y(1)-R*COS(P111)
1157.      YF2(J)=YE2(J-1)+(XF12(J)-XF12(J-1))*Z
1158.      X1=IM/Z
1159.      XX=(XF12(J)+XE12(J-1))/2.
1160.      YY=(YX-X1)/(X0-X1)
1161.      IMJ=IM*(1.-YY*YY)
1162.      IF (XX-X1)45,45,46
1163.      45 IMJ=IW
1164.      46 IF(YF2(J)-IE11)60,60,50
1165.      50 IF(XF12(J,J)-XL11)52,52,54
1166.      52 YF2(J)=IE11
1167.      60 TO 60
1168.      54 YF2(J)=IE11-(XF12(J,J)-XL11))*Z
1169.      60 YY=(YF1(J-1)+YE1(J))/2.
1170.      YY2=(YF2(J-1)+YE2(J))/2.
1171.      YDRY=YY2-IMJ
1172.      YMFT=IMJ-YY1
1173.      IF(YMFT)70,70,80
1174.      70 YMFT=0.
1175.      YDRY=YY2-YY1
1176.      YB=Y(1)-YY1
1177.      YD=Y(1)-YY1-YDRY/2.
1178.      80 TO 199
1179.      80 IF(YDRY)90,90,140
1180.      90 YDRY=0.
1181.      YURT=YY2-YY1
1182.      YW=Y(1)-YY2+YURT/2.
1183.      YD=Y(1)-YY2
1184.      90 TO 199
1185.      140 YU=Y(1)-YY1-YMFT/2.
1186.      YDRY=YY2-IMJ
1187.      YURT=YY1-YY2+YDRY/2.
1188.      YD=Y(1)-YY2+YURT/2.

```

BAUER ENGINEERING INC. CHICAGO	SUBJECT Earth Dams: Stability	PROJECT Design Standard
COMPUTED Bauer	CHECKED	FILE NO. DATE 4-5-67 PAGE 7 OF 8

```

189. =
190. =
191. =
192. =
193. =
194. =
195. =
196. =
197. =
198. =
199. = WF1TW=(XF12(J)-XF12(J-1))*Y1FTGAM
WF1TD=(XF12(J)-XF12(J-1))*Y0RTGAM
PHI1=PHI-ANG1
PRFS=(WF1TD+WF1TW)*(COS(PHI1)-SIN(PHI1))
PRFS=PRFS/DIST
IF(PRFS)170,175,175
170 PRES=0.
175 IF(Y1-IWJ)180,180,185
180 SUMT=SURF+(CY+PRFS*SIN)*DIST*R
185 SUMT=SUMT+(CD+PRFS*SIN)*DIST*R
190 SURW=SURW+((WF1TD+WF1TW)*((XF12(J)+XF12(J-1))/2.-Y(J)))
XX=IWJ-IWF
OSUMD=31.2*XX*XX*(Y(J)-IWJ+2.*XX/3.)*31.2*XX*WTF*(Y(J)-IWJ+2.*WTF/3.)
4)
SUMH=SURW+WF1TW*Y1*SCIF+WF1TD*YD*SF1F
4
26 CONTINUE
27 FS(1)=SUMT/(SUMD+SUMH+SUMW)
28 PRINT 2,X(1),Y(1),SUMT,SUMW,SUMD,FS(1)
10FORMAT(//,90H X SUMT Y FS ) SUMT
4 SUMD SUMH FS )
2 FORMAT(2F10.2,4F15.0,r10.3)
202. =
203. =
204. =
205. =
206. =
207. =
208. =
209. =
210. =
211. =
212. =
213. =
214. =
215. =
216. =
217. =
40FORMAT(//,10X,20M1FT OF THE DAM = F11.1,3H FT/,10X,23H TOP WID
1TH OF THE DAM = ,F8.0,3H FT/,10X,19H SLOPE OF THE DAM = ,F4.2,6H
4 TO 1.)
8 FORMAT(/,10X,9INCH SOIL, )
50FORMAT(10X,26INCH HEIGHT OF THE SOIL = F11.2,9H INCH/INCH /,10
1X,23INCH THICKNESS OF THE SOIL = F14.2,9H INCH/INCH /,10X,23INCH R. OF
4 INTERFACIAL FRICTION = ,F10.4)
9 FORMAT(10X,9INCH SOIL, )
60FORMAT(/,10X,7INCHORD DIAMETER OF THE RUPTURE SURFACE FOR
4R PUFF COHESIVE SOIL, /,10X,4INCH = ,F12.2,10X,4INCH = ,F12.2)
70FORMAT(10X,14INCH WATER LEVEL = ,F13.2,3H FT /,10X,17INCH ISKINIC FACTOR
4= ,F10.2)
11 FORMAT()
END

```

EXAMPLE FROM LAKE OF THE WOODS - Job # 6692

BAUER ENGINEERING INC. CHICAGO	SUBJECT Earth Dams: Stability	PROJECT Design Standard
COMPUTED Bauer	CHECKED	FILE NO. DATE 4-5-67 PAGE 8

HEIGHT OF THE DAM = 50.0 FT
 TOP WIDTH OF THE DAM = 15. FT
 SLOPE OF THE DAM = 0.33 TO 1.

DRY SOIL:
 UNIT WEIGHT OF THE SOIL = 115.00 LBS/CUFT
 COHESION OF THE SOIL = 250.00 LBS/SQFT
 COEF. OF INTERNAL FRICTION = 0.4245
 WET SOIL:
 UNIT WEIGHT OF THE SOIL = 52.60 LBS/CUFT
 COHESION OF THE SOIL = 250.00 LBS/SQFT
 COEF. OF INTERNAL FRICTION = 0.4245
 WATER LEVEL = 42.50 FT
 SEISMIC FACTOR = 0.05

COORDINATE OF THE CENTER OF THE RUPTURE SURFACE FOR PUKE COHESIVE SOIL;
 X = 94.13
 Y = 89.12


VII-18

95% AASHO modified
 Using the overlap value
 upstream: 1 : 3.
 (see page 512 — 14
 for selected
 Design Values "A")

X	Y	SUMT	SUMW	FS
88.13	95.50	36900281.	17815673.	2544168.
82.13	101.88	32594329.	15679281.	2286410.
76.13	108.26	29299423.	14824357.	11147.
70.13	114.63	26095905.	12957792.	11958.
64.13	121.01	23465008.	11809912.	12769.
58.13	127.39	21261411.	10808177.	13579.
52.13	133.77	19244232.	9599124.	14390.
46.13	140.15	17505402.	8521606.	15201.
40.13	146.53	15927407.	7344906.	16012.
34.13	152.90	14564660.	6303823.	16823.

STATEMENT ENCOUNTERED DURING EXECUTION

BAUER ENGINEERING INC. CHICAGO	SUBJECT Earth Dams: Stability	PROJECT Design Standard
COMPUTED Bauer	CHECKED	FILE NO. DATE 4-5-67 PAGE 9 OF 10



Segment →	1	2	3	4	5	6	7	8
ΔX	-38	-18	2	22	42	62	82	102
ΔY	127	126	123	119	114	107	97	87
ΔP/ΔN	-28/.95	-.14/1.00	0/1.00	.19/1.00	.34/.93	.50/.86	.64/.76	.76/.67
W	15.7"	25.0	33.0	39.0	41.5	40.0	40.7	36.0
N	15.0	25.0	33.0	39.0	39.0	34.4	31.0	23.0
P	-4.3	-3.5	0	7.0	14.0	20.0	26.5	27.5
L	30	20	20	20	21	23	26	30
250L = C	7.5	5.0	5.0	5.0	5.25	5.75	6.50	7.50
0.4245N = T _c	6.4	10.6	14.0	16.5	16.5	14.60	13.20	9.70
C + T _c = T	13.9	15.6	19.0	21.5	21.75	20.35	19.70	17.50

$$\Sigma P = -7.8 + 95 = 87.2$$

$$\Sigma T_c = 149.1$$

$$F.S. = \frac{149.1 \times 140.1}{87.2 \times 125} = 1.92$$

VII-19

Compare 1.957 in machine comp.
with seismic factor = 0, p. 11

BAUER ENGINEERING INC. CHICAGO	SUBJECT Earth Dams: Stability	PROJECT Design Standard
COMPUTED Bauer	CHECKED	FILE NO. 4-5-67 DATE PAGE 10 PAGE

Seismic Factor - approximate analysis using preceding sample computation.

Note that the sum of W for the 8 slices is equal to 270.9 kips. Assuming a seismic horizontal acceleration of 0.05 g, the equivalent horizontal force = $0.05 \times 270.9 = 13.5^{\prime\prime}$. The center of gravity of the 8 slices is by inspection at $Y = 12$, so arm = $127.39 - 12 = 115'$. The moment produced is then the equivalent of $\frac{13.5 \times 115}{140.1} = 11.1^{\prime\prime}$ placed

at the perimeter of the circle. The Factor of Safety = F.S., resulting from the addition of the seismic effect is:

$$F.S. = \frac{(149.1 - 11.1) 140.1}{87.2 \times 125} = 1.77$$

Compare 1.726 from machine computation including seismic drawdown effect.

Seismic Drawdown

Line	α/g Seismic Factor	T Vibration Period	Δx Horizontal Movement	HEM Embankment Height	ΔHW Seismic Drawdown
1	0.10	0.25 sec.	0.012'	50'	0.13'
2	0.05	0.25 sec.	0.006'	50'	0.065'

$$\text{Force} = 25' \times .065 \times .0625 = 0.1^{\prime\prime} - \text{neglect.}$$

AD-A073 631

BAKER (MICHAEL) JR INC BEAVER PA
NATIONAL DAM SAFETY PROGRAM. LAKE OF THE WOODS, INVENTORY NUMBER--ETC(U)
MAR 79 M BAKER


F/G 13/2

DACW65-78-D-0016


NL

UNCLASSIFIED

3 OF 3
AD
AD 73631



END
DATE
FILED
10-19
DDC



EXAMPLE FROM LAKE OF THE WOODS.

JOB #6692

HEIGHT OF THE DAM = 50.0 FT
TOP WIDTH OF TIE DAM = 15. FT
SLOPE OF THE DAM = 0.33 TO 1.

95% AASHTO modified
using extrapolated values
Upstream 1:3

DRY SOIL;
UNIT WEIGHT OF THE SOIL = 115.00 LBS/CUFT
COHESION OF THE SOIL = 250.00 LBS/SQFT
COEF. OF INTERNAL FRICTION = 0.4245
WET SOIL;
UNIT WEIGHT OF THE SOIL = 52.60 LBS/CUFT
COHESION OF THE SOIL = 250.00 LBS/SQFT
COEF. OF INTERNAL FRICTION = 0.4245

WATER LEVEL = 42.50 FT
SEISMIC FACTOR = 0.

COORDINATE OF THE CENTER OF THE RUPTURE SURFACE FOR PURE COHESIVE SOIL;
X = 94.13
Y = 89.12

X	Y	SUMT	SUMD	SUMH	FS
88.13	95.50	37699266.	18590618.	0.0000000000	2.028
82.13	101.88	33200767.	16173505.	0.0000000000	2.053
76.13	108.26	29848563.	15300947.	0.0000000000	1.951
70.13	114.64	26635390.	135553688.	0.0000000000	1.965
64.13	121.01	23888076.	12189094.	0.0000000000	1.960
58.13	127.39	21599294.	11039205.	0.0000000000	1.957
52.13	133.77	19510907.	9729184.	0.0000000000	2.005
46.13	140.15	17719382.	8587697.	0.0000000000	2.063
40.13	146.53	16099470.	7375119.	0.0000000000	2.183
34.13	152.91	14704565.	6313731.	0.0000000000	2.329

BAUER
ENGINEERING
INC.
CHICAGO

SUBJECT Earth Dams; Stability

COMPUTED Bauer CHECKED


PROJECT Design Standard

FILE NO.

DATE 4-5-67 PAGE 12 OF _____ PAGES

EXAMPLE FROM LAKE-OF-THE-WOODS - JOB #6692
Stability computation of earth-dam stability by
method of slices.

LEGEND		
	SOIL TYPE	% COMP. AASHO
•	I	90
○	I	83
◐	I	78
■	II	90
□	II	82
▢	II	78
△	III	90
△	III	83
▲	II	82



BAUER
ENGINEERING
INC.
CHICAGO

SUBJECT Earth Dams: Stability



PROJECT Design Standard

COMPUTED Bauer CHECKED

FILE NO.


DATE 4-5-67 PAGE 13 OF _____ PAGES

EXAMPLE FROM LAKE-OF-THE-WOODS, JOB # 6692



BAUER ENGINEERING INC. CHICAGO	SUBJECT Earth Dams; Stability	PROJECT Design Standard
COMPUTED Bauer	CHECKED	FILE NO. 4-5-67 PAGE 14 OF _____ PAGES

EXAMPLE FROM LITTLE-OF-THE-WOODS, JOB #6692



% AASHTO compaction

#	Item	% AASHTO	Soil Type	Molst earth above line of saturation	Saturated earth below line of sat.
1	Unit weight	95	II	115 16s./cu.ft	52.6 16s./cu.ft
2	Cohesion	95	II	850 16s./sq.in.	250 16s./sq.in.
3	Tan ϕ	95	II	0.625	0.425

APPENDIX VIII

REFERENCES

REFERENCES

1. Bureau of Reclamation, U.S. Department of the Interior, Design of Small Dams, A Water Resources Technical Publication, Revised Reprint, 1977.
2. Chow, Ven Te, Handbook of Applied Hydrology, McGraw - Hill Book Company, New York, 1964.
3. Chow, Ven Te, Open Channel Hydraulics, McGraw - Hill Book Company, New York, First Edition, 1959.
4. Commonwealth of Virginia, "Geologic Map of Virginia," Department of Construction and Economic Development, and Division of Mineral Resources, 1963.
5. King, Horace Williams and Brater, Ernest F., Handbook of Hydraulics, Fifth Edition, McGraw - Hill Book Company, New York, 1963.
6. Soil Conservation Service, "National Engineering Handbook - Section 4, Hydrology," U.S. Department of Agriculture, 1964.
7. Soil Conservation Service, "National Engineering Handbook - Section 5, Hydraulics," U.S. Department of Agriculture.
8. U.S. Army, Hydrologic Engineering Center, "Flood Hydrograph Package (HEC-1), Dam Safety Investigations, Users Manual," Corps of Engineers, Davis, California, September 1978.
9. U.S. Army, "Inventory of United States Dams," Corps of Engineers, 9 September 1978.
10. U.S. Army, Office of the Chief of Engineers, "Appendix D, Recommended Guidelines for Safety Inspection of Dams," National Program of Inspection of Dams, Volume 1, Corps of Engineers, Washington, D.C., May 1975.
11. U.S. Army, Office of the Chief of Engineers, Engineering Circular EC-1110-2-163 (Draft Engineering Manual), "Spillway and Freeboard Requirements for Dams, Appendix C, Hydrometeorological Criteria and Hyetograph Estimates," (August 1975).
12. U.S. Army, Office of the Chief of Engineers, Engineering Circular EC-1110-2-188, "Engineering and Design, National Program of Inspection of Non-Federal Dams," Corps of Engineers, Washington, D.C., 30 December 1977.

NAME OF DAM: LAKE OF THE WOODS
VIII-1

13. U.S. Army, Office of the Chief of Engineers, Engineer Technical Letter No. ETL 1110-2-234, "Engineering and Design, National Program of Inspection of Non-Federal Dams, Review of Spillway Adequacy," Corps of Engineers, Washington, D.C., 10 May 1978.
14. U.S. Department of Commerce, "Technical Paper No. 40, Rainfall Frequency Atlas of the United States for Durations from 30 Minutes to 24 Hours and Return Periods from 1 to 100 Years," Weather Bureau, Washington, D.C., May 1961.

NAME OF DAM: LAKE OF THE WOODS

VIII-2