

AD-A083 720


KETRON INC WAYNE PA
HAZARDS/FAILURE MODES AND EFFECTS ANALYSIS MK 1 MOD 0 LSO-MUD C--ETC(U)
MAR 80 F SEVCIK, G S FARBER, W S MANN
N68335-78-C-2002


UNCLASSIFIED

1 of 3
AD-A083 720

NAEC-91-7958

NL





MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS 1963-1



12
6,5

LEVEL II

NAVAL AIR ENGINEERING CENTER

REPORT NAEC-91-7958

LAKEHURST, N.J.
08733

ADA 083720

HAZARDS/FAILURE MODES AND EFFECTS ANALYSIS
MK 1 MOD 0 LSO HUD
CONSOLE SYSTEM

Ship Installation Engineering Department
Naval Air Engineering Center
Lakehurst, New Jersey 08733

24 March 1980

Technical Report
Contract No. N68335-78-C-2002

DTIC
SELECTED
S D
APR 29 1980
A

APPROVED FOR PUBLIC RELEASE;
DISTRIBUTION UNLIMITED

Prepared for

Commanding Officer
Naval Air Engineering Center
Lakehurst, New Jersey 08733

DOC FILE COPY

5010-2 (Rev. 10-77)

80 4 28 152


NAEC-91-7958

HAZARDS/FAILURE MODES AND EFFECTS ANALYSIS
MK 1 MOD 0 LSO HUD
CONSOLE SYSTEM

Prepared by:


F. Sevcik,
P.E., C.Eng., Dipl. Ing.

Reviewed by:


John Glenn
91133 Section

Approved by:


F. B. BOICE
Engineering Officer

NOTICE

Reproduction of this document in any form by other than naval activities is not authorized except by special approval of the Secretary of the Navy or the Chief of Naval Operations as appropriate.

The following espionage notice can be disregarded unless this document is plainly marked CONFIDENTIAL or SECRET.

This document contains information affecting the national defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C., Sections 793 and 794. The transmission or the revelation of its contents in any manner to an unauthorized person is prohibited by law.

3/24/80 da



NAVAL AIR ENGINEERING CENTER

REPORT NAEC-91-7958

LAKEHURST, N.J.
08733

HAZARDS/FAILURE MODES AND EFFECTS ANALYSIS

**MK 1 MOD 0 LSO HUD
CONSOLE SYSTEM**

**Ship Installation Engineering Department
Naval Air Engineering Center
Lakehurst, New Jersey 08733**

24 March 1980

**Technical Report
Contract No. N68335-78-C-2002**

**APPROVED FOR PUBLIC RELEASE;
DISTRIBUTION UNLIMITED**

Prepared for

**Commanding Officer
Naval Air Engineering Center
Lakehurst, New Jersey 08733**

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

19 REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER NAEC-91-7958	2. GOVT ACCESSION NO. AD-A083 720	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Hazards/Failure Modes and Effects Analysis MK 1 MOD 0 LSO-HUD Console System.	5. TYPE OF REPORT & PERIOD COVERED Technical, Final <i>regt</i>	
6. AUTHOR(S) 10 Francis Sevcik C. Eng., DIPL. Ing. Gerald S. Farber William S. Mann	7. PERFORMING ORGANIZATION NAME AND ADDRESS Ketron, Inc. 530 E. Swedesford Rd., Executive Mall Bldg #10 Wayne, PA 19087	
8. CONTRACT OR GRANT NUMBER(S) N68335-78-C-2002	9. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS 12 283	
10. CONTROLLING OFFICE NAME AND ADDRESS Naval Air Engineering Center Engineering Dept. (SI) (Code 91) Lakewood, NJ 08733	11. REPORT DATE 24 March 1980	
12. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)	13. NUMBER OF PAGES 286	
14. SECURITY CLASS. (of this report) UNCLASSIFIED	15a. DECLASSIFICATION/DOWNGRADING SCHEDULE	
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited.	17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)	
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Safety Criticality		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) The MK 1 MOD 0 LSO-HUD Console System provides aircraft recovery information to the Landing Signal Officer aboard aircraft carriers. This analysis identifies individual failure modes of the LSO-HUD Console System and assesses hazard level and probability of occurrence of these modes. Design recommendations are included.		

390480


NAEC-91-7958

PREFACE

The work on this report has progressed hand-in-hand with the design effort on the Console System.

This caused an inevitable delay in completing the report, but on the other hand, it proved beneficial in introducing corrective actions, resulting from this Analysis, in parallel with the Design.

The author wishes to acknowledge significant contributions provided by his KETRON, INC. colleagues: Messrs. G. S. Farber and W. S. Mann; the PGI Supervisor, Mr. Nathan Melman; and particularly, Mr. John Glenn, NAEC 91133 Section.



NAEC-91-7958

This page intentionally left blank

NAEC-91-7958

TABLE OF CONTENTS

<u>SECTION</u>	<u>SUBJECT</u>	<u>PAGE</u>
	PREFACE	1
I	INTRODUCTION	5
II	PURPOSE OF THE ANALYSIS	5
III	SYSTEM DESCRIPTION	5
IV	RESULTS AND RECOMMENDATIONS	7
V	SUBSYSTEM CONSIDERATIONS	8
VI	SCOPE AND METHODOLOGY OF ANALYSIS	10
	FIGURE 1: H/FMEA/(SSA) WORK SHEET FORMAT	14
	APPENDIX A: HAZARD/FAILURE MODES AND EFFECTS ANALYSIS (H/FMEA) -- WORK SHEETS	15(A-0)

TABLE: SUBSYSTEM:

UNIT 1	Heads-Up Display Console	17(A-1)
UNIT 2	Auxiliary Electronics Box	130(A-114)
UNIT 3A1	Retractable Pedestal Assembly	138(A-122)
UNIT 3A2	Hydraulic Power Package	149(A-133)
UNIT 3A3	Control Panel Assembly	163(A-147)
UNIT 3A4	Central Junction Box Assembly	178(A-162)
UNIT 3A5	Transformer Enclosure	187(A-171)
UNIT 3A6	Limit Switch Junction Box Assembly	188(A-172)
UNIT 3A7	Pendant Switch Assembly	189(A-173)
UNIT 3A8	Fuse Box Assembly	191(A-175)
UNIT 4A1	Signal Junction Box	192(A-176)
UNIT 4A2	Synchro Junction Box	212(A-196)
UNIT 4A3	MOVLAS-HUD Interface Electronics Box	233(A-217)
UNIT 4A4	Test Simulator Interface Box	236(A-220)
CABLES	Interconnecting Cables	238(A-222)
UNIT 5	Test Simulator Assembly	246(A-230)

APPENDIX B: H/FMEA RECOMMENDATIONS - SUMMARY

NAEC-91-7958

This page intentionally left blank

I. INTRODUCTION

This report presents the results of the Hazards/Failure Modes and Effects Analysis (H/FMEA) for the NAVAIRENGCEN designed MK 1 MOD 0 LSO Heads-Up Display (HUD) Console System.

II. PURPOSE OF THE ANALYSIS

A. The analysis of the MK 1 MOD 0 LSO HUD Console System was performed primarily to disclose potentially critical and catastrophic safety-related functional failure modes of components and sub-assemblies comprising the System.

B. Efforts were directed toward identifying single-point failure modes that could result in:

1. personnel hazards leading to injury or death; and
2. loss of equipment and mission capability.

C. A major objective of the analysis was to provide design improvement recommendations to preclude or circumvent identified failure possibilities, so that the resulting hazard risks would either be eliminated or greatly reduced.

D. The scope and methodology of the H/FMEA are discussed in detail in Section VI of this report.

III. SYSTEM DESCRIPTION

A. The LSO HUD Console System is located at the LSO's (Landing Signal Officer) Work Station on the aircraft carrier.

B. The mission of the LSO Work Station Facility is to serve as a focal point for recovery information display and communications required for flight path guidance control coordination between the LSO and pilot of the landing aircraft. The MK 1 MOD 0 LSO HUD Console System has been developed as part of an effort to increase the accessibility and visibility of information displays and communications facilities in the LSO Work Station to permit more rapid perception and response by the LSO to flight path deviations under all weather conditions to improve the safety of recovery operations.

NAEC-91-7958

C. The LSO HUD Console System consists of a display subsystem and a hydraulic lifting unit subsystem.

1. THE DISPLAY SUBSYSTEM receives data signals from various existing shipboard systems for processing and display in the LSO HUD console. Calibration, testing, and troubleshooting of display circuits is facilitated with a piece of portable special purpose test equipment. Those systems providing inputs to the HUD console include:

- a. SPN-42 Radar (automatic carrier landing system)
- b. SPN-44 Radar
- c. ILARTS (Integrated Launch and Recovery Television Surveillance) or PLAT (Pilot Landing Aid Television) system
- d. FLOLS (Fresnel Lens Optical Landing System)/Arresting gear cross-check system
- e. Landing area status system
- f. Ship's wind measuring system
- g. Ship's 21MC intercom system
- h. MOVLAS (Manually Operated Visual Landing Aid System) MK 1, MOD 2
- i. FLOLS MK 6 MOD 3 or MK 6 MOD 2 with Trim/Harmonization computer
- j. FLOLS Wave-Off subsystem

2. THE HYDRAULIC LIFTING UNIT SUBSYSTEM provides a means for raising the HUD console to an adjustable height to accommodate viewing by an LSO standing on the LSO Platform. It also provides for lowering the HUD console to an unobstructing level below the flight deck into a storage enclosure. Raising and lowering control is accomplished within the LSO work station, and control circuit interlocks guard against retracting the console when it is misaligned with its storage enclosure and raising the console when the storage enclosure lid is down.

D. MK1 MOD 0 LSO HUD Console System components (Units 1 through 5) are identified in the table of contents of this report (page 3) and individually described in the work sheets in Appendix A.

E. The LSO HUD console will be complemented in an improved LSO Work Station with side mounted LSO and assistant LSO communications attachments, an LSO "Base console", and provisions to hydraulically operate the LSO platform windscreen from a central control using the LSO HUD Console System Hydraulic power package. The communications attachments to the HUD console and the base console are the result of a repackaging of existing communications and display facilities in the LSO Work Station to eliminate redundant displays and provide for more accessible communications facilities with more efficient utilization of space.

IV. RESULTS AND RECOMMENDATIONS

A. RESULTS

The tabulated determinations of the H/FMEA of the HUD Console System are presented in Appendix A of this report.

The evaluation of the subsystems is included in Section V of this report.

Basically, the System was found well designed, with appropriately used redundancies and fail safe principles.

The few possible hazards found were immediately brought to the attention of the Program Management (NAEC), which provided the needed corrective actions.

B. RECOMMENDATIONS

Design improvement recommendations, resulting from the analysis, are presented in Appendix B of this report.

Each recommendation is numbered related to the H/FMEA table and item.

In the matrix, there are indications whether the recommended improvement is for:

- a -- General Reliability, Simplification, Design Improvement
- b -- Avoiding, Eliminating & Reducing Potential Hazards
- c -- Controlling & Minimizing Potential Hazards
- d -- Incorporation of Fail-Safe Principles

There is also an indication, whether the respective recommended design improvement should be used for:

- e -- Existing Design
- f -- Future Design

NAEC-91-7958

V. SUBSYSTEM CONSIDERATIONS

Analysis of this System's components and functions suggests that even though the possibility of failure modes of critical or catastrophic nature (category II or I) does exist, the corresponding probabilities are reasonably low.

By identifying these particular hazards, the corresponding corrective actions will eliminate them from operating times, or will reduce the probabilities of their occurrences to much lower figures, reducing the risks to acceptable levels.

The review of the categories I and II in each subsystem follows:

UNIT 1: Category I: None found.

- Category II: a) See Nos. 1 and 2 in Appendix B.
b) The loss of Console and HUD control due to discontinuity in the Cable's connector is expected to be corrected in a routine check-out of the System. (See Item No. 18.0 of the Unit 1 work sheets.)

UNIT 2: Category I: None found.

Category II: See Nos. 6, 7, 8 and 9 of Appendix B for the recommended corrective actions.

UNIT 3: Category I: None found.

Category II: See Nos. 11, 18, 19, 26, 28, 30, 31 and 32 for the recommended corrective actions.

UNIT 4: Category I-II: An interesting problem was found in specification, testing and requirements for operation of the Relays 518915-1, that provided a high probability, in fact a certainty, that the Relays would not allow low current signals (below 40 m amp) to pass through.

The Program Management was apprised of the problem as soon as it was discovered, and immediately provided a corrective action: to form two groups of these Relays -- one for the high current uses to be tested with 10 Amp current through the contacts, and one for the low current Signals, to be tested with appropriately low currents.

However, even with a good marking applied to distinguish these two kinds of Relays, there will exist a probability of a human error and, therefore, the corrective actions, as suggested in Appendix B, Nos. 33 and 34, would seem more appropriate.

CABLES: Category I(-II): The Wave-off Signals and the Deck Status warning were found with redundant wiring going through the same Cable (W-0 Signals), or there is no redundancy for the Foul Deck warning.

See Nos. 36 and 38 of Appendix B for recommendations.

UNIT 5: Category I: None found.

Category II: See Nos. 39, 40, 41 and 43 of Appendix B for identification and recommendations.

NAEC-91-7958

VI. SCOPE AND METHODOLOGY OF ANALYSIS

A. SCOPE

The Hazards/Failure Modes and Effects Analysis (H/FMEA) was performed on the MK 1 MOD 0 Heads-Up Display (HUD) Console System in accordance with the Work Statement of the Purchase Order 2288 of Power Generators, Inc., dated 5 June 1978.

The "Unit" Cables, even though not included in the Work Statement, was included by the Analyst because of the logical need for the completeness of the System.

The list of all the Subsystems ("Units") appears in the Table of Contents, page 3, under Appendix A.

The Analysis was performed at the levels of assembly consistent with available design definition and criticality of the various System functions.

The lowest level to which the Analysis was carried out was the component; i.e., Switches, Relays, Valves, etc. Failure modes associated with these elements were identified and related to their effect on the performance of higher assemblies or functions up to and including the System.

B. METHODOLOGY

1. DESCRIPTION OF THE H/FMEA FORMAT

Documentation structure of the H/FMEA is in general accordance with accepted industry standards, namely the Society of Automotive Engineers publication, Design Analysis Procedures for Failure Mode, Effects and Criticality Analysis (SAE ARP 926), and MIL-STD-1629, Procedures for Performing a Failure Mode and Effect Analysis. The FMEA was performed utilizing the System's related drawings and schematics provided by PGI/NAEC.

Reference is made to Figure 1 at the end of this section illustrating the H/FMEA form utilized for compiling the analysis.

The form heading information is used as follows:

- a) The TABLE denotes the major system and subsystem ("Unit") indexes.
- b) NAME presents the major system and subsystem titles.
- c) The system document where the treated components are defined is entered on the DWG. NO./REV. line.
- d) The page and total pages of a given subsystem table is at the upper right of the heading.

NAEC-91-7958

Column 1 numerically codes the component analyzed with respect to the subsystem indexes. The complete component/table item index is, for instance: Unit 1.7.0. for reference use.

Column 2 indicates the system, subsystem and component titles and includes brief descriptions of the functions at each level so the reader may gain insight into the significance of the component analyzed. Sketches, Schematics and other useful information have been entered when of importance or interest.

Column 3 lists the hazardous-functional failure modes of the component being treated and examples of causes where necessary.

Columns 4 through 9 are utilized to describe the effects of each assumed component failure mode upon the personnel, system and mission. These effects were determined based on a detailed analysis of the component functional relation to each system level.

Column 10 entries indicate if the considered failure would be detectable by the operator.

Column 11 classifies failure effects on a scale of I to IV in decreasing severity in accordance with Military Standard 882A, System Safety Program Requirements. A detailed explanation of the classifications is included on the next page. The numerical system of failure criticality codes is intended to quickly highlight for the reader those areas of the analysis where serious problems have been identified.

Column 12 is reserved for the Probability of Occurrence of the identified Failure Mode, in accordance with MIL-STD-882A.

Column 13 presents commentary the analyst may provide in the form of pertinent information which will clarify the results of the particular failure mode considered. These remarks include statements describing inherent compensating provisions of the design, and/or recommended design or procedures improvements.

At the bottom of the form there is the "NOTE", which explains in detail Column 11 ("Hazard Level") and Column 12 ("Hazard Probability") headings.

2. FAILURE/HAZARD CLASSIFICATION CRITERIA

Potential failures were classified relative to their criticality in accordance with the following criteria (per MIL-STD-882A, paragraph 5.4.3.1: Hazard level):

- a) Category I - Catastrophic
 - Will cause death or severe injury to personnel or system loss
- b) Category II - Critical
 - Will cause personnel injury or major system damage, or will require immediate corrective action for personnel or system survival.
- c) Category III - Marginal
 - Can be counteracted or controlled without injury to personnel or major system damage.
- d) Category IV - Negligible
 - Will not result in personnel injury or system damage.

The probabilities of the potential failures-hazards were selected according to the following criteria (per MIL-STD-882A, paragraph 5.4.3.2):

- A -- Frequent
- B -- Reasonably Probable
- C -- Occasional
- D -- Remote
- E -- Extremely Improbable
- F -- Impossible.

NOTE: In classifying the Failure/Hazards, the worst case effects on operating personnel or equipment were considered.

NAEC-91-7958

ESTATE PLANNING FOR THE RETIREMENT OF A COUPLE

DATA AND ANALYSIS

NAME: (Sub-system)
DATE: DD-MM-YYYY

卷之三

三

卷之三

100-100-100

NOTE: Hazard Level I, Column 11, per MIL-STD-883B, para. 5.4.3.1 (I-Catastrophic); II-Critical; III-Marginal; IV-Negligible; Hazard Probability, column 12, per MIL-STD-883B, para. 5.4.3.2 (R-Inpossible); B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Unprobable;

FIGURE 1

NAEC-91-7958

APPENDIX A

HAZARDS/FAILURE MODES AND EFFECTS ANALYSIS

MK 1 MOD 0 LSO HUD CONSOLE SYSTEM

WORK SHEETS

NAEC-91-7958

This page intentionally left blank

TABLE: UNIT 1
NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
DNG. NO./REV.: 620310

(Failure Modes & Effects Analysis - System) Safety Analysis "MK-I(M) n L30-HUD" (Console System)

NACC-91-7958

Page 1 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)			EFFECT ON:	FAILURE - HAZARD	
		PERSONNEL	SYSTEM	MISSION			
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)
INTRODUCTION							
<p>This segment of the System Safety Analysis focuses on the MK-I MOD 0 Landing Signal Officer's (LSO) Heads-Up-Display (HUD).</p> <p>Console and the Auxiliary Electronics Box depicted as (Unit 1 and Unit 2), respectively, in Figure 1.</p> <p>The display system consists of two major parts: A Display Console located at the LSO station, and an Auxiliary Electronics Box located one deck and almost directly below the LSO platform. The information displayed by the Console is obtained from the ship's radars and recovery-status sources.</p>							
<p>The front panel of the Console, Figure 2, contains scales and indicators that display Airspeed, Rate of Descent, R-type (or deck) Motion, Aircraft Type, Wind Direction and Speed, Deck Status, Pilot Landing Aid Telemetry (PLAT), and Automatic Carrier Landing System (ACLS) operating status. In addition, the Console provides a Heads-Up Display (HUD) that shows Rate of Descent, Range, Ramp Motion, and aircraft Glide-Slope position. The HUD information is optically focused to appear at infinity and it can be superimposed on the sky by Console tilt and rotation. This enables the LSO to see distant aircraft and the HUD Display is the same field of view, both are simultaneously in focus. Cross lines in the HUD are glide-slope references lines for showing the position of its electronically generated Aircraft Symbol, but do not function as a "gonsense" reference to use the HUD for visual aircraft tracking.</p> <p>The Display Subsystem takes data signals from various existing shipboard equipment sets for processing and display in the HUD Console. Calibration, testing and troubleshooting of the display circuitry is facilitated with the test simulator that drives the displays and other facilities in the HUD.</p>							
<p>a. SHM-42 Radar (Automatic Carrier Landing System (ACLS))</p> <p>b. SHM-44 Radar</p> <p>c. PLAT (Pilot Landing Aid Telemetry) Station</p> <p>d. PIOLS (Prismal Lens Optical Landing System) MK 6 MOD 2 with Tritium/Ternatron computer.</p> <p>e. Landing area with status subsystems</p> <p>f. Ship's wind measuring system</p> <p>g. Ship's 21MC Intercom system</p> <p>h. MOVLAS (Manually Operated Visual Landing Aid System) MKL, MOD 2</p> <p>i. PIOLS Wave-Off subsystems</p>							

(continuation on page iv)

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.2.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible); Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Occasionally; C-Occasional; D-Rare; E-Extremely Unprobable; F-Impossible)

EFFECTS MODES & FAILURE MODES

NAEC-91-7958

TABLE: UNIT 1

NAME: (Sub-system) HEADS-UP-DISPLAY COMPUTER

620310




FIGURE 1 DISPLAY SYSTEM

NOTE: Hazard Level 1, Column 11, per MIL-STD-882A, para. 5.4.3.1 (1-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability: Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable)

TABLE: UNIT 1
NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
DNC. NO./REV.: 620310

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MKI MOD 0 LSO-MUD CONSOLE SYSTEM

NAEC-91-7958

Page 1.1.1 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)		
			PERSONNEL INJURY	SYSTEM LOSS	MISSION LOSS	DETECTABLE BY OPERATOR?	CLASSIFICATION OF FAULT (LEVEL)	PROBABILITY OF OCCURRENCE	COMMENT	RECOMMENDATION	COMPENSATING PROVISIONS
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)




FIGURE 2
LSO HEADS-UP DISPLAY CONSOLE
DISPLAYS & FACILITIES

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Seasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable;
F-Inexmissible)

FAILURE MODES & EFFECTS ANALYSIS - SYSTEM SAFETY ANALYSIS MK1 MOD 0 LSO-HUD CONSOLE SYSTEM

NAEC-91-7958

METHYL-TRIS(2-PHENYLPHENYL) CONSOLE

THE VENICE CHARTER

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible) Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Inprobable; F-Impossible)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-HUD Console System

TABLE: UNIT 1NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLENAME: NAEC-91-7958Dwg. No./Rev.: 620310Page V of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
			PERSONNEL INJURY	SYSTEM LOSS	MISSION LOSS	DETECTABLE BY OPERATOR?	HAZARD QUANTITY (TEST) & OCCURRENCE PROBABILITY		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)
									(11)
									(12)
									(13)

(13) Automatic Carrier Landing System (ACLS): Lock-On, Mode II or III. White light incandescent characters for port and 0 to 100° Starboard. Mode I is green color.

(14) ACLS Wave-Off: Blue flashing, approx. 100/min.

(15) Wind Angle: White light incandescent characters/0 to 80° port and 0 to 100° Starboard.

(16) Wind Speed: White light incandescent characters for 0 to 99 knots.

(17) Pilot: Pilot Landing Aid television monitor.

(18) MOULAS: Incandescent repeater of the ship's Manually Operated Visual Landing Aid System. Datum bar, green light amber light for "madball" except red light for danger lights.

The measurement capabilities and appearance of the Heads-Up-Display combiner glass are:

- (1) Rate of Descent: 200 to 1500 ft/minute rate of descent. Vertical scale on right of HUD display.
- (2) Ramp Motion: +20 ft and -19 ft of ship's ramp motion plus ship's trim separately. Vertical scale on left of HUD display.
- (3) Glide-Slope & Line-Up Path: Aircraft symbol showing azimuth and altitude relative to the touch-down-point with 30 ft or 10 ft scale factor selection. Azimuth of 240 ft left and right and altitude of +240 ft up and -150 ft down are indicated with the 30 ft scale factor. Azimuth of 90° ft left and right and altitude of +80 ft and -50 ft are indicated with the 10 ft scale factor.
- (4) Range Circle: Appears when range of aircraft is one nautical mile or less from the carrier and disappears as a function of 10 distance from the carrier; as the aircraft approaches the deck, 3/4 circle equals 1/2 mile, etc. 1/2 circle equals 1/2 mi e., 1/3 circle equals 1/4 mi, etc.

NOTE: Hazard Lev.1, Column 11, per MIL-STD-802A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Negligible); Hazard Probability, Column 12, per MIL-STD-802A, para. 5.4.3.2 (A-Frequent; B-Random; C-Occasional; D-Remote; E-Incremately Improbable; F-Inmissible) (e)

FAILURE MODES & EFFECTS ANALYSIS - SYSTEM SAFETY ANALYSIS FOR THE ISO-HUD CONSOLE SYSTEM

TABLE: UNIT 1

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE

Dwg. No./Rev.: 620310

NAEC-91-7958

NAEC-91-7958

Page vi of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)			EFFECT ON: PERSONNEL SYSTEM MISSION	DETECTABILITY BY OPERATOR?	PROBABILITY OF OCCURRENCE (HAZARD LEVEL)	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
		POTENTIAL LOSS	DAMAGE	LIVES				
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)
	A description of the individual subsystems contained within the Heads-Up-Display Console are described on the separate worksheets. The various sub-systems contained in Unit 1 are listed on Table 1. The drawing numbers for the sub-systems contained in Unit 1 are listed on Table 2. Figures 3 to 10 illustrate, by use of block diagrams, the input/output connections between each of the sub-systems, their power supply requirements, and operating controls.							

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable;
 F-Inversible)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MKI MOD 0 LSO-HUD CONSOLE SYSTEM

TABLE: UNIT 1

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE

DMG. NO./REV.: 620310

NAEC-91-7958

Page vii of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD PROBABILITY (HAZARD LEVEL) DETECTABLE LOSS	COMMENTS: RECOMMENDATIONS; COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)					
			PERSONNEL INJURY	SYSTEM LOSS	MISSION LOSS							
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)

TABLE 1. WORKSHEET TABLE OF CONTENTS

ITEM NO.

SUBSYSTEM ELEMENT

- 1.0 Range Indication/Heads-Up-Display (HUD)
 2.0 Rate of Descent (ROD) Indication on Heads-Up-Display (HUD)
 3.0 Ramp Motion/Trim Indication on the Heads-Up-Display (HUD)
 4.0 Glidepath and Line-up Imaging on Heads-Up-Display (HUD)
 5.0 The Heads-up-Display Reticule Scale Projection Lamp Circuitry
 6.0 Console Range Indicator
 7.0 Console Rate of Descent Indicator
 8.0 Console Ramp Motion/Trim Indicator
 9.0 Console Airspeed Indicator
 10.0 Console Deck Status and PILOTS Wave-Off Status Indicator
 11.0 Console Wind Direction Indicator
 12.0 Console Aircraft Designation Indicator
 13.0 Console Aircraft Designation Indicator
 14.0 Console ACLS Status Indicator
 15.0 Console PLAT Centerline Camera Monitor
 16.0 Console MOVLAS Repeater
 17.0 Console Intercommunication System
 18.0 Console Operating Controls
 19.0 Console Obstruction Lamp
 20.0 Console Dehumidification
 21.0 Console DC Power Regulators
 22.0 Console Heads-Up-Display Circuitry
 23.0 Console Back Plate Assembly
 24.0 Heads-Up-Display Combiner and Mirror Assembly

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1. I-Catastrophic; II-Critical; III-Marginal; IV-Negligible
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Occasionally; C-Occasional; D-Rare; E-Extremely Improbable; F-Inpossible)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 LS0-HUD Console System

TABLE: UNIT 1

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE

DMG. NO./REV.: 620310

NAEC-91-7958

NAEC-91-7958

Page viii of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)			EFFECT ON:			FAILURE - HAZARD			COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)		
		PERSONNEL	SYSTEM	MISSION	DETECTABLE BY OPERATORS?	HAZARD OCCURRENCE RATE	PROBABILITY OF OCCURRENCE	HAZARD LEVEL	DETECTABLE BY OPERATORS?	HAZARD OCCURRENCE RATE	PROBABILITY OF OCCURRENCE	HAZARD LEVEL	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)	

TABLE 2. HEADS-UP-DISPLAY CONSOLE

UNIT 1 ASSEMBLIES

DESIGNATION	DESCRIPTION
IA1	PLAT Video Monitor Chassis
IA2	Airspeed Ind. Ass'y
IA3	Deck Status & Scale Ass'y
IA4	Regulator Board Ass'y
IA5	HUD Deflection Amplifier
IA6	ACLS Ind. Ass'y
IA7	Rate of Descent Ind. Ass'y
IA8	PLAT CRT and Deflection Yoke
IA9	Range Indicator Ass'y
IA10	Ramp Motion Ind. Ass'y
IA11	MOV/LAS Ass'y
IA12	Card Cage Ass'y
IA13	Transformer Shield Ass'y
IA14	High Voltage Ass'y
IA15	HUD CRT and Deflection Yoke
IA16	Heater Ass'y
IA17	Control Panel Ass'y
IA18	Card Extender Ass'y
IA19	Rate of Descent Card Ass'y
IA20	Range & Ramp Motion Card Ass'y
IA21	Synchro/Analog Card No. 1 Ass'y
IA22	Synchro/Analog Card No. 2 Ass'y
IA23	Airspeed Card Ass'y
IA24	HUD Display Card Ass'y
IA25	2INC Intercom Ass'y
IA26	Back Plate Ass'y

24 (A-8)

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable;
 F-Inapplicable)

(Failure Modes & Effects Analysis - System) Safety Analysis MKI Mod 0 ISO-HUD Console System
MEC-91-7958

TABLE: UNIT 1
NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
DAG. NO./REV.: 620310

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	EFFECT ON:			FAILURE - HAZARD CLASSIFICATION (HAZARD LEVEL)	PROBABILITY OF OCCURRENCE (%)	COMMENT(S), RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
		PERSONNEL INJURY	SYSTEM DAMAGE LOSS	MISSION LOSS			
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)

25 (A-9)

NAEC-91-7958

FIGURE 3. HEAD UP DISPLAY CIRCUITRY AND PANEL ILLUMINATION CONTROL

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.2 (B-Frequent; C-Occasional; D-Rare; E-Extremely Unprobable;
P-Inapplicable)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1/HOD 01 ISO-HUD CONSOLE SYSTEM

TABLE: UNIT 1

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
DNG. NO./REV.: 620310

NMEC-91-7928

NAEC-91-7958

Page x of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS, ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS				
		POTENTIAL LOSS	DAMAGED LOSS	INJURY LOSS	PERSONNEL	SYSTEM	MISSION	DETECTION BY OPERATOR?	POSSIBILITY OF ACCIDENT	PROBABILITY OF OCCURRENCE		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)

26 (A-10)

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Tolerable)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Unprobable; F-Inapplicable)

FIGURE 4. RANGE INDICATOR

(Failure Modes & Effects Analysis - System) Safety Analysis MIL-MOD-1 ISO-HUD CONSOLE SYSTEM

NAEC-91-7958

TABLE: UNIT 1
 NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
 DNG. NO./REV.: 620310

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)				
		POTENTIAL LOSS	PERSONNEL INJURY	SYSTEM LOSS	DETECTABLE BY OPERATOR?	CATEGORICAL LEVEL OF PROBABILITY OF OCCURRENCE	CLASSIFICATION	COMMENT				
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)

The diagram illustrates the power distribution and signal flow for the Heads-Up-Display Console. Power enters through connector J4 (1A, 175V) and connector J8 (1A, 25V). The 1A, 175V line powers the ROD (1A, 19) and the S12 indicator (1A, 12). The 1A, 25V line powers the S12 indicator (1A, 12) and the pointer control circuit. The ROD (1A, 19) outputs signals to the S12 indicator (1A, 12) and the pointer control circuit. The S12 indicator (1A, 12) also receives signals from the pointer control circuit. The pointer control circuit outputs signals to the pointer control unit (1A, 175V) and the R9 indicator (1A, 175V). The R9 indicator (1A, 175V) is connected to the ROD (1A, 19) and the S12 indicator (1A, 12). The ROD (1A, 19) also receives signals from the pointer control unit (1A, 175V).

27(A-11)

NAEC-91-7958

FIGURE 5. RATE OF DESCENT INDICATION

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (n-Frequent; p-Reasonably Probable; C-Occasional; R-Rare; E-Extremely Unprobable; P-Inprobable)

TABLE 1
NAME: HEADS-UP-DISPLAY CONSOLE
DWG. NO./REV.: 620310

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-HUD CONSOLE SYSTEM
NAEC-91-7958

NAEC-91-7958
Page xi of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
		PERSONNEL INJURY	SYSTEM LOSS	MISSION DAMAGE LOSS	DETECTION BY OPERATORS	COLOCABILITY (HAZARD LEVEL)	CASCADING (HAZARD LEVEL)	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)

Diagram description: The system starts with a trim switch S13. Its output goes through an inverter R10 and then to a logic gate R23. From R23, the signal goes to another inverter S14. The output of S14 is connected to a RAMO (RAMO) and a motion indicator. The RAMO also receives power from +5V and -5V. The motion indicator receives power from -6V. The RAMO has two outputs: one to the motion indicator and one to a connector J4. The motion indicator also has a connection to connector J4. A note at the bottom of the diagram says 'THIS IS NOT PRACTICABLE'.

28(A-12)

NOTE: Hazard Level, Column II, per MIL-STD-882B, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, Column 12, per MIL-STD-882B, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; Z-Extremely Unprobable;
F-Far-Probable)

FIGURE 6. RAMP MOTION/TRIM INDICATION

FAILURE MODES & EFFECTS ANALYSIS - SYSTEM SAFETY ANALYSIS MIK MOD 01 ISO-HUD CONSOLE SYSTEM

二

CONSOLE DISPLAY-UP-HEADS

620310 : 1000 NO

NAEFC-91-7953

九月一號

HAND CONSOLE SYSTEM

卷之三

TABLE I


HEADS-UP-DISPLAY CONSOLE

620310 : 1000 NO

Page xi of 113

~~THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC~~

29 (A-13)



SAFETY ANALYSIS - SYSTEMS MK1000 ISO-HUD CONSOLE SYSTEM

NAEC-91-7958

TABLE 1		UNIT 1	HEADS-UP-DISPLAY CONSOLE
NAME:	(Sub-System)		
ENG. NO.	/REV. 1	620310	

30 (A-14)




FIGURE 8. DECK STATUS INDICATION

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Marginal; III-Critical; IV-Negligible). Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Random; E-Extremely Improbable; F-Inconceivable).

(Failure Modes & Effects Analysis - System) Safety Analysis MK1 MOD 0 ISO-HUD Console System

NAEC-91-7958
TABLE: UNIT 1

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
DAG. NO./REV.: 620310

Page xv of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD	COMMENTS: RECOMMENDATIONS; COMPENSATING PROVISIONS; ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)
			PERSONNEL INJURY LIMIT	SYSTEM LOSS	MISSION DAMAGE		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)

31 (A-15)

FIGURE 9. ACLS STATUS, AIRCRAFT DESIGNATION, WIND DIRECTION INDICATION

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic); II-Critical; III-Marginal; IV-Negligible.
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable).
P=Probability

TABLE: UNIT 1
 NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
 DNG. NO./REV.: 620310

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-MND CONSOLE SYSTEM

MNEC-91-7958

NAEC-91-7958


Page xvi of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	EFFECT ON:				FAILURE - HAZARD	COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)					
		HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	PERSONNEL INJURIES	SYSTEM LOSS	MISSION LOSS							
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)

32 (A-16)

FIGURE 10. PLAT MONITOR SYSTEM

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1. (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2. (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable;
 F-Inimpossible)



(Failure Modes & Effects Analysis - System) SAFETY ANALYSIS MK1 MOD 0 ISO-HUD CONSOLE SYSTEM

NAEC-91-7958

TABLE: UNIT 1

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE

DOC. NO./REV.: 620310

Page xvii of 113

ITEM DESCRIPTION
(COMPONENT, MODE OF
OPERATION, FUNCTION)

HAZARDOUS-
FUNCTIONAL
FAILURE MODE
(HAZARD RELEASE
MECHANISM)

PERSONNEL
INJURY

SYSTEM
LOSS

MISSION
LOSS

DAMAGE

LOSS

POTENTIAL
LOSS

DETECTABLE
OPPONENTS


CLASSIFICATION
(HAZARD LEVEL)

PROBABILITY OF
OCURRENCE

COMMENTS, RECOMMENDATIONS,
COMPENSATING PROVISIONS
(ACCIDENT PREVENTION MEASURES;
SAFETY CONTROLS)

(1) (2) (3) (4) (5) (6) (7) (8) (9) (10) (11) (12) (13)

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)			EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)		
		PERSONNEL INJURY	SYSTEM LOSS	MISSION LOSS	DAMAGE	LOSS	POTENTIAL LOSS	DETECTABLE OPPONENTS	CLASSIFICATION (HAZARD LEVEL)	PROBABILITY OF OCURRENCE			
(1)		(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)



(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS-MKL MOD 0 ISO-HUD CONSOLE SYSTEM

TABLE: UNIT 1

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE


DMG. NO./REV.: 620310

NAEC-91-7958

NAEC-91-7958

Page xviii of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	EFFECT ON:			FAILURE - HAZARD PROBABILITY & CONSEQUENCE (HAZARD LEVEL DETECTION BY OPERATOR)	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)
		PERSONNEL LOSS	SYSTEM LOSS	MISSION LOSS		
(1)	(2)	(3)	(4)	(5)	(6)	(7)



NOTE: THIS IS BEST QUALITY PRACTICALLY
CAN NOT BE BETTER AND VICE-VERSA




FIGURE 12. INTERCOMMUNICATION

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Unprobable; F-Improbable)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-HUD CONSOLE SYSTEM


TABLE: UNIT 1
NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE

Dwg. No./Rev.: 620310

Page six of 113

ITEM DESCRIPTION
(COMPONENT, MODE OF
OPERATION, FUNCTION)

ITEM NO.	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			MISSION LOSS	DETECTABLE BY OPERATOR?	HAZARD LEVEL (CLASSIFICATION LEVEL)	PROBABILITY OF OCURRENCE	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS, (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)			
		LIVES LOSS	DAMAGE LOSS	POTENTIAL LOSS								
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)



35 (A-19)

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1. (I-Critical; II-Catastrophic; III-Hazardous; IV-Negligible)
Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2. (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable;
F-Insignificant)

FIGURE 13. CONSOLE CONTROL PANEL

FAILURE MODES & EFFECTS ANALYSIS - SYSTEM

MEC-91-7958

NAME: John D. Avant **NAME:** John D. Avant **NAME:** John D. Avant

DMG. NO./REV.: 620310

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	EFFECT ON:				FAILURE - HAZARD				COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS, (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)		
		POTENTIAL LOSS	MISSION LOSS	INJURY LOSSES	DETECTABLE BY OPERATOR?	HAZARD LEVEL	PROBABILITY OF OCCURRENCE	HAZARD LEVEL	PROBABILITY OF OCCURRENCE			
(1)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)


Diagram illustrating the control logic for a Console Obstruction Lamp. The lamp is controlled by a Main Power switch and an AC/AC Control switch. The AC/AC Control switch has two positions: "AC ON" and "AC OFF". In the "AC ON" position, the lamp is controlled by the Main Power switch. In the "AC OFF" position, the lamp is controlled by the AC/AC Control switch. The AC/AC Control switch is connected to a unit labeled "UNIT 2 AUXILIARY ELECTR." which also receives power from the Main Power switch. The Main Power switch is controlled by a pedestal switch located in Liftage Unit 3.

```

graph TD
    MainPower[Main Power] --> Lamp[LAMP]
    MainPower --> ACControl[AC/AC CONTROL]
    ACControl -- "AC ON" --> Lamp
    ACControl -- "AC OFF" --> ACControl
    ACControl --> Unit2[Unit 2 AUXILIARY ELECTR.]
    Unit2 --> Lamp
    Unit2 --> PedestalSwitch[Pedestal Switch in Liftage Unit 3]
    PedestalSwitch --> MainPower
  
```

36 (A-20)

FIGURE 14. CONSOLE OBSTRUCTION LAMP



NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible). Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (B-Frequent; C-Ocasional; D-Infrequent; E-Extremely Infrequent).

(FAILURE Modes & EFFECTS Analysis - SYSTEM) SAFETY ANALYSIS MKI MOD 0 LSO-HUD CONSOLE SYSTEM

NAEC-91-7958
TABLE: UNIT 1
NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
Dwg. No./Rev.: 620310

Page xvi of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)			EFFECT ON: PERSONNEL INJURIES	MISSION LOSS	DETECTABLE LOSS	PROBABILITY OF OCCURRENCE (HAZARD LEVEL)	COMMENTS: RECOMMENDATIONS; COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)					
		(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
(1)														




FIGURE 15. CONSOLE DEMONSTRIFICATION

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.2.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Invisable)

TABLE: UNIT 1
NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
DNG. NO./REV.: 620310

(Failure Modes & Effects Analysis - System) SAFETY ANALYSIS MKI NOD 0 LSO-HUD Console System

NAEC-91-7958

Page xvi of 113

NAEC-91-7958

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)			EFFECT ON:			FAILURE - HAZARD			COMMENTS: RECOMMENDATIONS: COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
		PERSONNEL INJURY	SYSTEM SMART	MISSION LOSS	DAMAGE LOSS	POTENTIAL LOSS	DETECTION BY GASSTATION	HAZARD LEVEL	PROBABILITY OF OCCURRENCE		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible) Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable; F-Impossible).

FIGURE 16. DC POWER REGULATORS

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MKI MOD 0 LSQ-HUD CONSOLE SYSTEM

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
Dwg. No./Rev.: 620310

TABLE: UNIT 1

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE

Dwg. No./Rev.: 620310

Page 111 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	EFFECT ON:			FAILURE - HAZARD		COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS, ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS					
		POTENTIAL INJURY	LOSS	MISSION	DETECTION BY OPERATOR?	PROBABILITY OF OCCURRENCE						
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
1A17 (R12)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)											
1A14	HUD CRT											
1A14	HUD CRT											
1A17 (R12)	HUD CRT											
1A12												
1A20	(REF. DWG C)											
1A24	HUD CRT DISPLAY BOUND											
S3												
S4												
TS												

39 (A-23)

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.2.1 (I-Critical); III-Very High; IV-Negligible; Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.2.2 (A-Frequent); B-Unreasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Inapplicable

FIGURE 17-1. HEADS-UP-DISPLAY DYNAMIC IMAGE SYSTEM

SWITCH CABLE

FIGURE 17-2. HEADS-UP-DISPLAY DYNAMIC IMAGE SYSTEM

NAEC-91-7958

TABLE 1
NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
Dwg. No./Rev.: 620310

UNIT 1

NAEC-91-7958

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 LSD-HUD CONSOLE SYSTEM

NAEC-91-7958

Page xxiv of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS, ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS		
			PERSONNEL	SYSTEM	MISSION	DETECTABILITY BY OPERATORS	HAZARD LEVEL	PROBABILITY OF OCCURRENCE	POTENTIAL LOSS	DAMAGES	LOSS
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)

The block diagram illustrates the signal flow through the system. It starts with a 'TO CRT FILAMENT' connection to a CRT component. A 'G2' signal is fed into an 'INTENSITY' block labeled '(518637)'. This intensity signal is then split into three paths, each leading to a display unit: 'R1', 'R2', and 'Focus'. Each display unit has a feedback line returning to the 'INTENSITY' block. The 'R1' and 'R2' units also have connections to a 'PSU' (Power Supply Unit). A 'NOVLAS' signal is shown entering the system. There are also connections to 'A14J1', 'A14J2', 'A14J3', 'A14J4', and 'A14J5' points, which likely represent specific failure modes or test points.

40 (A-24)

NOTES: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Marginal; III-Critical; IV-Negligible)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable; F-Impractical)

FIGURE 17-2. HEADS UP-DISPLAY CRT POWER SUPPLY

(Failure Modes & Effects Analysis - System) Safety Analysis MKI MOD 0 ISO-HUD Console System

TABLE: UNIT 1
NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE

DMG. NO./REV.: 620310

NAC-91-7958

Page xxv of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)			EFFECT ON:			FAILURE - HAZARD			COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS, ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS						
		PERSONNEL	SYSTEM	MISSION	DETECTABLE BY OPERATORS?			CLASSIFICATION OF HAZARD LEVEL	PROBABILITY OF OCCURRENCE								
					POTENTIAL LOSS	DAMAGE LOSS	INJURY LOSS										
(1)					(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)

1A14
HUD P. S.
ASS'Y.

ANODE

1A15 (620318)
CRT

PLATE

VIDEO

1A24
HUD CRT
DISPLAY BRO.

1A5
HUD DEF.
ADAPTER

DEFL. YOKE

1SO VIDEOWR

COMBINER

MYLAR
PELICLE

HUD PROJECTION
LAMP

HEAT REFLECTION
REFLECTOR

REFLECTION SCREEN

FIGURE 17-3. HEADS-UP-DISPLAY CRT AND YOKE

NAC-91-7958

NOTE: Hazard Level - Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Critical), III-Marginal; IV-Negligible;
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.1 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable;
F-Inapplicable)

(Failure Modes & Effects Analysis - System) Safety Analysis MK1 MOD 01 ISO-HUD Console System

TABLE: UNIT 1
NAME: (Sub-System) HEADS-UP-DISPLAY CONSOLE
DNC. NO./REV.: 620310

NAEC-91-7958

Page xxvi of 113

NAEC-91-7958

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)						EFFECT ON:						FAILURE - HAZARD						COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)								
		PERSONNEL INJURY	SYSTEM LOSS	MISSION DAMAGE	POTENTIAL LOSS	DETECTABLE BY SENSORS	HAZARD LEVEL	PROBABILITY OF OCCURRENCE	SEVERITY	PERSONNEL INJURY	SYSTEM LOSS	MISSION DAMAGE	POTENTIAL LOSS	DETECTABLE BY SENSORS	HAZARD LEVEL	PROBABILITY OF OCCURRENCE	SEVERITY	PERSONNEL INJURY	SYSTEM LOSS	MISSION DAMAGE	POTENTIAL LOSS	DETECTABLE BY SENSORS	HAZARD LEVEL	PROBABILITY OF OCCURRENCE	SEVERITY			
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)	(14)	(15)	(16)	(17)	(18)	(19)	(20)	(21)	(22)	(23)	(24)	(25)	(26)	(27)	(28)	

42 (A-26)

FIGURE 17-4. HEADS-UP-DISPLAY CRT DISPLAY BOARD

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Unprobable; F-Inversible)


(Failure Modes & Effects Analysis - System) Safety Analysis - HCU MOD 0 ALSO-HUD CONSOLE SYSTEM

TABLE: UNIT 1
NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE

DNG. NO./REV.: 620310

Page xxvii of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	EFFECT ON:				FAILURE - HAZARD				COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS, ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS		
		POTENTIAL LOSS	MISSION LOSS	PERSONNEL INJURY	DAMAGE	DETECTION BY POTENTIAL LOSS	CLASSIFICATION (HAZARD LEVEL)	PROBABILITY OF OCCURRENCE	RECOMMENDATION			
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)



43 (A-27)

FIGURE 17-5. HEADS-UP-DISPLAY DEFLECTION AMPLIFIER

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Tolerable); IV-Extrigible; Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Unlikely; E-Extremely Unlikely).

TABLE: UNIT 1
NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
DNG. NO./REV.: 620310

(Failure Modes & Effects Analysis - System) Safety Analysis MIL-MOD_01SO-HUD Console System

MAEc-91-7958

MAEc-91-7958

Page xxviii of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)			EFFECT ON: PERSONNEL SYSTEM MISSION			FAILURE - HAZARD DETECTION BY OPERATOR?			COMMENTS, RECOMMENDATIONS: COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)		
		LIGHTS	INJURY	DAMAGES	POTENTIAL LOSS	LOSS	LOSS	MISSION	HAZARD LEVEL	RECOMMENDATION	HAZARD LEVEL	RECOMMENDATION	HAZARD LEVEL
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)	

FIGURE 18. PRINTED CIRCUIT BOARD BACKPLANE

44 (A-28)

NOTE: Hazard Level, column 11, per MIL-STD-882A, para. 5.4.3.1 (1-Catastrophic; 2-Critical; 3-Marginal; 4-Negligible). Hazard Probability, column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Estremely Improbable; F-Inconsequential).

(Failure Modes & Effects Analysis - System) Safety Analysis MKI MOD 0 ISO-HUD Console System

TABLE: UNIT 1

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE

DMC. NO./REV.: 620310

NAEC-91-7958

Page xix of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)			EFFECT ON: PERSONNEL SYSTEM			MISSION			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)	
		INDUSTRY	SEATS	LIGHT	DAMAGE	LOSS	POTENTIAL LOSS	DETECTION BY OPERATOR?	CALSSIFICATION (HAZARD LEVEL)	PROBABILITY OF OCURRENCE	CLASSIFICATION (HAZARD LEVEL)	PROBABILITY OF OCURRENCE	(11)	(12)	(13)
(1)	(2)			(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)	




FIGURE 19. HUD PROJECTION LAMP ASSEMBLY

NOTE: Hazard Level, column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, column 12, per MIL-STD-882A, para. 5.4.3.7 (A-Frequent; B-Remote; C-Occasional; D-Rare; E-Extremely Unlikely; F-Ine-possible)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MKL MOD 0 LSO-HUD CONSOLE SYSTEM

TABLE: UNIT 1

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE

Dwg. No./Rev.: 620310

NAEC-91-7958

Page 1 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTION MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD PROBABILITY (HAZARD LEVEL)	COMMENT: RECOMMENDATIONS: COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)
			POTENTIAL LOSS INJURY	POTENTIAL LOSS DAMAGE	MISSION		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)
1.0	Range Indication/Heads-Up-Display (run). The range data superimposed on the HUD combiner glass commencing when returning aircraft reach the CV within one [1] nautical mile of the ramp edge. SPN-42 radar and are fed to the HUD console and are fed to the HUD console as varying DC stimulus via cable M227 to connector J8. When the aircraft approaches to 0.99 miles, a nearly complete circle suddenly appears on the display. At 0.5 miles, half a circle remains; at 0.25 miles a quarter of the circle remains visible; and so on until at about 0.01 miles, the circle disappears completely. The circle, or a portion thereof,	a) No image (while A/C within 1nm) i) Loss of LA24 image generator printed circuit board output, ii) Loss of HUD CRT subsystem, iii) Loss of input stimuli to LA24 from console connector J8 (Signal) due to signal breakdown in cable M227 and/or Signal Junction Box (Unit 4A1),	-	-	-	x	III When failures occur that affect the loss of only the HUD display of range information, the LSO will use the lower console range display. When a failure occurs that disables both displays, the LSO will depend on his visual contact with the aircraft and his experience to judge the range of the aircraft. This failure mode would therefore cause no problem during a given recovery period and it would be corrected before the next one.

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic); II-Critical; III-Marginal; IV-Negligible.
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Inconceivable).

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-HUD CONSOLE SYSTEM

NAEC-91-7958
TABLE: UNIT 1

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
DAG. NO./REV.: 620310

Page 2 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			MISSION PERSONNEL	DETECTABLE BY OPERATOR?	CLASSIFICATION (HAZARD LEVEL)	PROBABILITY OF OCURRENCE	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)
			MISSION		POTENTIAL LOSS					
			DAMAGE	LOSS						
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)
1.0	(cont'd)	a)	Iv) Loss of Internal console circuitry paths from <u>J8</u> to <u>J824</u> caused by open pin or/m broken wire/high resistance pin connection in connectors <u>J8231</u> (power) or <u>J8233</u> (signal) or interconnection within card cage back-plane <u>J812</u> .							
		v)	Loss of DC power supply input voltages to <u>J824</u> (HUD Display Board) and HUD CRT subsystems provided by Auxiliary Electronics Box (Unit 2) through console connector <u>J4</u> (DC power), assembly <u>J84</u> (Regulator Board Assembly)							

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Inmissible)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 (SO-HUD CONSOLE SYSTEM

TABLE: UNIT 1NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLEDwg. No./Rev.: 620310

NAEC-91-7958

Page 3 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS, ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS
			PERSONNEL	SYSTEM	MISSION		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)
1.0	(cont'd)	a)	vii)	Loss of range & ramp motion signal Condition circuit board 1A20 output	-	-	x
		b)	Incorrect value displayed	-	-	-	III
		1)	Component malfunction on 1A24 PCB causing misinterpretation of conditioned Range data.	-	-	-	D
		11)	Component malfunction on 1A20 PCB causing incorrect signal conditioning of input DC stimulus (varying DC voltage from SPN-42 radar,	-	-	-	This failure mode is detectable by the LSO when large incremental errors develop. Small errors are of little consequence to the LSO because of his visual contact with the aircraft in the approach. Small errors will ultimately be detected through periodic calibrations and corrected with an appropriate maintenance action. If only the HMD display is affected in this failure mode, the LSO will use the console display.

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible); Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable; F-Impossible).

(Failure Modes & Effects Analysis - System) SAFETY ANALYSIS MK1 MOD 0 JSD-HUD CONSOLE SYSTEM

NAEC-91-7958

TABLE: UNIT 1NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLEDWG. NO./REV.: 620310Page 4 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON: PERSONNEL SYSTEM	MISSION	FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
					DETECTABLE LOSS	POTENTIAL LOSS	PROBABILITY OF OCURRENCE (HAZARD LEVEL)	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)
1.0	(cont'd)	b)	1.1.1	Loss of critical voltages to <u>IA24</u> and <u>IA20</u> from <u>Auxiliary Electronics Box (Unit 2)</u> and <u>IA4</u> .				

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Critical); II-Catastrophic; III-Marginal; IV-Negligible!
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable;
 F-Inmissible)

TABLE: UNIT 1
 NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
 DNG. NO./REV.: 620310

NAEC-91-7958

NAEC-91-7958

Page 5 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD PROBABILITY OF OCCURRENCE (HAZARD LEVEL) DETERMINED BY OPERATOR?	COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)	
			PERSONNEL SYSTEM	MISSION	POTENTIAL LOSS			
LIVES	DAMAGE	LOSS						
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	
2.0	<u>Rate of Descent (ROD) Indication on Heads-up-Display (HUD).</u> The ROD scale on the HUD is a facsimile of the console indicator only the HUD display of ROD information, the LSO will use the console display. When a failure occurs that disables both displays, the LSO will depend on his visual contact with the aircraft and his experience to judge the normality of the aircraft ROD. This failure mode would, therefore, not significantly affect safety during a given recovery period and it would be corrected before the next one.	The rate of descent (sink rate) of the incoming aircraft as it approaches the CV on its glide-slope path to its final touchdown point. The ROD scale is located on the extreme right of the combiner glass. It displays a range from 200 feet per minute to 1500 feet per minute of aircraft descent during a recovery. Its pointer will move slightly off-scale at each end of the scale for descent rates outside of the range. This display is generated by the SPW-42 radar AILS system which provides varying analog	-	-	-	x	III	
	a) No Pointer Indication							D
	1) Loss of <u>IA24</u> Image generator printed circuit board output,							
	II) Loss of ROD CRR subsystem,							
	III) Loss of input stimulus to <u>IA24</u> from console connector <u>J8</u> (<u>Signal 1</u>) due to signal breakdown in cable W227 and/or <u>Signal 1</u> Junction Box (Unit <u>A1</u>),							

NOTE: Hazard Lev. I, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Inpossible)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-HUD CONSOLE SYSTEM

NAEC-91-7958

NAME : (Sub-system) HEADS-UP-DISPLAY CONSOLE

ITEM NO./REV. : 620310

Page 6 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:		FAILURE - HAZARD		COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
			PERSONNEL	SYSTEM	MISSION	POTENTIAL LOSS	
LIAZS	Hazard	DAMGE	LOSS	LOSS	DETECTABLE BY OPERATORS?	CLASSIFICATION OF PROBABILITY OF OCCURRENCE (HAZARD LEVEL)	CLASSIFICATION OF PROBABILITY OF OCCURRENCE (HAZARD LEVEL)
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)
2.0	(cont'd)	a)					
			iv) Loss of internal console circuitry paths from JB to <u>1A24</u> caused by open pin crimp/broken wire/high resistance pin connection in connectors <u>1A1231</u> (Power) or <u>1A1233</u> (Signal) or interconnection within card case back-plane <u>1A12</u> or connector <u>1A1236</u> (Module)				
			v) Loss of DC power supply input voltages to <u>1A24</u> (HUD Display Board) and HUD CRT subsystems provided by Auxiliary Electronics Box (Unit 2).				

NOTE: Hazard Level, Column 11, per MIL-STD-882B, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Unprobable; F-Inprobable)

TABLE: UNIT 1
 NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
 DNG. NO./REV.: 620310

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 LSO-HUD CONSOLE SYSTEM

NAEC-91-7958
 NAEC-91-7958
 Page 7 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS, ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS
			POTENTIAL LOSS	DAMAGED	LOSS		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)
2.0	(cont'd)	a)	through console connector J4 (DC power) assembly <u>LA4</u> (Regulator Board ass'y, and the LA5 VR-C Input ("AC On").	-	-	-	x
		v)	range & ramp motion Signal Conditioning circuit board <u>LA19</u> output.	-	-	-	III
		b)	Incorrect Value displayed	-	-	-	d
		i)	Component malfunction on <u>LA24</u> PCB causing mis-interpretation of conditioned range data.	-	-	-	
		ii)	Component malfunction on <u>LA12</u> PCB causing incorrect signal conditioning of input DC	-	-	-	

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Impossible)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MKI MOD 0 ISO-HUD CONSOLE SYSTEM

NAEC-91-7958

TABLE: UNIT 1
 NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
 DNG. NO./REV.: 620310

Page 8 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	PERSONNEL LIVES	SYSTEM LIVES	MISSION LOSS	EFFECT ON: INJURY LOSS	FAILURE - HAZARD			COMMENTS; RECOMMENDATIONS; COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)		
							DETECTABLE BY OPERATOR?	CLASSIFICATION (HAZARD LEVEL)	PROBABILITY OF OCURRENCE			
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
2.0	(cont'd)	b)										

i) stimulus
(varying DC
voltage) from
SPN-42 radar.

ii) Loss of
critical
voltages to
1A24 and
1A19 from
Auxiliary
Electronics
Box (Unit 2)
and 1A4.

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible); Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable; F-Inpossible).

(Failure Modes & Effects Analysis - System) Safety Analysis MK1 Mod 0 LSO-HUD Console System

TABLE: UNIT 1

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE

DMG. NO./REV. 1 620310

NAEC 91-7958

Page 9 of 113

NAEC-91-7958

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:	FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS, ACCIDENT PREVENTION MEASURES & SAFETY CONTROLS
				PERSONNEL	SYSTEM	MISSION	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	D
3.0	Ramp Motion/Trim Indication on the Heads-Up-Display (HUD). Indicator display displaying sum of ramp displacement due to sea and any fixed displacement on the vertical scale at the extreme left of the combiner glass. Ramp motion signal is from the ship Harmonization Computer (SHC). A momentary switch located on the console selects the ship's trim which is displayed (without ramp motion) on the ramp scale. NOTE: The most dangerous ramp position during landing operations is a high ramp from +10 feet to +20 feet. This range is indicated by a red filter on the scale. A high ramp is much more dangerous than a low ramp since the latter means a hard landing and less danger to the pilot and aircraft, while the former may mean a ramp strike.	INSTRUMENT SWITCH	DAMAGE LOSS	POTENTIAL LOSS	DETECTABLE BY OPERATOR?	CLASSIFICATION (HAZARD LEVEL)	PROBABILITY OF OCCURRENCE
	a) No indication	x	-	x	-	x	III
	i) Loss of LA24 image generator printed circuit board output.						
	ii) Loss of CRT subsystems,						
	iii) Loss of input stimulus to LA24 from console connector J19 (Signal) due to signal breakdown in W227 cable and/or Signal Junction Box (Unit 41),						

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Farmer; E-Extremely Inprobable; F-Terminable)

TABLE: UNIT 1
 NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
 DWG. NO./REV.: 620310

HAEC-91-7958

Page 10 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			PROBABILITY OF OCURRENCE (HAZARD LEVEL) CLASSIFICATION DETERMINED BY OPERATORS?	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)
			PERSONNEL LOSS	SYSTEM LOSS	MISSION LOSS	POTENTIAL LOSS	DAMAG E LOSS	INJURY LOSS		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)
3.0	(cont'd)	a)	iv)	Loss of internal console circuitry paths from JA to JA24 caused by open pin crimp/broken wire, high resistance pin connection in connectors JA12J1 (Power) or JA12J3 (Signal) or interconnection within card cage back-plane JA12 including connector JA12J7 (front panel),						
			v)	Loss of DC power supply input voltages to JA24 (HUD display)						

NOTE: Hazard Level, Column 11, per MIL-STD-882B, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Very Marginal); Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Occasional; C-Ocasional; D-Rare; E-Remote; F-Improbable).

TABLE: UNIT 1

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLES

DOC. NO./REV.: 620310

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM), SAFETY ANALYSIS, MK1 MOD 0 ISO-HUD Console System

NAEC-91-7958

NAEC-91-7958

Page 11 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	EFFECT ON:			FAILURE - HAZARD			COMMENTS: RECOMMENDATIONS! COMPENSATING PROVISIONS / ACCIDENT PREVENTION MEASURES / SAFETY CONTROLS
		POTENTIAL LOSS	DAMAGE LOSS	INJURY LOSS	MISSION	SYSTEM	PERSONNEL	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)
3.0	(cont'd)	a)	v)	Board and HUD CRT subsystem provided by Auxiliary Electronics Box (Unit 2) through console connector J4 (DC Power), assembly IA4 (Regulator Board Assembly, and the 115 VAC input ("AC ON").				
			vii)	Loss of trim information due to open or shorted momentary switch 1A17813.				
			viii)	Loss of range & ramp motion signal conditioning circuit board IA20 output.				

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible) Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Unprobable; F-Impossible)

[Failure Modes & Effects Analysis - System] SAFETY ANALYSIS MIL-MOD-01 ISO-HUD CONSOLE SYSTEM

NAEC-91-7958

TABLE: UNIT 1
 NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
 DNG. NO./REV.: 620310 _____

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON: PERSONNEL SYSTEM	MISSION	FAILURE - HAZARD	COMMENTS: RECOMMENDATIONS; COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)		
						DETECTABLE BY SENSORS	DETECTION BY OPERATORS	POTENTIAL LOSS
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)
3.0	(cont'd)	VIII) No trim selection due to shorted or open control switch <u>1A17S13</u> .	-	-	-	-	x	III
		b) Single un-changing indication or erroneous readout.	-	-	-	-	-	
		1) Component malfunction on <u>1A24</u> PCB causing misinterpretation of conditioned ramp data.	-	-	-	-	-	
		11) Component malfunction on <u>1A20</u> PCB causing incorrect signal conditioning of input DC stimulus	-	-	-	-	-	

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 LSO-HUD CONSOLE SYSTEM

TABLE: UNIT 1

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE

DNG. NO./REV.: 620310

NAEC-91-7958

Page 13 of 113

NAEC-91-7958

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)			
			POTENTIAL LOSS	DAMAGE LOSS	PERSONNEL INJURY	DETECTABLE LOSS	DETECTABLE OPERATORS?	PROBABILITY OF OCURRENCE	HAZARD LEVEL	CATASTROPIC	MARGINAL	NEGLIGIBLE
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
3.0 (cont'd)	b)	i)	(varying DC voltage) from ship's trunk/har- monization computer. ii)	Loss of critical voltages to <u>1A24</u> and <u>1A19</u> from Auxiliary Electronics Box (Unit 2 and 1A4).								

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic); II-Critical; III-Marginal; IV-Negligible;
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable;
 F-Inmissible)

TABLE: UNIT 1
 NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
 Dwg. No./Rev.: 620310

(Failure Modes & Effects Analysis - System) Safety Analysis - MK1 MOD 0 ISO-HUD Console System

NAEC-91-7958

Page 14 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)	
			POTENTIAL LOSS INJURY	DAMAGES	MISSION	OPERATOR?	PROBABILITY OF OCCURRENCE HAZARD LEVEL			
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	
4.0	Glidepath and Line-Up Imaging on Heads-up-Display (HUD).	The glidepath line-up information is presented by the location of an electronic generated aircraft symbol relative to a vertical line-up reference datum. A choice of two scale factors is available. 30 feet per division (ft/div) and 10 feet per division. To indicate to the observer that the 30 ft/div is in use, the aircraft is represented as a small circle. Wings and a tail are added when the 10 ft/div scale factor is in use. The selection is made with a three-position rotary switch on the HUD illumination panel. The third position is an automatic (auto) mode and produces a scale factor of 30 ft/div for the aircraft symbol when the aircraft is less than one mile away. For the 30 ft/div scale factor, the displacement of the aircraft symbol is electronically limited so that the symbol will remain in view no matter how far the aircraft is from the desired glide slope. With the 10 ft/div scale factor, the symbol can be driven completely out of view. The displacement of the electronically generated aircraft symbol is determined by analog DC signals from the SPN-42 radar.	a) No aircraft symbol	-	-	-	-	x	III D	
			i) Loss of image generator printed circuit board 1A24 output,							
			ii) Loss of HUD CRT subsystem,							
			iii) Loss of input stimulus to 1A24 from console connector J8 (signal) due to signal breakdown in cable M227							

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Inapplicable)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MKI MOD_0 LSO-IND CONSOLE SYSTEM

TABLE: UNIT 1

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE

DNG. NO./REV.: 620310

NAEC-91-7958

NAEC-91-7958
Page 15 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS/RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)		
			POTENTIAL LOSS INJURY	DAMAGE LOSS	MISSION LOSS	DETECTABLE BY SENSORS	CASCADING FAILURE (HAZARD LEVEL)	PROBABILITY OF OCCURRENCE	CLASSIFICATION	OPERATORS	HAZARD LEVEL
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)
4.0	(cont'd)	i) (11) and/or signal junction Box (Unit 1A1),									
		iv) Loss of internal console circuitry paths from 1A8 to 1A24 caused by open pin crimp/broken wire, high resistance pin connection in connectors 1A12J1 (power) or 1A12J3 (signal) or interconnection within card case back-plane 1A12,									
		v) Loss of DC power supply input voltages to 1A24 (Input Display									

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Very Little); Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Impossible)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MKI MON. O LSO-HUD Console System

NAEC-91-7958

TABLE: UNIT 1

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE

DNG. NO./REV.: 620310

Page 16 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTION MODE (HAZARD RELEASE MECHANISM)			EFFECT ON: PERSONNEL	SYSTEM	MISSION	FAILURE - HAZARD PROBABILITY (HAZARD LEVEL) CLASSIFICATION	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)
		DETECTABLE BY OPERATOR?	POTENTIAL LOSS	DAMAGE LOSS					
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)
4.0	(cont'd)	a)	v) Board and HUD CRT subsystems provided by Auxiliary Electronics Box (Unit 2) through console con- nector J4 (DC Power), assembly IA4 (Regu- lator Board Assembly), and the 115 VA-C input ("AC ON").	-	-	-	-	-	III
		b)	Incorrect pos- ition of air- craft symbol with respect to datum lines or incorrect scale factors	-	-	-	-	-	E
		i)	Component malfunction on IA24 PCB causing mis- interpre- tation of conditioned range data.	-	-	-	-	-	

61 (A-45)

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic) III-Critical; IV-Marginal; V-Frequent; VI-Probable; C-Ocasional; R-Remote; E-Extremely improbable; P-Impossible; Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2

Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Extremely improbable; B-Probable; C-Ocasional; D-Remote; E-Extremely improbable; F-Impossible)

NAEC-91-7958

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS_MK1 MOD 0 ISO-HUD_CONSOLE_SYSTEM

TABLE: UNIT 1

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
 DNG. NO./REV.: 620310

NAEC-91-7958

Page 17 of 113

NAEC-91-7958

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)
			PERSONNEL INJURY	SYSTEM LOSS	MISSION LOSS	DETECTABLE BY OPERATOR?	POTENTIAL LOSS	PROBABILITY OF HAZARD OCCURRENCE	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)
4.0	(cont'd)	b)	i) Component malfunction on IA20 PCB causing incorrect signal conditioning of input DC stimulus (varying DC voltage) from SPM-42 radar.						
			ii) Loss of critical voltages to IA24 and IA20 from <u>Auxiliary Electronics Box</u> (Unit 2) and <u>IA4</u> .						

NOTE: Hazard Lev. I, Column 11, per MIL-STD-882B, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, column 12, per MIL-STD-882B, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable;
 F-Impossible)

(Failure Modes & Effects Analysis - System) Safety Analysis MKI Mod 0 ISO-HUD Console System

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE

DATA NO./REV.: 620310

TABLE: UNIT 1

NAEC-91-7958

Page 18 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-PUNCTUAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON: PERSONNEL SYSTEM INJURY	MISSION LOSS DAMAGE	FAILURE - HAZARD PROBABILITY OF OCCURRENCE	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
(1)	(2)	(3)	(4)	(5) (6) (7) (8) (9)	(10) (11)	(12) (13)
5.0	The Heads-Up-Display Reticle Scale projection Lamp Circuitry provides the back-plate assembly (1M26-Dug-620310) and provides the back-lighting for the HUD combiner reticle scales (line-up datum, glide slope datum). The reticle scale illumination is obtained by passing the light from a 50-watt, 12.6 volt AC lamp through a heat deflector, heat absorber, a diffuser and a green filter. This produces a green scale illumination of approximately 520 nanometers. The pointer display is green. The CRT phosphor is green. The two light sources in the green region are not of the same wavelength so that the pointers and scale lines are not confused whose control is located on the console control panel A17.	a) Low, intermittent, or loss of HUD combiner reticle scale lighting. i) Loss of A-C input to common 115 VAC power connection ITB2. ii) Shorted or open "Scale On/Off" control switch ITB3. iii) Shorted or open winding in variac T_1 resulting in a random level of proj. lamp intensity & possible information loss.	- - -	- -	x -	III D

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Hazardous; IV-Negligible)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Somewhat Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Impossible)

(Failure Modes & Effects Analysis - System) Safety Analysis MK1 MOD 0 LSO-HUD Console System

NAEC-91-7958

TABLE: UNIT 1

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE

DOC. NO./REV.: 620310

Page 19 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)		
			PERSONNEL INJURY	SYSTEM LOSS	MISSION LOSS	DETECTABLE LOSS	CATASTROPHIC LOSS	PROBABILITY OF OCURRENCE (HAZARD LEVEL)			
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)
5.0	(cont'd)	<p>iv) 'washout', open isolation diodes, (no unblanking control) open relay coil or frozen contacts in K1 located on the HUD Projection Lamp Board 1A13A1 (Dwg. 516667) or its terminal strip 1A13TBL causing low A-C input to transformer LAT1.</p> <p>v) shorted or open winding in transformer LAT1 (12.6 VAC).</p> <p>vii) Open or loose connection on terminal board 1TB1 linking 1TB1 and the HUD projection lamp,</p>									

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable; F-Ineasible)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MKI MOD 0 LSO-HUD CONSOLE SYSTEM

MEC-91-7958

TABLE: UNIT 1
 NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
 DMG. NO./REV.: 620310

Page 20 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	PERSONNEL INJURY	SYSTEM LOSS	MISSION DAMAGE	EFFECT ON: PERSONNEL SYSTEM	FAILURE - HAZARD			PROBABILITY OF DETECTION BY OPPONENT	HAZARD LEVEL (CLASSIFICATION OF CONCERN)	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
							POTENTIAL LOSS	DAMAGES	INJURIES			
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
5.0	(cont'd)	a)	viii)									

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Probable; C-Occasional; D-Rare; E-Extremely Improbable;
 F-Impossible)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MKI MOD 0 LSD-HUD CONSOLE SYSTEM

TABLE: UNIT 1

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE

DAG. NO./REV.: 620310

NAEC-91-7958

Page 21 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	EFFECT ON:			FAILURE - HAZARD	COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS, ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS
		HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	PERSONNEL INJURY	SYSTEM LOSS		
(1)	(2)	(3)	(4)	(5)	(6)	(7)
6.0	Console Range Indicator - Refer to figure 4. The console Range Scale is below the PLAT display. It's Pointer will remain at 6 miles when the range is 6 miles or greater. The scale has a resolution of 0.2 nautical mile. Range signals are provided by the SPN-42 radar and are fed to the HUD console as varying DC stimulus via cable W227 to connector J8. The range PCB is located in the console cart cage.	a) No indication	-	-	x	III D

Figure 4. The console Range Scale is below the PLAT display. Its Pointer will remain at 6 miles when the range is 6 miles or greater. The scale has a resolution of 0.2 nautical mile. Range signals are provided by the SPN-42 radar and are fed to the HUD console as varying DC stimulus via cable W227 to connector J8. The range PCB is located in the console cart cage.

a) No indication

- 1) Loss of input stimulus to J420 from J420 to console connector J8 (Signal) due to signal breakdown in cable W227 or signal board J420 Junction Box -Unit 4A,
- 2) Loss of Range & Ramp Motion Signal Conditioning circuit board J420 output,
- 3) Loss of DC power supply input voltages to J420 and J420 through console connector J4 (DC Power)

NOTE: Hazard Level, Column 11, per MIL-STD-882B, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Occasional; C-Occasional; D-Remote; E-Extremely Improbable; F-Improbable)

TABLE: UNIT 1
 NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
 Dwg. No./Rev.: 620310

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-HUD CONSOLE SYSTEM
 NAEF-91-7958

Page 22 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	PERSONNEL INJURY	SYSTEM LOSS	MISSION DAMAGE	POTENTIAL LOSS	DETECTABLE BY OPERATOR	CLASSIFICATION LEVEL (HAZARD LEVEL)	PROBABILITY OF OCCURRENCE	COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)		
										EFFECT ON:	FAILURE - HAZARD	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
6.0 (cont'd)	a)	111) provided by Auxiliary Electronics Box and the supplementary DC voltages generated by <u>1A9</u> .										

i) Loss of a complete segment of redundant incandescent lamps within 1A9 indicated assembly.

v) Loss of circuit path between 1A9 indicator assembly and card cage back-plane 1A12.

vi) Loss of pointer and scale integrality caused by failure (short or high resistance open) within indicator on/off

NOTE: Hazard Lev. I, Column 11, per MIL-STD-882A, para. 5.4.2.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, column 12, per MIL-STD-882A, para. 5.4.3.7 (A-Frequent; B-Rare; C-Occasional; D-Random; E-Extremely Improbable; F-In impossible)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM SAFETY ANALYSIS_MK1 MOD 0 LSO-HUD CONSOLE SYSTEM

NAEC-91-7958
NAEC-91-7958TABLE: UNIT 1
NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
DNG. NO./REV.: 620310

Page 23 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)			EFFECT ON:			FAILURE - HAZARD			PROBABILITY OF OCCURRENCE (HAZARD LEVEL) (ASSESSMENT BY OPERATORS)	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
		PERSONNEL INJURY	SYSTEM LOSS	MISSION LOSS	DETECTION BY SMART	POTENTIAL LOSS	DAMAGE LOSS	INJURY	SYSTEM LOSS	MISSION LOSS		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
6.0												

68 (A-52)

This failure mode is detectable by the LSO when large incremental errors develop. Small errors are of little consequence to the LSO because of his visual contact with the aircraft in the approach. Small errors will ultimately be detected through periodic calibrations and corrected with an appropriate maintenance action. If only the HUD display is affected in this failure mode, the LSO will use the console display.

b) Single unchanging indication, non-linear response, or pressure limiting lens than full-scale.

1) Component failure within population of LA20 signal conditioning board causing geometric non-linearity of load isolation amplifiers and/or loss of the analog-to-digital (A/D) conversion

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Impracticable)

(Failure Modes & Effects Analysis - System) Safety Analysis MK1 MOD 0 ISO-HUD CONSOLE SYSTEM

TABLE: UNIT 1
 NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
 DMG. NO./REV.: / 620310

NAEC-91-7958

Page 24 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON: PERSONNEL SYSTEM	FAILURE - HAZARD		COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
				DETECTABLE BY OPERATOR?	PROBABILITY OF OCURRENCE (HAZARD LEVEL) CLASSIFICATION	
(1)	(2)	(3)	(4)	(5)	(6)	(7)
6.0	(cont'd)	b)	1) which drives the <u>149</u> Indi- cator asses- sibly.	(8)	(9)	(10)
				(11)	(12)	(13)

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible); Hazard Probability, column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Random; E-Extremely Unprobable; F-Inpossible).

TABLE: UNIT 1
 NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
 DNG. NO./REV.: 620310

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MKI MOD 0 LSO-IND CONSOLE SYSTEM

NAEC-91-7958

Page 25 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD PROBABILITY OF OCCURRENCE (HAZARD CLASSIFICATION)	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)
			PERSONNEL	SYSTEM	MISSION LOSS		
					DAMAGE LOSS	POTENTIAL LOSS	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)
7.0	Console Rate-Of-Descent Indicator - Refer to Figure 5. Indicator displays the Rate Of Descent (sink rate) of the incoming aircraft as it approaches the CV on its glide-slope path to its final touch-down point. The scale covers a range of zero to a maximum of 1912 feet per minute with a resolution of 50 feet per minute. If the rate of descent is greater than 1912 feet per minute, it will continue to read that value. A trend lamp adjacent to the main pointer and of lesser intensity is used to indicate the direction of change for rate of descent. If the trend lamp is a higher number, the rate of descent is decreasing; and if it is a lower number, the rate is increasing. The ROD indicator input is generated by the SPN-42 radar ACIS system which provides varying analog stimulus of 0-10 VDC corresponding to 0-20000 feet per minute descent rates.	a) No Indication i) Loss of input stimulus to <u>J1A9</u> from console connector <u>J8</u> due to signal breakdown in cable <u>M227</u> or Signal Junction Box Unit <u>4A1</u> . ii) Loss of ROD signal conditioning circuit board <u>M19</u> output. iii) Loss of DC power supply input voltages to <u>J4</u> and <u>J1A9</u> through console connector <u>J4</u> .	-	-	-	x	III D When failures occur that affect loss of only the console display or rate of descent information, the LSO will use the redundant indication on the IHP. When a failure occurs that disables both displays, the LSO will depend on his visual contact with the aircraft ROD. This failure mode would, therefore, not significantly affect safety during a given recovery period and it would be corrected before the next one.

TABLE: UNIT 1
 NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
 DNG. NO./REV.: 620310

Page 26 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON: PERSONNEL SYSTEM	MISSION	POTENTIAL LOSS	FAILURE - HAZARD	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)		
							DETECTABLE BY OPERATOR?	CLOSED CIRCUIT TELEVISION (CAMERA) LOSS	INTEGRITY OF POWER SUPPLY
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)
7.0	(cont'd)	a)	111) DC power provided by Auxiliary Electronics Box and the supplementary DC voltages generated by <u>IA1</u> ,						

- i) Loss of a complete segment of redundant incandescent lamps within IA7 indicator assembly,
- v) Loss of circuit path between IA7 Indicator assembly and card cage back-plane IA12,
- vi) Loss of pointer and scale intensity caused by failure of short or high resistance open) within

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 LSO-IND CONSOLE SYSTEM

TABLE: UNIT 1

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE

DMG. NO./REV.: 620310

MEC-91-7958

NAEC-91-7958

Page 27 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	EFFECT ON:			FAILURE - HAZARD		COMMENTS: RECOMMENDATIONS: COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)	
		HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	PERSONNEL INJURY	SYSTEM LOSS	MISSION LOSS	POTENTIAL LOSS		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	
7.0	(cont'd)	a)	a) i) Indicator on/off switch LA17S12 and/ or indicator intensity potenio- meter LA17S9. ii) No trend indi- cation iii) Component failure within the population of the LA23 con- ditioning board in the comparator and latch circuitry where period- ically stored A/D data is compared with current A/D data for the display of the sense of direction for changing data. iv) Single unchanging indi- cation, non- linear response, or premature	(9)	(10)	(11)	(12)	(13)

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable;
F-Inapplicable)

B
C
D
E
F

A
B
C
D
E
F

A
B
C
D
E
F

A
B
C
D
E
F

A
B
C
D
E
F

A
B
C
D
E
F

A
B
C
D
E
F

A
B
C
D
E
F

A
B
C
D
E
F

A
B
C
D
E
F

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 LSO-HUD Console System

MAEC-91-7958

TABLE: UNIT 1
 NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
 DNG. NO./REV.: 620310

Page 28 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			MISSION LOSS	DETECTION BY OPERATOR?	CLASSIFICATION (HAZARD LEVEL)	PROBABILITY OF OCURRENCE	COMMENTS! RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)		
			PERSONNEL	SYSTEM	HAZARD - HAZARD							
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
7.0	(cont'd)	a)										

- a) Limiting less than full-scale.
 i) Component failure with in population of 1A19 signal conditioning board causing loss of analog-to-digital (A/D) conversion and/or loss of the decoder/multiplexers output to the console lamp power driven.

NOTE: Hazard Level 1, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible); Hazard Probability, Column 12, per MIL-STD-882H, para. 5.4.3.2 (A-Frequent; B-Occasionally Probable; C-Occasional; D-Rare; E-Extremely Unprobable; F-Impossible).

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-MND CONSOLE SYSTEM

TABLE: UNIT 1

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE

DNC. NO./REV.: 620310

NAEC-91-7958

Page 29 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON: PERSONNEL SYSTEM	MISSION LOSS	FAILURE - HAZARD CLASSIFICATION (HAZARD LEVEL)	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)	
						DETECTABLE BY OPERATOR?	PROBABILITY OF OCCURRENCE
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)
6.0	Console Ramp Motion/Trim Indicator	Refer to Figure 6. Input information source is the ship's Harmonization Computer (SFNC). Instead of the SPN-42 radar, it indicates range motion plus ship's trim in the normal operating mode. A momentary toggle switch on the control panel is used to select ship's trim as a separate display on the Ramp Scale. A Trim lamp below the scale comes on when ship's trim is being selected for display. The area between +10 feet and +20 feet is covered by a red filter to produce a red pointer indication. This is the danger area and warns the ISO of a possible ramp strike. The ramp pointer remains at full scale when the ramp motion exceeds the +20 or -19 feet extremes.	a) No indication	x	-	x	-
			i) Loss of input stimulus to LA20 from console connector J8 (signal) due to signal breakdown in cable W227 or Signal Junction Box Unit 4A.			x	III
			ii) Loss of range & ramp motion signal conditioning circuit board LA20 output.				D
			iii) Loss of DC power supply input voltages to LA4 and LA20 through controls.				

The Ramp Motion Scale is the vertical scale to the left of the PLAT display. The Ramp Motion Computer (SFNC) instead of the SPN-42 radar. It indicates range motion plus ship's trim as a separate display on the ramp scale. The scale is a zero center display. The area between +10 feet and +20 feet is covered by a red filter to produce a red pointer indication. This is the danger area and warns the ISO of a possible ramp strike. The ramp pointer remains at full scale when the ramp motion exceeds the +20 or -19 feet extremes.

When failures occur that affect only the console display of ramp motion/trim information, the ISO will use the HUD display. When a failure occurs that disables both displays, the ISO will depend on the hook to ramp alarm in an auxiliary instrument facility (base console) in the ISO workstation. A red light is illuminated for a ramp condition causing a 7 to 3 ft. hook to ramp clearance and an audible alarm sounds when the clearance is less than 3 ft. This failure mode would, therefore, not significantly affect safety during a given recovery period and it would be corrected before the next one.

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Unprobable; F-Infeasible)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MKI MOD 0 ISO-HUD CONSOLE SYSTEM

TABLE: UNIT 1

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE

DMG. NO./REV.: 620310

NAEC-91-7958

Page 30 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTION MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)		
			PERSONNEL INJURY	SYSTEM LOSS	MISSION LOSS	DETECTABLE LOSS	DETECTION BY OPERATORS	HAZARD LEVEL PROBABILITY	COINCIDENCE LEVEL	HAZARD LEVEL PROBABILITY	COINCIDENCE LEVEL
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)
B.0	(cont'd)	a)	i) connector <u>J4</u> (DC power) provided by Auxiliary Electronics Box and the supplementary DC voltages generated by <u>LA4</u> . iv) Loss of a complete segment of redundant incandescent lamps within <u>LA10</u> indicator assembly. v) Loss of circuit path between <u>LA10</u> indicator assembly and card cage back-plane <u>LA12</u> . vi) Loss of pointer and scale intensity caused by failure (short or high).								

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.J.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.J.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable;
 F-Unpossible)

TABLE: UNIT 1
NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
DNG. NO./REV.: 620310

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MKI MOD 0 LSU-HUD CONSOLE SYSTEM

NAEC-91-7958

NAEC-91-7958

Page 31 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON: PERSONNEL SYSTEM	MISSION	DETERMINATE LOSS BY OPERATOR?	CLASSIFICATION (HAZARD LEVEL)	PROBABILITY OF OCCURRENCE	COMMENTS: RECOMMENDATIONS: COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)		
								DAMAGE	POTENTIAL LOSS	LOSS
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)
8.0	(cont'd)	a) vi) resistance open) within indicator on/off switch IAI7514 and/or indicator intensity potentiometer IAI7R10.								
		b) vii) No trim selection due to shorted or open control switch IAI7S13.								
		b) single unchanged indication, non-linear response or premature limiting less than full-scale.								
		1) Component failure within population of IAI20 signal conditioning board causing geometric non-linearity of load isolation amplifiers	-	x	-	x	-	x	x	x

A malfunction of this variety is extremely unlikely. If it would occur, the ISO would depend on the auxiliary provisions described in item (a) above.

(Failure Modes & Effects Analysis - System) Safety Analysis MIL MOD 0 LSO-HUD CONSOLE SYSTEM

NAEC-91-7958

TABLE: UNIT 1

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE

DNG. NO./REV.: 620310

Page 32 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)			DETECTABLE BY OPERATOR?	FAILURE - HAZARD	COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)		
		EFFECT ON: PERSONNEL	SYSTEM	MISSION			CLASSIFICATION (HAZARD LEVEL)	PROBABILITY OF OCURRENCE	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)
8.0	(cont'd)	b)	i) and/or loss of the analog-to- digital (A/D) con- version which drives the <u>LA10</u> indicator assembly.						(11)
									(12)
									(13)

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (a-Frequent; b-Occasional; c-Remote; d-Extremely Improbable;
 e-Infeasible)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-HUD CONSOLE SYSTEM

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE

DNG. NO./REV.: 620310

Page 33 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	PERSONNEL INJURY	EFFECT ON: SYSTEM	MISSION	DETECTABLE BY OPERATOR?	HAZARD LEVEL (CLASSIFICATION)	PROBABILITY OF OCCURRENCE	COMMENTS: RECOMMENDATIONS; COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)			
									POTENTIAL LOSS	DAMAGE	PROBABILITY OF OCCURRENCE	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
9.0	Console Airspeed Indicator - Refer to Figure 7. The airspeed pointer light over a range of from 30 to 180 knots (0 to 100 points). A trend light of lesser intensity adjacent to the main pointer to indicate either increasing or decreasing airspeed. The trend lamp is one knot less and with decreasing (TAS) or closing airspeed (CLSG) may be chosen for presentation. The selection is made by the letters TIS or CLS; appearing at the right-hand end of the Airspeed scale. In addition either the ship's SPN-44 ACIS radar or its SPN-44 radar can be selected as the source of the airspeed signal. The selection is made by the SPN-42 or SPN-44 toggle switch adjacent to the TAS/CLSG switch. The choice thus made is indicated at the right-hand end of the Airspeed scale by the presence of the number, 4, or the number, 44.	The airspeed scale, located above the PIAT, indicates aircraft airspeed by a moving pointer light with 100 points. Its pointer will stay at 80 knots when the correct value is less than or equal to 80, and will read 180 knots whenever the correct value is equal to or greater than 180. The scale incorporates a trend light of lesser intensity adjacent to the main pointer to indicate either increasing or decreasing airspeed. When the airspeed is increasing, the trend lamp is one knot less and with decreasing (TAS) or closing airspeed (CLSG) may be chosen for presentation. The selection is made by the letters TIS or CLS; appearing at the right-hand end of the Airspeed scale. In addition either the ship's SPN-44 ACIS radar or its SPN-44 radar can be selected as the source of the airspeed signal. The selection is made by the SPN-42 or SPN-44 toggle switch adjacent to the TAS/CLSG switch. The choice thus made is indicated at the right-hand end of the Airspeed scale by the presence of the number, 4, or the number, 44.	a) No indication	-	-	-	-	x	III	D	A malfunction of this variety is remote. However, if it should occur, the ISO will depend on visual contact with the aircraft or its angle of attack lights, the sound of the aircraft's engines (power state) to judge approach speed.	

The SPN-42 airspeed signal is a varying DC stimulus voltage. The SPN-44 is a synchro output. A synchro-to-analog converter is used to convert its output to analog voltage of the same range as the SPN-42.

a) No indication

1) Loss of input stimulus IAI20

from console connector J7

(Synchro) due to signal breakdown in

cable W226 or Synchro Junction Box

Unit 4A2,

II) Loss of cir-

cuitry paths between IAI22

(synchro-to-

analog con-

verter ckt.

airspeed board), IAI23

airspeed signal con-

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Marginal; III-Negligible); Hazard Probability, column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Ocasional; D-Remote; E-Extremely Improbable; F-Impossible).

Failure Modes & Effects Analysis - System) Safety Analysis MK1 Mod 0 ISO-IUD Console System
 Rev. 020310
 Heads-up-Display Console

NAEC-91-7958

Page 34 of 113

ITEM DESCRIPTION (Equipment, Mode of Operation, Function)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON: PERSONNEL SYSTEM	MISSION	DETERMINATE BY OPERATORS?	FAILURE - HAZARD		PROBABILITY OF OCURRENCE (HAZARD LEVEL)	COMMENTS: RECOMMENDATIONS COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)
					POTENTIAL LOSS	INJURY		
(2)	(3)	(4)	(5) (6) (7) (8) (9)	(10)	(11)	(12)	(13)	
(Event 4)	a) (1) ditioning ckt board, and <u>IA2</u> (console airspeed indicator) interconnec- ted via card cage back- plane <u>IA12</u> ,							

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic); II-Critical; III-Marginal; IV-Vegetative;
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.1: A-Probable; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Unprobable;
 F-Inapplicable.

(Failure Modes & Effects Analysis - System) Safety Analysis MK1 MOD 0 LSO-HUD Console System

TABLE: UNIT 1

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE

DWG. NO./REV.: 620310

NAEC-91-7958

Page 35 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)			EFFECT ON: PERSONNEL			FAILURE - HAZARD			COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
		INJURY LIVES	LOSS DAMAGE	POTENTIAL LOSS	MISSION	DETECTABLE BY OPERATORS?	CATASTROPHIC LEVEL	PROBABILITY OF OCURRENCE			
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)
9.0	(cont'd)	a)	<ul style="list-style-type: none"> i) provided by Auxiliary Electronics Box and the supplementary DC Voltages generated by <u>1A4</u>, v) Loss of a complete segment of redundant incandescent lamps within <u>1A2</u> indicator assembly, vi) Loss of air-speed select (TAS/CSC) or radar select (SPN 42/44) indication due to failure of redundant incandescent indicator lamps resident on air-speed indicator lamp board (Deg. 5: 3633) portion of <u>1A2</u> indicator assembly. 								(13)

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable;
 F-Impossibile)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 LSO-HUD CONSOLE SYSTEM

TABLE: UNIT 1

NAME: [Sub-system] HEADS-UP-DISPLAY CONSOLE

NAEC-91-7958

DWG. NO./REV.: 620310 1

Page 36 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD DETECTABLE BY OPERATOR?	PROBABILITY OF CATASTROPHE (HAZARD LEVEL) CATASTROPHE BY LOSS OF OPERATOR?	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
			PERSONNEL INJURY	SYSTEM LOSS	MISSION LOSS			
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)
9.0	(cont'd)	b) No trend indication	-	-	-	x	III	E A malfunction of this variety is extremely unlikely. If it would occur, the sense of direction for changing data would not be as evident, but identifiable by noting the directional movement of the main pointer lamp.
		1) Component failure within the population of the JA23 signal conditioning board in the comparator and latch circuitry where periodically stored A/D output data is compared with current A/D data for the display of sense of direction for changing data.						
		c) Single unchanging indication, non-linear response or premature limiting less than full scale.	-	-	-	x	III	E A malfunction of this variety is extremely unlikely and detectable by the LSO under periodic calibrations which will lead to an appropriate maintenance action. Recognizing the problem, the LSO will depend more fully on the alternate described in item 9(a) above.
		1) Component failure within population of						

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic); II-Critical; III-Marginal; IV-Negligible; Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Ocasional; D-Rare; E-Extremely Unprobable; F-Insignificant).

TABLE: UNIT 1
 NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
 DNG. NO./REV.: 620310

(FAILURE Modes & EFFECTS ANALYSIS - System) SAFETY Analysis_MKL MOD 0 ISO-IUUD_Console System
 NAEC-91-7958

Page 37 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
		HAZARDOUS-FUNCTION FAILURE MODE (HAZARD RELEASE MECHANISM)	PERSONNEL INJURY	SYSTEM LOSS	MISSION DAMAGE	POTENTIAL LOSS	DETECTION BY OPERATORS?	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)
9.0	(cont'd)	c)	1) <u>LA23</u> signal conditioning board causing geometric non-linearity of load isolation amplifiers and/or loss of the analog-to-digital (A/D) conversion which drives the LA2 indicator assembly.	-	-	-	x	IV
		d)	1) Non-select of true airspeed (TAS) or closing airspeed (CLSG). 1) Inoperative control switch <u>LA1789</u> due to internal short, high resistance open, or mechanical fatigue of toggle stem.	-	-	-	x	IV

The ability to alternate between TAS and CLSG is supplemental to the LSO.

NOTE: Hazard Level, Column 11, per MIL-STD-882B, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible); Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Unprobable; F-Inprobable)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 LSD-HUD CONSOLE SYSTEM

TABLE: UNIT 1NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLEDAG. NO./REV.: 620310Page 38 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD PROBABILITY OF OCURRENCE (HAZARD LEVEL) CLASSIFICATION	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
			POTENTIAL LOSS	MISSION LOSS	PERSONNEL INJURY		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)
9.0	(cont'd)	e) Non-select of radar system (ISPN 42/46)	-	-	-	x	IV
		i) Inoperative control switch <u>IA17S10</u> due to internal short, high resistance open, or mechanical fatigue of toggle stem.				x	B

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Tolerable); Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (a-Frequent; b-Rare; c-Very Probable; d-Occasional; e-Remote; f-Extremely Unprobable; f-Inexpressible)

(Failure Modes & Effects Analysis - System) Safety Analysis MK1 MOD 0 LSO-HUD Console System

TABLE: UNIT 1
NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
DNG. NO./REV.: 620310

NAEC-91-7958

Page 39 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)			EFFECT ON:	FAILURE - HAZARD DETECTABILITY BY OPERATORS	PROBABILITY OF OCURRENCE	COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
		POTENTIAL LOSS	INJURY SEAT	MISSION				
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)
10.0	Console Deck Status and FLOLS Wave-Off Status Indicator - Refer to Figure 3. The Airspeed Scale. A green light indicates the deck is open (clear) and ready to land aircraft. An adjacent red light indicates a closed (fouled) deck and any approaching aircraft must not land. With a fouled deck, any aircraft is given a wave-off. The LSO initiates a Fresnel Lens Optical Landing System Wave-Off (FOLLS wave-off) with a "Pitch Switch." The wave-off is indicated by the red flashing lamps below the open and closed deck lamps. The rate is approximately 90 flashes per minute.	-	-	-	-	-	-	-

84 (A-68)

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Inmissible)

(Failure Modes & Effects Analysis - System) SAFETY ANALYSIS MIL MOD 0 LSO-HUD CONSOLE SYSTEM

MAEC-91-7958

TABLE: UNIT 1
 NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
 Dwg. No./Rev.: 620310

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON: PERSONNEL SYSTEM	MISSION	FAILURE - HAZARD						COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES / SAFETY CONTROLS)
					POTENTIAL LOSS	DAMAGE	LOSS	LOSS	DETECTABLE BY OPERATORS?	PROBABILITY OF OCCURRENCE	
(11)	(2)	(3)	(4) (5) (6) (7) (8) (9)	(10) (11) (12)							
10.0 (cont'd)	a)	iii) breakdown in assembly. iv) Loss of DC input voltage (+12v) to <u>1A3</u> from <u>1A4</u> . v) Loss of indication due to failure of redundant indicator lamps resident in the deck status lamp assembly (<u>1A3e2</u>). vi) Wiper lift-off in intensity control potentiometer <u>1A1785</u> .	-	-	-	-	-	-	x	III	d

MAEC-91-7958

This indicator is the only display indicator by which the LSO can verify that his "pickle switch" has initiated the Personnel Lens Optical Landing System (PLOLS) wave-off to signal the pilot on the glide-slope landing approach not to land. PLOLS Wave-Off Monitor Assembly, located aft of the LSO platform, offers a redundant indication that wave-off has been initiated.

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable;
 F-Inexistential).

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS_NKL MOD 01 ISO-HUD CONSOLE SYSTEM

TABLE: UNIT 1

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE

DNG. NO./REV.: 620310

NAEC-91-7958

Page 41 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			PROBABILITY OF DETECTION BY DETECTABLE LOSS	CLASSIFICATION (HAZARD LEVEL), ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
			PERSONNEL INJURY	SYSTEM LOSS	MISSION LOSS	PERSONNEL INJURY	SYSTEM LOSS	MISSION LOSS		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)
10.0	(cont'd)	b)	1) cable W221 and/or Signal Junction Box (Unit 4A1).							
			ii) Loss of <u>LA1A1</u> (deg. 510539) deck status/ ISO wave-off circuit ass- embly lamp drive cause by component breakdown in assembly,							
			iii) Loss of DC input vol- tage (+12v) to <u>LA3</u> from <u>LA4</u> ,							
			iv) Loss of Indi- cation due to failure of redundant indicator lamps resi- dent in the deck status lamp assembly (<u>LA3A2</u>)							

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic); II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Unprobable;
 F-Inconsequential)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MKI MOD 0 LSO-HUD CONSOLE SYSTEM

NAEC-91-7958

TABLE: UNIT 1

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE

DNG. NO./REV.: 620310

Page 42 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD	COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES / SAFETY CONTROLS)
			PERSONNEL INJURY	SYSTEM LOSS	MISSION LOSS		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)
11.0	Console Wind Direction Indicator - Refer to Figure 9. Angle in degrees is indicated by three alpha-numeric characters above the ACLS Status displays. The angle is relative to the centerline of the angled landing deck which is 10.5 degrees to port of the ship's centerline. Therefore, wind down, the centerline of the ship would be indicated on the Console as an S 10.5 wind. Seven-segment, incandescent indicators are also used for these alpha-numeric characters. Approximately 50 can be displayed by the wind angle indicators in either the port or starboard direction. Normal landing operations are conducted with the wind within 10° of the centerline touch-down point.						
	a) No indication	-	-	-	-	x	III D
	1) Loss of input synchro information from console connector J7 (Synchro) due to signal breakdown in cable W226 and/or Synchro Junction Box (Unit 4A2).						
	1.1) Loss of internal console circuitry paths between J7, LA21(synchro-to-analog ckt. board), and LA62 interconnected via card cage back-plane LA12.						

87 (A-71)

NOTE: Hazard Level, Column 11, per MIL-STD-882B, para. 5.4.3.1 (I-Catastrophic); II-Critical; III-Marginal; IV-Negligible; Hazard Probability, Column 12, per MIL-STD-882B, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Unprobable; F-Im-possible)

NAEC-91-7958

(Failure Modes & Effects Analysis - System) Safety Analysis MK1 MOD 0 ISO-HUD Console System

TABLE: UNIT 1

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE

DNG. NO./REV.: 620310

NAEC-91-7958

Page 43 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)			EFFECT ON: PERSONNEL SYSTEM	MISSION LOSS	DETECTABILITY BY OPERATORS?	FAILURE - HAZARD LEVEL	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
		DAMAGE LOSS	INJURY LOSS	POTENTIAL LOSS					
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)
11.0	(cont'd)	a)	iii) Loss of DC power supply input voltages to <u>1A4</u> , <u>1A6A2</u> , and <u>1A21</u> through connector <u>J4</u> (DC power) provided by Auxiliary Electronics Box and the supplementary DC voltages generated by <u>1A4</u> ,						

iv) Loss of Light-Emitting Diode (LED) segments of 7-segment indicators in assembly 1A6A5.

v) Component failure within the population of the 1A21 synchro-to-analog Ckt. board, 1A6A2 wind v. locky wind direct bn.

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Critical); II-Catastrophic; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable; F-Impossible)

TABLE: UNIT 1
 NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLES
 DNG. NO./REV.: 620310

(FAILURE Modes & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MIL MOD 0 LSO/HUD CONSOLE SYSTEM

MSEC-91-7958

Page 44 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	FAILURE - HAZARD			COMMENTS: RECOMMENDATIONS; COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)						
			EFFECT ON:									
			PERSONNEL SMART	SYSTEM	MISSION							
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
11.0	(cont'd)	a)	ckt. board, or <u>LA6A5</u> - the 3-digit wind direction indicator assembly.									
		v.i)	Loss of in- tensity cause by wiper lift-off in intensity con- trol poten- tiometer <u>LA1786</u> or open in con- trol switch <u>LA1788</u> .									
		v.ii)	Loss of DC input voltage <u>(+5)</u> to <u>LA6A5</u> from <u>LA4</u> .									
		b)	Single unchanging indication, non- linear response, or premature latching less than full-scale. i)	-	-	-	-	-	-			
			Component failure with- in populations of <u>LA21</u> and <u>LA612</u> causes the synchro-									

MSEC-91-7958

A malfunction of this variety is
extremely unlikely. If it
would occur, the LSO would notify
Primary Flight of his problem
and they would communicate
information to the LSO. PRI-PF
monitors wind-over-deck on a
routine basis and would ascertain
an unsafe condition that went
undetected by the LSO.

NOTE: Hazard Lev. I, Column 11, ref MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Hazardous; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Unusually Probable; C-Occasional; D-Rare; E-Extremely Improbable;
 F-Inapplicable)

TABLE: UNIT 1
 NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
 Dwg. No./Rev.: 620310

(Failure Modes & Effects Analysis - System) Safety Analysis Mk1 Mod.0 ISO-HUD Console System

NAEC-91-7958

NAEC-91-7958

Page 45 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			PROBABILITY OF OCCURRENCE (HAZARD LEVEL)	COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
			POTENTIAL LOSS	DAMAGE	INJURY	LOSS	DETECTABILITY BY OPERATORS?	LOSS		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)
11.0	(cont'd)	b)	i) to-analog output to skew the 10.5° to port of the center line of the carrier reference compensation (synchro rotation) for the angled landing deck and/or magnitude buffer amplifier non-linearity in the wind angle magnitude display							(13)

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Inpossible)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-HUD CONSOLE SYSTEM
NAEC-91-7958

TABLE: UNIT 1

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE

DNC. NO./REV.: 620310

Page 46 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)			
			POTENTIAL LOSS	DAMAGED LOSS	MISSION LOSS	DETECTABLE BY OPERATORS	CLASSIFICATION (HAZARD LEVEL)	PROBABILITY OF OCURRENCE				
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
11.0 (cont'd)	b)	iii) Failure of test lamp switch 1A17S7 in the closed position causing all seven segment indicator elements to illuminate (resulting output indication will be all 0's).										

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Frequently Probable; C-Ocasional; D-Remote; E-Extremely Improbable;
F=Impossible)

(Failure Modes & Effects Analysis - System) SAFETY ANALYSIS MK1 MOD 0 LSO-IUD CONSOLE SYSTEM

TABLE: UNIT 1

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE

DWG. NO./REV.: 620310

NAEC-91-7958

Page **47** of **113**

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD PROBABILITY OF COINCIDENCE	COMMENTS: RECOMMENDATIONS; COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)
			PERSONNEL INJURY	SYSTEM LOSS	MISSION DAMAGE		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)
12.0	Console Wind Speed Indicator - Refer to Figure 2. The characters are the same type as in the wind angle display. They are capable of 0 to 99 knots indication. The characters are the same type as in the recovery deck.	a) No Indication	-	-	-	x	III

92 (A-76)

**Legend Lax 1, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Marginal; III-Negligible;
F-Insignificant), Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable;**

AD-A083 720


KETRON INC WAYNE PA
HAZARDS/FAILURE MODES AND EFFECTS ANALYSIS MK 1 MOD 0 LSO-HUD C--ETC(U)
MAR 80 F SEVCIK, G S FARBER, W S MANN N68335-78-C-2002


UNCLASSIFIED

2 of 3
AD-A083 720

KTM-1327-01 NAEC-91-7958

NL





(Failure Modes & Effects Analysis - System) Safety Analysis MIL MOD 0 LSO-HUD Console System

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
DNG. NO./REV.: 620310

TABLE: UNIT 1

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE

DNG. NO./REV.: 620310

Page 48 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON: PERSONNEL SYSTEM MISSION	FAILURE - HAZARD			COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)
				DETECTABLE LOSS	POTENTIAL LOSS	PROBABILITY OF (HAZARD LEVEL)	
(1)	(2)	(3)	(4) (5) (6) (7) (8) (9) (10) (11) (12) (13)				
12.0 (cont'd)	a)	<p>i) takes to <u>IA4</u> and <u>IA6A2</u>, and <u>IA21</u> through control connects <u>J4</u> (DC power) provided by Auxiliary Electronics Box and the supplementary DC voltages generated by <u>IA4</u>,</p> <p>iv) Loss of Light-Emitting-Diode (LED) segments of seven segment indicators in assembly <u>IA6A5</u>,</p> <p>v) Component failure with in the population of the <u>IA21</u> synchro-to-analog ckt. board, <u>IA6A2</u> wind velocity/wind direction ckt. board,</p>					

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Critical); III-Marginal; IV-Negligible
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Likely Probable; C-Occasional; D-Rare; E-Extremely Unlikely; F-Inconsequential)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MKI MOD 0 LSO-HUD CONSOLE SYSTEM

TABLE: UNIT 1NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLEDWG. NO./REV.: 620310

NAEC-91-7958

Page 49 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS; RECOMMENDATIONS; COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)		
			PERSONNEL	SYSTEM	MISSION	DETECTABILITY BY OPERATORS	HAZARD LEVEL	PROBABILITY OF OCCURRENCE	LOSS	LOSS	LOSS
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)
12.0	(cont'd)	a)	v)	or <u>1A646</u> - the 2-digit wind speed indicator assembly.							(13)

v1) Loss of intensity caused by wiper lift-off in intensity control potentiometer 1A1746 or open in control switch 1A1758.

v11) Loss of DC input voltage (+5) to 1A612 from 1M

b) single unchanging indication, non-linear response or premature limiting less than full-scale.

i) component failure within the populations of 1A21 and

A malfunction of this variety is extremely unlikely. If it would occur, the LSO would notify Primary Flight of his problem; they would communicate information to the LSO. Any unsafe condition would be ascertainable by PRI-FLY in their monitoring of wind-over-deck conditions.

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible); Hazard Probability, column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Inapplicable).

(Failure Modes & Effects Analysis - System) SAFETY ANALYSIS MK1 MOD 0 ISO-HUD CONSOLE SYSTEM

TABLE: UNIT 1

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
DNC. NO./REV.: 620310

NAEC-91-7958

Page 50 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD	COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
			PERSONNEL INJURY	SYSTEM LOSS	MISSION LOSS		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)
12.0	(cont'd)	b)	1) LAG6 causing the synchro-to-analog output to fail properly drive the leveling operational amplifier, subsequent A/D converters, and seven segment numeric indicator BCD decoders.				
			ii) Failure of test lamp switch 1A1757 in the closed position causing all seven segment indicator elements to illuminate (resulting output indication will be all 8's).				

NOTE: Hazard Level, Column 11, per MIL-STD-882a, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible). Hazard Probability, Column 12, per MIL-STD-882a, para. 5.4.1 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Unprobable; F-Invisible).

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 LSO-MUD CONSOLE SYSTEM

TABLE: UNIT 1

NAME: (sub-system) HEADS-UP-DISPLAY CONSOLE

DRG. NO./REV.: 620310 1

NAEC-91-7958

NAEC-91-7958

Page 51 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS: RECOMMENDATIONS: COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)
			PERSONNEL INJURY	SYSTEM LOSS	MISSION LOSS	DETECTABLE BY OPERATOR?	PROBABILITY OF OCURRENCE (HAZARD LEVEL)		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)
13.0	Console Aircraft Indication - Refer to Figure 9. One alpha and one numeric character below the ACILS status indicators. This display is set up by signals from Primary Flight and is used for verification between the recovery set-up and the aircraft in the glide-slope path to be recovered. Seven-segment, incandescent lamp indicators are used for the alpha-numeric aircraft type characters.	<p>The aircraft type that is being recovered on each rate of descent scale and the intercom station just displayed between the Rate of Descent scale and the Primary Flight and is used for verification between the recovery set-up and the aircraft in the glide-slope path to be recovered. Seven-segment, incandescent lamp indicators are used for the alpha-numeric aircraft type characters.</p> <p>a) No indication</p> <p>i) Loss of DC stimulus from console connector J2 (Aircraft Type Design.) caused by signal breakdown in cable W221 and/or Signal Junction Box (Unit 4A1),</p> <p>ii) Loss of internal console circuitry path between J2 and 1A6A1,</p> <p>iii) Loss of DC input supply (0-5v) to 1A6A1 from 1A1,</p> <p>iv) Loss of DC power supply</p>	-	-	-	-	x	IV D	

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.1.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Invisible)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MKI MOD 0 ISO-HUD CONSOLE SYSTEM

NAEC-91-7958

TABLE: UNIT 1
 NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
 DRG. NO./REV.: 620310

Page 52 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS, (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)			
			POTENTIAL LOSS	DAMAGE	PERSONNEL SYSTEM	MISSION	CROSS-REFERENCE HAZARD LEVEL DETERMINATION BY OPERATOR?					
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
13.0	(cont'd)	a)	iv) Input voltage to <u>LA6A1</u> through con- sole con- nector <u>J4</u> (DC Power).	v) Loss of Light-Emitting-Diode (LED) seg- ments of seven seg- ment indi- cators in assembly <u>LA6A1</u> ,								

NOTE: Hazard Level, Column 11, per MIL-STD-882B, para. 5.4.3.1 (I-Catastrophic; II-Marginal; III-Frequent; IV-Negligible); Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (a-Frequent; b-Reasonably Probable; c-Occasional; d-Remote; e-Estremely Improbable; f-Inmissible).

TABLE: UNIT 1
 NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLES
 DRG. NO./REV.: 620310

(Failure Modes & Effects Analysis - System) SAFETY ANALYSIS MIL-MOD 0 LSO-HUD CONSOLE SYSTEM

NAEC-91-7958

Page 53 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:				FAILURE - HAZARD				COMMENTS: RECOMMENDATIONS; COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)	
			PERSONNEL INJURY	SYSTEM LOSS	MISSION LOSS	POTENTIAL DAMAGE	DETECTABLE BY OPERATORS?	PROBABILITY OF OCCURRENCE	LSO	(11)	(12)	(13)
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
13.0 (cont'd)	a)	vii) Loss of intensity caused by wiper lift-off in intensity control potentiometer <u>1A178e</u> or open in control switch <u>1A178f</u> .	-	-	-	-	x	iv	x			
	b)	Single unchanging, partial, or erroneous indication	1) Component failure within <u>1A6A4</u> indicator assembly causing SCD decoder/drivers to synthesize alphanumeric aircraft type in error. ii) Failure of test lamp switch <u>1A178f</u> in the closed position causing all seven									

98 (A-82)

NOTE: Hazard Level, Column 11, per MIL-STD-882B, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Somewhat Probable; C-Occasional; D-Rare; E-Extremely Unprobable; F-Inmissible)

(Failure Modes & Effects Analysis - System) Safety Analysis MK1 HMD O LSO-HUD Console System

NAEC-91-7958

TABLE: UNIT 1
 NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
 DMG. NO./REV.: 620310

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON: PERSONNEL INJURY	MISSION LOSS	FAILURE - HAZARD DETECTABLE BY OPERATOR?	CLASSIFICATION (HAZARD LEVEL) PROBABILITY OF OCURRENCE	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)		
							POTENTIAL LOSS	DAMAGE	INJURY
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)
13.0	(cont'd)	b)	segment indicator elements to illuminate (resulting output indication will be all 8's).						

NOTE: Hazard Lev. I, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic); II-Critical); III-Marginal; IV-Negligible
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable;
 F-Inaccessible)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 LSO-HUD CONSOLE SYSTEM

TABLE: UNIT 1

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLEDNG. NO./REV.: 620310

NAEC-91-7958

Page 55 of 113

NAEC-91-7958

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARD-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS, ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS
			PERSONNEL	SYSTEM	MISSION		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)
14.0	Console ACLS Status Indicator - Refer to Figure 9. above the aircraft type by backlighted indicators. Mode II is an instrument landing approach and Mode III is a "Talk Down" Lock-On light. The ACLS system generates a wave-off when data off aimed from the computer and radar system or aircraft response to the landing instructions are questionable. The ACLS wave-off signal is displayed as a blue flashing light below the Mode lamps. The flash rate of this wave-off is approximately 180 per minute.	The operating status of the Automatic Carrier Landing System (ACLS) indicates a Lock-On and three modes of operation. Mode I is a full landing. The mode indicators are below the computer and radar system or aircraft response to the landing instructions are questionable. The ACLS wave-off signal is displayed as a blue flashing light below the Mode lamps. The flash rate of this wave-off is approximately 180 per minute.	a) No indication i) Loss of DC stimulus from console connector J2 (Aircraft Type Design.) caused by signal breakdown in cable <u>H221</u> and/or Signal Junction Box (Unit <u>4A1</u>). ii) Loss of internal console sole circuitry path between <u>J2</u> and <u>1A6A1</u> . iii) Loss of DC input voltage (+12v) to <u>1A6A1</u> from <u>1A4</u> ,	- - -	- - -	x x x	IV D If this information is lost, the LSO can be informed via the ship's intercommunication system. Regardless of LSO action, the abort or an aircraft not adhering to flight path is automatic.

NOTE: Hazard Level, Column 11, per MIL-STD-882B, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882B, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Unprobable; F-Impossible)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MKI MOD 0 ISO-HUD CONSOLE SYSTEM

NAEC-91-7958

TABLE: UNIT 1NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLEDwg. No./Rev.: 620310Page 56 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARD-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS, (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)		
			POTENTIAL LOSS	DAMAGE	LOSS	DETECTABLE BY OPERATOR?	CLASSIFICATION	PROBABILITY OF OCCURRING (EST.)			
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)
14.0	(cont'd)	a)	iv)	Loss of redundant incandescent lamps (Lock-On, Mode I-II-II, Wave Off) in indicator assembly <u>IAG13</u> ,							
		v)	Component failure with loss of lamp drive to lock-on and mode indicators and/or an inoperative wave-off flashing multivibrator enable,								
		vi)	Loss of intensity caused by wiper lift-off in intensity control potentiometer IAI7M or open in control switch <u>J4756</u> .								

101 (A-85)

NOTE: Hazard Lev.1, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Critical; II-Marginal; III-Tolerable;
IV-Negligible)
Lazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Ocasional; D-Rare; E-Extremely Unprobable;
F-Impossible)

NAEC-91-7958

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS Mk1 MOD 0 ISO-HUD CONSOLE SYSTEM

TABLE: UNIT:
NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
DWG. NO./REV.: 620310

NAEC-91-7958

NAEC-91-7958

Page 57 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	EFFECT ON:			FAILURE - HAZARD		COMMENT: RECOMMENDATIONS: COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)
		HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	PERSONNEL INJURY	SYSTEM LOSS	MISSION	DETECTABLES BY OPERATORS	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)
15.9	Console PLAT Centerline Camera Monitor - Refer to Figure 10. Landing Air Television monitor (PLAT), which connects to the ship's common center line television camera that monitors the glide-slope approach of the landing aircraft. The picture tube and circuit chassis were separated in order to physically locate them in the available space of the console. Remote controls were brought out to a PLAT control panel located at the extreme right of the Console control panel and includes an on/off switch, contrast, brightness, horizontal hold and vertical hold controls. A parallel power on/off switch, together with a rotary switch located on the chassis and designated J414 permits the selection of either internal or remote operation. The two hold controls are screwdriver adjustable. The monitor panel in addition to the normal chassis controls of brightness and contrast for remote operation permits the monitor to be removed and switched back to normal internal controls for testing and servicing.	a) No raster (no image).	-	-	-	x	IV D
		i) Loss of center-line camera video input to console connector J5 (Video In) caused by discontinuity in cable M22.					
		ii) Loss of primary A-C power input to chassis (power supply assembly J41) caused by breakdown in cable M22 linking the Auxiliary Electronics Box (unit 2) with					

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Inprobable)

(Failure Modes & Effects Analysis - System) Safety Analysis MIL-MOD 0150-IUUD CONSOLE SYSTEM

NAEC-91-7958
TABLE: UNIT 1

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE

DAG. NO./REV. 1 620310

Page 58 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON: PERSONNEL SYSTEM	MISSION	POTENTIAL LOSS	DETECTABLE BY OPERATORS	CLASSIFICATION (Hazard Level)	PROBABILITY OF OCCURRENCE	COMMENTS: RECOMMENDATIONS; COMPENSATING PROVISIONS; ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)				
									(1)	(2)	(3)	(4)	(5)
15.0	(cont'd)	a)											

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible); Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Occasional; C-Ocasional; D-Rare; E-Extremely Improbable; F-Inpossible).

TABLE: UNIT 1
 NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
 DNG. NO./REV.: 620310

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS - MKI MOD 0 ISO-HUD CONSOLE SYSTEM

MPEC-91-7958

NAEC-91-7958

Page 59 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS / RECOMMENDATIONS: (COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)	
			PERSONNEL SYSTEM	MISSION	DETECTABLE BY OPERATOR?	PROBABILITY OF OCURRENCE (HAZARD LEVEL)				
						DAMAGE LOSS	POTENTIAL LOSS	CLASSIFICATION (HAZARD LEVEL)		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	
15.0	(cont'd)	a)	v)	of the video monitor chassis <u>IAB</u> and/or CRT/Yoke assembly <u>IAB</u> causing loss of video drive to CRT, loss of high voltage to CRT anode, or weak deflection current to yoke.	-	-	-	-	II	
		b)	Airborne splintered glass.	-	-	-	-	-	B	
			1) The PLAT CRT and yoke assembly (<u>IAB</u>) must be removed from the console front after the plastic faceplate and its restraining bezel are removed. The unprotected CRT neck can be dealt a glancing blow causing the tube to						• It is recommended that the CRT and yoke be enclosed by a protective cover if the only removal path is through the console front. The cover should be secured to the CRT envelope and provide access for the removal of the high voltage lead and connections to the CRT and yoke.	

(Failure Modes & Effects Analysis - System) Safety Analysis MKI MOD 0.150-HUD CONSOLE SYSTEM

TABLE: UNIT 1
NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
DNG. NO./REV.: 620310

Page 60 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD PROBABILITY OF OCURRENCE	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)
			PERSONNEL	SYSTEM	MISSION		
	LIVES	DAMAGE	POTENTIAL LOSS	LIVES	DAMAGE		
(1)			(4)	(5)	(6)	(7)	(11)
15.0	(cont'd)	b)	(3)	(2)			
			1) Explode causing immediate injury to the maintenance personnel.				

105 (A-89)

NAEC-91-7958

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Hazardous; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Rarely Probable; C-Occasional; D-Remote; E-Extremely Improbable; F-Impossible)

TABLE: UNIT 1
NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
ENG. NO./REV.: 620110

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MCL MOD 0 LSO-HUD CONSOLE SYSTEM

NAEC-91-7958

Page 61 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)			EFFECT ON: PERSONNEL	MISSION	DETECTION BY SENSORS	PROBABILITY OF OCURRENCE (HAZARD LEVEL)	FAILURE - HAZARD COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
		POTENTIAL LOSS	DAMAGE	INJURY					
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)
16.0	Console MOVLAS Repeater - Refer to Figure 11. A MOVLAS repeater is incorporated on the left side of the LSO Console. The Manual Operated Visual Landing Aid System (MOVLAS) is used when the Personnel Landing System is inoperative. The repeater is driven from the ship's MOVLAS source and repeats what the pilot sees for the LSO station. The datum bar is supplied by 6.3V AC for the "meatball" indicators. The "meatball" indicators are vertical bars except for the three lower lamps, which are red indicating danger. The system's +5V DC is common to one side of these lamps and the proper amber or red lamps are turned on by the MOVLAS controller grounding the other lamp terminal. A dual control potentiometer is used to adjust the datum bar and "meatball" intensity. The system has a separate on/off switch to turn it off when not in use. These controls are located on the Console control panel.	a) No indication "meatball", datum bar, or warning lamps.	-	-	-	-	x	IV	D This repeater serves to indicate what the incoming aircraft is shown by the MOVLAS display. If the descending aircraft does not follow the glideslope path, the aircraft deviation will be detected by redundant indicating systems permitting an LSO wave-off command.

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Insignificant)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-HUD CONSOLE SYSTEM

NAEC-91-7958

TABLE: UNIT 1
 NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLES
 DNG. NO./REV.: 620310

Page 62 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- PUNCTUAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON: PERSONNEL SYSTEM	FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
				DAM- AGE	POTEN- TIAL LOSS	PROBABILITY OF OCURRENCE (HAZARD LEVEL, DETERMINED BY OPERATOR?)	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)
16.0 (cont'd)	a)	i) (or loss of 115V A-C to <u>IA1A1</u>),					
		ii) Loss of "meatball" and warning lamp +5 VDC supply voltage caused by failure of ship's +5V DC power supply,					
		iv) Loss of lamp inten- sity caused by viper lift-off in intensity control po- tentiometer <u>IA17R3</u> or open in control switch <u>IA17B5</u> .					

NOTE: Hazard Lev-1, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.2: (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable;
 F-Incredible)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 LSO-HUD CONSOLE SYSTEM

TABLE: UNIT 1
 NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
 DMC. NO./REV.: 620310

NAEC-91-7958

Page 63 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON: PERSONNEL SYSTEM	MISSION LOSS	FAILURE - HAZARD		COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
					DETECTABLE BY OBSERVATION (HAZARD LEVEL)	PROBABILITY OF OCCURRENCE (HAZARD LEVEL)	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)
17.0	Console Intercommunication System - An outlet junction box for a radio phone handset is used to communicate with the pilot in the aircraft glidesope approach path hook to the front bar at the base of the console for convenient access. Several trans-receive channels are available for use with this radio phone handset. A standard, two-station, intercommunication station 21MC (LS-458/SIC) is mounted on the right side of the Console above the control panel. It communicates with Primary Pilot (Pri. Fly) and the Carrier Traffic Control Center (CTCC). All of its controls are on the front and it is powered from the ship's intercom system.	Refer to Figure 12. The LSO operator has two forms of communication available at the console. The radio handset is mounted to the right and below the storage box for the console. The radio handset, along with the "pickle switch" is used to communicate with the pilot in the aircraft glidesope approach path. The radio handset, along with the "pickle switch" is used to communicate with the pilot in the aircraft glidesope approach path. Several trans-receive channels are available for use with this radio phone handset. A standard, two-station, intercommunication station 21MC (LS-458/SIC) is mounted on the right side of the Console above the control panel. It communicates with Primary Pilot (Pri. Fly) and the Carrier Traffic Control Center (CTCC). All of its controls are on the front and it is powered from the ship's intercom system.	(9)	(10)	(11)	(12)	
		a) No communication link. ii) Loss of signal path between 'pri. fly' and 'CTCC' caused by discontinuity in cable W225 and connector J5 (intercom), iii) Operational breakdown within the 21MC (LS-458/SIC) assembly.	-	-	-	X	IV E

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Vegetable)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Impossible)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 LSO-HUD CONSOLE SYSTEM

NAEC-91-7958

TABLE: UNIT 1
 NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
 DNG. NO./REV.: 620310

Page 64 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)			EFFECT ON: PERSONNEL			FAILURE - HAZARD		
		MISSION	SYSTEM	POTENTIAL LOSS	DETECTABLE BY INSTRUMENT	HAZARD LEVEL	PROBABILITY OF OCCURRENCE	COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)
10.0	Console Operating Controls - Refer to Figures 3 and 13 controls are mounted on a control panel directly below the upper display information panel. The console contains indicator pointers, power switching (on/off) of the console and scales. The 21MC intercommunications station contains internal controls - there are no interface controls for it within the console. The console contains an auxiliary interlock switch S1 and three indicators D1, D2, D3. The switch and indicators are part of assembly LA16 and respectively permit the override for testing and maintenance and on, and heater power on.	All controls for the console displays are located on the console front. These controls are mounted on a control panel directly below the upper display information panel. The control panel functions include the power switching (on/off) of the console, indicator pointers, scale reticles, MONIAS, Heads-Up-Display, and the PLAT monitor. The control panel contains the capability to adjust the intensity (bright ness) level for each of the emulsified display indicators 1) Internal controls - there are no interface controls for it within the console. The console contains an auxiliary interlock switch S1 and three indicators D1, D2, D3. The switch and indicators are part of assembly LA16 and respectively permit the override for testing and maintenance and on, and heater power on.	a) Loss of console - and Heads-Up-Display control. 1) Intermittent and/or mal-functioning console indicator pointer and scale intensity caused by open control switching and potentiometer lines between LA17 and the other console and HAD read-out. This initial condition is caused by disconnection/ high pin	-	-	-	-	x	II	D

109 (A-93)

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Critical, II-Catastrophic, III-Marginal, IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent, B-Reasonably Probable, C-Occasional, D-Remote, E-Extremely Unprobable, F-Impractical)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 LSO-HUD CONSOLE SYSTEM

TABLE 1

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE

DNG. NO./REV.: 620310

NAEC-91-7958

Page 65 of 113

NAEC-91-7958

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			PROBABILITY OF OCURRENCE (HAZARD LIKELIHOOD CLASSIFICATION BY OPERATOR)	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)							
			PERSONNEL	SYSTEM	MISSION	(1)	(2)	(3)			(4)	(5)	(6)	(7)	(8)	(9)	
10.0																	

NOTE: The failure mode and cause mechanisms for each control are separately treated on these worksheets.

- b) Loss of control panel backlighting.
- 1) Loss of A-C power input to the control panel edge-lit assembly caused by discontinuity in cable Y22

Loss of panel backlighting will limit the use of the LSO console under subdued ambient light conditions (e.g., stormy weather or night recovery).

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible). Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Ocasional; D-Rare; E-Extremely Improbable; F-Impossible).

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-HUD CONSOLE SYSTEM

TABLE: UNIT 1

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE

DOC. NO./REV.: 6202010

NAEC-91-7958

Page 66 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:	FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)		
				PERSONNEL INJURY	SYSTEM LOSS	MISSION LOSS	DETERMINATE BY CLASSIFICATION (HAZARD LEVEL)	PROBABILITY OF OCURRENCE	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)
18.0 (cont'd)		b)	i) feeding connector J3 (AC Control). ii) Loss of low voltage to edge-lit assembly caused by open in 6.3V A-C transformer <u>MT2</u> , iii) Loss of intensity and/or power caused by wiper lift-off in intensity control potentiometer <u>RA7R</u> or open in control switch <u>IA17S2</u> .						(11)

111 (A-95)

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-VeryUnlikely; C-Occasional; D-Rare; E-Extremely Unlikely; F-Inimpossible)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-HUD CONSOLE SYSTEM

TABLE: UNIT 1
 NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
 Dwg. No./Rev.: 620310

NAEC-91-7958

NAEC-91-7958

Page 67 or 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
		HAZARDOUS-FUNCTION FAILURE MODE (HAZARD RELEASE MECHANISM)	PERSONNEL INJURY	SYSTEM LOSS	MISSION LOSS	HAZARD LEVEL	DETECTION BY OPERATOR?	
(11)	(12)	(3)	(4)	(5)	(6)	(7)	(8)	(10)
19.0	Console Obstruction Lamp - Refer to Figure 14. The obstruction lamp provides a proximity and directional warning to carrier personnel of a non-operating (dark) deployed ISO console. The pedestal assembly actuated by the movement of hydraulic cylinder (part of the hydraulic lifting unit subsystem). The limit switch actuates the obstruction lamp when the HUD console is out of its storage enclosure and capable of orientation for use, but not in use (console main power switch off).	The obstruction lamp provides a proximity and directional warning to carrier personnel of a non-operating (dark) deployed ISO console. The pedestal assembly actuated by the movement of hydraulic cylinder (part of the hydraulic lifting unit subsystem). The limit switch actuates the obstruction lamp when the HUD console is out of its storage enclosure and capable of orientation for use, but not in use (console main power switch off).	-	-	-	x	(11)	(12)

112 (A-96)

The pedestal switch is the single element preventing obstruction lamp energization. Failure of the lamp to illuminate would indicate maintenance for its remedy.

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Marginal; III-Tolerable)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Impossible)

(Failure Modes & Effects Analysis - System) Safety Analysis MK1 MOD 0 LSO-HUD Console System

TABLE: UNIT 1

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE

DAG. NO./REV.: 620310

Page 68 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON: PERSONNEL SYSTEM	MISSION	LOSS DAMAGE	LOSS POTENTIAL	DETERMINANT BY OPERATOR?	CLASSIFICATION (HAZARD LEVEL)	PROBABILITY OF OCCURRENCE	COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES / SAFETY CONTROLS)				
										(1)	(2)	(3)		
19.0											caused by internal 'open' failure condition and/or lack of mechanical depression of this switch by linear cam action of the elevator LSO console (raised by the hydraulic lifting subsystem-Unit 3),			
											III) Loss of power to obstruction lamp circuit caused by failure of console main power control switch 1A17S1 in the 'open' state.			

(NOTE: 1A17S1 is a DPDT switch.)

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic) II-Critical III-Marginal IV-Ineligible
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.2 (A-Frequent) B-Unreasonably Probable C-Ocasional D-Rare E-Extremely Improbable
 F-Insignificant

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 LSO-JNU CONSOLE SYSTEM

TABLE: UNIT 1

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE

DNG. NO./REV.: 620310

NAEC-91-7958

Page 69 of 113

NAEC-91-7958

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS: RECOMMENDATIONS; COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)			
			POTENTIAL LOSS	DAMAGED BY LOSS	DETECTABLE OPERATORS	HAZARD LEVEL	PROBABILITY LEVEL	HAZARD LEVEL				
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
20.0	Console Dehumidification - Refer to Figure 15. The console incorporates a cartridge heater to maintain the inside of the cabinet condensation and equipment corrosion. Two heat sensors, HS1 and HS2 wired in parallel, energize the heater cartridge (located in assembly 1A16) whenever the inside cabinet temperature falls below +90°F. The sensors permit the heater to cycle between +90°F and +95°F.	a) No dehumidification. i) Loss of ship's A-C input power to heater circuitry caused by breakdown in cable W222 feeding console connector J3 (AC/AC Control). ii) Loss of A-C Input to 1A16 assembly feeding heater sensors caused by open interlock switch 1A16S1 contact,	-	-	-	-	-	-	-	IV	D	The failure of 1A16 to provide some degree of dehumidification will be detected during the maintenance cycle - lack of heater energization is indicated by DS3 and 1A16 viewed inside the console.

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic); II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Routine; E-Extremely Improbable; F-Inexpressible)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-HUD Console System

TABLE: UNIT 1

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLES

DNG. NO./REV.: 620310

NAEC-91-7958

Page 70 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS, (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
			PERSONNEL	SYSTEM	MISSION	POTENTIAL LOSS	DETECTION BY DETECTOR	CURRENT LEVEL (HAZARD LEVEL)	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)
20.0	(cont'd)	a)	1.1.1) Loss of heater cartridge power & control caused by failure of both heat sensors (HS1 & HS2).						

115 (A-99)

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-C) catastrophic; II-Critical; III-Marginal; IV-Minorable.
 Hazard Probability, column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent); B-Reasonable; C-Occasional; D-Rare; E-Extremely Improbable;

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MKI MOD 0 ISO-HUD CONSOLE SYSTEM

TABLE: UNIT 1
 NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
 DNG. NO./REV. 1 620310

NAEC-91-7958
 Page 71 of 113
 NAEC-91-7958

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD OCCURRENCE	COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS, ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS					
			PERSONNEL	SYSTEM	MISSION							
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
21.0	Console DC Power Regulators - Refer to Figure 16. Using integrated circuit voltage regulators, the IAC regulator supplies +20V and +5V regulated power supplies in the Auxiliary Electronics Box (Unit 2). These integrated circuit regulators contain built-in temperature-sensing circuitry that safely shuts down the regulator if for any reason it becomes too hot. This protects the device from problems such as short-circuited output and high ambient temperatures, but does not give protection against input voltages that exceed +35 volts. The regulators produce voltages of +15, +12, +8, -6, -15, and a variable output of zero to +5 volts (controlled by control potentiometer J117R0).											
	a) No output - loss of console/IND pointer & scale operation and illumination.		-	x	-	-	x	x	x	x	x	II
	i) Loss of voltage regulator operator caused by breakdown in cable W223 feeding +5, +20, and -20 volts to IAC regulator board assembly in console via connector J14 (DC power),											C
	ii) Loss of +15, +12, and +5											

^a Item 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic); II-Critical; III-Marginal; IV-Negligible)
 Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Impossible)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS_MK1 MOD.0 ISO-IUD_CONSOLE SYSTEM

NAEC-91-7958

TABLE: UNIT 1

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE

DNG. NO./REV.: 620310

Page 72 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS; RECOMMENDATIONS; COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)			
			PERSONNEL INJURY	SYSTEM LOSS	MISSION LOSS	DETECTABLE LOSS	HAZARD OPERATOR?	POSSIBILITY OF CASCADING FAILURE				
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
21.0	(cont'd)	a)	ii) volt out- puts caused by internal failure of <u>VRL</u> , <u>VR2</u> , and <u>VR3</u> IC regulators and/or failure of PS3, the +20 volt power supply in the Aux- iliary Electronics Box (Unit 2), iii) Loss of -6 and -15 volt out- puts caused by internal failure of <u>VR4</u> and <u>VR5</u> IC regulators and/or failure of PS2, the -20 volt power sup- ply in the Auxiliary Electronics Box (Unit 2),									overvoltage protection on each DC line to prevent damage to decoupling and transient protection components and to prevent exaggerated/non-linear indications and/or complete failure of a vital indicator.

NOTE: Hazard Level, column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Ineligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Unprobable;
 F-Inversible)

(FAILURE Modes & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS_MK1 MOD 0 LSD-HUD CONSOLE SYSTEM

TABLE: UNIT 1

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
 DNG. NO./REV.: 620310

NAEC-91-7958

Page 73 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-Failure Mode (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS, ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS		
			PERSONNEL INJURIES	SYSTEM LOSS	MISSION DAMAGE	POTENTIAL LOSS	DETECTABLE BY OPERATORS	HAZARD LEVEL	PROBABILITY OF OCCURRENCE	(11)	(12)
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)
21.0	(cont'd)	a)	iv) Loss of variable zero to +5 volt output caused by Internal component failure in hybrid circuitry and/or failure of PSI, the +5 volt power supply in the Auxiliary Electronics Box (Unit 2).								

118 (A-102)

NOTE: Hazard Level, column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible); Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable; F-Inaccessible).

(FAILURE Modes & EFFECTS Analysis - SYSTEM) SAFETY ANALYSIS MKL N00 0 ISO-HUD CONSOLE SYSTEM

**TABLE: UNIT 1
NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE**

DOC. NO./REV.: 620310

Page 74 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)			EFFECT ON: PERSONNEL	SYSTEM	MISSION	DETECTABLE BY PERSONNEL	CLASSIFICATION (HAZARD LEVEL)	PROBABILITY OF OCCURRENCE	COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES), SAFETY CONTROLS
		LIVES	INJURY	LOSS							
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)
22.0	Console Heads-Up-Display Circuitry - Refer to Figures 7-1 thru 17-5. Elements resident within the ISO console. The display presents a facsimile of the rate of descent, roll motion, and aircraft range information displayed on console indicators <u>IA7</u> , <u>IA10</u> , and <u>IA9</u> , along with an aircraft symbol superimposed on reference crosslines representing the landing deck vertical and horizontal line-up, by condensing input information for presentation on a high intensity cathode ray tube. The image on the face of the CRT is then projected to the combiner glass assembly mounted on top of the console. The process of creating this image on the HUD CRT assembly (<u>IA15</u>), and the HUD CRT Power Supply Assembly (<u>IA14</u>).	The Heads-Up-Display (HUD) is supported by a series of hardware by a series of hardware	The Heads-Up-Display (HUD) is supported by a series of hardware	The Heads-Up-Display (HUD) is supported by a series of hardware	The Heads-Up-Display (HUD) is supported by a series of hardware	The Heads-Up-Display (HUD) is supported by a series of hardware	The Heads-Up-Display (HUD) is supported by a series of hardware	The Heads-Up-Display (HUD) is supported by a series of hardware	The Heads-Up-Display (HUD) is supported by a series of hardware	The Heads-Up-Display (HUD) is supported by a series of hardware	The Heads-Up-Display (HUD) is supported by a series of hardware

The HUD CRT Display Circuit Board produces the dynamic portion of the HUD system while the static portion, the measurement reticle scales and reference cross lines are provided by a replaceable projection lamp system (reference 5.0) and combined with the moving pointers and synthesized aircraft symbol on the combiner glass. The HUD CRT display circuit board produces two types of signals for the CRT deflection signals that produce deflection in the X and Y directions, and a blanking signal that turns off the beam during intervals when a visible trace is not desired. The HUD CRT Display Board takes input data, in the form of analog signal voltages, and processes it into control signals (i.e., blanking signals and analog X and Y deflection signals) for the CRT. Except for the RAM MOTION signal, analog input voltages are obtained from digital-to-analog (D/A) converters that are part of the ship's automatic aircraft landing radar system (SPN-42 radar). The RAM MOTION signal is obtained from the Ship's Harmonization Computer (SHNC). The output signals drive external interface circuits.

The HUD CRT power supply circuit provides the filament voltages, grid voltages (electrostatic focusing), and anode voltage for the CRT. The HUD deflection amplifier provides the deflection current need to drive the CRT tube assembly.

- a) No dynamic presentation-reticle scale information.
- i) Loss of CRT assembly (IA15) operating voltages from CRT power supply assembly (IA14).

The presentation of the IUD is a facsimile of the console and as such is redundant. It would not cause any problem during the recovery. If the glidepath line-up information is lost, it is backed up by the PLAT centerline monitor.

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Minimal; III-Critical; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.1 (P-Frequent; U-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Unprobable; P-Inapplicable.)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-HUD CONSOLE SYSTEM

TABLE: UNIT 1

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE

NAEC-91-7958

DAG. NO./REV.: 620310

Page 75 of 113

NAEC-91-7958

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS: COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
			POTENTIAL LOSS	DAMAGE	MISSION	DETECTION BY OPERATOR?	CLOSESTIGATION (HAZARD LEVEL)	PROBABILITY OF OCURRENCE	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)
22.0	(cont'd)	a)							(11)
									(12)
									(13)

1) Failure of J14 can be caused by loss of D-C Input voltages (+5V and +28V from Unit 2), 115VA-C input voltage from console connector J3 (AC/AC Control), wiper lift-off in HUD CRT intensity control panel potentiometer J14R12, or internal component (sub-assessably) failure within J14 (including wiper lift-off in sub-intensity potentiometer J14R11).

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable;
F-Inapplicable)

(Failure Modes & Effects Analysis - System) Safety Analysis MIL MOD 01 ISO-HUD CONSOLE SYSTEM

TABLE: UNIT 1
NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE

Dwg. No./Rev.: 620310

Page 76 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS; RECOMMENDATIONS; COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)			
			POTENTIAL LOSS	DAMAGED	MISSION	DETECTABLE BY SENSORS	PROBABILITY OF OCCURRENCE	HAZARD LEVEL				
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
22.0	(cont'd)											
			1.1) Loss of CRT assembly (1A15) deflection current caused by loss of D-C input voltages (+20V and -20V from Unit 2) 115V A-C delayed A-C' signal from console connector J3 (AC/AC Control), or loss of drive from HMD CRT display circuit board <u>1A24</u> ,									
			1.1) Loss of synthesized video drive to CRT from HMD CRT display circuit board <u>1A24</u> , caused by loss of D-C input voltages									

NOTE: Hazard Level, column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Unprobable; F-Incredible)

TABLE: UNIT 1
 NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
 DMG. NO./REV.: E20310

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM SAFETY ANALYSIS MK1 MOD 0 LSO-HUD CONSOLE SYSTEM

NAEC-91-7958

Page 77 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS: RECOMMENDATIONS; COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES / SAFETY CONTROLS)
			PERSONNEL INJURY	SYSTEM LOSS	MISSION LOSS	DETECTABILITY (HAZARD LEVEL) BY OPERATOR?	PROBABILITY OF OCCURRENCE (HAZARD LEVEL)	CLASSIFICATION (HAZARD LEVEL)	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)
22.0	(cont'd)	a)	111) (+15V, -15V and -6V from LA4 and +5V from Unit 2), circuitry breakdown between back-plane (LA12) con- nections (input/ output) and LA24, in- ternal com- ponent failure within the population of the HUD CRT display circuit board, or a constant blanking signal caused by a failure within <u>LA12</u> ,						(11)
									(12)
									(13)

122(A-106)

NOTE: Hazard Level, Column 11, per MIL-STD-882B, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882B, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable;
 F-Inapplicable)

TABLE: UNIT 1
NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
DWG. NO./REV.: 620310

(FAILURE Modes & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 LSO-HUD CONSOLE SYSTEM

NAEC-91-7958

Page 78 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
		PERSONNEL INJURY	SYSTEM LOSS	MISSION LOSS	DETECTABLE BY OPERATOR?	Hazard Level CLASSIFICATION	Occurrence Probability	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)
22.0	(cont'd)	a)	iv) short with-in CRT and/or open filament.	-	-	-	x	IV
		b)	Single un-changing indica-tion, non-linear re-sponse, pre-mature limiting less than full-scale, no aircraft symbol, or incorrect reference cross-line divisions.	-	-	-	x	IV
		c)	Non-linear or limited output indication caused by internal failure of component within population of LA24.	-	-	-	x	IV
		d)	Incorrect references cross-lines	-	-	-	x	IV

123 (A-107)

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.1.3.1 (I-Catastrophic; II-Critical; III-Hazardous; IV-Negligible)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Inapplicable)

TABLE: UNIT 1
 NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
 Dwg. No./Rev.: 620310

FAILURE MODES & EFFECTS ANALYSIS - SYSTEM SAFETY ANALYSIS MKI MOD 0 ISO-HUD CONSOLE SYSTEM

NAEC-91-7958

NAEC-91-7958

Page 79 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:		FAILURE - HAZARD		PROBABILITY OF OCURRENCE (HAZARD LEVEL)	COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)
			PERSONNEL INJURY	SYSTEM LOSS	MISSION LOSS	POTENTIAL LOSS		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)
22.0	(cont'd)	b)	11) (distance per division with reference to the electronically generated aircraft symbol) caused by open in control switch JAI/S16.					

124 (A-108)

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Ocasional; D-Rare; E-Extremely Improbable; F-Insignificant)

(Failure Modes & Effects Analysis - System) Safety Analysis MIL MOD 01 SO-HUD Console System

NAEC-91-7958
NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE

UNIT 1

DNG. NO./REV.: 620310

Page 80 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD	COMMENTS: RECOMMENDATIONS: COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES / SAFETY CONTROLS)
			PERSONNEL INJURY	SYSTEM LOSS	MISSION DAMAGE		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)
23.0	<u>Console Back Plate Assembly</u> : The back plate assembly, the console store the PLAT monitor color filters and a protected hold-down fixture in which the Heads-up-Display reticle is mounted.						

1) Airborne splintered glass.

1) The projection lamp, an evacuated 50-watt glass halogen, is protected from the rear only. It can implode if shattered from the front whenever the back plate is removed from the console cabinet for maintenance (Refer to Figure 19).

• RECOMMEND: Wide wire mesh screen be placed over front face to preclude accident during maintenance.

125 (A-109)

NOTE: Hazard Level, Column 1, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible) Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Inconceivable)

NAEC-91-7958

(Failure Modes & Effects Analysis - System) Safety Analysis MKI MOD 0 ISO-HUD Console System

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE

DMG. NO./REV.: 620310

TABLE: UNIT 1

Page 81 of 113

NAEC-91-7958

ITEM DESCRIPTION
(COMPONENT, MODE OF
OPERATION, FUNCTION)

HAZARDOUS-
FUNCTIONAL
FAILURE MODE
(HAZARD RELEASE
MECHANISM)

COMMENTS: RECOMMENDATIONS,
COMPENSATING PROVISIONS
(ACCIDENT PREVENTION MEASURES;
SAFETY CONTROLS)

ITEM NO.		EFFECT ON:		FAILURE - HAZARD		COMMENT: RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)						
		PERSONNEL INJURY	SYSTEM LOSS	POTENTIAL LOSS	DAMGE LOSS							
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
24.0	Heads-up-Display Combiner and Mirror Assembly.	The HUD mirror, a 10-1/2 inch diameter spherical concave reflecting device, projects the dynamic HUD CRT image combined with the static reticle scale upon the inclined 30% transmittance combiner glass. The mirror and combiner are physically situated on top of the console (Reference Figure 2). During transitions from storage to use, the mirror and glass are manually deployed (erected). The mirror is raised into place by initially releasing a securing latch on the console side panel. The deployed mirror is firmly secured with a large diameter knurled knob on the base of vertical arm (Refer to Figure 20).										

126 (A-110)




FIGURE 20. HUD FRONT VIEW

NOTE: Hazard Level: Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Marginal; III-Negligible)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Unprobable; F-Inconsequential)

(Failure Modes & Effects Analysis - System) Safety Analysis MIL MOD 01 SO-HUD CONSOLE SYSTEM

TABLE: UNIT 1NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLEDwg. No./Rev.: 620310

NAEC-91-7958

Page 82 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)
			POTENTIAL LOSS	MISSION LOSS	PERSONNEL INJURY	DETECTION BY OPERATOR?	PROBABILITY OF OCCURRENCE	COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)
24-0	(cont'd) The ocular glass is manually raised to a 45° angle by compressing the two center knobs on the track base, sliding the bottom edge to the rear against a stop, and then assuring that the compressed glass is in place (refer to Figure 22).								

127 (A-111)




FIGURE 21. MID SIDE VIEW

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.2.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rarely; E-Extremely; F-Impossible)

NOTE: I-Catastrophic; II-Critical; III-Marginal; IV-Negligible
 Hazard Probability: Column 12, per MIL-STD-882A, para. 5.4.2.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rarely; E-Extremely; F-Impossible)

(FAILURE Modes & EFFECTS Analysis - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 LSO-HUD CONSOLE SYSTEM

TABLE: UNIT 1

NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE

DNG. NO./REV.: 620310

NAEC-91-7958

NAEC-91-7958

Page 83 of 113

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)			
			PERSONNEL LOSS	SYSTEM LOSS	MISSION LOSS	DETECTABILITY BY OPERATOR?	CASUALTY RATE (HAZARD OCCURRENCE PROBABILITY)	COINCIDENCE RATE				
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
24.0	(cont'd)	a) Airborne splintered glass.	-	x	-	x	-	x	x	x	x	• It is recommended that the following design changes be undertaken:
												(1) Create a sandwich of the combiner glass and a plastic neutral density filter on the observer side of the combiner glass.
												(2) Incorporate a compression pin locking device on the side of the mirror and support assembly base to lock and maintain the support arm in the vertical attitude regardless of the knurled knob tension, and
												(3) Incorporate a compression pin locking device on the spherical mirror hold-down latch.
												ii) Breakage of combiner glass caused by impact of flying debris (including)

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Marginal; III-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable;
 F-Inmissible)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 LSO-IUD CONSOLE SYSTEM
NAEC-91-7958

TABLE: UNIT 1
NAME: (Sub-system) HEADS-UP-DISPLAY CONSOLE
Dwg. No./Rev.: 620310

Page 84 of 113
(Last page of Unit 1)

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD	COMMENTS: RECOMMENDATIONS: COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES / SAFETY CONTROLS)
			PERSONNEL INJURY	SYSTEM LOSS	MISSION DAMAGE		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)
24.0 (cont'd)	a)	i) loose tools during maintenance cycle, iii) Shattering of spherical convex mirror caused by failure/fatigue of hold-down latch and subsequent slapping motion against the cabinet face.					

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic); II-Critical; III-Marginal; IV-Negligible; Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Inmissible)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS: MK1 MOD 0 ISO-IUD_CONSOLE SYSTEM

TABLE: UNIT 2
NAME: (Sub-system) AUXILIARY ELECTRONICS BOX
Dwg. No./Rev.: 620381

NAEC-91-7958

NAEC-91-7958

Page 1 of 8

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	EFFECT ON:			FAILURE - HAZARD			COMMENTS: RECOMMENDATIONS: COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES / SAFETY CONTROLS)
		HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	PERSONNEL SYSTEM	MISSION	DETECTABILITY BY OPERATORS	POTENTIAL OCCURRENCE	HAZARD LEVEL	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)
	<u>INTRODUCTION</u>							
	This segment of the System Safety Analysis focuses on the MK1 MOD 0 Landing Signal Officer's (LSO) Auxiliary Electronics Box depicted as Unit 2 in Figure 1.							
	The Auxiliary Electronic Box contains the D.C power supplies for the LSO Console. This box is located directly below the LSO platform in a small room inside the ship's hull. The Auxiliary Electronics Box is secured to the inner surface of this room. This is the outside skin of the ship. This box also contains a blower with air flow detectors, elapsed time meter, pilot light indicators and a circuit breaker.							
	A description of the Auxiliary Electronic Box's composition is described on the worksheets. Figure 2 illustrates, by use of a block diagram, the input/output connections between each of its elements, their supply voltage requirements, and operating controls.							

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Insignificant)

(Failure Modes & Effects Analysis - System) Safety Analysis MKI MDO HUO Console System

TABLE: UNIT 2
NAME: (Sub-system) AUXILIARY ELECTRONICS BOX
DNG. NO./REV.: 620301

Page 11 of 8

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)			EFFECT ON: PERSONNEL INJURY LIVES	MISSION LOSS	DETECTABLE BY OPERATOR?	PROBABILITY OF OCURRENCE (HAZARD LEVEL)	COMMENTS: RECOMMENDATIONS; COMPENSATING PROVISIONS; ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)					
		LIGHT	INJURY	DEATH										
(1)		(2)		(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)




FIGURE 1
DISPLAY SUBSYSTEM
MKI MDO HUO CONSOLE SYSTEM

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable;
F-Unlikely)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 LSO-JWD CONSOLE SYSTEM


TABLE: UNIT 2
 NAME: (Sub-system) AUXILIARY ELECTRONICS BOX
 DNG. NO./REV.: 620381

NAEC-91-7958

Page 111 of 8

NAEC-91-7958

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)			EFFECT ON: PERSONNEL			MISSION			PROBABILITY OF OCCURRENCE			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS, (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)		
		LIVES	INJURY	LOSS	DETECTION BY OPERATOR?	POTENTIAL LOSS	DAMAGE	LOSS	HAZARD LEVEL	DETECTION BY OPERATOR?	POTENTIAL LOSS	DAMAGE	LOSS	HAZARD LEVEL	DETECTION BY OPERATOR?	POTENTIAL LOSS
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)				



NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Marginal; III-Hazardous)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Unprobable; F-Improbable)

(Failure Modes & Effects Analysis - System) Safety Analysis MIL MOD 0 ISO-HUD CONSOLE SYSTEM


NAEC-91-7958

TABLE: UNIT 2
 NAME: (Sub-system) AUXILIARY ELECTRONICS BOX
 DNG. NO./REV.: 620301

Page iv of 8

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	PERSONNEL INJURY LIVES	SYSTEM LOSS	MISSION DAMAGE LOSS	EFFECT ON:	FAILURE - HAZARD
(1)			(3)	(4)	(5)	(6)	(7)
(2)					(8)	(9)	(10)

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	PERSONNEL INJURY LIVES	SYSTEM LOSS	MISSION DAMAGE LOSS	EFFECT ON:	FAILURE - HAZARD
(1)							
(2)							



133 (A-117)

NAEC-91-7958

FIGURE 2 (cont'd). AUXILIARY ELECTRONICS BOX

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Ocasional; D-Rare; E-Extremely Improbable;
 F-Inapplicable)

(Failure Modes & Effects Analysis - System) Safety Analysis MK1 MOD 0 ISO-HUD CONSOLE SYSTEM

NAEC-91-7958

TABLE: UNIT 2

NAME: (Sub-system) AUXILIARY ELECTRONICS BOX

Dwg. No./Rev.: 620161

Page 1 of 8

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)			EFFECT ON:	FAILURE - HAZARD	PROBABILITY OF OCCURRENCE (HAZARD LEVEL)	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
		POTENTIAL LOSS	DAMAGE LOSS	PERSONNEL INJURY LOSS				
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)
1.0	Auxiliary Electronics Box - Refer to Figure 1. The Auxiliary Electronics Box, Unit 2, contains the D.C. power supplies for the ISO console. The D.C. supplies provide +5 volts (PS1), -20 volts (PS2), and +28 volts (PS3). This box is located below the ISO platform in a small room inside the ship's hull. The auxiliary Electronics Box is secured to the inner surface of this room. This is the outside skin of the ship. This box also contains a blower with air flow detectors, a bypass relay within the assembly prevents rapid on/off power transitions from harming the Heads-Up-Display circuitry and CRT. After the delay period, AC is applied to the assembly cooling fan. This fan is a so safety interlocked via a wind velocity detector so that airflow must exist within Unit 2 to cool its heat dissipating power supplies before AC power is applied to the ISO console main power bus and console dehumidification. The initial and delayed AC power events are indicated on incandescent chassis within Unit 2 and assembly IAI6 located inside the ISO console.	a) Loss of DC power supply output. i) The loss of power supply outputs (PS1 thru PS4) which correlate with a lack of power supply A-C input power caused by a failure of one or several inter-linked time delayed components within Unit 2. The components are, in	-	-	*	*	II	C

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible); Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable; F-Incredible).

- (1) Provide a warning circuit within the ISO console (aural)

• RECOMMENDATIONS:

- (1) Provide a warning circuit within the ISO console (aural)

(Failure Modes & Effects Analysis - System) SAFETY ANALYSIS MKL NOD 0 LSO-HUD CONSOLE SYSTEM

NAEC-91-7958

**TABLE: UNIT 2
NAME: (Sub-system) AUXILIARY ELECTRONIC BOX
Dwg. No./Rev.: 620161**

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS, ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS	
			PERSONNEL LOSS	MISSION LOSS	POTENTIAL LOSSES			
					DAMAGE LOSS			
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	
1.0	(cont'd)	<p>their sequence of turn-on, <u>K1</u> the same Delay Relay, chassis fan <u>B1</u>, air-flow detector switch <u>S1</u>, control relay <u>K2</u>, and circuit breaker <u>CB1</u>.</p> <p>(ii) Loss of power supply output caused by internal component failure within the individual power supply.</p> <p>b) Out-of-Spec Power Supply Output.</p> <p>1) Over-voltage condition caused by</p>	<p>(9)</p> <p>(10)</p> <p>(11)</p> <p>(12)</p> <p>(13)</p>	<p>6 visual) to warn the user that an excursion has occurred which say, or may not, have caused damage that requires the attention of maintenance personnel,</p> <p>(2) Provide individual indicators on the LSO console for each voltage as a confidence indicator ("GO"/"NO-GO"),</p> <p>(3) Provide overvoltage protection for each power supply output to bar against damaging transients,</p> <p>(4) Replace the dependency of the main power control bus on the airflow switch - let loss of cooling airflow energize a warning indicator which coordinates with items (1) and (2), above.</p> <p>c</p>				

135 (A-119)

NOTE: Hazard Level, Column 11, per MIL-STD-882B, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible); Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (h-Frequent; b-Frequent; d-Reasonably Probable; c-Occasional; b-Rare; e-Extremely Unprobable); F-Fire, n-nitrogen

NAEC-91-7958

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-HUD CONSOLE SYSTEM

TABLE: UNIT 2

NAME: (Sub-system) AUXILIARY ELECTRONICS BOX

DMG. NO./REV.: 620381

NAEC-91-7958

Page 3 of 8

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL- FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON: PERSONNEL	MISSION	FAILURE - HAZARD	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)						
						DAMAGED LIVES	DAMAGE LOSS	POTENTIAL LOSS	DETECTABLE BY OPERATOR?	CASUALTY LEVEL (HAZARD CLASSIFICATION)	PROBABILITY OF OCURRENCE	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
1.0	(cont'd)											

- open sensing lines between junction at J1 connector of voltage lines (V+, V-) and sensing lines (S+, S-),
- Under voltage condition caused by shorted voltage and sensing lines at immediate power supply output terminal board,
- Non-regulated power supply output caused by internal failure within power supply.

NOTE: Hazard Level, Column 11, per MIL-STD-882B, para. 5.4.1.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Tolerable)

Hazard Probability, Column 12, per MIL-STD-882B, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Temporary)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS_MKL MOD_0 ISO-HUD_CONSOLE SYSTEM

TABLE: UNIT 2
NAME: (Sub-system) AUXILIARY ELECTRONICS BOX

Dwg. No./Rev.: 620381


Page 4 of 8
(Last page of Unit 2)

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			PROBABILITY OF OCCURRENCE (HAZARD LEVEL)	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
			PERSONNEL	SYSTEM	MISSION	POTENTIAL LOSS	DAMAGE	LOSS		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)
1.0	(cont'd)	c)	No A-C power transmission to Synchro Junction Box (Unit 4A2).	-	-	-	-	-	-	II

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Veillable)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable)
 P=Improbable

TABLE: UNIT 3A1
NAME: (Sub-system) THE RETRACTABLE PEDESTAL ASS'Y
Dwg. No./Rev. 1

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD CLASSIFICATION LEVEL (HAZARD LEVEL)	PROBABILITY OF OCCURRENCE BY OPERATOR?	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES / SAFETY CONTROLS)
			PERSONNEL INJURY	SYSTEM LOSS	MISSION DAMAGE LOSS			
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)
1.0	From the USNABC document, "An Improved LSO (Landing Signal Officer) Work Station for CINX Class Ships," 1 December 1977, the description of the equipment is as follows:	"The retractable pedestal subsystem is a hydraulic lifting system that provides for raised deployment and retracted stowage of the display console. The lift is a double acting, non-rotatable cylinder assembly capable of a 75-inch stroke to accommodate an Atlantic or Pacific Fleet platform installation. Atop the cylinder is the console storage enclosure with a hinged lid. Electrical interlocks are provided in the lift control system to guard against the lift being raised with the lid down. The interface between the rod of the cylinder assembly and the display console is a two-axis panning head for orienting the console. The panning head contains electrical interlocks to prevent retraction of the console when it is misaligned with the storage enclosure. The motor pump unit that will operate the cylinder assembly will be capable of forcing a full stroke in approximately 50 seconds. Integral to the motor pump unit will be the motor controller, zero leakage directional control valves, and all other hydraulic circuit components. The motor controller will provide for three minutes of motor operation before it automatically shuts it down. Remote and local controls of the motor will be provided. Consolidated remote controls for operating the lifting system will be provided on the LSO platform. Also, provisions will be made to raise the lift in the event of a hydraulics or power failure."	HAZARD LEVEL: 1 DETECTION LOSS: 1 POTENTIAL LOSS: 1 HAZARD LEVEL: 1 DETECTION LOSS: 1 POTENTIAL LOSS: 1	HAZARD LEVEL: 1 DETECTION LOSS: 1 POTENTIAL LOSS: 1				



138 (A-122)

The plate, Information deg. 510883-1 (see copy at right) shows the individual units/subunits and their interconnections. We use this information instead of the drawing tree, which is not available.

NOTE: Hazard Level, Column 11, per MIL-STD-882B, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, Column 12, per MIL-STD-882B, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Unprobable;
F-Inconsistent)

(FAILURE Modes & Effects Analysis - SYSTEM) SAFETY ANALYSIS MKI MOD 0 ISO-HUD CONSOLE SYSTEM

TABLE: UNIT 3A1

NAME: (Sub-system) THE RETRACTABLE PEDESTAL
DNG. NO./REV.: _____

MEC-91-7958

Page 2 of 11

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			MISSION	DETECTABLE LOSS POTENTIAL	OPERATOR'S COMPETENCY OF CONTROLLED DEVICE	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS, ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS			
			PERSONNEL INJURY	SYSTEM DAMAGE	LOSS							
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)

1.1.0 PEDESTAL ASSEMBLY (Unit 3A1), deg. 620740-1, composed of "non-rotating cylinder/piston" attached to the bulkhead according to "HMD CYLINDER INSTALLATION," deg. 620739-1, serves to lift or retract the Heads-Up-Display (HMD) Console. The Up/Down movements are enabled by the hydraulic liquid being introduced on one side of the non-rotating piston in the cylinder and relieved from its other side. The ends of these movements are controlled by the two LIMIT SWITCHES, LS1 and LS2.
See sketch at right.

NOTE: Hazard Level, Column 11. per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Hazardous; IV-Negligible Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (a-Frequent; b-Reasonably Probable; c-Occasional; d-Remote; e-Extremely Unprobable; f-Inapplicable)

TABLE: UNIT 3A1

NAME: (Sub-system) THE RETRACTABLE PEDESTAL

Dwg. No./Rev.: :

(FAILURE Modes & EFFECTS Analysis - SYSTEM) SAFETY Analysis MK1 MOD 0 LSO-HUD CONSOLE SYSTEM

NAEC-91-7958

NAEC-91-7958

Page 3 of 11

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTION MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)		
			DETECTABLE BY OPERATOR?		DETECTABLE BY MAINTENANCE TECHNICIAN		PROBABILITY OF OCURRENCE				
			POTENTIAL LOSS	DAMAGE LOSS	INJURY LOSS	LIVES LOSS	MISSION	PERSONNEL			
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)
1.1.1	SUPPORT, CYLINDER, misc. dwg. No. 04076, provides the attachment of the Hydraulic Cylinder to the bulkhead.	Cylinder support is not a part of the LSO-HUD SYSTEM therefore, no analysis provided.									(13)

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Impossible)


(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MIL-MOD-01 ISO-HUD CONSOLE SYSTEM

TABLE: UNIT 3A1
NAME: (Sub-system) THE RETRACTABLE PEDESTAL
Dwg. No./Rev.: _____

Page 4 of 11

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:		MISSION	POTENTIAL LOSS	DETECTABLE BY OPERATORS?	PROBABILITY OF OCCURRENCE (HAZARD LEVEL)	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS, (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)
			PERSONNEL SYSTEM	SIGHT					
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)
1.1.2 CYLINDER, dwg. 620728-4 (Calliano Henning Nopak, Inc. dwg. D-4178SK)	Is the assembly of the Hydraulic Cylinder with its Piston that is attached to the SUPPORT, and provides for the lifting and retracting of the HAD Console, which is attached by its Panning Head to the (upper end of the) Piston's Panning Head Adapter.		(11)	(12)	(13)				

See sketch at right.



NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Tolerable)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Unprobable; F-Infeasible)

TABLE: UNIT 3A1

NAME: (Sub-system) THE REFRACTABLE PEDESTAL

Dwg. No./Rev.: _____

(Failure Modes & Effects Analysis - System) Safety Analysis MK1 MOD 0 ISO-HUD Console System



NAEC-91-7958

Page 5 of 11

NAEC-91-7958

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	EFFECT ON:			FAILURE - HAZARD			COMMENTS: RECOMMENDATIONS! COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)
		HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	PERSONNEL INJURY	SYSTEM LOSS	MISSION LOSS	DETECTION BY OPERATOR?	CLASSIFICATION (HAZARD LEVEL)	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)
1.1.2.1	ROD HEAD WELMENT, item No. 1 of the CYLINDER, vendor's dog-D-4178SK, serves as the upper attachment of the CYLINDER to its SUPPORT, and also provides a hydraulic closure at the upper end of the CYLINDER. See sketch:	a) Possibility of injury by the sharp corners. b) Possibility of cracks from the stress concentration in the two corners for lack of round fillet.	x	x	x	x	III	C
							II	D
							II	D
							III	B

142(A-126)



NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable; F-Impractical)

TABLE: UNIT 3A1
 NAME: (Sub-system) THE RETRACTABLE PEDESTAL
 Dwg. No./Rev.:

FAILURE Modes & Effects Analysis - SYSTEM SAFETY ANALYSIS MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)



MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Ocasional; D-Remote; E-Extremely Unprobable; F-Impossible)

Page 6 of 11

MIL-STD-882A, para. 5.4.3.2

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			MISSION LOSS	DETECTABLE BY OPERATORS?	HAZARD LEVEL PROBABILITY OF OCCURRENCE	FAILURE - HAZARD COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)			
			PERSONNEL INJURY	SYSTEM DAMAGE	MISSION LOSS							
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
1.1.2.2	PISTON ROD, item 4 of the CYLINDER 620728-4, vendor's dng-C-2202AC1, provides the attachment for the PANNING HEAD at its upper end and the smooth surface on its OD and attachment of PISTON on its lower OD and BEARING SLIDE at its lower end, inside.	a) Danger of cracks in the weld or in the tubing next to the weld, due to: 1) Grossly unequal cross sections of the two pieces to weld. 11) Lack of a Radius specified in the fillet in the tubing next to the weld. b) Possibility of contamination of the hydraulic fluid by burrs created by the intersecting drilling of the air purging hole(s).	(x)	x	x	No	III	D	• RECOMMENDATION: Arrange with the vendor (G.H. Nopak, Inc.) to specify ample radii in all fillets, especially those that could cause stress concentration, and to pre-machine the round Stock to prepare it better for the welding to the tubing. See sketch below (end of this page).			

NAEC-91-7958



NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Ocasional; D-Remote; E-Extremely Unprobable; F-Impossible)

TABLE: UNIT 3A1
NAME: (Sub-system) THE RETRACTABLE PEDESTAL
DWG. NO./REV.: 1

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-HUD_Console System

NAEC-91-7958

NAEC-91-7958

Page 7 of 11

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)
		HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	PERSONNEL SYSTEM	MISSION	DETECTABILITY BY OPERATOR?	POTENTIAL LOSS	HAZARD LEVEL (HAZARD RELEASE MECHANISM)	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)
1.1.2.3	TUBE WELDMENT, Item 13 of the CYLINDER 620728-4, vendor's deg. C-22025C7, provides the connection between the lower and upper Heads-Attachments to the SUPPORT, and forms the cylinder, in which slides the PISTON. The inside of this carbon steel material (C1026) is electro-Nickel plated (0.002 in., 0.001 in.) and chrome-plated (0.00025Ct).	No safety problem found originating in/from this part.						

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable;
F-Invisible)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MKI MOD 0150-HUD CONSOLE SYSTEM
NAEC-91-7958

TABLE: UNIT 3A1
NAME: (Sub-system) THE RETRACTABLE PEDESTAL.
DNG. NO./REV.: _____

Page 8 of 11

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS - FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			MISSION LOSS	DETECTABLE BY OPERATOR?	CLASSIFICATION (HAZARD LEVEL)	PROBABILITY OF OCCURRENCE	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES), SAFETY CONTROLS
			PERSONNEL INJURY	SIGHT	POTENTIAL LOSS					
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)
1.1.2.4	STOP TUBE, item 15 of the CYLINDER 620728-4, vendor's deg. A2029CY, serves as a stop for the uplift: Its upper face will get in contact with the lower face of the ROD HEAD WELDMENT.	Possible "hard" stop when the STOP TUBE "hits" the ROD HEAD, particularly with the hydraulic liquid above the piston missing. This could result in cracks and peeling in/of the Chrome plating of the TUBE (cylinder).	x	x	x	x	x	x	x	C

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (1-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Fairly Probable; C-Ocasional; D-Rare; E-Extremely Improbable; F-Inmissible)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-IHUD CONSOLE SYSTEM

TABLE: UNIT 3A1

NAME: (Sub-system) THE RETRACTABLE PEDESTAL



DWG. NO./REV.: _____

NAEC-91-7958

Page 9 of 11

NAEC-91-7958

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD PROBABILITY OF DETECTION BY OPERATOR?	COMMENTS, RECOMMENDATIONS: COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
			POTENTIAL LOSS	DAMAGE LOSS	PERSONNEL INJURY		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)
1.1.2.5	BLIND HEAD WELDMENT & ROD, item 21 of the CYLINDER 620728-A, vendor's dwg. C-22022CY, serves as the lower attachment to the SUPPORT and the ROD serves as the non-rotating base for the PISTON movements.	a) Possibility of injury by the sharp corners of the PLATE. b) Possible crack due to stress concentration in the sharp fillet (no Radius specified, even though it is drawn as round).	x	x	x	x	III C



NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Tolerable)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable; F-Im Possible)

TABLE: UNIT 3A1
NAME: (Sub-system) THE RETRACTABLE PEDESTAL.
DNG. NO./REV.: _____


(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MIL MOD 0 ISO-HUD CONSOLE SYSTEM

NAEC-91-7958

Page 10 of 11

NAEC-91-7958

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			MISSION	FAILURE - HAZARD	COMMENTS: RECOMMENDATIONS (COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)
			POTENTIAL LOSS	DAMAGED	LIVES			
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)
1.1.3	LIMIT SWITCH, dng. 620728-5, provided by MICRO SWITCH, their dng. 34BN11-6 (CM). Two of these switches are used, LS1 and LS2 for the lower and upper end of the piston strokes, limiting the lift and retraction of the Retractable Pedestal. See sketches below:	a) Possibility of misadjustment due to accumulated debris interfering between the cam and the Roller of the Switch. b) Possible danger of damage due to overtravel in the Limit Switch's Arm due to forced overtravel beyond the 45° (interfering debris between the Roller and the Cam).	x	x	x	x	Yes	III



147 (A-131)

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic); II-Critical; III-Marginal; IV-Negligible
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely improbable; F-Inconsequential)

(Failure Modes & Effects Analysis - System) Safety Analysis MK1 MOD 0 ISO-MUD Console System

TABLE: UNIT 3A1

NAME: (Sub-system) THE RETRACTABLE PEDESTAL

DWG. NO./REV.: :

NAEC-91-7958

Page 11 of 11

NAEC-91-7958

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD LEVEL	PROBABILITY OF OCCURRENCE	CLASSIFICATION	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)
			PERSONNEL	SYSTEM	MISSION				
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)
1.1.4	CABLE CLAMP ASSEMBLY 516987-1 provides the support of all electrical cables leading to the HDD Console.	Possible danger of the insulation of some of the electrical cables to be cut through by the sharp edges of the HALF CLAMPS 620757-1 and 620757-2, and the ensuing electrical shorts and/or shocks.	*	*	*	*	*	Yes	III
									C
									• RECOMMENDATION: Provide the two existing rubber inner pads 516987-2 to "overhang" the length of the Half Clamps; also, provide a 45° chamfer or round the inner edges of the Half Clamps.

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Inexpressible)

F-Frequent

FAILURE MODES & EFFECTS ANALYSIS - SYSTEM SAFETY ANALYSIS MKI MOD 0 ISO-HUD CONSOLE SYSTEM


NAME: UNIT 3A2
 NAME: (Sub-system) THE HYDRAULIC POWER PACKAGE

DIAG. NO./REV.: 620578-1

Page 1 of 14

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)
		POTENTIAL LOSS	DAMAGE TO PERSONNEL	MISSION	POTENTIAL LOSS	DAMAGE TO PERSONNEL	MISSION	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(11)

1.2.0 HYDRAULIC POWER PACKAGE (Unit 3A2) provides and distributes the hydraulic liquid pressure to cause its lift or retraction as needed. See the Schematic below and sketch at right.



NAEC-91-7958

NOTE: Hazard Lvl. I, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Likely; E-Extremely Unprobable; F-Inprobable)

TABLE: UNIT 3A2
 NAME: (Sub-system) THE HYDRAULIC POWER PACKAGE
 DWG. NO./REV.: 620578-1

(Failure Modes & Effects Analysis - System) Safety Analysis MK1 MOD 0 ISO-HUD Console System

MAEC-91-7958

MAEC-91-7958

Page 2 of 14

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS! RECOMMENDATIONS! COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)			
			PEOPLE/PERSONNEL	SYSTEM	MISSION	DANGER LEVEL	DETECTION BY OPERATOR?	PREDICTABILITY OF OCCURRENCE				
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
1.2.1	TANK 620579-1 provides not only the storage for the hydraulic liquid, but also serves as a frame basis for Hydraulic Power Package Assembly, which is assembled on top of the tank.	a) Possibility of a discontinuity in the Suction column of the Pump, due to leaks. This arrangement explains the existence of the two Tank Covers on its sides.	(x)	(x)	x	x	Yes	III	III	C	Periodic checks on the operation of the System will indicate the incipient failures due to leaks. That in combination with the maintenance drills will keep the System in good operating condition.	

150 (A-134)

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Unprobable; F-Incredible)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-HUD Console System

NAEC-91-7958

TABLE: UNIT 3A2
 NAME: (Sub-system) THE HYDRAULIC POWER PACKAGE
 DMG. NO./REV.: 620578-1

Page 3 of 14

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES/ SAFETY CONTROLS)			
			PERSONNEL INJURY	SYSTEM LOSS	MISSION LOSS	DETECTABLE BY OPERATOR?	ELASCIFFICATION (HAZARD LEVEL)	PROBABILITY OF OCCURRENCE				
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
1.2.2	PUMP, 510893-1, rated 13GPM at 1200 RPM/8.8HP input, max operating pressure 1,000 psi, provides the flow/pressure of the hydraulic fluid from the Tank to the Directional Control Valve and the lower or upper side of the Hydraulic Cylinder Piston to lift or retract the Heads-Up Display Console.	Possible damage-failure of the Pump due to inadequate filtration of the hydraulic liquid in the suction: the Pump vendor (Vickers) recommends 10μ. Note 1P on the Pump dwg. 510893 specifies 25μ or less, but the Piping Ass'y. dwg. 620582-6 specifies Filter element Vickers P/N 361739, which is 70μ according to Vickers' info. but 149μ according to Hydraulic Schematic dwg. 510896.		x		Yes	III	C	• RECOMMENDATION: Re-evaluate the filtering arrangement and specify the correct filter element for 620582-6.			

NOTE: Hazard Lev. I, Column 11, per MIL-STD-882A, para. 5.4.1.1 (I-Catastrophic; II-Critical; III-Material; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Likely; C-Occasional; D-Rare; E-Extremely Improbable;
 F-Invisible)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 LSO-HUD CONSOLE SYSTEM

TABLE: UNIT 3A2

NAME: (Sub-system) THE HYDRAULIC POWER PACKAGE

DWG. NO./REV.: 620578-1

NAEC-91-7958

Page 4 of 14

NAEC-91-7958

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:		FAILURE - HAZARD LEVEL (HAZARD BY OPERATOR)	PROBABILITY OF OCCTRIDIENCE	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES / SAFETY CONTROLS)
			POTENTIAL LOSS	MISSION			
			DAMAGE LOSS	PERSONNEL SYSTEM			
(1)			(4)	(5)	(6)	(7)	(10)
(2)			(3)		x	x	(11)
(1.2.3)	MONITOR, AIR, chg. 518913-1, with the Hydraulic Pump connected by the Flexible Coupling form the redundant arrangement to supply the necessary Hydraulic Fluid flow and pressure to the Hydraulic Cylinder. In case the main Hydraulic Pump with its Electric Motor and Flexible Coupling would fail.	a) The Air Motor could be driven by the compressed air without a load from the Pump (in case the Pump could not suck the H. Fluid from the Tank). In which case the Air Motor could be damaged. b) The air exhaust could get clogged by frozen condensed moisture.		x	x	x	(12)
				x	x	x	(13)

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Unprobable; F-Invisible)

(Failure Modes & Effects Analysis - System) Safety Analysis MK1 MOD 0 ISO-HUD Console System

TABLE: UNIT 3A2

NAME: (Sub-System) THE HYDRAULIC POWER PACKAGE

DMG. NO./REV.: 620578-1

NAEC-91-7958

Page 5 of 14

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
			POTENTIAL LOSS	MISSION DAMAGE	PERSONNEL SYSTEM SEVES	DETECTABLE BY LOSS	CLASSTIFICATION BY HAZARD LEVEL	PROBABILITY OF OCCURRENCE	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)
1.2.4	PRESSURE SWITCH, deg. C403741-27 is a double pole, single throw electrical switch, actuated by a push rod from the power element (stainless phosphor bronze bellows) adjusted to close the NO contacts at 20 PSI pressure (increasing) in the Hydraulic Pump outlet.	<p>a) Power element leaks - possible contamination of the contacts and of the Junction Box by the H. fluid.</p> <p>The closure of these contacts will light up the green light L1 "Pump Running" on the Panel.</p>	x	x	x	x	No	III	D
		<p>b) Power element torn - the Pressure Switch does not function.</p> <p>c) Non-conductive contamination on (one of the) contacts.</p> <p>d) A short betw. the contacts.</p>	x	x	x	x	Yes	III	E
							Yes	IV	C
							Yes	IV	D
									The green light L1 would not light up, at most, but the System would be functioning.
									The green light L1 would be "on" as long as the System is "on", but the System would be functioning.

153 (A-137)

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Inexpressible)

(Failure Modes & Effects Analysis - System) Safety Analysis MIL-MOD-01SO-HUD CONSOLE SYSTEM

TABLE: UNIT 3A2

NAME: (Sub-system) THE HYDRAULIC POWER PACKAGE

MEC-91-7958

DNO. NO./REV.: 620578-1

Page 6 of 14

NAEC-91-7958

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HARMONIC FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD CLASSIFICATION TO ALLIED PROBLEMS			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)		
			PERSONNEL LOSS	SYSTEM LOSS	MISSION LOSS	DIRECTIVE BY OPERATOR?	PERMIT GRANTED CLASSIFICATION	PROBLEMS TO ALLIED PROBLEMS	(11)	(12)	(13)
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)
1.1.5	VALVE, SHUT-OFF, Aug. 424336-1, provides the connection/disconnection of the Hydraulic Liquid Pressure Gage 620578-2.	a) Inlet leak b) Blocked closed					Yes	IV	D	No real problem present. The fact that the (soft) seat will get worn and will leak will be handled by the maintenance, and the fact that the closing of the Valve will be hardly noticed on the Pressure Gage will be of little consequence.	

154 (A-138)

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (I-Frequent; II-Occasionally Probable; C-Occasional; D-Rarely Improbable; F-Improbable)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-HUD CONSOLE SYSTEM

NAME: UNIT 3A2

NAME: (Sub-system) THE HYDRAULIC POWER PACKAGE

DMG. NO./REV.: 620578-1


Page 7 of 14

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS, ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS						
			PERSONNEL INJURY	SYSTEM LOSS	MISSION DAMAGE								
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)	(14)
1.2.6	RELIEF VALVE 517792-1, on the Panel above the Pressure gage, enables the adjustment of the operating pressure of the hydraulic fluid in the system (200 Psi).	a) Contamination entering the Relief Valve with the hydraulic fluid, the unit requires filtration 25 micron or less (note 1.9 of the deg. 517792-1), but it receives the fluid filtered to 149 micron (according to Hydraulic Schematic 5188986).		x	x	x	x	x	x	x	x	x	x

155 (A-139)

One possible way could be by changing the connection as shown in the following HYDRAULIC schematic:

FROM:



NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic); II-Critical; III-Marginal; IV-Ineligible; Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Ocasional; D-Rare; E-Extremely Unprobable; F-Infeasible)

P - Infeasible

(FAILURE Modes & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-HNU CONSOLE SYSTEM

UNIT 3A2

TABLE: (Sub-system) THE HYDRAULIC POWER PACKAGE

NAME:

DNG. NO./REV. : 620578-1

NAEC-91-7958

NAEC-91-7958

Page 8 of 14


ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)		EFFECT ON: PERSONNEL SYSTEM		FAILURE - HAZARD DETECTABLE BY OPERATORS?		PROBABILITY OF OCURRENCE (HAZARD LEVEL) ESTIMATION	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS, (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
		POTENTIAL LOSS	DAMAGE LOSS	INJURY LOSS	MISSION LOSS	DAMGE LOSS	INJURY LOSS		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)
1.2.6	(cont'd) RELIEF VALVE	b) Contamination, entering the Relief Valve through its open Vent opening.		x	x		x	Yes	III
									C
									• RECOMMENDATION: Provide a connection (tube) between the Vent opening and the top of the tank, or plug the vent connection in the valve.
									(11)

156 (A-140)

NOTE: Hazard Level, Column 11, per MIL-STD-882B, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Impossible)

TABLE: UNIT 3A2
 NAME: (Sub-system) THIS HYDRAULIC POWER PACKAGE
 DNG. NO./REV.: 620578-1

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)				EFFECT ON: PERSONNEL SYSTEM	MISSION	FAILURE - HAZARD	COMMENTS; RECOMMENDATIONS; COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES) SAFETY CONTROLS
		LINES	INJURY	LOSS	POTENTIAL LOSS				
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)
1.2.7	DIRECTIONAL CONTROL VALVE, 518898-1, directs the flow of the Hydraulic Fluid, under pressure, to the Hydraulic Cylinder for lifting or retracting of the HUD, and allows the H. Fluid from the other side of the H. Cylinder to flow back to the Tank "without pressure."	a) The Control Valve, without failing itself, will send the HUD down even if the HUD would be "ASKEW", if the LS2 Limit Switch would fail to return to its normal position (at the 10 inch above the "Box" HUD going down)		x		(x)	Yes	11	C,D



NOTE: Hazard Lev. I, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic); II-Critical; III-Marginal; IV-Negligible). Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Unprobable; F-Inapplicable).

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-HNU CONSOLE SYSTEM

UNIT 3A2

NAME: (Sub-System) TIRE HYDRAULIC POWER PACKAGE

DNC. NO./REV.: 620578-1

NAEC-91-7958

NAEC-91-7958

Page 10 of 14

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	EFFECT ON:			FAILURE - HAZARD DETECTION BY OPERATORS?	PROBABILITY OF OCURRENCE HAZARD LEVEL (CLASSIFICATION LOSS)	COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)
		PERSONNEL	SYSTEM	MISSION			
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)
1.2.7	(Cont'd) DIRECTIONAL CONTROL VALVE	b) No further hazardous modes detected in the normally maintained system.		Yes	III	II	E
1.2.8	PIPING ASSEMBLY 620582-1 shows and specifies the pipes and tubing with their connections, filters, check valves and attaching parts, as needed for the Hydraulic Power Package.		x	x	II	C	• RECOMMENDATION: Re-evaluate the filtering arrangement and specify the correct filter element for 620582-6. (Same recommendation as that in item 1.2.2).
1.2.8.1	FILTER ELEMENT 620582-6, for filter enclosure 516965-1, is the Vickers' Part Number 361739 (Vickers Div. of SPERRY RAND). This filter is in the Hydraulic Pumps' Section, good for 149 micron filtration according to 516896.	Possible damage to the H. Pumps due to inadequate filtering.	x	x	II	C	

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable; F-Impossible)

(FAILURE Modes & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-HUD CONSOLE SYSTEM

NAEC-91-7958

TABLE: UNIT 3A2
 NAME: (Sub-system) THE HYDRAULIC POWER PACKAGE
 DMG. NO./REV.: 620578-1

Page 11 of 14

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON: PERSONNEL SYSTEM	FAILURE - HAZARD		COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)
				DETECTABLE BY OPERATOR?	DETECTABILITY OF OCURRENCE	
(1)	(2)	(3)	(4)	(5)	(6)	(7)
1.2.6.2	FILTER 518897-1 with its FILTER ELEMENT 424337-1 (possibly SCHROEDER 8405. CORP Dg-30-10C210) Provides filtering of the Hydraulic Fluid to 10 microns, and has a by-pass valve and the pointer Dirt Alarm.	Possibility of the by-pass valve being open and letting some unfiltered H. Fluid to flow to the Directional Control Valve. NOTE: The visible Dirt Alarm pointer could be overlooked!		x	x	III D However, we present the following, due to the possibility of the human forgetfulness: • RECOMMENDATIONS: a) Provide also electrical Dirt Alarm (available in this line of filters). b) Provide enough room for easy/quick replacement of the Filter Element. c) Show the Dirt Alarm pointer and scale of this Filter on the assembly drawings: 620582-1 (Piping Assy) & 620578-1 (Hydraulic Power Package).

NOTE: Hazard Level, Column 11, per MIL-STD-883A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable; F-Impossible)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-HUD CONSOLE SYSTEM

TABLE: UNIT 3A2

NAME: (Sub-System) TUB HYDRAULIC POWER PACKAGE


Dwg. No./Rev.: 620578-1

NAEC-91-7958

NAEC-91-7958

Page 12 of 14

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:		FAILURE - HAZARD		PROBABILITY OF OCCURRENCE (HAZARD LEVEL)	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS, (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
			PERSONNEL	SYSTEM	MISSION	DAMAGE		
			LOSS	LOSS	POTENTIAL LOSS	LOSS		
(11)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)
1.2.8.3	TUBING 620582-5 with the FILTER 516965-1 forms a relatively heavy and extended subassembly, held at two points. See sketch.	Possibility of cracks at the lower end(s) of the tubing, due to induced vibrations -- the cracks would produce leaks (air into the H. Pump Suction while the Pump is running, and causing a discontinuity in the suction column when the Pump is not running).		x	x	x	Yes	II
								B
								• RECOMMENDATION: Provide a tie between the upper end (the Filter 516965-1) and the Support Frame 620581-1 to eliminate or greatly reduce the vibration of the Filter.



160 (A-144)

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.J.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Frequent; C-Occasional; D-Remote; E-Extremely Improbable; F-Impossible)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MKI MOD 0 LSU-HUD CONSOLE SYSTEM

TABLE: UNIT 3A2
 NAMES: (Sub-system) THE HYDRAULIC POWER PACKAGE
 DMG. NO./REV.: 620578-1

NAEC-91-7958

Page 13 of 14

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD	COMMENTS: RECOMMENDATIONS; COMPENSATING PROVISIONS; ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS					
			PERSONNEL	SYSTEM	MISSION							
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
1.2.9.0	ELECTRICAL INSTALLATION, 620583-1 shows and specifies the electrical connections (cables), as well as it provides the wiring diagram for the Hydraulic Power Package 620578-1.											
1.2.9.1	ELECTRICAL MOTOR STARTER, 518910-1 provides the starting/stopping of the Electric Motor/H. Pump. It is equipped with protections (undervoltage, motor overload and pilot circuit) and a timer (set for three minutes - which is ample time, considering the HMD is lifted in about 60 seconds).		No problems expected in a reasonably-care-for assembly.									
							Yes	III	D			

161(A-145)

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Ineligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Insignificant)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-HUD CONSOLE SYSTEM

TABLE: UNIT 3A2
 NAME: (Sub-system) THE HYDRAULIC POWER PACKAGE
 DNG. NO./REV.: 620578-1

NAEC-91-7958

NAEC-91-7958

Page 14 of 14

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			PROBABILITY OF OCCURRENCE (HAZARD LEVEL)	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
			PERSONNEL	SYSTEM	MISSION	DAMAGE	POTENTIAL LOSS	LOSS		
LIVES	INJURY	LOSS	LOSS	LOSS	LOSS	LOSS	LOSS	LOSS	LOSS	LOSS
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)
1.2.9.2	ELECTRIC MOTOR, 518894-1, is a 440VAC, 60Hz, 3-phase, 10HP at 1160RPM full-load, 14 amp., motor for driving the H. Pump. It has an explosion-proof enclosure and class F insulation.							Yes	III	D
1.2.9.3	JUNCTION BOX ASSEMBLY, 519918-1, provides the housing for terminal boards TB1 & TB2 and the entry/exit for the electrical harnesses/cables: 620583-3 (from the Directional Control Valve) and 620583-4 (from the pressure switch).	Possibility of cutting the insulation of the cables to be cut by the edges of the 1.010 and 1.115 dia. openings. Also, the possibility of contamination entering through these openings around the cables (harnesses).	x	x	x	x	x	No	III-II	C

162(A-146)


NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Inprobable)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MKI MOD 0 ISO-HUD CONSOLE SYSTEM

NAME: (Sub-system) CONTROL PANEL ASS'Y
Dwg. No./Rev.: 620587-1

Page 1 of 15

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
			PERSONNEL	SYSTEM	MISSION	POTENTIAL LOSS	DAMGE	PROBABILITY OF OCCURRENCE	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)
1.3.0	CONTROL PANEL ASSEMBLY (Unit 3A3), dsg. 620587-1, contains several Terminal Boards (five) inside and several Switch-Indicators on the Display Panel for the remote operating of the Console System. There is also a Display Intensity Transformer.								



NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (1-Catastrophic) II-Critical; III-Marginal; IV-Negligible
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent, B-Reasonably Probable, C-Occasional, D-Remote, E-Extremely Unprobable)
 F=Impossible

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 LSO-HUD CONSOLE SYSTEM

TABLE: UNIT 3A3

NAME: (Sub-system) CONTROL PANEL ASS'Y

DMG. NO./REV.: 620587-1



NAEC-91-7958

NAEC-91-7958


Page 2 of 15

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD	COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS, ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS	
			PERSONNEL	SYSTEM	MISSION			
LIVES	INJURY	DAMAGE	POTENTIAL LOSS	LOSS	DETECTABILITY BY OPERATORS?	PROBABILITY OF FAILURE	RECOMMENDATION	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)
1.3.1	VARIABLE TRANSFORMER 516917-1 (V1 on the Electrical Schematic Diagram 620580), mounted on the Control Panel Ass'Y, serves to adjust, manually, the Display Intensity of the lights on the Control Panel.						Yes	III
1.3.2.	SWITCH-INDICATOR(s) A620741-X, mounted individually on the Control Panel, are basically the JAY-EL P/N 10648 as shown in the sketches at the right, and serve to switch and indicate by light the various electrical circuits of the system.							D
							No Problems expected in a well-maintained System.	(10)
								(11)
								(12)
								(13)

164 (A-148)



SPLASH PROOF INTEGRAL SEAL
Tested to Splash Proof MIL-STD 108. High Shock to MIL-S-901C. Seal is integral to the part/bumper. It does not cover face of pushbutton.



NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Random; E-Extremely Improbable)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MKI MOD 01 ISO-MUD CONSOLE SYSTEM


NAEC-91-7958
TABLE: UNIT 3A3

NAME: (Sub-system) CONTROL PANEL ASS'Y
DAG. NO./REV.: 620587-1

Page 3 of 15

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS, ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS
		PERSONNEL	SYSTEM	MISSION	DAMAGED	POTENTIAL LOSS	DETECTABLE BY OPERATOR?	
(1)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	(3)	(4)	(5)	(6)	(7)	(8)	(9)
(1)	(cont'd) SWITCH-INDICATOR	(2)						

165(A-149)



NAEC-91-7958

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable;
F-Unlikely)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-HUD CONSOLE SYSTEM

TABLE: UNIT 3A3

NAME: (Sub-system) CONTROL PANEL ASS'Y

DAG. NO./REV.: 620587-1


NAEC-91-7958

NAEC-91-7958

Page 4 of 15

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)			EFFECT ON: PERSONNEL			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)	
		POTENTIAL LOSS	DAMAGE	INJURY	SYSTEM	MISSION	DETECTABLE BY OPERATOR?	PROBABILITY OF OCURRENCE				
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
1.3.2.0 (cont'd) SWITCH-INDICATOR A620741-x							Yes	IV		C		

Possibility of the static electricity discharges between the Push-Button and the Switch Housing (ground), that could cause "glitches" on the test screen or record tape. Some of these could cause a considerable time loss in the Failure verification/analysis effort.



EMI SHIELDING

Welded 302 stainless steel grounding where provide
chassis ground for EMI.

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable;
F-Impossible)


TABLE: UNIT 3A
 NAME: (Sub-system) CONTROL PANEL ASS'Y
 Dwg. No./Rev.: 620507-1

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-HUD CONSOLE SYSTEM

NAEC-91-7958

Page 5 of 15

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			MISSION	PERSONNEL INJURY	DETECTABLE BY OPERATOR?	FAILURE - HAZARD	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS, (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
			POTENTIAL LOSS	DAMAGE LOSS	LIVES LOSS					
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)
1.3.2.1	SWITCH-INDICATOR A620741-1 (IL5-SI) "Pump Start" has an Amber light.	a) One lamp fails (burns out).						Yes	IV	C
		b) One lamp fails (its electric connection opened).								No real problem. There are four lamps, individually wired, which is a good arrangement. Also, the replacement of the lamp is a simple manner. Can be performed quickly without tools.
		c) All four lamps fail (open in the common line).						Yes	IV	D
										No real problem even if it does occur. Periodic checks and maintenance drills will prevent or repair these remote failures.
										Hardly any real problem, even if this failure occurred just before (during?) the actual operation, because the hydraulic pressure will indicate that the pump is running. (green light L1 "PUMP RUNNING")
										NOTE: This light is only for the switch button location.



167 (A-151)

NAEC-91-7958

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; I-Remote; E-Extremely Improbable;
 F-Ine-Verifiable)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS_MK1 MOD 0 ISO-IUD CONSOLE SYSTEM

TABLE: UNIT 3A3

NAME: (Sub-system) CONTROL PANEL ASS'Y

DNG. NO./REV.: 620587-1

NAEC-91-7958

NAEC-91-7958

Page 6 of 15

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)			EFFECT ON: PERSONNEL SYSTEM	MISSION POTENTIAL LOSS	DETECTABLE BY OPERATOR?	HAZARD CLASSIFICATION (HAZARD CATEGORY CODE)	PROBABILITY OF OCURRENCE	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
		LIVES	INJURY	DAMAGE						
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)
1.3.2.1 (cont'd) SWITCH-INDICATOR A620741-1 (L5-S1) "PUMP START"		d) Switch fails (open in the line of contacts 7-8) (non-conductive contamination between contacts).					Yes	III	C	The Pump would momentarily stop when the PUMP STOP switch would be pressed (L6-S2), but it would restart immediately upon releasing the finger pressure on the L6-S2 switch. In short: the Pump could not be switched off by a normally-provided switch. However, it could be stopped by the main switch (S10). It is expected that the Operation Manual will have the emergency procedures, like this one, properly explained.

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (h-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable;
 F-Impossible)

(FAILURE Modes & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-HUD CONSOLE SYSTEM

TABLE: UNIT-3A3


NAME: (Sub-system) CONTROL PANEL ASS'Y

DMG. NO./REV.: 620587-1

NAEC-91-7958

Page 7 of 15

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARD- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON: PERSONNEL SYSTEM	MISSION	FAILURE - HAZARD	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)			
						DAMAGED LOSS	POTENTIAL LOSS	DETECTABLE BY OPERATORS?	CLASSIFICATION (HAZARD LEVEL)
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)
1.3.2.2	SWITCH-INDICATOR A620741-2 (LG-S2) "PUMP STOP" has an amber light.	a) One Lamp fails (burns out). b) One Lamp fails (its electric connection opened). c) All four Lamps fail (open in the common line).						Yes	IV



169 (A-153)

NAEC-91-7958

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.2.1 (I-Catastrophic); II-Critical; III-Marginal; IV-Negligible;
Hazard Probability, Column 12, per MIL-STD-882A, Para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Unprobable;
F-Inevitable)

TABLE: UNIT 3A
NAME: (Sub-system) CONTROL PANEL ASS'Y
DAG. NO./REV.: 620587-1

(Failure Modes & Effects Analysis - System) SAFETY ANALYSIS MK1 MOD 0 ISO-HUD CONSOLE SYSTEM

NAEC-91-7958

NAEC-91-7958

Page 6 of 15

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-PUNCTUAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
			PERSONNEL	SYSTEM	MISSION		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)
1.3.2.2 (cont'd) SWITCH-INDICATOR A620741-2 (16-S2) "PUMP STOP"	d) Switch fails (open in the 5-6 contacts or line).			x	Yes	III	C The Pump cannot be started. There is the PUMP DISABLE SWITCH (S-7) that allows the checkout of the circuitry of the PUMP, and, therefore, it is expected that any such failure as contemplated would be quickly discovered, localized and corrected.

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable; F-Impossible)

(Failure Modes & Effects Analysis - System) Safety Analysis MK1 Mod. 0 ISO-HUD Console System

NAME: (Sub-system) CONTROL PANEL ASS'Y

NAEC-91-7958

TABLE: UNIT 3A3

DNG. NO./REV.: 6205087-1

Page 9 of 15

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD PROBABILITY OF Hazardous Level (CLASSIFICATION BY OPERATOR?)	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
			PERSONNEL INJURY	SYSTEM LOSS	MISSION LOSS		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)
1.3.2.3	SWITCH-INDICATOR A620741-3 (IL7-S5) "HUD UP," has an Amber light and serves for diverting the hydraulic fluid flow under the Piston of the Hydraulic Cylinder and, therefore, for lifting the HUD up to its operational mode (contacts connections are typical to the LS-S1, see item 1.3.2.1).	a) One Lamp fails (burns out). b) One Lamp fails (open in the electrical circuit). c) All four Lamps fail (open in Common line).				Yes	IV C No problem! There are four Lamps, individually wired, which is a good arrangement. Also, the replacement of the Lamp is a simple manner - can be performed quickly without tools.

171 (A-155)

NOTE: See 1.3.2.1.c, column 13.

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Unprobable;
 F-Unprovable)

TABLE: UNIT 3A3
 NAME: (Sub-system) CONTROL PANEL ASS'Y
 DMG. NO./REV.: 620587-1

(Failure Modes & Effects Analysis - System) Safety Analysis MK1 MOD 0 ISO-HUD CONSOLE SYSTEM

NAEC-91-7958

NAEC-91-7958

Page 10 of 15

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	EFFECT ON:			FAILURE - HAZARD	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
		HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	DETECTABLE BY OPERATORS?	POTENTIAL LOSS		
		PERSONNEL	SYSTEM	MISSION		
(1)	(2)	(3)	(4)	(5)	(6)	(7)
1.3.2.3	(cont'd) SWITCH-INDICATOR A620741-3 (U7-95) "HED UP"	d) Switch fails (open in the 7-8 contacts on line).			Yes	III
		e) Switch fails (short between contacts 7-8).			Yes	III
						D
						C
						B
						A

172 (A-156)


NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Inprobable; F-Inmissible)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-HUD CONSOLE SYSTEM

NAEC-91-7958
TABLE: UNIT 3ANAME: (Sub-system) CONTROL PANEL ASS'Y
DNG. NO./REV.: 620587-1

Page 11 of 15

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD	COMMENTS: RECOMMENDATIONS; COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)
			PERSONNEL SYSTEM	MISSION	POTENTIAL LOSS		
INJURY	DAMAGE	LOSS					
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)
1.3.2.4	SWITCH-INDICATOR A620741-4 (LB-S6) "HUD DOWN," has an Amber light and serves for diverting the hydraulic fluid flow above the Piloton and so to lower the HUD (contact connections are typical to the LS-61 - see item 1.3.2.1).	a) One or up to all four lamps failing to illuminate. b) Switch fails (open in the 7-8 contacts or line). c) Switch fails (short between contacts 7-8).				Yes	III
						Yes	IV
							C
							No real problem, thanks to the redundancy built in. See the reasoning in item 1.3.2.3, a, b, and c, column 13.
							The HUD cannot be stowed by this "local" switch. However, there is a redundant arrangement in the "remote" Switch S8, which could be used in such a case, or directional control valve can be manually operated.
							The HUD cannot be raised with this failure. This would represent a problem if the HUD would be needed in a hurry, because the Air Motor and manual operation of Directional Control valve would have to be used with the electric power off.
							RECOMMENDATION: Provide a redundancy by connecting the contacts.



NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Ocasional; D-Remote; E-Extremely Unprobable; F-Inaccessible)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD D ISO-HND CONSOLE SYSTEM

NAME: (Sub-system) CONTROL PANEL ASS'Y

TABLE: UNIT 3A

NAME: DNG. NO./REV.: 620587-1

NAEC-91-7958

Page 12 of 15

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON: PERSONNEL SYSTEM			MISSION LOSS	DETECTABLE BY CIRCUITRY OPERATORS?	CLASSIFICATION (Hazard Level) PROBABILITY OF OCURRENCE	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)		
			LIVES LOSS	DAMAGE LOSS	POTENTIAL LOSS				Yes	IV	C
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)
1.3.2.5	SWITCH-INDICATOR A620741-7 (L1) "PUMP RUNNING," has a Green light and serves to indicate that the Pump is running. Really, this light indicates the closure of contacts in the Pressure Switch Item 1.2.4, Table "b", which will close, normally, if the Pump is running and delivering the Hydraulic Fluid which would be under pressure. The switch is wired identically to the A620741-1 (L5-S1), and serves to check on the L1 light (RT-L1): "Press to Test the L1."	a) One or up to all four Lamps failing to illuminate. b) Switch fails (open in the 7-8 contacts or line). c) Switch fails (short between the contacts 7-8).							Yes	IV	C

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable);
 F-Jimplausible

TABLE 4
UNIT 3A3
NAME: (Sub-system) CONTROL PANEL ASS'Y
ITEM NO./REV.: 620587-1

(FAILURE Modes & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS [MK] MOD 0 ISO-HUD CONSOLE SYSTEM

NAEC-91-7958

Page 13 of 15

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARD- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS: RECOMMENDATIONS: COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)
			PERSONNEL	SYSTEM	MISSION	DETERMINATE BY OPERATOR?	PROBABILITY OF CLASSIFICATION (HAZARD LEVEL)	HAZARD - REDUNDANCY	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)
1.3.2.6	SWITCH-INDICATOR A620741-8 (L3) "HUD LID DOWN," has a Red light and serves to indicate that the HUD Lid is down, and, therefore, the HUD Ass'y cannot be released.	a) One or up to all four Lamps failing to illuminate. The Switch is wired identically to the A620741-1 (LS-51), see item 1.3.2.1, and serves to check on the L3 light (PRT-L3). "Press to Test the L3."				Yes	IV	C	No problem with up to three Lamps failing, due to the four-fold redundancy.
		b) Switch fails open in the 7-8 contacts or lines.				Yes	III	D	In case of all four Lamps failing, again there would be no danger that the HUD Ass'y could be raised, thanks to the interlock (LS3).
		c) Switch fails short between the contacts 7-8.				Yes	IV	C	Normally, there is no need to check on this light, since it is "on" when the System is "on" and the HUD Lid is down.
									This check would be needed in case the Normally Closed contacts of the LS3 "HUD LID DOWN" Switch would be failing open (troubleshooting). The probability of both of these failures at the same time is very remote.
									The warning Red light L3 would stay on even with the HUD Lid raised, which would call for a quick failure isolation and repair.

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic); II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Inpossible)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 LSO-HUD CONSOLE SYSTEM

TABLE: UNIT 3A3

NAME: (Sub-system) CONTROL PANEL ASS'Y

DMG. NO./REV.: 620587-1

NAEC-91-7958

Page 14 of 15

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD DETECTABLE BY OPERATOR?	PROBABILITY OF OCCURRENCE (%)	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES), SAFETY CONTROLS)
			POTENTIAL LOSS	MISSION LOSS	PERSONNEL INJURY LOSS			
(1)	(2)	(3)	(4)	(5)	(6)	IV	(11)	(12)
1.3.2.7	SWITCH-INDICATOR A620741-9 (LA) "HUD ASKEW," has a Red light and serves to indicate that the HUD Ass'y is not aligned for its loosening.	a) One or up to all four Lamps failing to illuminate. The switch is wired identically to the A620741-1 (LS-S1) - see Item 1.3.2.1, and serves to check on the LA light (FRT-L4), "Press to Test the LA." b) Switch fails (open in the 7-8 contacts or line). c) Switch fails (short between the contacts 7-8).	(7)	(8)	(9)	Yes	C	No problems with up to three Lamps failing, due to the four-fold redundancy.
						Yes	III	D
						Yes	III	C
						No	II - III	B
							III	D

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Inapplicable)

NAEC-91-7958
 Page 14 of 15

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 LSO-HUD CONSOLE SYSTEM

NAEC-91-7958
TABLE: UNIT 3A3NAME: (Sub-system) CONTROL PANEL ASS'Y
DNG. NO./REV.: 620587-1

Page 15 of 15

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)		
			PERSONNEL INJURY	SYSTEM LOSS	MISSION LOSS	POTENTIAL LOSS	DETECTABLE BY OPERATOR?	CLASSIFICATION (HAZARD LEVEL)	PROBABILITY OF OCURRENCE	CLASSIFICATION (HAZARD LEVEL)	PROBABILITY OF OCURRENCE
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)
1.3.3	TOGGLE SWITCH MS27735-22 (S10) is a two-pole switch that serves to switch the HUD Console System on and off. It is properly guarded with the Switch Guard MS25224-3.	No problem foreseen.						Yes	III	D	

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable;
 F-Inconceivable)



(Failure Modes & Effects Analysis - System) Safety Analysis MK1 MOD 0 ISO-HUD CONSOLE SYSTEM

NAEC-91-7958

TABLE: UNIT 3A4
 NAME: (Sub-system) CENTRAL JUNCTION BOX ASS'Y
 DMC. NO./REV.: 620739-1

Page 1 of 9

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			PROBABILITY OF OCCURRENCE (HAZARD LEVEL)	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
			POTENTIAL LOSS	DETECTION BY OPERATOR?	CLASSIFICATION	POTENTIAL LOSS	DETECTION BY OPERATOR?	POTENTIAL LOSS		
(11)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)
1.4.0	CENTRAL JUNCTION BOX ASSEMBLY (Unit 3A4), deg. 620739-1, contains several Terminal Boards, Relays, Indicator Lights, the V2 Transformer, Circuit Breaker, Fuse and Toggle Switch. It provides the central interconnection of the six harnesses W204 and W216 (Junction Box, Unit 3A5); W205 and W217 (Control Panel, Unit 3A3); and W210 (Limit Switch Junction Box, Unit 3A6).									



NOTE: Hazard Level, Column 11, per MIL-STD-882b, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882b, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Impractical)

(Failure Modes & Effects Analysis - System) SAFETY ANALYSIS MKI MOD.0 ISO-HUD Console System

TABLE: UNIT 3A4

NAME: (Sub-system) CENTRAL JUNCTION BOX ASS'Y


Dwg. No./Rev.: 620739-1

NAEC-91-7958

Page 2 of 9

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD	COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS, ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS
			PERSONNEL INJURY	MISSION LOSS	DAMAGE LOSS		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)
1.4.1	RELAY 5169315-1 (K1 & K2 and two spares plugged in K3 & K4), with coil operating voltage: 28VAC, 60Hz, 1 phase, coil operating current: 0.55 Amperes max. Contact load rating per pole: 10 Amp. resistive, 6 amp conductive at 120VAC, 60Hz. Minimum current: 0.04 Amp RMS, 1/2 wave rectified. See Electrical Schematic Diagram 620590 for connections.	K1-Head-Up-Relay K2-Head-Down-Relay	This Relay serves to prevent the operation of the HUD Down Solenoid by opening its Normally Closed contacts "A" (from A2/A3 to A2/A1) and to allow the operator of the HUD Up Solenoid SOL1 by closing its Normally Open Contacts "B" (from B2/B3 to B2/B1), when HUD UP command is executed. Similarly, this Relay serves to prevent the operation of the HUD Up solenoid SOL2 by opening its NC contacts "A" (from A2/A to A2/A1) and to allow the operation of the HUD Down Solenoid SOL2 by closing its NO contacts "B" (from B2/B1 to B2/B), when HUD DOWN command is executed.	(9)	(10)	(11)	(12)
						(x)	(13)

- a) The coil (K1-K2) is interrupted ("an open").




NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability: Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable; F-Impossible)

(Failure Modes & Effects Analysis - System) SAFETY ANALYSIS MKI MOD 0 ISO-HUD CONSOLE SYSTEM

NAEC-91-7952

TABLE: UNIT 3A4
 NAME: (Sub-system) CENTRAL JUNCTION BOX ASS'Y
 DNG. NO./REV.: 620739-1

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)			EFFECT ON:	FAILURE - HAZARD	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
		PERSONNEL	SYSTEM	MISSION			
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)
1.4.1	(cont'd) RELAY 516915-1	b) NC contacts A fail to make contact.			Yes	III	C
		1) In K1: This would result in the failure to lower the HUD when needed.					This could result in a serious problem (signs in parentheses). However, it is expected that the Operational Procedures (to raise the HUD with time to spare), together with the ease of the repair/replace-ment of the failed relay, will result in a considerably reduced problem (signs without parentheses).
		II) In K2: This would result in the failure to raise the HUD when needed.			Yes	(I-II)	C
					x	III	C
							RECOMMENDATION: Wire the K2 Relay according to the circuit diagram at left.



180 (A-164)

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable;
 F-Very Low)

TABLE: UNIT 3A
 NAME: (Sub-system) CENTRAL JUNCTION BOX ASS'Y
 DNG. NO./REV.: 620739-1

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-HUD CONSOLE SYSTEM

NAEC-91-7958

Page 4 of 9

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)			EFFECT ON: PERSONNEL SYSTEM			FAILURE - HAZARD DETECTABLE BY OPERATOR?			PROBABILITY OF CONTACTING HAZARD LEVEL (HAZARD CLASSIFICATION)	COMMENTS: RECOMMENDATIONS: COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)
		DAMGE LOSS	POTENTIAL LOSS	MISSION	DAMGE LOSS	POTENTIAL LOSS	MISSION	DAMGE LOSS	POTENTIAL LOSS	MISSION		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
1.4.1 (cont'd) RELAY 518915-1		a) NC contacts B fail to make contact in K1 and in K2; No problem, they are not wired. d) NO contacts A fail to make contact in K1 and in K2. e) NO contacts B fail to make contact when needed. i) In K1 - would result in failure to raise the HUP.										

181(A-165)

NAEC-91-7958

NOTE: There is an error on the sketch of the K1 and K2 pin connections in the drawing 620753-1 "Wiring Ass'y," location 4 and 5-A. See corrected sketch in Item 1.4.1, page 2 of this Table.

This could result in a serious problem. However, it is believed that the design and the Operation and Maintenance procedures will reduce this potential problem (signs in parentheses) into a practically and easily manageable task of raising the HUP ahead of time and, if needed, replacing the failing relay. (signs without the parentheses). But there is a simple, inexpensive way to produce a redundancy against this failure:

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Unprobable; F-Impossible)

(Failure Modes & Effects Analysis - System) SAFETY ANALYSIS MK1 MOD 0 ISO-HUD CONSOLE SYSTEM

TABLE: UNIT 3A4


NAME: (Sub-system) CENTRAL JUNCTION BOX ASS'Y

DMG. NO./REV.: 620739-1

NAEC-91-7958

NAEC-91-7958

Page 5 of 9

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:		FAILURE - HAZARD		COMMENTS: RECOMMENDATIONS; COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES / SAFETY CONTROLS)
			POTENTIAL LOSS	DAMAGED	POTENTIAL LOSS	DAMAGED	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(11)
1.4.1	(cont'd) RELAY 510915-1		(8)	(9)	(10)	(11)	(12)
							<p>• RECOMMENDATION: Wire the K1 Relay as follows:</p> 
							<p>FROM: (K1)</p> <p>To: (K1)</p> <p>D3 → D1 → C3 → C1 → B3 → A3 → A1 → K1</p> <p>D3 → D2 → C3 → C2 → B3 → A3 → A2 → K1</p> <p>D3 → D2 → C3 → C2 → B3 → A3 → A2 → K1</p> <p>D3 → D2 → C3 → C2 → B3 → A3 → A2 → K1</p> <p>D3 → D2 → C3 → C2 → B3 → A3 → A2 → K1</p> <p>D3 → D2 → C3 → C2 → B3 → A3 → A2 → K1</p> <p>D3 → D2 → C3 → C2 → B3 → A3 → A2 → K1</p> <p>D3 → D2 → C3 → C2 → B3 → A3 → A2 → K1</p>
							<p>No real problem. When the HUD is commanded down, there is usually more time to localize the failure and to replace the failing relay, which is nicely provided for in the design.</p>
							<p>Extremely improbable! This situation would require two failures to occur simultaneously. (Failure of the relay and a failure of someone pressing the "wrong" switch).</p>
							<p>Yes III C</p>
							<p>Yes III E</p>
							<p>(ii) In K2: would result in failure to lower the HUD.</p> <p>(f) Short between NC contacts A in K1 and in K2: this would result in a possibility of an inadvertent counter-command by pressing the local switch S₁ or S₆.</p>

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Marginal; III-Critical; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Proximate; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable; F-Impracticable)

TABLE: UNIT 3A4
 NAME: (Snb-system) CENTRAL JUNCTION BOX ASS'Y
 Dwg. No./Rev.: 620739-1

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-HUD CONSOLE SYSTEM

NAEC-91-7958

Page 6 of 9

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:		FAILURE - HAZARD		COMMENTS: RECOMMENDATIONS: COMPENSATING PROVISIONS ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS	
			PERSONNEL	SYSTEM	MISSION	PROBABILITY OF OCCURRENCE (HAZARD LEVEL)		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	
1.4.1	(coat'd) RELAY 510915-1	<ul style="list-style-type: none"> g) Short between NC contacts B, in K1 or K2. h) Short between NO contacts A. j) Short between NO contacts B l) In K1: this would result in raising the HUD as soon as the Pump would start running, and it could not be lowered. m) In K2: this would result in the failure to raise the HUD. 			x		Yes	
							III D	
							No real problem is expected to develop because of this possible failure mode, thanks to the anticipated timely check-out of the System and the ease with which the failed Relay would be localized and replaced.	
							This could result in a serious problem (signs in parentheses). However, it is expected that the System check-out procedures and the ease of finding and replacing the failing Relay will reduce the problems considerably (signs without parentheses). But, there is a simple and inexpensive way to design in a redundancy against this failure.	

NOTE: Hazard Level - Column 3, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic); II-Critical; III-Marginal; IV-Tolerable). Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Unprobable).

TABLE: UNIT 3A4
NAME: (Sub-system) CENTRAL JUNCTION BOX ASS'Y
DNG. NO./REV.: 620739-1

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 LSO-IUD CONSOLE SYSTEM

NAEC-91-7958
NAEC-91-7958
Page 7 of 9

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD DETECTION BY OPERATOR?	PROBABILITY OF OCCURRENCE (HAZARD LEVEL)	COMMENTS / RECOMMENDATIONS: COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)
			PERSONNEL	SYSTEM	MISSION			
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)
1.4.1	(cont'd) RELAY 510915-1	1)						
		11) (cont'd)						

184 (A-168)




- RECOMMENDATION: Wire the K2 Relay as shown in the sketch below.

NOTE: Hazard levels: Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable; F-Inapplicable)

TABLE: UNIT 3A4
NAME: (Sub-system) CENTRAL JUNCTION BOX ASS'Y
DMG. NO./REV.: 620739-1

Page 8 of 9

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON: PERSONNEL SYSTEM	MISSION	FAILURE - HAZARD		COMMENTS: RECOMMENDATIONS; COMPENSATING PROVISIONS; ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS
					DETECTABLE BY OPERATORS?	POTENTIAL LOSS	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)
1.4.2	TRANSFORMER 518984-1 (V2), with the primary and secondary windings as shown in the schematic diagrams shown here (the component and as wired in);	No problem foreseen.					No problem foreseen, thanks to the designed-in protection.



135 (A-169)

This V2 Transformer serves to provide the "25VAC" for the Switch-Indicators and the Relays.

NOTE: Hazard 4 Ass't, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Neigligible)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable; F-Inprobable)

TABLE: _____
 NAME: (Sub-system) CENTRAL JUNCTION BOX ASS'Y
 DNG. NO./REV.: 620739-1

NAEC-91-7958

NAEC-91-7958

Page 9 of 9

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	EFFECT ON:			FAILURE - HAZARD PROBABILITY	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)
		PERSONNEL INJURY	SYSTEM LOSS	MISSION LOSS		
(1)	(2)	(3)	(4)	(5)	(6)	(7)
1.4.3	CIRCUIT BREAKER M39019/3-107 (cb1) provides the line protection between the V3 and V2 Transformers (the 115VAC side).	No problem foreseen.			Yes	III
1.4.4	TOGGLE SWITCH MS25105-21 (sst) is a three-pole switch used for the Relay Test Circuit switching on/off.				Yes	IV
1.4.5	TOGGLE SWITCH MS25105-23 (st) is a three-pole switch used for the Pump Disable function (for the testing purposes).				Yes	IV
1.4.6	INDICATOR (Light) MS25256-4 (LCD, LED), Green light, with two Lamps each, is used to check the Relay with the coil energized and de-energized.				Yes	IV

186 (A-170)

NOTE: Hazard Level, column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Marginal; III-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable;
 F-Impossible)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 (SO-HUD CONSOLE SYSTEM)



NAEC-91-7958

TABLE: UNIT 3AS

NAME: (Sub-system) TRANSFORMER ENCLOSURE

DNG. NO./REV.: 518928-1

Page 1 of 1

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)			
			PERSONNEL	SYSTEM	MISSION	POTENTIAL LOSS	DAMAGE LOSS	DETECTABLE BY OPERATORS	CASCADING (HAZARD LEVEL)			
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
1.5.0	TRANSFORMER ENCLOSURE 518928-1 (Unit 3AS) contains the V3 Transformer 518928-2, which provides the step-down transformation of the ship's 440VAC to 115VAC used in the HMD System. It is a 1.0kVA, 60Hz unit, bulk-head mounted. See sketch at right.									Yes	III	E
1.5.1	TRANSFORMER 518928-2 (V3). It is protected from both sides: on the primary side 440VAC, there are fuses F2 & F3, and on the secondary 115VAC side, there is the circuit breaker CB1.		No problem foreseen.							No problem foreseen.	IV	Negligible

137 (A-171)

NOTES: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Unlikely; E-Extremely Unlikely)

(Failure Modes & Effects Analysis - System) Safety Analysis [MK1] MOD_0 ISO-HUD Console System

NAEC-91-7958

TABLE: UNIT 3A6
 NAME: (Sub-System) LIMIT SWITCH JUNCTION BOX ASS'Y
 DNG. NO./REV.: 518929-1

Page 1 of 1

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:				FAILURE - HAZARD PROBABILITY OF COINCIDENCE (HAZARD LEVEL)	COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)				
			POTENTIAL LOSS	DAMAGED LIVES	DETECTABLE LOSS	DETECTABLE OPERATORS?						
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
1.6.0	LIMIT SWITCHES JUNCTION BOX ASSEMBLY 518929-1 (Unit 3A6), contains three Terminal Boards for the connections of the ends of the Harnesses: W210 (from the Central Junction Box), W211 (Limit Switch LS1-HUD Down), W212 (LS2-HUD Up), W213 (LS3-HUD Storage Lid On) and W214 (LS4 and LS5-HUD Align).	INTEGRITY OF SWITCING FUNCTIONS	620138-6 6 PLACES	321907-1 6 PLACES	414475-1 3 PLACES	414475-1 3 PLACES	Yes	III	D	No problems foreseen in a well- assembled and checked-out assembly.		

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Random; E-Extremely Improbable; F-Inversible)

AD-A083 720

KETRON INC. WAYNE PA

F/6 5/8

HAZARDS/Failure MODES AND EFFECTS ANALYSIS MK 1 MOD 0 LSO-HUD C--ETC(U)

MAR 80 F SEVCIK, G S FARBER, W S MANN

N68335-78-C-2002


UNCLASSIFIED

3 OF 3
AD-A083 720


KTM-1327-01

NAEC-91-7958

NL



END
OF FILMED
OTIC



(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-HUD CONSOLE SYSTEM

TABLE: UNIT 3A7

NAME: (Sub-system) PENDANT SWITCH ASS'Y


DNC. NO./REV.: 510925-1

NAEC-91-7958

Page 1 of 2

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS: RECOMMENDATIONS; COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)
			PERSONNEL INJURY	SYSTEM LOSS	MISSION LOSS	DETECTABLE BY OPERATORS?	HAZARD AND LOSS LEVEL	PROBABILITY OF OCURRENCE	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)
1.7.0	PENDANT SWITCH ASSEMBLY 510925-1 (Unit 3A7), composed of the Pendant Switch 510924-1, cable, connector, etc., serves to operate the HMD Console System from a "remote" spot, enabling the operator the advantage of a freedom of movement and observation. This is the SB switch on the Schematic Diagram 620580. It rests on the Pendant Switch Bracket 510926-1 (which is attached to the Enclosure Ass'y 620586-1 of the Control Panel Ass'y 620587-1 (Unit 3A3)) when not in use.								(11) (12) (13)

189 (A-173)



Legend:
 I - Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic, II-Critical, III-Marginal, IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent, B-Reasonably Probable, C-Occasional, D-Remote, E-Extremely Unlikely, F-Impossible)

4. APPENDIX: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic, II-Critical, III-Marginal, IV-Negligible)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-HUD CONSOLE SYSTEM

TABLE: UNIT 3A7

NAME: (Sub-system) PENDANT SWITCH ASS'Y
DNG. NO./REV.: 518925-1

NAEC-91-7958

Page 2 of 2

NAEC-91-7958


ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	EFFECT ON:			FAILURE - HAZARD	COMMENTS: RECOMMENDATIONS: COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)						
		HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	PERSONNEL	SYSTEM								
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
1.7.1	PENDANT SWITCH 518924-1 (SS) allows the operation (HUD UP and HUD DOWN) from a "remote" place.	a) "Open" in the switch - would result in the lack of response of the HUD Console System to raise/retract. b) "Short" in the Switch (the contacts do not open when required) - would result in the HUD Console System "stuck" in the Up or Down position.	(x)	(x)	(x)	(x)	(x)	Yes	IV	C	A redundant provision is included in the design (the switches S5 and S6). No problem would result.	

This could represent a serious problem, if the System would be needed to be raised (signs in the parentheses). However, it is expected that the raising o' the System will be accomplished with some time before the actual need of it to allow for the check-out and a possible failure identification/localization and repair/replacement. (Operational and Maintenance Procedures.) Also, the Air Motor-R. Pump can be used! The problem then would be greatly reduced! (signs without parentheses.)

Attachable Pendant Switches

Pilot Grip

Completely ingress sealed, this switch features an integral handle for easy one-hand operation of small holes. The replaceable 25 Volt, 15 Amp, Up-Down-On, toggle switch is available as either standard or illuminated contact. A reinforced eye on the switch cover permits attachment of an external strain chain. The entire assembly is waterproof and suitable for use outdoors.



NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Inexpressible)


(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-HUD CONSOLE SYSTEM

TABLE: UNIT 348
 NAME: (Sub-system) FUSE BOX ASS'Y
 DMG. NO./REV. : 620742-1

NAEC-91-7958

Page 1 of 1

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES / SAFETY CONTROLS)		
			POTENTIAL LOSS	DAMAGE	MISSION	HAZARD AND OPERATOR?	PROBABILITY OF OCURRENCE (LEVEL)	PROBABILITY OF DETECTION BY DETECTABLE RELEASE	RECOMMENDATIONS (ACCIDENT PREVENTION MEASURES / SAFETY CONTROLS)		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)
1.6.0	FUSE BOX ASSEMBLY 620742-1 (Unit 348), holds the two Fuses (P2 and P3) in the Fuseholder and contains a Terminal Board Assembly. It is interconnected with the Motor Starter (Harness W202), the Transformer Enclosure (W207), and the Central Junction Box (Harness W215).	No problem foreseen.				Yes	III	D	No problems foreseen in a well-maintained system.		



NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic); II-Critical; III-Marginal; IV-Negligible;
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; R-Reasonably Probable; C-Occasional; P-Rare; E-Extremely Improbable;
 F-Inapplicable)

(Failure Modes & Effects Analysis - System) Safety Analysis Mk1 Mod 0 ISO-IUD Console System

TABLE: UNIT 4A1

NAME: (Sub-system) SIGNAL JUNCTION BOX

Dwg. No./Rev.: 621173-1 (Schematic: 621163)

(Wiring: 621164)

NAEC-91-7958

Page 1 of 20


ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)					
			POTENTIAL LOSS	DETECTABLE BY OPERATOR?	DETECTION LOSS	HAZARD LEVEL	PROBABILITY OF OCCURRENCE	HAZARD LEVEL	DETECTION LOSS	POTENTIAL LOSS	DAMAGE LOSS	SYSTEM	MISSION	PERSONNEL
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)		
1.0	The Signal Junction Box, located in the room area just below the console at the ISO platform, contains: 2 transformers for the Relay Power (115VAC to 28VAC), 12 Relays and a number of terminal strips.													

The Relays' Normally Closed Contacts (A3, B3, C3 and D3) are wired to the Ship's input signals.

With the Test Simulator "plugged in" the Test Simulator Interface box (Unit 4A4) and the switch actuated, the 12 Relays of the Signal Junction Box will transfer to close the Normally Open contacts and thus the Test Simulator Inputs will be handled.

See the Schematic Diagram at right (Relays in "Ship's Input Mode").

192(A-176)



NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Tolerable)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (h-Frequent; g-Reasonably Probable; c-Occasional; f-Remote; e-Extremely Improbable; F-Impossible)


(Failure Modes & Effects Analysis - System) Safety Analysis MK1 MOD 0 LSU-HMU LONSOLE SYSTEM

NAEC-91-7958
TABLE: UNIT 4A1

NAME: (Sub-system) SIGNAL JUNCTION BOX
Dwg. No./Rev.: 621173-1

Page 2 of 20

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS: RECOMMENDATIONS! COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)
			PERSONNEL	SYSTEM	MISSION	DAMAGE	POTENTIAL LOSS	CLASSIFICATION BY OPERATOR	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)
1.0	(cont'd) The Signal Junction Box provides for the transfer of: • Aircraft type identification signals from the crosscheck system, SPH-42 signals, • FLOLS wave-off signals, • Ramp motion and Ram trim signals from the FLOLS trim harmonization computer (all Analogue or varying DC signals) from Ship or Test Simulator to the MHD Console.								(11) (12) (13)



193 (A-177)

NOTES: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Tolerable; IV-Marginal)
Lazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Inprobable)

TABLE: UNIT 4A1
 NAME: (Sub-system) SIGNAL JUNCTION BOX
 DNG. NO./REV.: 621173-1

FAILURE MODES & EFFECTS ANALYSIS - SYSTEM SAFETY ANALYSIS MKI MOD 0 ISO-HUND CONSOLE SYSTEM

NAEC-91-7958

Page 3 of 20

NAEC-91-7958

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)		
			PERSONNEL	SYSTEM	MISSION	DETECTABLE	OPERATOR	CONSEQUENCE LEVEL	HAZARD QUANTIFICATION	CLASSIFICATION	RECOMMENDATION
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)
1.1	Transformer 422977-1. Primary: 115VAC, 60Hz, 1 phase. Secondary: 28VAC, 5.00 Amp. Two of these provide the current to the coils of the 12 Relays of the Signal Junction Box: Transformer T1 serves the Relays K1 through K8 and Transformer T2 serves the Relays K9 through K12.	a) Transformer T1: 1) Loss of the Primary power will cause the K1 through K8 reset to the ship's inputs mode-leaving the A/C designation for the Test Simulator input mode	-	-	-	-	-	Yes	III	D	<i>Fail safe arrangement - good!</i>
		b) Transformer T2: 1) Loss of one of the two secondary windings function will cause the first eight Relays to return to, or stay in, the Normally Closed contacts that are in the ship's mode.	-	-	-	-	-	Yes	III	D	

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Vigilable)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Impossible)

(Failure Modes & Effects Analysis - System) SAFETY ANALYSIS MK1 MOD 0 ISO-HUD CONSOLE SYSTEM

TABLE: UNIT 4A1

NAME: (Sub-System) SIGNAL JUNCTION BOX

DWG. NO./REV.: 621173-1

NAEC-91-7958

Page 4 of 20

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON: PERSONNEL SYSTEM	FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
				POTENTIAL LOSS	DAMAGE	MISSION	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(1)
1.1	(cont'd) TRANSPONER 422977-1	b) Transformer T2:					
		i) Loss of the Primary power will cause the Relays K9 through K12 to reset to the Ship's inputs mode-losing the PLOTS Ramp Motion & Trim and the SPN-42 for the Test Simulator input mode.	-	-	-	-	Yes III D Fail safe arrangement - good!
		ii) Loss of one of the two Secondary windings function will cause no apparent problem, since one winding will be enough to activate the four Relays.	-	-	-	-	Even if both of the Secondary windings' function would be lost, the result would be only to lose the Test Simulator input mode in the Ramp Motion & Trim and the SPN-42, returning the 4 Relays back to the Ship's input mode: fail safe arrangement.
				-	-	-	No IV D

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal/IV-Tolerable)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable;
 F-Inconsequential)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-HUD CONSOLE SYSTEM

NAME: (Sub-system) SIGNAL JUNCTION BOX

DNC. NO./REV.: 621173-1

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	EFFECT ON: PERSONNEL SYSTEM MISSION			FAILURE - HAZARD DETECTABILITY BY OPERATORS (CLASSIFICATION OF OCCURRENCE)			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES/ SAFETY CONTROLS)				
		POTENTIAL LOSS INJURY SEATS	POTENTIAL LOSS LOSS DAMAGE	POTENTIAL LOSS LOSS	POTENTIAL LOSS LOSS	POTENTIAL LOSS LOSS	POTENTIAL LOSS LOSS					
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
1.2	Relay 548915-1, socket mounted, 10 Amp, 4PDT, coil, 28VAC, 60Hz, Single phase, max-operating current 0.55 Amp, contact: max-10 Amp resistive, 6 Amp inductive load at 120 VAC, 60Hz. Minimum current to be 0.040 Amp RMS, 1 wave rectified. Twelve relays used for: SPN-42, PLOIS (W-off, Ramp Motion & Trim) & A/C Type Signals.	a) R1 1) Open in the Coil - loss of ACIS Lock-On, Mode I, II & III Signals in the Test Simulator Mode. ii) Failure of the NO contacts to close upon actuation: A1 - Loss of "ACIS Lock-On" in Test Sim. Mode	- - - -	- - - -	Yes - - -	III III III -	C C C -	GENERAL NOTE: Since the contacts of these Relays are assured for the minimum current of 40 mAmp, and 10 Amp max, there will be failures of the passage of the low current (40 milliamp or lower) after the 10A had gone through (in testing, for inst.). Considering that very low currents signals (10 micro/Amp) will be handled in the System, the following is recommended: • RECOMMENDATION: Change the circuitry to assure the passage of the low current signals!!! (Current amplification, solid state?)	These are failures affecting check-out with the Test Simulator function. The easy fault identification and the part replacement will keep the system outage to the minimum.			

CIRCUIT DIAGRAM

The Normally Closed (NC) contacts carry ship's inputs, the Normally Open (NO) contacts are for the Test Simulator mode of operation.

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable)
F-Inapplicable

(FAILURE Modes & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MKI MOD 0 ISO-HUD CONSOLE SYSTEM
NAEC-91-7958

TABLE: UNIT 411
NAME: (Sub-system) SIGNAL JUNCTION BOX
DNG. NO./REV.: 621173-1

Page 6 of 20

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS / COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES / SAFETY CONTROLS)			
			POTENTIAL LOSS	DAMAGE	INJURY	DETECTABLE BY OPERATOR?	CLASSIFICATION (HAZARD LEVEL)	PROBABILITY OF OCCURRENCE				
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
1.2 (cont'd) Relay 518915-1	a) K1	iii) Failure of the MC contacts to close upon deactivation: A3- Loss of ACIS Lock-on in the ship's input mode. B3- Loss of MCOS 1 in the ship's input mode. C3- Loss of MCOS II in the ship's input mode. D3- Loss of MCOS III in the ship's input mode.	-	-	-	-	-	-	-	-	-	c

The Maintenance procedure will assure a quick restoration of these functions.

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable;
F-Insignificant)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-IMD CONSOLE SYSTEM

TABLE: UNIT 4A1

NAME: (Sub-system) SIGNAL JUNCTION BOX
DNG. NO./REV.: 621173-1

Page 7 of 20

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)			EFFECT ON: PERSONNEL SYSTEM			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)		
		LIGHT	MEDIUM	SEVERE	LOSS	DAMAGE	LOSS	POTENTIAL LOSS	DETECTABLE BY OPERATOR?	DETECTABLE BY OPERATOR?	PROBABILTY OF CATASTROPHIC (HAZARD LEVEL)	PROBABILTY OF CATASTROPHIC (HAZARD LEVEL)	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)	
1.2	(cont'd) Relay 518915-1	b) K2											

1) Open in the Coil, loss of ACLs and ISO Wave-off in the Test Simulator Mode.

II) Failure of the NO Contacts to close upon actuation.

A1 or B1 - Loss of ACLs Wave-off.

C1 or D1 - Loss of ISO Wave-off, in the Test Simulator Mode.

These are failures affecting check-out with the Test Simulator.

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable;
 F-Insignificant).

(Failure Modes & Effects Analysis - System) SAFETY ANALYSIS MK1 MOD 0 ISO-MIN CONSOLE SYSTEM

TABLE: UNIT 4A1

NAME: (Sub-system) SIGNAL JUNCTION BOX

NAEC-91-7958

DNG. NO./REV.: 621173-1

Page 8 of 20

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON: PERSONNEL SYSTEM	MISSION LOSS	POTENTIAL LOSS	DETECTABLE BY OPERATOR?	CLASSIFICATION (HAZARD LEVEL)	PROBABILITY OF OCURRENCE	FAILURE - HAZARD	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)			
										(1)	(2)	(3)	(4)
1.2	(cont'd) Relay 518915-1	b) K2 iii) Failure of the NC contacts to close upon de-actuation A1 or B3 - Loss of ACLS Wave-off in the Ship's Input Mode. C3 or D3 - Loss of ISO Wave-off in the Ship's Input Mode.								Yes	I-II	C	The serious results of this failure would be as indicated only if other, redundant channels of communications also failed, and this particular failure were not corrected as soon as observed, which is right after the Test Simulator Mode functions. It is expected that the Maintenance procedure will be efficient and quick in such repairs.

NOTE: Hazard Level, Column 11, per MIL-STD-882a, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882a, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable;
 F-Insignificant)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MKL MOD 0 ISO-HUD CONSOLE SYSTEM

NAEC-91-7958

TABLE: UNIT 4A1
 NAME: (Sub-system) SIGNAL JUNCTION BOX
 DMC. NO./REV.: 621173-1

Page 9 of 20

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD CLASSIFICATION (HAZARD LEVEL) DETECTABILITY LOSS	FAILURE - HAZARD OCCURRENCE PROBABILITY OPERATOR?	COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS, (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)
			POTENTIAL INJURY SEAT	PERSONNEL SYSTEM	MISSION			
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)
1.2	(cont'd) Relay 510915-1	c) K3	-	-	-	-	Yes	III
			1) Open in the Circuit. Loss of signals for the A3, 4, 5 & 6 Air- craft in the Test Simulator Mode. II) Failure of the NC con- tacts to close upon actuation: A1, B1, C1, D1 - Loss of the cor- responding signal (A3, A4, A5, A6) in the Test Simulator Mode. III) Failure of the NC contacts to close up- on deactua- tion A3, B3 C3, D3 - loss of the corre- sponding sig- nal (A3, A4, A5, A6) in the Ship's Input Mode.	-	-	-	-	III
							Yes	C
								These failures would affect only the lights on the HUD Panel - easy and quick to repair.

NOTE: Hazard Level, Column 11, per MIL-STD-882B, para. 5.4.1.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable;
 F-Impracticable)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-HUD CONSOLE SYSTEM

TABLE: UNIT 4A1NAME: (sub-system) SIGNAL JUNCTION BOXDNC. NO./REV.: 621173-1Page 10 of 20

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:				FAILURE - HAZARD LEVEL	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
			POTENTIAL LOSS	DAMAGE LOSS	PERSONNEL INJURY	MISSION		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)
1.2	(cont'd) Relay 518915-1	d) K4	i) Open in the Coll. Loss of Signals for the A7, TA4, EA6 and C1 aircraft in the Test Sim- ulator Mode.	-	-	-	-	Yes
			ii) Failure of the NO con- tacts to close upon actuation: A1, B1, C1, D1 - loss of the corre- sponding Sig- nal (A7, TA4, EA6, C1) in the Test Simulator Mode.	-	-	-	-	Yes
			iii) Failure of the NC con- tacts to close upon deactuation: A3, B3, C3, D3 - loss of the correspon- ding signal (A7, TA4, EA6, C1) in the Ship's Inertial	-	-	-	-	Yes
			NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible) Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Unprobable; F-Inconceivable)					

TABLE: UNIT 4A1
 NAME: (sub-system) SIGNAL JUNCTION BOX
 DRG. NO./REV.: 621173-1

Page 11 of 20

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			PROBABILITY OF OCURRENCE (HAZARD LEVEL)	COMMENTS / RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)
			PERSONNEL SYSTEM	MISSION	POTENTIAL LOSS	DETECTOR BY OPPONENT	CLASSIFICATION OF OPERATOR?			
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)
1.2	(cont'd) Relay 510915-1	a) R5	-	-	-	-	-	Yes	III	C
			1) Open in the Coil - loss of signals for the S2, C2, E2, S3 Air- craft in the Test Simula- tor Mode.							
			II) Failure of the NC con- tacts to close upon actuation: A1, B1, C1, D1- loss of the corre- sponding sig- nal (S2, C2, E2, S3) In the Test Simu- lator Mode.					Yes	III	C
			III) Failure of the NC con- tacts to close upon deactuation: A3, B3, C3, D3- loss of the corresponding signal (S2, C2, E2, S3) In the Ship's Input Mode.					Yes	III	C
										These failures would affect only the lights on the HUD Panel - easy and quick to repair.

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable)
 F-1mvrn51h1-1

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MKI MOD 0 ISO-HUD CONSOLE SYSTEM

TABLE: UNIT 4A1

NAME: (Sub-system) SIGNAL JUNCTION BOX

NAEC-91-7958

DMG. NO./REV.: 621173-1

Page 12 of 20

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-PUNCTUAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS, (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)		
			PERSONNEL	SYSTEM	MISSION	POTENTIAL LOSS	DETECTABLE BY OPERATOR?	DETECTABILITY OF FAULTS	CLASSIFICATION LEVEL	PROBABILITY OF OCCURRENCE	TEST PROBLEM ONLY.
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)
1.2	(cont'd) Relay 518915-1	(4) K6	-	-	-	-	-	-	Yes	III	C

1) Open in the coil - loss of signals for the P14, P8, F4 & E1 Aircraft in the Test Simulator Mode.

II) Failure of the NO contacts to close upon actuation: A1, B1, C1, D1 - loss of the corresponding signal (E1, F4, F8, P14) in the Test Simulator Mode.

III) Failure of the NC contacts to close upon deactuation: A3, B3, C3, D3 - loss of corresponding signal (E1, F4, P8, P14) in the Ship' Input Mode.

These failures affect the lights on the H/D Panel - repair is quick and easy.

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Marginal; III-Very Unlikely); Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Unprobable; F-Inexistent).

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS_NKL MOD 01 ISO-HUD CONSOLE SYSTEM

TABLE: UNIT 4A1
NAME: (Sub-system) SIGNAL JUNCTION BOX
DNC. NO./REV.: 621173-1

NAEC-91-7958

Page 13 of 20

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON: PERSONNEL	SYSTEM	MISSION	FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES/ SAFETY CONTROLS)
						DETECTABLES BY LOSS	POTENTIAL LOSS	CLASSIFICATION OF HAZARD LEVEL	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)
1.2	(cont'd) Relay 510915-1	9) K7							
			I) Open in the Coil - loss of Signals for the (T2,T28, P18 & "spare" Aircraft in the Test Simulator Mode.	-	-	-	-	-	Yes III C
			II) Failure of the NO con- tacts to close upon actuation. A1,B1,C1,D1- loss of the corresponding Signal (T2, T28,P18 & "spare") in the Test Sim- ulator Mode.	-	-	-	-	-	Yes III C
			III) Failure of the NC contacts to close up- on deactua- tion: A3,B3, C3,D3-loss of the corre- sponding sig- nal (T2,T28, P18 & "spare") In the Ship's Input Mod.	-	-	-	-	-	Yes III C
									These failures affect the lights on the HMD Panel only - repair is quick and easy.

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic); II-Marginal; III-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Unprobable;
 F-Rarely)

(Failure Modes & Effects Analysis - System) SAFETY ANALYSIS Mk1 Mod 0 ISO-HUD CONSOLE SYSTEM

NAEC-91-7958

TABLE: UNIT 4A1
 NAME: (Sub-system) SIGNAL JUNCTION BOX
 Dwg. No./Rev.: 521173-1

Page 14 of 20

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
			PERSONNEL INJURY	SYSTEM LOSS	MISSION LOSS	DETECTION LOSS BY OPERATORS?	PROBABILITY OF OCCURRENCE (TEST) (HAZARD DENSITY)		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)
1.2	(cont'd) Relay 518915-1	h) KA	i) Open in the Coil - loss of Signals for the "3 future Air- craft design- ations" and all the Air- craft design- ations in the Test Simu- lator Mode (loss of 28V return).	-	-	-	-	-	Yes
			ii) Failure of the NO con- tacts to close upon actua- tion: A1,B1, C1,D1 - loss of the cor- responding Signals ("spare", "spare", 28V return-all signals), ("spare") in the Test Simulator Mode.	-	-	-	-	-	Yes
									III
									C

205 (A-189)

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable;
 F-Insignificant)

(Failure Modes & Effects Analysis - System) Safety Analysis MK1 MOD 0 ISO-HUD Console System

TABLE: UNIT 4A1

NAME: (sub-system) SIGNAL JUNCTION BOX

DMG. NO./REV.: 621173-1

NAEC-91-7958

Page 15 of 20

NAEC-91-7958

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
			PERSONNEL	SYSTEM	MISSION	POTENTIAL LOSS	DETECTABLE BY OPERATOR?	PROBABILITY OF OCURRENCE (HAZARD LEVEL)	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)
1.2	(cont'd) Relay 516915-1	b) NC							

III) Failure of the NC contacts to close upon deactivation; A3,B3,C3,D3-loss or all signals for the Aircraft Designation in the Ship's Input Mode (C3 carries the 28V return)

The failure of the C3 contact would affect (all) the lights of the A/C Designations on the HUD Panel - repair is quick and easy.

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic); II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Unprobable;
F-Temporary)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-MUD CONSOLE SYSTEM

TABLE: UNIT 4A1

NAME: (Sub-system) SIGNAL JUNCTION BOX

DN.G. NO./REV.: 621173-1

NAFC-91-7958

Page 16 of 20

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	PERSONNEL INJURY SEAT	EFFECT ON: SYSTEM	MISSION	FAILURE - HAZARD	COMMENTS: RECOMMENDATIONS: COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)		
							POTENTIAL LOSS	DAMAGE LOSS	DETECTION LOSS
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)
1.2	(cont'd) Relay 518915-1	j) k9		-	-	-	-	-	-
		i) Open in the coil - loss of the Ramp Motion and Trim Signals in the Test Simulator Mode.							
		ii) Failure of the NO contacts to close upon actuation: A1 or B1, C1 or D1-loss of the corresponding Signal (Ramp Motion, Trim in the Test Simulator Mode).							
		iii) Failure of the NC contacts to close upon deactivation: A3 or B3, C3 or D3-loss of the corresponding Signal (Ramp Motion, Trim in the Ship's Input Mode).							

207 (A-191)

NAFC-91-7958

{ Test problem only. However, due to the importance of this relay to work properly in the Ship's Input Mode, see the next entry below.

DANGER! According to the System Design analysis, the Signals for the Ramp Motion and Trim will be 0-28 MICRO AMP currents. With the Relay's contacts rating of 40 milliamp as minimum, this will not work and the circuit will have to be resorted. See the "General Note" & "RECOMMENDATION" in item 1.2.a (page 5).

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Occasional; C-Remote; D-Rare; E-Extremely Improbable);
P-Two = 10⁻¹¹ (I-I)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS_MK1 MOD_0 ISO-MUD_CONSOLE SYSTEM

TABLE: UNIT 4A1NAME: (Sub-system) SIGNAL JUNCTION BOXDNC. NO./REV.: 621173-1

NAEC-91-7958

Page 17 of 20

NAEC-91-7958

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON: PERSONNEL SYSTEM MISSION			FAILURE - HAZARD DETECTABILITY BY OPERATORS			FAILURE - HAZARD PROBABILITY OF OCcurring			COMMENTS / RECOMMENDATIONS / COMPENSATING PROVISIONS / (ACCIDENT PREVENTION MEASURES / SAFETY CONTROLS)
			LIGHTS	DAMAGE	POTENTIAL LOSS	LOSS	LOSS	LOSS	TEST	INPUT	TEST	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
1.2	(cont'd) Relay 548915-1	R) K10	-	-	-	-	-	-	Yes	III	C	

1) Open in the coil-loss of the Airspeed and Rate of Descent Signals in the Test Simulator Mode.

II) Failure of the NO contacts to close upon actuation: A1 or C1, B1 or C1, D1 - loss of the corresponding signals (RAS, CAS, Rate of Descent) in the Test Simulator Mode.

III) Failure of the NC contacts upon de-actuation: A3 or B3 or C3, D3 - loss of the corresponding signals (RAS, CAS, Rate of Descent) in the Test Simulator Mode.

Test problem only, but due to the serious situation in the Ship's Input Mode (see below), an improvement will have to be provided.

DANGER! According to the System design analysis, the Signals for the Rasp Motion and Trim will be 0-28 micro-Amp currents! With the Relay's contact rating of 40 milliAmp as minimum, this will not work and the circuit will have to be reported. See the "General Note" & "RECOMMENDATION" in Item 1.2.a (page 5)

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable; F-Insignificant)

(Failure Modes & Effects Analysis - System) Safety Analysis MKI Mod 0 ISO-HARD Console System

NAEC-91-7958

TABLE: UNIT 4A1

NAME: (Sub-system) SIGNAL JUNCTION BOX

Dwg. No./Rev.: 621173-1

Page 18 of 20

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	PERSONNEL SYSTEM	MISSION	EFFECT ON:	FAILURE - HAZARD		COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS
						POTENTIAL LOSS	PROBABILITY OF OCCURRENCE	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)
1.2	(cont'd) Relay 518915-1	1) Kill	-	-	-	-	Yes	III C
		1) Open in the Coil- Loss of the Rate of Descent and the Alt. Error ("Bag Y") Signals in the Test Simulator Mode.	-	-	-	-	Yes	III A
		iii) Failure of the NC contacts to close upon actuation on actuators A1, -C1 or D1	-	-	-	-	Yes	III A
		-Loss of the corresponding signals (Rate of Descent, Alt. Error) in the Test Simulator Mode.	-	-	-	-	Yes	III A
		1iii) Failure of the NC contacts to close upon deactivation: A1, -C3 or D3	(x)	(x)	(x)	(x)	Yes	I A
		-Loss of the corresponding signals (Rate of Descent, Alt. Error) in the Ship's Input Mode.	(x)	(x)	(x)	(x)	Yes	I A

NAEC-91-7958

DANGER! According to the System design analysis, the Signals for the Ramp Motion and Trim will be 0-20 milliamp currents! With the Relay's contact rating of 40 milliamp as minimum, this will not work and the circuit will have to be reworked. See the "General Note" & RECOMMENDATION" in item 1.2.a (page 5).

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Unprobable; F-Invisible).

(Failure Modes & Effects Analysis - System) Safety Analysis MK1 MOD 0 ISO-HUD Console System

MEC-91-7958

TABLE: UNIT 4A1

NAME: (Sub-system) SIGNAL JUNCTION BOX

DNG. NO./REV.: 621173-1

Page 19 of 20

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS / RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
			PERSONNEL INJURY	SYSTEM LOSS	MISSION LOSS	DETECTABLE BY OPERATORS?	HAZARD LEVEL CLASSIFICATION	TEST PROBLEMS	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)
1.2	(cont'd) Relay 518915-1	m) K12	-	-	-	Yes	III	C	
		1) Open in the Coil-loss of the Latitude Error ("Bug") & Range Sig- nals in the Test Simula- tor Mode.							Test problem only, but will have to be corrected - see below.
		II) Failure of the NO contacts to close upon activation: A1 or B1, C1 or D1-loss of the corre- sponding Sig- nals (Lat. Error, Range) In the Test Simulator Mode.				Yes	III	A	
		III) Failure of the NC contacts to close upon deactivation: A3 or B3, C3 or D3-loss of the corre- sponding Sig- nals (Lat. Error, Range) In the Ship's Input Mode.	(x)	(x)	(x)	(x)	I	A	DANGER! According to the System design analysis, the Signals for the Ramp Motion and Trim will be 0-28 microamp currents! With the Relay's contacts rating of 40 milliamp as minimum, this will not work and the circuit will have to be rewired. See the "General Note" & "RECOMMENDATION" in item 1.2-a (page 5).

210(A-194)

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic); II-Critical; III-Marginal; IV-Negligible;
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable;
 F-Impossible)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ALSO-HND CONSOLE SYSTEM

TABLE: UNIT 4A1NAME: (Sub-system) SIGNAL JUNCTION BOXDNG. NO./REV.: 621173-1

NAEC-91-7958

Page 20 of 20

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			PROBABILITY OF OCURRENCE (HAZARD LEVEL)	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)	
			PERSONNEL INJURY	SYSTEM LOSS	MISSION LOSS	DETECTABLE BY OPERATOR?					
						DAMAGE	POTENTIAL LOSS	LOSS	(1)	(2)	(3)
1.3	Connector J1 & J2	No problems are expected to develop in these components once the connections have been checked out, and the periodic check-out and Maintenance procedures are carried out - particularly after any accidental damage to the 4A1.							Yes	III-IV	B
1.4	Terminal Boards 701-7012										
1.5	Inside Wiring										

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Vegetable)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Casual; D-Rare; E-Extremely Improbable;
 F-Inconclusive)


[FAILURE MODES & EFFECTS ANALYSIS - SYSTEM] SAFETY ANALYSIS MKI MOD 0 LSO-HUD CONSOLE SYSTEM

TABLE: UNIT 4A2
NAME: [Sub-system] SYNCHRO JUNCTION BOX

NAEC-91-7958
 Page 1 of 21
 NAEC-91-7958

DNG. NO./REV.: 621107-1 (Schematic: 621120)
 (Wiring: 621123)

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD OCCURRENCE RATE (PERCENTAGE BY OPERATOR)	COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)
			POTENTIAL LOSS	DAMAGE LOSS	INJURY LOSS		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)
1.0	The Synchro Junction Box, located in the room area just below the Console at the LSO Platform, contains one transformer (T1), four synchro differential transmitters (B1, B2, B3 & B4 in the schematic below), eight transfer relays (K1-K8). The KB relay is a spare, and a number of terminal strips. The Synchro Junction Box provides for the electrical transfer of the following signals (either from the Ship or the Test Simulator) to the HMD Console:	<ul style="list-style-type: none"> • Wind Direction and velocity • SPM-44 True Air Speed (TAS) and Closing Air Speed (CAS) • Deck status (clear deck, foul deck) of the AC. 	(9)	(10)	(11)	(12)	(13)



NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (1-Catastrophic; 11-Marginal; 111-Tolerable; IV-Tolerable)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (h-Frequent; B-Frequent; C-Occasional; R-Rare; E-Extremely Unprobable; F-Improbable)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS - MK1 MOD 0 ISO-HUD CONSOLE SYSTEM

NAEC-91-7958

TABLE: UNIT 4A2

NAME: (Sub-system) SYNCHRO JUNCTION BOX

Dwg. No./Rev.: 621187-1

Page 2 of 21

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARD- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON: PERSONNEL SYSTEM	FAILURE - HAZARD				COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
				POTENTIAL LOSS	DAMAGED	DETECTION BY OPERATOR?	CATASTROPHIC HAZARD AND OPERATOR?	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)
1.1	Transformer 422977-1. Primary: 115VAC, 60Hz, 1 Phase Secondary: 28VAC, 5.00Amp. The secondary winding provides the current to the coils of the seven active Relays of the Synchro Junction Box (the 8th Relay is a spare). The Transformer is marked T1 on the Schematic Diagram.	i) Loss of the Primary power will cause the K1 thru K7 reset to the Ship's Input Mode losing all the signals through this Unit 4A2 in the Test Simulator Mode. ii) Loss of one of the two secondary windings function will cause the seven Relays to return to or stay in the Normally Closed Contacts, which is in the Ship's Input Mode.	-	-	-	-	-	Yes III D

NOTE: Hazard Level, Column 11, per MIL-STD-882B, para. 5.4.3.1 (I-Catastrophic; II-Marginal; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882B, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Unprobable; F-Insignificant)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 LSO-HUD CONSOLE SYSTEM

TABLE: UNIT 4A2

NAME: (Sub-system) SYNCHRO JUNCTION BOX

DNG. NO./REV.: 621187-1

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD PROBABILITY BY OPERATOR?	CLASSIFICATION (HAZARD LEVEL)	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)				
			PERSONNEL SYSTEM	MISSION	POTENTIAL LOSS							
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
1.2	B relay 516915-1, Socket mounted, 10Amp 4PDT, coil, 28VAC, 60Hz, single phase, max oper. current 0.55 Amp, contacts: max 10Amp resistive, 6Amp inductive load at 120VAC, 60Hz. Minimum current (contacts) to be 0.040Amp RMS, wave rectified. There are seven Relays for the transfer of Signals (Wind Velocity & Angle, SPN-44 TAS & CAS, Deck Status) to the HUD Console.	a) Kl										
		i) Open in the Coil-Loss or the Wind Angle Signals in the Test Simulator Mode.	-	-	-	-	-	-	Yes	III	C	This failure affects the Test check-out, not the Ship's Input Mode.
		ii) Failure of the NC contacts to close upon actuation: A1, B1, C1 (D1not wired) -Loss of the S1,S2 & S3 Wind Angle Signals in the Test Simulator Mode.	-	-	-	-	-	-	Yes	III	B	Even though these failures would affect only the Test procedures due to their high probability of occurrence, an improvement in the design is recommended. See below, item 1.2.a.iii.
		The Normally Closed Contacts (NC) carry the Ship's Inputs, and the Normally Open (NO) Contacts are for the Test Simulator Mode of Operation.										
		NOTE: From the Design Analysis, the signals that are being transferred in this Synchro Junction Box are 0-20 milliamps strong.										
		NOTE: From the Design Analysis, the signals that are being transferred in this Synchro Junction Box are 0-20 milliamps strong.										
		NOTE: Hazard Level, Column 11, per MIL-STD-882B, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible) Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Impossible)										
		DANGER! There is a certainty that the contacts, after their test in the 10Amp strong current, will not pass a weak current, even the 40 milliamp is too weak! That means that the situation as it is right now will not work!										
		RECOMMENDATION: Introduce the necessary changes in the Design and procedures (test) to assure work!										

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MKL MOD 0 ISO-HUD CONSOLE SYSTEM

TABLE: UNIT 4A2 NAME: (Sub-system) SYNCRO JUNCTION BOXDNC. NO./REV.: 621187-1Page 4 of 21

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON: PERSONNEL SYSTEM	MISSION	LOSS INJURY	LOSS DAMAGE	POTENTIAL LOSS	DETECTABLE BY OPERATOR?	HAZARD LEVEL (ASCENTRATION LEVEL)	PROBABILITY OF OCURRENCE	COMMENTS: RECOMMENDATIONS; COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)
1.2	(cont'd) Relay 510915-1	a) K1 111)									the reliable passage of the low current signals through (the contacts).

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Veasibly Probable; C-Occasional; D-Rare; E-Extremely Improbable;
 P-Inexpressible)

TABLE: UNIT 4A2

NAME: (Sub-system) SYNCIRO JUNCTION BOX

DMG. NO./REV.: 621107-1

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS "K1 MOD 01 SO-HUD CONSOLE SYSTEM

NAEC-91-7953

NAEC-91-7958

Page 5 of 21

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)
			PERSONNEL INJURY	SYSTEM LOSS	MISSION LOSS	HAZARD LEVEL DETECTION BY DETECTABLE OPERATOR?	PROBABILITY OF OCCURRENCE		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)
1.2	(cont'd) Relay 510915-1	b) K2	-	-	-	-	Yes	III	C
		i) Open in the Coil-Loss of the Wind Velocity Sig- nals S1,S2 & S3 in the Test Simu- lator Mode.	-	-	-	-	-		This failure affects the Test check-out, not the Ship's Input mode.
		ii) Failure of the NO con- tacts to close upon actuation: A1,B1,C1(D1 not wired)- Loss of the S1,S2,S3 Wind Velocity signals in the Test Simulator Mode.	-	-	-	-	Yes	III	B
		iii) Failure of the NC con- tacts to close upon deactuation: A1,B1,C3(D3 not wired)- Loss of the S1,S2,S3 Wind Velocity signals in the Ship's Input Mode.	(x)	(x)	(x)	(x)	Yes	I-II	A-B
									DANGER! There is a certainty that the contacts, after their test in the 10amp strong current, will not pass a weak current, even though the 40 milliamp is too weak! That means that the situation as it is right now will not work!
									RECOMMENDATION: Introduce the necessary changes in the Design and procedures (test)

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.2.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Unlikely; E-Extremely Unprobable;
F-Inimpossible)

Failure Modes & Effects Analysis - System Safety Analysis MIL-STD-883H Console System

NAME: (Sub-system) SYNCHRO JUNCTION BOX

TABLE: UNIT 4A2

NO.:

Dwg. No./Rev.: 621187-1

Page 6 of 21

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON: PERSONNEL SYSTEM	MISSION	LOSS	DETECTABLE BY OPERATOR?	DETECTABLE BY AUTOMATION	LOSS ACCUMULATIVE	COMMENT: RECOMMENDATIONS; COMPENSATING PROVISIONS; (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS.)				
										1	2	3	4
(1)													
1.2	(cont'd) Relay S18915-1	b) K2 1.1.1)											

NOTE: Hazard Level, Column 11, per MIL-STD-882a, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882a, para. 5.4.3.2 (A-Preventive; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Unprobable; F-Impossible).

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS_MKJ MOD Q ISO-MUD_CONSOLE SYSTEM

TABLE: UNIT 4A2

NAME: (Sub-system) SYNCHRO JUNCTION BOX

DWG. NO./REV.: 621187-1

NAEC-91-7958

Page 7 of 21

NAEC-91-7953

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			HAZARD LEVEL DETERMINED BY PERSONNEL DETECTION LOSS	PROBABILITY OF OCCURRENCE (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)	FAILURE - HAZARD COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)
			PERSONNEL	SYSTEM	MISSION			
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)
1.2	(cont'd) Relay 518915-1	c) R3						
		i) Open in the coil-Loss of the Wind Angle & Wind Velocity Sig- nals R1, R2 & R3, R1 in the Test Simula- tor Mode.	-	-	-	-	Yes	III
		ii) Failure of the NO con- tacts to close upon actuation A1 B1, C1, D1- Loss of the R1, R2 Wind Angle and R2, R1 Wind Velocity Sig- nals in the Test Simula- tor Mode.	-	-	-	-	Yes	III
		iii) Failure of the NC contacts upon deactua- tion: A3, B3, C3, D3-Loss of the Wind Angle & Wind Velocity Sig- nals R1, R2, R3, R1 in the Ship's Input Mode.	(x)	(x)	(x)	(x)	Yes	I-II
								A-B
								DANGER! There is a certainty that the contacts after their test in the 10amp strong current, will not pass a weak current, even the 40 milliamp is too weak! That means that the situa- tion as it is right now will not work!
								• RECOMMENDATION: Introduce the necessary changes in the Design and procedures (test) to assure

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable; F-Improbable)

FAILURE MODES & EFFECTS ANALYSIS - SYSTEM SAFETY ANALYSIS FOR THE C180-100 CONSOLE SYSTEM

TABLE: UNIT 4A2
NAME: (Sub-system) SYNCHRO JUNCTION BOX
DAG. NO./REV.: 621187-1

Page 8 of 21

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD PROBABILITY OF COMMITMENT (HAZARD LEVEL) CLASSIFICATION OF OPERATOR	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS, (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
			PERSONNEL INJURY	SYSTEM LOSS	MISSION LOSS		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)
1.2	(cont'd) Relay 518915-1	c) M3 III					

the reliable passage of the low current signals through (the contacts).

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic) II-Critical; III-Marginal; IV-Negligible;
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable;
 F-Inmissible)

TABLE: UNIT 4A2
NAME: (Sub-system) SYNCHRO JUNCTION BOX
DNC. NO./REV.: 621187-1

(Allergic Modes & Effects Analysis - System) Safety Analysis - MIL-MOD-0150-44D CONSOLE SYSTEM

NSEC-01-7953

NSEC-91-7958

Page 9 of 21

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-Failure Mode (HAZARD RELEASE MECHANISM)	EFFECT ON: PERSONNEL SYSTEM MISSION	FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
				DETECTABLE BY OPERATORS	DETECTABLE BY TEST EQUIPMENT	POTENTIAL LOSS	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)
1.2	(cont'd) Relay 516815-1	4) R4		-	-	-	Yes
			1) Open in the coil-loss of the SPN-42 True Air Speed Signals S1,S2,S3 in the Test Simulator Mode. II) Failure of the NC contacts to close upon actuation of A1,B1,C1 (D1 not wired)-Loss of the SPN-42 TAS Signals S1,S2,S3 in the Test Simulator Mode. III) Failure of the NC contacts to close upon deactivation of A3,B3,C3 (D3 not wired)-Loss of the SPN-44 TAS signals S1,S2,S3 in the ship's Input Node.	-	-	-	Yes
				-	-	-	Yes
							III B
							Even though these failures would affect only the Test Procedures, due to their high probability of occurrence, an improvement in the design is recommended. See below and item 1.2.e.iii.
							DANGER! There is a certainty that the contacts, after their test in the 10amp strong current, will not pass a weak current, even the 40 milliamp is too weak! That means that the situation as it is right now will not work!
							• RECOMMENDATION: Introduce the necessary changes in the design and procedures (test) to assure the reliable passage of the low current signals through the contacts.

NOTE:

Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable; F-Incredible).

TABLE: UNIT 4A2
 NAME: (Sub-system) SYNCHRO JUNCTION BOX
 DNG. NO./REV.: 621187-1

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 LSO-HUD CONSOLE SYSTEM

NAEC-91-7958

Page 10 of 21

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES / SAFETY CONTROLS)
			PERSONNEL	SYSTEM	MISSION	POTENTIAL LOSS	DETECTION BY OPERATOR?	PROBABILITY OF OCCURRENCE	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)
1.2	(cont'd) Relay 518915-1	a) K5							
		i) Open in the Coil - Loss of the SPN-4 closing Air Speed Signals S1-S2-S3 in the Test Simulation Mode.	-	-	-	-	-	Yes	III
		ii) Failure of the NO contacts to close upon actuation: A1, B1, C1 (D1 not wired) - Loss of the SPN-44 CAS Signals S1, S2, S3 in the Test Simulator Mode.	-	-	-	-	-	Yes	III
		iii) Failure of the NC contacts to close upon deactivation: A3, B3, C3(D3 not wired) - Loss of the SPN-44 CAS Signals S1, S2, S3 in the Sim's Input Mode.	(x)	(x)	(x)	(x)	(x)	Yes	I-II
									A-B
									DANGER! There is a certainty that the contacts, after their test in the 10Ωmp strong current, will not pass a weak current, even the 40 milliamp is too weak! That means that the situation as it is right now will not work!
									• RECOMMENDATION: Introduce the necessary changes in the

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882B, para. 5.4.3.2 (A-Frequent; B-Occasional; C-Reasonably Probable; D-Rare; E-Extremely Improbable; F-Inmissible)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-IUU CONSOLE SYSTEM

TABLE: UNIT 4A2
 NAME: (Sub-system) SYNCHRO JUNCTION BOX
 DNG. NO./REV.: 621087-1

NAEC-91-7958

NAEC-91-7958

Page 11 of 21

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	EFFECT ON:		FAILURE - HAZARD		COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS, (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)
		PERSONNEL	SYSTEM	MISSION	CAPABILITY OF PROTECTION	
		DAMAGE	POTENTIAL LOSS	DETECTABLE BY OPERATORS	HAZARD LEVEL	
		LOSS	LOSS	LOSS	LOSS	
		INJURY	LIVES	DETECTION	OPERATOR	
		SEIZES	LIVES	DETECTION	OPERATOR	
(1)	(2)	(3)	(4)	(5)	(6)	(11)
1.2	(cont'd) Relay 518915-1	a) xs	111)			

design and procedures (test)
to assure the reliable
passage of the low current
signals through (the contacts).

222 (A-206)

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable; F-Impossible)

TABLE: UNIT 4A2
 NAME: (Sub-system) SYNCIRO JUNCTION BOX
 Dwg. No./Rev.: 621167-1

(FAILURE MODES & EFFECTS ANALYSIS - System) SAFETY ANALYSIS MK1 MOD 0 ISO-IUD CONSOLE SYSTEM

NAEC-91-7958

Page 12 of 21

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
			POTENTIAL LOSS	DAMAGE LOSS	SMART LOSS	DETECTABLE BY SENSORS	DETECTION BY OPERATORS	PROBABILITY OF OCCURRENCE (HAZARD LEVEL)	
(1)			(5)	(6)	(7)	(8)	(9)	(10)	(11)
1.2	(cont'd) Relay 510915-1	f) K6	-	-	-	-	-	-	III
		1) Open in the Coll-Loss of the SPN-44 TAS Signal R2 and CAS Signal R1 In the Test Sim- ulator Mode.	-	-	-	-	-	-	III
		II) Failure of the NO con- tacts to close upon actuation: A1, B1(C1 & D1 not wired) -Loss of the SPN-44 CAS Signal R1 and /or TAS Sig- nal R2 In the Test Sim. Mode.	-	-	-	-	-	-	B
		III) Failure of the NC contacts upon deactua- tion: A3,B3 (C3AB3 not wired)-Loss of the SPN- 44 CAS Sig- nal R1 and/or TAS Signal R2 in the Ship's Input Node.	(x)	(x)	(x)	(x)	(x)	I-II	A-B

NAEC-91-7958

Even though these failures would affect only the test procedures due to their high probability of occurrence, an improvement in the design is recommended. See below and item 1.2.a.iii.

DANGER! There is a certainty that the contacts after their test in the 10Amp strong current even the 40 milliamp is too weak. That means that the situation as it is right now will not work!

RECOMMENDATION: Introduce the necessary changes in the Design and Procedures (test) to assure the reliable passage of the

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible); Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Unlikely).

(Failure Modes & Effects Analysis - System) Safety Analysis MIL-MOD-0150-HUD Console System

TABLE: UNIT 4N2

NAME: (Sub-system) SYNCRO JUNCTION BOX

DNC. NO./REV.: 621107-1

NAEC-91-7958

NAEC-91-7958

Page 13 of 21

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)			
			PERSONNEL	SYSTEM	MISSION	DETECTABILITY BY OPERATORS?	PROBABILITY OF OCURRENCE	HAZARD LEVEL				
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
1.2	(cont'd) Relay 516915-1	f) K6 111)										

low current signals through
(the contacts).

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rarely; E-Extremely Unlikely; F-Inconsequential)

TABLE: UNIT 4A2
 NAME: (Sub-system) SYNCHRO JUNCTION BOX
 DNG. NO./REV.: 621197-1

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-HUD CONSOLE SYSTEM

NAEC-91-7958

Page 14 of 21

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON: PERSONNEL SYSTEM	MISSION	FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)			
					DETECTABLE BY OPERATOR?	PROBABILITY OF OCURRENCE (HIGH AND LOW)	PROBABILITY OF TESTIFICATION				
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)			
1.2	(cont'd) Walty 518915-1	9) K7	1) Open in the Coil-Loss of the Deck Status Sig- nals in the Test Simula- tor Mode. 1.1) Failure of the NO con- tacts upon actuation: A1,B1,C1(D1 not wired)- Loss of the Deck Status Signals in the Test Simulator Mode.	-	-	-	-	Yes	III	C	Test check-out problem.
									B	DANGER! Even though these failures would affect only the test procedures due to their high probability of occurrence, an improvement in the design is recommended. See below and Item 1.2.iii.	
									A-B	DANGER! There is a certainty that the contacts, after their test in the 10amp strong current will not pass a weak current, even the 40 milliamp is too weak! That means that the situation as it is right now will not work!	
										• RECOMMENDATION: Introduce the necessary changes in the Design and procedures (test) to assure the reliable passage of the low current signals through the contacts).	

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Possible; C-Occasional; D-Rare; E-Extremely Unprobable; F-Inprobable)

NAEC-91-7958

Failure Modes & Effects Analysis - System) Safety Analysis MK1 MOD 0 ISO-HUD Console System
NAEC-91-7958

TABLE: UNIT 4A2
NAME: (Sub-System) SYNCHRO JUNCTION BOX
DNG. NO./REV.: 621187-1

Page 15 of 21

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)		
			PERSONNEL INJURY	SYSTEM LOSS	MISSION LOSS	POTENTIAL LOSS	DAMAGE LOSS	HAZARD OPERATOR?	PROBABILITY (HAZARD LEVEL)	SEVERITY (HAZARD LEVEL)	COCOMPATIBILITY
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)
1.2	(cont'd) Relay 510915-1	1) K8									This is a spare.

NOTE: The K8 is a spare Relay, to be used when any of the seven "active" Relays would be failing and in need of replacement.

The K8 Relay then would take place of that particular Relay, and its FMEA should be found under that one (page 3-14).

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Vigilant);
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable;
F-Impossibly)

TABLE: UNIT 4A2
 NAME: (Sub-system) SYNCHRO JUNCTION BOX
 DNG. NO./REV.: 621107-1


NAEC-91-7958

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MKI (MIL-DLQ-HUD) CONSOLE SYSTEM

Page 16 of 21

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD	COMMENTS: RECOMMENDATIONS: COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES / SAFETY CONTROLS)
			PERSONNEL	SYSTEM	MISSION		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)
1.3	Synchro Differential Transmitter. MIL-S-20109/22C-001. Made by: Vernitron Control Components, San Diego, CA 92073 (contact: Ron Campbell, Sr. Sales Eng'r, (714)-428-5581). Vendor's P/N: VCDX15-6N2. Primary Minding: Stator Voltage: Primary = 90 Secondary = 90 Primary Current: 38mAmp, 60MHz. Four of these components are used (1B1-B4) in this Unit 4A2, to adjust the nulls for the Wind Angle, Wind Velocity, SPM-44 True Air Speed and SPM-44 Closing Air Speed Signals, which are generated up in the Ship's Structure. General connections:	a) Bl 1) Increased friction in side of the Component will result in an increased accuracy of adjustment and, therefore, increased accuracy of the Wind Angle Signals S1, S2, S3.	?	x	?	-	Yes
							III
							D
							Periodic calibration and maintenance will keep the component working within its intended limits.
							This failure to occur within the short time after the check-out, during which time the function of this component is needed, is extremely improbable (in peacetime).

227 (A-211)



NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic) II-Critical III-Marginal IV-Negligible
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable; F-Invisible)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS_MKL MOD_0 LSO-JIUD_Console System

NAEC-91-7958

TABLE: UNIT 4A2

NAME: (Sub-system) SYNCIRO JUNCTION BOX

DNG. NO./REV.: 621187-1

Page 17 of 21

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARD- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			PROBABILITY OF OCCURRENCE	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
			POTENTIAL LOSS	MISSION	SYSTEM	PERSONNEL	HAZARD LEVEL BY OPERATORS	CATASTROPHIC LOSS		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)
1.3	(cont'd) Synciro Differential Transmitter MIL-S-20709/22C-001	b) B2	?	x	x	-	-	Yes	III	D

1) Increased friction inside of the Component will result in an increased inaccuracy of adjustment and, therefore, increased inaccuracy of the Wind Velocity Signals S1, S2,S3.

II) Mechanical bind (jamming) of the Motor against the Stator will cause the Wind Velocity signals S1,S2, S3 to be grossly inaccurate.

The probability of occurrence of this failure is extremely remote (in peacetime). Also, the pilot has other channels to get accurate information on the Wind Velocity.

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Impossible)

TABLE: UNIT 4A2
 NAME: (Sub-system) SYNCIRO JUNCTION BOX
 DMG. NO./REV.: 621107-1

(FAILURE Modes & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-MUD Console System

NAEC-91-7958

Page 18 of 21

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON: PERSONNEL SYSTEM MISSION	FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES / SAFETY CONTROLS)
				DETECTABLE BY OPERATOR?	PROBABILITY OF OCCURRENCE (HAZARD LEVEL)	CLASSIFICATION (1.1) (1.2) (1.3)	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)
1.3	(cont'd) Synciro Differential Transmitter MIL-S-20708/2C-001	c) B3	-	-	-	-	-
		1) Increased friction inside of the Component will result in an increased inaccuracy of adjustment-and, therefore, increased inaccuracy in the SPN-44 True Air Speed Signals S1,S2, S3.	Yes	III	D	Periodic calibration and Maintenance will keep the Component working within its intended limits.	Extremely improbable to occur (in peacetime). Also, the Pilot has other channels/means to get information on accurate True Air Speed.
		II) Mechanical bind (jamming) of the Rotor against the Stator will cause the SPN-44 True Air Speed Signals S1,S2, S3 to be grossly inaccurate.	Yes	I	E		

NOTE: Hazard Level, Column 11, per MIL-STD-802A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.1.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Unprobable; F-Insignificant)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MKL MOD 0 LSO-HUD CONSOLE SYSTEM

TABLE: UNIT 4A2

NAME: (Sub-system) SYNCRO JUNCTION BOX

DOC. NO./REV.: 621167-1

NAEC-91-7958

Page 19 of 21

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTION FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
			PERSONNEL LOSS	SYSTEM LOSS	MISSION LOSS	DETECTABILITY BY OPERATOR?	HAZARD LEVEL CLASSIFICATION	POTENTIAL COCONTRIBUTIVE FACTOR?	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)
1.3	(cont'd) Syncro Differential Transmitter MIL-S-20708/22C-001	d) B4	-	-	-	?	-	?	Yes
			1) Increased friction Inside of the component will result in an increased inaccuracy of adjustment and, therefore, increased inaccuracy in the SPN-44 Closing Air Speed Signals S1,S2,S3.						III D
			II) Mechanical bind (jamming) of the Rotor against the Stator will cause the SPN-44 Closing Air Speed Signals S1,S2, S3 to be grossly inaccurate.	(x)	(x)	(x)	(x)	(x)	I E
									Extremely Improbable to occur (in peacetime). Also, the pilot has other channels/means to get information on accurate True Air Speed.

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable)

(Failure Modes & Effects Analysis - System) Safety Analysis MIL-MOD 0 ISO-HUD Console System

TABLE: UNIT 4A2

NAME: [Sub-system] SYNCHRO JUNCTION BOX

MEC-91-7958

DAG. NO./REV.: 621167-1

Page 20 of 21

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTION MODE (HAZARD RELEASE MECHANISM)	EFFECT ON: PERSONNEL SYSTEM	MISSION	FAILURE - HAZARD PROBABILITY OF OCCURRENCE	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES / SAFETY CONTROLS)			
						DETECTABLE BY OPERATOR?	CASUALTY LEVEL	LOSS POTENTIAL	LOSS DAMAGE
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)
1.4	Synchro Dial Assembly 518420-1.	Pour of these are used, one each to "tune" one Synchro Differential Transmitter.	No problems are anticipated with this component in a well cared-for and maintained system.					Yes	III-IV E

Maker: Vesaline Products Div.
of Ostby & Barton Co., Warwick, RI.

Characteristics:

- Zero backlash
- Initial torque 15-20 oz. in.
- Corrosion resistant
- Ball driven planetary drive
- + 1 minute accuracy
- Withstands 100g shock in all planes/axes.

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional;
 D-Invisible)

TABLE: UNIT 4A2
 NAME: (Sub-system) SYNCHRO JUNCTION BOX
 DWG. NO./REV.: 621187-1

(Failure Modes & Effects Analysis - System) Safety Analysis MK1 MOD 0 ISO-HUD Console System

NAEC-91-7958

NAEC-91-7958

Page 21 of 21

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)			
			PERSONNEL	SYSTEM	MISSION	DETECTABLE BY OBSERVATION (HAZARD LEVEL)	POTENTIAL LOSS	COCONTRIBUTORY PROBABILITY	CLASSIFICATION (HAZARD LEVEL)	DETECTION BY OBSERVATION (HAZARD LEVEL)	POTENTIAL LOSS	COCONTRIBUTORY PROBABILITY
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
1.5	Connector J1 (NS17146R2/C28S)											
1.6	Terminal Boards T81-T86											
1.7	Relay Socket M12803/21-01 (For Relays K1-K8)											
1.8	Inside wiring											

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible); Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Impossible).

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS - MKL MOD 0 LSO-HUD CONSOLE SYSTEM

TABLE: UNIT 4A3

NAME: (Sub-system) NOVLAS-HUD INTERFACE ELECTRONICS BOX
 DWG. NO./REV.: 620522-1 (Schematic: 620528)
 (Wiring: 620529)


Page 1 of 3

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
		HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	PERSONNEL INJURY	SYSTEM LOSS	MISSION LOSS	DETECTION BY OPERATOR?	CLASSIFICATION LEVEL	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)
(1)	The HUD/NOVLAS Interface Electronics Box contains buffer electronics to allow independent intensity control. It contains a card cage assembly housing three lamp driver circuit boards, one power supply board, and an extended circuit board. It also contains a power switch, power monitor light and fuse holder assembly installed on it. Internal DC power supply. Internal AC power supply. To operate the electronics come from the auxiliary electronics box (Unit 2).							

Reduced copy of the Schematic Diagram 620528 is at right.

233 (A-217)

THIS PAGE IS BEST QUALITY PRACTICABLE
 FROM COPY FURNISHED TO DDC



NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Critical; II-Catastrophic; III-Tolerable); P=Ne negligible; Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Unlikely; E-Extremely Unprobable); P=Inf negligible

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS "C1_M01_01SP-IND_CONSOLE.SYSTEM

TABLE: UNIT 4A3

NAME: (Sub-system) MOVLAS-HUD INTERFACE ELECTRONICS BOX

EIN. NO./REV.: 620522-1 (Schematic: 620528)
TWIFING: 620529

VAC-91-7958

Page 2 of 3

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)			EFFECT ON: PERSONNEL SYSTEM			FAILURE - HAZARD PROBABILITY OF COINCIDENCE			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)	
		LIVES LOSS	INJURY LOSS	DAMAGE LOSS	POTENTIAL LOSS	MISSION	DETECTABLE BY OPERATOR?	CLASSIFICATION (HAZARD LEVEL)				
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
1.1	Fuse F03A250V4AS, two used, one in each of the two Transformer's Primary Winding feed lines of the 115VAC.	One of the two fuses burns out that will interrupt the electrical power feeding the Unit 4A3, and that will extinguish the MOVLAS lights and their corresponding "monitors" on the IND Console (on the left side of the ISO).	(x)	(x)	(x)	(x)	(x)	Yes	1	2	The probability of the fuse to burn out just in the moment of an aircraft approaching the landing strip and the Pilot depending only on the MOVLAS is extremely remote.	

NOTE:

Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible); Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Ocasional; D-Random; E-Extremely Improbable; F-Inconceivable)

(Failure Modes & Effects Analysis - System) Safety Analysis MIL-HD-0150-HUD Console System

TABLE: UNIT 4A3

NAME: (Sub-system) MOLAS-HUD INTERFACE ELECTRONICS BOX

DMG. NO./REV.: 620522-1

NAEC-91-7953

Page 3 of 3

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON: PERSONNEL SYSTEM	MISSION	FAILURE - HAZARD	COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES/ SAFETY CONTROLS)	
						HAZARD LEVEL (CLASSIFICATION BY OPERATOR?)	PROBABILITY OF OCCURRENCE
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)
1.2	Power Monitor Light, one Lamp M1099/11-001: Provides information to the personnel that the Power Switch on the Unit 4A3 is "on".	In case the Lamp burns out, the Power Monitor Light is "off" even if the switch is "on" - this can cause safety hazard to the personnel who might start working inside of the Unit 4A3 believing the Power is off.	-	-	-	-	Yes
1.3	Transformer 620522-2	No problem is foreseen for this component to fall (open winding) and thus to cause the function of the Unit 4A3 interrupted, once the check-out procedures have been satisfactorily performed before the landing activity.	No problem is foreseen for this component to fall (open winding) and thus to cause the function of the Unit 4A3 interrupted, once the check-out procedures have been satisfactorily performed before the landing activity.	Yes	III-III	D	D-E
1.4	A4 Power Supply Card 510937-1 provides the DC power for:	<ul style="list-style-type: none"> the Lamps (V_{Lamp} = 7VDC nom.) the A1 cards (V_{cc} = 12VDC, 5VDC) the "Ref" for A1 Cards (V_{REF} = 7.5VDC \pm 5%) 	No problem is foreseen in this card in a properly operated and maintained system.	Yes	III	E	E
1.5	Comparator Lamp Driver Card 510932-1 (A1, A2 & A3), Schematic Diagram: 510931.	No problem is foreseen for these solid state circuits in a well-maintained system.	Yes	III	E		

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic); II-Critical; III-Marginal; IV-Ineligible; Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Inapplicable)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 LSO-HUD CONSOLE SYSTEM

TABLE: UNIT 4A4
NAME: (Sub-system) TEST SIMULATOR INTERFACE BOX
DNC. NO./REV.: 621169-1

NAEC-91-7958
NAEC-91-7958
Page 1 of 2

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
			POTENTIAL LOSS	DAMAGE	MISSION		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)
1.0	The Test Simulator Interface Box is located in the LSO work station. It provides 115 VAC, 60 Hz, 15 ^W power to operate the test simulator and the means to connect the simulator to the HUD console for in-circuit testing. It allows one man to troubleshoot or calibrate the display subsystem from the location of the HUD console.						

Refer to the Block Diagram at right to see the interconnections of the Unit 4A4 to all other units of the System and to the Test Simulator (which at one time was called "Unit 5").




FIGURE 1
DISPLAY SUBSYSTEM
MK1 MOD 0 LSO-HUD CONSOLE SYSTEM

NOTE: Hazard Level, Column 11, per MIL-STD-882B, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, Column 12, per MIL-STD-882B, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Unprobable; F-Impressible)

(Failure Modes & Effects Analysis - System) Safety Analysis M00_0 LSO-HUD Console System

NAEC-91-7958

TABLE: UNIT 4A4
 NAME: Sub-system) TEST SIMULATOR INTERFACE BOX
 DNG. NO./REV.: 621189-1

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:				FAILURE - HAZARD			
			PERSONNEL	SYSTEM	MISSION	POTENTIAL LOSS	DETECTABLE BY OPERATOR?	POSSIBILITY OF ACCIDENT	COMMENTS: RECOMMENDATIONS; COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)
1.1	NOTES:									
		1) Considering that inside of this Box there are only "hard wire connections," no problems are foreseen once the Box is installed and checked-out, provided the periodic inspections and maintenance operations are carried out.								
		2) It is expected that the ratings and unmating of the line connectors of the Test Simulator's cables into the five receptacles on the Unit 4A4 will be performed in such a way that no water (particularly the salt water) will contaminate the pins/sockets.								
		3) It should be born in mind that this Unit 4A4, as well as the HUD Console in the deployed condition, is not protected against the "flying objects" as the case may be during an enemy attack in a battle. However, the scope of this work does not permit us to go into that scenario.								

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic); II-Critical; III-Marginal; IV-Tolerable
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable;
 F-Incredible)

TABLE: CABLES
NAME: (Sub-system) INTERCONNECTING CABLES
DNC. NO./REV.: 62115


(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 LSU-HUD CONSOLE SYSTEM

NAEC-91-7958

Page 1 of 8

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:	FAILURE - HAZARD
			PERSONNEL SYSTEM MISSION	POTENTIAL LOSS
			DAMAGE	LOSS
(1)	(2)	(3)	(4)	(5)
1.0	The Interconnecting Cables, W220 through W245, provide the interconnections among the Ship and Individual Units of the HUD Console System.		(6)	(7)
			(8)	(9)
			(10)	(11)
			(12)	(13)

Refer to the sketch at right, in which the 26 cables have been marked in the "Display Subsystem" block diagram.



NOTE: Hazard Level, Column 11, per MIL-STD-882B, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, Column 12, per MIL-STD-882B, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Inconsequential)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-HUD CONSOLE SYSTEM

NAME: (Sub-system) INTERCONNECTING CABLES

TABLE: CABLES

DNG. NO./REV.: 621145

MEC-91-798

Page 2 of 8

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			MISSION	PERSONNEL	FAILURE - HAZARD	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)	
			DETECTABLE BY OPERATOR?	POTENTIAL LOSS DAMAGE	POTENTIAL LOSS INJURY					
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	
1.1	Cable W220 (MOVLAS), carries the "23 Lamp" Signals (J1-L23) and the +5VDC return from Unit 1, Connector J1 (MOVLAS) to Unit 4A3, Connector J3.	a) An "open" in any of the 23 wires or connections ("Lamps" signals) - Loss of the corresponding light on the Mini-MOVLAS on the HUD Console. b) An "open" in the +5VDC return line - Loss of all the lights on the Mini-MOVLAS. c) A "short" between any two of the 23 "Lamp" wires - The corresponding two lights will be on, instead of only one. d) A "short" between any of the 23 "Lamp" wires and the ground - Loss of the corresponding light.	-	-	-	-	-	-	Yes (11)	(12)
										(13)

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Unprobable; F-Inprobable)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MKI MOD 0 ISO-HUD CONSOLE SYSTEM

TABLE: CABLES

NAME: Sub-system) INTERCONNECTING CABLES

DNC. NO./REV.: 621145

NAME: NMEC-91-7958

Page 3 of 8

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	EFFECT ON:			FAILURE - HAZARD		COMMENTS / RECOMMENDATIONS: COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)						
		HAZARDOUS- FUNCTIONAL FAILURE MODES (HAZARD RELEASE MECHANISM)	PERSONNEL INJURY	SYSTEM LOSS	MISSION LOSS	DETECTABLE BY OPERATORS?	POTENTIAL LOSS	PROBABILITY OF HAZARD OCCURRENCE					
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)	
1.1	(cont'd) Cable W220	a) A "short" of the +5VDC return and ground - Loss of all the lights.	-	-	-	-	-	-	Yes	III	E		None of these failures would represent a problem. Besides, the periodic check-out and maintenance procedures will diminish greatly the probability of these failures to occur.
1.2	Cable W221 carries the Aircraft Designation and Wave-off signals from Unit 1, Connector J2, to Unit 4A1, Connector J2.	An open in the LSO Wave-off or its return and in the ACIS Wave-off or its return will cause the loss of the Wave-off function.	x	x	x	x	x	x	Yes	I	E		RECOMMENDATION: Route the two pairs of Wave-off Signals through two different Cables.
1.3	Cable W222 carries the AC/AC (Power/Control) from Unit 1, Connector J3 to Unit 2, Connector J2.	An open in the wires carrying Ship's AC and the Main AC power will result in the loss of the System's function.	(x)	(x)	(x)	(x)	(x)	(x)	Yes	I	D		The periodic check-out and maintenance procedures will keep the Cable in good working order. Once checked out before the operation, it is not expected that the Cable would suffer any damage (in peace time).
1.4	Cable W223 carries the DC power from Unit 1, Connector J4 to Unit 2, Connector J1.	An open in a wire or connection - loss of that particular function of the System.	-	-	-	-	-	-	Yes	III	C		There are redundant channels of communication available.

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Marginal; III-Negligible; F-Impossible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Estremely Improbable)

FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS_NK1 MOD 0 ISO-HUD CONSOLE SYSTEM

NAME: 621145

TABLE: CABLES
NAME: (Sub-system) INTERCONNECTING CABLES

DMG. NO./REV.: 621145

Page 4 of 8

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS: RECOMMENDATIONS; COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)		
			PERSONNEL SYSTEM	MISSION LOSS	POTENTIAL DAMAGE	DETECTABLE BY OPERATOR?	CASUALTY (EARLY HAZARD INSTEAD)	PROBABILITY OCCURRING	TO OCCUR	PERIODICITY	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)
1.5	Cable W224 carries PLAT (Pilot Landing Aid Television) Signals from Unit 1, J5 to the PLAT System.	An open in the Wires or connection would cause a loss of the PLAT function.	(x)	(x)	(x)	Yes	II-III	D	The Hazard classification will depend on the need of the PLAT function. In good weather daylight, it could be as unimportant as a III, but at night or bad weather, it could easily be a III.		
1.6	Cable W225 carries the 2IMC Inter-Communication System Signals from Unit 1, J6 to the 2IMC System.	An open in the Wires or connections will cause the loss of the 2IMC System.	-	-	-	Yes	III	D	The Inter-Communication System is a redundant channel of communication between the ILSO and (PRV FLY) Pilot.		
1.7	Cable W226 carries the Wind (Angle & Velocity) and SPI-44 True Air Speed (TAS) and Closing Alt Speed (CAS) Signals from Unit 1, J7 to Unit 4A2, J1.	An open in the Wires or connections will cause an error in the corresponding signal that it carries.	(x)	(x)	(x)	Yes	III	D	The lost signals are amongst the redundant information arrangement. It would take all redundant branches to fail to cause a problem.		
1.8	Cable W227 carries the Rang Motion Trim, SPI-42, T.A.S. & C.A.S., Rate of Descent, Alt. Error, Lat. Error and Range Signals from Unit 1, J8 to Unit 4A1, J1.	An open in the Wires or connections will cause a loss of the corresponding signal.	(x)	(x)	(x)	Yes	III	D			
1.9	Cable W228 carries the Obstruction Light and the Pedestal Switch current from the Unit 2 to the Unit 3A4.	An open in the Wires or connections will cause a loss of: - Obstruction Light - Pedestal Light - Switch	-	x	-	-	Yes	II	D	The periodic check-out and maintenance procedures will assure this cable to be functioning when needed.	

241 (A-225)

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Unprobable; F-Inconsequential)

NAEC-91-7958

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS_MIL MOD_0 LSO-HUD CONSOLE SYSTEM

TABLE: CABLES

NAME: (Sub-system) INTERCONNECTING CABLES

DMG. NO./REV.: 621145

NAC-91-7958

NAC-91-7958

Page 5 of 8

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON: PERSONNEL SYSTEM			MISSION DETECTION BY OPERATOR?	PROBABILITY OF OCURRENCE	COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
			DAMAGE LOSS	POTENTIAL LOSS	MISSION DETECTION LOSS			
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)
1.10	Cable W229 carries the 115VAC power from Unit 2, J5 to Unit 4A3, J3.	An open in the wires or connections will cause a loss of the Unit 4A3 function (HUD-MOVLAS1).	(x)	(x)	(x)	(x)	(x)	(x)
1.11	Cable W230 carries the Ship's Power to the Unit 2, J3, and to the System.	An open in the wires or connections will render the HUD System inoperative.	(x)	(x)	(x)	(x)	(x)	(x)
1.12	Cable W231 carries the Deck Status Signals between Unit 2, TB4 and Unit 4A2, TB3 & 6.	An open in the "Poul" or the "Common" wire will cause a loss in the "Poul" Signal.	x	x	(x)	(x)	(x)	I D

242 (A-226)

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable; F-Improbable)

(Failure Modes & Effects Analysis - System) Safety Analysis Mk1 Mod 0 ISO-MUD Console System

TABLE: CABLES

NAME: (Sub-system) INTERCONNECTING CABLES

DIAG. NO./REV.: 621145

Page 6 of 8

NAEC-91-7958

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	PERSONNEL SYSTEM	MISSION	EFFECT ON:	FAILURE - HAZARD		COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS, ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
						DETECTABLE BY OPERATORS?	POTENTIAL LOSS OF OCCURRENCE	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)
1.13	Cable W232 carries the 23 Lamps and their return Signals from the NOVUS box A1200 to Unit 4A3.	I) An open in any of the 23 "Lamps" wires - Loss of one Light. II) An open in the return wire.	-	-	-	-	Yes	III
1.14	Cable W233 carries the Wind (Angle & Velocity) Signals from the Unit 4A2 to the Ship's Wind (Angle & Velocity) Syncros (or vice versa).	An open in any of the wires will cause an error in the Wind Angle or Wind Velocity display.	(x) (x) (x) (x) (x) (x)	(x) (x) (x) (x) (x) (x)	Yes	(I)-III	D	There are other means of communications to the pilot to guide him down.
1.15	Cable W234 carries the SPN-44 TAS & CAS Signals from Unit 4A2 to SPN-44 (or vice versa).	An open in any of the wires will cause an error or loss of the SPN-44 TAS or CAS displays.	(x) (x) (x) (x) (x) (x)	(x) (x) (x) (x) (x) (x)	Yes	(I)-III	D	RECOMMENDATION: If there is no redundancy in the warning arrangement, it is recommended to provide for it.
1.16	Cable W235 carries the Deck Status ("clear", "Common", "Woul") Signals from Unit 4A2, 7B3 to the Control Box (ship's). 1.17	An open in the "Common" or "Poul" wire will cause the loss of the warning.	x x (x) (x) (x) (x)	x x (x) (x) (x) (x)	Yes	I-III	D	RECOMMENDATION: If there is no redundancy in the warning arrangement, it is recommended to provide for it.
	Cable W236 carries the SPN-42 Signals (ACLS Lock-on, Mode I, II, III, & ACLS Wave-off) their return from Unit 4A1, to SPN-42.	I) An open in the Signal wires will cause the loss of that signal.	(x) (x) - - (x) (x)	(x) (x) - - (x) (x)	Yes	(I)-III	D	This would represent a loss of one of redundant paths of information available to the pilot.

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible); Hazard Probability, Column 12, per MIL-STD-882B, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Unprobable; F-Inprobable).

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS NKL MOD_0 LSO-HUD CONSOLE SYSTEM

NAME: (Sub-system) INTERCONNECTING CABLES

DNC. NO./REV.: 621145

Page 7 of 8

NAEC-91-7958

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODES (HAZARD RELEASE MECHANISM)			EFFECT ON: PERSONNEL SYSTEM			FAILURE - HAZARD			COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)
		DAMAGE	LOSS	POTENTIAL LOSS	MISSION	DETECTABLE BY OPERATORS?	CLASSIFICATION (HAZARD LEVEL)	PROBABILITY OF OCCURRENCE			
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)
1.17 (cont'd) Cable W236											
		(11) An open in the return wire will cause the loss of all the signals carried by the Cable W236.	(x)	-	(x)	(x)	Yes	(I)-III	E		
1.18	Cable W237 carries the Signals LSO Wave-off and its return.	An open in either wire will cause the loss of the LSO Wave-off Signal.	(x)	(x)	(x)	(x)	Yes	(I)-III	D		
1.19	Cable W238 carries the Signals of Ramp Motion and Trim and their returns from Unit 4A1 to FLOCS (Harmonization Computer).	An open in a wire will cause the loss of the corresponding Signal (Ramp Motion or Trim).	(x)	(x)	(x)	(x)	Yes	(I)-III	D		
1.20	Cable W239 carries the Signals of SPH-42 (TAS, CAS, Rate of Descent, Alt. Error, Lat. Error, Range) and their returns from 4A1 to SPH-42.	An open in a wire will cause the loss of the corresponding Signal.	(x)	(x)	(x)	(x)	Yes	(I)-III	D		
1.21	Cable W240 carries the Signals of the Aircraft Designations from the Cross Check J-B to 4A1.	An open in a wire will cause a loss of one AC Designation Signal.	-	-	-	-	-	Yes	III	D	

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MK1 MOD 0 ISO-HUD CONSOLE SYSTEM

NAEC-91-7958

TABLE: CABLES
 NAME: (Sub-system) INTERCONNECTING CABLES
 Dwg. No./Rev.: 621145

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:	FAILURE - HAZARD						COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES & SAFETY CONTROLS)	
				POTENTIAL LOSS	DAMAGE	LOSS	PERSONNEL	SYSTEM	MISSION	DETECTABLE BY OPERATOR?	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)
1.22	Cable W241		An open in a wire in these cables will cause the loss of that particular function in the Test Simulator mode.	-	-	-	-	-	-	Yes	III
1.23	Cable W242										D
1.24	Cable W243	Signals for the Test Simulator Application									
1.25	Cable W244	Ship's Power									
1.26	Cable W245										

245 (A-229)

NOTE: Hazard Level, Column 11, per MIL-STD-883B, para. 5.4.3.1 (I-Catastrophic; II-Marginal; III-Critical; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-883A, para. 5.4.3.2 (A-Frequent; B-Occasional; C-Reasonable; D-Rare; E-Extremely Unprobable; F-Inevidible.)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MIL-MIL-0 LSO-HUD CONSOLE SYSTEM

TABLE: UNIT 5
 NAME: (Sub-system) TEST SIMULATOR ASS'Y
 DMG. NO./REV.: 620598

NAEC-91-7958

Page 1 of 24

NAEC-91-7958

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)			EFFECT ON: PERSONNEL INJURY	SYSTEM LOSS	MISSION DAMAGE	DETECTABLE LOSS	CLASSIFICATION (HAZARD AND DANGER) PROBABILITY OF DETECTION BY OPERATOR?	PROBABILITY OF DETECTION BY SIMULATOR	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)	
		(1)	(2)	(3)								
1.0 DESCRIPTION												

The simulator (see Fig. 1) is a portable calibration and test device that synthesizes Signal and Synchro Junction Box inputs to calibrate the corresponding console displays or isolate a problem. The output signals incorporated in this simulator test box can be used to test the LSO Console operation without the SPN-42 ACS system or other ship's source outputs. The simulator can be used to test all display console displays (except PLAT monitor) in place or in the shop. The potentiometer controls, toggle switches and rotary switches permit checking of the functions as indicated on the simulator box.

The simulator is self-contained. It only requires 115V AC 60Hz to operate. It contains DC power supplies to generate the required output signals and a digital voltmeter to indicate the required level of output for each check point. Check point voltage data is available on each electronic drawing corresponding to the display or scale being tested. The potentiometers on the box permit adjustment of the voltage to the circuit under test to cover the full operating range for analog input voltage signals.

Operation with the simulator causes the relays in the Signal Junction Box to energize, transferring input signals from the normal ship's source to the simulator input signals. This permits testing of the console operation by one person with the simulator at the LSO platform.

A standard 115V 60Hz test synchro is used to test the displays driven by the ship's synchro output. The test synchro is a three line (S1, S2, S3) unit having 115V, 60Hz two line (R1, R2) reference input with a 0° to 360° dial at its end to adjust the output related to degree rotation. The S1, S2, S3 and reference signals are applied to the synchro junction box through relays which are closed for the test synchro inputs and open for normal operation from the ship's input synchro information.


NOTE: Hazard Level, Column 11, per MIL-STD-882B, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882B, para. 5.4.3.2 (A-Frequent; B-Occasional; C-Reasonably probable; D-Remote; E-Extremely improbable).

(Failure Modes & Effects Analysis - System) Safety Analysis YK1-M010150-100 CONSOLE SYSTEM
"AEC-O-7958"

TABLE: UNIT 5
NAME: (Sub-system) TEST SIMULATOR ASS'Y
DMG. NO./REV.: 620598

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
			POTENTIAL LOSS	DAMAGE LOSS	PERSONNEL INJURY	MISSION	DETECTABLE BY OPERATOR?	CLASSIFICATION TEST?	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)
(11)			(11)	(12)	(13)				

The following is a schematic of the test simulator circuitry.



247 (A-231)

Hazard Probability, Column 12, per MIL-STD-882B, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable;
F-Unlikely)


TABLE: UNIT 5
NAME: (Sub-system) TEST SIMULATOR ASS'Y
DMG. NO./REV. I 620598

(Failure Modes & Effects Analysis - System) Safety Analysis - MKI (W) 0150-IWU_Console System

NAEC-91-7958

Page 3 of 24

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)										EFFECT ON: PERSONNEL SYSTEM MISSION INJURY LOSS DAMAGE LIVES LOSS LOSS (1) (2) (3) (4) (5) (6) (7) (8) (9) (10) (11) (12) (13)	FAILURE - HAZARD CLASSIFICATION BY OPERATOR? DETECTABILITY LOSS LOSS POTENTIAL LOSS DAMAGE LIVES INJURY LIVES (11) (10) (9) (8) (7) (6) (5) (4) (3) (2) (1)	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)			
		PERSONNEL	SYSTEM	MISSION	DETECTABILITY	LOSS	POTENTIAL	LOSS	DAMAGE	LIVES	INJURY	LOSS	LOSS	LOSS	LOSS	LOSS	LOSS
(1)																	



248 (A-232)


NOTE: Hazard Level, column 11, per MIL-STD-882B, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, column 12, per MIL-STD-882B, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable)
F-Frequent

TABLE: UNIT 5
 NAME: (Sub-system) TEST SIMULATOR ASS'Y
 DRG. NO./REV.: 620598

(Failure Modes & Effects Analysis - System) Safety Analysis PAXL and Q LSO-HUD Console System
 NAEC-91-7958

Page 4 of 24

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTION MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			MISSION SYSTEM	LOSS DAMAGE	LOSS POTENTIAL LOSS	DETECTABLE BY OPERATOR?	HAZARD LEVEL (PROBABILITY OF OCCURRENCE)	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)	
			PERSONNEL	SYSTEM	HAZARD - HAZARD							
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	
1.1	System circuitry Considerations a) Power Supplies PS1 (24 VDC) PS2 (70 VDC) PS3 (28 VDC)	Failure of proper regulation resulting in large transients or consistent overvoltage(s).	-	-	*	-	-	No	II	D	If the DC power supplies produce large transients or consistent overvoltages, there is a possibility that the BUP console input conditioning boards and/or the indicators will be damaged.	
		provide DC power										• RECOMMENDATIONS: 1) Install overvoltage protection devices (OVP) across the power supply outputs.



When enough overvoltage is produced by the power supply, the OVP will short the power supply and the internal current limiting circuitry will shut the power supply down.

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Marginal; III-Negligible; IV-Inprobable; V-Critical); Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remoto; E-Extremely Inprobable; F-Impossible).

(Failure Modes, Effects Analysis - System) Safety Analysis 'KLMN_01SO-1W' Console System


NAEC-91-7958

TABLE: UNIT 5
 NAME: (Sub-system) TEST SIMULATOR ASS'Y
 Dwg. No./Rev.: 620598

Page 5 of 24

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD CLASSIFICATION (HAZARD LEVEL BY OPERATOR)	COMMENTS: RECOMMENDATIONS / COMPENSATING PROVISIONS / ACCIDENT PREVENTION MEASURES / SAFETY CONTROLS
			PERSONNEL	SYSTEM	MISSION		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)
1.1	a) (cont'd)						

250 (A-234)



- 2) Install power supply indicator lamps in parallel with the OVP. This lamp would inform the operator of a down power supply.
- 3) Utilize three additional positions on meter switch SW to check the output of the power supplies on the DWA

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible); Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Unprobable; F-Inconsequential)

Failure Modes & Effects Analysis - System Safety Analysis MIL-M-01704C CONSOLE SYSTEM

TABLE: UNIT 5

NAME: (Sub-system) TEST SIMULATOR ASS'Y

DMG. NO./REV.: 620598

MIL-STD-882A

NAEC-91-7958

Page 6 of 24

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES) SAFETY CONTROLS
			PERSONNEL INJURY	SYSTEM LOSS	POTENTIAL DAMAGE		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)
1.1	b) 115 VAC Relay power provides the power for the Relays in the Signal & Synchro J. boxes.	Failure in the 115 VAC Relay power.	-	-	-	-	III D
	c) Connectors:	1) Loss of circuit path	-	-	-	No	III C
		1) Multiple pin/socket connectors providing interface between the simulator and the IBD console systems:	1) Open crimp,				
			1) Foreign object blockage,				
			1) Bent pins				
		2) Incorrect circuit path	-	-	-	No	III C
		1) Bent pins					
		1) Foreign object short					
		Loss of circuit path	-	-	-	No	III C
		1) Connectors for external test points for DWN HI:	1) Open crimp				
			1) Foreign object blockage				
			1) Bent pins				

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic); II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (R-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable;
 F-Impossible)

(Failure Modes & Effects Analysis - System) Safety Analysis MKL MOD 0 ISO-HUD CONSOLE SYSTEM

TABLE: UNIT 5

NAME: (Sub-system) TEST SIMULATOR ASS'Y

DOC. NO./REV.: 620598

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)			
			POTENTIAL LOSS	DAMAGE	INJURY	DETERMINES HAZARD LEVEL BY OPERATOR?	PROBABILITY OCCURRENCE	IF PROPERLY SEATED, THERE SHOULD BE NO PROBLEMS WITH THESE GASKETS.				
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
1.2	a) Silicone gaskets - DWA M1 drawing 424392 - Instrument panel drawing 519281 Provide seals around the panel face and the DWA.	Seal break- down result- ing in water intrusion and possible simulator damage	-	-	x	-	No	III	E	If properly seated, there should be no problems with these gaskets.		
b) Rubber gaskets - MS51007-12 (1) - MS51007-10 (3) - MS51007-6 (1) Provide seals around connectors J1 - J5.	Seal breakdown 1) Rubber deteriorates due to environmental exposure (salt, water, etc.) II) Rubber dry rot	-	-	x	-	No	III	D				
1.3	The simulator enclosure drawing 517921. Encases the test simulator circuitry and instruments. The simulator enclosure is equipped with one handle.	Enclosure failure - Dropping the simulator - Handle failure	-	-	x	-	N/A	II-III	C	The test simulator weight 25 lbs. and is somewhat bulky 11.5" x 16" x 10". RECOMMENDATION: That a two-handled enclosure be considered for increased safety.		

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rarely; E-Extremely Unprobable)

(Failure Modes & Effects Analysis - System) Safety Analysis Document LSO-HUD CONSOLE SYSTEM

MEC-21-7958

TABLE: UNIT 5
NAME: (Sub-system) TEST SIMULATOR ASS'Y
DMG. NO./REV.: 620598

Page 8 of 24

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)					
			PERSONNEL INJURY	SYSTEM DAMAGE	MISSION LOSS	DETECTABILITY BY OPERATOR?	CLASSIFICATION (HAZARD LEVEL)	PROBABILITY OF OCCURRENCE	PERSONNEL INJURY	SYSTEM DAMAGE	MISSION LOSS	DETECTABILITY BY OPERATOR?	CLASSIFICATION (HAZARD LEVEL)	PROBABILITY OF OCCURRENCE
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)		
2.0	Digital Voltmeter MV and Meter Switch S8.	Switch S8 is required to select the function under test. The functions controlled by this switch are: 1. off/meter test 2. SPN A2 Alarmed, TMS/CLSG 3. rate of descent 4. ramp motion/trim 5. bug "x" 6. bug "y" 7. range	No function selection: - Switch S8 opens or shorts.	-	-	-	Yes	III	D	RECOMMENDATION: Arrange for a coincidence between the diag. 620766, Section B-B, and the Schematic diag. 621160, related to S8.				

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable;
F-Jimplausible)

NAEC-91-7958

TABLE: UNIT 3
NAME: (Sub-System) TEST SIMULATOR ASSY
DNG. NO./REV.: 620598

Failure Modes & Effects Analysis - System Safety Analysis (MIL-STD-882A, para. 5.4.3.1) [I-Catastrophic; II-Critical; III-Marginal; IV-Ineligible]
 HAZARD LEVEL: Column 11, per MIL-STD-882A, para. 5.4.3.1 (A-Frequent; B-Reasonably Probable; C-Ocasional; D-Remote; E-Extremely Improbable;
 F-Inconceivable)

MARC-91-7958
 Page 9 of 24

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS / RECOMMENDATIONS: COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES / SAFETY CONTROLS)			
			PERSONNEL	SYSTEM	MISSION	DETECTION BY OPERATORS	DETECTION BY SENSORS	LOSS				
STAFF	AIRCREW	LOSS	DANGER	POTENTIAL LOSS	LOSS	LOSS	LOSS	LOSS				
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
2.1	SPN-42 airspeed TAD/CLEO. Meter switch set position 2	a) no indication i) loss of 115 VAC input power ii) loss of fuses P1, P2, P3, or P4 - loss of AC power - loss of relay switching power iii) loss of PS3 (28 VDC) pwr. supply - internal failure b) incorrect indication i) fixed resistor R10(12KΩ) open or shorts iii) fixed resistor R11 (1.3KΩ) open or shorts	-	-	-	-	-	yes	III	D	Detectable by lamp D81 (AC power off)	

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Ineligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Ocasional; D-Remote; E-Extremely Improbable;
 F-Inconceivable)

TABLE: UNIT 5
NAME: (Sub-system) TEST SIMULATOR ASS'Y
DWG. NO./REV.: 620598

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS - MIL-MOD-01500-HD CONSOLE SYSTEM
 "AEC-Q-170G"

Page 10 of 24

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD	COMMENTS; RECOMMENDATIONS; COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES / SAFETY CONTROLS)
			PERSONNEL INJURY	SYSTEM DAMAGE	MISSION LOSS		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)
2.1	(cont'd)						
		1.1.1) Potentiometer R5 wiper arm lifts off or shorts					
		1.1.1) power supply PS3 (28 VDC) becomes un-regulated					
2.2	Rate of Descent. Mater switch SS position 3.	a) no indication	-	-	-	yes	III D
		b) loss of fuse F1, F2, F3, or F4					
		- loss of AC power					
		- loss of relay switching power					
		1.1.1) loss of PS3 (28 VDC) power supply - internal failure					

NOTE: Hazard Level, Column 11, per MIL-STD-882a, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882a, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Inprobable;
 F-Unlikely);

FAILURE MODES & EFFECTS ANALYSIS - SYSTEM ANALYSIS - MK1422010100-JUD CONSOLE SYSTEM

TABLE: UNIT 5
 NAME: (Sub-system) TEST SIMULATOR ASS'Y
 DNG. NO./REV.: 620598

NAEC-91-7958
 FRC-0-7958

Page 11 of 24

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)			EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
		PERSONNEL INJURY	SYSTEM DAMAGE	MISSION LOSS	POTENTIAL LOSS	DETECTABILITY BY OPERATORS?	HAZARD LEVEL	PROBABILITY OCCURRENCE			
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)
2.2	(con't)	b) incorrect indication	-	-	-	-	-	yes	III	D	When operating properly the DMM will display voltages in the range 0 - 11.2 volts.
2.3	Ramp motion/trim. Meter switch set position 4.	a) no indication	-	-	-	-	-	yes	III	D	low probability of simultaneous failures.

256 (A-240)

NOTE: Hazard Level, Column 11, per MIL-STD-882B, para. 5.4.3.1 (I-Catastrophic; II-Marginal; III-Critical; IV-Negligible); Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Unprobable; F-Improbable).

(Failure Modes & Effects Analysis - System) Safety Analysis - KCL Model CONSOLE SYSTEM

NAEC-91-7958

TABLE: UNIT 5
 NAME: (Sub-system) TEST SIMULATOR ASSY
 DNG. NO./REV.: 620598

Page 12 of 24

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD	PROBABILITY OF OCCURRENCE	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)
			PERSONNEL	SYSTEM	MISSION			
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)
2.3 (cont'd)		b) incorrect indication	-	-	-	-	yes	III

When operating properly the DMM will display voltages in the range -11.6 to +11.4 volts.

1) fixed resistor R7 (3.6kΩ) opens or shorts,

ii) fixed resistor R8 (2.7kΩ) opens or shorts,

iii) potentiometer R6 wiper arm lifts off or shorts,

iv) power supply PS3 (28 VDC) fails or becomes unregulated,

v) power supply PS1 (24 VDC) fails or becomes unregulated.

NOTE:

Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.2.1 (I-Critical; II-Catastrophic; III-Critical; IV-Negligible); Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable).

(P=Inexistent.)

TABLE: UNIT 5
 NAME: (Sub-system) TEST SIMULATOR ASS'Y
 DWG. NO./REV.: 620598

Page 13 of 24

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
			POTENTIAL LOSS	DAMAGE	INJURY	DETECTABILITY BY OPERATOR?	HAZARD LEVEL	PROBABILITY OF OCCURRENCE	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)
2.4	Bug "XX". Meter switch position 5.	a) no indication i) loss of 115 VAC input power ii) loss of fuses F1, F2, F3, or F4 - loss of AC power - loss of relay switching power iii) loss of PS3 (28 VDC) power supply - internal failure	-	-	-	-	yes	III	D

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Marginal; III-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable;
 F-Inapplicable)

Failure Modes & Effects Analysis - System Safety Analysis MK1/MOU_01SO-HUD Console System

NAEC-91-7958

TABLE: UNIT 5
NAME: (Sub-system) TEST SIMULATOR ASSY
DNG. NO./REV.: 620598

Page 14 of 24

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON: PERSONNEL INJURY	MISSION LOSS	DETECTABLE BY LOSS	OPERATOR? (HAZARD OCCURRENCE)	CLASSIFICATION LEVEL	COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES / SAFETY CONTROLS)		
								EFFECT ON: SYSTEM DAMAGE	POTENTIAL LOSS	FAILURE - HAZARD
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)
2.4	(cont'd)	b) incorrect indication	-	-	-	-	-	-	yes	III D
		i) potentiometer R1 wiper arm lifts off or shorts,								
		ii) power supply P3 (28 VDC) fails or becomes unregulated,								
		iii) power supply PS1 (24 VDC) fails or becomes unregulated.								
		a) no indication	-	-	-	-	-	-	yes	III D
		i) loss of 115 VAC input power.								
		ii) loss of fuse F1, F2, F3, or F4 - loss of AC power.								
		iii) loss of PS3 (28 VDC) and PS1 (24 VDC) power supplies - Internal failure.								
2.5	Bug "y". Meter switch S6 position 6.									
		Low probability of simultaneous failures.								

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Unprobable; F-Incredible)

(Failure Modes & Effects Analysis - System) Safety Analysis MK-101 ISO-HID Console System

TABLE: UNIT 5
 NAME: (sub-system) TEST SIMULATOR ASS'Y
 DRG. NO./REV.: 62059B

NAEC-91-7958

Page 15 of 24

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)			EFFECT ON: PERSONNEL SYSTEM			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
		DAMAGED	POTENTIAL LOSS	LOSS	DETECTION BY OPERATORS	HAZARD LEVEL	PROBABILITY OF OCCURRENCE				
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)
2.5	(con't)	b) Incorrect indication	-	-	-	-	-	-	yes	III	D
		i) potentiometer R2 wiper arm lifts off or shorts.									
		ii) power supply PS3 (38 vdc) fails or becomes unregulated.									
		iii) power supply PS1 (24 vdc) fails or becomes unregulated.									
		a) no indication	-	-	-	-	-	-	yes	III	D
		i) loss of 115 VAC input power,									
		ii) loss of fuse F1, F2, F3, or F4									
		- loss of AC power									
		- loss of relay switching power,									
		iii) loss of PS2 (70 vdc)									
2.6	Ranger. Meter switch set position 7.										

260 (A-244)

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Marginal; III-Critical; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable;
 F-Improbable)

{FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS - XE1_MPN_0152-100_CONSOLE SYSTEM}

NAC-91-7952

TABLE: UNIT 5
NAME: (Sub-system) TEST STIMULUS ASS'Y
DNC. NO./REV.: 620598

Page 16 of 24

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)			
			PERSONNEL	SYSTEM	MISSION	POTENTIAL LOSS	DAMAGE	LOSS				
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
2.6	(cont'd)	(iii) power supply - Internal failure b) Incorrect indication: i) Potentiometer R3 wiper arm lifts off or shorts. ii) Power supply Vs2 (70 VDC) becomes unregulated.	-	-	-	-	-	-	-	III	III	D

261 (A-245)

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Unprobable; F-Insignificant)

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MIL-MOD-9150-HUD CONSOLE SYSTEM

TABLE: UNIT 5

NAME: (Sub-system) TEST SIMULATOR ASS'Y

Dwg. No./Rev.: 1

NAEC-91-7958

Page 17 of 24

NAEC-91-7958

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:		FAILURE - HAZARD		COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS)
			PERSONNEL INJURY	SYSTEM LOSS	DETECTABLE BY OPERATORS	PROBABILITY OF OCURRENCE	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)
3.0	Test synchro S1 and associated circuitry. The 115VAC 60Hz single phase synchro motor provides the capability to monitor and test the following HUD console functions: 1) True Airspeed; 2) Closing air speed; 3) Wind velocity; 4) Wind angle. Two switches control operation of the test synchro. Switch S2 is the on-off synchro power switch and switch S3 is a four-position selector of the HUD console functions. The AC power circuitry is provided with an indicator lamp DS2 to show synchro power. The synchro select switch S3 is a five-deck waver switch controlling the synchro test functions.						
	Synchro select switch S3 positions 1, 2, 3, and 4.	a) No Indication	-	-	-	-	Yes III D
		i) Loss of 115 VAC input power					Detectable by lamp DS2
		ii) Switch S2 fails open					
		b) Incorrect indication	-	-	-	-	Yes III D
		i) Synchro select switch S3 shorts or opens					

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Marginal; III-Critical; IV-Negligible; V-Occasional; VI-Reasonably Probable; VII-B-Reasonably Unprobable; VIII-D-Remote; IX-E-Extremely Unprobable; X-F-Impossible). Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Occasional; C-Occasional; D-Remote; E-Extremely Unprobable; F-Impossible).

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS MIL-M-8150-HUD CONSOLE SYSTEM

NAEC-91-7458

TABLE: INIT-5
NAME: (Sub-system) TEST SIMULATOR ASS'Y
Dwg. No./Rev.: 620598

Page 18 of 24

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD	COMMENTS; RECOMMENDATIONS; COMPENSATING PROVISIONS; ACCIDENT PREVENTION MEASURES; SAFETY CONTROLS
			POTENTIAL LOSS	DAMAGE	PERSONNEL SYSTEM		
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)
4.0	NOVLAS - Manually Operated Visual Landing Aid System. Switch S10. The NOVLAS repeater duplicates, on the MFD console, the display of datum bar and weather lights that the pilot observes.	a) no indication i) loss of 115 VAC input power ii) loss of fuses F1, F2, F3, or F4 - loss of AC power - loss of relay switching power iii) loss of P3 (28 VDC) power supply - internal failure iv) switch S10 opens	-	-	-	-	yes III D

263 (A-247)

NAEC-91-7958

NOTE: Hazard Level, Column 11, per MIL-STD-882B, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Tolerable)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Unprobable; F-Improbable)

Failure Modes & Effects Analysis - System) Safety Analysis_MKC_MDN_0_LSO_HUD_CONSOLE System

TABLE: UNIT 5
 NAME: (Sub-system) TEST SIMULATOR ASS'Y
 DNG. NO./REV.: 620598

NAEC-91-7953

Page 19 of 24

NAEC-91-7958

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS, (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)
		POTENTIAL LOSS	DETECTABILITY BY OPERATORS	CLASSIFICATION (HAZARD LEVEL)	POTENTIAL LOSS	DETECTABILITY BY OPERATORS	CLASSIFICATION (HAZARD LEVEL)	
MISSION	SYSTEM	LIVE'S	DAMAGE	INJURY	LOSS	INJURY	LOSS	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)
4.0	(cont'd)	b) incorrect indication	-	-	-	-	-	yes
			i) power supply PS3 (28 VDC) becomes un-regulated					
			ii) switch S10 shorts					
5.0	Aircraft type. Switches S5 and S4 select the aircraft type to be displayed on the HUD console.	a) no indication	-	-	-	-	-	yes
		i) loss of 115 V.C input power						
		ii) loss of fuse F1, F2, F3, or F4						
		- loss of AC power						
		- loss of relay switching power						
		iii) loss of PS3 (28 VDC) power supply						- Internal failure
		iv) switch S6 and/or S4 opens						

264 (A-248)

NOTE: Hazard Level: Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic); II-Critical; III-Marginal; IV-Negligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably probable; C-Occasional; D-Remote; E-Extremely Unprobable;
 F-Insignificant)

(Failure Modes & Effects Analysis - System) Safety Analysis MIL-MOD Q1SQ-JUD Console System

MEC-9-7.958

TABLE: UNIT-5
 NAME: (Sub-system) TEST SIMULATOR ASS'Y
 DRG. NO./REV.: 620598

Page 20 of 24

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON: PERSONNEL SYSTEM	MISSION LOSS INJURY SEAT	FAILURE - HAZARD DETECTABLE BY OPERATOR?	PROBABILITY OF CLASSIFICATION (HAZARD LEVEL) DETECTION LOSS LOSS DAMAGE	COMMENTS: RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)		
							POTENTIAL LOSS	LOSS	LOSS
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)
5.0 (cont'd)		b) Incorrect indication	-	-	-	-	-	Yes	III D

1) Power supply PS3 (28 VDC) becomes un-regulated.
 2) Switch S6 and/or S4 short.

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Tolerable)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Unprobable;
 F-Improbable)

TABLE: UNIT 5
 NAME: (Sub-system) TEST SIMULATOR ASS'Y
 DNG. NO./REV.: 620598

(FAILURE MODES & EFFECTS ANALYSIS - SYSTEM) SAFETY ANALYSIS YKL/MON-0 LSCN-100 CONSOLE SYSTEM

MAR-2-91-7958

NAEC-91-7958

Page 21 of 24

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:			FAILURE - HAZARD			COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)			
			PERSONNEL	SYSTEM	MISSION	POTENTIAL LOSS	DAMAGES	DETECTABILITY BY OPERATORS?	HAZARD LEVEL	PROBABILITY OF OCURRENCE	(AC power off.)	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
6.0	Automatic Carrier Landing System (ACLS) status.	a) No indication 1) Loss of 115 VAC input power. The ACLS indicates a lock-on and one of three modes of operation as follows: Mode I - Full ACLS Landing Mode II - Instrument landing Mode III - "Talk Down" landing The ACLS indicators are powered by 28 VDC and testing is con- trolled by S5, a four position, double deck water switch.	-	-	-	-	-	-	Yes	III	D	Detectable by lamp DS1 (AC power off).

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Ineligible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Rare; E-Extremely Improbable)

(Failure Modes & Effects Analysis - System) Safety Analysis MKI M10152-100 Console System

NAEC-91-7958

TABLE: UNIT 5
 NAME: (Sub-system) TEST SIMULATOR ASS'Y
 DRG. NO./REV.: 620598

Page 22 of 24

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:				FAILURE - HAZARD				COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)	
			PERSONNEL	SYSTEM	MISSION	POTENTIAL LOSS	DAMAGE	INJURY	LIVES	DETECTABLE BY OPERATORS	CLASSIFICATION Hazardous Event	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
6.0	(cont'd)											

1. (11) loss of PS3
(28 VDC)
power supply
- internal
failure

2. (iv) switch S5
opens

3. (b) incorrect
indication

4. (i) power supply
PS3 (28 VDC)
fails or be-
comes unreg-
ulated

5. (ii) switch S5
shorts

NOTE: Hazard Level, Column 11, per MIL-STD-882B, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Veillible)
 Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable;
 F-Impossible)

(Failure Modes & Effects Analysis - System) Safety Analysis - VLSI MMU (149-110) CONSOLE SYSTEM

NAEC-91-7958
VAFS-01-7958
NAME: (Sub-system) TEST SIMULATOR ASS'Y
ITEM NO./REV.: 620598
TABLE: UNIT'S

Page 23 of 24

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS- FUNCTIONAL FAILURE MODE (HAZARD RELEASE MECHANISM)	EFFECT ON:				FAILURE - HAZARD				COMMENTS, RECOMMENDATIONS, COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES, SAFETY CONTROLS)	
			PERSONNEL SYSTEM	MISSION	POTENTIAL LOSS	DETECTION BY SMART	CLASSIFICATION (HAZARD LEVEL)	PROBABILITY OF OCURRENCE				
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)
7.0	ACLS wave off and LSO wave off switch, S9. This is a three position toggle switch (forward = LSO wave off, center = off, back = ACLS wave off). The LSO wave off activates red flashing lamps (90 flashes/min.). The ACLS wave off activates a blue flashing light (180 flashes/min).	no indication 1) loss of 115 VAC Input power 11) loss of fuse P1, P2, P3, or P4 - loss of AC power - loss of relay switching power 111) loss of PS3 (28 VDC) power supply - internal failure 1v) switch S9 opens or shorts	-	-	-	-	-	yes	III	D	Detectable by lamp DSI (AC power off).	

NOTE: Hazard Level, Column 11, per MIL-STD-802A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible)
Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable; F-Improbable)

(Failure Modes & Effects Analysis - System) Safety Analysis MIL-STD-883E

NAEC-91-7958

TABLE: UNIT 5
 NAME: (Sub-system) TEST SIMULATOR ASS'Y
 DNG. NO./REV.: 620598

Page 24 of 24

ITEM NO.	ITEM DESCRIPTION (COMPONENT, MODE OF OPERATION, FUNCTION)	HAZARDOUS-FUNCTIONAL FAILURE MODE (HAZARD MECHANISM)	EFFECT ON PERSONNEL	SYSTEM	MISSION	FAILURE - HAZARD		COMMENTS / RECOMMENDATIONS: COMPENSATING PROVISIONS (ACCIDENT PREVENTION MEASURES / SAFETY CONTROLS)
						DETECTABLE BY OPERATOR?	DETECTABILITY OF HAZARD LEVEL	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)
9.0	Clear deck/foul deck. The clear deck/foul deck indicators are controlled by a three pole, double throw switch, S7. A green light indicates a clear deck, while a red light indicates a fouled deck. These indicators are powered by 115 VAC.	a) no indication b) loss of 115 VAC input power c) loss of fuses F1, F2, F3, or F4 d) loss of AC power e) loss of relay switching power f) switch S7 opens g) incorrect indication h) switch S7 shorts	- - - - - -	- - - - -	- - - -	yes yes yes yes -	III III III III D	Detectable by lamp DSI (AC power off.)

NOTE: Hazard Level, Column 11, per MIL-STD-882A, para. 5.4.3.1 (I-Catastrophic; II-Critical; III-Marginal; IV-Negligible) Hazard Probability, Column 12, per MIL-STD-882A, para. 5.4.3.2 (A-Frequent; B-Reasonably Probable; C-Occasional; D-Remote; E-Extremely Improbable; F-Impossible)

NAEC-91-7958

This page intentionally left blank

270(A-254)

I

NAEC-91-7958

APPENDIX B
H/FMEA RECOMMENDATIONS SUMMARY

NAEC-91-7958

This page intentionally left blank

SUMMARY, SYSTEM SAFETY ANALYSIS
MK1 MOD 0 LSO-HUD CONSOLE SYSTEM

NAEC-91-7958

NO.	RECOMMENDATION	SSA		RELATED TO:					FOR:	
		UNIT	ITEM NO.	a	b	c	d	e	f	
1	It is recommended that the CRT and Yoke be enclosed by a protective cover if the only removal path is through the console front. The cover should be secured to the CRT envelope and provide access for the removal of the high voltage lead and connections to the CRT and yoke.	1	15.0.b	x	x	x	x	x	x	
2	Place a wide wire mesh screen over the front face of the projection lamp to preclude accident during maintenance.	1	23.0.a	x	x	x	x	x	x	
3	Create a sandwich of the combiner glass and a plastic neutral density filter on the observer side of the combiner glass.	1	24.0.a	x	x	x	x	x	x	
4	Incorporate a compression pin locking device on the side of the mirror and support assembly base to lock and maintain the support arm in the vertical attitude regardless of knurled knob tension.	1	24.0.a	x	x	x	x	x	x	
5	Incorporate a compression pin locking device on the spherical mirror hold-down latch.	1	24.0.a	x	x	x	x	x	x	
6	Provide a warning circuit within the LSO Console (aural & visual) to warn the user that an excursion has occurred which may, or may not, have caused damage that requires the attention of maintenance personnel.	2	1.0.a	x	x	x		x	x	
7	Provide individual indicators on the LSO console for each voltage as a confidence indicator ("GO"/"NO-GO").	2	1.0.a	x		x		x	x	
8	Provide overvoltage protection for each power supply output to bar against damaging transients.	2	1.0.a		x	x	x	x	x	
9	Replace the dependency of the main power control bus on the airflow switch - let loss of cooling airflow energize a warning indicator which coordinates with items 6 and 7 above.	2	1.0.a	x	x	x	x	x	x	

LEGEND:

- a - General Reliability, Simplification, Design Improvement
- b - Avoiding, Eliminating & Reducing Potential Hazards
- c - Controlling & Minimizing Potential Hazards
- d - Incorporation of Fail-Safe Principles
- e - Existing Design
- f - Future Design

SUMMARY, SYSTEM SAFETY ANALYSIS
MK1 MOD O LSO-HUD CONSOLE SYSTEM

NAEC-91-7958

NO.	RECOMMENDATION	SSA		RELATED TO:			FOR:		
		UNIT	ITEM NO.	a	b	c	d	e	f
10	Arrange with the vendor (Galland Henning Nopak, Inc. 1025 S. 4th St., Milwaukee, Wisc. 53215) to provide round and smooth corners and edges to avoid personal injury, on their dwg. C-22026CY.	3A1	1.1.2. 1.a	x	x	x		x	x
11	Arrange with the same vendor to provide ample radii to form round fillets between the attaching feet and the body of this part:	3A1	1.1.2. 1.b	x	x	x		x	x
	(Vendor's dwg. D-417SK; applies to Nos. 10, 11, 12)								
12	Arrange with the same vendor to incorporate an air purging or other means to get rid of the upper air bubble, to assure the gland to be always bathed in the hydraulic liquid.	3A1	1.1.2. 1.c	x	x	x		x	x
13	Arrange with the vendor (G.H. Nopak, Inc.) to specify ample radii in all fillets, especially those that could cause stress concentration, and to premachine the Round Stock to prepare it better for the welding to the tubing. See sketch below (Piston Rod, item 4 of Cylinder 620728-4)	3A1	1.1.2. 2.a	x	x			x	x

LEGEND:

- a — General Reliability, Simplification, Design Improvement
- b — Avoiding, Eliminating & Reducing Potential Hazards
- c — Controlling & Minimizing Potential Hazards
- d — Incorporation of Fail-Safe Principles
- e — Existing Design
- f — Future Design

SUMMARY, SYSTEM SAFETY ANALYSIS
MK1 MOD 0 LSO-HUD CONSOLE SYSTEM

NAEC-91-7958

NO.	RECOMMENDATION	SSA		RELATED TO:					FOR:	
		UNIT	ITEM NO.	a	b	c	d	e	f	
14	Arrange with the vendor to drill the perpendicular hole first and the axial hold second. See sketch: (Piston Rod, item 4 of Cylinder 620728-4)	3A1	1.1.2. 2.b	x	x				x	x
15	Arrange with the vendor to provide an assured "soft touch" for the upper limit of the stroke, and the hydraulic pressure release under the PISTON at reaching the upper limit of the stroke, derived from the movement of the PISTON.	3A1	1.1.2. 4	x	x				x	x
16	Arrange with the vendor to provide round/smooth corners and edges that can be expected to be handled/touched by the Navy personnel.	3A1	1.1.2. 5.a	x	x	x			x	x
17	Arrange with the vendor to specify radii for the important fillets! See sketch:	3A1	1.1.2. 5.b	x	x	x			x	x
18	For the Limit Switches LS1 & LS2 (620728-5):	3A1	1.1.3. b	x	x	x			x	x

LEGEND:

- a — General Reliability, Simplification, Design Improvement
- b — Avoiding, Eliminating & Reducing Potential Hazards
- c — Controlling & Minimizing Potential Hazards
- d — Incorporation of Fail-Safe Principles
- e — Existing Design
- f — Future Design

SUMMARY, SYSTEM SAFETY ANALYSIS
MK1 MOD 0 LSO-HUD CONSOLE SYSTEM

NAEC-91-7958


NO.	RECOMMENDATION	SSA		RELATED TO:					FOR:	
		UNIT	ITEM NO.	a	b	c	d	e	f	
18 (cont)	i) Introduce the necessary pre-operational checks of the System to be performed before the intended use. ii) Provide a protection arrangement to keep the debris from falling between the Roller and the Cam.									
19	Provide the two existing rubber inner pads 518987-2 to "overhang" the length of the Half Clamps; also, provide a 45° chamfer or round the inner edges of the Half Clamps.	3A1	1.1.4	x	x	x			x	x
20	It is always recommended (particularly for the new designs) to place the pump under the tank so that the Pump's suction column will be filled with a positive pressure. The need for priming will be avoided and the efficiency of the Pumps will increase.	3A2	1.2.1.a	x	x	x			x	x
21	Provide two gussets welded inside the Tank against the outside gussets 620579-11, to strengthen the support of the Air Motor/Pump Assembly.	3A2	1.2.1.b	x	x	x			x	x
22	Re-evaluate the filtering arrangement and specify the correct filter element for 620582-6.	3A2	1.2.2	x	x	x			x	x
23	For the Air Motor 518913-1: a) Mention in the Operation and Maintenance Manual the need to provide load to the Air Motor or otherwise limit its speed to 10% above that at maximum power. b) Provide an overspeed governor or shut-off arrangement.	3A2	1.2.3a	x	x	x			x	x
24	Evaluate the test results in cold, humid weather and introduce the corrective action as necessary, to avoid the air exhaust to get clogged by frozen, condensed moisture.	3A2	1.2.3b	x	x	x			x	x

LEGEND:

- a - General Reliability, Simplification, Design Improvement
- b - Avoiding, Eliminating & Reducing Potential Hazards
- c - Controlling & Minimizing Potential Hazards
- d - Incorporation of Fail-Safe Principles
- e - Existing Design
- f - Future Design

SUMMARY, SYSTEM SAFETY ANALYSIS
MK1 MOD 0 LSO-HUD CONSOLE SYSTEM

NAEC-91-7958


NO.	RECOMMENDATION	SSA		RELATED TO:		FOR:	
		UNIT	ITEM NO.	a	b	c	d
25	<p>Provide filtration of the Hydraulic Fluid to 25 micron or better, as required (to avoid contamination of the Hydraulic Fluid and the Relief Valve 517792-1).</p> <p>One possible way could be by changing the connection as shown in the following HYDRAULIC schematic:</p> 	3A2	1.2.6.a	x	x	x	x
26	<p>Re: Schematic Diagram 620580: Provide the connections in such a way that there will be an automatic interlocking, or an automatic return of Azimuth and Elevation to their aligned positions upon activating the HUD-Down switch(es) before the HUD would start moving down, or keep the LS2-B contacts always open(!)</p> <p>NOTES: (1) There should be no connection between pins LS4-2 and LS5-2!</p> <p>(2) For better reliability of the observation light to be "on", eliminate the LS1-B! (Leave only LS1-A to switch the observation light "on".)</p>	3A2	1.2.7.a	x	x	x	x

LEGEND:

- a - General Reliability, Simplification, Design Improvement
- b - Avoiding, Eliminating & Reducing Potential Hazards
- c - Controlling & Minimizing Potential Hazards
- d - Incorporation of Fall-Safe Principles
- e - Existing Design
- f - Future Design

SUMMARY, SYSTEM SAFETY ANALYSIS
MK1 MOD 0 LSO-HUD CONSOLE SYSTEM

NAEC-91-7957



NO.	RECOMMENDATION	SSA		RELATED TO:					FOR:	
		UNIT	ITEM NO.	a	b	c	d	e	f	
27	<p>For the Filter 518897-1:</p> <p>a) Provide also electrical Dirt Alarm (available in this line of filters).</p> <p>b) Provide enough room for easy/quick replacement of the Filter Element.</p> <p>c) Show the Dirt Alarm pointer and scale of this Filter on the assembly drawings:</p> <p>620582-1 (Piping Assy) & 620578-1 (Hydraulic Power Package).</p>	3A2	1.2.8.2	x	x	x		x	x	
28	Provide a tie between the upper end (the Filter 516965-1) and the Support Frame 620581-1 to eliminate or greatly reduce the vibration of the Filter.	3A2	1.2.8.3	x	x	x		x	x	
29	To assure an increased reliability of the Switch-Indicator A620741-4 (L8-S6) "HUD-DOWN" against short between contacts 7-8, provide a redundancy by connecting the contacts:	3A3	1.3.2. 4.c	x	x	x		x	x	
										

LEGEND:

- a — General Reliability, Simplification, Design Improvement
- b — Avoiding, Eliminating & Reducing Potential Hazards
- c — Controlling & Minimizing Potential Hazards
- d — Incorporation of Fail-Safe Principles
- e — Existing Design
- f — Future Design

SUMMARY, SYSTEM SAFETY ANALYSIS
MK1 MOD 0 LSO-HUD CONSOLE SYSTEM

NAEC-91-7958

NO.	RECOMMENDATION	UNIT	SSA ITEM NO.	RELATED TO:						FOR:
				a	b	c	d	e	f	
30	To increase the reliability in the K2 Relay 518915-1 against the NC contacts A failure to close, wire the K2 Relay according to the circuit diagram:	3A4	1.4.1. b.ii	x	x	x				x x
										
31	To increase the reliability in the K1 Relay 518915-1 against the NO contacts B failure to close, wire the K1 Relay according to the diagram below:	3A4	1.4.1. e.i	x	x	x				x x
										


LEGEND:

- a - General Reliability, Simplification, Design Improvement
- b - Avoiding, Eliminating & Reducing Potential Hazards
- c - Controlling & Minimizing Potential Hazards
- d - Incorporation of Fail-Safe Principles
- e - Existing Design
- f - Future Design

SUMMARY, SYSTEM SAFETY ANALYSIS

NAEC-91-7958

MK1 MOD O LSO-HUD CONSOLE SYSTEM

NO.	RECOMMENDATION	SSA		RELATED TO:				FOR:	
		UNIT	ITEM NO.	a	b	c	d	e	f
32	Wire the K2 Relay as shown to increase reliability against the short of the NO contacts B:	3A4	1.4.1. j.ii	x	x	x		x	x
									
33	Relay 518915-1, maximum current through contacts: 10 Amp, minimum current through contacts: 40 milli-Amp (!) Considering that very low current signals (38 micro/Amp!) will be handled in the System, the following is recommended: Change the circuitry to assure passage of low current signals!!! (Current amplification?, solid state?)	4A1	1.2 1.2.j.iii 1.2.k.iii 1.2.l.iii 1.2.m.iii	x	x	x	x	x	x
34	Relay 518915-1, maximum current through contacts: 10 Amp, minimum current through contacts: 40 milli-Amp (!) Considering that very low current signals (38 micro/Amp!) will be handled in the System, the following is recommended: Change the circuitry to assure passage of low current signals!!! (current amplification? solid state?)	4A2	1.2.a.iii 1.2.b.iii 1.2.c.iii 1.2.d.iii 1.2.e.iii 1.2.f.iii 1.2.g.iii	x	x	x	x	x	x
35	Include the necessary instruction (to observe the Power Monitor Light and switch off the Power Switch) for Maintenance personnel before they start working on the Unit 4A3.	4A3	1.2	x	x	x		x	x

LEGEND:

- a - General Reliability, Simplification, Design Improvement
- b - Avoiding, Eliminating & Reducing Potential Hazards
- c - Controlling & Minimizing Potential Hazards
- d - Incorporation of Fail-Safe Principles
- e - Existing Design
- f - Future Design

SUMMARY, SYSTEM SAFETY ANALYSIS
MK1 MOD O LSO-HUD CONSOLE SYSTEM

NAEC-91-7958

NO.	RECOMMENDATION	SSA		RELATED TO:					FOR:	
		UNIT	ITEM NO.	a	b	c	d	e	f	
36	Route the two pair of Wave-off Signals through two different Cables.	CABLES	1.2	x	x	x		x	x	
37	Evaluate a possible redundant provision of power and provide such design change if found viable and advantageous.	CABLES	1.11	x	x	x		x	x	
38	Provide redundancy in the warning arrangement of the Deck Status (Cable W235 and W231).	CABLES	1.16 1.11	x	x	x		x	x	
39	Provide overvoltage protection for three power supplies in the test simulator.	5	1.1a		x			x	x	
40	Install power supply indicator lamps to show power supply status. (Suggest usage with No. 39) Expediting fault isolation.	5	1.1a	x				x	x	
41	Utilize three additional positions on meter switch S8 to check power supply output on the DVM.	5	1.1a	x				x	x	
42	Install an indicator lamp to show AC to the switching relays.	5	1.1b	x				x	x	
43	Consider a two-handled simulator enclosure as the present one-handled enclosure is somewhat bulky. (11.5" x 16" x 10", 25lbs)	5	1.3			x		x	x	
44	Recommend the DVM be externally tested as the first step in fault isolation (where the DVM is utilized)	5	2.0 Procedures							
45	Recommend the drawing package be inspected for consistency.	5	2.0 3.0 4.0	x				x	x	

LEGEND:

- a - General Reliability, Simplification, Design Improvement
- b - Avoiding, Eliminating & Reducing Potential Hazards
- c - Controlling & Minimizing Potential Hazards
- d - Incorporation of Fail-Safe Principles
- e - Existing Design
- f - Future Design

NAEC-91-7958

This page intentionally left blank

DISTRIBUTION LIST

Internal

1115
9113
91118
91132 (2)
91133 (3)
92A12 (5)
9443 (2)

External

DDC (12)
COMNAVAVIRSYSCOM (AIR-5512) (2)
COMNAVAVIRSYSCOM (AIR-950D) (2)

REVISION LIST

REVISION	PAGES AFFECTED	DATE OF REVISION