

AD-A088 292

NEW JERSEY DEPT OF ENVIRONMENTAL PROTECTION TRENTON  
NATIONAL DAM SAFETY PROGRAM. CAMPBELLS POND DAM (NJ00517). RAHW--ETC(U)  
JAN 80 R MCDERMOTT

F/8 13/13


DACW61-79-C-0011

NL

UNCLASSIFIED

1 of 1  
28/Jan/80

END  
DATE  
FILMED  
9-80  
DTIC



MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS 1963 A

**LEVEL**

① B.S.

RAHWAY RIVER BASIN  
WEST BRANCH RAHWAY RIVER  
ESSEX COUNTY  
NEW JERSEY

SDTIC  
DELECT  
AUG 28 1980

**CAMPBELLS POND DAM**

**NJ 00517**

**PHASE 1 INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM**

AD A 088252



APPROVED FOR PUBLIC RELEASE  
DISTRIBUTION UNLIMITED.

**DEPARTMENT OF THE ARMY**

Philadelphia District  
Corps of Engineers  
Philadelphia, Pennsylvania

ORIGINAL CONTAINS COLOR PLATES: ALL DD  
REPRODUCTIONS WILL BE IN BLACK AND WHITE

**JANUARY 1980**

FILE COPY

DISTRIBUTION UNLIMITED. 8 21 020

Richard McDermott

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER NJ00517	2. GOVT ACCESSION NO. AD-A088252	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Inspection Report National Dam Safety Program Campbells Pond Dam (NJ00517), Rahway River Essex County, N.J. Basin, West Branch		5. TYPE OF REPORT & PERIOD COVERED FINAL report
6. AUTHOR(s) Rahway River, Essex RICHARD McDERMOTT County, New Jersey Phase I Inspection Report		7. PERFORMING ORG. REPORT NUMBER 15
8. PERFORMING ORGANIZATION NAME AND ADDRESS Storch Engineering 220 Ridgedale Ave. Flyham Park, N.J. 07932		9. CONTRACT OR GRANT NUMBER(s) DACW61-79-C-0011
11. CONTROLLING OFFICE NAME AND ADDRESS NJ Department of Environmental Protection Division of Water Resources P.O. Box CNO29 Trenton, NJ 08625		12. REPORT DATE January 1980
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) U.S. Army Engineer District, Philadelphia Custom House, 2d & Chestnut Streets Philadelphia, PA 19106		13. NUMBER OF PAGES 76
		18. SECURITY CLASS. (of this report) Unclassified
		18a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Copies are obtainable from National Technical Information Service, Springfield, Virginia 22151.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dams National Dam Safety Program Embankments Campbell's Pond Dam, New Jersey Visual Inspection Spillways Structural Analysis Seepage		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report cites results of a technical investigation as to the dam's adequacy. The inspection and evaluation of the dam is as prescribed by the National Dam Inspection Act, Public Law 92-367. The technical investigation includes visual inspection, review of available design and construction records, and preliminary structural and hydraulic and hydrologic calculations, as applicable. An assessment of the dam's general condition is included in the report.		

6

12 90

T

Yue

410891

**NOTICE**

**THIS DOCUMENT HAS BEEN REPRODUCED  
FROM THE BEST COPY FURNISHED US BY  
THE SPONSORING AGENCY. ALTHOUGH IT  
IS RECOGNIZED THAT CERTAIN PORTIONS  
ARE ILLEGIBLE, IT IS BEING RELEASED  
IN THE INTEREST OF MAKING AVAILABLE  
AS MUCH INFORMATION AS POSSIBLE.**



DEPARTMENT OF THE ARMY  
PHILADELPHIA DISTRICT, CORPS OF ENGINEERS  
CUSTOM HOUSE-2 D & CHESTNUT STREETS  
PHILADELPHIA, PENNSYLVANIA 19106

IN REPLY REFER TO

NAPEN-N

11 AUG 1980

Honorable Brendan T. Byrne  
Governor of New Jersey  
Trenton, New Jersey 08621

Dear Governor Byrne:

Inclosed is the Phase I Inspection Report for Campbells Pond Dam in Essex County, New Jersey which has been prepared under authorization of the Dam Inspection Act, Public Law 92-367. A brief assessment of the dam's condition is given in the front of the report.

Based on visual inspection, available records, calculations and past operational performance, Campbells Pond Dam, initially listed as a high hazard potential structure, but reduced to a significant hazard potential structure as a result of this inspection, is judged to be in poor overall condition. The dam's spillway is considered inadequate because a flow equivalent to 85 percent of the Spillway Design Flood - SDF - would cause the dam to be overtopped. (The SDF, in this instance, is one half of the Probable Maximum Flood). To ensure adequacy of the structure, the following actions, as a minimum, are recommended:

a. The spillway's adequacy should be determined by a qualified professional consultant engaged by the owner using more sophisticated methods, procedures, and studies within six months from the date of approval of this report. Within three months of the consultant's findings, remedial measures to ensure spillway adequacy should be initiated.

b. Within six months from date of approval of this report, the following engineering studies and analyses should be initiated:

(1) If it exists, the outlet works should be investigated and restored to a functional condition. If no outlet works exists, an adequate low level lake drain should be designed and installed.

(2) The masonry portion of the dam should be thoroughly inspected by a professional consultant engaged by the owner. The dam should be inspected with the lake drawn down and with the lake filled. Based on the inspections,

NAPEN-N

Honorable Brendan T. Byrne

together with any necessary subsoil, seepage and structural investigations, remedial measures to correct the leakage and other possible causes of distress should be determined then implemented.

c. Within six months from the date of approval of this report, the following remedial action should be completed:

(1) All trees and bushes on the embankment should be removed.

(2) Debris in the downstream channel should be removed.

d. The owner should develop written operating procedures and a periodic maintenance plan to ensure the safety of the dam within one year from the date of approval of this report.

e. The owner should develop an emergency action plan outlining actions to be taken by the operator to minimize the downstream effects of an emergency and establish a flood warning system for the downstream communities within six months from the date of approval of this report.

A copy of the report is being furnished to Mr. Dirk C. Hofman, New Jersey Department of Environmental Protection, the designated State Office contact for this program. Within five days of the date of this letter, a copy will also be sent to Congressman Minish of the Eleventh District. Under the provision of the Freedom of Information Act, the inspection report will be subject to release by this office, upon request, five days after the date of this letter.

Additional copies of this report may be obtained from the National Technical Information Services (NTIS), Springfield, Virginia 22161 at a reasonable cost. Please allow four to six weeks from the date of this letter for NTIS to have copies of the report available.


Accession For	
NTIS GRA&I	<input checked="" type="checkbox"/>
DDC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification _____	
By _____	
Distribution/ _____	
Availability Codes	
Dist	Avail and/or special
A	

NAPEN-N

• Honorable Brendan T. Byrne

An important aspect of the Dam Safety Program will be the implementation of the recommendations made as a result of the inspection. We accordingly request that we be advised of proposed actions taken by the State to implement our recommendations.

Sincerely,

  
JAMES G. TON  
Colonel, Corps of Engineers  
District Engineer

1 Incl  
As stated

Copies furnished:  
Mr. Dirk C. Hofman, P.E., Deputy Director  
Division of Water Resources  
N.J. Dept. of Environmental Protection  
P.O. Box CNO29  
Trenton, NJ 08625

Mr. John O'Dowd, Acting Chief  
Bureau of Flood Plain Management  
Division of Water Resources  
N.J. Dept. of Environmental Protection  
P.O. Box CNO29  
Trenton, NJ 08625



CAMPBELLS POND DAM (NJ00517)

CORPS OF ENGINEERS ASSESSMENT OF GENERAL CONDITIONS

This dam was inspected on 15 November and 23 November 1979 by Storch Engineers under contract to the State of New Jersey. The State, under agreement with the U.S. Army Engineer District, Philadelphia, had this inspection performed in accordance with the National Dam Inspection Act, Public Law 92-367.

Campbells Pond Dam, initially listed as a high hazard potential structure, but reduced to a significant hazard potential structure as a result of this inspection, is judged to be in poor overall condition. The dam's spillway is considered inadequate because a flow equivalent to 85 percent of the Spillway Design Flood - SDF - would cause the dam to be overtopped. (The SDF, in this instance, is one half of the Probable Maximum Flood). To ensure adequacy of the structure, the following actions, as a minimum, are recommended:

a. The spillway's adequacy should be determined by a qualified professional consultant engaged by the owner using more sophisticated methods, procedures, and studies within six months from the date of approval of this report. Within three months of the consultant's findings, remedial measures to ensure spillway adequacy should be initiated.

b. Within six months from date of approval of this report, the following engineering studies and analyses should be initiated:

(1) If it exists, the outlet works should be investigated and restored to a functional condition. If no outlet works exists, an adequate low level lake drain should be designed and installed.

(2) The masonry portion of the dam should be thoroughly inspected by a professional consultant engaged by the owner. The dam should be inspected with the lake drawn down and with the lake filled. Based on the inspections, together with any necessary subsoil, seepage and structural investigations, remedial measures to correct the leakage and other possible causes of distress should be determined then implemented.

c. Within six months from the date of approval of this report, the following remedial action should be completed:

(1) All trees and bushes on the embankment should be removed.

(2) Debris in the downstream channel should be removed.

d. The owner should develop written operating procedures and a periodic maintenance plan to ensure the safety of the dam within one year from the date of approval of this report.

e. The owner should develop an emergency action plan outlining actions to be taken by the operator to minimize the downstream effects of an emergency and establish a flood warning system for the downstream communities within six months from the date of approval of this report.

APPROVED: James G. Ton

JAMES G. TON  
Colonel, Corps of Engineers  
District Engineer

DATE: 18 July 80

**PHASE I REPORT  
NATIONAL DAM SAFETY PROGRAM**

**Name of Dam:** Campbells Pond Dam, NJ00517  
**State Located:** New Jersey  
**County Located:** Essex  
**Drainage Basin:** Rahway River  
**Stream:** West Branch Rahway River  
**Dates of Inspection:** November 15, 1979  
November 23, 1979

**Assessment of General Condition of Dam**

Based on visual inspection, past operational performance and Phase I engineering analyses, Campbells Pond Dam is assessed as being in poor overall condition.

Based on investigations of the downstream flood plain made in connection with this report, it is recommended that the hazard potential classification be downgraded from high to significant hazard.

Hydraulic and hydrologic analyses indicate that the spillway is inadequate. Discharge capacity of the spillway is not sufficient to pass the designated spillway design flood (SDF) without an overtopping of the dam. (The SDF for Campbells Pond Dam is equal to one-half the probable maximum flood.) The spillway is capable of passing approximately 42 percent of the probable maximum flood or 84 percent of the SDF. Therefore, the owner should engage a professional engineer experienced in the design and construction of dams in the near future to perform accurate hydraulic and hydrologic analyses relating to spillway capacity. Based on the findings of the analyses, the need for and type of remedial measures should be determined and then implemented.

Extensive leakage and other indications of possible distress in the dam were observed. Therefore, the masonry portion of the dam should be thoroughly inspected in the near future by a professional engineer experienced in the design and construction of dams. The dam should be inspected with the lake drawn down and also with the lake filled. Based on the inspections, together with any necessary subsoil, seepage and structural investigations, remedial measures to correct the leakage and other possible causes of distress should be determined and then implemented.

In addition, it is recommended that the following remedial measures be undertaken by the owner in the near future:

- 1) If it exists, the outlet works should be investigated and restored to a functional condition. If no outlet works exists, an adequate low level lake drain should be designed and installed.
- 2) All adverse vegetation on the embankments should be removed.
- 3) Debris in the downstream channel should be removed.


The owner of the dam should initiate, in the near future, a program of periodic inspection and maintenance, the complete records of which to be kept on file and made available to the public. A visual inspection of the dam and appurtenances by a professional engineer experienced in the design and construction of dams should be made annually and reported on a standardized check-list form. Repairs should be made as required and the following maintenance should be performed annually: remove trees and brush from the embankments, fill and sod any eroded surfaces of the embankments and clear the downstream channel. After the outlet works have been made operative or installed, at least once

Extensive leakage and other indications of possible distress in the dam were observed. Therefore, the masonry portion of the dam should be thoroughly inspected in the near future by a professional engineer experienced in the design and construction of dams. The dam should be inspected with the lake drawn down and also with the lake filled. Based on the inspections, together with any necessary subsoil, seepage and structural investigations, remedial measures to correct the leakage and other possible causes of distress should be determined and then implemented.

In addition, it is recommended that the following remedial measures be undertaken by the owner in the near future:

- 1) If it exists, the outlet works should be investigated and restored to a functional condition. If no outlet works exists, an adequate low level lake drain should be designed and installed.
- 2) All adverse vegetation on the embankments should be removed.
- 3) Debris in the downstream channel should be removed.

In the near future, the owner of the dam should develop written operating procedures and a periodic maintenance plan to insure the safety of the dam.

  
Richard J. McDermott, P.E.

  
John E. Gribbin, P.E.



OVERVIEW - CAMPBELLS POND DAM

29 NOVEMBER 1979

## TABLE OF CONTENTS

	<u>Page</u>
ASSESSMENT OF GENERAL CONDITION OF DAM	i
OVERVIEW PHOTO	iii
TABLE OF CONTENTS	iv
PREFACE	vi
SECTION 1 - PROJECT INFORMATION	1
1.1 General	
1.2 Description of Project	
1.3 Pertinent Data	
SECTION 2 - ENGINEERING DATA	8
2.1 Design	
2.2 Construction	
2.3 Operation	
2.4 Evaluation	
SECTION 3 - VISUAL INSPECTION	10
3.1 Findings	
SECTION 4 - OPERATIONAL PROCEDURES	14
4.1 Procedures	
4.2 Maintenance of Dam	
4.3 Maintenance of Operating Facilities	
4.4 Description of Warning System	
4.5 Evaluation	

TABLE OF CONTENTS (cont.)

	<u>Page</u>
SECTION 5 - HYDRAULIC/HYDROLOGIC	16
5.1 Evaluation of Features	
SECTION 6 - STRUCTURAL STABILITY	18
6.1 Evaluation of Structural Stability	
SECTION 7 - ASSESSMENT AND RECOMMENDATIONS	20
7.1 Dam Assessment	
7.2 Recommendations	
PLATES	
1 KEY MAP	
2 VICINITY MAP	
3 SOIL MAP	
4 GENERAL PLAN	
5 SECTIONS	
6 PHOTO LOCATION PLAN	
APPENDICES	
1 Check List - Visual Inspection	
Check List - Engineering Data	
2 Photographs	
3 Engineering Data	
4 Hydraulic/Hydrologic Computations	
5 Bibliography	



## PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 30214. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. It is important to note that the condition of dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that the unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The test flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM

CAMPBELLS POND DAM, I.D. NJ00517

SECTION 1: PROJECT INFORMATION

1.1 General

a. Authority

Public Law 92-367, August 8, 1972 authorized the Secretary of the Army, through the Corps of Engineers, to initiate a National Program of Dam Inspection throughout the United States. The Division of Water Resources of the New Jersey Department of Environmental Protection (NJDEP) in cooperation with the Philadelphia District of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the State of New Jersey. Storch Engineers has been retained by the NJDEP to inspect and report on a selected group of these dams. The NJDEP is under agreement with the Philadelphia District of the Corps of Engineers.

b. Purpose of Inspection

The visual inspections of Campbells Pond Dam were made on November 15 and November 23, 1979. The purpose of the inspections was to make a general assessment of the structural integrity and operational adequacy of the dam structure and its appurtenances.

## 1.2 Description of Project

### a. Description of Dam and Appurtenances

Campbells Pond Dam consists of a stone masonry free overflow spillway with earth embankments abutting each end. Reportedly, the dam does not include a low level outlet works. Three cast iron pipes penetrating the spillway are reportedly associated with water supply to the City of Orange. Two of these are abandoned while one may be currently in use.

A timber and steel bridge spans the entire length of the spillway and is supported by masonry abutments and piers.

At the junction between spillway and earth embankments, masonry training walls extend upstream and downstream from the spillway. Upstream from the spillway the training walls are located along a portion of the upstream faces of the embankments.

The spillway which is oriented approximately east/west has an overall length of 140 feet and a crest length of 124 feet. The overall length of the dam, including spillway and embankments is 300 feet. The hydraulic height of the dam is 18.5 feet while the structural height is estimated to be 22 feet.

### b. Location

Campbells Pond Dam is located in the South Mountain Reservation in the Township of Millburn, Essex County, New Jersey.

Constructed across the West Branch of the Rahway River, the dam impounds Campbells Pond. Principal access to the dam is by Brookside Drive which is a paved road located along the lake and downstream channel.

c. Size and Hazard Classification

Size and Hazard Classification criteria presented in "Recommended Guidelines for Safety Inspection of Dams," published by the U.S. Army Corps of Engineers are as follows:

SIZE CLASSIFICATION

	<u>Impoundment</u>	
	<u>Storage (Ac-ft)</u>	<u>Height (Ft.)</u>
Small	< 1000 and $\geq$ 50	< 40 and $\geq$ 25
Intermediate	$\geq$ 1000 and < 50,000	$\geq$ 40 and < 100
Large	$\geq$ 50,000	$\geq$ 100

HAZARD POTENTIAL CLASSIFICATION

<u>Category</u>	<u>Loss of Life</u> (Extent of Development)	<u>Economic Loss</u> (Extent of Development)
Low	None expected (no permanent structures for human habitation)	Minimal (Undeveloped to to occasional structures or agriculture)
Significant	Few (No urban developments and no more than a small number of inhabitable structures)	Appreciable (Notable agriculture, industry or structures)
High	More than a small number	Excessive (Extensive community, industry or agriculture)

The following data relating to size and downstream hazard for Campbells Pond Dam have been obtained for this Phase I assessment:

Storage: 62 acre-feet

Height: 18.5 feet

Potential Loss of Life:

Heavily used road (Brookside Drive) is located along the bank of the downstream channel for a distance of approximately 2500 feet. Failure of dam could possibly cause loss of life.

Potential Economic Loss:

A road bridge and an urban area of Millburn is located about 2700 feet downstream from the dam. A masonry dam impounding Diamond Mill Pond is located about 1700 feet downstream from the dam.

Therefore, Campbells Pond Dam is classified as "Small" size and "Significant" hazard potential.

d. Ownership

Campbells Pond Dam is owned and maintained by the City of Orange, 29 North Day Street, Orange, N.J. 07050

e. Purpose of Dam

The purpose of the dam is the impoundment of a recharge basin for nearby wells used for water supply for the City of Orange.

f. **Design and Construction History**

Campbells Pond Dam reportedly was originally constructed about 1899 in conjunction with a pump house located on the east bank of Campbells Pond. The purpose of the dam, at that time, was the impoundment of a reservoir for direct water supply to the City of Orange. Use of the pump house for water supply has since been discontinued.

g. **Normal Operational Procedures**

The dam and appurtenances are maintained by the Orange City Water Department. There is no fixed schedule of maintenance; repairs are made as the need arises.

Due to the lack of an outlet works, the lake is not lowered as a normal operational procedure. However, the lake reportedly normally becomes dry during the summer months at which time silt is removed from its bed.

1.3 **Pertinent Data**

a. <b>Drainage Area</b>	<b>6.4 square miles</b>
b. <b>Discharge at Damsite</b>	
<b>Maximum flood at damsite</b>	<b>Unknown</b>
<b>Outlet works at normal pool elevation</b>	<b>No known outlet</b>
<b>Spillway capacity at top of dam</b> <b>(Elev. 218.5)</b>	<b>3748 c.f.s.</b>

**c. Elevation (Feet above MSL)**

Top of Dam	Varies: 218.5 to 222.0
Maximum pool-design surcharge	219.1
Normal pool	214.0
Spillway crest	214.0
Stream bed at centerline of dam	200.0
Maximum tailwater	206.0

**d. Reservoir**

Length of maximum pool	1,300 feet
Length of normal pool	1,100 feet

**e. Storage (Acre-feet)**

Spillway Crest	21 acre-feet
Design Surcharge	70 acre-feet
Top of dam (Elev. 218.5)	62 acre-feet

**f. Reservoir Surface (Acres)**

Spillway Crest	4.6 acres
Top of dam (Elev. 218.5)	15 acres
Maximum Pool - design surcharge	16 acres

**g. Dam**

Type	Masonry/Earthfill
Length	300 feet
Height	18.5 feet

Side Slopes

Embankments - Upstream	2 horiz. to 1 vert.
- Downstream	3 horiz. to 1 vert.
Masonry - Upstream	1 horiz. to 3 vert.
- Downstream	1 horiz. to 12 vert.

Zoning	Unknown
Impervious core	Unknown
Cutoff	Unknown
Grout curtain	Unknown

h. Diversion and Regulating Tunnel N.A.

i. Spillway

Type	Uncontrolled masonry weir
Length of weir	124 feet
Crest elevation	214.0
Gates	N.A.
Upstream channel	N.A.
Downstream channel	Natural stream

j. Regulating outlets

None known.



## SECTION 2: ENGINEERING DATA

### 2.1 Design

No calculations, reports nor plans pertaining to the design of the dam are available.

### 2.2 Construction

No data nor reports pertaining to the construction of the dam are available.

### 2.3 Operation

No records of operation and maintenance of the dam subsequent to construction are available. Records of lake level monitoring are available. Reports of inspections made by the State of New Jersey in 1928 and 1929 are contained in the files of the NJDEP. According to the reports, several leaks were present in the masonry portion of the dam. The leaks were assessed as being of a nature that did not threaten the structural integrity of the dam. Suggestions for remedial measures were withheld pending further investigations.

### 2.4 Evaluation

#### a. Availability

Available engineering information is limited to that which is on file at the City Engineer's Office, City of Orange and at the NJDEP. The City of Orange file contains copies of lake level gaging records and maps showing the layout of the pump house and water main distribution. The NJDEP file contains correspondence and inspection reports.

b. Adequacy

Available engineering data pertaining to Campbells Pond Dam is not adequate to be of significant assistance to the performance of a Phase I evaluation. A list of absent information is included in paragraph 7.1.b.

c. Validity

The validity of engineering data cannot be assessed due to the absence of data.

## SECTION 3: VISUAL INSPECTION

### 3.1 Findings

#### a. General

The inspections of Campbells Pond Dam took place on November 15 and 23, 1979 by members of the staff of Storch Engineers. A copy of the visual inspection check list is contained in Appendix 1. The following procedures were employed for the inspection:

- 1) The embankments of the dam, appurtenant structures and adjacent areas were examined.
- 2) Areas of suspected seepage were noted and located.
- 3) The embankment and appurtenant structures were measured and key elevations determined with the use of a surveyor's level.
- 4) The embankment, appurtenant structures and adjacent areas were photographed.

#### b. Spillway

The grouted masonry overflow portion of the dam comprises the spillway. The downstream face of the spillway is generally aligned straight with some displacement of stones at the toe near its center. Also, some stones at the toe have been dislodged. Extensive patching and pointing of the stones on the downstream face is evident. The spillway apron which appeared to be composed of stone masonry overlaid with concrete, was observed to be in deteriorated condition. A timber strip which is located on the downstream face at the crest has a small section broken away near the center.

Extensive leakage was noted discharging from the downstream face. The leaks were numerous and extended across the entire length of the spillway. The leaks, which were discharging as jet flow under pressure, varied in diameter from approximately 1/4 inch to 2 inches. The estimated total quantity, with lake level at the spillway crest, is 150 gallons/minute. At the time of the first inspection, November 15, 1979, the lake level was at the spillway crest but was approximately 2 feet below the spillway crest at the time of the second inspection, November 23, 1979. It is assumed that most of the water lost from the lake during the time between inspections discharged through the dam as leakage. At the time of the second inspection, when the lake level was approximately 2 feet below the spillway crest, the leakage was observed to be considerably less in quantity than the leakage observed when the lake level was at the spillway crest.

Orange deposits were noted among the rocks approximately 15 feet downstream from the dam. It was not determined whether these were due to leakage through the dam or seepage under the dam.

The stone masonry training walls at either end of the spillway appeared to be structurally stable and in generally satisfactory condition with patching and pointing of the stones noted.

c. Embankments

Both embankments are generally grass covered with a paved roadway located along the crest. Also, brush and tree growth was observed on both embankments.

The upstream face of the east embankment consists of a continuation of the east training wall of the spillway. The upstream face of the west embankment consists, in part, of a continuation of the west training wall.

Both embankments appeared to be outwardly structurally stable with no evidence of distress observed. Also, no significant erosion nor seepage was observed.

d. Bridge

The timber roadway, steel beams and chain link fence appeared to be in satisfactory condition. The stone masonry piers upon which the bridge rests appeared to be structurally sound with extensive patching and pointing noted.

e. Reservoir Area

Campbell's Pond is bordered by woods along its east bank and by a paved road along its west bank. A brick pump house is located on the east bank of the lake approximately 300 feet from the dam.

f. Downstream Channel

The spillway discharges directly into the West Branch of the Rahway River which is a well defined stream with a bottom of cobbles and boulders. Approximately 1700 feet from the dam the stream widens into Diamond Mill Pond which has a surface area of approximately 3 acres and is impounded by a masonry and earth dam approximately 12 feet high.

A paved road (Brookside Drive) is located along the channel and varies in height above the stream bed from 4 feet to 8 feet. Approximately 2700 feet from the dam, the channel passes under Glen Avenue and into an urban area of Millburn. Buildings near the channel lie approximately 7 feet to 8 feet above the stream bed.

Extensive debris including large pieces of broken concrete was observed in the downstream channel in the immediate vicinity of the dam. Also, a few apparent well casings were observed in and adjacent to the channel immediately downstream from the dam. A small abandoned well pump house was noted adjacent to the channel in the vicinity of the dam.

## SECTION 4: OPERATIONAL PROCEDURES

### 4.1 Procedures

The level of water in Campbells Pond is regulated naturally by discharge over the masonry spillway portion of the dam. In addition, the lake water level apparently drops during dry weather due to leakage in the dam. Reportedly, the lake becomes dry during the summer season almost every year.

### 4.2 Maintenance of the Dam

Reportedly, there is no program of regular maintenance of the dam and appurtenant structures. Maintenance is performed on an "as needed" basis by the City of Orange Water Department which also conducts an annual inspection of the bridge.

Recent maintenance reportedly includes a cleaning of the downstream area of the dam and a patching, by concrete, of the downstream face of the spillway about 3 years ago. In addition, the lake bed reportedly is dredged each summer that it becomes dry.

### 4.3 Maintenance of Operating Facilities

The recording lake level gage located in the abandoned pump house is maintained in operating condition on an "as needed" basis.

### 4.4 Description of Warning System

Reportedly, no formal warning system is in use at the present time. However, surveillance is maintained by the City of Orange Water Department on a daily basis.

#### 4.5 Evaluation of Operational Adequacy

The apparent absence of a functioning outlet works contributes to a poor operational adequacy of the dam.

Maintenance documentation is poor and the maintenance program for the dam appears to be insufficient in the following areas:

1. Trees and brush on embankments.
2. Section of timber strip at crest of spillway broken away.
3. Extensive leaking of masonry portion of dam (spillway).
4. Extensive debris in immediate downstream area of dam.
5. Stones dislodged and displaced from downstream face of spillway.



## SECTION 5: HYDRAULIC/HYDROLOGIC

### 5.1 Evaluation of Features

#### a. Design Data

The quantity of storm water runoff that the spillway should be able to pass without an overtopping of the dam is based on the size and hazard classification of the dam. This runoff, called the Spillway Design Flood (SDF), is described in terms of frequency or probable maximum flood (PMF) depending on the extent of the dam's size and potential hazard. According to the "Recommended Guidelines for Safety Inspection of Dam," published by the U.S. Army Corps of Engineers, the SDF for Campbells Pond Dam falls in a range of 100-year frequency to 1/2 PMF. In this case the high end of the range, 1/2 PMF, is chosen because of the hazard potential caused by the road downstream from the dam.

The SDF hydrograph for Campbells Pond was computed by use of the HEC-1-DB computer program using Clark's Method employing parameters supplied by the Corps of Engineers. Hydrologic computations and computer output are contained in Appendix 4. The calculated SDF peak inflow for Campbells Pond Dam is 4529 c.f.s.

Discharge capacity for the spillway was computed by considering free discharge over the masonry portion of the dam. Hydraulic computations are contained in Appendix 4.

The elevation of the crest of dam varies from 218.5 to 222.0. For purposes of computer input, the top of dam was taken as 222.0. However, for overtopping analysis, the top of dam was assumed to be 218.5.

A routing of the SDF through Campbells Pond resulted in an overtopping of the dam by a depth of 0.6 feet. The overtopping would occur at the west end of the dam which has the lowest elevation (218.5) of any point on the dam. Accordingly, the subject spillway is assessed as being inadequate in accordance with criteria developed by the U.S. Army Corps of Engineers.

b. Experience Data

Reportedly, the dam has not been overtopped due to high lake water level. However, the roadway downstream from the dam reportedly is occasionally inundated during periods of heavy precipitation.

c. Visual Observations

No evidence was found at the time of inspection that would indicate that the dam had been overtopped.

d. Overtopping Potential

As indicated in paragraph 5.1.a., a storm of magnitude equivalent to the SDF would cause overtopping of the dam by a height of 0.6 feet above the top of the dam. The spillway is capable of passing approximately 42% of the PMF or 84% of the SDF with lake level equal to the top of the dam (elev. 218.5).

## SECTION 6: STRUCTURAL STABILITY

### 6.1 Evaluation of Structural Stability

#### a. Visual Observations

The embankments appeared, at the time of inspection to be outwardly stable. However, the masonry portion of the dam appeared marginally stable because of its numerous leaks and slight displacement at the toe and the presence of possible seepage containing orange deposits downstream from the toe.

An accurate determination of the severity of the observed indications of possible distress cannot be made without further investigation beyond the scope of a Phase I inspection.

#### b. Generalized Soils Description

The generalized soil description of the dam site consists of alluvial soil composed of stratified materials deposited by streams overlying glacial terminal moraine. The moraine consists of silt, sandy silt and silty sand with varying amounts of gravel and small amounts of clay deposited at the outer edge of the ice sheet during the Wisconsin stage of continental glaciation. The glacial terminal moraine overlies "Newark" basalt bedrock.

#### c. Design and Construction Data

Analysis of structural stability and construction data for the embankment and spillway structure are not available.

d. **Operating Records**

No operating records are available for the dam. Reports of inspections made by the State of New Jersey in 1928 and 1929 are contained in the files of the NJDEP. According to the reports, several leaks were present in the masonry portion of the dam. The leaks were assessed as being of a nature that did not threaten the structural integrity of the dam. Suggestions for remedial measures were withheld pending further investigations.

e. **Post Construction Changes**

No records of any post construction changes are available.

f. **Seismic Stability**

Campbells Pond Dam is located in Seismic Zone 1 as defined in "Recommended Guideline for Safety Inspection of Dams," which is a zone of very low seismic activity. Experience indicates that dams in Seismic Zone 1 will have adequate stability under seismic loading conditions if stable under static loading conditions. Campbells Pond Dam appeared at the time of inspection to be outwardly stable.

## SECTION 7: ASSESSMENT AND RECOMMENDATIONS

### 7.1 Dam Assessment

#### a. Safety

Based on hydraulic and hydrologic analyses outlined in Section 5 and Appendix 4, the spillway of Campbells Pond Dam is assessed as being inadequate.

The masonry portion of the dam exhibits extensive leakage and other indications of possible distress. The condition of the dam indicates that it could become unstable if corrective measures are not implemented.

#### b. Adequacy of Information

Information sources for this study include: 1) field inspections, 2) USGS quadrangle, 3) aerial topography, 4) aerial photography 5) inspection reports in NJDEP file and 6) consultation with representatives of the City of Orange. The information outlined is sufficient to allow a Phase I assessment as outlined in "Recommended Guidelines for Safety Inspection of Dams."

Some of the absent data are as follows:

1. Soils Report
2. Plans of the dam
3. Structural Design Report
4. Hydraulic Design Report

**c. Necessity for Additional Data/Evaluation**

Additional data and evaluation is considered necessary in order to assess the structural integrity of the dam.

**7.2 Recommendations**

**a. Remedial Measures**

Based on hydraulic and hydrologic analyses outlined in paragraph 5.1.a., the spillway is assessed as being inadequate. It is therefore recommended that a professional engineer experienced in the design and construction of dams be engaged in the near future to perform more accurate hydraulic and hydrologic analyses relating to spillway capacity. Based on the findings of these analyses, the need for and type of mitigating measures should be determined and then implemented.

In addition, it is recommended that the following remedial measures be undertaken by the owner in the near future.

- 1) If it exists, the outlet works should be investigated and restored to a functional condition. If no outlet works exists, an adequate low level lake drain should be designed and installed.
  
- 2) The masonry portion of the dam should be thoroughly inspected by a professional engineer experienced in the design and construction of dams. The dam should be inspected with the lake drawn down and with the lake filled. Based on the inspections, together with any necessary subsoil, seepage and structural investigations, remedial measures to correct the leakage and other possible causes of distress should be determined and then implemented.

3) All adverse vegetation on the embankments should be removed.

4) Debris in the downstream channel should be removed.

b. Maintenance

In the near future, the owner of the dam should develop written operating procedures and a periodic maintenance plan to insure the safety of the dam.

PLATES






PLATE I


STORCH ENGINEERS  
FLORHAM PARK, NEW JERSEY

INSPECTION AND EVALUATION OF DAMS  
KEY MAP

DIVISION OF WATER RESOURCES  
N.J. DEPT. OF ENVIR. PROTECTION  
TRENTON, NEW JERSEY

CAMPBELL POND DAM


I.D. N.J. 00517  
SCALE: NONE  
DATE: NOV., 1979



**CAMPBELL POND DAM**

**PLATE 2**

<p><b>STORCH ENGINEERS</b> FLORHAM PARK, NEW JERSEY</p>	<p><b>INSPECTION AND EVALUATION OF DAMS</b> <b>VICINITY MAP</b> <b>CAMPBELL POND DAM</b></p>	
<p><b>DIVISION OF WATER RESOURCES</b> N.J. DEPT. OF ENVIR. PROTECTION TRENTON, NEW JERSEY</p>	<p>I. D. N. J. 00517</p>	<p>SCALE: AS SHOWN DATE: NOV., 1979</p>



**Legend**

- AR Recent alluvium composed of stratified materials deposited by streams.
- GMM-24 Glacial Terminal moraine. Silt, sandy silt and silty sand with varying amounts of gravel and small amounts of clay deposited at the outer edge of the ice sheet during the Wisconsin stage of continental glaciation.
- Ib Triassic igneous rocks identified as "Newark" basalt and commonly called trap rock.

**NOTE:** Information taken from Rutgers University Soil Survey of New Jersey, Report No. 2, Essex County, and Geologic Map of New Jersey prepared by Lewis and Kummel.

**PLATE 3**

**STORCH ENGINEERS**  
 FLORHAM PARK, NEW JERSEY

---

**DIVISION OF WATER RESOURCES**  
 N.J. DEPT. OF ENVIR. PROTECTION  
 TRENTON, NEW JERSEY

**INSPECTION AND EVALUATION OF DAMS**


**SOIL MAP**

**CAMPBELL POND DAM**

---

I.D. NJ00517	SCALE: NONE
	DATE: NOV., 1979

CAMPBELLS POND



NOTE:  
Information taken from field  
inspection November 15 & 23, 1979.

LS POND





PLATE 4


STORCH ENGINEERS FLORHAM PARK, NEW JERSEY	DIVISION OF WATER RESOURCES N.J. DEPT. OF ENVIR. PROTECTION TRENTON, NEW JERSEY
INSPECTION AND EVALUATION OF DAMS <b>GENERAL PLAN</b> CAMPBELLS POND DAM	
I.D.N.J.00517	SCALE: NOT TO SCALE DATE: DEC., 1979



DAM SECTION

NOTES:

1. Information taken from field inspections November 15 & 23 1979
2. Elevations based on N.G.V.D. estimated from U.S.G.S. quadrangle.





**SPILLWAY SECTION**

**PLATE 5**

<b>STORCH ENGINEERS</b> FLORHAM PARK, NEW JERSEY	<b>DIVISION OF WATER RESOURCES</b> N.J. DEPT. OF ENVIR. PROTECTION TRENTON, NEW JERSEY
<b>INSPECTION AND EVALUATION OF DAMS</b>	
<b>SECTIONS</b>	
<b>CAMPBELLS POND DAM</b>	
I.D. N.J.00517	SCALE: NOT TO SCALE
	DATE: DEC. 1979

CAMPBELLS POND



NOTE:  
Information taken from field  
inspection November 15 & 23, 1979.



25 POND




PLATE 6

<p>STORCH ENGINEERS FLORHAM PARK, NEW JERSEY</p>	<p>DIVISION OF WATER RESOURCES N.J. DEPT. OF ENVIR. PROTECTION TRENTON, NEW JERSEY</p>
<p>INSPECTION AND EVALUATION OF DAMS <b>PHOTO LOCATION PLAN</b> CAMPBELLS POND DAM</p>	
<p>I.D.N.J.00517</p>	<p>SCALE: NOT TO SCALE DATE: DEC., 1979</p>

1 2

**APPENDIX 1**

**Check List - Visual Inspection**

**Check List - Engineering Data**

Check List  
Visual Inspection  
Phase I

Name of Dam Cambell Pond Dam County Essex State New Jersey Coordinators NJDEP

Date(s) Inspection 11/15/79 Weather Cloudy Temperature 50°F  
11/23/79

Pool Elevation at Time of Inspection 214.0 M.S.L. (11/15/79) Tailwater at Time of Inspection 200.0 M.S.L.  
212.0 (11/23/79)

Inspection Personnel:

John Gribbin Alan Volle  
Ronald Lai Thomas Miller  
Richard McDermott

J. Gribbin Recorder

Present: Paul Vertiramo, Reservoir Attendant (11/15/79)

CONCRETE/MASONRY DAMS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
<b>GENERAL</b>	Masonry overflow appeared structurally stable. Some stones near the toe were dislodged. A portion of downstream face at toe near center was slightly displaced possibly due to freeze-thaw cycles.	Overflow portion of dam composed of grouted stones.
<b>STRUCTURE TO ABUTMENT/EMBANKMENT JUNCTIONS</b>	Junctions at both ends of masonry overflow section appeared stable.	
<b>DRAINS</b>	None	Three cast iron pipes penetrate the masonry portion of dam. They did not appear to be drains.
<b>WATER PASSAGES</b>	None	
<b>APRON</b>	Concrete and masonry apron along toe of masonry portion of dam was in generally poor condition. Pieces of concrete were broken away.	Recommend further inspection and corrective measures.
<b>VERTICAL AND HORIZONTAL ALIGNMENT</b>	Appeared to be straight. Small section of spillway crest broken away.	

CONCRETE/MASONRY DAMS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS CONCRETE SURFACES	Evidence of extensive patching and pointing observed on downstream face.	
STRUCTURAL CRACKING	Cracks observed in downstream face and training walls appeared to be surface cracks.	
CONSTRUCTION JOINTS	No distress observed.	
MONOLITH JOINTS	N.A.	
LEAKAGE	Numerous leaks observed on downstream face of masonry portion of dam. Total leakage approx. 150 gal./min. when lake level at top of spillway.	Recommend further inspection and corrective measures.
SEEPAGE	Flow of water containing orange deposits was emerging approx. 15 feet downstream from toe. Flow could be seepage under dam or accumulation of leakage through dam.	Further investigations are recommended.

EMBANKMENT

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
GENERAL	Paved roadway on crest appeared to be in satisfactory condition. Numerous trees and brush growth.	
JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM	Appeared stable.	Spillway training walls extend along portion of upstream faces of embankments.
ANY NOTICEABLE SEEPAGE	None observed.	
STAFF GAGE AND RECORDER	None	
DRAINS	None observed.	

EMBANKMENT

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS	None observed	
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	None observed	
SLOUGHING OR EROSION OF EMBANKMENT AND ABUTMENT SLOPES	Some erosion at training walls.	
VERTICAL AND HORIZONTAL ALIGNMENT OF THE CREST	Vertical: west embankment crest pitches down from spillway to west end of dam. Horizontal: curved	
RIPRAP FAILURES	None observed	

OUTLET WORKS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE SURFACES IN OUTLET CONDUIT	N.A.	Reportedly, the dam has no outlet works.
INTAKE STRUCTURE	N.A.	
OUTLET STRUCTURE	N.A.	
OUTLET CHANNEL	N.A.	
GATE AND GATE HOUSING	N.A.	



SPILLWAY

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE WEIR	<p>Conc. weir fitted with timber strip at crest. Timber strip in generally good condition - one small portion broken away.</p>	
APPROACH CHANNEL	<p>N.A.</p>	
DISCHARGE CHANNEL	<p>Spillway discharges directly into downstream channel.</p>	
BRIDGE AND PIERS	<p>Bridge in generally satisfactory condition. Masonry piers appeared to be in satisfactory condition. Evidence of extensive pointing was observed.</p>	

**INSTRUMENTATION**

<b>VISUAL EXAMINATION</b>	<b>OBSERVATIONS</b>	<b>REMARKS OR RECOMMENDATIONS</b>
<b>MONUMENTATION/SURVEYS</b>	None	
<b>OBSERVATION WELLS</b>	None	
<b>WEIRS</b>	None	
<b>PIEZOMETERS</b>	None	
<b>OTHER</b>	Recording lake level gage located in original pump house on east bank of lake.	Lake level monitored by maintenance personnel

RESERVOIR

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SLOPES	Shore slopes have average pitch of approx. 20%. Entire shore of lake is wooded.	
SEDIMENTATION	Soundings in vicinity of spillway indicate silt deposits approx. 6 feet thick.	
STRUCTURES ALONG BANKS	Original brick pump house (no longer functioning) located on east bank. Paved road located along west bank.	

DOWNSTREAM CHANNEL

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
<p>CONDITION (OBSTRUCTIONS, DEBRIS, ETC.)</p>	<p>Considerable debris was present immediately downstream from the dam. Further downstream, the channel is well defined, rock lined and free of significant obstructions.</p>	<p>Recommend removal of debris.</p>
<p>SLOPES</p>	<p>The banks have slopes of approximately 4:1 and are wooded.</p>	
<p>STRUCTURES ALONG BANKS</p>	<p>No buildings are located along the channel for approx. 2700 feet downstream. A small lake and masonry dam is located approx. 1700 feet downstream from the dam. A paved road (Brookside Drive) is located along the channel bank for approx. 2500 feet. A road bridge is located 2700 feet from dam.</p>	

CHECK LIST  
ENGINEERING DATA  
DESIGN, CONSTRUCTION, OPERATION

ITEM	REMARKS
DAM - PLAN	Not Available
SECTIONS	
SPILLWAY - PLAN	Not Available
SECTIONS	
DETAILS	
OPERATING EQUIPMENT PLANS & DETAILS	Not Available
OUTLETS - PLAN	Reportedly, no outlet
DETAILS	
CONSTRAINTS	
DISCHARGE RATINGS	
HYDRAULIC/HYDROLOGIC DATA	Not Available
RAINFALL/RESERVOIR RECORDS	Lake level gaging records available - City of Orange, Engineer's Office
CONSTRUCTION HISTORY	Not Available
LOCATION MAP	Available - City of Orange, Engineers Office

**ITEM** **REMARKS**

**DESIGN REPORTS** Not Available

**GEOLOGY REPORTS** Not Available

**DESIGN COMPUTATIONS** Not Available  
**HYDROLOGY & HYDRAULICS**  
**DAM STABILITY**  
**SEEPAGE STUDIES**

**MATERIALS INVESTIGATIONS** Not Available  
**BORING RECORDS**  
**LABORATORY**  
**FIELD**

**POST-CONSTRUCTION SURVEYS OF DAM** Not Available

**BORROW SOURCES** Not Available

ITEM	REMARKS
MONITORING SYSTEMS	Lake level gaging records on file at Orange City Engineers Office.
MODIFICATIONS	Not Available
HIGH POOL RECORDS	Lake level gaging records available. - City of Orange, Engineer's Office
POST CONSTRUCTION ENGINEERING STUDIES AND REPORTS	Inspection reports available in NJDEP file.
PRIOR ACCIDENTS OR FAILURE OF DAM DESCRIPTION REPORTS	None
MAINTENANCE OPERATION RECORDS	None

APPENDIX 2

Photographs






PHOTO 1  
MASONRY SPILLWAY AND BRIDGE




PHOTO 2  
TOP OF DAM - BRIDGE OVER SPILLWAY

CAMPBELLS POND DAM  
15 NOVEMBER 1979



**PHOTO 3**  
**UPSTREAM FACE OF SPILLWAY**



**PHOTO 4**  
**DOWNSTREAM FACE OF SPILLWAY**

**CAMPBELLS POND DAM**  
**23 NOVEMBER 1979**



PHOTO 5      15 NOVEMBER 1979  
LEAKS IN DOWNSTREAM FACE OF SPILLWAY



PHOTO 6      23 NOVEMBER 1979  
DETERIORATION AT TOE OF DAM - STONES DISLODGED

CAMPBELLS POND DAM



PHOTO 7      15 NOVEMBER 1979  
WATER TRANSMISSION PIPES PENETRATING TOE OF DAM



PHOTO 8      23 NOVEMBER 1979  
MANHOLE UPSTREAM FROM DAM REPORTEDLY HOUSING WATER MAIN VALVE

CAMPBELLS POND DAM




PHOTO 9

23 NOVEMBER 1979

ORANGE DEPOSITS IN SUSPECTED SEEPAGE



PHOTO 10

15 NOVEMBER 1979

DOWNSTREAM CHANNEL

CAMPBELLS POND DAM

APPENDIX 3

Engineering Data

CHECK LIST  
HYDROLOGIC AND HYDRAULIC DATA  
ENGINEERING DATA

DRAINAGE AREA CHARACTERISTICS: Urban and Wooded

ELEVATION TOP NORMAL POOL (STORAGE CAPACITY): 214.0 (21 acre-feet)

ELEVATION TOP FLOOD CONTROL POOL (STORAGE CAPACITY): N.A.

ELEVATION MAXIMUM DESIGN POOL: 219.1

ELEVATION TOP DAM: Varies: 218.5 to 222.0

SPILLWAY CREST: Straight Masonry Weir with Piers

- a. Elevation 214.0
- b. Type Irregular Section
- c. Width 4 feet
- d. Length 124 feet
- e. Location Spillover Center of dam
- f. Number and Type of Gates None

OUTLET WORKS: None

- a. Type N.A.
- b. Location N.A.
- c. Entrance inverts N.A.
- d. Exit inverts N.A.
- e. Emergency draindown facilities: N.A.

HYDROMETEOROLOGICAL GAGES: Lake Water Level Gage

- a. Type Recording
- b. Location Abandoned Pump House
- c. Records Orange City Engineer's File

MAXIMUM NON-DAMAGING DISCHARGE:


(Lake stage equal to top of dam) 3748 c.f.s.  
(Elev. 218.5)

APPENDIX 4

Hydraulic/Hydrologic Computations



Stage Discharge Calculation



Spillway Section

Discharge over weir will be calculated by

The formula :  $Q = CLh^{3/2}$

Total length of spillway 124 feet

Effective length of spillway 119 feet

Correction for piers 5 feet

C use 3.3 Ref. "Handbook of Hydraulics" by Brater and King 5-44

As water level rise above the bridge, discharge will be calculated as on orifice :

$$Q = 0.576 A \sqrt{2gh}$$

$$A = 119 \times 5.2 = 618.8 \text{ sq ft.}$$



STORCH ENGINEERS

Sheet 2 of 8

Project Campbell Pond Dam

Made By FL Date 11-29-79

Chkd By JG Date 12/19/79



Flow over low point will be calculated by broad crested weir formula :

$$Q = CLh^{3/2}$$

Where  $C = 2.63$   
 $L = 55$  feet

Flow over full length of dam crest will be calculated by HEC-1-DB program

STORCH ENGINEERS

Sheet 3 of 8

Project Campbells Pond Dam

Made By RL Date 3-5-80

Chkd By JG Date 3-5-80

Stage Discharge Tabulation

Water level (ft)	Q (cfs) Spillway	Q (cfs) Low Point	Q (cfs) Total
214	0	0	0
215	393	0	393
216	1111	0	1111
217	2041	0	2041
218	3142	0	3142
218.5	3748	0	3748
219	4391	45	4436
220	5725	255	5980
221	6513	558	7071
222	7215	931	8146

Top of dam elevation varies from 218.5 to 222.0

STORCH ENGINEERS


Sheet 4 of 8

Project Campbell Pond Dam

Made By RL Date 11-27-79

Chkd By JG Date 12/14/79

Stage Discharge Curve



STORCH ENGINEERS

Sheet 5 of 8

Project CAMDBELLS POND DAM

Made By STO Date 12/10/79

Chkd By JG Date 12/14/79

## HYDROLOGY

PRECIPITATION (Re. "DESIGN OF SMALL DAMS", USDI, 1977)

FROM FIGURE 15, ZONE 6

PROBABLE MAXIMUM PRECIPITATION = 25.7 INCHES  
FOR 6 HOUR DURATION & 10 SQ. MILE AREA

<u>DURATION (HOURS)</u>	<u>% PMP</u>
6	100
12	109
24	117

### INFILTRATION DATA

INITIAL INFILTRATION = 1.0 INCHES

CONSTANT INFILTRATION = 0.10 INCHES / HOUR

### DRAINAGE AREA, D.A.

FROM USGS QUADRANGLES, ROSELLE, ORANGE, CALDWELL

DRAINAGE AREA = 6.4 SQUARE MILES

MAIN CHANNEL SLOPE, S FROM USGS QUADRANGLE

TOTAL CHANNEL LENGTH = 6.1 MILES

10% LENGTH = .61 MILES ; ELEVATION = 270

85% LENGTH = 5.2 MILES ; ELEVATION = 380

$$S = \frac{380 - 270}{5.2 - 0.61}$$

$$S = 24 \text{ FEET / MILE}$$

STORCH ENGINEERS

Sheet 6 of 8

Project CAMPBELL POND DAM

Made By STD Date 12/10/79

Chkd By JG Date 12/14/79

IMPERVIOUS COVER INDEX, I

(POPULATION TAKEN FROM CITY OF WEST ORANGE  
AND USGS QUADRANGLE)

$$\text{POPULATION} = 16,050$$

$$\text{POPULATION DENSITY (D)} = \frac{16,050}{6.4} \approx 2500 \frac{\text{PERSONS}}{\text{SQ. MILE}}$$

$$I = 0.117 D^{(0.792 - 0.039 \log D)} \quad (\text{FROM SPECIAL REPORT 38})$$

$$I = 20.37\%$$

TIME OF CONCENTRATION, T<sub>c</sub>

USING CLARK'S PARAMETERS SUPPLIED  
BY THE CORPS OF ENGINEERS

$$T_c = 8.29 (1.0 + 0.03 I)^{-1.28} (DA/S)^{0.28}$$

$$\frac{R}{T_c + R} = 0.65$$

$$I = 20.37\%$$

$$DA = 6.4 \text{ SM}$$

$$S = 24 \text{ FT/MILE}$$

$$T_c = 8.29 [1.0 + 0.03 (20.37)]^{-1.28} (6.4/24)^{0.28}$$

$$T_c = 3.11 \text{ HOURS}$$

$$\frac{R}{3.11 + R} = 0.65$$

$$R = 5.78 \text{ HOURS}$$

STORCH ENGINEERS

Sheet 7 of 8

Project CAMPBELL POND DAM

Made By STO Date 12/12/79

Chkd By JG Date 12/14/79

LAKE STORAGE VOLUME (FROM USGS QUADRANGLE)

STAGE (FT)

SURFACE AREA (AC.)

200

0

214

4.59

220

18.36

240

35.81

260

62.44

HEC-1-DB PROGRAM WILL DEVELOP

STORAGE CAPACITY FROM SURFACE

AREA & ELEVATION.

STORCH ENGINEERS


Sheet 8 of 8

Project Campbells Pond Dam

Made By JG Date 12/17/79

Chkd By \_\_\_\_\_ Date \_\_\_\_\_

Overtopping Potential



Overtopping occurs at elev. 218.5  
with  $Q = 3748$  c.f.s.

$\therefore$  Dam can pass approx 42% PMF



HEC-1-DB COMPUTATIONS

NATIONAL DAM SAFETY PROGRAM  
 CAMPBELL POND DAM, MILLBURN, NEW JERSEY

Code	PMF Multiplier	Ratio	Routing	0	0	0	3
A1	300	0					
A2	1	5					
A3	0.5	0.4					
B1	1	0.3					
J1	0.5	0.2					
K1	1	0.1					
V1	1	0					
T	3.11	5.78					
V	-1.0	-3.05					
X	1	2.0					
K1	1	0					
Y1	1	0					
Y4	214	216					
Y5	200	1110.7					
SA	214	118.36					
SE	222	18.220					
SS		214					
SD		2.63					
K		1.5					
A		245					
A		217					
A		2940.5					
A		35.81					
A		35.241					
A		218					
A		3141.6					
A		62.44					
A		62.260					
A		219					
A		4435.6					
A		5980.0					
A		220					
A		221					
A		7070.6					
A		-1					
A		222					
A		8145.7					

LAKE INFLOW HYDROGRAPH TO CAMPBELL DAM 0  
 6.4  
 117

ROUTED DISCHARGE THROUGH CAMPBELL DAM 0  
 1

.....  
 FLOOD HYDROGRAPH PACKAGE (MFC-1)  
 DAM SAFETY VERSION JULY 1978  
 LAST MODIFICATION 26 FEB 79  
 .....

RUN DATE# 79/12/13  
 TIME# 08.37.57

NATIONAL DAM SAFETY PROGRAM  
 CAMPBELL POND DAM, MILLBURN, NEW JERSEY  
 PMF MULTI RATIO ROUTING

NO	NMR	NMIN	IDAY	JOPER	NWJ	LROPT	METRC	IPLI	IPRI	NSTAN
300	0	10	0	5	0	0	0	0	0	0

RTIO# = .50 .40 .30 .20 .10  
 MULTI-PLAN ANALYSIS TO BE PERFORMED  
 NPLAN= 1 NRTIO= 5 LRTIO= 1

..... SUB-AREA RUNOFF COMPUTATION .....

INFLOW HYDROGRAPH TO CAMPBELL DAM

ISTAQ	ICOMP	IECON	ITAPE	JPLI	JPRI	INAME	ISTAGE	IAUTO
0	0	0	0	0	0	I	0	0

IHYDS	IUMG	TAREA	SNAP	TRSDA	TRSPC	RATIO	ISNOV	ISAME	LOCAL
1	0	6.40	0.00	6.40	0.00	0.000	0	I	0

TRSPC COMPUTED BY THE PROGRAM IS .860  
 SPEE PMS R6 R12 R48 R72 R96  
 0.00 25.70 100.00 109.00 117.00 0.00 0.00 0.00 0.00

LOSS DATA  
 ERAIN STKRS RTIOK SRTIL CNSTL ALSMX RTIMP  
 0.00 0.00 0.00 1.00 1.00 .10 0.00 0.00

UNIT HYDROGRAPH DATA NTA= 0  
 TC= 3.11 RE= 5.78  
 RECESSION DATA  
 STAR# = -1.00 GRCS# = -.05 RTIOR = 2.00  
 UNIT HYDROGRAPH 100 END-OF-PERIOD ORDINATES, LAGE 3.07 HOURS, CP= .40 VOLZ .93  

6	374	49	114	152	193	237	282	327	371	414	452	493	535	579	624	669	713	755
7	322	451	508	565	622	679	736	793	850	907	964	1021	1078	1135	1192	1249	1306	1363
8	291	369	426	483	540	597	654	711	768	825	882	939	996	1053	1110	1167	1224	1281
9	220	285	350	415	480	545	610	675	740	805	870	935	1000	1065	1130	1195	1260	1325
10	165	213	261	309	357	405	453	501	549	597	645	693	741	789	837	885	933	981
11	123	160	207	254	301	348	395	442	489	536	583	630	677	724	771	818	865	912
12	90	117	144	171	198	225	252	279	306	333	360	387	414	441	468	495	522	549
13	69	87	105	123	141	159	177	195	213	231	249	267	285	303	321	339	357	375









HYDROGRAPH AT STA LAKE FOR PLAN 1, RTIO 1

CFS	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CMS	4529.	3798.	1698.	822.	246674.
INCHES	128.	108.	48.	23.	6385.
MM		5.53	1.97	0.96	
AC-FT		140.23	250.77	232.97	252.97
THOUS CU M		1893.	3368.	3398.	4191.
		2323.	4155.	4191.	

.....

HYDROGRAPH ROUTING

ROUTED DISCHARGE THROUGH CAMPBELL DAM

STAGE	214.00	215.00	216.00	217.00	218.00	219.00	220.00	221.00	222.00
FLOW	0.00	392.70	1110.70	2040.50	3141.60	4435.60	5980.00	7070.60	8145.70
SURFACE AREA	0.	5.	18.	36.	62.				
CAPACITY	0.	21.	86.	618.	1588.				
ELEVATION	200.	214.	220.	240.	260.				

ISTAG	ICOMP	IECON	ITAPE	JPLY	JPRY	INAME	ISTAGE	IAUTO
DAM	1	0	0	0	0			
CLOSS	AVG	IRRES	ROUTING DATA	IOPT	IPMP		LSTR	
0.00	0.00	1	1	0	0		0	
MSTPS	MSTDOL	LAG	AMSK	X	ISK	STORA	ISPRAY	
1	0	0	0.000	0.000	0.000	-214.	-1	
COOL	COOH	EXPJ	ELEVJ	COOL	CAREA	EXPL		
214.00	0.00	0.00	0.00	0.00	0.00	0.00		

TOPFL	DAM DATA
222.00	EXPJ
	2.6
	DAMVID
	1.5
	245.



STATION DAM, PLAN 1, RATIO 1  
END-OF-PERIOD HYDROGRAPH ORDINATES

STAGE	OUTFLOW
0.00	0.00
0.10	1.00
0.20	1.00
0.30	1.00
0.40	1.00
0.50	1.00
0.60	1.00
0.70	1.00
0.80	1.00
0.90	1.00
1.00	1.00
1.10	1.00
1.20	1.00
1.30	1.00
1.40	1.00
1.50	1.00
1.60	1.00
1.70	1.00
1.80	1.00
1.90	1.00
2.00	1.00
2.10	1.00
2.20	1.00
2.30	1.00
2.40	1.00
2.50	1.00
2.60	1.00
2.70	1.00
2.80	1.00
2.90	1.00
3.00	1.00
3.10	1.00
3.20	1.00
3.30	1.00
3.40	1.00
3.50	1.00
3.60	1.00
3.70	1.00
3.80	1.00
3.90	1.00
4.00	1.00
4.10	1.00
4.20	1.00
4.30	1.00
4.40	1.00
4.50	1.00
4.60	1.00
4.70	1.00
4.80	1.00
4.90	1.00
5.00	1.00
5.10	1.00
5.20	1.00
5.30	1.00
5.40	1.00
5.50	1.00
5.60	1.00
5.70	1.00
5.80	1.00
5.90	1.00
6.00	1.00
6.10	1.00
6.20	1.00
6.30	1.00
6.40	1.00
6.50	1.00
6.60	1.00
6.70	1.00
6.80	1.00
6.90	1.00
7.00	1.00
7.10	1.00
7.20	1.00
7.30	1.00
7.40	1.00
7.50	1.00
7.60	1.00
7.70	1.00
7.80	1.00
7.90	1.00
8.00	1.00
8.10	1.00
8.20	1.00
8.30	1.00
8.40	1.00
8.50	1.00
8.60	1.00
8.70	1.00
8.80	1.00
8.90	1.00
9.00	1.00
9.10	1.00
9.20	1.00
9.30	1.00
9.40	1.00
9.50	1.00
9.60	1.00
9.70	1.00
9.80	1.00
9.90	1.00
10.00	1.00
10.10	1.00
10.20	1.00
10.30	1.00
10.40	1.00
10.50	1.00
10.60	1.00
10.70	1.00
10.80	1.00
10.90	1.00
11.00	1.00
11.10	1.00
11.20	1.00
11.30	1.00
11.40	1.00
11.50	1.00
11.60	1.00
11.70	1.00
11.80	1.00
11.90	1.00
12.00	1.00
12.10	1.00
12.20	1.00
12.30	1.00
12.40	1.00
12.50	1.00
12.60	1.00
12.70	1.00
12.80	1.00
12.90	1.00
13.00	1.00
13.10	1.00
13.20	1.00
13.30	1.00
13.40	1.00
13.50	1.00
13.60	1.00
13.70	1.00
13.80	1.00
13.90	1.00
14.00	1.00
14.10	1.00
14.20	1.00
14.30	1.00
14.40	1.00
14.50	1.00
14.60	1.00
14.70	1.00
14.80	1.00
14.90	1.00
15.00	1.00
15.10	1.00
15.20	1.00
15.30	1.00
15.40	1.00
15.50	1.00
15.60	1.00
15.70	1.00
15.80	1.00
15.90	1.00
16.00	1.00
16.10	1.00
16.20	1.00
16.30	1.00
16.40	1.00
16.50	1.00
16.60	1.00
16.70	1.00
16.80	1.00
16.90	1.00
17.00	1.00
17.10	1.00
17.20	1.00
17.30	1.00
17.40	1.00
17.50	1.00
17.60	1.00
17.70	1.00
17.80	1.00
17.90	1.00
18.00	1.00
18.10	1.00
18.20	1.00
18.30	1.00
18.40	1.00
18.50	1.00
18.60	1.00
18.70	1.00
18.80	1.00
18.90	1.00
19.00	1.00
19.10	1.00
19.20	1.00
19.30	1.00
19.40	1.00
19.50	1.00
19.60	1.00
19.70	1.00
19.80	1.00
19.90	1.00
20.00	1.00

10.5  
10.4

SUMMARY OF DAM SAFETY ANALYSIS

1 .....	FLEWATION STORAGE OUTFLOW	INITIAL VALUE 214.00 21.00	SPIILLWAY CREST 214.00 21.00	TOP OF DAM 222.00 124.00 8146.00	DURATION OVER TOP HOURS	MAXIMUM OUTFLOW CFS	MAXIMUM STORAGE AC-FT	MAXIMUM DEPTH OVER DAM	MAXIMUM RESERVOIR W.S. ELEV	PATIO OF PMF	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
						4522.00	70.00	0.00	219.06	.50	18.83	0.00
						3617.00	60.00	0.00	218.37	.40	19.00	0.00
						2713.00	50.00	0.00	217.91	.30	19.00	0.00
						1808.00	41.00	0.00	215.75	.20	19.00	0.00
						904.00	32.00	0.00	215.71	.10	19.00	0.00

**APPENDIX 5**

**Bibliography**

1. "Recommended Guidelines for Safety Inspection of Dams," Department of the Army, Office of the Chief of Engineers, Washington, D.C. 20314.
2. Design of Small Dams, Second Edition, United States Department of the Interior, Bureau of Reclamation, United States Government Printing Office, Washington, D.C., 1973.
3. Holman, William W. and Jumikis, Alfreds R., Engineering Soil Survey of New Jersey, Report No. 2, Essex County, Rutgers University, New Brunswick, N.J., 1953.
4. "Geologic Map of New Jersey," prepared by J. Volney Lewis and Henry B. Kummel, dated 1910 - 1912.
5. Safety of Small Dams, Proceedings of the Engineering Foundation Conference, American Society of Civil Engineers, 1974.
6. King, Horace Williams and Brater, Ernest F., Handbook of Hydraulics, Fifth Edition, McGraw-Hill Book Company, 1963.

END

DATE  
FILMED

9-80

DTIC