


AD-A091 076

NEW YORK STATE DEPT OF ENVIRONMENTAL CONSERVATION ALBANY F/6 13/13  
NATIONAL DAM SAFETY PROGRAM. OGDENSBURG WATER POWER COMPANY DAM--ETC(U)  
SEP 80 J B STETSON DACW51-79-C-0001


UNCLASSIFIED

2

ALBANY



0910



MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A

DDC FILE COPY ADA 091076

OSWEGATCHIE RIVER BASIN


OGDENSBURG WATER POWER CO. DAM

ST. LAWRENCE COUNTY  
NEW YORK

INVENTORY NO NY 400

PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM

APPROVED FOR PUBLIC RELEASE;  
DISTRIBUTION UNLIMITED  
CONTRACT NO. DACW-51-79-C0001



"Original contains color  
plates: All DTIC reproduct-  
ions will be in black and  
white"

NEW YORK DISTRICT CORPS OF ENGINEERS  
AUGUST 1980

80 10 31 047

## **DISCLAIMER NOTICE**

**THIS DOCUMENT IS BEST QUALITY  
PRACTICABLE. THE COPY FURNISHED  
TO DTIC CONTAINED A SIGNIFICANT  
NUMBER OF PAGES WHICH DO NOT  
REPRODUCE LEGIBLY.**

## REPORT DOCUMENTATION PAGE

READ INSTRUCTIONS  
BEFORE COMPLETING FORM

1. REPORT NUMBER	2. GOVT ACCESSION NO. AD-A091076	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Inspection Report Ogdensburg Water Power Company Dam Oswegatchie River Basin, St. Lawrence County, NY Inventory No. 400		5. TYPE OF REPORT & PERIOD COVERED Phase I Inspection Report National Dam Safety Program
7. AUTHOR(s)  John B. Stetson		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS Stetson-Dale Engineering Company Bankers Trust Building Utica, NY 13073		8. CONTRACT OR GRANT NUMBER(s)  DACW-51-79-C-0001
11. CONTROLLING OFFICE NAME AND ADDRESS New York State Department of Environmental Conservation 50 Wolf Road Albany, NY 12233		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) Department of the Army 26 Federal Plaza New York District, CofE New York, NY 10287		12. REPORT DATE 26 September 1980
		13. NUMBER OF PAGES
		15. SECURITY CLASS. (of this report)  UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE

## 16. DISTRIBUTION STATEMENT (of this Report)

Approved for public release; Distribution unlimited.

## 17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)

## 18. SUPPLEMENTARY NOTES

THIS DOCUMENT IS BEST QUALITY PRACTICABLE.  
THE COPY FURNISHED TO DTIC CONTAINED A  
SIGNIFICANT NUMBER OF PAGES WHICH DO NOT

## 19. KEY WORDS (Continue on reverse side if necessary and identify by block number)

Dam Safety  
National Dam Safety Program  
Visual Inspection  
Hydrology, Structural Stability

St. Lawrence County  
Oswegatchie River  
Ogdensburg Water Power Company Dam

## 20. ABSTRACT (Continue on reverse side if necessary and identify by block number)

This report provides information and analysis on the physical condition of the dam as of the report date. Information and analysis are based on visual inspection of the dam by the performing organization.

The examination of documents and visual inspection of the dam and appurtenant structures did not reveal conditions which constitute an immediate hazard to human life or property. The dam, however, has a number of problem areas which require further surveillance and remedial work.

DD FORM 1473 EDITION OF 1 NOV 65 IS OBSOLETE

\*Original contains color  
plates: All DTIC reproductions  
will be in black and  
white\*

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

393110

AD A091076

DDC FILE COPY

The structural stability analysis of the spillway section indicates unsatisfactory stability under loadings which could occur under normal winter operations. Marginal stability against overturning is indicated under loading which could occur during the Probable Maximum Flood (PMF) flow. A structural stability investigation should be commenced within six months to determine the characteristics of the uplift forces acting on the dam, the properties of the existing dam and the effect of these conditions on the stability of the dam. Remedial work should be undertaken depending on the results of this investigation.

The source of seepage near the right abutment should be investigated and immediate repair measures should be taken to eliminate this seepage.

The hydrologic/hydraulic analysis indicates that the spillway will pass only 20% of the Probable Maximum Flood (PMF). The dam will be overtopped by 11.8 feet and 5.0 feet by the PMF and 1/2 PMF respectively. The stability analysis indicates satisfactory stability under loadings which would occur during the 1/2 PMF. Therefore, the spillway is assessed as inadequate according to the Corps of Engineers Screening Criteria.

The following is a list of recommended measures to be undertaken to insure safety of the facility. These measures should be completed within two years.

1. The existing sluice gate structure has suffered structural damage so as to render the gates inoperable. Repairs should be undertaken to place the sluice gate structure in proper operating condition.
2. Repairs should be undertaken on the deteriorated concrete surfaces of the abutments and spillway.
3. A flood warning and emergency evacuation system should be implemented to alert the public in the event conditions occur which could result in failure of the dam.
4. A formalized inspection system should be initiated to develop data on conditions and maintenance operations at the facility.

## PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I Investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

Accession For	
RTIS G-21	<input checked="" type="checkbox"/>
DTIC T-3	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By	
Distribution/	
Availability Codes	
Avail and/or	
Special	
Dist	A 23

## TABLE OF CONTENTS

	<u>Page</u>
Preface	
Assessment of General Conditions	i-ii
Overall View of Dam	iii-v
Section 1 - Project Information	1-4
Section 2 - Engineering Data	5-6
Section 3 - Visual Inspection	7-8
Section 4 - Operational Procedures	9
Section 5 - Hydrologic/Hydraulic Computations	10-12
Section 6 - Structural Stability	13-16
Section 7 - Assessment/Remedial Measures	17-18

## FIGURES

- Figure 1 - Location Map  
Figure 2 - Typical Cross Section of Spillway

## APPENDIX

Field Inspection Report	A
Previous Inspection Report/Relevant Correspondence	B
Hydrologic and Hydraulic Computations	C
References	D



(15) DHCN51-79-C-0001

Inventory Number

PHASE I REPORT  
NATIONAL DAM SAFETY PROGRAM

Name of Dam Ogdensburg Water Power Company Dam (NY400) Oswegatchie River Basin  
State Located New York  
County Located St. Lawrence County, New York  
Stream Oswegatchie River  
Date of Inspection June 10, 1980 Phase I Inspection Report.

(10) B. Stetson

ASSESSMENT OF  
GENERAL CONDITIONS

(11) 26 Sep 80

(12) 255

The examination of documents and visual inspection of the dam and appurtenant structures did not reveal conditions which constitute an immediate hazard to human life or property. The dam, however, has a number of problem areas which require further surveillance and remedial work.

The structural stability analysis of the spillway section indicates unsatisfactory stability under loadings which could occur under normal winter operations. Marginal stability against overturning is indicated under loading which could occur during the Probable Maximum Flood (PMF) flow. A structural stability investigation should be commenced within six months to determine the characteristics of the uplift forces acting on the dam, the properties of the existing dam and the effect of these conditions on the stability of the dam. Remedial work should be undertaken depending on the results of this investigation.

The source of seepage near the right abutment should be investigated and immediate repair measures should be taken to eliminate this seepage.

The hydrologic/hydraulic analysis indicates that the spillway will pass only 20% of the Probable Maximum Flood (PMF). The dam will be overtopped by 11.8 feet and 5.0 feet by the PMF and 1/2 PMF respectively. The stability analysis indicates satisfactory stability under loadings which would occur during the 1/2 PMF. Therefore, the spillway is assessed as inadequate according to the Corps of Engineers Screening Criteria.

The following is a list of recommended measures to be undertaken to insure safety of the facility. These measures should be completed within two years.


1. The existing sluice gate structure has suffered structural damage so as to render the gates inoperable. Repairs should be undertaken to place the sluice gate structure in proper operating condition.

393977

*VR*

2. Repairs should be undertaken on the deteriorated concrete surfaces of the abutments and spillway.
3. A flood warning and emergency evacuation system should be implemented to alert the public in the event conditions occur which could result in failure of the dam.
4. A formalized inspection system should be initiated to develop data on conditions and maintenance operations at the facility.

Dale Engineering Company


  
John B. Stetson, President

26 SEP 1990


Approved By:  
Date:

Col. W. M. Smith, Jr.  
New York District Engineer





1. Overview of Ogdensburg Water Company Dam



2. Sluice gate structure on left abutment.  
Note severe spalling, exposed reinforcing  
and crack showing daylight under walkway.



3. Cracked walkway with rail lashed to operating mechanism at sluice gate structure.



4. Cracking and severe deterioration at spillway end of sluice gate structure.



5. Tailrace of water company pumping station. Wall in background is right abutment of spillway. Close-up in Photo #6 is at concrete section near center of abutment wall.



6. Area of substantial seepage at rear of right abutment.



7. View of spillway from left abutment. Seepage area in Photo #6 is located opposite red door in low roof section of Water Company pump station.



8. Commercial development and marina downstream of dam showing high hazard potential.



9. End of training wall downstream of left abutment.

PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM  
NAME OF DAM - OGDENSBURG WATER POWER COMPANY DAM ID# - NY 400

SECTION 1 - PROJECT INFORMATION

1.1 GENERAL

a. Authority

Authority for this report is provided by the National Dam Inspection Act, Public Law 92-367 of 1972. It has been prepared in accordance with a contract for professional services between Dale Engineering Company and The New York State Department of Environmental Conservation.

b. Purpose of Inspection

The purpose of this inspection is to evaluate the existing condition of the Ogdensburg Water Power Company Dam and appurtenant structures, owned jointly by the Niagara Mohawk Power Corporation (90% share) and the City of Ogdensburg (10% share), and to determine if the dam constitutes a hazard to human life or property and to transmit findings to the State of New York.

This Phase I inspection report does not relieve an Owner or Operator of a dam of the legal duties, obligations or liabilities associated with the ownership or operation of the dam. In addition, due to the limited scope of services for these Phase I investigations, the investigators had to rely upon the data furnished to them. Therefore, this investigation is limited to visual inspection, review of data prepared by others, and simplified hydrologic, hydraulic and structural stability evaluations where appropriate. The investigators do not assume responsibility for defects or deficiencies in the dam or in the data provided.

1.2 DESCRIPTION OF PROJECT

a. Description of Dam and Appurtenances

The Ogdensburg Water Power Company Dam is located in the City of Ogdensburg, approximately 800 feet downstream from the LaFayette Bridge. The dam is a run-of-river structure which formerly provided an impoundment for hydropower for the City of Ogdensburg Water Department as well as several industries formerly located on the left bank of the river. The dam is a 19 foot high concrete gravity structure with an ogee shaped spillway spanning approximately 350 feet across the Oswegatchie River. A sluice gate structure consisting of six wooden sluice gates, 6 feet wide and 8 feet high is situated on the left abutment. The pumping station of the Ogdensburg Water Company is located on the right abutment. This structure is not presently in use by the Water Department. The structure is situated on bedrock foundation.

b. Location

The Ogdensburg Water Power Company Dam is located in the City of Ogdensburg, St. Lawrence County, New York.

c. Size Classification

The maximum height of the dam is approximately 19 feet. The volume of the impoundment is approximately 1450 acre feet. Therefore, the dam is in the Intermediate Size Classification as defined by the Recommended Guidelines for Safety Inspection of Dams.

d. Hazard Classification

The Oswegatchie River, the receiving stream from the impoundment flows through the City of Ogdensburg. Several commercial establishments are located on the bank of the river downstream from the dam. A marina is also located a short distance downstream. Therefore, the dam is in the High Hazard Category as defined by The Recommended Guidelines for Safety Inspection of Dams.

e. Ownership

The dam is jointly owned by the Niagara Mohawk Power Corporation (90% share) and the City of Ogdensburg (10% share.)

Contact: Niagara Mohawk Power Corporation  
300 Erie Boulevard, West  
Syracuse, New York 13202  
Engineer - Robert J. Levett  
Telephone: 315-474-1511

Contact: City Engineer  
City of Ogdensburg  
330 Ford Street  
Ogdensburg, New York 13669  
Telephone: 315-393-7900

f. Purpose of the Dam

The dam is used to control the level of the impoundment for recreational purposes.

g. Design and Construction History

Dam Reports included in Appendix B indicate that a dam was originally constructed on the site in approximately 1825. The present dam was constructed in approximately 1910. The dam originally provided water for industrial power on both the left and right banks of the river. However, the use of this impoundment as a source of power has been abandoned. No data was available to determine the date of the abandonment of the power facilities. No data was available regarding the



design or the construction of the present dam and no plans of the dam were found.

h. Normal Operational Procedures

The facility is presently used to maintain the water level in the impoundment for recreational purposes. The sluice gates which control flow from the impoundment are in such poor condition as to be inoperative. No manipulation of these gates is presently made.

1.3 PERTINENT DATA

a. Drainage Area

The drainage area of Ogdensburg Water Power Company Dam is approximately 1,607 square miles.

b. Discharge at Dam Site

No discharge records are available for this site.

Computed Discharges:

Ungated Spillway, Top of Dam	26,600 cfs
Gated Drawdown, 6' x 8' gates	2,050 cfs*

c. Elevation (Feet Above MSL) - based on pool elevations shown on USGS Map

Top of Dam	265
Spillway Crest	258
Stream Bed at Centerline of Dam	246

d. Reservoir

Length of Normal Pool	21,000 FT
-----------------------	-----------

e. Storage

Top of Dam	4,175 Acre Feet
Normal Pool	1,450 Acre Feet

\* Assuming all gates fully open and reservoir elevation at spillway crest.

f. Reservoir Area

Top of Dam	490 Acres
Spillway Pool	290 Acres

g. Dam

Type - Concrete Gravity Dam.  
Length - 400 Feet.  
Height - 19 Feet.  
Freeboard Between Normal Reservoir and Top of Dam - 7 feet.

h. Spillway

Type - Concrete Ogee Shaped.  
Length - 350 Feet.  
Crest Elevation - 258 (Estimated from USGS Map)

i. Regulating Outlets

Six, 6 feet wide x 8 feet high wooden sluice gates.

## SECTION 2 - ENGINEERING DATA

### 2.1 GEOTECHNICAL DATA

#### a. Geology

Geologically, Ogdensburg is located in the St. Lawrence Valley Province.

According to early state reports (1913 through 1925, see Appendix B) the foundation bed of the dam and its right bank is bedrock; the left bank is "clay loam."

Bedrock at the dam site is Lower Ordovician Ogdensburg Dolostone of the Beekmantown Group. The dolostone is light to medium-gray, fine-to medium-grained crystalline rock with scattered medium-to coarse-grained quartz grains in places. The rock weathers to a tan to grayish-tan color. Bedding thickness varies from 4 to 12 inches in thickness. A few thin-bedded, medium-and coarse-grained, calcareous and dolomitic sandstones, weathering tan, are interlayered with the more predominant dolostone.

Dolostone, albiet a calcareous sedimentary rock, does not go into solution as readily as would a pure limestone; nevertheless, it does dissolve. Thus, in time, solution along joints and bedding planes could create conduits for water flow.

The left bank is in the Rhinebeck soils type which has formed from glacio-lacustrine deposits. These materials have a low to very low permeability and seepage generally presents no problem, particularly when the soils are compacted.

Rock bedding in the area is essentially horizontal. Three prominent joint sets are present and are as follows:

<u>Set</u>	<u>Orientation</u>	<u>Spacing</u>
1	Strike N80E-N-N85W	Dip 90° 8"-5' Av. 2-1/2'
2	N5-10E	90° 4'
3	N60W	90° 20'

The last joint set is parallel to the dam.

#### b. Subsurface Investigations

No records of subsurface investigations for this structure were available. The only information regarding the foundation materials are found in the Dam Reports included in Appendix B. A 1925 Report indicates that the foundation material for the dam is a limestone rock.

## 2.2 DESIGN RECORDS

No records were available from the original design of the dam.

## 2.3 CONSTRUCTION RECORDS

No information was available concerning either the original construction or the reconstruction of this dam.

## 2.4 OPERATIONAL RECORDS

There are no operational records available from this dam.

## 2.5 EVALUATION OF DATA

The data presented in this report was obtained from the Department of Environmental Conservation files. The information appears to be reliable and adequate for a Phase I inspection report.

## SECTION 3 - VISUAL INSPECTION

### 3.1 FINDINGS

#### a. General

The Ogdensburg Water Power Company Dam was inspected on June 10, 1980. The Dale Engineering Company Inspection Team was accompanied on the inspection by Brad Upson, City Engineer of the City of Ogdensburg and by Robert Levett of the Niagara Mohawk Power Corporation.

#### b. Dam

At the time of the inspection, the water level in the impoundment was approximately 8 inches above the spillway level. Flow over the spillway obscured view of the spillway surface. The irregular pattern of flow on the spillway surface indicates that some materials attrition has occurred. Deterioration at horizontal joints was evident through the flow. Visual observation did not disclose physical displacement of the alignment of the structure. Seepage was noted at the right abutment of the dam (see Photograph No. 6). The concrete in both abutments shows signs of significant deterioration.

#### c. Appurtenant Structures

The Ogdensburg Water Company pumping station is situated near the right abutment of the dam. The use of this facility has been abandoned and no inspection of the structure was made.

#### d. Control Outlet

Flow from the impoundment is controlled by a series of 6 sluice gates situated on the left abutment of the dam. The concrete in this structure shows significant deterioration with reinforcing exposed in many areas and with cracking of structural members evident in the abutments between the sluice gates (See Photographs). The walkway supporting the operating mechanism for the sluice gates is severely cracked and displacement of the structural elements of the walkway has occurred. No attempt was made to manipulate the gates at the time of the inspection. The displacement of the foundations of the operating mechanisms would indicate that attempts to operate the gates at this time could cause malfunction of the gate system. Although there was severe structural misalignment in the walkway of the sluice gate structure, there was no misalignment or displacement of the structural elements which form the seats for the sluice gates. The upstream face of the sluice gate structure shows no sign of misalignment below the level of the walkway.

e. Reservoir Area

The reservoir area extends approximately 4 miles to the south to another run-of-river dam on the Oswegatchie. There are no known areas of bank instability along this impoundment.

f. Downstream Channel

The downstream channel is formed in bedrock and extends approximately 1/2 mile to the mouth of the river at its confluence with the St. Lawrence River. There are no signs of recent erosion in the downstream channel.

3.2 EVALUATION

The visual inspection revealed a number of problem areas which require further investigation and remedial action. The seepage on the right abutment should be closely monitored and remedial action should be taken as soon as possible to eliminate this seepage. Repairs should be undertaken on the deteriorated surfaces of the abutments. The sluice gate structure should be repaired by replacing the walkway slab, re-aligning the operating mechanism and placing the sluice gates in operating condition. An investigation should be undertaken to determine the condition of the concrete in the spillway and the existence of any leakage which may occur through or under the spillway structure. Remedial action should then be taken depending on the results of this investigation.

## SECTION 4 - OPERATIONAL PROCEDURES

### 4.1 PROCEDURES

The normal operating procedure for this structure is to control the water level in the impoundment for recreational purposes. The deteriorated condition of the sluice gate structure prevents manipulation of the sluice gates so that the water level in the impoundment is controlled only by the volume of flow in the river.

### 4.2 MAINTENANCE OF THE DAM

Maintenance and operation of the dam is controlled jointly by Niagara Mohawk Power Corporation and the City of Ogdensburg. No formal reporting system is in effect at this site.

### 4.3 MAINTENANCE OF OPERATING FACILITIES

The sluice gates controlling flow from the impoundment are presently in poor condition as a result of severe structural damage to the foundations of the operating mechanisms for the gates. Operation of the gates is difficult if not impossible under the present conditions.

### 4.4 DESCRIPTION OF WARNING SYSTEM

No warning system is in effect at present.

### 4.5 EVALUATION

Conditions at the dam indicate that the facility has been poorly maintained in the past. A periodic inspection procedure should be instituted and a formal reporting system adopted to detect signs of further deterioration. This system should be continued after repairs are made at the facility. Special attention should be given to the surveillance of the seepage at the right abutment. Since the dam is in a High Hazard Classification, a warning system should be implemented to alert the public should conditions occur which could result in failure of the dam.

## SECTION 5 - HYDROLOGIC/HYDRAULIC

### 5.1 DRAINAGE AREA CHARACTERISTICS

The Ogdensburg Water Power Company Dam is located in the northern portion of St. Lawrence County. The dam spans the Oswegatchie River just upstream of the confluence of the Oswegatchie and St. Lawrence Rivers. The Oswegatchie has a drainage area of approximately 1607 square miles upstream of the dam, which is rather sparsely populated and wooded over most of its area. The Oswegatchie River Basin is a rather complex river network of many miles of rivers and streams. Numerous control structures span these rivers. The principal storage areas in the basin are provided by Cranberry Lake, Black Lake, and the numerous swamps and ponds. The impoundment created by the Ogdensburg dam backs up to the dam at Eel Weir creating a reservoir area of approximately 290 acres.

### 5.2 ANALYSIS CRITERIA

The purpose of this investigation is to evaluate the dam and spillway with respect to their flood control potential and adequacy. This has been assessed through the evaluation of the Probable Maximum Flood (PMF) for the watershed and the subsequent routing of the flood through the reservoir and the dam's spillway system. The PMF event is that hypothetical flow induced by the most critical combination of precipitation, minimum infiltration loss and concentration of run-off of a specific location that is considered reasonably possible for a particular drainage area.

The hydrologic analysis was performed using the unit hydrograph method to develop the flood hydrograph. Due to the limited scope of this Phase I investigation, certain assumptions, based on experience and existing data were used in this analysis and in the determination of the dam's spillway capacity to pass the PMF.

The U.S. Army Corps of Engineers' Hydrologic Engineering Center's Computer Program HEC-1 DB was used to evaluate the dam, spillway capacity, and downstream hazard. Unit hydrographs were defined by Snyder coefficients  $C_t$  and  $C_p$ . The drainage area was divided into sub-areas to model the variability in hydrologic characteristics within the drainage basin. The Muskingum routing method was used for river routing, whereas the Modified Puls method of flood routing was used for reservoir routing. In order to model the attenuation of the flood hydrographs due to the storage capacity of Cranberry Lake and Black Lake, the flood hydrographs were routed through these lakes. The data used for the outlet control structures of these lakes was obtained from the New York State Department of Environmental Conservation Dam Safety Section and Niagara Mohawk Power Corporation. Storage capacities for these lakes were estimated from U.S.G.S. mapping and previous reports.



Due to the size and complexity of the basin, Snyder's parameters, loss rate parameters and routing parameters were adjusted to attempt to calibrate the model to predicted discharges at some of the gages in the basin. These parameters were adjusted to obtain the peak discharges at the selected gages for the 100 year storm derived from the discharge-frequency curves obtained from the USGS data. Using a  $C_t$  of 3.0 and  $C_p$  of 0.55 and an SCS curve number of 69 essentially reproduced the 100 year peak discharge at Eel Weir (just upstream of the dam) and came within 3% of the corresponding discharges predicted at the gages at Heuvelton, Harrisville, and Oswegatchie. Running the model for a 500 year storm produced a peak discharge at Eel Weir that was 22% higher than predicted and 14% high at Heuvelton. The period of record spans over 58 years at Heuvelton and only 12 years at Eel Weir, therefore, the data for Heuvelton should be more reliable in predicting the discharge for a flood with such low probability of occurring as a 500 year storm. A refinement of this model might determine the various parameters based on the reconstitution of the hydrographs of a few major storms.

The developed computer model was then utilized to analyse the Probable Maximum Flood. The Probable Maximum Precipitation (PMP) was 18 inches according to Hydrometeorological Report (HMR #33) for a 24-hour duration storm, 200 square mile basin, while loss rates were set at 1.0 inches initial abstraction and 0.1 inches/hour continuous loss rate. The loss rate function yielded 73 percent run-off from the PMF. The peak for the PMF inflow hydrograph was 135,044 cfs and the 1/2 PMF inflow peak was 65,207 cfs. The storage capacity of the reservoir only reduced these peak flows to 134,957 cfs for the PMF and 65,167 cfs for the 1/2 PMF.

### 5.3 SPILLWAY CAPACITY

The spillway is an ogee-crested weir type structure 350 feet in length. Weir coefficients ranging from 3.14 to 4.15 over the heads encountered in routing the PMF were assigned for the spillway rating curve development. The discharge capacity of the spillway at the top of dam elevation is 26,640 cfs.

#### SPILLWAY CAPACITY

<u>Flood</u>	<u>Peak Discharge</u>	<u>Capacity as % of Flood Discharge</u>
PMF	134,957 cfs	20%
1/2 PMF	65,167 cfs	41%

### 5.4 RESERVOIR CAPACITY

The reservoir storage capacity was estimated from USGS mapping. The resulting estimates of the reservoir storage capacity are shown below:

Top of Dam	4175 Acre Feet
Spillway Crest	1450 Acre Feet

## 5.5 FLOODS OF RECORD

There are no accurate records of flood discharges at the site. A review of pertinent publications revealed the maximum discharges shown below for sites on the Oswegatchie River upstream of the dam site (Ref. 15).

<u>Gage Location</u>	<u>Drainage Area (Sq. Mi.)</u>	<u>Period of Record</u>	<u>Date</u>	<u>Maximum Discharge(cfs)</u>
Near Ogdensburg, New York	1580	1904-1916	3/31/05	15,800
Heuvelton, New York	973	1917-1975	4/06/60	19,600

These gage records are not truly representative of the flows experienced at the dam site due to the limited period of record at the gage near Ogdensburg and the substantially smaller drainage area for the Heuvelton gage (this gage is located upstream of the confluence with the Indian River drainage basin). However, these flood discharges do give an indication of the magnitude of previous flood flows for the river.

## 5.6 OVERTOPPING POTENTIAL

The HEC-1 DB analysis indicates that the dam will be overtopped as follows:

<u>Flood</u>	<u>Maximum Depth Over Dam</u>
PMF	11.8 Feet
1/2 PMF	5.0 Feet

## 5.7 EVALUATION

The hydrologic/hydraulic analysis establishes the spillway capacity as 20% of the Probable Maximum Flood (PMF). The dam will be overtopped by 11.8 and 5.0 feet by the PMF and 1/2 PMF respectively. However, results of the stability analysis indicate satisfactory stability under the 1/2 PMF. Therefore, the spillway is assessed as inadequate according to the Corps of Engineers screening criteria.

## SECTION 6 - STRUCTURAL STABILITY

### 6.1 EVALUATION OF STRUCTURAL STABILITY

#### a. Visual Observations

This concrete dam, extending across the width of the Oswagatchie River, currently functions as a spillway for nearly its full length. A three-bay gated outlet structure, 2 gates per bay, forms the dam's westerly (left) section. The dam's easterly (right) abutment consists of a concrete headwall on the river's eastern bank. A large pump house building situated adjacent to this abutment has its intake just upstream from the dam.

The dam was inspected under the condition where flow over the dam and through-the-gate spillway was occurring. The physical detail visible for evaluation was limited, particularly for the in-river section. Information relating to possible deterioration, erosion or seepage in the dam's toe region could not be obtained. The field observations indicate the main river section of the dam retains structural stability although some significant materials attrition of the surface, crack development and joint erosion has occurred throughout.

The gated spillway structure of the dam is generally in poor structural condition, with the upper section in particularly poor condition. The concrete walls dividing the spillway bays and the thick concrete abutment headwall joining the main dam to the spillway sections are spalled with some cracking. The horizontal slab walkway forming the top of the gated spillway (for workmen operating the spillway gates) is severely fractured, and generally has sections separated from the underlying supporting bay walls.

The dam's eastern concrete abutment wall is presently structurally stable but has experienced cracking and materials attrition, some severe. Leakage through the abutment section above the ground line is evident, with some underground leakage/seepage also possible.

A concrete retaining wall situated along the river's west bank extends downstream starting from the spillway. This wall has sections which are in poor structural condition. It appears that the primary function of this wall was to establish or protect land area on the river's west shore.

#### b. Seismic Stability

Although no known faults exist in the vicinity of the dam site, several earthquakes have been recorded in the immediate area. Speculation that the St. Lawrence River may follow a fault line in this portion of the river has been suggested by some authorities but evidence is lacking. The Seismic Probability map locates the dam

site at the border of a Zone 3 designation. Some of the earthquakes for the area are tabulated below:

<u>Date</u>	<u>Intensity Modified Mercalli</u>	<u>Location Relative to Dam</u>
1874	II	0 miles
1903	V	0 miles
1911	III	0 miles
1927	IV	8 miles SE
1938	IV-V	13 miles E-NE
1964	IV-V	10 miles E
1980	IV-V	11 miles NE

c. Stability Evaluation

No design drawings were available for review. Previous dam reports show plan alignment and the cross-section for the dam but do not include information on the properties of the dam and foundation materials, nor stability analysis. As part of the present study, stability evaluations have been performed for the dam's spillway section. Actual properties of the dam's construction materials and foundations were not determined as part of this study; where information on properties was necessary for computations but lacking, assumptions felt to be practical were made. The stability computations assumed a structural cross-section based on dimensions indicated in the previous dam reports included in this report. It should be considered that, in areas where deterioration has occurred, section dimensions would be less than indicated by the plans, with some adverse effect on the structural strength expected. The analysis also assumed the dam section to be monolithic, possessing necessary internal resistance to shear and bending occurring as a result of loading.

The results of the stability computations are summarized in the table following this page. The stability analyses are presented in Appendix D.

The engineering studies indicate satisfactory stability against overturning and sliding effects for the dam when subjected to forces possible during normal summer-type operation (no ice loading). Satisfactory stability is also indicated where seismic effects are imposed onto the normal summer operating condition. The analysis indicates unsatisfactory stability against overturning for the dam subject to forces including ice loading possible during winter operations, according to the Recommended Guidelines for Safety Inspection of Dams (i.e., factor of safety less than unity, and, where the resultant of forces acting on the dam is located outside the middle third of the base, tensile stresses would develop in the dam section, a condition which is structurally undesirable.)

The stability analysis indicates satisfactory stability against overturning and sliding for the dam under the 1/2 PMF loading condition.

# RESULTS OF STABILITY COMPUTATIONS

	<u>Loading Condition</u>	<u>Factor of Safety*</u>		<u>Location of Resultant Passing through Base***</u>
		<u>Overturning</u>	<u>Sliding**</u>	
(1)	Water level at spillway elevation, uplift on base (no ice).	2.13	50 <sub>+</sub>	0.51b
(2)	Water level at spillway elevation, uplift on base plus 7.5 kip per lineal foot ice load acting.	1.01	19 <sub>+</sub>	0.01b
(3)	Water elevations against upstream face and downstream face based on 1/2 PMF levels, uplift acting on base as computed for normal operating condition.	1.42	17 <sub>+</sub>	0.33b
(4)	Water elevations against upstream face and downstream face based on PMF levels, uplift acting on base as computed for normal operating condition.	1.3	12 <sub>+</sub>	0.30b
(5)	Water level at spillway elevation, uplift on base, seismic effect applicable to Zone 3.	1.73	34 <sub>+</sub>	0.44b

\* These factors of safety indicate the ratio of moments resisting overturning to those moments causing overturning, and the ratio of forces resisting sliding to those causing sliding.

\*\* As determined, applying the friction-shear method.

\*\*\* Indicated in terms of the dam's base dimension, b, measured from the toe of the dam.

For the PMF loading condition, the analysis indicates satisfactory stability against sliding but marginal stability against overturning. Lateral water pressures were calculated from the water surface elevations computed in the hydrologic/hydraulic analysis.

Critical to the analysis and resulting indication of stability are the items of uplift water pressure acting on the base of the dam and the relative permeability of the site's foundation rock. For the "normal operating conditions" case, the analysis uplift force was based on a full headwater hydrostatic pressure acting on the dam's upstream corner and a zero tailwater hydrostatic pressure acting on the dam's downstream corner. Uplift pressures were assumed to vary linearly between the dam's upstream and downstream corners, and to act upon 100 percent of the dam base. The resulting uplift force represents a condition that is significant to indications of instability.

Uplift as computed for the normal operating condition was also assigned to the flood conditions studied, assuming that uplift pressures would not increase significantly over a relatively short flood stage time period because of an expected low foundation rock permeability. With this assumption for uplift, the winter operating condition represents a loading combination more critical to dam stability than the 1/2 PMF and PMF flood conditions because of the significant effect of ice forces.

The discussed analysis applies to a dam in structurally good condition. The field observations indicate some materials attrition including cracking and surface deterioration, has occurred. Although this analysis indicates generally satisfactory stability under normal operating conditions, there is a lack of information regarding the condition of many of the structural elements of the facility and the uplift forces acting on the base. Therefore, further investigations are recommended. Evaluation of existing structural conditions should be based upon inspection of the dam and abutment structures with the reservoir drawn down. Because of the influence on the dam's stability under flood and winter operating conditions, means to evaluate the presence and magnitude of uplift acting on the base should be undertaken. This study should also investigate and evaluate the structural condition of the rock underlying the dam and immediately downstream for determining the resistance to displacement. Dam stability studies based on actual existing conditions should be performed and if necessary, recommendations to improve the stability should be developed. As a minimum, it should be anticipated that some structural repair to the surficial zones of the dam section will be required. Meanwhile, repair should be provided for the spillway to return it to a structurally sound and operationally proper condition. Similarly, means to correct the leakage/seepage occurring at the easterly abutment should be undertaken.

## SECTION 7 - ASSESSMENT/REMEDIAL MEASURES

### 7.1 DAM ASSESSMENT

#### a. Safety

The Phase I inspection of the Ogdensburg Water Power Company Dam did not indicate conditions which would constitute an immediate hazard to human life or property.

The hydrologic/hydraulic analysis indicates that the spillway will pass only 20% of the PMF. The dam will be overtopped by 11.8 feet and 5.0 feet by the PMF and the 1/2 PMF respectively. The stability analysis indicates satisfactory stability under loadings which could occur during the 1/2 PMF. Therefore, the spillway is assessed as inadequate according to the Corps of Engineers screening criteria.

The following specific safety assessments are based on the Phase I Visual Examination and Analysis of Hydrology and Hydraulics and Structural Stability:

1. The stability analysis of the spillway section indicates unsatisfactory stability under loadings which could occur during normal winter operations. Marginal stability against overturning is indicated under loadings which could occur during the PMF flow.
2. Seepage is occurring near the right abutment of the dam.
3. The sluice gate structure is in a deteriorated condition rendering the facility inoperable from a practical standpoint.
4. The surfaces of both the spillway and the abutments are severely deteriorated as evidenced by extensive surface spalling of concrete.
5. No formal inspection system is in effect at the facility.
6. No warning system is presently in effect to alert the public should conditions occur which could result in failure of the dam.

#### b. Adequacy of Information

The information available is adequate for this Phase I investigation.

#### c. Urgency

The items in the safety assessment should be addressed by the owner and appropriate repairs should be completed within two years. The recommended investigations should be started within six months.

d. Need for Additional Investigation


Further investigation relative to the stability of the spillway section should be performed to determine appropriate remedial measures. Further investigation should also be undertaken to determine the source of the seepage on the right abutment and the appropriate remedial measures necessary to eliminate the seepage.

7.2 RECOMMENDED MEASURES

The following is a list of recommended measures to be undertaken to insure safety of the facility:


1. A structural stability investigation of the spillway section should be performed to determine the characteristics of the uplift forces acting on the dam, the properties of the existing dam and the effect of these conditions on the stability of the dam. Remedial work should be undertaken depending on the results of this investigation.
2. The source of seepage near the right abutment should be investigated and immediate repair measures should be taken to eliminate this seepage.
3. Repairs should be undertaken to place the sluice gate structure in proper operating condition.
4. Structural repairs to the surficial zones of the spillway and abutments should be undertaken.
5. A flood warning and emergency evacuation system should be implemented to alert the public in the event conditions occur which could result in failure of the dam.
6. A formalized inspection system should be initiated to develop data on conditions and maintenance operations at the facility.





# LOCATION PLAN

FIGURE 1



SCALE: 1"=40'



STETSON • DALE

DATE

6-25-80

DRAWN

D.M.E.

NO.

2599

FIGURE 2

TYPICAL  
SECTION

APPENDIX A  
FIELD INSPECTION REPORT

CHECK LIST  
VISUAL INSPECTION

PHASE I

Name Dam Ogdensburg Water Power County St. Lawrence State N.Y. ID # NY 400  
Company Dam  
 Type of Dam Concrete Gravity Hazard Category High  
 Date(s) Inspection 6/10/80 Weather Partially cloudy Temperature 40-50°

Pool Elevation at Time of Inspection 258.7<sup>+</sup> M.S.L. Tailwater at Time of Inspection Not measured

Inspection Personnel:

<u>J. A. Gomez</u>	<u>Dale Engineering Company</u>
<u>F. W. Byszewski</u>	<u>Dale Engineering Company</u>
<u>D. F. McCarthy</u>	<u>Dale Engineering Company</u>
<u>H. Muskatt</u>	<u>Dale Engineering Company</u>
<u>R. Levett</u>	<u>Niagara Mohawk</u>
<u>B. Upsom</u>	<u>Ogdensburg City Engineer</u>
	<u>J. A. Gomez</u> Recorder

CONCRETE/MASONRY DAMS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
ANY NOTICEABLE SEEPAGE	Appears to be flow through cracks in concrete of east abutment wall of easterly gate and through east abutment wall. Quite noticeable leakage 3-5 gpm. East abutment wall also wet along 4' x 12' area. Seepage through foundation wall of pumping station.	
STRUCTURE TO ABUTMENT/EMBANKMENT JUNCTIONS	No problems observed.	
DRAINS	Flow out of drain on east abutment.	
WATER PASSAGES	None.	
FOUNDATION	Bedrock	

CONCRETE/MASONRY DAMS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS CONCRETE SURFACES	Numerous and very significant deterioration of gate structure/abutments	
STRUCTURAL CRACKING	Numerous and very significant structural cracks. Horizontal and vertical slab on gate structure.	
VERTICAL & HORIZONTAL ALIGNMENT	Middle of slab (over middle gate opening) displaced towards upstream 2 inches. (Tilted towards upstream)	
MONOLITH JOINTS	Some deterioration detected when viewed through the flow.	
CONSTRUCTION JOINTS	Separation of structural elements at construction joints for gate abutments/structure.	
STAFF GAGE OF RECORDER	None.	

EMBANKMENT

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS	Not applicable.	
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	Not applicable.	
SLOUGHING OR EROSION OF EMBANKMENT AND ABUTMENT SLOPES	Not applicable.	
VERTICAL AND HORIZONTAL ALIGNMENT OF THE CREST	Not applicable.	
RIPRAP FAILURES	Not applicable.	

EMBANKMENT

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM	Not applicable.	
ANY NOTICEABLE SEEPAGE	Not applicable.	
STAFF GAGE AND RECORDER	Not applicable.	
DRAINS	Not applicable.	



UNGATED SPILLWAY

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE WEIR	Flow pattern indicates some deterioration of surface. Horizontal joints evident through flow. Deterioration of 6" or so on east end of spillway.	
APPROACH CHANNEL	Oswegatchie River (natural)	
DISCHARGE CHANNEL	Oswegatchie. Concrete wall on west side for 150' downstream. Couple sections on end tipped over. Concrete and masonry wall on east. Stones misplaced in masonry section. Small section of masonry wall in ruins.	
BRIDGE AND PIERS	None.	

# GATED SPILLWAY

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE SILL	3 wooden sluice gate openings 2 gates each opening = 6 gates	
APPROACH CHANNEL	Oswegatchie River	
DISCHARGE CHANNEL	Receiving stream Training wall badly deteriorated	
BRIDGE AND PIERS	Significant structural cracks in piers, abutments and top slab, especially in two most easterly openings. Easterly pier allows water to leak through crack. Cracks vertical (3" wide) and horizontal 2". Severe deterioration of pier/abutment. Easterly abutment deteriorated 18" upstream.	
GATES AND OPERATION EQUIPMENT	6 gates, one wheel missing. Don't appear to have been operated recently.	

Upstream side of middle of slab raised 1" and moved upstream.  
Tilted towards upstream. Top of east of 2 piers popped off.  
Upstream east corner of slab up 5".

# OUTLET WORKS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	Old outlets to mills, etc. blocked off (west side).	
INTAKE STRUCTURE	Old intake shows deterioration. (fairly significant) (west side)	
OUTLET STRUCTURE	Some flow also was diverted through Water Power Co. Building on east side in past.	
OUTLET CHANNEL	Masonry walls (west side -tailrace) have some displacement of units miss- ing . Some pointing etc. - general lack of maintenance.	
EMERGENCY GATE	See gated spillway section.	

DOWNSTREAM CHANNEL

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONDITION (OBSTRUCTIONS, DEBRIS, ETC.)	Flows relative short distance to St. Lawrence.	
SLOPES	Fairly shallow	
APPROXIMATE NO. OF HOMES AND POPULATION	Marina and business buildings along bank just downstream. Significant recreational use of downstream river.	

INSTRUMENTATION

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
MONUMENTATION/SURVEYS	NOT APPLICABLE	
OBSERVATION WELLS	NOT APPLICABLE	
WEIRS	NOT APPLICABLE	
PIEZOMETERS	NOT APPLICABLE	
OTHER	NOT APPLICABLE	

RESERVOIR

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SLOPES	~15% east      ~3% west No known areas of instability.	
SEDIMENTATION	Signs of sedimentation of east side.	

Ogdensburg Water  
Power Company Dam

**CHECK LIST**  
**ENGINEERING DATA**  
**DESIGN, CONSTRUCTION, OPERATION**  
**PHASE 1**

NAME OF DAM

ID #

NY 400

ITEM	REMARKS
AS-BUILT DRAWINGS	None available.
REGIONAL VICINITY MAP	See report.
CONSTRUCTION HISTORY	No data, except from Dam Safety files.
TYPICAL SECTIONS OF DAM	From old dam reports
OUTLETS - PLAN - DETAILS - CONSTRAINTS - DISCHARGE RATINGS	No data
RAINFALL/RESERVOIR RECORDS	Not available.

ITEM	REMARKS
DESIGN REPORTS	Not available.
GEOLOGY REPORTS	Not available.
DESIGN COMPUTATIONS HYDROLOGY & HYDRAULICS DAM STABILITY SEEPAGE STUDIES	Not available.
MATERIALS INVESTIGATIONS BORING RECORDS LABORATORY FIELD	Not available.
POST-CONSTRUCTION SURVEYS OF DAM	Not available.
BORROW SOURCES	Not available.



ITEM	REMARKS
MONITORING SYSTEMS	Not available.
MODIFICATIONS	Not available.
HIGH POOL RECORDS	Not available.
POST CONSTRUCTION ENGINEERING STUDIES AND REPORTS	Not available.
PRIOR ACCIDENTS OR FAILURE OF DAM DESCRIPTION REPORTS	Not available.
MAINTENANCE OPERATION: RECORDS	Not available.

ITEM	REMARKS
SPILLWAY PLAN SECTIONS DETAILS	Not available.
OPERATING EQUIPMENT PLANS & DETAILS	Not available.

CHECK LIST  
HYDROLOGIC & HYDRAULIC  
ENGINEERING DATA

DRAINAGE AREA CHARACTERISTICS: 1607 square miles

ELEVATION TOP NORMAL POOL (STORAGE CAPACITY): 258

ELEVATION TOP FLOOD CONTROL POOL (STORAGE CAPACITY): 265

ELEVATION MAXIMUM DESIGN POOL: Unknown

ELEVATION TOP DAM: 265

CREST:

- a. Elevation 258 (based on USGS map pool elevation)
- b. Type Ogee crested
- c. Width Not applicable
- d. Length 350 feet
- e. Location Spillover Center of dam
- f. Number and Type of Gates None

OUTLET WORKS:

- a. Type 6 - 6 feet wide x 8 feet high wooden sluice gates
- b. Location Left abutment.
- c. Entrance Inverts Not available.
- d. Exit Inverts Not available.
- e. Emergency Draindown Facilities Same.

HYDROMETEOROLOGICAL GAGES:

- a. Type None.
- b. Location None.
- c. Records None.

MAXIMUM NON-DAMAGING DISCHARGE: No data.

APPENDIX B

PREVIOUS INSPECTION REPORTS/RELEVANT CORRESPONDENCE

ADDRESS ALL COMMUNICATIONS TO THE CONSERVATION COMMISSION

STATE OF NEW YORK



CONSERVATION COMMISSION

GEORGE E. VAN KENNEN  
CHAIRMAN

JAMES W. FLEMING  
JOHN D. MOORE  
COMMISSIONERS

ALBERT E. HOYT  
SECRETARY

JOHN J. FARRELL  
ASST. SECRETARY

DIVISION OF FISH AND GAME

JAMES W. FLEMING  
COMMISSIONER

THOMAS H. GUY  
DEPUTY COMMISSIONER

DR. TARTYTON H. BEAN  
FISH CULTURIST

LLEWELLYN LEGGE  
CHIEF GAME PROTECTOR

Dexter N. Y.

July 26th. 1912

Conservation Commission

Albany N. Y.

Gentlemen:-

On April 6th. 1912, the Fishway in the dam on the Oswesthie river, at Ogdensburg, went out, and I notice that the owners have not done anything toward replacing the same. I am reporting this as I understand it is one of my duties.

Respectfully Yours.

*F. C. Mullie*

Division Chief Protector.

*to Cooper*

July 29, 1912.

W. E. C. F. Allen,

Dexter, N. Y.

Dear Sir:-

Yours of July 26th concerning the fishway  
in the dam at Ogdensburg received, and we thank you  
exceedingly for the information.

Yours truly,

Conservation Commission,

By

McK/F

Inspector of Docks & Dams.

July 29, 1912.

*W. W. Keating*

Ogdensburg Water Company,

Ogdensburg, N. Y.

Gentlemen:-

The fishway for your dam at Ogdensburg having been carried out, we submit to you our pamphlet on fishways as a suggestion for a new one, plans of which should be sent for the approval of this Commission.

Kindly send us any prints of the dam which you may have for our files.

Yours very truly,

Conservation Commission,

By

McK/F

Inspector of Docks & Dams.

November 19, 1912.

Ogdensburg Water Company,

Ogdensburg, N. Y.

Gentlemen:-

I wrote you on July 29th concerning the replacement of the fishway for your dam, which was carried out, but have received no reply from you in regard to same.

Very truly yours,

Conservation Commission,

By

Inspector of Docks and Dams.

LCK/C.



WATER COMMISSIONERS  
JES. M. WELLS, CHAIRMAN  
WILLARD N. BELL  
GEORGE F. DARROW  
FRANK CHAPMAN

## OGDENSBURG CITY WATER WORKS

OGDENSBURG, NEW YORK

SUPERINTENDENT  
HARRY A. LORD

December 10, 1912.

Mr. Alexander McKim, Inspector,  
Docks and Dams,  
Conservation Commission,  
Albany, New York.


Dear Sir:-

I have received from the City Clerk's office your inquiry of November 19th, addressed to Ogdensburg Water Company, relative to the replacement of the fishway at the Ogdensburg dam.

While this matter is something we have nothing to do with and, no doubt your letter was intended for some other commission, I am able to state at this time that it would be impossible to do anything about replacing this fishway as the Oswegatchie has been extraordinarily high this Fall and at present is running at flood mark.

We note you have written a former letter regarding this matter but we have no recollection of having received the same.

Very respectfully yours,



Superintendent.

Dic. HAL/F.

January 3, 1913.

Mr. Harry A. Lord, Superintendent,  
Ogdensburg City Water Works,  
Ogdensburg, N. Y.

Dear Sir:-

Yours of December 10th received concerning dam  
No. 11 Oswegatchie watershed.

I understand from your letter that the City of  
Ogdensburg is the owner of said dam. I enclose a sketch  
as a suggestion for the replacement of the fishway which  
was washed out sometime ago, plans for which should be sent  
to this Commission for its approval. I also send a blank  
to be filled out with data concerning the dam.

Very truly yours,

Conservation Commission,

By

Inspector of Docks and Dams.

McK/C.

Encls.

WATER COMMISSIONERS  
JES. M. WELLS, CHAIRMAN  
J. WILLARD N. BELL  
GEORGE F. DARROW  
FRANK CHAPMAN

## OGDENSBURG CITY WATER WORKS

OGDENSBURG, NEW YORK

SUPERINTENDENT  
HARRY A. LORD

January 8, 1913.

*11 C. A. L.*

Mr. Alexander Rice McKim,  
Inspector Docks & Dams,  
Conservation Commission,  
Albany, New York.

Dear Sir:-

Yours of January 3rd relative to the dam  
in the Oswegatchie River at Ogdensburg is at hand  
together with the sketch as a suggestion for the  
replacement of the fishway and also a blank to fill  
out with data concerning the dam.

The Ogdensburg dam does not belong to the City  
of Ogdensburg nor is it in any way controlled by  
the City. The government of all water power matters  
is vested in a commission established by the courts  
of three members consisting at this time of Messrs.  
John Hannan, Frank Chapman and Chas. O. R. Bell with  
whom you should communicate in regard to water power  
matters in connection with this dam and canal.

Yours very truly,

*H. A. Lord*  
Superintendent.

Dic. HAL/P

January 9, 1913.

Messrs. John Hannan, Frank Chapman & Chas. O. E. Bell,  
Ogdensburg, N. Y.

Gentlemen:

Concerning dam No. 11 Oswegatchie Watershed at  
Ogdensburg which is under the jurisdiction of your Com-  
mission.

The fishway for this dam having been carried  
away, I enclose a sketch as a suggestion for a new fish-  
way, plans of which should be submitted to this Commis-  
sion for approval. I also enclose a blank for data  
concerning your dam, which I wish you would kindly fill  
out and return to this Commission.

Very truly yours,

Conservation Commission,

By

Inspector of Docks and Dams.

McK/C.

Encls.

February 24, 1914.

Ogdensburg Water Power Co.,

Ogdensburg, N. Y.

Gentlemen:-

Concerning your dam on the Oswegatchie River, kindly advise us whether anything has been done in the matter of a fishway in regard to which we wrote you the following on January 9, 1913:

"Concerning dam No. 6 Oswegatchie Watershed at Ogdensburg which is under the jurisdiction of your Commission.

"The fishway for this dam having been carried away, I enclose a sketch as a suggestion for a new fishway, plans of which should be submitted to this Commission for approval. I also enclose a blank for data concerning your dam, which I wish you would kindly fill out and return to this Commission."

Very truly yours,

Conservation Commission,

By

Commissioner.

JDM/C.

CAPITAL \$100,000.

SURPLUS \$250,000.

## OGDENSBURG BANK.

FRANK CHAPMAN, PRES.  
THOMAS SPRATT, VICE PRES.  
SAMUEL W. LEONARD, CASHIER.

*Ogdensburg, N.Y.* Feby '26'1914.

RECEIVED

FEB 27 1914

DIVISION OF LAND WATERS  
J. D. M.

Conservation Commission,  
Albany, N.Y.

Gentlemen:-

I have this day received, through the hands of the Ogdensburg City Water Works, your favor of the 24th., inst. addressed to the Ogdensburg Water Power Company, relative to Fishway at the Dam on the Oswegatchie River at Ogdensburg, N.Y., and asking more particularly if anything has been done in regard to the same, along the lines of your letter dated January 9th., 1913. I fail to find among my files any such letter.

Nothing has been done in the matter of a Fishway at this dam, for the following reasons. The Dam is a part of the Ogdensburg Water Power Property, so called and distinguished in a decree of the Supreme Court, dated April 2, 1872. The affairs of this property, so far as the use of the water for water power purposes, and certain specific duties relative to the maintenance of the dam etc., was placed in the hands of three referees appointed by the said Court, and in conformity therewith the old timber dam, built early in 1800, was replaced by a concrete dam, built in the year 1910. The referees did, either in that year, or in the year 1911, construct what was regarded as an extra strong, and well secured Fishway, in compliance with the request of your commission. This structure

**OGDENSBURG BANK.**

MAN. PREST.  
ATT. VICE PREST.  
CONARD. CASHIER

*Ogdensburg, N.Y.*

2.

dam, and swept away. We are satisfied from our past experience, that nothing in the form of a Fishway will stand, unless it be built of re-inforced concrete. Such a structure will cost a large sum of money, and the referees can find no authority given them to make any such expenditure. Such authority, I presume, would have to proceed from the Court having jurisdiction in this matter.

I submit this for your consideration, and for your further advice and suggestion,

Very truly yours,

Ogdensburg Water Power Property,

by *Frank C. Benson*  
Referee.

6 lbs. fish

February 28, 1914.

Frank Chapman, Esq., Referee,  
Ogdensburg Water Power Property,  
Ogdensburg, N. Y.

Dear Sir:-

Yours of February 26, 1914 received, having crossed  
our letter of February 24th containing a copy of our letter of  
January 9, 1913, which you requested in yours of February 26th.

We agree with you that it will be wise to replace  
the fishway by one of concrete and have same well anchored to  
the foundation ledge.

We enclose a pamphlet on fishways, which describes  
just such a fishway as we would recommend for your purpose.

Very truly yours,

Conservation Commission,

By

Commissioner.

YcK/C.

Encl.



GEORGE E. VAN KENNEN,  
CHAIRMAN

JAMES W. FLEMING,

JOHN D. MOORE,  
COMMISSIONERS

ALBERT E. HOYT,  
SECRETARY

JOHN J. FARRELL,  
ASST. SECRETARY

STATE OF NEW YORK



DIVISION OF FISH AND GAME

JAMES W. FLEMING,  
COMMISSIONER

THOMAS H. GUY,  
DEPUTY COMMISSIONER

DR. TARLETON H. BEAN,  
FISH CULTURIST

LLEWELLYN LEGGE,  
CHIEF GAME PROTECTOR

IN REPLYING PLEASE REFER  
TO FILE NUMBER

508

CONSERVATION COMMISSION

ALBANY

March 15, 1914.

DAVID

C. E. V'K.

Conservation Commission,

Hon. George E. Van Kernen, Chairman,

Albany, N.Y.

Gentlemen:-

On the subject of a fishway in the dam of the Ogdensburg Water Power Company, mentioned in a letter of Mr. Frank Chapman, Feb. 26, 1914, I am of the opinion that it is not necessary for any purpose of fish culture to construct a fishway in the dam.

I have examined a large portion of the Oswegatchie including the site of the dam in question, and have expressed to the Forest, Fish and Game Commission my belief that the Oswegatchie can be best treated fish culturally as a series of ponds. The river above the dam of the Ogdensburg Water Power Company is very well stocked with valuable food and game fish, and it has in Black Lake a reservoir in which good fish of various species abound. At one point on the stream there is a natural rock dam which, of itself, effectually prevents the passage of fish of all kinds, except eels, upstream at ordinary stages of flow.

For the reasons stated, that is, the presence of Black Lake, which is rich in fish, and the fact that nature has divided the stream so as to form what constitutes in reality a series of ponds, I suggest that the river be handled without a fishway in the dam at Ogdensburg and stocked in sections with species adapted to the region.

Very respectfully,

Tarleton H. Bean,  
Fish Culturist.

Address all communications to the Conservation Commission.

March 21, 1914.

Mr. Frank Chapman,  
Ogdensburg, N. Y.

Dear Mr. Chapman:

Your favor of February 26th, 1914 to this commission, with respect to fishway and dam on Oswegatchie river at Ogdensburg, N. Y., finally came to my attention a few days ago.

I immediately took the matter up with our fish culturist and asked for a report. After giving the matter full consideration he made a report to the commission in which he stated that he did not consider it essential that a fishway be constructed at the dam; that inasmuch as Black Lake was tributary to the section of the river immediately above the dam and that such lake was well stocked with all kinds of game fish, he did not feel that it was necessary at this time to require the construction of a fishway. In other words, he felt that the cost of constructing and maintaining a fishway at that point was disproportionate to the benefits to be derived therefrom under the conditions that exist at the present time.

Dr. Bean's report was considered by the commission and I was authorized to advise you that the commission

FC2

In re fishway in Oswegatchie

had determined that for the present, at least, a fishway  
would not be required .

With kind regards, I remain

Respectfully yours,

VK/B

Chairman

GEORGE D. PRATT  
COMMISSIONER  
ALEXANDER MACDONALD  
DEPUTY COMMISSIONER  
WARWICK S. CARPENTER  
SECRETARY  
MARSHALL MCLEAN  
SPECIAL DEPUTY ATTORNEY GENERAL

STATE OF NEW YORK



DIVISION OF FISH AND GAME  
LLEWELLYN LEGGE, CHIEF  
DIVISION OF LANDS AND FORESTS  
C. R. PETTIS, SUPERINTENDENT  
DIVISION OF WATERS  
A. H. PERKINS, DIVISION ENGINEER  
DIVISION OF SARATOGA SPRINGS  
J. S. JONES, SUPERINTENDENT  
SARATOGA SPRINGS, N. Y.

CONSERVATION COMMISSION

IN REPLYING PLEASE REFER  
TO FILE NUMBER

ALBANY

April 24, 1918.

Mr. A. H. Perkins,  
Division Engineer.

Dear Mr. Perkins:

Referring to the accompanying petition from the residents of Ogdensburg that this commission have a fishway erected in the dam on the Oswegatchie River in the city of Ogdensburg, I have to say that at the present time experts on fishways have not been able to plan an effective one. In other words, I know of no fishways in this part of the country which are on dams like that across the Oswegatchie which will induce the pikeperch to ascend them.

Undoubtedly the applicants desire to facilitate the ascent of the pikeperch which run the river at the city of Ogdensburg at this season of the year for the purpose of spawning.


You have doubtless seen the leaflet of the United States Bureau of Fisheries on this subject. The author of it is an engineer who has been identified with the United States Bureau of Fisheries for a great many years, and has planned quite a few fishways; he has also inspected fishways planned by others. His conclusions, as given on page 5 of the accompanying circular, in which he states, "The Bureau lacks information as to the efficient operation of any existing

A. H. Perkins, Division Engineer. . .April 24, 1918. . .Page 2

fishway in the United States at dams more than 20 feet in height," could probably be applied with equal force to many dams no higher than the one at Ogdensburg. However, I am not informed as to the height of the dam there.

I hesitate about recommending constructions which cause the dam owners large expense, unless the commission is prepared to demonstrate that the proposed constructions will facilitate the passage of valuable food fishes to the upper waters, and is also prepared to furnish plans for such proposed fishways.

Yours very truly,

  
Fish Culturist.

JWT  
CAP

Encl.

Ogdensburg City Engineer Dec. 1, 1913. Sales built by Commission of the Oswegatchie  
River Conserv. Comm. Trans C.O.R. Bell, Joseph Hall and John Dorsey, Commissioners

FORM 1W-1 6-16-12-2000 (16-1008)

(NOTICE: After filling out one of these forms as completely as possible for each dam in your district, return it at once to the Conservation Commission, Albany.)

STATE OF NEW YORK  
CONSERVATION COMMISSION  
ALBANY

DAM REPORT

February 19, 1913  
(Date)

6  
Ogdensburg  
line

CONSERVATION COMMISSION,

DIVISION OF INLAND WATERS.

GENTLEMEN:

I have the honor to make the following report in relation to the structure known as the Ogdensburg Water Power Co. Dam.

This dam is situated upon the Oswegatchie River  
(Give name of stream)  
in the Town of Oswegatchie, St. Lawrence County,  
about center from the Village or City of Ogdensburg  
(State distance)  
The distance down stream from the dam, to the St. Lawrence river  
(Up or down) (Give name of nearest important stream or of a bridge)  
is about 1/4 mile  
(State distance)


The dam is now owned by Ogdensburg Water Power Co.  
(Give name in full)  
and was built in or about the year 1910, and was extensively repaired or reconstructed during the year 1910.

As it now stands, the spillway portion of this dam is built of reinforced concrete  
(State whether of masonry, concrete or timber)  
and the other portions are built of reinforced concrete without rock fill  
(State whether of masonry, concrete, earth or timber with or without rock fill)


As nearly as I can learn, the character of the foundation bed under the spillway portion of the dam is Bedrock and under the remaining portions such foundation bed is Bedrock.

Frank Chapman  
John Hannan  
C.O.R. Bell  
refers

double steel I beams



(In the space below, make a third sketch showing the general plan of the dam, and its approximate position in relation to buildings or other conspicuous objects in the vicinity.



- 1 Sandersburg City Water works
- 2 " " " " tail race
- 3 Bulk head
- 4 Oswegatchie river & Oswegatchie R-
- 5 dam
- 6 Bulk head
- 7 split chest
- 8 Chestment
- 9 strip of land
- 10 "
- 11 "
- 12 canal
- 13 land
- 14 land
- 15 Canal bulk heads gates 10 in number  
each gate 7 x 4 ft 4 1/2 in
- 16 abutment
- 17 small building, used to put tools in.
- 18 High water
- 19 Proctor Mfg Co. Lumber

The total length of this dam is <sup>about</sup> 410 feet. The spillway or waste-weir portion, is about 36 feet long, and the crest of the spillway is about 12 feet below the top of the dam.

The number, size and location of discharge pipes, waste pipes or gates which may be used for drawing off the water from behind the dam, are as follows: 6

6 X 8 ft

West end of dam

State briefly, in the space below, whether, in your judgment, this dam is in good condition, or bad condition, describing particularly any leaks or cracks which you may have observed.)

The dam in my judgment is in good condition

The dam was built about 6 or 8 ft below the old timber dam which was left in place. It was earth filled as near as can be seen



Reported by John H. Mallette  
(Signature)

82 Mansion Ave.

(Address—Street and number, P. O. Box or R. F. D. route)

Ogdensburg, N.Y.

(Name of place)

(SEE OTHER SIDE)



INVESTIGATION REPORT

SEP 21 1914

(NOTICE: After filling out one of these forms as completely as possible for each dam in your district, return it at once to the Conservation Commission, Albany.)

STATE OF NEW YORK  
CONSERVATION COMMISSION  
ALBANY

## DAM REPORT

September 17, 1914  
(Date)

CONSERVATION COMMISSION,

DIVISION OF INLAND WATERS.

GENTLEMEN:

I have the honor to make the following report in relation to the structure known as the Ogdensburg Dam.

This dam is situated upon the Oswegatchie River  
(Give name of stream)  
in the Town of Oswegatchie, St. Lawrence County,  
~~in~~ in the ~~Village~~ City of Ogdensburg  
(State distance)

The distance down stream from the dam, to the Ogdensburg Bridge (Tower)  
(Up or down) (Give name of nearest important stream or of a bridge)  
is about 1/4 miles.  
(State distance)

The dam is now owned by Ogdensburg Water Power Owners, Ogd., N.Y.  
(Give name in full)  
and was built in or about the year 1911, and was extensively repaired or reconstructed during the year \_\_\_\_\_.

As it now stands, the spillway portion of this dam is built of concrete  
(State whether of masonry, concrete or timber)  
and the other portions are built of concrete  
(State whether of masonry, concrete, earth or timber with or without rock fill)

As nearly as I can learn, the character of the foundation bed under the spillway portion of the dam is solid rock and under the remaining portions such foundation bed is solid rock.

The total length of this dam is 500 feet. The spillway or waste-weir portion, is about 350 feet long, and the crest of the spillway is about 6 feet below the top of the dam.

The number, size and location of discharge pipes, waste pipes or gates which may be used for drawing off the water from behind the dam, are as follows: six waste gates, each 6 ft. wide x 8 ft. deep (see general view)

State briefly, in the space below, whether, in your judgment, this dam is in good condition, or bad condition, describing particularly any leaks or cracks which you may have observed.)

*This dam is in good condition and does not leak. The fishway which was built with the dam has been taken out by the ice.*


Reported by C. W. H. Douglass,  
(Signature)

115 Standard St.,  
(Address—Street and number, P. O. Box or R. F. D. route)

Syracuse, N. Y.  
(Name of place)


(SEE OTHER SIDE)

# Oswegatchie R




(In the space below, make one sketch showing the form and dimensions of a cross section through the spillway or waste-weir of this dam, and a second sketch showing the same information for a cross section through the other portion of the dam. Show particularly the greatest height of the dam above the stream bed, its thickness at the top, and thickness at the bottom, as nearly as you can learn.)

### Spillway section



(In the space below, make a third sketch showing the general plan of the dam, and its approximate position in relation to buildings or other conspicuous objects in the vicinity.)

### Section through concrete wall + pier



Concrete abutments in center between spillway + wastegates + between wastegates + canal, of similar construction and dimensions.

10, 1916 U.S. Chas

A. 2. 383

(NOTICE: After filling out one of these forms as completely as possible for each dam in your district, return it at once to the Conservation Commission, Albany.)

STATE OF NEW YORK  
CONSERVATION COMMISSION  
ALBANY

DAM REPORT

July 1, 1916  
(Date)

CONSERVATION COMMISSION.

DIVISION OF INLAND WATERS.

GENTLEMEN:

I have the honor to make the following report in relation to the structure known as the Ogdensburg Water Power Property Dam.


This dam is situated upon the Oswegatchie River  
(Give name of stream)  
in the Town of Ogdensburg, St. Lawrence County,  
about in it from the Village or City of Ogdensburg  
(State distance)  
The distance up stream from the dam, to the Bridge  
(Up or down) (Give name of nearest important stream or of a bridge)  
is about 1000 feet  
(State distance)

The dam is now owned by Ogdensburg Light and Power Co.  
(Give name and address in full)  
and was built in or about the year 1855, and was extensively repaired or reconstructed during the year 1908.


As it now stands, the spillway portion of this dam is built of No spillway. Water flows over entire length of dam  
(State whether of masonry, concrete or other)  
and the other portions are built of concrete  
(State whether of masonry, concrete, earth or timber with or without rock fill)

As nearly as I can learn, the character of the foundation bed under the spillway portion of the dam is \_\_\_\_\_ and under the remaining portions such foundation bed is \_\_\_\_\_

(In the space below, make a third sketch showing the general plan of the dam, and its approximate position in relation to buildings or other conspicuous objects in the vicinity.)



In the space below, make one sketch showing the form and dimension of a cross section through the spillway or waste-weir of this dam, and a second sketch showing the same information for a cross section through the other portion of the dam. Show particularly the greatest height of the dam above the stream bed, its thickness at the top, and thickness at the bottom, as nearly as you can learn.)



The total length of this dam is 350 feet. The ~~spillway or~~ <sup>flap gate or</sup> waste-weir portion, is about Thirty feet long, and the crest of the spillway is about                      feet below the top of the dam.

The number, size and location of discharge pipes, waste pipes or gates which may be used for drawing off the water from behind the dam, are as follows: 58 Openings  
Size 4' x 5' Located at different mills.

At the time of this inspection the water level above the dam was 1.5 ft.            in. ~~below~~ above the crest of the spillway.

(State briefly, in the space below, whether, in your judgment, this dam is in good condition, or bad condition, describing particularly any leaks or cracks which you may have observed.)

The dam appeared to be in very good condition and did not seem to have any leaks in or around it. It is practically a new dam and was put in on the down stream side of an old timber dam which helped to relieve the pressure upon it.

Reported by M. H. Montross  
(Signature)

Harold Norman  
(Address - Street and number, P. O. Box or R. F. D. route)

W. H. Norman, New, etc.



STATE OF NEW YORK  
DEPARTMENT OF  
**State Engineer and Surveyor**  
ALBANY

RECEIVED  
OFFICE OF STATE ENGINEER  
MAR 19 1925  
REF'D TO Mr. K...  
ANS'D

## Report of a Structure Impounding Water

To assist in carrying out the provisions of Section 22 of the Conservation Law, being Chapter LXV of the Consolidated Laws of New York State, relating to safeguarding life and property and the erection, reconstruction, or maintenance of structures for impounding water, owners of such structures are requested to fill out as completely as possible this report form for each such dam or reservoir owned within the State of New York for which no plans or reports relative thereto are on file in this Department, and to return this report form, together with prints or photographs explanatory thereof to this department.

1. The structure is on Oswegatchie River flowing into St. Lawrence in the Town of Oswegatchie County of St. Lawrence and City of Ogdensburg, North of LaFayette Bridge and South-East of Lake Street Bridge,  
(Give exact distance and direction from a well-known bridge, dam, village main cross-roads or mouth of a stream.)
2. Is any part of the structure built upon or does its pond flood any State lands? No
3. The name and address of the owner is Ogdensburg Water Power Property  
Ogdensburg, N. Y. - managed by three Referees appointed by Supreme Court
4. The structure is used for Impounding water for Power purposes
5. The material of the right bank, in the direction with the current, is Concrete retaining wall at the spillway crest elevation this material has a top slope of Flat on top-concrete inches vertical to a foot horizontal on the center line of the structure, a vertical thickness at this elevation of from bed rock, feet, and the top surface extends for a vertical height of 7 feet above the spillway crest.
6. The material of the left bank is clay loam, has a top slope of flat on top, inches to a foot horizontal, a thickness of ✓ feet and a height of Gradual rise back from river, feet.
7. The natural material of the bed on which the structure rests is (clay, sand, gravel, boulders, granite, shale, slate, limestone, etc.) Limestone rock,
8. State the character of the bed and the banks in respect to the hardness, perviousness, water bearing, effect of exposure to air and to water, uniformity, etc. Bed is-bed rock and is hard and impervious non water bearing, no effect of exposure to air and water and is uniform. Banks are fairly hard, impervious non water bearing, exposure to air and water having little effect and are uniform.

9. If the bed is in layers, are the layers horizontal or inclined? Horizontal, If inclined what is the direction of the horizontal outcropping relative to the axis of the main structure and the inclination and direction of the layers in a plane perpendicular to the horizontal outcropping?

10. What is the thickness of the layers? 2" to 5"

11. Are there any porous seams or fissures? No

12. The watershed at the above structure and draining into the pond formed thereby is 1580 square miles.

13. The pond area at the spillway crest elevation is Approximately 160 acres and the pond impounds 69,000,000 cubic feet of water.

14. The maximum known flow of the stream at the structure was 15,200 cubic feet per second on April 10, 1912,  
(Date)

15. Has the spillway capacity ever been exceeded by a high flow? No

Can any possible flood flow from the pond otherwise than through the wastes noted under 17 and 18 of this report? No, If so, give the location, the length and the elevation relative to the spillway crest and the character and slopes of the ground of such possible wastes.

16. State if any damage to life or to any buildings, roads or other property could be caused by any possible failure of the above structure. Describe the location, the character and the use of buildings below the structure which might be damaged by any failure of the structure; of roads adjacent to or crossing the stream below the structure, giving the lowest elevation of the roadway above the stream bed and giving the shape, the height and the width of stream openings; and of any embankments or steep slopes that any flood could pass over. Also indicate the character and use made of the ground below the structure.

Several boathouses on right bank might be damaged. Buildings of Proctor Manufacturing Company and buildings belonging to James McCasland on left bank might be flooded temporarily. Proctor Manufacturing Company are Manufacturers of lumber and mill work and James McCasland has hub factory.

17. WASTES. The spillway of the above structure is 300 feet long in the clear; the waters are held at the right end by a retaining wall of City Water Works, 6'9 3/4" the top of which is 6'9 3/4" feet above the spillway crest, and has a top width of 4 feet; and at the left end by a Power Canal, the top of which is 7 feet above the spillway crest, and has a top width of ----- feet.

18. There is also for flood discharge a pipe ----- inches inside diameter and the bottom is ----- feet below the spillway crest; and a (sluice, gate outlet) ----- feet wide in the clear by ----- feet high, and the bottom is ----- feet below the spillway crest.

19. APRON. Below the spillway there is an apron built of concrete,  
(Material)  
feet wide and ..... feet thick. The downstream side of the apron has a thickness of 1 1/2 to 2 feet  
for a width of tapers up into dam,  
feet.

20. Has the structure any weaknesses which are liable to cause its failure in high flows? No

21. SKETCHES. On the back of this report make a sketch to scale for each different cross-section of the above structure at the greatest depth; giving the height and the depth from the surface of the foundation, the bottom width, the top width (for a concrete or masonry spillway at two feet below the crest), the elevation of the top in reference to the spillway crest, the length of the section, and the material of which the section is constructed; on the spillway section show a cross section of the apron, giving its width, thickness and material, and show the abutment or wash wall at the end of the spillway, giving its heights and thickness. Mark each section with a capital letter. Also sketch a plan; show the above sections by their top lines, giving the mark and the length of each; the openings by their horizontal dimensions; the abutments by their top width and top lengths from the upstream face of the spillway section; and outline the apron. Also sketch an elevation of each end of the structure with a cross section of the banks, giving the depth and width excavated into the banks.

22. WATER SUPPLY. The waters impounded by the above structure have (not) been used for a public water supply since July 1912 by City of Ogdensburg,

The above information is correct to the best of my knowledge and belief.

G. O. R. Bell, J. E. Fell, John Dorsey,

(Name of Referee)

(Signature)

March 18, 1925.

(Date)

Referees, Ogdensburg Water Power Property,  
Ogdensburg, N. Y.

(A person signing for owner should indicate his title or authority)

# DAM INSPECTION REPORT

NS CITY YR AP. DAM NO. INS. DATE USE TYPE

## AS PER INSPECTION

☐ Location of Sp'way and outlet *Hydraulic Canal* ☐ Elevations  
*Blocked off*  
☐ Size of Sp'way and Outlet ☐ Geometry of Non-overflow section

## ☐ GENERAL CONDITION OF NON-OVERFLOW SECTION

☐ Settlement ☐ Cracks ☐ Deflections  
☐ Joints ☐ Surface of Concrete ☐ Leakage  
☐ Undermining ☐ Settlement of Embankment ☐ Crest of Dam  
☐ Downstream Slope ☐ Upstream Slope ☐ Toe of Slope

## ☐ GENERAL COND. OF SP'WAY AND OUTLET WORKS

☐ Auxiliary Spillway ☐ Service or Concrete Sp'way ☐ Stilling Basin  
☐ Joints ☐ Surface of Concrete ☐ Spillway Toe  
☐ Mechanical Equipment ☐ Plunge Pool ☐ Drain

☐ Maintenance ☐ Hazard Class  
☐ Evaluation ☐ Inspector

## COMMENTS:

The Hydraulic Canal That originally went to a power house has been filled in

Dam is in good condition

low and buildings on the shore make this a hazard

1. River Basin - Nos. 1-23 on Compilation Sheets
2. County - Nos. 1-62 Alphabetically
3. Year Approved -
4. Inspection Date - Month, Day, Year
5. Apparent use -
  1. Fish & Wildlife Management
  2. Recreation
  3. Water Supply
  4. Power
  5. Farm
  6. No Apparent Use
6. Type -
  1. Earth with Aux. Service Spillway
  2. Earth with Single Conc. Spillway
  3. Earth with Single non-conc. Spillway
  4. Concrete
  5. Other
7. As-Built Inspection - Built substantially according to approved plans and specifications

#### Location of Spillway and Outlet Works

1. Appears to meet originally approved plans and specifications.
2. Not built according to plans and specifications and location appears to be detrimental to structure.
3. Not built according to plans and specifications but location does not appear to be detrimental to structure.

#### Elevations

1. Generally in accordance to approved plans and specifications as determined from visual inspection and use of hand level.
2. Not built according to plans and specifications and elevation changes appear to be detrimental to structure.
3. Not built according to plans and specifications but elevation changes do not appear to be detrimental to structure.

#### Size of Spillway and Outlet Works

1. Appears to meet originally approved plans and specifications as determined by field measurements using tape measure.
2. Not built according to plans and specifications and changes appear detrimental to structure.
3. Not built according to plans and specifications but changes do not appear detrimental to structure.

#### Geometry of Non-overflow Structures

1. Generally in accordance to originally approved plans and specifications as determined from visual inspection and use of hand level and tape measure.
2. Not built according to plans and specifications and changes appear detrimental to structure.
3. Not built according to plans and specifications but changes do not appear detrimental to structure.

#### General Conditions of Non-Overflow Section

1. Adequate - No apparent repairs needed or minor repairs which can be covered by periodic maintenance.
2. Inadequate - Items in need of major repair.

ITL:MS  
For boxes listed on condition under non-overflow section.

1. Satisfactory.
2. Can be covered by periodic maintenance.
3. Unsatisfactory - Above and beyond normal maintenance.

# GENERAL CONDITION OF SPILLWAY AND OUTLET WORKS

1. Adequate - No apparent repairs needed or minor repairs which can be covered by periodic maintenance.
2. Inadequate - Items in need of major repair.

Items) For boxes listed conditions listed under spillway and outlet works.

1. Satisfactory.
2. Can be covered by periodic maintenance.
3. Unsatisfactory - Above and beyond normal maintenance.
4. Dam does not contain this feature.

## Maintenance

1. Evidence of periodic maintenance being performed.
2. No evidence of periodic maintenance.
3. No longer a dam or dam no longer in use.

## (S.C.S.) Hazard Classification Downstream

1. (A) Damage to agriculture and county roads.
2. (B) Damage to private and/or public property.
3. (C) Loss of life and/or property.

Evaluation - Based on Judgment and Classification in Box Nos.

## Evaluation for Unsafe Dam

1. Unsafe - Repairable.
2. Unsafe - Not Repairable.
3. Insufficient evidence to declare unsafe.

### RIVER BASINS

- (1) LOWER HUDSON
- (2) UPPER HUDSON
- (3) MOHAWK
- (4) LAKE CHAMPLAIN
- (5) DELAWARE
- (6) SUSQUEHANNA
- (7) CHEMUNG
- (8) OSWEGO
- (9) GENESEE
- (10) ALLEGHENY
- (11) LAKE ERIE
- (12) WESTERN LAKE ONTARIO
- (13) CENTRAL LAKE ONTARIO
- (14) EASTERN LAKE ONTARIO
- (15) SALMON RIVER
- (16) BLACK RIVER
- (17) WEST ST. LAWRENCE
- (18) EAST ST. LAWRENCE
- (19) RACQUETTE RIVER
- (20) ST. REGIS RIVER
- (21) HOUSATONIC
- (22) LONG ISLAND
- (23) OSWEGATCHIE
- (24) GRASSE

### COUNTIES

STATE NAME: NEW YORK

STATE ABBREVIATION: NY

STATE CODE: 36

CODE COUNTY NAME

- 1 ALBANY
- 2 ALLEGANY
- 3 BROOK
- 4 BROOME
- 5 CATTARAUGUS
- 6 CAYUGA
- 7 CHAUTAUGUA
- 8 CHEMUNG
- 9 CHENANGO
- 10 CLINTON
- 11 COLUMBIA
- 12 CORTLAND
- 13 DELAWARE
- 14 DUTCHESS
- 15 ERIE
- 16 ESSEX
- 17 FRANKLIN
- 18 FULTON
- 19 GENESEE
- 20 GREENE
- 21 HAMPTON
- 22 HERKIMER
- 23 JEFFERSON
- 24 KINGS
- 25 LEWIS


- 26 LIVINGSTON
- 27 MADISON
- 28 MONROE
- 29 MONTGOMERY
- 30 NASSAU
- 31 NEW YORK
- 32 NIAGARA
- 33 ONEIDA
- 34 ONONDAGA
- 35 ONTARIO
- 36 ORANGE
- 37 ORLEANS
- 38 OSWEGO
- 39 OTSEGO
- 40 PUTNAM
- 41 QUEENS
- 42 RENSSELAER
- 43 RICHMOND
- 44 ROCKLAND
- 45 ST LAWRENCE
- 46 SARATOGA
- 47 SCHENECTADY
- 48 SCHONARIE
- 49 SCHUYLER
- 50 SENECA
- 51 STEUBEN
- 52 SUFFOLK
- 53 SULLIVAN
- 54 TIOGA
- 55 TOMPKINS
- 56 ULSTER
- 57 WARREN
- 58 WASHINGTON
- 59 WAYNE
- 60 WESTCHESTER
- 61 WYOMING
- 62 YATES

CLASSIFICAT  
CORPS ENGR  
(III)  
(II)  
(I)

APPENDIX C

HYDROLOGIC AND HYDRAULIC COMPUTATIONS





SCALE: 1" = 8 MI. 2

# DRAINAGE BASIN

## LEGEND

——— WATERSHED AREA  
 --- SUB AREA



**STETSON • DALE**BANKERS TRUST BUILDING  
UTICA • NEW YORK • 13501  
TEL 315-797-5800**DESIGN BRIEF**

PROJECT NAME

N.Y.S. Dam Inspections - 1980

DATE

SUBJECT

Ogdensburg Water Power Co.

PROJECT NO.

Sub-Basin Areas

DRAWN BY

<u>Sub-Area</u>	<u>Area</u>	<u>Area of Major Lakes</u>
1	341 mi <sup>2</sup>	1.68 mi <sup>2</sup>
2	218	19.35
3	144	10.76
4	119	3.13
5	258	2.30
6	258	1.85
7	194	
8	48	
9	27	

Total = 1607 mi<sup>2</sup>



STETSON • DALE

BANKERS TRUST BUILDING  
UTICA • NEW YORK • 13501  
TEL 315-797-5800

## DESIGN BRIEF

PROJECT NAME N.Y.S. Lam Inspections DATE \_\_\_\_\_

SUBJECT Ogdenburg W.P. Co. Lam PROJECT NO. \_\_\_\_\_

Drainage Parameters DRAWN BY \_\_\_\_\_

<u>Sub-Area</u>	<u>L</u>	<u>L<sub>CA</sub></u>	<u><math>t_p = C_t (L \times L_{CA})^{0.3}</math></u> <u>(<math>C_t = 3</math>)</u>
1	59.6 mi	34.7 mi	29.7
2	21.3	7.5	13.8
3	15.8	6.7	12.1 + .6* = 12.7
4	21.3	14.6	16.8
5	34.5	13.4	18.9
6	39.85	22.1	25.0
7	29.6	11.05	17.1
8	13.8	6.7	11.7
9	11.84	5.13	10.2

\* Adjusted for travel time thru lakes

## TRAVEL TIME THRU LAKES

	<u>Length</u>	<u>avg. depth</u>	<u><math>V = T_{glm}</math></u>	<u>Lag</u>
Cranberry Lake	48,000'	16'	22.7 fps	0.6 hr.
Black Lake				
Sub-area 1 hydrograph	46,000'	12'	19.7	1.35 hr.
Sub-area 2 hydrograph	77,000'			1.1 hr.

**STETSON • DALE**BANKERS TRUST BUILDING  
UTICA • NEW YORK • 13501  
TEL 315-797-5800**DESIGN BRIEF**PROJECT NAME N.Y.S. Dam Inspections - 1980 DATE \_\_\_\_\_SUBJECT Ogdensburg W.P. Co. Dam PROJECT NO. \_\_\_\_\_Precipitation Values DRAWN BY \_\_\_\_\_

Longitude ~ 75°30' Lat. index ~ 44°15'

PMP = 18" for 200 mi<sup>2</sup>, 24 hr. duration  
 Adjusting for the drainage area of  
 ~1600 mi<sup>2</sup> - From HMR #33 (HMR #33 curves  
 only extend to areas = 1000 mi<sup>2</sup> therefore  
 values for area = 1600 mi<sup>2</sup> were extrapolated)

<u>Duration</u>	<u>% of Index</u>
6 hr	45
12	59
24	70
48	77

24 hr. storm, 7 point precipitations

<u>Storm</u>	<u>Point Precipitation</u>	<u>Adjusted Precip. Area Adjustment Factor ~.91</u>
1 yr.	2.1	1.9
2	2.4	2.2
5	3.1	2.8
10	3.5	3.2
25	4.	3.6
50	4.5	4.1
100	4.8	4.37
500	5.8	5.3

**STETSON • DALE**BANKERS TRUST BUILDING  
UTICA • NEW YORK • 13501  
TEL 315-797-5800**DESIGN BRIEF**

PROJECT NAME N.Y.S. Dam Inspections - 1980 DATE \_\_\_\_\_

SUBJECT Ogdensburg Dam NY # 400 PROJECT NO. \_\_\_\_\_

Spillway Rating Curve DRAWN BY \_\_\_\_\_

Length = 350'

Design Head, Assumed  $H_d = 5.5'$  based on spillway geometry

$$Q = CLH^{3/2}$$

C FROM Fig. 14-4 - Open Channel

Hydraulics by Chow

$$C_d = 4.03$$

$$h/H_d = 12/5.5 > 1.33$$

Elev.	$H_e$	$H_e/H_d$	$C/C_d$	C	Q (cfs)
258	0	—			0
259	1	.18	.78	3.14	1100
260	2	.36	.855	3.45	3415
261	3	.55	.915	3.69	6710
262	4	.73	.96	3.87	10835
263	5	.91	.98	3.95	15455
264	6	1.1	1.01	4.07	20935
265	7	1.3	1.02	4.11	26640
266	8	1.5	1.03	4.15	32865
268	10		1.03	4.15	45930
270	12		1.03	4.15	60380
272	14		1.03	4.15	76085
274	16		1.03	4.15	92960
276	18			4.15	110925
278	20			4.15	129915



STETSON • DALE


BANKERS TRUST BUILDING  
UTICA • NEW YORK • 13501  
TEL 315-797-5800

# DESIGN BRIEF


PROJECT NAME N.Y.S. Dam Inspectors - 1980 DATE \_\_\_\_\_

SUBJECT Ogdensburg W.T. Co. Dam PROJECT NO \_\_\_\_\_

DRAWN BY \_\_\_\_\_



Area - Capacity Curve



THIS DRAWING IS A PART OF THE APPLICATION  
 FOR LICENSE MADE BY THE UNDERSIGNED  
 THIS 30TH DAY OF NOVEMBER 1970  
 NIAGARA MOHAWK POWER CORPORATION


BY

TITLE VICE PRESIDENT & CHIEF ENGINEER

NIAGARA MOHAWK POWER CORPORATION  
 SYRACUSE, N. Y.  
**CONSTRUCTED OSWEGATCHIE RIVER PROJECT**  
 EEL WEIR DEVELOPMENT  
 GENERAL PLAN - DAM, INTAKE AND SPILLWAY  
 EXHIBIT L PLAN, ELEVATIONS AND SECTIONS SHEET NO. 7  
 SCALE: 1" = 50'  
 0' 50' 100' 150' 200' 250' 300' 350'



EXCEEDENCE FREQUENCY PER 100 YRS



DISCHARGE - FREQUENCY  
CURVE



STETSON • DALE

DATE

JOB


DRAWN

JPG

APP'D

U.S.G.S. Gage  
No. 04263500  
Near Ogdensburg  
STA. 800

EXCEEDENCE FREQUENCY PER 100 YRS



DISCHARGE - FREQUENCY  
CURVE



STETSON • DALE

DATE

JOB

DRAWN

JPG

APP'D

Heuvelton Gage  
No. 04263000

STA. 700

AD-A091 076

NEW YORK STATE DEPT OF ENVIRONMENTAL CONSERVATION ALBANY F/G 13/13  
NATIONAL DAM SAFETY PROGRAM. OGDENSBURG WATER POWER COMPANY DAM--ETC(U)  
SEP 80 J B STETSON


DACW51-79-C-0001

NI

UNCLASSIFIED

2

1




END  
DATE  
FILMED  
12-80  
DTIC

551F1ED

2 OF 2


AD.

09/06



MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A

EXCEEDENCE FREQUENCY PER 100 YRS



DISCHARGE - FREQUENCY  
CURVE



STETSON • DALE

DATE

JOB

DRAWN

JPG

APP'D

U.S.G.S. Gage  
No. 04262500  
HARRISVILLE, NY  
STA 500


EXCEEDENCE FREQUENCY PER 100 YRS

99 98 95 90 80 70 60 50 40 30 20 10 5 2 1 .5 .2 .1 .05 .02 .01

10,000

DISCHARGE (cfs)

1,000



2

5

10

20

50

100

200

500

1000

2000

5000

10000

EXCEEDENCE INTERVAL IN YRS

DISCHARGE - FREQUENCY  
CURVE



STETSON • DALE

DATE

JOB

DRAWN

JPG

APP'D

U.S.G.S. Gage  
No. 04262000  
Oswegatchie, NY  
STA. 400

CODE	DESCRIPTION	PARAMETER	VALUE	UNIT	REMARKS
0001	OGDENBURG WATER POWER CO. DAM NY 400				
0002	HEC-1DB (SNYDER PARAMETERS)				
0003	PMF - DAM OVERTOPPING ANALYSIS				
0004	1	C	C	C	4
0005	288				
0006	1	C	C	C	
0007	7	1			
0008	0.3	0.4	0.5	0.6	0.8
0009	100	C	0	1	
0010	1 RUNOFF SUBAREA 1				
0011	1	341	0	1607	0
0012	18.	45	59	70	77
0013	0	0	0	0	0
0014	0.550				
0015	-0.20	1.3	0	0	1
0016	201	0	0	0	
0017	2 ROUTE TO BLACK LAKE				
0018	0	0	0	1	
0019	0	0	4.00	0.2	
0020	201	0	0	0	1
0021	0	0	0	1	
0022	3	1			
0023	250	0	0	0	1
0024	4 RUNOFF SUBAREA 2				
0025	1	216	C	1607	0
0026	18.	45	59	70	77
0027	0	0	0	0	0
0028	0.550				
0029	-0.20	1.3	0	0	1
0030	201	0	0	0	
0031	5 ADDITIONAL LAG TO ACCOUNT FOR TRAVEL TIME THRU BLACK LAKE				
0032	0	0	0	1	
0033	3	1			
0034	200	0	0	0	1
0035	6 COMBINE 2 HYDROGRAPHS AT BLACK LAKE				
0036	300	C	C	C	1
0037	8 RUNOFF SUBAREA 3				
0038	1	144	0	1607	0
0039	1	1	0	0	1

(0039)	P	18.	45	59	7C	77	1.0	0.1	0	C.075
(0040)	T	0	C	C	C	C				
(0041)	W	12.7	0.550							
(0042)	X	-2.0	-0.20	1.3						
(0043)	K	1	300	C	C	0	1			
(0044)	K1	10 ROUTE THRU AND OVER CRANBERRY LAKE								
(0045)	Y	C	C	1						
(0046)	Y1	0	C	C	0		-1490			
(0047)	Y4	1493	1492	1494	1496	1500	1502			
(0048)	Y5	0	1855	3800	7870	19880	27315			
(0049)	SS	C	15040	31745	50110	91840	115200			
(0050)	SE	1490	1492	1494	1496	1500	1502			
(0051)	SS	1490								
(0052)	SD	1493	2.6	1.5	1					
(0053)	K	1	400	0	0	C	1			
(0054)	K1	11 ROUTE THRU AREA 4								
(0055)	Y	C	0	C	0	1				
(0056)	Y1	1	0	0	2.6	0.35				
(0057)	K	0	400	0	0	C	1			
(0058)	K1	12 RUNOFF SUBAREA 4								
(0059)	M	1	1	119	0	1607	C	C	1	
(0060)	P	0	16.	45	59	7C	77			
(0061)	T	C	C	0	0	0	1.0	0.1	0	C.026
(0062)	W	16.8	0.550							
(0063)	X	-2.0	-0.20	1.3						
(0064)	K	2	400	0	0	C	1			
(0065)	K1	13 COMBINE 2 HYDROGRAPHS AT 400, 3+4=4								
(0066)	K	1	601	C	C	C	1			
(0067)	K1	15 ROUTE TO CONFLUENCE WITH AREA 5								
(0068)	Y	0	0	C	C	1				
(0069)	Y1	1	C	C	3.7	0.35				
(0070)	K	0	500	0	0	C	1			
(0071)	K1	15 RUNOFF SUBAREA 5								
(0072)	M	1	1	256	C	1607	C	0	1	
(0073)	P	C	16.	45	59	70	77			
(0074)	T	0	C	C	0	C	1.0	0.1	0	0.009
(0075)	W	18.9	0.550							
(0076)	X	-2.0	-0.20	1.3						



(0077)	K	1	601	0	C	C	1	
(0076)	K1	16 ROUTE TO CONFLUENCE WITH AREA 4						
(0079)	Y	0	0	0	1			
(0080)	Y1	0	0	1.9	0.35			
(0081)	K	2	601	0	C	C	1	
(0082)	K1	17 COMBINE 2 HYDROGRAPHS AT 601, 5+4=4						
(0083)	K	1	600	0	C	C	1	
(0084)	K1	18 ROUTE THRU AREA 6						
(0085)	Y	0	0	0	1			
(0086)	Y1	0	0	4.5	0.35	C		
(0087)	K	0	600	0	C	C	1	
(0088)	K1	19 RUNOFF SUBAREA 6						
(0089)	M	1	258	C	1607	0	C	1
(0090)	F	0	18.	59	70	77		
(0091)	T	0	0	0	0	0	1.0	0 C.007
(0092)	W	23.0	0.550					
(0093)	X	-2.0	-0.20	1.3				
(0094)	K	2	600	0	0	0	1	
(0095)	K1	20 COMBINE 2 HYDROGRAPHS AT 600 4+6=6						
(0096)	K	1	700	0	C	C	1	
(0097)	K1	21 ROUTE THRU AREA 7						
(0098)	Y	0	0	0	1			
(0099)	Y1	0	0	10.7	0.25	C		
(0100)	K	0	700	0	C	C	1	
(0101)	K1	22 RUNOFF SUBAREA 7						
(0102)	M	1	194	0	1607	0	0	1
(0103)	P	0	18.	59	70	77		
(0104)	T	0	0	0	C	C	1.0	0.1 C.003
(0105)	W	17.1	0.550					
(0106)	X	-2.0	-0.20	1.3				
(0107)	K	2	700	0	C	C	1	
(0108)	K1	23 COMBINE 2 HYDROGRAPHS AT 700 7+6=7						
(0109)	K	1	801	C	C	C	1	
(0110)	K1	24 ROUTE TO CONFLUENCE WITH AREA 2						
(0111)	Y	0	0	0	1			
(0112)	Y1	0	0	1.9	0.2	C		
(0113)	K	0	800	0	C	C	1	
(0114)	K1	25 RUNOFF SUBAREA 8						

(0115)	M	1	1	48	0	1607	0	C	C	1
(0116)	F	18.	59	77	77	77	77	77	77	1
(0117)	T	0	0	0	0	0	0	0	0	0
(0118)	W	11.7	0.550	1.3	0	0	0	0	0	0
(0119)	X	-2.0	-0.20	0	0	0	0	0	0	0
(0120)	K	3	800	0	0	0	0	0	0	0
(0121)	K1	26	COMBINE 3 HYDROGRAPHS	2+7+8=8	0	0	0	0	0	0
(0122)	K	1	901	0	0	0	0	0	0	0
(0123)	K1	27	ROUTE THRU RESERVOIR AND OVER DAM AT EEL WEIR	0	0	0	0	0	0	0
(0124)	Y	0	0	0	0	0	0	0	0	0
(0125)	Y1	0	0	0	0	0	0	0	0	0
(0126)	Y4	272	273	274	275	276	277	278	279	280
(0127)	Y5	0	2500	8000	15000	23000	32000	42300	53000	64000
(0128)	SS	0	18125	40475	67375	92225	0	0	0	0
(0129)	SE	272	274	276	278	280	0	0	0	0
(0130)	SS	272	0	0	0	0	0	0	0	0
(0131)	SD	280	2.65	1.5	185	0	0	0	0	0
(0132)	K	0	900	0	0	0	0	0	0	0
(0133)	K1	28	RUNOFF SUBAREA 5	0	0	0	0	0	0	0
(0134)	M	1	1	27	0	1607	0	0	0	1
(0135)	P	0	18.	45	59	77	77	77	77	0
(0136)	T	0	0	0	0	0	0	0	0	0
(0137)	W	10.2	0.550	1.3	0	0	0	0	0	0
(0138)	X	-2.0	-0.20	0	0	0	0	0	0	0
(0139)	K	2	900	0	0	0	0	0	0	0
(0140)	K1	29	COMBINE 2 HYDROGRAPHS AT UGDENSBURG DAM	8+9=9	0	0	0	0	0	0
(0141)	K	1	900	0	0	0	0	0	0	0
(0142)	K1	30	ROUTE THRU RESERVOIR AND OVER UGDENSBURG DAM	0	0	0	0	0	0	0
(0143)	Y	0	0	0	0	0	0	0	0	0
(0144)	Y1	0	0	0	0	0	0	0	0	0
(0145)	Y4	258	259	260	261	262	263	264	265	266
(0146)	Y4	270	272	274	276	278	280	282	284	286
(0147)	Y5	0	1100	3415	6710	10835	15455	20935	26640	32865
(0148)	Y5	60380	76085	92960	110925	129915	15455	20935	26640	32865
(0149)	SS	0	560	1450	2080	2820	3665	4665	6980	9780
(0150)	SE	246	254	258	260	262	264	266	270	274
(0151)	SS	258	0	0	0	0	0	0	0	0
(0152)	SD	265	2.65	1.5	150	0	0	0	0	0

	K	1	9J1	0	0	0	1
(0153)	K	1	9J1	0	0	0	1
(0154)	K1	CHANNEL ROUTE DOWNSTREAM OF DAM					
(0155)	V	0	0	1	1	0	0
(0156)	V1	1	0	0	0	0	-1
(0157)	V6	0.160	0.035	0.070	245	1000	0.0015
(0158)	V7	10	260	650	250	248	1000
(0159)	V7	1302	253	1400	280	290	245
(0160)	K	99					1300
(0161)	A						
(0162)	A						
(0163)	A						
(0164)	A						
(0165)	A						

# PREVIEW OF SEQUENCE OF STREAM NETWORK CALCULATIONS

```

RUNOFF HYDROGRAPH AT      100
ROUTE HYDROGRAPH TO      201
ROUTE HYDROGRAPH TO      201
ROUTE HYDROGRAPH TO      200
ROUTE HYDROGRAPH TO      201
COMBINE 2 HYDROGRAPHS AT  220
RUNOFF HYDROGRAPH AT      300
ROUTE HYDROGRAPH TO      300
ROUTE HYDROGRAPH TO      401
ROUTE HYDROGRAPH AT      400
COMBINE 2 HYDROGRAPHS AT  400
ROUTE HYDROGRAPH TO      601
ROUTE HYDROGRAPH AT      500
ROUTE HYDROGRAPH TO      601
COMBINE 2 HYDROGRAPHS AT  601
ROUTE HYDROGRAPH TO      600
ROUTE HYDROGRAPH AT      600
COMBINE 2 HYDROGRAPHS AT  600
ROUTE HYDROGRAPH TO      700
ROUTE HYDROGRAPH AT      700
COMBINE 2 HYDROGRAPHS AT  700
ROUTE HYDROGRAPH TO      801
ROUTE HYDROGRAPH AT      800
COMBINE 2 HYDROGRAPHS AT  800
ROUTE HYDROGRAPH TO      901
ROUTE HYDROGRAPH AT      900
COMBINE 2 HYDROGRAPHS AT  900
ROUTE HYDROGRAPH TO      900
ROUTE HYDROGRAPH TO      901
END OF NETWORK
    
```

\*\*\*\*\*  
 FLOOD HYDROGRAPH PACKAGE (HEC-1)  
 DAM SAFETY VERSION JULY 1978  
 LAST MODIFICATION 20 FEB 75  
 \*\*\*\*\*

RUN DATED: AUG 75 19.0  
 TIME 213507:14

CONDENSED WATER POWER CO. DAM NY 400  
 REC-105 (SYDER PARAMETERS)  
 PMF - DAM OVERTOPPING ANALYSIS

JOB SPECIFICATION									
AL	HR	MIN	DAY	HR	MIN	METRIC	IFLT	IFRT	INSTAN
002	1	0	0	0	0	0	0	4	0
			JUFR	NWT	LICPT	TRACE			
			5	0	0	0			

MULTI-PLAN ANALYSES TO BE PERFORMED  
 NPLAN= 1 NPTIO= 7 LPTIC= 1  
 RTIOS= 0.20 0.30 0.40 0.50 0.60 0.80 1.00

\*\*\*\*\*

SUB-AREA RUNOFF COMPLETION

1 RUNOFF SUBAREA 1  
 ISTAQ ICCMP ILCON ITAPE JPLT JFRT INAME ISTAGE IAFUTO  
 1 0 0 0 0 0 0 0 0 0

HYDROGRAPH DATA									
INVDG	INDG	TAPLA	SNAP	TRSDA	TRSPC	RATIO	ISNO	ISAME	LOCAL
1	1	541.00	0.00	1077.00	0.00	0.000	0	1	0

PRECIP DATA			
SPEE	PMS	R12	R24
0.00	12.00	45.00	59.00
			70.00
			77.00
			0.00
			0.00
			0.00

TRSPC COMPUTED BY THE PROGRAM IS 0.917

LOSS DATA										
INOPT	STKX	BLTRF	MTICL	FRIN	STKSC	RTIOK	STRTL	CNSTL	ALSMX	RTIYP
1	0.00	0.00	1.00	0.00	0.00	1.00	1.00	0.10	0.00	0.00

UNIT HYDROGRAPH DATA  
 TF= 25.70 CPE= 55 NTA= 0

RECESSION DATA

23

●●●●●●●●●●

ROUTE TO BLACK LAKE

★ ★ ★ ★ ★ ★ ★ ★ ★ ★

☆☆☆☆☆☆☆☆

4. RUOFF SUHARA 2

ISTAQ	ICOMP	IECON	ITAFE	JPLT	JFRT	INAME	ISTAGE	IAUTO
2.0	5	0	0	0	0	1	0	0

HYDR(1),GAP, DATA

ITEM	ITEM	TAREA	TYPE	TRSD	TRSDC	RATIO	ISNO	ISAME	LOCAL
1	1	210.00	0.00	1607.00	0.00	0.000	0	1	0

PRECIP DATA

SPFE	PMS	RC	R12	R24	448	R72	R96
12.00	12.00	45.00	50.00	100.00	177.50	0.00	0.00

TRSPAL COMPUTED BY THE PROGRAM IS 0.917

**LUSS DATA**

LRPOT	STRKR	DLTKR	RTIOL	ERAIN	STRKS	PTIOK	STRTL	CNSTL	ALSMX	RTIPE
10.00	10.00	10.00	1.00	5.00	5.00	1.00	1.00	0.10	5.00	0.0

UNIT HYDROGRAPH DATA  
TC= 13.80 CP=0.55

RECESSION DATA  
STRTQ# -2.00 QRC#N= -0.20 RTOR= 1.30

[illegible]

MO. DA	HR. MIN	PERIOD	RAIN	EXCS	LCSS	COMP Q	MO. DA	HR. MIN	PERIOD	RAIN	EXCS	LOSS	COMP Q
END-OF-PERIOD FLOW													
SUM													
12.73 9.49 3.24 1564508.													
( 323.)( 241.)( 82.)(44313.22)													

10  
 9  
 8  
 7  
 6  
 5  
 4  
 3  
 2  
 1

HYDROGRAPH FOUTING

5 ADDITIONAL LAG TO ACCOUNT FOR TRAVEL TIME THRU BLACK LAKE

ROUTING DATA

QLOSS	CLOSS	AVG	IFRS	ISAP	IOFT	IFPP	LSTR
0.0	0.00	0.00	0	1	0	0	0

NSTFS	NSTD	LAG	AMSK	X	TSK	STOR	ISFRAT
0	3	1	0.00	0.00	0.00	C.	0

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

# COMBINE HYDROGRAPHS

5 COMBINE 2 HYDROGRAPHS AT BLACK LAKE 1+2=2

ISTAQ	ICOMP	IECON	ITAPE	JPLT	JFRT	INAME	ISTAGE	I-UTO
2.0	2	0	0	0	0	1	0	0

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

# SUB-AREA RUNOFF COMPLETION

6 RUNOFF SUB-AREA 3

ISTAQ	ICOMP	IECON	ITAPE	JPLT	JFRT	INAME	ISTAGE	I-UTO
3.0	0	0	0	0	0	1	0	0

HYDROGRAPH DATA

INVG	IUPE	TAREA	SNAP	TRSDA	TRSPC	RATIO	ISHOW	ISAME	LOCAL
1	1	144.00	0.00	1607.00	0.00	0.000	0	1	0

# PRECIP DATA

SPEE	PMS	R1	R12	R24	R48	R72	R96
0.00	16.00	45.00	59.00	70.00	77.00	0.00	0.00

TRSPC COMPUTED BY THE PROGRAM IS 1.919

# LOSS DATA

LROPT	STIRK	DLTKR	RTIOL	ERAIN	STIRKS	RTIOL	STRTL	CYSTL	ALSMX	RTIAP
0.00	0.00	0.00	1.00	0.00	0.00	1.00	1.00	0.10	0.00	0.7

# UNIT HYDROGRAPH DATA

TP= 12.00 CP=370. NTA= 0

# RECESSION DATA

STRTG= -2.00 ORCSN= -0.20 RTIOR= 1.30

UNIT HYDROGRAPH 23 END-OF-PERIOD ORIGINATES, LAG= 12.00 HOURS, CP= 0.77 VCL= 1.00

040.	1754.	2602.	3207.	3711.	4152.	4551.	4917.	5258.	5578.
5800.	6077.	5907.	5696.	5384.	5052.	4696.	4311.	3887.	3410.
2652.	2137.	1012.							

# END-OF-PERIOD FLOW



**A**

**B**

**C**

**D**

**E**

# HYDROGRAPH ROUTING

11 ROUTE THOL AREA 4  
 ISTAQ ICCMP 1  
 4.0 0 0  
 ROUTING DATA  
 IRES ISAME 1 0  
 0.0 0.00 0.00  
 NSTPS NSTDL 1 0  
 1 0 2.600 0.350  
 LAG ANSKK X  
 0 0 0.100 C. C.

\*\*\*\*\*

## SUB-AREA RUNOFF COMPUTATION

12 RUNOFF SUBAREA 4  
 ISTAQ ICCMP 0  
 4.0 0 0  
 JPLT JFRT INAPE ISTAGE I-AUTO  
 0 0 1 0 0

HYDROGRAPH DATA  
 IHYG IUNG TAREA SNAF TRSDA TRSPC RATIO ISNOW ISAME LOCAL  
 1 1 119.30 0.00 1607.00 0.00 0.000 C 1 C

PRECIP DATA  
 SPEE PMS RC R12 R24 R48 R72 R96  
 0.00 15.00 45.00 59.00 70.00 77.00 0.00 0.00

TRSPC COMPUTED BY THE PROGRAM IS 0.919

LOSS DATA  
 LROPT STRKR ULTKR RTICL ERAIN STRKS RTIOK STRIL CNSTL ALSMX RTIMP  
 0 0.00 0.00 1.00 0.00 0.00 0.00 1.00 0.10 0.00 0.00

UNIT HYDROGRAPH DATA  
 TF= 16.80 CP= 0.55 NTA= 0

RECESSION DATA  
 STRTG= -2.00 QRCSN= -0.20 RTIOR= 1.30

UNIT HYDROGRAPH END-OF-PERIOD ORDINATES, LAG= 16.74 HOURS, CP= 0.55 VOL= 0.09  
 35. 154. 270. 440. 636. 843. 1061. 1290. 1527. 1761.  
 1972. 2153. 2355. 2425. 2514. 2569. 2586. 2549. 2451. 2330.  
 2215. 2106. 1903. 1839. 1720. 1635. 1555. 1478. 1405. 1305.  
 1270. 1147. 1091. 1037. 986. 937. 891. 847. 811. 767.  
 705. 692. 652. 625. 594. 565. 537. 511. 485. 461.  
 439. 417. 396. 377. 350. 324. 308. 286. 264. 243.  
 225. 204. 182. 159. 144. 131. 118. 105. 91. 78.  
 67. 56. 43. 31. 20. 10. 0. 0. 0. 0.

MO.DA	HR.MN	PERIOD	RAIN	EACS	LOSS	55.	57.	50.	47.	45.	43.	41.
END-OF-PERIOD FLOW												
MO.DA HR.MN PERIOD RAIN EACS LOSS												
SUM 12.73 9.27 3.47 800451.												
( 323.)( 235.)( 88.)(22666.23)												

\*\*\*\*\*

# COMBINE HYDROGRAPHS

13 COMBINE 2 HYDROGRAPHS AT 400, 344=4

ISTAG	ICOMP	IECON	ITAFE	JFLT	JFRT	INAME	ISTAGE	I-UTO
4.0	2	0	0	0	0	1	0	0

\*\*\*\*\*

# HYDROGRAPH ROUTING

15 ROUTE TO CONFLUENCE WITH AREA 5

ISTAG	ICOMP	IECON	ITAFE	JFLT	JFRT	INAME	ISTAGE	I-UTO
4.1	1	0	0	0	0	1	0	0

ROUTING DATA

QLOSS	AVG	IRIS	ISAME	LOPT	IPMP	LSTR
0.0	0.00	0	1	0	0	0

INSTPS NSTBL LAG AMSKK X TSK STORA ISPRAT

1	0	3.700	0.350	0 <th>0.00</th> <th>0 </th>	0.00	0
0	0	3.700	0.350	0	0.00	0

\*\*\*\*\*

# SUE-AREA RUNOFF COMPUTATION

15 RUNOFF SUBAREA 5

INVDG	IURC	IAREA	SNAP	TRSDA	TRSPC	RATIC	ISNOW	ISAME	LOCAL
1	1	258.00	0.00	1607.00	0.00	0.010	0	1	0

PRECIP DATA

SPFE	PHS	RG	R12	R24	R48	R72	R96
0.00	10.00	45.00	59.00	70.00	77.00	0.00	0.00

TRSPC COMPUTED BY THE PROGRAM IS .919

17	COMBINE 2 HYDROGRAPHS AT 001, 5+4=4	JFLT	JFT	INAME	ISTAGE	TAUTO
	ISTAG	ICOMP	IECON	ITAFE		

6.1 2 0 0 0 0 1 0 0

\*\*\*\*\*

HYDROGRAPH ROUTING

IC ROUTE THRU AREA  
ISTAQ ICCPP 1  
6.0  
ROUTING DATA  
OLGSS CLOSS AVG IRES ISAME IOPT IFMP LSTR  
0.0 0.000 0.00 0 1 0 0  
NSTPS NSTDL LAG AMSKK X TSK STORA ISPRAT  
1 0 4.500 0.357 0.000 0 0

\*\*\*\*\*

SUB-AREA RUNOFF COMPLETION

15 RUNOFF SUBAREA 6  
ISTAQ ICCPP 0  
6.0  
HYDROGRAPH DATA  
IMYDG IUPG TAREA SNAF TRSDA TRSPC NATIC ISNOW ISAME LOCAL  
1 1 258.00 0.00 1607.00 0.00 0.000 C 0 1 0

PRECIP DATA  
SPEE PMS R6 R12 R24 R48 R72 R96  
0.00 15.00 45.00 59.00 70.00 77.00 0.00 0.00

TRSPC COMPUTED BY THE PROGRAM IS 0.919

LOSS DATA  
LROFT STAKH DLTKR RTIOL ERAIN STRKS RTIOK STATL CASTL ALSMX PTIPP  
0.00 0.00 1.00 0.00 0.00 0.00 1.00 1.00 0.10 0.00 0.1

UNIT HYDROGRAPH DATA  
1F= 23.00 CP=0.55 NTA= C

RECESSION DATA  
STATG= -2.00 QRCSN= -0.20 RTIOF= 1.50

UNIT HYDROGRAPH .00 END-OF-PERIOD ORDINATES, LAG= 23.10 HOURS, CP= 0.55 VOL= 0.6  
36. 136. 201. 455. 652. 868. 1098. 1341. 1595. 1858.  
2129. 2426. 2685. 2948. 3186. 3398. 3585. 3746. 3880. 3987.  
4060. 4115. 4130. 4104. 4015. 3878. 3750. 3599. 3467. 3340.  
3217. 3099. 2905. 2676. 2770. 2669. 2571. 2476. 2386. 2298.

NO	HR	DA	PERIOD	RAIN	EXCS	LOSS	COMP Q	PO	DA	HR	MIN	PERIOD	RAIN	EXCS	LOSS	COMP Q
2214	2133	2054	1579	1916	1130	1769	1704	1642	1581							
1523	1408	1414	1362	1312	1204	1217	1173	1130	1088							
1348	1010	973	937	913	870	838	807	777	749							
721	895	869	845	821	790	766	735	705	675							
496	478	467	444	427	412	397	382	368	355							
342	324	317	305	294	283	273	263	253	244							

END-OF-PERIOD FLOW

SUM 12.73 9.20 3.53 1630148.  
( 323.)( 234.)( 90.)(40160.61)

\*\*\*\*\*

# COMBINE HYDROGRAPHS

20 COMBINE 4 HYDROGRAPHS AT 600 4+0=6

ISTAQ	ICOMP	IECON	ITAPE	JFLT	JPRT	INAME	ISTAGE	IAUTO
600	2	0	0	0	0	1	0	0

\*\*\*\*\*

# HYDROGRAPH ROUTING

21 ROUTE THRU AREA 7

ISTAQ	ICOMP	IECON	ITAPE	JFLT	JPRT	INAME	ISTAGE	IAUTO
700	1	0	0	0	0	1	0	0

ROUTING DATA

QLOSS	CLOSS	AVG	IRCS	ISAME	IOFT	IPMP	LSIR
0.0	0.00	0.00	0	1	0	0	0

INSTPS NSTDL LAG AMSKK X TSK STORA ISPRAT

1	0	10.700	0.250	0.000	0

\*\*\*\*\*

# SUE-AREA RUN-OFF COMPUTATION

22 RUNOFF SUBAREA 7

ISTAQ	ICOMP	IECON	ITAPE	JFLT	JPRT	INAME	ISTAGE	IAUTO
700	0	0	0	0	0	1	0	0

# HYDROGRAPH DATA

INHYD	IUPG	TAREA	SNAP	TRSDA	TRSPC	RATIO	ISNOW	ISAME	LOCAL
1	1	194.00	9.00	1607.00	0.00	0.000	0	1	0

```

PRECIP DATA
R72 R9C
0.00 77.00 C.00
R72 R9C
0.00 77.00 C.00

```

LOSS DATA										
LOGPT	STRIKE	CLTRF	RTICL	BRAIN	STRKS	RTICK	STRTL	CSTL	ALSMX	RTIDP
0.0	0.0	0.0	1.00	0.00	1.00	1.00	1.00	0.10	0.00	0.00

UNIT HYDROGRAPH DATA  
IP= 17.10 CP=0.55 STA= C

```

RECESSION DATA
STRATUM= -2.23 QRC5N= -1.21 RTIOR= 1.39

```

UNIT	HYDROGRAPH	1 - END-OF-PERIOD	ORDINATES,	LAGE =	17.13 HOURS,	CP = 0.55	VOL = 3.19
50.	212.	436.	705.	1036.	1332.	1676.	2415.
100.	326.	375.	3874.	4026.	4125.	4166.	3947.
150.	342.	374.	3114.	2962.	2617.	2680.	2424.
200.	2866.	1904.	1828.	1795.	1762.	1624.	1545.
250.	1265.	1213.	1144.	1023.	1035.	985.	936.
300.	725.	693.	663.	627.	627.	597.	568.
350.	442.	420.	410.	387.	362.	344.	327.
400.	252.	255.	242.	231.	209.	219.	198.
450.	171.	162.	154.	147.	140.	133.	120.
500.	103.	95.	89.	85.	81.	77.	73.
550.							69.
600.							65.
650.							61.
700.							57.
750.							53.
800.							49.
850.							45.
900.							41.
950.							37.
1000.							33.

C		END-OF-PERIOD FLO <sup>W</sup>				C							
MM.DA	HR.MN	PERIOD	RAIN	EXCS	LOSS	COMP Q	P.C.DA	HR.MN	PERIOD	RAIN	EXCS	LOSS	COMP G
									SUM	12.73	9.19	3.55	1290918.
										( 323.)	( 233.)	( 90.)	(36554.69)

COMBINE HYDROGRAPHS

## HYDROGRAPH POUTING

ROUTING DATA

QLOSS CLOSS AVG IPES ISAPE ICFI IFMP LSTR  
 0.00 0.000 0.00 0 1 0 0  
 ASTES NSTDL LAG ANSKK X TSK STORA ISPRAT  
 1 0 0 1.900 0.200 0.000 0.000 0

\*\*\*\*\*

# SUB-AREA RUN-OFF COMPUTATION

45 RUNOFF SUBAREA 8  
 ISTAG ICMF IECON ITAFE JFLT JFRT INAME ISTAGE I-UTO  
 000 0 0 0 0 0 1 0 0

HYDROGRAPH DATA  
 INYDG IUDG TAREA SNAF TRSDA TRSFC PATIC ISNCG ISAME LOCAL  
 1 1 48.00 0.00 1007.00 0.00 0.000 0 1

PRECIP DATA  
 SFE PMS R0 R12 R24 R48 R72 R96  
 0.00 12.00 45.00 59.00 70.00 77.00 0.00 0.00

TRSPC COMPUTED BY THE PROGRAM IS 0.919

LOSS DATA  
 LROPT STRKR ULTKR RTIOL ERAIN STRKS RTIUR STRTL CNSTL ALSMX RTIIP  
 0.00 0.00 1.00 0.00 0.00 0.00 1.00 1.00 0.10 0.00 0.00

UNIT HYDROGRAPH DATA  
 TP= 11.70 CP=0.55 NTA= 0

RECESION DATA  
 STKQ= -2.00 QRCNS= -0.20 RTIOR= 1.30

UNIT HYDROGRAPH 80 END-OF-PERIOD ORIGINATES, LAC= 11.65 HCLRS, CP= 0.55 VOL= 1.0  
 34. 129. 264. 423. 599. 787. 979. 1153. 1293. 1397.  
 1464. 1590. 1711. 1831. 1951. 2071. 2191. 2311. 2431. 2551.  
 2671. 2791. 2911. 3031. 3151. 3271. 3391. 3511. 3631. 3751.  
 3871. 3991. 4111. 4231. 4351. 4471. 4591. 4711. 4831. 4951.  
 5071. 5191. 5311. 5431. 5551. 5671. 5791. 5911. 6031. 6151.  
 6271. 6391. 6511. 6631. 6751. 6871. 6991. 7111. 7231. 7351.  
 7471. 7591. 7711. 7831. 7951. 8071. 8191. 8311. 8431. 8551.  
 8671. 8791. 8911. 9031. 9151. 9271. 9391. 9511. 9631. 9751.  
 9871. 10000.

MC.DA MR.MN PERIOD RAIN EXCS LOSS COMP 3 END-OF-PERIOD FLOW  
 SUM 12.73 9.19 3.55 346324.  
 ( 323.)( 233.)( 90.)( 9806.75)



```

*****
COMBINE HYDROGRAPHS
*****
26 COMBINE 3 HYDROGRAPHS 2+7+8=8
  ISTAQ  ICOMP  IECON  ITAPE  JPLT  JPRT  INAME  ISTAGE  IAUTO
    0.0    3      0      0      0      0      1      0      0
*****

```

```

*****
HYDROGRAPH ROUTING
*****
27 ROUTE THRU RESERVOIR AND OVER DAM AT EEL WEIR
  ISTAQ  ICOPP  IECON  ITAPE  JPLT  JPRT  INAME  ISTAGE  IAUTO
    5.1    1      0      0      0      0      1      0      0
  ROUTING DATA
  QLOSS  CLUSS  AVG  IHES  ISAME  IOPT  IPMP  LSTR
    0.0    0.000  0.00  1      0      0      0      C
  NSTPS  NSTDL  LAG  AMSKK  X  TSK  STORA  ISPRAY
    1      0      0  0.000  0.000  0.000  -272.  -1
  STAGE  272.00  273.00  274.00  275.00  276.00  277.00  278.00  279.00  280.00
  FLOW   1.00   2500.00  8000.00  15000.00  23000.00  32000.00  42300.00  53000.00  64000.00
  CAPACITY= 0.  18125.  40475.  67375.  94225.
  ELEVATION= 272.  274.  276.  278.  280.

```

```

*****
DAM DATA
*****
  TOPEL  COGD  EXPD  DAMWID
  280.0  2.6  1.5  185.

```

```

PEAK OUTFLOW IS 25356. AT TIME 84.00 HOURS
PEAK OUTFLOW IS 38754. AT TIME 84.00 HOURS
PEAK OUTFLOW IS 51059. AT TIME 84.00 HOURS
PEAK OUTFLOW IS 64656. AT TIME 85.00 HOURS
PEAK OUTFLOW IS 72221. AT TIME 85.00 HOURS
PEAK OUTFLOW IS 105881. AT TIME 85.00 HOURS
PEAK OUTFLOW IS 135944. AT TIME 85.00 HOURS

```

\*\*\*\*\*

SUB-AREA RUNOFF COMPLETION

20 RUNOFF SUBAREA 9  
ISTAG ICOMP IECON ITAFE JPLT JFRT INAME ISTAGE I-UTO  
900 0 0 0 0 1 0

HYDROGRAPH DATA  
INPDC IUNG TAREA SNAP TRSDA TRSFC RATIO ISNOW ISAME LOCAL  
1 27.00 0.00 1607.00 0.00 0.000 0 1

PRECIP DATA  
SPFE PMS R6 R12 R24 R48 R72 R96  
0.00 18.00 45.00 59.00 70.00 77.00 0.00 0.00

TRSPC COMPUTED BY THE PROGRAM IS 0.919

LOSS DATA  
LROPT STRKR DLTGR RTIOL ERAIN STKRS RTIOK STPTL CNSTL ALSPX RTJPF  
0 0.00 0.00 1.00 1.00 0.00 0.00 1.00 0.10 0.00 0.00

UNIT HYDROGRAPH DATA  
TF= 10.20 CP=0.55 RTA= 0

RECESSION DATA  
SRTG= -2.00 QRCNS= -0.20 RTIDE= 1.30

UNIT HYDROGRAPH 69 END-OF-PERIOD ORDINATES, LAG= 13.26 HOURS, CP= 0.55 VOL= 1.00  
27. 101. 205. 328. 462. 603. 733. 837. 911. 953.  
957. 910. 838. 770. 705. 651. 598. 550. 506. 465.  
428. 393. 361. 332. 305. 281. 258. 237. 218. 201.  
184. 170. 156. 143. 132. 121. 111. 102. 94. 87.  
80. 73. 67. 62. 57. 52. 48. 44. 41. 37.  
34. 32. 29. 27. 25. 23. 21. 19. 18. 16.  
15. 14. 13. 12. 11. 10. 9. 8. 6.

MO.DA HR.MN PERIOD RAIN EXCS LOSS END-OF-PERIOD FLOW  
COMP Q MO.DA HR.MN PERIOD RAIN EXCS LOSS COMP Q  
SUM 12.73 9.19 3.55 201681.  
( 323.)( 233.)( 90.)( 5710.96)

\*\*\*\*\*

COMBINE HYDROGRAPHS

29 COMBINE 2 HYDROGRAPHS AT UGDENSBURG DAM 849=5  
ISTAG ICOMP IECON ITAFE JPLT JFRT INAME ISTAGE I-UTO  
900 2 0 0 0 1 0

\*\*\*\*\*

HYDROGRAPH ROUTING

3. ROUTE THRU RESERVOIR AND OVER GREENSBURG DAM

ISTAG ICONF RECON ITARE JPLY JERT INAME ISTAGE I-UTO

GLUSS CLOSS AVG  
C.O 0.000 0.00

ROUTING DATA

IPES ISAME IOFT IFMP LSTR

NSTPS NSTDL  
1 0

LAG ANSKK X ISK STURA ISPRAT

STAGE 254.00 259.00 260.00 261.00 262.00 263.00 264.00 265.00 266.00

FLOW 6.38E+00 1100.00 3415.00 6710.00 10635.00 15455.00 20935.00 26140.00 32865.00

CAPACITY= 0. 560. 1450. 2060. 2820. 3625. 4665. 6980. 9780. 12750.

ELEVATION= 246. 254. 258. 260. 262. 264. 266. 270. 274. 278.

CREL SPLID CCGW EXPW ELEV COUL CAREA EXPL  
252.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0

DAM DATA  
TOPEL CUGD EXFD DAMWID  
265.0 2.6 1.5 150.

PEAK OUTFLOW IS 25542. AT TIME 85.00 HOURS  
PEAK OUTFLOW IS 39050. AT TIME 84.00 HOURS  
PEAK OUTFLOW IS 52170. AT TIME 84.00 HOURS  
PEAK OUTFLOW IS 65167. AT TIME 84.00 HOURS  
PEAK OUTFLOW IS 78829. AT TIME 84.00 HOURS  
PEAK OUTFLOW IS 106694. AT TIME 84.00 HOURS  
PEAK OUTFLOW IS 134957. AT TIME 84.00 HOURS

\*\*\*\*\*

# HYDROGRAPH ROUTING

## CHANNEL ROUTE DOWNSTREAM OF DAM

ISTAG	ICUFP	IECON	ITAFE	JFLT	JFRT	INAPE	ISTAGE	I-UTO
5.1	1	0	0	0	0	1	0	0
ROUTING DATA								
QLUSS	CLUSS	AVG	IPES	ISAME	IGFT	IPMP	LSTR	
0.0	0.000	0.00	1	1	0	0	0	
NSTPS NSTDL LAG AMSK A TSK STORA ISPRAT								
1	2	0.00	0.000	0.000	0.000	-1.	0	

## NORMAL DEPTH CHANNEL ROUTING

GN(1)	GN(2)	GN(3)	ELNVT	ELMAP	RLNTH	SEL
100.00	100.00	100.00	290.00	290.00	100.00	0.0000

## CROSS SECTION COORDINATES--STA, ELEV, STAGE, ELEV--ETC

100.00	200.00	650.00	250.00	950.00	245.00	100.00	245.00	245.00
1300.00	255.00	1400.00	280.00	1650.00	290.00			

STORAGE	10.54	39.32	77.40	124.84	170.51	244.88	316.13	388.30
	534.05	607.63	621.67	631.16	906.67	984.58	1165.70	1150.03
OUTFLOW	0.00	2001.65	6002.67	15250.33	43171.22	63091.28	88774.83	119904.64
	1934.00.15	255611.77	281266.44	330316.56	437691.94	495242.44	556034.00	621660.00
STAGE	245.00	247.37	249.74	252.11	256.84	259.21	261.58	263.95
	260.66	271.95	273.42	275.79	280.53	282.89	285.26	287.63
FLOW	100.00	2001.65	6002.67	15250.33	43171.22	63091.28	88774.83	119904.64
	1934.00.15	255611.77	281266.44	330316.56	437691.94	495242.44	556034.00	621660.00

MAXIMUM STAGE IS 254.1

MAXIMUM STAGE IS 256.2

MAXIMUM STAGE IS 257.9

MAXIMUM STAGE IS 259.4

MAXIMUM STAGE IS 260.7

MAXIMUM STAGE IS 262.9

MAXIMUM STAGE IS 265.0

\*\*\*\*\*

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS  
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)  
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION	STATION	AREA	PLAN	RATIOS APPLIED TO FLOWS						
				RATIO 1	RATIO 2	RATIO 3	RATIO 4	RATIO 5	RATIO 6	RATIO 7
				0.20	0.30	0.40	0.50	0.60	0.80	1.00
HYDROGRAPH AT	101	341.00 ( 843.12)	1	7524. ( 213.36)	11285. ( 319.57)	15047. ( 426.09)	18809. ( 532.61)	22571. ( 639.13)	30094. ( 852.18)	37618. ( 1065.22)
	201	341.00 ( 843.12)	1	7363. ( 208.48)	11044. ( 312.72)	14725. ( 416.97)	18466. ( 521.21)	22088. ( 625.45)	29450. ( 833.93)	36813. ( 1042.42)
ROUTED TO	201	341.00 ( 843.12)	1	7350. ( 208.13)	11025. ( 312.19)	14701. ( 416.26)	18375. ( 520.32)	22050. ( 624.39)	29400. ( 832.52)	36750. ( 1040.64)
	200	218.00 ( 564.61)	1	9821. ( 272.09)	14731. ( 417.14)	19642. ( 556.19)	24552. ( 695.23)	29462. ( 834.28)	39283. ( 1112.37)	49104. ( 1390.47)
ROUTED TO	201	218.00 ( 564.61)	1	9765. ( 276.52)	14648. ( 414.77)	19530. ( 553.03)	24413. ( 691.29)	29295. ( 829.55)	39060. ( 1106.66)	48825. ( 1382.58)
2 COMBINED	200	559.00 ( 1447.75)	1	13068. ( 369.48)	19572. ( 554.22)	26096. ( 738.95)	32620. ( 923.69)	39144. ( 1108.43)	52192. ( 1477.51)	65240. ( 1847.39)
	300	144.00 ( 372.96)	1	10017. ( 283.64)	15025. ( 425.46)	20033. ( 567.28)	25042. ( 709.10)	30050. ( 850.91)	40066. ( 1134.55)	50083. ( 1418.19)
ROUTED TO	300	144.00 ( 372.96)	1	1568. ( 44.40)	2332. ( 66.02)	3082. ( 87.26)	3860. ( 109.30)	5160. ( 146.13)	7755. ( 219.61)	10860. ( 307.51)
ROUTED TO	400	144.00 ( 372.96)	1	1568. ( 44.39)	2331. ( 66.00)	3081. ( 87.24)	3858. ( 109.24)	5157. ( 146.02)	7735. ( 219.62)	10781. ( 305.29)
HYDROGRAPH AT	400	119.00 ( 308.21)	1	4436. ( 125.62)	6654. ( 188.42)	8872. ( 251.23)	11050. ( 314.04)	13308. ( 376.85)	17744. ( 502.46)	22180. ( 628.08)
	400	263.00 ( 681.16)	1	5574. ( 157.84)	8363. ( 236.80)	11125. ( 315.03)	13883. ( 395.13)	16625. ( 470.76)	23010. ( 651.57)	29576. ( 837.49)
ROUTED TO	601	263.00 ( 681.16)	1	5448. ( 154.28)	8171. ( 231.37)	10870. ( 307.81)	13566. ( 384.15)	16300. ( 461.58)	22512. ( 637.47)	28987. ( 820.83)
	50	258.00 ( 668.21)	1	6640. ( 244.65)	12960. ( 366.98)	17280. ( 489.30)	21599. ( 611.63)	25919. ( 733.95)	34559. ( 978.60)	43199. ( 1223.26)

ROUTED TO	601	250.00 ( 608.21)	1	8592. ( 243.30)	128.00 ( 304.95)	17164. ( 486.60)	21420. ( 608.25)	25776. ( 729.90)	34308. ( 973.20)	42960. ( 1216.50)
2 COMBINED	601	521.00 ( 1349.37)	1	14018. ( 390.90)	21028. ( 595.45)	28017. ( 793.36)	35050. ( 951.10)	41972. ( 1188.52)	56568. ( 1601.83)	71472. ( 2023.87)
ROUTED TO	600	521.00 ( 1349.37)	1	13575. ( 384.41)	20361. ( 576.55)	27129. ( 768.20)	33892. ( 959.72)	40719. ( 1153.04)	54924. ( 1555.26)	69379. ( 1964.59)
HYDROGRAPH AT	600	258.00 ( 668.21)	1	7253. ( 205.37)	10879. ( 308.36)	14505. ( 410.74)	18132. ( 513.43)	21758. ( 616.11)	29015. ( 821.48)	36263. ( 1026.85)
2 COMBINED	600	779.00 ( 2017.59)	1	20093. ( 585.97)	31039. ( 878.94)	41367. ( 1171.39)	51690. ( 1463.71)	62031. ( 1756.51)	83237. ( 2357.02)	104684. ( 2964.31)
ROUTED TO	700	779.00 ( 2017.59)	1	17704. ( 501.31)	26555. ( 751.21)	35382. ( 1001.91)	44211. ( 1251.92)	53209. ( 1506.72)	71485. ( 2024.22)	90018. ( 2549.02)
HYDROGRAPH AT	700	194.00 ( 502.45)	1	7112. ( 201.38)	10667. ( 302.37)	14223. ( 402.76)	17779. ( 503.45)	21335. ( 604.14)	28447. ( 805.52)	35558. ( 1006.90)
2 COMBINED	700	973.00 ( 2520.04)	1	21271. ( 602.34)	31916. ( 903.47)	42528. ( 1204.27)	53148. ( 1504.97)	63822. ( 1807.25)	85529. ( 2421.90)	107455. ( 3042.77)
ROUTED TO	801	973.00 ( 2520.04)	1	21174. ( 595.59)	31765. ( 899.33)	42333. ( 1198.74)	52904. ( 1498.07)	63539. ( 1799.21)	85145. ( 2411.03)	106979. ( 3029.30)
HYDROGRAPH AT	800	46.00 ( 124.32)	1	2418. ( 68.47)	3627. ( 102.70)	4836. ( 136.94)	6045. ( 171.17)	7254. ( 205.41)	9672. ( 273.88)	12090. ( 342.34)
3 COMBINED	800	1580.00 ( 4092.15)	1	32953. ( 933.13)	49433. ( 1399.73)	65898. ( 1866.02)	82362. ( 2332.23)	98834. ( 2798.68)	132036. ( 3738.85)	165400. ( 4683.60)
ROUTED TO	901	1580.00 ( 4092.15)	1	23356. ( 718.00)	38754. ( 1097.40)	51659. ( 1462.63)	64658. ( 1830.90)	78221. ( 2214.97)	105851. ( 2998.21)	133944. ( 3792.87)
HYDROGRAPH AT	900	27.00 ( 69.93)	1	1528. ( 43.27)	2292. ( 64.90)	3056. ( 86.54)	3820. ( 108.17)	4584. ( 129.81)	6112. ( 173.08)	7640. ( 216.35)
2 COMBINED	900	1607.00 ( 4162.08)	1	25570. ( 724.07)	39060. ( 1106.63)	52095. ( 1475.17)	65207. ( 1846.47)	78881. ( 2233.65)	100760. ( 3023.12)	135044. ( 3824.01)
ROUTED TO	900	1607.00 ( 4162.08)	1	25548. ( 723.44)	39053. ( 1105.76)	52070. ( 1474.47)	65167. ( 1845.33)	78829. ( 2232.19)	106654. ( 3021.24)	134957. ( 3821.56)
ROUTED TO	901	1607.00 ( 4162.08)	1	25548. ( 723.43)	39048. ( 1105.73)	52069. ( 1474.43)	65164. ( 1845.24)	78826. ( 2232.15)	106657. ( 3021.32)	134961. ( 3821.67)

# SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1 .....

RATIO OF PMF	MAXIMUM RESERVOIR W.S.ELEV	ELEVATION STORAGE OUTFLOW	INITIAL VALUE 1490.00 J. 0.	SPILLWAY CREST 1490.00 C. C.	TOP OF DAM 1493.00 2393. 2828.	DURATION OVER TOP HOURS	MAXIMUM OUTFLOW CFS	MAXIMUM STORAGE AC-FT	MAXIMUM DEPTH OVER DAM	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
0.20	1491.59					0.00	1568.	12714.	0.00	71.00	0.00
0.30	1492.49					0.00	2332.	19133.	0.00	71.00	0.00
0.40	1493.26					45.00	3082.	25572.	0.00	72.00	0.00
0.50	1494.03					84.00	3260.	32003.	0.00	72.00	0.00
0.60	1494.87					105.00	5160.	37858.	0.00	67.00	0.00
0.80	1495.94					131.00	7755.	49534.	0.00	63.00	0.00
1.00	1497.59					148.00	10860.	60981.	0.00	62.00	0.00

# SUMMARY OF DAM SAFETY ANALYSTS

PLAN 1 .....	ELEVATION STORAGE OUTFLOW	INITIAL VALUE 272.00 0. 0.	SPILLWAY CREST 272.00 0. 0.	TOP OF DAM 260.00 99225. 64000.	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
	MAXIMUM RESERVOIR W.S. ELEV	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS				
0.20	276.26	43996.	25326.	0.00	84.00	0.00	0.00
0.30	277.66	62745.	32754.	0.00	84.00	0.00	0.00
0.40	278.87	74305.	51659.	0.00	84.00	0.00	0.00
0.50	279.96	103167.	64658.	8.00	83.00	0.00	0.00
0.60	281.23	116643.	78221.	33.00	83.00	0.00	0.00
0.80	283.51	155182.	105881.	54.00	83.00	0.00	0.00
1.00	285.74	196712.	133944.	67.00	83.00	0.00	0.00



# SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1 .....

ELEVATION  
STORAGE  
OUTFLOW

INITIAL VALUE  
252.00  
1450.  
C.

SPILLWAY CREST  
258.00  
1450.  
C.

TOP OF DAM  
265.00  
4175.  
26640.

RATIO	MAXIMUM	MAXIMUM	MAXIMUM	MAXIMUM	DURATION	TIME OF	TIME OF
OF	RESERVOIR	DEPTH	STORAGE	OUTFLOW	OVER TOP	MAX OUTFLOW	FAILURE
PMF	W.S.-ELEV	OVER DAM	AC-FT	CFS	HOURS	HOURS	HOURS
0.20	264.81	3.00	4081.	25548.	0.36	85.00	0.00
0.30	266.20	1.80	5126.	39048.	46.00	84.00	0.00
0.40	268.49	3.49	6107.	52070.	65.00	84.00	0.00
0.50	270.14	5.04	7006.	65167.	78.00	84.00	0.00
0.60	271.51	6.51	8036.	78829.	88.00	84.00	0.00
0.80	274.20	9.20	9987.	106694.	104.00	84.00	0.00
1.00	276.23	11.23	11860.	134957.	116.00	84.00	0.00

PLAN 1 STATION 501

RATIO	MAXIMUM	MAXIMUM	MAXIMUM	TIME
OF	FLOW/CFS	STAGE/FT	HOURS	HOURS
0.20	25548.	254.1	65.00	84.00
0.30	39048.	256.2	84.00	84.00
0.40	52070.	257.9	84.00	84.00
0.50	65167.	259.4	84.00	84.00
0.60	78829.	260.7	84.00	84.00
0.80	106697.	262.9	84.00	84.00
1.00	134961.	265.0	84.00	84.00



ADJUTANTS WATER POWER CO. DAM NY 400

(0039)	M	0	1	144	C	1607	0	C	0	1	
(0040)	C	-24	4.4								
(0041)	T	0	0	0	C	C	0	-1	-69	0	0.075
(0042)	W	12.7	0.550								
(0043)	X	-0.75	-0.20	1.3	0	C	0	1			
(0044)	K	1	300	0	0	C	0				
(0045)	K1		10 ROUTE THRU AND OVER CRANBERRY LAKE								
(0046)	Y	0	0	0	1						
(0047)	Y1	1	0	0	0	C	0	-1490			
(0048)	Y4	1490	1492	1494	1496	1498	1500	1502			
(0049)	Y5	0	1855	3800	7870	13340	19880	27315			
(0050)	SS	0	15040	31745	50110	70145	91840	115200			
(0051)	SE	1490	1492	1494	1496	1498	1500	1502			
(0052)	SS	1490									
(0053)	SD	1493	2.6	1.5	1						
(0054)	K	1	400	0	0	C	0	1			
(0055)	K1		11 ROUTE THRU AREA 4								
(0056)	Y	0	0	0	C	1					
(0057)	Y1	1	0	0	2.6	0.35	0	1			
(0058)	K	0	400	0	0	C	0				
(0059)	K1		12 RUNOFF SUBAREA 4								
(0060)	M	0	1	115	0	1607	0	C	0	1	
(0061)	0	-24	4.4								
(0062)	T	0	0	0	0	0	0	-1	-69	0	0.026
(0063)	W	16.6	0.550								
(0064)	X	-0.75	-0.20	1.3	0	C	0	1			
(0065)	K	2	400	C	C	C	0	1			
(0066)	K1		13 COMBINE 2 HYDROGRAPHS AT 400, 3+4=4								
(0067)	K	1	601	0	0	C	0	1			
(0068)	K1		15 ROUTE TO CONFLUENCE WITH AREA 5								
(0069)	Y	0	0	0	0	1					
(0070)	Y1	1	0	0	3.7	0.35	C	1			
(0071)	K	0	500	0	0	C	0				
(0072)	K1		15 RUNOFF SUBAREA 5								
(0073)	M	0	1	258	0	1607	0	C	0	1	
(0074)	0	-24	4.4								
(0075)	T	0	0	0	C	C	0	-1	-69	0	0.009
(0076)	W	18.9	0.550								

[illegible]

[illegible]

1 CUDENSBURG WATER POWER CO. DAM NY 400

PAGE 0005

(0153)	SD	265	2.65	1.5	50
(0154)	K	yy			
(0155)	A				
(0156)	A				
(0157)	A				
(0158)	A				
(0159)	A				

# PREVIEW OF SEQUENCE OF STREAM NETWORK CALCULATIONS

```

100
RUNOFF HYDROGRAPH AT
ROUTE HYDROGRAPH TC
ROUTE HYDROGRAPH TC
201
RUNOFF HYDROGRAPH AT
ROUTE HYDROGRAPH TC
200
ROUTE HYDROGRAPH TC
COMBINE 2 HYDROGRAPHS AT
201
RUNOFF HYDROGRAPH AT
ROUTE HYDROGRAPH TC
300
ROUTE HYDROGRAPH TC
ROUTE HYDROGRAPH TC
400
RUNOFF HYDROGRAPH AT
COMBINE 2 HYDROGRAPHS AT
400
ROUTE HYDROGRAPH TC
601
RUNOFF HYDROGRAPH AT
ROUTE HYDROGRAPH TC
500
COMBINE 2 HYDROGRAPHS AT
601
ROUTE HYDROGRAPH TC
600
RUNOFF HYDROGRAPH AT
COMBINE 2 HYDROGRAPHS AT
600
ROUTE HYDROGRAPH TC
700
RUNOFF HYDROGRAPH AT
COMBINE 2 HYDROGRAPHS AT
700
ROUTE HYDROGRAPH TC
801
RUNOFF HYDROGRAPH AT
COMBINE 3 HYDROGRAPHS AT
800
ROUTE HYDROGRAPH TC
901
RUNOFF HYDROGRAPH AT
COMBINE 2 HYDROGRAPHS AT
900
ROUTE HYDROGRAPH TC
900
END OF NETWORK

```

\*\*\*\*\*  
 FLOOD HYDROGRAPH PACKAGE (HEC-1)  
 DAM SAFETY VERSION JULY 1978  
 LAST MODIFICATION 26 FEB 75  
 \*\*\*\*\*

RUN DATE: TUE, AUG 05 1980  
 TIME: 17:52:56

OGDENSBURG WATER POWER CO. DAM NY 400  
 HEC-1DB (SNYDER PARAMETERS) 100 YR. STORM  
 HYPOTHETICAL STORM - CALIBRATION OF MODEL - SCS TYPE II DISTRIBUTION

NO NMR NMIN IDAY IMR IMIN METRC IPLT IFRT NSTAN  
 280 1 0 0 0 0 0 0 4 0  
 JOPER MWT LRPT TRACE  
 3 0 0 0

JOB SPECIFICATION

\*\*\*\*\*

SUB-AREA RUNOFF COMPLETION

1 RUNOFF SUBAREA 1  
 ISTAQ ICOMP IECON ITAFE JPLT JFRT INAME ISTAGE I-AUTO  
 100 0 0 0 0 0 1 0 0

HYDROGRAPH DATA

INMDC IUNG TAREA SNAF TRSDA TRSPC RATIO ISNOW ISAME LOCAL  
 C 1 341.00 0.00 1607.00 0.00 0.00 0 1 0

LOSS DATA

LRPT STAKR DLTKR RTIOL ERAIN STRKS RTIOK STRTL CMSTL ALSMX RTIMP  
 C 0.00 0.00 1.00 0.00 0.00 1.00 -1.00 -69.00 C.CC C.CC

CURVE NO = -69.00 WETNESS = -1.00 EFFECT CN = 69.00

UNIT HYDROGRAPH DATA

TF= 29.70 CP=5.55 NTA= C

RECESSION DATA

STRTQ= -0.75 QRCSN= -0.20 RTIOK= 1.30

UNIT HYDROGRAPH 100 END-OF-PERIOD ORDINATES, LAG= 29.79 HOURS, CP= 0.55 VOL= 0.51  
 25. 96. 199. 325. 467. 623. 791. 969. 1156. 1351.  
 1553. 1760. 1973. 2191. 2413. 2637. 2856. 3061. 3249. 3421.  
 3578. 3718. 3842. 3950. 4040. 4114. 4169. 4205. 4210. 4246.  
 4168. 4281. 3967. 3746. 3640. 3537. 3438. 3340. 3246.



3155.	3066.	2979.	2695.	2613.	2734.	2657.	2582.	2509.	2438.
2309.	2302.	2237.	2174.	2113.	2053.	1995.	1939.	1884.	1831.
1775.	1725.	1680.	1633.	1587.	1542.	1498.	1456.	1415.	1375.
1330.	1299.	1262.	1226.	1192.	1158.	1125.	1094.	1063.	1033.
1004.	975.	940.	921.	895.	870.	845.	821.	798.	776.
754.	732.	712.	692.	672.	653.	635.	617.	599.	583.

MP.DA HR.MN PERIOD RAIN EXCS LOSS COMP Q MO.DA HR.MN PERIOD RAIN EXCS LOSS COMP Q

END-OF-PERIOD FLOW

SUM 4.40 1.55 2.85 353760.

( 112.)( 39.)( 72.)(10017.36)

\*\*\*\*\*

# HYDROGRAPH ROUTING

2 ROUTE TO BLACK LAKE

ISTAQ	ICOMP	IECON	ITAPE	JPLT	JPRT	INAME	ISTAGE	IAUTO
201	1	0	0	0	0	1	C	0

ROUTING DATA

QLOSS	CLOSS	AVG	IPMP	LSTR
0.0	0.000	0.00	0	0

ROUTING DATA

LAG	AMSKK	X	TSK	STORA	ISFRAT
0	4.000	0.200	0.000	C.	0

NSTPS NSTDL

1	0
---	---

\*\*\*\*\*

# HYDROGRAPH ROUTING

3 ADDITIONAL LAG TO ACCOUNT FOR TRAVEL TIME THRU BLACK LAKE

ISTAQ	ICOMP	IECON	ITAPE	JPLT	JPRT	INAME	ISTAGE	IAUTO
201	1	0	0	0	0	1	0	0

ROUTING DATA

QLOSS	CLOSS	AVG	IPMP	LSTR
0.0	0.000	0.00	0	0

ROUTING DATA

LAG	AMSKK	X	TSK	STORA	ISFRAT
0	1	0.000	0.000	C.	0

NSTPS NSTDL

0	3
---	---

\*\*\*\*\*

# SUB-AREA RUNOFF COMPUTATION

4 RUNOFF SUBAREA 2

ISTAQ	ICOMP	IECON	ITAPE	JPLT	JPRT	INAME	ISTAGE	IAUTO
200	C	0	0	0	0	1	0	0

[illegible]

6 COMBINE 2 HYDROGRAPHS AT BLACK LAKE 1+2=2

6 COMBINE 2 HYDROGRAPHS AT BLACK LAKE 1+2=2 JPL  
ISTAD ICOMP JECON ITAFE 0  
2.0 2 0

[illegible]

3 RINOFF SUBAREA 3

ISTAQ	ICOMP	IECON	ITAPE	JPLT	JPRT	INAME	ISTAGE	IAUTO
300	C	0	0	0	0	1	C	0

INHY6	IUHG	TABLE	SNAP	TRSDA	TRSPC	RATIO	ISNOW	ISAME	LOCAL
0	1	144.00	0.00	1607.00	0.00	0.000	0	1	0

LOSS DATA										
LEOPT	STKR	DLTR	RTIOL	ERAIN	STRKS	RTIOK	STRTL	CNSTL	ALSMX	HTIMP
0	0.00	0.00	1.00	0.00	0.00	1.00	-1.00	-69.00	0.00	0.07

CURVE NO = -69.00 NETNESS = -1.00 EFFECT CM = 69.00

UNIT HYDROGRAPH DATA  
TF= 12.00 CP=\$70. NTA= 0

```
STRITQ= -C.75  QRCSN= -C.20  RTIOR= 1.50
```

UNIT HYDROGRAPH 23 END-OF-PERIOD ORDINATES, LAG= 12.08 HOURS, CP= 0.77 VOL= 1.00

62..	1754.	2602.	3207.	3711.	4152.	4551.	4917.	5256.	5578.
58..	6377.	5987.	5696.	5384.	5052.	4696.	4311.	3887.	3410.
2852.	2137.	1012.							

C		END-OF-PERIOD FLOW				C							
MO.DA	MR.MN	PERIOD	RAIN	EXCS	LCSS	COMP Q	PO.DA	MR.MN	PERIOD	RAIN	EXCS	LOSS	COMP Q
									SUM	4.4C	1.75	2.65	229945.
										( 112.)	( 44.)	( 67.)	( 6511.31)

● ● ● ● ● ● ● ●  
● ● ● ● ● ● ● ●  
● ● ● ● ● ● ● ●  
● ● ● ● ● ● ● ●

10 ROUTE THRU AND OVER CRANBERRY LAKE

ISTAG	ICOMP	IECON	ITYAE	JPLT	JPRI	INAME	ISTAGE	IAUTO
300	1	0	0	0	0	1	0	0

CREL	SPWID	COOM	EXPW	ELEV	COGL	CAREA	EXPL
1495.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0

DAM DATA	
TOPEL	COGD EXPD DAMWID
1493.0	2.6 1.5 1.

PEAK OUTFLOW IS 1444. A7 TIME 46.00 HOURS

[illegible]

## HYDROGRAPH ROUTING

11 ROUTE THRU AREA 4  
ISTAQ ICOMP  
400 1

GLOSS	CLOSS	AVG
C.0	0.000	0.00

NS7FS 1  
NS7DL 0

[illegible]

## SUB-AREA RUNOFF COMPLETION

12 RUNOFF SUBAREA 4  
ISTAG IC  
400

HYDROGRAPH DATA	
IMYDG	TRSDA
0	0.00
1	1.19
2	2.38
3	3.57
4	4.76
5	5.95
6	7.14
7	8.33
8	9.52
9	10.71
10	11.90
11	13.09
12	14.28
13	15.47
14	16.66
15	17.85
16	19.04
17	20.23
18	21.42
19	22.61
20	23.80
21	25.00
22	26.19
23	27.38
24	28.57
25	29.76
26	30.95
27	32.14
28	33.33
29	34.52
30	35.71
31	36.90
32	38.09
33	39.28
34	40.47
35	41.66
36	42.85
37	44.04
38	45.23
39	46.42
40	47.61
41	48.80
42	50.00
43	51.19
44	52.38
45	53.57
46	54.76
47	55.95
48	57.14
49	58.33
50	59.52
51	60.71
52	61.90
53	63.09
54	64.28
55	65.47
56	66.66
57	67.85
58	69.04
59	70.23
60	71.42
61	72.61
62	73.80
63	75.00
64	76.19
65	77.38
66	78.57
67	79.76
68	80.95
69	82.14
70	83.33
71	84.52
72	85.71
73	86.90
74	88.09
75	89.28
76	90.47
77	91.66
78	92.85
79	94.04
80	95.23
81	96.42
82	97.61
83	98.80
84	100.00
85	101.19
86	102.38
87	103.57
88	104.76
89	105.95
90	107.14
91	108.33
92	109.52
93	110.71
94	111.90
95	113.09
96	114.28
97	115.47
98	116.66
99	117.85
100	119.04
101	120.23
102	121.42
103	122.61
104	123.80
105	125.00
106	126.19
107	127.38
108	128.57
109	129.76
110	130.95
111	132.14
112	133.33
113	134.52
114	135.71
115	136.90
116	138.09
117	139.28
118	140.47
119	141.66
120	142.85
121	144.04
122	145.23
123	146.42
124	147.61
125	148.80
126	150.00
127	151.19
128	152.38
129	153.57
130	154.76
131	155.95
132	157.14
133	158.33
134	159.52
135	160.71
136	161.90
137	163.09
138	164.28
139	165.47
140	166.66
141	167.85
142	169.04
143	170.23
144	171.42
145	172.61
146	173.80
147	175.00
148	176.19
149	177.38
150	178.57
151</	

LUSS DATA  
 LROPT STRKR DLTKR RTIOL ERAIN STRKS RTIOL STRIL CNSTL ALSMX RTIIP  
 C 5.00 5.00 1.00 0.00 0.00 1.00 -1.00 -69.00 0.00 0.3

CURVE NO = -69.00 WEINSS = -1.00 EFFECT CN = 69.00

UNIT HYDROGRAPH DATA  
 TF= 16.80 CP=0.55 NTA= C

RECESSION DATA  
 STRTQ= -0.75 QRCSN= -0.20 RTIOR= 1.30

UNIT HYDROGRAPH-100 END-OF-PERIOD ORIGINATES, LAG= 16.74 HOURS, CP= 0.55 VOL= 0.9  

35.	134.	276.	446.	636.	843.	1061.	1290.	1527.	1761.
1972.	2153.	2305.	2425.	2514.	2569.	2586.	2549.	2451.	2330.
2215.	2106.	2002.	1903.	1809.	1720.	1635.	1555.	1478.	1405.
1336.	1270.	1207.	1147.	1091.	1037.	986.	937.	891.	847.
805.	765.	728.	692.	658.	625.	594.	565.	537.	511.
485.	461.	439.	417.	396.	377.	358.	341.	324.	308.
293.	278.	264.	251.	239.	227.	216.	205.	195.	186.
176.	168.	159.	152.	144.	137.	130.	124.	118.	112.
106.	101.	96.	91.	87.	83.	78.	75.	71.	67.
64.	61.	58.	55.	52.	50.	47.	45.	43.	41.

MC.DA HR.MN PERIOD RAIN EXCS LOSS END-OF-PERIOD FLOW  
 MO.DA HR.MN PERIOD RAIN EXCS LOSS COMP G  
 SUM 4.4C 1.61 2.79 140512.  
 ( 112.)( 41.)( 71.)( 3978.85)

# COMBINE HYDROGRAPHS

13 COMBINE 2 HYDROGRAPHS AT 400, 3+4=4  

ISTAQ	ICOPF	IECON	ITAFE	JPLT	JFRT	INAME	ISTAGE	IAUTO
400	2	0	0	0	0	1	C	0

# HYDROGRAPH ROUTING

15 ROUTE TO CONFLUENCE WITH AREA 5

ISTAQ	ICOMP	IECON	ITAFE	JPLT	JFRT	INAME	ISTAGE	IAUTO
601	1	0	0	0	0	1	0	0
ROUTING DATA								
QLOSS	CLOSS	AVG	IRES	ISAME	IOPT	IFPP	LSTR	C
0.0	0.000	0.00	0	1	0	0		

\*\*\*\*\*  
NSTPS NSTDL LAG AMSKK X TSK STORA ISPRAT  
1 0 0 3.700 0.350 0.000 0  
\*\*\*\*\*

\*\*\*\*\* SUB-AREA RUNOFF COMPUTATION \*\*\*\*\*

SUB-AREA RUNOFF COMPUTATION

15 RUNOFF SUBAREA 5  
ISTAN ICOMP IECON ITAPE JPLT JPRT INAME ISTAGE IAUO  
570 0 0 0 0 0 1 0 0

HYDROGRAPH DATA  
INYUG IUNG TAREA SNAP TRSDA TRSPC RATIO ISNOW ISAME LOCAL  
0 1 258.00 0.00 1607.00 0.00 C.000 0 1 0

LOSS DATA  
LROFT STRKR DLTKR MTIOL ERAIN STRKS MTIOK STRTL CVSTL ALSMX RTIMP  
0.00 0.00 1.00 0.00 0.00 1.00 -1.00 -69.00 0.00 0.01

CURVE NO = -69.00 WETNESS = -1.00 EFFECT CN = 69.00

UNIT HYDROGRAPH DATA  
TF= 18.90 CP=0.55 NTA= C

RECESSION DATA  
STRTO= -0.75 QRCNS= -0.20 RTIUR= 1.30

UNIT HYDROGRAPH END-OF-PERIOD ORIGINATES, LAG= 18.86 HOURS, CP= 0.55 VOL= 0.52  
58. 219. 452. 731. 1045. 1380. 1749. 2131. 2527. 2936.  
3342. 3716. 4044. 4325. 4561. 4749. 4887. 4973. 4999. 4946.  
4797. 4579. 4377. 4184. 4000. 3823. 3655. 3494. 3339. 3192.  
3051. 2917. 2788. 2665. 2548. 2435. 2328. 2225. 2127. 2033.  
1944. 1858. 1776. 1698. 1623. 1551. 1483. 1418. 1355. 1295.  
1236. 1164. 1131. 1082. 1034. 986. 945. 903. 843. 825.  
769. 754. 721. 689. 659. 630. 602. 575. 550. 526.  
502. 480. 459. 420. 401. 383. 366. 350. 335. 335.  
320. 292. 280. 267. 255. 244. 233. 223. 213. 213.  
204. 195. 186. 176. 170. 163. 156. 149. 142. 136.

MC.DA HR.MN PERIOD RAIN EACS LOSS END-OF-PERIOD FLOW MC.DA HR.MN PERIOD RAIN EACS LOSS COMP Q  
SUM 4.40 1.56 2.84 289540.  
( 112.)( 40.)( 72.)( 8196.85)

HYDROGRAPH ROUTING

16 ROUTE TO CONFLUENCE WITH AREA 4

ISTAQ	ICOMP	IECON	ITAFE	JPLT	JFRT	JNAME	ISTAGE	IAUTO
601	1	0	0	0	0	1	0	0

ROUTING DATA

QLOSS	CLOSS	AVG	IRIS	ISAME	IOFT	IPMP	LSTR
0.0	0.00	0.00	0	1	0	0	0

NSIPS NSTDL LAG AMSKK X TSK STORA ISFRAT

1	0	0	1.900	0.350	0.000	0
---	---	---	-------	-------	-------	---

\*\*\*\*\*

# COMBINE HYDROGRAPHS

17 COMBINE 2 HYDROGRAPHS AT 601, 5+4=4

ISTAQ	ICOMP	IECON	ITAFE	JPLT	JFRT	JNAME	ISTAGE	IAUTO
601	2	0	0	0	0	1	0	0

\*\*\*\*\*

# HYDROGRAPH ROUTING

18 ROUTE THRU AREA 6

ISTAQ	ICOMP	IECON	ITAFE	JPLT	JFRT	JNAME	ISTAGE	IAUTO
600	1	0	0	0	0	1	0	0

ROUTING DATA

QLOSS	CLOSS	AVG	IRIS	ISAME	IOFT	IPMP	LSTR
0.0	0.000	0.00	0	1	0	0	0

NSIPS NSTDL LAG AMSKK X TSK STORA ISFRAT

1	0	0	4.500	0.350	0.000	0
---	---	---	-------	-------	-------	---

\*\*\*\*\*

# SUB-AREA RUNOFF COMPUTATION

19 RUNOFF SUBAREA 6

ISTAQ	ICOMP	IECON	ITAFE	JPLT	JFRT	JNAME	ISTAGE	IAUTO
600	0	0	0	0	0	1	0	0

HYDROGRAPH DATA

IMYDG	IUNG	TAREA	SNAP	TRSDA	TRSPC	RATIG	ISNOW	ISAME	LOCAL
0	1	250.00	0.00	1607.00	0.00	0.000	0	1	0

LOSS DATA

LPROT	STKR	DLTK	RTIOL	ERAIN	STRS	RTIOK	STRTL	CNSTL	ALSMX	RTIMP
0	0.00	0.00	1.00	0.00	0.00	1.00	-1.00	-69.00	0.00	0.0

UNIT HYDROGRAPH DATA  
TF= 23.00 CP=C.55 NTA= C

```

RECESSION DATA
STRIG= -5.75  QRCSN= -0.20  RTIOR= 1.30

```

UNIT	HYDROGRAPHIC	END-OF-PERIOD	ORDINATES	LAG	23.10	HOURS	CP	D.55	VOL	0.56
36.	136.	261.	455.	652.	868.	1098.	1341.	1555.	1858.	
2129.	4406.	2685.	2948.	3186.	3398.	3585.	3746.	3880.	3987.	
4066.	4115.	4130.	4104.	4015.	3878.	3736.	3599.	3460.	3340.	
3217.	3099.	2985.	2876.	2770.	2684.	2571.	2476.	2386.	2298.	
2214.	2133.	2054.	1979.	1906.	1836.	1769.	1704.	1642.	1581.	
1523.	1468.	1414.	1362.	1312.	1264.	1217.	1173.	1130.	1088.	
1345.	1010.	973.	937.	903.	870.	838.	807.	777.	749.	
721.	695.	669.	645.	621.	598.	576.	555.	535.	515.	
496.	478.	461.	444.	427.	412.	397.	382.	368.	355.	
342.	329.	317.	305.	294.	283.	273.	263.	253.	244.	

END-OF-PERIOD FLOW													
MC.DA	HR.MN	PERIOD	RAIN	EXCS	LGSS	COMP Q	MO.DA	HR.MN	PERIOD	RAIN	EXCS	LOSS	CONF Q
									SUM	4.40	1.55	2.85	279427.
										( 112.)	( 39.)	( 72.)	( 7912.48)

[illegible]

## COMBINE HYDROGRAPHS

20 COMBINE 2 HYDROGRAPHS AT 600 4+6=6

ISTAQ	ICGPP	IECON	ITAPE	JPLY	JFRT	INAME	ISTAGE	I' AUTO
600	2	0	0	0	0	1	0	0

[illegible]

## HYDROGRAPH ROUTING

21 ROUTE THRU AREA 7

ISTAQ	ICOPP	IECON	ITAFE	JPLT	JFRT	INAME	ISTAGE	IAUTO
7C0	1	0	0	0	0	1	0	0

QLOSS	CLOSS	AVG	IRES	ISAVE	ROUTING DATA
0.0	0.700	0.00	0	1	

INSTPS	NSTDL	LAG	AMSKK	X	TSK	STORA	ISPRAT
1	3	0	10.700	0.250	0.000	0.	0



\*\*\*\*\*

SUB-AREA RUNOFF COMPUTATION

12 RUNOFF SUBAREA 7  
ISTAG ICCPP IECON ITAPE JPLT JFRT INAME ISTAGE IAUTO  
7 0 0 0 0 0 1 0 0

HYDROGRAPH DATA  
INAME JUNG TAREA SNAF TRSDA TRSPC RATIO ISNOW ISAME LOCAL  
1 194.00 0.00 1607.00 0.00 0.00 0 1 0

LOSS DATA  
LROFT STRR DLTR RTIOL ERAIN STRKS RTIOK STRTL CNSTL ALSMX RTIMP  
0.00 0.00 1.00 0.00 0.00 1.00 -1.00 -69.00 0.00 0.00

CURVE NO = -09.00 NETNESS = -1.00 EFFECT CN = 69.00

UNIT HYDROGRAPH DATA  
TF= 17.10 CP=0.55 NTA= 0

RECESSION DATA  
STRTO= -0.75 QRCSN= -0.20 RTIOR= 1.30

UNIT HYDROGRAPHING END-OF-PERIOD ORDINATES, LAG= 17.15 HOURS, CP= 0.55 VOL= 0.59  
50. 212. 436. 705. 1006. 1332. 1678. 2040. 2415. 2789.  
3131. 3426. 3674. 3875. 4026. 4125. 4166. 4133. 3957. 3805.  
3619. 3442. 3274. 3114. 2962. 2817. 2680. 2549. 2424. 2306.  
2193. 2086. 1984. 1888. 1795. 1708. 1624. 1545. 1470. 1398.  
1330. 1265. 1203. 1144. 1088. 1035. 985. 936. 891. 847.  
806. 767. 729. 693. 660. 627. 597. 568. 540. 514.  
488. 465. 442. 420. 400. 380. 362. 344. 327. 311.  
296. 282. 268. 255. 242. 231. 219. 209. 198. 189.  
179. 171. 162. 154. 147. 140. 133. 126. 120. 114.  
103. 98. 94. 89. 85. 81. 77. 73. 69. 65.

MO.DA HR.MN PERIOD RAIN EXCS LOSS END-OF-PERIOD FLOW MO.DA HR.MN PERIOD RAIN EXCS LOSS COMP Q  
SUM 4.40 1.54 2.86 219506.  
( 112.)( 39.)( 73.)( 6215.71)

\*\*\*\*\*

COMBINE HYDROGRAPHS

23 COMBINE 2 HYDROGRAPHS AT 700 746=7  
ISTAG ICCPP IECON ITAPE JPLT JFRT INAME ISTAGE IAUTO  
700 2 0 0 0 0 1 0 0

\*\*\*\*\*

HYDROGRAPH ROUTING

24 ROUTE TO CONFLUENCE WITH AREA 2  
ISTAQ ICOPP IECON ITAPE JPLT JFRT INAME ISTAGE IAUTO  
001 1 0 0 0 0 0 0 0

ROUTING DATA

QLOSS CLOSS AVG IRES ISAME IOFT IFPP LSTR  
0.0 0.000 0.00 0 1 0 0 0

NSTPS NSTDL LAG AMSKK X TSK STORA ISPRAT  
1 0 0 1.900 0.200 0.000 0 0

\*\*\*\*\*

SUB-AREA RUNOFF COMPUTATION

25 RUNOFF SUBAREA 8

ISTAQ ICOPP IECON ITAPE JPLT JFRT INAME ISTAGE IAUTO  
000 0 0 0 0 0 0 0 0

HYDROGRAPH DATA

INVDG IUPC TAREA SNAF TRSDA TRSPC RATIO ISNOW ISAME LOCAL  
0 1 48.00 0.00 1607.00 0.00 0.000 0 1 0

LOSS DATA

LPROPT STRKR DLTKR RTIOL ERAIN STRKS RTIOK STRTL CNSTL ALSMX RTIMP  
0 0.00 0.00 1.00 0.00 0.00 1.00 -1.00 -69.00 0.00 0.0

CURVE NO = -69.00 WETNESS = -1.10 EFFECT CN = 69.00

UNIT HYDROGRAPH DATA

TF= 11.70 CP=0.55 NTA= 0

RECESSION DATA

STRIG= -0.75 QRCSN= -0.20 RTIOR= 1.30

UNIT HYDROGRAPH 00 END-OF-PERIOD ORIGINATES, LAG= 11.65 HOURS, CP= 0.55 VOL= 1.00  
34. 129. 264. 423. 599. 787. 979. 1153. 1293. 1397.  
1404. 1490. 1555. 1609. 1673. 1737. 1801. 1865. 1929. 1993.  
022. 765. 711. 661. 614. 571. 531. 494. 459. 427.  
397. 369. 343. 319. 297. 276. 256. 238. 222. 206.  
192. 178. 166. 154. 143. 133. 124. 115. 107. 99.  
92. 80. 74. 69. 64. 60. 56. 52. 48. 44.  
45. 41. 39. 36. 33. 29. 27. 25. 23. 21.  
22. 20. 19. 17. 16. 15. 14. 13. 12. 11.

0

MC.DA HR.MN PERIOD RAIN EXCS LCSS COMP Q END-OF-PERIOD FLOW MC.DA HR.MN PERIOD RAIN EXCS LOSS COMP Q

SUM 4.40 1.54 2.86 58496.  
( 112.)( 39.)( 73.)( 1656.42)

# COMBINE HYDROGRAPHS

26 COMBINE 3 HYDROGRAPHS 2+7+8=8

ISTAQ ICCPP IECON ITAFE JPLT JFRT INAME ISTAGE IAUTO  
800 3 0 0 0 0 1 0 0

## HYDROGRAPH ROUTING

27 ROUTE THRU RESERVOIR AND OVER DAM AT EEL WEIR

ISTAQ ICCPP IECON ITAFE JPLT JFRT INAME ISTAGE IAUTO  
901 1 0 0 0 0 1 0 0

### ROUTING DATA

IFMP LSTR  
0 C

GLSS CLOSS AVG  
5.0 0.000 0.00

NSTPS NSTDL  
1 0

LAG AMSKK X  
0 0.000 0.000

TSK STORA ISFRAT  
0.000 -272. -1

STAGE	272.00	273.00	274.00	275.00	276.00	277.00	278.00	279.00	280.00
FLO.	0.00	2500.00	8000.00	15000.00	23000.00	32000.00	42300.00	53 00.00	64000.00
CAPACITY=	0.	18125.	40475.	67375.	99225.				
ELEVATION=	272.	274.	276.	278.	280.				

CREL SPWID CQBW EXPW ELEV CQWL CAREA EXPL  
272.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0

### DAM DATA

TOPEL CQWD EXFD DAMWID  
280.0 2.6 1.5 1.5

PEAK OUTFLOW IS 22091. AT TIME 60.00 HOURS

## SUB-AREA RUNOFF COMPUTATION

28 RUNOFF SUBAREA 9

## HYDROGRAPH DATA

INVDG	IUNG	TAREA
0	1	27.CO

NO	ISAME	LOCAL
0	1	0

LOSS DATA

	DLTKR	RTIOL	STRLK	RTIOK	STRTL	CNSTL	ALSMX	RTIOP
LROPT	0.00	1.00	0.00	1.00	-1.00	-69.00	0.00	0.00

CURVE NO = -69.CC WETNESS = -1.00 EFFECT CN = 69.CC

UNIT HYDROGRAPH DATA  
IF= 1C.20 CP=C.55 NTA= C

REFLECTION DATA

```
STRTOQ= -0.75  QRCSN= -0.20  RYIO4= 1.30
```

UNIT HYDROGRAPH 69 END-OF-FERIOD ORDINATES, LAG= 10.26 HOURS, CP= 0.55 VOL= 1.50

27.	101.	205.	328.	462.	603.	733.	837.	911.	953.
28.	910.	836.	770.	708.	651.	598.	550.	506.	465.
29.	593.	361.	332.	305.	281.	258.	237.	218.	201.
30.	170.	156.	143.	132.	121.	111.	102.	87.	81.
31.	73.	67.	62.	57.	52.	48.	44.	41.	37.
32.	32.	29.	27.	25.	23.	21.	19.	18.	16.
33.	14.	13.	12.	11.	10.	9.	8.	8.	8.

### END-OF-PERIOD FLOW

MU.DA	HR.MN	PERIOD	RAIN	EXCS	LOSS	COMP Q
		SUM	4.4C	1.54	2.86	33934.
		( 112.)	( 39.)	( 73.)	( 960.9C)	

[illegible]

## COMBINE HYDROGRAPHS

229 COMBINE 2 HYDROGRAPHS AT OGDENSBURG DAM R+9=9

ISTAQ	ICOMP	IECON	ITAPE	JPLY	JFRT	INAME	ISTAGE	IAUTO
950	2	0	0	0	0	1	0	0

[illegible]

## HYDROGRAPH ROUTING

30	ROUTE	THRU	RESERVICR	AND	OVER	OGDENSBURG	DAM
	ISTAQ	ICCPF	IECOM	ITAFE	JPLI	JFRT	INAME
	9CD	1	0	0	0	0	1
							ISTAGE
							IAUTO
							0

[illegible]

RUNOFF SUMMARY, AVERAGE FLOW IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)  
AREA IN SQUARE MILES (SQUARE KILOMETERS)

		PEAK	6-HOUR	24-HOUR	72-HOUR	AREA
HYDROGRAPH AT	100	6429.	6360.	5777.	3931.	341.00
ROUTED TO		( 162.04 )	( 180.09 )	( 163.56 )	( 111.31 )	( 883.16 )
	201	6257.	6210.	5693.	3914.	341.00
ROUTED TO		( 177.17 )	( 175.84 )	( 161.21 )	( 110.82 )	( 883.16 )
	201	6247.	6200.	5688.	3912.	341.00
HYDROGRAPH AT	200	9186.	8955.	7110.	3630.	218.00
ROUTED TO		( 260.12 )	( 253.59 )	( 201.32 )	( 102.79 )	( 564.61 )
	201	9131.	8914.	7094.	3628.	218.00
2-COMBINED		( 258.55 )	( 252.41 )	( 200.87 )	( 102.74 )	( 564.61 )
	200	11665.	11618.	10918.	7384.	559.00
HYDROGRAPH AT	300	9409.	9146.	6454.	2673.	144.00
ROUTED TO		( 260.45 )	( 258.98 )	( 182.76 )	( 81.36 )	( 372.96 )
	300	1444.	1444.	1435.	1338.	144.00
ROUTED TO		( 40.90 )	( 40.88 )	( 40.63 )	( 37.93 )	( 372.96 )
	400	1444.	1443.	1434.	1337.	144.00
HYDROGRAPH AT	400	3841.	3764.	3119.	1698.	119.00
2-COMBINED		( 108.77 )	( 106.58 )	( 86.33 )	( 48.07 )	( 338.21 )
	400	4855.	4810.	4240.	2904.	263.00
ROUTED TO		( 137.47 )	( 136.21 )	( 120.06 )	( 82.22 )	( 581.16 )
	601	4768.	4725.	4201.	2895.	263.00
HYDROGRAPH AT	500	7342.	7207.	6105.	3465.	258.00
ROUTED TO		( 207.91 )	( 204.08 )	( 172.87 )	( 98.11 )	( 668.21 )
	601	7282.	7166.	6387.	3463.	258.00
2-COMBINED		( 216.20 )	( 202.91 )	( 172.38 )	( 98.05 )	( 668.21 )
	601	12008.	11839.	10251.	6326.	521.00
ROUTED TO		( 346.03 )	( 335.23 )	( 290.29 )	( 179.14 )	( 1349.37 )
	600	11645.	11519.	10106.	6308.	521.00
HYDROGRAPH AT	600	6189.	6097.	5341.	3271.	258.00
2-COMBINED		( 175.27 )	( 172.66 )	( 151.23 )	( 92.61 )	( 668.21 )
	600	17643.	17456.	15334.	9518.	779.00
ROUTED TO		( 499.60 )	( 494.29 )	( 434.22 )	( 269.53 )	( 2017.59 )
	700	15246.	15145.	13954.	9344.	779.00
HYDROGRAPH AT	700	5969.	5838.	4849.	2650.	194.00
2-COMBINED		( 165.02 )	( 165.32 )	( 137.32 )	( 75.04 )	( 502.45 )
	700	18290.	18183.	16853.	11612.	973.00
ROUTED TO		( 517.91 )	( 514.88 )	( 477.23 )	( 328.80 )	( 2520.04 )
	801	18214.	18109.	16801.	11601.	973.00
HYDROGRAPH AT	800	1072.	1050.	1172.	770.	14.00
2-COMBINED		( 515.75 )	( 512.78 )	( 475.75 )	( 328.49 )	( 2520.04 )

3-COMBINED	800	17100	17100	17100	17100	17100	17100	17100	17100
	800	56.01)	54.37)	41.69)	20.39)	124.32)			
ROUTED TO	901	28691.	28546.	26869.	19469.	1580.00			
	901	812.44)	608.33)	760.66)	551.31)	4092.15)			
HYDROGRAPH AT	900	22091.	22037.	21291.	16962.	1580.00			
	900	625.54)	624.03)	602.89)	480.33)	4092.15)			
	900	1236.	1194.	883.	419.	27.00			
	900	35.01)	33.02)	24.99)	11.53)	69.93)			
2-COMBINED	900	22267.	22213.	21465.	17136.	1607.00			
	900	635.52)	629.01)	607.82)	485.24)	4162.08)			
ROUTED TO	900	22248.	22194.	21450.	17129.	1607.00			
	900	629.99)	628.48)	607.40)	485.33)	4162.08)			

# SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1 .....

ELEVATION STORAGE OUTFLOW	INITIAL VALUE 1490.00 0. 0.	SPILLWAY CREST 1490.00 C. C.	TOP OF DAM 1493.00 23393. 2828.	DURATION		TIME OF		TIME OF	
				MAXIMUM	OVER TOP	MAX OUTFLOW	FAILURE	MAX OUTFLOW	FAILURE
				STORAGE AC-FT	HOURS	CFS	HOURS	HOURS	HOURS
				1171C.	0.00	1444.	46.00	0.00	0.00

RATIO  
OF  
PMF  
3.00



# SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1 .....

ELEVATION	INITIAL VALUE	SPILLWAY CREST	TOP OF DAM	
STORAGE	272.00	272.00	280.00	
OUTFLOW	0.	C.	99225.	
	0.	C.	64000.	
RATIO	MAXIMUM	MAXIMUM	DURATION	TIME OF
OF	RESERVOIR	STORAGE	OVER TOP	MAX OUTFLOW
PMF	W.S.ELEV	AC-FT	HOURS	HOURS
0.00	275.89	39205.	0.00	60.00
				FAILURE
				HOURS
				0.00

PLAN 1 .....

ELEVATION  
STORAGE  
OUTFLOW

INITIAL VALUE
258.00
1450.
0.

SPILLWAY CREST  
258.00  
1450.  
00

TOP OF DAM  
265.00  
4175.  
26040.

10  
RATC

MAXIMUM  
RESERVUJIR

MAXIMUM  
DEPTH

MAXIMUM  
STORAGE

MAXIMUM  
OUTFLOW

**DURATION  
OVER TOP**

TIME OF  
MAX OUTFLOW

TIME CF  
FAILURE

APPENDIX D  
STABILITY ANALYSIS



# DESIGN BRIEF

 $\frac{1}{5}$ 

Ogdensburg Dam

DATE \_\_\_\_\_

7/22/80



SUBJECT

## Stability Analysis

PROJECT NO.

**DRAWN BY**

1. f. w.



$$\text{Weight Load} = (1.50) \left[ (1.5 \times 13) + \left( \frac{9+5}{2} \right) (10.5) + \left( \frac{1}{2} \times 2 \times 12 \right) \right] = 15.75 \text{ K/ft. of length}$$

$$M_o \text{ due to weight of beam} = (150) \left[ \left( \frac{19.5 \times 12}{12} \right) + (5 \times 10.5) \left( 8 + \frac{5}{2} \right) + \left( \frac{1}{2} \times 4 \times 10.5 \right) \left( 4 + \frac{2 \times 4}{3} \right) + (12) \left( 13 + \frac{2}{3} \right) \right] = 147.3 \text{ k}$$


Location of c.g. from top =  $\frac{147.3^{14}}{15.75^{14}} = 9.35' = \bar{x}$



PROJECT NAME Ogdensburg DATE \_\_\_\_\_  
 SUBJECT \_\_\_\_\_ PROJECT NO. \_\_\_\_\_  
 DRAWN BY \_\_\_\_\_

### Case I. Normal Operations (No Ice)

(i) Overturning



$M_a$  resisting overturning due to mass of dam,  $H_2O$  above upstream face =

$$= 147.3 \text{ k} + \left( \frac{1}{2} \times 2 \times 12 \times 0.0624 \text{ kcf} \right) \left( 13 + \frac{2 \times 2}{3} \right) = 158 \text{ k}$$

$M_a$  causing ovt due to lat.  $H_2O$  upstream, uplift =

$$= \left( \frac{1}{2} \times 1.75 \times 12 \right) \left( \frac{12}{3} \right) + (1.75 \times \frac{15}{2}) \left( \frac{2}{3} \times 15 \right) = 74.1 \text{ k}$$

$U = \text{uplift force} = 1.75 \times 15 = 5.63 \text{ k}$

FS against overturning =  $\frac{158 \text{ k}}{74.1 \text{ k}} = 2.13$

Position of Resultant measured from toe,  $d = \frac{\sum M_h}{\sum V}$

$$d = \frac{(158 - 74.1) \text{ k}}{W_{\text{dam}} - U + H_2O \text{ above upst. face}} = \frac{83.9 \text{ k}}{15.75 - 5.63 + 0.75} = \frac{83.9 \text{ k}}{10.88 \text{ k}} = 7.7' = 5.16 \text{ ft}$$

(ii) Sliding (using friction-shear method,  $T_{\text{conc-rock}} = 100 \text{ psi}$ ,  $\mu = 0.65$ )

$$\text{FS against Sliding} = \frac{(\mu)(\sum V) + T b l}{\text{lat. } H_2O \text{ upstream}} = \frac{(0.65)(10.88 \text{ k}) + (100 \text{ psi} \times 15' \times 1' \times 144 \frac{\text{in}^2}{\text{ft}^2})}{(\frac{1}{2} \times 1.75 \times 12')} = \frac{(7.1 + 216) \text{ k}}{4.5 \text{ k}} = 50 \pm$$

### Case II. Normal Operations, with Ice

(i) FS against overturning =  $\frac{158 \text{ k}}{74.1 + (1.5 \times 11)} = \frac{158}{156.6} = 1.01$   
 $d = 1.01 \text{ b}$

(ii) FS against sliding =  $\frac{223}{4.5 + 7.5} = 18.6$

[Comparison will be made of 10 k/ft ice load acts]



PROJECT NAME \_\_\_\_\_ DATE \_\_\_\_\_


SUBJECT \_\_\_\_\_ PROJECT NO. \_\_\_\_\_

DRAWN BY \_\_\_\_\_

Case III • Normal Operations (No Ice) plus seismic effects applicable to Zone 3

Zone 3 Seismic coef = 0.10 (horiz.)  
= 0.05 (vert.)locating c.g. from toe,  $\bar{y}$ 

$$\sum W\bar{y} = (15) \left[ (13 \times 1.5 \times \frac{10.5}{2}) + (\frac{1}{2} \times 4 \times 10.5) (15 + \frac{10.5}{2}) + (15 \times 10.5) (\frac{10.5}{2} + 1.5) + (\frac{1}{2} \times 2 \times 12) (\frac{12}{3}) \right] = 78.3^{12}$$



$$\bar{y} = \frac{78.3^{12}}{15.75} = 4.97'$$

(i) overturning

Additional overturning  $M_a$  due to seismic effects on mass of dam =

$$= (10 \times 15.75)(4.97') + (0.05 \times 15.75)(9.35') = 15.2^{12}$$

Additional overturning  $M_a$  due to dam-reservoir water interaction =

$$= (0.30)(1.67 \times 10 \times 0.0624 \times 12 \times 12 \times 12) = 2.2^{12}$$

$$FS \text{ against overturning} = \frac{158^{12}}{(74.1 + 15.2 + 2.2)} = \frac{158}{91.5} = \underline{1.73}$$

$$\text{Position of Resultant measured from toe, } d = \frac{158 - 91.5}{10.88 - (0.05 \times 15.75)} = \frac{66.5}{10.89} = 6.6' = 4.46'$$

(ii) Sliding

Additional lateral force due to dam-reservoir interaction =

$$= (0.7)(0.67 \times 10 \times 0.0624 \times 12 \times 12) = 0.44^{12}$$

$$FS \text{ against sliding} = \frac{223}{4.5^{12} + 0.44^{12} + 10(15.75)} = \frac{223}{6.5} = \underline{34 \pm}$$


**STETSON • DALE**BANKERS TRUST BUILDING  
UTICA • NEW YORK • 13501  
TEL 315-797-5800**DESIGN BRIEF**

4/5

PROJECT NAME \_\_\_\_\_ DATE \_\_\_\_\_

SUBJECT \_\_\_\_\_ PROJECT NO. \_\_\_\_\_

DRAWN BY \_\_\_\_\_

1/2 PMF

Add'l  $\frac{1}{2}$   $H_2O$  force  
 $= (.0624)ksf (270' - 258') (12') = 9.0k$   
 Add'l Moment  $= 9k (\frac{12'}{2}) = 53.9'k$

Add'l resistance - D/s  $H_2O$   
 Force  $= 4.5k + .087ksf (12') = 4.5 + 1.05 = 5.55k$   
 Moment  $= 4.5k (\frac{12'}{3}) + 1.05k (\frac{12'}{2}) = 24.3'k$

Overturning

$$F.S. = \frac{158'k + 24.3'k}{74.1'k + 53.9'k} = \frac{182.3}{128} = 1.42$$

$$d = \frac{\sum M}{\sum V} = \frac{182.3 - 128}{10.88} = 5.0' = 0.33b \text{ at edge of middle third}$$

Sliding

$$F.S. = \frac{5.55k + 5.55k}{4.5k + 9k} = 17 \pm$$



STETSON • DALE

BANKERS TRUST BUILDING  
UTICA • NEW YORK • 13501  
TEL 315-797-5800

## DESIGN BRIEF

5/5


PROJECT NAME \_\_\_\_\_ DATE \_\_\_\_\_

SUBJECT \_\_\_\_\_ PROJECT NO. \_\_\_\_\_

DRAWN BY \_\_\_\_\_

PMF

Headwater



Tailwater

Elev = 265

 $7'(.0624) = .437\frac{1}{2}'$ 

$$\begin{aligned} \text{Add'l } \frac{1}{2} \text{ H}_2\text{O force} &= (.0624 \text{ ksf})(6.77' - 2.58')(12') \\ &= 14.23\text{k} \end{aligned}$$

$$\begin{aligned} \text{Add'l moment} &= 14.23\text{k} \left( \frac{12'}{2} \right) = 85.4\text{k}' \end{aligned}$$

Add'l resistance due  
to  $\frac{1}{2}$  H<sub>2</sub>O

$$\begin{aligned} \text{force} &= 4.5\text{k} + 12'(.0624\text{k}') = 4.5 + 5.24 \\ &= 9.74\text{k} \end{aligned}$$

$$\text{moment} = 17.97 + 5.24\text{k}(6') = 49.4\text{k}'$$

Overturning


$$F.S. = \frac{158\text{k}' + 49.4\text{k}'}{74.1 + 85.4\text{k}' } = \frac{207.4}{159.5} = 1.3$$

$$d = \frac{\sum M}{\sum V} = \frac{207.4 - 159.5}{10.88} = \frac{47.9}{10.88} = 4.4' = 0.36$$

Sliding

$$F.S. = \frac{223 + 9.74}{4.5' + 14.23\text{k}} = \frac{232.7}{18.73} = 12\pm$$





SCALE: 1"=40'



STETSON-DALE

DATE

6-25-80

DRAWN

D.M.E.

JOB

2899

APP'D

TYPICAL  
SECTION

APPENDIX E  
REFERENCES

## APPENDIX E

### REFERENCES

1. Department of the Army, Office of the Chief of Engineers. National Program of Investigation of Dams; Appendix D: Recommended Guidelines for Safety Inspection of Dams, 1976
2. U.S. Nuclear Regulatory Commission: Design Basis Floods for Nuclear Power Plants, Regulating Guide 1.59, Revision 2, August 1977
3. Linsley and Franzini: Water Resources Engineering, Second Edition, McGraw-Hill (1972)
4. W. Viessman, Jr., J. Knapp, G. Lewis, 1977, 2nd Edition, Introduction to Hydrology
5. Ven Te Chow: Handbook of Applied Hydrology, McGraw-Hill, 1964
6. The Hydrologic Engineering Center: Computer Program 723-X6-L2010, HEC-1 Flood Hydrograph Package, User's Manual, Corps of Engineers, U.S. Army, 609 Second Street, Davis, California 95616, January 1973
7. The Hydrologic Engineering Center, Computer Program: Flood Hydrograph Package (HEC-1) Users Manual For Dam Safety
8. Soil Conservation Service (Engineering Division): Urban Hydrology for Small Watersheds, Technical Release No. 55, U.S. Department of Agriculture, January 1975
9. H.W. King, E.F. Brater: Handbook of Hydraulics, McGraw-Hill, 5th Edition, 1963
10. Ven Te Chow: Open Channel Hydraulics, McGraw-Hill, 1959
11. Bureau of Reclamation, United States Department of the Interior, Design of Small Dams: A Water Resources Technical Publication, Third Printing, 1965
12. J.T. Riedel, J.F. Appleby and R.W. Schloemer: Hydrometeorological Report No. 33, U.S. Department of Commerce, U.S. Department of Army, Corps of Engineers, Washington, D.C., April 1956. Available from Superintendent of Documents, U.S. Government Printing Office, Washington, D.C.
13. U.S. Weather Bureau, Rainfall-Frequency Atlas of the United States for Duration from 30 Minutes to 24 Hours and Return Periods from 1 to 100 years.
14. North Atlantic Regional Water Resources Study Coordinating Committee: Appendix C, Climate, Meteorology and Hydrology, February 1972

15. U.S. Department of the Interior, Geological Survey, Maximum Known Stages and Discharges of New York Streams Through 1973, by Irving R. Leonard and Bernard Dunn, 1976
16. The University of the State of New York - The State Education Department, State Museum and Science Service, Geological Survey: Geologic Map of New York, 1970
17. Y.W. Isachsen and W.G. McKendree, 1977, Preliminary Brittle Structures Map of New York, Adirondack Sheet, New York State Museum Map and Chart Series No. 31A
18. H. P. Cushing, 1916 Geology of the Vicinity of Ogdensburg, New York State Museum Bulletin 191.
19. W. T. Kirchgasser and G. Theokritoff, 1971, Precambrian and Lower Paleozoic Stratigraphy, Northwest St. Lawrence and North Jefferson Counties, New York: New York State Geological Association Guidebook, 43rd Annual Meeting, Potsdam, New York.