AD-A091 162 UNCLASSIFIED	GAI CON NATIONA AUG 80	SULTANTS INC L DAM INSPEC	MONRO TION PR	EVILLE Ogram.	PA STEEL	DAM (ND)	DACW3	NUMBER 1-80-C-	F/G 13/ PAET 0016 NL	13 C(U)	
AD- AD- AD-906**					ľ						
		R									
END MATT FRAMED A2-80 PTRC.					_						ME ST

TYEK MODON CREEK. TASHENGTON GOUNTE D 4 m nspection i e i k k k Prog ta ma 2 (NDI ÅD Å 0 9 1 1 6 be 68-63 200 N 10 PHASE I INSPECTION REAL PROPERTY 「日本はなかだして TS BEST QUILTY THE COPY FURMILSHED TO DDV ICHIFICART NURBER (M) Aug 80 PREPARED FOR DEPARTMENT OF THE ARMY Baltimore District, Corps of Hagineers TE COP Himore DACW 31-80 GAI CONSULTANTS, INC. 570 BRATTY ROAD MONROEVILLE, PENNSYLVANIA 1514 AUCUST 1980 生1100亿 421202 8011 08 128

DISCLAIMER NOTICE

THIS DOCUMENT IS BEST QUALITY PRACTICABLE. THE COPY FURNISHED TO DTIC CONTAINED A SIGNIFICANT NUMBER OF PAGES WHICH DO NOT REPRODUCE LEGIBLY.

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C., 20314. The purpose of a Phase I investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established guidelines, the spillway design flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonable possible storm runoff), or fractions thereof. The spillway design flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition, and the downstream damage potential.



.

PHASE I INSPECTION REPORT NATIONAL DAM INSPECTION PROGRAM

ABSTRACT

Bethlehem Mines Corporation

Steel Dam: NDI I.D. No. PA-00495

<u>Owner</u>:

1

<u>State Located</u>: Pennsylvania (PennDER I.D. No. 63-63)

County Located:

Stream: Center Branch of Pigeon Creek

Washington

Inspection Date: 22 July 1980

Inspection Team: GAI Consultants, Inc. 570 Beatty Road Monroeville, PA 15146

The visual inspection, operational history and hydrologic/ hydraulic analysis indicate that the facility is in good condition.

The size classification of the facility is small and its hazard classification is considered to be high. In accordance with the recommended guidelines, the Spillway Design Flood (SDF) for the facility ranges between the 1/2-PMF (Probable Maximum Flood) and the PMF. Due to the high potential for damage to downstream structures and possible loss of life, the SDF is considered to be the PMF. Results of the hydrologic and hydraulic analysis indicate the facility will pass and/or store approximately 51° percent of the PMF prior to embankment overtopping at the low top of dam. Thus, the spillway system is considered to be inadequate, but not seriously inadequate. Should the embankment crest be regraded to design elevation, the spillway would be capable of passing approximately 60 percent of the PMF prior to embankment overtopping.

It is recommended that the owner immediately:

a. Develop a formal emergency warning system to notify downstream residents should hazardous conditions develop. Included in the plan should be provisions for around-the-clock surveillance of the facility during periods of unusually heavy precipitation. b. Remove the trees adjacent to the right spillway sidewall and regrade the right abutment crest to conform to the design top of dam elevation.

1.18

c. Remove the regetation from within the spillway channel and fill the joints with appropriate expansion material.

d. Develop formal manuals of operation and maintenance to ensure the continued proper care of the facility.

Approved by: GAI Consultants, inc. Bernard M. Mihalcin, P.E. amou AMES W. FECK colonel, Corps of Engineers District Engineer



and an the order of the strategy of the second s

1

日本中

Date 15 Statistic Date 12 Sep 80

FERRER FREE FREE FREE FREE FREE FREE

Accession Ter WEIS STUEL D210 T13 0 спредске Juitine -50 0 Ry ... Distants .:/ Anası \sim surrended 20 Dit1

11111



iii



TABLE OF CONTENTS

Page

PREFACE
ABSTRACT
OVERVIEW PHOTOGRAPH
TABLE OF CONTENTS
SECTION 1 - GENERAL INFORMATION
1.0 Authority
1.1 Purpose
1.3 Pertinent Data
SECTION 2 - ENGINEERING DATA
2.1 Design
2.2 Construction Records
2.3 Operational Records
2.5 Evaluation
SECTION 3 - VISUAL INSPECTION
3.1 Observations
3.2 Evaluation
SECTION 4 - OPERATIONAL PROCEDURES
4.1 Normal Operating Procedure
4.2 Maintenance of Dam
4.4 Warning System
4.5 Evaluation 10
SECTION 5 - HYDROLOGIC/HYDRAULIC EVALUATION 11
5.1 Design Data
5.2 Experience Data
5.5 Visual Observations
5.5 Summary of Analysis
5.6 Spillway Adequacy
SECTION 6 - EVALUATION OF STRUCTURAL INTEGRITY 13
6.1 Visual Observations
6.2 Design and Construction Techniques 13
6.3 Past Performance
SECTION 7 $-$ ASSESSMENT AND DECOMMENDATIONS FOR
REMEDIAL MEASURES
7.1 Dam Assessment.
7.2 Recommendations/Remedial Measures 15

v

4

ì

TABLE OF CONTENTS

APPENDIX A - VISUAL INSPECTION CHECKLIST AND FIELD SKETCHES APPENDIX B - ENGINEERING DATA CHECKLIST APPENDIX C - PHOTOGRAPHS APPENDIX D - HYDROLOGY AND HYDRAULICS ANALYSES APPENDIX E - FIGURES APPENDIX F - GEOLOGY



vi



j\$

PHASE I INSPECTION REPORT NATIONAL DAM INSPECTION PROGRAM STEEL DAM (PIGEON CREEK RESERVOIR DAM) NDI# PA-00495, PennDER# 63-63

> SECTION I GENERAL INFORMATION

1.0 Authority.

The Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of inspection of dams throughout the United States.

1.1 Purpose.

11

5.4

. 1

The purpose is to determine if the dam constitutes a hazard to human life or property.

1.2 Description of Project.

a. <u>Dam and Appurtenances</u>. Steel Dam is an earth embankment approximately 15 feet high and 485 feet long (including spillway). The facility is provided with a centrally located concrete spillway with an ogee shaped weir 100 feet long. The spillway is flanked on both sides by earth abutments. A concrete corewall within both abutments, is founded on rock and extends to within 1-foot of the design crest of the dam. A reinforced concrete control tower is located along the upstream slope to the left of the spillway. Outlet conduits consist of a 10-inch diameter supply pipe and a 24-inch diameter blowoff pipe both encased in concrete and valved at their inlet ends.

b. Location. Steel Dam is located on the center branch of Pigeon Creek in Somerset Township, Washington County, Pennsylvania about three miles northwest of Ellsworth, Pennsylvania. The dam, reservoir and watershed are contained within the Hackett and Ellsworth, Pennsylvania 7.5-minute U.S.G.S. topographic quadrangles (see Figure 1, Appendix E). The coordinates of the dam are N 40° 07.7' and W 80° 03.9'.

c. <u>Size Classification</u>. Small (15 feet high, 189 acre-feet storage capacity at top of dam).

- d. Hazard Classification. High (See Section 3.1.e).
- e. <u>Ownership</u>. Bethlehem Mines Corporation Ellsworth Division P.O. Box 143 Eighty Four, PA 15330 D. A. Sparks - Manager
 - c/o D. Patterson

f. Purpose. Water Supply.

g. <u>Historical Data</u>. Correspondence in PennDER files indicate that Steel Dam was designed in 1950-1951 and was constructed between July 1952 and November 1953. Neither the designer or contractor is specifically named in available correspondence; however, Morris Knowles, Inc., consulting engineers from Pittsburgh, Pennsylvania, is mentioned.

Design review by PennDER predecessors resulted in many design change recommendations, all of which were incorporated into the final design. Construction progress reports, inspection memoranda and photographs indicate that contract compliance was achieved and that all structural elements were founded on competent rock. One of the construction photographs indicates that the downstream slope was extended to its present configuration during the original construction.

No significant modifications have been made to the facility since construction and it has reportedly functioned adequately.

1.3 Pertinent Data.

12

1.1

a. Drainage Area (square miles). 4.1

b. Discharge at Dam Site.

Discharge Capacity of Outlet Conduit - Discharge curves are not available.

Discharge Capacity of Spillway at Maximum Pool ≅ 3590 cfs (See Appendix D, Sheet 6).

c. <u>Elevation (feet above mean sea level)</u>. The following elevations were obtained from available drawings and through field measurements that were based on the elevation of the service spillway crest at 1002.0 feet (see Appendix D, Sheet 1).

	Design Top of Dam Low Top of Dam Maximum Design Pool Maximum Pool of Record Normal Pool Spillway Crest Upstream Inlet Invert Downstream Outlet Invert Streambed at Centerline of Dam Maximum Tailwater	1007.0 1006.5 (field). 1007.0 Not known. 1002.0 1002.0 994.0 991.5 992.5 Not known.
d.	Reservoir Length (feet).	
	Top of Dam Normal Dam	3200 2000
e.	Storage (acre-feet).	
	Top of Dam Normal Pool	189 89
f.	Reservoir Surface (acres).	
	Top of Dam Normal Pool	29 17
g.	Dam.	
	Туре	Earth.
	Length	385 feet (ex- cluding spill- way).
	Height	15 feet (field measured; low top of dam to invert of blowoff out- let).
	Top Width	150 feet (mini- mum).
	Upstream Slope	3H:1V
	Downstream Slope	N/A (see "Gen- eral Plan - Field Inspec- tion Notes," Appendix A).

.1

1

3

e!

٠. **ب**

Ż

Zoning Impervious Core Cutoff Grout Curtain Diversion Canal and h. Regulating Tunnels. i. Spillway. Type Crest Elevation Crest Length j. Outlet Conduit. Type

Length

Closure and Regulating Facilities

4

Homogenous earth.

Concrete corewall extends from rock to l-foot below crest. Corewall extends to sound rock.

None.

None.

Uncontrolled, rectangular concrete channel with an ogee shaped weir.

1002.0 feet.

100.0 feet.

24-inch diameter CIP encased in concrete.

180 feet (estimated; inlet to blowoff outlet).

Flow through conduit is controlled by a 24-inch diameter sluice gate located at the inlet

within the concrete control tower.

•

Steel framed, wood plank foot bridge from crest (see Photograph 7).

5

Access

12

1

÷

3

SECTION 2 ENGINEERING DATA

2.1 Design.

j\$

a. <u>Design Data Availability and Sources</u>. No formal design reports are available for any aspect of the facility. A drawing from the owner (see Figure 6, Appendix E) contains a stability evaluation of the gravity type spillway structure. Design drawings are available from the owner and PennDER files.

b. Design Features.

1. Embankment. The original design features of the embankment are shown on Figures 2 through 6. As indicated, the embankment design consists of a homogeneous earthfill with a central concrete corewall. Correspondence and construction photographs indicate the corewall was extended into competent rock. The upstream slope is covered with 12 inches of grouted rock and the slope angle was set The design called for the crest width to be 10 at 3H:1V. feet and the downstream slope to be set at 2-1/2H:1V. Field observations revealed the upstream slope was constructed as per design. The downstream face, however, was apparently covered with excess material and now slopes very gently downstream making it hardly discernible from the embankment crest.

2. Appurtenant Structures.

a) <u>Spillway</u>. Details of the spillway design are shown on Figures 3 and 4. As indicated, the spillway design consists of an ogee shaped gravity section, a stilling basin and a reinforced concrete, trapezoidal shaped discharge channel. The gravity section and wall foundations are seated on rock. The concrete corewalls join the gravity section to provide a continuous seepage barrier along the dam centerline.

b) <u>Outlet Works</u>. The outlet works is shown in detail on Figures 3 and 5. As indicated, it consists of a 10-inch diameter supply pipe and a 24-inch diameter blowoff pipe, both encased in concrete and controlled by slide gates within a control tower situated near the upstream dam toe. The gates are operated by handwheels from atop the control tower which is accessed by a foot bridge from the embankment crest.

c. <u>Specific Design Data and Criteria</u>. Figure 6 shows a detailed spillway analysis for five reservoir conditions.

Results of the analysis (also shown on the figure) indicate that the design configuration is acceptable. Specifications for concrete mixes and fill placement are also presented in the notes shown on Figures 3 and 5.

2.2 Construction Records.

Bi-weekly construction progress reports are available from PennDER files in addition to seven construction photographs that confirm pertinent construction details.

2.3 Operational Records.

No formal records of operation are available for the facility.

2.4 Other Investigations.

No records of any formal investigations other than one state inspection report are available.

2.5 Evaluation.

.1

The available data in the form of design drawings, construction progress reports and dated construction photographs are considered sufficient to make a reasonable Phase I assessment of the facility.

SECTION 3 VISUAL INSPECTION

3.1 Observations.

1

a. <u>General</u>. The general appearance of the facility suggests that it is in good condition.

b. <u>Embankment</u>. The visual inspection indicates that the embankment is in good condition and is generally well maintained with few exceptions. It was noted that the configuration of the crest and downstream slope were substantially modified, probably during construction. The crest was extended and the downstream slope virtually eliminated such that the overall appearance of the facility is that of an incised impoundment.

Deficiencies that should be corrected include: sizeable tree growth adjacent to the right spillway wingwall and noticeable crest settlement along the right abutment section.

c. Appurtenant Structures.

1. <u>Spillway</u>. The overall condition of the spillway is good. No significant cracking or concrete deterioration was observed. Moderate scaling of the flow surface is apparent especially near the downstream end of the spillway. An excessive amount of vegetation has rooted itself along the expansion joints in the spillway floor (see Photographs 3 and 4). The vegetation and supporting soil should be removed and the joints filled with appropriate expansion material.

2. <u>Outlet Works</u>. The outlet works structures and mechanisms all appear to be in good condition (see Photographs 7 and 8). No significant cracking or deterioration of the concrete elements was observed. Metal parts were adequately painted and the access bridge was in good condition.

d. <u>Reservoir Area</u>. The reservoir impounded by Steel Dam is surrounded by gentle to moderate slopes that are primarily wooded. No slope distress or significant sedimentation was observed.

e. <u>Downstream Channel</u>. The spillway discharges into the center branch of Pigeon Creek which is contained in a gently sloped, relatively wide valley. At approximately two miles downstream of the dam the center branch merges with

the south branch of Pigeon Creek. Other than the Conrail track that parallels the stream, no inhabitable structures are located within the reach from the dam to this confluence. At approximately 2,000 feet further downstream from the confluence, the combined stream flow enters the Ellsworth Reservoir, an industrial and municipal water supply impoundment. Failure of Steel Dam would probably cause overtopping and failure of the downstream dam and possibly result in loss of life within the several commercial structures adjacent to the reservoir. Consequently, the hazard classification is considered to be high.

3.2 Evaluation.

.1

The overall condition of the facility is considered to be good. The dam and its appurtenances are reasonably well maintained and the as-built configuration of the embankment provides more than adequate stability. Deficiencies which should be corrected include: overgrowth adjacent the right spillway wingwall near the embankment crest; a low area along the dam crest to the right of the spillway; and excessive vegetation rooted within the expansion joints of the spillway floor.

SECTION 4 OPERATIONAL PROCEDURES

4.1 Normal Operating Procedure.

The facility is self-regulating with excess inflow automatically discharged through the spillway. Under normal operating conditions the blowoff line is closed and the intake line opened within the intake tower. Valve mechanisms within the tower were not operated in the presence of the inspection team and the owner's representative did not know when they were last operated. There is no formal operations manual associated with the facility.

4.2 Maintenance of Dam.

The facility has been maintained on an unscheduled basis and there are no formal records or maintenance manual available. The left abutment section is reasonably well maintained apparently due to its easy access and use as a mine rescue practice area. The right abutment, which is not readily accessible, has become overgrown with brush and trees. The crest level of the right abutment is also noticeably low, particularly adjacent to the right spillway wingwall.

4.3 Maintenance of Operating Facilities.

The access bridge and operating mechanisms appear to be well maintained although the operability of the valve mechanism could not be confirmed during the inspection. No formal maintenance manual is available.

4.4 Warning System.

.1

There is no formal warning system associated with the facility; however, the owner maintains communications with the downstream water treatment facility.

4.5 Evaluation.

No formal manuals of maintenance and operation are available, but, are recommended to ensure the continued proper care of the facility. Included in these manuals should be a formal emergency warning system for the notification of downstream inhabitants in the event hazardous conditions develop.

SECTION 5 HYDROLOGIC/HYDRAULIC EVALUATION

5.1 Design Data.

No formal design reports or calculations are available. Correspondence contained in PennDER files indicate the spillway was sized to accommodate a storm runoff of 1,000 cubic feet per second per square mile of watershed.

5.2 Experience Data.

No specific records are available for this facility.

5.3 Visual Observations.

On the date of the inspection, no conditions were observed that would indicate that the spillway structure would not perform satisfactorily during a flood event, within the limits of its design capacity. Discharge through the spillway would be limited, however, by the low area along the right abutment crest.

5.4 Method of Analysis.

12

The facility has been analyzed in accordance with the procedures and guidelines established by the U.S. Army, Corps of Engineers, Baltimore District, for Phase I hydrologic and hydraulic evaluations. The analysis has been performed utilizing a modified version of the HEC-1 program developed by the U.S. Army, Corps of Engineers, Hydrologic Engineering Center, Davis, California. Analytical capabilities of the program are briefly outlined in the preface contained in Appendix D.

5.5 Summary of Analysis.

a. <u>Spillway Design Flood (SDF)</u>. In accordance with procedures and guidelines contained in the National Guidelines for Safety Inspection of Dams for Phase I Investigations, the Spillway Design Flood (SDF) for Steel Dam ranges between the 1/2-PMF and the PMF. This classification is based on the relative size of the dam (small), and the potential hazard of dam failure to downstream developments (high). Due to its high potential for damage to downstream structures and possible loss of life, the SDF for this facility is considered to be the PMF.

b. <u>Results of Analysis</u>. Steel Dam was evaluated under normal operating conditions. That is, the reservoir was initially at its normal pool or spillway elevation of 1002.0 feet with the spillway weir discharging freely. The outlet conduit was assumed to be non-functional for the purpose of analysis, since the flow capacity of the conduit is not such that it would significantly increase the total discharge capabilities of the facility. The spillway consists of a concrete, trapezoidal, chute channel with discharges controlled by a concrete, ogee shaped weir. All pertinent engineering calculations relative to the evaluation of this facility are provided in Appendix D.

Overtopping analysis (using the Modified HEC-1 Computer Program) indicated that the discharge/storage capacity of Steel Dam can accommodate only about 51 percent of the PMF (SDF) prior to embankment overtopping. The peak PMF inflow of approximately 7075 cfs was slightly attenuated by the discharge/storage capability of the dam, as the resulting PMF peak outflow was about 7055 cfs (Appendix D, Summary Input/Output Sheets, Sheet C). Under PMF conditions, the embankment would be overtopped for approximately 6.5 hours with a maximum depth of inundation of about 1.9 feet above the low top of dam (Summary Input/Output Sheets, Sheet C). It is also noted that if the embankment crest was regraded to design elevation, the spillway would be capable of passing approximately 60 percent of the PMF prior to embankment overtopping.

5.6 Spillway Adequacy.

11

Although Steel Dam cannot accommodate its SDF (the PMF) without overtopping, the possible downstream consequences of embankment failure due to overtopping were not evaluated. Since the facility can safely pass a flood of at least 1/2-PMF magnitude, breaching analysis was not performed in accordance with Corps directive ETL-1110-2-234. Thus, as Steel Dam cannot accommodate a PMF-size flood, its spillway is considered to be inadequate, but not seriously inadequate.

SECTION 6 EVALUATION OF STRUCTURAL INTEGRITY

6.1 Visual Observations.

a. <u>Embankment</u>. Based on visual observations, the embankment is in good condition. The grouted rock riprap provides adequate upstream slope protection. Modifications (probably during construction) have resulted in a downstream configuration that virtually precludes embankment instability. The right abutment section has apparently settled with the crest being lower than the right spillway wingwall. Overtopping would therefore be concentrated over the right abutment and could cause serious erosion along the spillway. Several large trees are also located on the right abutment adjacent to the spillway wingwall. The root systems and/or toppling of these trees could eventually cause structural damage to the spillway components if not removed.

b. Appurtenant Structures.

1. <u>Spillway</u>. The spillway appears to be structurally well designed and currently in good condition. An unusual amount of vegetation appears to be rooted along the floor slab expansion joints providing some obstruction to flow. The vegetation should be removed and the joints filled with appropriate expansion material.

2. <u>Outlet Works</u>. The outlet structures and mechanisms appear to be in good condition. Routine maintenance is recommended to ensure operability of the slide gates.

6.2 Design and Construction Techniques.

Limited data indicate that the design and construction were performed in accordance with generally accepted practices.

6.3 Past Performance.

.1

No data or other evidence is available that would indicate the facility has not performed satisfactorily since its construction.

6.4 Seismic Stability.

4

i

The dam is located within Seismic Zone No. 1 and is subject to minor earthquake induced dynamic forces. It is believed that the static stability of the structure is sufficient to withstand such forces; however, no calculations and/or investigations were performed to confirm this belief.



SECTION 7 ASSESSMENT AND RECOMMENDATIONS FOR REMEDIAL MEASURES

7.1 Dam Assessment.

12

a. <u>Safety</u>. The visual inspection suggests that the facility is in good condition.

The size classification of the facility is small and its hazard classification is considered to be high. In accordance with the recommended guidelines, the Spillway Design Flood (SDF) for the facility ranges between the 1/2-PMF (Probable Maximum Flood) and the PMF. Due to the high potential for significant downstream economic damage and possible loss of life that would be associated with an embankment breach, the SDF for the facility is considered to be the PMF. Results of the hydrologic and hydraulic analysis indicate the facility will pass approximately 51 percent of the PMF prior to overtopping the right abutment section at low top of dam. Thus, the spillway system is considered inadequate, but not seriously inadequate. Should the embankment crest be regraded to design elevation, the spillway would be capable of passing approximately 60 percent of the PMF prior to embankment overtopping.

b. <u>Adequacy of Information</u>. The available data are considered sufficient to make a reasonable Phase I evaluation of the facility.

c. <u>Urgency</u>. The recommendations listed below should be implemented immediately.

d. <u>Necessity for Additional Investigations</u>. No additional investigations are considered necessary at this time.

7.2 Recommendations/Remedial Measures.

It is recommended that the owner immediately:

a. Develop a formal emergency warning system to notify downstream residents should hazardous conditons develop. Included in the plan should be provisions for around-the-clock surveillance of the facility during periods of unusually heavy precipitation.

b. Remove the trees adjacent to the right spillway sidewall and regrade the right abutment crest to conform to the design top of dam elevation.

c. Remove the vegetation from within the spillway channel and fill the joints with appropriate expansion material.

d. Develop formal manuals of operation and maintenance to ensure the continued proper care of the facility.



19:00

16

.1

1., 1'

APPENDIX A

VISUAL INSPECTION CHECKLIST AND FIELD SKETCHES

10:30 AM HAZARD CATEGORY High 8 COUNTY Washington OTHERS TEMPERATURE ______ M.S.L. M.S.L. **OWNER REPRESENTATIVES** STATE Pennsylvania PENNDER # ____63-63 CHECK LIST VISUAL INSPECTION PHASE 1 WEATHER Overcast SIZE Small None at site. 00495 DATE(S) INSPECTION 22 July 1980 TAILWATER AT TIME OF INSPECTION. RECORDED BY B. M. Mihalcin NDI # PA -INSPECTION PERSONNEL NAME OF DAM Steel Dam Earth B. M. Mihalcin Spaeder D. L. Bonk **TYPE OF DAM** D. J.

.1

1

ي.

4

ż

.

ţ

PAGE 1 OF 8

EMBANKMENT

12

١,

) (1

1

;

ITEM	OBSERVATIONS/REMARKS/RECOMMENDATIONS NDI# PA · 00495
SURFACE CRACKS	None observed.
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	None observed.
SLOUGHING OR ERO- SION OF EMBANK- MENT AND ABUTMENT SLOPES	None observed.
VERTICAL AND HORI- ZONTAL ALIGNMENT OF THE CREST	<pre>Vertical - low area (0.8 feet below top of dam) adjacent spillway right wingwall (see "Profile of Dam Crest," Appendix A). Horizontal - Good.</pre>
RIPRAP FAILURES	None observed. Riprap consists of grouted rock covering the entire upstream face.
JUNCTION OF EMBANK- MENT AND ABUT- MENT, SPILLWAY AND DAM	Good condition.
	DAGE 2 OF R

٩

EMBANKMENT

.

1

:

1

1

3

3 1 .

ITEM	OBSERVATIONS/REMARKS/RECOMMENDATIONS NDI# PA · 00495
DAMP AREAS IRREGULAR VEGETA- TION (LUSH OR DEAD PLANTS)	No damp areas observed. Right abutment is overgrown with high brush and large trees probably because it is not readily accessible. Left abutment is well kept. Large trees are in evidence that are not detrimental to the facility.
ANY NOTICEABLE SEEPAGE	None observed.
STAFF GAGE AND RECORDER	Staff gage attached to corner of control tower - no reference numbers on it.
DRAINS	12-inch diameter terra cotta drain observed discharging (= 1 gpm) through spillway left wingwall about midway along the spillwav discharge channel downstream of the spillwav crest.
	PAGE 3.0

₹,

こうちょうかんできょう しょうちょうちょう しょうちょう ちょうしょう しょうしょう ちょうちょう ちょうちょう ちょうしょう しょうしょう ひょうちょうちょう しょうちょう ちょうちょう

1

Į

OUTLET WORKS

.1

.

.

ł

ź

3 1 .

ITEM	OBSERVATIONS/REMARKS/RECOMMENDATIONS NDI# PA · 00495
INTAKE STRUCTURE	Concrete control tower riser in excellent condition. No evidence of concrete deterioration.
OUTLET CONDUIT (CRACKING AND SPALLING OF CON- CRETE SURFACES)	24-inch diameter cast iron pipe. Partially submerged.
OUTLET STRUCTURE	Concrete outlet headwall in good condition.
OUTLET CHANNEL	Discharges into stream below spillway.
GATE(S) AND OPERA- TIONAL EQUIPMENT	Painted and apparently well maintained. Not operated in the presence of the inspection team.
	PAGE 4 OF 8

 4 -

1

.

ì

••

EMERGENCY SPILLWAY

÷

J\$

۱. ۱

1

,

;

ŧ

. <u>-</u>

2

ITEM	OBSERVATIONS/REMARKS/RECOMMENDATIONS NDI# PA · 00495
TYPE AND CONDITION	Uncontrolled, rectangular, concrete channel with an ogee shaped weir in good condition. Beyond weir the channel is trapezoidal in cross section.
APPROACH CHANNEL	None .
SPILLWAY CHANNEL AND SIDEWALLS	Minor to moderate scaling apparent across the channel bottom. Considerable vegetation apparently rooted in expansion joints. Should remove and fill joints with expansion material. Sidewalls are in excellent condition.
STILLING BASIN PLUNGE POOL	100-foot by 10-foot by 5-foot stilling basin located at base of weir.
DISCHARGE CHANNEL	Unlined, trapezoidal shaped earth channel - natural stream.
BRIDGE AND PIERS EMERGENCY GATES	None.
	PAGE 5 OF 8

e;

4

1

· • 1

.

SERVICE SPILLWAY

;

:

;

;1

el el

2

5

.

21.

ITEM	OBSERVATIONS/REMARKS/RECOMMENDATIONS NDI# PA · 00495
TYPE AND CONDITION	N/A
APPROACH CHANNEL	N/A
OUTLET STRUCTURE	N/A
DISCHARGE CHANNEL	N/A
	PAGE

* :

• •

,

INSTRUMENTATION

1

. . .

i t

;‡

,

-5

> I ŧ ł

\$

ł

4 ;

ITEM	OBSERVATIONS/REMARKS/RECOMMENDATIONS NDI# PA · 00495
MONUMENTATION SURVEYS	None observed.
OBSERVATION WELLS	None observed.
WEIRS	Flume and automatic recording device located on a discharge line adjacent to the blowoff - not associated with embankment.
PIEZOMETERS	None observed.
OTHERS	None observed.
	PAGE 7 OF 8

高い

1. 1.

4

٠

•• • **RESERVOIR AREA AND DOWNSTREAM CHANNEL**

•

;

;

۽ ڊ

. 5

•

1 .

;

ITEM	OBSERVATIONS/REMARKS/RECOMMENDATIONS NDI# PA · 00495
SLOPES: RESERVOIR	Right abutment - steep and heavily wooded. Left abutment - contains mining and railroad facilities.
SEDIMENTATION	None observed. Reservoir is brown in color which is indicative of a high sediment content. May be the result of heavy rainfall (= 3-3/4") the night prior to inspection.
DOWNSTREAM CHAN- NEL (OBSTRUCTIONS, DEBRIS, ETC.)	Downstream channel is a natural stream located in a relatively wide, gently to moderately sloped valley. Stream merges with the south branch of Pigeon Creek = 2 miles from dam and enters Ellsworth Reservoir = 2000 feet further downstream.
SLOPES: CHANNEL VALLEY	Channel slope is gentle to moderate. Valley slope is moderate.
APPROXIMATE NUMBER OF HOMES AND POPULATION	No houses located upstream of confluence with the south branch of Pigeon Creek. Stream enters Ellsworth Reservoir about 2000 feet downstream of confluence. Several industrial/commercial structures are located around the lower reservoir that could be damaged by a failure of Steel Dam and subsequent overtopping of the downstream reservoir. High potential for damage and loss of many lives.

Č.

5

PAGE 8 OF 8

t

•••



									••••	1	۲	
										u J	3	
											4 : .	
		· · · · · · · · · · · · · · · · · · ·				2					*	•
						== 2					4	• •
						H				•		
						∝ ≪					2	
						\	• •	-			₩ ₩	
						1	<u>ş</u>	2		5	¥.	
							2	ข		5	Ĩ	
		<u></u>						1	· · · · · · · · · · · · · · · · · · ·	<u>u</u>		
							5	÷.		\$		
						(3			2		
		1					Ś	Ş				
					a	<u>n</u>	- 1				 	
					ð	8		4				
					2							
	5				31	<u>L</u>						
	्भ	÷				U						
₹		Щ.							· · · · · · · · · · · · · · · · · · ·		· · · · · · · · · · · · · · · · · · ·	
\square	2	<u>iz</u>								· · · · · · · · · · · · · · · · · · ·		<u> </u>
	Δ.	ภี					·····			•		<u>.</u>
	5	.									1 - E	
E E	щ.	F										
11	Ĥ	₹										· · · · · ·
	: <u>5</u> ::	<u>.</u>									<u>. </u>	: :
	Ŭ	H				1				4		
<u> </u>						1						
					/ /					· · · · · · · · · · · · · · · · · · ·		
				1	/					•		
		1			/							
				<u>F</u>	1				• • • • • • • • • • • • • • • • • • •			
				ų r								
				5/						1		
			ц	le l								
												· · · · · · · · · · · · · · · · · · ·
				1	h	2	8	}				•
							<u> </u>					
						· · · · · · · · · · · · · · · · · · ·					<u> </u>	
										· · · · · · · · · · · · · · · · · · ·		
								• • • • • • • • • • • • • • • • • • •				<u> </u>
··· ····		!		•		<u>.</u>		· · · · · · · · · · · ·				
			1	*****		••••••••••••••••••••••••••••••••••••••	1	••••••••••••••••••••••••••••••••••••••	1	:	1	1 1

.*

.
APPENDIX B

e'

ENGINEERING DATA CHECKLIST

.1



CHECK LIST ENGINEERING DATA PHASE I

.:

I

ź

4

1 ŧ , Steel Dam NAME OF DAM

ITEM	REMARKS NDI# PA · 00495
PERSONS INTERVIEWED AND TITLE	James Loveland - Environmental Engineer
REGIONAL VICINITY MAP	See Appendix E, Figure 1 (U.S.G.S. 7.5 minute topographic quadrangles, Hackett and Ellsworth, PA).
CCNSTRUCTION HISTORY	Details available from PennDER files. Designed in 1950-51. Morris Knowles, Inc., mentioned in correspondence. Constructed July 1952 through November 1953. Contractor unknown.
AVAILABLE DRAWINGS	Four prints from initial design available from PennDER files. Owner has complete set of reproducible drawings of final design at office in Eighty-four, Pennsylvania.
TYPICAL DAM SECTIONS	See Appendix E, Figure 3.
OUTLETS: PLAN DETAILS DISCHARGE RATINGS	See Appendix E, Figures 2, 3 and 5.

PAGE 1 OF 5

۹. -

ł .

a series and a series of the s

- Charles and a second second

. .

CHECK LIST ENGINEERING DATA PHASE I (CONTINUED)

.1

• **3**

ŀ

• ţ

\$

4

		A 00495
IIEM		
SPILLWAY: PLAN SECTION DETAILS	See Appendix E, Figures 2, 3, 4 and 6.	
OPERATING EQUIP. MENT PLANS AND DETAILS	See Appendix E, Figures 3 and 5.	
DESIGN REPORTS	None available.	
GEOLOGY REPORTS	None available.	
DESIGN COMPUTATIONS: HYDROLOGY AND HYDRAULICS STABILITY ANALYSES SEEPAGE ANALYSES	See Appendix E, Figure 6 for analysis of gravity spillway secti	ion.
MATERIAL INVESTIGATIONS: BORING RECORDS LABORATORY TESTING FIELD TESTING	None available.	
		DAGE 2 OF 5

~~ . •.

PAGE 2 0F 5

...

PAGE 3 OF 5 00495 NDI# PA -Downstream slope modified, probably during construction. CHECK LIST ENGINEERING DATA PHASE I (CONTINUED) Probably from within reservoir. REMARKS None in last four years. Not known. None. None. POST CONSTRUCTION ENGINEERING STUDIES AND REPORTS MONITORING SYSTEMS POST CONSTRUCTION HIGH POOL RECORDS BORROW SOURCES MODIFICATIONS DAM SURVEYS ITEM

.!

.

jal V

;

4

1

.

3

(CONTINUED)	REMARKS NDI# PA· 0049	None.	None available.	None available.	Self-regulating. Supply chamber gate apparently always open and flow controlled in treatment facility.	Owner has communication with downstream water treatment facility at Ellsworth Reservoir. No formal warning system in effect.	
	ITEM	PRIOR ACCIDENTS O FAILURES	MAINTENANCE: RECORDS MANUAL	OPERATION: RECORDS MANUAL	OPERATIONAL PROCEDURES	WARNING SYSTEM AND/OR COMMUNICATION FACILITIES	MISCELLANEOUS

~

CHECK LIST ENGINEERING DATA PHASE I

;

4

PAGE 4 OF 5

GAI CONSULTANTS. INC.

CHECK LIST HYDROLOGIC AND HYDRAULIC ENGINEERING DATA

NDIID # ______ PA-00495 PENNDER ID # _ 63-63

ELEVATION TOP NORMAL POOL: 1002.0 STORAGE CAPACITY: 89 acre-feet.

ELEVATION TOP FLOOD CONTROL POOL: ______ STORAGE CAPACITY: ______

ELEVATION MAXIMUM DESIGN POOL: 1007.0 STORAGE CAPACITY: _____

ELEVATION TOP DAM: 1006.5 STORAGE CAPACITY: 189 acre-feet.

SPILLWAY DATA

CREST ELEVATION: 1002.0 feet.

TYPE: Uncontrolled, rectangular, concrete channel with ogee shaped weir.

CRESTLENGTH: 100.0 feet.

CHANNELLENGTH: 150 feet.

SPILLOVER LOCATION: Near center of dam.

NUMBER AND TYPE OF GATES: None.

OUTLET WORKS

.!

TYPE: 10-inch diameter CIP supply; 24-inch diameter CIP blowoff.

LOCATION: Left of spillway.

ENTRANCE INVERTS: Blowoff - 994.0 feet.

EXITINVERTS: Blowoff - 991.5 feet.

EMERGENCY DRAWDOWN FACILITIES: 24-inch diameter blowoff controlled by a 24-inch diameter sluice gate.

HYDROMETEOROLOGICAL GAGES

TYPE: _None.

LOCATION: ____

RECORDS: _____

MAXIMUM NON-DAMAGING DISCHARGE: Not known.

PAGE 5 OF 5

APPENDIX C PHOTOGRAPHS

.:



Overview of the embankment and reservoir from atop a building located along the left abutment hillside. PHOTOGRAPH 1

ļ

.:

ł

ų,

;

1 1

View of the upstream embankment face to the right of the spillway. PHOTOGRAPH 2

View, looking upstream, of the spillway weir. PHOTOGRAPH 3

۰,

View of the spillway channel looking downstream. PHOTOGRAPH 4 ▲ 泉 ··· ::

and a local section of the section o



View of the 12-inch diameter terra cotta drain observed discharging (\approx 1 gpm) through the spillway left wingwall. PHOTOGRAPH 5

.

:

j,

4

ź

ł

View of a flume and automatic recording device located just downtream of the blowoff outlet. PHOTOGRAPH 6

View of the control tower as seen from the upstream face of the left abutment. PHOTOGRAPH 7

View of the outlet end of the blowoff conduit.

PHOTOGRAPH 8



APPENDIX D

HYDROLOGY AND HYDRAULICS ANALYSES

1

ţ

PREFACE

The modified HEC-1 program is capable of performing two basic types of hydrologic analyses: 1) the evaluation of the overtopping potential of the dam; and 2) the estimation of the downstream hydrologic-hydraulic consequences resulting from assumed structural failures of the dam. Briefly, the computational procedures typically used in the dam overtopping analysis are as follows:

a. Development of an inflow hydrograph(s) to the reservoir.

b. Routing of the inflow hydrograph(s) through the reservoir to determine if the event(s) analyzed would over-top the dam.

c. Routing of the outflow hydrograph(s) from the reservoir to desired downstream locations. The results provide the peak discharge(s), time(s) of the peak discharge(s), and the maximum stage(s) of each routed hydrograph at the downstream end of each reach.

The evaluation of the hydrologic-hydraulic consequences resulting from an assumed structural failure (breach) of the dam is typically performed as shown below.

a. Development of an inflow hydrograph(s) to the reservoir.

b. Routing of the inflow hydrograph(s) through the reservoir.

1

c. Development of a failure hydrograph(s) based on specified breach criteria and normal reservoir outflow.

d. Routing of the failure hydrograph(s) to desired downstream locations. The results provide estimates of the peak discharge(s), time(s) to peak and maximum water surface elevations of failure hydrographs for each location.

D-1

HYDROLOGY AND HYDRAULIC ANALYSIS DATA BASE

NAME OF DAM:

STEEL DAM

PROBABLE MAXIMUM PRECIPITATION (PMP) = 24 INCHES/24 HOURS ⁽¹⁾

STATION	. 1	2	3
STATION DESCRIPTION	STEEL DAM		
DRAINAGE AREA (SQUARE MILES)	4.1		
CUMULATIVE DRAINAGE AREA (SQUARE MILES)	-		
ADJUSTMENT OF PMF FOR DRAINAGE AREA LOCATION (%) ⁽¹⁾	Zone 7		
6 HOURS 12 HOURS 24 HOURS 48 HOURS 72 HOURS	102 120 130 140 -		
SNYDER HYDROGRAPH PARAMETERS ZCNE (2) C_p (3) C_t (3) L (MILES) (4) L_{ca} (MILES) (4) $t_p = C_t (L \cdot L_{ca})^{0.3}$ (HOURS)	29 0.50 1.60 4.0 2.0 2.99		
SPILLWAY DATA CREST LENGTH (PEET) FREEBCARD (FEET)	100 4.5		

(1) HYDRCMETEOROLOGICAL REPORT - 33, U.S. ARMY CORPS OF ENGINEERS, 1956.

(2) HYDROLOGIC ZONE DEFINED BY CORPS OF ENGINEERS, BALTIMOPE DISTRICT, FOR DETERMINATION OF SNYDER COEFFICIENTS (C_p and C_t).

(3) SNYDER COEFFICIENTS

....

(4) L = LENGTH OF LONGEST WATERCOURSE FROM DAM TO BASIN DIVIDE. LCA = LENGTH OF LONGEST WATERCOURSE FROM DAM TO POINT OPPOSITE BASIN CENTRO

_____2

العرب ا 4 4 × 4 4

		· •	
SUBJECT DAM_SAFETY_INSPECT STEEL DAM BYDATE PROJ. NO CHKD. BY DATE SHEET NO	TICN 79-203-495 10F2	CONSULTANTS, I: Engineers • Geologists • Planners Environmental Specialists	
DAM STATISTICS			
- HEIGHT OF DAM = 15 FT	Low MUTOT	TO OF DAM TO	
- NORMAL POL STORES CARLETS 5 39	- CT	((35 Nors 2)	
- MAXIMUM POOL STORAGE CARINEY = 183 (@ LOW TOP OF DAM)	AC-57	(דערדער א-שאא)	
- DRAINAZE AREA = <u>4.1</u> 57 MI.	(Реалитен Наскотт	و و المدني 1.5 (2.5 من 2.5) المراجعة المستنفية (المراجعة المستنفية 1.5 (المراجعة المراجعة المراجعة المراجعة المستنفية المراجعة المراجعة ا	
ELEVATIONS:			
$T_{32} = \mathcal{D}_{24} \left(\mathcal{D}_{32} + \mathcal{D}_{33} \right) =$ $T_{32} = \mathcal{D}_{34} \left(\mathcal{D}_{32} + \mathcal{D}_{33} \right) =$	1007.0	(<i>m.</i> 3)	
Marmar Pool =	1202.0	(F13 3)	
SPILLWAY CREST 3	1002.0	(F: 3)	
Unorthe Init Inst I	574.0	(=3. 3)	ł
DOWNSTREAM CURIST INCOM	791.5	(FIS. 3)	-
STREAMON @ DAM CRATE INNE E	9925	(FIG. 3)	

More 1: Detraises FROM "PENCE UNIT - FE ADDUCATION OF THE DETRUCTION STERE COMPANY FOR THE CONSTRUCTION OF A DAM ACON-CENTER DRANGED OF BREAN CREEK IN JOMENCE TOURING WARNESS. CONTY, PERMITUNANIA," JACUART, 1952, EDUCT IN REINDEN ACON.

SUBJECT DAM SAFETY	NEPTOTION	
STEEL DA	Μ	
BY DATE	PROJ. NO	CONSULTANTS, I
CHKD. BY DATE	SHEET NO OF	Engineers • Geologists • Planners Environmental Specialists

DAM CLASSIFICAT DN

DAM JIZE: JMALL (REF 1, TABLE 1) HAZARD CLAUFICATION: HIGH (FIZD)RECONDUCT) REDURED JDF: JTY TO THE (REF 1, TABLE 3)

HYDROGRAPH HARAMETERS

LENGTH OF LOWERT WATEROURIE = 4.0 MILES

SEUST OF LOVELT UNTERDUCTE FROM DAM. TO A POINT OPPLYTE STUDY OFFICE ≤ 3.0 MILES

(MEASTRED ON USES TOPO 2000 - MACHET AND SUBSTRATE

 $C_{2} = 1.60$ (SUPPLIED BY CO.E., ZONCE D9, MONDAUGUL RUD DIED TO $C_{p} = 0.50$

(ASTE: MIDROSTANH VARIANCES WED HETLE ARE DEFINED IN REF ?, IN: SECTION EXTITLED "SNYDER SYNDISTIC DUT HIDROSTAPPH.")

SUBJECT	DAM	SAFETY INST	PECTION		
		STEEL DAM		·	
BY	DATE	7-22-23	PROJ. NO.	<u>- 19 - 3</u>	123-495
СНКО. ВУ	DATE	<u>= 1-2-</u>	SHEET NO.	3	OF



Engineers • Geologists • Planners Environmental Specialists

RESERVOIR CAPACITY

REVERVOIR SURPACE AREAS:

SURFACE AREA (S.A.) @ NORMAL POOL (EL. 1002) = <u>16.6</u> ACRES (SEE NOTE I) S.A. @ ELEV. 1020 = <u>64.0</u> ACRES (USS) TOTS - HACKETT JA

 $J_{A} = 200 \text{ FOP } J = 2400 (E2. 1006.5) = <u>38.5</u> \text{ ports}$ (BY 2005AR MATCHER (2007-2007))

ZERO - STORAGE" EVENATION :

....

BY USE OF THE CONIC METHOD,

VOLUME @ NORMAL POL = 13HA

WHERE H = MAXIMUM DEPTH OF RESERVOIR, IN FT, A = SURFACE AREA @ NORMAL ROL = 16.6 AC.

> $V_{CLUME} = \frac{1}{3}HA$ $89 = \frac{1}{3}H(16.6)$ $H = \frac{(3)(39)}{16.6}$ $= \frac{16.1}{5}FT$

· ZERO-STORAGE ASSUMED AT 1000.0 -16.1 = <u>985.9</u> FT

<u>Above</u>: ALTHOUGH THE MINIMUM RESERVER ELECTORIZED IS IN ACTUALITY AT APPROXIMATELY ELECT. 993, THE ELECTRON EDMOSED ACTUALITY DE USED AS INPUT IN THE MECTI PROSEAM, IN ORDER TO

and when the second



MAINTAIN A STORAGE OF A AR-FT AT NORMAL PODL.

ELEVATION - STORAGE RELATIONSHIP:

AN ELEVATION-STORAGE SELAT, SANGHIR IS COMPUTED INTERNALLY IN THE HEC-1 PROSERVA , BY NE DE THE CONSCINCTION, DAVED ON THE ELEVATION-SURFACE AREA DATA GIVEN HERE. (SEE JUMMARY INDA /JUTIST JUETTIN)

PMP CALCULATIONS

- APPROXIMATE RANDERLE INDER = 24 INCHES (CORRESPONDING TO A DURATION OF 24 HOURS, AND A BRAINDER AREA DF 200 JOJARE MILES.) (REE 3, FIS. 1) - DEMY-AREA-DURATION ENCE 7 (REF 3, FIS. 1)

- ASSIME DATA CORRESPONDING TO A 13-33,205 - 12 AREA MAY SE APPLIED TO THIS 41 SQUARE MILE RASIN:

DURATION (HRS) :	6	12	24	48
PERCENT OF INDEX RAINFALL :	102	123	150	140

(REF 3, FIS. 2)

HOP BROK FOOTOR (ADJUSTMENT FOR JASH) SHAPE AND FOR THE LESSER LIKELIHOOD OF A SEVERE STORM CRUTERING CUER A SMALL SOUND) FOR A DRAINAGE AREA OF <u>4.1</u> SQUARE MILES IS <u>D.80</u> (REG 4, p. 44)



Q = DIXHARSE OVER THE WOR, IN CFS, (= CORFERIENT OF DISCHARSE,

J. HERE

>

ŧ

SUBJECT		<u> </u>	M SAFETY	INSPEC	TION
			STEEL	DAM	
BY	255	DATE	7-24-22	PROJ. NO.	79-303-425
CHKD. BY	<u> </u>	DATE		SHEET NO.	OFO



Engineers • Geologists • Planners Environmental Specialists

L= WEIR LENGTH = 100 FT, H = HEAD, IN FT.

THE DESIGN COEFFICIENT OF DISCHARGE IS <u>3.80</u>. As THE MEAD ON THE WER DECOMES SMALL, DISCHARGE IS REDUCED DISPUTIDIATIONATELY, DUE TO THE RUCHNESS AND THE CONTACT PRESSURE DETWEEN THE WATER AND THE WEIR SURFACE. THUS, THE DISCHARGE COEFFICIENT TAKES ON A VALUE LOWER THAN THAT OF DEDISN (DESIGN HEAD) IS ASSUMED TO BE <u>50</u>, or AT THE DESIGN TOD OF WINGWALL RESUMING. THE OPPOSITE TOEND JOCUTS DOR HEADS STEATER THAN THAT OF DESIGN. THEREFORE, FOR HEADS LESS THAN <u>50</u> FT, THE DISCHARGE ODEFFICIENT WILL BE REDUCED, ACCORDING TO FIG. 250, REF. 4. FOR MEADS SCEATER THAN <u>50</u>, THE COEFFICIENT WILL REMAIN CONSTANT AT 3.80 - DUE TO THE MINUR CONSTER ACTING EFFECTS OF TURWARES INTERFERENCE AND INCREMING HEAD (TRILMATER SPECEDS ARE MINOR FOR THE RAMBE OF DISCHARGE DISCHARGE DE ACTING FOR ALL RETURNES ARE THAN THE FORMERS.

	רובעברי בעביטים, דעיבוד (ב=))-1 (et)	H/H0	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	<u> </u>	0 م (د-ی)
-	,003.0	0			-	0
	1003.0	1.0	J. Z	0.85	J.23	330
	1204.0	2.0	0.4	0.10	3.42	770
	1305.0	3.0	0.6	0.74	3.57	1860
	1006.0	4.0	0.8	077	3.07	3450
ر سادید رو = و)	/JJ6.J	4.5	0.9	0.99	3.76	3570
	1007.0	5.3	10	1.30	3.80	4250
	1037.5	5.5	1.1		3.3Û	4700
	1008.0)	1.2	_	3.50	5580
	1007.0	-7.0	1.4		3.80	7340
	1313.0	80	1.6		3.80	8600

0 Q = 100 x CH ">

· .



EMBANKMENT RATING CURVE

DISCHARGE OVER THE DAM STUTIE WILL EXENTIALLY CONSIST OF OPEN CHANNEL FLOW, DUE TO THE NATURE OF THE ENDICIONENT. DISCHARGE WILL DE ESTIMATED BY USE OF MANNUSS SUB-CONSIST FLOW AT NORMAL DENTH:

$$Q = \frac{1.49}{n} A R^{3/3} V^{3/3} \qquad (P = J_{1,2}, 7 - 7)$$

WHERE

...

Q = DISCULARES, IN OFS, N = REDUGANESS CONSECTIONERT, A = FOOW AREA, IN ETS, R = HEDRAULIC RADIUS (N ET, S = AVERAGE CHANNEL SLOPE, IN ET/FT.

DUE TO THE DIFFERENT CONDITIONS ON THE RIGHT SIDE AND LEFT NOE PORTIONS OF THE EMPANISMENT, FLOW OVER ENCH SIDE WILL DE COMPUTED SEPARATELT.

155

LEVETH OF DOM INUNDATED IS REFERR ELENTION: JAMON LENGTH - LEFT SIDE (==) (==) 1000.5 Э 1036.7 0 1006.9 0 1007.1 25 1307.5 110 120 1003.0 1009.0 135

1013.0

(FROM FELD WIRLS)
CLU TO -A-CET
والمرادة المسريم فيتعريك والعراقات

LENCEN - RISH SIJE

(5-)

0

65

105

120

145

155

165

175

ب التارين المسابع موجز جد السامن الر



Assume that incremental discharges for under le recervoir ELEVATIONS ARE APROXIMATELY TRAPEDOIDAL IN CROSS-JEUT WAL FLOW AREA. THEN ANY INCREMENTAL AREA OF FLOW CAN BE FORMATED AS $D_{L}\left[(L_{1}+L_{2})/\partial\right]$, WHERE $L_{1} = LENSTH OF EMBAJNICMENT OVERTSPRED AT HIS-ER SUBJECTION,$ $<math>L_{2} = LENSTH AT LOWER EVERNTION, <math>D_{L} = D_{1}EEERENCE IN EVENTSIN, THU, The$ $TOTAL AVERAGE "FLOW AREA - MERS-TED DEFINA (DW) CAN BE FUT AS (TOTAL FLOW AVER / L_1).$ THIS "WEIGHTED DEFINA" WILL BE ANSWED AS AN ASSIDATE ESTIMATED DE LEIN THE MANNUG EQUATION.

CHANNEL SLOPE: SE 2.5%

.:

(ASSUME THAT FANDALL, YEUT GLOPE II, THE ADDALL FUT SHALL AND THE ADDALL ADDALLE ADDALL ADDAL

SHOULD THE ABOUR METHOD PROVIDE DISCHARGES WHICH ARE EXAD TO DE SUPERCRITICAL, THEN <u>CRITICAL</u> ELSI WHICH SATTON , AND PRIMARGES CAN DE FESTIMATED AS

 $Q = 3.087 L H^{2/2} \qquad (Ref S, p. J-04)$

WHERE L = LENGTH OF DAM WUNDATED, IN FT, Hu = WERGHTED HEAD ABOVE CREST = Dw (SEE ABOVE).

THE EMEANY, NEUT RATING THEE IS TROUDED ON SHEET 1.

SUBJECT		C	AM	SAE	ET	Y IN	ISPE	CTION	1		i i		
8Y	255	DATE			<u>ا حارد</u>		J. NO.	رۇ- ەر	:- ५ १ऽ				ANTS,
CHKD. BY	<u></u>	 DATE		• <u> -</u> -	-	SHE	ET NO.	<u> </u>	_ OF	1	Eng Envi	ineers • Geologists ironmental Specialist	• Planne s
RILIT SIDE DOKTIAN	$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	0 - - - - 0 0 65 0 0.0 7 7 0.1 0 0	135 65 0.0 17 24 0.2 10 10	145 130 0.4 53 100 0.7 1.0 1.0 1.4 151 152 155 151 11 120 449	165 155 1.0 160 335 2.0 780 1620	125 115 1.0 1.20 505 29 1.510 3180				$\mathcal{D}_{i}^{\mathcal{M}}$	MATED AS Due FUR UNDE SHALLOW		5
LEFT SIDE PORTIUN	ELEV LI LO DI AI $A\tau$ $Du Q$ Q (r1) (r1) (r1) (r1) (r1) (r1) (r1) (r1)	10%.7 0 0 10%.7 0 0 0.3 0	12051 05 0 0.0 0	002 1/0 25 0.4 27 30 0.3 60 000 000 000 000 000 000 000 000 000	048 9.1 918 801 01 021 SC1 0.001	12/01/152 132 1.0 142 361 9.3 1/020			$(3) \mathcal{M}_{11} = \frac{A_T}{A_T}$	(1) (1) (1) (2)	THE HADRAN IN THE AND A CONTRACT IN THE ADDRESS INTO ADDRESS IN THE ADDRESS IN THE ADDRESS INTO ADD	FOU AKEN USED NEVE	

<u>_</u>

:

...

,

1

ul 1

SUBJECT	DAM SAFETY INSPECTION						
		STEEL DA	<u>sm</u>				
BY	DATE		PROJ. NO.		103 -	. 495	
СНКО. ВУ	DATE	<u> </u>	SHEET NO.	0	OF	<u> </u>	



Engineers • Geologists • Planners Environmental Specialists

TOTAL FACILITY RATING TABLE

QTOTAL = QSDILLLAY T DEMONSIONENT

	REVERIOUR ELEVATION	O QSPILLWAY	I CHEMITALKIMENT	Grand
_	(=1)	(c=s)	(c#s)	(c=s)
_	1002.0	0	-	0
	1003.0	320	-	330
	1004.0	470	-	970
	1005.0	1863	-	1860
	1006.Û	2950		5450
	1005.5	3590	Э	3540
	1007.0	4250	30*	4280
	1007.5	-1400	180	5150
	1008.0	5580	470	6û70
	1009.0	7040	1620	8660
	1010.0	8600	3180	11,780

* - CIMEARLY INTERPOLATED.

() FROM SHIT 6.

5 FROM SHOT 9

вү <u>255</u> снкр. ву <u>34</u>	DATE	 DAM 00	SAFE STEE PROJ.N SHEET	<u>TY IN</u> EL DA 10. <u>7</u> NO. <u> </u>	<u>NE PECT</u> M 9-203- <u>A</u> 0	495 F			ginee	rs • Geolinental Spi
OVERTORPING ANHLYSIS UAM SAFTY INSPECTION STALE UNN ON INFLOW HUNDERAPH **** 10-NINUTF TIME STEP AND 48-HUUR STURM DIMATION NO WA WAIN TOAT AND AFECIFICATION NO WA NAIN TOAT THRE IN MIN WEEKC FOLT TOAT ASTAU	284 0 10 0	 RESERVIR INFLUM HYDROGHAFH Istadi Icump Iecum Itape Jpci Jprt Iname Istage Iauto I 0 0 0 0 0 0	HYDG TUHG TARFA SWAP THSDA THSPC RATTU ISMDW ISAME 1.0CAL 1 1 4.10 0.00 4.10 0.00 0.000 0 1 0	PRECIP DATA SPFE PMS R6 M12 M24 M49 M72 M96 0.00 24.00 102.00 120.00 130.00 0.00 0.00 0.00 SPC cumputed At The phinema is .800	LROPT STAKE ULTKE RTIOL EMAIN STRES NTIOK STRTL CONSTMUT U 0.00 0.00 1.00 0.00 0.00 1.00 1.00 0.05 0.05	UNIT HYDRUGKAPH DATA TP= 2.99 CP3 .50 NTA3 0 AASEFLOWD	PROXIMATE CLARK COEFFICIENTS FWOM GIVEN SWYDFR CP AND TP AND TELEVAL. PROXIMATE CLARK COEFFICIENTS FWOM GIVEN SWYDFR CP AND TP ANE TC=18.69 AND H=24.60 INTERVALS	UMIT HYDHOGRAPHIDD EMD-DF-PERIUD URDIMATES, LAG= 2.97 HUNKS, CFE 50 VOLM .97 6. 21. 41. 70. 101. 134. 164. 206. 245. 244. 322. 355. 344. 408. 427. 422. 452. 455. 449. 414.		123. 111. 109.

.:

1

.....

,

J,

1

ł

1 ŧ 1

SUB 1507				•••				
308JEC 1			4	JAM SA	FETY IN	SPECTIO	~	
		. <u></u>	<u>-</u>	S7	EEL DAM	<u>ا</u>		
BY	5	DATE	1-30-20	PRO.	J. NO. <u>79</u>	-203-4	95	CONSU
СНКО. ВУ	DLA	DATE	1-20	SHEE	ET NO. <u>8</u>	OF	<u> </u>	Engineers • Geologis Environmental Specia
RESER	OIR	INFLOW	HYDI	ZOGRA	PHS			
		CFS CNS Inches -HM AC-FT Thous Cu M	PFAK 3537. 100.	6-HUUR 2857. 81. 6.48 164.64 1417. 1747.	24-HIHR 1080. 31. 9.80 248.97 2147. 2647.	72-11011R 555. 16. 10.08 255.96 2202. 2717.	TUTAL VULU 15989 4521 10.0 255-5 2202 271	40 4. 4. 58 66 7. 7.
		CFS CMS Inchs Ham C=ft Thous Cu M	PEAK 4245. 120.	6-HOUR 3428. 97. 7.78 197.57 1700. 2097.	24-HOUR 1296, 37, 11.76 298.77 2571, 3171,	72-HUUR 666. 19. 12.09 307.15 2643. 3260.	TUTAL VOLUM 191873 5433 12.0 307.1 2643 3260	E
		CFS CMS Inches Mm Ac-Ft Thous C1 H	PEAK 7075. 200.	6-HUUR 5714. 162. 12.96 329.28 2833.	24-HOUR 2160. 61. 19.60 497.94 4285.	72-HDUR 1110. 31. 20.15 511.92 4405.	TOTAL YOLUAE 319788. 9055. 20.15 511.92 4405.	PA
				3495.	5285.	5433.	5433.	
*****		- 6+4344	****	3495.	5285.	5433.		*****
•••••		- 604344		3495.	5285.	5433;	• • • • • •	*****
•••••	ROUTE	- CARDAR	JGRAPH THRC	TARTA NIDROGRAPH	5285. 4 ROUTING	5433:		
•••••	ROUTE	INFLOW HYDRO ISTAQ 101 0055 CLOSS	DCRAPH THRO	NIDROGRAPH UGH RESERV IECON II O ROUTING IRES IS	S285. A ROUTING VOIR CAPP JPU1 C DATA SAME IOP	5433; 5433;	INAME 1577	LGE IAUTO 0 0
•••••	ROUTE	INFI.OW HYDRO ISTAQ 101 055 CLOSS 0.0 0.000 NSTPS	DGPAPH THRC ICOMP 1 AVG 0.00 NSTDL 0	NYDROGRAPH UGH RESERV IECON II ROUTING IRES IS I UAG AP	5285. 4 ROUTING /OIR CIR CIR CIR CIR CIR CIR CIR C	5433. T JPRT D 0 T IPHP D 0 C TSK 0,000	INAME IST	ининининининининин асе тайтинин о о ста ат
•••••• 52 1002. 1010.	ROUTE ROUTE	INFI.ON HYDRO ISTAQ 101 0055 CLOSS 0.0 0.000 NSTPS 1 103.00 10	осрарн тирс ICOMP 1 ачс 0.00 NSTDE 0 0004.00	HIDROGRAPH DUGH RESERV IECON II O ROUTINO IRES IS I LAC AP 0 0. 1005.00	5285. 4 ROUTING 1018 CAPY - JPU1 0 (2 DATA 3AMF IOPI 1 (1 000 0.000 1005.00	5433; 5433; 7 JPRT 0 0 1 JPRT 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	INAME IST 1 1 5TORA ISP -1002. 0 1007.00	AGE IAUT" 0 0 STR 0 RAT -1 0 1007.50
•••••• 52 1002. 1010. 59 0. 11789.	ROUTE ROUTE	INFLOW HYDRO ISTAQ 101 055 CLOSS 0.0 0.000 NSTP3 1 003.00 10	осварн тико ICOMP 1 аус 0.00 NSTDL 0 004.00 976.00	3495. HYDROGRAPH DUGH RESERV IECON II O IRES IS I LAC AP 0 0. 1005.00 1866.00	5285. 6 ROUTING 7018 TAPF: - JPL1 0 0 1 0 1 0 1 0 1 0 1 0 1 0 1	5433. DPRT DPRT 0 1 DPRT 0 0 0 0 0 0 0 0 0 0 0 0 0	INAME IST 1 STORA ISP -1002. 0 1007.00 0 4280.00	TTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTT
52 1002. 1010. 1010. 11780. CE AREA=	ROUTE ROUTE DL 00 10 00 3 00 0.	INFI.OW HYDRC ISTAG 101 0.055 CL035 0.0 0.000 NSTPS 1 103.00 10 120.00 10 17.	DGPAPH THRC ICOMP 1 AVG 0.00 NSTDL 0 004.00 976.00 29.	3495. NYDROGRAPH UGH RESERV IECON II ROUTING IRES IS I LAC AP 0 0. 1005.00 1860.00 1860.00	5285. 4 ROUTING VOIR CAPE JPL1 0 (5 DATA 5 AWF IOPT 1 (15KK) 000 0.000 1006.00 7450.00	5433. T JPRT D 0 T IPMP D 0 T SK D 0.000 1006.5 3590.0	INAME IST INAME IST La STORA ISP -1002. 0 1007.00 0 4280.00	ACE IAUTO 0 0 STR 0 RAT -1 0 1007.50 5080.00
GE 1002. 1010. 09 0. 11780. CE AREA= APACITY=	ROUTE ROUTE DL 00 10 00 30 00 0. 0. 0.	INFLOW HYDRO ISTAQ 101 055 CLOSS 0.0 0.000 NSTPS 1 103.00 10 120.00 17. 89.	DCRAPH THRC ICOMP 1 &VC 0.00 NSTDE 0 004.00 976.00 29. 189.	3495. NYDROGRAPH UGH RESERV IECON IT O ROUTINC IRES IS LAC AP O 0 1005.00 1860.00 1860.00	5285. 4 ROUTING 7019 7019 7019 7019 7010 7010 7010 7010 7050.00 7050.00	5433. JPRT 0 1 1 0 0 0 0 0 0 0 0 0 0 0 0 0	INAME IST INAME IST L: STORA ISP -1002. 0 1007.00 0 4280.00	TTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTT
GE 1002. 1010. 1010. 11789. CE AREA= APACITY= EVATION=	ROUTE ROUTE DL 00 10 00 00 0. 00 0. 00 0. 0. 986.	INFLOW HYDRC ISTAG 101 0.055 CL035 0.0 0.000 NSTPS 1 103.00 10 120.00 17. 89. 1092.	DCPAPH THRC ICOMP 1 AVC 0.00 NSTDL 0 004.00 976.00 29. 189. 1007.	3495. NYDROGRAPH UGH RESERV IECON II ROUTING IRES IS I LAC AP 0 0. 1005.00 1860.00 1860.00 1860.00 1860.00	5285. 4 ROUTING 7018 7018 7018 7018 7018 7018 7018 7010 7010 7010 70500 7050 7050 7050 7050 7050 7050 7050 7050	5433. JPRT 0 1 0 0 0 0 0 0 0 0 0 0 0 0 0	INAME IST INAME IST La STORA ISP -1002. 0 1007.00 0 4280.00	ACE IAUTO 0 0 STR 0 RAT -1 0 1007.50 5080.00

1

:

,

нł т

4 × 100

SUBJECT		DA	<u>M SAFE</u> Ste	τγ 11 εει 1	NSPECTI DAM	<u>0N</u>	-	
BY	DATE7	- 70 - 80	PROJ. N	vo	19-203-	495		CONS
	DATE	-1-90	SHEET	NQ	<u> </u>	: <u> </u>	Engine - Enviror	ers • Geolo rmental Spe
RESERVOIR O	JTFLOW	HYDRO	IGRAP	15				
PEAK OU	TFLOW IS	3509. AT T	INE 42.83	HOURS				
0.50 PMF	-	IN THOUS	CFS 3 CMS CHES NM C-FT CU M	PEAK 509. 99.	6-HOUR 2849. 81. 6.46 164.13 1412. 1742.	24-HOUR 1057. 30. 9.54 243.67 2097. 2586.	72-HQUR 543. 15. 9.85 750.30 2154. 2657.	TOTAL VOLU 15635 442 9, 250, 215 265
PEAK C	UTFLUW IS	4213. AT	t1×€ 42.8	3 HOURS	5			
0.60 PMF	• • • •	THOUS	CFS CMS NCHFS MM AC-FT CU M	РЕАК 4213. 119.	6-HOUR 3418. 97. 7.76 197.00 1695. 2091.	24-400R 1270. 36. 11.57 292.70 2519. 3107.	72-HOUR 657. 18. 11.84 300.65 2587. 3191.	TUTAL VO 187 5 1 30 2' 3
PEAK O	JTFLOW IS	7055. AT 1	THE 42.61	1 HOURS				
PME	· · · · · · · · · · · · · · · · ·	IN THOUS	CFS CNS ICHES MM NC-FT C11 M	PEAR 1055. 200.	5-ROUR 5700. 161. 12.93 328.47 2026. 3486.	24-HOUR 2127. 60. 19.76 489.17 4209. 5191.	72-HOUR 1090. 31. 19.7R 502.35 4322. 5332.	TOTAL VOL 3138 88 19 502 43 53
		SU INITIAL	MMARY OF 1	SPILL	ETY ANALYS	13 TOP (7F DAM	
	ELEVATION Storage Outflow	1002	.00 89. 0.		302.00 89. 0.	100	6.50 189. 1590.	
9ATIO - OF - PMF	MAXIMUM RESERVOIR W.S.FLEV	MAXIMUM DEPTH Over Dam	MAXIMUM Storage Ac-ft	MAX DUTI C1	INUM DU Flow Ov Fs k	RATION ER TOP IOURS	TIME OF HAX OUTFLOW Hours	TIME OF FAILURE Hours
	-							- a aa -

(OUGATOPPING OCCURS @ = 0.51 PMF)

.:

el •

.

ŧ,

;

LIST OF REFERENCES

1. "Recommended Guidelines for Safety Inspection of Dams," prepared by Department of the Army, Office of the Chief of Engineers, Washington, D. C. (Appendix D). 2. "Unit Hydrograph Concepts and Calculations," by Corps of Engineers, Baltimore District (L-519). 3. "Seasonal Variation of Probable Maximum Precipitation East of the 105th Meridian for Areas from 10 to 1,000 Square Miles and Duration of 6, 12, 24, and 48 Hours," Hydrometeorological Report No. 33, prepared by J. T. Riedel, J. F. Appleby and R. W. Schloemer, Hydrologic Service Division Hydrometeorological Section, U. S. Department of the Army, Corps of Engineers, Washington, D. C., April 1956. Design of Small Dams, U. S. Department of the Interior, 4. Bureau of Reclamation, Washington, D. C., 1973. 5. Handbook of Hydraulics, H. W. King and E. F. Brater, McGraw-Hill, Inc., New York, 1963. Standard Handbook for Civil Engineers, F. S. Merritt, 6. McGraw-Hill, Inc., New York, 1968. 7. Open-Channel Hydraulics, V. T. Chow, McGraw-Hill, Inc., New York, 1959. 8. Weir Experiments, Coefficients, and Formulas, R. E. Horton, Water Supply and Irrigation Paper No. 200, Department of the Interior, United States Geological Survey, Washington, D. C., 1907. 9. "Probable Maximum Precipitation Susquehanna River Drainage Above Harrisburg, Pennsylvania," Hydrometeorological Report 40, prepared by H. V. Goodyear and J. T. Riedel, Hydrometeorological Branch Office of Hydrology, U. S. Weather Bureau, U. S. Department of Commerce, Washington, D. C., May 1965. 10. Flood Hydrograph Package (HEC-1) Dam Safety Version, Hydrologic Engineering Center, U. S. Army, Corps of Engineers, Davis, California, July 1978. 11. "Simulation of Flow Through Broad Crest Navigation Dams with Radial Gates, "R. W. Schmitt, U. S. Army, Corps of Engineers, Pittsburgh District.

.2

- 12. "Hydraulics of Bridge Waterways," BPR, 1970, Discharge Coefficient Based on Criteria for Embankment Shaped Weirs, Figure 24, page 46.
- 13. Applied Hydraulics in Engineering, Morris, Henry M. and Wiggert, James N., Virginia Polytechnic Institute and State University, 2nd Edition, The Ronald Press Company, New York, 1972.
- 14. <u>Standard Mathematical Tables</u>, 21st Edition, The Chemical Rubber Company, 1973, page 15.
- 15. Engineering Field Manual, U. S. Department of Agriculture, Soil Conservation Service, 2nd Edition, Washington, D. C. 1969.
- 16. Water Resources Engineering, R. K. Linsley and J. B. Franzini, McGraw-Hill, Inc., New York, 1972.
- 17. Engineering for Dams, Volume 2, W. P. Creager, J. D. Justin, J. Hinds, John Wiley & Sons, Inc., New York, 1964.
- 18. <u>Roughness Characteristics of Natural Channels</u>, H. H. Barnes, Jr., Geological Survey Water-Supply Paper 1849, Department of the Interior, United States Geological Survey, Arlington, Virginia, 1967.
- 19. "Hydraulic Charts for the Selection of Highway Culverts," Hydraulic Engineering Circular No. 5, Bureau of Public Roads, Washington, D. C., 1965.

APPENDIX E FIGURES

LIST OF FIGURES

- - -

Figure	Description/Title
1	Regional Vicinity and Watershed Boundary Map
2	Location Plan
3	Plan and Sections
4	Details of Concrete Spillway
5	Gate Tower
6	Typical Cross-Section Through Spillway






















:

.



APPENDIX F

- - ----

GEOLOGY

ւտը է նախելից մեն են ե

<u>Geology</u>

Steel Dam is located in the Pittsburgh Plateaus section of the Appalachian Plateaus province of southwestern Pennsylvania. In this area, the Pittsburgh Plateaus section is characterized by flat-lying to very gently folded sedimentary rock strata of upper Pennsylvanian age. Major structural axes strike from southwest to northeast with flanking strata gently dipping northwest and southeast.

Structurally, the dam and reservoir lie about one mile east of the axial trace of the southwestward plunging Amity anticline. In the vicinity of the dam and reservoir, the bedrock dips gently to the southeast or downstream at approximately one-half degree.

The sedimentary rock sequence contained in the abutments and underlying the embankment is the lower member of the Uniontown Formation, Monongahela Group, of Pennsylvanian age. The rocks of this group typically exhibit the rapid vertical and lateral lithology changes characteristic of cyclic sedimentation. Rock types to be expected immediately underlying the dam and reservoir are: "limestone; silty mudstone; siltstone; sandstone; mudstone; and locally impure coal (the Uniontown Coal)". The Uniontown Coal horizon lies about 40 feet beneath the dam. Underlying the Uniontown Formation is the Pittsburgh Formaton, the base of which is delineated by the Pittsburgh Coal. The Pittsburgh Coal, therefore, lies approximately 300 feet beneath the dam embankment and about 280 feet below the upstream inlet to the reservoir. According to the Geologic Map of the Hackett Quadrangle, Washington County, Pennsylvania, "the Pittsburgh Coal largely has been removed by mining" around the dam and reservoir and, possibly, beneath same.

Alluvial materials in the valley consist of "unconsolidated silt, sand, gravel, and cobbles. These have been removed from beneath the core cutoff wall within the dam embankment.

F-1

REFERENCES

Clapp, Frederick G., "Geologic Atlas of the United States - Amity Folio," No. 144, U. S. Geological Survey, Washington, D. C., 1907.

Kent, Bion H., "Geologic Map of the Hackett Quadrangle, Washington County, Pennsylvania," Map No. GQ-630, U. S. Geologic Survey in cooperation with the Commonwealth of Pennsylvania, 1967.

Wallace, Joseph J., et al., "Estimate of Known Recoverable Reserves of Coking Coal in Washington County, Pennsylvania," Bureau of Mines Report of Investigations 5109, U. S. Department of the Interior, Washington, D. C., 1955.



and some work

