

AD-A091 525


NEW YORK STATE DEPT OF ENVIRONMENTAL CONSERVATION ALBANY F/G 13/13
NATIONAL DAM SAFETY PROGRAM, LOCK 32 - ERIE CANAL (INVENTORY NU--ETC(U))
SEP 80 B L THOMSEN, G L WOOD

DACW51-79-C-0001

NL

UNCLASSIFIED

1 of 1
AC
W51-79



LEVEL II

6
B.S.

AD A 091525

6 National Dam Safety Program,
 LOCK 32 - ERIE CANAL
 (Inventory Number N.Y. 791),
 MONROE COUNTY, NEW YORK.
~~INVENTORY NUMBER 791~~
 PHASE I INSPECTION REPORT,
 NATIONAL DAM SAFETY PROGRAM

11 SEP 80

12 58

15 DACW51-79-C-0001



DTIC
ELECTE
NOV 10 1980

Prepared by
 THOMSEN ASSOCIATES
 105 CORONA AVE. GROTON, N.Y.

10 Bent L. Thoms
 Gary L. Wood

Prepared for
 DEPARTMENT OF THE ARMY
 NEW YORK DISTRICT, CORPS OF ENGINEERS
 NEW YORK, NEW YORK

SEPTEMBER 1980 THIS DOCUMENT IS BEST QUALITY PRACTICABLE
 THE COPY FURNISHED TO DDC CONTAINED A
 SIGNIFICANT NUMBER OF PAGES WHICH DO NOT
 REPRODUCE LEGIBLY.

APPROVED FOR PUBLIC RELEASE;
 DISTRIBUTION UNLIMITED
 CONTRACT NO. DACW-51-79-G0001

323970

80 10 29 010

DDC FILE COPY

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO. AD-A091525	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Inspection Report Lock 32-Erie Canal Monroe County, New York Inventory No. 791		5. TYPE OF REPORT & PERIOD COVERED Phase I Inspection Report National Dam Safety Program
7. AUTHOR(s) Bent L. Thomsen Gary L. Wood		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS Thomsen Associates 105 Corona Avenue Groton, NY 13073		8. CONTRACT OR GRANT NUMBER(s) ✓ DACW-51-79-C-0001
11. CONTROLLING OFFICE NAME AND ADDRESS New York State Department of Environmental Conservation 50 Wolf Road Albany, NY 12233		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) Department of the Army 26 Federal Plaza New York District, CofE New York, NY 10287		12. REPORT DATE 25 September 1980
		13. NUMBER OF PAGES
		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; Distribution unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dam Safety National Dam Safety Program Visual Inspection Hydrology, Structural Stability Lock 32 Erie Canal Monroe County Seneca River		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report provides information and analysis on the physical condition of the dam as of the report date. Information and analysis are based on visual inspection of the dam by the performing organization. Examination of available documents and a visual inspection of the dam did not reveal conditions which constitute an immediate hazard to human life or property. However, increased maintenance		

34-970

is required to correct concrete deterioration in the general lock area, of the spillway intake structure, and of the foot bridge which crosses the spillway discharge pool. Also, a detailed emergency operation-action plan and warning system should be developed and implemented.

No additional investigations are deemed necessary at this time. Because flow to Lock 32 is controlled by other structures, no hydrologic/hydraulic analyses were possible.

DISCLAIMER NOTICE

THIS DOCUMENT IS BEST QUALITY PRACTICABLE. THE COPY FURNISHED TO DTIC CONTAINED A SIGNIFICANT NUMBER OF PAGES WHICH DO NOT REPRODUCE LEGIBLY.

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, DC 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I Investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Accession For	
NTIS GRA&I	
DDC TAB	
Unannounced	
Justification	
By _____	
Distribution/	
Availability Codes	
Dist..	Avail and/or special
A	23 CP

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
LOCK 32 ERIE CANAL
I. D. NO. N.Y. 791

MONROE COUNTY, NEW YORK

TABLE OF CONTENTS

		<u>Page No.</u>
-	ASSESSMENT	-
-	OVERVIEW PHOTOGRAPHS	-
1	PROJECT INFORMATION	1
1.1	GENERAL	1
1.2	DESCRIPTION OF PROJECT	1
1.3	PERTINENT DATA	3
2	ENGINEERING DATA	4
2.1	GEOTECHNICAL DATA	4
2.2	DESIGN/CONSTRUCTION RECORDS	5
2.3	OPERATION RECORDS	5
2.4	EVALAUTION OF DATA	5
3	VISUAL INSPECTION	6
3.1	FINDINGS	6
3.2	EVALUATION OF OBSERVATIONS	6
4	OPERATION AND MAINTENANCE PROCEDURES	7
4.1	PROCEDURES	7
4.2	MAINTENANCE OF LOCK	7
4.3	MAINTENANCE OF SPILLWAY AND APPURTENANT STRUCTURES	7
4.4	WARNING SYSTEM IN EFFECT	7
4.5	EVALUATION	7
5	HYDROLOGIC/HYDRAULIC	8
5.1	HYDRAULIC CHARACTERISTICS	8
5.2	ANALYSIS CRITERIA	8
5.3	SPILLWAY CAPACITY	8
5.4	RESERVOIR CAPACITY	9
5.5	FLOOD OF RECORD	9
5.6	OVERTOPPING POTENTIAL	9
5.7	EVALUATION	9

		<u>Page No.</u>
6	STRUCTURAL STABILITY	10
6.1	EVALUATION OF STRUCTURAL STABILITY	10
7	ASSESSMENT/RECOMMENDATIONS	11
7.1	ASSESSMENT	11
7.2	RECOMMENDED MEASURES	12

APPENDICES

Appendix A - Photographs

Appendix B - Visual Inspection Checklist

Appendix C - Hydrologic/Hydraulic:Engineering Data and Computations

Appendix D - Drawings

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

NAME OF DAM: Lock 32 Erie Canal
I.D. No. N.Y. 791

STATE LOCATED: New York

COUNTY LOCATED: Monroe

WATERSHED: Seneca River

STREAM: New York State Barge Canal

DATE OF INSPECTION: June 12, 1980

From P2

ASSESSMENT

Examination of available documents and a visual inspection of the dam did not reveal conditions which constitute an immediate hazard to human life or property. However, increased maintenance is required to correct concrete deterioration in the general lock area, of the spillway intake structure, and of the foot bridge which crosses the spillway discharge pool. Also, a detailed emergency operation-action plan and warning system should be developed and implemented.

No additional investigations are deemed necessary at this time. Because flow to Lock 32 is controlled by other structures, no hydrologic/hydraulic analyses were possible.

Bent L. Thomsen
Bent L. Thomsen, P. E.
Thomsen Associates
N.Y. License #40553

Gary K. Wood 9/25/80
Gary K. Wood, P.E.
Thomsen Associates
N.Y. License #44504

APPROVED BY

Colonel W. M. Smith, Jr. 9/30/80
Colonel W. M. Smith, Jr.
New York District Engineer



Overview Photo of
Upstream Works



Overview Photo of
Lock 32

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
LOCK 32 ERIE CANAL
I.D. NO. N.Y. 791
MONROE COUNTY, NEW YORK

SECTION 1: PROJECT INFORMATION

1.1 GENERAL

a. Authority

The Phase I inspection reported herein was authorized by the Department of the Army, New York District, Corps of Engineers, to fulfill the requirements of the National Dam Inspection Act, Public Law 92-367.

b. Purpose of Inspection

This inspection was conducted to evaluate the existing conditions of the lock and its appurtenant structures, to identify deficiencies and hazardous conditions, to determine if they constitute hazards to human life and property, and to recommend remedial measures where necessary.

1.2 DESCRIPTION OF PROJECT

a. Description of the Lock and Appurtenant Structures

Lock 32 is a concrete, pile supported structure set in an earth embankment. The interior of the lock is approximately 340 feet long, 44 feet wide, and 40 feet deep. There are vertically hinged gates at the west (upstream) and east (downstream) end of the lock. The approximate head differential is 25 feet.

The only spillway is located south (See layout plan and sections, Appendix D, for compass directions) of the lock. It is an open, riprap-lined channel approximately 1000 feet in length. The entrance to the spillway consists of five gates, each approximately 8½ feet wide. These

gates are equipped with stoplogs. The downstream end of the spillway consists of a double box culvert under Route 65. This culvert empties into a pool at the downstream end.

b. Location

The lock is located on the Erie Canal of the New York State Barge Canal system, south of the City of Rochester, and just west of the Village of Pittsford. It is near the intersection of Routes 252 and 65.

c. Size Classification

→ This lock has a head of approximately 25 feet, and a storage volume of approximately 360 acre-feet. Therefore, it is classified as a small dam. → cont. p 2

d. Hazard Classification

The dam is classified "high" hazard because of downstream residences and the potential impact on navigation.

e. Ownership

Lock 32 is owned by the New York State Department of Transportation, Waterways Maintenance Subdivision. The controlling office is located near Rochester, New York.

New York State Department of Transportation
Region 4
Jefferson Road
Rochester, New York
Mr. Clarence Burkwit
716-442-8550

f. Purpose of the Dam

The sole purpose of Lock 32 is to facilitate navigation along the New York State Barge Canal. The impounded waters behind the dam provide a storage pool used for gravity inflow to the lock.

g. Design and Construction History

The New York State Barge Canal in the vicinity of Lock 32 is an artificial waterway. Plans are dated 1908, and the lock was constructed a short time after this.

h. Normal Operational Procedures

During the navigation season, the upstream and downstream water levels are maintained as nearly as possible to the design levels of 487.5 (BCD-Barge Canal Datum) and 462.4 (BCD). These levels are established by the spillway stoplogs in the upstream and downstream locks, as well as this one. Manipulation of these stoplogs is not normally required. Staff gauge readings upstream and downstream of the lock are recorded daily. During the winter, the canal in the vicinity of Lock 32 is drained by closing the inlet gates at the Genesee River, some 5 miles upstream.

1.3

PERTINENT DATA

a. Elevations (Barge Canal Datum-BCD)

Top of Dam	490.0
Design Pool	487.5
Maximum Recorded Pool	488+
Spillway Crest (Minimum)	485.5
Spillway Crest (Maximum)	490.0
Streambed at Dam Centerline (Upstream)	475.5+
Streambed at Dam Centerline (Downstream)	450.4+
Design Tailwater	462.4
Maximum Recorded Tailwater	463+

b. Reservoir (feet)

Length of Normal Pool	6800+
-----------------------	-------

c. Storage (acre-feet)

Normal Pool	360+
-------------	------

d. Reservoir Surface (acres)

Normal Pool	30+
-------------	-----

e. Dam

Type	Lock
Length	350'+
Height (Head)	25'+
Top Width	50'+

f. Spillway

Type	Open Channel (Rip-Rap lined)
Crest Elevation	485.5-490.0
Gates	5 gates, each 8.5' wide, with stoplogs

SECTION 2: ENGINEERING DATA

2.1 GEOTECHNICAL DATA

a. Geology

Lock 32 is located approximately 1.5 miles west of Pittsford, a southeastern suburb of Rochester, New York.

The site lies north of the Onondaga Escarpment, a cuesta which trends east-west across upstate New York, and therefore, is situated in the Erie-Ontario Lowlands physiographic province. This province is characterized by the general low relief of a glacial lake plain, above which rise hills and drumlins composed of glacial till and bedrock.

Bedrock in the immediate Lock 32 vicinity consists of the Upper Silurian Salina Group of interbedded shales, siltstones, dolostones and evaporites. The shale and siltstone units are characteristically gypsiferous and many units are known to be cavernous. Despite a regional southward dip, stratification may be considered horizontal over short distances; no major or active faults are to be found in the area. The depth to bedrock is uncertain.

Lock 32 is situated in a region classified as Zone 3 seismicity, as shown on Figure 1 of the Recommended Guidelines for Safety Inspections of Dams.

Pleistocene glaciation of the region has left, as its most marked effect, extensive fine-grained lacustrine deposits which once formed the floor of proglacial Lake Iroquois. Subsequent to final retreat of the Wisconsinan Stage ice sheet and reduction of Lake Iroquois to present Lake Ontario, drainage channels dissecting the lake plain became the site of stratified sand and gravel outwash deposits. Throughout the lacustrine phase, uplands of sufficient elevation such as drumlins and knolls of till and bedrock, remained free of sedimentation.

b. Subsurface Investigations

No records of subsurface investigations were available. Based upon the available plans and the site characteristics, it appears that the lock and spillway intake are founded on piles. The lengths and type(s) of the piles are uncertain.

2.2 DESIGN/CONSTRUCTION RECORDS

Plans dated 1908 and identified as Contract 23 show the existing lock, spillway, and appurtenant structures as they presently exist. Selected drawings are included in Appendix D.

2.3 OPERATION RECORDS

This site has an attendant on a continuous basis during the navigation season. During the winter, the lock and canal are drained. Upstream and downstream water elevation readings are recorded daily during the navigation season. These levels are maintained as nearly as possible to the design levels of 487.5 (BCD) and 462.4 (BCD). The upstream level can be controlled by stoplogs at the spillway entrance.

2.4 EVALUATION OF DATA

The data presented in this report were obtained during the site inspection and from the files of the New York State Department of Transportation. The information is considered adequate for Phase I inspection purposes.

SECTION 3: VISUAL INSPECTION

3.1 FINDINGS

a. General

Visual inspection of the lock and appurtenant structures was conducted on June 12, 1980. The weather was generally fair. The upstream and downstream water elevations were 486.2 (BCD) and 462.5 (BCD) respectively.

b. Lock

The lock was observed in operation and no mechanical, electrical, or hydraulic problems were noted. Concrete deterioration was noted in the general lock area, including upstream and downstream dock walls.

c. Spillway

Concrete deterioration was noted at the spillway intake structure, and very significant concrete deterioration (including exposed reinforcing bars) was noted at the foot bridge which crosses the downstream spillway pool.

d. Upstream and Downstream Canals

The conditions of the canals upstream and downstream of the lock appeared to be satisfactory. Slopes in the Lock 32 vicinity are generally graded to 1 vertical on 2 horizontal. No signs of instability were noted.

3.2 EVALUATION OF OBSERVATIONS

The following deficiencies were noted, and are shown in the photographs in Appendix A.

- 1) Concrete deterioration in the general lock area.
- 2) Concrete deterioration of the spillway intake structure.
- 3) Concrete deterioration of the foot bridge.

SECTION 4: OPERATION AND MAINTENANCE PROCEDURES

4.1 PROCEDURES

Normal practice is to maintain the upstream and downstream water elevations as nearly as possible to the design levels of 487.5 (BCD) and 462.4 (BCD). These levels are affected by Locks 33 (upstream) and 31 (downstream). The water level within the lock is gravity-controlled by means of valves.

4.2 MAINTENANCE OF LOCK

The lock is maintained by the New York State Department of Transportation. Most of the lock maintenance is performed on an as-needed basis, with the largest part of the work being done during the portions of the year when the canal is drained. Every year, one of the four lock gates and its motor and operating mechanism are overhauled. Increased maintenance is required to correct concrete deterioration in the general lock area, including upstream and downstream dock walls.

4.3 MAINTENANCE OF SPILLWAY AND APPURTENANT STRUCTURES

The spillway and its appurtenant structures are maintained by the New York State Department of Transportation. Increased maintenance is required to correct concrete deterioration of the spillway intake structure, and of the foot bridge which crosses the downstream spillway pool.

4.4 WARNING SYSTEM IN EFFECT

No apparent warning system is present.

4.5 EVALUATION

It appears that past maintenance practices have largely ignored the concrete portions of the lock and its appurtenances and additional maintenance now is required to correct concrete deterioration in the general lock area, of the spillway intake structure, and of the foot bridge. In addition, a detailed emergency warning system should be developed.

SECTION 5: HYDROLOGIC/HYDRAULIC

5.1 HYDRAULIC CHARACTERISTICS

The New York State Barge Canal in the vicinity of Lock 32 is an artificial waterway. There are no tributaries. Flow to the lock and its spillway can be controlled by the following structures:

- o The Court Street Dam in Rochester. This dam maintains the Genesee River at an elevation of approximately 513.1 (BCD) during the navigation season, and supplies water for the Barge Canal.
- o Gates near the intersection of the Barge Canal and the Genesee River. These gates, which can be lowered even in the event of a power failure, are designed to prevent excessively high river waters from entering the canal. The top elevation of these gates is approximately 524 (BCD).
- o Lock 33. Through the use of stoplogs, the spillway crest of this lock can be made as high as approximate elevation 517 (BCD).

5.2 ANALYSIS CRITERIA

Because the canal in the vicinity of Lock 32 is an artificial waterway, and flow to the lock is controlled by other structures, no conventional hydrologic/hydraulic analyses were possible.

5.3 SPILLWAY CAPACITY

The spillway capacity was computed using an equation for orifice flow, and assuming that the water surface elevation was at the top of the lock walls (elevation 490.0-BCD). It was also assumed that all stoplogs were removed. With this analysis, a discharge of 1510 cubic feet per second was obtained.

5.4 RESERVOIR CAPACITY

The canal between Locks 32 and 33 was estimated to have a water surface area of approximately 30 acres, and a design depth of approximately 12 feet. The approximate storage, therefore, was computed as 360 acre-feet. The surcharge depth of 2 1/2 feet between normal water level and the top of embankment adds approximately 75 acre-feet, for a total storage capacity of approximately 435 acre-feet.

5.5 FLOOD OF RECORD

The maximum upstream pool elevation at Lock 32 has been approximately 488 (BCD). This level was noted during an isolated occurrence when an unusually high amount of water was discharged through Lock 33.

5.6 OVERTOPPING POTENTIAL

There is no record of the lock and/or spillway ever being overtopped.

5.7 EVALUATION

Because flow to Lock 32 is controlled by other structures, no hydrologic/hydraulic analyses were possible.

SECTION 6: STRUCTURAL STABILITY

6.1 EVALUATION OF STRUCTURAL STABILITY

a. Visual Observations

No visible evidence of structural instability was noted. The horizontal and vertical alignments, abutments, and joints between structural elements all appeared to be satisfactory. The concrete deterioration noted in the visual inspection does not affect structural stability (except that of the footbridge which does not affect the structure per se) at this time.

b. Stability Evaluation

No stability analyses (either overturning or sliding) were deemed applicable to this structure because of its configuration as a monolithic box.

A review of design parameters* for earth embankments of compacted sands and gravels indicates that embankment slopes of approximately 1 vertical on 2 horizontal will have adequate factors of safety with respect to shear failures.

Seismic stability was not considered during the design phase and was not evaluated as a part of this investigation since stability of the concrete structure was not applicable and there is no data available for stability analyses of the levee section.

*"Design of Small Dams", U.S. Department of Interior, Bureau of Reclamation, 1977.

SECTION 7: ASSESSMENT/RECOMMENDATIONS

7.1 ASSESSMENT

a. Safety

The Phase I inspection of Lock 32 did not reveal conditions which constitute an immediate hazard to human life or property. However, increased maintenance is required to correct deterioration in the general lock area, of the spillway intake structure, and of the foot bridge.

Because the flow to Lock 32 and its spillway is controlled by other structures, hydrologic/hydraulic analyses were not possible. In the event of a possible emergency (such as might result from impending failure of an upstream structure), however, continuous surveillance should be provided to warn of high floodwater conditions. Such surveillance procedures and other measures deemed necessary should be developed, documented, and placed in readiness for future use as part of a detailed emergency operation-action plan. A warning system should also be developed and implemented.

b. Adequacy of Information

The information available for preparation of this report is considered adequate.

c. Necessity for Additional Investigations

No additional investigations are deemed necessary at this time.

d. Urgency

The deficiencies noted in this investigation should be corrected before the next navigation season.

7.2


RECOMMENDED MEASURES

The following actions should be undertaken:

- a) Correct concrete deterioration in the general lock area, of the spillway intake structure, and of the foot bridge.
- b) Develop and implement a detailed emergency operation-action plan and warning system.

APPENDIX A

PHOTOGRAPHS



Concrete deterioration on
North Lock Wall




Upstream staff gauge;
NOTE: Concrete deterioration




Downstream staff gauge;
NOTE: Concrete deterioration

Concrete deterioration on
Downstream south wall



Leakage through upstream gates





Leakage through downstream
gates



Spillway entrance;
NOTE: Concrete deterioration

Spillway entrance;
NOTE: Concrete deterioration

Upper spillway



Box culvert and downstream
spillway pool



Lower spillway



Upper spillway





Foot bridge:
NOTE: Concrete deterioration
including exposed
reinforcing bars _____

APPENDIX B

VISUAL INSPECTION CHECKLIST

THOMSEN ASSOCIATES
CONSULTING GEOTECHNICAL ENGINEERS & GEOLOGISTS

VISUAL INSPECTION CHECKLIST

1) Basic Data

a. General

Name of Dam LOCK 32 EAGLE CANAL
I.D. # 40 D DEC. Dam No. 791
River Basin SENECA RIVER
Location: Town PITTSFORD County WATKINS
U.S.G.S. Quadrangle PITTSFORD
Stream Name EAGLE CANAL
Tributary of SENECA RIVER
Latitude (N) 43° 5' Longitude (W) 77° 32' 30"
Type of Dam LOCK
Hazard Category HIGH
Date(s) of Inspection 6/12/00
Weather Conditions SHINY
Reservoir Level at Time of Inspection 452.5 278.00
Tailwater Level at Time of Inspection 462.4

b. Inspection Personnel Tom ... (1-11)
Pat ... (170-5)

c. Persons Contacted (Including Address & Phone No.)
CLARENCE EICKHART, NYSDOT (716-442-8532)
DICK BAILEY, NYSDOT (716-442-8532)

d. History:
Date Constructed 1908 Date(s) Reconstructed _____
(Plans)
Designer NEW YORK STATE
Constructed by NEW YORK STATE
Owner NYSDOT

e. Seismic Zone 2

THOMSEN ASSOCIATES
CONSULTING GEOTECHNICAL ENGINEERS & GEOLOGISTS

VISUAL INSPECTION CHECKLIST

2) Embankment

a. Characteristics

- 1) Embankment Material EARTH
- 2) Cutoff Type NONE
- 3) Impervious Core NONE
- 4) Internal Drainage System NONE
- 5) Miscellaneous _____

b. Crest

- 1) Vertical Alignment GOOD
- 2) Horizontal Alignment GOOD
- 3) Surface Cracks NONE NOTED
- 4) Miscellaneous _____

c. Upstream Slope

- 1) Slope (Estimate) (V:H) VARIES. ALL APPEAR STABLE
- 2) Undesirable Growth or Debris, Animal Burrows NONE NOTED
- 3) Sloughing, Subsidence or Depressions NONE NOTED

THOMSEN ASSOCIATES
CONSULTING GEOTECHNICAL ENGINEERS & GEOLOGISTS

VISUAL INSPECTION CHECKLIST

4) Slope Protection SLOPE: VEGETATED

5) Surface Cracks or Movement at Toe UNOBSERVABLE

d. Downstream Slope

1) Slope (Estimate - V:H) VARIES ALONG LENGTH STABLE

2) Undesirable Growth or Debris, Animal Burrows _____

NONE NOTED

3) Sloughing, Subsidence or Depressions _____

NONE NOTED

4) Surface Cracks or Movement at Toe _____

UNOBSERVABLE

5) Seepage NONE NOTED

6) External Drainage System (Ditches, Trenches; Blanket)

NONE OTHER THAN SPILLWAY

7) Condition Around Outlet Structure _____

GENERALLY GOOD

8) Seepage Beyond Toe UNOBSERVABLE

e. Abutments-Embankment Contact

THOMSEN ASSOCIATES
CONSULTING GEOTECHNICAL ENGINEERS & GEOLOGISTS

VISUAL INSPECTION CHECKLIST

1) Erosion at Contact None Noted

2) Seepage Along Contract None Noted

3) Drainage System

a. Description of System N.A.

b. Condition of System N.A.

c. Discharge from Drainage System N.A.

4) Instrumentation (Monumentation/Surveys, Observation Wells, Weirs, Piezometers, Etc.)

2 Staff Gages - 100'-1100' 1 Piezometer

THOMSEN ASSOCIATES
CONSULTING GEOTECHNICAL ENGINEERS & GEOLOGISTS

VISUAL INSPECTION CHECKLIST

5) Reservoir

- a. Slopes GENERALLY GOOD
- b. Sedimentation UNOBSERVABLE
- c. Unusual Conditions Which Affect Dam NONE NOTED

6) Area Downstream of Dam

- a. Downstream Hazard (No. of Homes, Highways, etc.) SEVERAL HOMES
- b. Seepage, Unusual Growth NONE NOTED
- c. Evidence of Movement Beyond Toe of Dam NONE NOTED
- d. Condition of Downstream Channel GENERALLY GOOD

7) Spillway(s) (Including Discharge Conveyance Channel)

- a. General FLASHBOARDS; 5 GATES EACH 8.5' WIDE; GREST VARIABLE 487.5 - 490.0; 50' WIDE; 1000'S LONE
- b. Condition of Service Spillway

THOMSEN ASSOCIATES
CONSULTING GEOTECHNICAL ENGINEERS & GEOLOGISTS

VISUAL INSPECTION CHECKLIST

c. Condition of Auxiliary Spillway N.A.

d. Condition of Discharge Conveyance Channel GOOD

8) Reservoir Drain/Outlet (BYPASS)

Type: Pipe _____ Conduit _____ Other TUNNEL

Material: Concrete _____ Metal _____ Other BRICK

Size: 5' x 7' Length APPROX. 700'

Invert Elevations: Entrance 467.0 Exit 461.9

Physical Condition (Describe): Unobservable X

Material: _____

Joints: _____ Alignment _____

Structural Integrity: _____

Hydraulic Capability: _____

Means of Control: Gate _____ Valve X Uncontrolled _____

Operation: Operable X Inoperable _____ Other _____

Present Condition (Describe): APPARENTLY GOOD

THOMSEN ASSOCIATES

CONSULTING ENGINEERS

9) Structural

a. Concrete Surfaces SOME DETRIORATION

b. Structural Cracking NONE NOTED

c. Movement - Horizontal & Vertical Alignment (Settlement)

NONE NOTED

d. Junctions with Abutments or Embankments

AVERAGE GOOD

e. Drains - Foundation, Joint, Face N.A.

f. Water Passages, Conduits, Sluices AVERAGE GOOD

g. Seepage or Leakage SOME NOTED THROUGH

LOCK GATES

THOMSEN ASSOCIATES

CIVIL AND MECHANICAL ENGINEERS

h. Joints - Construction, etc. APPEAR GOOD

i. Foundation UNOBSERVABLE

j. Abutments GOOD

k. Control Gates GENERALLY GOOD

l. Approach & Outlet Channels GOOD

m. Energy Dissipators (Plunge Pool, etc.) N.A.

n. Intake Structures SOME CONCRETE DEGRADATION

o. Stability _____

p. Miscellaneous _____

APPENDIX C

HYDROLOGIC/HYDRAULIC:
ENGINEERING DATA AND COMPUTATIONS

L3 x 32

HYDROLOGIC / HYDRAULIC ANALYSES

DETERMINE MAXIMUM SPILLWAY CAPACITY
(WITH WATER SURFACE AT TOP OF WALLS,
ELEV. 490).

USE ORIFICE DISCHARGE EQUATION

$$Q = CA \sqrt{2gH}$$

$$C = 0.7$$

$$A = (5)(8.5)(4) = 170 \text{ FT}^2$$

$$g = 32.2 \text{ FT/SEC}^2$$


$$H = 490.0 - 487.5 = 2.5 \text{ FT}$$

$$Q = (0.7)(170) \sqrt{(2)(32.2)(2.5)} = \underline{\underline{1510 \text{ CFS}}}$$

1 - 200 2/25/51


APPENDIX D

DRAWINGS






TOPOGRAPHIC MAP
LOCK 32 ERIE CANAL
I.D. NO. N.Y. 791

LOCK SITE




VICINITY MAP
LOCK 32 ERIE CANAL
I.D. NO. N.Y. 791



PLAN
 DETAIL OF SPILLWAY
 SCALE 1"=50'
 Scale of Sections 1"=16'
 Note: Arrows indicate down slope. For all numbered sections see sheet No. 25. Round piles not shown on sections.

DRAWN BY E. C. ...
 CHECKED BY ...
 DATE ...



TYPICAL SECTION OF APPROACH
SCALE 1"-16'0"

NOTE:
Lining not to be put in place
until the rock has been
in position one year.


The center line of Lock No. 32
is assumed. The lock is 200' long
the actual center line of approach is 200'

If the present highway is staged continue the wooden fence to bottom of the approach and
connect it with the existing fence by a suitable iron bars gate about 200' long
provided with hinges and latch. Gate to be estimated and paid for at the contract
price for wooden fence.
This applies to all Sludge Approaches on this contract

Contract No. 23.


Erie Canal Section 9.
From Kings Bend to the Genesee River.
LAYOUT PLAN & SECTIONS OF LOCK 32
& VICINITY SHOWING PROTECTION WORK

Scale, as indicated.
Feather, Lead, etc.
L. J. ...



MADE BY F.C. Thomas
 TRACED BY J.N. Stone 6-12-08
 1ST CHECK BY G.W. [unclear] 7-1-08
 2ND CHECK BY R.E. Phillips 6-18-08

Scale of Sections - P. 16



Excavation Plan
240.0'

3 blocks @ 26.8' - 240.0'
58 spaces @ 2.8' - 26.8'

Class C Piles

Class B Piles from breast wall to land end of needle beam (Center)


Class C Piles

PILE PLAN

Elevations refer to bottom of concrete.
 Round piles to be cut 1.6' above elevations shown.
 Length of round piles to be determined by test driving according to specifications.
 In case however local conditions are found such that the specified penetration is exceeded, the State Engineer may direct the contractor to drive such additional piles as may be necessary, or to spread and reinforce the footings or to use both methods in order to obtain a stable foundation. All such work shall be done at contractor's expense, subject to the requirements of the contract regarding alterations.

Triple lap steel piling
 See also
 Within
 for one
 in place
 Spacing
 so req'd
 emb'd
 Top of
 excav
 Sec 5

MADE BY Underhill & Co
 TRACED BY J.K. Reed S.I.C.
 1ST CHECK BY O.P. Bullen S.I.C.
 2ND CHECK BY J.C. Kelly S.I.C.



EXCAVATION PLAN

240.0"
 3 blocks @ 26.8' = 240.0"
 30 spaces @ 2.8' = 261.6"

Class C Piles

breast wall to lower end of needle sill Notched as shown in detail see sheet No. 56
 Center Line of Lock

43 spaces @ 4.0' = 172.0"

Class C Piles

8 blocks @ 26.8' = 214.4"

30 spaces @ 2.8' = 261.6"


PILE PLAN

Triple lap sheet piling to be 3 pieces of 2" plank 10 or 12 inches wide
 See detail Sheet No. 56
 Within the boundaries of the structure where different elevations
 for excavation are encountered the material shall be held
 in place by sheeting where so directed.
 Spaces under and around masonry shall be backfilled, where
 so required, with material placed as specified for forming
 embankment
 Top of wooden sheet piling shall be embedded 12" in concrete
 except where otherwise noted.
 See Special Specifications for clause about omitting piles.



Contract No. 23.
 Erie Canal Section 9.
 From Kings Bend to the Genesee River.
FOUNDATION PLAN OF LOCK 32

Scale: 16 feet to the inch.

Prepared and approved
 J. J. ...
 190



SECTIONAL ELEVATION



REAR ELEVATION




Sheeting shall be used during construction, as far as practicable, to maintain surfaces marked "C".

The following sections shall be built as a monolith and mark once begun thereon shall be continued without interruption until the section is completed viz:-
 Side wall between limits of X1, X2, X3 & X4 from El. 457.9 to El. 465.9
 Y1, Y2, Y3 & Y4 El. 480.0 to El. 491.0
 Both thrust walls bet. Stns. 2154+52 & 2154+92 El. 484.0 to El. 490.0
 2157+33.5 & 2158+25.5 El. 486.0 to El. 490.0

The floor shall be built dividing lines at right angles of lock. Each section shall monolith.
 The bases of structures of plans of this contract shall be approximate only, and the State Engineer in his elevation and of any dimension a proper foundation.

Spaces under and around masonry shall be back filled, where so required, with material placed as specified for forming embankment

MADE BY O.F.B. 3-22
 TRACED BY J.H. 4-22-20
 1ST CHECK BY W.H. 7-11
 2ND CHECK BY R.L. 7-12



The floor shall be built in sections with dividing lines at right angles to center line of lock. Each section shall be built as a monolith.


The bases of structures shown on any of the plans of this contract shall be considered as approximate only, and may be ordered by the State Engineer in writing to be at any elevation and of any dimensions necessary to give a proper foundation.

For directions relating to modification of foundations see sheet No. 30
For detailed dimensions of Lock ends see sheet No. 33 & 34
Top of Lock walls to be crowned 1/4 inch.
Top edges of all walls are to be rounded to a radius of 2" unless otherwise shown
For reinforcement of toe of chamber walls, and lower thrust walls see sheet No. 32 & 35

Contract No. 23.
Erie Canal Section 9.
From Kings Bend to the Genesee River.
PLAN & ELEVATION OF LOCK 32
Scale: 16 feet to 1 inch.

Examined and approved,
Special Inspector
State Engineer

2




For reinforcement see sec. C-C

D-D

Keyways shall not be closer to each other or to the face of walls than one foot and not closer to the top of walls than two feet

H-H


For reinforcement see sec. J-J




In each of the 12 pile spaces under the lower gate recesses use 4 def bars 0.77" dia sec 8.0 long spaced about 5' c/c and 3' from bottom of concrete. Also under each recess use 3 longitudinal bars 0.77" dia sec 25.0 long placed as shown. See also detail on sheet N° 58

C-C

G-G




B-B



F-F

See note on sheet No 56 regarding brick and cast iron linings



A-A









For reinforcement see sec. J-J

E-E

MADE BY O.S. [unclear] 3-28
 TRACED BY J.H. [unclear] 9-20-21
 1ST CHECK BY Underhill
 2ND CHECK BY [unclear] 1-28

Masonry shown on this sheet shall be second class concrete except where otherwise shown as reinforced concrete
 Top of lock walls to be crowned 3/8 inch

Top edges of all walls are to be rounded to a radius of 2 inches unless otherwise shown
 For directions relating to modification of foundations see sheet N° 30
 For additional notes see Lock Drawing Sheet N° 31










SYMBOLS

- 2nd Class Concrete
- Reinforced Concrete
- 2nd Class Concrete

Contract No. 23.
Erie Canal Section 9.
 From Kings Bend to the Genesee River.
SECTIONS OF LOCK 32
 Scale: 16 feet to the inch.










In each pile space under toe of chamber wall from the lower gate recess to angle of breast wall use 4 steel bars 0.75" net section 10.0 long spaced about 6" C to C and 3" from bottom of concrete; also place three rows of bars 0.75" net section with ends lapped not less than 3.0' spaced as shown. See also retention sheet N-59

Examined and approved
[Signature]
 State Engineer



MADE BY T. C. Thomas
 DRAWN BY G. J. [unclear]
 IN CHARGE [unclear]
 ENGINEERING CO. [unclear]

REAR ELEVATION OF SOUTH WALL OF SPILLWAY DEVELOPED
 Scale 1/8" = 1'-0"




Contract No. 23.

Erie Canal Section 9.


From Kings Bend to the Genesee River.

UPPER GUIDE WALL & UPPER SPILLWAY LOCK 32

Scales as indicated.
Examined and approved
Wm. H. ...
Special Deputy State Engineer






Triple lap sheet piling 3 pieces 27'
10' or 12' wide 16.0' long if practical



All organic base or unsuitable material beneath the structure shall be removed and back fill the proper elevation with embankment well tamped.
All masonry must be back filled before water to an extent sufficient to protect foundations from Length of foundations to be determined by test piling according to special conditions.
Piles shown on this sheet to be of Class B. No special specifications.
The bases of structures shown on any of the plans of this contract shall be considered as final only and may be ordered by the Side Engineer in writing to be any elevation and of any dimensions necessary to give a proper foundation.
For detail of sheet piling see sheet No. 54.
Pile heads are indicated thus: .
Top of sheet piling shall be embedded 12" in concrete.

N. - See note on sheet No. 56 regarding the omission of the brick and cast iron lining in the by pass culvert.



Filling for 6" in front of wall must be thoroughly rammed. All filling in front of wall must be done before the embankment back of wall is carried above El. 476.0



Reinforcing bars 0.39" net sec. 40' long, placed as shown.

21 de' bars 0.39" net sec. 6.0' long, 1.0' c/c vertically from El. 473.5 to El. 475.5 and 6' from face.



MADE BY F.C. Hammer
CHECKED BY K. Long, June 1911
1st CHECK BY J. G. ...
2nd CHECK BY J. C. Phelps, 6.15.11

Scale 1"=8'




SECTION RECESS



When the structure shall be removed and back filled to suit well summed
 concrete sufficient to protect foundations from frost
 according to special conditions
 No. B
 special spec. sections
 the plans of this contract shall be considered as appropriate
 in writing to be at any elevation and of
 sheet N° 11
 finished in concrete




No. 36 regarding the omission of the
 drawings in 1st by pass culvert




Contract No. 23.
 Erie Canal Section 9.
 From Kings Bend to the Genesee River.
UPPER GUIDE WALL & UPPER SPILLWAY LOCK 32
 Scales as indicated.


Examined and approved
[Signature]
 Special Deputy State Engineer




REAR ELEVATION OF LOWER GUIDE WALL (with outlet removed)
Scale 1"=16'-0"




PLAN




PILE FOUNDATION PLAN
Scale 1"=16'-0"




DETAIL OF FORM FOR KEYWAYS
Scale 1"=1'-0"




SECTION SHOWING
THROUGH LOWER DRAIN PIPE
Scale 3/4"=1'-0"



Scale 3/4"=1'-0"







DETAIL OF SHUDDING
POST SETTING
Scale 1:80"



SECTION ON CENTER LINE
Scale 1"=8'-0"

DETAIL OF OUTLET

Made by: P. C. ...
Drawn by: P. C. ...
Checked by: W. ...
Approved by: ...



SCALE OF SECTIONS
1" = 8'-0"

NOTES:


- All masonry shown on this sheet shall be second class concrete
- Top edges of all walls are to be finished to a radius of two inches unless otherwise shown
- Structural steel and spacing of masonry shall be provided where so required with material furnished at special cost for 100' long 10" to c.
- The bases of structures shown on the plans shall be considered as approximate only and may be ordered by the State Engineer in writing to be at any elevation and of any dimension necessary for a proper foundation.
- Pile heads are indicated thus \cup . Length of piles to be determined by test driving according to specifications. Piles shown on this sheet to be of class B.
- For detail of ladder and recess see sheet No. 56. For detail of scrubbing post see sheet No. 56.
- If the sheet piling prove insufficient for bearing, the contractor shall upon order of the State Engineer drive additional round piles of suitable length and number at the contract price therefor.
- For details of sheet piling see sheet No. 56.
- For detail of of cast iron angle see sheet No. 49.
- For detail of cast iron Elbows see sheet No. 49.

Contract No. 23.
Erie Canal Section 9.
 From Kings Bend to the Genesee River.
LOWER GUIDE WALL & BY-PASS OUTLET
LOCK 32


Scales as indicated.

Examined and approved
Wm. B. ...
 Special Deputy State Engineer


2



ELEVATION OF BREAST WALL









PLAN





SECTION ON A-A

DRAWN BY: J. L. Moorey
 TRACED BY: J. L. Moorey
 CHECKED BY: J. L. Moorey




DETAIL OF FORM FOR KEYWAYS
Scale 1"=10"



for detail of protection work see sheets 24225

All masonry shown on this sheet to be 2nd Class concrete
The bases of structures shown on this plan shall be considered as approximate only and they be ordered by the State Engineer in writing to be at any elevation and of any dimensions necessary to give a proper foundation.

All exposed edges to be rounded to a radius of 2" unless otherwise shown.
All organic matter loose or unsuitable material beneath the structures shall be removed and back filled to the proper elevation, with an embankment thoroughly rammed.
Lining must not be placed until the material on which it rests shall have been in place 12 months.



Contract No. 23.
Erie Canal Section 9.
From Kings Bend to the Genesee River.
LOWER SPILLWAY & CULVERT UNDER KINGSLEY ROAD LOCK 32

Scales as indicated.

Examined and approved
Special Deputy State Engineer