


AD-A096 058

O'BRIEN AND GERE ENGINEERS INC PHILADELPHIA PA F/G 13/13  
NATIONAL DAM SAFETY PROGRAM. LAKE COMO DAM (DE 00028), DELAWARE--ETC(U)  
NOV 80 J J WILLIAMS DACW61-80-0-0013

UNCLASSIFIED

DAEN/NAP-53842/DE00028-80/ NL

179  
200 0





REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER 18 DAEN/NAD 53842/DE00028-80/11	2. GOVT ACCESSION NO. AD-104605	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Inspection Report National Dam Safety Program Lake Como Dam Kent County, Delaware	5. TYPE OF REPORT & PERIOD COVERED FINAL	
	6. PERFORMING ORG. REPORT NUMBER	
7. AUTHOR(s) JOHN J. WILLIAMS, P.E.	8. CONTRACT OR GRANT NUMBER(s) DACW61-80-D-0013	
9. PERFORMING ORGANIZATION NAME AND ADDRESS O'Brien & Gere Engineers, Inc. Suite 1760 1617 J.F. Kennedy Blvd. Philadelphia, PA 19103	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS	
11. CONTROLLING OFFICE NAME AND ADDRESS U.S. Army Engineer District, Philadelphia Custom House, 2d & Chestnut Streets Philadelphia, Pennsylvania 19106	12. REPORT DATE Nov 1980	
	13. NUMBER OF PAGES 65	
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) National Dam Safety Program, Lake Como Dam (DE 00028), Delaware River Basin, Mill Creek, Kent County, Delaware. Phase I Inspection Report.	15. SECURITY CLASS. (of this report) Unclassified	
	15a. DECLASSIFICATION/DOWNGRADING SCHEDULE	
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Copies are obtainable from National Technical Information Service, Springfield, Virginia, 22151.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dams National Dam Safety Program Embankments Lake Como Dam, DE Visual Inspection Spillways Structural Analysis		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report cites results of a technical investigation as to the dam's ade- quacy. The inspection and evaluation of the dam is as prescribed by the National Dam Inspection Act, Public Law 92-367. The technical investigation includes visual inspection, review of available design and construction records, and preliminary structural and hydraulic and hydrologic calculations, as applicable. An assessment of the dam's general condition is included in the report.		

AD-104605

**NOTICE**

**THIS DOCUMENT HAS BEEN REPRODUCED  
FROM THE BEST COPY FURNISHED US BY  
THE SPONSORING AGENCY. ALTHOUGH IT  
IS RECOGNIZED THAT CERTAIN PORTIONS  
ARE ILLEGIBLE, IT IS BEING RELEASED  
IN THE INTEREST OF MAKING AVAILABLE  
AS MUCH INFORMATION AS POSSIBLE.**



DEPARTMENT OF THE ARMY  
PHILADELPHIA DISTRICT, CORPS OF ENGINEERS  
CUSTOM HOUSE-2 D & CHESTNUT STREETS  
PHILADELPHIA, PENNSYLVANIA 19106

①

IN REPLY REFER TO

NAPEN-N

**LEVEL**

17 FEB 1981

Honorable Pierre S. DuPont  
Governor of Delaware  
Dover, Delaware 19901

SDTIC  
ELECTED  
MAR 6 1981

Dear Governor DuPont:

Inclosed is the Phase I Inspection Report for Lake Como Dam in Kent County, Delaware which has been prepared under authorization of the Dam Inspection Act, Public Law 92-367. A brief assessment of the dam's condition is given in the front of the report.

Based on visual inspection, available records, calculations and past operational performance, Lake Como Dam, a significant hazard potential structure, is judged to be in poor overall condition. Also, the spillway is considered inadequate since nine percent of the Spillway Design Flood (SDF) would cause the dam to be overtopped. (The SDF, in this instance, is one-half of the Probable Maximum Flood.) The dam's stability is considered questionable by personnel (Consulting Engineer's Staff, State and Federal Engineers) who inspected this structure. To ensure adequacy of the structure, the following actions, as a minimum are recommended:

a. Within thirty days from the date of approval of this report, the following remedial actions should be initiated:

(1) Ownership of and maintenance responsibility for the dam should be clarified.

(2) A registered professional engineer experienced in the design and construction of dams should be engaged by the owner to:

(a) Perform more detailed hydrologic and hydraulic analysis to determine what measures are required to provide adequate spillway discharge capacity and/or to protect the embankment from overtopping.

APPROVED FOR PUBLIC RELEASE;  
DISTRIBUTION UNLIMITED.

NAPEN-N

Honorable Pierre S. Dupont

(b) Design and supervise construction of repairs to the existing embankment section.

(c) Design and supervise the construction of erosion protection for the upstream and downstream slopes of the dam and outlet channel.

(d) Provide guidance to the owner for removal of the trees and utility poles from the embankment and the backfilling of voids with suitable, thoroughly compacted material.

(e) Provide guidance to the owner for removal of the water and gas lines from the dam and their relocation.

b. The owner should maintain the reservoir elevation 3 feet below the spillway crest until permanent repairs are completed.

c. Continuous monitoring of reservoir levels during periods of heavy precipitation should be undertaken until permanent repairs are completed.

d. The owner should develop written operating procedures and a periodic maintenance plan to ensure the safety of the reconstructed facilities, within one year from the date of their completion.

e. An emergency action plan should be developed which outlines actions to be taken by the Owner to minimize the downstream effects of an emergency at the dam within six months from the date of approval of this report.

A copy of the report is being furnished to Mr. John E. Wilson III, Delaware Department of Natural Resources and Environmental Control, the designated State Office contact for this Program. Within five days of the date of this letter, a copy will also be sent to Congressman Thomas B. Evans. Under the provisions of the Freedom of Information Act, the inspection report will be subject to release by this office, upon request, thirty days after the date of this letter.

Additional copies of this report may be obtained from the National Technical Information Services (NTIS), Springfield, Virginia, 22161 at a reasonable cost. Please allow four to six weeks from the date of this letter for NTIS to have copies of the report available.

Accession For	
NTIS	<input type="checkbox"/>
DTIC	<input type="checkbox"/>
Unannounced	
Justification	
By	
Distribution/	
Availability Codes	
Available or	
Dist	
	<b>A</b>

NAPEN-N

Honorable Pierre S. Dupont

An important aspect of the Dam Inspection Program will be the implementation of the recommendations made as a result of the inspection. We accordingly request that we be advised of proposed actions taken by the State to implement our recommendations.

Sincerely,



JAMES G. TON  
Colonel, Corps of Engineers  
District Engineer

1 Incl  
As stated

Copies Furnished:

Mr. John E. Wilson III, Acting Secretary  
Department of Natural Resources and  
Environmental Control  
Edward Tatnall Bldg.  
Dover, DE 19901

Mr. Melvin H. Koster, Acting Director  
Division of Soil & Water Conservation  
Department of Natural Resources and  
Environmental Control  
Dover, DE 19901

LAKE COMO DAM (DE00028)

CORPS OF ENGINEERS ASSESSMENT OF GENERAL CONDITIONS

This dam was inspected on 12 August 1980 by Corps and State personnel and by O'Brien and Gere Engineers, Inc., under contract to the U.S. Army Engineer District, Philadelphia, in accordance with the National Dam Inspection Act, Public Law 92-367.

The inspection of Lake Como Dam was requested by the State of Delaware in response to its overtopping on 29 July 1980. As a result of this inspection, Lake Como Dam, is judged to be in an UNSAFE, non-emergency condition until corrective measures are completed. This condition, erosion and partial failure of the downstream half of the embankment and the east outlet channel slope, if left uncorrected, could result in complete failure of the dam and further property damage. Until further study could determine the full extent of the problem and possible permanent corrective actions, immediate remedial recommendations were made to preclude further property damage. The Governor and his representative and the Delaware Division of Highways were notified of this condition and the recommended immediate remedial actions by telegram on 19 August 1980. (Also, a teletype report was submitted to the U.S. Army Engineer Division, North Atlantic, on 29 July 1980.) The representative of the town of Smyrna indicated that the lake will be maintained in a drawn down condition until corrective measures are completed.

Lake Como Dam, a significant hazard potential structure, is judged to be in poor overall condition. Also, the spillway is considered inadequate since nine percent of the Spillway Design Flood (SDF) would cause the dam to be overtopped. (The SDF, in this instance, is one-half of the Probable Maximum Flood.) The dam's stability is considered questionable by personnel (Consulting Engineer's Staff, State and Federal Engineers) who inspected this structure. To ensure adequacy of the structure, the following actions, as a minimum are recommended:

a. Within thirty days from the date of approval of this report, the following remedial actions should be initiated:

(1) Ownership of and maintenance responsibility for the dam should be clarified.

(2) A registered professional engineer experienced in the design and construction of dams should be engaged by the owner to:

(a) Perform more detailed hydrologic and hydraulic analysis to determine what measures are required to provide adequate spillway discharge capacity and/or to protect the embankment from overtopping.



(b) Design and supervise construction of repairs to the existing embankment section.

(c) Design and supervise the construction of erosion protection for the upstream and downstream slopes of the dam and outlet channel.

(d) Provide guidance to the owner for removal of the trees and utility poles from the embankment and the backfilling of voids with suitable, thoroughly compacted material.

(e) Provide guidance to the owner for removal of the water and gas lines from the dam and their relocation.


b. The owner should maintain the reservoir elevation 3 feet below the spillway crest until permanent repairs are completed.

c. Continuous monitoring of reservoir levels during periods of heavy precipitation should be undertaken until permanent repairs are completed.

d. The owner should develop written operating procedures and a periodic maintenance plan to ensure the safety of the reconstructed facilities, within one year from the date of their completion.

e. An emergency action plan should be developed which outlines actions to be taken by the Owner to minimize the downstream effects of an emergency at the dam within six months from the date of approval of this report.

APPROVED:

  
\_\_\_\_\_  
JAMES G. TON

Colonel, Corps of Engineers  
District Engineer

DATE:

17 Feb 1981

UNSAFE DAM

NATIONAL PROGRAM OF INSPECTION OF DAMS

a. NAME: Lake Como Dam b. ID NO.: DE00028 c. LOCATION State: Delaware. County: Kent.

d. HEIGHT: 12 feet e. MAXIMUM IMPOUNDMENT CAPACITY: 312 ac. ft.  
River or Stream: Mill Creek.  
Nearest D/S City or Town: Smyrna.

f. TYPE: Roadway Embankment.

g. OWNER: Unknown, Town of Smyrna and Delaware Division of Highways appear to have joint ownership.

h. DATE GOVERNOR NOTIFIED OF UNSAFE CONDITIONS: 19 Aug 80.

i. URGENCY CATEGORY: UNSAFE, Non-Emergency, Significant Hazard.  
CONDITION OF DAM RESULTING IN UNSAFE ASSESSMENT: Dam was overtopped and suffered severe erosion of downstream embankment and outlet channel.

m. EMERGENCY ACTIONS TAKEN:

Embankment was sandbagged by local volunteers to prevent further erosion.

j. REMEDIAL ACTIONS TAKEN: Lake was drawn down until remedial measures are completed.  
DESCRIPTION OF DANGER INVOLVED: Significant Hazard potential. Overtopping and failure of the dam poses significant hazard potential to loss of life and property downstream of dam at Route 13 Highway Bridge, small private luncheonette and sewage pumping plant.

o. REMARKS: Delaware Highway Department is undertaking repair to the structure to reopen Main Street.

k. RECOMMENDATIONS GIVEN TO GOVERNOR:

Within 30 days of the date of the District Engineer's letter, the owner should do the following:

- (1) Lower the lake level three feet.
- (2) Engage the services of a qualified professional consultant to more accurately determine the spillway adequacy by using more detailed and sophisticated hydrologic and hydraulic analyses, and to recommend any remedial measures required to prevent overtopping of the dam.
- (3) Develop a detailed emergency operation plan and downstream warning system. Provide around the clock surveillance during periods of unusually heavy precipitation.
- (4) Monitor the dam and inspect for additional seepage or sloughing.
- (5) Make soil borings and a topo-survey.
- (6) Relocated gas and water lines from the embankment
- (7) Design an adequate embankment section.

T.B. HEVERIN, Coordinator  
Dam Inspection Program

DELAWARE RIVER BASIN

NAME OF DAM: LAKE COMO DAM  
COUNTY AND STATE: KENT, DELAWARE  
INVENTORY NUMBER: DE00028

PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM

Prepared by:  
O'BRIEN & GERE ENGINEERS, INC.

For

DEPARTMENT OF THE ARMY  
Philadelphia District, Corps of Engineers  
Custom House - 2nd & Chestnut Streets  
Philadelphia, Pennsylvania 19106

## PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I Investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonable possible storm runoff), or fractions thereof. The test flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

PHASE I REPORT  
NATIONAL DAM INSPECTION PROGRAM

Name of Dam:	Lake Como Dam ID#DE.00028
State Located:	Delaware
County Located:	Kent
Stream:	Mill Creek
Coordinates:	Latitude 39° 17.8', Longitude 75° 36'
Date of Inspection:	August 12, 1980

ASSESSMENT

Based on visual observations made during the inspection (which followed overtopping and partial failure of the dam on July 29, 1980), information provided by the Town of Smyrna, and conversations with town officials, Lake Como Dam is considered to be in poor overall condition.

The dam is an earth embankment approximately 240 feet long with a maximum height of about 12 feet. The top width of the dam is about 60 feet and the upstream and downstream slopes are relatively steep. The spillway consists of five circular drop inlets, each with a diameter of 27 inches, which provide about 3 feet of freeboard between the spillway crest and the top of the dam.

The downstream half of the embankment eroded away by as much as five feet when the dam was overtopped on July 29, 1980. One section of the failure zone extends nearly through the embankment and has been backfilled with sandbags. A large section of the east outlet channel slope was also eroded away. A ruptured gas line and a water main were exposed in the erosion zone. Small trees were growing on the embankment and utility poles have been installed on the dam.

The selected Spillway Design Flood (SDF) for this "Small" size, "Significant" hazard dam is one-half of the Probable Maximum Flood (PMF). Examination of the results of the hydrologic and hydraulic analyses indicates that the spillway is capable of discharging approximately 8 percent of the SDF prior to overtopping of the embankment. Failure of the dam would cause appreciable property damage downstream. Therefore, the spillway is classified as "Inadequate", and the dam is classified as "Unsafe, non-emergency".


Recommendations and remedial measures which should be initiated immediately are as follows:


a. Facilities

1. Ownership and maintenance responsibility for the dam should be clarified.

A registered professional engineer experienced in the design and construction of dams should be engaged to:

1. Perform detailed hydrologic and hydraulic analyses to determine what measures are required to provide adequate spillway discharge capacity and/or to protect the embankment from overtopping.
  2. Design and supervise construction of repairs to the existing embankment section.
  3. Design and supervise the construction of erosion protection for the upstream and downstream slopes of the dam and outlet channel.
  4. Provide guidance to the Owner for the removal of trees and utility poles from the embankment and backfilling of voids with suitable, thoroughly compacted material.
  5. Provide guidance to the Owner for the removal of water and gas lines from the dam and their relocation.
- b. Operation and Maintenance Procedures
1. The Owner should maintain the reservoir elevation 3 feet below the spillway crest until permanent repairs are completed.
  2. Continuous monitoring of reservoir levels during periods of heavy precipitation should be undertaken until permanent repairs are completed.
  3. The Owner should employ a professional engineer experienced in operation and maintenance of dams to develop written operating procedures and a periodic maintenance plan to insure the safety of the reconstructed facilities.
  4. An emergency action plan should be developed which outlines actions to be taken by the Owner to minimize the downstream effects of an emergency.

  
John J. Williams, P.E.  
Vice President  
Delaware Registration No. 2884



Date: 20 JAN. 1981



UPSTREAM OVERVIEW LOOKING TOWARDS LEFT ABUTMENT  
(8/12/80)



DOWNSTREAM OVERVIEW SHOWING FAILURE ZONE AND SPILL-  
WAY OUTLET CONDUIT HEADWALL.  
(8/12/80)

## TABLE OF CONTENTS

	<u>PAGE</u>
Preface	i
Assessment	ii
SECTION 1 - PROJECT INFORMATION	
1.1    General	1
1.2    Project Description	1
1.3    Pertinent Data	2
SECTION 2 - ENGINEERING DATA	
2.1    Design	4
2.2    Construction	4
2.3    Operation	4
2.4    Evaluation	4
SECTION 3 - VISUAL INSPECTION	
3.1    Findings	5
SECTION 4 - OPERATIONAL PROCEDURES	
4.1    Procedures	6
4.2    Maintenance of Dam	6
4.3    Maintenance of Operating Facilities	6
4.4    Description of Any Warning System in Effect	6
4.5    Evaluation of Operational Adequacy	6
SECTION 5 - HYDRAULICS AND HYDROLOGY	
5.1    Evaluation of Features	7
SECTION 6 - STRUCTURAL STABILITY	
6.1    Evaluation of Structural Stability	9
SECTION 7 - ASSESSMENT, RECOMMENDATIONS, AND PROPOSED REMEDIAL MEASURES	
7.1    Dam Assessment	11
7.2    Recommendations and Proposed Remedial Measures	11



TABLE OF CONTENTS (cont.)

APPENDICES

APPENDIX A -	CHECKLIST, ENGINEERING DATA, DESIGN, CONSTRUCTION OPERATION, PHASE I
APPENDIX B -	CHECKLIST, VISUAL INSPECTION, PHASE I
APPENDIX C -	HYDROLOGIC AND HYDRAULIC DATA
APPENDIX D -	PHOTOGRAPHS
APPENDIX E -	DRAWINGS
APPENDIX F -	SITE GEOLOGY

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM  
LAKE COMO DAM  
INVENTORY NUMBER - DE 00028

SECTION 1

PROJECT INFORMATION

1.1 General

a. Authority. This report is authorized by the Dam Inspection Act, Public Law 92-367, and has been prepared in accordance with contract #DACW 61-80-D-0013 between O'Brien & Gere Engineers, Inc. and the United States Army Corps of Engineers, Philadelphia District.

b. Purpose of Inspection. The purpose of this inspection is to evaluate the structural and hydraulic condition of Lake Como Dam and appurtenant structures and to determine if the dam constitutes a hazard to human life or property.

1.2 Project Description (Based on information supplied by the Town of Smyrna, DE and supplemented by field observations.)

a. Description of Dam and Appurtenances. The following is a general description of the dam and appurtenances prior to its overtopping and partial failure on July 29, 1980. A detailed description of the structure after this event is given in Section 3, Visual Inspection. Lake Como Dam is an earth embankment approximately 240 feet long with a maximum height of about 12 feet. The top width of the embankment is about 60 feet and the upstream and downstream slopes are variable, ranging between 2H:1V and 1H:1V. A 30 feet wide asphalt concrete paved street is located along the entire embankment length.

The spillway consists of five 27-inch diameter concrete drop inlets provided with anti-vortex devices. Each drop inlet is connected to a 36-inch diameter reinforced concrete outlet pipe which terminates at a headwall at the downstream toe of the embankment. The outlet works consist of hand operated sluice gates situated upstream of two drop inlet structures. Access to the gate operators is across a timber bridge.

b. Location. Lake Como Dam is located on Mill Creek in the City of Smyrna, Delaware. The site is shown on USGS Quadrangle entitled "Smyrna, Del." at coordinates N39° 17.8', W75° 36'. A regional location map of Lake Como Dam is included as Figure 1 in Appendix E.

c. Size Classification. Lake Como Dam has a maximum height of 12 feet which places it in the "Small" size dam category since it is less than 40 feet high.

The maximum storage capacity of 312 acre-feet also places the structure within the "Small" size classification (less than 1,000 acre-feet). Lake Como Dam is therefore classified as a "Small" size dam.

d. Hazard Classification. A reinforced concrete bridge supporting U.S. Route 13 spans Mill Creek about 110 feet downstream of Lake Como Dam. Both the bridge deck and highway approach elevations are at or near the existing dam crest elevation. A restaurant is located adjacent to the right bank of Mill Creek between the dam and the highway bridge. The ground floor elevation of the restaurant is at the existing dam crest elevation. A sewage pumping station and treatment plant are located immediately downstream of the highway bridge within the potential floodplain. Since failure of the dam could result in appreciable property damage, Lake Como Dam is classified in the "Significant" hazard potential category.

e. Ownership. The owner of Lake Como Dam is unknown. According to Mr. Dean Phillips, Assistant Manager, Town of Smyrna, the Town has no record of ownership on file at their offices.

f. Purpose of Dam. The dam is used for recreation only.

g. Design and Construction History. Information is unavailable concerning the original design and construction of the dam. The only drawings made available for this report were those prepared by J.E. Haddaway Engineer dated March, 1941 which were prepared for reconstruction of the dam after its failure in 1940. The original date of construction is unknown.

i. Normal Operating Procedures. Records of operating procedures are unavailable for this site.

### 1.3 Pertinent Data

a. <u>Drainage Area.</u>	
Square Miles	6.8
b. <u>Discharge at Dam Site (cfs).</u>	
Spillway Capacity	184
c. <u>Elevation (Feet above MSL).</u>	
Spillway Crest (Normal Pool)	14.6
Top of Dam (Maximum Pool)	17.6
Streambed at Downstream Toe of Dam	6.0
d. <u>Reservoir Length (Feet).</u>	
Normal Pool	4,400
Maximum Pool	6,000

e. Storage (Acre-Feet).

Normal Pool	138
Maximum Pool	312

f. Reservoir Surface Area (Acres).

Normal Pool	46
Maximum Pool	71

g. Dam Data.

Type	Earth
Length	240 Feet
Height	12 Feet
Top Width	60 Feet
Side Slopes (Upstream and Downstream)	Variable, 1H:1V Steepest
Zoning	None
Impervious Core	None
Cutoff	None
Grout Curtain	None

h. Spillway.

Type	5 Circular Drop Inlets
Crest Diameter	27 Inches
Crest Elevation	14.6
Outlet Diameter	36 Inches
Outlet Invert Elevation	6.0
Gates	None
Upstream Channel	None
Downstream Channel	Trapezoidal concrete and brick-lined channel to R/C bridge to Mill Creek

i. Outlet Works.

Type	2-36 inch diameter concrete pipes
Length	90 Feet
Closure	36"x44" sluice gates
Access	Timber-decked bridge
Regulating Facility	Hand-operated rising stems

SECTION 2  
ENGINEERING DATA

2.1 Design.

a. Data Available. Information available for review is limited to drawings entitled "DROP INLET SPILLWAY, LAKE COMO" sheets 1 and 2, dated March, 1941 by J.E. Haddaway Engineer. No design data is available for this structure.

b. Design Features. The principal design features for this structure are discussed in Section 1.2a.

2.2 Construction.

Information is unavailable relative to the original construction or reconstruction of Lake Como Dam in 1941.

2.3 Operation.

No operational data is available for this site.

2.4 Evaluation.

a. Availability. All information made available was provided by the Town of Smyrna.

b. Adequacy. The information made available by the Town of Smyrna, conversations with city officials and observations made during the field investigations provided adequate data for a Phase 1 evaluation.

c. Validity. The drawings prepared by J.E. Haddaway Engineer are not a valid representation of the present structure. Refer to Section 1.2a for a description of the dam and appurtenances.

SECTION 3  
VISUAL INSPECTION

3.1 Findings.

a. General. The field inspection of Lake Como Dam took place on August 12, 1980. At the time of inspection, the reservoir water surface was approximately 15 inches below the spillway crest elevation. No underwater areas were inspected. The observations and comments of the field inspection team are in the checklist which is Appendix B of this report. The embankment had experienced overtopping and partial failure on July 29, 1980.

b. Dam. The overtopping which occurred on July 29, 1980, resulted in erosion of about five feet of the downstream half of the embankment. Large sections of the 40-foot wide concrete and asphalt street paving within the failure zone had collapsed and were lying on the embankment fill. The entire downstream slope had been eroded away. One section of the failure zone near the right abutment extended almost to the crest of the upstream slope and was backfilled with sandbags. A six-inch water main and ruptured four-inch diameter gas line were exposed within the dam failure zone. The upstream slope was not damaged even though it is unprotected by riprap or other slope protection. The embankment crest upstream of the street is grass covered except for a sidewalk. Two trees with trunk diameters of about six inches were growing on the dam crest. Two power utility poles have been installed in the dam crest upstream of the sidewalk. No seepage was observed flowing from the failure zone.

c. Appurtenant Structures. The five circular concrete drop inlets, the wooden access bridge and gate operators for the low-level outlet works were not damaged during the overtopping failure. The outlet conduits and headwall downstream of the dam were in fair condition. The operators for the low-level outlets were in serviceable condition and were being used to lower the reservoir level. The deck elevation of the access bridge is about 18 inches below the dam crest elevation.

d. Reservoir Area. The reservoir slopes are very gentle and are grass and tree covered. No indications of slope instability were observed.

e. Downstream Channel. A large section of the east slope of the stream channel downstream of the headwall between the dam and the highway bridge has been eroded away. The cascading concrete outlet apron extending downstream of the headwall was in good condition. The concrete and brick-lined west channel slope was severely damaged but had not allowed the occurrence of significant erosion.

SECTION 4  
OPERATIONAL PROCEDURES

4.1 Procedures

No formal operating procedures have been established for Lake Como Dam.

4.2 Maintenance of Dam

The grass on the embankment is cut on a regular basis during the growing season.

4.3 Maintenance of Operating Facilities

The operators for the low-level outlets are maintained in a serviceable condition.

4.4 Description of Any Warning System in Effect

No formal warning system exists for this site.

4.5 Evaluation of Operational Adequacy

A periodic inspection and maintenance program should be implemented and a formal warning system should be established.

## SECTION 5

### HYDRAULICS AND HYDROLOGY

#### 5.1 Evaluation of Features

a. Design Data. No hydrologic or hydraulic data was available for review. Lake Como has a drainage area of 6.8 square miles. The spillway at Lake Como Dam has an estimated discharge capacity of 184 cfs.

For further information, refer to the calculations and computer printout included in Appendix C of this report.

b. Experience Data. No rainfall or reservoir level records are maintained at this site. The locally heavy rains which caused the overtopping of Lake Como Dam on July 29, 1980, were measured by the U.S. Weather Service to be in excess of 5 inches with 4 inches falling between 5:00 and 6:00 a.m. According to local newspapers, floodwaters overtopped the dam by as much as 4 feet and the total precipitation was reported as 7 inches. A letter dated August 15, 1980, from the Delaware Geological Survey to the Delaware Department of Transportation stated that preliminary calculations performed by the United States Geological Survey indicate a peak discharge of 1,250 cubic feet per second (cfs) in Mill Creek upstream of Lake Como. The peak flow downstream of the dam was computed to be about 2,520 cfs (a copy of the letter is included in Appendix E). Inspection of the dam after the overtopping indicated that the high water marks were about two feet above the dam crest. The embankment also collapsed in 1940 and was overtopped in 1913 according to town officials. Unverified accounts indicate that the dam has been overtopped on several occasions since its 1941 reconstruction. Further details concerning these events are unavailable.

c. Visual Observations. On the date of inspection the reservoir pool was about 15 inches below the spillway crest. The low level outlets were partially open allowing about 2 cfs to discharge into Mill Creek.

d. Overtopping Potential. The recommended Spillway Design Flood (SDF) range for a "Small" size, "Significant" hazard dam is from the 100-year flood to one-half of the Probable Maximum Flood (PMF). Since disruption of a major highway, a sewage treatment plant and pumping station caused by a dam failure would have a significant effect upon the community, the selected SDF is one-half of the PMF. The SDF was synthesized from one-half of the Probable Maximum Precipitation (PMP) using the SCS unit hydrograph for Lake Como. The inflow hydrograph was routed through Lake Como with the initial water surface elevation at the spillway crest. The peak inflow and outflow rates for the SDF were computed to be 6620 cfs and 6568 cfs, respectively. The spillway is capable of discharging approximately 8 percent of the SDF prior to overtopping of the embankment (refer to Appendix C for computations and the computer printout).

e. Spillway Adequacy. The Lake Como Dam spillway is incapable of passing one-half of the PMF and the dam is classified as a "Significant" hazard structure. Therefore, the Lake Como Dam spillway is classified as "Inadequate".



The two gated 36-inch diameter low-level conduits are capable of draining the normal pool storage capacity to Elevation 6.2 within about 15 hours.

## SECTION 6

### STRUCTURAL STABILITY

#### 6.1 Evaluation of Structural Stability

a. Visual Observations. It is evident from the overtopping and partial failure of the embankment on July 29, 1980, that Lake Corno Dam cannot withstand significant overtopping for an extended period of time. Leakage or rupture of the water main if left within the embankment could cause piping of sand and fine-grained soil from the dam. The unprotected upstream slope exposes the dam to erosion by wave action. The trees and utility poles in the embankment present potential hazards to the structural integrity of the dam. The root systems of the trees create seepage paths through the embankment. Dislodging of the trees or utility poles during severe wind conditions could remove portions of the embankment.

b. Design and Construction Data. No construction data is available. The design data is limited to two drawings prepared for reconstruction of the dam in 1941.

c. Operating Records. No operating records are maintained at this site.

d. Post Construction Changes. There are no records of post construction changes. Representatives of the Delaware Department of Natural Resources and Environmental Control, the Army Corps of Engineers and O'Brien & Gere inspected Lake Corno Dam following the July 29, 1980 overtopping, and the following "immediate remedial actions" were recommended (copy of the teletype letter from the Corps of Engineers to DE Governor DuPont is included on pages 8 and 9 of Appendix E):

1. Gas lines and water lines should be removed from the embankment and relocated.
2. A professional engineer, experienced in the design and construction of dams, should be engaged to design an adequate spillway and embankment section for the dam.
3. Borings should be taken through the embankment and foundation to determine soil types, in-place densities and other soil properties.
4. A detailed topographic survey of the embankment from the upstream slope to the Highway 13 bridge should be made.
5. The reservoir should be maintained 3 feet below the crest of the spillway pipe risers until permanent repairs have been made.
6. The embankment should be inspected periodically by an experienced engineer for signs of seepage or additional sloughing until permanent repairs are made.

7. Until permanent repairs are completed, continuous monitoring of the lake levels should be made during periods of heavy rainfall so that increases in the lake levels can be minimized.

e. Seismic Stability. Lake Como Dam is in a state of partial failure and its stability under static loading conditions is uncertain. Therefore, an accurate assessment of Lake Como Dam for earthquake loading conditions is not possible.

## SECTION 7

### ASSESSMENT, RECOMMENDATIONS, AND PROPOSED REMEDIAL MEASURES

#### 7.1 Dam Assessment

a. Safety. The visual observations and review of available information indicate that Lake Como Dam is in poor condition. The deficiencies and problem areas noted in Sections 3.1B, 3.1c, 5.1b, 5.1e, and 6.1a indicate an inadequate original design.

The selected SDF for this structure is one-half of the PMF. The spillway is capable of discharging approximately 8 percent of the SDF prior to overtopping of the embankment. The dam is classified as a "Significant" hazard structure since failure would cause appreciable property damage. The spillway is classified as "Inadequate", and the dam is classified as "Unsafe, non-emergency".

b. Adequacy of Information. The information provided by the Town of Smyrna, conversations with town officials and observations made during the field investigations provided adequate data for a Phase 1 evaluation.

c. Urgency. The recommendations and remedial measures described in Section 7.2 should be initiated immediately.

d. Necessity for Further Evaluation. Further investigations should be performed in accordance with Section 7.2, Item 1.

#### 7.2 Recommendations and Proposed Remedial Measures

##### a. Facilities

1. Ownership of and maintenance responsibility for the dam should be clarified.

A registered professional engineer experienced in the design and construction of dams should be engaged to:

1. Perform detailed hydrologic and hydraulic analyses to determine what measures are required to provide adequate spillway discharge capacity and/or to protect the embankment from overtopping.

2. Design and supervise construction of repairs to the existing embankment section.

3. Design and supervise the construction of erosion protection for the upstream and downstream slopes of the dam and outlet channel.

4. Provide guidance to the Owner for removal of the trees and utility poles from the embankment and the backfilling of voids with suitable, thoroughly compacted material.

5. Provide guidance to the Owner for removal of the water and gas lines from the dam and their relocation.

b. Operation and Maintenance Procedures.

1. The Owner should maintain the reservoir elevation 3 feet below the spillway crest until permanent repairs are completed.

2. Continuous monitoring of reservoir levels during periods of heavy precipitation should be undertaken until permanent repairs are completed.

3. The Owner should employ a professional engineer experienced in operation and maintenance of dams to develop written operating procedures and a periodic maintenance plan to insure the safety of the reconstructed facilities.

4. An emergency action plan should be developed which outlines actions to be taken by the Owner to minimize the downstream effects of an emergency.

APPENDIX

A

Check List Engineering Data  
Design, Construction, Operation  
Phase I

CHECK LIST  
VISUAL INSPECTION  
PHASE I

Sheet 1 of 7

Name Dam Lake Como Dam County Kent State Delaware National ID # DE00028

Type of Dam Earth Hazard Category Significant

Date(s) Inspection 8/12/80 Weather Partly Cloudy Temperature 85<sup>o</sup>

Pool Elevation at Time of Inspection 13.3 M.S.L. Tailwater at Time of Inspection 6.3 M.S.L.

Inspection Personnel:

John J. Williams Lee DeHeer Steve Snider

S.H. Snider Recorder

Remarks:  
Mr. Brian Heverin and Mr. Brian Mulvanna, Phila. Corps of Engineers, Mr. Krishna Patel, DE Dept. of Natural Resources and Environmental Control and Mr. Harry Odren, City Manager, City of Smyrna were also present. A complete list of attendees during the visual inspection is included on Sheet 1a.

# DISPOSITION FORM

For use of this form, see AR 340-15, the proponent agency is TAGCEN.

REFERENCE OR OFFICE SYMBOL

NAPEN

SUBJECT

Trip Report of Phase I Inspection of Lake Como Dam and meeting with Delaware D.O.T.

TO Files

FROM

Chief Gen. Des. Sec. DATE 18 August 1980 CMT 1  
MULVENNA/ja/4756

1. The undersigned and Brian Mulvenna, General Design Section, travelled to Smyrna, Delaware on 12 August 1980 to meet with representatives of the Delaware Department of Natural Resources, the Delaware Department of Transportation and the City of Smyrna and conduct a Phase I inspection of the Lake Como Dam which was overtopped on 28 July 1980. This inspection was requested by the State in a letter dated August 1980.

2. Following is a list of those present during the inspection of Lake Como Dam:

NAME	REPRESENTING
Brian Heverin	USACE
Brian Mulvenna	USACE
Lee Deheer	O'Brien & Gere
Jay Williams	O'Brien & Gere
Krishna Patel	DDNR & EC
Darwin Kates	Del. D.O.T.
Gary Homewood	Del. D.O.T.
Jim Moore	Del. D.O.T.
Paul Martin	Del. D.O.T.
James W. Simpson	Del. D.O.T.
Charles Bostick	Del. D.O.T.
Thomas N. Jarman	Town of Smyrna
Harry M. Odren	Town of Smyrna
Skip Rebar	Councilman - Smyrna
Dean Phillips	Asst. Mgr. Smyrna
STEVE SNIDER	O'BRIEN & GERE

3. Upon completion of the visual inspection of the dam, discussion ensued with officials of the City of Smyrna and the Delaware Department of Transportation regarding possible courses of action for repair of the dam and any recommendations the Corps may have regarding what repairs should be undertaken. The State and City officials also asked if the Corps could fund the repairs and a negative reply was furnished.

4. It was also reported to the state and local officials that the Corps' consultant, O'Brien & Gere, would develop some interim technical recommendations for repair once they have reviewed the existing data on the dam and conducted some preliminary hydrological calculations. These recommendations are expected to be ready approximately one week from the inspection date.

DA FORM 2496  
1 FEB 62

REPLACES DD FORM 96, WHICH IS OBSOLETE.



EMBANKMENT

Sheet 2 of 7

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS	Surface cracks were evident around the periphery of the failure zone.	Repair Embankment
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	The downstream toe had been entirely washed away.	Repair Embankment
SLOUGHING OR EROSION OF EMBANKMENT AND ABUTMENT SLOPES	The entire half of the downstream slope was eroded away.	Repair Embankment
VERTICAL AND HORIZONTAL ALIGNMENT OF THE CREST	The embankment crest had been reduced by as much as five feet in some locations.	Repair Embankment
RIPRAP FAILURES	No riprap	Provide erosion protection

EMBANKMENT

Sheet 3 of 7

REMARKS OR RECOMMENDATIONS

OBSERVATIONS

VISUAL EXAMINATION OF

This area should be repaired along with embankment.

Hydraulic erosion extends into the left abutment

JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM

None observed

ANY NOTICEABLE SEEPAGE

None

STAFF GAGE AND RECORDER

None

DRAINS

OUTLET WORKS

Sheet 4 of 7

<u>VISUAL EXAMINATION OF</u>	<u>OBSERVATIONS</u>	<u>REMARKS OR RECOMMENDATIONS</u>
CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	None observed	
INTAKE STRUCTURE	No problems observed	Access bridge below dam crest elevation limits access during high reservoir stages.
OUTLET STRUCTURE	No problems observed	
OUTLET CHANNEL	The right channel slope entirely eroded away.	Repair and provide slope protection.
EMERGENCY GATE	None	

UNGATED SPILLWAY

Sheet 5 of 7

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE WEIR	5 circular drop inlets	Insufficient discharge capacity.
APPROACH CHANNEL	NONE	
DISCHARGE CHANNEL	An R/C bridge carrying U. S. route 13 is located 110 feet d/s of dam. Span is about 40 feet and vertical opening about 9 feet.	
BRIDGE AND PIERS	NOT APPLICABLE	

RESERVOIR

Sheet 6 of 7

VISUAL EXAMINATION OF      OBSERVATIONS      REMARKS OR RECOMMENDATIONS

SLOPES

Very gently sloping grass and forest covered  
No indications of instability.

SEDIMENTATION

None observed.

DOWNSTREAM CHANNEL

Sheet 7 of 7

VISUAL EXAMINATION OF

OBSERVATIONS

REMARKS OR RECOMMENDATIONS

CONDITION  
(OBSTRUCTIONS,  
DEBRIS, ETC.)

Beyond the Rt. 13 bridge the channel opens into a wide flat flood plain.

SLOPES

Channel slope is less than 1% to confluence with Smyrna River

APPROXIMATE NO.  
OF HOMES AND  
POPULATION

No homes downstream of dam.  
A restaurant and sewage pump station are within the potential floodplain.

APPENDIX

B

Checklist  
Visual Inspection  
Phase I

NAME OF DAM L. Como Dam

ID # DE 00028

CHECK LIST  
ENGINEERING DATA  
DESIGN, CONSTRUCTION, OPERATION  
PHASE I

Sheet 1 of 4

REMARKS

ITEM

AS-BUILT DRAWINGS

NONE AVAILABLE

REGIONAL VICINITY MAP

Refer to Appendix E, Fig. 1

CONSTRUCTION HISTORY

Original date of construction unknown.  
Dam reconstructed in 1941 after wash-  
out.

TYPICAL SECTIONS OF DAM

Refer to Appendix E.

OUTLETS - PLAN

DETAILS

CONSTRAINTS

Refer to Appendix E.

DISCHARGE RATINGS

NONE AVAILABLE

RAINFALL/RESERVOIR RECORDS

NONE AVAILABLE



ITEM \_\_\_\_\_ REMARKS \_\_\_\_\_

DESIGN REPORTS NONE AVAILABLE

GEOLOGY REPORTS NONE AVAILABLE

DESIGN COMPUTATIONS NO DATA AVAILABLE  
HYDROLOGY & HYDRAULICS NO DATA AVAILABLE  
DAM STABILITY NO DATA AVAILABLE  
SEEPAGE STUDIES NC DATA AVAILABLE

MATERIALS INVESTIGATIONS NO INFORMATION AVAILABLE  
BORING RECORDS }  
LABORATORY }  
FIELD }

POST-CONSTRUCTION SURVEYS OF DAM NONE

BORROW SOURCES No Records Available

ITEM	REMARKS
MONITORING SYSTEMS	None
MODIFICATIONS	The dam was rebuilt in 1941 after a collapse during overtopping in 1940. The dam reportedly failed earlier in the century, but no documentation is available.
HIGH POOL RECORDS	Numerous overtoppings have occurred. Details are unavailable.
POST CONSTRUCTION ENGINEERING STUDIES AND REPORTS	None
PRIOR ACCIDENTS OR FAILURE OF DAM DESCRIPTION REPORTS	The dam failed in 1940 and sometime between 1913 and 1940.
MAINTENANCE OPERATION RECORDS	None available.

APPENDIX

C

Hydrologic & Hydraulic Data



SUBJECT <u>LAKE COMO DAM</u>	SHEET	BY	DATE	JOB NO
---------------------------------	-------	----	------	--------

APPENDIX C  
HYDROLOGIC & HYDRAULIC DATA  
TABLE OF CONTENTS

Sheet No.

<i>PMP Calculations, Reservoir Surface Areas</i>	<i>1</i>
<i>Unit Hydrograph &amp; Lag Time Calculations</i>	<i>1-2</i>
<i>Spillway Plan &amp; Section Sketches</i>	<i>3</i>
<i>Discharge Calculations</i>	<i>4</i>
<i>HEC-1 Dam Safety Version Computer Printout</i>	<i>5-29</i>



SUBJECT	SHEET	BY	DATE	JOB NO
LAKE COMO DAM - H&H	1	SHS	8/13/80	1800.006.109

HYDROLOGIC CALCULATIONS

Drainage Area - 6.8 sq.mi. (Planimetered from USGS Quad Sheets)

Reservoir Surface Area:

Storage By HEC-1 Program:

Normal Pool - El. 14.6 = 46 acres

138 acre-feet

Top of Dam - El. 17.6 = 71 acres

312 acre-feet

El. 22.6 = 124 acres

794 acre-feet

PMP COMPUTATIONS: HMR 33

Watershed is in Zone 6 of PMP ALL SEASON ENVELOPE

24 hr., 200 sq.mi. RAINFALL = 24 inches

<u>H.R.</u>	<u>%</u>	<u>Rainfall</u>
6	113	27.1"
12	124	29.8"
24	137	31.7"
48	142	34.1"

SCS UNIT HYDROGRAPH: Lag Time

The upper 8000 ft. of drainage basin is considered to be overland flow.

$$\text{Travel Time} = \frac{8000}{V}$$

$V \approx 0.4$  fps. (SCS Upland Method, Cultivated)

$$= 5.6 \text{ hrs.}$$



SUBJECT	SHEET	BY	DATE	JOB NO
LAKE COMO DAM - H.E.H	2	SHS	8/13/80	1800.006.109

The remainder of  $T_c$  can be obtained by computing a velocity based upon average channel characteristics using Manning's Equation.



$$n = 0.040$$

$$A = 500 \text{ ft}^2$$

$$W_p \approx 201$$

$$R = 2.49$$

$$S = \frac{70-12}{30,000}$$

$$S \approx 0.002 \text{ ft/ft}$$

$$V = \frac{1.49 R^{2/3} S^{1/2}}{n} = \frac{1.49 (2.49)^{0.67} (0.002)^{0.5}}{0.040}$$

$$V = 3.1 \text{ fps.}$$

$$\text{Channel Length} = 22,000 \text{ ft.}$$

$$\text{Travel Time} = \frac{22,000'}{3.1 (3600)} = 2.0 \text{ hrs.}$$

$$\therefore T_c = 7.6 \text{ hours.} = 5.6 + 2.0$$

$$\therefore \text{Lag} = 0.6 T_c = \boxed{4.5 \text{ hrs.}}$$



SUBJECT

LAKE COMO DAM - H&H

SHEET

3

BY

SHS


DATE

8/13/80


JOB NO

1800.006.109

HYDRAULIC CALCULATIONS:




± Main Street



SPILLWAY  
PLAN SKETCH

N.T.S.



SPILLWAY  
CROSS SECTION

N.T.S.



SUBJECT LAKE COMO DAM - H&H	SHEET 4	BY SHS	DATE 8/13/80	JOB NO. 1800.006.109
--------------------------------	------------	-----------	-----------------	-------------------------

Discharge through a "morning-glory" spillway can be calculated by dividing the stage-discharge relationship into two segments as follows: Ref. DESIGN OF SMALL DAMS

1. Weir Crest Control:  $Q = C_w L H^{3/2}$   $L = 5 \times 71.25 = 356.25'$   
 Although orifice control is present, the weir coefficient can be adjusted using this eqn. to obtain Q.

2. \* Orifice Control:  $Q = CA \sqrt{2g} H$   $C = 0.50$   
 Does not begin until after dam overtopping.

\* Assume free discharge at spillway outlet.

Discharge over the dam can be described by:  $Q = CLH^{3/2}$ ;  $C = 2.8$   
 Dam Length - 240', Right Abutment @ Same EL. - 260' ∴  $L = 500'$

STAGE - DISCHARGE TABULATION

W.S.E. (MSL)	$H_{\text{spillway}}$	Weir		Orifice		Dam		$(cfs) \geq Q$
		$C_w$	Q	H	Q	H	Q	
14.6	0	-	-	-	-	-	-	0
15.1	0.5	3.2	40	-	-	-	-	40
15.6	1.0	2.8	99	-	-	-	-	99
16.6	2.0	1.6	160	-	-	-	-	160
17.6	3.0	1.0	184	-	-	-	-	184
18.1	3.5	1.0	231	-	-	0.5	495	726
18.6	4.0	1.0	283	-	-	1.0	1400	1683
19.6	5.0	-	-	13.0	288	2.0	3960	4248
20.6	6.0	-	-	14.0	299	3.0	7275	7574
21.6	7.0	-	-	15.0	309	4.0	11,200	11,509
22.6	8.0	-	-	16.0	319	5.0	15,652	15,971



.....  
 FLOOD HYDROGRAPH PACKAGE (HFC-1)  
 DAM SAFETY VERSION JULY 1978  
 LAST MODIFICATION 26 FEB 79  
 .....

NATIONAL DAM INSPECTION PROGRAM									
LAKE COMO DAM									
HYDROLOGIC ANALYSIS									
1	A1								
2	A2								
3	A3								
4	M	300	0	10	0	0	0	0	-3
5	M	5							
6	J	1							
7	J1	0.02	0.03	0.04	0.05	0.10	0.15	0.25	1.0
8	K	0	INFLOW						
9	K1	1	2	6.4					
10	M	0	2	113	124	132	142		
11	T								
12	T								
13	M2		4.5						
14	K	-1.5	-0.5	2					
15	K	1	OUTFLOW						
16	K1								
17	Y								
18	Y1	1							
19	Y4	14.6	15.1	15.6	16.6	17.6	18.1	18.6	-14.6
20	Y4	22.5							19.0
21	Y5	0							20.4
22	Y5	1571	40	99	160	184	226	1683	7574
23	Y5	0	40	71	124				11509
24	Y8	5.6	14.6	17.6	22.6				
25	Y8	14.6							
26	Y8	17.5							
27	K	99							

PREVIEW OF SEQUENCE OF STREAM NETWORK CALCULATIONS

MUNDIFF HYDROGRAPH AT  
 MOUNT HYDROGRAPH TO  
 END OF NETWORK

INFLOW  
 OUTFLOW

\*\*\*\*\*  
 FLOOD HYDROGRAPH PACKAGE (HEC-1)  
 DAM SAFETY VERSION JULY 1978  
 LAST MODIFICATION 20 FEB 79  
 \*\*\*\*\*

RUN DATE 80/09/10  
 TIME 06.03.24

NATIONAL DAM INSPECTION PROGRAM  
 LAKE COMO DAM  
 HYDROLOGIC ANALYSIS

JOB SPECIFICATION  
 IDAY 0 IMH 0 METRC 0  
 IMIN 0  
 IUPER 5 NWT 0 LHOPT 0  
 IPLT 0  
 IPHT -3 NSTAN 0

MULTI-PLAN ANALYSES TO BE PERFORMED  
 NPLAN= 1 NPTIO= 6 LRTIO= 1

MTIO= .02 .03 .04 .05 .10 .15 .25 .50 1.00

\*\*\*\*\*

SUB-AREA RUNOFF COMPUTATION

INFLOW TO LAKE COMO DAM

ISTAU 2 TAREA 0.00 ICOMP 0 IFCON 0 ICAPE 0 JPLT 0 JPHI 0 JNAME 1 ISTATE 0 IAUTO 0  
 INFLOW 0

HYDROGRAPH DATA

ISYD 1 IUMS 2 TAREA 0.00 SWAP 0 TRSDA 0 TRSPC 0 RATIO 0 ISNOW 0 ISAME 1 LOCAL 0  
 ISTRM 0 ULTRM 0.00 MTIOL 1.00 ERAIN 0.00 STIOL 1.00 CNSTL 0.05 ALSMX 0.00 HTIMP 0.00  
 SPTS 0.00 26.00 113.00 124.00 132.00 142.00 0.00 0.00  
 H45 H6 H12 H24 H48 H96  
 TRSPC COMPUTED BY THE PROGRAM IS 0.00

PRECIP DATA

PRECIP DATA  
 H45 H12 H24 H48 H96  
 0.00 26.00 113.00 124.00 132.00 142.00 0.00 0.00

LOSS DATA

LOSS DATA  
 LHOPT 0 STRM 0.00 ULTRM 0.00 MTIOL 1.00 ERAIN 0.00 STIOL 1.00 CNSTL 0.05 ALSMX 0.00 HTIMP 0.00  
 TC= 0.00 LAG= 0.50

UNIT HYDROGRAPH DATA

UNIT HYDROGRAPH DATA  
 TC= 0.00 LAG= 0.50

RECESSION DATA

RECESSION DATA  
 STRTUE -1.50 WRCSTA= 0.05 MTIOW= 2.00

UNIT HYDROGRAPH 1ST END OF PERIOD ORDINATES, TC= 0.00 MTIOWS, LAG= 4.50 VOL= 1.00  
 0. 16. 26. 46. 63. 83. 107. 130. 160. 191.  
 222. 264. 305. 349. 399. 448. 494. 535. 577. 609.  
 639. 682. 697. 710. 712. 715. 712. 710. 712. 710.

Sh. 6

67.	68.	69.	70.	71.	72.	73.	74.	75.	76.	77.	78.	79.	80.	81.	82.	83.	84.	85.	86.	87.	88.	89.	90.	91.	92.	93.	94.	95.	96.	97.	98.	99.	100.	
546.	547.	548.	549.	550.	551.	552.	553.	554.	555.	556.	557.	558.	559.	560.	561.	562.	563.	564.	565.	566.	567.	568.	569.	570.	571.	572.	573.	574.	575.	576.	577.	578.	579.	580.

MU-118	HR-MN	PERIOD	MAIN	EACS	LOSS	END-OF-PERIOD FLOW		MU-DA	HR-MN	PERIOD	RAIN	EACS	LOSS	COMP U
						COMP Q	MU-DA							
1.01	1.10	1	.00	0.00	.00	1.02	10.	1.02	1.10	151	.02	.01	.01	162.
1.01	1.20	2	.00	0.00	.00	1.02	9.	1.02	1.20	152	.02	.01	.01	154.
1.01	1.30	3	.00	0.00	.00	1.02	8.	1.02	1.30	153	.02	.01	.01	147.
1.01	1.40	4	.00	0.00	.00	1.02	7.	1.02	1.40	154	.02	.01	.01	140.
1.01	1.50	5	.00	0.00	.00	1.02	6.	1.02	1.50	155	.02	.01	.01	135.
1.01	1.00	6	.00	0.00	.00	1.02	5.	1.02	2.00	156	.02	.01	.01	130.
1.01	1.10	7	.00	0.00	.00	1.02	4.	1.02	2.10	157	.02	.01	.01	126.
1.01	1.20	8	.00	0.00	.00	1.02	3.	1.02	2.20	158	.02	.01	.01	122.
1.01	1.30	9	.00	0.00	.00	1.02	2.	1.02	2.30	159	.02	.01	.01	119.
1.01	1.40	10	.00	0.00	.00	1.02	1.	1.02	2.40	160	.02	.01	.01	118.
1.01	1.50	11	.00	0.00	.00	1.02	0.	1.02	2.50	161	.02	.01	.01	117.
1.01	2.00	12	.00	0.00	.00	1.02	0.	1.02	3.00	162	.02	.01	.01	117.
1.01	2.10	13	.00	0.00	.00	1.02	0.	1.02	3.10	163	.02	.01	.01	117.
1.01	2.20	14	.00	0.00	.00	1.02	0.	1.02	3.20	164	.02	.01	.01	119.
1.01	2.30	15	.00	0.00	.00	1.02	0.	1.02	3.30	165	.02	.01	.01	110.
1.01	2.40	16	.00	0.00	.00	1.02	0.	1.02	3.40	166	.02	.01	.01	110.
1.01	2.50	17	.00	0.00	.00	1.02	0.	1.02	3.50	167	.02	.01	.01	121.
1.01	3.00	18	.00	0.00	.00	1.02	0.	1.02	4.00	168	.02	.01	.01	126.
1.01	3.10	19	.00	0.00	.00	1.02	0.	1.02	4.10	169	.02	.01	.01	129.
1.01	3.20	20	.00	0.00	.00	1.02	0.	1.02	4.20	170	.02	.01	.01	131.
1.01	3.30	21	.00	0.00	.00	1.02	0.	1.02	4.30	171	.02	.01	.01	135.
1.01	3.40	22	.00	0.00	.00	1.02	0.	1.02	4.40	172	.02	.01	.01	138.
1.01	3.50	23	.00	0.00	.00	1.02	0.	1.02	4.50	173	.02	.01	.01	142.
1.01	4.00	24	.00	0.00	.00	1.02	0.	1.02	5.00	174	.02	.01	.01	145.
1.01	4.10	25	.00	0.00	.00	1.02	0.	1.02	5.10	175	.02	.01	.01	149.
1.01	4.20	26	.00	0.00	.00	1.02	0.	1.02	5.20	176	.02	.01	.01	153.
1.01	4.30	27	.00	0.00	.00	1.02	0.	1.02	5.30	177	.02	.01	.01	157.
1.01	4.40	28	.00	0.00	.00	1.02	0.	1.02	5.40	178	.02	.01	.01	160.
1.01	4.50	29	.00	0.00	.00	1.02	0.	1.02	5.50	179	.02	.01	.01	164.
1.01	5.00	30	.00	0.00	.00	1.02	0.	1.02	6.00	180	.02	.01	.01	164.
1.01	5.10	31	.00	0.00	.00	1.02	0.	1.02	6.10	181	.06	.05	.01	171.
1.01	5.20	32	.00	0.00	.00	1.02	0.	1.02	6.20	182	.06	.05	.01	175.
1.01	5.30	33	.00	0.00	.00	1.02	0.	1.02	6.30	183	.06	.05	.01	180.
1.01	5.40	34	.00	0.00	.00	1.02	0.	1.02	6.40	184	.06	.05	.01	185.
1.01	5.50	35	.00	0.00	.00	1.02	0.	1.02	6.50	185	.06	.05	.01	191.
1.01	6.00	36	.00	0.00	.00	1.02	0.	1.02	7.00	186	.06	.05	.01	197.
1.01	6.10	37	.00	0.00	.00	1.02	0.	1.02	7.10	187	.06	.05	.01	204.
1.01	6.20	38	.00	0.00	.00	1.02	0.	1.02	7.20	188	.06	.05	.01	212.
1.01	6.30	39	.00	0.00	.00	1.02	0.	1.02	7.30	189	.06	.05	.01	221.
1.01	6.40	40	.00	0.00	.00	1.02	0.	1.02	7.40	190	.06	.05	.01	231.
1.01	6.50	41	.00	0.00	.00	1.02	0.	1.02	7.50	191	.06	.05	.01	242.
1.01	7.00	42	.00	0.00	.00	1.02	0.	1.02	8.00	192	.06	.05	.01	255.
1.01	7.10	43	.00	0.00	.00	1.02	0.	1.02	8.10	193	.06	.05	.01	264.
1.01	7.20	44	.00	0.00	.00	1.02	0.	1.02	8.20	194	.06	.05	.01	245.
1.01	7.30	45	.00	0.00	.00	1.02	0.	1.02	8.30	195	.06	.05	.01	303.

Sh. 7

1.01	7.40	46	.00	0.00	.00	0.00	.00	0.00	1.02	8.40	196	.06	.05	.01	323.
1.01	7.50	47	.00	0.00	.00	0.00	.00	0.00	1.02	8.50	197	.06	.05	.01	345.
1.01	8.00	48	.00	0.00	.00	0.00	.00	0.00	1.02	9.00	198	.06	.05	.01	369.
1.01	8.10	49	.00	0.00	.00	0.00	.00	0.00	1.02	9.10	199	.06	.05	.01	394.
1.01	8.20	50	.00	0.00	.00	0.00	.00	0.00	1.02	9.20	200	.06	.05	.01	420.
1.01	8.30	51	.00	0.00	.00	0.00	.00	0.00	1.02	9.30	201	.06	.05	.01	444.
1.01	8.40	52	.00	0.00	.00	0.00	.00	0.00	1.02	9.40	202	.06	.05	.01	477.
1.01	8.50	53	.00	0.00	.00	0.00	.00	0.00	1.02	9.50	203	.06	.05	.01	506.
1.01	9.00	54	.00	0.00	.00	0.00	.00	0.00	1.02	10.00	204	.06	.05	.01	536.
1.01	9.10	55	.00	0.00	.00	0.00	.00	0.00	1.02	10.10	205	.06	.05	.01	566.
1.01	9.20	56	.00	0.00	.00	0.00	.00	0.00	1.02	10.20	206	.06	.05	.01	597.
1.01	9.30	57	.00	0.00	.00	0.00	.00	0.00	1.02	10.30	207	.06	.05	.01	628.
1.01	9.40	58	.00	0.00	.00	0.00	.00	0.00	1.02	10.40	208	.06	.05	.01	658.
1.01	9.50	59	.00	0.00	.00	0.00	.00	0.00	1.02	10.50	209	.06	.05	.01	688.
1.01	10.00	60	.00	0.00	.00	0.00	.00	0.00	1.02	11.00	210	.06	.05	.01	719.
1.01	10.10	61	.00	0.00	.00	0.00	.00	0.00	1.02	11.10	211	.06	.05	.01	748.
1.01	10.20	62	.00	0.00	.00	0.00	.00	0.00	1.02	11.20	212	.06	.05	.01	777.
1.01	10.30	63	.00	0.00	.00	0.00	.00	0.00	1.02	11.30	213	.06	.05	.01	805.
1.01	10.40	64	.00	0.00	.00	0.00	.00	0.00	1.02	11.40	214	.06	.05	.01	833.
1.01	10.50	65	.00	0.00	.00	0.00	.00	0.00	1.02	11.50	215	.06	.05	.01	859.
1.01	11.00	66	.00	0.00	.00	0.00	.00	0.00	1.02	12.00	216	.06	.05	.01	885.
1.01	11.10	67	.00	0.00	.00	0.00	.00	0.00	1.02	12.10	217	.36	.35	.01	913.
1.01	11.20	68	.00	0.00	.00	0.00	.00	0.00	1.02	12.20	218	.36	.35	.01	941.
1.01	11.30	69	.00	0.00	.00	0.00	.00	0.00	1.02	12.30	219	.36	.35	.01	972.
1.01	11.40	70	.00	0.00	.00	0.00	.00	0.00	1.02	12.40	220	.36	.35	.01	1004.
1.01	11.50	71	.00	0.00	.00	0.00	.00	0.00	1.02	12.50	221	.36	.35	.01	1047.
1.01	12.00	72	.00	0.00	.00	0.00	.00	0.00	1.02	13.00	222	.36	.35	.01	1092.
1.01	12.10	73	.03	0.00	.03	0.00	.03	0.00	1.02	13.10	223	.43	.43	.01	1143.
1.01	12.20	74	.03	0.00	.03	0.00	.03	0.00	1.02	13.20	224	.43	.43	.01	1201.
1.01	12.30	75	.03	0.00	.03	0.00	.03	0.00	1.02	13.30	225	.43	.43	.01	1267.
1.01	12.40	76	.03	0.00	.03	0.00	.03	0.00	1.02	13.40	226	.43	.43	.01	1343.
1.01	12.50	77	.03	0.00	.03	0.00	.03	0.00	1.02	13.50	227	.43	.43	.01	1423.
1.01	13.00	78	.03	0.00	.03	0.00	.03	0.00	1.02	14.00	228	.43	.43	.01	1527.
1.01	13.10	79	.03	0.00	.03	0.00	.03	0.00	1.02	14.10	229	.54	.53	.01	1640.
1.01	13.20	80	.03	0.00	.03	0.00	.03	0.00	1.02	14.20	230	.54	.53	.01	1768.
1.01	13.30	81	.03	0.00	.03	0.00	.03	0.00	1.02	14.30	231	.54	.53	.01	1914.
1.01	13.40	82	.03	0.00	.03	0.00	.03	0.00	1.02	14.40	232	.54	.53	.01	2074.
1.01	13.50	83	.03	0.00	.03	0.00	.03	0.00	1.02	14.50	233	.54	.53	.01	2261.
1.01	14.00	84	.03	0.00	.03	0.00	.03	0.00	1.02	15.00	234	.54	.53	.01	2460.
1.01	14.10	85	.04	0.00	.04	0.00	.04	0.00	1.02	15.10	235	.49	.49	.01	2676.
1.01	14.20	86	.04	0.00	.04	0.00	.04	0.00	1.02	15.20	236	.82	.82	.01	2910.
1.01	14.30	87	.04	0.00	.04	0.00	.04	0.00	1.02	15.30	237	1.48	1.48	.01	3166.
1.01	14.40	88	.04	0.00	.04	0.00	.04	0.00	1.02	15.40	238	3.71	3.70	.01	3463.
1.01	14.50	89	.04	0.00	.04	0.00	.04	0.00	1.02	15.50	239	1.07	1.06	.01	3779.
1.01	15.00	90	.04	0.00	.04	0.00	.04	0.00	1.02	16.00	240	.66	.65	.01	4123.
1.01	15.10	91	.04	0.00	.04	0.00	.04	0.00	1.02	16.10	241	.51	.50	.01	4505.
1.01	15.20	92	.06	0.00	.06	0.00	.06	0.00	1.02	16.20	242	.51	.50	.01	4902.
1.01	15.30	93	.11	.03	.09	.03	.09	.03	1.02	16.30	243	.51	.50	.01	5317.
1.01	15.40	94	.25	.27	.27	.27	.27	.27	1.02	16.40	244	.51	.50	.01	5751.
1.01	15.50	95	.08	.07	.01	.01	.01	.01	1.02	16.50	245	.51	.50	.01	6196.
1.01	16.00	96	.05	.04	.01	.01	.01	.01	1.02	17.00	246	.51	.50	.01	6665.
1.01	16.10	97	.04	.03	.01	.01	.01	.01	1.02	17.10	247	.40	.39	.01	7146.
1.01	16.20	98	.04	.03	.01	.01	.01	.01	1.02	17.20	248	.40	.39	.01	7636.
1.01	16.30	99	.04	.03	.01	.01	.01	.01	1.02	17.30	249	.40	.39	.01	8155.
1.01	16.40	100	.04	.03	.01	.01	.01	.01	1.02	17.40	250	.40	.39	.01	8718.
1.01	16.50	101	.04	.03	.01	.01	.01	.01	1.02	17.50	251	.40	.39	.01	9206.
1.01	17.00	102	.04	.03	.01	.01	.01	.01	1.02	18.00	252	.40	.39	.01	9745.
1.01	17.10	103	.03	.02	.01	.01	.01	.01	1.02	18.10	253	.03	.02	.01	10270.
1.01	17.20	104	.03	.02	.01	.01	.01	.01	1.02	18.20	254	.03	.02	.01	10765.
1.01	17.30	105	.03	.02	.01	.01	.01	.01	1.02	18.30	255	.03	.02	.01	11226.

1.01	17.40	106	.03	.02	.01	145.	1.02	18.40	250	.03	.02	.01	11653.
1.01	17.50	107	.03	.02	.01	169.	1.02	18.50	257	.03	.02	.01	12025.
1.01	18.00	108	.03	.02	.01	196.	1.02	19.00	264	.03	.02	.01	12353.
1.01	18.10	109	.00	0.00	.00	226.	1.02	19.10	259	.03	.02	.01	12639.
1.01	18.20	110	.00	0.00	.00	252.	1.02	19.20	260	.03	.02	.01	12855.
1.01	18.30	111	.00	0.00	.00	260.	1.02	19.30	261	.03	.02	.01	13030.
1.01	18.40	112	.00	0.00	.00	304.	1.02	19.40	262	.03	.02	.01	13155.
1.01	18.50	113	.00	0.00	.00	334.	1.02	19.50	263	.03	.02	.01	13217.
1.01	19.00	114	.00	0.00	.00	354.	1.02	20.00	264	.03	.02	.01	13249.
1.01	19.10	115	.00	0.00	.00	403.	1.02	20.10	265	.03	.02	.01	13222.
1.01	19.20	116	.00	0.00	.00	403.	1.02	20.20	266	.03	.02	.01	13161.
1.01	19.30	117	.00	0.00	.00	422.	1.02	20.30	267	.03	.02	.01	13098.
1.01	19.40	118	.00	0.00	.00	440.	1.02	20.40	268	.03	.02	.01	12890.
1.01	19.50	119	.00	0.00	.00	453.	1.02	20.50	269	.03	.02	.01	12678.
1.01	20.00	120	.00	0.00	.00	466.	1.02	21.00	270	.03	.02	.01	12535.
1.01	20.10	121	.00	0.00	.00	476.	1.02	21.10	271	.03	.02	.01	12154.
1.01	20.20	122	.00	0.00	.00	484.	1.02	21.20	272	.03	.02	.01	11890.
1.01	20.30	123	.00	0.00	.00	490.	1.02	21.30	273	.03	.02	.01	11540.
1.01	20.40	124	.00	0.00	.00	492.	1.02	21.40	274	.03	.02	.01	11196.
1.01	20.50	125	.00	0.00	.00	492.	1.02	21.50	275	.03	.02	.01	10436.
1.01	21.00	126	.00	0.00	.00	489.	1.02	22.00	276	.03	.02	.01	10555.
1.01	21.10	127	.00	0.00	.00	485.	1.02	22.10	277	.03	.02	.01	10056.
1.01	21.20	128	.00	0.00	.00	479.	1.02	22.20	278	.03	.02	.01	9647.
1.01	21.30	129	.00	0.00	.00	471.	1.02	22.30	279	.03	.02	.01	9220.
1.01	21.40	130	.00	0.00	.00	462.	1.02	22.40	280	.03	.02	.01	4788.
1.01	21.50	131	.00	0.00	.00	451.	1.02	22.50	281	.03	.02	.01	8444.
1.01	22.00	132	.00	0.00	.00	439.	1.02	23.00	282	.03	.02	.01	7944.
1.01	22.10	133	.00	0.00	.00	425.	1.02	23.10	283	.03	.02	.01	7441.
1.01	22.20	134	.00	0.00	.00	411.	1.02	23.20	284	.03	.02	.01	7156.
1.01	22.30	135	.00	0.00	.00	394.	1.02	23.30	285	.03	.02	.01	6797.
1.01	22.40	136	.00	0.00	.00	376.	1.02	23.40	286	.03	.02	.01	6450.
1.01	22.50	137	.00	0.00	.00	357.	1.02	23.50	287	.03	.02	.01	6117.
1.01	23.00	138	.00	0.00	.00	340.	1.03	0.00	288	.03	.02	.01	5797.
1.01	23.10	139	.00	0.00	.00	322.	1.03	.10	289	.00	0.00	0.00	5449.
1.01	23.20	140	.00	0.00	.00	304.	1.03	.20	290	.00	0.00	0.00	5197.
1.01	23.30	141	.00	0.00	.00	288.	1.03	.30	291	.00	0.00	0.00	4914.
1.01	23.40	142	.00	0.00	.00	272.	1.03	.40	292	.00	0.00	0.00	4654.
1.01	23.50	143	.00	0.00	.00	257.	1.03	.50	293	.00	0.00	0.00	4411.
1.02	0.00	144	.00	0.00	.00	243.	1.03	1.00	294	.00	0.00	0.00	4181.
1.02	.10	145	.02	.01	.01	229.	1.03	1.10	295	.00	0.00	0.00	3944.
1.02	.20	146	.02	.01	.01	215.	1.03	1.20	296	.00	0.00	0.00	3754.
1.02	.30	147	.02	.01	.01	203.	1.03	1.30	297	.00	0.00	0.00	3563.
1.02	.40	148	.02	.01	.01	191.	1.03	1.40	298	.00	0.00	0.00	3381.
1.02	.50	149	.02	.01	.01	180.	1.03	1.50	299	.00	0.00	0.00	3210.
1.02	1.00	150	.02	.01	.01	171.	1.03	2.00	300	.00	0.00	0.00	3047.

SUM 27.24 24.47 2.40 60193.  
( 693.11 632.11 61.11704.54)

CF5	PF4K	9-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
13240.	11014.	4050.	2002.	600472.	
375.	312.	115.	57.	17003.	
	15.07	22.16	22.42	22.42	
	382.89	562.94	579.57	579.57	
	5454.	4034.	8271.	8271.	
	6740.	9909.	10202.	10202.	

Sh. 9

HYDROGRAPH AT STAINFLOW FOR PLAN 1. H110 1

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	263.	220.	41.	40.	12009.
CMS	7.	6.	2.	1.	340.
INCHES		.30	.44	.46	.46
MM		7.66	11.26	11.59	11.59
AC-FT		109.	161.	165.	165.
THOUS CU M		135.	192.	204.	204.

HYDROGRAPH AT STAINFLO FOR PLAN 1. RTIO 2

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	397.	331.	122.	60.	18014.
CMS	11.	9.	3.	2.	510.
INCHES		.45	.66	.68	.68
MM		11.49	16.89	17.39	17.39
AC-FT		164.	241.	248.	248.
THOUS CU M		202.	297.	306.	306.

HYDROGRAPH AT STAINFLO FOR PLAN 1. RTIO 3

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	530.	441.	162.	40.	24014.
CMS	15.	12.	5.	2.	640.
INCHES		.60	.89	.91	.91
MM		15.32	22.52	23.14	23.14
AC-FT		219.	321.	331.	331.
THOUS CU M		270.	396.	408.	408.

HYDROGRAPH AT STAINFLO FOR PLAN 1. RTIO 4

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	662.	551.	203.	100.	30024.
CMS	19.	16.	6.	3.	850.
INCHES		.75	1.11	1.14	1.14
MM		19.14	28.15	28.98	28.98
AC-FT		273.	402.	414.	414.
THOUS CU M		337.	495.	510.	510.

HYDROGRAPH AT STAINFLO FOR PLAN 1. RTIO 5

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	132.	1102.	405.	200.	60047.
CMS	37.	31.	11.	6.	1700.
INCHES		1.51	2.22	2.28	2.28
MM		34.29	56.29	57.96	57.96
AC-FT		540.	803.	827.	827.
THOUS CU M		674.	991.	1020.	1020.

HYDROGRAPH AT STAINFLO FOR PLAN 1. RTIO 6

Sh. 10

PEAK 6-HOUR 24-HOUR 72-HOUR TOTAL VOLUME  
 1946. 1653. 604. 300. 90071.  
 56. 47. 17. 4. 2551.  
 INCHES 2.26 3.32 3.42 3.42 46.94  
 MM 57.43 84.44 86.94 86.94 1241.  
 AC-FT 420. 1205. 1241. 1241. 1530.  
 T-HOUS CU M 1011. 1486. 1530.

HYDROGRAPH AT STAINFLOW FOR PLAN 1, MTIO 7

PEAK 6-HOUR 24-HOUR 72-HOUR TOTAL VOLUME  
 3310. 2755. 1013. 500. 150114.  
 94. 78. 29. 14. 4251.  
 INCHES 3.77 5.54 5.70 5.70 5.70  
 MM 95.72 140.74 144.89 144.89 144.89  
 AC-FT 1366. 2008. 2048. 2048. 2068.  
 T-HOUS CU M 1685. 2477. 2551.

HYDROGRAPH AT STAINFLOW FOR PLAN 1, MTIO 8

PEAK 6-HOUR 24-HOUR 72-HOUR TOTAL VOLUME  
 6020. 5510. 2025. 1001. 300234.  
 187. 156. 57. 28. 4502.  
 INCHES 7.54 11.08 11.41 11.41 11.41  
 MM 191.44 281.47 289.79 289.79 289.79  
 AC-FT 2732. 4017. 4135. 4135. 4135.  
 T-HOUS CU M 3370. 4955. 5101.

HYDROGRAPH AT STAINFLOW FOR PLAN 1, MTIO 9

PEAK 6-HOUR 24-HOUR 72-HOUR TOTAL VOLUME  
 13240. 11019. 4050. 2002. 600472.  
 375. 312. 115. 57. 17003.  
 INCHES 15.07 22.16 22.82 22.82 22.82  
 MM 382.89 562.94 579.57 579.57 579.57  
 AC-FT 5444. 8034. 8271. 8271. 8271.  
 T-HOUS CU M 4740. 9909. 10202.

\*\*\*\*\*

HYDROGRAPH ROUTING

OUTFLOW FROM LAKE COMU DAM

ISTAR ICOMP IFCON ITAPE JPLT JPHI INAME ISTAGE IAUTO  
 0.00 0.000 0.00 1 0 0 0 0 0  
 ROUTING DATA  
 ISTAR ICOMP IFCON ITAPE JPLT JPHI INAME ISTAGE IAUTO  
 0.00 0.000 0.00 1 0 0 0 0 0  
 Sh. 11

NSTPS 1 NSTOL 0 LAG 0 AMSKK 0.000 A TSK 0.000 STORA ISPVAF  
 -15.

STAGE 14.00 15.10 16.60 17.60 18.10 18.60 19.60 21.60  
 22.60

FLOW 0.00 99.00 160.00 184.00 726.00 1683.00 4248.00 7574.00  
 11509.00

SURFACE AREA= 0. 46. 71. 124.

CAPACITY= 0. 134. 312. 794.

ELEVATION= 6. 15. 18. 23.

CHEL SPWID CUW EXPW ELEV COUL CAWEA EXPL  
 14.6 0.0 0.0 0.0 0.0 0.0 0.0 0.0

DAM DATA  
 TOPEL CUOD EXPD DAMWID  
 17.6 0.0 0.0 0.0

STATION OUTLE. PLAN 1, RATIO 1

END-OF-PERIOD HYDROGRAPH ORIGINATES

	OUTFLOW												
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
0.1	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
0.2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
0.3	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
0.4	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
0.5	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
0.6	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
0.7	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
0.8	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
0.9	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
1.0	1.0	1.0	1.0	1.0	1.0	1.0	2.0	2.0	1.0	1.0	2.0	2.0	1.0
1.1	2.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0	3.0
1.2	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0
1.3	5.0	5.0	5.0	5.0	5.0	5.0	5.0	5.0	5.0	5.0	5.0	5.0	5.0
1.4	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0
1.5	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0
1.6	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0
1.7	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0	4.0
1.8	6.0	6.0	6.0	6.0	6.0	6.0	6.0	6.0	6.0	6.0	6.0	6.0	6.0
1.9	8.0	9.0	9.0	10.0	10.0	11.0	11.0	11.0	11.0	11.0	11.0	11.0	11.0
2.0	13.0	13.0	15.0	15.0	16.0	17.0	17.0	17.0	17.0	17.0	17.0	17.0	17.0
2.1	23.0	26.0	28.0	30.0	32.0	34.0	34.0	34.0	34.0	34.0	34.0	34.0	34.0
2.2	48.0	52.0	62.0	64.0	72.0	77.0	77.0	77.0	77.0	77.0	77.0	77.0	77.0
2.3	97.0	103.0	105.0	104.0	110.0	112.0	112.0	112.0	112.0	112.0	112.0	112.0	112.0
2.4	121.0	122.0	122.0	124.0	126.0	127.0	127.0	127.0	127.0	127.0	127.0	127.0	127.0
2.5	132.0	133.0	133.0	133.0	133.0	133.0	133.0	133.0	133.0	133.0	133.0	133.0	133.0
2.6	132.0	131.0	130.0	129.0	129.0	129.0	129.0	129.0	129.0	129.0	129.0	129.0	129.0

STORAGE

Sh. 12





16.1	16.2	16.2	16.2	16.2	16.2	16.2	16.2	16.2	16.2	16.2	16.2	16.2
16.1	16.1	16.1	16.1	16.1	16.1	16.1	16.1	16.1	16.1	16.1	16.1	16.0

PEAK OUTFLOW IS 133. AT TIME 47.50 HOURS

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
	133.	127.	45.	22.	6635.
	4.	4.	1.	1.	188.
	CFS				
	INCHES	.17	.25	.25	.25
	MM	4.40	6.25	6.40	6.40
	AC-FT	63.	89.	91.	91.
	THOUS CU M	77.	110.	113.	113.

STATION OUTFLO. PLAN 1. RATIO 2

END-OF-PERIOD HYDROGRAPH ORDINATES

		OUTFLOW											
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
1.	1.	1.	2.	2.	2.	2.	2.	2.	2.	2.	2.	3.	3.
3.	4.	4.	4.	4.	4.	4.	4.	4.	4.	4.	5.	5.	6.
6.	6.	6.	6.	6.	6.	6.	6.	6.	6.	6.	7.	7.	7.
7.	7.	7.	7.	7.	7.	7.	7.	7.	7.	7.	7.	7.	7.
7.	7.	7.	7.	7.	7.	7.	7.	7.	7.	7.	7.	7.	7.
6.	6.	6.	6.	6.	6.	6.	6.	6.	6.	6.	6.	6.	6.
6.	6.	6.	6.	6.	6.	6.	6.	6.	6.	6.	6.	6.	6.
5.	5.	5.	5.	5.	5.	5.	5.	5.	5.	5.	5.	5.	5.
6.	6.	6.	6.	6.	6.	6.	6.	6.	6.	6.	6.	6.	6.
7.	7.	7.	7.	7.	7.	7.	7.	7.	7.	7.	7.	7.	7.
9.	10.	10.	10.	11.	11.	11.	11.	11.	11.	11.	11.	11.	12.
13.	14.	14.	14.	15.	15.	15.	15.	15.	15.	15.	15.	15.	16.
19.	20.	21.	22.	23.	23.	24.	24.	26.	26.	26.	26.	26.	28.
36.	36.	36.	42.	46.	46.	51.	51.	56.	56.	61.	61.	61.	66.
76.	86.	91.	94.	102.	106.	106.	106.	109.	109.	113.	113.	117.	121.
129.	124.	133.	136.	140.	144.	144.	144.	147.	147.	150.	150.	154.	157.
154.	161.	162.	163.	166.	166.	166.	166.	166.	166.	166.	166.	166.	166.
167.	168.	168.	168.	168.	168.	168.	168.	168.	168.	168.	168.	168.	168.
169.	169.	168.	168.	168.	168.	168.	168.	167.	167.	167.	167.	167.	166.

		STORAGE											
134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.
134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.
134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.
134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.
134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.
134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.
134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.
134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.
134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.
134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.
134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.
134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.
134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.
134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.	134.









147.	147.	147.	144.	148.	148.	149.	149.	149.	149.	150.
150.	151.	151.	152.	152.	153.	153.	154.	154.	155.	156.
156.	157.	158.	159.	161.	162.	163.	165.	167.	167.	169.
171.	173.	176.	179.	182.	185.	188.	192.	196.	196.	200.
205.	210.	215.	220.	226.	232.	238.	244.	251.	251.	257.
264.	270.	277.	284.	291.	297.	304.	310.	316.	316.	321.
325.	327.	330.	331.	332.	333.	333.	333.	333.	333.	332.
331.	331.	330.	329.	328.	327.	326.	325.	325.	325.	322.
321.	320.	319.	318.	317.	317.	316.	315.	314.	314.	313.
STAGE										
14.6	14.6	14.6	14.6	14.6	14.6	14.6	14.6	14.6	14.6	14.6
14.6	14.6	14.6	14.6	14.6	14.6	14.6	14.6	14.6	14.6	14.6
14.6	14.6	14.6	14.6	14.6	14.6	14.6	14.6	14.6	14.6	14.6
14.6	14.6	14.6	14.6	14.6	14.6	14.6	14.6	14.6	14.6	14.6
14.6	14.6	14.6	14.6	14.6	14.6	14.6	14.6	14.6	14.6	14.6
14.6	14.6	14.6	14.6	14.6	14.6	14.6	14.6	14.6	14.6	14.6
14.6	14.6	14.6	14.6	14.6	14.6	14.6	14.6	14.6	14.6	14.6
14.6	14.6	14.6	14.6	14.6	14.6	14.6	14.6	14.6	14.6	14.6
14.6	14.6	14.6	14.6	14.6	14.6	14.6	14.6	14.6	14.6	14.6
14.6	14.6	14.6	14.6	14.6	14.6	14.6	14.6	14.6	14.6	14.6
14.7	14.7	14.7	14.7	14.7	14.7	14.7	14.7	14.7	14.7	14.7
14.7	14.7	14.7	14.7	14.7	14.7	14.7	14.7	14.7	14.7	14.7
14.7	14.7	14.7	14.7	14.7	14.7	14.7	14.7	14.7	14.7	14.7
14.7	14.7	14.7	14.7	14.7	14.7	14.7	14.7	14.7	14.7	14.7
14.7	14.7	14.7	14.7	14.7	14.7	14.7	14.7	14.7	14.7	14.7
14.7	14.7	14.7	14.7	14.7	14.7	14.7	14.7	14.7	14.7	14.7
14.8	14.8	14.8	14.8	14.8	14.8	14.8	14.8	14.8	14.8	14.8
14.8	14.8	14.8	14.8	14.8	14.8	14.8	14.8	14.8	14.8	14.8
14.9	14.9	14.9	14.9	14.9	14.9	14.9	14.9	15.0	15.0	15.0
15.0	15.0	15.0	15.0	15.1	15.1	15.1	15.2	15.2	15.2	15.2
15.3	15.3	15.4	15.4	15.5	15.5	15.5	15.7	15.8	15.8	15.8
15.9	16.0	16.1	16.2	16.3	16.4	16.5	16.6	16.7	16.7	16.8
16.9	17.0	17.1	17.2	17.3	17.4	17.5	17.6	17.7	17.7	17.7
17.8	17.8	17.8	17.9	17.9	17.9	17.9	17.9	17.9	17.9	17.9
17.9	17.9	17.8	17.8	17.8	17.8	17.8	17.8	17.8	17.8	17.7
17.7	17.7	17.7	17.7	17.7	17.7	17.6	17.6	17.6	17.6	17.6

PEAK OUTFLOW IS 496. AT TIME 06.17 HOURS

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL	VOLUME
CFS	496.	349.	117.	58.	17272.	
CMS	14.	10.	3.	2.	489.	
INCHES		.48	.64	.66		.66
MM		12.14	16.28	16.67		16.67
AC-FT		173.	232.	238.		238.
TOTAL CUM		214.	287.	293.		293.

STATION OUTFLO. PLAN 1, RATIO 5

8-HOUR-OF-PERIOD HYDROGRAPH ORDINATE:

OUTFLOW

Sh. 19

PRINTED IN U.S.A.













14.6	14.7	14.8	14.9	15.0	15.1	15.2	15.3	15.4	15.5	15.6	15.7	15.8	15.9	16.0	16.1	16.2	16.3	16.4	16.5	16.6	16.7	16.8	16.9	17.0	17.1	17.2	17.3	17.4	17.5	17.6	17.7	17.8	17.9	18.0	18.1	18.2	18.3	18.4	18.5	18.6	18.7	18.8	18.9	19.0	19.1	19.2	19.3	19.4	19.5	19.6	19.7	19.8	19.9	20.0
14.6	14.7	14.8	14.9	15.0	15.1	15.2	15.3	15.4	15.5	15.6	15.7	15.8	15.9	16.0	16.1	16.2	16.3	16.4	16.5	16.6	16.7	16.8	16.9	17.0	17.1	17.2	17.3	17.4	17.5	17.6	17.7	17.8	17.9	18.0	18.1	18.2	18.3	18.4	18.5	18.6	18.7	18.8	18.9	19.0	19.1	19.2	19.3	19.4	19.5	19.6	19.7	19.8	19.9	20.0
14.6	14.7	14.8	14.9	15.0	15.1	15.2	15.3	15.4	15.5	15.6	15.7	15.8	15.9	16.0	16.1	16.2	16.3	16.4	16.5	16.6	16.7	16.8	16.9	17.0	17.1	17.2	17.3	17.4	17.5	17.6	17.7	17.8	17.9	18.0	18.1	18.2	18.3	18.4	18.5	18.6	18.7	18.8	18.9	19.0	19.1	19.2	19.3	19.4	19.5	19.6	19.7	19.8	19.9	20.0
14.6	14.7	14.8	14.9	15.0	15.1	15.2	15.3	15.4	15.5	15.6	15.7	15.8	15.9	16.0	16.1	16.2	16.3	16.4	16.5	16.6	16.7	16.8	16.9	17.0	17.1	17.2	17.3	17.4	17.5	17.6	17.7	17.8	17.9	18.0	18.1	18.2	18.3	18.4	18.5	18.6	18.7	18.8	18.9	19.0	19.1	19.2	19.3	19.4	19.5	19.6	19.7	19.8	19.9	20.0

PEAK OUTFLOW IS 3275. AT TIME 46.50 HOURS

PLAN	CFS	5-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
3275.	918.	2731.	918.	448.	134301.
93.	26.	77.	13.		3803.
INCHES		3.74	5.02	5.10	5.10
MM		96.88	127.62	129.63	129.63
AC-FI		135%	1821.	1850.	1850.
1000'S CU '4		1670.	2266.	2282.	2282.

STATION OUTFLO. PLAN 1. RATIO 8  
END-OF-PERIOD HYDROGRAPH UMINATES

0.	1.	2.	3.	4.	5.	6.	7.	8.	9.	10.	11.	12.	13.	14.	15.	16.	17.	18.	19.	20.	21.	22.	23.	24.	25.	26.	27.	28.	29.	30.	31.	32.	33.	34.	35.	36.	37.	38.	39.	40.	41.	42.	43.	44.	45.	46.	47.	48.	49.	50.
0.	1.	2.	3.	4.	5.	6.	7.	8.	9.	10.	11.	12.	13.	14.	15.	16.	17.	18.	19.	20.	21.	22.	23.	24.	25.	26.	27.	28.	29.	30.	31.	32.	33.	34.	35.	36.	37.	38.	39.	40.	41.	42.	43.	44.	45.	46.	47.	48.	49.	50.
0.	1.	2.	3.	4.	5.	6.	7.	8.	9.	10.	11.	12.	13.	14.	15.	16.	17.	18.	19.	20.	21.	22.	23.	24.	25.	26.	27.	28.	29.	30.	31.	32.	33.	34.	35.	36.	37.	38.	39.	40.	41.	42.	43.	44.	45.	46.	47.	48.	49.	50.
0.	1.	2.	3.	4.	5.	6.	7.	8.	9.	10.	11.	12.	13.	14.	15.	16.	17.	18.	19.	20.	21.	22.	23.	24.	25.	26.	27.	28.	29.	30.	31.	32.	33.	34.	35.	36.	37.	38.	39.	40.	41.	42.	43.	44.	45.	46.	47.	48.	49.	50.
0.	1.	2.	3.	4.	5.	6.	7.	8.	9.	10.	11.	12.	13.	14.	15.	16.	17.	18.	19.	20.	21.	22.	23.	24.	25.	26.	27.	28.	29.	30.	31.	32.	33.	34.	35.	36.	37.	38.	39.	40.	41.	42.	43.	44.	45.	46.	47.	48.	49.	50.

Sh. 25



PEAK OUTFLOW IS 6568 AT TIME 44.33 HOURS											
	15.6	15.6	15.6	15.6	15.6	15.6	15.6	15.6	15.6	15.6	15.6
15.6	15.6	15.6	15.6	15.6	15.6	15.6	15.6	15.6	15.6	15.6	15.6
15.6	15.6	15.6	15.6	15.6	15.6	15.6	15.6	15.6	15.6	15.6	15.6
15.7	15.8	15.8	15.8	15.9	15.9	15.9	16.0	16.0	16.0	16.1	16.1
16.2	16.2	16.3	16.4	16.4	16.4	16.5	16.5	16.6	16.6	16.7	16.8
16.8	16.9	17.0	17.1	17.2	17.3	17.4	17.5	17.6	17.7	17.7	17.7
17.8	17.9	18.0	18.1	18.2	18.3	18.3	18.4	18.4	18.5	18.5	18.6
18.6	18.7	18.8	18.9	19.0	19.0	19.1	19.1	19.2	19.3	19.4	19.4
19.5	19.5	19.7	19.8	19.9	19.9	20.0	20.0	20.1	20.1	20.2	20.2
20.2	20.2	20.3	20.3	20.3	20.3	20.3	20.3	20.3	20.3	20.3	20.3
20.2	20.2	20.1	20.1	20.1	20.0	20.0	19.9	19.9	19.8	19.8	19.8
19.7	19.5	19.6	19.5	19.4	19.4	19.4	19.4	19.2	19.2	19.2	19.1
19.0	19.0	18.9	18.9	18.8	18.8	18.8	18.7	18.7	18.7	18.7	18.6

	PEAK	5-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	6568	576	1929	940	281955
CMS	186	155	55	27	7984
INCHES	7.49	10.56	10.71	10.71	272.15
MM	190.27	268.11	272.15	272.15	3884
AC-FT	2715	3826	3884	3884	4791
T-00'S CU	3369	4719	4791	4791	

STATION OUTFLOW PLAN 1.0 RATIO 9											
END-OF-PERIOD HYDROGRAPH ORDINATES											
	0.	1.	1.	1.	1.	1.	1.	1.	1.	1.	2.
0.	0.	1.	1.	1.	1.	1.	1.	1.	1.	1.	2.
2.	2.	2.	2.	2.	2.	2.	2.	2.	2.	2.	2.
2.	2.	2.	2.	2.	2.	2.	2.	2.	2.	2.	2.
2.	2.	2.	2.	2.	2.	2.	2.	2.	2.	2.	2.
1.	1.	1.	1.	1.	1.	1.	1.	1.	1.	1.	1.
1.	1.	1.	1.	1.	1.	1.	1.	1.	1.	1.	1.
1.	1.	1.	1.	1.	1.	1.	1.	1.	1.	1.	1.
1.	1.	1.	1.	1.	1.	1.	1.	1.	1.	1.	1.
4.	6.	7.	9.	12.	14.	18.	21.	26.	26.	30.	30.
35.	42.	51.	60.	69.	79.	84.	99.	105.	105.	110.	110.
115.	121.	126.	131.	137.	142.	146.	151.	155.	155.	160.	160.
161.	163.	164.	165.	166.	168.	169.	170.	171.	171.	171.	171.
172.	172.	173.	173.	174.	174.	174.	174.	174.	174.	174.	174.
174.	174.	174.	174.	174.	173.	173.	173.	173.	173.	173.	173.
172.	172.	171.	171.	171.	171.	171.	170.	170.	170.	170.	170.
170.	170.	169.	169.	169.	169.	169.	169.	169.	169.	169.	169.
169.	169.	169.	169.	169.	169.	169.	170.	170.	170.	170.	170.
170.	171.	171.	172.	172.	173.	174.	175.	175.	175.	177.	177.
178.	179.	181.	183.	185.	269.	333.	390.	442.	442.	490.	490.
534.	575.	614.	651.	685.	718.	767.	814.	856.	856.	895.	895.
934.	973.	1015.	1061.	1111.	1147.	1229.	1300.	1381.	1381.	1473.	1473.
1577.	1698.	1847.	2042.	2228.	2426.	2639.	2872.	3129.	3129.	3407.	3407.
3711.	4040.	4424.	4868.	5304.	5744.	6142.	6649.	7118.	7118.	7605.	7605.
8166.	8710.	9242.	9760.	10256.	10726.	11164.	11570.	11966.	11966.	12298.	12298.
12790.	12790.	12956.	13070.	13137.	13160.	13139.	13070.	12950.	12950.	12785.	12785.
12580.	12319.	12068.	11770.	11453.	11139.	10791.	10419.	10025.	10025.	9613.	9613.

Sh. 27





PEAK	19.4	19.5	19.7	19.8	19.9	20.0	20.1	20.2	20.3	20.4	20.5	20.6
19.4	19.5	19.7	19.8	19.9	20.0	20.1	20.2	20.3	20.4	20.5	20.6	20.7
20.9	21.0	21.2	21.3	21.4	21.5	21.6	21.7	21.8	21.9	21.9	21.9	21.9
21.9	21.9	21.9	22.0	22.0	22.0	22.0	22.0	21.9	21.9	21.9	21.9	21.9
21.8	21.8	21.7	21.6	21.5	21.4	21.3	21.2	21.1	21.0	20.9	20.8	20.7
21.0	20.9	20.8	20.7	20.6	20.5	20.4	20.3	20.2	20.1	20.0	19.9	19.8
20.0	19.9	19.8	19.7	19.6	19.5	19.4	19.3	19.2	19.1	19.0	18.9	18.8

PEAK OUTFLOW IS 13160. AT TIME 44.33 HOURS

PEAK	13160.	10968.	3927.	1927.	577971.
LES	13160.	10968.	3927.	1927.	577971.
CMS	373.	311.	112.	55.	16366.
INCHES	15.00	21.71	21.96	21.96	21.96
MM	381.09	551.33	557.85	557.85	557.85
AC-FT	5439.	7868.	7961.	7961.	7961.
T-00S CU M	6708.	9705.	9820.	9820.	9820.

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS  
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)  
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION	STATION	AREA	PLAN	RATIO 1	RATIO 2	RATIO 3	RATIO 4	RATIO 5	RATIO 6	RATIO 7	RATIO 8	RATIO 9
HYDROGRAPH AT INFLW	( 17.61 )	6.80	1	265.	397.	530.	662.	1324.	1986.	3110.	5620.	13240.
				( 7.50 )	( 11.25 )	( 15.00 )	( 18.75 )	( 37.49 )	( 56.24 )	( 93.73 )	( 167.46 )	( 375.92 )
ROUTED TO	( 17.61 )	6.80	1	133.	169.	278.	496.	1289.	1964.	3275.	6568.	13160.
				( 3.77 )	( 4.78 )	( 7.86 )	( 14.03 )	( 36.49 )	( 55.63 )	( 92.74 )	( 185.99 )	( 372.44 )

RATIOS APPLIED TO FLOWS

OPERATION	STATION	AREA	PLAN	RATIO 1	RATIO 2	RATIO 3	RATIO 4	RATIO 5	RATIO 6	RATIO 7	RATIO 8	RATIO 9
				.02	.03	.04	.05	.10	.15	.25	.50	1.00

SUMMARY OF DAM SAFETY ANALYSIS


PLAN 1	ELEVATION STORAGE	INITIAL VALUE	SPILLWAY CREST	TOP OF DAM	DURATION OVER TOP	TIME OF MAX OUTFLOW	TIME OF FAILURE
		14.60	14.60	17.60	0.00	47.50	0.00
		138.	138.	312.	0.00	48.17	0.00
		0.	0.	144.	0.00	47.50	0.00
					5.33	45.17	0.00
					7.67	44.67	0.00
					8.87	44.50	0.00
					9.83	44.50	0.00
					12.00	44.33	0.00
					16.00	44.33	0.00

Sh. 29

APPENDIX

D

Photographs



US ARMY CORPS OF ENGINEERS PHILADELPHIA DISTRICT	
LAKE COMO DAM SITE PLAN	
OBRIENBERGER	AUGUST 1980 SMS

**LEGEND**

The location and direction in which each photo was taken and the number of the photo.

APPENDIX D  
SELECTED PHOTOGRAPHS OF THE SITE

LOCATION PLAN

Page No.


Site Plan Sketch

A

PHOTOGRAPHS

Page No.

- |    |   |   |
|----|---|---|
| 1. | Upstream overview looking towards right abutment.   | 1 |
| 2. | View of multiple drop inlet spillway, access bridge and operators for low-level outlet.                   | 1 |
| 3. | View showing the zone of failure at the right abutment which was prevented from breaching by sandbagging. | 2 |
| 4. | View showing failure zone looking towards left abutment.  | 2 |
| 5. | View exhibiting undermining of restaurant downstream of the right abutment.                               | 3 |
| 6. | View of failure zone looking towards right abutment.  | 3 |
| 7. | View exhibiting contact between embankment fill on left and natural abutment material on right.           | 4 |
| 8. | Operator for low-level outlet.  | 4 |



1. UPSTREAM OVERVIEW LOOKING TOWARDS RIGHT ABUTMENT.  
(8/12/80)



2. VIEW OF MULTIPLE DROP INLET SPILLWAY, ACCESS BRIDGE  
AND OPERATORS FOR LOW-LEVEL OUTLET.  
(8/12/80)



3. VIEW SHOWING THE ZONE OF FAILURE AT THE RIGHT ABUTMENT WHICH WAS PREVENTED FROM BREACHING BY SAND-BAGGING.

(8/12/80)



4. VIEW SHOWING FAILURE ZONE LOOKING TOWARDS LEFT ABUTMENT. NOTE THE RUPTURED 6" WATER AND 4" GAS LINES.


(8/12/80)




5. VIEW EXHIBITING UNDERMINING OF RESTAURANT DOWN-  
STREAM OF THE RIGHT ABUTMENT. AUTO IN LEFT BACKGROUND  
IS TRAVELING UPON U.S. ROUTE 13.  
(8/12/80)



6. VIEW OF FAILURE ZONE LOOKING TOWARDS RIGHT ABUT-  
MENT. AREA OF OVERTOPPING EXTENDED ABOUT 500 FEET TO  
CEMETARY IN BACKGROUND.  
(8/12/80)



7. VIEW EXHIBITING CONTACT BETWEEN EMBANKMENT FILL ON  
LEFT AND NATURAL ABUTMENT MATERIAL ON RIGHT.  
(8/12/80)



8. OPERATOR FOR  
LOW-LEVEL OUTLET.  
(8/12/80)



APPENDIX


E

Drawings


SUBJECT LAKE COMO DAM	SHEET	BY	DATE	JOB NO.
--------------------------	-------	----	------	---------

APPENDIX E  
TABLE OF CONTENTS  
DRAWINGS

	<u>Sheet No.</u>
Figure 1, Regional Vicinity Map	1
Site Plan Showing Failure Zone	2
Topographic Survey Data (Post Failure)	3
March 1941 Site Plan, J.E. HADDAWAY ENGINEER	4
Plan & Section, Inlet Heads, 3/41	5
Profile, Drop Inlets, 3/41	6
Embankment Profile & Section, 3/41	7
Teletype Letter from Corps of Engineers to State of Delaware	8-9



Lake  
Como




Cemetery

SIDWALK

MAIN ST

U.S. ROUTE 13

1



SHEET 2

US ARMY CORPS OF ENGINEERS  
PHILADELPHIA DISTRICT

LAKE COMO DAM  
SITE PLAN



O'BRIEN & GERE

AUGUST 1980


SHS

LAKE CO

DR  
Spi

END 24. (24.00)


Cemetery




U.S. ROUTE 13 N.B.

Topographic Survey Lines  
Elevations @ 25' Intervals


Topographic Survey Lines  
Elevs. @ 10' Intervals and at  
limits of failure zone



- NOTES
1. LINE "B" WAS ESTABLISHED JUST BEHIND SIDEWALK, NOT ON SIDEWALK
  2. DATUM = USCGGS
  3. I.E. = INVERT ELEVATION



SMYRNA, DE  
 LAKE COMO DAM  
 SITE PLAN  
 1"=50'  
 SHEET 3




**DROP INLET SPILLWAY**  
**LAKE COMO**  
 SMYRNA, DELAWARE.  
 PROJECT - TOWN COMMISSIONERS  
 PLAYGROUND - RECREATION COMM'T.

**SHEET NO. ①**

J. E. HADDAWAY ENGINEER  
 WYOMING, DELAWARE  
 FROM DESIGNS OF PROF. L. H. KESSLER  
 UNIVERSITY OF WISC.  
 MARCH - 1941.


PLA  
 Scale 1"






AN  
 1" = 50.0'


SHEET 4



PLAN OF HEADS  
 See No. 20, 191, SHEET 2.  
 1" = 4.0'



INLET HEAD  
 SHOWING I.S.C. CON. PIPE  
 Scale 1" = 4.0'




# DROP INLET SPILLWAY LAKE COMO

SMYRNA, DELAWARE.  
PROJECT - TOWN COMMISSIONERS  
PLAYGROUND - RECREATION COMM'T.

SHEET NO. ①

J. E. HADDAWAY ENGINEER  
WYOMING, DELAWARE  
FROM DESIGNS OF PROF. L. H. KESSLER  
UNIVERSITY OF WISC.  
MARCH - 1941.




16'-0"

7'-0"

El. = 26.5'


CONCRETE  
BULKHEAD FINS

JOINT COLLARS




SHEET 5

TO COMMISSION ST



Guard Rails



DROP INLETS  
 FINISHED ELEVATION  
 SC011=4.0'  
 UP-STREAM SIDE.


# DROP INLET SPILLWAY LAKE COMO

SMYRNA, DELAWARE.  
 PROJECT-TOWN COMMISSIONERS  
 PLAYGROUND-RECREATION COMM'T.


SHEET NO. ①

J. E. HADDAWAY ENGINEER  
 WYOMING, DELAWARE.  
 FROM DESIGNS OF PROF. L. H. KESSLER  
 UNIVERSITY OF WISC.  
 MARCH - 1941.


SHEET 6



PRESENT ELEV. - U  
 Scale 1" = 50.0'



PRESENT TYPICAL  
 CROSS SEC.  
 Scale 1" = 20.0'



TEMPORARY WOOD  
 BRIDGE  
 Showing Flood Gate Wash  
 UP-STREAM ELEVATION  
 Scale 1" = 20.0'

265.0'

El. = 28.5'  
Normal High Water  
Present Lake Bed  
El. = 27.0'  
El. = 24.0'

ELEV. - UP STREAM  
1" = 50.0'




ENT TYPICAL  
SECTION  
1" = 20'

**DROP INLET SPILLWAY**  
**LAKE COMO**  
SMYRNA, DELAWARE.  
PROJECT - TOWN COMMISSIONERS  
PLAYGROUND - RECREATION COMM'T.

SHEET NO. ①

J. E. HADDAWAY ENGINEER  
WYOMING, DELAWARE  
FROM DESIGNS OF PROF. L. H. KESSLER  
UNIVERSITY OF WISC.  
MARCH - 1941.




WOOD  
GE  
ate Wash-out  
ELEVATION  
20.0'

MAILGRAM SERVICE CENTER  
MIDDLETOWN, VA. 22645

LL L L L  
MAILGRAM

MAILGRAM



4-045806S232002 08/19/80 ICS IPMMTZZ CSP PHAB  
1 2155974756 MGM TDMT PHILADELPHIA PA 08-19 0355P EST

ARMY CORP OF ENGINEERS J MEEHAN RMD ATTN B  
HEVERIN  
CUSTOM HOUSE 2 AND CHESTNUT ST  
PHILADELPHIA PA 19106

THIS MAILGRAM IS A CONFIRMATION COPY OF THE FOLLOWING MESSAGE:

2155974756 TDMT PHILADELPHIA PA 468 08-19 0355P EST  
PMS R D BEWICK JR DIRECTOR DIV HIGHWAYS RPT DLY MGM, DLR  
DEPT OF TRANSPORTATION OFFICE OF ADMINISTRATION  
DUVER DE 99901  
SUBJECT LAKE COMO SMYRNA DELAWARE

AT THE REQUEST OF MR KIRSHNA PATEL OF THE DIVISION OF SOIL AND WATER CONSERVATION DEPARTMENT OF NATURAL RESOURCES AND ENVIRONMENTAL CONTROL REPRESENTATIVES OF THIS OFFICE CONDUCTED A PHASE I INSPECTION OF LAKE COMO DAM IN SMYRNA ON 12 AUGUST 1980 THIS INSPECTION WAS REQUESTED BECAUSE OF THE DAMS CONDITION AS A RESULT OF THE OVERTOPPING WHICH OCCURRED ON 29 JULY 1980 IN RESPONSE TO MR PATEL'S REQUEST WE ARE HEREBY TRANSMITTING PRELIMINARY ENTRANT RECOMMENDATIONS FOR IMMEDIATE REMEDIAL ACTIONS THAT SHOULD BE UNDERTAKEN AT LAKE COMO DAM UNTIL PERMANENT REPAIRS ARE COMPLETED A FOREMAN PHASE 1 INSPECTION REPORT WILL BE ISSUED AT APPROXIMATELY TWO (2) MONTHS

A. AT THE CONCLUSION OF THE VISUAL INSPECTION OF THE DAM WE RECOMMEND THE LAKE BE LOWERED TWO (2) FEET UNTIL REPAIRS ARE COMPLETED WE ARE NOW RECOMMENDING THAT IT BE LOWERED AN ADDITIONAL FOOT TO A TOTAL OF THREE (3) FEET BELOW THE CREST OF THE SPILLWAY PIPE RISERS UNTIL REPAIRS ARE MADE IN ORDER TO INCREASE THE LAKES IMPOUNDING CAPACITY

B. CONTINUOUS MONITORING OF THE LAKE LEVEL SHOULD BE CONDUCTED DURING PERIODS OF HEAVY PERCIPITATION SO THAT INCREASED IN THE LAKE LEVEL CAN MINIMIZED

C. THE DAMS OWNERS SHOULD DEVELOP AN EMERGENCY ACTION PLAN OUTLINING ACTIONS TO BE TAKEN BY THE OPERATOR TO MINIMIZE DOWNSTREAM EFFECTS OF AN EMERGENCY AT THE DAM AND A DOWNSTREAM WARNING SYSTEM FOR THE LAKE COMO SUBSHOP THE ROUTE 13 HIGHWAY THE SEWAGE PUMPING STATION AND LOCAL EMERGENCY OFFICIALS

D. THE EMBANKMENT SHOULD BE INSPECTED PERIODICALLY BY AN EXPERIENCED ENGINEER FOR SIGNS OF SEEPAGE OR ADDITIONAL SLOUGHING UNTIL PERMANENT REPAIRS ARE MADE

SHEET 8



E. USING CORPS OF ENGINEERS SCREENING CRITERION THE SPILLWAY IS CONSIDERED INADEQUATE AS A FLOW EQUIVALENT TO 5 PERCENT OF THE ONE HALF PMF OR NINE (9) PERCENT OF THE 100 YEAR FLOOD WOULD CAUSE A DAM TO BE OVERTOPPED THEREFORE THE OWNER SHOULD ENGAGE A QUALIFIED PROFESSIONAL CONSULTANT USING MORE PERCISE METHODS PROCEDURES AND STUDIES TO DETERMINE THE ACTUAL CAPACITY OF THE SPILLWAY AND ANY MITIGATING MEASURES NECESSARY

F. BORINGS SHOULD BE TAKING THROUGH THE EMBANKMENT AND FOUNDATION TO DETERMINE SOIL TYPES IN-PLACE DENSITIES AND OTHER SOIL PROPERTIES

G. A DETAILED TOPOGRAPHIC SURVEY OF THE EMBANKMENT FROM THE UPSTREAM SLOPE TO THE ROUTE 13 BRIDGE SHOULD BE MADE

H. GAS LINES AND WATER LINES SHOULD BE REMOVED FROM THE EMBANKMENT AND RELOCATED

I. THE OWNERS SHOULD ENGAGE A QUALIFIED PROFESSIONAL CONSULTANT EXPERIENCED IN THE DESIGN AND CONSTRUCTION OF DAMS TO DESIGN AN ADEQUATE EMBANKMENT SECTION FOR THE DAM

2. REPRESENTATIVES OF THIS OFFICE ARE AVAILABLE TO DISCUSS POSSIBLE SPILLWAY AND EMBANKMENT REMEDIAL MEASURES AND COST ESTIMATES WITH THE DIVISION OF SOIL AND WATER CONSERVATION DIVISION OF HIGHWAYS AND THE CITY OF SMYRNA UNDER OUR TECHNICAL ASSISTANCE CAPABILITIES AT THEIR CONVENIENCE YOUR COOPERATION IN THIS MATTER IS APPRECIATED

JOEL T CALLAHAN LT COL CORP OF ENGINEERS ACTING DISTRICT ENGINEERS  
CUSTOM HOUSE 2 AND CHESTNUT ST  
PHILADELPHIA PA 19106

15:56 EST

MGMCOMP

AD-A096 058

O'BRIEN AND GERE ENGINEERS INC PHILADELPHIA PA F/G 13/13  
NATIONAL DAM SAFETY PROGRAM. LAKE COMO DAM (DE 00028), DELAWARE--ETC(U)  
NOV 80 J J WILLIAMS DACW61-80-D-0013

DAEN/NAP-53842/DE00028-80/ NL

UNCLASSIFIED

2 of  
204 0



END

DATE

FILED

4 - 11

DTIC

RC

State of Delaware  
DELAWARE GEOLOGICAL SURVEY  
UNIVERSITY OF DELAWARE  
Newark, Delaware  
19711

ROBERT R. JORDAN, STATE GEOLOGIST  
101 PENNY HALL  
PHONE: 302-738-2833, 2834

August 15, 1980

Mr. J. J. Schuh, Chief of Design  
Division of Highways  
Department of Transportation  
Administration Center  
Dover, DE 19901


Dear Jack:

This will confirm our telephone conversation of this morning in which I passed along to you the flow information for Mill Creek for the storm of July 29. The data were provided by the U. S. Geological Survey as part of the stream gaging program in Delaware. The peak flow below the dam at Lake Como was calculated at 2,520 cfs. USGS staff believe this flow may be near, or perhaps exceed, the flow for the statistical 100-year flood. The flow at the first bridge north of Lake Como was estimated at 1,250 cfs. The difference in flow indicates the large amount of rain that fell within the drainage area of the lake proper, exclusive of the inflow from Mill Creek. This agrees with the precipitation maps recently worked up by John Talley of this office.

These figures are provisional subject to complete review by the USGS. However, the staff of the Dover USGS office feels fairly confident of their accuracy.

We are glad to have been of service and know that you will appreciate the rapid response of our federal cooperators in supplying the data you needed.

Sincerely,

  
Kenneth D. Woodkuff  
Associate Director

KDW:dcw


cc: Art Hodges, USGS

APPENDIX  
F  
SITE GEOLOGY

## SITE GEOLOGY

### LAKE COMO DAM

Lake Como Dam is located in the Coastal Plain physiographic province. The Miocene sediments at the site are primarily bluish gray silts with quartz sand and shell beds. The Chesapeake Group sands and silts were deposited during marine submergence of the Delaware Peninsula and attain depths of over 1,000 feet.



**FIGURE 1**  
**REGIONAL**  
**GEOLOGY MAP**  
**SCALE 1:24000**

