

AD-A099 074


KIMBALL (L ROBERT) AND ASSOCIATES EBENSBURG PA
NATIONAL DAM INSPECTION PROGRAM, COKEBURG WATER SUPPLY DAM (NDI--ETC(U)
APR 81

F/G 13/13

DACW31-81-C-0012
NL

UNCLASSIFIED

1 OF 1
AD A
099074



AD A099074

1

OHIO RIVER BASIN
TRIBUTARY SOUTH BRANCH PIGEON CREEK, WASHINGTON COUNTY

PENNSYLVANIA
National Dam Inspection Program
COKEBURG WATER SUPPLY DAM


NDI ID 100, PA-1094

DER ID 100, 63-30

BOROUGH OF COKEBURG

PHASE I INSPECTION REPORT

NATIONAL DAM INSPECTION PROGRAM



April 1981

75

Prepared By

L. ROBERT KIMBALL & ASSOCIATES

CONSULTING ENGINEERS & ARCHITECTS

EBENSBURG, PENNSYLVANIA

15931

FOR

DEPARTMENT OF THE ARMY

BALTIMORE DISTRICT CORPS OF ENGINEERS

BALTIMORE, MARYLAND

21203

This document is the property of the Department of the Army and is loaned to you for your use only. It is not to be distributed outside your agency.

DTIC FILE COPY

APRIL 1981

81 5 18 010


411059

OHIO RIVER BASIN
TRIBUTARY SOUTH BRANCH PIGEON CREEK, WASHINGTON COUNTY

PENNSYLVANIA
COKEBURG WATER SUPPLY DAM

NDI ID NO. PA-1094
DER ID NO. 63-30

BOROUGH OF COKEBURG
PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM



Prepared By
L. ROBERT KIMBALL & ASSOCIATES
CONSULTING ENGINEERS & ARCHITECTS
EBENSBURG, PENNSYLVANIA
15931

FOR
DEPARTMENT OF THE ARMY
BALTIMORE DISTRICT CORPS OF ENGINEERS
BALTIMORE, MARYLAND
21203

APRIL, 1981

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the spillway design flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The spillway design flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

Letter on file

A

PHASE I REPORT
NATIONAL DAM INSPECTION REPORT

NAME OF DAM	Cokeburg Water Supply Dam
STATE LOCATED	Pennsylvania
COUNTY LOCATED	Washington
STREAM	Tributary to the South Branch of Pigeon Creek
DATE OF INSPECTION	November 5, 1980
COORDINATES	Lat: 40° 5.9' Long: 80° 4.2'

ASSESSMENT

The assessment of Cokeburg Water Supply Dam is based upon visual observations made at the time of inspection, review of available data, hydraulic and hydrologic computations and past operational performance of the structure. The inspection and review of data of the Cokeburg Water Supply Dam revealed that further investigations of the magnitude of a Phase II are required. The inspection did not reveal any problems which require immediate emergency action. The dam appears to be in poor condition and poorly maintained. The structure is classified as unsafe, non-emergency.

The stability of the structure is questionable due to the existence of coke ovens in the downstream slope of the embankment and failure of the discharge culvert outlet. Considerable erosion and/or settlement has occurred near the outlet of the spillway discharge culvert. The interior walls of the culvert, at the outlet are caving in and debris partially blocks the outlet. Portions of the reservoir slopes may contain coal refuse, which could lead to potential landslides affecting the storage and volume of the reservoir. During periods of heavy precipitation a potential landslide could occur, increasing the possibility for overtopping of the structure.

The Cokeburg Water Supply Dam is a high hazard-small size dam. The Spillway Design Flood (SDF) for a dam of this size and classification is in the range of 1/2 PMF to the PMF. The PMF has been selected as the spillway design flood based on the downstream potential for loss of life and property damage. The spillway and reservoir are capable of controlling less than 30% of the PMF without overtopping the embankment low spot. Results of the dam breach analysis indicate that downstream damages would be significantly increased due to dam failure. The spillway is termed seriously inadequate. The dam is classified as an unsafe, non-emergency structure.

COKEBURG WATER SUPPLY DAM
PA 1094

The following recommendations and remedial measures should be instituted immediately.

1. A detailed stability and seepage analysis should be conducted by a registered professional engineer knowledgeable in dam design and construction and should be conducted in conjunction with a detailed hydraulic and hydrologic analysis of the structure to increase the spillway capacity and to document the stability of the structure.
2. The fence which surrounds the inlet for the spillway should be removed. The location and type of fence is such that it may reduce the spillway capacity by collecting debris. The fence apparently serves as a security measure against injury to unauthorized personnel who may frequent the site. Other security measures should be implemented, and a trash rack provided, which does not hamper the capability of the spillway to discharge excess inflow to the reservoir.
3. The discharge culvert outlet for the spillway is caving in and debris partially blocks the outlet. The debris should be removed from the outlet, and the area immediately beyond the outlet and the walls of the culvert should be repaired.
4. The owner should make an evaluation to determine the extent of subsurface mining beneath the dam and its possible effects relative to subsidence.
5. The vegetation on the slopes of the structure should be removed under the direction of a professional engineer knowledgeable in dam design and construction to insure that removal of the vegetation does not adversely affect the stability of the structure.
6. It should be ascertained whether the 6" diameter water line which serves as the feed line for the water supply system is capable of serving as a drainline for the reservoir. If it is determined that the line is capable of serving as a drainline, some means of positive upstream closure of the line should be provided. If the line is determined unsuitable as a drainline, an upstream closure should be provided, or the line should be abandoned, and plugged; and some alternate method devised to drain the reservoir.
7. An investigation should be conducted to determine the type of material which forms the slopes immediately adjacent to the reservoir. The investigation should include the potential for the material to slide into the reservoir, thus reducing the storage potential of the reservoir and the potential for overtopping.
8. A safety inspection program should be implemented with inspections at regular intervals by a qualified personnel.

COKEBURG WATER SUPPLY DAM
PA 1094

9. A warning system should be developed to warn downstream residents of large spillway discharges or imminent failure of the dam.

10. A regularly scheduled maintenance program should be prepared and implemented to insure the continued safe operation of the facility.

SUBMITTED BY:



L. ROBERT KIMBALL & ASSOCIATES
CONSULTING ENGINEERS AND ARCHITECTS

Date

R Jeffrey Kimball
R. Jeffrey Kimball, P.E.

APPROVED BY:

Date

21 APR 81

James W. Peck
JAMES W. PECK
Colonel, Corps of Engineers
District Engineer



Overview of rock face, 5000 ft. Supply Dam

TABLE OF CONTENTS

	PAGE
SECTION 1 - PROJECT INFORMATION	1
1.1 General	1
1.2 Description of Project	1
1.3 Pertinent Data	3
SECTION 2 - ENGINEERING DATA	5
2.1 Design	5
2.2 Construction	5
2.3 Operation	5
2.4 Evaluation	5
SECTION 3 - VISUAL INSPECTION	6
3.1 Findings	6
3.2 Evaluation	7
SECTION 4 - OPERATIONAL PROCEDURES	8
4.1 Procedures	8
4.2 Maintenance of Dam	8
4.3 Maintenance of Operating Facilities	8
4.4 Warning System in Effect	8
4.5 Evaluation	8
SECTION 5 - HYDRAULICS AND HYDROLOGY	9
5.1 Evaluation of Features	9
5.2 Evaluation Assumptions	9
5.3 Summary of Overtopping analysis	10
5.4 Summary of Dam Breach Analysis	10
SECTION 6 - STRUCTURAL STABILITY	11
6.1 Evaluation of Structural Stability	11
SECTION 7 - ASSESSMENT AND RECOMMENDATIONS/REMEDIAL MEASURES	12
7.1 Dam Assessment	12
7.2 Recommendations/Remedial Measures	12

APPENDICES

- APPENDIX A - CHECKLIST, VISUAL INSPECTION, PHASE I
- APPENDIX B - CHECKLIST, ENGINEERING DATA, DESIGN, CONSTRUCTION,
OPERATION, PHASE I
- APPENDIX C - PHOTOGRAPHS
- APPENDIX D - HYDROLOGY AND HYDRAULICS
- APPENDIX E - DRAWINGS
- APPENDIX F - GEOLOGY

PHASE I
NATIONAL DAM INSPECTION PROGRAM

COKEBURG WATER SUPPLY DAM
NDI. I.D. NO. PA 1094
DER I.D. NO. 63-30

SECTION 1
PROJECT INFORMATION

1.1 General.

a. Authority. The National Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of inspection of dams throughout the United States.

b. Purpose. The purpose of the inspection is to determine if the dam constitutes a hazard to human life or property.

1.2 Description of Project.

a. Dam and Appurtenances. The Cokeburg Water Supply Dam is an earthfill dam, 400 feet long and 27 feet high. The crest width is 20 feet. The upstream slope is 1/2H:1V to 1H:1V and grass covered. The downstream slope of the dam is 1H:1V and grass covered. Small trees and brush exist on the upstream and downstream slopes of the structure.

Several abandoned coke ovens are visible on the downstream slope of the structure adjacent to the left abutment contact and above the outlet conduit for the spillway.

The spillway for the Cokeburg Water Supply Dam is located at the left abutment of the structure. The spillway consists of a rectangular concrete drop intake structure. A chainlink fence exists around the inlet to the intake structure. Inflow to the structure is discharged through a rectangular masonry culvert. The outlet for the culvert is located at the downstream toe of the dam.

b. Location. The dam is located on a tributary of the South Branch of Pigeon Creek, within the Cokeburg Borough limits, Washington County, Pennsylvania. The Cokeburg Water Supply Dam can be located on the Ellsworth, U.S.G.S. 7.5 minute quadrangle.

c. Size Classification. The Cokeburg Water Supply Dam is a small size dam (27 feet high, 61 acre-feet).

d. Hazard Classification. The Cokeburg Water Supply Dam is a high hazard dam. Downstream conditions indicate that the loss of more than a few lives and property damage is probable should the structure fail. A small business establishment is located approximately 1,000 feet downstream of the dam.

e. Ownership. The dam is owned by the Borough of Cokeburg. Correspondence should be addressed to:

Mr. Lee Karpoff, Council President
Box 398
Cokeburg, Pennsylvania
412/945-6425

f. Purpose of Dam. The dam is used for water supply.

g. Design and Construction History. The original owner of the Cokeburg Water Supply Dam was the Bethlehem Mines Corporation. The impoundment was originally started about 1902 and was used in conjunction with the mining of the Pittsburgh coal seam. Sometime around 1953 the reservoir was purchased from Bethlehem Mines Corporation by the Cokeburg Borough for use as a water supply reservoir. The impoundment is currently used to supply water for Cokeburg, Pennsylvania.

The dam was constructed on top of a bank of abandoned coke ovens. Information in the DER files suggests that the coke ovens were abandoned prior to construction of the dam in 1902. Past inspection reports note seepage through the embankment.

A 1919 inspection report indicates that the dam was originally built with both the upstream and downstream slopes equal to 1.5H:1V. A sketch drawn on that inspection report indicates that coke ovens existed along the downstream toe of the dam and along either downstream abutment. A railroad siding existed along the crest of the dam. Apparently, the railroad siding was utilized for loading the coke ovens as part of the coking process. Other information in the inspection report indicates that two brick core walls, each 9 inches thick with a puddle core between the walls, existed at the time of inspection. It was also noted that a portion of the walls exposed on the crest had fallen down.

It was reported by members of the council, who accompanied the inspection team, that the spillway crest had been raised 10 or 12 years ago to increase the capacity of the reservoir. No information was available regarding who had completed the work or the design associated with the work.

h. Normal Operating Procedures. Normal inflow to the reservoir is discharged through the spillway at the left abutment. The reservoir pool is maintained at the spillway crest elevation, 1072.0. A 6 inch diameter waterline exists near the right abutment of the dam and supplies the normal flow of water to the Borough of Cokeburg. Two manholes exist at the downstream toe of the dam near the right abutment. One of the manholes provides access to the 6 inch waterline.

1.3 Pertinent Data.

- a. Drainage Area. 0.53 square mile
- b. Discharge at Dam Site (cfs).
- | | |
|-----------------------------------|---------|
| Maximum known flood at dam site | Unknown |
| Drainline capacity at normal pool | None |
| Spillway capacity at top of dam | 750 |
- c. Elevation (U.S.G.S. Datum) (feet). - Field survey based on spillway crest elevation, 1072.0, from U.S.G.S. 7.5 minute quadrangle.
- | | |
|--|---------|
| Top of dam - low point | 1075.0 |
| Top of dam - design height | Unknown |
| Maximum pool - design surcharge | Unknown |
| Normal pool | 1072.0 |
| Spillway crest | 1072.0 |
| Upstream invert - 6" waterline | Unknown |
| Downstream invert - 6" waterline (approximate) | 1045.0 |
| Maximum tailwater | None |
| Toe of dam | 1047.9 |
- d. Reservoir (feet).
- | | |
|------------------------------|------|
| Length of maximum pool (PMF) | 1500 |
| Length of normal pool | 1200 |
- e. Storage (acre-feet).
- | | |
|-------------|----|
| Normal pool | 37 |
| Top of dam | 61 |
- f. Reservoir Surface (acres).
- | | |
|----------------|---|
| Top of dam | 9 |
| Normal pool | 7 |
| Spillway crest | 7 |
- g. Dam.
- | | |
|------------------------|---|
| Type | Earthfill over abandoned coke oven bank |
| Length | 400 feet |
| Height | 27 feet |
| Top width | 20 feet |
| Side slopes - upstream | 0.5H:1V to 1H:1V |
| - downstream | 1H:1V |

Zoning	None
Impervious core	None
Cutoff	Brick (deteriorated)
Grout curtain	None

h. Reservoir Drain.

Type	6" diameter water supply line
Length	Unknown
Closure	Valve at toe
Access	Manhole at downstream toe
Regulating facilities	Valve in manhole

i. Spillway.

Type	Rectangular drop inlet
Length (total crest)	45 feet
Crest elevation	1072.0
Upstream channel	Lake
Downstream channel	Masonry culvert

SECTION 2
ENGINEERING DATA

2.1 Design. Limited information relative to the design of the Cokeburg Water Supply Dam was available in the DER files. Comments made as part of various inspection reports indicate that the dam was constructed by the Bethlehem Mines Corporation to be utilized in the mining of the Pittsburgh coal seam. The Commonwealth of Pennsylvania, Department of Environmental Resources, correspondence file was reviewed for the purposes of this report. Several members of the Cokeburg Borough Council accompanied the inspection team but did not provide any additional information relative to the design of the structure.

2.2 Construction. No information exists relative to the construction of the dam. Remarks contained in various inspection reports indicate that the dam was constructed on top of an abandoned bank of coke ovens.

2.3 Operation. No operating records are maintained.

2.4 Evaluation.

a. Availability. Limited available data was provided by the PennDER, Bureau of Dams and Waterway Management, and through interviews with the owner. Several members of the Cokeburg Borough Council were interviewed to obtain data on the operation and maintenance of the dam.

b. Adequacy. Detailed analysis cannot be made because of the lack of detailed design information. This Phase I Report is based on available data, visual inspection and hydrologic and hydraulic analysis. Sufficient information exists to complete a Phase I Report.

SECTION 3
VISUAL INSPECTION

3.1 Findings.

a. General. The onsite inspection of the Cokeburg Water Supply Dam was conducted by personnel of L. Robert Kimball and Associates on November 5, 1980. The inspection consisted of:

1. Visual inspection of the retaining structure, abutments and toe.
2. Examination of the spillway facilities, exposed portion of any outlet works and other appurtenant works.
3. Observations affecting the runoff potential of the drainage basin.
4. Evaluation of the downstream area hazard potential.

b. Dam. The dam appeared to be in poor condition and poorly maintained. From a brief survey conducted during the inspection, it was noted that a low area exists on the embankment crest near the left abutment. The crest width of the dam was measured to be 20 feet. The upstream slope above the water level was measured to be 0.5H:1V to 1H:1V and grass covered. It was also observed that small trees and brush exist on the upstream slope of the dam. The downstream slope of the dam was measured to be 1H:1V and covered with grasses and brush. Large trees were also observed on the downstream slope of the structure. Access to the dam is along an earthen road downstream of the left abutment. The access road continues along the crest of the structure. No major erosion was observed on the crest of the dam. Several coke ovens were observed on the downstream slope near the left abutment and above the outlet culvert for the spillway. It was reported by the owners that coke ovens are present under the entire embankment length. The brick wall, assumed to be used as a cutoff, was partially exposed on the upstream slope. A large part of this wall has failed and fallen into the reservoir. No seepage was observed on the downstream slope or along the toe during the inspection.

c. Appurtenant Structures. The spillway for the reservoir is located near the left abutment through the embankment section. The spillway is a concrete rectangular drop inlet structure, and flows are carried by a masonry culvert through the embankment. The outlet for the culvert is at the downstream toe near the left abutment. A chain link fence exists at the inlet for safety reasons. The inspection team entered the inlet and culvert to inspect the condition of the structure. Seepage was observed exiting from the left interior wall of the culvert. Several concentrated seepage points were observed, and the seepage was estimated at 2 to 3 gallons per minute. The floor of the culvert consists of concrete. The culvert is constructed of rubble masonry with mortar. It was observed that the culvert is in a

deteriorating condition, and the sidewalls at the outlet are caving in. The outlet is partially blocked due to the caving sidewalls. Considerable erosion was observed along the downstream slope of the dam in the area of the culvert outlet. Past erosion has exposed a considerable portion of the outlet culvert.

Two rectangular concrete block structures (manholes) were observed at the toe of the dam near the right abutment contact. It was reported by members of the Council who accompanied the inspection team that one structure supplied access to a gate valve for the water supply line. The second structure was utilized to supply reservoir water to a mine shaft during past mining of the coal seam below the dam. The water was reportedly supplied to the mine through a borehole.

d. Reservoir Area. The watershed is covered mostly with moderate to steep woodlands. The reservoir slopes to the south of the reservoir consist of an old refuse bank. It was reported by members of the Borough Council who accompanied the inspection team that a portion of the slope had slid into the reservoir several years ago. The reservoir surface area is relatively small, and the steep slopes to the south of the reservoir reportedly contain significant amounts of coal refuse. The area may be susceptible to landslides which could potentially affect the storage volume of the reservoir and overtopping of the dam by displacing water if the slopes should slide into the reservoir.

e. Downstream Channel. The downstream channel for the Cokeburg Water Supply Dam consists of a tributary to the South Branch of Pigeon Creek. A small business establishment is located approximately 1,000 feet downstream of the dam.

3.2 Evaluation. In general, the Cokeburg Water Supply Dam and appurtenant structures are in a seriously deteriorated condition. Maintenance of the dam and operating facilities is considered very poor. Major erosion was observed in the area of the outlet culvert for the spillway. The outlet culvert is in a seriously deteriorated condition. Caving in at the outlet of the culvert partially blocks the outlet. Brush and debris exist in the area of the outlet. No seepage was observed on the downstream slope or along the toe of the dam, although the structure has a history of seepage and settlement. No settlement areas were observed during the inspection.

SECTION 4
OPERATIONAL PROCEDURES

4.1 Procedures. The water level is maintained at the spillway crest elevation, 1072. Water is drawn from the reservoir to supply water requirements for the Borough of Cokeburg.

4.2 Maintenance of the Dam. No planned maintenance schedule exists for the dam. The embankment slopes are covered with brush and small trees which hampered the visual inspection.

4.3 Maintenance of Operating Facilities. No planned maintenance program exists for the operating facilities.

4.4 Warning System in Effect. There is no warning system in effect to warn downstream residents of large spillway discharges or imminent failure of the dam.

4.5 Evaluation. The maintenance of the dam and operating facilities is considered poor. The structure is in a seriously deteriorated condition. Trees and brush exist on the embankment slopes, and debris partially blocks the spillway outlet channel. The outlet culvert is caving in and erosion at the outlet is evident.

There is no warning system in effect at the dam. An emergency action plan should be available for every dam in the high and significant hazard category. Such plans should outline actions to be taken by the operator to minimize downstream effects of an emergency and should include an effective warning system.

SECTION 5
HYDRAULICS AND HYDROLOGY

5.1 Evaluation of Features.

a. Design Data. No calculations or design data pertaining to the hydrology or hydraulics associated with the dam were available.

b. Experience Data. No rainfall, runoff or reservoir level data were available. The spillway reportedly has functioned adequately in the past.

c. Visual Observations. The spillway appeared to be in poor condition. A chain link fence surrounds the crest of the drop inlet structure. The fence has the potential to block inflow to the drop inlet, since debris could collect on the fence. The spillway discharge culvert is caving in at the outlet and the outlet is partially blocked.

The low spot on the top of dam (1075.0) was noted as existing near the left abutment of the structure.

d. Overtopping Potential. Overtopping potential was investigated through the development of the probable maximum flood (PMF) for the watershed and the subsequent routing of the PMF and fractions of the PMF through the reservoir and spillway.

The Corps of Engineers, Baltimore District, has directed that the HEC-1 Dam Safety Version systemized computer program be utilized. The program was prepared by the Hydrologic Engineering Center (HEC), U.S. Army Corps of Engineers, Davis, California, July, 1978. The major methodologies or key input data for this program are discussed briefly in Appendix D.

5.2 Evaluation Assumptions. To enable completion of the hydraulic and hydrologic analysis for this structure, it was necessary to make the following assumptions.

1. The pool level in the reservoir prior to the storm was assumed to be at the spillway crest elevation, 1072.0.

2. The top of dam was considered the low spot at elevation 1075.0.

3. The chain link fence which surrounds the intake to the drop inlet was ignored during the analysis. Debris could collect on the fence and block inflow to the drop inlet.

4. The embankment soils appeared to be highly susceptible to erosion; and based on the evaluating engineers judgement, a pool elevation of 1076.0 was sufficient to cause failure by overtopping.

5.3 Summary of Overtopping Analysis. Complete summary sheets for the computer output are presented in Appendix D.

Peak inflow (PMF)	2620 cfs
Spillway capacity	750 cfs

a. Spillway Adequacy Rating. The Spillway Design Flood is based on the hazard and size classification of the dam. The recommended Spillway Design Flood (SDF) for a small size dam is in the range of 1/2 PMF to PMF. The Spillway Design Flood for this dam was selected to be the PMF based on the downstream potential for loss of life. Based on the following definition provided by the Corps of Engineers, the spillway is rated as seriously inadequate as a result of our hydrologic analysis. The spillway and reservoir are capable of controlling less than 30% of the PMF without overtopping the embankment.

Seriously inadequate - All high hazard dams not capable of passing 50% of the Spillway Design Flood (PMF) and where there is a significant increase in the downstream hazard potential due to dam failure from that which exists prior to the failure.

5.4 Summary of Dam Breach Analysis. As the subject dam cannot satisfactorily pass 50% of the PMF, it was necessary to perform a dam breach analysis and downstream routing of the flood wave. This analysis determines the degree of increased flooding due to dam failure. The results of the dam breach analysis indicate that downstream flooding is significantly increased. Since flooding downstream is significantly increased due to dam failure, the spillway is considered seriously inadequate. The Cokeburg Water Supply Dam is classified as an unsafe, non-emergency structure. Input data for the HEC-1 dam breach program appear in Appendix D.

SECTION 6 STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability.

a. Visual Observations. The inspection of the Cokeburg Water Supply Dam revealed several deficiencies which were considered as having a significant affect on the stability of the structure. Coke ovens were observed on the downstream slope near the left abutment of the structure. The coke ovens were open. The openings to the coke ovens were not sealed, and the potential exists for the fill material within the ovens to erode out of the openings. The existence of the coke ovens is verified by a 1919 Water Supply Commission inspection report. The potential exists for settlement of the material in the ovens, and the structures could collapse and cause settlement of the embankment. Information in the DER files suggest that some settlement has occurred near the right abutment of the structure. It is unclear as to the date associated with the settlement.

The outlet for the spillway discharge culvert is collapsing and debris partially blocks the outlet. The condition of the culvert outlet appears to be due to erosion and settlement in the area of the outlet.

No major erosion or settlement was observed on the embankment crest during the inspection. No seepage was observed on the downstream slope or along the toe of the embankment. Seepage estimated at 2 to 3 GPM was observed on the left interior wall of the culvert near the inlet. The upstream and downstream slopes contain considerable brush and trees. The existence of the trees on the embankment slopes increases the potential for the development of erosion cavities and slides.

b. Design and Construction Data. No design or construction data are available. Limited information is available in the DER files relative to the general characteristics of the site during various periods leading up to the present day facility. No known stability analysis exists for this dam.

c. Operating Records. No operating records are maintained.

d. Post Construction Changes. No post construction changes are known to have occurred at the dam in the recent past.

e. Seismic Stability. The dam is located in seismic zone 1. No seismic stability analyses are known to have been performed. Normally, it can be considered that if a dam in this zone is stable under static loading conditions, it can be assumed safe for any expected earthquake loading. The conditions as previously discussed in Section 6.1a indicate that the static stability of the structure is questionable with regards to minimum factors of safety associated with current criteria.

SECTION 7
ASSESSMENT AND RECOMMENDATIONS/REMEDIAL MEASURES

7.1 Dam Assessment.

a. Safety. The dam appears to be in poor condition and poorly maintained. The stability of the structure is questionable due to the existence of coke ovens in the downstream slope of the embankment and failure of the brick wall. The possibility also exists that erosion cavities exist within the embankment and could lead to potential piping of the structure or settlement of the embankment which would increase the potential for overtopping failure. Considerable erosion and/or settlement has occurred near the outlet of the spillway discharge culvert. The interior walls of the culvert at the outlet are caving in and debris partially blocks the outlet. Portions of the reservoir slopes may contain coal refuse which could lead to potential landslides affecting the storage and volume of the reservoir. During periods of heavy precipitation, a potential landslide could occur increasing the possibility for overtopping of the structure.

The structure has a past history of seepage, although no seepage was observed on the downstream slope or along the toe area of the structure during the inspection. Seepage estimated at 2 to 3 GPM was observed on the left interior wall of the culvert, at the inlet.

The visual observations, review of available data, hydraulic and hydrologic calculations and the past operational performance of the structure indicate that the Cokeburg Water Supply Dam's spillway is seriously inadequate. The spillway is capable of controlling 30% of the PMF without overtopping the embankment. No known stability analysis have been performed for this structure. The dam is an unsafe, non-emergency structure.

b. Adequacy of Information. Sufficient information is available to complete a Phase I report.

c. Urgency. The recommendations suggested below should be implemented immediately.

d. Necessity for Further Investigation. In order to accomplish some of the recommendations/remedial measures outlined below, further investigations will be required.

7.2 Recommendations/Remedial Measures.

1. A detailed stability and seepage analysis should be conducted by a registered professional engineer knowledgeable in dam design and construction and should be conducted in conjunction with a detailed hydraulic and hydrologic analysis of the structure to increase the spillway capacity and to document the stability of the structure.

2. The fence which surrounds the inlet for the spillway should be removed. The location and type of fence is such that it may reduce the spillway capacity by collecting debris. The fence apparently serves as a security measure against injury to unauthorized personnel who may frequent the site. Other security measures should be implemented, and a trash rack provided, which does not hamper the capability of the spillway to discharge excess inflow to the reservoir.

3. The discharge culvert outlet for the spillway is caving in and debris partially blocks the outlet. The debris should be removed from the outlet, and the area immediately beyond the outlet and the walls of the culvert should be repaired.

4. The owner should make an evaluation to determine the extent of subsurface mining beneath the dam and its possible effects relative to subsidence.

5. The vegetation on the slopes of the structure should be removed under the direction of a professional engineer knowledgeable in dam design and construction to insure that removal of the vegetation does not adversely affect the stability of the structure.

6. It should be ascertained whether the 6" diameter water line which serves as the feed line for the water supply system is capable of serving as a drainline for the reservoir. If it is determined that the line is capable of serving as a drainline, some means of positive upstream closure of the line should be provided. If the line is determined unsuitable as a drainline, an upstream closure should be provided, or the line should be abandoned, and plugged; and some alternate method devised to drain the reservoir.

7. An investigation should be conducted to determine the type of material which forms the slopes immediately adjacent to the reservoir. The investigation should include the potential for the material to slide into the reservoir, thus reducing the storage potential of the reservoir and the potential for overtopping.

8. A safety inspection program should be implemented with inspections at regular intervals by a qualified personnel.

9. A warning system should be developed to warn downstream residents of large spillway discharges or imminent failure of the dam.

10. A regularly scheduled maintenance program should be prepared and implemented to insure the continued safe operation of the facility.

APPENDIX A
CHECKLIST, VISUAL INSPECTION, PHASE I

CHECK LIST
VISUAL INSPECTION
PHASE I

NAME OF DAM Cokeburg Water Supply Dam COUNTY Washington STATE Pennsylvania ID# 1094

TYPE OF DAM Earthfill HAZARD CATEGORY High

DATE(s) INSPECTION November 5, 1980 WEATHER Clear and cool TEMPERATURE 35°

POOL ELEVATION AT TIME OF INSPECTION 1071.2 M.S.L. TAILWATER AT TIME OF INSPECTION None M.S.L.

INSPECTION PERSONNEL:

R. Jeffrey Kimball, P.E. - L. Robert Kimball and Associates

James T. Hockensmith - L. Robert Kimball and Associates

O.T. McConnell - L. Robert Kimball and Associates

Lee Karpoff, Council President - Cokeburg Borough Council

Mr. Michael Megles - Cokeburg Borough Councilman

Mr. Charles Pscolka - Cokeburg Borough Councilman

O.T. McConnell

RECORDER

EMBANKMENT

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS	None noted.	
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	Considerable erosion and/or settlement at outlet for spillway culvert.	The outlet is caving in and should be repaired.
SLOUGHING OR EROSION OF EMBANKMENT AND ABUTMENT SLOPES	Considerable erosion at the toe of the downstream slope adjacent to the left abutment in the area of the spillway outlet culvert.	
VERTICAL AND HORIZONTAL ALIGNMENT OF THE CREST	No signs suggesting settlement or movement of the embankment noted during the inspection.	
RIPRAP FAILURES	No riprap on the upstream slope. Minor erosion observed.	

EMBANKMENT

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
VEGETATION	Considerable vegetation on the upstream and downstream slopes.	Vegetation should be removed.
JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM	No deficiencies observed.	
ANY NOTICEABLE SEEPAGE	Minor seepage observed on the left interior wall of the spillway discharge culvert at the inlet. Seepage flow estimated at 2 to 3 gallons per minute.	
STAFF GAUGE AND RECORDER	None.	
DRAINS	None.	

CONCRETE/MASONRY DAMS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
ANY NOTICEABLE SEEPAGE	Not applicable.	
STRUCTURE TO ABUTMENT/EMBANKMENT JUNCTIONS	Not applicable.	
DRAINS	Not applicable.	
WATER PASSAGES	Not applicable.	
FOUNDATION	Not applicable.	

CONCRETE/MASONRY DAMS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS CONCRETE SURFACES	Not applicable.	
STRUCTURAL CRACKING	Not applicable.	
VERTICAL AND HORIZONTAL ALIGNMENT	Not applicable.	
MONOLITH JOINTS	Not applicable.	
CONSTRUCTION JOINTS	Not applicable.	
STAFF GAUGE OR RECORDER	Not applicable.	

OUTLET WORKS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	The outlet conduit is in a deteriorating condition and the outlet is caving in. Debris partially blocks the outlet.	The outlet culvert should be repaired and debris removed at the outlet.
INTAKE STRUCTURE	Appeared to be in good condition except for a fence which surrounds the crest.	The fence should be removed since it hampers the capability of the spillway to discharge excess inflow to the reservoir.
OUTLET STRUCTURE	Outlet structure constructed of masonry rubble with mortar. Outlet for the culvert is caving in.	
OUTLET CHANNEL	Natural stream at outlet, debris exists in the channel.	The debris should be removed from the outlet channel.
EMERGENCY GATE	Gate valve on 6" water supply feed line. The control valve is located in a manhole at the downstream toe of the dam.	The valve was not operated during the inspection.

UNGATED SPILLWAY

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE WEIR	Semi-broad crest. Concrete appeared to be in good condition. A chain link fence surrounds the intake inlet.	The fence should be removed.
APPROACH CHANNEL	Lake, restricted by chain link fence.	
DISCHARGE CHANNEL	Masonry rubble culvert with concrete channel bottom to natural stream.	
BRIDGE AND PIERS	None.	

GATED SPILLWAY

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE SILL	Not applicable.	
APPROACH CHANNEL	Not applicable.	
DISCHARGE CHANNEL	Not applicable.	
BRIDGE AND PIERS	Not applicable.	
GATES AND OPERATION EQUIPMENT	Not applicable.	

DOWNSTREAM CHANNEL


VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONDITION (OBSTRUCTIONS, DEBRIS, ETC.)	The downstream channel for the Cokeburg Water Supply Dam consists of a natural stream to a tributary of the South Branch of Pigeon Creek. The channel below the spillway outlet culvert is partially blocked.	The debris blocking the channel should be removed.
SLOPES	Channel slopes appear to be stable.	
APPROXIMATE NO. OF HOMES AND POPULATION	One small business is located approximately 1,000 feet downstream of the dam. The population would consist of employees at the business. Population estimated at 6 to 8 people.	

RESERVOIR


VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SLOPES	Moderate to steep. Slopes may be formed by mine refuse. Stability of the slopes is questionable.	Slopes should be investigated and stability analyzed if necessary.
SEDIMENTATION	Unknown.	

INSTRUMENTATION


VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
MONUMENTATION/SURVEYS	None.	
OBSERVATION WELLS	None.	
WEIRS	None.	
PIEZOMETERS	None.	
OTHER	None.	



COKEBURG WATER SUPPLY DAM
SCALE: 1"=50'



SPILLWAY INTAKE AND CULVERT ENTRANCE
LOOKING UPSTREAM
SCALE AS SHOWN



PROFILE
LOOKING UPSTREAM
SCALE: 1"=50'

COKEBURG WATER SUPPLY DAM



APPENDIX B
CHECKLIST, ENGINEERING DATA, DESIGN, CONSTRUCTION, OPERATION, PHASE I

CHECK LIST
ENGINEERING DATA
DESIGN, CONSTRUCTION, OPERATION
PHASE I

Cokeburg Water
Supply Dam

NAME OF DAM
ID# PA 1094


ITEM	REMARKS
AS-BUILT DRAWINGS	None available.
REGIONAL VICINITY MAP	U.S.G.S. 7.5 minute Ellsworth quadrangle.
CONSTRUCTION HISTORY	Limited information available in DER files.
TYPICAL SECTIONS OF DAM	Approximate sketch in DER files. See Appendix D.
OUTLETS - PLAN - DETAILS - CONSTRAINTS - DISCHARGE RATINGS RAINFALL/RESERVOIR RECORDS	None. None. None. None. None.

ITEM	REMARKS
DESIGN REPORTS	None.
GEOLOGY REPORTS	None.
DESIGN COMPUTATIONS HYDROLOGY & HYDRAULICS DAM STABILITY SEEPAGE STUDIES	None known to exist.
MATERIALS INVESTIGATIONS BORING RECORDS LABORATORY FIELD	Unknown.
POST-CONSTRUCTION SURVEYS OF DAM	None known to have occurred.
BORROW SOURCES	Unknown.

ITEM	REMARKS
MONITORING SYSTEMS	None.
MODIFICATIONS	None known to have occurred in the recent past.
HIGH POOL RECORDS	None.
POST CONSTRUCTION ENGINEERING STUDIES AND REPORTS	None known to have existed.
PRIOR ACCIDENTS OR FAILURE OF DAM DESCRIPTION REPORTS	Information in the DER files suggest that past settlement has occurred at the structure. No major failure to the structure reported due to the settlement.
MAINTENANCE OPERATION RECORDS	None.

ITEM	REMARKS
SPILLWAY PLAN SECTIONS DETAILS	See Appendix D.
OPERATING EQUIPMENT PLANS & DETAILS	None.

APPENDIX C
PHOTOGRAPHS



C-1



COKEBURG WATER SUPPLY DAM
PHOTO INDEX

P - INDICATES PHOTO LOCATION

COKEBURG WATER SUPPLY DAM
PA 1094

Sheet 1

Front

- (1) Upper left - View of unstream slope and left abutment.
- (2) Upper right - View of upstream slope, embankment crest and right abutment.
- (3) Lower left - View of the spillway intake structure.
- (4) Lower right - View of seepage along the culvert wall directly inside the entrance to the culvert.

Back

- (5) Upper left - View of the approach to the spillway culvert.
- (6) Upper right - View of drop inlet section of spillway.
- (7) Lower left - View of the outlet for the discharge culvert. Note the deterioration and collapse of the walls near the outlet.
- (8) Lower right - Partial view of the downstream slope directly above the spillway discharge culvert. Note the deterioration of the coke oven structure and the obvious void directly inside the oven entrance.



Sheet 2

Front




- (9) Upper left - View along the top of the outlet culvert. View from the crest looking down onto the top of the culvert. Note the erosion along the edges of the culvert.
- (10) Upper right - Downstream slope. View towards the left abutment.
- (11) Lower left - View of control valve which regulates flow to a borehole to a mine shaft located some distance below the embankment.
- (12) Lower right - Downstream exposure.

TOP OF PAGE

1,5,9	2,6,10
3,7,11	4,8,12







APPENDIX D
HYDROLOGY AND HYDRAULICS

APPENDIX D
HYDROLOGY AND HYDRAULICS

Methodology. The dam overtopping and breach analyses were accomplished using the systemized computer program HEC-1 (Dam Safety Investigation), September, 1978, prepared by the Hydrologic Engineering Center, U.S. Army Corps of Engineers, Davis, California. A brief description of the methodology used in the analysis is presented below.

1. Precipitation. The Probable Maximum Precipitation (PMP) is derived and determined from regional charts prepared from past rainfall records including "Hydrometeorological Report No. 33" prepared by the U.S. Weather Bureau.

The index rainfall may be reduced from 10% to 20% depending on watershed size by utilization of what is termed the HOP Brook adjustment factor. Distribution of the total rainfall is made by the computer program using distribution methods developed by the Corps.

2. Inflow Hydrograph. The hydrologic analysis used in development of the overtopping potential is based on applying a hypothetical storm to a unit hydrograph to obtain the inflow hydrograph for reservoir routing.

The unit hydrograph is developed using the Snyder method. This method requires calculation of several key parameters. The following list gives these parameters their definition and how they were obtained for these analysis.

Parameter	Definition	Where Obtained
Ct	Coefficient representing variations of watershed	From Corps of Engineers*
L	Length of main stream channel miles	From U.S.G.S. 7.5 minute topographic
Lca	Length on main stream to centroid of watershed	From U.S.G.S. 7.5 minute topographic
Cp	Peaking coefficient	From Corps of Engineers*
A	Watershed size	From U.S.G.S. 7.5 minute topographic

*Developed by the Corps of Engineers on a regional basis for Pennsylvania.

3. Routing. Reservoir routing is accomplished by using Modified Puls routing techniques where the flood hydrograph is routed through reservoir storage. Hydraulic capacities of the outlet works, spillways and the crest of the dam are used as outlet controls in the routing.

The hydraulic capacity of the outlet works can either be calculated and input, or sufficient dimensions input, and the program will calculate an elevation discharge relationship.

Storage in the pool area is defined by an area - elevation relationship from which the computer calculates storage. Surface areas are either planimeted from available mapping or U.S.G.S. 7.5 minute series topographic maps or taken from reasonably accurate design data.

4. Dam Overtopping. Using given percentages of the PMF, the computer program will calculate the percentage of the PMF, which can be controlled by the reservoir and spillway without the dam overtopping.

5. Dam Breach and Downstream Routing. The computer program is equipped to determine the increase in downstream flooding due to failure of the dam caused by overtopping. This is accomplished by routing both the pre-failure peak flow and the peak flow through the breach (calculated by the computer with given input assumptions) at a given point in time and determining the water depth in the downstream channel. Channel cross-sections taken from U.S.G.S. 7.5 minute topographic maps were used in the downstream flood wave routing. Pre and post failure water depths are calculated at locations where cross-sections are input.

HYDROLOGICAL AND HYDRAULIC DATA FOR THE

NAME OF DAM: Cokesburg water supply dam

PROBABLE MAXIMUM PRECIPITATION (PMP) = 1.00 in.

STATION 100+00

Station Description: concrete dam

Drainage Area
 Square miles 1.00

Contributing Drainage Area
 Square miles 1.00

Adjustment of PMP for
 Drainage Area (1.00)² 1.00
 6 hours 1.00
 12 hours 1.00
 24 hours 1.00
 48 hours 1.00
 72 hours N/A

Snyder Hydrograph

Parameters
 C₁ (2) 1.00
 C₂ (3) 1.00
 C₃ (3) 1.00
 L (miles) (4) 1.00
 L_{ca} (miles) (4) 1.00
 tp = C₁(LxL_{ca})^{0.3 hrs.} 1.00

Spillway Data

Crest Length (ft) 40
 Freeboard (ft) 3.
 Discharge Coefficient N/A
 Exponent N/A

(1) Hydrometeorological Report 33 (Figure 10, U.S. Weather Bureau
 and U.S. Army Corp of Engineers, 1956).

(2) Hydrological zone defined by Corps of Engineers, Baltimore
 District, for determining Snyder's coefficients (1) and (2).

(3) Snyder's Coefficients.

(4) L=Length of longest water course from outlet to drainage area.
 L_{ca}=Length of water course from outlet to point opposite the
 centroid of drainage area.

CHECK LIST
HYDROLOGIC AND HYDRAULIC
ENGINEERING DATA

DRAINAGE AREA CHARACTERISTICS: 1.51 sq. mi.

ELEVATION TOP NORMAL POOL (STORAGE CAPACITY): 1072.0 [37 ac-ft]

ELEVATION TOP FLOOD CONTROL POOL (STORAGE CAPACITY): 1075.0 [61 ac-ft]

ELEVATION MAXIMUM DESIGN POOL: Unknown

ELEVATION TOP DAM: 1072.0 [low spot]

STILLWAY CREST:

1. Elevation 1072.0
 2. Type Grass inlet
 3. Width 4.0 feet
 4. Length 45 feet (total)
 5. Location Spillway Left abutment
 6. Number and Type of Gates None

INTAKE & RACE:

1. Type 12" diameter water supply feed line
 2. Location Through embankment near right abutment
 3. Entrance in earth None
 4. Exit inverts None
 5. Surfaces 12" diameter water supply feed line

PIPE MAINS & LATERALS:

1. Type None
 2. Location None
 3. Inverts None

MAXIMUM NON-DAMAGING DISCHARGE average

L. ROBERT KIMBALL & ASSOCIATES
CONSULTING ENGINEERS & ARCHITECTS
EBENSBURG PENNSYLVANIA

SHEET NO. _____ OF _____
BY _____ DATE _____ 3 3

$$\begin{aligned} S + R + L &= 1.24 \\ C + S + L &= 0.05 \text{ in } -2 \\ S + T + Q &= 1.5 \text{ cfs } 112 \\ Q_P - S + Z &= 0.05 \text{ (5000 = } \pi \times 40^2 \times 10^4) \\ R + Q + Z &= 3.0 \end{aligned}$$

MEMO - 01-423A-64042 - 01-423A-63

SPELLMAN CREST ELEVATION (U.S.G.S.) = 1072.0
REFERENCE AREA AT NO. 3 AND 4 = 7.4 ACRES
IN-THE-FORECAST DEC FILE (APPROX) = 36.9 ACRES - SEE ATT.


$$\begin{aligned} H &= 3 \text{ V/A} \\ &= 3(37) / 7.4 \\ &= 15.0 \end{aligned}$$
$$1072.0 - 15.0 = 1057.0$$

AT ELE/ 090, ACEA = 10 ACCEC
AT ELE/ 1100, ACEA = 23 ACCEC

TOP OF DAM ON SPOT ELEVATION = 1075.0

ROBERT KIMBALL & ASSOCIATES
CONSULTING ENGINEERS & ARCHITECTS
EBensburg PENNSYLVANIA

NAME _____
NUMBER PA-1034
SHEET NO. 2 OF 4
BY DTM DATE 3-91



AREA (AC)	0	7.4	9.5	15	20	23
ELEV (FT)	100	107.2	107.5	109.0	109.7	110

DISCHARGE ESTING

WEIR FLOW:

$$Q = CLH^{3/2} \quad \text{USE } C = 3.2 \quad (\text{ELEV NOT CONSIDERED})$$

$L = 45'$

CULVERT FULL FLOW, ENTRANCE CONTROLS,
CONSIDERED AS CONDUIT WITH DROP INLET.

$$Q = A \sqrt{\frac{2.3L}{1 + \sum \text{LOSSES}}} \quad \text{LET } C = \frac{1}{\sqrt{1 + \sum \text{LOSSES}}} = 0.6$$

$$\therefore Q = CA \sqrt{2.3L} \quad \text{WHERE } L = \text{GUL ELEV} - \text{CULVERT ENT INVERT}$$

OVERTOPPING:

$$Q = CLH^{3/2} \quad \text{USE } C = 3.0 \quad (\text{BROAD CREST})$$



$L \text{ VARIES WITH } H$

SE
10
10
10

L. ROBERT KIMBALL & ASSOCIATES
CONSULTING ENGINEERS & ARCHITECTS
EBENSBURG PENNSYLVANIA

NAME _____
NUMBER PA-1094

SHEET NO. 3 OF 4
BY OTM DATE 3-31



NOTE: OVERTOPPING WILL FIRST OCCUR AT THE
LEFT ABUTMENT. THE AREA OF THE
SPILLWAY.

SHEET NO. 4 OF 4
BY cm DATE 3/31

EACH CROSS-SECTIONS FROM U.S.G.S. 7.5 MIN. QUAD. SEE
PAGE E-1. OVBANK MANNINGS' $n = 0.06$ (ASSUMED),
CHANNEL MANNINGS' $n = 0.05$ (ASSUMED).

	A1	ANALYSIS OF DAN OVERLAP PRO USING RATIOS OF THE PTH HYDROLOGIC-HYDRAULIC ANALYSIS OF SAFETY OF CORNBORG RESERVOIR AND DAM							
	A2	RATIOS OF THE FTH ROUTE THROUGH THE RESERVOIR (0.6-1094)							
	A3	B	C	D	E	F	G	H	
1	288	0	10	0	0	0	0	0	
2	5	5							
3	1	1	4	1					
4	J1	.05	.1	.5	1				
5	K	0	1						
6	K1	INFLOW							
7	M	1	0.53						
8	P	24.25	102	120	130	140		1	
9	T	0.64	0.50				1.0	0.05	
10	X	-1.5	-0.5	2.0					
11	K	1	2				1		
12	K1	ROUTE THROUGH CORNBORG							
13	V			1					
14	V1	1					-1072	-1	
15	V4	1072	1073	1074	1075	1076	1076.5	1077	
16	V5	0	145	405	150	1135	2470	5785	
17	S4	0	7.4	8.5	15	20	23		
18	S1	1051	1072	1075	1090	1091	1100		
19	S3	1072							
20	S0	1075							
21	K	99							
22									
23									
24									
25									

 FLOW HYDROGRAPH PACKAGE (DEC-1)
 DAM SAFETY VERSION JULY 1978
 LAST MODIFICATION 01 APR 80

RUN DATE# 81/03/16.
 TIME# 05.33.20.

ANALYSIS OF DAM OVERTOPPING USING RATIOS OF THE PM
 HYDROLOGIC-HYDRAULIC ANALYSIS OF SAFETY OF CONCRETE RESERVOIR AND DAM
 RATIOS OF THE PM RUNOFF THROUGH THE RESERVOIR (PA-1094)

JOH SPECIFICATION
 INR AMIN IDAY IHR IMIN MTRC IPLT IPRT NSTAN
 200 0 10 0 0 0 0 0 0
 JOPER NWL LROPT TRACT
 5 0 0 0

MULTI-PLAN ANALYSIS TO BE PERFORMED
 NPLAN= 1 NRATIO= 4 RATIO= 1
 RTIOS= .05 .10 .50 1.00

SUB-AREA RUNOFF COMPUTATION

INFLOW

ISTAG	ICOMP	ILCON	ITAPE	JPLT	JPRE	INAME	ISTAGE	TAUTO
1	0	0	0	0	0	1	0	0

HYDROGRAPH DATA

DAYING	INRG	TAREA	SHAP	TRSDA	TRSPC	RATIO	ISNOW	ISABT	LOCAL
1	1	.53	0.00	.53	1.00	0.000	0	1	0

PRECIP DATA

SPFL	PMS	R6	R12	R24	R48	R72	R96
0.00	24.25	102.00	120.00	130.00	140.00	0.00	0.00

LOSS DATA

URAPT	STPR	DETR	RTD	RTD	STPR	RTD	STPR	RTD	STPR	RTD	STPR	RTD
0	0.00	0.00	1.00	1.00	0.00	1.00	1.00	0.05	0.05	0.00	0.00	0.00

OUT USED CAPACITY DATA

10 20 30 40 50 60 70 80 90 100

UNIT HYDROGRAPH DATA

APPROXIMATE CLARK COEFFICIENTS FROM GIVEN CATCHES OF WIND TO AMOUNT OF 0.21 AT 10 5.10 INTERVALS

30.	102.	203.	304.	405.	506.	607.	708.	809.	910.	1011.	1112.	1213.	1314.	1415.	1516.	1617.	1718.	1819.	1920.	2021.	2122.	2223.	2324.	2425.	2526.	2627.	2728.	2829.	2930.	3031.	3132.	3233.	3334.	3435.	3536.	3637.	3738.	3839.	3940.	4041.	4142.	4243.	4344.	4445.	4546.	4647.	4748.	4849.	4950.	5051.	5152.	5253.	5354.	5455.	5556.	5657.	5758.	5859.	5960.	6061.	6162.	6263.	6364.	6465.	6566.	6667.	6768.	6869.	6970.	7071.	7172.	7273.	7374.	7475.	7576.	7677.	7778.	7879.	7980.	8081.	8182.	8283.	8384.	8485.	8586.	8687.	8788.	8889.	8990.	9091.	9192.	9293.	9394.	9495.	9596.	9697.	9798.	9899.	9900.
30.	102.	203.	304.	405.	506.	607.	708.	809.	910.	1011.	1112.	1213.	1314.	1415.	1516.	1617.	1718.	1819.	1920.	2021.	2122.	2223.	2324.	2425.	2526.	2627.	2728.	2829.	2930.	3031.	3132.	3233.	3334.	3435.	3536.	3637.	3738.	3839.	3940.	4041.	4142.	4243.	4344.	4445.	4546.	4647.	4748.	4849.	4950.	5051.	5152.	5253.	5354.	5455.	5556.	5657.	5758.	5859.	5960.	6061.	6162.	6263.	6364.	6465.	6566.	6667.	6768.	6869.	6970.	7071.	7172.	7273.	7374.	7475.	7576.	7677.	7778.	7879.	7980.	8081.	8182.	8283.	8384.	8485.	8586.	8687.	8788.	8889.	8990.	9091.	9192.	9293.	9394.	9495.	9596.	9697.	9798.	9899.	9900.

HYDROGRAPH ROUTING

ROUTE THROUGH COKERBURG

ISTAG	ICOMP	ICCON	ITAPE	JPLT	JPRY	INAME	ISTAGE	TAUTO
2	1	0	0	0	0	1	0	0
ROUTING DATA								
CLOSS	AVG	IRCS	IRAMP	IPDI	IPMP	LSTR		
0.0	0.00	1	1	0	0			

NSIPS	NSIDL	LAG	AMSKK	X	TSK	STORA	TSPRAT
1	0	0	0.000	0.000	0.000	-1072.	-1

STAGE	1072.00	1073.00	1074.00	1075.00	1076.00	1077.00	1078.00	1079.00
1080.00								

FLOW	0.00	149.00	405.00	750.00	1135.00	2470.00	3785.00	7185.00
16810.00								

SURFACE AREA	0.	7.	9.	13.	20.	23.

CAPACITY	0.	37.	61.	235.	357.	421.

ELEVATION	1057.	1072.	1075.	1090.	1097.	1100.

CREL	SPWID	CUOM	EXPW	FLEVI	COUL	CAREA	EXPL
1072.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0

DAM DATA			
TOPIL	COUL	EXPL	EXWID
1075.0	0.0	0.0	0.0

DAM DATA			
TOPIL	COUL	EXPL	EXWID
1075.0	0.0	0.0	0.0

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PEAK-RATIO FLOODING COMPUTATIONS
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

RATIOS APPLIED TO FLOWS

RATIO 1 RATIO 2 RATIO 3 RATIO 4
 .05 .10 .50 1.00

HYDROGRAPH AT

ROUTED TO

1 131. 262. 1311. 2627.
 (1.37) (3.71) (37.11) (74.25)

2 105. 226. 1255. 2670.
 (1.37) (2.90) (35.53) (74.18)

6/

PLAN 1

DATE OF PM	MAXIMUM RESERVOIR W.S. ELEV.	ELEVATION STORAGE OUTFLOW	FULLER VALUE 1072.00 37. 0.	OUTFLOW VALUE 1072.00 37. 0.	FOR OF DAM 1075.30 61. 750.	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
0.05	1072.74		0.00	1.00	0.00	46.67	0.00
0.10	1073.51		0.00	2.00	0.00	40.67	0.00
0.50	1076.04		1.00	12.00	1.00	40.50	0.00
1.00	1076.56		1.00	26.00	5.17	40.33	0.00

2/7

 FLOOD HYDROGRAPH PACKAGE (FHC-1)
 DATA SAFETY VERSION JULY 1978
 LAST MODIFICATION 01 APR 80

RUN DATE 81/03/16
 TIME 05.52.37

RATIOS OF PMF ROUTED THROUGH THE RESERVOIR AND DOWNSTREAM
 DOWNSTREAM CONDITIONS DUE TO OVERTOPPING OF COKEBURG DAM
 PLAN 1 ASSUMES BREACH, PLAN 2 ASSUMES NO BREACH (PA-1094)

JOB SPECIFICATION									
EQ	NHR	NMIN	LUAY	TRK	TRM	TRRC	IPRT	IPRT	ISTAN
288	0	10	0	0	0	0	0	0	0
			JUPTR	AWT	LRPT	TRACE			
			5	0	0	0			

MULTI-PLAN ANALYSIS TO BE PERFORMED

RTIOS= 0.50

IPRT= 2 NR110= 1 LR110= 1

SUB-AREA RUNOFF COMPUTATION

INFLOW

ISTAG	ICOMP	TECON	ITAPE	JPLT	JPRT	INAME	ISTAGE	TAUTO
1	0	0	0	0	0	1	0	0

HYDROGRAPH DATA

LDYNG	LDNG	TAELA	STAGP	TRSDA	TRSPC	RATIO	ISUM	ISAME	LOCAL
1	1	0.53	0.00	0.53	1.00	0.0000	0	1	0

PRECIP DATA

SPFE	PMX	RC	R12	R24	R48	R72	R96
0.00	24.25	102.00	120.00	130.00	140.00	0.00	0.00

LOSS DATA

LRPT	STKR	DLTKR	RTIOL	EPAIN	STRES	RTIOL	STRT	CNST	ALSRX	RTIMP
0	0.00	0.00	1.00	0.00	0.00	1.00	1.00	0.00	0.00	0.00

DIFF HYDROGRAPH DATA

5/7

TP= 0.04 CP= 0.50 N/A= 0

RECESSION DATA

APPROXIMATE CLARK COEFFICIENTS FROM GIVEN SIDER CP AND TP ARE TC= 4.21 AND R= 5.10 INTERVALS

STRENGTH = 1.50 GR/SQ = 7.05 R/TOR = 2.00

UNIT HYDROGRAPH TO UNIT-OF-PERIOD ORIGINATES. LAG= .04 HOURS. CP= .50 VOL= 1.00

30.	109.	203.	262.	255.	213.	175.	166.	118.	97.
80.	65.	54.	44.	36.	30.	24.	20.	17.	14.
11.	9.	8.	6.	5.	4.	3.	3.	2.	2.

PEAK FLOW AND STORAGE CAPACITY OF THE DAM AND RESERVOIR FOR THE DESIGN FLOOD
 FLOOD TO WHICH THE DAM AND RESERVOIR ARE DESIGNED
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

PEAK FLOW AND STORAGE CAPACITY OF THE DAM AND RESERVOIR FOR THE DESIGN FLOOD

DESCRIPTION	STATION	AREA	PEAK FLOW	RATIO	
				1	2
HYDROGRAPH AT	1	.53	1	1.11	
	(1.37)	(1.11	
				1.11	
RATIO TO	2	.53	1	1.11	
	(1.37)	(1.11	
				1.11	
RATIO TO	3	.53	1	1.11	
	(1.37)	(1.11	
				1.11	

Summary of Dam Safety Evaluation

PLAN 1

RATIO OF PMF	MAXIMUM RESERVOIR WATER LEVEL	ELEVATION Storage OUTFLOW		MAXIMUM STORAGE ACFT		MAXIMUM OUTFLOW CFS		DURATION OVER TOP HOURS		TIME OF MAX OUTFLOW HOURS		TIME OF FAILURE HOURS
		1076.00	1076.05	1076.00	1076.05	1076.00	1076.05	1076.00	1076.05	1076.00	1076.05	
.50	1076.05	1076.05	1076.05	1076.00	1076.05	1076.00	1076.05	1076.00	1076.05	1076.00	1076.05	1076.05

PLAN 2

RATIO OF PMF	MAXIMUM RESERVOIR WATER LEVEL	ELEVATION Storage OUTFLOW		MAXIMUM STORAGE ACFT		MAXIMUM OUTFLOW CFS		DURATION OVER TOP HOURS		TIME OF MAX OUTFLOW HOURS		TIME OF FAILURE HOURS
		1076.00	1076.05	1076.00	1076.05	1076.00	1076.05	1076.00	1076.05	1076.00	1076.05	
.50	1076.05	1076.05	1076.05	1076.00	1076.05	1076.00	1076.05	1076.00	1076.05	1076.00	1076.05	1076.05


PLAN 1 STATION 3

RATIO	MAXIMUM STORAGE ACFT	ELEVATION Storage OUTFLOW		MAXIMUM STORAGE ACFT		MAXIMUM OUTFLOW CFS		DURATION OVER TOP HOURS		TIME OF MAX OUTFLOW HOURS		TIME OF FAILURE HOURS
		1076.00	1076.05	1076.00	1076.05	1076.00	1076.05	1076.00	1076.05	1076.00	1076.05	
.50	1076.05	1076.05	1076.05	1076.00	1076.05	1076.00	1076.05	1076.00	1076.05	1076.00	1076.05	1076.05

PLAN 2 STATION 3

RATIO	MAXIMUM STORAGE ACFT	ELEVATION Storage OUTFLOW		MAXIMUM STORAGE ACFT		MAXIMUM OUTFLOW CFS		DURATION OVER TOP HOURS		TIME OF MAX OUTFLOW HOURS		TIME OF FAILURE HOURS
		1076.00	1076.05	1076.00	1076.05	1076.00	1076.05	1076.00	1076.05	1076.00	1076.05	
.50	1076.05	1076.05	1076.05	1076.00	1076.05	1076.00	1076.05	1076.00	1076.05	1076.00	1076.05	1076.05

APPENDIX E
DRAWINGS




ELLSWORTH QUADRANGLE
7.5 MINUTE SERIES

COKEBURG WATER SUPPLY DAM

DOWNSTREAM EXPOSURE MAP
SCALE 1" = 2000'

L. ROBERT KIMBALL & ASSOCIATES
CONSULTING ENGINEERS & ARCHITECTS

E-1



SITE LOCATION MAP
WASHINGTON COUNTY, PENNSYLVANIA


APPENDIX F
GEOLOGY

General Geology

The Cokeburg Water Supply Dam is located in the Pittsburgh Plateaus Section of the Appalachian Plateaus Province. This section typically consists of rounded hills and ridges formed through the erosion by streams of a former plain-like area. In the study area, the ridges are more definite and folds are broader than elsewhere. The sediments are deformed by several sub-parallel secondary folds which are superimposed upon a major spoon-shaped trough of first magnitude in southwestern Pennsylvania and adjacent regions. The axes of these folds trend about N30-50° E, plunging gently southward. The Cokeburg Water Supply Dam lies on the northwest limb of the Waynesburg Syncline, striking to the northeast. The strata dip gently, 1-2°, to the southeast. No major faulting is noted in the area.


The dam is underlain by strata of the lower and middle members of the Waynesburg Formation of Lower Permian and Upper Pennsylvanian Age. This formation is made up of alternating beds of shale and sandstone with many thin coal seams and discontinuous limestone beds. The dam is underlain in part by the Waynesburg A Coal Seam and by argillaceous limestones separated by siltstone and sandstone in places. In general, the Washington Formation is a poor producer of water, with the exception of its basal member, the Waynesburg Sandstone.

The Cokeburg Water Supply Dam is located in the Main Bituminous Coal Field. Principal coal beds which underly the dam are the Waynesburg "A", Waynesburg, and Pittsburgh, in descending order. The Waynesburg "A" coal has a thickness range of 14-28 inches. The Pittsburgh coal is about 440 feet beneath the dam and has been mined out (1964). These beds and several other coal beds of local economic value exist beneath the strata in the vicinity of the dam. Mine dumps are located to the north, east and west of the dam site.



GEOLOGIC MAP OF THE AREA AROUND CHAMBERS DAM,
COKEBURG WATER SUPPLY DAM AND BENTLEYVILLE DAM

SCALE: 1:250,000



CHAMBERS DAM

COKEBURG WATER SUPPLY DAM

BENTLEYVILLE DAM

CHAMBERS DAM

