

AD-A105 768

BAKER (MICHAEL) JR INC BEAVER PA
NATIONAL DAM SAFETY PROGRAM. WOODWARD DAM (INVENTORY NUMBER NY --ETC(U)
JUN 81 G KESTER


F/G 13/13

DACW51-81-C-0010

NL

UNCLASSIFIED

1 of 2
AD-A105 768
20-50



LOWER HUDSON RIVER BASIN

4


WOODWARD DAM

LEVEL II

ORANGE COUNTY, NEW YORK
INVENTORY NO. 507

AD A105768

**PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM**



APPROVED FOR PUBLIC RELEASE;
DISTRIBUTION UNLIMITED

DTIC
SELECTED
JUL 1 1981

D

NEW YORK DISTRICT CORPS OF ENGINEERS

JUNE 1981

70 10 19

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
	AD-A420576	
4. TITLE (and Subtitle) Phase I Inspection Report Woodward Dam Lower Hudson River Basin, Orange County, NY Inventory 507		5. TYPE OF REPORT & PERIOD COVERED Phase I Inspection Report National Dam Safety Program
7. AUTHOR(s) GRANVILLE KESTER, JR.		6. PERFORMING ORG. REPORT NUMBER
		8. CONTRACT OR GRANT NUMBER(s) (15) DACW51-81-C-0010
9. PERFORMING ORGANIZATION NAME AND ADDRESS Michael Baker, Jr. Inc. 4301 Dutch Ridge Road Box 280 Beaver, PA 15009		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS (12) 557
11. CONTROLLING OFFICE NAME AND ADDRESS Department of the Army 26 Federal Plaza New York District, CofE New York, New York 10287		12. REPORT DATE (11) 30 June 1981
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) Department of the Army 26 Federal Plaza New York District, CofE New York, NY 10287		13. NUMBER OF PAGES
		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; Distribution unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report) (6) National Dam Safety Program. Woodward Dam (Inventory Number NY 507), Lower Hudson River Basin, Orange County, New York. Phase I Inspection Report.		
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dam Safety Woodward Dam National Dam Safety Program Orange County Visual Inspection Lower Hudson River Basin Hydrology, Structural Stability		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report provides information and analysis on the physical condition of the dam as of the report date. Information and analysis are based on visual inspection of the dam by the performing organization. Examination of available documents and a visual inspection of the dam and appurtenant structures did not reveal conditions which constitute an immediate hazard to human life or property.		

Using the Corps of Engineers' screening criteria, it has been determined that the dam would be overtopped for all storms exceeding approximately 60 percent of the Probable Maximum Flood (PMF). Therefore, the spillway is adjudged "inadequate."

No signs of instability were noted in the embankment; therefore, no stability analysis will be required.

Current inspection and maintenance procedures by the owner are adequate but need to be documented. Monitoring of the reservoir levels should be expanded to include readings during peak flow periods.

Accession For	
NTIS GRA&I	☒
DTIC TAB	☐
Unannounced	☐
Justification	
By	
Distribution/	
Availability Codes	
Dist	Avail and/or Special
A	

DTIC
ELECTE
S OCT 19 1981 D

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I Investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
WOODWARD DAM
I.D. No. NY 507
DEC DAM No. 179A-562 LOWER HUDSON RIVER BASIN
ORANGE COUNTY, NEW YORK

TABLE OF CONTENTS

	<u>PAGE NO.</u>
- ASSESSMENT	-
- OVERVIEW PHOTOGRAPH	-
1 PROJECT INFORMATION	1
1.1 GENERAL	1
1.2 DESCRIPTION OF PROJECT	1
1.3 PERTINENT DATA	3
2 ENGINEERING DATA	5
2.1 GEOLOGY	5
2.2 SUBSURFACE INVESTIGATION	5
2.3 DAM AND APPURTENANT STRUCTURES	6
2.4 CONSTRUCTION RECORDS	6
2.5 OPERATION RECORDS	6
2.6 EVALUATION OF DATA	7
3 VISUAL INSPECTION	9
3.1 FINDINGS	9
3.2 EVALUATION	11
4 OPERATION AND MAINTENANCE PROCEDURES	13
4.1 PROCEDURES	13
4.2 MAINTENANCE OF THE DAM	13
4.3 WARNING SYSTEM	13
4.4 EVALUATION	13
5 HYDRAULIC/HYDROLOGIC	15
5.1 DRAINAGE AREA CHARACTERISTICS	15
5.2 ANALYSIS CRITERIA	15
5.3 SPILLWAY CAPACITY	15
5.4 RESERVOIR CAPACITY	16
5.5 FLOODS OF RECORD	16
5.6 OVERTOPPING POTENTIAL	16
5.7 RESERVOIR EMPTYING POTENTIAL	16
5.8 EVALUATION	16

	<u>PAGE NO.</u>
6 STRUCTURAL STABILITY	17
6.1 EVALUATION OF EMBANKMENT STABILITY	17
6.2 STABILITY ANALYSIS	17
6.3 SEISMIC STABILITY	18
7 ASSESSMENT/RECOMMENDATIONS	19
7.1 ASSESSMENT	19
7.2 RECOMMENDED MEASURES	19

APPENDIX

- A. PHOTOGRAPHS
- B. VISUAL INSPECTION CHECKLIST
- C. HYDROLOGIC/HYDRAULIC DATA AND COMPUTATIONS
- D. REFERENCES
- E. DRAWINGS
- F. BACKGROUND DOCUMENTS

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

Name of Dam: Woodward Dam (I.D. NY 507)
State: New York
County: Orange
Stream: Little Shawangunk Kill
Dates of Inspection: 10 January 1981
9 March 1981

ASSESSMENT

Examination of available documents and a visual inspection of the dam and appurtenant structures did not reveal conditions which constitute an immediate hazard to human life or property.

Using the Corps of Engineers' screening criteria, it has been determined that the dam would be overtopped for all storms exceeding approximately 60 percent of the Probable Maximum Flood (PMF). Therefore, the spillway is adjudged "inadequate."

No signs of instability were noted in the embankment; therefore, no stability analysis will be required.

Current inspection and maintenance procedures by the owner are adequate but need to be documented. Monitoring of the reservoir levels should be expanded to include readings during peak flow periods.

The following remedial measures must be completed within one year.

Woodward Dam:

1. All low areas on the crest of the dam must be filled to the average crest elevation, compacted, and seeded.
2. Riprap must be placed on the upstream face of the dam above normal pool level.
3. The seep and wet areas at the toe of the dam must be monitored at regular intervals and during


periods of high reservoir levels for turbidity and increase in flow, which may indicate potential for the piping of embankment material.

4. The eroded areas at the downstream end of the spillway discharge channel must be repaired and protected.
5. All trees and brush must be cut off at ground level on the downstream toe, upstream slope, and spillway discharge channel. The root systems of all trees with a trunk diameter greater than 3 inches must be removed from the downstream toe of the dam. All resultant areas of erosion and cavities must be filled, graded, compacted, and seeded.
6. The animal burrow at the toe of the dam must be filled, compacted, and seeded.
7. Spalled areas in the concrete of the gate house and concrete weir must be repaired.
8. A staff gage must be installed to monitor reservoir levels above normal pool.


Greenleaf Dam:

1. The seep at the toe of the dam must be monitored at regular intervals and during periods of high reservoir levels for turbidity and increase in flow, which may indicate potential for the piping of embankment material.
2. Riprap must be placed on the upstream face of the dam above normal pool level.
3. All trees and brush must be cut off at ground level on the downstream toe of the dam. The root systems of all trees with a trunk diameter greater than 3 inches are to be removed. All resultant areas of erosion and cavities must be filled, graded, compacted, and seeded.
4. The animal burrow and depression on the downstream side of the dam must be filled, graded, compacted, and seeded.

SUBMITTED:


Granville Kester, Jr., P.E.
Vice President
MICHAEL BAKER, JR. of New York, INC.

APPROVED:


Colonel W.M. Smith, Jr.
New York District Engineer

DATE: 30 JUN 1981



Overall View of Dam
Woodward Dam
I.D. No. NY 507
9 March 1981

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
WOODWARD DAM
I.D. No. NY 507
DEC DAM No. 179A-562
LOWER HUDSON RIVER BASIN
ORANGE COUNTY, NEW YORK

SECTION 1: PROJECT INFORMATION

1.1 GENERAL

- a. Authority - The Phase I Inspection reported herein was authorized by the Department of the Army, New York District, Corps of Engineers, to fulfill the requirements of the National Dam Inspection Act, Public Law 92-367.
- b. Purpose of Inspection - This inspection was conducted to evaluate the existing conditions of the dam, to identify deficiencies and hazardous conditions, to determine if these deficiencies constitute hazards to life and property, and to recommend remedial measures where required.

1.2 DESCRIPTION OF PROJECT

- a. Description of Dam and Appurtenances - Shawangunk Lake is formed by Woodward Dam and Greenleaf Dam. Woodward Dam is an earthfill dam with a height of 29.7 feet, measured from the minimum top of dam to the toe of the dam, and a total length of 463 feet. The embankment has a crest width of 9 feet. The side slope of the upstream face is 1V:2.4H (Vertical to Horizontal) and the side slope of the downstream face is 1V:2.2H. The upstream face of the embankment is protected by riprap up to normal pool level. The original plans show a masonry core wall, but test pits dug by the owner reportedly show no evidence of this core wall. The reservoir is used as a water supply for the City of Middletown, New York.

The spillway is 50 feet from the right abutment and 18 feet upstream from the crest of the dam. The crest of the weir is 18.7 feet long (perpendicular to the direction of flow). The breadth of the weir (parallel to the direction of flow) is 1.1 feet. Flow over the spillway falls 2.7 feet to the discharge channel.

The discharge channel extends approximately 300 feet downstream from the crest of the weir. The portion of the channel extending downstream from the weir to the downstream side of the access bridge on the crest of the dam is rock-lined with stone side walls. Downstream from the access bridge, the discharge channel is a trapezoidal, rock-lined channel. A large number of trees are growing in this section of the channel.

The outlet from the reservoir consists of a 20-inch water supply line which gravity feeds to Monhegan Lake, 1 mile northeast of Shawangunk Lake. The upper level intake for the 20-inch water supply line is 11.6 feet below normal pool level, and the lower level intake is 26 feet below normal pool level. Both intake pipes (each 20-inch) are controlled by valves housed in a building on the upstream face of the dam. The plans show an 8-inch drain from the valve house to the downstream face of the dam, but this drain outlet could not be located.

Greenleaf Dam is an earthfill dam with a height of 27.9 feet, measured from the minimum top of dam to the toe of the dam, and a total length of 281 feet. The embankment has a crest width of 14.5 feet. The side slopes of the upstream and downstream faces are both 1V:2H. The upstream face of the embankment is protected by riprap up to normal pool level. Greenleaf Dam has no spillway or functioning outlet pipes.

- b. Location - Woodward Dam, on Little Shawangunk Kill, is 1 mile east of Mount Hope, New York. The reservoir and dam are in Orange County, New York. The coordinates of the dam are N 41° 27.0' and W 74° 29.7'. Woodward and Greenleaf Dams can be found on the Middletown and Otisville, New York, USGS 7.5 minute topographic quadrangles.
- c. Size Classification - The height of Woodward Dam is 29.7 feet and the reservoir storage capacity at the top of dam, elevation 769.7 feet M.S.L. (Mean Sea Level) is 1,633 acre-feet. Therefore, the dam is in the "intermediate" size category as defined by the Recommended Guidelines for Safety Inspections of Dams.

- d. Hazard Classification - Mapes Road and one home are located 3200 feet downstream from Woodward Dam. There are also three other areas downstream where the stream passes under roadways and through residential developments (see Location Plan in Appendix E). Economic damage to the roads and residential areas is likely if the dam were to fail. The possibility of excessive economic damage places Woodward Dam in the "high" hazard category as defined by the Recommended Guidelines for Safety Inspection of Dams.
- e. Ownership - The dams and reservoir are owned and operated by the City of Middletown, 16 James Street, Middletown, New York 10940. The contact person is Mr. Bill Johnson (Telephone 914-343-3169).
- f. Purpose of the Dam - The dams and reservoir are used for water supply.
- g. Design and Construction History - According to available records, the dams were originally built about 1901. The Woodward Dam was designed by W.R. Hill, consulting engineer and D.R. Lee, resident engineer. The contractor is unknown. A permit was issued to the City of Middletown to raise the dam 2.5 feet in July 1925. Plans were made for raising Woodward and Greenleaf Dams 10 feet in 1946-1947, but these plans were never implemented.
- h. Normal Operating Procedures - The Shawangunk reservoir continuously feeds Monhegan Lake through a gravity-fed 20-inch pipe. The reservoir level is normally kept at the spillway crest. The dam and spillway are visually inspected daily, and weekly records are kept on the reservoir level. The valve for the 20-inch pipe is normally open and is periodically operated to check its condition.

1.3 PERTINENT DATA

- a. Drainage Area (square miles) - 1.50
 - b. Discharge at Dam cubic feet per second (c.f.s.) -
- | | |
|---------------------------------|-------|
| Spillway Capacity (at Pool | |
| Elevation 769.7 Feet M.S.L.)* - | 532.0 |
| Reservoir Drain at Normal Pool | 6.0 |

*All elevations are referenced to the spillway crest, elevation 767.0 feet M.S.L., as shown on the plans supplied by the owner.

c. Elevations (Feet above M.S.L.) -

Average Top of Dam	771.7
Minimum Top of Dam	769.7
Normal Pool (Spillway Crest)	767.0
Streambed at Toe of Dam	740.0

d. Reservoir Surface Area (Acres) -

Top of Dam (Minimum)	125.4
Spillway Crest	100.7

e. Reservoir Storage Capacity (Acre-Feet) -

Top of Dam (Minimum)	1633.0
Spillway Crest	1332.0

f. Dam -

Type:	Earth
Length (Feet)	463.0
Height (Feet)	29.7
Top Width (Feet) - Design	20.0
Field	9.0
Side Slopes - Upstream - Design	1V:2H
Field	1V:2.4H
Downstream - Design	1V:2H
Field	1V:2.2H

g. Spillway -

Type:	Broad-crested concrete weir
Length of Crest Perpendicular to	
Direction of Flow (Feet)	18.7
Width of Crest Parallel to	
Direction of Flow (Feet)	1.1
Crest Elevation (Feet M.S.L.)	767.0

h. Reservoir Drain -

Type: Gravity fed 20-inch water supply
line to Monhegan Lake.

Control: Manual control valves in the gate
house on the crest of the dam.
The valves are normally open.

SECTION 2: ENGINEERING DATA

2.1 GEOLOGY

The Woodward and Greenleaf Dams, forming Shawangunk Reservoir, are located in the southern end of the "Hudson-Mohawk Lowlands" physiographic province of New York State. Most of this province is characterized by low elevation and relief due to the erosion of outcropping weak rocks. Bedrock occurring in the immediate vicinity of the dam, as indicated on the Geologic Map of New York (J.G. Broughton and others, 1970), consists of moderately to intensely folded shales and graywacke of the Austin Glen Formation, Trenton Group (Middle Ordovician). Tabular blocks of silt shale and fine grained sandstone were noted on both abutment slopes during the visual inspection. No major faults are reported in the vicinity of the dam. This entire area has been glaciated.

2.2 SUBSURFACE INVESTIGATION

Original subsurface information for Woodward Dam could not be located during this inspection. However, visual observation indicates that the area appears to be covered in part by glacial debris in the form of silt and fine sand.

According to the available soils report (preliminary) for Orange County, prepared by the USDA Soil Conservation Service, local foundation and abutment materials for the dam consist of the following soils:

Left Side: Arnot Rock Outcrop Association Soils - These soils are medium textured, well drained materials formed in glacial till derived from red shale and gray sandstone. Bedrock occupies from 50 to 90 percent of the mapped areas containing these soils. Soil thickness is approximately 1 to 1-1/2 feet. Depth to seasonal high water table is approximately 2+ feet.

Right Side: Bath Silt Loam - These soils are medium textured, well drained, yellowish brown, strongly to medium acid materials with a very firm fragipan that developed in deep glacial till derived from slates, shales, and sandstone mainly. Bath soils have approximately 2 to 2-1/2

feet of moderately permeable gravelly loam over 1-1/2 to 4 feet of slowly permeable, very firm gravelly silt loam. Depth to seasonal high water table is approximately 4+ feet.

2.3 DAM AND APPURTENANT STRUCTURES

Woodward and Greenleaf dams are earthen embankments built around 1901 by the City of Middletown for water supply purposes. The impoundment formed, Shawangunk Reservoir, is used in conjunction with the neighboring Kinch, Monhegan, and Highland reservoirs. Plans were formulated in 1946-1947 for raising the Woodward and Greenleaf Dams to increase the storage area in Shawangunk Reservoir, but these plans were never implemented (Plate 5).

The appurtenant structures for operation of the reservoir are mainly located at Woodward Dam. A gate house on the upstream side of the dam houses two 20-inch cast iron intake pipes and the respective control valves. A 20-inch water supply pipe leads from the gate house to Monhegan Lake. An 8-inch blow-off pipe reportedly leads from the gate house to just downstream of the dam. However, the outlet of the blow-off pipe was not observed during the visual inspection (a seep was observed at the toe of the dam that is probably related to this outlet). Woodward Dam has a spillway located 50 feet to the left of the right abutment. The spillway contains a concrete weir 18.7 feet long which is offset 18 feet upstream of the crest of the dam. The crest of the weir lies 2.7 feet below the minimum embankment elevation. The discharge channel between the weir and just beyond the crest of the dam is protected by stone wing walls.

2.4 CONSTRUCTION RECORDS

Construction records are not available. General design plans were available for review as part of these investigations. These plans are included in Appendix E.

2.5 OPERATION RECORDS

Weekly observations of reservoir water levels are kept by a watchman for the City of Middletown. The watchman visually inspects Woodward Dam daily. The valves are reportedly operated periodically. Formal records of the inspections or operation of valves are not kept.

2.6 EVALUATION OF DATA

The background information collected during this investigation was obtained primarily from files of the New York State Department of Environmental Conservation. Supplementary information was acquired through conversations with Mr. Bill Johnson, representing the City of Middletown. The available data are considered adequate and reliable for Phase I Inspection purposes.

SECTION 3: VISUAL INSPECTION

3.1 FINDINGS

- a. General - The inspection was performed on 10 January 1981. The weather was sunny and the temperature was 20° Fahrenheit. There was 4 to 6 inches of snow on the dam. The water surface was 13.6 feet below the spillway crest. This low reservoir level was attributed to an unusually low amount of precipitation occurring in the watershed prior to the inspection. Deficiencies found during the inspection will require remedial treatment. A Field Sketch of conditions found during the inspection is included in Appendix E. The complete Visual Inspection Checklist is presented as Appendix B. Because there was a snow cover on the dam during the initial inspection, a follow-up inspection was carried out on 9 March 1981.
- b. Spillway - The spillway at Woodward Dam is 50 feet from the right abutment and 18 feet upstream from the crest of the dam. The spillway is a low, broad-crested, concrete weir with masonry training walls. The masonry training walls are placed stone with many voids and extend to the downstream side of the wood deck bridge, across the discharge channel at the crest of the dam. The right masonry training wall is collapsing under the bridge. The concrete weir has relatively major spalling on the downstream face. Greenleaf Dam has no spillway.
- c. Embankment - No evidence of sloughing or subsidence was observed on the upstream or downstream slopes of the embankment at Woodward Dam.

The following is a list of deficiencies observed during the visual inspection of the embankment at Woodward Dam:

1. Minor erosion (riprap displacement) at normal pool level on the upstream face of the dam.
2. Minor low areas along the crest of the dam near the gate house.
3. A small amount of brush growing on the upstream slope of the dam.
4. Trees and brush growing on the downstream face and toe of the dam. There are six trees

24 inches in diameter and one tree 14 inches in diameter.

5. Minor seepage at the toe of the dam at Station 2+30. The estimated flow rate of the seep is 0.5 gallons per minute (g.p.m.). This could be from the 8-inch outlet pipe that could not be located during the visual inspection.

A wet area (10 square feet) was observed at Station 2+70 at the toe of the dam. The flow rate or source of this moisture could not be determined.

No evidence of sloughing or subsidence was observed on the upstream or downstream slopes of the embankment at Greenleaf Dam.

The following is a list of deficiencies observed at Greenleaf Dam during the visual inspection of the embankment:

1. Minor erosion (riprap displacement) at normal pool level on the upstream face of the dam.
 2. Trees and brush growing on the downstream face and toe of the dam. There are two trees 24 inches in diameter.
- d. 9 March 1981 Inspection - The reservoir level was approximately 4 feet higher during the second inspection than the initial inspection.

The only additional observation made at Woodward Dam was that there is an animal burrow in the downstream toe of the embankment at approximately the center of the embankment.

Several additional problems were observed at Greenleaf Dam, the dam which, along with Woodward Dam, forms Shawangunk Lake. These were: (1) an animal burrow in the downstream toe of the dam approximately 50 feet from the right abutment, (2) a wet area covering approximately 10 square feet at the downstream toe of the dam near the buried outlet for the abandoned outlet works; and (3) a small depression on the downstream face of the embankment slightly to the right of the center of the dam and approximately half-way down the downstream face. There was no measurable flow from the wet area and it could not be determined if the wet area resulted from seepage through the embankment, poor surface drainage, or seepage through the abandoned outlet works.

- e. Outlet Works - A 20-inch pipe, 19,500 feet long, runs from the reservoir at Woodward Dam to Monhegan Lake. A gate valve on the upstream side is used to control the gravity flow to Monhegan Lake. The outlet for an 8-inch drain for the gate house as shown on the original plans could not be located at the time of inspection.

The gate house is a 14-foot by 28-foot brick structure on the upstream face of Woodward Dam. Spalled areas on the gate house foundation have been recently patched, but the patches are deteriorating.

Greenleaf Dam has no operating outlet works. An abandoned valve pit is on the crest near the center of the dam.

- f. Downstream Channel - The discharge channel downstream from the Woodward Dam spillway has a mild slope with rocks, trees, and local accumulations of debris in the channel. At the downstream end of the discharge channel there is severe erosion of the channel banks.

One house and Mapes Road are located 3200 feet downstream from the dam.

- g. Reservoir - The reservoir slopes are moderate with large wooded areas. There were no signs of slope instability and sedimentation is only a minor problem. At the time of inspection, some minor sedimentation was being removed from the reservoir.

3.2 EVALUATION

The visual inspection of Woodward Dam revealed several deficiencies in this structure. The following items were noted:

1. Minor low areas along the crest of the dam near the gate house.
2. Minor erosion (riprap displacement) at normal pool level on the upstream face of the dam.
3. Minor seepage at the toe of the dam at Station 2+30. The estimated flow rate of the seep is 0.5 gallons per minute (g.p.m.). This could be from the 8-inch outlet pipe that could not be located during the visual inspection.

4. A wet area (10 square feet) at Station 2+70 at the toe of the dam. The flow rate or source of this moisture could not be determined.
5. Severe erosion of the channel banks exists at the downstream end of the discharge channel.
6. Trees and brush growing on the downstream face and toe of the dam. There are six trees 24 inches in diameter and one tree 14 inches in diameter.
7. Trees growing in the spillway discharge channel.
8. A small amount of brush growing on the upstream slope of the dam.
9. An animal burrow at the downstream toe of the dam at approximately the center of the embankment.
10. Spalled areas on the concrete of the gate house.

The visual inspection of Greenleaf Dam revealed several deficiencies in this structure. The following items were noted:

1. A wet area at the downstream toe of the dam near the buried outlet for the abandoned outlet works.
2. Minor erosion (riprap displacement) at normal pool level on the upstream face of the dam.
3. Trees and brush growing on the downstream face and toe of the dam. There are two trees 24 inches in diameter.
4. A small depression on the downstream face of the embankment slightly to the right of the center of the dam and approximately half-way down the downstream face.
5. An animal burrow in the downstream toe of the dam approximately 50 feet from the right abutment.

SECTION 4: OPERATION AND MAINTENANCE PROCEDURES

4.1 PROCEDURES

There are no formal operating procedures. The reservoir continuously feeds Monhegan Lake through a gravity feed 20-inch pipe. The reservoir is normally kept at the spillway crest, but at the time of the inspection, the reservoir was 13.6 feet below the spillway crest because of a water shortage in the area.

4.2 MAINTENANCE OF THE DAM

Maintenance of Woodward Dam is the responsibility of the City of Middletown. The watchman visually inspects Woodward Dam daily and weekly records are maintained on the reservoir level. The grass is mowed and some of the trees are removed each year. The valves for the water supply line are operated periodically.

4.3 WARNING SYSTEM

At the time of the inspection, there was no warning system or emergency action plan in operation.

4.4 EVALUATION

Past maintenance of the dam and operating facilities appears to have been adequate, but, except for the water level measurements, the past activities have not been documented. A checklist should be compiled by the owner's representative to document the findings made during the periodic inspections and the maintenance items completed. A warning system and emergency action plan should be developed and put into operation.

SECTION 5: HYDRAULIC/HYDROLOGIC DATA

5.1 DRAINAGE AREA CHARACTERISTICS

Delineation of the watershed of Woodward Dam was made using the USGS quadrangles for Middletown and Otisville, New York. The drainage basin consists of moderate slopes which are well covered by forests and ground vegetation. Some storage exists in Highland Lake which is upstream from Shawangunk Lake, formed by Woodward Dam and Greenleaf Dam. A small amount of residential development exists in the drainage area. The total drainage area controlled by the dam is 1.50 square miles.

5.2 ANALYSIS CRITERIA

A hydrologic analysis of the watershed and hydraulic analysis of dam was conducted using the U.S. Army Corps of Engineers' Flood Hydrograph Package HEC-1 DB computer program (Reference 12, Appendix D). The unit hydrograph was defined using the Snyder Unit Hydrograph Method. Estimates of Snyder hydrograph coefficients were based upon average coefficients from the Hydrologic Flood Routing Model for Lower Hudson River Basin (Reference 16, Appendix D). Precipitation data was taken from Hydrometeorological Report No. 33 (Reference 8, Appendix D). Rainfall losses were estimated at an initial loss of 1.0 inch and a constant loss rate of 0.1 inch per hour thereafter. The hydraulic capacity of the dam, reservoir, and spillway was determined by incorporating the Modified Puls Routing Method. All flood routings were begun with the reservoir at normal pool level. Outlet discharge capacity was computed by hand. The Probable Maximum Flood (PMF) and 1/2 Probable Maximum Flood (1/2 PMF) were developed and routed through the reservoir.

The runoff hydrograph was routed through Highland Lake Dam and combined with the runoff hydrograph for Shawangunk Lake, then routed through Woodward Dam.

5.3 SPILLWAY CAPACITY

The spillway capacity at the minimum top of dam is 532 c.f.s. There is no auxiliary or emergency spillway at Woodward Dam.

PRECEDING PAGE BLANK-NOT FILMED

5.4 RESERVOIR CAPACITY

The storage capacity of Shawangunk Lake at normal pool is 1332 acre-feet. The storage capacity of the reservoir at the minimum top of dam is 1633 acre-feet. Therefore, flood control storage of the reservoir between the spillway crest and top of dam is 301 acre-feet. This volume represents a total of 1.88 inches of runoff from the watershed.

5.5 FLOODS OF RECORD

No information concerning the effects of significant floods on the dam is available.

5.6 OVERTOPPING POTENTIAL

The maximum capacity of the spillway is 532 c.f.s. before overtopping would occur. The peak outflows of the PMF and 1/2 PMF are 1084 c.f.s. and 422 c.f.s., respectively. Therefore, the spillway is capable of passing 60 percent of the PMF before overtopping would occur.

5.7 RESERVOIR EMPTYING POTENTIAL

The reservoir can only be drawn down by the 20-inch, 19,500 foot long, gravity fed water supply line from Woodward Dam to Monhagen Lake. Neglecting inflow, the reservoir can be drawn down from normal pool in approximately 113 days. This is equivalent to an approximate drawdown rate of 0.3 feet per day, based on the hydraulic height measured from normal pool divided by the time to dewater the reservoir.

5.8 EVALUATION

Woodward Dam is an "intermediate" size - "high" hazard dam requiring the spillway to pass a flood in the range of the 1/2 PMF to PMF. The PMF and 1/2 PMF were routed through the watershed and dam. It was determined that the spillway is capable of passing 60 percent of the PMF before overtopping the dam. The spillway is, therefore, judged to be "inadequate."

Conclusions pertain to present conditions and the effect of future development on the hydrology has not been considered.

SECTION 6: STRUCTURAL STABILITY

6.1 EVALUATION OF EMBANKMENT STABILITY

- a. Visual Observations - No signs of potential instability were observed during the visual inspections of Woodward Dam and Greenleaf Dam. The dams are generally well maintained. A seep was observed along the downstream toe of Woodward Dam during the visual inspection; however, this is believed to be related to the 8-inch blow-off pipe outlet that is shown on available plans for the structure.
- b. Design and Construction Information - No design and construction information relating to stability is available for Woodward Dam or Greenleaf Dam.
- c. Operating Records - Woodward and Greenleaf Dams are inspected daily by a watchman for the City of Middletown. The control valves in the gate house are operated periodically.
- d. Post Construction Changes - Background information indicates that the dam may have been raised 2.5 feet in 1925. Plans were formulated in 1946-1947 for raising Woodward and Greenleaf Dams significantly to increase the storage area in Shawangunk Reservoir, but these plans were never implemented.

6.2 STABILITY ANALYSIS

The results of previous stability analyses, if any, were not available for Woodward Dam.

The dam appears to be a relatively homogeneous embankment composed largely of sandy silt (estimated to be ML Group Soils - Unified Classification System). The original plans for Woodward Dam indicate a masonry core wall, but test pits dug in past investigations reportedly revealed no evidence of this core wall. Woodward Dam is 29.7 feet high with a crest width of 9 feet. The upstream slope of the embankment is 1V:2.4H while the downstream slope is 1V:2.2H. The upstream slope is protected well with riprap with the exception of the top 4 to 5 feet below the crest. The dam is not subject to rapid drawdown (greater than 0.5 feet drop in the reservoir level per day) as determined by hydraulic calculations made during these investigations.

The slopes of Woodward Dam are slightly steep (particularly the upstream slope) and the crest width is narrow. However, a stability analysis is not considered necessary, based on the overall condition of the dam as observed during the visual inspection.

6.3 SEISMIC STABILITY

The dam is located in Seismic Zone 1 which presents no hazard from earthquakes, according to the Recommended Guidelines for Safety Inspection of Dams. This determination is contingent on the requirements that static stability conditions are satisfactory and conventional safety margins exist.

SECTION 7: ASSESSMENT/RECOMMENDATIONS

7.1 ASSESSMENT

- a. Safety - Examination of available documents and visual inspections of Woodward Dam did not reveal any conditions which are considered to be hazardous.

Using the Corps of Engineers' screening criteria for review of spillway adequacy, it has been determined that the dam would be overtopped for all storms exceeding approximately 60 percent of the PMF. Therefore, the spillway is adjudged "inadequate."

- b. Adequacy of Information - The information available and the observations and measurements made during the visual inspection are considered sufficient for this Phase I Inspection Report.
- c. Need for Additional Information - No additional information is needed as a result of this Phase I Inspection Report. A stability analysis is not considered necessary at this time.
- d. Urgency - The remedial measures listed below must be completed within one year from notification.

7.2 RECOMMENDED MEASURES

The regular inspections and maintenance procedures presently being conducted by the owner's representative appear to be adequate, although some form of documentation is needed. A thorough checklist should be compiled by the owner's representative and completed during each inspection. Maintenance items should be completed annually. Monitoring of the reservoir level should be expanded to include reservoir levels above normal pool.

The following remedial measures must be completed within one year.

Woodward Dam:

1. All low areas on the crest of the dam must be filled to the average crest elevation, compacted, and seeded.
2. Riprap must be placed on the upstream face of the dam above normal pool level.

3. The seep and wet areas at the toe of the dam must be monitored at regular intervals and during periods of high reservoir levels for turbidity and increase in flow, which may indicate potential for the piping of embankment material.
4. The eroded areas at the downstream end of the spillway discharge channel must be repaired and protected.
5. All trees and brush must be cut off at ground level on the downstream toe, upstream slope, and spillway discharge channel. The root systems of all trees with a trunk diameter greater than 3 inches must be removed from the downstream toe of the dam. All resultant areas of erosion and cavities must be filled, graded, compacted, and seeded.
6. The animal burrow at the toe of the dam must be filled, compacted, and seeded.
7. Spalled areas in the concrete of the gate house and concrete weir must be repaired.
8. A staff gage must be installed to monitor reservoir levels above normal pool.

Greenleaf Dam:

1. The seep at the toe of the dam must be monitored at regular intervals and during periods of high reservoir levels for turbidity and increase in flow, which may indicate potential for the piping of embankment material.
2. Riprap must be placed on the upstream face of the dam above normal pool level.
3. All trees and brush must be cut off at ground level on the downstream toe of the dam. The root systems of all trees with a trunk diameter greater than 3 inches are to be removed. All resultant areas of erosion and cavities must be filled, graded, compacted, and seeded.
4. The animal burrow and depression on the downstream side of the dam must be filled, graded, compacted, and seeded.

APPENDIX A
PHOTOGRAPHS

CONTENTS

- Photo 1: Upstream Face of Dam from Left Abutment -
9 March 1981
- Photo 2: Downstream Face of Dam from Right Abutment -
9 March 1981
- Photo 3: Gate House from Reservoir Side of Dam - 9 March 1981
- Photo 4: Spillway from Upstream Side - 9 March 1981
- Photo 5: Spillway Discharge Channel with Collapsed Training
Wall under Bridge (from Downstream Side of Bridge) -
9 March 1981
- Photo 6: Upstream face of Greenleaf Dam from Left Abutment -
9 March 1981

WOODWARD DAM



Photo 1. Upstream Face of Dam from Left Abutment
9 March 1981



Photo 2. Downstream Face of Dam from Right Abutment
9 March 1981

WOODWARD DAM



Photo 3. Gatehouse from Reservoir Side of Dam
9 March 1981



Photo 4. Spillway from Upstream Side
9 March 1981

WOODWARD DAM



Photo 5. Spillway Discharge Channel with Collapsed
Training Wall under Bridge (from Downstream Side of Bridge)
9 March 1981




Photo 6. Upstream Face of Greenleaf Dam from Left Abutment
9 March 1981

APPENDIX B
VISUAL INSPECTION CHECKLIST

VISUAL INSPECTION CHECKLIST

1) Basic Data

a. General

Name of Dam Woodward Dam
Fed. I.D. # NY 507 DEC Dam No. 179A-562
River Basin Hudson
Location: Town Mount Hope County Orange
Stream Name Little Shawangunk Kill
Tributary of _____
Latitude (N) 41°27.0' Longitude (W) 74°29.7'
Type of Dam Earth embankment
Hazard Category High
Date(s) of Inspection 10 January 1981
Weather Conditions Sunny 20°
Reservoir Level at Time of Inspection 753.4 ft. M.S.L.

b. Inspection Personnel Wayne D. Lasch, Gary W. Todd, Rory L. Galloway

c. Persons Contacted (Including Address & Phone No.) _____
Bill Johnson, City Hall
16 James Street
Middletown, NY 10940
914/343-3169

d. History:

Date Constructed 1901 Date(s) Reconstructed 1925
Designer W.R. Hill - Consulting Engineer
D.R. Lee - Resident Engineer
Constructed By Unknown
Owner City of Middletown, NY

2) Embankment

a. Characteristics

- (1) Embankment Material Earth (sandy silt)
- (2) Cutoff Type None
- (3) Impervious Core Reported to be masonry core. However, previous test pits by owner failed to locate any masonry core.
- (4) Internal Drainage System None observed
- (5) Miscellaneous Snow covered at time of inspection, 2-6 in. on dam.

b. Crest

- (1) Vertical Alignment Minor low areas located between Sta. 2+00 and 3+00.
- (2) Horizontal Alignment Good
- (3) Surface Cracks None observed at time of inspection.
- (4) Miscellaneous Good grass cover on crest.

c. Upstream Slope

- (1) Slope (Estimate) (V:H) 1:2.4
- (2) Undesirable Growth or Debris, Animal Burrows Small amount of brush growing on slope.

- (3) Sloughing, Subsidence, or Depressions Minor erosion (riprap displacement) at normal pool level.
- (4) Slope Protection Quartzite riprap protection extending from normal pool level to water surface at time of inspection.
- (5) Surface Cracks or Movement at Toe Unobservable at time of inspection.

d. Downstream Slope

- (1) Slope (Estimate - V:H) 1:2.2
- (2) Undesirable Growth or Debris, Animal Burrows Trees (2 to 24 in. diameter) and brush along toe of dam.
- (3) Sloughing, Subsidence or Depressions None observed at time of inspection.
- (4) Surface Cracks or Movement at Toe None observed at time of inspection.
- (5) Seepage Approx. 0.5 g.p.m. at toe of dam (Sta. 2+30), wet area (approx. 10 sq. ft.) at toe of dam at Sta. 2+70.
- (6) External Drainage System (Ditches, Trenches, Blanket) None observed
- (7) Condition Around Outlet Structure None observed at time of inspection.

(8) Seepage Beyond Toe None observed

e. Abutments - Embankment Contact Appeared good at time of inspection.

(1) Erosion at Contact None observed at time of inspection.

(2) Seepage Along Contact None observed at time of inspection.

3) Drainage System

a. Description of System None

b. Condition of System None

c. Discharge from Drainage System None

4) Instrumentation (Monumentation/Surveys, Observation Wells, Weirs, Piezometers, Etc.) None observed

5) Reservoir

- a. Slopes Mild to moderate slopes, heavily wooded.
- b. Sedimentation Minor problem, sediments currently being removed to increase capacity.
- c. Unusual Conditions Which Affect Dam Highland Lake Dam upstream, 400 ft. long, 30 ft. high, 15 ft. crest width.

6) Area Downstream of Dam

- a. Downstream Hazard (No. of Homes, Highways, etc.) Mapes road and 1 home 3200 ft. downstream, economic damage only.
- b. Seepage, Unusual Growth None observed at time of inspection.
- c. Evidence of Movement Beyond Toe of Dam None observed at time of inspection.
- d. Condition of Downstream Channel Rocks, large trees and local debris in channel.

7) Spillway(s) (Including Discharge Conveyance Channel)

Spillway is located on the right upstream side of the crest.

a. General Low concrete weir with masonry training walls. Wooden bridge
(5 ft. x 20 ft.) crosses training walls along crest of dam.

b. Condition of Service Spillway Concrete weir has relatively major
spalling especially on the downstream face.

c. Condition of Auxiliary Spillway None

d. Condition of Discharge Conveyance Channel Masonry training walls have
many voids. Right training wall under bridge is collapsing. Discharge
channel has rocks, trees and local debris. Severe erosion of channel
banks at downstream end.

8) Reservoir Drain/Outlet

Type: Pipe _____ Conduit X Other _____

Material: Concrete _____ Metal cast iron Other _____

Size: 20 in. Length 19,500 ft.

Invert Elevations: Entrance 738.0 ft.

Exit 712.0 ft. (Estimated)

Physical Condition (Describe): Unobservable X

Material: _____

Joints: _____ Alignment _____

Structural Integrity: _____

Hydraulic Capability: _____

Means of Control: Gate _____ Valve 20 in. Uncontrolled _____

Operation: Operable ☒ Inoperable _____ Other _____

Present Condition (Describe): Owner reported valves are operated
regularly.

9) Structural - Not Applicable

a. Concrete Surfaces _____

b. Structural Cracking _____

c. Movement - Horizontal & Vertical Alignment (Settlement) _____

d. Junctions with Abutments or Embankments _____

e. Drains - Foundation, Joint, Face _____

f. Water Passages, Conduits, Sluices _____

g. Seepage or Leakage _____

h. Joints - Construction, etc. _____

i. Foundation _____

j. Abutments _____

k. Control Gates _____

- l. Approach & Outlet Channels _____

- m. Energy Dissipators (Plunge Pool, etc.) _____

- n. Intake Structures _____

- o. Stability _____

- p. Miscellaneous _____

10) Appurtenant Structures (Power House, Lock, Gatehouse, Other)

- a. Description and Condition Gatehouse is a 14 ft. x 28 ft. brick structure
located on the upstream face of the dam. Spalled areas on the gatehouse
foundation have been recently patched but patches are deteriorating.

VISUAL INSPECTION CHECKLIST

1) Basic Data

a. General

Name of Dam Greenleaf Dam

Fed. I.D. # NY 508 DEC Dam No.

River Basin Hudson

Location: Town Mount Hope County Orange

Stream Name Little Shawangunk Kill

Tributary of

Latitude (N) 41°26.85' Longitude (W) 74°30.24'

Type of Dam Earth embankment

Hazard Category	High
-----------------	------

Date(s) of Inspection _____ 10 January 1981

Weather Conditions Sunny 20°

Reservoir Level at Time of Inspection 753.4 ft. M.S.L.

b. Inspection Personnel Wayne D. Lasch, Gary W. Todd,

Rory L. Galloway

c. Persons Contacted (Including Address & Phone No.)

Bill Johnson, City Hall

16 James Street

Middletown, NY 10940

914/343-3169

d. History:

Date Constructed	1901	Date(s) Reconstructed	1925
------------------	------	-----------------------	------

Designer	Unknown
----------	---------

Constructed By Unknown

Owner City of Middletown, NY

2) Embankment

a. Characteristics

- (1) Embankment Material Earth embankment
- (2) Cutoff Type None
- (3) Impervious Core None
- (4) Internal Drainage System None observed
- (5) Miscellaneous Snow covered at time of inspection, 2-6 in. on dam.

b. Crest

- (1) Vertical Alignment Good
- (2) Horizontal Alignment Good
- (3) Surface Cracks None observed at time of inspection.
- (4) Miscellaneous Snow covered at time of inspection.

c. Upstream Slope

- (1) Slope (Estimate) (V:H) 1:2
- (2) Undesirable Growth or Debris, Animal Burrows None observed at time of inspection.

(3) Sloughing, Subsidence, or Depressions Minor erosion (riprap displacement) at normal pool level.

(4) Slope Protection Quartzite riprap protection extending from normal pool level to water surface at time of inspection.

(5) Surface Cracks or Movement at Toe Unobservable at time of inspection.

d. Downstream Slope

(1) Slope (Estimate - V:H) 1:2

(2) Undesirable Growth or Debris, Animal Burrows Trees (2-24 in. diameter) and brush along toe of dam.

(3) Sloughing, Subsidence or Depressions None observed at time of inspection.

(4) Surface Cracks or Movement at Toe None observed at time of inspection.

(5) Seepage None observed at time of inspection.

(6) External Drainage System (Ditches, Trenches, Blanket) None

(7) Condition Around Outlet Structure None

(8) Seepage Beyond Toe None

e. Abutments - Embankment Contact Appeared good at time of inspection.

(1) Erosion at Contact None observed at time of inspection.

(2) Seepage Along Contact None observed at time of inspection.

3) Drainage System

a. Description of System None

b. Condition of System None

c. Discharge from Drainage System None

4) Instrumentation (Monumentation/Surveys, Observation Wells, Weirs, Piezometers, Etc.) None

5) Reservoir

- a. Slopes Moderate slopes, heavily wooded.
- b. Sedimentation Minor problem, sediments currently being removed to increase capacity.
- c. Unusual Conditions Which Affect Dam Highland Lake Dam upstream, 400 ft. long, 30 ft. high, 15 ft. crest width.

6) Area Downstream of Dam

- a. Downstream Hazard (No. of Homes, Highways, etc.) 1 small pond 200 ft. directly downstream, Yapes road and 1 home downstream.
- b. Seepage, Unusual Growth None observed at time of inspection.
- c. Evidence of Movement Beyond Toe of Dam None observed at time of inspection.
- d. Condition of Downstream Channel Mild slopes with trees and debris in channel.

7) Spillway(s) (Including Discharge Conveyance Channel)

None

- a. General _____

- b. Condition of Service Spillway _____

- c. Condition of Auxiliary Spillway _____

- d. Condition of Discharge Conveyance Channel _____

8) Reservoir Drain/Outlet - None

Type: Pipe _____ Conduit _____ Other _____

Material: Concrete _____ Metal _____ Other _____

Size: _____ Length _____

Invert Elevations: Entrance _____

Exit _____

Physical Condition (Describe): Unobservable _____

Material: _____

Joints: _____ Alignment _____

Structural Integrity: _____

Hydraulic Capability: _____

Means of Control: Gate _____ Valve _____ Uncontrolled _____

Operation: Operable _____ Inoperable _____ Other _____

Present Condition (Describe): _____

9) Structural - Not Applicable

a. Concrete Surfaces _____

b. Structural Cracking _____

c. Movement - Horizontal & Vertical Alignment (Settlement) _____

d. Junctions with Abutments or Embankments _____

e. Drains - Foundation, Joint, Face _____

f. Water Passages, Conduits, Sluices _____

g. Seepage or Leakage _____

h. Joints - Construction, etc. _____

i. Foundation _____

j. Abutments _____

k. Control Gates _____

l. Approach & Outlet Channels _____

m. Energy Dissipators (Plunge Pool, etc.) _____

n. Intake Structures _____

o. Stability _____

p. Miscellaneous _____

10) Appurtenant Structures (Power House, Lock, Gatehouse, Other)

a. Description and Condition None _____

APPENDIX C

HYDROLOGIC/HYDRAULIC DATA
AND COMPUTATIONS

MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009

Subject WOODWARD DAM S.O. No. _____
APPENDIX C - HYDROLOGIC/HYDRAULIC Sheet No. _____ of _____
ENGINEERING DATA AND COMPUTATIONS Drawing No. _____
Computed by _____ Checked by _____ Date _____

<u>SUBJECT</u>	<u>PAGE</u>
CHECK LIST FOR DAMS	1
DRAINAGE AREA AND CENTROID MAP	5
HYDROLOGIC AND HYDRAULIC DATA	6
WOODWARD DAM - TOP OF DAM PROFILE AND CROSS SECTION	7
GREENLEAF DAM - TOP OF DAM PROFILE AND CROSS SECTION	8
SPILLWAY PROFILE AND CROSS SECTION	9
SPILLWAY DISCHARGE RATING	10
20 IN. PIPE RATING	13
SPILLWAY CAPACITY ANALYSIS	14
HEC-1 COMPUTER ANALYSIS	15

CHECK LIST FOR DAMS
HYDROLOGIC AND HYDRAULIC
ENGINEERING DATA

AREA-CAPACITY DATA:

	<u>Elevation</u> (ft.)	<u>Surface Area</u> (acres)	<u>Storage Capacity</u> (acre-ft.)
1) Top of Dam	<u>769.7</u>	<u>125.4</u>	<u>1633</u>
2) Design High Water (Max. Design Pool)	<u>-</u>	<u>-</u>	<u>-</u>
3) Auxiliary Spillway Crest	<u>-</u>	<u>-</u>	<u>-</u>
4) Pool Level with Flashboards	<u>-</u>	<u>-</u>	<u>-</u>
5) Service Spillway Crest	<u>767.0</u>	<u>100.7</u>	<u>1332</u>

DISCHARGES

	<u>Volume</u> (cfs)
1) Average Daily	<u>Unknown</u>
2) Spillway @ Maximum High Water - Top of Dam - (El. 769.7 ft. M.S.L.)	<u>532</u>
3) Spillway @ Design High Water	<u>Unknown</u>
4) Spillway @ Auxiliary Spillway Crest Elevation	<u>-</u>
5) Low Level Outlet (20 in. C.I.P.)	<u>6</u>
6) Total (of all facilities) @ Maximum High Water	<u>538</u>
7) Maximum Known Flood	<u>Unknown</u>
8) At Time of Inspection	<u>0</u>

CREST:

ELEVATION: 769.7 ft.

Type: Earthfill dam

Width: 9 ft.

Length: 463 ft.

Spillover Low, broad-crested weir

Location 50 ft. from right abutment and 18 ft. upstream from the crest of the dam.

SPILLWAY:

SERVICE		AUXILIARY
<u>767.0 ft.</u>	Elevation	<u>None</u>
<u>Broad-crested weir</u>	Type	<u>-</u>
<u>18.7 ft.</u>	Width	<u>-</u>
	<u>Type of Control</u>	
<u>X</u>	Uncontrolled	<u>-</u>
	Controlled:	
<u>-</u>	Type	<u>-</u>
	(Flashboards; gate)	
<u>-</u>	Number	<u>-</u>
<u>-</u>	Size/Length	<u>-</u>
	Invert Material	<u>-</u>
	Anticipated Length of Operating Service	<u>-</u>
<u>-</u>	Chute Length	<u>-</u>
<u>0.8 ft.</u>	Height Between Spillway Crest & Approach Channel Invert (Weir Flow)	<u>-</u>

HYDROMETEROLOGICAL GAGES:

Type: None

Location: _____

Records:

Date: _____

Max. Reading: _____

FLOOD WATER CONTROL SYSTEM:

Warning System: None

Method of Controlled Releases (mechanisms):

A 20 in. gravity fed water supply line approximately 19,500 ft. long to

Monhagen Lake.

DRAINAGE AREA: 1.50 sq. mi.

DRAINAGE BASIN RUNOFF CHARACTERISTICS:

Land Use - Type: Wooded with light residential development.

Terrain - Relief: Moderate slopes.

Surface - Soil: Well drained.

Runoff Potential (existing or planned extensive alterations to existing surface or subsurface conditions)

There were no known plans for altering the existing runoff patterns at the time of inspection.

Potential Sedimentation problem areas (natural or man-made; present or future)

None observed at the time of inspection.

Potential Backwater problem areas for levels at maximum storage capacity including surcharge storage:

None observed at the time of inspection.

Dikes - Floodwalls (overflow & non-overflow) - Low reaches along the Reservoir perimeter:

Location: None


Elevation: _____

Reservoir:

Length @ Maximum Pool 8,500 ft. (El. 769.7 ft. M.S.L.)

Length of Shoreline (@ Spillway Crest) 20,800 ft. (3.94 mi.)

(El. 767.0 ft. M.S.L.)



QUADS: ① OTISVILLE, N.Y.
 ② MIDDLETOWN, N.Y.

DRAINAGE AREA A = 0.72 SQ. MI.

DRAINAGE AREA B = 0.78 SQ. MI.

DRAINAGE AREA ABOVE
WOODWARD DAM

SCALE: 1 IN. = 2000 FT.

MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009

Subject NEW YORK TRAIL

WOODWARD DAM

S.O. No. _____

Sheet No. 6 of 38

Drawing No. _____

Computed by WLS Checked by _____ Date 1/22/81

WLS

HYDROLOGIC AND HYDRAULIC DATA

TOTAL DRAINAGE AREA ABOVE WOODWARD DAM = 10.45 SQ. MI.
(MEASURED ON OTISVILLE AND MIDDLETOWN, N.Y. QUADS)
= 1.50 SQ. MI.

DRAINAGE AREA BETWEEN WOODWARD DAM AND HIGHLAND LAKE DAM = 0.72 SQ. MI

$$T_p = C_T (L \times L_{CA})^{.3}$$

$$L = 8400 \text{ FT.} = 1.59 \text{ MI}$$

$$C_T = 2.0 \quad C_P = .63$$

$$L_{CA} = 3200 \text{ FT} = 0.61 \text{ MI}$$

$$T_p = 2.0 [(1.59)(.61)]^{.3}$$

SURFACE AREA - ELEVATION (FROM QUAD)

$$T_p = 1.98$$

<u>ELEV.</u> <u>(FT.)</u>	<u>AREA</u> <u>(AC.)</u>
767	100.7
760	218.8

* From Plaque @ Valve house - Capacity 434,024,999 gal. (1332.06 ACF.)

DRAINAGE AREA ABOVE HIGHLAND LAKE DAM = 0.78 SQ. MI

$$L = 6200 \text{ FT} = 1.21 \text{ MI}$$

$$T_p = C_T (L \times L_{CA})^{.3}$$

$$C_P = 0.63 \quad C_T = 2.0$$

$$L_{CA} = 2400 \text{ FT} = 0.45 \text{ MI}$$

$$T_p = 2.0 [(1.21)(0.45)]^{.3}$$

$$= 1.67$$

SURFACE AREA - ELEVATION (FROM QUAD)

<u>ELEV.</u> <u>(FT.)</u>	<u>AREA</u> <u>(AC.)</u>
792	117.5
800	152.4

NOTE. NORMAL POOL OF HIGHLAND LAKE
ASSUMED TO BE AT EL. 792
(AS SHOWN ON PLANS)


MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009


Subject WOODWARD DAM S.O. No. _____
TOP OF DAM PROFILE AND Sheet No. 7 of 38
TYPICAL CROSS SECTION Drawing No. _____
Computed by GWT Checked by WLS Date 1-19-81

TOP OF DAM PROFILE (LOOKING DOWNSTREAM)

LENGTH OF DAM = 463 FT.



TYPICAL CROSS SECTION AT STATION 2+30




MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009


Subject GREENLEAF DAM S.O. No. _____
TOP OF DAM PROFILE AND Sheet No. 8 of 38
TYPICAL CROSS SECTION Drawing No. _____
Computed by GWY Checked by _____ Date 2-12-81

TOP OF DAM PROFILE (LOOKING DOWNSTREAM)

LENGTH OF DAM = 281 FT.



TYPICAL CROSS SECTION AT STATION 1+68



MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009

Subject WOODWARD DAM

S.O. No. _____

SPILLWAY PROFILE AND

Sheet No. 9 of 38

CROSS SECTION


Drawing No. _____

Computed by GWT


Checked by ULS

Date 1-19-81

SPILLWAY CROSS SECTION



SPILLWAY PROFILE



MICHAEL BAKER, JR., INC.

THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009Subject WOODWARD DAM

S.O. No. _____

SPILLWAY DISCHARGE RATINGSheet No. 10 of 38

Drawing No. _____

Computed by GWJ Checked by WLS Date 1-20-81SPILLWAY RATINGDEVELOPE RATING CURVE BASED UPON CRITICAL FLOW OVER
SPILLWAY:

$$V = \sqrt{gD}$$

CHOW, OPEN CHANNEL HYDRAULICS, P. 43

$$g = 32.2 \text{ FT/SEC}^2$$


$$D = \text{MEAN HYDRAULIC DEPTH} = \frac{\text{FLOW AREA}}{\text{TOP WIDTH}} = \frac{A}{T}$$

$$V = \text{MEAN FLOW VELOCITY}$$

$$Q = AV$$

SPILLWAY

ELEVATION, (FT)	FLOW DEPTH, (FT)	AREA, (FT ²)	TOP WIDTH (FT)	A/T	V, FT/SEC	Q, (CFS)	V ^{3/2g}	RESERVOIR ELEV.
767.0	0'	0	18.7	0	0	0	0	777.0
767.5	.5'	9.35	18.7	0.50	4.01	37.52	.25	777.7
768.0	1.0'	18.70	18.7	1.00	5.67	106.03	.50	778.5
768.5	1.5'	28.05	18.7	1.50	6.95	194.95	.75	779.2
769.0	2.0'	37.40	18.7	2.00	8.02	300.13	1.00	780.0
769.5	2.5'	46.75	18.7	2.50	8.97	419.45	1.25	780.7

SPILLWAY DISCHARGE CURVE

MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009

Subject WOODWARD DAM S.O. No. _____
SPILLWAY DISCHARGE RATING Sheet No. 11 of 39
(CONTINUED) Drawing No. _____
Computed by GWT/ALE Checked by _____ Date 1/20/81

RIGHT TRAINING WALL


ELEVATION (FT)	FLOW DEPTH (FT)	AREA (FT ²)	TOPWIDTH (FT)	A/T	V (FT/SEC)	Q (CFS)	V ² /2g	RESERVOIR ELEVATION
767.2	0	0	0	0	0	0	0	777.2
767.5	.3	2.10	14	.15	2.20	4.62	.07	777.57
768.0	.8	9.10	14	.65	4.57	41.63	.32	778.32
768.5	1.3	16.10	14	1.15	6.08	97.97	.57	779.07
769.0	1.8	23.10	14	1.65	7.29	168.38	.82	779.82
769.5	2.3	30.10	14	2.15	8.32	250.44	1.07	780.57



LEFT TRAINING WALL

ELEVATION (FT)	FLOW DEPTH (FT)	AREA (FT ²)	TOPWIDTH (FT)	A/T	V (FT/SEC)	Q (CFS)	V ² /2g	RESERVOIR ELEVATION
767.4	0	0	3.5	0	0	0	0	777.4
767.5	.1	.42	5.0	0.08	1.60	0.67	0.04	777.54
768.0	.6	4.57	9.5	0.48	3.93	17.96	0.24	778.24
768.5	1.1	9.95	12.0	0.83	5.17	51.44	0.42	778.92
769.0	1.6	16.58	14.5	1.14	6.06	100.47	0.57	779.57
769.5	2.1	24.33	16.5	1.47	6.88	167.39	0.74	780.24

SPILLWAY RATING CURVE



MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009

Subject WEDWARD DAM S.O. No. _____
SPILLWAY DISCHARGE RATING Sheet No. 12 of 38
SUMMARY Drawing No. _____
Computed by GWT/HIA Checked by _____ Date 01/20/80

SPILLWAY DISCHARGE SUMMARY

ELEVATION (FT)	SPILLWAY (CFS)	RT. TRAINING WALL (CFS)	LT. TRAINING WALL (CFS)	TOTAL (CFS)
767.0	0	0	0	0
767.5	22.0	6.0	1.0	29.0
768.0	50.0	36.0	10.0	96.0
768.5	106.0	55.0	24.0	185.0
769.0	160.0	97.0	51.0	308.0
769.5	230.0	140.0	95.0	465.0
770.0	300.0	190.0	142.0	632.0

Pipe Flow

$$Q = \frac{A(2gh)^{1/2}}{[1 + K_e + K_b + K_c(L)]^{1/2}}$$

$$= \frac{2.16(2 \times 32.2 \times h)^{1/2}}{[1 + 0.78 + 0.39 + 0.0185(19,500)]^{1/2}}$$

$$= \frac{17.334 h^{1/2}}{19.0505}$$

$$= 0.9099 h^{1/2}$$

Pipe is 20" Dia Cast Iron Pipe

$$A = \pi r^2 = \pi (0.83)^2 = 2.16 \text{ ft}^2$$

$$g = 32.2 \text{ ft/sec}^2$$

h = head measured from the top of Pipe @ outlet (est. @ 712.0 ft.)

$$L = 19,500 \text{ ft.}^*$$

$$K_e = 0.78 \text{ Pg 5.5-6 SCS NEH-5}$$

$$K_b = 0.39(\text{est.})^* \text{Pg 5.5-10 "}$$

$$K_c = 0.0185 \text{ Pg 5.5-4 "}$$

$$"n" = 0.014 \text{ (uncoated Cast Iron Pipe)}$$


	Elev. (ft.)	h (ft.)	Q (cfs)
Invert of Drain	738	26	0
	739	27	4.73
	740	28	4.81
	742	30	4.98
	744	32	5.15
	746	34	5.31
	748	36	5.46
	750	38	5.61
	754	42	5.90
	758	46	6.17
	762	50	6.43
	766	54	6.69
Spillway Crest	767	55	6.75

* Note: The route traveled by the drain pipe is unknown. The outlet was not located in the field. The length and outlet elevation of the pipe are estimated by knowing the approximate area of the outlet (Monhagen Lake - Normal pool elev. 712 ft.) The number and degree of bends in this pipe are unknown. One 90° bend was assumed for use in this rating curve.

MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009

Subject WOODWARD DAM S.O. No. _____
SPILLWAY CAPACITY ANALYSIS Sheet No. 14 of 35
Drawing No. _____
Computed by GWT Checked by _____ Date 2-10-81



SHEET 1- OF 12

HYUGURAPI KUJIAU

RILLI'S SUBAREA A THROUGH HIGHLAND LAKE DAM

[illegible]

ROUTING DATA

ES 15AME 10PT 10MP 10K

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100
101
102
103
104
105
106
107
108
109
110
111
112
113
114
115
116
117
118
119
120
121
122
123
124
125
126
127
128
129
130
131
132
133
134
135
136
137
138
139
140
141
142
143
144
145
146
147
148
149
150
151
152
153
154
155
156
157
158
159
160
161
162
163
164
165
166
167
168
169
170
171
172
173
174
175
176
177
178
179
180
181
182
183
184
185
186
187
188
189
190
191
192
193
194
195
196
197
198
199
200
201
202
203
204
205
206
207
208
209
210
211
212
213
214
215
216
217
218
219
220
221
222
223
224
225
226
227
228
229
230
231
232
233
234
235
236
237
238
239
240
241
242
243
244
245
246
247
248
249
250
251
252
253
254
255
256
257
258
259
260
261
262
263
264
265
266
267
268
269
270
271
272
273
274
275
276
277
278
279
280
281
282
283
284
285
286
287
288
289
290
291
292
293
294
295
296
297
298
299
300
301
302
303
304
305
306
307
308
309
310
311
312
313
314
315
316
317
318
319
320
321
322
323
324
325
326
327
328
329
330
331
332
333
334
335
336
337
338
339
340
341
342
343
344
345
346
347
348
349
350
351
352
353
354
355
356
357
358
359
360
361
362
363
364
365
366
367
368
369
370
371
372
373
374
375
376
377
378
379
380
381
382
383
384
385
386
387
388
389
390
391
392
393
394
395
396
397
398
399
400
401
402
403
404
405
406
407
408
409
410
411
412
413
414
415
416
417
418
419
420
421
422
423
424
425
426
427
428
429
430
431
432
433
434
435
436
437
438
439
440
441
442
443
444
445
446
447
448
449
450
451
452
453
454
455
456
457
458
459
460
461
462
463
464
465
466
467
468
469
470
471
472
473
474
475
476
477
478
479
480
481
482
483
484
485
486
487
488
489
490
491
492
493
494
495
496
497
498
499
500
501
502
503
504
505
506
507
508
509
510
511
512
513
514
515
516
517
518
519
520
521
522
523
524
525
526
527
528
529
530
531
532
533
534
535
536
537
538
539
540
541
542
543
544
545
546
547
548
549
550
551
552
553
554
555
556
557
558
559
560
561
562
563
564
565
566
567
568
569
570
571
572
573
574
575
576
577
578
579
580
581
582
583
584
585
586
587
588
589
590
591
592
593
594
595
596
597
598
599
600
601
602
603
604
605
606
607
608
609
610
611
612
613
614
615
616
617
618
619
620
621
622
623
624
625
626
627
628
629
630
631
632
633
634
635
636
637
638
639
640
641
642
643
644
645
646
647
648
649
650
651
652
653
654
655
656
657
658
659
660
661
662
663
664
665
666
667
668
669
670
671
672
673
674
675
676
677
678
679
680
681
682
683
684
685
686
687
688
689
690
691
692
693
694
695
696
697
698
699
700
701
702
703
704
705
706
707
708
709
710
711
712
713
714
715
716
717
718
719
720
721
722
723
724
725
726
727
728
729
730
731
732
733
734
735
736
737
738
739
740
741
742
743
744
745
746
747
748
749
750
751
752
753
754
755
756
757
758
759
760
761
762
763
764
765
766
767
768
769
770
771
772
773
774
775
776
777
778
779
780
781
782
783
784
785
786
787
788
789
790
791
792
793
794
795
796
797
798
799
800
801
802
803
804
805
806
807
808
809
810
811
812
813
814
815
816
817
818
819
820
821
822
823
824
825
826
827
828
829
830
831
832
833
834
835
836
837
838
839
840
84

AG AM3KK X ION 3LKA 13PKAI

	0	0.0	0.0	-71.	-1
--	---	-----	-----	------	----

4.00	795.00	796.00	191.00
------	--------	--------	--------

[illegible]

2.00 00.471 00.007 00.007

1. The first part of the paper is devoted to the study of the asymptotic behavior of the solutions of the system (1) as $\epsilon \rightarrow 0$. It is shown that the solutions of the system (1) converge to the solutions of the system (2) in the sense of the weak convergence in the space $L^2(\Omega; \mathbb{R}^n)$. The second part of the paper is devoted to the study of the asymptotic behavior of the solutions of the system (1) as $\epsilon \rightarrow 0$. It is shown that the solutions of the system (1) converge to the solutions of the system (2) in the sense of the weak convergence in the space $L^2(\Omega; \mathbb{R}^n)$.

EXP#	CLEVEL	LUPL	CAKED	EXPL
1				
2				
3				
4				
5				
6				
7				
8				
9				
10				
11				
12				
13				
14				
15				
16				
17				
18				
19				
20				
21				
22				
23				
24				
25				
26				
27				
28				
29				
30				
31				
32				
33				
34				
35				
36				
37				
38				
39				
40				
41				
42				
43				
44				
45				
46				
47				
48				
49				
50				
51				
52				
53				
54				
55				
56				
57				
58				
59				
60				
61				
62				
63				
64				
65				
66				
67				
68				
69				
70				
71				
72				
73				
74				
75				
76				
77				
78				
79				
80				
81				
82				
83				
84				
85				
86				
87				
88				
89				
90				
91				
92				
93				
94				
95				
96				
97				
98				
99				
100				

00
00
00
00

UAA1 UATA

7300
CITY OF LOS ANGELES

	7.0	3.1	1.5	4/0.
100	98	96	94	92
200	196	192	188	184
300	292	288	284	280
400	388	384	380	376
500	484	480	476	472
600	580	576	572	568
700	676	672	668	664
800	772	768	764	760
900	868	864	860	856
1000	964	960	956	952

411	• 6007	• 608	• 051	• 165
-----	--------	-------	-------	-------

0.408 0.708 0.008 0.440

.....

1. The first part of the paper discusses the importance of the role of the state in the development of the economy. It argues that the state should play a leading role in the development of the economy, particularly in the areas of infrastructure, education, and health care. The paper also discusses the importance of the role of the private sector in the development of the economy, and the need for a balance between the two.

100

PHOTOGRAPH KUTTING

U RULUSAKU WAM

17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100
101
102
103
104
105
106
107
108
109
110
111
112
113
114
115
116
117
118
119
120
121
122
123
124
125
126
127
128
129
130
131
132
133
134
135
136
137
138
139
140
141
142
143
144
145
146
147
148
149
150
151
152
153
154
155
156
157
158
159
160
161
162
163
164
165
166
167
168
169
170
171
172
173
174
175
176
177
178
179
180
181
182
183
184
185
186
187
188
189
190
191
192
193
194
195
196
197
198
199
200
201
202
203
204
205
206
207
208
209
210
211
212
213
214
215
216
217
218
219
220
221
222
223
224
225
226
227
228
229
230
231
232
233
234
235
236
237
238
239
240
241
242
243
244
245
246
247
248
249
250
251
252
253
254
255
256
257
258
259
260
261
262
263
264
265
266
267
268
269
270
271
272
273
274
275
276
277
278
279
280
281
282
283
284
285
286
287
288
289
290
291
292
293
294
295
296
297
298
299
300
301
302
303
304
305
306
307
308
309
310
311
312
313
314
315
316
317
318
319
320
321
322
323
324
325
326
327
328
329
330
331
332
333
334
335
336
337
338
339
340
341
342
343
344
345
346
347
348
349
350
351
352
353
354
355
356
357
358
359
360
361
362
363
364
365
366
367
368
369
370
371
372
373
374
375
376
377
378
379
380
381
382
383
384
385
386
387
388
389
390
391
392
393
394
395
396
397
398
399
400
401
402
403
404
405
406
407
408
409
410
411
412
413
414
415
416
417
418
419
420
421
422
423
424
425
426
427
428
429
430
431
432
433
434
435
436
437
438
439
440
441
442
443
444
445
446
447
448
449
450
451
452
453
454
455
456
457
458
459
460
461
462
463
464
465
466
467
468
469
470
471
472
473
474
475
476
477
478
479
480
481
482
483
484
485
486
487
488
489
490
491
492
493
494
495
496
497
498
499
500
501
502
503
504
505
506
507
508
509
510
511
512
513
514
515
516
517
518
519
520
521
522
523
524
525
526
527
528
529
530
531
532
533
534
535
536
537
538
539
540
541
542
543
544
545
546
547
548
549
550
551
552
553
554
555
556
557
558
559
560
561
562
563
564
565
566
567
568
569
570
571
572
573
574
575
576
577
578
579
580
581
582
583
584
585
586
587
588
589
590
591
592
593
594
595
596
597
598
599
600
601
602
603
604
605
606
607
608
609
610
611
612
613
614
615
616
617
618
619
620
621
622
623
624
625
626
627
628
629
630
631
632
633
634
635
636
637
638
639
640
641
642
643
644
645
646
647
648
649
650
651
652
653
654
655
656
657
658
659
660
661
662
663
664
665
666
667
668
669
670
671
672
673
674
675
676
677
678
679
680
681
682
683
684
685
686
687
688
689
690
691
692
693
694
695
696
697
698
699
700
701
702
703
704
705
706
707
708
709
710
711
712
713
714
715
716
717
718
719
720
721
722
723
724
725
726
727
728
729
730
731
732
733
734
735
736
737
738
739
740
741
742
743
744
745
746
747
748
749
750
751
752
753
754
755
756
757
758
759
760
761
762
763
764
765
766
767
768
769
770
771
772
773
774
775
776
777
778
779
780
781
782
783
784
785
786
787
788
789
790
791
792
793
794
795
796
797
798
799
800
801
802
803
804
805
806
807
808
809
810
811
812
813
814
815
816
817
818
819
820
821
822
823
824
825
826
827
828
829
830
831
832
833
834
835
836
837
838
839
840
841
842
843
844
845
846
847
848
849
850
851
85

UNIT HYDROGRAPH DATA
IP= 1.07 1750.03 NIM= 0

RELATION DATA
STAGE= -1.50 WLSN= -0.05 RILN= 2.00

UNIT HYDROGRAPH 27 END-OF-PERIOD UNRAILED, LAG= 1.00 HOURS, LVE= 0.00 VOL= 1.00
14. 101. 147. 174. 199. 119. 92. 15.
63. 38. 30. 24. 19. 12. 10. 8.
6. 4. 3. 2. 2. 2. 2. 2.

40.0A H2.44 PERIOD LAIN EXCS LUSS CUMP W END-OF-PERIOD FLOW MU.0A H2.44 PERIOD KAIN LALS LUSS CUMP W
SUM 44.00 20.57 3.71 29.38.
(012.11 517.11 74.11 824.581

***** ***** ***** *****

COMBINE HYDROGRAPHS

COMBINED HYDROGRAPHS FOR SUBAREAS A AND B

1STA	ICUM	TECUN	ITAPE	JPLT	JPRI	INAME	ISTAGE	IACTU
5	2	0	0	0	0	1	0	0

***** ***** ***** *****

HYDROGRAPH ROUTING

ROUTING FOR WOODWARD DAM

1STA	ICUM	TECUN	ITAPE	JPLT	JPRI	INAME	ISTAGE	IACTU
6	1	0	0	0	0	1	0	0

ROUTING DATA
JLUS 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0
CROSS 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0
AVG 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0
INES 1 1 1 1 1 1 1 1 1
ISML 1 1 1 1 1 1 1 1 1
IPAP 1 1 1 1 1 1 1 1 1
LSPK 1 1 1 1 1 1 1 1 1

LAU AMSKK X ISK 310KA 1SPRAI
0 0 0.0 0.0 0.0 -101. -1

STAGE 167.00 168.00 169.00 169.50 169.50 169.50 169.50 169.50 169.50

FLOW 0.0 23.00 96.00 185.00 308.00 465.00 632.00

SURFACE AREA= 8. 101. 215.

CAPACITY= 0. 1332. 3364.

ELEVATION= 738. 767. 780.

CRCL SPALU CUMW EXPN ELLVL LUL UNKLA CAPL
127.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0

UAM DATA
TUPEL CUAD EXPU UNAMLU
169.7 3.1 1.5 74.

CREST LENGTH 0. 23. 69. 78. 239. 401. 590. 761. 820. 910.

110.0

110.0

112.0

111.8

111.6

111.4

111.3

111.0

110.0

109.1

108.4

107.5

106.6

PEAK OUTFLOW IS 108.4 AT TIME 11.41E 11.67 HOURS

PEAK OUTFLOW IS 725. AT TIME 11.41E 11.00 HOURS

PEAK OUTFLOW IS 422. AT TIME 11.41E 11.00 HOURS

PEAK OUTFLOW IS 157. AT TIME 11.41E 11.00 HOURS

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO LOGARITHMIC COMPUTATIONS
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

RATIOS APPLIED TO FLOWS

OPERATION	STATION	AREA	PLAN	RATIO 1 1.00	RATIO 2 0.75	RATIO 3 0.50	RATIO 4 0.25
HYDROGRAPH AT	1	0.75 2.021	1	1057.	1392.	529.	409.
				52.5311	37.4511	26.3011	13.1511
ROUTED TO	2	0.75 2.021	1	357.	213.	121.	51.
				11.2411	6.0411	3.4111	1.4411
ROUTED TO	3	0.75 2.021	1	357.	213.	121.	51.
				11.2511	6.0411	3.4111	1.4411
HYDROGRAPH AT	4	0.72 1.801	1	1867.	1400.	933.	467.
				52.8611	39.6311	26.4311	13.2211
2 COMBINED	5	1.20 3.881	1	1987.	1481.	983.	484.
				56.2611	41.9511	27.8311	13.7111
ROUTED TO	6	1.20 3.881	1	1084.	725.	422.	157.
				30.7111	20.5211	11.9411	4.4311

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1 HIGHWAY LAKE DAM

ELEVATION
STORAGE
OUTFLOW

INITIAL VALUE
192.00
392.
0.

SPILLWAY CREST
191.00
1032.
200.

TOP OF DAM
191.00
1032.
200.

RATIO OF PMF	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
1.00	0.20	1000.	371.	4.00	45.01	0.0
0.75	0.0	937.	213.	0.0	40.53	0.0
0.50	0.0	744.	121.	0.0	40.07	0.0
0.25	0.0	512.	51.	0.0	47.00	0.0

PLAN 1 STATION 3

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
1.00	397.	177.1	45.01
0.75	213.	170.0	40.53
0.50	121.	176.4	40.07
0.25	51.	176.2	47.00

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1 *WEEPWARR Dam*

RATE OF PMF	MAXIMUM RESERVOIR ELEVATION "S.S. LEVEL"	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-PI	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
1.00	770.98	1.28	1795.	1034.	9.07	43.07	6.0
0.75	770.23	0.53	1639.	725.	5.07	44.00	0.0
0.50	769.36	0.0	1592.	422.	0.0	44.00	0.0
0.25	768.34	0.0	1475.	157.	0.0	44.07	6.0

INITIAL VALUE	SPILLWAY CALCD	TOP OF DAM
767.00	767.00	769.70
1332.	1332.	1033.
0.	0.	936.

5218 3761A-277

A1 NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS
A2 HYDROLOGIC AND HYDRAULIC ANALYSIS OF MODERN DAM
A3 DESIGNING ANALYSIS OF AGEWARD DAM

ATIONAL PROGRAM FOR INSPECTION OF
HYDROLOGIC AND HYDRAULIC ANALYSIS OF
DRAINING ANALYSIS OF AGRICULTURAL DAM

[illegible]

KI JUL KJUUFF HYDROGRAPH IC CAM
M -1 1.00 1.

0001 0001

1

SHEET 25 OF 38

28

K	1		2		1		1	
	K1		JLWATERING - GUARDIAN LAM		1		1	
51	Y							
52	Y1		1					
53	Y4		139.0		146.0		-101.0	
54	Y4		102.0		107.0		-1	
55	Y5		4.81		4.98		124.0	
56	Y5		0.01		0.01		120.0	
57	Y5		0.01		0.01		0.11	
58	SA		8.00		218.8			
59	SE		1.01		780			
60	SS		767.0					
61	SD		109.7		1.5		744	
62	K							
63								

RUN DATE 02/11/81
 TIME 11.10

NATIONAL PROGRAM FOR INSPECTION OF NON-FLEXURAL DAMS
HYDROLOGIC AND HYDRAULIC ANALYSES OF SUBURBAN DAM
GENERAL TO ANALYSIS OF MOUNTAIN DAM

JUD. SPELLEALIAN.

NO	DATE	NAME	DAY	HR	TIME	PRICE	PLT	APPL	NOTAN
400	3	0	0	0	0	0	0	0	0
			JUPER	NOI	LRUP	FRAGE	0	0	0
			3	0	0	0	0	0	0

MULTI-PLAN ANALYSES TO BE PERFORMED
NPLAN= 1 NKIU= 1 LKIU= 1

$$RIL_{ij} = 1.20$$

姓名	性别	年龄	职业	住址	联系电话	电子邮箱	身份证号	银行卡号	支付宝账号	微信账号	其他联系方式
张三	男	35	教师	北京市海淀区中关村大街100号	13800138000	zhangsan@163.com	110101199001010001	6228480100001000100010	15888888888	zhangsan123	15888888888
李四	女	28	程序员	北京市朝阳区望京SOHO塔楼1001室	13900139000	lisi@163.com	110105199205050002	6228480100001000100010	15888888888	lisi456	15888888888
王五	男	42	医生	上海市浦东新区世纪大道100号	13600136000	wangwu@163.com	310101195001010001	6228480100001000100010	15888888888	wangwu789	15888888888
赵六	女	30	设计师	深圳市福田区华强北路100号	13700137000	zhaoliu@163.com	440101199001010001	6228480100001000100010	15888888888	zhaoliu123	15888888888
孙七	男	38	工程师	广州市天河区珠江新城100号	13500135000	sunqi@163.com	440101196001010001	6228480100001000100010	15888888888	sunqi456	15888888888
周八	女	25	销售	深圳市南山区科技园100号	13400134000	zhouba@163.com	440101199501010001	6228480100001000100010	15888888888	zhouba789	15888888888
吴九	男	45	会计师	北京市西城区金融大街100号	13200132000	wujiu@163.com	110101195001010001	6228480100001000100010	15888888888	wujiu123	15888888888
郑十	女	32	律师	上海市浦东新区世纪大道100号	13100131000	zhengshi@163.com	310101196001010001	6228480100001000100010	15888888888	zhengshi456	15888888888
冯十一	男	29	产品经理	北京市海淀区中关村大街100号	13000130000	fengshi1@163.com	110101199001010001	6228480100001000100010	15888888888	fengshi1789	15888888888
陈十二	女	27	运营	北京市朝阳区望京SOHO塔楼1001室	12900129000	chenshi2@163.com	110105199205050002	6228480100001000100010	15888888888	chenshi2123	15888888888
林十三	男	40	项目经理	深圳市福田区华强北路100号	12800128000	linshi3@163.com	440101195001010001	6228480100001000100010	15888888888	linshi3456	15888888888
周十四	女	33	市场专员	广州市天河区珠江新城100号	12700127000	zhoushi4@163.com	440101196001010001	6228480100001000100010	15888888888	zhoushi4789	15888888888
吴十五	男	36	数据分析师	深圳市南山区科技园100号	12600126000	wushi5@163.com	440101196001010001	6228480100001000100010	15888888888	wushi5123	15888888888
郑十六	女	26	人力资源	北京市西城区金融大街100号	12500125000	zhengshi6@163.com	110101199001010001	6228480100001000100010	15888888888	zhengshi6456	15888888888
冯十七	男	41	财务总监	上海市浦东新区世纪大道100号	12400124000	fengshi7@163.com	310101195001010001	6228480100001000100010	15888888888	fengshi7789	15888888888
陈十八	女	31	产品经理	北京市海淀区中关村大街100号	12300123000	chenshi8@163.com	110101199001010001	6228480100001000100010	15888888888	chenshi8123	15888888888
林十九	男	28	运营	北京市朝阳区望京SOHO塔楼1001室	12200122000	linshi9@163.com	110105199205050002	6228480100001000100010	15888888888	linshi9456	15888888888
周二十	女	34	市场专员	深圳市福田区华强北路100号	12100121000	zhoushi0@163.com	440101196001010001	6228480100001000100010	15888888888	zhoushi0789	15888888888
吴二十一	男	37	数据分析师	广州市天河区珠江新城100号	12000120000	wushi1@163.com	440101196001010001	6228480100001000100010	15888888888	wushi1123	15888888888
郑二十二	女	29	人力资源	深圳市南山区科技园100号	11900119000	zhengshi2@163.com	440101199001010001	6228480100001000100010	15888888888	zhengshi2456	15888888888
冯二十三	男	43	财务总监	北京市西城区金融大街100号	11800118000	fengshi3@163.com	110101195001010001	6228480100001000100010	15888888888	fengshi3789	15888888888
陈二十四	女	30	产品经理	上海市浦东新区世纪大道100号	11700117000	chenshi4@163.com	310101196001010001	6228480100001000100010	15888888888	chenshi4123	15888888888
林二十五	男	27									

SUB-AREA KULTUR: COMPUTALUD.

INJUL 6JHUFF HYURUGRAPH TU JAM

	JCLAD	JCOMP	JECUN	JTAPE	JPLT	JPKI	JNAME	JSAUL	JAUIG
--	-------	-------	-------	-------	------	------	-------	-------	-------

HYDRO	ISING	TAREA	SNAPP	INSDA	TRISPL	KAT10	ISINON	ISAME	LOCAL
-1	0	1-20	0-0	1-20	0-0	0-0	0	1	0

IHSU

1.03	16.00	8	04.00	0.	7.	1290.	700.0
1.04	0.0	9	12.00	0.	7.	1292.	700.0
1.04	3.00	10	80.00	0.	7.	1296.	700.0
1.04	16.00	11	80.00	0.	7.	1293.	700.5
1.05	0.0	12	90.00	0.	7.	1294.	700.5
1.05	8.00	13	10.00	0.	7.	1294.	700.5
1.05	16.00	14	112.00	0.	7.	1290.	700.4
1.06	0.0	15	120.00	0.	7.	1292.	700.5
1.06	8.00	16	120.00	0.	7.	1261.	700.3
1.06	16.00	17	136.00	0.	7.	1290.	700.2
1.07	0.0	18	144.00	0.	7.	1292.	700.2
1.07	8.00	19	152.00	0.	7.	1290.	700.1
1.07	16.00	20	160.00	0.	7.	1243.	700.1
1.08	0.0	21	168.00	0.	7.	1239.	700.1
1.08	8.00	22	170.00	0.	7.	1239.	700.0
1.08	16.00	23	184.00	0.	7.	1230.	700.0
1.09	0.0	24	192.00	0.	7.	1225.	700.5
1.09	8.00	25	200.00	0.	7.	1221.	700.5
1.09	16.00	26	200.00	0.	7.	1210.	700.0
1.10	0.0	27	216.00	0.	7.	1212.	700.0
1.10	8.00	28	224.00	0.	7.	1208.	700.1
1.10	16.00	29	232.00	0.	7.	1203.	700.1
1.11	0.0	30	240.00	0.	7.	1192.	700.0
1.11	8.00	31	248.00	0.	7.	1191.	700.0
1.11	16.00	32	256.00	0.	7.	1190.	700.5
1.12	0.0	33	264.00	0.	7.	1189.	700.5
1.12	8.00	34	272.00	0.	7.	1181.	700.5
1.12	16.00	35	280.00	0.	7.	1177.	700.4
1.13	0.0	36	288.00	0.	7.	1172.	700.4
1.13	8.00	37	296.00	0.	7.	1168.	700.5
1.13	16.00	38	304.00	0.	7.	1159.	700.5
1.14	0.0	39	312.00	0.	7.	1159.	700.2
1.14	8.00	40	320.00	0.	7.	1150.	700.2
1.14	16.00	41	328.00	0.	7.	1150.	700.1
1.15	0.0	42	330.00	0.	7.	1140.	700.1
1.15	8.00	43	344.00	0.	7.	1142.	700.0
1.15	16.00	44	352.00	0.	7.	1137.	700.0
1.16	0.0	45	360.00	0.	7.	1133.	700.9
1.16	8.00	46	368.00	0.	7.	1128.	700.9
1.16	16.00	47	376.00	0.	7.	1129.	700.8
1.17	0.0	48	384.00	0.	7.	1120.	700.8
1.17	8.00	49	392.00	0.	7.	1115.	700.7
1.17	16.00	50	400.00	0.	7.	1111.	700.7
1.18	0.0	51	408.00	0.	7.	1107.	700.6
1.18	8.00	52	416.00	0.	7.	1102.	700.6
1.18	16.00	53	424.00	0.	7.	1098.	700.5
1.19	0.0	54	432.00	0.	7.	1093.	700.5
1.19	8.00	55	440.00	0.	7.	1089.	700.4
1.19	16.00	56	448.00	0.	7.	1080.	700.4
1.20	0.0	57	456.00	0.	7.	1080.	700.5
1.20	8.00	58	464.00	0.	7.	1070.	700.5
1.20	16.00	59	472.00	0.	7.	1072.	700.2
1.21	0.0	60	480.00	0.	7.	1067.	700.2
1.21	8.00	61	488.00	0.	7.	1063.	700.1
1.21	16.00	62	496.00	0.	7.	1059.	700.1
1.22	0.0	63	504.00	0.	7.	1059.	700.0
1.22	8.00	64	512.00	0.	7.	1050.	700.0
1.22	16.00	65	520.00	0.	7.	1040.	700.9
1.23	0.0	66	528.00	0.	7.	1041.	700.9
1.23	8.00	67	536.00	0.	7.	1037.	700.8
1.23	16.00	68	544.00	0.	7.	1033.	700.8
1.24	0.0	69	552.00	0.	7.	1028.	700.7
1.24	8.00	70	560.00	0.	7.	1029.	700.7
1.24	16.00	71	568.00	0.	7.	1020.	700.0
1.25	0.0	72	576.00	0.	7.	1019.	700.0
1.25	8.00	73	584.00	0.	7.	1011.	700.5

1.25	16.00	74	552.00	U.	U.	100.0	103.2
1.26	0.0	75	600.00	U.	U.	100.0	103.4
1.26	8.00	76	608.00	U.	U.	170.	103.4
1.26	16.00	77	616.00	U.	U.	174.	103.3
1.27	0.0	78	624.00	U.	U.	109.	103.3
1.27	8.00	79	632.00	U.	U.	103.	103.2
1.27	16.00	80	640.00	U.	U.	101.	103.2
1.28	0.0	81	648.00	U.	U.	170.	103.1
1.28	8.00	82	656.00	U.	U.	112.	103.1
1.28	16.00	83	664.00	U.	U.	100.	103.0
1.29	0.0	84	672.00	U.	U.	904.	103.0
1.29	8.00	85	680.00	U.	U.	551.	102.9
1.29	16.00	86	688.00	U.	U.	922.	102.9
1.30	0.0	87	696.00	U.	U.	931.	102.8
1.30	8.00	88	704.00	U.	U.	140.	102.8
1.30	16.00	89	712.00	U.	U.	142.	102.7
1.31	0.0	90	720.00	U.	U.	130.	102.7
1.31	8.00	91	728.00	U.	U.	133.	102.6
1.31	16.00	92	736.00	U.	U.	127.	102.5
2.01	0.0	93	744.00	U.	U.	127.	102.5
2.01	8.00	94	752.00	U.	U.	124.	102.4
2.01	16.00	95	760.00	U.	U.	110.	102.4
2.02	0.0	96	768.00	U.	U.	912.	102.3
2.02	8.00	97	776.00	U.	U.	100.	102.3
2.02	16.00	98	784.00	U.	U.	904.	102.2
2.03	0.0	99	792.00	U.	U.	897.	102.2
2.03	8.00	100	800.00	U.	U.	891.	102.1
2.03	16.00	101	808.00	U.	U.	881.	102.0
2.04	0.0	102	816.00	U.	U.	882.	102.0
2.04	8.00	103	824.00	U.	U.	370.	101.9
2.05	0.0	104	832.00	U.	U.	874.	101.8
2.05	8.00	105	840.00	U.	U.	870.	101.8
2.05	16.00	106	848.00	U.	U.	862.	101.7
2.06	0.0	107	856.00	U.	U.	361.	101.7
2.06	8.00	108	864.00	U.	U.	357.	101.6
2.06	16.00	109	872.00	U.	U.	353.	101.5
2.07	0.0	110	880.00	U.	U.	348.	101.5
2.07	8.00	111	888.00	U.	U.	342.	101.4
2.07	16.00	112	896.00	U.	U.	340.	101.4
2.08	0.0	113	904.00	U.	U.	330.	101.3
2.08	8.00	114	912.00	U.	U.	314.	101.3
2.08	16.00	115	920.00	U.	U.	327.	101.2
2.09	0.0	116	928.00	U.	U.	323.	101.2
2.09	8.00	117	936.00	U.	U.	312.	101.1
2.09	16.00	118	944.00	U.	U.	310.	101.1
2.10	0.0	119	952.00	U.	U.	302.	101.0
2.10	8.00	120	960.00	U.	U.	300.	100.9
2.10	16.00	121	968.00	U.	U.	302.	100.9
2.11	0.0	122	976.00	U.	U.	170.	100.8
2.11	8.00	123	984.00	U.	U.	153.	100.8
2.11	16.00	124	992.00	U.	U.	189.	100.7
2.12	0.0	125	1000.00	U.	U.	182.	100.7
2.12	8.00	126	1008.00	U.	U.	181.	100.6
2.12	16.00	127	1016.00	U.	U.	177.	100.5
2.13	0.0	128	1024.00	U.	U.	176.	100.5
2.13	8.00	129	1032.00	U.	U.	100.	100.4
2.13	16.00	130	1040.00	U.	U.	104.	100.4
2.14	0.0	131	1048.00	U.	U.	103.	100.3
2.14	8.00	132	1056.00	U.	U.	100.	100.2
2.14	16.00	133	1064.00	U.	U.	102.	100.2
2.15	0.0	134	1072.00	U.	U.	102.	100.1
2.15	8.00	135	1080.00	U.	U.	101.	100.1
2.15	16.00	136	1088.00	U.	U.	103.	100.0
2.16	0.0	137	1096.00	U.	U.	103.	100.0
2.16	8.00	138	1104.00	U.	U.	103.	100.0

2.19	16.00	1401120.00	0.	0.	121.	159.8
2.17	0.0	1411128.00	0.	0.	122.	159.8
2.17	8.00	1421130.00	0.	0.	123.	159.7
2.17	16.00	1431144.00	0.	0.	124.	159.6
2.18	0.0	1441152.00	0.	0.	125.	159.6
2.18	8.00	1451160.00	0.	0.	126.	159.5
2.18	16.00	1461168.00	0.	0.	127.	159.4
2.19	0.0	1471176.00	0.	0.	128.	159.4
2.19	8.00	1481184.00	0.	0.	129.	159.3
2.19	16.00	1491192.00	0.	0.	130.	159.3
2.20	0.0	1501200.00	0.	0.	131.	159.2
2.20	8.00	1511208.00	0.	0.	132.	159.1
2.20	16.00	1521216.00	0.	0.	133.	159.1
2.21	0.0	1531224.00	0.	0.	134.	159.0
2.21	8.00	1541232.00	0.	0.	135.	158.9
2.21	16.00	1551240.00	0.	0.	136.	158.8
2.22	0.0	1561248.00	0.	0.	137.	158.8
2.22	8.00	1571256.00	0.	0.	138.	158.7
2.22	16.00	1581264.00	0.	0.	139.	158.6
2.23	0.0	1591272.00	0.	0.	140.	158.6
2.23	8.00	1601280.00	0.	0.	141.	158.5
2.23	16.00	1611288.00	0.	0.	142.	158.4
2.24	0.0	1621296.00	0.	0.	143.	158.4
2.24	8.00	1631304.00	0.	0.	144.	158.3
2.24	16.00	1641312.00	0.	0.	145.	158.3
2.25	0.0	1651320.00	0.	0.	146.	158.2
2.25	8.00	1661328.00	0.	0.	147.	158.2
2.25	16.00	1671336.00	0.	0.	148.	158.1
2.26	0.0	1681344.00	0.	0.	149.	158.0
2.26	8.00	1691352.00	0.	0.	150.	158.0
2.26	16.00	1701360.00	0.	0.	151.	157.9
2.27	0.0	1711368.00	0.	0.	152.	157.8
2.27	8.00	1721376.00	0.	0.	153.	157.8
2.27	16.00	1731384.00	0.	0.	154.	157.7
2.28	0.0	1741392.00	0.	0.	155.	157.6
2.28	8.00	1751400.00	0.	0.	156.	157.6
2.28	16.00	1761408.00	0.	0.	157.	157.5
2.29	0.0	1771416.00	0.	0.	158.	157.4
2.29	8.00	1781424.00	0.	0.	159.	157.4
2.29	16.00	1791432.00	0.	0.	160.	157.3
3.01	0.0	1801440.00	0.	0.	161.	157.2
3.01	8.00	1811448.00	0.	0.	162.	157.2
3.01	16.00	1821456.00	0.	0.	163.	157.1
3.02	0.0	1831464.00	0.	0.	164.	157.1
3.02	8.00	1841472.00	0.	0.	165.	157.0
3.02	16.00	1851480.00	0.	0.	166.	156.9
3.03	0.0	1861488.00	0.	0.	167.	156.8
3.03	8.00	1871496.00	0.	0.	168.	156.7
3.03	16.00	1881504.00	0.	0.	169.	156.7
3.04	0.0	1891512.00	0.	0.	170.	156.6
3.04	8.00	1901520.00	0.	0.	171.	156.5
3.04	16.00	1911528.00	0.	0.	172.	156.4
3.05	0.0	1921536.00	0.	0.	173.	156.4
3.05	8.00	1931544.00	0.	0.	174.	156.3
3.05	16.00	1941552.00	0.	0.	175.	156.2
3.06	0.0	1951560.00	0.	0.	176.	156.2
3.06	8.00	1961568.00	0.	0.	177.	156.1
3.06	16.00	1971576.00	0.	0.	178.	156.0
3.07	0.0	1981584.00	0.	0.	179.	155.9
3.07	8.00	1991592.00	0.	0.	180.	155.8
3.07	16.00	2001600.00	0.	0.	181.	155.8
3.08	0.0	2011608.00	0.	0.	182.	155.7
3.08	8.00	2021616.00	0.	0.	183.	155.6
3.08	16.00	2031624.00	0.	0.	184.	155.5
3.09	0.0	2041632.00	0.	0.	185.	155.5

3.09	16.00	2001690.00	0.	0.	100.	100.3
3.10	0.0	2011670.00	0.	0.	100.	100.2
3.10	8.00	2001600.00	0.	0.	100.	100.2
3.10	16.00	2001672.00	0.	0.	100.	100.1
3.11	0.0	2101680.00	0.	0.	100.	100.0
3.11	8.00	2111688.00	0.	0.	100.	100.0
3.11	16.00	2121690.00	0.	0.	100.	100.8
3.12	0.0	2131700.00	0.	0.	100.	100.8
3.12	8.00	2141712.00	0.	0.	100.	100.1
3.12	16.00	2151720.00	0.	0.	100.	100.0
3.13	0.0	2161728.00	0.	0.	100.	100.0
3.13	8.00	2171736.00	0.	0.	100.	100.4
3.13	16.00	2181740.00	0.	0.	100.	100.4
3.14	0.0	2191752.00	0.	0.	100.	100.3
3.14	8.00	2201760.00	0.	0.	100.	100.2
3.14	16.00	2211768.00	0.	0.	100.	100.1
3.15	0.0	2221776.00	0.	0.	100.	100.0
3.15	8.00	2231784.00	0.	0.	100.	100.5
3.15	16.00	2241792.00	0.	0.	100.	100.5
3.16	0.0	2251800.00	0.	0.	100.	100.0
3.16	8.00	2261808.00	0.	0.	100.	100.1
3.16	16.00	2271816.00	0.	0.	100.	100.0
3.17	0.0	2281824.00	0.	0.	100.	100.0
3.17	8.00	2291832.00	0.	0.	100.	100.4
3.17	16.00	2301840.00	0.	0.	100.	100.3
3.18	0.0	2311848.00	0.	0.	100.	100.3
3.18	8.00	2321856.00	0.	0.	100.	100.3
3.18	16.00	2331864.00	0.	0.	100.	100.1
3.19	0.0	2341872.00	0.	0.	100.	100.0
3.19	8.00	2351880.00	0.	0.	100.	100.5
3.19	16.00	2361888.00	0.	0.	100.	100.0
3.20	0.0	2371896.00	0.	0.	100.	100.1
3.20	8.00	2381904.00	0.	0.	100.	100.0
3.20	16.00	2391912.00	0.	0.	100.	100.0
3.21	0.0	2401920.00	0.	0.	100.	100.4
3.21	8.00	2411928.00	0.	0.	100.	100.4
3.21	16.00	2421936.00	0.	0.	100.	100.3
3.22	0.0	2431944.00	0.	0.	100.	100.2
3.22	8.00	2441952.00	0.	0.	100.	100.1
3.22	16.00	2451960.00	0.	0.	100.	100.0
3.23	0.0	2461968.00	0.	0.	100.	100.5
3.23	8.00	2471976.00	0.	0.	100.	100.0
3.23	16.00	2481984.00	0.	0.	100.	100.1
3.24	0.0	2491992.00	0.	0.	100.	100.0
3.24	8.00	2502000.00	0.	0.	100.	100.0
3.24	16.00	2512008.00	0.	0.	100.	100.4
3.25	0.0	2522016.00	0.	0.	100.	100.3
3.25	8.00	2532024.00	0.	0.	100.	100.2
3.25	16.00	2542032.00	0.	0.	100.	100.1
3.26	0.0	2552040.00	0.	0.	100.	100.0
3.26	8.00	2562048.00	0.	0.	100.	100.5
3.26	16.00	2572056.00	0.	0.	100.	100.8
3.27	0.0	2582064.00	0.	0.	100.	100.1
3.27	8.00	2592072.00	0.	0.	100.	100.0
3.27	16.00	2602080.00	0.	0.	100.	100.5
3.28	0.0	2612088.00	0.	0.	100.	100.4
3.28	8.00	2622096.00	0.	0.	100.	100.3
3.28	16.00	2632104.00	0.	0.	100.	100.2
3.29	0.0	2642112.00	0.	0.	100.	100.0
3.29	8.00	2652120.00	0.	0.	100.	100.5
3.29	16.00	2662128.00	0.	0.	100.	100.8
3.30	0.0	2672136.00	0.	0.	100.	100.1
3.30	8.00	2682144.00	0.	0.	100.	100.0
3.30	16.00	2692152.00	0.	0.	100.	100.5
3.31	0.0	2702160.00	0.	0.	100.	100.4

4.01	16.00	2122110.00	0.	0.	200.	145.1
4.01	0.0	2132104.00	0.	0.	202.	145.0
4.01	0.00	2142152.00	0.	0.	171.	140.5
4.01	16.00	2152200.00	0.	0.	175.	140.0
4.02	0.0	2162208.00	0.	0.	191.	140.1
4.02	0.00	2172210.00	0.	0.	188.	140.0
4.02	16.00	2182224.00	0.	0.	184.	140.4
4.03	0.0	2192232.00	0.	0.	180.	140.3
4.03	0.00	2202240.00	0.	0.	177.	140.2
4.03	16.00	2212248.00	0.	0.	173.	140.1
4.04	0.0	2222256.00	0.	0.	170.	141.5
4.04	0.00	2232264.00	0.	0.	168.	141.0
4.04	16.00	2242272.00	0.	0.	162.	141.1
4.05	0.0	2252280.00	0.	0.	159.	141.5
4.05	8.00	2262288.00	0.	0.	157.	141.4
4.05	16.00	2272296.00	0.	0.	152.	141.3
4.06	0.0	2282304.00	0.	0.	140.	141.1
4.06	8.00	2292312.00	0.	0.	138.	141.6
4.07	0.0	2302320.00	0.	0.	141.	140.5
4.07	0.0	2312328.00	0.	0.	137.	140.1
4.07	8.00	2322336.00	0.	0.	134.	140.0
4.07	16.00	2332344.00	0.	0.	130.	140.4
4.08	0.0	2342352.00	0.	0.	127.	140.3
4.08	8.00	2352360.00	0.	0.	123.	140.1
4.08	16.00	2362368.00	0.	0.	120.	140.0
4.09	0.0	2372376.00	0.	0.	110.	140.0
4.09	8.00	2382384.00	0.	0.	113.	140.1
4.09	16.00	2392392.00	0.	0.	109.	140.5
4.10	0.0	2402400.00	0.	0.	106.	140.4
4.10	8.00	2412408.00	0.	0.	102.	140.6
4.10	16.00	2422416.00	0.	0.	99.	140.0
4.11	0.0	2432424.00	0.	0.	95.	144.9
4.11	8.00	2442432.00	0.	0.	92.	144.1
4.11	16.00	2452440.00	0.	0.	88.	144.5
4.12	0.0	2462448.00	0.	0.	85.	144.4
4.12	8.00	2472456.00	0.	0.	82.	144.2
4.12	16.00	2482464.00	0.	0.	78.	144.0
4.13	0.0	2492472.00	0.	0.	75.	143.8
4.13	8.00	2502480.00	0.	0.	71.	143.0
4.13	16.00	2512488.00	0.	0.	68.	143.4
4.14	0.0	2522496.00	0.	0.	65.	143.2
4.14	8.00	2532504.00	0.	0.	61.	143.0
4.14	16.00	2542512.00	0.	0.	58.	142.8
4.15	0.0	2552520.00	0.	0.	55.	142.6
4.15	8.00	2562528.00	0.	0.	51.	142.4
4.15	16.00	2572536.00	0.	0.	48.	142.2
4.16	0.0	2582544.00	0.	0.	45.	142.0
4.16	8.00	2592552.00	0.	0.	41.	141.8
4.16	16.00	2602560.00	0.	0.	38.	141.5
4.17	0.0	2612568.00	0.	0.	35.	141.3
4.17	8.00	2622576.00	0.	0.	32.	141.0
4.17	16.00	2632584.00	0.	0.	28.	140.8
4.18	0.0	2642592.00	0.	0.	25.	140.5
4.18	8.00	2652600.00	0.	0.	22.	140.2
4.18	16.00	2662608.00	0.	0.	19.	140.0
4.19	0.0	2672616.00	0.	0.	16.	139.1
4.19	8.00	2682624.00	0.	0.	13.	139.4
4.19	16.00	2692632.00	0.	0.	9.	139.6
4.20	0.0	2702640.00	0.	0.	6.	130.8
4.20	8.00	2712648.00	0.	0.	3.	130.5
4.20	16.00	2722656.00	0.	0.	1.	130.4
4.21	0.0	2732664.00	0.	0.	1.	130.3
4.21	8.00	2742672.00	0.	0.	1.	130.2
4.21	16.00	2752680.00	0.	0.	1.	130.1
4.22	0.0	2762688.00	0.	0.	1.	130.1

4.22	16.00	3302704.00	U.	U.	U.	U.	130.0
4.23	0.00	3392712.00	U.	U.	U.	U.	130.0
4.23	8.00	3402720.00	U.	U.	U.	U.	130.0
4.23	16.00	3412728.00	U.	U.	U.	U.	130.0
4.24	0.00	3422736.00	U.	U.	U.	U.	130.0
4.24	8.00	3432744.00	U.	U.	U.	U.	130.0
4.24	16.00	3442752.00	U.	U.	U.	U.	130.0
4.25	0.00	3452760.00	U.	U.	U.	U.	130.0
4.25	8.00	3462768.00	U.	U.	U.	U.	130.0
4.25	16.00	3472776.00	U.	U.	U.	U.	130.0
4.26	0.00	3482784.00	U.	U.	U.	U.	130.0
4.26	8.00	3492792.00	U.	U.	U.	U.	130.0
4.26	16.00	3502800.00	U.	U.	U.	U.	130.0
4.27	0.00	3512808.00	U.	U.	U.	U.	130.0
4.27	8.00	3522816.00	U.	U.	U.	U.	130.0
4.27	16.00	3532824.00	U.	U.	U.	U.	130.0
4.28	0.00	3542832.00	U.	U.	U.	U.	130.0
4.28	8.00	3552840.00	U.	U.	U.	U.	130.0
4.28	16.00	3562848.00	U.	U.	U.	U.	130.0
4.29	0.00	3572856.00	U.	U.	U.	U.	130.0
4.29	8.00	3582864.00	U.	U.	U.	U.	130.0
4.29	16.00	3592872.00	U.	U.	U.	U.	130.0
4.30	0.00	3602880.00	U.	U.	U.	U.	130.0
4.30	8.00	3612888.00	U.	U.	U.	U.	130.0
4.30	16.00	3622896.00	U.	U.	U.	U.	130.0
5.01	0.00	3632904.00	U.	U.	U.	U.	130.0
5.01	8.00	3642912.00	U.	U.	U.	U.	130.0
5.01	16.00	3652920.00	U.	U.	U.	U.	130.0
5.02	0.00	3662928.00	U.	U.	U.	U.	130.0
5.02	8.00	3672936.00	U.	U.	U.	U.	130.0
5.02	16.00	3682944.00	U.	U.	U.	U.	130.0
5.03	0.00	3692952.00	U.	U.	U.	U.	130.0
5.03	8.00	3702960.00	U.	U.	U.	U.	130.0
5.03	16.00	3712968.00	U.	U.	U.	U.	130.0
5.04	0.00	3722976.00	U.	U.	U.	U.	130.0
5.04	8.00	3732984.00	U.	U.	U.	U.	130.0
5.04	16.00	3742992.00	U.	U.	U.	U.	130.0
5.05	0.00	3753000.00	U.	U.	U.	U.	130.0
5.05	8.00	3763008.00	U.	U.	U.	U.	130.0
5.05	16.00	3773016.00	U.	U.	U.	U.	130.0
5.06	0.00	3783024.00	U.	U.	U.	U.	130.0
5.06	8.00	3793032.00	U.	U.	U.	U.	130.0
5.06	16.00	3803040.00	U.	U.	U.	U.	130.0
5.07	0.00	3813048.00	U.	U.	U.	U.	130.0
5.07	8.00	3823056.00	U.	U.	U.	U.	130.0
5.07	16.00	3833064.00	U.	U.	U.	U.	130.0
5.08	0.00	3843072.00	U.	U.	U.	U.	130.0
5.08	8.00	3853080.00	U.	U.	U.	U.	130.0
5.08	16.00	3863088.00	U.	U.	U.	U.	130.0
5.09	0.00	3873096.00	U.	U.	U.	U.	130.0
5.09	8.00	3883104.00	U.	U.	U.	U.	130.0
5.09	16.00	3893112.00	U.	U.	U.	U.	130.0
5.10	0.00	3903120.00	U.	U.	U.	U.	130.0
5.10	8.00	3913128.00	U.	U.	U.	U.	130.0
5.10	16.00	3923136.00	U.	U.	U.	U.	130.0
5.11	0.00	3933144.00	U.	U.	U.	U.	130.0
5.11	8.00	3943152.00	U.	U.	U.	U.	130.0
5.11	16.00	3953160.00	U.	U.	U.	U.	130.0
5.12	0.00	3963168.00	U.	U.	U.	U.	130.0
5.12	8.00	3973176.00	U.	U.	U.	U.	130.0
5.12	16.00	3983184.00	U.	U.	U.	U.	130.0
5.13	0.00	3993192.00	U.	U.	U.	U.	130.0
5.13	8.00	4003200.00	U.	U.	U.	U.	130.0

PEAK	10-DAY	33-DAY	90-DAY	TOTAL VOLUME
7.	7.	7.	0.	2001.
0.	0.	0.	0.	31.
	1.00	4.92	13.97	10.37
	42.20	125.03	359.21	466.24
	133.	394.	1116.	1326.
	104.	485.	1370.	1030.

10
MS
INCHES

MM

AC-FT
11133 00 M

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
 FLOWS IN CUBIC FEET PER SECOND (CFS) (METERS PER SECOND)
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

RATIOS APPLIED TO FLOWS

OPERATION STATION ARC PLAN RATIO 1
 1.00

HYDROGRAPH AT 1 1.00 1 0.00

ROUTE 1 2 1.00 1 0.19

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1	ELEVATION	INITIAL VALUE	SPELLWAY GUEST	TOP OF DAM	
	STORAGE	101.00	101.00	101.00	
	OUTFLOW	1332.	1332.	1332.	
		1.	1.	1.	
RATIO	MAXIMUM	MAXIMUM	MAXIMUM	MAXIMUM	TIME OF
OF	DEPTH	STORAGE	OUTFLOW	OVER TOP	MAX OUTFLOW
PMF	OVER DAM	ACTL	UPS	HOURS	HOURS
1.00	100.96	0.0	1332.	1.	0.0

APPENDIX D

REFERENCES

REFERENCES

1. University of the State of New York, Geology of New York, Education Leaflet 20, 1966.
2. Broughton, John G. and others, "Geologic Map of New York - Lower Hudson Sheet," New York State Museum and Science Service, Map and Chart Series No. 15, 1970.
3. Dunbar, Carl O. and Waage, Karl M., Historical Geology, John Wiley and Sons, Inc., New York, 1969.
4. Soil Conservation Service, Soil Interpretations Inventory Analysis and Erosion Control - Orange County, New York, U.S. Dept. of Agriculture, January 1972.
5. Bureau of Reclamation, U.S. Dept. of the Interior, Design of Small Dams, A Water Resources Technical Publication, 1977.
6. Chow, Ven Te, Handbook of Applied Hydrology, McGraw - Hill Book Company, New York, 1964.
7. Chow, Ven Te, Open Channel Hydraulics, McGraw - Hill Book Company, New York, First Edition, 1959.
8. HMR 33, "Seasonal Variations of Probable Maximum Precipitation, East of the 105th Meridian for Areas 10 to 1000 Square Miles and Durations of 6 to 48 Hours," (1956).
9. King, Horace Williams and Brater, Ernest F., Handbook of Hydraulics, Fifth Edition, McGraw - Hill Book Company, New York, 1963.
10. Soil Conservation Service, "National Engineering Handbook - Section 4, Hydrology," U.S. Department of Agriculture, 1964.
11. Soil Conservation Service, "National Engineering Handbook - Section 5, Hydraulics," U.S. Department of Agriculture.
12. U.S. Army, Hydrological Engineering Center, "Flood Hydrograph Package (HEC-1), Dam Safety Investigations, Users Manual," Corps of Engineers, Davis, California, September 1978.
13. U.S. Army, Hydrological Engineering Center, "HEC-2 Water Surface Profiles, Users Manual," Corps of Engineers, Davis, California, October 1973.

14. U.S. Army, "Inventory of United States Dams," Corps of Engineers, 9 September 1978.
15. U.S. Army, Office of the Chief of Engineers, "Appendix D, Recommended Guidelines for Safety Inspection of Dams," National Program of Inspection of Dams, Volume 1, Corps of Engineers, Washington, D.C., May 1975.
16. George, Thomas S. and Taylor, Robert S., Hydrologic Flood Routing Model For Lower Hudson River Basin, Water Resources Engineers, Inc., 8001 Forbes Place, Suite 312, Springfield, Virginia, January 1977.
17. U.S. Army, Office of the Chief of Engineers, Engineering Circular EC-1110-2-163 (Draft Engineering Manual), "Spillway and Freeboard Requirements for Dams, Appendix C, Hydrometeorological Criteria and Hyetograph Estimates," (August 1975).
18. U.S. Army, Office of the Chief of Engineers, Engineering Circular EC-1110-2-188, "Engineering and Design, National Program of Inspection of Non-Federal Dams," Corps of Engineers, Washington, D.C., 30 December 1977.
19. U.S. Army, Office of the Chief of Engineers, Engineer Technical Letter No. ETL 1110-2-234, "Engineering and Design, National Program of Inspection of Non-Federal Dams, Review of Spillway Adequacy," Corps of Engineers, Washington, D.C., 10 May 1978.
20. U.S. Department of Commerce, "Technical Paper No. 40, Rainfall Frequency Atlas of the United States for Durations from 30 Minutes to 24 Hours and Return Periods from 1 to 100 Years," Weather Bureau, Washington, D.C., May 1961.
21. U.S. Department of Commerce, National Oceanic and Atmospheric Administration, "Hydrometeorological Report No. 51, Probable Maximum Precipitation Estimates, United States East of the 105th Meridian," Washington, D.C., June 1978.

APPENDIX E
DRAWINGS

AD-A105 768

BAKER (MICHAEL) JR INC BEAVER PA

F/G 13/13

NATIONAL DAM SAFETY PROGRAM. WOODWARD DAM (INVENTORY NUMBER NY --ETC(U)

JUN 81 G KESTER

DACW51-81-C-0010

NL

UNCLASSIFIED

2-11-81
41-1-81
8 5 40




END
DATE
11 MAY 81
DTIC


CONTENTS

Location Plan

Watershed Map

- Plate 1a: Field Sketch of Woodward Dam
- Plate 1b: Field Sketch of Greenleaf Dam
- Plate 2: Plan of Dam (1901)
- Plate 3: Contours for Proposed Spillway
- Plate 4: Plan of Wells of Gate House and Core Wall
- Plate 5: Reconstruction Plans (1947)





MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009

Subject WOODWARD DAM S.O. No. _____
FIELD SKETCH Sheet No. _____ of _____
Drawing No. _____
Computed by _____ Checked by _____ Date _____




PLATE 1a

MICHAEL BAKER, JR., INC.
THE BAKER ENGINEERS

Box 280
Beaver, Pa. 15009

Subject GREENLEAF DAM S.O. No. _____
FIELD SKETCH Sheet No. _____ of _____
Drawing No. _____
Computed by _____ Checked by _____ Date _____






PLATE 1b



**ELEVATION OF DAM.
ON LINE "A B."**

SCALE
HOR 20' TO 1"
VER 10' TO 1"




PLAN OF DAM.

SCALE
20' TO 1"

IN 5 LAYERS
WATERED
AND
ROLLED

**SECTION IN DETAIL
SHOWING
PAVING & FILLING
SCALE
2 TO 1**



**SECTION OF EARTH DAM
RUBBLE MASONRY CORE
ON LINE C.D.
SCALE
HORIZ. VER.
10 TO 1"**

**WEST END.
B**

**BOARD OF WATER COMMISSIONERS
MIDDLETOWN
N.Y.**


WOODWARD DAM


**CONSULTING ENGINEER
JAN 1961**

PLATE 2



RESIDENT ENGINEER








- SECTION THROUGH SCREEN WELL




NOTE: THE 8 INCH AND 20 INCH PIPES ARE TO BE Laid BY THE CONTRACTOR THROUGH THE EXISTING A DISTANCE OF 80 FEET FROM THE CENTER OF THE CORE WALL.



Scale 1" = 10'

NOTES FOR
CONSTRUCTION
OF
DAM



BOARD OF WATER COMMISSIONERS
MIDDLETOWN, N. Y.

Plan of Wells, et al. Co. Inc. for the
WOODWARD DAM

January 1911


Resident Engineer

Consulting Engineer

-NOTE-

ALL FOUNDATION PITS FOR STRUCTURES
AND CORE WALLS ARE TO BE EXCAVATED TO
FIRM BOTTOM TO BE DETERMINED BY
ENGINEER.

NO ALLOWANCE FOR FOUNDATION
SETTLING AND DAMPNESS OF
MATERIAL SHALL BE MADE BY THE
ENGINEER FOR THE FOUNDATION WORK
BECAUSE OF ANY FOUNDATION WORK.




2

742 743 744 745 746



DRAWN BY: R.V.V.
 TRACED BY: J.M.M.
 CHECKED BY: J.K.F.



NOTE: THIS RECONSTRUCTION WAS NEVER COMPLETED, BUT ITEMS SHOWN AS EXISTING REFLECT PRESENT CONDITIONS.

PLATE 5

CITY OF MIDDLETOWN
ORANGE COUNTY NEW YORK
N.Y.S.R.W.R.W.G. SERIAL NO. 5757.

INCREASING STORAGE
AT SHAWANGUNK LAKE

WOODWARD DAM PLAN

SCALE 1" = 20 FEET

DESIGNED BY
BANKER & WATSON

35 STATE ST.
ALBANY, N.Y.

REVISED NOV. 5, 1937.

Approved: _____
N.Y. State Dept. of Public Works

Approved: _____
N.Y. S. Port & Public Works Planning Commission
Chairman

NOTE: Elevation shown based on
Bench Mark - west end of spillway
notch - Elevation 787.01

APPENDIX F
BACKGROUND DOCUMENTS

01

RD

36

CTY

25

YR AP.

562

DAM NO.

180474

INS. DATE

003

USE

TYPE

AS BUILT DESCRIPTION☒Location of Sp'way
and outlet☐

Elevations

☐Size of Sp'way
and Outlet☐Geometry of
Non-overflow section☐GENERAL CONDITION OF NON-OVERFLOW SECTION☒

Settlement

☒

Cracks

☒

Deflections

☒

Joints

☒Surface of
Concrete☒

Leakage

☒

Undermining

☒Settlement of
Embankment☒

Crest of Dam

☒Downstream
Slope☒Upstream
Slope☒Toe of
Slope☒GENERAL COND. OF SP'WAY AND OUTLET WORKS☒Auxiliary
Spillway☒Service or
Concrete Sp'way☒Stilling
Basin☐

Joints

☒Surface of
Concrete☒Spillway
Toe☒Mechanical
Equipment☒Plunge
Pool☒

Drain

☐

Maintenance

☒

Hazard Class

☒

Evaluation

35

Inspector

COMMENTS:

good condition

STATE OF NEW YORK
DEPARTMENT OF
State Engineer and Surveyor
ALBANY

Received July 14 - 1925Dam No. 562 Lower Hudson WatershedDisposition Approved July 23 - 1925Serial No. 633

Foundation inspected _____

Structure inspected _____

Application for the ~~Construction or~~ Reconstruction of a Dam

Application is hereby made to the State Engineer, Albany, N. Y., in compliance with the provisions of Chapter LXV of the Consolidated Laws and Chapter 647, Laws of 1911, Section 22 as amended, for the approval of specifications and detailed drawings, marked Westward Dam on the

Shawangunk Reservoir raising same 2 1/2 ft.
herewith submitted for the { ~~construction~~ reconstruction } of a dam located as stated below. All provisions of law will be complied with in the erection of the proposed dam. It is intended to complete the work covered by the application about Nov 1st 1925
(Date)

1. The dam will be on Shawangunk Reservoir flowing into _____ in the town of Mt. Hope, County of Orange and _____

-- (Give exact distance and direction from a well-known bridge, dam, village main cross-roads or mouth of a stream)

2. The name and address of the owner is City of Middletown, N.Y.

3. The dam will be used for Storage Reservoir

4. Will any part of the dam be built upon or its pond flood any State lands? No

5. The watershed at the proposed dam draining into the pond to be formed thereby is 8 square miles.

6. The proposed dam will have a pond area at the spillcrest elevation of 101 acres and will impound 20,000,000 cubic feet of water.

7. The lowest part of the natural shore of the pond is 15 feet vertically above the spillcrest, and everywhere else the shore will be at least 10-25 feet above the spillcrest.

8. The maximum known flow of the stream at the dam site was _____ cubic feet per second on _____ (Date)

9. State if any damage to life or to any buildings, roads or other property could be caused by any possible failure of the proposed dam No

10. The natural material of the bed on which the proposed dam will rest is (clay, sand, gravel, boulders, granite, shale, slate, limestone, etc.) _____

11. The material of the right bank, in the direction with the current, is.....; at the spillcrest elevation this material has a top slope ofinches vertical to a foot horizontal on the center line of the dam, a vertical thickness at this elevation of.....feet, and the top surface extends for a vertical height offeet above the spillcrest.

12. The material of the left bank is.....; has a top slope of.....inches to a foot horizontal, a thickness of.....feet, and a height of.....feet.

13. State the character of the bed and the banks in respect to the hardness, perviousness, water bearing, effect of exposure to air and to water, uniformity, etc.....

14. If the bed is in layers, are the layers horizontal or inclined?..... If inclined what is the direction of the horizontal outcropping relative to the axis of the main dam and the inclination and direction of the layers in a plane perpendicular to the horizontal outcropping.....

15. What is the thickness of the layers?.....

16. Are there any porous seams or fissures?..... *No*

17. WASTES. The spillway of the above proposed dam will be..... *16* feet long in the clear; the waters will be held at the right end by a..... the top of which will be..... *6 1/2* feet above the spillcrest, and have a top width of.....feet; and at the left end by a..... the top of which will be.....feet above the spillcrest, and have a top width of.....feet.

18. There will be also for flood discharge a pipe.....inches inside diameter and the bottom will be.....feet below the spillcrest, a sluice or gate.....feet wide in the clear byfeet high, and the bottom will be.....feet below the spillcrest.

19. APRON. Below the proposed dam there will be an apron built of.....feet long across the stream,feet wide and.....feet thick. The downstream side of the apron will have a thickness of.....feet for a width of.....feet.

20. PLANS. Each application for a permit of a dam over 12 feet in height must be accompanied by a location map and complete working drawings in triplicate of the proposed structure, one set of which will be returned if they are approved. Each drawing should have a title giving the parts shown, the name of the town and county in which the dam site is located, and the name of the owner and of the engineer.

The location map (U. S. Geological Quadrangle or other map) should show the exact location of the proposed dam; of buildings below the dam which might be damaged by any failure of the dam; of roads adjacent to or crossing the stream below the dam, giving the lowest elevation of the roadway above the stream bed and giving the shape,

The above information is correct to the best of my knowledge and belief.

Middletown, NY
(Address of signer)

July 13/25
(Date)

John M. Mearns
Comr. Public Works
(A person signing for owner should indicate his title or authority)

July 24, 1925.

Dam 562, L. Hudson.
Middletown.

Commissioner of Public Works,
Middletown,
N. Y.

Dear Sir:

Application having been duly made to the State Engineer, you are hereby given permission up to November 30, 1925, in so far as the matter involves the jurisdiction conferred upon this office by chapter 82 of the laws of 1923, to reconstruct the Woodward dam at the northeast end of the Shawangunk Lake, designated on the records of this Department as dam No. 562, Lower Hudson watershed, by raising the embankment 2.5 ft. according to the two prints in triplicate submitted therefor, under the following conditions:

1. That the slopes of the embankment if made steeper than 1 vertical to 2-1/2 horizontal on the upstream side, be well laid in Portland cement.
2. That the spillway be laid up in cement mortar and have a cutoff of 3 ft. deep into the bed and into the banks.
3. That the Lamson dam at the southwest end of Shawangunk Lake, and designated on the records of this Department as dam No. 559, Lower Hudson watershed, be raised to the same elevation as the Woodward dam, be paved on the upstream slope and have the same depth, elevation, top width and slopes as required for the Woodward dam.
4. That the embankments and wall of the channel be constructed by paving wherever they may be subject to any wave or current erosive action.
5. That this Department be notified when the work is started.

This approval shall not be deemed to authorize any invasion of property rights, either public or private, in carrying out the above work; nor to create any claim or demand against the State of New York, nor to authorize the flooding or use of State lands; nor to acquiesce in the flooding or use of such lands.

No. 2.

Commr. Public Wks, Middletown

July 23, 1925.

On July 16th there were sent to you report blanks to be filled out, one for each of the other dams besides the Finch dam and the Lamson, Greenleaf and Woodward dams on the Shawangunk Lake, these include the two dams on Highland Lake, the two dams on Monhagen Lake and perhaps others. These report blanks were returned partially filled out for the Shawangunk Lake dams. We enclose additional blanks for the dams on Highland and Monhagen Lakes.

Acknowledgment is requested of the receipt of this letter and of the prints.

Yours very truly,

Roy G. Finch,
State Engineer.

By

Assistant Deputy.

ARMCK/ECH