

AD-A106 040

HORNER AND SHIFRIN INC ST LOUIS MO
NATIONAL DAM SAFETY PROGRAM. HIDDEN VALLEY LAKE DAM (MO 31100),--ETC(U)
FEB 80 H B LOCKETT, A B BECKER

F/G 13/13

DACW43-79-C-0047

NL

UNCLASSIFIED

1 OF 1
40 A
106640

END
DATE
FILMED
11-81
DTIC

LEVEL

①

MISSISSIPPI - KASKASKIA - ST. LOUIS BASIN

AD A106040

**HIDDEN VALLEY LAKE DAM
STE. GENEVIEVE COUNTY, MISSOURI
MO 31100**

**PHASE 1 INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM**

ST. LOUIS DISTRICT



**United States Army
Corps of Engineers**
*... Serving the Army
... Serving the Nation*

St. Louis District

**DTIC
ELECTRIC**
OCT 23 1981
S
A

PREPARED BY: U.S. ARMY ENGINEER DISTRICT, ST. LOUIS

FOR: STATE OF MISSOURI

This document has been approved for public release and sale; its distribution is unlimited.

FEBRUARY 1980

81 10 21

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO. AD-H-106 040	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Dam Inspection Report National Dam Safety Program Hidden Valley Lake Dam (MO 31100) Ste. Genevieve County, Missouri		5. TYPE OF REPORT & PERIOD COVERED Final Report
7. AUTHOR(s) Horner & Shifrin, Inc.		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS U.S. Army Engineer District, St. Louis Dam Inventory and Inspection Section, LMSED-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101		8. CONTRACT OR GRANT NUMBER(s) DACW43-79-C-0047
11. CONTROLLING OFFICE NAME AND ADDRESS U.S. Army Engineer District, St. Louis Dam Inventory and Inspection Section, LMSED-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS 11-9
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		12. REPORT DATE February 1980
		13. NUMBER OF PAGES Approximately 55
		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) Approved for release; distribution unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report) National Dam Safety Program, Hidden Valley Lake Dam (MO 31100), Mississippi - Kaskaskia - St. Louis Basin, Ste. Genevieve County, Missouri. Phase I Inspection Report.		
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dam Safety, Lake, Dam Inspection, Private Dams		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report was prepared under the National Program of Inspection of Non-Federal Dams. This report assesses the general condition of the dam with respect to safety, based on available data and on visual inspection, to determine if the dam poses hazards to human life or property.		


DD FORM 1 JAN 73 1473

EDITION OF 1 NOV 65 IS OBSOLETE

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)



SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

INSTRUCTIONS FOR PREPARATION OF REPORT DOCUMENTATION PAGE

RESPONSIBILITY. The controlling DoD office will be responsible for completion of the Report Documentation Page, DD Form 1473, in all technical reports prepared by or for DoD organizations.

CLASSIFICATION. Since this Report Documentation Page, DD Form 1473, is used in preparing announcements, bibliographies, and data banks, it should be unclassified if possible. If a classification is required, identify the classified items on the page by the appropriate symbol.

COMPLETION GUIDE

General. Make Blocks 1, 4, 5, 6, 7, 11, 13, 15, and 16 agree with the corresponding information on the report cover. Leave Blocks 2 and 3 blank.

Block 1. Report Number. Enter the unique alphanumeric report number shown on the cover.

Block 2. Government Accession No. Leave Blank. This space is for use by the Defense Documentation Center.

Block 3. Recipient's Catalog Number. Leave blank. This space is for the use of the report recipient to assist in future retrieval of the document.

Block 4. Title and Subtitle. Enter the title in all capital letters exactly as it appears on the publication. Titles should be unclassified whenever possible. Write out the English equivalent for Greek letters and mathematical symbols in the title (see "Abstracting Scientific and Technical Reports of Defense-sponsored RDT/E," AD-667 000). If the report has a subtitle, this subtitle should follow the main title, be separated by a comma or semicolon if appropriate, and be initially capitalized. If a publication has a title in a foreign language, translate the title into English and follow the English translation with the title in the original language. Make every effort to simplify the title before publication.

Block 5. Type of Report and Period Covered. Indicate here whether report is interim, final, etc., and, if applicable, inclusive dates of period covered, such as the life of a contract covered in a final contractor report.

Block 6. Performing Organization Report Number. Only numbers other than the official report number shown in Block 1, such as series numbers for in-house reports or a contractor/grantee number assigned by him, will be placed in this space. If no such numbers are used, leave this space blank.

Block 7. Author(s). Include corresponding information from the report cover. Give the name(s) of the author(s) in conventional order (for example, John R. Doe or, if author prefers, J. Robert Doe). In addition, list the affiliation of an author if it differs from that of the performing organization.

Block 8. Contract or Grant Number(s). For a contractor or grantee report, enter the complete contract or grant number(s) under which the work reported was accomplished. Leave blank in in-house reports.

Block 9. Performing Organization Name and Address. For in-house reports enter the name and address, including office symbol, of the performing activity. For contractor or grantee reports enter the name and address of the contractor or grantee who prepared the report and identify the appropriate corporate division, school, laboratory, etc., of the author. List city, state, and ZIP Code.

Block 10. Program Element, Project, Task Area, and Work Unit Numbers. Enter here the number code from the applicable Department of Defense form, such as the DD Form 1498, "Research and Technology Work Unit Summary" or the DD Form 1634, "Research and Development Planning Summary," which identifies the program element, project, task area, and work unit or equivalent under which the work was authorized.

Block 11. Controlling Office Name and Address. Enter the full, official name and address, including office symbol, of the controlling office. (Equates to funding/sponsoring agency. For definition see DoD Directive 5200.20, "Distribution Statements on Technical Documents.")

Block 12. Report Date. Enter here the day, month, and year or month and year as shown on the cover.

Block 13. Number of Pages. Enter the total number of pages.

Block 14. Monitoring Agency Name and Address (if different from Controlling Office). For use when the controlling or funding office does not directly administer a project, contract, or grant, but delegates the administrative responsibility to another organization.

Blocks 15 & 15a. Security Classification of the Report: Declassification/Downgrading Schedule of the Report. Enter in 15 the highest classification of the report. If appropriate, enter in 15a the declassification/downgrading schedule of the report, using the abbreviations for declassification/downgrading schedules listed in paragraph 4-207 of DoD 5200.1-R.

Block 16. Distribution Statement of the Report. Insert here the applicable distribution statement of the report from DoD Directive 5200.20, "Distribution Statements on Technical Documents."

Block 17. Distribution Statement (of the abstract entered in Block 20, if different from the distribution statement of the report). Insert here the applicable distribution statement of the abstract from DoD Directive 5200.20, "Distribution Statements on Technical Documents."

Block 18. Supplementary Notes. Enter information not included elsewhere but useful, such as: Prepared in cooperation with . . . Translation of (or by) . . . Presented at conference of . . . To be published in . . .

Block 19. Key Words. Select terms or short phrases that identify the principal subjects covered in the report, and are sufficiently specific and precise to be used as index entries for cataloging, conforming to standard terminology. The DoD "Thesaurus of Engineering and Scientific Terms" (TEST), AD-672 000, can be helpful.

Block 20. Abstract. The abstract should be a brief (not to exceed 200 words) factual summary of the most significant information contained in the report. If possible, the abstract of a classified report should be unclassified and the abstract to an unclassified report should consist of publicly-releasable information. If the report contains a significant bibliography or literature survey, mention it here. For information on preparing abstracts see "Abstracting Scientific and Technical Reports of Defense-Sponsored RDT&E," AD-667 000.

MISSISSIPPI - KASKASKIA - ST. LOUIS BASIN

**HIDDEN VALLEY LAKE DAM
STE. GENEVIEVE COUNTY, MISSOURI
MO 31100**

**PHASE 1 INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM**



**United States Army
Corps of Engineers**

*... Serving the Army
... Serving the Nation*

St. Louis District

This document has been approved
for public release and sale; its
distribution is unlimited.

PREPARED BY: U.S. ARMY ENGINEER DISTRICT, ST. LOUIS

FOR: STATE OF MISSOURI

FEBRUARY 1980

A



DEPARTMENT OF THE ARMY
ST. LOUIS DISTRICT, CORPS OF ENGINEERS
210 NORTH 12TH STREET
ST. LOUIS, MISSOURI 63101

IN REPLY REFER TO

SUBJECT: Hidden Valley Lake Dam (Mo. 31100) Phase I Inspection Report

This report presents the results of field inspection and evaluation of the Hidden Valley Lake Dam:

It was prepared under the National Program of Inspection of Non-Federal Dams.

This dam has been classified as unsafe, non-emergency by the St. Louis District as a result of the application of the following criteria:

1. Spillway will not pass 50 percent of the Probable Maximum Flood.
2. Overtopping of the dam and/or erosion of the spillway could result in failure of the dam.
3. Dam failure significantly increases the hazard to loss of life downstream.

SUBMITTED BY: _____

SIGNED
Chief, Engineering Division

31 MAR 1980

Date

APPROVED BY: _____

SIGNED
Colonel, CE, District Engineer

1 APR 1980

Date

HIDDEN VALLEY LAKE DAM
MISSOURI INVENTORY NO. 31100
STE. GENEVIEVE COUNTY, MISSOURI

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

PREPARED BY:

HORNER & SHIFRIN, INC.
5200 OAKLAND AVENUE
ST. LOUIS, MISSOURI 63110

FOR:

U.S. ARMY ENGINEER DISTRICT, ST. LOUIS
CORPS OF ENGINEERS

FEBRUARY 1980

HS-7925

PHASE I REPORT

NATIONAL DAM SAFETY PROGRAM

Name of Dam: Hidden Valley Lake Dam
State Located: Missouri
County Located: Ste. Genevieve
Stream: Brushy Creek
Date of Inspection: 18 October 1979

The Hidden Valley Lake Dam, was visually inspected by engineering personnel of Horner & Shifrin, Inc., Consulting Engineers, St. Louis, Missouri. The purpose of this inspection was to assess the general condition of the dam with respect to safety and, based upon this inspection and available data, determine if the dam poses a hazard to human life or property.

The following summarizes the findings of the visual inspection and the results of certain hydrologic/hydraulic investigations performed under the direction of the inspection team. Based on the visual inspection, the present general physical condition of the dam proper is considered to be satisfactory. However, the following deficiencies were noticed during the inspection and are considered to have an adverse effect on the overall safety and future operation of the dam:

1. Seepage, as characterized by soft ground, running and standing water, cattails, and willows; was observed at the toe of the center of the dam in the area between the emergency spillway outlet channel and the original creek channel. Uncontrolled seepage could develop into a piping condition that can lead to failure of the dam. Saturation of the soil adjacent to the dam can weaken the foundation and impair the stability of the dam.

2. The earthen banks of the outlet channel for the principal spillway are in an unstable state as evidenced by erosion, sloughing, cracking, and near vertical slopes. In a location at the upper bend in the channel, the left bank of the channel appeared to be on the verge of collapse. Loss of the channel banks could render the spillway outlet ineffective which may result in overtopping and possibly failure of the dam.
3. The crest and outlet channel for the emergency spillway were noticeably eroded. Continued erosion of the spillway could lower the spillway crest resulting in increased lake outflow and conditions promoting greater erosion with the possibility of flooding the downstream area adjacent to the dam.
4. Erosion of the grass covered upstream face of the dam apparently by wave action and/or by fluctuations in the lake surface level has created a near vertical bank approximately 1 to 2 feet high at the normal waterline. A grass covered slope is not considered adequate to prevent erosion by wave action or fluctuations of the lake level.
5. A beaver dam exists within the downstream channel, Brush Creek, just downstream of the junction of the creek with the spillway outlet channels, a distance of approximately 400 feet from the dam. The beaver dam serves to obstruct flow restricting the capacity of the channel which could result in flooding of the area below the dam.


According to the criteria set forth in the recommended guidelines, the magnitude of the spillway design flood for the Hidden Valley Lake Dam, which is classified as small in size and of high hazard potential, is specified to be a minimum of one-half the Probable Maximum Flood (PMF). Considering the fact that a fairly large volume of water is

impounded; the downstream floodplain is relatively narrow and flow in the stream will be deep and with high velocities; and that several dwellings lie within the possible flood damage zone, it is recommended that the spillway for this dam be designed for the PMF. The Probable Maximum Flood (PMF) is the flood that may be expected from the most severe combination of critical meteorologic and hydrologic conditions that are reasonably possible in the region. The PMF is ordinarily accepted as the inflow design flood for dams where failure of the structure would increase the danger to human life.

Results of a hydrologic/hydraulic analysis indicated that both spillways, principal plus emergency, are inadequate to pass lake outflow resulting from a storm of PMF magnitude or from the 1 percent chance (100-year frequency) flood. The spillways are capable however, of passing lake outflow corresponding to about 9 percent of the PMF lake inflow and the lake outflow resulting from the 0.1 percent chance (10-year frequency) flood. According to the St. Louis District, Corps of Engineers, the length of the downstream damage zone, should failure of the dam occur, is estimated to be 3 miles. Accordingly, within the possible damage zone are three dwellings and several farm buildings.


A review of available data did not disclose that seepage or stability analyses of this dam were performed. This is considered a deficiency and should be rectified.

It is recommended that the Owner take the necessary action in the near future to correct or control the deficiencies and safety defects reported herein.



Harold B. Lockett

P.E. Missouri E-4189



Albert B. Becker, Jr.

P.E. Missouri E-9168



PEACE 1 INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

HIDDEN VALLEY LAKE DAM - ID. NO. 31100

TABLE OF CONTENTS

<u>Paragraph No.</u>	<u>Title</u>	<u>Page No.</u>
SECTION 1 - PROJECT INFORMATION		
1.1	General	1-1
1.2	Description of Project	1-1
1.3	Pertinent Data	1-4
SECTION 2 - ENGINEERING DATA		
2.1	Design	2-1
2.2	Construction	2-1
2.3	Operation	2-1
2.4	Evaluation	2-2
SECTION 3 - VISUAL INSPECTION		
3.1	Findings	3-1
3.2	Evaluation	3-4
SECTION 4 - OPERATIONAL PROCEDURES		
4.1	Procedures	4-1
4.2	Maintenance of Dam	4-1
4.3	Maintenance of Outlet Operating Facilities	4-1

<u>Paragraph No.</u>	<u>Title</u>	<u>Page No.</u>
4.4	Description of Any Warning Systems in Effect	4-1
4.5	Evaluation	4-1
SECTION 5 - HYDRAULIC/HYDROLOGIC		
5.1	Evaluation of Features	5-1
SECTION 6 - STRUCTURAL STABILITY		
6.1	Evaluation of Structural Stability	6-1
SECTION 7 - ASSESSMENT/REMEDIAL MEASURES		
7.1	Dam Assessment	7-1
7.2	Remedial Measures	7-2

LIST OF PLATES

<u>Plate No.</u>	<u>Title</u>
1	Regional Vicinity Map
2	Lake Watershed Map
3	Dam Plan and Profile
4	Dam Section & Spillway Profile
5	Spillway Rating Curves
6	Lake Area-Storage Curves

APPENDIX A - INSPECTION PHOTOGRAPHS

<u>Page No.</u>	<u>Title</u>
A-1 through A-6	Inspection Photographs

APPENDIX B - HYDROLOGIC AND HYDRAULIC ANALYSES

<u>Page No.</u>	<u>Title</u>
B-1, B-2	Hydrologic & Hydraulic Computations
B-3 thru B-5	Computer Input Data
B-6	Summary Dam Safety Analyses
B-7	PMF Hydrographs

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

HIDDEN VALLEY LAKE DAM - I.D. NO. 31100

SECTION I - PROJECT INFORMATION

1.1 GENERAL

a. Authority. The National Dam Inspection Act, Public Law 92-367, dated 8 August 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of safety inspection of dams throughout the United States. Pursuant to the above, the St. Louis District, Corps of Engineers, directed that a safety inspection of the Hidden Valley Lake Dam be made.

b. Purpose of Inspection. The purpose of this visual inspection was to make an assessment of the general condition of the above dam with respect to safety and, based upon available data and this inspection, determine if the dam poses a hazard to human life or property.

c. Evaluation Criteria. This evaluation was performed in accordance with the "Phase I" investigation procedures as prescribed in "Recommended Guidelines for Safety Inspection of Dams," Appendix D to "Report to the Chief of Engineers on the National Program of Inspection of Non-Federal Dams," dated May 1975.

1.2 DESCRIPTION OF PROJECT

a. Description of Dam and Appurtenances. The Hidden Valley Lake Dam is an earthfill type embankment rising approximately 35 feet above the original streambed. The embankment has an upstream slope (above the waterline) of 1v on 2.3h, a crest width of about 20 feet, and a

downstream slope of 1v on 2.4h. The length of the dam including the spillway sections is approximately 620 feet. A plan and profile of the dam are shown on Plate 3 and a cross-section of the dam is shown on Plate 4. At normal pool elevation the reservoir impounded by the dam occupies approximately 28 acres.

The dam has both a principal and emergency spillway. The principal spillway is cut into the hillside at the right or east abutment. The spillway outlet channel, a badly eroded canyon-like section with near vertical side walls, conducts flow towards a watercourse of the adjacent valley that lies approximately 340 feet downstream and to the east of the dam. Just downstream of the spillway crest the channel drops abruptly through a series of rock ledges into the deep, canyon-like section. The channel then continues by meandering through both earth and rock formations before joining the watercourse east of the dam. This watercourse joins the downstream channel, Brushy Creek, at a point approximately 350 feet below the dam.

The emergency spillway, trapezoidal section, is located at the left or west abutment. The spillway is moderately eroded throughout. A V-shaped section cut into the overburden serves as the spillway outlet channel. The spillway channel joins the downstream channel, Brushy Creek at a point approximately 350 feet below the dam. An earthen berm on the right side that adjoins the dam serves to confine flow to the channel and protect the dam.

b. Location. The dam is located on Brushy Creek, a tributary of Saline Creek, about one-half mile west of State Highway N and approximately 5 miles southwest of the Town of Minnith, Missouri, as shown on the Regional Vicinity Map, Plate 1. The dam is located in Section 19, Township 35 North, Range 9 East, within Ste. Genevieve County.

c. Size Classification. The size classification based on the height of the dam and storage capacity, is categorized as small. (Per Table 1, Recommended Guidelines for Safety Inspection of Dams.)

d. Hazard Classification. Hidden Valley Lake Dam, according to the St. Louis District, Corps of Engineers, has a high hazard potential, meaning that if the dam should fail, there may be loss of life, serious damage to homes; or extensive damage to agricultural, industrial and commercial facilities, important public utilities, main highways, or railroads. The estimated flood damage zone, should failure of the dam occur, as determined by the St. Louis District, extends 3 miles downstream of the dam. Within the possible damage zone are three dwellings and several farm buildings.

e. Ownership. The lake and dam are owned by the Hidden Valley Sportsman's Club Association, Incorporated, a Missouri corporation of which Mr. Thomas J. Robertson is the current president. The Club's address is Hidden Valley Sportsman's Club, Inc., 902 Tenth Street, Crystal City, Missouri 63019.

f. Purpose of Dam. The dam impounds water for recreational use by individuals who are members of the club.

g. Design and Construction History. According to Mr. Gary Linderer, past president of the Club and familiar with the lake project since its inception, construction of the dam was started in 1974 and completed in 1975, and the builder of the dam was the Vern Bauman Contracting Co. of Ste. Genevieve, Missouri. Mr. Bauman reported that several test borings were made along the dam alignment prior to construction of the dam. However, records of this subsurface investigation as well as any other design and construction data are no longer available. The extent of the engineering investigations performed for design of the dam are unknown.

h. Normal Operational Procedure. The lake level is unregulated. Lake outflow is governed by the capacities of two overflow type spillways.

1.3 PERTINENT DATA

a. Drainage Area. The area tributary to the lake is essentially in a native state and covered with timber. The watershed above the dam amounts to approximately 1,130 acres. The watershed area is outlined on Plate 2.

b. Discharge at Damsite.

- (1) Estimated known maximum flood at damsite ... 90 cfs*
(W.S. Elev. 631.4)
- (2) Spillway capacity (principal + emergency) ... 870 cfs
(W.S. Elev. 632.9)

c. Elevation (Ft. above MSL). The following elevations were determined by survey and are based on topographic data shown on the 1959 Parker Lake, Missouri Quadrangle Map, 7.5 Minute Series.

- (1) Top of Dam ... 632.9 (min.)
- (2) Normal pool (spillway crest) ... 630.0
- (3) Streambed at centerline of dam ... 598+
- (4) Maximum tailwater ... Unknown
- (5) Tailwater at time of inspection ... 601.5

d. Reservoir.

- (1) Length at normal pool (elevation 630.0) ... 2,000 ft.
- (2) Length at maximum pool (elevation 632.9) ... 2,200 ft.

e. Storage.

- (1) Normal pool ... 305 ac. ft.
- (2) Top of dam (incremental) ... 87 ac. ft.

f. Reservoir Surface.

- (1) Normal pool ... 28 acres
- (2) Top of dam (incremental) ... 5 acres

*Based on an estimate of depth of flow at emergency spillway as observed by a representative of the Owner.

9. Dam.

- (1) Type ... Earth fill, homogeneous*
- (2) Length ... 620 ft.
- (3) Height ... 35 ft.
- (4) Top width ... 20 ft.
- (5) Side slopes
 - a. Upstream ... 1v on 2.3h (above waterline)
 - b. Downstream ... 1v on 2.4h
- (6) Cutoff ... Clay core*
- (7) Slope protection
 - a. Upstream ... Grass
 - b. Downstream ... Grass

h. Principal Spillway.

- (1) Type ... Uncontrolled, broad-crested, trapezoidal section
- (2) Location ... Right abutment
- (3) Crest ... Elevation 630.0
- (4) Approach channel ... Lake
- (5) Exit channel ... Earth and rock cut, U-shaped section

i. Emergency Spillway.

- (1) Type ... Uncontrolled, earth, trapezoidal section.
- (2) Location ... Left abutment
- (3) Crest ... Elevation 630.9
- (4) Approach channel ... Lake
- (5) Exit channel ... V-shaped, earth section

j. Lake Drawdown Facility.

- (1) Size ... 6-inch pipe (intake), 4-inch pipe (outlet)
- (2) Control ... 6-inch x 4-inch reducing valve (near outlet)
- (3) Elevation (Ft. above MSL) ... 603.8 (outlet end)

*Per dam builder.

SECTION 2 - ENGINEERING DATA

2.1 DESIGN

It was reported by the past president of the club, Mr. Gary Linderer, and by Mr. Vernon Bauman, the Contractor who constructed the dam, that a minimum of four test borings were advanced along the centerline of the dam. However, records of these borings or other engineering data used as a basis for design of the dam were not available.

2.2 CONSTRUCTION

As previously indicated, the dam was constructed by the Vernon Bauman Excavating Company of Ste. Genevieve, Missouri. According to Mr. Bauman, no formal records were kept during construction of the dam. However, the Contractor reported that considerable blasting was performed in order to construct a core trench and to anchor the right abutment into sound rock. It was reported that this core trench was 4 to 8 feet deep and about 8 feet wide; that several layers of gravel and clay-seamed ledge rock were excavated; that the trench was backfilled with clay, and that the material placed within the trench was compacted using a sheepsfoot roller. Mr. Bauman stated that most of the remaining embankment material was compacted with rubber-tired equipment, although a sheepsfoot roller was used to compact fill in critical areas. The Contractor mentioned that the embankment at the right abutment was anchored 20 to 25 feet into rock at the hillside while at the left abutment the embankment was secured into the clay covered hillside.

2.3 OPERATION

The lake level is uncontrolled and governed by the crest elevation of the principal spillway located at the right abutment. An emergency spillway, with a crest elevation approximately 0.9 feet higher than the crest of the principal spillway and about 2.0 feet lower than the top of

the dam at its lowest point, is located at the left abutment. A representative of the Owner, reported that the dam has not been overtopped and that the highest lake level observed occurred sometime during the spring of 1979 when the depth of flow at the emergency spillway was estimated to be about 6 inches.

2.4 EVALUATION

a. Availability. Engineering data for assessing the design of the dam and spillways were unavailable.

b. Adequacy. No data available. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety" were not available, which is considered a deficiency. These seepage and stability analyses should be performed for appropriate loading conditions (including earthquake loads) and made a matter of record.

SECTION 3 - VISUAL INSPECTION

3.1 FINDINGS

a. General. A visual inspection of the Hidden Valley Lake Dam was made by Horner & Shifrin engineering personnel, H. B. Lockett, Civil Engineer and Hydrologist, T. K. Deddens, Geological Engineer, and A. B. Becker, Jr., Civil and Soils Engineer, on 18 October 1979. An examination of the dam site was also made by an engineering geologist, Jerry D. Higgins, a consultant retained by Horner & Shifrin for the purpose of assessing the area geology. Also examined at the time of the inspection, was the area below the dam within the potential flood damage zone. Photographs of the dam taken at the time of the inspection are included on Pages A-1 through A-6 of Appendix A. The locations of the photographs taken during the inspection are indicated on Plate 3.

b. Area Geology. The dam site is located on the eastern flank of the Ozark Uplift on gently dipping Ordovician-age sedimentary rock in the area of the dam, the Gasconade formation is exposed at the surface. The Gasconade is predominantly a light brownish gray, crystalline and cherty dolomite with a few thin, irregular sandstone lenses. Cryptozoan, cellular and ropey cherts are also common. The residuum, formed by deep in situ weathering of the overlying Roubidoux consists of a thick, cherty clay soil containing boulder-size chert overlying an irregular bedrock surface of cryptozoan chert (reef) and dolomite. The residuum is relatively permeable and erodible. Bedrock exposures are primarily limited to the main spillway in the right abutment.

The right abutment is moderately sloping, composed of thick, cherty clay residuum overlying cryptozoan chert and dolomite. The spillway cut through the abutment hillside exposes a thick section of residuum and cryptozoan chert. The spillway channel has been eroded to a deep, steep-walled section with numerous potholes formed in the irregular bedrock surface.

The left abutment is gently sloping, composed of thick cherty clay residuum cut by a small emergency spillway. The spillway has undergone moderate erosion, and some small potholes have formed along its channel.

c. Dam. The visible portions of the upstream and downstream faces of the dam (See Photos 1 and 2) appeared to be in sound condition, although erosion of the unprotected upstream slope has created a near vertical face about 1 to 2 feet high at the normal pool waterline. No cracking or sloughing of the embankment, or misalignment of the dam crest was evident. The downstream slope and the upstream slope above normal pool were well covered by a thick stand of fescue and lespedeza type grasses that were about 12 inches high. No trees were present on either face of the embankment. The gravel surfaced road on the crest of the dam was found to be in good condition and appeared to be well maintained.

A marshy area (see Photo 9) as evidenced by cattails, willows, soft ground, and standing and flowing water, was observed just downstream of the center of the dam. Seepage flow from this area was difficult to estimate because of the fact that it extended over an area approximately 150 feet wide and 350 feet long. However, seepage flow near the dam appeared to be less than 5 gpm. Flooding of the old creek channel, believed primarily due to the fact that the valve on the lake drawdown pipe (see Photo 12) was open and discharging flow to the channel, and the presence of a beaver dam (see Photo 11) across the channel at a point approximately 350 feet downstream of the dam, had created a pool (see Photo 10) which abutted the base of the dam. Due to the presence of the pool it could not be determined if the dam was experiencing underseepage at the location of the old stream.

The crest area of the principal spillway (see Photo 3) appeared to be in sound condition, although the earthen bank at the interface of the dam and spillway had only a sparse cover of grass to prevent erosion of the embankment. It was also noted that an accumulation of miscellaneous debris littered the upstream area. Downstream of the crest the spillway

outlet channel was found to be badly eroded (see Photos 4 through 6) with several potholes formed in the bedrock surface of the invert and evidence of recent sloughing of the steep-walled earthen banks. At a location approximately 125 feet downstream of the crest, a vertical crack had severed a portion of the channel bank (see Photo 5) leaving it unstable and on the verge of collapse. The hillside to the right of the channel was also badly eroded, apparently by storm water runoff, with the surface cut by numerous small channels. Recent minor sloughing of the hillside adjacent to the channel was also evident.

The emergency spillway was moderately eroded with approximately 6 to 12 inches of foundation material (see Photo 7) missing throughout most of the crest area. Erosion of the overburden had created a V-shaped channel section (see Photo 8) up to about 3 feet in depth along the entire length of the outlet. Seepage, estimated to be on the order of 1 to 2 gpm, was noticed emerging in the channel invert beginning at a location approximately 200 feet below the crest. The berm adjacent to the right side of the channel and the hillside adjoining the left side were well covered by various varieties of grass and no significant erosion of these areas was noticed.

d. Downstream Channel. The channel, Brushy Creek, downstream of the dam is unimproved, although a low earth and gravel berm that appeared to be material excavated from the channel was noticed along the right bank in the vicinity of the dam. At a point approximately 350 feet from the dam the stream is joined by the principal and emergency spillway outlet channels. A low beaver dam crosses the stream just below the confluence of the spillway channels. Flow passing the beaver dam was attributed mostly to discharge from the lake drawdown valve which was open at the time of the inspection.

e. Reservoir. The area adjacent to the lake is in a natural state covered with a dense growth of trees. Except for those areas normally inundated by the lake, the shoreline about the lake was tree lined or

grass covered. The amount of sediment within the lake could not be determined at the time of the inspection; however, it is believed not to be significant.

3.2 EVALUATION

The deficiencies observed during this inspection and noted herein are not considered significant to warrant immediate remedial action. It is advisable, however, that the Owner address the problem of erosion at both the principal and emergency spillways within the near future.

SECTION 1 - OPERATIONAL PROCEDURES

4.1 PROCEDURES

The spillways are uncontrolled. The water surface level is determined by precipitation runoff, evaporation, seepage, and the capacities of the uncontrolled principal and emergency spillways.

4.2 MAINTENANCE OF DAM

The embankment and areas immediately adjacent thereto appeared relatively well maintained as no trees or brush were observed on the slopes and the area was uniformly covered with grass that was approximately 12 inches high at the time of the inspection. However, judging by the badly eroded and deteriorating conditions observed at the outlet channel for the principal spillway as well as the generally eroded condition of the emergency spillway it is apparent that no attempt has been made to remedy either situation. It also appears that there is little concern for problems associated with seepage or drainage of the low-lying marshy areas adjacent to the dam.

4.3 MAINTENANCE OF OUTLET OPERATING FACILITIES

No outlet operating facilities exist at this dam.

4.4 DESCRIPTION OF ANY WARNING SYSTEMS IN EFFECT

The inspection did not reveal the existence of a dam warning system.

4.5 EVALUATION

Lack of or inadequate maintenance is considered detrimental to the safety of the dam. It is recommended that maintenance of the dam and spillways be undertaken on a regular basis and that records be kept of all maintenance work performed.

SECTION 5 - HYDROLOGIC GENERALIZATION

5.1 EVALUATION OF FEATURES

a. Design Data. Design data are not available.

b. Experience Data. The drainage area and lake surface area were developed from the USGS Parker Lake, Missouri, Quadrangle Map. The proportions and dimensions of the spillways and dam were developed from surveys made during the inspection. Records of rainfall, streamflow or flood data for the watershed are not available.

c. Visual Observations.

(1) The principal spillway, a broad-crested trapezoidal section with a width of about 15 feet at the crest, is cut into the hillside at the right (east) abutment.

(2) At the spillway crest the spillway is defined by a grass covered earth berm on the left and by a nearly vertical excavated rock face on the right.

(3) Just downstream of the crest, the spillway drops abruptly through a series of rock ledges into a narrow, steep walled and badly eroded canyon-like channel.

(4) The spillway channel joins a watercourse from the adjacent valley at a point approximately 340 feet downstream of the crest.

(5) The spillway channel conducts flow away from the dam and releases within the capacity of the spillway should not endanger the dam.

(6) The emergency spillway, a shallow broad-crested trapezoidal section is located in the gently sloping hillside of the left (west) abutment. The spillway is moderately eroded throughout.

(7) An earthen berm that joins the dam parallels the spillway outlet and serves to confine flow to the channel and protect the dam.

(8) A 6-inch pipe that reduces to a 4-inch pipe at the control valve is provided to dewater the lake. The valve is located near the downstream toe of the dam.

(9) The original stream channel abuts the dam.

d. Overtopping Potential. The spillways (principal and emergency) are inadequate to pass the probable maximum flood, or 1/2 the probable maximum flood, or the 1 percent chance (100-yr. frequency) flood without overtopping the dam. The spillways are adequate, however to pass the 0.1 percent chance (10-yr. frequency) flood without overtopping the dam. The results of the dam overtopping analysis are as follows:

<u>Ratio</u>	<u>Q-Peak</u>	<u>Max. Lake</u>	<u>Max. Depth (Ft.)</u>	<u>Duration of</u>
<u>of PMF</u>	<u>Outflow (cfs)</u>	<u>W.S. Elev.</u>	<u>of Flow over Dam</u>	<u>Overtopping</u>
			<u>(Elev. 632.9)</u>	<u>of Dam (Hrs.)</u>
0.09	907	632.9	0.0	0.0
0.50	7,726	636.2	3.3	6.2
1.00	16,462	637.9	5.0	7.4
100-Yr. Flood	2,250	634.1	1.2	1.2
10-Yr. Flood	851	632.9	0.0	0.0

Elevation 632.9 was found to be the lowest point in the dam crest. The flow safely passing the spillway just prior to overtopping amounts to about 907 cfs, which is equivalent to about 9 percent of the probable maximum flood inflow. During peak flow of the probable maximum flood, the greatest depth of flow over the dam is projected to be 5.0 feet and overtopping will extend across the entire length of the dam.

e. Evaluation. Experience with embankments constructed of similar material (a gravelly red clay) to that used to construct this dam have shown evidence that the material under certain conditions such as high velocity flow, can be very erodible. Examples of such erosion are apparent at each of the spillways. Such a condition exists during the PMF when large lake outflow, accompanied by high flow velocities,

occurs. For the PMP condition where the depth of flow over the dam crest, a maximum of 5.0 feet, and the duration of flow over the dam, 7.4 hours, are substantial, damage by erosion to the crest and downstream face of the dam is expected. The extent of these damages is not predictable, however, there is a possibility that they could result in failure of the dam.

f. References. Procedures and data for determining the probable maximum flood, the 100-year frequency flood, the 10-year frequency flood, and the discharge rating curve for flow over the spillways and the dam crest are presented on Pages B-1 and B-2 of the Appendix. A listing of the HEC-1 (Dam Safety Version) input data is shown on Pages B-3 thru B-5 of the Appendix. A copy of the computer output tables entitled "Summary of Dam Safety Analysis" for ratios of the PMP, the 100-year flood, and the 10-year flood, are presented on Page B-6. The inflow and outflow hydrographs for the probable maximum flood are shown on Page B-7 of the Appendix. Area-storage curves for the reservoir are shown on Plate 5 and the spillway rating curves are shown on Plate 6 of the report.

SECTION 6 - STRUCTURAL STABILITY

6.1 EVALUATION OF STRUCTURAL STABILITY

a. Visual Observations. Visual observations which adversely affect the structural stability of the dam are discussed in Section 3, paragraph 3.1c.

b. Design and Construction Data. No design or construction data relating to the structural stability of the dam are known to exist. It was reported that records of test borings taken at the dam site prior to construction are no longer available. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available, which is considered a deficiency. These seepage and stability analyses should be performed for appropriate loading conditions (including earthquake loads) and made a matter of record.

c. Operating Records. With the exception of the valve on the lake drawdown pipe, no appurtenant structures or facilities requiring operation exist at this dam. According to a representative of the Owner, no records are kept of the lake level, spillway discharge, dam settlement, or seepage.

d. Post Construction Changes. The Owner's representative also reported that no post construction changes have been made or have occurred which would affect the structural stability of the dam.

e. Seismic Stability. The dam is located within a Zone II seismic probability area and an earthquake of the magnitude predicted for this area is not expected to produce a hazardous condition to the dam, provided that static stability conditions are satisfactory and conventional safety margins exist.

SECTION 7 - ASSESSMENT/REMEDIAL MEASURES

7.1 DAM ASSESSMENT

a. Safety. A hydraulic analysis indicated that the spillways (principal plus emergency) are capable of passing lake outflow of about 870 cfs without the level of the lake exceeding the low point in the top of the dam. A hydrologic analysis of the lake watershed area, as discussed in Section 5, paragraph 5.1d, indicates that for storm runoff of probable maximum flood magnitude, the lake outflow would be about 16,460 cfs, and that for the 1 percent chance (100-year frequency) flood, the lake outflow would be about 2,250 cfs. A similar analysis indicated that for the 0.1 percent (10-year frequency) flood, the lake outflow would be approximately 850 cfs.

Several items were noticed during the inspection that could adversely affect the safety of the dam. These items include seepage, the deteriorating condition of the spillway outlets, and the lack of adequate erosion protection along the upstream face of the dam.

Seepage and stability analyses of the dam were not available for review and therefore no judgment could be made with respect to the structural stability of the dam.

b. Adequacy of Information. Due to lack of design and construction data, the assessments reported herein were based on external conditions as determined during the visual inspection. The assessments of the hydrology of the watershed and capacities of the spillways were based on a hydrologic/hydraulic study as indicated in Section 5. Seepage and stability analyses comparable to the requirements of "Recommended Guidelines for Safety Inspection of Dams" were not available, which is considered a deficiency.

c. Urgency. The items concerning the safety of the dam noted in paragraph 7.1a and the remedial measures recommended in paragraph 7.2 should be accomplished within a reasonable time. It is recommended, however, that priority be given to remedying the problem of erosion at both the principal and emergency spillways and to increasing the capacity of the spillway outlets which are considered to be seriously inadequate.

d. Necessity for Phase II. Based on the results of the Phase I inspection, a Phase II investigation is not recommended.

e. Seismic Stability. The dam is located within a Zone II seismic probability area and an earthquake of the magnitude predicted for this area is not expected to produce a hazardous condition to the dam, provided that static stability conditions are satisfactory and conventional safety margins exist.

7.2 REMEDIAL MEASURES

a. Recommendations. The following actions are recommended:

(1) Based upon criteria set forth in the recommended guidelines, alterations to the design of the dam should be made in order to pass lake outflow resulting from a storm of probable maximum flood magnitude.

(2) Obtain the necessary soil data and perform dam seepage and stability analyses in order to determine the structural stability of the dam for all operational conditions. Seepage and stability analyses should be performed by a qualified professional engineer experienced in the design and construction of earthen dams.

b. Operations and Maintenance (O & M) Procedures. The following O & M Procedures are recommended:

(1) Provide some means of controlling seepage evident in the area adjacent to the downstream toe near the center of the dam. Uncontrolled seepage can lead to a piping condition which could result in failure of the dam. Drainage of the areas affected by seepage including elimination of the marshy area just downstream of the dam should be one of the objectives of the seepage control measures since saturation of the soil weakens the foundation which could impair the stability of the dam.




(2) Provide some form of protection at the spillways in order to prevent erosion by lake outflow or overland drainage. In the case of the principal spillway measures should be undertaken to insure the stability of the channel banks, which are considered to be overly steep. Failure of the channel banks could result in blockage of the spillway outlet which could lead to overtopping and possibly failure of the dam. Continued erosion of the emergency spillway could lower the crest and promote progressive erosion.


(3) Provide some form of protection other than grass for the upstream face of the dam at and above the normal waterline in order to prevent erosion. A grass covered slope is not considered adequate protection to prevent erosion by wave action or by a fluctuating lake level.

(4) Remove the beaver dam that obstructs the downstream channel. Obstructions within the channel will restrict the capacity of the outlet which could result in flooding of the area below the dam and conditions unfavorable to the structural stability of the dam.

(5) Provide maintenance of all areas of the dam and spillways on a regularly scheduled basis in order to insure features of being in satisfactory operational condition.

(6) A detailed inspection of the dam should be instituted on a regular basis by an engineer experienced in the design and construction of dams. It is also recommended, for future reference, that records be kept of all inspections made and remedial measures taken.






HIDDEN VALLEY LAKE




SCALE IN FEET
(CONTOUR INTERVAL 20 FEET)

LAKE WATERSHED MAP




PLAN OF DAM
SCALE: 1" = 50'




DAM CREST
SCALE: 2" V., 1" = 50' H.

HIDDEN VALLEY LAKE
DAM PLAN & PROFILE
Horner & Shifrin, Inc. Nov. 1979


12




DAM CROSS-SECTION STA. 1+62
 SCALES: 1"=10'V., 1"=20'H.



PROFILE SPILLWAY CHANNEL
 SCALES: 1"=10'V., 1"=20'H.




SECTION STA. 1+62
 1"=10' V., 1"=20' H.



SPILLWAY CHANNEL
 1"=10' V., 1"=20' H.

HIDDEN VALLEY LAKE
 DAM CROSS-SECTION &
 SPILLWAY PROFILE
 Horner & Shifrin, Inc. Nov. 1979

12



PRINCIPAL & EMERGENCY
SPILLWAYS

HIDDEN VALLEY LAKE
SPILLWAY RATING CURVE

Horner & Shifrin, Inc.


Nov. 1979


00 DISCHARGE (cfs), 8000

10000

12000

PLATE 5





HIDDEN VALLEY LAKE
 AREA-STORAGE CURVES
 Horner & Shifrin, Inc. Nov. 1979

(ACRES) 150
 (ACRE-FT.) 3000

200
 4000

250
 5000

PLATE 6

APPENDIX A
INSPECTION PHOTOGRAPHS



NO. 1: UPSTREAM FACE OF DAM



NO. 2: DOWNSTREAM FACE OF DAM



NO. 3: PRINCIPAL SPILLWAY CREST (LOOKING DOWNSTREAM)




NO. 4: ROCK FALLS AT PRINCIPAL SPILLWAY OUTLET CHANNEL




NO. 5: SLOUGHING AND CRACKING OF SPILLWAY CHANNEL BANK



NO. 6: DOWNSTREAM SECTION OF SPILLWAY CHANNEL




NO. 7: EMERGENCY SPILLWAY CREST



NO. 8: EMERGENCY SPILLWAY CHANNEL (LOOKING DOWNSTREAM FROM CREST)




NO. 9: SEEPAGE AREA AT BASE OF DAM



NO. 10: POOL IN ORIGINAL STREAM CHANNEL AT TOE OF DAM



NO. 11: BEAVER DAM ACROSS DOWNSTREAM CHANNEL



NO. 12: VALVE ON LAKE DRAWDOWN PIPE

APPENDIX E

HYDROLOGIC AND HYDRAULIC ANALYSIS

HYDROLOGIC AND HYDRAULIC COMPUTATIONS

1. The HEC-1 Dam Safety Version (July 1978, Modified 26 February 1979) program was used to develop inflow and outflow hydrographs and dam overtopping analyses, with hydrologic inputs as follows:

a. Probable maximum precipitation (200 sq. mile, 24-hour value equals 26.3 inches) from Hydrometeorological Report No. 33. The precipitation data used in the analysis of the 1 percent (100-year frequency) flood and the 0.1 percent (10-year frequency) flood was provided by the St. Louis District, Corps of Engineers.

b. Drainage area = 1.76 square miles = 1,130 acres.

c. SCS parameters:

Soil Group C = 100 percent

Soil type CN = 88 (AMC III, PMF condition)

= 75 (AMC II, 100-yr. and 10-year flood conditions)

Time of Concentration (T_c) = $\left(\frac{11.9L^3}{H}\right)^{0.385}$

Lag Time = 0.60 T_c = 0.28 hours

Where; T_c = Travel time of water from hydraulically most distant point to point of interest, hours.
 L = Length of longest watercourse, miles.
 H = Elevation difference, feet.

2. The principal and emergency spillway sections consist essentially of broad-crested, trapezoidal sections for which conventional weir formulas do not apply.

Spillway release rates for these sections were determined as follows:

- a. Spillway crest section properties (area, "a" and top width, "t") were computed for various depths, "d."
- b. It was assumed that flow over the spillway crest would occur at critical depth. Flow at critical depth was computed as $Q_c = \left(\frac{d^3}{t}\right)^{0.5}$ for the various depths, "d." Corresponding velocities (v_c) and velocity heads (H_{vc}) were determined using conventional formulas.
- c. Static lake levels corresponding to the various values passing the spillway were computed as critical depths plus critical velocity head ($d_c + H_{vc}$), and the relationship between lake level and spillway discharge was thus obtained. This procedure neglects the minor insignificant friction losses across the length of the spillway.
- d. The discharges for the principal and emergency spillways for equal elevations were summated for entry on the Y4 and Y5 cards.

3. The profile of the dam crest between the principal spillway and emergency spillway is irregular and flow over the dam crest cannot be determined by conventional weir formulas. Crest length and elevation data for the dam crest proper were entered into the HEC-1 Program on the \$L and the \$V cards. The program computes internally the flow over the dam crest and adds this flow to the flow over the principal and emergency spillways as entered on the Y4 and Y5 cards.

ANALYSIS OF DAM OVERTOPPING USING RATIOS OF FPM
 HYDROLOGIC-HYDRAULIC ANALYSIS OF SAFETY OF HIGDON VALLEY LAKE DAM

STATION	INFLW HYDROGRAPH	RAM	RECEPVSIS ROUTING BY MODIFIED PULS	RAM	RECEPVSIS ROUTING BY MODIFIED PULS	RAM	RECEPVSIS ROUTING BY MODIFIED PULS	RAM
A1	288	0	5	0	0	0	0	0
A2	0.08	1	1	1	1	1	1	1
A3	1	1	1	1	1	1	1	1
B1	1	1	1	1	1	1	1	1
J1	1	1	1	1	1	1	1	1
K1	1	1	1	1	1	1	1	1
M1	1	1	1	1	1	1	1	1
P1	1	1	1	1	1	1	1	1
T1	1	1	1	1	1	1	1	1
Y1	1	1	1	1	1	1	1	1
Y2	1	1	1	1	1	1	1	1
Y3	1	1	1	1	1	1	1	1
Y4	1	1	1	1	1	1	1	1
Y5	1	1	1	1	1	1	1	1
Y6	1	1	1	1	1	1	1	1
Y7	1	1	1	1	1	1	1	1
Y8	1	1	1	1	1	1	1	1
Y9	1	1	1	1	1	1	1	1
Y10	1	1	1	1	1	1	1	1
Y11	1	1	1	1	1	1	1	1
Y12	1	1	1	1	1	1	1	1
Y13	1	1	1	1	1	1	1	1
Y14	1	1	1	1	1	1	1	1
Y15	1	1	1	1	1	1	1	1
Y16	1	1	1	1	1	1	1	1
Y17	1	1	1	1	1	1	1	1
Y18	1	1	1	1	1	1	1	1
Y19	1	1	1	1	1	1	1	1
Y20	1	1	1	1	1	1	1	1
Y21	1	1	1	1	1	1	1	1
Y22	1	1	1	1	1	1	1	1
Y23	1	1	1	1	1	1	1	1
Y24	1	1	1	1	1	1	1	1
Y25	1	1	1	1	1	1	1	1
Y26	1	1	1	1	1	1	1	1
Y27	1	1	1	1	1	1	1	1
Y28	1	1	1	1	1	1	1	1
Y29	1	1	1	1	1	1	1	1
Y30	1	1	1	1	1	1	1	1
Y31	1	1	1	1	1	1	1	1
Y32	1	1	1	1	1	1	1	1
Y33	1	1	1	1	1	1	1	1
Y34	1	1	1	1	1	1	1	1
Y35	1	1	1	1	1	1	1	1
Y36	1	1	1	1	1	1	1	1
Y37	1	1	1	1	1	1	1	1
Y38	1	1	1	1	1	1	1	1
Y39	1	1	1	1	1	1	1	1
Y40	1	1	1	1	1	1	1	1
Y41	1	1	1	1	1	1	1	1
Y42	1	1	1	1	1	1	1	1
Y43	1	1	1	1	1	1	1	1
Y44	1	1	1	1	1	1	1	1
Y45	1	1	1	1	1	1	1	1
Y46	1	1	1	1	1	1	1	1
Y47	1	1	1	1	1	1	1	1
Y48	1	1	1	1	1	1	1	1
Y49	1	1	1	1	1	1	1	1
Y50	1	1	1	1	1	1	1	1
Y51	1	1	1	1	1	1	1	1
Y52	1	1	1	1	1	1	1	1
Y53	1	1	1	1	1	1	1	1
Y54	1	1	1	1	1	1	1	1
Y55	1	1	1	1	1	1	1	1
Y56	1	1	1	1	1	1	1	1
Y57	1	1	1	1	1	1	1	1
Y58	1	1	1	1	1	1	1	1
Y59	1	1	1	1	1	1	1	1
Y60	1	1	1	1	1	1	1	1
Y61	1	1	1	1	1	1	1	1
Y62	1	1	1	1	1	1	1	1
Y63	1	1	1	1	1	1	1	1
Y64	1	1	1	1	1	1	1	1
Y65	1	1	1	1	1	1	1	1
Y66	1	1	1	1	1	1	1	1
Y67	1	1	1	1	1	1	1	1
Y68	1	1	1	1	1	1	1	1
Y69	1	1	1	1	1	1	1	1
Y70	1	1	1	1	1	1	1	1
Y71	1	1	1	1	1	1	1	1
Y72	1	1	1	1	1	1	1	1
Y73	1	1	1	1	1	1	1	1
Y74	1	1	1	1	1	1	1	1
Y75	1	1	1	1	1	1	1	1
Y76	1	1	1	1	1	1	1	1
Y77	1	1	1	1	1	1	1	1
Y78	1	1	1	1	1	1	1	1
Y79	1	1	1	1	1	1	1	1
Y80	1	1	1	1	1	1	1	1
Y81	1	1	1	1	1	1	1	1
Y82	1	1	1	1	1	1	1	1
Y83	1	1	1	1	1	1	1	1
Y84	1	1	1	1	1	1	1	1
Y85	1	1	1	1	1	1	1	1
Y86	1	1	1	1	1	1	1	1
Y87	1	1	1	1	1	1	1	1
Y88	1	1	1	1	1	1	1	1
Y89	1	1	1	1	1	1	1	1
Y90	1	1	1	1	1	1	1	1
Y91	1	1	1	1	1	1	1	1
Y92	1	1	1	1	1	1	1	1
Y93	1	1	1	1	1	1	1	1
Y94	1	1	1	1	1	1	1	1
Y95	1	1	1	1	1	1	1	1
Y96	1	1	1	1	1	1	1	1
Y97	1	1	1	1	1	1	1	1
Y98	1	1	1	1	1	1	1	1
Y99	1	1	1	1	1	1	1	1
Y100	1	1	1	1	1	1	1	1

SUMMARY OF DAM SAFETY ANALYSIS
RATIOS OF PMF

RATIO OF PMF	INITIAL VALUE		SPILLWAY CREST		TOP OF DAM		TIME OF FAILURE HOURS
	ELEVATION STORAGE OUTLET	MAXIMUM STORAGE AC-FT	MAXIMUM CUTFLOW CFS	DURATION OVER TOP HOURS	MAX CUTFLOW	MAX HOURS	
1.00	632.00	305.0	630.00	0.00	632.00	305.0	0.00
.98	632.77	368.	782.	.25	632.00	305.0	0.00
.90	632.95	399.	1055.	.28	632.00	305.0	0.00
.80	632.11	509.	7726.	6.17	632.00	305.0	0.00
1.00	632.10	577.	16462.	7.42	632.00	305.0	0.00

SUMMARY OF DAM SAFETY ANALYSIS
100-YR. FLOOD

RATIO OF PMF	INITIAL VALUE		SPILLWAY CREST		TOP OF DAM		TIME OF FAILURE HOURS
	ELEVATION STORAGE OUTLET	MAXIMUM STORAGE AC-FT	MAXIMUM CUTFLOW CFS	DURATION OVER TOP HOURS	MAX CUTFLOW	MAX HOURS	
1.00	630.00	305.0	630.00	0.00	632.00	305.0	0.00
.98	634.12	434.	2259.	1.17	632.00	305.0	0.00


SUMMARY OF DAM SAFETY ANALYSIS
10-YR. FLOOD

RATIO OF PMF	INITIAL VALUE		SPILLWAY CREST		TOP OF DAM		TIME OF FAILURE HOURS
	ELEVATION STORAGE OUTLET	MAXIMUM STORAGE AC-FT	MAXIMUM CUTFLOW CFS	DURATION OVER TOP HOURS	MAX CUTFLOW	MAX HOURS	
1.00	630.00	305.0	630.00	0.00	632.00	305.0	0.00
.87	632.87	351.	851.	0.00	632.00	305.0	0.00

HIDDEN VALLEY LAKE PMF INFLOW & OUTFLOW HYDROGRAPHS

Horner & Shifrin, Inc.

Nov. 1979



3
 14
 15
 16
 17
 18
 19
 20
 21
 22
 23
 24
 25
 26
 27
 28
 29
 30
 31
 32
 33
 34
 35
 36
 37
 38
 39
 40
 41
 42
 43
 44
 45
 46
 47
 48
 49
 50
 51
 52
 53
 54
 55
 56
 57
 58
 59
 60
 61
 62
 63
 64
 65
 66
 67
 68
 69
 70
 71
 72
 73
 74
 75
 76
 77
 78
 79
 80
 81
 82
 83
 84
 85
 86
 87
 88
 89
 90
 91
 92
 93
 94
 95
 96
 97
 98
 99
 100

