


AD-A106 050

NEW YORK STATE DEPT OF ENVIRONMENTAL CONSERVATION ALBANY F/8 13/13  
NATIONAL DAM SAFETY PROGRAM, GENEAGANTSLET LAKE DAM (INVENTORY N--ETC(U)  
MAR 81 6 KOCH DACW51-79-C-0001

UNCLASSIFIED

NL

1 of 1  
200 DEC



AD A106050

DTIC FILE COPY

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Inspection-Report Genegantslet Lake Dam Susquehanna River Basin, Chenango County, N.Y. Inventory No. 846		5. TYPE OF REPORT & PERIOD COVERED Phase I Inspection Report National Dam Safety Program
7. AUTHOR National Dam Safety Program. Genegants- let Lake Dam (Inventory Number NY. 846), GEORGE ROCK Susquehanna River Basin, Chenango County, New York. Phase I Inspection Report,		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING O. New York State Department of Environmental Conservation 50 Wolf Road Albany, New York 12233		CONTRACT OR GRANT NUMBER(s) DACW51-79-C-0001
11. CONTROLLING OFFICE NAME AND ADDRESS Department of the Army 26 Federal Plaza New York District, CofE New York, New York 10287		12. REPORT DATE 31 March 1981
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) Department of the Army 26 Federal Plaza New York District, CofE New York, NY 10287		13. NUMBER OF PAGES 74
16. DISTRIBUTION STATEMENT (of this Report)		15. SECURITY CLASS. (of this report) UNCLASSIFIED
Approved for public release; Distribution unlimited.		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dam Safety National Dam Safety Program Visual Inspection Hydrology, Structural Stability		Genegantslet Lake Dam Chenango County Susquehanna River Basin
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report provides information and analysis on the physical condition of the dam as of the report date. Information and analysis are based on visual inspection of the dam by the performing organization. Examination of available documents and a visual inspection of the dam did not reveal conditions which constitute an immediate hazard to human life or property. However, the dam has some deficiencies which need to be evaluated and remedied.		

LEVEL

DTIC  
OCT 22 1981

\*Original contains color plates: All DTIC reproductions will be in black and white\*

cont

Using the Corps of Engineers' Screening Criteria for initial review of spillway adequacy, it has been determined that the dam would be overtopped by all storms exceeding 5% of the Probable Maximum Flood (PMF) inflows. While this dam has withstood overtopping in the past, it cannot be assumed that overtopping will not eventually cause the dam to fail. Since failure of the dam would increase the hazard to downstream residents, the spillway capacity is adjudged as seriously inadequate and the dam is assessed as "unsafe, non emergency".

The classification of "unsafe" applied to a dam because of a seriously inadequate spillway is not meant to connote the same degree of emergency as would be associated with an "unsafe" classification applied for a structural deficiency. It does mean that there appears to be a serious deficiency in spillway capacity and if a severe storm were to occur, overtopping and failure of the dam could take place, significantly increasing the hazard to loss of downstream of the dam.

Inspection of the dam also revealed that there was a seepage problem on this structure. Seepage was exiting on the downstream slope and at the toe in the embankment section at the right end of the dam. There were also several locations where leakage was noted through the laid up stone portion of the dam.

It is recommended that within 3 months of the date of notification of the owner, a hydrologic/hydraulic investigation of the structure should be commenced. Investigation into the seepage problem should also be commenced within 3 months. Mitigating measures deemed necessary as a result of these investigations should be completed within 18 months.

Several other deficiencies were noted on this structure. These should be corrected within 12 months of the date of notification. Among the items which should be corrected are the eroded area on the downstream slope at the left end of the dam, gaps between sections of pipe which need to be filled with mortar, displaced stones on the laid up stone portion of the dam, brush and small trees growing on the embankment, an outlet channel from the spillway

Accession for	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
NTIS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
DTIC	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Justification			
By	Distribution/Availability Codes		
Dist	Avail and/or	Special	
A			

AD A106050

SUSQUEHANNA RIVER BASIN  
GENEGANTSLET LAKE DAM

CHENANGO COUNTY, NEW YORK  
INVENTORY NO. N.Y. 846

PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM



APPROVED FOR PUBLIC RELEASE;  
DISTRIBUTION UNLIMITED

DTIC FILE COPY

NEW YORK DISTRICT CORPS OF ENGINEERS  
FEBRUARY, 1981

81 10 20

## PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I Investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM  
GENEGANTSLET LAKE DAM  
SUSQUEHANNA RIVER BASIN  
CHENANGO COUNTY, NEW YORK

TABLE OF CONTENTS

	<u>PAGE NO.</u>
- ASSESSMENT	-
- OVERVIEW PHOTOGRAPH	-
1 PROJECT INFORMATION	1
1.1 GENERAL	1
1.2 DESCRIPTION OF PROJECT	1
1.3 PERTINENT DATA	2
2. ENGINEERING DATA	4
2.1 GEOTECHNICAL DATA	4
2.2 DESIGN RECORDS	4
2.3 CONSTRUCTION RECORDS	4
2.4 OPERATION RECORD	4
2.5 EVALUATION OF DATA	4
3. VISUAL INSPECTION	5
3.1 FINDINGS	5
3.2 EVALUATION OF OBSERVATIONS	6
4. OPERATION AND MAINTENANCE PROCEDURES	7
4.1 PROCEDURE	7
4.2 MAINTENANCE OF DAM	7
4.3 WARNING SYSTEM IN EFFECT	7
4.4 EVALUATION	7

	<u>PAGE NO.</u>
5. HYDROLOGIC/HYDRAULIC	8
5.1 DRAINAGE AREA CHARACTERISTICS	8
5.2 ANALYSIS CRITERIA	8
5.3 SPILLWAY CAPACITY	8
5.4 RESERVOIR CAPACITY	8
5.5 FLOODS OF RECORD	8
5.6 OVERTOPPING POTENTIAL	8
5.7 EVALUATION	9
6. STRUCTURAL STABILITY	10
6.1 EVALUATION	10
7 ASSESSMENT/RECOMMENDATIONS	11
7.1 ASSESSMENT	11
7.2 RECOMMENDED MEASURES	11

#### APPENDIX

- A. PHOTOGRAPHS
- B. VISUAL INSPECTION CHECKLIST
- C. HYDROLOGIC/HYDRAULIC ENGINEERING DATA AND COMPUTATIONS
- D. REFERENCES
- E. DRAWINGS

Phase I Inspection Report  
National Dam Safety Program

Name of Dam: Genegantslet Lake Dam (I.D. NY 846)  
State Located: New York  
County : Chenango  
Watershed: Susquehanna River Basin  
Stream: Unnamed tributary of Genegantslet Creek  
Date of Inspection: October 22, 1980

ASSESSMENT

Examination of available documents and a visual inspection of the dam did not reveal conditions which constitute an immediate hazard to human life or property. However, the dam has some deficiencies which need to be evaluated and remedied.

Using the Corps of Engineers' Screening Criteria for initial review of spillway adequacy, it has been determined that the dam would be overtopped by all storms exceeding 5% of the Probable Maximum Flood (PMF) inflows. While this dam has withstood overtopping in the past, it cannot be assured that overtopping will not eventually cause the dam to fail. Since failure of the dam would increase the hazard to downstream residents, the spillway capacity is adjudged as seriously inadequate and the dam is assessed as "unsafe, non emergency".

The classification of "unsafe" applied to a dam because of a seriously inadequate spillway is not meant to connote the same degree of emergency as would be associated with an "unsafe" classification applied for a structural deficiency. It does mean that there appears to be a serious deficiency in spillway capacity and if a severe storm were to occur, overtopping and failure of the dam could take place, significantly increasing the hazard to loss of downstream of the dam.

Inspection of the dam also revealed that there was a seepage problem on this structure. Seepage was exiting on the downstream slope and at the toe in the embankment section at the right end of the dam. There were also several locations where leakage was noted through the laid up stone portion of the dam.

It is recommended that within 3 months of the date of notification of the owner, a hydrologic/hydraulic investigation of the structure should be commenced. Investigation into the seepage problem should also be commenced within 3 months. Mitigating measures deemed necessary as a result of these investigations should be completed within 18 months.

Several other deficiencies were noted on this structure. These should be corrected within 12 months of the date of notification. Among the items which should be corrected are the eroded area on the downstream slope at the left end of the dam, gaps between sections of pipe which need to be filled with mortar, displaced stones on the laid up stone portion of the dam, brush and small trees growing on the embankment, an outlet channel from the spillway



conduit which runs along the base of the dam, and the following safety  
action plan



---

George Koch  
Chief, Dam Safety Section  
New York State Department  
of Environmental Conservation  
NY License No. 45937

Approved by:



---

Col. W. M. Smith, Jr.  
New York District Engineer

Date:

---

81 MAR 1961



OVERVIEW  
GENEGANTSLET LAKE DAM  
I.D. No. NY 846

Phase I Inspection Report  
National Dam Safety Program  
Genegantslet Lake Dam  
I.D. No. Ny 846  
#94D-3437  
Susquehanna River Basin  
Chenango County, New York

SECTION 1: PROJECT INFORMATION

1.1 GENERAL

a. Authority

The Phase I inspection reported herein was authorized by the Department of the Army, New York District, Corps of Engineers, to fulfill the requirements of the National Dam Inspection Act, Public Law 92-367.

b. Purpose of Inspection

This inspection was conducted to evaluate the existing conditions of the dam, to identify deficiencies and hazardous conditions, to determine if these deficiencies constitute hazards to life and property, and to recommend remedial measures where required.

1.2 DESCRIPTION OF PROJECT

a. Description of Dam

The Genegantslet Lake Dam is an earth fill and laid up stone dam with a drop inlet spillway and a conduit passing through the embankment.

The dam is approximately 300 feet long and about 10 feet high. The upstream slope of the dam is composed of earth fill. The laid up stone is exposed on the center portion of the downstream face. The earth fill extends over the top of the laid up stone, forming the crest along the entire dam. Earth and rock fill form the downstream slope at either end of the structure.

The spillway consists of a 48 inch reinforced concrete pipe flowing into the base of a drop inlet structure. There are wooden stop logs in the center of the structure which are used to control the water level in the lake. When the stop logs are in place, water must flow over them and then to the outlet pipe. If the stop logs are removed, the 48 inch pipe would act as a reservoir drain.

The top of the drop inlet structure is open to permit flow. The crest on the upstream face is 2 feet below the top of the structure providing additional capacity. All of the openings have screens to prevent debris from entering the drop inlet.

There is a 48 inch concrete outlet pipe leading from the base of the drop inlet to a concrete manhole 25 feet downstream. Another 48 inch pipe extends 116 feet from the manhole to a headwall at the outlet.

b. Location

This dam is located in the Town of Mc Donough, off Moon Hill Road on an unnamed tributary of the Genegantslet Creek. The dam is approximately 3/4 mile north of the village of Mc Donough.

c. Size Classification

The dam is 9.5 feet high and has a storage capacity of 2,000 acre-feet. Therefore, the dam is in the small size category as defined by the "Recommended Guidelines for Safety Inspection of Dams".

d. Hazard Classification

The dam is classified as "high" hazard due to the presence of one house immediately downstream of the dam and 6 additional houses plus one trailer located near the stream channel in the Village of Mc Donough.

e. Ownership

The dam is owned by the Genegantslet Lake Association, Inc. The secretary-treasurer of the association is Frank Ulrichs, 127 South Broad Street, Norwich, New York 13815. Mr. Ulrich's telephone number is (607) 334-3789.

f. Purpose of Dam

The dam is used to maintain the water surface of Genegantslet Lake for recreational purposes.

g. Design and Construction History

This dam was constructed around 1900. No information was available concerning the original design or construction of the dam. In 1947, the owner contracted with Les Strong Construction Company of Whitney Point, New York to perform work designed to reduce the leakage through the dam. This same company made further repairs in 1955. The 1955 work included placing shale fill on the upstream slope to again reduce leakage. A 36 inch iron pipe through the dam was sealed as part of this work, since it was considered to be a major source of the leakage.

Major modifications to the structure were made in 1965. At that time, clay fill was placed on the upstream face and the new conduit was installed to provide some control over the lake level. The design engineer for these modifications was Mr. Carl Crandall, P.E., of Ithaca, New York.

h. Normal Operating Procedures

Stop logs to within about 1/2 foot of the lower crest of the drop inlet maintain the water surface at approximately this elevation from April thru October. In October, three stop logs (2 inch by 12 inch) are removed to lower the water surface during the winter months.

1.3 PERTINENT DATA

<u>a. Drainage Area (sq. mi.)</u>	5.04
<u>b. Discharge at Dam (cfs)</u> Water Surface at Top of Dam	55
<u>c. Elevations- (Plan Datum)</u> Top of Dam and Top of Drop Inlet	101.3
Crest of Drop Inlet	99.3
Invert of Inlet Pipe	90.3
Invert of Outlet of Pipe	90.3

d. Reservoir-Surface Area (acres)

Top of Dam	114
Crest of Drop Inlet	105

e. Storage Capacity (acre-feet)

Top of Dam	1969
Crest of Drop Inlet	1750

f. Dam

Type: Laid up stone and earth embankment

Dam Length (ft)	300
Crest Width (ft)	35

g. Spillway

Type: Concrete drop inlet approximately 6 ft. by 6 ft, rising 11 feet above the invert of 48 inch diameter concrete pipes on both upstream and downstream ends. Stop logs in center of structure can be used to control water surface.

Weir length (ft): low level	6.1
Conduit length (ft): upstream of drop inlet	31
downstream of drop inlet	142

h. Reservoir Drain

Type: 48 inch concrete conduit into drop inlet

Control: Stop logs can be removed down to invert elevation.

## SECTION 2: ENGINEERING DATA

### 2.1 GEOTECHNICAL DATA

#### a. Geology

The Ganegantslet Lake Dam is located in the Glaciated Allegheny Plateau of physiographic province of New York State. This plateau is underlaid by a great thickness of sedimentary rocks from the Devonian Era which lie almost horizontal. Severe trenching by streams and glacial erosion has carved the upland into a rugged terrain. The Susquehanna Hills rise to elevations of up to 1700 feet between the rolling, relatively narrow valleys. The surficial soils and features of the area are the result of glaciations during the Cenozoic Era, the last of which was the Wisconsin glaciation.

A review of the "Brittle Structures Map of the State of New York" indicated that there are no faults in the immediate vicinity of the dam.

#### b. Subsurface Investigations

No records of any subsurface investigations performed for this structure were available. The only subsurface information available was from a 1925 inspection report which stated that the foundation of the dam consisted of clay and hardpan.

### 2.2 DESIGN RECORDS

No records were available concerning the original design of this structure. An engineer's report and plans for the modifications made to the structure in 1965 were available. This design work was performed by Mr. Carl Crandall, P.E., of Ithaca, New York.

### 2.3 CONSTRUCTION RECORDS

No records exist for the original construction of this structure. A contract between the owner and the Les Strong Construction Company of Whitney Point, New York was available, and it described the repairs made to the dam in 1947. The same company made additional repairs in 1955. There were several photographs in the files which were taken during this construction. The only records from the 1965 modifications were the plans prepared by Mr. Crandall and photographs taken during construction.

### 2.4 OPERATION RECORDS

There are no regular operation records maintained for this structure.

### 2.5 EVALUATION OF DATA

Data available for the preparation of this report was somewhat limited. In addition, several of the dimensions shown on the plans, such as the size of the riser did not agree with the actual dimensions measured during the inspection.

## SECTION 3: VISUAL INSPECTION

### 3.1 FINDINGS

#### a. General

Visual inspection of the Genegantslet Lake Dam was conducted on October 22, 1980. The weather was overcast and the temperature was in the forties. The water surface at the time of the inspection was 2.5 feet below the top of the drop inlet structure. Water was flowing over the stop logs inside the drop inlet.

#### b. Dam

Several deficiencies were observed on this structure. The most serious deficiency noted was the seepage exiting both on the downstream slope and at the toe. The most concentrated seepage was in the embankment section between the right abutment and the center of the dam where the laid up stone face is exposed. There was also leakage through the laid up stone portion in several locations.

Another deficiency noted was erosion of embankment material on the downstream slope at the left end of the dam near the headwall for the spillway conduit. This erosion was probably caused by flow over the top of the dam.

Brush and saplings growing on the embankment and some displaced stones on the laid up stone segment were other deficiencies noted on this structure.

#### c. Spillway

The drop inlet and the outlet conduits were in good condition. Trash racks over all openings on the drop inlet prevented debris from entering the spillway. These trash racks were properly maintained and there was no accumulation of debris around the drop inlet.

The outlet conduits were composed of sections of reinforced concrete pipe which were 4 feet long. Inspection of the pipe revealed that the individual sections were not fit together tightly. Furthermore, only the bottom third of the joints between sections had been mortared. There was no mortar in the remainder of each of the joints. There was some seepage into the pipe through several of the joints. The joints where seepage was observed were approximately midway between the outlet of the pipe and the buried manhole which is downstream of the drop inlet.

The conduit upstream of the drop inlet structure extends into the lake. It was submerged and could not be observed.

#### d. Reservoir

There was no indication of soil instability in the reservoir area.

#### e. Downstream Channel

The outlet channel from the spillway conduit ran along the downstream toe of the dam. This fact may have contributed to the erosion problem beyond the head wall. The channel contained riprap but the toe of the dam was not well protected.

### 3.2 EVALUATION OF OBSERVATIONS

Visual inspection of the dam revealed several deficiencies. The following items were noted:

1. Seepage both through the embankment section at the right end of the dam and the laid up stone section.
2. Erosion of embankment material on the downstream slope at the left end of the dam.
3. There were gaps between sections of the outlet pipe. Mortar had been placed only in the bottom third of these joints.
4. There was some brush and small trees growing on the embankment.
5. There were some displaced stones on the laid up stone portion of the dam.
6. The outlet channel from the spillway ran along the toe of the dam.



## SECTION 4: OPERATION AND MAINTENANCE PROCEDURES

### 4.1 PROCEDURES

The only operating procedures for this structure involve the removal and replacement of stop logs in the drop inlet structure. Three stop logs each about (2 inch by 12 inch) are removed in October to lower the water surface during the winter months. In April, after the ice has gone out of the pond, the stop logs are replaced. When these stop logs are in place, the normal water level in the pond is about 1/2 foot below the crest of the drop inlet structure.

### 4.2 MAINTENANCE OF DAM

There are no formal maintenance procedures for this structure. Mr. Ulrichs of the Genegantslet Lake Association reported that brush and weeds are cleared annually.

### 4.3 WARNING SYSTEM IN EFFECT

No apparent warning system for evacuation of downstream residents is present.

### 4.4 EVALUATION

The operation procedures on this dam are generally satisfactory. The deficiencies noted on the structure are evidence of the need for additional maintenance efforts.

## SECTION 5: HYDROLOGIC/HYDRAULIC

### 5.1 DRAINAGE AREA CHARACTERISTICS

Delineation of the watershed draining into the reservoir pool area was made using the 7 1/2 minute USGS quadrangle sheet for Pitcher, New York. The 5.04 square mile drainage area consists of wooded lands and open fields. Hilltops at the boundary of the drainage area range from elevation 1660 to elevation 1840. Relief within the drainage area is moderate to steep with steeper slopes in the eastern portion.

### 5.2 ANALYSIS CRITERIA

The analysis of the floodwater retarding capability of this dam was performed using the Crops of Engineers HEC-1 computer program, Dam Safety version. This program uses the Snyder Synthetic Unit hydrograph method and the "Modified Puls" flood routing procedure. The spillway design flood selected for analysis was the Probable Maximum Flood (PMF) in accordance with the recommended guidelines for the U.S. Army Corps of Engineers.

### 5.3 SPILLWAY CAPACITY

The spillway consists of a drop inlet structure with 48 inch pipes going into and out of it. Wood stop logs in the center of the drop inlet structure provide some control over the level of the lake.

The spillway capacity was calculated assuming that all of the stop logs were in place. The elevation of the stop log crest was thus the same as the upstream riser crest. The crest of the remainder of the riser was two feet higher and was assumed to be equal to the top of dam elevation. The total spillway capacity for a water surface at the top of the dam was 55 cfs.

### 5.4 RESERVOIR CAPACITY

Normal storage capacity of the reservoir with the water surface at the spillway crest and the top of the dam is an additional 219 acre feet which is equivalent to a direct runoff depth of 0.81 inches over the drainage area.

### 5.5 FLOODS OF RECORD

There was no data concerning the occurrence of the maximum known flood. It was stated in the Engineer's report, prepared for the 1965 modifications, that three feet of water flowed over the dam during a flood in the mid-thirties.

### 5.6 OVERTOPPING POTENTIAL

Analyses using the PMF and one half the PMF indicates that the dam does not have sufficient spillway capacity. The inflow from the PMF is 11741 cfs and the outflow is 11449 cfs. The dam would be overtopped to a computed depth of 5.91 feet for this storm event. For the peak outflow of one-half the PMF (5612 cfs), the depth of overtopping would be 3.63 feet. All storms exceeding 5% of the PMF will result in the dam being overtopped. It was apparent from the visual inspection that the dam is overtopped frequently.

## 5.7 EVALUATION

Using the Corps of Engineer's screening criteria for initial review of spillway adequacy, it has been determined that the dam would be overtopped by all storms exceeding 5% of the PMF. While the dam has withstood overtopping in the past, the fact that the structure is composed of earth fill and laid up stone makes overtopping undesirable. The very limited spillway capacity results in frequent overtopping and it cannot be assumed that this will not eventually cause the failure of the dam. Since a failure would increase the hazard to downstream residents over that which would exist just prior to the failure, the spillway capacity is adjudged to be seriously inadequate.

## SECTION 6: STRUCTURAL STABILITY

### 6.1 EVALUATION OF STRUCTURAL STABILITY

#### a. Visual Observations

Visual observations revealed that there were several deficiencies on this structure which could affect the stability. Seepage through the dam at the right end and in the laid up stone portion was the most serious deficiency. Erosion of the embankment material on the downstream slope near the outlet to the spillway conduit was also noted. It appears that this erosion was caused by flow over the top of the dam. The outlet channel from the spillway flows along the toe of the embankment creating a potential stability problem.

#### b. Stability Evaluation

This structure is composed of earth fill and laid up stone. The earth completely covers the laid up stone at both ends of the dam, but in the center, the stone is exposed on the downstream face.

Due to the nature of the composition of this structure, a stability analysis was not considered to be feasible.

## SECTION 7: ASSESSMENT/RECOMMENDATIONS

### 7.1 ASSESSMENT

#### a. Safety

The Phase 1 inspection of the Genegantslet Lake Dam revealed that the spillway capacity is seriously inadequate and outflows from all storms exceeding 5% of the Probable Maximum Flood would overtop the dam. While the dam has withstood overtopping in the past, this regarded as undesirable. Failure of the dam would increase the hazard to downstream residents. Therefore, this is assessed as unsafe, non-emergency.

In addition to the spillway inadequacy, other deficiencies were noted which affect the safety of the structure. The most serious of these was seepage through the dam exiting along a substantial portion of the downstream toe. There was also some erosion, probably caused by flow over the top of the dam.

#### b. Adequacy of Information

The information available for the preparation of this report was somewhat limited. Plans for the 1965 modifications were used, but some of the dimensions shown on these plans did not agree with measurements made at the time of the inspection.

#### c. Need for Additional Investigations

Since the spillway has been assessed as seriously inadequate, additional hydrologic/hydraulic investigations are required to more accurately determine the site specific characteristics of the watershed. Analysis will then be required to determine how to provide the additional spillway capacity needed.

Investigation into the seepage is also required. A method of either eliminating or controlling the seepage should be devised.

#### d. Urgency

The additional hydrologic and hydraulic investigations which are needed should be commenced within 3 months of the date of notification of the owner. Investigation into the seepage problem should also be commenced within 3 months.

Mitigating measures deemed necessary as a result of the investigation should be completed within 18 months of the date of notification. Other deficiencies should be corrected within 12 months.

### 7.2 RECOMMENDED MEASURES

- a. After the hydrologic/hydraulic investigation has been completed, mitigating measures dealing with the seriously inadequate spillway should be undertaken.
- b. After the investigation into the seepage problem has been completed, appropriate remedial actions should be taken.
- c. The eroded area on the downstream slope at the left end of the dam should be refilled with compacted embankment material.
- d. Gaps between sections of the outlet pipe should be filled with mortar.
- e. The outlet channel from the spillway conduit should either be relocated away from the toe of the dam or lined with riprap to better protect the downstream toe.
- f. Displaced stones on the laid up stone portion of the dam should be replaced.

g. Brush and small trees growing on the embankment should be cut.

h. An emergency action plan for the notification of downstream residents should be developed and implemented.

APPENDIX A

PHOTOGRAPHS



Crest of embankment



View Looking Along Crest; Exposed Laid-up  
Stone on Downstream Face






Laid up Stone Exposed on Downstream Face



Laid up Stone Exposed on Downstream Face



Erosion Adjacent to Wingwall on  
Spillway Conduit



Channel Leading From Spillway Conduit;  
Flowing along Downstream Toe

Seeo



Seepage Emerging on Downstream Face Near  
Right End of Structure

APPENDIX B

VISUAL INSPECTION CHECKLIST

VISUAL INSPECTION CHECKLIST1) Basic Data

## a. General

Name of Dam GENEGANTSLET DAM  
 Fed. I.D. # 846 DEC Dam No. 940-3437  
 River Basin SUSQUEHANNA  
 Location: Town McDONOUGH County CHENANGO  
 Stream Name UN NAMED  
 Tributary of GENEGANTSLET CREEK  
 Latitude (N) 42° 31.5' Longitude (W) 75° 46.3'  
 Type of Dam EARTH & LAID UP STONE  
 Hazard Category C  
 Date(s) of Inspection 10/22/80  
 Weather Conditions 45° OVERCAST  
 Reservoir Level at Time of Inspection 2.45' BELOW TOP OF DROP INLET

b. Inspection Personnel R. WARRENDER W. LYNICK

c. Persons Contacted (Including Address & Phone No.)  
GENEGANTSLET LAKE ASSOC.  
SEC-TRES FRANK ULRICH  
127 BROAD ST. (607) 334-3789  
NORWICH, N.Y.

d. History:  
 Date Constructed ≈ 1900 Date(s) Reconstructed 1947-1955  
1965  
 Designer 1965- CARL CRANDAL PE  
 Constructed By 1947 & 55 LES STRONG CO.  
 Owner GENEGANTSLET LAKE ASSOCIATION

2) Embankment

## a. Characteristics

- (1) Embankment Material VARIABLE - EARTH & ROCK
- (2) Cutoff Type NONE
- (3) Impervious Core NONE
- (4) Internal Drainage System NONE
- (5) Miscellaneous GRASS & SMALL BRUSH COVER

## b. Crest

- (1) Vertical Alignment SOMEWHAT IRREGULAR - MIDDLE HALF IS LOWER THAN ENDS
- (2) Horizontal Alignment CURVILINEAR
- (3) Surface Cracks NONE - SOME RIVULETS WHERE MATERIAL HAS BEEN REMOVED DURING OVERTOPPING
- (4) Miscellaneous ● APPEARS TO HAVE BEEN OVERTOPPED RECENTLY - POSSIBLY SPRING OF 1980 \*

## c. Upstream Slope

- (1) Slope (Estimate) (V:H) 1:5 OR FLATTER
- (2) Undesirable Growth or Debris, Animal Burrows SOME CAT TAILS
- (3) Sloughing, Subsidence or Depressions NO

\* DISCUSSION WITH F. ULRICHS - HE SAID THAT LAST TIME DAM WAS OVERTOPPED WAS POSSIBLY FALL OF 1978

(4) Slope Protection VERY SMALL STONE ON SLOPE

(5) Surface Cracks or Movement at Toe NONE

d. Downstream Slope

(1) Slope (Estimate - V:H) VARIABLES  
1:2 ON RIGHT END TO 1:5 OR FLATTER ON LEFT

(2) Undesirable Growth or Debris, Animal Burrows BRUSH & SAPLINGS  
SPARSE GRASS - MORE LIKE WEEDS & MOSS

(3) Sloughing, Subsidence or Depressions ERODED AREAS NEAR  
RCP OUTLET AT LEFT END - PROBABLY CAUSED BY  
OVERTOPPING.

(4) Surface Cracks or Movement at Toe NONE

(5) Seepage ENTIRE RIGHT END NEAR & AT TOE FROM ABUTMENT  
TO LAIN UP STONE SECTION - ALSO SOME DOWNSTREAM  
OF MASONRY SECTION

(6) External Drainage System (Ditches, Trenches; Blanket) NONE

(7) Condition Around Outlet Structure ADDITIONAL RIP RAP NEEDED  
SOME SCOUR AT LEFT SIDE OF HEADWALL

(8) Seepage Beyond Toe NO - OUTLET STREAM RUNS ALONG  
TOE.

e. Abutments - Embankment Contact

LEFT END SATISFACTORY

93-15-3(9/80)

(1) Erosion at Contact SOME MINOR EROSION AT RIGHT END

(2) Seepage Along Contact - RIGHT ABUTMENT - ENTIRE TOE IS  
WET, PONDED

3) Drainage System

a. Description of System NONE

b. Condition of System \_\_\_\_\_

c. Discharge from Drainage System \_\_\_\_\_

4) Instrumentation (Momentum/Surveys, Observation Wells, Weirs,  
Piezometers, Etc.) \_\_\_\_\_

NONE



5) Reservoir

- a. Slopes WOODED TO EDGE OF LAKE
- b. Sedimentation NOT NOTICIBLE
- c. Unusual Conditions Which Affect Dam \_\_\_\_\_

6) Area Downstream of Dam

- a. Downstream Hazard (No. of Homes, Highways, etc.) HOUSE 750' DOWNSTREAM OF DAM - HOME ON STREAM BANK - 1 TRAILER & 6 HOUSES JUST UPSTREAM OF STATE RTE 220
- b. Seepage, Unusual Growth \_\_\_\_\_
- c. Evidence of Movement Beyond Toe of Dam NONE
- d. Condition of Downstream Channel BEYOND POINT WHERE IT TURNS AWAY FROM DAM IT IS OKAY

7) Spillway(s) (Including Discharge Conveyance Channel)

SUBMERGED RESERVOIR INLET - LEADING TO DROP INLET WITH STOP LOGS 4' RCP CONDUIT

- a. General SATISFACTORY CONDITION - DROP INLET OPENINGS ARE FULLY PROTECTED WITH TRASH RACKS  
CONDUIT WENT FROM D.I. TO A MANHOLE ABOUT 30', THEN WENT 120' TO OUTLET. THERE WAS SLIGHT BEND IN PIPE AT ABOUT 60' FROM MANHOLE
- b. Condition of Service Spillway CONDUIT JOINTS ARE SEVERAL INCHES WIDE - (SECTIONS NOT FIT TOGETHER TIGHTLY)  
THERE WAS NO MORTAR IN THE JOINTS IN THE UPPER PORTION - ONLY THE BOTTOM  $\frac{1}{3}$  HAD BEEN MORTARED.  
THERE WAS SEEPAGE INTO PIPE ON SEAMS 9 & 10 FROM MANHOLE INTO CONDUIT

c. Condition of Auxiliary Spillway NONE

d. Condition of Discharge Conveyance Channel RAN ALONG DOWNSTREAM TOE OF DAM - RIPRAPPED NEAR OUTLET PIPE ALTHOUGH MORE RIPRAP WAS NEEDED BECOMES NATURAL CHANNEL 20' BOTTOM WIDTH W/ 1:3 SS DEPTH 4' ROCK/BOULDER INVERT

8) Reservoir Drain/Outlet

Type: Pipe  Conduit \_\_\_\_\_ Other \_\_\_\_\_

Material: Concrete  Metal \_\_\_\_\_ Other \_\_\_\_\_

Size: 48" Length \_\_\_\_\_

Invert Elevations: Entrance 90.3 Exit 90

Physical Condition (Describe): Unobservable

Material: \_\_\_\_\_

Joints: \_\_\_\_\_ Alignment \_\_\_\_\_

Structural Integrity: \_\_\_\_\_

Hydraulic Capability: GOOD FOR A DRAIN

Means of Control: Gate \_\_\_\_\_ Valve \_\_\_\_\_ <sup>STOP LOGS</sup> Uncontrolled

Operation: Operable  Inoperable \_\_\_\_\_ Other \_\_\_\_\_

Present Condition (Describe): SATISFACTORY - THIS CAN BE USED AS RES. DRAIN BY REMOVING ALL STOP LOGS

9) Structural

a. Concrete Surfaces SATISFACTORY - ONLY CONCRETE ON D.I. & HEADWALL

MASONRY - (CENTER SECTION) - SOME STONE DISPLACED - VEGETATION  
GROWING THROUGH

b. Structural Cracking NONE

c. Movement - Horizontal & Vertical Alignment (Settlement) NONE

d. Junctions with Abutments or Embankments N/A

e. Drains - Foundation, Joint, Face NONE

f. Water Passages, Conduits, Sluices SATISFACTORY

g. Seepage or Leakage SOME SEEPAGE THROUGH LAID UP  
STONE SEGMENT

h. Joints - Construction, etc. N/A

i. Foundation N/A

j. Abutments N/A

k. Control Gates N/A

l. Approach & Outlet Channels N/A

m. Energy Dissipators (Plunge Pool, etc.) RIPRAP AT PLUNGE POOL OKAY BUT  
COULD USE MORE - COULD USE MORE ROCK ALONG ENTIRE TOE  
OF DAM

n. Intake Structures SATISFACTORY

o. Stability \_\_\_\_\_

p. Miscellaneous \_\_\_\_\_

APPENDIX C

HYDROLOGIC/HYDRAULIC  
ENGINEERING DATA AND COMPUTATIONS

CHECK LIST FOR DAMS  
HYDROLOGIC AND HYDRAULIC  
ENGINEERING DATA

1

AREA-CAPACITY DATA:

	<u>Elevation</u> (ft.)	<u>Surface Area</u> (acres)	<u>Storage Capacity</u> (acre-ft.)
1) Top of Dam	<u>101.3</u>	<u>114</u>	<u>1969</u>
2) Design High Water (Max. Design Pool)	_____	_____	_____
3) Auxiliary Spillway Crest	_____	_____	_____
4) Pool Level with Flashboards	_____	_____	_____
5) Service Spillway Crest	<u>99.3</u>	<u>105</u>	<u>1750</u>

DISCHARGES

	<u>Volume</u> (cfs)
1) Average Daily	<u>UNKNOWN</u>
2) Spillway @ Maximum High Water	<u>55</u>
3) Spillway @ Design High Water	<u>N/A</u>
4) Spillway @ Auxiliary Spillway Crest Elevation	<u>N/A</u>
5) Low Level Outlet	<u>N/A</u>
6) Total (of all facilities) @ Maximum High Water	<u>55</u>
7) Maximum Known Flood	<u>UNKNOWN</u>
8) At Time of Inspection	_____

CREST:

ELEVATION: 101.3

Type: EARTH & LAIN UP STONE

Width: 35' Length: 300'

Spillover NONE

Location \_\_\_\_\_

SPILLWAY:

SERVICE

AUXILIARY

99.3

Elevation \_\_\_\_\_

DROP INLET

Type \_\_\_\_\_

6 ft x 6 ft

Width \_\_\_\_\_

Type of Control

V

Uncontrolled \_\_\_\_\_

Controlled:

Type

(Flashboards; gate) \_\_\_\_\_

Number

\_\_\_\_\_

Size/Length

\_\_\_\_\_

Invert Material

\_\_\_\_\_

Anticipated Length  
of operating service

\_\_\_\_\_

Chute Length

\_\_\_\_\_

Height Between Spillway Crest  
& Approach Channel Invert  
(Weir Flow)

\_\_\_\_\_

HYDROMETEROLOGICAL GAGES:

Type : NONE

Location: \_\_\_\_\_

Records:

Date - NONE

Max. Reading - \_\_\_\_\_

FLOOD WATER CONTROL SYSTEM:

Warning System: NONE

Method of Controlled Releases (mechanisms):

REMOVE STOP LOGS DOWN TO BOTTOM  
OF RISER STRUCTURE



DRAINAGE AREA: 5.04 sq. mi.

DRAINAGE BASIN RUNOFF CHARACTERISTICS:

Land Use - Type: FOREST & FIELD

Terrain - Relief: ROLLING HILLS

Surface - Soil: GLACIAL TILL

Runoff Potential (existing or planned extensive alterations to existing (surface or subsurface conditions)

NONE

Potential Sedimentation problem areas (natural or man-made; present or future)

NONE

Potential Backwater problem areas for levels at maximum storage capacity including surcharge storage:

\_\_\_\_\_

Dikes - Floodwalls (overflow & non-overflow ) - Low reaches along the Reservoir perimeter:

Location: \_\_\_\_\_

Elevation: \_\_\_\_\_

Reservoir:

Length @ Maximum Pool \_\_\_\_\_ (Miles)

Length of Shoreline (@ Spillway Crest) \_\_\_\_\_ (Miles)

PROJECT GRID

JOB	SHEET NO.	CHECKED BY	DATE
GENEGANTSLET LAKE DAM	1		
SUBJECT	COMPUTED BY		DATE
HYDROLOGIC / HYDRAULIC COMPUTATIONS	RLW		12/8/80
DRAINAGE AREA - PLANIMETER FROM PITCHER, N.Y. QUAD			
$35.12 \text{ IN}^2 (91.83 \text{ AC/IN}^2) = 3225 \text{ AC} = 5.0450 \text{ MI.}$			
SURFACE AREA - PLANIMETERED = 105 ACRES			
		$A_1 = \pi R^2 \Rightarrow R = \sqrt{\frac{A}{\pi}} = \sqrt{\frac{105(43560)}{\pi}} = 1207$	
		$V_1 = \frac{\pi R^2 h}{3} = \frac{(105)}{3} (50) = 1750 \text{ AC-FT}$	
		$\frac{H}{V} = \frac{1207}{50} = 24 \text{ FT/FT}$	
		$R_2 = 1207 + 2(24) = 1255$	
		$A_2 = \pi R^2 = \pi (1255)^2 = 113.6 \text{ ACRES}$	
		$V_2 = \frac{A}{3} h = \frac{113.6}{3} (52) = 1969 \text{ AC-FT}$	
SNYDER SYNTHETIC UNIT HYDROGRAPH			
$L = 3.45 \text{ mi}$		$L_{CA} = 1.1 \text{ mi}$	$C_f \rightarrow \text{USE } 2.0$
$t_p = C_f (L \cdot L_{CA})^{.3} = 2.0 [(3.45)(1.1)]^{.3} = 2.98 \text{ HOURS}$			
$t_r = \frac{2.98}{5.5} = .54 \quad \text{USE } \frac{1}{2} \text{ HOUR}$			
$t_{RR} = t_p + .25(t_e - t_r) = 2.98 + .25(.5 - .54) = 2.97$			
$\text{TRBPC} = \text{T.F.} = 1 - \frac{.3005}{(5.04)} = .94$			

PROJECT GRID

JOB GENEGANT'S LET LAKE DAM	SHEET NO. 2	CHECKED BY	DATE
SUBJECT HYDROLOGIC / HYDRAULIC COMPUTATIONS		COMPUTED BY RLW	DATE 12/9/80
COMPUTED SPILLWAY CAPACITY			
ELEVATIONS - USING PLAN DATUM			
TOP OF DAM & TOP OF RISER 101.3			
LOWER CREST OF RISER & TOP OF STOP LOGS 99.3			
THREE FLOW CONDITIONS			
1. FLOW OVER STOP LOGS			
2. FLOW OVER BACK PORTION OF INTAKE STRUCTURE			
3. FLOW THROUGH OUTLET PIPE			

PROJECT GRID

JOB		SHEET NO.	CHECKED BY	DATE
GENEGANSLET LAKE DAM		3		
SUBJECT			COMPUTED BY	DATE
HYDRAULIC COMPUTATIONS			RLW	12/9/80
1. FLOW OVER STOP LOGS ASSUME SHARP CRESTED WEIR C=3.2				
$Q = CLH^{3/2} = (3.2)(6.1)(H)^{3/2}$				
W.S. ELEV.	H	Q		
99.3	0	-		
99.7	.4	4.9 cfs		
100	.7	11		
100.5	1.2	28		
101	1.7	43		
101.3	2	55		
102	2.7	87		
103	3.7	139		
2. FLOW OVER BACK PORTION OF INTAKE STRUCTURE WEIR LENGTH $L = 3 + 3 + 6.1 = 12.1$				
$Q = CLH^{3/2} = 3.1(12.1)(H)^{3/2}$ ASSUME SHARP CRESTED WEIR C=3.1				
W.S. ELEV.	H	Q		
101.3	0	-		
102	0.7	22 cfs		
103	1.7	83		
3. FLOW THROUGH OUTLET PIPE - 48" PIPE ASSUME FULL CONDUIT FLOW FOR DROP INLET RISER ASSUME INVERT OF OUTLET AT 90				
$A = \pi r^2 = \pi(2)^2 = 12.57 \text{ ft}^2$				
$Q = A \sqrt{\frac{2.5H}{1 + K_c + K_f + K_{pH}}} = 12.57 \sqrt{\frac{2(3.2)H}{1 + .5 + .45 + (.00656)(4H)}} =$				
W.S. ELEV.	H	Q		
99.3	7.3	159 cfs		
99.7	7.7	164		
100	8	167		
100.5	8.5	172		
101	9	177		
101.3	9.3	180		
102	10	187		
103	11	196		
104	12	204		
105	13	213		
107	15	229		

PROJECT GRID

JOB	GENEGANTSLET LAKE DAM		SHEET NO.	4	CHECKED BY		DATE	
SUBJECT	HYDRAULIC COMPUTATIONS			COMPLETED BY	RLW		DATE	12/9/80
STAGE - DISCHARGE TABLE								
	STAGE	DISCHARGE						
	99.3	0 cfs						
	99.7	49						
	100	11						
	100.5	26						
	101	43						
	101.3	55						
	102	109						
	103	196		← PIPE FLOW CONTROLS				
	104	204						
	105	213						
	107	229						
FOR FLOW OVER TOP OF DAM ASSUME WEIR FLOW								
$Q = CLH^{3/2}$								
ASSUME BROAD CRESTED WEIR $C = 2.6$								
CREST WIDTH = 35								
KING & BRATER (SEE APPENDIX D) TABLE 5-3 p. 5-46								



\*\*\*\*\*  
 NEW YORK STATE  
 DEPT OF ENVIRONMENTAL CONSERVATION  
 FLOOD PROTECTION BUREAU  
 \*\*\*\*\*

\*\*\*\*\*  
 FLOOD HYDROGRAPH PACKAGE (HEC-1)  
 DAN SAFETY VERSION JULY 1974  
 LAST MODIFICATION 26 FEB 79  
 MODIFIED BY BONEYWELL AND BZ  
 \*\*\*\*\*

RUN DATE 03/11/91

CONECATISLET LAKE DAM  
 PPF WITH RATIOS  
 OVERTOPPING ANALYSIS

JOB SPECIFICATION  
 INP 1 IN METR 0  
 JOPER 5  
 IPRY 2  
 IPRY 0  
 INSTAN 0

MULTI-PLAN ANALYSES TO BE PERFORMED  
 NPLAN= 1 LRTIO= 3 LRTIO= 1  
 RTIFS= 0.05 0.50 1.00

\*\*\*\*\*

SUB-AREA RUNOFF COMPUTATION

INFLOW HYDROGRAPH  
 ISTAT ICDIMP IECN ITAPE JPLY JPRT INAME ISTAGE IAUDD  
 1 0 0 0 0 0 1 0 0

HYDRO I IMG TAREA SNAP TRSDA TRSPC FATIC ISHOW ISAME LOCAL  
 1 1 5.04 0. 5.04 1.00 0. 0 0 1 0

PRECIP DATA  
 SPFE PHS R6 R12 R24 R48 R72 R96  
 0. 20.50 111.00 123.00 132.00 142.00 0. 0.

LOSS DATA  
 LROPT STRKR DLTKR RTIDL ERAIN STKKS RTICK STRYL CNSTL ALSPX RTIMP  
 0 0 0. 1.00 0. 0. 1.00 1.00 0.10 0. 0.

UNIT HYDROGRAPH DATA  
 TP= 2.97 CP=0.63 NTA= C  
 REFESSION DATA  
 STRT2= 10.00 SPCS2= 10.00 RTIR2= 1.00  
 APPROXIMATE CLARK COEFFICIENTS FROM GIVEN SYNOP CP AND TP ARE TC= 6.73 AND R= 5.36 INTERVALS

UNIT HYDROGRAPH 32 ENG-OF-PERIOD DIMENSIONS, LAG= 2.95 HOURS, CP= 0.63 VCL= 1.00  
 45. 104. 225. 495. 627. 697. 680. 552. 491. 407.  
 334. 280. 232. 192. 161. 132. 110. 51. 75. 63.  
 52. 42. 36. 30. 25. 20. 17. 14. 12. 10.  
 9.

END-OF-PERIOD FLOW  
 NO. DA  
 1.01 0.30  
 1.01 1.00  
 1.01 1.30  
 LOSS 0.00  
 EXCS 0.  
 RYN 0.00  
 PERIOD 1  
 2  
 3  
 FLOW 1.03  
 3.00  
 3.00  
 PERIOD 101  
 102  
 103  
 KAIN 0.  
 0.  
 0.  
 EXCS 0.  
 0.  
 0.  
 LOSS 0.  
 0.  
 0.  
 CDDP C 1092.  
 512.  
 758.  
 10





1.02	12.30	72	0.21	0.10	0.05	0.01	1.04	15.00	172	0.	0.	10.
1.02	12.30	73	1.11	1.00	0.05	0.07	1.04	14.40	173	0.	0.	10.
1.02	13.30	74	1.11	1.02	0.05	1.70	1.04	15.00	174	0.	0.	10.
1.02	13.30	75	1.37	1.32	0.05	1414.	1.04	15.30	175	0.	0.	10.
1.02	14.30	76	1.37	1.32	0.05	1522.	1.04	16.00	176	0.	0.	10.
1.02	14.30	77	1.71	1.66	0.04	1624.	1.04	17.30	177	0.	0.	10.
1.02	15.30	78	1.71	1.66	0.05	2456.	1.04	17.00	178	0.	0.	10.
1.02	15.30	79	2.03	2.03	0.05	4372.	1.04	17.30	179	0.	0.	10.
1.02	16.30	80	6.37	6.52	0.05	1923.	1.04	17.00	180	0.	0.	10.
1.02	16.30	81	1.53	1.54	0.05	0.03.	1.04	18.30	181	0.	0.	10.
1.02	17.30	82	1.53	1.54	0.05	0.77.	1.04	19.00	182	0.	0.	10.
1.02	17.30	83	1.25	1.20	0.05	10.63.	1.04	19.30	183	0.	0.	10.
1.02	18.30	84	1.25	1.20	0.05	11.90.	1.04	20.00	184	0.	0.	10.
1.02	18.30	85	0.09	0.04	0.05	11741.	1.04	20.30	185	0.	0.	10.
1.02	19.30	86	0.09	0.04	0.05	11574.	1.04	21.00	186	0.	0.	10.
1.02	19.30	87	0.09	0.04	0.05	13759.	1.04	21.30	187	0.	0.	10.
1.02	20.30	88	0.09	0.04	0.05	0.22.	1.04	22.00	188	0.	0.	10.
1.02	20.30	89	0.09	0.04	0.05	1351.	1.04	22.30	189	0.	0.	10.
1.02	21.30	90	0.09	0.04	0.05	7156.	1.04	23.00	190	0.	0.	10.
1.02	21.30	91	0.09	0.04	0.05	6017.	1.04	23.30	191	0.	0.	10.
1.02	22.30	92	0.09	0.04	0.05	5036.	1.05	0.	192	0.	0.	10.
1.02	22.30	93	0.09	0.04	0.05	4226.	1.05	0.30	193	0.	0.	10.
1.02	23.30	94	0.09	0.04	0.05	3552.	1.05	1.00	194	0.	0.	10.
1.02	23.30	95	0.09	0.04	0.05	2953.	1.05	1.30	195	0.	0.	10.
1.03	0.	96	0.09	0.04	0.05	2930.	1.05	2.00	196	0.	0.	10.
1.03	0.30	97	0.	0.	0.	2144.	1.05	2.30	197	0.	0.	10.
1.03	1.00	98	0.	0.	0.	1318.	1.05	3.00	198	0.	0.	10.
1.03	1.30	99	0.	0.	0.	1341.	1.05	3.30	199	0.	0.	10.
1.03	2.00	100	0.	0.	0.	1301.	1.05	4.00	200	0.	0.	10.

SUM 29.11 25.36 3.75 166089.  
( 739.1) ( 644.1) ( 55.1) ( 4703.12)

CFS	INCHES	MM	AC-FT	TFOUS	CU M
11741.					
332.					
6947.					
253.					
16.51					
419.45					
4437.					
5473.					
3315.					
94.					
24.48					
621.70					
6576.					
8111.					
1130.					
33.					
25.46					
645.65					
6240.					
8437.					
166083.					
4703.					
25.54					
645.64					
6240.					
8437.					
TOTAL	VOLUME				





HYDROGRAPH AT STA		1 FOR PLAN 1, PTIC 1		TOTAL VOLUME	
PEAK	6-HOUR	24-HOUR	72-HOUR	PEAK	6-HOUR
507.	447.	166.	57.	8364.	
17.	13.	5.	2.	235.	
	0.83	1.22	1.27	1.28	
	20.97	31.08	32.33	32.44	
	222.	325.	342.	243.	
	274.	406.	422.	423.	

HYDROGRAPH AT STA		1 FOR PLAN 1, PTIC 2		TOTAL VOLUME	
PEAK	6-HOUR	24-HOUR	72-HOUR	PEAK	6-HOUR
5871.	4474.	1658.	575.	83041.	
166.	127.	47.	16.	2351.	
	6.26	12.24	12.73	12.77	
	209.73	310.45	375.85	324.62	
	2218.	3281.	3420.	3431.	
	2736.	4056.	4215.	4231.	

HYDROGRAPH AT STA		1 FOR PLAN 1, PTIC 1		TOTAL VOLUME	
PEAK	6-HOUR	24-HOUR	72-HOUR	PEAK	6-HOUR
5871.	4474.	1658.	575.	83041.	
166.	127.	47.	16.	2351.	
	6.26	12.24	12.73	12.77	
	209.73	310.45	375.85	324.62	
	2218.	3281.	3420.	3431.	
	2736.	4056.	4215.	4231.	

HYDROGRAPH AT STA		1 FOR PLAN 1, PTIC 2		TOTAL VOLUME	
PEAK	6-HOUR	24-HOUR	72-HOUR	PEAK	6-HOUR
5871.	4474.	1658.	575.	83041.	
166.	127.	47.	16.	2351.	
	6.26	12.24	12.73	12.77	
	209.73	310.45	375.85	324.62	
	2218.	3281.	3420.	3431.	
	2736.	4056.	4215.	4231.	





TABLE 15. SUMMARY OF THE RESULTS

CLASS	NO. OF	34-104	72-100	TOTAL	VOLUME
CPS	133	1	1	2	5057
CMS	20	2	1	3	166
J-CMS	0.3	0.60	0.50	1.10	0.90
AC-FI	7.66	15.22	26.01	48.89	22.98
TR	1	1	2	4	242
AC-FI	1	1	2	4	242
TR	100	199	299	598	259

TOTALS CU M







STATUS 1. PL N L RATIC 2  
 FUND-OPERED HYDROCARBON OPERATES

BOTTLES

C.	C.	C.	C.	C.	C.	C.	C.	C.
2442.	3163	3556.	4712.	5301.	5612	585.	527.	1345.
3750.	3730.	2767.	2367.	2021.	1731.	1481.	1711.	4839.
812.	695.	601.	517.	442.	392.	328.	281.	543.
179.	151.	128.	109.	94.	81.	72.	64.	207.
56.	56.	52.	52.	52.	51.	50.	50.	55.
41.	47.	46.	46.	45.	45.	44.	43.	48.
42.	41.	41.	41.	40.	40.	39.	37.	42.
37.	37.	37.	36.	35.	35.	35.	35.	38.
36.	33.	34.	32.	32.	32.	31.	31.	34.
37.	36.	29.	29.	29.	29.	28.	28.	30.
27.	27.	26.	26.	25.	25.	26.	25.	27.
25.	24.	24.	24.	24.	24.	23.	23.	25.

STORAGE

C.	C.	C.	C.	C.	C.	C.	C.	C.
1750.	1750.	1751.	1751.	1751.	1751.	1751.	1752.	1752.
1752.	1752.	1753.	1753.	1753.	1753.	1753.	1754.	1754.
1754.	1754.	1755.	1755.	1755.	1755.	1755.	1756.	1756.
1756.	1756.	1757.	1757.	1757.	1757.	1757.	1758.	1758.
1814.	1820.	1844.	1845.	1846.	1846.	1847.	1848.	1848.
1842.	1843.	1854.	1857.	1859.	1859.	1860.	1860.	1860.
1851.	1857.	1858.	1875.	1879.	1879.	1879.	1900.	1913.
2190.	2235.	2261.	2321.	2351.	2351.	2366.	2328.	2130.
2270.	2230.	2211.	2185.	2162.	2142.	2124.	2094.	2500.
2063.	2036.	2059.	2041.	2031.	2025.	2015.	2007.	2081.
1997.	1993.	1989.	1981.	1981.	1978.	1976.	1971.	2002.
1967.	1905.	1903.	1901.	1901.	1900.	1906.	1902.	1930.
1940.	1947.	1945.	1944.	1942.	1940.	1936.	1936.	1934.
1932.	1931.	1925.	1920.	1927.	1925.	1924.	1921.	1920.
1913.	1917.	1916.	1914.	1913.	1912.	1911.	1908.	1907.
1904.	1905.	1903.	1902.	1901.	1900.	1899.	1897.	1896.
1895.	1894.	1893.	1892.	1891.	1890.	1889.	1888.	1886.
1885.	1884.	1882.	1882.	1881.	1880.	1880.	1879.	1878.
1876.	1876.	1875.	1874.	1873.	1872.	1872.	1871.	1870.

STAGE

C.	C.	C.	C.	C.	C.	C.	C.	C.
99.3	99.3	99.3	99.3	99.3	99.3	99.3	99.3	99.3
99.3	99.3	99.3	99.3	99.3	99.3	99.3	99.3	99.3
99.3	99.3	99.3	99.3	99.3	99.3	99.3	99.3	99.3
99.3	99.3	99.3	99.3	99.3	99.3	99.3	99.3	99.3
100.1	100.2	100.2	100.2	100.2	100.2	100.2	100.2	100.2
100.9	101.0	101.2	101.4	101.4	101.5	102.0	102.6	103.0
103.3	103.7	104.1	104.0	104.0	104.9	104.8	104.8	104.3
104.0	104.3	104.5	104.5	104.5	104.9	104.8	104.8	104.3
102.0	102.1	102.5	102.5	102.5	102.9	102.7	102.6	102.3
101.6	101.6	101.5	101.4	101.4	101.4	101.8	101.7	101.6
101.6	101.5	101.5	101.4	101.4	101.4	101.4	101.3	101.3

TIME	100.5	100.6	100.7	100.8	100.9	101.0	101.1	101.2	101.3	101.4	101.5	101.6	101.7	101.8	101.9	102.0
100.5	100.5	100.6	100.7	100.8	100.9	101.0	101.1	101.2	101.3	101.4	101.5	101.6	101.7	101.8	101.9	102.0
100.6	100.6	100.7	100.8	100.9	101.0	101.1	101.2	101.3	101.4	101.5	101.6	101.7	101.8	101.9	102.0	102.1
100.7	100.7	100.8	100.9	101.0	101.1	101.2	101.3	101.4	101.5	101.6	101.7	101.8	101.9	102.0	102.1	102.2
100.8	100.8	100.9	101.0	101.1	101.2	101.3	101.4	101.5	101.6	101.7	101.8	101.9	102.0	102.1	102.2	102.3
100.9	100.9	101.0	101.1	101.2	101.3	101.4	101.5	101.6	101.7	101.8	101.9	102.0	102.1	102.2	102.3	102.4
101.0	101.0	101.1	101.2	101.3	101.4	101.5	101.6	101.7	101.8	101.9	102.0	102.1	102.2	102.3	102.4	102.5
101.1	101.1	101.2	101.3	101.4	101.5	101.6	101.7	101.8	101.9	102.0	102.1	102.2	102.3	102.4	102.5	102.6
101.2	101.2	101.3	101.4	101.5	101.6	101.7	101.8	101.9	102.0	102.1	102.2	102.3	102.4	102.5	102.6	102.7
101.3	101.3	101.4	101.5	101.6	101.7	101.8	101.9	102.0	102.1	102.2	102.3	102.4	102.5	102.6	102.7	102.8
101.4	101.4	101.5	101.6	101.7	101.8	101.9	102.0	102.1	102.2	102.3	102.4	102.5	102.6	102.7	102.8	102.9
101.5	101.5	101.6	101.7	101.8	101.9	102.0	102.1	102.2	102.3	102.4	102.5	102.6	102.7	102.8	102.9	103.0

PEAK OUTFLJ - IS 5-12, AT TIE 43.00 HOURS

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
5012	43%	15%	5%	80183
159	13%	4%	1%	2211
	4.0%	11.0%	12.2%	12,233
	204.5%	299.7%	312.27%	213,225
	214%	3171%	3333%	3313
	204%	3911%	4074%	4087

CFS  
 GAS  
 INCHES  
 41  
 AC-FT  
 T-CUM





STATION 1, PLAN 1, PATIC 3  
 PROPOSED HYDROELECTRIC FACILITIES

INLET		OUTLET		STORAGE		STAGE	
C.	Q.	C.	Q.	C.	Q.	C.	Q.
1.	1.	1.	1.	1751.	1752.	99.3	99.3
1.	1.	1.	1.	1755.	1755.	99.3	99.4
1.	1.	1.	1.	1759.	1760.	99.4	99.4
1.	1.	1.	1.	1763.	1761.	99.4	99.4
2.	2.	1.	1.	1765.	1763.	99.4	99.4
3.	3.	1.	1.	1769.	1765.	99.4	99.4
4.	4.	1.	1.	1773.	1769.	99.4	99.4
5.	5.	1.	1.	1777.	1773.	99.4	99.4
6.	6.	1.	1.	1781.	1777.	99.4	99.4
7.	7.	1.	1.	1785.	1781.	99.4	99.4
8.	8.	1.	1.	1789.	1785.	99.4	99.4
9.	9.	1.	1.	1793.	1789.	99.4	99.4
10.	10.	1.	1.	1797.	1793.	99.4	99.4
11.	11.	1.	1.	1801.	1797.	99.4	99.4
12.	12.	1.	1.	1805.	1801.	99.4	99.4
13.	13.	1.	1.	1809.	1805.	99.4	99.4
14.	14.	1.	1.	1813.	1809.	99.4	99.4
15.	15.	1.	1.	1817.	1813.	99.4	99.4
16.	16.	1.	1.	1821.	1817.	99.4	99.4
17.	17.	1.	1.	1825.	1821.	99.4	99.4
18.	18.	1.	1.	1829.	1825.	99.4	99.4
19.	19.	1.	1.	1833.	1829.	99.4	99.4
20.	20.	1.	1.	1837.	1833.	99.4	99.4
21.	21.	1.	1.	1841.	1837.	99.4	99.4
22.	22.	1.	1.	1845.	1841.	99.4	99.4
23.	23.	1.	1.	1849.	1845.	99.4	99.4
24.	24.	1.	1.	1853.	1849.	99.4	99.4
25.	25.	1.	1.	1857.	1853.	99.4	99.4
26.	26.	1.	1.	1861.	1857.	99.4	99.4
27.	27.	1.	1.	1865.	1861.	99.4	99.4
28.	28.	1.	1.	1869.	1865.	99.4	99.4
29.	29.	1.	1.	1873.	1869.	99.4	99.4
30.	30.	1.	1.	1877.	1873.	99.4	99.4
31.	31.	1.	1.	1881.	1877.	99.4	99.4
32.	32.	1.	1.	1885.	1881.	99.4	99.4
33.	33.	1.	1.	1889.	1885.	99.4	99.4
34.	34.	1.	1.	1893.	1889.	99.4	99.4
35.	35.	1.	1.	1897.	1893.	99.4	99.4
36.	36.	1.	1.	1901.	1897.	99.4	99.4
37.	37.	1.	1.	1905.	1901.	99.4	99.4
38.	38.	1.	1.	1909.	1905.	99.4	99.4
39.	39.	1.	1.	1913.	1909.	99.4	99.4
40.	40.	1.	1.	1917.	1913.	99.4	99.4
41.	41.	1.	1.	1921.	1917.	99.4	99.4
42.	42.	1.	1.	1925.	1921.	99.4	99.4
43.	43.	1.	1.	1929.	1925.	99.4	99.4
44.	44.	1.	1.	1933.	1929.	99.4	99.4
45.	45.	1.	1.	1937.	1933.	99.4	99.4
46.	46.	1.	1.	1941.	1937.	99.4	99.4
47.	47.	1.	1.	1945.	1941.	99.4	99.4
48.	48.	1.	1.	1949.	1945.	99.4	99.4
49.	49.	1.	1.	1953.	1949.	99.4	99.4
50.	50.	1.	1.	1957.	1953.	99.4	99.4
51.	51.	1.	1.	1961.	1957.	99.4	99.4
52.	52.	1.	1.	1965.	1961.	99.4	99.4
53.	53.	1.	1.	1969.	1965.	99.4	99.4
54.	54.	1.	1.	1973.	1969.	99.4	99.4
55.	55.	1.	1.	1977.	1973.	99.4	99.4
56.	56.	1.	1.	1981.	1977.	99.4	99.4
57.	57.	1.	1.	1985.	1981.	99.4	99.4
58.	58.	1.	1.	1989.	1985.	99.4	99.4
59.	59.	1.	1.	1993.	1989.	99.4	99.4
60.	60.	1.	1.	1997.	1993.	99.4	99.4
61.	61.	1.	1.	2001.	1997.	99.4	99.4
62.	62.	1.	1.	2005.	2001.	99.4	99.4
63.	63.	1.	1.	2009.	2005.	99.4	99.4
64.	64.	1.	1.	2013.	2009.	99.4	99.4
65.	65.	1.	1.	2017.	2013.	99.4	99.4
66.	66.	1.	1.	2021.	2017.	99.4	99.4
67.	67.	1.	1.	2025.	2021.	99.4	99.4
68.	68.	1.	1.	2029.	2025.	99.4	99.4
69.	69.	1.	1.	2033.	2029.	99.4	99.4
70.	70.	1.	1.	2037.	2033.	99.4	99.4
71.	71.	1.	1.	2041.	2037.	99.4	99.4
72.	72.	1.	1.	2045.	2041.	99.4	99.4
73.	73.	1.	1.	2049.	2045.	99.4	99.4
74.	74.	1.	1.	2053.	2049.	99.4	99.4
75.	75.	1.	1.	2057.	2053.	99.4	99.4
76.	76.	1.	1.	2061.	2057.	99.4	99.4
77.	77.	1.	1.	2065.	2061.	99.4	99.4
78.	78.	1.	1.	2069.	2065.	99.4	99.4
79.	79.	1.	1.	2073.	2069.	99.4	99.4
80.	80.	1.	1.	2077.	2073.	99.4	99.4
81.	81.	1.	1.	2081.	2077.	99.4	99.4
82.	82.	1.	1.	2085.	2081.	99.4	99.4
83.	83.	1.	1.	2089.	2085.	99.4	99.4
84.	84.	1.	1.	2093.	2089.	99.4	99.4
85.	85.	1.	1.	2097.	2093.	99.4	99.4
86.	86.	1.	1.	2101.	2097.	99.4	99.4
87.	87.	1.	1.	2105.	2101.	99.4	99.4
88.	88.	1.	1.	2109.	2105.	99.4	99.4
89.	89.	1.	1.	2113.	2109.	99.4	99.4
90.	90.	1.	1.	2117.	2113.	99.4	99.4
91.	91.	1.	1.	2121.	2117.	99.4	99.4
92.	92.	1.	1.	2125.	2121.	99.4	99.4
93.	93.	1.	1.	2129.	2125.	99.4	99.4
94.	94.	1.	1.	2133.	2129.	99.4	99.4
95.	95.	1.	1.	2137.	2133.	99.4	99.4
96.	96.	1.	1.	2141.	2137.	99.4	99.4
97.	97.	1.	1.	2145.	2141.	99.4	99.4
98.	98.	1.	1.	2149.	2145.	99.4	99.4
99.	99.	1.	1.	2153.	2149.	99.4	99.4
100.	100.	1.	1.	2157.	2153.	99.4	99.4

101.2	101.3	101.4	101.5	101.6	101.7	101.8	101.9	102.0
101.0	101.0	101.0	101.0	101.0	101.0	101.0	101.0	101.0
100.9	100.9	100.9	100.9	100.9	100.9	100.9	100.9	100.9
100.8	100.8	100.8	100.8	100.8	100.8	100.8	100.8	100.8
100.7	100.7	100.7	100.7	100.7	100.7	100.7	100.7	100.7
100.6	100.6	100.6	100.6	100.6	100.6	100.6	100.6	100.6
100.5	100.5	100.5	100.5	100.5	100.5	100.5	100.5	100.5

PEAK OUTPUT IS 11449. AT TIME 43.00 HOURS

CFS 11449.  
 CMS 324.  
 IFCMS  
 AC-FT  
 T-OLS C U H

PEAK  
 11449.  
 324.  
 16.2  
 413.91  
 4373.  
 535%  
 229%  
 93.  
 24.32  
 617.61  
 6533.  
 8053.

72-SEC  
 117%  
 32.  
 24.58  
 627.46  
 6711.  
 8278.

TOTAL VOLUME  
 162521.  
 4613.  
 25.00  
 630.49  
 6732.  
 8904.

STATION I

1' FLD (1), OUTFLOW AND OBSERVED FLOW (C)  
DATE: 10/10/75 10:00 - 12:00

0.	2000.	4000.	6000.	8000.	10000.	12000.	C.	C.	C.	C.	C.
0.30 11	.	.	.	.	.	.	.	.	.	.	.
1.00 21	.	.	.	.	.	.	.	.	.	.	.
1.30 31	.	.	.	.	.	.	.	.	.	.	.
2.00 41	.	.	.	.	.	.	.	.	.	.	.
2.30 51	.	.	.	.	.	.	.	.	.	.	.
3.00 61	.	.	.	.	.	.	.	.	.	.	.
3.30 71	.	.	.	.	.	.	.	.	.	.	.
4.00 81	.	.	.	.	.	.	.	.	.	.	.
4.30 91	.	.	.	.	.	.	.	.	.	.	.
5.00 101	.	.	.	.	.	.	.	.	.	.	.
5.30 111	.	.	.	.	.	.	.	.	.	.	.
6.00 121	.	.	.	.	.	.	.	.	.	.	.
6.30 131	.	.	.	.	.	.	.	.	.	.	.
7.00 141	.	.	.	.	.	.	.	.	.	.	.
7.30 151	.	.	.	.	.	.	.	.	.	.	.
8.00 161	.	.	.	.	.	.	.	.	.	.	.
8.30 171	.	.	.	.	.	.	.	.	.	.	.
9.00 181	.	.	.	.	.	.	.	.	.	.	.
9.30 191	.	.	.	.	.	.	.	.	.	.	.
10.00 201	.	.	.	.	.	.	.	.	.	.	.
10.30 211	.	.	.	.	.	.	.	.	.	.	.
11.00 221	.	.	.	.	.	.	.	.	.	.	.
11.30 231	.	.	.	.	.	.	.	.	.	.	.
12.00 241	.	.	.	.	.	.	.	.	.	.	.
12.30 251	.	.	.	.	.	.	.	.	.	.	.
13.00 261	.	.	.	.	.	.	.	.	.	.	.
13.30 271	.	.	.	.	.	.	.	.	.	.	.
14.00 281	.	.	.	.	.	.	.	.	.	.	.
14.30 291	.	.	.	.	.	.	.	.	.	.	.
15.00 301	.	.	.	.	.	.	.	.	.	.	.
15.30 311	.	.	.	.	.	.	.	.	.	.	.
16.00 321	.	.	.	.	.	.	.	.	.	.	.
16.30 331	.	.	.	.	.	.	.	.	.	.	.
17.00 340I	.	.	.	.	.	.	.	.	.	.	.
17.30 350I	.	.	.	.	.	.	.	.	.	.	.
18.00 360 I	.	.	.	.	.	.	.	.	.	.	.
18.30 370 I	.	.	.	.	.	.	.	.	.	.	.
19.00 380 I	.	.	.	.	.	.	.	.	.	.	.
19.30 390 I	.	.	.	.	.	.	.	.	.	.	.
20.00 400.1	.	.	.	.	.	.	.	.	.	.	.
20.30 410 I	.	.	.	.	.	.	.	.	.	.	.
21.00 420I	.	.	.	.	.	.	.	.	.	.	.
21.30 430I	.	.	.	.	.	.	.	.	.	.	.
22.00 440I	.	.	.	.	.	.	.	.	.	.	.
22.30 450I	.	.	.	.	.	.	.	.	.	.	.
23.00 460I	.	.	.	.	.	.	.	.	.	.	.
23.30 470I	.	.	.	.	.	.	.	.	.	.	.
0. 480I	.	.	.	.	.	.	.	.	.	.	.
0.30 491	.	.	.	.	.	.	.	.	.	.	.
1.00 501	.	.	.	.	.	.	.	.	.	.	.
1.30 511	.	.	.	.	.	.	.	.	.	.	.
2.00 521	.	.	.	.	.	.	.	.	.	.	.
2.30 531	.	.	.	.	.	.	.	.	.	.	.
3.00 541	.	.	.	.	.	.	.	.	.	.	.
3.30 551	.	.	.	.	.	.	.	.	.	.	.
4.00 561	.	.	.	.	.	.	.	.	.	.	.
4.30 571	.	.	.	.	.	.	.	.	.	.	.
5.00 581	.	.	.	.	.	.	.	.	.	.	.

07VF\*



7.00 001  
7.00 001  
8.00 0401  
8.00 650 I  
9.00 601 I  
9.00 670 I  
10.00 000 I  
10.00 69. 01  
11.00 70. 01  
11.00 71. 01  
12.00 72. 01  
12.00 73. 01  
13.00 74. 01  
13.00 75. 01  
14.00 76. 01  
14.00 77. 01  
15.00 78. 01  
15.00 79. 01  
16.00 80. 01  
16.00 81. 01  
17.00 82. 01  
17.00 83. 01  
18.00 84. 01  
19.00 85. 01  
19.00 86. 01  
19.00 87. 01  
20.00 88. 01  
20.00 89. 01  
21.00 90. 01  
21.00 91. 01  
22.00 92. 01  
22.00 93. 01  
23.00 94. 01  
23.00 95. 01  
0. 96.  
0.00 97.  
1.00 98.  
1.00 99.  
2.00 100.  
2.00 101.  
3.00 102.  
3.00 103.  
4.00 104.  
4.00 105.  
5.00 106.  
5.00 107.  
6.00 108.  
6.00 109.  
7.00 110.  
7.00 111.  
8.00 112.  
8.00 113.  
9.00 114.  
9.00 115.  
10.00 116.  
10.00 117.  
11.00 118.  
12.00 119.  
12.00 120.  
12.00 121.  
13.00 122.  
13.00 123.  
14.00 124.  
14.00 125.

PEAK FLOW AND STORAGE (CALCULATED PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS  
 FLOWS IN CUBIC FEET PER SECOND (CUBIC FEET PER SECOND)  
 AREA IN SQUARE FEET (SQUARE KILOMETERS)

OPERATION	STATION	AREA	PLAN	RATIO	RATIOS APPLIED TO FLOWS		
					1	2	3
HYDROGRAPH AT	1	5.04 (0.30E 19)	1	0.02	537. ( 16.62)	5871. ( 166.29)	11741. ( 332.48)
	1	5.04 (0.30E 19)	1	0.50	204. ( 5.78)	5612. ( 156.92)	11449. ( 324.19)

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1 .....

ELEVATION STORAGE OUTFLOW	INITIAL VALUE	SPILLWAY CREST	TCP OF DAM	RATIO OF P/F	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TCP (HOURS)	TIME OF MAX OUTFLOW (HOURS)	TYPE OF FAILURE
101.30	99.30	95.30	101.30	0.65	0.30	2001.	204.	10.50	46.50	G.
1969.	1750.	1750.	1969.	0.50	3.63	2367.	5612.	23.50	43.00	G.
55.	0.	0.	55.	1.00	5.91	2617.	11445.	29.00	43.00	G.

APPENDIX D  
REFERENCES

APPENDIX D

REFERENCES


- 1) U.S. Department of Commerce; Weather Bureau;  
Hydrometeorological Report No. 33 - Seasonal Variation of the Probable  
Maximum Precipitation East of the 105th Meridian for Areas from 10 to  
1,000 Square Miles and Durations of 6, 12, 24, and 48 Hours, April 1956.
- 2) H.W. King and E.F. Brater, Handbook of Hydraulics, 5th edition,  
McGraw-Hill, 1963.
- 3) University of the State of New York, Geology of New York, Education  
Leaflet 20, Reprinted 1973.
- 4) Elwyn E. Seelye, Design, 3rd edition, John Wiley and Sons, Inc., 1960.
- 5) U.S. Department of the Interior, Bureau of Reclamations;  
Design of Small Dams, 2nd edition (rev. reprint), 1977.

APPENDIX E  
DRAWINGS



DAM SITE

VICINITY MAP  
 GENEGANTSLET LAKE DAM  
 I.D. No. NY 846




TOPOGRAPHIC MAP  
GENEGANTSLET LAKE DAM  
I.D. No. NY 846




----- ELEV. 99.7 FLOOD FLOW BEGINS TO PASS OVER THE DAM AT SECTION  
 & Summer Lake Level At 99.3

----- ELEV. 96.6 LAKE LEVEL ON SEPT. 22, 1964






NOTE: Any existing holes or weak spots found in stream face of dam or lake bottom to be sealed with compacted clay before placing the new clay fill layer on to dam



Approach Channel To Have Minimum Bottom Width of 20 ft and Side Slopes Not Steeper Than 2 Horizontal To 1 Vertical. Channel To Be Located So As To Drain Lake Down To Elevation 90.3

# SECTION A-A



GENEGANTSLET LAKE DAM  
 Mc DONOUGH, N. Y.  
 PROPOSED REPAIRS  
 AND  
 IMPROVEMENTS

SCALE 1" = 5' Horiz. and Vertical  
 Oct. 10, 1964 - Revised July 22, 1965  
 DRAWN BY Carl Crandall, C.E.  
 Ithaca, N.Y.

See Also Survey Map  
 Exhibit No. 9



STATE OF NEW YORK  
 DEPARTMENT OF PUBLIC WORKS  
 SUBDIVISION OF WATERWAY OPERATION  
 AND MAINTENANCE  
 ALBANY, N. Y. 12226



NEW DESIGNATION NO. 94D-3437 (orig #495)

WATERSHED Susquehanna River  
 Pursuant to the provisions of Section 948 of the Conservation Law, the design, details and specifications for the construction of the structure shown on these plans are hereby

approved. Date August 12, 1965

Reviewed by John E. Peck  
 Senior Civil Engineer

APPROVED by E.C. Hrudowalshki  
 Assistant Superintendent



3

END

DATE  
FILMED

11-81

DTIC