

AD-A106 215


HORNER AND SHIFRIN INC ST LOUIS MO
NATIONAL DAM SAFETY PROGRAM. SKY RANCH LAKE DAM (MO 31293), MIS--ETC(U)
SEP 80 R E SAUTHOFF, A B BECKER
DACW43-80-C-0063

F/8 13/13

UNCLASSIFIED

NL

10/13/80



LEVEL II



AD A106215

MISSOURI - KANSAS CITY BASIN

SKY RANCH LAKE DAM

WARREN COUNTY, MISSOURI

MO 31293

**DTIC
ELECTE
OCT 26 1981**

E

**PHASE 1 INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM**



**United States Army
Corps of Engineers**
... Serving the Army
... Serving the Nation

St. Louis District

THIS FILE COPY

PREPARED BY: U.S. ARMY ENGINEER DISTRICT, ST. LOUIS

FOR: STATE OF MISSOURI

... has been approved
for publication and sale; its
distribution is unlimited.

SEPTEMBER 1980

81 10 21

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO. A-1-A-2-3	3. RECIPIENT'S CATALOG NUMBER 1-2-5
4. TITLE (and Subtitle) Phase I Dam Inspection Report National Dam Safety Program Sky Ranch Lake Dam (MO 31293) Warren County, Missouri		5. TYPE OF REPORT & PERIOD COVERED 9) Final Report
7. AUTHOR(s) Horner & Shifrin, Inc.		6. PERFORMING ORG. REPORT NUMBER
8. PERFORMING ORGANIZATION NAME AND ADDRESS U.S. Army Engineer District, St. Louis Dam Inventory and Inspection Section, LMSED-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101		9. CONTRACT OR GRANT NUMBER(s) 13) DACW43-80-C-0063
11. CONTROLLING OFFICE NAME AND ADDRESS U.S. Army Engineer District, St. Louis Dam Inventory and Inspection Section, LMSED-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) 10) Ralph E. /Sauthoff Albert B. /Becker, Jr		12. REPORT DATE 11) September 1980
		13. NUMBER OF PAGES Approximately 45 (12) 601
		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) Approved for release; distribution unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report) 6) National Dam Safety Program. Sky Ranch Lake Dam (MO 31293), Missouri - Kansas City Basin, Warren County, Missouri. Phase I Inspection Report.		
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dam Safety, Lake, Dam Inspection, Private Dams		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report was prepared under the National Program of Inspection of Non-Federal Dams. This report assesses the general condition of the dam with respect to safety, based on available data and on visual inspection, to determine if the dam poses hazards to human life or property.		


SD FORM 1 JAN 78 1473

EDITION OF 1 NOV 65 IS OBSOLETE

421333 UNCLASSIFIED 401
SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

2

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)



SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

INSTRUCTIONS FOR PREPARATION OF REPORT DOCUMENTATION PAGE

RESPONSIBILITY. The controlling DoD office will be responsible for completion of the Report Documentation Page, DD Form 1473, in all technical reports prepared by or for DoD organizations.

CLASSIFICATION. Since this Report Documentation Page, DD Form 1473, is used in preparing announcements, bibliographies, and data banks, it should be unclassified if possible. If a classification is required, identify the classified items on the page by the appropriate symbol.

COMPLETION GUIDE

General. Make Blocks 1, 4, 5, 6, 7, 11, 13, 15, and 16 agree with the corresponding information on the report cover. Leave Blocks 2 and 3 blank.

Block 1. Report Number. Enter the unique alphanumeric report number shown on the cover.

Block 2. Government Accession No. Leave Blank. This space is for use by the Defense Documentation Center.

Block 3. Recipient's Catalog Number. Leave blank. This space is for the use of the report recipient to assist in future retrieval of the document.

Block 4. Title and Subtitle. Enter the title in all capital letters exactly as it appears on the publication. Titles should be unclassified whenever possible. Write out the English equivalent for Greek letters and mathematical symbols in the title (see "Abstracting Scientific and Technical Reports of Defense-sponsored RDT/E," AD-667 000). If the report has a subtitle, this subtitle should follow the main title, be separated by a comma or semicolon if appropriate, and be initially capitalized. If a publication has a title in a foreign language, translate the title into English and follow the English translation with the title in the original language. Make every effort to simplify the title before publication.

Block 5. Type of Report and Period Covered. Indicate here whether report is interim, final, etc., and, if applicable, inclusive dates of period covered, such as the life of a contract covered in a final contractor report.

Block 6. Performing Organization Report Number. Only numbers other than the official report number shown in Block 1, such as series numbers for in-house reports or a contractor/grantee number assigned by him, will be placed in this space. If no such numbers are used, leave this space blank.

Block 7. Author(s). Include corresponding information from the report cover. Give the name(s) of the author(s) in conventional order (for example, John R. Doe or, if author prefers, J. Robert Doe). In addition, list the affiliation of an author if it differs from that of the performing organization.

Block 8. Contract or Grant Number(s). For a contractor or grantee report, enter the complete contract or grant number(s) under which the work reported was accomplished. Leave blank in in-house reports.

Block 9. Performing Organization Name and Address. For in-house reports enter the name and address, including office symbol, of the performing activity. For contractor or grantee reports enter the name and address of the contractor or grantee who prepared the report and identify the appropriate corporate division, school, laboratory, etc., of the author. List city, state, and ZIP Code.

Block 10. Program Element, Project, Task Area, and Work Unit Numbers. Enter here the number code from the applicable Department of Defense form, such as the DD Form 1498, "Research and Technology Work Unit Summary" or the DD Form 1634, "Research and Development Planning Summary," which identifies the program element, project, task area, and work unit or equivalent under which the work was authorized.

Block 11. Controlling Office Name and Address. Enter the full, official name and address, including office symbol, of the controlling office. (Equates to funding/sponsoring agency. For definition see DoD Directive 5200.20, "Distribution Statements on Technical Documents.")

Block 12. Report Date. Enter here the day, month, and year or month and year as shown on the cover.

Block 13. Number of Pages. Enter the total number of pages.

Block 14. Monitoring Agency Name and Address (if different from Controlling Office). For use when the controlling or funding office does not directly administer a project, contract, or grant, but delegates the administrative responsibility to another organization.

Blocks 15 & 15a. Security Classification of the Report: Declassification/Downgrading Schedule of the Report. Enter in 15 the highest classification of the report. If appropriate, enter in 15a the declassification/downgrading schedule of the report, using the abbreviations for declassification/downgrading schedules listed in paragraph 4-207 of DoD 5200.1-R.

Block 16. Distribution Statement of the Report. Insert here the applicable distribution statement of the report from DoD Directive 5200.20, "Distribution Statements on Technical Documents."

Block 17. Distribution Statement (of the abstract entered in Block 20; if different from the distribution statement of the report). Insert here the applicable distribution statement of the abstract from DoD Directive 5200.20, "Distribution Statements on Technical Documents."

Block 18. Supplementary Notes. Enter information not included elsewhere but useful, such as: Prepared in cooperation with . . . Translation of (or by) . . . Presented at conference of . . . To be published in . . .

Block 19. Key Words. Select terms or short phrases that identify the principal subjects covered in the report, and are sufficiently specific and precise to be used as index entries for cataloging, conforming to standard terminology. The DoD "Thesaurus of Engineering and Scientific Terms" (TEST), AD-672 000, can be helpful.

Block 20. Abstract. The abstract should be a brief (not to exceed 200 words) factual summary of the most significant information contained in the report. If possible, the abstract of a classified report should be unclassified and the abstract to an unclassified report should consist of publicly-releasable information. If the report contains a significant bibliography or literature survey, mention it here. For information on preparing abstracts see "Abstracting Scientific and Technical Reports of Defense-Sponsored RDT&E," AD-667 000.

MISSOURI - KANSAS CITY BASIN

SKY RANCH LAKE DAM

WARREN COUNTY, MISSOURI

MO 31293

PHASE 1 INSPECTION REPORT NATIONAL DAM SAFETY PROGRAM



United States Army
Corps of Engineers

...Serving the Army
...Serving the Nation

St. Louis District

PREPARED BY: U.S. ARMY ENGINEER DISTRICT, ST. LOUIS
FOR: STATE OF MISSOURI

SEPTEMBER 1980

Accession For	
NTIS GRA&I	☒
DTIC TAB	☐
Unannounced	☐
Justification	
By _____	
Distribution/	
Availability Codes	
Dist	Avail and/or Special
A	



DEPARTMENT OF THE ARMY
ST. LOUIS DISTRICT, CORPS OF ENGINEERS
210 TUCKER BOULEVARD, NORTH
ST. LOUIS, MISSOURI 63101

REPLY TO
ATTENTION OF

LMSD-P

SUBJECT: Sky Ranch Lake Dam, MO 31293, Phase I Inspection Report

This report presents the results of field inspection and evaluation of the Sky Ranch Lake Dam (MO 31293):

It was prepared under the National Program of Inspection of Non-Federal Dams.

This dam has been classified as unsafe, non-emergency by the St. Louis District as a result of the application of the following criteria:

- 1) Spillway will not pass 50 percent of the Probable Maximum Flood without overtopping the dam.
- 2) Overtopping of the dam could result in failure of the dam.
- 3) Dam failure significantly increases the hazard to loss of life downstream.

SUBMITTED BY:

SIGNED

Chief, Engineering Division

15 OCT 1980

Date

APPROVED BY:

SIGNED

Colonel, CE, District Engineer

15 OCT 1980

Date

7
3
SKY RANCH LAKE DAM
MISSOURI INVENTORY NO. 31293
WARREN COUNTY, MISSOURI

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

PREPARED BY:

HORNER & SHIFRIN, INC.
5200 OAKLAND AVENUE
ST. LOUIS, MISSOURI 63110

FOR:

U. S. ARMY ENGINEER DISTRICT, ST. LOUIS
CORPS OF ENGINEERS

OCTOBER 1980

3
HS-8011

PHASE I REPORT
NATIONAL DAM SAFETY PROGRAM

Name of Dam:	Sky Ranch Lake Dam
State Located:	Missouri
County Located:	Warren
Stream:	Tributary of Lost Creek
Date of Inspection:	9 July 1980

The Sky Ranch Lake Dam was visually inspected by engineering personnel of Horner & Shifrin, Inc., Consulting Engineers, St. Louis, Missouri. The purpose of this inspection was to assess the general condition of the dam with respect to safety and, based upon this inspection and available data, determine if the dam poses a hazard to human life or property.

The following summarizes the findings of the visual inspection and the results of certain hydrologic/hydraulic investigations performed under the direction of the inspection team. Based on the visual inspection and the results of these hydrologic/hydraulic investigations, the present general condition of the dam is considered to be somewhat less than satisfactory. The following deficiencies were noticed during the inspection and are considered to have an adverse effect on the overall safety and future operation of the dam:

1. An eroded section of embankment (up to 6 feet in depth and approximately 8 feet wide and 30 feet long), that appears to be due to spillway releases impinging upon the dam, exists at the junction of the downstream toe of the dam and the spillway outlet channel. Loss of embankment material by erosion can be detrimental to the structural stability of the dam.
2. The upstream face of the dam has only a grass cover to prevent erosion by wave action or fluctuations of the lake surface level. A

grass cover is not considered adequate protection to prevent erosion of the embankment by wave action or fluctuations of the lake surface.

3. Several small trees along with some brushy undergrowth that could conceal animal burrows exists at the waterline along the upstream face of the dam. Tree roots and animal burrows can provide passageways for lake seepage that could develop into a piping condition (progressive internal erosion) and possible failure of the dam.
4. According to survey data obtained during the inspection, the crest elevation of the emergency spillway was found to be approximately 0.1 foot lower than the low area in the top of the dam between stations 1+00 and 1+50. As a result of this suspected settlement, the effectiveness of the emergency spillway is virtually negated.

According to the criteria set forth in the recommended guidelines, the magnitude of the spillway design flood for the Sky Ranch Lake Dam, which is classified as small in size and of high hazard potential, is specified to be a minimum of one-half the Probable Maximum Flood (PMF). Considering the fact that there are but four dwellings, one of which is unoccupied, within the estimated flood damage zone and the fact that the downstream flood plain is fairly broad and that the level of the living quarters of the dwellings within the flood damage zone are at an elevation appreciably above the bank of the downstream channel, it is recommended that the spillway for this dam be designed for one-half the Probable Maximum Flood. The Probable Maximum Flood (PMF) is the flood that may be expected from the most severe combination of critical meteorologic and hydrologic conditions that are reasonably possible in the region.


Results of the hydrologic/hydraulic analysis indicated that the spillways, principal plus emergency, are inadequate to pass lake outflow resulting from a storm of one-half PMF magnitude without overtopping the dam. The spillways are capable, however, of passing lake outflow resulting from the one percent probability (100-year frequency) flood and the outflow corresponding to about

14 percent of the PMF. According to the St. Louis District, Corps of Engineers, the length of the downstream damage zone, should failure of the dam occur, is estimated to be two miles. Within the downstream damage zone are four dwellings, one of which is unoccupied, several farm buildings and State Highway 94.

A review of available data did not disclose that seepage or stability analyses of this dam were performed. This is considered a deficiency and should be rectified.

It is recommended that the Owner take the necessary action within a reasonable time to correct or control the deficiencies and safety defects reported herein. The provision of additional spillway capacity should be pursued on a high priority basis.


Ralph E. Sauthoff
P. E. Missouri E-19090


Albert B. Becker, Jr.
P. E. Missouri E-9168



OVERVIEW SKY RANCH LAKE DAM

PHASE 1 INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
SKY RANCH LAKE DAM - MO 31293

TABLE OF CONTENTS

<u>Paragraph No.</u>	<u>Title</u>	<u>Page No.</u>
SECTION 1 - PROJECT INFORMATION		
1.1	General	1-1
1.2	Description of Project	1-1
1.3	Pertinent Data	1-3
SECTION 2 - ENGINEERING DATA		
2.1	Design	2-1
2.2	Construction	2-1
2.3	Operation	2-1
2.4	Evaluation	2-1
SECTION 3 - VISUAL INSPECTION		
3.1	Findings	3-1
3.2	Evaluation	3-4
SECTION 4 - OPERATIONAL PROCEDURES		
4.1	Procedures	4-1
4.2	Maintenance of Dam	4-1
4.3	Maintenance of Outlet Operating Facilities	4-1
4.4	Description of Any Warning Systems in Effect	4-1
4.5	Evaluation	4-2

Paragraph No.

Title

Page No.

SECTION 5 - HYDRAULIC/HYDROLOGIC

5.1	Evaluation of Features	5-1
-----	------------------------	-----

SECTION 6 - STRUCTURAL STABILITY

6.1	Evaluation of Structural Stability	6-1
-----	------------------------------------	-----

SECTION 7 - ASSESSMENT/REMEDIAL MEASURES

7.1	Dam Assessment	7-1
-----	----------------	-----

7.2	Remedial Measures	7-2
-----	-------------------	-----

LIST OF PLATES

Plate No.

Title

1	Regional Vicinity Map
2	Lake Watershed Map
3	Dam Plan & Profile
4	Dam Cross-Section and Spillway Profiles
5	Emergency Spillway Cross-Section

APPENDIX A - INSPECTION PHOTOGRAPHS

Page No.

Title

A-1 thru A-5	Inspection Photographs
--------------	------------------------

APPENDIX B - HYDROLOGIC AND HYDRAULIC ANALYSES

<u>Page No.</u>	<u>Title</u>
B-1 and B-3	Hydrologic & Hydraulic Computations
B-4 thru B-6	Computer Input Data
B-7 thru B-10	Computer Output Data
B-11	Lake Surface Area, Storage Volume and Elevation; Summary of Dam Safety Analysis

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
SKY RANCH LAKE DAM - MO 31293

SECTION I - PROJECT INFORMATION

1.1 GENERAL

a. Authority. The National Dam Inspection Act, Public Law 92-367, dated 8 August 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of safety inspection of dams throughout the United States. Pursuant to the above, the St. Louis District, Corps of Engineers, directed that a safety inspection of the Sky Ranch Lake Dam be made.

b. Purpose of Inspection. The purpose of this visual inspection was to make an assessment of the general condition of the dam with respect to safety and, based upon available data and this inspection, determine if the dam poses a hazard to human life or property.

c. Evaluation Criteria. This evaluation was performed in accordance with the "Phase I" investigation procedures as prescribed in "Recommended Guidelines for Safety Inspection of Dams", Appendix D to "Report to the Chief of Engineers on the National Program of Inspection of Non-Federal Dams", dated May 1975.

1.2 DESCRIPTION OF PROJECT

a. Description of Dam and Appurtenances. The Sky Ranch Lake Dam is an earthfill type embankment rising approximately 34 feet above the natural streambed at the downstream toe of the barrier. The embankment has an upstream slope (above the waterline) of approximately 1v on 1.9h, a crest width of about 14 feet, and a downstream slope on the order of 1v on 3.0h. The length of the dam is approximately 450 feet and the axis of the dam curves moderately away from the lake between abutments. A plan and profile of the dam are shown on Plate 3 and a cross-section of the dam is presented on Plate 4.

The dam has both a principal and an emergency spillway. The principal spillway, a culvert consisting of two 18-inch diameter corrugated metal pipes, is located at the left, or south, end of the dam. A concrete headwall serves to protect the upstream face of the dam at the pipes. The emergency spillway, a shallow V-section with the invert of the crest protected by concrete pavement, is also located at the left end of the dam. The outlet channel for both spillways closely follows the intersection of the embankment and the left abutment joining the original stream channel at a point about 100 feet downstream of the dam centerline. Profiles of the two spillway pipes are shown on Plate 4. The emergency spillway cross-section is shown on Plate 5.

The reservoir has two pipe outlets for lake drawdown. One of the outlets, a 2.5-inch galvanized steel pipe, enters an old cistern located in the downstream side of the dam at a point approximately 140 feet from the right, or north, abutment. A valve located within the cistern serves to control flow in the pipe. According to the Owner, it was intended that the cistern would serve as a storage facility to supply water to the old farm house located just downstream of the cistern. However, the Owner stated that this plan was never implemented and that the old farm house is not used. The second outlet, a 2-inch galvanized steel pipe, is located just to the left of the dam center. A valve located in a small shed near the toe of the dam serves to control flow in the pipe. The outlet pipe for this line, elevated about 3 feet above the ground surface, joins the original stream channel at a point just downstream of the dam. The piping within the shed is protected from freezing by heating tape and lamps as well as insulation attached to the building interior. According to the Owner, the inlet end of the 2-inch diameter pipe projects 8 feet above the bottom of the reservoir at a location just upstream of the base of the dam; the inlet end of the 2.5-inch diameter pipe is near the bottom of the reservoir opposite the cistern, and both pipes have well screen type filters on the inlet ends.

b. Location. The dam is located on an unnamed tributary of Lost Creek, about 1 mile east of the intersection of a private unnamed road and State Highway 94, and approximately 4 miles northwest of the town of Pinkney, Missouri, as shown on the Regional Vicinity Map, Plate 1. The dam is located within U. S. Survey No. 1765, approximately 6,900 feet southeast and 8,700 feet southwest of the northwest corner, within Warren County.

c. Size Classification. The size classification based on the height of the dam and storage capacity, is categorized as small (per Table 1, Recommended Guidelines for Safety Inspection of Dams).

d. Hazard Classification. The Sky Ranch Lake Dam, according to the St. Louis District, Corps of Engineers, has a high hazard potential, meaning that if the dam should fail, there may be loss of life, serious damage to homes, or extensive damage to agricultural, industrial and commercial facilities, important public utilities, main highways, or railroads. The estimated flood damage zone, should failure of the dam occur, as determined by the St. Louis District, extends two miles downstream of the dam. Within the possible flood damage zone are four dwellings, one of which is unoccupied, several farm buildings and State Highway 94. Those features lying within the downstream damage zone reported by the Corps of Engineers, St. Louis District, were verified by the inspection team.

e. Ownership. The lake and dam are owned by Elmer C. Edelmann. Mr. Edelmann's address is Box 211, Rural Route 1, Marthasville, Missouri 63357.

f. Purpose of Dam. The dam impounds water for recreational use.

g. Design and Construction History. According to the Owner, construction of the dam was completed in 1970 and the builder of the dam was Arthur Whaley, an excavator and earth moving contractor, from Jonesburg, Missouri. Efforts to contact Mr. Whaley to ascertain details of the dam design were unsuccessful. Records of the design were unavailable.

h. Normal Operational Procedure. The lake level is unregulated. Lake outflow is governed by the combined capacities of a culvert type spillway, consisting of two 18-inch diameter pipes, and an overflow type emergency spillway.

1.3 PERTINENT DATA

a. Drainage Area. The area tributary to the lake is for the most part in a native state covered with timber. The watershed above the dam amounts to approximately 134 acres. The watershed area is outlined on Plate 2.

b. Discharge at Damsite.

- (1) Estimated known maximum flood at dam site ... 11 cfs* (W.S.Elev. 610.5)
- (2) Spillway capacity ... 38 cfs.

c. Elevation (Ft. above MSL). The following elevations were determined by survey and are based on topographic data shown on the 1974 Berger, Missouri, Quadrangle Map, 7.5 Minute Series.

- (1) Observed pool ... 609.5
- (2) Normal pool ... 610.0
- (3) Spillway crest
 - A. Principal ... 610.0
 - B. Emergency ... 613.8
- (4) Maximum experienced pool ... 610.5*
- (5) Top of dam ... 613.9 (min.)
- (6) Streambed at centerline of dam ... 583+ (Est.)
- (7) Maximum tailwater ... Unknown
- (8) Observed tailwater ... None

d. Reservoir.

- (1) Length at normal pool (Elev. 610.0) ... 1,400 ft.
- (2) Length at maximum pool (Elev. 613.9) ... 1,500 ft.

e. Storage.

- (1) Normal pool ... 51 ac. ft.
- (2) Top of dam (incremental) ... 32 ac.ft.

f. Reservoir Surface.

- (1) Normal pool ... 8 acres
- (2) Top of dam (incremental) ... 1 acre

*Based on an estimate of depth of flow at pipe spillway as observed by the Owner.

g. Dam. The height of the dam is defined to be the overall vertical distance from the lowest point of foundation surface at the downstream toe of the barrier, to the top of the dam.

- (1) Type ... Earthfill, homogeneous *
- (2) Length ... 450 ft.
- (3) Height ... 34 ft.
- (4) Top width ... 14 ft.
- (5) Side slopes
 - a. Upstream ... 1v on 1.9h (above waterline)
 - b. Downstream ... 1v on 3.0h
- (6) Cutoff ... Core trench*
- (7) Slope protection
 - a. Upstream ... Grass
 - b. Downstream ... Grass

h. Principal Spillway.

- (1) Type ... Uncontrolled, two 18-inch diameter corrugated metal pipes (culvert)
- (2) Location ... Left abutment
- (3) Crest ... Elevation 610.0 & 610.4
- (4) Outlet channel ... Excavated earth, irregular trapezoidal section

i. Emergency Spillway.

- (1) Type ... Uncontrolled, V-section, paved concrete invert at crest
- (2) Location ... Left abutment
- (3) Crest ... Elevation 613.8
- (4) Outlet channel ... Common with principal spillway outlet channel

*Per Owner

j. Lake Drawdown Facility.

- (1) Pipe, 2.5-inch diameter with control valve and outlet in old cistern located in downstream face of dam at station 2+50₊.
- (2) Pipe, 2.0-inch diameter with control valve in shed located near downstream toe of dam at station 1+10₊.

SECTION 2 - ENGINEERING DATA

2.1 DESIGN

Data relative to the design of the dam were unavailable.

2.2 CONSTRUCTION

As previously stated, the dam was constructed in 1970 by Arthur Whaley, a local earth excavating contractor. According to the Owner, a core trench for seepage cutoff was excavated along the axis of the dam. The Owner reported that the material used to backfill the trench and construct the dam was clay that was obtained from the hillside just north of the lake. The Owner also recalled that the embankment material was compacted using a sheepsfoot roller. Records of the construction of the dam were unavailable.

2.3 OPERATION

The lake level is uncontrolled and governed by the elevation of the crest of the southern most of two 18-inch diameter pipes. No indication was found that the dam has been overtopped. The Owner reported that the dam has never been overtopped and that to his knowledge, the highest lake level experienced to date produced a depth of flow at the pipe spillway estimated to be about 6 inches above the invert of the south pipe.

2.4 EVALUATION

a. Availability. Engineering data for assessing the design of the dam and spillways were unavailable.

b. Adequacy. No data available. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available, which is considered a deficiency. These seepage and stability analyses should be performed for appropriate loading conditions (including earthquake loads) and made a matter of record.

SECTION 3 - VISUAL INSPECTION

3.1 FINDINGS

a. General. A visual inspection of the Sky Ranch Lake Dam was made by Horner & Shifrin engineering personnel, R. E. Sauthoff, Civil Engineer, and A. B. Becker, Jr., Civil and Soils Engineer, on 9 July 1980. An examination of the dam area was also made by an engineering geologist, Jerry D. Higgins, Ph.D., a consultant retained by Horner & Shifrin for the purpose of assessing the site geology. Also examined at the time of the inspection were the areas and features below the dam within the potential flood damage zone. Photographs of the dam taken at the time of the inspection are included on pages A-1 through A-5 of Appendix A. The locations of the photographs taken during the inspection are indicated on Plate 3.

b. Site Geology. The lake and dam are located within the Ozark Plateaus Physiographic Province near the border with the Dissected Till Plains Section of the Central Lowlands Province. The topography is moderately rugged, and there is up to approximately 280 feet of relief between the reservoir and the surrounding drainage divides. In the general area, the bedrock formations consist of gently northward-dipping Ordovician-age dolomites of the Jefferson City-Cotter formation and sandstones of the St. Peter formation. The dam and reservoir are situated on Jefferson City-Cotter dolomite with the St. Peter sandstone exposed well above the reservoir level. No faulting was observed or has been reported in the vicinity of the site.

The Jefferson City-Cotter dolomite is a light brown, medium to finely crystalline dolomite or argillaceous dolomite. It is thin- to medium-bedded, often argillaceous, and cherty. Solution enlargement of joints and bedding planes frequently occurs in the dolomite, and the contact between bedrock and the overlying surficial materials is usually an irregular surface. Jefferson City-Cotter dolomites outcrop in the spillway channel. The St. Peter sandstone is a white, fine- to medium-grained, pure quartz sandstone. It generally is massively bedded and although loosely cemented, exposed rock surfaces usually are case hardened by weathering processes.

The unconsolidated surficial materials are composed principally of soils of the Winfield series overlying residual clays. This series consists of deep, well-drained soils derived from the wind-deposited silts on the uplands adjacent to the Missouri River Valley. The soils consist of light brown silts in the upper layers, becoming darker and more clayey with depth. According to the Unified Soil Classification System, they are classified as CL or CL-ML materials, are moderately permeable and susceptible to erosion, but are generally suited for embankments and water impoundments. The bottom of the valley beneath the reservoir is covered by alluvial soils of the Cedargap and Nodaway series. The Cedargap series consists of a dark, grayish-brown silt grading with depth to a very cherty clay. The soils are classified as ML to GC material, are permeable, and may be subject to piping. The Nodaway series consists of a dark brown silt. The soils are classified as CL or CL-ML materials and are moderately permeable. Seepage may be common in both alluvial soils. Residual cherty clays are exposed in the dam abutments. These soils typically are somewhat permeable and often cause some seepage from reservoirs.

No geologic condition was noted that would be considered to severely affect the stability or performance of the dam or reservoir.

c. Dam. The visible portions of the upstream and downstream faces of the dam (see Photos 1, 2 and 7) as well as the dam crest were inspected and, except as noted herein, found to be in sound condition. No surface cracks or sloughing of the embankment slopes were noted. A section of embankment, approximately 30 feet long and 8 feet wide, was eroded to a depth of about 6 feet at a location adjacent to the lower end of the spillway outlet channel. No other significant erosion of the dam was noticed. No seepage was observed at the dam or in the area adjacent to the downstream toe of the dam. Except for the dam crest, which had a combination of turf that had been recently mowed, and crushed stone surfacing, the grass on the dam was about 3 feet high at the time of the inspection. Several small willow trees on the order of 1 inch in diameter along with some brushy undergrowth were found along the unprotected (no riprap) upstream face of the dam near the normal waterline. Examination of a soil sample obtained from the downstream face of the dam indicated the surficial material of the embankment to be a brown, silty lean clay (CL) of low-to-medium plasticity.

The visible portions of the two 18-inch diameter corrugated metal spillway pipes (see Photos 3 and 4) including the pole structure at the upstream end of the pipes were examined and found to be in satisfactory condition. According to the Owner, the poles are intended to support a dock that is planned to be constructed at some future time. The concrete headwall that serves to protect the upstream face of the dam at the pipes was also inspected and found to be in good condition without cracks or deterioration due to weathering. Some minor erosion of the embankment at the downstream ends of the pipes was evident; however, it did not appear to be significant. Inspection of the concrete slab (see Photo 5) that serves to protect the top of the dam at the emergency spillway indicated the pavement to be in satisfactory condition without cracks or spalls. Some minor erosion of the spillway outlet channel invert was noticed; however, it appeared that most of the channel bottom between the spillway pipes and the downstream channel was protected by bedrock outcrops. As previously stated, erosion that appeared to be due to spillway releases, has damaged a section of the embankment adjacent to the spillway outlet channel.

According to survey data obtained during the inspection, the crest elevation of the emergency spillway was found to be approximately 0.1 foot lower than the low area in the top of the dam between stations 1+00 and 1+50. It appears likely that the dam has settled to some extent in the vicinity of stations 1+00 to 1+50; however, the extent of the possible settlement in this area could not be determined.

The visible portions of the two lake drawdown pipes and appurtenances were examined and both features appeared to be in satisfactory condition. The 2-inch diameter pipe system within the shed (see Photo 6) was protected from freezing by heating tape and lamps as well as by insulation secured to the interior of the structure. The 2.5-inch diameter pipe outlet within the cistern (see Photo 8) was exposed to the weather at the time of the inspection.

The cistern, a concrete block structure parged with mortar and about 6.5 feet in diameter, was inspected and no serious defects were noted. The bottom of the cistern was sounded and found to about 19.5 feet below the top of the structure which was approximately 5 feet below the top of the dam. The water

level within the cistern was approximately 8.5 feet below the top at the time of the inspection. The incoming lake drawdown pipe was located about 3.5 feet below the top and the outlet pipe was approximately 7.5 feet below the cistern top. The upper 8 feet of the structure appeared to be newer than the lower portion and was probably added when the dam was built.

d. Appurtenant Structures. Except for the lake drawdown pipes, there are no appurtenant structures at this dam.

e. Downstream Channel. Except as noted herein, the downstream channel is unimproved. A culvert type structure allows State Highway 94 to cross the stream at a point about 1 mile downstream of the dam. A bridge conveys a railroad over the stream at a point almost 2 miles downstream of the dam just upstream of its juncture with the Missouri River. Between the dam and Highway 94 two low-water type crossings allow the road that accesses the Owner's property to cross the tributary. The tributary joins Lost Creek at a point about 1.5 miles downstream of the dam.

f. Reservoir. At the time of the inspection, the reservoir was approximately 0.5 feet below normal level and clear. No erosion of the lake banks was evident. Except for a section near the north end of the dam, the area about the lake was tree covered. The amount of sediment within the lake could not be determined during the inspection; however, due to the vegetation covering the surrounding area, it is not expected to be significant.

3.2 EVALUATION

The deficiencies observed during the inspection and noted herein, are not considered of significant importance to warrant immediate remedial action.

SECTION 4 - OPERATIONAL PROCEDURES

4.1 PROCEDURES

The spillways are uncontrolled. The lake surface level is governed by precipitation runoff, evaporation, seepage, and the combined capacities of the uncontrolled spillways.

4.2 MAINTENANCE OF DAM

According to the Owner, in 1979, a concrete diaphragm (wall) approximately 18 inches wide, 12 feet deep and 20 feet long, was installed in the dam at the location of the two culvert type spillway pipes. The Owner reported that muskrats had tunneled into the embankment adjacent to the pipes and that the purpose of the wall was to prevent erosion by piping of the dam at the spillway location. Since installation of the wall, the Owner indicated that there have been no problems with muskrats or erosion at the spillway location. The Owner also reported that muskrats are removed from the dam area by trapping.

4.3 MAINTENANCE OF OUTLET OPERATING FACILITIES

With the exception of the valves on the two lake drawdown pipes, no outlet facilities requiring operation exist at this dam. The valves on both lake drawdown pipes appeared to be in good condition, although neither valve was operated to check performance. As previously stated, the valve located in the shed at the base of the dam is protected from freezing by heat tape and lamps, whereas the valve located in the old cistern is exposed to the weather. There is no reservoir regulation plan.

4.4 DESCRIPTION OF ANY WARNING SYSTEMS IN EFFECT

The inspection did not reveal the existence of a dam failure warning system.

4.5 EVALUATION

It is recommended that maintenance of the dam also include periodic cutting of grass on the slopes and the removal of the small trees along the upstream face of the dam. Provisions should also be taken to prevent further erosion of the embankment at the left side of the dam adjacent to the spillway outlet channel. It is also recommended that a detailed inspection of the dam be instituted on a regular basis by an engineer experienced in the design and construction of dams and that records be kept of all inspections made and remedial measures taken.

SECTION 5 - HYDRAULIC/HYDROLOGIC

5.1 EVALUATION OF FEATURES

a. Design Data. Design data were not available.

b. Experience Data. The drainage area and lake surface area were developed from the 1974 USGS Berger, Missouri, Quadrangle Map. The proportions and dimensions of the spillways and dam were developed from surveys made during the inspection. Records of rainfall, streamflow, or flood data for the watershed were not available.

Due to the fact that the watershed for this reservoir is small, the lake level was assumed to be at normal pool as a result of antecedent storms prior to occurrence of the PMF and the probabilistic storm.

According to the St. Louis District, Corps of Engineers, the estimated flood damage zone, should failure of the dam occur, extends two miles downstream of the dam. The embankment for State Highway 94, which crosses the stream at a point about one mile downstream of the dam, is expected to act as a barrier in the event of dam failure.

c. Visual Observations.

(1) The dam has both a principal and an emergency spillway. The principal spillway, a culvert type installation consisting of two 18-inch diameter corrugated metal pipes, is located near the left abutment of the dam. The emergency spillway, a V-section with the crest protected by a concrete slab, is also located at the left abutment.

(2) A single outlet channel serves both spillways. The channel follows closely the junction of the dam and the abutment joining the original stream on which the dam is constructed just downstream of the dam.

(3) Spillway releases have caused damage by erosion to an area of the embankment adjacent to the outlet channel.

(4) The reservoir has two outlets for lake drawdown. One outlet consists of a 2.5-inch diameter pipe that has its control valve within a cistern located in the downstream face of the dam. A 2.5-inch diameter pipe extends from the cistern at a lower elevation than the control valve, but presently is capped near the cistern. The second outlet consists of a 2-inch diameter pipe that has its control valve within a shed located at the downstream toe of the dam. A 2-inch diameter discharge line conducts flow to the downstream channel at a point just downstream of the dam.

d. Overtopping Potential. The spillways are inadequate to pass the probable maximum flood, or 1/2 the probable maximum flood, without overtopping the dam. The results of the dam overtopping analyses are as follows:

(Note: The data appearing in the following table has been extracted from the computer output data appearing in Appendix B. Decimal values have been rounded to the nearest one-tenth in order to prevent assumption of unwarranted accuracy.)

<u>Ratio of PMF</u>	<u>Q-Peak Outflow (cfs)</u>	<u>Max. Lake W.S. Elev.</u>	<u>Max. Depth (Ft.) of Flow over Dam (Elev. 613.9)</u>	<u>Duration of Overtopping of Dam (Hours)</u>
0.50	1,435	615.4	1.5	7.4
1.00	2,998	616.2	2.2	11.7

Elevation 613.9 was found to be the lowest point in the dam crest. The flow safely passing the spillway, just prior to overtopping amounts to approximately 38 cfs, which is the routed outflow corresponding to about 14 percent of the probable maximum flood inflow. During peak flow of the probable maximum flood, the greatest depth of flow over the dam is projected to be 2.2 feet and overtopping will extend across the entire length of the dam.

e. Evaluation. Examination of the surficial material of the dam indicated it to be a brown, silty lean clay of low-to-medium plasticity. Experience indicates that this type of material, under certain conditions,

such as high velocity flow, can be very erodible. An example of such erosion exists along the downstream toe of the embankment adjacent to the spillway outlet channel. Such a condition exists during the PMF when large lake outflow, accompanied by high flow velocities, occurs. For the PMF condition where the depth of flow over the dam crest, a maximum of 2.2 feet, and the duration of flow over the dam, 11.7 hours, are appreciable, damage by erosion to the crest and downstream face of the dam is expected. The extent of these damages is not predictable within the scope of these investigations; however, there is a possibility that they could result in failure by erosion of the dam. A similar condition, although not quite as severe, also exists during the 1/2 PMF event.

f. References. Procedures and data for determining the probable maximum flood, the 1 percent probability flood, and the discharge rating curve for flow passing the spillways are presented on pages B-1 thru B-3 of the Appendix. Listings of the HEC-1 (Dam Safety Version) input data for both the probable maximum flood and the 1 percent probability flood are shown on pages B-4 through B-6. Computer output data, including unit hydrograph ordinates, tabulation of PMF rainfall, loss and inflow data are shown on pages B-7 through B-10; tabulation of lake surface area, elevation and storage volume is shown on page B-11; and tabulations titled "Summary of Dam Safety Analysis" for the PMF and 1 percent probability (100-year frequency) flood are also shown on page B-11.

SECTION 6 - STRUCTURAL STABILITY

6.1 EVALUATION OF STRUCTURAL STABILITY

a. Visual Observations. Visual observations of conditions which adversely affect the structural stability of the dam are discussed in Section 3, paragraph 3.1c.

b. Design and Construction Data. No design or construction data relating to the structural stability of the dam are known to exist. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available, which is considered a deficiency. These seepage and stability analyses should be performed for appropriate loading conditions (including earthquake loads) and made a matter of record.

c. Operating Records. With the exception of the valves on the two lake drawdown pipes, no appurtenant structures or facilities requiring operation exist at this dam. According to the Owner, no records are kept of the lake level, spillway discharge, dam settlement, or seepage.

d. Post Construction Changes. As discussed in Section 4, paragraph 4.2, in 1979 a concrete diaphragm (wall) was installed in the dam at the location of the spillway pipes in order to prevent erosion of the embankment. According to the Owner, no other post construction changes have been made or have occurred which would affect the structural stability of the dam.

e. Seismic Stability. The dam is located in an area close to the boundary separating the Zone I and Zone II seismic probability areas. An earthquake of the magnitude that might occur in this area would not be expected to cause structural damage to a well-constructed earth dam of this size provided that static stability conditions are satisfactory and conventional safety margins exist. However, it is recommended that the prescribed seismic loading be applied in any stability analyses performed for this dam.

SECTION 7 - ASSESSMENT/REMEDIAL MEASURES

7.1 DAM ASSESSMENT

a. Safety. A hydraulic analysis indicated that the spillway is capable of passing lake outflow of about 38 cfs without the level of the lake exceeding the low point in the top of the dam. A hydrologic analysis of the lake watershed area, as discussed in Section 5, paragraph 5.1d, indicates that for storm runoff of one-half probable maximum flood magnitude, the recommended spillway design flood for this dam, the lake outflow would be about 1,435 cfs, and that for the 1 percent probability (100-year frequency) flood, the lake outflow would be about 35 cfs.

Seepage and stability analyses of the dam were not available for review, and therefore, no judgment could be made with respect to the structural stability of the dam.

Significant items noticed during the inspection that could adversely affect the safety of the dam were the embankment erosion adjacent to the spillway outlet channel, the lack of adequate slope protection to prevent erosion of the upstream face of the dam, the small trees and undergrowth along the upstream face of the dam, and possible settlement of the dam crest.

b. Adequacy of Information. Due to lack of design and construction data, the assessments reported herein were based on external conditions as determined during the visual inspection. The assessments of the hydrology of the watershed and capacities of the spillways were based on a hydrologic/hydraulic study as indicated in Section 5. Seepage and stability analyses comparable to the requirements of "Recommended Guidelines for Safety Inspection of Dams" were not available, which is considered a deficiency.

c. Urgency. The remedial measures recommended in paragraph 7.2 for the items concerning the safety of the dam noted in paragraph 7.1a should be accomplished within a reasonable time. The item recommended in paragraph 7.2a concerning the provision of additional spillway capacity should be pursued on a high priority basis.

d. Necessity for Phase II. Based on the results of the Phase I inspection, Phase II investigation is not recommended.

e. Seismic Stability. The dam is located in an area close to the boundary separating the Zone I and Zone II seismic probability areas. An earthquake of the magnitude that might occur in this area would not be expected to cause structural damage to a well constructed earth dam of this size provided that static stability conditions are satisfactory and conventional safety margins exist. However, it is recommended that the prescribed seismic loading be applied in any stability analyses performed for this dam.

7.2 REMEDIAL MEASURES

a. Recommendations. The following actions are recommended.

(1) Based upon criteria set forth in the recommended guidelines, spillway size and/or height of dam should be increased in order to pass lake outflow resulting from a storm of one-half the probable maximum flood magnitude, which is the recommended spillway design flood for this dam. In any event, the Owner should address the relationship of the crest elevation of the emergency spillway and the low area of the top of the dam between stations 1+00 and 1+50; since the effectiveness of the emergency spillway is virtually negated under the existing condition.

(2) Obtain the necessary soil data and perform dam seepage and stability analyses in order to determine the structural stability of the dam for all operational conditions. Seepage and stability analyses should be performed by a qualified professional engineer experienced in the design and construction of earthen dams.

b. Operations and Maintenance (O & M) Procedures. The following O & M Procedures are recommended:

(1) Restore the embankment at the eroded area adjacent to the spillway outlet channel and provide some form of protection in order to



prevent erosion by spillway releases. Loss of embankment material by erosion can impair the structural stability of the dam.

(2) Provide some form of protection other than grass along the upstream face of the dam at and above the normal waterline in order to prevent erosion. A grass covered slope is not considered adequate protection to prevent erosion of the embankment by wave action or by a fluctuating lake level.

(3) Remove the trees and brushy type undergrowth that may conceal animal burrows from the upstream face of the dam. Tree roots and animal burrows can provide passageways for lake seepage that could lead to a piping condition and failure of the dam.

(4) Provide maintenance of all areas of the dam including periodic cutting of the grass on the slopes, on a regularly scheduled basis in order to insure features of being in satisfactory operational condition.

(5) A detailed inspection of the dam should be instituted on a regular basis by an engineer experienced in the design and construction of dams. It is also recommended, for future reference, that records be kept of all inspections made and remedial measures taken.



**WARREN
COUNTY**

LOCATION MAP


SKY RANCH LAKE





SCALE (MILES)

REGIONAL VICINITY MAP


PLATE I








GENERAL PLAN OF
SCALE: 1" = 50'




6
PHOTO LOCATION & KEY
(SEE APPENDIX A)

PROFILE DAM CREST
SCALES: 1" = 5' V., 1" = 50'

DAM
 DRAWDOWN OUTLET PIPE
 SHED W/2" Ø LAKE
 DRAWDOWN VALVE





AL PLAN OF DAM
 SCALE: 1" = 50'




LE DAM CREST
 ES: 1" = 5' V., 1" = 50' H.

**SKY RANCH LAKE
 DAM PLAN & PROFILE**

Horner & Shifrin, Inc. August 1980




DAM
4.0



CROSS-SECTION STA. 0+75

SCALES: 1"=10' V., 1"=20' H.



SPILLWAY PIPE PROFILES

SCALES: 1"=10' V., 1"=20' H.

SKY RANCH LAKE
DAM CROSS-SECTION &
SPILLWAY PROFILES

Horner & Shifrin, Inc.

August 1980

PLATE 4

APPENDIX A

INSPECTION PHOTOGRAPHS



NO. 1: UPSTREAM FACE OF DAM



NO. 2: VALVE SHED AT DOWNSTREAM TOE OF DAM



NO. 3: UPSTREAM END OF SPILLWAY PIPES



NO. 4: DOWNSTREAM END OF SPILLWAY PIPES



NO. 5: CONCRETE SLAB AT CREST
OF EMERGENCY SPILLWAY




NO. 6: 2" LAKE DRAWDOWN PIPING WITHIN SHED



NO. 7: CISTERN AND OLD HOUSE IN DOWNSTREAM FACE OF DAM



NO. 8: 2½" LAKE DRAWDOWN PIPING IN CISTERN



NO. 9: EMBANKMENT EROSION ADJACENT TO SPILLWAY OUTLET CHANNEL

APPENDIX B

HYDROLOGIC AND HYDRAULIC ANALYSES

HYDROLOGIC AND HYDRAULIC COMPUTATIONS

1. The HEC-1 Dam Safety Version (July 1978, Modified 26 February 1979) program was used to develop inflow and outflow hydrographs and dam overtopping analyses, with hydrologic inputs as follows:

a. Probable maximum precipitation (200 sq. mile, 24-hour value equals 25.1 inches) from Hydrometeorological Report No. 33. The precipitation data used in the analysis of the 1 percent probability flood was provided by the St. Louis District, Corps of Engineers.

b. Drainage area = 0.209 square miles = 134 acres.

c. SCS parameters:

$$\text{Time of Concentration } (T_c) = \left(\frac{11.9L^3}{H} \right)^{0.385} = 0.100 \text{ hours}$$

Where: T_c = Travel time of water from hydraulically most distant point to point of interest, hours.

L = Length of longest watercourse, 0.388 miles

H = Elevation difference, 272 feet

The time of concentration (T_c) was obtained using Method C as described in Figure 30, "Design of Small Dams", by the United States Department of the Interior, Bureau of Reclamation and was verified using average channel velocity estimates and watercourse lengths.

Lag Time = 0.060 hours (0.60 T_c)

Hydrologic Soil Group = 40% B (Winfield, Cedargap and Goss Series) + 60% D (Holstien and Gasconade Series) per County SCS Soil Report.

Soil type CN = 76 (AMC II, 1 percent probability flood condition)
= 89 (AMC III, PMF condition)

2. Flow passing the double 18-inch diameter corrugated metal pipe spillway was determined using Bernoulli's equation for flow in pipes. A pipe friction factor (n) of 0.021 was used. Losses, including entrance, pipe and exit losses totaled 3.95 velocity heads for the south pipe and 4.09 velocity heads for the north pipe. Reference "Handbook of Hydraulics", Fifth Edition, King and Brater, pages 8-5 and 8-6.

Discharge quantities, determined by the methods described herein were plotted versus corresponding lake water surface elevations to determine the discharge rating curve for the principal spillway.

3. The emergency spillway section consists of a broad-crested, V-section for which conventional weir formulas do not apply.

Spillway release rates were determined as follows:

- a. Spillway crest section properties (area, "a" and top width, "t") were computed for various depths, "d".
- b. It was assumed that flow over the spillway crest would occur at critical depth. Flow at critical depth was computed as $Q_c = \left(\frac{a^3}{t}\right)^{0.5}$ for the various depths, "d". Corresponding velocities (v_c) and velocity heads (H_{vc}) were determined using conventional formulas.* Reference, "Handbook of Hydraulics", Fifth Edition, by King and Brater, page 8-7.
- c. Static lake levels corresponding to the various values passing the spillway were computed as critical depths plus critical velocity head ($d_c + H_{vc}$), and the relationship between lake level and spillway discharge was thus obtained. The procedure neglects the minor insignificant friction losses across the length of the spillway.

$$* \quad v_c = \frac{Q_c}{a} \quad ; \quad H_{vc} = \frac{v_c^2}{2g}$$

4. The discharges for the principal and emergency spillways for equal elevations were summated for entry on the Y4 and Y5 cards.

5. The profile of the dam crest is irregular and flow over the dam cannot be determined by application of conventional weir formulas. Crest length and elevation data for the dam crest proper were entered into the HEC-1 Program on the \$L and the \$V cards. The program assumes that flow over the dam crest section occurs at critical depth and computes internally the flow over the dam crest and adds this flow to the flow passing the spillways as entered on the Y4 and Y5 cards.

401 ANALYSIS OF DAM OVERTOPPING USING RATIOS OF PMF
402 HYDROLOGIC-HYDROELECTRIC ANALYSIS OF SAFETY OF SKY RANCH LAKE DAM
403 RATIOS OF PMF FORCED THROUGH RESERVOIR

[illegible]

THE UNIVERSITY OF CHICAGO

[illegible]

4

B-5

100-YR. FLOOD (Cont'd)

[illegible]

ANALYSIS OF DAM OVERTOPPING USING RATIONALE METHOD
 HYDROLOGIC-HYDRAULIC ANALYSIS OF SAFETY OF A. J. CANN LAKE DAM
 RATIOS OF FPM ROUTED THROUGH RESERVOIR

JOB SPECIFICATION

NO	NHR	NMIN	ICAY	IHR	IMIN	NETR	IRI	IERT	ISTAR
268	0	5	0	0	0	0	0	0	0
			JOPER	INT	LRPT	WAVE			
			5	0	0	0			

MULTI-PLAN ANALYSES TO BE PERFORMED
 NPLAN= 1 NRTIO= 4 LRTIO= 1
 RTIOS= .14 .15 .50 1.00

CURVE AREA SUMMED OVER SECTION

INFLOW HYDROGRAPH

ISTAD	ICOND	ICORN	ICAVE	ICLT	ICET	ICAME	ICSTAF	ICAUT
INFLOW	0	0	0		0	1	0	0

HYDROGRAPH DATA

HYDS	IRAG	TAREA	QAVE	TRIDA	TRIDE	TRTIO	ICORN	ICAME	LOCAL
1	2	.21	0.00	.21	1.00	0.000	0	1	0

FEEDBACK DATA

SPFE	FMS	R6	R12	R24	R48	R72	R96
0.00	25.10	102.00	120.00	130.00	0.00	0.00	0.00

LOSS DATA

LRPT	STRKR	ELTKR	RTIOL	ERAIN	STRIS	RTIOK	STATL	ENSTL	ALOMX	RTIMP
0	0.00	0.00	1.00	0.00	0.00	1.00	-1.00	-89.00	0.00	0.00

CURVE NO = -89.00 WETNESS = -1.00 EFFECT. CN = 89.00

UNIT HYDROGRAPH DATA

TC= 0.00 LAG= .06

RECESSION DATA

STRT0= -1.00 OFCSH= -.10 RTIOR= 2.00

TIME INCREMENT TOO LARGE--(NNO IS GT LAG/2)

UNIT HYDROGRAPH 6 END OF PERIOD ORDINATES, TC= 0.00 HOURS, LAG= .06 VOL= 1.00
 927. 512. 133. 25. 10. 1.

0		END-OF-PERIOD FLOW											
MO. DA	HR. MIN	PERIOD	RAIN	EXCS	LOSS	COMP G	MO. DA	HR. MIN	PERIOD	RAIN	EXCS	LOSS	COMP G
1.01	.05	1	.01	0.00	.01	0.	1.01	12.05	145	.21	.21	.01	293.
1.01	.10	2	.01	0.00	.01	0.	1.01	12.10	146	.21	.21	.01	303.
1.01	.15	3	.01	0.00	.01	0.	1.01	12.15	147	.21	.21	.01	328.
1.01	.20	4	.01	0.00	.01	0.	1.01	12.20	148	.21	.21	.01	333.
1.01	.25	5	.01	0.00	.01	0.	1.01	12.25	149	.21	.21	.01	335.
1.01	.30	6	.01	0.00	.01	0.	1.01	12.30	150	.21	.21	.01	336.
1.01	.35	7	.01	0.00	.01	0.	1.01	12.35	151	.21	.21	.01	336.
1.01	.40	8	.01	0.00	.01	0.	1.01	12.40	152	.21	.21	.00	337.
1.01	.45	9	.01	0.00	.01	0.	1.01	12.45	153	.21	.21	.00	337.
1.01	.50	10	.01	0.00	.01	0.	1.01	12.50	154	.21	.21	.00	338.
1.01	.55	11	.01	0.00	.01	0.	1.01	12.55	155	.21	.21	.00	338.
1.01	1.00	12	.01	0.00	.01	0.	1.01	13.00	156	.21	.21	.00	338.
1.01	1.05	13	.01	0.00	.01	0.	1.01	13.05	157	.26	.25	.00	378.
1.01	1.10	14	.01	0.00	.01	0.	1.01	13.10	158	.26	.25	.00	399.
1.01	1.15	15	.01	0.00	.01	0.	1.01	13.15	159	.26	.25	.00	405.
1.01	1.20	16	.01	0.00	.01	0.	1.01	13.20	160	.26	.25	.00	407.
1.01	1.25	17	.01	0.00	.01	0.	1.01	13.25	161	.26	.25	.00	408.
1.01	1.30	18	.01	.00	.01	0.	1.01	13.30	162	.26	.25	.00	408.
1.01	1.35	19	.01	.00	.01	0.	1.01	13.35	163	.26	.25	.00	409.
1.01	1.40	20	.01	.00	.01	1.	1.01	13.40	164	.26	.25	.00	409.
1.01	1.45	21	.01	.00	.01	1.	1.01	13.45	165	.26	.25	.00	409.
1.01	1.50	22	.01	.00	.01	2.	1.01	13.50	166	.26	.25	.00	409.
1.01	1.55	23	.01	.00	.01	2.	1.01	13.55	167	.26	.25	.00	409.
1.01	2.00	24	.01	.00	.01	2.	1.01	14.00	168	.26	.25	.00	410.
1.01	2.05	25	.01	.00	.01	3.	1.01	14.05	169	.32	.31	.00	459.
1.01	2.10	26	.01	.00	.01	3.	1.01	14.10	170	.32	.31	.00	501.
1.01	2.15	27	.01	.00	.01	4.	1.01	14.15	171	.32	.32	.00	510.
1.01	2.20	28	.01	.00	.01	4.	1.01	14.20	172	.32	.31	.00	512.
1.01	2.25	29	.01	.00	.01	4.	1.01	14.25	173	.32	.32	.00	513.
1.01	2.30	30	.01	.00	.01	5.	1.01	14.30	174	.32	.32	.00	513.
1.01	2.35	31	.01	.00	.01	5.	1.01	14.35	175	.32	.32	.00	514.
1.01	2.40	32	.01	.00	.01	5.	1.01	14.40	176	.32	.32	.00	514.
1.01	2.45	33	.01	.00	.01	6.	1.01	14.45	177	.32	.32	.00	514.
1.01	2.50	34	.01	.00	.01	6.	1.01	14.50	178	.32	.32	.00	514.
1.01	2.55	35	.01	.00	.01	6.	1.01	14.55	179	.32	.32	.00	514.
1.01	3.00	36	.01	.00	.01	7.	1.01	15.00	180	.32	.32	.00	514.
1.01	3.05	37	.01	.00	.01	7.	1.01	15.05	181	.39	.38	.00	599.
1.01	3.10	38	.01	.00	.01	7.	1.01	15.10	182	.39	.39	.00	514.
1.01	3.15	39	.01	.00	.01	8.	1.01	15.15	183	.39	.39	.00	597.
1.01	3.20	40	.01	.00	.01	8.	1.01	15.20	184	.58	.58	.00	798.
1.01	3.25	41	.01	.01	.01	8.	1.01	15.25	185	.68	.68	.00	993.
1.01	3.30	42	.01	.01	.01	8.	1.01	15.30	186	1.65	1.65	.01	1966.
1.01	3.35	43	.01	.01	.01	9.	1.01	15.35	187	2.72	2.71	.01	3474.
1.01	3.40	44	.01	.01	.01	9.	1.01	15.40	188	1.07	1.07	.00	2629.
1.01	3.45	45	.01	.01	.01	9.	1.01	15.45	189	.68	.68	.00	1602.
1.01	3.50	46	.01	.01	.01	9.	1.01	15.50	190	.58	.58	.00	1141.
1.01	3.55	47	.01	.01	.01	10.	1.01	15.55	191	.39	.39	.00	813.
1.01	4.00	48	.01	.01	.01	10.	1.01	16.00	192	.39	.39	.00	672.
1.01	4.05	49	.01	.01	.01	10.	1.01	16.05	193	.30	.30	.00	555.
1.01	4.10	50	.01	.01	.01	10.	1.01	16.10	194	.30	.30	.00	500.
1.01	4.15	51	.01	.01	.01	10.	1.01	16.15	195	.30	.30	.00	426.

PMF END-OF-PERIOD FLOW

1.01	4.20	52	.01	.01	.01	11.	1.01	16.20	196	.30	.30	.00	433.
1.01	4.25	53	.01	.01	.01	11.	1.01	16.25	197	.30	.30	.00	432.
1.01	4.30	54	.01	.01	.01	11.	1.01	16.30	198	.30	.30	.00	432.
1.01	4.35	55	.01	.01	.01	11.	1.01	16.35	199	.30	.30	.00	432.
1.01	4.40	56	.01	.01	.01	11.	1.01	16.40	200	.30	.30	.00	432.
1.01	4.45	57	.01	.01	.01	12.	1.01	16.45	201	.30	.30	.00	432.
1.01	4.50	58	.01	.01	.01	12.	1.01	16.50	202	.30	.30	.00	432.
1.01	4.55	59	.01	.01	.01	12.	1.01	16.55	203	.30	.30	.00	432.
1.01	5.00	60	.01	.01	.01	12.	1.01	17.00	204	.30	.30	.00	432.
1.01	5.05	61	.01	.01	.01	12.	1.01	17.05	205	.23	.23	.00	423.
1.01	5.10	62	.01	.01	.01	12.	1.01	17.10	206	.23	.23	.00	390.
1.01	5.15	63	.01	.01	.01	13.	1.01	17.15	207	.23	.23	.00	392.
1.01	5.20	64	.01	.01	.01	13.	1.01	17.20	208	.23	.23	.00	390.
1.01	5.25	65	.01	.01	.01	13.	1.01	17.25	209	.23	.23	.00	379.
1.01	5.30	66	.01	.01	.01	13.	1.01	17.30	210	.23	.23	.00	379.
1.01	5.35	67	.01	.01	.01	13.	1.01	17.35	211	.23	.23	.00	379.
1.01	5.40	68	.01	.01	.01	13.	1.01	17.40	212	.23	.23	.00	379.
1.01	5.45	69	.01	.01	.01	13.	1.01	17.45	213	.23	.23	.00	379.
1.01	5.50	70	.01	.01	.01	13.	1.01	17.50	214	.23	.23	.00	379.
1.01	5.55	71	.01	.01	.01	14.	1.01	17.55	215	.23	.23	.00	379.
1.01	6.00	72	.01	.01	.01	14.	1.01	18.00	216	.23	.23	.00	375.
1.01	6.05	73	.03	.04	.02	42.	1.01	18.05	217	.02	.02	.00	328.
1.01	6.10	74	.06	.04	.02	59.	1.01	18.10	218	.02	.02	.00	318.
1.01	6.15	75	.06	.04	.02	65.	1.01	18.15	219	.02	.02	.00	285.
1.01	6.20	76	.06	.04	.02	68.	1.01	18.20	220	.02	.02	.00	256.
1.01	6.25	77	.06	.04	.02	71.	1.01	18.25	221	.02	.02	.00	240.
1.01	6.30	78	.06	.05	.02	72.	1.01	18.30	222	.02	.02	.00	232.
1.01	6.35	79	.06	.05	.02	74.	1.01	18.35	223	.02	.02	.00	216.
1.01	6.40	80	.06	.05	.02	75.	1.01	18.40	224	.02	.02	.00	202.
1.01	6.45	81	.06	.05	.02	76.	1.01	18.45	225	.02	.02	.00	193.
1.01	6.50	82	.06	.05	.01	78.	1.01	18.50	226	.02	.02	.00	176.
1.01	6.55	83	.06	.05	.01	79.	1.01	18.55	227	.02	.02	.00	164.
1.01	7.00	84	.06	.05	.01	80.	1.01	19.00	228	.02	.02	.00	153.
1.01	7.05	85	.06	.05	.01	81.	1.01	19.05	229	.02	.02	.00	143.
1.01	7.10	86	.06	.05	.01	82.	1.01	19.10	230	.02	.02	.00	133.
1.01	7.15	87	.06	.05	.01	83.	1.01	19.15	231	.02	.02	.00	124.
1.01	7.20	88	.06	.05	.01	83.	1.01	19.20	232	.02	.02	.00	116.
1.01	7.25	89	.06	.05	.01	84.	1.01	19.25	233	.02	.02	.00	108.
1.01	7.30	90	.06	.05	.01	85.	1.01	19.30	234	.02	.02	.00	101.
1.01	7.35	91	.06	.05	.01	86.	1.01	19.35	235	.02	.02	.00	94.
1.01	7.40	92	.06	.05	.01	86.	1.01	19.40	236	.02	.02	.00	88.
1.01	7.45	93	.06	.05	.01	87.	1.01	19.45	237	.02	.02	.00	82.
1.01	7.50	94	.06	.05	.01	87.	1.01	19.50	238	.02	.02	.00	76.
1.01	7.55	95	.06	.05	.01	88.	1.01	19.55	239	.02	.02	.00	71.
1.01	8.00	96	.06	.05	.01	88.	1.01	20.00	240	.02	.02	.00	67.
1.01	8.05	97	.06	.06	.01	89.	1.01	20.05	241	.02	.02	.00	62.
1.01	8.10	98	.06	.06	.01	89.	1.01	20.10	242	.02	.02	.00	58.
1.01	8.15	99	.06	.06	.01	90.	1.01	20.15	243	.02	.02	.00	54.
1.01	8.20	100	.06	.06	.01	90.	1.01	20.20	244	.02	.02	.00	50.
1.01	8.25	101	.06	.06	.01	90.	1.01	20.25	245	.02	.02	.00	47.
1.01	8.30	102	.06	.06	.01	91.	1.01	20.30	246	.02	.02	.00	44.
1.01	8.35	103	.06	.06	.01	91.	1.01	20.35	247	.02	.02	.00	41.

PMF END-OF-PERIOD FLOW

1.01	8.40	104	.06	.06	.01	91.	1.01	20.40	240	.02	.02	.00	38.
1.01	8.45	105	.06	.06	.01	91.	1.01	20.45	249	.02	.02	.00	30.
1.01	8.50	106	.06	.06	.01	92.	1.01	20.50	250	.02	.02	.00	34.
1.01	8.55	107	.06	.06	.01	92.	1.01	20.55	251	.02	.02	.00	34.
1.01	9.00	108	.06	.06	.01	93.	1.01	21.00	252	.02	.02	.00	34.
1.01	9.05	109	.06	.06	.01	93.	1.01	21.05	253	.02	.02	.00	34.
1.01	9.10	110	.06	.06	.01	93.	1.01	21.10	254	.02	.02	.00	34.
1.01	9.15	111	.06	.06	.00	94.	1.01	21.15	255	.02	.02	.00	34.
1.01	9.20	112	.06	.06	.00	94.	1.01	21.20	256	.02	.02	.00	34.
1.01	9.25	113	.06	.06	.00	94.	1.01	21.25	257	.02	.02	.00	34.
1.01	9.30	114	.06	.06	.00	94.	1.01	21.30	258	.02	.02	.00	34.
1.01	9.35	115	.06	.06	.00	94.	1.01	21.35	259	.02	.02	.00	34.
1.01	9.40	116	.06	.06	.00	94.	1.01	21.40	260	.02	.02	.00	34.
1.01	9.45	117	.06	.06	.00	95.	1.01	21.45	261	.02	.02	.00	34.
1.01	9.50	118	.06	.06	.00	95.	1.01	21.50	262	.02	.02	.00	34.
1.01	9.55	119	.06	.06	.00	95.	1.01	21.55	263	.02	.02	.00	34.
1.01	10.00	120	.06	.06	.00	95.	1.01	22.00	264	.02	.02	.00	34.
1.01	10.05	121	.06	.06	.00	95.	1.01	22.05	265	.02	.02	.00	34.
1.01	10.10	122	.06	.06	.00	95.	1.01	22.10	266	.02	.02	.00	34.
1.01	10.15	123	.06	.06	.00	96.	1.01	22.15	267	.02	.02	.00	34.
1.01	10.20	124	.06	.06	.00	96.	1.01	22.20	268	.02	.02	.00	34.
1.01	10.25	125	.06	.06	.00	96.	1.01	22.25	269	.02	.02	.00	34.
1.01	10.30	126	.06	.06	.00	96.	1.01	22.30	270	.02	.02	.00	34.
1.01	10.35	127	.06	.06	.00	96.	1.01	22.35	271	.02	.02	.00	34.
1.01	10.40	128	.06	.06	.00	96.	1.01	22.40	272	.02	.02	.00	34.
1.01	10.45	129	.06	.06	.00	96.	1.01	22.45	273	.02	.02	.00	34.
1.01	10.50	130	.06	.06	.00	96.	1.01	22.50	274	.02	.02	.00	34.
1.01	10.55	131	.06	.06	.00	97.	1.01	22.55	275	.02	.02	.00	34.
1.01	11.00	132	.06	.06	.00	97.	1.01	23.00	276	.02	.02	.00	34.
1.01	11.05	133	.06	.06	.00	97.	1.01	23.05	277	.02	.02	.00	34.
1.01	11.10	134	.06	.06	.00	97.	1.01	23.10	278	.02	.02	.00	34.
1.01	11.15	135	.06	.06	.00	97.	1.01	23.15	279	.02	.02	.00	34.
1.01	11.20	136	.06	.06	.00	97.	1.01	23.20	280	.02	.02	.00	34.
1.01	11.25	137	.06	.06	.00	97.	1.01	23.25	281	.02	.02	.00	34.
1.01	11.30	138	.06	.06	.00	97.	1.01	23.30	282	.02	.02	.00	34.
1.01	11.35	139	.06	.06	.00	97.	1.01	23.35	283	.02	.02	.00	34.
1.01	11.40	140	.06	.06	.00	97.	1.01	23.40	284	.02	.02	.00	34.
1.01	11.45	141	.06	.06	.00	98.	1.01	23.45	285	.02	.02	.00	34.
1.01	11.50	142	.06	.06	.00	98.	1.01	23.50	286	.02	.02	.00	34.
1.01	11.55	143	.06	.06	.00	98.	1.01	23.55	287	.02	.02	.00	34.
1.01	12.00	144	.06	.06	.00	98.	1.02	0.00	288	.02	.02	.00	34.

SUM 32.03 31.19 1.44 53524.
(629.) (792.) (37.) 1515.05

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFC	3471.	579.	100.	100.	53511.
CMS	90.	10.	5.	5.	1515.
INCHES		25.37	33.00	33.08	33.08
MM		644.49	840.22	840.22	840.22
FE-FT		283.	368.	368.	368.
THOUS CU FT		349.	455.	455.	455.

SURFACE AREA= 0. 8. 11. 15.
CAPACITY= 0. 51. 143. 271.
ELEVATION= 520. 610. 620. 630.

SUMMARY OF DAM SAFETY ANALYSIS RATIOS OF PMF

	INITIAL VALUE	SPILLWAY CREST	TOP OF DAM
ELEVATION	610.00	610.00	613.00
STORAGE	51.	51.	83.
OUTFLOW	0.	0.	38.

RATIO OF PMF	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP	TIME OF MAX OUTFLOW	TIME OF FAILURE
.14	0.00	62.	35.	0.00	15.1	15.1
.15	.13	74.	45.	2.06	13.1	13.1
.50	1.51	66.	1435.	7.41	15.1	15.1
1.00	2.25	104.	2908.	11.07	15.1	15.1

SUMMARY OF DAM SAFETY ANALYSIS

100-YEAR FLOOD

	INITIAL VALUE	SPILLWAY CREST	TOP OF DAM
ELEVATION	610.00	610.00	613.00
STORAGE	51.	51.	83.
OUTFLOW	0.	0.	38.

RATIO OF PMF	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP	TIME OF MAX OUTFLOW	TIME OF FAILURE
1.00	0.00	81.	35.	0.00	14.00	0.00

END

DATE
FILMED

11-81

DTIC