

AD-A106 461

BLACK AND VEATCH KANSAS CITY MO
NATIONAL DAM SAFETY PROGRAM, HARRISON COUNTY DAM C-2 (MO 10614)--ETC(U)
MAR 81 E R BURTON, M L CALLAHAN

F/8 13/13

DACW43-81-C-0037

NL

UNCLASSIFIED

1 of 2

46
37 (total)



LEVEL

MISSOURI-GRAND-CHARITON BASIN

(P)

AL A 106461

**HARRISON COUNTY DAM C-2
HARRISON COUNTY, MISSOURI
MO 10614**

**DTIC
ELECTED
NOV 2 1981
H.**

**PHASE 1 INSPECTION REPORT
NATIONAL / DAM SAFETY PROGRAM**

Original contains color plates: All DTIC reproductions will be in black and white

THIS FILE COPY



**United States Army
Corps of Engineers**
...Serving the Army
...Serving the Nation

St. Louis District

PREPARED BY: U.S. ARMY ENGINEER DISTRICT. ST. LOUIS

FOR: STATE OF MISSOURI

MAR 1981

(S)

DISTRIBUTION STATEMENT 1981
Approved for public release
Distribution Unlimited

81 11 02 015

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO. A106462	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Dam Inspection Report National Dam Safety Program Harrison County Dam C-2 (MO 10614) Harrison County, Missouri		5. TYPE OF REPORT & PERIOD COVERED Final Report
7. AUTHOR(s) Black & Veatch, Consulting Engineers		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS U.S. Army Engineer District, St. Louis Dam Inventory and Inspection Section, LMSED-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101		8. CONTRACT OR GRANT NUMBER(s) DACW43-81-C-0037
11. CONTROLLING OFFICE NAME AND ADDRESS U.S. Army Engineer District, St. Louis Dam Inventory and Inspection Section, LMSED-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) 16/59 1 K. E. ... M. ...		12. REPORT DATE March 1981
		13. NUMBER OF PAGES Approximately 120
		15. SECURITY CLASS. (of this report) UNCLASSIFIED
16. DISTRIBUTION STATEMENT (of this report) Approved for release; distribution unlimited.		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report) 6 National Dam Safety Program. Harrison County Dam C-2 (MO 10614), Missouri - Grand - Chariton Basin, Harrison County, Missouri. Phase I Inspection Report.		
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dam Safety, Lake, Dam Inspection, Private Dams		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report was prepared under the National Program of Inspection of Non-Federal Dams. This report assesses the general condition of the dam with respect to safety, based on available data and on visual inspection, to determine if the dam poses hazards to human life or property.		

DD FORM 1 JAN 73 1473

EDITION OF 1 NOV 65 IS OBSOLETE

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

058517

MISSOURI-GRAND-CHARITON BASIN

HARRISON COUNTY DAM C-2
HARRISON COUNTY, MISSOURI
MO 10614

PHASE 1 INSPECTION REPORT NATIONAL DAM SAFETY PROGRAM



United States Army
Corps of Engineers
*... Serving the Army
... Serving the Nation*

St. Louis District

PREPARED BY: U.S. ARMY ENGINEER DISTRICT. ST. LOUIS

FOR: STATE OF MISSOURI

MARCH 1981

HARRISON COUNTY DAM C-2
HARRISON COUNTY, MISSOURI
MISSOURI INVENTORY NO. 10614

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

PREPARED BY:
BLACK & VEATCH
CONSULTING ENGINEERS
KANSAS CITY, MISSOURI

UNDER DIRECTION OF
ST. LOUIS DISTRICT CORPS OF ENGINEERS
FOR
GOVERNOR OF MISSOURI

MARCH 1981



DEPARTMENT OF THE ARMY
ST. LOUIS DISTRICT, CORPS OF ENGINEERS
 210 TUCKER BOULEVARD, NORTH
 ST. LOUIS, MISSOURI 63101

REPLY TO
 ATTENTION OF

SUBJECT: Dam Phase I Inspection Report

This report presents the results of field inspection and evaluation of the Harrison County Dam C-2 (MO 10614).

It was prepared under the National Program of Inspection of Non-Federal Dams.

This dam has been classified as unsafe, non-emergency by the St. Louis District as a result of the application of the following criteria:

- a. Spillway will not pass 50 percent of the Probable Maximum Flood without overtopping the dam.
- b. Overtopping of the dam could result in failure of the dam.
- c. Dam failure significantly increases the hazard to loss of life downstream.

SUBMITTED BY: **SIGNED** **9 JUL 1981**
 Chief, Engineering Division Date

APPROVED BY: **SIGNED** **10 JUL 1981**
 Colonel, CE, Commanding Date

Accession For	<input checked="" type="checkbox"/>
NTIS GRA&I	<input type="checkbox"/>
ERIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By	
Distribution/	
Availability Codes	
Dist Avail and/or	
Special	
A	

PHASE I REPORT
NATIONAL DAM SAFETY PROGRAM

Name of Dam	Harrison County Dam C-2
State Located	Missouri
County Located	Harrison County
Stream	Panther Creek
Date of Inspection	3 March 1981

Harrison County Dam C-2 was inspected by a team of engineers from Black & Veatch, Consulting Engineers for the St. Louis District, Corps of Engineers. The purpose of the inspection was to make an assessment of the general condition of the dam with respect to safety, based upon available data and visual inspection, in order to determine if the dam poses hazards to human life or property.

The guidelines used in the assessment were furnished by the Department of the Army, Office of the Chief of Engineers and developed with the help of several Federal and state agencies, professional engineering organizations, and private engineers. Based on these guidelines, this dam is classified as an intermediate size dam with a high downstream hazard potential. According to the St. Louis District, Corps of Engineers, failure would threaten lives and property. The estimated damage zone extends approximately six miles downstream of the dam. Within the estimated damage zone are four dwellings and two farm buildings. Contents of the estimated downstream damage zone were verified by the inspection team.

Our inspection and evaluation indicates the spillways do not meet the criteria set forth in the guidelines for a dam having the above size and hazard potential. The spillways will not pass the probable maximum flood without overtopping but will pass 40 percent of the probable maximum flood. The spillways will pass the flood which has a one percent chance of occurrence in any given year (100-year flood). The spillway design flood recommended by the guidelines is 100 percent of the probable maximum flood. The probable maximum flood is defined as the flood discharge which may be expected from the most severe combination of critical meteorologic and hydrologic conditions which are reasonably possible in the region.

Based on visual observations, this dam appears to be in satisfactory condition. Deficiencies visually observed by the inspection team were erosion at the downstream toe of slope and at both abutment/embankment interfaces, a wet area downstream of the dam, the growth of trees on the embankment, animal burrows in the embankment, irregularities

in the downstream slope, vehicle tracks on the crest of the dam, and an inoperable slide gate at the low level inlet to the principal spillway drop structure. Seepage analyses required by the guidelines were not available.


There were no observed deficiencies or conditions existing at the time of the inspection which indicated an immediate safety hazard. Future corrective action and regular maintenance will be required to correct or control the described deficiencies. In addition, detailed seepage analyses of the existing dam, as required by the guidelines, should be performed. A detailed report discussing each of these deficiencies is attached.

Edwin R. Burton

Edwin R. Burton, PE
Missouri E-10137

Harry I. Callahan

Harry I. Callahan, Partner
Black & Veatch



OVERVIEW OF DAM

FIGURE 1. OVERVIEW OF DAM. (FROM THE REPORT OF THE COMMISSION OF ENQUIRY INTO THE CAUSES OF THE COLLAPSE OF THE DAM AT BRANSON, MISSOURI, 1976.)

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
HARRISON COUNTY DAM C-2

TABLE OF CONTENTS

<u>Paragraph No.</u>	<u>Title</u>	<u>Page No.</u>
SECTION 1 - PROJECT INFORMATION		
1.1	General	1
1.2	Description of Project	1
1.3	Pertinent Data	3
SECTION 2 - ENGINEERING DATA		
2.1	Design	6
2.2	Construction	6
2.3	Operation	6
2.4	Geology	6
2.5	Evaluation	7
SECTION 3 - VISUAL INSPECTION		
3.1	Findings	8
3.2	Evaluation	10
SECTION 4 - OPERATIONAL PROCEDURES		
4.1	Procedures	11
4.2	Maintenance of Dam	11
4.3	Maintenance of Operating Facilities	11
4.4	Description of Any Warning System in Effect	11
4.5	Evaluation	11
SECTION 5 - HYDRAULIC/HYDROLOGIC		
5.1	Evaluation of Features	12
SECTION 6 - STRUCTURAL STABILITY		
6.1	Evaluation of Structural Stability	14
SECTION 7 - ASSESSMENT/REMEDIAL MEASURES		
7.1	Dam Assessment	17
7.2	Remedial Measures	17

TABLE OF CONTENTS (Cont'd)

LIST OF PLATES

<u>Plate No.</u>	<u>Title</u>
1	Location Map
2	Vicinity Topography
3	Dam Plan
4	Principal Spillway & Typical Section
5	Dam Crest Profile & Cross Section
6	Emergency Spillway Profile & Cross Section
7	Boring Plan and Logs
8	Photo Index

LIST OF PHOTOGRAPHS

<u>Photo No.</u>	<u>Title</u>
1	Upstream Face of Dam
2	Upstream Face of Dam at Waterline
3	Crest of Dam Looking West
4	Crest of Dam Looking East
5	Downstream Face of Dam Looking West
6	Downstream Face of Dam Looking East
7	Principal Spillway Drop Inlet Structure
8	Principal Spillway Weir
9	Principal Spillway Pipe Outlet
10	Channel Downstream of Principal Spillway

TABLE OF CONTENTS (Cont'd)

LIST OF PHOTOGRAPHS

<u>Photo No.</u>	<u>Title</u>
11	Emergency Spillway Looking Upstream
12	Emergency Spillway Channel Looking Downstream
13	Dike Along Left Bank of Emergency Spillway
14	Erosion at Toe of Downstream Face of Dam
15	Erosion at Left Abutment - Upstream Face of Dam
16	Drainage Ditch Downstream of Dam
17	Animal Burrow near Crest of Dam
18	Animal Burrow on Upstream Face of Dam

APPENDIX

- Appendix A - Hydrologic and Hydraulic Analyses
- Appendix B - Geologic Investigation & Design Memorandum

SECTION 1 - PROJECT INFORMATION

1.1 GENERAL

a. Authority. The National Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of safety inspection of dams throughout the United States. Pursuant to the above, the District Engineer of the St. Louis District, Corps of Engineers, directed that a safety inspection of the Harrison County Dam C-2 be made.

b. Purpose of Inspection. The purpose of the inspection was to make an assessment of the general condition of the dam with respect to safety, based upon available data and visual inspection, in order to determine if the dam poses hazards to human life or property.

c. Evaluation Criteria. Criteria used to evaluate the dam were furnished by the Department of the Army, Office of the Chief of Engineers, in "Recommended Guidelines for Safety Inspection of Dams." These guidelines were developed with the help of several Federal agencies and many state agencies, professional engineering organizations, and private engineers.

1.2 DESCRIPTION OF PROJECT

a. Description of Dam and Appurtenances.

(1) The dam is an earth structure located in the valley of Panther Creek (see Plate 1). The watershed is an area of low hills with fairly steep rugged terrain devoted primarily to grassland pasture and meadow. Timber occurs mostly adjacent to stream channels and along drainage ways. The dam is approximately 1,500 feet long along its crest and 54 feet high. The dam crest is 13 feet wide. The upstream slope of the dam is broken by a 10 foot wide berm about 12 feet below the crest and another berm just below the principal spillway level. The upstream slope is faced with riprap below the upper berm. The downstream face of the dam slopes uniformly from the crest to a graded 10 foot wide berm about 36 feet below the crest, then slopes to the valley floor below the dam.

(2) The principal spillway is a typical SCS design drop inlet structure with a pipe outlet. The rectangular reinforced concrete drop inlet structure has an overflow weir on two sides and is protected by an angle-iron trash rack supported by concrete walls. The outlet from the drop structure is through a 48-inch diameter reinforced concrete pipe that passes under the dam to a plunge pool and natural stream channel below the dam. The drop structure has a gated reinforced concrete pipe low-level inlet.

(3) The emergency spillway is a 180 foot wide trapezoidal channel cut through the natural abutment around the right end of the dam. The emergency spillway has a natural limestone floor and right bank in the reach at the end of the dam. The downstream reach is grass lined in soil with 8-foot wide dikes along each bank. The dam embankment is protected from emergency spillway flows by a dike along the left bank of the spillway. Reference to right or left as used in this report is defined as right or left while facing in a downstream direction.

b. Location. The dam is located in east central Harrison County, Missouri, as indicated on Plate 1. The lake formed by the dam is in an area shown on the United States Geological Survey 15 minute series quadrangle map for Blythedale, Missouri in Section 36 of T65N, R27W. The lake is shown on the USGS 7.5 minute orthophotograph for Blythedale NW, Missouri.

c. Size Classification. Criteria for determining the size classification of dams and impoundments are presented in the guidelines referenced in paragraph 1.1c above. Based on these criteria, the dam and impoundment are in the intermediate size category. An intermediate size dam is classified as having a height less than 100 feet, but greater than or equal to 40 feet and/or a storage capacity less than 50,000 acre-feet, but greater than or equal to 1,000 acre-feet.

d. Hazard Classification. The hazard classification assigned by the Corps of Engineers for this dam is as follows: The Harrison County Dam C-2 has a high hazard potential, meaning that the dam is located where failure may cause loss of life, and serious damage to homes, agricultural, industrial and commercial facilities, and to important public utilities, main highways, or railroads. For the Harrison County Dam C-2, the estimated flood damage zone extends approximately six miles downstream of the dam. Within the estimated damage zone are four dwellings and two farm buildings. Contents of the estimated downstream damage zone were verified by the inspection team.

e. Ownership. The dam is owned by Jess Hale, Ridgeway, Missouri 64481.

f. Purpose of Dam. The dam forms a 67-acre lake used for recreation, flood control, water supply, and soil stabilization.

g. Design and Construction History. Data relating to the design and construction of the dam were available from the U.S. Department of Agriculture, Soil Conservation Service at Columbia, Missouri. Construction of the dam was completed in October, 1972 by Turner Construction Company, Maryville, Missouri.

h. Normal Operating Procedure. Normal rainfall, runoff, transpiration, evaporation, and overflow through the uncontrolled spillways all combine to maintain a relatively stable water surface elevation.

1.3 PERTINENT DATA

a. Drainage Area - 5,831 acres

b. Discharge at Damsite.

(1) Normal discharge at the damsite is over a weir of the concrete drop inlet structure to a 48-inch reinforced concrete pipe through the embankment.

(2) Estimated experienced maximum flood at damsite - Unknown.

(3) Estimated ungated spillway capacity at maximum pool elevation 20,910 cfs (Probable Maximum Flood Pool El. 931.6).

c. Elevation (Feet above m.s.l.)(Survey elevations).

(1) Top of dam - 928.3 (see Plate 5)

(2) Principal spillway crest - 906.3

(3) Emergency spillway crest - 920.4

(4) Streambed at toe of dam - 873.8

(5) Maximum tailwater - Unknown.

d. Reservoir.

(1) Length of maximum pool - 1.7 miles \pm (Probable maximum flood pool level)

(2) Length of normal pool - 4,600 feet \pm (Principal spillway crest)

e. Storage (Acre-feet).

(1) Top of dam - 3,963

(2) Principal spillway crest - 424

(3) Emergency spillway crest - 2,079

(4) Design surcharge - 1,520 \pm

f. Reservoir Surface (Acres).

(1) Top of dam - 471

- (2) Principal spillway crest - 67
- (3) Emergency spillway crest - 161

g. Dam.

- (1) Type - Earth embankment
- (2) Length - 1,500 feet \pm
- (3) Height - 54 feet \pm
- (4) Top width - 13 feet
- (5) Side slopes - upstream face 1.0 V on 2.5 H design, 1.0 V on 2.6 H field measured, downstream face 1.0 V on 2.5 H design, and 1.0 V on 2.6 H field measured (See Plates 4 & 5).

(6) Zoning - Zone 1 - Core CH material, Zone 2 - upstream and downstream embankment CL material, Zone 3 upstream face limestone riprap, Zone 4 - lower upstream face limestone and shale rock (See Plate 4).

- (7) Impervious core - CH material (See Plate 4).
- (8) Cutoff - Impervious core trench.
- (9) Grout curtain - None.

h. Diversion and Regulating Tunnel - None.

i. Principal Spillway (Survey elevations).

- (1) Type - Overflow weir drop inlet structure to reinforced concrete pipe through dam.
- (2) Crest elevation - 906.3 feet m.s.l.
- (3) Inlet invert elevation - 887.4 feet m.s.l.
- (4) Outlet invert elevation - 884.5 feet m.s.l.
- (5) Gates - Slide gate at low level inlet to drop structure.
- (6) Upstream channel - None.
- (7) Downstream channel - Principal spillway pipe discharges to a riprap lined plunge pool, then to the natural stream below the dam.

j. Emergency Spillway (Survey elevation).

- (1) Type - Trapezoidal open channel.
- (2) Width of channel - 180 feet.
- (3) Crest elevation - 920.4 feet m.s.l.
- (4) Gates - None.
- (5) Upstream channel - Each of the two arms, forming the lake contain a few trees.
- (6) Downstream channel - Grass lined to natural stream below dam.

k. Regulating Outlets ("As-Built" elevation).

- (1) Type - Slide gate low level inlet to drop structure.
- (2) Inlet invert elevation - 888.5 feet m.s.l.

SECTION 2 - ENGINEERING DATA

2.1 DESIGN

Design data in the form of a detailed geologic site investigation report, a design memorandum from the SCS Soils Mechanics Laboratory, "As-Built" drawings and hydrologic/hydraulic data were made available by the Soil Conservation Service. The geology report and design memorandum are included herein as Appendix B. Pertinent data from the "As-Built" drawings are included on Plates 3, 4, & 7. Hydrologic/Hydraulic data provided is included in Appendix A.

2.2 CONSTRUCTION

Construction records in the form of "As-Built" drawings were provided for the dam and spillways. A log of construction is available in the project file through the Soil Conservation Service, Columbia, Missouri office.

2.3 OPERATION

Operational records and documentation of past floods were unavailable.

2.4 GEOLOGY

The site of the dam and reservoir is located across a broad, steep-sided valley cut by Panther Creek. The dam impounds this creek and the drainage from its watershed in Harrison County, Missouri.

The site is located within the Iowa and Missouri Till Plain. The soils of the area consist predominantly of silty clays (CL) with sand and gravel intermixed developed in Kansas age glacial till on the uplands and hill slopes, and silty clay to clayey silt (CL-ML) alluvium and terrace deposits on the valley floor. In addition there is a layer of silty sand (SM) that is present about 1 foot above the bedrock in the valley that is continuous and is assumed to be permeable. Bedrock consists of the interbedded limestones and shales of the Pennsylvanian age Kansas City Group and is buried to a depth of generally greater than 10 feet.

The foundation of the dam is recent alluvial silty clay to clayey silt (CL-ML) overlying the Winterset Limestone of the Dennis Formation to a thickness of 6 to 10 feet. The emergency spillway is cut through this limestone formation at the centerline of the dam.

2.5 EVALUATION

a. Availability. Engineering data were obtained from the Soil Conservation Service as noted in Section 2.1.

b. Adequacy. Engineering data were available from which to make an assessment of the design and construction. Seepage analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available which is considered a deficiency. These seepage analyses should be performed and made a matter of record.

c. Validity. The available engineering data on the design and construction were determined to be valid.

SECTION 3 - VISUAL INSPECTION

3.1 FINDINGS

a. General. A visual inspection of Harrison County Dam C-2 was made on March 3, 1981. The inspection team consisted of Edwin Burton, team leader; Robert Pinker, geologist; Gary Van Riessen, geotechnical engineer; and David Rensing, hydrologist. The dam appeared to be in satisfactory condition. Specific observations are discussed below. No observations were made of the condition of the upstream face of the dam below the pool elevation at the time of the inspection.

b. Dam. The inspection team observed the following conditions at the dam. No cracking, sliding, sloughing or other signs of settlement or instability were observed. There were no instruments on the dam to measure performance.

A wet area was observed downstream of the dam between the principal spillway outlet and the emergency spillway (Photo 16). The inspection team believed that this wet area was due to poor drainage of local runoff. The downstream slope of the embankment had minor irregularities which appeared to be the result of cattle traffic. These irregularities consisted of two or three lines located about one quarter of the way up the slope from the toe where the slope was interrupted by a vertical drop of approximately one foot followed by a flat slope for about one and one half to two feet. Minor erosion was observed on the downstream face of the dam which appeared to have occurred before the grass cover had become established. Erosion gullies were beginning to develop at the embankment-abutment interfaces (Photo 15), on the upstream and downstream side at the left abutment, on the downstream side at the right abutment, and along the toe of the downstream slope (Photo 14) between the left end and the principal spillway. Riprap slope protection in good condition was provided on the upstream face below the upper berm (Photo 2). Slope protection was provided on the downstream slope, the crest, and the upstream slope above the riprap by a good stand of fescue grass. The grass was maintained by cattle grazing. Vehicular traffic has worn tracks and bare areas across the crest of the dam (Photos 3 & 4). Several small trees, 1-inch in size, were growing in the riprap on the upstream face (Photo 2). A few animal burrows were observed on the crest and upstream face of the dam (Photos 17 & 18). There was no evidence to indicate that the dam has ever been overtopped.

c. Appurtenant Structures. The inspection team observed the following items pertaining to the appurtenant structures. The drop inlet structure of the principal spillway appeared to be in good condition (Photos 7 & 8). No cracking, spalling, or other evidence of concrete deterioration was observed. The angle-iron trash rack was secure with no signs of rust. One log, 8 inches in diameter, was jammed against the trash rack but probably would not reduce the capacity of the

inlet. A low-level inlet for lake drawdown was provided on the reservoir side of the structure through a slide gate. The gate was in a closed position. The inspection team was unable to operate the gate. A small stream of water, estimated at approximately 1/2 gallon per minute, was leaking from the side of the gate. The inspection team was unable to measure the gate but estimated its size to be 18 inches in diameter.

The inspection team observed the downstream end of the 48-inch reinforced concrete principal spillway pipe (Photo 9). Three pipe sections supported by a concrete cradle were exposed. The pipe joints appeared to be tight with no obvious movement. The alignment of the pipe appeared to be true and straight when looking through the pipe from the downstream end. Some minor erosion and undercutting of the pipe cradle was observed. Erosion was noted in the plunge pool below the pipe outlet. The elevation of the bottom of the plunge pool at the pipe outlet was field surveyed to be about three feet lower than shown on the "As-Built" drawings.

The emergency spillway is a channel cut into the embankment at the right end of the dam (Photos 11 & 12). The channel was in good condition with no evidence of erosion. The floor of the spillway to about 50 feet downstream of the dam centerline was limestone bedrock. The channel floor for the downstream reach was protected from erosion by a good covering of fescue grass. The embankment was protected from flows in the emergency spillway by an earth dike along the left spillway bank (Photo 13). The dike was also grass covered.

There was no development in the spillway area which would suffer damage due to flow through the spillways.

d. Geology. The soils in the area of the dam and reservoir consist of low plastic silty clays developed in glacial till on the uplands and hillsides and alluvial silty clays to clayey silts on the valley floor. Depth to the interbedded limestones and shales of the Pennsylvanian age Dennis Formation is greater than 10 feet.

A sample of the material in the embankment was taken with an Oakfield sampler from near station 6+00 on the crest. The materials sampled were visually classified for engineering properties as silty sand (SM) top soil for the upper 1-1/2 feet and dark brown silty clay (CL) glacial till from 1-1/2 feet to 2-1/2 feet. The inspectors suspect that the lower sample was from core material. Both abutments are in stiff glacial till classified as silty clay (CL) material.

e. Reservoir Area. No slumping or slides of the reservoir banks were observed. The lake has two arms with Panther Creek forming the east arm and a lesser tributary forming the west arm. The upstream channel to the lake contains a few trees. The lake was noted to be clean with no appreciable siltation.

f. Downstream Channel. The spillways discharge to a natural stream channel containing no obstructions.

3.2 EVALUATION

The various deficiencies observed at the time of the inspection are not believed to represent an immediate safety hazard. They do, however, warrant monitoring and control.

The wet area observed downstream of the dam is believed to be due to poor drainage of local runoff. However, it should be observed during dry periods. If it does not begin to dry up during dry weather, then it should be considered a seep area and monitored regularly.

The gully erosion observed at the abutment-embankment interfaces and at the toe of the downstream slope is where local runoff concentrates. Erosion control in these areas may require riprap or paving.

The irregularities observed on the downstream slope are believed to be the result of cattle traffic on the slopes and are not considered a problem at this time. If the slope irregularities become larger, however, it could lead to erosion and/or sloughing.

The vehicle tracks across the crest of the dam do not constitute a problem at this time but could result in erosion of the crest if not corrected.

The growth of trees on the embankment, if allowed to go unchecked, could cause deterioration of the embankment and displacement of the riprap slope protection. This could lead to erosion of the embankment. The roots of trees can loosen the embankment material and create voids through which water can pass.

Burrowing animals will continue to damage the embankment unless a program is undertaken to eliminate them. Piping failure of the embankment has resulted in similar small earth dams as the result of burrowing animal damage.

The low level slide gate inlet to the principal spillway drop structure is to provide for drawdown of the reservoir which is a safety feature. The design drawdown time is ten days. The inoperable condition of the gate will hinder and delay any drawdown operations if a crisis were to arise. The observed leakage from the gate is not considered a safety deficiency but if not corrected it will probably worsen and could result in draining the reservoir.

SECTION 4 - OPERATIONAL PROCEDURES

4.1 PROCEDURES

The pool is primarily controlled by rainfall, runoff, evaporation, transpiration, and capacity of the uncontrolled spillway.

4.2 MAINTENANCE OF DAM

Maintenance is the responsibility of the Soil and Water Conservation District for the Panther Creek watershed. There was no evidence that a maintenance program was in effect. The grass cover is maintained by cattle grazing.

4.3 MAINTENANCE OF OPERATING FACILITIES

The slide gate at the low level inlet to the drop structure has not been maintained in an operating condition.

4.4 DESCRIPTION OF ANY WARNING SYSTEM IN EFFECT

There is no existing warning system or preplanned scheme for alerting downstream residents for this dam.

4.5 EVALUATION

A maintenance program should be implemented to include removal of trees from the embankment and control of animal burrowing. The slide gate should be repaired and maintained.

SECTION 5 - HYDRAULIC/HYDROLOGIC

5.1 EVALUATION OF FEATURES

a. Design Data. Limited design data pertaining to hydrology and hydraulics were available from the Soil Conservation Service (SCS). Independent calculations were performed for this evaluation in accordance with the guidelines referenced in Section 1.1c and the St. Louis District Hydrologic/Hydraulic Standards, Phase I Safety Inspection of Non-Federal Dams, 22 August 1980. The SCS data provided for an emergency spillway design for a 2 percent chance (50-year) storm of 6 hours duration. The design resulted in an emergency spillway maximum discharge of 718 cubic feet per second at a flow velocity of 5.7 feet per second and a maximum water surface elevation of 922.2. This design considered routing through three upstream structures. The freeboard design by SCS considered a 13.70 inch rainfall on an uncontrolled watershed to produce a maximum emergency spillway discharge with a maximum water surface elevation of 927.9. A copy of the design data is included in Appendix A.

b. Experience Data. The drainage area and lake surface area are from the "As-Built" data and from the USGS Blythedale, Missouri Quadrangle Map. The dam and spillway layouts are from a survey made during the inspection and from "As-Built" drawings.

c. Visual Observations.

(1) The principal spillway appears to be in good condition. The lake level at the time of the inspection was at the inlet weir crest with a small flow going over the weir. One large log was against the trash rack but was not effecting the spillway capacity. The spillway outlet pipe discharges with a free outfall into a plunge pool then to the natural channel of Panther Creek. There were no obstructions to flow through the principal spillway.

(2) The emergency spillway appeared to be in good condition. The floor of the spillway adjacent to the end of the dam was exposed limestone bedrock. The downstream spillway channel was grass lined. There were no obstructions to flow in the emergency spillway.

(3) Spillway discharges do not endanger the integrity of the dam.

d. Overtopping Potential. The spillways will not pass the probable maximum flood without overtopping the dam. The probable maximum flood is defined as the flood discharge that may be expected from the most severe combination of critical meteorologic and hydrologic conditions that are reasonably possible in the region. The spillway will pass 40 percent of the probable maximum flood without overtopping the dam. The spillway will pass the one percent probability flood as indicated by

comparison of the one percent probability rainfall total to the rainfall totals of the various ratios of the probable maximum storm. According to the recommended guidelines from the Department of the Army, Office of the Chief of Engineers, a high hazard dam of intermediate size should pass 100 percent of the probable maximum flood. The portion of the estimated peak discharge of 50 percent of the probable maximum flood overtopping the dam would be 135 cfs of the total discharge from the reservoir of 13,345 cfs. The estimated duration of overtopping is 2.1 hours with a maximum height of 0.7 feet. The portion of the estimated peak discharge of the probable maximum flood overtopping the dam would be 15,900 cfs of the total discharge from the reservoir of 36,810 cfs. The estimated duration of overtopping is 4.8 hours with a maximum height of 3.3 feet. The embankment could be jeopardized should overtopping occur for these periods of time. The good stand of grass on the embankment will reduce the potential for erosion.

According to the St. Louis District, Corps of Engineers, the effect from rupture of the dam could extend approximately six miles downstream of the dam. Within the estimated damage zone are four dwellings and two farm buildings. Contents of the estimated downstream damage zone were verified by the inspection team. There does not appear to be any flood plain regulations or other constraints in force to limit future downstream development.

SECTION 6 - STRUCTURAL STABILITY

6.1 EVALUATION OF STRUCTURAL STABILITY

a. Visual Observations. Visual observations of conditions which affect the structural stability of this dam are discussed in section 3, paragraph 3.1b.

b. Design and Construction Data. Design data relating to the structural stability of the dam were available from the United States Department of Agriculture, Soil Conservation Service which consisted of Detailed Geologic Investigation of Dam Sites, 12-13-67 and Memorandum to James M. Dale, State Conservation Engineer from Lorn P. Dunnigan, Head Soil Mechanics Laboratory, SCS, dated April 30, 1968.

"As-Built" construction drawings, dated October 3, 1972 were available from the Soil Conservation Service.

As reported in the SCS data, samples for testing were obtained from borings located within the original site area. One jar and two undisturbed samples were submitted to the laboratory to represent the foundation materials. One large bag sample from the emergency spillway and eleven large bag samples from the flood plain area were submitted to represent available fill material.

Laboratory tests performed for the dam design include:

(1) Foundation Area.

- a) Atterberg Limits
- b) Sieve Analysis
- c) Dry Unit Weight
- d) One Dimensional Consolidation Test
- e) Permeability
- f) Triaxial Shear Test (CU)

(2) Embankment Materials.

- a) Atterberg Limits
- b) Sieve Analysis

- c) Standard Proctor Test
- d) Triaxial Shear Test (CU)

(3) Stability Loading Conditions.

Stability analyses performed by the SCS for the dam design included consideration of two loading conditions:

- a) Steady Seepage
- b) Full Drawdown

(4) Stability Analysis.

a) Maximum Section at Station 6+25: A slope stability analysis was made on the 2-1/2:1 upstream embankment slope using a modified Swedish circle method. Rapid drawdown from the emergency spillway to the base of the embankment is considered. The embankment will rest on bedrock after normal channel cleanout; therefore, the foundation is considered competent. Strength parameters used for the embankment are $\phi = 10.5^\circ$, $c = 850$ psf. No berms were considered in this analysis and the computed factor of safety is 1.58.

The downstream 2-1/2:1 embankment slope stability analysis considered a full phreatic line (no drain) and a competent foundation. With embankment strength parameters of $\phi = 10.5^\circ$, $c = 850$ psf the computed factor of safety is 1.66.

b) Flood plain Section at Station 6+10: The slope stability analysis of the 2-1/2:1 upstream embankment slope was made using the modified Swedish circle method. Rapid drawdown from the emergency spillway to the base of the embankment is considered. The embankment strength parameters used are $\phi = 10.5^\circ$, $c = 850$ psf. A foundation depth of 11 feet, strength parameters of $\phi = 14.5^\circ$ and $c = 400$ psf were considered and the computed factor of safety is 1.29. No berms were considered in the analysis.

The downstream 2-1/2:1 embankment slope stability analysis considers a full phreatic line (no drain) and an 11-foot depth of foundation. The strength parameters considered are the same as the upstream and the computed factor of safety is 1.29.

(5) Evaluation. The available stability analyses performed by the SCS included the factor of safety for steady seepage and full drawdown loading conditions. Factors of safety for the maximum section were well within the acceptable limits suggested by Appendix D of the guidelines. The flood plain section safety factor is less than the acceptable limits; however, the analysis did not include the berms.

Stability analyses for the partial pool and earthquake loading conditions were not available. The conditions, assumptions, and strength parameters for the full drawdown and steady seepage stability analyses represent a more critical stability condition than for partial pool. The factors of safety determined for the steady seepage and full drawdown loading conditions are about equal to or greater than the suggested factor of safety for the partial pool loading condition.

Stability analyses for the earthquake loading conditions were not available. In accordance with the guidelines, the dam is located within Seismic Zone 1 with a designated seismic coefficient of 0.025 to be used in the conventional equivalent static force method of analysis.

Seepage analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available. The design memorandum indicates that near positive cutoff is anticipated and a drain system was not considered necessary for stability of the embankment.

The embankment design provided for a settlement allowance of 1.5 feet. A crest of dam profile survey made as part of the inspection revealed that the anticipated settlement of the embankment has not taken place since construction of the dam.

c. Operating Records. No operational records were available for review by the inspection team.

d. Postconstruction Changes. There have been no post construction changes. Sheet 4 of the "As-Built" drawings shows a 15-inch low level inlet to the drop structure. Sheet 13 of the "As-Built" drawings shows the low level inlet to be 18 inches in diameter. The inspection team was unable to measure the size of this inlet.

e. Seismic Stability. The dam is located in Seismic Zone 1 which is a zone of minor seismic risk. A properly designed and constructed earth dam using sound engineering principles and conservatism should pose no serious stability problems during earthquakes in this zone. An assesment of the seismic stability is a requirement of the guidelines.

SECTION 7 - ASSESSMENT/REMEDIAL MEASURES

7.1 DAM ASSESSMENT

a. Safety. Several conditions observed during the visual inspection by the inspection team should be monitored, corrected, and/or controlled. These are erosion at the downstream toe of slope and at both abutment/embankment interfaces, the wet area downstream of the dam, the growth of trees on the embankment, animal burrows in the embankment, irregularities in the downstream slope, vehicle tracks on the crest of the dam, and the inoperable slide gate. Seepage analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available, which is considered a deficiency.

b. Adequacy of Information. The conclusions in this report were based only on performance history and visual conditions and the available engineering design data. The inspection team considers that these data are sufficient to support the conclusions herein. Seepage analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available, which is considered a deficiency.

c. Urgency. It is the opinion of the inspection team that a program should be developed as soon as possible to implement remedial measures recommended in paragraph 7.2b. If the safety deficiencies listed in paragraph 7.1a are not corrected, they will continue to deteriorate and lead to a serious potential of failure. The item recommended in paragraph 7.2a should be pursued on a high priority basis.

d. Necessity for Phase II. The Phase I investigation does not raise any serious questions relating to the safety of the dam nor does it identify any serious dangers which would require a Phase II investigation. However, the additional analyses noted in paragraph 2.5b are necessary for compliance with the guidelines.

e. Seismic Stability. This dam is located in Seismic Zone 1 which is a zone of minor seismic risk. A properly designed and constructed earth dam using sound engineering principals and conservatism should pose no serious stability problems during earthquakes in this zone. However, an assessment of the seismic stability is required by the guidelines.

7.2 REMEDIAL MEASURES

a. Alternatives. The spillway capacity and/or height of the dam would need to be increased or the lake level would need to be permanently lowered to increase available flood storage in order to pass the spillway design flood.

b. Operation and Maintenance Procedures. The following operation and maintenance procedures are recommended and should be carried out under the direction of a professional engineer experienced in the design, construction, and maintenance of earth dams.

(1) The irregularities in the downstream slope should be monitored. If they become larger, grazing of cattle on the dam should be stopped or reduced. Should the irregularities continue to worsen, the condition should be evaluated by an engineer.

(2) The wet area below the dam noted during the visual inspection should be closely monitored during dry periods to determine if it is dam related. If it is determined to be due to seepage, it should be monitored and documented regularly and any significant changes should be evaluated.

(3) An improved maintenance program to remove and control the growth of brush and trees on the embankment should be developed.

(4) The erosion gullies at the downstream toe of slope and at the interface of the embankment and the right and left abutments should be backfilled with suitable material and compacted. Paved ditches, riprap, or other slope protection may be required to control the concentrated runoff.

(5) The animal burrows in the embankment should be corrected since they can lead to piping. Control measures should be implemented under the direction of a qualified engineer to discourage increased animal activity in the area. The embankment slope should be monitored during this repair.

(6) The slide gate for the low level inlet to the drop structure of the principal spillway should be repaired and maintained in working condition.

(7) Seepage analyses should be performed and made a matter of record.

(8) A detailed inspection of the dam should be made periodically. The results should be recorded and made a matter of record. More frequent inspections may be required if additional deficiencies are observed or the severity of the reported deficiencies increase.





PLATE I



**HARRISON COUNTY DAM C-2
VICINITY TOPOGRAPHY**

SCALE IN MILES








PLATE 3



**HARRISON COUNTY DAM C-2
PRINCIPAL SPILLWAY
& TYPICAL SECTION**







PLATE 6



SCALE IN FEET
200 100 0 200 400

NOTE: TAKEN FROM "AS-BUILT" DRAWINGS

SCALE IN FEET
100 50 0 100 200

HARRISON COUNTY DAM C-2
BORING PLAN AND LOGS




PLATE 8




PHOTO 1: UPSTREAM FACE OF DAM



PHOTO 2: UPSTREAM FACE OF DAM AT WATERLINE




PHOTO 3: CREST OF DAM LOOKING WEST




PHOTO 4: CREST OF DAM LOOKING EAST




PHOTO 5: DOWNSTREAM FACE OF DAM LOOKING WEST




PHOTO 6: DOWNSTREAM FACE OF DAM LOOKING EAST




PHOTO 7: PRINCIPAL SPILLWAY DROP INLET STRUCTURE



PHOTO 8: PRINCIPAL SPILLWAY WEIR




PHOTO 9: PRINCIPAL SPILLWAY PIPE OUTLET




PHOTO 10: CHANNEL DOWNSTREAM OF PRINCIPAL SPILLWAY




PHOTO 11: EMERGENCY SPILLWAY LOOKING UPSTREAM



PHOTO 12: EMERGENCY SPILLWAY LOOKING DOWNSTREAM



PHOTO 13: DIKE ALONG LEFT BANK OF EMERGENCY SPILLWAY



PHOTO 14: EROSION AT TOE OF DOWNSTREAM FACE OF DAM




PHOTO 15: EROSION AT LEFT ABUTMENT - UPSTREAM FACE OF DAM



PHOTO16: DRAINAGE DITCH DOWNSTREAM OF DAM




PHOTO 17: ANIMAL BURROW NEAR CREST OF DAM



PHOTO 18: ANIMAL BURROW ON UPSTREAM FACE OF DAM

APPENDIX A
HYDROLOGIC AND HYDRAULIC ANALYSES

HYDROLOGIC AND HYDRAULIC ANALYSES

To determine the overtopping potential, flood routings were performed by applying the Probable Maximum Precipitation (PMP) to a synthetic unit hydrograph to develop the inflow hydrographs for Harrison County Dam C-2 and five upstream reservoirs, Harrison County Dam B-11, Harrison County Dam B-13, Harrison County Dam B-10, Tugglet's Dam LT-93, and Meek's Dam LT-84. The inflow hydrographs were then routed through the reservoirs and spillways. The overtopping analysis was determined using the computer program HEC-1 (Dam Safety Version) (1).

The PMP was determined from regional charts prepared by the National Weather Service in "Hydrometeorological Report No. 33" (HMR-33) (2). Reduction factors were not applied. The rainfall distribution for the 24-hour PMP storm was determined according to the procedures outlined in HMR-33 and EM 1110-2-1411 (3). Comparison of the routings of the PMP storm ratios with the total rainfall of a 24 hour, one percent chance probability storm indicates that the one percent chance flood will not cause overtopping of Harrison County Dam C-2.

The synthetic unit hydrograph for the watershed was developed by the computer program using the Soil Conservation Service (SCS) method (1, 4). The parameters for the unit hydrograph are shown in Table 1. The lag and time of concentration for each watershed were obtained from SCS design data and were verified using the Kirpich and Snyder methods.

The SCS curve number (CN) method was used in computing the infiltration losses for the rainfall-runoff relationship. The CN values used, and the result from the computer output, are shown in Table 2.

Storms were routed through the six reservoirs noted above.

Routing through the reservoirs was performed using the modified Puls Method. The initial reservoir pool elevations for the routing of each storm were determined to be equivalent to the crest elevations of the principal spillways in accordance with antecedent storm conditions preceding the probable maximum storm outlined by the U.S. Army Corps of Engineers, St. Louis District (5). The hydraulic capacity of the spillways and the storage capacity of the reservoirs were defined by the elevation, surface area, storage, and discharge relationships shown in Table 3.

The rating curves for the spillways are shown in Table 4. The flow over the crests of the dams was determined using either the non-level dam crest option (\$L and \$V cards) or the weir flow option of the HEC-1 program. The program assumes critical flow over a broad-crested weir in the non-level dam crest option.

Breach analyses were performed using HEC-1 for reservoirs upstream of Harrison County Dam C-2 with spillway capacities less than 50 percent of the PMF. The breaching parameters are shown in Table 5.

The result of the routing analysis indicates that 40 percent of the Probable Maximum Flood (PMF) will not overtop Harrison County Dam C-2.

A summary of the routing analysis for different ratios of the PMF is shown in Table 6.

The computer input data and a summary of the output data are presented at the back of this appendix.

"As-Built" drawings and hydrologic/hydraulic design data for Harrison County Dam C-2 and the upstream reservoirs were made available by the SCS, Columbia, Missouri.

TABLE 1

SYNTHETIC UNIT HYDROGRAPH

Parameters:	Harrison County Dam B-10	Harrison County Dam B-11	Harrison County Dam B-13	Meek's Dam LT-84	Tuggett's Dam LT-93	Harrison ⁴ County Dam C-2 East Arm West Arm
Drainage Area (A) ¹	1.01 sq. mi.	0.32 sq. mi.	0.76 sq. mi.	0.39 sq. mi.	0.36 sq. mi.	3.52 sq. mi.
Lag Time (L _g)	0.32 hour	0.19 hour	0.32 hour	0.22 hour	0.20 hour	1.33 hour
Time of concentration (T _c)	0.53 hour ²	0.31 hour ²	0.54 hour ²	0.37 hour ³	0.34 hour ³	2.21 hour ²
Duration (D)	4.2 minutes	2.5 minutes	4.3 minutes	3.0 minutes	2.7 minutes	17.7 minutes

(Use 5 minutes in each case for the duration)

NOTES:

- 1 - Incremental drainage areas. Total drainage area for Harrison County Dam C-2 is 9.11 square miles.
- 2 - Obtained from SCS design data. These values are comparable to those calculated using the Kirpich method.
- 3 - Calculated using the Kirpich method.
- 4 - The portion of the Harrison County Dam C-2 drainage area below the upstream reservoirs was divided into the east and west arm for performing the hydrologic analyses.

Unit Hydrograph Ordinates
Discharge (cfs)*

	Harrison County Dam B-10	Harrison County Dam B-11	Harrison County Dam B-13	Meek's Dam LT-84
<u>Time (Min.)*</u>				
0	0	0	0	0
5	174	182	125	147
10	556	579	400	502
15	1,098	670	795	706
20	1,342	484	993	630
25	1,291	252	968	419
30	1,065	141	807	239
35	728	77	567	146
40	484	43	377	87
45	337	24	262	52
50	232	13	184	31
55	159	7	126	19
60	108	4	87	11
65	73	2	59	7
70	51	0	41	4
75	35		28	2
80	24		20	0
85	17		14	
90	12		10	
95	8		7	
100	5		4	
105	2		2	
110	0		0	

* From HEC-1 computer output

FORMULAS USED:

$$T_c = (11.9 \times L^3/H)^{0.385} (6)$$

$$L_g = 0.6 T_c$$

$$D = 0.133 T_c$$

Unit Hydrograph Ordinates
Discharge (cfs)*
 (Continued)

<u>Time (Min.)*</u>	Tugglet's	Harrison	
	Dam LT-93	East Arm	County Dam C-2 West Arm
0	0	0	0
5	167	23	74
10	554	56	232
15	704	109	446
20	575	173	743
25	327	243	1,121
30	188	334	1,472
35	109	438	1,710
40	63	559	1,819
45	36	698	1,828
50	21	839	1,763
55	12	960	1,623
60	7	1,062	1,463
65	4	1,145	1,260
70	2	1,195	1,013
75	0	1,232	815
80		1,239	674
85		1,238	557
90		1,231	469
95		1,187	392
100		1,139	326
105		1,086	265
110		1,028	223
115		967	185
120		892	153
125		810	127
130		719	104
135		640	87
140		566	72
145		513	60
150		464	50
155		418	41
160		379	34
165		343	28
170		315	24
175		288	20
180		260	17
.		.	.
.		.	.
410		0	0

TABLE 2
RAINFALL-RUNOFF VALUES

<u>Selected Storm Event</u>	<u>Storm Duration (Hours)</u>	<u>Rainfall (Inches)</u>	<u>Runoff (Inches)</u>	<u>Loss (Inches)</u>
PMP				
Harrison County Dam B-10	24	31.07	29.91	1.16
Harrison County Dam B-11	24	31.07	29.78	1.29
Harrison County Dam B-13	24	31.07	29.78	1.29
Meek's Dam LT-84	24	31.07	29.78	1.29
Tugglet's Dam LT-93	24	31.07	29.78	1.29
Harrison County Dam C-2				
East Arm	24	31.07	29.78	1.29
West Arm	24	31.07	29.78	1.29

Additional Data:

	SCS Runoff Curve Number (CN)	
	AMC II ¹	AMC III ²
Harrison County Dam B-10	79	91
Harrison County Dam B-11	78	90
Harrison County Dam B-13	78	90
Meek's Dam LT-84	78	90
Tugglet's Dam LT-93	78	90
Harrison County Dam C-2	78	90

¹ Obtained from SCS "As-Built" data

² Used for PMF runoff hydrograph calculations

TABLE 3

ELEVATION, SURFACE AREA, STORAGE, AND DISCHARGE RELATIONSHIPS

Elevation (feet-MSL)	Lake Surface Area (acres)	Lake Storage (acre-ft)	Spillway Discharge (cfs)
Harrison County			
Dam B-10			
*122.0 ¹	19.2	128	0
**126.8	29.0	243	80
***129.1	35.7	318	498
Harrison County			
Dam B-11			
*80.0 ¹	3.9	19	0
**84.0	6.9	40.6	40
***86.8	9.5	65	268
Harrison County			
Dam B-13			
*112.0 ¹	11.6	93	0
**116.4	18.5	160	77
***118.7	28.8	214	780
Meek's Dam			
LT-84			
*94.0 ¹	6	27	0
**96.9	9.9	48.7	5
***101.0	10.5	89	1,048
Tugglet's Dam			
LT-93			
*95.0 ¹	5	25	0
**98.0	7.5	40	11
***101.3	10.3	88	478
Harrison County			
Dam C-2			
*906.3 ²	67	424	0
**920.4	161	2,079	362
***928.3	471	3,963	11,791

*Principal spillway inlet crest elevation

**Emergency spillway crest elevation

***Top of dam elevation

The relationships in Table 3 were developed from the SCS "As-Built" data and the field measurements.

¹ Elevation based on arbitrary datum for specific site

² Elevation in feet m.s.l.

TABLE 4

SPILLWAY RATING CURVE

<u>Reservoir Elevation</u>	<u>Principal Spillway Discharge (cfs)</u>	<u>Emergency Spillway Discharge (cfs)</u>	<u>Total Spillway Discharges (cfs)</u>
Harrison County			
Dam B-10			
*122.0 ¹	0	0	0
122.5	73	0	73
**126.8	80	0	80
127.8	80	100	180
***129.1	81	417	498
131.8	81	1,700	1,781
Harrison County			
Dam B-11			
*80.0 ¹	0	0	0
82.0	12	0	12
**84.0	40	0	40
85.0	41	15	56
***86.8	44	224	268
89.0	48	970	1,018
Harrison County			
Dam B-13			
*112.0 ¹	0	0	0
114.5	63	0	63
**116.4	77	0	77
117.5	79	222	301
***118.7	81	699	780
120.6	84	1,820	1,904
Meek's Dam LT-84			
*94.0 ¹	0	0	0
95.0	2	0	2
**96.9	5	0	5
98.9	7	314	321
***101.0	8	1,040	1,048
103.9	9	2,680	2,689

TABLE 4
SPILLWAY RATING CURVE
(Continued)

<u>Reservoir Elevation</u>	<u>Principal Spillway Discharge (cfs)</u>	<u>Emergency Spillway Discharge (cfs)</u>	<u>Total Spillway Discharges (cfs)</u>
Tugget's Dam LT-93			
*95.0 ¹	0	0	0
96.0	3	0	3
**98.0	11	0	11
100.0	15	193	208
***101.3	18	460	478
103.0	20	985	1,005
Harrison County Dam C-2			
*906.3 ²	0	0	0
910.3	299	0	299
**920.4	362	0	362
924.4	384	3,616	4,000
***928.3	404	11,387	11,791
931.0	420	18,600	19,020

*Principal spillway crest elevation
 **Emergency spillway crest elevation
 ***Top of dam elevation

¹ Elevation based on arbitrary datum for specific site

² Elevation in feet m.s.l.

METHOD USED:

Principal spillway release rates were determined from SCS "As-Built" data which utilized the weir flow and pipe flow equations.

Emergency spillway releases were determined from the SCS "As-Built" data and SCS Technical Release No. 39⁽⁷⁾.

TABLE 5

BREACHING PARAMETERS

	Harrison County Dam B-10	Harrison County Dam B-11	Harrison County Dam B-13	Meek's Dam LT-84	Tugglet's Dam LT-93
Bottom Width of Breach (BRWID)	10.0 feet	10.0 feet	10.0 feet	10.0 feet	10.0 feet
Side Slope of Breach (z) (In feet horizontal to 1.0 feet vertical)	0.5	0.5	0.5	0.5	0.5
Elevation of Breach Bottom at Maximum Size of Breach (ELBM)	108.0 feet	68.0 feet	92.0 feet	85.0 feet	83.0 feet
Time for Breach to Develop to Maximum Size (TFAIL)	1.0 hour	1.0 hour	1.0 hour	1.0 hour	1.0 hour
Elevation of Water Surface Which Will Cause Dam to Fail (FAILEL)	129.10 feet	86.8 feet	118.7 feet	101.0 feet	101.3 feet

TABLE 6

RESULTS OF FLOOD ROUTINGS

Ratio of PMF	Peak Inflow (CFS)	Peak Lake Elevation (ft.-MSL)	Total Storage (AC.-FT.)	Peak Outflow (CFS)	Depth (ft.) Over Top of Dam	Duration of Overtopping (Hours)
-	0	*906.3	424	0	-	-
0.40	22,087	927.9	3,789	10,880	0	-
0.45	23,286	928.5	4,037	12,165	0.2	1.1
0.50	25,458	929.0	4,252	13,345	0.7	2.1
1.00	43,125	931.6	5,338	36,810	3.3	4.8

* Principal spillway crest elevation

BIBLIOGRAPHY

- (1) U.S. Army Corps of Engineers, Hydrologic Engineering Center, Flood Hydrograph Package (HEC-1), Dam Safety Version, July 1978, Modification April 1980, Davis, California.
- (2) HMR 33, Seasonal Variations of Probable Maximum Precipitation, East of the 105th Meridian for Areas 10 to 1000 Square Miles and Durations from 6 to 48 Hours, U.S. Department of Commerce, NOAA, National Weather Service, 1956.
- (3) U.S. Department of the Army, Corps of Engineers, Standard Project Flood Determinations, Civil Engineer Bulletin No. 52-8, EM 1110-2-1411, Revised 1965, Washington, D.C.
- (4) U.S. Department of Agriculture, Soil Conservation Service, National Engineering Handbook, Section 4, Hydrology, August 1972.
- (5) U.S. Army Corps of Engineers, St. Louis District, Hydrologic/Hydraulic Standards, Phase I Safety Inspection of Non-Federal Dams, 22 August 1980.
- (6) U.S. Department of the Interior, Bureau of Reclamation, Design of Small Dams, 1974, Washington, D.C.
- (7) U.S. Department of Agriculture, Soil Conservation Service, Technical Release No. 39, Hydraulics of Broad-Crested Spillways, May 1968.
- (8) U.S. Department of the Interior, Geological Survey, Techniques of Water Resources Investigations of the United States Geological Survey, Chapter A5, 1967.
- (9) U.S. Department of Agriculture, Soil Conservation Service, Soil Interpretations Record, 1979.

APPENDIX B
GEOLOGIC INVESTIGATION
&
DESIGN MEMORANDUM

DETAILED GEOLOGIC INVESTIGATION OF DAM SITES

GENERAL

State Missouri County Harrison ; k. k. Sec. 36 T. 65N R. 27W; Watershed Punther Creek
Subwatershed Fund class WP-08-5 Site number C-2 Site group I Structure class a
Investigated by Nuel E. Johnson (signature and title) Geologist Equipment used Feiling 1500 (Type, size, make, model, etc.) Date 12-13-67

SITE DATA

Drainage area size 9.1 sq. mi., 5831 acres. Type of structure D.I. concrete Purpose Floodwater
Direction of valley trend (downstream) SE Maximum height of fill 45.8 feet. Length of fill 1450 feet.
Estimated volume of compacted fill required 172,000 yards

STORAGE ALLOCATION

	Volume (ac. ft.)	Surface Area (acres)	Depth at Dam (feet)
Sediment	<u>476</u>	<u>67.5</u>	<u>25.6</u>
Floodwater	<u>1615</u>	<u>160</u>	<u>39.2</u>

SURFACE GEOLOGY AND PHYSIOGRAPHY

Physiographic description Disected Till Plain, Topography Rolling, Attitude of beds: Dip 0 Strike
Steepness of abutments: Left 23 percent; Right 9 percent. Width of floodplain at centerline of dam 300 feet
General geology of site: The site is located in National Soil Resource Area 109, the Iowa & Missouri Till Plain. The Kansan till occurs on the slopes & ridges with modern alluvium and terrace level alluvium occurring in the valley floor. Kansan till in the area is classified as a stiff cl, coarse material is predominately sand and fine gravel with few glacial rocks larger than cobbles. The stream channel has cut into and is now held by the underlying Winterset limestone which is a member of the Dennis Formation, Kansas City Group, Pennsylvanian System. The site is located in an area devoted to pasture & meadow. Timber occurs mostly adjacent to the stream channel and other drainage ways

C-2
Panther Creek
DETAILED GEOLOGIC INVESTIGATION OF DAM SITES

Drainage, Borrow

FEATURE Q Dam, Principal Spillway, Emergency Spillway, Stream Channel,
(CENTERLINE OF DAM, PRINCIPAL SPILLWAY, EMERGENCY SPILLWAY, THE STREAM CHANNEL, INVESTIGATIONS FOR DRAINAGE OF STRUCTURE, BORROW AREA, RESERVOIR BASIN, ETC.)

DRILLING PROGRAM

EQUIPMENT USED	NUMBER OF HOLES		NUMBER OF SAMPLES TAKEN		
	EXPLORATION	SAMPLING	UNDISTURBED	DISTURBED	
			(STATE TYPE)	LARGE	SMALL
<u>6" Slat Auger</u>	<u>31</u>	<u>12</u>	<u>2 Shelby</u>	<u>12 Bag</u>	<u>1 Jar</u>
<u>NX Core</u>	<u>6</u>				
<u>NX Core, pressure test</u>	<u>3</u>				
TOTAL	<u>40</u>	<u>12</u>	<u>2</u>	<u>12</u>	<u>1</u>

SUMMARY OF FINDINGS
(INCLUDE ONLY FACTUAL DATA)

The left abutment is stiff glacial Till. Bedrock occurred in Test Hole #2 at 17.6 feet, elevation 975.4. Pressure tests were made in the rock without water loss. The right abutment is also till, however, bedrock was not encountered in test holes #10 & #11. The bedrock of the valley floor has a rather uniform surface at approximate elevation 889.0. The overlying alluvium ranges in depth from 6 to 10 feet. An apparent old channel occurs on the right side as shown by Test Hole #4, station 6+25. Material in the lower part is classified SM and SC. Similar conditions were found 50 feet upstream and 35 feet downstream. The surface alluvium is classified CL except for the material adjacent to the channel in TH #302 which was classified ML. A stratum of coarser material classified SM occurs about 1 foot above the contact of the bedrock. This stratum is continuous and believed permeable. A rock core was taken in TH #3. Rock occurred at 9.5' and was penetrated 4 feet with the slat auger. The upper 2 feet of core appeared weathered and broken. The remaining core was unweathered and sound rock. The gentle slope from station 7+00 to approximately 13+00 is classified as stiff CL Terrace alluvium. Test holes

C-2
Parthen Creek
DETAILED GEOLOGIC INVESTIGATION OF DAM SITES

FEATURE _____
(CENTERLINE OF DAM, PRINCIPAL SPILLWAY, EMERGENCY SPILLWAY, THE STREAM CHANNEL, INVESTIGATIONS FOR DRAINAGE OF STRUCTURE, BORROW AREA, RESERVOIR BASIN, ETC.)

DRILLING PROGRAM

EQUIPMENT USED	NUMBER OF HOLES		NUMBER OF SAMPLES TAKEN		
	EXPLORATION	SAMPLING	UNDISTURBED	DISTURBED	
			(STATE TYPE)	LARGE	SMALL
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
7	TOTAL	_____	_____	_____	_____

SUMMARY OF FINDINGS
(INCLUDE ONLY FACTUAL DATA)

6, 7, 8, & 9 were bottomed in bedrock or carried to refusal. Rock core was taken in test hole #6 and pressure test of the bedrock were made without water loss. Alluvium underlain with limestone at a relatively uniform elevation forms the foundation of the principal spillway. The alluvium is similar to the alluvium on the S of Dam and is 10 to 12 feet deep. The pier location is in the channel and on bedrock. A core was taken from this test hole. Bedrock occurs at shallow depths on the centerline of the emergency spillway. The overburden is classified as stiff cl. glacial till or residuum. The underlying bed rock is mostly limestone with interbedded thin shale beds with lesser amounts of shale. The depth of weathering in the bedrock is approximately 3 to 7 feet. The underlying sound rock is thin to medium bedded limestone with interbedded gray shale. Borrow will be Terrace level alluvium classified stiff cl. and alluvium classified Mh and Ch. There is sufficient borrow available below the crest elevation of the principal spillway. Bedrock occurs at shallow depth in the stream channel or the channel is on bedrock. Channel deposits are seasonal and change frequently.

10-59

DETAILED GEOLOGIC INVESTIGATION OF DAM SITES

State Missouri County Harrison Watershed Panther Creek Subwatershed _____
Site number C-2 Site group F Structure class a Investigated by Dwight K. Reynolds Date 12-13-67
(signature of Geologist)

INTERPRETATIONS AND CONCLUSIONS

The weakest material in the embankment foundation appeared to be the alluvium of the valley floor. Samples were taken from TH 301, 2 principal spillway 1450 as being most representative of the material classified CL & SM. The alluvial material classified ML on the surface is confined to the area immediately adjacent to the right side of the channel and limited in extent. The old channel on the right side of the floodplain between & stations 6400 and 6440 appears to extend the width of the foundation. The material to the right of station 6450 is classified mostly a stiff CL and occurs as terrace level alluvium, till or residuum. The underlying coarse material in test holes 6, 7, 8 & 9 is classified SC & GC and believed not permeable. The GC material in TH #7 was sampled for laboratory classification. Several pressure tests were made in the bedrock with no unfavorable results were in the upper part of the limestone which was classified as weathered. At the proposed location of the principal spillway the alluvium varies somewhat in texture but the depth and the elevation of the underlying bedrock is generally uniform. The overburden of the emergency spillway was sampled for borrow and is representative of material which will not contain broken or weathered rock fragments. The depth of weathering of the bedrock is variable due to the different thickness and sequence of the shale and limestone beds and which was exposed to weathering. This was discussed with the project engineer and estimates were made on how much of the weathered rock could be classed as common excavation and are indicated on the engineers field design prints of the geology sheets. The underlying or unweathered rock will stand on a vertical cut.

DETAILED GEOLOGIC INVESTIGATION OF DAM SITES

10-59

State Missouri County Harrison Watershed Reister Creek Subwatershed _____
Site number C-2 Site group _____ Structure class _____ Investigated by Dwight L. Edwards Date _____
(signature and title)
Geologist

INTERPRETATIONS AND CONCLUSIONS

There is sufficient Borrow available below the crest elevation of the principal spillway. However, a higher water level in the alluvial areas at construction will increase haul distance.

Estimated cu/yds of compacted fill available.

Borrow Hole	@ cu/yds
101	19,200
102, 104, 106, 109	30,000 per ft depth
103	3,600
107	19,200
105, 108	27,800
Emergency Spillway	16,500 Common
	7,500 Rock

Engineer's Report - Investigation of Dam site - Structure C-2, Panther Creek

Harold Townsend 12-13-67

CORE TRENCH: Recommended depths

Station	Elevations
1+00	920.0
2+40	902.0
3+10	878.0
5+00	876.5
6+50	876.5
7+30	883.5
8+00	882.0
9+00	885.0
9+50	895.0
12+00	900.0
14+00	907.0
15+60	917.0

3:1 slopes at both end of the core trench.

The recommended core trench depths will remove the weathered limestone or be in good CL material and should provide a positive core cutoff. Foundation drainage will not be needed to relief seepage through the foundation or embankment.

Rock excavation is not anticipated. Only material that is weathered and can be ripped will ~~be~~ need to be removed. This material will need to be wasted.

EMERGENCY SPILLWAY: Limestone was encountered in the inlet channel to the emergency spillway. Some of the overburden will be suitable for fill and should be classed as borrow. The weather limestone, shale and material with rock fragments too large for fill material should be classed as excavation common and wasted. This material should be wasted along the upstream toe of the dam in the deeper fill sections. Preliminary estimates indicate that there will be about 2500 cu yds of rock excavation. A zone fill is recommended so the rock excavation material utilized. This zone of rock fill should oh on the upstream face in the area of anticipated wave action.

STREAM CHANNEL CLEAN OUT: Excavation in the stream channel is recommended from the core trench to the upstream toe of the dam. The extent and depth will be indicated on the field design prints of the geology sheets.

BORROW: Adequate fill material will be available from the emergency spillway and the sediment pool areas. A wet construction period will limit depth of borrow in the sediment pool and lengthen the haul distance.

LOG OF TEST HOLES

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

WATERSHED: Panther Creek SUB-WATERSHED: C-2
 LOCATION: Harrison Co STATE: Mo
 LOGGED BY: M.F. Edmunds DATE: 11-16-67 WP-07: 5 WP-08: 5 FP-03: 5 P.L. 46:
 DRILLING EQUIPMENT: Fauling 1500 PROJECT: R. Fill
 LOCATION OF HOLES: R. Fill

HOLE NO.	STA. & SURFACE ELEVATION	HOLE DEPTH		DESCRIPTION OF MATERIALS	N	U S C S	TYPE BIT USED	SAMPLES		
		FROM FT.	TO FT.					1 TYPE	2 FROM FT. TO FT.	3 CSE. REM. REC. MIN. DIAM.
1	1775 913.4	0	1.5	Silt, slightly clayey, dark grayish brown, top soil		ML SA				
		1.5	8	Clay, silty, yellowish brown and gray, moist, stiff till		CL SA				
		8	20	Clay, silty, reddish brown and yellowish brown, moist, stiff till		CL SA				

W.L. 16' 11-27-67

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

LOG OF TEST HOLES

WATERSHED: Panther Creek SITE NO. C-2
 LOCATION: Harrison Co. STATE: Mo
 LOGGED BY: N.F. Edmunds DATE: 11-15-67 PROJECT: WP-07 WP NO. 5
 DRILLING EQUIPMENT: Fauling 1500 LOCATION OF HOLES & FILL: FP-03 P.L. 46

HOLE NO.	STA. & SURFACE ELEVATION	HOLE DEPTH FROM TO FT. FT.	DESCRIPTION OF MATERIALS	N	U S C S	BIT USED	SAMPLES		
							1 FROM FT.	2 TO FT.	3 CSE. REM. MIN. DIAM.
2	770	0 2	Silt. clayey, dark grayish brown topsoil		ML SA				
	993.0	2 10	Clay, silty, yellowish brown and gray slightly moist, stiff, subsoil		CL SA				
		10 17.6	Clay, silty, reddish brown, moist, stiff fill		CL SA				
		17.6 18	Limestone		SA				
		18 27.2	Limestone, gray, thinly bedded with interbedded gray shale, shale beds mostly 1/4 to 1/2 inch thick, one shale bed from 21 to 21.4. Pressure test was made from 18.5' to 27.2'. No water loss.		Red				

BCS-5317
 No. 2-64

LOG OF TEST HOLES

U. S. DEPARTMENT OF AGRICULTURE
 SOIL CONSERVATION SERVICE

WATERSHED Parther Creek SUB-WATERSHED C-2
 LOCATION Harrison County STATE Mo
 LOGGED BY M. E. Edmonds DATE 11-14-67
 DRILLING EQUIPMENT Failing 1500 PROJECT WP-07 EP-03 P.L. 48
 LOCATION OF HOLES 5 WP-08 5

HOLE NO	STA. & SURFACE ELEVATION FT.	HOLE DEPTH FROM TO FT.	DESCRIPTION OF MATERIALS	U S C S	N	TYPE BIT USED	SAMPLES			
							1 NO. TYPE	2 FROM TO FT.	3 CSE. REM. REC. (MIN. INCH)	
3	5100 888.6	0 7.8	Clay, very silty with some fine sand, dark grayish brown, moist, medium alluvium sand, silty, grayish brown, wet, medium fine & medium sand with 20% fines	CL	SA					
		7.8		SM	SA					
		8.3		CL	SA					
		9.5		SA						
		9.5		Ac						30
		9.9								100
		11.9								90
		16.8								90

1. DISTURBED-UNDISTURBED-ROCK CORE 2. COARSE MATERIAL REMOVED 3. PERCENT SAMPLE RECOVERY SHEET _____ OF _____ SHEETS

9CS-533T
1-1-64

LOG OF TEST HOLES
WATERSHED Panther Creek SUR-WATERSHED
LOCATION Harrison Co STATE Mo

LOGGED BY N F Edmonds DATE 11-9-67 PROJECT WP-07 WP-08 5 FP-03
DRILLING EQUIPMENT Failing 1500 LOCATION OF HOLES & Fill P.L. 48

HOLE NO.	STA. & SURFACE ELEVATION	HOLE DEPTH FROM TO FT. FT.	DESCRIPTION OF MATERIALS	U S C S	TYPE BIT USED	SAMPLES	
						1 FROM, TO FT. FT.	2 CSE. REAM REC. MIN DIAM. IN.
3 4	6725 885.5	0 2	silt, clayey, with some sand, dark grayish brown, moist, medium sand, silty, yellowish brown and grayish brown, estimated 15% fines with occasional gravel Limestone, refusal Caved at 2.5' 11-27-67	ML	SA		
		2 6.5		SA	SA		
		6.5					

208-5107
REV. 7-64

LOG OF TEST HOLES

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

WATERSHED Panther Creek LOCATION Harrison Co SUB-WATERSHED Mo STATE Mo

LOGGED BY N F Edmonds DATE 11-9-67 PROJECT: WP-07 WP-09 5 FP-03 FP-46

DRILLING EQUIPMENT Failing 1500 LOCATION OF HOLES 2 Fill

HOLE NO.	STA. & SURFACE ELEVATION	HOLE DEPTH FROM TO FT. FT.	DESCRIPTION OF MATERIALS	N	U S C S	TYPE BIT USED	SAMPLES		
							1 TYPE FT.	2 FROM TO FT.	3 CSE. REM. REC. INCH. %
5	6780	0 1	Clay, silty, reddish brown, moist		CL	SA			
	6870	1 4	medium, slope wash silt, clayey, dark grayish brown, moist, medium alluvium		ML	SA			
		4 5	Limestone, weathered, w/clay.			SA			
		5	Limestone, refusal						
	5a	6755 8870	0 3.5	silt, clayey, dark grayish brown, moist medium, alluvium		CL	SA		
		35 6.5	Gravel, clayey, yellowish brown		GC	SA			
		6.5	Refusal at 6.5' w.t. 5' 11-27-67						

LOG OF TEST HOLES

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

WATERSHED Panther Creek SITE NO. C-2
 LOCATION Harrison Co STATE MO
 LOGGED BY N F Edmonds DATE 11-8-67
 DRILLING EQUIPMENT Falling 1500 PROJECT: WP. 08 5 WP. 03 P.L. 46
 SUB-WATERSHED _____ OWNER _____
 LOCATION OF HOLES S Fill

HOLE NO.	STA. & SURFACE ELEVATION	HOLE DEPTH FROM TO FT. FT.	DESCRIPTION OF MATERIALS	U S C S	M	U S C S	TYPE RIT USED	SAMPLES		
								1 NO. TYPE	2 FROM TO FT. FT.	3 CSE. REM. REC. MIN DIAM.
# 6	7725 896.3	0-6	clay, silty, reddish brown, slightly moist, stiff	CL	SA					
		6-8	clay, sandy, reddish brown, moist, stiff estimated 30% fine sand	CL	SN					
		8-9	sand, clayey, reddish brown, moist, medium, fine sand with estimated 35% fines	SC	SN					
		9-9.5	clay, silty, reddish brown, moist, stiff	CL	SN					
		9.5-9.8	limestone, weathered	SN						
		9.8	limestone, refusal							
		0-9.2	overburden	SA						
		9.2-13.0	limestone, thinly bedded, light brown and weathered but has hardness of 4 to 5							
		13.0-13.9	limestone, gray, thinly to medium beds, hardness of 3, with interbedded gray shale shale beds range in thickness from 1/4 to 3/8" pressure test with NO WATER LOSS.							

LOG OF TEST HOLES

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

WATERSHED Panther Creek LOCATION Harrison Co SITE NO. C-2 STATE AL

LOGGED BY A. F. Edmonds DATE 11-8-67 PROJECT: WP-07 WP-08 5 FP-03 P.L. 46

DRILLING EQUIPMENT Failing 1500 SUB-WATERSHED OWNER ALC LOCATION OF HOLES Fill

HOLE NO.	STA. & SURFACE ELEVATION	HOLE DEPTH		DESCRIPTION OF MATERIALS	N	U S C S	BIT USED	SAMPLES	
		FROM FT.	TO FT.					1 TYPE	2 FROM TO CSE REM. MIN. DIAM. FT. N
7	8+00 896.5	0	1	Silt, slightly clayey, dark brown Top soil		ML SA			
		1	2	silt, slightly clayey, grayish brown, moist, medium		ML SA			
		2	9	clay, silty, yellowish brown and gray slightly moist, hard, becomes moist and stiff at 6 feet		CL SA			
		9	10	clay, gravelly, dark brown, moist stiff, coarse sand and fine gravel estimated 35%		CL SA			
		10	13	Gravel, clayey, reddish brown, moist to very moist		GC SA		1	D 10 11
		13	24	Refusal with auger at 13.2		Rb			
		24	26.5	Limestone with interbedded shale beds at 14.5 to 18.8; 16.6 to 16.9; 19.8 to 20.3 shale		Rb			

LOG OF TEST HOLES

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

WATERSHED
LOCATION
LOGGED BY
DRILLING EQUIPMENT

Watershed: Panther Creek
Location: Harrison Co.
Logged by: N.F. Edmonds
Drilling equipment: Falling 1500

Sub-watershed: [blank]
Owner: [blank]
Project: [blank]
Location of holes: & Fill

Date: 11-8-67
Project: [blank]
Location of holes: & Fill

HOLE NO.	STA. & SURFACE ELEVATION FT. FT.	HOLE DEPTH FROM TO FT. FT.	DESCRIPTION OF MATERIALS	N	U S C B	TYPE BIT USED	SAMPLES			
							1 NO.	2 TYPE	3 FROM TO FT. FT.	4 CSE. REM. % DIAM.
8	9100 8974	0 2	Silt, slightly clayey, brown and grayish brown moist topsoil		ML SA					
		2 9	Clay, silty, reddish brown, moist stiff		CL SA					
		9 104	Sand, clayey, reddish brown, moist medium, medium to coarse angular sand with occasional gravel, estimated 30 to 35% fines		SC SA					
		104 106	Limestone, weathered		SA					
		106	Limestone, refusal w.t. 9.5 11-27-67							

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE
LOG OF TEST HOLES

WATERSHED: Panther Creek SUB-WATERSHED: C-2
 LOCATION: Harrison Co STATE: MO
 LOGGED BY: M.F. Edmonds DATE: 11-8-67
 DRILLING EQUIPMENT: Feiling 1500 PROJECT: WP-07-5 P.L. # 16
 LOCATION OF HOLES: g Fill

HOLE NO.	STA. & SURFACE ELEVATION FT.	HOLE DEPTH FROM TO FT. FT.	DESCRIPTION OF MATERIALS	N	U S C S	TYPE RIT USED	SAMPLES				
							1 TYPE	2 FROM FT.	3 TO FT.	CSE. %	REM. %
9	11400 901.6	0 1	silt, slightly clayey, topsoil Clay, silty, yellowish brown and gray, moist, stiff		ML SA						
		7 10	Clay, silty, with some fine sand, reddish brown, moist, stiff		CL SA						
		10 144	Sand, clayey, reddish brown, moist medium, fine & medium sand with estimated 30% fines		SC SA						
		144 146	Limestone, weathered Limestone, refusal w.l. 11' 11-27-67		SA						

LOG OF TEST HOLES

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

WATERSHED Panther Creek

LOCATION Harrison Co

LOGGED BY NFEchmonds

DRILLING EQUIPMENT Failing 1500

SUB-WATERSHED _____

OWNER _____

PROJECT: WP-07 WP-08 5 5 5

DATE 11-7-67

LOCATION OF HOLES Fill

SITE NO. C-2

STATE MO

P.L. 48 _____

HOLE NO	STA & SURFACE ELEVATION FT.	HOLE DEPTH FROM TO FT.	DESCRIPTION OF MATERIALS	N	U S C S	TYPE RIT USED	SAMPLES		
							1 FROM FT.	2 TO FT.	3 CSE. REM. REC. MIN. DIAM. IN.
10	1275.0 904.8	0	1 silt, slightly clayey, dark grayish brown very moist, medium Top soil		ML	SA			
		1	6 clay, silty, grayish brown and yellowish brown, moist, medium		CL	SA			
		6	9 clay, dark grayish brown and gray, moist stiff		CL	SA			
		9	13 clay, silty, reddish brown, moist, medium, Till		CL	SA			
		13	18 Clay, silty, yellowish brown and gray, moist, medium, slightly sandy from 16 to 18', Till. w.L. 10.5 11-27-67		CL	SA			

LOG OF TEST HOLES

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

WATERSHED Panther Creek SUB-WATERSHED _____
 LOCATION Harrison Co. STATE MO
 LOGGED BY N. F. Edmonds DATE 11-16-67
 DRILLING EQUIPMENT Fauling 1500 PROJECT MP-07 PP-03
 LOCATION OF HOLES R 14700 P.L.-46

HOLE NO.	STA. & SURFACE ELEVATION	HOLE DEPTH FROM TO FT. FT.	DESCRIPTION OF MATERIALS	U S C S	BIT USED	SAMPLES		
						1 TYPE	2 FROM TO FT. FT.	3 REM. REC. MIN. DIAM. %
11	14700	0 1	Silt, clayey, brown, Top soil	ML	SA			
	911.0	1 3	Clay, silty, yellowish brown and gray, moist, stiff	CL	SA			
		3 10	Clay, silty, reddish brown, moist, stiff	CL	SA			
		10 16	Clay, silty, yellowish brown and gray moist, stiff, Till wt. 3' 11-27-67	CL	SA			

LOG OF TEST HOLES

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

WATERSHED Panther Creek LOCATION Mo
 SUB-WATERSHED _____ OWNER _____
 LOGGED BY N.E. Edmonds DATE 11-14-67 PROJECT: WP-07 WP-08 5 P.L.-46 _____
 DRILLING EQUIPMENT Failing 1500 LOCATION OF HOLES Fill FP-03 _____

HOLE NO.	STA. & SURFACE ELEVATION	HOLE DEPTH FROM TO FT. FT.	DESCRIPTION OF MATERIALS	U S C S	N	U S C S	BIT USED	NO. TYPE	SAMPLES			
									1 FROM TO FT. FT.	2 CSE. REM. %	3 MIN. DIAM. %	
12	3445 3440 881.0	0.16 1.63.4 3.46.6	Sand, w limestone cobbles, channel fill Limestone, with interbedded shale, predominately shale with poor recovery from 2.4 to 3.2. Upper limestone appears thinly bedded and unweathered Limestone, thinly to medium bedded with thin interbedded shale seams, sound limestone, hardness 5				SA red					50 100

LOG OF TEST HOLES

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

WATERSHED: Panther Creek SITE NO.: C-2
 LOCATION: Harrison Co STATE: MO
 LOGGED BY: M. F. Edmonds DATE: 11-17-67
 DRILLING EQUIPMENT: Failing 1500 PROJECT: WP-07 P.L.: 46
WP-08 LOCATION OF HOLES: Q Fill 8+85 Grid A+75

HOLE NO.	STA. & SURFACE ELEVATION FT. FT.	HOLE DEPTH FROM TO FT. FT.	DESCRIPTION OF MATERIALS	N	SAMPLES					
					U S C S	TYPE BIT USED	NO. NO.	1 FROM TO TYPE FT. FT.	2 CSE. REM. FT. INCH	3 REC. INCH
101 9045	0 2	2 7.5	Clay, silty, reddish brown, moist stiff, Till		CLSA	1	0 8.5			
		7.5 7.5 8.5	clay, silty, yellowish brown and gray moist, stiff Till		CLSA	1	0 8.5			
			sand, clayey, gray Refusal at 8.5		SCSA					

LOG OF TEST HOLES

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

WATERSHED: Parthier Creek SITE NO.: C-2
 LOCATION: HARRISON CO STATE: MO
 LOGGED BY: N F Edmonds DATE: 11-16-67
 DRILLING EQUIPMENT: Failing 1500 PROJECT: WP-07 WP-08: 5 FP-03: P.L. 46
 LOCATION OF HOLES: § 1400 Grid C100

HOLE NO.	STA. & SURFACE ELEVATION FT. FT.	HOLE DEPTH FROM TO FT. FT.	DESCRIPTION OF MATERIALS	N	U S C S	TYPE BIT USED	SAMPLES			
							1 NO.	FROM TYPE FT.	TO FT.	2 CSE. REM MIN. DIAM
103	9045	0 1	Clay, silty, dark grayish brown Top soil			CL 5A				
		1 4	Clay, silty, reddish brown, moist stiff Till			CL 5A				

LOG OF TEST HOLES

WATERSHED: Panther Creek LOCATION: Harrison Co STATE: MO
 LOGGED BY: N. F. Edwards DATE: 11-27-67 PROJECT: WP-07 P.L. 46
 DRILLING EQUIPMENT: Falling 1500 LOCATION OF HOLES: 6-100 Grid C100

HOLE NO.	STA. & SURFACE ELEVATION	HOLE DEPTH FROM TO FT. FT.	DESCRIPTION OF MATERIALS	N	U S C S	TYPE BIT USED	SAMPLES			
							1 TYPE	2 FROM TO FT. FT.	3 CSE. REM. MIN. DIAM.	
102	893.6	0 5	silt, slightly clayey, dark brown alluvium becomes very moist at 5			MLSA	1	0	0	4
		5 6	silt, slightly sandy, very moist			MLSA				

LOG OF TEST HOLES

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

WATERSHED Panther Creek SUB-WATERSHED Mo STATE Mo

LOCATION Harrison Co OWNER Mo

LOGGED BY A. F. Edmonds DATE 11-27-67 PROJECT: WP-07 WP-08 5 PP-03 P.L.-46

DRILLING EQUIPMENT Failing 1500 LOCATION OF HOLES Q 12100 Grid B100

HOLE NO.	STA. & SURFACE ELEVATION	HOLE DEPTH FROM TO FT. FT.	DESCRIPTION OF MATERIALS	U S C S	N	M L S A	BIT USED	SAMPLES			
								1 FROM TO FT. FT.	2 CORE. REM. IN IN DIAM.	3 REM. RFC.	
111	895.9	0 2	silt, clayey, with some sand, dark grayish brown alluvium	ML		SA					
104	896.3	2 8	silt, clayey, dark grayish brown and brown, alluvium. W.L. 7.5' E.O.D	ML		SA		1	0	0	6
		0 5	Q 14100 Grid C150 clay, silty, with some sand dark grayish brown alluvium	ML		SA		1	0	0	5
		5 8	clay, silty, dark grayish brown, alluvium, becomes too and for borrow at 6'								

LOG OF TEST HOLES

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

WATERSHED: Panther Creek SUB-WATERSHED: _____
 LOCATION: Harrison Co. OWNER: _____
 LOGGED BY: N. F. Edmonds DATE: 11-16-67 PROJECT: _____
 DRILLING EQUIPMENT: Failing 1500 LOCATION OF HOLES & Fill: 1x00 Grid DT50

HOLE NO.	STA. & SURFACE ELEVATION FT.	HOLE DEPTH FROM TO FT. FT.	DESCRIPTION OF MATERIALS	N	U S C S	TYPE BIT USED	NO.	I TYPE	SAMPLES		3 REC.
									FROM FT.	TO FT.	
105	897.0	0 2	silt clayey, dark grayish brown and grayish brown top soil			MLSA	1	D	0	Z	
		2 8	Clay, silty, reddish brown, moist medium			CLSA	2	D	Z	8	
		8 10	Sand, clayey, brown, very moist, estimated 30% fines			SC					
109	894.9		Fill 3x00 Grid DT50								
		0 6	silt, clayey, w/some sand, dark grayish brown, moist alluvium			MLSA	1	D	0	6	
		6 8	Sand, clayey, reddish brown, very moist, estimated 30% fines			SCSA					

LOG OF TEST HOLES

WATERSHED Peaither Creek SUB-WATERSHED _____ SITE NO. C-2
 LOCATION Harrison Co OWNER _____ STATE _____

LOGGED BY N F Edmonds DATE 11-27-67 PROJECT: WP 07 _____ WP 08 5 TP 03 _____ P.L. 48 _____
 DRILLING EQUIPMENT Failing 1500 LOCATION OF HOLES Q 12+00 Grid E 100

HOLE NO	STA. & SURFACE ELEVATION	HOLE DEPTH FROM TO FT. FT.	DESCRIPTION OF MATERIALS	N	U S C S	TYPE BIT USED	SAMPLES			
							1 NO.	1 FROM TO FT. FT.	2 CSE. REA. MAIN N. JOINT. N.	3 REA. REFC. N.
109	900.7	0 3.5	silt, clayey, dark brown slopewash			ML SA	1	0 3.5		
		3.5 8	clay, silty, yellowish brown and grey moist, stiff			CL SA	2	0 3.5 8		
		8 12	clay, grayish brown, moist to very moist, soft. w.L. 11' F.O.D.			CL SA				
106	895.8	0 2	Fill 10x00 Grid D+00			ML SA	1	0 4		
		2 4	silt, slightly clayey, dark yellowish brown, alluvium			ML SA				
		4 8	silt, slightly clayey, dark grayish brown alluvium			ML SA				
		8 12	silt, sandy, reddish brown, moist To very moist at 6'			ML SA				

LOG OF TEST HOLES

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

WATERSHED Panther Creek SUB-WATERSHED _____ SITE NO. C-2
 LOCATION Harrison Co OWNER _____ STATE MO

LOGGED BY N. F. Edmonds DATE 11-16-67 PROJECT: WP-07 WP-08 5 EP-03 _____ P.L. 46 _____
 DRILLING EQUIPMENT Falling 1500 LOCATION OF HOLES Fill 3x00 Grid C750

HOLE NO	STA & SURFACE ELEVATION	HOLE DEPTH FROM TO FT. FT.	DESCRIPTION OF MATERIALS	U TYPE			SAMPLES				
				N	C	S	1 TYPE	2 FROM TO FT. FT.	3 CSE. REA. REC. INCH. DIAM.		
108	898.3	0 1	Silt, slightly clayey, dark grayish brown topsoil.				ML SA				
		1 2	Silt, slightly clayey, grayish brown moist, medium alluvium				ML SA				
		2 10	Clay, silty, reddish brown, moist medium,				CL SA	1	D	2	10
		10 12	Sand, clayey, brown, very moist, medium, estimated 35% fines No wt. 11-27-67				SC SA				

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

WATERSHED Panther Creek

LOCATION Harrison Co

LOGGED BY MF Edmonds

DRILLING EQUIPMENT Failing 1500

LOG OF TEST HOLES

SUB-WATERSHED

OWNER

PROJECT: WP-07 WP-08 5 FP-03 P.L. 48

LOCATION OF HOLES Fill 1450 C 100

SCS 9337
REV. 9-64

SITE NO. C-2

STATE Mo

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

DATE 11-16-67

HOLE NO.	STA & SURFACE ELEVATION	HOLE DEPTH FROM TO FT. FT.	DESCRIPTION OF MATERIALS	N	U S C S	TYPE BIT USED	SAMPLES		
							1 TYPE	2 FROM TO FT. FT.	3 CSE REC. MIN. DIAM. IN.
110	901.0	0 1.5	silt, clayey, dark grayish brown Top soil		MLSA				
		1.5 8	Clay, silty, reddish brown, moist medium, Terrace alluvium		CL SA				
		8 10	sand, clayey, brown, very moist medium to w.L. 11-27-67		SCSA				

LOG OF TEST HOLES

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

WATERSHED Panther Creek SUB-WATERSHED _____
LOCATION Harrison Co OWNER _____
LOGGED BY N. F. Edmunds DATE 11-20-67

DRILLING EQUIPMENT Triling 1500 PROJECT: _____
WP-01 _____ WP-02 5 WP-03 _____ P.L.-46 _____
LOCATION OF HOLES & Energy Sply

HOLE NO.	STA & SURFACE ELEVATION	HOLE DEPTH FROM TO FT. FT.	DESCRIPTION OF MATERIALS	N	U S C S	TYPE BIT USED	SAMPLES		
							1 NO.	2 FROM TO FT. FT.	3 ESE. REM. REC. MIN. DIAM. %
201	3100 930.5	0 4.8	Clay, silty, yellowish brown and gray, Till, Refusal at 4.8			CL 50			
		4.8 6.2	Limestone, weathered, broken			Red			50
		6.2 8.2	Limestone, gray, hard, thickly bedded						100
		8.2 9.6	Shale yellowish brown, one limestone bed from 8.8 to 8.9.						
		9.6 11.4	Limestone, thin to medium beds with interbedded yellowish brown shale						
		11.4 20	Limestone, gray and dark gray, hard medium bedded. Thin shale bed from 13.9 to 14.0						

LOG OF TEST HOLES

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

WATERSHED: Panther Creek SUB-WATERSHED: _____
LOCATION: Harrison Co STATE: MD

LOGGED BY: N. F. Edmonds DATE: 11-22-67 PROJECT: WP-07 WP-08 S PP-03 _____ P.L. 46 _____
DRILLING EQUIPMENT: Failing 1500 LOCATION OF HOLES: Emerg. Spiky

HOLE NO.	STA. & SURFACE ELEVATION FT. FT.	HOLE DEPTH FROM TO FT. FT.	DESCRIPTION OF MATERIALS	N	U	S	C	S	TYPE BIT USED	SAMPLES											
										1 FROM TO FT. FT.	2 CSE. REM. MIN. DIAM. %	3 REC. %									
202	4100 937.7	0 6	Clay, silty, yellowish brown and gray moist stiff till Refusal at 6'						CL SA												
		6 8.5	Limestone, gray & buff, weathered, 2 beds 2' and 5'. Thick, one thin yellowish brown shale bed at 8'						RCD												90
		8.5 11.5	shale, yellowish brown, with thin interbedded limestone less than 1" thick																		70
		11.5 16	Limestone, gray, thin and medium bedded with interbedded dark gray shale and shaly limestone																		100

1. DISTURBED-UNDISTURBED-ROCK CORE 2. COARSE MATERIAL REMOVED 3. PERCENT SAMPLE RECOVERY SHEET 1 OF 1 SHEETS

LOG OF TEST HOLES
SUB-WATERSHED
OWNER
PROJECT
LOCATION OF HOLES

LOGGED BY *Panther Creek*
WATERSHED *Harrison Co*
DATE *11-22-67*
PROJECT: *WP OF 5*
SUB-WATERSHED *Mo*
OWNER *Mo*
PROJECT *100' right*
LOCATION OF HOLES *Q. Emerg Sply*

LOGGING EQUIPMENT *Failing 1500*
DATE *11-22-67*
PROJECT: *WP OF 5*
SUB-WATERSHED *Mo*
OWNER *Mo*
PROJECT *100' right*
LOCATION OF HOLES *Q. Emerg Sply*

HOLE NO.	STA. & SURFACE ELEVATION FT.	HOLE DEPTH FROM TO FT. FT.	DESCRIPTION OF MATERIALS	N	U S C S	TYPE BIT USED	NO.	SAMPLES			
								1 FROM FT.	2 TO FT.	3 CSE. REAM. REC.	
203	4400 944.5	0 .5 .5 10.3	<i>Silt, clayey, brown topsoil clay, silty yellowish brown and gray moist, stiff, till</i>		<i>ML SA</i>		<i>1</i>	<i>0</i>	<i>5</i>	<i>10</i>	100
		10.3 118	<i>Limestone, light gray & buff, thinly bedded with interbedded yellowish brown shale, weathered</i>			<i>Red</i>					100
		11.8 163	<i>Limestone, light gray, medium bedded with thin shale partings</i>								100
		16.3 182	<i>Shale, yellowish brown with interbedded limestone beds about 1" thick</i>								100
		18.2 204	<i>Limestone, gray, with interbedded dark gray shale and shaly limestone</i>								100

LOG OF TEST HOLES

WATERSHED: Ranther Creek SUB-WATERSHED: C-2
 LOCATION: Harrison Co STATE: Mo
 LOGGED BY: N. F. Edmonds DATE: 11-21-67
 DRILLING EQUIPMENT: Feeling 1500 PROJECT: WP-07 WP-08 5 P.L.-46
 LOCATION OF HOLES: Emera Spwy

HOLE NO.	STA. & SURFACE ELEVATION	HOLE DEPTH FROM TO FT. FT.	DESCRIPTION OF MATERIALS	N	U S C S	BIT USED	NO. TYPE	SAMPLES				
								1 FROM FT.	2 TO FT.	CSE. REM. MIN. DIAM. %		
204	5100 932.0	0 25	Clay, silty, yellowish brown and gray Till Refusal at 25'									
		25	Limestone, weathered, broken w/clay				Rb					
		5.7	Shale, yellowish brown, with interbedded thin limestone beds.				Red					
		7.3	Limestone, gray, thin and medium bedded with interbedded gray shale and shaly limestone.									

LOG OF TEST HOLES

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

WATERSHED: Parther Creek SITE NO.: C-2
 LOCATION: Harrison Co STATE: Mo
 LOGGED BY: N. F. Edwards DATE: 11-21-67
 DRILLING EQUIPMENT: FALLING 1500 PROJECT: WP-07 P.L.-46
 LOCATION OF HOLES: Emerg Sp/way FP-03

HOLE NO.	STA. & SURFACE ELEVATION FT. FT.	HOLE DEPTH FROM TO FT. FT.	DESCRIPTION OF MATERIALS	U S C S	N	TYPE BIT USED	SAMPLES		
							1 NO. TYPE	2 FROM TO CSE. REH. FT. FT.	3 REC. ORIGINAL DIAM.
207	2100 9185	0 8.5	Clay, silty, yellowish brown and gray moist, stiff, Till			CL5A			
		8.5 96	Limestone, weathered with clay			9A			
		96 136	Limestone, gray, thinly bedded with interbedded yellowish brown shale			Red			50

LOG OF TEST HOLES

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

WATERSHED: Panther Creek SUB-WATERSHED: _____ SITE NO.: C-2
 LOCATION: Harrison Co OWNER: _____ STATE: Mo
 LOGGED BY: N. F. Edwards DATE: 11-22-67 PROJECT: _____
 DRILLING EQUIPMENT: Failing 1500 LOCATION OF HOLES: Emery Salway WP-07: _____ WP-08: 5 FP-03: _____ PL-46: _____

HOLE NO.	STA. & SURFACE ELEVATION	HOLE DEPTH FROM TO FT. FT.	DESCRIPTION OF MATERIALS	U S C S	N	TYPE BIT USED	SAMPLES		
							1 TYPE	2 FROM TO CSE. REM. FT. FT. %	3 MIN. DIAM.
208	2150 924.5	0 3.3	Clay, silty, yellowish brown and gray, moist, stiff Refusal at 3.3	CL	SA				
209	2125 921.5	0 4.3	Clay, silty, yellowish brown and gray, moist, stiff Refusal at 4.3.	CL	SA				

LOG OF TEST HOLES

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

WATERSHED Parthen Creek SUB-WATERSHED _____ STATE C-2

LOCATION Harrison Co OWNER _____

LOGGED BY N.F. Edmonds DATE 11-22-67 PROJECT: _____

DRILLING EQUIPMENT Failury 1500 LOCATION OF HOLES Emergy Spwy P.L. 46 _____

HOLE NO.	STA. & SURFACE ELEVATION	HOLE DEPTH FROM TO FT. FT.	DESCRIPTION OF MATERIALS	N	U S C S	TYPE BIT USED	NO. USED	SAMPLES		
								1 FROM FT.	2 TO FT.	3 CSE REM. REC. MIN. INCHES
210	9207.5	0	clay, silty, yellowish brown and gray moist, stiff Limestone weathered, broken, with clay weathered pebbles, yellowish brown. Refusal at 3.5		CL SA	SA				
	512.5	1								
	929.5	3.5								
211	5150	0	Clay, silty, yellowish brown and gray moist stiff Refusal at 2.6		CL SA	SA				
	926.5	2.6								

LOG OF TEST HOLES

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

WATERSHED Peaither Creek SITE NO. C-2
 LOCATION Harrison Co STATE Mo
 LOGGED BY M. F. Edmonds DATE 11-27-67
 DRILLING EQUIPMENT Failing 1500 PROJECT: WP-07 WP-08 5 FP-03 5 P.L. 46

HOLE NO.	STA. & SURFACE ELEVATION FT.	HOLE DEPTH FROM TO FT.	DESCRIPTION OF MATERIALS	U S C	N S	U S C	SAMPLES			
							1 NO. TYPE	2 FROM FT.	3 TO FT.	CRE. REC. N
215	921.5 6100	0 3.2	clay, silty, yellowish brown, moist, stiff Refusal at 3.2	CL	SA					
212	4100 100' Lt. 924.7	0 4.8	clay, silty, yellowish brown, moist, stiff Refusal at 4.8	CL	SA					
213	4100 50' Lt. 931.0	0 4	clay, silty, yellowish brown, moist, stiff Refusal at 4.0.	CL	SA					

LOG OF TEST HOLES

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

WATERSHED Panther Creek SUB-WATERSHED _____ STATE Mo
LOCATION Harrison Co OWNER _____

LOGGED BY N.F. Edwards DATE 11-22-67 PROJECT WP-07 WP-08 5 PP-03 _____ P.L.-46 _____
DRILLING EQUIPMENT Excelling 1500 LOCATION OF HOLES Emerys plwy 150' right

HOLE NO.	STA. & SURFACE ELEVATION FT.	HOLE DEPTH FROM TO FT. FT.	DESCRIPTION OF MATERIALS	N	U S C S	TYPE BIT USED	SAMPLES		
							1 FROM TO FT. FT.	2 CSE. REM MIN DIAM	3 REF. N
214	4100 946.8	0 .5	silt, slightly clayey, dark brown topsoil MS clay, silty, yellowish brown and gray, moist, stiff, fill		ML CL	SA SA			

LOG OF TEST HOLES

WATERSHED: Parthen Creek SUB-WATERSHED: _____
 LOCATION: Harrison Co OWNER: _____
 LOGGED BY: A.F. Edwards DATE: 12-6-67 PROJECT: WP 07 WP 08: 5 FP 03: _____ P.L. 46: _____
 DRILLING EQUIPMENT: Failing 1500 LOCATION OF HOLES: Emergency Spillway

HOLE NO.	STA. & SURFACE ELEVATION	HOLE DEPTH FROM TO FT. FT.	DESCRIPTION OF MATERIALS	U S C S	N	BIT USED	SAMPLES		3 REC.
							1 TYPE	2 FROM TO USE. REM. FT. FT. N	
221	3100 922.3	0 5	100 feet Left Clay, overburden Refusal at 5'	CL		SA			
220	3100 926.4	0 14	50 feet Left Clay, overburden Refusal at 14'	CL		SA			
219	3100 932.0	0 27 2.713.4	50 feet Right Clay, overburden Clay and broken rock Refusal at 3.4'	CL		SA			
218	3100 933.4	0 18 4.8'5	100 feet Right Clay, overburden Clay & broken rock Refusal at 5'	CL		SA			

AD-A106 461

BLACK AND VEATCH KANSAS CITY MO
NATIONAL DAM SAFETY PROGRAM, HARRISON COUNTY DAM C-2 (MO 10614)--ETC(U)
MAR 81 E R BURTON, H L CALLAHAN

F/G 13/13

DACW43-81-C-0037
NL

UNCLASSIFIED

2 of 2

2000



END
DATE
FILED
11 8
DTIC

LOG OF TEST HOLES

WATERSHED Parther Creek SUB-WATERSHED _____ STATE C-2

LOCATION Harrison Co OWNER _____

LOGGED BY N.F. Edmonds DATE 12-5-67 PROJECT WP-07 WP-08 5 FP-03 _____ PL-46 _____

DRILLING EQUIPMENT Failing 1500 LOCATION OF HOLES Emergency Spillway

HOLE NO.	STA. & SURFACE ELEVATION	HOLE DEPTH FROM TO FT. FT.	DESCRIPTION OF MATERIALS	U TYPE			SAMPLES		
				N	S	C	1 FROM TO FT. FT.	2 CSE. REM. MIN DIAM	3 REC.
217	919.8 918.8 2100	0 4.3 4.3 5.2	64 feet Right Clay, overburden Clay & broken rock Refusal at 5.2	CL	SA				
216	923.0 2100	0 3.4	96 feet Right Clay, overburden Refusal at 3.4	CL	SA				

LOG OF TEST HOLES

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE
WATERSHED Panther Creek

LOGGED BY Harrison Co

DRILLING EQUIPMENT Failing 1500

LOCATION Harrison Co

DATE 12-6-67

STATE Mo

SITE NO. C-2

PROJECT: WP 07 WP 08 5 FP 03

OWNER N. F. Edwards

LOCATION OF HOLES Emergency Spillway

P.L. 46

HOLE NO.	STA. & SURFACE ELEVATION	HOLE DEPTH FROM SURFACE TO FT.	DESCRIPTION OF MATERIALS	U T S			N C S			I FROM TO TYPE FT. FT.	CSE. REM. %	MIN. DIAM. %	REC. %
				U	T	S	N	C	S				
226	5100 924.4	0 2.4 4.3 4.3 5.7	100 feet left clay, overburden clay and broken rock wca. limestone Refusal at 5.7										
225	5100 929.4	0 4.6 4.6 5	50 feet left clay, overburden wca. limestone										
224	5100 921.0	0 0.7	50 feet Right overburden Refusal at .7										
223	5100 920.5	0 5 6.6	100 feet Right clay, overburden clay & broken rock Refusal at 6.6										

1. DISTURBED-UNDISTURBED-ROCK CORE 2. COARSE MATERIAL REMOVED 3. PERCENT SAMPLE RECOVERY

SHEET ____ OF ____ SHEETS

LOG OF TEST HOLES

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

WATERSHED Panther Creek SUB-WATERSHED _____ SITE NO. C-2
LOCATION Harrison Co OWNER _____ STATE Mo

LOGGED BY M.F. Edmonds DATE 11-9-67 PROJECT _____ WP-07 _____ WP-08 5 FP-03 _____ P.L.-46 _____

DRILLING EQUIPMENT Failing 1500 LOCATION OF HOLES & Prix. Spillway

HOLE NO.	STA. & SURFACE ELEVATION FT. & FT.	HOLE DEPTH FROM TO FT. & FT.	DESCRIPTION OF MATERIALS	N	U S C S	TYPE BIT USED	SAMPLES						
							NO.	TYPE	1 FROM, TO FT.	2 CSE. REM. MIN. DIAM. IN.	3 RFC. IN.		
301	1750 8890	0 2	silty, clayey, with some fine sand, dark grayish brown, moist, medium, alluvium		ML	SA	1	U	3	5.2			
		2	clay, very silty, dark grayish brown moist, medium		CL	SA							
		4	clay, very silty, with some fine & medium sand, moist, medium, brown		CL	SA							
		6	Sand, silty, yellowish brown and grayish brown, saturated, soft, fine & medium sand with estimated 15% fines, occasional limestone gravel in lower part limestone, refusal		SM	SA	2	U	6.5	5.2			
		98	Hole caved 6.5' 11-27-67										

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

LOG OF TEST HOLES

WATERSHED Panther Creek SUB-WATERSHED C-2
 LOCATION Harrison Co STATE Mo
 LOGGED BY N.F. Edmonds DATE 11-9-67 PROJECT WP-07 WP-08 5 P.L. # FP-03
 DRILLING EQUIPMENT Failing 1500 LOCATION OF HOLES R. Fill

HOLE NO.	STA & SURFACE ELEVATION	HOLE DEPTH FROM TO FT. FT.	DESCRIPTION OF MATERIALS	N	U S C S	TYPE BIT USED	SAMPLES		
							1 FROM TO TYPE FT. FT.	2 CSE. REFC. MIN. INCHES	3 RFC. INCHES
302	4100 889.3	0 3	silt silt, sandy, dark grayish brown moist, medium, alluvium		ML	SA			
		3 6	sand, silty, reddish brown, moist medium, fine & medium sand with estimated 15% fines		SA	SA			
		6 8	Clay, very silty, with some sand, dark grayish brown, moist, medium alluvium		CL	SA			
		8 9	Sand, silty, dark grayish brown, saturated, soft		SA	SA			
		9 10.2	Clay silty, yellowish brown, moist medium		CL	SA			
		10.2/10.4	Limestone, refusal wt. 7.5' 11-27-67		SA				

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

WATERSHED Panther Creek SUB-WATERSHED _____

LOCATION Harrison Co STATE Mo

LOGGED BY N.F. Edmonds DATE 11-9-67

DRILLING EQUIPMENT Failing 1500 PROJECT: Principal Spillway

WP. 01 _____ WP. 02 _____ WP. 03 _____ P.L. 45 _____

HOLE NO.	STA & SURFACE ELEVATION FT.	HOLE DEPTH FROM TO FT.	DESCRIPTION OF MATERIALS	SAMPLES			1 FROM TO FT.	2 CSE. REM. MIN. DIAM.	3 REM. REC. %
				U TYPE	S BIT USED	N C S			
303	2+50 889.6	0 3	silt, slightly clayey with fine sand dark grayish brown moist alluvium	MA SA					
		3 6	clay, silty, with fine sand, brown moist, medium	CL SA					
		6 9	clay, silty, dark grayish brown, moist medium alluvium	CL SA					
		9 10	sand, clayey, yellowish brown, saturated soft, fine & medium sand with occasional gravel, estimated 25% fines	SC SA					
		10 11.3	clay, gravelly, yellowish brown, moist, stiff	CL SA					
		11.3	limestone, refusal cut off - 11-27-67						

LOG OF TEST HOLES

WATERSHED Panther Creek SUB-WATERSHED _____ SITE NO. C-2
 LOCATION Harriison Co. OWNER _____ STATE Mo
 LOGGED BY N. F. Edmonds DATE 11-15-67 PROJECT: _____
 DRILLING EQUIPMENT Fairling 1500 LOCATION OF HOLES Prin. Spillway

HOLE NO.	STA. & SURFACE ELEVATION	HOLE DEPTH FROM TO FT. FT.	DESCRIPTION OF MATERIALS	U S C S	N	USED	BIT	TYPE	NO.	SAMPLES		
										1	2	3
										FROM TO FT. FT.	CSE. %	RECOVERED MIN. DIAM.
304	3135 881.0	0 2.5	Sand with limestone cobbles in lower part Refusal at 2.5 feet	S				SA				
		2.5 3.8	Limestone, weathered, broken	R				Rb				
		3.8 4.4	Limestone, sound rock	R				Rb				
		4.4 10.7	Limestone, thinly bedded with interbedded gray shale. Shale bed less than 1/2" thick	R				Red				
		10.7 11.7	Shale, gray									
		11.7 12.5	Shale, black, hardness 4									

LOG OF TEST HOLES

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

WATERSHED: Panther Creek STATE: MO
 LOCATION: Harrison Co
 LOGGED BY: M.F. Edwards DATE: 11-9-67 PROJECT: WP-07 WP-08: 5 FP-09: 50' Right
 DRILLING EQUIPMENT: Failing 1500 LOCATION OF HOLES: R Fill 6725 P.L.-46

HOLE NO.	STA. & SURFACE ELEVATION	HOLE DEPTH		DESCRIPTION OF MATERIALS	N	U S C S	U S C S	NO. USED	SAMPLES			
		FROM, FT.	TO, FT.						1 FROM, FT.	2 TO, FT.	3 CSE. REM. MIN. DIAM. %	
602	6725	0	3	silt, clayey, dark grayish brown alluvium								
	8855	3	5	silt, sandy, brown								
		5	6.5	sand, silty, yellowish brown, occasional gravel								
601			6.5	limestone, refusal Hole caved 4' 11-27-67								
	6735			R Fill 35' left.								
	8855	0	2	silt, sandy, brown alluvium								
		2	6	Gravel, silty, brown, estimated 15% fines								
		6	6.3	limestone, weathered w/ clay								
		6	6.3	limestone, refusal. Hole caved 3' 11-27-67								

SCS-384
7-60

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

Part III - Flow Test Data

Hole No. 6 Name of Site C-2 Fort Per Creek

Depth Tested: From 9.5 To 14.5; Formation Windsor Limestone P 5 psi

Graph Plot No.	Pressure Gage psi	Total Pressure (Gage+P)	Start Time	Stop Time	Elapsed Time (Mins)	Water Meter Readings			
						Start Test	End of Test	Total Gals. Water Used	GPM
1	5	15	1619	1620	2	4.32	4.32	0	
2	5	20	1622	1624		4.32	4.35	.03	
3									
4									
5									
6									
7									

Remarks:

Depth Tested: From 14.5 To 20; Formation Windsor Limestone P 7 psi

1	6	13	1600	1610	2	4.25	4.25	0	
2	6	23	1615	1617	2	4.25	4.25	0	
3									
4									
5									
6									
7									

Remarks:

Hole # 2

Depth Tested: From 15.5 To 22; Formation Windsor Limestone P 10 psi

1	5	15	1522	1522	2	9.03	9.03	0	
2	10	20	1527	1527	2	9.03	9.03	0	

Remarks: water loss was observed in packet

SCS-384
7-6C

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

Part III - Flow Test Data

Hole No. 3 Name of Site C-2 Panther Creek

Depth Tested: From 2.5 To 2.0; Formation Unconsolidated P 6 psi

Graph Plot No.	Pressure Gage psi	Total Pressure (Gage+P)	Start Time	Stop Time	Elapsed Time (Mins)	Water Meter Readings			
						Start Test	End of Test	Total Gals. Water Used	GPM
1	5	11	12:00	12:02	2	4.5	5.5	0	
2	10	16							
3									
4									
5									
6									
7									

Remarks:

Depth Tested: From 2.5 To 2.0; Formation Unconsolidated P 7 psi

1									
2									
3									
4									
5									
6									
7									

Remarks:

Depth Tested: From To ; Formation P psi

Remarks:

UNITED STATES GOVERNMENT

Memorandum

TO : James M. Dale, State Conservation Engineer,
SCS, Columbia, Missouri 65201

DATE: April 30, 1968

FROM : Lorn P. Dunnigan, Head, Soil Mechanics Laboratory,
SCS, Lincoln, Nebraska 68508

SUBJECT: ENG 22-5, Missouri WP-08, Panther Creek, Site No. C-2 (Harrison County)

ATTACHMENTS

1. Form SCS-354, Soil Mechanics Laboratory Data, 3 sheets.
2. Form SCS-127, Soil Permeability, 1 sheet.
3. Form SCS-128 and SCS-128A, Consolidation Test Data, 3 sheets (1 test).
4. Form SCS-355A, Triaxial Shear Test Data, 3 sheets.
5. Form SCS-352, Compaction and Penetration Resistance, 6 sheets.
6. Form SCS-357, Summary - Slope Stability Analysis, 3 sheets.

DISCUSSION

FOUNDATION

- A. Bedrock: The bedrock consists of thin to medium bedded limestone with interbedded gray shale which has been weathered to a depth of 3 to 7 feet. The bedrock appears to be relatively uniform at elevation 887± except in the channel alluvium area where it occurs at elevation 879±. There is a hump in the bedrock at Station 6+60. The limestone bedrock is overlain, in the emergency spillway, by 2.0 to 10.0 feet of CL till.
- B. Soil Classification: Both abutments are classified CL till. The thin layer of SC material to the right of Station 9+00 is considered to be of low permeability by the geologist.
- C. Density: Undisturbed samples were taken from Test Hole 301. The sample taken from 3.0 to 5.2-foot depth has a dry density of 1.40 g/cc in the top portion and 1.76 g/cc in the lower portion. An undisturbed sample was submitted from Test Hole 301 at a depth of 6.5 to 8.7 feet. The dry density of this sample is in the range of 1.55 g/cc.

No blow counts were submitted.
- D. Consolidation: A consolidation test was made on sample No. 68W1961 "T". Based on the results of this test, and load of the embankment, the settlement in alluvium represented is estimated to approach one foot.



Buy U.S. Savings Bonds Regularly on the Payroll Savings Plan

2 -- James M. Dale -- 4/30/68

Lorn P. Dunnigan

Subj: ENG 22-5, Missouri WP-08, Panther Creek, Site No. C-2

- E. Permeability: A falling head permeability test was made on Sample 68W1961 "T". The results of this test show a permeability rate of 0.1 ft/day. Data on pressure tests in the bedrock are reported in the geology report.
- F. Shear Strength: A consolidated undrained shear test was made on Sample 68W1961 "T" from TH 301. The test specimens were trimmed from the undisturbed sample and soaked prior to testing. The data obtained from the test represent two strata. An average strength value of $\phi = 14.5^\circ$, $c = 400$ psf was used for design purposes.

EMBANKMENT MATERIALS

- A. Classification: The borrow samples submitted are CL and CL-ML materials. The CL materials have liquid limits ranging from 20 to 40 and PI's ranging from 9 to 20. The CL-ML materials have liquid limits of 28 and 23 and PI's of 7. The material from the emergency spillway is CH material with liquid limit of 51 and PI of 30.
- B. Compacted Density: The compacted dry density of borrow samples was 112.0 pcf for the sandier CL (68W1965), 106.0 pcf for the finer grained CL (68W1971) and 105.0 pcf (68W1972), 111.0 pcf for the Mix of samples (68W1966, 1967, 1970, 1974, 1975), and 101.0 pcf for the CH material from the emergency spillway (68W1964).
- C. Shear Strength: Consolidated undrained shear tests were made on Samples 68W1972 and Mix of 68W1966, 1967, 1970, 1974, 1975. The shear strength parameters obtained for Sample 68W1972 are $\phi = 10.5^\circ$, $c = 850$ psf. The shear strength parameters of the Mix are $\phi = 13.5^\circ$, $c = 1100$ psf. These values are for saturated material at a minimum of 95% of standard Proctor density.

SLOPE STABILITY

- A. Maximum Section at Station 6+25: A slope stability analysis was made on the 2 1/2:1 upstream embankment slope using a modified Swedish circle method. Rapid drawdown from the emergency spillway to the base of the embankment is considered. The embankment will rest on bedrock after normal channel cleanout; therefore, the foundation is considered competent. Strength parameters used for the embankment are $\phi = 10.5^\circ$, $c = 850$ psf. No berms were considered in this analysis and the computed factor of safety is 1.58.

The downstream 2 1/2:1 embankment slope stability analysis considered a full phreatic line (no drain) and a competent foundation. With embankment strength parameters of $\phi = 10.5^\circ$, $c = 850$ psf the computed factor of safety is 1.66.

3 -- James M. Dale -- 4/30/68

Lorn F. Dunnigan

Subj: ENG 22-5, Missouri WP-08, Panther Creek, Site No. C-2

- B. Floodplain Section at Station 6+10: The slope stability analysis of the 2 1/2:1 upstream embankment slope was made using the modified Swedish circle method. Rapid drawdown from the emergency spillway to the base of the embankment is considered. The embankment strength parameters used are $\phi = 10.5^\circ$, $c = 850$ psf. A foundation depth of 11 feet, strength parameters of $\phi = 14.5^\circ$ and $c = 400$ psf was considered and the computed factor of safety is 1.29. No berms were considered in the analysis.

2 - 10' berm upstream

The downstream 2 1/2:1 embankment slope stability analysis considers a full phreatic line (no drain) and an 11-foot depth of foundation. The strength parameters considered are the same as the upstream and the computed factor of safety is 1.29.

10' berm downstream

RECOMMENDATIONS

- A. Site Preparation: Investigational data indicates that limestone outcrops in the left abutment near the left channel bank. We suggest that the bedrock-soil contact be examined for overhangs when the cutoff trench is open. If overhangs are present they should be flattened and a check made to assure there are no overhangs elsewhere.

The alluvium material has a consolidation potential in the range of 0.095 ft/ft. Because of the high consolidation potential of the alluvium we suggest that the right channel bank be flattened to a 3:1 slope to reduce differential settlement. *It already is!*

- B. Cutoff Trench: We concur with the engineer's recommended cutoff depths with the suggestion that concurrent with the inspection of the limestone bedrock, after the cutoff trench is open, the permeability of the SC stratum encountered in TH 8 should be evaluated to determine if it is necessary to deepen the trench in the vicinity of test hole No. 9 to cut off seepage through the foundation.
- C. Principal Spillway: Material from TH 301 is stratified alluvium. The sample submitted from TH 301 to the Laboratory was logged in the field as CL. The sample is reported to be representative of the alluvial foundation material. A consolidation test was made on this material (lab. sample 68W1961 "T") and the test indicated a relatively high consolidation potential. Based on the test data the elongation potential is estimated to be in the range of 0.011 ft/ft. If this amount of settlement is intolerable, we suggest that you consider an alternate location. It is noted that the limestone bedrock occurs at elevation 883 in the vicinity of Station 6+25 and it might be possible to bottom the conduit on bedrock.

4 -- James M. Dale -- 4/30/68

Lorn P. Dunnigan

Subj: ENG 22-5, Missouri WP-08, Panther Creek, Site No. C-2

D. Drain: Near positive cutoff is anticipated with cutoff trench depths suggested and a drain is not considered necessary for stability of the embankment.

E. Embankment Design:

1. Placement of Materials: Selective placement of materials is suggested to utilize the higher plasticity CL materials like sample No. 68W1964, 68W1971, and 68W1972 in the center portion of the embankment. This type of material is expected to be more flexible than the low plasticity materials sampled.

All materials should be placed at a minimum of 95 percent of standard Proctor density with a placement moisture controlled on the wet side of Proctor optimum.

2. Slopes: With the embankment at 95 percent of Proctor and no drain, the proposed 2 1/2:1 slopes are expected to be stable.
3. Settlement: An overflow allowance of 1.5 feet is suggested to compensate for residual consolidation within the foundation and embankment.

Prepared by:

Gerald N. Gibson
Gerald N. Gibson

Reviewed and Approved by:

Lorn P. Dunnigan
Lorn P. Dunnigan

Attachments

cc: James M. Dale (2)
E. D. Butler, Lincoln, Nebraska

FEDERAL AGENCY ACQUISITION CENTER CITY STATE	MATERIALS (WP-08) ACQUISITION NUMBER LOCATION	MATERIALS	QUANTITIES RECEIVED AS PURCHASE ORDER OR ON ORDER												ATTENDING UNIT	UNIT NUMBER DATE	MATERIAL DESCRIPTION	MATERIALS MANUFACTURE DATE	SERIAL NO.
			1971	1972	1973	1974	1975	1976	1977	1978	1979	1980	1981	1982					
684	109.1 Panther Creek, Site No. C-2 Borrow, D+50, 3+00, L.Bag Alluvium	0-6	12/16	12/16	12/16	12/16	12/16	12/16	12/16	12/16	12/16	12/16	12/16	12/16	12/16				
			12/16	12/16	12/16	12/16	12/16	12/16	12/16	12/16	12/16	12/16	12/16	12/16	12/16	12/16			
1975 1976 1977 1978 1979	111.1 Borrow, B+00, 12+00, L.Bag Alluvium	0-6	12/26	12/26	12/26	12/26	12/26	12/26	12/26	12/26	12/26	12/26	12/26	12/26	12/26				
			12/26	12/26	12/26	12/26	12/26	12/26	12/26	12/26	12/26	12/26	12/26	12/26	12/26				
			12/26	12/26	12/26	12/26	12/26	12/26	12/26	12/26	12/26	12/26	12/26	12/26	12/26				
			12/26	12/26	12/26	12/26	12/26	12/26	12/26	12/26	12/26	12/26	12/26	12/26	12/26				
			12/26	12/26	12/26	12/26	12/26	12/26	12/26	12/26	12/26	12/26	12/26	12/26	12/26				
1979 1980 1981																			

YEAR	CONTRACT NO.	DESCRIPTION	TYPE	DAILY PRODUCTION												TOTAL	UNIT											
				1	2	3	4	5	6	7	8	9	10	11	12													
1968	105.1	Panther Creek, Site C-2 Borrow, D+50, 1+00, L.Bag <i>Top Soil</i>	0-2	ML	13	18	13	68	72	100											28.7	ML						
1969	105.2	" Borrow, D+00, 10+00, L.Bag <i>Aluminum</i>	2-8	CL	21	21	15	69	66	100											21.6	CL						
1970	106.1	" Borrow, D+00, 10+00, L.Bag <i>Aluminum</i>	0-4	ML	17	23	16	56	23	100											20.9	CL						
1971	107.1	" Borrow, E+00, 12+00, L.Bag <i>Slope wash</i> <i>19,200 cu yd.</i>	0-3.5	ML	23	30	56	93	97	100											35.17	CL	105,912.0					263
1972	107.2	" Borrow, C+50, 3+00, L.Bag <i>Aluminum</i>	3-5-8	CL	29	35	66	72	75	100											42.10	CL	105,018.5					266
1973	108.1	" Borrow, C+50, 3+00, L.Bag <i>Aluminum</i>	2-10	CL	27	35	15	68	71	100											27.16	CL						

UNITED STATES GEOLOGICAL SURVEY
WATER RESOURCES DIVISION
PAPER 1485-C

LADINET-111 NO. _____


MATERIALS TESTING REPORT U.S. DEPARTMENT of AGRICULTURE SOIL CONSERVATION SERVICE **CONSOLIDATION TEST**

PROJECT and STATE _____ SAMPLE LOCATION _____

FIELD SAMPLE NO. _____ DEPTH _____ GEOLOGIC ORIGIN Aluminum

TYPE OF SAMPLE _____ TESTED AT _____ APPROVED BY [Signature] DATE 1-26-68

CLASSIFICATION _____ TEST SPECIFICATIONS: Saturated at Start
G_s 2.65 LL 29 PI 12
INITIAL DENSITY γ_d _____
INITIAL VOID RATIO, e_0 0.5132
COMPRESSION INDEX, C_c 0.265



REMARKS _____


LABORATORY NO. 100-100-100

MATERIALS TESTING REPORT	U. S. DEPARTMENT of AGRICULTURE SOIL CONSERVATION SERVICE	LOG TIME CONSOLIDATION
--------------------------	--	-----------------------------------

PROJECT AND STATE	SAMPLE LOCATION
-------------------	-----------------


FIELD SAMPLE NO.	DEPTH	GEOLOGIC ORIGIN
------------------	-------	-----------------

TYPE OF SAMPLE	TESTED AT	APPROVED BY	DATE
----------------	-----------	-------------	------



LAB. REPORT NO. 1000000

MATERIALS TESTING REPORT		U.S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE		LOG TIME CONSOLIDATION	
PROJECT AND STATE				SAMPLE LOCATION	
FIELD SAMPLE NO.	DEPTH	GEOLOGIC ORIGIN <i>Aluminum</i>			
TYPE OF SAMPLE	TESTED AT	APPROVED BY <i>[Signature]</i>	DATE <i>4-26-68</i>		



REMARKS

MATERIALS TESTING REPORT		U.S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE			SOIL PERMEABILITY		
PROJECT AND STATE MISSOURI				SAMPLE LOCATION COLUMBIANA, MISSOURI			
FIELD SAMPLE NO. 501-201	DEPTH 501-201	GEOLOGIC ORIGIN					
TYPE OF SAMPLE	TESTED AT COLUMBIANA, MISSOURI	APPROVED BY		DATE			
CLASSIFICATION CL LL 20 PI 12				SPECIFIC GRAVITY			
TEST NO	2010	6020	8030	4	$G_s (-)^{\#4}$	2.65	
INITIAL MOISTURE %					$G_s (+)^{\#4}$		
DRY DENSITY D_{100}^{100} D. per ft	1.52	1.60	1.65		$G_m(Bulk)(+)^{\#4}$		
VOID RATIO	0.7382	0.6595	0.5731		TEST SPECIFICATIONS Falling Head Perm Test on the Consolidation Sample		
PERMEABILITY COEF FPD	0.047	0.0027	0.0036				
PERCOLATION COEF							
M_L DURING TEST							
REMARKS							

MATERIALS TESTING REPORT U.S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE **TRIAxIAL SHEAR TEST**


PROJECT and STATE: Highway 242nd Site No. 2-2 Missouri SAMPLE LOCATION: E. Box 9700, 14th St

FIELD SAMPLE NO: 2-119 DEPTH: 3-5.2' GEOLOGIC ORIGIN: Alluvium

TYPE OF SAMPLE: undisturbed TESTED AT: SRL, Lincoln APPROVED BY: [Signature] DATE: 4-25-65

INDEX TEST DATA			SPECIMEN DATA		TYPE OF TEST
USCS <u>CL</u>	LL <u>29</u>	PI <u>12</u>	HEIGHT <u>3.0</u> "	DIAMETER <u>1.01</u> "	UU <input type="checkbox"/> CU <input checked="" type="checkbox"/> CU <input type="checkbox"/> CD <input type="checkbox"/>
% FINER (mm): 0.002 <u>19</u> ; 0.005 <u>23</u> ; 0.074 (#200) <u>64</u>			MATERIALS TESTED PASSED _____ SIEVE		
G_s (-#4) <u>2.65</u> ; G_s (+#4) _____			METHOD OF PREPARATION: <u>Trimmed</u> <u>From undisturbed core</u>		
STANDARD: γ_d MAX. _____ pcf; w_p _____ %			MOLDING MOISTURE _____ %		
MODIFIED: γ_d MAX. _____ pcf; w_p _____ %			MOLDED AT _____ % OF γ_d MAXIMUM		

DRY DENSITY		MOISTURE CONTENT, %			TIME OF CONSOLIDATION (hrs.)	MINOR PRINCIPAL STRESS σ_3 (psi)	DEVIATOR STRESS $\sigma_1 - \sigma_3$ (psi)	AXIAL STRAIN AT FAILURE, ϵ (%)
INITIAL pcf	CONSOLIDATED pcf	START OF TEST	DEG. OF SAT. AT START OF TEST	END OF TEST				
1.50	1.54	22.9	79.2	21.4	6.67	10	2	
1.62	1.68	21.7	90.4	19.7	6.15	20	5	
1.61	1.68	22.1	90.6	19.4	6.10	30	7	
1.47	1.53	24.5	80.8	21.6	5.83	15	5	



REMARKS SOAKED TO SATURATION

MATERIALS TESTING REPORT U.S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE TRIAXIAL SHEAR TEST


PROJECT AND STATE: Lincoln Creek Site No. 2-7 Missouri SAMPLE LOCATION: Borrow

FIELD SAMPLE NO.: ATK DEPTH: _____ GEOLOGIC ORIGIN: Mix (Alluvial)

TYPE OF SAMPLE: Compacted TESTED AT: SML Lincoln APPROVED BY: [Signature] DATE: 4-26-63

INDEX TEST DATA		SPECIMEN DATA		TYPE OF TEST
USCS _____; LL _____; PI _____	HEIGHT <u>3.0</u> "; DIAMETER <u>1.4</u> "	MATERIALS TESTED PASSED # <u>4</u> SIEVE		UU <input type="checkbox"/>
% FINER (mm): 0.002 _____; 0.005 _____; 0.074 (#200) _____	METHOD OF PREPARATION <u>STATIC</u>	MOLDING MOISTURE <u>17.4</u> %		CU <input checked="" type="checkbox"/>
G _s (-#4) <u>2.63</u> ; G _s (+#4) _____	LAYER CONSOLIDATION AND SOAKED	MOLDED AT <u>94.9</u> % OF γ_d MAXIMUM		CU <input type="checkbox"/>
STANDARD: γ_d MAX. <u>111.0</u> pcf; w_0 <u>15.0</u> %				CD <input type="checkbox"/>
MODIFIED: γ_d MAX. _____ pcf; w_0 _____%				

DRY DENSITY		MOISTURE CONTENT, %			TIME OF CONSOLIDATION (hrs.)	MINOR PRINCIPAL STRESS σ_3 (psi)	DEVIATOR STRESS $\sigma_1 - \sigma_3$ (psi)	AXIAL STRAIN AT FAILURE, E (%)
INITIAL pcf	CONSOLIDATED pcf	START OF TEST	DEG. OF SAT. AT START OF TEST	END OF TEST				
106.3	106.9	18.9	90.9	18.5	9.18	10	27.5	3
106.5	107.1	18.6	91.0	18.2	4.21	20	32.1	6
106.6	107.2	18.5	90.7	17.8	5.15	30	39.6	11



REMARKS: TESTED @ 95.8% STD

MATERIALS TESTING REPORT		U.S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE		TRIAXIAL SHEAR TEST	
PROJECT AND STATE <u>Side 2-2, Madison</u>			SAMPLE LOCATION <u>POYOW #40, 17+00</u>		
FIELD SAMPLE NO. <u>107.2</u>	DEPTH <u>2.5-9'</u>	GEOLOGIC ORIGIN <u>Glacial Till</u>			
TYPE OF SAMPLE <u>Compacted</u>	TESTED AT <u>Soil, Lincoln</u>	APPROVED BY <u>H N G</u>	DATE <u>4-26-68</u>		
INDEX TEST DATA			SPECIMEN DATA		TYPE OF TEST
USCS <u>CL</u> ; LL <u>40</u> ; PI <u>20</u>			HEIGHT <u>3.0</u> " ; DIAMETER <u>1.4</u> "		TEST
% FINER (mm): 0.002 <u>29</u> ; 0.005 <u>35</u> ; 0.074 (#200) <u>75</u>			MATERIALS TESTED PASSED #4 SIEVE		UU <input type="checkbox"/>
G_s (#4) <u>2.66</u> ; G_s (#4)			METHOD OF PREPARATION <u>STATIC</u>		CU <input checked="" type="checkbox"/>
STANDARD: γ_d MAX. <u>105.0</u> pcf; w_0 <u>15.5</u> %			MOLDING MOISTURE <u>20.3</u> %		CU <input type="checkbox"/>
MODIFIED: γ_d MAX. _____ pcf; w_0 _____ %			MOLDED AT <u>95.2</u> % OF γ_d MAXIMUM		CD <input type="checkbox"/>
DRY DENSITY		MOISTURE CONTENT, %			TIME OF CONSOLIDATION (hrs.)
INITIAL pcf <input checked="" type="checkbox"/> g/cc <input type="checkbox"/>	CONSOLIDATED pcf <input checked="" type="checkbox"/> g/cc <input type="checkbox"/>	START OF TEST	DEG. OF SAT. AT START OF TEST	END OF TEST	MINOR PRINCIPAL STRESS σ_3 (psi)
<u>100.0</u>	<u>100.0</u>	<u>23.3</u>	<u>93.6</u>	<u>23.3</u>	<u>5.92</u>
<u>100.2</u>	<u>100.5</u>	<u>23.1</u>	<u>92.6</u>	<u>22.8</u>	<u>6.08</u>
<u>99.4</u>	<u>101.2</u>	<u>23.7</u>	<u>93.7</u>	<u>22.6</u>	<u>5.78</u>
<u>96.6</u>	<u>99.0</u>	<u>24.6</u>	<u>93.7</u>	<u>24.4</u>	<u>6.60</u>
<u>100.2</u>	<u>102.4</u>	<u>23.5</u>	<u>92.9</u>	<u>22.7</u>	<u>6.22</u>
		DEVIATOR STRESS ($\sigma_1 - \sigma_3$), psi			
STRAIN (e), %					
SHEAR STRESS (c), psi					
		NORMAL STRESS (σ), psi			
REMARKS <u>AVERAGE TEST $\phi = 95.1$ % STD.</u>					

MATERIALS U.S. DEPARTMENT OF AGRICULTURE COMPACTION AND
 TESTING REPORT SOIL CONSERVATION SERVICE PENETRATION RESISTANCE

PROJECT OR STATE Parthen Creek #C-2, Missouri



FIELD SAMPLE NO. 202.1 LOCATION E Emer. Spuy. 100' St. U+00 DEPTH 0.5'-10'

GEOLOGIC ORIGIN Glacial Till TESTED AT S.M.L. Lincoln APPROVED BY H.N.L. DATE 4-26-68

CLASSIFICATION CH LL 51 PI 30 CURVE NO. 1 OF 6

MAX. PARTICLE SIZE INCLUDED IN TEST < # 4 STD. (ASTM D-698) METHOD L


SPECIFIC GRAVITY (G_s) { MINUS NO. 4 2.72 MOD. (ASTM D-1557) METHOD _____
 PLUS NO. 4 _____ OTHER TEST (SEE REMARKS)



REMARKS

MATERIALS TESTING REPORT SOIL CONSERVATION SERVICE
 U.S. DEPARTMENT OF AGRICULTURE
 COMPACTION AND PENETRATION RESISTANCE

PROJECT OR STATE: Springer Creek # C-2, Missouri
 FIELD SAMPLE NO: 1011 LOCATION: BORROW, A-75, E-85 DEPTH: 0-2.5'
 GEO. SEC. OR GR.: Gilgoh Till TESTED AT: S.M.L. Lincoln APPROVED BY: [Signature] DATE: 4-23-68
 CLASSIFICATION: CL LL 34 PI 18 CURVE NO. 2 OF 6
 MAX. PARTICLE SIZE INCLUDED IN TEST: < #4 STD. (ASTM D-698) ; METHOD A
 SPECIFIC GRAVITY (G_s): MINUS NO. 4 2.66 MOD. (ASTM D-1557) ; METHOD _____
 PLUS NO. 4 _____ OTHER TEST (SEE REMARKS)



REMARKS

MATERIALS TESTING REPORT U.S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE COMPACTION AND PENETRATION RESISTANCE

PROJECT OR STATE Panther Creek # C-2, Missouri



FIELD SAMPLE NO. Composite LOCATION Borrow Composite DEPTH 0-6'

GEOLOGIC ORIGIN Mix (Alluvial) TESTED AT S.M.L. Lincoln APPROVED BY [Signature] DATE 4-26-65

CLASSIFICATION CL LL PI CURVE NO. 3 OF 6

MAX. PARTICLE SIZE INCLUDED IN TEST < #4 STD. (ASTM D-698) METHOD A

SPECIFIC GRAVITY (G_s) { MINUS NO. 4 2.63 MOD. (ASTM D-1557) METHOD
PLUS NO. 4 OTHER TEST (SEE REMARKS)



REMARKS

MATERIALS TESTING REPORT U.S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE COMPACTION AND PENETRATION RESISTANCE

PROJECT OR SITE Parthen Creek # C-2 Missouri



FIELD SAMPLE NO. 125.2 & 125.1 LOCATION 0+50, 1+00 = 105.1 DEPTH 2-E
2-10

GEOLOGIC ORIGIN Alluvium TESTED AT C.M.L. Lincoln APPROVED BY [Signature] DATE 4-26-62

CLASSIFICATION CL LL PI CURVE NO. 4 OF 6

MAX. PARTICLE SIZE INCLUDED IN TEST 4 # 2 STD. (ASTM D-698) METHOD 2

SPECIFIC GRAVITY (G_s) { MINUS NO. 4 2.66 MOD. (ASTM D-1557) METHOD
 PLUS NO. 4 OTHER TEST (SEE REMARKS)





MAX. γ_d 112.5 pcf
 OPT. MOIST. 15.0 %
 NATURAL MOIST. %

REMARKS

LABORATORY NO. 6701971

MATERIALS TESTING REPORT		U.S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE		COMPACTION AND PENETRATION RESISTANCE	
PROJECT OR STATE <u>Panther Creek "C-2", Missouri</u>					
FIELD SAMPLE NO. <u>1071</u>	LOCATION <u>Borrow, E-22 12+00</u>			DEPTH <u>0-3.5</u>	
GEOLOGIC ORIGIN <u>Glacial Till derived</u>		TESTED AT <u>S.M. Lurie</u>	APPROVED BY <u>N.V. G.</u>	DATE <u>4-26-67</u>	
CLASSIFICATION <u>CL</u>		LL <u>35</u>	PI <u>17</u>	CURVE NO. <u>5</u> OF <u>6</u>	
MAX. PARTICLE SIZE INCLUDED IN TEST <u>< #4</u>			STD. (ASTM D-698) <input checked="" type="checkbox"/> METHOD <u>A</u>		
SPECIFIC GRAVITY (G _s)			MOD. (ASTM D-1557) <input type="checkbox"/> METHOD _____		
			OTHER TEST <input type="checkbox"/> (SEE REMARKS)		
			MINUS NO. 4 <u>2.63</u>		
			PLUS NO. 4 _____		





MAX. γ_d 106.0 pcf
 OPT. MOIST. 17.0 %
 NATURAL MOIST. _____ %

REMARKS

LABORATORY NO. 6300177


MATERIALS		U.S. DEPARTMENT OF AGRICULTURE		COMPACTION AND	
TESTING REPORT		SOIL CONSERVATION SERVICE		PENETRATION RESISTANCE	
PROJECT OR STATE <u>Panther Creek "C-2, Missouri</u>					
FIELD SAMPLE NO.	LOCATION	DEPTH			
<u>1072</u>	<u>Barren, E+00 12+00</u>	<u>15'-2'</u>			
GEOLOGIC ORIGIN	TESTED AT	APPROVED BY	DATE		
<u>Glacial Till</u>	<u>S.M.L. Lincoln</u>	<u>[Signature]</u>	<u>4-26-68</u>		
CLASSIFICATION	LL	PI	CURVE NO.	OF	
<u>CL</u>	<u>40</u>	<u>20</u>	<u>6</u>	<u>6</u>	
MAX. PARTICLE SIZE INCLUDED IN TEST <u>< #4</u>			STD. (ASTM D-698) <input checked="" type="checkbox"/> METHOD <u>A</u>		
SPECIFIC GRAVITY (G _s)			MOD. (ASTM D-1557) <input type="checkbox"/> METHOD _____		
MINUS NO. 4 <u>2.66</u>			OTHER TEST <input type="checkbox"/> (SEE REMARKS)		
PLUS NO. 4 _____					



REMARKS

MATERIALS TESTING REPORT		U. S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE		SUMMARY - SLOPE STABILITY ANALYSIS						
PROJECT AND STATE LEWIS CREEK SITE - 1955				DATE 11-21-55						
METHOD OF ANALYSIS EMPIRICAL CIRCLE			ANALYZED AT M. L. LINDSEY		APPROVED BY					
TRIAL NO	SLOPE	SOURCE AND USE OF MATERIALS	CLASSIFICATION	ADOPTED DESIGN DATA				REMARKS	F _s	
				γ _d (pcf)	γ _m (pcf)	γ _{sub} (pcf)	φ (deg)			tan φ (psf)
1	2 1/2:1	Embank.	CL	97.0	119.0	56.5	12.5	0.253	402	1.60
2	2 1/2:1	Embank.	CL	99.7	118.0	56.5	10.5	0.185	950	1.23
3	2 1/2:1	Embank.	CL	106.5	122.5	63.0	13.5	0.340	1202	1.70
4	2 1/2:1	MAXIMUM SECTION @ STATION 6+25 Full depth - No berm - Arc cut from app. shldr. thru emb. (19.5°-35°) only							1.73	
5	2 1/2:1	Same conditions as trial #1							1.66	
6	2 1/2:1	Same conditions as trial #1							1.92	
7	2 1/2:1	MAXIMUM SECTION @ STATION 6+25 Full depth - No berm - Arc cut from app. shldr. thru emb. (19.5°-35°) only							1.57	
8	2 1/2:1	Same conditions as trial #1							1.20	
9	2 1/2:1	Same conditions as trial #1							1.45	
10	2 1/2:1	FLOOD PLAIN SECTION @ STATION 4+00 Full depth - No berm - Arc cut from app. shldr. thru emb. (10.5°-85°) Full depth - No berm - Arc cut from app. shldr. thru emb. (10.5°-95°) Full depth - No berm - Arc cut from app. shldr. thru emb. (10.5°-95°)							1.40	
11	2 1/2:1	Same conditions as trial #10							1.29	
12	2 1/2:1	Same conditions as trial #10							1.32	

38-257
Panther Creek site No. 2
Missouri



MAXIMUM SECTION
STATION 6+25

Scale 1 inch = 5 Feet

558-857/
Panther Creek Station
Missouri

FLOOD PLAIN SECTION
STATION 4+00

#9

$15 = 14.5$
#9

$E_3 = 129$
 $E_3 = 157$
#7

$2 = 11$
 $(10.5 - 8.5)$

$(14.5 - 4.0)$

927.8
#10

57.3
 57.1

#11

920.2
#12

920.2
 920.12

920.12
 920.12

#12

$68 = 1.48$

920

890

Scale 1 inch = 20 feet

STRUCTURE DATA


Class of Structure: **"a" Floodwater Retarding**
 Drainage Area (total): 5.031 Ac. 211 Sq. Mi.
 (uncontrolled): 1.995 Ac. 702 Sq. Mi.
 Time of Concentration: 2.21 Hours
 Soil Cover Complex Number: 78 for A.M.C. II
 Sediment Capacity Available: 476 Ac. Ft. below Elev. 906.5
 Total Sediment Capacity Available: 476 Ac. Ft. ①
 Capacity Equivalents (Vol.): 1.27 In.
 Retarding Capacity Provided: 1510 Ac. Ft. ①
 Capacity Equivalents (Vol.): 4.05 In.
 Water Supply Provided: _____ Ac. Ft. - Identify Uses

Principal Spillway:
 Maximum Capacity (uncontrolled): 339 c.f.s.
 10 Day Drainage Elev.: 906.5
 Emergency Spillway:
 Percent Chance Use: 2 Storm Duration: 6 Hours
 Type: Earth-Exit Channel
 Type: Rock-Inlet Channel "n" Value Used: 0.04

② Emergency Spillway Hydrograph for Class 6 Structures
 Rainfall: 7.90 in.
 Runoff: 5.31 in.
 ⑤ Peak Inflow: 7237 c.f.s.
 Maximum Discharge - Emergency Spillway: 710 c.f.s.
 Maximum Water Surface Elev.: 922.2
 Velocity of flow (V_e): 5.7 f.p.s.

- Supplementary Data and Special Design Features:
 ① Based on uncontrolled drainage area
 ② The following conditions existed:
 a. Emergency Spillway Routing considered
 b. Structure B-13, B-10, and B-11 in place.
 c. Freeboard Routing considered total drainage area, uncontrolled.
 ③ Taken from Composite Hydrograph.

③ Freeboard Hydrograph for Class 6 Structures:
 Rainfall: 13.70 in.
 Runoff: 10.83 in.
 Peak Inflow: 18,516 c.f.s.
 Maximum Discharge - Emergency Spillway: 8774 c.f.s.
 Maximum Water Surface Elev.: 927.9
 Reservoir Capacity



AS BUILT
 10-3-72

Total Storage - Ac. Ft.

STRUCTURE C-2
 PANTHER CREEK WATERSHED PL. 566
 HARRISON COUNTY, MISSOURI
 U. S. DEPARTMENT OF AGRICULTURE
 SOIL CONSERVATION SERVICE
 N.B.T. & R.M.K. 1959
 U.S.G.
 R.M.T. & M.R. 7/11/57 27,029-E

- Supplementary Data and Special Design Features:
 1. The Emergency Spillway inlet channel was routed with a 0.00 slope. A 0.005 slope was used.
 2. Principal Spillway Crest Elev. 906.5
 3. Emergency Spillway Crest Elev. 920.2
 4. Emergency Spillway Bottom Width = 180'
 5. Settled Top of Dam Elev. 927.9
 H.S. = 34.2 x 1994 = 78,165

 FLOOD HYDROGRAPH PACKAGE - REC-1

 FLOOD HYDROGRAPH PACKAGE (MEC-1)
 DAM SAFETY VERSION JULY 1979
 LAST MODIFICATION 01 APR 80

 1 A1=PHASE 1 DAM INSPECTION FOR STATE OF MISSOURI - ST. LOUIS DISTRICT COE
 2 A2= HARRISON COUNTY DAM C-2 MO ID # 10014 FILE - M219457PHD1-HARRISON
 3 A3 PROBABLE MAXIMUM STORM & OTHER RATIOS
 4 B ZBP 0 5 0 0 0 0 0 0 0 0
 5 B1 5
 6 J 0.15 0.2 0.25 1 0.35 0.4 0.45 0.5 1.0
 7 J10.15 0.2 0.25 1 0.35 0.4 0.45 0.5 1.0
 8 K
 9 K1 CALCULATE IMFLON HYDROGRAPH TO B-11 1.0
 10 M 1 23.9 101. 120. 130.
 11 P
 12 T
 13 W 0.186 1.
 14 X
 15 Y
 16 K1 ROUTE HYDROGRAPH THROUGH STRUCTURE B-11 (MO.ID.#10461)
 17 Y1
 18 Y1
 19 1480. 81. 52. 82. 84. 85. 86. 87. 88. 89.
 20 150.0 4. 12. 20. 40. 56. 142. 249. 666. 1018.
 21 857.0 2. 6. 9. 13. 29. 47. 58. 75.
 22 3666. 78. 74. 76. 78. 80. 82. 84. 86.
 23 3980.
 24 5086.8
 25 319. 15. 430.
 26 3666.8 86.9 87.7
 27 3813. 0.5 1. 60. 86.8
 28 A
 29 K1 CHANNEL ROUTING TO STRUCTURE C-2
 30 Y
 31 Y1
 32 160.06 0.05 0.06 62.5 85. 8500. 0.0075 62.5 325. 62.5
 33 170.0 85. 300. 72. 318. 65.5 322. 62.5 325. 62.5
 34 17330. 66. 360. 75.5 430. 85.
 35 K
 36 K1 CALCULATE IMFLON HYDROGRAPH TO B-13 1.0
 37 M 1 23.9 101. 120. 130.
 38 P
 39 T
 40 W 0.324 1.
 41 X
 42 Y
 43 K1 ROUTE HYDROGRAPH THROUGH STRUCTURE B-13 (MO.ID.#10453)
 44 Y1
 45 Y1
 46 14312. 112.5 113. 113.5 114.5 115.5 116.4 116.8 117. 117.5
 47 14312. 118.5 119. 119.6 119.8 120. 120.6 121. 122. 122.
 48 14040 15. 35. 47. 63. 77. 77. 77. 125. 166. 301.
 49 15475. 684. 924. 1253. 1373. 1503. 1904. 2205. 3016.
 50 350.0 2. 5. 13. 25. 50. 100. 150. 200. 240.

47 100.0 100.0 100.0 100.0 100.0 100.0 100.0 100.0 100.0 100.0 100.0 100.0 100.0 100.0
 48 100.0 100.0 100.0 100.0 100.0 100.0 100.0 100.0 100.0 100.0 100.0 100.0 100.0 100.0
 49 100.0 100.0 100.0 100.0 100.0 100.0 100.0 100.0 100.0 100.0 100.0 100.0 100.0 100.0
 50 100.0 100.0 100.0 100.0 100.0 100.0 100.0 100.0 100.0 100.0 100.0 100.0 100.0 100.0

51 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 52 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 53 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 54 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 55 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 56 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 57 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 58 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 59 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.

K1 CHANNEL ROUTING TO STRUCTURE C-2
 60 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 61 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 62 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 63 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 64 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 65 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 66 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 67 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 68 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 69 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 70 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 71 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 72 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 73 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.

K1 CALCULATE INFLOW HYDROGRAPH TO B-10
 74 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 75 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 76 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 77 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 78 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 79 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 80 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 81 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 82 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 83 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 84 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 85 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 86 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 87 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 88 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.

K1 CHANNEL ROUTING TO STRUCTURE C-2
 89 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 90 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 91 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 92 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 93 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 94 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 95 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 96 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 97 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 98 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 99 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 100 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.

K1 CALCULATE INFLOW HYDROGRAPH TO UNCONTROLLED AREA OF WEST ARM OF C-2
 101 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 102 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 103 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 104 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 105 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 106 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 107 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 108 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 109 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 110 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.

K1 CHANNEL ROUTING TO STRUCTURE C-2
 111 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 112 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 113 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 114 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 115 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 116 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 117 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 118 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 119 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.
 120 93. 96. 100. 103. 107.6 112.7 115.8 118. 120.

LINE NO.	DESCRIPTION	VALUE 1	VALUE 2	VALUE 3	VALUE 4	VALUE 5
101	KT COMBINE HYDROGRAPHS FROM WEST ARM OF C-2					
102	K C 12					
103	KT CALCULATE INFLOW HYDROGRAPH TO LT-93					
104	M 2 C-358	1.0				
105	P	23.9	101.	120.	130.	
106	T					-1-90.
107	K 2	0.204				
108	K 1					
109	K 13					
110	KT ROUTE HYDROGRAPH THROUGH STRUCTURE LT-93 (NO.ID.#11938)					
111	V 1					
112	V1	96.	97.	98.	99.	100.
113	V1	101.3	101.5	102.		
114	V1	103.	104.	105.	106.	107.
115	V1	108.	109.	110.	111.	112.
116	V1	113.	114.	115.	116.	117.
117	V1	118.	119.	120.	121.	122.
118	V1	123.	124.	125.	126.	127.
119	V1	128.	129.	130.	131.	132.
120	V1	133.	134.	135.	136.	137.
121	V1	138.	139.	140.	141.	142.
122	V1	143.	144.	145.	146.	147.
123	V1	148.	149.	150.	151.	152.
124	V1	153.	154.	155.	156.	157.
125	V1	158.	159.	160.	161.	162.
126	V1	163.	164.	165.	166.	167.
127	V1	168.	169.	170.	171.	172.
128	V1	173.	174.	175.	176.	177.
129	V1	178.	179.	180.	181.	182.
130	V1	183.	184.	185.	186.	187.
131	V1	188.	189.	190.	191.	192.
132	V1	193.	194.	195.	196.	197.
133	V1	198.	199.	200.	201.	202.
134	V1	203.	204.	205.	206.	207.
135	V1	208.	209.	210.	211.	212.
136	V1	213.	214.	215.	216.	217.
137	V1	218.	219.	220.	221.	222.
138	V1	223.	224.	225.	226.	227.
139	V1	228.	229.	230.	231.	232.
140	V1	233.	234.	235.	236.	237.
141	V1	238.	239.	240.	241.	242.
142	V1	243.	244.	245.	246.	247.
143	V1	248.	249.	250.	251.	252.
144	V1	253.	254.	255.	256.	257.
145	V1	258.	259.	260.	261.	262.
146	V1	263.	264.	265.	266.	267.
147	V1	268.	269.	270.	271.	272.
148	V1	273.	274.	275.	276.	277.
149	V1	278.	279.	280.	281.	282.
150	V1	283.	284.	285.	286.	287.

151	Y	1	1	1			
152	Y	1	1	1			
153	V	0.06	0.04	0.06	85.	142.	12330. 0.0054
154	V	73.0	142.	250.	122.	316.	102. 550. 85. 560. 85.
155	V	7750.	102.	1170.	122.	1670.	142.
156	C	1A					1
157	K	KT CALCULATE INFLOW HYDROGRAPH TO UNCONTROLLED AREA OF EAST ARM OF C-2					
158	M	1	2	3.520	120.	130.	1.0
159	P	1	23.0	101.	120.	130.	-1-90.
160	T						
161	W	2	1.326				
162	X						
163	X		1.0				
164	K	4	19				1
165	K	20					1
166	K	KT TOTAL INFLOW HYDROGRAPH TO C-2 (COMBINE FROM EAST & WEST ARMS)					
167	V	1					
168	V	1					
169	V	1	1				
170	V	1	1				
171	V	1	1				
172	V	1	1				
173	V	1	1				
174	V	1	1				
175	V	1	1				
176	V	1	1				
177	V	1	1				
178	V	1	1				
179	V	1	1				
180	V	1	1				
181	V	1	1				
182	V	1	1				
183	V	1	1				
184	V	1	1				

169	V	1	1	907.3	908.3	910.3	917.	-206.3	920.9	921.4	922.4
170	V	1	1	925.4	926.4	927.4	928.4	929.	930.	931.	931.
171	V	1	1	85.	269.	259.	342.	362.	583.	720.	1520.
172	V	1	1	5760.	7570.	9820.	17010.	13210.	16110.	19020.	
173	V	1	1	80.0	120.	168.	462.	1098.	2010.	2700.	8250.
174	V	1	1	8825.	897.	900.	904.	907.	909.	924.	927.
175	V	1	1	8906.3							
176	V	1	1	8928.3							
177	V	1	1	510.0	60.	270.	540.	590.	890.	1150.	1390.
178	V	1	1	8928.3	928.6	928.9	929.2	929.3	929.4	929.5	929.6
179	V	1	1	99							
180	V	1	1								
181	V	1	1								
182	V	1	1								
183	V	1	1								
184	V	1	1								

P6.2 P6.3 P6.4 P6.5 P6.6 P6.7 P6.8 P6.9 P6.10 P6.11 P6.12 P6.13 P6.14 P6.15
 87.7 86.6 87.7 86.7 86.8 86.7 86.7 86.8 86.9 87.0 87.1 87.2 87.3 87.4
 87.7 86.6 87.7 86.7 86.8 86.7 86.7 86.8 86.9 87.0 87.1 87.2 87.3 87.4

PROJECT 9437: DATE 20 MAR 81 PAGE 355
 FLOOD HYDROGRAPH PACKAGE - REC-1 PROGRAM M21/02-1V TIME 17:48:24 CASE C2

P6.2 P6.3 P6.4 P6.5 P6.6 P6.7 P6.8 P6.9 P6.10 P6.11 P6.12 P6.13 P6.14 P6.15
 87.7 86.6 87.7 86.7 86.8 86.7 86.7 86.8 86.9 87.0 87.1 87.2 87.3 87.4
 87.7 86.6 87.7 86.7 86.8 86.7 86.7 86.8 86.9 87.0 87.1 87.2 87.3 87.4

PEAK 6-HOUR 24-HOUR 72-HOUR TOTAL VOLUME
 CFS 2024. 1037. 317. 91366.
 CMS 57. 29. 9. 2587.
 INCHES 24.86 30.42 30.42 30.42
 AC-FT 631.60 772.59 772.59 772.59
 THOUS CU 4 518. 629. 629. 629.
 634. 776. 776.

MAXIMUM STORAGE = 145.

MAXIMUM STAGE IS 91.0

SUB-AREA RUNOFF COMPUTATION

CALCULATE INFLOW HYDROGRAPH TO UNCONTROLLED AREA OF EAST ARM OF C-2

ISTAT ICOPP IECOM ITAPE JPLT JPPT INAME ISTAGE IAUTO
 18 0 0 0 0 0 0 0 0 0

HYDROGRAPH DATA
 IIMDE IUMS YAREA SNAP TRSDA TRSPC RATIO ISNOW ISAME LOCAL
 1 2 3.52 .00 3.52 1.00 .000 C C C

PRECIP DATA
 SPFE PPS R6 R12 R24 R48 R72 R96
 .00 23.90 101.00 120.00 130.00 .00 .00 .00

LOSS DATA
 LPOPT STRRR DLTRR RTIOL ERRAIN STRKS RTIOR SINTL CNSTL ALSPM RTIMP
 0 .00 .00 1.00 .00 .00 1.00 -1.00 -90.00 .00 .00

CURVE NO = -90.00 WFTNESS = -1.00 EFFECT CN = 90.00

UNIT HYDROGRAPH DATA

Tc = .00 LAG = 1.53

RECESSION DATA
 STOR= .00 BRESN= .00 RTIOR= 1.00
 UNIT HYDROGRAPH R2 END OF PERIOD ORIGINATES, TC= .00 HOURS, LFG= 1.33 VOL= 1.00
 27. 56. 109. 173. 243. 314. 389. 459. 529. 599. 669.
 966. 1602. 1145. 1193. 1232. 1232. 1231. 1231. 1187. 1139. 1086.
 1028. 907. 892. 810. 719. 640. 566. 483. 404. 325. 246.
 418. 379. 343. 288. 260. 237. 214. 191. 174. 157. 140.
 128. 118. 107. 95. 82. 70. 58. 46. 34. 22. 10.
 58. 48. 39. 32. 26. 20. 15. 12. 10. 10. 10.
 9. 8. 7. 6. 5. 4. 3. 2. 2. 2. 2.

MO-DA	HR-PM	PERIOD	RAIN	EXCS	LOSS	COMP G	END-OF-PERIOD FLOW	MO-DA	HR-PM	PERIOD	RAIN	EXCS	LOSS	COMP G
1-01	1-01	1	-01	-00	-01	0	1-01 12-05	145	145	145	-20	-20	-01	1633
1-01	1-01	2	-01	-00	-01	0	1-01 12-10	146	146	146	-20	-20	-01	1643
1-01	1-01	3	-01	-00	-01	0	1-01 12-15	147	147	147	-20	-20	-01	1653
1-01	1-01	4	-01	-00	-01	0	1-01 12-20	148	148	148	-20	-20	-00	1664
1-01	1-01	5	-01	-00	-01	0	1-01 12-25	149	149	149	-20	-20	-00	1674
1-01	1-01	6	-01	-00	-01	0	1-01 12-30	150	150	150	-20	-20	-00	1684
1-01	1-01	7	-01	-00	-01	0	1-01 12-35	151	151	151	-20	-20	-00	1694
1-01	1-01	8	-01	-00	-01	0	1-01 12-40	152	152	152	-20	-20	-00	1704
1-01	1-01	9	-01	-00	-01	0	1-01 12-45	153	153	153	-20	-20	-00	1714
1-01	1-01	10	-01	-00	-01	0	1-01 12-50	154	154	154	-20	-20	-00	1724
1-01	1-01	11	-01	-00	-01	0	1-01 12-55	155	155	155	-20	-20	-00	1734
1-01	1-01	12	-01	-00	-01	0	1-01 13-00	156	156	156	-20	-20	-00	1744
1-01	1-01	13	-01	-00	-01	0	1-01 13-05	157	157	157	-24	-24	-00	1754
1-01	1-01	14	-01	-00	-01	0	1-01 13-10	158	158	158	-24	-24	-00	1764
1-01	1-01	15	-01	-00	-01	0	1-01 13-15	159	159	159	-24	-24	-00	1774
1-01	1-01	16	-01	-00	-01	0	1-01 13-20	160	160	160	-24	-24	-00	1784
1-01	1-01	17	-01	-00	-01	0	1-01 13-25	161	161	161	-24	-24	-00	1794
1-01	1-01	18	-01	-00	-01	0	1-01 13-30	162	162	162	-24	-24	-00	1804
1-01	1-01	19	-01	-00	-01	0	1-01 13-35	163	163	163	-24	-24	-00	1814
1-01	1-01	20	-01	-00	-01	0	1-01 13-40	164	164	164	-24	-24	-00	1824
1-01	1-01	21	-01	-00	-01	0	1-01 13-45	165	165	165	-24	-24	-00	1834
1-01	1-01	22	-01	-00	-01	0	1-01 13-50	166	166	166	-24	-24	-00	1844
1-01	1-01	23	-01	-00	-01	0	1-01 13-55	167	167	167	-24	-24	-00	1854
1-01	1-01	24	-01	-00	-01	0	1-01 14-00	168	168	168	-24	-24	-00	1864
1-01	1-01	25	-01	-00	-01	0	1-01 14-05	169	169	169	-30	-30	-00	1874
1-01	1-01	26	-01	-00	-01	0	1-01 14-10	170	170	170	-30	-30	-00	1884
1-01	1-01	27	-01	-00	-01	0	1-01 14-15	171	171	171	-30	-30	-00	1894
1-01	1-01	28	-01	-00	-01	0	1-01 14-20	172	172	172	-30	-30	-00	1904
1-01	1-01	29	-01	-00	-01	0	1-01 14-25	173	173	173	-30	-30	-00	1914
1-01	1-01	30	-01	-00	-01	0	1-01 14-30	174	174	174	-30	-30	-00	1924
1-01	1-01	31	-01	-00	-01	0	1-01 14-35	175	175	175	-30	-30	-00	1934
1-01	1-01	32	-01	-00	-01	0	1-01 14-40	176	176	176	-30	-30	-00	1944
1-01	1-01	33	-01	-00	-01	0	1-01 14-45	177	177	177	-30	-30	-00	1954
1-01	1-01	34	-01	-00	-01	0	1-01 14-50	178	178	178	-30	-30	-00	1964
1-01	1-01	35	-01	-00	-01	0	1-01 14-55	179	179	179	-30	-30	-00	1974
1-01	1-01	36	-01	-00	-01	0	1-01 15-00	180	180	180	-30	-30	-00	1984
1-01	1-01	37	-01	-00	-01	0	1-01 15-05	181	181	181	-18	-18	-00	1994
1-01	1-01	38	-01	-00	-01	0	1-01 15-10	182	182	182	-37	-37	-00	2004
1-01	1-01	39	-01	-00	-01	0	1-01 15-15	183	183	183	-37	-37	-00	2014

B L A C K & V E A T E M
 FLOOD HYDROGRAPH PACKAGE - MEC-1

1.01	3.20	40	-01	-01	41	1.01	15.20	184	.55	.55	.00	6475.
1.01	3.25	41	-01	-01	46.	1.01	15.25	185	.64	.64	.00	6810.
1.01	3.30	42	-01	-01	50.	1.01	15.30	186	1.56	1.56	.01	6975.
1.01	3.35	43	-01	-01	55.	1.01	15.35	187	2.57	2.56	.01	7209.
1.01	3.40	44	-01	-01	60.	1.01	15.40	188	1.01	1.01	.00	7506.
1.01	3.45	45	-01	-01	65.	1.01	15.45	189	.64	.64	.00	7872.
1.01	3.50	46	-01	-01	69.	1.01	15.50	190	.55	.55	.00	8311.
1.01	3.55	47	-01	-01	74.	1.01	15.55	191	.37	.37	.00	8868.
1.01	4.00	48	-01	-01	79.	1.01	16.00	192	.37	.37	.00	9389.
1.01	4.05	49	-01	-01	84.	1.01	16.05	193	.28	.28	.00	10042.
1.01	4.10	50	-01	-01	89.	1.01	16.10	194	.28	.28	.00	10764.
1.01	4.15	51	-01	-01	93.	1.01	16.15	195	.28	.28	.00	11532.
1.01	4.20	52	-01	-01	98.	1.01	16.20	196	.28	.28	.00	12283.
1.01	4.25	53	-01	-01	102.	1.01	16.25	197	.28	.28	.00	12958.
1.01	4.30	54	-01	-01	107.	1.01	16.30	198	.28	.28	.00	13556.
1.01	4.35	55	-01	-01	111.	1.01	16.35	199	.28	.28	.00	14002.
1.01	4.40	56	-01	-01	116.	1.01	16.40	200	.28	.28	.00	14511.
1.01	4.45	57	-01	-01	120.	1.01	16.45	201	.28	.28	.00	14545.
1.01	4.50	58	-01	-01	124.	1.01	16.50	202	.28	.28	.00	14637.
1.01	4.55	59	-01	-01	129.	1.01	16.55	203	.28	.28	.00	14648.
1.01	5.00	60	-01	-01	133.	1.01	17.00	204	.28	.28	.00	14570.
1.01	5.05	61	-01	-01	137.	1.01	17.05	205	.22	.22	.00	14360.
1.01	5.10	62	-01	-01	141.	1.01	17.10	206	.22	.22	.00	14133.
1.01	5.15	63	-01	-01	144.	1.01	17.15	207	.22	.22	.00	13836.
1.01	5.20	64	-01	-01	146.	1.01	17.20	208	.22	.22	.00	13496.
1.01	5.25	65	-01	-01	152.	1.01	17.25	209	.22	.22	.00	13111.
1.01	5.30	66	-01	-01	156.	1.01	17.30	210	.22	.22	.00	12672.
1.01	5.35	67	-01	-01	159.	1.01	17.35	211	.22	.22	.00	12195.
1.01	5.40	68	-01	-01	153.	1.01	17.40	212	.22	.22	.00	11659.
1.01	5.45	69	-01	-01	166.	1.01	17.45	213	.22	.22	.00	11224.
1.01	5.50	70	-01	-01	169.	1.01	17.50	214	.22	.22	.00	10784.
1.01	5.55	71	-01	-01	172.	1.01	17.55	215	.22	.22	.00	10395.
1.01	6.00	72	-01	-01	176.	1.01	18.00	216	.22	.22	.00	10036.
1.01	6.05	73	-06	-04	180.	1.01	18.05	217	.02	.02	.00	9699.
1.01	6.10	74	-06	-04	184.	1.01	18.10	218	.02	.02	.00	9385.
1.01	6.15	75	-06	-04	191.	1.01	18.15	219	.02	.02	.00	9085.
1.01	6.20	76	-06	-04	200.	1.01	18.20	220	.02	.02	.00	8802.
1.01	6.25	77	-06	-05	211.	1.01	18.25	221	.02	.02	.00	8512.
1.01	6.30	78	-06	-05	225.	1.01	18.30	222	.02	.02	.00	8216.
1.01	6.35	79	-06	-05	243.	1.01	18.35	223	.02	.02	.00	7918.
1.01	6.40	80	-06	-05	266.	1.01	18.40	224	.02	.02	.00	7606.
1.01	6.45	81	-06	-05	293.	1.01	18.45	225	.02	.02	.00	7278.
1.01	6.50	82	-06	-05	326.	1.01	18.50	226	.02	.02	.00	6942.
1.01	6.55	83	-06	-05	343.	1.01	18.55	227	.02	.02	.00	6597.
1.01	7.00	84	-06	-05	405.	1.01	19.00	228	.02	.02	.00	6242.
1.01	7.05	85	-06	-05	450.	1.01	19.05	229	.02	.02	.00	5885.
1.01	7.10	86	-06	-05	498.	1.01	19.10	230	.02	.02	.00	5531.
1.01	7.15	87	-06	-05	548.	1.01	19.15	231	.02	.02	.00	5179.
1.01	7.20	88	-06	-05	595.	1.01	19.20	232	.02	.02	.00	4830.
1.01	7.25	89	-06	-05	651.	1.01	19.25	233	.02	.02	.00	4504.
1.01	7.30	90	-06	-05	704.	1.01	19.30	234	.02	.02	.00	4179.
1.01	7.35	91	-06	-05	755.	1.01	19.35	235	.02	.02	.00	3871.
1.01	7.40	92	-06	-05	806.	1.01	19.40	236	.02	.02	.00	3580.
1.01	7.45	93	-06	-06	856.	1.01	19.45	237	.02	.02	.00	3306.
1.01	7.50	94	-06	-06	904.	1.01	19.50	238	.02	.02	.00	3049.
1.01	7.55	95	-06	-06	950.	1.01	19.55	239	.02	.02	.00	2808.

SUM OF 4 HYDROGRAPHS AT 19 PLAN 1 RTIO 5

	C.	1.	2.	3.	4.	5.	6.	7.	8.	9.	10.	11.	12.
14.	17.	20.	23.	26.	29.	32.	35.	39.	42.				
46.	49.	51.	56.	61.	63.	67.	70.	74.	77.				
81.	84.	87.	91.	94.	97.	100.	103.	106.	109.				
112.	115.	118.	122.	125.	126.	128.	131.	133.	136.				
139.	144.	148.	150.	152.	152.	151.	149.	146.	143.				
316.	355.	395.	435.	474.	512.	549.	585.	620.	653.				
685.	715.	745.	772.	798.	821.	844.	867.	886.	904.				
527.	552.	570.	589.	607.	621.	631.	639.	644.	647.				
1047.	1052.	1060.	1069.	1076.	1083.	1086.	1096.	1102.	1107.				
1111.	1116.	1124.	1129.	1134.	1138.	1143.	1147.	1152.	1156.				
1167.	1165.	1169.	1176.	1179.	1183.	1187.	1192.	1196.	1201.				
1214.	1214.	1214.	1219.	1222.	1225.	1228.	1234.	1234.	1234.				
1505.	1516.	1525.	1537.	1540.	1541.	1541.	1549.	1557.	1563.				
2842.	2867.	2884.	2902.	2926.	2946.	2961.	2976.	2988.	2998.				
4012.	4034.	4052.	4086.	4116.	4141.	4161.	4176.	4188.	4198.				
15825.	15877.	15922.	15962.	15998.	16031.	16051.	16071.	16088.	16102.				
950.	915.	883.	853.	826.	801.	777.	753.	730.	710.				
742.	720.	697.	676.	656.	636.	624.	614.	605.	597.				
590.	582.	572.	564.	560.	561.	557.	553.	549.	545.				
542.	538.	535.	532.	530.	527.	525.	523.	520.	518.				

B L A C K B V E A T C H
 FLOOD HYDROGRAPH PACKAGE - REC-1
 PROJECT 94572 DATE 20 MAR 81 PAGE 369
 PROGRAM M21/02-1V TIME 17:48:24 CASE C2

PEAK 6-HOUR 24-HOUR 72-HOUR TOTAL VOLUME
 CFS 10873. 8463. 2638. 759280.
 563. 240. 75. 21517.
 INCHES 8.64 10.78 10.78
 219.47 273.70 273.70
 4196. 5233. 5233.
 AC-FT 5176. 6455. 6455.
 TBOUS CUP

SUM OF 4 HYDROGRAPHS AT 19 PLAN 1 RTIO 6

	C.	1.	2.	3.	4.	5.	6.	7.	8.	9.	10.	11.	12.
14.	17.	20.	23.	26.	29.	32.	35.	39.	42.				
46.	49.	51.	56.	61.	63.	67.	70.	74.	77.				
81.	84.	87.	91.	94.	97.	100.	103.	106.	109.				
112.	115.	118.	122.	125.	126.	128.	131.	133.	136.				
139.	144.	148.	150.	152.	152.	151.	149.	146.	143.				
316.	355.	395.	435.	474.	512.	549.	585.	620.	653.				
685.	715.	745.	772.	798.	821.	844.	867.	886.	904.				
527.	552.	570.	589.	607.	621.	631.	639.	644.	647.				
1047.	1052.	1060.	1069.	1076.	1083.	1086.	1096.	1102.	1107.				
1111.	1116.	1124.	1129.	1134.	1138.	1143.	1147.	1152.	1156.				
1167.	1165.	1169.	1176.	1179.	1183.	1187.	1192.	1196.	1201.				
1214.	1214.	1214.	1219.	1222.	1225.	1228.	1234.	1234.	1234.				
1505.	1516.	1525.	1537.	1540.	1541.	1541.	1549.	1557.	1563.				
2842.	2867.	2884.	2902.	2926.	2946.	2961.	2976.	2988.	2998.				
4012.	4034.	4052.	4086.	4116.	4141.	4161.	4176.	4188.	4198.				
15825.	15877.	15922.	15962.	15998.	16031.	16051.	16071.	16088.	16102.				
950.	915.	883.	853.	826.	801.	777.	753.	730.	710.				
742.	720.	697.	676.	656.	636.	624.	614.	605.	597.				
590.	582.	572.	564.	560.	561.	557.	553.	549.	545.				
542.	538.	535.	532.	530.	527.	525.	523.	520.	518.				

6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
4729.	5019.	5707.	5779.
6400.	6271.	6735.	7246.
13595.	17695.	19243.	20765.
21765.	26452.	18133.	21560.
32068.	11624.	10763.	15059.
7749.	7322.	6402.	9102.
3484.	3433.	2929.	4685.
1770.	1601.	1476.	2177.
1056.	1011.	949.	1169.
782.	766.	721.	821.
601.	654.	641.	608.
611.	606.	600.	617.

6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
9727.	3024.	3024.	870771.
275.	76.	76.	24659.
9.93	12.35	12.35	12.35
252.24	313.64	313.64	21.64
4823.	5997.	5997.	5997.
5649.	7397.	7397.	7397.

SUR OF 6 HYDROGRAPHS AT		19 PLAN 1		RTIO 7	
C.	C.	C.	C.	C.	C.
0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.
1.	2.	4.	5.	10.	12.
18.	25.	29.	37.	43.	50.
59.	68.	71.	77.	86.	94.
109.	112.	110.	123.	129.	136.
144.	151.	155.	162.	165.	171.
172.	185.	192.	221.	245.	277.
407.	508.	559.	610.	705.	797.
874.	947.	980.	1042.	1071.	1097.
1165.	1263.	1237.	1252.	1267.	1293.
1317.	1330.	1349.	1358.	1366.	1374.
1425.	1425.	1453.	1460.	1468.	1475.
1490.	1504.	1511.	1525.	1532.	1551.
1557.	1569.	1574.	1609.	1648.	1699.
2056.	2211.	2547.	2897.	3059.	3547.
3718.	4079.	4262.	4464.	4993.	5139.
5506.	5642.	6248.	6446.	6913.	7372.
7428.	8174.	8553.	8766.	9043.	9709.
10048.	11156.	11976.	12504.	12039.	13271.
21998.	19688.	18531.	16595.	23207.	23266.
12006.	12274.	11716.	10266.	15019.	14299.
8547.	8087.	7086.	6072.	9683.	8065.
4070.	3768.	3490.	2770.	5184.	4772.
1956.	1810.	1723.	1661.	2364.	2045.
1165.	1121.	1042.	984.	1326.	1214.
847.	831.	811.	787.	657.	608.
735.	728.	715.	700.	776.	753.
681.	678.	672.	669.	698.	689.

SUR OF 6 HYDROGRAPHS AT		19 PLAN 1		RTIO 7	
C.	C.	C.	C.	C.	C.
0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.
1.	2.	4.	5.	10.	12.
18.	25.	29.	37.	43.	50.
59.	68.	71.	77.	86.	94.
109.	112.	110.	123.	129.	136.
144.	151.	155.	162.	165.	171.
172.	185.	192.	221.	245.	277.
407.	508.	559.	610.	705.	797.
874.	947.	980.	1042.	1071.	1097.
1165.	1263.	1237.	1252.	1267.	1293.
1317.	1330.	1349.	1358.	1366.	1374.
1425.	1425.	1453.	1460.	1468.	1475.
1490.	1504.	1511.	1525.	1532.	1551.
1557.	1569.	1574.	1609.	1648.	1699.
2056.	2211.	2547.	2897.	3059.	3547.
3718.	4079.	4262.	4464.	4993.	5139.
5506.	5642.	6248.	6446.	6913.	7372.
7428.	8174.	8553.	8766.	9043.	9709.
10048.	11156.	11976.	12504.	12039.	13271.
21998.	19688.	18531.	16595.	23207.	23266.
12006.	12274.	11716.	10266.	15019.	14299.
8547.	8087.	7086.	6072.	9683.	8065.
4070.	3768.	3490.	2770.	5184.	4772.
1956.	1810.	1723.	1661.	2364.	2045.
1165.	1121.	1042.	984.	1326.	1214.
847.	831.	811.	787.	657.	608.
735.	728.	715.	700.	776.	753.
681.	678.	672.	669.	698.	689.

PEAK 6-HOUR 24-HOUR 72-HOUR TOTAL VOLUME

B L A C K & V E A T C M PROJECT 0657: DATE 20 MAR 81 PAGE 371
 FLOOD HYDROGRAPH PACKAGE - PEG-1 PROGRAM M2YJ02-1V TIME 17:48:24 CASE C2

CFS	23286.	10889.	3384.	974524.
CMS	639.	96.	96.	27595.
INCHES	11.12	13.82	13.82	13.82
MM	282.38	353.61	353.61	353.61
AC-F1	5399.	6712.	6712.	6712.
THOUS CU P	6060.	8279.	8279.	8279.

SUM OF 4 HYDROGRAPHS AT		19 PLAN 1 RTIO 8		TOTAL VOLUME	
C.	C.	C.	C.	C.	C.
25458.	12048.	3744.	1746.	1078264.	
721.	361.	106.	100.	50533.	
	312.30	15.29	15.29	15.29	
	5974.	388.38	388.38	388.38	
	7369.	7426.	7426.	7426.	
	9160.	9160.	9160.	9160.	
21299.	2532.	25948.	25360.	22584.	0.
26781.	16662.	18436.	17712.	15137.	14.
83961.	13204.	11256.	10979.	10256.	17.
5408.	2566.	7248.	6989.	5253.	55.
4355.	3929.	3545.	3947.	2447.	60.
4474.	4355.	3285.	2830.	2457.	110.
4135.	2003.	1886.	1800.	1452.	156.
1277.	1229.	1140.	1077.	904.	194.
551.	913.	890.	860.	829.	399.
811.	796.	785.	777.	782.	351.
733.	746.	743.	737.	733.	923.
					1262.
					1428.
					1558.
					1651.
					1719.
					1726.
					1897.
					3816.
					4015.
					5923.
					8958.
					19069.
					21220.
					14493.
					9859.
					4842.
					2282.
					1330.
					973.
					20.
					27.
					33.

CFS	25458.	12048.	3744.	1078264.
CMS	721.	361.	106.	50533.
INCHES	312.30	15.29	15.29	15.29
MM	5974.	388.38	388.38	388.38
AC-F1	7426.	7426.	7426.	7426.
THOUS CU P	7369.	9160.	9160.	9160.

SUM OF 4 HYDROGRAPHS AT		19 PLAN 1 RTIO 9		TOTAL VOLUME	
C.	C.	C.	C.	C.	C.
0.	0.	0.	0.	0.	0.
1.	1.	1.	1.	1.	1.
2.	2.	2.	2.	2.	2.
5.	5.	5.	5.	5.	5.
8.	8.	8.	8.	8.	8.
17.	17.	17.	17.	17.	17.
16.	16.	16.	16.	16.	16.
27.	27.	27.	27.	27.	27.
33.	33.	33.	33.	33.	33.

STAGE	50F.7C	566.F0	907.50	90F.7C	910.50	917.00	920.90	921.40	922.40
	923.40	924.40	925.40	926.40	927.40	928.40	929.00	930.00	931.00

6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
43325.	23614.	7348.	216750.
12271.	6631.	2028.	59529.
	23.91	31.01	30.01
	67.21	762.28	762.28
	11610.	14575.	14575.
	14321.	17979.	17979.

CEFS	INCHES	MM	AC-FT	THOUS CU M
43325.	12271.			

ROUTING THROUGH STRUCTURE C-2 (PO. I.P. 910314)

HYDROGRAPH ROUTINE

ISTAB	ICOMP	IFCON	ITAPE	JPLY	JPRT	INAME	ISTAGE	LAUTO
20	1	C	C	0	0	1	0	0
			ROUTING DATA					
			IFES	ISAPE	IOPT	IPPF	LSTR	C
			LAG	AMSK	ISK	STPA	ISPRAT	
			1	0	0	0	0	-1
			0.000	0.000	0.000	-930.		

PERIOD	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
PERIOD 74	10880	7105	2031	86690
PERIOD 75	300	205	58	16505
PERIOD 76	735	830	830	21070
PERIOD 77	10659	21070	21070	4029
PERIOD 78	3568	4029	4029	4970
PERIOD 79	4401	4970	4970	

STATION 20, PLAN 1, RATIO 7

PERIOD	SUB-STEP 1	TIME	RATIO
PERIOD 74	SUB-STEP 1	TIME 6.17 HR	
	CONTINUITY BALANCE	-1.107509+00	
PERIOD 75	SUB-STEP 1	TIME 6.25 HR	
	CONTINUITY BALANCE	-1.57936+00	
PERIOD 76	SUB-STEP 1	TIME 6.33 HR	
	CONTINUITY BALANCE	-2.25837+00	
PERIOD 77	SUB-STEP 1	TIME 6.42 HR	
	CONTINUITY BALANCE	-3.317305+00	
PERIOD 78	SUB-STEP 1	TIME 6.50 HR	
	CONTINUITY BALANCE	-4.090223+00	
PERIOD 79	SUB-STEP 1	TIME 6.58 HR	
	CONTINUITY BALANCE	-7.625728+00	
PERIOD 80	SUB-STEP 1	TIME 6.67 HR	
	CONTINUITY BALANCE	-1.169275+01	

END-OF-PERIOD HYDROGRAPH ORDINATES

ORDINATE	OUTFLOW	CONTINUITY BALANCE
0	0	0
1	0	0
2	0	0
3	0	0
4	0	0
5	0	0
6	0	0
7	0	0
8	0	0
9	0	0
10	0	0
11	0	0
12	0	0
13	0	0
14	0	0
15	0	0
16	0	0
17	0	0
18	0	0
19	0	0
20	0	0
21	0	0
22	0	0
23	0	0
24	0	0
25	0	0
26	0	0
27	0	0
28	0	0
29	0	0
30	0	0
31	0	0
32	0	0
33	0	0
34	0	0
35	0	0
36	0	0
37	0	0
38	0	0
39	0	0
40	0	0
41	0	0
42	0	0
43	0	0
44	0	0
45	0	0
46	0	0
47	0	0
48	0	0
49	0	0
50	0	0
51	0	0
52	0	0
53	0	0
54	0	0
55	0	0
56	0	0
57	0	0
58	0	0
59	0	0
60	0	0
61	0	0
62	0	0
63	0	0
64	0	0
65	0	0
66	0	0
67	0	0
68	0	0
69	0	0
70	0	0
71	0	0
72	0	0
73	0	0
74	0	0
75	0	0
76	0	0
77	0	0
78	0	0
79	0	0
80	0	0
81	0	0
82	0	0
83	0	0
84	0	0
85	0	0
86	0	0
87	0	0
88	0	0
89	0	0
90	0	0
91	0	0
92	0	0
93	0	0
94	0	0
95	0	0
96	0	0
97	0	0
98	0	0
99	0	0
100	0	0

ITERATIVE SOLUTION DID NOT CONVERGE

ESTIMATED W.S. ELEV	ITERATIVE SOLUTION DID NOT CONVERGE
120	120
125	125
130	130
135	135
140	140
145	145
150	150
155	155
160	160
165	165
170	170
175	175
180	180
185	185
190	190
195	195
200	200
205	205
210	210
215	215
220	220
225	225
230	230
235	235
240	240
245	245
250	250
255	255
260	260
265	265
270	270
275	275
280	280
285	285
290	290
295	295
300	300
305	305
310	310
315	315
320	320
325	325
330	330
335	335
340	340
345	345
350	350
355	355
360	360
365	365
370	370
375	375
380	380
385	385
390	390
395	395
400	400
405	405
410	410
415	415
420	420
425	425
430	430
435	435
440	440
445	445
450	450
455	455
460	460
465	465
470	470
475	475
480	480
485	485
490	490
495	495
500	500
505	505
510	510
515	515
520	520
525	525
530	530
535	535
540	540
545	545
550	550
555	555
560	560
565	565
570	570
575	575
580	580
585	585
590	590
595	595
600	600
605	605
610	610
615	615
620	620
625	625
630	630
635	635
640	640
645	645
650	650
655	655
660	660
665	665
670	670
675	675
680	680
685	685
690	690
695	695
700	700
705	705
710	710
715	715
720	720
725	725
730	730
735	735
740	740
745	745
750	750
755	755
760	760
765	765
770	770
775	775
780	780
785	785
790	790
795	795
800	800
805	805
810	810
815	815
820	820
825	825
830	830
835	835
840	840
845	845
850	850
855	855
860	860
865	865
870	870
875	875
880	880
885	885
890	890
895	895
900	900
905	905
910	910
915	915
920	920
925	925
930	930
935	935
940	940
945	945
950	950
955	955
960	960
965	965
970	970
975	975
980	980
985	985
990	990
995	995
1000	1000

STATION	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
908.4	8372.	2379.	2379.	65089.
908.5	277.	67.	67.	19399.
908.6	8.55	9.71	9.71	246.75
908.7	217.12	246.75	246.75	4718.
908.8	4152.	4718.	4718.	5820.
908.9	5123.	5820.	5820.	

PEAK OUTFLOW IS 12165. AT TIME 17:07 HOURS

CFS 12165.
 CMS 346.
 INCHES 8.55
 MPH 9.71
 AC-FT 217.12
 TPOUS CU M 4152.

STATION 20, PLAN 1, RATIO 0

PERIOD	SUR-STEP	TIME	CONTINUITY BALANCE
71	1	5.92 HR	-1.033757+00
72	1	6.00 HR	-1.467757+00
73	1	6.08 HR	-1.969779+00
74	1	6.17 HR	-2.644393+00
75	1	6.25 HR	-3.557978+00
76	1	6.33 HR	-4.261579+00
77	1	6.42 HR	-6.402277+00
78	1	6.50 HR	-9.784822+00

END-OF-PERIOD HYDROGRAPH ORDINATES

OUTFLOW	C.
0.	0.
0.	0.
0.	0.
1.	2.
5.	6.
13.	15.
17.	16.
18.	12.
19.	11.
20.	10.
21.	9.
22.	8.
23.	7.
24.	6.
25.	5.
26.	4.
27.	3.
28.	2.
29.	1.
30.	0.
31.	0.

Evaluation of output and iterations within HEC-1 indicates that the results of this program run were not affected by the lack of convergence within the iterations for the routing through Harrison County Dam C-2.

D L A C K E V E A T C M PROJECT 94572 DATE 20 MAR 81 PAGE 303
 FLOOD HYDROGRAPH PACKAGE - MEC-1 PROGRAM M21/02-1V TIME 17:48:26 CASE C2

PEAK FLOW AND STORAGE (END OF PERIOD) SUPMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION	STATION	AREA	PLAN	RATIOS APPLIED TO FLOWS								
				RATIO 1	RATIO 2	RATIO 3	RATIO 4	RATIO 5	RATIO 6	RATIO 7	RATIO 8	RATIO 9
				.15	.20	.25	.30	.35	.40	.45	.50	1.00
HYDROGRAPH AT	1	.32 (.83)	1	519. (14.72)	692. (19.69)	865. (24.50)	1038. (29.39)	1211. (34.29)	1384. (39.19)	1557. (44.09)	1730. (48.99)	3460. (97.98)
ROUTED TO	2	.32 (.83)	1	161. (4.57)	1468. (41.57)	1599. (44.15)	1641. (46.47)	1741. (49.31)	2189. (61.97)	2157. (61.07)	1725. (48.85)	2733. (77.40)
ROUTED TO	3	.32 (.83)	1	136. (3.86)	1121. (31.75)	1237. (35.03)	1332. (37.71)	1440. (40.77)	1694. (47.90)	1598. (45.26)	1331. (37.70)	2045. (57.91)
HYDROGRAPH AT	4	.76 (1.97)	1	959. (27.11)	1277. (36.15)	1596. (45.19)	1915. (54.23)	2234. (63.27)	2552. (72.30)	2873. (81.34)	3192. (90.58)	6383. (180.76)
ROUTED TO	5	.76 (1.97)	1	290. (8.21)	622. (17.61)	4491. (127.76)	4819. (136.45)	5120. (144.97)	5412. (152.25)	5687. (160.47)	6601. (186.93)	5594. (158.42)
ROUTED TO	6	.76 (1.97)	1	271. (7.69)	538. (15.22)	3897. (110.34)	4173. (118.15)	4401. (124.63)	4638. (131.32)	4887. (138.40)	5456. (154.49)	4742. (134.29)
HYDROGRAPH AT	7	1.01 (2.61)	1	1286. (36.43)	1715. (48.57)	2144. (60.72)	2573. (72.86)	3002. (85.00)	3431. (97.16)	3859. (109.29)	4288. (121.43)	8577. (242.86)
ROUTED TO	8	1.01 (2.61)	1	207. (5.86)	402. (11.32)	4312. (122.12)	4547. (127.75)	4794. (135.76)	5520. (156.38)	5300. (150.00)	4660. (131.95)	5192. (147.02)
ROUTED TO	9	1.01 (2.61)	1	200. (5.66)	356. (10.22)	3546. (100.42)	3817. (108.09)	4081. (115.57)	4669. (132.21)	4582. (129.75)	4073. (115.35)	4900. (138.75)
HYDROGRAPH AT	10	2.76 (7.14)	1	2404. (68.09)	3266. (92.78)	4907. (139.48)	4809. (136.18)	5610. (158.87)	6412. (181.57)	7212. (204.26)	8015. (226.96)	16030. (453.92)
4 COMBINED	11	4.84 (12.55)	1	2731. (77.33)	4173. (118.16)	9813. (277.86)	11692. (331.09)	13432. (380.34)	15439. (437.19)	15926. (450.98)	18537. (524.92)	27498. (778.67)
HYDROGRAPH AT	12	.26 (.93)	1	544. (15.96)	751. (21.20)	939. (26.80)	1127. (31.92)	1315. (37.24)	1501. (42.58)	1491. (42.88)	1879. (53.20)	3757. (106.59)
ROUTED TO	13	.26 (.93)	1	199. (5.60)	311. (8.60)	414. (11.79)	1955. (55.37)	2101. (59.51)	2236. (63.32)	2310. (65.41)	2348. (66.48)	2918. (82.63)
ROUTED TO	14	.26	1	128.	183.	241.	880.	978.	1075.	1174.	1257.	1834.

B L A C K B V E A T C H
 FLOOD HYDROGRAPH PACKAGE - MEC-1
 PROJECT 6457: DATE 20 MAR 81 PAGE 395
 PROGRAM #21/02-1V TIME 17:48:24 CASE C2
 PROJECT 6457: DATE 20 MAR 81 PAGE 395
 PROGRAM #21/02-1V TIME 17:48:24 CASE C2

IR	AGE	7:	ATE	IR	AGE
15	0.93	(3.623)	(5.173)	(6.843)	(24.923)
15	0.39	(1.00)	(16.573)	(22.103)	(27.623)
16	1.00	(9.083)	(13.363)	(17.223)	(21.683)
17	0.39	(1.00)	(5.173)	(7.303)	(9.423)
18	0.32	(9.12)	(21.97)	(29.30)	(36.62)
19	0.11	(23.60)	(49.55)	(73.06)	(139.69)
20	0.11	(23.60)	(137.47)	(206.80)	(395.56)

B L A C K B V E A T C H
 FLOOD HYDROGRAPH PACKAGE - MEC-1
 PROJECT 6457: DATE 20 MAR 81 PAGE 395
 PROGRAM #21/02-1V TIME 17:48:24 CASE C2
 PROJECT 6457: DATE 20 MAR 81 PAGE 395
 PROGRAM #21/02-1V TIME 17:48:24 CASE C2

IR	AGE	7:	ATE	IR	AGE
15	0.93	(3.623)	(5.173)	(6.843)	(24.923)
15	0.39	(1.00)	(16.573)	(22.103)	(27.623)
16	1.00	(9.083)	(13.363)	(17.223)	(21.683)
17	0.39	(1.00)	(5.173)	(7.303)	(9.423)
18	0.32	(9.12)	(21.97)	(29.30)	(36.62)
19	0.11	(23.60)	(49.55)	(73.06)	(139.69)
20	0.11	(23.60)	(137.47)	(206.80)	(395.56)

SUPPLY OF DAM SAFETY ANALYSIS

PROJECT 6457: DATE 20 MAR 81 PAGE 395
 PROGRAM R21702-IV TIME 17:48:24 CASE C2

BLACK RIVER TCM
 FLOOD HYDROGRAPH PACKAGE - NEC-1

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1	ELEVATION STORAGE OUTFLOW	INITIAL VALUE	SPILLWAY CREST	TOP OF DAM	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
RATIO CF PRI	MAXIMUM RESERVOIR W.S.ELEV	80.00	80.00	86.80	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
.15	86.12	19.	19.	65.	.60	59.	161.	.00	16.17	.00
.20	87.02	0.	0.	268.	.22	67.	1468.	.35	16.83	15.92
.25	87.37				.37	76.	1560.	.48	16.62	15.75
.30	87.53				.57	71.	1631.	.52	16.54	15.67
.35	87.63				.83	72.	1732.	.58	16.48	15.58
.40	87.35				.55	69.	2203.	.71	16.12	15.27
.45	86.91				.37	66.	2157.	.37	15.87	14.67
.50	86.95				.35	66.	1710.	.42	15.29	14.33
1.00	87.11				.37	67.	2733.	.52	15.83	12.58

PLAN 1	STATION	3	RATIO	MAXIMUM FLOW,CFS	MAXIMUM STAGE,FT	TIME HOURS
.15			.15	136.	64.3	16.83
.20			.20	1821.	71.1	16.92
.25			.25	1237.	71.4	16.75
.30			.30	1332.	71.7	16.67
.35			.35	1440.	72.0	16.58
.40			.40	1694.	72.6	16.53
.45			.45	1588.	72.4	15.83
.50			.50	1331.	71.7	15.62
1.00			1.00	2045.	73.4	16.08

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1		INITIAL VALUE		SPILLWAY CREST		TOP OF DAM	
ELEVATION STORAGE OUTFLOW		112.00 93. 0.		112.00 93. 0.		118.70 214. 780.	
RATIO OF PPF	MAXIMUM RESERVOIR M.S.ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
.15	117.44	.00	186.	290.	.00	16.67	.00
.20	118.35	.00	207.	622.	.00	16.33	.00
.25	119.03	.33	221.	4543.	.44	16.96	16.00
.30	119.38	.68	226.	4872.	.56	16.81	15.83
.35	119.60	.90	236.	5123.	.66	16.75	15.75
.40	119.72	1.02	236.	5412.	.67	16.67	15.67
.45	119.78	1.02	236.	5667.	.71	16.58	15.58
.50	118.74	.04	215.	6001.	.31	16.00	15.00
1.00	118.99	.20	220.	5594.	.54	14.00	13.00

PLAN 1 STATION 6

RATIO	MAXIMUM FLOW-CFS	MAXIMUM STAGE-FT	TIME HOURS
.15	271.	91.0	17.42
.20	338.	92.1	16.67
.25	3897.	97.6	17.08
.30	4173.	97.9	16.92
.35	4401.	98.1	16.83
.40	4638.	98.3	16.75
.45	4887.	98.5	16.67
.50	5456.	99.1	16.08
1.00	4742.	98.4	16.25

SUMMARY OF DAM SAFETY ANALYSIS

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1	ELEVATION STORAGE	INITIAL VALUE	SPILLWAY CREST	TOP OF DAM
	126.00	122.00	128.00	129.10
	0.00	0.00	0.00	378.00
	0.00	0.00	0.00	498.00

RATIO OF PMF	MAXIMUM RESERVOIR W.S. ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
.15	127.92	.60	276.	207.	.00	18.25	.00
.20	128.78	.60	306.	452.	.00	17.33	.00
.25	129.55	.65	334.	4313.	.65	17.08	16.08
.30	129.98	.89	350.	4547.	.77	16.83	15.83
.35	130.22	1.12	358.	4794.	.85	16.67	15.67
.40	129.95	.85	348.	5320.	1.00	16.25	15.25
.45	129.41	.31	329.	5300.	.71	15.83	14.83
.50	129.48	.38	331.	4660.	.73	15.30	14.30
1.00	129.67	.57	338.	5192.	.83	16.17	12.67

PLAN 1 STATION 9

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
.15	260.	100.1	18.50
.20	396.	101.0	17.75
.25	3546.	106.2	17.25
.30	3817.	106.5	17.00
.35	4081.	106.7	16.83
.40	4669.	107.2	16.42
.45	4562.	107.1	16.08
.50	4073.	106.7	16.00
1.00	4900.	107.4	16.42

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1	ELEVATION STORAGE OUTFLOW	INITIAL VALUE	SPILLWAY CREST	TOP OF DAM
		95.00	95.00	101.30
		25.	25.	88.
		0.	0.	478.

RATIO OF PMF	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
.15	.00	88.	198.	.00	16.17	.00
.20	.00	76.	311.	.00	16.08	.00
.25	.00	83.	418.	.00	16.08	.00
.30	.15	96.	1582.	.35	16.81	15.92
.35	.44	94.	2131.	.48	16.75	15.83
.40	.66	97.	2276.	.54	16.67	15.75
.45	.83	99.	2377.	.60	16.60	15.67
.50	1.01	102.	2419.	.62	16.62	15.67
1.00	.18	90.	2018.	.50	15.92	13.58

PLAN 1 STATION 14

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TYPE HOURS
.15	128.	84.4	16.00
.20	183.	85.0	17.67
.25	241.	85.6	17.42
.30	560.	87.3	17.00
.35	978.	87.5	16.92
.40	1075.	87.7	16.83
.45	1174.	88.0	16.83
.50	1257.	88.2	16.83
1.00	1834.	89.0	16.25

SUPMARY OF DAM SAFETY ANALYSIS

PLAN 1		ELEVATION STORAGE	INITIAL VALUE	SPILLWAY CREST	TOP OF DAM		
		OUTFLOW	94.00	94.00	101.00		
			27.	27.	89.		
			0.	0.	1048.		
RATIO CF P#1	MAXIMUM RESERVOIR U.S.ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TYPE OF FAILURE HOURS
.15	98.90	.00	68.	321.	.00	16.08	.00
.20	99.40	.00	73.	471.	.00	16.00	.00
.25	99.84	.00	78.	601.	.00	16.00	.00
.30	100.27	.00	82.	760.	.00	16.00	.00
.35	100.66	.00	86.	917.	.00	16.00	.00
.40	101.04	.04	89.	1586.	.17	16.92	15.92
.45	101.26	.26	91.	1649.	.33	16.83	15.83
.50	101.46	.46	93.	1690.	.37	16.83	15.83
1.00	102.32	1.32	108.	3510.	.71	15.90	15.58

PLAN 1 STATION 17

RATIO	MAXIMUM FLOW-CFS	MAXIMUM STAGE-FT	TYPE HOURS
.15	183.	86.5	17.00
.20	238.	87.1	16.83
.25	333.	87.7	16.67
.30	428.	88.1	16.58
.35	534.	88.3	16.50
.40	1026.	89.2	17.08
.45	1114.	89.3	17.00
.50	1166.	89.5	17.00
1.00	2024.	91.0	16.67

SUPMARY OF DAM SAFETY ANALYSIS

PLAN 1	ELEVATION STORAGE OUTFLOW	INITIAL VALUE	SPILLWAY CREST	TOP OF DAM
		976.30	906.50	928.50
		424.	424.	3963.
		0.	0.	11791.

RATIO OF PPF	MAXIMUM RESERVOIR W.S.ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TYPE OF FAILURE	TIME OF FAILURE HOURS
.15	920.11	.00	2030.	360.	.00	24.50	.00
.20	922.64	.00	2466.	1792.	.00	19.50	.00
.25	925.14	.00	2973.	5298.	.00	18.42	.00
.30	926.33	.00	3258.	7437.	.00	18.02	.00
.35	927.22	.00	3503.	9368.	.00	17.83	.00
.40	927.88	.00	3789.	10880.	.00	17.75	.00
.45	928.48	.18	4037.	12165.	1.08	17.67	.00
.50	928.99	.69	4252.	13365.	2.08	17.67	.00
1.00	931.59	3.29	5338.	30810.	6.83	16.83	.00

ATE
LMED
— 8