

AD-A106 623

PRC CONSOER TOWNSEND INC ST LOUIS MO
NATIONAL DAM SAFETY PROGRAM. DR. HENSON LAKE DAM (MO 31570), MI--ETC(U)
SEP 80 W & SWIFRIN


F/G 13/13

DACW43-80-C-0094

NL

UNCLASSIFIED

For 2
Access



AD A106623

LEVEL II

①

MISSOURI - KANSAS CITY RIVER BASIN

DR. HENSON LAKE DAM
GASCONADE COUNTY, MISSOURI
MO. 31570

DTIC
ELECTE
OCT 0 1 1981
S D

**PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM**

FILE COPY



United States Army
Corps of Engineers

... Serving the Army
... Serving the Nation

St. Louis District

PREPARED BY: U. S. ARMY ENGINEER DISTRICT, ST. LOUIS

FOR: STATE OF MISSOURI

This document has been approved
for public release and sale; its
distribution is unlimited.


SEPTEMBER, 1980

81 10 29 055

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO. <u>AD-A106623</u>	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Dam Inspection Report National Dam Safety Program Dr. Henson Lake Dam (MO 31570) Gasconade County, Missouri		5. TYPE OF REPORT & PERIOD COVERED <u>Final Report</u>
7. AUTHOR(s) <u>Consoer, Townsend and Associates, Ltd.</u> <u>10/1/80 - 1/1/81</u>	6. PERFORMING ORG. REPORT NUMBER	
8. CONTRACT OR GRANT NUMBER(s) <u>151 DACW43-80-C-0094</u>		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS <u>11</u> <u>121964</u>
9. PERFORMING ORGANIZATION NAME AND ADDRESS U.S. Army Engineer District, St. Louis Dam Inventory and Inspection Section, LMSED-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101		12. REPORT DATE <u>September 1980</u>
11. CONTROLLING OFFICE NAME AND ADDRESS U.S. Army Engineer District, St. Louis Dam Inventory and Inspection Section, LMSED-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101		13. NUMBER OF PAGES <u>Approximately 91</u>
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) <u>(C) National Dam Safety Program. Dr. Henson Lake Dam (MO 31570), Missouri - Kansas City River Basin, Gasconade County, Missouri. Phase I Inspection Report.</u>		15. SECURITY CLASS. (of this report) <u>UNCLASSIFIED</u>
16. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report) Approved for release; distribution unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dam Safety, Lake, Dam Inspection, Private Dams		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report was prepared under the National Program of Inspection of Non-Federal Dams. This report assesses the general condition of the dam with respect to safety, based on available data and on visual inspection, to determine if the dam poses hazards to human life or property.		

Cont'd on Pg. II

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)



SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

INSTRUCTIONS FOR PREPARATION OF REPORT DOCUMENTATION PAGE

RESPONSIBILITY. The controlling DoD office will be responsible for completion of the Report Documentation Page, DD Form 1473, in all technical reports prepared by or for DoD organizations.

CLASSIFICATION. Since this Report Documentation Page, DD Form 1473, is used in preparing announcements, bibliographies, and data, it should be unclassified if possible. If a classification is required, identify the classified items on the page by the appropriate symbol.

COMPLETION GUIDE

General. Make Blocks 1, 4, 5, 6, 7, 11, 13, 15, and 16 agree with the corresponding information on the report cover. Leave Blocks 2 and 3 blank.

Block 1. Report Number. Enter the unique alphanumeric report number shown on the cover.

Block 2. Government Accession No. Leave Blank. This space is for use by the Defense Documentation Center.

Block 3. Recipient's Catalog Number. Leave blank. This space is for the use of the report recipient to assist in future retrieval of the document.

Block 4. Title and Subtitle. Enter the title in all capital letters exactly as it appears on the publication. Titles should be unclassified whenever possible. Write out the English equivalent for Greek letters and mathematical symbols in the title (see "Abstracting Scientific and Technical Reports of Defense-sponsored RDT/E," AD-667 000). If the report has a subtitle, this subtitle should follow the main title, be separated by a comma or semicolon if appropriate, and be initially capitalized. If a publication has a title in a foreign language, translate the title into English and follow the English translation with the title in the original language. Make every effort to simplify the title before publication.

Block 5. Type of Report and Period Covered. Indicate here whether report is interim, final, etc., and, if applicable, inclusive dates of period covered, such as the life of a contract covered in a final contractor report.

Block 6. Performing Organization Report Number. Only numbers other than the official report number shown in Block 1, such as series numbers for in-house reports or a contractor/grantee number assigned by him, will be placed in this space. If no such numbers are used, leave this space blank.

Block 7. Author(s). Include corresponding information from the report cover. Give the name(s) of the author(s) in conventional order (for example, John R. Doe or, if author prefers, J. Robert Doe). In addition, list the affiliation of an author if it differs from that of the performing organization.

Block 8. Contract or Grant Number(s). For a contractor or grantee report, enter the complete contract or grant number(s) under which the work reported was accomplished. Leave blank in in-house reports.

Block 9. Performing Organization Name and Address. For in-house reports enter the name and address, including office symbol, of the performing activity. For contractor or grantee reports enter the name and address of the contractor or grantee who prepared the report and identify the appropriate corporate division, school, laboratory, etc., of the author. List city, state, and ZIP Code.

Block 10. Program Element, Project, Task Area, and Work/Unit Numbers. Enter here the number code from the applicable Department of Defense form, such as the DD Form 1498, "Research and Technology Work Unit Summary" or the DD Form 1634, "Research and Development Planning Summary," which identifies the program element, project, task area, and work unit or equivalent under which the work was authorized.

Block 11. Controlling Office Name and Address. Enter the full, official name and address, including office symbol, of the controlling office. (Equates to funding/sponsoring agency. For definition see DoD Directive 5200.20, "Distribution Statements on Technical Documents.")

Block 12. Report Date. Enter here the day, month, and year or month and year as shown on the cover.

Block 13. Number of Pages. Enter the total number of pages.

Block 14. Monitoring Agency Name and Address (if different from Controlling Office). For use when the controlling or funding office does not directly administer a project, contract, or grant, but delegates the administrative responsibility to another organization.

Blocks 15 & 15a. Security Classification of the Report: Declassification/Downgrading Schedule of the Report. Enter in 15 the highest classification of the report. If appropriate, enter in 15a the declassification/downgrading schedule of the report, using the abbreviations for declassification/downgrading schedules listed in paragraph 4-207 of DoD 5200.1-R.

Block 16. Distribution Statement of the Report. Insert here the applicable distribution statement of the report from DoD Directive 5200.20, "Distribution Statements on Technical Documents."

Block 17. Distribution Statement (of the abstract entered in Block 20, if different from the distribution statement of the report). Insert here the applicable distribution statement of the abstract from DoD Directive 5200.20, "Distribution Statements on Technical Documents."

Block 18. Supplementary Notes. Enter information not included elsewhere but useful, such as: Prepared in cooperation with . . . Translation of (or by) . . . Presented at conference of . . . To be published in . . .

Block 19. Key Words. Select terms or short phrases that identify the principal subjects covered in the report, and are sufficiently specific and precise to be used as index entries for cataloging, conforming to standard terminology. The DoD "Thesaurus of Engineering and Scientific Terms" (TEST), AD-672 000, can be helpful.

Block 20: Abstract. The abstract should be a brief (not to exceed 200 words) factual summary of the most significant information contained in the report. If possible, the abstract of a classified report should be unclassified and the abstract to an unclassified report should consist of publicly-releasable information. If the report contains a significant bibliography or literature survey, mention it. For information on preparing abstracts see "Abstracting Scientific and Technical Reports of Defense-Sponsored RDT&E," AD-667 000.



DEPARTMENT OF THE ARMY
ST. LOUIS DISTRICT, CORPS OF ENGINEERS
210 TUCKER BOULEVARD, NORTH
ST. LOUIS, MISSOURI 63101

REPLY TO
ATTENTION OF

SUBJECT: Dr. Hensen Lake Dam (Mo. 31570) Phase I Inspection Report

This report presents the results of field inspection and evaluation of the Dr. Hensen Lake Dam (Mo. 31570).

It was prepared under the National Program of Inspection of Non-Federal Dams.

SUBMITTED BY: _____
Chief, Engineering Division

Date

APPROVED BY: _____
Colonel, CE, District Engineer

Date

Accession For	
NTIS GRA&I	<input checked="checked" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By _____	
Distribution/	
Availability Codes	
Dist	Avail and/or Special
A	

DR. HENSON LAKE DAM
GASCONADE COUNTY, MISSOURI

MISSOURI INVENTORY NO. 31570

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

PREPARED BY
CONSOER, TOWNSEND AND ASSOCIATES, LTD.
ST. LOUIS, MISSOURI
AND
PRC ENGINEERING CONSULTANTS, INC.
ENGLEWOOD, COLORADO
A JOINT VENTURE

UNDER DIRECTION OF
ST. LOUIS DISTRICT, CORPS OF ENGINEERS
FOR
GOVERNOR OF MISSOURI

SEPTEMBER 1980

Cont'd

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

Name of Dam: Dr. Henson Lake Dam, Missouri Inv. No. 31570
State Located: Missouri
County Located: Gasconade
Stream: An unnamed tributary of Frene Creek
Date of Inspection: April 23, 1980

Assessment of General Condition

Dr. Henson Lake Dam was inspected by the engineering firms of Consoer, Townsend and Associates, Ltd. and PRC Engineering Consultants, Inc. (A Joint Venture) of St. Louis, Missouri according to the U. S. Army Corps of Engineers "Engineer Regulation No. 1110-2-106" and additional guidelines furnished by the St. Louis District of the Corps of Engineers. Based upon the criteria in the guidelines, the dam is in the high hazard potential classification, which means that urban development with more than a small number of habitable structures could be effected in the event of failure of the dam. Within the estimated damage zone of one mile downstream of the dam are three dwellings, a state highway (Hwy. 100), a park and a campground which may be subjected to flooding, with possible damage and/or destruction, and possible loss of life. Dr. Henson Lake Dam is in the small size classification since it is less than 40 feet and more than 25 feet high.

File


con'td

The dam appears to be in poor condition. Our inspection and evaluation indicates that the spillway of Dr. Henson Lake Dam does not meet the criteria set forth in the guidelines, for a dam having the above size and hazard potential. Dr. Henson Lake Dam being a small size dam with a high hazard potential is required by the guidelines to pass from one-half of the Probable Maximum Flood to the Probable Maximum Flood without overtopping. Considering the number of inhabited dwellings located downstream of the dam, the PMF is considered the appropriate spillway design flood for Dr. Henson Lake Dam. It was determined that the reservoir/spillway system can accommodate approximately 50 percent of the Probable Maximum Flood without overtopping the dam. Our evaluation also indicates that the reservoir/spillway system can accommodate the one-percent chance flood (100-year flood) without overtopping the dam.

The Probable Maximum Flood is defined as the flood discharge that may be expected from the most severe combination of critical meteorological and hydrologic conditions that are reasonably possible in the region.

Other deficiencies noted by the inspection team were the erosion on the upstream slope due to wave action and on the downstream slope due to surface erosion, a scarp on the upstream slope, possible seepage downstream of the toe of the dam, trees on the downstream and upstream slopes, obstructions in the spillway channel; some unprotected areas on the side slopes of the spillway channel, burrowing animals activities in the embankment, a need for periodic inspection by a qualified engineer and a lack of maintenance schedule. The lack of seepage and stability analyses on record is also a deficiency that should be corrected.

It is recommended that the owner take action to correct
or control the deficiencies described above.



Walter G. Shifrin, P.E.





Overview of Dr. Henson Lake Dam

NATIONAL DAM SAFETY PROGRAM

DR. HENSON LAKE DAM, I.D. No. 31570

TABLE OF CONTENTS

<u>Sect. No.</u>	<u>Title</u>	<u>Page</u>
SECTION 1	PROJECT INFORMATION	1
	1.1 General	1
	1.2 Description of Project	3
	1.3 Pertinent Data	7
SECTION 2	ENGINEERING DATA	9
	2.1 Design	9
	2.2 Construction	9
	2.3 Operation	9
	2.4 Evaluation	9
SECTION 3	VISUAL INSPECTION	11
	3.1 Findings	11
	3.2 Evaluation	17

TABLE OF CONTENTS

(Continued)

<u>Sect. No.</u>	<u>Title</u>	<u>Page</u>
SECTION 4	OPERATION PROCEDURES	19
	4.1 Procedures	19
	4.2 Maintenance of Dam	19
	4.3 Maintenance of Operating Facilities	19
	4.4 Description of Any Warning System in Effect	19
	4.5 Evaluation	20
SECTION 5	HYDRAULIC/HYDROLOGIC	21
	5.1 Evaluation of Features	21
SECTION 6	STRUCTURAL STABILITY.	26
	6.1 Evaluation of Structural Stability.	26
SECTION 7	ASSESSMENT/REMEDIAL MEASURES.	28
	7.1 Dam Assessment	28
	7.2 Remedial Measures.	31

TABLE OF CONTENTS

(Continued)

LIST OF PLATES

	<u>Plate No.</u>
LOCATION MAP	1
PLAN, ELEVATION AND SECTION OF DAM AND SPILLWAY PROFILE	2
GEOLOGIC MAPS.	3-4
SEISMIC ZONE MAP	5

APPENDICES

APPENDIX A - PHOTOGRAPHS

APPENDIX B - HYDROLOGIC AND HYDRAULIC COMPUTATIONS

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

DR. HENSON LAKE DAM, Missouri Inv. No. 31570

SECTION 1: PROJECT INFORMATION

1.1 General

a. Authority

The Dam Inspection Act, Public Law 92-367 of August, 1972, authorizes the Secretary of the Army, through the Corps of Engineers, to initiate a national program of dam inspections. Inspection for Dr. Henson Lake Dam was carried out under Contract DACW 43-80-C-0094 between the Department of the Army, St. Louis District, Corps of Engineers, and the engineering firms of Consoer, Townsend & Associates, Ltd., and PRC Engineering Consultants, Inc. (A Joint Venture), of St. Louis, Missouri.

b. Purpose of Inspection

The visual inspection of Dr. Henson Lake Dam was made on April 23, 1980. The purpose of the inspection was to make a general assessment as to the structural integrity and operational adequacy of the dam embankment and its appurtenant structures.

c. Scope of Report

This report summarizes available pertinent data relating to the project, presents a summary of visual observations made during the field inspection, presents an assessment of hydrologic and hydraulic conditions at the site, presents an assessment of the structural adequacy of the various project features and assesses the general condition of the dam with respect to safety.

Subsurface investigations, laboratory testing and detailed analyses were not within the scope of this study. No warranty as to the absolute safety of the project features is implied by the conclusions presented in this report.

It should be noted that in this report reference to left or right abutments is viewed as looking downstream. Where left abutment or left side of the dam is used in this report, this also refers to the north abutment or side, and right to the south abutment or side.

d. Evaluation Criteria

The inspection and evaluation of the dam is performed in accordance with the U.S. Army Corps of Engineers "Engineer Regulation No. 1110-2-106" and additional guidelines furnished by the St. Louis District office of the Corps of Engineers for Phase 1 Dam Inspection.

Description of the Project

a. Description of Dam and Appurtenances

The following description is based upon observations and measurements made during the visual inspection. No design or as-built drawings were available for the dam or appurtenant structures.

The dam is an earthfill structure between earth abutments. The main portion of the dam has a crest width of 9 feet and crest length of 300 feet which runs between the spillway and the left abutment. At the left abutment, the crest extends for approximately another 100 feet. This section is approximately perpendicular to the main section in the direction of the reservoir. The main section has a slight curvature in the alignment, convex towards the downstream. The crest elevation is at approximately 575 feet above mean sea level (MSL). The upstream slope was measured to be 1 vertical to 1 horizontal (1V to 1H) from the crest to the water surface. The downstream slope was measured to be 1V to 1H. The maximum height of the embankment was measured to be 29 feet. The right half of the embankment was only 15-foot high. This portion of the embankment appeared to be placed upon a natural shelf of the right abutment. No riprap protection was provided on the upstream slope.

Dr. Henson Lake Dam has only one spillway and the spillway is located just to the right of the right abutment. It functions as an open channel conveying the flow past the toe of embankment to a vertical rock wall face, about 10 feet in height over which the flow spills to the downstream channel below. As the flow moves over the crest at the spillway inlet, it enters a trapezoidal channel having a 24 foot top

width and a 10 foot bottom width; the side slopes vary from 1V to 2.25H to 1V to 1.14H and the slope of the invert is about 1.79%. The channel is well defined and its centerline is almost perpendicular to the axis of the dam at its beginning and for the first 70 feet, after which the centerline is sharply curved to the left; it is immediately after this curve that the flow spills over the rock wall face. It is fairly evident that the spillway invert is close to bedrock.

There are no low-level drains or controlled outlet works provided for this dam.

b. Location

Dr. Henson Lake Dam had no name prior to the visual inspection and has now been named after its present owner. It is located in Gasconade County in the state of Missouri, across an unnamed tributary to Frene Creek which is a tributary to the Missouri River. The damsite is slightly west of the community of Hermann on the banks of the Missouri River, and can be found on the 7.5 minute series of the Hermann, Missouri Quadrangle in Section 35, Range 5 West, Township 46 North.

c. Size Classification

According to the "Recommended Guidelines for Safety Inspection of Dams" by the U.S. Department of the Army, Office of the Chief Engineer, the dam is classified in the dam-size category as being "small" since its height is less than 40 feet and more than 25 feet. The dam falls below the "small" size classification by storage criteria, since its storage is less than 50 acre-feet. The overall size classification is

determined by the larger of the two sizes as determined by storage and the height of the dam. The overall size classification is accordingly "small".

d. Hazard Classification

The dam has been classified as having a "high" hazard potential in the National Inventory of Dams, on the basis that in the event of failure of the dam or its appurtenances, excessive damage could occur to downstream property, together with the possibility of the loss of life. Our findings concur with this classification. Within the estimated damage zone, extending one mile downstream of the dam, are three dwellings, a state highway, a park and a campground.

e. Ownership

Dr. Henson Lake Dam is owned privately by Dr. and Mrs. Robert Henson. The mailing address is Dr. and Mrs. Robert Henson, Route 1, Box 308, Hermann, Missouri, 65041.

f. Purpose of Dam

The purpose of the dam is to impound water for recreational use as a private lake.

g. Design and Construction History

According to the owner, Dr. Robert Henson, the dam was built in 1953 by Mr. Amel Ensing of Hermann, Missouri. The original owner of the dam and Mr. Ensing are deceased. It is very doubtful if there are any plans or specifications for the dam.

The northwest end of the lake was deepened about five years ago. The excavated material was used for the fill for a nursing home in Hermann, Missouri.

h. Normal Operational Procedures

The dam is used to impound water for recreational use. Normal procedure is to allow the lake level to remain as full as possible with the water level being controlled by rainfall, runoff, evaporation, and elevation of the spillway crest.

1.3 Pertinent Data

a. Drainage Area (square miles):	0.089
b. Discharge at Damsite	
Estimated experienced maximum flood (cfs):	20
Estimated ungated spillway capacity with reservoir at top of dam elevation (cfs):	446
c. Elevation (Feet above MSL)	
Top of dam (minimum):	575
Spillway crest:	570.6
Normal Pool:	570.6
Maximum Experienced Pool:	571.3
Observed Pool:	570.6
d. Reservoir	
Length of pool with water surface at top of dam elevation (feet):	700
e. Storage (Acre-Feet)	
Top of dam (minimum):	16
Spillway crest:	5
Normal Pool:	5
Maximum Experienced Pool:	6+
Observed Pool:	5
f. Reservoir Surfaces (Acres)	
Top of dam (minimum):	3.5
Spillway crest:	2
Normal Pool:	2
Maximum Experienced Pool:	2+
Observed Pool:	2

g. Dam

Type:	Earthfill
Length:	400 feet
Structural Height:	29 feet
Hydraulic Height:	29 feet
Top width:	9 feet
Side slopes:	
Downstream	1V to 1H (measured)
Upstream	1V to 1H (measured)
Zoning:	Unknown
Impervious core:	Unknown
Cutoff:	Unknown
Grout curtain:	Unknown

h. Diversion and Regulating Tunnel None

i. Spillway

Type:	Trapezoidal open channel, uncontrolled
Length of crest:	10 feet
Crest Elevation (feet above MSL):	570.6

j. Regulating Outlets None

SECTION 2: ENGINEERING DATA

2.1 Design

No design drawings or data are available for the dam.

2.2 Construction

The dam was built by Mr. Amel Ensing (deceased) of Hermann, Missouri in 1953. No construction records or data are available relative to the construction of the dam.

2.3 Operation

No operation records are available for the dam.

2.4 Evaluation

a. Availability

No design drawings, design computations, construction data, or operational data are available.

In addition, no pertinent data were available for review of hydrology, spillway capacity, flood routing through the reservoir, outlet capacity, slope stability, seepage analysis, or foundation conditions.

b. Adequacy

The lack of engineering data did not allow for a definitive review and evaluation. Therefore, the adequacy of this dam could not be assessed from the standpoint of reviewing and evaluating design, operation and construction data, but is based primarily on visual inspection, past performance history, and sound engineering judgement.

Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available, which is considered a deficiency. These seepage and stability analyses should be performed for appropriate loading conditions (including earthquake loads) and made a matter of record.

c. Validity

No valid engineering data are available.

SECTION 3: VISUAL INSPECTION

3.1 Findings

a. General

A visual inspection of the Dr. Henson Lake Dam was made on April 23, 1980. The following persons were present during the inspection:

<u>Name</u>	<u>Affiliation</u>	<u>Disciplines</u>
Dr. M.A. Samad	PRC Engineering Consultants, Inc.	Project Engineer, Hydraulics and Hydrology
Mark R. Haynes	PRC Engineering Consultants, Inc.	Soils and Mechanical
Robert G. McLaughlin	PRC Engineering Consultants, Inc.	Civil
Razi Quraishi	PRC Engineering Consultants, Inc.	Geology
John Lauth	Consoer, Townsend & Assoc., Ltd.	Civil and Structural

Specific observations are discussed below.

b. Dam

The dam crest supports a good growth of vegetative cover which appears to provide adequate protection against surface erosion. A few small depressions were observed near the center of the dam which appeared to be due to vehicular traffic and were not attributed to instability of the embankment. Some small 2 to 3 inch deep holes were observed which appeared to be due to livestock activity on the crest. There was no evidence of significant settlement or cracking on the crest. No significant deviations in horizontal or vertical alignment were apparent. There was no evidence observed indicating that the dam has ever been overtopped.

The upstream slope has no riprap protection. Considerable erosion has occurred above the water surface due to wave action. Scarps up to 12 inches high were observed above the water surface in which the slope was near vertical. One 6-foot wide scarp extending from the water surface to the crest was observed near the center of the dam. The scarp appears to have stabilized and was due to a past instability. The slope appeared to be adequately protected from surface erosion by an unmaintained vegetative cover. Three large trees and some small saplings were growing on the slope. Evidence of burrowing animals were observed on the slope. A few burrows approximately 3 to 4 inches in diameter were observed. No depressions, bulges or cracks which would indicate an instability in the embankment were apparent on the slope.

The downstream slope has a heavy unmaintained vegetative cover which appears to provide adequate protection against surface erosion. Nevertheless, some erosion gullies were observed which were apparently due to past erosion. Some

trees were observed growing on the slope. One area of standing water was observed downstream of the toe of the dam. It was undetermined whether the standing water was due to seepage through the embankment or foundation or some other source. No measurable seepage was observed. Due to the heavy vegetative cover, a comprehensive inspection of the slope was hampered. No depressions or bulges which would indicate an instability of the slope were apparent.

Both abutments appeared to be stable. The left abutment supported a gravel access road which runs nearly perpendicular to the embankment. The right abutment supported the spillway. Rock outcrops were observed on the right abutment in the spillway channel. No erosion or instabilities which would affect the safety or stability of the dam were apparent on either of the abutments. No seepage was observed along either of the embankment/abutment contacts.

c. Project Geology and Soils

(1) Geology

The damsite is located on an unnamed tributary of the Frene Creek in the Salem Plateau section of the Ozark Plateaus Physiographic Province. Deep dissection of topography by major streams is one of the important characteristics of the Salem Plateau section. There is a wide distribution of dolomites and limestones in the Salem Plateau. Cuesta-form topography is exhibited in this plateau section consisting of two major escarpments, namely the Crystal Escarpment and Burlington Escarpment. Deep dissection in dolomites and limestones is a major factor in the development of many springs in this area. The topography at the damsite vicinity is hilly with U to V shaped valleys. Elevation ranges from

900 feet M.S.L. (nearly 3.5 miles south of the damsite) to 570 feet M.S.L. at the damsite. The reservoir slopes are generally 15° to 25° from horizontal. The reservoir appears to be water tight. Localized erosional gullies were observed near the northern rim of the reservoir. These localized erosional gullies are not detrimental to the stability of the reservoir banks. The area at the damsite is covered with slope wash deposits of glacial-fluvial origin and loess, consisting of reddish-brown, silty clay, with some fine sand. The inlet and outlet areas of the unnamed tributary of the Frene Creek contain Quaternary alluvium. Outcrops of Ordovician, moderately weathered, hard Dolomitic rocks, interbedded with moderately weathered, hard, sandstone and shales with a dip of 5° towards the west and a strike of N-S are exposed as the spillway cut and the downstream channel of the spillway. The areal bedrock geology beneath the slope wash deposits as shown on the Geologic map of Missouri (1979), Plate 3 consists of Pennsylvanian rocks undifferentiated, Ordovician St. Peters sandstone and Dolomitic rocks.

No faults have been identified in the vicinity of the damsite. The closest trace of a fault to the damsite is the Cuba Fault, nearly 25 miles south of the damsite. The Cuba Fault had its last movement in post-Pennsylvanian time. This fault appears to have no effect on the damsite.

Dr. Henson Lake Dam consists of an homogeneous earthfill embankment and a spillway located at the right end of the embankment. No boring logs or construction reports were available which would indicate foundation conditions encountered during construction. Based on the visual inspection, it is assumed the embankment probably rests on Brownish Gray Calcareous Sandstone interbedded with Dolomite. The spillway is cut into hard sandstone interbedded with Dolomite.

The spillway rock cut slopes are stable; minor localized rock debris were observed at the foot of the slope at the downstream channel walls of the spillway.

(2) Project Soils

According to the "Missouri General Soil Map and Soil Association Descriptions" published by the Soil Conservation Service, the materials in the general area of the dam belong to the soil series of Menfro-Winfield in the Central Mississippi Valley Wooded Slopes family. The soils were basically formed from loess. The permeability of these soils is considered to be moderate.

Materials removed from the embankment on the crest and downstream slope approximately one foot below the vegetative cover appeared to be a light brown sandy silt. Based upon the Unified Soil Classification System, the soil would probably be classified as a ML. This soil type generally has the following characteristics: impervious with a coefficient of permeability less than 50 feet per year; medium to low shear strength; and intermediate to low resistance to piping.

d. Appurtenant Structures

The spillway approach slope up to the crest is about 6% and is clear of brush and debris. Downstream of the crest the spillway channel invert slope is about 1.79% and soon becomes somewhat clogged with overgrown grass, cattails, small trees, and miscellaneous debris. Some portions of the channel are not clogged, but grass is growing on the invert, which appears to lie directly over bedrock. One section of channel side slope is bare, possibly due to high velocity flow as it rounds the covered alignment and spills over the drop.

Basically the spillway appears stable and is adequately protected from surface erosion by grass that is for the most part too tall.

There were no low level drains or mechanically controlled outlet works provided for the dam.

e. Reservoir Area

The water surface elevation was 570.6 feet above M.S.L. on the day of the inspection.

The reservoir rim has mild slopes which appear to be of an easily erodible soil as there are quite a few wide erosion gullies along the left side of the reservoir. The land above the rim slopes up to a road on the left side of the reservoir and to a forest along the remainder of the reservoir. The mild slopes above the reservoir rim are grass covered until the trees. There are no houses built in the vicinity of the reservoir.

f. Downstream Channel

The downstream channel is well defined. The channel flows pass through a culvert underneath a light duty road which is about 700 feet downstream of the dam. Upstream from the culvert the channel has a bottom width of about 25 feet and a side flope of 1V to 1H on the right and 1V to 3H on the left side (looking downstream). Downstream from the culvert the channel is approximately 20 feet wide and has the same side slopes. The channel is obstructed by trees which could affect the hydraulic efficiency of the channel.

3.2 Evaluation

The visual inspection did not reveal any items which are sufficiently significant to indicate a need for immediate remedial action. The following conditions were observed which could affect the safety of the facility and will require maintenance within a reasonable period of time.

1. The trees observed on the downstream and upstream slopes pose a potential danger to the safety of the dam depending upon the extent of the root system. The roots present possible paths for piping through the embankment. The root systems can also do damage to the embankment from being uprooted by a storm.

2. The possible seepage indicated by the standing water downstream of the toe of the dam could affect the structural stability of the dam. If the rate of seepage were to increase, it is possible that the seepage could transport soil particles which could cause piping of embankment material which in turn could lead to an eventual failure of the embankment.

3. The erosion on the upstream slope due to wave action and on the downstream slope due to surface runoff could affect the safety of the dam if allowed to continue and should be properly repaired. Continual erosion will steepen the slopes which could lead to an eventual failure of the embankment.

4. Rodent activities on the upstream slope could jeopardize the safety of the dam. The holes created by the animals make avenues for possible piping.

5. The obstructed section of the spillway channel causes the water level of a high flow to rise thus causing higher backwater effects. Also, the tall grasses growing within the channel area cause the channel to operate at a higher friction factor.

6. The unprotected area of the spillway channel side slope at the downstream end will become further eroded with each additional high velocity flow.

SECTION 4: OPERATIONAL PROCEDURES

4.1 Procedures

There are no specific procedures which are followed for the operation of this dam. The water level below the spillway crest is allowed to remain as high as possible.

4.2 Maintenance of Dam

The dam is maintained by the owner, Dr. Robert Henson. The maintenance of the dam appears to be inadequate. The downstream slope is covered with bushes, saplings and a few large trees. Several saplings and small trees are also growing on the upstream slope of the dam.

There have not been any major repairs done to the dam itself since its original construction.

4.3 Maintenance of Operating Facilities

There are no operating facilities associated with this dam.

4.4 Description of Any Warning System in Effect

The inspection team is not aware of any warning system in use at the dam site.

4.5 Evaluation

The maintenance at the dam appears to be inadequate at this time. The corrective measures listed in Section 7 should be undertaken within a reasonable period of time to improve the condition of the dam.

SECTION 5: HYDRAULIC/HYDROLOGIC

5.1 Evaluation of Features

a. Design

The watershed area of the Dr. Henson Lake Dam upstream from the dam axis consists of approximately 57 acres. The watershed area is mostly pasture and range land with some wooded areas. Land gradients in the watershed average roughly 13 percent. The Dr. Henson Lake Dam Reservoir is located on an unnamed tributary of Frene Creek. The reservoir is about 2400 feet upstream from the confluence of the unnamed tributary and Frene Creek. At its longest arm the watershed is approximately 1/2 mile long. A drainage map showing the watershed and the downstream hazard zone is presented as Plate 1 in Appendix B.

Evaluation of the hydraulic and hydrologic features of Dr. Henson Lake Dam was based upon criteria set forth in the Corps of Engineers' "Engineer Regulation No. 1110-2-106" and additional guidance provided by the St. Louis District of the Corps of Engineers. The Probable Maximum Flood (PMF) was calculated from the Probable Maximum Precipitation (PMP) using the methods outlined in the U.S. Weather Bureau Publication, Hydrometeorological Report No. 33. The probable maximum storm duration was set at 24 hours, and storm rainfall distribution was based upon criteria given in the Corps of Engineers' EM 1110-2-1411 (Standard Project Storm). The Soil Conservation Service (SCS) method was used for deriving the unit hydrograph, utilizing the Corps of Engineers' computer program HEC-1

(Dam Safety Version). The unit hydrograph parameters are presented in Appendix B. The SCS method also was used for determining the loss rate. The hydrologic soil group of the watershed was determined by use of published soil maps. The hydrologic soil group of the watershed and the SCS curve number are presented in Appendix B. The curve number, unit hydrograph parameters, the PMP index rainfall and the percentages for various durations were directly input to the HEC-1 (Dam Safety Version) computer program to obtain the PMF hydrograph. The computed peak inflow of the PMF and one-half of the PMF are 1,537 cfs and 769 cfs, respectively.

Both the PMF and one-half of the PMF inflow hydrographs were routed through the reservoir by the Modified Puls Method also utilizing the HEC-1 (Dam Safety Version) computer program. A storm of 50 percent and 25 percent PMF, respectively, preceded the PMF and 50 percent PMF by four days. The reservoir was assumed at the mean annual high water level at the beginning of the antecedent storm. The mean annual high water level for Dr. Henson Lake was estimated to be at the crest of the spillway. The antecedent 50 percent PMF storm, when routed through the reservoir, leaves the reservoir at approximately the same elevation as the crest of the spillway at the end of the the four day period. Thus the reservoir was assumed at the spillway crest at the start of the routing computation for PMF, one-half of the PMF and other PMF ratio floods. The peak outflow discharges for the PMF and one-half of the PMF are 1,302 and 404 cfs, respectively. Only the PMF when routed through the reservoir resulted in overtopping of the dam.

The sizes of physical features utilized to develop the stage-outflow relation for the spillway and overtopping of the dam were prepared from field notes and sketches prepared during the field inspection. The reservoir elevation-area data were obtained from the U.S.G.S. Hermann, Missouri Quadrangle topographic map (7.5 minute series). The spillway and dam overtop-rating curve and the reservoir-elevation-area curve are presented as Plates 2 & 3, respectively, in Appendix B.

From the standpoint of dam safety, the hydrologic design of a dam must aim at avoiding overtopping. Overtopping is especially dangerous for an earth dam because of its erodable characteristics. The safe hydrologic design of an embankment dam requires a spillway discharge capability combined with an embankment crest height that can handle a very large and exceedingly rare flood without overtopping.

The Corps of Engineers designs dams to safely pass the Probable Maximum Flood that could be generated from the dam's watershed. This is generally the standard for dam safety where overtopping would pose any threat to human life. Accordingly, the hydrologic requirement for safety for this dam is the capability to pass the Probable Maximum Flood without overtopping.

b. Experience Data

It is believed that records of reservoir stage or spillway discharge are not maintained for this site. However, according to the owner, the maximum reservoir level was about 6-inches above the crest of the spillway.

c. Visual Observations

Observations made of the spillway during the visual inspection are discussed in Section 3.1d and evaluated in Section 3.2.

d. Overtopping Potential

As indicated in Section 5.1.a, only the Probable Maximum Flood, when routed through the reservoir, resulted in overtopping of the dam. The peak outflow discharges for the PMF and one-half of the PMF are 1,302 and 404 cfs, respectively. The maximum capacity of the spillway just before overtopping the dam is 446 cfs. The PMF overtopped the dam by 0.71 feet. The total duration of flow over the top of dam was 20 minutes. The spillway/reservoir system of Dr. Henson Lake Dam is capable of accommodating a flood equal to approximately 50 percent of the PMF just before overtopping the dam. The reservoir/spillway system of Dr. Henson Lake Dam will accommodate the one percent chance flood without overtopping. The results of the flood routings are summarized in the following Table.

Table: Summary of Routings of Floods

Flood Routed	Max. Pool Elevation (M.S.L.)	Maximum Discharge (cfs)	Depth of Overtopping (feet)	Duration of Overtopping (hrs)
100-yr	573.14	164	0	0
45% PMF	574.56	359	0	0
50% PMF	574.83	404	0	0
55% PMF	575.05	482	0.05	0.17
60% PMF	575.22	608	0.22	0.17
100% PMF	575.71	1302	0.71	0.33

The surface soils in the embankment appears to be sandy silt. The spillway, being a rock cut channel should be able to withstand high velocity flow during the PMF without being subject to excessive erosion; however, the downstream slope of the dam might be eroded and thus endanger the safety of the dam due to overtopping during the occurrence of the PMF.

The failure of the dam could cause extensive damage to the property downstream of the dam and possible loss of life. The estimated damage zone extends approximately one mile downstream of the dam. Within the damage zone are three dwellings, a state highway (Hwy. 100), a park and a campground.

SECTION 6: STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability

a. Visual Observations

There were no major signs of settlement or distress observed on the embankment during the visual inspection. The wave erosion on the upstream slope and the surface runoff erosion on the downstream slope do not appear to affect the structural stability of the dam in their present condition. Also the possible seepage observed downstream of the toe does not appear to affect the stability of the dam in its present condition. There were no indications of past or present slope instability except for the 6-foot wide scarp observed near the center of the embankment which appears to be stable. In the absence of seepage and stability analyses, no quantitative evaluation of this structure can be made.

Overall, the spillway crest and the channel appear to be in stable shape. However, some area of the channel side slope at the downstream end just before the drop is not protected against erosion.

b. Design and Construction Data

No design computations were uncovered during the report preparation phase. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available. No embankment or foundation soil parameters are available for carrying

out a conventional stability analysis on the embankment. No construction data or specifications relating to the degree of embankment compaction are available for use in a stability analysis.

c. Operating Records

No operating records are available relating to the stability of the dam or appurtenant structures. The water level on the day of inspection was near the crest of the spillway, and it is assumed that the reservoir remains close to full at all times. No regulated outlet works or low level drain was provided for this dam.

d. Post Construction Changes

No post construction changes exist which will affect the structural stability of the dam.

e. Seismic Stability

The dam is located in Seismic Zone 1, as defined in "Recommended Guidelines for Safety Inspection of Dams" as prepared by the Corps of Engineers, and does not require a seismic stability analysis. An earthquake of the magnitude which would be expected in a Seismic Zone 1 should not cause distress to a well designed and constructed earth dam.

SECTION 7: ASSESSMENT/REMEDIAL MEASURES

7.1 Dam Assessment

The assessment of the general condition of the dam is based upon available data and visual inspection. Detailed investigations, testing and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

It should be realized that the reported condition of the dam is based upon observations of field conditions at the time of inspection along with data available to the inspection team.

It is also important to note that the condition of a dam depends upon numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be assurance that an unsafe condition could be detected.

a. Safety

The spillway capacity of Dr. Henson Lake Dam is found to be "Inadequate". The spillway/reservoir system will accommodate about 50 percent of the PMF without overtopping. The surface soils in the embankment appears to be sandy silt. The dam is overtopped by about a foot during the occurrence of the PMF. The spillway, being a rock cut channel, should be

able to withstand high velocity flow during the PMF without being subject to excessive erosion; however, the downstream slope of the dam might be eroded and thus endanger the safety of the dam due to overtopping during the occurrence of the PMF.

No quantitative evaluation of the safety of the embankment can be made in view of the absence of seepage and stability analyses. The present embankment, however, appears to have performed satisfactorily since its construction without failure or evidence of instability. There was no evidence indicating the dam has ever been overtopped.

The safety of the dam can be improved if the deficiencies described in Section 6.1a and below are corrected as described in Section 7.2b. The trees observed on the downstream and upstream slopes pose a potential danger to the safety of the dam depending upon the extent of the root system. The roots of trees present possible paths for piping through the embankment. The root systems can also do damage to the embankment from being uprooted by a storm. Therefore, the trees should be removed from the embankment under the guidance of an engineer experienced in the design and construction of earthen dams.

The existence of burrowing animals on the embankment could jeopardize the safety of the dam. The holes created by the animals make avenues for possible piping. The extent of damage to the embankment done by the burrowing animals should be determined and corrective measures undertaken as required.

A clean, well-trimmed spillway channel contributes to the overall efficiency and the safety of the dam.

b. Adequacy of Information

Information relating to the design and construction of the dam is lacking. The conclusions presented in this report are based on field measurement, past performance and present condition of the dam. Information on the design hydrology, hydraulic design, and the operation and maintenance of the dam were not available. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available which is considered a deficiency.

c. Urgency

The remedial measures recommended in Paragraph 7.2 should be accomplished within a reasonable period of time, and the item recommended in paragraph 7.2a should be pursued on a high priority basis.

d. Necessity for Phase II Inspection

Based upon results of the Phase I inspection, and if the remedial measures recommended in Paragraph 7.2 are undertaken, a Phase II inspection is not felt to be necessary.

7.2 Remedial Measures

a. Alternatives

There are several general options which may be considered to reduce the possibility of dam failure or to diminish the harmful consequences of such a failure. Some of these options are:

1. Increase the spillway capacity to pass the Probable Maximum Flood without overtopping the dam.
2. Increase the height of the dam enough to pass the PMF without overtopping the dam; an investigation should also be done that includes studying the effects on the structural stability of the existing embankment. The overtopping depth during the occurrence of the PMF, stated in Section 5.1d, is not the required or recommended increase in the height of the dam.
3. A combination of 1 and 2 above.

b. O & M Procedures


1. The erosion on the upstream slope due to wave action and on the downstream slope due to surface erosion and the 6-foot wide scarp on the upstream slope should be backfilled with a suitable material and properly compacted. The slopes should then be graded and properly protected from further damage due to erosion.

2. The possible seepage downstream of the toe of the embankment should be monitored to detect any changes in turbidity, location or quantity. Any changes should be reported and investigated further.
3. Remove the trees from the downstream and upstream slopes of the dam. Removal of large trees should be under the guidance of an engineer experienced in the design and construction of earthen dams.
4. Determine the extent of damage done to the embankment by burrowing animals and corrective repairs made as required. All burrowing animals should be eliminated from the embankment and their burrows properly backfilled and compacted.
5. The spillway channel bottom should be cleaned of all tall grass and cattail growth and miscellaneous debris (e.g. plastic bottles); other grassy areas of the channel bottom should be either cut very short or prevented from growing at all if on bedrock.
6. The unprotected areas of the spillway channel side slopes should be given protection against any erosion from high velocity flows.
7. Seepage and stability analyses should be performed by a professional engineer experienced in the design and construction of earth dams.


8. The owner should initiate the following programs:

- (a) Periodic inspection of the dam by a professional engineer experienced in the design and construction of earthen dams.
- (b) Set up a maintenance schedule and log all visits to the dam for operation, repairs and maintenance.


PLATES




LOCATION MAP - DR. HENSON LAKE DAM
MO. 31570



SPILLWAY PROFILE (SECTION B-B)



ELEVATION (SECTION A-A)



Section C-C

- NO OUTLET WORKS

NO SCALE

DR. HENSON LAKE DAM
PLAN, ELEVATION, SECTION
AND SPILLWAY PROFILE



⊕ LOCATION OF DAM

NOTE: LEGEND OF THIS DAM IS ON PLATE


REFERENCE:

GEOLOGIC MAP OF MISSOURI
DEPARTMENT OF NATURAL RESOURCES
MISSOURI GEOLOGICAL SURVEY
KENNETH H. ANDERSON, 1979

REGIONAL GEOLOGICAL MAP
OF
DR. HENSON LAKE DAM

LEGEND

<u>PERIOD</u>	<u>SYMBOL</u>	<u>DESCRIPTION</u>
QUATERNARY	Qal	ALLUVIUM: SAND, SILT, GRAVEL
PENNSYLVANIAN	Pu	PENNSYLVANIAN UNDIFFERENTIATED
	Pm	MARMATON GROUP: CYCLIC DEPOSITS OF SHALE, LIMESTONE AND SANDSTONE
	Pcc	CHEROKEE GROUP: CYCLIC DEPOSITS OF SHALE, LIMESTONE AND SANDSTONE
MISSISSIPPIAN	Mm	ST. LOUIS FORMATION: LIMESTONE INTERBEDDED WITH SHALE.
	Mm	SALEM FORMATION: LIMESTONE INTERBEDDED WITH SHALE AND SILTSTONE
	Mm	WARSAW FORMATION: ARGILLACEOUS LIMESTONE AND CALCAREOUS SHALE
	Mo	KEOKUK - BURLINGTON FORMATION: CHERTY GRAYISH BROWN SANDY LIMESTONE
	Mk	NORTHVIEW - COMPTON AND BACHELOR FORMATION
DEVONIAN	D	CHATTANOOGA SHALE, SYLAMORE SANDSTONE
ORDOVICIAN	Omk	MAQUOKETA SHALE, KIMMSWICK LIMESTONE
	Odp	DECORAH FORMATION: GREEN TO GRAY CALCAREOUS SHALE WITH THIN FOSSILIFEROUS LIMESTONE
	Osp	ST PETER SANDSTONE
	Ojc	SMITHVILLE FORMATION POWELL DOLOMITE
	Or	ROUBIDOUX FORMATION



APPENDIX A

PHOTOGRAPHS




PHOTO INDEX
FOR
DR. HENSON LAKE DAM

Dr. Henson Lake Dam
Photographs

- Photo 1 - Top of dam showing good grass cover.
- Photo 2 - Upstream slope of dam showing trees growing on slope (looking right).
- Photo 3 - Upstream slope of dam (looking left) showing brush and grass growth.
- Photo 4 - View of hole in upstream slope of dam--indicates burrowing activity.
- Photo 5 - Downstream slope of dam showing dense grass growth and trees growing on slope (looking right).
- Photo 6 - Downstream slope of dam showing dense grass and trees (looking left).
- Photo 7 - Reservoir rim showing tree-lined mild slopes.
- Photo 8 - Entrance to spillway showing thick grass and reeds within channel (look downstream).
- Photo 9 - Spillway channel showing turn and point of 10-foot drop.
- Photo 10 - View of downstream channel crossing under road.
- Photo 11 - View of downstream channel showing trees lining channel and nearby structure.
- Photo 12 - Outcrop-Ordovician, moderately weathered, grey Dolomite interbedded with sandstones and shale.

Dr. Henson Lake Dam



Photo 1



Photo 2

Dr. Henson Lake Dam



Photo 3




Photo 4

Dr. Henson Lake Dam



Photo 5



Photo 6

Dr. Henson Lake Dam



Photo 7



Photo 8

Dr. Henson Lake Dam



Photo 9



Photo 10

Dr. Henson Lake Dam




Photo 11



Photo 12

APPENDIX B

HYDROLOGIC AND HYDRAULIC COMPUTATIONS



**DR. HENSON LAKE DAM MO 31570
DRAINAGE BASIN**

PRC ENGINEERING CONSULTANTS, INC.

DAM SAFETY


SHEET NO. 1 OF 2

DR. BENSON LAKE DAM

JOB NO. 1262

SPILLWAY & OVERTOP RATING CURVE

BY FZ DATE Sept 80



y_{c1}	A_{c1}	T_{c1}	$V_{c1} \sqrt{\frac{A_{c1}^3}{T_{c1}}}$	$Q_0 = V_{c1} A_{c1}$	$\frac{V_{c1}^2}{2g}$	h_1	H_2	C_2	Q_2	WSEL	$y_1 + Q_2$
0										570.60	0
0.5	5.4	11.1	3.9	21	0.23	0.73				571.33	21
1.0	11.7	12.4	5.3	62	0.44	1.44				572.04	62
1.5	18.8	15.1	6.3	119	0.62	2.12				572.72	119
2.0	26.8	16.8	7.2	192	0.80	2.80				573.40	192
2.5	35.6	18.5	7.9	280	0.96	3.46				574.06	280
3.0	45.2	20.2	8.5	385	1.12	4.12				574.72	385
3.2	49.3	20.8	8.7	431	1.18	4.38				574.98	431
3.4	53.6	21.5	8.9	480	1.25	4.65	0.25	2.98	149	575.25	629
3.6	57.9	22.2	9.2	531	1.31	4.91	0.51	3.02	440	575.51	971
3.8	62.5	22.9	9.4	586	1.37	5.17	0.77	3.03	819	575.77	1405
4.0	67.1	23.6	9.6	643	1.42	5.42	1.02	3.04	1251	576.02	1894
4.5	79.0	24.0	10.3	813	1.65	6.15	1.75	3.07	2841	576.75	3654

11-3

$$WSEL = y_{c1} + \frac{V_{c1}^2}{2g} + 570.6 \quad H_1 = y_{c1} + \frac{V_{c1}^2}{2g}$$

$$H_2 = H_1 - 4.4$$


$$Q_2 = 400 C_2 H_2^{3/2}$$

$$y_{c1} \leq 4 \quad A_{c1} = y_{c1} (1.69 y_{c1} + 10)$$

$$T_{c1} = 3.37 y_{c1} + 10$$

$$y_{c1} \geq 4.4 \quad A_{c1} = 24 (y_{c1} - 1)$$

$$T_{c1} = 2 y_{c1}$$



DAM SAFETY

SHEET NO. 2 OF 2

DR. JOHNSON LAKE DAM # 31570

JOB NO. 1263BY PZ DATE Sept 80VERIFICATION OF CRITICAL DEPTH ASSUMPTION

$$\underline{y \leq 4} \Rightarrow A = y(1.69y + 10) \\ P = 3.98y + 10$$

$$\text{Assume } h = 0.03 \\ S = 1.25/70$$


$$Q = \frac{1.49}{0.03} \times \sqrt{\frac{1.25}{70}} \times \frac{A^{5/3}}{P^{4/3}} = 0.64 \frac{A^{5/3}}{P^{4/3}}$$

$$\underline{y \geq 4.4} \quad A = 24(y-1) \\ P = 26.5$$

$$Q = 0.75 A^{5/3}$$

Q	y_c	y_n
21	0.5	0.497
119	1.5	1.4
280	2.5	2.2
531	3.4	3.1
813	4.5	3.9

Normal depth $y_n < y_c \Rightarrow$ the water surface will go through critical depth downstream of the dam and the assumption is adequate



DR. HENSON LAKE DAM (MO. 31570)
 SPILLWAY & OVERTOP RATING CURVE
 B-5

PRC ENGINEERING CONSULTANTS, INC.


DAM SAFETY INSPECTION - MISSOURI

SHEET NO. 1 OF 1DAM NAME: DT. HENSON LAKE DAM ID NO.: 31570JOB NO. 1263

RESERVOIR ELEVATION - AREA DATA

BY JFK FE DATE 4/21/80

ELEV. (M.S.L.) (Ft.)	RESERVOIR SURFACE AREA (Acres)	REMARKS
563.6	0	Assumed Bottom of Reservoir
570.6	2.0	Spillway elevation
580	5.0	Estimate from USGS Topo Map.
600	12.0	" " " "
590	8.3	Interpolated



DR. HENSON LAKE DAM (MO. 31570)
 RESERVOIR ELEVATION-AREA CURVE
 B-7

DAM SAFETY INSPECTION / MISSOURI

SHEET NO. 1 OF 3

DAM NAME: DR. HENSON LAKE DAM # 31570

JOB NO. 1267

PROBABLE MAXIMUM PRECIPITATION

BY FE DATE MAY 80

DETERMINATION OF PMP

- 1) Determine drainage area of the basin

D.A. = 0.089 sq mile

- 2) Determine PMP Index Rainfall (for D.A. = 200 sq. mi. & 24 hr. duration)

Location of centroid of basin,


Long. = $91^{\circ}27'16''$ Lat. = $38^{\circ}41'54''$

PMP = 25" (from Fig. 1, HMR 33)

Zone = 7

- 3) Determine basin rainfall in terms of percentage of PMP Index Rainfall for various durations.
-
- (from Fig. 2, HMR 33)

Duration (Hrs.)	Percent of Index Rainfall (%)	Total Rainfall (Inches)	Rainfall Increments (Inches)	Duration of Increment (Hrs.)
6	100	25	25	6
12	120	30	5	6
24	130	32.5	2.5	12



⊕ LOCATION OF DAM




FIGURE 2
SEASONAL VARIATION
DEPTH-AREA-DURATION RELATIONSHIPS
Percentages to be applied to 200 square miles
24 hour probable maximum precipitation values
for: THE-ALL SEASON ENVELOPE

DAM SAFETY INSPECTION / MISSOURI

SHEET NO. 1 OF 1

DAM NAME: DR. HENSON LAKE DAM # 31570

JOB NO. 1263

UNIT HYDROGRAPH PARAMETERS

BY FZ DATE MAY 80

- 1) DRAINAGE AREA, $A = 0.089$ sq. mi. = (57 acres)
- 2) LENGTH OF STREAM, $L = (0.85' \times 2000' = 1700') = 0.32$ mi.
- 3) ELEVATION AT DRAINAGE DIVIDE ALONG THE LONGEST STREAM,
 $H_1 = 810$
- 4) ELEVATION OF RESERVOIR AT SPILLWAY CREST, $H_2 = 570.6$
- 5) ELEVATION OF CHANNEL BED AT $0.85L$, $E_{85} = 740$
- 6) ELEVATION OF CHANNEL BED AT $0.10L$, $E_{10} = 577$
- 7) AVERAGE SLOPE OF THE CHANNEL, $S_{AVG} = (E_{85} - E_{10}) / 0.75L = 0.13$
- 8) TIME OF CONCENTRATION:

A) BY KIRKPICH'S EQUATION,

$$t_c = [(11.9 \times L^3) / (H_1 - H_2)]^{0.385} = [(11.9 \times 0.32^3) / (810 - 570.6)]^{0.385} = 0.084 \text{ hr}$$

B) BY VELOCITY ESTIMATE,

$$\text{SLOPE} = 13\% \Rightarrow \text{AVG. VELOCITY} = 5 \text{ fps}$$

$$t_c = L/V = \frac{1700}{5} \times \frac{1}{3600} = 0.094 \text{ hr}$$

$$\text{USE } t_c = 0.084 \text{ hr}$$

$$9) \text{ LAG TIME, } t_L = 0.6 t_c = 0.05$$

$$10) \text{ UNIT DURATION, } D \leq t_L / 3 = 0.017 < 0.083 \text{ hr}$$

$$\text{USE } D = 0.083$$

$$11) \text{ TIME TO PEAK, } T_p = D/2 + t_L = \frac{0.083}{2} + 0.05 = 0.0915$$

12) PEAK DISCHARGE,

$$q_p = (484 \times A) / T_p = \frac{484 \times 0.089}{0.0915} = 471 \text{ cfs}$$

PRC ENGINEERING CONSULTANTS, INC.

DAM SAFETY INSPECTION / MISSOURI - 1980 SHEET NO. 1 OF 1DAM NAME: DR. HENSON LAKE DAM # 31570 JOB NO. 1263CURVE NUMBER DETERMINATION BY PZ DATE MAY 80I) SOIL GROUP

WATERSHED SOILS IN THE BASIN CONSIST OF GROUP

MENFRO - WINFIELDA
B
C
D

GROUP C SOILS SEEM TO PREDOMINATE THE BASIN. THEREFORE,
ASSUME GROUP C SOILS FOR THE ENTIRE WATERSHED
FOR HYDROLOGIC PURPOSES.

II) COVER COMPLEX

ASSUMED LAND USE	ASSUMED HYDROLOGIC CONDITION	PER CENT AREA	CN (AMC II)
WOODS	FAIR	47	73
RANGE	FAIR	53	79

III) CURVE NUMBERWEIGHTED AVERAGE CN = 76 FOR AMC IICURVE NUMBER = 89 FOR AMC III

SHEET NO. 1 OF 1


DAM SAFETY

JOB NO. 1263

DR NENSON LAKE DAM

BY FZ DATE Sept 80

1/2 PMF antecedent storm is at 570.9 after 24 hrs



ϕ	Q	Δt	$\Sigma \Delta t$	Time in days
4.44	5.5		1	
4.86	3.0	0.01	1.01	
4.78	1.5	0.02	1.03	
4.72	0	0.04	1.07	< 4 days <u>OK</u>

HEC1DB INPUT DATA

INFLOW PMF AND ONE-HALF PMF HYDROGRAPHS

PREVIEW OF SEQUENCE OF STREAM NETWORK CALCULATIONS

WUNDEE HYDROGRAPH AT 021578
WUNDEE HYDROGRAPH TO 031570
END OF NETWORK

08-16-60
JIM - 09-11-60

ONE FIFTY TWO TWO - WASH DC
DWF AND FIFTY THREE ONE PMF
AM IN JUNE AT THE NEW YORK
OFFICE OF THE DIRECTOR OF FBI

[illegible]

MULTI-PLAN ANALYSIS TO BE REPORTED
NPLAN=1 N-YIO=2 LRVIC=1

05. 1. 66. 1. 50

SUN-4RE: RUGOFF COMPUTATION

INPUT PRECIPITATION INDEX, FERTILISER AND UNIT HANDS/HECTARE.

ISTAG	ICOMP	IRECON	ITAFF	JULY	JUNE	ISTAGE	AUTO
2:57C	0	0	0	1	1	0	0

ИЗДАТЕЛЬСТВО «НАУКА»

[illegible]

REF ID: A67474

SPFE	AMS	R6	R12	R24	R40	72	89E
30.00	25.00	100.00	170.00	120.00	0.00	0.00	3.30

100-174

[illegible]

U.S. IT IVT HOGRAH C27A

TC=, 0.00 LAC= .85

RECESSION DATA

STRTIME - 9.06 DURATION DATA WY100- 1.00

FILE 100-6981700 LARGE-444 25 07 LAG/20

SECRET

MOJOA	HR. 44	PERIOD	WAIN	EXCS	LOSS	COMP	HR. 44	PERIOD	WAIN	EXCS	LOSS	COMP
1.01	0.05	1	0.01	0.00	0.01	0	1.01	12.35	151	0.21	0.00	141
1.01	0.10	2	0.01	0.00	0.01	0	1.01	12.40	152	0.21	0.00	142
1.01	0.15	3	0.01	0.00	0.01	0	1.01	12.45	153	0.21	0.00	143
1.01	0.20	4	0.01	0.00	0.01	0	1.01	12.50	154	0.21	0.00	144
1.01	0.25	5	0.01	0.00	0.01	0	1.01	12.55	155	0.21	0.00	145
1.01	0.30	6	0.01	0.00	0.01	0	1.01	13.00	156	0.21	0.00	146
1.01	0.35	7	0.01	0.00	0.01	0	1.01	13.05	157	0.21	0.00	147
1.01	0.40	8	0.01	0.00	0.01	0	1.01	13.10	158	0.21	0.00	148
1.01	0.45	9	0.01	0.00	0.01	0	1.01	13.15	159	0.21	0.00	149
1.01	0.50	10	0.01	0.00	0.01	0	1.01	13.20	160	0.21	0.00	150
1.01	0.55	11	0.01	0.00	0.01	0	1.01	13.25	161	0.21	0.00	151
1.01	0.60	12	0.01	0.00	0.01	0	1.01	13.30	162	0.21	0.00	152
1.01	0.65	13	0.01	0.00	0.01	0	1.01	13.35	163	0.21	0.00	153
1.01	0.70	14	0.01	0.00	0.01	0	1.01	13.40	164	0.21	0.00	154
1.01	0.75	15	0.01	0.00	0.01	0	1.01	13.45	165	0.21	0.00	155
1.01	0.80	16	0.01	0.00	0.01	0	1.01	13.50	166	0.21	0.00	156
1.01	0.85	17	0.01	0.00	0.01	0	1.01	13.55	167	0.21	0.00	157
1.01	0.90	18	0.01	0.00	0.01	0	1.01	14.00	168	0.21	0.00	158
1.01	0.95	19	0.01	0.00	0.01	0	1.01	14.05	169	0.21	0.00	159
1.01	1.00	20	0.01	0.00	0.01	0	1.01	14.10	170	0.21	0.00	160
1.01	1.05	21	0.01	0.00	0.01	0	1.01	14.15	171	0.21	0.00	161
1.01	1.10	22	0.01	0.00	0.01	0	1.01	14.20	172	0.21	0.00	162
1.01	1.15	23	0.01	0.00	0.01	0	1.01	14.25	173	0.21	0.00	163
1.01	1.20	24	0.01	0.00	0.01	0	1.01	14.30	174	0.21	0.00	164
1.01	1.25	25	0.01	0.00	0.01	0	1.01	14.35	175	0.21	0.00	165
1.01	1.30	26	0.01	0.00	0.01	0	1.01	14.40	176	0.21	0.00	166
1.01	1.35	27	0.01	0.00	0.01	0	1.01	14.45	177	0.21	0.00	167
1.01	1.40	28	0.01	0.00	0.01	0	1.01	14.50	178	0.21	0.00	168
1.01	1.45	29	0.01	0.00	0.01	0	1.01	14.55	179	0.21	0.00	169
1.01	1.50	30	0.01	0.00	0.01	0	1.01	15.00	180	0.21	0.00	170
1.01	1.55	31	0.01	0.00	0.01	0	1.01	15.05	181	0.21	0.00	171
1.01	1.60	32	0.01	0.00	0.01	0	1.01	15.10	182	0.21	0.00	172
1.01	1.65	33	0.01	0.00	0.01	0	1.01	15.15	183	0.21	0.00	173
1.01	1.70	34	0.01	0.00	0.01	0	1.01	15.20	184	0.21	0.00	174
1.01	1.75	35	0.01	0.00	0.01	0	1.01	15.25	185	0.21	0.00	175
1.01	1.80	36	0.01	0.00	0.01	0	1.01	15.30	186	0.21	0.00	176
1.01	1.85	37	0.01	0.00	0.01	0	1.01	15.35	187	0.21	0.00	177
1.01	1.90	38	0.01	0.00	0.01	0	1.01	15.40	188	0.21	0.00	178
1.01	1.95	39	0.01	0.00	0.01	0	1.01	15.45	189	0.21	0.00	179
1.01	2.00	40	0.01	0.00	0.01	0	1.01	15.50	190	0.21	0.00	180
1.01	2.05	41	0.01	0.00	0.01	0	1.01	15.55	191	0.21	0.00	181
1.01	2.10	42	0.01	0.00	0.01	0	1.01	15.60	192	0.21	0.00	182
1.01	2.15	43	0.01	0.00	0.01	0	1.01	15.65	193	0.21	0.00	183
1.01	2.20	44	0.01	0.00	0.01	0	1.01	15.70	194	0.21	0.00	184
1.01	2.25	45	0.01	0.00	0.01	0	1.01	15.75	195	0.21	0.00	185
1.01	2.30	46	0.01	0.00	0.01	0	1.01	15.80	196	0.21	0.00	186
1.01	2.35	47	0.01	0.00	0.01	0	1.01	15.85	197	0.21	0.00	187
1.01	2.40	48	0.01	0.00	0.01	0	1.01	15.90	198	0.21	0.00	188
1.01	2.45	49	0.01	0.00	0.01	0	1.01	15.95	199	0.21	0.00	189
1.01	2.50	50	0.01	0.00	0.01	0	1.01	16.00	200	0.21	0.00	190
1.01	2.55	51	0.01	0.00	0.01	0	1.01	16.05	201	0.21	0.00	191
1.01	2.60	52	0.01	0.00	0.01	0	1.01	16.10	202	0.21	0.00	192
1.01	2.65	53	0.01	0.00	0.01	0	1.01	16.15	203	0.21	0.00	193
1.01	2.70	54	0.01	0.00	0.01	0	1.01	16.20	204	0.21	0.00	194
1.01	2.75	55	0.01	0.00	0.01	0	1.01	16.25	205	0.21	0.00	195
1.01	2.80	56	0.01	0.00	0.01	0	1.01	16.30	206	0.21	0.00	196
1.01	2.85	57	0.01	0.00	0.01	0	1.01	16.35	207	0.21	0.00	197
1.01	2.90	58	0.01	0.00	0.01	0	1.01	16.40	208	0.21	0.00	198
1.01	2.95	59	0.01	0.00	0.01	0	1.01	16.45	209	0.21	0.00	199
1.01	3.00	60	0.01	0.00	0.01	0	1.01	16.50	210	0.21	0.00	200
1.01	3.05	61	0.01	0.00	0.01	0	1.01	16.55	211	0.21	0.00	201
1.01	3.10	62	0.01	0.00	0.01	0	1.01	16.60	212	0.21	0.00	202
1.01	3.15	63	0.01	0.00	0.01	0	1.01	16.65	213	0.21	0.00	203
1.01	3.20	64	0.01	0.00	0.01	0	1.01	16.70	214	0.21	0.00	204
1.01	3.25	65	0.01	0.00	0.01	0	1.01	16.75	215	0.21	0.00	205
1.01	3.30	66	0.01	0.00	0.01	0	1.01	16.80	216	0.21	0.00	206
1.01	3.35	67	0.01	0.00	0.01	0	1.01	16.85	217	0.21	0.00	207
1.01	3.40	68	0.01	0.00	0.01	0	1.01	16.90	218	0.21	0.00	208
1.01	3.45	69	0.01	0.00	0.01	0	1.01	16.95	219	0.21	0.00	209
1.01	3.50	70	0.01	0.00	0.01	0	1.01	17.00	220	0.21	0.00	210
1.01	3.55	71	0.01	0.00	0.01	0	1.01	17.05	221	0.21	0.00	211
1.01	3.60	72	0.01	0.00	0.01	0	1.01	17.10	222	0.21	0.00	212
1.01	3.65	73	0.01	0.00	0.01	0	1.01	17.15	223	0.21	0.00	213
1.01	3.70	74	0.01	0.00	0.01	0	1.01	17.20	224	0.21	0.00	214
1.01	3.75	75	0.01	0.00	0.01	0	1.01	17.25	225	0.21	0.00	215

[illegible][illegible]

PMF AND ONE-HALF PMF ROUTING

SUMMARY OF PMF AND ONE-HALF PMF FLOOD ROUTING

PEAK FLOW AND STORAGE HEAD OF PERIODIC SCHEMATIC FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

RAILOS ADJUSTED TO FLOWS

OPERATION STATION AREA PLAN RATIO 1 RATIO 2
 1.00 0.50

HYDROGRAPH AT 031570 0.29 1 1537 75% 21.7014
 0.23 0.425314

ROUTED TO 031570 0.05 1 1312 41% 11.9911
 0.23 0.368091

SUMMARY OF DAN SAFETY ANALYSIS

[illegible]

0374100
ELEVATION
STONES

INITIAL VALUE	STILLAY CREDIT
570.63	570.60
5.	5.
0.	0.

104 25 644
475.20
16.
496.

TYPE OF LOAD	MAXIMUM RESERVATION AVAILABLE	MAXIMUM PEAK OVER DEM	MAXIMUM STORAGE CAPACITY	MAXIMUM OUTFLOW RATE	OPERATION CAPACITY DOWN TOP MILES	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
100							
200							
300							
400							
500							
600							
700							
800							
900							
1000							

PERCENT OF PIF FLOOD ROUTING
EQUAL TO SPILLWAY CAPACITY

PREFACE OF SUBJECT OF STREAM NETWORK CALCULATIONS

NUMBER OF STREAMS IN NETWORK — 31570
ROUTE HYDROGRAPH TO — 31570
END OF NETWORK

DATE	TIME	LOC	SCUT	COMP D	WIND	PERIOD	RAIN	SXN3	SSUT	COMP D
770524	1400	48.44	52X3	0	0.0	0.00	0.00	0.00	0	0
770524	1500	48.44	52X3	0	0.0	0.00	0.00	0.00	0	0
770524	1600	48.44	52X3	0	0.0	0.00	0.00	0.00	0	0
770524	1700	48.44	52X3	0	0.0	0.00	0.00	0.00	0	0
770524	1800	48.44	52X3	0	0.0	0.00	0.00	0.00	0	0
770524	1900	48.44	52X3	0	0.0	0.00	0.00	0.00	0	0
770524	2000	48.44	52X3	0	0.0	0.00	0.00	0.00	0	0
770524	2100	48.44	52X3	0	0.0	0.00	0.00	0.00	0	0
770524	2200	48.44	52X3	0	0.0	0.00	0.00	0.00	0	0
770524	2300	48.44	52X3	0	0.0	0.00	0.00	0.00	0	0
770525	0000	48.44	52X3	0	0.0	0.00	0.00	0.00	0	0
770525	0100	48.44	52X3	0	0.0	0.00	0.00	0.00	0	0
770525	0200	48.44	52X3	0	0.0	0.00	0.00	0.00	0	0
770525	0300	48.44	52X3	0	0.0	0.00	0.00	0.00	0	0
770525	0400	48.44	52X3	0	0.0	0.00	0.00	0.00	0	0
770525	0500	48.44	52X3	0	0.0	0.00	0.00	0.00	0	0
770525	0600	48.44	52X3	0	0.0	0.00	0.00	0.00	0	0
770525	0700	48.44	52X3	0	0.0	0.00	0.00	0.00	0	0
770525	0800	48.44	52X3	0	0.0	0.00	0.00	0.00	0	0
770525	0900	48.44	52X3	0	0.0	0.00	0.00	0.00	0	0
770525	1000	48.44	52X3	0	0.0	0.00	0.00	0.00	0	0
770525	1100	48.44	52X3	0	0.0	0.00	0.00	0.00	0	0
770525	1200	48.44	52X3	0	0.0	0.00	0.00	0.00	0	0
770525	1300	48.44	52X3	0	0.0	0.00	0.00	0.00	0	0
770525	1400	48.44	52X3	0	0.0	0.00	0.00	0.00	0	0
770525	1500	48.44	52X3	0	0.0	0.00	0.00	0.00	0	0
770525	1600	48.44	52X3	0	0.0	0.00	0.00	0.00	0	0
770525	1700	48.44	52X3	0	0.0	0.00	0.00	0.00	0	0
770525	1800	48.44	52X3	0	0.0	0.00	0.00	0.00	0	0
770525	1900	48.44	52X3	0	0.0	0.00	0.00	0.00	0	0
770525	2000	48.44	52X3	0	0.0	0.00	0.00	0.00	0	0
770525	2100	48.44	52X3	0	0.0	0.00	0.00	0.00	0	0
770525	2200	48.44	52X3	0	0.0	0.00	0.00	0.00	0	0
770525	2300	48.44	52X3	0	0.0	0.00	0.00	0.00	0	0
770526	0000	48.44	52X3	0	0.0	0.00	0.00	0.00	0	0
770526	0100	48.44	52X3	0	0.0	0.00	0.00	0.00	0	0
770526	0200	4								

SUM 32.50 31.06 1.44 219.0
 1.925-15 740.35 27.15 585.71

HYDROGRAPH ROUTING

ROUTE HYDROGRAPH THROUGH D. HENSON LANE DAM (NO. 31-70)

INSTAG	ICOMP	ICOG	ITAP	ICPT	INAME	ISTAGE	IAUTO
001578	1	0	0	0	1	0	0

ROUTING DATA	ROUTING DATA	ROUTING DATA	ROUTING DATA
CLAS	LAG	ICPT	ICPT
0.000	0.75	1	0

ASTO	ACTOL	LAG	APK	ICPT	ICOG	ICPT	ICOG
1	0	0.000	0.000	0.000	0.000	0.000	0.000

STAG	STAG	STAG	STAG	STAG	STAG	STAG	STAG
571.51	571.51	571.51	571.51	571.51	571.51	571.51	571.51

FLOW	FLOW	FLOW	FLOW	FLOW	FLOW	FLOW	FLOW
1425.00	1425.00	1425.00	1425.00	1425.00	1425.00	1425.00	1425.00

SURFACE AREA	SURFACE AREA	SURFACE AREA	SURFACE AREA	SURFACE AREA	SURFACE AREA	SURFACE AREA	SURFACE AREA
0.	0.	0.	0.	0.	0.	0.	0.

CAPACITVE	CAPACITVE	CAPACITVE	CAPACITVE	CAPACITVE	CAPACITVE	CAPACITVE	CAPACITVE
0.	0.	0.	0.	0.	0.	0.	0.

ELEVATION	ELEVATION	ELEVATION	ELEVATION	ELEVATION	ELEVATION	ELEVATION	ELEVATION
554.	571.	580.	590.	600.	610.	620.	630.

COUL	SPIC	COUL	SPIC	COUL	SPIC	COUL	SPIC
170.0	0.0	170.0	0.0	170.0	0.0	170.0	0.0

TOPCL	COGR	TAID	TAID	TOPCL	COGR	TAID	TAID
575.0	575.0	575.0	575.0	575.0	575.0	575.0	575.0

PEAK OUTFLOW IS	300. AT TIME	15.75 HOURS
400. AT TIME	15.75 HOURS	400. AT TIME

PEAK OUTFLOW IS	400. AT TIME	15.75 HOURS
400. AT TIME	15.75 HOURS	400. AT TIME

PEAK OUTFLOW IS	400. AT TIME	15.75 HOURS
400. AT TIME	15.75 HOURS	400. AT TIME

PEAK OUTFLOW IS	400. AT TIME	15.75 HOURS
400. AT TIME	15.75 HOURS	400. AT TIME

PEAK OUTFLOW IS	400. AT TIME	15.75 HOURS
400. AT TIME	15.75 HOURS	400. AT TIME

AD-A106 623

PRC CONSOER TOWNSEND INC ST LOUIS MO
NATIONAL DAM SAFETY PROGRAM. DR. HENSON LAKE DAM (MO 31570), MI--ETC(U)
SEP 80 W S SHIFRIN
DACW43-80-C-0094

F/G 13/13

UNCLASSIFIED

NL

242
AD-A106 623



END
DATA
FILMED
12-81
DTIC

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMIT FOR MULTIPLE PLANNING ECONOMIC COMPUTATIONS
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION STATION AREA PLAN RATIO 1 RATIO 2 RATIO 3 RATIO 4 RATIO 5 RATIO 6 RATIO 7 RATIO 8 RATIO 9 RATIO 10 RATIO 11 RATIO 12 RATIO 13 RATIO 14 RATIO 15 RATIO 16 RATIO 17 RATIO 18 RATIO 19 RATIO 20 RATIO 21 RATIO 22 RATIO 23 RATIO 24 RATIO 25 RATIO 26 RATIO 27 RATIO 28 RATIO 29 RATIO 30 RATIO 31 RATIO 32 RATIO 33 RATIO 34 RATIO 35 RATIO 36 RATIO 37 RATIO 38 RATIO 39 RATIO 40 RATIO 41 RATIO 42 RATIO 43 RATIO 44 RATIO 45 RATIO 46 RATIO 47 RATIO 48 RATIO 49 RATIO 50 RATIO 51 RATIO 52 RATIO 53 RATIO 54 RATIO 55 RATIO 56 RATIO 57 RATIO 58 RATIO 59 RATIO 60 RATIO 61 RATIO 62 RATIO 63 RATIO 64 RATIO 65 RATIO 66 RATIO 67 RATIO 68 RATIO 69 RATIO 70 RATIO 71 RATIO 72 RATIO 73 RATIO 74 RATIO 75 RATIO 76 RATIO 77 RATIO 78 RATIO 79 RATIO 80 RATIO 81 RATIO 82 RATIO 83 RATIO 84 RATIO 85 RATIO 86 RATIO 87 RATIO 88 RATIO 89 RATIO 90 RATIO 91 RATIO 92 RATIO 93 RATIO 94 RATIO 95 RATIO 96 RATIO 97 RATIO 98 RATIO 99 RATIO 100

HYDROGRAPH AT 031570 100 600 769 805 900 970
 1 19,591 21,741 27,941 26,123
 ROUTED TO 031570 1 300 400 412 600
 1 11,180 11,000 13,000 17,270

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1		INITIAL VALUE	SPILLWAY CREST	TOP OF DAM			
ELEVATION		570.00	570.00	575.00			
STORAGE		0.	0.	16.			
OUTFLOW		0.	0.	446.			
RATIO OF DOWN	MAXIMUM MT. EROSION U.S. SLIP	MAXIMUM DEPTH DOWN	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION HOURS	TIME OF MAX. OUTFLOW HOURS	TIME OF FAILURE HOURS
0.95	74.06	0.01	15.	155.	0.00	15.75	0.00
0.90	74.04	0.00	10.	404.	0.00	15.75	0.00
0.85	74.01	0.	5.	482.	.17	15.67	0.00
0.80	73.92	0.0	17.	608.	.17	15.67	0.00

