

AD-A106 625

PRC CONSOER TOWNSEND INC ST LOUIS MO  
NATIONAL DAM SAFETY PROGRAM, BOCO MO DAM (MO 10893), MISSOURI ---ETC(U)  
SEP 80 W G SHIFRIN

F/6 13/13


DACW43-80-C-0094

NL

UNCLASSIFIED

1 of 2

AD-A  
10866\*



AD A106625

LEVEL



# MISSOURI - KANSAS CITY RIVER BASIN

BOCO MO DAM  
BOONE COUNTY, MISSOURI  
MO. 10893

## PHASE I INSPECTION REPORT NATIONAL DAM SAFETY PROGRAM


DTIC FILE COPY



United States Army  
Corps of Engineers

... Serving the Army  
... Serving the Nation

### St. Louis District



A

PREPARED BY: U. S. ARMY ENGINEER DISTRICT, ST. LOUIS

FOR: STATE OF MISSOURI

This document has been approved  
for public release and sale; its  
distribution is unlimited.

SEPTEMBER, 1980

81 11 02 046

UNCLASSIFIED


SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO. AD-A106625	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Dam Inspection Report National Dam Safety Program Boco MO Dam (MO 10893) Boone County, Missouri		5. TYPE OF REPORT & PERIOD COVERED Final Report
7. AUTHOR(s) Consoer, Townsend and Associates, Ltd.		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS U.S. Army Engineer District, St. Louis Dam Inventory and Inspection Section, LMSED-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101		8. CONTRACT OR GRANT NUMBER(s) DACW43-80-C-0094
11. CONTROLLING OFFICE NAME AND ADDRESS U.S. Army Engineer District, St. Louis Dam Inventory and Inspection Section, LMSED-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) National Dam Safety Program. Boco Mo Dam (MO 10893), Missouri - Kansas City River Basin, Boone County, Missouri. Phase I Inspection Report.		12. REPORT DATE September 1980
16. DISTRIBUTION		13. NUMBER OF PAGES Approximately 100
Approved for release; distribution unlimited.		15. SECURITY CLASS. (of this report) UNCLASSIFIED
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dam Safety, Lake, Dam Inspection, Private Dams		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report was prepared under the National Program of Inspection of Non-Federal Dams. This report assesses the general condition of the dam with respect to safety, based on available data and on visual inspection, to determine if the dam poses hazards to human life or property.		

41253

522

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)



SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)



DEPARTMENT OF THE ARMY  
 ST. LOUIS DISTRICT, CORPS OF ENGINEERS  
 210 TUCKER BOULEVARD, NORTH  
 ST. LOUIS, MISSOURI 63117

REPLY TO  
 ATTENTION C-

SUBJECT: BoCo Mo Dam (Mo. 10893) Phase I Inspection Report

This report presents the results of field inspection and evaluation of the BoCo Mo Dam (Mo. 10893).

It was prepared under the National Program of Inspection of Non-Federal Dams.

This dam has been classified as unsafe, non-emergency by the St. Louis District as a result of the application of the following criteria:

- 1) Spillway will not pass 50 percent of the Probable Maximum Flood
- 2) Overtopping could result in dam failure. *and*
- 3) Dam failure significantly increases the hazard to loss of life downstream

**SIGNED**

SUBMITTED BY: \_\_\_\_\_  
 Chief, Engineering Division

**07 OCT 1980**  
 \_\_\_\_\_  
 Date

**SIGNED**

APPROVED BY: \_\_\_\_\_  
 Colonel, CE, District Engineer

**08 OCT 1980**  
 \_\_\_\_\_  
 Date

*[Faint administrative routing stamp with illegible text]*

*A*

*P*

BoCo Mo DAM  
BOONE COUNTY, MISSOURI

MISSOURI INVENTORY NO. 10893

PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM

PREPARED BY  
CONSOER, TOWNSEND AND ASSOCIATES, LTD.  
ST. LOUIS, MISSOURI  
AND  
PRC ENGINEERING CONSULTANTS, INC.  
ENGLEWOOD, COLORADO  
A JOINT VENTURE

UNDER DIRECTION OF  
ST. LOUIS DISTRICT, CORPS OF ENGINEERS  
FOR  
GOVERNOR OF MISSOURI

SEPTEMBER 1980

PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM

Name of Dam: BoCo Mo Dam, Missouri Inv. No. 10893  
State Located: Missouri  
County Located: Boone  
Stream: The Slacks Branch of Perche Creek  
Date of Inspection: June 2, 1980

Assessment of General Condition

BoCo Mo Dam was inspected by the engineering firms of Consoer, Townsend and Associates, Ltd. and PRC Engineering Consultants, Inc. (A Joint Venture) of St. Louis, Missouri according to the U. S. Army Corps of Engineers "Engineer Regulation No. 1110-2-106" and additional guidelines furnished by the St. Louis District of the Corps of Engineers. Based upon the criteria in the guidelines, the dam is in the high hazard potential classification, which means that loss of life and appreciable property damage could occur in the event of failure of the dam. Within the estimated damage zone of four miles downstream of the dam are three dwellings, one building, two barns, and one trailer all of which may be subjected to flooding, with possible damage and/or destruction, and possible loss of life. BoCo Mo Dam is in the intermediate size classification since it is less than 40 feet in height but impounds more than 1,000 acre-feet of water.

Our inspection and evaluation indicates that the spillway system of BoCo Mo Dam does not meet the criteria set forth in the guidelines for a dam having the above size and hazard potential. BoCo Mo Dam, an intermediate size dam with a high hazard potential, is required

by the guidelines to be able to pass the Probable Maximum Flood without an occurrence of overtopping the dam. It was determined that the reservoir/spillway system can accommodate approximately 35 percent of the Probable Maximum Flood before overtopping of the dam occurs. Our evaluation also indicates that the reservoir/spillway system will accommodate the one-percent chance flood (100-year flood) without overtopping the dam.


The Probable Maximum Flood is defined as the flood discharge that may be expected from the most severe combination of critical meteorological and hydrologic conditions that are reasonably possible in the region.

BoCo Mo Dam and its appurtenant structures appear to be in a poor condition due to the seepage observed to the left of the service spillway outlet, which is considered to be a major deficiency, and the other deficiencies described below. The seepage is apparently occurring along the service spillway conduit due to the fact that rust colored sediment was observed in the discharge. This indicates a potential danger to the safety of both the dam and the service spillway.


Other deficiencies noted by the inspection team were as follows: two areas of possible seepage; cracks on the downstream and upstream slopes; wave erosion on the upstream berm; two areas of erosion downstream of the toe; damage to the embankment slopes due to grazing livestock and inadequate vegetative protection; problems associated with the service spillway consisting of the corrosion along the conduit and in the intake structure; the distortion of the conduit and the beads of water observed on the inside of the conduit; a need for periodic inspection by a qualified engineer; and a lack of maintenance schedule. The lack of seepage and stability analyses on record is also a deficiency that should be corrected.



It is recommended that the owner should take action to investigate the cause of seepage occurring along the service spillway and other suspected seepage areas and implement necessary corrective measures. Other deficiencies in the dam mentioned above should also be corrected without delay.



Walter G. Shifrin, P.E.





Overview of BoCo Mo Dam

NATIONAL DAM SAFETY PROGRAM

BoCo Mo DAM, I.D. No. 10893

TABLE OF CONTENTS

<u>Sect. No.</u>	<u>Title</u>	<u>Page</u>
SECTION 1	PROJECT INFORMATION . . . . .	1
	1.1 General . . . . .	1
	1.2 Description of Project . . . . .	2
	1.3 Pertinent Data . . . . .	8
SECTION 2	ENGINEERING DATA . . . . .	11
	2.1 Design . . . . .	11
	2.2 Construction . . . . .	11
	2.3 Operation . . . . .	11
	2.4 Evaluation . . . . .	12
SECTION 3	VISUAL INSPECTION . . . . .	13
	3.1 Findings . . . . .	13
	3.2 Evaluation . . . . .	20

TABLE OF CONTENTS

(Continued)

<u>Sect. No.</u>	<u>Title</u>	<u>Page</u>
SECTION 4	OPERATION PROCEDURES . . . . .	23
	4.1 Procedures . . . . .	23
	4.2 Maintenance of Dam . . . . .	23
	4.3 Maintenance of Operating Facilities . . . . .	23
	4.4 Description of Any Warning System in Effect . . . . .	23
	4.5 Evaluation . . . . .	24
SECTION 5	HYDRAULIC/HYDROLOGIC . . . . .	25
	5.1 Evaluation of Features . . . . .	25
SECTION 6	STRUCTURAL STABILITY. . . . .	29
	6.1 Evaluation of Structural Stability. . . . .	29
SECTION 7	ASSESSMENT/REMEDIAL MEASURES. . . . .	32
	7.1 Dam Assessment . . . . .	32
	7.2 Remedial Measures. . . . .	34

TABLE OF CONTENTS

(Continued)

LIST OF PLATES

	<u>Plate No.</u>
LOCATION MAP . . . . .	1
PLAN AND ELEVATION OF DAM . . . . .	2
EMBANKMENT SECTION AND SPILLWAY PROFILE . . . . .	3
GEOLOGIC MAP . . . . .	4-5
SEISMIC ZONE MAP . . . . .	6
LETTER CONCERNING THE GEOLOGY NEAR THE DAMSITE . . . . .	7-9

APPENDICES

- APPENDIX A - PHOTOGRAPHS
- APPENDIX B - HYDROLOGIC AND HYDRAULIC COMPUTATIONS

PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM

BoCo Mo DAM, Missouri Inv. No. 10893

SECTION 1: PROJECT INFORMATION

1.1 General

a. Authority

The Dam Inspection Act, Public Law 92-367 of August, 1972, authorizes the Secretary of the Army, through the Corps of Engineers, to initiate a national program of dam inspections. Inspection for BoCo Mo Dam was carried out under Contract DACW 43-80-C-0094 between the Department of the Army, St. Louis District, Corps of Engineers, and the engineering firms of Consoer, Townsend & Associates, Ltd., and PRC Engineering Consultants, Inc. (A Joint Venture), of St. Louis, Missouri.

b. Purpose of Inspection

The visual inspection of BoCo Mo Dam was made on June 2, 1980. The purpose of the inspection was to make a general assessment regarding the structural integrity and operational adequacy of the dam embankment and its appurtenant structures.

c. Scope of Report

This report summarizes available pertinent data relating to the project, provides an account of visual observations made during the field inspection, gives an assessment of hydrologic and hydraulic conditions at the site, presents an assessment of the

structural adequacy of the various project features and evaluates the general condition of the dam with respect to safety.

Subsurface investigations, laboratory testing and detailed analyses were not within the scope of this study. No warranty as to the absolute safety of the project features is implied by the conclusions presented in this report.

It should be noted that in this report reference to left or right abutments is viewed as looking downstream. Where left abutment or left side of the dam is used in this report, this also refers to the southeast abutment or side, and right abutment or right side to the northwest abutment or side.

d. Evaluation Criteria

The inspection and evaluation of the dam is performed in accordance with the U.S. Army Corps of Engineers "Engineer Regulation No. 1110-2-106" and additional guidelines furnished by the St. Louis District office of the Corps of Engineers for Phase 1 Dam Inspection.

1.2 Description of the Project

a. Description of Dam and Appurtenances

The following description is based upon observations and measurements made during the visual inspection and from telephonic conversations with Mr. Kenneth Mertens of Mertens Construction Company of Fulton, Missouri and Mr. Bill Crockett of Williams and Works Engineering Firm of Columbia, Missouri. Mertens Construction Company constructed the dam. Williams and Works did the planning, the preliminary design of the dam, and some of the surveying at the damsite. No final design drawings for the dam or appurtenant structures were available and the design engineer for the project is unknown.

The dam is a homogeneous, rolled earthfill structure with a straight alignment between earth abutments. Photos 1 through 3 show views of the embankment. The top of dam is 16-foot wide, 912 feet long, and was found approximately level from the left abutment/embankment contact to the service spillway, located approximately 475 feet to the right of the left abutment. From this point, the top of dam slopes slightly upward to the right side of the embankment and the difference in elevation between the lowest and the highest points is approximately 1.5 feet (see Plate 2). The minimum elevation of the top of dam is approximately 705 feet above mean sea level (M.S.L.). The maximum structural height of the dam is 38.5 feet. The upstream and downstream slopes were measured as 1 vertical to 2 horizontal (1V to 2H). A berm exists on the upstream slope of the dam at an elevation of 696.5 feet above M.S.L. The width of the berm varied from 8 feet on the left side to 19 feet on the right side. According to Mr. Mertens, a 12- to 14-foot wide core trench was excavated into bedrock under the embankment.

The dam has two spillways; one is the service spillway, which is a drop inlet type of structure, and the other is the emergency spillway, comprising an overflow section formed into the right side of the dam. The service spillway basically consists of a horizontal inlet opening (with a crest level about 8.5 feet below the minimum elevation of the top of dam), a drop of approximately 28 feet to the invert of the steel conduit, and about 185 feet of steel conduit running slightly askew through the embankment on a 1.0 to 1.5 percent slope. A steel trashrack-cattleguard sits atop the inlet opening. The combination trashrack-cattleguard consists of steel bars welded to a 5-1/2 foot diameter steel plate at the top and a 14-foot diameter ring at the bottom; it is anchored in place atop the inlet with a collar of dumped concrete around the bottom ring (see Photo 7).



The construction of the drop portion of the inlet can be divided into two parts, an upper segment and a lower segment. The upper segment approximates a cloverleaf shape (see Photo 7) and appears to be assembled from four 10-foot long semi-cylindrical sections of used, riveted boilerplate, welded together along the 10-foot vertical edges (according to Mr. Mertens, the material used in constructing the spillway was not used boilerplate but old railroad tank cars). The drop inlet structure has a maximum horizontal outside dimension of approximately 14 feet and stands with its bottom edge formed into a concrete floor. The upper segment therefore reaches from the normal water level down to the concrete floor, 10 feet below the normal water level. The lower segment is oval to about circular in shape and appears to be assembled from two or more lengths of semi-or partially-cylindrical sections of used, riveted, railroad tank car welded together to form a cylinder which is about 10 feet deep and approximately 7 feet across a diameter (see Photo 9). The top of this cylindrical enclosure is encased into the above mentioned concrete floor and the bottom appears to be weld-fitted to the top of the conduit. Therefore, this lower segment reaches from the concrete floor down to the top of the steel conduit, 11 feet below the concrete floor. The steel conduit is 80 inches in diameter and also appears to be constructed from used, riveted railroad tank cars. The conduit is laid through the approximate center of the embankment on a line  $20^{\circ}$  right skew from the normal to the dam axis and outlets into a 40- by 90-foot pool area at the toe of the embankment (see Photos 8 and 13).

The emergency spillway is an overflow section off the right side of the dam (see Photo 11). The waterway at the crest is trapezoidal in shape with a 390-foot top width, a 118-foot bottom width, and a depth of just over 3 feet. The invert elevation of the spillway crest is 1.6 feet lower than the minimum top of dam and 6.9 feet higher than the crest of the service spillway. The emergency crest was found approximately 8.3 feet higher than the reservoir water level on the day of inspection. Downstream of the crest, the defined discharge channel disappears into a very flat

configuration until a natural gully is intercepted, 100 to 150 feet downstream (see Photo 12). The axis of the spillway crest angles from the axis of the dam in an upstream direction (see Plate 2).

A low level outlet was provided for BoCo Mo Dam. The outlet consists of an 8-inch diameter steel pipe which passes through the embankment and is controlled by an 8-inch Walworth gate valve located at the downstream end of the pipe. The valve is located 12 feet to the right of the service spillway outlet (see Photo 8). The valve is housed in a 4.8-foot diameter riveted steel encasement which is itself enclosed in a 6.8-foot diameter riveted steel encasement. The two encasements are connected together by a steel plate. The 4.8-foot diameter encasement has a circular steel plate cover which is hinged at one point on the perimeter (see Photo 14).

b. Location

BoCo Mo Dam is located in Boone County of the State of Missouri on the Slacks Branch of Perche Creek which flows into the Missouri River. The dam is located approximately 6 miles north of Columbia and 1.5 miles west of the small community of Hinton. The dam is located in the northeast quarter of Section 10 of Range 13 West, Township 49 North as shown on the Browns, Missouri Quadrangle (7.5 minute series) sheet.

c. Size Classification

The BoCo Mo Dam reservoir impoundment is less than 50,000 acre-feet but more than 1,000 acre-feet which would classify it as an "intermediate" size dam. The maximum height of the dam is less than 40 feet and greater than 25 feet which classifies it classified as a "small" size dam. The size classification is determined by either the storage or height, whichever gives the larger size category. Therefore, the size classification is determined to fall within the "intermediate" category, according to the "Engineer

Regulation No. 1110-2-106, Appendix D" by the U.S. Department of the Army, Office of the Chief Engineer.

d. Hazard Classification

The dam has been classified as having a "high" hazard potential in the National Inventory of Dams, on the basis that in the event of failure of the dam or its appurtenances, excessive damage could occur to downstream property, together with the possibility of the loss of life. From a visual inspection of the downstream area, our findings concur with this classification. Within the estimated damage zone, which extends approximately four miles downstream of the dam, are three dwellings, one building, two barns, and one trailer (see Photos 17 and 18).

e. Ownership

BoCo Mo Dam is privately owned by Mr. Gordon Burnam. The mailing address is Mr. Gordon Burnam, P.O. Box U, Columbia, Missouri, 65205.

f. Purpose of Dam

The dam was constructed so that its reservoir could be used for recreational purposes.

g. Design and Construction History

According to Mr. Don Nicolson of Williams and Works Engineering Firm, Columbia, Missouri, their firm was responsible for much of the surveying work (i.e., centerline control stakes, offset stakes, etc.) for BoCo Mo Dam. Williams and Works also gave recommendations for the size of the core trench and emergency spillway. Mr. Nicolson also stated that their firm did not do the actual design for the dam and that he believed it was done as a "moon lighting" project. The name of the actual design engineer is not known.

BoCo Mo Dam was constructed by Mertens Construction Company of Fulton, Missouri between April and June, 1973. According to Mr. Bill Crockett of Williams and Works Engineering Firm, the dam has a volume of approximately 80,000 cubic yards. Mr. Crockett also stated that no plans or specifications were prepared for the dam.

h. Normal Operational Procedures

Normal procedure is to allow the reservoir to remain as full as possible while the water level is controlled by rainfall, runoff, evaporation and the elevation of the service spillway crest.

1.3 Pertinent Data

a. Drainage Area (square miles): . . . . . 3.18

b. Discharge at Damsite

Estimated experienced maximum flood (cfs): . . . . . Unknown

Estimated ungated spillway capacity with reservoir at top of dam elevation (cfs): . . . . . 2206

c. Elevation (Feet above MSL)

Top of dam (minimum): . . . . . 705 (Assumed)\*

Spillway crest:

Service Spillway . . . . . 696.5

Emergency Spillway . . . . . 703.4

Normal Pool: . . . . . 696.5

Maximum Experienced Pool: . . . . . Unknown

Observed Pool: . . . . . 695.1

d. Reservoir

Length of pool with water surface at top of dam elevation (feet): . . . . . 6,700

e. Storage (Acre-Feet)

Top of dam (minimum): . . . . . 1,861

Spillway crest:

Service Spillway . . . . . 854

Emergency Spillway . . . . . 1,628

Normal Pool: . . . . . 854

Maximum Experienced Pool . . . . . Unknown

Observed Pool: . . . . . 759

\* No exact elevation is known for the top of dam, therefore an assumed elevation was estimated from the Browns, Missouri U.S.G.S. Quadrangle sheet. All other elevations were determined from the assumed top of dam elevation and field measurements.

f. Reservoir Surfaces (Acres)

Top of dam (minimum): . . . . .	153
Spillway crest:	
Service Spillway . . . . .	86
Emergency Spillway . . . . .	140
Normal Pool: . . . . .	86
Maximum Experienced Pool: . . . . .	Unknown
Observed Pool: . . . . .	79

g. Dam

Type: . . . . .	Rolled, earthfill
Length: . . . . .	912 feet
Structural Height: . . . . .	38.5 feet
Hydraulic Height: . . . . .	38.5 feet
Top width: . . . . .	16 feet
Side slopes:	
Downstream . . . . .	1V to 2H
Upstream . . . . .	1V to 2H
	(from top of dam to the berm)
Zoning: . . . . .	Homogeneous
Impervious core: . . . . .	NA
Cutoff: . . . . .	A core trench with a 12 to 14 foot bottom width excavated to bedrock (Ac- cording to Mr. Mertens.)
Grout curtain: . . . . .	No
Volume: . . . . .	80,000 cu.yds. (According to Mr. Crockett)

h. Diversion and Regulating Tunnel. . . . None

i. Spillway

Type:

Service Spillway . . . . . Drop inlet,  
uncontrolled  
Emergency Spillway . . . . . Earthcut channel,  
uncontrolled

Length of crest:

Service Spillway . . . . . 44 feet  
Emergency Spillway . . . . . 118 feet

Crest Elevation (feet above MSL):

Service Spillway . . . . . 696.5  
Emergency Spillway . . . . . 703.4

j. Regulating Outlets

Type: . . . . . 8-inch diameter  
low-level outlet  
Location: . . . . . 12 feet to the  
right of the  
service spillway  
Length: . . . . . Unknown  
Closure: . . . . . 8-inch Walworth  
gate valve  
Maximum Capacity: . . . . . Unknown

## SECTION 2: ENGINEERING DATA

### 2.1 Design

No design data were available for BoCo Mo Dam. In addition, no "as-built" plans were available. The only information available was a letter from J. Hadley Williams of the Missouri Geological Survey, explaining the geologic suitability for the site. The letter is dated November 8, 1972 and is presented in this report as Plates 7 through 9.

### 2.2 Construction

No data are available concerning the construction of the dam and appurtenant structures. The following information about the construction of the dam and appurtenant structures was obtained from telephone conversations with Mr. Mertens and Mr. Crockett. The compaction of the embankment was achieved by the use of a sheepsfoot roller. No compaction tests were performed; however, it is believed that good compaction of the embankment material was achieved. The material used for the embankment was a good clay with no boulders. The core trench was excavated to bedrock. The material for the service spillway was obtained from used railroad tank cars and the service spillway was founded on the compacted embankment.

### 2.3 Operation

There were no operations records which could be made available to the inspection team for this dam.



Evaluation

## a. Availability

The availability of engineering data is poor and consists only of a letter from the Department of Natural Resources Geologic Division, dated November 8, 1972, pertaining to the Geologic suitability of the site, along with state Geologic Maps, U.S.G.S. Quadrangle sheets, and a soil survey by the Soil Conservation Service for Boone County.

## b. Adequacy

The conclusions presented in this report are based on field measurements, the available engineering data, past performance and present condition of the dam. The available data, including the field measurements taken by the field inspection team, are considered adequate to evaluate the hydraulic and hydrologic capabilities of the dam. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available, which is considered a deficiency. These seepage and stability analyses should be performed for appropriate loading conditions (including earthquake loads) and made a matter of record.

## c. Validity

The only pertinent and valid engineering data available was the letter by J. Hadley Williams pertaining to the geologic site suitability. The report was basically written for an original damsite some 500 to 600 feet downstream of the present damsite. Mr. Williams recommended that the dam be moved upstream, which it was. The report also stated that sinkholes in the Burlington Limestone bedrock were present near the original damsite. This was verified by the observation of two sinkholes 300 feet downstream of the dam (see Photo 16).

SECTION 3: VISUAL INSPECTION

3.1 Findings

a. General

A visual inspection of the BoCo Mo Dam was made on June 2, 1980. The following persons were present during the inspection:

<u>Name</u>	<u>Affiliation</u>	<u>Disciplines</u>
Mark Haynes, P.E.	PRC Engineering Consultants, Inc.	Project Engineer, Soils and Mechanical
Jerry Kenny	PRC Engineering Consultants, Inc.	Hydraulics and Hydrology
Ken Bullard, P.E.	PRC Engineering Consultants, Inc.	Hydraulics and Hydrology
Robert McLaughlin, P.E.	PRC Engineering Consultants, Inc.	Civil
Razi Quraishi, R.P.G.	PRC Engineering Consultants, Inc.	Geology
Kevin Blume	Consoer, Townsend & Assoc., Ltd.	Civil and Structural

Specific observations are discussed below.

b. Dam

The overall condition of the dam appears to be poor due to the several items of concern discussed below.

The top of dam supports a dirt access road. Tire tracks caused by vehicular traffic across the dam were observed. No tire ruts or depressions, which are generally associated with vehicular traffic across earthen structures, were seen. Evidence of a gravel surface placed on the top of dam at one time was observed. No depressions indicating a settlement of the dam were observed. The difference in elevation between the right side and the left side of the dam did not appear to be due to an instability of the embankment. The dam was most likely constructed in this way. No significant deviation in horizontal alignment was apparent. Minor surface shrinkage cracks were observed, however, no major cracking was observed on the top of dam. No evidence of the dam ever being overtopped was observed.

The upstream slope of the dam has no riprap protection. Consequently, some erosion has occurred on the upstream side of the berm due to wave action. The portion of the slope above the water surface and the berm itself have a tall grass cover. The grass cover is not dense enough to adequately protect the slope from surface runoff. Some minor erosion due to surface runoff was observed; however, no large erosion gullies were noted. Considerable damage to the surface of the embankment slopes has been caused by grazing livestock. Small 6-inch diameter depressions and shallow surface sloughs due to the livestock activity were observed. Longitudinal and transverse cracks were observed over most of the slope. The cracks were noncontinuous and some were measured up to 8 inches deep, 1/2-inch wide, and 6-feet long. No bulges or depressions were observed on the slope.

The downstream slope of the dam has the same problems as the upstream slope with the tall but inadequate grass cover, the minor surface runoff erosion, the damage caused by the grazing livestock and the longitudinal and transverse cracks as described above (see Photo 5). Flowing seepage and two areas of probable seepage were observed in three different locations. The flowing seepage was observed a few feet to the left of the service spillway outlet (see Photo 6). The rate of flow was estimated at less than 1 gallon per minute (gpm). The discharge did not appear to be transporting soil particles. It is unknown whether the seepage was through the embankment or along the spillway pipe. A boggy area measuring approximately 70 feet long was observed to the left of the service spillway discharge channel and downstream of the toe of the dam (see Photo 3). No measurable flowing seepage was observed in this area. The second area of probable seepage was observed approximately 100 feet to the right of the service spillway and downstream of the toe. In this area, boggy ground and standing water were observed. It appeared that the presence of water in this area is fairly recent because the area contained fairly sparse vegetation generally associated with moist, boggy areas and only small cattails were observed. No measurable flowing seepage was observed in this area. No bulges or depressions were apparent on the slope. No trees were observed on the embankment. Two erosion gullies were observed downstream of the embankment one on each side of the dam (see Photos 3 and 4). The largest gully is located on the right side of the dam. It measured approximately 5 to 6 feet deep and 6 feet wide.

Both abutments slope gently upward from the top of dam. No instabilities or seepage were observed on either abutment. Erosion gullies were observed on the right upstream side of the abutment near the reservoir. The erosion did not appear to affect the safety of the dam or abutment.

No rodent activity was apparent on either the embankment or the abutments.

c. Project Geology and Soils

(1) Project Geology

The damsite is located on the Slacks Branch of Perche Creek in the Dissected Till Plains Section of the central Lowland Physiographic Province. Loess-mantled Kansas drift covers the surface of most of the Dissected Till Plains Section. This section is distinguished from the Young Drift Section to the north and from the Till Plains on the east by the stage it has reached in the post-glacial erosion cycle. Broadly generalized, this section is a nearly flat till plain, submature to mature in its erosion cycle.

The topography at the damsite is rolling to hilly with strip mining stockpiles in the vicinity of the damsite. Elevation of the ground surface ranges from 800 feet above M.S.L. (one mile east of the site) to about 700 feet above M.S.L. at BoCo Mo Dam. The reservoir slopes are generally  $10^{\circ}$  to  $20^{\circ}$  from horizontal. The area near the damsite is covered with slope wash deposits of glacial-fluvial and loess origin consisting of yellowish brown to gray, silty clay with brown shale fragments.

The regional bedrock geology beneath the glacial outwash deposit in the damsite, shown on the Geologic Map of Missouri (1979) (see Plate 4), consists of Pennsylvanian age rocks of the Marmaton-Cherokee Group (cyclic deposits of shale, limestone, and sandstone), Mississippian age Burlington Limestone (cherty, grayish brown, sandy limestone), Devonian age rocks of the Sulphur Springs Group (Glen Park Limestone, Grassy Creek Shale) and Ordovician rocks consisting of St. Peter Sandstone and Powell Dolomite. The predominant bedrock underlying glacial-fluvial deposits in the vicinity of the damsite are the coal beds and the Burlington Limestone. Two sinkholes with moderately progressive solution activity were observed nearly 300 feet downstream from the dam (see Photo 16). No outcropping of bedrock was seen at the damsite. The inlet and outlet areas of the Slacks Branch contain Quaternary alluvium.

No faults have been identified in the vicinity of the damsite. The closest trace of a fault to the damsite is the Fox Hollow Fault nearly 20 miles south of the site. The Fox Hollow Fault had its last movement in post-Mississippian time. Thus, the fault appears to have no effect on the dam.

BoCo Mo Dam consists of a homogeneous earthfill embankment, a cloverleaf shaped drop inlet service spillway with a metal outlet pipe located near the midsection of the embankment and an emergency spillway located at the right abutment end of the embankment.

No boring logs or construction reports were available which would indicate foundation conditions encountered during the construction. Based on conversations with the construction contractor, Mr. Mertens, the embankment rests on bedrock which may be of Burlington Limestone of Mississippian age. The cloverleaf shaped drop inlet service spillway and the outlet pipe rests on the compacted embankment, according to Mr. Mertens. The emergency spillway was cut into the compacted embankment fill.

## (2) Project Soils

According to the "Soil Survey for Boone County, Missouri" published by the Soil Conservation Service in 1962, the common soils in the general area of the dam belong to the White Oak Land:Lindley - Hatton association. The Boone County soil maps show the soil at the damsite consisting of a narrow strip of the Westerville silt loam along the creek channel with the Mandeville silt loam, the Lindley loam, and the Lindley clay loam laying on both sides of the Westerville silt loam. These soils are basically formed from glacial till, alluvium, and weathered limestone. The Lindley soil is generally quite susceptible to erosion. If the Lindley soil type was used in the embankment, the potential of failure of the embankment would be increased due to erosion during overtopping.

Materials removed from the upstream and downstream slopes of the embankment appeared to be a mottled, yellowish brown and gray, silty clay with some fine to medium sand. Based upon the Unified Soil Classification System, the soil would probably be classified as a CL. This soil type generally has the following characteristics: an impervious soil with a coefficient of permeability less than 1.0 foot per year, medium shear strength, and a high resistance to piping.

d. Appurtenant Structures

(1) Service Spillway

The service spillway conduit has apparently been in place for several years and the following observations were noted. The combination trashrack-cattleguard is set over the inlet opening with its bottom edge partially held in place by dumped, unvibrated concrete. There is no protective coating present and rust reaction is happening over the entire structure (see Photo 7). The upper segment of the inlet drop structure is approximately 10 feet high with its bottom edge held fast by the concrete floor; the vertical edges of the semi-cylindrical sections appear to be welded together to form seams. Since this upper segment acts as a retaining structure for 10 feet of fill, the seams are somewhat bowed out of vertical and are severely corroded; it looks as though the outside surfaces are covered by what appears to be an epoxy coating except at the edges; here from welding, cutting, etc. the epoxy coating is slightly peeled back (see Photo 10). The crest of the inlet was approximately 1.5 feet higher than the reservoir water level on the day of the inspection, therefore no flow through the conduit was observed. The lower segment of the drop inlet structure extends from the concrete floor to a point approximately 11 feet down where it is apparently welded to the top of the conduit (see Photo 9). The shape of this part approaches a circular cylinder, however, it is difficult to determine the exact shape or condition of this segment. (It appears circular on top and oval on the bottom). The conduit

itself carries the flow under the embankment to the downstream channel. The inside of the conduit exhibited a fair degree of corrosion and sweating (i.e., beads of water resting on the top area of the conduit surface), but as previously mentioned, there was no flow in the conduit; however, there was a pool of water at the outlet end, perhaps supplied by the various potential seepage spots nearby (see Photo 8). The flowing seepage mentioned in Section 3.1b, immediately adjacent to the conduit outlet (see Photos 6 and 8), was discharging a rust colored sediment, albeit at the rate of less than one gallon per minute. Although the outlet of the pipe appears round, the view of the perimeter from deep inside the pipe, looking out, is that of an oval or bowed shape for a partial length of the pipe, i.e. for that portion under the top of dam. No debris was accumulated in or around the trashrack-cattleguard structure.

#### (2) Emergency Spillway

The emergency spillway, located just off the right side of the dam, has a crest and flat V-shaped discharge channel, both of which have little or no grass cover protection or other surface erosion control measures. The slope of the discharge channel is approximately 9 percent and it has a clay surface (see Photos 11 and 12). There was also some erosion noted in the emergency spillway approach area.

#### (3) Outlet Works

The 8-inch low level outlet is in an operable condition. The gate valve was operated on the day of the inspection, and it operated freely. The entire system appeared to operate as originally intended. The gate stem of the valve was bent at an angle of approximately 20° from vertical. This did not appear to hamper the operation of the valve. No leakage through the valve or seepage along the pipe were observed. Some minor surface rusting was observed on the gate stem and the hand wheel. The intake of the system was not located due to the water level of the reservoir.



e. Reservoir Area

The reservoir water surface elevation at the time of the inspection was 695.1 feet above M.S.L.

The surface area of the reservoir at normal water level is about 86 acres. The rim appears to be stable with no severe erosion problems. A localized erosional slump approximately 20-feet wide and 5-feet high was observed just upstream of the dam on the left abutment. Erosional gullies due to the surface runoff were observed upstream of the dam in the right abutment area. Some minor erosion due to wave action was observed along the shoreline. The erosional problems do not appear to be detrimental to the stability of the reservoir or the embankment. The land around the reservoir slopes gently to the rim and is grass and/or tree covered. There are a few homes built in close proximity to the reservoir (see Photo 15).

f. Downstream Channel

The downstream channel is well defined. The channel has a bottom width of about 5 feet and has side slopes of 1V to 2.5H on the right and 1V to 5H on the left. The channel is approximately 2 feet deep, but is obstructed with trees (see Photo 13). The floodplain outside of the channel is fairly wide near the damsite and is grass covered with some trees.

3.2 Evaluation

The visual inspection revealed the following condition which was felt to pose a threat to the safety of the structure and would warrant prompt attention.

The flowing seepage observed to the left of the service spillway outlet poses a potential danger to the structural integrity of the dam and the service spillway. The source of the seepage is unknown, however, it appears that the water is flowing along the outside of the conduit of the service spillway. The evidence which points to this conclusion is the sweating condition on inside of the conduit and the

rust colored sediment observed in the discharge. The rust colored sediment indicates that possibly the outside of the conduit is undergoing some deterioration due to corrosion. Holes could develop in the conduit due to the corrosion; in which case, fill material could wash into the pipe due to the seepage, or the flow through the conduit would erode the material exposed by the holes. Such progressive erosion, if it occurs, could cause collapse of the embankment material around the conduit leading to its eventual failure.

The following conditions were observed which could affect the safety of the dam.

1. The two probable seepage areas observed downstream of the toe could have an adverse effect on the stability and safety of the embankment. If the rate of seepage were to increase, it is possible that the seepage could transport soil particles which would cause piping of the embankment material. This condition could lead to the eventual failure of the embankment.

2. The wave erosion on the upstream berm and the areas of surface runoff erosion downstream of the toe do not appear to affect the structural stability of the dam in their present condition. However, continual erosion due to wave action can only be detrimental to the stability of the dam. The erosion downstream of the toe of the dam, if allowed to continue, could encroach upon the toe and endanger the safety of the dam.

3. It is unknown whether the cracks observed on the upstream and downstream slopes are indicative of shrinkage, slope movement or foundation settlement. However, judging from their extent and location, the cracks were probably caused by shrinkage.

4. The damage to the downstream and upstream slopes due to the grazing livestock and to the lack of an adequate grass protection against surface runoff does not adversely affect the stability of the dam in its present condition.

5. The corrosion due to the lack of protective covering occurring along the seams of the cloverleaf portion of the drop inlet section and along the outlet conduit, plus the corrosion potentially occurring on the walls of the fill side of the drop inlet structure could lessen the structural integrity of the spillway to such a degree that it could not retain the presently imposed fill. This condition, if it eventually occurred, would cause at least a partial obstruction, if not a full closure of the service spillway.

6. The distortion of the shape of the conduit seems to be taking place under the maximum section of the dam. The weight of the embankment could have a crushing effect upon the conduit, especially if the used tank cars were originally designed to take tension forces but not compression forces. Since the conduit has been in place for about 7 years, it would seem that this condition could only progressively worsen in the future causing damage to both the conduit and the embankment.

It was also noted that there was no flow entering the inlet to the service spillway but there were boggy and seepage areas along the toe of the dam, sweating on the inside top of the conduit, and a 90-foot by 40-foot outlet pool (see Photo 13) on the day of the inspection.

7. No accumulation of debris was observed in or around the trashrack-cattleguard structure on the day of the inspection. Nevertheless, floating debris could accumulate in the future, which could hamper the normal operation of the spillway.

8. The gate valve for the low level outlet appeared to operate properly and no major problems with the drain were observed. However, the condition of the pipe through the dam is unknown and deterioration of the pipe could cause considerable damage to the dam. Since the pipe carries full reservoir pressure, a failure of the pipe could result in internal erosion (piping) of the dam.

## SECTION 4: OPERATIONAL PROCEDURES

### 4.1 Procedures

BoCo Mo Dam was constructed to impound water for recreational use, however, it is also used for livestock watering. There are no specific operational procedures for the dam and reservoir.

### 4.2 Maintenance of Dam

The dam and appurtenant structures are maintained by workmen hired by the owner, Mr. Gordon Burnam. Cattle are allowed to graze on the slopes of the dam and, consequently, damage to slopes has occurred. However, the cattle appear to keep the vegetation from growing too tall. Several areas of erosion were observed.

### 4.3 Maintenance of Operating Facilities

The only operable facility at the damsite is the 8-inch low level gate valve. The 8-inch low level valve was tested on the day of inspection and found to be in good working order.

### 4.4 Description of Any Warning System in Effect

The inspection team is not aware of any existing warning system for this dam consisting of any electrical warning systems or manual warning notification plans.

4.5

Evaluation

Operational procedures are non-existent, and the maintenance of the dam appears to be less than adequate. The remedial measures outlined in Section 7 should be undertaken to improve the condition of the dam.

## SECTION 5: HYDRAULIC/HYDROLOGIC

### 5.1 Evaluation of Features

#### a. Design Data

The watershed area of the BoCo Mo Dam upstream from the dam axis consists of approximately 2,035 acres. The watershed area consists mostly of pasture and range land with some wooded areas. Land gradients in the watershed average roughly 1 percent. The BoCo Mo Dam Reservoir is located on the Slacks Branch of Perche Creek. The reservoir is about 3.4 miles upstream from the confluence of Slacks Branch tributary and the Perche Creek. The watershed measures approximately 3 miles at its longest arm. A drainage map showing the watershed and the downstream hazard zone is presented on Plates 1A and 1B in Appendix B.

Evaluation of the hydraulic and hydrologic features of BoCo Mo Dam was based upon criteria set forth in the Corps of Engineers' "Engineer Regulation No. 1110-2-106" and additional guidance provided by the St. Louis District of the Corps of Engineers. The Probable Maximum Flood (PMF) was calculated from the Probable Maximum Precipitation (PMP) using the methods outlined in the U.S. Weather Bureau Publication, Hydrometeorological Report No. 33. The probable maximum storm duration was set at 48 hours, and the storm rainfall distribution was based upon criteria given in the Corps of Engineers' EM 1110-2-1411 (Standard Project Storm). The Soil Conservation Service (SCS) method was used for deriving the unit hydrograph, utilizing the Corps of Engineers' computer program HEC-1 (Dam Safety Version). The unit hydrograph parameters are presented in Appendix B. The SCS method also was used for determining the loss rate. The hydrologic soil group of the watershed was determined by use of published soil maps. The hydrologic soil group of the watershed and the SCS curve number are presented in Appendix B. The curve number, unit hydrograph parameters, the PMP index rainfall and the percentages for various durations were the

direct input to the HEC-1 (Dam Safety Version) computer program used to obtain the PMF hydrograph. The computed peak inflows of the PMF and one-half of the PMF are 16,400 cfs and 8,200 cfs, respectively.

Both the PMF and the one-half PMF inflow hydrographs were routed through the reservoir by the Modified Puls Method also utilizing the HEC-1 (Dam Safety Version) computer program. A storm of 50 percent of the PMF preceded the PMF and a storm of 25 percent of the PMF preceded the one-half PMF, each by four days. The reservoir was assumed at the mean annual high water level at the beginning of the antecedent storm. The mean annual high water level for BoCo Mo Lake was estimated to be at the crest of the service spillway. The antecedent 50 percent PMF storm, when routed through the reservoir, will leave the reservoir at approximately the same elevation as the crest of the service spillway (see Appendix B) at the end of the four day period. Thus, the reservoir was assumed at the crest level of the service spillway at the start of the routing computation for the PMF, one-half of the PMF and other PMF ratio floods. The peak outflow discharges for the PMF and one-half of the PMF are 15,178 and 5,970 cfs, respectively. Both the PMF and one-half of the PMF when routed through the reservoir resulted in overtopping of the dam.

The sizes of physical features, utilized to develop the stage-outflow relation for the spillway and overtopping of the dam, were taken from field notes and sketches prepared during the field inspection. The reservoir elevation-area data were obtained from the U.S.G.S. Browns, Missouri Quadrangle topographic map (7.5 minute series). The reservoir elevation-area curve and the spillway and overtop rating curve are presented as Plates 2 and 3, respectively, in Appendix B.

From the standpoint of dam safety, the hydrologic design of a dam must aim at avoiding overtopping. Overtopping is especially dangerous for an earth dam because of its erodable characteristics. The safe hydrologic design of an embankment dam requires a spillway discharge capability combined with an embankment height that can handle a very large and exceedingly rare flood without

overtopping.

The Corps of Engineers designs dams to safely pass the Probable Maximum Flood that could be generated from the dam's watershed. This is the generally accepted criterion for major dams throughout the world and is the standard for dam safety where overtopping would pose any threat to human life. Accordingly, the hydrologic requirement for safety for this dam is the capability to pass the Probable Maximum Flood without overtopping.

b. Experience Data

No records of reservoir stage or spillway discharge are maintained for this site. Nevertheless, there was no evidence of the dam ever having been overtopped.

c. Visual Observations

Observations made of the spillways during the visual inspection are discussed in Section 3.1d and evaluated in Section 3.2. The trashrack-cattleguard structure over the service spillway inlet appeared sufficiently adequate to prevent clogging of the pipe by floating debris.

d. Overtopping Potential

As indicated in Section 5.1a, both the Probable Maximum Flood and one-half of the Probable Maximum Flood when routed through the reservoir, resulted in overtopping of the dam. The peak outflow discharges for the PMF and one-half of the PMF are 15,178 and 5,970 cfs, respectively. The maximum capacity of the spillway just before overtopping of the dam is 2206 cfs. The PMF overtopped the dam by 2.39 feet and one-half of the PMF overtopped the dam by 1.02 feet. The total duration of flow over the lowest point on the top of dam is 5.75 hours during the PMF and 3 hours during the occurrence of one-half of the PMF. The spillway/reservoir system of BoCo Mo Dam is capable of accommodating a flood equal to approximately 35 percent of the PMF just before overtopping the dam. The reser-



voir/spillway system of BoCo Mo Dam will accommodate the one-percent chance flood (100-year flood) without overtopping. Due to the lack of adequate vegetative cover and the high flow velocities, the silty clay soil in the emergency spillway may be susceptible to erosion. The downstream slope of the embankment may also be susceptible to erosion during overtopping of the dam.

The failure of the dam could cause extensive damage to the property downstream of the dam and possible loss of life. The estimated damage zone extends approximately four miles downstream of the dam. There are three dwellings, one building, two barns, and one trailer within the damage zone.

## SECTION 6: STRUCTURAL STABILITY

### 6.1 Evaluation of Structural Stability

#### a. Visual Observations

There were no major signs of settlement or distress observed on the embankment or foundation during the visual inspection. The flowing seepage and the two areas of probable seepage observed in the three different locations downstream of the toe could be detrimental to the stability of the embankment. Nevertheless, the seepage did not appear to constitute an unsafe condition at this time. It was not apparent whether the cracks on the upstream and downstream slopes were due to shrinkage, slope movement, or foundation settlement. Judging from their extent and location, the cracks were probably caused by shrinkage. Nevertheless, further investigation of the cracks is warranted. The erosional problems due to wave action and surface runoff on the upstream berm and downstream of the toe, respectively, and the damage to the downstream and upstream slope due to grazing livestock and inadequate grass cover do not endanger the structural integrity of the embankment in their present condition. Nevertheless, continual aggravation could only have an adverse effect on the stability of the embankment. In the absence of seepage and stability analyses, no quantitative evaluation of the structural stability can be made.

Due to the corrosion taking place both along the conduit and at the intake structure, the distortion of the conduit under the center of the embankment, and the apparent seepage path along the outside of the conduit, the service spillway could not be considered as structurally stable.

The low level outlet did not exhibit signs of structural instability.

b. Design and Construction Data

No design computations pertaining to the embankment were uncovered during the report preparation phase. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available. No embankment or foundation soil parameters were available for carrying out a conventional stability analysis on the embankment. No construction data or specifications relating to the degree of embankment compaction were available for use in a stability analysis.

c. Operating Records

No operating records are available relating to the stability of the dam or appurtenant structures. The water level on the day of inspection was 17 inches below the crest of the service spillway, and it is assumed that the reservoir remains close to full at all times. The low level drain is in operable condition and was operated on the day of the inspection.

d. Post Construction Changes

No post construction changes to the embankment are known to exist which will affect the structural stability of the dam.

e. Seismic Stability

The dam is located in Seismic Zone 1 (see Plate 6), as defined in "Recommended Guidelines for Safety Inspection of Dams", prepared by the Corps of Engineers, and will not require a seismic stability analysis. An earthquake of the magnitude which would be expected in Seismic Zone 1 will not cause significant distress to a well designed and constructed earth dam. Available literature

indicates that no active faults exist near the vicinity of the  
damsite.

## SECTION 7: ASSESSMENT/REMEDIAL MEASURES

### 7.1 Dam Assessment

The assessment of the general condition of the dam is based upon available data and the visual inspection. Detailed investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

It should be realized that the reported condition of the dam is based upon observations of field conditions at the time of the inspection along with data available to the inspection team.

It is also important to realize that the condition of a dam depends upon numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be assurance that an unsafe condition would be detected.

#### a. Safety

The spillway capacity of BoCo Mo Dam is found to be "Seriously Inadequate". The spillway/reservoir system will accommodate about 35 percent of the PMF without overtopping the dam. The safety of the embankment will be in jeopardy if the dam is overtopped. The embankment itself would be susceptible to erosion due to the high velocity of flow on its downstream slope which could lead to an eventual failure of the dam. The present erosion downstream of the toe of the dam, if left unattended, would be further eroded in the event the dam is overtopped which would further jeopardize the safety of the dam.

The dam and appurtenant structures appear to be in a poor condition and a quantitative evaluation of the safety of the embankment could not be made in view of the absence of seepage and stability analyses. The present embankment and appurtenant structures, however, appear to have performed satisfactorily since their construction without any apparent failures. There was no evidence observed of the dam ever being overtopped. The safety of the dam can be improved if the deficiencies described in Section 3.2 and 6.1a are properly corrected as described in Section 7.2b.

b. Adequacy of Information

Pertinent information relating to the design of the dam and appurtenant structures is completely lacking. The conclusions presented in this report are based on field measurements, past performance, and the present condition of the dam. Information on the design hydrology, hydraulic design, and the operation and maintenance of the dam, as well as seepage and stability analyses was not available for review. Lack of seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" is considered a deficiency.

c. Urgency

The items recommended in paragraph 7.2a and the first item in paragraph 7.2b should be pursued on a high priority basis. The remaining remedial measures recommended in Paragraph 7.2 should be accomplished within a reasonable period of time.

d. Necessity for Phase II Inspection

Based upon results of the Phase I inspection, and assuming that the remedial measures recommended in Paragraph 7.2 are undertaken, a Phase II inspection is not felt to be necessary.

## 7.2 Remedial Measures

### a. Alternatives

There are several general options which may be considered to reduce the possibility of dam failure or to diminish the harmful aspects of such a failure. Some of these options are:

1. Increase the spillway capacity to pass the PMF without overtopping the dam.

2. Increase the height of the dam in order to pass the PMF without overtopping the dam; an investigation should also include studying the effects on the structural stability of the present embankment. The overtopping depth during the occurrence of the PMF, stated in Section 5.1d, is not the required or recommended increase in the height of the dam.

3. A combination of 1 and 2 above.

### b. O & M Procedures

1. Further investigation of the flowing seepage should be undertaken to determine the cause and the seriousness of the seepage. The area should also be monitored to determine if the seepage is transporting embankment material. The investigation should be carried out under the direction of a qualified professional engineer.

2. The two areas of probable seepage should be monitored to detect any changes in turbidity, location, or quantity. Any changes should be reported and investigated further.

3. The observed cracking on the upstream and downstream slopes should be further investigated to ensure that it is not symptomatic of distress in the slopes or foundation. Large cracks should be properly repaired.

4. The wave erosion on the upstream berm and the two areas of erosion due to surface runoff downstream of the toe should be properly repaired and adequately protected from further damage.
5. The damage to the downstream and upstream slopes due to the grazing livestock and to the lack of an adequate grass cover should be properly repaired and adequately protected from further damage. The grazing livestock should be prevented access to the embankment. The vegetation on the slopes should be maintained periodically and large vegetation, such as bushes and trees, should be prevented from growing on the slope.
6. The corrosion of the upper segment of the inlet structure should be closely watched and monitored to detect any potential problems associated with this condition; also the interior of the spillway conduit should be watched and monitored on a periodic basis for a worsening of the distorted section of the conduit which could indicate a failure of the conduit and the "beading" condition on the upper surfaces of the conduit interior which indicates possible seepage along the pipe. Any worsening of these conditions should be investigated further in greater detail by a qualified engineer. Repairs should be made when deemed necessary.
7. The gate valve for the low level outlet should be properly maintained as recommended by the valve manufacturer and operated periodically. The area around the pipe should also be monitored to detect any potential problems which when detected should be investigated and properly repaired.
8. The trashrack-cattleguard structure should be maintained free of any accumulation of debris.





9. Seepage and stability analyses should be performed by a professional engineer experienced in the design and construction of earth dams.

10. The owner should initiate the following programs:

(a) Periodic inspection of the dam by a professional engineer experienced in the design and construction of earthen dams.

(b) Set up a maintenance schedule and log all visits to the dam for operation, repairs and maintenance.


PLATES




POLYCONIC PROJECTION

LOCATION MAP - BOCO MO DAM

MO. 10893




PLAN




ELEVATION

SCALE:  
 HORIZ. 1" = 200'  
 VERT. NO SCALE



MAXIMUM SECTION

SCALE:  
HORIZ. 1" = 40'  
VERT. 1" = 20'




SECTION A-A

EMERGENCY SPILLWAY PROFILE

SCALE:  
HORIZ. 1" = 40'  
VERT. 1" = 10'

① REFERENCE POINT SHEET 1 OF 2

BOCO MO DAM (MO. 10893)  
MAXIMUM SECTION OF EMBANKMENT  
AND EMERGENCY SPILLWAY PROFILE  
(SHEET 2 OF 2)



⊕ LOCATION OF DAM

NOTE: LEGEND OF THIS DAM IS ON PLATE 5


REFERENCE:

GEOLOGIC MAP OF MISSOURI  
 DEPARTMENT OF NATURAL RESOURCES  
 MISSOURI GEOLOGICAL SURVEY  
 KENNETH H. ANDERSON, 1979

REGIONAL GEOLOGICAL MAP  
 OF  
 BOCO MO DAM

LEGEND

<u>PERIOD</u>	<u>SYMBOL</u>	<u>DESCRIPTION</u>
QUATERNARY	Qal	ALLUVIUM: SAND, SILT, GRAVEL
PENNSYLVANIAN	{ Pu	PENNSYLVANIAN UNDIFFERENTIATED
	{ Pm	MARMATON GROUP: CYCLIC DEPOSITS OF SHALE, LIMESTONE AND SANDSTONE
	{ Pcc	CHEROKEE GROUP: CYCLIC DEPOSITS OF SHALE, LIMESTONE AND SANDSTONE
MISSISSIPPIAN	{ Mo	KEOKUK - BURLINGTON FORMATION: CHERTY GRAYISH BROWN SANDY LIMESTONE
	{ Mk	CHOUTEAU GROUP: NORTHVIEW, COMPTON AND BACHELOR FORMATION (LIMESTONE AND SHALE)
DEVONIAN	D	SULPHUR SPRING GROUP: BUSHBERG SANDSTONE, GLEN PARK LIMESTONE, GRASSY CREEK SHALE
ORDOVICIAN	{ Osp	ST PETER SANDSTONE
	{ Ojc	SMITHVILLE FORMATION, POWELL DOLOMITE





Boone County, Missouri

LOCATION: NE $\frac{1}{4}$  sec. 10, T. 49 N., R. 13 W., Browns Quadrangle.

GEOLOGIC SUITABILITY: Poor

GEOLOGIC SETTING:

The dam site (NW $\frac{1}{4}$  SW $\frac{1}{4}$  SE $\frac{1}{4}$  sec. 10) is located in an area where faulting has affected bedrock. The most direct evidence of this faulting is an active sinkhole near the dam site. However, bedrock exposed upstream also points out the affect of faulting. In essence, this faulting of the bedrock has caused the overlying bedrock, the coal bearing strata, to drop relatively to the underlying bedrock, a massive limestone. This underlying bedrock formation is Mississippian age Burlington limestone. This formation, while prone to sinkhole development in many areas, is not characterized by sinkholes north of Columbia. Thus, development of the sinkhole at this site is believed to be primarily associated with faulting which has intensified solutioning and enlargement of caverns that has occurred in the Burlington limestone bedrock. The overlying bedrock, exposed upstream, in which coal beds occur, is a part of lower Pennsylvanian age strata. The relatively thick limestone, the Ardmore, is underlain by the Crowburg coal. These strata which have a relative dip toward the southwest do not occur at the dam site because of the affects of faulting. Further upstream, the underlying Mississippian or Burlington limestone is again present. However, this time there is a normal sequence of bedrock with the overlying Pennsylvanian age formations on the nearby hillslopes where strip mining has taken place. Thus, no faulting or extreme dipping of rock strata occurs in this portion of the valley.

Soil characteristics change relative to the change in underlying bedrock formations. Where the Burlington or Mississippian limestone is present, the soil is a stoney clay with 50% or more stone made up of chert fragments which are residual from the weathering of the underlying limestone. Because of the irregular limestone surface soil thickness will vary from a few feet to 15 or 20 feet. Where the Pennsylvanian sediments are present, the influence of a predominately shale bedrock sequence is paramount. Here the soil cover is generally stone free. The underlying shale may be moderately weathered so that a thickness of 4 to 6 feet of clay rich material can be obtained before sound shale is encountered.

RECOMMENDATIONS:

Basically, the site is poor to consider, even for further exploration. The underlying Burlington limestone is characterized by solution openings which are formed in a random pattern. These cannot be predicted as can the solution openings in many rock formations where interconnected horizontal and vertical openings exist. The solution openings that characterized the development of sinkholes in the Burlington are not related to a definite vertical or horizontal fracture or parting plane pattern. Thus, it is essentially impossible to find an opening and consequently extremely difficult to close such an opening by grouting. The active sinkhole points out the severity in which underground solution development has taken place.


While there is the possibility of moving the dam site upstream, a leakage hazard still exists. The possible leakage or movement of water along the bedrock of the Pennsylvanian age strata would be intensified with the downstream inclination of these rock layers. The contact between the Ardmore limestone and the underlying fissile shale (slate) is a typical leakage horizon. The possibility of water moving from the exposed bedrock within the lake area downstream into the area affected by faulting cannot be discounted. If this should occur, the water leaking from the lake could move laterally even away from the valley and hinder a grout program. It should be noted, however, that grouting would be more successful in the Pennsylvanian sediments than the underlying Burlington limestone as previously described.

If further interest exists in additional exploration of the dam site, it is suggested that several holes be drilled into the bedrock along the floodplain. These holes oriented approximately parallel with the stream channel should be spaced on approximate 200 feet centers. Closer spacing should then be accomplished after the preliminary exploration was completed. Holes should be drilled from 20 to 30 feet into the underlying bedrock. It is suggested that coring would not be necessary. However, preparation should be made for pressure testing. Close monitoring of the drilling should be accomplished so that zones of water loss or soft areas, possibly affected by faulting, could also be noted.

SUMMARY:

The site is poor for a lake on Slacks Creek, although it is possible to move the dam upstream. However, if this is considered, a detailed subsurface

exploration program should be conducted. Burlington limestone is present in the stream channel upstream to the mine road crossing. Consequently, considerable extent of limestone which could cause water leakage exists and thus, the exploration steps should be thoroughly completed. Sites on tributary valleys are feasible with the exception of those valleys in the immediate area that is affected by faulting.




---

J. Hadley Williams, Chief  
Applied Engineering & Urban Geology Section  
Missouri Geological Survey  
November 8, 1972

APPENDIX A

PHOTOGRAPHS TAKEN DURING INSPECTION



BoCo Mo Dam  
Photographs

- Photo 1 - Overview of the upstream slope showing the location of the service spillway drop inlet and the wave erosion along the berm.
- Photo 2 - View of the top of dam looking toward the right abutment.
- Photo 3 - View of the downstream slope from near the service spillway outlet showing the boggy area near the outlet (right side of Photo), the large erosion gully on the left abutment (see Photo 4), and a portion of the pool at the service spillway outlet.
- Photo 4 - View of the large erosion gully on the left downstream abutment.
- Photo 5 - Closeup view of the downstream slope showing the cattle damage, some minor cracking and the inadequate grass cover.
- Photo 6 - View of the flowing seepage to the left of the service spillway outlet.
- Photo 7 - View of the drop inlet of the service spillway showing the trashrack-cattle guard combination, the dumped concrete collars and the cloverleaf shape of the inlet.
- Photo 8 - View of the outlet of the service spillway from the downstream end of the stilling pool. Note location of the low level drain to the left (in Photo) of the outlet.

- Photo 9 - View of the inside of the drop inlet of the service spillway showing the transition from the cloverleaf shaped upper segment to the circular shaped lower segment.
- Photo 10 - Closeup view of the steel lining of the service spillway drop inlet showing the corrosion along the joint and on the backside of the lining.
- Photo 11 - View of the emergency spillway control section looking toward the embankment, and area of sparse protective vegetation.
- Photo 12 - View of the emergency spillway discharge channel from the control section showing areas of sparse protective vegetation and the intersection with downstream channel tributary.
- Photo 13 - View of the downstream channel.
- Photo 14 - View of the low level drain gate valve and outlet pipe of the drain.
- Photo 15 - View of the reservoir and rim.
- Photo 16 - View of progressive sinkhole located approximately 300 feet downstream of the dam.
- Photo 17 - View of a dwelling approximately 0.3 miles downstream of the dam with the downstream channel on the right side of the photo.
- Photo 18 - View of a dwelling approximately 1.3 miles downstream of the dam with the downstream channel on the right side of the photo.

BoCo Mo Dam



Photo 1




Photo 2



BoCo Mo Dam




Photo 3



Photo 4

BoCo Mo Dam




Photo 5



Photo 6

BoCo Mo Dam



Photo 7



Photo 8

BoCo Mo Dam




Photo 9



Photo 10

BoCo Mo Dam



Photo 11



Photo 12

BoCo Mo Dam



Photo 13



Photo 14

BoCo Mo Dam



Photo 15



Photo 16

BoCo Mo Dam



Photo 17




Photo 18



APPENDIX B

HYDROLOGIC AND HYDRAULIC COMPUTATIONS



D/S HAZARD  
ZONE  
(SEE PLATE IB)

BOCO MO DAM - MO. 10893  
DRAINAGE BASIN  
AND  
DOWNSTREAM HAZARD ZONE



PRC ENGINEERING CONSULTANTS, INC.

DAM SAFETY INSPECTION - MISSOURI

SHEET NO. 1 OF 1

DAM NAME: PaCo Mo DAM


ID No.: MO 10992 JOB NO. 1263

RESERVOIR ELEVATION - AREA DATA

BY JFK DATE 20

ELEV. (M.S.L.) (Ft.)	RESERVOIR SURFACE AREA (Acres)	REMARKS
670	0	Estimated Streambed Elevation at Dam
680	20	Measured from USGS Map
690	51.5	Measured from USGS Map
696.5	86	Service Spillway Crest
703.4	140	Emergency Spillway Crest
705	153	Top of Dam (Assumed)
710	200	Interpolated from Curve
710	302	Measured from USGS Map

X



BOCO MO DAM (MO. 10893)  
RESERVOIR ELEVATION-AREA CURVE

DAM SAFETY INSPECTION / MISSOURI

SHEET NO. 1 OF 1

DAM NAME: B&amp;C No (MO 10993)

JOB NO. 1263

UNIT HYDROGRAPH PARAMETERS

BY JCK DATE 1/15/80

- 1) DRAINAGE AREA,  $A = 3.18$  sq. mi. = (2,035 acres)
- 2) LENGTH OF STREAM,  $L = (7.5 \text{ " } \times 2000' = 15,000') = 2.84$  mi.
- 3) ELEVATION AT DRAINAGE DIVIDE ALONG THE LONGEST STREAM,  
 $H_1 = 822$
- 4) ELEVATION OF RESERVOIR AT SPILLWAY CREST,  $H_2 = 696.5$
- 5) ELEVATION OF CHANNEL BED AT  $0.85L$ ,  $E_{85} = 767$
- 6) ELEVATION OF CHANNEL BED AT  $0.10L$ ,  $E_{10} = 698$
- 7) AVERAGE SLOPE OF THE CHANNEL,  $S_{AVG} = (E_{85} - E_{10}) / 0.75L = (767 - 698) / 11,250 = 0.006$
- 8) TIME OF CONCENTRATION:

A) BY KIRPICH'S EQUATION,

$$t_c = [(11.9 \times L^3) / (H_1 - H_2)]^{0.385} = [(11.9 \times (2.84)^3) / (822 - 696.5)]^{0.385} = 1.35 \text{ hr.}$$

B) BY VELOCITY ESTIMATE,

$$\text{SLOPE} = 0.006 \Rightarrow \text{AVG. VELOCITY} = 2 \text{ fps}$$

$$t_c = L/V = 15,000 \text{ ft} / (2 \text{ ft/s} \times 3600 \text{ s/hr}) = 2.08 \text{ hr}$$

USE  $t_c = 1.35$  hr

$$9) \text{ LAG TIME, } t_l = 0.6 t_c = 0.6 (1.35) = 0.81 \text{ hr}$$

$$10) \text{ UNIT DURATION, } D \leq t_l / 3 = 0.81 \text{ hr} / 3 = 0.27 \text{ hr} \quad \neq 0.083 \text{ hr.}$$

USE  $D = 0.25$  hr

$$11) \text{ TIME TO PEAK, } T_p = D/2 + t_l = 0.25/2 + 0.81 = 0.94 \text{ hr.}$$

12) PEAK DISCHARGE,

$$q_p = (484 \times A) / T_p = 484 \times 3.18 \text{ mi}^2 / 0.94 \text{ hr} = 1,637 \text{ cfs}$$

DAM SAFETY INSPECTION / MISSOURI - 1980 SHEET NO. 1 OF 1

DAM NAME: Boco Mo DAM (Mo 10893) JOB NO. 1263

CURVE NUMBER DETERMINATION BY JFK DATE 6/2/80

I) SOIL GROUP

WATERSHED SOILS IN THE BASIN CONSIST OF :

WELLER (C) - KESWICK (D) - LINDLEY (C) - MANDEVILLE (B)

GROUP C SOILS SEEM TO PREDOMINATE THE BASIN. THEREFORE,

ASSUME GROUP C SOILS FOR THE ENTIRE WATERSHED

FOR HYDROLOGIC PURPOSES.

II) COVER COMPLEX

ASSUMED LAND USE	ASSUMED HYDROLOGIC CONDITION	PER CENT AREA	CN (AMC II)
PASTURE	FAIR	60	79
WOODS	FAIR	30	73
Row Crops (Contoured)	GOOD	10	82

III) CURVE NUMBER

WEIGHTED AVERAGE CN = 78 FOR AMC II

CURVE NUMBER = 90 FOR AMC III

DAM SAFETY INSPECTION / MISSOURI SHEET NO. 1 OF 1

DAM NAME: BoCo Mo DAM (MO 10893) JOB NO. 1263

PROBABLE MAXIMUM PRECIPITATION BY JFK DATE 6/16/80

DETERMINATION OF PMP

HLB

1) Determine drainage area of the basin

D.A. = 3.18 sq. mi.

2) Determine PMP Index Rainfall (for D.A. = 200 sq. mi. & 24 hr. duration)

Location of centroid of basin,

Long. = 92° 21' 54" Lat. = 39° 3' 12"


PMP = 24.7" (from Fig. 1, HMR 33)

Zone = 7

3) Determine basin rainfall in terms of percentage of PMP Index Rainfall for various durations.  
(from Fig. 2, HMR 33)

Duration (Hrs.)	Percent of Index Rainfall (%)	Total Rainfall (Inches)	Rainfall Increments (Inches)	Duration of Increment (Hrs.)
6	100	24.7"	24.7"	6
12	120	29.6"	4.9"	6
24	130	32.1"	2.5"	12
48	140	34.6"	2.5"	24





⊕ LOCATION OF BASIN CENTROID  
 BaCo Mo DAM (MO. 10893)













FIGURE 2  
SEASONAL VARIATION  
DEPTH-AREA-DURATION RELATIONSHIPS  
Percentage to be applied to 200 square miles  
24 hour probable maximum precipitation values  
for: THE-ALL SEASON ENVELOPE



for Weir Flow:

$$Q = CLH_w^{1.5}, \quad L = 4(\pi r) = 4(\pi \cdot 3.5) = 44$$

$$C = 3.6 \text{ (assumed)}$$

$$H_w = \text{W.S. ELEV} - 696.5$$

$$= 158.4 H_w^{1.5}$$

for Orifice Flow:

$$Q = CA\sqrt{2gH_T}, \quad A = \pi r^2 = \pi (3.33)^2 = 34.9$$

$$C = 0.6$$

$$H_T = \text{W.S. ELEV} - 666.5$$

$$= 168\sqrt{H_T}$$

for Pressure Flow:

$$H_T = (K_{entrance} + K_{trashrack} + K_{band \& contraction} + K_{friction} + K_{exit}) \frac{V^2}{2g}$$

$$V = \left( \frac{2g H_T}{\sum K} \right)^{1/2}$$

DAM SAFETY INSPECTION / MISSOURI - 1980

SHEET NO. 2 OF 3

BoCo Mo DAM (MO. 10893)

JOB NO. 1263

SERVICE SPILLWAY RATING CURVE

BY JFK DATE 6/16/80

PL2

$$Q = VA \quad , \quad \text{where}$$

$$K_{\text{entrance}} = 0.5$$

$$K_{\text{trashrack}} = 0.25$$

$$K_{\text{friction}} = f \frac{L}{D}$$

( $\epsilon/D = 0.005/6.67 = 0.0007$ ,  $f = 0.0185$ : use the same  $f$  value for all three sections of pipe)

$$K_{f, \text{clover}} = f \frac{L}{D}$$

$$, \quad \frac{A}{C} = \frac{\pi r^2}{2\pi r} = \frac{r}{2}$$

$$r = 2A/C$$

$$D = 2r = 4A/C$$

$$A_{\text{clover}} = (7')^2 + 4(\pi(3.5')^2/2) = 126$$

$$= 0.0185 \frac{9.5}{4(126/44)} = 0.015$$

$$K_{f, 7'} = f \frac{L}{D}$$

$$, \quad A_{7'} = \pi(3.5')^2 = 38.48$$

$$= 0.0185 \frac{18}{7} = 0.048$$

$$K_{f, 80''} = f \frac{L}{D}$$

$$, \quad A_{80''} = 34.91$$

$$= 0.0185 \frac{185}{6.67} = 0.513$$

$$K_{\text{bend \& contraction}} = 0.5$$

$$K_{\text{exit}} = 1.0$$

$$ZK = 0.5 + 0.25 + 0.015 \left(\frac{34.9}{126}\right)^2 + 0.048 \left(\frac{34.9}{38.48}\right)^2 + 0.513 + 0.5 + 1.0$$

$$= 2.804$$

DAM SAFETY INSPECTION / MISSOURI - 1980

SHEET NO. 3 OF 3

BoCo Mo DAM (MO 10893)

JOB NO. 1263

SERVICE SPILLWAY RATING CURVE

BY JFK DATE 6/16/80  
KLEV

$$V = \left( \frac{2g H_T}{2.804} \right)^{1/2}$$

$$= 4.79 \sqrt{H_T}$$

$$Q = VA = 4.79 (34.9) \sqrt{H_T}$$

$$= 167.3 \sqrt{H_T}$$

at W.S. ELEV = 697

$$\text{weir flow, } Q = 158 (0.5)^{1.5} = 56 \text{ cfs}$$

at W.S. ELEV = 698

$$\text{weir flow, } Q = 158 (1.5)^{1.5} = 290 \text{ cfs}$$

at W.S. ELEV = 699

$$\text{weir flow, } Q = 158 (2.5)^{1.5} = 625 \text{ cfs} \quad \leftarrow \text{weir flow controls}$$

$$\text{orifice flow, } Q = 168 (29.2)^{1/2} = 908 \text{ cfs}$$

$$\text{pressure flow, } Q = 167.3 (29.2)^{1/2} = 904 \text{ cfs}$$

at W.S. ELEV = 700

$$\text{weir flow, } Q = 158 (3.5)^{1.5} = 1035 \text{ cfs}$$

$$\text{orifice flow, } Q = 168 (30.2)^{1/2} = 923 \text{ cfs}$$

$$\text{pressure flow, } Q = 167.3 (30.2)^{1/2} = 919 \text{ cfs} \quad \leftarrow \text{pressure flow controls}$$

∴ For W.S. ELEV. = 700 and above, pressure flow controls and

$$Q = 167.3 \sqrt{H_T} \quad \text{where } H_T = \text{W.S. ELEV} - 669.8$$

H-LB

AREA ①:

for  $y_{c1} < 3.1$ ,  
 $T_1 = 87.74 y_{c1} + 118$   
 $A_1 = (y_{c1} / 2) [T + 118]$

for  $y_{c1} \geq 3.1$ ,  
 $T_1 = 390$   
 $A_1 = 390 y_{c1} - 421.61$


AREA ②:

$H_2 = W.S. ELEV - 705$

AREA ③:

for  $y_{c3} < 1.5$ ,  
 $T_3 = 291.33 y_{c3}$   
 $A_3 = (T) y_{c3} / 2$

for  $y_{c3} \geq 1.5$ ,  
 $T_3 = 437$   
 $A_3 = 437 (y_{c3} - 0.75)$



$y_{c1}$	$T_1$	$A_1$	$V = \frac{Q}{A_1}$	$Q_1 = V A_1$	$V^{1/2}$	W.S. ELEV $= y_{c1} + \frac{V^2}{2g}$ $+ 703.4$	$H_2$	$Q_2$	$L_2$	$Q_2 = 4.48 H_2^{1.5}$	$y_{c3}$	$T_3$	$A_3$	$Q_3 = \left(\frac{A_3^3}{T_3}\right)^{1/3}$	$Q_{TOTAL} = Q_1 + Q_2 + Q_3$
0	0	0	0	0	0	703.4	-	-	-	-	-	-	-	-	0
0.5	161.9	700	373	261	0.22	704.1	-	-	-	-	-	-	-	-	261
1	205.7	161.9	503	815	0.89	704.8	-	-	-	-	-	-	-	-	1815
1.5	249.6	275.7	596	1644	0.55	705.5	0.5	3.01	475	505.5	0.44	116.5	23.3	59	2208.5
2	293.5	411.5	672	2765	0.70	706.1	1.1	3.64	475	2192	0.88	284.4	112.8	42.5	5382
3	381.2	748.8	795	5955	0.99	707.4	2.4	3.05	475	5382.5	1.85	437	4807	2861	14282.5

DAM SAFETY INSPECTION / MISSOURI - '980

SHEET NO. 2 OF 3

BaCo Mo DAM (MO. 10893)

JOB NO. 1263

EMERGENCY SPILLWAY AND OVERTOP RATING CURVE (cont)

BY JPK DATE 6/11/80

Yc1	T1	A1	$V_1 = \left(\frac{A_1 g}{T_1}\right)^{1/2}$	Q1 = V1 A1	$V_2 = \sqrt{\frac{g}{2g}}$	W'S ELEV $= Yc1 + V_2^2 / 2g$	H2	C1	L2	Q2 = C1 L2 H2 <sup>1.5</sup>	Yc3	T3	A3	$Q3 = \left(\frac{A_3^3}{T_3}\right)^{1/2}$	Q TOTAL = Q1 + Q2 + Q3
4	390	1138.4	9.69	11037	1.46	708.9	3.9	3.08	415	11267.9	285	437	917.7	7546	29850.9
5	390	1528.4	11.23	17169	1.96	710.4	5.4	3.09	475	18418	385	437	1351.7	13535	49122
6	390	1918.4	12.58	24144	2.46	711.9	6.9	3.09	475	26602.7	485	437	1791.7	20587	71333.7

DAM SAFETY INSPECTION / MISSOURI - 1980

SHEET NO. 3 OF 3

BoCo Mo DAM (MO 10893)

JOB NO. 1263

EMERGENCY SPILLWAY SLOPE

BY JFK

DATE 6/17/80

CHECK EMERGENCY SPILLWAY SLOPE FOR CRITICAL FLOW

$$S_b = 4.5' / 50' = 0.09$$

$$\text{for } y = 0.5',$$

$$A = 70$$

$$R = 0.43$$

$$Q = 261$$

$$n = 0.025$$

$$S_c = \left[ \frac{Q n}{1.49 A} \frac{1}{R^{2/3}} \right]^2$$

$$S_c = \left[ \frac{261 \cdot 0.025}{1.49 \cdot 70} \frac{1}{(0.43)^{2/3}} \right]^2$$

$$S_c = 0.0121 < S_b \quad \text{O.K.}$$

$$\text{for } y = 3',$$

$$A = 748.8$$

$$R = 1.96$$

$$Q = 5955$$

$$n = 0.025$$

$$S_c = \left[ \frac{5955 \cdot 0.025}{1.49 \cdot 748.8} \frac{1}{(1.96)^{2/3}} \right]^2$$

$$S_c = 0.0072 < S_b \quad \text{O.K.}$$

∴ Critical depth assumption at emergency spillway is valid



DAM SAFETY INSPECTION / MISSOURI - 1980

SHEET NO. 1 OF 1

BeCo Mo DAM (MO. 10893)

JOB NO. 1263


COMBINED RATING CURVE

BY JFK DATE 6/16/80

SERVICE SPILLWAY, EMERGENCY SPILLWAY, AND OVERTOP DISCHARGES

U.S. ELEV	H <sub>w</sub> or H <sub>T</sub>	Q <sub>1</sub> , SERVICE SPILLWAY	Q <sub>2</sub> , E. SPLWY AND OVERTOP	Q <sub>TOTAL</sub> = Q <sub>1</sub> + Q <sub>2</sub>
696.5	0	0		0
697	0.5	56 *		56
698	1.5	290 *		290
699	2.5	625 *		625
700	30.2	919		919
701	31.2	935		935
702	32.2	949		949
703A	33.6	970	0	970
704.1	34.3	980	261	1241
704.8	35.0	990	815	1805
705.5	35.7	1000	2209	3209
706.1	36.3	1008	5382	6390
707.4	37.6	1026	14203	15229
708.9	39.1	1046	29581	30627
710.4	40.6	1066	49122	50188
711.9	42.1	1086	71334	72420

\* Weir flow controls  $Q = 158.4 H_w^{1.5}$  For U.S. ELEV. = 700 and above,  
pressure flow controls  $Q = 167.3 (H_T)^{1/2}$



BOCO MO DAM (MO. 10893)  
SPILLWAY & OVERTOP RATING CURVE

PERCENT OF PMF FLOOD ROUTING  
EQUAL TO SPILLWAY CAPACITY

PREVIEW OF SEQUENCE OF STREAM NETWORK CALCULATIONS

HUNDE HYDROGRAPH AT 18893  
ROUTE HYDROGRAPH TO 18893  
END OF NETWORK





PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PEAK-RATIO HYDROLOGIC COMPUTATIONS  
 FLOWS IN CUBIC FEET PER SECOND (CUBIC FEET PER SECOND)  
 AREA IN SQUARE MILES (SQUARE MILES)

OPERATION STATION AREA PEAK RATIO 1 RATIO 2 RATIO 3 RATIOS APPLIED TO FLOWS

HYDROGRAPH AT	17042	3.19	1	4920	5740	6560
	(	1624)	(	139.32)	162.83)	185.75)
ROUTED TO	1707	3.19	1	1457	2279	3170
	(	1624)	(	11.27)	64.53)	96.02)

AREA SUMMARY OF DAM SAFETY ANALYSIS

DATE OF ANALYSIS	INITIAL VALUE		SPILLWAY CREST		TOP OF DAM		DURATION OVER TOP HOURS	MAXIMUM OUTFLOW (CFS)	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
	ELEVATION STORAGE	RESERVOIR W.S. ELEV	MAXIMUM STORAGE AC-FT	MAXIMUM DEPTH OVER DAM	INITIAL VALUE	RESERVOIR W.S. ELEV				
PLAB 1	704.57	709.09	1766	0.00	696.50	1861	0.00	1457	42.75	0.00
	795.66		1935	0.00	824	2206	0.75	2779	42.25	0.00
				0.00	0.00		2.25	5179	41.75	0.00



HEC1DB INPUT DATA

AD-A106 625

PRC CONSOER TOWNSEND INC ST LOUIS MO  
NATIONAL DAM SAFETY PROGRAM. BOCO MO DAM (MO 10893), MISSOURI ---ETC(U)  
SEP 80 W G SHIFRIN DACW43-80-C-0094

F/G 13/13

UNCLASSIFIED

NL

2 OF 2

AD-A  
106625



END  
DATE  
FILMED  
11-81  
DTIC

\*\*\*\*\*  
 FLOOD HYDROGRAPH PACKAGE (HEC-1)  
 DAY SAFETY VERSION JULY 1978  
 LAST MODIFICATION 25 FEB 79  
 \*\*\*\*\*

	DAY SAFETY INSPECTION - MISSOURI									
	BOCO MO DAM (MC. 10897)					PMF AND 50 PERCENT PMF				
	0	15	0	15	0	0	0	0	0	0
1	61									
2	72									
3	47		102							
4			5							
5	0	1		1						
6	0.1									
7	0									
8	0									
9	61									
10	1									
11	2									
12	24.7									
13	100									
14	0.51									
15	1									
16	10000									
17	1									
18	1									
19	696.5									
20	702									
21	849									
22	870									
23	290									
24	710									
25	696.5									
26	705									
27	59									

\*\*\*\*\*  
 INPUT RUNOFF PARAMETERS  
 1 1 3.18 1  
 2 2 3.18 140  
 3 3 100 120  
 4 4 1  
 5 5  
 6 6  
 7 7  
 8 8  
 9 9  
 10 10  
 11 11  
 12 12  
 13 13  
 14 14  
 15 15  
 16 16  
 17 17  
 18 18  
 19 19  
 20 20  
 21 21  
 22 22  
 23 23  
 24 24  
 25 25  
 26 26  
 27 27  
 \*\*\*\*\*

\*\*\*\*\*  
 ROUTE HYDROGRAPH THROUGH BOCO MO RESERVOIR  
 1 1  
 2 2  
 3 3  
 4 4  
 5 5  
 6 6  
 7 7  
 8 8  
 9 9  
 10 10  
 11 11  
 12 12  
 13 13  
 14 14  
 15 15  
 16 16  
 17 17  
 18 18  
 19 19  
 20 20  
 21 21  
 22 22  
 23 23  
 24 24  
 25 25  
 26 26  
 27 27  
 \*\*\*\*\*

1	701	702	703.4	704.1	704.8
2	711.9	711.9	711.9	711.9	711.9
3	700	700	700	700	700
4	707.4	708.9	708.9	708.9	708.9
5	290	625	625	625	625
6	15229	30627	30627	30627	30627
7	51.5	86	86	86	86
8	690	696.5	696.5	696.5	696.5
9	690	696.5	696.5	696.5	696.5
10	696.5	696.5	696.5	696.5	696.5
11	696.5	696.5	696.5	696.5	696.5
12	696.5	696.5	696.5	696.5	696.5
13	696.5	696.5	696.5	696.5	696.5
14	696.5	696.5	696.5	696.5	696.5
15	696.5	696.5	696.5	696.5	696.5
16	696.5	696.5	696.5	696.5	696.5
17	696.5	696.5	696.5	696.5	696.5
18	696.5	696.5	696.5	696.5	696.5
19	696.5	696.5	696.5	696.5	696.5
20	696.5	696.5	696.5	696.5	696.5
21	696.5	696.5	696.5	696.5	696.5
22	696.5	696.5	696.5	696.5	696.5
23	696.5	696.5	696.5	696.5	696.5
24	696.5	696.5	696.5	696.5	696.5
25	696.5	696.5	696.5	696.5	696.5
26	696.5	696.5	696.5	696.5	696.5
27	696.5	696.5	696.5	696.5	696.5

INFLOW PMF AND ONE-HALF PMF HYDROGRAPHS

PREVIEW OF SEQUENCE OF STRAIN NETWORK CALCULATIONS

J0693  
10-93

MURPHY HYDROGRAPH AT  
ROUTE HYDROGRAPH TO  
E.L.O. OF NETWORK

\*\*\*\*\*  
 FLOOD HYDROGRAPH PACKAGE (FHC-1)  
 JAM SAFETY VERSION JULY 1978  
 LAST MODIFICATION 26 FEB 79  
 \*\*\*\*\*

RUN DATE: 00/07/17  
 TIME: 07:05:23

DET SAFETY INSPECTION - MISSOURI  
 HOTO NO. 048 (NOV. 1993)  
 PMF AND 50 PERCENT PMF

JOB SPECIFICATION  
 DAY 1000 1000 1000 1000 1000 1000 1000 1000  
 INR 1000 1000 1000 1000 1000 1000 1000 1000  
 MTRC 1000 1000 1000 1000 1000 1000 1000 1000  
 T-PT 1000 1000 1000 1000 1000 1000 1000 1000  
 WSTAY 1000 1000 1000 1000 1000 1000 1000 1000  
 WWT 1000 1000 1000 1000 1000 1000 1000 1000  
 TRACT 1000 1000 1000 1000 1000 1000 1000 1000

\*\*\*\*\*  
 MULTI-PURPOSE ANALYSIS TO BE PERFORMED  
 UPDATE 1 NOTICE 2 LISTING 1  
 \*\*\*\*\*

RTIME 1.00 0.0

\*\*\*\*\*  
 SUB-AREA FLOOD COMPUTATION  
 \*\*\*\*\*

\*\*\*\*\*  
 FLOOD FLOW PARAMETERS  
 \*\*\*\*\*

IS10	IS20	IS30	IS40	IS50	IS60	IS70	IS80	IS90	IS100
1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00

HYDROGRAPH DATA

IS10	IS20	IS30	IS40	IS50	IS60	IS70	IS80	IS90	IS100
1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00

PRECIP. DATA

IS10	IS20	IS30	IS40	IS50	IS60	IS70	IS80	IS90	IS100
1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00

LOSS DATA

IS10	IS20	IS30	IS40	IS50	IS60	IS70	IS80	IS90	IS100
1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00

\*\*\*\*\*  
 WAVE LOSS -0.00 METHODS = -1.00 EFFECT CR = 90.00  
 \*\*\*\*\*

UNIT HYDROGRAPH DATA

ICE 0.00 LACE 0.01

RECESSION DATA

STRIC= 0.00 QRCSS= 0.00 RTIME= 1.00

\*\*\*\*\*  
 UNIT HYDROGRAPH IN END OF PERIOD ORIGINATES, ICE 0.00 HOURS, LACE 0.01 VOL= 1.00  
 204. 891. 1530. 1366. 913. 579. 577. 239. 158.  
 101. 65. 27. 18. 13. 7. 3.  
 \*\*\*\*\*

MO	DA	HR	NN	FAN-OF-PERIOD FLOW				PERIOD	HR	NN	EXCS	LOSS	COMP	PERIOD	HR	NN	EXCS	LOSS	COMP
				RAIN	EXCS	LOSS	COMP												
1.01	1.15	1	1	.00	.00	.00	.00	1.02	.15	.97	.04	.00	97	.04	.00	.00	.00	48.	
1.01	1.30	2	1	.00	.00	.00	.00	1.02	.30	98	.04	.00	98	.04	.00	.00	.00	72.	
1.01	1.45	3	1	.00	.00	.00	.00	1.02	.45	99	.04	.00	99	.04	.00	.00	.00	122.	
1.01	1.10	4	1	.00	.00	.00	.00	1.02	1.00	100	.04	.00	100	.04	.00	.00	.00	176.	
1.01	1.15	5	1	.00	.00	.00	.00	1.02	1.15	101	.04	.00	101	.04	.00	.00	.00	221.	
1.01	1.20	6	1	.00	.00	.00	.00	1.02	1.30	102	.04	.00	102	.04	.00	.00	.00	251.	
1.01	1.25	7	1	.00	.00	.00	.00	1.02	1.45	103	.04	.00	103	.04	.00	.00	.00	271.	
1.01	1.30	8	1	.00	.00	.00	.00	1.02	2.00	104	.04	.00	104	.04	.00	.00	.00	284.	
1.01	1.35	9	1	.00	.00	.00	.00	1.02	2.15	105	.04	.00	105	.04	.00	.00	.00	292.	
1.01	1.40	10	1	.00	.00	.00	.00	1.02	2.30	106	.04	.00	106	.04	.00	.00	.00	294.	
1.01	1.45	11	1	.00	.00	.00	.00	1.02	2.45	107	.04	.00	107	.04	.00	.00	.00	302.	
1.01	1.50	12	1	.00	.00	.00	.00	1.02	3.00	108	.04	.00	108	.04	.00	.00	.00	305.	
1.01	1.55	13	1	.00	.00	.00	.00	1.02	3.15	109	.04	.00	109	.04	.00	.00	.00	307.	
1.01	1.00	14	1	.00	.00	.00	.00	1.02	3.30	110	.04	.00	110	.04	.00	.00	.00	308.	
1.01	1.05	15	1	.00	.00	.00	.00	1.02	3.45	111	.04	.00	111	.04	.00	.00	.00	309.	
1.01	1.10	16	1	.00	.00	.00	.00	1.02	4.00	112	.04	.00	112	.04	.00	.00	.00	310.	
1.01	1.15	17	1	.00	.00	.00	.00	1.02	4.15	113	.04	.00	113	.04	.00	.00	.00	311.	
1.01	1.20	18	1	.00	.00	.00	.00	1.02	4.30	114	.04	.00	114	.04	.00	.00	.00	312.	
1.01	1.25	19	1	.00	.00	.00	.00	1.02	4.45	115	.04	.00	115	.04	.00	.00	.00	313.	
1.01	1.30	20	1	.00	.00	.00	.00	1.02	5.00	116	.04	.00	116	.04	.00	.00	.00	314.	
1.01	1.35	21	1	.00	.00	.00	.00	1.02	5.15	117	.04	.00	117	.04	.00	.00	.00	315.	
1.01	1.40	22	1	.00	.00	.00	.00	1.02	5.30	118	.04	.00	118	.04	.00	.00	.00	316.	
1.01	1.45	23	1	.00	.00	.00	.00	1.02	5.45	119	.04	.00	119	.04	.00	.00	.00	317.	
1.01	1.50	24	1	.00	.00	.00	.00	1.02	6.00	120	.04	.00	120	.04	.00	.00	.00	318.	
1.01	1.55	25	1	.00	.00	.00	.00	1.02	6.15	121	.04	.00	121	.04	.00	.00	.00	319.	
1.01	1.00	26	1	.00	.00	.00	.00	1.02	6.30	122	.04	.00	122	.04	.00	.00	.00	320.	
1.01	1.05	27	1	.00	.00	.00	.00	1.02	6.45	123	.04	.00	123	.04	.00	.00	.00	321.	
1.01	1.10	28	1	.00	.00	.00	.00	1.02	7.00	124	.04	.00	124	.04	.00	.00	.00	322.	
1.01	1.15	29	1	.00	.00	.00	.00	1.02	7.15	125	.04	.00	125	.04	.00	.00	.00	323.	
1.01	1.20	30	1	.00	.00	.00	.00	1.02	7.30	126	.04	.00	126	.04	.00	.00	.00	324.	
1.01	1.25	31	1	.00	.00	.00	.00	1.02	7.45	127	.04	.00	127	.04	.00	.00	.00	325.	
1.01	1.30	32	1	.00	.00	.00	.00	1.02	8.00	128	.04	.00	128	.04	.00	.00	.00	326.	
1.01	1.35	33	1	.00	.00	.00	.00	1.02	8.15	129	.04	.00	129	.04	.00	.00	.00	327.	
1.01	1.40	34	1	.00	.00	.00	.00	1.02	8.30	130	.04	.00	130	.04	.00	.00	.00	328.	
1.01	1.45	35	1	.00	.00	.00	.00	1.02	8.45	131	.04	.00	131	.04	.00	.00	.00	329.	
1.01	1.50	36	1	.00	.00	.00	.00	1.02	9.00	132	.04	.00	132	.04	.00	.00	.00	330.	
1.01	1.55	37	1	.00	.00	.00	.00	1.02	9.15	133	.04	.00	133	.04	.00	.00	.00	331.	
1.01	1.00	38	1	.00	.00	.00	.00	1.02	9.30	134	.04	.00	134	.04	.00	.00	.00	332.	
1.01	1.05	39	1	.00	.00	.00	.00	1.02	9.45	135	.04	.00	135	.04	.00	.00	.00	333.	
1.01	1.10	40	1	.00	.00	.00	.00	1.02	10.00	136	.04	.00	136	.04	.00	.00	.00	334.	
1.01	1.15	41	1	.00	.00	.00	.00	1.02	10.15	137	.04	.00	137	.04	.00	.00	.00	335.	
1.01	1.20	42	1	.00	.00	.00	.00	1.02	10.30	138	.04	.00	138	.04	.00	.00	.00	336.	
1.01	1.25	43	1	.00	.00	.00	.00	1.02	10.45	139	.04	.00	139	.04	.00	.00	.00	337.	
1.01	1.30	44	1	.00	.00	.00	.00	1.02	11.00	140	.04	.00	140	.04	.00	.00	.00	338.	
1.01	1.35	45	1	.00	.00	.00	.00	1.02	11.15	141	.04	.00	141	.04	.00	.00	.00	339.	
1.01	1.40	46	1	.00	.00	.00	.00	1.02	11.30	142	.04	.00	142	.04	.00	.00	.00	340.	
1.01	1.45	47	1	.00	.00	.00	.00	1.02	11.45	143	.04	.00	143	.04	.00	.00	.00	341.	
1.01	1.50	48	1	.00	.00	.00	.00	1.02	12.00	144	.04	.00	144	.04	.00	.00	.00	342.	
1.01	1.55	49	1	.00	.00	.00	.00	1.02	12.15	145	.04	.00	145	.04	.00	.00	.00	343.	
1.01	1.00	50	1	.00	.00	.00	.00	1.02	12.30	146	.04	.00	146	.04	.00	.00	.00	344.	
1.01	1.05	51	1	.00	.00	.00	.00	1.02	12.45	147	.04	.00	147	.04	.00	.00	.00	345.	
1.01	1.10	52	1	.00	.00	.00	.00	1.02	13.00	148	.04	.00	148	.04	.00	.00	.00	346.	
1.01	1.15	53	1	.00	.00	.00	.00	1.02	13.15	149	.04	.00	149	.04	.00	.00	.00	347.	
1.01	1.20	54	1	.00	.00	.00	.00	1.02	13.30	150	.04	.00	150	.04	.00	.00	.00	348.	
1.01	1.25	55	1	.00	.00	.00	.00	1.02	13.45	151	.04	.00	151	.04	.00	.00	.00	349.	
1.01	1.30	56	1	.00	.00	.00	.00	1.02	14.00	152	.04	.00	152	.04	.00	.00	.00	350.	

STATION	15-MIN	30-MIN	1-HOUR	2-HOUR	4-HOUR	8-HOUR	12-HOUR	24-HOUR	48-HOUR	72-HOUR	TOTAL VOLUME
1.01 14.15	37	77	105	233	182	14.15					5553
1.01 14.30	58	87	82	268	182	14.30					6366
1.01 14.45	59	67	62	294	152	14.45					6333
1.01 15.00	68	87	82	323	187	15.00					8111
1.01 15.15	61	87	82	351	152	15.15					7816
1.01 15.30	62	86	86	387	152	15.30					7876
1.01 15.45	63	86	82	514	152	15.45					9358
1.01 16.00	64	86	82	741	152	16.00					12888
1.01 16.15	65	87	82	957	152	16.15					15986
1.01 16.30	66	87	82	990	152	16.30					16808
1.01 16.45	67	87	81	916	152	16.45					14782
1.01 17.00	66	67	61	772	152	17.00					12316
1.01 17.15	69	67	61	651	152	17.15					10322
1.01 17.30	72	65	61	583	152	17.30					9039
1.01 17.45	71	65	61	520	152	17.45					7974
1.01 17.60	72	65	61	474	152	17.60					7196
1.01 17.75	73	65	60	429	152	17.75					6458
1.01 17.90	74	67	60	376	152	17.90					5538
1.01 18.05	75	67	60	297	152	18.05					3358
1.01 18.20	75	66	60	215	152	18.20					3194
1.01 18.35	77	69	60	159	152	18.35					2253
1.01 18.50	78	67	60	119	152	18.50					1628
1.01 19.05	79	67	61	64	152	19.05					1228
1.01 20.00	42	64	60	34	152	20.00					959
1.01 20.15	31	66	60	54	152	20.15					788
1.01 20.30	32	67	60	47	152	20.30					685
1.01 20.45	43	66	60	42	152	20.45					619
1.01 21.00	44	66	60	47	152	21.00					577
1.01 21.15	43	67	60	58	152	21.15					549
1.01 21.30	46	67	60	54	152	21.30					531
1.01 21.45	47	66	60	36	152	21.45					528
1.01 22.00	44	66	60	34	152	22.00					513
1.01 22.15	49	66	60	34	152	22.15					508
1.01 22.30	40	66	60	34	152	22.30					506
1.01 22.45	41	66	60	34	152	22.45					506
1.01 23.00	42	66	60	34	152	23.00					506
1.01 23.15	43	66	60	35	152	23.15					506
1.01 23.30	44	66	60	35	152	23.30					504
1.01 23.45	44	66	60	35	152	23.45					506
1.02 00.00	76	68	60	26	152	00.00					506

CUP 34.53 53.55 1.23 27163R.  
 ( 078.01 847.01 31.01 7691.73)

PERM	PEAK	CFS	THOUS CU Y	HYDROGRAPH AT STA 10R93 FOR PLAIN 1, RTID 1
31405	31405	32	109	0. 0.
40%	40%	32	109	1. 1.
		14.60	51.84	1. 1.
		301.24	140.21	1. 1.
		590.42	301.24	1. 1.
		900.	354.7	6. 6.
		6914.	6917.	26. 26.
				29. 29.
				31. 31.
				36. 36.
				42. 42.
				55. 55.



77	107	130	140	150	160	170	180	190	200	210	220	230	240	250	260	270	280	290	300
351	362	373	384	395	406	417	428	439	450	461	472	483	494	505	516	527	538	549	560
52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71
122	123	124	125	126	127	128	129	130	131	132	133	134	135	136	137	138	139	140	141
302	303	304	305	306	307	308	309	310	311	312	313	314	315	316	317	318	319	320	321
1500	1501	1502	1503	1504	1505	1506	1507	1508	1509	1510	1511	1512	1513	1514	1515	1516	1517	1518	1519
1657	1658	1659	1660	1661	1662	1663	1664	1665	1666	1667	1668	1669	1670	1671	1672	1673	1674	1675	1676
4010	4011	4012	4013	4014	4015	4016	4017	4018	4019	4020	4021	4022	4023	4024	4025	4026	4027	4028	4029
7874	7875	7876	7877	7878	7879	7880	7881	7882	7883	7884	7885	7886	7887	7888	7889	7890	7891	7892	7893
506	507	508	509	510	511	512	513	514	515	516	517	518	519	520	521	522	523	524	525

1687	1688	1689	1690	1691	1692	1693	1694	1695	1696	1697	1698	1699	1700	1701	1702	1703	1704	1705	1706	1707
288	289	290	291	292	293	294	295	296	297	298	299	300	301	302	303	304	305	306	307	308
1184	1185	1186	1187	1188	1189	1190	1191	1192	1193	1194	1195	1196	1197	1198	1199	1200	1201	1202	1203	1204
8024	8025	8026	8027	8028	8029	8030	8031	8032	8033	8034	8035	8036	8037	8038	8039	8040	8041	8042	8043	8044
587	588	589	590	591	592	593	594	595	596	597	598	599	600	601	602	603	604	605	606	607
608	609	610	611	612	613	614	615	616	617	618	619	620	621	622	623	624	625	626	627	628

1708	1709	1710	1711	1712	1713	1714	1715	1716	1717	1718	1719	1720	1721	1722	1723	1724	1725	1726	1727	1728
1729	1730	1731	1732	1733	1734	1735	1736	1737	1738	1739	1740	1741	1742	1743	1744	1745	1746	1747	1748	1749
1750	1751	1752	1753	1754	1755	1756	1757	1758	1759	1760	1761	1762	1763	1764	1765	1766	1767	1768	1769	1770
1771	1772	1773	1774	1775	1776	1777	1778	1779	1780	1781	1782	1783	1784	1785	1786	1787	1788	1789	1790	1791
1792	1793	1794	1795	1796	1797	1798	1799	1800	1801	1802	1803	1804	1805	1806	1807	1808	1809	1810	1811	1812
1813	1814	1815	1816	1817	1818	1819	1820	1821	1822	1823	1824	1825	1826	1827	1828	1829	1830	1831	1832	1833
1834	1835	1836	1837	1838	1839	1840	1841	1842	1843	1844	1845	1846	1847	1848	1849	1850	1851	1852	1853	1854
1855	1856	1857	1858	1859	1860	1861	1862	1863	1864	1865	1866	1867	1868	1869	1870	1871	1872	1873	1874	1875
1876	1877	1878	1879	1880	1881	1882	1883	1884	1885	1886	1887	1888	1889	1890	1891	1892	1893	1894	1895	1896
1897	1898	1899	1900	1901	1902	1903	1904	1905	1906	1907	1908	1909	1910	1911	1912	1913	1914	1915	1916	1917

1918	1919	1920	1921	1922	1923	1924	1925	1926	1927	1928	1929	1930	1931	1932	1933	1934	1935	1936	1937	1938
1939	1940	1941	1942	1943	1944	1945	1946	1947	1948	1949	1950	1951	1952	1953	1954	1955	1956	1957	1958	1959
1960	1961	1962	1963	1964	1965	1966	1967	1968	1969	1970	1971	1972	1973	1974	1975	1976	1977	1978	1979	1980
1981	1982	1983	1984	1985	1986	1987	1988	1989	1990	1991	1992	1993	1994	1995	1996	1997	1998	1999	2000	2001
2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022
2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043
2044	2045	2046	2047	2048	2049	2050	2051	2052	2053	2054	2055	2056	2057	2058	2059	2060	2061	2062	2063	2064
2065	2066	2067	2068	2069	2070	2071	2072	2073	2074	2075	2076	2077	2078	2079	2080	2081	2082	2083	2084	2085
2086	2087	2088	2089	2090	2091	2092	2093	2094	2095	2096	2097	2098	2099	2100	2101	2102	2103	2104	2105	2106

2107	2108	2109	2110	2111	2112	2113	2114	2115	2116	2117	2118	2119	2120	2121	2122	2123	2124	2125	2126	2127
2128	2129	2130	2131	2132	2133	2134	2135	2136	2137	2138	2139	2140	2141	2142	2143	2144	2145	2146	2147	2148
2149	2150	2151	2152	2153	2154	2155	2156	2157	2158	2159	2160	2161	2162	2163	2164	2165	2166	2167	2168	2169
2170	2171	2172	2173	2174	2175	2176	2177	2178	2179	2180	2181	2182	2183	2184	2185	2186	2187	2188	2189	2190
2191	2192	2193	2194	2195	2196	2197	2198	2199	2200	2201	2202	2203	2204	2205	2206	2207	2208	2209	2210	2211
2212	2213	2214	2215	2216	2217	2218	2219	2220	2221	2222	2223	2224	2225	2226	2227	2228	2229	2230	2231	2232
2233	2234	2235	2236	2237	2238	2239	2240	2241	2242	2243	2244	2245	2246	2247	2248	2249	2250	2251	2252	2253

PMF AND ONE-HALF PMF ROUTING







694.0 698.0 699.0 699.6 699.8  
 700.1 700.4 700.7 701.0 701.6 702.0 702.6 703.1 703.8  
 703.6 703.8 703.9 704.0 704.0 704.0 704.0 704.0 704.0  
 705.4 705.5 705.5 705.6 705.6 705.6 705.6 705.6 705.6  
 707.9 708.1 708.1 708.1 708.1 708.1 708.1 708.1 708.1  
 709.1 709.1 709.1 709.1 709.1 709.1 709.1 709.1 709.1

PEAK UTILIZATION 970. AT TIME 45.00 HOURS  
 699.6 699.8 702.6 703.1 703.8 704.0 704.0 704.0 704.0 704.0  
 705.6 705.6 705.6 705.6 705.6 705.6 705.6 705.6 705.6  
 708.1 708.1 708.1 708.1 708.1 708.1 708.1 708.1 708.1

599.1 599.2 599.4 599.4 599.4 599.4 599.4 599.4 599.4  
 601.8 601.8 601.8 601.8 601.8 601.8 601.8 601.8 601.8  
 603.9 603.9 603.9 603.9 603.9 603.9 603.9 603.9 603.9  
 604.6 604.6 604.6 604.6 604.6 604.6 604.6 604.6 604.6  
 605.5 605.5 605.5 605.5 605.5 605.5 605.5 605.5 605.5

599.0 599.0 599.0 599.0 599.0 599.0 599.0 599.0 599.0  
 601.4 601.4 601.4 601.4 601.4 601.4 601.4 601.4 601.4  
 606.0 606.0 606.0 606.0 606.0 606.0 606.0 606.0 606.0  
 704.8 704.8 704.8 704.8 704.8 704.8 704.8 704.8 704.8  
 703.4 703.4 703.4 703.4 703.4 703.4 703.4 703.4 703.4

278M 278M 278M 278M 278M 278M 278M 278M 278M  
 79. 79. 79. 79. 79. 79. 79. 79. 79.  
 4.16 4.16 4.16 4.16 4.16 4.16 4.16 4.16 4.16  
 207.16 207.16 207.16 207.16 207.16 207.16 207.16 207.16 207.16  
 1383. 1383. 1383. 1383. 1383. 1383. 1383. 1383. 1383.

1313 1313 1313 1313 1313 1313 1313 1313 1313  
 29. 29. 29. 29. 29. 29. 29. 29. 29.  
 12.09 12.09 12.09 12.09 12.09 12.09 12.09 12.09 12.09  
 307.07 307.07 307.07 307.07 307.07 307.07 307.07 307.07 307.07  
 2949. 2949. 2949. 2949. 2949. 2949. 2949. 2949. 2949.

517. 517. 517. 517. 517. 517. 517. 517. 517.  
 15. 15. 15. 15. 15. 15. 15. 15. 15.  
 315.23 315.23 315.23 315.23 315.23 315.23 315.23 315.23 315.23  
 2130. 2130. 2130. 2130. 2130. 2130. 2130. 2130. 2130.

2628. 2628. 2628. 2628. 2628. 2628. 2628. 2628. 2628.  
 2628. 2628. 2628. 2628. 2628. 2628. 2628. 2628. 2628.

103113. 103113. 103113. 103113. 103113. 103113. 103113. 103113. 103113.  
 2920. 2920. 2920. 2920. 2920. 2920. 2920. 2920. 2920.

319.27 319.27 319.27 319.27 319.27 319.27 319.27 319.27 319.27  
 2130. 2130. 2130. 2130. 2130. 2130. 2130. 2130. 2130.

2628. 2628. 2628. 2628. 2628. 2628. 2628. 2628. 2628.

SUMMARY OF PMF AND ONE-HALF PMF FLOOD ROUTING

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS  
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)  
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION STATION AREA PLAN RATIO 1 RATIO 2 PATIOS APPLIED TO FLOWS  
 1.00 .50

HYDROGRAPH AT 10093 3.16 1 14900 8200  
 ( 4.20) ( 604.39) ( 232.14) (

ROUTED TO 10093 3.16 1 15178 5974  
 ( 4.24) ( 627.79) ( 169.04) (



SUMMARY OF DAM SAFETY ANALYSIS

INITIAL VALUE SPILLWAY CREST TYP OF DAM  
 496.50 196.00 705.00  
 850. 420. 1061.  
 0. 0. 2206.

TYPE OF RECLAMATION M.S.S.ELEV	MINIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION W/IMP TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
1.01	2.39	2252.	15178.	5.75	40.75	0.00
0.51	1.02	2023.	5970.	3.00	41.00	0.00

ELEVATION  
STORAGE  
OUTFLOW

END

DATE  
FILMED

11-81

DTIC