

AD-A106 736

BLACK AND VEATCH KANSAS CITY MO

F/G 13/13

NATIONAL DAM SAFETY PROGRAM, SKY HAVEN LAKE DAM (MO 20177), MIS--ETC(U)


JUN 80 P R ZAMAN, E R BURTON, H L CALLAHAN

DACW43-80-C-0074

NL

UNCLASSIFIED

1-1  
500-728



END

DATE

FILMED

11-81

DTIC

**LEVEL** # **(1)**

**MISSOURI-KANSAS CITY BASIN**

**AL A 106736**

**SKY HAVEN LAKE DAM  
JOHNSON COUNTY, MISSOURI  
MO 20177**

**PHASE 1 INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM**

**DTIC FILE COPY**



**United States Army  
Corps of Engineers**  
*... Serving the Army  
... Serving the Nation*

**St. Louis District**

**DTIC  
ELECT**  
**S** NOV 6 1981  
**A**

**PREPARED BY: U.S. ARMY ENGINEER DISTRICT. ST. LOUIS**

**FOR: STATE OF MISSOURI**

**JUNE 1980**

**This document has been approved  
for public release and sale; its  
distribution is unlimited.**

**81 11 02 055**

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

| REPORT DOCUMENTATION PAGE   |                                     | READ INSTRUCTIONS<br>BEFORE COMPLETING FORM                                  |
|---|-------------------------------------|--|
| 1. REPORT NUMBER  | 2. GOVT ACCESSION NO.<br>AD-A106736 | 3. RECIPIENT'S CATALOG NUMBER  |
| 4. TITLE (and Subtitle)<br>Phase I Dam Inspection Report<br>National Dam Safety Program<br>Skyhaven Lake Dam (MO 20177)<br>Johnson County, Missouri   |                                     | 5. TYPE OF REPORT & PERIOD COVERED<br>9) Final Report, 1                     |
| 7. AUTHOR(s)<br>Black & Veatch, Consulting Engineer<br>10) Paul R. / Zaman Edwin R. / Burton<br>Harry L. / Callahan   |                                     | 6. PERFORMING ORG. REPORT NUMBER   |
| 9. PERFORMING ORGANIZATION ADDRESS<br>U.S. Army Engineer District, St. Louis<br>Dam Inventory and Inspection Section, LMSED-PD<br>210 Tucker Blvd., North, St. Louis, Mo. 63101   |                                     | 8. CONTRACT OR GRANT NUMBER(s)<br>15) DACW43-80-C-0074                       |
| 11. CONTROLLING OFFICE NAME AND ADDRESS<br>U.S. Army Engineer District, St. Louis<br>Dam Inventory and Inspection Section, LMSED-PD<br>210 Tucker Blvd., North, St. Louis, Mo. 63101  |                                     | 10. PROGRAM ELEMENT, PROJECT, TASK<br>AREA & WORK UNIT NUMBERS<br>11) 12) 53 |
| 14. MONITORING AGENCY NAME & ADDRESS (if different from<br>controlling office)<br>6) National Dam Safety Program. Sky Haven<br>Lake Dam (MO 20177), Missouri - Kansas<br>City Basin, Johnson County, Missouri.<br>Phase I Inspection Report.  |                                     | 12. REPORT DATE<br>June 1980   |
| 16. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)  |                                     | 13. NUMBER OF PAGES<br>Approximately 60                                      |
| 17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)  |                                     | 14. SECURITY CLASS. (of this report)<br>UNCLASSIFIED                         |
| 18. SUPPLEMENTARY NOTES   |                                     | 15. DECLASSIFICATION/DOWNGRADING<br>SCHEDULE                                 |
| 19. KEY WORDS (Continue on reverse side if necessary and identify by block number)<br>Dam Safety, Lake, Dam Inspection, Private Dams  |                                     |  |
| 20. ABSTRACT (Continue on reverse side if necessary and identify by block number)<br>This report was prepared under the National Program of Inspection of<br>Non-Federal Dams. This report assesses the general condition of the dam with<br>respect to safety, based on available data and on visual inspection, to<br>determine if the dam poses hazards to human life or property. ← |                                     |  |

DD FORM 1 JAN 73 1473

EDITION OF 1 NOV 65 IS OBSOLETE


UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

058550

JUB

**SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)**



**SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)**

## INSTRUCTIONS FOR PREPARATION OF REPORT DOCUMENTATION PAGE

**RESPONSIBILITY.** The controlling DoD office will be responsible for completion of the Report Documentation Page, DD Form 1473, in all technical reports prepared by or for DoD organizations.

**CLASSIFICATION.** Since this Report Documentation Page, DD Form 1473, is used in preparing announcements, bibliographies, and data banks, it should be unclassified if possible. If a classification is required, identify the classified items on the page by the appropriate symbol.

### COMPLETION GUIDE

General. Make Blocks 1, 4, 5, 6, 7, 11, 13, 15, and 16 agree with the corresponding information on the report cover. Leave Blocks 2 and 3 blank.

**Block 1.** Report Number. Enter the unique alphanumeric report number shown on the cover.

**Block 2.** Government Accession No. Leave Blank. This space is for use by the Defense Documentation Center.

**Block 3.** Recipient's Catalog Number. Leave blank. This space is for the use of the report recipient to assist in future retrieval of the document.

**Block 4.** Title and Subtitle. Enter the title in all capital letters exactly as it appears on the publication. Titles should be unclassified whenever possible. Write out the English equivalent for Greek letters and mathematical symbols in the title (*see "Abstracting Scientific and Technical Reports of Defense-sponsored RDT/E," AD-667 000*). If the report has a subtitle, this subtitle should follow the main title, be separated by a comma or semicolon if appropriate, and be initially capitalized. If a publication has a title in a foreign language, translate the title into English and follow the English translation with the title in the original language. Make every effort to simplify the title before publication.

**Block 5.** Type of Report and Period Covered. Indicate here whether report is interim, final, etc., and, if applicable, inclusive dates of period covered, such as the life of a contract covered in a final contractor report.

**Block 6.** Performing Organization Report Number. Only numbers other than the official report number shown in Block 1, such as series numbers for in-house reports or a contractor/grantee number assigned by him, will be placed in this space. If no such numbers are used, leave this space blank.

**Block 7.** Author(s). Include corresponding information from the report cover. Give the name(s) of the author(s) in conventional order (for example, *John R. Doe* or, if author prefers, *J. Robert Doe*). In addition, list the affiliation of an author if it differs from that of the performing organization.

**Block 8.** Contract or Grant Number(s). For a contractor or grantee report, enter the complete contract or grant number(s) under which the work reported was accomplished. Leave blank in in-house reports.

**Block 9.** Performing Organization Name and Address. For in-house reports enter the name and address, including office symbol, of the performing activity. For contractor or grantee reports enter the name and address of the contractor or grantee who prepared the report and identify the appropriate corporate division, school, laboratory, etc., of the author. List city, state, and ZIP Code.

**Block 10.** Program Element, Project, Task Area, and Work Unit Numbers. Enter here the number code from the applicable Department of Defense form, such as the DD Form 1498, "Research and Technology Work Unit Summary" or the DD Form 1634, "Research and Development Planning Summary," which identifies the program element, project, task area, and work unit or equivalent under which the work was authorized.

**Block 11.** Controlling Office Name and Address. Enter the full, official name and address, including office symbol, of the controlling office. (*Equates to funding/sponsoring agency. For definition see DoD Directive 5200.20, "Distribution Statements on Technical Documents."*)

**Block 12.** Report Date. Enter here the day, month, and year or month and year as shown on the cover.

**Block 13.** Number of Pages. Enter the total number of pages.

**Block 14.** Monitoring Agency Name and Address (*if different from Controlling Office*). For use when the controlling or funding office does not directly administer a project, contract, or grant, but delegates the administrative responsibility to another organization.

**Blocks 15 & 15a.** Security Classification of the Report: Declassification/Downgrading Schedule of the Report. Enter in 15 the highest classification of the report. If appropriate, enter in 15a the declassification/downgrading schedule of the report, using the abbreviations for declassification/downgrading schedules listed in paragraph 4-207 of DoD 5200.1-R.

**Block 16.** Distribution Statement of the Report. Insert here the applicable distribution statement of the report from DoD Directive 5200.20, "Distribution Statements on Technical Documents."

**Block 17.** Distribution Statement (*of the abstract entered in Block 20, if different from the distribution statement of the report*). Insert here the applicable distribution statement of the abstract from DoD Directive 5200.20, "Distribution Statements on Technical Documents."

**Block 18.** Supplementary Notes. Enter information not included elsewhere but useful, such as: Prepared in cooperation with . . . Translation of (or by) . . . Presented at conference of . . . To be published in . . .

**Block 19.** Key Words. Select terms or short phrases that identify the principal subjects covered in the report, and are sufficiently specific and precise to be used as index entries for cataloging, conforming to standard terminology. The DoD "Thesaurus of Engineering and Scientific Terms" (TEST), AD-672 000, can be helpful.

**Block 20.** Abstract. The abstract should be a brief (*not to exceed 200 words*) factual summary of the most significant information contained in the report. If possible, the abstract of a classified report should be unclassified and the abstract to an unclassified report should consist of publicly-releasable information. If the report contains a significant bibliography or literature survey, mention it here. For information on preparing abstracts see "Abstracting Scientific and Technical Reports of Defense-Sponsored RDT&E," AD-667 000.

# MISSOURI-KANSAS CITY BASIN

SKY HAVEN LAKE DAM

JOHNSON COUNTY, MISSOURI

MO 20177

## PHASE 1 INSPECTION REPORT NATIONAL DAM SAFETY PROGRAM



United States Army  
Corps of Engineers

... Serving the Army  
... Serving the Nation

### St. Louis District

PREPARED BY: U.S. ARMY ENGINEER DISTRICT. ST. LOUIS

FOR: STATE OF MISSOURI

JUNE 1980

|                    |                                     |
|--------------------|-------------------------------------|
| Accession For      |                                     |
| WTIS               | <input checked="" type="checkbox"/> |
| DPIC T R           | <input type="checkbox"/>            |
| Unannounced        | <input type="checkbox"/>            |
| Justification      |                                     |
| By                 |                                     |
| District           |                                     |
| Availability Codes |                                     |
| and/or             |                                     |
| Discussion         |                                     |
| AI                 |                                     |



**DEPARTMENT OF THE ARMY**  
**ST. LOUIS DISTRICT, CORPS OF ENGINEERS**  
**210 TUCKER BOULEVARD, NORTH**  
**ST. LOUIS, MISSOURI 63101**

REPLY TO  
ATTENTION OF

**LMSD-PD**

**SUBJECT: Sky Haven Lake Dam, Mo. ID No. 20177**

**Phase I Inspection Report**

This report presents the results of field inspection and evaluation of the Sky Haven Lake Dam. It was prepared under the National Program of Inspection of Non-Federal Dams.

**SUBMITTED BY:** \_\_\_\_\_  
Chief, Engineering Division Date

**APPROVED BY:** \_\_\_\_\_  
Colonel, CE, District Engineer Date

**SKY HAVEN LAKE DAM  
JOHNSON COUNTY, MISSOURI  
MISSOURI INVENTORY NO. 20177**

**PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM**

**PREPARED BY:**

**BLACK & VEATCH  
CONSULTING ENGINEERS  
KANSAS CITY, MISSOURI**

**UNDER DIRECTION OF  
ST. LOUIS DISTRICT CORPS OF ENGINEERS  
FOR  
GOVERNOR OF MISSOURI**

**JUNE 1980**



PHASE I REPORT  
NATIONAL DAM SAFETY PROGRAM

|                    |  |
|--------------------|--|
| Name of Dam        | Sky Haven Lake Dam                               |
| State Located      | Missouri   |
| County Located     | Johnson County                                   |
| Stream             | Tributary to Devil's Branch of Post<br>Oak Creek |
| Date of Inspection | 5 June 1980                                      |

Sky Haven Lake Dam was inspected by a team of engineers from Black & Veatch, Consulting Engineers for the St. Louis District, Corps of Engineers. The purpose of the inspection was to make an assessment of the general condition of the dam with respect to safety, based upon available data and visual inspection, in order to determine if the dam poses hazards to human life or property.

The guidelines used in the assessment were furnished by the Department of the Army, Office of the Chief of Engineers and developed with the help of several Federal and state agencies, professional engineering organizations, and private engineers. Based on these guidelines, this dam is classified as a small size dam with a high downstream hazard potential. According to the St. Louis District, Corps of Engineers, failure would threaten lives and property. The estimated damage zone extends approximately one mile downstream of the dam. Within the estimated damage zone are U.S. highway 50 and approximately eight trailers.

Our inspection and evaluation indicates the spillway does meet the criteria set forth in the guidelines for a dam having the above size and hazard potential. The spillway will not pass the probable maximum flood without overtopping but will pass 60 percent of the probable maximum flood and the one percent probability flood. The spillway design flood recommended by the guidelines is 50 to 100 percent of the probable maximum flood. Considering the volume of water impounded behind the dam and the hazard zone, the spillway design flood should be 50 percent of the probable maximum flood. The probable maximum flood is defined as the flood discharge which may be expected from the most severe combination of critical meteorologic and hydrologic conditions which are reasonably possible in the region.

Based on visual observations, this dam appears to be in satisfactory condition. Deficiencies visually observed by the inspection team were seepage at the downstream toe of the dam along the right section of the embankment, erosion and sloughing on the upstream slope, settlement of

one section of the principal spillway pipe, and many small and medium sized trees growing on both the upstream and downstream faces of the dam. Seepage and stability analyses required by the guidelines were not available.

There were no observed deficiencies or conditions existing at the time of the inspection which indicated an immediate safety hazard. Future corrective action and regular maintenance will be required to correct or control the described deficiencies. In addition, detailed seepage and stability analyses of the existing dam, as required by the guidelines, should be performed. A detailed report discussing each of these deficiencies is attached.

*Paul R. Zaman*


Paul R. Zaman, PE  
Illinois 62-29261

*Edwin R. Burton*

Edwin R. Burton, PE  
Missouri E-10137

*Harry L. Callahan*

Harry L. Callahan, Partner  
Black & Veatch



OVERVIEW OF DAM

PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM  
SKY HAVEN LAKE DAM

TABLE OF CONTENTS

| <u>Paragraph No.</u>                     | <u>Title</u>                                | <u>Page No.</u> |
|--|---|-----------------|
| SECTION 1 - PROJECT INFORMATION          |   |                 |
| 1.1                                      | General                                     | 1               |
| 1.2                                      | Description of Project                      | 1               |
| 1.3                                      | Pertinent Data                              | 2               |
| SECTION 2 - ENGINEERING DATA             |   |                 |
| 2.1                                      | Design                                      | 5               |
| 2.2                                      | Construction                                | 5               |
| 2.3                                      | Operation                                   | 5               |
| 2.4                                      | Geology                                     | 5               |
| 2.5                                      | Evaluation                                  | 5               |
| SECTION 3 - VISUAL INSPECTION            |   |                 |
| 3.1                                      | Findings                                    | 7               |
| 3.2                                      | Evaluation                                  | 9               |
| SECTION 4 - OPERATIONAL PROCEDURES       |   |                 |
| 4.1                                      | Procedures                                  | 10              |
| 4.2                                      | Maintenance of Dam                          | 10              |
| 4.3                                      | Maintenance of Operating Facilities         | 10              |
| 4.4                                      | Description of Any Warning System in Effect | 10              |
| 4.5                                      | Evaluation                                  | 10              |
| SECTION 5 - HYDRAULIC/HYDROLOGIC         |   |                 |
| 5.1                                      | Evaluation of Features                      | 11              |
| SECTION 6 - STRUCTURAL STABILITY         |   |                 |
| 6.1                                      | Evaluation of Structural Stability          | 13              |
| SECTION 7 - ASSESSMENT/REMEDIAL MEASURES |   |                 |
| 7.1                                      | Dam Assessment                              | 14              |
| 7.2                                      | Remedial Measures                           | 14              |

TABLE OF CONTENTS (Cont'd)

LIST OF PLATES

| <u>Plate No.</u> | <u>Title</u>               |
|------------------|----------------------------|
| 1                | Location Map               |
| 2                | Vicinity Topography        |
| 3                | Plan                       |
| 4                | Dam Cross Section          |
| 5                | Emergency Spillway Profile |
| 6                | Photo Index                |

LIST OF PHOTOGRAPHS

| <u>Photo No.</u> | <u>Title</u>                            |
|------------------|---|
| 1                | Overview of Dam                         |
| 2                | Upstream Face of Dam                    |
| 3                | Crest of Dam                            |
| 4                | Crest at Right End of Dam               |
| 5                | Downstream Slope of Dam                 |
| 6                | Downstream Slope at Right End of Dam    |
| 7                | Principal Spillway Inlet                |
| 8                | Principal Spillway Outlet               |
| 9                | Highway Ditch below Spillway Outlet     |
| 10               | Highway Culvert Downstream of Dam       |
| 11               | Embankment Erosion Upstream Side of Dam |
| 12               | Seepage Area at Downstream Toe of Dam   |

APPENDIX

Appendix A - Hydrologic and Hydraulic Analyses

## SECTION 1 - PROJECT INFORMATION

### 1.1 GENERAL

a. Authority. The National Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of safety inspection of dams throughout the United States. Pursuant to the above, the District Engineer of the St. Louis District, Corps of Engineers, directed that a safety inspection of the Sky Haven Lake Dam be made.

b. Purpose of Inspection. The purpose of the inspection was to make an assessment of the general condition of the dam with respect to safety, based upon available data and visual inspection, in order to determine if the dam poses hazards to human life or property.

c. Evaluation Criteria. Criteria used to evaluate the dam were furnished by the Department of the Army, Office of the Chief of Engineers, in "Recommended Guidelines for Safety Inspection of Dams." These guidelines were developed with the help of several Federal agencies and many state agencies, professional engineering organizations, and private engineers.

### 1.2 DESCRIPTION OF PROJECT

#### a. Description of Dam and Appurtenances.

(1) The dam is an earth structure located adjacent to Sky Haven Airfield and U.S. Highway 50 in a valley of a tributary to Devil's Branch of Post Oak Creek (Plate 1). The watershed is a low hilly area consisting of a few residences with large grass yards and one runway of the airfield (Plate 2). The dam is approximately 1,075 feet long along the crest and 20 feet high. The dam crest is 18 feet wide, with gravel surface and serves as an access road to the houses around the lake. The downstream face of the dam slopes from the crest to the north ditch of westbound U.S. Highway 50.

(2) The principal spillway from the lake is an uncontrolled 42-inch reinforced concrete pipe without headwalls installed in the embankment. Flow through the pipe discharges into the U.S. Highway 50 drainage ditch. The emergency spillway consists of a low section cut in the natural overburden and embankment. Discharge through the emergency spillway overflows the embankment downstream to the U.S. Highway 50 drainage ditch.

(3) Pertinent physical data are given in paragraph 1.3.

b. Location. The dam is located in central Johnson County, Missouri, as indicated on Plate 1. The lake formed by the dam is shown on the United States Geological Survey 7.5 minute series quadrangle map for Warrensburg West, Missouri in Section 17 of T46N, R26W.

c. Size Classification. Criteria for determining the size classification of dams and impoundments are presented in the guidelines referenced in paragraph 1.1c above. Based on these criteria, the dam and impoundment are in the small size category.

d. Hazard Classification. The hazard classification assigned by the Corps of Engineers for this dam is as follows: The Sky Haven Lake Dam has a high hazard potential, meaning that the dam is located where failure may cause loss of life, and serious damage to homes, agricultural, industrial and commercial facilities, and to important public utilities, main highways, or railroads. For the Sky Haven Lake Dam the estimated flood damage zone extends approximately one mile downstream of the dam. Within the estimated damage zone are the four lane Highway U.S. 50 and about eight trailers.

e. Ownership. The dam is owned by Mr. Eugene V. Fryhoff, 12 N. Buena Vista, Englewood, Florida 33533 Telephone 813/474-8769.

f. Purpose of Dam. The dam forms a 12-acre lake used for recreation and water supply.

g. Design and Construction History. Data relating to the design and construction were not available. The dam was constructed during 1954 and 1955. The principal spillway was relocated by the Missouri Department of Highways when U.S. 50 was increased to a four-lane limited access highway.

h. Normal Operating Procedure. Normal rainfall, runoff, transpiration, evaporation, water supply withdrawals and overflow through the uncontrolled spillways all combine to maintain a relatively stable water surface elevation.

### 1.3 PERTINENT DATA

a. Drainage Area - 62 acres

b. Discharge at Damsite.

(1) Normal discharge at the damsite is through an uncontrolled 42-inch concrete outlet pipe.

- (2) Estimated experienced maximum flood at damsite - Unknown.
- (3) Estimated ungated spillway capacity at maximum pool elevation 65 cfs (50 Percent Probable Maximum Flood Pool El. 783.6).
  - c. Elevation (Feet above m.s.l.).
    - (1) Top of dam - 782.8 (see Plate 3)
    - (2) Emergency spillway crest - 782.2
    - (3) Principal spillway pipe inlet invert - 779.0
    - (4) Principal spillway pipe outlet invert - 778.1
    - (5) Maximum tailwater - Unknown.
  - d. Reservoir.
    - (1) Length of maximum pool - 1,500 feet  $\pm$  (50 percent Probable maximum flood pool level)
    - (2) Length of normal pool - 1,100 feet  $\pm$  (Principal spillway pipe invert)
  - e. Storage (Acre-feet).
    - (1) Top of dam - 109
    - (2) Emergency spillway crest - 98.4
    - (3) Principal spillway pipe invert - 47
    - (4) Design surcharge - Not available.
  - f. Reservoir Surface (Acres).
    - (1) Top of dam - 22.7
    - (2) Emergency spillway crest - 20.9
    - (3) Principal spillway pipe invert - 11.7
  - g. Dam.
    - (1) Type - Earth embankment



- (2) Length - 1,075 feet
- (3) Height - 20 feet ±
- (4) Top width - 18 feet
- (5) Side slopes - upstream face 1.0 V on 2.9 H, downstream face between 1.0 V on 1.7 H and 1.0 V on 3.6 H (see Plate 4).
- (6) Zoning - Unknown.
- (7) Impervious core - Unknown.
- (8) Cutoff - Unknown.
- (9) Grout curtain - Unknown.
- h. Diversion and Regulating Tunnel - None.
- i. Principal Spillway.
  - (1) Type - 42-inch concrete pipe.
  - (2) Inlet invert elevation - 779.0 feet m.s.l.
  - (3) Outlet invert elevation 778.1 feet m.s.l.
  - (4) Gates - None.
  - (5) Upstream channel - Not applicable.
  - (6) Downstream channel - North ditch of westbound U.S. Highway 50.
- j. Emergency Spillway.
  - (1) Type - Grass open channel.
  - (2) Width of channel - 60 feet.
  - (3) Emergency spillway crest - 782.2
  - (4) Gates - None.
  - (5) Upstream channel - Not applicable.
  - (6) Downstream channel - Open channel along toe of the dam to north ditch of westbound U.S. Highway 50.
- k. Regulating Outlets - None.

## SECTION 2 - ENGINEERING DATA

### 2.1 DESIGN

Design data was unavailable.

### 2.2 CONSTRUCTION

Construction records were unavailable, however; according to the owner, the dam was constructed during 1954 and 1955 with assistance of the Department of Agriculture Soil Conservation Service.

### 2.3 OPERATION

Presently, water is pumped from the lake to supply the several houses located around the lake. Supply connections to these homes have been made to begin service from a rural water district in the very near future. The lake supply system will then be put on stand-by service. Documentation of past floods was not available.

### 2.4 GEOLOGY

The site of the dam and reservoir is located in a very broad and shallow valley. The dam impounds a very small intermittent, headwater tributary of Devil's Branch of Post Oak Creek.

The soils in the area of the dam and reservoir consist of the Deepwater, Macksburg and Snead soil series. The Deepwater series consists of deep, moderately well-drained soils formed in residuum weathered from shales on uplands. Bedrock depth is normally greater than five feet. The soils are classified for engineering purposes as low plastic silt (ML) and low-plastic clay (CL). The Macksburg soils consist of deep somewhat poorly-drained, soils formed in loess overlying limestone, shale, or sandstone bedrock. Bedrock depth is normally greater than five feet. The soils are classified for engineering purposes as low-plastic silt (ML) and low plastic clay (CL). The Snead series consists of moderately deep, moderately well-drained soils formed in residuum from thin shale layers underlain by limestone or sandstone. The soils are classified for engineering purposes as low-plastic clay (CL) and low-plastic silty clay to clayey silt (ML-CL).

The bedrock in the area of the dam and reservoir consists of interbedded limestone, shale, sandstone and coal of the Marmaton Group of the lower Pennsylvanian system.

## 2.5 EVALUATION

- a. Availability. No engineering data could be obtained.
- b. Adequacy. No engineering data were available upon which to make a detailed assessment of the design, construction, and operation. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available, which is considered a deficiency. These seepage and stability analyses should be performed for appropriate loading conditions (including earthquake loads) and made a matter of record.
- c. Validity. The validity of the design, construction, and operation could not be determined due to the lack of engineering data.

## SECTION 3 - VISUAL INSPECTION

### 3.1 FINDINGS

a. General. A visual inspection of Sky Haven Lake Dam was made on 5 June 1980. The inspection team consisted of Ed Burton, team leader; Paul Zaman, geotechnical engineer; Andy Dywan, civil engineer; Ray Herzog, geologist; Mark Snyder, hydrologist; and Alan Reif, structural engineer. Specific observations are discussed below. No observations were made of the condition of the upstream face of the dam below the pool elevation at the time of the inspection.

b. Dam. The inspection team observed the following conditions at the dam. No cracks were observed in the embankment. The upstream slope has irregularities in the waterline due to wave action, erosion, undercutting, and some evidence of minor sloughing. No instruments to measure the performance of the dam were located.

Clear seepage was observed at the downstream toe on the right portion of the dam. This seepage extends across an area, parallel to the dam centerline of about 100 feet. No visible flow was evident but the area was saturated. No toe drains or relief wells were observed.

The dam crest has a two-lane gravel roadway which provides access to several residences. The upstream slope of the embankment is faced with some riprap at and below the present waterline. The upstream slope also has many small trees, willows and an occasional cottonwood, brush, and some grass. One cottonwood is 18 inches in diameter. The downstream slope is covered with grass, brush and occasional small trees, the largest about 8 inches in diameter. Some erosion was evident on the upstream slope due to wave action. A vertical step and undercutting from one to two feet were noted in several places. Erosion of the silty clay material was beginning at the top left side of the principal spillway inlet due to runoff from the roadway. No evidence was found to indicate that the embankment had ever been overtopped.

Evidence of maintenance included mowing of grass around the abutments. The roadway gravel surface was well maintained. The power company has cut some brush and small trees beneath the power line located parallel to and on the downstream slope (about 5 feet above the toe). Some riprap had been placed in isolated areas for erosion control. In general, the upstream and downstream slopes were covered with much brush, small trees and is considered to be poorly maintained. No animal burrows were observed.

c. Appurtenant Structures. The inspection team observed the following items pertaining to the appurtenant structures. The principal

spillway is a 42-inch reinforced concrete pipe without headwalls which runs through the embankment to provide uncontrolled discharge. The first 10-foot section of the RCP had settled at the inlet end causing a small separation at the crown of the first joint. Otherwise, alignment of the pipe was fairly good. No evidence of leaking joints was observed. The inlet to the 42-inch RCP was obstructed by a make-shift trash screen stretched across steel stakes and a 2-1/2 inch tree growing about two feet in front of the inlet. The outlet of the RCP spillway were clear of obstructions. About 5 feet of each end of the concrete pipe was inspected. The spillway pipe was found to be in good workable condition.

The emergency spillway consists of a low area at the right end of the dam. This low area is either grass lined or has the roadway gravel surfacing.

The emergency spillway contains no obstructions to flow and is considered to be in satisfactory condition. There was no evidence of erosion upstream or downstream of the spillway. It should be noted that an abnormally large spillway discharge would probably overflow and erode the embankment.

There was no development in the emergency spillway area which could suffer damage due to flow through the spillway.

d. Geology. The soil in the area of the dam and reservoir consisted of sandy clay soil (CL) and localized layers of weathered sandstone. The bedrock consists of sandstone and shale. Sandstone was encountered in a shallow auger boring at the toe of the embankment near the right abutment.

Samples of the embankment materials were taken near the center of the downstream face using an Oakfield sampler. The materials were visually classified as low-plastic silty clay (CL). Based on these samples and visual observations, the embankment is anticipated to consist of low-plastic silty clay (CL).

The abutments of the dam consist of interbedded sandstone and shale of the Marmaton Group. The foundation of the dam is anticipated to be residual silty clay overlying sandstone or shale bedrock.

e. Reservoir Area. No slumping or slides of the reservoir banks were observed. The area considered as the upstream channel to the lake contains no defined channel but a very small area of residential grass yards and one runway of the Sky Haven Airfield. The residential grass yards were well maintained and should drain well. The lake contains a minor amount of siltation.

f. Downstream Channel. The channel downstream of the spillways is the north ditch of the west bound U.S. Highway 50. A 42-inch culvert passes under the highway about 250 feet west of the principal spillway pipe outlet. The ditch continues to the west to another culvert approximately 1200 feet west of the principal spillway pipe outlet which is located at the low point of the ditch where the highway crosses a natural stream. There are no obstructions to flow in the highway ditch. The highway constitutes a major obstruction.

### 3.2 EVALUATION

The various deficiencies observed at the time of the inspection are not believed to represent an immediate safety hazard. They do, however, warrant monitoring and control. The poor quality of riprap on the face of the dam has resulted in wave action erosion of the embankment. If not corrected, wave action will continue to erode the embankment and could lead to slope stability problems. The separated joint of the principal spillway pipe can result in leakage from the pipe during high flows which in turn can lead to erosion of material from around the pipe resulting in displacement of the pipe and/or failure of the embankment. The growth of small trees and brush and the uncut grass is not presently a serious problem, but if allowed to go unchecked, it could cause deterioration of the embankment. The roots of trees can loosen the embankment material and also can leave voids through which water can pass. Brush on the dam prevents inspection of the embankment and kills the smaller grasses whose roots are more effective in protecting the surface soil of the slope from erosion. The brush and tall uncut grass provides habitat for burrowing animals which can damage the embankment. The area of seepage which was observed should be monitored regularly for quality and quantity. Seepage can cause internal erosion creating cavities and underground channels, thereby weakening the embankment and/or abutments.

## SECTION 4 - OPERATIONAL PROCEDURES

### 4.1 PROCEDURES

The pool is primarily controlled by rainfall, runoff, pumped withdrawals for water supply to several residences, evaporation, transpiration, and capacity of the uncontrolled spillways.

### 4.2 MAINTENANCE OF DAM

There is no regular systematic maintenance program, but the Homes Association looks after the water supply facilities and the access road on the crest. Also, the Missouri Department of Highways and the power company have done some cutting of brush and small trees on the downstream slope along the toe of the embankment where the powerline runs parallel to the dam for several hundred feet.

### 4.3 MAINTENANCE OF OPERATING FACILITIES

No operating facilities exist.

### 4.4 DESCRIPTION OF ANY WARNING SYSTEM IN EFFECT

There is no existing warning system or preplanned scheme for alerting downstream residents for this dam.

### 4.5 EVALUATION

A systematic maintenance program should be started to include mowing the grass cover on the embankment in order to discourage animal burrowing. The brush and trees on the embankment should be removed more frequently. The areas of seepage should be monitored periodically and, if flows increase significantly or if seepage flows become muddy, a qualified engineer should be consulted.

## SECTION 5 - HYDRAULIC/HYDROLOGIC

### 5.1 EVALUATION OF FEATURES

a. Design Data. Design data pertaining to hydrology and hydraulics were unavailable.

b. Experience Data. The drainage area and lake surface area are developed from USGS Warrensburg West Quadrangle Map. The dam layout is from a survey made during the inspection.

c. Visual Observations.

(1) The principal spillway appears to be in good condition. The lake level at the time of the inspection was at the inlet level and there was no flow through the pipe. About five feet of the inlet and outlet ends were exposed and in good condition. There was no headwall at either end. The first 10-foot section of the pipe had settled at the inlet end causing a small separation at the crown of the first joint. Otherwise, the alignment of the pipe was fairly good and there was no evidence of leaky joints. The spillway pipe discharges into the north ditch of west-bound U.S. Highway 50. Discharges can flow west along the ditch of U.S. Highway 50 or pass under U.S. Highway 50 through a 42-inch diameter concrete culvert.

(2) The emergency spillway channel is in good condition with no evidence of erosion at the time of the inspection.

(3) Spillway discharges do not endanger the integrity of the dam.

d. Overtopping Potential. The spillways will not pass the probable maximum flood without overtopping the dam. The probable maximum flood is defined as the flood discharge that may be expected from the most severe combination of critical meteorologic and hydrologic conditions that are reasonably possible in the region. The spillways will pass 60 percent of the probable maximum flood without overtopping the dam. The spillways will also pass the one percent probability flood estimated to have a peak outflow of 11 cfs developed by a 24-hour, one percent probability rainfall. According to the recommended guidelines from the Department of the Army, Office of the Chief of Engineers, a high hazard dam of small size should pass 50 to 100 percent of the probable maximum flood. Considering the volume of water impounded by the dam and the downstream hazard, the appropriate spillway design flood should be 50 percent of the probable maximum flood. The portion of the estimated peak discharge of the probable maximum flood overtopping the dam would be 480 cfs of the total discharge from the reservoir of 800 cfs. The estimated duration of overtopping is 3.3 hours with a maximum height of 0.8 feet. The embankment could be jeopardized by overtopping for this period of time.



According to the St. Louis District, Corps of Engineers, the effect from rupture of the dam could extend approximately one mile downstream of the dam. Within the estimated damage zone are U.S. Highway 50 and approximately eight trailers.

There does not appear to be any flood plain regulations or other constraints in force to limit future downstream development.

## SECTION 6 - STRUCTURAL STABILITY

### 6.1 EVALUATION OF STRUCTURAL STABILITY

a. Visual Observations. Visual observations of conditions which affect the structural stability of this dam are discussed in Section 3, paragraph 3.1b.

b. Design and Construction Data. No design data relating to the structural stability of the dam were found. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available, which is considered a deficiency.

c. Operating Records. No operational records exist.

d. Postconstruction Changes. The principal spillway was relocated by the Missouri Department of Highways when U.S. 50 was increased to a four-lane limited access highway.

e. Seismic Stability. The dam is located in Seismic Zone 1 which is considered a zone of minor seismic risk. A properly designed and constructed earth dam using sound engineering principles and conservatism should pose no serious stability problems during earthquakes in this zone.

The seismic stability of an earth dam is dependent upon a number of factors: embankment and foundation material classifications and shear strengths; abutment materials, conditions, and strengths; embankment zoning; and embankment geometry.

Adequate descriptions of embankment design parameters, foundation and abutment conditions, or static stability analyses to assess the seismic stability of this embankment were not available and therefore no inferences will be made regarding the seismic stability. An assessment of the seismic stability should be included as part of the stability analysis required by the guidelines.

## SECTION 7 - ASSESSMENT/REMEDIAL MEASURES

### 7.1 DAM ASSESSMENT

a. Safety. Several conditions observed during the visual inspection by the inspection team should be monitored and/or controlled. These are erosion and sloughing of the upstream face of the embankment at normal lake level due to undercutting of the slope by wave action, settlement of one section of the principal spillway pipe, seepage from the right section of the dam, and the growth of brush and trees on the embankment.

b. Adequacy of Information. Due to the inadequacy of engineering design data, the conclusions in this report were based only on performance history and visual conditions. The inspection team considers that these data are sufficient to support the conclusions herein. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available, which is considered a deficiency.

c. Urgency. It is the opinion of the inspection team that a program should be developed as soon as possible to implement remedial measures recommended in paragraph 7.2b. If the safety deficiencies listed in paragraph 7.1a are not corrected, they will continue to deteriorate and lead to a serious potential of failure.

d. Necessity for Phase II. The Phase I investigation does not raise any serious questions relating to the safety of the dam nor does it identify any serious dangers which would require a Phase II investigation. However, the additional analyses noted in paragraph 2.5.b are necessary for compliance with the guidelines.

e. Seismic Stability. This dam is located in Seismic Zone 1. Adequate description of embankment design parameters, foundation and abutment conditions, or static stability analyses to assess the seismic stability of this embankment was not available and therefore no inferences will be made regarding the seismic stability. An assessment of the seismic stability should be included as part of the recommended stability analysis.

### 7.2 REMEDIAL MEASURES

a. Alternatives. No alternative measures other than those noted in paragraph 7.2.b. below are recommended.

b. Operation and Maintenance Procedures. The following operation and maintenance procedures should be carried out under the direction of an engineer experienced in the design, construction, and inspection of dams:

(1) Erosion damage to the upstream face of the dam should be repaired and riprap should be placed on the upstream face of the dam at the normal lake level to prevent erosion of the embankment material.


(2) The separated joint of the first section of the principal spillway pipe should be repaired to prevent leakage from the joint during high flows.

(3) The seepage areas noted during the visual inspection should be closely monitored and documented as to quantity and quality of flow. If flow increases significantly or if seepage flow becomes muddy, a qualified engineer should be consulted.

(4) An improved maintenance program to remove and control the growth of brush and trees on the embankment should be developed. Grass cover on the embankments should be cut periodically.

(5) Seepage and stability analysis should be performed.

(6) A detailed inspection of the dam should be made periodically. This inspection should include measurement of seepage flows and analyzing water samples taken from the seeps and lake. More frequent inspections may be required if additional deficiencies are observed or the severity of the reported deficiencies increase.




**SKY HAVEN LAKE  
LOCATION MAP**


SCALE IN MILES



**PLATE I**



**SKY HAVEN LAKE  
VICINITY TOPOGRAPHY**








PLATE 3



**SKY HAVEN LAKE DAM  
DAM CROSS SECTION**



SKY HAVEN LAKE LEVEL  
AT TIME OF INSPECTION  
EL. 779.0



# SKY HAVEN LAKE DAM EMERGENCY SPILLWAY PROFILE

**LEGEND**

① PHOTO NO. & DIRECTION

② OF EMERGENCY SPILLWAY

③ 1 1/2" Ø PVC. PIPE FOR WATER SUPPLY


④ WATER PUMP HOUSE

⑤ SEEPAGE AREA

⑥ WEST BOUND OF U.S. HWY. 50

⑦ DRAINAGE DITCH

SKY HAVEN LAKE



SKY HAVEN LAKE DAM  
PHOTO INDEX



SCALE IN FEET



PHOTO 1: UPSTREAM FACE OF DAM



PHOTO 2: UPSTREAM FACE AT RIGHT END OF DAM



PHOTO 3: CREST OF DAM



PHOTO 4: CREST AT RIGHT END OF DAM



PHOTO 5: DOWNSTREAM SLOPE OF DAM



PHOTO 6: DOWNSTREAM SLOPE AT RIGHT END OF DAM



PHOTO 7: PRINCIPAL SPILLWAY INLET



PHOTO 8: PRINCIPAL SPILLWAY OUTLET




PHOTO 9: HIGHWAY DITCH BELOW SPILLWAY OUTLET



PHOTO 10: HIGHWAY CULVERT DOWNSTREAM OF DAM




PHOTO 11: EMBANKMENT EROSION UPSTREAM SIDE OF DAM



PHOTO 12: SEEPAGE AREA AT DOWNSTREAM TOE OF DAM



**APPENDIX A**  
**HYDROLOGIC AND HYDRAULIC ANALYSES**

## HYDROLOGIC AND HYDRAULIC ANALYSES

To determine the overtopping potential, flood routings were performed by applying the Probable Maximum Precipitation (PMP) to a synthetic unit hydrograph to develop the inflow hydrograph. The inflow hydrograph was then routed through the reservoir and spillways. The overtopping analysis was determined using the computer program HEC-1 (Dam Safety Version) (1).

The PMP was determined from regional charts prepared by the National Weather Service in "Hydrometeorological Report No. 33" (HMR-33). Reduction factors were not applied. The rainfall distribution for the 24-hour PMP storm was determined according to the procedures outlined in HMR-33 and EM 1110-2-1411. The Sweet Springs, Missouri rainfall distribution (5 min. interval - 24 hours duration), as provided by the St. Louis District, Corp of Engineers, was used when the one percent chance probability flood was routed through the reservoir and spillways.

The synthetic unit hydrograph for the watershed was developed by the computer program using the Soil Conservation Service (SCS) method. The parameters for the unit hydrograph are shown in Table 1.

The SCS curve number (CN) method was used in computing the infiltration losses for rainfall-runoff relationship. The CN values used, and the result from the computer output, are shown in Table 2.

The reservoir routing was performed using the Modified Puls Method. The initial reservoir pool elevation for the routing of each storm was determined to be equivalent to the pipe invert elevation of the principal spillway at elevation 779.0 feet m.s.l. in accordance with antecedent storm conditions preceding the one percent probability and probable maximum storms outlined by the U.S. Army Corps of Engineers, St. Louis District (2). The hydraulic capacity of the spillway and the storage capacity of the reservoir were defined by the elevation, surface area, storage, and discharge relationships shown in Table 3.

The rating curve for the spillways is shown in Table 4. The flow over the crest of the dam and emergency spillway was determined using the non-level dam crest option (\$L and \$V cards) of the HEC-1 program. The program assumes critical flow over a broad-crested weir. The flow through the principal spillway was determined from nomographs for pipe culverts with inlet and outlet control (3). It was assumed that the trash screen is kept free of debris.

The result of the routing analyses indicates that 60 percent of the PMF will not overtop the dam.

A summary of the routing analysis for different ratios of the PMF is shown in Table 5.

The computer input data and a summary of the output data are presented at the back of this appendix.

TABLE 1  
SYNTHETIC UNIT HYDROGRAPH

Parameters:

|   |   |
|---|---|
| Drainage Area (A)                       | 62 acres  |
| Hydraulic Length of Watercourse (L)     | 1,000 feet  |
| Elevation Differences in Watershed (H)  | 23 feet   |
| Wave Velocity (V)                       | 19.3 feet per second  |
| Length of Reservoir (L <sub>w</sub> )   | 1,150 feet  |
| Lag Time (L <sub>g</sub> )              | 4.7 minutes (AMC II and AMC III)                            |
| Time of concentration (T <sub>c</sub> ) | 7.8 minutes<br>2.48 hours (AMC II and AMC III)              |
| Duration (D)                            | 1 min. (AMC II and AMC III)<br>(use 5 minutes in each case) |

| <u>Time (Min.) *</u> | <u>Discharge (cfs) *</u> |
|----------------------|--------------------------|
| 0                    | 311                      |
| 5                    | 301                      |
| 10                   | 95                       |
| 15                   | 30                       |
| 20                   | 10                       |
| 25                   | 3                        |
| 30                   | 0                        |

\* From HEC-1 computer output

FORMULAS USED:

$$T_c = (11.9 \times L^3/H)^{0.385} + V/Lw \text{ (4 and 5)}$$

$$L_g = 0.6 T_c$$

$$D = 0.133 T_c$$

TABLE 2

RAINFALL-RUNOFF VALUES

| <u>Selected Storm<br/>Event</u> | <u>Storm Duration<br/>(Hours)</u> | <u>Rainfall<br/>(Inches)</u> | <u>Runoff<br/>(Inches)</u> | <u>Loss<br/>(Inches)</u> |
|---------------------------------|-----------------------------------|------------------------------|----------------------------|--------------------------|
| PMP                             | 24                                | 32.17                        | 30.45                      | 1.72                     |
| 1% Probability                  | 24                                | 7.49                         | 4.36                       | 3.13                     |

Additional Data:

- 1) The soil associations in this watershed are Deepwater and Macksburg (6).  
60 percent of drainage area in hydrologic soil group B.  
40 percent of drainage area in hydrologic soil group C.  
100 percent of the land use was grassland.
- 2) SCS Runoff Curve CN = 87 (AMC III) for the PMF.
- 3) SCS Runoff Curve CN = 73 (AMC II) for the one percent probability flood (5).

TABLE 3

ELEVATION, SURFACE AREA, STORAGE, AND DISCHARGE RELATIONSHIPS

| <u>Elevation<br/>(feet-MSL)</u> | <u>Lake Surface<br/>Area (acres)</u> | <u>Lake Storage<br/>(acre-ft)</u> | <u>Spillway<br/>Discharge (cfs)</u> |
|---------------------------------|--------------------------------------|-----------------------------------|-------------------------------------|
| *779.0                          | 11.7                                 | 47                                | 0                                   |
| **782.2                         | 20.9                                 | 98                                | 45                                  |
| ***782.8                        | 22.7                                 | 109                               | 94                                  |

\*Principal spillway pipe invert elevation

\*\*Emergency spillway crest elevation

\*\*\*Top of dam elevation

The relationships in Table 3 were developed from the Warrensburg West, Missouri 7.5 minute quadrangle map and the field measurements.

TABLE 4

SPILLWAY RATING CURVE

| <u>Reservoir<br/>Elevation (ft-msl)</u> | <u>Principal Spillway<br/>Discharge (cfs)</u> | <u>Emergency Spillway<br/>Discharge (cfs)</u> | <u>Total Spillway<br/>Discharges (cfs)</u> |
|---|---|---|--|
| 779.0                                   | 0   | 0   | 0  |
| 781.0                                   | 21  | 0   | 21   |
| 782.0                                   | 38  | 0   | 38   |
| *782.2                                  | 45  | 0   | 45   |
| 782.5                                   | 55  | 5   | 60   |
| **782.8                                 | 62  | 32  | 94   |

\*Emergency Spillway Crest Elevation

\*\*Top of Dam Elevation

METHOD USED:

Principal spillway release rates were determined by nomographs for pipe culverts with inlet and outlet control (3).

Emergency spillway releases were computed by HEC-1 from spillway geometry data input on \$L and \$V cards. The following equations were used in calculating the emergency spillway discharge:

$$d_c = 2/3 (H_m + 1/4 Y)$$

$$A = 1/2 T (2d_c - Y)$$

$$Q = (A^3 g/T)^{0.5}$$

where:

$d_c$  = critical depth (feet)

$H_m$  = available specific energy which is taken to be the height of the water surface in the reservoir above the bottom of the section (feet)

Y = change in elevation across the section (feet)

A = flow area (sq. ft.)

T = top width (feet)

Q = flow (cfs)

g = 32.2 ft/sec<sup>2</sup> = acceleration due to gravity.

TABLE 5

RESULTS OF FLOOD ROUTINGS

| Ratio<br>of<br>PMF | Peak<br>Inflow<br>(CFS) | Peak Lake<br>Elevation<br>(ft.-MSL) | Total<br>Storage<br>(AC.-FT.) | Peak<br>Outflow<br>(CFS) | Depth<br>(ft.)<br>Over Top<br>of Dam |
|--------------------|-------------------------|-------------------------------------|-------------------------------|--------------------------|--------------------------------------|
| -                  | 0                       | *779.0                              | 47                            | 0                        | -                                    |
| 0.50               | 696                     | 782.6                               | 104                           | 65                       | 0                                    |
| 0.60               | 835                     | 782.8                               | 109                           | 94                       | 0                                    |
| 1.00               | 1,392                   | 783.6                               | 127                           | 805                      | 0.8                                  |

\* Principal spillway pipe invert elevation

## BIBLIOGRAPHY

- (1) U.S. Army Corps of Engineers, Hydrologic Engineering Center, Flood Hydrograph Package (HEC-1), Dam Safety Version, July 1978, Davis, California.
- (2) U.S. Army Corps of Engineers, St. Louis District, Hydrologic/Hydraulic Standards, Phase I Safety Inspection of Non-Federal Dams, 12 December 1979.
- (3) U.S. Department of Commerce, Bureau of Public Roads, Hydraulic Engineering Circular No. 5, Hydraulic Charts for the Selection of Highway Culverts, December, 1965.
- (4) U.S. Department of the Interior, Bureau of Reclamation, Design of Small Dams, 1974, Washington, D.C.
- (5) U.S. Department of Agriculture, Soil Conservation Service, National Engineering Handbook, Section 4, Hydrology, August 1972.
- (6) U.S. Department of Agriculture, Soil Conservation Service, Soils Report for Johnson County, Missouri.
- (7) U.S. Department of Agriculture, Soil Conservation Service, Soil Survey Interpretations and Field Maps, 1980.
- (8) Mary H. McCracken, Missouri Division of Geological Survey, Geologic Map of Missouri, 1961.



FLOOD HYDROGRAPH PACKAGE (MEC-1)  
 DAM SAFETY VERSION JULY 1973  
 LAST MODIFICATION 06 FEB 80

MISSOURI DAM INSPECTION PROGRAM  
 2ND DISTRICT US ARMY CORPS OF ENGINEERS  
 ASSKY HAVEN LAKE DAM

|    |   |   |   |   |   |   |   |   |   |
|----|---|---|---|---|---|---|---|---|---|
| 1  | 0 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2  | 0 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 3  | 0 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 4  | 0 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 5  | 0 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 6  | 0 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 7  | 0 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 8  | 0 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 9  | 0 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 10 | 0 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 11 | 0 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 12 | 0 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 13 | 0 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 14 | 0 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 15 | 0 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 16 | 0 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 17 | 0 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 18 | 0 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 19 | 0 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 20 | 0 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 21 | 0 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 22 | 0 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 23 | 0 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 24 | 0 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 25 | 0 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 26 | 0 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 27 | 0 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 28 | 0 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 29 | 0 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

FLOOD HYDROGRAPH PACKAGE (NEC-1)  
 BAR SAFETY VERSION JULY 1976  
 LAST MODIFICATION 06 FEB 80

MISSOURI DAM INSPECTION PROGRAM  
 ST. LOUIS DISTRICT US ARMY CORPS OF ENGINEERS  
 SKY HAVEN LAKE DAM

JOB SPECIFICATION  
 NO NHR ANIN IDAY IMA IMIN METRC IPLT IPRT NSTAN  
 288 0 5 0 0 0 0 0 0 0 0  
 JOPER NVT LROPT TRACE  
 5 0 0 0

MULTI-PLAN ANALYSES TO BE PERFORMED  
 MPLAN= 1 NRATIO= 6 LRATIO= 1  
 RTIOS= .50 .55 .60 .65 .70 1.00

SUB-AREA RUNOFF COMPUTATION  
 SKY HAVEN LAKE (24 HR. PROBABLE MAXIMUM RUNOFF)

ISTAG ICOMP IECON ITAPE IJPLT IPRT INAME ISAGE ISAUTO  
 1 0 0 0 0 0 3 1 0 0

PRECIP DATA  
 INYDC IJHL TAREA SHAP TRSDA TRSPC RATIO ISNOB ISAME LOCAL  
 1 2 .10 .00 .10 1.00 .000 0 0 0 0  
 SPFE PMS AQ RTZ R24 R4F R72 R96  
 .00 24.75 101.00 120.50 130.50 .00 .00 .00 .00

RECSSION DATA  
 LROPT STRAP DLTKR RTIOL ERJIN SINES RTIOW STIHL CSHYL ALSHY RTIMP  
 0 .00 .00 1.00 .00 .00 1.00 -1.00 -87.00 .00 .00  
 CURVE NO = -87.00 VEINNESS = -1.00 EFFECT CN = RT.00

UNIT HYDROGRAPH DATA  
 TC= .00 LAG= .00  
 SIEIIE .00 RECSION DATA  
 .00 RECSION DATA  
 RIIOB= 1.00

TIME INCREMENT TOO LARGE--(NHR IS 67 LAG/2)  
 UNIT HYDROGRAPH 7 END OF PERIOD ORDINATES. TC= .00 HOURS, LAG= .08 VOL= 1.00  
 319. 301. 95. 30. 10. 3. 0. 0.



|      |      |     |     |     |     |      |       |     |     |     |      |
|------|------|-----|-----|-----|-----|------|-------|-----|-----|-----|------|
| 1.01 | 4.30 | 54  | .01 | .01 | 4.  | 1.01 | 16.30 | 198 | .29 | .00 | 218. |
| 1.01 | 4.35 | 55  | .01 | .01 | 4.  | 1.01 | 16.35 | 199 | .29 | .00 | 218. |
| 1.01 | 4.40 | 56  | .01 | .01 | 4.  | 1.01 | 16.40 | 200 | .29 | .00 | 218. |
| 1.01 | 4.45 | 57  | .01 | .01 | 4.  | 1.01 | 16.45 | 201 | .29 | .00 | 218. |
| 1.01 | 4.50 | 58  | .01 | .01 | 4.  | 1.01 | 16.50 | 202 | .29 | .00 | 218. |
| 1.01 | 4.55 | 59  | .01 | .01 | 4.  | 1.01 | 16.55 | 203 | .29 | .00 | 218. |
| 1.01 | 5.00 | 60  | .01 | .01 | 5.  | 1.01 | 17.00 | 204 | .29 | .00 | 218. |
| 1.01 | 5.05 | 61  | .01 | .01 | 5.  | 1.01 | 17.05 | 205 | .29 | .00 | 218. |
| 1.01 | 5.10 | 62  | .01 | .01 | 5.  | 1.01 | 17.10 | 206 | .29 | .00 | 218. |
| 1.01 | 5.15 | 63  | .01 | .01 | 5.  | 1.01 | 17.15 | 207 | .29 | .00 | 218. |
| 1.01 | 5.20 | 64  | .01 | .01 | 5.  | 1.01 | 17.20 | 208 | .29 | .00 | 218. |
| 1.01 | 5.25 | 65  | .01 | .01 | 5.  | 1.01 | 17.25 | 209 | .29 | .00 | 218. |
| 1.01 | 5.30 | 66  | .01 | .01 | 5.  | 1.01 | 17.30 | 210 | .29 | .00 | 218. |
| 1.01 | 5.35 | 67  | .01 | .01 | 5.  | 1.01 | 17.35 | 211 | .29 | .00 | 218. |
| 1.01 | 5.40 | 68  | .01 | .01 | 5.  | 1.01 | 17.40 | 212 | .29 | .00 | 218. |
| 1.01 | 5.45 | 69  | .01 | .01 | 5.  | 1.01 | 17.45 | 213 | .29 | .00 | 218. |
| 1.01 | 5.50 | 70  | .01 | .01 | 5.  | 1.01 | 17.50 | 214 | .29 | .00 | 218. |
| 1.01 | 5.55 | 71  | .01 | .01 | 5.  | 1.01 | 17.55 | 215 | .29 | .00 | 218. |
| 1.01 | 6.00 | 72  | .01 | .01 | 5.  | 1.01 | 18.00 | 216 | .29 | .00 | 218. |
| 1.01 | 6.05 | 73  | .07 | .04 | 14. | 1.01 | 18.05 | 217 | .62 | .00 | 197. |
| 1.01 | 6.10 | 74  | .07 | .04 | 21. | 1.01 | 18.10 | 218 | .02 | .00 | 64.  |
| 1.01 | 6.15 | 75  | .07 | .04 | 27. | 1.01 | 18.15 | 219 | .02 | .00 | 23.  |
| 1.01 | 6.20 | 76  | .07 | .04 | 29. | 1.01 | 18.20 | 220 | .02 | .00 | 18.  |
| 1.01 | 6.25 | 77  | .07 | .04 | 30. | 1.01 | 18.25 | 221 | .02 | .00 | 16.  |
| 1.01 | 6.30 | 78  | .07 | .04 | 31. | 1.01 | 18.30 | 222 | .02 | .00 | 15.  |
| 1.01 | 6.35 | 79  | .07 | .04 | 32. | 1.01 | 18.35 | 223 | .02 | .00 | 15.  |
| 1.01 | 6.40 | 80  | .07 | .04 | 33. | 1.01 | 18.40 | 224 | .02 | .00 | 15.  |
| 1.01 | 6.45 | 81  | .07 | .05 | 34. | 1.01 | 18.45 | 225 | .02 | .00 | 15.  |
| 1.01 | 6.50 | 82  | .07 | .05 | 35. | 1.01 | 18.50 | 226 | .02 | .00 | 15.  |
| 1.01 | 6.55 | 83  | .07 | .05 | 35. | 1.01 | 18.55 | 227 | .02 | .00 | 15.  |
| 1.01 | 7.00 | 84  | .07 | .05 | 36. | 1.01 | 19.00 | 228 | .02 | .00 | 15.  |
| 1.01 | 7.05 | 85  | .07 | .05 | 36. | 1.01 | 19.05 | 229 | .02 | .00 | 15.  |
| 1.01 | 7.10 | 86  | .07 | .05 | 37. | 1.01 | 19.10 | 230 | .02 | .00 | 15.  |
| 1.01 | 7.15 | 87  | .07 | .05 | 37. | 1.01 | 19.15 | 231 | .02 | .00 | 15.  |
| 1.01 | 7.20 | 88  | .07 | .05 | 38. | 1.01 | 19.20 | 232 | .02 | .00 | 15.  |
| 1.01 | 7.25 | 89  | .07 | .05 | 38. | 1.01 | 19.25 | 233 | .02 | .00 | 15.  |
| 1.01 | 7.30 | 90  | .07 | .05 | 39. | 1.01 | 19.30 | 234 | .02 | .00 | 15.  |
| 1.01 | 7.35 | 91  | .07 | .05 | 39. | 1.01 | 19.35 | 235 | .02 | .00 | 15.  |
| 1.01 | 7.40 | 92  | .07 | .05 | 40. | 1.01 | 19.40 | 236 | .02 | .00 | 15.  |
| 1.01 | 7.45 | 93  | .07 | .05 | 40. | 1.01 | 19.45 | 237 | .02 | .00 | 15.  |
| 1.01 | 7.50 | 94  | .07 | .05 | 40. | 1.01 | 19.50 | 238 | .02 | .00 | 15.  |
| 1.01 | 7.55 | 95  | .07 | .05 | 41. | 1.01 | 19.55 | 239 | .02 | .00 | 15.  |
| 1.01 | 8.00 | 96  | .07 | .05 | 41. | 1.01 | 20.00 | 240 | .02 | .00 | 15.  |
| 1.01 | 8.05 | 97  | .07 | .06 | 41. | 1.01 | 20.05 | 241 | .02 | .00 | 15.  |
| 1.01 | 8.10 | 98  | .07 | .06 | 41. | 1.01 | 20.10 | 242 | .02 | .00 | 15.  |
| 1.01 | 8.15 | 99  | .07 | .06 | 42. | 1.01 | 20.15 | 243 | .02 | .00 | 15.  |
| 1.01 | 8.20 | 100 | .07 | .06 | 42. | 1.01 | 20.20 | 244 | .02 | .00 | 15.  |
| 1.01 | 8.25 | 101 | .07 | .06 | 42. | 1.01 | 20.25 | 245 | .02 | .00 | 15.  |
| 1.01 | 8.30 | 102 | .07 | .06 | 42. | 1.01 | 20.30 | 246 | .02 | .00 | 15.  |
| 1.01 | 8.35 | 103 | .07 | .06 | 43. | 1.01 | 20.35 | 247 | .02 | .00 | 15.  |
| 1.01 | 8.40 | 104 | .07 | .06 | 43. | 1.01 | 20.40 | 248 | .02 | .00 | 15.  |
| 1.01 | 8.45 | 105 | .07 | .06 | 43. | 1.01 | 20.45 | 249 | .02 | .00 | 15.  |
| 1.01 | 8.50 | 106 | .07 | .06 | 43. | 1.01 | 20.50 | 250 | .02 | .00 | 15.  |
| 1.01 | 8.55 | 107 | .07 | .06 | 43. | 1.01 | 20.55 | 251 | .02 | .00 | 15.  |
| 1.01 | 9.00 | 108 | .07 | .06 | 43. | 1.01 | 21.00 | 252 | .02 | .00 | 15.  |
| 1.01 | 9.05 | 109 | .07 | .06 | 43. | 1.01 | 21.05 | 253 | .02 | .00 | 15.  |

| TIME       | PEAK | 6-HOUR | 24-HOUR | 72-HOUR    | TOTAL VOLUME    |
|------------|------|--------|---------|------------|-----------------|
| 1.01 9.10  | .07  | .06    | .01     | 1.01 21.10 | 254 .02 .00 15. |
| 1.01 9.15  | .07  | .06    | .01     | 1.01 21.15 | 255 .02 .00 15. |
| 1.01 9.20  | .07  | .06    | .01     | 1.01 21.20 | 256 .02 .00 15. |
| 1.01 9.25  | .07  | .06    | .01     | 1.01 21.25 | 257 .02 .00 15. |
| 1.01 9.30  | .07  | .06    | .01     | 1.01 21.30 | 258 .02 .00 15. |
| 1.01 9.35  | .07  | .06    | .01     | 1.01 21.35 | 259 .02 .00 15. |
| 1.01 9.40  | .07  | .06    | .01     | 1.01 21.40 | 260 .02 .00 15. |
| 1.01 9.45  | .07  | .06    | .01     | 1.01 21.45 | 261 .02 .00 15. |
| 1.01 9.50  | .07  | .06    | .01     | 1.01 21.50 | 262 .02 .00 15. |
| 1.01 9.55  | .07  | .06    | .01     | 1.01 21.55 | 263 .02 .00 15. |
| 1.01 10.00 | .07  | .06    | .01     | 1.01 22.00 | 264 .02 .00 15. |
| 1.01 10.05 | .07  | .06    | .01     | 1.01 22.05 | 265 .02 .00 15. |
| 1.01 10.10 | .07  | .06    | .01     | 1.01 22.10 | 266 .02 .00 15. |
| 1.01 10.15 | .07  | .06    | .01     | 1.01 22.15 | 267 .02 .00 15. |
| 1.01 10.20 | .07  | .06    | .01     | 1.01 22.20 | 268 .02 .00 15. |
| 1.01 10.25 | .07  | .06    | .01     | 1.01 22.25 | 269 .02 .00 15. |
| 1.01 10.30 | .07  | .06    | .01     | 1.01 22.30 | 270 .02 .00 15. |
| 1.01 10.35 | .07  | .06    | .01     | 1.01 22.35 | 271 .02 .00 15. |
| 1.01 10.40 | .07  | .06    | .01     | 1.01 22.40 | 272 .02 .00 15. |
| 1.01 10.45 | .07  | .06    | .01     | 1.01 22.45 | 273 .02 .00 15. |
| 1.01 10.50 | .07  | .06    | .01     | 1.01 22.50 | 274 .02 .00 15. |
| 1.01 10.55 | .07  | .06    | .01     | 1.01 22.55 | 275 .02 .00 15. |
| 1.01 11.00 | .07  | .06    | .01     | 1.01 23.00 | 276 .02 .00 15. |
| 1.01 11.05 | .07  | .06    | .01     | 1.01 23.05 | 277 .02 .00 15. |
| 1.01 11.10 | .07  | .06    | .01     | 1.01 23.10 | 278 .02 .00 15. |
| 1.01 11.15 | .07  | .06    | .01     | 1.01 23.15 | 279 .02 .00 15. |
| 1.01 11.20 | .07  | .06    | .01     | 1.01 23.20 | 280 .02 .00 15. |
| 1.01 11.25 | .07  | .06    | .01     | 1.01 23.25 | 281 .02 .00 15. |
| 1.01 11.30 | .07  | .06    | .01     | 1.01 23.30 | 282 .02 .00 15. |
| 1.01 11.35 | .07  | .06    | .01     | 1.01 23.35 | 283 .02 .00 15. |
| 1.01 11.40 | .07  | .06    | .01     | 1.01 23.40 | 284 .02 .00 15. |
| 1.01 11.45 | .07  | .06    | .01     | 1.01 23.45 | 285 .02 .00 15. |
| 1.01 11.50 | .07  | .06    | .01     | 1.01 23.50 | 286 .02 .00 15. |
| 1.01 11.55 | .07  | .06    | .01     | 1.01 23.55 | 287 .02 .00 15. |
| 1.01 12.00 | .07  | .06    | .01     | 1.02 .00   | 288 .02 .00 15. |

SUM 32.17 30.45 1.73 22816.  
 (.817316 772.69 66.31 668.08)

| PEAK       | 6-HOUR | 24-HOUR | 72-HOUR | TOTAL VOLUME |
|------------|--------|---------|---------|--------------|
| 1392.      | 257.   | 79.     | 79.     | 22816.       |
| 39.        | 7.     | 2.      | 2.      | 667.         |
| INCHES     | 64.61  | 30.42   | 30.42   | 30.42        |
| MM         | 645.17 | 772.69  | 772.69  | 772.69       |
| AC-FT      | 127.   | 157.    | 157.    | 157.         |
| THOUS CU M | 157.   | 194.    | 194.    | 194.         |

HYDROGRAPH AT STA 1 FOR PLAN 1, RT10.1

| PEAK   | 6-HOUR | 24-HOUR | 72-HOUR | TOTAL VOLUME |
|--------|--------|---------|---------|--------------|
| 496.   | 128.   | 42.     | 42.     | 11420.       |
| 20.    | 4.     | 1.      | 1.      | 323.         |
| INCHES | 12.31  | 15.21   | 15.21   | 15.21        |
| MM     | 312.59 | 386.35  | 386.35  | 386.35       |

CFS 1392. 257. 79. 79. 22639.  
 CMS 39. 39. 2. 2. 647.  
 INCHES 14.61 30.62 30.62 30.62 9.62  
 MM 625.17 772.69 772.69 772.69 772.69  
 AC-FI 127. 157. 157. 157. 157.  
 THOUS CU N 157. 194. 194. 194. 194.

HYDROGRAPH ROUTING

ROUTE THROUGH SPILLWAY

1STAB 2 ICOMP 1 IECON 0 ITAPE 0 JPLT 0 JPRT 0 INAME 1STAGE 1AUTO 0  
 GLOSS 0.00 AVG 0.00 IRMS 1 ISAKE 1 IOPT 0 IPRP 0 LSTR 0  
 NSTPS 1 NSTDL 0 LAG 0 ARSKK 2 TSK STORA 1SPRAT -1

STAGE 779.00 780.75 781.00 781.50 782.00 782.50 783.00 783.50 784.00 784.50  
 FLOW 100.00 17.00 21.00 31.00 38.00 55.00 67.00 77.00 86.00 91.00

SURFACE AREA 0. 12. 16. 46.  
 CAPACITY 0. 47. 60. 339.

ELEVATION 767. 774. 760. 790.

CREL SPMID COLV EXPN ELEVEL COOL CAREA EMPL  
 779.0 .0 .0 .0 .0 .0 .0 .0 .0 .0

TOPEL COCB EXPD DAMVID  
 782.8 .0 .0 .0

CREST LENGTH 0. 60. 185. 315. 365. 437. 462. 905. 1037. 1145.  
 AT OR BELOW ELEVATION 782.2 782.8 782.9 783.1 783.2 783.4 784.0 784.7 785.3

STATION 2. PLAN 1. RATIO 1

END-OF-PERIOD HYDROGRAPH ORDINATES

0. 0. 0. 0. 0. 0. 0. 0. 0. 0.  
 0. 0. 0. 0. 0. 0. 0. 0. 0. 0.

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS  
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)  
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

| OPERATION     | STATION | AREA | PLAN RATIO 1 | RATIO 2 | RATIO 3 | RATIO 4 | RATIO 5 | RATIO 6 |
|---------------|---------|------|--------------|---------|---------|---------|---------|---------|
| HYDROGRAPH AT | 1       | .10  | .60          | .76     | .83     | .93     | .97     | 1.02    |
|               | (       | .25) | ( 19.7)      | ( 21.6) | ( 23.5) | ( 25.6) | ( 27.5) | ( 29.4) |
| ROUTED TO     | 2       | .10  | .65          | .86     | 1.03    | 1.33    | 1.80    | 2.05    |
|               | (       | .25) | ( 1.85)      | ( 2.38) | ( 2.93) | ( 3.82) | ( 5.10) | ( 22.8) |

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1 .....

ELEVATION INITIAL VALUE SPILLWAY CREST TOP OF DAM  
 STORAGE 779.00 779.00 762.00  
 OUTFLOW 47. 47. 109.  
 0. 0. 54.

| RATIO OF PMF | MAXIMUM DEPTH OVER DAM | MAXIMUM STORAGE AC-FT | MAXIMUM OUTFLOW CFS | DURATION OVER TOP HOURS | TIME OF MAX OUTFLOW HOURS | TIME OF FAILURE HOURS |
|--------------|------------------------|-----------------------|---------------------|-------------------------|---------------------------|-----------------------|
| .50          | 762.50                 | 136.                  | 65.                 | .00                     | 15.68                     | .00                   |
| .55          | 762.73                 | 108.                  | 64.                 | .00                     | 16.00                     | .00                   |
| .60          | 762.85                 | 110.                  | 103.                | 1.58                    | 17.35                     | .00                   |
| .65          | 762.92                 | 112.                  | 135.                | 2.50                    | 17.00                     | .00                   |
| .70          | 763.04                 | 114.                  | 180.                | 3.75                    | 16.00                     | .00                   |
| 1.00         | 763.59                 | 127.                  | 263.                | 5.33                    | 15.75                     | .00                   |



