

AD-A107 408

TIPPETTS-ABBETT-MCCARTHY-STRATTON NEW YORK
NATIONAL DAM SAFETY PROGRAM. KIRK LAKE DAM (INVENTORY NUMBER N.--ETC(U)
AUG 81 E O'BRIEN


F/G 13/13


DACW51-81-C-0008

NL

UNCLASSIFIED

1 of 8
AD
AT 760





MICROCOPY RESOLUTION TEST CHART
NBS 1963-A

AD A107408

3
LEVEL

LOWER HUDSON RIVER BASIN

KIRK LAKE DAM

PUTNAM COUNTY, NEW YORK
INVENTORY NO. N.Y. 682

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

THIS DOCUMENT IS BEST QUALITY PRACTICABLE.
IT IS THE USER'S RESPONSIBILITY TO DETERMINE
THE APPROPRIATE NUMBER OF PAGES WHICH DO NOT
CONTAIN THIS DOCUMENT.



APPROVED FOR PUBLIC RELEASE;
DISTRIBUTION UNLIMITED

DTIC
ELECTE
NOV 16 1981
S

NEW YORK DISTRICT CORPS OF ENGINEERS

SEPTEMBER 1981

DTIC FILE COPY

81

DISCLAIMER NOTICE

THIS DOCUMENT IS BEST QUALITY PRACTICABLE. THE COPY FURNISHED TO DTIC CONTAINED A SIGNIFICANT NUMBER OF PAGES WHICH DO NOT REPRODUCE LEGIBLY.

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
	AD-A107408	
4. TITLE (and Subtitle) Phase I Inspection Report Kirk Lake Dam Lower Hudson River Basin, Putnam County, NY Inventory No. 682		5. TYPE OF REPORT & PERIOD COVERED Phase I Inspection Report National Dam Safety Program
7. AUTHOR(s) EUGENE O'Brien		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS Tippett-Abbett-McCarthy-Stratton The TAMS Building 655 Third Avenue New York, New York 10017		8. CONTRACT OR GRANT NUMBER(s) 15 DACW51-81-C-0008
11. CONTROLLING OFFICE NAME AND ADDRESS Department of the Army 26 Federal Plaza New York District, CofE New York, New York 10287		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) Department of the Army 26 Federal Plaza New York District, CofE New York, NY 10287		12. REPORT DATE 13 August 81
		13. NUMBER OF PAGES
		15. SECURITY CLASS. (of this report) UNCLASSIFIED
15. DISTRIBUTION STATEMENT (of this Report) Approved for public release; Distribution unlimited.		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report) National Dam Safety Program, Kirk Lake Dam (Inventory Number N.Y. 682), Lower Hudson River Basin, Putnam County, New York. Phase I Inspection Report.		
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dam Safety National Dam Safety Program Visual Inspection Hydrology, Structural Stability Kirk Lake Dam Putnam County Lower Hudson River Basin		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report provides information and analysis on the physical condition of the dam as of the report date. Information and analysis are based on visual inspection of the dam by the performing organization. The examination of documents and the visual inspection of Kirk Lake Dam did not reveal conditions which constitute an immediate hazard to human life or property. However, the		

→ dam has some deficiencies which require further investigation and remedial action. ←

Using the Corps of Engineers screening criteria for the initial review of spillway adequacy, it has been determined that the dam would be overtopped for all storms exceeding approximately 6.1 percent of the Probable Maximum Flood (PMF). The spillway is therefore adjudged as "seriously inadequate" and the dam is assessed as unsafe, non-emergency.

The classification of "unsafe" applied to a dam because of a "seriously inadequate" spillway is not meant to connote the same degree of emergency as would be associated with an "unsafe" classification applied for a structural deficiency. It does mean, however, that based on an initial screening and preliminary computations, there appears to be a serious deficiency in spillway capacity so that if a severe storm were to occur, overtopping and failure of the dam would take place, significantly increasing the hazard for loss of life downstream from the dam.

The structural stability analysis based on available information and visual inspection indicates that the stability against sliding and overturning of the spillway section of the dam is inadequate.

The structural stability analysis based on available information and visual inspection indicates that the stability of the spillway section against sliding is inadequate for the following cases: Case II - normal loading with ice load, Case III - unusual loading 1/2 PMF and Case IV - extreme loading PMF. The stability of the spillway section against overturning is inadequate for Case II - normal loading with ice load, Case III - unusual loading, 1/2 PMF and Case IV - extreme loading, PMF.

DTIC
ELECTE
S NOV 16 1981 **D**
D

Accession For	
NTIS GRA&I	<input checked="" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By	
Distribution/	
Availability Codes	
Dist	Avail and/or Special
A	230

LOWER HUDSON RIVER BASIN

KIRK LAKE DAM

**PUTNAM COUNTY, NEW YORK
INVENTORY NO. N.Y. 682**

**PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM**



NEW YORK DISTRICT CORPS OF ENGINEERS

SEPTEMBER 1981

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
KIRK LAKE DAM
I.D. NO. N.Y. 682
D.E.C. NO. 481
LOWER HUDSON RIVER BASIN
PUTNAM COUNTY, N.Y.

CONTENTS

	<u>Page No.</u>
- ASSESSMENT	-
- OVERVIEW PHOTOGRAPH	-
1 PROJECT INFORMATION	1
1.1 GENERAL	1
a. Authority	1
b. Purpose of Inspection	1
1.2 DESCRIPTION OF THE PROJECT	1
a. Description of Dam and Appurtenant Structures	1
b. Location	2
c. Size Classification	2
d. Hazard Classification	2
e. Ownership	2
f. Purpose of Dam	2
g. Design and Construction History	2
h. Normal Operating Procedure	3
1.3 PERTINENT DATA	3
a. Drainage Area	3
b. Discharge at Dam Site	3
c. Elevation	3
d. Reservoir	3
e. Storage	3
f. Dam	4
g. Spillway	4
h. Reservoir Drain and Pipeline	4
2 ENGINEERING DATA	5
2.1 GEOLOGY	5

	<u>Page No.</u>
2.2 SUBSURFACE INVESTIGATIONS	5
2.3 DAM AND APPURTENANT STRUCTURES	5
2.4 CONSTRUCTION RECORDS	5
2.5 OPERATION RECORD	5
2.6 EVALUATION OF DATA	5
3 VISUAL INSPECTION	6
3.1 FINDINGS	6
a. General	6
b. Dam	6
c. Spillway	6
d. Outlets and Pipes	6
e. Abutments	7
f. Reservoir Area	7
3.2 EVALUATION OF OBSERVATIONS	7
4 OPERATION AND MAINTENANCE PROCEDURES	9
4.1 PROCEDURES	9
4.2 MAINTENANCE OF THE DAM	9
4.3 WARNING SYSTEM IN EFFECT	9
4.4 EVALUATION	9
5 HYDROLOGIC/HYDRAULIC	10
5.1 DRAINAGE AREA CHARACTERISTICS	10
5.2 ANALYSIS CRITERIA	10
5.3 SPILLWAY CAPACITY	10
5.4 RESERVOIR CAPACITY	11
5.5 FLOODS OF RECORD	11
5.6 OVERTOPPING POTENTIAL	11
5.7 EVALUATION	11

	<u>Page No.</u>	
6	STRUCTURAL STABILITY	12
6.1	EVALUATION OF STRUCTURAL STABILITY	12
	a. Visual Observation	12
	b. Design and Construction Data	12
	c. Stability Analysis	12
7	ASSESSMENT/RECOMMENDATIONS	14
7.1	ASSESSMENT	14
	a. Safety	14
	b. Adequacy of Information	15
	c. Need for Additional Investigations	15
	d. Urgency	15
7.2	RECOMMENDED MEASURES	15

APPENDICES

- A. DRAWINGS
 - a. Vicinity Map
 - b. Topographic Map
 - c. General Location Plan
 - d. Spillway Plan and Sections
- B. PHOTOGRAPHS
- C. VISUAL INSPECTION CHECKLISTS
- D. HYDROLOGIC DATA AND COMPUTATIONS
- E. STABILITY ANALYSIS
- F. REFERENCES
- G. OTHER DATA

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

NAME OF DAM	Kirk Lake Dam, N.Y. 682
STATE LOCATED	New York
COUNTY LOCATED	Putnam
STREAM	Tributary of Muscoot River
BASIN	Lower Hudson
DATE OF INSPECTION	May 6, 1981

ASSESSMENT

The examination of documents and the visual inspection of Kirk Lake Dam did not reveal conditions which constitute an immediate hazard to human life or property. However, the dam has some deficiencies which require further investigation and remedial action.

Using the Corps of Engineers screening criteria for the initial review of spillway adequacy, it has been determined that the dam would be overtopped for all storms exceeding approximately 6.1 percent of the Probable Maximum Flood (PMF). The spillway is therefore adjudged as "seriously inadequate" and the dam is assessed as unsafe, non-emergency.

The classification of "unsafe" applied to a dam because of a "seriously inadequate" spillway is not meant to connote the same degree of emergency as would be associated with an "unsafe" classification applied for a structural deficiency. It does mean, however, that based on an initial screening and preliminary computations, there appears to be a serious deficiency in spillway capacity so that if a severe storm were to occur, overtopping and failure of the dam would take place, significantly increasing the hazard for loss of life downstream from the dam.

The structural stability analysis based on available information and visual inspection indicates that the stability against sliding and overturning of the spillway section of the dam is inadequate.

The structural stability analysis based on available information and visual inspection indicates that the stability of the spillway section against sliding is inadequate for the following cases: Case II - normal loading with ice load, Case III - unusual loading 1/2 PMF and Case IV - extreme loading PMF. The stability of the spillway section against overturning is inadequate for Case II - normal loading with ice load, Case III - unusual loading, 1/2 PMF and Case IV - extreme loading, PMF.


It is therefore recommended that within 3 months of notification to the owner, a detailed hydrological and hydraulic investigation be undertaken to more accurately determine the site specific characteristics of the watershed and their affect upon the overtopping potential of the dam. At the same time, a structural stability study of the spillway section should be performed as detailed in Section 6.lc. Within twelve (12) months of the date of notification to the owner, any modification to the structure deemed necessary as a result of investigations, to achieve a spillway capacity adequate to discharge the outflow from at least one-half (1/2) PMF, should have been completed. In the interim, a detailed emergency action plan and warning system should be promptly developed. Also, during periods of unusually heavy precipitation, around-the-clock surveillance should be provided.

In addition, the dam has a number of problem areas which, if left uncorrected, have the potential for the development of hazardous conditions and must be corrected within twelve (12) months.

The following are the recommended measures which must be corrected:

- 1) All debris should be cleaned out from the downstream channel and hauled away. The collapsed section of the downstream channel should be cleared and repaired.

- 2) The small saddle near the right abutment contact should be filled in.
- 3) Stones missing in the masonry spillway section should be replaced.
- 4) All moving parts of the gate system should be lubricated.
- 5) Provide a program of periodic inspection and maintenance of the dam and appurtenances including yearly operation and lubrication of the reservoir drainage system. Document this information for future reference. The emergency action plan described in Section 7.1d should be developed and updated periodically during the life of the structure.



Eugene O'Brien, P.E.
New York No. 29823

Approved by:



Col. W. M. Smith Jr.
New York District Engineer

Date:

19 AUG 1981



1. OVERVIEW

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
KIRK LAKE DAM
I. D. NO. N.Y. 682
D.E.C. No. 481
LOWER HUDSON RIVER BASIN
PUTNAM COUNTY, N.Y.

SECTION 1 - PROJECT INFORMATION

1.1 GENERAL

a. Authority

The Phase I inspection reported herein was authorized by the Department of the Army, New York District, Corps of Engineers by Contract No. DACW 651-81-C-008 dated 14 December 1980 in fulfillment of the requirements of the National Dam Inspection Act, Public Law 92-367, 8 August 1972.

b. Purpose of Inspection

The inspection was conducted to evaluate the existing conditions of the dam, to identify deficiencies and hazardous conditions, to determine if these deficiencies constitute hazards to life and property, and to recommend remedial measures where required.

1.2 DESCRIPTION OF THE PROJECT

a. Description of the Dam and Appurtenant Structures

The Kirk Lake Dam is composed of an approximately 220 foot long stone masonry-earth buttress dam. The crest of the dam is 60 feet wide and its maximum height above the river is 28 feet. The downstream masonry wall face of the dam is vertical. Upstream of the 11 foot thick wall is a 50 foot wide earth embankment with a slight upstream slope. Upstream of the earth embankment is another smaller concrete masonry wall. The slope of the fill upstream of this wall is unknown.

Centrally located within the dam is a 15.5 foot wide stone masonry spillway section which has a 6 feet by 4 feet chamber.

The spillway has sills at three levels and the maximum and minimum depths of the sills are 5.3 feet and 2.3 feet respectively from the top of the dam. At the bottom of the chamber is the control for the reservoir drain. The reservoir drain is a 36-inch cast iron pipe, controlled by a gate valve. The intake is located in the lake approximately 200 feet upstream of the dam. The outlet is in the base of the spillway structure.

The spillway and reservoir drains discharge through a stone masonry lined channel about 15 feet deep.

b. Location

Kirk Lake Dam is located on a tributary of the Muscoot River about 1/2 mile northeast of the village of Mahopac Falls in Putnam County, New York. The dam is about 1/3 mile north of Route 6N near its intersection with Hill Street.

c. Size Classification

The dam is 28 feet high and has a reservoir with a maximum storage capacity of 1,822 acre-feet and therefore is classified as an intermediate dam (storage capacity > 1,000 acre-feet, < 50,000 acre-feet).

d. Hazard Classification

The dam is in the "high" hazard potential category because of its close proximity to the village of Mahopac Falls.

e. Ownership

Kirk Lake Dam is owned by the New York City Bureau of Water Supply. The person to contact is Mr. Don Grassman at the Department of Environmental Protection, P.O. Box 66, Valhalla, New York, 10595, Telephone (914) 232-5711.

f. Purpose of Dam

The dam impounds water for a recreational lake.

g. Design and Construction History

The dam was designed and built in 1871 and major reconstruction was done in 1881. The designers and constructors are not known.

h. Normal Operating Procedures

Operations are carried out on an as-needed basis, with the water level maintained at between 1 and 3 feet below the lowest spillway sill. The 36 inch cast iron pipe serves as reservoir drain. The intake of the drain is about 200 ft from the upstream face.

1.3 PERINENT DATA

a.	<u>Drainage Area</u> , Square Miles	2.95
b.	<u>Discharge at Dam Site</u> , cfs	
	Ungated Spillway	279
	Maximum Capacity - 36-Inch Cast Iron Pipe	160
	Total Discharge Maximum Pool	439
c.	<u>Elevation</u> , Feet Above MSL, USGS Datum	
	Top of Dam	592.3
	Maximum Pool	592.3
	Spillway Crest - Lowest Sill	587.0
	Spillway Crest - Mid Sill	589.0
	Spillway Crest - High Sill	590.3
	Invert Low Level Intake	Unknown
	Invert Low Level Outlet	568.3
d.	<u>Reservoir</u>	
	Length of Normal Pool (miles)	0.8
	Surface Area of Maximum Pool (Acres)	216
	Surface Area of Normal Pool (Acres)	124
e.	<u>Storage</u> , Acre-feet	
	Reservoir at Spillway Crest	920
	Reservoir at Maximum Pool	1822

f. <u>Dam</u>	
Type	Masonry Wall with Upstream Earth Embankment
Length (feet)	220
Upstream Slope	Unknown
Downstream Slope	Vertical
Crest Elevation	592.3
Crest Width	61 feet
Grout Curtain	Unknown
Cutoff	Unknown

g. <u>Spillway</u>	
Type	Uncontrolled Broad Crested Weir
Size	15 feet wide
Crest Elevations - Low Sill	587
Mid Sill	589
High Sill	590.3
Upstream Channel	Concrete Slab with Masonry Concrete Training Walls
Downstream Channel	Masonry Walled Channel - 15 feet wide base approx- imately 4V to 1H sloped walls

h. Reservoir Drain and Pipeline

Upstream. The intake for the 36-inch cast iron reservoir drain line is located about 200 feet upstream of the dam. A gate valve, located in a chamber below the spillway, controls discharges. The outlet is located in the base of the spillway section of the dam.

SECTION 2 - ENGINEERING DATA

2.1 GEOLOGY

The records of the owner contain no data on site geology. However, there is data available in the literature on the general geology of the area. Kirk Lake Dam is located in the Hudson Highlands section of the New England Uplands physiographic province. The province is characterized by a low, but rugged mountain range consisting primarily of igneous and metamorphic rock. The rock underlying the area of Kirk Lake is Precambrian biotite-quartz-plagioclase paragneiss with subordinate biotite granitic gneiss, amphibolite and calcilicate rock.

2.2 SUBSURFACE INVESTIGATIONS

There are no records of subsurface investigations carried out at the site. It is known that the surficial soils in the vicinity of the Kirk Lake Dam are coarse grained glacial till material.

2.3 DAM AND APPURTENANT STRUCTURES

There are no records or drawings available with regard to the original construction of the dam in 1872. No records are available of the reconstruction carried out in 1881. There is some information regarding the dam section shown in the inspection reports of 1915 which are included in Appendix

2.4 CONSTRUCTION RECORDS

No information has been located in relation to the construction of the project. The name(s) of the contractor(s) is (are) unknown.

2.5 OPERATION RECORDS

There is no regularly scheduled operation of the dam. The outlets are operated on an as-needed basis to maintain a water level between 1 and 3 feet below the lowest sill of the spillway. Maintenance is performed on an as-needed basis by staff of the owner. No systematic monitoring of the dam is in effect.

2.6 EVALUATION OF DATA

There is sufficient data available to support a Phase I evaluation of the dam.

SECTION 3 - VISUAL INSPECTION

3.1 FINDINGS

a. General

The visual inspection of Kirk Lake Dam was made on May 6, 1981. The weather was clear and the temperature was in the mid 60's. At the time of the inspection, the water level in the reservoir was about 1 foot below lowest sill of the spillway.

b. Dam

The stone masonry and earth buttress portions of the dam appears to be in good condition. The vertical and horizontal alignment of the crest appears to be good (see Photos 2 and 3).

The visible portion of the upstream face of the dam is in good condition with some minor ice damage to the upstream wall.

The downstream face of the masonry wall is in good condition except minor vegetation growing through.

There is no emergency action plan for the project.

c. Spillway

The masonry spillway is in good condition. There are a few stones missing in the central portion of the spillway. The approach channel of the spillway is clear and training walls are in good condition except for some local ice damage. The tailrace channel of the spillway is choked with heavy debris and a section of channel wall about 300 feet downstream of the dam (see Photos 5 and 10) is collapsed.

d. Outlets and Pipes

The condition of the reservoir drain and in and intake could not be determined because it was unobservable. The control for the gate valve is in good operating condition but requires lubrication. The 36-inch reservoir drain pipeline was unobservable. The outlet of the pipe appears to be in good condition. The discharge was free of sediment or rust staining (see Photo 7) and therefore the condition of the reservoir drain could not be determined.

e. Abutments

The abutment contact and abutment at the left end of the dam are in good condition. The right abutment is in good condition, however, a small "ditch" passes over the contact. The ditch is slightly lower than crest and at the time contained some standing water (see Photo 11).

f. Reservoir Area

The reservoir area is hilly and for the most part, developed with small homes. There is some forested area surrounding the reservoir and the area to the north is marshy land. There are neither slides, rockfalls or sloughing around the reservoir.

3.2 EVALUATION OF OBSERVATIONS

Visual observations made during the course of the inspection did not indicate any serious problems which would adversely affect the adequacy of the dam and appurtenant facilities. The following is a list in order of importance of problem areas encountered which should be corrected before further deterioration results in the development of a hazardous condition. Appropriate remedies are also included.

- 1) The downstream channel for the spillway and reservoir drain is filled with debris, and a section of the channel wall has collapsed resulting in the clogging of the channel. The debris should be removed and hauled away and the collapsed section of the channel should be repaired.
- 2) The small drainage ditch which is near the right abutment contact is subject to flow conditions during high water. This ditch should be filled in with properly compacted earth to an elevation equal to the crest elevation of the dam.
- 3) Stones have been pried loose in the spillway. These stones should be replaced. Additionally, concrete damaged by ice in the approach channel should be repaired.
- 4) All moving parts of the outlet system should be lubricated.
- 5) A program of periodic inspection and maintenance of the dam and appurtenances, should be provided including yearly

lubrication of the moving parts of the outlet system. The inspection and the test operations should be documented for future reference. The emergency action plan described in Section 7.1d should be maintained and updated during the life of the project.

SECTION 4 - OPERATION AND MAINTENANCE PROCEDURES

4.1 PROCEDURES

No written operation and maintenance procedure manuals exist for the project. Normal operation of the project consists of maintaining a reservoir level about 1 to 3 feet below lowest sill of the spillway by releasing the discharge through the reservoir drain.

4.2 MAINTENANCE OF THE DAM

There is no regular maintenance schedule for the dam. Maintenance and repairs which are required are carried out by the staff of the owner under the direction of Mr. Birrel, Assistant Civil Engineer for the Bureau of Water Supply.

4.3 WARNING SYSTEM IN EFFECT

No warning system is in effect or in preparation.

4.4 EVALUATION

The overall maintenance of the Kirk Lake Dam is considered inadequate in the following areas.

- 1) The downstream channel for the spillway and outlet needs to be cleaned out.
- 2) Moving parts of the outlet works require lubrication.
- 3) Vegetation, although minor, at the downstream face of the dam, should be removed.

SECTION 5 - HYDROLOGIC/HYDRAULIC

5.1 DRAINAGE AREA CHARACTERISTICS

The Kirk Lake Dam is located on an unnamed tributary of the Muscoot River about 1/2 mile north of Mahopac Falls, Carmel Township, Putnam County. The Hydrologic Unit Code number for this area is 02030101. The drainage basin extends north of the lake with an area of 2.95 square miles. The basin consists of a north/south valley with approximately 15 percent swamp area in the middle and steep slopes at the edges. About 30 percent of the basin is suburban with the remaining 70 percent being wooded slopes.

5.2 ANALYSIS CRITERIA

The analysis of the adequacy of the spillway was performed by developing a design flood, using the unit hydrograph method and the Probable Maximum Precipitation (PMP). The all season 200 square mile 24 hours PMP for the Carmel area is 22 inches (Weather Bureau sources). The unit hydrograph was computed by the Snyder method using coefficient of 2 and 0.625 for C_t and C_p , respectively. The inflow hydrograph was developed by the U.S. Army Corps of Engineers HEC-1DB computer program. Initial loss of 1.0 inch and constant loss of 0.1 inch/hour were estimated as representative of the basin for the design storm.

In accordance with the Recommended Guidelines for Safety Inspection of Dams (Ref. 3), the adequacy of the spillway was analyzed using the Probable Maximum Flood (PMF). A multi-ratio analysis was performed for the full, 0.75, 0.50 and 0.25 PMF.

5.3 SPILLWAY CAPACITY

The spillway, which is centrally located in the dam, is a 15.5 feet wide stone masonry structure. The spillway has broad crested overflow sills at several different heights. The maximum and minimum depths of the sills are 5.3 feet and 2.3 feet from the top of the dam respectively. The computed maximum discharge over the sills with the water surface at El 592.3 (top of dam) is 309.7 cfs.

5.4 RESERVOIR CAPACITY

The normal reservoir capacity is listed as 920 acre-feet. The computed surcharge storage of 901.7 acre-feet, while water level reaches the top of the dam (592.3 feet MSL), is equivalent to approximately 5.7 inches of runoff over the entire basin.

5.5 FLOODS OF RECORD

There are no records available of floods or maximum lake elevation.

5.6 OVERTOPPING POTENTIAL

The potential of the dam being overtopped was investigated on the basis of the spillway discharge capacity and the available surcharge storage to meet the selected design flood inflows.

The analysis was performed assuming that the reservoir level was at the lowest sill of the spillway at the start of the flood event.

<u>Ratio of PMF</u>	<u>Inflow Peak (cfs)</u>	<u>Overtopping (ft)</u>	<u>Outflow Peak (cfs)</u>
1.00	8006	3.56	5070
0.75	6004	2.65	3401
0.50	4003	1.37	1496
0.25	2001	0.00	217

The analysis indicates that the spillway is capable of passing 6.1 percent of the PMF without overtopping the dam.

5.7 EVALUATION

The spillway at Kirk Lake Dam does not have sufficient spillway capacity to pass either the PMF or one-half (1/2) PMF without overtopping the dam. The overtopping of the dam could cause the failure of the dam, thus significantly increasing the hazard for the loss of life downstream. The spillway is therefore assessed as being "seriously inadequate" and the dam is assessed as unsafe, non-emergency.

SECTION 6 - STRUCTURAL STABILITY

6.1 EVALUATION OF STRUCTURAL STABILITY

a. Visual Observations

Visual observations did not indicate any structural problems with the embankment or appurtenant structures with the reservoir at its present level. There are no observable adverse conditions which would affect the stability of the dam at the present time.

b. Design and Construction Data

There are no design calculations or construction data available.

On the basis of performance, visual inspection, as well as engineering judgment, the embankment and appurtenant structures appear to be adequate with the reservoir at its present level.

c. Stability Analysis

As there were no drawings available, the structural stability of the masonry spillway section was analyzed based on an assumed typical section and field measurements. Stability analysis for the spillway section was done in accordance with the Corps of Engineers Recommended Guidelines. (Reference 3). The following table shows the loading cases considered and the results of the analysis.

<u>Loading Case</u>	<u>Overturning (see Appendix E)</u>	<u>Sliding factor of Safety (see Appendix E)</u>
I) Normal Loading Condition with res- ervoir at Spillway Crest, No Ice Load	Inside of Middle 1/3	3.41
II) Normal Loading Condition with Res- ervoir at Spillway Crest, with Ice Load	0.63 ft. Outside of Middle 1/3	2.20

<u>Loading Case</u>	<u>Overturning (see Appendix E)</u>	<u>Sliding Factor of Safety (see Appendix E)</u>
III) Unusual Loading, One-Half (1/2) PMF, water overtopping the dam by 1.18 feet	0.75 ft. Outside of Middle 1/3	1.68
IV) Extreme Loading: PMF-water overtopping the dam by 3.29 feet	1.75 ft. Outside of Middle 1/3	1.40
V) Unusual Loading; Reservoir level of spillway crest, 0.05 g earthquake force	Inside of Base	2.52

The structural stability analysis based on available information and visual inspection indicates that the stability of the spillway section against sliding is inadequate for the following cases: Case II - normal loading with ice load, Case III - unusual loading 1/2 PMF and Case IV - extreme loading PMF. The stability of the spillway section against overturning is inadequate for Case II - normal loading with ice load Case III - unusual loading, 1/2 PMF and Case IV - extreme loading PMF.

Since exact geometry of the spillway section, foundation conditions, upstream backfill characteristics and extent, as well as the extent and magnitude of the uplift pressure are unknown, it is recommended that a more detailed structural stability study be performed. The study should include field investigations to obtain more information regarding the extent and characteristics of the backfill and foundation materials, as well as the quality and condition of the observable masonry of the structure. Based on the results of the analysis, modifications to the spillway should be recommended.

SECTION 7 - ASSESSMENT/RECOMMENDATIONS

7.1 ASSESSMENT

a. Safety

Examination of the available documents and visual inspections of the Kirk Lake Dam and appurtenant structures did not reveal conditions which constitute an immediate hazard to human life or property. However, the dam has some deficiencies which require further investigation and remedial action.

Using the Corps of Engineers screening criteria for review of spillway adequacy, it has been determined that the dam would be overtopped for all storms exceeding approximately 35 percent of the PMF. The overtopping of the dam could cause the erosion of both abutments, resulting in dam failure, thus significantly increasing the hazard for loss of life downstream. The spillway is therefore adjudged as "seriously inadequate" and the dam is assessed as unsafe, non-emergency.

The classification of "unsafe" applied to a dam because of a "seriously inadequate" spillway is not meant to connote the same degree of emergency as would be associated with an "unsafe" classification applied for a structural deficiency. It does mean, however, that based on an initial screening and preliminary computations, there appears to be a serious deficiency in spillway capacity so that if a severe storm were to occur, overtopping and failure of the dam would take place, significantly increasing the hazard to loss of life downstream from the dam.

The structural stability analysis based on available information and visual inspection indicates that the stability of the spillway section against sliding is inadequate for the following cases: Case II - normal loading with ice load, Case III - unusual loading 1/2 PMF and Case IV - extreme loading PMF. The stability of the spillway section against overturning is inadequate for Case II - normal loading with ice load, Case III - unusual loading, 1/2 PMF and Case IV - extreme loading PMF.

b. Adequacy of Information

The information and data available were adequate for the performance of a Phase I inspection, except as noted in Sections 6.1c and 6.1d.

c. Need for Additional Investigations

Since the spillway is considered to be "seriously inadequate", additional hydrologic/hydraulic investigations are required to more accurately determine the site specific characteristics of the watershed. After the in-depth hydrologic/hydraulic investigations have been completed, remedial measures must be initiated to provide spillway capacity sufficient to discharge the outlet from the one-half (1/2) PMF event. In addition, an investigation of the structural stability of the spillway portion of the dam is required.

d. Urgency

The additional hydrologic/hydraulic investigations and the stability investigation which are required must be initiated within 3 months from the date of notification. Within 18 months of notification, remedial measures determined as a result of these investigations must be initiated, with completion of these measures during the following year. In the interim, develop an emergency action plan for the notification of downstream residents and proper government authorities in the event of overtopping and provide around-the-clock surveillance of the dam during periods of extreme runoff. The other problem areas listed below must be corrected within one year from notification.

7.2 RECOMMENDED MEASURES

The following are the recommended measures.


- 1) The results of the aforementioned investigation will determine the appropriate remedial measures required regarding spillway.
- 2) All debris should be cleaned out of the downstream channel and hauled away. The collapsed section of the downstream channel should be cleared out and repaired.

- 3) The small saddle near the right abutment contact should be filled in with properly compacted earth.
- 4) Stones missing in the spillway section should be replaced.
- 5) A program of periodic inspection and maintenance of the dam and appurtenances should be provided including yearly operation and lubrication of the repaired gates. The emergency action plan described in Section 7.1b should be maintained and updated periodically during the life of the structure. The inspection and the test operation should be documented for future reference.

DRAWINGS



- a. Vicinity Map
- b. Topographic Map
- c. General Location Plan (DRAW # 1)
- d. Spillway Plan and Sections (DRAW # 2)

APPENDIX A



Scale: 1"=2.2 Miles

KIRK LAKE DAM
VICINITY MAP




SCALE 1:24000

LAKE CARMEL, N.Y. AND OSCAWANA LAKE, N.Y.

QUAD TOPOGRAPHIC MAP

KIRK LAKE DAM




PLAN - KIRK LAKE DAM


SCALE: 1" = 50'

NOTES:


- i) For Details of Spillway See Drawing No. 2
- ii) All dimensions from field measurements.



PLAN
SCALE: 1" = 5'



SECTION A-A
SCALE 1" = 5'



SECTION B-B
SCALE: 1" = 5'

SPILLWAY - PLAN & SECTIONS
KIRK LAKE DAM

DWG #2


2

PHOTOGRAPHS

APPENDIX B



2. VIEW ALONG CREST OF DAM FROM THE
RIGHT ABUTMENT.




3. VIEW ALONG CREST OF DAM FROM
LEFT ABUTMENT.




4. VIEW OF SPILLWAY APPROACH CHANNEL




5. VIEW OF TALLRACE CHANNEL



6. CONTROL FOR
LOW LEVEL
OUTLET




7. CLOSEUP OF LOW LEVEL OUTLET



8. UPSTREAM VIEW OF SPILLWAY



9. DOWNSTREAM VIEW OF SPILLWAY



10. VIEW OF COLLAPSED PORTION OF TAILRACE CHANNEL.



11. VIEW OF LOW SADDLE NEAR RIGHT ABUTMENT CONTACT.

VISUAL INSPECTION CHECKLISTS

APPENDIX C

VISUAL INSPECTION CHECKLIST

1) Basic Data

a. General

Name of Dam Kirk Lake Dam
Fed. I.D. # NY 682 DEC Dam No. 481
River Basin Lower Hudson
Location: Town Carmel County Putnam
Stream Name Muscoot River
Tributary of Muscoot River
Latitude (N) 41-22.7 Longitude (W) 73-45.5
Type of Dam Masonry with earth fill upstream
Hazard Category High
Date(s) of Inspection May 6 1981
Weather Conditions Fair 65° F
Reservoir Level at Time of Inspection 1.5 below spillway crest

b. Inspection Personnel K Szalay, J Fiteni JR.

c. Persons Contacted (Including Address & Phone No.) Mr. C. Picha, (914) 232-5171
NYC Dept. of Env. Protection, PO Box 66 Valhalla, N.Y. 10595
MR. Birrell - (914) 225-3550.

d. History:

Date Constructed 1871 Date(s) Reconstructed 1881

Designer Unknown

Constructed By Unknown

Owner NYC Dept. of Env. Conservation

(4) Slope Protection Concrete Wall - good.
condition

(5) Surface Cracks or Movement at Toe None

d. Downstream Slope

(1) Slope (Estimate - V:H) Vertical Masonry Wall

(2) Undesirable Growth or Debris, Animal Burrows None

(3) Sloughing, Subsidence or Depressions None

(4) Surface Cracks or Movement at Toe None

(5) Seepage None

(6) External Drainage System (Ditches, Trenches; Blanket) None

(7) Condition Around Outlet Structure Structure in good con-
dition, channel debris clogged

(8) Seepage Beyond Toe None

e. Abutments - Embankment Contact

Left abutment - good

Right abutment - small depression below crest level.

(1) Erosion at Contact None

(2) Seepage Along Contact Evidence of possible past seepage in right abutment contact at higher reservoir levels

3) Drainage System

a. Description of System one 36 inch ϕ cast iron low level outlet pipe. Controlled from well in middle of spillway by slide gate. Intake located about 400' out in lake. Control by multigear wheel

b. Condition of System good operating condition

c. Discharge from Drainage System regulated by Mr. Birrel - Discharging at time of visit. Usual condition is to discharge controlled amounts.

4) Instrumentation (Monumentation/Surveys, Observation Wells, Weirs, Piezometers, Etc.)

None

5) Reservoir

- a. Slopes Hilly - some development - Generally
Glacial Till material - Stable
- b. Sedimentation Some minor amounts
- c. Unusual Conditions Which Affect Dam None

6) Area Downstream of Dam

- a. Downstream Hazard (No. of Homes, Highways, etc.) Few homes (10)
downstream, Highway 6N about 1/4 mile d/s
- b. Seepage, Unusual Growth None obvious
- c. Evidence of Movement Beyond Toe of Dam None
- d. Condition of Downstream Channel Downstream channel is paved
Much debris, one collapsed section

7) Spillway(s) (Including Discharge Conveyance Channel)

- Multi-levelled structure approximately in
center of dam, Masonry walls and bottom
- a. General good condition, few stones missing
due to recent vandalism, approach channel
clear, some ice damage to training walls.
Downstream channel good but clogged by debris.
- b. Condition of Service Spillway good condition
few stones missing

c. Condition of Auxiliary Spillway None

d. Condition of Discharge Conveyance Channel Channel is clogged by debris, natural as well as dumped. Stone paved channel has collapsed at one section about 400' D/S of dam.

3) Reservoir Drain/Outlet

Type: Pipe Conduit _____ Other _____

Material: Concrete _____ Metal Other _____

Size: 36" Length ≈ 400'

Invert Elevations: Entrance unknown Exit 560

Physical Condition (Describe): UNKNOWN Unobservable

Material: _____

Joints: _____ Alignment _____

Structural Integrity: _____

Hydraulic Capability: _____

Means of Control: Gate Valve _____ Uncontrolled _____

Operation: Operable Inoperable _____ Other _____

Present Condition (Describe): good - needs lubrication

9) Structural

a. Concrete Surfaces — Masonry Surfaces are
in generally good condition. Few missing
blocks

b. Structural Cracking None visible

c. Movement - Horizontal & Vertical Alignment (Settlement) None
Visible or evident

d. Junctions with Abutments or Embankments Good condition

e. Drains - Foundation, Joint, Face None

f. Water Passages, Conduits, Sluices None

g. Seepage or Leakage None visible

h. Joints - Construction, etc. Masonry joints in good condition, repaired as required

i. Foundation No evidence of or visible problems

j. Abutments good condition

k. Control Gates good operating condition (see items)

l. Approach & Outlet Channels Approach channel wall - some concrete deterioration - otherwise ok. Outlet channel - good condition except one section collapsed \approx 300 ft downstream, debris throughout

m. Energy Dissipators (Plunge Pool, etc.) None

n. Intake Structures Not visible

o. Stability Visually ok - to be calculated

p. Miscellaneous _____

HYDROLOGIC DATA AND COMPUTATIONS

APPENDIX D

CREST:

ELEVATION: 592

Type: Masonry walls

Width: 11 Feet Length: 205

Spillover Masonry Structure - 15.5 Feet wide - Stepped

Location Near Center of DAM

SPILLWAY:

SERVICE

AUXILIARY

Varies 587 → 590 Elevation _____

Masonry - Broad Crested Type _____

15.5 feet Width _____

Type of Control

Uncontrolled _____

Controlled:

Type _____
(Flashboards; gate)

Number _____

Size/Length _____

Invert Material _____

Anticipated Length
of operating service _____

≈ 100 feet Chute Length _____

Slopes 4/3 ≈ 3 feet Height Between Spillway Crest
beyond that un- & Approach Channel Invert
observable (Weir Flow)

HYDROMETEOROLOGICAL GAGES:

Type : None Used

Location: _____

Records:

Date - _____

Max. Reading - _____

FLOOD WATER CONTROL SYSTEM:

Warning System: None

Method of Controlled Releases (mechanisms):

DRAINAGE AREA: 2.95 sq. miles

DRAINAGE BASIN RUNOFF CHARACTERISTICS:

Land Use - Type: Rural

Terrain - Relief: Hilly

Surface - Soil: Glacial Till

Runoff Potential (existing or planned extensive alterations to existing surface or subsurface conditions)

Potential Sedimentation problem areas (natural or man-made; present or future)

None

Potential Backwater problem areas for levels at maximum storage capacity including surcharge storage:

None

Dikes - Floodwalls (overflow & non-overflow) - Low reaches along the Reservoir perimeter:

Location: None
Elevation: _____

Reservoir:

Length @ Maximum Pool 0.8 (Miles)

Length of Shoreline (@ Spillway Crest) 3.1 (Miles)

TAMS

Job No. 1579-13

Sheet 1 of

Project KIRK LAKE DAM

Date JAN 21, 1981

Subject

By D.L.C.

Ch'k. by

LAKE EL.

587' MSL

LAKE PERIMETER

8.25" / 14,500' / 3.13 mi.

FETCH

4000'

LAKE AREA

4236 1.31
4105

1.35

123.47 ac

1057 1.39
0918

Drainage Area

5800 20.69
3731

20.59

1890.73 / 2.95 mi²

4105 20.49
2056

600 FT CONTOUR

.6582

3.79

.6203

3.815.

350.32 ac

3.82

.5821

620 FT CONTOUR

TAMS

Job No. 1579-13

Sheet 2 of _____

Project KIRK LAKE DAM

Date 1/81

Subject 600 CONTOUR LINE AREA

By A. PERDOMO

Ch'k. by _____

PLAN. RDNG

	<u>Sq. INC.</u>	<u>ACRES</u>	<u>Sq. MILES</u>
4235	>	3.70	
3865	>		
4606	>	3.71	340.6
4235	>		0.532

TAMS

Job No. 1579-04
 Project KIRK LAKE
 Subject HYDROLOGIC / HYDRAULIC COMPUTATION

Sheet 3 of _____
 Date 7-20-91
 By D.L.C.
 Ch'k. by _____

EL	H	H ₁	L ₁	Q ₁	H ₂	L ₂	Q ₂	H ₃	L ₃	Q ₃	Q _{TOTAL}
587	0										0
588	1		6.8	18.0							18.0
589	2		"	50.8	0						50.8
590	3		"	93.3	1	1.6	4.2	0		0	97.5
591	4		"	143.6	2	"	11.9	1	7.1	18.7	174.2
592.3	5.3		"	219.0	3.3	"	25.3	2.3	"	65.4	309.7
594	7		"	332.5	5.	"	47.2	4	"	150.0	529.7
597	10.		"	567.7	8	"	95.6	7	"	347.1	1010.4

USE C = 2.64

LOW LEVEL OUTLET IS ASSUMED CLOSED FOR PMF ANALYSIS

EL	ΔH	AREA	MEAN AREA	ΔVOL	SURCHARGE STORAGE
Fr	(Ft)	(Ac)	(Ac)	(Ac Ft)	(Ac Ft)
587		124			0
	3		150.1	450.3	
590		176.2			450.3
	2.3		196.25	451.4	
592.3		216.3			901.7
	2.7		239.8	647.5	
595		263.3			1549.2
	5.0		306.8	1534.0	
600		350.3			3083.2

TAMS

Job No. 1579
 Project KIRK LAKE DAM INSPECTION
 Subject HYDROLOGIC/HYDRAULIC COMPUTATIONS

Sheet 4 of
 Date May 18 1981
 By D. L. C
 Ch'k. by

FROM HYDROMET # 33

ALL SEASON 200 SQ MILE 24 hour PMP = 22 inches

DURATION IN HOURS	Percent of INDEX RAINFALL
----------------------	------------------------------

6	112
---	-----

12	123
----	-----

24	133
----	-----

48	141
----	-----

Assume INITIAL LOSS \approx 1.0 inches

$\frac{1}{4}$ CONSTANT LOSS \approx 0.1 inch/hour

% Impervious area 0.1

Assume SNYDER COEFS $C_p \approx 0.625$ or $640 C_p = 400$

$\frac{1}{4}$ $C_T \approx 2.0$

$L = 3.75'' = 7500' \approx 1.4$ mi

$L_{CN} = 0.9'' = 1800' \approx 0.34$ mi

$t_p = C_T (L L_{CN})^{0.3} = 2 (1.4 \times 0.34)^{0.3} = 1.6$ hours

$t_n = t_p / 5.5 = 1.6 / 5.5 = 0.29$ hrs use $t_R = 0.5$ hrs

$t_{PR} = t_p + 0.25(t_R - t_n) = 1.6 + 0.25(0.5 - 0.29)$

$= 1.6 + 0.05 = 1.65$ hours

TAMS

Job No. 1579-13
Project KIRK LAKE
Subject HYDROLOGIC/HYDRAULIC COMPUTATIONS

Sheet 5 of _____
Date 5/20/81
By D.K. BORAH
Ch'k. by _____

Basin area = 2.95 sq. miles
Water Surface area:
Lake = 0.194 sq. miles
Swamps etc. = 0.155
Total = 0.299 sq. miles


Ratio of water surface area to total basin area = 0.101
≈ 0.1

D/S channel characteristics

Length = 1000 ft.

Slope = 1:1000 = 0.012

cross section



.....
 FLOOD HYDROGRAPH PACKAGE (HEC-1)
 DAM SAFETY VERSION JULY 1978
 LAST MODIFICATION 01 APR 80

KIRK LAKE DAM										
PHASE 1 INSPECTION										
	A1	A2	A3	B	C	D	E	F	G	H
	HEC-10B	HEC-10B	HEC-10B	HEC-10B	HEC-10B	HEC-10B	HEC-10B	HEC-10B	HEC-10B	HEC-10B
	Q	Q	Q	Q	Q	Q	Q	Q	Q	Q
1										
2										
3										
4										
5										
6										
7										
8										
9										
10										
11										
12										
13										
14										
15										
16										
17										
18										
19										
20										
21										
22										
23										
24										
25										
26										
27										
28										
29										
30										
31										
32										

Chart 6 of 21

PREVIEW OF SEQUENCE OF STREAM NETWORK CALCULATIONS

RUNOFF HYDROGRAPH AT 1
 ROUTE HYDROGRAPH TO 2
 ROUTE HYDROGRAPH TO 3
 END OF NETWORK

11/16/80

PREVIEW OF SEQUENCE OF STREAM NETWORK CALCULATIONS

- 1 RUNOFF HYDROGRAPH AT
- 2 ROUTE HYDROGRAPH TO
- 3 ROUTE HYDROGRAPH TO
- END OF NETWORK

Sheet 7 of 21

FLOOD HYDROGRAPH PACKAGE (HEC-1)
DAP SAFETY VERSION JULY 1978
LAST MODIFICATION 01 APR 80

RUN DATE 81/07/21
TIME 12.35.33

 FLOOD HYDROGRAPH PACKAGE (HEC-1)
 DAM SAFETY VERSION JULY 1978
 LAST MODIFICATION 01 APR 80

RUN DATE 81/07/21
 TIME 12.35.53

KIRK LAKE DAM
 PHASE 1 INSPECTION
 HEC-1DB PMF ANALYSIS MAY 81

JOB SPECIFICATION
 HQ NHR 0 3C 0 0 0 0 0 0 0 0
 TCO 0 0 0 0 0 0 0 0 0 0
 JOPER 5 0 0 0 0 0 0 0 0 0
 MHT LROPT TRACE 0 0 0 0 0 0 0 0 0 0

MULTI-PLAN ANALYSES TO BE PERFORMED
 NPLAN= 1 NRTIO= 4 LRTIO= 1
 RTIOS= 1.00 .75 .50 .25

 SUB-AREA RUNOFF COMPUTATION

1 BASIN INFLOW HYDROGRAPH

ISTAQ 1 ICOMP 0 ITCN 0 ITAPE 0 JPLY 0 JPRT 0 INAME 1 ISTAGE 0 IAUTO 0

HYDROGRAPH DATA
 INYDG 1 IUNG 1 TAREA 2.95 SHAP 0.00 TRSDA 2.95 TRSPC 0.00 RATIO ISNOW ISAPE LOCAL
 1 1 2.95 0.00 0.00 0.000 0 1 0

PRECIP DATA
 SPE PHS RL R12 R24 R48 R72 R96
 0.00 22.00 112.00 123.00 133.00 141.00 0.00 0.00

TRSPC COMPUTED BY THE PROGRAM IS .800

LOSS DATA
 LROPT 0 STRKR 0 LTRK 0.00 RTIOL 1.00 ERAIN 0.00 STRKS 0.00 RTIOK 1.00 STRTL 1.00 CHSTL 0.10 ALSXK 0.00 RTIMD 0.10

UNIT HYDROGRAPH DATA
 TP= 1.65 CP= .63 NYA= 0

APPROXIMATE CLARY COEFFICIENTS FROM GIVEN SNYDER CP AND TP ARE TC= 3.93 AND P= 2.98 INTERVALS
 STGT2= -1.00 GRESN= -10 RTIOR= 1.50
 RECESION DATA

UNIT HYDROGRAPH 12 END-OF-PERIOD ORIGINATES, LAG= 1.66 HOURS, CP= .63 VOL= 1.00
 99. 351. 700. 588. 419. 299. 213. 152. 108.
 77. 55. 39. 28. 20. 14. 10. 7.

Sheet E of 21

MO-DA	MR-MN	PERIOD	RAIN	EXCS	LOSS	END-OF-PERIOD FLOW	MO-DA	MR-MN	PERIOD	RAIN	EXCS	LOSS	COMP 0
1.01	1.30	1	.00	.00	.00	3.	1.02	1.30	51	.06	.01	.05	17.
1.01	1.00	2	.00	.00	.00	3.	1.02	2.00	52	.06	.01	.05	26.
1.01	1.30	3	.00	.00	.00	3.	1.02	2.30	53	.06	.01	.05	33.
1.01	2.00	4	.00	.00	.00	3.	1.02	3.00	54	.06	.01	.05	39.
1.01	2.30	5	.00	.00	.00	3.	1.02	3.30	55	.06	.01	.05	43.

NO.	MO-DA	HR-MN	PERIOD	RAIN	EXCS	LOSS	COMP Q	END-OF-PERIOD FLOW	MO-DA	HR-MN	PERIOD	RAIN	EXCS	LOSS	COMP Q
1	01	1-30	1	0.00	0.00	0.00	3	1.02	1-02	1-30	51	0.06	0.01	0.03	17.
1	01	1-00	2	0.00	0.00	0.00	3	1.02	1-02	2-00	52	0.06	0.01	0.03	26.
1	01	1-30	3	0.00	0.00	0.00	3	1.02	1-02	3-00	53	0.06	0.01	0.03	33.
1	01	2-00	4	0.00	0.00	0.00	3	1.02	1-02	3-00	54	0.06	0.01	0.03	39.
1	01	2-30	5	0.00	0.00	0.00	3	1.02	1-02	4-00	55	0.06	0.01	0.03	45.
1	01	3-00	6	0.00	0.00	0.00	3	1.02	1-02	4-00	56	0.06	0.01	0.03	45.
1	01	3-30	7	0.00	0.00	0.00	3	1.02	1-02	5-00	57	0.06	0.01	0.03	47.
1	01	4-00	8	0.00	0.00	0.00	3	1.02	1-02	5-00	58	0.06	0.01	0.03	49.
1	01	4-30	9	0.00	0.00	0.00	3	1.02	1-02	5-00	59	0.06	0.01	0.03	50.
1	01	5-00	10	0.00	0.00	0.00	3	1.02	1-02	6-00	60	0.06	0.01	0.03	50.
1	01	5-30	11	0.00	0.00	0.00	3	1.02	1-02	6-30	61	0.16	0.12	0.05	61.
1	01	6-00	12	0.00	0.00	0.00	3	1.02	1-02	7-00	62	0.16	0.12	0.05	58.
1	01	6-30	13	0.00	0.00	0.00	3	1.02	1-02	7-30	63	0.16	0.12	0.05	160.
1	01	7-00	14	0.00	0.00	0.00	3	1.02	1-02	8-00	64	0.16	0.12	0.05	232.
1	01	7-30	15	0.00	0.00	0.00	4	1.02	1-02	8-30	65	0.16	0.12	0.05	283.
1	01	8-00	16	0.00	0.00	0.00	4	1.02	1-02	9-00	66	0.16	0.12	0.05	336.
1	01	8-30	17	0.00	0.00	0.00	4	1.02	1-02	9-30	67	0.16	0.12	0.05	368.
1	01	9-00	18	0.00	0.00	0.00	4	1.02	1-02	10-00	68	0.16	0.12	0.05	405.
1	01	9-30	19	0.00	0.00	0.00	5	1.02	1-02	10-30	69	0.16	0.12	0.05	405.
1	01	10-00	20	0.00	0.00	0.00	5	1.02	1-02	11-00	70	0.16	0.12	0.05	483.
1	01	10-30	21	0.00	0.00	0.00	5	1.02	1-02	11-30	71	0.16	0.12	0.05	483.
1	01	11-00	22	0.00	0.00	0.00	5	1.02	1-02	12-00	72	0.16	0.12	0.05	489.
1	01	11-30	23	0.00	0.00	0.00	5	1.02	1-02	13-00	73	0.99	0.94	0.05	514.
1	01	12-00	24	0.00	0.00	0.00	5	1.02	1-02	13-00	74	0.99	0.94	0.05	207.
1	01	12-30	25	0.00	0.00	0.00	5	1.02	1-02	14-00	75	1.18	1.14	0.05	1330.
1	01	13-00	26	0.00	0.00	0.00	7	1.02	1-02	14-00	76	1.18	1.14	0.05	1627.
1	01	13-30	27	0.00	0.00	0.00	10	1.02	1-02	14-00	77	1.48	1.43	0.05	2612.
1	01	14-00	28	0.00	0.00	0.00	14	1.02	1-02	15-00	78	1.43	1.43	0.05	3260.
1	01	14-30	29	0.00	0.00	0.00	18	1.02	1-02	15-30	79	1.60	1.75	0.05	3774.
1	01	15-00	30	0.00	0.00	0.00	21	1.02	1-02	16-00	80	5.69	5.65	0.04	4737.
1	01	15-30	31	0.00	0.00	0.00	25	1.02	1-02	16-30	81	1.38	1.33	0.05	6789.
1	01	16-00	32	0.00	0.00	0.00	34	1.02	1-02	17-00	82	1.38	1.33	0.05	7564.
1	01	16-30	33	0.00	0.00	0.00	36	1.02	1-02	17-30	83	1.08	1.04	0.05	4006.
1	01	17-00	34	0.00	0.00	0.00	83	1.02	1-02	18-00	84	1.08	1.04	0.05	7437.
1	01	17-30	35	0.00	0.00	0.00	106	1.02	1-02	18-30	85	0.00	0.00	0.00	6442.
1	01	18-00	36	0.00	0.00	0.00	113	1.02	1-02	19-00	86	0.00	0.00	0.00	5375.
1	01	18-30	37	0.00	0.00	0.00	107	1.02	1-02	19-30	87	0.00	0.00	0.00	4231.
1	01	19-00	38	0.00	0.00	0.00	93	1.02	1-02	20-00	88	0.00	0.00	0.00	3151.
1	01	19-30	39	0.00	0.00	0.00	74	1.02	1-02	20-30	89	0.00	0.00	0.00	2292.
1	01	20-00	40	0.00	0.00	0.00	55	1.02	1-02	21-00	90	0.00	0.00	0.00	1650.
1	01	20-30	41	0.00	0.00	0.00	40	1.02	1-02	21-30	91	0.00	0.00	0.00	1240.
1	01	21-00	42	0.00	0.00	0.00	22	1.02	1-02	22-00	92	0.00	0.00	0.00	726.
1	01	21-30	43	0.00	0.00	0.00	22	1.02	1-02	22-30	93	0.00	0.00	0.00	735.
1	01	22-00	44	0.00	0.00	0.00	16	1.02	1-02	23-00	94	0.00	0.00	0.00	735.
1	01	22-30	45	0.00	0.00	0.00	12	1.02	1-02	23-30	95	0.00	0.00	0.00	735.
1	01	23-00	46	0.00	0.00	0.00	11	1.03	1-03	0-00	96	0.00	0.00	0.00	696.
1	01	23-30	47	0.00	0.00	0.00	11	1.03	1-03	0-30	97	0.00	0.00	0.00	689.
1	02	0-00	48	0.00	0.00	0.00	10	1.03	1-03	1-00	98	0.00	0.00	0.00	682.
1	02	0-30	49	0.00	0.00	0.00	10	1.03	1-03	1-30	99	0.00	0.00	0.00	617.
1	02	1-00	50	0.00	0.00	0.00	10	1.03	1-03	2-00	100	0.00	0.00	0.00	592.

SUM 24.82 21.51 3.30 84080.
(630.1) (566.1) (24.1) (2381.16)

6-HOUR PEAK 8006. 227. 146. 49. 24. 2373.
5217. 1723. 838. 146. 49. 24. 2373.
TOTAL VOLUME 83795. 22.02 22.02 559.29 559.29

Sheet 9 of 21

CMS 227. 146. 49. 24. 2373.
INCHES 16.45 21.73 22.02 22.02
MM 417.83 551.91 559.29 559.29
AC-FT 2587. 3417. 3663. 3663.
THOUS CU M 3191. 4215. 4271. 4271.

CMS 227. 148. 49. 24. 2373.
 INCHES 16.45 21.73 22.02 22.02
 M4 417.83 531.91 559.29 559.29
 AC-FT 2587. 3417. 3463. 3463.
 THOUS CU M 3191. 4215. 4271. 4271.

HYDROGRAPH AT STA 1 FOR PLAN 1, RTIO 1

	3.	3.	3.	3.	3.	3.	3.	3.	3.
3.	3.	3.	3.	3.	3.	3.	3.	3.	3.
3.	3.	3.	3.	3.	3.	3.	3.	3.	3.
5.	5.	5.	5.	5.	5.	5.	5.	5.	5.
25.	34.	55.	83.	106.	113.	107.	93.	76.	55.
40.	29.	16.	11.	11.	11.	10.	10.	10.	10.
17.	26.	33.	39.	43.	45.	47.	49.	50.	50.
61.	93.	150.	232.	293.	336.	367.	388.	406.	415.
423.	429.	516.	807.	1330.	1977.	2612.	3200.	3776.	4737.
6229.	7564.	6006.	7437.	6442.	5375.	4231.	3151.	2292.	1680.
1240.	926.	785.	755.	725.	696.	669.	642.	617.	592.

PEAK 6-HOUR 24-HOUR 72-HOUR TOTAL VOLUME
 8006. 5217. 1723. 838. 83793.
 CFS 227. 148. 49. 24. 2373.
 INCHES 16.45 21.73 22.02 22.02
 M4 417.83 531.91 559.29 559.29
 AC-FT 2587. 3417. 3463. 3463.
 THOUS CU M 3191. 4215. 4271. 4271.

HYDROGRAPH AT STA 1 FOR PLAN 1, RTIO 2

	2.	2.	2.	2.	2.	2.	2.	2.	2.
2.	2.	2.	2.	2.	2.	2.	2.	2.	2.
2.	2.	2.	2.	2.	2.	2.	2.	2.	2.
4.	4.	4.	4.	4.	4.	4.	4.	4.	4.
18.	25.	41.	62.	79.	85.	80.	70.	55.	41.
30.	22.	16.	12.	9.	8.	8.	7.	7.	7.
13.	19.	25.	29.	32.	34.	36.	37.	37.	38.
46.	73.	120.	174.	220.	252.	275.	271.	271.	311.
317.	321.	386.	605.	997.	1483.	1959.	2400.	2831.	3553.
4672.	5673.	6004.	5578.	4832.	4031.	3174.	2353.	1719.	1200.
920.	694.	590.	566.	544.	522.	502.	482.	462.	444.

PEAK 6-HOUR 24-HOUR 72-HOUR TOTAL VOLUME
 6004. 3913. 1292. 628. 62846.
 CFS 170. 111. 37. 18. 1700.
 INCHES 12.34 16.30 16.51 16.51
 M4 313.37 433.29 419.47 419.47
 AC-FT 1940. 2363. 2597. 2597.
 THOUS CU M 2393. 3161. 3203. 3203.

HYDROGRAPH AT STA 1 FOR PLAN 1, RTIO 3

	1.	2.	2.	2.	2.	2.	2.	2.	2.
1.	1.	2.	2.	2.	2.	2.	2.	2.	2.
2.	2.	2.	2.	2.	2.	2.	2.	2.	2.
2.	2.	2.	2.	2.	2.	2.	2.	2.	2.
12.	17.	28.	42.	53.	57.	54.	48.	37.	28.
20.	11.	8.	5.	6.	5.	5.	5.	5.	5.
9.	13.	17.	19.	21.	23.	24.	24.	25.	25.
31.	49.	116.	146.	168.	183.	194.	202.	208.	208.

PEAK 6-HOUR 24-HOUR 72-HOUR TOTAL VOLUME
 4003. 3719. 3221. 2888. 1306. 1600. 2369.
 CFS 393. 376. 363. 348. 2116. 1576. 840.
 INCHES 8.22 10.46 11.01 11.01 11.01 11.01
 M4 208.91 275.93 270.05 270.05 270.05
 AC-FT 1294. 1708. 1741. 1741.

Sheet 10 of 31

211.	214.	257.	403.	665.	989.	1306.	1800.	1887.	2369.
3115.	3782.	4003.	3719.	3221.	2688.	2116.	1576.	1126.	840.
620.	463.	393.	378.	363.	348.	334.	321.	308.	296.
PEAK 6-HOUR 24-HOUR 72-HOUR TOTAL VOLUME CFS 4003 2608 861 419 41837 CMS 113 74 24 12 1186 INCHES 8.22 10.86 11.01 11.01 PM 208.91 275.95 279.65 279.65 AC-FT 1293 1708 1731 1731 THOUS CU M 1595 2107 2136 2136									

HYDROGRAPH AT STA 1 FOR PLAN 1, RTIO 4

1.	1.	1.	1.	1.	1.	1.	1.	1.	1.
1.	1.	1.	1.	1.	1.	1.	1.	1.	1.
1.	1.	1.	1.	1.	1.	1.	1.	1.	1.
6.	8.	14.	21.	26.	28.	27.	23.	18.	14.
10.	7.	4.	3.	3.	3.	3.	2.	2.	2.
4.	6.	8.	10.	11.	11.	12.	12.	12.	13.
15.	26.	40.	58.	73.	84.	92.	97.	101.	104.
106.	107.	129.	202.	332.	494.	653.	800.	944.	1184.
1557.	1891.	2001.	1859.	1611.	1344.	1058.	782.	573.	420.
310.	231.	197.	189.	181.	174.	167.	151.	154.	148.

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
2001.	1304.	431.	209.	20940.
CFS	37.	12.	6.	593.
CMS	4.11	5.43	5.50	5.50
INCHES	104.46	137.58	139.82	139.82
MM	647.	854.	866.	866.
AC-FT	790.	1034.	1068.	1068.
THOUS CU M				

2 ROUTE THROUGH LAKE

ISTAG	2	ICOMP	1	IECON	0	ITAPE	0	JPLT	0	JPRT	0	INAME	ISTAGE	IAUTO
ROUTING DATA														
QLOSS	0.0	CLOSS	0.00	AVG	0.00	IBRES	1	ISAKE	1	IOPT	0	IPMP	0	LSTR
MSTPS MSTDL LAS AMSK X TSK STORA ISPRAT														
1	0	0	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
STAGE	587.00	598.00	589.00	570.00	591.00	592.30	594.00	597.00						
FLOW	0.00	18.00	50.80	97.50	174.20	309.70	529.70	1010.40						
CAPACITY	920.	1370.	1822.	2469.	4003.									
ELEVATION	587.	590.	592.	595.	600.									

CREL	SPMID	COU	EXPN	ELEV	COQL	CAREA	EXPL
587.0	0.0	C.0	0.0	0.0	0.0	0.0	0.0

TOPEL COOD EXPD BARRID

QN(1) QN(2) QN(3) ELNVT ELMAX RLNTH SEL
 .0350 .0170 .0350 566.0 600.0 1300. .01200

CROSS SECTION COORDINATES--STA, ELEV, STA, ELEV--ETC
 0.00 600.00 250.00 570.00 377.00 548.00 303.00 508.00
 345.00 575.00 645.00 540.00 1395.00 609.00

STORAGE	0.00	54.07	110.14	139.45	172.63	208.65	247.94	5.28	12.62	24.84	41.32	61.07
OUTFLW	0.00	337.21	62944.34	82737.79	120192.05	1785.02	29222.97	4846.96	8326.33	15160.83	26521.99	42338.60
STAGE	568.00	564.84	569.68	571.37	573.05	574.74	576.42	578.11	579.79	581.47	583.16	600.00
FLOW	0.00	337.21	98737.78	120192.05	1885.02	29222.97	4846.96	8326.33	15160.83	26521.99	42338.60	530315.22

STATION 3. PLAN 1. RTIO 1

STAGE	568.00	564.84	569.68	571.37	573.05	574.74	576.42	578.11	579.79	581.47	583.16	600.00
OUTFLW	0.00	337.21	98737.78	120192.05	1885.02	29222.97	4846.96	8326.33	15160.83	26521.99	42338.60	530315.22
STAGE	568.00	564.84	569.68	571.37	573.05	574.74	576.42	578.11	579.79	581.47	583.16	600.00
FLOW	0.00	337.21	98737.78	120192.05	1885.02	29222.97	4846.96	8326.33	15160.83	26521.99	42338.60	530315.22

STOR

STAGE	568.00	564.84	569.68	571.37	573.05	574.74	576.42	578.11	579.79	581.47	583.16	600.00
OUTFLW	0.00	337.21	98737.78	120192.05	1885.02	29222.97	4846.96	8326.33	15160.83	26521.99	42338.60	530315.22
STAGE	568.00	564.84	569.68	571.37	573.05	574.74	576.42	578.11	579.79	581.47	583.16	600.00
FLOW	0.00	337.21	98737.78	120192.05	1885.02	29222.97	4846.96	8326.33	15160.83	26521.99	42338.60	530315.22

STAGE

STAGE	568.00	564.84	569.68	571.37	573.05	574.74	576.42	578.11	579.79	581.47	583.16	600.00
OUTFLW	0.00	337.21	98737.78	120192.05	1885.02	29222.97	4846.96	8326.33	15160.83	26521.99	42338.60	530315.22
STAGE	568.00	564.84	569.68	571.37	573.05	574.74	576.42	578.11	579.79	581.47	583.16	600.00
FLOW	0.00	337.21	98737.78	120192.05	1885.02	29222.97	4846.96	8326.33	15160.83	26521.99	42338.60	530315.22

Sheet 16 of 21

STAGE	575.1	574.4	573.7	573.2	572.7	572.3	572.0	571.8	571.6	571.4
OUTFLW	0.00	337.21	98737.78	120192.05	1885.02	29222.97	4846.96	8326.33	15160.83	26521.99
STAGE	568.00	564.84	569.68	571.37	573.05	574.74	576.42	578.11	579.79	581.47
FLOW	0.00	337.21	98737.78	120192.05	1885.02	29222.97	4846.96	8326.33	15160.83	26521.99

PEAK 5055. 3764. 1172. 563. 56347.
 CFS 107. 33. 1500.
 CHS 11.27 14.78 14.81
 INCHES 301.50 375.51 374.09
 AC-FT 1162. 255. 2108.

STATION	574.4	573.7	573.2	572.7	572.3	572.0	571.8	571.6	571.4
PEAK		5055.	3764.	1172.	563.				
CFS		143.	107.	73.	16.				
CMS		11.67	14.78	14.81	14.81				
INCHES		301.50	375.51	374.09	374.09				
PH		1867.	2321.	2328.	2328.				
AC-FT		2302.	2668.	2872.	2872.				
THOUS CU M									
TOTAL VOLUME									

MAXIMUM STORAGE = 6.

MAXIMUM STAGE IS 576.6 STATION 3, PLAN 1, RATIO 2

STATION	575.1	574.6	573.7	573.2	572.7	572.3	572.0	571.8	571.6	571.4
OUTFLD	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
STOR	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
THOUS CU M	2261.	1932.	1579.	1453.	1296.	1150.	1050.	950.	881.	809.

STAGE

STATION	566.0	568.0	569.0	568.0	568.0	568.0	568.0	568.0	568.0	568.0
OUTFLD	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
STOR	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
THOUS CU M	2261.	1932.	1579.	1453.	1296.	1150.	1050.	950.	881.	809.

STAGE

STATION	566.0	568.0	569.0	568.0	568.0	568.0	568.0	568.0	568.0	568.0
OUTFLD	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
STOR	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
THOUS CU M	2261.	1932.	1579.	1453.	1296.	1150.	1050.	950.	881.	809.

Sheet 17 of 21

STATION	575.1	574.6	573.7	573.2	572.7	572.3	572.0	571.8	571.6	571.4
PEAK		3406.	2448.	763.						
CFS		96.	69.	22.	10.					
CMS		7.72	9.62	9.64	9.64					
INCHES		196.11	244.36	244.80	244.80					
PH										
AC-FT										
THOUS CU M										
TOTAL VOLUME										

MAXIMUM STORAGE = 3.

ST-SI 2

AC-FT 1214. 1513. 1516. 1516.
THOUS CU M 1498. 1866. 1869. 1869.

MAXIMUM STORAGE = 3.

STATION 3, PLAN 1, RATIO 3

MAXIMUM STAGE IS 575.2

STAGE	IN	OUT	STOR	OUTFLOW
0	0	0	0	0
1	0	0	0	0
2	0	0	0	0
3	1	1	1	2
4	2	2	2	2
5	3	3	3	3
6	4	4	4	4
7	5	5	5	5
8	6	6	6	6
9	7	7	7	7
10	11	12	14	16
11	18	22	22	22
12	26	32	32	32
13	43	45	45	45
14	83	64	64	64
15	139	90	90	90
16	247	138	138	138
17	415	197	197	197
18	653	284	284	284
19	982	403	403	403
20	1412	569	569	569
21	2064	831	831	831
22	2959	1189	1189	1189
23	4137	1700	1700	1700
24	575.2	2367	2367	2367

STOR

OUTFLOW

STAGE

OUTFLOW

PEAK 6-HOUR 24-HOUR 72-HOUR TOTAL VOLUME

CFS 1497. 1136. 361. 174. 17395.

CMS 42. 32. 10. 5. 493.

INCHES 3.58 4.56 4.57 4.57

PM 90.97 115.8 116.10 116.10

AC-FT 563. 719. 719.

THOUS CU M 695. 887. 887.

MAXIMUM STORAGE = 2.

Sheet 18 of 21

MAXIMUM STAGE IS 572.3

STATION 3, PLAN 1, RATIO 4

OUTFLOW

STAGE	IN	OUT	STOR	OUTFLOW
0	0	0	0	0
1	0	0	0	0
2	0	0	0	0
3	1	1	1	2
4	2	2	2	2
5	3	3	3	3
6	4	4	4	4
7	5	5	5	5
8	6	6	6	6
9	7	7	7	7
10	11	12	14	16
11	18	22	22	22
12	26	32	32	32
13	43	45	45	45
14	83	64	64	64
15	139	90	90	90
16	247	138	138	138
17	415	197	197	197
18	653	284	284	284
19	982	403	403	403
20	1412	569	569	569
21	2064	831	831	831
22	2959	1189	1189	1189
23	4137	1700	1700	1700
24	572.3	2367	2367	2367

Sheet 19 of 21

MAXIMUM STAGE IS 572.3

STATION 3. PLAN 1. RATIO 4

STAGE	INLET	OUTFLOW	STOR	OUTLET
0.	0.	0.	0.	0.
1.	0.	0.	0.	0.
2.	0.	0.	0.	0.
3.	0.	0.	0.	0.
4.	1.	1.	0.	1.
5.	1.	1.	0.	1.
6.	2.	2.	0.	2.
7.	3.	3.	0.	3.
8.	4.	4.	0.	4.
9.	6.	10.	0.	16.
10.	8.	13.	0.	23.
11.	11.	18.	0.	31.
12.	14.	24.	0.	40.
13.	17.	31.	0.	50.
14.	20.	40.	0.	61.
15.	23.	50.	0.	74.
16.	26.	61.	0.	88.
17.	29.	74.	0.	104.
18.	32.	88.	0.	122.
19.	35.	104.	0.	142.
20.	38.	122.	0.	164.
21.	41.	142.	0.	188.
22.	44.	164.	0.	214.
23.	47.	188.	0.	242.
24.	50.	214.	0.	272.
25.	52.	242.	0.	304.
26.	54.	272.	0.	338.
27.	56.	304.	0.	374.
28.	58.	338.	0.	412.
29.	60.	374.	0.	452.
30.	62.	412.	0.	494.
31.	64.	452.	0.	538.
32.	66.	494.	0.	584.
33.	68.	538.	0.	632.
34.	70.	584.	0.	682.
35.	72.	632.	0.	734.
36.	74.	682.	0.	788.
37.	76.	734.	0.	844.
38.	78.	788.	0.	902.
39.	80.	844.	0.	962.
40.	82.	902.	0.	1024.
41.	84.	962.	0.	1088.
42.	86.	1024.	0.	1154.
43.	88.	1088.	0.	1222.
44.	90.	1154.	0.	1292.
45.	92.	1222.	0.	1364.
46.	94.	1292.	0.	1438.
47.	96.	1364.	0.	1514.
48.	98.	1438.	0.	1592.
49.	100.	1514.	0.	1672.
50.	102.	1592.	0.	1754.
51.	104.	1672.	0.	1838.
52.	106.	1754.	0.	1924.
53.	108.	1838.	0.	2012.
54.	110.	1924.	0.	2102.
55.	112.	2012.	0.	2194.
56.	114.	2102.	0.	2288.
57.	116.	2194.	0.	2384.
58.	118.	2288.	0.	2482.
59.	120.	2384.	0.	2582.
60.	122.	2482.	0.	2684.
61.	124.	2582.	0.	2788.
62.	126.	2684.	0.	2894.
63.	128.	2788.	0.	3002.
64.	130.	2894.	0.	3112.
65.	132.	2992.	0.	3224.
66.	134.	3094.	0.	3338.
67.	136.	3192.	0.	3454.
68.	138.	3294.	0.	3572.
69.	140.	3394.	0.	3692.
70.	142.	3492.	0.	3814.
71.	144.	3594.	0.	3938.
72.	146.	3692.	0.	4064.
73.	148.	3794.	0.	4192.
74.	150.	3892.	0.	4322.
75.	152.	3994.	0.	4454.
76.	154.	4092.	0.	4588.
77.	156.	4194.	0.	4724.
78.	158.	4292.	0.	4862.
79.	160.	4394.	0.	5002.
80.	162.	4492.	0.	5144.
81.	164.	4594.	0.	5288.
82.	166.	4692.	0.	5434.
83.	168.	4794.	0.	5582.
84.	170.	4892.	0.	5732.
85.	172.	4994.	0.	5884.
86.	174.	5092.	0.	6038.
87.	176.	5194.	0.	6194.
88.	178.	5292.	0.	6352.
89.	180.	5394.	0.	6512.
90.	182.	5492.	0.	6674.
91.	184.	5594.	0.	6838.
92.	186.	5692.	0.	7004.
93.	188.	5794.	0.	7172.
94.	190.	5892.	0.	7342.
95.	192.	5994.	0.	7514.
96.	194.	6092.	0.	7688.
97.	196.	6194.	0.	7864.
98.	198.	6292.	0.	8042.
99.	200.	6394.	0.	8222.
100.	202.	6492.	0.	8404.
101.	204.	6594.	0.	8588.
102.	206.	6692.	0.	8774.
103.	208.	6794.	0.	8962.
104.	210.	6892.	0.	9152.
105.	212.	6994.	0.	9344.
106.	214.	7092.	0.	9538.
107.	216.	7194.	0.	9734.
108.	218.	7292.	0.	9932.
109.	220.	7394.	0.	10132.
110.	222.	7492.	0.	10334.
111.	224.	7594.	0.	10538.
112.	226.	7692.	0.	10744.
113.	228.	7794.	0.	10952.
114.	230.	7892.	0.	11162.
115.	232.	7994.	0.	11374.
116.	234.	8092.	0.	11588.
117.	236.	8194.	0.	11804.
118.	238.	8292.	0.	12022.
119.	240.	8394.	0.	12242.
120.	242.	8492.	0.	12464.
121.	244.	8594.	0.	12688.
122.	246.	8692.	0.	12914.
123.	248.	8794.	0.	13142.
124.	250.	8892.	0.	13372.
125.	252.	8994.	0.	13604.
126.	254.	9092.	0.	13838.
127.	256.	9194.	0.	14074.
128.	258.	9292.	0.	14312.
129.	260.	9394.	0.	14552.
130.	262.	9492.	0.	14794.
131.	264.	9594.	0.	15038.
132.	266.	9692.	0.	15284.
133.	268.	9794.	0.	15532.
134.	270.	9892.	0.	15782.
135.	272.	9994.	0.	16034.
136.	274.	10092.	0.	16288.
137.	276.	10194.	0.	16544.
138.	278.	10292.	0.	16802.
139.	280.	10394.	0.	17062.
140.	282.	10492.	0.	17324.
141.	284.	10594.	0.	17588.
142.	286.	10692.	0.	17854.
143.	288.	10794.	0.	18122.
144.	290.	10892.	0.	18392.
145.	292.	10994.	0.	18664.
146.	294.	11092.	0.	18938.
147.	296.	11194.	0.	19214.
148.	298.	11292.	0.	19492.
149.	300.	11394.	0.	19772.
150.	302.	11492.	0.	20054.
151.	304.	11594.	0.	20338.
152.	306.	11692.	0.	20624.
153.	308.	11794.	0.	20912.
154.	310.	11892.	0.	21202.
155.	312.	11994.	0.	21494.
156.	314.	12092.	0.	21788.
157.	316.	12194.	0.	22084.
158.	318.	12292.	0.	22382.
159.	320.	12394.	0.	22682.
160.	322.	12492.	0.	22984.
161.	324.	12594.	0.	23288.
162.	326.	12692.	0.	23594.
163.	328.	12794.	0.	23902.
164.	330.	12892.	0.	24212.
165.	332.	12994.	0.	24524.
166.	334.	13092.	0.	24838.
167.	336.	13194.	0.	25154.
168.	338.	13292.	0.	25472.
169.	340.	13394.	0.	25792.
170.	342.	13492.	0.	26114.
171.	344.	13594.	0.	26438.
172.	346.	13692.	0.	26764.
173.	348.	13794.	0.	27092.
174.	350.	13892.	0.	27422.
175.	352.	13994.	0.	27754.
176.	354.	14092.	0.	28088.
177.	356.	14194.	0.	28424.
178.	358.	14292.	0.	28762.
179.	360.	14394.	0.	29102.
180.	362.	14492.	0.	29444.
181.	364.	14594.	0.	29788.
182.	366.	14692.	0.	30134.
183.	368.	14794.	0.	30482.
184.	370.	14892.	0.	30832.
185.	372.	14994.	0.	31184.
186.	374.	15092.	0.	31538.
187.	376.	15194.	0.	31894.
188.	378.	15292.	0.	32252.
189.	380.	15394.	0.	32612.
190.	382.	15492.	0.	32974.
191.	384.	15594.	0.	33338.
192.	386.	15692.	0.	33704.
193.	388.	15794.	0.	34072.
194.	390.	15892.	0.	34442.
195.	392.	15994.	0.	34814.
196.	394.	16092.	0.	35188.
197.	396.	16194.	0.	35564.
198.	398.	16292.	0.	35942.
199.	400.	16394.	0.	36322.
200.	402.	16492.	0.	36704.
201.	404.	16594.	0.	37088.
202.	406.	16692.	0.	37474.
203.	408.	16794.	0.	37862.
204.	410.	16892.	0.	38252.
205.	412.	16994.	0.	38644.
206.	414.	17092.	0.	39038.
207.	416.	17194.	0.	39434.
208.	418.	17292.	0.	39832.
209.	420.	17394.	0.	40232.
210.	422.	17492.	0.	40634.
211.	424.	17594.	0.	41038.
212.	426.	17692.	0.	41444.
213.	428.	17794.	0.	41852.
214.	430.	17892.	0.	42262.
215.	432.	17994.	0.	42674.
216.	434.	18092.	0.	43088.
217.	436.	18194.	0.	43504.
218.	438.	18292.	0.	43922.
219.	440.	18394.	0.	44342.
220.	442.	18492.	0.	44764.
221.	444.	18594.	0.	45188.
222.	446.	18692.	0.	45614.
223.	448.	18794.	0.	46042.
224.	450.	18892.	0.	46472.
225.	452.	18994.	0.	46904.
226.	454.	19092.	0.	47338.
227.	456.	19194.	0.	47774.
228.	458.	19292.	0.	48212.
229.	460.	19394.	0.	48652.
230.	462.	19492.	0.	49094.
231.	464.	19594.	0.	49538.
232.	466.	19692.	0.	49984.
233.	468.	19794.	0.	50432.
234.	470.	19892.	0.	50882.
235.	472.	19994.	0.	51334.
236.	474.	20092.	0.	51788.
237.	476.	20194.	0.	52244.
238.	478.	20292.	0.	52702.
239.	480.	20394.	0.	53162.
240.	482.	20492.	0.	53624.
241.	484.	20594.	0.	54088.
242.	486.	20692.	0.	54554.
243.	488.	20794.	0.	55022.
244.	490.	20892.	0.	55492.
245.	492.	20994.	0.	55964.
246.	494.	21092.	0.	56438.
247.	496.	21194.	0.	56914.
248.	498.	21292.	0.	57392.
249.	500.	21394.	0.	57872.
250.	502.	21492.	0.	58354.
251.	504.	21594.	0.	58838.
252.	506.	21692.	0.	59324.
253.	508.	21794.	0.	59812.
254.	510.	21892.	0.	60302.
255.	512.	21994.	0.	60794.
256.	514.	22092.	0.	61288.
257.	516.	22194.	0.	61784.
258.	518.	22292.	0.	62282.
259.	520.	22394.	0.	62782.
260.	522.	22492.	0.	63284.
261.	524.	22594.	0.	63788.
262.	526.	22692.	0.	64294.
263.	528.	22794.	0.	64802.
264.	530.	22892.	0.	65312.
265.	532.	22994.	0.	65824.
266.	534.	23092.	0.	66338.
267.	536.	23194.	0.	66854.
268.	538.	23292.	0.	67372.
269.	540.	23394.	0.	67892.
270.	542.			

URGENT 10 21

SUMMARY OF DAM SAFETY ANALYSIS

PLAY 1		INITIAL VALUE	SPILLWAY CREST	TOP OF DAM
ELEVATION	587.00	920.	920.	592.30
STORAGE	0.	0.	0.	1822.
OUTFLOW	0.	0.	0.	310.

RATIO OF PMF	MAXIMUM RESERVOIR W.S. ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
1.00	595.80	3.56	2734.	5070.	10.00	43.00	0.00
.75	594.95	2.65	2457.	3401.	9.50	43.50	0.00
.50	593.67	1.37	2150.	1496.	8.50	44.00	0.00
.25	591.41	0.00	1648.	217.	0.00	46.00	0.00

PLAN 1 STATION 3

RATIO	MAXIMUM FLC CFS	MAXIMUM STAGE FT	TIME HOURS
1.00	5055.	574.6	43.00
.75	3426.	575.2	43.50
.50	1497.	572.3	44.00
.25	217.	569.1	46.50

Sheet 21 of 21

STABILITY ANALYSIS

APPENDIX E

TAMS

Job No. 1579-13

Sheet 1 of 24

Project NYS Dam Inspection

Date 5-27-81

Subject Kirk Lake Dam Stability Analysis

By JF

Ch'k. by _____

Assumptions

- 1) The Unit weights assumed were as follows:
fill 115pcf, Concrete 150pcf, Earthfill (ds.s) 65pcf
- 2) Stability and conditions determined in accordance with
Code of Engineers Part I Guidelines
- 3) The Concrete slab on the approach channel
is not considered an integral part of the
structure. The earthfill below the slab is considered
to be completely pervious and saturated. Therefore
total hydrostatic head is considered to be
acting at the base of the structure.
- 4) Angle of internal resistance of Till Soil
foundation is considered to be 35° , $C=200$ pcf
based on observations and engineering judgement.
 K_a assumed for backfill, based on $\phi=35^\circ$.
- 5) Dam site is in Seismic Zone 2.
- 6) Ice Load of $5K/ft^2$ acting at $1/2$ from
the top of the spillway section.

Loading Conditions

- I) Normal Load; Lake at spillway crest, Elev. 587.
No Ice Load.
- II) Normal Load; Lake at spillway crest; Elev 587.
With Ice Load
- III) Unusual Load; Lake at $1/2$ PNF Elev. 593.67
- IV) Extreme Load; Lake at PNF Elev. 575.86
- V) Unusual Load; Lake at Elev. 587 with
addition of 0.05g earthquake force.

TAMS

Job No. 1579-13

Sheet 2 of 24

Project NYS Dam Insp.

Date 5-27-01

Subject Kirk Lake Dam

By JF

Ch'k. by _____

STABILITY CRITERIA (see assumption # 2)

a) Overturning Criteria Loading Cases ~~I, II, III~~ ~~IV, V, VI~~ - Resultant must fall within the middle 1/3 of the base.

- Loading Case ~~I~~ Resultant must fall within the base.

b) Sliding Criteria - Cases I through VI

Shear friction factor of safety ≥ 3
(SFFS)


Case ~~I~~

Shear friction factor of safety ≥ 1.5
(SFFS)


TAMS

Job No. 1579-13
 Project NYS DAM INSP
 Subject KICK LAKE DAM

Sheet 3 of 27
 Date _____
 By _____
 Ch'k. by _____



SPILLWAY
 Plan Scale 1" = 5'



Section A-A Scale 1" = 5'

TAMS

Joh No. 1577-13

Project NYS DAM INSPECTION


Subject KIRK LAKE DAM

Sheet 4 of 20

Date 6-9-81

By JW

Ch'k. by _____



TAMS

Job No. 1577-13

Sheet 5 of 24

Project Wife Dam Spillway

Date 6-8-57


Subject L. K. Lake Dam - Spillway Analysis

By JGD

Ch'k. by _____

Calculate total Mass of Spillway Section

Section E-B- width 4 feet



Total Mass of $17' \times 22' \times 4.0'$ block =	$17' \times 22' \times 165 \text{ pcf} = 646,340 \text{ K}$
Less Mass of Circular pile 4' x 6' $17.0' \times 165 \text{ pcf}$	- 75,340 K
Mass of (A) $3' \times 4' \times 4.0' \times 165 \text{ pcf}$	- 7,920
Mass of (B) $3' \times 1' \times 4.0' \times 165 \text{ pcf}$	- 1,980
(C) $2' \times 4' \times 4.0' \times 165 \text{ pcf}$	- 21,120
(D) $2' \times 1' \times 4.0' \times 165 \text{ pcf}$	- 2,640
(E) $3' \times 3' \times 4.0' \times 165 \text{ pcf}$	- 11,880
(F) $1/2(3' \times 5') \times 4.0' \times 165 \text{ pcf}$	- 4,950
(G) $1/2(3' \times 5') \times 4.0' \times 165 \text{ pcf}$	- 11,880

Total Mass = 117,220 K

TAMS

Job No. 1579-13

Sheet 6 of 24

Project 1145 River Improvement

Date 6-9-31

Subject Kink Lake Dam - Foundation Design

By JW

Ch'k. by _____

Find Centroid of Area Section B-B - symmetric about long axis

Sum of Areas = 127.67 sq ft
 Dist. of Centroid from Base = 64.82

$$246.540 - 117.870 = 128.670 \times 0.5 = 64.335$$

$$M_B + A \cdot X + \frac{1}{2} A \cdot X^2 = 64.82$$

$$7.97 + \frac{128.67}{11} X + \frac{128.67}{2} X^2 = 64.82$$

$$3.98 + 11.68 X + 12.867 X^2 = 64.82$$


$$7.97 + 11.68 X + 12.867 X^2 = 64.82$$

$$13.70 X = 137.04$$

$$X = 9.64$$

17.00 - 7.36 = 9.64

Section C-C 21/8



1. Area of 17' x 17' = 289

2. Area of 17' x 17' = 289

3. Area of 17' x 17' = 289

4. Area of 17' x 17' = 289

5. Area of 17' x 17' = 289

6. Area of 17' x 17' = 289

7. Area of 17' x 17' = 289

8. Area of 17' x 17' = 289

9. Area of 17' x 17' = 289

10. Area of 17' x 17' = 289

11. Area of 17' x 17' = 289

12. Area of 17' x 17' = 289

13. Area of 17' x 17' = 289

14. Area of 17' x 17' = 289

15. Area of 17' x 17' = 289

16. Area of 17' x 17' = 289

17. Area of 17' x 17' = 289

18. Area of 17' x 17' = 289

19. Area of 17' x 17' = 289

20. Area of 17' x 17' = 289

TAMS

Job No. 1479-13

Sheet 7 of 24

Project 1715 Canal Expansion

Date 6-28-51

Subject 1. 1/2 Lake Dam - 2nd Div. Reservoir

By J.P.

Ch'k. by _____

Total Area of Remaining Block - 67' wide x 2.5' high

$$\text{Total Area } 243 \times 17' \times 2.5(1) \times 115 \text{ ft} = 913.364 \text{ K ft}^2$$


Area of concrete to be placed 1/2' high

700 ft x 12 ft x 1/2' = 4200 ft³ of concrete

at 125 lb/ft³

$$\text{Weight of concrete } 4200 \text{ ft}^3 \times 125 \text{ lb/ft}^3 = 525,000 \text{ lb}$$

Area of concrete to be placed 1/2' high



$$\text{Area of concrete } [243 \times 17' + 17' \times 2.5'] \times 1/2' = 2430 \text{ ft}^2$$

Volume of concrete = 2430 ft² x 1/2' = 1215 ft³

Weight of concrete = 1215 ft³ x 125 lb/ft³ = 151,875 lb

$$\text{Total Mass of concrete } 151,875 \text{ lb} + 763,125 \text{ lb} = 915,000 \text{ lb}$$

Area of concrete to be placed 1/2' high

$$\frac{754,125 \text{ K}}{2} = 377.0625 \text{ K} = (12.15 \times 115) \text{ K} - (1.72 \times 115 \times 115)$$

$$377.07 \text{ K} - 52.727 \text{ K} = 324.34 \text{ K}$$

$$377.07 \text{ K} - 46.311 \text{ K}$$

17-531 = 5.25'

17-531 = 5.25'

TAMS

Job No. 1579-13

Sheet 8 of 24

Project 145 Dr. ...

Date 6-2-51

Subject Rock Lab. ...


By J.W.

Ch'k. by _____

Average Mass/lf of spillway width

$$\frac{\sum M_{avg}}{w} = \frac{117.2 + 166.2 + 754.1}{20.5'} = 50.6 \text{ Kips/lf}$$

Location of Net Resultant



$$\sum M = (754.1 \times 8.88) + (166.2 \times 9.6) + (117.2 \times 7.3) = 9214.8 \text{ K-ft}$$

Equival. Moment Arm $\frac{M}{F} = \frac{9214.8}{1037.5 \text{ K}} = 8.88'$

Resultant M $M = 449.3 \text{ K-ft}$

TAMS

Job No. 15-77-13

Sheet 9 of 24

Project M/S Dam Inspection

Date 6-2-51

Subject Kirk Lake Dam - Foundation Inspection

By JW


Ch'k. by _____

Calculate
ACTIVE EARTH PRESSURE ON WALL

- 1) Consider concrete Slabs as a 300 psf surcharge
- 2) Neglect pressure of lower level 25' pipe at center

$$\gamma_{\text{sub}} = 65 \text{ pcf} \quad K_a \text{ from } \phi = 35^\circ$$

$$K_a = .27$$



$$P_h = .5(300) + .27(65 \text{ pcf})(h)$$

$$P_h = 150 \quad P_b = 150 + 298 = 448 \text{ psf}$$

$$P = \frac{150 + 448}{2} \times 17 = 5,083 \text{ K}$$

Find Resultant Location ($\frac{1}{2}$ Load P_h)

$$\text{from Top } 150h + \frac{1}{2}(17.55x^2) = \frac{5,083}{2}$$

$$150h + 8.775x^2 = 2541.5$$

$$x^2 + 17.1x - 287.6 = 0$$

$$x = 10.5$$

$$M_A = 17 \cdot 10.5 = 178.5$$

$$F_H = 5,083 \text{ K}$$

$$M_D = 33.04 \text{ Kft}$$

TAMS

Job No. 1579-13

Sheet 10 of 24

Project NYS Dam Inspection


Date 1-8-57

Subject Kirk Lake Dam - Seepage Analysis

By Jed

Ch'k. by _____

Calculate Side Shear Available on side of spillway sections



From previous distribution of
 side of spillway section
 at 0.5923 w/ Dam Seepage
 is (comp. 0.26 pcf $k_0 = 1 - \sin \phi = 0.43$
 assume to irregular distribution

$$p = k_0 \gamma_c h = .43(62.4)h$$

$$P_s = \frac{1}{2} k_0 \gamma_c L^2 = \frac{1}{2} (24.3) P_T = 7.95 / \text{ft}$$

total $P_s = 7.95 \times 15.5 = 123.2 \text{ kips}$

bottom $\times 2 = 246.4 \text{ kips}$

Distributed pressure over of spillway

$$P_H = \frac{246.4 \text{ k}}{15.5 \text{ ft}} = 15.9 \text{ kips}$$

$$\text{at } 1/3 \text{ h} = \frac{24.3}{3} = 8.1 \text{ ft}$$

Spillage force is assumed
 $= 15 \times 15.9 = 238.5 \text{ kips}$

$$\text{Average depth} = \frac{238.5}{15.5} = 15.5 \text{ ft}$$

$$\text{Friction factor} = \frac{1}{2} \tan \phi = \frac{1}{2} (\tan 35^\circ) = .46$$

Upward resistance $.46 P_H = F_H = 7.31 \text{ kips}$

Resistance $M_H = 59.24 \text{ kft}$


TAMS

Job No. 1579-13
 Project KYS DI
 Subject KLD - SA

Sheet 11 of 24
 Date 6-8-81
 By [Signature]
 Ch'k. by _____

Case I Hydrostatic Pressure W/L @ 587'

1) H₂O pressure acts on 15.5' width of Spilling nose pressure on 242' retaining wall -



Case II Ice Force Calculations

1' thick ice cap at Water Level bearing 5000 psf

$$F_H = 5000 \text{ psf} \cdot 9'$$

$$M_A = 18.5'$$

$$M = 18.5 \times 5000 \text{ k} = 92.5 \text{ Kft}$$

TAMS

Job No. 1579-13

Sheet 12 of 24

Project NYS DE

Date 6-20-81



Subject KLD-SA

By JW

Ch'k. by _____


Case III 1/2 PMF WL @ 593.67

Face of Dam which acts on



Zone A

$F_p = 19.83 \text{ K}$ $F_v = 13.6 \text{ K}$
 $\bar{x} = 7.2'$ $\bar{y} = 11.3'$



Zone B

$F_p = 19.16 \text{ K}$ $F_v = 12.6 \text{ K}$
 $\bar{x} = 6.9'$ $\bar{y} = 11.3'$

TAMS

Job No. 1579-13

Sheet 13 of 24

Project 145 Dam Inspection


Date 6-8-21

Subject Kirk Lake Dam Spouting Structure

By JW

Ch'k. by _____

Cr. III Cont.



Calculate Ave Force / unit width of Non-Monolith Area

Force	$X_{H/C}$	F_H	X_v	F_v	M
A	1.6	19.85	1.6	27.83	200.37
B	7.0	19.16	6.9	134.10	925.29
C	7.1	20.14	7.3	142.99	1043.80
				304.92	2169.46

for 15.5 ft width $\bar{F} = 19.67 \text{ k/ps}$

$\bar{M}_H = \frac{2169.46}{304.92} = 7.11'$

$\bar{F}_H = 19.67 \text{ k/ps}$ $\bar{M}_H = 139.9 \text{ k-ft}$

$\bar{F}_v = 13.6 \text{ k/ps}$ $\bar{M}_v = 153.68 \text{ k-ft}$

TAMS


Job No. 1578-13
 Project 1145 Long Improvement
 Subject Kirk Lake Dam - Topography Computations

Sheet 14 of 24
 Date 8/23/51
 By J. J. [unclear]
 Ch'k. by _____

Case II PMP W.L. @ 515.86

Surface of Dam as Case III

Zone A @ 515.86



$P = 515.86 - 428 = 92.86$

$T = \frac{428 \times 21}{2} = 4494$

$F = 1138 \times 21 = 23900$

$x = 7.6'$

$F = 1138 \times 14.8 = 16842$

$x = 11.37'$

$T = 1738 \times 6 = 10428$

$M = 172.5 \times 6 = 1035$

$T = 14.8 \times 1138 = 16842$

$M = 167.2 \times 1138 = 190200$

TAMS

Job No. 1579-13

Sheet 15 of 24

Project 1943 Fire Department


Date 6-2-31

Subject First Lake Dam - Section 1 of Dam

By JW

Ch'k. by _____

Point B



$$P_1 = (595.86 - 553) \cdot 62.4 = 553$$

$$P_2 = 1738 \text{ as given A}$$


$$P_H = \frac{553 + 1738}{2} \cdot 9 = 21.8 \text{ Kips}$$

$$Q = 1738 \times \frac{1}{2} (62.4)^2 = 10,882 = 0$$

$$R = 7.2$$

$F_H = 21.8 \text{ Kips}$
 $W = 1570 \text{ lbs}$
 $T_H = 14.8 \text{ Kips}$
 $W_H = 167.2 \text{ lbs}$

Point C



$$P_1 = (595.86 - 366) \cdot 62.4 = 366 \text{ lbs}$$

$$P_2 = 366 + 1738 = (22) \cdot 23.14 \text{ lbs}$$

$$P_H = 1738 \times \frac{1}{2} (62.4)^2 = 11572 = 0$$

$$R = 7.7'$$

$F_H = 23.14 \text{ K}$
 $W = 1738 \text{ lbs}$
 $T_H = 14.8 \text{ K}$
 $W_H = 167.2 \text{ lbs}$

TAMS

Job No. 157A-13

Sheet 16 of 24

Project 1975 Dam Inspection

Date 6-8-71

Subject Kink Lake Dam - Stability Analysis

By Jed

Ch'k. by _____

Calculate Ave. Force / unit width & resultant moment

Case	Height	F_H	\bar{x}_H	$F_{1/2}$	M_o
A	1.4'	22.7K	7.6'	31.8K	241.5 K-ft
B	7.0'	21.8K	7.2'	152.6K	1098.7 K-ft
C	7.1'	23.14K	7.7'	164.3K	1235.1 K-ft
				348.7K	2075.8 K-ft

$$\bar{F}_H = \frac{348.7}{15.5} = 22.5 \text{ K}$$

$$\bar{M}_o = \frac{2075.8}{348.7} = 5.95 \text{ K-ft}$$

$$\bar{F}_H = 22.5 \text{ K} \quad \bar{M}_o = 100.1 \text{ K-ft}$$

$$\bar{F}_H = 21.8 \text{ K} \quad \bar{M}_o = 167.2 \text{ K-ft}$$

TAMS

Job No. 1571-13

Sheet 17 of 24

Project M/S Dam Inspection

Date 6-8-91

Subject Kirk Lake Dam

By Jed

Ch'k. by _____

Calculate Y-Y Centroid of mass for location of dynamic mass sources
 Find center of mass \rightarrow in Y-Y direction for spillway section

Section E-B from pg 5

Total Mass 117.20 kips

$$M_{\text{top}} = 4 \times 6 \times 3 \times 165 = 1188$$

From Top

$$0-3' \text{ Mass } (3.5 \times 4 \times 165) - 118 - 118 - 118 = 217 - 354 = -137$$

$$= 7.92$$

$$3-Y' \text{ Mass } ((Y-3) \times 15 \times 4 \times 165) - (4 \times 6 \times (Y-3) \times 165)$$

$$\text{Area to total mass} = \frac{1188}{165} = 7.2$$

$$58.603 = 7.92 + (Y-3)(7.2) - (Y-3)(5.76)$$

$$58.603 = 7.92 + 2.44(Y-3)$$

$$50.683 = 2.44(Y-3)$$

$$Y-3 = 20.77$$

$$X = 11.53' \text{ from top of spill}$$

Section C-C

Width 6 Total mass = 165 kips find width of spill

From top

$$0-3' \text{ Mass } (2.15 \times 3.1 \times 165) - 118 - 118 = 23.02 - 236 = -212.98$$

$$= 15.34$$

$$3-Y \text{ YR } 16 \text{ Mass } (Y-3)(15)(3.1) \times 165$$

$$\frac{1}{2} \text{ Total Mass} = 82.5 \text{ find Centroid}$$

$$82.5 = 15.34 + (Y-3) 7.67$$

$$67.16 = (Y-3) 7.67$$

$$8.75 = Y-3$$

$$Y = 11.83' \text{ from top}$$

TAMS

Job No. 1579-13

Sheet 18 of 24

Project Mt. Park Engineering

Date 6-8-81

Subject Kirk Lake Dam

By Jed

Ch'k. by _____

Find Centroid of Remaining Mass as per pg. 7
Total mass is 754.155

$$M_{mass} \bar{y} > 5.3 = [15 \times 2(6.7) \times 1.65] (Y) - 103.257 -$$


$$Prof \frac{1}{2} \text{ mass} = 377.077 = 33.165Y - 103.257$$

$$480.334 = 33.165Y$$

$Y = 14.48'$ from top of wall

Recall mass center for finding point from wall
Masses are by sum of mass center from wall

Area	M _c
117.206	22-11.53 = 10.47'
169.2	22-11.53 = 10.47'
754.155	24.3-14.48 = 9.82



$$\sum M_o = 7405.8 + 1699.2 + 10.47$$

$$= 10,323.2 \text{ kft}$$

$$\text{Total Mass} = 1037.5 \text{ k}$$

$$\frac{\sum M_o}{T.M.} = \frac{10,323.2 \text{ kft}}{1037.5 \text{ k}} = 9.95'$$

Location of Y-Y Center is 9.95' above base at
midpoint of wall.

TAMS

Job No. 1579-13

Sheet 19 of 24

Project 145 Bin Expansion

Date 6-2-51

Subject Kick Lake Dam - Stability Analysis

By gwd

Ch'k. by _____

CASE V, Normal Loading Plus Earthquake
 Zone 2 \Rightarrow 0.05 g

1) HYDRODYNAMIC LOAD - 3' of FREEWATER

Zangiacchi Method

for Vertical wall $\theta = 0$ $C = 0.73$

$$P = 0.73 \times 0.05 \times 0.0624 \times 3.0 = .0068$$

$$P_T = \frac{1}{2} (.0068) 3 = .010 \text{ kips}$$

$$M = .010 \times .4 \times 3 = .012 \text{ k-ft}$$

2) Dynamic Load

Soil mass

$$W_s = 125 \left(\frac{1}{2}\right) (17')^2 (1.75) (0.05) = .677 \text{ Ksf}$$

Apply at $\frac{2}{3}$ wall Ht
 per case
 (See Whitman 1970)

$$M = .677 \times 17 \times \frac{2}{3} = 7.68 \text{ k-ft}$$

Massive (vertical)

inertia force $\Sigma F = 50.6 \text{ kips}$

for 0.05 g resultant dynamic force

in inertia $50.6 \times 0.05 = 2.53 \text{ kips}$

$M = 9.95'$ $M = 25.17 \text{ k-ft}$

$$\Sigma F_c = 3.20 \text{ kips}$$

$$\Sigma M = 32.85 \text{ k-ft}$$

TAMS

Job No. 1579-03

Sheet 20 of 24

Project NY 5th Ave. Temporary

Date 3-17-51

Subject Kick Out Line - Sliding Analysis

By [Signature]

Ch'k. by _____

Analysis

CASE I Normal Loading

	F_v	F_H	M_x	M_y
DEAD LOAD	50.6	—	449.3 kft	—
Side Skirt	—	-7.21	59.2	—
Hydrostatic Load	-11.3	11.26k	—	185.2 kft
EARTH FORCES	—	5.1k	—	33.0 kft
	37.3	9.05	508.5	218.2

$$\Sigma M = 508.5 - 218.2 = 290.3 \text{ kft}$$

$$e = \frac{M}{P} = \frac{290.3}{37.3} = 7.78'$$

is $\frac{17}{6} = 2.83 > 2.0$ (1.72 sec) *Reaction within reach*
 $Y_3 = \text{OK}$

Sliding Stability required $f = 1.0$ assume $C \& D = 20\%$

$$F.S. = \frac{F_v + C/M}{F_H}$$

$$F.S. = \frac{37.3 + 0.2(185.2)}{9.05} = 3.41 \quad \text{OK}$$

TAMS

Job No. 1579-13
 Project 1115 Univ. of Michigan
 Subject Klein Salt Pond - Snowdrift

Sheet 21 of 24
 Date 6-10-81
 By JFD
 Ch'k. by _____

Case II ICE loading of Normal winter load

	<u>I_L</u>	<u>E_u</u>	<u>A_L</u>	<u>A_u</u>
DEAD LOAD	58.6		449.3	—
SIDE SHEET	—	-731	57.2	—
HYDROSTATIC LOAD	-11.3	1126	—	185.2
ICE LOAD	—	5.0	—	92.5
EMBEDMENT	—	5.1	—	33.0
	<u>39.3</u>	<u>14.5</u>	<u>508.5</u>	<u>310.7</u>

$$S_{LH} = 508.5 - 310.7 = 197.8 \text{ kft}$$

$$e = \frac{L}{2} - \frac{197.8}{39.3} = 3.16'$$

$$10 \frac{L}{6} - 3.16 \geq 0 \quad (-63) \text{ in} \quad \text{Deck height over beam is } 43$$

sliding stability $\phi = 35^\circ$ $c = 200 \text{ psf}$ $\mu = 0.30$

$$F.S. = \frac{39.3 + 200 - 17(0)}{14.5} = \underline{2.20}$$

At this time the shear stress is
 sliding and the magnitude
 stress acceptable criteria

TAMS

Job No. 1579-13 Sheet 22 of 24
 Project NYS Dam Inspection Date 6-22-31
 Subject Kirk Lake Dam - Secondary Analysis By J. E. J.
 Ch'k. by _____

Case III 1/2 PMF - NO ICE.

	<u>F_v</u>	<u>F_u</u>	<u>M_v</u>	<u>M_u</u>
Dead Load	20.6		449.3	
Side Sluic.	—	-7.31	37.2	
Hydrostatic Load	-12.6	19.67	—	293.58
Earth Loads	—	5.10	—	32.0
	<u>37.0</u>	<u>17.46</u>	<u>508.5</u>	<u>326.58</u>

$$\Sigma M = 508.5 - 326.58 = 181.92 \text{ kft}$$

$$\bar{e} = \frac{17}{2} - \frac{181.92}{37.0} = 3.58'$$

$15 \cdot \frac{17}{6} \cdot 3.58 = 14.749$ NO NOT ACCEPTABLE - TOO HEAVY
 NOT A SLICE - TAKE 1/3 OF THIS

Sliding Stability assumed $\phi = 33$ $c = 200 \text{ psf}$

$$F.S. = \frac{37.0 (\tan 33^\circ) + 17(3)}{17.46} = 1.68 < 3$$

Does not meet criteria

TAMS

Job No. 1577-13

Sheet 23 of 24

Project 1945 Dam Completion

Date 1-20-51

Subject Kuck Lake Dam - secondary drainage

By [Signature]

Ch'k. by _____

Case IV PMF

	<u>F_u</u>	<u>F_d</u>	<u>U_u</u>	<u>U_d</u>
Dam Load	58.6	—	449.3	—
Stem Shear	—	-7.31	57.2	—
Hydrostatic Load	-14.8	22.50	—	336.3
Earthquake	—	5.10	—	33.0
	<u>35.8</u>	<u>20.29</u>	<u>508.5</u>	<u>366.3</u>

$$\Sigma H = 508.5 - 366.3 = 140.2 \text{ kft}$$

$$z = \frac{17}{2} - \frac{140.2}{35.8} = 4.58$$

$$15 \frac{17}{6} - 4.58 \geq 0 \quad (-1.75 \text{ no})$$

no. 15 ft above top of pile
middle 1/3 of pile is in soil
2 ft above water level

Sliding Safety

$\phi = 35^\circ$ $C = 200 \text{ psf}$ at base

$$F.S. = \frac{366.3 + 200 \times 17}{20.29} = 140.43$$

Does not meet criteria

Case V - Dynamic Loading

	<u>F_u</u>	<u>F_d</u>	<u>U_u</u>	<u>U_d</u>
Dam Load	58.6	—	449.3	—
Stem Shear	—	-7.31	57.2	—
Hydrostatic Load	-11.3	11.26	—	155.2
Dynamic Load	—	5.10	—	33.0
Hydrodynamic Load	—	3.20	—	32.85
	<u>39.3</u>	<u>12.26</u>	<u>508.5</u>	<u>251.05</u>

$$\Sigma H = 508.5 - 251.05 = 257.44$$

$$z = \frac{17}{2} - \frac{257.44}{39.3} = 1.95$$

$$15 \frac{17}{4} - 1.95 \geq 0 \quad (2.30 \text{ ok})$$

Sliding Safety

$$F.S. = \frac{251.05 + 200 \times 17}{12.26} = 288.5$$

AD-A107 408


TIPPETT-ABBETT-MCCARTHY-STRATTON NEW YORK F/G 13/13
NATIONAL DAM SAFETY PROGRAM. KIRK LAKE DAM (INVENTORY NUMBER N.--ETC(U)
AUG 81 E O'BRIEN DACW51-81-C-0008
NL .

UNCLASSIFIED

2
A
740



END
DATE
FILMED
12-81
DTIC



MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A

TAMS

Job No. 1579-13

Sheet 24 of 24

Project 1145 Dam Improvement

Date 6-10-81

Subject Kirk Lake Dam - Sealing Damages

By JFW

Ch'k. by _____

SUMMARY

<u>Case</u>	<u>Resultant Losses</u>		<u>Stability</u>	
	<u>E</u>	<u>Acceptable</u>	<u>Sliding F.S.</u>	<u>Acceptable</u>
<u>I</u>	1.11'	yes	3.41 > 3	yes
<u>II</u>	3.46'	no	2.20 < 3	no
<u>III</u>	3.58'	no	1.68 < 3	no
<u>IV</u>	4.58'	no	1.40 < 3	no
<u>V</u>	2.30'	yes	2.52 > 1.5	yes

REFERENCES

APPENDIX F

REFERENCES

1. "Flood Hydrograph Package (HEC-1) Users Manual for Dam Safety Investigations", U. S. Army Corps of Engineers, Hydrologic Engineering Center, September 1979.
2. "Seasonal Variation of the Probable Maximum Precipitation, East of the 105th Meridian for Areas from 10 to 1,000 Square Miles, and Durations of 6, 12, 24 and 48 Hours", Hydrometeorological Report No. 33. Weather Bureau, U.S. Department of Commerce, April 1956.
3. "Recommended Guidelines for Safety Inspection of Dams", Department of the Army, Office of the Chief of Engineers, Appendix B.
4. The University of the State of New York, The State Education Department State Museum and Science Service Geological Survey - MAP and Chart Series No. 5, Geologic MAP of New York 1961, Lower Hudson Sheet.

OTHER DATA

APPENDIX G

NYC-1, FORM W. 6-21 M
RECEIVED
FEB 28 1925
R. G. McKeen
ASST.

THE CITY OF NEW YORK
DEPARTMENT OF
WATER SUPPLY, GAS AND ELECTRICITY

BUREAU OF WATER SUPPLY
MUNICIPAL BUILDING
NEW YORK

Structures impounding
water

February 28, 1925.

Mr. Roy G. Finch,
State Engineer,
Albany, New York.

Dear Sir:

Your favor of the 19th inst. acknowledging receipt of our letter of February 13, 1925 with accompanying reports on fourteen dams in the Croton watershed, to hand.

I am transmitting herewith reports on six distributing reservoirs (Croton and Long Island supplies) within the limits of the City of New York, one distributing reservoir (Hill View Catskill supply) just north of the city limits and one storage reservoir (Hempstead) on Long Island.

Your assumption that the Muscoot dam (your number 406) is just below the point where the Muscoot river originally flowed into the Croton River, is correct.

451 LX

I note your reference to the dam on the headwaters of the Muscoot river one mile from the village of Mahopac and 1/4 mile above the NYC RR bridge. This dam is undoubtedly the one at the outlet of Kirk Lake and is located one half mile above the village of Mahopac Falls. It is owned by the City of New York and was originally constructed in 1870-71; it was reconstructed in 1881. Length of dam 160 feet; 36" inlet pipe 19 feet below High water. There are no plans of this dam in existence so far as we have know.

Very truly yours,

Chief Engineer

Enc. 8 reports

- 55 L.H. New General Post Office
- 102 " High Bridge
- 135 " ...
- 136 " ...
- 160 " ...

H 7 187

1181 18 N
NEW YORK PRESS
BEST
NEW YORK CITY
118 WEST 40th STREET
TELEPHONE CO.

CARMEL, N. Y., COURIER (662)

Friday, January 26, 1917.

so last the 1885
to Temperance, in whose interest he was
working had transferred a number
of their men, to the eastern states.

A LEAK IN KIRK-LAKE DAM

A small leak was discovered in the dam at Kirk Lake on last Friday evening which required about three hours work to repair it. It was fortunate that the leak was discovered in time or perhaps the dam might have given away causing much trouble.

THIRD ANNUAL RECEPTION

The third annual reception and ball

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION
DAM INSPECTION REPORT
(By Visual Inspection)

Dam Number	River Basin	Town	County	Hazard Class*	Date & Inspector
781	L. Hudson	Conner	Peter	B-C	12/22/76 KAH

- | Type of Construction | Use |
|---|--|
| <input type="checkbox"/> Earth w/concrete spillway | <input type="checkbox"/> Water Supply |
| <input type="checkbox"/> Earth w/drop inlet pipe | <input type="checkbox"/> Power |
| <input checked="" type="checkbox"/> Earth w/stone or pipe spillway | <input checked="" type="checkbox"/> Recreation |
| <input type="checkbox"/> Concrete | <input type="checkbox"/> Fish and Wildlife |
| <input type="checkbox"/> Stone | <input type="checkbox"/> Farm Pond |
| <input type="checkbox"/> Timber | <input type="checkbox"/> No Apparent Use-Abandoned |


- | Estimated Impoundment Size | Estimated Height of Dam above Streambed |
|---|--|
| <input type="checkbox"/> 1-5 acres | <input type="checkbox"/> Under 10 feet |
| <input type="checkbox"/> 5-10 acres | <input type="checkbox"/> 10-25 feet |
| <input checked="" type="checkbox"/> Over 10 acres 120 (+) ac.
565 MG | <input checked="" type="checkbox"/> Over 25 feet 30' |

- Condition of Spillway
- | | |
|---|---|
| <input checked="" type="checkbox"/> Service satisfactory | <input type="checkbox"/> Auxiliary satisfactory |
| <input type="checkbox"/> In need of repair or maintenance | <input type="checkbox"/> In need of repair or maintenance |
- Explain: _____

- Condition of Non-Overflow Section
- | | |
|---|----------------|
| <input checked="" type="checkbox"/> Satisfactory | |
| <input type="checkbox"/> In need of repair or maintenance | Explain: _____ |

- Condition of Mechanical Equipment
- | | |
|---|----------------|
| <input checked="" type="checkbox"/> Satisfactory | |
| <input type="checkbox"/> In need of repair or maintenance | Explain: _____ |

- Evaluation (From Visual Inspection)
- | |
|---|
| <input checked="" type="checkbox"/> No defects observed beyond normal maintenance |
| <input type="checkbox"/> Repairs required beyond normal maintenance |
- *Explain Hazard Class, if Necessary _____



(NOTICE: After filling out one of these forms as completely as possible for each dam in your district, return it at once to the Conservation Commission, Albany.)

STATE OF NEW YORK
CONSERVATION COMMISSION
ALBANY

DAM REPORT

July 27th, 1915
(Date)

CONSERVATION COMMISSION,

DIVISION OF INLAND WATERS.

GENTLEMEN:

I have the honor to make the following report in relation to the structure known as the Kirk Lake Dam.

This dam is situated upon the Headwaters of Muscat River in the Town of Cornel, Putnam County,

about 1 mile from the Village ~~near~~ of Lake Mahopac.

The distance down stream from the dam, to the N.Y. Central R.R. Bridge, is about 1/4 mile.

The dam is now owned by New York City and was built in or about the year 1872, and was extensively repaired or reconstructed during the year _____.

As it now stands, the spillway portion of this dam is built of Cut Stone and the other portions are built of Cut Stone Earth fill.

As nearly as I can learn, the character of the foundation ~~bed~~ under the spillway portion of the dam is Rock and under the remaining portions such foundation bed is Rock & Gravel.

213-C₂F

The total length of this dam is 150 feet. The spillway or waste-weir portion, is about 20 feet long, and the crest of the spillway is about 4 feet below the top of the dam.

The number, size and location of discharge pipes, waste pipes or gates which may be used for drawing off the water from behind the dam, are as follows: One 36"

discharge pipe directly under spillway
State briefly, in the space below, whether, in your judgment, this dam is in good condition, or bad condition, describing particularly any leaks or cracks which you may have observed.)

This dam is in excellent condition and should it go out the water would pretty nearly take care of itself without serious damage to surrounding property because there seems to be scarcely any buildings in its valley and a special artificial sluiceway through the gulch has been built.



Reported by L. D. Seymour
(Signature)


(Address - Street and number, P. O. Box or R. F. D. route)

Walcott, N. Y.
(Name of place)


(SEE OTHER SIDE)

(In the space below, make one sketch showing the form and dimensions of a cross section through the spillway or waste-weir of this dam, and a second sketch showing the same information for a cross section through the other portion of the dam. Show particularly the greatest height of the dam above the stream bed, its thickness at the top, and thickness at the bottom, as nearly as you can learn.)


SPILLWAY SECTION



OTHER SECTION



(In the space below, make a third sketch showing the general plan of the dam, and its approximate position in relation to buildings or other conspicuous objects in the vicinity.)



END

DATE
FILMED

12-81

DTIC