


AD-A108 252


TENNESSEE STATE DEPT OF CONSERVATION NASHVILLE DIV 0--ETC F/G 13/13  
NATIONAL PROGRAM OF INSPECTION OF NON-FEDERAL DAMS, TENNESSEE. --ETC(U)  
SEP 81 P F BLUMM DACW62-81-C-0056

UNCLASSIFIED

NL

1 2





MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS 1963 A.

LEVEL II

②  
y.w.

AD A108252

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO. AD-A208252	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) National Program of Inspection of Non-Federal Dams, Tennessee. Lambert Dam (Inventory Number TN 00901) near Six Mile, Tennessee, Blount County, TN., Little Tennessee River Basin		5. TYPE OF REPORT & PERIOD COVERED Phase 1 Investigation Report
7. AUTHOR(s)		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS Tennessee Department of Conservation Division of Water Resources 4721 Trousdale Dr., Nashville, TN. 37220		8. CONTRACT OR GRANT NUMBER(s) DACW-62-81-C-0056
11. CONTROLLING OFFICE NAME AND ADDRESS U.S. Army Engineer District, Nashville P.O. Box 1070 Nashville, TN 37202		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		12. REPORT DATE September, 1981
		13. NUMBER OF PAGES
		15. SECURITY CLASS. (of this report) Unclassified
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report)  Approved for public release; distribution unlimited		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number)		
Dams Dam Safety National Dam Safety Program Lambert Dam, TN		Six Mile, TN Blount County, TN. Embankments Visual Inspection Structural Analysis
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) Lambert Dam is a linear earthfill structure 605 feet long and 53 feet high with a crest width of 18 feet. The upstream and downstream slopes are 1V on 3.8H and 1V on 3.4H respectively. It has a capacity of 336 acre-feet at normal pool and 454 acre-feet at the top of the dam. The principal spillway consists of a 2.5 feet by 7.5 feet (ID) reinforced concrete riser which feeds a 30 inch diameter outlet pipe. Drawdown of the reservoir is controlled by a 24 inch square sliding headgate. The emergency spillway is an uncontrolled saddle type located just upstream of the right abutment. It runs parallel to the crest and		

DD FORM 1 JAN 73 1473 EDITION OF 1 NOV 65 IS OBSOLETE

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

112670

is 117 feet in width. The embankment is well grassed and has no undesirable vegetation except for some 2 to 4 inch diameter pine trees located at the toe and left abutment tie in. No signs of sliding, cracking, differential settlement or erosion were observed on the dam or in the area immediately downstream. The dam is in the intermediate size and high potential category and should pass the Probable Maximum Flood (PMF). A hydraulic and hydrologic analysis reveals that during the PMF the dam will overtop by 1.3 feet for 4.75 hours. During the 1/2 PMF, the dam overtops by .65 feet for three hours. The embankment appears to be structurally stable; however, it is considered "significantly deficient" because the spillway is inadequate. It is recommended that a qualified engineer be engaged to develop project modifications that will allow the dam to pass the PMF and that the owner perform routine maintenance operations.

Accession For	
NTIS GPA&I	<input checked="" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By	
Distribution/	
Availability Codes	
Dist	Avail and/or Special
A	



DEPARTMENT OF THE ARMY  
NASHVILLE DISTRICT, CORPS OF ENGINEERS  
P. O. BOX 1070  
NASHVILLE, TENNESSEE 37202

IN REPLY REFER TO

21 SEP 1981

ORNED-G

Honorable Lamar Alexander  
Governor of Tennessee  
Nashville, TN 37219

Dear Governor Alexander:

Furnished herewith is the Phase I Investigation Report on Lambert Dam near Sixmile, Tennessee. The report was prepared under the authority and provisions of PL 92-367, the National Dam Inspection Act, dated 8 August 1972.

The report presents details of the field inspection, background information, technical analyses, findings, and recommendations for improving the condition of the dam.

Based upon the inspection and subsequent evaluation, Lambert Dam is classified as significantly deficient due to insufficient storage and spillway capacity to pass the probable maximum flood.

We do not consider this an emergency situation at this time, but the recommendation concerning project modifications to allow safe passage of the design flood and others contained in this report should be undertaken in the near future.

Public release of the report and initiation of public statements fall within your prerogative. However, under provisions of the Freedom of Information Act, the Corps of Engineers is required to respond fully to inquiries on information contained in the report and to make it accessible for review on request.

Your assistance in keeping me informed of any further developments will be appreciated.

Sincerely,

*Kenneth W. Ashley, LTC*  
for LEE W. TUCKER  
Colonel, Corps of Engineers  
Commander

1 Incl  
As stated

CF:  
Mr. Robert A. Hunt, Director  
Division of Water Resources  
4721 Trousdale Drive  
Nashville, TN 37220

PHASE I REPORT  
NATIONAL DAM SAFETY PROGRAM  
TENNESSEE

Names of Dam ..... Lambert Dam  
County ..... Blount  
Stream ..... Tributary of Big  
Spring Branch  
Date of Inspection ..... April 21, 1981

This investigation and evaluation was prepared by the Engineering Division of  
the Nashville District of the Corps of Engineers.

PREPARED BY:

*Paul F. Blum*  
\_\_\_\_\_  
PAUL F. BLUM  
Civil Engineer

APPROVED BY:

*Tim McCleskey*  
\_\_\_\_\_  
TIM McCLESKEY  
Chief I&I Section

## TABLE OF CONTENTS

	<u>Page</u>
<b>Abstract</b>	i
<b>Overview Photograph</b>	ii
<b>SECTION 1 - GENERAL</b>	
1.1 Authority .....	1
1.2 Purpose and Scope .....	1
1.3 Past Inspection .....	1
1.4 Details of Inspection .....	2
<b>SECTION 2 - PROJECT DESCRIPTION</b>	
2.1 Location .....	2
2.2 History of Project .....	2
2.3 Size and Hazard Classification .....	3
2.4 Description of Dam and Appurtenances .....	3
<b>SECTION 3 - FINDINGS</b>	
3.1 Visual Findings .....	4
3.2 Review of Data .....	5
3.3 Static and Seismic Stability .....	5
3.4 Hydraulic and Hydrologic Analysis.....	5
3.5 Conclusions and Recommendations .....	6
<b>SECTION 4 - REVIEW BOARD FINDINGS.....</b>	<b>8</b>
 <b>APPENDICES</b>	
A. Data Summary	
B. Sketches and Location Maps	
C. Photographic Record	
D. Technical Critiques	
E. Design Drawings	
F. Hydraulic and Hydrologic Analysis	
G. Correspondence	
H. Previous Investigations	



PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM  
TENNESSEE

Name of Dam: Lambert Dam  
County: Blount  
Stream: Tributary of Big Spring Branch  
Date of Inspection: April 21, 1981

ABSTRACT

Lambert Dam is a linear earthfill structure 605 feet long and 53 feet high with a crest width of 18 feet. The upstream and downstream slopes are IV on 3.8H and IV on 3.4H respectively. It has a capacity of 336 acre-feet at normal pool and 454 acre-feet at the top of the dam.

The principal spillway consists of a 2.5 feet by 7.5 feet (ID) reinforced concrete riser which feeds a 30 inch diameter outlet pipe. Drawdown of the reservoir is controlled by a 24 inch square sliding headgate. The emergency spillway is an uncontrolled saddle type located just upstream of the right abutment. It runs parallel to the crest and is 117 feet in width. The embankment is well grassed and has no undesirable vegetation except for some 2 to 4 inch diameter pine trees located at the toe and left abutment tie in.

No signs of sliding, cracking, differential settlement or erosion were observed on the dam or in the area immediately downstream.

The dam is in the intermediate size and high potential category and should pass the Probable Maximum Flood (PMF). A hydraulic and hydrologic analysis reveals that during the PMF the dam will overtop by 1.3 feet for 4.75 hours. During the 1/2 PMF, the dam overtops by .65 feet for three hours.

The embankment appears to be structurally stable; however, it is considered "significantly deficient" because the spillway is inadequate. It is recommended that a qualified engineer be engaged to develop project modifications that will allow the dam to pass the PMF and that the owner perform routine maintenance operations.



OVERVIEW  
LAMBERT DAM

## SECTION 1 - GENERAL

- 1.1 Authority: The Phase I inspection of this dam was conducted under the authority of Tennessee Code Annotated, Section 70-2501 to 70-2530, "The Safe Dams Act of 1973", in cooperation with the US Army Corps of Engineers under the authority of Public Law 92-367, "The National Dam Inspection Act".
- 1.2 Purpose and Scope: This report is prepared under guidance contained in the Department of the Army, Office of the Chief of Engineers, "Recommended Guidelines for Safety Inspection of Dams", for a Phase I investigation. The purpose of the Phase I investigation is to identify expeditiously those dams which may pose hazard to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed analyses involving topographic mapping, subsurface investigation, testing, and detailed computational evaluations are beyond the scope of Phase I investigations. However, the investigation is intended to identify the need for any such study.

In the review of this report, it should be realized that the reported conditions of the dam are based on observations of field conditions at the time of inspection along with data available to the inspection team. Additional data or data furnished containing incorrect information could alter the findings of this report.

The analyses and the recommendations included in this report are related to the hazard classifications of the structure at the time of this report. Changes in conditions downstream of the dam may change the hazard classification of the structure. A change in hazard classification may in turn change the design flood on which the hydraulic and hydrologic analyses are based and may have a significant impact on assessment of the safety of the structure.

It is important to note that the condition of the dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions will be detected.

- 1.3 Past Inspections: Following the failure of the dam on October 12, 1963, the dam was inspected on October 17, 1963 by William P. Clark of the Tennessee Valley Authority. A written report and photos of this failure are on file with TVA. A summary of the report indicated that failure may have been due to the collapse of a 6-inch pipe that

existed through the dam. See Appendix H for a copy of this report. An inventory inspection was also conducted on 8 September 1980 by the Tennessee Department of Conservation, Division of Water Resources.

- 1.4 Details of Inspection: The Phase I inspection was conducted on April 21, 1981 by the US Army Corps of Engineers. It was surveyed by the Tennessee Department of Conservation, Division of Water Resources on the same date. The weather was clear and warm (72°). The reservoir was at normal pool, elevation 1059.0.

Inspection team members were:

Paul F. Bluhm	-	Civil Engineer Nashville District US Army Corps of Engineers
Timothy McCleskey	-	Civil Engineer Nashville District US Army Corps of Engineers
Tom Porter	-	Hydraulic Engineer Nashville District US Army Corps of Engineers
Troy Wedekind	-	Water Resources Engineer Tennessee Department of Conservation Division of Water Resources

## SECTION 2 - PROJECT DESCRIPTION

- 2.1 Location: Lambert Dam is located about seven miles south of Maryville, Tennessee, and approximately one-half mile due east of the intersection of Montvale Road and Old Piney Road. It impounds a tributary of Big Spring Branch which is in turn a tributary of Sixmile Creek. The dam is shown on the US Geological Survey 7.5 minute Blockhouse Quadrangle Map at latitude 35° 39' 30"N and longitude 83° 57' 12"W. Location maps are provided in Appendix B of this report.
- 2.2 History of the Project: Design of the dam was by the Soil Conservation Service of Blount County and it was constructed in 1957 to impound a 17 acre lake for use as a farm pond. On October 12, 1963 a small leak occurred, presumably near a 6-inch pipe that existed through the dam. The size of the leak increased until the embankment caved in failing the dam. Although exact cause of failure was not determined it is thought to be due to failure of the 6-inch pipe which led to piping of the embankment material and a breach of the dam. Damage to the downstream area was limited to flooding of a church and slight damage to Montvale Road. The SCS redesigned the dam and it was reconstructed in 1964 by Blount Brothers Construction

Company. During the reconstruction, soil borings were taken from the borrow area and from the spillway foundation area by the SCS. The dam is now slightly larger and impounds a 20 acre lake. The dam was owned by J. B. Lambert when it failed in 1963, but is now owned by Keith McCord.

2.3 Size and Hazard Classification: According to CCE guidelines, the dam is in the intermediate size category with a height of 53 feet and a storage capacity of 336 acre-feet at normal pool level and approximately 454 acre-feet at the top of the dam. The structure is classified in the high hazard potential category because a house, small grocery store and county road located one-half mile downstream would be in the probable flood path should a sudden failure occur.

2.4 Description of Dam and Appurtenances:

2.4.1 Embankment: The embankment is a linear aligned earthfill structure presumably constructed of material (ML, CL and SC) excavated from the reservoir area. The dam has a maximum structural height of 53 feet. The crest is 605 feet in length, 18 feet wide, and varies in elevation from 1064.5 feet to 1067.4 feet. The upstream and downstream slopes are uniform and are inclined at IV on 3.8H and IV on 3.4H respectively. A small wave berm, 18 feet in width, and inclined at IV on 8H is located along the upstream face, 1.5 to 2.5 feet above the water surface.

The dam is underlain by Paleozoic Age rocks, mainly Cambrian and Lower Ordovician. The overburden at the dam site is composed of colluvial and local alluvial deposits of silty and sandy loam (ML, CL and SC) which were derived from sandstone, quartzite, slate and shale.

2.4.2 Emergency Spillway: The emergency spillway is a 117 foot wide saddle spillway located just upstream of the right abutment. The centerline of the spillway is parallel to the axis of the dam and exits to a broad, open meadow just upstream of the right abutment. The left side slope (toward the dam) is IV on 9.9H while the right side slope is IV on 7.6H. Although the entrance channel is steep (28.2%) the exit channel is fairly flat and uniform ranging from a beginning slope of .1% to a 6% slope 200 feet from the reservoir. The spillway ends in a large ravine 400 to 500 feet from the reservoir. A paved access road crosses the spillway at approximately 30 feet from the reservoir.

2.4.3 Service Spillway: The service spillway is a 2.5 feet by 7.5 feet reinforced concrete riser, 36 feet high and maintains a normal pool at elevation 1059.0. It is covered by a solid metal platform and has trash racks covering two sides of the structure. A grated metal walkway provides access to the structure.

The riser feeds a 30 inch diameter, reinforced concrete pipe, 336 feet long. The plans show 11 anti-seep collars along the length of the discharge pipe.

- 2.4.4 Drawdown Facilities: The drawdown facility consists of an 18 inch diameter pipe controlled by a 24 inch square slide gate. The gate is manually operated from the top of the riser.
- 2.4.5 Downstream Channel: The 30 inch diameter reinforced concrete pipe empties into a 25 foot diameter stilling basin. The channel exiting from the stilling basin is about 3 to 4 feet wide and widens to 5 to 6 feet after passing under a culvert 200 feet from the stilling basin. The channel then joins a larger stream and flows into a flat pasture before passing under Montvale Road one-half mile downstream from the dam.
- 2.4.6 Reservoir and Drainage Area: At normal pool level, elevation 1059.0, the reservoir impounds about 336 acre-feet of water and has a surface area of about 20 acres. At the top of the dam the reservoir volume is about 450 acre-feet. The size of the drainage area is 0.73 square miles. Major soil types in the watershed include Ramsey, Jefferson, and Montevallo series. The majority of the watershed is woods.

### SECTION 3 - FINDINGS

#### 3.1 Visual Findings:

3.1.1 Embankment: The upstream slope has a good, but short grass cover. Wave action has been eroding the wave berm somewhat but it does not appear to be serious at this time. The crest is straight and uniform and is covered with a thin layer of gravel. It is in good condition with the exception of some ruts made by vehicle traffic. The downstream slope also has a good but short grass cover. Apparently, the owner allows cattle to graze on the dam which keeps the grass short but also produces tracks and ruts. Because of these ruts parts of the downstream slope near the crest had to be reseeded. The dam was free of undesirable growth with the exception of a few 2 to 4 inch diameter pine trees which were located at the contact of the left abutment and the embankment and just past the toe of the dam. Two 5 inch diameter pine trees were also located on the embankment, about 20 feet from the end of the outlet pipe.

Two apparent wet areas were observed on the embankment. One was located on the left side at the toe of the dam and was about 20 feet in length and 3 feet wide. The other was at about station 0+50R, about two-thirds the way down the embankment. It was about 30 feet long and 10 feet in width. Because of the recent rains, it could not be ascertained if the areas were wet due to seepage through the embankment or residual moisture from the rain. Two eight inch diameter toe

drains, located near the outlet structure were visible. Both were half filled with silt and had a slight trickle of water flowing from them.

3.1.2 Service Spillway: The service spillway is in good condition with the exception of some leaks in the construction joints of the riser. The worst leak was at the first construction joint (from the bottom) and according to the caretaker was keeping the lake below normal pool. The 30 inch diameter reinforced concrete pipe was in good condition and showed no signs of spalling or deterioration. The drawdown gate was not operated during the inspection but was reported to be in good condition. The stilling basin was in good condition with no signs of erosion or undercutting.

3.1.3 Downstream Channel: The downstream channel is relatively flat for the first few hundred feet and is well grassed with some trees and brush lining the banks. The channel then deepens (10 to 12 feet in depth) with heavy brush lining the steep banks. It then joins another stream which traverses through a well grassed pasture.

3.1.4 Reservoir and Drainage Area: The drainage area is steep and heavily wooded although part of the area bordering the lake is well grassed. There was no indication of any significant sedimentation.

- 3.2 Review of Data: Information available for review included a set of drawings that was prepared by the Soil Conservation Service for the repair of the dam following its failure. The plans called for the remedial work to key into the existing embankment. In addition, the plans also called for a toe drain which was evident by the 8-inch diameter pipes near the outlet structure.
- 3.3 Static and Seismic Stability - The actual margin of safety for static stability cannot be determined because the engineering data required for an analytical stability analysis are not available. However, an assessment of the embankment stability based on visual evidence and engineering judgment would indicate a stable structure due to moderate embankment slopes and the lack of leaks or seepage. The project is located in Seismic Zone 2, and according to OCE guidelines, should not be expected to be threatened by seismic effects provided static conditions are satisfied.
- 3.4 Hydraulic and Hydrologic Analysis - According to OCE guidelines, the design flood for an intermediate size dam in a high hazard area is the Probable Maximum Flood (PMF). Hydraulic analysis indicates that outflow resulting from the PMF (AMC II) will over top the dam by a maximum depth of 1.3' for a duration of 4.75 hours. Additional analysis indicates that outflow from the  $1/2$  PMF will overtop the dam by a maximum depth of .65' for 3.0 hours.

### 3.5 Conclusions and Recommendations:

#### 3.5.1 Conclusions:

- a. On the basis of visual evidence and engineering judgement, the dam is considered to be structurally stable. The embankment slopes are moderate and are considered adequate. The two wet areas found are not considered serious. The project has the appearance that it is well constructed.
- b. The leaks in the construction joints of the principal spillway do not pose a serious problem.
- c. Small pine trees are present only at the embankment-abutment contact, toe of the dam and above the spillway outlet.
- d. The dam is located in Seismic Zone 2, indicating that risk of damage from seismic activity is only moderate.
- e. Hydraulic analysis indicates that the spillway will not pass the Probable Maximum Flood as required by OCE guidelines for dams of intermediate size and high hazard potential. Under the  $\frac{1}{2}$  PMF, the dam is overtopped by .65 feet for 3 hours. Failure would probably not occur during the  $\frac{1}{2}$  PMF.
- f. The dam is considered "significantly deficient" solely because the spillway will not pass the appropriate design flood.

#### 3.5.2 Recommendations:

- a. The owner should engage the services of a qualified engineer to:
  1. Develop project modifications to allow safe passage of the PMF.
  2. Evaluate the leaks in the service spillway and make appropriate recommendations.
  3. Direct the removal of pine trees and repair of embankment following their removal.
- b. The toe drains should be cleaned out so they can function properly. They should be checked periodically for any deposition of additional material. A qualified engineer should be engaged to determine the cause of any further deposition.



- c. The owner should not allow cattle to overgraze the embankment. Controlled grazing should be practiced to minimize damage to the embankment.
- d. The two small wet areas on the embankment should be reinspected during a dry period to determine if they were a result of rainfall or actual seepage. A qualified engineer should be engaged to determine the cause of the wet areas if they are still present during a dry period.
- e. The progression of the erosion of the wave berm shall be periodically checked. A qualified engineer should be engaged if the erosion becomes severe.
- f. The drawdown gate on the service spillway should be operated at least twice a year.
- g. An emergency action plan should be developed, including a warning system to alert downstream residents, in the event a serious condition develops with the dam.
- h. The owner should establish a regular program of inspection and maintenance to provide detection and timely correction of problem areas.

#### SECTION 4 REVIEW BOARD FINDINGS

The Interagency Review Board for the National Program of Inspection of Non-Federal Dams met in Nashville on 27 August 1981 to examine the technical data contained in the Phase I investigation report for Lambert Dam. The Review Board considered the information and recommended that (1) the owner should engage the services of a qualified engineer if any deposition of material continues to occur in the toe drains, (2) cattle grazing on the embankment should be controlled to minimize damage to the embankment, and (3) the progression of the erosion of the wave berm should be periodically checked. They agreed with other report conclusions and recommendations. A copy of the letter report presented by the Review Board is included in Appendix G.

**APPENDIX A**  
**DATA SUMMARY**

APPENDIX A  
DATA SUMMARY SHEET  
LAMBERT DAM  
BLOUNT COUNTY, TENNESSEE

A.1 DAM

- A.1.1 Type: The dam is a linear earth structure with an open channel emergency spillway exiting just upstream of the right abutment. The service spillway is a reinforced concrete riser with a 30-inch reinforced concrete drain pipe.
- A.1.2 Dimensions and Elevations: Elevations are expressed in feet and are referenced from an assumed benchmark elevation of 1060.0.
- a. Crest Length: 605 feet
  - b. Crest Width: 18 feet
  - c. Height: 53.4 feet (Low point of crest to D/S invert of spillway pipe)
  - d. Crest Elevation: 1064.5 feet
  - e. Emergency Spillway Elevation: 1061.8 feet
  - f. Service Spillway Elevation: 1059.0 feet (normal pool)
  - g. Embankment Slope, Upstream: IV on 3.8H
  - h. Embankment Slope, Downstream: IV on 3.4H
  - i. Size Classification: Intermediate
- A.1.3 Embankment Zoning: Design drawings of the reconstructed section show that it was to be compacted to 95% Standard Proctor Density. As built drawings also show that a toe drain with two 8 inch CMPS was constructed.
- A.1.4 Cutoffs and Grout Curtains: None
- A.1.5 Instrumentation: None
- A.1.6 Operation and Maintenance: The dam is maintained by the owner, Keith McCord, and his caretaker. The drawdown gate has not been operated in recent years.

**A.2 RESERVOIR AND DRAINAGE AREA**

**A.2.1 Reservoir:**

**a. At Normal Pool**

- (1) Elevation: 1059.0
- (2) Surface Area: 20 acres
- (3) Storage: 336 acre-feet
- (4) Length: 1700 feet

**b. At Top of Dam**

- (1) Elevation: 1064.5 feet
- (2) Surface Area: 25 acres
- (3) Storage: 454 acre feet.

**A.2.2 Drainage Area:**

- a. Size: 467 acres (.73 sq. mi.)
- b. Soils: Jefferson, Ramsey
- c. Average Slope: 25%
- d. Land Uses: Woods, pasture, few roads or structures
- e. Runoff from PMP (28.5 inches in 6 hours)
  - (1) AMC II: 25.5 inches
  - (2) AMC III: 27.5 inches
- f. Runoff from 100 year storm (4.8 inches in 6 hours)
  - (1) AMC II: 2.3 inches
  - (2) AMC III: 3.5 inches

**A.3 OUTLET STRUCTURES**

**A.3.1 Service Spillway and Drawdown Facilities:**

- a. Type - Reinforced concrete riser, 36 feet in height with 2.5' by 7.5' opening.

- b. Pipe Size - 30" diameter, reinforced concrete, 336 feet long.
- c. Pipe gradient - 3.5%
- d. Drawdown - 18" opening covered by 24" slide gate. Manually operated.

A.3.2 Emergency Spillway: The spillway is just upstream of the right abutment and has a grass cover. It crosses a paved access road parallel to the abutment and empties into a broad meadow.

- a. Elevation: 1061.8
- b. Size: The spillway entrance has a width of 117 feet and side slopes of IV to 9.9H (left side toward dam) and IV to 7.6H (rt. side)
- c. Maximum capacity: 743 cfs

#### A.4 HISTORICAL DATA

A.4.1 Original Construction Date: 1957

A.4.1.1 Failure Date: October 12, 1963

A.4.1.2 Reconstruction Date: 1964

A.4.2 Designer: Soil Conservation Service

A.4.3 Builder: Lambert Brothers Construction Company

A.4.4 Owner: Keith McCord

A.4.5 Previous Inspections: October 17, 1963 by William P. Clure of TVA following failure on October 12, 1963

A.4.6 Seismic Zone: 2

#### A.5 DOWNSTREAM HAZARD DATA


A.5.1 Downstream Hazard Classification: High

A.5.2 Persons in Likely Flood Path: Approximately 4 to 10

A.5.3 Downstream Property: One house, a grocery store and county road.

A.5.4 Warning Systems: None


**APPENDIX B**  
**SKETCHES AND LOCATION MAPS**



LAMBERT DAM

LAMBERT DAM  
MARYVILLE, TENN.  
SITE






LAMBERT DAM


LAMBERT DAM  
MARYVILLE, TENN.

LAMBERT DAM  
BLOUNT COUNTY, TENNESSEE  
PLAN VIEW  
NOT TO SCALE




LAMBERT DAM  
DRAWN BY: cld  
DATE: 22 APR. 81  
SHEET: 1 OF 5

LAMBERT DAM  
 BLOUNT COUNTY, TENNESSEE  
 MAXIMUM SECTION STA. 4+75  
 NOT TO SCALE




LAMBERT DAM
DRAWN BY: cld
DATE: 22 APR. 81
SHEET 2 OF 5

LAMBERT DAM  
 BLOUNT COUNTY, TENNESSEE  
 EMBANKMENT PROFILE  
 LOOKING DOWNSTREAM  
 NOT TO SCALE




N.P. EL. 1059.0




LAMBERT DAM	
DRAWN BY: cld	
DATE: 22 APR. 81	
SHEET 2 OF 2	

LAMBERT DAM  
BLOUNT COUNTY, TENNESSEE  
EMERGENCY SPILLWAY CROSS SECTION  
ALONG PAVED ACCESS ROAD  
LOOKING NORTH  
NOT TO SCALE



LAMBERT DAM
DRAWN BY: cld
DATE: 22 APR. 81
SHEET: 4 OF 5

LAMBERT DAM  
 BLOUNT COUNTY, TENNESSEE  
 EMERGENCY SPILLWAY PROFILE  
 NOT TO SCALE



LAMBERT DAM

DRAWN BY: cid  
 DATE: 22 APR. 81  
 SHEET 5 OF 5

**APPENDIX C**  
**PHOTOGRAPHIC RECORD**

APPENDIX C  
PHOTOGRAPHIC RECORD

Photograph No.

- |    |  |
|----|--|
| 1  | Downstream slope of dam  |
| 2  | View of access road and right abutment                           |
| 3  | Upstream slope of dam. Note erosion of wave berm                 |
| 4  | Crest of dam   |
| 5  | Crest of dam. Note ruts with standing water                      |
| 6  | Downstream slope of dam from right abutment. Note reseeded area  |
| 7A | Contact between left abutment and embankment. Note pine trees    |
| 7  | Contact between toe of dam and downstream area. Note pine trees  |
| 8  | Emergency spillway entrance channel                              |
| 9  | Emergency spillway crossed by access road.                       |
| 10 | Exit channel of emergency spillway                               |
| 11 | Principal spillway and riser                                     |
| 12 | Outlet pipe and stilling basin. Note pine tree on the embankment |
| 13 | Toe drain partially covered                                      |
| 14 | Downstream channel   |
| 15 | Downstream channel 200 feet from outlet pipe                     |
| 16 | View from crest of downstream area                               |
| 17 | View of "lowpoint" in access road.                               |





PHOTO NO. 1



PHOTO NO. 2



PHOTO NO. 3



PHOTO NO. 4



PHOTO NO. 5



PHOTO NO. 6



PHOTO NO. 7A



PHOTO NO. 7



PHOTO NO. 8



PHOTO NO. 9



PHOTO NO. 10




PHOTO NO. 11



PHOTO NO. 12




PHOTO NO. 13



PHOTO NO. 14





PHOTO NO. 15



PHOTO NO. 16



PHOTO NO. 17

**APPENDIX D**  
**TECHNICAL CRITIQUES**

4 May 1981

## MEMORANDUM FOR RECORD

SUBJECT: Phase Investigation of Lambert Dam

1. An inspection team, composed of engineers from the Corps of Engineers and Tennessee Water Resources Department, conducted a Phase I investigation on Radnor Dam, near Maryville, Tennessee on 21 April 1981. Listed below are members of the inspection team:

Paul Bluhm	Civil Engineer	Corps of Engineers
Tim McCleskey	Civil Engineer	Corps of Engineers
Tom Porter	Hydraulic Engineer	Corps of Engineers
Troy Wedekind	Water Resources Engineer	State of Tennessee

2. Lambert Dam is owned by Keith McCord of Maryville, Tennessee and is used as a farm pond. The dam is located approximately 7 miles south of Maryville, and is on a tributary of Big Spring Branch which is in turn, a tributary of Six Mile Creek. The dam was originally designed by the Soil Conservation Service and was constructed by Lambert Brothers Construction Company in 1957. The dam failed in October of 1963 and the SCS again provided the design plans for its reconstruction.

3. Prior to inspecting the dam, the inspection team went to the Blount County SCS office. Mr. Dewey Simpson of the SCS, had photographs of the failure in 1963 and provided information concerning the failure. The exact cause of failure was not determined. However, Mr. Simpson said the failure may have been due to the collapse of the 30-inch concrete outlet pipe or of an 8-inch pipe that extended through the dam that was used for irrigation purposes. No lives were lost and property damage was limited to flooding of a church basement 1/2 mile downstream. The church has since been relocated.

4. The dam is an earth embankment 605 feet in length, 54 feet in height and impounds a 20 acre lake. The reservoir contains an estimated 336 acre-feet at normal pool and 454 acre-feet at the crest of the dam. Observations noted at time of inspection are as follows:

a. Upstream slope - The upstream slope of 1V to 3.8H meets an 18-foot wide wave berm. The wave berm lies on a 1V to 8H slope and is about 1.5 feet above normal pool level. Both the slope and the wave berm are well grassed. Wave action is eroding the berm somewhat, but was not considered serious.

4 May 1981

SUBJECT: Phase I Investigation of Lambert Dam

b. Crest - The 18-foot wide crest was straight and uniform. It was covered with a thin layer of gravel and was used as a road. It was in good condition except for some vehicle tracks in which 1-2 inches of water was standing.

c. Downstream slope - The downstream slope of 1V to 3.4H agrees with that shown on the "as built" drawings. The slope was uniform and had a good grass cover although it was very short due to the cattle that grazed on it. Near the crest, the owner had to reseed part of the embankment due to the tracks made by the cattle. Small pine trees, 2-4 inches in diameter were present at the contact between the left abutment and the embankment and at the toe of the dam. Two pine trees, 5 inches in diameter were also present at the toe, directly above the 30-inch outlet pipe. Two, small wet areas were found. The first was on the left side at the contact between the toe and natural ground. There was a small swale at this point and the moisture observed could possibly be retainage from recent rains. The second wet area was about 2/3 the way down the embankment, just to the right of the outlet structure at Station 7+00. It was 25 to 30 feet in length and 10 feet wide. Again, it is possible that this area was still wet due to recent rains. Two 8-inch diameter CMP toe drains were visible near the outlet of the 30-inch diameter pipe. Both were about half filled with material and water and had a very small flow exiting from them.

d. Abutments - Both abutments were in good condition. No significant erosion or seepage was observed. A paved access road was on the right abutment.

e. Emergency Spillway - The emergency spillway was a 125-foot wide saddle type, located on the right side of the embankment. It runs parallel to the crest and crosses the paved access road and exits into a broad field just upstream of the right abutment. Water was present in the spillway, between the reservoir and the access road, but this was due to the recent rainfall. The spillway was in good condition with a good grass cover.

f. Principal Spillway - According to the "as built" plans, the principal spillway consists of a reinforced concrete riser 36 feet in height, feeding a 30-inch diameter reinforced concrete pipe. Access to the structure was by means of a 110 foot walkway. The structure was covered by a solid metal platform. Trash racks, 9.5 feet by 1 foot were present on two sides of the structure, and both were clear of debris. An inspection of the 7.5 by 2.5 foot opening revealed that there was considerable leakage at the first construction joint. With the exception of this leakage, the structure was in good condition. Drawdown facilities consisted of a 18-inch diameter inlet, operated by a 24-inch sliding headgate. The gate is manually operated but was not operated at the time of inspection. A 336 foot, 30-inch diameter reinforced concrete pipe was fed by the riser and exits into a stilling basin at the toe of the dam. The 30-inch pipe was in excellent condition.

ORNED-G

4 May 1981

SUBJECT: Phase I Investigation of Lambert Dam

g. Stilling basin - Located at the toe of the dam, the stilling basin was about 25 to 30 feet in diameter and has its slopes protected by large concrete slabs. Small trees and saplings were present as was a good grass cover in places where concrete slabs weren't placed. The flow from the 30-inch pipe was estimated to be between 60 and 100 gpm and was very clear. Riprap placed directly below the outflow prevented any erosion.

h. Downstream channel - The channel downstream of the stilling basin had a base width of 4-5 feet and side slopes of about 1V to 3 H. The slopes were well grassed and lined with small trees. About 250 feet downstream, the stream passes under an access road through an old riser culvert. The channel widens to about 6-8 feet in width and has a heavier brush cover lining the banks. The stream then flows into a flat pasture before flowing under Montvale Road 1/2 mile from the dam.

i. Reservoir - An access road encompasses most of the reservoir. The slopes were moderately steep with a good grass cover around about half of the reservoir and woods around the rest. A low point exists on the access road across from the crest and it was at about the same elevation as the crest.

5. Potential downstream damage if rapid failure occurred could include a house, small store, and Montvale Road.

6. The undersigned concluded from the visual inspection that:

a. The small trees growing near the left embankment, below the toe of the embankment, and those above the 30-inch pipe should be removed.

b. Cattle should not be allowed to graze on the embankment.

c. The solid metal platform covering the principal spillway should be replaced with a grated platform.

d. Hydraulic and hydrologic analyses should be conducted to determine the adequacy of the spillway.

e. The two small wet areas on the downstream embankment should be re-inspected during a dry period to determine if they were a result of rainfall or actual seepage.

f. The two toe drains should be cleaned out so that they can function properly.

g. The concrete riser should be repaired to prevent seepage that is entering the first construction joint.

ORNED-G

4 May 1981

SUBJECT: Phase I Investigation of Lambert Dam

h. The owner should maintain a regular program of regular inspection and general maintenance. The objective of the program should be for the early detection and timely correction of any problem areas.

  
PAUL F. BLUHM  
Civil Engineer

MCCLESKEY/ED-G

COUCH/ED-G

30 April 1981

## MEMORANDUM FOR RECORD

SUBJECT: Trip Report on the Inspection of Lambert Dam, Blount County, Tennessee

1. A Phase I inspection of Lambert Dam was made 21 April 1981 by Messrs. Paul Bluhm, Tom Porter, and Timothy McCleskey. Troy Wedekind and a two-man surveying crew from the Division of Water Resource, State of Tennessee, the carekeeper, and the wife of the owner of the dam were also present during the inspection. The dam is located about 7 miles south of Maryville, Tennessee, and approximately one-half mile due east of the intersection of Montvale Road and Old Piney Road. It is shown on USGS Blockhouse Quadrangle, Blount County, Tennessee, dated 1966. The owner is Mr. Keith McCord. During the inspection, the weather was clear, sunny, warm, slightly windy, and temperatures in the low 70's.

2. Before the inspection, the inspection team talked with Mr. Dewey Simpson, District Conservationist, of the Soil Conservation Service, about the history, safety, and structural adequacy of the dam. We were informed that the dam failed in 1963 at a section along the service spillway outlet pipes. The outlet pipes consisted of a 30-inch concrete pipe with an upstream valve and a 6-inch steel pipe with a downstream valve. The original design included two 30-inch concrete pipes; however, the owners chose to install the 30-inch and 6-inch pipes. The cause of failure was not given, but a pipe failure and subsequent piping along one of the pipes is suspected. No loss of life or injuries resulted from the failure and property damage was mostly confined to the property of the owner. A church building located near the intersection of Montvale Road and Old Piney Road was partially flooded and damaged. This building has since been relocated. Mr. Simpson showed us photographs of the dam and downstream area after the failure, but he was reluctant to provide us with negatives of these photographs. The dam was initially designed by the SCS in the early sixties, prior to 1963. After the 1963 failure, a redesign to repair the breached section was prepared by the SCS and construction was completed about 1965.

3. The underlying rock at the dam probably includes shales, sandstones, and slate. Rock exposed in cuts at the dam and in nearby road cuts consists of highly weathered sandstones and shales. These exposed rocks appeared to be inclined at very high angles. Based on information provided in the SCS soil survey report for Blount County and USGS geology maps, the rock in the vicinity of the dam is Paleozoic in age - mainly Cambrian and lower Ordovician. These rocks have been subjected to intense earth movements and are highly folded and faulted. The region is characterized by series of alternate linear ridges and valleys extending in the southwest-northeast direction. The overburden at the dam site is composed of colluvial and local alluvial deposits of



ORNED-G

30 April 1981

SUBJECT: Trip Report on the Inspection of Lambert Dam, Blount Count, Tennessee

silty and sandy loam or ML, CL, and SC materials, which were derived from sandstone, quartzite, slate, and shale. The dam was constructed from material excavated from the lake, which includes sandy loam or ML, CL, and SC materials. These materials are characterized by the presence of many angular sandstone cobbles, 3 to 10-inches in diameter. Such cobbles were quite noticeable on the downstream slope.

4. The dam is a linearly earthfill structure approximately 605 feet long and 54 feet high. It has a crest width of about 18 feet and upstream and downstream slope dimensions of 1:3.8 and 1:2.7 respectively. The upstream slope has a 10-15 wave berm about 2.5 feet below the crest which slopes gently toward the pool. The slope immediately below this berm and just below the pool level is near vertical and badly eroded from wave wash. A service spillway, consisting of a concrete riser and a 30-inch diameter concrete outlet pipe, is located about 130 feet from the left abutment. A low area on the reservoir rim, just upstream of the right abutment, serves as an emergency spillway. The access road to the dam has an asphalt surface. It traverses the axis of the dam at the right abutment and extends across the emergency spillway and along the right reservoir rim, providing access to two houses upstream of the lake. A 20-25 feet section of this road along the reservoir rim is approximately 0.5 feet lower than the crest of the dam. In the event the lake reaches this level, water would spill over the emergency spillway and this section of the road before the dam is overtopped. Two 8-inch metal outlet pipes, located at the toe of the dam and to the immediate left and right of the service spillway outlet pipe, drains an internal sand and gravel toe drain. The right toe drain pipe was covered during the initial part of the inspection, but was later uncovered by Troy Wedekind. Only a trickle of water was flowing through either pipe. The area surrounding the right toe drain pipe was wet, soggy, and holding pockets of standing water before the outlet was uncovered. About 5-inches of water were flowing through the service spillway outlet pipe. The stilling basin consists of the old natural channel bed overlain with sandstone boulders and huge chunks of the old concrete riser - apparently left from the 1963 failure.

5. No cracks, scarfs, or evidence of sloughing or sliding were observed along the crest, slopes, or abutments. The slopes are fairly uniform and contain a relatively good vegetative cover of fescue, clover, lespedeza, and other grasses. Surface erosion, except for wave wash on the upstream slope, was minimal. The owner has permitted livestock to graze on the dam. This practice has caused the turf to be churned up, particularly near the crest and has destroyed the grass cover in certain areas. However, these areas have been reseeded and mulched and new grass is growing. The only undesirable growth on the dam consisted of several 2 to 4-inch diameter trees located at the left abutment contact and along or just below the left toe of the dam. Two areas on the downstream slope were somewhat wetter than the rest of the downstream slope area. One area was at the toe where the slope intersects the natural ground just left of the spillway outlet pipe. The other area is about 50 feet

ORNED-G

30 April 1981

SUBJECT: Trip Report on the Inspection of Lambert Dam, Blount Count, Tennessee

to the right of the spillway outlet pipe and about two-thirds the distance down the slope. Both areas appeared to be wet from surface water draining slowly off the dam. The crest, which has a thin layer of crushed stone, provides vehicular access to the left abutment and reservoir rim.

6. During the inspection, water was spilling into the service spillway riser from the sides. No water was flowing in from the top because the reservoir had not reached the top of the riser. A walkway, about 50 feet long, extends from the crest out to the top of the riser. A platform constructed at the top of the riser provides a service area for operating the drawdown gate and opening or closing a solid steel hinged plate over the opening at the top of the riser. While this plate protects the spillway from being clogged with debris, it also prevents using the spillway to its full capacity when the level of the reservoir is above the riser, unless the plate is open. A grate would be a much better covering, since it could prevent entrance of debris that may clog the spillway and yet leave the spillway open for near full discharge capacity. Observation of discharge into the riser indicated leakage along the upper construction joint.

7. The drainage area, except for small areas immediately adjacent to the reservoir, is woody. The slopes in the drainage area are gentle to steep - but mostly steep. No evidence of sliding, cracking, or subsidence were observed along the reservoir rim or within the drainage area. The channel downstream of the dam is relatively shallow, narrow, and slopes gently with adjacent terrain. The surrounding land is mostly pasture, although some trees align the banks of the creek. The downstream banks are near vertical at places but overall are fairly flat and in some areas grassed. The banks appeared to be stable. No boils or seepage was observed downstream of the dam.

8. It appears there are two buildings in the paths of flood waters, should the dam fail again. One is a house located on the property of the owner and the other is a store - possible residence, located near the intersection of Montvale Road and Old Piney Road. Since both buildings are occupied, at least on a part time basis, the dam is in the high hazard potential classification. The dam is 54 feet high and is classified as an intermediate-size dam. Overall, the dam appeared to be well maintained and in good condition. However, the following recommendations are given in the interest of increasing the safety of the dam:

a. All trees at the left abutment contact and toe of the dam should be removed.

b. Outlet pipes for the toe drains should be kept open and cleared of all soil and other debris at all times.

ORNED-G

30 April 1981

SUBJECT: Trip Report on the Inspection of Lambert Dam, Blount County, Tennessee

c. The steel plate over the service spillway riser opening should be changed to a grate covering.

d. Livestock should not be permitted to graze on the dam.

TIMOTHY MCCLESKEY  
Chief, I&I Section

COUCH/ED-G

# DISPOSITION FORM

For use of this form, see AR 340-16; the proponent agency is The Adjutant General's Office.

REFERENCE OR OFFICE SYMBOL	SUBJECT
ORNED-H	Dam Inspection of Lambert Dam (Blount Co.)

TO Chief, J.E. & B. Sec. 1 FROM Chief, H.E. & H. Br. DATE 29 May 1981 CMT 1  
JNP Porter // 5632

1. Specific hydraulic and structural data on Lambert Dam is given in Memorandums for Record by Timothy McClesky dated 30 April 1981 and by Paul J. Bluhm dated 4 May 1981.

2. The drainage area above Lambert Dam is 0.73 square miles.

3. The dam was classified as intermediate size and high hazard potential. The hazard classification was considered justified because of the home and store located downstream of the dam.

4. The PM-1 event was used to evaluate Lambert Dam. Antecedent Moisture Conditions II and III were used to analyze the project.

The computer program HEC1DB was used to develop inflow hydrographs and route them through the dam. The program used the SCS dimensionless unit hydrograph to develop inflow hydrographs. For each routing, water was assumed to be at the invert of the opening in the drop inlet. The PMP was a 24 hour duration of 38.0 inches with a maximum 6 hour intensity

of 28.5 inches. Resulting runoff for AMC II conditions was 34.5 inches (24 hour) and 36.0 inches (24 hour) for AMC III conditions.

5. Results of the routings showed that Lambert Dam would be overtopped by both PMF and  $\frac{1}{2}$  PMF events. A table of these results are attached.
6. Since Lambert Dam was classified as intermediate size and high hazard the spillway design flood is a PMF. Based on the results given above we consider the dam to be hydrologically unsafe.
7. We concur in the conclusions and recommendations made in the aforementioned memorandums for record.

  
Connor

<sup>DW</sup>  
Williams / ED-H

1 Encl. as

CORPS OF ENGINEERS, U.S. ARMY OHIO RIVER DIVISION	COMPUTATION SHEET		PAGE	OF	PAGES
	SUBJECT		DATE		
INSTALLATION	COMPUTATION		NUMBER		
COMPUTED BY					
CHECKED BY					

LAMBERT DAM (BLOUNT CO.)

		Antecedent Moisture Conditions	
		AMC II (CN 75)	AMC III (CN 88)
24 hour duration	Spillway design flood		
	PMF	1.30' overtop 6 hr duration	1.31' overtop 6.25 hr duration
	1/2 PMF	0.63' overtop 3.25 hr duration	0.65' overtop 3.50 hr duration
	100YR	2.1' freeboard	1.3' freeboard
6 hour duration	PMF	1.32' overtop 4.75 hr duration	1.32' overtop 4.75 hr duration
	1/2 PMF	0.65' overtop 3 hr duration	0.65' overtop 3 hr duration
	100YR	2.2' freeboard	1.6' freeboard

Check List  
Visual Inspection of Earth Dams  
Department of Conservation  
Division of Water Resources

Name of Dam Lambert Dam

County Blount Date of Inspection 21 April 1981

ID # - State \_\_\_\_\_ Federal TN-901

Type of Dam Earthen

Hazard Category-Federal High State Tennessee

Weather Clear - Warm Temperature 75°

Pool at Time of Inspection E11059.00 (6.2' from crest) (distance from crest)

Tailwater at Time of Inspection 10000 (distance from stream bed)

Design/As Built Drawings Available: Yes  No \_\_\_\_\_

Location: SCS Office in Nashville

Copy Obtained: Yes  No \_\_\_\_\_

Reviewed: Yes  No \_\_\_\_\_

Construction History Available: Yes \_\_\_\_\_ No \_\_\_\_\_

Location: \_\_\_\_\_

Copy Obtained: Yes \_\_\_\_\_ No \_\_\_\_\_

Reviewed: Yes \_\_\_\_\_ No \_\_\_\_\_

Other Records and Reports Available: Yes  No \_\_\_\_\_

Location: Photos of failure on file in SCS office in Maryville TN

Copy Obtained: Yes \_\_\_\_\_ No

Reviewed: Yes  No \_\_\_\_\_

Prior Incidents or Failures: Yes  No \_\_\_\_\_

Inspection Personnel and Affiliation:

Paul Bluhm Corps of Engineers

Tim McCleskey Corps of Engineers

Tom Porter Corps of Engineers

Troy Wedekind Tennessee Department of Water Resources

I. Embankment

A. Crest

Description (1st inspection) Top of crest is used as a  
gravel road. There are some ruts and water standing due to  
traffic. Cattle tracks have also made some ruts.

1. Longitudinal Alignment Straight. Extends from left  
abutment to paved road on right abutment.

2. Longitudinal Surface Cracks None were seen

3. Transverse Surface Cracks None were seen.

4. General Condition of Surface Good condition other  
than traffic ruts

5. Miscellaneous Paved road crosses crest at right  
abutment.

B. Upstream Slope

1. Undesirable Growth or Debris There are some small  
shrubs and trees near left abutment. Otherwise the slope  
is clear.



2. Sloughing, Subsidence, or Depressions None was  
seen

3. Slope Protection An 18 foot wide berm is present at about  
1½' above normal pool. This berm is 2½' below the crest and  
has a good grass cover. However, it is being eroded away by wave action.

a. Condition of Riprap N/A

b. Durability of Individual Stones N/A

c. Adequacy of Slope Protection Against Waves  
and Runoff Has a good grass cover, but wave action has been  
eroding it away.

d. Gradation of Slope Protection - Localized Areas  
of Fine Material N/A

4. Surface Cracks None were seen

C. Downstream Slope

1. Undesirable Growth or Debris Pine trees, 4" to 5" in diameter  
were present at toe of slope. One 5" diameter tree, on the slope, and  
20' from the toe was located directly above the outlet structure.

2. Sloughing, Subsidence, or Depressions; Abnormal  
Bulges or Non-Uniformity The slope appears to be flatter  
in section that was rebuilt.
3. Surface Cracks on Face of Slope None were seen.
4. Surface Cracks or Evidence of Heaving at  
Embankment Toe None were seen.
5. Wet or Saturated Areas or Other Evidence of Seepage  
on Face of Slope; Evidence of "Piping" or "Boils"  
At about station 7+00,  $\frac{2}{3}$  the way down the slope there is a  
small wet area. It could be retainage from recent rain  
rather than seepage.
6. Drainage System There are two toe drains, one on each side  
of the outlet structure. Two 8" diameter pipes near the outlet  
structure are visible, but are about half filled with material.  
Both had a very small flow coming from these pipes
7. Fill Contact with Outlet Structure Good Riprap  
was directly below the structure. No evidence of erosion  
around the structure.
8. Condition of Grass Slope Protection Good grass cover,  
but cattle are keeping it short. Some areas near crest have  
been reseeded.

**D. Abutments**

1. Erosion of Contact of Embankment with Abutment from  
Surface Water Runoff, Upstream or Downstream \_\_\_\_\_

None Evident

---

---

2. Springs or Indications of Seepage Along Contact of  
Embankment with the Abutments \_\_\_\_\_ None were seen

---

---

3. Springs or Indications of Seepage in Areas a Short  
Distance Downstream of Embankment - Abutment Tie-in

None were seen

---

---

---

II. Area Downstream of Embankment, Including Channel

A. Localized Subsidence, Depressions, Sinkholes, Etc. \_\_\_\_\_

None were seen

B. Evidence of "Piping", "Boils", or "Seepage" \_\_\_\_\_

None were seen

C. Unusual Presence of Lush Growth, such as Swamp  
Grass, etc. \_\_\_\_\_ None

D. Unusual Muddy Water in Downstream Channel \_\_\_\_\_

Water was clear.

E. Sloughing or Erosion \_\_\_\_\_ None were seen

F. Surface Cracks or Evidence of Heaving Beyond  
Embankment Toe \_\_\_\_\_ None

G. Stability of Channel Sideslopes \_\_\_\_\_ Good

H. Condition of Channel Slope Protection \_\_\_\_\_ Good grass slopes

I. Adequacy of Slope Protection Against Waves, Currents,  
and Surface Runoff Good slope protection

J. Miscellaneous \_\_\_\_\_

K. Condition of Relief Wells, Drains, and Other  
Appurtenances N/A

L. Unusual Increase or Decrease in Discharge from  
Relief Wells N/A

III. Instrumentation

A. Monumentation/Surveys None

\_\_\_\_\_  
\_\_\_\_\_

B. Observation Wells None

\_\_\_\_\_  
\_\_\_\_\_

C. Weirs None

\_\_\_\_\_  
\_\_\_\_\_

D. Piezometers None

\_\_\_\_\_  
\_\_\_\_\_

E. Other \_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_

IV. Spillways

A. Service Spillway (Service/Emergency Combination Yes  No )

1. Intake Structure Condition Good condition. It has a  
walk way and a metal cover. A trash rack is on two sides of the  
square structure providing two, 9.5' by 1' openings. The 5th construction

2. Outlet Structure Condition Good condition. A 30" reinforced  
joint from the top is leaking badly and should be repaired.  
concrete pipe empties into a 25' diameter stilling basin. The  
basin slopes are protected by concrete slabs and riprap is directly  
beneath the outflow.

3. Pipe Condition \_\_\_\_\_  
Excellent condition

4. Evidence of Leakage or Piping None was evident.

5. General Remarks Depth of water in the 30" pipe was about 5".  
Flow was about 180 gpm.

B. Emergency Spillway

1. General Condition Good condition

2. Entrance Channel Entrance channel is about 1½' above  
normal pool. It is well grassed although some water was  
standing.

3. Control Section The control section runs parallel to the dam  
exiting in front of the right abutment. It crosses the paved  
access road.

3. Exit Channel The exit channel is wide and well grassed  
It slopes at 2 to 3% for about 250 feet then drops off to a  
gully.

4. Vegetative/Woody Cover Well grassed cover.

5. Other Observations \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



V. Emergency Drawdown Facilities (if part of service spillway so state) A gate valve on the service spillway controls an 18" diameter opening.

---

---

Are Facilities Operable: Yes x No \_\_\_\_\_

Were Facilities Operated During Inspection: Yes \_\_\_\_\_ No x

Date Facilities Were Last Used \_\_\_\_\_

VI. Reservoir

A. Slopes Grass slopes around half of reservoir and steep wooded  
slopes are around the other half of the reservoir.

B. Sedimentation None evident

C. Turbidity None

VII. Drainage Area

Description (for hydrologic analysis) Heavily wooded with  
very steep topography.

A. Changes in Land Use None expected

VIII. Downstream Area (Stream)

A. Condition (obstructions, debris, etc.) Channel passes  
through a small culvert 200' downstream and through another  
under the paved road ½ mile downstream. No major obstructions.

B. Slopes Area downstream is gently sloping pasture land.

C. Approximate No. Homes, Population, and Distance D/S  
One house and one store about ½ mile downstream. The population  
varies from 3 to 6 people depending upon the people at the store.

D. Other Hazards A barn is next to the house and could possibly  
be damaged.

**IX. Miscellaneous**

**Incidents/Failures** A failure occurred in October of 1963. The cause of the failure is unknown, although it is believed that a 6" diameter pipe coming through the dam caused failure. No loss of life and damage was minimal.

**Observed Geology of Area** \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

**X. Conclusions**

The dam appears to be well constructed and in good condition.  
\_\_\_\_\_  
\_\_\_\_\_


**XI. Recommendations**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

\_\_\_\_\_  
**Regional Engineer**

\_\_\_\_\_  
**Chief Engineer**

APPENDIX E  
DESIGN DRAWINGS



**PLAN VIEW OF EMBANKMENT SHOWING PROPOSED IMPROVEMENTS / MODIFICATIONS.**


**PROFILE ALONG & OF EMBANKMENT SHOWING REQUIRED EXCAVATION**

**ESTIMATED QUANTITIES**


- Concrete: Estimated
- 6" Rein. Concrete
- 8" Rein. Concrete
- 12" Rein. Concrete
- 18" Rein. Concrete
- 24" Rein. Concrete
- 30" Rein. Concrete
- 36" Rein. Concrete
- 42" Rein. Concrete
- 48" Rein. Concrete
- 54" Rein. Concrete
- 60" Rein. Concrete
- 66" Rein. Concrete
- 72" Rein. Concrete
- 78" Rein. Concrete
- 84" Rein. Concrete
- 90" Rein. Concrete
- 96" Rein. Concrete
- 102" Rein. Concrete
- 108" Rein. Concrete
- 114" Rein. Concrete
- 120" Rein. Concrete
- 126" Rein. Concrete
- 132" Rein. Concrete
- 138" Rein. Concrete
- 144" Rein. Concrete
- 150" Rein. Concrete
- 156" Rein. Concrete
- 162" Rein. Concrete
- 168" Rein. Concrete
- 174" Rein. Concrete
- 180" Rein. Concrete
- 186" Rein. Concrete
- 192" Rein. Concrete
- 198" Rein. Concrete
- 204" Rein. Concrete
- 210" Rein. Concrete
- 216" Rein. Concrete
- 222" Rein. Concrete
- 228" Rein. Concrete
- 234" Rein. Concrete
- 240" Rein. Concrete
- 246" Rein. Concrete
- 252" Rein. Concrete
- 258" Rein. Concrete
- 264" Rein. Concrete
- 270" Rein. Concrete
- 276" Rein. Concrete
- 282" Rein. Concrete
- 288" Rein. Concrete
- 294" Rein. Concrete
- 300" Rein. Concrete

**ENGINE CLASS III AS BUILT**  
**LAMBERT LAKE**  
**BLOUNT CO., TENNESSEE**  
**PLAN AND PROFILE SHEET**  
**U. S. DEPARTMENT OF AGRICULTURE**  
**SOIL CONSERVATION SERVICE**

**LETTER OF APPROVAL**  
**S/ L. F. SILBERBERG**  
**SEPTEMBER 25, 1964**




**PROFILE VIEW OF EMBANKMENT SHOWING REQUIRED EXCAVATION**



**PROFILE VIEW OF EMBANKMENT SHOWING REQUIRED EXCAVATION**

**FILTER SANDS**

Filter Sand	Quantity
3/4"	400
1/2"	2500
3/8"	2500
1/4"	2500
1/8"	2500
0.075"	2500
0.045"	2500
0.025"	2500
0.015"	2500
0.0075"	2500
0.0045"	2500
0.0025"	2500
0.0015"	2500
0.00075"	2500
0.00045"	2500
0.00025"	2500
0.00015"	2500
0.000075"	2500
0.000045"	2500
0.000025"	2500
0.000015"	2500
0.0000075"	2500
0.0000045"	2500
0.0000025"	2500
0.0000015"	2500
0.00000075"	2500
0.00000045"	2500
0.00000025"	2500
0.00000015"	2500
0.000000075"	2500
0.000000045"	2500
0.000000025"	2500
0.000000015"	2500
0.0000000075"	2500
0.0000000045"	2500
0.0000000025"	2500
0.0000000015"	2500



1. The Contractor shall be responsible for the design and construction of the foundation drain system. The drain shall be installed in accordance with the specifications and drawings. The drain shall be installed in a trench 18 inches wide and 18 inches deep. The drain shall be installed in a trench 18 inches wide and 18 inches deep. The drain shall be installed in a trench 18 inches wide and 18 inches deep.

ENG. CLASS. VI AS BUILT

LAMBERT LAKE  
BLOUNT CO. TENNESSEE  
2.5" I.D. R.C. RISER - 30" DIA. R.C. PIPE




U.S. DEPARTMENT OF AGRICULTURE  
SOIL CONSERVATION SERVICE

DATE: 1/21/54  
DRAWN BY: J. W. BROWN  
CHECKED BY: J. W. BROWN  
APPROVED BY: J. W. BROWN

FORM NO. 317 APRIL 1949

STEEL SECTIONS FOR BENT

SECTION	SECTION NO.	SECTION NAME	SECTION TYPE
1	1	SECTION A-A	SECTION A-A
2	2	SECTION B-B	SECTION B-B
3	3	SECTION C-C	SECTION C-C
4	4	SECTION D-D	SECTION D-D
5	5	SECTION E-E	SECTION E-E
6	6	SECTION F-F	SECTION F-F
7	7	SECTION G-G	SECTION G-G
8	8	SECTION H-H	SECTION H-H
9	9	SECTION I-I	SECTION I-I
10	10	SECTION J-J	SECTION J-J
11	11	SECTION K-K	SECTION K-K
12	12	SECTION L-L	SECTION L-L
13	13	SECTION M-M	SECTION M-M
14	14	SECTION N-N	SECTION N-N
15	15	SECTION O-O	SECTION O-O
16	16	SECTION P-P	SECTION P-P
17	17	SECTION Q-Q	SECTION Q-Q
18	18	SECTION R-R	SECTION R-R
19	19	SECTION S-S	SECTION S-S
20	20	SECTION T-T	SECTION T-T



STEEL SECTIONS FOR PIPE COLLARS





SECTION	SECTION NO.	SECTION NAME	SECTION TYPE
1	1	SECTION A-A	SECTION A-A
2	2	SECTION B-B	SECTION B-B
3	3	SECTION C-C	SECTION C-C
4	4	SECTION D-D	SECTION D-D
5	5	SECTION E-E	SECTION E-E
6	6	SECTION F-F	SECTION F-F
7	7	SECTION G-G	SECTION G-G
8	8	SECTION H-H	SECTION H-H
9	9	SECTION I-I	SECTION I-I
10	10	SECTION J-J	SECTION J-J
11	11	SECTION K-K	SECTION K-K
12	12	SECTION L-L	SECTION L-L
13	13	SECTION M-M	SECTION M-M
14	14	SECTION N-N	SECTION N-N
15	15	SECTION O-O	SECTION O-O
16	16	SECTION P-P	SECTION P-P
17	17	SECTION Q-Q	SECTION Q-Q
18	18	SECTION R-R	SECTION R-R
19	19	SECTION S-S	SECTION S-S
20	20	SECTION T-T	SECTION T-T

DETAILS OF PRECAST CONCRETE JOINTING BARS BUILT

LAMBERT LAKE  
BLOUNT CO. TENNESSEE

**STRUCTURAL DETAILS**

U.S. DEPARTMENT OF AGRICULTURE  
SOIL CONSERVATION SERVICE



STEEL SECTIONS FOR PIPE COLLARS

SECTION	SECTION NO.	SECTION NAME	SECTION TYPE
1	1	SECTION A-A	SECTION A-A
2	2	SECTION B-B	SECTION B-B
3	3	SECTION C-C	SECTION C-C
4	4	SECTION D-D	SECTION D-D
5	5	SECTION E-E	SECTION E-E
6	6	SECTION F-F	SECTION F-F
7	7	SECTION G-G	SECTION G-G
8	8	SECTION H-H	SECTION H-H
9	9	SECTION I-I	SECTION I-I
10	10	SECTION J-J	SECTION J-J
11	11	SECTION K-K	SECTION K-K
12	12	SECTION L-L	SECTION L-L
13	13	SECTION M-M	SECTION M-M
14	14	SECTION N-N	SECTION N-N
15	15	SECTION O-O	SECTION O-O
16	16	SECTION P-P	SECTION P-P
17	17	SECTION Q-Q	SECTION Q-Q
18	18	SECTION R-R	SECTION R-R
19	19	SECTION S-S	SECTION S-S
20	20	SECTION T-T	SECTION T-T




### STEEL SCHEDULE

Location	Quantity	Weight	Volume
Beam 101.0	10	5.2	0.52
Beam 102.0	10	5.2	0.52
Beam 103.0	10	5.2	0.52
Beam 104.0	10	5.2	0.52
Beam 105.0	10	5.2	0.52
Beam 106.0	10	5.2	0.52
Beam 107.0	10	5.2	0.52
Beam 108.0	10	5.2	0.52
Beam 109.0	10	5.2	0.52
Beam 110.0	10	5.2	0.52
Beam 111.0	10	5.2	0.52
Beam 112.0	10	5.2	0.52
Beam 113.0	10	5.2	0.52
Beam 114.0	10	5.2	0.52
Beam 115.0	10	5.2	0.52
Beam 116.0	10	5.2	0.52
Beam 117.0	10	5.2	0.52
Beam 118.0	10	5.2	0.52
Beam 119.0	10	5.2	0.52
Beam 120.0	10	5.2	0.52
Beam 121.0	10	5.2	0.52
Beam 122.0	10	5.2	0.52
Beam 123.0	10	5.2	0.52
Beam 124.0	10	5.2	0.52
Beam 125.0	10	5.2	0.52
Beam 126.0	10	5.2	0.52
Beam 127.0	10	5.2	0.52
Beam 128.0	10	5.2	0.52
Beam 129.0	10	5.2	0.52
Beam 130.0	10	5.2	0.52
Beam 131.0	10	5.2	0.52
Beam 132.0	10	5.2	0.52
Beam 133.0	10	5.2	0.52
Beam 134.0	10	5.2	0.52
Beam 135.0	10	5.2	0.52
Beam 136.0	10	5.2	0.52
Beam 137.0	10	5.2	0.52
Beam 138.0	10	5.2	0.52
Beam 139.0	10	5.2	0.52
Beam 140.0	10	5.2	0.52
Beam 141.0	10	5.2	0.52
Beam 142.0	10	5.2	0.52
Beam 143.0	10	5.2	0.52
Beam 144.0	10	5.2	0.52
Beam 145.0	10	5.2	0.52
Beam 146.0	10	5.2	0.52
Beam 147.0	10	5.2	0.52
Beam 148.0	10	5.2	0.52
Beam 149.0	10	5.2	0.52
Beam 150.0	10	5.2	0.52
Beam 151.0	10	5.2	0.52
Beam 152.0	10	5.2	0.52
Beam 153.0	10	5.2	0.52
Beam 154.0	10	5.2	0.52
Beam 155.0	10	5.2	0.52
Beam 156.0	10	5.2	0.52
Beam 157.0	10	5.2	0.52
Beam 158.0	10	5.2	0.52
Beam 159.0	10	5.2	0.52
Beam 160.0	10	5.2	0.52
Beam 161.0	10	5.2	0.52
Beam 162.0	10	5.2	0.52
Beam 163.0	10	5.2	0.52
Beam 164.0	10	5.2	0.52
Beam 165.0	10	5.2	0.52
Beam 166.0	10	5.2	0.52
Beam 167.0	10	5.2	0.52
Beam 168.0	10	5.2	0.52
Beam 169.0	10	5.2	0.52
Beam 170.0	10	5.2	0.52
Beam 171.0	10	5.2	0.52
Beam 172.0	10	5.2	0.52
Beam 173.0	10	5.2	0.52
Beam 174.0	10	5.2	0.52
Beam 175.0	10	5.2	0.52
Beam 176.0	10	5.2	0.52
Beam 177.0	10	5.2	0.52
Beam 178.0	10	5.2	0.52
Beam 179.0	10	5.2	0.52
Beam 180.0	10	5.2	0.52
Beam 181.0	10	5.2	0.52
Beam 182.0	10	5.2	0.52
Beam 183.0	10	5.2	0.52
Beam 184.0	10	5.2	0.52
Beam 185.0	10	5.2	0.52
Beam 186.0	10	5.2	0.52
Beam 187.0	10	5.2	0.52
Beam 188.0	10	5.2	0.52
Beam 189.0	10	5.2	0.52
Beam 190.0	10	5.2	0.52
Beam 191.0	10	5.2	0.52
Beam 192.0	10	5.2	0.52
Beam 193.0	10	5.2	0.52
Beam 194.0	10	5.2	0.52
Beam 195.0	10	5.2	0.52
Beam 196.0	10	5.2	0.52
Beam 197.0	10	5.2	0.52
Beam 198.0	10	5.2	0.52
Beam 199.0	10	5.2	0.52
Beam 200.0	10	5.2	0.52

**QUANTITIES**

Reinforcing Steel	45,465 Lb.	19.46 Cu Yd
Numbering Steel	55,500 Lb.	25.11 Cu Yd
Numbering Steel	68,000 Lb.	30.88 Cu Yd
Numbering Steel	73,500 Lb.	33.48 Cu Yd
Numbering Steel	127,000 Lb.	58.21 Cu Yd




NOTE: Minimum Radius of All Curves To Be Not Less Than 10'.

NOTE: FLASH POSITIONING STEEL 2' FROM FACE.

**AS BUILT**

LANBERT LAKE  
 BLOUNT CO. TENNESSEE  
 DETAILS OF 24" REINFORCED CONCRETE RISER  
 U.S. DEPARTMENT OF AGRICULTURE  
 SOIL CONSERVATION SERVICE

DATE: 10-1-58  
 DRAWN BY: J. J. ...  
 CHECKED BY: ...



**UPSTREAM WALL ELEVATION**

STEEL REINFORCEMENT PAGE

**DOWNSTREAM WALL ELEVATION**

STEEL REINFORCEMENT PAGE

**SIDE WALL ELEVATION**

STEEL REINFORCEMENT PAGE

NOTES:  
 All dimensions are in feet.  
 All dimensions shall be in accordance with the  
 U.S. DEPARTMENT OF AGRICULTURE  
 SOIL CONSERVATION SERVICE  
 DESIGN OFFICE OF TENNESSEE  
 See Sheet 5-01

**UPSTREAM WALL ELEVATION**


STEEL REINFORCEMENT PAGE

**DOWNSTREAM WALL ELEVATION**

STEEL REINFORCEMENT PAGE



**SIDE WALL ELEVATION**

STEEL REINFORCEMENT PAGE





ITEM SCHEDULE FOR ANTI-WHITE BATTLE	
ITEM	QUANTITY
1. Reinforcing Steel Bars	100.00
2. Concrete	100.00
3. Formwork	100.00
4. Grating	100.00
5. Metal Strap	100.00
6. Grating Cover	100.00
7. Grating	100.00
8. Grating	100.00
9. Grating	100.00
10. Grating	100.00
11. Grating	100.00
12. Grating	100.00
13. Grating	100.00
14. Grating	100.00
15. Grating	100.00
16. Grating	100.00
17. Grating	100.00
18. Grating	100.00
19. Grating	100.00
20. Grating	100.00

THE FLOOR PLAN INCLUDES THE FOLLOWING:  
 1. FLOOR PLAN SHOWING STEEL LAYOUT  
 2. FLOOR PLAN SHOWING CONCRETE LAYOUT  
 3. FLOOR PLAN SHOWING REINFORCING STEEL LAYOUT  
 4. FLOOR PLAN SHOWING METAL STRAP LAYOUT  
 5. FLOOR PLAN SHOWING GRATING LAYOUT  
 6. FLOOR PLAN SHOWING GRATING COVER LAYOUT





NOTE: ALL CONCRETE SHALL BE PLACED IN PLACE.  
 ALL METALS SHALL BE GALVANIZED AND PROTECTED BY PAINT.  
 ALL METALS SHALL BE GALVANIZED AND PROTECTED BY PAINT.  
 ALL METALS SHALL BE GALVANIZED AND PROTECTED BY PAINT.





NOTE: MINIMUM COVER SHALL BE 4 INCHES.  
 ALL METALS SHALL BE GALVANIZED AND PROTECTED BY PAINT.  
 ALL METALS SHALL BE GALVANIZED AND PROTECTED BY PAINT.




NOTE: ALL METALS SHALL BE GALVANIZED AND PROTECTED BY PAINT.  
 ALL METALS SHALL BE GALVANIZED AND PROTECTED BY PAINT.



NOTE: ALL METALS SHALL BE GALVANIZED AND PROTECTED BY PAINT.  
 ALL METALS SHALL BE GALVANIZED AND PROTECTED BY PAINT.



NOTE: ALL METALS SHALL BE GALVANIZED AND PROTECTED BY PAINT.  
 ALL METALS SHALL BE GALVANIZED AND PROTECTED BY PAINT.



AS BUILT  
 LAMBERT LAKE  
 BLOUNT CO., TENNESSEE  
 DETAILS OF ANTI-WHITE BATTLE, TRASH BACK & WEBSITE  
 U.S. DEPARTMENT OF AGRICULTURE  
 SOIL CONSERVATION SERVICE

CONSTRUCTION SHEET

REVISION REV 7-58

DATE

CONTRACT

STATE **TENNESSEE**


PROJECT **LANBERT LAKE**

C.I.M. 10-28-64

STEEL COVER FOR 2.5' x 7.5' RC. RISER


1

3



ELEVATION

Angle Bolts  
See Details Sheet 2




FLANGE


**AS BUILT**

SHEET 6A1 OF 6


TENNESSEE LAMBERT LAKE  
C.I.M. 10-28-68  
STEEL COVER FOR 2.5' x 7.5' R.C. RISER



DETAIL A



3/4" Pipe Sleeve MANHOLE COVER DETAILS



AS BUILT

DETAIL - 12 ANGLE BOLTS REQ'D  
SHEET 6A OF 6

STATE **TENNESSEE**

PROJECT **LAMBERT LAKE**

C.U.M. 10-28-54

STEEL COVER FOR 2.5' x 7.5' R.C. RISER



3

3

BILL OF MATERIALS

ITEM	DESCRIPTION	QUAN.
1	12'-0 1/2" x 9'-4" x 1/4" Steel Plate	1
2	3 U.S.O., 9'-4" long	6
3	3 U.S.O., 2'-3" long	2
4	1/8" Dia. Angle Bolts, 13 1/2" x 8 3/4"	12
5	3/4" I.D. Fine Sleeve, 11" long	12
6	6" x 1/8" Strap Hinge, Steel	2
7	Handle - 10" of 1/2" $\phi$ Round	1
8	Locking Device - 3 1/2" of 1/4" Round	1
9	2" x 1/8" Flat Washers - 5/8" $\phi$ Hole	12
10	5/8" $\phi$ Flat Washers - Standard	12
11	5/8" $\phi$ Hex Nuts -	24
12	Padlock	1

AS BUILT



PROFILE LOOKING UPSTREAM

PROFILE OF 4'x4'  
 FOUNDATION DRAIN  
 LAMBERT LAKE  
 AS BUILT  
 SHEET 2A

**APPENDIX F**  
**HYDRAULIC AND HYDROLOGIC ANALYSIS**



## HYDROLOGIC AND HYDRAULIC ANALYSIS

According to OCL guidelines, Lambert Dam must be able to safely pass the Probable Maximum Flood (PMF). Six-hour rainfall depths for the Probable Maximum Precipitation (PMP) and the 100-year rainfall were obtained from the U. S. Weather Service's Technical Paper 40. Flood routings were performed using the HEC-1-DB computer program. The program used the dimensionless hydrograph technique described in Section 4 of the Soil Conservation Service National Engineering Handbook and the Modified Puls method of reservoir routing.

The peak outflow from the PMF is 3584 CFS, which overtops the dam for 4.75 hours at a maximum depth of 1.32 feet.

LAMBERT DAM (BLOUNT CO)

SUMMARY OF ROUTINGS

Spillway design flood	Antecedent Moisture Condition	
	AMC II	AMC III
PMF	Overtops by 1.32' for 4.75 hrs.	Overtops by 1.32' for 4.75 hrs.
$\frac{1}{2}$ PMF	Overtops by 0.65' for 3.00 hrs.	Overtops by 0.65' for 3.00 hrs.
100 YR	2.2 ' freeboard	1.6' freeboard

\*\*\*\*\*  
 FLOOD HYDROGRAPH PACKAGE (HSC-1)  
 DAM SAFETY VERSION JULY 1978  
 LAST MODIFICATION 01 APR 80  
 \*\*\*\*\*

1	A1	LAKE LAMBERT DAM							
2	A2	SAFE DAM INSPECTION AGENCY							
3	A3	MAY 1981 TNP							
4	B	0	15	0	0	0	0	0	0
5	B1	3	1						
6	J	1	.5						
7	J1	1	.14						
8	K	1							
9	K1	LOCAL RUNOFF COMPUTATION							
10	M	1	.732						
11	P	38.0	75	90					
12	T								
13	T2	1.18							
14	K	10	100						
15	K1	1	2						
16	K1	ROUTING COMPUTATION							
17	V								
18	V1	1							
19	V4	1059	1060	1061	1062	1063	1064	1064.5	
20	V5	0	42	102	138	262	543	743	
21	S8	330	357	379	400	422	443	456	
22	S4	1059	1060	1061	1062	1063	1064	1064.5	
23	S81061.0								
24	S01064.5	2.0	1.5	0.05					
25	K								

PREVIEW OF SEQUENCE OF STREAM NETWORK CALCULATIONS

RUNOFF HYDROGRAPH AT 1  
ROUTE HYDROGRAPH TO  
END OF NETWORK

\*\*\*\*\*  
 FLOOD HYDROGRAPH PACKAGE (HEC-01)  
 DAM SAFETY VERSION JULY 1978  
 LAST MODIFICATION BY RPN 80  
 \*\*\*\*\*

RUN DATE= 01/08/75.  
 TIME= 09.15.02.

LANE LEMBERT DAM  
 SAFE DAM INSPECTION ANCHIII  
 MAY 1981 IMP

NO NMR NMIN IOAV JOB SPECIFICATION  
 150 0 15 0 0 IMR IMIN METRC IFLT ISPT NSTAN  
 JOPER NMT LROPT TRACE  
 5 0 0 0

MULTI-PLAN ANALYSES TO BE PERFORMED  
 NPLAN= 1 NRTION= 3 LRTION= 1

RTION= 1.00 .50 .14

\*\*\*\*\*  
 SUB-AREA RUNOFF COMPUTATION  
 \*\*\*\*\*

LOCAL RUNOFF COMPUTATION

ISYAB ICOMP ISECON IYAPE JPLT JPRT INAME ISTAGE IAUTO  
 1 0 0 0 0 0 0 0 0 0 0

HYDROGRAPH DATA

IMVDS IUMG YAREA SNAP TRSDA TRSFC RATIO ISNGH ISAME LOCAL  
 1 2 .73 0.00 .73 1.00 0.000 0.00 0 0 0

PRECIP DATA

SPFE PMS R6 R12 R24 R48 R72 R96  
 0.00 30.00 75.00 90.00 100.00 0.00 0.00 0.00

LOSS DATA

LROPT STRAR DLTKR RTIOL ERAIN STRKS RTIOK STRTL CNSTL ALSHX RTIMP  
 0 0.00 0.00 1.00 0.00 0.00 1.00 -1.00 -88.00 0.00 0.00

CURVE NO = 000.00 WETNESS = -1.00 EFFECT CN = 66.00

UNIT HYDROGRAPH DATA  
 TCS 0.00 LAGS 1.18

RECESSION DATA  
 STRTOR 10.00 GRC5MB 100.00 RTIDRM 2.00

UNIT HYDROGRAPH 26 END OF PERIOD ORDINATES, TCS 0.00 HOURS, LAGS 1.18 VOLV 1.00  
 79. 166. 242. 270. 260. 224. 174. 120. 07.  
 45. 35. 26. 19. 18. 10. 7. 5. 8.

END-OF-PERIOD FLOW				END-OF-PERIOD FLOW				END-OF-PERIOD FLOW					
MO,DA	HR,MIN	PERIOD	RAIN	EXCS	LOSS	COMP Q	MO,DA	HR,MIN	PERIOD	RAIN	EXCS	LOSS	COMP U
1.01	1.15	1	.06	0.00	.06	9.	1.01	19.00	76	.10	.09	.00	1393.
1.01	1.30	2	.06	0.00	.06	9.	1.01	19.15	77	.10	.09	.00	1135.
1.01	1.45	3	.06	0.00	.06	8.	1.01	19.30	78	.10	.09	.00	904.
1.01	1.00	4	.06	0.00	.06	8.	1.01	19.45	79	.10	.09	.00	712.
1.01	1.15	5	.06	.00	.06	7.	1.01	20.00	80	.10	.09	.00	562.
1.01	1.30	6	.06	.01	.06	7.	1.01	20.15	81	.10	.09	.00	461.
1.01	1.45	7	.06	.01	.05	7.	1.01	20.30	82	.10	.09	.00	366.
1.01	2.00	8	.06	.02	.05	8.	1.01	20.45	83	.10	.09	.00	330.
1.01	2.15	9	.06	.02	.04	11.	1.01	21.00	84	.10	.09	.00	290.
1.01	2.30	10	.06	.02	.04	14.	1.01	21.15	85	.10	.09	.00	259.
1.01	2.45	11	.06	.03	.04	19.	1.01	21.30	86	.10	.09	.00	236.
1.01	3.00	12	.06	.03	.03	24.	1.01	21.45	87	.10	.09	.00	219.
1.01	3.15	13	.06	.03	.03	29.	1.01	22.00	88	.10	.09	.00	206.
1.01	3.30	14	.06	.03	.03	35.	1.01	22.15	89	.10	.09	.00	198.
1.01	3.45	15	.06	.03	.03	40.	1.01	22.30	90	.10	.09	.00	192.
1.01	4.00	16	.06	.04	.03	45.	1.01	22.45	91	.10	.09	.00	188.
1.01	4.15	17	.06	.04	.03	50.	1.01	23.00	92	.10	.09	.00	185.
1.01	4.30	18	.06	.04	.02	54.	1.01	23.15	93	.10	.09	.00	183.
1.01	4.45	19	.06	.04	.02	58.	1.01	23.30	94	.10	.09	.00	182.
1.01	5.00	20	.06	.04	.02	62.	1.01	23.45	95	.10	.09	.00	180.
1.01	5.15	21	.06	.04	.02	66.	1.02	0.00	96	.10	.09	.00	180.
1.01	5.30	22	.06	.04	.02	69.	1.02	.15	97	0.00	0.00	0.00	177.
1.01	5.45	23	.06	.04	.02	72.	1.02	.30	98	0.00	0.00	0.00	169.
1.01	6.00	24	.06	.05	.02	75.	1.02	.45	99	0.00	0.00	0.00	154.
1.01	6.15	25	.24	.18	.06	80.	1.02	1.00	100	0.00	0.00	0.00	131.
1.01	6.30	26	.24	.19	.05	93.	1.02	1.15	101	0.00	0.00	0.00	105.
1.01	6.45	27	.24	.19	.04	116.	1.02	1.30	102	0.00	0.00	0.00	95.
1.01	7.00	28	.24	.20	.04	154.	1.02	1.45	103	0.00	0.00	0.00	88.
1.01	7.15	29	.24	.20	.03	175.	1.02	2.00	104	0.00	0.00	0.00	82.
1.01	7.30	30	.24	.21	.03	256.	1.02	2.15	105	0.00	0.00	0.00	77.
1.01	7.45	31	.24	.21	.03	273.	1.02	2.30	106	0.00	0.00	0.00	72.
1.01	8.00	32	.24	.21	.02	304.	1.02	2.45	107	0.00	0.00	0.00	67.
1.01	8.15	33	.24	.22	.02	328.	1.02	3.00	108	0.00	0.00	0.00	62.
1.01	8.30	34	.24	.22	.02	347.	1.02	3.15	109	0.00	0.00	0.00	58.
1.01	8.45	35	.24	.22	.02	363.	1.02	3.30	110	0.00	0.00	0.00	54.
1.01	9.00	36	.24	.22	.02	375.	1.02	3.45	111	0.00	0.00	0.00	51.
1.01	9.15	37	.24	.22	.01	366.	1.02	4.00	112	0.00	0.00	0.00	47.
1.01	9.30	38	.24	.22	.01	394.	1.02	4.15	113	0.00	0.00	0.00	44.
1.01	9.45	39	.24	.23	.01	401.	1.02	4.30	114	0.00	0.00	0.00	41.
1.01	10.00	40	.24	.23	.01	407.	1.02	4.45	115	0.00	0.00	0.00	38.
1.01	10.15	41	.24	.23	.01	411.	1.02	5.00	116	0.00	0.00	0.00	38.
1.01	10.30	42	.24	.23	.01	415.	1.02	5.15	117	0.00	0.00	0.00	33.
1.01	10.45	43	.24	.23	.01	419.	1.02	5.30	118	0.00	0.00	0.00	31.
1.01	11.00	44	.24	.23	.01	422.	1.02	5.45	119	0.00	0.00	0.00	29.
1.01	11.15	45	.24	.23	.01	424.	1.02	6.00	120	0.00	0.00	0.00	27.
1.01	11.30	46	.24	.23	.01	426.	1.02	6.15	121	0.00	0.00	0.00	25.
1.01	11.45	47	.24	.23	.01	428.	1.02	6.30	122	0.00	0.00	0.00	24.
1.01	12.00	48	.24	.23	.01	430.	1.02	6.45	123	0.00	0.00	0.00	22.
1.01	12.15	49	.71	.69	.02	443.	1.02	7.00	124	0.00	0.00	0.00	21.
1.01	12.30	50	.71	.70	.02	461.	1.02	7.15	125	0.00	0.00	0.00	19.
1.01	12.45	51	.71	.70	.01	559.	1.02	7.30	126	0.00	0.00	0.00	18.
1.01	13.00	52	.71	.70	.01	672.	1.02	7.45	127	0.00	0.00	0.00	17.
1.01	13.15	53	.86	.84	.01	803.	1.02	8.00	128	0.00	0.00	0.00	16.
1.01	13.30	54	.86	.84	.01	937.	1.02	8.15	129	0.00	0.00	0.00	15.
1.01	13.45	55	.86	.85	.01	1066.	1.02	8.30	130	0.00	0.00	0.00	14.

TIME	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
1.01 14.00	56	.46	.01	1184.	1.02 6.45 131 0.00 0.00 0.00 13.
1.01 14.15	57	1.07	.01	1295.	1.02 9.00 132 0.00 0.00 0.00 12.
1.01 14.30	58	1.07	.01	1362.	1.02 9.15 133 0.00 0.00 0.00 11.
1.01 14.45	59	1.07	.01	1481.	1.02 9.30 138 0.00 0.00 0.00 10.
1.01 15.00	60	1.07	.01	1581.	1.02 9.45 135 0.00 0.00 0.00 10.
1.01 15.15	61	1.08	.01	1674.	1.02 10.00 136 0.00 0.00 0.00 9.
1.01 15.30	62	2.17	.01	1784.	1.02 10.15 137 0.00 0.00 0.00 8.
1.01 15.45	63	6.06	.02	2388.	1.02 10.30 136 0.00 0.00 0.00 8.
1.01 16.00	64	1.52	.00	2481.	1.02 10.45 139 0.00 0.00 0.00 7.
1.01 16.15	65	1.00	.00	3339.	1.02 11.00 140 0.00 0.00 0.00 7.
1.01 16.30	66	1.00	.00	3509.	1.02 11.15 141 0.00 0.00 0.00 6.
1.01 16.45	67	1.00	.00	3679.	1.02 11.30 142 0.00 0.00 0.00 6.
1.01 17.00	68	1.00	.00	3802.	1.02 11.45 143 0.00 0.00 0.00 6.
1.01 17.15	69	.78	.00	3349.	1.02 12.00 148 0.00 0.00 0.00 5.
1.01 17.30	70	.78	.00	2995.	1.02 12.15 145 0.00 0.00 0.00 5.
1.01 17.45	71	.78	.00	2828.	1.02 12.30 148 0.00 0.00 0.00 4.
1.01 18.00	72	.78	.00	2353.	1.02 12.45 147 0.00 0.00 0.00 4.
1.01 18.15	73	.70	.00	2130.	1.02 13.00 148 0.00 0.00 0.00 4.
1.01 18.30	74	.10	.00	1906.	1.02 13.15 149 0.00 0.00 0.00 4.
1.01 18.45	75	.10	.00	1836.	1.02 13.30 150 0.00 0.00 0.00 3.

SUM 36.00 36.41 1.59 69974.  
 (.965)(.925)(.40)(.1981.44)

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
3679.	2093.	720.	466.	69969.
104.	59.	20.	13.	1981.
26.80	38.58	37.05		37.05
675.55	929.10	941.04		941.04
1036.	1427.	1485.		1485.
1280.	1761.	1783.		1783.

HYDROGRAPH AT STA 1 FOR PLAN 1, RTIO 1

TIME	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
9.	8.	6.	7.	7.	8.
19.	29.	40.	45.	50.	54.
68.	72.	80.	93.	118.	158.
273.	304.	328.	374.	346.	394.
411.	419.	424.	428.	428.	430.
559.	672.	803.	1066.	1184.	1285.
1678.	1784.	2036.	3039.	3679.	3602.
2624.	2353.	1906.	1658.	1393.	1135.
461.	386.	330.	259.	238.	219.
180.	185.	183.	180.	177.	169.
105.	95.	88.	77.	72.	67.
51.	47.	44.	38.	36.	31.
23.	24.	22.	19.	18.	17.
13.	12.	11.	10.	9.	8.
8.	8.	5.	5.	4.	4.

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
3679.	2093.	720.	466.	69969.
104.	59.	20.	13.	1981.
26.60	36.58	37.05		37.05
675.55	929.10	941.04		941.04
1036.	1427.	1486.		1486.
1280.	1761.	1783.		1783.

HYDROGRAPH AT STA		1 FOR PLAN 1, RTIO 2						
		4	3	4	5	4	7	
5	4	20	23	27	29	27	31	
9	15	40	47	77	97	77	114	
33	16	181	168	197	200	197	203	
137	168	213	214	215	221	214	240	
208	209	412	502	643	740	643	791	
299	336	533	1519	1840	1674	1840	1498	
279	401	1231	829	568	356	568	282	
837	1019	953	130	103	99	103	86	
1312	1065	145	118	109	77	109	65	
231	165	90	85	85	77	85	65	
94	92	30	36	33	29	33	27	
53	41	19	18	16	15	16	14	
24	22	10	9	8	7	8	7	
13	11	5	4	4	4	4	3	
6	6	3	2	2	2	2	2	
3	3							
PEAK		24-HOUR	72-HOUR	TOTAL VOLUME				
CFS		360	233	36984				
CMS		10	7	991				
INCHES		13.30	16.52	16.52				
MM		337.78	470.52	470.52				
AC-FT		714	723	723				
THOUS CU M		880	892	892				

HYDROGRAPH AT STA		1 FOR PLAN 1, RTIO 3						
		1	1	1	2	1	4	
1	1	6	6	7	8	8	9	
3	4	11	13	17	22	27	33	
10	10	51	53	54	55	56	57	
43	49	59	60	60	62	62	67	
36	58	149	180	193	207	207	221	
58	112	425	491	515	504	469	414	
76	285	232	199	127	100	100	79	
236	329	81	36	28	28	27	27	
367	298	25	25	24	22	22	18	
65	58	12	10	9	8	8	6	
26	26	6	5	4	4	4	3	
19	13	3	3	2	2	2	2	
7	7	2	2	1	1	1	1	
4	3	1	1	1	1	1	1	
2	2	1	1	1	1	1	1	
1	1	1	1	1	1	1	1	
PEAK		24-HOUR	72-HOUR	TOTAL VOLUME				
CFS		101	65	9796				
CMS		3	2	277				
INCHES		3.72	5.12	5.12				
MM		96.58	131.07	131.75				
AC-FT		145	202	202				
THOUS CU M		179	250	250				

\*\*\*\*\*



ROUTING COMPUTATION

STAD	ICORP	IERON	ITAPP	JPLT	JPRP	ITAME	ISTAGE	IAUTO
1	1	1	0	1	0	1	0	0
ROUTING DATA								
CLASS	AVG	IPES	ISAME	IMPT	IPMP	LSIP		
0.0	0.00	1	1	0	0	0		
STPS	HSTII	LAG	AMSKK	Y	TSK	STORA	ISPRAT	
1	0	0	0.000	0.000	0.000	-1.	-1	
STAGE	1060.00	1061.00	1062.00	1063.00	1064.00	1064.50		
PLI	0.00	102.00	136.0	242.00	503.0	743.00		
CAPACITY	330.	379.	400.	422.	435.	454.		
ELEVATION	1059.	1060.	1062.	1063.	1064.	1065.		

CRREL SP=IN CQUM EXPM ELEV CQOL CAREA EXPL  
1061.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0

DAM DATA  
TOPEL CQUD EXPD DAMIN  
1064.5 2.6 1.5 605.

STATION 1, PLAN 1, RATIO 1

END-OF-PERIOD HYDROGRAPH ORDINATES

OUTFLOW		STORAGE	
1.	2.	1.	2.
0.	7.	337.	337.
3.	10.	339.	340.
16.	32.	347.	350.
20.	128.	349.	349.
74.	128.	374.	344.
215.	367.	424.	427.
430.	395.	403.	459.
481.	1427.	409.	477.
1730.	3485.	421.	472.
2764.	1046.	449.	470.
663.	858.	472.	438.
587.	265.	470.	418.
247.	207.	481.	417.
240.	200.	480.	404.
191.	132.	472.	337.
171.	135.	470.	340.
124.	108.	438.	357.
94.	73.	418.	360.
61.	46.	403.	409.
56.	46.	403.	432.
34.	32.	404.	465.
		404.	479.
		404.	482.
		404.	483.
		404.	485.
		404.	486.
		404.	487.
		404.	488.
		404.	489.
		404.	490.
		404.	491.
		404.	492.
		404.	493.
		404.	494.
		404.	495.
		404.	496.
		404.	497.
		404.	498.
		404.	499.
		404.	500.

374	394	376	386	381	390	384	392	381	379
375	375	373	375	371	379	370	368	367	366
385	384	383	382	381	380	384	380	381	380
350	350	355	354	354	353	352	352	351	351

STAGE

1059.0	1059.0	1059.0	1059.0	1059.0	1059.0	1059.0	1059.0	1059.0	1059.0	1059.1
1059.1	1059.1	1059.1	1059.1	1059.1	1059.1	1059.1	1059.1	1059.1	1059.1	1059.1
1059.2	1059.2	1059.2	1059.2	1059.2	1059.2	1059.2	1059.2	1059.2	1059.2	1059.2
1059.5	1059.5	1059.5	1059.5	1059.5	1059.5	1059.5	1059.5	1059.5	1059.5	1059.5
1060.3	1060.3	1060.3	1060.3	1060.3	1060.3	1060.3	1060.3	1060.3	1060.3	1060.3
1062.0	1062.0	1062.0	1062.0	1062.0	1062.0	1062.0	1062.0	1062.0	1062.0	1062.0
1063.0	1063.0	1063.0	1063.0	1063.0	1063.0	1063.0	1063.0	1063.0	1063.0	1063.0
1063.5	1063.5	1063.5	1063.5	1063.5	1063.5	1063.5	1063.5	1063.5	1063.5	1063.5
1065.0	1065.0	1065.0	1065.0	1065.0	1065.0	1065.0	1065.0	1065.0	1065.0	1065.0
1065.1	1065.1	1065.1	1065.1	1065.1	1065.1	1065.1	1065.1	1065.1	1065.1	1065.1
1065.4	1065.4	1065.4	1065.4	1065.4	1065.4	1065.4	1065.4	1065.4	1065.4	1065.4
1065.5	1065.5	1065.5	1065.5	1065.5	1065.5	1065.5	1065.5	1065.5	1065.5	1065.5
1064.1	1064.1	1064.1	1064.1	1064.1	1064.1	1064.1	1064.1	1064.1	1064.1	1064.1
1062.9	1062.9	1062.9	1062.9	1062.9	1062.9	1062.9	1062.9	1062.9	1062.9	1062.9
1062.4	1062.4	1062.4	1062.4	1062.4	1062.4	1062.4	1062.4	1062.4	1062.4	1062.4
1061.7	1061.7	1061.7	1061.7	1061.7	1061.7	1061.7	1061.7	1061.7	1061.7	1061.7
1060.9	1060.9	1060.9	1060.9	1060.9	1060.9	1060.9	1060.9	1060.9	1060.9	1060.9
1060.4	1060.4	1060.4	1060.4	1060.4	1060.4	1060.4	1060.4	1060.4	1060.4	1060.4
1060.3	1060.3	1060.3	1060.3	1060.3	1060.3	1060.3	1060.3	1060.3	1060.3	1060.3
1059.9	1059.9	1059.9	1059.9	1059.9	1059.9	1059.9	1059.9	1059.9	1059.9	1059.9

PEAK OUTFLOW IS 3641, AT TIME 17.00 HOURS

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
3641	2081	706	462	69267
103	59	20	13	1961
	26.45	55.87	36.68	36.68
	671.72	911.03	931.60	931.60
	1032	1400	1431	1431
	1273	1726	1765	1765

CFS  
CMS  
INCHES  
MM  
AC-FT  
TMOUS CU M

STATION 1, PLAN 1, RATIO 2  
END-OF-PERIOD HYDROGRAPH ORDINATES

0	1	1	1	1	1	1	1	1	1	1	1
2	3	4	5	6	7	8	9	10	11	12	13
10	11	12	13	14	15	16	17	18	19	20	21
28	33	44	51	59	68	73	80	86	93	102	109
133	142	167	111	115	118	122	125	129	134	141	148
640	716	835	830	872	904	931	956	971	984	994	1000
1408	1253	1133	1065	1025	997	971	946	922	899	877	856
445	389	336	293	259	230	210	192	176	161	147	134
141	172	155	146	141	136	130	125	120	115	110	104
124	126	123	121	119	115	112	109	107	104	102	99
101	97	93	89	85	81	78	74	71	68	65	62
65	62	59	57	54	52	49	45	43	41	38	36
41	40	39	37	36	34	33	32	31	30	29	28
24	24	24	24	24	24	23	22	21	21	21	21
330	330	330	330	330	330	330	330	330	330	330	330
337	337	337	337	337	337	337	337	337	337	337	337
340	340	340	340	340	340	340	340	340	340	340	340

9

355	355	345	343	340	345	346	373
370	342	341	346	344	340	390	395
377	410	410	425	410	425	435	440
453	460	463	466	463	467	468	4667
464	461	458	456	458	453	449	440
470	474	471	479	470	475	476	470
486	480	482	481	480	480	484	486
395	391	390	387	388	385	394	396
374	377	375	371	370	370	369	367
345	342	361	361	360	360	359	357
356	355	354	353	353	353	352	351
350	349	348	348	348	348	347	346

1059.0	1059.0	1059.0	1059.0	1059.0	1059.0	1059.0	1059.0
1059.1	1059.1	1059.1	1059.1	1059.1	1059.1	1059.2	1059.2
1059.2	1059.3	1059.3	1059.3	1059.4	1059.4	1059.5	1059.6
1059.7	1059.8	1060.0	1060.2	1060.3	1060.4	1060.6	1060.7
1060.8	1061.0	1061.2	1061.3	1061.4	1061.5	1061.6	1061.7
1061.0	1062.2	1062.5	1062.7	1063.0	1063.3	1063.6	1064.1
1064.3	1064.8	1064.7	1064.9	1065.1	1065.1	1065.1	1065.0
1065.0	1065.8	1064.7	1064.7	1064.5	1064.3	1064.1	1063.9
1063.7	1063.5	1063.1	1063.0	1062.9	1062.7	1062.5	1062.4
1062.3	1062.3	1062.1	1062.1	1062.0	1061.9	1061.9	1061.8
1061.7	1061.7	1061.6	1061.6	1061.4	1061.3	1061.1	1061.1
1061.0	1060.9	1060.8	1060.7	1060.7	1060.6	1060.5	1060.4
1060.4	1060.3	1060.3	1060.2	1060.2	1060.1	1060.1	1060.0
1059.9	1059.9	1059.9	1059.9	1059.8	1059.8	1059.8	1059.7
1059.7	1059.6	1059.6	1059.6	1059.6	1059.5	1059.5	1059.5

PEAK OUTFLOW IS 1021. AT TIME 17.00 HOURS

CFS	1821	1005	350	230	30494
CMS	52	28	10	7	977
INCHES	324.30	12.77	17.77	18.26	18.26
MM	220	451.43	463.63	463.63	463.93
AC-FT	615	693	713	713	713
THOUS CU M	615	855	879	879	879

STATION 1, PLAN 1, RATIO 3  
END-OF-PERIOD HYDROGRAPH OPD/NATFS

0.	0.	0.	0.	0.	0.	0.	0.
1.	1.	1.	1.	1.	2.	2.	2.
3.	3.	4.	4.	4.	5.	6.	7.
9.	11.	14.	15.	17.	18.	20.	21.
23.	26.	28.	29.	31.	32.	33.	34.
36.	38.	41.	42.	44.	46.	47.	48.
92.	100.	108.	123.	135.	148.	164.	180.
240.	304.	306.	288.	270.	243.	229.	213.
190.	143.	148.	142.	135.	128.	125.	121.
114.	112.	109.	106.	103.	95.	91.	87.
77.	70.	69.	69.	60.	60.	57.	54.
50.	47.	45.	45.	41.	38.	37.	35.

34.	33.	32.	31.	30.	29.	28.	27.	26.	25.	24.
23.	22.	21.	20.	19.	18.	17.	16.	15.	14.	13.
16.	15.	14.	13.	12.	11.	10.	9.	8.	7.	6.
330.	330.	330.	330.	330.	330.	330.	330.	330.	330.	330.
336.	336.	336.	336.	336.	336.	336.	336.	336.	336.	336.
337.	337.	337.	337.	337.	337.	337.	337.	337.	337.	337.
339.	339.	339.	339.	339.	339.	339.	339.	339.	339.	339.
341.	341.	341.	341.	341.	341.	341.	341.	341.	341.	341.
347.	347.	347.	347.	347.	347.	347.	347.	347.	347.	347.
354.	354.	354.	354.	354.	354.	354.	354.	354.	354.	354.
375.	375.	375.	375.	375.	375.	375.	375.	375.	375.	375.
424.	424.	424.	424.	424.	424.	424.	424.	424.	424.	424.
411.	411.	411.	411.	411.	411.	411.	411.	411.	411.	411.
346.	346.	346.	346.	346.	346.	346.	346.	346.	346.	346.
371.	371.	371.	371.	371.	371.	371.	371.	371.	371.	371.
361.	361.	361.	361.	361.	361.	361.	361.	361.	361.	361.
353.	353.	353.	353.	353.	353.	353.	353.	353.	353.	353.
348.	348.	348.	348.	348.	348.	348.	348.	348.	348.	348.
347.	347.	347.	347.	347.	347.	347.	347.	347.	347.	347.
344.	344.	344.	344.	344.	344.	344.	344.	344.	344.	344.

STORAGE

STAGE

1059.0	1059.0	1059.0	1059.0	1059.0	1059.0	1059.0	1059.0	1059.0	1059.0	1059.0
1059.0	1059.0	1059.0	1059.0	1059.0	1059.0	1059.0	1059.0	1059.0	1059.0	1059.0
1059.1	1059.1	1059.1	1059.1	1059.1	1059.1	1059.1	1059.1	1059.1	1059.1	1059.1
1059.2	1059.2	1059.2	1059.2	1059.2	1059.2	1059.2	1059.2	1059.2	1059.2	1059.2
1059.5	1059.5	1059.5	1059.5	1059.5	1059.5	1059.5	1059.5	1059.5	1059.5	1059.5
1059.6	1059.6	1059.6	1059.6	1059.6	1059.6	1059.6	1059.6	1059.6	1059.6	1059.6
1059.9	1059.9	1059.9	1059.9	1059.9	1059.9	1059.9	1059.9	1059.9	1059.9	1059.9
1060.0	1060.0	1060.0	1060.0	1060.0	1060.0	1060.0	1060.0	1060.0	1060.0	1060.0
1060.8	1060.8	1060.8	1060.8	1060.8	1060.8	1060.8	1060.8	1060.8	1060.8	1060.8
1061.0	1061.0	1061.0	1061.0	1061.0	1061.0	1061.0	1061.0	1061.0	1061.0	1061.0
1063.1	1063.1	1063.1	1063.1	1063.1	1063.1	1063.1	1063.1	1063.1	1063.1	1063.1
1062.5	1062.5	1062.5	1062.5	1062.5	1062.5	1062.5	1062.5	1062.5	1062.5	1062.5
1061.4	1061.4	1061.4	1061.4	1061.4	1061.4	1061.4	1061.4	1061.4	1061.4	1061.4
1060.7	1060.7	1060.7	1060.7	1060.7	1060.7	1060.7	1060.7	1060.7	1060.7	1060.7
1060.2	1060.2	1060.2	1060.2	1060.2	1060.2	1060.2	1060.2	1060.2	1060.2	1060.2
1059.8	1059.8	1059.8	1059.8	1059.8	1059.8	1059.8	1059.8	1059.8	1059.8	1059.8
1059.6	1059.6	1059.6	1059.6	1059.6	1059.6	1059.6	1059.6	1059.6	1059.6	1059.6
1059.4	1059.4	1059.4	1059.4	1059.4	1059.4	1059.4	1059.4	1059.4	1059.4	1059.4

PEAK INFLOW IS 300. AT TIME 18.25 HOURS

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
106.9	211.6	495.3	952.7	9527.0
CFS	CMS	INCHES	MM	AC-FT
106.9	6.0	2.68	0.815	128.14
THOUS CU H	105.0	189.0	241.0	197.0
	129.0	233.0	241.0	243.0

\*\*\*\*\*

WATER FLOW AND STORAGE (FOR PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS  
 FLOWS IN CUBIC FEET PER SECOND (LITRIC METERS PER SECOND)  
 AREA IN SQUARE FEET (SQUARE METERS)

OPERATION	STATION	AREA	PLAN RATIO 1	RATIO 2	RATIO 3	RATIO APPLIED TO FLOWS		
			1.00	.50		.14		
HYDROGRAPH AT	1	.73	1	3679	1000	515		
	(	1.00)	(	104.10)	(	52.09)	(	14.59)
PUMPING TO	1	.73	1	3041	1421	306		
	(	1.00)	(	103.10)	(	51.50)	(	4.67)

//

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1 .....

INITIAL VALUE	SPILLWAY CREST	TOP OF DAM
1050.00	1061.60	1064.50
336.	306.	454.
0.	131.	743.

ELEVATION STORAGE OUTFLOW	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLUM CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
1065.81	403.	3041.	6.25	17.00	0.00
1065.15	408.	1821.	3.50	17.00	0.00
1063.16	425.	306.	0.00	18.25	0.00

MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLUM CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
1.31	403.	3041.	6.25	17.00	0.00
.85	408.	1821.	3.50	17.00	0.00
0.00	425.	306.	0.00	18.25	0.00

.....  
 PUMP AND MOTOR MESSAGE (MAY 1961)  
 DAILY SAFETY INSPECTION JULY 1974  
 LIST IDENTIFIALLY AT LAFB AN  
 .....

LINE	AL	LAKE LAURENT DAM	SAFE	INSPECTION	AMCIT	U	U	U	U	U	U
1	41		MAY 1961								
2	42										
3	43										
4	44	150									
5	45	5									
6	46	1									
7	47	.5									
8	48	1									
9	49	1									
10	50										
11	51										
12	52										
13	53										
14	54										
15	55										
16	56										
17	57										
18	58										
19	59										
20	60										
21	61										
22	62										
23	63										
24	64										
25	65										

PREPARED BY SENGUO, CE OF SIMULAN NETWORK CALCULATIONS

MINUTE HYDROGRAPH AT 1  
ROUTE HYDROGRAPH TO 1  
END OF NETWORK

14

3



\*\*\*\*\*  
 FLOOD HYDROGRAPH PACKAGE (MCC-1)  
 DAM SAFETY VERSION JULY 1978  
 LAST MODIFICATION 01 APR 80  
 \*\*\*\*\*

RUN DATE: 01/08/25.  
 TIME: 0A.20.33.

LAKE LAMBERT DAM  
 SAFF DAM INSPECTION AMCTI  
 MAY 1981 TNP

NO. 150  
 IHR 0  
 NMTN 15  
 IDAY 0  
 JOPFN 5  
 IHR IMR IMIN MEIRC  
 0 0 0 0  
 NMT LRUPT TRACE  
 0 0 0 0

MULTI-PLAN ANALYSES TO BE PERFORMED  
 NPLANS 1 NRTIO 3 LRTIO 1

RTIUSE 1.00 .50 .11

\*\*\*\*\*  
 SUB-AREA RUNOFF COMPUTATION  
 \*\*\*\*\*

LOCAL RUNOFF COMPUTATION

ISTAQ 1 ICOMP 0 TECUN 0 ITAPE 0 JPLT 1 JPRT 0 INAME 1 ISTAGE 1 IAUTO 0

HYDROGRAPH DATA

IMYR 1 IUMI 2 TAMFA .73 SNAP 0.00 TRSC: 1RSPC MATIO 0.000 1SNOX 0 ASAME 0 LOCAL 0  
 .73 1.00 0.000

PRECIP DATA

SPEE 0.00 PMS 30.00 R6 75.00 R12 90.00 R24 100.00 P4R 0.00 R72 0.00 R96 0.00

LUSS DATA

LKOPT 0 STRKR 0.00 RTIUL 1.00 FRAIN 0.00 STRKS RTIUK STRIL CNSTL ALSHX RTIMP  
 0.00 0.00 0.00 0.00 1.00 -1.00 -75.00 0.00 0.00

CURVE NU = -75.00 WEYNES = -1.00 EFFECT CN = 75.00

UNIT HYDROGRAPH DATA

TCE 0.00 LAG= 1.18  
 SIPTDZ 10.00  
 PCESSION DATA  
 DMCSN 100.00 RTIURE 2.00

UNIT HYDROGRAPH 26 FLD OF PENTON ORIGINATES, TCE 0.00 HOURS, IACE 1.18 VOLE 1.00 87.  
 20. 74. 100. 242. 270. 274. 274. 174. 120. 5.  
 25. 35. 10. 14. 10. 7. 5. 4.

15

MO, DA	HR, MN	PERIOD	RATN	EXCS	LOSS	END-OF-PERIOD FLOW	MO, DA	HR, MN	PERIOD	RAIN	EXCS	LUSS	COMP O
1.01	1.15	1	.00	0.00	.10	9.	1.01	19.00	76	.10	.09	.00	1300.
1.01	1.30	2	.00	0.00	.00	9.	1.01	19.15	77	.10	.09	.00	1125.
1.01	1.45	3	.00	0.00	.00	8.	1.01	19.30	78	.10	.09	.00	896.
1.01	1.00	4	.00	0.00	.00	8.	1.01	19.45	79	.10	.09	.00	706.
1.01	1.15	5	.00	0.00	.00	7.	1.01	20.00	80	.10	.09	.00	500.
1.01	1.30	6	.00	0.00	.00	7.	1.01	20.15	81	.10	.09	.00	450.
1.01	1.45	7	.00	0.00	.00	6.	1.01	20.30	82	.10	.09	.00	303.
1.01	2.00	8	.00	0.00	.00	6.	1.01	20.45	83	.10	.09	.00	320.
1.01	2.15	9	.00	0.00	.00	5.	1.01	21.00	84	.10	.09	.00	200.
1.01	2.30	10	.00	0.00	.00	5.	1.01	21.15	85	.10	.09	.00	258.
1.01	2.45	11	.00	0.00	.00	5.	1.01	21.30	86	.10	.09	.00	235.
1.01	3.00	12	.00	0.00	.00	4.	1.01	21.45	87	.10	.09	.00	210.
1.01	3.15	13	.00	0.00	.00	4.	1.01	22.00	88	.10	.09	.00	205.
1.01	3.30	14	.00	0.00	.00	5.	1.01	22.15	89	.10	.09	.00	197.
1.01	3.45	15	.00	0.00	.00	6.	1.01	22.30	90	.10	.09	.00	191.
1.01	4.00	16	.00	0.00	.00	7.	1.01	22.45	91	.10	.09	.00	187.
1.01	4.15	17	.00	0.00	.00	9.	1.01	23.00	92	.10	.09	.00	184.
1.01	4.30	18	.00	0.00	.00	12.	1.01	23.15	93	.10	.09	.00	180.
1.01	4.45	19	.00	0.00	.00	14.	1.01	23.30	94	.10	.09	.00	180.
1.01	5.00	20	.00	0.00	.00	17.	1.01	23.45	95	.10	.09	.00	179.
1.01	5.15	21	.00	0.00	.00	20.	1.02	0.00	96	.00	.00	.00	179.
1.01	5.30	22	.00	0.00	.00	23.	1.02	.15	97	.00	.00	.00	176.
1.01	5.45	23	.00	0.00	.00	26.	1.02	.30	98	.00	.00	.00	168.
1.01	6.00	24	.00	0.00	.00	29.	1.02	.45	99	.00	.00	.00	153.
1.01	6.15	25	.00	0.00	.00	33.	1.02	1.00	100	.00	.00	.00	130.
1.01	6.30	26	.00	0.00	.00	42.	1.02	1.15	101	.00	.00	.00	104.
1.01	6.45	27	.00	0.00	.00	50.	1.02	1.30	102	.00	.00	.00	95.
1.01	7.00	28	.00	0.00	.00	61.	1.02	1.45	103	.00	.00	.00	88.
1.01	7.15	29	.00	0.00	.00	100.	1.02	2.00	104	.00	.00	.00	82.
1.01	7.30	30	.00	0.00	.00	150.	1.02	2.15	105	.00	.00	.00	77.
1.01	7.45	31	.00	0.00	.00	167.	1.02	2.30	106	.00	.00	.00	72.
1.01	8.00	32	.00	0.00	.00	194.	1.02	2.45	107	.00	.00	.00	67.
1.01	8.15	33	.00	0.00	.00	217.	1.02	3.00	108	.00	.00	.00	62.
1.01	8.30	34	.00	0.00	.00	258.	1.02	3.15	109	.00	.00	.00	58.
1.01	8.45	35	.00	0.00	.00	257.	1.02	3.30	110	.00	.00	.00	54.
1.01	9.00	36	.00	0.00	.00	273.	1.02	3.45	111	.00	.00	.00	51.
1.01	9.15	37	.00	0.00	.00	288.	1.02	4.00	112	.00	.00	.00	47.
1.01	9.30	38	.00	0.00	.00	301.	1.02	4.15	113	.00	.00	.00	44.
1.01	9.45	39	.00	0.00	.00	312.	1.02	4.30	114	.00	.00	.00	41.
1.01	10.00	40	.00	0.00	.00	323.	1.02	4.45	115	.00	.00	.00	38.
1.01	10.15	41	.00	0.00	.00	320.	1.02	5.00	116	.00	.00	.00	36.
1.01	10.30	42	.00	0.00	.00	340.	1.02	5.15	117	.00	.00	.00	33.
1.01	10.45	43	.00	0.00	.00	340.	1.02	5.30	118	.00	.00	.00	31.
1.01	11.00	44	.00	0.00	.00	350.	1.02	5.45	119	.00	.00	.00	29.
1.01	11.15	45	.00	0.00	.00	360.	1.02	6.00	120	.00	.00	.00	27.
1.01	11.30	46	.00	0.00	.00	360.	1.02	6.15	121	.00	.00	.00	25.
1.01	11.45	47	.00	0.00	.00	371.	1.02	6.30	122	.00	.00	.00	24.
1.01	12.00	48	.00	0.00	.00	370.	1.02	6.45	123	.00	.00	.00	22.
1.01	12.15	49	.00	0.00	.00	371.	1.02	7.00	124	.00	.00	.00	21.
1.01	12.30	50	.00	0.00	.00	400.	1.02	7.15	125	.00	.00	.00	19.
1.01	12.45	51	.00	0.00	.00	503.	1.02	7.30	126	.00	.00	.00	18.
1.01	13.00	52	.00	0.00	.00	611.	1.02	7.45	127	.00	.00	.00	17.
1.01	13.15	53	.00	0.00	.00	730.	1.02	8.00	128	.00	.00	.00	16.
1.01	13.30	54	.00	0.00	.00	805.	1.02	8.15	129	.00	.00	.00	15.
1.01	13.45	55	.00	0.00	.00	912.	1.02	8.30	130	.00	.00	.00	14.

AD-A108 252

TENNESSEE STATE DEPT OF CONSERVATION NASHVILLE DIV 0--ETC F/G 13/13  
NATIONAL PROGRAM OF INSPECTION OF NON-FEDERAL DAMS, TENNESSEE, --ETC(U)  
SEP 81 P F BLUMM DACW62-81-C-0056


UNCLASSIFIED

NL

2 2


END  
DATE  
FILMED  
1 82  
DTIC

END  
DATE  
FILMED  
1 82  
DTIC



MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A

1.01	14.00	54	1.46	.04	11.44	1.02	8.45	131	0.00	0.00	0.00	13.
1.01	14.15	57	1.07	.04	12.11	1.02	9.00	132	0.00	0.00	0.00	12.
1.01	14.30	58	1.07	.03	13.09	1.02	9.15	133	0.00	0.00	0.00	11.
1.01	14.45	59	1.07	.03	14.11	1.02	9.30	134	0.00	0.00	0.00	10.
1.01	14.60	60	1.07	.03	15.14	1.02	9.45	135	0.00	0.00	0.00	10.
1.01	14.75	61	1.04	.03	16.10	1.02	10.00	136	0.00	0.00	0.00	9.
1.01	14.90	62	2.12	.05	17.23	1.02	10.15	137	0.00	0.00	0.00	8.
1.01	15.05	63	6.06	1.10	19.74	1.02	10.30	138	0.00	0.00	0.00	8.
1.01	15.20	64	1.52	.02	20.01	1.02	10.45	139	0.00	0.00	0.00	7.
1.01	15.35	65	1.00	.01	20.76	1.02	11.00	140	0.00	0.00	0.00	7.
1.01	15.50	66	1.00	.01	30.45	1.02	11.15	141	0.00	0.00	0.00	6.
1.01	15.65	67	1.00	.01	31.19	1.02	11.30	142	0.00	0.00	0.00	6.
1.01	15.80	68	1.00	.01	33.44	1.02	11.45	143	0.00	0.00	0.00	6.
1.01	15.95	69	.78	.01	33.22	1.02	12.00	144	0.00	0.00	0.00	5.
1.01	16.10	70	.78	.01	25.56	1.02	12.15	145	0.00	0.00	0.00	5.
1.01	16.25	71	.74	.01	25.93	1.02	12.30	146	0.00	0.00	0.00	5.
1.01	16.40	72	.78	.01	22.27	1.02	12.45	147	0.00	0.00	0.00	4.
1.01	16.55	73	.10	.00	21.04	1.02	13.00	148	0.00	0.00	0.00	4.
1.01	16.70	74	.10	.00	18.04	1.02	13.15	149	0.00	0.00	0.00	4.
1.01	16.85	75	.10	.00	16.43	1.02	13.30	150	0.00	0.00	0.00	3.

SUM 30.00 34.27 3.73 85939.  
 (95.)(871.)(95.)(1067.10)

CFR	3619.	6-MOHR	24-MOHR	72-MOHR	TOTAL VOLUME
CMS	102.	2044.	681.	440.	65930.
INCMPS		58.	19.	12.	1867.
MM		25.97	36.61	34.91	34.91
ACFT		659.69	879.01	866.72	866.72
THOUS CU H		1013.	1350.	1367.	1362.
		1250.	1664.	1680.	1680.

HYDROGRAPH AT STA 1 FOR PLAN 1, RTIN 1

9.	6.	7.	6.	6.	5.
4.	5.	7.	9.	12.	17.
23.	29.	42.	58.	81.	138.
104.	230.	273.	288.	301.	323.
308.	354.	366.	371.	376.	428.
736.	845.	992.	1108.	1309.	1514.
1976.	2401.	2476.	3485.	3619.	2956.
2327.	1686.	1643.	1340.	696.	560.
393.	228.	235.	1125.	706.	706.
458.	180.	179.	176.	197.	191.
104.	82.	77.	67.	153.	130.
65.	41.	36.	33.	58.	54.
47.	21.	19.	17.	29.	27.
24.	11.	10.	9.	15.	14.
12.	6.	5.	4.	7.	7.
6.	5.	4.	4.	4.	3.

CFR	3619.	6-MOHR	24-MOHR	72-MOHR	TOTAL VOLUME
CMS	102.	2044.	681.	440.	65930.
INCMPS		58.	19.	12.	1867.
MM		25.97	36.61	34.91	34.91
ACFT		659.69	879.01	866.72	866.72
THOUS CU H		1013.	1350.	1367.	1362.
		1250.	1664.	1680.	1680.

HYDROGRAPH AT STA 1 FOR PLAN 1, RTIN 2

TIME	0-MOON	24-MOON	72-MOON	TOTAL VOLUME
3.	4.	4.	3.	3.
6.	13.	17.	21.	9.
9.	109.	129.	144.	69.
10.	174.	180.	186.	150.
11.	306.	433.	554.	161.
12.	506.	1480.	1723.	214.
13.	844.	221.	290.	757.
14.	1164.	621.	690.	1474.
15.	191.	129.	117.	280.
16.	224.	144.	109.	90.
17.	304.	90.	80.	65.
18.	44.	36.	36.	27.
19.	24.	19.	18.	14.
20.	12.	10.	9.	7.
21.	6.	5.	4.	3.
22.	3.	2.	2.	2.

PEAK 1810.  
 CFS 1022.  
 CWS 29.  
 INCMFS 12.99  
 THOUS CU M 32965.  
 AC=FT 439.51  
 507  
 681.  
 840.

HYDROGRAPH AT STA 1 FOR PLAN 1, RTIN 3

TIME	6-MOON	24-MOON	72-MOON	TOTAL VOLUME
1.	1.	1.	1.	1.
2.	1.	1.	1.	3.
3.	3.	4.	5.	12.
4.	24.	24.	30.	15.
5.	39.	40.	40.	39.
6.	61.	109.	80.	43.
7.	218.	177.	122.	167.
8.	232.	161.	152.	325.
9.	32.	28.	26.	78.
10.	20.	20.	20.	62.
11.	9.	6.	7.	21.
12.	5.	4.	4.	14.
13.	2.	2.	2.	6.
14.	1.	1.	1.	3.
15.	1.	1.	0.	2.
16.	1.	1.	0.	1.
17.	1.	1.	0.	0.

PEAK 348.  
 CFS 225.  
 CWS 6.  
 INCMFS 2.40  
 THOUS CU M 7652.  
 AC=FT 72.57  
 111.  
 149.  
 183.

.....

HYDROGRAPH AT STA 1 FOR PLAN 1, RTIN 3

.....



RELATIVE COMPUTATION

STAGE	1059.00	1060.00	1061.00	1062.00	1063.00	1064.00	1064.50
FLOW	0.00	42.00	102.00	136.00	262.00	543.00	743.00
CAPACITY	330.	357.	379.	400.	422.	483.	450.
ELEVATIONS	1059.	1060.	1061.	1062.	1063.	1064.	1065.

CPFL SPWID COUM EXPH FLEVL COOL CAREA EXPL  
 1061.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0

DAM DATA  
 TUPEL COUM EXPD DAMWID  
 1060.5 2.4 1.5 605.

STATION 1, PLAN 1, PLYTO 1

END-OF-PERIOD HYDROGRAPH ORDINATES

STATION	0.	1.	2.	3.	4.	5.	6.	7.	8.	9.	10.	11.	12.	13.	14.	15.	16.	17.	18.	19.	20.	21.	22.	23.	24.	25.	26.	27.	28.	29.	30.	31.	32.	33.	34.	35.	36.	37.	38.	39.	40.	41.	42.	43.	44.	45.	46.	47.	48.	49.	50.
OUTFLOW	0.	1.	2.	3.	4.	5.	6.	7.	8.	9.	10.	11.	12.	13.	14.	15.	16.	17.	18.	19.	20.	21.	22.	23.	24.	25.	26.	27.	28.	29.	30.	31.	32.	33.	34.	35.	36.	37.	38.	39.	40.	41.	42.	43.	44.	45.	46.	47.	48.	49.	50.
STORAGE	0.	1.	2.	3.	4.	5.	6.	7.	8.	9.	10.	11.	12.	13.	14.	15.	16.	17.	18.	19.	20.	21.	22.	23.	24.	25.	26.	27.	28.	29.	30.	31.	32.	33.	34.	35.	36.	37.	38.	39.	40.	41.	42.	43.	44.	45.	46.	47.	48.	49.	50.

350.	351.	352.	353.	354.	355.	356.	357.	358.	359.	360.	361.	362.	363.	364.	365.	366.	367.	368.	369.	370.
1059.0	1059.0	1059.0	1059.0	1059.0	1059.0	1059.0	1059.0	1059.0	1059.0	1059.0	1059.0	1059.0	1059.0	1059.0	1059.0	1059.0	1059.0	1059.0	1059.0	1059.0
1059.1	1059.1	1059.1	1059.1	1059.1	1059.1	1059.1	1059.1	1059.1	1059.1	1059.1	1059.1	1059.1	1059.1	1059.1	1059.1	1059.1	1059.1	1059.1	1059.1	1059.1
1059.2	1059.2	1059.2	1059.2	1059.2	1059.2	1059.2	1059.2	1059.2	1059.2	1059.2	1059.2	1059.2	1059.2	1059.2	1059.2	1059.2	1059.2	1059.2	1059.2	1059.2
1059.3	1059.3	1059.3	1059.3	1059.3	1059.3	1059.3	1059.3	1059.3	1059.3	1059.3	1059.3	1059.3	1059.3	1059.3	1059.3	1059.3	1059.3	1059.3	1059.3	1059.3
1059.4	1059.4	1059.4	1059.4	1059.4	1059.4	1059.4	1059.4	1059.4	1059.4	1059.4	1059.4	1059.4	1059.4	1059.4	1059.4	1059.4	1059.4	1059.4	1059.4	1059.4
1059.5	1059.5	1059.5	1059.5	1059.5	1059.5	1059.5	1059.5	1059.5	1059.5	1059.5	1059.5	1059.5	1059.5	1059.5	1059.5	1059.5	1059.5	1059.5	1059.5	1059.5
1059.6	1059.6	1059.6	1059.6	1059.6	1059.6	1059.6	1059.6	1059.6	1059.6	1059.6	1059.6	1059.6	1059.6	1059.6	1059.6	1059.6	1059.6	1059.6	1059.6	1059.6
1059.7	1059.7	1059.7	1059.7	1059.7	1059.7	1059.7	1059.7	1059.7	1059.7	1059.7	1059.7	1059.7	1059.7	1059.7	1059.7	1059.7	1059.7	1059.7	1059.7	1059.7
1059.8	1059.8	1059.8	1059.8	1059.8	1059.8	1059.8	1059.8	1059.8	1059.8	1059.8	1059.8	1059.8	1059.8	1059.8	1059.8	1059.8	1059.8	1059.8	1059.8	1059.8
1059.9	1059.9	1059.9	1059.9	1059.9	1059.9	1059.9	1059.9	1059.9	1059.9	1059.9	1059.9	1059.9	1059.9	1059.9	1059.9	1059.9	1059.9	1059.9	1059.9	1059.9
1060.0	1060.0	1060.0	1060.0	1060.0	1060.0	1060.0	1060.0	1060.0	1060.0	1060.0	1060.0	1060.0	1060.0	1060.0	1060.0	1060.0	1060.0	1060.0	1060.0	1060.0

PEAK UNIFLOW IS 3500. AT TIME 17.00 HOURS

PEAK	6-MOHR	24-MOHR	72-MOHR	TOTAL	VOLUME
3584.	2046.	684.	235.	65230.	1087.
101.	57.	14.	12.	34.54	677.30
	45.75	33.03	54.94	1348.	1002.
	633.95	661.86	877.30	1000.1	1059.7
	1005.	1324.	1344.	1000.0	1059.7
	1239.	1633.	1662.	1059.8	1059.7

CFS  
CMS  
INMFS  
MM  
AC-FT  
THOUS CU H

STATION 1. PLAN 1. RATIO 2

END-OF-PERIOD HYDROGRAPH ORDINATES

OUTFLOW	STORAGE
1.	330.
1.	337.
1.	337.
1.	330.
4.	336.
20.	336.
70.	330.
134.	330.
134.	337.
970.	330.
1301.	337.
408.	336.
250.	330.
147.	337.
116.	337.
115.	330.
115.	337.
115.	330.
61.	337.
54.	330.
54.	337.
36.	330.
36.	337.
25.	330.
25.	337.







PEAK FLOW AND STORAGE (FWD OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS  
 FLOWS IN CURRIC FEET PER SECOND (CUBIC METERS PER SECOND)  
 AREA IN SQUARE FEET (SQUARE METERS)

OPERATOR	STATION	AREA	PLAN RATIO 1	RATIO 2	RATIO 3	RATIO APPLIED TO FLOWS
			1.00	.50	.11	
HYDROGRAPH AT	1	.73				
	(	1.00)	1	3019.	1810.	500.
			(	102.00)	51.24)	11.27)
ROUTED TO	1	.73				
	(	1.00)	1	3500.	1702.	191.
			(	101.50)	50.75)	5.41)

22

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1 .....

RATIO OF P/F	ELEVATION STORAGE OUTFLOW	INITIAL VALUE	SPILLWAY CREST	TOP OF DAM	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE ACFT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
.50	336	336	396	454	.63	404	1702	5.25	17.00	0.00
.11	0	0	111	143	0.00	409	191	0.00	18.75	0.00

**APPENDIX G**  
**CORRESPONDENCE**



**DEPARTMENT OF THE ARMY**  
**NASHVILLE DISTRICT, CORPS OF ENGINEERS**  
P. O. BOX 1070  
NASHVILLE, TENNESSEE 37202

IN REPLY REFER TO

ORNE-D

13 March 1981

Keith McCord  
Route #7  
Maryville, Tenn. 37801

Dear Mr. McCord:

As provided under authority of the National Dam Inspection Act, Public Law 92-367, all non-Federal dams in Tennessee must be inspected for the purpose of protecting human life and property. According to our records, you are the owner of Lamert Dam, located in Blount County, Tennessee.

An inspection of this dam is scheduled for 21-23 April, 1981. Engineers from the Engineering Division of the U.S. Army Corps of Engineers in conjunction with the Tennessee Division of Water Resources will conduct the inspection. As the owner we encourage your participation in the inspection. Following this inspection a report will be prepared and a copy forwarded to you.

If there are any questions or a need for additional information, please contact Mr. Paul Bluhm or Mr. Timothy McCleskey at 615/251-7366.

Sincerely,


E.C. MOORE  
Chief, Engineering Division


ORNED-G


NON-FEDERAL DAM INSPECTION REVIEW BOARD  
PO BOX 1070  
NASHVILLE, TENNESSEE 37202


Commander, Nashville District  
US Army Corps of Engineers  
PO Box 1070  
Nashville, TN 37202


1. The Interagency Review Board, appointed by the Commander on 19 June 1981, presents the following recommendations after meeting on 27 August 1981, to consider the Phase I investigation report on Lambert Dam located near Maryville, Tennessee.
2. The toe drains should be periodically checked for deposition of material. If significant deposition is occurring, the owner should engage the services of a qualified engineer to determine the cause of the deposition.
3. Recommendation c. should be changed to allow cattle grazing on the dam; this grazing should be controlled to minimize damage to the embankment.
4. The progression of the erosion of the wave berm should be periodically checked.
5. The Board is in agreement with other report conclusions and recommendations following minor revisions.


  
FRANK B. COUCH, JR.  
Chief, Geotechnical Branch  
Chairman

  
BOBBY G. MOORE  
Assistant State Conservation Engineer  
Alternate, Soil Conservation Service

  
EDMOND B. O'NEILL  
Alternate, Division of Water Resources  
State of Tennessee

  
THOMAS ALLEN  
Hydraulic Engineer  
Alternate, Hydrology and Hydraulics  
Branch

  
EDWARD B. BOYD  
Hydrologic Technician  
Alternate, US Geological Survey

  
JAMES GUNNELS  
Structural Engineer  
Alternate, Design Branch



DEPARTMENT OF THE ARMY  
NASHVILLE DISTRICT, CORPS OF ENGINEERS  
P. O. BOX 1070  
NASHVILLE, TENNESSEE 37202

IN REPLY REFER TO

11 AUG 1981

ORNED-G

SUBJECT: Report of Phase I Investigation of Lambert Dam, Maryville, Tennessee.

Commander, Ohio River Division  
ATTN: ORDED-T (Griff Ray)

1. Inclosed are three copies of our draft report covering the Phase I investigation of Lambert Dam in Blount County, Tennessee.
2. The report is still in draft form at this time. Request return of copy containing color photographs along with your comments. We will furnish you a final version of the report when it is completed.

FOR THE COMMANDER:

A handwritten signature in cursive script, appearing to read "E. C. Moore".

E. C. MOORE  
Chief, Engineering Division

1 Incl  
as



CPMED

NASH. DIST.  
U.S.A.  
CORPS. OF ENG

SEP 3 1 20 PM '81

SAENGDIST WVL

P 231647Z SEPT 81  
FM CDR USAEDON CINCINNATI OH //ORDED-T//  
TO CDR USAED NASHVILLE TN //ORDED-3//

BT  
UNCLAS

SUBJ: PHASE I INSPECTION REPORT, LANBERT DAM, BLOUNT COUNTY,  
TENNESSEE THE INSPECTION REPORT AND RECOMMENDATIONS ARE  
SATISFACTORY SUBJECT TO THE FOLLOWING COMMENTS.

- A. THE REPORT SHOULD RECOMMEND THAT THE EMERGENCY DISCHARGE GATE SHOULD BE PERIODICALLY OPERATED TO INSURE THAT IT IS FUNCTIONAL AND CAN BE RELIED UPON IN CASE OF AN EMERGENCY SUCH AS THE ONE IN OCTOBER 1963.
- B. CONCUR WITH THE RECOMMENDATIONS TO REINSPECT THE DAM DURING A DRY PERIOD TO DETERMINE IF THE WET SPOTS ON THE DOWNSTREAM ABUTMENT SLOPE ARE A RESULT OF SURFACE WATER OR THROUGH SEEPAGE. THE RECOMMENDATIONS SHOULD, HOWEVER, BE EXPANDED TO STATE THAT IF SUCH AN INSPECTION DOES NOT CONFIRM THE JETNESS TO BE THE RESULT OF PRECIPITATION, THE OWNER SHOULD HAVE THE STABILITY OF STRUCTURE REVIEWED BY A QUALIFIED ENGINEER.
- C. APPENDIX F, PAGE 1. THE POP CANNOT BE OBTAINED FROM TP 40 AND THE NUMERICAL VALUES FOR DEPTH OF OVERTOPPING AND DURATION OF OVERTOPPING APPEAR TO BE TRANSPOSED. APPROPRIATE CHANGES SHOULD BE MADE.

BT  
UNCLAS

SENT 1 PLS ACK TJ  
UNCLAS WVL  
P

DIST ENGR	COMPT	EEO	ADMIN SVC	CONST
DEP DE	AUDIT	PAO	PROG DEV	ENG
DEP DE TTW	ADP	COUNSEL	PERS	OPER
EX ASST	SEC MGR	SAFETY	PROC & SUP	

ORNED-G (11 Aug 1981) 2d Ind

SUBJECT: Report of Phase I Investigation of Lambert Dam, Maryville, Tennessee

DA, Nashville District, Corps of Engineers, PO Box 1070, Nashville,  
Tennessee 37202

TO: Commander, Ohio River Division, ATTN: ORDED-T (Griff Ray)

1. 1st Indorsement, paragraph A. Concur. This recommendation has been added to the report.
2. 1st Indorsement, paragraph B. Concur. This recommendation has been added to the report.
3. 1st Indorsement, paragraph C. The PMP can be obtained from TP 40. This has been resolved by telephone between Tom Porter, Hydrology and Hydraulics Branch, Nashville District, and Tom Liggitt, Hydrology Section, Ohio River Division.

An error was made in computing the depth and duration of overtopping in the preliminary report, but the correct values are present in the final report. There was a significant change in these values which resulted in a change in the condition classification from "unsafe-nonemergency" to "significantly deficient." See attached sheet for definitions of these terms. It was felt that the depth and duration of overtopping was not enough to cause failure of the dam and, therefore, should be called significantly deficient.

FOR THE COMMANDER:

1 Incl  
as



E. C. MOORE

Chief, Engineering Division

*FR*

## DEFINITION OF CONDITION CLASSIFICATION

"Unsafe - Emergency" - A dam in a state of imminent failure. State and local authorities and downstream residents should be advised immediately. Downstream residents may have to be evacuated, remedial work should begin immediately, the reservoir should be drawn down or drained, or combination of the above (e.g., advanced piping, major slope instability, recent sudden collapse of a portion of the foundation, imminent overtopping, etc.).

"Unsafe - Nonemergency" - A dam with obviously serious deficiencies which could clearly and rapidly develop, or are developing, into failure modes, but do not yet pose the threat of imminent failure. State and local authorities should be advised promptly and remedial work should begin as soon as practical. Someone should be assigned to periodically check on the dam's condition until remedial work is begun. Drawing down the reservoir should be considered, (e.g., flowing seepage from embankment which could lead to piping, evidence of solution channels or cavitation in the foundation, seriously inadequate spillway capacity as per ETL 1110-2-234, history of recurring slope instability, etc.).

"Significantly Deficient" - A dam with deficiencies which, if left unchecked, would likely become serious deficiencies and could ultimately result in failure. Advise State authorities and recommend remedial work be scheduled in time to prevent substantial further deterioration of the condition(s) - usually within 6 months to a year or sooner (e.g., heavy growth of sizeable trees on slopes, potentially serious erosion, spillway discharge channel too close to embankment, etc.).

"Deficient" - A dam with deficiencies which need attention, but which would not likely affect the safety of the dam unless left unchecked for a long period of time. Advise State authorities and recommend remedial action at owner's convenience, but before problem can escalate into a significant deficiency (e.g., brush and/or few or very small trees on embankment, long term deterioration of masonry or metal outlet features, formation of deep ruts in embankment roadway, deterioration of riprap, etc.).

"Not Deficient" - Well constructed and maintained dam with no apparent deficiencies relative to its safety and structural integrity.

**APPENDIX H**  
**PREVIOUS INVESTIGATIONS**

UNITED STATES GOVERNMENT

## Memorandum

TENNESSEE VALLEY AUTHORITY

HYDRAULIC DATA BRANCH
Rec'd NOV 6 1963
File No. 110-923
W.B. - 11 Larkin

TO : Edwin H. McGain

FROM : William P. Clark

DATE : October 18, 1963

SUBJECT: LAMBERT DAM FAILURE - BLOUNT COUNTY, TENNESSEE

On October 17, 1963, a field investigation was made of the subject dam which had failed on October 12. This investigation was made to try to determine the cause or causes of this failure.

No visible signs could be found that would indicate that muskrats had been working in the dam fill in the vicinity of the wash out or elsewhere for that matter. The soil in the lake area appeared to be very conducive for crawfish but no signs of these were found either.

The concrete pipe, 24-inch concrete, which formed the spillway discharge culvert showed no visible signs that seepage rings had existed on this pipe, neither were any seep rings found among the various pieces of pipe scattered below the dam. The pipe had been laid on a concrete cradle throughout the width of the dam but again there were no signs of seep rings on these portions of the cradle that were found washed out and/or still in place.

The morning glory type of spillway entrance to the 24-inch pipe consisted of a vertical square concrete box, constructed in sections, which sections appeared to have not been banded together. There was no means of controlling the discharge through this spillway, the discharge varying according to reservoir height over the intake.

There was no other spillway other than the one mentioned above. However, there did exist through the dam, a 6-inch pipe with a screened inlet on the lake end and a valve at the downstream end. This pipe was used to furnish water for irrigation purposes. From talking with the farm manager, Mr. Hoffstetter, the 6-inch pipe was at an elevation approximately 10 feet higher than the 24-inch pipe.

The first leakage was noticed on the downstream side of the fill at an elevation about 10 feet higher than the 24-inch pipe, however, the farm manager could not remember whether or not it was at or near the 6-inch pipe outlet.

In summing up the possible causes of the dam failure, it appears that it could have been any of the following reasons or a combination of them:

- (1) Settlement of the earth fill could have broken the 6-inch pipe at a joint or joints, causing water to seep out into the earth fill. (The water in this pipe being under pressure at all times, since the valve was on the outlet end.)

UNITED STATES GOVERNMENT

# Memorandum

TENNESSEE VALLEY AUTHORITY

-2-

TO : Edwin H. McCain

FROM : William P. Clark

DATE : October 18, 1963

SUBJECT: LAMBERT DAM FAILURE - BLOUNT COUNTY, TENNESSEE

- (2) Settlement could have caused a break in the 24-inch concrete pipe creating a leak in it.
- (3) Lack of seepage rings around the 24-inch and also the 6-inch pipe.
- (4) And least likely of all, possibly some help from muskrats.

  
\_\_\_\_\_  
William P. Clark

WPC:JQM

CC: Melton D. Cauthen




(a) Looking upstream on Six Mile Creek from Montvale Road. Note wash and highwater marks 2300 feet downstream from Lambert Brother's Dam.



(b) Looking upstream and towards Six Mile Creek from the left bank, upstream of Montvale Road.

LAMBERT BROTHER'S DAM  
TRIBUTARY OF SIX MILE CREEK  
BLOUNT COUNTY, TENNESSEE



(c) Looking east and upstream at break in dam, center background, from Montvale Road.



(d) Looking upstream at break in dam. Note a portion of vertical morning glory type overflow section at left center.






(e) Close-up view of break in Lambert Brother's Dam as seen from downstream.



(f) Close view of dam cross section looking towards the left bank, south end of dam. Note slide on upstream slope.




(g) Looking from the top of the Lambert Brother's Dam at the break on the upstream side and remaining pool.



Maryville, Tennessee  
November 12, 1964

H. H. H. DATA BRANCH  
NOV 23 1964  
File No. 110-923  
F. Loudoun




### *Tying Steel On Anti-Seep Collars*

J. B. Lambert gives first hand supervision to tying of steel in one of the 10 concrete anti-seep collars on the Lambert Farms Dam

being reconstructed in the Six Mile Community. A concrete cradle is also being poured to support the pipe from below.

- Blount Soil Conservation District Photos



### *Drill Crew Gets Rock, Soil Samples*



## Drill Crew Gets Rock, Soil Samples

Soil Conservation Service drill crew investigates borrow area to a depth of 15 feet.

Samples of rock and soil were also taken from the spillway foundation area.

# Lambert Dam Being Rebuilt, Improved

"Everything we're doing to our dam will make it better than before," says J. B. Lambert as he watched the work progress along the center line of his dam. "We're putting in the best pipe available. It's been tested under 20 feet of head and it doesn't leak a drop. The six inch pipe, thought by some to have caused the break in our previous dam, is left out completely."

The Lambert Dam, at Six Mile, is being rebuilt by the most rigid of standards. Every part is being double checked and additional safety measures installed. Borrow areas were sampled and tested to deter-

mine suitability and desired compaction and are being put in according to the results of these tests.

Last spring the dam developed a small leak, which eventually led to a break in the dam and completely emptied the lake, damaging some of the Lambert farm.

The reservoir itself is being improved by deepening the shallow areas and by filling in the deeper areas. This should help eliminate some of the waterweed growth as well as generally improve fishing.

Aside from this, a cold water release is being installed as part of the spillway that will remove the normal overflow from the bottom of the lake rather than from the top. Water at the bottom is usually colder, contains less fish food and is lower in oxygen content than water near the top of a lake.

The first shipment of fish are to arrive for stocking this lake early in December. The fish on order for stocking are bluegill, shell crackers, channel catfish and largemouth bass. The bass will be stocked in May 1965 after the bluegill have had time to spawn.

Another feature included in the new dam is a drain at the top of the dam to collect any seepage that may occur. The dam is also 20 feet wider at the base. It is now 320 feet wide.

The lake has been expanded to a full 20 acres by excavation along the edges to get fill material. The slopes at the edges have all been sloped to at least the three-to-one that is to be desired.

Lambert Brothers is planning a rigid fertilization program for the lake beginning


early next spring. They realize that fertilization is as necessary to getting full fish production as it is to getting full production of field crops.

This dam is being constructed with engineering assistance through the Blount Soil Conservation District as a regular part of its technical assistance to farmers.


# Break In Large Farm Dam Brings Flood




**WHERE DAM BROKE** — Arrow in aerial view (left) by Soil Conservation Service shows point where break occurred Saturday night in dam on Lambert Brothers farm. Large sycamore tree near point of arrow was



swept away by the water. At right is view from behind dam after the break in background. Two men, tiny specs near dam (background) were picking up fish. When water receded, tracks made seven years ago by



**BREAK IN DAM** at the 17-acre lake



heavy machinery grading the bed of the lake were still visible. Also noticeable were many small "dimples" in the lake floor where Blue Gills had made their nesting areas.


October 14, 1963

10/14/63  
110-972-2511  
Lambert Bros.

# am Brings Flood Of Visitors



inery grading the bed of the lake were . Also noticeable were many small "dime lake floor where Blue Gills had made g areas.



**BREAK IN DAM** — About 35 feet wide at the top is this break in the 47-foot high dirt fill dam at the 17-acre lake on Lambert Brothers farm at Six Mile on Montvale Road.





**ROAD DAMAGE** — Some washout damage occurred at this bridge on Six Mile Creek on Montvale Road at Six Mile Community. New blacktop pavement was floated loose from base and settled backdown on limb which had washed under it. Between trees may be seen overturned pick-up truck in background. Truck was washed from road in foreground some 75 yards into the field and overturned.

— Times Staff Photos — Stone

**78 Million Gallons —**

**— Through The Dam**

# Lambert Dam At Six Mile Breaks

Enough water to supply the City of Maryville's needs for two months swept across the Six Mile area on Montvale Road Saturday night when the dirt fill dam on Lambert Brothers Farm broke.

No one was injured and there was no serious damage except to the dam and the Lambert fields which were covered with mud and rocks deposited by the water.

Cause of the break has not been determined but Soil Conservation Service Engineers from Knoxville and Nashville are expected to examine the dam this week to attempt to determine the cause and to suggest methods for repairing the damage.

While muskrats had been seen in the lake and around the dam, there had been no indication that they caused the leak that resulted in the break in the dam. However, muskrats are one of the biggest enemies of such dirt fill dams and could have caused the damage.

Completed in 1957, the 17-acre farm lake was one of the biggest of its kind in the state at the time it was built. Considered a \$40,000 to \$50,000 project, the 538-foot long dirt fill dam contained 12,000 cubic yards of dirt and was 47 feet high. The lake, which was full when the leak was discovered, contained 240 acre feet of water (78,408,000 gallons). In places the water

was 40 feet deep and included drainage from 327 acres.

Well stocked with Blue Gills and Largemouth Bass, the lake was one of the best fishing spots in the county. This past spring it was not unusual to see catches weighing five pounds.

Elmer Lambert, one of the owners, said he expected the dam would be repaired by the

near future.

Many area residents were at the scene Saturday night. By 7:30 a.m. Sunday approximately 50 persons were on hand, curiously eyeing the damage from such an unusual event. Lambert estimated that as many as 1,000 persons were scattered around the farm area by midafternoon Sunday to get a closer look at the damage.

A small leak in the dam was discovered about 6 p.m. Saturday by Ben Grindstaff who lives on the farm on the banks of the lake. The hole increased in size and about 9 p.m. a cave-in occurred in the dam above the leak and the water ripped through a 35-foot wide hole, emptying the lake in about an hour.

Grindstaff said that when he first discovered the leak it wasn't over four inches across. He added the water was just boiling up like a spring out of the dirt face of the dam. A little later, he spotted a large swirl in the lake between the top of the dam and a vertical overflow pipe out in the lake, indicating a large amount of water was draining out of the lake. However, the stream coming out the lower side of the dam at that time was no larger than six or eight inches.

The hole increased in size until the stream was as large as a creek. After about three hours, the water level had dropped only about a foot. The top of the dam then caved in with a loud rumble, Grindstaff said. The cave-in threw water 30 feet into the air, Grindstaff added. He was standing on top of the dam a few yards from the cave-in and was sprayed with the water thrown into the air.

The water from the dam had



68,408,000  
the water

til the stream was as large as a creek. After about three hours, the water level had dropped only about a foot. The top of the dam then caved in with a loud rumble, Grindstaff said. The cave-in threw water 20 feet into the air, Grindstaff added. He was standing on top of the dam a few yards from the cave-in and was sprayed with the water thrown into the air.

The water from the dam followed roughly the low area along Six Mile Creek into which overflow from the lake drains. About half a mile downstream, where the creek goes under a concrete bridge on Montvale Road, the water covered the road to a depth of five or six feet.

Two youths narrowly escaped injury when their pick-up truck was swept from the road 75 yards downstream into a field and turned on its side. They climbed onto the side of the new pick-up truck and were rescued by Blount County Rescue Squad. Larry Lambert, driver of the pick-up truck, and Milton Dickenson were the two rescued. They had heard about the leak in the dam and had gone over to look at it. They had been warned of the danger but delayed too long in leaving the area.

Six Mile Baptist Church also received some damage. Water covered the church parking lot, reaching almost to the door level of the sanctuary. The basement, where the oil furnace is located, was flooded. The water also swept the outside oil tank supplying the furnace from its foundation, spilling its contents. One of the church's outdoor toilets was also washed away.

At the point where Montvale Road crosses Six Mile Creek, the water floated the fresh blacktop loose from the road bed. As the water went back down, the blacktop settled back into place. In one spot it settled down on a limb that had been washed between the blacktop and the roadbed.

Old Piney Road, northeast of Six Mile, was flooded in several places within a short distance from the Montvale Road intersection.

Sheriff Roger Trotter set up road blocks around the flooded area. Area residents were warned of the impending danger and left their homes in the event the water should flood any homes. However, no homes were seriously threatened.

Long sections of the three-foot in diameter concrete pipe, used as the overflow for the lake, were scattered like match sticks as far as half a mile below the dam. A large sycamore tree near the break in the dam was swept aside like a splinter. The water left heavy deposits of silt

Monday morning area fishermen were wading in the mud and small pools of water along the route of the water from the well-stocked lake, stringing up fish. Cracks were visible in the top of the dam near the break. The cracks apparently resulted from the impact of the cave-in.

A number of prominent persons have fished on the private lake. Among them was the late United States House of Representatives Speaker Sam Rayburn of Texas. He fished on the lake in July 1961 while he was here for the dedication of the bridge across Fort Loudoun Dam, shortly before his death.

The Lambert dam was designed by the United States Department of Agriculture's Soil Conservation Service through the Blount County Soil Conservation District. Tillman E. Lee, now in Columbia, was work unit conservationist at the time it was built. Because of the unusual height of the dam, plans were sent to the regional office in Spartanburg, S. C., where they were approved.

Dewey Simpson, present work unit conservationist, stated that it was the first time he had ever known of a dirt fill dam breaking when it had been built in accordance with basic engineering standards. Observing the layers of construction at the point of the break in the dam, he said that from all indications the layers of dirt were put in place and packed in complete accordance with the best known procedures.

The break came above two pipes running through the base of the dam. One was a three-foot in diameter concrete overflow pipe. The other was a six-inch iron pipe. A vertical concrete box standpipe in the water near the dam automatically took care of the overflow when the lake reached full stage, draining it through the overflow pipe in the base of the dam. The iron pipe had a valve on the lower side of the dam and was installed so irrigation pipe could be hooked directly to it for irrigation of the farm.

Two other theories have been advanced as to the possible cause of the break. One is that sweating of the overflow pipe during the six-year period could have wet the soil through the dam and eventually led to a wet spot and then a leak. A wet spot had been noticed in the dam recently but it was not close to the break. The other theory is that the iron pipe, which had water pressure on it at all times, could have been broken or begun leaking and eventually caused a leak in the dam.

HYDRAULIC DATA BRANCH

Rec'd NOV 6 1933

File No. 110-923

W.B. - E. L. Laddan  
Lambert Dam

## Small Dam Collapses On Farm Near Maryville

MARYVILLE, Tenn. (AP) — An earthen dam impounding about 15 acres of water slowly gave way and collapsed near here Saturday night as rescue workers and police stood by with emergency equipment.

The flow of water washed a truck off a road and against a tree, and its two occupants had to be rescued by boat.

But fears for the safety of some two dozen homes below the dam eased with the gradual disintegration of the dam.

The dam is located above a creek four miles southeast of here. It was a structure 70 feet high, 200 feet wide and 60 feet deep.

James Kagley, jailer at the Blount County sheriff's office, said there would be "real trouble" if the dam broke.

"We're calling people by phone right now, telling them to abandon their homes," he added. "We are trying to round up boats in case they're needed."

Police said from one to two

dozen homes are located along the six mile creek below the dam in the Chota community.

The estimated 100 men, including about 75 members of the Blount County rescue squad, were on the scene with floodlights and other rescue equipment.

KINGSPORT NEWS

OCT 13 1933

END

DATE  
FILMED

1-82

DTIC

END

DATE  
FILMED

1-82

DTIC