

AD-A109 796

FLAHERTY-GIAVARA ASSOCIATES NEW HAVEN CT

F/6 13/13

NATIONAL DAM SAFETY PROGRAM. LAKE LUDLOW CLUB DAM (INVENTORY NU--ETC(U)

SEP 81 H C FLAHERTY


DACW51-81-C-0006


NL

UNCLASSIFIED

1 - 2

4/20/84





MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A

AD A109796

**LEVEL II**

SUSQUEHANNA RIVER BASIN



**LAKE LUDLOW CLUB DAM**

**CHENANGO COUNTY, NEW YORK  
INVENTORY No. NY 350**

**PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM**



**DTIC  
ELECTE  
JAN 20 1982**

E

**DTIC FILE COPY**

**APPROVED FOR PUBLIC RELEASE;  
DISTRIBUTION UNLIMITED**

**NEW YORK DISTRICT, CORPS OF ENGINEERS  
JULY 1981**

6

01 19 82

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Inspection Report Lake Ludlow Club Dam Susquehanna River Basin, Chenango County, N.Y. Inventory No. 350		5. TYPE OF REPORT & PERIOD COVERED Phase I Inspection Report National Dam Safety Program
7. AUTHOR(s) HUGH C. FLAHERTY		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS Flaherty-Giavara Associates One Columbus Plaza New Haven, CT 06510		8. CONTRACT OR GRANT NUMBER(s) DACW51-81-C-0006
11. CONTROLLING OFFICE NAME AND ADDRESS Department of the Army 26 Federal Plaza New York District, CofE New York, New York 10287		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
13. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) Department of the Army 26 Federal Plaza New York District, CofE New York, NY 10287		12. REPORT DATE 14 September 1981
		13. NUMBER OF PAGES
		14. SECURITY CLASS. (of this report) UNCLASSIFIED
		15. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report)  Approved for public release; Distribution unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dam Safety National Dam Safety Program Visual Inspection Hydrology, Structural Stability  Lake Ludlow Club Dam Chenango County Susquehanna River Basin		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number)  This report provides information and analysis on the physical condition of the dam as of the report date. Information and analysis are based on visual inspection of the dam by the performing organization.  Examination of available documents and a visual inspection of the dam did not reveal conditions which constitute an immediate hazard to human life or property. However, the dam has some deficiencies that need to be evaluated and remedied. →		

Using the Corps of Engineers' screening criteria for the initial review of spillway adequacy, it has been determined that the embankment would be overtopped by all storms exceeding 38 percent of the Probable Maximum Flood (PMF). Dam overtopping, the resulting erosion of the embankment and hence, dam breaching would cause water surface levels downstream to reach depths which would pose significant danger to residents. Therefore, the spillway is adjudged to be seriously inadequate and the dam is assessed as unsafe, nonemergency.

The classification "unsafe" applied to a dam because of a seriously inadequate spillway is not meant to connote the same degree of emergency as would be associated with an "unsafe" classification applied for a structural deficiency. It does mean that there appears to be a serious deficiency in spillway capacity and if a severe storm were to occur, overtopping and failure of the dam could take place, significantly increasing the hazard to life downstream of the dam.

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I Investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test Flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

Accession For	A						
NTIS							
DTIC							
USDA							
State							
Branch							
Division							
Activity							
Dist							
							A

PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM  
LAKE LUDLOW CLUB DAM  
INVENTORY NO. NY 350  
SUSQUEHANNA RIVER BASIN  
CHENANGO COUNTY, NEW YORK

TABLE OF CONTENTS

	<u>PAGE NO.</u>
ASSESSMENT	-
OVERVIEW PHOTOGRAPH	-
LOCATION MAP	i
1 - PROJECT INFORMATION	1
1.1 GENERAL	1
1.2 DESCRIPTION OF PROJECT	1
1.3 PERTINENT DATA	3
2 - ENGINEERING DATA	6
2.1 GEOTECHNICAL DATA	6
2.2 DESIGN RECORDS	6
2.3 CONSTRUCTION RECORDS	6
2.4 OPERATION RECORDS	7
2.5 EVALUATION OF DATA	7
3 - VISUAL INSPECTION	8
3.1 FINDINGS	8
3.2 EVALUATION OF OBSERVATIONS	9
4 - OPERATION AND MAINTENANCE PROCEDURES	11
4.1 PROCEDURE	11
4.2 MAINTENANCE OF DAM	11
4.3 WARNING SYSTEM	11
4.4 EVALUATION	11

5 - HYDROLOGIC/HYDRAULIC	12
5.1 DRAINAGE AREA CHARACTERISTICS	12
5.2 ANALYSIS CRITERIA	12
5.3 SPILLWAY CAPACITY	12
5.4 RESERVOIR CAPACITY	13
5.5 FLOODS OF RECORD	13
5.6 OVERTOPPING POTENTIAL	13
5.7 EVALUATION	14
6 - STRUCTURAL STABILITY	15
6.1 EVALUATION OF STRUCTURAL STABILITY	15
7 - ASSESSMENT/RECOMMENDATIONS	16
7.1 ASSESSMENT	16
7.2 RECOMMENDED MEASURES	17

#### APPENDICES

- A. PHOTOGRAPHS
- B. VISUAL INSPECTION CHECKLIST
- C. HYDROLOGIC/HYDRAULIC ENGINEERING DATA AND COMPUTATIONS
- D. PREVIOUS INSPECTION REPORTS/AVAILABLE DOCUMENTS
- E. STRUCTURAL STABILITY ANALYSIS
- F. REFERENCES
- G. DRAWINGS



PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM

Name of Dam: Lake Ludlow Club Dam  
State Located: New York  
County: Chenango  
Watershed: Susquehanna River Basin  
Watercourse: Ludlow Creek  
Date of Inspection: April 8, 1981

ASSESSMENT

Examination of available documents and a visual inspection of the dam did not reveal conditions which constitute an immediate hazard to human life or property. However, the dam has some deficiencies that need to be evaluated and remedied.

Using the Corps of Engineers' screening criteria for the initial review of spillway adequacy, it has been determined that the embankment would be overtopped by all storms exceeding 38 percent of the Probable Maximum Flood (PMF). Dam overtopping, the resulting erosion of the embankment and hence, dam breaching would cause water surface levels downstream to reach depths which would pose significant danger to residents. Therefore, the spillway is adjudged to be seriously inadequate and the dam is assessed as unsafe, nonemergency.

The classification "unsafe" applied to a dam because of a seriously inadequate spillway is not meant to connote the same degree of emergency as would be associated with an "unsafe" classification applied for a structural deficiency. It does mean that there appears to be a serious deficiency in spillway capacity and if a severe storm were to occur, overtopping and failure of the dam could take place, significantly increasing the hazard to life downstream of the dam.

It is recommended that the following additional investigations be performed by a registered professional engineer engaged by the owner:

1. Conduct a detailed hydrologic and hydraulic analysis to more accurately determine the site specific characteristics of the watershed.

2. Monitor the seepage that was evident at the downstream end of the right spillway retaining wall, including observation when the uphill seepage is not active, evaluate the cause and recommend remedial measures, if appropriate.
3. There appeared to have been past erosion from heavy spillway discharge behind the stepped spillway retaining walls; therefore, evaluate the height of erosion protection that is necessary above these walls, and recommend measures to provide this protection.

It is recommended that within 3 months of the final approval date of this report, all of the additional investigations should be initiated and within 18 months, appropriate remedial measures should be completed. In the interim, a plan for providing around-the-clock surveillance of the dam during periods of unusually heavy precipitation should be developed and implemented.


The following remedial measures should be completed within 12 months to correct existing deficiencies:

1. Clear the brush and trees from the embankments, establish a vegetative cover, and cut the grass and weeds on the embankments at least annually.
2. Regrade and fill the low area at the right abutment (natural spillway) up to the level of the top of the core wall, reshape major embankment irregularities, and reestablish vegetative cover on all graded areas.
3. Place rockfill or riprap erosion protection upstream of the left spillway retaining wall and enlarge protected area upstream of right spillway retaining wall.
4. Remove the apparent remains of the concrete core wall of the dam that washed out in 1935 as well as the fallen logs, brush and man-made debris to permit unrestricted flow in the downstream channel.
5. Develop and implement a flood warning and emergency evacuation plan to alert the downstream residents in the event conditions occur which could result in failure of the dam.


6. A program for regular maintenance should be developed and implemented.

Submitted by:

FLAHERTY GIAVARA ASSOCIATES, P.C.

  
\_\_\_\_\_  
Hugh C. Flaherty, P.E. & L.S.  
Chairman of the Board  
New York License No. 58508

Approved by:



  
\_\_\_\_\_  
Col. W. M. Smith, Jr.  
New York District Engineer

Date:

14 Sept 81



PHOTO #1: Overview of  
Lake Ludlow Club Dam  
Inventory No. NY 350



**VICINITY MAP**

1" = 47 MILES

**LOCATION MAP**

LAKE LUDLOW CLUB DAM  
 INVENTORY No. NY 350  
 SUSQUEHANNA RIVER BASIN  
 CHENANGO COUNTY  
 Mc DONOUGH, NEW YORK

NATIONAL DAM SAFETY PROGRAM  
PHASE I INSPECTION REPORT  
LAKE LUDLOW CLUB DAM  
INVENTORY NO. NY 350  
D.E.C. NO. 106A-1119  
SUSQUEHANNA RIVER BASIN  
CHENANGO COUNTY, NEW YORK

SECTION 1 - PROJECT INFORMATION

1.1 GENERAL

a. Authority

The Phase I Inspection reported herein was authorized by the Department of the Army, New York District, Corps of Engineers, to fulfill the requirements of the National Dam Inspection Act, Public Law 92-367. Flaherty Giavara Associates, P.C. has been retained by the New York District to inspect and report on selected dams in the State of New York. Authorization and notice to proceed was issued to Flaherty Giavara Associates, P.C. under a letter of December 24, 1980 from W. M. Smith Jr., Colonel, Corps of Engineers. Contract No. DACW 51-81-C-0006 has been assigned by the Corps of Engineers for this work.

b. Purpose

Evaluation of the existing conditions of the subject dam to identify deficiencies and hazardous conditions, determine if they constitute hazards to life and property and recommend remedial measures where necessary.

1.2 DESCRIPTION OF PROJECT

a. Description of Dam and Appurtenances

Lake Ludlow Club Dam consists of an earthen embankment with a nearly full-width stepped overflow spillway originally constructed of rockfill but which is now capped with concrete on the downstream face. It was constructed in 1937 to replace an earlier dam that had washed out in the flood of July 8, 1935. The total length of the reconstructed dam is approximately 130 feet. A plan, section and elevation view of the 1937 dam are shown in Appendix G.

The dam embankment extends a short distance on either side of the 70 foot wide overflow spillway to abutments at the valley slopes. A concrete core wall projects above the side embankments and extends down through the

embankments and the spillway section to at least 5 feet "below grade of impervious hardpan". The dam height to the top of the core wall is approximately 24 feet. The upstream slope is shown on the 1937 plan as 3 horizontal to 1 vertical, and the average downstream spillway slope is similar. The earth embankment material is not known; the overflow spillway was constructed of timber cribbing with rockfill and planking, but it is now concrete steps with a concrete apron. There is a low, stepped concrete retaining wall on each side of the spillway, and there are weep holes in the vertical face of the lowest spillway step. There is also a natural spillway at the right abutment beyond the end of the core wall. The short side embankments have a cover of trees and brush, with no upstream erosion protection.

b. Location

The Lake Ludlow Club Dam is located off Ludlow Road approximately 2.8 miles northwest of the village of Tyner in the Town of McDonough, New York. The dam is located at latitude north  $42^{\circ}-27.5'$  and longitude west  $75^{\circ}-42.2'$  on the U.S. Geological Survey 7.5 minute series topographic map "Tyner, New York". The Location Map on page i indicates where the dam is situated.

c. Size Classification

The maximum height of the dam is 24 feet and the maximum storage capacity is 1220 acre-feet at the top of dam. Therefore, Lake Ludlow Club Dam is classified as an "Intermediate" dam as defined by the Recommended Guidelines for Safety Inspection of Dams.

d. Hazard Classification

There are three roads (including New York State Route 12), approximately 3 dwellings, 3 barns and a church within the dam failure flood hazard area. Additionally, on July 8, 1935, the Lake Ludlow Club Dam failed during an extremely heavy rainstorm which resulted in extensive property damage in Tyner (See Photo No. 16) and the loss of three lives in South Oxford (See Photo No. 17). A copy of a newspaper article relating these events and Flood Impact Maps showing where they occurred are included on pages D-21 through D-23 in Appendix D. Therefore, the dam is in the "High" hazard category as defined by the Recommended Guidelines for Safety Inspection of Dams.

e. Ownership

The dam is owned by the Lake Ludlow Club, Inc. The address and telephone number are as follows:

Owner

Contact: Lake Ludlow Club, Inc.  
Ludlow Road  
McDonough, New York 13801

Telephone: (607) 843-9404

f. Purpose

The primary purpose of this dam is to maintain the water level of the lake for recreational use.

g. Design and Construction History

The original date of construction is not known; however, it was sometime prior to 1925 when the dam was reconstructed making use of "a dry, laid up stone wall" which remained from the original dam.

On July 8, 1935, the dam built in 1925 failed during an extremely heavy rainstorm. The dam was then reconstructed in 1937, having been designed by H. C. Schloer and engineered by L. G. McCauley of Sidney, New York.

The only major post construction modification noted was the concrete cap over the rockfill and timber cribbing in August, 1961.

h. Normal Operating Procedure

There are no regular operating procedures for this dam. The normal water level in the lake is maintained by the crest elevation of the spillway weir at 1459.0 (NGVD).

1.3 PERTINENT DATA

a. <u>Drainage Area (Square Miles)</u>	6.34
b. <u>Discharge at Dam Site (CFS)</u>	
- Top of Dam	2864
- Crest of Natural Spillway	2092
- Crest of Overflow Spillway	-



c. Elevations (NGVD)

- Top of Dam	1464.7
- Crest of Natural Spillway	1463.7
- Crest of Overflow Spillway	1459.0

d. Reservoir Surface Area (Acres)

- Top of Dam	153
- Crest of Natural Spillway	-
- Crest of Overflow Spillway	100

e. Storage (Acre-Feet)

- Top of Dam	1220
- Crest of Natural Spillway	-
- Crest of Overflow Spillway	500

f. Dam

- Type: Earthfill with a projecting concrete core wall	
- Length (Feet)	130
- Upstream Slope (H:V)	3:1
- Downstream Slope (H:V)	3.3:1
- Crest Width (Feet)	1.5

g. Overflow Spillway

- Type: Stepped spillway consisting of timber cribbing and rock-fill with a concrete cap and concrete abutments and apron	
- Length (Feet)	67
- Width (Feet)	47
- Side Slopes (H:V)	vertical
- Channel Bottom Slopes (Feet/Foot)	
upstream	-
downstream (average)	0.030
- Control: None	

h. Natural Spillway

- Type: Two-stage earthen weir with an earthen discharge channel	
- Length (Feet)	
left weir	18+
right weir	10+
- Width (Feet)	5+
- Control: None	

i. Reservoir Drain

No reservoir drain is known to exist.

## SECTION 2 - ENGINEERING DATA

### 2.1 GEOTECHNICAL DATA

#### a. Geology

The Lake Ludlow Club Dam is located on Ludlow Creek, an easterly flowing tributary to the Chenango River, about 2.8 miles northwest of the village of Tyner in the Allegheny Plateau physiographic province of New York State.

The topography in the area ranges from elevation 1440 at the downstream toe of the dam to elevation 1700 at the summits of the hills surrounding the dam and reservoir area.

The underlying bedrock at the site consists of the Ithaca Formation, belonging to the Upper Devonian Genesee group. This formation consists of coarse silty shales, siltstones and sandstones that were deposited in a shallow water, near-shore setting of the Catskill Delta that prograded across the state from east to west.

Above the bedrock, the valley bottom and side slopes are mantled by a heterogeneous mixture of clay, silt, sand and rock fragments known as glacial till, deposited at the base of ice sheets which once covered the region. Glacial outwash sands and silts may overlie the till in the bottom of the valley.

#### b. Subsurface Conditions

There is no record of subsurface explorations at the site of the Lake Ludlow Club Dam. A July 25, 1925 letter regarding a site visit during construction of the earlier dam refers to "clay hardpan" and "dense blue clay" with "small stones", indicating that the foundation material is probably glacial till.

### 2.2 DESIGN RECORDS

Some design information for the 1925 dam is included in Appendix D. No other design records were obtained.

### 2.3 CONSTRUCTION RECORDS

This dam was constructed in 1937. A plan, section and elevation view of the dam are included in Appendix G. No other construction records were obtained.

2.4 OPERATION RECORDS

No operation records were obtained for this dam.

2.5 EVALUATION OF DATA

The data presented herein was obtained primarily from the files of the New York State Department of Environmental Conservation (DEC). This information appears to be reliable and adequate for the purposes of a Phase I Inspection Report.

## SECTION 3 - VISUAL INSPECTION

### 3.1 FINDINGS

#### a. General

A visual inspection of the Lake Ludlow Club Dam was conducted on April 8, 1981. The weather was sunny and the temperature was 60+°F. At the time of the inspection, water was flowing in the overflow spillway (See Photos No. 5 and 7).

#### b. Dam

The dam has a short embankment section on each side of the overflow spillway (See Photos No. 8 and 9); these embankments are generally in fair condition. The irregular configuration tended to obscure any evidence of lateral movement or settlement, but there was some local erosion and possible seepage.

The following specific items were noted:

1. Most of the slopes and crest of the embankment had a moderate growth of brush and trees ranging up to about 15 inches in diameter (See Photos No. 3, 4, 5, 6, 7, 8, 9 and 13). There was considerable trash on the downstream slope of the left embankment.
2. The embankments were irregular, and for the most part there was no well-defined crest (See Photos No. 3 and 6). At the right end of the projecting core wall, and about 18 feet further right near the valley slope, the ground surface was a foot or more below the level of the top of the core wall and led to an earthen discharge channel (See Photo No. 13).
3. Slight seepage flow was exiting from the bottom of the right channel slope at and a short distance downstream from the end of the right spillway retaining wall (See Photo No. 11). There was no evident soil movement in the flow; the seepage appeared to be a continuation of downhill seepage that was observed further up above the lake level on the abutment (valley) slope, rather than seepage through or under the dam embankment.
4. The stepped spillway retaining walls were not high enough to fully protect the adjacent embankments (See Photos No. 8 and 9). There appeared to have been past erosion from heavy spillway discharge, exposing pieces of old timber both upstream and downstream from the walls. Rock fragments on the slopes above

the walls were either part of the original spillway construction, or had been placed as erosion protection.

5. Except for several concrete slab fragments to the right of the spillway (See Photo No. 3), there was no upstream erosion protection. However, there was also little evidence of wave action.

c. Overflow Spillway

The overflow spillway is in good condition consisting of a 67 foot long broad-crested weir and stepped discharge (see close-up in Photo No. 12) constructed of timber cribbing and rockfill and having a concrete cap. Remains of the timber cribbing were observed at the end of the stepped concrete retaining wall on either side of the spillway (See Photos No. 10 and 11).

d. Natural Spillway

This natural earthen two-stage weir is approximately 28 feet long, located between the end of the core wall and the right abutment. A 5+ foot wide earthen discharge channel conveys flow from this spillway into the main discharge channel, Ludlow Creek (See Photo No. 13) but would not appear to be stable during periods of heavy flow.

e. Downstream Channel

The natural channel downstream of the dam has a bed of gravel, a width of 15+ feet and a depth of 12 inches (See Photo No. 14). Fallen logs and brush as well as man-made debris were observed in the channel (See Photo No. 1). In addition, the apparent remains of the core wall of the dam that washed out in 1935 are located approximately 200 feet downstream of the existing dam on either side of the channel (See Photo No. 15) and would restrict channel flow during periods of heavy discharge.

f. Reservoir - Storage Pool Area

The lake shoreline is generally wooded or developed with cabins (See Photo No. 2) and, except for one steep point that is probably rock, the slopes are moderate to gentle. There is no significant possibility of landslides into the lake affecting the safety of the dam.

### 3.2 EVALUATION OF OBSERVATIONS

The visual inspection revealed several deficiencies on this structure. The following observations were made:

- a. A moderate growth of brush and trees was noted on most slopes and on the crest of the embankment.
- b. The embankments were irregular and generally, the crest was not well-defined.
- c. Slight seepage was observed exiting from the bottom of the right channel slope at and a short distance downstream from the end of the right spillway retaining wall.
- d. The stepped spillway retaining walls were apparently not high enough to fully protect the adjacent embankments from erosion due to heavy spillway discharge.
- e. There was no upstream erosion protection except for several concrete slab fragments to the right of the spillway.
- f. The apparent remains of the concrete core wall of the dam that washed out in 1935 were observed 200+ feet downstream on either side of the channel.
- g. Fallen logs and brush as well as man-made debris were noted in the downstream channel.

## SECTION 4 - OPERATION AND MAINTENANCE PROCEDURES

### 4.1 PROCEDURES

The normal water surface level is maintained by the crest of the spillway weir at elevation 1459.0 (NGVD). No operational procedures are in effect at this time.

### 4.2 MAINTENANCE OF DAM

There was no evidence of any routine maintenance operations at the Lake Ludlow Club Dam; however, at least a partial reconstruction of the spillway was apparently built in August, 1961.

### 4.3 WARNING SYSTEM

No warning system is presently in effect.

### 4.4 EVALUATION

Presently, no operation or maintenance procedures are in effect for this dam. Therefore, a program of regular operation and maintenance procedures should be implemented.



## SECTION 5 - HYDROLOGIC/HYDRAULIC

### 5.1 DRAINAGE AREA CHARACTERISTICS

The dam is located in the Town of McDonough on Ludlow Creek, approximately 18,500 feet upstream of Bowman Creek. Bowman Creek joins the Chenango River near the village of South Oxford, approximately twenty-nine miles upstream of the Susquehanna River at Binghamton, New York.

The watershed (shown on the Watershed Map on Page C-5 in Appendix C) consists of 4,059 acres (6.34 square miles) of rolling to hilly uplands with typical slopes of 10 percent. Land within the watershed is primarily agricultural with extensive open fields.

The watercourse upon which the reservoir is located, is a perennial stream with a typical flow width of 15 feet and a typical flow depth of 12 inches.

### 5.2 ANALYSIS CRITERIA

The purpose of the hydrologic/hydraulic analysis is to evaluate the spillway capacity and the potential for overtopping. The analysis of the spillway capacity of the dam and storage of the reservoir was performed using the Corps of Engineers' HEC-1 Computer Model - Dam Safety Version. The procedure included determining the Probable Maximum Flood (PMF) runoff from the watershed and routing the inflow hydrograph through the impoundment to determine the outflow hydrograph. The unit hydrograph was defined by the Snyder Synthetic Unit Hydrograph method, and the Modified Puls routing procedure was incorporated.

The initial rainfall loss was assumed to be 1.0 inches, and the uniform rainfall loss was assumed to be 0.1 inches per hour. In accordance with recommended guidelines of the Corps of Engineers, the Probable Maximum Precipitation (PMP) was 20.4 inches (24 hour duration, 200 square mile area).

The analysis was conducted for both the full PMF and for several fractional PMF conditions. The PMF inflow of 10,072 CFS was routed through the reservoir and the peak outflow was determined to be 8,982 CFS.

### 5.3 SPILLWAY CAPACITY

The total outlet capacity is the sum of the discharges from the overflow spillway and the natural spillway.

The overflow spillway consists of a 67 foot long broad-crested concrete weir.

The natural spillway consists of a two-stage earthen weir and an earthen discharge channel.

The stage discharge data for the combined capacity of the overflow and natural spillways was calculated for the stages tabulated below:

<u>Stage (Feet)</u>	<u>Discharge Capacity (CFS)</u>	<u>Element of Structure</u>
1459.0	0	Overflow Spillway Crest
1460.0	201	--
1461.0	568	--
1461.1	612	Top of Spillway Abutments
1462.0	1054	--
1463.0	1636	--
1463.7	2092	Natural Spillway Crest
1464.7	2864	Top of Dam

The total spillway capacity at the top of dam is 2864 CFS.

#### 5.4 RESERVOIR CAPACITY

The storage capacity of the lake was obtained from the application for the reconstruction of the dam dated May 21, 1937 for the stages indicated below:

<u>Stage (Feet)</u>	<u>Storage (Acre-Feet)</u>	<u>Storage (Inches of Runoff)</u>
1459.0	500	1.48
1464.7	1220	3.55

#### 5.5 FLOODS OF RECORD

No data regarding flood levels was obtained for this dam; however, on July 8, 1935, the original dam was swept away by an extremely heavy rainstorm.

#### 5.6 OVERTOPPING POTENTIAL

The results of the HEC-1 DB computer analysis indicate that the crest of the dam is overtopped by all storms exceeding 38 percent of the PMF event. The PMF discharge rate of 8,982 cubic feet per second (CFS) would occur at a peak flood stage of 1468.9 feet, which is 4.2 feet above the crest of the dam.

The results of the analysis are tabulated below:

<u>Flood Condition</u>	<u>Peak Inflow (CFS)</u>	<u>Peak Outflow (CFS)</u>	<u>Maximum Stage Elevation (NGVD)</u>
0.5 PMF	5036	4044	1465.8
1.0 PMF	10072	8982	1468.9

#### 5.7 EVALUATION

Using the Corps of Engineers' screening criteria for the initial review of spillway adequacy, it has been determined that the capacity of the overflow spillway is not adequate to pass either the full PMF or one half the PMF; only approximately 38 percent of the PMF can be safely passed before overtopping will occur. The PMF event would overtop the dam for a duration of 9.5 hours and the maximum depth of flow over the crest would be 4.2 feet. It is estimated that breaching of the dam as a result of overtopping, would cause water surface levels downstream to reach depths which would pose significant danger to residents. Therefore, the spillway is adjudged to be seriously inadequate and the dam is assessed as unsafe, nonemergency.

## SECTION 6 - STRUCTURAL STABILITY

### 6.1 EVALUATION OF STRUCTURAL STABILITY

#### a. Visual Observations

There was no visible evidence of major settlement or lateral movement of the core wall, or overall structural instability of the dam during the site examination, although there may have been some settlement of the embankment on either side of the core wall. The slight seepage downstream from the right spillway retaining wall is not an immediate reason to question the static structural stability of the dam; however, its origin should be confirmed. In addition, the moderate tree growth on the slopes and embankment of the dam offers potential for long-term embankment deterioration, and both the low embankment crest at the right abutment and the low retaining walls at the overflow spillway could lead to damaging erosion under high flow conditions.

#### b. Design and Construction Data

There is no construction data to confirm the actual physical properties and configuration of the earthfill in the embankments. However, the dam proportions are considered to be reasonable for the soils that were available at the site and therefore, the dam would be expected to have adequate safety margins with respect to stability under static loading conditions.

#### c. Post Construction Changes

The 1937 drawing for the Lake Ludlow Club Dam in Appendix G shows a configuration for the dam and overflow spillway that generally corresponds to the conditions observed during the visual examination on April 8, 1981. However, the spillway and retaining walls are now concrete, and there appears to be two or three spillway "steps" less than are shown on the plan. The extent to which the rock-filled cribbing has been altered is not known.

#### d. Seismic Stability

The Lake Ludlow Club Dam is located in Seismic Zone 1 and in accordance with recommended Phase I guidelines does not require seismic analysis.

## SECTION 7 - ASSESSMENT/RECOMMENDATIONS

### 7.1 ASSESSMENT

#### a. Condition

On the basis of the visual examination, there were no signs of impending structural failure or other conditions which would warrant urgent remedial action, but a number of deficiencies were noted.

#### b. Adequacy of Information

The evaluation of this dam is based primarily on visual examination, reference to the 1937 plan, approximate hydraulic and hydrologic computations, and application of engineering judgement. The available information that was obtained is adequate for the purposes of a Phase I assessment.

#### c. Need for Additional Investigations

It is recommended that the following additional investigations be performed by a registered professional engineer engaged by the owner:

1. Conduct a detailed hydrologic and hydraulic analysis to more accurately determine the site specific characteristics of the watershed.
2. Monitor the seepage that was evident at the downstream end of the right spillway retaining wall, including observation when the uphill seepage is not active, evaluate the cause and recommend remedial measures, if appropriate.
3. There appeared to have been past erosion from heavy spillway discharge behind the stepped spillway retaining walls; therefore, evaluate the height of erosion protection that is necessary above these walls, and recommend measures to provide this protection.

#### d. Urgency

It is recommended that within 3 months of the final approval date of this report, all of the additional investigations should be initiated and within 18 months, appropriate remedial measures should be completed. In the interim, a plan for providing around-the-clock surveillance of the dam during periods of unusually heavy precipitation should be developed and implemented. The recommended corrective measures presented in Section 7.2 should be completed within 12 months of final approval.

## 7.2 RECOMMENDED MEASURES

It is considered important that the following items be accomplished in addition to any items required as a result of the additional investigations recommended in Section 7.1c:

- a. Clear the brush and trees from the embankments, establish a vegetative cover, and cut the grass and weeds on the embankments at least annually.
- b. Regrade and fill the low area at the right abutment (natural spillway) up to the level of the top of core wall, reshape major embankment irregularities and reestablish vegetative cover on all graded areas.
- c. Place rockfill or riprap erosion protection upstream of the left spillway retaining wall and enlarge the protected area upstream of the right spillway retaining wall.
- d. Remove the apparent remains of the concrete core wall of the dam that washed out in 1935 as well as the fallen logs, brush and man-made debris to permit unrestricted flow in the downstream channel.
- e. Develop and implement a flood warning and emergency evacuation plan to alert downstream residents in the event conditions occur which could result in the failure of the dam.
- f. A program of regular maintenance should be developed and implemented.

APPENDIX A  
PHOTOGRAPHS








PHOTO #2: Overview of impoundment



PHOTO #3: Crest of dam looking toward  
right abutment



PHOTO #4: Overview of upstream face  
of dam




PHOTO #5: Overview of downstream face  
of dam



PHOTO #6: Upstream face of dam



PHOTO #7: Downstream face of dam




PHOTO #8: Stepped concrete retaining  
wall on left side of spillway



PHOTO #9: Stepped concrete retaining  
wall on right side of spillway



PHOTO #10: Remains of timber cribbing on  
left side of spillway



PHOTO #11: Remains of timber cribbing on  
right side of spillway




PHOTO #12: Close-up of concrete step  
of spillway



PHOTO #13: Earthen overflow discharge channel  
at right abutment



PHOTO #14: Downstream channel conditions



PHOTO #15: Remains of concrete core wall of dam that failed



PHOTO #16: Reconstructed church in Tyner which was washed away by 1935 flood



PHOTO #17: Site of Robbins' home in South Oxford near Route 12, also swept away by 1935 flood



APPENDIX B  
VISUAL INSPECTION CHECKLIST

VISUAL INSPECTION CHECKLIST

1) Basic Data

a. General

Name of Dam Lake Ludlow Club Dam  
Fed. I.D. # NY 350 DEC Dam No. 106A-1119  
River Basin Susquehanna  
Location: Town McDonough County Chenango  
Stream Name Ludlow Creek  
Tributary of Bowman Creek  
Latitude (N) 42° - 27.5' Longitude (W) 75° - 42.2'  
Type of Dam Earthfill embankment with a rockfill overflow spillway  
Hazard Category High  
Date(s) of Inspection April 8, 1981  
Weather Conditions Sunny, 60° + F.  
Reservoir Level at Time of Inspection Elevation 1459.1 + (NGVD)

b. Inspection Personnel T.L. Ward & R.A. Criscuolo of Flaherty Giavara Associates  
P.C.; P. L. LeCount of Haley & Aldrich, Inc.; B. McL. Whittingham of Salmon Associates

c. Persons Contacted (Including Address & Phone No.)  
None  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

d. History:

Date Constructed 1925 Date(s) Reconstructed 1937  
Designer H.C. Schloer Engineer L. G. McCauley  
Constructed By Unknown  
Owner Lake Ludlow Club, Inc.

2) Embankment

a. Characteristics

- (1) Embankment Material Unknown
- (2) Cutoff Type Core wall into "impervious hardpan"
- (3) Impervious Core Concrete and stone masonry core wall
- (4) Internal Drainage System None observed
- (5) Miscellaneous No comments

b. Crest

- (1) Vertical Alignment The top of the projecting core wall is level; however, the earthen crest is very irregular.
- (2) Horizontal Alignment Good; substantially straight
- (3) Surface Cracks None observed
- (4) Miscellaneous The concrete and stone masonry core wall projects above the embankment crest at varying heights (1 to 3 feet); several small stumps left of the overflow spillway; grass, weeds, brambles, brush and trees

c. Upstream Slope

- (1) Slope (Estimate - V:H) 1:3
- (2) Undesirable Growth or Debris, Animal Burrows Grass, weeds, brush and trees up to 18 inches in diameter; no animal burrows were noted.
- (3) Sloughing, Subsidence or Depressions None apparent; however, possible previous slight erosion adjacent to the overflow spillway

(4) Slope Protection Small broken concrete slab fragments to the right  
of the overflow spillway.

(5) Surface Cracks or Movement at Toe None evident

d. Downstream Slope

(1) Slope (Estimate - V:H) 1:3.3 (average for stepped overflow spillway)

(2) Undesirable Growth or Debris, Animal Burrows Brush, moss, weeds and trees  
to 15 inches in diameter; several small burrows near top of left embankment

(3) Sloughing, Subsidence or Depressions Minor incidental erosion related to  
surface runoff and foot traffic; past erosion above spillway walls.

(4) Surface Cracks or Movement at Toe None apparent; however, slope is very  
irregular

(5) Seepage None evident on left side; however, slight flow from behind end of  
right retaining wall and lesser flow from behind timber cribbing which extends  
downstream from end of wall; also, seepage coming downhill further up on right  
abutment slope

(6) External Drainage System (Ditches, Trenches, Blanket) Weep holes at the  
bottom step on either side of overflow spillway.

(7) Condition Around Outlet Structure Not applicable

(8) Seepage Beyond Toe None evident

e. Abutments - Embankment Contact at Overflow Spillway

Earth slopes above top of concrete retaining walls partially supported by  
stone and old timber.

(1) Erosion at Contact Described in 2)d.(3)

(2) Seepage Along Contact Described in 2)d.(5)

3) Drainage System

a. Description of System Broad-crested concrete weir and stepped concrete channel leading to the natural streambed.

b. Condition of System Good

c. Discharge from Drainage System Stepped concrete discharge dropping approximately 14 feet from weir to streambed

4) Instrumentation (Monumentation/Surveys, Observation Wells, Weirs, Peizometers, Etc.)

None observed

5) Reservoir

- a. Slopes Moderate to gentle wooded slopes and lakeside cabins border the  
impoundment
- b. Sedimentation Possible accumulation of sediment behind the dam
- c. Unusual Conditions Which Affect Dam None noted

6) Area Downstream of Dam

- a. Downstream Hazard (No. of Homes, Highways, etc.) Approximately 3 dwellings,  
3 barns, a church and three roads (including New York State Route 12) are  
within the dam failure flood hazard area
- b. Seepage, Unusual Growth None observed
- c. Evidence of Movement Beyond Toe of Dam None evident
- d. Condition of Downstream Channel Good; except remains of concrete core wall from  
previous dam would restrict channel flow

7) Spillway(s) (Including Discharge Conveyance Channel)

Overflow spillway, natural spillway and their discharge channels

- a. General Overflow spillway and discharge channel handle nearly  
all flows
- b. Condition of Overflow Spillway Good; no signs of deterioration except  
the exposed core wall on either side of the overflow spillway is  
deteriorating

c. Condition of Emergency Spillway Not applicable  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

d. Condition of Discharge Conveyance Channel Good condition, presently stable  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

8) Reservoir Drain/Outlet

Type: Pipe None Conduit None Other None

Material: Concrete \_\_\_\_\_ Metal \_\_\_\_\_ Other \_\_\_\_\_

Size: \_\_\_\_\_ Length \_\_\_\_\_

Invert Elevations: Entrance \_\_\_\_\_ Exit \_\_\_\_\_

Physical Condition (Describe): \_\_\_\_\_ Unobservable \_\_\_\_\_

Material: \_\_\_\_\_

Joints: \_\_\_\_\_ Alignment \_\_\_\_\_

Structural Integrity: \_\_\_\_\_

Hydraulic Capability: \_\_\_\_\_

Means of Control: Gate \_\_\_\_\_ Valve \_\_\_\_\_ Uncontrolled \_\_\_\_\_

Operator: Operable \_\_\_\_\_ Inoperable \_\_\_\_\_ Uncontrolled \_\_\_\_\_

Present Condition (Describe): \_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

9) Structural

a. Concrete Surfaces Concrete of the overflow spillway is generally in good condition;  
however, the concrete of the exposed core wall at the overflow spillway  
has spalled

b. Structural Cracking No evidence of any structural cracks; only minute surface  
cracks.

c. Movement - Horizontal & Vertical Alignment (Settlement) Very minor and only  
local at the slab section of the overflow spillway crest.

d. Junctions with Abutments or Embankments Stepped concrete retaining walls at  
both ends of the overflow spillway are in good condition.

e. Drains - Foundation, Joint, Face None evident

f. Water Passages, Conduits, Sluices Good condition

g. Seepage or Leakage No signs of seepage or leakage




- h. Joints - Construction, etc. Good condition  
\_\_\_\_\_  
\_\_\_\_\_
- i. Foundation Inaccessible  
\_\_\_\_\_  
\_\_\_\_\_
- j. Abutments See 9) d. above  
\_\_\_\_\_
- k. Control Gates None observed  
\_\_\_\_\_  
\_\_\_\_\_
- l. Approach & Outlet Channels Not applicable  
\_\_\_\_\_  
\_\_\_\_\_
- m. Energy Dissipators (Plunge Pool, etc.) Overflow spillway is comprised of concrete steps.  
\_\_\_\_\_  
\_\_\_\_\_
- n. Intake Structures Not applicable  
\_\_\_\_\_  
\_\_\_\_\_
- o. Stability Appears to be stable  
\_\_\_\_\_  
\_\_\_\_\_
- p. Miscellaneous No comments  
\_\_\_\_\_  
\_\_\_\_\_

10) Appurtenant Structures (Power House, Lock, Gatehouse, Other)

a. Description and Condition None observed  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

SALMON ASSOCIATES • Consulting Engineers


BY BA DATE \_\_\_\_\_ SUBJECT LAKE LUDLOW SHEET NO. 1 OF 2  
CHKD. BY \_\_\_\_\_ DATE \_\_\_\_\_ JOB NO. 241



SALMON ASSOCIATES • Consulting Engineers

BY BW DATE \_\_\_\_\_ SUBJECT LAKE HENRIE DAM SHEET NO. 2 OF 2  
 CHKD. BY \_\_\_\_\_ DATE \_\_\_\_\_ JOB NO. 20-11

EMERGENCY SHOWING  
 SECTION A-A



ELEVATION A-A

APPENDIX C

HYDROLOGIC/HYDRAULIC ENGINEERING DATA AND COMPUTATIONS

CHECK LIST FOR DAMS  
HYDROLOGIC AND HYDRAULIC  
ENGINEERING DATA

AREA-CAPACITY DATA:

	<u>Elevation</u> (ft.)	<u>Surface Area</u> (acres)	<u>Storage Capacity</u> (acre-ft.)
1) Top of Dam	1464.7	153	1220
2) Design High Water (Max. Design Pool)	--	--	--
3) Emergency Spillway Crest	--	--	--
4) Pool Level with Flashboards	--	--	--
5) Overflow Spillway Crest	1459.0	100	500

DISCHARGES:

	<u>Volume</u> (cfs)
1) Average Daily	Unknown
2) Overflow Spillway @ Maximum High Water (Top of Dam)	2807
3) Natural Spillway @ Maximum High Water (Top of Dam)	57
4) Principal Spillway @ Emergency Spillway Crest	--
5) Low Level Outlet @ Principal Spillway Crest	--
6) Total (of all facilities) @ Maximum High Water	2864
7) Maximum Known Flood	Unknown
8) At Time of Inspection	6 +

CREST:

ELEVATION: 1464.7 (NGVD)

Type Earthen embankment with a projecting concrete core wall

Width 1.5 feet Length 130 feet

Spillover Concrete overflow spillway weir

Location Center of embankment

SPILLWAY:

OVERFLOW

EMERGENCY

<u>1459.0 (NGVD)</u>	<u>Elevation</u>	<u>1462.7 and 1462.9 (NGVD)</u>
<u>Broad-crested weir</u>	<u>Type</u>	<u>Two-stage broad-crested weir</u>
<u>47 feet</u>	<u>Width</u>	
	<u>Type of Control</u>	
<u>Weir</u>	<u>Uncontrolled</u>	<u>Weir</u>
<u>--</u>	<u>Controlled</u>	<u>--</u>
<u>None</u>	<u>Type:</u> <u>(Flashboards; gate)</u>	<u>None</u>
<u>One</u>	<u>Number</u>	<u>One</u>
<u>67 foot long weir</u>	<u>Size/Length</u>	<u>28 foot long two-staged weir</u>
<u>Concrete</u>	<u>Invert Material</u>	<u>Earth</u>
<u>Continuously</u>	<u>Anticipated Length</u> <u>of Operating Service</u>	<u>Unknown</u>
<u>Unknown</u>	<u>Chute Length</u>	<u>Unknown</u>
<u>Unknown</u>	<u>Height Between</u> <u>Spillway Crest</u> <u>&amp; Approach Channel</u> <u>Invert (Weir Flow)</u>	<u>Unknown</u>

Type: \_\_\_\_\_

Location: \_\_\_\_\_

Records: \_\_\_\_\_

Date Unknown

Max. Reading Unknown

FLOOD WATER CONTROL SYSTEM:

Warning System None in effect

Method of Controlled Releases (mechanisms) None



DRAINAGE AREA: 4059 acres = 6.34 square miles

DRAINAGE BASIN RUNOFF CHARACTERISTICS:

Land Use - Type Rural, agriculture

Terrain - Relief Rolling uplands

Surface - Soil Glacial till

Runoff Potential (existing or planned extensive alterations to existing surface or subsurface conditions)

Primarily woodlands with scattered open fields; some agriculture; glacial till soils; average watershed slope is 10 ± percent, some residential homes and roadways; possible future development around lake

Potential Sedimentation problem areas (natural or man-made; present or future)

Possible surface erosion from agricultural fields during fallow periods

Potential Backwater problem areas for levels at maximum storage capacity including surcharge storage:

Flooding of some lakeside cabins is possible

Dikes - Floodwalls (overflow & non-overflow) - Low reaches along the reservoir perimeter:


Location: Low reach (natural spillway) at the right abutment


Elevation: 1463.7 (NGVD)

Reservoir:

Length @ Maximum Pool 4500 ± feet = 0.9 miles (Miles)

Length of Shoreline (@ Spillway Crest) 13,000 ± feet = 2.5 miles (Miles)





**WATERSHED MAP**

**LAKE LUDLOW CLUB DAM  
INVENTORY No. NY 350**

**SUSQUEHANNA RIVER BASIN  
CHENANGO COUNTY  
McDONOUGH, NEW YORK**



**SCALE IN FEET**

CALCULATIONS



## WATERSHED DATA FOR HEC-1 SNYDER HYDROGRAPH

### 1) TIME TO PEAK

$$L = 23,000' = 4.36 \text{ miles}$$
$$L_c = 10,000' = 1.89 \text{ miles}$$
$$C_T = 2.0 \text{ } \frac{hr}{mi} \text{ average slopes}$$

$$T_p = C_T (L + L_c)^{0.3}$$
$$= 2.0 (4.36 + 1.89)^{0.3} = 3.77 \text{ Hours}$$

$$t_r = \frac{T_p}{5.5} = \frac{3.77}{5.5} = 0.68 \text{ USE } t_r = 0.5$$

$$t_{pr} = T_p + 0.25 (t_r - t_r)$$
$$= 3.77 + 0.25 (0.5 - 0.68) = 3.73 \text{ Hours}$$

### 2) $C_p = 0.63$ for HIGHLAND AREA

### 3) % Impervious

$$\text{Roads} = 65,000 \text{ LF} \times 25' = 1,625,000 \text{ } ft^2$$
$$\text{Houses} = 20 @ 1000 \text{ } ft^2 = \frac{20,000 \text{ } ft^2}{1,645,000 \text{ } ft^2}$$
$$1,645,000 \text{ } ft^2 = 37.8 \text{ acres}$$

$$\frac{37.8}{4059} = 0.9\%$$

### 4) WATERSHED AREA

$$4059 \text{ AC} / 640 = 6.34 \text{ square miles}$$

Based on 1" = 2000' USGS maps

PROJECT \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



**FLAHERTY-GIAVARA ASSOCIATES**  
ENVIRONMENTAL DESIGN CONSULTANTS  
ONE COLUMBUS PLAZA NEW HAVEN CONN 06510/203/789-1280

SHEET NO. 2 OF \_\_\_\_\_  
BY: \_\_\_\_\_ DATE 4-20-89  
CHK'D. BY: TLV DATE 4-20-89

WATERFALL DATA FROM HYDROMETEOROLOGICAL

Station No. 53

04 40 700 = 204 11 10 200  
3.000 1.0

STATION 53


4-7-89

6  
12  
24  
48

111  
122  
133  
143



STAGE DISCHARGE DATA



<u>STAGE</u>	<u><math>Q = 2.5LH^{1.5}</math></u>	<u><math>Q = 3.0LH^{1.5}</math></u>	<u>DISCHARGE</u>
1459.0	-	0.0	0.0
1460.0	-	201.0	201.0
1461.0	-	568.5	568.5
1461.1	-	611.8	611.8
1462.0	-	1053.9	1053.9
1463.0	-	1635.3	1635.3
1463.7	-	2092.1	2092.1
1463.9	2.2	2229.3	2231.5
1464.7	57.2	2806.5	2863.7
1465.0	89.0	3064.0	3153.0
1466.0	224.1	4103.9	4323.0

PROJECT 2000  
250




**FLAHERTY-GIAVARA ASSOCIATES**  
ENVIRONMENTAL DESIGN CONSULTANTS  
ONE COLUMBUS PLAZA NEW HAVEN CONN 06510/203/789-1200

SHEET NO. 4 OF       
BY      DATE 4-15-91  
CHK'D BY TLW DATE 4-20-91

STAGE DISCHARGE CURVE

Spillway & Overflow Section





PROJECT Cover Dam  
NA 370




**FLAHERTY-GIAVARA ASSOCIATES**  
ENVIRONMENTAL DESIGN CONSULTANTS  
ONE COLUMBUS PLAZA NEW HAVEN CONN 06510/203/786-1200

SHEET NO. 5 OF         
BY        DATE 4-15-91  
CHK'D. BY TLW DATE 4-20-91

STAGE DISCHARGE CURVE

SPILLWAY



C-10

HEC-1 FLOOD HYDROGRAPH COMPUTATIONS

FLAHERTY GIAVARA ASSOCIATES, P. C.

FLAHERTY GIAVARA ASSOCIATES, P. C.  
FLOOD HYDROGRAPH PACKAGE (HEC-1)  
DAM SAFETY VERSION JULY 1978  
LAST MODIFICATION 26 FEB 79

A1 NATIONAL DAM INSPECTION PROGRAM, PHASE I REPORT, CORPS OF ENGINEERS - NEW YORK DISTRICT  
A2 DAM INVENTORY NO. NY 350, LAKE LUDLOW CLUB DAM, CHENANGO COUNTY, NEW YORK, APRIL 21, 1981  
A3 PREPARED BY FLAHERTY GIAVARA ASSOCIATES, P. C., ONE COLUMBUS PLAZA, NEW HAVEN, CONNECTICUT  
B1 120  
B2 120  
B3 120  
B4 120  
B5 120  
B6 120  
B7 120  
B8 120  
B9 120  
B10 120  
B11 120  
B12 120  
B13 120  
B14 120  
B15 120  
B16 120  
B17 120  
B18 120  
B19 120  
B20 120  
B21 120  
B22 120  
B23 120  
B24 120  
B25 120  
B26 120  
B27 120

NO	NHR	NR	NRMIN	IDAY	JOPER	NHT	IMIN	IPRT	NETAN
1	0	0	30	0	0	0	0	2	0
2	0	0	30	0	0	0	0	0	0
3	0	0	30	0	0	0	0	0	0
4	0	0	30	0	0	0	0	0	0
5	0	0	30	0	0	0	0	0	0
6	0	0	30	0	0	0	0	0	0
7	0	0	30	0	0	0	0	0	0
8	0	0	30	0	0	0	0	0	0
9	0	0	30	0	0	0	0	0	0
10	0	0	30	0	0	0	0	0	0
11	0	0	30	0	0	0	0	0	0
12	0	0	30	0	0	0	0	0	0
13	0	0	30	0	0	0	0	0	0
14	0	0	30	0	0	0	0	0	0
15	0	0	30	0	0	0	0	0	0
16	0	0	30	0	0	0	0	0	0
17	0	0	30	0	0	0	0	0	0
18	0	0	30	0	0	0	0	0	0
19	0	0	30	0	0	0	0	0	0
20	0	0	30	0	0	0	0	0	0
21	0	0	30	0	0	0	0	0	0
22	0	0	30	0	0	0	0	0	0
23	0	0	30	0	0	0	0	0	0
24	0	0	30	0	0	0	0	0	0
25	0	0	30	0	0	0	0	0	0
26	0	0	30	0	0	0	0	0	0
27	0	0	30	0	0	0	0	0	0

PREVIEW OF SEQUENCE OF STREAM NETWORK CALCULATIONS  
RUNOFF HYDROGRAPH AT  
ROUTE HYDROGRAPH TO  
END OF NETWORK

RUN DATE: 8/20/78  
TIME: 4:53 PM

NATIONAL DAM INSPECTION PROGRAM, PHASE I REPORT, CORPS OF ENGINEERS - NEW YORK DISTRICT  
DAM INVENTORY NO. NY 350, LAKE LUDLOW CLUB DAM, CHENANGO COUNTY, NEW YORK, APRIL 21, 1981  
PREPARED BY FLAHERTY GIAVARA ASSOCIATES, P. C., ONE COLUMBUS PLAZA, NEW HAVEN, CONNECTICUT

MULTI-PLAN ANALYSES TO BE PERFORMED

RTIOS= 0.30 0.35 0.37 0.38 0.39 0.40 0.50 1.00  
 NPLAN= 1 NR1ID= 9 LRTID= 1

\*\*\*\*\* SUB-AREA RUNOFF COMPUTATION \*\*\*\*\*

INFLOW HYDROGRAPH - SNYDER METHOD

ISTAG 1 ICOMP 0 IECON 0 ITAPE 0 JPLI 0 JPRT 0 INAME 1 ISTAGE 0 IAUTO 0

HYDROGRAPH DATA

IHYDQ 1 IUHQ 1 TAREA 6.34 SNAP 0.00 TRSDA 2.34 TRSFC 0.00 NRATIO 0 ISNDW 0 ISAME 1 LOCAL 0

PRECIP DATA

SRFS 0.00 20.40 111.00 122.00 133.00 143.00 148.00 149.00  
 R12 R23 R48 R72 R98

TRSPC COMPUTED BY THE PROGRAM IS 0.800

LOSS DATA

LROPT 0 STRKR 0 DLTKR 0 RTIOL 1.00 ERAIN 0.00 STIOL 1.00 CNSTL 0.10 ALSMX 0.00 RTIMP 0.01

UNIT HYDROGRAPH DATA NTA= 0 TP= 3.73 CP=0.63

RECESSION DATA

STARTW= 2.00 GRCSIN= 0.10 RTIORM= 1.50  
 APPROXIMATE CLARK COEFFICIENTS FROM GIVEN SNYDER CP AND TP ARE TC= 8.62 AND R= 6.71 INTERVALS

UNIT HYDROGRAPH 41 END-OF-PERIOD ORDINATES, LAG= 3.74 HOURS, CP= 0.63 VOL= 1.00

32	117	333	440	511	577	670	743
115	126	137	148	159	170	180	193
19	22	25	28	31	34	37	40
14	16	18	20	22	24	26	28

END-OF-PERIOD FLOW

MO DA	HR MN	PERIOD	RAIN	EXCS	LOSS	COMP 0	MO DA	HR MN	PERIOD	RAIN	EXCS	LOSS	COMP 0
1 01	0 30	1	0.00	0.00	0.00	0	1 02	6 30	61	0.19	0.10	0.00	76
1 01	1 30	2	0.00	0.00	0.00	0	1 02	7 30	62	0.15	0.10	0.00	88
1 01	2 30	3	0.00	0.00	0.00	0	1 02	8 30	63	0.15	0.10	0.00	110
1 01	3 30	4	0.00	0.00	0.00	0	1 02	9 30	64	0.15	0.10	0.00	144
1 01	4 30	5	0.00	0.00	0.00	0	1 02	10 30	65	0.15	0.10	0.00	170
1 01	5 30	6	0.00	0.00	0.00	0	1 02	11 30	66	0.15	0.10	0.00	205
1 01	6 30	7	0.00	0.00	0.00	0	1 02	12 30	67	0.15	0.10	0.00	240
1 01	7 30	8	0.00	0.00	0.00	0	1 02	13 30	68	0.15	0.10	0.00	275
1 01	8 30	9	0.00	0.00	0.00	0	1 02	14 30	69	0.15	0.10	0.00	310
1 01	9 30	10	0.00	0.00	0.00	0	1 02	15 30	70	0.15	0.10	0.00	345
1 01	10 30	11	0.00	0.00	0.00	0	1 02	16 30	71	0.15	0.10	0.00	380
1 01	11 30	12	0.00	0.00	0.00	0	1 02	17 30	72	0.15	0.10	0.00	415
1 01	12 30	13	0.00	0.00	0.00	0	1 02	18 30	73	0.15	0.10	0.00	450
1 01	13 30	14	0.00	0.00	0.00	0	1 02	19 30	74	0.15	0.10	0.00	485



STATION	INFLOW(I), OUTFLOW(O) AND OBSERVED FLOW(*)				PRECIP(L) AND EXCESS(X)
	4000.	8000.	10000.	12000.	
0	0	0	0	0	0
1	0	0	0	0	0
2	0	0	0	0	0
3	0	0	0	0	0
4	0	0	0	0	0
5	0	0	0	0	0
6	0	0	0	0	0
7	0	0	0	0	0
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	0	0	0	0	0
12	0	0	0	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	0	0	0	0	0
17	0	0	0	0	0
18	0	0	0	0	0
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	0	0	0	0
25	0	0	0	0	0
26	0	0	0	0	0
27	0	0	0	0	0
28	0	0	0	0	0
29	0	0	0	0	0
30	0	0	0	0	0
31	0	0	0	0	0
32	0	0	0	0	0
33	0	0	0	0	0
34	0	0	0	0	0
35	0	0	0	0	0
36	0	0	0	0	0
37	0	0	0	0	0
38	0	0	0	0	0
39	0	0	0	0	0
40	0	0	0	0	0
41	0	0	0	0	0
42	0	0	0	0	0
43	0	0	0	0	0
44	0	0	0	0	0
45	0	0	0	0	0
46	0	0	0	0	0
47	0	0	0	0	0
48	0	0	0	0	0
49	0	0	0	0	0
50	0	0	0	0	0
51	0	0	0	0	0
52	0	0	0	0	0
53	0	0	0	0	0
54	0	0	0	0	0
55	0	0	0	0	0
56	0	0	0	0	0
57	0	0	0	0	0
58	0	0	0	0	0
59	0	0	0	0	0
60	0	0	0	0	0
61	0	0	0	0	0
62	0	0	0	0	0
63	0	0	0	0	0
64	0	0	0	0	0
65	0	0	0	0	0
66	0	0	0	0	0
67	0	0	0	0	0
68	0	0	0	0	0
69	0	0	0	0	0
70	0	0	0	0	0
71	0	0	0	0	0
72	0	0	0	0	0
73	0	0	0	0	0
74	0	0	0	0	0
75	0	0	0	0	0
76	0	0	0	0	0
77	0	0	0	0	0
78	0	0	0	0	0
79	0	0	0	0	0
80	0	0	0	0	0
81	0	0	0	0	0
82	0	0	0	0	0
83	0	0	0	0	0
84	0	0	0	0	0
85	0	0	0	0	0
86	0	0	0	0	0
87	0	0	0	0	0
88	0	0	0	0	0
89	0	0	0	0	0
90	0	0	0	0	0
91	0	0	0	0	0
92	0	0	0	0	0
93	0	0	0	0	0
94	0	0	0	0	0
95	0	0	0	0	0
96	0	0	0	0	0
97	0	0	0	0	0
98	0	0	0	0	0
99	0	0	0	0	0
100	0	0	0	0	0

\*OVF\*

PAGE 0005

FLAHERTY GIAVARA ASSOCIATES, P. C.

22	00	521	XXXXXXXXXX	
33	00	531	XXXXXXXXXX	
44	00	541	XXXXXXXXXX	
55	00	551	XXXXXXXXXX	
66	00	561	XXXXXXXXXX	
77	00	571	XXXXXXXXXX	
88	00	581	XXXXXXXXXX	
99	00	591	XXXXXXXXXX	
10	30	601	XXXXXXXXXX	
11	00	611	XXXXXXXXXX	
12	00	621	XXXXXXXXXX	
13	00	631	XXXXXXXXXX	
14	00	641	XXXXXXXXXX	
15	00	651	XXXXXXXXXX	
16	30	661	XXXXXXXXXX	
17	00	671	XXXXXXXXXX	
18	30	681	XXXXXXXXXX	
19	00	691	XXXXXXXXXX	
20	00	701	XXXXXXXXXX	
21	00	711	XXXXXXXXXX	
22	00	721	XXXXXXXXXX	
23	00	731	XXXXXXXXXX	
24	00	741	XXXXXXXXXX	
25	00	751	XXXXXXXXXX	
26	00	761	XXXXXXXXXX	
27	00	771	XXXXXXXXXX	
28	00	781	XXXXXXXXXX	
29	00	791	XXXXXXXXXX	
30	00	801	XXXXXXXXXX	
31	00	811	XXXXXXXXXX	
32	00	821	XXXXXXXXXX	
33	00	831	XXXXXXXXXX	
34	00	841	XXXXXXXXXX	
35	00	851	XXXXXXXXXX	
36	00	861	XXXXXXXXXX	
37	00	871	XXXXXXXXXX	
38	00	881	XXXXXXXXXX	
39	00	891	XXXXXXXXXX	
40	00	901	XXXXXXXXXX	
41	00	911	XXXXXXXXXX	
42	00	921	XXXXXXXXXX	
43	00	931	XXXXXXXXXX	
44	00	941	XXXXXXXXXX	
45	00	951	XXXXXXXXXX	
46	00	961	XXXXXXXXXX	
47	00	971	XXXXXXXXXX	
48	00	981	XXXXXXXXXX	
49	00	991	XXXXXXXXXX	
50	00	1000	XXXXXXXXXX	
51	00	1001	XXXXXXXXXX	
52	00	1002	XXXXXXXXXX	
53	00	1003	XXXXXXXXXX	
54	00	1004	XXXXXXXXXX	
55	00	1005	XXXXXXXXXX	
56	00	1006	XXXXXXXXXX	
57	00	1007	XXXXXXXXXX	
58	00	1008	XXXXXXXXXX	
59	00	1009	XXXXXXXXXX	
60	00	1010	XXXXXXXXXX	





THOUS CU M

AC-FT  
1412  
1742

2300  
2837

2394  
2953

2394  
2953

STATION	HYDROGRAPH AT STA				I FOR PLAN 1, RTIO 3				TOTAL VOLUME
	4	3	2	1	4	3	2	1	
4 3 2 1	32	32	32	32	32	32	32	32	32
76	11	20	47	71	71	30	26	78	32
27	62	54	47	39	30	24	24	24	24
17	19	21	21	21	133	133	133	133	133
32	40	52	68	88	117	117	117	117	117
2249	269	343	343	343	343	343	343	343	343
1807	288	301	301	301	301	301	301	301	301
2630	199	173	132	132	1008	1008	1008	1008	1008
870	504	439	373	324	324	311	311	311	311
287	289	254	244	238	218	208	208	208	208

PEAK

6-HOUR

24-HOUR

72-HOUR

TOTAL VOLUME

3626

1193

497

5793

103

39

14

1987

INCHES

4.30

7.00

7.29

109.18

177.81

189.07

2463

AC-FT

1453

2368

2463

THOUS CU M

1772

2918

5037

5037

THOUS CU M

AC-FT  
1412  
1742

2300  
2837

2394  
2953

2394  
2953

STATION	HYDROGRAPH AT STA				I FOR PLAN 1, RTIO 4				TOTAL VOLUME
	4	3	2	1	4	3	2	1	
4 3 2 1	32	32	32	32	32	32	32	32	32
76	11	21	48	73	73	31	27	80	32
27	62	55	48	41	34	24	25	26	26
17	19	20	22	22	114	137	160	179	179
32	41	53	71	91	114	114	114	114	114
2249	233	276	353	471	636	636	636	636	636
1807	2762	3177	3501	3688	3727	3601	3340	3021	3021
2630	2054	1786	1355	1357	1185	1036	905	790	790
870	518	447	385	361	333	320	320	307	307
283	272	261	251	241	222	213	213	205	205

PEAK

6-HOUR

24-HOUR

72-HOUR

TOTAL VOLUME

3727

1226

510

61248

106

3011

14

1734

INCHES

4.42

7.19

7.49

112.21

182.75

190.22

3531

AC-FT

1493

2379

3122

THOUS CU M

1842

3122

3122

AC-FT  
1412  
1742

2300  
2837

2394  
2953

2394  
2953

2394  
2953

2394  
2953

202	217	239	284	363	484	653	872	1133	1473
1907	2374	2837	3263	3994	3786	3828	3698	3430	3102
2769	2423	2102	1834	1397	1373	1217	1064	930	812
707	914	532	439	376	371	356	342	329	318
303	291	279	268	258	247	238	228	219	210
			PEAK	24-HOUR	72-HOUR	TOTAL	VOLUME		
			3828	1299	524	62903			
			108	36	15	1781			
				4.54	7.69				
			113.24	187.69	195.36				
			1533	2497	2599				
			1891	3080	3206				
			CFS						
			CMS						
			INCHES						
			MM						
			AC-FT						
			THOUS CU M						

5	3	4	4	4	4	4	4	4	4
32	32	32	32	32	32	32	32	32	32
83	73	67	58	36	31	25	23	20	18
23	21	21	21	22	23	23	23	27	28
30	34	43	50	74	76	120	145	168	187
207	223	245	271	372	476	771	875	1014	1163
1937	2437	3112	3349	3971	4888	7281	8796	10521	12184
2833	2486	2165	1883	1539	1430	1249	1092	954	833
726	631	546	471	406	381	366	351	337	324
311	299	287	275	264	254	244	234	225	216
			PEAK	24-HOUR	72-HOUR	TOTAL	VOLUME		
			3728	1292	538	64559			
			111	37	13	1828			
				4.66	7.89				
			118.28	192.62	200.50				
			1574	2563	2668				
			1941	3161	3291				
			CFS						
			CMS						
			INCHES						
			MM						
			AC-FT						
			THOUS CU M						

5	3	4	4	4	4	4	4	4	4
32	32	32	32	32	32	32	32	32	32
84	77	68	60	37	35	27	25	22	20
23	22	21	22	23	23	23	23	27	28
30	34	41	48	74	78	123	148	173	194
208	226	251	277	382	507	688	817	954	1093
2008	2497	3435	3783	4029	3987	4029	3893	3611	3263
2707	2390	2230	1931	1691	1487	1284	1120	977	854
744	647	560	484	417	391	375	360	346	332
319	306	294	282	271	260	250	240	231	221
			PEAK	24-HOUR	72-HOUR	TOTAL	VOLUME		
			4029	1325	552	66214			
			114	38	16	1875			
				4.78	8.10				
			121.31	197.56	205.64				
			1614	2629	2736				
			CFS						
			CMS						
			INCHES						
			MM						
			AC-FT						

THOUS CU M 1991. 3242. 3375. 3375.

THOUS CU M	HYDROGRAPH AT STA	5-HOUR	24-HOUR	72-HOUR	TOTAL	VOLUME
6	6	4067	1697	690	85767	4
4	4	115	47	20	2344	3
3	3	9	77	10	19	3
103	13	151.64	246.95	10.12	257.05	99
28	27	2018	3286	3420	4219	108
38	44	2489	4053	4219	4219	34
266	373					216
3531	474					1491
508	2414					4914
377	373					1233
	504					1400
	368					1400
						500
						288
						277

THOUS CU M	HYDROGRAPH AT STA	5-HOUR	24-HOUR	72-HOUR	TOTAL	VOLUME
12	11	8138	3313	1379	16553	9
6	7	230	74	39	467	6
6	5	11	19	24	20	5
210	30	150	130	112	183	197
58	97	194	190	199	63	72
76	144	171	190	245	66	69
331	627	954	1273	1719	371	431
5019	7466	8587	9969	10072	2294	2983
6248	7466	9463	1273	1719	9027	9027
6373	827	4203	3666	3802	2799	2446
1861	1400	1042	651	625	901	865
797	735	678	651	625	600	577

THOUS CU M	HYDROGRAPH AT STA	5-HOUR	24-HOUR	72-HOUR	TOTAL	VOLUME
12	11	8138	3313	1379	16553	9
6	7	230	74	39	467	6
6	5	11	19	24	20	5
210	30	150	130	112	183	197
58	97	194	190	199	63	72
76	144	171	190	245	66	69
331	627	954	1273	1719	371	431
5019	7466	8587	9969	10072	2294	2983
6248	7466	9463	1273	1719	9027	9027
6373	827	4203	3666	3802	2799	2446
1861	1400	1042	651	625	901	865
797	735	678	651	625	600	577

THOUS CU M	HYDROGRAPH AT STA	5-HOUR	24-HOUR	72-HOUR	TOTAL	VOLUME
12	11	8138	3313	1379	16553	9
6	7	230	74	39	467	6
6	5	11	19	24	20	5
210	30	150	130	112	183	197
58	97	194	190	199	63	72
76	144	171	190	245	66	69
331	627	954	1273	1719	371	431
5019	7466	8587	9969	10072	2294	2983
6248	7466	9463	1273	1719	9027	9027
6373	827	4203	3666	3802	2799	2446
1861	1400	1042	651	625	901	865
797	735	678	651	625	600	577

\*\*\*\*\*  
 HYDROGRAPH ROUTING  
 \*\*\*\*\*

RESERVOIR ROUTING - MODIFIED PLUS METHOD  
 ISTATG ICOMP IRECON ITAPE JPLT JPRI INAME I8TAGE IAUTO

ROUTING DATA		ROUTING DATA		ROUTING DATA		ROUTING DATA		ROUTING DATA				
GLSS	CLOSS	AVG	IRF	ISAME	IOPT	IPMP	LSTR	LAG	AMSK	TBK	STORA	IBPRAT
0.0	0.000	0.00	1	1	0	0	0	0	0.000	0.000	0	-1
NSPTS	NSTD	LAG	AMSK	TBK	STORA	IBPRAT	IBPRAT	IBPRAT	IBPRAT	IBPRAT	IBPRAT	IBPRAT
1	0	1461.00	1461.10	1462.00	1463.00	1463.70	1463.90	1464.70	1465.00	1465.00	1465.00	1465.00
0.00	201.00	368.50	611.80	1053.90	1635.80	2092.10	2231.90	2863.70	3123.10	3123.10	3123.10	3123.10
1486.00	1470.00											
0.00	8679.50											
100.	138.	179.	276.									
0	118.	1698.	3994.									
1459.	1460.	1470.	1480.									
CREL	SPRID	COB	EXPH	ELEV	COOL	CAREA	EXPL					
1459.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0					

DAM DATA	
TOPEL	DAMID
1464.7	61.
3.0	1.5

STATION 1, PLAN 1, RATIO 1

END-OF-PERIOD HYDROGRAPH ORDINATES

OUTFLOW		STORAGE	
1	2	1	2
1	1	0	0
2	2	1	1
3	3	1	1
4	4	1	1
5	5	1	1
6	6	1	1
7	7	1	1
8	8	1	1
9	9	1	1
10	10	1	1
11	11	1	1
12	12	1	1
13	13	1	1
14	14	1	1
15	15	1	1
16	16	1	1
17	17	1	1
18	18	1	1
19	19	1	1
20	20	1	1
21	21	1	1
22	22	1	1
23	23	1	1
24	24	1	1
25	25	1	1
26	26	1	1
27	27	1	1
28	28	1	1
29	29	1	1
30	30	1	1
31	31	1	1
32	32	1	1
33	33	1	1
34	34	1	1
35	35	1	1
36	36	1	1
37	37	1	1
38	38	1	1
39	39	1	1
40	40	1	1
41	41	1	1
42	42	1	1
43	43	1	1
44	44	1	1
45	45	1	1
46	46	1	1
47	47	1	1
48	48	1	1
49	49	1	1
50	50	1	1
51	51	1	1
52	52	1	1
53	53	1	1
54	54	1	1
55	55	1	1
56	56	1	1
57	57	1	1
58	58	1	1
59	59	1	1
60	60	1	1
61	61	1	1
62	62	1	1
63	63	1	1
64	64	1	1
65	65	1	1
66	66	1	1
67	67	1	1
68	68	1	1
69	69	1	1
70	70	1	1
71	71	1	1
72	72	1	1
73	73	1	1
74	74	1	1
75	75	1	1
76	76	1	1
77	77	1	1
78	78	1	1
79	79	1	1
80	80	1	1
81	81	1	1
82	82	1	1
83	83	1	1
84	84	1	1
85	85	1	1
86	86	1	1
87	87	1	1
88	88	1	1
89	89	1	1
90	90	1	1
91	91	1	1
92	92	1	1
93	93	1	1
94	94	1	1
95	95	1	1
96	96	1	1
97	97	1	1
98	98	1	1
99	99	1	1
100	100	1	1

FLAHERTY GIOVARA ASSOCIATES, P. C.

1459.0	1459.0	1459.0	1459.0	1459.0	1459.0	1459.0	1459.0	1459.0	1459.0	1459.0	1459.0	1459.0	1459.0	1459.0	1459.0	1459.0	1459.0	1459.0	1459.0
1459.0	1459.0	1459.0	1459.0	1459.0	1459.0	1459.0	1459.0	1459.0	1459.0	1459.0	1459.0	1459.0	1459.0	1459.0	1459.0	1459.0	1459.0	1459.0	1459.0


PEAK OUTFLOW IS 2166. AT TIME 43.50 HOURS

6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
1714	729	380	45644
54	24	11	1293
2.81	3.43	3.58	5.58
71.34	128.43	141.76	141.76
847	1842	1886	1886
1171	2272	2327	2327

STATION 1

#DVF*	INFLOW(1)	OUTFLOW(0)	AND OBSERVED FLOW(*)
0	1200	1600	2400
1	300	1200	2800
2	300	1200	3200
3	300	1200	2800
4	300	1200	2800
5	300	1200	2800
6	300	1200	2800
7	300	1200	2800
8	300	1200	2800
9	300	1200	2800
10	300	1200	2800
11	300	1200	2800
12	300	1200	2800
13	300	1200	2800
14	300	1200	2800

15 00 301  
16 30 311  
17 00 321  
18 30 331  
19 00 341  
20 30 3501  
21 00 3601  
22 30 3701  
23 00 3801  
24 30 390  
25 00 40 01  
26 30 41 01  
27 00 42 1  
28 30 43 1  
29 00 44 1  
30 30 45 1  
31 00 46 1  
32 30 47 1  
33 00 48 1  
34 30 49 1  
35 00 50 1  
36 30 51 1  
37 00 52 1  
38 30 53 1  
39 00 54 1  
40 30 55 1  
41 00 56 1  
42 30 57 1  
43 00 58 1  
44 30 59 1  
45 00 60 1  
46 30 61 1  
47 00 62 1  
48 30 63 1  
49 00 64 1  
50 30 65 1  
51 00 66 1  
52 30 67 1  
53 00 68 1  
54 30 69 1  
55 00 70 1  
56 30 71 1  
57 00 72 1  
58 30 73 1  
59 00 74 1  
60 30 75 1  
61 00 76 1  
62 30 77 1  
63 00 78 1  
64 30 79 1  
65 00 80 1  
66 30 81 1  
67 00 82 1  
68 30 83 1  
69 00 84 1  
70 30 85 1  
71 00 86 1  
72 30 87 1  
73 00 88 1  
74 30 89 1  
75 00 90 1



STATION	1. PLAN 1, RATIO 2	END-OF-PERIOD HYDROGRAPH ORDINATES	OUTFLOW	STORAGE
20.00	88			
21.00	89			
22.00	90			
23.00	91			
24.00	92			
25.00	93			
26.00	94			
27.00	95			
28.00	96			
29.00	97			
30.00	98			
31.00	99			
32.00	100			
33.00	101			
34.00	102			
35.00	103			
36.00	104			
37.00	105			
38.00	106			
39.00	107			
40.00	108			
41.00	109			
42.00	110			
43.00	111			
44.00	112			
45.00	113			
46.00	114			
47.00	115			
48.00	116			
49.00	117			
50.00	118			
51.00	119			
52.00	120			


STATION	1. PLAN 1, RATIO 2	END-OF-PERIOD HYDROGRAPH ORDINATES	OUTFLOW	STORAGE
20.00	88			
21.00	89			
22.00	90			
23.00	91			
24.00	92			
25.00	93			
26.00	94			
27.00	95			
28.00	96			
29.00	97			
30.00	98			
31.00	99			
32.00	100			
33.00	101			
34.00	102			
35.00	103			
36.00	104			
37.00	105			
38.00	106			
39.00	107			
40.00	108			
41.00	109			
42.00	110			
43.00	111			
44.00	112			
45.00	113			
46.00	114			
47.00	115			
48.00	116			
49.00	117			
50.00	118			
51.00	119			
52.00	120			





9	00	181
9	30	191
10	00	201
10	30	211
11	00	221
11	30	231
12	00	241
12	30	251
13	00	261
13	30	271
14	00	281
14	30	291
15	00	301
15	30	311
16	00	321
16	30	331
17	00	341
17	30	350
18	00	360
18	30	370
19	00	380
19	30	390
20	00	40
20	30	41
21	00	42
21	30	43
22	00	44
22	30	45
23	00	46
23	30	47
24	00	48
24	30	49
25	00	50
25	30	51
26	00	52
26	30	53
27	00	54
27	30	55
28	00	56
28	30	57
29	00	58
29	30	59
30	00	60
30	30	61
31	00	62
31	30	63
32	00	64
32	30	65
33	00	66
33	30	67
34	00	68
34	30	69
35	00	70
35	30	71
36	00	72
36	30	73
37	00	74
37	30	75

14 00 74  
 14 30 77  
 15 00 78  
 15 30 77  
 16 00 80  
 16 30 81  
 17 00 82  
 17 30 83  
 18 00 84  
 18 30 85  
 19 00 86  
 19 30 87  
 20 00 88  
 20 30 89  
 21 00 90  
 21 30 91  
 22 00 92  
 22 30 93  
 23 00 94  
 23 30 95  
 0 00 97  
 0 30 97  
 1 00 98  
 1 30 100  
 2 00 101  
 3 00 102  
 3 30 103  
 4 00 104  
 4 30 105  
 5 00 106  
 5 30 107  
 6 00 108  
 6 30 109  
 7 00 110  
 7 30 111  
 8 00 112  
 8 30 113  
 9 00 114  
 9 30 115  
 10 00 116  
 10 30 117  
 11 00 118  
 11 30 119  
 12 00 120



\*OVN\*

STATION 1, PLAN 1, RATIO 3  
 END-OF-PERIOD HYDROGRAPH ORDINATES

OUTFLOW

1 00 000  
 1 30 000  
 2 00 000  
 2 30 000  
 3 00 000  
 3 30 000  
 4 00 000  
 4 30 000  
 5 00 000  
 5 30 000  
 6 00 000  
 6 30 000  
 7 00 000  
 7 30 000  
 8 00 000  
 8 30 000  
 9 00 000  
 9 30 000  
 10 00 000  
 10 30 000  
 11 00 000  
 11 30 000  
 12 00 000



3 00 61  
4 00 71  
5 00 81  
6 00 91  
7 00 101  
8 00 111  
9 00 121  
10 00 131  
11 00 141  
12 00 151  
13 00 161  
14 00 171  
15 00 181  
16 00 191  
17 00 201  
18 00 211  
19 00 221  
20 00 231  
21 00 241  
22 00 251  
23 00 261  
24 00 271  
25 00 281  
26 00 291  
27 00 301  
28 00 311  
29 00 321  
30 00 331  
31 00 341  
32 00 3501  
33 00 3601  
34 00 3701  
35 00 3801  
36 00 3901  
37 00 4001  
38 00 4101  
39 00 4201  
40 00 4301  
41 00 4401  
42 00 4501  
43 00 4601  
44 00 4701  
45 00 4801  
46 00 4901  
47 00 5010  
48 00 5100  
49 00 5200  
50 00 5300  
51 00 5400  
52 00 5500  
53 00 5600  
54 00 5700  
55 00 5800  
56 00 5900  
57 00 6000  
58 00 6100  
59 00 6200  
60 00 6300

8 00 64 I  
 8 30 65 I  
 9 00 66 01  
 9 30 67 01  
 10 00 68 01  
 10 30 69 01  
 11 00 70 01  
 11 30 71 01  
 12 00 72 01  
 12 30 73 01  
 13 00 74 01  
 13 30 75 01  
 14 00 76 01  
 14 30 77 01  
 15 00 78 01  
 15 30 79 01  
 16 00 80 01  
 16 30 81 01  
 17 00 82 01  
 17 30 83 01  
 18 00 84 01  
 18 30 85 01  
 19 00 86 01  
 19 30 87 01  
 20 00 88 01  
 20 30 89 01  
 21 00 90 01  
 21 30 91 01  
 22 00 92 01  
 22 30 93 01  
 23 00 94 01  
 23 30 95 01  
 24 00 96 01  
 24 30 97 01  
 25 00 98 01  
 25 30 99 01  
 26 00 100 01  
 26 30 101 01  
 27 00 102 01  
 27 30 103 01  
 28 00 104 01  
 28 30 105 01  
 29 00 106 01  
 29 30 107 01  
 30 00 108 01  
 30 30 109 01  
 31 00 110 01  
 31 30 111 01  
 32 00 112 01  
 32 30 113 01  
 33 00 114 01  
 33 30 115 01  
 34 00 116 01  
 34 30 117 01  
 35 00 118 01  
 35 30 119 01  
 36 00 120 01

\*OVN\*

STATION 1, PLAN 1, RATIO 4  
END-OF-PERIOD HYDROGRAPH ORDINATES

STATION	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME	END-OF-PERIOD HYDROGRAPH ORDINATES					
					0	1	2	3	4	5
0	0	0	0	0	0	0	0	0	0	0
1	1	1	1	1	1	1	1	1	1	1
2	2	2	2	2	2	2	2	2	2	2
3	3	3	3	3	3	3	3	3	3	3
4	4	4	4	4	4	4	4	4	4	4
5	5	5	5	5	5	5	5	5	5	5
6	6	6	6	6	6	6	6	6	6	6
7	7	7	7	7	7	7	7	7	7	7
8	8	8	8	8	8	8	8	8	8	8
9	9	9	9	9	9	9	9	9	9	9
10	10	10	10	10	10	10	10	10	10	10
11	11	11	11	11	11	11	11	11	11	11
12	12	12	12	12	12	12	12	12	12	12
13	13	13	13	13	13	13	13	13	13	13
14	14	14	14	14	14	14	14	14	14	14
15	15	15	15	15	15	15	15	15	15	15
16	16	16	16	16	16	16	16	16	16	16
17	17	17	17	17	17	17	17	17	17	17
18	18	18	18	18	18	18	18	18	18	18
19	19	19	19	19	19	19	19	19	19	19
20	20	20	20	20	20	20	20	20	20	20
21	21	21	21	21	21	21	21	21	21	21
22	22	22	22	22	22	22	22	22	22	22
23	23	23	23	23	23	23	23	23	23	23
24	24	24	24	24	24	24	24	24	24	24
25	25	25	25	25	25	25	25	25	25	25
26	26	26	26	26	26	26	26	26	26	26
27	27	27	27	27	27	27	27	27	27	27
28	28	28	28	28	28	28	28	28	28	28
29	29	29	29	29	29	29	29	29	29	29
30	30	30	30	30	30	30	30	30	30	30
31	31	31	31	31	31	31	31	31	31	31
32	32	32	32	32	32	32	32	32	32	32
33	33	33	33	33	33	33	33	33	33	33
34	34	34	34	34	34	34	34	34	34	34
35	35	35	35	35	35	35	35	35	35	35
36	36	36	36	36	36	36	36	36	36	36
37	37	37	37	37	37	37	37	37	37	37
38	38	38	38	38	38	38	38	38	38	38
39	39	39	39	39	39	39	39	39	39	39
40	40	40	40	40	40	40	40	40	40	40
41	41	41	41	41	41	41	41	41	41	41
42	42	42	42	42	42	42	42	42	42	42
43	43	43	43	43	43	43	43	43	43	43
44	44	44	44	44	44	44	44	44	44	44
45	45	45	45	45	45	45	45	45	45	45
46	46	46	46	46	46	46	46	46	46	46
47	47	47	47	47	47	47	47	47	47	47
48	48	48	48	48	48	48	48	48	48	48
49	49	49	49	49	49	49	49	49	49	49
50	50	50	50	50	50	50	50	50	50	50

PEAK OUTFLOW IS 2769 AT TIME 49.50 HOURS

PEAK	2769
6-HOUR	2420
24-HOUR	1134
72-HOUR	472
TOTAL VOLUME	5669
CFS	69
CMS	3.53
INCHES	6.77
MM	176.08
AC-FT	176.08
	2343

THOUS CU M

1480.

2822.

2890.

STATION 1

INFLOW(I), OUTFLOW(O) AND OBSERVED FLOW(\*)

500. 1000. 1500. 2000. 2500. 3000. 3500. 4000. 0 0 0 0

0	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
0	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100

2	00	5210	
3	30	5310	
4	00	5410	
5	00	5510	
6	00	5610	
7	30	5710	
8	00	5810	
9	00	5910	
10	00	6010	
11	00	6110	
12	00	6210	
13	00	6310	
14	00	6410	
15	00	6510	
16	00	6610	
17	00	6710	
18	00	6810	
19	00	6910	
20	00	7010	
21	00	7110	
22	00	7210	
23	00	7310	
24	00	7410	
25	00	7510	
26	00	7610	
27	00	7710	
28	00	7810	
29	00	7910	
30	00	8010	
31	00	8110	
32	00	8210	
33	00	8310	
34	00	8410	
35	00	8510	
36	00	8610	
37	00	8710	
38	00	8810	
39	00	8910	
40	00	9010	
41	00	9110	
42	00	9210	
43	00	9310	
44	00	9410	
45	00	9510	
46	00	9610	
47	00	9710	
48	00	9810	
49	00	9910	
50	00	00100	
51	00	00101	
52	00	00102	
53	00	00103	
54	00	00104	
55	00	00105	
56	00	00106	
57	00	00107	
58	00	00108	
59	00	00109	



7. 00110  
 8. 00111  
 9. 00112  
 10. 00113  
 11. 00114  
 12. 00115  
 13. 00116  
 14. 00117  
 15. 00118  
 16. 00119  
 17. 00120

\*DOWN\*

STATION 1, PLAN 1, RATIO 5

END-OF-PERIOD HYDROGRAPH ORDINATES

STATION	OUTFLOW		STORAGE		STAGE		STATION	OUTFLOW		STORAGE		STAGE	
	1	2	1	2	1	2		1	2	1	2	1	2
1	1	1	1	1	1	1	1	1	1	1	1	1	1
2	1	1	1	1	1	1	1	1	1	1	1	1	1
3	1	1	1	1	1	1	1	1	1	1	1	1	1
4	1	1	1	1	1	1	1	1	1	1	1	1	1
5	1	1	1	1	1	1	1	1	1	1	1	1	1
6	1	1	1	1	1	1	1	1	1	1	1	1	1
7	1	1	1	1	1	1	1	1	1	1	1	1	1
8	1	1	1	1	1	1	1	1	1	1	1	1	1
9	1	1	1	1	1	1	1	1	1	1	1	1	1
10	1	1	1	1	1	1	1	1	1	1	1	1	1
11	1	1	1	1	1	1	1	1	1	1	1	1	1
12	1	1	1	1	1	1	1	1	1	1	1	1	1
13	1	1	1	1	1	1	1	1	1	1	1	1	1
14	1	1	1	1	1	1	1	1	1	1	1	1	1
15	1	1	1	1	1	1	1	1	1	1	1	1	1
16	1	1	1	1	1	1	1	1	1	1	1	1	1
17	1	1	1	1	1	1	1	1	1	1	1	1	1
18	1	1	1	1	1	1	1	1	1	1	1	1	1
19	1	1	1	1	1	1	1	1	1	1	1	1	1
20	1	1	1	1	1	1	1	1	1	1	1	1	1
21	1	1	1	1	1	1	1	1	1	1	1	1	1
22	1	1	1	1	1	1	1	1	1	1	1	1	1
23	1	1	1	1	1	1	1	1	1	1	1	1	1
24	1	1	1	1	1	1	1	1	1	1	1	1	1
25	1	1	1	1	1	1	1	1	1	1	1	1	1
26	1	1	1	1	1	1	1	1	1	1	1	1	1
27	1	1	1	1	1	1	1	1	1	1	1	1	1
28	1	1	1	1	1	1	1	1	1	1	1	1	1
29	1	1	1	1	1	1	1	1	1	1	1	1	1
30	1	1	1	1	1	1	1	1	1	1	1	1	1
31	1	1	1	1	1	1	1	1	1	1	1	1	1
32	1	1	1	1	1	1	1	1	1	1	1	1	1
33	1	1	1	1	1	1	1	1	1	1	1	1	1
34	1	1	1	1	1	1	1	1	1	1	1	1	1
35	1	1	1	1	1	1	1	1	1	1	1	1	1
36	1	1	1	1	1	1	1	1	1	1	1	1	1
37	1	1	1	1	1	1	1	1	1	1	1	1	1
38	1	1	1	1	1	1	1	1	1	1	1	1	1
39	1	1	1	1	1	1	1	1	1	1	1	1	1
40	1	1	1	1	1	1	1	1	1	1	1	1	1
41	1	1	1	1	1	1	1	1	1	1	1	1	1
42	1	1	1	1	1	1	1	1	1	1	1	1	1
43	1	1	1	1	1	1	1	1	1	1	1	1	1
44	1	1	1	1	1	1	1	1	1	1	1	1	1
45	1	1	1	1	1	1	1	1	1	1	1	1	1
46	1	1	1	1	1	1	1	1	1	1	1	1	1
47	1	1	1	1	1	1	1	1	1	1	1	1	1
48	1	1	1	1	1	1	1	1	1	1	1	1	1
49	1	1	1	1	1	1	1	1	1	1	1	1	1
50	1	1	1	1	1	1	1	1	1	1	1	1	1
51	1	1	1	1	1	1	1	1	1	1	1	1	1
52	1	1	1	1	1	1	1	1	1	1	1	1	1
53	1	1	1	1	1	1	1	1	1	1	1	1	1
54	1	1	1	1	1	1	1	1	1	1	1	1	1
55	1	1	1	1	1	1	1	1	1	1	1	1	1
56	1	1	1	1	1	1	1	1	1	1	1	1	1
57	1	1	1	1	1	1	1	1	1	1	1	1	1
58	1	1	1	1	1	1	1	1	1	1	1	1	1
59	1	1	1	1	1	1	1	1	1	1	1	1	1
60	1	1	1	1	1	1	1	1	1	1	1	1	1
61	1	1	1	1	1	1	1	1	1	1	1	1	1
62	1	1	1	1	1	1	1	1	1	1	1	1	1
63	1	1	1	1	1	1	1	1	1	1	1	1	1
64	1	1	1	1	1	1	1	1	1	1	1	1	1
65	1	1	1	1	1	1	1	1	1	1	1	1	1
66	1	1	1	1	1	1	1	1	1	1	1	1	1
67	1	1	1	1	1	1	1	1	1	1	1	1	1
68	1	1	1	1	1	1	1	1	1	1	1	1	1
69	1	1	1	1	1	1	1	1	1	1	1	1	1
70	1	1	1	1	1	1	1	1	1	1	1	1	1
71	1	1	1	1	1	1	1	1	1	1	1	1	1
72	1	1	1	1	1	1	1	1	1	1	1	1	1
73	1	1	1	1	1	1	1	1	1	1	1	1	1
74	1	1	1	1	1	1	1	1	1	1	1	1	1
75	1	1	1	1	1	1	1	1	1	1	1	1	1
76	1	1	1	1	1	1	1	1	1	1	1	1	1
77	1	1	1	1	1	1	1	1	1	1	1	1	1
78	1	1	1	1	1	1	1	1	1	1	1	1	1
79	1	1	1	1	1	1	1	1	1	1	1	1	1
80	1	1	1	1	1	1	1	1	1	1	1	1	1
81	1	1	1	1	1	1	1	1	1	1	1	1	1
82	1	1	1	1	1	1	1	1	1	1	1	1	1
83	1	1	1	1	1	1	1	1	1	1	1	1	1
84	1	1	1	1	1	1	1	1	1	1	1	1	1
85	1	1	1	1	1	1	1	1	1	1	1	1	1
86	1	1	1	1	1	1	1	1	1	1	1	1	1
87	1	1	1	1	1	1	1	1	1	1	1	1	1
88	1	1	1	1	1	1	1	1	1	1	1	1	1
89	1	1	1	1	1	1	1	1	1	1	1	1	1
90	1	1	1	1	1	1	1	1	1	1	1	1	1
91	1	1	1	1	1	1	1	1	1	1	1	1	1
92	1	1	1	1	1	1	1	1	1	1	1	1	1
93	1	1	1	1	1	1	1	1	1	1	1	1	1
94	1	1	1	1	1	1	1	1	1	1	1	1	1
95	1	1	1	1	1	1	1	1	1	1	1	1	1
96	1	1	1	1	1	1	1	1	1	1	1	1	1
97	1	1	1	1	1	1	1	1	1	1	1	1	1
98	1	1	1	1	1	1	1	1	1	1	1	1	1
99	1	1	1	1	1	1	1	1	1	1	1	1	1
100	1	1	1	1	1	1	1	1	1	1	1	1	1

1464.7 1464.6 1464.9 1464.3 1464.1 1463.9 1463.7 1463.4 1463.2 1463.0  
 1462.8 1462.5 1462.3 1462.1 1462.0 1461.8 1461.6 1461.5 1461.4 1461.2  
 1461.1 1461.1 1461.0 1460.9 1460.8 1460.7 1460.7 1460.6 1460.6 1460.5

PEAK OUTFLOW IS 2853 AT TIME 49.50 HOURS

PEAK 2853  
 CFS 2853  
 CMS 81  
 INCHES 3.66  
 AC-FT 92.88  
 THOUS CU FT 1236  
 1524

6-HOUR 2492  
 1184  
 34  
 71  
 6.96  
 174.76  
 2332  
 2901

72-HOUR 484  
 14  
 7.13  
 180.98  
 2408  
 2970

TOTAL VOLUME 58274  
 1450  
 7.13  
 180.98  
 2408  
 2970


\*OVF\*

STATION 1

	500.	1000.	1500.	2000.	2500.	3000.	3500.	4000.	0.	0.	0.
0.11											
0.30											
1.00											
2.00											
3.00											
4.00											
5.00											
6.00											
7.00											
8.00											
9.00											
10.00											
11.00											
12.00											
13.00											
14.00											
15.00											
16.00											
17.00											
18.00											
19.00											
20.00											
21.00											
22.00											
23.00											
24.00											
25.00											
26.00											
27.00											
28.00											
29.00											
30.00											
31.00											
32.00											
33.00											
34.00											
35.00											
36.00											
37.00											
38.00											
39.00											
40.00											



FLAHERTY GIAVARA ASSOCIATES, P. C.



1 00 98  
 1 30 99  
 2 00 100  
 2 30 101  
 3 00 102  
 3 30 103  
 4 00 104  
 4 30 105  
 5 00 106  
 5 30 107  
 6 00 108  
 6 30 109  
 7 00 110  
 7 30 111  
 8 00 112  
 8 30 113  
 9 00 114  
 9 30 115  
 10 00 116  
 10 30 117  
 11 00 118  
 11 30 119  
 12 00 120

\*DVNS\*

STATION 17 PLAN 17 RATIO 6  
 END-OF-PERIOD HYDROGRAPH ORDINATES

STATION	OUTFLOW	STORAGE
1	1222	1
2	37	1
3	33	1
4	31	1
5	95	1
6	1000	0
7	2776	1
8	1276	1
9	568	1
10	34	0
11	36	1
12	30	1
13	55	1
14	746	17
15	2883	18
16	1398	46
17	603	311
18		813
19		488
20		457
21		772
22		457
23		428
24		428
25		428
26		428
27		428
28		428
29		428
30		428
31		428
32		428
33		428
34		428
35		428
36		428
37		428
38		428
39		428
40		428
41		428
42		428
43		428
44		428
45		428
46		428
47		428
48		428
49		428
50		428
51		428
52		428
53		428
54		428
55		428
56		428
57		428
58		428
59		428
60		428
61		428
62		428
63		428
64		428
65		428
66		428
67		428
68		428
69		428
70		428
71		428
72		428
73		428
74		428
75		428
76		428
77		428
78		428
79		428
80		428
81		428
82		428
83		428
84		428
85		428
86		428
87		428
88		428
89		428
90		428
91		428
92		428
93		428
94		428
95		428
96		428
97		428
98		428
99		428
100		428

283.	269.	257.	246.	236.	226.	216.	208.	200.	192.
1459.0	1459.0	1459.0	1459.0	1459.0	1459.0	1459.0	1459.0	1459.0	1459.0
1459.0	1459.0	1459.0	1459.0	1459.0	1459.0	1459.0	1459.0	1459.0	1459.0
1459.2	1459.2	1459.2	1459.2	1459.2	1459.2	1459.2	1459.2	1459.2	1459.2
1459.1	1459.2	1459.2	1459.2	1459.2	1459.2	1459.2	1459.2	1459.2	1459.2
1459.4	1459.4	1459.5	1459.5	1459.6	1459.7	1459.8	1460.0	1460.3	1460.6
1460.9	1461.4	1461.9	1462.4	1463.0	1463.6	1464.0	1464.4	1464.6	1464.8
1462.8	1462.7	1462.4	1462.2	1462.0	1461.8	1461.7	1461.5	1461.3	1461.0
1461.2	1461.1	1461.0	1460.9	1460.8	1460.8	1460.7	1460.6	1460.6	1460.5

PEAK OUTFLOW IS 2746 AT TIME 49.50 HOURS									
CFB	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL	VOLUME			
2946	1218	2306	1218	499	5287				
85	73	259	73	14	1975				
INCHES	3.76	7.15	7.15	7.32	189.90				
AC-FT	75.63	181.96	187.90	2473	2473				
THOUS CU M	1272	2416	2473	3051	2473				
	1989	2780	3051		3051				

#OVF\*

STATION 1


INFLOW(I), OUTFLOW(O) AND OBSERVED FLOW(O)

500.	1000.	1500.	2000.	2500.	3000.	3500.	4000.	O.	O.
0.11	0.30	1.00	1.20	1.41	1.50	1.50	1.50	0.	0.
1.20	2.30	3.00	4.00	4.71	5.00	5.00	5.00	0.	0.
2.30	3.00	4.00	4.71	5.00	5.00	5.00	5.00	0.	0.
3.00	4.00	4.71	5.00	5.00	5.00	5.00	5.00	0.	0.
4.00	4.71	5.00	5.00	5.00	5.00	5.00	5.00	0.	0.
5.00	5.00	5.00	5.00	5.00	5.00	5.00	5.00	0.	0.
6.00	5.00	5.00	5.00	5.00	5.00	5.00	5.00	0.	0.
7.00	5.00	5.00	5.00	5.00	5.00	5.00	5.00	0.	0.
8.00	5.00	5.00	5.00	5.00	5.00	5.00	5.00	0.	0.
9.00	5.00	5.00	5.00	5.00	5.00	5.00	5.00	0.	0.
10.00	5.00	5.00	5.00	5.00	5.00	5.00	5.00	0.	0.
11.00	5.00	5.00	5.00	5.00	5.00	5.00	5.00	0.	0.
12.00	5.00	5.00	5.00	5.00	5.00	5.00	5.00	0.	0.

FLAHERTY CIAVARA ASSOCIATES, P. C.

14 00 281  
14 30 291  
15 00 301  
15 30 311  
16 00 321  
16 30 331  
17 00 341  
17 30 350  
18 00 360  
18 30 370  
19 00 380  
19 30 390  
20 00 400  
20 30 410  
21 00 420  
21 30 430  
22 00 440  
22 30 450  
23 00 460  
23 30 470  
24 00 480  
24 30 490  
25 00 500  
25 30 510  
26 00 520  
26 30 530  
27 00 540  
27 30 550  
28 00 560  
28 30 570  
29 00 580  
29 30 590  
30 00 600  
30 30 610  
31 00 620  
31 30 630  
32 00 640  
32 30 650  
33 00 660  
33 30 670  
34 00 680  
34 30 690  
35 00 700  
35 30 710  
36 00 720  
36 30 730  
37 00 740  
37 30 750  
38 00 760  
38 30 770  
39 00 780  
39 30 790  
40 00 800  
40 30 810  
41 00 820  
41 30 830  
42 00 840  
42 30 850

00 86  
 19 30 87  
 20 30 88  
 21 30 89  
 22 30 90  
 23 30 91  
 24 30 92  
 25 30 93  
 26 30 94  
 27 30 95  
 28 30 96  
 29 30 97  
 30 30 98  
 31 30 99  
 32 30 100  
 33 30 101  
 34 30 102  
 35 30 103  
 36 30 104  
 37 30 105  
 38 30 106  
 39 30 107  
 40 30 108  
 41 30 109  
 42 30 110  
 43 30 111  
 44 30 112  
 45 30 113  
 46 30 114  
 47 30 115  
 48 30 116  
 49 30 117  
 50 30 118  
 51 30 119  
 52 30 120



\*OVN\*


STATION - 11 PLAN - 11' RATIO 7''  
 END-OF-PERIOD HYDROGRAPH ORDINATES

STATION	ORDINATE	OUTFLOW
0	222	1
1	222	2
2	222	3
3	31	4
4	38	5
5	37	6
6	33	7
7	31	8
8	31	9
9	77	10
10	304	11
11	1534	12
12	861	13
13	222	14
14	222	15
15	222	16
16	17	17
17	41	18
18	32	19
19	31	20
20	31	21
21	59	22
22	44	23
23	174	24
24	219	25
25	206	26
26	205	27
27	834	28
28	904	29
29	407	30
30	428	31
31	222	32
32	82	33
33	40	34
34	31	35
35	31	36
36	48	37
37	306	38
38	2907	39
39	1847	40
40	1713	41
41	404	42





00	161
08	30
09	30
10	30
11	30
12	30
13	30
14	30
15	30
16	30
17	30
18	30
19	30
20	30
21	30
22	30
23	30
24	30
25	30
26	30
27	30
28	30
29	30
30	31
31	31
32	31
33	31
34	31
35	31
36	31
37	31
38	31
39	31
40	31
41	31
42	31
43	31
44	31
45	31
46	31
47	31
48	31
49	31
50	31
51	31
52	31
53	31
54	31
55	31
56	31
57	31
58	31
59	31
60	31
61	31
62	31
63	31
64	31
65	31
66	31
67	31
68	31
69	31
70	31
71	31
72	31
73	31



STATION 1; PLAN 1; RATIO 8  
 END-OF-PERIOD HYDROGRAPH ORDINATES

OUTFLOW 2 2 2 3 3

\*OVNS

AD-A109 796

FLAHERTY-GIAVARA ASSOCIATES NEW HAVEN CT  
NATIONAL DAM SAFETY PROGRAM. LAKE LUDLOW CLUB DAM (INVENTORY NU--ETC(U)  
SEP 81 H C FLAHERTY DACW51-81-C-0006

F/6 13/13

(U)

DACW51-81-C-0006

NL

UNCLASSIFIED

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2

2 1 2


END

DATE

FILMED

2 82

01Q



MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A



41	00	100	300	201
51	30	111	300	221
61	00	111	300	231
71	30	112	300	241
81	00	113	300	251
91	30	114	300	261
101	00	115	300	271
111	30	116	300	281
121	00	117	300	291
131	30	118	300	301
141	00	119	300	311
151	30	120	300	321
161	00	121	300	331
171	30	122	300	341
181	00	123	300	351
191	30	124	300	361
201	00	125	300	371
211	30	126	300	381
221	00	127	300	391
231	30	128	300	401
241	00	129	300	411
251	30	130	300	421
261	00	131	300	431
271	30	132	300	441
281	00	133	300	451
291	30	134	300	461
301	00	135	300	471
311	30	136	300	481
321	00	137	300	491
331	30	138	300	501
341	00	139	300	511
351	30	140	300	521
361	00	141	300	531
371	30	142	300	541
381	00	143	300	551
391	30	144	300	561
401	00	145	300	571
411	30	146	300	581
421	00	147	300	591
431	30	148	300	601
441	00	149	300	611
451	30	150	300	621
461	00	151	300	631
471	30	152	300	641
481	00	153	300	651
491	30	154	300	661
501	00	155	300	671
511	30	156	300	681
521	00	157	300	691
531	30	158	300	701
541	00	159	300	711
551	30	160	300	721
561	00	161	300	731
571	30	162	300	741
581	00	163	300	751
591	30	164	300	761
601	00	165	300	771
611	30	166	300	781
621	00	167	300	791
631	30	168	300	801
641	00	169	300	811
651	30	170	300	821
661	00	171	300	831
671	30	172	300	841
681	00	173	300	851
691	30	174	300	861
701	00	175	300	871
711	30	176	300	881
721	00	177	300	891
731	30	178	300	901
741	00	179	300	911
751	30	180	300	921
761	00	181	300	931
771	30	182	300	941
781	00	183	300	951
791	30	184	300	961
801	00	185	300	971
811	30	186	300	981
821	00	187	300	991
831	30	188	300	001
841	00	189	300	011
851	30	190	300	021
861	00	191	300	031
871	30	192	300	041
881	00	193	300	051
891	30	194	300	061
901	00	195	300	071
911	30	196	300	081
921	00	197	300	091
931	30	198	300	101
941	00	199	300	111
951	30	200	300	121
961	00	201	300	131
971	30	202	300	141
981	00	203	300	151
991	30	204	300	161
001	00	205	300	171
011	30	206	300	181
021	00	207	300	191
031	30	208	300	201
041	00	209	300	211
051	30	210	300	221
061	00	211	300	231
071	30	212	300	241
081	00	213	300	251
091	30	214	300	261
101	00	215	300	271
111	30	216	300	281
121	00	217	300	291
131	30	218	300	301
141	00	219	300	311
151	30	220	300	321
161	00	221	300	331
171	30	222	300	341
181	00	223	300	351
191	30	224	300	361
201	00	225	300	371
211	30	226	300	381
221	00	227	300	391
231	30	228	300	401
241	00	229	300	411
251	30	230	300	421
261	00	231	300	431
271	30	232	300	441
281	00	233	300	451
291	30	234	300	461
301	00	235	300	471
311	30	236	300	481
321	00	237	300	491
331	30	238	300	501
341	00	239	300	511
351	30	240	300	521
361	00	241	300	531
371	30	242	300	541
381	00	243	300	551
391	30	244	300	561
401	00	245	300	571
411	30	246	300	581
421	00	247	300	591
431	30	248	300	601
441	00	249	300	611
451	30	250	300	621
461	00	251	300	631
471	30	252	300	641
481	00	253	300	651
491	30	254	300	661
501	00	255	300	671
511	30	256	300	681
521	00	257	300	691
531	30	258	300	701
541	00	259	300	711
551	30	260	300	721
561	00	261	300	731
571	30	262	300	741
581	00	263	300	751
591	30	264	300	761
601	00	265	300	771
611	30	266	300	781
621	00	267	300	791
631	30	268	300	801
641	00	269	300	811
651	30	270	300	821
661	00	271	300	831
671	30	272	300	841
681	00	273	300	851
691	30	274	300	861
701	00	275	300	871
711	30	276	300	881
721	00	277	300	891
731	30	278	300	901
741	00	279	300	911
751	30	280	300	921
761	00	281	300	931
771	30	282	300	941
781	00	283	300	951
791	30	284	300	961
801	00	285	300	971
811	30	286	300	981
821	00	287	300	991
831	30	288	300	001
841	00	289	300	011
851	30	290	300	021
861	00	291	300	031
871	30	292	300	041
881	00	293	300	051
891	30	294	300	061
901	00	295	300	071
911	30	296	300	081
921	00	297	300	091
931	30	298	300	101
941	00	299	300	111
951	30	300	300	121

7 00 6301  
 8 30 6301  
 9 30 6301  
 10 30 69 01  
 11 30 71 01  
 12 30 72 00  
 13 30 73 00  
 14 30 74 00  
 15 30 75 00  
 16 30 76 00  
 17 30 77 00  
 18 30 78 00  
 19 30 79 00  
 20 30 80 00  
 21 30 81 00  
 22 30 82 00  
 23 30 83 00  
 24 30 84 00  
 25 30 85 00  
 26 30 86 00  
 27 30 87 00  
 28 30 88 00  
 29 30 89 00  
 30 30 90 00  
 31 30 91 00  
 32 30 92 00  
 33 30 93 00  
 34 30 94 00  
 35 30 95 00  
 36 30 96 00  
 37 30 97 00  
 38 30 98 00  
 39 30 99 00  
 40 30 00 00  
 41 30 00 00  
 42 30 00 00  
 43 30 00 00  
 44 30 00 00  
 45 30 00 00  
 46 30 00 00  
 47 30 00 00  
 48 30 00 00  
 49 30 00 00  
 50 30 00 00  
 51 30 00 00  
 52 30 00 00  
 53 30 00 00  
 54 30 00 00  
 55 30 00 00  
 56 30 00 00  
 57 30 00 00  
 58 30 00 00  
 59 30 00 00  
 60 30 00 00  
 61 30 00 00  
 62 30 00 00  
 63 30 00 00  
 64 30 00 00  
 65 30 00 00  
 66 30 00 00  
 67 30 00 00  
 68 30 00 00  
 69 30 00 00  
 70 30 00 00  
 71 30 00 00  
 72 30 00 00  
 73 30 00 00  
 74 30 00 00  
 75 30 00 00  
 76 30 00 00  
 77 30 00 00  
 78 30 00 00  
 79 30 00 00  
 80 30 00 00  
 81 30 00 00  
 82 30 00 00  
 83 30 00 00  
 84 30 00 00  
 85 30 00 00  
 86 30 00 00  
 87 30 00 00  
 88 30 00 00  
 89 30 00 00  
 90 30 00 00  
 91 30 00 00  
 92 30 00 00  
 93 30 00 00  
 94 30 00 00  
 95 30 00 00  
 96 30 00 00  
 97 30 00 00  
 98 30 00 00  
 99 30 00 00  
 00 30 00 00





488.95  
6506  
8025

488.95  
6506  
8025

477.94  
6339  
7844

277.49  
3692  
4334

MM  
AC-FT  
THOUS CU M

80VF\*

STATION 1

INFLW(I), OUTFLOW(O) AND OBSERVED FLOW(\*)

2000 4000 8000 10000 12000

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

FLAHERTY CIAVARA ASSOCIATES, P. C.

501  
 00 511  
 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100 101 102 103 104 105 106 107 108 109 110

6.00108. 1 0  
 7.00110. 1 0  
 8.00112. 1 0  
 9.00114. 1 0  
 10.00116. 1 0  
 11.00118. 1 0  
 12.00120. 1 0

SOVNS

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO-ECONOMIC COMPUTATIONS  
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)  
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION	STATION	AREA	PLAN	RATIO 1	RATIO 2	RATIO 3	RATIO 4	RATIO 5	RATIO 6	RATIO 7	RATIO 8	RATIO 9
				0.30	0.35	0.36	0.37	0.38	0.39	0.40	0.50	1.00
HYDROGRAPH AT	1	6.34 ( 16.42)	1	3022 ( 89.57)	3929 ( 97.83)	4626 ( 102.88)	5727 ( 105.53)	7828 ( 108.58)	9928 ( 111.24)	12029 ( 114.09)	15036 ( 142.61)	18072 ( 283.22)
ROUTED TO	1	6.34 ( 16.42)	1	2188 ( 61.33)	2600 ( 73.83)	2883 ( 76.03)	2782 ( 78.42)	2853 ( 80.80)	2894 ( 83.41)	3041 ( 86.10)	3044 ( 114.51)	254.55 ( 8782)

SUMMARY OF DAM SAFETY ANALYSIS

PLAN	1	INITIAL VALUE	SPILLWAY CREST	TOP OF DAM	DURATION OVER TOP	MAXIMUM OUTFLOW	MAXIMUM STORAGE	MAXIMUM DEPTH OVER DAM	MAXIMUM RESERVOIR STORAGE	RATIO OF PMF	TIME OF FAILURE	TIME OF MAX OUTFLOW
		1459.00	1459.00	1464.70	HOURS	CFS	AC-FT	0.00	W.S. ELEV		HOURS	HOURS
		0.	0.	1807.	0.00	2166.	671.	0.00	1463.81	0.30	0.00	45.50
		0.	0.	2864.	0.00	2600.	757.	0.00	1464.37	0.39	0.00	45.50
		0.	0.		0.00	2685.	774.	0.00	1464.47	0.36	0.00	45.50
		0.	0.		0.00	2853.	791.	0.00	1464.58	0.37	0.00	45.50
		0.	0.		1.50	2894.	823.	0.00	1464.69	0.38	0.00	45.50
		0.	0.		2.00	3041.	839.	0.19	1464.77	0.40	0.00	45.50

FLAHERTY GIARARA ASSOCIATES, P. C.

0:00  
0:00

43.00  
44.50

1.50  
2.50

4044  
8982

979  
1505

1.97  
4.21

1469.77  
1468.97

0:50  
1:00

\*\*\*\*\*  
FLOOD HYDROGRAPH PACKAGE (HEC-1)  
DATA SAFETY VERSION JULY 1978  
LAST MODIFICATION 26 FEB 79  
\*\*\*\*\*

APPENDIX D

PREVIOUS INSPECTION REPORTS/AVAILABLE DOCUMENTS

DAM CONSTRUCTION PERMIT APPLICATION

STATE OF NEW YORK  
DEPARTMENT OF

State Engineer and Surveyor

ALBANY

RECEIVED  
OFFICE STATE ENG.  
MAY 21 1925  
REF ID: \_\_\_\_\_  
ANS: \_\_\_\_\_

Superseded 106-1119

Received \_\_\_\_\_

Dam No. 500 Susquehanna Watershed

Disposition Approved Jan 6 - 1925

Serial No. 106-1119-620

Foundation inspected \_\_\_\_\_

Structure inspected \_\_\_\_\_

Application for the Construction or Reconstruction of a Dam

Application is hereby made to the State Engineer, Albany, N. Y., in compliance with the provisions of Chapter LXV of the Consolidated Laws and Chapter 647, Laws of 1911, Section 22 as amended, for the approval of specifications and detailed drawings, marked The Lake Ludlow Club, Inc. Dam, Oxford, N. Y.

herewith submitted for the { construction reconstruction } of a dam located as stated below. All provisions of law will be complied with in the erection of the proposed dam. It is intended to complete the work covered by the application about September 1st, 1925.  
(Date)

1. The dam will be on Ludlow Brook flowing into Chenango River in the town of McDonough, County of Chenango and 6 miles Northwest of Oxford, N. Y.  
(Give exact distance and direction from a well-known bridge, dam, village main cross-roads or mouth of a stream)

2. The name and address of the owner is Lake Ludlow Club, Inc., Oxford, N. Y.

3. The dam will be used for Increasing size of lake for recreation purposes

4. Will any part of the dam be built upon or its pond flood any State lands? No

5. The watershed at the proposed dam draining into the pond to be formed thereby is 6.5 square miles.

6. The proposed dam will have a pond area at the spillcrest elevation of 240 acres and will impound 42,000,000 cubic feet of water.

7. The lowest part of the natural shore of the pond is 18 feet vertically above the spillcrest, and everywhere else the shore will be at least 100 feet above the spillcrest.

8. The maximum known flow of the stream at the dam site was \_\_\_\_\_ cubic feet per second on \_\_\_\_\_ (Date)

9. State if any damage to life or to any buildings, roads or other property could be caused by any possible failure of the proposed dam Very small possibility of any damage

10. The natural material of the bed on which the proposed dam will rest is (clay, sand, gravel, boulders, granite, shale, slate, limestone, etc.) clay

11. The material of the right bank, in the direction with the current, is.....clay.....; at the spillcrest elevation this material has a top slope of 12 inches vertical to a foot horizontal on the center line of the dam, a vertical thickness at this elevation of 10 feet, and the top surface extends for a vertical height of 200 feet above the spillcrest. (In deep natural valley)

12. The material of the left bank is.....clay.....; has a top slope of 8 inches to a foot horizontal, a thickness of 10 feet and a height of 100 feet.

13 State the character of the bed and the banks in respect to the hardness, perviousness, water bearing, effect of exposure to air and to water, uniformity, etc. Bed is composed of hard impervious clay with some stones imbedded. Exposure to air and water have had no effect on bed and banks

14. If the bed is in layers, are the layers horizontal or inclined? not in layers If inclined what is the direction of the horizontal outcropping relative to the axis of the main dam and the inclination and direction of the layers in a plane perpendicular to the horizontal outcropping

15. What is the thickness of the layers?

16. Are there any porous seams or fissures? No

17. WASTES. The spillway of the above proposed dam will be 20 feet long in the clear; the waters will be held at the right end by an abutement the top of which will be 4 feet above the spillcrest, and have a top width of 1 feet; and at the left end by an abutement the top of which will be 4 feet above the spillcrest, and have a top width of 1 feet.

18. There will be also for flood discharge a pipe 24 inches inside diameter and the bottom will be 12 feet below the spillcrest, a sluice or gate 2 feet wide in the clear by 2 feet high, and the bottom will be 12 feet below the spillcrest.

19. APRON. Below the proposed dam there will be an apron built of paved spillway around end of dam feet long across the stream, ..... feet wide and ..... feet thick. The downstream side of the apron will have a thickness of ..... feet for a width of ..... feet.

20. PLANS. Each application for a permit of a dam over 12 feet in height must be accompanied by a location map and complete working drawings in triplicate of the proposed structure, one set of which will be returned if they are approved. Each drawing should have a title giving the parts shown, the name of the town and county in which the dam site is located, and the name of the owner and of the engineer.

The location map (U. S. Geological Quadrangle or other map) should show the exact location of the proposed dam; of buildings below the dam which might be damaged by any failure of the dam; of roads adjacent to or crossing the stream below the dam, giving the lowest elevation of the roadway above the stream bed and giving the shape,



the height and the width of stream openings; and of any embankments or steep slopes that any flood could pass over. Also indicate the character and use made of the ground below the dam.

The complete working drawings should give all the dimensions necessary for the calculations of the stability of the structure, and all the information asked for below under "Sketches." There may be attached to the application any written reports, calculations, investigations or opinions that may aid in showing the data and method used by the designer. State the assumed ice and uplift pressures and the conditions on which based.




21. SKETCHES. For small and unimportant structures, if plans have not been made, on the back of this application make a sketch to scale for each different cross-section at the highest point; giving the height and the depth from the surface of the foundation, the bottom width, the top width (for a concrete or masonry spill at 18 inches below the crest), the elevation of the top in reference to the spillcrest, the length of the section, and the material of which the section is to be constructed; on the spillway section show a cross section of the apron, giving its width, thickness and material, and show the abutment or wash wall at the end of the spillway, giving its heights and thickness. Mark each section with a capital letter. Also sketch a plan; show the above sections by their top lines, giving the mark and the length of each; the openings by their horizontal dimensions; the abutments by their top width and top lengths from the upstream face of the spillcrest; and outline the apron. Also sketch an elevation of each end of the dam with a cross section of the banks, giving the depth and width excavated into the banks.

22. ELEVATIONS. Also give the elevations, if possible from the Mean Sea Level, of at least two permanent Bench Marks; of the spillcrest for any existing dam on the proposed dam site, at the middle and at the ends of the spill; of the spillcrest for the above proposed dam; and of the spillcrest of any adjacent dams.

23. SAMPLES. When so instructed, send samples of the materials to be used in the construction of the proposed dam, using shipping tags which will be furnished. For sand, one-half a cubic foot is desired (exclusive of any stone over  $\frac{1}{4}$  inch in size mixed therewith); for cement, three pints; and for the natural bed, twenty cubic inches if of ledge and one-half a cubic foot if of soil.

24. INSPECTION. State how inspection is to be provided for during construction. The club will provide a competent inspector to insure proper construction

25. WATER SUPPLY. Are the waters impounded by the above dam to be used for a public water supply? No  
Has an application under the provisions of Article IX of the Conservation Law for such use been made to the Water Control Commission, Albany, N. Y.?



The above information is correct to the best of my knowledge and belief.

Oxford, N. Y.  
(Address of signer)

May 18, 1925  
(Date)

The Lake Ludlow Club, Inc.

F. Tainter Coburn, Pres.  
(A person signing for owner should indicate his title or authority)

DESIGN DATA

## COMPUTATIONS USED IN THE DESIGN OF SPILLWAY.

### LAKE LUDLOW CLUB DAM.

#### WATER SHED

Area 6.5 Sq. Miles. 10 Sq.Miles used in computations  
Turneure & Russell 'Public Water Supplies table gives 10 in.  
per 24 hrs. as a maximum rainfall giving 268.9 cu.ft.per sec.  
per sq.mile,giving 2689 cu.ft.per sec.Maximum discharge over  
spillway.

Using data given in Amer.Civil Eng.Handbook on Mill Brook  
Reservoir Edmeston N.Y. with drainage area of 9.4 sq.mi.  
241 cu.ft. sec. per sq.mile. which would give a comparative  
maximum discharge of 2410 cu.ft. sec. over the spillway.

#### LOCATION

The proposed site of the dam is located 1350 ft.below  
the present lake Ludlow containing about 80 acres in area.  
It is proposed to raise the level of the lake 6 ft. by con-  
structing a dam on the site of an old dam which was washed  
out some years ago.There is left standing a dry laid up stone  
wall,and it is our intentions to complete the wall where it  
has been washed out and place a puddled clay core wall above,  
together with the earth fill above and below. We plan on  
constructing a heavy rein. concrete culvert with a gate on the  
upper end to take care of the water during constructing of the  
dam.This will also provide a means to drain the lake if at  
any time it should become necessary. It is planned to place  
several baffles on the outside of the culvert to obstruct any  
seepage of water along the outside of the concrete.

# Design of Spillway Lake Ludlow Club Dam

Spillway 20 ft. Wide 3' Deep 100 ft. Long.

Chezy Formula

$$V = c \sqrt{rS}$$

$c$  = a coefficient

$r$  = hydraulic radius

$$= \frac{60}{26} = 2.3 <$$

Kutters Formula

$S$  = Sine of Slope

$$= \frac{14}{100} = .14$$

$$c = \frac{\frac{1.81}{.017} + 41.65 + \frac{.0028}{S}}{1 + \frac{41.65 + \frac{.0028}{S}}{\sqrt{r}}}$$

$$= \frac{\frac{1.81}{.017} + 41.65 + \frac{.0028}{.14}}{1 + \frac{41.65 + \frac{.0028}{.14}}{\sqrt{2.3}}} = \frac{148.17}{1.465}$$

$$= 101$$

$$V = 101 \sqrt{2.3 \times .14}$$

$$= 57.5 \text{ C.F.S.}$$

$$Q = 60 \times 57.5$$

$$= 3450.0 \text{ C.F.S.}$$

It was decided to use a 20 ft. Spillway paved with large stone and securely grouted.

SOILS ANALYSES

COPY FOR MR. MCKIM:

July 23, 1925.

Dam 500 Susquehanna,  
Sand.

Mr. F. Taintor Corbin,  
President, Lake Ludlow Club, Inc.,  
Oxford, N. Y.

Dear Sir:

The receipt of your letter of July 6th, 1925, in regard to the dam which you proposed to build, is acknowledged. The sand mentioned in your letter from the Winsor bank has been examined by the State Highway Commission in 1923 and accepted for use in concrete and should give good results in the work which you are undertaking. The use of this sand meets with the approval of this department.

The reason for requesting a sample of sand proposed for use was to insure that only good sand be used in the concrete. It is suggested that, as the nature of the sand obtained from the bank at the present time may be different from that obtained in 1923, you send a sample to our testing laboratory for a check test.

Yours very truly,

Roy G. Finch,  
State Engineer.

By  
Assistant Deputy.

TLW/ECH



STATE OF NEW YORK  
STATE ENGINEER AND SURVEYOR  
ALBANY

ROY G. FINCH  
STATE ENGINEER  
FRANK R. LANAGAN  
DEPUTY  
THOS. L. WATKINS  
ASSISTANT DEPUTY

ADDRESS ALL COMMUNICATIONS TO  
ROY G. FINCH, STATE ENGINEER

August 13, 1925.

Hon. Roy G. Finch,  
State Engineer,  
Albany, N. Y.

RECEIVED  
AUG 15 1925  
STATE ENGINEER  
ALBANY

Dear Sir:-

We have tested and examined a sample of material submitted by Dr. A. R. Morse, Vice President of the Lake Ludlow Club, Inc., of Oxford, N. Y., and proposed for use as core in the dam at Lake Ludlow.

"The contract calls for a clay core of blue clay or a substitute equally as good -----." This is quoted from the letter from Dr. Morse in transmitting the sample.

Tests show that the sample graded as follows:-

Passing Sieve No.	Sample as received	Sample free from gravel (above $\frac{1}{4}$ " )
4	73 %	
6	70	96 %
10	67	92
20	62	83
30	59	81
40	57	78
60	52	72
100	48	66
200	35	48

This material mixed into a very good plastic mass and should prove to be a satisfactory core material.

Yours very truly,

*Francis J. Sherman*

Sen. Asst. Engineer  
in charge of Tests.



PREVIOUS INSPECTION REPORTS

STATE OF NEW YORK  
DEPARTMENT OF STATE ENGINEER AND SURVEYOR  
MIDDLE DIVISION  
WEIGH LOCK BUILDING

SUBJECT: DAM NO. 500 *Sms*  
OXFORD - SUSQUEHANNA

SYRACUSE

July 27, 1925.

Mr. Wm. W. Cronin,  
Division Engineer,  
Syracuse, N.Y.

Dear Sir:

On July 24th I visited the site of the dam under construction at the lower end of Ludlow Pond, owned by the Lake Ludlow Club of Oxford.

This dam is located in a very rough country, about seven miles by road northwest of the village of Oxford. The pond is to be raised by this dam about 10 ft. above present elevation. On the site of this new dam there are portions of an old dry stone dam very nearly the height of the present dam. The existing portions of this dam are to be left in place to serve as a protection against any possibility of muskrats boring through the new earthen structure.

The center portion of the stream valley, where the old dam has been carried out, is to be enclosed by a line of steel sheet piling driven well into the clay hardpan. The existing portions of the old masonry are not water tight, but the plan is to bank this up with a 3 ft. layer of clay puddle, against which an earth fill, also made of clay soil, will be placed.

On the northeastern end of the dam the spillway is to be constructed. This spillway is to consist of a paved channel 33 ft. in width, separated from the earthen portion of the dam by a concrete wall  $5\frac{1}{2}$  ft. in height. The underlying material here is a very dense clay hardpan, and with the paving, as plans provide, should probably furnish a safe spillway.

On the plans under which the contractor is working no cut-off wall was provided at the crest of the spillway section. I suggested that such a cut-off wall be provided by excavating a trench to the same depth as the side walls in the spillway channel; that is,  $2\frac{1}{2}$  ft. below the top of the paving, and filling this with concrete up to the top elevation of the paving at its highest point.

The President of the Lake Ludlow Club, who was with me, agreed with me that this was a reasonable precaution and instructed the contractor, while I was there, to put in such a cut-off.

The reinforced concrete culvert for drawing down the lake, in case it is desirable, has been constructed and appears to be of really good quality concrete. One wall for the spillway channel has been built and the trench for the other wall is now being dug.

I examined the bed of clay which will be used in making the puddle core wall for the dam and it appears to be of the best material; a very dense

-2-

blue clay containing a considerable percentage of small stones.

A portion of the stone paving had been placed, but not grouted, near the lower end of the spillway channel. This was fully 12" in depth, but did not consist of very large stones. This, however, would not be of serious consequence after the paving is grouted.

Respectfully submitted,

*Foster B. Rocky*  
-----  
Asst. Engr.


FBC:ALG

DAM CONSTRUCTION PERMIT APPLICATION

STATE OF NEW YORK



DEPARTMENT OF PUBLIC WORKS  
DIVISION OF ENGINEERING  
ALBANY



Received May 21, 1937  
Disposition June 16, 1937  
Foundation inspected \_\_\_\_\_  
Structure inspected \_\_\_\_\_

Dam No. 106-1119  
Watershed Susquehanna

### Application for the Construction or Reconstruction of a Dam

Application is hereby made to the Superintendent of Public Works, Albany, N. Y., in compliance with the provisions of Section 948 of the Conservation Law (see last page of this application) for the approval of specifications and detailed drawings, marked Dam for Lake Ludlow Club.

Oxford, New York.

herewith submitted for the { construction }  
  { reconstruction } of a dam herein described. All provisions of law will be complied with in the erection of the proposed dam. It is intended to complete the work covered by the application about September 1st, 1937.  
(Date)

1. The dam will be on Ludlow Brook flowing into Chenango River in the town of McDonough, County of Chenango and 300 ft. south of Ludlow Club House  
(give exact distance and direction from a well-known bridge, dam, village main cross-roads or mouth of a stream)

2. Location of dam is shown on the Oxford quadrangle of the United States Geological Survey.

3. The name of the owner is The Lake Ludlow Club Inc.

4. The address of the owner is Oxford, New York.

5. The dam will be used for Maintaining level of Lake Ludlow

6. Will any part of the dam be built upon or its pond flood any State lands? No.

7. The watershed above the proposed dam is 6.32 square miles.

8. The proposed dam will create a pond area at the spillcrest elevation of 100 acres and will impound 21,780,000 cubic feet of water.

9. The maximum height of the proposed dam above the bed of the stream is 16 feet          inches.
10. The lowest part of the natural shore of the pond is 15 feet vertically above the spillcrest, and everywhere else the shore will be at least 25 feet above the spillcrest.
11. State if any damage to life or to any buildings, roads or other property could be caused by any possible failure of the proposed dam. Very small possibility of any damage.
- 
12. The natural material of the bed on which the proposed dam will rest is (clay, sand, gravel, boulders, granite, shale, slate, limestone, etc.) Clay
13. Facing down stream, what is the nature of material composing the right bank? Clay
- 
14. Facing down stream, what is the nature of the material composing the left bank? Same
- 
15. State the character of the bed and the banks in respect to the hardness, perviousness, water bearing, effect of exposure to air and to water, uniformity, etc. Hard impervious clay with some stones imbedded. Exposed to air and water have had no effect.
- 
16. Are there any porous seams or fissures beneath the foundation of the proposed dam? No
- 
17. WASTES. The spillway of the above proposed dam will be 70 feet long in the clear; the waters will be held at the right end by a Core wall and crib the top of which will be 5 feet above the spillcrest, and have a top width of 5 feet; and at the left end by a same as right end the top of which will be 5 feet above the spillcrest, and have a top width of 5 feet.
18. The spillway is designed to safely discharge 1000 cubic feet per second.
19. Pipes, sluice gates, etc., for flood discharge will be provided through the dam as follows:  
None
- 
20. What is the maximum height of flash boards which will be used on this dam? None
21. APRON. Below the proposed dam there will be an apron built of Cribbing and cut off wall 50 feet long across the stream, 50 feet wide and 2 feet thick.
22. Does this dam constitute any part of a public water supply? No

## SECTION 948 OF THE CONSERVATION LAW

§ 948. Structures for impounding water; inspection of docks; penalties. No structure for impounding water and no dock, pier, wharf or other structure used as a landing place on waters shall be erected or reconstructed by any public authority or by any private person or corporation without notice to the superintendent of public works, nor shall any such structure be erected, reconstructed or maintained without complying with such conditions as the superintendent of public works may by order prescribe for safeguarding life or property against danger therefrom. No order made by the superintendent of public works shall be deemed to authorize any invasion of any property rights, public or private, by any person in carrying out the requirements of such order. The superintendent of public works shall have power, whenever in his judgment public safety shall so require, to make and serve an order directing any person, corporation, officer or board, constructing, maintaining or using any structure hereinbefore referred to, remove, repair or reconstruct the same within such reasonable time and in such manner as shall be specified in such order, and it shall be the duty of every such person, corporation, officer or board, to obey, observe and comply with such order and with the conditions prescribed by the superintendent of public works for safeguarding life or property against danger therefrom, and every person, corporation, officer or board failing, omitting or neglecting so to do, or who hereafter erects or reconstructs any such structure hereinbefore referred to without submitting to the superintendent of public works and obtaining his approval of plans and specifications for such structures when required so to do by his order or who hereafter fails to remove, erect or to reconstruct the same in accordance with the plans and specifications so approved shall forfeit to the people of this state a sum not to exceed five hundred dollars to be fixed by the court for each and every offense; every violation of any such order shall be a separate and distinct offense, and, in case of a continuing violation, every day's continuance thereof shall be and be deemed to be a separate and distinct offense. This section shall not apply to a dam where the area draining into the pond formed thereby does not exceed one square mile, unless the dam is more than ten feet in height above the natural bed of the stream at any point or unless the quantity of water which the dam impounds exceeds one million gallons; nor to a dock, pier, wharf or other structure under the jurisdiction of the department of docks, if any, in a city of over one hundred and seventy-five thousand population. This section as hereby amended shall not impair the effect of an order heretofore made by the conservation commission or commissioner under this section prior to the taking effect of chapter four hundred and ninety-nine of the laws of nineteen hundred and twenty-one, nor require the approval by the superintendent of public works of plans and specifications heretofore approved by such commission or commissioner under this section.

The foregoing information and accompanying plans and specifications are correct to the best of my knowledge and belief.

Lake Ludlow Club Inc., Owner

By F Jainton Corbin, Pres., authorized agent of owner.

Address of signer Oxford, New York. Date May 13th, 1937.

PREVIOUS INSPECTION REPORTS



NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION  
 DAM INSPECTION REPORT  
 (By Visual Inspection)

Ludlow Lake Club

Dam Number	River Basin	Town	County	Hazard Class*	Date & Inspector
106-1119	Susq	McDonough	Chenango	B	4/17/75

Type of Construction

- Earth w/concrete spillway
- Earth w/drop inlet pipe
- Earth w/stone or riprap spillway
- Concrete
- Stone
- Timber

Use

- Water Supply
- Power
- Recreation
- Fish and Wildlife
- Farm Pond
- No Apparent Use-Abandoned

Estimated Impoundment Size

- 1-5 acres
- 5-10 acres
- Over 10 acres

Estimated Height of Dam above Streambed

- Under 10 feet
- 10-25 feet
- Over 25 feet

Condition of Spillway

- Service satisfactory
- In need of repair or maintenance
- Auxiliary satisfactory
- In need of repair or maintenance

Explain: \_\_\_\_\_

Condition of Non-Overflow Section

- Satisfactory
  - In need of repair or maintenance
- Explain: \_\_\_\_\_

Condition of Mechanical Equipment

- Satisfactory
  - In need of repair or maintenance
- Explain: \_\_\_\_\_

Evaluation (From Visual Inspection)

- No defects observed beyond normal maintenance
- Repairs required beyond normal maintenance

\*Explain Hazard Class, if Necessary Large Impoundment



**FLAHERTY  
GIAVARA  
ASSOCIATES, P.C.**

ONE COLUMBUS PLAZA  
NEW HAVEN, CONN. 06510  
203/789-1260

HUGH C. FLAHERTY, P.E., L.S.  
S. GIAVARA, P.E.

March 30, 1981

Department of the Army  
New York District  
Corps of Engineers  
26 Federal Plaza  
New York, New York 10007

Attention: Mr. Thomas F. Costanzo  
Civil Projects Management Branch  
Room 2123

Re: Initial Screening  
Lake Ludlow Club Dam  
Dam NY 350  
DACW 51-81-C-0006  
FGA No. 80 121 10

Dear Mr. Costanzo:

In accordance with the subject contract, an initial screening of the downstream hazard potential of Lake Ludlow Club Dam (NY 350) located in McDonough, New York (Chenango County) was conducted.

The site was visited on December 16, 1980 for the purpose of determining existing development in the area that would be affected by a dam failure flood wave and verifying existing dam inventory data (i.e., height, crest length, etc.). In addition, FGA contacted the firm of Stetson-Dale who had originally classified the dam as having a "high" downstream hazard potential (D/S Hazard -1). Stetson-Dale was required to select a hazard classification for the dam during their contract to update and complete the Inventory of Non-Federal Dams for the New York District.

The dam is 22 feet high, with a crest length of 130 feet and a spillway width of 70 feet (see photos no. 1, 2 and 3). The initial flood wave impact area is located approximately one mile downstream of the dam (see attached Flood Impact Map, sheet 1 of 2). Approximately 3 to 4 houses would be affected (see photos no. 4, 5 and 6). The secondary impact area is the borough of Tyner which is located about 3.5 miles downstream of the

- Engineering
- Environmental Sciences
- Planning
- Surveys
- Testing



FLAHERTY  
GIAVARA  
ASSOCIATES, P.C.

Initial Screening - Lake Ludlow Club Dam - Dam NY 350

Page 2

dam (see attached Flood Impact Map, sheet 2 of 2). Several buildings and a church are located in this area. The flood wave would continue down Bowman Creek in a narrow steep-sided valley until spreading out on a broad floodplain in South Oxford just before entering the Chenango River. Several dwellings are located in this floodplain.

Mr. Terry Hardin of Stetson-Dale related that the primary reason for classifying the dam "High Hazard" was that the Lake Ludlow Dam had failed in the flood of 1935 and had killed several people downstream in Tyner. FGA obtained original newspaper accounts appearing in the July 11, 1935 edition of "The Oxford Review-Times", copies of which are attached. These reports indicated that in the early morning of July 8, 1935, after very heavy rains and initial flooding, the Lake Ludlow Dam failed and its waters "coursed down through the valley".

When the water struck Tyner, the old Universalist Church and four buildings including a portion of the old Tyner cheese factory were destroyed. Several bridges were washed out and all the lowlands down in the valley were rock strewn, gutted or entirely washed out. Quantities of hay and crops, the value of which could not be estimated, were ruined. The destruction included the entire reach from Lake Ludlow to the Chenango River. Three lives were lost as a result of the flooding.

In accordance with the Recommended Corps of Engineers Guidelines, in order to classify a dam as having a "high" downstream hazard potential it must be located in an area "where failure may cause serious damage to homes, extensive agricultural, industrial and commercial facilities, important public utilities, main highways or railroads", or that more than a few lives would be lost.

Based on our site visit, inspection of existing downstream conditions, review of the results of initial flooding and an actual dam failure flood wave (1935), we believe that the downstream hazard classification should remain "high". We recommend that the dam receive a Phase I Dam Inspection.



FLAHERTY  
GIAVARA  
ASSOCIATES, P.C.

Initial Screening - Lake Ludlow Club Dam - Dam NY 350

Page 3

We trust this is the information you require at this time. Please let me know if we should proceed with the Phase I investigation of the Lake Ludlow Club Dam.

Very truly yours,

FLAHERTY GIAVARA ASSOCIATES, P.C.

*Robert C. Smith*

Robert C. Smith, P.E.  
Project Manager

/car

Enclosures

cc: Mr. George Koch  
New York State Department of  
Environmental Conservation



PHOTO #1: Downstream face of dam




PHOTO #2: Crest of dam looking toward right abutment



PHOTO #3: Downstream channel conditions



PHOTO #4: Upstream view from bridge (See  
Flood Impact Map - sheet 2 of 2)



PHOTO #5: Upstream face of bridge (See Flood Impact Map - sheet 2 of 2)



PHOTO #6: Downstream view from bridge (See Flood Impact Map - sheet 2 of 2)

# THE OXFORD

## NEW NEW TIMES

OXFORD, NEW YORK, THURSDAY MORNING, JULY 31, 1936

### Mr. and Mrs. Fred Robbins and McWilliams Boy Carried Away by Bowman Creek

All Buildings of Pleasant Homestead at South  
Oxford Wiped Out Between 3 and 4 a. m.  
Monday Morning from Repeated Storms

Death, destruction and desolation were spread throughout the town of Oxford and this part of New York state Sunday night and Monday morning as a result of repeated cloudbursts during the night which spread eight inches of water over the land, the majority of it within two or three hours. Damages in the township will probably amount to half a million dollars or more.

The only ones known to have lost their lives here were Mr. and Mrs. Fred Robbins who lived in the old Powers house on the south side of Bowman creek. Their house, barn and other farm buildings were swept before the angry waters descending the gorge between 3 and 4 o'clock Monday morning.

Clayton Soules, who lives across the creek and on the same side of the highway from the Robbins home, reported seeing a light in the Robbins house as late as 2 a. m. When they arose at 4 o'clock not a building on their neighbor's place was left.

### Ludlow Damaged; Bowman Creek is Great Destroyer

Three Lives, Dozen Buildings, Numerous Bridges, Fields, Crops, Destroyed By Terrific Water Forces.

Church at Tyner and  
Four Buildings Gone

Part of Cheese Factory Is  
Torn Off; Upper Bridge  
Goes Out with No Trace  
of Girders or Timbers.

Bowman creek was probably the fiercest of the streams which caused havoc in this section Sunday night and Monday morning. Added to the raging torrent from the cloudbursts was the water from Lake Ludlow which coursed down through the valley when the dam below the church house failed to withstand the great pressure behind it.


As the water from Richmond brook struck Tyner, four buildings and a part of the old Tyner cheese factory were carried off their foundations, crushed into bits and hurled along down the valley to add to the force of the stream which wiped out the Robbins buildings at South Oxford.

The old Universalist church on the north road out of Tyner was the first structure to go. As it floated off its foundations, it gathered speed and crashed into the Grange hall where it was partially smashed. Veering off from here it gradually went to pieces as it sailed down the valley.

The old house and barn on the former Annis Hall place, now owned by Mrs. Ned Landers, were both carried away as was the barn belonging to Clifford Still, and a portion of the cheese factory, also his property. The upper bridge was carried away despite its remarkable height above the normal stream, and the bridge at Ralph Sharpe's was also wiped out. Not a trace of the upper bridge has been found.

FLAHERTY · GIAVARA ASSOCIATES, P.C.





**VICINITY MAP**

" = 47 MILES

**INITIAL FLOOD WAVE  
IMPACT AREA  
(BRIDGE DESTROYED)**

**DAM**

**PROJECT  
SITE**

**NOTE:**

SEE SHEET 2 OF 2  
PROPERTY DAMAGE RESULTING FROM  
THE LAKE LUDLOW CLUB DAM FAILURE  
ON JULY 8, 1935 IS INDICATED ABOVE.

**FLOOD IMPACT MAP**

**LAKE LUDLOW CLUB DAM  
INVENTORY No. NY 350**

SUSQUEHANNA RIVER BASIN  
CHENANGO COUNTY  
Mc DONOUGH, NEW YORK


SHEET 1 OF 2



0 2000 4000

SCALE IN FEET

FLAHERTY · GIAVARA ASSOCIATES, P.C.



**NOTE:**  
 LOSS OF LIFE AND PROPERTY DAMAGE  
 RESULTING FROM THE LAKE LUDLOW  
 CLUB DAM FAILURE ON JULY 8, 1935  
 IS INDICATED ABOVE.



0      2000      4000

SCALE IN FEET

## FLOOD IMPACT MAP

LAKE LUDLOW CLUB DAM  
 INVENTORY No. NY 350

SUSQUEHANNA RIVER BASIN  
 CHENANGO COUNTY  
 McDONOUGH, NEW YORK

SHEET 2 OF 2

APPENDIX E  
STRUCTURAL STABILITY ANALYSIS

(No STRUCTURAL STABILITY ANALYSIS was required for this dam)


APPENDIX F  
REFERENCES

## REFERENCES

1. Chow, Ven Te, Editor - Handbook of Applied Hydrology. McGraw-Hill Book Company, New York, New York, 1964.
2. Hydrologic Engineering Center, U.S. Army Corps of Engineers, HEC-1 Flood Hydrograph Package, Users Manual. Davis, California, January 1973.
3. Hydrologic Engineering Center, U.S. Army Corps of Engineers, Flood Hydrograph Package (HEC-1), Users Manual for Dam Safety Investigations, Davis, California, September 1978.
4. King, Horace and Brater, Ernest. Handbook of Hydraulics, 5th Edition. McGraw-Hill Book Company, New York, New York, 1963.
5. Riedel, J.T., Appleby, J.F. and Schloemer, R.W. Seasonal Variation of the Probable Maximum Precipitation East of the 105th Meridian for Areas from 10 to 1000 Square Miles and Durations of 6, 12, 24, and 48 Hours (Hydrometeorological Report No. 33) U.S. Department of Commerce - Weather Bureau and U.S. Department of the Army - Corps of Engineers, Washington, D.C., April 1956
6. U.S. Department of the Interior, Bureau of Reclamation, Design of Small Dams, Second Edition, Washington, D.C., 1973.

APPENDIX G



DRAWINGS



NOTE: ALL CONCRETE TO BE CURVED TO THE PROPER RADIUS.

DESIGNED BY  
 DRAWN BY  
 CHECKED BY





NOTE: ALL COLS AND BEAMS  
TO BE CONCRETE TO FULL FOUNDATION  
AS SHOWN.

PLAN FOR LINE LUDLOW CLING  
 CHICAGO - N.Y.  
 DRAWN BY: J.C. McCarty  
 FOR: J.C. McCarty - Bureau of  
 DRAWN BY: H.C. [unclear]