


AD-A109 838

NEW YORK STATE DEPT OF ENVIRONMENTAL CONSERVATION ALRANY F/G 13/13
NATIONAL DAM SAFETY PROGRAM, GOSHEN RESERVOIR NUMBER 1 DAM (INV--ETC(U))
AUG 81 G KOCH DACW51-79-C-0001

UNCLASSIFIED

NL

1 of 2
40 A
1098 1*




1

OF



AD A

109838



3.2 EVALUATION OF OBSERVATIONS

Visual observations made during the course of the investigation reveal

REPORT DOCUMENTATION PAGE

LEVEL 1
 READ INSTRUCTIONS
 BEFORE COMPLETING FORM
 14 REPORT NUMBER
 15 REPORT NUMBER'S CATALOG NUMBER

1. REPORT NUMBER AD-A 104834	2. GOVT ACCESSION NO.	3. REPORT NUMBER'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Inspection Report Goshen Reservoir No. 1 Dam Lower Hudson River Basin, Orange County, NY Inventory No. NY00488	5. TYPE OF REPORT & PERIOD COVERED Phase I Inspection Report National Dam Safety Program	
7. AUTHOR(s) GEORGE KOCH	6. PERFORMING ORG. REPORT NUMBER	
9. PERFORMING ORGANIZATION NAME AND ADDRESS New York State Department of Environmental Conservation 50 Wolf Road Albany, New York 12233	8. CONTRACT OR GRANT NUMBER(s) DACW51-79-C-0001	
11. CONTROLLING OFFICE NAME AND ADDRESS Department of the Army 26 Federal Plaza New York District, CofE New York, New York 10287	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS	
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) Department of the Army 26 Federal Plaza New York District, CofE New York, NY 10287	12. REPORT DATE 14 September 1981	
	13. NUMBER OF PAGES	
	15. SECURITY CLASS. (of this report) UNCLASSIFIED	
	15a. DECLASSIFICATION/DOWNGRADING SCHEDULE	

16. DISTRIBUTION STATEMENT (of this Report)

Approved for public release; Distribution unlimited.

17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)

DTIC
ELECT
JAN 21 1982

18. SUPPLEMENTARY NOTES

19. KEY WORDS (Continue on reverse side if necessary and identify by block number)
 Dam Safety
 National Dam Safety Program
 Visual Inspection
 Hydrology, Structural Stability
 Goshen Reservoir No. 1 Dam
 Orange County, NY
 Lower Hudson River Basin

20. ABSTRACT (Continue on reverse side if necessary and identify by block number)
 This report provides information and analysis on the physical condition of the dam as of the report date. Information and analysis are based on visual inspection of the dam by the performing organization.
 The examination of documents and the visual inspection of the Goshen Reservoir did not reveal conditions which constitute an immediate hazard to human life or property. However, the dam has some problem areas which require additional studies and remedial work.

393170

AD A109838

copy

The most serious of these deficiencies are the two areas of seepage on the downstream slope of the dam. First is at the end of the grouted stone spillway channel and the second is at the toe in the center of the dam. It is recommended that within six months from notification, an engineering investigation is initiated to determine the sources of the seepage found.

Using the Corps of Engineers' "screening criteria" for the initial review of spillway adequacy, it has been determined that the embankment would be overtopped for all storms in excess of 51% of the Probable Maximum Flood (PMF). Therefore, the spillway is adjudged as "inadequate".

LOWER HUDSON RIVER BASIN
GOSHEN RESERVOIR NO. 1 DAM
ORANGE COUNTY, NEW YORK
INVENTORY NO. N.Y. 488
PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM



**APPROVED FOR PUBLIC RELEASE;
DISTRIBUTION UNLIMITED**

NEW YORK DISTRICT CORPS OF ENGINEERS

AUGUST, 1981


PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I Investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.



PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
GOSHEN RESERVOIR NO.1 DAM
I.D. NO. NY 488
D.E.C. NO. 179B-3163
LOWER HUDSON RIVER BASIN
ORANGE COUNTY, N.Y.

TABLE OF CONTENTS

		<u>PAGE NO.</u>
-	ASSESSMENT	-
-	OVERVIEW PHOTOGRAPH	-
1	PROJECT INFORMATION	1
1.1	GENERAL	1
1.2	DESCRIPTION OF PROJECT	1
1.3	PERTINENT DATA	2
2	ENGINEERING DATA	3
2.1	DESIGN	3
2.2	CONSTRUCTION RECORDS	3
2.3	OPERATION RECORDS	3
2.4	EVALUATION OF DATA	3
3	VISUAL INSPECTION	4
3.1	FINDINGS	4
3.2	EVALUATION OF OBSERVATIONS	5
4	OPERATIONS AND MAINTENANCE PROCEDURES	6
4.1	PROCEDURES	6
4.2	MAINTENANCE OF DAM	6
4.3	WARNING SYSTEM	6
4.4	EVALUATION	6
5	HYDROLOGIC/HYDRAULIC	7

	<u>PAGE NO.</u>
5.1 DRAINAGE AREA CHARACTERISTICS	7
5.2 ANALYSIS CRITERIA	7
5.3 SPILLWAY CRITERIA	7
5.4 RESERVOIR CAPACITY	7
5.5 FLOODS OF RECORD	7
5.6 OVERTOPPING POTENTIAL	7
5.7 EVALUATION	7
6 STRUCTURAL STABILITY	8
6.1 EVALUATION OF STRUCTURAL STABILITY	8
7 ASSESSMENT/RECOMMENDATIONS	9
7.1 ASSESSMENT	9
7.2 RECOMMENDED MEASURES	9

APPENDICES

- A. PHOTOGRAPHS
- B. VISUAL INSPECTION CHECKLIST
- C. HYDROLOGIC/HYDRAULIC ENGINEERING
DATA AND COMPUTATIONS
- D. REFERENCES
- E. DRAWINGS

**PHASE 1 INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM**

Name of Dam:	Goshen Reservoir No. 1 Dam (I.D. No. NY 488)
State Located:	New York
County Located	Orange
Stream:	Rio Grande Creek
Date of Inspection:	November 20, 1980

ASSESSMENT

The examination of documents and the visual inspection of the Goshen Reservoir did not reveal conditions which constitute an immediate hazard to human life or property. However, the dam has some problem areas which require additional studies and remedial work.

The most serious of these deficiencies are the two areas of seepage on the downstream slope of the dam. First is at the end of the grouted stone spillway channel and the second is at the toe in the center of the dam. It is recommended that within six months from notification, an engineering investigation is initiated to determine the sources of the seepage found.

Using the Corps of Engineers' "screening criteria" for the initial review of spillway adequacy, it has been determined that the embankment would be overtopped for all storms in excess of 51% of the Probable Maximum Flood (PMF). Therefore, the spillway is adjudged as "inadequate".

In addition the dam has a number of problem areas, which if left uncorrected, have the potential for the development of hazardous conditions and must be corrected within 1 year. The following remedial work is required:

- a. Repair the spillway walls.
- b. Clean and recaulk the joints in the spillway.
- c. Provide a program of periodic inspection and maintenance of the dam and appurtenances, including operation and lubrication of all gates and valves. This information should be documented for future reference.
- d. An emergency action plan must be established.

George Koch

George Koch
Chief, Dam Safety Section
New York State Department
of Environmental Conservation
NY License No. 45937

Approved By:

W. H. Smith, Jr.

Col. W.H. Smith, Jr.
New York District Engineer

Date:

14 SEP 81



OVERVIEW OF GOSHEN RESERVOIR #1 DAM

PHOTO #1

PHASE 1 INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
GOSHEN RESERVOIR NO. 1 DAM I.D. NO. NY 488
DEC # 179 B - 3163 LOWER HUDSON RIVER BASIN
ORANGE COUNTY

SECTION 1: PROJECT INFORMATION

1.1 GENERAL

a. Authority

The Phase 1 inspection reported herein was authorized by the Department of the Army, New York District, Corps of Engineers, to fulfill the requirements of the National Dam Inspection Act, Public Law 92-367.

b. Purpose of Inspection

Evaluation of the existing conditions of the subject dam to identify deficiencies and hazardous conditions, determine if they constitute hazards to human life and property and recommend remedial measures where necessary.

1.2 DESCRIPTION OF PROJECT

a. Description of Dam and Appurtenances

The Goshen Reservoir No. 1 Dam consists of a 550 feet long earth embankment with a 25 feet concrete overflow spillway located at the left abutment. The original embankment was raised 4 feet in 1963 to its present height of 37 feet. The rip rap protected upstream slope is 3-on 1, while the downstream slope was backfilled to a 2 on 1 grade. The crest width is 12', but there has been fill placed on the downstream slope in the recent past, increasing the crest width to 20' in the area adjacent to the access road. The gate house is located on the upstream slope on the right side of the embankment. It houses two 20" intake valves to the Goshen water supply system. The spillway is a concrete channel with a concrete cutoff extending into the embankment. The outlet channel is grouted stone channel which follows the abutment contact and bends back into the original stream bed. There is no reservoir drain except for the intake lines to the filtration plant.

b. Location

The dam is located on the Rio Grande Creek, a tributary of the Wallkill River, Lower Hudson River Basin. It is in the Town of Goshen, Orange County, State of New York.

c. Size

The dam is approximately 37 feet high and impounds 704. acre feet at normal or spillway crest elevation. The dam is classified as "small" in size (25 to 40 feet in height).

d. Hazard Classification

The dam is classified as high hazard due to its location above several homes along Reservoir Road.

e. Ownership

The dam is owned by the Village of Goshen, New York. The owner's representative is Conrad Kroll, Superintendent of Public Works, Village of Goshen, 276 Main Street, Goshen, NY 10924, (914) 294-6750.

f. Purpose of the Dam

The dam augments the storage of the Village of Goshen water supply.

g. Design and Construction History

The original dam was constructed around 1875. In 1964 the embankment was raised 4 feet and a new spillway was constructed. The design of the reconstruction was by Chumark & McGough, Consulting Engineers, Middletown, New York.

h. Normal Operating Procedures

Releases from the Goshen Reservoir are normally passed into the treatment plant and into the water supply system. Excess runoff is passed over the spillway and into the original stream channel.

1.3 PERTINENT DATA

a. Drainage Area (sq. mi.) 0.59

b. Elevations (ft. USGS datum)

Top of Dam 546.0
Spillway Crest 543.0
Original Stream Channel 509.0

c. Reservoir (acre feet)

Storage at Top of Dam 867.0
Storage at Spillway Crest 704.0

d. Dam

Type: Homogeneous earth fill with a clay addition to the top of the embankment, upstream slope is rip rapped.

Length (ft): 550.0
Downstream Slope: 2:1
Upstream Slope: 3:1
Crest Width (ft): 12.
Height (ft): 37.

e. Spillway

Type: Concrete channel with concrete cutoff wall and grouted stone outlet channel.

Weir Length (ft): 25.0'
Maximum Capacity (cfs): 236.

5-8

SECTION 2: ENGINEERING DATA

2.1: DESIGN

a. Geology

The Goshen Reservoir No. 1 Dam is located in the "Hudson Valley Lowlands" physiographic province of New York State. These lowland areas have gentle relief and are underlain by Ordovician shales that have been exposed by the erosion of overlying Silurian and Devonian limestones. Drainage is generally northeast towards the Hudson River.

b. Subsurface Investigation

The Troy-Cossayuna is the dominant association of the glacial till of the Hudson Valley (Ref. 8). The only information or past investigation of the site that could be located are the boring logs included in the report. These are borings through the original dam embankment taken for the design of the raising embankment.

c. Dam and Appurtenant Structures

There is no data on the original structure except what can be interpreted from the reconstruction plans (App. E). The reconstruction was designed by Chumard and McGough, Consulting Engineers in 1963 and believed to be implemented the same year.

2.2 CONSTRUCTION RECORDS

Some correspondence regarding seepage and some settlement problems were located in the files located in the Dam Safety Section, Department of Environmental Conservation, 50 Wolf Road, Albany, NY 12233. Several of the reconstruction photos are included in this report (See App. A).

2.3 OPERATION RECORD

All information regarding operation and maintenance of the dam is on file with the Goshen Water Superintendent.

2.4 EVALUATION OF DATA

The data presented in this report is compiled from information made available by the representatives of the Village of Goshen and the files at Department of Environmental Conservation. This information appears to be adequate and reliable for Phase 1 Inspection purposes.

SECTION 3: VISUAL INSPECTION

3. 1: FINDINGS

a. General

Visual inspection of the Goshen Reservoir No. 1 dam and surrounding watershed was conducted on November 20, 1980 and April 30, 1981. The weather was clear and the temperature ranged in the thirties; there was approximately 2 inches of snow on the ground in November and clear of snow in April. The reservoir was approximately 4 feet below normal or spillway crest elevation.

b. Dam

The dam, which was raised in 1963 is approximately 37 feet high. It is composed of an earth embankment with a concrete spillway. The upstream rip rap was well placed and in good condition, and the embankment as a whole appeared stable. However, there were several points of seepage on the downstream slope, emanating from under the grouted spillway channel and a wet area at the toe, in the center of the dam. This seepage was also found during and after construction in 1964 (See photos, App. A), and suspected to be flowing in the area of the original spillway. The seepage did not show signs of material transport. The Department of Public Works has been placing fill material on the downstream slope adjacent to the access road. This has widened the crest by 10 feet in this area of the dam.

c. Spillway

As evidenced in the construction photos settlement of the embankment was large. This movement is apparent in the spillway. Both walls are cracked and the right wall has moved inward. The construction joints are showing signs of deterioration, much of the compound is missing. The grouted stone channel is in good condition, however, there was a small amount of seepage emanating from under the channel.

d. Appurtenant Structures

The gate house was raised in 1963 with the embankment and appears to be sound. All gates are operated continually and in good working condition.

e. Abutments

There is no sign of seepage or other unusual conditions at the abutments, however, the right abutment is concealed by the backfilling on the downstream slope of the dam.

f. Downstream Channel

The channel downstream of the spillway is natural, stream bed upon leaving the grouted stone spillway channel. Although the channel contains natural vegetation, including large trees and brush, its present condition would not significantly impede discharges from the spillway.

g. Reservoir Area

In the vicinity of the dam there is no evidence of sloughing, potentially unstable slopes or other unusual conditions which may adversely affect the dam. No evidence of excessive sedimentation was observed.

3.2 EVALUATION OF OBSERVATIONS

Visual observations made during the course of the investigation reveal several deficiencies which should be corrected before further deterioration leads to a hazardous condition. They are;

- a. Determine the source of the seepage found at the toe and the center of the dam and at the end of the grouted spillway channel. Monitor the seepage at bi-weekly intervals with the aid of weirs.
- b. Repair the spillway walls.
- c. Clean and recaulk joints in the spillway.
- d. Provide a program of periodic inspection and maintenance of the dam and appurtenances, including operation and lubrication of all gates and valves. This information should be documented for future reference.
- e. An emergency action plan must be established.

SECTION 4: OPERATIONS AND MAINTENANCE PROCEDURES

4.1 PROCEDURES

The normal water surface is at the spillway crest. The reservoir is kept at or below this elevation by discharge through the two 20" lines into the Goshen Water Supply. Flows in excess of this requirement are passed over the ungated spillway.

4.2 MAINTENANCE OF THE DAM

Maintenance of the dam is provided by the owner, the Village of Goshen, NY. Maintenance of the dam is considered unsatisfactory, as evidenced by the cracking of concrete elements, deteriorated concrete joints, and unmonitored seepage.

4.3 WARNING SYSTEM

There is no warning system in effect or in preparation.

4.4 EVALUATION

The dam has not been maintained in satisfactory condition as noted in "Section 3: Visual Inspection".

SECTION 5: HYDROLOGIC/HYDRAULIC

5.1 DRAINAGE AREA CHARACTERISTICS

The total drainage area tributary to this dam is 0.59 square miles with generally moderate slopes. The area is fairly well drained and was treated as a single basin for analysis purposes.

5.2 ANALYSIS CRITERIA

The analysis of the spillway capacity of the dam and storage of the reservoir was performed using the Corps of Engineers HEC-1 computer program incorporating the "Snyder Synthetic Unit Hydrograph" method and the "Modified Puls" flood routing procedure. The floods selected for analysis were the PMF and 1/2 PMF in accordance with the recommended guidelines of the Corps of Engineers.

5.3 SPILLWAY CAPACITY

The spillway has a capacity of 343 cfs with the reservoir level at the top of the dam. For the 1/2 PMF the peak inflow will be 895 cfs and the peak outflow will be 338 cfs. For the PMF the peak inflow will be 1789 cfs and the peak outflow will be 1466 cfs. During this event, the dam will be overtopped by 0.89 foot of water.

5.4 RESERVOIR CAPACITY

Capacity to normal water elevation is 704 acre-feet. Surcharge storage to top of dam is an additional 163 acre-feet, creating a total storage of 867 acre-feet. The surcharge storage between spillway and dam crest is equivalent to 5.18 inches of runoff.

5.5 FLOODS OF RECORD

No records of past floods for Rio Grande Creek are available.

5.6 OVERTOPPING POTENTIAL

Our analysis indicates the dam will be overtopped by 0.89 foot during the PMF which could cause damages to several homes located downstream. It would, however, be able to handle 1/2 the PMF but with practically no freeboard (about 0.03 feet).

5.7 EVALUATION

The spillway is inadequate to pass all floods exceeding 51% of the PMF and is, therefore, adjudged as "inadequate".

SECTION 6: STRUCTURAL STABILITY

6.1 EVALUATION OF STRUCTURAL STABILITY

a. Visual Observations

The most serious signs of distress in connection with the earth embankment are the seepage areas previously noted. There are a number of other problem areas, discussed in "Section 3: Visual Inspection", which if left uncorrected, have the potential for the development of hazardous conditions.

b. Design and Construction Data

Some information on the problems resulting from the 1963 reconstruction is available in the NYS Department of Environmental Conservation files. No data was available on the original structure, but plans and photos of the reconstruction are included in this report.

c. Post Construction Changes

The original dam was constructed about 1875 and raised in 1963 to its present configuration. The last raising was designed by Chumard and McGough, Consulting Engineers, Middleton, NY.

SECTION 7: ASSESSMENT/RECOMMENDATIONS

7.1 ASSESSMENT

a. Safety

The Phase 1 Inspection of Goshen Reservoir No. 1 Dam revealed that the spillway as "inadequate" based on the Corps of Engineer's "screening criteria". The dam will be overtopped by all storms in excess of 51% of the PMF. Also several areas of seepage were found at the spillway channel outlet and at the toe of the dam. These areas must be investigated to determine the source of this seepage and what remedial action must be initiated.

b. Adequacy of Information

The information reviewed is considered adequate for Phase 1 Inspection purposes.

c. Need for Additional Investigations

There is need for a further engineering investigation into the seepage found at the toe of the embankment and at the end of the spillway channel. After these investigations have been completed, appropriate remedial measures must be initiated.

d. Urgency

The engineering investigations must be initiated within six months from the date of notification, and remedial measures as a result of these investigations completed within 18 months from the date of notification. In the interim monitor the seepage area on a regular basis, develop an emergency action plan for notification of downstream residents and the proper governmental authorities, and provide around-the-clock surveillance of the dam during periods of unusually heavy runoff. The other repairs and maintenance noted in Section 3.2 must be complete within one year from the date of notification.

7.2 RECOMMENDED MEASURES

- a. Initiate an engineering study to determine the source of the seepage found on the dam and determine a method of treatment. Monitor this seepage at biweekly intervals with the aid of weirs.
- b. Repair the spillway walls.
- c. Clean and recaulk the joints in the spillway.
- d. Provide a program of periodic inspection and maintenance of the dam and appurtenances, including operation and lubrication of all gates and valves. This information should be documented for future reference.
- e. An emergency action plan must be established.

In addition, the dam has a number of problem areas, which if left uncorrected, have the potential for the development of hazardous conditions and must be corrected within one year. These areas are:

1. Monitor seepage in the spillway and outlet conduit. If significant increases are observed, investigate and repair.
2. Monitor the calcification of the outlet conduit construction joints and repair as required.
3. Repoint all joints of the masonry construction. Recaulk all construction joints where necessary.
4. Repair the deteriorated stoplog brackets.
5. Remove the debris in the spillway area, outlet conduit and downstream channel.
6. Remove the tree and brush growth on the embankment and in the downstream channel. Provide a program of periodic cutting and mowing.
7. Provide a program of periodic inspection and maintenance of the dam and appurtenances, including yearly operation and lubrication of the reservoir drain system. Document this information for future reference. Also develop an emergency action plan.

APPENDIX A

PHOTOGRAPHS



PHOTO # 2: DOWNSTREAM SLOPE AT EMBANKMENT



PHOTO #3: SPILLWAY LOCATED AT LEFT ABUTMENT

NOTE CRACK IN WALL




PHOTO #4: LEFT SPILLWAY WALL
NOTE CRACK ABOVE FISH SCREEN



PHOTO #5: BACKFILLED AREA ON DOWNSTREAM SLOPE
RESULTING IN WIDENED CREST



PHOTO #6: SPILLWAY CHANNEL
BELOW COBBLE PAVED CHANNEL





PHOTO #7: SEEPAGE AT END OF SPILLWAY CHANNEL



PHOTO # 8: GATE HOUSE LOCATED AT RIGHT ABUTMENT



PHTOT # 9: RESERVOIR FROM CREST OF DAM



PHOTO # 10: SETTLEMENT DURING RECONSTRUCTION OF DAM IN 1963



PHOTO # 11: SEEPAGE AT END OF SPILLWAY CHANNEL

1963



PHOTO # 12: SEEPAGE AT TOE IN SAME GENERAL
AREA AS WAS FOUND DURING PHASE I INSPECTION
PHOTO TAKEN IN 1963

APPENDIX B

VISUAL INSPECTION CHECKLIST

VISUAL INSPECTION CHECKLIST1) Basic Data

a. General

Name of Dam GOSHEN RESERVOIR
 Fed. I.D. # NY 488 DEC Dam No. 179 B - 3163
 River Basin LOWER HUDSON
 Location: Town GOSHEN County ORANGE
 Stream Name RIO GRANDE CREEK
 Tributary of WALKILL RIVER
 Latitude (N) 41° 23.0' Longitude (W) 74° 20.0'
 Type of Dam EARTH FILL
 Hazard Category 'C' high
 Date(s) of Inspection NOVEMBER 20, 1980 / APRIL 30, 1981
 Weather Conditions SNOWY 30's / clear 30's
 Reservoir Level at Time of Inspection 4 feet below spillcrest

b. Inspection Personnel KEN HARMER, JAMIE VEITCH

c. Persons Contacted (Including Address & Phone No.) _____

MR. CONRAD KROLL, SUPERINTENDENT

276 MAIN STR.

GOSHEN NY 10929

(914) 294-6750

d. History:

Date Constructed 1875 Date(s) Reconstructed 1964

Designer Chumark & McGough, Middletown NY

Constructed By —

Owner Village of GOSHEN

93-15-3(9/80)

2) Embankment

a. Characteristics

- (1) Embankment Material EARTH/CLAY FILL
- (2) Cutoff Type NONE
- (3) Impervious Core CLAYFILL
- (4) Internal Drainage System None
- (5) Miscellaneous tackfilled on downstream slope.

b. Crest

- (1) Vertical Alignment good
- (2) Horizontal Alignment good
- (3) Surface Cracks None
- (4) Miscellaneous -

c. Upstream Slope

- (1) Slope (Estimate) (V:H) 1:3
- (2) Undesirable Growth or Debris, Animal Burrows None
- (3) Sloughing, Subsidence or Depressions None

(4) Slope Protection rip rap - well placed good condition

(5) Surface Cracks or Movement at Toe None apparent

d. Downstream Slope

(1) Slope (Estimate - V:H) ORIGINAL 1:2, presently backfill to slightly steep slope

(2) Undesirable Growth or Debris, Animal Burrows brush & tree growth

(3) Sloughing, Subsidence or Depressions —

(4) Surface Cracks or Movement at Toe —

(5) Seepage Several points of seepage at toe and from under spillway channel

(6) External Drainage System (Ditches, Trenches; Blanket) none

(7) Condition Around Outlet Structure None

(8) Seepage Beyond Toe None

e. Abutments - Embankment Contact

good

93-15-3(9/80)

(1) Erosion at Contact None

(2) Seepage Along Contact None

3) Drainage System

a. Description of System gravel/tile under drain under the spillway channel

b. Condition of System _____

c. Discharge from Drainage System SMALL AMOUNT \approx 0.5 gal/min

4) Instrumentation (Momentum/Surveys, Observation Wells, Weirs, Piezometers, Etc.) _____

93-15-3(9/80)

5) Reservoir

- a. Slopes stable, shallow
- b. Sedimentation SOME, No PROBLEM
- c. Unusual Conditions Which Affect Dam NONE

6) Area Downstream of Dam

- a. Downstream Hazard (No. of Homes, Highways, etc.) SEVERAL HOMES. just downstream (1/4 mi) on Reservoir Rd.
- b. Seepage, Unusual Growth WET AREAS CAUSED BY SEEPAGE
- c. Evidence of Movement Beyond Toe of Dam NONE
- d. Condition of Downstream Channel heavily treed

7) Spillway(s) (Including Discharge Conveyance Channel)

- a. General in need of maintenance
- b. Condition of Service Spillway movement apparent, cracking joints deteriorated.

c. Condition of Auxiliary Spillway N/A

d. Condition of Discharge Conveyance Channel grouted channel
in good condition

8) Reservoir Drain/Outlet N/A

Type: Pipe _____ Conduit _____ Other _____

Material: Concrete _____ Metal _____ Other _____

Size: _____ Length _____

Invert Elevations: Entrance _____ Exit _____

Physical Condition (Describe): _____ Unobservable _____

Material: _____

Joints: _____ Alignment _____

Structural Integrity: _____

Hydraulic Capability: _____

Means of Control: Gate _____ Valve _____ Uncontrolled _____

Operation: Operable _____ Inoperable _____ Other _____

Present Condition (Describe): _____

9) Structural

a. Concrete Surfaces gate house / INTAKE STRUCTURE -
good

b. Structural Cracking spillway

c. Movement - Horizontal & Vertical Alignment (Settlement) spillway

d. Junctions with Abutments or Embankments ---

e. Drains - Foundation, Joint, Face ---

f. Water Passages, Conduits, Sluices None

g. Seepage or Leakage at toe & from spillway underdrain

h. Joints - Construction, etc. spillary - deteriorated

i. Foundation no apparent problem

j. Abutments good

k. Control Gates operational (to water supply only)

l. Approach & Outlet Channels good

m. Energy Dissipators (Plunge Pool, etc.) None

n. Intake Structures good

o. Stability good

p. Miscellaneous _____

10) Appurtenant Structures (Power House, Lock, Gatehouse, Other)

a. Description and Condition gate house intake good
condition

11) Operation Procedures (Lake Level Regulation):

water supply fluctuations.

APPENDIX C

HYDROLOGIC / HYDRAULIC

ENGINEERING DATA AND COMPUTATIONS

GOSHEN RESERVOIR


Spillway Capacity

Top of Dam - 546.0 Streambed = 507.
 Spillway Crest. 543.0
 $L_{weir} = 25'$ 1.5' fish screen assume full
 $C = 2.64$ (KING & BRATER; 5.3)

EL.	H.	C	Q
543.3	0	2.64	0
543.5	.5	↓	23.
544.0	1.0		66.
544.5	1.5		121.
545.0	2.0		187.
545.5	2.5		261.
546.0	3.0	2.64	343.


RESERVOIR CAPACITY

Volume 215×10^6 gal @ 543.0 = 661.4 AC FT. (USE FIGURE FROM DEVELOPED CURVE)
 AREA 500 = 108 AC IN $\frac{543.0 - 500}{543.0 - 500} = 99$ ACRES 704 AC FT.
 543 = 52 ACRES Vol = $\left(\frac{99+52}{2}\right) 17 = 1233.65$ AC FT.



46 0782

K-E 10 X 10 TO THE INCH = 7 X 10 INCHES
KEUFFEL & ESSER CO. MADE IN U.S.A.



GASHEN

cont.

PRECIPITATION

$$\Sigma(PMP) = 21.5'' \quad \begin{array}{cccc} \text{DUE} \rightarrow & 6 & 12 & 24 & 48 \\ \% \rightarrow & 111 & 123 & 133 & 142 \end{array}$$

$$L = 3200'$$

$$L_{ca} = 750'$$

$$DA = 0.59 \text{ mi.}^2$$

$$\text{POOL AREA} = .08 \text{ mi.}^2$$

$$t_p = 0.95 \text{ hr.} \quad T_p = .95 + .25(.17 - .17) = .95 \text{ hr.} \quad \text{USE } T_p = .90 \text{ hr}$$
$$t_r = 10 \text{ MIN} \quad \quad \quad t_r = 10 \text{ MIN}$$

$$\text{TRANSPOSITION FACTOR} = 1 - \frac{0.3008}{(.59)^{0.17718}} = 0.67$$

USE SINGLE BASIN ANALYSIS w/ shortened T_p MORE
CONSERVATIVE RUNOFF COMBINED RUNOFF AND DIRECT INFLOW

CHECK LIST FOR DAMS
HYDROLOGIC AND HYDRAULIC
ENGINEERING DATA

1

AREA-CAPACITY DATA:

	<u>Elevation</u> (ft.)	<u>Surface Area</u> (acres)	<u>Storage Capacity</u> (acre-ft.)
1) Top of Dam	<u>546.0</u>	_____	<u>867.0</u>
2) Design High Water (Max. Design Pool)	<u>NA</u>	_____	_____
3) Auxiliary Spillway Crest	<u>NA</u>	_____	_____
4) Pool Level with Flashboards	<u>NA</u>	_____	_____
5) Service Spillway Crest	<u>543.0</u>	_____	<u>704.0</u>

DISCHARGES

	<u>Volume</u> (cfs)
1) Average Daily	<u>1.2</u>
2) Spillway @ Maximum High Water	_____
3) Spillway @ Design High Water	<u>NA</u>
4) Spillway @ Auxiliary Spillway Crest Elevation	<u>NA</u>
5) Low Level Outlet	<u>NA</u>
6) Total (of all facilities) @ Maximum High Water	_____
7) Maximum Known Flood	_____
8) At Time of Inspection	_____

CREST:

ELEVATION: 546.0

Type: Compacted earth

Width: 12' Length: 550'

Spillover _____

Location _____

SPILLWAY:

SERVICE

AUXILIARY

543.0 Elevation _____

Concrete channel Type _____

25' Width _____

Type of Control

✓

Uncontrolled _____

Controlled:

Type

(Flashboards; gate) _____

Number _____

Size/Length _____

Invert Material _____

Anticipated Length
of operating service _____

Chute Length _____

Height Between Spillway Crest
& Approach Channel Invert
(Weir Flow) _____

HYDROMETEROLOGICAL GAGES:

Type : None

Location: _____

Records:

Date - _____

Max. Reading - _____

FLOOD WATER CONTROL SYSTEM:

Warning System: None

Method of Controlled Releases (mechanisms):

None except for two 20" intake lines into
the filtration plant.

DRAINAGE AREA: 0.59 mi²

DRAINAGE BASIN RUNOFF CHARACTERISTICS:

Land Use - Type: _____

Terrain - Relief: _____

Surface - Soil: _____

Runoff Potential (existing or planned extensive alterations to existing (surface or subsurface conditions)

No alterations planned or anticipated

Potential Sedimentation problem areas (natural or man-made; present or future)

Potential Backwater problem areas for levels at maximum storage capacity including surcharge storage:

Dikes - Floodwalls (overflow & non-overflow) - Low reaches along the Reservoir perimeter:

Location: _____

Elevation: _____

Reservoir:

Length @ Maximum Pool _____ (Miles)

Length of Shoreline (@ Spillway Crest) _____ (Miles)

PREVIEW OF SEQUENCE OF STREAM NETWORK CALCULATIONS
OFFICE HYDROGRAPH AT
ACUTE HYDROGRAPH TO
EPI OF V. 190

.....
 NEW YORK STATE
 DEPT OF ENVIRONMENTAL CONSERVATION
 FLOOD PROTECTION BUREAU

.....
 1.000 HYDROGRAPH PACKAGE (HC-C-1)
 LAST MODIFICATION - JULY 1978
 LAST MODIFICATION 26 FEB 79
 MODIFIED FOR KENEWELL APR 79

.....
 RUN DATE 05/01/81
 GUSHEN RESERVOIR
 PHASE I
 PHF

JOB SPECIFICATION											
NO	NHR	RMTA	JDAY	IR	IRHR	W T C	IPL	IPRT	INSTAN		
200	0	10	0	0	0	0	0	0	0		
JUPER	VAT	LRPT	TRACE								
5	0	0	0								

MULTI-PLAN ANALYSES TO BE PERFORMED

WTDISE 0.20 0.40 0.50 0.60 0.80 1.00
 NPLAN=1 RATIO=5.0 RATIO=1

.....
 SUR-AREA RUNOFF COMPUTATION

INFLOW FROM BASIN											
ISTAD	ICOMP	ICOV	ITAPE	JPLT	JPRT	IVAME	ISTAGE	IAUTO			
1	0	0	0	2	0	1	0	0			

HYDROGRAPH DATA

IHYG	IUNG	TAKEA	SNAP	TRDA	TRSPC	RATIO	ISUM	ISAME	LOCAL
1	1	0.55	0.	0.39	0.67	0.	0	0	0

PRECIP DATA

SPEE	PPS	R	R2	R24	K93	RZ2	RZ6
0.	21.50	111.00	123.90	131.00	142.00	0.	0.

LOSS DATA

LRPT	STKR	OLTKP	RTIOL	FRAFI	STKRS	RT OS	SIRL	CISIL	ALSMY	RTIAP
0	0.	0.	1.00	0.	0.	1.00	1.00	0.10	0.	0.

UNIT HYDROGRAPH DATA
 TPE=0.00 CP=0.53 RTA=0

PRECSSION DATA

SIRIOE -2.00
 SRESNE -0.0
 RTIORE 1.00

.....
 UNIT HYDROGRAPH CALCULATED FROM GIVEN CENTER CP AND TP ARE ICE 6.31 AND RE 1.30 INTERVALS

1.	2.	3.	4.	5.	6.	7.	8.	9.	10.	11.	12.	13.
100.	80.	72.	59.	48.	39.	32.	27.	23.	20.	18.	16.	15.
14.	13.	9.	6.	5.	5.	4.	3.	3.	3.	3.	3.	2.

1.01	11.00	66	0.00	0.	1.00	0.	0.	0.	0.	0.	0.	210	0.05	0.03	0.02	72.
1.01	11.10	67	0.00	0.	0.00	0.	0.	0.	0.	0.	0.	211	0.05	0.03	0.02	72.
1.01	11.20	68	0.00	0.	0.00	0.	0.	0.	0.	0.	0.	212	0.05	0.03	0.02	72.
1.01	11.30	69	0.00	0.	0.00.	0.	0.	0.	0.	0.	0.	213	0.05	0.03	0.02	72.
1.01	11.40	70	0.00	0.	1.00	0.	0.	0.	0.	0.	0.	214	0.05	0.03	0.02	72.
1.01	11.50	71	0.00	0.	0.00	0.	0.	0.	0.	0.	0.	215	0.05	0.03	0.02	72.
1.01	12.00	72	0.00	0.	0.00	0.	0.	0.	0.	0.	0.	216	0.05	0.03	0.02	72.
1.01	12.10	73	0.02	0.	0.02	0.	0.	0.	0.	0.	0.	217	0.27	0.25	0.02	77.
1.01	12.20	74	0.02	0.	0.02	0.	0.	0.	0.	0.	0.	218	0.27	0.25	0.02	92.
1.01	12.30	75	0.02	0.	0.02	0.	0.	0.	0.	0.	0.	219	0.27	0.25	0.02	121.
1.01	12.40	76	0.02	0.	0.02	0.	0.	0.	0.	0.	0.	220	0.27	0.25	0.02	165.
1.01	12.50	77	0.02	0.	0.02	0.	0.	0.	0.	0.	0.	221	0.27	0.25	0.02	226.
1.01	13.00	78	0.02	0.	0.02	0.	0.	0.	0.	0.	0.	222	0.27	0.25	0.02	278.
1.01	13.10	79	0.02	0.	0.02	0.	0.	0.	0.	0.	0.	223	0.32	0.30	0.02	333.
1.01	13.20	80	0.02	0.	0.02	0.	0.	0.	0.	0.	0.	224	0.32	0.30	0.02	381.
1.01	13.30	81	0.02	0.	0.02	0.	0.	0.	0.	0.	0.	225	0.32	0.30	0.02	424.
1.01	13.40	82	0.02	0.	0.02	0.	0.	0.	0.	0.	0.	226	0.32	0.30	0.02	464.
1.01	13.50	83	0.02	0.	0.02	0.	0.	0.	0.	0.	0.	227	0.32	0.30	0.02	502.
1.01	14.00	84	0.02	0.	0.02	0.	0.	0.	0.	0.	0.	228	0.32	0.30	0.02	536.
1.01	14.10	85	0.03	0.	0.03	0.	0.	0.	0.	0.	0.	229	0.40	0.38	0.02	566.
1.01	14.20	86	0.03	0.	0.03	0.	0.	0.	0.	0.	0.	230	0.40	0.38	0.02	595.
1.01	14.30	87	0.03	0.	0.03	0.	0.	0.	0.	0.	0.	231	0.40	0.38	0.02	626.
1.01	14.40	88	0.03	0.	0.03	0.	0.	0.	0.	0.	0.	232	0.40	0.38	0.02	658.
1.01	14.50	89	0.03	0.	0.03	0.	0.	0.	0.	0.	0.	233	0.40	0.38	0.02	690.
1.01	15.00	90	0.03	0.	0.03	0.	0.	0.	0.	0.	0.	234	0.40	0.38	0.02	722.
1.01	15.10	91	0.02	0.	0.02	0.	0.	0.	0.	0.	0.	235	0.36	0.35	0.02	750.
1.01	15.20	92	0.04	0.	0.04	0.	0.	0.	0.	0.	0.	236	0.61	0.59	0.02	775.
1.01	15.30	93	0.07	0.	0.07	0.	0.	0.	0.	0.	0.	237	1.09	1.08	0.02	803.
1.01	15.40	94	0.19	0.	0.19	0.	0.	0.	0.	0.	0.	238	2.73	2.72	0.02	821.
1.01	15.50	95	0.05	0.	0.05	0.	0.	0.	0.	0.	0.	239	0.73	0.77	0.02	1116.
1.01	16.00	96	0.03	0.	0.03	0.	0.	0.	0.	0.	0.	240	0.49	0.47	0.02	1358.
1.01	16.10	97	0.03	0.	0.03	0.	0.	0.	0.	0.	0.	241	0.37	0.36	0.02	1624.
1.01	16.20	98	0.03	0.	0.02	0.	0.	0.	0.	0.	0.	242	0.37	0.35	0.02	1781.
1.01	16.30	99	0.03	0.01	0.02	0.	0.	0.	0.	0.	0.	243	0.37	0.35	0.02	1894.
1.01	16.40	100	0.03	0.01	0.02	0.	0.	0.	0.	0.	0.	244	0.37	0.35	0.02	1713.
1.01	16.50	101	0.03	0.01	0.02	0.	0.	0.	0.	0.	0.	245	0.37	0.35	0.02	1973.
1.01	17.00	102	0.03	0.01	0.02	0.	0.	0.	0.	0.	0.	246	0.37	0.35	0.02	1437.
1.01	17.10	103	0.02	0.00	0.02	0.	0.	0.	0.	0.	0.	247	0.29	0.28	0.02	1320.
1.01	17.20	104	0.02	0.00	0.02	0.	0.	0.	0.	0.	0.	248	0.29	0.28	0.02	1231.
1.01	17.30	105	0.02	0.00	0.02	0.	0.	0.	0.	0.	0.	249	0.29	0.28	0.02	1133.
1.01	17.40	106	0.02	0.00	0.02	0.	0.	0.	0.	0.	0.	250	0.29	0.28	0.02	1054.
1.01	17.50	107	0.02	0.00	0.02	0.	0.	0.	0.	0.	0.	251	0.29	0.28	0.02	983.
1.01	18.00	108	0.02	0.00	0.02	0.	0.	0.	0.	0.	0.	252	0.29	0.28	0.02	920.
1.01	18.10	109	0.00	0.	0.00	0.	0.	0.	0.	0.	0.	253	0.02	0.01	0.02	861.
1.01	18.20	110	0.00	0.	0.00	0.	0.	0.	0.	0.	0.	254	0.02	0.01	0.02	799.
1.01	18.30	111	0.00	0.	0.00	0.	0.	0.	0.	0.	0.	255	0.02	0.01	0.02	727.
1.01	18.40	112	0.00	0.	0.00	0.	0.	0.	0.	0.	0.	256	0.02	0.01	0.02	643.
1.01	18.50	113	0.00	0.	0.00	0.	0.	0.	0.	0.	0.	257	0.02	0.01	0.02	552.
1.01	18.60	114	0.00	0.	0.00	0.	0.	0.	0.	0.	0.	258	0.02	0.01	0.02	461.
1.01	18.70	115	0.00	0.	0.00	0.	0.	0.	0.	0.	0.	259	0.02	0.01	0.02	373.
1.01	18.80	116	0.00	0.	0.00	0.	0.	0.	0.	0.	0.	260	0.02	0.01	0.02	312.
1.01	18.90	117	0.00	0.	0.00	0.	0.	0.	0.	0.	0.	261	0.02	0.01	0.02	256.
1.01	19.00	118	0.00	0.	0.00	0.	0.	0.	0.	0.	0.	262	0.02	0.01	0.02	212.
1.01	19.10	119	0.00	0.	0.00	0.	0.	0.	0.	0.	0.	263	0.02	0.01	0.02	179.
1.01	19.20	120	0.00	0.	0.00	0.	0.	0.	0.	0.	0.	264	0.02	0.01	0.02	149.
1.01	19.30	121	0.00	0.	0.00	0.	0.	0.	0.	0.	0.	265	0.02	0.01	0.02	119.
1.01	19.40	122	0.00	0.	0.00	0.	0.	0.	0.	0.	0.	266	0.02	0.01	0.02	179.
1.01	19.50	123	0.00	0.	0.00	0.	0.	0.	0.	0.	0.	267	0.02	0.01	0.02	179.
1.01	20.00	124	0.00	0.	0.00	0.	0.	0.	0.	0.	0.	268	0.02	0.01	0.02	179.
1.01	21.00	125	0.00	0.	0.00	0.	0.	0.	0.	0.	0.	269	0.02	0.01	0.02	179.
1.01	21.10	126	0.00	0.	0.00	0.	0.	0.	0.	0.	0.	270	0.02	0.01	0.02	179.
1.01	21.20	127	0.00	0.	0.00	0.	0.	0.	0.	0.	0.	271	0.02	0.01	0.02	179.
1.01	21.30	128	0.00	0.	0.00	0.	0.	0.	0.	0.	0.	272	0.02	0.01	0.02	179.

1.01	21.80	130	0.00	0.00	1.00	0.00	0.00	274	0.02	0.01	0.02	179.
1.01	21.90	131	0.00	0.00	1.00	0.00	0.00	275	0.02	0.01	0.02	179.
1.01	22.00	132	0.00	0.00	1.00	0.00	0.00	276	0.02	0.01	0.02	179.
1.01	22.10	133	0.00	0.00	1.00	0.00	0.00	277	0.02	0.01	0.02	179.
1.01	22.20	134	0.00	0.00	1.00	0.00	0.00	278	0.02	0.01	0.02	179.
1.01	22.30	135	0.00	0.00	1.00	0.00	0.00	279	0.02	0.01	0.02	179.
1.01	22.40	136	0.00	0.00	1.00	0.00	0.00	280	0.02	0.01	0.02	179.
1.01	22.50	137	0.00	0.00	1.00	0.00	0.00	281	0.02	0.01	0.02	179.
1.01	22.60	138	0.00	0.00	1.00	0.00	0.00	282	0.02	0.01	0.02	179.
1.01	22.70	139	0.00	0.00	1.00	0.00	0.00	283	0.02	0.01	0.02	179.
1.01	22.80	140	0.00	0.00	1.00	0.00	0.00	284	0.02	0.01	0.02	179.
1.01	22.90	141	0.00	0.00	1.00	0.00	0.00	285	0.02	0.01	0.02	179.
1.01	23.00	142	0.00	0.00	1.00	0.00	0.00	286	0.02	0.01	0.02	179.
1.01	23.10	143	0.00	0.00	1.00	0.00	0.00	287	0.02	0.01	0.02	179.
1.01	23.20	144	0.00	0.00	1.00	0.00	0.00	288	0.02	0.01	0.02	179.
1.01	0.											

SUM 21.46 15.84 3.51 41911.
 (20.3) (28.1) (92.3) (1180.79)

FEAK	5-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
1789.	419.	289.	147.	41953.
51.	25.	8.	4.	1185.
	14.36	18.01	18.33	18.33
	564.62	462.21	465.59	465.59
	451.	577.	576.	576.
	567.	705.	711.	711.

CFS
 INCHES
 M
 AC-FT
 THOUS CU M

9.00 5/1
9.10 5/1
9.20 5/1
9.30 5/1

9.40 5/1
9.50 5/1
10.00 5/1
10.10 5/1
10.20 5/1
10.30 5/1
10.40 5/1
10.50 5/1
11.00 5/1
11.10 5/1
11.20 5/1
11.30 5/1
11.40 5/1
11.50 5/1
12.00 5/1
12.10 5/1
12.20 5/1
12.30 5/1
12.40 5/1
12.50 5/1
13.00 5/1
13.10 5/1
13.20 5/1
13.30 5/1
13.40 5/1
13.50 5/1
14.00 5/1
14.10 5/1
14.20 5/1
14.30 5/1
14.40 5/1
14.50 5/1
15.00 5/1
15.10 5/1
15.20 5/1
15.30 5/1
15.40 5/1
15.50 5/1
16.00 5/1
16.10 5/1
16.20 5/1
16.30 5/1
16.40 5/1
16.50 5/1
17.00 5/1
17.10 5/1
17.20 5/1
17.30 5/1
17.40 5/1
17.50 5/1
18.00 5/1
18.10 5/1
18.20 5/1
18.30 5/1
18.40 5/1
18.50 5/1
19.00 5/1
19.10 5/1
19.20 5/1
19.30 5/1
19.40 5/1
19.50 5/1

LX
LLX
LX

19.2011301
19.2011301
19.2011301
19.2011301

19.2011301
19.2011301
19.2011301
19.2011301

19.2011301
19.2011301
19.2011301
19.2011301

19.2011301
19.2011301
19.2011301
19.2011301

19.2011301
19.2011301
19.2011301
19.2011301

19.2011301
19.2011301
19.2011301
19.2011301

19.2011301
19.2011301
19.2011301
19.2011301

19.2011301
19.2011301
19.2011301
19.2011301

19.2011301
19.2011301
19.2011301
19.2011301

19.2011301
19.2011301
19.2011301
19.2011301

19.2011301
19.2011301
19.2011301
19.2011301

19.2011301
19.2011301
19.2011301
19.2011301

19.2011301
19.2011301
19.2011301
19.2011301

19.2011301
19.2011301
19.2011301
19.2011301

LXVX
LXX
LXX
LXX

0. 285.
0. 287.
0. 288.
0. 289.

LXX
LXX
LXX

0. 290.
0. 291.
0. 292.
0. 293.
0. 294.
0. 295.
0. 296.
0. 297.
0. 298.
0. 299.

LXX
LXX
LXX

0. 300.
0. 301.
0. 302.
0. 303.
0. 304.
0. 305.
0. 306.
0. 307.
0. 308.
0. 309.

LXX
LXX
LXX

0. 310.
0. 311.
0. 312.
0. 313.
0. 314.
0. 315.
0. 316.
0. 317.
0. 318.
0. 319.

LXX
LXX
LXX

0. 320.
0. 321.
0. 322.
0. 323.
0. 324.
0. 325.
0. 326.
0. 327.
0. 328.
0. 329.

LXX
LXX
LXX

0. 330.
0. 331.
0. 332.
0. 333.
0. 334.
0. 335.
0. 336.
0. 337.
0. 338.
0. 339.

LXX
LXX
LXX

0. 340.
0. 341.
0. 342.
0. 343.
0. 344.
0. 345.
0. 346.
0. 347.
0. 348.
0. 349.

LXX
LXX
LXX

0. 350.
0. 351.
0. 352.
0. 353.
0. 354.
0. 355.
0. 356.
0. 357.
0. 358.
0. 359.

LXX
LXX
LXX

0. 360.
0. 361.
0. 362.
0. 363.
0. 364.
0. 365.
0. 366.
0. 367.
0. 368.
0. 369.

STATION 1, P. 1, RATIO 5
 END-OF-PERIOD HYDROGRAPH ORDINATES

TIME	INLET	OUTLET	RESERVOIR	STORAGE
0.	0.	0.	0.	0.
1.	0.	0.	0.	0.
2.	0.	0.	0.	0.
3.	0.	0.	0.	0.
4.	0.	0.	0.	0.
5.	0.	0.	0.	0.
6.	0.	0.	0.	0.
7.	0.	0.	0.	0.
8.	0.	0.	0.	0.
9.	0.	0.	0.	0.
10.	0.	0.	0.	0.
11.	0.	0.	0.	0.
12.	0.	0.	0.	0.
13.	0.	0.	0.	0.
14.	0.	0.	0.	0.
15.	0.	0.	0.	0.
16.	0.	0.	0.	0.
17.	0.	0.	0.	0.
18.	0.	0.	0.	0.
19.	0.	0.	0.	0.
20.	0.	0.	0.	0.
21.	0.	0.	0.	0.
22.	0.	0.	0.	0.
23.	0.	0.	0.	0.
24.	0.	0.	0.	0.
25.	0.	0.	0.	0.
26.	0.	0.	0.	0.
27.	0.	0.	0.	0.
28.	0.	0.	0.	0.
29.	0.	0.	0.	0.
30.	0.	0.	0.	0.
31.	0.	0.	0.	0.
32.	0.	0.	0.	0.
33.	0.	0.	0.	0.
34.	0.	0.	0.	0.
35.	0.	0.	0.	0.
36.	0.	0.	0.	0.
37.	0.	0.	0.	0.
38.	0.	0.	0.	0.
39.	0.	0.	0.	0.
40.	0.	0.	0.	0.
41.	0.	0.	0.	0.
42.	0.	0.	0.	0.
43.	0.	0.	0.	0.
44.	0.	0.	0.	0.
45.	0.	0.	0.	0.
46.	0.	0.	0.	0.
47.	0.	0.	0.	0.
48.	0.	0.	0.	0.
49.	0.	0.	0.	0.
50.	0.	0.	0.	0.
51.	0.	0.	0.	0.
52.	0.	0.	0.	0.
53.	0.	0.	0.	0.
54.	0.	0.	0.	0.
55.	0.	0.	0.	0.
56.	0.	0.	0.	0.
57.	0.	0.	0.	0.
58.	0.	0.	0.	0.
59.	0.	0.	0.	0.
60.	0.	0.	0.	0.
61.	0.	0.	0.	0.
62.	0.	0.	0.	0.
63.	0.	0.	0.	0.
64.	0.	0.	0.	0.
65.	0.	0.	0.	0.
66.	0.	0.	0.	0.
67.	0.	0.	0.	0.
68.	0.	0.	0.	0.
69.	0.	0.	0.	0.
70.	0.	0.	0.	0.
71.	0.	0.	0.	0.
72.	0.	0.	0.	0.
73.	0.	0.	0.	0.
74.	0.	0.	0.	0.
75.	0.	0.	0.	0.
76.	0.	0.	0.	0.
77.	0.	0.	0.	0.
78.	0.	0.	0.	0.
79.	0.	0.	0.	0.
80.	0.	0.	0.	0.
81.	0.	0.	0.	0.
82.	0.	0.	0.	0.
83.	0.	0.	0.	0.
84.	0.	0.	0.	0.
85.	0.	0.	0.	0.
86.	0.	0.	0.	0.
87.	0.	0.	0.	0.
88.	0.	0.	0.	0.
89.	0.	0.	0.	0.
90.	0.	0.	0.	0.
91.	0.	0.	0.	0.
92.	0.	0.	0.	0.
93.	0.	0.	0.	0.
94.	0.	0.	0.	0.
95.	0.	0.	0.	0.
96.	0.	0.	0.	0.
97.	0.	0.	0.	0.
98.	0.	0.	0.	0.
99.	0.	0.	0.	0.
100.	0.	0.	0.	0.

9.00 5/1
9.00 5/1
9.00 5/1
9.00 5/1

10.00 5/1
10.10 5/1
10.20 5/1
10.30 5/1

10.40 5/1
10.50 5/1
11.00 5/1
11.10 5/1

11.20 5/1
11.30 5/1
11.40 5/1
11.50 5/1

12.00 5/1
12.10 5/1
12.20 5/1
12.30 5/1

12.40 5/1
12.50 5/1
13.00 5/1
13.10 5/1

13.20 5/1
13.30 5/1
13.40 5/1
13.50 5/1

14.00 5/1
14.10 5/1
14.20 5/1
14.30 5/1

14.40 5/1
14.50 5/1
15.00 5/1
15.10 5/1

15.20 5/1
15.30 5/1
15.40 5/1
15.50 5/1

16.00 5/1
16.10 5/1
16.20 5/1
16.30 5/1

16.40 5/1
16.50 5/1
17.00 5/1
17.10 5/1

17.20 5/1
17.30 5/1
17.40 5/1
17.50 5/1

18.00 5/1
18.10 5/1
18.20 5/1
18.30 5/1

18.40 5/1
18.50 5/1
19.00 5/1
19.10 5/1

19.20 5/1
19.30 5/1
19.40 5/1
19.50 5/1

20.00 5/1
20.10 5/1
20.20 5/1
20.30 5/1

20.40 5/1
20.50 5/1
21.00 5/1
21.10 5/1

21.20 5/1
21.30 5/1
21.40 5/1
21.50 5/1

22.00 5/1
22.10 5/1
22.20 5/1
22.30 5/1

22.40 5/1
22.50 5/1
23.00 5/1
23.10 5/1

23.20 5/1
23.30 5/1
23.40 5/1
23.50 5/1

24.00 5/1
24.10 5/1
24.20 5/1
24.30 5/1

24.40 5/1
24.50 5/1
25.00 5/1
25.10 5/1

25.20 5/1
25.30 5/1
25.40 5/1
25.50 5/1

19.0120
20.0121
20.0122
20.0123
20.0124
20.0125
20.0126
20.0127
20.0128
20.0129
20.0130
20.0131
20.0132
20.0133
20.0134
20.0135
20.0136
20.0137
20.0138
20.0139
20.0140
20.0141
20.0142
20.0143
20.0144
20.0145
20.0146
20.0147
20.0148
20.0149
20.0150
20.0151
20.0152
20.0153
20.0154
20.0155
20.0156
20.0157
20.0158
20.0159
20.0160
20.0161
20.0162
20.0163
20.0164
20.0165
20.0166
20.0167
20.0168
20.0169
20.0170
20.0171
20.0172
20.0173
20.0174
20.0175
20.0176
20.0177
20.0178
20.0179
20.0180
20.0181
20.0182
20.0183
20.0184
20.0185
20.0186
20.0187
20.0188
20.0189
20.0190
20.0191
20.0192
20.0193
20.0194
20.0195
20.0196
20.0197
20.0198
20.0199
20.0200

5.0154 I
6.0150 I
7.0150 I
7.1015 I

7.0151 I
7.0152 I
7.0153 I

7.0154 I
7.0155 I
7.0156 I

7.0157 I
7.0158 I
7.0159 I

7.0160 I
7.0161 I
7.0162 I

7.0163 I
7.0164 I
7.0165 I

7.0166 I
7.0167 I
7.0168 I

7.0169 I
7.0170 I
7.0171 I

7.0172 I
7.0173 I
7.0174 I

7.0175 I
7.0176 I
7.0177 I

7.0178 I
7.0179 I
7.0180 I

7.0181 I
7.0182 I
7.0183 I

7.0184 I
7.0185 I
7.0186 I

7.0187 I
7.0188 I
7.0189 I

7.0190 I
7.0191 I
7.0192 I

7.0193 I
7.0194 I
7.0195 I

7.0196 I
7.0197 I
7.0198 I

7.0199 I
7.0200 I
7.0201 I

7.0202 I
7.0203 I
7.0204 I

7.0205 I
7.0206 I
7.0207 I

7.0208 I
7.0209 I
7.0210 I

748.	795.	842.	889.	936.	983.	1030.	1077.	1124.	1171.	1218.	1265.	1312.	1359.	1406.	1453.	1500.	1547.
802.	849.	896.	943.	990.	1037.	1084.	1131.	1178.	1225.	1272.	1319.	1366.	1413.	1460.	1507.	1554.	1601.
872.	919.	966.	1013.	1060.	1107.	1154.	1201.	1248.	1295.	1342.	1389.	1436.	1483.	1530.	1577.	1624.	1671.
870.	917.	964.	1011.	1058.	1105.	1152.	1199.	1246.	1293.	1340.	1387.	1434.	1481.	1528.	1575.	1622.	1669.
852.	899.	946.	993.	1040.	1087.	1134.	1181.	1228.	1275.	1322.	1369.	1416.	1463.	1510.	1557.	1604.	1651.
839.	886.	933.	980.	1027.	1074.	1121.	1168.	1215.	1262.	1309.	1356.	1403.	1450.	1497.	1544.	1591.	1638.

STAGE

543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0
543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0
543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0
543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0
543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0
543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0
543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0
543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0
543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0
543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0
543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0
543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0
543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0
543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0
543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0
543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0
543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0
543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0
543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0
543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0
543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0	543.0

PEAK OUTFLOW IS 146.5 AT TIME 41.00 HOURS

PEAK	6-HOUR	24-HOUR	71-HOUR	TOTAL VOLUME
146.6	723.	221.	113.	32439.
42.	6.	6.	1.	919.
CFS	11.39	14.17	14.21	14.21
INCHES	289.42	359.33	160.36	360.86
MM	358.	445.	447.	447.
AC-FT	443.	549.	551.	551.
THOUS CU M				

10.00 501
10.00 502
10.00 503
10.00 504
10.00 505
10.00 506
10.00 507
10.00 508
10.00 509
10.00 510

10.00 511
10.00 512
10.00 513
10.00 514
10.00 515
10.00 516
10.00 517
10.00 518
10.00 519
10.00 520

10.00 521
10.00 522
10.00 523
10.00 524
10.00 525
10.00 526
10.00 527
10.00 528
10.00 529
10.00 530

10.00 531
10.00 532
10.00 533
10.00 534
10.00 535
10.00 536
10.00 537
10.00 538
10.00 539
10.00 540

10.00 541
10.00 542
10.00 543
10.00 544
10.00 545
10.00 546
10.00 547
10.00 548
10.00 549
10.00 550

10.00 551
10.00 552
10.00 553
10.00 554
10.00 555
10.00 556
10.00 557
10.00 558
10.00 559
10.00 560

10.00 561
10.00 562
10.00 563
10.00 564
10.00 565
10.00 566
10.00 567
10.00 568
10.00 569
10.00 570

10.00 571
10.00 572
10.00 573
10.00 574
10.00 575
10.00 576
10.00 577
10.00 578
10.00 579
10.00 580

10.00 581
10.00 582
10.00 583
10.00 584
10.00 585
10.00 586
10.00 587
10.00 588
10.00 589
10.00 590

10.00 591
10.00 592
10.00 593
10.00 594
10.00 595
10.00 596
10.00 597
10.00 598
10.00 599
10.00 600

10.00 601
10.00 602
10.00 603
10.00 604
10.00 605
10.00 606
10.00 607
10.00 608
10.00 609
10.00 610

00.01211
00.01211
00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

00.01211

6561831
7.011800 I
7.101870 I

7.201850 I
7.311850 I
7.411870 I

7.501841 I
7.601800 I
7.701870 I

7.801870 I
7.901890 I
8.001890 I

8.101910 I
8.201910 I
8.301910 I

8.401930 I
8.501970 I
8.601980 I

8.701910 I
8.801910 I
8.901910 I

9.001910 I
9.101910 I
9.201910 I

9.301910 I
9.401910 I
9.501910 I

9.601910 I
9.701910 I
9.801910 I

9.901910 I
10.001910 I
10.101910 I

10.201910 I
10.301910 I
10.401910 I

10.501910 I
10.601910 I
10.701910 I

10.801910 I
10.901910 I
11.001910 I

11.101910 I
11.201910 I
11.301910 I

11.401910 I
11.501910 I
11.601910 I

0. 248. 0. 0.
0. 249. 0. 0.
0. 250. 0. 0.
0. 251. 0. 0.
0. 252. 0. 0.
0. 253. 0. 0.
0. 254. 0. 0.
0. 255. 0. 0.
0. 256. 0. 0.
0. 257. 0. 0.
0. 258. 0. 0.
0. 259. 0. 0.
0. 260. 0. 0.
0. 261. 0. 0.
0. 262. 0. 0.
0. 263. 0. 0.
0. 264. 0. 0.
0. 265. 0. 0.
0. 266. 0. 0.
0. 267. 0. 0.
0. 268. 0. 0.
0. 269. 0. 0.
0. 270. 0. 0.
0. 271. 0. 0.
0. 272. 0. 0.
0. 273. 0. 0.
0. 274. 0. 0.
0. 275. 0. 0.
0. 276. 0. 0.
0. 277. 0. 0.
0. 278. 0. 0.
0. 279. 0. 0.
0. 280. 0. 0.
0. 281. 0. 0.
0. 282. 0. 0.
0. 283. 0. 0.
0. 284. 0. 0.
0. 285. 0. 0.
0. 286. 0. 0.
0. 287. 0. 0.
0. 288. 0. 0.
0. 289. 0. 0.
0. 290. 0. 0.
0. 291. 0. 0.
0. 292. 0. 0.
0. 293. 0. 0.
0. 294. 0. 0.
0. 295. 0. 0.
0. 296. 0. 0.
0. 297. 0. 0.
0. 298. 0. 0.
0. 299. 0. 0.
0. 300. 0. 0.

PEAK FLOW AND STORAGE (END OF PIPED) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
 AREA IN SQUARE FEET (SQUARE KILOMETERS)

OPERATION	STATION	AREA	PLAN RATIO	RATIOS APPLIED TO FLOWS					
				RATIO 1	RATIO 2	RATIO 3	RATIO 4	RATIO 5	RATIO 6
ADJUDGMENT AT	1	0.59	1	0.20	0.40	0.50	0.50	0.80	1.00
	(1798.09)	(10.13)	(20.27)	(25.33)	(30.40)	(40.53)	(50.67)	(1789.)	(50.67)
ADJUD IS	1	0.59	1	105.	255.	338.	555.	807.	1466.
	(3798.09)	(2.93)	(7.21)	(9.57)	(15.72)	(28.57)	(41.53)	(41.53)	(41.53)

SUMMARY OF DAM SAFETY ANALYSIS

PLAD 1

ELEVATION STORAGE
OUTFLOW

INITIAL VALUE SUTELLWAY CRYST T.P. IF DAM
543.00 543.00 545.00
709. 734. 867.
0. 0. 543.

RATIO OF PWF	MAXIMUM RESERVOIR W-S-ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM CUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
0.20	549.34	0.	777.	103.	0.	42.83	0.
0.40	545.46	0.	837.	255.	0.	42.67	0.
0.50	545.97	0.	865.	338.	0.	42.67	0.
0.60	546.27	0.27	882.	555.	2.50	42.00	0.
0.80	546.62	0.62	901.	1009.	3.50	41.33	0.
1.00	546.85	0.89	915.	1466.	4.17	41.00	0.

APPENDIX 0

REFERENCES



APPENDIX D

REFERENCES


- 1) U.S. Department of Commerce, Technical Paper No. 40, Rainfall Frequency Atlas of the United States, May 1961.
- 2) U.S. Department of Commerce, Hydrometeorological Report No. 33, Seasonal Variation of the Probable Maximum Precipitation East of the 105th Meridian for Areas from 10 to 1,000 Square Miles and Durations of 6, 12, 24, and 48 Hours; April 1956.
- 3) Soil Conservation Service, National Engineering Handbook, Section 4, Hydrology, August 1972 (U.S. Department of Agriculture),
- 4) H.W. King and E.F. Brater, Handbook of Hydraulics, 5th edition, McGraw-Hill, 1963.
- 5) T.W. Lambe and R.V. Whitman, Soil Mechanics, John Wiley and Sons, 1965.
- 6) W.D. Thornbury, Principles of Geomorphology, John Wiley and Sons, 1969.
- 7) University of the State of New York, Geology of New York, Education Leaflet 20, Reprinted 1973.
- 8) Cornell University Agriculture Experiment Station (compiled by M.G. Cline and R.L. Marshall); General Soil Map of New York State and Soils of New York Landscapes, Information Bulletin 119, 1977.

APPENDIX E

DRAWINGS



TOPOGRAPHIC MAP



VICINITY MAP

TEST BORING REPORT RAYMOND

CONCRETE PILE DIVISION
RAYMOND INTERNATIONAL INC.
140 CEDAR STREET - NEW YORK 6, N. Y.

To CHUMARD & MC GOUGH

Date JUNE 4 19 63

Address 4 FAIRLAWN AVENUE, MIDDLETOWN, NEW YORK


We have completed the following borings for you at EXISTING RESERVOIR DAM, VILLAGE OF GOSHEN, GOSHEN, N.Y.

with results show below In accordance with your instructions, we ~~WILL SEND~~ WILL SEND labelled samples of the strata encountered

To SAME AS ABOVE Address SAME AS ABOVE

Via RAILWAY EXPRESS under date of JUNE, 1963 Raymond Concrete Pile Division

Raymond International Inc. LOCATION PLAN SCALE 1" =



This boring report prepared in the
NEW YORK OFFICE of the
Raymond Concrete Pile Division
RAYMOND INTERNATIONAL INC.

By CQ
Job No. B E-2734
Sheet 1 of 2

TEST BORING REPORT

RAYMOND

CONCRETE PILE COMPANY
GOW DIVISION

To CHUMARD & MC SOUGH

Date JUNE 4, 1963

Location of Borings GOSHEN, NEW YORK

All borings are plotted to scale of 1" = 8 ft. using ELEVATIONS TAKEN FROM PRINT as a fixed datum.
SUPPLIED BY CLIENT

Boring No. 1

Boring No. 2

Boring No. _____

ELEV. 100.89' ±

0.0	FINE BRN SAND, GRAVEL & SOME BOULDERS		36 42 50 54
4.0	FINE BROWN SAND, SOME GRAVEL & CLAY	12	20 16 19 17 12 10 9 8 8 11 7 8 9 10 9 6 9 11 10 9 7 12 13 10 11 7
(WL) 6.0 (12)		14	
		7	
17.0		10	
	GRAY BROWN SILTY CLAY & SOME SHALE	8 9	13 10 11 7 13 14 39 54
32.5	FINE BRN SANDY CLAY & SHALE	100/8	
34.5			

ELEV. 100.82' ±

0.0	SAND, GRAVEL & BOULDERS		32 46 54 39
4.0	FINE BROWN SAND, SOME GRAVEL & CLAY	15	20 16 14 11 11 9 8 7 10 7 6 8 8 9 7
(WL) 6.0 (12)		13	
		9	
19.0	FINE GRAY BROWN SANDY SILTY CLAY & SOME SHALE	6 10	10 11 11 9 9 7 7 8 9 10 8 10 10 11 11 9 11 11 12 16 22
37.0	FINE BRN SANDY CLAY & SOME GRAVEL	19	
40.0			


GENERAL NOTE: NUMBERS ON EXTREME RIGHT OF COLUMN INDICATE NUMBER OF BLOWS REQUIRED TO DRIVE 2 1/2" CASING ONE FOOT, USING 350 LB WEIGHT FALLING 18"

Classifications are made from visual inspection.

Water Levels (WL). Figure indicates time of reading (hours) after completion of boring. Water levels indicated are those observed when borings were made, or as noted. Porosity of the soil stratas, variations of rainfall, site topography, etc., may cause changes in these levels.

Figures in right hand column indicate number of blows required to drive 2" O. D. sampling pipe one foot, using a 140 lb. weight falling 30 inches.

Total Footage 74.5'
Foreman WATTERS
Classifications by WL/MB
Job No. B E-2734
Sheet 2 of 2



OPER. INV. EL. 98.29
INV. EL. 98.94

TOP CON. WALL 45.60
EL. 98.12

NEW
SPILLWAY

EXISTING SPILLWAY
CHANNEL

NEW SPILLWAY CHANNEL
RIP RAP SIDES AND BOTTOM

PLAN

STAIRS

51

51

51

51

51

51

51

51

51

51


51

51

51

51

51



OPER. INV. EL. 98.29
INV. EL. 98.94

TOP CON. WALL 45.60
EL. 98.12

NEW
SPILLWAY

EXISTING SPILLWAY
CHANNEL

NEW SPILLWAY CHANNEL
RIP RAP SIDES AND BOTTOM

PLAN

STAIRS

51

51

51

51

51

51

51

51

51

51

51

51

51

51

51

EXISTING CHANNEL

2' TOP OF SLOPE

REMOVE EXISTING
GRUB AND CL

TOP OF
PROPOSED DAM

1730
EL. 105.00

73.74

90

100

BASE LINE 3.86'
POINT "O" ON
PROFILE BELOW

112.15

112.15

112

60

70

72

74

76

EXISTING
ROAD CL

MALABAN

ROAD

9.05

20.5

6.45

14.00

10.25

12.15

EL. 105.00

27.00


STAKE

RELOCATE
DOCK HERE

NEW SPICE LINE
WATER - 2/12/50

BENCH MARK

NEW DOCK



CONCRETE
BASE EL. 99.42

CLEAR AND GRUB
THIS AREA

TOP EL. 105.00

NEW CONCRETE FLOOR

NEW HIGH
WATER LINE

TOP OF NEW
ENCLOSURE WALL
EL. 105.00

NEW FLOOR

EXISTING GRADE

TOP OF NEW
ENCLOSURE WALL
EL. 105.00


NEW GRADE

EXISTING GRADE


WEST ELEV

RELOCATE
EXISTING DOOR HERE


RAISE WATER
STANDS 5'
RAISE FLOOR
3'-6"



NORTH ELEVATION





WEST ELEVATION



RAISE WATER STANDS 3'-6"

RAISE FLOOR 3'-6"

BRICK UP



SECTION
SCALE - 1"


SEE SHEET 3

TOP OF
EXISTING DAM

EXISTING
LINE

A ←

GENERAL PLAN
SCALE - 1" = 30'



DAM

PROPOSED SLOPE

REMOVE TREES,
GRUB AND CLEAR

SECTION A-A

SCALE - 1" = 10'

SEE SHEET 3 FOR OTHER SECTIONS

17


EXISTING FLOOR EL. 100.00
LINE

EXISTING FLOOR EL. 100.00

EXISTING FLOOR EL. 100.00
NEW FLOOR EL. 102.00
SEE DETAILS

EXISTING
GATE HOUSE



EXISTING GROUND LINE



NEW SPILLWAY
SCALE - 1" = 20'

1-8

PAGE EL. 100.0
OR EL. 103.75
STALS



FLOOR PLAN
DETAIL AT GATE
SCALE - 1/8" = 1'-0"

DETAIL ENCLOSURE WALL
SCALE - 3/8" = 1'-0"

STATE OF NEW YORK
DEPARTMENT OF PUBLIC WORKS
DIVISION OF CONSTRUCTION
ALBANY, N. Y.

This plan for re-construct
Lower Hudson River
approved under the provisions of
Conservation Law.

Examined and recommended for
approval.

ASSOCIATE

APPROVED

CH
Department

By:

INCREASING STORAGE CAPACITY PROSPECT RESERVOIR VILLAGE OF GOSHEN ORANGE COUNTY SCALE - STATED

ASSOCIATE - JOSEPH A. WESTNER, JR.
CONSULTING ENGINEER
TROY, N. Y.

BRICK UP
FOORWAY

FLOOR PLAN

DETAIL AT GATE HOUSE

SCALE - 1/8" = 1'-0"

STATE OF NEW YORK
DEPARTMENT OF PUBLIC WORKS
DIVISION OF CONSTRUCTION
ALBANY, N. Y.

July 5, 1963

This plan for re-constructing dam No. 174B-3163
Lower Hudson River watershed is hereby
approved under the provisions of Section 948 of the
Conservation Law.

Examined and recommended to the Chief Engineer for
approval.

[Signature]
ASSOCIATE CIVIL ENGINEER

CHIEF ENGINEER
Department of Public Works

By *[Signature]*
Deputy Chief Engineer

APPROVED

STORAGE CAPACITY
RESERVOIR FOR

ORANGE COUNTY, N.Y.

MAY 13, 1963

[Signature]
CRUMAZZ & MCGOUGH
CONSULTING ENGINEERS
4 FIELLANK AVE.
MIDDLETOWN, N.Y.

6" PERFORATED
COARSE SAND
SEE DETAIL

6" CONCRETE SLAB
W/ 2" MESH 6" x 6" @ 10" O.C.

10'-0"



ES&W

12

PERFORATED PIPE IN
GRAVEL TRENCH
SEWER

10'-0"

2 A
2 A

CONST. JOINT

5'-0"

25'-0"

5'-0"

28'-0"

5'-0"

6'-0"

7'-0"

0'-0"

2 1/2 BATH

W. 25 WEST

EL. 10'-0"

2

AD-A109 838

NEW YORK STATE DEPT OF ENVIRONMENTAL CONSERVATION ALBANY F/G 13/13
NATIONAL DAM SAFETY PROGRAM. GOSHEN RESERVOIR NUMBER 1 DAM (INV--ETC(U)
AUG 81 G KOCH DACW51-79-C-0001

NL

UNCLASSIFIED

2 of 2


AD-A109 838



2 OF 2

AD A

109838




WESTERN
NBS 1963-A
NBS 1963-A

13





SECTION B-P

105




LOCATION PLAN
 906.E-11-201





25-01
27-01



WIRE MESH
6" x 6" @ 18"




SECTION 2-D
SCALE 1/4" = 1'-0"


28-01
27-01

PLAN

SCALE 1/4" = 1'-0"



SECTION



EXISTING

EARTH

S.P. 2AD

E.L. 10.50

S.P. 2AD

SECTION A-A

SCALE 1/4" = 1'-0"

18

EXISTING SECOND LINE

TOP OF DAM E. 102.00

E. 102.00

COMPACT FILL

SATUM 100.00

SECTION ALONG C DAM

SCALE - HORIZONTAL
VERTICAL

INCREASING STORAGE CAPACITY PROSPECT RESERVOIR

VILLAGE OF GOSHEN ORANGE COUNTY

SCALE - STATED

ASSOCIATE - JOSEPH A. KESTNER JR.
CONSULTING ENGINEER
TROY, N.Y.

REF. N. 04-17
ENGR. B. 3

SHEET 2 OF 5

CHUMA
CONSULTING
& ENGINEERING
MIDDLETOWN, N.Y.

1. 1955-56
SATUM 188.00

CAPACITY

RESERVOIR

ORANGE COUNTY, N.Y.

JUNE 1955

CHUMAZE & MCGOUGH
CONSULTING ENGINEERS
4 FARLAWN AVE.
MIDDLETOWN, N.Y.