

AD-A109 966

METCALF AND EDDY OF NEW YORK INC NY

F/G 13/13

NATIONAL DAM SAFETY PROGRAM. POTTERS FALLS DAM (INVENTORY NUMBE--ETC(U)


SEP 81 G P FULTON

DACW51-81-C-0044

NL

UNCLASSIFIED

1 of 2
AD-A
109 966




1

OF



AD A

109966



REPORT DOCUMENTATION PAGE

READ INSTRUCTIONS
BEFORE COMPLETING FORM

1. REPORT NUMBER

2. GOVT ACCESSION NO.

3. RECIPIENT'S CATALOG NUMBER

4. TITLE (and Subtitle)

Phase I Inspection Report

Potters Falls Dam

Oswego River Basin, Tompkins County, NY

Inventory No. 378

5. TYPE OF REPORT & PERIOD COVERED

Phase I Inspection Report

National Dam Safety Program

6. PERFORMING ORG. REPORT NUMBER

7. AUTHOR(s)

GEORGE P. FULTON

8. CONTRACT OR GRANT NUMBER(s)

DACW51-81-C-0044

9. PERFORMING ORGANIZATION NAME AND ADDRESS

Metcalf and Eddy of New York, Inc.

60 East 42nd Street

New York, New York 100017

10. PROGRAM ELEMENT, PROJECT, TASK

AREA & WORK UNIT NUMBERS

11. CONTROLLING OFFICE NAME AND ADDRESS

Department of the Army

26 Federal Plaza New York District, CofE

New York, New York 10287

12. REPORT DATE

23 September 1981

13. NUMBER OF PAGES

14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)

Department of the Army

26 Federal Plaza New York District, CofE

New York, NY 10287

15. SECURITY CLASS. (of this report)

UNCLASSIFIED

15a. DECLASSIFICATION/DOWNGRADING SCHEDULE

16. DISTRIBUTION STATEMENT (of this Report)

Approved for public release; Distribution unlimited.

17. DISTRIBUTION STATE

18. SUPPLEMENTARY NOTES

19. KEY WORDS (Continue on reverse side if necessary and identify by block number)

Dam Safety

National Dam Safety Program

Visual Inspection

Hydrology, Structural Stability

Potter Falls Dam

Oswego River Basin

Tompkins County

20. ABSTRACT (Continue on reverse side if necessary and identify by block number)

This report provides information and analysis on the physical condition of the dam as of the report date. Information and analysis are based on visual inspection of the dam by the performing organization.

Visual inspection of this dam and engineer analysis which was performed revealed that several deficiencies exist on this structure.

DD FORM 1 JAN 73 1573

EDITION OF 1 NOV 65 IS OBSOLETE

4112141

AD A109966

DTIC FILE COPY

DTIC
ELECTED
JAN 25 1982
H

The worst of these deficiencies was the localized spalling and erosion of the gunite covering the dam. This was observed in three areas on the downstream face and toe. A more thorough examination of the gunite when there is no discharge over the spillway is needed to evaluate the extent and cause of this deterioration. If the gunite is not repaired, the interior concrete of the dam will become exposed to erosion.

Using the Corps of Engineer's Guidelines for the initial review of spillway adequacy, it has been determined that the structure would be overtopped by all storms exceeding 31 percent of the Probable Maximum Flood (PMF). During a one-half PMF storm, the abutments of the dam would be overtopped by 3.4 feet. The dam is a concrete arch-gravity structure with bedrock at both abutments. While overtopping is not likely to induce failure from erosion, a stability analysis indicates that the factor of safety is below the recommended level during the one-half PMF storm. If the dam were to fail, it would increase the degree of flooding in downstream residential areas. Therefore, the spillway is assessed as seriously inadequate.

DISCLAIMER NOTICE

**THIS DOCUMENT IS BEST QUALITY
PRACTICABLE. THE COPY FURNISHED
TO DTIC CONTAINED A SIGNIFICANT
NUMBER OF PAGES WHICH DO NOT
REPRODUCE LEGIBLY.**


OSWEGO RIVER BASIN

POTTER'S FALLS DAM

**TOMPKINS COUNTY, NEW YORK
INVENTORY NO. NY 378**

**PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM**

**APPROVED FOR PUBLIC RELEASE;
DISTRIBUTION UNLIMITED**



01 15 82 058

NEW YORK DISTRICT CORPS OF ENGINEERS

AUGUST 1981

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I Investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, and Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

Accession For	
NTIS GRA&I	<input checked="checked" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By	
Date	
Project	
Special	
A	27



PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
POTTER'S FALLS DAM
I.D. No. 378
75A-717
OSWEGO RIVER BASIN
TOMPKINS COUNTY, NEW YORK

TABLE OF CONTENTS

	<u>PAGE NO.</u>
- ASSESSMENT	
- OVERVIEW PHOTOGRAPH	
1 PROJECT INFORMATION	1
1.1 GENERAL	1
1.2 DESCRIPTION OF PROJECT	1
1.3 PERTINENT DATA	2
2 ENGINEERING DATA	4
2.1 GEOTECHNICAL	4
2.2 DESIGN RECORDS	4
2.3 CONSTRUCTION RECORDS	4
2.4 OPERATION RECORDS	4
2.5 EVALUATION OF DATA	4
3 VISUAL INSPECTION	6
3.1 FINDINGS	6
3.2 EVALUATION OF OBSERVATIONS	7
4 OPERATION AND MAINTENANCE PROCEDURES	8
4.1 PROCEDURES	8
4.2 MAINTENANCE OF DAM	8
4.3 WARNING SYSTEM IN EFFECT	8
4.4 EVALUATION	8

	<u>PAGE NO.</u>
5 HYDRAULIC/HYDROLOGIC	9
5.1 DRAINAGE AREA CHARACTERISTICS	9
5.2 ANALYSIS CRITERIA	9
5.3 SPILLWAY CAPACITY	9
5.4 RESERVOIR CAPACITY	9
5.5 FLOODS OF RECORD	9
5.6 OVERTOPPING POTENTIAL	10
5.7 EVALUATION	10
6 STRUCTURAL STABILITY	11
6.1 EVALUATION OF STRUCTURAL STABILITY	11
7 ASSESSMENT/RECOMMENDATIONS	13
7.1 ASSESSMENT	13
7.2 RECOMMENDED MEASURES	14

APPENDIX

- A. PHOTOGRAPHS
- B. VISUAL INSPECTION CHECKLIST
- C. HYDROLOGIC/HYDRAULIC ENGINEERING DATA AND COMPUTATIONS
- D. STRUCTURAL STABILITY
- E. REFERENCES
- F. PREVIOUS INSPECTION REPORTS
- G. DRAWINGS

PHASE I REPORT
NATIONAL DAM SAFETY PROGRAM

Name of Dam: Potter's Falls Dam (I.D. No. NY 378)
State Located: New York
County: Tompkins
Watershed: Oswego River Basin
Stream: Sixmile Creek
Date of Inspection: July 8, 1981

ASSESSMENT

Visual inspection of this dam and engineering analyses which have been performed revealed that several deficiencies exist on this structure.

The worst of these deficiencies was the localized spalling and erosion of the gunite covering the dam. This was observed in three areas on the downstream face and toe. A more thorough examination of the gunite when there is no discharge over the spillway is needed to evaluate the extent and cause of this deterioration. If the gunite is not repaired, the interior concrete of the dam will become exposed to erosion.


Using the Corps of Engineer's Guidelines for the initial review of spillway adequacy, it has been determined that the structure would be overtopped by all storms exceeding 31 percent of the Probable Maximum Flood (PMF). During a one-half PMF storm, the abutments of the dam would be overtopped by 3.4 feet. The dam is a concrete arch-gravity structure with bedrock at both abutments. While overtopping is not likely to induce failure from erosion, a stability analysis indicates that the factor of safety is below the recommended level during the one-half PMF storm. If the dam were to fail, it would increase the degree of flooding in downstream residential areas. Therefore, the spillway is assessed as seriously inadequate.


Within three months of the receipt of this report, the owner should commence a more detailed stability analysis. Further hydraulic/hydrologic studies are needed to accurately determine flood reservoir levels. Additional inspection and evaluation of the deteriorated gunite is also required. The owner should exercise the gate on the low-level outlet and maintain it in good operating condition. Remedial measures deemed necessary as a result of these studies should be completed within 18 months.

C


Other deficiencies as outlined below should be corrected within 12 months of the date of notification of the Owner:

1. The operating condition of the sluice gate on the low-level outlet should be tested and repaired as necessary for dependable operation.
2. The deteriorated concrete on the abutments should be repaired, and the brick facing replaced or repaired as necessary.
3. Vegetation growing on the abutment should be removed.
4. The concrete sill on the weir should be repaired to prevent further leakage beneath it.
5. Any open joints in the spillway should be repointed, particularly in the area of heavy efflorescence.
6. An emergency action plan should be developed for the notification and evacuation of downstream residents.


Edward M. Greco, P.E.
Project Manager
Metcalf & Eddy of New York, Inc.
New York Registration No. 47463


George P. Fulton, P.E.
Vice President
Metcalf & Eddy of New York, Inc.
New York Registration No. 22390

Approved By:


Col. W. M. Smith, Jr.
New York District Engineer

Date:

22 Sept 81

OVERVIEW
POTTER'S FALLS DAM
NY ID NO. 378



PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
POTTER'S FALLS DAM
I.D. No. NY 378
75A-717
OSWEGO RIVER BASIN
TOMPKINS COUNTY, NEW YORK

SECTION 1: PROJECT INFORMATION

1.1 GENERAL

a. Authority

The Phase I inspection reported herein was authorized by the Department of the Army, New York District, Corps of Engineers, to fulfill the requirements of the National Dam Inspection Act, Public Law 92-367.

b. Purpose of Inspection

This inspection was conducted to evaluate the existing conditions of the dam, to identify deficiencies and hazardous conditions, to determine if these deficiencies constitute hazards to life and property, and to recommend remedial measures where required.

1.2 DESCRIPTION OF PROJECT

a. Description of Dam

Potter's Falls Dam, locally known as the 60 Foot Dam, impounds the Ithaca Reservoir used as a water supply for the City of Ithaca. The dam is a concrete gravity structure that is arch-shaped in plan view. A spillway weir is centrally located on the top of the dam, and a low-level outlet is located at the base. On the upstream side, there is a gatehouse containing mechanisms to operate valves on the water supply line and the low-level outlet.

The dam is 220 feet long with a maximum height of 70.5 feet. It is constructed of cyclopean concrete covered with gunite and mesh. The top width is 8.5 feet. The upstream face of the dam is vertical and the downstream face is 0.7 to 1 (horizontal to vertical).

The spillway is a 100-foot long, ungated ogee weir. Discharge flows onto the downstream face of the dam and into a 100-foot wide bedrock gorge.

A 72-inch cast iron pipe passes through the base of the dam and serves as the low-level outlet. The pipe is 45.5 feet long. Flow is controlled by a gate at the upstream end of the pipe. The gate is operated from the upper level of the gatehouse.

A 24-inch cast iron pipe passes through the right abutment of the dam and serves as the water supply line. The pipe extends from a wet well in the lower level of the gatehouse to the treatment plant 9,400 feet downstream. Flow is normally regulated at the treatment plant, however,

there are also two gates on the pipe in the gatehouse. One is at the upstream end of the pipe and the other is on the opening into the wet well. Both are operated from floor stands in the upper level of the gatehouse.

b. Location

The dam is located on Sixmile Creek about 2.5 miles southeast of downtown Ithaca. An unpaved road that leads to the dam is located off Route 79, 0.3 miles south of the junction with Route 174.

c. Size Classification

The dam is a maximum of 70.5 feet high and has a storage capacity of 1,290 acre-feet. Therefore, the dam is in the intermediate size category as defined by the "Recommended Guidelines for Safety Inspection of Dams".

d. Hazard Classification

The dam is classified as "high" hazard due to the presence of dense commercial and residential development adjacent to the stream bed in the City of Ithaca, about 2.5 miles downstream.

e. Ownership

The dam is owned by the City of Ithaca and operated by personnel from the Department of Public Works - Water and Sewer Division. Mr. Phillip Cox, City Engineer was contacted concerning the Phase I Inspection. His address is City Hall, 108 East Green Street, Ithaca, New York 14850.

f. Purpose of Dam

The dam is a water supply reservoir for the City of Ithaca.

g. Design and Construction History

The dam was constructed in 1911. Drawings were prepared in 1910 and signed by Donald F. McLeod, City Engineer. Specifications are not available, and the name of the construction contractor is unknown. By 1925, siltation had decreased the storage capacity of the dam by 12 percent. The Silt Dam was therefore constructed 3,500 feet upstream to control siltation. In 1939, a covering of gunite and mesh was placed over the entire dam. There are no drawings or construction data available for that work.

e. Normal Operating Procedures

There are no regular operating procedures at the dam. The gate on the low-level outlet has not been operated since 1959 when the reservoir was drained to inspect for siltation. The gates on the water supply pipe are operated once or twice a year to dewater the wet well and clean the screens in the gatehouse.

1.3 PERTINENT DATA

a. Drainage Area (sq. mi.)

45.6

<u>b. Discharge at Dam (cfs)</u>		
Concrete Spillway-water surface at top of dam		10,450
72-inch Outlet-water surface at crest of spillway		1,044
<u>c. Elevation (Plan Datum)</u>		
Top of Dam		715.5
Spillway Crest		705.0
Invert of 72-inch outlet pipe		647.0
Invert of 24-inch water pipe		665.0
<u>d. Reservoir (Surface Area) (acres)</u>		
Top of Dam		47
Spillway Crest		47
<u>e. Storage Capacity (acre-feet)</u>		
Top of Dam		1,290
Spillway Crest		800
<u>f. Dam</u>		
Type:	cyclopean concrete gravity dam, arch in plan, surface covering of gunite and mesh	
Length (ft)		220
Slopes (V:H) Upstream		Vertical
Downstream		0.7:1
Crest Width (ft)		8.5
<u>g. Spillway</u>		
Type:	Concrete ogee overflow weir	
Length of Weir (ft)		100
<u>h. Low Level Outlet</u>		
Type:	72-inch cast iron pipe through dam, 45.5 feet long, gate controlling flow at upstream end of pipe, operating mechanism inside gatehouse	
<u>k. Appurtenant Structures</u>		
24-inch cast iron water supply pipe through dam at right abutment, 9,400 feet long, two gates at upstream end (gatehouse), but flow is controlled at downstream end (treatment plant)		

SECTION 2: ENGINEERING DATA

2.1 GEOTECHNICAL DATA

a. Geology

Potter's Falls Dam is located in the Southern New York Section of the Appalachian Plateaus physiographic province. The bedrock in this area consists of shales, siltstones, and sandstones that have been uplifted and gently folded into regional basin structures. The bedrock at the dam is a dark gray, thin bedded shale with prominent vertical joints that form the steep walls of the gorge below the dam. A review of the "Geologic Map of New York" indicated that there are no faults in the vicinity of the dam.

Surficial soils in the area are the result of glaciations during the Pleistocene Epoch, the last of which was the Wisconsin glaciation.

b. Subsurface Investigations

There are no records of any subsurface investigation for Potter's Falls Dam. Continuous bedrock outcrops are visible at the abutments and along the base of the dam.

2.2 DESIGN RECORDS

Design plans were prepared in 1910 under the direction of the City Engineer for the City of Ithaca. These were the only design records available.

2.3 CONSTRUCTION RECORDS

This dam was constructed in 1911. The name of the contractor is unknown, and there are no as-built drawings available. There was some correspondence available concerning the construction. Personnel from the New York State Conservation Commission inspected the structure about halfway through construction. The principal comment made by the Conservation Commission was that the concrete was not of good quality, containing too much coarse aggregate (3/8 to 3/4 inch crushed shale) and not enough sand. The sand fraction was increased as a result of this comment. There were no records of significant changes made in the design of the dam during construction.

2.4 OPERATION RECORDS

The only operation records available are hydrographs of the height of the reservoir above the crest of the spillway for the years 1939 through 1944.

2.5 EVALUATION OF DATA

Information used for the preparation of this report was obtained from the Department of Environmental Conservation files and from the City of

Ithaca's Water and Sewer Division files. The information available appeared to be reasonably accurate. The plan datum agrees with elevation given on U.S. Geological Survey quadrangle maps.

SECTION 3: VISUAL INSPECTION

3.1 FINDINGS

a. General

Visual inspection of Potter's Falls Dam was conducted on July 8, 1981. The weather was sunny with the temperature around 90 degrees. The water level at the time of the inspection was slightly above the crest to the spillway.

b. Dam

Inspection of the dam was hampered by the flow of discharge over the spillway and by the lack of access to the abutments on the downstream side of the dam.

Spalling and erosion of the gunite and mesh covering the dam has occurred in the following areas on the downstream face:

1. left abutment - halfway down
2. bottom of face - from outlet opening to left abutment
3. downstream toe - right abutment

A large bulge in the gunite is also visible on the downstream face opposite the level of the water pipe. There are hairline cracks with slight efflorescence in many areas on the dam. This deterioration could be caused by flowing water, freezing and thawing, seepage through the dam, improper construction techniques or materials, or a combination of these factors.

Minor seepage indicated by wet areas on the bedrock face was observed at both abutments on the downstream face of the dam. At the left abutment, the wet area is larger, extending from the top to about halfway down. There is no visible flow in the wet areas, and the bedrock is intact. It is likely that this seepage is occurring along nearly horizontal bedding planes in the bedrock.

Brush and trees are growing on the upstream side of both abutments of the dam.

c. Spillway

The spillway weir is in satisfactory condition. No voids or cracks were visible. The crest is clear of obstructions.

d. Low-Level Outlet

The low-level outlet was partly submerged and only visible at the downstream end. This end of the pipe is clear of debris and silt. To inspect the pipe further, it should be dewatered and ventilated.

e. Water Supply Pipe

The water supply pipe is mostly embedded in concrete or in bedrock. The concrete around the pipe just downstream of the dam is moderately eroded. Where the pipe is visible farther downstream, it is in satisfactory condition.

f. Gatehouse

The gatehouse is in fair structural condition. There are some thin vertical cracks in the walls and localized spalling of the concrete at the water line. Inside, the floor stands for operating the gates on the low-level outlet and the water supply pipe are intact.

g. Reservoir

There were no indications of slope instability in the reservoir area.

h. Downstream Channel

The channel downstream of the dam is a bedrock gorge. There are no significant obstructions in the floor or sides of the channel.

3.2 EVALUATION OF OBSERVATIONS

Visual observations revealed several deficiencies on this structure. The following items were noted:

1. Localized spalling and erosion of the gunite surface.
2. Minor seepage at the dam abutments.
3. Brush and trees growing next to the upstream face.
4. Eroded concrete on the exterior of the gatehouse and around the water supply pipe downstream of the dam.

SECTION 4: OPERATIONAL PROCEDURES

4.1 PROCEDURES

This reservoir is used as a water supply by the City of Ithaca. Flow through the water supply pipe is controlled downstream at the water treatment plant. The two gates on the water supply pipe at the dam are normally kept open. Once or twice a year, these gates are closed to de-water the wet well and clean the screens on the water supply pipe. The gate on the low-level outlet is normally kept closed. Its condition is unknown, since the last time it was operated was in 1959.

4.2 MAINTENANCE

Periodic visits are made to the dam to check on the condition of the facilities. The visits are made by personnel from the Ithaca Water and Sewer Division.

4.3 WARNING SYSTEM IN EFFECT

There is no apparent warning system for the notification and evacuation of downstream residents.

4.4 EVALUATION

The operation and maintenance procedures on this structure are not satisfactory. Additional maintenance efforts are required to correct some of the deficiencies noted in Section 3.2.

SECTION 5: HYDROLOGIC/HYDRAULIC

5.1 DRAINAGE AREA CHARACTERISTICS

The delineation of the watershed contributing to this dam is indicated on the Vicinity Map (Appendix F). The irregularly shaped 45.6 square mile (29,184 acre) watershed is comprised of relatively undeveloped land consisting of open fields and woodland. The village of Brooktondale located near the center of the watershed is the largest developed area. Slopes along the primary drainage paths are flat (1.5 percent). However, the adjacent hillsides have steep (9 percent) slopes. The hills that form the watershed divide are 700 to 1,200 feet above the reservoir elevation. There are a few small ponds and wetlands in lowland areas of the watershed. The only upstream dam is Silt Dam which fills with debris flowing toward the reservoir.

5.2 ANALYSIS CRITERIA

No hydrologic/hydraulic information was available regarding the original design for this dam. Therefore, the analysis of the floodwater retarding capability of the dam was performed using the Corps of Engineers HEC-1 computer program, Dam Safety version. This program uses the Snyder Synthetic Unit hydrograph and the "Modified Puls" flood routing procedure. The spillway design flood selected for analysis was the Probable Maximum Flood (PMF), in accordance with the Recommended Guidelines of the U.S. Army Corps of Engineers.

5.3 SPILLWAY CAPACITY

A 100-foot long ogee-crested spillway is located at the center of the dam. Flow over the weir was analyzed using a discharge coefficient of 3.97. The computed discharge capacity of the spillway is 10,450 cfs with the reservoir level at the top of the dam. The flood analysis performed for this dam indicates that the spillway does not have sufficient capacity for discharging one-half the PMF. For this storm event, the peak inflow is 18,850 and the peak outflow is 18,830 cfs. The full PMF peak inflow and peak outflow are 37,700 cfs and 37,680 cfs respectively.

5.4 RESERVOIR CAPACITY

The normal water surface is at or near the spillway crest elevation of 705.0 (plan datum). The impounded capacity at this elevation is 800 acre-feet. Surge storage capacity to the top-of-dam (elev. 715.5) adds 490 acre-feet which is equivalent to a direct runoff depth of 0.2 inches over the watershed. The total storage capacity is 1,290 acre-feet.

5.5 FLOODS OF RECORD

The maximum flood at the dam site is reported to have been in 1935, but the reservoir level at that time is unknown. The highest level on record

occurred March 17, 1942 when the reservoir reached elevation 709.1. This elevation is 4.1 feet above the crest of the spillway and 6.4 feet below the top of the dam.

5.6 OVERTOPPING POTENTIAL

Analyses using the PMF and one-half PMF storm events indicate that the spillway does not have sufficient discharge capacity. The computed depths of overtopping for these two events are 9.6 feet and 3.4 feet respectively. All storm events exceeding 31 percent of the PMF will result in the dam being overtopped.

5.7 EVALUATION

The spillway is inadequate for the peak outflow from one-half the PMF. Due to the concrete construction of the dam and bedrock outcrops at both abutments, overtopping is unlikely to result in failure due to erosion. However, as discussed in the following section, a preliminary stability analysis indicates that the factor of safety is below the recommended value with the reservoir at the one-half PMF level. Dense residential and commercial development exists 2.5 miles downstream in the City of Ithaca. If the dam were to fail, it would increase the degree of flooding downstream from that which would exist prior to failure. Based on the capacity of the spillway, the low factor of safety, and the increased flooding as a result of failure, the spillway is assessed as seriously inadequate.

SECTION 6: STRUCTURAL STABILITY

6.1 EVALUATION OF STRUCTURAL STABILITY

a. Visual Observation

The dam is a combined arch and gravity design, constructed of concrete which was later covered with gunite and mesh. The reason for adding the gunite is unknown.

A close inspection of the downstream face of the dam was restricted by discharge over the spillway and a lack of access to the abutments. The downstream toe near the middle of the dam was submerged and could not be inspected. No major settlement was visible. The gunite covering the dam is locally spalled and bulging. Minor seepage was observed on the downstream face at both abutments.

b. Data Review and Stability Analysis

No design information concerning the stability of either the concrete dam or spillway sections was available. The design drawings provided cross sections used in the analyses. There are no as-built drawings or other construction data available for the dam.

A stability analysis was performed for this report in accordance with the "Recommended Guidelines for Safety Inspection of Dams". The analysis was performed using a section at the center of the dam perpendicular to the spillway weir. It was assumed that the structure is constructed of cyclopean concrete, as shown on the construction drawing dated August, 1910. The foundation material is horizontally bedded shale. No drainage system to relieve uplift pressures is shown on the drawings.

Due to the arch design of the dam, an overturning analysis was not performed for this structure. Therefore, only the safety factors against sliding were computed. The results of the analysis are as follows:

Case:	Sliding: Factors of Safety Spillway Section
a) Reservoir level at spillway crest	0.76
b) a) plus ice load of 5,000 lb./ft.	0.73
c) Reservoir level at top of dam	0.49
d) a) plus seismic coefficient of 0.10	0.57

c. Evaluation of Structural Stability

The analyses indicate that the factors of safety for the spillway are significantly below recommended levels. Due to the very low factors of safety for the spillway section, the non-overflow section of the dam was not analyzed.

Although the dam appears to be stable, the factors of safety are below acceptable values. If the dam were to fail during a storm or under other loading conditions, a significant amount of flooding would occur in downstream residential areas. Furthermore, failure would result in the loss of a public water supply reservoir.

A more detailed analysis is required to accurately evaluate the structural stability of the dam. Two features in its construction would provide stability and have not been taken into account in this analysis. One feature is the cut-off wall shown on the drawings as extending into bedrock under the entire length of the dam and the keying of the base of the dam into the bedrock. The second feature is the arched curvature of the dam which would resist lateral pressures from the reservoir. It is also known that the structure has withstood a reservoir level 4.1 feet above the spillway crest (6.4 feet below the top of the dam) without failure.

There is a lack of data concerning the concrete in the dam, the as-built construction of the cut-off wall, the physical properties of the bedrock, and seepage (uplift) conditions under the dam. Also, the condition of the downstream toe could not be evaluated during the visual inspection. Field investigations are required to obtain more information about the structure. This information should then be incorporated into a more detailed stability analysis. Based on this analysis, a design may be required to correct deficiencies in the stability of the dam.

d. Seismic Stability

This dam is located in Seismic Zone 1. However, a seismic stability analysis was performed in accordance with Corps of Engineer's Guidelines. The analysis is based on an assumed seismic coefficient of 0.10 and the reservoir level at the crest of the spillway. For the spillway section, the safety factor against sliding is 0.57. This low factor of safety further indicates that additional stability studies are needed.

SECTION 7: ASSESSMENT/RECOMMENDATIONS

7.1 ASSESSMENT

a. Safety

The Phase I inspection of Potter's Falls Dam revealed that the gunite surface is eroded in three areas on the downstream face and toe. A large bulge was also visible in the gunite on the downstream face as well as hairline cracks in other areas on the dam. Further deterioration will occur if the gunite is not repaired.

Outflows from all storms exceeding 31 percent of the Probable Maximum Flood will overtop the dam. During the one-half PMF, the abutments of the dam would be overtopped by 3.4 feet. The dam is a concrete structure that ties into bedrock at both abutments. However, a preliminary stability analysis of the spillway indicates that the factor of safety is less than 1.0 when the reservoir is at the one-half PMF level. A failure of the dam would increase the degree of flooding in downstream residential areas. Therefore, the spillway is assessed as seriously inadequate.

b. Adequacy of Information

The information which was available for the preparation of this report was limited. Drawings prepared during design of the dam were used for the stability analyses. No as-built drawings or detailed construction data is available.

c. Need for Additional Investigation

Investigation of the materials and as-built construction of the dam is required to conduct a detailed stability analysis. The investigation should develop accurate data on the construction of the cut-off wall, the nature and strength of concrete in the dam, the condition and strength of bedrock under the dam, and the uplift pressures acting on the base of the dam.

Additional hydraulic/hydrologic studies are required to more accurately determine reservoir levels that would occur during the full PMF. These levels are needed to evaluate the stability of the dam under maximum head conditions.

Additional investigation is required to determine the cause and extent of deterioration of the gunite covering the dam. This should include an inspection of the gunite when there is no flow over the spillway.

Evaluate the possibility that seepage is causing the gunite to spall. If this is the case, repairs such as sealing the upstream face or providing internal drainage may be necessary.

d. Urgency

The required investigations should be commenced within three months of the date of notification of the Owner. Within the same time, the gate on the low-level outlet should be exercised and maintained in good operating condition in the future.

Remedial measures deemed necessary as a result of the investigations and repairs required to correct other deficiencies which exist should be completed within 18 months of the date of final approval of this report.

7.2 RECOMMENDED MEASURES

- a. After the structural stability analysis has been completed, perform necessary remedial work.
- b. After the condition of the gunite has been evaluated, conduct necessary repairs.
- c. Visually monitor wet areas at both abutments of the dam. If flowing water or spalling bedrock is evident, conduct an investigation and correct the seepage.
- d. Repair the deteriorated concrete on the exterior of the gatehouse and around the water supply pipe downstream of the dam.
- e. Clear brush and trees along the upstream face of both abutments of the dam.
- f. Develop an emergency action plan for the notification and evacuation of downstream residents.

APPENDIX A

PHOTOGRAPHS




UPSTREAM VIEW OF DAM



TOP OF DAM, RIGHT ABUTMENT




CREST OF SPILLWAY AND LEFT ABUTMENT




**DOWNSTREAM TOE AT LEFT ABUTMENT (NOTE ERODED
GUNITE ON DOWNSTREAM FACE BETWEEN OUTLET AND
ABUTMENT)**




GATEHOUSE AND RIGHT ABUTMENT




**DOWNSTREAM TOE AT RIGHT ABUTMENT (NOTE BULGE ON
DOWNSTREAM FACE AND EROSION OF GUNITE AT TOE)**




INTERIOR OF GATEHOUSE



EXTERIOR OF GATEHOUSE



ERODED CONCRETE UNDER WATER MAIN IN WALL OF
DOWNSTREAM CHANNEL



EXPOSED SECTION OF WATER MAIN IN WALL OF
DOWNSTREAM CHANNEL

APPENDIX B

VISUAL INSPECTION CHECKLIST

VISUAL INSPECTION CHECKLIST1) Basic Data

a. General

Name of Dam Potter's Falls Dam / 60-Foot DamFed. I.D. # NY 378 DEC Dam No. 75A-717River Basin OswegoLocation: Town Ithaca County TompkinsStream Name Sixmile CreekTributary of Oswego RiverLatitude (N) 42° 25.0' Longitude (W) 76° 27.7'Type of Dam cyclopean concrete arch-gravity dam covered with guniteHazard Category highDate(s) of Inspection July 8, 1981Weather Conditions sunny + hotReservoir Level at Time of Inspection 705.1b. Inspection Personnel Reginald Barron, Carol Sweet

c. Persons Contacted (Including Address & Phone No.)

Mr. Philip Cox, City EngineerCity Hall, 108 Green StreetIthaca, New York 14850(607) 272-1716

d. History:

Date Constructed 1911 Date(s) Reconstructed 1939-gunite addedDesigner unknownConstructed By unknownOwner City of Ithaca - Dept. of Public Works - Sewer + Water Div.

2) Embankment

a. Characteristics

- (1) Embankment Material cyclopean concrete covered with gunite
- (2) Cutoff Type Key wall 10ft. thick into bedrock foundation
- (3) Impervious Core concrete
- (4) Internal Drainage System none shown on drawings
- (5) Miscellaneous _____

b. Crest

- (1) Vertical Alignment flat
- (2) Horizontal Alignment curved upstream (arch)
- (3) Surface Cracks hairline transverse cracks in gunite (oriented upstream → downstream)
- (4) Miscellaneous _____

c. Upstream Slope

- (1) Slope (Estimate) (V:H) vertical
- (2) Undesirable Growth or Debris, Animal Burrows brush and a few trees growing along upstream face at both abutments
- (3) Sloughing, Subsidence or Depressions none

(4) Slope Protection Covered with gunite

(5) Surface Cracks or Movement at Toe some hairline cracks - one long horizontal crack from gatehouse to right abutment

d. Downstream Slope

(1) Slope (Estimate - V:H) battered 1:1.44 (0.7 percent)

(2) Undesirable Growth or Debris, Animal Burrows minor weed growth at right abutment

(3) Sloughing, Subsidence or Depressions eroded gunite: 1) midway down slope at left abutment, 2) between outlet and left abutment, 3) downstream toe at right abutment. Also large bulge in gunite on downstream face near water supply pipe.

(4) Surface Cracks or Movement at Toe not visible due to spillway discharge and tailwater

(5) Seepage wet areas on bedrock at both abutments, but no visible flow

(6) External Drainage System (Ditches, Trenches; Blanket) none

(7) Condition Around Outlet Structure eroded gunite to left of outlet opening

(8) Seepage Beyond Toe not visible - submerged

e. Abutments - Embankment Contact

dam ties into bedrock at both abutments -
condition is satisfactory except for minor seepage noted above

93-15-3(9/80)

- (1) Erosion at Contact eroded granite at left abutment, midway
on downstream slope
- (2) Seepage Along Contact minor seepage (wet areas) at both
abutments - bedrock is intact

3) Drainage System

- a. Description of System none
- b. Condition of System
- c. Discharge from Drainage System

4) Instrumentation (Monumentation/Surveys, Observation Wells, Weirs,
Piezometers, Etc.) none

5) Reservoir

- a. Slopes steep wooded slopes - shallow bedrock
- b. Sedimentation conditions not visible, but siltation has been a problem in the past - Silt Dam built upstream to intercept sediment.
- c. Unusual Conditions Which Affect Dam _____

6) Area Downstream of Dam

- a. Downstream Hazard (No. of Homes, Highways, etc.) 2.5 miles to downtown Ithaca - little attenuation of flood flow in gorge downstream of dam.
- b. Seepage, Unusual Growth none in channel
- c. Evidence of Movement Beyond Toe of Dam none visible
- d. Condition of Downstream Channel steep bedrock walls, some loose blocks of rock in floor

7) Spillway(s) (Including Discharge Conveyance Channel)

- ogee weir near top of dam - discharge flows onto downstream face and into bedrock channel
- a. General condition is satisfactory except discharge is contributing to erosion of gunite on downstream face and toe of dam
- b. Condition of Service Spillway good - no visible cracks or voids - crest is clear of debris and obstructions

93-15-3(9/80)

Potter's Falls Dam 6
NY-378

c. Condition of Auxiliary Spillway none

d. Condition of Discharge Conveyance Channel good-shale bedrock
on sides and in bottom-some loose rock could be
picked up during flood flows

8) Reservoir Drain/Outlet

Type: Pipe ☒ Conduit _____ Other _____

Material: Concrete _____ Metal ☒ cast iron Other _____

Size: 72-inch dia. Length 45.5 feet

Invert Elevations: Entrance 647.0 Exit 647.0

Physical Condition (Describe): _____ Unobservable ☒

Material: _____

Joints: _____ Alignment _____

Structural Integrity: _____

Hydraulic Capability: _____

Means of Control: Gate ☒ Valve _____ Uncontrolled _____

Operation: Operable _____ Inoperable _____ Other not operated since 1959

Present Condition (Describe): submerged at the upstream
end of the outlet

9) Structural

- a. Concrete Surfaces concrete of dam covered with gunite which is eroded in places (see page 3) - also concrete on gatehouse is eroded at water line - concrete is eroded around water pipe downstream of dam
- b. Structural Cracking hairline cracks in gunite visible on top and upstream face of dam - also around bulge on downstream face
- c. Movement - Horizontal & Vertical Alignment (Settlement) none visible
- d. Junctions with Abutments or Embankments generally satisfactory but close inspection not possible due to lack of access
- e. Drains - Foundation, Joint, Face no drainage system visible
- f. Water Passages, Conduits, Sluices outlet not inspected - visible sections of water supply pipe are in satisfactory condition, no significant corrosion, joints tight
- g. Seepage or Leakage minor wet areas on bedrock at both abutments

93-15-3(9/80)

h. Joints - Construction, etc. none visible

i. Foundation N/A - bedrock

j. Abutments N/A - bedrock

k. Control Gates submerged - not inspected

l. Approach & Outlet Channels N/A - natural channels

m. Energy Dissipators (Plunge Pool, etc.) none

n. Intake Structures none

o. Stability

p. Miscellaneous

10) Appurtenant Structures (Power House, Lock, Gatehouse, Other)

a. Description and Condition

Gatehouse - foundation made of poured concrete,
superstructure is concrete blocks - concrete on
exterior is eroded at water line - minor vertical
cracks in superstructure

11) Operation Procedures (Lake Level Regulation):

Reservoir is regulated downstream at water treatment plant.

APPENDIX C

HYDROLOGIC/HYDRAULIC ENGINEERING
DATA AND COMPUTATIONS

Potter's Falls Dam
NY 378

CHECK LIST FOR DAMS
HYDROLOGIC AND HYDRAULIC
ENGINEERING DATA

1

AREA-CAPACITY DATA:

	<u>Elevation</u> (ft.)	<u>Surface Area</u> (acres)	<u>Storage Capacity</u> (acre-ft.)
1) Top of Dam	<u>715.5</u>	<u>47</u>	<u>1290</u>
2) Design High Water (Max. Design Pool)	<u>Unknown</u>	<u> </u>	<u> </u>
3) Auxiliary Spillway Crest	<u>N/A</u>	<u> </u>	<u> </u>
4) Pool Level with Flashboards	<u>N/A</u>	<u> </u>	<u> </u>
5) Service Spillway Crest	<u>705.0</u>	<u>47</u>	<u>800</u>

DISCHARGES

	<u>Volume</u> (cfs)
1) Average Daily	<u>Unknown</u>
2) Spillway @ Maximum High Water	<u>10,450</u>
3) Spillway @ Design High Water	<u>N/A</u>
4) Spillway @ Auxiliary Spillway Crest Elevation	<u>N/A</u>
5) Low Level Outlet (72" ϕ pipe, WS El. 705)	<u>1,044</u>
6) Total (of all facilities) @ Maximum High Water	<u>11,494</u>
7) Maximum Known Flood (reservoir El 709.1)	<u>3,240</u>
8) At Time of Inspection (reservoir El 705.1)	<u>± 10</u>

Potter's Falls Dam
NY 378 2

CREST:

ELEVATION: 715.5

Type: broad-crested; concrete with gunite surface

Width: 8.5 feet Length: 220 feet

Spillover service spillway

Location center of dam

SPILLWAY:

SERVICE

AUXILIARY

705.0

Elevation

ungated ogee weir

Type

100 feet

Width

Type of Control

✓

Uncontrolled

Controlled:

Type

(Flashboards; gate)

Number

Size/Length

Invert Material

Anticipated Length
of operating service

N/A

Chute Length

vertical upstream
face of dam

Height Between Spillway Crest
& Approach Channel Invert
(Weir Flow)

HYDROMETEROLOGICAL GAGES:

Type : none

Location: _____

Records:

Date - _____

Max. Reading - _____

FLOOD WATER CONTROL SYSTEM:

Warning System: none

Method of Controlled Releases (mechanisms):

72-inch ϕ low-level outlet-gate at upstream end-Inv. El. 647.0

DRAINAGE AREA: 45.6 sq.mi. (29,184 acres)

DRAINAGE BASIN RUNOFF CHARACTERISTICS:

Land Use - Type: relatively undeveloped w/open fields, woodland

Terrain - Relief: drainways-flat slopes; hillsides-steep slopes

Surface - Soil: glacial till over shallow bedrock

Runoff Potential (existing or planned extensive alterations to existing
(surface or subsurface conditions)

runoff will flow downstream to Sixmile Creek Reservoir

Potential Sedimentation problem areas (natural or man-made; present or future)

Sedimentation a problem in the past- Silt Dam built
upstream in 1925 to control sedimentation

Potential Backwater problem areas for levels at maximum storage capacity
including surcharge storage:

backwater will inundate Silt Dam located
about 0.4 mi. upstream of Ithaca Reservoir

Dikes - Floodwalls (overflow & non-overflow) - Low reaches along the
Reservoir perimeter:

Location: none

Elevation: _____

Reservoir:

Length @ Maximum Pool _____ ± 0.4 (Miles)

Length of Shoreline (@ Spillway Crest) _____ ± 1.2 (Miles)

BASE FLOW



Based on Fall Creek at Ithaca 04234000, average August 1980 flow from 126 sq mi is 42.2 cfs
 \therefore at Ithaca reservoir

\therefore at Ithaca reservoir

$$42.2 \text{ cfs} \left(\frac{45.6 \text{ sq mi}}{126 \text{ sq mi}} \right) = 15.3 \text{ cfs}$$

Using other dam inspection reports, $RTDR = 1.5$
and $QRCSN = 15\%$

STORAGE - Based on the assumption that the surface area will not significantly increase with changes in pool elevation above the spillway.



SPILLWAY The spillway is a concrete, ogee overflow weir.
 Discharge can be calculated using the equation

$$Q = CLH^{3/2}$$

where $C = 3.97$ → refer to "Open-Channel Flow" by Henderson.

LOW LEVEL OUTLET

Calculate discharge capacity of 72" ϕ outlet:

Water surface el 705 (spillway crest)
 Down stream invert el 647

Use the energy eqn to determine discharge

$$\frac{V_1^2}{2g} + z_1 = \frac{V_2^2}{2g} + z_2 + h_{L1-2}$$

$$705 = \frac{V_2^2}{2g} + 647 + \frac{V_2^2}{2g} \leq k$$

losses:

entrance $k = 1.0$
 exit $k = 0.5$

$$\text{Friction } \frac{E}{D} = \frac{Q}{6} \cdot .0017 \therefore f = .023$$

Substituting into eqn

$$58 = \frac{V^2}{2g} (1 + 1 + .5 + .023 \left(\frac{45.5}{6} \right))$$

$$58 = 2.6 \frac{Q^2}{2gA^2}$$


$$Q = .62 A \sqrt{2g(55)}$$

$$Q = .62 \pi (3)^2 (59.5)$$

$$Q = 1044 \text{ cfs}$$

DISCHARGE - DOWNSTREAM CHANNEL

Channel is most narrow directly downstream of the dam. Calculate the discharge for the tail water elevation.




$$Q = \frac{1.49}{n} A R^{2/3} S^{1/2}$$

where $S = \frac{645-600}{1600} = 0.0281$

ELEV	Y	A	WP	$R^{2/3}$	$\frac{1.49}{n} S^{1/2}$	Q cfs
645	0	~	~	~	~	~
655	10	864	103.8	4.1	6.24	22,100
670	25	2398	139.4	6.7	6.24	100,300
680	35	3580	163.2	7.8	6.24	174,360

Project NY COLE PH 1 DAM INSP Acct. No. 7594 Page of
 Subject POTTER'S FALLS DAM Comptd. By M. NOBLE Date 8-25-51
 Detail % PMF PASSING Ch'd. By Date

METCALF & EDDY, ENGINEERS



PREVIEW OF SEQUENCE OF STREAM NETWORK CALCULATIONS

RUNOFF HYDROGRAPH AT 1
ROUTE HYDROGRAPH TO 1
END OF NETWORK

.....
 FLOOD HYDROGRAPH PACKAGE (HEC-1)
 DAN SAFETY VERSION JULY 1978
 LAST MODIFICATION 25 SEP 78

RUN DATE: 25 AUG 1981

NEW YORK C. OF E. PHASE 1 DAN INSPECTION
 POTTERS FALLS DAM - ITHICA RESERVOIR
 FULL AND HALF PHF FLOOD ANALYSIS

JOB SPECIFICATION									
NO	NHB	NNIN	IDAY	IHR	IMIN	NETRC	IPLT	IPRT	INSTAB
100	0	30	0	0	0	0	0	0	0
	JOPER			NWT	LROPT	TRACE			
	5			0	0	0			

MULTI-PLAN ANALYSES TO BE PERFORMED

RTIOS= 0.25 0.35 0.50 1.00
 PLAN= 1 RTIO= 4 LRTIO= 1

SUB-AREA RUNOFF COMPUTATION

INFLOW HYDROGRAPH

ISTAQ	ICOMP	IECON	ITAPE	JPLT	JPRT	INANE	ISTAGE	IAUTO
1	0	0	0	0	0	1	0	0

HYDROGRAPH DATA

INHYD	IUNG	TAREA	SNAP	TESDA	TRSPC	RATIO	ISNOW	ISANE	LOCAL
1	45.60	0.0	45.60	0.0	0.0	0.0	0	1	0

PRECIP DATA

SPFE	PHS	R6	R12	R24	R48	R72	R96
0.0	21.00	93.00	106.00	117.00	124.00	0.0	0.0

TRSPC COMPUTED BY THE PROGRAM IS 0.847

LOSS DATA

LROPT	STERR	DLTR	RTIOL	ERAIN	STRKS	RTIOK	STRTL	CMSTL	ALSW	RTIWP
0	0.0	0.0	1.00	0.0	0.0	1.00	1.00	0.10	0.0	0.00

UNIT HYDROGRAPH DATA

TP= 7.70 CP=0.60 NTA= 0

RECESSION DATA

STRIO= 15.00 ORCSN= -0.15 RTIOR= 1.50
 APPROXIMATE CLARK COEFFICIENTS FROM GIVEN SNYDER CP AND TP ARE TC=16.50 AND R=15.30 INTERVALS

UNIT HYDROGRAPH 91 END-OF-PERIOD ORDINATES, LAG= 7.66 HOURS, CP= 0.60 VOL= 1.00									
39.	187.	302.	485.	688.	906.	1136.	1374.	1613.	1832.
2015.	2163.	2275.	2350.	2387.	2377.	2299.	2169.	2032.	1904.
1784.	1672.	1566.	1468.	1375.	1289.	1208.	1132.	1060.	994.

931.
486.
253.

872.
455.
238.

817.
427.
223.

766.
400.
209.

718.
374.
195.

672.
351.
183.

630.
329.
172.

590.
308.
161.

553.
289.
151.

518.
271.
141.

END-OF-PERIOD FLOW									
NO.DA	HR.MN	PERIOD	RAIN	EXCS	LOSS	COMP Q	NO.DA	HR.MN	PERIOD
101	0.30	1	0.00	0.00	0.00	14.	102	96.	51
101	1.00	2	0.00	0.00	0.00	14.	102	2.00	52
101	1.30	3	0.00	0.00	0.00	13.	102	2.30	53
101	2.00	4	0.00	0.00	0.00	13.	102	3.00	54
101	2.30	5	0.00	0.00	0.00	12.	102	3.30	55
101	3.00	6	0.00	0.00	0.00	12.	102	4.00	56
101	3.30	7	0.00	0.00	0.00	11.	102	4.30	57
101	4.00	8	0.00	0.00	0.00	11.	102	5.00	58
101	4.30	9	0.00	0.00	0.00	10.	102	5.30	59
101	5.00	10	0.00	0.00	0.00	10.	102	6.00	60
101	5.30	11	0.00	0.00	0.00	10.	102	6.30	61
101	6.00	12	0.00	0.00	0.00	9.	102	7.00	62
101	6.30	13	0.01	0.00	0.01	9.	102	7.30	63
101	7.00	14	0.01	0.00	0.01	9.	102	8.00	64
101	7.30	15	0.01	0.00	0.01	8.	102	8.30	65
101	8.00	16	0.01	0.00	0.01	8.	102	9.00	66
101	8.30	17	0.01	0.00	0.01	8.	102	9.30	67
101	9.00	18	0.01	0.00	0.01	7.	102	10.00	68
101	9.30	19	0.01	0.00	0.01	7.	102	10.30	69
101	10.00	20	0.01	0.00	0.01	7.	102	11.00	70
101	10.30	21	0.01	0.00	0.01	7.	102	11.30	71
101	11.00	22	0.01	0.00	0.01	7.	102	12.00	72
101	11.30	23	0.01	0.00	0.01	6.	102	12.30	73
101	12.00	24	0.01	0.00	0.01	6.	102	13.00	74
101	12.30	25	0.05	0.00	0.05	6.	102	13.30	75
101	13.00	26	0.05	0.00	0.05	6.	102	14.00	76
101	13.30	27	0.06	0.00	0.06	6.	102	14.30	77
101	14.00	28	0.06	0.00	0.06	6.	102	15.00	78
101	14.30	29	0.07	0.00	0.07	5.	102	15.30	79
101	15.00	30	0.07	0.00	0.07	5.	102	16.00	80
101	15.30	31	0.09	0.00	0.09	5.	102	16.30	81
101	16.00	32	0.29	0.00	0.29	5.	102	17.00	82
101	16.30	33	0.07	0.00	0.07	5.	102	17.30	83
101	17.00	34	0.07	0.02	0.05	6.	102	18.00	84
101	17.30	35	0.05	0.00	0.05	9.	102	18.30	85
101	18.00	36	0.05	0.00	0.05	12.	102	19.00	86
101	18.30	37	0.01	0.00	0.01	17.	102	19.30	87
101	19.00	38	0.01	0.00	0.01	23.	102	20.00	88
101	19.30	39	0.01	0.00	0.01	29.	102	20.30	89
101	20.00	40	0.01	0.00	0.01	35.	102	21.00	90
101	20.30	41	0.01	0.00	0.01	41.	102	21.30	91
101	21.00	42	0.01	0.00	0.01	48.	102	22.00	92
101	21.30	43	0.01	0.00	0.01	54.	102	22.30	93
101	22.00	44	0.01	0.00	0.01	60.	102	23.00	94
101	22.30	45	0.01	0.00	0.01	64.	102	23.30	95
101	23.00	46	0.01	0.00	0.01	67.	103	0.0	96
101	23.30	47	0.01	0.00	0.01	70.	103	0.30	97
102	0.0	48	0.01	0.00	0.01	71.	103	1.00	98
102	0.30	49	0.07	0.02	0.05	72.	103	1.30	99
102	1.00	50	0.07	0.02	0.05	72.	103	2.00	100
SUN 22.06 16.45 3.61 635104.									

74.
38.
20.

84.
44.
23.

90.
47.
24.

96.
50.
26.

102.
53.
28.

109.
57.
30.

116.
61.
32.

124.
65.
34.

132.
69.
36.
19.

132.
69.
36.
19.

(560.)(469.)(92.)(1798.17)

PEAK 6-HOUR 24-HOUR 72-HOUR TOTAL VOLUME

CFS 37698. 34856. 12901. 6204. 620394.
 CHS 1067. 987. 365. 176. 17568.
 INCHES 7.11 10.53 10.55
 HH 180.61 267.39 267.88 267.88
 AC-FT 17284. 25589. 25636. 25636.
 THOUS CU H 21319. 31564. 31622. 31622.

HYDROGRAPH AT STA 1 FOR PLAN 1, RTIO 1
 3. 3. 3. 3. 3.
 2. 2. 2. 2. 2.
 2. 2. 1. 1. 1.
 1. 2. 3. 4. 6.
 1. 15. 17. 17. 18.
 19. 21. 27. 32. 43.
 67. 99. 153. 190. 284.
 477. 551. 868. 1030. 1232. 1477.
 2677. 3283. 4688. 5486. 6205. 6983. 7632. 8234. 8720.
 9083. 9318. 9425. 9265. 8996. 8628. 8216. 7786. 7351.
 PEAK 6-HOUR 24-HOUR 72-HOUR TOTAL VOLUME
 9425. 8714. 3225. 1551. 155098.
 267. 247. 91. 44. 4392.
 INCHES 1.78 2.63 2.64 2.64 2.64
 HH 45.15 66.85 66.97 66.97 66.97
 AC-FT 4321. 6397. 6409. 6409. 6409.
 THOUS CU H 5330. 7891. 7905. 7905. 7905.

HYDROGRAPH AT STA 1 FOR PLAN 1, RTIO 2
 5. 5. 4. 4. 4.
 3. 3. 3. 3. 3.
 2. 2. 2. 2. 2.
 2. 2. 4. 6. 8.
 18. 19. 21. 22. 24. 25. 25.
 26. 27. 30. 33. 38. 44. 52. 61.
 94. 113. 138. 172. 215. 266. 327. 398.
 667. 771. 888. 1033. 1215. 1443. 1724. 2068.
 3788. 4596. 5543. 6563. 7624. 8687. 9720. 10685.
 12716. 13045. 13194. 13167. 12970. 12594. 12079. 11502.
 PEAK 6-HOUR 24-HOUR 72-HOUR TOTAL VOLUME
 13194. 12199. 4515. 2171. 217138.
 374. 345. 128. 61. 6149.
 INCHES 2.49 3.68 3.69 3.69 3.69
 HH 63.21 93.59 93.76 93.76 93.76
 AC-FT 6049. 8956. 8973. 8973. 8973.
 THOUS CU H 7462. 11047. 11068. 11068. 11068.

HYDROGRAPH AT STA 1 FOR PLAN 1, RTIO 3
 7. 7. 6. 6. 6.
 5. 4. 4. 4. 4.
 3. 3. 3. 3. 3.
 3. 3. 3. 6. 9.
 27. 30. 32. 34. 35. 36. 36.
 37. 42. 47. 54. 63. 74. 87.
 PEAK 6-HOUR 24-HOUR 72-HOUR TOTAL VOLUME
 13194. 12199. 4515. 2171. 217138.
 374. 345. 128. 61. 6149.
 INCHES 2.49 3.68 3.69 3.69 3.69
 HH 63.21 93.59 93.76 93.76 93.76
 AC-FT 6049. 8956. 8973. 8973. 8973.
 THOUS CU H 7462. 11047. 11068. 11068. 11068.

135.
953.
5354.

161.
1102.
6566.

198.
1269.
7918.

246.
1475.
9375.

307.
1735.
10891.

380.
2061.
12411.

467.
2463.
13885.

569.
2955.
15264.

685.
3551.
16468.

813.
4333.
17441.

705.00	800.	0.	0.0	0.	1044.	0.0	1044.	1044.
710.00	1035.	3419.	648.3	3419.	1090.	645.5	1090.	4509.
715.00	1270.	9572.	651.7	9572.	1135.	645.5	1135.	10707.

720.00 1505. 17406. 655.0 17406. 1177. 645.5 1177. 18583. 18583.
 725.00 1740. 26522. 658.3 26522. 1219. 645.6 1219. 27741. 27741.
 730.00 1975. 36680. 661.7 36680. 1259. 645.6 1259. 37938. 37938.
 800.00 4090. 231665. 708.4 231665. 1723. 645.8 1723. 233389. 233389.

DAM DATA
 TPEL COOD EXPD DAMVID
 715.5 2.7 1.5 120.

STATION 1, PLAN 1, RATIO 1

ITERATIVE SOLUTION DID NOT CONVERGE 52 1 0.0 6.500D+02 -5.385D+01 6.501D+02 8.794D+01 CONVERGENCE DOES NOT
 OCCUR WHEN RESERVOIR
 RUNS OUT OF WATER-
 ITERATIVE SOLUTION DID NOT CONVERGE 54 1 0.0 6.500D+02 -5.341D+01 6.501D+02 8.787D+01 (LWE TO LOW LEVEL OUTLET)
 ITERATIVE SOLUTION DID NOT CONVERGE 61 1 0.0 6.500D+02 5.274D+01 6.500D+02 -8.612D+01

END-OF-PERIOD HYDROGRAPH ORDINATES

OUTFLOW	756	717	679	644	610
989.	937.	888.	842.	798.	756.
578.	548.	519.	492.	466.	442.
338.	320.	304.	288.	273.	258.
198.	187.	178.	168.	160.	151.
117.	112.	106.	102.	97.	93.
0.	88.	0.	88.	0.	87.
0.	88.	88.	89.	92.	96.
150.	169.	192.	218.	248.	285.
628.	751.	902.	1381.	3102.	4374.
8702.	9054.	9278.	9375.	9347.	9194.
					8924.
					8570.

STORAGE

STORAGE	580	549	521	493	468
758.	718.	681.	645.	612.	580.
443.	420.	398.	377.	357.	339.
259.	246.	233.	221.	209.	198.
152.	144.	136.	129.	122.	116.
90.	86.	82.	78.	74.	71.
67.	67.	66.	67.	67.	67.
66.	67.	67.	68.	70.	73.
115.	130.	147.	167.	190.	219.
481.	576.	691.	823.	940.	1026.
1194.	1207.	1216.	1219.	1218.	1213.
					1202.
					1189.

STAGE

STAGE	688.5	686.2	684.0	682.0	680.1
701.9	698.9	696.1	693.4	690.9	688.5
678.2	676.5	674.8	673.3	671.8	670.4
664.4	663.4	662.5	661.5	660.7	659.9
656.4	655.8	655.2	654.7	654.2	653.7
651.7	651.4	651.1	650.8	650.6	650.3
650.0	650.1	650.0	650.1	650.0	650.0
650.0	650.0	650.1	650.1	650.3	650.5
653.6	654.7	656.0	657.5	659.3	661.4
681.1	688.2	696.9	705.5	708.0	709.8
713.4	713.7	713.8	713.9	713.9	713.8
					713.6
					711.9
					711.9
					712.5
					713.0
					712.6

PEAK OUTFLOW IS 9375. AT TIME 07.00 HOURS

PEAK
 9375.
 265.
 CFS
 CMS
 INCHES
 AC-FT
 THOUS CU H

6-HOUR
 8647.
 2676.
 76.
 2.18
 55.47
 5308.
 6547.
 7417.
 72-HOUR
 1455.
 41.
 2.47
 62.83
 6013.
 7417.
 TOTAL VOLUME
 145520.
 4121.
 2.47
 62.83
 6013.
 7417.

STATION 1, PLAN 1, RATIO 2

CONVERGENCE DOES NOT
 OCCUR WHEN RESERVING
 IS WITHOUT WATER (DUE
 TO LOW LEVEL OUTLET)

ITERATIVE SOLUTION DID NOT CONVERGE	50	1	0.0	6.500D+02	-5.359D+01	6.501D+02	8.816D+01
ITERATIVE SOLUTION DID NOT CONVERGE	55	1	0.0	6.500D+02	5.399D+01	6.499D+02	-8.594D+01
ITERATIVE SOLUTION DID NOT CONVERGE	56	1	0.0	6.500D+02	-5.359D+01	6.501D+02	8.816D+01
ITERATIVE SOLUTION DID NOT CONVERGE	57	1	0.0	6.500D+02	5.406D+01	6.499D+02	-8.606D+01
ITERATIVE SOLUTION DID NOT CONVERGE	59	1	0.0	6.500D+02	5.399D+01	6.499D+02	-8.595D+01

END-OF-PERIOD HYDROGRAPH ORDINATES

		OUTFLOW		STORAGE		STAGE	
989.	937.	888.	842.	646.	681.	696.1	701.9
579.	548.	520.	493.	398.	398.	674.9	678.3
339.	321.	304.	288.	221.	233.	663.5	664.5
198.	188.	178.	169.	130.	137.	655.2	656.4
118.	113.	108.	103.	79.	83.	651.2	651.8
0.	0.	0.	0.	66.	67.	650.0	650.0
88.	89.	90.	94.	72.	69.	650.0	650.0
189.	217.	249.	287.	220.	191.	650.0	650.0
867.	1040.	2894.	4370.	1026.	926.	650.0	650.0
12377.	12842.	13102.	13176.	1336.	1334.	650.0	650.0
758.	719.	681.	646.	646.	681.	696.1	701.9
444.	420.	398.	378.	378.	398.	674.9	678.3
260.	246.	233.	221.	221.	233.	663.5	664.5
152.	144.	137.	130.	130.	137.	655.2	656.4
91.	87.	83.	79.	79.	83.	651.2	651.8
67.	67.	67.	66.	66.	67.	650.0	650.0
67.	68.	69.	72.	72.	69.	650.0	650.0
145.	166.	191.	220.	220.	191.	650.0	650.0
664.	797.	926.	1026.	1026.	926.	650.0	650.0
1317.	1328.	1334.	1336.	1336.	1334.	650.0	650.0
758.	719.	681.	646.	646.	681.	696.1	701.9
444.	420.	398.	378.	378.	398.	674.9	678.3
260.	246.	233.	221.	221.	233.	663.5	664.5
152.	144.	137.	130.	130.	137.	655.2	656.4
91.	87.	83.	79.	79.	83.	651.2	651.8
67.	67.	67.	66.	66.	67.	650.0	650.0
67.	68.	69.	72.	72.	69.	650.0	650.0
145.	166.	191.	220.	220.	191.	650.0	650.0
664.	797.	926.	1026.	1026.	926.	650.0	650.0
1317.	1328.	1334.	1336.	1336.	1334.	650.0	650.0
758.	719.	681.	646.	646.	681.	696.1	701.9
444.	420.	398.	378.	378.	398.	674.9	678.3
260.	246.	233.	221.	221.	233.	663.5	664.5
152.	144.	137.	130.	130.	137.	655.2	656.4
91.	87.	83.	79.	79.	83.	651.2	651.8
67.	67.	67.	66.	66.	67.	650.0	650.0
67.	68.	69.	72.	72.	69.	650.0	650.0
145.	166.	191.	220.	220.	191.	650.0	650.0
664.	797.	926.	1026.	1026.	926.	650.0	650.0
1317.	1328.	1334.	1336.	1336.	1334.	650.0	650.0

650.0	650.1	650.2	650.4	650.7	651.1	651.7	652.4	653.4	654.5
655.9	657.5	659.3	661.5	664.0	667.0	670.6	675.0	680.3	686.8
694.8	704.8	707.7	709.8	711.4	712.5	713.4	714.2	715.0	715.6

716.0 716.2 716.4 716.6 716.8 716.0 716.2 716.4 716.6 716.8 715.0

PEAK OUTFLOW IS 13176. AT TIME 47.00 HOURS

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
13176.	12127.	3907.	2047.	204691.
373.	343.	111.	58.	5796.
	2.47	3.19	3.48	
	62.83	80.98	88.38	
	6073.	7750.	8458.	
	7417.	9559.	10433.	

THOUS CU M

STATION 1, PLAN 1, RATIO 3

ITERATIVE SOLUTION DID NOT CONVERGE 50 1 0.0 6.500D+02 5.274D+01 6.500D+02 -8.612D+01

ITERATIVE SOLUTION DID NOT CONVERGE 51 1 0.0 6.500D+02 -5.355D+01 6.507D+02 8.809D+01

DOE TO LOW LEVEL
RECEIVED DRAINAGE
COMPLETEN AT 1.50.21

END-OF-PERIOD HYDROGRAPH ORDINATES

		OUTFLOW			
989.	938.	889.	842.	799.	757.
579.	549.	521.	494.	468.	443.
340.	322.	305.	289.	274.	260.
199.	189.	179.	170.	161.	153.
120.	115.	110.	106.	102.	98.
88.	87.	87.	87.	87.	87.
91.	94.	98.	105.	114.	126.
250.	291.	338.	392.	456.	532.
2668.	4206.	6193.	7924.	9483.	11061.
17823.	18420.	18755.	18833.	18663.	18246.
					17605.
					16827.
					185.
					215.
					864.
					1026.
					15853.
					15993.
					15140.

STORAGE

758.	719.	681.	646.	612.	580.	550.	521.	494.	469.
444.	421.	399.	378.	359.	340.	322.	306.	290.	275.
260.	247.	234.	222.	210.	199.	189.	179.	170.	161.
153.	145.	137.	130.	124.	117.	111.	106.	101.	96.
92.	88.	84.	81.	78.	75.	73.	70.	68.	66.
68.	67.	67.	67.	67.	67.	67.	67.	67.	68.
69.	72.	75.	80.	87.	96.	108.	123.	142.	165.
192.	223.	259.	301.	349.	407.	477.	561.	662.	786.
910.	1014.	1099.	1164.	1228.	1281.	1329.	1365.	1394.	1416.
1433.	1444.	1451.	1452.	1449.	1441.	1429.	1413.	1396.	1379.

STAGE

701.9	698.9	696.1	693.4	690.9	688.5	686.3	684.1	682.1	680.1
678.3	676.6	674.9	673.4	671.9	670.5	669.2	667.9	666.7	665.6
664.5	663.5	662.5	661.6	660.8	660.0	659.2	658.4	657.7	657.1
656.5	655.9	655.3	654.8	654.3	653.8	653.4	652.9	652.6	652.2
651.9	651.6	651.3	651.1	650.9	650.7	650.5	650.3	650.1	650.0
650.1	650.0	650.0	650.0	650.0	650.0	650.0	650.0	650.0	650.1
650.2	650.4	650.6	651.0	651.5	652.2	653.1	654.3	655.7	657.4
659.4	661.7	664.4	667.5	671.2	675.6	680.8	687.1	694.7	704.0
707.3	709.6	711.4	712.8	714.0	715.2	716.3	717.0	717.6	718.1
718.5	718.7	718.8	718.9	718.8	718.6	718.4	718.0	717.7	717.3

PEAK OUTFLOW IS 18833. AT TIME 47.00 HOURS

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
18833.	17400.	5789.	2952.	295221.
533.	493.	164.	84.	8360.
	3.55	4.72	5.02	
	90.16	119.99	127.48	127.48
	8628.	11483.	12199.	12199.
	10643.	14164.	15048.	15048.

CFS
CMS
INCHES
MM
AC-FT
THOUS CU M

STATION 1. PLAN 1, RATIO 4
END-OF-PERIOD HYDROGRAPH ORDINATES

OUTFLOW	
990.	800.
582.	471.
343.	277.
202.	164.
126.	112.
100.	98.
121.	131.
465.	549.
8945.	11098.
35856.	36977.

STORAGE	
759.	613.
466.	361.
263.	213.
155.	126.
96.	86.
77.	75.
93.	137.
357.	677.
1203.	1422.
1721.	1736.

STAGE	
701.9	691.0
678.5	672.1
664.7	661.0
656.6	654.9
652.2	651.4
650.8	650.6
652.0	653.2
671.8	682.1
713.6	716.9
724.6	725.1

PEAK OUTFLOW IS 37675. AT TIME 47.00 HOURS

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
37675.	34840.	12115.	5992.	599171.
1067.	987.	343.	170.	16967.
	7.11	9.89	10.19	
	180.53	251.10	258.72	258.72
	17276.	24030.	24759.	24759.

CFS
CMS
INCHES
MM
AC-FT

THOUS CU M

21310.

29640.

30540.

30540.

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION	STATION	AREA	PLAN	RATIOS APPLIED TO FLOWS			
				RATIO 1	RATIO 2	RATIO 3	RATIO 4
				0.25	0.35	0.50	1.00
HYDROGRAPH AT	1	45.60	1	9425.	13194.	18849.	37698.
	(118.10)	(266.87)	(373.62)	(533.75)	(1067.49)
ROUTED TO	1	45.60	1	9375.	13176.	18833.	37675.
	(118.10)	(265.46)	(373.11)	(533.29)	(1066.84)

PLAN 1

ELEVATION
STORAGE
OUTFLOW


INITIAL VALUE	SPILLWAY CREST	TOP OF DAM
705.00	705.00	715.50
800.	800.	1293.
1044.	1044.	11498.

RATIO OF PHF	MAXIMUM RESERVOIR W.S.ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
0.25	713.93	0.0	1219.	9375.	0.0	47.00	0.0
0.35	716.39	0.89	1336.	13176.	4.50	47.00	0.0
0.58	718.88	3.38	1452.	18833.	7.00	47.00	0.0
1.00	725.13	9.63	1746.	37675.	9.00	47.00	0.0

APPENDIX D
STRUCTURAL STABILITY

Project Phase I - N.Y. Acct. No. 7594 Page 1 of 5
 Subject Potters Falls Dam Comptd. By EMG Date 7/29/81
 Detail Stability Anal Ck'd. By CFS Date _____

NONREPRODUCIBLE GRID FORM 143



<u>Segment</u>	<u>Area</u>	<u>Centroid to Pt. C</u>
①	$9 \times 59 = 531$	45.5
②	$\frac{1}{2}(41) 59 = 1210$	27.3

Project Phase I - NY Dams Acct. No. 7594 Page 2 of 5
Subject Potters Falls Dam Comptd. By Sweet Date _____
Detail Stability Analysis Ck'd. By EMG Date _____

Analysis Conditions

1. Normal conditions:
water surface at crest of spillway
2. Winter conditions:
level at crest of spillway with
ice 2 feet thick
3. Flood Conditions:
water surface at top
of dam.
4. Normal Conditions with seismic
coefficient of 0.1

SPILLWAY SECTION

Potters Fall Dam

STABILITY ANALYSIS PROGRAM - WORK SHEET

INPUT ENTRY

ANALYSIS CONDITION

		1	2	3	4	5
Unit Weight of Dam (K/ft ³)	0	0.14	0.14	0.14	0.14	
Area of Segment No. 1 (ft ²)	1	531	531	531	531	
Distance from Center of Gravity of Segment No. 1 to Downstream Toe (ft)	2	45.5	45.5	45.5	45.5	
Area of Segment No. 2 (ft ²)	3	1210	1210	1210	1210	
Distance from Center of Gravity of Segment No. 2 to Downstream Toe (ft)	4	27.3	27.3	27.3	27.3	
Area of Segment No. 3 (ft ²)	5	—	—	—	—	
Distance from Center of Gravity of Segment No. 3 to Downstream Toe (ft)	6	—	—	—	—	
Base Width of Dam (Total) (ft)	7	50	50	50	50	
Height of Dam (ft)	8	59	59	59	59	
Ice Loading (K/L ft.)	9	—	5	—	—	
Coefficient of Sliding	10	0.55	0.55	0.55	0.55	
Unit Weight of Soil (K/ft ³) (deduct 18)	11	—	—	—	—	
Active Soil Coefficient - Ka	12	—	—	—	—	
Passive Soil Coefficient - Kp	13	—	—	—	—	
Height of Water over Top of Dam or Spillway (ft)	14	—	—	10.5'	—	
Height of Soil for Active Pressure (ft)	15	—	—	—	—	
Height of Soil for Passive Pressure (ft)	16	—	—	—	—	
Height of Water in Tailrace Channel (ft)	17	—	—	—	—	
Weight of Water (K/ft ³)	18	.0625	.0625	.0625	.0625	
Area of Segment No. 4 (ft ²)	19	—	—	—	—	
Distance from Center of Gravity of Segment No. 4 to Downstream Toe (ft)	20	—	—	—	—	
Height of Ice Load or Active Water (ft) (does not include 14)	46	59'	59'	69.5	59'	
Seismic Coefficient (g)	50	—	—	—	0.1	
RESULTS OF ANALYSIS						
Factor of Safety vs. Overturning						
Distance From Toe to Resultant						
Factor of Safety vs. Sliding		0.76	0.73	0.49	0.57	

Project Phase I Acct. No. 7599 Page 4 of 5
 Subject Potters Falls Comptd. By EMG Date 7/29/81
 Detail Stab. Anal. Ckd. By CFS Date

Condition 1

Uplift

$$\frac{(59)(.0625)(50)}{2} = 92.2 \text{ kips}$$

Total Wt. (Area 1 + Area 2)

$$(531 + 1210)(.14) = 243.7 \text{ kips}$$

Total Net Force

$$= 243.7 - 92.2 = 151.5 \text{ kips}$$

Sliding Resistance

$$= (151.5)(.55) = 83.3 \text{ kips}$$

Water Pressure on Face Dam

$$= \left(\frac{1}{2}\right)(59)^2(.0625) = 108.8 \text{ kips}$$

$$F.S. = \frac{83.3}{108.8} = 0.76$$

Condition 2

$$F.S. = \frac{83.3}{108.8 + 5.0} = 0.73$$

Project Phase I Acct. No. 7594 Page 5 of 5
 Subject Potters Falls Comptd. By EMG Date 7/29/81
 Detail Stabil. Ansl. Ch'd. By CFS Date

Condition 3

Uplift

$$\frac{(69.5)(.0625)(50)}{2} = 108.6$$

Total Net Force

$$243.7 - 108.6 = 135.1$$

Sliding Resist.

$$= 135.1 (.55) = 74.3$$

Water Pressure

$$= \left(\frac{1}{2}\right)(69.5)^2(.0625) = 150.9$$

$$F.S. = \frac{74.3}{150.9} = 0.49$$

Condition 4 - Earthquake (0.1g)

$$W_H = (243.7)(.1) = 24.4 \text{ kips (Horizontal Force)}$$

$$\text{Dynamic water pressure} = \frac{1}{12}(4^2)(80)(.1)$$

$$= \frac{1}{12}(59)^2(.0625)(.1) = 12.7 \text{ kips}$$

$$F.S. = \frac{83.3}{108.6 + 24.4 + 12.7} = 0.57$$

145.7

APPENDIX E

REFERENCES

LIST OF REFERENCES

GENERAL

Harris, Dorothy, History of Ithaca's Water & Sewer Systems, Reprinted August 1956.

University of the State of New York, Geologic Map of New York, Map and Chart Series No. 5, 1962.

University of the State of New York, Geology of New York, Education Leaflet 20, Reprinted 1972.

HYDRAULICS

Chow, Ven Te, 1959, Open Channel Hydraulics, McGraw Hill.

King, H.W. and E.F. Brater, 1963, Handbook of Hydraulics, 5th Edition, McGraw-Hill

U.S. Army Corps of Engineers:

HEC-1 Flood Hydrograph Package - Dam Safety Version, September 1978.

Engineering Manual 1110-2-1405; Flood-Hydrograph Analyses and Computations, August 1959.

U.S. Department of Agriculture, Soil Conservation Service:

National Engineering Handbook; Section 4 - Hydrology, August 1972.

U.S. Department of Commerce; Weather Bureau:

Hydrometeorological Report No. 33; Seasonal Variation of the Probable Maximum Precipitation East of the 105th Meridian for Areas from 10 to 1,000 Square Miles and Durations of 6, 12, 24, and 48 Hours, April 1956.

U.S. Department of the Interior:

BUREC, 1977, Design of Small Dams, 2nd Ed. (rev. reprint).

USGS, 1980, Water Resources Data For New York, Western New York, USGS Water Data Report NY-80-3.

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION

DAM INSPECTION REPORT
(By Visual Inspection)

CITY OF ITHACA

Dam Number	River Basin	Town	County	Hazard Class*	Date & Inspector
717	Oswego	ITHACA	Tompkins	C	11/22/76 B.C.

Type of Construction

- ☐ Earth w/concrete spillway
☐ Earth w/drop inlet pipe
☐ Earth w/stone or riprap spillway
☒ Concrete
☐ Stone
☐ Timber

Use

- ☒ Water Supply
☐ Power
☐ Recreation
☐ Fish and Wildlife
☐ Farm Pond
☐ No Apparent Use-Abandoned

Estimated Impoundment Size

- ☐ 1-5 acres
☐ 5-10 acres
☒ Over 10 acres (15 ACRES)

Estimated Height of Dam above Streambed

- ☐ Under 10 feet
☐ 10-25 feet
☒ Over 25 feet 64 FT.

260,000,000 gals.

Condition of Spillway

- ☒ Service satisfactory
☐ In need of repair or maintenance
☐ Auxiliary satisfactory
☐ In need of repair or maintenance

Explain: With 4" of water going over spillway there are some surface cracks
Should reinspect at low flows to see if there are any bad cracks or leaks

Condition of Non-Overflow Section

- ☒ Satisfactory
☐ In need of repair or maintenance Explain: _____

Condition of Mechanical Equipment

- ☒ Satisfactory
☐ In need of repair or maintenance Explain: _____

Reinspected 7/30/79 KOH
OK

Evaluation (From Visual Inspection)

- ☐ No defects observed beyond normal maintenance
☐ Repairs required beyond normal maintenance


*Explain Hazard Class, if Necessary Reinspect Summer '79 during low flows
"C" HAZARD. Lowland business & homes in ITHACA would be flooded if dam went out

Potters Falls Dam.

Fill out a form as complete as possible for each dam in your district and send to State Conservation Commission, Albany, N. Y.

1. Name and address of owners. Ithaca Water Works Co. Ithaca N.Y.
2. Date of construction June 1913.
3. Uses of impounded water. City Water Main.
4. Character of foundation bed. Rock.
5. Material of waste spill. Concrete.
6. Length of waste and depth below dam. Waste 100ft, Depth below dam 6ft.
7. Total length of dam including waste. 130ft.
8. Material of dam. Concrete and Steel.
9. Discharges, size and location. Iron pipe at bottom of Dam 3ft. in diameter.
Two miles to City Filter plant.

Below sketch section of waste and section of dam, with greatest heights and top thickness and bottom thickness. On opposite side sketch general plan of dam and give distance from a bridge or from a tributary stream.



(Signature, address and date.)

John B. Vann
Ithaca N.Y.
Feb 12th 1913

717

October 31,,1911.

In re Potters Falls Dam
#722 Oswego-Seneca Watershed.

Donald F. McLeod, Esq.,
City Engineer,
Ithaca, N. Y.

717 *Oswego*

Dear Sir:-

I visited the above dam on October 26th and it appeared to be of good proportions and run well into the rock at the side. I regretted, however, to see it built up at an angle of about 45 degrees for the entire length instead of keeping the top of work horizontal. The sand was not a good quality, one-half being composed of 3/8 to 3/4 inch stones and the other half of poorly washed screenings. I suggest that this be washed better and a test be made to be sure that the voids are filled; if not additional sand should be added.

I further suggest to bond each day's work to the preceding days by longitudinal and vertical grooves formed by 6 x 6 joist smoothed and battered built into the concrete.

We should like to receive, for the files of this office, plans, sections and elevations of this dam and of all other dams owned or controlled by the City.

Very truly yours,

Inspector of Dams and Docks.

WCK/C.

Oswego - Ithaca

Potters Falls dam situated on Six Mile Creek.

Used for water supply purposes for the City of Ithaca.

Built of reinforced concrete 9 feet top width, 46 feet bottom width, 64 feet high, 197 feet long.


Inspected October 26, 1911.

Concrete work about ^{half} finished.

Comment:- The concrete work was built up at about an angle of 43 degrees for the entire length of the dam instead of building same up in horizontal layers. Sand was not a good quality 1/2 being composed of 3/8 to 3/4 inch stones and the other half of poorly washed screenings; the portions of concrete being 2 of cement, 4 of sand and 7 of broken stone about 2 1/2 inch size.


As at present mixed the sand would be better washed. Where necessary to fill the voids a large proportion of sand should be added. Also there should be better bonding between the different day's work longitudinally - horizontally and vertically by grooves.

APPENDIX G
DRAWINGS




SCALE 1:250,000
 5 0 5 MILES

VICINITY MAP
 POTTER'S FALLS DAM
 ID No. NY 378



Alterations from Contract Drawings are in Red



POTTER'S FALLS DAM
Ithaca, N.Y. Water Supply
FINISHED CONCRETE PLAN


Scale: 1 inch = 100 feet

Wm. L. J. McLeod, Civil Engineer.
August, 1910.

August, 1910

0-0

INDEX



100'-0"

Measured on Chord.

Crest of Spillway, Elev. 705.0', 4'-0" in front of Sect

Dotted Steps show Foundation
beyond Cut off Wall.

24" Discharge, Elev. Center 666.0'

Gale House Canal,
Elev. Bottom 664.0'

Present Rock
Surface

Opening for
Sluice Gate,
size depends on type used.


72" Blow off,
Elev. Center, 650.0'

Elev. 641.0'

5'-0" 5'-0" 5'-0"

East Side

B-B



East Side

Surface


Section

24" Discharge Pipe.

Present

12

1



POTTER'S FALLS DAM

Ithaca, N.Y. Water Supply


SECTIONS B-B AND C-C

Scale: 1 in. = 10 ft.

Donald S. McLeod, City Engineer.

August, 1910.

O-12



AD-A109 966

METCALF AND EDDY OF NEW YORK INC NY

F/G 13/13

NATIONAL DAM SAFETY PROGRAM. POTTERS FALLS DAM (INVENTORY NUMBE--ETC(U)

SEP 81 G P FULTON

DACW51-81-C-0044

UNCLASSIFIED

NL

2

4110
13/13/81


END

DATE

FILED


02-82

DTIC




MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A

Section 2-2




Section




Section 4-4

1 1/2" W.I. Round Bar,
3'-2" Long.



tail of Pinning
Concrete is but 2' thick.
Scale: 1"=4 ft.




POTTER'S FALLS DAM DETAIL OF SECTIONS AND PINNING.

Scales: 1"=10 ft., and 1"=1 ft.


July, 1910.

City Engineer--

7-7.





72



13

FLY TOP WEST 745F





POTTER'S FALLS DAM
Ithaca, N.Y. Water Supply

EAST SIDE FROM Φ OF SPILLWAY

Scale: 1 in = 10 ft.

Donald F. Ireland, City Engineer.

January 4, 1911.

H.D. D.

22 1334

ATE
LMED
-8