

AD-A142 782


NATIONAL DAM INSPECTION PROGRAM PEMBERWICK DAM (CT  
00042) SOUTHWESTERN CO. (U) CORPS OF ENGINEERS WALTHAM  
MA NEW ENGLAND DIV FEB 88


1/2

UNCLASSIFIED

FFG 13/13

NL





MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A

AD-A142 702

**SOUTHWESTERN COASTAL BASIN  
GREENWICH, CONNECTICUT**

**PEMBERWICK DAM  
CT 00042**

**PHASE 1 INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM**

DTIC FILE COPY



DTIC  
SELECTED  
JUL 05 1984  
S E D

**DEPARTMENT OF THE ARMY  
NEW ENGLAND DIVISION, CORPS OF ENGINEERS  
WALTHAM, MASS.**

**FEBRUARY, 1980**

This document has been approved  
for public release and sale; its  
distribution is unlimited.

84 07 02 043

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER CT 00042	2. GOVT ACCESSION NO. <b>AD A14 2702</b>	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Southwaestern Coastal Basin Greenwich, Conn. (Pemberwick Dam) NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS	5. TYPE OF REPORT & PERIOD COVERED INSPECTION REPORT	
	6. PERFORMING ORG. REPORT NUMBER	
7. AUTHOR(s) U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION	8. CONTRACT OR GRANT NUMBER(s)	
9. PERFORMING ORGANIZATION NAME AND ADDRESS	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS	
11. CONTROLLING OFFICE NAME AND ADDRESS DEPT. OF THE ARMY, CORPS OF ENGINEERS NEW ENGLAND DIVISION, NEDED 424 TRAPELO ROAD, WALTHAM, MA. 02254	12. REPORT DATE Feb. 1980	
	13. NUMBER OF PAGES 110	
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)	15. SECURITY CLASS. (of this report)  UNCLASSIFIED	
	15a. DECLASSIFICATION/DOWNGRADING SCHEDULE	
16. DISTRIBUTION STATEMENT (of this Report)  APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Cover program reads: Phase I Inspection Report, National Dam Inspection Program; however, the official title of the program is: National Program for Inspection of Non-Federal Dams; use cover date for date of report.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number)  DAMS, INSPECTION, DAM SAFETY,  Southwestern Coastal Basin Greenwich, Conn. Pemberwick Dam		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This dam is masonry arch approx. 115 ft. long, 45 ft. high with an average top of dam width of 8 ft. The dam was built about 1867 and presently serves no function except an aesthetic one. The test flood for this dam is the Probable Maximum Flood. The test flood has an outflow discharge equal to 25,6000 cfs and will overtop the dam by 17.0 ft. in stillwater condition. The maximum outflow capacity of the spillway under a stillwater condition is 1,100 cfs, which is 4 percent of the test flood.		



DEPARTMENT OF THE ARMY  
NEW ENGLAND DIVISION, CORPS OF ENGINEERS  
424 TRAPELO ROAD  
WALTHAM, MASSACHUSETTS 02154

REPLY TO  
ATTENTION OF  
NEDED

MAR 21 1960

Honorable Ella T. Grasso  
Governor of the State of Connecticut  
State Capitol  
Hartford, Connecticut 06115

Dear Governor Grasso:


Inclosed is a copy of the Pemberwick Dam Phase I Inspection Report, which was prepared under the National Program for Inspection of Non-Federal Dams. This report is presented for your use and is based upon a visual inspection, a review of the past performance and a brief hydrological study of the dam. A brief assessment is included at the beginning of the report. I have approved the report and support the findings and recommendations described in Section 7 and ask that you keep me informed of the actions taken to implement them. This follow-up action is a vitally important part of this program.

A copy of this report has been forwarded to the Department of Environmental Protection, the cooperating agency for the State of Connecticut. In addition, a copy of the report has also been furnished the owner, Fairfield Associates, Inc., Greenwich, Connecticut.

Copies of this report will be made available to the public, upon request, by this office under the Freedom of Information Act. In the case of this report the release date will be thirty days from the date of this letter.

I wish to take this opportunity to thank you and the Department of Environmental Protection for your cooperation in carrying out this program.

Sincerely,

  
MAX B. SCHEIDER  
Colonel, Corps of Engineers  
Division Engineer

Incl  
As stated

**SOUTHWESTERN COASTAL BASIN**

**GREENWICH, CONNECTICUT**

**PEMBERWICK DAM**

**CT 00042**

Accession Map	
NOV	<input checked="" type="checkbox"/>
DEC	<input type="checkbox"/>
JAN	<input type="checkbox"/>
FEB	<input type="checkbox"/>
MAR	<input type="checkbox"/>
APR	<input type="checkbox"/>
MAY	<input type="checkbox"/>
JUN	<input type="checkbox"/>
JUL	<input type="checkbox"/>
AUG	<input type="checkbox"/>
SEP	<input type="checkbox"/>
OCT	<input type="checkbox"/>

**A-1**



**PHASE I INSPECTION REPORT**

**NATIONAL DAM INSPECTION PROGRAM**

# NATIONAL DAM INSPECTION PROGRAM

## PHASE I - INSPECTION REPORT

Identification No.: CT 00042  
Name of Dam: Pemberwick Dam  
Town: Greenwich  
County and State: Fairfield, Connecticut  
Stream: Byram River  
Date of Inspection: November 12, 1979

### BRIEF ASSESSMENT

This dam is a masonry arch approximately 115 feet long, 45 feet high with an average top of dam width of 8 feet. The dam was built about 1867 and presently serves no function except an aesthetic one.

Based on the visual inspection and past operational performance, the dam is judged to be in FAIR condition. Seepage was noted on the downstream face. The emergency outlet works are inoperable and there is no method of lowering the water level.

This dam is classified as INTERMEDIATE in size and a HIGH hazard potential structure in accordance with recommended guidelines established by the Corps of Engineers.

The test flood for this dam is the Probable Maximum Flood (PMF). The test flood has an outflow discharge equal to 25,600 cfs and will overtop the dam by 17.0 feet in a stillwater condition. The maximum outflow capacity of the spillway under a stillwater condition is 1,100 cfs, which is 4 percent of the test flood.

It is recommended that the following items be studied further: The downstream leakage, the toe and the upstream face, and the spillway capacity.

Recommendations and remedial measures that should be implemented by the Owner within one year period after receipt of this Phase I Inspection Report, are further described in Section 7.

JAMES P. PURCELL ASSOCIATES, INC.

Sudhir A. Shah

Sudhir A. Shah, P.E.  
Vice-President  
Connecticut P.E. No. 8012





This Phase I Inspection Report on Pemberwick Dam has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the Recommended Guidelines for Safety Inspection of Dams, and with good engineering judgment and practice, and is hereby submitted for approval.

Carney M. Terzian

CARNEY M. TERZIAN, MEMBER  
Design Branch  
Engineering Division

Richard J. DiBuono

RICHARD DIBUONO, MEMBER  
Water Control Branch  
Engineering Division

Aramast Mahtesian

ARAMAST MAHTESIAN, CHAIRMAN  
Foundation & Materials Branch  
Engineering Division

APPROVAL RECORDED:

Joe B. Fryar

JOE B. FRYAR  
Chief, Engineering Division

## PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I Investigation. However, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the spillway test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and downstream damage potential.

The Phase I Investigation does not include an assessment of the need for fences, gates, no-trespassing signs, repairs to existing fences and railings and other items which may be needed to minimize trespass and provide greater security for the facility and safety to the public. An evaluation of the project for compliance with OSHA rules and regulations is also excluded.

## TABLE OF CONTENTS

<b>Section</b>	<b>Page</b>
Letter of Transmittal	
Brief Assessment	
Review Board Page	
Preface	i
Table of Contents	ii-iv
Overview Photo	v
Location Map	vi

### REPORT

#### 1. Project Information

1.1	General	1
	a. Authority	
	b. Purpose of Inspection	
1.2	Description of Project	1
	a. Location	
	b. Description of Dam and Appurtenances	
	c. Size Classification	
	d. Hazard Classification	
	e. Ownership	
	f. Operator	
	g. Purpose of Dam	
	h. Design and Construction History	
	i. Normal Operational Procedure	

1.3	Pertinent Data	3
-----	----------------	---

#### 2. Project Information

2.1	Design	3
-----	--------	---

## TABLE OF CONTENTS (Cont'd)


<b>Section</b>	<b>Page</b>
2.2 Construction	7
2.3 Operation	7
2.4 Evaluation	7
<b>3. Visual Inspection</b>	
3.1 Findings	8
a. General	
b. Dam	
c. Appurtenant Structures	
d. Reservoir Area	
e. Downstream Channel	
3.2 Evaluation	10
<b>4. Operational and Maintenance Procedures</b>	
4.1 Operational Procedures	11
4.2 Maintenance of the Dam	11
4.3 Maintenance of the Operating Facilities	11
4.4 Description of Any Warning System in Effect	11
4.5 Evaluation	11
<b>5. Evaluation of Hydraulic/Hydrologic Features</b>	
5.1 General	12
5.2 Design Data	12
5.3 Experience Data	12
5.4 Test Flood Analysis	13
5.5 Dam Failure Analysis	13

## TABLE OF CONTENTS (Cont'd)

Section	Page
<b>6. Evaluation of Structural Stability</b>	
6.1 Visual Observations	14
6.2 Design and Construction Data	14
6.3 Post-Construction Changes	14
6.4 Seismic Stability	14
<b>7. Assessment, Recommendations and Remedial Measures</b>	
7.1 Dam Assessment	15
a. Condition	
b. Adequacy of Information	
c. Urgency	
7.2 Recommendations	15
7.3 Remedial Measures	15
a. Operation and Maintenance Procedures	
7.4 Alternatives	16
<b>APPENDIXES</b>	
<b>Appendix A - Inspection Checklist</b>	<b>A-1</b>
<b>Appendix B - Engineering Data</b>	<b>B-1</b>
<b>Appendix C - Photographs</b>	<b>C-1</b>
<b>Appendix D - Hydrologic and Hydraulic Computations</b>	<b>D-1</b>
<b>Appendix E - Information as Contained in the National Inventory of Dams</b>	<b>E-1</b>



OVERVIEW PHOTO - FEMBERWICK DAM



**LOCATION PLAN**  
**PEMBERWICK DAM**  
 Scale: 1" = 2000'  
 PLATE NO. 1

# NATIONAL DAM INSPECTION PROGRAM

## PHASE I - INSPECTION REPORT

NAME OF DAM: PEMBERWICK DAM

### SECTION 1

#### PROJECT INFORMATION

##### 1.1 General

- a. **Authority:** Public Law 92-367, August 8, 1972, authorized the Secretary of the Army through the Corps of Engineers to initiate a national program of dam inspection throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region. James P. Purcell Associates, Inc. has been retained by the New England Division to inspect and report on selected dams in the State of Connecticut. Authorization and notice to proceed was issued to James P. Purcell Associates, Inc., under a letter from William E. Hodgson, Jr., Colonel, Corps of Engineers. Contract No. DACW33-80-C-0002 has been assigned by the Corps of Engineers for this work.
- b. **Purpose of Inspection**
  1. Perform technical inspection and evaluation of non-Federal dams to identify conditions which threaten the public safety and thus permit correction in a timely manner by non-Federal interests.
  2. Encourage and prepare the States to initiate quickly, effective dam safety programs for non-Federal dams.
  3. To update, verify and complete the National Inventory of Dams.

##### 1.2 Description of Project

- a. **Location:** Pemberwick Dam is located in Fairfield County, Connecticut, approximately 0.4 miles north of the village of Pemberwick on the Connecticut - New York state line (See Plate No. 1). The dam impounds water from the Byram River and is located approximately 3.5 miles upstream of Long Island Sound. The impoundment is situated in a north-south direction, with the dam



located at the southern end. The latitude is 41° -01'-42" and the longitude is 73° -39'-48".

- b. **Description of Dam and Appurtenances:** The Pemberwick Dam is an arch dam, built between ledge rock abutments, creating an impoundment in the narrow gorge with nearly vertical sides. The downstream face is nearly vertical with a plan radius of 180+/- feet and is constructed of coursed ashlar masonry. The date of construction of the dam is approximately 1867.

A 63 foot long spillway is located in the center of the dam.

The outlet works, consisting of pipes through the dam, have been inoperable for many years. The high level outlet was sealed in 1978 to control leakage and the inlet for the low level outlet is suspected to be below the present sediment level.

- c. **Size Classification:** The dam is classified as an INTERMEDIATE structure as per the criteria set forth in the Recommended Guidelines for the Safety Inspection of Dams by the Corps of Engineers. The impoundment storage at the top of the dam is 60 ac.-ft. (within the "small" category range of 50 to 1000 acre-feet) and the maximum height of the dam is 45 feet (within the "intermediate" category range of 40 to 100 feet). The size classification is governed by the height criteria.
- d. **Hazard Classification:** The dam is classified as a HIGH hazard potential structure as per the criteria set forth in the Recommended Guidelines for the Safety Inspection of Dams by the Corps of Engineers. It is located just upstream of a residential development, a day school, and an industrial facility where failure discharge may cause the loss of more than a few lives and excessive damage due to high velocity impact from debris and flooding. The estimated water depth will inundate the school by approximately 10 feet and cause flooding of structures along the banks in the village of Pemberwick of approximately 3 to 5 feet.

The failure of an upstream dam (the American Felt Dam), located approximately 3000 feet upstream, might have a potentially hazardous effect on the Pemberwick Dam.

- e. **Ownership:** The Pemberwick Dam is presently owned by Fairfield Associates, Inc., 100 Putnam Street, Greenwich, Connecticut 06830. The property was acquired in 1979 from the GAF Corporation, Wayne, New Jersey, as a development investment. Subsequent to the development of the property, the owners will be a condominium association.

- f. **Operator:** The operator and caretaker for Pemberwick Dam is:

John Koslowski, Maintenance Superintendent  
Fairfield Associates, Inc.  
6 Glenville Street  
Greenwich, CT 06830  
Tel: (203) 531-1822 (mill)  
531-9093 (home)

- g. **Purpose of Dam:** The Pemberwick Dam impounds water from the Byram River. The original purpose of this dam is unknown, and its purpose now is only aesthetic.
- h. **Design and Construction History:** The Pemberwick Dam was constructed after the Civil War in 1867. Reportedly, the dam failed in a flood of 1877 and was rebuilt shortly thereafter. No information on the extent of the damage or rebuilding is available. This dam was probably never used for power generation. No construction plans are known to be in existence.
- i. **Normal Operating Procedures:** The dam, as it is presently used, requires no attention for normal operating procedures.

### 1.3 Pertinent Data

- a. **Drainage Area:** The Pemberwick Dam is located in Fairfield County, Connecticut. The drainage basin lies 0.4 miles north of the village of Pemberwick. The basin is generally rectangular in shape having a length of 11.8 miles and an average width of 2.2 miles. The total drainage area to the dam is 26.2 square miles (see drainage basin map in Appendix D). The topography is generally rolling to moderate terrain, with elevations ranging from a high of 740 feet to 76.5 feet at the spillway crest. Stream and basin slopes are flat to moderate having average grades of 0.9 percent to 1.2 percent, respectively. The pond has a normal surface area of 5.5 acres, which is 0.03 percent of the watershed.

All elevations used in this report are based on the National Geodetic Vertical Datum (NGVD). Elevations are based on a spillway crest elevation of 76.5 feet estimated from available mapping.

- b. **Discharge at Dam Site:** Discharge records are limited to estimated flows for the 1938 and 1955 storms (refer to Section 5.3 - Experience Data). Listed below are calculated discharge values for the spillway:

1. Outlet works: N/A (inoperable)
2. Maximum known flood at dam site: Estimated by unknown source to have been 3200 cfs in October 1955.
3. Spillway capacity at top of dam: 1100 cfs at elevation 80.0.
4. Spillway capacity at test flood: 15800 cfs at elevation 97.0.
5. Gated outlet capacity at normal pool elevation: N/A
6. Gated outlet capacity at test flood elevation: N/A
7. Gated outlet capacity at top of dam elevation: N/A
8. Total project discharge at top of dam: 1100 cfs at elevation 80.0.
9. Total project discharge at test flood elevation: 15800 cfs at elevation 97.0.

**c. Elevation (Feet above NGVD)**

1. Streambed at toe of dam	35.0
2. Bottom of cutoff	Unknown
3. Maximum tailwater	Unknown
4. Recreation pool	N/A
5. Full flood control pool	N/A
6. Spillway crest	76.5
7. Design surcharge (original design)	Unknown
8. Top of dam	80.0
9. Test flood level	97.0

**d. Reservoir (Length in Feet)**

1. Normal pool	1500
----------------	------

2.	Flood control pool	N/A
3.	Spillway crest pool	1500
4.	Top of dam	3000
5.	Test flood pool	3000
3.	<b>Storage (Acre-Feet)</b>	
1.	Normal pool	41
2.	Flood control pool	N/A
3.	Spillway crest pool	41
4.	Top of dam	60
5.	Test flood pool	223
f.	<b>Reservoir Surface (Acres)</b>	
1.	Normal pool	5.5
2.	Flood control pool	N/A
3.	Spillway crest	5.5
4.	Top of dam	7.0
5.	Test flood pool	11.0
g.	<b>Dam</b>	
1.	Type	Stone masonry arch dam
2.	Length	115 ft.
3.	Height	45 ft.
4.	Top width	8 ft.

5.	Side slopes	Upstream: Vertical above spillway Downstream: 1H:10V
6.	Zoning	Unknown
7.	Impervious core	Unknown
8.	Cutoff	Unknown
9.	Grout curtain	Unknown
h.	<b>Diversion and Regulating Tunnel</b>	N/A
i.	<b>Spillway</b>	
1.	Type	Overflow broad crested, uncon- trolled weir
2.	Length of weir	63 ft.
3.	Crest elevation	76.5
4.	Gates	None
5.	U/S Channel	Natural bed
6.	D/S Channel	Natural bed, floodwall on east bank.
j.	<b>Regulating Outlets (inoperable)</b>	
1.	Invert	N/A
2.	Size	N/A
3.	Description	N/A
4.	Control mechanism	N/A

## SECTION 2

### ENGINEERING DATA

#### 2.1 Design

There are no available records presenting design information for the construction of the Pemberwick Dam. A plan made during a previous inspection in 1938 is included in Appendix B of this report.

#### 2.2 Construction

There are no available records of the construction of the dam and it appears that the above referenced drawing illustrates the "as built" condition. The high level outlet was plugged in 1978.

#### 2.3 Operation

No formal records of operation are kept for this facility. The dam is inspected weekly by personnel from Greenwich Associates, Inc., developers of the surrounding property inclusive of the Pemberwick Dam. The dam has only an aesthetic use at this time.

#### 2.4 Evaluation

- a. **Availability:** The information noted above for this facility is available in the files of the Department of Environmental Protection, Water and Related Resources Unit, Dam Safety Engineers, State Office Building, Hartford, Connecticut, and Greenwich Associates, Inc., Greenwich, Connecticut.
- b. **Adequacy:** The lack of indepth engineering data did not allow a definitive review. Therefore, the adequacy of this dam could not be assessed from the standpoint of reviewing design and construction data, but is based primarily on the visual inspection, the dam's past performance, and sound engineering judgment.
- c. **Validity:** The validity of the limited information available must be verified.

## SECTION 3

### VISUAL INSPECTION

#### 3.1 Findings

- a. **General:** The visual inspection of the Pemberwick Dam was conducted on November 12, 1979 and a copy of the visual inspection check list is contained in Appendix A of this report.

The following procedure was used:

1. Inspection of the upstream reach of the river which was impounded by the dam.
2. Visual inspection of the face and the top of the dam and spillway for cracks, loose stones, leakage, etc.
3. Inspection of the outlet works and other appurtenances as to their existence, location and operability.
4. Review of procedures that could be utilized in the event of an emergency situation.
5. A check of the downstream area for seepage, piping, boils or other indications of abnormal conditions. The downstream hazard potential in the event of dam failure was investigated.
6. Photographs of the general area of the dam and of specific items of note were taken and are included in Appendix C of this report.

Before the inspection, the available existing data and aerial photographs were studied and reviewed.

b. **Dam**

1. **Crest:** The top of the dam is constructed of granite capstones with no evidence of settlement or misalignment (Photo C-1). Grass is growing between some of the stones. The dam's east crest supports the gear lift mechanisms for the outlet works, and a metal pipe railing around the perimeter, which appears in good condition (Photo C-5). The western top of the dam was not accessible, but appears to be in a similar condition. The top of the dam has a width of approximately 8 feet.

2. **Upstream Face:** The upstream face of the dam is stone masonry with a vertical face above the water level at the time of the inspection, which was approximately 31 inches below the top of the dam. Grass was growing in the joints between some of the stones.
3. **Downstream Face:** The downstream face is also stone masonry with a nearly vertical face. See Appendix B for a typical cross section through the dam. Grass and small shrubs were growing in joints between some of the stone blocks. Leakage was noted from several masonry joints at and adjacent to both ends of the spillway (Photos C-3, C-4). The dam appears to be founded on bedrock.

c. **Appurtenant Structures**

1. **Spillway:** The spillway is a 63 foot long and 8 foot wide broad crested weir with a free drop of approximately 33 feet to the tailwater (Photo C-6). It is constructed of capstones which overhang the downstream face of the dam by approximately 6 inches. Water was flowing over the spillway at the time of inspection, and leakage was noted between the stone comprising the vertical ends of the spillway and the masonry dam embankment. Two logs, each approximately 15 inches in diameter and 30 feet long, were resting on the spillway crest at the time of inspection (Photo C-2). It is probable that they will wash over the crest during the next high discharge, possibly creating an impact or blockage hazard downstream.
  2. **Low Level Outlet:** The information provided by the representatives of the owner, and record photographs, indicate the presence of a low level outlet located approximately in the center of the dam. The slanted gear lift mechanism on the dam's east crest apparently regulated flow through this outlet, which is suspected to lead through the dam. The present level of silt and sediment on the upstream side of the dam, and the owner, indicate that the intake is covered and, therefore, inoperable.
  3. **High Level Outlet:** The high level outlet is located on the east side of the dam and was controlled by a valve attached to the vertical gear mechanism. The threaded bar for the mechanism has been sheared, rendering the valve inoperable (reportedly in the open position). The horizontal outlet pipe from the downstream face of the dam to the vertical shaft in the center of the dam was filled with concrete in 1978 by the S. E. Minor Company.
- d. **Reservoir Area:** The impoundment created by the dam is a narrow flooded portion of the natural river bed. The valley walls are fairly steep at the dam and



become less steep 1500 to 2000 feet upstream. Bedrock appears to be at or near the surface. No geologic features were detected that could be expected to adversely affect the dam.

Trespassing on the dam is prohibited and the dam site is fenced and locked on the east side and fenced on the west side, reducing the potential for trespassing and vandalism. The fence on the west side has collapsed on the upstream end (Photo C-2), but protection against access to the site is still afforded.

- e. **Downstream Channel:** Immediately downstream of the dam is a continuation of the steep valley walls on the west side, and a building (Mead School) and flood wall on the east side (Photo C-7). Numerous trees are overhanging the channel in this section. Further downstream, the channel is lined with riprap and is a fairly straight uniform trapezoidal channel (Photo C-8).

### 3.2 Evaluation

Based on the visual inspection, the Pemberwick Dam appears to be in fair condition overall, and there were no major areas of distress noted. Specific items of concern that were noted are:

The inability to draw down the pond level due to the inoperability of the outlet works.

The presence of leakage on the downstream face and the vegetative growth on the faces of the dam.

The structural integrity cannot be evaluated due to the unknown conditions within and below the dam.

## SECTION 4

### OPERATIONAL AND MAINTENANCE PROCEDURES

#### 4.1 Operational Procedures

There are presently no operational procedures for the Pemberwick Dam. It has only an aesthetic purpose at this time.

#### 4.2 Maintenance of the Dam

There is no regular maintenance schedule for this dam. The downstream channel is lined with riprap for erosion protection and is free of vegetation growth. Upstream of the dam, the tree-lined channel has natural steeply sloping rock walls not requiring any maintenance.

#### 4.3 Maintenance of the Operating Facilities

No maintenance of the outlet works is presently performed. The high level outlet was plugged in 1978 and the low level outlet is apparently covered with sediment and is inoperable.

#### 4.4 Description of Any Warning System in Effect

No formal emergency or contingency plan is in effect to reduce or minimize downstream damage in emergency situations.

#### 4.5 Evaluation

To insure the safety of the residents and industries immediately downstream, a regular inspection and maintenance program should be developed and implemented.

## SECTION 5

### EVALUATION OF HYDRAULIC/HYDROLOGIC FEATURES

#### 5.1 General

The Pemberwick Dam, built across the Byram River, creates a narrow impoundment with a total storage capacity of 41 ac.-ft. at the spillway elevation of 76.5 or 0.03 percent of the watershed area of 26.2 square miles. Each foot of depth in the pond above the spillway crest can accommodate approximately 5.5 ac.-ft. The spillway is a 63 foot long by 8 foot wide broad crested uncontrolled weir. Stream and basin slopes are flat to moderate having average grades of 0.9 percent and 1.2 percent, respectively.

#### 5.2 Design Data

- a. Flood calculations were done by the State of Connecticut in November, 1955 and yielded a 100-year frequency flood of 3390 cfs for the Pemberwick Dam site.

To supplement this data, U.S.G.S. topographic maps (scale 1"=2000') were utilized to develop hydrologic parameters such as drainage areas, reservoir surface areas, basin length, time of concentration and other runoff characteristics. Elevation-storage relationships for the reservoir were approximated. Surcharge storage was computed using U.S.G.S. maps. Some of the pertinent hydraulic design data was obtained and/or confirmed by actual field measurements at the time of the visual field inspection.

- b. Outflow values (routing procedures) and dam overtopping analyses were computed in accordance with the guidelines developed by the Corps of Engineers. Judgment was used in calculating final values outlined in this report, which are quite approximate and should not be considered a substitute for actual detailed analysis.

#### 5.3 Experience Data

Historical data for recorded discharges at the dam site is limited to the following approximations derived in 1955 from an unknown source:

July and September 1938 - 2400 cfs  
October 1955 - 3200 cfs

From the spillway capacity and dam overtopping analysis calculations, both of these floods overtopped the dam by at least 2 feet.

#### 5.4 Test Flood Analysis

Recommended Guidelines for the Safety Inspection of Dams by the Corps of Engineers were used for the selection of the "Test Flood". This dam is classified as a HIGH hazard and an INTERMEDIATE size structure. Guidelines indicate that the Probable Maximum Flood (PMF) be used as the test flood for these classifications. The watershed has a total area of 26.2 square miles. Snyder's lag was calculated to be 7.31 hours and a Snyder peaking coefficient of 0.625 was used. The 200 square miles - 24 hour Probable Maximum Precipitation (PMP) is 22 inches. The flood hydrograph package, HEC-1 computer program, developed by the Corps of Engineers was utilized to develop the inflow hydrograph, route the flood through the reservoir, and for the dam overtopping analysis. A test flood inflow equal to the PMF was calculated to be 25600 cfs. The inflow of 1/2 PMF is 12800 cfs.

The spillway capacity is hydraulically inadequate to pass the test flood (PMF) and overtopping of the dam will occur. The maximum outflow capacity of the spillway without overtopping the dam is 1100 cfs. This corresponds to 4 percent of the test flood and a storage above the spillway level of 19 ac.-ft. The maximum outflow discharge value for the test flood is 25600 cfs corresponding to a depth of flow over the top of the dam of 17.0 feet and a storage above the spillway level of 182 ac.-ft. The outflow value for 1/2 PMF is 12800 cfs. A spillway rating curve and a reservoir surface area - capacity curve are included in Appendix D of this report.

There are no operating outlet works and all flow must be discharged over the spillway or top of the dam. Storage for impending flood conditions cannot be provided if the pool level is high.

#### 5.5 Dam Failure Analysis

This dam is classified as a high hazard structure. Failure discharge can cause damage due to high velocities, impact from debris, and flooding to over 5 residential homes, a school and a commercial building. The calculated dam failure discharge is 8350 cfs at a pool level equal to the top of the dam. At this level, the pre-failure flow in the downstream channel will be 1100 cfs corresponding to a depth of flow of approximately 5 feet. Failure will produce a water surface level of approximately 11.5 feet immediately downstream from the dam. The failure discharge will affect downstream areas for a distance of 3000 feet from the dam. At this distance the water surface level will be approximately 1 to 2 feet above normal observations. Beyond 3000 feet, the effects of the failure discharge will be reduced as it enters an unnamed pond. Water surface elevations due to the failure of the dam are listed in Appendix D. Probable consequences including the prime impact areas, are also listed in Appendix D.

## SECTION 6

### EVALUATION OF STRUCTURAL STABILITY

#### 6.1 Visual Observation

The visual inspection revealed no signs of major physical distress in the structure. However, leakage was noted on the downstream face.

#### 6.2 Design and Construction Data

There is insufficient design and construction data to permit a formal evaluation of stability.

#### 6.3 Post-Construction Changes

No post-construction design data pertinent to the embankment or foundation is available. It is believed that the original dam failed in October 1877 and the present dam rebuilt shortly thereafter. The extent of the damage due to the failure or information concerning the rebuilding is unavailable.

The high level outlet was sealed in 1978. The low level outlet is suspected to be below the present sediment level.

#### 6.4 Seismic Stability

The dam is in Seismic Zone 1 and, hence, does not require evaluation for seismic stability according to the Corps of Engineers Recommended Guidelines.

## SECTION 7

### ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES

#### 7.1 Dam Assessment

- a. **Condition:** Based on the visual inspection, past performance and hydraulic/hydrologic evaluation, the Pemberwick Dam and appurtenances are judged to be generally in FAIR condition. Items of concern that should be addressed as a result of this inspection are listed in Sections 7.2 and 7.3.
- b. **Adequacy of Information:** The absence of existing engineering data did not allow for definitive review. Therefore, the adequacy of the dam is based on visual inspection, past performance history, and engineering judgment.
- c. **Urgency:** The recommendations and remedial measures described below should be implemented by the owner within one year after receipt of this Phase I Inspection Report.

#### 7.2 Recommendations

It is recommended that the owner engage a qualified registered engineer to carry out the following actions:

- a. A detailed hydraulic-hydrologic investigation to determine the need and means of increasing the discharge capacity of the project.
- b. The pond be lowered and the upstream face be visually inspected, and the toe checked for potential undermining.

#### 7.3 Remedial Measures

- a. **Operational and Maintenance Procedures**
  - 1. The vegetation should be removed from the joints and the joints re-pointed on the faces and top of the dam.
  - 2. The two logs should be removed from the spillway crest as soon as possible.
  - 3. The trees overhanging the channel downstream of the dam should be removed.

4. The damaged fence on the west abutment should be repaired.
5. The seepage on the downstream face should be monitored to note any change from the existing conditions.
6. The low level outlet should be brought back to an operating condition to allow the pond to be lowered.
7. Institute a program of annual periodic technical inspection with special emphasis on the joint between the dam and the rock abutments at the valley walls.
8. Develop a formal flood warning and surveillance plan, including round-the-clock monitoring during heavy precipitation.

#### **7.4 Alternatives**

Remove the dam.

**APPENDIX A**  
**INSPECTION CHECK LIST**



INSPECTION CHECK LIST

PARTY ORGANIZATION

PROJECT PEMBERWICK DAM

DATE NOVEMBER 12, 1979

TIME 10:00 AM - 12:00

WEATHER PARTLY SUNNY

W.S. ELEV. \_\_\_\_\_ U.S. \_\_\_\_\_ DN.S.

PARTY:

1. R. JOHNSTON, JPPA

6. D. KNABEL - GREENWICH ASSOC.

2. R. LYON, JPPA

7. \_\_\_\_\_

3. G. SALZMAN, CWDD

8. \_\_\_\_\_

4. \_\_\_\_\_

9. \_\_\_\_\_

5. \_\_\_\_\_

10. \_\_\_\_\_

PROJECT FEATURE	INSPECTED BY	REMARKS
1. <u>Hydraulics</u>	<u>R. Johnston</u>	
2. <u>Structural</u>	<u>R. Lyon</u>	
3. <u>Geotechnical</u>	<u>G. Salzman</u>	
4. _____		
5. _____		
6. _____		
7. _____		
8. _____		
9. _____		
10. _____		

INSPECTION CHECK LIST

PROJECT PEMBERWICK DAM

DATE 11-12-79

PROJECT FEATURE \_\_\_\_\_

NAME \_\_\_\_\_

DISCIPLINE \_\_\_\_\_

NAME \_\_\_\_\_

AREA EVALUATED	CONDITION
<u>DAM EMBANKMENT</u>	
Crest Elevation 80.0	GOOD - STONE CREST
Current Pool Elevation 76.5	GOOD - 31" BELOW CREST
Maximum Impoundment to Date	
Surface Cracks	NONE OBSERVED
Pavement Condition	GRASS GROWING BETWEEN STONES
Movement or Settlement of Crest	NONE OBSERVED
Lateral Movement	NONE OBSERVED
Vertical Alignment	GOOD
Horizontal Alignment	GOOD
Condition at Abutment and at Concrete Structures	GOOD
Indications of Movement of Structural Items on Slopes	NONE OBSERVED
Trespassing on Slopes	NOT PERMITTED
Vegetation on Slopes	MINOR - GRASS & SM. SHRUBS IN JOINTS
Sloughing or Erosion of Slopes or Abutments	NONE OBSERVED
Rock Slope Protection - Riprap Failures	N/A
Unusual Movement or Cracking at or near Toes	TOE NOT VISIBLE - UNDERWATER
Unusual Embankment or Downstream Seepage	LEAKS AT AND ADJACENT TO SPILLWAY SILL EDGES
Piping or Boils	NONE OBSERVED
Foundation Drainage Features	NONE OBSERVED
Toe Drains	NONE OBSERVED
Instrumentation System	NONE OBSERVED

INSPECTION CHECK LIST

PROJECT PIMBERWICK DAM

DATE 11-12-79

PROJECT FEATURE \_\_\_\_\_

NAME \_\_\_\_\_

DISCIPLINE \_\_\_\_\_

NAME \_\_\_\_\_

AREA EVALUATED	CONDITION
<p><u>CUTLET WORKS - INTAKE CHANNEL AND INTAKE STRUCTURE</u></p>	
<p>a. Approach Channel</p>	<p>ENTIRE RIVER BFD - UNDERWATER</p>
<p>b. Intake Structures</p> <p style="padding-left: 40px;">Low Level Outlet</p> <p style="padding-left: 40px;">High Level Outlet</p>	<p>NOT VISIBLE - SUSPECTED TO BE CONTROLLED BY THE SLANTED GEAR LIFT ON THE TOP OF THE DAM. INTAKE SUSPECTFD TO BE BELOW PRESENT SILT LEVEL AND INOPERABLE.</p> <p>SURFACE INTAKE OPEN. LOWER INTAKE NOT VISIBLE. VERTICAL GFAR STEM ON INOPERABLE (SHEARED SHAFT).</p>

INSPECTION CHECK LIST

PROJECT PEMBERWICK DAM

DATE 11-12-79

PROJECT FEATURE \_\_\_\_\_

NAME \_\_\_\_\_

DISCIPLINE \_\_\_\_\_

NAME \_\_\_\_\_

AREA EVALUATED	CONDITION
<p><u>OUTLET WORKS - TRANSITION &amp; CONDUIT</u></p> <p>Low Level Outlet</p> <p>High Level Outlet</p>	<p>TYPE AND CONDITION UNKNOWN.</p> <p>A VERTICAL SHAFT LEADS FROM THE SURFACE AND LOWER INTAKE TO A 36" PIPE WHICH EXTENDS HORIZONTALLY TO THE DOWNSTREAM FACE OF THE DAM. PLUGGED WITH CONCRETE IN 1978.</p>

INSPECTION CHECK LIST

PROJECT PFMBFRWICK DAM

DATE 11-12-79

PROJECT FEATURE \_\_\_\_\_

NAME \_\_\_\_\_

DISCIPLINE \_\_\_\_\_

NAME \_\_\_\_\_

AREA EVALUATED

CONDITION

OUTLET WORKS - OUTLET STRUCTURE  
AND OUTLET CHANNEL

Structure

NOT VISIBLE. 12 INCH OUTLET VALVE ON DOWNSTREAM FACE OF DAM FOR HIGH LEVEL OUTLET WAS REMOVED AND OUTLET SEALED WITH CONCRETE IN 1978. LOW LEVEL OUTLET WAS APPARENTLY A PIPE OUTLETTING THROUGH THE FACE OF THE DAM.

Channel

SEE SPILLWAY DISCHARGE CHANNEL.

INSPECTION CHECK LIST

PROJECT PEMBERWICK DAM DATE 11-12-79  
 PROJECT FEATURE \_\_\_\_\_ NAME \_\_\_\_\_  
 DISCIPLINE \_\_\_\_\_ NAME \_\_\_\_\_

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS</u>	
a. Approach Channel	ENTIRE RIVER BED - UNDER WATER
General Condition	
Loose Rock Overhanging Channel	
Trees Overhanging Channel	
Floor of Approach Channel	
b. Weir	
General Condition of Granite	GOOD
Rust or Staining	N/A
Spalling	NONE OBSERVED
Any Visible Reinforcing	NONE OBSERVED
Any Seepage or Efflorescence	SPILLWAY FLOWING - NONE VISIBLE
Drain Holes	NONE OBSERVED
c. Discharge Channel	ENTIRE RIVERBED - UNDERWATER
General Condition	GOOD
Loose Rock Overhanging Channel	NONE OBSERVED
Trees Overhanging Channel	YES
Floor of Channel	UNDERWATER - APPARENTLY ROCK
Other Obstructions	BUILDING AND SURROUNDING CONCRETE WALL ON LEFT SLOPE

**APPENDIX B**  
**ENGINEERING DATA**

## **APPENDIX B-1**

### **DESIGN, CONSTRUCTION AND MAINTENANCE RECORDS AND LOCATION**

**Mr. Victor J. Galgowski  
Dam Safety Engineer  
Water and Related Resources Unit  
Department of Environmental Protection  
State of Connecticut  
State Office Building  
Hartford, Connecticut 06115**

**Greenwich Associates, Inc.  
100 Putnam Green  
Greenwich, Connecticut 06830**



**APPENDIX B-2**

**COPIES OF PAST INSPECTION REPORTS**

# BUCK & BUCK

E N G I N E E R S

98 WADSWORTH STREET, HARTFORD, CONNECTICUT 06106

JAMES A. THOMPSON  
ROBINSON W. BUCK  
LAWRENCE F. BUCK

HENRY WOLCOTT BUCK  
1931-1968  
ROBINSON D. BUCK  
1935-1959

COMM. 5713-131

June 13, 1978

Mr. Victor Galgowski,  
Superintendent of Dams,  
Department of Environmental Protection,  
State Office Building,  
Capitol Avenue,  
Hartford, Connecticut 06115

WATER RESOURCES  
UNIT  
RECEIVED

JUN 16 1978

Reference: "American Felt Dam"  
Byram River, Greenwich

ANSWERED \_\_\_\_\_  
REFERRED \_\_\_\_\_  
FILED \_\_\_\_\_

Dear Vic:

We inspected the subject dam on May 19, 1978 and found the dam to be in good condition and apparently safe. There is a slight leak at spillway level in the west abutment, but the leak is very minor and nothing to be concerned about. The dam is a cut stone masonry arch, founded on ledge rock. Most probably the abutments also bear against ledge rock. The dam is basically a run of the river type structure which can be overtopped without danger to the dam.

I checked the Corps of Engineers "Flood Plain Information Study" of the Byram River, prepared in 1964 and found that the subject dam is called the "Aerotec" dam in that report. The Corps study indicates the dam will be overtopped by a 10-year flood. The study also indicates the downstream channel will contain a flood flow of 4,300 cfs, which is equal to the flood of record, which occurred in October of 1955.

Although the dam itself is in good condition, we found some of its appurtenances in bad shape. The protective railing which surrounds the east abutment is rusting at the base of each post and a large section on the downstream side has broken off. The gate mechanism operating wheel has been broken, the stem is badly rusted and it's most probable that the mechanism is inoperable. A gate and section of pipe that had been installed in the old "pipe head race" has broken off, reportedly due to heavy ice loads this last Winter, and water is spewing freely from the broken pipe. Downstream owners expressed concern about the flow from this pipe, but it is being deflected by a ledge outcropping and is causing no damage.

Reproduced from  
best available copy.

BUCK & BUCK

ENGINEERS

TO Mr. Victor Galgowski

PAGE 2.


DATE June 13, 1978

COMM. 5713-131

In summary, the structure is in good condition and appears to be safe. Some of its appurtenances need improvement, but they are all non-structural maintenance type items. The owner should be notified of these conditions.

Sincerely yours,

BUCK & BUCK

A handwritten signature in cursive script that reads "James A. Thompson". The signature is written in dark ink and is positioned above the printed name.

James A. Thompson

JAT:fb

No.                     

WATER RESOURCES COMMISSION  
SUPERVISION OF DAMS  
INVENTORY DATA

42

Inventoried  
By DEC

Date 3-8-65

Name of Dam or Pond Comly Hill Dam PEPPERWICK DAM

Code No.                      (R.B.W. DAM)

Nearest Street Location                     

Town Greenwich

U.S.G.S. Quad. GREENVILLE

Name of Stream RYAN'S CREEK

Owner G.H.F.

Address 1361 Alps Road  
Wayne, NJ 07470

Pond Used For INDUSTRIAL USES DA-65-61511

Dimensions of Pond: Width              Length              Area 3HL

Total Length of Dam 150' Length of Spillway 20'

Location of Spillway End of Dam

Height of Pond Above Stream Bed 35' 5" 15' water  
20' spill

Height of Embankment Above Spillway 20' 11" 15' water

Type of Spillway Construction STONE & CONC

Type of Dike Construction STONE & CONC

Downstream Conditions FRICTION LAST RECORD 1/6/64

Summary of File Data                     

Remarks SHOULD HAVE FILE ON THIS CHECK

AS TO CONDITION

Would Failure Cause Damage? To Factory Class B

1867

COPY

TOWN OF GREENWICH  
CONNECTICUT

DEPT. OF PUBLIC WORKS

September 5, 1950

Mr. W. H. Lehberg  
American Felt Co.  
Glenville, Conn.

Re: Miscoy Arch Dam - Myran River  
North of Conly Ave.

Dear Mr. Lehberg:

It was fortunate for my purposes you mentioned the other day that your company now owns the R.E. & W. Dam and that you had drawn down the water for the purpose of repairing a gate. The foundation of this dam was ignored for several years not knowing whether or not undersecuring had occurred at the foundation in the tailwater pool. This pool was pumped out and photographs taken Sept. 1st, a set of same being enclosed. I had previously attempted to test the foundation by prodding with long poles from a raft but as you can readily realize this was not entirely satisfactory. You will note that the photographs show no undersecuring of the foundation at the toe of the dam. I would suggest that whenever opportunity affords, say in periods of five to ten years, that the pool be de-watered and the foundation examined.


The ledge rock on the west abutment apparently is in better condition than that on the east due apparently to the inclination of the stratification.

I did not examine the ashlar masonry joints closely since the whole area was slippery and I did not care to fall and break a leg. As suggested to you over the telephone I think it would be to your company's interest to examine the pointing to determine to what depth it has deteriorated. This is a semi-arch type dam and if the pointing deteriorates materially, it would be possible over a period of time, through the accumulation of smaller movements, to bring about a condition that might impair the safety of the dam. If the mortar has deteriorated or is washed out entirely to a considerable depth I would suggest you look into the possibility of making repairs by the gunite process. As you know, by this process mortar is shot into the structure at considerable velocity. I would believe also that this process would do as good or a better job and at less cost than the usual hand methods of pointing.

I understand that now diving is not permitted from the dam. You will note in the photographs a sizeable boulder approximately in the center of the pool; it is a wonder that some boy did not break his neck in the past.

You will understand of course that my principal interest in this structure is due to feeling that the Town has some responsibility to the inhabitants in the Westbrook flood plain below the dam as well as damage to Town roads and bridges.

Yours very truly,

  
Joseph V. Cone  
Commissioner

Reproduced from  
best available copy.

JVC:CB  
cc. State Bd. of Dams

B-6



RECORD PHOTOGRAPH FROM  
PREVIOUS DAM INSPECTION  
SEPTEMBER 5, 1950

56-1-1  
from Mr. Caldwell's  
Office  
December 15, 1938

Drainage Commission  
Town Hall  
Greenwich, Conn.

COPY

Re: Byram River Dams

Gentlemen:-

At the request of your Commission, representing the Town of Greenwich, and other interested parties, an inspection was made November 2, 1938 of three dams on the Byram River by a committee of this Board consisting of Messrs. Palmer, Blair and Cone, with particular reference to loss or damage in the Pemberwick flood area should these dams break away.

A study of the watershed to determine probable maximum run-off was made by the writer and field data was obtained under his supervision.

The dams under consideration, in order following downstream, are commonly known as the:- Reynolds Dam, Felt Co. Dam, and R. B. & W. Dam, owned respectively by Grace V. A. Reynolds, The American Felt Co. and Russell, Burdall & Hard Bolt & Nut Co.

Watershed.

Watershed tributary to the Felt Co. dam is 27.35 sq. mi. and to the R. B. & W. dam 27.75 sq. mi., both approximate. Water is diverted from the watershed at two points; by New York City on the west branch of the Byram at the State Line and on the east branch by the Greenwich Water Co. above Old Mill Road.

Estimated flood flow on July 23, 1938 and Sept. 21, 1938, both of the same magnitude, was approximately 2000 cubic feet per second. Had both tunnels been closed, the flow would have been

approximately 2200 c.f.s.

The watershed, from a runoff viewpoint, is undeveloped. Quicker runoff with higher flood stages is to be expected in the future due to swamp clearance and drainage, construction of storm drains, buildings, pavements, and other impervious surfaces.

Using the Fuller formula with a watershed constant of 60 and time frequency of 1000 a maximum rate of runoff is obtained of 5200 cubic feet per second or more than twice the flood flow of the floods of July and September. This is not an unreasonable flood to expect sometime in the future, particularly considering the comparatively small area of the watershed. Had the center of the hurricane of September passed along the Byram watershed, this flow would have been obtained.

#### Plans.

No construction plans of the dams are known to be in existence. The Reynolds and Felt Co. dams are evidently by their appearance quite old. The original R. B. & W. dam quite likely failed in the flood of October 9, 1877 when precipitation was 9.7 inches in 10.5 hours at White Plains, N. Y. It is reasonable to presume the present R. B. & W. dam was built shortly thereafter.

Back profiles of sections of dams at maximum height were obtained by sounding from a boat with an iron rod through water and silt, consequently sections are approximate. Condition of toe of R. B. & W. dam was investigated in the same manner.

#### Reynolds Dam.

This dam is a typical dry rubble overflow dam with vertical



face, originally with a tight-line and probably an impact platform. Abutments are against ledge rock. Headrace ends in a wooden bulkhead in poor condition. Old mill has been razed. The pond formed by the dam is shallow due to silting and impounds about 5 acre feet.

The dam is a small affair in poor condition and unless repaired will go out during some freshet. Failure will be comparatively slow; the dam will not give way all at once. For this reason and since only a small amount of water is retained by the dam, no serious harm will be done.

#### Felt Co. Dam.

This dam is located 1700'± below the Reynolds dam and 3300'± above the R. B. & W. dam. Principal dimensions are as follows:-

Crest length	200'±
Spillway length	49'
Maximum height at spillway	30'
Top width at spillway	15'
Bottom width at spillway	19'±
Freeboard	4.75 Aver.
Area of pond	2.6± Ac.
Capacity of pond (silted)	6± Ac. ft.

The dam is constructed of cement rubble masonry with a vertical face. The back, as nearly as could be determined by soundings, is stopped. The spillway section is arched in plan with a face radius of 65'. The east abutment has considerable mass and is backed by a retaining wall, perpendicular to the dam, with heavy fill in back of retaining wall and between dam and mill building. The west abutment has not sufficient mass nor is the plan proper to take arch thrust. Consequently the dam should be considered as a gravity section disregarding arch action.

Impact of overflow at spillway is taken by exposed ledge rock and there is no danger of concealed underscour. It is believed the main portion of the dam is on ledge rock. The extreme ends may not be.

The spillway is inadequate. The crest was topped by a few inches during the floods of 1938. If spillway length remains the same and crest length is held to 185' by building up ends, it is probable a future flood would have a still water height of about 2.5' above crest of dam and about 7.3 above spillway. Length of spillway should be increased by extending same to the west.

Under the conditions stated above and considered as a gravity section, the resultant of forces acting on the dam falls well outside the middle third and while the dam is theoretically safe against overturning, there is probable tension in masonry in the back of the dam. There is not the margin of safety indicated by good practice, particularly when the condition of the masonry in the interior of the dam is unknown. The dam can be strengthened by additional masonry along the downstream face.

Trees have been allowed to grow on and close to the dam. This should not be allowed account of root action.

There is a collecting trough along the east portion of the dam to take overtopping. If this was not included in the original design, it was built as the result of some experience in the past. The bottom of this trough should be paved to prevent scouring.

If the building on the downstream side of the west end of

the dam is to be protected, a similar trough should be constructed along the west portion of the dam.

An extraordinary flood would probably cut around the ends of the dam, particularly the west end. This might result in progressive undermining of the ends of the dam and final failure. To prevent this, ends of dam should be raised and carried back into solid ground.

There is a leak through the bottom of the sluiceway under the easterly portion of the spillway. This should be repaired. The old sluiceway in the western portion of the dam is not used and should be closed with masonry.

The fact that a dam has stood for a long period of years should not of itself give assurance the dam will withstand all future floods. To refute this idea there is the evidence, throughout New England, of numerous neglected dams that have failed. An old dam requires frequent and thorough maintenance. Moreover, it is quite probable the particular watershed has not been subject to a serious flood condition for a period far beyond the memory of the oldest inhabitant.

To place the dam in better condition the following is recommended:- Lengthen spillway - Additional masonry to increase section - Remove trees - Pave east collecting trough - Construct similar trough along west end - Build up ends of dam to prevent end scour - Repair leak - Close up old sluiceway - Careful maintenance.

The volume impounded by this dam is small, the distance to the R. B. & V. dam is 3300 feet mostly still water, area

of the R. B. & W. pond is 5.5± acres, surge would flatten out quickly and still water level at the R. B. & W. dam would be only slightly raised. Should the dam fail, loss or damage would be confined to the American Felt Co. and the Pemberwick flood plain would not suffer loss or damage.

R. B. & W. Dam. (PEMBERWICK)

This dam is located 3300'± below the Felt Co. dam and immediately above the flood plain section of "Pemberwick". Principal dimensions are as follows:-

Crest length	115'
Spillway length	63'
Maximum height at spillway	41'
Top width at spillway	8'
Bottom width at spillway	17'±
Freeboard	3.5
Area of pond	5.5± Ac.
Capacity of pond (silted)	29± Ac. ft.

This is an arch dam, between ledge rock abutments, in a narrow gorge with nearly vertical sides. Face of dam is vertical and face radius of arch is 180'±. Face masonry is coursed ashlar and is a wonderful piece of work. Entire visible portion of dam is on ledge rock. As nearly as could be determined by sounding with iron rods from a boat in the spillway pool, overflow impact is taken by ledge rock and there was no underscouring of the dam that could be found by prodding.

Still water height over spillway during recent floods was 4.3'±. The entire length of the dam acts as an overflow dam during floods with no danger of end scour.

The dam is safe in its present condition and will withstand

any flood it is reasonable to expect.

The stability of this type of dam, among other things, depends on tight contact with gorge walls and constant inter-contact of the various sections of the dam; and of course, as with any dam, underscouring must be prevented. Consequently this dam must be inspected periodically to determine (1) that gorge walls are not softening and that no leaks are developing around ends or along bottom; (2) that mortar in masonry joints has not seriously deteriorated and is in good condition; (3) that underscouring is not taking place.

It is recommended that the spillway pool be dewatered during the next low water stage of the river to determine by visual inspection the exact condition of the dam and foundation at the toe in the pool, and to determine whether or not repairs are necessary.

Conclusion.

It is our opinion that:-

The Reynolds dam is in poor condition and will fail during some freshet but the Pemberwick Section will not suffer loss or damage on account of such failure.

The Felt Co. dam may fail during some future flood but the Pemberwick Section will not suffer loss or damage on account of such failure.

The R. B. & H. dam is safe at present and will not

Greenwich Drainage Commission

- 8 -

fail under the action of any flood it is reasonable to expect,  
provided the dam is maintained in good condition.

Yours very truly,

State Board of Civil Engineers

By

Joseph W. Cone  
Member for Fourth District

Concurred in

Shepard B. Palmer  
Member for Second District


Clarence W. Blair  
Member for Third District

COPY

**APPENDIX B-3**

**RECORD DRAWINGS AND SKETCHES**


**NOTE:**  
 All Dimensions Shown  
 Are Plus Or Minus



**SECTION SHOWING OUTLETS**


SCALE: 1" = 10'

PEMBERWICK DAM

  
**JAMES P. PURDELL ASSOCIATES, INC.**  
 ENGINEERS • ARCHITECTS • PLANNERS



Pemberwick Dam



Reproduced from  
best available copy.




B-18



150


40  
30  
20  
10  
0

R7



R12

B-18 (2)



R7

R12

R20

RIVER WEST

RIVER RUN

UPPER HAWTHORNE

CENTRAL MILL

BLDG 21

LB

MILL POND


LOWER HAWTHORNE

R7  
American Felt Dam



LBR

3

B-18




REVISED BY K-71



**THE MILL**  
GREENWICH CT

**SITE PLAN**  
1" = 100'




SHEET REDUCED  
NOT TO SCALE

**B-18**

*4 of 4*

DATE: 11-22-72  
BY: MRS. C. L. V.

DONNY STREAM ELEVATION  
(feet)





Lease

①

P<sub>L</sub>

004-STREAM ELEVATION P. S. & W. DAM 1"=10' High water 4.34' at peak  
 (has)



PLAN 1"=10'


(2)

34.27 peak

E. 15'

Sill water Sep. 21, 1938

4.85



Assumed

TRIBUTARY WATERSHED 2775 SQ. MI.

AREA POND 55 AC.

CAPACITY (silted) 29 ACFT.

3900' to FELT CO. DAM

-10.0

LRD. 20'

-3.40'

SHEET REDUCED  
NOT TO SCALE


(3) of (3)

1938  
BYRAM RIVER  
GREENWICH, CONN.

**APPENDIX C**

**PHOTOGRAPHS**





PEMBERWICK DAM  
PHOTO INDEX



C-1 EAST CREST AND SPILLWAY - LOOKING FROM SLOPE  
ABOVE WEST CREST




C-2 WEST CREST - LOOKING FROM EAST CREST



C-3 LEAKAGE AT DOWNSTREAM FACE OF WEST CREST




C-4 SPILLWAY AND LEAKAGE AT EAST END OF SPILLWAY



C-5 OUTLET WORKS CONTROL MECHANISM



C-6 SPILLWAY - LOOKING FROM DOWNSTREAM ON EAST BANK




C-7 MEAD SCHOOL AND FLOODWALL - LOOKING  
FROM EAST CREST




C-8 DOWNSTREAM CHANNEL - LOOKING NORTH  
FROM COMLY AVENUE

**APPENDIX D**

**HYDROLOGIC AND HYDRAULIC COMPUTATIONS**








# Limit Of Drainage Area

3



Damage Area

4

Limit Of Impact Area

Pemberwick Dam

VERMONT

FAIRFIELD CO.  
WESTCHESTER CO.

Glenville

Riversville

RIVERSVILLE

River

Toll Gate Pond

Willow Pond

Brook

St. John's Hospital

Widener Hospital

Mount of St. Sacrament

Robert Hill Laundry Plant


Glennville


Ridge

WATERBURY

LINCOLN

AVENUE





let Area

am

Pemberwick Ave

RIVER

PORT CHESTER

RY

Blind Brook

Brook

Greenwich

Belle Haven

Byram Harbor

Byram INTERCHANGE

Field Pt

Other Wilson

Home Cock

Farrells

W. Leblond

W. Leblond

W. Leblond

W. Leblond

W. Leblond

W. Leblond

W. Leblond

W. Leblond

W. Leblond


W. Leblond


W. Leblond


W. Leblond

W. Leblond

W. Leblond







Branch  
TONNETT  
550

Quaker  
Ridge

North  
Greenwich

WESTCHESTER CO  
HARTLED CO

NORTH CAROLINA


MOUNT  
PLEASANT


RESERVOIR  
KENSICO

KENSICO

Great Island

Wampum  
CA





PEMBERWICK DAM  
DRAINAGE AREA AND  
IMPACT AREA  
DATUM: NGVD  
QUADRANGLE SHEETS:  
MT. KISKO, NY-CT  
GLENVILLE, CT-NY  
SCALE: 1:24000  
PLATE NO. D-1



12.00 60.....10  
13.00 61.    1  
14.00 62.    1  
15.00 63.    1  
16.00 64.    1  
17.00 65.    1  
18.00 66.   10  
19.00 67.    1  
20.00 68.    1  
21.00 69.    1  
22.00 70...10  
23.00 71.    1  
0.00 72.    1  
1.00 73.    1  
2.00 74.    1  
3.00 75.    1

HYDROLOGIC AND HYDRAULIC ANALYSIS  
SUMMARY SHEET

Dam Pemberwick Dam

Test Flood PMF

INFLOW HYDROGRAPH DEVELOPMENT

Drainage Area 26.2 sq. mi.

Probable Maximum Precipitation  
24 hour - 200 square mile PMP 22 inches

Initial Rainfall Loss 0 Inch  
Uniform Rainfall loss .1 Inch

Snyder's Lag 7.31 hours  
Snyder's Peaking Coefficient .625

Test Flood Inflow 25600 CFS

PMF Inflow 25600 CFS

RESERVOIR ROUTING AND DAM OVERTOPPING

Test Flood Outflow 25600 CFS

Spillway Capacity at Top of Dam 1100 CFS  
4 % of Test Flood

Flow Over Spillway at Test Flood 15800 CFS

Spillway Crest Elevation	<u>76.5</u>	Feet
Top of Dam Elevation	<u>80.0</u>	Feet
Test Flood Elevation	<u>97.0</u>	Feet

FINAL

.....  
 FLOOD HYDROGRAPH PACKAGE (HEC-1)  
 DAM SAFETY VERSION JULY 1978  
 LAST MODIFICATION 26 FEB 79  
 .....

1 A1 DAM SAFETY ANALYSIS-JOR NO. 79-905/02-EHJ  
 2 A2 PEMREWICK DAM-GREENWICH-CONN  
 3 A3 12-05-79

4	R	75	1	0	0	0	0	2	0	0
5	A1	5								
6	J	1	2	1						
7	J1	.5	1	0	0	0	0	0	0	0
8	K	0	1	0	0	0	1	0	0	
9	K1									
10	M	1	1	26.2	0	26.2	0	0	0	1
11	P	0	22	100	114	124	132			
12	T	0	0	0	0	0	0	.1		
13	W	7.31	.625							
14	X	1.5	.05	2.0						
15	K	1	1	0	0	0	0	1		
16	K1									
17	Y	0	0	0	1	1	0	-1		0
18	Y1	1	0	0	0	0	0			
19	SA	5.5	8.5	11.5						
20	SE	76.5	85	95						
21	SS	76.5	63	2.7	1.5					
22	SD	80.0	2.7	1.5	52					
23	K		99							

.....  
 COMPUTATION OF PMF-DEVELOPMENT OF INFLOW HYDROGRAPH  
 ROUTING INFLOW HYDROGRAPH THRU LAKE-OVERTOPPING ANALYSIS  
 .....

PREVIEW OF SEQUENCE OF STREAM NETWORK CALCULATIONS

RUNOFF HYDROGRAPH AT 1  
ROUTE HYDROGRAPH TO 1  
END OF NETWORK

.....  
 FLOOD HYDROGRAPH PACKAGE (HEC-1)  
 DAM SAFETY VERSION JULY 1978  
 LAST MODIFICATION 26 FEB 79  
 .....

RUN DATE 12/06/79.  
 TIME 15.05.40.

DAM SAFETY ANALYSIS-JOB NO. 79-905/02-ERJ  
 PENRFRICK DAM-GREENWICH-CONN  
 12-05-79

JOB SPECIFICATION									
NO	NHR	NMWN	IDAY	IHR	IMIN	METRC	IPLT	IPRT	NSTAN
75	1	0	0	0	0	0	2	0	0
			JOPER	NWT	LROPT	TRACE			
			5	0	0	0			

MULTI-PLAN ANALYSES TO BE PERFORMED  
 NPLAN= 1 NRTIO= 2 LRTIO= 1

RTIOS= .50 1.00

\*\*\*\*\*

SUB-AREA RUNOFF COMPUTATION

COMPUTATION OF PMF-DEVELOPMENT OF INFLOW HYDROGRAPH

ISTAO	ICOMP	IECON	ITAPP	JPLT	JPRT	INAME	ISTAGE	IAUTO
1	0	0	0	0	0	1	0	0

HYDROGRAPH DATA

SPFE	PMS	R6	R12	R24	R48	R72	R96
0.00	22.00	100.00	114.00	124.00	132.00	0.00	0.00

TRSPC COMPUTED BY IMF PROGRAM IS .831

LOSS DATA

LROPT	STRKR	DLTKR	HTIOL	ERAIN	STRKS	RTIOK	STRTL	CNSTL	ALSMX	RTIMP
0	0.00	0.00	1.00	0.00	0.00	1.00	0.00	.10	0.00	0.00

UNIT HYDROGRAPH DATA

IP= 7.31 CP= .63 NTA= 0

RECESSION DATA

STRTQ= 1.50 GRCSN= .05 RTIO= 2.00  
 APPROXIMATE CLARK COEFFICIENTS FROM GIVEN SNYDER CP AND IP ARE IC= 8.40 AND R= 6.66 INTERVALS

UNIT	HYDROGRAPH	40 END-OF-PERIOD	ORDINATES,	LAG=	7.28	HOURS,	CP=	.63	VOL=	1.00
69.	253.	505.	749.	1073.	1300.	1435.	1472.	1379.	1204.	
1036.	891.	767.	660.	568.	488.	420.	362.	311.	268.	

1.01	1.00	1	.01	0.00	.01	1.	1.02	14.00	38	2.19	2.09	.10	2957.
1.01	2.00	2	.01	0.00	.01	1.	1.02	15.00	39	2.74	2.64	.10	4215.
1.01	3.00	3	.01	0.00	.01	1.	1.02	16.00	40	6.95	6.85	.10	6299.
1.01	4.00	4	.01	0.00	.01	1.	1.02	17.00	41	2.56	2.46	.10	9448.
1.01	5.00	5	.01	0.00	.01	1.	1.02	18.00	42	2.01	1.91	.10	13345.
1.01	6.00	6	.01	0.00	.01	1.	1.02	19.00	43	.18	.08	.10	17492.
1.01	7.00	7	.03	0.00	.03	1.	1.02	20.00	44	.18	.08	.10	21305.
1.01	8.00	8	.03	0.00	.03	1.	1.02	21.00	45	.18	.08	.10	24138.
1.01	9.00	9	.03	0.00	.03	1.	1.02	22.00	46	.18	.08	.10	25583.
1.01	10.00	10	.03	0.00	.03	1.	1.02	23.00	47	.18	.08	.10	25577.
1.01	11.00	11	.03	0.00	.03	1.	1.03	0.00	48	.18	.08	.10	24155.
1.01	12.00	12	.03	0.00	.03	1.	1.03	1.00	49	0.00	0.00	0.00	21792.
1.01	13.00	13	.12	.02	.10	2.	1.03	2.00	50	0.00	0.00	0.00	19171.
1.01	14.00	14	.14	.04	.10	8.	1.03	3.00	51	0.00	0.00	0.00	16676.
1.01	15.00	15	.18	.08	.10	25.	1.03	4.00	52	0.00	0.00	0.00	14469.
1.01	16.00	16	.45	.35	.10	79.	1.03	5.00	53	0.00	0.00	0.00	12537.
1.01	17.00	17	.17	.07	.10	184.	1.03	6.00	54	0.00	0.00	0.00	10843.
1.01	18.00	18	.13	.03	.10	324.	1.03	7.00	55	0.00	0.00	0.00	9358.
1.01	19.00	19	.01	0.00	.01	478.	1.03	8.00	56	0.00	0.00	0.00	8059.
1.01	20.00	20	.01	0.00	.01	627.	1.03	9.00	57	0.00	0.00	0.00	6934.
1.01	21.00	21	.01	0.00	.01	743.	1.03	10.00	58	0.00	0.00	0.00	5966.
1.01	22.00	22	.01	0.00	.01	809.	1.03	11.00	59	0.00	0.00	0.00	5133.
1.01	23.00	23	.01	0.00	.01	820.	1.03	12.00	60	0.00	0.00	0.00	4417.
1.02	0.00	24	.01	0.00	.01	771.	1.03	13.00	61	0.00	0.00	0.00	3800.
1.02	1.00	25	.12	.02	.10	686.	1.03	14.00	62	0.00	0.00	0.00	3270.
1.02	2.00	26	.12	.02	.10	600.	1.03	15.00	63	0.00	0.00	0.00	2813.
1.02	3.00	27	.12	.02	.10	529.	1.03	16.00	64	0.00	0.00	0.00	2420.
1.02	4.00	28	.12	.02	.10	475.	1.03	17.00	65	0.00	0.00	0.00	2082.
1.02	5.00	29	.12	.02	.10	437.	1.03	18.00	66	0.00	0.00	0.00	1791.
1.02	6.00	30	.12	.02	.10	413.	1.03	19.00	67	0.00	0.00	0.00	1541.
1.02	7.00	31	.43	.33	.10	420.	1.03	20.00	68	0.00	0.00	0.00	1326.
1.02	8.00	32	.43	.33	.10	490.	1.03	21.00	69	0.00	0.00	0.00	1140.
1.02	9.00	33	.43	.33	.10	641.	1.03	22.00	70	0.00	0.00	0.00	981.
1.02	10.00	34	.43	.33	.10	879.	1.03	23.00	71	0.00	0.00	0.00	840.
1.02	11.00	35	.43	.33	.10	1204.	1.04	0.00	72	0.00	0.00	0.00	719.
1.02	12.00	36	.43	.33	.10	1598.	1.04	1.00	73	0.00	0.00	0.00	615.
1.02	13.00	37	1.83	1.73	.10	2130.	1.04	2.00	74	0.00	0.00	0.00	525.
							1.04	3.00	75	0.00	0.00	0.00	448.

SUM 24.14 20.86 3.28 349564.  
( 613.1( 530.1( R3.1( 9898.55)

CFS	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
25583.	25583.	23580.	13076.	4852.	349342.
INCHES	724.	668.	370.	137.	9892.
MM		8.37	18.57	20.67	20.67
AC-FT		212.65	471.69	525.07	525.08
THOUS CU M		11693.	25936.	28871.	28871.
		14423.	31992.	35612.	35612.

0048

STATION 1

	0.	4000.	8000.	12000.	16000.	20000.	24000.	28000.	0.	0.	0.	0.	0.	0.
		INFLOW(I).	OUTFLOW(O)	AND OBSERVED FLOW(I*)						PRECIP(L) AND EXCESS(X)				
		0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
1.00	11	.	.	.	.	.	.	.	.	.	.	.	.	L
2.00	21	.	.	.	.	.	.	.	.	.	.	.	.	L
3.00	31	.	.	.	.	.	.	.	.	.	.	.	.	L
4.00	41	.	.	.	.	.	.	.	.	.	.	.	.	L
5.00	51	.	.	.	.	.	.	.	.	.	.	.	.	L
6.00	61	.	.	.	.	.	.	.	.	.	.	.	.	L
7.00	71	.	.	.	.	.	.	.	.	.	.	.	.	L
8.00	81	.	.	.	.	.	.	.	.	.	.	.	.	L
9.00	91	.	.	.	.	.	.	.	.	.	.	.	.	L
10.00	101	.	.	.	.	.	.	.	.	.	.	.	.	L
11.00	111	.	.	.	.	.	.	.	.	.	.	.	.	L
12.00	121	.	.	.	.	.	.	.	.	.	.	.	.	L
13.00	131	.	.	.	.	.	.	.	.	.	.	.	.	LX
14.00	141	.	.	.	.	.	.	.	.	.	.	.	.	LX
15.00	151	.	.	.	.	.	.	.	.	.	.	.	.	LX
16.00	161	.	.	.	.	.	.	.	.	.	.	.	.	LXX
17.00	171	.	.	.	.	.	.	.	.	.	.	.	.	LX
18.00	181	.	.	.	.	.	.	.	.	.	.	.	.	LX
19.00	191	.	.	.	.	.	.	.	.	.	.	.	.	L
20.00	201	.	.	.	.	.	.	.	.	.	.	.	.	L
21.00	211	.	.	.	.	.	.	.	.	.	.	.	.	L
22.00	221	.	.	.	.	.	.	.	.	.	.	.	.	L
23.00	231	.	.	.	.	.	.	.	.	.	.	.	.	L
0.00	241	.	.	.	.	.	.	.	.	.	.	.	.	L
1.00	251	.	.	.	.	.	.	.	.	.	.	.	.	L
2.00	261	.	.	.	.	.	.	.	.	.	.	.	.	LX
3.00	271	.	.	.	.	.	.	.	.	.	.	.	.	LX
4.00	281	.	.	.	.	.	.	.	.	.	.	.	.	LX
5.00	291	.	.	.	.	.	.	.	.	.	.	.	.	LX
6.00	301	.	.	.	.	.	.	.	.	.	.	.	.	LX
7.00	311	.	.	.	.	.	.	.	.	.	.	.	.	LXX
8.00	321	.	.	.	.	.	.	.	.	.	.	.	.	LXX
9.00	331	.	.	.	.	.	.	.	.	.	.	.	.	LXX
10.00	341	.	.	.	.	.	.	.	.	.	.	.	.	LXX
11.00	351	.	.	.	.	.	.	.	.	.	.	.	.	LXX
12.00	361	.	.	.	.	.	.	.	.	.	.	.	.	LXX
13.00	371	.	.	.	.	.	.	.	.	.	.	.	.	LXX
14.00	381	.	.	.	.	.	.	.	.	.	.	.	.	LXX
15.00	391	.	.	.	.	.	.	.	.	.	.	.	.	LXX
16.00	401	.	.	.	.	.	.	.	.	.	.	.	.	LXX
17.00	411	.	.	.	.	.	.	.	.	.	.	.	.	LXX
18.00	421	.	.	.	.	.	.	.	.	.	.	.	.	LXX
19.00	431	.	.	.	.	.	.	.	.	.	.	.	.	LXX
20.00	441	.	.	.	.	.	.	.	.	.	.	.	.	LXX
21.00	451	.	.	.	.	.	.	.	.	.	.	.	.	LXX
22.00	461	.	.	.	.	.	.	.	.	.	.	.	.	LXX
23.00	471	.	.	.	.	.	.	.	.	.	.	.	.	LXX
0.00	481	.	.	.	.	.	.	.	.	.	.	.	.	LXX
1.00	491	.	.	.	.	.	.	.	.	.	.	.	.	LXX
2.00	501	.	.	.	.	.	.	.	.	.	.	.	.	LXX
3.00	511	.	.	.	.	.	.	.	.	.	.	.	.	LXX
4.00	521	.	.	.	.	.	.	.	.	.	.	.	.	LXX





•OVNS•

HYDROGRAPH AT STA		1 FOR PLAN 1, RTIO 1	
1.	1.	1.	0.
0.	4.	13.	40.
372.	386.	343.	300.
210.	439.	602.	799.
4724.	10652.	12791.	12789.
8338.	6268.	5421.	4679.
1900.	1407.	1210.	1041.
420.	308.	243.	224.

HYDROGRAPH AT STA		1 FOR PLAN 1, RTIO 2	
1.	1.	1.	1.
1.	8.	25.	79.
743.	809.	771.	600.
420.	490.	1204.	1598.
9448.	13345.	21305.	24138.
16776.	14469.	9358.	8059.
3800.	3270.	2420.	1791.
840.	719.	525.	448.

HYDROGRAPH AT STA		1 FOR PLAN 1, RTIO 1	
1.	1.	1.	0.
0.	13.	40.	92.
162.	239.	2107.	10896.
206.	219.	2567.	2208.
3150.	2107.	12077.	2983.
9586.	10896.	663.	570.
2208.	2567.	663.	570.
490.	570.	663.	570.

HYDROGRAPH AT STA		1 FOR PLAN 1, RTIO 2	
1.	1.	1.	1.
1.	8.	25.	79.
627.	478.	324.	475.
413.	437.	475.	4215.
6299.	4215.	2957.	21792.
19171.	21792.	24155.	5966.
4417.	5133.	1326.	1140.
981.	1140.	1326.	1140.

\*\*\*\*\*

HYDROGRAPH ROUTING

ROUTING INFLOW HYDROGRAPH THRU LAKE-OVERTOPPING ANALYSIS

ISTAO	ICOMP	IECON	ITAPE	JPLT	JPRT	INAME	ISTAGE	IAUTO
1	1	0	0	0	0	1	0	0
ROUTING DATA								
QLOSS	CLOSS	AVG	IPRES	ISAME	IOPT	IPMP	LSTR	
0.0	0.000	0.00	1	1	0	0		
*****								
NSTPS	NSTDLL	LAG	AMSKK	X	TSK	STORA	ISPRAT	
1	0	0	0.000	0.000	0.000	-1.	0	
*****								
SURFACE AREA= 6. 9. 12.								

CREL SPWID COOW EXPW ELEV COOL CAREA EXPL  
 76.5 63.0 2.7 1.5 0.0 0.0 0.0

DAM DATA  
 TOPEL COOD EXPD DAMWID  
 80.0 2.7 1.5 52.

STATION 1, PLAN 1, RATIO 1

END-OF-PERIOD HYDROGRAPH ORDINATES

0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
360.	411.	393.	353.	310.	24.	69.	139.	219.	296.
208.	300.	410.	567.	761.	1014.	273.	244.	203.	209.
4567.	8582.	10515.	11982.	12761.	12812.	1014.	1413.	2031.	3026.
8433.	6344.	5489.	4740.	4084.	3516.	12812.	12153.	10996.	9687.
1931.	1433.	1235.	1067.	920.	792.	3026.	3026.	2605.	2243.
434.	372.	273.	233.			682.	587.	506.	

STORAGE

0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	1.	6.	24.	69.	139.	219.	296.
9.	10.	10.	9.	9.	9.	8.	7.	7.	8.
6.	7.	8.	13.	16.	20.	25.	30.	39.	39.
50.	64.	78.	100.	104.	105.	101.	93.	85.	85.
77.	70.	63.	57.	52.	47.	43.	39.	32.	32.
30.	27.	25.	21.	18.	17.	15.	13.	12.	12.
11.	10.	9.	7.						

STAGE

76.5	76.5	76.5	76.5	76.5	76.5	76.5	76.5	76.5	76.5
76.5	76.5	76.5	76.6	76.8	76.5	76.5	76.5	76.5	76.5
78.1	78.3	78.2	78.1	78.0	77.9	77.4	77.7	77.7	77.9
77.6	77.7	78.0	78.7	79.2	79.8	80.5	81.3	82.5	82.5
84.0	85.6	87.1	88.5	89.4	90.0	89.5	88.8	87.9	87.9
87.0	86.2	85.5	84.8	84.1	83.5	82.5	82.0	81.6	81.6
81.2	80.9	80.5	80.2	79.9	79.6	79.0	78.0	78.0	78.6
78.4	78.2	78.0	77.9	77.7					

PEAK OUTFLOW IS 12812. AT TIME 47.00 HOURS

CFS	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
12812.	12812.	11801.	6537.	2425.	1745H6.
	363.	334.	185.	69.	4944.
		4.19	9.28	10.33	10.33
		106.42	235.80	262.41	262.41
		5852.	12965.	14429.	14429.
		7218.	15993.	17797.	17797.

THOUS CU M

•OVF•

STATION 1

	0.	2000.	4000.	6000.	8000.	10000.	12000.	14000.	0.	0.	0.	0.	0.
1.00	I	.	.	.	.	.	.	.	.	.	.	.	.
2.00	2I	.	.	.	.	.	.	.	.	.	.	.	.
3.00	3I	.	.	.	.	.	.	.	.	.	.	.	.
4.00	4I	.	.	.	.	.	.	.	.	.	.	.	.
5.00	5I	.	.	.	.	.	.	.	.	.	.	.	.
6.00	6I	.	.	.	.	.	.	.	.	.	.	.	.
7.00	7I	.	.	.	.	.	.	.	.	.	.	.	.
8.00	8I	.	.	.	.	.	.	.	.	.	.	.	.
9.00	9I	.	.	.	.	.	.	.	.	.	.	.	.
10.00	10I	.	.	.	.	.	.	.	.	.	.	.	.
11.00	11I	.	.	.	.	.	.	.	.	.	.	.	.
12.00	12I	.	.	.	.	.	.	.	.	.	.	.	.
13.00	13I	.	.	.	.	.	.	.	.	.	.	.	.
14.00	14I	.	.	.	.	.	.	.	.	.	.	.	.
15.00	15I	.	.	.	.	.	.	.	.	.	.	.	.
16.00	16I	.	.	.	.	.	.	.	.	.	.	.	.
17.00	17I	.	.	.	.	.	.	.	.	.	.	.	.
18.00	18.I	.	.	.	.	.	.	.	.	.	.	.	.
19.00	19.I	.	.	.	.	.	.	.	.	.	.	.	.
20.00	20.OI	.	.	.	.	.	.	.	.	.	.	.	.
21.00	21. I	.	.	.	.	.	.	.	.	.	.	.	.
22.00	22. I	.	.	.	.	.	.	.	.	.	.	.	.
23.00	23. I	.	.	.	.	.	.	.	.	.	.	.	.
0.00	24. I	.	.	.	.	.	.	.	.	.	.	.	.
1.00	25. I	.	.	.	.	.	.	.	.	.	.	.	.
2.00	26. I	.	.	.	.	.	.	.	.	.	.	.	.
3.00	27.I	.	.	.	.	.	.	.	.	.	.	.	.
4.00	28.I	.	.	.	.	.	.	.	.	.	.	.	.
5.00	29.I	.	.	.	.	.	.	.	.	.	.	.	.
6.00	30.I	.	.	.	.	.	.	.	.	.	.	.	.
7.00	31.I	.	.	.	.	.	.	.	.	.	.	.	.
8.00	32.I	.	.	.	.	.	.	.	.	.	.	.	.
9.00	33.OI	.	.	.	.	.	.	.	.	.	.	.	.
10.00	34. I	.	.	.	.	.	.	.	.	.	.	.	.
11.00	35. I	.	.	.	.	.	.	.	.	.	.	.	.
12.00	36. I	.	.	.	.	.	.	.	.	.	.	.	.
13.00	37. I	.	.	.	.	.	.	.	.	.	.	.	.
14.00	38. I	.	.	.	.	.	.	.	.	.	.	.	.
15.00	39. I	.	.	.	.	.	.	.	.	.	.	.	.
16.00	40.OI	.	.	.	.	.	.	.	.	.	.	.	.
17.00	41. OI	.	.	.	.	.	.	.	.	.	.	.	.
18.00	42. I	.	.	.	.	.	.	.	.	.	.	.	.
19.00	43. OI	.	.	.	.	.	.	.	.	.	.	.	.
20.00	44. I	.	.	.	.	.	.	.	.	.	.	.	.
21.00	45. I	.	.	.	.	.	.	.	.	.	.	.	.
22.00	46. I	.	.	.	.	.	.	.	.	.	.	.	.
23.00	47. I	.	.	.	.	.	.	.	.	.	.	.	.
0.00	48. I	.	.	.	.	.	.	.	.	.	.	.	.
1.00	49. I	.	.	.	.	.	.	.	.	.	.	.	.
2.00	50. I	.	.	.	.	.	.	.	.	.	.	.	.
3.00	51. I	.	.	.	.	.	.	.	.	.	.	.	.
4.00	52. I	.	.	.	.	.	.	.	.	.	.	.	.
5.00	53. I	.	.	.	.	.	.	.	.	.	.	.	.
6.00	54. I	.	.	.	.	.	.	.	.	.	.	.	.

STATION 1. PLAN 1. RATIO 2  
END-OF-PERIOD HYDROGRAPH ORDINATES

OUTFLOW	
0.	1.
1.	1.
724.	821.
416.	830.
9165.	13037.
16852.	14622.
3852.	3316.
864.	740.
1.	1.
1.	148.
445.	288.
417.	485.
6085.	444.
19363.	4083.
4476.	21982.
1008.	5200.
	1165.

STORAGE	
0.	0.
0.	0.
16.	17.
11.	11.
82.	106.
129.	116.
45.	41.
18.	16.
0.	0.
0.	1.
15.	15.
17.	14.
22.	22.
131.	172.
104.	84.
37.	31.
14.	11.
0.	0.
0.	3.
14.	14.
31.	26.
182.	182.
84.	75.
31.	29.
11.	11.
0.	0.
0.	8.
11.	11.
11.	11.
47.	47.
160.	174.
145.	61.
50.	55.
20.	22.

STAGE	
76.5	76.5
76.5	76.5
79.1	79.1
78.3	78.5
87.6	90.1
92.4	91.1
83.3	82.3
79.5	79.2
76.5	76.5
76.5	77.4
79.4	78.9
78.5	80.7
92.6	96.2
89.9	87.8
82.3	81.4
78.9	78.7
76.5	76.5
76.5	77.9
79.4	78.5
78.8	82.3
92.6	96.3
89.9	85.2
82.3	80.4
78.9	80.1

PEAK OUTFLOW IS 25622. AT TIME 47.00 HOURS

CFS	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
25622.	23601.	13074.	4850.	349205.	
726.	668.	370.	137.	988.	
	8.38	18.57	20.66	20.66	
	212.84	471.63	524.87	524.87	
	11703.	25932.	28860.	28860.	
	14435.	31987.	35598.	35598.	

INCHES  
MH  
AC-FT  
THOUS CU M

•OVF•

STATION 1

	0.	4000.	8000.	12000.	16000.	20000.	24000.	28000.	0.	0.	0.	0.	0.
1.00	11												
2.00	21												
3.00	31												
4.00	41												
5.00	51												
6.00	61												
7.00	71												
8.00	81												
9.00	91												
10.00	101												
11.00	111												
12.00	121												
13.00	131												
14.00	141												
15.00	151												
16.00	161												
17.00	171												
18.00	18.1												
19.00	19.1												
20.00	20.01												
21.00	21.1												
22.00	22.1												
23.00	23.1												
0.00	24.1												
1.00	25.1												
2.00	26.1												
3.00	27.1												
4.00	28.1												
5.00	29.1												
6.00	30.1												
7.00	31.1												
8.00	32.1												
9.00	33.1												
10.00	34.1												
11.00	35.1												
12.00	36.1												
13.00	37.1												
14.00	38.1												
15.00	39.1												
16.00	40.01												
17.00	41.1												
18.00	42.1												
19.00	43.1												
20.00	44.1												
21.00	45.1												
22.00	46.1												
23.00	47.1												
0.00	48.1												
1.00	49.1												
2.00	50.1												
3.00	51.1												
4.00	52.1												
5.00	53.1												
6.00	54.1												

LINE	QTY	UNIT	PRICE	AMOUNT	TAX	TOTAL	DATE
12.00	60						
13.00	61						
14.00	62	I					
15.00	63	I					
16.00	64	I					
17.00	65	I					
18.00	66	I					
19.00	67	I					
20.00	68	I					
21.00	69	I					
22.00	70	10					
23.00	71	I					
0.00	72	I					
1.00	73	I					
2.00	74	I					
3.00	75	I					

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS  
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)  
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

RATIOS APPLIED TO FLOWS

OPERATION	STATION	AREA	PLAN RATIO	RATIO 1	RATIO 2
				.50	1.00
HYDROGRAPH AT	1	26.20 ( 67.86)	1	12791. ( 362.21)	25583. ( 724.42)
ROUTED TO	1	26.20 ( 67.86)	1	12812. ( 362.79)	25622. ( 725.52)

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1 .....	ELEVATION STORAGE	INITIAL VALUE	SPILLWAY CREST	TOP OF DAM
	OUTFLOW	76.50	76.50	80.00
		0.	0.	21.
		0.	0.	1114.

RATIO OF PMF	MAXIMUM RESERVOIR W.S.ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
.50	89.96	9.96	105.	12812.	27.00	47.00	0.00
1.00	97.00	17.00	182.	25622.	35.00	47.00	0.00



A. Size ClassificationHeight of dam = 45 ft.; hence intermediateStorage capacity at top of dam (elev. 80.0) = 60 AC-FT.; hence smallAdopted size classification intermediateB.i) Hazard Potential

This dam is located upstream of Pemberwick, an urbanized area. Residential homes are located along the downstream channel. Mead School and a commercial building also are located along the channel.

ii) Impact of Failure of Dam at Maximum Pool (Top of Dam)

It is estimated from the "rule of thumb" failure hydrograph, that the following adverse impacts are a possibility by the failure of this dam.

- a) Loss of homes Over 5 ;  
 b) Loss of buildings 1-2 ;  
 c) Loss of highways or roads None ;  
 d) Loss of bridges None ;

The failure profile can affect a distance of 3000 feet from the dam.

C. Hazard Potential Classifications

<u>HAZARD</u>	<u>SIZE</u>	<u>TEST FLOOD RANGE</u>
<u>High</u>	<u>Intermediate</u>	<u>PMF</u>
Adopted Test Flood =	<u>PMF</u>	= <u>1010</u> CSM
		= <u>26500</u> CFS

D. Overtopping PotentialDrainage Area 16,777 Acres = 26.2 sq. milesSpillway crest elevation = 76.5 NGVDTop of Dam Elevation = 80.0 NGVDMaximum spillway dischargeCapacity without overtopping of dam = 1100 CFS"test flood" inflow discharge = 26500 CFS"test flood" outflow discharge = 26500 CFS

PEMBERWICK DAM

Dam Failure Analysis

1. Failure discharge with pool at top of dam (elev. 80.0) = 8350 CFS
2. Depth of water in reservoir at time of failure = 36 ft.
3. Maximum depth of flow downstream of dam = 11.5 ft.
4. Water surface elevation just downstream) of dam at time of failure ) = 51.5 NGVD

The failure discharge of 8350 CFS will enter and flow downstream 3,000 feet until the brook enters a pond on Byram River. Valley storage in this 3,000 foot length of brook is substantial in reducing the discharge. Also due to roughness characteristics, obstructions and frictional losses, it is very likely that the unsteady dam failure flow will dissipate its wave and kinetic energy and thus convert to steady and uniform flow obeying Manning's formulae 3000 feet downstream. The failure profile will have the following hydraulic characteristics:

DISTANCE FROM THE DAM	WATER SURFACE ELEVATION NGVD	REMARKS
0'	80.0	Upstream of dam
0'	51.5	Downstream of dam
1000'	41.5	
2000'	31.5	
3000'	10.0	@ Pond

Beyond 3,000 feet, failure discharge will flow in the below given channel characteristics:

Q = 3158 CFS; S = .007  
 n = 0.05; b = 300; d = 3<sup>±</sup>

Side slopes = 1V or 2H.

AD-A142 702

NATIONAL DAM INSPECTION PROGRAM PEMBERWICK DAM (CT  
00042) SOUTHWESTERN CO. (U) CORPS OF ENGINEERS WALTHAM  
MA NEW ENGLAND DIV FEB 80


2/2

UNCLASSIFIED

FFG 13/13

NL





MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A

"Rule of Thumb Guidance for Estimating  
Downstream Dam Failure Analysis"

DATA

Name of Dam Pemberwick Dam  
Location North of Pemberwick, CT.  
Drainage Area 26.2 sq. mi., Top of Dam 80.0 NGVD  
Spillway Type Overflow-broad crest, Crest of Spillway 76.5 NGVD  
Surface Area @ Crest Elev. 5.5 Acres = .009 sq. mi.  
Pool Bottom Near Dam = 44 ± NGVD  
Assumed Side Slopes of Embankments = 1:1  
Depth of Pool at Dam (Yo) = 36 Feet  
Mid-Height Elev. 62 NGVD  
Length of Dam at Crest = 115 Feet  
Length of Dam at Mid-Height = 93 Feet  
% of Dam Length at Mid-Height =  $W_b$  = 23 Feet

Step 1

Storage (S) at time of failure 60 Ac-FT  
(Equal to top of dam)

Step 2

Peak Failure Discharge  
 $Q_{p1} = 8/27 W_b \sqrt{g} Y_o^{3/2}$   
= 1.68  $W_b Y_o^{3/2}$  = 8346 cfs


Failure is assumed to coincide with pool elevation at top of dam.

No Name Pond is located 3000 feet downstream of Pemberwick dam. There is a 35 foot drop into No Name pond which will cause the dissipation of wave and kinetic energy of the failure discharge. Approximately, the water surface elevations between Pemberwick dam and No Name pond will be as given on Dam Failure Analysis. The increase of depth in No Name pond due to failure of Pemberwick dam is estimated to be 1-2 feet.

DOWNSTREAM W.S.E.L. COMPS

PEMBERWICK DAM

SECTION - 0+00 (DOWNSTREAM FACE OF DAM)




$n = .05$

$S = .01 \frac{1}{4}$   $Q_P = 8346 \text{ cfs}$

FIND DEPTH & STORAGE FOR  $Q_P$

$Q = 1.486/n A R^{2/3} S^{1/2}$

ELEV	AREA	WP	R	$R^{2/3}$	S	$S^{1/2}$	1.486	n	Q
60	1200	95	12.63	5.42	.01	0.1	29.72		19,330
50	550	72	7.64	3.88	.01	0.1	29.72		6,340
55	875	83.5	10.48	4.79	.01	0.1	29.72		12,454



DEPTH @ DOWNSTREAM FACE OF DAM  
 EQUAL TO 11.5' OR EL 51.5


NEXT DOWNSTREAM SECTION AT 10+00

STORAGE DOES NOT CHANGE

DOWNSTREAM WSEL COMPS


PEMBERWICK DAM

SECTION - 10+00 DOWNSTREAM OF DAM



$n = .05$   
 $S = .01\%$   $Q_{P1} = 8346 \text{ cfs}$

ELEV	AREA	WP	R	$R^{2/3}$	$S^{1/2}$	$1.486/n$	Q	DEPTH
EL 45	2025	405	5	2.92	.1	29.72	17,599	10'
EL 42	987	282	3.5	2.3	.1	29.72	6,762	7'
EL 40	500	200	2.5	1.84	.1	29.72	1093	5'



$$V_1 = \frac{11.5 + 7.5}{2} \times \left( \frac{300 + 62}{2} \times 1000 \div 43560 \right) \times \frac{1}{2} = 19.8 \text{ AC-FT}$$

$19.8 > 51$  SECTION OK  $S = 51$

$$Q_{P2} (\text{TRIAL}) = Q_{P1} \left( 1 - \frac{V}{S} \right) = 5106 \text{ cfs}$$

$$V_2 = \frac{11.5 + 6.5}{2} \times 4.16 \times \frac{1}{2} = 18.7 \text{ AC-FT}$$

$$Q_{P2} = Q_{P1} \left( 1 - \frac{V_{AVE}}{S} \right) = 5196 \text{ cfs}$$

STAGE-DISCHARGE = 5196 WSEL = 41.5' D = 6.5'

NEXT DOWNSTREAM SECTION AT 20+00




**DOWNSTREAM W.S. EL. COMPUTATIONS**

NAME OF DAM: PENNYBUNCK


SECTION LOCATION: 2000' DOWNSTREAM OF DAM

USING:  $Q = 1.486/n A R^{2/3} S^{1/2}$   
 WHERE:  $n = 0.05$   $S = \text{SLOPE} = 0.0014$



$Q_{P1} = 5196$  cfs STORAGE (S) 51 AC-FT.

ELEV	AREA	V.P	R	$R^{2/3}$	$S^{1/2}$	$1.486/n$	Q	DEPTH
35	1188	325	3.66	2.37	.083	29.72	7001	10
40	1688	525	3.22	2.18	.083	29.72	9071	15
30	250	100	2.5	1.24	.083	29.72	1136	5



$V_1 = 6.5 \times \frac{160+300}{2} \times \left( \frac{230+300}{2} \times 1000 \div 43,560 \right)^{1/2} = 22.8$  AC-FT

$Q_{P2} (\text{TRIAL}) = Q_{P1} (1 - V_1/S) = 2872$  cfs

$V_2 = 6.5 \times \left( \frac{160+300}{2} \times 1000 \div 43,560 \right)^{1/2} = 11.2$   $V_{AVE} = 20.0$

$Q_{P2} = Q_{P1} (1 - \frac{V_{AVE}}{S}) = 3158$  cfs

STAGE DISCHARGE = 3158 cfs ELEV = 31.5 OR A D = 6.5'  
 NEXT DOWNSTREAM SECTION 1000 FT.




DOWNSTREAM W.S. EL. COMPUTATIONS

NAME OF DAM: PEMBELICK

SECTION LOCATION: 3000' DOWNSTREAM OF DAM

USING:  $Q = 1.486/n A R^{2/3} S^{1/2}$   
 WHERE:  $n = 0.05$   $S = \text{SLOPE} = 0.007^{1/4}$



$Q_{P1} = 3158$  STORAGE (S) 51

ELEV.	AREA	WP	R	$R^{2/3}$	$S^{1/2}$	$1.486/n$	Q	DEPTH
10	750	300	2.5	1.87	.083	29.72	3408	5
						29.72		
						29.72		

EL. -  
 EL. -  
 EL. -

CFs

\* ELEVATION 10 IS APPROXIMATELY EQUAL TO  $Q_{P2}$  3158 cfs. THEREFORE THE FAILURE DISCHARGE WILL DISAPPEAR AT THE POND CAUSING A 1 TO 2 FOOT RISE IN THE POND W.S. EL.

STAGE DISCHARGE = \_\_\_\_\_ ELEV = \_\_\_\_\_ OR A D = \_\_\_\_\_  
 NEXT DOWNSTREAM SECTION N/A FT.



RATING CURVE DEVELOPMENT


Pemberwick Dam


Spillway

$$Q = C L H^{2/3}$$

$$C = 2.70$$

$$L = 63 \text{ feet}$$





**APPENDIX E**  
**INFORMATION AS CONTAINED IN THE**  
**NATIONAL INVENTORY OF DAMS**

# INVENTORY OF DAMS IN THE UNITED STATES

STATE	DIVISION	COUNTY	CONTRACT	NAME	LONGITUDE (WEST)	REPORT DATE
CT	02	MED	001 00	PEMBERWICK DAM	7339.0	20 DEC 79

POPULAR NAME	NAME OF IMPONDMENT
BYRAM DAM	BYRAM RIVER
REGION	NEAREST DOWNSTREAM CITY-TOWN-VILLAGE
01 07	PEMBERWICK
BYRAM RIVER	DIST FROM DAM (MI.)
	1
	POPULATION
	1000

TYPE OF DAM	YEAR COMPLETED	PURPOSES	HYDRAULIC HEAD (FT.)	IMPOUNDING CAPACITIES (ACRE-FT.)	NORMAL (ACRE-FT.)
VARGOT	1067	0	45	45	60

REMARKS									
23-AESTHETIC 21-STONE MASONARY									
D/S	SPILLWAY	MAXIMUM DISCHARGE (CFS)	VOLUME OF DAM (CY)	POWER CAPACITY (KW)	INSTALLED	PROPOSED	NO.	LENGTH (FT.)	NAVIGATION LOCKS
1	U	63	1100	2200					

OWNER	ENGINEERING BY
FAIRFIELD ASSOCIATES INC	CONSTRUCTION BY

DESIGN	REGULATORY AGENCY
	CONSTRUCTION
	OPERATION
	MAINTENANCE

INSPECTION BY	INSPECTION DATE
JAMES P PURCELL ASSOCIATES INC	DAY   MO   YR
	12 NOV 79
	PL-92-367

REMARKS

DIST OWN FED R PRV/FED SCS A VER/OATE  
N N N N N





REPROD

FILMED

8

74

ADNIO