





	PAGE	READ INSTRUCTIONS BEFORE COMPLETING FORM
REPORT NUMBER	2. GOVE ACCESSION NO A14285	PECIPIENT'S CATALOG NUMBER
CT_00092		. TYPE OF REPORT & PERIOD COVERED
Housatonic River Basin		
Shelton, Conn., Means Brook Reservoi	r Dam	INSPECTION REPORT
VATIONAL PROGRAM FOR INSPECTION OF N	ON-FEDERAL	6. PERFORMING ORG. REPORT NUMBER
AUTHOR(a)		S. CONTRACT OR GRANT NUMBER(
J.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION		
PERFORMING ORGANIZATION NAME AND ADDRESS		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
CONTROLLING OFFICE NAME AND ADDRESS		12. REPORT DATE
DEPT. OF THE ARMY, CORPS OF ENGINEER	S	April 1980
NEW ENGLAND DIVISION, NEDED		13. NUMBER OF PAGES
124 TRAPELO ROAD, WALTHAM, MA. 02254		• 85
MONITORING AGENCY NAME & ADDRESS/I dillerent	trom Centrolling Office)	15. SECURITY CLASS. (of this report)
		UNCLASSIFIED
		184. DECLASSIFICATION/DOWNGRADING SCHEDULE
APPROVAL FOR PUBLIC RELEASE: DISTRIB		- Pecari
APPROVAL FOR PUBLIC RELEASE: DISTRIB		F Report)
DISTRIBUTION STATEMENT (of the about on inred in SUPPLEMENTARY NOTES Cover program reads: Phase I Inspect Nowever, the official title of the pi Ion-Federal Dams; use cover date for KEY WORDS (Continue on reverse elde if necessary and	ion Report, Nati rogram is: Natio r date of report	onal Dam Inspection Program; nal Program for Inspection of
DISTRIBUTION STATEMENT (of the about on intered in supplementary notes cover program reads: Phase I Inspect lowever, the official title of the pi lon-Federal Dams; use cover date for XEY WORDS (Continue on reverse side if necessary and DAMS, INSPECTION, DAM SAFETY,	ion Report, Nati rogram is: Natio r date of report	onal Dam Inspection Program; nal Program for Inspection of DTIC CELECT
DISTRIBUTION STATEMENT (of the observed in supplementary notes over program reads: Phase I Inspect owever, the official title of the pr lon-Federal Dams; use cover date for XEY WORDS (Continue on reverse side if necessary and DAMS, INSPECTION, DAM SAFETY, Housatonic River Basin	ion Report, Nati rogram is: Natio r date of report	onal Dam Inspection Program; nal Program for Inspection of
DISTRIBUTION STATEMENT (of the about on intered in supplementary notes cover program reads: Phase I Inspect lowever, the official title of the pi lon-Federal Dams; use cover date for XEY WORDS (Continue on reverse side if necessary and DAMS, INSPECTION, DAM SAFETY,	ion Report, Nati rogram is: Natio r date of report	onal Dam Inspection Program; nal Program for Inspection of DTIC SELECT JUL 1 2 1984
DISTRIBUTION STATEMENT (of the observed in supplementary notes over program reads: Phase I Inspect owever, the official title of the p ion-Federal Dams; use cover date for XEY WORDS (Continue on reverse side if necessary and DAMS, INSPECTION, DAM SAFETY, Housatonic River Basin Shelton, Conn.	ion Report, Nati rogram is: Natio r date of report	onal Dam Inspection Program; nal Program for Inspection of DTIC CELECT



DEPARTMENT OF THE ARMY

NEW ENGLAND DIVISION. CORPS OF ENGINEERS 424 TRAPELO ROAD WALTHAM. MASSACHUSETTS 02154

REPLY TO ATTENTION OF NEDED

MAY 0.5 1909

Honorable Ella T. Grasso Governor of the State of Connecticut State Capitol Hartford Connecticut 06115

Dear Governor Grasso.

Inclosed is a copy of the Means Brook Keservoir Dam Phase I Inspection Report, which was prepared under the National Program for Inspection of Non-Federal Dams. This report is presented for your use and is based upon a visual inspection, a review of the past performance and a brief hydrological study of the dam. A brief assessment is included at the beginning of the report. I have approved the report and support the findings and recommendations described in Section 7 and ask that you keep me informed of the actions taken to implement them. This follow-up action is a vitally important part of this program.

A copy of this report has been forwarded to the Department of Environmental Protection, the cooperating agency for the State of Connecticut. In addition, a copy of the report has also been furnished the owner, Bridgeport Hydraulic Company, 835 Main Street, Bridgeport, Connecticut 06609.

Copies of this report will be made available to the public, upon request, by this office under the Freedom of Information Act. In the case of this report the release date will be thirty days from the date of this letter.

I wish to take this opportunity to thank you and the Department of Environmental Protection for your cooperation in carrying out this program.

Sincerely,

1

Incl As stated

1

ļ

7

MAX B. SCHEIDER Colonel, Corps of Engineers Division Engineer



SHELTON, CONNECTICUT



NATIONAL DAM INSPECTION PROGRAM

PHASE I - INSPECTION REPORT

Identification No.:	CT 00092
Name of Dam:	Means Brook Reservoir Dam
Town:	Shelton
County and State:	Fairfield County, Connecticut
Stream:	Means Brook
Date of Inspection:	November 16, 1979

BRIEF ASSESSMENT

The dam at Means Brook Reservoir is concrete, 527 feet long, 50 feet high at the center of the dam (from the top of the creat wall to the toe of the downstream embankment), has a 100 foot long spillway, has a top width of 10 feet, and a 2.1 high foot wall along the top. It was originally built in 1917 with subsequent spillway and top of dam modifications in 1977. The Bridgeport Hydraulic Company presently owns and operates the dam including its waterworks facilities.

Based on the visual inspection and past operational performance, the dam is judged to be in FAIR condition. Significant spalling of the concrete and efflorescence was noted on the downstream face of the dam, and the edges of the top of the dam are chipped revealing reinforcement in places.

This dam is classified as INTERMEDIATE in size and a HIGH hazard potential structure in accordance with recommended guidelines established by the Corps of Engineers. The impoundment storage at the top of the dam is 373 ac.-ft, and the maximum height of the dam is 50 feet. Failure of the dam would result in the loss of more than a few lives and excessive damage to 25-30 residential homes.

The test flood for this dam is the Probable Maximum Flood (PMF). The test flood has an inflow equal to 7800 cfs and an outflow discharge of 7800 cfs, with stillwater elevation of 351.5 which will overtop the dam by 1.4 feet. The maximum outflow capacity of the spillway is 4000 cfs which is 51 percent of the test flood. It is recommended that the following items be studied further: The upstream face of the dam, the spalled concrete on the downstream face and top of the dam, the subsurface leakage beneath the spillway, and the structural stability.

The following remedial measures should be taken; the toe at the downstream face be monitored for leakage, and the development of a downstream warning plan and an annual inspection program.

Recommendations and remedial measures that should be implemented within one year of receipt of this Phase I Inspection Report are further described in Section 7.

JAMES P. PURCELL ASSOCIATES, INC.

А.

Sudhir A. Shah, P.E. Vice-President Connecticut P.E. No. 8012



This Phase I Inspection Report on MEANS BROOK RESERVOIR DAM has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the <u>Recommended Guidelines for Safety Inspection of</u> <u>Dams</u>, and with good engineering judgment and practice, and is hereby submitted for approval.

may M.

CARNEY M. TERZIAN, MEMBER Design Branch Engineering Division

BICHARD DIBUONO, MEMBER Water Control Branch Engineering Division

Ingener Det alter

ARAMAST MAHTESIAN, CHAIRMAN Geotechnical Engineering Branch Engineering Division

APPROVAL RECOMMENDED:

Chief, Engineering Division

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I Investigation. However, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there by any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the spillway test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and downstream damage potential.

The Phase I Investigation does not include an assessment of the need for fences, gates, no-trespassing signs, repairs to existing fences and railings and other items which may be needed to minimize trespass and provide greater security for the facility and safety to the public. An evaluation of the project for compliance with OSHA rules and regulations is also excluded.

i

TABLE OF CONTENTS

Se	ctior	n	Page
Let	ter of	f Transmittal	
Bri	ef As	ssessment	
Rev	view	Board Page	
Pre	face		i
Tal	ble o	of Contents	ii-iv
Ov	ervie	w Photo	v
Loc	cation	n Map	vi
		REPORT	
1.	Proj	ject Information	
	1.1	General	1
		a. Authority	
		b. Purpose of Inspection	
	1.2	Description of Project	1
		a. Location	
		b. Description of Dam and Appurtenances	
		c. Size Classification	
		d. Hazard Classification	
		e. Ownership	
		f. Operator	
		g. Purpose of Dam h. Design and Construction History	
		i. Normal Operational Procedure	
	1.3	Pertinent Data	3
2.		insering Data	-
	-		8
	∠.1	Design	o

T

ii

TABLE OF CONTENTS (Cont'd)

Se	ction		Page
	2 .2	Construction	8
	2.3	Operation	8
	2.4	Evaluation	9
3.	Visu	ual Inspection	
	3.1	Findings	10
		a. General	
		b. Dam	
		c. Appurtenant Structures	
		d. Reservoir Area	
		e. Downstream Channel	
	3.2	Evaluation	12
4.	Оре	rational and Maintenance Procedures	
	4.1	Operational Procedures	13
	4.2	Maintenance of the Dam	13
	4.3	Maintenance of the Operating Facilities	13
	4.4	Description of Any Warning System in Effect	13
	4.5	Evaluation	13
5 .	Eval	uation of Hydraulic/Hydrologic Features	
	5.1	General	14
	5.2	Design Data	14
	5.3	Experience Data	14
	5.4	Test Flood Analysis	15
	5.5	Dem Failure Analysis	15

iii

•

1

•

TABLE OF CONTENTS (Cont'd)

Section	Page
6. Evaluation of Structural Stability	
6.1 Visual Observations	17
6.2 Design and Construction	17
6.3 Post-Construction Changes	17
6.4 Seismic Stability	17
7. Assessment, Recommendations and Remedial Measures	
7.1 Dam Assessment	18
a. Condition b. Adequacy c. Urgency	
7.2 Recommendations	18
7.3 Remedial Measures	18
a. Operation and Maintenance Procedures	
7.4 Alternatives	19
APPENDIXES	
Appendix A - Inspection Checklist	A-1
Appendix B - Engineering Data	B-1
Appendix C - Photographs	C-1
Appendix D - Hydrologic and Hydraulic Computations	D-1
Appendix E - Information as Contained in the National Inventory of Dams	E-1





-

• •

NATIONAL DAM INSPECTION PROGRAM

PHASE I - INSPECTION REPORT

NAME OF DAM: MEANS BROOK RESERVOIR DAM

SECTION 1

PROJECT INFORMATION

1.1 General

a. Authority: Public Law 92-367, August 8, 1972, authorized the Secretary of the Army through the Corps of Engineers to initiate a national program of dam inspection throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region. James P. Purcell Associates, Inc. has been retained by the New England Division to inspect and report on selected dams in the State of Connecticut. Authorization and notice to proceed was issued to James P. Purcell Associates, Inc., under a letter from William E. Hodgson, Jr., Colonel, Corps of Engineers. Contract No. DACW33-89-C-0002 has been assigned by the Corps of Engineers for this work.

b. Purpose:

- 1. Perform technical inspection and evaluation of non-Federal dams to identify conditions which threaten the public safety and thus permit correction in a timely manner by non-Federal interests.
- 2. Encourage and prepare the States to initiate quickly, effective dam safety programs for non-Federal dams.
- 3. To update, verify and complete the National Inventory of Dams.

1.2 Description of the Project

a. Location: Means Brook Reservoir Dam is located in the Town of Shelton in Fair-field County, Connecticut, approximately 1.6 miles north of the village of Huntington along Means Brook (see Plate No. 1). The dam impounds water from Means Brook and is located 11,500 feet above the confluence with Farmill River. The impoundment is situated in a northwest/southeast direction, with the dam at the southeast end. The longitude is 73°-09'-28" and the latitude is 41°-18'-57".

All elevations used in this report are based on the National Geodetic Vertical Datum (NGVD).

b. Description of Dam and Appurtenances: Means Brook Reservoir Dam is a concrete structure with abutments and foundation keyed into rock. The length at the top of the dam is 527 feet and maximum depth to the bottom of the cutoff is 59.5 feet. The spillway is a concrete ogee weir and is located at, and is keyed into rock at the west abutment at the end of the dam. It has a length of 100.0 feet and a width of 6 feet with a crest elevation of 345.0. The width of the original top of the dam is 10.0 feet and is 3 feet above the top of the spillway. A 2.1 foot high concrete wall was added to the dam's crest in 1977. The maximum width at the base of the dam is 35+/- feet. The upstream face of the dam is concrete and is vertical in a cross sectional view. The downstream face of the dam is also concrete and is battered at 0.7H: 1.0V from the toe to a distance of approximately 24.0 feet from the top of the dam. Continuing to elevation 346.5, the face of the dam, in a cross sectional view, is concave with a radius equal to 36 feet.

The upper gate house is a concrete structure located on the top of the dam approximately in the center of the dam. Water can enter the wet well via a 36 inch sluice gate with an invert at elevation 335.4 and a 16 inch sluice gate with an invert at elevation 322.0. Water flows from the upper gate house through the dam to the concrete lower gate house via the following pipes: A 30 inch service main, a 10 inch auxiliary service, and an 8 inch drain. The 10 inch auxiliary service joins the 30 inch service main in the lower gate house and a 36 inch pipe continues downstream to an outfall at Trap Falls Reservoir. Both pipes have gate valves in the lower gate house. The 8 inch drain is controlled by a gate valve in the lower gate house and drains to the blowoff pipe.

The blowoff is a 24 inch pipe with an invert on the upstream face of the dam approximately at elevation 307.0. The pipe extends through the dam to the lower gate house where discharge is controlled by a gate valve. The 24 inch pipe continues downstream, transitions to a 16 inch pipe, and outlets at an endwall 160 feet below the dam. A 12 inch blowoff from the 36 inch service main controlled by a valve in a manhole also discharges at this endwall.

- c. Size Classification: The size classification of this dam is INTERMEDIATE as per the criteria set forth in the Recommended Guidelines for Safety Inspection of Dams, by the Corps of Engineers. The impoundment storage at the top of the dam is 373 acre-feet (within the "small" range of 50 to 1000 ac.-ft.) and the maximum height of the dam is 50 feet (within the range of 40 to 100 feet). The size classification is based on the height criteria.
- d. Hezerd Classification: The hazard classification of this dam is HIGH as per the criteria set forth in the Recommended Guidelines for Safety Inspection of Dams,

by the Corps of Engineers. The failure of the dam would result in more than a few losses of lives and extensive damage to residential areas located downstream. Twenty-five to thirty homes will be inundated by 2 to 5 feet of water.

- Ownership: The Means Brook Reservoir is presently owned and maintained by the Bridgeport Hydraulic Company, 835 Main Street, Bridgeport, Connecticut 06609.
- f Operator: The person in charge of the day-to-day operation of this dam is:

Mr. Mark L. Johnson Superintendent of System Operations Bridgeport Hydraulic Company 835 Main Street Bridgeport, CT 06609 Tel. (203) 367-6621

- g. Purpose of Dam: The Means Brook Reservoir Dam impounds water from Means Brook and is used to supply water to the distribution system of the Bridgeport Hydraulic Company.
- h. Design and Construction History: The dam was constructed in 1917. The spillway was rehabilitated and extended 25 feet, a 2.1 foot concrete wall was added along the top of the dam, and the raceway was widened in 1977. Other minor modifications to some of the appurtenant structures also took place. Various changes in the subsurface pipe network below the dam and the addition of the high lift pump house have taken place over the years. The piping through the dam has apparently remained unchanged.
- i. Normal Operating Procedures: Water is withdrawn via the 36 inch sluice gate and 30 inch service main, and continues to Trap Falls Reservoir via the 36 inch pipe. All other valves and pipes are normally closed.

1.3 Pertinent Data

a. Drainage Area: The Means Brook Reservoir drainage basin extends approximately 1.5 miles south of Route 110 and 2.3 miles north of Route 110 in the western section of Shelton and eastern section of Monroe. The basin is generally rectangular in shape having a length of 3.8 miles and an average width of 2.1 miles. The total drainage area to the dam is 7.65 square miles (see drainage basin map in Appendix D) including 1.88 square miles draining to a 5 foot high horseshoe shaped aqueduct. This aqueduct diverts water from Hurds Brook to Means Brook in the northwest portion of the watershed. The topography is generally moderate to steep terrain, with elevations ranging from a high of 650 feet to a low of 345 feet at the spillway crest. Stream slopes are flat having an average grade of 1/4 percent. Basin slopes range from 5 to 10 percent. The normal pond area is 18.4 acres which is 0.4 percent of the watershed.

- b. Discharge at Dam Site: Daily water usage records are available from the Bridgeport Hydraulic Company. Other than this, there are no specific flood discharge records available for this dam. Listed below are calculated discharge values for the spillway and outlet works (30 inch service main and 24 inch blowoff).
 - 1. Outlet Works: A 30 inch service main with an intake invert at elevation 322.0 and a discharge capacity of 113 cfs at elevation 345.0. A 24 inch blowoff with an invert approximately at elevation 307.0 and a discharge capacity of 42 cfs at elevation 345.0.
 - 2. Maximum Known Discharge at Dam Site: Calculated to be 2000 cfs in October, 1955 based on a recorded flow of 4 inches over the dam. The spillway was 76.5 feet long and the wall on the top of the dam did not exist at this time.
 - 3. Spillway Capacity at Top of Dam (Crest Wall): 4000 cfs at elevation 350.1.
 - 4. Spillway Capacity at Test Flood Level: 5800 cfs at elevation 351.5.
 - 5. Gated Outlet Capacity at Normal Pool Elevation: 113 cfs (30 inch main) and 42 cfs (24 inch blowoff) at elevation 345.0.
 - 6. Gated Outlet Capacity at Test Flood Level: 128 cfs (30 inch main) and 45 cfs (24 inch blowoff) at elevation 351.5.
 - 7. Gated Outlet Capacity at Top of Dam (Crest Wall) Elevation: 125 cfs (30 inch main) and 44 cfs (24 inch blowoff) at elevation 350.1.
 - 8. Total Project Discharge at Top of Dam (Crest Wall) Elevation: 4170 cfs at elevation 350.1.
 - 9. Total Project Discharge at Test Flood Elevation: 7970 cfs at elevation 351.5.

c. Elevation (Ft. above N.G.V.D.)

1.	Stream bed at toe of dam	305+/- (upstream)
		300+/- (downstream)

2	2. Bottom of cutoff	Approximately 290.6 at lowest point.
3	. Maximum tailwater	N/A
4	Recreation pool	N/A
5.	Full flood control pool	N/A
6 .	Spillway crest (Normal pool)	345.0
7.	Design surcharge (1977 Original Design)	349.1 w/1' freeboard
8 .	Top of dam	350.1 (top of wall) 348.0 (top of dam)
9 .	Test flood level	351.5
. Re	servoir (Length in feet)	
1.	Normal pool	1600
2.	Flood control pool	N/A
3.	Spillway crest pool	1600
4.	Top of dam (crest wall)	2500
5.	Test flood pool	2500
Sto	rage (acre-feet)	
1.	Normal pool	268
2.	Flood control pool	N/A
3.	Spillway crest pool	268
4.	Top of dam (crest wall)	373
5.	Test flood pool	412

đ.

5

f. Reservoir Surface (acres)

1.	Normal pool	18.4
2.	Flood control pool	N/A
3.	Spillway crest	18.4
4.	Test flood pool	26.0

5. Top of dam (crest wall) 24.0

g. Dam

h.

I.

1

ł

1

1. Туре	Concrete
2. Length	527 feet
3. Height	50 feet (top of wall to downstream toe)
4. Top width	10 feet (top of dam) 1 foot (top of wall)
5. Side slopes	Upstream: vertical Downstream: 0.7H:1.0V and radius of 36'
6. Zoning	Concrete
7. Impervious core	Concrete
8. Cutoff	Concrete keyed into bedrock
9. Grout curtain	N/A
Diversion and Regulating Tunnel	N/A
Spillway	
1. Туре	Overflow, ogee crest, uncontrolled weir

6

.

2.	Length of weir	100 feet
3.	Crest elevation	345.0
4.	Gates	None
5.	U/S Channel	Bedrock
6.	D/S Channel	Bedrock

j. Regulating Outlets

Refer to Paragraph 1.2b - "Description of Dam and Appurtenances" for description of Outlet Works.

1.	Inverts	335.4 – 36 inch main intake 322.0 – 16 inch auxiliary intake 307+/– 24 inch blowoff intake
2.	Size	30 inch service main 10 inch auxiliary service 8 inch drain 24 inch blowoff
3.	Description:	Cast iron pipes
4.	Control mechanisms	Hand operated lift mechanisms in the upper gate house.

Gate valves in the lower house.

ENGINEERING DATA

2.1 Design

Available design data consists of the following documents and plans:

- a. Bridgeport Hydraulic Co., Means Brook Development, Plan and Profile of Dam, Town of Huntington, Connecticut, May, 1915.
- b. Bridgeport Hydraulic Co., Means Brook Development, Plan, Profile and Cross Section of Dam, Town of Huntington, Connecticut, February 1916.
- c. Plans for Revisions to Means Brook Spillway, Designed by Seelye, Stevenson, Value and Knecht, 1977.
- d. Design Report, Revisions to Means Brook Reservoir Spillway for Bridgeport Hydraulic Company by Seelye, Stevenson, Value and Knecht, Consulting Engineers, March 15, 1977.
- e. Design Report, Addendum No. 1, Revisions to Means Brook Reservoir Spillway for Bridgeport Hydraulic Company, March 31, 1977.
- f. Plan of Lower Gate House, Means Brook Reservoir.
- g. Plan of Upper Gate House, Means Brook Reservoir.

2.2 Construction

This dam was constructed in 1917. Review of the contract plans for the 1977 revisions showed that the modifications to the dam were limited to lengthening of the spillway and spillway channel (raceway), spillway rehabilitation, extension of the pipe bridge over the widened raceway, construction of a 2.1 foot wall on the dam's crest and other minor modifications to some appurtenant structures. These revisions were implemented as the result of a 1973 inspection of the dam. A copy of this inspection report is contained in Appendix B.

2.3 Operation

The operation of the dam is for the purpose of water supply, and therefore, the water level for this dam is established on the basis of the water supply demand. However, there is no written procedure that has been established for this purpose.

~...

2.4 Evaluation

ł

- a. Availability: The information noted above for this facility is available in the files of the Department of Environmental Protection, Water and Related Resources Unit, Dam Safety Engineers, State Office Building, Hartford, Connecticut, and the Bridgeport Hydraulic Company, 835 Main Street, Bridgeport, Connecticut.
- **b.** Adequacy: The information that was available complemented a complete visual inspection of the dam. Since there were no signs of major distress, the information is adequate at this time.
- c. Validity: The validity of the 1977 design data appears good. The validity of the 1915 and 1916 plans could not be verified.

VISUAL INSPECTION

3.1 Findings

a. General: The visual inspection of the Means Brook Reservoir Dam was conducted on November 16, 1979 and a copy of the visual inspection check list is contained in Appendix A of this report.

The following procedure was used:

- 1. Inspection of the upstream area of the reservoir which was impounded by the dam.
- 2. Visual inspection of the face and crest of the dam and spillway for cracks, spalling, leakage, etc.
- 3. Inspection of the outlet works and other appurtenances as to their existence, location, and operability.
- 4. Review of procedures that could be utilized in the event of an emergency situation.
- A check of the downstream area for seepage, piping, boils or other indications of abnormal conditions. The downstream hazard potential in the event of dam failure was investigated.
- 6. Photographs of the general area of the dam and of specific items of note were taken and are included in Appendix C of this report.

Before the inspection, the available existing data and aerial photographs were studied and reviewed.

b. Dam

 Crest: The top of the dam is concrete with no evidence of settlement or misalignment. The top is spalled (Photo C-4) and there is visible reinforcing in a few locations along the edge of the top (Photo C-5). A 2.1 foot high concrete wall was added to the upstream edge of the dam's crest in 1977 (Photo C-5).

The top of the dam has a width of 10 feet and support pipe railing (good condition) on both the upstream and downstream edges (Photo C-4).

- 2. Upstream face: The upstream face of the dam is concrete with a vertical face (Photo C-3). The water level at the time of the inspection was 5.6 feet below the top of the dam (wall). Spalling and efflorescence was noted.
- 3. Downstream face: The downstream face is concrete with a sloped face (see record drawings in Appendix B). Substantial spalling and efflorescence was noted on the downstream face (Photos C-1, C-2). Leakage at the toe in the center of the dam was reported in a 1977 inspection. However, no sign of any leakage was noted in the inspection for this report.

c. Appurtenant Structures

- 1. Spillway: The spillway is a 100 foot long and 6 foot wide concrete ogee crested weir with a drop of 3 feet to the raceway (Photos C-6, C-8). The spillway was widened and rehabilitated in 1977 and, except for leakage through a small crack (Photo C-7), and possible subsurface leakage, is in good condition. The spillway is located at the west abutment of the dam and is keyed into rock.
- 2. Water Supply Outlets: A 30 inch service main and a 10 inch auxiliary service drain water from the wet well of the upper gate house, through the dam, to the lower gate house. The 30 inch pipe is normally in use and expands to a 36 inch pipe which extends downstream to the Trap Falls Reservoir. The visible portions are rusted but appear in good condition and are reportedly operational. The 36 inch pipe can be drained to the raceway via a 12 inch blowoff.
- 3. 24 Inch Blowoff: A 24 inch blowoff extends from the upstream face, through the dam, to the lower gate house. Gate valves in the lower gate house control the discharge in this pipe and are reportedly operational. A cross over pipe can permit flow between the 30 inch service main and the 24 inch blowoff. The 24 inch pipe continues from the lower gate house, transitions to a 16 inch pipe, and outfalls to the raceway at an endwall 160 feet below the dam (Photo C-12).
- 4. Upper Gate House: The upper gate house is a concrete structure in generally good condition (Photo C-4). The lift mechanisms for the wet well intake sluice gates are located in the house and appear operational (Photo C-11).
- 5. Lower Gate House: The lower gate house is a concrete structure in generally good condition (Photo C-2, building at toe of dam). Controls for the various gate valves are located in the house and appear operational. Pumps are also located in the house which may be utilized to increase the flow through the 36 inch pipe to the Trap Falls Reservoir.

d. Reservoir Area

The impoundment created by the dam is a flooded portion of the natural brook bed. There are fairly gentle slopes abuting the reservoir on the west side and steeper slopes on the east side.

The natural drainage area of the reservoir has been increased by the diversion of the Hurds Brook Watershed. This watershed flows through an unregulated 5 foot by 5 foot horseshoe shaped aqueduct just south of Webb Circle Road in the northwest portion of the drainage area.

No geologic features were detected that could be expected to adversely affect the dam or its appurtenant structures.

Trespassing on the dam is prohibited and the crest is fenced and locked. Access to the dam site is limited and the access road is chained and locked.

e. Downstream Channel

The spillway channel or raceway is cut into the valley slope at the west abutment below the spillway (Photos C-6, C-9). The floor of the channel is rock with a fairly steep gradient. Water was not flowing over the spillway, however, a substantial flow was noted in the raceway below the spillway (Photo C-6).

A pipe bridge for the 36 inch service main to Trap Falls Reservoir spans the raceway just upstream of the blowoff endwall (Photo C-10).

The raceway was expanded as part of the 1977 modifications to the dam.

3.2 Evaluation

Based on the visual inspection, the Means Brook Reservoir Dam appears to be in fair condition overall, and there were no major areas of distress noted. Specific areas of concern that were noted are:

The substantial spalling and efflorescence on the downstream face.

The subsurface flow to the raceway.

OPERATIONAL AND MAINTENANCE PROCEDURES

4.1 Operational Procedures

The responsibility for the operation and maintenance of this facility is with the Bridgeport Hydraulic Company. The maintenance staff is located at the Company headquarters in Bridgeport, Connecticut. These staff personnel make daily visits to the dam facility. During storm conditions, the Means Brook Reservoir Dam is monitored around the clock. These staff personnel operate and maintain the valves and equipment necessary to maintain the flow to the Trap Falls Reservoir for distribution in the water supply system. No written procedure is available for emergency operation of the blowoff system. The blowoff valve was last opened in 1977 to drain the reservoir during alterations to the dam.

4.2 Maintenance of the Dam

The maintenance of the dam is centered around those valves and sluice gates that control the water supply to the public water distribution system. The dam is super-ficially inspected by the Bridgeport Hydraulic Company on an annual basis. Records of these inspections are available from the Bridgeport Hydraulic Company.

4.3 Maintenance of the Operating Facilities

The operating facilities consist of a 36 inch sluice gate for the main water service intake, a 16 inch sluice gate for the auxiliary water service intake and a gate valve for the blowoff system. All valves are manually operated from within the gate houses. No specific testing of the valves is conducted.

4.4 Description of any Warning System in Effect

No formal emergency or contingency plan is in effect to reduce or minimize downstream damage in emergency situations.

4.5 Evaluation

The operation and maintenance of this dam could be oriented so that it more directly deals with procedures to be followed in case of an emergency situation.

EVALUATION OF HYDRAULIC/HYDROLOGIC FEATURES

5.1 General

The Means Brook Reservoir Dam creates an impoundment with a total storage capacity of 268 ac.-ft. at elevation 345.0, the spillway crest elevation. Each foot of depth in the reservoir above the spillway crest can accommodate approximately 20 ac.-ft. The natural drainage area has been increased by 1.88 square miles by the diversion of a portion of Hurds Brook to Means Brook. The stream bed of Means Brook above the dam is flat with an average slope of 1/4 percent. The spillway is a concrete ogee weir 100.0 feet in length and 5.1 feet below the top of the wall on the crest.

5.2 Design Data

- The available design data is limited to final design discharges by Seelye, Stevenson, Value and Knecht, Inc., for the 1977 spillway and top of dam modifications. Refer to Appendix B for location of this data. Design calculations were unavailable.
- b. The drainage area utilized in the 1977 design calculations was 5.77 square miles, which apparently did not include the 1.88 square mile watershed of Hurds Brook upstream of the diversion aqueduct. Inclusion of this watershed yields the total drainage area to the Means Brook Dam of 7.65 square miles used in this inspection report.
- c. To supplement and verify the existing design information, USGS topographic maps (scale 1"=2000') were utilized to develop hydrologic parameters such as drainage area, basin length, time of concentration, and other runoff characteristics. Elevation-storage relations for the reservoir were approximated. Reservoir surface area and surcharge storage was computed using the USGS maps. Some of the pertinent hydraulic design data was obtained and/or confirmed by actual field measurements at the time of the visual inspection.
- d. Outflow values (routing procedures) and dam overtopping analyses were computed in accordance with the guidelines developed by the Corps of Engineers. Judgment was used in calculating final values outlined in this report, which are quite approximate and should not be considered a substitute for actual detailed analysis.

5.3 Experience Data

Historical data for recorded discharges is available for this dam. The maximum discharge to date occurred in October, 1955 and was calculated to be approximately 2000 cfs, corresponding to a reported water level of 4 inches over the top of the dam. The spillway was 76.5 feet long, the wall on the dam's crest did not exist, and the top of the dam was 407 feet long at this time.

5.4 Test Flood Analysis

Recommended guidelines for the Safety Inspection of Dams by the Corps of Engineers were used for the selection of the "Test Flood". This dam is classified as a HIGH hazard and INTERMEDIATE size structure. Guidelines indicate that the Probable Maximum Flood (PMF) be used as the "Test Flood": for these classifications. The watershed has a total area of 7.65 square miles. Snyder's lag was calculated to be 5.2 hours and a Snyder peaking coefficient of 0.625 was used. The 200 square mile - 24 hour Probable Maximum Precipitation (PMP) is 22 inches. The flood hydrograph package, HEC-1 computer program, developed by the Corps of Engineers was utilized to develop the inflow hydrograph, route the flood through the reservoir, and for the dam overtopping analysis. A test flood inflow equal to the PMF was calculated to be 7800 cfs, or 1020 cfs/sq. mi. (drainage area equal to 7.65 square miles). The inflow from 1/2 PMF was calculated to be 3900 cfs of 510 cfs/sq. mi. This correlates well with the 1977 calculated value of the design discharge (1/2 PMF) of 2850 cfs or 490 cfs/sq. mi. (drainage area equal to 5.77 square miles).

The spillway capacity is hydraulically inadequate to pass the "Test Flood" (PMF) and overtopping of the dam will occur. The maximum outflow capacity of the spillway without overtopping the dam is 4000 cfs. This corresponds to 51 percent of the test flood and a storage above the spillway crest of 105 ac.-ft. The maximum outflow discharge value for the test flood is 7800 cfs corresponding to a depth of flow over the top of dam of 1.4 feet and a storage above the spillway level of 144 ac.-ft. The outflow from 1/2 PMF is equal to 3900 cfs. A spillway rating curve, low level outlet rating curve and a reservoir surface area-capacity curve are included in Appendix D of this report.

At the spillway crest elevation of 345.0, the capacity of the 16 inch outlet structure is 42 cfs and approximately 113 cfs are withdrawn via the 30 inch supply main. It will require approximately 2 hours to lower the water level the first foot assuming a water surface area of 18.4 acres, normal inflow conditions and use of the outlet works to regulate the water level for expected inflows.

5.5 Dam Failure Analysis

This dam is classified as a HIGH hazard structure. Failure discharge can cause damage due to high velocities, impact from debris, and flooding to 25-30 residental homes and urban areas along the downstream channel.

The calculated dam failure discharge is 19600 cfs at a pool level equal to the spillway crest. This pool level was chosen instead of the top of the dam level as having the greater hazard potential because a pre-failure flow of 4000 cfs (maximum spillway capacity) would have caused evacuation and/or a warning of flood conditions downstream of the dam. Failure of the dam at normal pool level would catch the downstream area off guard and probably result in greater losses. Failure will produce a water surface level approximately 16.0 feet immediately downstream from the dam which would completely inundate the lower gate house and pump house. The failure discharge will effect downstream areas for a distance of 11500 feet from the dam where approximately 25 - 30 residential homes will be inundated by 2 - 5 feet of water. At this distance, the water surface level will be approximately 2.0 feet above normal observations as it enters the Farmill River. Beyond 11500 feet, the effects of the failure discharge will be reduced as it enters the Farmill River. Water surface elevations, due to the failure of the dam, are listed in Appendix D. Probable consequences including the prime impact areas are also listed in Appendix D.

- -

EVALUATION OF STRUCTURAL STABILITY

6.1 Visual Observations

Since no major physical distress or movement has been noted since the construction of this dam in 1917, stability does not appear to be a problem. On the downstream face, the concrete shows signs of spalling and efflorescence. A 2.1 foot concrete wall was added to this structure and the spillway was widened in 1977. Reinforcement is visible in a few places along the edges of the crest.

6.2 Design and Construction Data

There are plans available from the 1917 construction. However, it was not until 1977 that a design analysis was available which was done in conjunction with the revisions that were made to the Means Brook Spillway. The structural analysis done by Seelye, Stevenson, Value and Knecht assumed several loading conditions to check the stability of the structure. Refer to Appendix B for location of this data. Conventional structural analysis methods were employed, however, to establish its conformity with the Corps of Engineers Recommended Guidelines for a Phase II analysis, it appears that other loading conditions will have to be studied.

Other than the contract plans there were no available construction records of the 1977 modifications to the top of the dam and the spillway.

6.3 Post-Construction Changes

Prompted by a 1973 inspection of the dam, the 1977 modifications to the top of the dam and the spillway were performed. The abutments for the pipe bridge at the bottom of the raceway were relocated and modified to increase the hydraulic capacity. Minor changes to the downstream training walls and riprap limits were performed to improve flow characteristics.

6.4 Seismic Stability

The dam is in Seismic Zone 1 and hence does not require evaluation for seismic stability according to the Corps of Engineers Recommended Guidelines.

ASSESSMENT, RECOMMENDATIONS, AND REMEDIAL MEASURES

7.1 Dam Assessment

- a. Condition: Based on the visual inspection, past performance and hydraulic/hydrologic evaluation, the Means Brook Reservoir Dam and appurtenances is judged to be generally in FAIR condition. Items of concern that should be addressed as a result of this inspection are listed in Sections 7.2 and 7.3.
- b. Adequacy of information: The existing engineering data did not allow for a complete review. Therefore, the adequacy of the dam is also based on visual inspection, past performance history, and engineering judgment.
- c. Urgency: The recommendations and remedial measures described below should be implemented by the owner within one year after receipt of this Phase I Inspection Report.

7.2 Recommendations

It is recommended that the owner engage a qualified registered engineer to carry out the following actions and that his recommendations be implemented.

- a. An investigation as to the source and cause of the subsurface flow beneath the spillway.
- b. The upstream face of the dam be visually inspected.
- c. The spalling on the downstream face and the top of the dam be rehabilitated to their original condition.
- d. A further analysis be conducted as to the structural stability of the dam.

7.3 Remedial Measures

a. Operational and Maintenance Procedures

- 1. The toe at the downstream face be monitored for signs of the reoccurrence of leakage.
- 2. Develop a downstream warning and surveillance plan, to supplement the round-the-clock monitoring during heavy precipitation.

3. Institute a program of annual periodic technical inspection.

7.4 Alternatives

None.

.

1.1

APPENDIX A

INSPECTION CHECK LIST

÷

R. Johnston, JPPA 6. V. Zanillo Bridgeport R. Lyon, JPPA 7. J. Stone Hydraulic J. Chastanet, CWDD 8. M. Johnson Company 9.		ON CHECK LIST RGANIZATION
R. Lyon, JPPA 7. J. Stone Hydraulic J. Chastanet, CWDD 8. M. Johnson Company 9.	ROJECT MEANS BROOK RESERVO	TIME 9:00 - 10:30 a.m. WEATHER Partly Cloudy
Hydraulics R. Johnston Structural R. Lyon Geotechnical J. Chastanet	R. Johnston, JPPA R. Lyon, JPPA J. Chastanet, CWDD	7. J. Stone Hydraulic 8. M. Johnson Company 9.
. <u>Geotechnical</u> J. Chastanet	PROJECT FFATURE	INSPFCTED BY REMARKS
·	. Hydraulics	R. Johnston
•	. Structural . Geotechnical	R. Lyon J. Chastanet
	. <u>Structural</u> . <u>Geotechnical</u> 	R. Lyon J. Chastanet
	. <u>Structural</u> . <u>Geotechnical</u> 	R. Lyon J. Chastanet
INSPECTION		
---	---	-----
PROJECT MEANS BROOK RESERVOIR DAM	DATE NOVEMBER 16, 1979	
PROJECT FEATURE	NAME	
DISCIPLINE	NAME	
AREA EVALUATED	CONDITION	
DAM EMBANKMENT	Concrete - Wall on crest added in 1977.	
Crest Elevation 348.0	Good - Minor spalling and some visible reinforcement at edges	
Current Pool Elevation 344.5	3.5 feet below crest	
Maximum Impoundment to Date	4 inches over crest in 1955	
Surface Cracks	Substantial spalling on downstream face	
Pavement Condition	N/A	
Movement or Settlement of Crest	None observed	
Lateral Movement	None observed	
Vertical Alignment	Good	
Horizontal Alignment	Good	
Condition at Abutment and at Concrete Structures	Good - Spillway at west abutment	
Indications of Movement of Structural Items on Slopes	N/A	
Trespassing on Slopes Vegetation on Slopes Sloughing or Erosion of Slopes or Abutments	Not permitted Grass, two bushes on side slopes Substantial spalling on downstream face	
Rock Slope Protection - Riprap Failures	N/A	/
Unusual Movement or Cracking at or near Toes	None observed	
Unusual Embankment or Downstream Seepage	None observed	
Piping or Boils	None observed	
Foundation Drainage Features	None observed	
Toe Drains	None observed	
Instrumentation System	None observed	
A-2		l I

INSPECTION PROJECT MEANS BROOK RESERVOIR DAM	
PROJECT FEATURE	NAME
DISCIPLINE	
AREA EVALUATED	CONDITION
OUTLET WORKS - INTAKE CHANNEL AND INTAKE STRUCTURE	
a. Approach Channel	Entire lake bed - underwater
b. Intake Structures	
24 Inch Blowoff Intake	A free access inlet at the base of the dam on the upstream face of the upper gate house. Last utilized in 1977 to drain the reservoir.
36 Inch Main Intake	A 36 inch sluice gate controls discharge into the well of the upper gate house. Gate controlled by a lift mechanism in the gate house and is currently in the open position. Reportedly closed in 1977.
16 Inch Auxiliary Intake	A 16 inch sluice gate also allows discharge into the well of the upper gate house. Gate controlled by a lift mechanism in the gate house. Normally closed, but reportedly operational.
A-3	

Ş

INSPECTION	CHECK LIST
PROJECT MEANS BROOK RESERVOIR DAM	DATE NOVEMBER 16, 1979
PROJECT FEATURE	NAME
DISCIPLINE	NAME
AREA EVALUATED	CONDITION
OUTLET WORKS - CONTROL TOWFR	Upper gate house
a. Concrete and Structural	
General Condition	Good
Condition of Joints	Good
Spalling	Minor on exterior
Visible Reinforcing	None observed
Rusting or Staining of Concrete	None observed
Any Seepage or Efflorescence	None observed
Joint Alignment	Good
Unusual Seepage or Leaks in Gate Chamber	None observed
Cracks	Minor cracks in wall above water line
Rusting or Corrosion of Steel	None observed
b. Mechanical and Electrical	
Air Vents	None observed
Float Wells	N/A
Crane Hoist	Mechanical chain hoists for screens
Elevator	N/A
Hydraulic System	N/A
Service Gates	36 inch sluice gate
Emergency Gates	16 inch auxiliary gate
Lightning Protection System	None observed
Emergency Power System	None observed
Wiring and Lighting System in Gate Chamber	Domestic lighting
2-4	

• •

. | **---**

INSPECTION	CHECK LIST
PROJECT MEANS BROOK RESERVOIR DAM	DATE NOVEMBER 16, 1979
PROJECT FEATURE	NAME
DISCIPLINE	NAME
AREA EVALUATED	CONDITION
OUTLET WORKS - TRANSITION AND CONDUIT	
30 Inch Service Main	A 30 inch cast iron pipe extends from the well in the upper gate house, through the dam, to a 30 inch valve in the lower gate house. A 36 inch cast iron pipe continues from the lower gate house to Trap Falls Reservoir, 2.8 miles south fo the dam.
10 Inch Auxiliary Servi <i>c</i> e	A 10 inch cast iron pipe extends from the well in the upper gate house, through the dam, to a 10 inch valve in the lower gate house. The pipe then feeds into the 36 inch service main in the base- ment of the lower gate house.
24 Inch Blowoff	A 24 inch pipe extends from the inlet, through the dam, to a 24 inch valve in the lower gate house. The 24 inch pipe continues through the house reducing to a 16 inch pipe before the outlet. A 24 inch pipe and valve in the lower gate house can permit flow between the 36 inch service main and the 24 inch blowoff.
8 Inch Drain	An 8 inch pipe extends from the upper gate house, through the dam, to an 8 inch valve in the lower gate house. The 8 inch pipe then feeds into the 24 inch blowoff in the basement of the lower gate house.
A-5	

INSPECTION	
PROJECT MEANS BROOK RESERVOIR DAM	DATE NOVEMBER 16, 1979
PROJECT FEATURE	NAME
DISCIPLINE	NAME
AREA EVALUATED	CONDITION
OUTLET WORKS - OUTLET STRUCTURE AND OUTLET CHANNEL	
36 Inch Service Main	The 36 inch pipe may be drained, to the raceway, via a 12 inch pipe to an endwall below the dam. The 36 inch pipe continues to a dis- charge at Trap Falls Peservoir.
24 Inch Blowoff	The 24 inch pipe reduces to a 16 inch pipe and outlets, to the raceway, at an endwall below the dam.
Outlet Channel	A short channel extends from the endwall to the raceway. The channel is overgrown with grass and brush.
A-6	

ſ	
INSPECTION	
PROJECT MEANS BROOK RESERVOIR DAM	DATE NOVEMBER 16, 1979
PROJECT FEATURE	NAME
DISCIPLINE	NAME
AREA EVALUATED	CONDITION
OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNFLS	Spillway widened and rebuilt in 1977.
a. Approach Channel	Entire lake bed - underwater
General Condition	
Loose Rock Overhanging Channel	
Trees Overhanging Channel	
Floor of Approach Channel	
b. Weir	
General Condition of Concrete	Good - Rebuilt in 1977
Rust or Staining	None observed
Spalling	None observed
Any Visible Reinforcing	None observed
Any Seepage or Efflorescence	Small leak through hairline crack.
Drain Holes	None observed
c. Discharge Channel (raceway)	
General Condition	Good
Loose Rock Overhanging Channel	None observed
Trees Overhanging Channel	None observed
Floor of Channel	Rock
Other Obstructions	Pipe bridge for 36 inch service main

A-7	

Į

APPENDIX B

14

l

ľ

1. 2

State 1 - Second

ENGINEERING DATA

.

APPENDIX B-1

DESIGN, CONSTRUCTION AND MAINTENANCE RECORDS AND LOCATION

Mr. Victor J. Galgowski Dam Safety Engineer Water and Related Resources Unit Department of Environmental Protection State of Connecticut State Office Building Hartford, Connecticut 06115

Bridgeport Hydraulic Company 835 Main Street Bridgeport, Connecticut 06609

APPENDIX B-2

COPIES OF PAST INSPECTION REPORTS

<u>.</u>,,

BUCK & BUCK

ENGINEERS

98 WADSWORTH STREET, HARTFORD, CONNECTICUT 06106

JAMES A. TEOMPSON BOSINSON W. BUCK LAWEENCE P. BUCK HENET WOLCOTT BUCK 1931-1965 NOBUSON D. BUCK 1935-1939

COMM. 5713-74

April 24, 1973

Mr. Victor Galgowski Supt. of Dams Dept. of Environmental Protection State Office Building Hartford, CT 06106

RE: Means Brook Reservoir Dam, Shelton

Dear Vic:

We inspected the subject dam on April 12th and noted sandbags on top of same. If the sandbags were placed there to prevent overtopping of the structure, it means that the spillway capacity is inadequate. We recommend that you request an engineering report of this matter from the owner.

During our inspection we also noted a hole in the westerly embankment, 10' \pm downstream from the face of the dam and 20' \pm east of the east wall of the spillway. The masonry endwall of the spillway discharge channel has been partially broken away and there is evidence that flow has escaped the channel at some time in the past. The recommended engineering report should also include proposed remedial measures for the last two items mentioned.

Sincerely. BUCK & BUCK ana Ahingson James A. Thompson

JAT:d1b

WATER & RELATED RESOURCES RECEIVED

APR 2 6 1973

B-3

ANSWER, U	
REFERRED	
FILED	

ven By	WATER RESOURCES CONFILSSION SUPERVISION OF DAMS Long 73-09.2 CT-9: INVENTORY DATA 11 JUNE 1964
	Name of Dain or Pond MEANS BROOK RESERVOIR
	Code No. H 5.7 FM 4 6 MN 2.5
	Nearest Street Location SAWMILL ROAD
	Town SHELTON
	U.S.G.S. Quai, LONG HILL
	Name of Stream MEANS BRUCK
	Owner BRIDGEPORT HYDRAULIC COMPANY
	Address 835 MAIN STREET
	BRIDGEFORT 367-6621 06 12/18
	Pond lised for WATER SUPPLY DA 7.65 SM1
	Pond Used For WATER SUPPLY DF 103 30
• • •	22
	Dimensions of Pond: Width 500 FEET Length 1200 FEET Area 45-Act Total Length of Dam 400 FEET Length of Spillway 43 FEET
	Dimensions of Pond: Width 500 FEET Length 1200 FEET Area 45 Act
	Dimensions of Pond: Width 500 FEET Length of Spillway 43 FEET Total Length of Dam 400 FEET Length of Spillway 43 FEET
· · · ·	Dimensions of Pond: Width 500 FEET Length 1200 FEET Area 45-Act Total Length of Dam 400 FEET Length of Spillway 68 FEET Location of Spillway WEST SIDE OF DAM
	Dimensions of Pond: Width 500 FEET Length 1200 FEET Area 45 Act Some Total Length of Dam 400 FEET Length of Spillway 43 FEET Location of Spillway WEST SIDE OF DAM Height of Pond Above Stream Bed 35 FEET
	Dimensions of Pond: Width <u>500 FEET</u> Length <u>1200 FEET</u> Area <u>45 Act</u> Total Length of Dam <u>409 FEET</u> Length of Spillway <u>43 FEET</u> Location of Spillway <u>WEST SIDE OF DAM</u> Height of Pond Above Stream Bed <u>35 FEET</u> Height of Embankment Above Spillway <u>5 FEET</u>
	Dimensions of Pond: Width <u>500 FEET</u> Length <u>1200 FEET</u> Area <u>45 Act</u> Total Length of Dam <u>400 FEET</u> Length of Spillway <u>63 FEET</u> Location of Spillway <u>WEST SIDE OF DAM</u> Height of Pond Above Stream Bed <u>35 FEET</u> Height of Embankment Above Spillway <u>5 FEET</u> Type of Spillway Construction <u>CONCRETE</u>
	Dimensions of Pond: Width 500 FEET Length 1200 FEET Area 45-Act Scar Total Length of Dam 409 FEET Length of Spillway 63 FEET Location of Spillway WEST SIDE OF DAM Height of Pond Above Stream Bed 35 FEET Height of Embankment Above Spillway 5 FEET Type of Spillway Construction CONCRETE Type of Dike Construction CONCRETE
	Dimensions of Pond: Width 500 FEET Length 1200 FEET Area 45 Act Total Length of Dam 400 FEET Length of Spillway 48 FEET Location of Spillway WEST SIDE OF DAM Height of Pond Above Stream Bed 35 FEET Height of Embankment Above Spillway 5 FEET Type of Spillway Construction CONCRETE Downstream Conditions WeoDS
	Dimensions of Pond: Width <u>500 FEET</u> Length <u>1200 FEET</u> Area <u>15 Act</u> Total Length of Dam <u>400 FEET</u> Length of Spillway <u>63 FEET</u> Location of Spillway <u>WEST SIDE OF DAM</u> Height of Pond Above Stream Bed <u>35 FEET</u> Height of Embankment Above Spillway <u>5 FEET</u> Type of Spillway Construction <u>CONCRETE</u> Type of Dike Construction <u>CONCRETE</u> Downstream Conditions <u>WeeDS</u> RoADS
	Dimensions of Pond: Width 500 FEET Length 1200 FEET Area 45 Act Total Length of Dam 400 FEET Length of Spillway 43 FEET Location of Spillway WEST SIDE OF DAM Height of Pond Above Stream Bed 35 FEET Height of Embankment Above Spillway 5 FEET Type of Spillway Construction CONCRETE Downstream Conditions Weeds Summary of File Data

1

l

-i-73 - 2" mote vor cours, privat and and in the second of a secon المت في ا And the second 3-14-27 Supage sing toe about cute is serve chusches and minitalis le is preparing plane à province more conclusive cap. 27 32

B-5

APPENDIX B-3

RECORD DRAWINGS AND SKETCHES



























3000

G

LIST OF DRAWINGS

- 1.
- 2
- 3.
- 4.5.6
- 7

.

- 9
- LOCATION PLAN AND BORINGS SITE PLAN PIPE BRIDGE DETAILS ALTERATION NORTH ABUTMENT SOUTH ABUTMENT WIALL DETAILS CROSS SECTION STA 9+00 TO STA 9+50 CROSS SECTION STA 0+00 TO STA 0+25 CROSS SECTION STA 0+00 TO STA 0+25 CROSS SECTION STA 0+00 TO STA 1+75 CROSS SECTION STA 0+00 TO STA 12+35 CROSS SECTION STA 2+00 TO STA 12+35 CROSS SECTION STA 2+00 TO STA 12+35 11

ومنهج



Stound Water Elev. 3299

Note:

Figures at left indicate depth Below ground surface of strate change. Figures at center indicate Coring Time Par Ft (Nin).

<u>B-3</u>

د،

13

27

15

18

13

13

22

15

Surface Elev. 3295

Sand Gravel, Coboles (Boulders

Pock Drilled

Ground Water Elev. 5'85

Locm

20

60

<u> 11.C</u>

150

Figures of Right indicate tumbers of Blows required to drive 145 od. Samper 6' using 1401b harmen dropping 30".



Brown Sand, Gnavel Bouiders f Cobbies 12.5 Snoken Seems Ż Decomposed Rock

8-5

306 8

interio.

.

00

OC

x

i. Sy

14.2

Driled 200 Ground Neter Elev. 2897

175

DEPORT Ca CO

EAN DOLTON

Sheet Rock Scal

\$ 150 19.4.1

Ç





APPENDIX C

PHOTOGRAPHS



Ì





N

ł





.






APPENDIX D

HYDROLOGIC AND HYDRAULIC COMPUTATIONS

· •

-...





HYDROLOGIC AND HYDRAULIC ANALYSIS SUMMARY SHEET

Dam Means Brook Reservoir Dam ______

INFLOW HYDROGRAPH DEVELOPMENT

Drainage Area 7.65 sq. mi.

Probable Maximum Precipation 24 hour - 200 square mile PMP 22 inches

Initial Railfall Loss 0 Inch Uniform Railfall loss 1 Inch

i

Snyder's Lag 5.2 hours Snyder's Peaking Coefficient .625 Test Flood Inflow 7800 CFS PMF Inflow 7800 CFS

RESERVOIR ROUTING AND DAM OVERTOPPING

Test Flood Outflow 7800	CFS
Spillway Capacity at Top of Dam	4000 CPS 51 \$ of Test Flood
Flow Over Spillway at Test Flood	5800 CFS
Spillway Crest Elevation345.Top of Dam Elevation350.Test Flood Elevation351.	1 Feet

D-2

5 4 1 6 4 5 6 7 6 7 6 7 6 7 6 7 6 7 6 7 6 7 6 7 6			ăī.	AN SAFE Tans Br -29-80	DAM SAFETY ANALYSIS-JOB Mfans Rrudk Heservoir D 1-29-80	_ <	NU. 79-905 M- SHELTON	79-905/07 EHJ 16110N-CONN.								
J J <th></th> <th>ะร้า</th> <th>5 n -</th> <th>~~ (</th> <th>0 -</th> <th>•</th> <th>.</th> <th>3</th> <th>0</th> <th>~</th> <th></th> <th>•</th> <th>0</th> <th></th> <th></th> <th></th>		ะร้า	5 n -	~~ (0 -	•	.	3	0	~		•	0			
1 1	,	5*5	n e			· .	••	• • •	•••	• • •	•	•				
K1 K1 <td< th=""><th></th><th>27-3</th><th>- 99 4 V</th><th></th><th></th><th>1 F</th><th>0074ENT 0 5.8 133</th><th>0 4 0 C</th><th>HYDROGR 0 0</th><th>АРН 0 • 1</th><th></th><th>-</th><th></th><th></th><th></th><th></th></td<>		27-3	- 99 4 V			1 F	0074ENT 0 5.8 133	0 4 0 C	HYDROGR 0 0	АРН 0 • 1		-				
1 1	!	; • • • • • • • • • • • • • • • • • • •		າທາ 🛹	0 1	0			. -		1	*	•		:	
			Ĩ		INFLOW M	NDHOGRAPH	THRU L	1 - (ATOPPING		IS					
			18.4 18.4	21.0		•	•	9	7							
		:28,	345•0 350•1	100.0		- 4					1				4 	
		1												i 1	:	
	i								•		,	1				
				*										6 	1	
	•	1)	:		•	:								
						: : : :		- * *	1 • •							
					l				•							
					•					•	: !			:		

ł

•	DATEO 01/24/80. TIMEO 14.20.18. NG	•	DAM SAFFIY Means brog 1-29-60 NHR N	TANALYS Dok reserve NMIN 0	AMALYSIS-JOB NO. Reservir Dam- 1 10 I Day Job 1 0 0 1		79-965/07 ERJ Helton-comm. Hectfication Him imin Hi 1 Luopt Ti 0 0	HE TRC	1PL 7	1 0 1 0	N E L S X	÷	:
		- 50 I I B			ri-plan Nplan	MULTI-PLAN ANALYSES TO BE PERFORMED NPLANE 1 NRTIOE 2 LATIOE 1 .00	S TO BE 0= 2 LRT	BE PERFORME Latio= 1	ED				
	С	COMPU	ITATION OF ISTAG	0F PHF- AQ 1C(1	F- DEVELO	COMPUTATION OF PMF- DEVELOPMENT OF INFLOW HYDHOGRAPH ISTAQ ICOMP IECON ITAPE JPLT JP I 0 0 0 0 0 11MG TARFA SWAP HYDHOGRAPH DATA	DFF-COMPUT DF INFLOW 11APE 11APE 0 14PH DATA	141104 Hydhogra JPL1 0	Fo	INAME I	ISTAGE IA	14410	
COMPUTED BY THE PROGRAM	THE Pac	SPF SPF OGRAM IS			00000 00000	5.80 5.80 PRECIP 1.412	ua i i	448 142.00	15N04 0 6 7 7 7 7 8 9 0 0	1 SAME 1 1 1 966 0.00	P D C V		
-	L & 0 P T 6	57RKR 6.00	0LTKR 0.00-	RTI0 1.6			TRKS RTIOK 6.66 - 1.00 Rograph Data CP= .63 N		CNSTL 00 .10	11 AL 10 - 4	AL SMX RT IMP 0.00 0.00		:
APPNOAIMATE CLAMK CNEFFICIENTS Imit mydrogi 34. 123. 172. 138. 20. 15.	K CAEFFIC IMIT 1 34. 72. 20.	CIENTS HYDHOGR 123. 138. 16.	5404 61V 6404 61V 6424 1114 134	1.90 HOM GIVEN SNYDER CP PH 28 END-OF-PERIOD 242. 111. 13. 13.	1.90 168 CP PER100 357. 90.	STRTUM 1.99 QRCSN= .05 RTIOR= ICIENTS FROM GIVEN SNYDER CP AND TP ARE TC= 6.13 AND R= HYDROGRAPH 28 END-OF-PERIOD ONUINATES, LAG= 5.19 HOUR 123. 242. 357. 435. 454. 476. 138. 111. 90. 72. 58. 47.	RE TC= 6. S1 LAG= 58.	RTIOR= 2.	0 4 0 4 0 4 0 4 0 4 0 4 0 4 0 4 0 4 0 4	00 54 INTERVALS CPm 63 V 329. 38.	LS VOL= 1.00 265. 30.	213. 25.	

.

Ł

	0 5427.	÷			716				0 3355.			-		-	0 939.	;	489.		316.		•		-				•	0 2.	o 1.		• •	•	7 80882.	(26.0925) (.						
.10	Ĭ			Ĭ	.10			0.0	0.0	0.0	0.0	•	0.0	•	0.0		0.00	0.0	00.0	0.00	00.0	00.0			0.00	0.0(٩	•	•	•••	0.0	0.0	3.21	CA)						
2.61		.06	.06	.06	-06	.06	.06	0.00	00.0	00.00	0.00			•		•	0.00	•	• •	•	00.0	0.0			0.00	0 .00	0.00	0.00	•	00.0	0.0	0.00	21.12	(552.)						
11.5	61.5	.16	.16	.16	.16	.16	.16	00	00.0	0.00	0.00	0.00	.0.00	0.00	00.0		00.0	0.00	0.00	0.00		•			00.0	0 • 0 •	•	•	•	••	00.0	0.00	24.99	(635.) (IME	92.	90.	21.62	.16	
1+	42	Ģ	1	45	46	47	4 8	64	50	51	52	53		ភ្ន ភ្ន	6 F 10 V		5 6	99	9	62	. 63	4 i 9 i		67	89		20	2	- 72	21	21	15	NUS		AL VOLUME	æ	2290	21	549.16	6684
00*	A.00	• 00	• 00	.00	• 00	23.00	.00	• 00	.00	-00-	4.00	• 00	e•00 · ·	00.	8.00		11.00	.00	3.00	4.00	5.00	00.9	00.7		20.00	• • • •	• 00	23.00	00	0		• • •			TOTAL	5				
~	-	.02 19.0			~	~	•	-		•	•	~		~ ·					-	-						÷.	-03 22			- ·	•	₩ •			2-HOUR	1123.	32.	21.62	549.15	6684.
-	-	-		1.0		1.	1.0	1.0	1.0	0 - 1	1-0	1.0	1.0				-	-	-	1.0						1 · · ·	-	-				-			1	•				•
	•	•	•	•	•	•	•	•		6.		•	:		•			•		•	1 	•					-	-	•	•	•				24-HOUR		89.	3	513.99	6256.
-	-	-	-	-	-	-	-	-			61	ي ال]] 0	182		200	273	- 228.	186.	150				9	63.	6	163	268.	865	105	Ē	•			6-ноия	6805	193.	16.0	277.24	3375.
10.	- • 1	10.	E0.	E0.	.03	•03	.03	•03	.10	.10	.10	.10	- 10		10.		.01	. 10.	10.			-			.10	.10	.10	-		.10					9-1-9		-		115	5
• 00		.00		• 00		.00	0.00	0.00	E0.		.10	. 40	. 90	4 0			00.00	000	0.00	10.	0 -				.31	16	[6.	16.		m 4	10.1				PEAK	1782.	220.		•	
10.	10.	10.	E0.	E0.	E0.	.0.	50.	.03	EI .	. 16	.20	- 20					5	10.	10.	Π.								7		.	***					- eFS	CMS	NCHES	Ŧ	AC-FT
4	ŝ	•	~	¢	σ	10	11	12	2	· • •	15	16		18	: • • • •	3	22	53	54	25		12		5 M	IE	36	.	÷.	, SE	95	-							-		
•	•	٩.	•	•	?	0.0	:	2.0		;	5.0	0 - 0		• •	19.00		ۍ د	9.0	0.0	•	•	•••	•••		•	2	•		Ĭ	٠	5									
~	æ	•	•	10.	0	•	•	•	٩	•	•	9	•	•			•	•	٩	٩.	•	•	•		•	9	٩	•	•	•	•	i								

۰.

D

-5

f

- ----

t

. . . .

		, ,														,
		0,	0	0,0	.0	.0	.0	3	•0	8			MELIPIL)	AND		
	3			•	, .	,		•)		;•	•	•		
		21	•	•	•		•	•	•			•	•		•	
		31	•	•	•	•	•	•	•		•	•	•		•	_
	- 40	14	•	•	•	•	•	•	•		•	•	•		•	. .
	8	51.	•	•	•	•		•		:		•	•	,	•	
			•	•	•	•	•	•	•		•	•	• •		• •	
		- 0	•	•	•	•				1		• •	•			
		; ;	•	•								•	•		•	
			•		1											
				•			:	• 1								
			•	•	•								•			
			•	•	•	•						, (• •		-	*
			•		•	•						•	• •			ж
			•	:	•							•	•		•	
	_		•	•	•	•	•	•	•		•	•	•		•	(>
	_	10.1	•	•	•	•	•	•	•		•	•	•		•	•
		17.1	 •	•	•	•		•	•			•	÷		•	< :
		18.1	•	•	•	•	•	•	•		•	•	•		•	2
		19. I	•	•	•	•	•	•	•			•	•		•	.
		201									•••••					
		21. 1		•					•		•	•	•		•	_
		22. 1	•		•		. •	•	•		•	•	•		•	
		23.1	•									•		-		
		24.1	•	• •								•	•		•	ر.
		25.1	•	•									•			×
		1.46	•	•								, , ,	•			×
			•	•								•	•			×
			•	•	•							• •	•			×
			•	•												×
																X
		••••	:	•	••••	•••••	• • • • • • • •	•••••								. 74
		1.15	•	•	•	•		•			•	•	•			()4
33.1 1 <td>5</td> <td>1.26</td> <td>•</td> <td>•</td> <td>.• • •</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>•</td> <td>•</td> <td>•</td> <td></td> <td>•</td> <td>():</td>	5	1.26	•	•	.• • •						•	•	•		•	() :
	5	1.1.	•	•	•	•		-	•	_	•	•	•			
	5		•	•		•			•		•	•	•			
			[.●	•							•	•	•			٤ س
	5	10. 10.	•	•	•	•		•	•	_		•	•			
	8	31.	•	•	•	•	_	•	•	_	•	•	•	•		()
39 I Кикикики и и и и и и и и и и и и и и и и	÷.	38.	-	•	•	•						•	•			•
	00-		•	•	•	•	-	•	•			•	• 1			K ,
	.00	۰			.1	•••••		٠	:	•••••	:		XXXXXXXX	XXXXX		
		•	•									•		LXX		× 1
	.00	۰	•	•	•	•		-	•	_	•	•	•	-	LARARARAAN	
	.00	•	•	•	•	•		•	-			•	•		•	۲ »
		٠	•	•	•	•		•	•	 '	•	•	•		•	•
46. 47. 48. 49. 49. 40. 40. 41. 42. 43. 44. 44. 45. 46. 47. 48. 49. 49. 40. 40. 40. 41. 41. 42. 43. 44. 44. 45. 45. 46. 47. 47. 48. 49. 49. 40. 40. 41. 41. 42. 43. 44. 44. 45. 47. 47. 47. 47. 47. 47. 47. 47. 47. 4	00.	٠	•	•	•	•	-	•	•	-		•	•		•	× 1
47 48 49 49 49 40 41 42 43 44 44 45 46 47 49 49 49 49 40 41 41 42 43 44 44 45 46 47 48 49 49 41 41 41 42 43 44 44 45 46 47 48 49 49 41 41 41 42 43 44 44 45 46 47 47	00.		•	•	•	•		•	•	-	•	•	•		•	
			•	•	·	•					•	•	: • 1		•	
	.00		•	•	•	•			•		•	•	•		•	< .
	.00		•	•	·	•	-					•	•		•	
	03 -	50												••••		
	. 00		•	•	-	•	_	•	•	_	•	•	•		•	
	00		•	•	-	•		•	•		•	•	•		•	
	00-		•	•					•		•	•	•			
	. 00		•	•	•	•		•	• •	_		•	•		•	

ł

ĺ ļ -; . ٠ ł 1.00 . ì i • . . ł t ł 1 1 . , . ì . 1 . . ŧ 1 • ; ł ÷ ì 1.1 ٠ 63. 61. 62. なないのです。 D -

ł

1 1	1. 0. 150.	. IE	1917.	1364.	-961 -1	:								•	200		- CC		316.	5°		•					•		****								SURFACE AREA=	
11. 1. <t< td=""><td>1. 0.</td><td>.1.</td><td>-E172</td><td>1108.</td><td>127.</td><td>:</td><td></td><td>53</td><td>INCHE</td><td>-</td><td>AC-1</td><td></td><td></td><td>N •</td><td></td><td>613</td><td></td><td>2215</td><td>253.</td><td></td><td></td><td>ē</td><td>5</td><td>INCH</td><td></td><td>55</td><td>* * *</td><td>;</td><td></td><td></td><td></td><td></td><td></td><td>GLOSS</td><td></td><td></td><td></td><td></td></t<>	1. 0.	.1.	-E172	1108.	127.	:		53	INCHE	-	AC-1			N •		613		2215	253.			ē	5	INCH		55	* * *	;						GLOSS				
1 1		82.	-61+E	896.	- 101			nu	າທາ	Ī	- 1	Ē	HUTH	Ň		163.			203.			2	ţ	ES		Ĩ	:		***		INFLOW	15140	-	CLOSS	00000	NSTPS 1	12	
1. 1. <td< td=""><td></td><td>1</td><td>3839.</td><td>723.</td><td> O</td><td>•</td><td>¢</td><td></td><td></td><td>-</td><td></td><td></td><td></td><td>•</td><td></td><td>268.</td><td>7677</td><td></td><td>162.</td><td></td><td></td><td></td><td>20.</td><td>•</td><td></td><td></td><td></td><td></td><td></td><td></td><td>YDROGRAF</td><td>I COMP</td><td>-</td><td>AVG Avg</td><td></td><td>NSTOL 0</td><td></td><td></td></td<>		1	3839.	723.	O	•	¢			-				•		268.	7677		162.				20.	•							YDROGRAF	I COMP	-	AVG Avg		NSTOL 0		
1 1			Ē			_	-HOOH-	3403. 06	5.46	38.62]687. 200)		 S		-		r .				anon-	6805	.591	10.91	3375.	4162.	1		•	орнол		IECON	00 80U	IRES				
1 1		. 66		83 .	• • •		-	12/1	10.12	257.00	3128.			- <u>-</u>							•	r –	89.	20.24	44.61c	7717.	• •	-		KAPH ROUI	AKE: 1	ITAPE	0 A T	AME.		AMSKK D. DDD		
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		267.		_			<u>.</u>	200				7 1	PLAN 1.			534.					_ n	1123.	32.			8245	•			5 ING	ERTOPPING					× 000 0		
1. 124. 91. 124. 504. 761. 2532. 2061. 304. 761. 2532. 246. 1145. 249. 1145. 249. 1145. 1523. 2229. 229. 2229. 1523. 5063. 4122. 2229. 1523. 5063. 4122. 2229. 1523. 5064. 122. 5063. 4122. 609. 489. 21.62. 5063. 4122. 609. 489. 122. 514. 122. 514. 122. 1145. 1122. 214. 1145. 1149.	55. 50.	354.	3065.	Э7А.	32.		-		_	_			۰ م		••••••••••••••••••••••••••••••••••••••	707.	6129	756.	65.				_				•		÷					dwd1	Ð	15K .000		•
124. 124. 124. 124. 124. 124. 124. 124.		504.	2532.	304.	13.			40441.	10.81	274.58	3342		•	.1.	81.	1007.	5063	609	27.	. ÷.			2290.	21.62	349.10 6684.	8245.	1		:		:	-	-					
	124	761.	-1902	245.									•	- I -		1523.	4122	1001	12.													-	4	51	2	SPRAT 0		
4 M 2 V 2 V 2 V 2 V 2 V 2 V 2 V 2 V 2 V 2	996 146	1224	1677	141	-								•			2448	3355		, , , , , , , , , , , , , , , , , , ,												•	010	•					

~ ۲ ____

	DAMW IC	124
AIA	COQU E KPU	۲. ۱
HVO	0000	2.1
	TOPEL	350.1

-(___

,

1. PLAN 1. RATTO 1 STATION

END-OF-PERIOD MYOROGHAPH OHDINATES

5		, ,		-		-			
•	••	-	-	2.		28.	6].	- 66	
146.	143.	127.	106.	87.		59 .	49.	11.	
32.	37.	51.	99.	160.		311.	435.	654.	Ì
1689.	2489.	3245.	3755.	3402.	~	3205.	2670.	2186.	171
1456.	1187.	965.	783.	634.		410.	337.	273.	221.
179.	145.	117.	95.	75.	58.		29.	17.	
5.	•		2 · · ·	· · · · · · · · ·					:
				STORAGE	ų				
	• • 0 ==	. 0.		•		•	•••	•0	
•	••					З.	÷	8.	
10.	10.	10.	9.	٦.	• •	6°	5.	÷	
•••			İ		÷			29	•
58.	76.	•£6		106.		92.	80.	70.	
52.	45.	39.		29.		21.	19.]6.	-
12.		•6		. 7.		.		ج• ج	~ ~
۱.		l.		•					
				STA65		-			
345.0	345.0	345.0	345.0	345.0	345.0	345.0	345*0	345.0	345
345-0	345.0	345.0	345.0	345.0	345.1	345.2	345.3	345.4	346
345.6	345.6	345.5	· 345.5 ·	- 345 4 -	- 345+3	345.3	345.3	345.2	345.2
345.2	345.2	345.3	345.4	345.6	345.8	345.9	346.2	346.5	94
347.9	348.7	4.946	349.9	350.0	349.8	349.4	348.9	348.4	346
		347.0	346,7	346.5		- 346.1	346.8	- 345.8 -	54E
345.6	345.6	345+5	345.4	345.4	345.3	345.3	345.2	345.1	ň
345.1	345.0	345.0	345.0	345.0					

. ...

PL AK

	72-HUUR TOTAL VOLUME	-				i .	
	24-HOUK 72-I					-	
	PEAK 6-HOUR	3902. 3395.		5.44	134.29		2076.
• • • • •		CF S	CMS	INCHES	I	AC-FT	S CU M

1

.. ... · -------

ł

1

D-9

• •

•••

72 72 73 73 74 73 75 74 74 74 75 74 74 74 74 74 75 74 74 74	72 72 72 72 73 73 73 73 73 74 74 74 74 74 74 74 74 74 74 74 74 74 74 74 74 74 74 74 74 74 74 74 74 74 74 74 74 74 74 74 74 74 74 74 74 75 74 74 74 74 74 75 74 74 74 74 74 75 74 74 74 74 74 75 74 74 74 74 74 75 74 74 74 74 74 75 74 74 74 74 74 75 74 74		
72.0 22. 1 72.0 23.10 23.10 7.0 25.10 23.10 7.0 25.10 23.10 7.0 23.01 23.01 7.0 23.01 23.01 7.0 25.01 23.01 10.0 10 10 11.0 23.01 23.01 11.0 23.01 23.01 11.0 23.01 23.01 11.0 23.01 23.01 11.0 23.01 23.01 11.0 23.01 23.01 11.0 23.01 23.01 11.0 23.01 23.01 11.0 23.01 24.01 11.0 24.01 25.01 11.0 10 10 11.0 10 10 11.0 10 10 11.0 10 10 11.0 10 10 11.0 10 10 11.0 10 10 11.0 10 10	72 1 73 72 74 74		
73.0 73.1 7.0 75.1 7.0 75.1 7.0 75.1 7.0 75.1 7.0 70 7.0 11	72.00 25.10 7.00 25.10 3.00 26.11 3.00 28.1 4.00 30.1 5.00 32.1 5.00 32.1 5.00 32.1 5.00 32.1 5.00 32.1 5.00 33.01 11.00 35.01 12.00 34.01 13.00 10 14.00 35.01 15.00 34.01 11.00 35.01 11.00 40.1 12.00 0 13.00 0 14.00 1 15.00 0 11.00 1 11.00 1 11.00 1 12.00 1 12.00 1 12.00 1 12.00 1 12.00 1 11.00 1 12.00 1 12.00 1 12.00 1 12.00 1 <td></td> <td></td>		
73.0 23.1 7.0 24.1 7.1 24.1 7.1 24.1 7.1 24.1 7.1 24.1 7.1 24.1 7.1 24.1 7.1 24.1 7.1 24.1 7.1 24.1 7.1 24.1 7.1 24.1 7.1 24.1	73.00 23.1 7.00 24.1 7.00 28.1 5.00 28.1 5.00 28.1 5.00 28.1 5.01 28.1 5.01 28.1 5.01 31.1 5.01 32.1 6.01 11.0 11.00 35.01 11.00 35.01 11.00 35.01 12.00 34.01 12.00 34.01 12.00 34.01 12.00 34.01 12.00 01 12.00 10.0 13.00 10.0 14.00 10.0 15.00 10.0 15.00 10.0 10.00 10.0 11.00 10.0 12.00 10.0 13.00 10.0 14.00 10.0 15.00 10.0 10.00 10.0 10.00 10.0 10.00 10.0 10.00 10.0		
1 0 0 2 0 0 5 0 0 5 0 0 5 0 0 5 0 0 6 0 0 1 0 0	1 0		
25.10 27.00 27.1 50.00 27.1 50.00 30.1 50.00 31.0 50.00 31.0 50.00 31.0 50.00 31.0 50.00 31.0 50.00 32.0 50.00 31.0 50.00 31.0 50.00 32.0 50.00 33.0 50.00 33.0 50.00 34.0 50.00 34.0 50.00 34.0 50.00 34.0 50.00 34.0 50.00 34.0 50.00 34.0 50.00 34.0 50.00 34.0 50.00 34.0 50.00 34.0 50.00 34.0 50.00 34.0 50.00 34.0 50.00 34.0 50.00 34.0 50.00 34.0 50.00 34.0 50.00 34.0	7 65 10 7 26 10 5 26 1 5 26 1 5 26 1 5 26 1 5 33 0 1 10 1 5 33 0 1 10 1 5 31 0 1 10 1 5 0 1 1 10 1 5 0 1 5 0 1 5 0 1 6 1 0 7 1 0 7 1 0 7 1 0 7 1 0 7 1 0 7 1 0 7 1 0 7 1 0 7 1 0 7 1 0 7 1 0		
2 0 1 0 2 0 1 0 1 0 1 0 1 0 1 0 1 0 1 0 1 0 1 0 1 0 1 0 1 0 1 0 1 0 1 0 1 0 1 0 1 0 1 0 1 1 0 1 0 1 1 0 1 0 1 0 1 0 1 0 1 0 1 1 0 1 0 1 0 1 1 0 1 0 1 0 1 0 1 0 1 0 1 0 1 0 1 1 0 1 0 1 0 1 0 1 0 1 0	2.00 27.1 3.00 27.1 3.00 32.1 3.01 33.01 3.01 35.01 3.01 35.01 3.01 01 3.01<		
	2 2		
200 271 7 201 7 310 7 320 10 35 11 35 12 31 13 10 14 35 15 01 15 01 15 0 16 0 17 0 16 0 17 0 17 0 18 0 19 0 10 1 10 1 10 1 10 1 10 1 10 1 10 1 10 1 10 1 10 1 10 1 10 1 10 1 10 1 10 1 10 1 10 1 10 1 10 </td <td>29.1 29.1 29.1 29.1 10 31.1 11 32.01 11.00 34.01 11.00 35.01 11.00 <</td> <td></td> <td></td>	29.1 29.1 29.1 29.1 10 31.1 11 32.01 11.00 34.01 11.00 35.01 11.00 <		
5.00 30.1 7.00 31.1 8.00 32.01 9.00 35.01 11.00 35.01 12.00 36.01 13.00 01 14.00 36.01 15.00 39.01 16.00 01 17.00 10 17.00 10 17.00 10 17.00 10 17.00 10 17.00 10 17.00 10 17.00 10 17.00 10 17.00 10 17.00 10 17.00 10 18.00 10 19.00 10 10.00 10 10.00 10 10.00 10 10.00 10 10.00 10 10.00 10 10.00 10 10.00 10 10.00 10 10.00 10 10.00 10 </td <td>7.0 28.1 7.0 31.1 7.0 32.1 9.0 32.1 9.0 32.1 9.0 34.01 11.0 35.01 12.0 36.01 12.0 36.01 12.0 36.01 12.0 36.01 12.0 36.01 12.0 36.01 12.0 37.01 12.0 31.0 12.0 31.0 12.0 31.0 12.0 31.0 12.0 31.0 12.0 31.0 12.0 31.0 12.0 31.0 12.0 31.0 12.0 31.0 12.0 1.0 12.0 1.0 12.0 1.0 12.0 1.0 12.0 1.0 12.0 1.0 12.0 1.0 12.0 1.0 12.0 1.0 13.0 1.0 10.0</td> <td></td> <td></td>	7.0 28.1 7.0 31.1 7.0 32.1 9.0 32.1 9.0 32.1 9.0 34.01 11.0 35.01 12.0 36.01 12.0 36.01 12.0 36.01 12.0 36.01 12.0 36.01 12.0 36.01 12.0 37.01 12.0 31.0 12.0 31.0 12.0 31.0 12.0 31.0 12.0 31.0 12.0 31.0 12.0 31.0 12.0 31.0 12.0 31.0 12.0 31.0 12.0 1.0 12.0 1.0 12.0 1.0 12.0 1.0 12.0 1.0 12.0 1.0 12.0 1.0 12.0 1.0 12.0 1.0 13.0 1.0 10.0		
5.00 20.1 10 32.1 10 32.01 11.0 35.01 12.0 36.01 12.0 36.01 12.0 36.01 15.0 38.01 15.0 38.01 15.0 38.01 15.0 38.01 15.0 38.01 15.0 38.01 15.0 38.01 15.0 38.01 15.0 38.01 15.0 38.01 15.0 38.01 16.0 1 17.0 1 10.1 1 10.1 1 10.1 1 10.1 1 10.1 1 10.1 1 10.1 1 10.1 1 10.1 1 10.1 1 10.1 1 10.1 1 10.1 1 10.1 1 10.1 1	5.00 39.1 10 32.1 6.00 32.1 6.00 32.1 6.00 34.01 11.00 35.01 12.00 36.01 14.00 38.01 15.00 39.01 14.00 38.01 15.00 39.01 15.00 39.01 15.00 39.01 15.00 39.01 15.00 39.01 15.00 39.01 15.00 39.01 15.00 39.01 15.00 39.01 15.00 39.01 15.00 39.01 15.00 39.01 15.00 41.00 15.00 41.00 15.00 41.00 15.00 41.00 15.00 41.00 15.00 41.00 15.00 41.00 15.00 41.00 15.00 41.00 15.00 41.00 15.00 41.00 15.00		
7 31 7 31 7 32 1 0 1 34 1 0 <	7 31 8 32 9 32 9 35 1 0 <		
1 32.1 1 52.1 1 53.01 1 55.01 1 0 <t< td=""><td>1 3 1</td><td></td><td></td></t<>	1 3 1		
	8.00 32.1 4.00 34.01 11.00 35.01 12.00 36.1 13.00 36.1 14.00 36.01 15.00 39.01 14.00 36.01 14.00 36.01 14.00 36.01 15.00 39.01 16.00 1 17.00 1 18.00 1 19.01 0 11.00 1 22.00 46 22.00 46 23.00 46 10.00 1 22.00 46 23.00 46 10.00 1 20.01 0 20.02 1 20.03 1 20.04 1 20.05 1 20.06 1 20.07 1 20.08 1 20.09 1 20.00 1 20.01 0 20.01 0 <		
V 00 33.01 11.00 35.01 12.00 37.01 14.00 39.01 15.00 39.01 14.00 31.01 15.00 39.01 14.00 11.0 15.00 39.01 16.00 10.0 17.00 11.0 18.00 10.0 19.00 10.0 10.01 0.0 10.02 10.0 10.03 10.0 10.04 10.0 10.05 10.0 10.06 10.0 10.07 10.0 10.08 10.0 10.09 10.0 10.05 10.0 10.06 10.0 10.07 10.0 10.08 10.0	V 00 33.01 11.00 35.01 12.00 37.01 13.00 37.01 14.00 39.01 15.00 39.01 16.00 10 17.00 10 18.00 01 19.00 10 19.00 10 19.00 10 19.00 10 19.00 10 19.00 10 19.00 10 10.00 10 10.00 10 10.00 10 10.00 10 10.00 10 10.00 10 10.00 10 10.00 10 10.00 10 10.00 10 10.00 10 10.00 10 10.00 10 10.00 10 10.00 10 10.00 10 10.00 10 10.00 10 10.00 10 <td></td> <td></td>		
12.00 35.01 13.00 36.01 15.00 36.01 15.00 39.01 15.00 39.01 15.00 39.01 15.00 39.01 15.00 39.01 15.00 39.01 17.00 10 17.00 10 17.00 10 17.00 10 17.00 10 17.00 10 10.01 10 10.02 10 10.03 10 10.04 10 10.05 10 10.06 10 10.07 10 10.07 10 10.07 10 10.07 10 10.07 10 10.07 10 10.07 10 10.07 10 10.07 10 10.07 10 10.07 10 10.07 10	11.00 35.01 12.00 36.01 13.00 37.01 15.00 38.01 15.00 39.01 15.00 39.01 16.00 10 17.00 11 19.00 1 19.00 1 19.00 1 19.00 1 19.00 1 19.00 1 19.00 1 10.00 1 10.00 1 10.00 1 10.00 1 10.00 1 10.00 1 10.00 1 10.00 1 10.00 1 10.00 1 10.00 1 10.00 1		
1 0 1			
12.00 36 01 15.00 39 01 15.00 39 01 17.00 11 0 1 17.00 11 0 1 19.00 12 0 1 19.00 10 1 0 1 19.00 10 1 0 1 19.00 10 1 0 1 19.00 10 1 0 1 19.00 10 1 0 1 0 19.00 10 1 0 1 0 1 19.00 10 1 0 1 0 1 0 10.00 1 0 1 0 1 0 1 0 1 10.00 1 0 1 0 1 0 1 0 1 10.00 1 0 1 0 1 0 1 0 1 0 1 0 1 0 1	12.00 36 0 14.00 39 0 15.00 39 0 15.00 39 0 15.00 41 0 17.00 11 0 19.00 43 22.00 46 23.00 47 24.00 1 25.00 46 27.00 1 28.00 47 29.00 47 20.01 1 21.00 1 22.00 50 23.00 51 24.00 1 25.00 1 26.00 1 27.00 53 28.00 1 29.00 1 20.00 1 20.00 1 20.00 1 20.00 1 20.00 1 20.00 1 20.00 1 20.00 1 20.00 1 20.00		
13.00 37. 01 15.00 39. 01 15.00 39. 01 15.00 39. 01 15.00 40. 10 17.00 41. 0 1 17.00 41. 0 1 17.00 41. 0 1 19.00 45. 0 1 22.00 45. 0 1 23.00 47. 0 1 22.00 46. 1 0 1 23.00 47. 0 1 0 1 24.00 59. 1 0 1 0 1 25.00 40. 50. 1 0 1 0 1 25.00 51. 1 0 1 0 1 0 1 26.00 55. 1 0 1 0 1 0 1 26.00 55. 10 1 0 1 0 1 0 1 <	13.00 37.01 01 15.00 36.01 01 15.00 39.01 0 15.00 40 0 15.00 40 0 17.00 41 0 19.00 40 0 19.00 40 0 20.00 40 0 21.00 40 22.00 40 23.00 40 24.00 1 25.00 1 26.00 1 27.00 40 28.00 40 29.00 1 20.00 1 20.00 1 20.00 1 20.00 1 20.00 1 20.00 1 20.00 1 20.00 1 20.00 1 20.00 1 20.00 1 20.00 1 20.00 1 20.00 1 20.00		
15.00 38 01 15.00 39 01 11.00 41 12.00 41 13.00 41 20.00 44 21.00 45 22.00 46 23.00 47 23.00 46 24.00 40 25.00 1 26.00 1 27.00 1 28.00 46 29.00 47 20.01 1 20.02 1 20.03 1 20.04 1 20.05 1 20.06 1 20.07 1 20.08 1 20.09 1 20.00 1 20.01 1 20.02 1 20.03 1 20.04 1 20.05 1 20.06 1 20.07 1 20.08 1 20.09 1	14.00 38. 01 15.00 39. 01 11.00 41. 0 11.00 41. 0 11.00 43. 0 20.00 44. 0 21.00 45. 0 22.00 46. 0 23.00 46. 0 23.00 46. 0 23.00 46. 0 23.00 48. 0 100 1 0 100 1 0 3.00 51. 0 3.00 51. 0 3.00 53. 1 3.00 53. 1		
17.00 19 11.00 11 11.00 11 12.00 11 13.00 11 14.00 11 15.00 11 10.00 11 11.00 10 11.00 10 12.00 10 13.00 10 14.00 10 15.00 10 10.00 10 10.00 10 10.00 10 10.00 10 10.00 10 10.00 10			
100 1 0 1 0 1 1100 44 20 1 0 1 22000 44 1 0 1 0 1 22000 46 1 0 1 0 1 0 1 2200 46 1 0 1 <	16.00 40 17.00 41 19.00 43 20.00 44 21.00 45 22.00 46 23.00 48 11.00 49 12.00 1 22.00 48 23.00 48 23.00 48 20.01 1 20.02 1 20.02 1 20.02 1 20.05 1 20.05 1 20.05 1 20.05 1 20.05 1 20.05 1 20.05 1 20.05 1 20.05 1 20.05 1 20.05 1 20.05 1 20.05 1 20.05 1 20.05 1 20.05 1 20.05 1 20.05 1 20.05 1 20		
17.00 11 19.00 42 19.00 43 22.00 44 23.00 47 22.00 48 23.00 47 24.00 48 25.00 49 26.00 48 27.00 49 28.00 49 29.00 40 20.00 10 30.05 10 30.05 10 40.055 10 53.00 10 54 10 54 10 55 10 56 10	17.00 +1. 19.00 +3. 20.00 +4. 21.00 +5. 22.00 +6. 23.00 +7. 23.00 +7. 24.00 -1.0 1.00 -9. 24.00 -1.0 1.00 -1.0 24.00 -1.0 25.00 +6. 25.00 +6. 25.00 +6. 25.00 +6. 25.00 +6. 25.00 +7. 25.00 +6. 25.00 +7. 25.00 +6. 25.00 +7. 25.00 +7. 20.00 +7.		
19.00 +2 20.00 +4 21.00 +5 22.00 +6 22.00 +6 23.00 +1 200 51 300 51 300 53 100 9 100 9 100 9 100 10 100 10 100 10 100 10 100 10	19.00 +2 20.00 +4 21.00 +5 22.00 +6 23.00 +6 24.00 +1 25.00 10 26.00 10 27.00 10 28.00 10 29.00 53 20.05 10 20.05 10 20.05 10 20.05 53		
			· · · · · · · · · · · · · · · · · · ·
	71.00 45. 73.00 46. 73.00 47. 73.00 49. 1.00 49. 2.00 59. 2.00 59. 4.00 52. 1.0 10. 1.0 10.		• • • • • • •
			• •
			• • • • • • • • • • • • • • • • • • • •
			•
2.00 59. 2.00 50. 3.00 51. 5.00 52. 5.00 54. 1.0. 7.00 55. 10. 10. 10. 10. 10. 10. 10. 10			· · · · · · · ·
3.00 51	3.00 51 1 0. 4.00 52		
4.00 52. 5.00 53. 6.00 54. 1.00 10 1.00 10 1.00 10 1.00 10 1.00 10	5.00 55. 10. 10. 10. 10. 10. 10. 10. 10. 10. 10	• • • • • • • • • • • • • • • • • • •	•
		• • •	
7.00 56. 10 8.00 56. 10			• • •
2.66 55. 10 8.66 55. 10	6.00 54. I		• • • •
5 10 		_	• • •
10	. IO		
		· · · · · · · · · · · · · · · · · · ·	•
		· · · · · ·	• • • •

-

t

-



STATION I. PLAN I. RAIIO 2

•

Ì

-!

I

ļ

ļ

END-OF-PERIOD HYDROGRAMM ONDINATES

270.	68.	2151.	3545.	432.	15.			•	· · · · · · ·	 	22.	2.					348.4	349.7	346.2	345.1										
2112	79.	1340.	4252.	535.	29.			•	· ••••••••••••••••••••••••••••••••••••	 112.	26.	•						350.2	346.3	345.2										
134.		.198	5178.	662.	53.				10.	 122	30.	5.		1				350.7	346.5	345.3			VOLUME	2290.		549.12	6684.	- 8245		
64.	113.	637.	6246.	818.	83.			•••		132.	34.	۲.			345.0 345.1			351.0	346.8				UR TOTAL	•		12				
22.	136.	475.	7237.	1011.	112.			•		 140.	40.				345.2	34545		351.4	0.746	- 345+5			2	32.		ų,	. 6684.	8445.	· · · · · · · · · · · · · · · · · · ·	
ç.	170.	. • 66	7412.	1250.	146.	۶.	STORAGE	. .		144.	47.	10.	•	STAGE		345.6	346-0	351.5	347.3	345.6	0-545		1 24-HOUR		20	S.				
2	208.	210.	7609.	1546	184.	э.		•••			54.	12.	:		345-0	145.7	34547	351.5	347.7	•	345.0	58			T	277.24	3375.			
•	250.	121.	6743.	1907.	228.	÷		••		136.	63.	14.				9+5-6 9+5-8	94545	351.2	348.1		345.0	- 45 . 00HOURS	:	221.	1			•		
-	286.	76.	5195.	2349.	282.	5.		•••		123.	73.	16.	•					350.7	348.6	345.9	345.1			CHO SHO	INCHES	H	AC-FT	THOUS CU H		
-	296.	63.			349.	8.	:		•	97.	85.	19.	:		345-0					346.0 ···	_	IS 7812 AF	•					-		

+4

٠

1 1

;

. . ٠ , ı. ł 1 : ł i i 1 • . ł ļ : . 1 64. 1 64. 1 65. 1 65. 1 65. 1 65. 1 65. 1 701. . 701. . 721 731 731 751 D-14 ٠

-• ·-

14 -

ł

1

• • •

_

UPENAT ION	STATION	AREA	PLAN			AFIOS APP	RATIOS APPLIED TO FLOWS	SMU		
				20	1.00					
нтриобядри ат	۸۲ ۱	5.A0 15.02)		3891.	7782. 220.38) (
HOUTED TO	~ ~	5.80 15.02)	~~~	3962. 110.491 (7812. 221.22) (•		, , , , , , , , , , , , , , , , , , ,		
				:			1	;		
			•							
	•					 	: : : : :			
							4	1990 A 1990 - 1991 - 198	- - - - -	-
	ļ								:	
						-		i i i		-
		- - - -		, , , ,	2	•		:		
		-	4 4						1	*
	·									
				•	'	:	:	;	1	ï
					·		÷	·		
		!			3				;	

-

ł

00°476 01 03E 00°476 001 00 00	MAXIMUM MAXIMUM DUMATION Storage Outflow Over Top Ac-FT CFS Hours	106. 3902. 0.00 144. 7812. 8.00	•			•	 •			
345.00 0.	H I I	004 004	•	an ann an Anna		· · · · · · · · · · · · · · · · · · ·			•	
ELEVATION Storage Outflow	D MAAIMUM Reservoih N.S.Elev	-50 349.99 •00 351.53	· · ·				· · ·			

t

MEANS	BROOK	RESERVOIR	DAM
-------	-------	-----------	-----

Α.	Size Classification	
Heigh	nt of dam = 50 ft.; hence intermediate	
Stora	age capacity at top ofwall (elev.350.1)= <u>373</u> AC-FT.; hence	small
Adopt	ed size classificationintermediate	
B.i)	Hazard Potential	
	Failure would result in the loss of more than a few lives,	
	many homes and damage to the village of Huntington.	
ii)	Impact of Failure of Dam at Normal Pool (Spillway crest)	
	It is estimated from the rule of "thumb" failure hydrograph the following adverse impacts are a possibility by the fail his dam.	
	a) Loss of homes 25-30 ;	
	b) Loss of buildings <u>6±</u> ; c) Loss of highways or roads 2-3 ;	
	d) Loss of bridges;	
from	The failure profile can affect a distance of <u>11500</u> feet the dam.	
с.	Hazard Potential Classification3	
HAZAR	D SIZE TEST FLOOD RANGE	
Hig	gh Intermediate PMF	
Adopt	ed Test Flood = PMF = 1020	CSM
	=	CFS
D.	Overtopping Potential	
	Drainage Area 3519 acres = 7.65 sq. r	miles
	Spillway crest elevation = 345.0	NGVD
	Top of Dam Elevation = 348.0 (350.1 - top of wall)	NGVD
	um spillway discharge	
"test	ity without overtopping of dam = 4000 flood" inflow discharge = 7800	_CFS _CFS
"test	flood" outflow discharge =7800	CFS

D-17

•# --

-•

•

, ž.

MEANS BROOK RESERVOIR DAM

J

1

Dam Failure Analysis

1. Failure discharge with pool at spillway $(elev. 345.0) = 19600$ CFS						
2. Depth of water in reservoir at time of failure = <u>30</u> ft.						
3. Maximum depth of flow downstream of dam = 16 ft.						
4. Water surface elevation just downstream) 316 of dam at time of failure) =NGVD						
The failure discharge of 19600 CFS will enter and flow down-						
stream 11500 feet until the brook enters the Farhill River						
Valley storage in this <u>11500</u> feet length of brook is <u>substantial in</u>						
reducing the discharge. Also due to roughness characteristics,						
obstructions and frictional losses, it is very likely that the						
unsteady dam failure flow will dissipate its wave and kinetic						
energy and thus convert to steady and uniform flow obeying Manning's						
formulae <u>11500</u> feet downstream. The failure profile will have						
the following hydraulic characteristics:						

DISTANCE FROM THE DAM	WATER	SURFACE	ELEVATION	IIGVD	REMARKS
0		345.0			Upstream of dam
100 1000		316.0			
4000		304.6 302.2			
8000		252.0			Huntington
10500 11500		232.0 232.0			Farhill River
		25210			i uliili kivel
Beyond 11500 feet failure discharge will	flow in	the below	given ch	annel	<u>characteristics</u>
Q =4700	CFS;	S =		.005	
n = .05	; b =	20	;	d =	2
Side slopes = 1V on 5H	• •		·,	u = .	<u>د</u>

die 1

D-18

•••• •

"Rule of Thumb Guidance for Estimating Downstream Dam Failure Analysis"

DATA

Name of Dam	Means Brook F	Rese:	rvoir	Dam					
Location	Town of Shelt	on							
Drainage Area	7.65	sq.	mi.,		of I	Dam	348.0)	1 IG VD
Spillway Type	Overflow -	oáe	e_, (Crest	of	Spi	llway	345.0	NGVD
Surface Area 3	Crest Elev.	24	Acre	es = .		.04		_sq. mi	•
Pool Bottom Nea	ar Dam =		315		?	:GVD	*		
Assumed Side Si	lopes of Emban	kmer	nts =		2:	1			
Deptn of Pool a	at Dam (Yo) =	<u> </u>		30		Fe	eet*		
Mid-Height Elev				332		_NG			
Length of Dam a	at Crest =			430		Fee	et		
Length of Dam a	at Mid-Height	=		285		Fee	et		
25% of Dam Leng							_Feet	:	
Step 1									
	ge (S) at time l to spillway			ure _		268	A	-FT	

Step 2

ì

į

Peak Failure Discharge $Q_{p1} = 8/27 W_b \sqrt{g} Yo^{3/2}$ = <u>1.68</u> W_b Yo^{3/2} = <u>19600</u> cfs

- 4

ير يوم

Failure is assumed to coincide with pool elevation at top of dam. * Referring to toe of dam on the downstream face.

D-19

The Farhill River is located 11500 feet downstream of Means Brook Reservoir dam. There is a 70 foot drop into the Farhill River which will cause the dissipation of wave and kinetic energy of the failure discharge. Approximately, the water surface elevations between the Means Brook Reservoir dam and the Farhill River will be as given on Dam Failure Analysis. The increase of depth in the Farhill River due to failure of Means Brook Res. dam is estimated to be 2 feet.



BY FCB DATE 1/27/79 SUBJECT DAM INSPECTION SHEET NO 2 OF 5 CHKO BY BOR DATE 1-21-80 STUDIES JOB NO 79-905 107
DOWNSTREAM W.S.EL. COMPUTATIONS
NAME OF DAM: Men Kroce Reservoir
SECTION LOCATION: 1000 DOWNSTREAM OF DAM
USING : $Q = \frac{1.486}{n} A R^{\frac{2}{3}} S^{\frac{1}{2}}$ NHERE: $n = 0.05$ S=SLOPE = $\frac{.0067}{\frac{1}{7}}$
EL. 340EL,
EL 320 550' 310
EL,300 S. 100' 150 BI WO CARNNEL SECTION 000 500
QF = 19600 cfs STORAGE (S) 268 AC-FT
E.E.Y FIREA WP R R=13 512 1.486/ Q DEPTH 310 6150 682 9.02 4.33 .09 29.72 63314 10'
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$
EL 200 15746 cts 19600 cts
EL. 20
EL. ~ w 10000 C+30000 30000 China Ch
$V_{1} = \frac{k \rho_{1.5.0}}{2} \times \left(\frac{175 + 600}{2} \times 1000 \div 43,560\right) \frac{1}{2} = 52.7 \text{ Ac} - 52.7 Ac$
$V_2 = \frac{161+5.2}{2} \times 8.90 \times \frac{1}{2} = \frac{51.8}{2} \text{ Ac-ft } V_{A} = \frac{52.3}{2} \cdot \frac{ft}{2}$
GPZ= GPI (1-VAVES) - 15779 = fs
D-22 MENT DOWN STREAM SECTION 3000 FT. DEURCELL ASSOCIATES





MICROCOPY RESOLUTION TEST CHART NATIONAL BUREAU OF STANDARDS-1963-A

a a set of the set of



÷

•

BY FLE DATE 1/27/79 SUBJECT DAM INSPECTION SHEET NO 3 OF 5 D BY BOA DATE 1-21-8C STUDIES NO 79-905/07 DOWNSTREAM W.S.EL. COMPUTATIONS NAME OF DAM: Means Brook Pascroic SECTION LOCATION: 4000' DOWNSTEERM OF DAM USING : Q = 1.486/n A R 23 5 1/2 WHERE: n= 0.05 S=SLOPE = .0067 /// EL. 320 _ 700 EL.310 700' 625' 600' 550' 500' 800 éco 400 400 CARNNEL SECTION QP = 15779 cfs STORAGE (5, 268 AS.FT 51/2 1.486/n ELEY FIREA WP RZS R Q DEPTH 5' 2.71 305 4.46 .08 36679 5633 1275 29.72 123784 10' 12250 1400 8.75 4.25 29.72 .03 210 2150 1100 1.95 1.56 .03 29.72 7974 2 32 EL 320 9253 :/s 15779 cts E1. 302.8 E1. 302.1 EL. 3101 EL. 300 Eden 10000 1000-1 60000 • • C + 5 1 4.6+2.8 (600+1140 x 3000:43,560) 1/2 = /// AC-FT QP2 = QP1 (1-1/5) = 9253 CPS V2= 46.+ 21 x (600+1120x 3000- 425- 1/2 = 19 Ac-FT VAN 105 C.FT. GPZ= QPI (1-VAVES) - 9591 cfs STAGE DISCHARGE 959 & ELEV : 302.2 OR A E 2.2 AT VENT DOWNSTREAM SECTION 4000 FT. DURCELL ASSOCIATES D-23





RATING CURVE DEVELOPMENT

Means Brook Reservoir Dam

-	٠	-	-		
Sp	•				
30	1	T.	1	w	av

30 Inch Pipe

ţ

Q = C L H 3/2C = 3.5 L = 100 feet Q = c a $(2gh)^{1/2}$ c = .6 a = 4.9 square feet

24 Inch Blowoff $Q = c a (2gh)^{1/2}$ c = .6a = 1.4 square feet (16 inch pipe at outlet)



-





-,:-

-

•



APPENDIX E

INFORMATION AS CONTAINED IN THE

NATIONAL INVENTORY OF DAMS



1

- 1

ł

1

ŧ

.

1

I

I

