

MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A

AD-A142 986

CONNECTICUT WESTERN COASTAL AREA  
FAIRFIELD , CONNECTICUT

1

**HEMLOCKS RESERVOIR DAM  
CT 00018**

**PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM**

DTIC FILE COPY



DTIC  
JUL 9 1984  
A

This document has been approved for public release and sale; its distribution is unlimited.

DEPARTMENT OF THE ARMY  
NEW ENGLAND DIVISION, CORPS OF ENGINEERS  
WALTHAM, MASS. 02154

AUGUST 1978

84 06 29 065



DEPARTMENT OF THE ARMY  
NEW ENGLAND DIVISION, CORPS OF ENGINEERS  
424 TRAPELO ROAD  
WALTHAM, MASSACHUSETTS 02154

REPLY TO  
ATTENTION OF:  
NEDED

SEP 28 1978

Honorable Ella T. Grasso  
Governor of the State of Connecticut  
State Capitol  
Hartford, Connecticut 06115

Dear Governor Grasso:


I am forwarding to you a copy of the Hemlocks Reservoir Dam Phase I Inspection Report, which was prepared under the National Program for Inspection of Non-Federal Dams. This report is presented for your use and is based upon a visual inspection, a review of the past performance and a brief hydrological study of the dam. A brief assessment is included at the beginning of the report. I have approved the report and support the findings and recommendations described in Section 7 and ask that you keep me informed of the actions taken to implement them. This follow-up action is a vitally important part of this program.

A copy of this report has been forwarded to the Department of Environmental Protection, the cooperating agency for the State of Connecticut. In addition, a copy of the report has also been furnished the owner. The Bridgeport Hydraulic Company, 835 Main Street, Bridgeport, Connecticut 06604.

Copies of this report will be made available to the public, upon request, by this office under the Freedom of Information Act. In the case of this report the release date will be thirty days from the date of this letter.

I wish to take this opportunity to thank you and the Department of Environmental Protection for your cooperation in carrying out this program.

Sincerely yours,

  
JOHN P. CHANDLER  
Colonel, Corps of Engineers  
Division Engineer

Incl  
As stated

HEMLOCKS RESERVOIR DAM

CT 00018

CONNECTICUT WESTERN COASTAL AREA  
FAIRFIELD, CONNECTICUT

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

Accession For  
S GRAB  
TAB  
A1

0218  
COPY  
INSPECTOR  
2

PHASE I REPORT  
NATIONAL DAM SAFETY PROGRAM

Name of Dam: HEMLOCK RESERVOIR DAM

State Located: Connecticut

County Located: Fairfield County

Stream: Cricker Brook


Date of Inspection: 21 JUNE 1978

BRIEF ASSESSMENT

The Hemlock Reservoir Dam is a linear concrete gravity dam about 700 feet long with an earth embankment concrete cone section comprising the west side of the dam. A concrete spillway section about 120 feet long is located at the eastern side of the dam. The dam is 64 feet high. Based on the visual inspection of the site, review of available information and the past performance of the dam, the dam is judged to be in good condition.

The project will not pass the test flood without overtopping the dam, and therefore the spillway capacity is inadequate. As the spillway will pass more than 50 per cent of the test flood without overtopping, the spillway is not judged seriously inadequate. The overflow will be 0.9 feet above the top of the dam.

Horizontal and vertical cracks should be repaired to every extent possible to prevent seepage and continuing deterioration. Additionally, since the degree and extent of spalling is somewhat excessive, the areas affected should be repaired. Due to the potential for overtopping, it is recommended that a definite plan for around the clock surveillance be implemented by the owner during periods of unusually heavy rains and a formal warning system should be developed.

  
S. Giavara, P.E.  
Principal

Registered, CT 7634

This Phase I Inspection Report on Hemlocks Reservoir Dam has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the Recommended Guidelines for Safety Inspection of Dams, and with good engineering judgment and practice, and is hereby submitted for approval.

*Charles G. Tiersch*

CHARLES G. TIERSCH, Chairman  
Chief, Foundation and Materials Branch  
Engineering Division

*Fred J. Ravens, Jr.*

FRED J. RAVENS, Jr., Member  
Chief, Design Branch  
Engineering Division

*Saul Cooper*

SAUL COOPER, Member  
Chief, Water Control Branch  
Engineering Division

APPROVAL RECOMMENDED:

*Joe B. Fryar*

JOE B. FRYAR  
Chief, Engineering Division

## PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.



## TABLE OF CONTENTS

<u>Section</u>	<u>Page</u>
Letter of Transmittal	
Brief Assessment	
Review Board Signature Sheet	
Preface	i
Table of Contents	ii - iv
Overview Photo	v
Location Map	vi
1. PROJECT INFORMATION	
1.1 General	1
a. Authority	1
b. Purpose of Inspection	1
1.2 Description of Project	1
a. Description of Dam and Appurtenances	1
b. Location	2
c. Size Classification	2
d. Hazard Classification	2
e. Ownership	2
f. Purpose of Dam	2
g. Design and Construction History	2
h. Normal Operational Procedure	2
1.3 Pertinent Data	2-4
2. ENGINEERING DATA	
2.1 Design	5
2.2 Construction	5
2.3 Operation	5
2.4 Evaluation	5

<u>Section</u>	<u>Page</u>
<b>3. VISUAL INSPECTION</b>	
3.1 Findings	6
a. General	6
b. Dam	6
c. Appurtenant Structures	6-7
d. Reservoir Area	8
e. Downstream Channel	8
3.2 Evaluation	9
<b>4. OPERATIONAL PROCEDURES</b>	
4.1 Procedures	10
4.2 Maintenance of Dam	10
4.3 Maintenance of Operating Facilities	10
4.4 Description of any Warning System in Effect	10
4.5 Evaluation	10
<b>5. HYDRAULIC/HYDROLOGIC</b>	
5.1 Evaluation of Features	11
a. Design Data	11
b. Experience Data	12
c. Visual Observation	12
d. Overtopping Potential	12
<b>6. STRUCTURAL STABILITY</b>	
6.1 Evaluation of Structural Stability	13
a. Visual Observation	13
b. Design and Construction Data	13
c. Operating Records	13
d. Post-Construction Changes	13
e. Seismic Stability	13


<u>Section</u>	<u>Page</u>
<b>7. ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES</b>	
7.1 Dam Assessment	14
a. Condition	14
b. Adequacy of Information	14
c. Urgency	14
d. Need for Additional Investigation	14
7.2 Recommendations	14
7.3 Remedial Measures	14
a. Alternatives	14
b. Operation and Maintenance and Procedures	15

LIST OF APPENDICES

<u>Appendix</u>	<u>Description</u>
I	Photographs
II	Hydrologic Computations
III	Visual Inspection - Check List
IV	Engineering Data - Check List
V	Drawings
VI	Information as Contained in the National Inventory of Dams



HEMLOCKS RESERVOIR DAM



PHASE I INSPECTION REPORT  
HEMLOCKS RESERVOIR DAM CT 00018

SECTION 1 - PROJECT INFORMATION

1.1 GENERAL:

a. Authority. Public Law 92-367, August 8, 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a national program of dam inspection throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region. Flaherty Giavara Associates, P.C. has been retained by the New England Division to inspect and report on selected dams in the State of Connecticut. Authorization and notice to proceed was issued to Flaherty Giavara Associates, P.C. under a letter of 25 April 1978 from Ralph T. Garver, Colonel, Corps of Engineers. Contract No. DACW33-78-0309 has been assigned by the Corps of Engineers for this work.

b. Purpose:

1) Perform technical inspection and evaluation of non-federal dams to identify conditions which threaten the public safety and thus permit correction in a timely manner by non-federal interests.

2) Encourage and assist the States to initiate quickly effective dam safety programs for non-federal dams.

3) To update, verify and complete the National Inventory of Dams.

1.2 DESCRIPTION OF PROJECT:

a. Description of Dam and Appurtenance. The Hemlock Reservoir Dam is a linear concrete gravity dam about 700 feet long, with an earth embankment, concrete core segment 300 feet long on the west side. A concrete spillway section is on the east side of the dam and is 120 feet in length. The spillway has an ogee crest. The dam section is 64 feet high, with a vertical upstream face and a downstream slope of 0.7 horizontal to 1 vertical. The earth embankment section has a slope of 2 horizontal to 1 vertical with a shelf and then a flatter slope to the entrance roadway. Upper and Lower gate houses provide for take off to two 48-inch supply mains and 10 and 36-inch blow off lines.

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER CT 00018	2. GOVT ACCESSION NO. ADA142986	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Conn. Western Coastal Area, Fairfield Conn. Hemlocks Reservoir Dam NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS		5. TYPE OF REPORT & PERIOD COVERED INSPECTION REPORT
		6. PERFORMING ORG. REPORT NUMBER
7. AUTHOR(s) U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION		8. CONTRACT OR GRANT NUMBER(s)
9. PERFORMING ORGANIZATION NAME AND ADDRESS		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
11. CONTROLLING OFFICE NAME AND ADDRESS DEPT. OF THE ARMY, CORPS OF ENGINEERS NEW ENGLAND DIVISION, NEDED 424 TRAPELO ROAD, WALTHAM, MA. 02254		12. REPORT DATE August 1978
		13. NUMBER OF PAGES 55
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Cover program reads: Phase I Inspection Report, National Dam Inspection Program; however, the official title of the program is: National Program for Inspection of Non-Federal Dams; use cover date for date of report.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) DAMS, INSPECTION, DAM SAFETY, Western Coastal Area, Fairfield Conn., Hemlocks Reservoir Dam		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) The Hemlock Reservoir Dam is a linear concrete gravity dam about 700 ft. long with an earth embankment concrete cone section comprising the west side of the dam. A concrete spillway section about 120 ft. long is located at the eastern side of the dam. The dam is 64 ft. high. Based on the visual inspection of the site, review of available information & the past performance of the dam, the dam is judged to be in fair good condition.		

b. Location. The dam is located on Cricker Brook 1.5 miles north of its junction with the Mill River within the Connecticut western coastal area. The dam is located in the Town of Fairfield, 1/2 mile north of the Merritt Parkway and 4-1/2 miles north of Mill Plain.

c. Size Classification. The applicable guidelines indicate that for an intermediate category the storage in acre/feet for the impoundment must be greater or equal to 1,000 and less than 50,000. The height must be greater or equal to 40 feet and less than 100 feet. The top of dam storage is 11,635 arce-feet and the height of dam is 75 feet. Therefore, based on both the storage capacity and height of dam the size classification is intermediate.

d. Hazard Classification. The dam is designated as having a high hazard potential. There are more than 50 dwellings less than 10 feet above the riverbed along the first 3 miles of the downstream river channel. The Merritt Parkway would also be damaged by a flood produced by a dam failure.

e. Ownership. Hemlock's Dam is owned and operated by the Bridgeport Hydraulic Company, of Bridgeport, Connecticut.

f. Purpose of Dam. The dam's function is to impound water for the Hemlock Reservoir. This reservoir forms part of the water company's distribution system and supplies a major portion of the demand.

g. Design and Construction History. The dam was designed and constructed in 1914. Both the designer and contractor who constructed the dam are unknown.

h. Normal Operational Procedure. The reservoir is utilized for drinking water purposes by taking water through the upper gate house to two 48-inch supply lines. A 36-inch and a 10-inch pipe provide for blow off. To augment supply, water from the Aspetuck and Saugatuck River watersheds are diverted to Hemlock's Reservoir as needed.

### 1.3 PERTINENT DATA:

a. <u>Drainage Area</u> -	5.3 sq. miles
b. <u>Discharge at Dam Site</u> -	
Maximum Known Flood	Unknown
Warm Water Outlet	Not Applicable
Div. Tunnel Low Pool Outlet	Not Applicable
Diversion Tunnel Outlet	Not Applicable
Gated Spillway	Not Applicable
Ungated Spillway at Max. Pool	4,700 CFS
Total Spillway Cap. at Max. Pool	4,700 CFS



- c. Elevation (above M.S.L.) -
- |                                       |                |
|---------------------------------------|----------------|
| Top of Dam                            | 230            |
| Max. Design Pool                      | Unknown        |
| Full Flood Control Pool               | Not Applicable |
| Recreation Pool                       | Not Applicable |
| Spillway Crest Ungated                | 225            |
| Upstream Portal Invert Div. Tunnel    | Not Applicable |
| Downstream Portal Invert. Div. Tunnel | Not Applicable |
| Streambed at Centerline of Dam        | 155            |
| Maximum Tailwater                     | 165+           |
- d. Reservoir -
- |                              |               |
|------------------------------|---------------|
| Length of Max. Pool          | 13,000 Ft.    |
| Length of Recreation Pool    | Not Available |
| Length of Flood Control Pool | Not Available |
- e. Storage -
- |                    |                  |
|--------------------|------------------|
| Recreation Pool    | Not Applicable   |
| Flood Control Pool | Not Applicable   |
| Design Surcharge   | Unknown          |
| Top of Dam         | 11,635 Acre-Feet |
- f. Reservoir Surface (acres) -
- |                    |                |
|--------------------|----------------|
| Top of Dam         | Not Available  |
| Max. Pool          | Not Applicable |
| Flood Control Pool | Not Applicable |
| Recreation Pool    | Not Applicable |
| Spillway Crest     | 437            |
- g. Dam -
- |                  |   |
|------------------|---|
| Type:            | 700' concrete gravity dam, 400' earth embankment            |
| Length:          | 1,100 feet  |
| Height:          | 75 feet   |
| Top Width:       | 11 feet   |
| Side Slopes:     | Concrete  |
|                  | Upstream: Vertical  |
|                  | Downstream: 0.7 Horizontal/1 Vertical                       |
| Zoning:          | Earth embankment, downstream slope: 2 Horizontal/1 Vertical |
| Impervious Core: | Concrete Core   |
| Grout Curtain:   | Unknown   |
- h. Diversion and Regulating Tunnel -
- |             |                |
|-------------|----------------|
| Type:       | No tunnel      |
| Length:     | Not Applicable |
| Diameter:   | Not Applicable |
| Access:     | Not Applicable |
| Regulation: | Not Applicable |

i. Spillway -

Type: Ogee  
Length of Weir: 116 feet  
Crest Elevation: 225  
Gates: Ungated  
Upstream Channel: Reservoir perimeter, stone bottom  
Downstream Channel: Concrete training wall  
Spillway is founded on rock

j. Regulating Outlets -

Intake Structure: 8 - sluice gates, 3' x 5'-6"  
2 - 48" dia. water supply mains  
1 - 36" dia. reservoir drain -  
blow off  
1 - 10" dia. gate house drain -  
blow off

## SECTION 2 - ENGINEERING DATA

### 2.1 DESIGN:

The designer of the dam is unknown. Two drawings were utilized during this study entitled as follows:

- a. "Hemlock's Dam Gate Houses" - not dated
- b. "Gate House Details" - not dated

### 2.2 CONSTRUCTION:

A rock and earth profile developed for the site of Hemlock's Dam has been reviewed. The data and accuracy of the profile are unknown.

### 2.3 OPERATION:

No operation records were made available for use during this investigation.

### 2.4 EVALUATION:

a. Availability. Only plans showing some of the dimensional features are available. Specifications indicating the properties of the materials used and construction procedures are not available.

b. Adequacy. Information available is adequate for Phase I purposes.

c. Validity. There is no reason to question the validity of the documents reviewed.

## SECTION 3 - VISUAL INSPECTION

### 3.1 FINDINGS:

a. General. The dam is composed of two sections, a concrete core wall earth embankment on the west and a concrete dam with downstream earth berms on the east. The concrete section was gunited in 1964 and is spalling at several locations. Some staining is occurring, however, the source of water is unknown. The earth embankment sections were well maintained and did not show any evidence of sloughing, erosion, or wet spots.

#### b. Dam.

##### 1) Gravity Concrete Section -

a) Upstream Face - For the full length of the dam horizontally about two feet above the water line there is an area of scour exposing the fine aggregate in the concrete. At almost every joint in the dam there is a larger space where deterioration has taken place and concrete is absent. Generally, there are some minor areas of spalling along the U/S face of the dam, however, at the panel adjacent to the gate house (west side) there is an area of severe spalling nearly the full length of the panel about one foot thick (approximately one foot above the water line). In the panel on the east side of the gate house there is an area of deep scour (one foot thick) for nearly its full length. Generally, there is some spalling of the joints at the coping.

b) Downstream Face - The joints are generally in poor condition. At the joint at Station 4+71 just above the ground surface a large area of gunite has spalled off exposing the wire mesh. At the joint at Station 5+31 there is a bubble for about the middle third of the exposed portion of the joint and a deep, narrow spalling of the gunite at the bottom third of the joint. There is efflorescence for most of the joint at Station 5+91 and a large wet spot near the ground surface. The joint at Station 6+51 has spalling and considerable rust stains. The panel between Station 6+51 and Station 7+11 has several areas of surface cracks, efflorescence and bubbles. Near the bottom of the joint at Station 7+11 there is an area of spalling several inches deep which exposes the wire mesh. A short distance down from the top of the dam horizontally across this joint there is a large bevel and just below a depression, probably due to guniting. In the panel between Station 7+11 and Station 7+71, near the bottom there is a large area of surface spalling. Also, in this panel near the bottom is a large bubble and some spalling and below this, an area of surface

cracks. Near the joint at Station 7+71 close to the ground surface is an area of deep spalling and efflorescence. In the panel at the gate house between Station 7+71 and Station 8+01 there is a large spalled area close to the top of the dam. At Station 8+01 the joint shows cracking for nearly the full depth and a bubble and small spalled area near the ground surface. Slight seepage was noted at several joints.

c) Spillway - The area of the spillway adjacent to the dam has severe spalling and the wire mesh is exposed at what appears to be the uppermost horizontal construction joint with water seeping through and evidence of efflorescence. There are several areas of cracking and spalling and also several places showing evidence of water seeping through at the horizontal joints.

d) Earth Embankment - The downstream berm is generally in good condition with no sloughing or wet spots noted. The berm appeared to be relatively shallow in the vicinity of the downstream concrete gate house.

Mica schist bedrock is exposed about 30 feet downstream from the face of the dam in the vicinity of Station 6+00. Several large outcrops appear to strike N35°W and dip 10° west. Additional stone inlets were located in the downstream berm at Station 4+90 adjacent to the access road, Station 5+25 on the berm and one near Station 9+70 on the left side of the dam. The outlet for the later stone inlet could not be located during the visual inspection.

## 2) Core Wall Embankment Dam Section -

a) Upstream Slope - The upstream slope was exposed for a distance of approximately 6 feet. (The reservoir was about 1 foot below the spillway crest.) The riprap extended to within 1 foot of the embankment crest and generally appeared in good condition. Some small windows were exposed through the riprap and there was some evidence of differential weathering of the mica schist riprap at a few locations.

b) Crest - The crest of the dam consisted of the top of the earth embankment, 30 feet wide. The core wall, 10 feet wide, is exposed only at the junction with the concrete dam, Station 3+89. A small test pit was excavated at Station 2+30 which uncovered the top of the concrete core wall about 9 inches below the roadway surface.

c) Downstream Slope - The portion of the downstream slope above the lower access road is grassed and had been recently mowed. It did not show any evidence of sloughing, erosion or wet spots. There are several stone inlets (stone was not removed) on the upstream side of the lower access road at

approximately Stations 1+37, 2+57, and 3+44. The inlets appear to connect to culverts which are laid underneath the access road and which connect into a grassed drainage channel on the downstream side of the road. All the culverts were dry except for a small trickle of water flowing from the culvert under the road at Station 1+37. Below the road, the slope is heavily wooded, and it is difficult to observe any movement.

There are a few holes made by burrowing animals on the slope.

c. Appurtenant Structures.

1) Upper Gate House - The upper gate house was clean and neat. The gate controls appeared to be easy turning and are exercised once a year. A recent diver's report is purported to have indicated that two of the stem guides were broken. (Report not released by Bridgeport Hydraulics Company.) A request by the inspection team to operate the blow offs to ensure proper functioning was not met. The filtration screens for the water supply mains have electrical power hoists in good condition. Electrical equipment for the hoists, interior light, dam floodlights, and deicer pumps appeared in good condition. All interior wiring was enclosed in conduits free of corrosion and dirt.

2) Lower Gate House - Generally good condition.

d. Reservoir Area. The reservoir perimeter has well vegetated banks at moderate to steep slopes. There was no evidence of slides or sloughing. No noticeable debris or obstructions were seen in the vicinity of the upper gate house. The depth of sediment, and rate of accumulation in the reservoir, is unknown. However, sediment has accumulated in the eastern end of the reservoir at the spillway (reaching the crest).

e. Downstream Channel.

1) Spillway Discharge - The spillway channel is in good condition. The low concrete and stone wall on the right side of the channel is also in good condition. Mica schist bedrock is exposed about 150 feet downstream from the spillway weir. At this location, it is planar, and strikes N10°W and dips 10° west. There are minor obstructions on the bottom of the channel consisting of small bushes, tree branches and grass growing at various locations along the bottom. The spillway channel has a large crevice near the end of the low concrete wall which has been created by differential erosion along the foliation of the exposed mica schist.

2) Blow-Off Discharge Channel - The channel is becoming obstructed with sediment at its junction with the spillway discharge channel.

### 3.2 EVALUATION:

The dam appears in good condition, and there are no visual indications of the dam being unsafe. The gunite repair (1964) has deteriorated and a program of concrete maintenance is warranted.

The spillway channel contained debris and obstructions on the bottom and it is important it be maintained to allow unobstructed flow during peak discharge periods. Some trees immediately adjacent to the left side of the spillway channel could also adversely effect capacity.

## SECTION 4 - OPERATIONAL PROCEDURES

### 4.1 PROCEDURES:

Water is withdrawn through the upper gatehouse service gates and treated at a plant just downstream of the dam. Two 48-inch supply lines service customers in the greater Bridgeport region.

### 4.2 MAINTENANCE OF DAM:

The dam and associated structures are generally well maintained with a regular program of grass mowing and general maintenance in effect. Yearly routine inspections are carried out by Bridgeport Hydraulic Company staff. A consultant was hired to perform a cursory inspection of Bridgeport Hydraulic Company dams during November 1976. It was recommended that spalling concrete at Hemlock's dam be repaired.

### 4.3 MAINTENANCE OF OPERATING FACILITIES:

The operating valves were inspected recently; although the results of the inspection are not available, generally the valves/valve stems need some repair.

### 4.4 DESCRIPTION OF ANY WARNING SYSTEM IN EFFECT:

There was no warning system of any kind in effect at the time of the inspection.

### 4.5 EVALUATIONS:

The Hemlock's Reservoir, which is approximately 70 years old, is well operated and maintained. Although not designed for rapid drawdown, it should be noted that, if the need should arise, drawdown could be effected by the following procedures:

- a. Allowing for maximum discharge through the 36-inch and 10-inch blow-offs.
- b. Allowing for discharge through the two 48-inch supply mains.

The blow-off was not operated during the site inspection, therefore comments on the serviceability cannot be made. The valve should be tested on a periodic basis to insure that it could be operated if required.



## SECTION 5 - HYDRAULICS/HYDROLOGY

### 5.1 EVALUATION OF FEATURES:

a. Design Data. There is no available information on the hydraulic design criteria for this dam and appurtenances. Under established criteria (OCE Guidelines) the recommended spillway test flood for the size (intermediate) and hazard potential (high) classification is the probable maximum flood (PMF). The PMF is the flood that may be expected from the most severe combination of critical meteorologic and hydrologic conditions that are reasonably possible in the region.

An estimate of the magnitude of the test flood at the site is based on an analysis of several sets of regional flood frequency data as presented in Appendix II.

As a conservative approach to the investigation, the most critical design hydrograph was used throughout (peak discharge of 9,600 CFS).

A stage-discharge relationship was calculated for the spillway and indicates the following flows, based upon a coefficient of 3.6 and a length of 116 feet.

#### Stage - Discharge Relationship

<u>Stage</u>	<u>Head, Ft.</u>	<u>Discharge Rate, CFS</u>
225	0	0
226	1	420
227	2	1,180
228	3	2,170
229	4	3,340
230	5	4,670

The maximum spillway capacity, with no freeboard, is less than the peak inflow rate of the test flood. (Compare 9,600 CFS with 4,670 CFS.) In order to determine the effect of the reservoir storage capacity, a hydrograph of the test flood was routed through the reservoir.

The hydrograph was formed by assuming the test flood had a duration of 24 hours, with the peak of 9,600 CFS occurring at 8 hours from the beginning of runoff. The rising and falling limbs of the hydrograph were assumed to be changing at a constant rate, forming a triangle. The routing operation indicated that the peak rate of discharge would be reduced to 8,800 CFS, resulting in a stage elevation of 230.9 feet.

b. Experience Data. Discussion with water company personnel indicates that since the early 1950's the dam has not been overtopped.

c. Visual Observations. The on-site inspection of the dam provided the data for the hydraulic evaluation of the spillway.

d. Overtopping Potential. The peak rate of discharge from the test flood will overtop the dam and embankment (0.9 feet). The maximum spillway capacity is however equal to more than one-half of the test flood.

## SECTION 6 - STRUCTURAL STABILITY

### 6.1 EVALUATIONS OF STRUCTURAL STABILITY:

a. Visual Observations. No evidence was observed that would indicate structural instability. The concrete surface (gunite) has deteriorated, and some water was seeping at the joints. Monitoring of this seepage should be initiated.

b. Design and Construction Data. The design and construction data available are not sufficient to formally evaluate the stability of the dam. In particular, there is no available information concerning the embankment and berm materials and construction documentation nor the foundation material for the core wall and the concrete gravity section. The drawing suggests that the gravity section was placed in an excavation. It is now known whether bedrock was reached and, if so, what was the in-situ properties of the bedrock.

c. Operating Records. There are no available records which indicate evidence of stability problems since the dam was constructed in 1914. As the Hemlock Reservoir Dam was designed and constructed as a water supply dam and has been subjected to a full head of water a majority of the time since construction, its stability could be considered to be adequate based on past performance.

d. Post-Construction Changes. A lime feed and storage tank was constructed downstream of the dam west of the treatment facility. A large diameter gas main was also constructed downstream of the dam south of the entrance roadway. Neither of these changes affects the structural stability of the dam.

e. Seismic Stability. This dam is in Seismic Zone 1 and hence does not have to be evaluated for seismic stability.

SECTION 7 - ASSESSMENT, RECOMMENDATIONS AND  
REMEDIAL MEASURES

7.1 DAM ASSESSMENT:

a. Condition. Based on the visual inspection, records available and past operational performance, the dam is judged to be in good condition.

The project will not discharge the test flood without overtopping the dam, and therefore the spillway capacity is inadequate. The spillway capacity is not judged seriously inadequate, as the project will pass one-half the test flood without overtopping the dam.

b. Adequacy of Information. The information and data available were adequate for performance of this investigation.

c. Urgency. The recommendations and remedial measures presented should be carried out in the near term.

d. Need for Additional Investigation. Additional investigations to further assess the adequacy of the dam and appurtenant structures do not appear necessary.

7.2 RECOMMENDATIONS:

It is recommended that the following measures be undertaken by the owner:

1) Horizontal and vertical cracks should be patched to every extent possible to prevent seepage and continuing deterioration.

2) Since degree and extent of spalling is considered excessive, the areas affected should be repaired.

3) Sediment accumulation in front of spillway section (east side) should be removed and hauled away.

4) Defective valves and stems should be repaired to insure that if required, they could be operated to lower the water level in the reservoir.

7.3 REMEDIAL MEASURES:

Although the dam is generally maintained in good condition, it is considered important that the following items be accomplished:

a. Alternatives. Not applicable.

b. Operation and Maintenance and Procedures.

1) An operation and maintenance manual for the project should be prepared.

2) Animal bore holes should be filled and plugged.


3) The blow-off valve should be exercised periodically.

4) Due to the potential for overtopping, it is recommended that a definite plan for around the clock surveillance be implemented during periods of unusually heavy rains and a formal warning system be developed for use in the event of an emergency.

APPENDIX I

PHOTOGRAPHS

N



HEMLOCK RESERVOIR DAM

LOCATION OF PHOTOGRAPHS



PHOTO #1: Upstream Face of Dam, looking West.



PHOTO #2: Upstream Face of Dam and Spillway Bridge, looking East.





PHOTO #3: Spillway, looking East.



PHOTO #4: Spillway, looking West. Note Flashboards.




PHOTO #5: Outlet Works and Discharge Point and Channel.



PHOTO #6: Downstream Face of Dam and Embankment looking West.




PHOTO #7: Downstream Face of Dam and Embankment looking West.



PHOTO #8: Central Portion of Embankment, looking East.



PHOTO #9: Control Tower.



PHOTO #10: Typical Spalling at a Construction Joint on the Upstream Face of the Dam.



PHOTO #11: Typical Spalling at Joint,  
Downstream Face.





PHOTO #12: Typical Spalling, Downstream  
Face, at Top of Earth Embankment.

APPENDIX II  
HYDROLOGIC COMPUTATIONS



**DRAINAGE AREA MAP**  
**HEMLOCK RESERVOIR DAM**  
FAIRFIELD, CONNECTICUT





## PMF PEAK FLOW ESTIMATE

WATERSHED AREA IS 5.27 SQUARE MILES

### METHOD #1

REFER TO "PRELIMINARY GUIDANCE FOR ESTIMATING PMF DISCHARGES" by NEW ENGLAND DIVISION, CORPS OF ENGINEERS

$$\begin{aligned} \text{UNIT FLOW} &= 1820 \text{ CFS}/\text{mi}^2 \text{ (ROLLING)} \\ \text{PMF} &\approx (5.27 \text{ mi}^2)(1820 \text{ CFS}/\text{mi}^2) = 9591 \text{ CFS} \\ \text{SAY} &\approx 9600 \text{ CFS} \end{aligned}$$

### METHOD #2

REFER TO CONN WATER RESOURCE BULLETIN #17, BY USGS, PART 4.

$$\begin{aligned} \text{MEAN ANNUAL FLOOD} &= 250 \text{ CFS} \text{ (FIG. 13)} \\ Q_{100} &= 5 \times \text{MAF} = 5 \times (250) = 1250 \text{ CFS} \text{ (FIG. 14)} \end{aligned}$$

$$\begin{aligned} \text{PMF} &\approx 5 \times Q_{100} \text{ (APPROXIMATE)} \\ \text{PMF} &\approx 5 \times 1250 \text{ CFS} = 6250 \text{ CFS} \end{aligned}$$

### METHOD #3

REFER TO FAIRFIELD FLOOD INSURANCE STUDY, "FREQUENCY DISCHARGE, DRAINAGE AREA CURVES"

$$\begin{aligned} Q_{100} &= 1500 \text{ CFS} \\ \text{PMF} &\approx 5 \times (1500) = 7500 \text{ CFS} \end{aligned}$$

FOR SPILLWAY EVALUATION, USE 9600 CFS





INFLOW HYDROGRAPH FORMATION

- 1) P.M.F. PEAK FLOW = 9600 CFS ±
- 2) FORM A 24 HOUR LONG TRIANGULAR INFLOW HYDROGRAPH, PEAK AT 8 HOURS

<u>TIME HOURS</u>	<u>UNIT FLOW RATE</u>	<u>FLOW RATE CFS</u>
0	0.00	0
2	0.25	2400
4	0.50	4800
6	0.75	7200
8	1.00	9600
10	0.875	8400
12	0.75	7200
16	0.50	4800
20	0.25	2400
24	0.00	0

33MLOCK DAM

78-36-10

FLOOD ROUTING

JCM

7/14/78


INPUT DATA:  
SEGMENT 1  
SEGMENT 2  
IE=225 IV=

UNSUBMERGED WEIR  
DISCHARGE COEFFICIENT = 3.6  
DISCHARGE COEFFICIENT = 3  
0.0 E=225 A=437.00 E=235 A=437.00

LENGTH OF WEIR = 116  
LENGTH OF WEIR = 1100  
A=437.00

ELEVATION OF WEIR = 225  
ELEVATION OF WEIR = 230

Hour	Inflow	Mass Inflow	Water El.	Tail Water	Outflow	Mass Outflow	Storage (R)	Storage (A)
0.00	0CFS	0.00AC-F	225.00FT	0.00FT	0CFS	0.00AC-F	0.00AC-F	0.00AC-F
2.00	2,400CFS	198.34AC-F	225.43FT	0.00FT	118CFS	9.78AC-F	188.56AC-F	188.56AC-F
4.00	4,800CFS	793.38AC-F	226.60FT	0.00FT	852CFS	90.03AC-F	703.35AC-F	703.35AC-F
6.00	7,200CFS	1,785.12AC-F	228.25FT	0.00FT	2,451CFS	363.09AC-F	1,422.02AC-F	1,422.02AC-F
8.00	9,600CFS	3,173.55AC-F	230.05FT	0.00FT	4,800CFS	962.45AC-F	2,211.09AC-F	2,211.09AC-F
10.00	8,400CFS	4,661.15AC-F	230.89FT	0.00FT	8,777CFS	2,084.61AC-F	2,576.53AC-F	2,576.53AC-F
12.00	7,200CFS	5,950.41AC-F	230.72FT	0.00FT	7,741CFS	3,449.80AC-F	2,500.60AC-F	2,500.60AC-F
16.00	4,800CFS	7,933.88AC-F	230.26FT	0.00FT	5,478CFS	5,634.92AC-F	2,298.96AC-F	2,298.96AC-F
20.00	2,400CFS	9,123.96AC-F	229.43FT	0.00FT	3,901CFS	7,185.37AC-F	1,938.59AC-F	1,938.59AC-F
24.00	0CFS	9,520.66AC-F	228.03FT	0.00FT	2,206CFS	8,194.99AC-F	1,325.66AC-F	1,325.66AC-F
30.00	0CFS	9,520.66AC-F	226.39FT	0.00FT	686CFS	8,912.16AC-F	608.49AC-F	608.49AC-F
36.00	0CFS	9,520.66AC-F	225.82FT	0.00FT	313CFS	9,159.93AC-F	360.72AC-F	360.72AC-F
48.00	0CFS	9,520.66AC-F	225.36FT	0.00FT	92CFS	9,360.97AC-F	159.68AC-F	159.68AC-F



APPENDIX III

VISUAL INSPECTION

CHECK LIST

**PERIODIC INSPECTION CHECK LIST**

**PROJECT** Hemlocks Reservoir

**DATE** June 21, 1978

**INSPECTOR** Anthony Rummo

**DISCIPLINE** Structural

**INSPECTOR** \_\_\_\_\_

**DISCIPLINE** \_\_\_\_\_

AREA EVALUATED	CONDITION
<u>CONCRETE DAM STRUCTURE</u>	
General Condition Concrete Surfaces	Gunite surface severely spalled
Movement or Settlement of Crest	None
Vertical Alignment	Good
Horizontal Alignment	Good
Condition at Abutment and Other Structures	
Structural Cracking	None observed
Spalling	Major spalling of surface (gunite)
Visible Reinforcing	Wire mesh, exposed (gunite)
Rusting or Staining of Concrete	Yes, at some joints
Condition of Monolith/ Construction Joints	Joints in poor condition
Drains - Foundation, Joint, Faces	None
Any Seepage or Efflorescence	Major efflorescence observed and seepage noted at joints
Foundation Damage, Undermining	None
Water Passages	
Abutments	

**PERIODIC INSPECTION CHECK LIST**

**PROJECT** Hemlocks Reservoir

**DATE** June 21, 1978

**INSPECTOR** Richard Murdock

**DISCIPLINE** Geotechnical

**INSPECTOR** \_\_\_\_\_

**DISCIPLINE** \_\_\_\_\_

AREA EVALUATED	CONDITION
<u>DAM EMBANKMENT</u>	
Crest Elevation	El. 225
Current Pool Elevation	El. 224
Maximum Impoundment to Date	
Surface Cracks	None observed
Pavement Condition	Ruts evident in roadway
Movement or Settlement of Crest	None observed
Lateral Movement	None
Vertical Alignment	Good
Horizontal Alignment	Good
Condition at Abutment and at Concrete Structures	Good
Indications of Movement of Structural Items on Slopes	None
Trespassing on Slopes	Few small animal holes
Sloughing or Erosion of Slopes or Abutments	None
Rock Slope Protection - Riprap Failures	Good, some minor deterioration present
Unusual Movement or Cracking at or near Toes	None observed
Unusual Embankment or Down-stream Seepage	None

PERIODIC INSPECTION CHECK LIST

PROJECT Hemlocks Reservoir

DATE June 21, 1978

INSPECTOR Richard Murdock

DISCIPLINE Geotechnical

INSPECTOR \_\_\_\_\_

DISCIPLINE \_\_\_\_\_

AREA EVALUATED	CONDITION
<p><u>DAM EMBANKMENT</u> - (continued)</p> <p>Piping or Boils</p> <p>Foundation Drainage Features</p> <p>Toe Drains</p> <p>Instrumentation System</p>	<p>None</p> <p>None</p> <p>None</p> <p>None</p>

**PERIODIC INSPECTION CHECK LIST**

**PROJECT** Hemlocks Reservoir

**DATE** June 21, 1978

**INSPECTOR** Anthony Rummo

**DISCIPLINE** Structural

**INSPECTOR** James MacBroom

**DISCIPLINE** Hydraulics/  
Hydrology

AREA EVALUATED	CONDITION
<b>OUTLET WORKS - CONTROL TOWER</b>	
<p><b>a. Concrete and Structural</b></p> <p>General Condition</p> <p>Condition of Joints</p> <p>Spalling</p> <p>Visible Reinforcing</p> <p>Rusting or Staining of Concrete</p> <p>Any Seepage or Efflorescence</p> <p>Joint Alignment</p> <p>Unusual Seepage or Leaks in Gate Chamber</p> <p>Cracks</p> <p>Rusting or Corrosion of Steel</p>	<p>Generally in good condition, some erosion</p> <p>Minor spalling noted</p> <p>No visible reinforcing</p> <p>No cracks noted</p> <p>None</p>
<p><b>b. Mechanical and Electrical</b></p> <p>Air Vents</p> <p>Float Wells</p> <p>Crane Hoist</p> <p>Elevator</p> <p>Hydraulic System</p>	<p>Good condition</p> <p>None</p>

**PERIODIC INSPECTION CHECK LIST**

**PROJECT** Hemlocks Reservoir

**DATE** June 21, 1978

**INSPECTOR** Anthony Rummo

**DISCIPLINE** Structural

**INSPECTOR** James MacBroom

**DISCIPLINE** Hydraulics/  
Hydrology

AREA EVALUATED	CONDITION
<p><b>OUTLET WORKS - CONTROL TOWER</b> (continued)</p> <p><b>Service Gates</b></p> <p><b>Emergency Gates</b></p> <p><b>Lightning Protection System</b></p> <p><b>Emergency Power System</b></p> <p><b>Wiring and Lighting System In Gate Chamber</b></p>	<p>Good condition</p> <p>Satisfactory</p> <p>None</p> <p>Electrical, good condition</p>



PERIODIC INSPECTION CHECK LIST

PROJECT Hemlocks Reservoir

DATE June 21, 1978

INSPECTOR \_\_\_\_\_

DISCIPLINE \_\_\_\_\_

INSPECTOR \_\_\_\_\_

DISCIPLINE \_\_\_\_\_

AREA EVALUATED	CONDITION
<p><u>OUTLET WORKS - INTAKE CHANNEL AND INTAKE STRUCTURE</u></p> <p>a. Approach Channel</p> <ul style="list-style-type: none"><li>Slope Conditions</li><li>Bottom Conditions</li><li>Rock Slides or Falls</li><li>Log Boom</li><li>Debris</li><li>Condition of Concrete Lining</li><li>Drains or Weep Holes</li></ul> <p>b. Intake Structure</p> <ul style="list-style-type: none"><li>Condition of Concrete</li><li>Stop Logs and Slots</li></ul>	<p>Water travels from the reservoir directly into the intake structure.</p>

**PERIODIC INSPECTION CHECK LIST**

**PROJECT** Hemlocks Reservoir

**DATE** June 21, 1978

**INSPECTOR** Anthony Rummo

**DISCIPLINE** Structural

**INSPECTOR** Richard Murdock  
James MacBroom

**DISCIPLINE** Geotechnical  
Hydraulics/Hydrology

AREA EVALUATED	CONDITION
<p><b><u>OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS</u></b></p>	
<p><b>a. Approach Channel</b></p> <p>General Condition</p> <p>Loose Rock Overhanging Channel</p> <p>Trees Overhanging Channel</p> <p>Floor of Approach Channel</p>	<p>Sediment has accumulated at eastern end of approach to spillway</p>
<p><b>b. Weir and Training Walls</b></p> <p>General Condition of Concrete</p> <p>Rust or Staining</p> <p>Spalling</p> <p>Any Visible Reinforcing</p> <p>Any Seepage or Efflorescence</p> <p>Drain Holes</p>	<p>Severe spalling</p> <p>Yes</p> <p>Yes</p> <p>Wire mesh exposed</p> <p>Some seepage and efflorescence</p> <p>None observed</p>
<p><b>c. Discharge Channel</b></p> <p>General Condition</p> <p>Loose Rock Overhanging Channel</p> <p>Trees Overhanging Channel</p> <p>Floor of Channel</p> <p>Other Obstructions</p>	<p>Good</p> <p>None observed</p> <p>A few trees in close proximity to left wall.</p> <p>Good condition</p> <p>Brush, grass, a few wood pieces</p>

**PERIODIC INSPECTION CHECK LIST**

**PROJECT** Hemlocks Reservoir

**DATE** June 21, 1978

**INSPECTOR** \_\_\_\_\_

**DISCIPLINE** \_\_\_\_\_

**INSPECTOR** \_\_\_\_\_

**DISCIPLINE** \_\_\_\_\_

AREA EVALUATED	CONDITION
<p><b>OUTLET WORKS - SERVICE BRIDGE</b></p> <p><b>a. Super Structure</b></p> <ul style="list-style-type: none"><li>Bearings</li><li>Anchor Bolts</li><li>Bridge Seat</li><li>Longitudinal Members</li><li>Under Side of Deck</li><li>Secondary Bracing</li><li>Deck</li><li>Drainage System</li><li>Railings</li><li>Expansion Joints</li><li>Paint</li></ul> <p><b>b. Abutments &amp; Piers</b></p> <ul style="list-style-type: none"><li>General Condition of Concrete</li><li>Alignment of Abutment</li><li>Approach to Bridge</li><li>Condition of Seat &amp; Backwall</li></ul>	<p>None</p>

PERIODIC INSPECTION CHECK LIST

PROJECT Hemlocks Reservoir

DATE June 21, 1978

INSPECTOR \_\_\_\_\_

DISCIPLINE \_\_\_\_\_

INSPECTOR \_\_\_\_\_

DISCIPLINE \_\_\_\_\_

AREA EVALUATED	CONDITION
<p><u>OUTLET WORKS - TRANSITION AND CONDUIT</u></p> <p>General Condition of Concrete</p> <p>Rust or Staining on Concrete</p> <p>Spalling</p> <p>Erosion or Cavitation</p> <p>Cracking</p> <p>Alignment of Monoliths</p> <p>Alignment of Joints</p> <p>Numbering of Monoliths</p>	

**PERIODIC INSPECTION CHECK LIST**

**PROJECT** Hemlocks Reservoir

**DATE** June 21, 1978

**INSPECTOR** James MacBroom

**DISCIPLINE** Hydraulics/  
Hydrology

**INSPECTOR** \_\_\_\_\_

**DISCIPLINE** \_\_\_\_\_

AREA EVALUATED	CONDITION
<p><u>OUTLET WORKS - OUTLET STRUCTURE AND OUTLET CHANNEL</u></p> <p>General Condition of Concrete</p> <p>Rust or Staining</p> <p>Spalling</p> <p>Erosion or Cavitation</p> <p>Visible Reinforcing</p> <p>Any Seepage or Efflorescence</p> <p>Condition at Joints</p> <p>Drain Holes</p> <p>Channel</p> <p>Loose Rock or Trees Over- hanging Channel</p> <p>Condition or Discharge Channel</p>	<p>Generally good condition; some sediment collected at junction with spillway discharge channel</p>

APPENDIX IV

ENGINEERING DATA

CHECK LIST

Hemlocks  
NAME OF DAM Reservoir Dam

CHECK LIST  
ENGINEERING DATA

DESIGN, CONSTRUCTION, OPERATION  
PHASE I

I.D. NO. 18

ITEM

REMARKS

AS-BUILT DRAWINGS

None exist

REGIONAL VICINITY MAP

Available from U.S.G.S.

CONSTRUCTION HISTORY

Not available (letter in DEP File, re: cursory inspection)

TYPICAL SECTIONS OF DAM

From plans, Concrete Section only

OUTLETS - Plan

From plans, not complete

- Details

From plans, not complete

- Constraints

Unknown

- Discharge Ratings

None available

RAINFALL/RESERVOIR RECORDS

None

DESIGN REPORTS

None

GEOLOGY REPORTS

None

DESIGN COMPUTATIONS

None

HYDROLOGY & HYDRAULICS

None

DAM STABILITY

None

SEEPAGE STUDIES

None

MATERIALS INVESTIGATIONS

None

BORINGS RECORDS

None

LABORATORY

None

FIELD

None

**CHECK LIST  
ENGINEERING DATA  
DESIGN, CONSTRUCTION, OPERATION  
PHASE I**

**NAME OF DAM** Hexlocks Reservoir Dam  
**I.D. NO.** 18

**ITEM**

**REMARKS**

**POST-CONSTRUCTION SURVEYS OF DAM**

None available

**BORROW SOURCES**

Unknown

**MONITORING SYSTEMS**

None

**MODIFICATIONS**

None

**HIGH POOL RECORDS**

Approximate from Bridgeport Hydraulic Co. records

**POST-CONSTRUCTION ENGINEERING  
STUDIES AND REPORTS**

None

**PRIOR ACCIDENTS OR FAILURE OF DAM  
DESCRIPTION  
REPORTS**

None

**MAINTENANCE OPERATION RECORDS**

Inspection reports from Bridgeport Hydraulic Co.

**SPILLWAY PLAN**

**SECTIONS**

From plans

**DETAILS**

From plans



**OPERATING EQUIPMENT  
PLANS & DETAILS**

From plans



APPENDIX V

DRAWINGS



DOWNSTREAM

DAM 7

UPPER GATE HOUSE

SPILLWAY


LOWER GATE HOUSE

TREATMENT PLANT

SPILLWAY CHANNEL

48" PIPES

PLAN  
NTS



TOP OF DAM EL 230

SPILLWAY EL 225

CONCRETE DAM

EXISTING GROUND (APPROX)

00


10+00

240  
220  
200  
180  
160

STREAM ELEVATION OF DAM  
NTS

HEMLOCKS RESERVOIR DAM  
MILL RIVER

2



SECTION OF DAM AND GATE HOUSES

NTS

HEMLOCKS RESERVOIR DAM

MILL RIVER

APPENDIX VI  
INFORMATION AS CONTAINED IN  
THE NATIONAL INVENTORY OF DAMS



END

FILMED

8

74

DITIC