AD-A147 172	NATION BA®SON MA NEW	NAL PRO N RESER N ENGLA	GRAM FC VOIR DA ND DIV	R INSPE M ((L NOV 78	ECTION J) CORP B	OF NON- S OF EN	FEDERAL GINEERS F/	DAMS WALTH	1 M NL	/ •		•
	i) Maria									F ¢	- ``q	
						Ż	, 	<u></u>				
						N.						
										END DATE FILMED 12-84 DTIC		



MICROCOPY RESOLUTION TEST CHART NATIONAL BUREAU OF STANDARDS-1963-A



REPORT DOCUMENTA	READ INSTRUCTIONS		
. REPORT NUMBER	2. GOVT ACCESSION NO	J BEFORE COMPLETING FORM	
MA 00187	AD- 4147	172	
TITLE (and Sublillo)		S. TYPE OF REPORT & PERIOD COVERE	
Babson Reservoir Dam	INSPECTION REPORT		
NATIONAL PROGRAM FOR INSPECTION	5. PERFORMING ORG. REPORT NUMBER		
. AUTHOR(a)		S. CONTRACT OR GRANT NUMBER(s)	
U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION			
PERFORMING ORGANIZATION NAME AND AG	DDRESS	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS	
1. CONTROLLING OFFICE NAME AND ADDRES	35	12. REPORT DATE	
DEPT. OF THE ARMY, CORPS OF EN	GINEERS	November 1978	
NEW ENGLAND DIVISION, NEDED 424 TRADELO DOAD WALTHAM MA	02254	13. NUMBER OF PAGES	
4. MONITORING AGENCY NAME & ADDRESSII	diliorent from Controlling Office)	15. SECURITY CLASS. (of this report)	
	•	UNCLASSIFIED	
DISTRIBUTION STATEMENT (of Min Report) APPROVAL FOR PUBLIC RELEASE: D	ISTRIBUTION UNLIMITED	UNCLASSIFIED	
DISTRIBUTION STATEMENT (of the Report) APPROVAL FOR PUBLIC RELEASE: D DISTRIBUTION STATEMENT (of the oborrow) SUPPLEMENTARY NOTES Cover program reads: Phase I II	ISTRIBUTION UNLIMITED	UNCLASSIFIED 18. DECLASSIFICATION/DOWNGRADING SCHEDULE Tonal Dam Inspection Program:	
APPROVAL FOR PUBLIC RELEASE: D 7. DISTRIBUTION STATEMENT (of the observe) 8. SUPPLEMENTARY NOTES Cover program reads: Phase I II however, the official title of Non-Federal Dams; use cover da	ISTRIBUTION UNLIMITED microd in Block 30, 11 different in nspection Report, Nat the program is: Nati ate for date of repor	UNCLASSIFIED 18. DECLASSIFICATION/DOWNGRADING SCHEDULE 10nal Dam Inspection Program; onal Program for Inspection of t.	
APPROVAL FOR PUBLIC RELEASE: D APPROVAL FOR PUBLIC RELEASE: D D DISTRIBUTION STATEMENT (of the choract of program reads: Phase I II however, the official title of Non-Federal Dams; use cover da KEY WORDS (Continue on reverse alde if mere DAMS, INSPECTION, DAM SAFETY;	ISTRIBUTION UNLIMITED microd in Block 39, 11 different in nspection Report, Nat the program is: Nati ate for date of repor	UNCLASSIFIED 15. DECLASSIFICATION/DOWNGRADING SCHEDULE ional Dam Inspection Program; onal Program for Inspection of t.	
APPROVAL FOR PUBLIC RELEASE: D. 2. DISTRIBUTION STATEMENT (of the above) 2. DISTRIBUTION STATEMENT (of the above) 3. SUPPLEMENTARY NOTES Cover program reads: Phase I II however, the official title of Non-Federal Dams; use cover da 3. KEY WORDS (Continue on reverse aldo if necesing DAMS, INSPECTION, DAM SAFETY, Mass, - Rhode Island Coastal B Gloucester, Mass.	ISTRIBUTION UNLIMITED microd in Block 30, 11 different h nspection Report, Nat the program is: Nati ate for date of repor comy and identify by block number s asin	UNCLASSIFIED 18. DECLASSIFICATION/DOWNGRADING SCHEDULE 10nal Dam Inspection Program; onal Program for Inspection of t.	

ĩ

i

DO 1 JAN 73 1473 EDITION OF 1 NOV SE IS DESOLETE



: -1.

7 -

1_

1.

1.

DEPARTMENT OF THE ARMY NEW ENGLAND DIVISION, CORPS OF ENGINEERS 424 TRAPELO ROAD WALTHAM, MASSACHUSETTS 02154

REPLY TO ATTENTION OF: NEDED

JAN 2 2 1979

Honorable Edward J. King Governor of the Commonwealth of Massachusetts State House Boston, Massachusetts 02133

Dear Governor King:

I am forwarding to you a copy of the Babson Reservoir Dam Phase I Inspection Report, which was prepared under the National Program for Inspection of Non-Federal Dams. This report is presented for your use and is based upon a visual inspection, a review of the past performance and a brief hydrological study of the dam. A brief assessment is included at the beginning of the report. I have approved the report and support the findings and recommendations described in Section 7 and ask that you keep me informed of the actions taken to implement them. This follow-up action is a vitally important part of this program.

A copy of this report has been forwarded to the Department of Environmental Quality Engineering, the cooperating agency for the Commonwealth of Massachusetts. In addition, a copy of the report has also been furnished the owner, City of Gloucester, Public Works Department, Poplar Street, Gloucester, Massachusetts 01930, ATTN: Mr. Robert O'Brien, Director.

Copies of this report will be made available to the public, upon request, by this office under the Freedom of Information Act. In the case of this report the release date will be thirty days from the date of this letter.

I wish to take this opportunity to thank you and the Department of Environmental Quality Engineering for your cooperation in carrying out this program.

Sincerely yours,

JOHN P. CHANDLER Colonel, Corps of Engineers Division Engineer

Incl As stated



and the second second

PHASE I INVESTIGATION REPORT NATIONAL DAM INSPECTION PROGRAM

Identification No.:MA 00187Name of Dam:Babson ReservoirTown:GloucesterCounty:EssexState:MassachusettsStream:Tributary to Mill RiverDate of Site Visit:8 September 1978

BRIEF ASSESSMENT

Babson Reservoir is located on Alewife Brook approximately one mile north of the City of Gloucester, Mass. A dam, spillway and intake works were constructed in 1930 to impound a water supply for the City. The dam consists of an earth embankment approximately 630 ft. long and 40 ft. high with an ungated spillway about 40 ft. long at the center of the structure. The only outlet is a 24-in. pipe from a gate house intake located in the upstream slope.

Babson Reservoir Dam is currently classified as having a "high" hazard potential in the Corps of Engineers National Inventory of dams.

>Based on a visual examination of the structure, the earth embankment and spillway are in good to fair condition. There was no evidence of settlement, lateral movement or other signs of structural failure or other conditions which would warrant urgent remedial treatment.

Based on size and hazard classifications in accordance with Corps of Engineers guidelines, the test flood for this dam is the Probable Maximum Flood (PMF). > The spillway has a capacity of 1790 cfs with flashboards removed and can pass the PMF outflow of 1530 cfs (750 csm) with the water level 0.6 ft. below the top of the concrete core wall.

Within two years after receipt of this Phase I Inspection Report, the City of Gloucester, owner of the dam, should engage a registered professional engineer to determine embankment slope stability during an earthquake event and implement the results of this evaluation. The owner should also implement the remedial measures, including removal of trees and brush from the downstream slope and repair of deteriorating concrete, as outlined in Section 2.3.

HALEY & ALDRICH, INC. by:	OTHENTH OF MASSACH
Level aldrich	S ALORICH, JR. 7 734
Harl Aldrich President	EURSSIONAL ENGINE
	3

This Phase I Inspection Report on Babson Reservoir Dam has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the <u>Recommended Guidelines for Safety Inspection of</u> <u>Dams</u>, and with good engineering judgment and practice, and is hereby submitted for approval.

1.6 OOSTPH W. HINEGAN, JR., MEMPER Warer Control Branch ngineering Division

CARNEY M. TERZIAN, MEMBER Design Branch Engineering Division

۰...

1.

1.

L

L

U

U

0. Mr Elroy

JOSEPH A. MCELROY, CHAIRMAN Chief, NED Materials Testing Lab. Foundations & Materials Branch Engineering Division

APPROVAL RECONDENDED:

0E 8. FRYAR

Chief, Engineering Division

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, DC 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I Investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

. .

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I Investigations are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the test flood is based on the estimated "probable maximum flood" for the region (greatest reasonably possible storm run-off), or a fraction thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

TABLE OF CONTENTS

I

I

I

Ī

I

Ī.

Ī

I

Ī

Γ

Ŀ

Ľ

Ľ

and the state of the second second

		Page No.
	MDA MONTONA T	
DETTER UP	TRANSMITTAL,	<u>.</u>
Drief Agg	ADD SICNAMUDE CUERA	1
DEFENCE	ARD SIGNATURE SHEET	11
TARTE OF	CONTENTE	111
AVEDVIEW	DECATOS	
LOCATION	MAD (VI Vii
DOWNIZOW		
SECTION 1	- PROJECT INFORMATION	
1.1	GENERAL	. 1
1.2	PROJECT DESCRIPTION	2
1.3	PERTINENT DATA	4
SECTION 2	- ENGINEERING DATA	
2.1	DESIGN RECORDS	8
2.2	CONSTRUCTION RECORDS	8
2.3	OPERATION RECORDS	8
2.4	EVALUATION	8
SECTION 3	- VISUAL FRAMINATION	
3.1	FINDINGS	9
3.2	EVALUATION	12
SECTION A	- OPERATIONAL PROCEDURES	
4.1	PROCEDURES	13
4.2	MAINTENANCE OF EMBANKMENT	13
4.3	MAINTENANCE OF OPERATING	13
	FACILITIES	
4.4	DESCRIPTION OF ANY WARNING	13
	SYSTEM IN EFFECT	
4.5	EVALUATION	13
SECTION 5	- HYDRAULIC/HYDROLOGIC	
. 5.1	EVALUATION OF FEATURES	14
SECTION 6	- STRUCTURAL STABILITY	
6.1	EVALUATION OF EMBANKMENT	16
	STRUCTURAL STABILITY	
6.2	EVALUATION OF SPILLWAY	16
	STRUCTURAL STABILITY	

iv

A STATE OF A

TABLE OF CONTENTS (Continued)

Page No.

18 18 18

SECTION 7 - ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES 7.1 DAM ASSESSMENT 7.2 RECOMMENDATIONS 7.3 REMEDIAL MEASURES
APPENDIX A - INSPECTION TEAM ORGANIZATION AND CHECK LIST
APPENDIX B - LIST OF AVAILABLE DOCUMENTS AND PRIOR INSPECTION REPORTS
APPENDIX C - SELECTED PHOTOGRAPHS OF PROJECT

APPENDIX D - OUTLINE OF DRAINAGE AREA AND HYDRAULIC COMPUTATIONS

. .

• •

- -

. .

• •

. .

APPENDIX E - INFORMATION AS CONTAINED IN THE NATIONAL INVENTORY OF DAMS



1. Overview of crest and upstream slope from left abutement.



PHASE I INVESTIGATION REPORT NATIONAL DAM INSPECTION PROGRAM BABSON RESERVOIR DAM MA 00187

SECTION 1-PROJECT INFORMATION

1.1 GENERAL

A. <u>Authority</u>. Public Law 92-367, August 8, 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a National Program of Dam Inspection throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region.

Haley & Aldrich, Inc. has been retained by the New England Division to inspect and report on selected dams in the State of Massachusetts. Authorization and notice to proceed were issued to Haley & Aldrich, Inc. under a letter dated 26 April 1978 from Colonel Ralph T. Garver, Corps of Engineers. Contract No. DACW33-78-C-0301 has been assigned by the Corps of Engineers for this work. Camp, Dresser & McKee, Inc. was retained as consultant to Haley & Aldrich, Inc. on the structural, mechanical/electrical and hydraulic/hyrologic aspects of the investigation.

B. <u>Purpose</u>. The primary purposes of the National Dam Inspection Program are to:

1. Perform technical inspection and evaluation of non-Federal dams to identify conditions which threaten the public safety and thus permit correction in a timely manner by non-Federal interests.

2. Encourage and prepare the states to initiate quickly effective dam safety programs for non-Federal dams.

3. To update, verify and complete the National Inventory of Dams.

1.2 PROJECT DESCRIPTION

いないないので

1

A. Location. The dam impounds Babson Reservoir on Alewife Brook, a tributary to the Mill River, in the City of Gloucester, Massachusetts. The dam is located on the southwest end of the reservoir, as shown on the Location Map, page vii.

B. Dam and Appurtenances. The Babson Reservoir Dam consists of an earth embankment, an ungated concrete-faced spillway near the middle of the embankment, and a gate house structure. The total length of the dam is approximately 630 ft. The "Site Sketch Plan", Appendix C-1, shows the general configuration of the dam and appurtenances. More detailed plans and sections are shown on construction drawings in Appendix B.

The right and left embankments are approximately 40 ft. high. Slopes are 2 horizontal to 1 vertical on the downstream side. The upper part of the upstream side is sloped 2.5 to 1, becoming 2.75 to 1 below a berm at El. 45. The embankments contain a 15-in. thick concrete core wall bearing on rock or interlocking steel sheet piling driven to rock, as shown on the section in Appendix B-10. The lower part of the upstream slope is protected by riprap and the upper part is paved with reinforced concrete. There is a gravel road on the crest of the left abutment and the downstream slopes are wooded.

The spillway is a broad crested weir with 2 horizontal to 1 vertical discharge slope supported by rock fill founded on bedrock. It is 40 ft. long with a crest at El. 55, 5.8 ft. below the top of the concrete core wall. Three rows of four 6-in. tile drains exit on the discharge slope. A cross-section through the spillway is also shown in Appendix B-10.

A gate house structure is located left of the spillway on the upstream slope of the dam embankment. The reservoir drain is a 24-in. pipe from the gate house with a hand operated valve near the discharge end. This pipe also feeds a 16-in. line to the pump station downstream of the left embankment.

C. <u>Size Classification</u>. Babson Reservoir has an estimated maximum storage of 925 acre-feet and the dam has a maximum height of about 40 feet. Storage of from 50 to 1,000 acre-feet and a height of from 25 to 40 feet classifies a dam to be in the "small" size category, according to guidelines established by the Corps of Engineers

D. <u>Hazard Classification</u>. Babson Reservoir is currently classified as having a "high" hazard potential in the Corps of Engineers National Inventory of Dams. Computations based on "Guidance for Estimating Downstream Dam Failure Hydrograph", included in Appendix D, confirm this classification. In the event of a failure of the dam, the water pumping station, the elderly housing development, and the dense residential district located near the foot of the dam would be completely inundated. Loss of life and excessive economic losses from structural damage would prevail along both sides of the brook from the dam to its outlet into Mill Pond Tidal Basin.

1-1. E. Ownership. The name and address of the owner are:

City of Gloucester Public Works Department Poplar Street Gloucester, MA 01930 (Phone: 617/283-5940)

The dam has always been owned by the City of Gloucester. Mr. Robert O'Brien is the current director of the Public Works Department.

F. Operator. Mr. Wilford Burke is the superintendent of the water treatment plant and responsible for the day-to-day operation of the dam. He represented the owner during this investigation. His address and telephone number are the same as the owners, listed above.

G. <u>Purpose of Dam</u>. Babson Reservoir Dam was built and is used for impounding a water supply for the City of Gloucester.

H. Design and Construction History. The Babson Reservoir Dam was designed by Fay, Spofford & Thorndike in 1930 to create a water supply for the City of Gloucester. The scope of work included engineering studies of the Alewife Brook watershed and several test borings.

As indicated by the six test borings shown in Appendix B-9 and later during excavation and construction, the site was underlain by stiff blue clay, glacial till with boulders and bedrock which formed a natural basin. Steel sheeting and a 15-in. thick concrete core wall were used to effect a cut off to rock for the dam. Selected soils and boulders excavated from the reservoir were incorporated into the embankments and used for riprap. The gate house was founded on clay. Construction of the dam began in July 1930 and was completed in six months by C. & R. Construction. Several contract drawings prepared by Fay, Spofford and Thorndike are included in Appendix B to show details of the original construction.

Flashboards were added as proposed by Metcalf & Eddy in 1950 to increase the capacity of the reservoir. Around 1968, a 30-in. diameter pipeline was constructed from Babson Reservoir to Goose Cove. In 1970 the water treatment plant adjacent to the dam was completed.

I. <u>Normal Operational Procedures</u>. There is no established formal routine for the operation of the dam. The dam, being a water supply dam, is operated according to the demand and supply of water and the funds available for its operation and maintenance.

1.3 PERTINENT DATA

۰.

à ...

All elevations appearing on drawings and referred to in this report are based on a local datum. To convert from the local datum to National Geodetic Vertical Datum (NGVD), add 3.03 ft. to elevations based on the local datum.

A. <u>Drainage Area</u>. The drainage area of Babson Reservoir is approximately 1,310 acres (2.04 square miles), including the watershed of Cape Pond, water supply for Rockport. The Cape Pond drainage area (Cape Pond is the source of Alewife Brook, the major tributary to Babson Reservoir) comprises an estimated 275 of the total 1,310 acres. Because runoff from the Cape Pond watershed would be tributory to the Babson Reservoir watershed during periods of high runoff, it has been included in the computations for the test flood. The Babson Reservoir pool occupies 40 acres, or 3.1 percent of the total drainage area. The watershed's topography is a mixture of flat and coastal terrain with some moderate hills and swampy areas located adjacent to Alewife Brook.

B. Discharge at Dam Site

1.	Outlet Works	24-in. dia. pipe at invert El. 24
2.	Maximum known impoundment	
	at dam site	Unknown
3.	Ungated spillway capacity	
	at top of dam	1790 cfs at El.
		60.8
4.	Ungated spillway capacity at	
	test flood pool elevation	1530 cfs at E1.
		60.2
5.	Gated spillway capacity at	
	normal pool elevation	Not applicable
6.	Gated spillway capacity at	
	test flood pool elevation	Not applicable

	7. Total spillway capacity at	
	test flood pool elevation	1530 cfs at El. 60.2
	8. Total project discharge at	
	test flood pool elevation	1530 cfs at El. 60.2
с.	Elevation (Local datum)	
	 Top dam Test flood pool-design 	60.8
	surcharge	60.2
	design	58.25
	4. Full flood control pool	Not applicable
	5. Water supply pool (full)	55
	(with flashboards)	57.15
	(without flashboards)	55
	7. Upstream portal invert diversion tunnel	Not applicable
	8. Streambed at centerline of	Not abbildable
	dam9. Maximum tailwater	21 Unknown
D.	Reservoir	
	1. Length of maximum pool	0.72 mi. (Est.)
	2. Length of water supply pool (full)	0 72 mi (Fet)
	3. Length of flood control	othe mail (nact)
	poo1	Not applicable
E.	Storage (acre-feet)	
	1. Top of dam	925
	2. Test flood pool	887
	3. Flood control pool	Not applicable
	4. Water supply pool (full)	635
	5. Spillway Crest	000
F.	Reservoir Surface (acres)	
	1. Top of dam	63.5
	2. Test flood pool	62.5
	3. Flood control pool	Not applicable
	 mater supply pool (IUII) Spillway crest 	56
	~~ ~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	

T

G. Dam Embankment

H.

I.

「ないないない」

L

1.	Туре	Earth
2.	Length	Approx. 630 ft.
3.	Height	Approx. 40 ft.
4.	Top Width	Approx. 15 ft.
5.	Side Slopes	2.5:1 and 2.75:1
		U/S and 2:1 D/S
6.	Zoning	Selected pervious
••		material downstream
		of core wall
7	Impervious core	Concrete core wall
ģ.	Cutoff	Concrete core wall
υ.		or staal sheet
		biling to rock
٥	Crout aurtain	None
7.		None Coro wall drain
1 ^		COLE MAIL GLAIN
10.		and has durin
10.		and toe drain
10.	wengion and Degulating Regilitie	and toe drain
10. <u>Di</u>	version and Regulating Facilitie	and toe drain
10. <u>Di</u>	version and Regulating Facilitie	and toe drain es. Not applicable.
10. <u>Div</u> <u>Sp</u> :	version and Regulating Facilitie	and toe drain es. Not applicable.
10. <u>Div</u> <u>Sp</u> :	version and Regulating Facilitie	and toe drain es. Not applicable.
10. <u>Div</u> <u>Sp</u> : 1.	version and Regulating Facilitie illway Type	and toe drain es. Not applicable. Irregular shape
10. <u>Div</u> <u>Sp</u> 1.	version and Regulating Facilitie	and toe drain es. Not applicable. Irregular shape (broad crested weir
10. <u>Div</u> <u>Sp</u> : 1.	version and Regulating Facilitie	and toe drain es. Not applicable. Irregular shape (broad crested weir with discharge
10. <u>Div</u> <u>Sp</u> 1.	version and Regulating Facilitie	and toe drain es. Not applicable. Irregular shape (broad crested weir with discharge face sloped 2:1)
10. <u>Div</u> <u>Sp</u> 1.	version and Regulating Facilitie illway Type Length of weir	and toe drain es. Not applicable. Irregular shape (broad crested weir with discharge face sloped 2:1) 39.75 ft.
10. <u>Div</u> <u>Sp</u> 1. 2. 3.	version and Regulating Facilitie <u>illway</u> Type Length of weir Crest elevation	and toe drain es. Not applicable. Irregular shape (broad crested weir with discharge face sloped 2:1) 39.75 ft. 55.0 (57.15 with
10. <u>Div</u> <u>Sp</u> 1. 2. 3.	version and Regulating Facilitie <u>illway</u> Type Length of weir Crest elevation	and toe drain es. Not applicable. Irregular shape (broad crested weir with discharge face sloped 2:1) 39.75 ft. 55.0 (57.15 with flashboards)
10. <u>Div</u> <u>Sp</u> 1. 2. 3. 4.	version and Regulating Facilitie <u>illway</u> Type Length of weir Crest elevation Gates	and toe drain es. Not applicable. Irregular shape (broad crested weir with discharge face sloped 2:1) 39.75 ft. 55.0 (57.15 with flashboards) None
10. <u>Div</u> <u>Sp</u> 1. 2. 3. 4.	version and Regulating Facilitie <u>illway</u> Type Length of weir Crest elevation Gates U/S Channel	and toe drain es. Not applicable. Irregular shape (broad crested weir with discharge face sloped 2:1) 39.75 ft. 55.0 (57.15 with flashboards) None Approx. 0.15
10. <u>Div</u> <u>Sp</u> 1. 2. 3. 4. 5.	version and Regulating Facilitie <u>illway</u> Type Length of weir Crest elevation Gates U/S Channel	and toe drain es. Not applicable. Irregular shape (broad crested weir with discharge face sloped 2:1) 39.75 ft. 55.0 (57.15 with flashboards) None Approx. 0.15 percent slope
10. <u>Div</u> <u>Sp</u> 1. 2. 3. 4. 5. 6.	version and Regulating Facilitie <u>illway</u> Type Length of weir Crest elevation Gates U/S Channel D/S Channel	and toe drain es. Not applicable. Irregular shape (broad crested weir with discharge face sloped 2:1) 39.75 ft. 55.0 (57.15 with flashboards) None Approx. 0.15 percent slope Approx. one

J. <u>Regulating Outlets</u>. The main intake is a 24-in. castiron pipe with an invert at El. 24 at the gate house. The pipe feeds a 16-in. intake line to the pump station and a 16-in. bypass line. The capacity of this 16-in. intake line is approximately 40 cfs. At the junction of the 16-in. lines with the 24-in. intake, there is a 24-in. cast-iron blow off line to the stilling basin. The blow off line is controlled by a manually operated gate valve in a manhole at the toe of slope for the dam. During the field inspection, this blow off was shown to be operable.

The intake line is controlled by a manually operated valve in the gate house at the dam crest. There are places for three slots for screens in the gate house.

Two additional methods are available for the purpose of drawing down the level in the reservoir. One is to pump the water into Goose Cove via a 30-in. diameter cast iron pipe utilizing the 4 to 5 mgd capacity pumps located at Goose Cove. The second way is to run the water through the treatment plant at the reservoir via the 16-in. C.I. main.

Ļ

Ι

I

Ι

I

I

Í

I

I

Γ

Ľ

l

[]

SECTION 2 - ENGINEERING DATA

2.1 DESIGN RECORDS

「「「「「「「「「「「」」」」

An engineering design report, Appendix B-4, and contract drawings for the dam prepared by Fay, Spofford & Thorndike in 1930 are available. The drawings include details of many design features. Correspondence from the Essex County Engineer relates to the spillway stability and design of the flashboards.

2.2 CONSTRUCTION RECORDS

The original construction activities were periodically observed and reported by the Essex County Engineer.

2.3 OPERATION RECORDS

Operation records in the form of reservoir water levels and inspection reports by outside agencies are available on the dam.

2.4 EVALUATION

A. <u>Availability</u>. All of the design, construction and operation records mentioned above and available for use in preparing this report are listed in Appendix B with the locations where they can be found. Selected documents from the listing are also included in Appendix B.

B. <u>Adequacy</u>. The available engineering data when used in combination with the visual examination described in Section 3 were adequate for the purposes of the Phase I Investigation.

C. <u>Validity</u>. The information contained in the engineering data may be generally considered valid. Details on the drawings are shown as designed and may vary slightly from those actually built. For example, the configuration of the channel immediately downstream of the spillway differs from that shown on the drawings.

SECTION 3 - VISUAL EXAMINATION

3.1 FINDINGS

à .

. .

٠.

A. <u>General</u>. The Phase I visual examination of the Babson Reservoir dam was conducted on 8 September 1978.

In general, the dam embankment and spillway were found to be in good to fair condition. Some deficiencies which require correction were noted.

A visual inspection check list is included in Appendix A and selected photographs of the project are given in Appendix C.

B. Dam. The earth embankment located right and left of the spillway is generally in good condition. There was no evidence of settlement, lateral movement or other serious defects. Concrete paving on the upstream slope is in satisfactory condition except for localized areas where the concrete has deteriorated. The downstream slope could not be examined closely because of brush and trees.

The following deficiencies were noted:

- Concrete pavement slabs on the upstream slope have deteriorated in several localized areas, the most severe of which is shown in Photo No. 6. Isolated cracking and minor differential settlement of the slabs relative to the core wall has occurred. The sealant used at the slab joints has broken down and needs replacement. A number of joints now have vegetation. The upstream slope is shown in Photos No. 4 and 5.
- 2. The downstream slope is covered by trees, brush, weeds and grass. Trees are mature scotch pine from 10 to 15 in. in diameter and spaced 10 to 15 ft. apart. It appears that they were systematically planted. One tree located at the top of slope near the right abutment was blown over and uprooted. Vegetation on the downstream slope is shown in Photos No. 2, 3, 7 and 8 as well as others.
- 3. Minor seepage in the form of a small (less than 10 ft. square) wet area occurs at the toe of the embankment, approximately 105 ft. left of the spillway. No flowing water was noted. It is understood that this condition has existed for years.

- 4. Earth fill at the top of the embankment immediately right of the spillway has been eroded by rainfall and foot traffic. The maximum depth is about 3 ft. at the top of the downstream slope. Since the concrete core wall at El. 60.8 forms the top of the dam, minor erosion downstream of the wall is not considered serious.
- 5. Minor small depressions in the embankment immediately downstream of the core wall were noted. The cause of these depressions is not known, but does not appear to be a result of erosion through joints in the concrete core wall.

The core wall and toe drains discharge into the stilling basin at the toe of the spillway. Both drains were flowing clear. The left drain is shown immediately left of the 24-in. blowoff pipe in Photo No. 11. The outlet of the right drain is submerged, and is located just in front of the observer in Photo No. 12. Coarse gravel and stones cover the end of the pipe.

The exposed portion of the concrete core wall is in good condition. The wall has been patched a number of times and a portion of these patches are now loose. The surface of the wall has eroded and exposed the aggregate. The sealant at the wall joints has broken down and needs replacement. Minor vegetation is present at some of these joints. Other joints have started to break down.

÷ ...

1

C. Appurtenant Structures. The spillway was found to be in good condition. The approach to the spillway is formed by pavement slabs on the upstream face of the dam, Photo No. 9. The surface of the slabs has eroded and the aggregate is exposed. The sealant at slab joints has broken down. Two logs are present at the entrance to the spillway, Photo No. 9. The impact of these logs against the core wall has caused spalling of the wall. Flashboards on top of the weir are in good condition. The flashboards have been securely bolted to each other and fastened to the training walls. It is questionable whether these flashboards would release under flood conditions.

The downstream side of the spillway, Photo No. 10, is formed by inclined pavement slabs placed on rock fill. The slabs show considerable erosion on the surface. Joint sealant has broken down at the joints and vegetation is present. Cold

joints in the slab have been exaggerated by the erosion. The side walls of the downstream portion of the weir (chute) have been patched. A number of these patches are now loose. Shrinkage cracks and several stress cracks are present in the side walls. Efflorescence is present on the wall surfaces. Considerable erosion has taken place at the downstream end of the chute where it joins the stilling basin. The surface of the chute has stains from the discharge of drain holes in the chute, Photo No. 12.

The side walls of the stilling basin are of reinforced concrete. The left side wall shows considerable cracking and efflorescence. This wall should be considered in good to fair condition. The right side wall shows minor cracking and some efflorescence. This wall is in good condition. The end walls of the stilling basin are of cut stone masonry. One small section of this wall, on the left side where it joins the downstream channel, is on the verge of collapse. The rest of the cut stone masonry wall is in good condition with some open joints.

..

- -

.

. .

È.

4.

÷.

• •

1.

. .

1.

1.

The gate house, Photo No. 14, is in good condition. The superstructure is of cut stone masonry. One crack was noticed in the stone work on the left side of the gate house. Metal work in the form of ladders, railings, hatches and screen guides show considerable deterioration. Hatches have been removed from the openings they once covered. This metal work is considered to be in good condition. The exterior surface of the concrete has been eroded to expose the aggregate at the water line. The interior surfaces of the concrete show cracking and efflorescence.

The service bridge to the gate house is in good condition except for the concrete support brackets at the gate house end. The two brackets show considerable cracking and loose concrete. These brackets should be considered in poor condition.

All railings observed on the service bridge and within the gate house are considered to be in poor condition. Major portions of these railings are missing. The remaining portions show considerable deterioration.

D. <u>Reservoir Area</u>. The area around Babson Reservoir is generally wooded with irregular topography and rock outcrops. There are no conditions which would lead to a significant increase in sediment load to the reservoir or landslides which would cause waves to overtop the dam. E. Downstream Channel. The channel downstream of the stilling basin is shown in Photo No. 13. It is a narrow channel formed by stone masonry walls and differs from the 48 ft. wide "ditch" shown on the drawing in Appendix B-9. The channel is discussed further in Section 5.

3.2 EVALUATION

I

4 .

. .

÷ .

i .

÷ .

Based on visual observations during the site examination, the general condition of the project is satisfactory. Deficiencies which have been noted should not have a serious effect on the performance or safety of the dam.

SECTION 4 - OPERATIONAL PROCEDURES

4.1 PROCEDURES

۷.

In general, there are no formal procedures to assure regular maintenance and satisfactory operation of the dam. The current dam operator attempts to keep an adequate water supply in the reservoir by pumping water to or from Goose Cove Reservoir.

4.2 MAINTENANCE OF DAM

There are no established procedures to assure periodic inspection and maintenance of the dam. A maintenance crew from the Gloucester Public Works Department is available to perform work when requested.

4.3 MAINTENANCE OF OPERATING FACILITIES

The operation of the facility is based on the demand and supply of water rather than any formal established operational procedures.

The outlet from the dam does not receive regular maintenance, but is operational. However, the gates appear to have received limited maintenance.

4.4 DESCRIPTION OF ANY WARNING SYSTEM IN EFFECT

There is no formal warning system or emergency preparedness plan in effect for this structure.

4.5 EVALUATION

The current operation and maintenance procedures for Babson Reservoir are inadequate for a high hazard structure of this size. An annual inspection and maintenance program should be developed to remedy deficiencies before they become a threat. In addition, the City of Gloucester should establish a formal written emergency preparedness plan and warning system, since failure of the dam would cause loss of life and extensive property damage.

SECTION 5 - HYDRAULIC/HYDROLOGIC

5.1 EVALUATION OF FEATURES

. .

A. <u>Design Data</u>. A set of plans entitled "Alewife Dam and Reservoir - Gloucester, Mass." bearing the date of June, 1930 were the basis for the construction of this facility. The reservoir was constructed in order to augment the City's water supply and was designed for a safe yield of 1 MGD. Hydraulic design data developed by Fay, Spofford, and Thorndike indicate that the spillway had been designed for a flow of 800 cfs. for a depth of flow of 3.25 ft. over the weir. However, the total freeboard of the dam above the weir level was designated to be 6 ft. for safety. The reservoir's inflow was computed using the Rational Method on the basis of a 2.25 square mile drainage area. However, because of land use changes and the construction of man-made drainage divides (i.e. Route 128), the present size of the watershed is approximately 2.04 square miles.

The recommended test flood for the size (small) and hazard potential (high) of this dam is in the range of the one-half probable maximum flood (1/2 PMF) to the probable maximum flood (PMF).

B. Experience Data. The PMF was determined using the chart prepared by the Corps of Engineers, New England Division in the Guidelines. Assuming flat and coastal terrain, the PMF is 1740 cfs. By taking advantage of surcharge storage, this peak is decreased to 1530 cfs. Because the water surface area is an estimated 3.05 percent (40 acres) of the total drainage area, flood routing techniques were not deemed worthwhile. The spillway will discharge the peak flow of 1530 cfs. with the reservoir water surface at El. 60.2, 0.6 ft. below the top of the concrete core wall.

C. Visual Observations. The inspection revealed that no significant modifications have been made to the inlet or outlet works since the construction of the dam, with the exception of the channel immediately downstream which is of man-made origin with vertical stone masonry walls. Approximately 62 ft. downstream of the dam's stilling basin, there exists a 60-inch diameter concrete pipe which carries the flow for an estimated 41 ft. at which point the stone channel resumes, Photo No. 13. Approximately 260 ft. further downstream, the brook is conveyed in twin 48-inch concrete pipes under the road leading to the elderly housing project. After this point, the brook flows in a natural earth channel with cobbles and dense vegetation encroaching upon it. It is confined to culverts under the private way on the westerly side of the housing project (twin 36-in. diameter and one 12-in. diameter concrete pipes) under Cherry Street (36 in. x 58 in. C.M. Plate Arch) and under the D.P.W. Yard (48-in. diameter concrete pipe). It empties into what appears to be a tidal flood basin on the westerly side of the D.P.W. Yard and eventually into Mill Pond.

D. Overtopping Potential. As stated previously, based on the size (small) and hazard (high) classifications published in the Guidelines, the test flood falls in the range of the 1/2 PMF to the PMF. However, because of the elderly housing located in such close proximity to the base of the dam, as well as the surrounding dense residential district, the test flood has been designated the PMF. A rating curve for the dam's spillway was developed, and demonstrated that the spillway was capable of handling approximately 1790 cfs with the flashboards removed. Therefore, since the value of the PMF is 1530 cfs , it is estimated that the spillway can pass the test flood with 0.6 ft. of freeboard remaining.

E. Evaluation. As stated previously, the spillway is capable of handling the PMF. However, a failure of this dam would result in extensive downstream damage and loss of life would be unavoidable. The degree of this damage would lessen as one approached Mill Pond Tidal Basin. However, the high hazard potential from this flow would still exist until it entered the tidal basin. At this point, the available storage in the basin would most likely contain the flow.

.

.

SECTION 6 - STRUCTURAL STABILITY

6.1 EVALUATION OF EMBANKMENT STRUCTURAL STABILITY

٠.

• -

A. <u>Visual Observations</u>. There was no visual evidence of instability of the earth embankment during the site examination on 8 September 1978. However, it was not possible to closely examine the downstream slope because of dense vegetation.

B. Design and Construction Data. A theoretical analysis of the structural stability of the embankment slopes was not possible due to lack of pertinent design and construction data, in particular with reference to the properties of earth materials placed in the embankment. Nevertheless, since the embankment is only 40 ft. high, has a 2 horizontal to 1 vertical downstream slope and a central concrete core wall to rock and internal drains, the embankment slope can be expected to be stable under static loading conditions. Upstream slopes of 2.5:1 and 2.75:1 are reasonably flat.

C. <u>Operating Records</u>. No operating records or measurements from field instrumentation are known to exist for this dam.

D. <u>Post-Construction Changes</u>. There are no known postconstruction alterations or additions to the project which affect embankment stability.

E. <u>Seismic Stability</u>. Babson Reservoir is located in Seismic Zone 3. The stability of the embankment slopes during an earthquake is unknown. Settlement of the crest and downslope movements during a seismic event are a function of foundation soils below the embankment and properties of embankment materials. These conditions should be determined and stability analyses made using conventional equivalent static load methods.

6.2 EVALUATION OF SPILLWAY STRUCTURAL STABILITY

A. Visual Observations. There was no visual evidence that movement or distress had taken place in the spillway.

B. Design and Construction Data. Design data in the form of construction plans are available on the spillway. A letter from the design engineers shown in Appendix B-7 states that the spillway as originally designed would have a stability "factor of safety of at least four". The spillway is formed by concrete pavement slabs over rock fill on a 2:1 slope. The structural stability of the spillway is, therefore, dependent on the stability of the roc' fill. Rock fill on a 2:1 slope, confined by concrete walls, can be expected to be adequately stable under static loads.

2

.

۷.

C. Operating Records. No records or other information was located which indicated stability problems with the spillway.

D. Post-Construction Changes. Although flashboards were added to the spillway after the original construction, there have been no post-construction structural alterations to the spillway.

E. Seismic Stability. The stability of this spillway under earthquake loading is dependent upon the seismic stability of rock fill which supports the concrete pavement slabs. While a Zone 3 earthquake event would cause some shifting and possible downslope movement of boulder fill and thus damage to the spillways, it is unlikely that the spillway would suffer a catastrophic failure.

SECTION 7 - ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES

7.1 DAM ASSESSMENT

E.

4...

A. <u>Condition</u>. The visual examination of the Babson Reservoir dam revealed that the embankment and spillway are generally in good to fair condition. There were no obvious signs of failure or other conditions which would warrant urgent remedial treatment.

Based on the results of computations included in Appendix D, the spillway is capable of passing the test flood, which is based on the probable maximum flood, with 0.6 ft. of freeboard remaining.

B. Adequacy of Information. The information available concerning the design and construction of the dam are adequate for a Phase I Investigation when supplemented by field observations.

C. <u>Urgency</u>. The recommended additional investigation and remedial work outlined in Section 7.2 and 7.3 should be undertaken by the Owner and completed within 24 months after receipt of this Phase I Inspection Report.

D. Need for Additional Investigation. An additional investigation is required, as outlined in the following section.

7.2 RECOMMENDATIONS

It is recommended that the Owner engage a registered professional engineer experienced in dam design to undertake an investigation of embankment stability under earthquake loading conditions for Seismic Zone 3.

7.3 REMEDIAL MEASURES

A. Alternatives. Not Applicable.

B. Operating and Maintenance Procedures. The following remedial work should be undertaken by the City of Gloucester:

1. Cut and remove trees on the downstream slope of the embankment. Stumps may be cut flush with the ground and left in place. Remove all brush and cut grass and weeds. For the future, the downstream slope should be mowed at least once a year to limit the height of vegetation and allow for visual examination of the embankment.

- 2. Place earth fill in shallow depressions at the top of the embankment adjacent to the concrete core wall. Place earth fill immediately right of the spillway where erosion has occurred, to restore embankment cross-section to the original design geometry.
- 3. Clear debris from the stilling basin below the spillway, in particular in the area of the underdrain discharge pipe on the right side. The pipe should flow freely without obstruction.
- 4. Repair the concrete support brackets at the gate house end of the service bridge.
- 5. Renew railings at this facility.
- 6. Renew gratings, hatches and ladders within the gate house structure.
- 7. Reseal all joints in the concrete pavement on the upstream slope, exposed core wall and spillway. Remove all loose concrete patches, fill all resultant voids, spalls, and missing pieces of pavement with concrete.
- 8. Resurface the chute portion of the spillway with shotcrete, mortar or other materials to prevent further deterioration of the spillway.
- 9. Repair the cut stone masonry wall at the entrance to the discharge channel.

Due to the "high" hazard potential classification, the Owner should establish a formal operations and maintenance manual for this dam. The operating procedure should include provisions for biennial technical inspection of the dam and for surveillance of the dam during periods of heavy precipitation and high reservoir water levels. The procedures should delineate the maintenance work to be done on the dam to ensure satisfactory operation and to minimize deterioration of the facility.

The Owner should develop a formal emergency preparedness plan and warning system to be used in the event of impending failure of the dam. The system should be developed in cooperation with other local officials and downstream inhabitants.

APPENDIX A PACTION TEAM ORGANIZATION AND CHECK LIST

Page No.

1

SUNI INSPECTION PARTY ORGANISATION

VISUAL DESTRUCTION CHECK LIST

Dem Embankment

e.

Outlet Works - Approach Channel, Spillway Weir, Stilling Basin and Discharge Channel

Outlet Works - Gate House

VISUAL INSPECTION PARTY ORGANIZATION

NATIONAL DAM INSPECTION PROGRAM

Dam: Babson Reservoir

Date: 8 September 1978

Time: 0900-1430

Weather: Clear and Cool (50's F.)

Water Surface Elevation Upstream: 51.45 (local datum)

Stream Flow: Negligible

Inspection Party: Harl P. Aldrich, Jr. - Soils/Geology Haley & Aldrich, Inc. Roger H. Wood - Structural/Mechanical Camp, Dresser & McKee, Inc. Charles E. Fuller - Hydraulic/Hydrologic Camp, Dresser & McKee, Inc.

Present During Inspction: Wilford Burke, Chief of Treatment Plant Richard A. Brown, Haley & Aldrich, Inc. Donna D'Amore, Camp, Dresser & McKee, Inc.

A-1

VISUAL INSPECTION CHECK LIST NATIONAL DAM INSPECTION PROGRAM				
DAM:Babson Reservoir	DATE :8 Sept			
AREA EVALUATED	CONDITION			
DAM EMBANKMENT				
Crest Elevation	60.0 (local datum); Top of concre core wall El. 60.8			
Current Pool Elevation Maximum Impoundment	51.45 Unknown			
Surface Cracks	None observed			
Pavement Condition	No pavement			
of Crest	small shallow depressions adjacent to concrete core wall			
Lateral Movement	None observed			
Vertical Alignment	Good (top of concrete wall slight) uneven, by 1 to 2 in. in places			
Condition at Abutment and at Concrete Structures	Conditions at abutments good; good immediately left of spillway; right of spillway, adjacent to wall, there has been erosion by rainfall and foot traffic up to 3 ft. depth, 4 ft. wide, at			
Indications of Movement of Structural Items on Slopes	downstream side of crest No structural items on slopes			
Trespassing on Slopes	Frequent at crest of dam and upstream slope, although area in posted			
Animal Burrows in Embank- ment	None observed, but downstream slop difficult to examine because of vegetation			
Vegetation on Embankment	Top of embankment is grass, mowed; trees, brush, weeds and grass on downstream slope including mature scotch pine from 10 to 15-in. diameter spaced 10 to 19 ft. apart			
Sloughing or Erosion of Slopes or Abutments Rock Slope Protection -	Minor, but some at contact with spillway No riprap; upstream slope is paved			
Riprap Failures	with a 6 in. reinforced concret slab above El. 45; The surface the concrete pavement has erode and the aggregate is exposed. There is differential settlemen			
	,			

「あるのではない」

	I	VISUAL INS	VISUAL INSPECTION CHECK LIST					
	1	NATIONAL DAM INSPECTION PROGRAM						
	1	DAM: <u>Babson Reservoir</u>	DATE : 8 Sept 78					
	Ι		CONDITION					
		AREA EVALUATED	CONDITION					
	L	Rock Slope Protection - Riprap Failures (Cont.)	of the pavement slabs. Joints are in need of new sealant. There are a number of joints with minor					
	Γ		vegetation present. There are					
	4 • 7-		slabs and small missing portion of pavement slabs					
	I .	Unusual Movement or Cracking at or near Toes	None observed					
	1.	Unusual Embankment or Downstream Seepage	Small wet area (less than 10 ft. square) at toe of embankment about 105 ft. left of spillway.					
	Ī		no flowing water; another moist					
	4.	Piping or Boils	None observed					
	I.	Foundation Drainage Features and Toe Drains	⁶ -inch vetrified clay drains immediately downstream of					
			concrete core wall and at toe					
	L		spillway stilling chamber; water flowing from both pipes.					
	Ι	Instrumentation Systems Exposed Concrete Core Wall	None The exposed portion of the core wall					
	-		has been patched in a considerable number of places. A number of these are new loose Vertical					
	Å •		cracks and efflorescence are					
	Γ		and exposed the aggregate. Joints have been sealed but it needs to					
	r		be renewed. Breakdown of the concrete is ocurring at some of					
	L		the joints. There are isolated instances of vegetation in the					
	Γ		joints. The major portion of the railing on top of the wall is missing; the remaining portion					
	Γ		is in disrepair.					
	L~'	9						
	E	₹ g	A-3					
		Z HALEY & ALDRICH, INC.						

~

والمتعافية والمتعاقبة والمعاملة والمعالية والمعالم والمعالم ومعالما والمعالية والمعالية والمعالم والمعالم والمعالم والمعالم

.

. ٠
AREA EVALUATED	CONDITION
Drain Holes	Drain holes on spillway slope an generally open. Three of fou located at the toe are flowing
c. Stilling Basin	
General Condition	The left side wall shows many or and considerable efflorescend The right side wall shows lit cracking and some efflorescen The end wall is cut stone mas with some open joints. One small area of this wall where becomes the left side wall of discharge channel is almost completely broken down. The basin contains considerable soil reported to have been wa down from the dam embankment. The blowoff pipe as well as t underdrains from the dam dis- charge into the stilling basi All pipes appear to be clear drain although one of the und drain outlets is presently be the silted area. Bottom of b has automobile tires and othe debris
d. <u>Discharge</u> Channel	
General Condition	Narrow vertical channel formed by stone masonry walls. General free of vegetation and debris See text of report and photog
OUTLET WORKS - GATE HOUSE	
a. Approach Channel	The outlet works is adjacent to reservoir; no approach channe present

٠ •

- j

	DAM: <u>Babson Reservoir</u>	DATE:8_Sept_
	AREA EVALUATED	CONDITION
ь.	Gate House Structure	
	General Condition	Good condition; the stone masonry superstructure has one noticeal crack in stone work. Windows and doors need replacement. Interior metal work especially ladder, hatches and guides for screens need replacement. Othe interior metal work needs re- painting. The concrete sub- structure shows erosion on the exterior surfaces at the water line. Efflorescence and crack was observed on the interior s There is debris present on the gate house floor
c.	Bridge to Gate House	
	General Condition	The concrete bridge is in good structural condition other that the concrete support brackets at the gate house end. The brackets indicate sever cracki and need for rebuilding. The bridge railing is in need of replacement
d.	Mechanical and Electrical	
	Reservoir Gauge	The mechanical float gauge is operable; reservoir level indi- cated by pointer on circular d
	Service Gates	repainting The service gates are operable bu
	Lightning Protection System	need repainting None observed
	Emergency Power System Wiring and Lighting System in Gate Chamber	None Conduits and outlets have rust pr sent. It is presently operably but its condition is only con- sidered fair. It should be re

. .

i.

	VISUAL INSPECTION CHECK LIST NATIONAL DAM INSPECTION PROGRAM							
DAM:DADSON RESERVOIT DATE: 8 Sept								
Ľ	AREA EVALUATED	CONDITION						
e	. Outlet Pipeline	The pipeline is not visible for inspection						
j g								
MD 414		A-						

APPENDIX B LIST OF AVAILABLE DOCUMENTS AND PRIOR INSPECTION REPORTS

-

•••

•••

۰.

.

ł

	Page No.
LIST OF AVAILABLE DOCUMENTS	1
SELECTED DOCUMENTS	
Text of design report by Fay, Spofford & Thorndike, Inc., Boston, MA, 31 May 1930	4
Letter regarding adequacy of spillway stability design, Fay, Spofford & Thorndike, Inc., Boston, MA, 3 November 1930	7
Contract drawings - Alewife Dam and Reservoir, Sheets 2 and 3, June 1930	9
PRIOR INSPECTION REPORTS	
Letter report on the 13 construction inspections from 22 July 1930 through 4 December 1930 by the Essex County Engineer	11
Summary reports on the 26 inspections from 21 January 1931 through 31 March 1968 by the Essex County Engineer	13
15 July 1971 report by the Mass. Department of Environmental Quality Engineering	20

LIST OF AVAILABLE DOCUMENTS BABSON RESERVOIR DAM

DOCUMENT

1

Design report, Fay, Spofford & Thorndike, Inc., Boston, MA, 31 May 1930

Contract Drawings - Alewife Dam and Reservoir, Fay, Spofford & Thorndike, Inc., Boston, MA, June 1930

CONTENTS

Text, hydraulic calculations and location map for original dam design

Sheet 1 - "General Plan and Sheet 3 - "Sections of Dam Plan and Sections" Sheet 8 - "Pumping Station Sheet 9 - "Pumping Station Electrical Details" Sheet 7 - "Pumping Station Sheets 5 & 6 - "Gatehouse Sheet 4 - "Profile of Dam Elevations and Details" Sheet 10 - "Miscellaneous Sheet 11 - "Elevated Tank Sheet 2 - "Plan of Dam, Boring and Grading" and Substructure" Iron and Steel" and Details" and Details" Key Map"

and Force Main"

LOCATION*

Essex County Engineers Office⁽¹⁾ and Appendix B-4

Gloucester Public Works Department(2) and Appendix B-9 and Appendix B-10

SI1	T OF AVAILABLE DOCUMENTS BABSON RESERVOIR DAM (Cont.)	
DOCUMENT	CONTENTS	LOCATION
"Alewife Dam, Gloucester, MA Inspections Made During Con- struction", R.R. Evans, Salem, MA, 1930	Detailed reports and a summary letter of construction inspec- tions by the Essex County Engineer	Essex County Engineers Office(1) and Appendix B-11
"Stability Under Various Assumptions", R.R. Evans, Salem, MA, 30 October 1930	Calculations for chability against sliding the Essex County Enganger	Essex County Engineers Office(1)
Letter from Fay, Spofford & Thorndike, Inc. to Essex County Engineer, dated 3 November 1930	Statement regarding adequacy of spillway stability design	Essex County Engineers Office(l) and Appendix B-7
Water Treatement Facilities, Contract No. 1964-2, City of Gloucester, 14 October 1964	Plans and specifications for treatment plant completed in 1970	Gloucester Public Works Department (2)
Letter from Metcalf & Eddy, Engineers, to Essex County Engineer, dated 5 November 1969	Discussion and plan drawing of filter and drain separa- ting new treatment lagoon and the downstream slope of dam	Essex County Engineers Office(2)

I

• •

• •

.

• •

• •

• •

.

ļ

i | • •

٠

B-2

J

Contraction of the second s					- - #					
		LOCATION	Essex County Engineers Office(1) and Appendix B-13	Mass. Department of Environmental Quality Engineering ⁽³⁾ and Appendix B-20	Gloucester Public Works Department ⁽²⁾				ineering	え
	ST OF AVAILABLE DOCUMENTS BABSON RESERVOIR DAM (Cont.)	CONTENTS	As listed on cover page of Appendix B	15 July 1971 report	Reservoir levels		gineers Office et O	ic Works Department 01930	t of Environmental Quality Engi erways et 14	
	SIT	DOCUMENT	Inspection reports from 1930 through 1968	Inspection reports after 1968	Operation records	* Addresses:	 (1) Essex County Eng 32 Federal Stree Salem, MA 01970 	<pre>(2) Gloucester Publi Poplar Street Gloucester, MA</pre>	 (3) Mass. Department Division of Wate 100 Nashua Stree Boston, MA 0211 	
										B-3

FAT. SPOFFORD & THORNOIKE CONSULTING ENGINEERS

752823HE # Far Cradic25 # 30877888 -.gen arts 844 848 4 68444 Elandels a familis 84444 4 4844

TELERHORE HUBBARD (84) CABLE TATEBIRE BORTON

44 SCHOOL STREET. BOSTON, HASS.

. County Commissioners Essex County

Salem, Massachusatts

. ...

Attention Mr. Robert R. Evans, County Engineer

Gentlemen:

; . n

J,

÷

1

•

٠.

••

d =

-

*-

We have been engaged by the Board of Water Commissioners of Gloucester, Massachusetts, to prepare contract drawings and specifications of a dam and reservoir together with appurtenent structures which they desire to build at the earliest possible moment on Alewife Brook in the City of Gloucester. They have requested us to submit to you all necessary data for your approval as required by the General Laws of the Commonwealth. We are, therefore, submitting herewith a United States Geological sheet upon which we have shown the location of the project and the extent of the natural watershed tributary to the site of the dam; a topographical plan of the dam and reservoir site showing the exact location of the dam; and e drawing showing the size of the dam and details of construction. We respectfully request for the Soard of Water Commissioners your approval of the plans for the construction of this dam.

Location of Dam. The site of the dam is north of the built-up area of Gloucester proper on Alewife Brook about 400 feet distant from the corner of Poplar Street and Russell Avenue.

Area of Watershed. The area of the watershed of Alewife Brook which is tributary to the site of the dam, including the watershed of Cape Fond, is approximately 2.25 square miles. Cape Fond used by the fown of Rockport as a source of water supply is located in the upper part of this watershed and is the source of Alewife Brook. The area of the watershed tributary to Cape Fond is about .55 of a square mile. These areas have been determined from United States Geological Surveys and from aerial photographic surveys.

Description of Dam. The dam will have a maximum height of about 35 feet and will be about 600 feet long at the crest. It will be built of earth with a reinforced concrete core wall and a sheet pile cut-off. The downstream slope will be 2 to 1 and the upstream slope will be 2-1/2 to 1 between elevation 57

>

· · ·

--

B-4

May 31, 1930

CONSULTING ENGINEERS BOSTON, MASS.

€.

i

County Commissioners, Essex County - 2 Vey 31, 1930

and elevation 45, and 2-3/4 to 1 from elevation 45 to the bed of the valley. There will be a five-foot berm at the upstream side of the dam at elevation 45. It will be necessary to strip the site of the reservoir to prepare it for the storage of the water and it is planned to use as much of this material in the construction of the dam as possible. The site of the reservoir will be thoroughly cleared and grubbed previous to stripping. Adjacent to the downstream side of the core wall, the plans call for clean gravel with a thickness varying from four feet at the base of the dam to 2 feet at the top. Between this material and a slope from the top of the dam of 1 to 1, it is proposed to use selected material from the reservoir stripping which will consist of loam, sand and gravel or if this material does not seem satisfactory to use, we will substitute a more suitable material obtained below the surface of the ground in the reservoir site which will not contain very much organic matter. Between this material and the downstream face, the embankment will consist of stripping material from the reservoir site. Ten inch vitrified pipe underdrains laid with open joints wrapped with cheesecloth and surrounded by clean gravel or broken stone will be built to drain any seepage through the core wall and through the gravel material adjacent to the core wall. These underdrains will keep the degree of satu-ration of the embankment below the core wall to a minimum. The material in the upstream side of the core wall will consist almost entirely of earth to be stripped from the reservoir site. The part of the slope above the bern will be protected by gravel and concrete paving. That part of the slope below the bern will be protected by gravel or broken stone or large stones which can not be used in the earth embankment. The specifications will call for the embarkment to be thoroughly compacted either by use of rollers especially adapted for the purpose or by the hauling equipment to be used in hauling the material to the embankment.

Outlet Conduit. For use in carrying the flow of the brook during the construction, the plans call for the construction of a 36-inch class B cast iron, Bell and Spigot pipe laid in a continuous concrete cradle underneath the dam. This pipe will be closed at the upper end after the completion of the dam and previous to the storage of water by a cast iron pipe cap; it will also be closed at the center of the dam by the use of concrete in a manhole especially designed for the purpose.

Spillway. The spillway will be located in the middle of the dam and will consist of concrete side walls with steel sheet pile out-offs, a stilling chamber at the foot of the spillway and a paved slope of reinforced concrete. The plans call for a

FAT SPOFFORE & THORNEISE CONSULTING ENSINEERS BORTON, MASS.

County Commissioners, Esser County - 3 May 31, 1930

Ċ

z**

٠.

4 .

ž

stone embankment undermeath the spillway and below the concrete cut-off wall. The part of the dam adjacent to the spillway on the upstream side of the cut-off wall will be of earth from the reservoir stripping similar to the remaining portion of the dam. The spillway has been designed for a flow of 300 cubic feet per second for about a depth of flow of 3.25 fast over the weir. We have computed the maximum flood flow from this area for the design of the spillway by the rational method. We have not considered the effect of storage in Cape Pond but have considered the effect of storage in the proposed reservoir which has a sur-face area of about 40 acres. We estimate that the maximum rate of run-off from this area may amount to 1250 cubic feet per second. This is based, however, upon a time of concentration of about one hour. The time of concentration for the maximum flow over the spillway will be materially lengthened on account of 7 4's the storege of water in the reservoir between the level of the We estimate that when the run-off enterweir and flood level. 5 ing the reservoir coincides with the capacity of the weir at al depth of flow on the weir of about 3.25 feet, the time of concentration will be about 2-1/2 hours. We believe these \mathbf{Y} 6 estimates of flood flow are very conservative but however, we Ъ have designed the dam with a free board great enough to care for a much larger flow than that estimated. The total free board of the dam above the weir level is 6 feet.

<u>Foundations of Dam</u>. We have taken several wash borings at the site of the dam, and find that there is a top stratum of sand and silt of an average thickness of 3 to 4 feet, and underlying this stratum, there is medium blue clay and hard yellow clay for a depth of about 35 feet resting upon bed rock.

<u>Cate House</u>. The water from the reservoir will enter the distribution system through a reinforced concrete gate house, located between the berm on the upstream face of the dam and the top of the dam. There will be a 24-inch cast iron pipe laid in a concrete cradle extending from the gate house to a pumping station below the dam.

We will be glad to furnish you with any additional information regarding this project which you may desire. The Board of Water Commissioners desire to proceed with the construction of this project at once. We would, therefore, appreciate very much your immediate consideration of this request for approval of the plans.

Very truly yours.

By

FAY, SPORFORD

З.

Kyo;

-1 ND TEORYD/IKE

X: MEZ

 $\overline{}$

Mar we down a commence

-

1ê e

.

4

....

é•

.

...

1.

FAY, SPOFFORD & THORNDIKE CONSULTING ENGINEERS

TELEPHONE HUBBARD ISSI CARLE PATEDIRE BOSTON

44 SCHOOL STREET, BOSTON, MASS.

Robert R. Evans, Esq. County Engineer Court House Salem, Massachusetts

Dear Mr. Evans:

Our Mr. Myott has told me of his talks with you regarding the stability of the spillway section of the dam at Gloucester. He has also informed me of the work already done and to be done on this spillway in addition to that called for by the plans and specifications.



In view of the doubts which may have arisen in your nind, I have today personally reviewed the situation in order to check once more the design prepared by us and to consider also the effect of the modifications of the design agreed upon between Mr. Myott and yourself.

is regards the original design of this spillway, I am satisfied from the investigations made today that it would have had a factor of safety of at least four. In other words, that the resistance to failure of the spillway construction as originally proposed would have been at least four times the maximum force which could be exerted on it due to a combination of water pressure and earth pressure against the upstream face of the core wall.

The changes in the construction of the spillway made as the result of your suggestions; that is, the grouting of the upper layer of rock fill, additional dowelling, and the substitution of concrete for a portion of the rock fill; have in my judgment added materially to its stability. The construction now being carried out makes of this spillway practically a concrete surfaced dam with a rock fill center. It has no analogy to the ordinary type of rock fill dam, some of which dams, as we well know, have failed for good and sufficient reasons.

In reaching these conclusions we have carried through calculations of hydrostatic and earth pressures according to commonly accepted practice; we have checked these results with the results of extensive tests on actual earth pressures made at the Massachusetts Institute of Technology on a large model

804088 804034 408 5546406 9047 408 5546406 4047 408 554644 40457645 2015846 7485 2024567691

November 3, 1930

TAY SPOTTONS & THOMMERAE Consulting Engineers Soston, Mass.

Robert R. Evans, Esq. - 2 November 3, 1930

۰.

.

in connection with the design of a portion of the "Fifteen Mile Falls" dam of the New England Power Company; and we have checked them also against the results of experience in building retaining walls and bulkheads on waterfront and other constructions which have to withstand the pressure of saturated earths, in which type of construction: I and my associates have had a good many years experience.

It is in the light of all this information that I base my conclusions regarding the ample margin of safety of the spillway.

If there is further doubt in your mind as to the stability of this structure I shall be glad to discuss it with you personally, and to go into the matter in full detail, at some mutually convenient time.

Very truly yours, Attaline Frederic H. Fay

737:X

「「ないない」、「ないない」で Advante -

10 - N

¥ ź







No As . Im.













December 5, 1930.

To the Commissioners of Essex County:

Gentlaman:

U

ی م :

Á.

Â.,

ŝ

4.

-

I submit herewith the following report as to the construction of the Alewife Dam in Gloucester, plans and specifications for which were approved by the County Commissioners on June 20th, 1930.

. ...

Work was begin shortly after your approval was issued, and I have visited the dam at various times since then as follows, viz: July 22, August 11, Sectamber 5, 17 and 29, October 14, 17, 21 and 25, November 1, 7 and 20, and December 4, the structure at the time of this last visit being substantially complete, so that the filling of the reservoir will probably start within a week.

the filling of the reservoir will probably start within a week. The material encountered in the foundation has proved to be what was anticipated, a fairly herd tenacious blue clay from about four fest below the surface, and the steel sheeting has been driven substantially as called for on the plans, but for a bhort distance at both the northerly and southerly ends boulders were found and here a concrete wall was used in place of the sheeting.

Under the gate house it was deemad best to omit the pile foundation, as the meterial seemed to be unquestionably hard enough to carry the load. This was done with my approval, and in fact I believe it is better construction than if the piles had been used.

The material for the embaniment has been found at least as good as required by the specifications, and a large part of it has come from borrow pits excerted within the limits of the reservoir. In the construction of the embaniment, material has been hauled in by trucks and by trailers hauled by tractors, dumped in piles and levelled off by a bulldozer. During the construction of the lower half of the embankment, the weather was very dry and no watering of the material was done. Apparently, however, the continued hauling of the material sufficed to give a well compacted embaniment, and reasonable attention seems to have been given to removal of roots and perishable material.

As the work progressed on the rock fill of the spillway it became evident that this fill would not be what I had assumed in approving the plans. The boulders were mostly rounded and were being dumped into place, but no hand placing done to reduce the voids to a minimum, and the stone placed on top of these to fill

County Commissioners

12/5/30

the voids and level up to the concrete slab were, in my judgment, too small. Following several conferences with the engineer in charge, three trenches were excavated in this rock fill trensversely to the slope of the spillway, and concrete walls were built and well grouted into the rock fill, extending nearly to the surface and tied into the concrete paving. These small stone, for a depth of at least a foot, were also grouted before placing the concrete slab, and the apex of the triangle forming the upper half of the spillway section was cast as a solid concrete block, resting on the rock fill beneath.

- 2 -

Care was taken to provide free drainage for the rock fill at the spillway, and careful attention seems to have been given to the placing of the porous gravel on the downstream side of the core wall in other parts of the dam and to the under-drains leading from it. The concrete in the core wall is apparently of good quality and care has been given to the installation of the copper expansion joints, and, in general, I feel confident that the structure has been well built substantially in accordance with the plans and specifications.

Respectfully submisted,

County Engineer.

E/A-2

Gloucester D. 17

. .

•

۰.

Alewife Brook Dam, northeasterly from the corner of Poplar St. to Russell Ave. Gloucester Water Works, Owners.

1930. Watershed 2.25 sq. m. Max. Ht. 4/, 27.

1930, June. R. R. Evans Investigation of Alewife Dam) 1930, June 20. R. R. Evans Report to Co. Comm. on) petition of Board of Water Commissioners of Gloucester) See 0360 C for approval of plans and specifications to construct dam) 1930. R. R. Evans Insp. made during construction)

1930

ł

ب آز ا

1930, June. Contract Plans approved by the Co. Comm. on file in County Engineer's Office.

1930, Dec. 5. R. R. Evans Report to Co. Comm. See 0350 C - 1930.

1931, Jan. 21. C. C. Sarker, Insp. I visited the new dam at "Dog Town Common". The water level was 43.7' or 6.3' below the top of the spillway. There is evidence of slight seepage from the weep holes at the base of the spillway, but there was none today. The dam is apparently in very good shape.

1931, April 24. C. C. Barker, Insp. Today about one-half inch of water is flowing over the spillway, and one cannot see whether there is any water flowing in the underdrains or out of the drain pipes in the spillway. About 120 feet south of the spillway and several feet from the toe of the slope a small stream of clear water is flowing on the surface in a slight gutter to the stilling basin. It is said this comes from a spring. Also more southerly at the toe of the slope and the old From a spring. Also more southerly at the toe of the slope and the bld earth there is slight seepage. The ground below the dam where stumps atc. were deposited at the southerly end below the dam is more or less wet and there is rusty and slimy water in the ditch along the driveway. On the north side of the spillway channel the ground below the dam is quite wet and there is some seepage or ground water. At the north end next old surface there is slight seepage. One construction joint near the north end has opened some. The slopes and dam are in good condi-tion. tion.

1932, Aug. 2. C. C. Barker, Insp. The dam is apparently in good condition. At each end of the spillway on the upper side the concrete slab next the spillway has settled a little, the one on the nort h end about 3 inches. There is no seepage through the drains on the slope of the spillway, those at the base are covered by the water in the stilling basin. The fourth block of concrete slope paving north of the spillway has disintegrated some. There is some seepage at the toe of the slope on the south end, also some on the north end about the same as at last inspection. The water lavel is about 4 inches be-low the top of the spillway. The slopes are grassed, six rows of pine trees have been planted and also some honey suckle vines.

1932, Nov. 2. R. R. Evans, Insp. Reservoir full and water about 1" in depth running over spillway. Bround wet below ism near south and. No indication that it comes through the dam. Everything which can be seen at this stage of the water seems to be in good condition.

1932 Report to Co. Comm. Safe and in reasonably good condition.

D. 17. Sh. 2

Gloucester D. 17

1934, Sept. 25. C. C. Barker, Insp. I gave a copy of the notice to Mr. Moran, Supt. At the dam I saw Mr. Bray, one of Mr. Moran's men. The water level is very low, the reservoir has just been drawn down as low as possible. There is a slight trickle of water out of the lower drains at the bottom of the spillway. The south east corner of the concrete apron is slightly out of place and somewhat cracked. The cutoff wall on the upper side is somewhat disintegrated at the expansion joint near the south end also one on the northerly end. The base wall at the bottom of the concrete apron about 100 feet from the north end has disintegrated very much. The slab of concrete in the spillway on the upper 5 f the crest on the south side has fallen about 5 inches and the slab on the north side has fallen about 5 inches. Under the center slab there is z somewhat of a cavity. There is settlement in the spillway on the upper side of the crest. The fill next the south side of the apillway has washed some. The lower slopes are well covered with vines and pine trees. As the water is low there is no seepage today.

1934, Dec. 12. R.R.Evans, Insp. Of three slabs up side of spillway wall that at each end has settled some two inches or more at edge against wall, these should be out out and fill beneath investigated.

1934 Report to Co. Comm. The new dam at Alewife Brock seems to be in good condition in all essential respects except that just back of the cut-off wall in the spillway two of the three concrete slabs have settled considerably, although the material underneath them was supposed to be compacted so that this could not happen. I believe that enough of these concrete slabs should be removed so that investigation can be made to ascertain the cause of this settlement, and make sure that it is not serious.

1936 August 10, C.C.Farker, Insp. I left a copy of the notice at the office for John W. Moran, Sutp., no one went to the dam with me. On the south side next the spillway there is a gully in the embankment, three feet wide and 2.5 to 3 feet deep, the earth having washed out down to the stone. At the lower end of the spillway there is a crack in each side wall. Water is trickling out of the two northerly and the south drain pipes at the bottom of the spillway, almost 1/4 inch deep. The settlement in the concrete slabs on upper side of the spillway is about the same. On the upper side the concrete has cracked in a number of places, and the concrete slope paving has settled in some places. At the south end the bottom of the embankment is wet and there must be a large amount of seerage from all indications. Also there is some at the north end. The water level today is about one foot below the spillway.

1936 Report to Co. Comm. The new Alewife dam is in good condition, except that the concrete paving just back of the spillway has settled several inches, and apparently there is a cavity of unknown extent below it, but no investigation by removing parts of the slab has apparently been made. Such an investigation should be made to make sure that the condition is not serious, and some washing which has occurred adjacent to the side walls of the spillway in the earth embankment should be refilled and protected from further wash.

1936 Nov. 20 Mr. Erans. Insp. See Shoot 3

D. 17 Sh. 3

Gloucester D. 17

1938 October 25, C.C.Barker, Insp. I gave a copy of the notice to D. R. Bradley Asst. Supt. The water has been drawn off and is very low. The water wall on the south portion of the dam has been repaired where some of the concrete spalled off. Next the spillway on the south side where the earth fill washed out on the lower slope concrete steps have been built. On the upper slope there are several spots in the concrete apron and tos wall where there is much disintegration also in the cut off wall on the north portion. There is disintegration in the concrete gate house at the water line. The settlement in the concrete slabs on the upper side next the crest of the spillway is greater. The north slab has settled 8" and the south slab 6" pext the crest of the spillway. It is hollow under the center slab, which, I was told by Mr. Wheeler one of the Water Works men, is supported by the man hole which was used during the construction of the dam. Mr. Wheeler says the sepage remains about the same. The earth slopes are well covered with pine trees and honeysuckle vines.

1936 R.H.Evans, Insp. Saw this dam November 20 with Mr. Barker. Along the side wall of the spillway nearest Gloucester there has been considerable washing of embankment. Broken pieces of ledge rock have been filled in against the wall. The top of this fill is rough and considerably below the original level of the earth. Whether some excavation has been made purposely in which to place these stone is not quite evident, but apparently this might have been done to form a gutter. If this is the purpose it should be brought up to the original level, and bound with asphalt or otherwise to prevent washing. The water is barely flowing over the spillway today. Through the water it is possible to see that the slabs behind the spillway are sunken, but not to make any examination. An examination should be made here by removing some of the concrete to ascertain what is below it as Mr. Earker says it sounded hollow when he mad his investigation. The parapet wall along the main dam is disintegrating badly. As yet there is no apparent weakness which would reduce the amount of freeboard, but if it continues that will apparently happen before many years. The embankment seems to be in good condition and no seepage along the toe of the bank is noticeable, but a new drain has apparently been laid a short distance below the toe of the slope discharging into the outlet from the spillway and quite a stream of water is running through this drain. How much of it, if any, comes through the dam cannot be determined as the land towards Gloucester is wet.

1938 November 9, R.R.Evans, Insp. With Mr. Barker visited Alewife Dam in Gloucester to observe conditions beneath the slab on the water side of the spillway where concrete has recently been removed, since my previous conversation with Mr. Moran. Found that for a width of six or eight feet back of the apron on the inside slope the concrete slab has been renewed across the entire width of the spillway, and a space some three or four inches deep is exposed between this opening and the cut-off wall and on the other side of the opening toward the pond this space can be seen to extend many feet. It seems to be an even settlement. The concrete slabs rest on the top of the abandoned manhols and there is no evidence that the water found any outlet. A man, who is apparently an employee of the water board was at the work when I inspected it and I later called on Mr. Moran to talk the situation over with him. I told him that it would, of course, be possible to fill this space under the slab by grouting but that I felt that

D. 17 Sh. 4

Gloucester D. 17

1

a better job night be obtained, and perhaps cost less, to remove the apron immediately back of the cut-off wall and renew some ten or twelve feet of the slab on the side toward the pond, to fill the depression with gravel similar to that which was used originally under the slab, well tamped, to avoid further settlement, and to construct new concrete slabs the same as originally built. He apparently agrees with us that this is the best method to follow and as I understand him will attempt to have it done.

1938 Report to Co. Comm. It was noted in my last report that the concrete paving back of the spillway at the Alewife Dam in West Gloucester had settled and that there was a cavity beneath it. The The same condition was found at the present inspection and again called to the attention of the Superintendent of the Water Board. At that time the reservoir was practically empty to permit some work which is being done at the upper end of the pond, and the Superintendent caused these sunken slabs to be removed so that we could inspect the fill beneath them. We found that the earth fill had settled some four inches or more, but found no evidence that the water was finding any outlet through it behind the concrete block forming the spillway. The matter was discussed with the concrete block forming the spillway. Superintendent and it is my understanding that he is removing the remaining portions of this slab under which settlement has taken place, and will bring the fill up to grade and lay a new concrete pavement upon it. Concrete steps have been built against the wall on the side of the spillway and erosion of this fill by the surface water running down the embankment has been stopped.

1940 Oct. 2, C.C.Barker, Insp. I gave a copy of the notice to L. B. Hull, Supt. Gloucester Water Works. This dam is in good condition. Water is just splashing over the spillway. Some water id dripping out of the weep holes at the base of the spillway. The seepage at the south end is about the same. The upstream face of the northerly cut-off wall is badly disintegrated in two places. There are side walls, 5 feet apart and 3.5 feet high, on the outlet stream below the dam.

1940 Report to Co. Comm. Safe and in reasonably good condition.

1942 July 31, C.C.Barker, Insp. I gave a copy of the notice to L. B. Hull, Supt. This dam is in good condition. The reservoir is full and spilling over. There is much seepage at the southerly end about the same as in the past. There has not been any change.

1942 Report to Co. Comm. Safe and in reasonably good condition.

1944 July 20, S.W.Woodbury, Insp. I gave a copy of the notice to Mr. Hull, but visited the dam alone. Water level is 4 ft. below the lip of the spillway. Concrete is badly disintegrated at corners of walls at spillway, at northerly end and at the lower part of the spillway. Concrete paving is cracked at southerly end. The concrete walls are cracked and spalled at expansion joints. There is some setage through the lower holes of the spillway. The sidewalls of the spillway are badly cracked at the bottom. The condition of the dam is about the same as when last reported. No repairs have been made.

an an an carsen an an an an

D. 17, Sh. 5

Gloucester D. 17

4 -

۰.

.

4

1944 Report to Co. Comm. Safe and in reasonably good condition.

1946 Sept. 20, S.W.Woodbury, Insp. I gave a copy of the notice to Mr. Hall and went to the dam alone. Bushes have been cut on slopes, also the branches of the pine trees have been cut about 6 ft. up. Water just running over soillway. Concrete wall is badly disintegrated at points previously reported. At the bottom of the spillway in the middle there is a block of concrete about 6" x 10" and 12 ft. long scoured out.

1946 Report to Co. Comm. Safe and in reasonably good condition.

1948 Sept. 21, S. W. Woodbury, Insp. Left a copy of the notice for Wr. Hull at his office and went to dam alone. Further inspection needed to see that concrete is repaired. No repairs since last inspection. Conditions below the dam: A new highway (route 123) has been built just below the dam. Water level today: 6" below crest of spillway. Condition of the dam: Concrete very badly disintegrated in many places. Concrete at bottom of spillway should be repaired.

1948 Report to Co. Comm. The Alewife Brook Dam, a large important dam, should be kept in good repair. The concrete on the upstream side is badly disintegrated in many places. Also the concrete at the bottom of the spillway should be repaired. The dam may be considered safe, but the repairs should be made and the dam kept in good condition.

1950 Sept. 27, S.W.Woodbury, Insp. Left a copy of the notice for Mr. Hull at his office and went to the dam alone. Further inspection needed to see that concrete is repaired. New permanent stop planks 2 ft. high have been built on the spillway (Freeboard is now about 3.5 ft.) Conditions below the dam: Gloucester Housing Development is just below the dam. Highway Dept. buildings below the dam. Water level today: 13 ft. below crest of concrete spillway. Concrete very badly disintegrated in many places. Concrete at bottom of spillway has not been repaired.

1950 Report to Co. Comm. The Alewife Brook Dam, due to its location, is a very important dam and should be kept in good repair. The concrete in many places is very badly disintegrated and should be repaired. Recently, flash boards two feet in height were placed in the spillway to give the reservoir increased storage capacity upon the approval of the County Commissioners. This dam may be considered safe, but it should be kept in good condition.

1952 Sept. 25, E.H.Page, Insp. Gave a copy of the notice to Mr. Hull, Supt. of Water Dept., at his office on Froctor Street and went to reservoir alone. No repairs since last inspection. Water level today: 1.3 above crest of conc. spillway and 0.7 below top of permanent flashboards. Conc. badly disintegrated in many places. Conc. at bottom of spillway needs repairing.

1952 Report to Co. Comm. The Alewife Brook Dam, a very important dam due to its location, should be kept in good condition. Although the dam may be considered safe, the concrete is badly disintegrated in many places and should be repaired.

Gloucester D. 17

à

á .

٠.

۰.

ά.

۰.

. .

4.

D 17, Sh. 6

1954, May 28, E.H.Page, Insp. Owner's agent, Wilfred Bourque. Height of glashboards: 2'-1". Minimum freeboard: 2'-11'. Spillway clear. Bad place in conc. wall about 100' easterly of gate house. One place about 3" thickness has spalled off. Quite a lot of seepage at the toe about opposite the above mentioned spalled place. Mr. Bourque said it seems to be a lot worse since they added 2' of flashboards.

1954 Report to Co. Comm. At the Babson Reservoir on Alewife Brook, a very important dam, due to its location, should be kept in good condition. The concrete is badly disintegrated in many places. There is a very bad place in the concrete wall and slope paving about one hundred feet easterly of the gatehouse where the concrete has spalled off to a depth of about three inches. At this point in the dam the toe is very wet.

1956, Sept. 12, E.H.Page, Insp. Owner G.W.W. No repairs since last inspection. Leaks: Toe wet as previously noted. Height of flashboards: 2'. Condition: Same. Conc. spalling very badly in places.

1956 Report to Co. Comm. At the Babson Reservoir on Alswife Brook, a very important dam, due to its location, the concrete is badly disintegrated in many places. It should be kept in good condition. There is a very bad place in the concrete wall and the slope paving has settled about one hundred feet easterly of the gatehouse where the concrete has spalled off to a depth of about three inches. At this point in the dam the toe is very wet.

1958, Dec. 30, E.H.Page & K.M.Jackson, Insp. Elev. of water: 21' below top of flashboards. Height of flashboards 2'. Condition: Same. Conc. spalling badly in many places on dam and spillway. Toe very wet southeasterly of gatehouse.

1958 Report to Co. Comm. At Babson Reservoir on Alewife Brook, a very important dam due to its location, the concrete is badly disintegrated in many places. There is a very bad place in the concrete wall and the slope paving has settled at a point about one hundred feet easterly of the gatehouse where the concrete has spalled off to a depth of about three inches. At this point in the dam the toe is very wet. The walls of the spillway are spalling and disintegrating.

1959 E.H.Page, Insp. Elev. of water 12 over flashboards.

1961, March 10, E.H. Page and P.D. Killam, Insps. Conditions below dam: Same. Elev. of water: 2" over flashboards. Leaks: Same. Height of flashboards: 2'. Condition of dam: Same.

1960 Report to Co. Comm. At Babson Reservoir on Alewife Brook, a very important dam due to its height and location, the concrete is badly disintegrated in many places. There is a bad place in the concrete wall and the slope paving has settled at a point about one hundred feet easterly of the gatehouse. The concrete has spalled off to a depth of about three inches. At this point in the dam the toe is very wet. The walls of the spillway are spalling and disintegrating

1962 Dec. 17, K.M.Jackson, Insp. Owner; City of Gloucester Water Works. Repairs since last inspection: Made boat ramp at east end of dam. Elev. of water: 2'. Height of flashboards: 2'. No obstructions in spillway. Condition: Same as 1960. Man at gate house said

Gloucester, D. 17

1.

1.

Ł

D. 17. Sh. 7

some work was done this summer. He did not know just what it was.

1962 Report to Co. Comm. At Babson Reservoir on Alewife Brook, a very important dam, due to its height and location. There has been some work done on this dam. Because of height of water, it is hard to tell just how much has been done since last report. A boat ramp has been built at easterly end of dam. The walls of spillway are still spalling and disintegrating.

.1964 Dec. 29, P.D.K. & K.M.J. Insps. Spalled portions at gate house and dam have been repaired.

1964 Report to Co. Comm. Spalled portions at gate house and dam have been patched. This should be continued at the walls of the spillway.

1965 April 17, 1967. P.D.K. & K.M.J. Insps. Conditions same.

1966 Report to Co. Comm. Safe and in reasonably good condition.

1968 March 31, 1969 P.D.Killam and J. Fitzgerald. There were two feet of flashboards in the spillway with two inches of water going over. Brush clearing has been done and should be continued. The flashboards and piers should be larger since the aereator unit is not working to keep the entrance to the spillway free of ice.

D. 17 -GLOULESTER 5-5-107-17

7/15/71 N.E WILLINSON

ON BADSON LEVER, BEAND ON ROUTE IZE AT WASHINGTON ST. TALL WASHINGTON ST. MURTH TO POPLAR ST. JUD U.F. TAKE POPLAR ST. 0.50 MI EAST TO FAIT.

GITY UF GLOUCESTER. VATER SUPPLY

FARTH & STUDE EMBAUXIENTS NITH CONCRETE COUSE JALL OVER STEEL SHEET RLWG. (SEE RAND ESGE COUTANDO. 2597 (6 SHEETS) 40.0 ± FT. 61.0 MENN LUD HATER

T. = T.

625.0 FT.

3.25

WATER LEVEL IN RESERVOIR 4.0 IFT BELLIN

40. Acres

TOP OF FLASH DOARDS. SOME DISINTER, LATIN OF SIGEWALL OF SMLLWAY SOUTHEAST END OF FLASH BOARDS ABOUT 3FT. Hund X 3FT. WIDE TING THE WATER 410 3 INCRES DEEP

OFACE WISE DANT IN APACENE EXCELLENT CONTROLOGIES

	APPENDIX C		
SELECTED	PHOTOGRAPHS	OF	PROJECT

Page No.

1

LOCATION PLAN

Site Plan Sketch

PHOTOGRAPHS

ľ

ſ

I

Γ

[

1

[

-

Ľ

Γ

ſ

	No.		<u>Roll</u>	Frame	Page No.
	1.	Overview of crest and upstream slope from left abutment	C16	13	Vi
	2.	Overview of dam from hillside downstream of left abutment	C16	21,22	2
	3.	View of spillway and wooded embankment from elderly housing project	8	24	3
	4.	Upstream paved slope at left end	8	10	3
	5.	Top of embankment and upstream slope right of spillway	C16	18	4
	6.	Deterioration of concrete in pavement on upstream slope, about 55 ft. right of spillway	8	14	4
	7.	Downstream slope left of spillway	8	22	5
	8.	Downstream slope right of spillway	8	20	5
	9.	Spillway approach and log boom	C16	16	6
	10.	Downstream face of spillway	8	21	6
	11.	Training wall left of stilling basin showing 24-in. blow-off pipe and underdrain outlet	C17	6	7
	12.	Training wall right of stilling basin	.8	4	7
• .	13.	Discharge channel downstream of spillway	8	6	8
	14.	Gate house and service bridge	8	8	8










r

2. Overview of dam from hillside downstream of left abutment

1



3. View of spillway and wooded embankment from elderly housing project

.....



4. Upstream paved slope at left end



 Top of embankment and upstream slope right of spillway



 Deterioration of concrete in pavement on upstream slope, about 55 ft. right of spillway



7. Downstream slope left of spillway



8. Downstream slope right of spillway



9. Spillway approach and log boom



10. Downstream face of spillway



11. Training wall left of stilling basin showing 24-in. blow-off pipe and underdrain outlet



12. Training wall right of stilling basin



13. Discharge channel downstream of spillway



14. Gate house and service bridge

APPENDIX D OUTLINE OF DRAINAGE AREA AND HYDRAULIC COMPUTATIONS

OUTLINE	OP	DRA	INAGE	AREA
and the state of the				

Page No.

1

23479

Drainage Area Map

COMPUTATIONS

Size and Hazard Classification Reservoir Surface Area Graph PMF Calculations Spillway Rating Curve Dam Failure Analysis



PAGE 20 # 13 CAMP ORESSER & MCKEE Anonmental Engineers PROJECT_____ DATE CHECKED DATE CHECKED BY DETAIL - COMPUTED BY------------...... ____ fice and Hasard Classification Jie Class Fication ____ Height of Came = 35.8' ____ (25-35.8 < 40) Jorage: _ x 31'x 56 - (<u>56+63-5</u>) x 5.8' Storage = 925 Acre-Feet (50 - 92561000) ______ jize closs i Fication_ s <u>small</u> Hazard Classification Because of elderly housing development, as well as numerous homes and In Water Pumping Station -located immediately downstream of dams initially assume that the racard classification will be high. -----Grainage Area المرادا البرامينيورين المرور المردم وومرا ومرزم موقا الموقات Oroirage Area to suitlet at Eakson Riservoir . 1308water surface Area of Bioson وبارج (2 = (at eley. 48) Later comprises + 3. 1% area____ lat uses Datur Historical Floods ----------____No gaging records available. Test Flood - Ronge of 1/2 PMF to PMF Size-Small - Hazard - High because of downstream account جاند -- -----. · -

4.

I ; 1. 1. ά. 1 . a . i 4. 1.

L.



SER & MCKEE CLIENT PAGE A OF 13 CAMP ORESSER & MCKEE DATE 3 1.11 _ COMPUTED BY -----Probable Maximum Flood Calculations -----Orenage Area = 2.04 sq. mi_ (1308 Acres) * The drainage area is less Than 10 square miles, to try ses TP-147 Method for determining flow. ينيهي الالان المحمد المعربين بلادين الديام الاليمة المايم ميبو فالمواد الاليم يتعييها الم مستحصيتها سيدور سرار والعاد والانتخاص والتباد والالالة Curve Lumber Ostermination Givestor Sui Goup : A - Bockport Joil Group : C From worry intervorers : 'or layer - Loors, sond (snaicie) middle byer-midium + hord coy (auc. bottom byer-bedroch (NOO'down) - Use Hydrologic Joil Grave B. -----Land Use Area Chi Cix Crea Reservor, Pord 35____ 100____ 3500 Horshland 180 98 17640 Homes (1/4 Acre) 13_75_1350 84682 -----Weighted CU's 65 1 Jime of Concentration, Lag times ----------_____ _lag = 10.8 (3+1)0.7 1900 125 - -----...... L= 11,500 FEET · • •

108 NO. 51-1- 2 - ET PAGE FOF 13 CLIENT Haley and Aldrich DATE 911517. PROJECT _ OTTO / DOT 1050. DATE CHECKED /049 COMPUTED BY ... 5.38462 ______ 65____ - 31000 15% 1725' 62' 25% 9775' 74' 5/200 = 12 = , 2015 _ Y = .15% 129 - 11,500 00 (6.38462) - 2.22 hours E= L = 14.7 hours 00= 0,4L = 3.53 Hours A=(p-,23)² 700-20,71 hours_ P-0.85 ----Time Per Loss P Hoss Q (nours Per (incres) Indurs -----______0____ 0 0 _____.07 _____.0003 _____.10 2 **4** _ 1,86 2.80 8... _____3.43 _____ ____4.22 ____ 9 1,10 _____.181_ 10 _____1.50 . ____ / 3. 820 17,11 13.89 .820 20.50 15.21 .952 22.18 16.81 1.000 23.00 17.89 20

La in ned A mining 79-1-1-17 aF 13 CAMP ORESSER & MCKEE CLIENT. JOB NO._ PAGE 6 DATE - -----PROJECT / 'n-w Endur Reison Vigerinie CHECKED BY ----DETAIL. COMPUTED BY . . . Hand · 15 B 11.75-4.5 (3.53) =-4,14 112 1120 community for 0 5 _D____15_ 20. 25 Time (bairs) YAq Time (rairs) _ 00 ____ <u>89</u>____ mement 1.235 Euroff (in.) linches -4,10 0 0 012 10, 0 -----0,61 0 0.4 ACz. 0 0 2.92 0 0.6 0.15 LO3 ... 14 3 6.45 0.15 ADA ___ 94 0.8 75 _1,01 .. . 9,98 11.84 _1103 1.0_ 1103 105-13.51_ -----13 AQ, 261 0.462 174 2.8 17.04 15.8 10, 0.333 50 1.6_ 149 20.57 17.4___ Z- 1410 c 13 19- 483 A (DQ) - 432 (204) DQ - 93.2 DQ 3<u>.5</u>++ 3,83 42+5 _____ ------

a same service as a service servic

I

4

۰.

4.

÷.,

۰.

1

÷ .

1.

Í.

CLIENT Harris and Alerica PAGE 7 F 108 NO 21- 2- 27 CAMP ORESSER & MOKEE PROJECT ATTOPO COME TED DATE CHECKED 10-11-78 Intel Engineers DATE ... DETAH BASSOR Literior CHECKED BY Baller -1-1 COMPLITED BY-...... ------ ... _ Using Hoximum Provoile Flood, Ang Elow Rots Smon - Flat and Castol Cure, Q = 925_6F3/39, mi --- Babon: 1.50x 925= 132825 70% lape Rond: . 70x 54 x925 . 350 cts : 2= 1388+350 = 1738 cfs = Use this Flow, more conserver Lote that 1734 ats is close to 1410 ets SURCHARSE STORAGE DECHARSE <u>STORAGE</u> STOR: <u>5.63×56</u> = 2.9", Op. 1738, (1-29) = 1519 = 13 _ 2.24 x 533 2.34 × 533 5TOR • <u>5113 × 56</u> • 2.7" Are STOR • 2.3 2021533 Qpg• 1738 (1- 23) • <u>1526 : F3</u> elev. 30.3 Joillway Cating CLINE SEROH INSPECTION _____ initialy length = 39,75' Elevotion of spillwoy crest = 55' Garate Danim Ekvation of soillway crest w/ floghboards = 57.15' Elevation of top of dams = 60.30' ____Joillway shace - closely approximates Fig. 5.11 -- in_ King and Brater, Hardbook of Hydroules 0 - Ekvation Head -Q=LLH3k (4.) (cfs) (10001000 _ 0 55___ ____ . . 124 _362 5.6 _ __/_ _ _ 57 _ 2 _ 58 445 59 4 1024 60 1631 5.8 60.8 1788 ____ --------------. - . --------------------

CLIENT Holey and Aldreh JOS NO. 51-1-2- 27 PAGE 3 ~ 7 13 IN Engineers PROJECT LATION CAR CAR DATE CHECKED OTTOM DATE 31.51 ... COMPUTED BY -----. . Spillway Lating Lune ---------_____ 2000-----------1500 - --- ----D(cf5) . . . · •- · -- - - ---. X -ৃত ----500--÷ . õ - D -____ 407 -55. _____50 ____57 ____58.___ 61 60003 -----Elevation (local datum) Guidance For Estimating Counstream Com Follore Hydrogens . این هم مانند بسید به در این این با این و میشونی این با این و میشونی و با این این و میشونی و با این و این و این I. leservoir Storage, 3, in Ack-feet_at_top or dom: 5 = 925 Acre-Fect _____ 2. Qp. - B. Wo T9 16-12 $Q_{D_{1}} = \underbrace{B}_{27} \times (.40 \times \pm 00) \times \underbrace{32.21}_{32} \times \underbrace{35.3^{1}}_{27}^{3/2}$ -**..** . _____QQ, = 86,435 CF3 _____ -----···· ··· ··· ··· · ··· · - ----

PAGE - -FIZ CAMP ORESSER & MOKEE 3.02 nental Engineers 21 DATE_ n, Mass. COMPUTED BY_ dini. 14/1/102 8 ò 100 JAYUL Channel Condo Crund . i 51/2. V 9 5 660000 Do al 2 200015 a 1025 コ at a tool NH H ţ 1 , £ 7 N 22 Q ÷ 0 C Ŋ 9 h Ð ò ĥ à S ų 9 1.0 Z 3 83 η 1 J 0 t 5 θ TH ŝ. 2 2 ž NAN N ---------.... _ ---------

.

٠

• •

. .

.

Å .

i.

1

T

CLIENT in an and Alingian PAGE CAMP ORESSER & MCKEE DETAIL BARSON PASETUDIC CHECKED 10-11-28 In Engineers DATE COMPUTED BY The of mound ----______3.8 -----First Leach - local datums ____ -----(B) A Charriel - store ined_____ _____ - elev. 30.5 1 41 long - - elev 28.33 -----____ ____ ••• · C'24.25.5 ekv.25.5 Q=149 823 51/2 A . A= 2.83 × 4,25' - 12.04 4 10. 9.91 lance - 1.215 9.91 Assume 5-,0001 Q=129 (1215) 4 (,0001) 2 x 12.04 = 10 cF3 @ Ground Aptile at 60" @ pipe, 2000 10 sludge lagoons ____looking_ downstream . (local datern) 367 34.2 33.3 343 31.7 31.3 215 -365 -----25.5 3-20

CLIENT In an and Aldrich JOB NO. 50/28-27 MOJECT 12-22 100-100 DETAIL 22-22 100-100 CHECKED BY PAGE 11 OF 1.3 DATE DIS 72 COMPUTED BY ------ - . . -----. .. 0 pipe Eler. 2 _Head _____ (H.) For total • • • • • (local dat averland - Racrond: 6-25C 25.5 0 0 26.0 0.5 28.0 25 _____ ---- Cope . 0.89 ---------..... 23 --------______ . 109____ 360 8138 10289 12840 --------- For Quer, or -----Ressure Flow - Q - CA VZgh_____ pipe will be ___washed out, -----Pumping state -- ---------Note: Larry full breach flow caun to second reac ------------Elderly Housing Section 0 looking downstream 120 LUS.55 Datums Cross - Section 100 100 -55 -----а^н . ----0 2-1.0 3+50 7-00

CLIENT HALPHAN DIALINA JOB NO. 51-1-2.PT BOJECT 1990- 101 - 50 DATE CHECKED 10-11-20 PAGE 12 01 13 CAMP DRESSER & MOKEE DATE_ 71.51--onmental Engineers CHECKED BY CHECKED BY OETAIL NON, MARA -----. _____ 2 ----. Elevotor Head Almsi) (A) 2 toriuoy 1010/ pices 451 Accord ______ 451_0_ 30 ___ 101 13493 14097 -12.570 _ 11, 3 25..... 43832 Curry Field in: .735 163 43107 63940 Filed in with 329 63111 35 21,3 721 114243 115 154 Jond one goss ______50____ 26.3 185316 186298 scare. 1022 363 ____60 ___ ---------------_____ ____CROSS SELTION RATING CURVE -150,000 1----. ----------. ____ ____ ____ ____ 100,000F \$6,435) 3 ----- <u>-</u> <u>ر</u>----. -----. _ ____ G in in **/**• · ·-----50,000-- ------ - -. ____ ------ -- -. --. - ------------.- .. • ••• • ~- - ... 45 - 37 50 401 - Electron (4. 35 55 60 ص 40

U

CLIENT Halon - - - ----CAMP ORESSER & MCKEE 108 NO. 2-1-2-00 800 PAGE 130713 PROJECT Lintoni Dane into DATE CHECKED 1011-18 nonmental Engineers DETAIL Batton Proprint CHECKED BY Boston, Mess. Any Foringe Arolisis (continued) 4. Qp. . 20, 435 cr3 Elevation = 47.0 (mol) H=2 8-366 + 10665 FH2, Yojume - 101245 x 363 5 43 560 Volume 23.3 Acre-A Qp. 8'2, 435 (1-22.3) 73137 cfs. 2 925 At 78,137 off, Area X section - 9953 AZ (Elex. 46,1) Volume - 9953 × 363.5 - 03.1 Acre-H 43560 V1+12 = 89-8-83,1 = 85.95 Acre-A 2p= 36,435 (1- 25.95) = 79406 cF3 9251 at Elcy, 44.2 (mal) ÷ 1



2 5C3 A z : PRV/FED .
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
 O
z 1500778 DAY MO YR LATITUDE LONGITUDE REPORT DATE WORTH! (WEST) DAY | MO IYE 27209 FED R POPULATION z ۲ ۲ N M O MAINTENANCE FAY SPOFFORD + THORNDIKE C. + P. CONSIRUCTION 4237.4 7040.1 z FRONDAL o AUTHORITY FOR INSPECTION 9 CONSTRUCTION BY €]0157 MA DPH 635 NED 0 NAME OF MPOUNDMENT PUBLIC LAM 92-347 ۲ HYPRAU BOUNDING CAPACITIES HIPPAU MADUNDING CAPACITIES ۲ INVENTORY OF DAMS IN THE UNITED STATES E MEAREST DOWNSTREAM CITY-TOWN-VILLAGE HABSON RESERVUIR 925 OPERATION • ۲ **GLOUCESTER** () INSPECTION DATE DAY | MO | YR NONE **REGULATORY AGENCY** 065EP7A 3 ENGINEERING BY NAME HAHSON RESERVOIR DAM Θ REMARKS ◙ REMARKS 40 ۲ STRUC-AURAC ۲ CONSTRUCTION OF DAM ۲ PURPOSES 0 RIVER OR STREAM **WNO**R DISCHARDE 1790 POPULAR NAME S € 21-CONCHETE CORE HALL + ALORICH, INC. INSPECTION BY TP-MILL HIVER STATE DENTITY DAYSON STATE COUNTY CONCARTS COUNTY DOET Ξ YEAR COMPLETED 1930 OF GLEUCESTER E A) CREAT TYPE WRITH 40 9 OWNER € DESIGN SPILLWAY ັບ E ۲ IRT VED VE ONG ON TYPE OF DAM 0,51 630 PG4FCT Ē EGICINEASIN 43164 90 10 E 1110 A P O N HAS 0

l

l

Ĩ

1306C76

VER/DATE
