

AD-A155 201


NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS
COHASSE BROOK RESERVO. (U) CORPS OF ENGINEERS WALTHAM
MA NEW ENGLAND DIV APR 79


1/1

UNCLASSIFIED

F/G 13/13

NL





MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A

2

AD-A155 201

QUINEBAUG RIVER BASIN
SOUTHBRIDGE, MASSACHUSETTS

COHASSE BROOK RESERVOIR DAM
MA 00694

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM

Copy available to DTIC does not
permit fully legible reproduction

DTIC FILE COPY



DTIC
SELECTED
JUN 20 1985
S D G

DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
WALTHAM, MASS. 02154

APRIL 1979

DISTRIBUTION STATEMENT A
Approved for public release;
Distribution Unlimited

DISCLAIMER NOTICE

THIS DOCUMENT IS BEST QUALITY PRACTICABLE. THE COPY FURNISHED TO DTIC CONTAINED A SIGNIFICANT NUMBER OF PAGES WHICH DO NOT REPRODUCE LEGIBLY.

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER MA 00694	2. GOVT ACCESSION NO. AD-A155201	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Cohasse Brook Reservoir Dam		5. TYPE OF REPORT & PERIOD COVERED INSPECTION REPORT
NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS		6. PERFORMING ORG. REPORT NUMBER
7. AUTHOR(s) U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION		8. CONTRACT OR GRANT NUMBER(s)
9. PERFORMING ORGANIZATION NAME AND ADDRESS		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
11. CONTROLLING OFFICE NAME AND ADDRESS DEPT. OF THE ARMY, CORPS OF ENGINEERS NEW ENGLAND DIVISION, NEED 424 TRAPELO ROAD, WALTHAM, MA. 02254		12. REPORT DATE April 1979
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		13. NUMBER OF PAGES 51
		18. SECURITY CLASS. (of this report) UNCLASSIFIED
		18a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Cover program reads: Phase I Inspection Report, National Dam Inspection Program; however, the official title of the program is: National Program for Inspection of Non-Federal Dams; use cover date for date of report.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) DAMS, INSPECTION, DAM SAFETY, Quinebaug River Basin Southbridge, Massachusetts Cohasse Brook-A tributary of Quinebaug River		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) The dam is a 760 ft. long, 60 ft. high earthfill dam. The dam is in good condition. There are maintenance and monitoring needs that need to be performed to assure the continued performance of the dam. It has a hazard classification of high.		



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
424 TRAPELO ROAD
WALTHAM, MASSACHUSETTS 02154

REPLY TO
ATTENTION OF:
NEDED

JUN 16 1979

Honorable Edward J. King
Governor of the Commonwealth of
Massachusetts
State House
Boston, Massachusetts 02133

Dear Governor King:

I am forwarding to you a copy of the Cochase Brook Reservoir Dam Phase I Inspection Report, which was prepared under the National Program for Inspection of Non-Federal Dams. This report is presented for your use and is based upon a visual inspection, a review of the past performance and a brief hydrological study of the dam. A brief assessment is included at the beginning of the report. I have approved the report and support the findings and recommendations described in Section 7 and ask that you keep me informed of the actions taken to implement them. This follow-up action is a vitally important part of this program.

A copy of this report has been forwarded to the Department of Environmental Quality Engineering, the cooperating agency for the Commonwealth of Massachusetts. In addition, a copy of the report has also been furnished the owner, Southbridge Water Supply Company, 70 Foster Street, Southbridge, Massachusetts 01550.

Copies of this report will be made available to the public, upon request, by this office under the Freedom of Information Act. In the case of this report the release date will be thirty days from the date of this letter.

I wish to take this opportunity to thank you and the Department of Environmental Quality Engineering for your cooperation in carrying out this program.

Sincerely yours,

JOHN P. CHANDLER
Colonel, Corps of Engineers
Division Engineer

Incl
As stated

COHASSE BROOK RESERVOIR

MA 00694

QUINEBAUG RIVER BASIN
SOUTHBRIDGE, MASSACHUSETTS

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION
PROGRAM

Accession For	
NTIS GRA&I	<input checked="" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By _____	
Distribution/	
Availability Codes	
Dist	Avail and/or Special
A/	

NATIONAL DAM INSPECTION
PROGRAM

PHASE I INSPECTION REPORT

BRIEF ASSESSMENT

Identification No.: MA00694

Name of Dam: Cohasse Brook Reservoir

Town: Southbridge

County and State: Worcester County, Massachusetts

Stream: Cohasse Brook - A Tributary of Quinebaug River

Date of Inspection: November 20, 1978

Cohasse Brook Reservoir Dam is a 760-foot long, 60-foot high earthfill dam built in 1968. The zoned embankment has a core of impervious fill and a cutoff trench into bedrock. A 5-foot high dike, 280-feet long is located about 250 feet southeast of the east end of the dam. The spillway is a 40-foot long ungated ogee weir with a rectangular concrete stilling basin with baffle blocks at the toe. The spillway, which is located on the west abutment, has a crest elevation (E1) of 632.0. The stilling basin discharges into a trapezoidal channel lined with stone riprap for a length of about 160 feet. A gate house is located on the upstream face of the dam. Flow through two 16-inch diameter intakes and a 30-inch drain conduit is controlled by gate valves operated from the first floor of the gatehouse. The outlet from the gatehouse is through a 30-inch pipe located at the bottom of the gatehouse. This outlet is also controlled by a gate valve. A 20-inch pump suction line extends from the gatehouse to a pumping station just downstream of the dam on the west side of Cohasse Brook. The 30-inch outlet conduit terminates at a small concrete headwall at the downstream toe in-the middle of the dam.

The dam is in good condition. However, there are maintenance and monitoring needs that must be performed to assure the continued performance of this dam.

COHASSE BROOK RESERVOIR

This conclusion is based on the visual inspection at the site and the available engineering and maintenance data. According to the Corps of Engineers' guidelines for the classification of hazard potential, it has been classified in the "high" hazard category.


The following visible signs of distress were noted at the site: slight seepage at one small area at the downstream toe of the dam, disintegration of some stone riprap in the spillway discharge channel and on the upstream slope of the dam, minor accumulation of brush, logs and stones in the spillway stilling basin, loss of joint filler in the spillway concrete joints, and small trees and brush growing on the dike.

Hydraulic analyses indicate that the spillway, without flashboards, at the dam can discharge a flow of 3,580 cubic feet per second (cfs) with the water surface at El 639.9 which is the low point on the crest of the dike. An outflow test flood (full probable maximum flood or PMF) of 2,600 cfs at El 638.4 will not overtop the dam. The low point on the crest of the dam is El 640.9. With the flashboards in place, the spillway can discharge the outflow test flood without overtopping the dam. However, overtopping of the dike by 0.4 foot will occur.

It is recommended that the Owner accomplish the following: repair erosion at various locations on the embankment, monitor the rate of seepage in the seepage area in the stone gutter at the toe of the dam and take appropriate action if the rate substantially increases, clear accumulated rock and other debris from the spillway stilling basin, clean accumulated logs and bushes from the spillway channel, and remove all trees and brush on the upstream face, downstream face and crest of the dike. The Owner should also continue the systematic program of inspection and maintenance.

COHASSE BROOK RESERVOIR

The above recommendations and remedial measures should be implemented by the Owner within a period of two years after receipt of this Phase I Inspection Report.



A handwritten signature in cursive script, appearing to read "Edward M. Greco".

Edward M. Greco, P.E.
Project Manager
Metcalf & Eddy, Inc.

Connecticut Registration
No. 08365

Approved by:

A handwritten signature in cursive script, appearing to read "Stephen L. Bishop".

Stephen L. Bishop, P.E.
Vice President
Metcalf & Eddy, Inc.

Massachusetts Registration
No. 19703



COHASSE BROOK RESERVOIR

This Phase I Inspection Report on Cohasse Reservoir Dam has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the Recommended Guidelines for Safety Inspection of Dams, and with good engineering judgment and practice, and is hereby submitted for approval.

Joseph A. McElroy

JOSEPH A. MCELROY, MEMBER
Foundation & Materials Branch
Engineering Division

Carney M. Terzian

CARNEY M. TERZIAN, MEMBER
Design Branch
Engineering Division

Joseph W. Finegan, Jr.

JOSEPH W. FINEGAN, JR., CHAIRMAN
Chief, Reservoir Control Center
Water Control Branch
Engineering Division

APPROVAL RECOMMENDED:

Joe B. Fryar

JOE B. FRYAR
Chief, Engineering Division

PREFACE

This report is prepared under guidance contained in Recommended Guidelines for Safety Inspection of Dams, for a Phase I Investigation. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigations, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test Flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general conditions and the downstream damage potential.

COHASSE BROOK RESERVOIR

TABLE OF CONTENTS

	<u>Page</u>
BRIEF ASSESSMENT	
PREFACE	
OVERVIEW PHOTO	
LOCATION MAP	
REPORT	
SECTION 1 - PROJECT INFORMATION	1
1.1 General	1
1.2 Description of Project	1
1.3 Pertinent Data	6
SECTION 2 - ENGINEERING DATA	11
2.1 General	11
2.2 Construction Records	11
2.3 Operating Records	12
2.4 Evaluation	12
SECTION 3 - VISUAL INSPECTION	13
3.1 Findings	13
3.2 Evaluation	16
SECTION 4 - OPERATING PROCEDURES	17
4.1 Procedures	17
4.2 Maintenance of Dam	17
4.3 Maintenance of Operating Facilities	17
4.4 Description of Any Warning System in Effect	17
4.5 Evaluation	18
SECTION 5 - HYDRAULIC/HYDROLOGIC	19
5.1 Evaluation of Features	19

COHASSE BROOK RESERVOIR

TABLE OF CONTENTS (Continued)

	<u>Page</u>
SECTION 6 - STRUCTURAL STABILITY	21
6.1 Evaluation of Structural Stability	21
SECTION 7 - ASSESSMENT, RECOMMENDATIONS, AND REMEDIAL MEASURES	22
7.1 Dam Assessment	22
7.2 Recommendations	23
7.3 Remedial Measures	23
7.4 Alternatives	24

APPENDIXES

APPENDIX A - PERIODIC INSPECTION CHECKLIST
APPENDIX B - PLANS OF DAM AND PREVIOUS INSPECTION REPORTS
APPENDIX C - PHOTOGRAPHS
APPENDIX D - HYDROLOGIC AND HYDRAULIC COMPUTATIONS
APPENDIX E - INFORMATION AS CONTAINED IN THE NATIONAL INVENTORY OF DAMS

COHASSE BROOK RESERVOIR

2.3 Operating Records. Daily operating records are taken by the Superintendent's staff and maintained in the Southbridge office of the Southbridge Water Supply Company.

2.4 Evaluation

- a. Availability. There is considerable engineering data available.
- b. Adequacy. A definitive but limited review was made of the hydraulic, soils, structural and construction data. Therefore, the evaluation of the adequacy of this dam is based on review of this data, available drawings, visual inspection, past performance history and engineering judgment.
- c. Validity. Comparison of the available drawings with the field survey conducted during the Phase I inspection indicates that the information is valid.

SECTION 2

ENGINEERING DATA

2.1 General. There are 25 sheets of drawings available from the design engineer's office, Metcalf & Eddy, Engineers. These include four sheets, dated March, 1966, of preliminary design details and 21 sheets, dated August, 1966, which show details of the proposed construction of Cohasse Brook Reservoir Dam. Three of the latter 21 drawings are included in Appendix B. Specifications, computations and test results relative to the design and construction of the dam were found in the engineer's office. Visual observations during inspection, review of previous inspection reports, review of construction reports, and conversations with the Owner and with personnel from Town, State and County agencies provided the remainder of the data for this evaluation.

We acknowledge the assistance and cooperation of personnel from the Massachusetts Department of Public Works, Messrs. Willis Regan and Raymond Rochford, and personnel of the Massachusetts Department of Environmental Quality Engineering, Division of Waterways, Messrs. John J. Hannon and Joseph Iagallo.

Also, we acknowledge the cooperation and assistance of personnel from the Worcester County Engineer's Office, Messrs. John O'Toole, Joseph Brazauskas, and Mr. Wallace Lindquist - recently retired from County service.

Mr. Chester Spielvogel, Treasurer and Superintendent, Southbridge Water Supply Co., granted permission to enter the property and inspect the dam. Mr. Maurice Contois of his staff provided assistance to access during the inspection.

2.2 Construction Records. There are no as-built drawings available for this dam, only the proposed construction drawings. Records of inspection and tests made during construction were reviewed. A review of these drawings and records indicates the dam generally was built in accordance with the available drawings.

COHASSE BROOK RESERVOIR

(6) Downstream channel: Stilling basin and baffle blocks are concrete. Trapezoidal stone-lined spillway channel at end of stilling basin extends 160 feet downstream; leads to a stream, waterfalls and merging with Cohasse Brook.

- i. Regulating Outlets. The regulating outlet at the dam is a 30-inch diameter prestressed concrete cylinder drain pipe located in the center of the dam. The pipe is about 300 feet long from toe to toe. On the upstream side of the reservoir, there are two 16-inch diameter intake pipes in addition to the lower drain line. The three inlets to the gatehouse are controlled by gate valves on the inside upstream face. Two more valves, located inside the gatehouse on the drain line, allow water to be drained from either the drain line or from the gatehouse. The drain outlet is in the concrete headwall works at the toe of the dam. There is also a sixth gate valve in the gatehouse which allows flow to be diverted through a 20-inch prestressed concrete cylinder pipe to the pumping station. Water is pumped overland to Reservoir No. 4 through a 16-inch cast-iron transmission main. The 30-inch pipe drain has a capacity of 150 cfs (76.5 cfs per square mile). The reservoir surface can be lowered 1 foot in four hours at El 632.0 which is the crest elevation of the spillway. All six gate valves have valve operating mechanisms located on the first floor of the gatehouse.

COHASSE BROOK RESERVOIR

g. Dam

- (1) Type - Main dam: Zoned earthfill
- Dike section: earthfill
- (2) Length - Main dam: 720 feet
- Dike section: 280 feet
- (3) Height - Main dam: (maximum) 60 feet
- Dike section (maximum) 5 feet
- (4) Top width - Main dam: 22 feet
- Dike section: 12 feet
- (5) Side slopes - Main dam: downstream 2:1;
upstream 2.5:1
- Dike section: downstream 2:1;
upstream 2.5:1
- (6) Zoning: Main dam (see Figure B-5)
- (7) Impervious core: Main dam (see Figure B-5)
- (8) Cutoff: Placed at bottom of impervious core.
Narrows down to 8-foot width with vertical
sides from top of bedrock to firm bedrock.
Trench key for most of the length of the
dam.
- (9) Grout curtain: None

h. Spillway

- (1) Type: Ogee crest
- (2) Crest length: 40 feet
- (3) Crest elevation: 632.0 (assumed bench-
mark)
- (4) Gates: None, flashboards 23 inches high
when used in spring.
- (5) Upstream channel: Approach channel is
lined with riprap up to concrete weir.

COHASSE BROOK RESERVOIR

- (5) Recreation pool: N/A
- (6) Spillway crest (ungated): 632.0
- (7) Upstream portal invert diversion tunnel:
N/A
- (8) Stream bed at centerline of dam: 580.0
- (9) Tailwater: 580.5 (water in downstream
channel)

d. Reservoir

- (1) Length of maximum pool: 4,800 feet
- (2) Length of recreation pool: N/A
- (3) Length of flood control pool: N/A

e. Storage (acre-feet)

- (1) Test flood surcharge: 346 at El 638.4
- (2) Top of dam: 1,300
- (3) Flood control pool: N/A
- (4) Recreation pool: N/A
- (5) Spillway crest: 830

f. Reservoir Surface (acres)

- * (1) Top dam: 54
- * (2) Test flood pool: 54
- (3) Flood-control pool: N/A
- (4) Recreation pool: N/A
- (5) Spillway crest: 54

*Based on the assumption that the surface area will not significantly increase with changes in pond elevation from 632.0 to 641.8.

COHASSE BROOK RESERVOIR

30 feet wide at the base and extends for about 160 feet beyond the end of the stilling basin. The channel is lined to the top with stone riprap and contains some brush and logs along the bottom. A small pool of water at the toe of the slope in the center of the main dam at the headwall structure discharges into a separate channel known as Cohasse Brook. The brook with the waterfalls joins with Cohasse Brook approximately 150 feet downstream of the dam. At the time of inspection, the drain gate valve was closed and about a 1/4 inch deep flow was observed at the outlet works pipe. Cohasse Brook flows into Wells Pond. Below Wells Pond, Cohasse Brook flows through the developed residential area of Southbridge.

The spillway, without flashboards, can discharge a maximum of 3,580 cfs when the water surface is at El 639.9 which is the low point on the crest of the dike. The outflow test flood (the PMF) is 2,600 cfs at water surface El 638.4, and will not overtop the dam or dike. With flashboards in place, the spillway can discharge the outflow test flood without overtopping the dam. However, overtopping of the dike by 0.4 foot will occur.

The maximum recorded flood level at the dam, which occurred in 1973, was El 634.2 which corresponds to 3 inches over the top of the flashboards in 1973.

- c. Elevation (feet above Mean Sea Level (MSL)).
A benchmark was established at El 632.0 on the crest of the spillway. This elevation was estimated from a United States Geological Survey (USGS) topographic map.

- (1) Top dam - Main dam: 640.9 to 641.8
Dike section: 639.9 to 640.1
- (2) Test flood pool: 638.4
- (3) Design surcharge (original design):
Unknown
- (4) Full flood control pool: Not Applicable
(N/A)

COHASSE BROOK RESERVOIR

- i. Normal Operating Procedures. Under normal conditions, the gate valves in the outlet structure are closed. Occasionally, when the water level rises over the spillway, the outlet drain valves are opened to discharge water from the bottom of the reservoir. The intake gate valves are normally opened. When water is needed in the lower reservoirs in the Southbridge system, the gate valve from the pump suction line is opened and the water is pumped to Reservoir No. 4 through a 16-inch pipeline. During pumping operations, the water passes through screens located in the gatehouse. In 1978, the pump was operated on about five separate occasions to verify it was in operating condition. The combined pump operating time for last year was less than one day. All gate valves in the outlet structure are operable.

The spillway for Cohasse Dam is ungated. At the time of inspection, flashboard rods were in place but without flashboards. The flashboards that are used are reportedly 23 inches high. The flashboards are usually placed in the spring and removed in the fall, typically from April through August.

1.3 Pertinent Data

- a. Drainage Area. The drainage area for Cohasse Brook Reservoir is estimated to be 1,254 acres (1.96 square miles). Cohasse Brook flows from the south through undeveloped woodland and swamp. There is no residential development on the reservoir and only a few homes are located in the drainage area.
- b. Discharge at the Dam Site. Uncontrolled discharge at the dam site flows over the 40 foot long concrete ogee weir at the west end of the dam, through a concrete stilling basin with baffle blocks and into a stone-lined trapezoidal channel. The channel then discharges at a right angle into a unnamed brook with a waterfall which merges downstream with Cohasse Brook. The stilling basin is rectangular and terminates with two rows of concrete baffle blocks at the downstream end. The channel is

COHASSE BROOK RESERVOIR

- d. Hazard Classification. Downstream of the dam is Wells Pond with a dam. The shoreline area of Wells Pond is undeveloped. The Cohasse Country Club is too high to be affected in the event of failure of the dam. The developed portion of the Town of Southbridge is downstream of Wells Pond. The brook passes for more than 1 mile through dense residential areas before reaching the Quinebaug River. In the event of overtopping and complete failure of the dam, more than a few lives could be lost and excessive property damage could occur. Accordingly, the dam has been classified in the "high" hazard category.
- e. Ownership. The dam and dike are located on property owned by the Southbridge Water Supply Company, 70 Foster Street, Southbridge, Massachusetts 01550. Mr. Chester Spielvogel, Treasurer and Superintendent (617-764-3207) granted permission to enter the property and inspect the dam and dike. The dam and dike have been owned by the Southbridge Water Supply Company since their construction in 1968.
- f. Operators. The Southbridge Water Supply Company employs a full time caretaker who serves as the operator of the dam. Access to the site is restricted by a chainlink fence with a locked road gate and a second locked cable across the entrance road.
- g. Purpose of the Dam. The dam was built to provide, and presently serves as, a water supply to the Town of Southbridge.
- h. Design and Construction History. This dam was constructed in 1967 and 1968. A complete set of drawings, dated 1966, are on file at the office of Metcalf & Eddy. Construction reports are also available in the same office. The only inspection report on file is dated February 12, 1973, and described the dam and dike as being in excellent condition (see Appendix B). At that time, the water level was about 9 feet below the top of the dam and there was no evidence of seepage.

COHASSE BROOK RESERVOIR

is reduced to a 24-inch diameter line at the same elevation through the gatehouse and contains three gate valves. The three valves allow drainage of the reservoir and/or gatehouse. The size of the drain line increases to 30 inches just downstream of the gatehouse and continues to the concrete headwall located at the toe of the downstream slope near the center of the main embankment. The invert of the outlet pipe is at El 580.6. The outlet channel is lined with stone riprap for a distance of about 160 feet downstream of the headwall structure. This channel is also Cohasse Brook. The sixth valve in the gatehouse structure can divert flow to a 20-inch diameter pump suction line that extends to a pumping station just downstream of the dam on the west side of Cohasse Brook. The center-line elevation of this line is 583.08. Screens are installed in the gatehouse to prevent fish and debris from entering the distribution system. A water level gage located in the gatehouse indicated the water level was about 11 feet below the first floor slab.

The pumping station is a one-story high concrete block structure with brick facing and a reinforced concrete substructure. One pump is located in the basement. Water can be pumped from Cohasse Reservoir to Reservoir No. 4 through a 16-inch line.

A dike, which is located southeast of the dam, is about 280 feet long and has a maximum height of 5 feet. The dike is an earthfill embankment. The upstream slope is 2.5:1 and is covered with riprap and some small trees, brush and logs. The downstream slope is 2:1 and is covered with grass and brush. About 50 feet north of the right abutment, bedrock is exposed near the downstream toe. The crest of the dike varies from El 639.9 to 640.1.

- c. Size Classification. Cohasse Brook Reservoir Dam is classified in the "intermediate" category since it has a maximum height of 60 feet and a maximum storage capacity of 1,300 acre-feet.

COHASSE BROOK RESERVOIR

The concrete spillway consists of two vertical training walls containing a concrete ogee crest weir and concrete stilling basin with baffle blocks. The crest of the spillway is at El 632.0. There are six flashboard rods about 2 feet high on the spillway crest. The side walls of the spillway are 9 feet above the crest. There are seven weep holes exposed at the base of each training wall. The length of the concrete section from the upstream edge of the spillway crest to the end of the stilling basin is 82.8 feet. An underdrain system beneath the basin concrete floor slab consists of 8-inch vitrified clay open joint pipe placed in a layer of pervious crushed stone overlying bedrock. The pipe drains to an 8-inch cast-iron pipe that discharges in the stone gutter about midheight on the intersection between the dam and left abutment. The spillway discharges into a channel that extends about 160 feet down to a brook which cascades over a waterfall and then flows into Cohasse Brook. The spillway channel is trapezoidal shaped, 30 feet wide at the bottom with side slopes of 1.5:1. The channel is lined with riprap for the full width and height. A 40-foot long prestressed concrete bridge spans the spillway channel. At each end of the bridge, a 10-foot long approach slab is supported on the top of the training wall and adjacent backfill.

The gatehouse is located near the center of the dam (see Figure B-1). It is constructed of reinforced concrete except the superstructure which is concrete block with brick facing. It contains six operable gate valves with valve stems extending to six operating mechanisms mounted on the first floor. On the upstream side of the gatehouse there are three conduits indicated on the drawings extending into the reservoir (see Figures B-6 and B-7). These conduits consist of a 30-inch drain with a centerline El 583.25, a 16-inch intake with centerline El 590.50, and a second 16-inch intake with centerline El 618.25. A gate valve is located at each end of the 16-inch intake line just inside the gatehouse. These valves allow water intake from the reservoir at different levels. The 30-inch drain line

COHASSE BROOK RESERVOIR

Town of Southbridge, Worcester County, Massachusetts (see Location Map and Drainage Area Map).

- b. Description of Dam and Appurtenances. Cohasse Brook Reservoir Dam is an earthfill dam with a maximum height of 60 feet (see Plan of Dam and Sections, Figures B-1 through B-7). The dam and spillway are about 760 feet long and the spillway is 40 feet wide. The embankment is founded on bedrock with a cutoff trench key 8 feet wide extending to variable depths to firm bedrock along some of the dam. The zoned embankment consists entirely of earth fill with a central impervious core 8 feet wide at the top increasing in width at the base. Adjacent to both sides of the impervious core is random pervious fill which in turn is covered on both the upstream and downstream faces to El 632.0 with pervious fill zones. According to the drawings, organic and other deleterious soil was stripped at the foundation level within the random pervious and pervious fill zones. A 2-foot thick screened gravel drainage blanket extends for the full width at the base of the downstream pervious fill zone. Drawings indicate (see Figure B-4) that there is an 8-inch vitrified clay pipe with open joints within the drainage blanket along the toe of the entire length of the main embankment. This underdrain pipe discharges adjacent to the two side walls of the outlet structure near the center of the dam. The crest of the dam is about 22 feet wide and the elevation varies from 640.9 to 641.8. A paved road is located on the crest, with an access bridge spanning the spillway on the west abutment. The upstream slope is 2.5:1 and is covered with riprap. The downstream slope is 2:1 and is covered with grass. An asphalt paved road descends along the downstream slope resulting in a 20-foot wide bern. A stone-lined gutter is located along the downstream intersection between the dam and natural ground, and along the uphill side of the road on the downstream slope of the dam. A slight knoll near the east end of the dam serves as a turning point for the embankment which angles off to the southeast. This latter portion of the dam has a maximum height of only 4 feet.

COHASSE BROOK RESERVOIR

NATIONAL DAM INSPECTION
PROGRAM

PHASE I INSPECTION REPORT

COHASSE BROOK RESERVOIR

SECTION 1

PROJECT INFORMATION


1.1 General

- a. Authority. Public Law 92-367, August 8, 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a national program of dam inspection throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region. Metcalf & Eddy, Inc. has been retained by the New England Division to inspect and report on selected dams in the State of Massachusetts. Contract No. DACW 33-79-C-0016, dated November 28, 1978, has been assigned by the Corps of Engineers for this work.
- b. Purpose:
- (1) Perform technical inspection and evaluation of non-Federal dams to identify conditions which threaten the public safety and thus permit correction in a timely manner by non-Federal interests.
 - (2) Encourage and assist the States to initiate quickly effective dam safety programs for non-Federal dams.
 - (3) Update, verify and complete the National Inventory of Dams.

1.2 Description of Project

- a. Location. The dam is located on Cohasse Brook, a tributary of the Quinebaug River, in the

COHASSE BROOK RESERVOIR



LOCATION MAP – COHASSET BROOK RESERVOIR DAM

**OVERVIEW
COHASSE BROOK RESERVOIR DAM
SOUTHBRIDGE, MASSACHUSETTS**



SECTION 3
VISUAL INSPECTION

3.1 Findings

- a. General. The Phase I Inspection of the dam and dike at Cohasse Brook Reservoir was performed on November 20, 1978. A copy of the inspection check list is in Appendix A. A previous inspection of this dam was made in 1973 by the Massachusetts Department of Public Works, and a copy of that report is included in Appendix B.

- b. Dam. In general, the dam is in good condition. Minor seepage was observed in several areas. About 1 gpm of water was observed flowing from a side drain located about midheight of the stone gutter adjacent to the left abutment. This location corresponds with the drain which discharges from the spillway channel underdrain system. A small amount of water was observed flowing in the stone-lined gutter at the toe of the dam about 50 feet east of the outlet works. Water was also observed flowing from an 8-inch pipe about 60 feet north of the same outlet works. There is a small pool in Cohasse Brook in the immediate vicinity of the concrete outlet works at the downstream toe. The area is covered with riprap adjacent to the outlet walls. The exposed ends of two 8-inch clay tile toe drains were broken. These drains are located on each side of the concrete training walls. About 0.1 gpm flow was observed from the west drain and about 1 gpm from the east drain. Although the base of the riprap in this area was partially submerged, seepage was observed through the riprap on both sides of the outlet works. A flow of about 1 gpm was estimated discharging from each side. Seepage was also observed through some large stones piled in the area immediately north of the pumping station pavement and on the east steep stone face abutment immediately north of the dam. The downstream face is covered with a growth of grass and the upstream slope is covered with a

COHASSE BROOK RESERVOIR

layer of riprap. Some weathered or disintegrated stones were found throughout the exposed riprap.

There is a longitudinal crack in the asphalt pavement on the crest along most of the length of the main dam. It varies in width from hair-line to about 0.6 inch and is located about 2 feet or so in from the downstream edge of the pavement. Grass is growing through some of the wider cracks. There is no perceptible differential settlement across the cracks, and the uniform location of these cracks suggests a construction paving joint. There is also a transverse crack about 0.6 inch wide across the asphalt pavement. This crack is located about 15 feet east of the east bridge abutment. A transverse crack was observed, in the pavement at each end of the spillway access bridge, corresponding with the ends of the concrete slab. There is a slight depression of the pavement in front of the gatehouse on the north half of the crest. There is also some erosion of the north edge of the roadway shoulder from the middle of the dam to the left abutment, and along some of the edge of the road and lined gutter on the downstream berm of the dam.

In general, the dike is in fair condition. The dike is partially covered with brush and trees. The upstream slope of the dike is protected by riprap, however, some stones have disintegrated. The reservoir level was several feet below the upstream toe of the dike. Therefore, there was no opportunity to determine if there was any seepage through the dike.

- c. Appurtenant Structures. The concrete in the spillway channel and bridge is in good condition. In general, there is slight spalling of the concrete in the channel bottom up to the high water mark, including the surface of the ogee weir. There is one large surface spall at the top of the east training wall next to the south edge of the bridge deck. There is minor cracking on the top of the west training wall. Some expansion joint filler material is

COHASSE BROOK RESERVOIR

missing in the training walls and in the two vertical joints exposed in the ogee weir. Leakage was observed discharging from the downstream vertical joints. At the time of the inspection, a very small amount of water was flowing over the spillway. Although flashboards were not in place, there are six rods on the crest which allow flashboards to be placed to a height of 23 inches above the crest. There are several stones, up to 2 feet in size, in the bottom of the stilling basin. Two rows of concrete baffle blocks are located at the downstream end of the stilling basin. A few small logs, leaves and debris have collected in the stilling basin. The seven drainholes at the base of each training wall were dry but show some efflorescence. Minor efflorescence has also occurred near the bottom of the east training wall. Some erosion of soil has occurred in the northwest corner next to the bridge and training wall. Some water was observed flowing from the outlet pipe for the spillway underdrain system. The spillway channel is stone lined and is located immediately downstream of the concrete stilling basin. The spillway channel is relatively clear except for a few bushes and logs in the bottom of the channel. Some of the stone riprap has disintegrated, particularly on the west slope of the channel. The concrete access bridge spans the full width of the channel. The channel training walls also serve as abutments for the bridge. There are four horizontal weep holes, two at each end of the bridge, that penetrate the bridge curbing.

The gatehouse structure is in good condition. The inlets and six gate valves are not visible since the structure was filled with water to an elevation of about 11 feet below the first floor. The exterior concrete has some spalling below the high water mark. The visible metal braces used for support of the valve stem extensions inside the gatehouse are rusted. Valve operating mechanisms are mounted on the first floor. All gate valves are reported operable. There is no cracking or spalling of the superstructure brick exterior.

COHASSE BROOK RESERVOIR

The outlet headwall is in good condition. The outlet from the gatehouse is a 30-inch diameter prestressed concrete cylinder drain pipe which is recessed into a vertical concrete headwall which extends into two vertical concrete training walls. There is slight spalling of the concrete on the downstream edge of the training walls of the outlet structure at the present water level. At the time of inspection, water, about 1/4 inch deep, was flowing out of the drain pipe at a rate estimated to be about 1 gpm.

The pumping station is in good condition. There is one pump in the structure with space and piping available for a second pump. The pump was last operated in August, 1978, when new packings were installed.

- d. Reservoir Area. There is no residential, commercial, or industrial development around the shore of Cohasse Brook Reservoir. The area is heavily wooded and hilly with slopes averaging 3 percent. The shoreline is well maintained.
- e. Downstream Channel. The discharge from the spillway channel flows into a unnamed stream then over a waterfall and into Cohasse Brook. Cohasse Brook then flows into Wells Pond and then on through the developed portion of the Town of Southbridge.

3.2. Evaluation. Although the dam appears to be in good condition, there are several deficiencies which require attention. Recommended measures to improve these conditions are included in Section 7.

COHASSE BROOK RESERVOIR

SECTION 4

OPERATING PROCEDURES

- 4.1 Procedures. Under normal conditions, the 30-inch drain valve and the pump suction valve are closed. When water is in demand in Reservoir No. 4, the pump suction valve is opened and water is pumped into the 16-inch diameter cast-iron transmission main. In 1978, the pump was operated on about five separate occasions to determine that the pump was operable. This amounted to less than a total combined pump operating time of 24 hours. All six valves in the gate house are operable. Flashboards are placed on the spillway crest each year during spring and then removed in the fall. Occasionally, when the reservoir water level rises over the spillway or flashboards, the 30-inch outlet drain valve is opened to discharge water at the bottom of the reservoir into Cohasse Brook.
- 4.2 Maintenance of Dam. The dam is generally well maintained. The caretaker reportedly visits the dam each and every day of the year and briefly inspects the dam during each visit. Repair work is done as the need arises. The grass on the downstream slope is cut several times during the summer.
- 4.3 Maintenance of Operating Facilities. The operating facilities are well maintained, as evidenced by the condition of the spillway, gatehouse, outlet works and pumping station. The valves and stems were inspected during the summer of 1978 when the gate house was drained. Flow over the spillway is controlled only to the extent that flashboards are used. The facilities are also checked by the caretaker during his daily visit.
- 4.4 Description of Any Warning System in Effect. There is a warning system in effect at the dam. However, there are no written procedures for the warning system. We understand through verbal discussion that the system consists of a 24-hour radio call system between the caretaker's truck, the office of the Southbridge Water Supply Company and the home of the superintendent. The superintendent can be contacted by the public at his home

COHASSE BROOK RESERVOIR

by telephone. In the event of an emergency, the superintendent can then call local officials. The amount of rainfall is recorded every 24 hours. When the amount exceeds 1/2 inch, the gage is read every six hours. The dam is also inspected concurrently at least every six hours during such inclement weather conditions. If water level in the reservoir is relatively high during a hurricane or hurricane warning, the reservoir level may be lowered by opening the drain outlet valves.

- 4.5 Evaluation. An operating program has been developed for establishing a constant supply of water to the Southbridge Water Supply Company. Some additional maintenance should be implemented and the emergency warning procedures should be placed in writing, considering that the dam is in the "high" hazard category. Recommendations for a more thorough maintenance program are included in Section 7.3.

SECTION 5

HYDRAULIC/HYDROLOGIC

5.1 Evaluation of Features

- a. General. Cohasse Brook Reservoir Dam is a 60-foot high-earthfill dam built in 1968. The zoned embankment has a core of impervious fill. A 5-foot high dike, 240 feet long, is located southeast of the dam. The spillway is a 40-foot long, ungated ogee weir with a rectangular concrete stilling basin at the toe.

The dam was built to serve as storage for a water supply to the Town of Southbridge. It is located on Cohasse Brook.

- b. Design Data. Hydraulic computations are available at the design engineer's office. A review of those computations reveals the design crest elevation of the weir was 631.6 (design drawings show 632.0), the maximum discharge rate was 1,600 cfs, with a water surface at El 636.7.
- c. Experience Data. Daily records of air temperature, water level and rainfall are maintained by the Southbridge Water Supply Company. When rainfall exceeds 1/2 inch, the rain gage is read every six hours. The maximum recorded level in the reservoir was 26 inches above the spillway or El 634.2 when flashboards, 23 inches high, were in place. Since the lowest point on the dike is 639.9, there has been no overtopping of either the dike or dam.
- d. Visual Observations. Discharge from Cohasse Brook Reservoir is over the spillway located on the west end of the main dam. The spillway is a 40-foot long ogee-type weir.

The concrete spillway is in good condition and includes two rows of concrete baffle blocks at the downstream end.

COHASSE BROOK RESERVOIR

- e. Test Flood Analysis. The PMF rate was determined to be 1,550 cfs per square mile. This calculation is based on the average drainage area slope of 3 percent, the pond-plus-swamp area to drainage area ratio of 12 percent, and the U.S. Army Corps of Engineers' guide curves for Maximum Probable Flood Peak Flow Rates (dated December, 1977). Applying the full PMF to the 1.96 square miles of drainage area results in a calculated peak flood of 3,100 cfs as the inflow test flood. By adjusting the inflow test flood for surcharge storage, the maximum discharge rate was established as 2,600 cfs, with a water surface at El 638.4.

Hydraulic analyses indicate that the spillway without flashboards can discharge a total of 3,580 cfs at El-639.9 which is the low point on the top of the dike. Therefore, the spillway can discharge the full test flood without overtopping the dam or dike. The low point on the top of the dam is at El 640.9. There will be a freeboard of about 1.5 feet on the dike and about 2.3 feet on the dam, assuming wave action is negligible. With the flashboards in place, the spillway can discharge the outflow test flood without overtopping the dam. However overtopping of the dike by 0.4 foot will occur.

- f. Dam Failure Analysis. The hydraulic computations indicate the maximum calculated impounded water level is 638.4, or 2.3 feet below the crest of the dam. In the event the dam fails under peak outflow conditions, the initial outflow would be in the order of 61,900 cfs, including 2,600 cfs through the spillway. Failure of the dam would produce a flood wave 27 feet high at a point 6,500 feet downstream of the dam, as estimated using the Corps of Engineers criteria. This distance corresponds to the developed area of the Town of Southbridge.

Downstream of the dam is Wells Pond with a dam, and the developed area of the Town of Southbridge downstream of Wells Pond. Since the latter is a highly developed residential area, a large number of homes, in excess of 10, would be impacted by the calculated flood wave.

SECTION 6

STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability

- a. Visual Observations. The evaluation of the structural stability of the dam is based on the visual inspection conducted on November 20, 1978, and review of the plans and data as referenced in Section 2, Engineering Data. As discussed in Section 3, Visual Inspection, the embankment of the dam is generally in good condition.

Based on these observations, the embankment of the dam is not a potential hazard.

- b. Design and Construction Data. The information listed in Section 2, Engineering Data, represents the available design and construction data. Design computations for the dam were located. Limited information exists on the type, shear strength and permeability of the soil and/or rock materials.
- c. Operating Records. There is no evidence that any type of instrumentation has ever existed at Cohasse Brook Reservoir Dam except for one observation well located northeast of the pumping station, well beyond the toe of the dam. The performance of the spillway and dam under prior loading can only be inferred from physical evidence at the site.
- d. Post-construction Changes. There are no recorded changes after 1968.
- e. Seismic Stability. The dam is located in Seismic Zone No. 2 and in accordance with Phase I "Recommended Guidelines" does not warrant seismic analyses.

COHASSE BROOK RESERVOIR

SECTION 7

ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES

7.1 Dam Assessment

- a. Condition. Based upon a review of available drawings, the visual inspection of the site and limited operational or maintenance information, there are maintenance and monitoring needs that must be performed to assure the continued performance of this dam. Generally, the dam is considered to be in good condition. However, several signs of distress were observed at the site: slight settlement of the downstream side of the crest of the dam in front of the gatehouse, disintegration of some stone riprap on the upstream face of the dam and spillway channel, accumulation of brush, logs and stones in the spillway stilling basin, accumulation of brush and logs in the spillway channel, loss of joint filler material on the ogee spillway crest and the vertical spillway training walls, seepage from the lined stone gutter east of the outlet works, and a growth of trees and brush on the dike.

Hydraulic analyses indicate that the spillway, without flashboards, can discharge a flow of 3,580 cfs with the water surface at El 639.9 which is the low point on the crest of the dike. The low point on the crest of the dam is El 640.9. An-outflow test flood at 2,600 cfs (full PMF) will not overtop the dam or dike. With the flashboards in place, the spillway can discharge the outflow test flood without overtopping the dam. However, overtopping of the dike by 0.4 foot will occur.

- b. Adequacy of Information. The detailed design and construction data did allow for a definitive review. The evaluation of the adequacy of this dam and dike is based on review of available drawings, design computations, construction reports, visual inspection, past performance history and engineering judgment.

COHASSE BROOK RESERVOIR

- c. Urgency. The recommendations and remedial measures outlined below should be implemented by the Owner within two years after receipt of this Phase I Inspection Report.
- d. Need for Additional Investigation. No additional investigations to further assess the dam are recommended at this time.

7.2 Recommendations. The recommendations on repairs and maintenance procedures are outlined below under Section 7.3, Remedial Measures.

7.3 Remedial Measures

- a. Operating and Maintenance Procedures. The dam and spillway are adequately maintained. However, it is recommended that the Owner accomplish the following:
 - (1) monitor the seepage in the stone gutter at the toe of the dam, located about 50 feet east of the concrete outlet works. If the seepage rate substantially increases with time, appropriate action may then be necessary;
 - (2) fill in small settled area with asphalt on crest of dam downstream of gatehouse;
 - (3) repair and replace joint filler material on spillway crest and in spillway training walls;
 - (4) clean accumulated rock and other debris from the spillway stilling basin;
 - (5) clean accumulated logs and bushes from the spillway channel;
 - (6) fill in eroded areas along edge of crest of dam and at northwest corner of bridge and spillway training wall, cover with loam and then seed;
 - (7) repair or replace missing or dislodged stone in stone gutter along road located on downstream face of dam;


COHASSE BROOK RESERVOIR

- (8) remove all trees and brush from the upstream face, downstream face and crest of the dike;
- (9) replace disintegrated stone riprap on the upstream face of the dam and spillway discharge channel;
- (10) institute a written definite plan for surveillance and a warning system during periods of unusually heavy rains and/or runoff. The existing system is not described in writing. The flashboards should be removed prior to periods of unusually heavy rains and/or runoff.
- (11) continue the systematic program of maintenance inspections. As a minimum, the inspection program should consist of a monthly inspection of the dam and appurtenances and be supplemented by additional inspections during and after severe storms. All repairs and maintenance should be undertaken in compliance with all applicable State regulations;
- (12) technical inspection of this dam should be continued on a biennial frequency.


7.4 Alternatives. There are no alternatives.

APPENDIX A
PERIODIC INSPECTION
CHECKLIST

COHASSE BROOK RESERVOIR



TRANSVERSE SECTION KEEN TO R.M. EDGE ROCK




NOTE: DRAWING HAS BEEN REDUCED FOR THIS REPORT.

SCALE OF DAM 1/4" = 10'

SCALE FOR REEF 1/8" = 10'



SCALE FOR FOUNDATION 1/16" = 10'

NO.	DATE	REVISION
1	1910	DESIGN
2	1911	CONSTRUCTION
3	1912	REVISION
4	1913	REVISION
5	1914	REVISION
6	1915	REVISION
7	1916	REVISION
8	1917	REVISION
9	1918	REVISION
10	1919	REVISION
11	1920	REVISION
12	1921	REVISION
13	1922	REVISION
14	1923	REVISION
15	1924	REVISION
16	1925	REVISION
17	1926	REVISION
18	1927	REVISION
19	1928	REVISION
20	1929	REVISION
21	1930	REVISION
22	1931	REVISION
23	1932	REVISION
24	1933	REVISION
25	1934	REVISION
26	1935	REVISION
27	1936	REVISION
28	1937	REVISION
29	1938	REVISION
30	1939	REVISION
31	1940	REVISION
32	1941	REVISION
33	1942	REVISION
34	1943	REVISION
35	1944	REVISION
36	1945	REVISION
37	1946	REVISION
38	1947	REVISION
39	1948	REVISION
40	1949	REVISION
41	1950	REVISION
42	1951	REVISION
43	1952	REVISION
44	1953	REVISION
45	1954	REVISION
46	1955	REVISION
47	1956	REVISION
48	1957	REVISION
49	1958	REVISION
50	1959	REVISION
51	1960	REVISION
52	1961	REVISION
53	1962	REVISION
54	1963	REVISION
55	1964	REVISION
56	1965	REVISION
57	1966	REVISION
58	1967	REVISION
59	1968	REVISION
60	1969	REVISION
61	1970	REVISION
62	1971	REVISION
63	1972	REVISION
64	1973	REVISION
65	1974	REVISION
66	1975	REVISION
67	1976	REVISION
68	1977	REVISION
69	1978	REVISION
70	1979	REVISION
71	1980	REVISION
72	1981	REVISION
73	1982	REVISION
74	1983	REVISION
75	1984	REVISION
76	1985	REVISION
77	1986	REVISION
78	1987	REVISION
79	1988	REVISION
80	1989	REVISION
81	1990	REVISION
82	1991	REVISION
83	1992	REVISION
84	1993	REVISION
85	1994	REVISION
86	1995	REVISION
87	1996	REVISION
88	1997	REVISION
89	1998	REVISION
90	1999	REVISION
91	2000	REVISION
92	2001	REVISION
93	2002	REVISION
94	2003	REVISION
95	2004	REVISION
96	2005	REVISION
97	2006	REVISION
98	2007	REVISION
99	2008	REVISION
100	2009	REVISION
101	2010	REVISION
102	2011	REVISION
103	2012	REVISION
104	2013	REVISION
105	2014	REVISION
106	2015	REVISION
107	2016	REVISION
108	2017	REVISION
109	2018	REVISION
110	2019	REVISION
111	2020	REVISION
112	2021	REVISION
113	2022	REVISION
114	2023	REVISION
115	2024	REVISION
116	2025	REVISION
117	2026	REVISION
118	2027	REVISION
119	2028	REVISION
120	2029	REVISION
121	2030	REVISION
122	2031	REVISION
123	2032	REVISION
124	2033	REVISION
125	2034	REVISION
126	2035	REVISION
127	2036	REVISION
128	2037	REVISION
129	2038	REVISION
130	2039	REVISION
131	2040	REVISION
132	2041	REVISION
133	2042	REVISION
134	2043	REVISION
135	2044	REVISION
136	2045	REVISION
137	2046	REVISION
138	2047	REVISION
139	2048	REVISION
140	2049	REVISION
141	2050	REVISION
142	2051	REVISION
143	2052	REVISION
144	2053	REVISION
145	2054	REVISION
146	2055	REVISION
147	2056	REVISION
148	2057	REVISION
149	2058	REVISION
150	2059	REVISION
151	2060	REVISION
152	2061	REVISION
153	2062	REVISION
154	2063	REVISION
155	2064	REVISION
156	2065	REVISION
157	2066	REVISION
158	2067	REVISION
159	2068	REVISION
160	2069	REVISION
161	2070	REVISION
162	2071	REVISION
163	2072	REVISION
164	2073	REVISION
165	2074	REVISION
166	2075	REVISION
167	2076	REVISION
168	2077	REVISION
169	2078	REVISION
170	2079	REVISION
171	2080	REVISION
172	2081	REVISION
173	2082	REVISION
174	2083	REVISION
175	2084	REVISION
176	2085	REVISION
177	2086	REVISION
178	2087	REVISION
179	2088	REVISION
180	2089	REVISION
181	2090	REVISION
182	2091	REVISION
183	2092	REVISION
184	2093	REVISION
185	2094	REVISION
186	2095	REVISION
187	2096	REVISION
188	2097	REVISION
189	2098	REVISION
190	2099	REVISION
191	2100	REVISION
192	2101	REVISION
193	2102	REVISION
194	2103	REVISION
195	2104	REVISION
196	2105	REVISION
197	2106	REVISION
198	2107	REVISION
199	2108	REVISION
200	2109	REVISION
201	2110	REVISION
202	2111	REVISION
203	2112	REVISION
204	2113	REVISION
205	2114	REVISION
206	2115	REVISION
207	2116	REVISION
208	2117	REVISION
209	2118	REVISION
210	2119	REVISION
211	2120	REVISION
212	2121	REVISION
213	2122	REVISION
214	2123	REVISION
215	2124	REVISION
216	2125	REVISION
217	2126	REVISION
218	2127	REVISION
219	2128	REVISION
220	2129	REVISION
221	2130	REVISION
222	2131	REVISION
223	2132	REVISION
224	2133	REVISION
225	2134	REVISION
226	2135	REVISION
227	2136	REVISION
228	2137	REVISION
229	2138	REVISION
230	2139	REVISION
231	2140	REVISION
232	2141	REVISION
233	2142	REVISION
234	2143	REVISION
235	2144	REVISION
236	2145	REVISION
237	2146	REVISION
238	2147	REVISION
239	2148	REVISION
240	2149	REVISION
241	2150	REVISION
242	2151	REVISION
243	2152	REVISION
244	2153	REVISION
245	2154	REVISION
246	2155	REVISION
247	2156	REVISION
248	2157	REVISION
249	2158	REVISION
250	2159	REVISION
251	2160	REVISION
252	2161	REVISION
253	2162	REVISION
254	2163	REVISION
255	2164	REVISION
256	2165	REVISION
257	2166	REVISION
258	2167	REVISION
259	2168	REVISION
260	2169	REVISION
261	2170	REVISION
262	2171	REVISION
263	2172	REVISION
264	2173	REVISION
265	2174	REVISION
266	2175	REVISION
267	2176	REVISION
268	2177	REVISION
269	2178	REVISION
270	2179	REVISION
271	2180	REVISION
272	2181	REVISION
273	2182	REVISION
274	2183	REVISION
275	2184	REVISION
276	2185	REVISION
277	2186	REVISION
278	2187	REVISION
279	2188	REVISION
280	2189	REVISION
281	2190	REVISION
282	2191	REVISION
283	2192	REVISION
284	2193	REVISION
285	2194	REVISION
286	2195	REVISION
287	2196	REVISION
288	2197	REVISION
289	2198	REVISION
290	2199	REVISION
291	2200	REVISION
292	2201	REVISION
293	2202	REVISION
294	2203	REVISION
295	2204	REVISION
296	2205	REVISION
297	2206	REVISION
298	2207	REVISION
299	2208	REVISION
300	2209	REVISION
301	2210	REVISION
302	2211	REVISION
303	2212	REVISION
304	2213	REVISION
305	2214	REVISION
306	2215	REVISION
307	2216	REVISION
308	2217	REVISION
309	2218	REVISION
310	2219	REVISION
311	2220	REVISION
312	2221	REVISION
313	2222	REVISION
314	2223	REVISION
315	2224	REVISION
316	2225	REVISION
317	2226	REVISION
318	2227	REVISION
319	2228	REVISION
320	2229	REVISION
321	2230	REVISION
322	2231	REVISION
323	2232	REVISION
324	2233	REVISION
325	2234	REVISION
326	2235	REVISION
327	2236	REVISION
328	2237	REVISION
329	2238	REVISION
330	2239	REVISION
331	2240	REVISION
332	2241	REVISION
333	2242	REVISION
334	2243	REVISION
335	2244	REVISION
336	2245	REVISION
337		





NOTE: DRAWING HAS BEEN REDUCED FOR
REPRODUCTION

1 - C



METCALF & EDDY, INC. ENGINEERS BOSTON, MA.	U.S. ARMY ENGINEER DISTRICT, NEW ENGLAND CORPS OF ENGINEERS WALTHAM, MA.
NATIONAL PROGRAM OF INSPECTION OF NON-FED. DAMS	
COHASSE BROOK RESERVOIR DAM	
FIGURE B-2 SECTIONS THROUGH DAM	
TRIBUTARY QUINEBAUG RIVER	MASSACHUSETTS
SCALE: 1" = 20'	DATE: JANUARY, 1979







ADJACENT BENCHMARK ELEV = 632.00 (MOL) ON SPILLWAY CREST
 DATE OF NOVEMBER 20, 1978; AND CONTRACT 1966-W1
 CONTRACTOR METCALF & EDDY, INC., AUGUST, 1966

LOCATION OF VIEW FOR PHOTOGRAPHS

METCALF & EDDY, INC. BOSTON, MASS.	U.S. ARMY ENGINEER DIV. NEW ENGLAND CORPS OF ENGINEERS WALTHAM, MASS.
NATIONAL PROGRAM OF INSPECTION OF NON-FLOOD DAMS	
COHASSETT BROOK RESERVOIR DAM	
FIGURE B-1 PLAN OF DAM AND DIKE	
TRIBUTARY QUINCY RIVER	MASSACHUSETTS
SCALE: 1" = 80'	DATE: JANUARY, 1979

Handwritten signature or initials



NOTES:

1. ELEVATIONS SHOWN ARE REFERENCED TO ASSUMED 60'
2. INFORMATION SHOWN BASED ON FIELD SURVEY OF NOV. "COHASSE RESERVOIR AND APPURTENANT WORK"
3. ↗ #3 DENOTES SEEPAGE
4. ↗ #2 INDICATES LOCATION AND DIRECTION OF V

METCALF & EDDY, INC.

11/2

APPENDIX B
PLANS OF DAM AND PREVIOUS
INSPECTION REPORT

	<u>Page</u>
Figure B-1 Plan of Dam and Dike	B-1
Figure B-2 Sections of Dam and Dike	B-2
Figure B-3 Cohasse Brook Reservoir, Reservoir Plan and Vicinity Map	B-3
Figure B-4 Cohasse Brook Reservoir, Plan of Dam and Appurtenances	B-4
Figure B-5 Cohasse Brook Reservoir, Dam Embankment Section and Profile	B-5
Figure B-6 Cohasse Brook Reservoir, Intake and Outlet Sections and Details	B-6
Figure B-7 Cohasse Brook Reservoir, Gate House and Pumping Station Piping Plans and Sections	B-7
Inspection by Massachusetts Department of Public Works, dated February 12, 1973	B-8

COHASSE BROOK RESERVOIR

PERIODIC INSPECTION CHECK LIST

PROJECT COHASSE BROOK RESERVOIR

DATE November 20, 1978

PROJECT FEATURE Spillway Bridge

NAME M. Larson

DISCIPLINE Geotechnical

NAME _____

AREA EVALUATED	CONDITION
SPILLWAY - ACCESS BRIDGE OUTLET WORKS - SERVICE BRIDGE	
a. Super Structure	Reinforced concrete
Bearings	None visible
Anchor Bolts	None visible
Bridge Seat	None visible
Longitudinal Members	Concrete
Under Side of Deck	Concrete
Secondary Bracing	None
Deck	Asphalt paved
Drainage System	Four weep holes
Railings	Pipe railings both sides, painted, good condition
Expansion Joints	None visible
Paint	On pipe railings
b. Abutment and Piers	
General Condition of Concrete	Good
Alignment of Abutment	Good
Approach to Bridge	Left side - abutment Right side - embankment
Condition of Seat and Backwall	Good. Transverse cracks in asphalt pavement at each end of deck at interface with soil subgrade.

PERIODIC INSPECTION CHECK LIST

PROJECT COHASSE BROOK RESERVOIR
 PROJECT FEATURE Spillway
 DISCIPLINE Hydraulic

DATE November 20, 1978
 NAME M. Larson
 NAME L. Branagan

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS</u>	Two concrete inlet wing walls extend into reservoir.
a. Approach Channel	
General Condition	Good
Loose Rock Overhanging Channel	None
Trees Overhanging Channel	None-a few logs and branches on top of riprap on left bank
Floor of Approach Channel	Submerged-only last 5' visible, floor covered with leaves.
b. Weir and Training Walls*	Concrete sidewalls. Concrete ogee weir-flow over full width, no flashboards..
General Condition of Concrete	Walls-good condition. One crack in top of west wall at south end of bridge. Some expansion joint filler material is missing
Rust or Staining	Weir & bottom - good condition
Spalling***	Yes-up to high water mark in channel & channel bottom, & high water mark on inlet walls.
Any Visible Reinforcing	None
Any Seepage or Efflorescence	Effl. at weep holes. Also at base of east training wall underneath north side of bridge.**
Drain Holes	Yes-at base of training walls D/S of weir
c. Discharge Channel	Seven on each side of channel, all dry. Trapezoidal shaped, about 160' long.
General Condition	Bottom & sides lined with stone riprap. Good
Loose Rock Overhanging Channel	None
Trees Overhanging Channel	None
Floor of Channel	Some of stone lining has weathered & disintegrated, particularly on west slope for about 100'
Other Obstructions	Some bushes and logs in bottom, slight movement of stone on side slopes.

*Concrete lined channel terminates with 2 rows of jump blocks. Few small logs, leaves and debris in blocks, several stones up to 2 ft. size in channel.

**At two vertical joints in D/S weir face, filler has eroded or is missing, maybe some water leakage.

***Slight pitting on weir face. Spalling up to high water mark on page A-7 of A-8 inlet walls & conc. channel. One spall on top of east wall next to S. edge of Brg. deck.

PERIODIC INSPECTION CHECK LIST

PROJECT COHASSE BROOK RESERVOIR

DATE November 20, 1978

PROJECT FEATURE Outlet Works

NAME M. Larson

DISCIPLINE Geotechnical

NAME _____

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - OUTLET STRUCTURE AND OUTLET CHANNEL</u>	
General Condition of Concrete	Good
Rust or Staining	Below high water mark
Spalling	Slight spalling at high water mark
Erosion or Cavitation	None
Visible Reinforcing	None
Any Seepage or Efflorescence	None visible
Condition at Joints	N/A
Drain Holes	N/A
Channel	
Loose Rock or Trees Overhanging Channel	None
Condition of Discharge Channel	Good - lined with riprap, clear of debris. Flowing water is clear.

Note - Refer to page A-2, Instrumentation System, Observation well is located northeast of pump station and west of Cohasse Brook, with the following surveyed information;

Elevation of ground surface = 586.1
 Elevation of top of pipe = 586.81
 Elevation of bottom of pipe = 582.06
 Elevation of water level = 583.56

PERIODIC INSPECTION CHECK LIST

PROJECT COHASSE BROOK RESERVOIR

DATE November 20, 1978

PROJECT FEATURE Outlet Works

NAME M. Larson

SUBDISCIPLINE Geotechnical

NAME _____

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - CONTROL TOWER</u>	Superstructure is concrete block faced with brick. Remainder is reinforced concrete.
a. Concrete and Structural	
General Condition	Good
Condition of Joints	Not visible
Spalling	Below high water mark on outside
Visible Reinforcing	None visible
Rusting or Staining of Concrete	Below high water mark on outside and inside of tower
Any Seepage or Efflorescence	None
Joint Alignment	N/A
Unusual Seepage or Leaks in Gate	None visible. Water level inside tower was 48'-7" on 60' long tankometer
Cracks	None visible
Rusting or Corrosion of Steel	Visible braces for valve stem extensions are rusted.
b. Mechanical and Electrical	
Air Vents Valves	All six valves are operable.
Float Walls Screens	Screens used when valve opened to pump house
Crane Hoist	
Elevator	
Hydraulic System	
Service Gates	
Emergency Gates	
Lightning Protection System	
Emergency Power System	
Wiring and Lighting System in Gate Chamber	

PERIODIC INSPECTION CHECK LIST

PROJECT COHASSE BROOK RESERVOIR

DATE November 20, 1978

PROJECT FEATURE Outlet Works

NAME M. Larson

DISCIPLINE Geotechnical

NAME _____

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - INTAKE CHANNEL AND INTAKE STRUCTURE</u>	
a. Approach Channel	Not visible
Slope Conditions	/
Bottom Conditions	
Rock Slides or Falls	
Log Boom	
Debris	
Condition of Concrete Lining	
Drains or Weep Holes	Refer to outlet works - control tower
b. Intake Structure	
Condition of Concrete	
Stop Logs and Slots	

PERIODIC INSPECTION CHECK LIST

PROJECT COHASSE BROOK RESERVOIR

DATE November 20, 1978

PROJECT FEATURE Dike embankment

NAME M. Larson

DISCIPLINE Geotechnical

NAME _____

AREA EVALUATED	CONDITION
<u>DIKE EMBANKMENT</u>	
Crest Elevation	Varies from 639.9 to 640.1
Current Pool Elevation	632.0
Maximum Impoundment to Date	634.2
Surface Cracks	None visible
Pavement Condition	Not applicable (N/A)
Movement or Settlement of Crest	None visible
Lateral Movement	None visible
Vertical Alignment	Level
Horizontal Alignment	Straight
Condition at Abutment and at Concrete Structures	Left abutment-bedrock outcrop Right abutment-earth & few stones, some exposed bedrock about 50 ft. north of rt. abutment at D/S toe
Indications of Movement of Structural Items on Slopes	<u>No structural items</u>
Trespassing on Slopes	Footpath on crest
Sloughing or Erosion of Slopes or Abutments	None visible
Bank Slope Protection - Riprap Failures	U/S slope covered with riprap & some small trees, brush & logs. Some rocks have weathered (disintegrated).
Unusual Movement or Cracking at or near Toes	None visible
Unusual Embankment or Downstream Seepage	None visible
Piping or Boils	None visible
Foundation Drainage Features	None visible
Toe Drains	None visible
Instrumentation System	None

PERIODIC INSPECTION CHECK LIST

PROJECT COHASSE BROOK RESERVOIR DATE November 20, 1978


PROJECT FEATURE Dam Embankment NAME M. Larson

DISCIPLINE Geotechnical NAME _____

Note: U/S = Upstream; D/S = Downstream

AREA EVALUATED	CONDITIONS
<u>DAM EMBANKMENT</u>	Crest-paved asphalt road, including bridge over spillway
Crest Elevation	Varies from 640.7 to 641.8
Current Pool Elevation	632.0
Maximum Impoundment to Date	634.2
Surface Cracks	Longitudinal cracking and one transverse crack on crest, transverse cracks at br.abut
Pavement Condition	Fair, grass growing through longitudinal cracks
Movement or Settlement of Crest	None visible, except for localized pavement depression on D/S edge of pave.at gate house
Lateral Movement	None visible
Vertical Alignment	Level
Horizontal Alignment	Straight, with an angle to southeast near right abutment
Condition at Abutment and at Concrete Structures	Right abutment-bedrock outcrops Left abut.-bedrock outcrops above road
Indications of Movement of Structural Items on Slopes	No structural items
Trespassing on Slopes	None - site fenced off
Sloughing or Erosion of Slopes or Abutments	No sloughing.Slight erosion on D/S face near center and left half at top of slope, middle of D/S slope,& along road edges on road onD/S slope,including stone lined gutter.
Rock Slope Protection - Riprap Failures	U/S slope covered with riprap.Some stone is disintegrated throughout riprap.Few logs & small bushes on U/S slope.
Unusual Movement or Cracking at or near Toes	None visible.
Unusual Embankment or Downstream Seepage	Slight flow from the following: about mid-height of stone lined ditch at left abut. contact, at toe about 50 ft. east of outlet headwall,both tile toe drains & riprap near outlet headwall,stones north of PP.Sta., steep face of bedrock outcrop on rt.abut.
Piping or Boils	None visible
Foundation Drainage Features	8"v.c.p.toe drain &stone gutter along full length of dam
Toe Drains	Two 8"v.c. pipes exit next to outlet train-
Instrumentation System*	ing walls. One observation well NE of PP Sta.


*See note on page A-6.




SECTION ALONG 30" DRAIN PIPE
SCALE 1" = 10' 0"




SECTION A
SCALE 1" = 10' 0"




SECTION B
SCALE 1" = 10' 0"



SECTION C
SCALE 1" = 10' 0"



SECTION D
SCALE 1" = 10' 0"



SECTION E
SCALE 1" = 10' 0"

NOTE: DRAWING HAS BEEN REDUCED FROM THIS REPORT.

REVISIONS

NO.	DATE	DESCRIPTION
1		
2		
3		
4		
5		
6		
7		
8		
9		
10		

APPROVED

DATE


SCALE

PROJECT NO.

DATE

SCALE

PROJECT NO.



NOTE: DRAWING HAS BEEN REVISIONED PER THIS REPORT.

DATE: 10/21/01

BY: [Signature]

NO.	DESCRIPTION	DATE	BY

ALL WORK SHALL BE DONE IN ACCORDANCE WITH THE LATEST EDITIONS OF THE BUILDING CODES AND STANDARDS.

DATE: 10/21/01

BY: [Signature]

CK
FILE Au.

INSPECTION REPORT - DAMS AND RESERVOIRS

1. Location: City/Town SOUTHBRIDGE Dam No. 3-14-278-19
Name of Dam COHASSE RESERVOIR Inspected by M. RICHARD
Date of Inspection 2-12-73

2. Owner/s: per: Assessors _____ Prev. Inspection _____
Reg. of Deeds _____ Pers. Contact ✓

1. SOUTHBRIDGE WATER SUPPLY Co. 70 FOSTER ST. SOUTHBRIDGE MA. 01550
Name St. & No. City/Town State Tel. No.

2. _____
Name St. & No. City/Town State Tel. No.

3. _____
Name St. & No. City/Town State Tel. No.

3. Caretaker (if any) e.g. superintendent, plant manager, appointed by absentee owner, appointed by multi owners.

Name: _____ St. & No.: _____
City/Town: _____ State: _____ Tel. No.: _____

4. No. of Pictures taken NONE

5. Degree of Hazard: (if dam should fail completely)*

1. Minor _____ 2. Moderate ✓
3. Severe _____ 4. Disastrous _____

* This rating may change as land use changes (future development)

6. Outlet Control: Automatic _____ Manual ✓
Operative ✓ yes; _____ No.

Comments:

7. Upstream Face of Dam: Condition:

1. Good ✓ 2. Minor Repairs _____
3. Major Repairs _____ 4. Urgent Repairs _____

Comments:

8. Downstream Face of Dam:

Condition: 1. Good ✓ 2. Minor Repairs _____
3. Major Repairs _____ 4. Urgent Repairs _____

Comments:

9. Emergency Spillway:

Condition: 1. Good _____ 2. Minor Repairs _____
3. Major Repairs _____ 4. Urgent Repairs _____

Comments:

10. Water Level at time of inspection: 9 ft. above _____ below ✓
top of dam ✓ principal spillway _____
other _____

11. Summary of Deficiencies Noted:

Growth (Trees and Brush) on Embankment NONE
Animal Burrows and Washouts NONE
Damage to slopes or top of dam NONE
Cracked or Damaged Masonry NONE
Evidence of Seepage NONE
Evidence of Piping NONE
Erosion NONE
Leaks NONE
Trash and/or debris impeding flow NO
Clogged or blocked spillway NO
Other NONE

12. Remarks & Recommendations: (Fully Explain)

THIS DAM & RELATED DIKE WERE FOUND TO BE IN EXCELLENT
CONDITION AND IS VERY ^{WELL} MAINTAINED BY THE WATER COMPANIES
FORCES

13. Overall Condition:

- 1. Safe _____
- 2. Minor repairs needed _____
- 3. Conditionally safe - major repairs needed _____
- 4. Unsafe _____
- 5. Reservoir impoundment no longer exists (explain)
Recommend removal from inspection list _____

DESCRIPTION OF DAM

DISTRICT 3

Submitted by Misses R. Williams Dam No. 3-14-27E-19

Date 2-12-73 City/Town SOUTHBRIDGE

Name of Dam COHASSE RESERVOIR

1. Location: Topo Sheet No. 18D

Provide 8 1/2" x 11" in clear copy of topo map with location of Dam clearly indicated.

2. Year built: 1968 Year/s of subsequent repairs _____

3. Purpose of Dam: Water Supply Recreational _____
Irrigation _____ Other _____

4. Drainage Area: 1.9 sq. mi. _____ acres

5. Normal Ponding Area: 75 acres; Ave. depth _____
Impoundment: 225,000,000 gals.; _____ acre ft.

6. No. and type of dwellings located adjacent to pond or reservoir
GATE HOUSE i.e. summer homes, etc. _____

7. Dimensions of Dam: Length 750' Max. Height 60'
Slopes: Upstream Face 2.5:1
Downstream Face 2:1
Width across top 22'

8. Classification of Dam by Material:
Earth Conc. Masonry Stone Masonry _____
Timber _____ Rockfill _____ Other _____

9. A. Description of present land usage downstream of dam:
100 % rural; _____ % urban.

B. Is there a storage area or flood plain downstream of dam which could accomodate the impoundment in the event of a complete dam failure? yes no _____

COHASSE BROOK RESERVOIR DAM

DAM NO. 3-14-278-19



10. Risk to life and property in event of complete failure.

- No. of people NONE.
- No. of homes NONE.
- No. of Businesses NONE.
- No. of industries NONE. Type _____
- No. of utilities WATER CO. PUMP HOUSE. Type _____
- Railroads NONE.
- Other dams 3-14-278-13.
- Other NONE.


11. Attach Sketch of dam to this form showing section and plan on 8 1/2" x 11" sheet.

12. How to Locate: FROM THE INTERSECTION OF RTE. 198 & DENNISON RD., 500' SOUTH ON RTE. 198 TAKE LT. AT OILED GRAVEL RD., THIRD PASTURE, TO WATER WORKS GATE & DAM SITE.

DAM # 3-14-278-1
 COHASSE BROOK DAM
 SOUTHBRIDGE
 FEB, 12, 1973



SECTION A-A'



S O U T H B R I D G E

Southbridge

QUINERANG

Wells Pond

3-14-278-19

WORCESTER CO
WINDHAM CO


18D

APPENDIX C
PHOTOGRAPHS

COHASSE BROOK RESERVOIR



NO. 1 VIEW OF SPILLWAY



NO. 2 VIEW OF SPILLWAY CREST

CHASSE BROOK RESERVOIR DAM

C-1



NO. 3 VIEW OF SPILLWAY AND DISCHARGE CHANNEL



NO. 4 VIEW OF DOWNSTREAM SLOPE OF DAM

WATNE BROOK RESERVOIR DAM



NO. 5 VIEW OF DOWNSTREAM SLOPE OF DAM



NO. 6 VIEW OF OUTLET CONDUIT

NO. 7 VIEW OF DAM



NO. 7 VIEW OF OUTLET DISCHARGE CHANNEL



NO. 8 VIEW OF UPSTREAM SLOPE OF DIKE

COHASSE BROOK RESERVOIR DAM

C-4

APPENDIX D
HYDROLOGIC AND HYDRAULIC
COMPUTATIONS

	<u>Page</u>
Figure D-1 Drainage Area Map - Cohasse Brook Reservoir	D-1
Hydrologic and Hydraulic Computations	D-2

COHASSE BROOK RESERVOIR




FIG. D-1 DRAINAGE AREA MAP – COHASSE BROOK RESERVOIR

I Test Flood Storage & Storage Functions - Without Flashboards

1 - Total Drainage Area - 1.96 mi²

2 - Pond(s) Area: 0.08 mi²
 Swamp(s) Area: .02 + .02 + .03 + .10 = 0.17
 Total Area Pond(s) & Swamp(s): 0.25

% Ponds & Swamps = $\frac{0.25}{1.96} \approx 12\%$

3 - $\frac{1035 - 632}{13900} = 2.89$ } Say Ave Slope = 3%

4 - Using C. of E. Curves for Peak Flow Rates & above guide values the Peak Flow Rate was estimated to be between "Rolling and Flat & Coastal" and taken at 1550 c.f.s./mi²
 Size Class: Interm.; Hazard Pot.: High; Spill. Des. Flood: P.M.F.
 Use: Test Flood = P.M.F.

5 - Test Flood Inflow = (1550)1.96 \approx 3100 c.f.s.

6 - Pond Storage

The pond area is 0.08 sq. mi. at elev. 632
 Based on a const. area, storage increases at 54 ac. feet per foot of depth increase.

7 - Storage Functions are based on $Q_{out} = Q_{in} \left[1 - \frac{S_{out}}{R} \right]$

S_{out} = Storage Vol. in Reservoir related to final Q_{out}
 in terms of inches of rain over the drainage area.

S (in Inches) = $12 D \left(\frac{0.08}{1.96} \right) = 0.49 D$; R = 3hr rain of storm

D = Storage Depth (above spillway) on reservoir in feet

8 - Storage Functions: (F_T) ; $D = 0$ @ Pond E. 632

$F_T = 3100 - 163 S = 3100 - 80 D$

② Discharge Ratings

A - Ogee Spillway

Width = 40', $Q = CLH^{1.5} = 4 \times 40 \times H^{1.5} = 160H^{1.5}$

Res. El. 633 634 635 636 637 638 639 640

Discharge 160 450 830 1280 1790 2350 2960 3620

B - Low Level Outlet


30 in. ϕ pipe - Say losses = $3 \times \text{Vel. Hd.}$ (Ent, Ex + Valve Frict)

Head = $632 - 583 = 49 \text{ ft} = 3.0 \frac{V^2}{2g}$

$V = 32 \text{ fps}$, $Q_i = 150 \text{ cfs}$

Time to Lower Res. 1 ft = $\frac{54(43560)}{150(3600)} = 4 \text{ hours}$

III Discharge, Storage & Storage Function vs Res. Level



METCALF & EDDY, ENGINEERS

IV Failure of Dam

Peak Failure Flow:

Pond Elevation - 638.4 (Max. Pond w/ T.F. Qout)
 Toe Elevation - 584.0 (Bot. of Dam - not channel)
 $Y_0 = 54.4$ ft.


Dam Length Subject to Breaching = 220 ft
 $W_0 = 40\% (220) = 88$ ft.

T.F. Qout = 2600 cfs
 $Q_P = 1.68 W_0 (Y_0)^{1.5} = 1.68 (88) (54.4)^{1.5} = 59300$ c.f.s.
 Total 61,900 cfs

Storage Volume Released:

Storage Above Spillway = 346 ac. ft.
 Storage Below Spillway $48 \times \frac{1}{3} \times 52 = 832$
 $S = \text{Total Storage} = 1178$ ac. ft.


1st Channel Hydraulics: $S = \frac{20}{1700} = .0118$, $n = .06$, $V = 2.7 R^{2/3}$



$R \approx \frac{1}{2} y \therefore V = 1.7 y^{2/3}$; $A = 4.5 y^2$

At outskirts of So' bridge
 Dist. = 6500 ft
 Vol. = $6500(3784) = 565$ ac.ft.

y	A	V	Q
5	112.5	5.0	560
10	450	7.9	3550
15	1012	10.3	10460
20	1800	12.5	22500
25	2812	14.5	40900
30	4050	16.4	66500
35	5512	18.2	100300
37	6160	18.9	116200



Trial $Q_1 = 61900 (1 - \frac{565}{1178})$

" " = 32200
 $y_2 = 23$; Ave $y = 27$

$\therefore Q_2 = 50000$ cfs
 at entrance to
 Southbridge

Time to Drain:

$\frac{43560 (1178)}{3600 (\frac{1}{2}) (59300)} = 0.48$ Hours or 29 min.

APPENDIX E
INFORMATION AS CONTAINED IN THE
NATIONAL INVENTORY OF DAMS

COHASSE BROOK RESERVOIR

STATE NO. 100	DIVISION	CONGR. DIST.	COUNTY	CONGR. DIST.	NAME	LATITUDE (NORTH)	LONGITUDE (WEST)	REPORT DATE
100						123.2	123.2	001-1974

POPULAR NAME	NAME OF IMPROVEMENT
RIVER OR STREAM	NEAREST DOWNSTREAM CITY - TOWN - VILLAGE
POPULATION	POPULATION
0	16000

TYPE OF DAM	YEAR COMPLETED	PURPOSES	STORAGE CAPACITY (CY)	HYDRAULIC HEAD (FT)	HYDROELECTRIC CAPACITY (KW)	IRREGULAR CAPACITIES (ACRE-FT)	NEAREST TOWN (MILE)

REMARKS

SPILLWAY HAS (1) (2) (3) (4) (5) (6) (7) (8) (9) (10)	VOLUME OF DAM (CY)	POWER CAPACITY (KW)	NAVIGATION LOCKS

OWNER	ENGINEERING BY	CONSTRUCTION BY

DESIGN	CONSTRUCTION	OPERATION	MAINTENANCE

INSPECTION BY	INSPECTION DATE	AUTHORITY FOR INSPECTION

REMARKS

LIST OWN FROM REVISED SCS A VIEW/DATE

21 FEB 79

END

FILMED

7-85

DTIC