AD-A15	5 407	NAT NAR	IONAL E INDU	PROGRI	AM FOR	INSPE	CTION	OF NO PS OF	N-FEDE Engine	RAL DI ERS N	RNS Rltham	1/	1
UNCLAS	SIFIE								_	F/G :	13/13		
													Ĩ.
						1							
												P,	71 14
		5 22		1978									
							END Ministra Ministra	-		_	_		
													and the second



ł

Ś

1

MICROCOPY RESOLUTION TEST CHART NATIONAL BUREAU OF STANDARDS 1963 A



RFPORT DOCUMENTATI	ION PAGE	READ INSTRUCTIONS BEFORE COMPLETING FORM
REPORT NUMBER MA 00594	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
TITLE (and Sublille)		5. TYPE OF REPORT & PERIOD COVERE
Ware Industries Main (upper) Dan	INSPECTION REPORT	
NATIONAL PROGRAM FOR INSPECTION DAMS	OF NON-FEDERAL	6. PERFORMING ORG. REPORT NUMBER
U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION		S. CONTRACT OR GRANT NUMBER(*)
PERFORMING ORGANIZATION NAME AND ADD	RESS	10. PROGRAM ELEMENT, PROJECT, TAS AREA & WORK UNIT NUMBERS
I. CONTROLLING OFFICE NAME AND ADDRESS		12. REPORT PATE November 1978
NEW ENGLAND DIVISION, NEDED 424 TRAPELO ROAD, WALTHAM, MA. O	NEEKS	13. NUMBER OF PAGES
MONITORING AGENCY NAME & ADDRESS(II di	Iterent from Controlling Office)	15. SECURITY CLASS. (of this report)
		UNCLASSIFIED
DISTRIBUTION STATEMENT (of this Report)	TPIBUTION UNLIMITED	UNCLASSIFIED 184. DECLASSIFICATION/DOWNGRADING SCHEDULE
DISTRIBUTION STATEMENT (of the Report)	TPIBUTION UNLIMITED	UNCLASSIFIED
APPROVAL FOR PUBLIC RELEASE: DIS DISTRIBUTION STATEMENT (of the ebotteet end SUPPLEMENTARY NOTES Cover program reads: Phase I Ins however, the official title of t Non-Federal Dams; use cover dat	TPIBUTION UNLIMITED	UNCLASSIFIED 18. DECLASSIFICATION/DOWNGRADING SCHEDULE onal Dam Inspection Program nal Program for Inspection (
APPROVAL FOR PUBLIC RELEASE: DIS SUPPLEMENTARY NOTES OUSTRIBUTION STATEMENT (of the observect on SUPPLEMENTARY NOTES Over program reads: Phase I Ins Nowever, the official title of t Von-Federal Dams; use cover dat KEY WORDS (Continue on reverse side if necessar DAMS, INSPECTION, DAM SAFETY, Connecticut River Basin Ware, Massachusetts Ware River	TPIBUTION UNLIMITED fored in Block 20, 11 different free pection Report, Nati he program is: Natio e for date of report	UNCLASSIFIED Isa. DECLASSIFICATION/DOWNGRADING SCHEDULE m Report) onal Dam Inspection Program nal Program for Inspection of
APPROVAL FOR PUBLIC RELEASE: DIS APPROVAL FOR PUBLIC RELEASE: DIS DISTRIBUTION STATEMENT (of the obstract and SUPPLEMENTARY NOTES Cover program reads: Phase I Ins however, the official title of t Non-Federal Dams; use cover dat KEY WORDS (Continue on reverse side if necessar DAMS, INSPECTION, DAM SAFETY, Connecticut River Basin Ware, Massachusetts Ware River	TPIBUTION UNLIMITED fored in Block 20, if different free pection Report, Nati he program is: Natio e for date of report my and identify by block number) ry and identify by block number)	UNCLASSIFIED Isa DECLASSIFICATION/DOWNGRADING SCHEDULE onal Dam Inspection Program nal Program for Inspection (

ALL COMPANY DESCRIPTION DESCRIPTION

ú



Inclosed is a copy of the Ware Industries Main (Upper Dam) Phase I Inspection Report, which was prepared under the National Program for Inspection of Non-Federal Dams. The report is based upon a visual inspection, a review of past performance, and a preliminary hydrological analysis. A brief assessment is included at the beginning of the report.

The preliminary hydrologic analysis has indicated that the spillway capacity for the Ware Industries Main (Upper Dam) would likely be exceeded by floods greater than 7 percent of the Probable Maximum Flood (PMF), the test flood for spillway adequacy. Our screening criteria specifies that a dam of this class which does not have sufficient spillway capacity to discharge fifty (50) percent of the PMF, should be adjudged as having a seriously inadequate spillway and the dam assessed as unsafe, non- emergency, until more detailed studies prove otherwise or corrective measures are completed.

The term "unsafe" applied to a dam because of an inadequate spillway does not indicate the same degree of emergency as that term would if applied because of structural deficiency. It does indicate, however, that a severe storm may cause overtopping and possible failure of the dam, with significant damage and potential loss of life downstream.

It is recommended that within twelve months from the date of this report the owner of the dam engage the services of a professional or consulting engineer to determine by more sophisticated methods and procedures the magnitude of the spillway deficiency. Based on this determination, appropriate remedial mitigating measures should be designed and completed within 24 months of this date of notification. In the interim a detailed emergency operation plan and warning system should be promptly developed. During periods of unusually heavy precipitation, round-the-clock surveillance should be provided. NEDED-E Honorable Edward J. King

I have approved the report and support the findings and recommendations described in Section 7, with qualifications as noted above. I request that you keep me informed of the actions taken to implement these recommendations since this follow-up is an important part of the non-Federal Dam Inspection Program.

A copy of this report has been forwarded to the Department of Environmental Quality Engineering, the cooperating agency for the Commonwealth of Massachusetts. This report has also been furnished to the owner of the project, Nenameseck Industrial Properties, Inc., East Main Street, Ware, Massachusetts 01082.

Copies of this report will be made available to the public, upon request to this office, under the Freedom of Information Act, thirty days from the date of this letter.

I wish to take this opportunity to thank you and the Department of Environmental Quality Engineering for the cooperation extended in carrying out this program.

Sincerely,

2

MAX B. SCHEIDER Colonel, Corps of Engineers Division Engineer CONNECTICUT RIVER BASIN WARE, MASSACHUSETTS

Ĺ

. . .

1

WARE INDUSTRIES MAIN (UPPER) DAM MA 00594

PHASE I INSPECTION REPORT

NATIONAL DAM INSPECTION PROGRAM

DEPARTMENT OF THE ARMY NEW ENGLAND DIVISION, CORPS OF ENGINEERS WALTHAM, MASS 02154

NOVEMBER 1978

REPRODUCED AT GOVERNMENT EXPENSE

DISCLAIMER NOTICE

THIS DOCUMENT IS BEST QUALITY PRACTICABLE. THE COPY FURNISHED TO DTIC CONTAINED A SIGNIFICANT NUMBER OF PAGES WHICH DO NOT REPRODUCE LEGIBLY.

PHASE I INVESTIGATION REPORT NATIONAL DAM INSPECTION PROGRAM

Identification No.: Name of Dam: Town: County: State: Stream: Date of Site Visit:

2

MA 00594 Ware Industries Main (Upper) Ware Hampshire Massachusetts Ware River 12 May 1978

BRIEF ASSESSMENT

The Ware Industries Main (Upper) Dam is located on the Ware River in Ware, Massachusetts. The dam consists of a main spillway 115 ft. long and approximately 34 ft. high, a spillway extension 50 ft. long and 4 ft. high, a concrete emergency spillway, a gate house with control works to a canal, and a 115 ft. long overflow weir from the canal. The dam was constructed in the years 1880 to 1882 to power mill equipment.

The dam is currently classified as having a "high" hazard potential in the Corps of Engineers National Inventory of dams.

Based on a visual examination of the structure, the project is in good to fair condition. There was no evidence of structural failure or other conditions which would warrant urgent remedial action.

Based on size and hazard classifications in accordance with Corps of Engineers guidelines, the test flood for this dam is the Probable Maximum Flood (PMF). The PMF outflow of 109,200 cfs would overtop the dam by 11.25 ft. With the water level at the top of dam, the spillway system can pass 7980 cfs which is 7.3 percent of the test flood.

Nenameseck Industrial Properties, Inc., owner of the dam, should engage a registered professional engineer to determine the structural stability of the main dam, to evaluate alternative measures for increasing the discharge capacity of the dam and to inspect the main spillway weir during no flow condition as outlined in Section 7.2. The results of those investigations and the remedial measures, including repair of concrete surfaces, reconstruction or stabilization of a stone wall donwstream of the right abutment for the emergency spillway, and other work as outlined in Section 7.3, should be implemented by the Owner within one year after receipt of this report.

HALEY & ALDRICH, INC. by: Harl Aldrich

President



This Phase I Inspection Report on Ware Industries Main Upper Dam has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the <u>Recommended Guidelines for Safety Inspection</u> of Dams, and with good engineering judgment and practice, and is hereby submitted for approval.

Charles +

CHARLES G. TIERSCH, Chairman Chief, Foundation and Materials Branch Engineering Division

Karns

FRED J. RAVENS, Jr., Member Chief, Design Branch Engineering Division

SAUL COOPER, Member Chief, Water Control Branch Engineering Division

APPROVAL RECOMMENDED:

ac B. Fryan JOE B. FRYAR

Chief, Engineering Division

. :

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, DC 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I Investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I Investigations are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the test flood is based on the estimated "probable maximum flood" for the region (greatest reasonably possible storm run-off), or a fraction thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

PREFACE

E

•

i. Ta

-

•

TABLE OF CONTENTS

U

.

. .

	rage no.
LETTER OF TRANSMITTAL BRIEF ASSESSMENT REVIEW BOARD SIGNATURE SHEET PREFACE TABLE OF CONTENTS OVERVIEW PHOTO LOCATION MAP	i ii iii iv v v vi vii
SECTION 1 - PROJECT INFORMATION 1.1 GENERAL 1.2 PROJECT DESCRIPTION 1.3 PERTINENT DATA	1 2 4
SECTION 2 - ENGINEERING DATA 2.1 DESIGN RECORDS 2.2 CONSTRUCTION RECORDS 2.3 OPERATION RECORDS 2.4 EVALUATION	7 7 7 7
SECTION 3 - VISUAL EXAMINATION 3.1 FINDINGS 3.2 EVALUATION	8 10
SECTION 4 - OPERATIONAL PROCEDURES 4.1 PROCEDURES 4.2 MAINTENANCE OF EMBANKMENT 4.3 MAINTENANCE OF OPERATING FACILITIES 4.4 DESCRIPTION OF ANY WARNING SYSTEM IN EFFECT	11 11 11 11
4.5 EVALUATION SECTION 5 - HYDRAULIC/HYDROLOGIC 5.1 EVALUATION OF FEATURES	11 12
SECTION 6 - STRUCTURAL STABILITY 6.1 EVALUATION OF EMBANKMENT STRUCTURAL STABILITY 6.2 EVALUATION OF SPILLWAY	15 15
STRUCTURAL STABILITY	

iv

TABLE OF CONTENTS (Continued)

i,

1

ì

5-

P

•

) -1

C.

Pac	re	NO.	_
1 UL U		$m \cup n$	•

SECTION 7	- ASSESSMENT, RECOMMENDATIONS AND	
	REMEDIAL MEASURES	
7.1	DAM ASSESSMENT	
7.2	RECOMMENDATIONS	
7.3	REMEDIAL MEASURES	
7.4	ALTERNATIVES	

APPENDIX A - INSPECTION TEAM ORGANIZATION AND CHECK LIST

APPENDIX B - LIST OF AVAILABLE DOCUMENTS AND PRIOR INSPECTION REPORTS

APPENDIX C - SELECTED PHOTOGRAPHS OF PROJECT

APPENDIX D - OUTLINE OF DRAINAGE AREA AND HYDRAULIC COMPUTATIONS

APPENDIX E - INFORMATION AS CONTAINED IN THE NATIONAL INVENTORY OF DAMS

v



PHASE I INVESTIGATION REPORT NATIONAL DAM INSPECTION PROGRAM

WARE INDUSTRIES MAIN (UPPER) DAM MA 00594

SECTION 1-PROJECT INFORMATION

1.1 GENERAL

(

A. <u>Authority</u>. Public Law 92-367, August 8, 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a National Program of Dam Inspection throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region.

Haley & Aldrich, Inc. has been retained by the New England Division to inspect and report on selected dams in the State of Massachusetts. Authorization and notice to proceed were issued to Haley & Aldrich, Inc. under a letter dated 26 April 1978 from Colonel Ralph T. Garver, Corps of Engineers. Contract No. DACW33-78-C-0301 has been assigned by the Corps of Engineers for this work. Camp, Dresser & McKee, Inc. was retained as consultant to Haley & Aldrich, Inc. on the structural, mechanical/electrical and hydraulic/hyrologic aspects of the investigation.

B. <u>Purpose</u>. The primary purposes of the National Dam Inspection Program are to:

1. Perform technical inspection and evaluation of non-Federal dams to identify conditions which threaten the public safety and thus permit correction in a timely manner by non-Federal interests.

2. Encourage and prepare the states to initiate quickly effective dam safety programs for non-Federal dams.

3. To update, verify and complete the National Inventory of Dams.

1.2 PROJECT DESCRIPTION

A. <u>Location</u>. The Ware Industries Main (Upper) Dam is located on the Ware River in Ware, Massachusetts, as indicated on the Location Map, page vii.

B. Dam and Appurtenances. The dam consists of a concretecapped main spillway with a higher concrete spillway extension to the right, separated by a concrete wall. There is an emergency spillway left of the dam and an outlet gate house to a canal right of the dam, all connected by either concrete or stone walls. A stone-capped overflow weir is located on the side of the canal downstream of the main spillway. There are no earth embankments. The dam and appurtenances are all believed to be founded on rock. A "Site Plan" is shown in Appendix B-4.

The main spillway is 115 ft. in length and approximately 34 ft. high. The 50 ft. long spillway extension has a crest elevation of 464.8, 12 inches higher than the main spillway crest. The extension is founded on rock and only about 3 to 4 ft. high. The spillways are shown in Photos No. 2 and 4. The concrete emergency spillway 'left of the main spillway is 16 ft. in length with a crest elevation of 466.9. There are stone walls upstream and downstream of the spillway at both abutments, as shown in the plan in Appendix B-5 and Photos No. 10, 12 and 13.

A gate house located right of the spillways is the outlet to a canal shown on the plan in Appendix B-3. The structure consists of 5 timber slide gates and a timber bulkhead. The overflow weir downstream of the gate house is 115 ft. in length and has a crest elevation of approximately 466.35 with the exception of an 8 ft. length at El. 464.45 where the 22-in. thick cap stone has been removed, as shown in Photo No. 8.

C. <u>Size Classification</u>. The storage to the top of the dam is estimated to be 746 acre-ft., and the height of the dam is approximately 40 ft. Storage of less than 1000 acre-ft. or a height of less than 40 ft. classifies the dam in the "small" category according to guidelines established by the Corps of Engineers.

D. <u>Hazard Classification</u>. The dam is currently classified as having a "high" hazard potential in the Corps of Engineers National Inventory of Dams.

During the September 1938 huuricane, extensive damage to the surrounding residential, industrial and commercial structures as well as to the dam itself was incurred. Flood waters resulting from approximately 6 in. of rainfall in six hours inundated East Main Street by 4 ft. and caused the bridge to be washed out. The South Street bridge downstream was also washed out and the flood waters rose to the top of the first floor windows of the old Ware Woolen Company. At the dam, the emergency spillway was washed out and the homes on the easterly side of the dam became islands, as the water rushed down the adjoining streets.

É

R

.

Based on dam failure analysis computations, Appendix D-11, the flow generated from a breach of the dam is approximately 1.5 times greater than that of the 1938 hurricane and would likely cause an even greater amount of structural damage and loss of life downstream of the dam. Therefore, it is recommended that the "high" hazard potential classification be retained.

E. <u>Ownership</u>. The name and address of the current owner is:

Nenameseck Industrial Properties, Inc. East Main Street Ware, MA 01082 (Phone: (617) 967-5191)

Mr. Edward C. Beaudin, Receiver's Agent, represented the owner during the course of this investigation.

Ware Industries, Inc. of the same address as above was the owner from 1937 until it went bankrupt in 1978. Prior to 1937, Otis Company of an unknown address owned the dam.

F. Operator. Mr. Edward C. Beaudin has been responsible for operation and maintenance of the dam.

G. <u>Purpose of the Dam</u>. The dam was originally used for generating power. Presently, the dam serves no specific purpose.

H. <u>Design and Construction History</u>. The dam is believed to have been constructed between 1880 and 1882 as part of a power generating system for mills in the area. This system included the adjacent canal downstream of the gate house and

penstocks from the canal. Mr. Joseph A. Nowak of Springfield, MA, is an engineer familiar with this project. He believes that seven water wheels operated prior to the 1938 flood and that at least two operated into the 1950's. Some water is still being used from the canal for manufacturing purposes, but the penstocks have been plugged.

The original design and construction records are not available. Although not documented, the only apparent major post-construction changes to the dam were the addition of the spillway extension and reconstruction to the emergency spillway following the 1938 flood. Repairs proposed in 1975 were never implemented.

I. <u>Normal Operational Procedures</u>. There is no formal established routine for the operation of the dam. The control gates are operated on a demand basis.

1.3 PERTINENT DATA

21

Elevation given in this report are based on field measurements correlated with those appearing on a "Site Plan" prepared by Nowak in 1975, a copy of which is included in Appendix B-3. The datum for those elevations is believed to be the National Geodetic Vertical Datum (NGVD).

A. <u>Drainage Area</u>. The drainage area of the Ware River at the Ware Industries Main (Upper) Dam in 199 square miles (127,360 acres). The pond surface comprises 39.5 acres (0.03 percent) of this total. The topography within the watershed varies from rolling to very hilly while the major tributary streams are the East and West Branches of the Ware River and the Burnshirt River. These tributaries all enter upstream of South Barre and only two minor tributaries, Moose Brook and Prince River enter between South Barre and Ware.

B. <u>Discharge at Dam Site</u>. The maximum known flood at the damsite is that which occurred during the September 1938 hurricane (approx. 6 in. of rain in 6 hours). This storm resulted in a peak inflow of 22,700 cfs. However, because of the construction of the Barre Falls Dam, this peak would be decreased to approximately 17,700 cfs, if the same storm were to occur at present.

- 1. Outlet Works.....Not applicable
- 2. Maximum known flow at
 - dam site.....22,700 cfs
- 3. Ungated spillway capacity at top of dam.....7,980 cfs at El. 470.0

	4.	Ungated spillway capa- city at test flood pool	
		elevation	109,200 cfs (the test flood outflow) provided the top of dam was raised 37.8 ft. to El. 507.8
	5.	Gated spillway capa- city at normal pool	
	6.	elevation Gated spillway capa-	Not applicable
	7.	elevation Total spillway capa- city at test flood pool	Not applicable
		elevation	109,200 cfs (the test flood outflow) provided the top of dam was raised 37.8 ft. to El. 507.8
	8.	Total project discharge at test flood pool	
		elevation	109,200 cfs at El. 481.25
c.	Ele	evation (ft. above NGVD)	
	1. 2.	Top Dam Test flood pool-design	470 (Est.)
	3.	surcharge Design surcharge-	481.25
	4.	Full flood control	Unknown
	5.	pool Recreation pool	Not applicable 463.8
	ь. 7	(no flashboards)	463.8
	/. e	diversion tunnel	Not applicable
	ð.	of dam	430 (Est.)
	У.	Maximum taliwater	UNKNOWN
· D.	Res	servoir	
	1.	Length of maximum	0.88 mi (Fet)
	2.	Length of recreation	
		pool	0.88 mi. (Est.)

Ē

•

5

2

3. Length of flood control pool...... Not applicable

Ε. Storage (acre-feet) 1. 2. Test flood pool..... 3,535 (Est.) Flood-control pool..... Not applicable 3. 4. Recreation pool..... 145 (Est.) 5. Spillway crest..... 145 (Est.) F. Reservoir Surface (acres) 1. Top of dam..... 181 (Est.) Test flood pool..... 315 (Est.) 2. 3. Flood control pool..... Not applicable Recreation pool...... 39.5 (Est.) Spillway crest..... 39.5 (Est.) 4. 5. G. Dam Embankment..... Not applicable Η. Diversion and Regulating Facilities..... Not applicable I. Spillway Type..... "Broad-crested" ir-1. regularly shaped weir 2. Length of weir Main dam..... 115 ft. Extension.... 50 ft. 3. Crest elevation Main dam..... 463.8 ft. Extension..... 464.8 ft. 4. Gates..... None U/S Channel..... Flat slope; wide flood 5. plain 6. D/S Channel..... Approx. 3 percent; Ware Woolen Co. Dam located approx 1,950 ft. downstream from Ware Road

J. <u>Regulating Outlets</u>. There are five double-stem manually operated (through rack and pinion gears) gates in a gate house located upstream of the right abutment. The gates are five feet wide and are estimated to be four to five feet in height. The invert elevation of the gates is unknown. The gates are operable.

2.1 DESIGN RECORDS

E

P

No records of the original design are available. Drawings by Joseph A. Nowak, Consulting Engineer, in 1975 and flow calculations dated 22 April 1976 are the only "design" records available.

2.2 CONSTRUCTION RECORDS

No original construction records are available and no subsequent construction is documented in prior inspection reports or correspondence.

2.3 OPERATION RECORDS

No operational records specific to this dam are available. However, the New England Division of the Corps of Engineers made general studies of this area following the 1938 flood.

2.4 EVALUATION

A. <u>Availability</u>. A detailed list of all engineering data available for use in preparing this report is included in Appendix B-1. Selected documents from the listing are also included in Appendix B.

B. <u>Adequacy</u>. A review of design and construction data is a highly desirable factor in developing a thorough Phase I assessment. However, there were insufficient engineering data available for this dam to allow for such a review. The evaluation of the dam is based primarily on visual inspection, past performance and engineering judgement.

C. <u>Validity</u>. The three 1975 drawings by Joseph A. Nowak show the general configuration of the dam and site, but details such as the elevation of the overflow weir are incorrect. Furthermore, the repairs shown on the 1975 drawing "Emergency Spillway Repairs" by Joseph A. Nowak were never implemented.

SECTION 3 - VISUAL EXAMINATION

3.1 FINDINGS

R

A. <u>General</u>. The Phase I visual examination of the Ware Industries Main (Upper) dam was conducted on 11 May 1978.

In general, the project was found to be in good to fair condition, although the main dam could not be examined because of discharge over the weir. A few deficiencies which require correction were noted.

A visual inspection check list is included in Appendix A and selected photographs of the project are given in Appendix C.

B. Dam. The view of the main dam (spillway weir) was obscured by flowing water during the inspection. The left side wall is constructed of cut granite masonry. A number of the blocks at the downstream end of this wall are loose and have fallen free, barely visible in Photo No. 2. The right wall of the main dam is constructed of concrete, Photo No. 3. The wall is undermined at the downstream end and has small spalls on the edges of the concrete, Photo No. 7.

A spillway extension wall extends 50 ft. to the right from the main dam, Photo No. 4. Concrete shows considerable deterioration at the top edge and the vertical downstream face. The wall is undermined at the right end, Photo No. 5, and at the left end adjacent to the main dam, Photo No. 6. The wall exhibits cracks and efflorescence. The wall is 2 ft. wide at the top and has an upstream slope which was measured to be 2 horizontal to 1.3 vertical.

The main dam and the extension are believed to be founded on bedrock. The downstream channel is also on the schist. Minor rock debris is present in the downstream channel.

C. Appurtenant Structures. The flow of water to the canal is controlled by gates located in a gate house at the entrance of the canal. The canal is located to the right of the spillway extension. The gate house shows the effect of vandalism and lack of maintenance. The top cord of the main truss on the canal side shows considerable deterioration at a panel point. A light temporary brace has been inserted at this point to support the roof.

The gate mechanisms are in good condition. The gate structure is supported by cut stone masonry walls on each side of the canal. The walls have open joints and voids near the water surface.

1

An overflow weir is present on the southeast side of the canal, allowing water to flow back into the main channel. The weir is made up of cut quarry stones for the main portion of the wall and a cut granite cap for the weir crest. One section of the cut granite cap has been removed to provide a pilot channel, Photo No. 8. Trees and brush has been cut recently downstream of the channel. They are presently piled in the channel itself. The access bridge which parallels the overflow weir is in good condition. It is of timber construction. Several of the pier caps for this bridge have cracked timbers. Conditions on the approach to the overflow weir are shown in Photo No. 9.

A separate concrete emergency spillway is located to the left of the main dam, Photos No. 10 and 11. The upper portion of the weir and concrete side walls are in good condition. The lower regions of the weir show considerable efflorescence. There is one large spall out of the face of the left side wall, Photo No. 12. In back of the side walls are cut quarry stone retaining walls. The left wall primarily, Photo No. 12, contains no mortar in the joints. The right wall, Photo No. 13, has mortared joints but the lower regions of the wall have failed. Stones have fallen to the channel invert below. This wall is considered to be unsafe and on the verge of failure. The downstream channel from the emergency spillway contains considerable debris at the toe of the weir and brush and young trees in the channel further downstream.

The cut stone masonry flood wall located between the main dam and the emergency spillway is in fair condition. Seepage estimated to be 8 to 12 gpm was noted throught the base of the wall near its center. The "head" producing this seepage is 6 in., the difference between the reservoir level and ponded water downstream of the floodwall.

D. <u>Reservoir Area</u>. The area around the Ware Industries Main (Upper) dam and reservoir has variable slopes and is generally wooded with open areas. There were no conditions observed which could cause a sudden increase in sediment load into the reservoir. There is no possibility of a major landslide into the reservoir which could result in a wave overtopping the dam.

E. <u>Downstream Channel</u>. The channel immediately downstream of the main dam is the bed of the Ware River and is in satisfactory condition. The floor of the channel is ledge rock, predominantly amphibole schist with interspersed bands of granite gneiss. There are some rock falls present.

3.2 EVALUATION

Γ

K

Based on visual observations during the site examination, the general condition of the project is satisfactory, although the main dam could not be examined. The dam extension does require repair. The cut quarry stone wall on the right side of the emergency spillway is on the verge of failure. Plans which propose repairs to the emergency spillway are available, Appendix B-5.

SECTION 4 - OPERATIONAL PROCEDURES

4.1 PROCEDURES

Г

·. ·

In general, there are no formal procedures to assure regular maintenance and satisfactory operation of the dam.

4.2 MAINTENANCE OF DAM

There are no established procedures or manuals to assure periodic inspection and maintenance of the dam.

4.3 MAINTENANCE OF OPERATING FACILITIES

The operating facilities in the gate house were operated on a demand basis. The gate house and gates have received minimum maintenance.

4.4 DESCRIPTION OF ANY WARNING SYSTEM IN EFFECT

There is no warning system or emergency preparedness plan in effect for this structure.

4.5 EVALUATION

For a high hazard structure of this size, an annual inspection and maintenance program should be developed. In addition, the Owner should prepare a formal emergency preparedness plan and warning system, since failure of the dam would cause loss of life and extensive property damage.



SECTION 5 - HYDRAULIC/HYDROLOGIC

5.1 EVALUATION OF FEATURES

A. <u>Design Data</u>. No hydraulic or hydrologic design data were found for the original dam. However, proposed repair work to the emergency spillway is shown on two blueline prints prepared by Joseph A. Nowak of Springfield, Massachusetts, dated May 1, 1975. Copies of these prints are included in Appendix B. From the field inspection, it was found that these repairs were never implemented. However, in the absence of any other data, these plans provided an adequate "Site Plan" of the main dam and a cross-section of the emergency spillway which were used as a basis for the hydraulic and hydrologic analyses.

The recommended test flood for the size (small) and hazard potential (high) classification of this dam is between the one half probable maximum flood ($\frac{1}{2}$ PMF) and the probable maximum flood (PMF).

B. Experience Data. The PMF was determined by using the chart prepared by the Corps of Engineers, New England Division, in the Guidelines. The portion of the drainage area upstream of the Barre Falls Dam was excluded because the downstream drainage area will have peaked before the peak outflow from the Barre Falls Dam reaches this dam. Therefore, the PMF was determined on the basis of the 112 square mile drainage area between the Barre Falls Dam and this dam.

A combination of the rolling and mountainous curves were used, tending more towards the rolling terrain. This resulted in a PMF of 109,800 cfs. When the effect of surcharge storage is considered, the PMF is reduced to 109,200 cfs. Because the water surface area of the pond is only 39.5 acres, flood routing techniques were not deemed worthwhile. The value for the ½ PMF is, therefore, 54,600 cfs.

C. <u>Visual Observations</u>. The inspection revealed that the emergency spillway repairs proposed in 1975 were never accomplished. It appeared that the only major change in the original dam was the 50-foot concrete dam extension on the right side. This addition and reconstruction of the emergency spillway were completed after the September 1938 hurricane.

On the day of the inspection, water appeared to flow quite smoothly over the main dam. There was also water flowing from the canal over the overflow weir where the capstone had been removed, cascading down the steep, bedrock slope into the channel downstream of the main dam. The downstream channel is severely overgrown with weeds, brush, bushes and small trees.

The downstream channel has steep, rocky embankments covered with increasing amounts of vegetation as one proceeds downstream and is approximately 60 ft. in width. The channel itself is scattered with cobbles and some scattered large boulders and has a moderate slope. The East Main Street Bridge, which is located approximately 420 ft. downstream of the dam, is a stone arch spanning an approximately 60-ft. width. A cornerstone bearing the date of 1898 was located on the easterly side of the bridge along with a section of what appeared to be the original abutment. The remaining portion of the bridge had been rebuilt after its washout in the 1938 flood.

Downstream of the East Main Street Bridge, the right bank is lined with industries in low lying areas and the left bank reflects the same except that these structures appear to be at a higher elevation. The channel in this portion of the river has similar characteristics as its preceding portion except that it is interrupted by a small dam located approximately midway between East Main Street and South Street. After this dam, the channel widens to approximately 100 ft.

The South Street Bridge is also approximately 100 ft. in width and is basically a concrete structure with a 3-ft. wide center pier. Downstream of this bridge, the left bank contains low lying buildings. The right side is primarily residential. These structures are somewhat protected by a high concrete retaining wall which lines the right bank.

D. Overtopping Potential. Based on the size and hazard classifications published in the Guidelines, the test flood is the PMF. However, the combined capacities of the spillway system (as shown in Appendix D) at El. 470.0 (top of dam) is only approximately 7,980 cfs, whereas the values of the PMF is 109,200 cfs. Therefore, it is evident that the spillway system cannot handle the test flood. The dam would be overtopped by 11.25 ft.

The spillways' inadequacy was also demonstrated in both the 1936 and 1938 floods. In these two storms, there was local flooding in the residential area immediately adjacent to the emergency spillway. In the 1936 flood, the Ware Road Bridge was overtopped, and in the 1933 flood, both the East Main Street Bridge and the South Street Bridge were washed out. Although the main dam was extended after the 1938 storm, the spillway system is still unable to handle flows resulting from an occurence of not only the PMF but also of a 1/2 PMF.

E. <u>Evaluation</u>. As stated previously, the spillway system cannot pass the test flood. In the event of a dam failure, even greater flows would be generated than during the September 1938 storm and excessive economic losses from commercial, industrial, and residential structural damage as well as loss of life would likely prevail downstream of the dam along both banks of the Ware River.

14

Ľ

SECTION 6 - STRUCTURAL STABILITY

6.1 EVALUATION OF EMBANKMENT STRUCTURAL STABILITY

There is no earth embankment included in the Ware Industries Main (Upper) dam.

Although the concrete dam extension has deteriorated and is undermined, it is only 4 ft. high, has a broad base, and is founded on rock. Although a failure is unlikely, such a failure in the absence of failure of the main dam would not cause extensive damage downstream.

The stone masonry flood wall left of the main dam is considered unsafe in the event of the PMF. Again, the wall is about 5 to 6 ft. in height and a failure during the flood would have little additional adverse effect.

6.2 EVALUATION OF SPILLWAY STRUCTURAL STABILITY

D

A. Visual Observations. There was no evidence that movement or distress is present in the main dam, dam extension and emergency spillway. However, the main spillway weir was obscured by flowing water. The cut quarry stone wall on the right side and downstream of the emergency spillway was considered to be unsafe and on the verge of failure, based on the visual observations. A failure of this wall could result in a breach immediately right of the emergency spillway.

B. <u>Design and Construction Data</u>. No design data or construction plans were located for this dam. Data in the form of proposed modifications to the overflow weir at the canal and modifications to the emergency spillway in the form of construction plans were located. Since the geometry (cross-section) of the main dam is not known, it was not possible to determine its structural stability under static loading conditions.

C. <u>Operating Records</u>. No operating records or field measurements are known to exist for this dam.

D. <u>Post-Construction Changes</u>. Due to the differences in concrete, it is estimated that this facility has been through a number of changes. However, other than the previously mentioned proposed changes to the overflow weir from the canal and the proposed changes to the emergency spillway, no documentation for post-construction changes were located. E. <u>Seismic Stability</u>. This facility is located in Seismic Zone 2 and in accordance with recommended Phase I guidelines does not warrant seismic analysis.

Ľ

Ľ

.....



SECTION 7 - ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES

7.1 DAM ASSESSMENT

E

•

. L

A. <u>Condition</u>. The visual examination of Ware Industries Main (Upper) dam revealed that the structure was in good to fair condition. Although there were no signs of structural failure or other conditions which would warrant urgent remedial action, several deficiencies were noted.

Based on the results of computations included in Appendix D and described in Section 5, the spillway is not capable of passing the test flood, which for this structure is the PMF. The PMF outflow of 109,200 cfs would overtop the dam by 11.25 ft. With the water level at the top of the dam, the spillway system can pass 7980 cfs which is 7.3 percent of the test flood.

B. Adequacy of Information. A review of design and construction data is a highly desirable factor in developing a thorough Phase I assessment. However, there were insufficient engineering data available for this dam to allow for such a review. The evaluation of the dam is based primarily on visual inspection, past performance and engineering judgement.

C. <u>Urgency</u>. The recommendations for additional investigations and remedial measures outlined in Section 7.2 and 7.3, respectively, should be undertaken by the Owner and completed within one year after receipt of this report.

D. <u>Need For Additional Investigation</u>. Additional investigations should be performed by the Owner as outlined in the following section.

7.2 RECOMMENDATIONS

It is recommended that the Owner engage a registered professional engineer to undertake the following investigations:

- 1. Determine the dimensions of the various spillway structures, in particular the main dam, in order that mathematical structural stability calculations can be performed.
- 2. Perform hydrologic and structural studies to determine what alternative measures are required to significantly increase the discharge capabilities at the dam.

3. Main spillway weir should be inspected during no flow condition.

7.3 REMEDIAL MEASURES

۲ì

L

A. <u>Operation and Maintenance Procedures</u>. The following remedial work should be undertaken by the Owner:

- 1. Repair the concrete surfaces on the concrete dam extension to prevent continued deterioration of this structure in the future. Loose weak concrete should be removed and the surface restored by the application of concrete mortar, shotcrete or other methods. Areas of contact with bedrock should also be restored.
- Rebuild or otherwise stabilize the cut quarry stone wall at the right side of the emergency spillway. This wall may be stabilized by instituting the proposed revision to the emergency spillway as delineated on drawings now in the hands of the Owner.
- 3. Place mortar in open joints in the left side wall of emergency spillway to prevent loss of stone from this wall.
- 4. Renew the main supports for the gate house structure.
- 5. Clear the downstream channel of the emergency spillway of trees, brush and debris. Complete the clearing and brush removal downstream of the overflow weir.

Because the dam is classified as having a "high" hazard potential, the Owner should prepare an operations and maintenance manual for the dam. The manual should include provisions for biennial technical inspection of the dam and for surveillance of the dam during periods of heavy precipitation and high river water levels. The procedures should delineate the routine maintenance work to be done on the dam to ensure satisfactory operation and to minimize deterioration of the facility.

The Owner should also develop a written emergency preparedness plan and warning system to be used in the event of impending failure of the dam. The plan should be developed in cooperation with local officials and downstream inhabitants.

7.4 ALTERNATIVES

Not applicable.

APPENDIX A INSPECTION TEAM ORGANIZATION AND CHECK LIST

1

í C

1.

	Page No.
VISUAL INSPECTION PARTY ORGANIZATION	1
VISUAL INSPECTION CHECK LIST	
Outlets Works - Spillway Weirs, Approach and Discharge Channels	2
Outlet Works - Gate House and Channels	3
Overflow Weir and Walkway	4

VISUAL INSPECTION PARTY ORGANIZATION

NATIONAL DAM INSPECTION PROGRAM

Dam: Ware Industries Main (Upper)

Date: 12 May 1978

Time: 1100-1445

Weather: High thin clouds and cool (60's F.)a.m. Clear and warm (70's F.)p.m.

Water Surface Elevation Upstream: Approximately El. 464.5 (water level 3" below top of main dam extension.)

Stream Flow: Not known

Inspection Party: Harl P. Aldrich, Jr. Haley & Aldrich, Inc. Roger H. Wood Camp, Dresser & McKee, Inc. Allen W. Hatheway Haley & Aldrich, Inc.

Soils

Structural/Mechanical

Geology

Present During Inspection: John Critchfield, Haley & Aldrich, Inc. Mrs. Edward Beaudin, Ware Industries, Inc. (present parttime)

A-1

VISUAL INSPECTION CHECK LIST NATIONAL DAM INSPECTION PROGRAM DAM: ____Ware Industries Main (Upper) _____ DATE :11 May 78 AREA EVALUATED CONDITION OUTLET WORKS - SPILLWAY WEIRS, APPROACH AND DISCHARGE CHANNELS a. Approach Channel to All Spillway essentially at reservoir Spillways General Condition Good - some reed growth one side of spillway Not visible Floor of Approach Channel b. Weirs and Training Walls, Main Dam and Extension General Condition Main dam spillway not visible due to flowing water. Right side wall of main dam deteriorated and undercut at downstream end. Left side wall main dam has loose masonry blocks downstream end. Concrete dam extension is undermined at right and left sides. Seepage under wall appears to be present. Efflorescence present downstream face. Top of spillway deteriorated at both ends c. Discharge Channel Below Main Dam General Condition Satisfactory (bed of river) Loose Rock Overhanging Could not examine (see photographs Channel of rock faces) Trees Overhanging Channel Some young tree growth in channel and at sides, but not significant Bed of river is bedrock; some large blocks of stone and concrete Floor of Channel (cannot examine most of floor because of water) Other Obstructions None of significance observed 4160 ĝ A-2 HALEY & ALDRICH, INC. CAMBRIDGE, MASSACHUSETTS

T

R

ſ

DAM: <u>Ware Industries Mai</u>	in (Upper) DATE: <u>11 May</u> 78
AREA EVALUATED	CONDITION
1. Emergency Spillway	
General Condition	Sixteen-foot long concrete weir with concrete abutments in good to excellent condition. Masonry wall behind concrete abutment on left side has open joints. Wall behind right abutment downstream of weir has missing blocks and is on the verge of collapse
Emergency Spillway	
General Condition	Poor; piled debris at toe of weir and channel floor wooded. Granite masonry wall on right side of spillway in poor condition
Loose Rock Overhanging	None observed
Channel Trees Overhanging Channel	Yes, numerous
Floor of Channel	Wooded; irregular; some debris
OUTLET WORKS - GATE HOUSE	
Approach Channel	
General Condition Bottom Conditions Log Boom Debris Condition of Walls	Good Not visible None present Light material Stone masonry construction with open joints, fair condition
. <u>Gate House</u>	
General Condition	Fair. Timber building with no shingles. Four pieces of siding missing. Main support truss has deteriorated panel point None observed
. Mechanical and Electrical	Electrical service has been discon-
	tinued

u
VISUAL INSPECTION CHECK LIST NATIONAL DAM INSPECTION PROGRAM

DAM: <u>Ware Industries Main (Upper)</u> DATE: <u>11 May</u> 78

1

AREA EVALUATED	CONDITION
Service Gates	Tota! of five rack and pinion gates, in working condition but have received little maintenance. Gates are 5 ft. wide, estimated to be 4 to 5 ft. high
d. <u>Downstream Channel</u>	
General Condition of Walls Erosion or Cavitation Alignment Channel Floor	Masonry walls with open joints Joints are wider at water surface Alignment of stones good Not visible
OVERFLOW WEIR AND WALKWAY	
a. <u>Overflow Weir</u>	Overflow weir of cut quarry stone with granite cap stone. Horizon- tal and vertical alignment are good. One cap stone removed for pilot channel. Weir joints show loss of mortar. Moss growth present on weir. Stone training walls are in fair condition. Upstream channel has no training walls and contains brush. Channel is filled at right end for vehicle access. Downstream channel is bedrock with some boulders and medium tree growth. Center section has trees and brush removed recently and piled along the left side wall
b. <u>Walkway</u>	Walkway bridge is in good condition but is in need of repainting. Several timber pier caps have large cracks present. Bridge bearing areas are good
HALEY & ALDRICH, INC.	A-4

APPENDIX B LIST OF AVAILABLE DOCUMENTS AND PRIOR IN. ECTION REPORTS

Page No.

1

3

4

5

6

LIST OF AVAILABLE DOCUMENTS

SELECTED RECORDS

1 [[

) **F**(

"Location Plan, Main Dam Repairs", Drawing No. D-1948-1, Joseph A. Nowak, Springfield, MA, 1 May 1975

"Site Plan, Main Dam Repairs", Drawing No. D-1948-2, Joseph A. Nowak, Springfield, MA, 8 May 1975

"Emergency Spillway Repairs, Main Dam Repairs", Drawing No. D-1948-3, Joseph A. Nowak, Springfield, MA, 1 May 1975

"Flow Calculations", Joseph A. Nowak, Springfield, MA, 22 April 1976

PRIOR INSPECTION REPORTS

Date

Ву

26	June	1970	Tighe & Bond Consulting Engineers for the Hampshire County Commission	9
15	March	1976 i	Mass. Department of Envir- onmental Quality Engineering	11

	LOCATION	Mass. Department of Environmental Quality Engineering, 100 Nashua Street, Boston, MA, 02114 and Appendix B-3	Nenameseck Industrial Properties, Inc., East Main Street, Ware, MA 01082 and Appendix B-4	Nenameseck Industrial Properties, Jnc., East Main Street, Ware, MA 01082 and Appendix B-5	Nenameseck Industrial Properties, Inc., East Main Street, Ware, MA 01802 and Appendix B-6	Hampshire County Com- missioner's Office, Hampshire County Court- house, Northampton, MA 01060 and Appendix B-9	Mass. Dept. of Environ- mental Quality Engineering 100 Nashua Street, Boston, MA 02114
AVAILABLE DOCUMENTS RIES MAIN (UPPER) DAM	CONTENTS	50 scale location plan	20 scale site plan	Plan and section for proposed repairs	Site data, flow records and flow calculations for various situations	States condition and deficiencies of dam	Results of reconnais- sance study of water resource problems along the Ware River in Ware, Massachusetts
LIST OF WARE INDUST	DOCUMENT	"Location Plan, Main Dam Repairs", Drawing No. 1, Joseph A. Nowak, Springfield, MA, 1 May 1975	"Site Plan, Main Dam Repairs", Drawing No. 2, Joseph A. Nowak, Springfield, MA, 8 May 1975	"Emergency Spillway Repairs, Main Dam Repairs", Drawing No. 3, Joseph A. Nowak, Springfield, MA, 1 May 1975	Flow Calculations, Joseph A. Nowak, Springfield, MA, 22 April 1976	Inspection report by Tighe & Bond Consulting Engineers for the Hampshire County Commissioner dated 26 June 1970	Letter from NED, Corps of Engineers, to Town of Ware, dated 31 October 1973

Ţ

i R

ł

Z

led)	LOCATION	Mass. Dept. of Environ- mental Quality Engineering, 100 Nashua Street, Boston, MA 02114 and Appendix B-11 Marking B-11		
OF AVAILABLE DOCUMENTS [ES MAIN (UPPER) DAM (Continu	CONTENTS	States condition and deficiencies of dam		
LIST WARE INDUSTRI	DOCUMENT	Inspection reports by the Mass. Dept. of Environmental Quality Engineering, dated 22 August 1973, 17 January 1974 and 15 March 1976	в-2	

ŀ

. . .







• •		desten 1	12141173	/22/76 <u>/148</u>
•		WOREIN	OUSTRIES "	ALS ENO.
		19.41.01		· .
	FLOW CAL	CULATION	V_	Õ
1. <u>SITE</u>	DATA FOR C	ALCULA	VONJ	
TEM	<u> </u>	LENGT	<u>د</u> ۲	M DAM
MAIN DA	LA .	463. B	115'	-
OVER FLOL	w worr	463.3	115	+0.1
NO. DAM.	STENJION	AL 4. 8	50	+1.0
EMERGEN	cy Jpill way	466.9	/6 ·	
WAST RES	ALL WALL	470. C		+6.2'
64TE NOL	VE WALL	470.0		+6.2
	•-			_ · · ·
a. 641	CLOURA:	OVER PO	our co	115° 3/2
a. 641 (E CLOURA D= 3.33'x 115 = <u>383</u> CA	0484.8 (464.8 5 <u>2</u> 4	.our 2 = - 1 (s. 8) 1 <u>8. 2</u> M	115° ¥2 60
а. сфі с в. сфіга (маля	E CLOSEA = 3.33' × 115 = <u>383</u> CA = 04A4 + 0464	0484.8 (464.8 <u>24</u> FER FLOW	- 4(5. 8) - 4(5. 8) - 8. 2 M - 2 = 23 - 2 - 23 - 2 - 23	115° 3/2 60
Q. GAT Q. B. GAT (MAIN	CLOSEA: D= 3.33' × 115; = <u>383</u> CA = CAEA + CEA OAA + CEA Q= <u>766</u> CA	0484.8 464.8 5 7 7 7 7 7 7 7 7 7 7 7 7 7	- 4 (3. 8) - 4 (3. 8) - 8 - 2 - 8 - 1 - 8 - 1 - 8 - 10 - 10 - 10 - 10 - 10 - 10 - 10 - 10	115° 3/2 60 10° ¹ 10°
а. САТ 6. САТ (Мал 3. <u>Есоци</u> я <u>Мая</u>	CLOSEA = 3.33' × 115 = <u>383</u> CA = 000 A + 000 04A + 0000 04A + 000 04A + 000 04A + 0000 04A + 0000 00	00 SA PA (464. 8 5 <u>24</u> 7 CA PLOUA FCOW W 1 <u>89</u> 4 CA CAN 3.1'	- 1 (5. 8) - 1 (5. 8) - 2 - 2 3 - 2 - 2 - 2 3 - 2 - 2 - 2 3 - 2 - 2 - 2 - 2 3 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2	115 · 3/2 CO 10 · · · · 0 C. · · · ·
а. САТ 6. САТ (Маля 3. <u>Геоц</u> ия <u>Мая</u> а. <u>САТ</u> Мал Мо.	CLOSEA = 3.33' × 115 = <u>383</u> CA = 0AA + 0+ CA OAA + 0+ CA OAA + 0+ CA <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>COLA</u> <u>C</u>	0	(3.1) % -	M5 3/2 CO CO CO CO CO CO CO CO CO CO
а. САТ 6. САТ (Маля 3. <u>Геош</u> я <u>Мая</u> а. <u>САТ</u> Мал Мо.	CLOSEA: = 3.33' × 115; = <u>383</u> CA = 0AAA + 0+ CA 0AAA + 0+ CA Q = <u>766</u> CA <u>4 CAA</u> <u>CA</u> <u>6 CLOSED</u> ; = 0 AAA; 0 = 1	04.5.4.8 24.4.8 7.2.4.20 7.2.4.00 7.2.60	(3.1) % =	115" 3/2 CO 10"""" 10""""""""""""""""""""""""""""

Ľ

, ,

<u>1949</u>	
. WARE IND	
G	. 1
O. CATE OPEN;	
MANN DAN: Q = 3.33 × 115 × (3.1) 1/2 = 2.030	
NO. EXTEN: 0 = 3.33×50 × (2.1) × = 507	
OV. WEIL : Q = 3.33 × 115 × (3.1) 4 = 2,030	
4.663 641	
A FARARANCY SPILL WAY IN ACTION	•
WATER LEVEL . ALS. 2	
a. CATES CLOUED	
MAIN DAM; Q=3.33 x 115 x (463.2 - 463.6) " . 4.805.4	
10. Ext : Q = 3.334 50 x (463.2 - 464.0) = 3 /, 536.7	
EM. SPILL : Q = 3.332 R X (463.2-466.3) - = <u>183.0</u> C 523 J	
D. CATEJ OPEN :	
MAIN DAM: Q = 4,805. 4 CAU	
OV. WEIR : Q = 4.205.4	
AB, EFF : G = 7, 336, 7	
EM. 17/22: 4	
5. FLOW RECORDS (GIRAS CROSSING)	• •
(AOUCOTANENTU POR DIVERJON)	
AVERALE di VERALI DISSI - 319 CEU	
LAINING UN FLOW TO 1353 = 7 CAU	
PLODO, MARCH, 1936 - 18.200 CF4	
FLOOD, SEPT. 1338 = 22,700 CPS	
FLOOD, AUG. 1955 72,200	
BARRE FALLS DAMA IN OPBRATION	
FLOOD OF SEAF, 1838 = 17, 200 CFy	• •
B-1	

.

IJ

134 B WALS INA. CALCULATIONS & NOTES MAR OPTIONS 1. NORTH DAM BITENSION REMOVED THIS WOULD LOWER RIVER LEVEL TO SLEV. OF ROCK ON MORTH SIDE, OR Q = 3.0 MAIN DAM. 460.8 ± ELEV. A. FLOW TO REACH MAIN DAM LAVEL 463.8 Q3 3.33 x 50'x (3.4) 3/2 - 865 CFS > 819 CFJ. A+6. b. CATES OPEN: WATER LEVEL = 466.9 EM. JALL NO. GATENSION . 3.33 + 50 + (446.3 - 460.2) = 2,50 2 2,030 MAIN QAM 2,010 OVERFLOW WEIR = 6,688 CPU THIS IS GREATER THAN & KO CAN (MAN-MANO) 2. OVER BLOW WEIR LOW BRED 1.0' TO BL 463.3. <u>GATEN ALWANN OPEN</u> G: J. 3. x 115'x (1) ¹ = <u>383</u> CF X > 318 CFJ A. RIVAR LEVEL AT BL. ACA. C a h= +1.0 MAIN OAM WEIR - Q = 3.33 × 115' × (44 + e - 44) e) 1/2 = 1,083 DAM - 3.33 + 115' × (1') 42 = <u>383</u> 383 CAV 1,466 643

в**-8**

JETRGE - WOODNNELL amilia N SHERIDAN EDWARD J BAYON

C

TIGHE BOND CONSULTING ENGINEERS_

CIVIL SANITARY AND ELECTRICAL ENGINEERING INVESTIGATIONS REPORTS PLANS AND SPECIFICATIONS SUPERVISION OF CONSTRUCTION AND OPERATION

> BOWERS AND PEQUOT STREETS HOLYOKE MASSACHUSETTS TEL JEFFERSON 3-3991

H-36 Ware June 26, 1970

The Honorable the Board of County Commissioners Hampshire County Courthouse Northampton, Massachusetts

Gentlemen:

Attached hereto is our inspection report on dams located within the Town of Ware. We are including herewith, suggested letters to be sent to four dam owners, three of which indicate necessary repairs, and the fourth letter is sent at the request of the dam owner, as he wishes to have a letter of notice on file that his dams were observed to be satisfactory.

Very truly yours,

Tighe & Bond, Inc.

George/H. McDonnell Chief Engineer

GHM/amd Encl.

The remaining portion of the dam is estimated to be only 3 ft. to 4 ft. in height and little or no water is stored. Actually, the dam is nothing more than a shallow waterfall in the stream.

-7-

The dam does not present any danger to persons and property as it now exists.

K. Ware Industries Main Dam - Upper

The concrete crest of the main dam shows further evidence of erosion, particularly at the downstream edge. On the day of inspection no flashboards were on the crest of this dam which extends across the width of the stream, and water was overflowing the entire crest length. Based upon the amount of water passing over the crest and little evidence of any motion in the adjacent canal, it would appear that the industry is using little or no water from the pool in back of the dam.

Because of the heavy flow of water over the crest, the toe of the dam in the bed of the stream could not be inspected. However, since the bed of the stream is ledge, there is little doubt but what the toe of the dam and its foundation are o.k.

The left abutment stone masonry wall is satisfactory. The right stone masonry and concrete abutment was also satisfactory. Conditions on the natural ledge at the right abutment are o.k.

The emergency concrete overflow spillway upstream of and to the left of the main dam was noted to be in satisfactory condition with the exception that at the right stone masonry abutment wall just downstream from the concrete overflow, there has been a failure at the face of the wall. Stones above the failure are improperly supported and seepage which takes place thru this area of the wall will undoubtedly contribute to further failure with the passing of time. Should this stone masonry wall fail as a result of collapse of the unsupported stone masonry, the failure might have an undesirable effect on the left abutment wall of the main dam located 20 ft. to 25 ft. behind the damaged wall. Thus, the industry should carefully examine the failure at the stone masonry wall as pointed out herein and should provide proper support, thru repair of the walls, for the upper stone blocks forming the wall. INSPECTION REPORT - DAMS AND RESERVOIRS

İ

R

.

. La

P

.

. . .

!•

	Casty/Town_Ware_	County_Har	pahire	Dam No	2-8-309-9
	Name of Dam Ware L	ndustries Main Dam "uppe	r"		
	1122 02 102	Mass. Rect.	600 E koo		•
	Topo Sheet No. 170	Coordinates: N_400,	, <u>E 400</u>	.900	•
	Inspected by: Harol	d T. Shumway , On Mar	Dat <u>Ch 15, 1976</u> . Las	e t Inspectio	8-22-73 m <u>1-17-74</u>
2.					
1	OWNER/S: as of M	arch 15, 1976			
	per: Assessors	_, Reg. of Deeds,	Prev. Insp. <u>X</u> ,	Per. Contac	st
	1. Ware Industries,	Inc. East Main St., War	e, Mass.	C+-+-	Tel No
	Name	St. & NO.	3339/10W1	State	TET NO.
	2	0+ · · N-	Ci +== /T== =	State	Tel No.
	Name	Jt , α №0.	CI CJ / LOWE		1674 104
	3	St // No	City/Town	State	Tel. No.
35	3 Name	St. & No.	City/Town	State	Tel, No.
35	3. <u>Name</u> CARETALER: (if any absente	St. « No.) e.g. superintendent, j owner, appointed by m	City/Town Dlant manager, appo	State inted by	Tel. No.
3.	3. Name CARETALER: (if any absente	St. « No.) e.g. superintendent, p e owner, appointed by mu	City/Town Dlant manager, appo Liti owners.	State	Tel. No.
3.	3. Name CARETALER: (if any absente Edward Beaudin, Su Name	<u>St. & No.</u>) e.g. superintendent, r e owner, appointed by mu upt., Ware Industries, I St. & No.	City/Town plant manager, appo plti owners. <u>nc., East Main St.</u> City/Town	State inted by . Ware. Ma: State	Tel. No. ag. Tel. No.
3.	3. Name CARETALER: (if any absente Edward Beaudin, Su Name	St. & No.) e.g. superintendent, p e owner, appointed by mu upt., Wars Industries, I St. & No.	City/Town Dlant manager, appo llti owners. inc., East Main St. City/Town	State inted by . Ware, Mar State	Tel. No. 33. Tel. No.
3 .	3. Name CARETALER: (if any absented Edward Beaudin, Su Name	St. & No.) e.g. superintendent, r e owner, appointed by mu upt., Ware Industries, I St. & No.	City/Town plant manager, appo plti owners. <u>inc., East Main St.</u> City/Town	State inted by . Ware, Man State	Tel. No. 93. Tel. No.
3.	3. Name CARETALER: (if any absented Edward Beaudin, Su Name DATA: No. of Pictu	<u>St. & No.</u>) e.g. superintendent, r e owner, appointed by mu upt., Wars Industries, r St. & No.	City/Town plant manager, appo ulti owners. <u>nc., East Main St.</u> City/Town tches_ <u>See descripti</u>	State inted by . Ware. Mar State	Tel. No.
3.	3. <u>Name</u> CARETALER: (if any absented Edward Beaudin, Su Name DATA: No. of Pictu Plans, Where	<u>St. & No.</u>) e.g. superintendent, p e owner, appointed by mu upt., Wars Industries, I St. & No. res Taken_None Sket	City/Town blant manager, appo llti owners. <u>ne., East Main St.</u> City/Town tches <u>See descript</u> i	State inted by . Ware, Mar State .on of Dam.	Tel. No. 33. Tel. No.
3.	3. <u>Name</u> CARETALER: (if any absented Edward Beaudin, Su Name DATA: No. of Pictu Plans, Where	<u>St. & No.</u>) e.g. superintendent, j e owner, appointed by mu upt., Wars Industries, I St. & No. res Taken <u>None</u> . Sket	City/Town plant manager, appo ulti owners. <u>nc., East Main St.</u> City/Town tches <u>See descripti</u>	State inted by . Ware, Mar State .on of Dam.	Tel. No.
3. 	3. Name CARETALER: (if any absented Edward Beaudin, Su Name DATA: No. of Pictu Plans, Where	<u>St. & No.</u>) e.g. superintendent, r e owner, appointed by mu upt., Wars Industries, r St. & No. res Taken <u>None</u> . Sket	City/Town plant manager, appo ulti owners. <u>inc., East Main St.</u> City/Town tches_ <u>See descripti</u>	State inted by . Ware. Ma: State	Tel. No.
33 33 33 33 33 33 33	3. <u>Name</u> CARETALER: (if any absented Edward Beaudin, Su Name DATA: No. of Pictu Flans, Where DEGREE OF HAZARD:	<u>St. & No.</u>) e.g. superintendent, y e owner, appointed by mu upt., Wars Industries, I St. & No. res Taken <u>None</u> . Skew (if dam should fail com	City/Town blant manager, appo llti owners. <u>inc., East Main St.</u> City/Town tches <u>See descripti</u> pletely)*	State inted by . Ware, Mar State	Tel. No.
33. 4.)	3. <u>Name</u> CARETALER: (if any absented Edward Beaudin, Su Name DATA: No. of Pictu Plans, Where DEGREE OF HAZARD: 1. Minor_	<u>St. & No.</u>) e.g. superintendent, p e owner, appointed by mu upt., Wars Industries, I St. & No. res Taken <u>None</u> . Sket (if dam should fail com	City/Town Dlant manager, appo lti owners. <u>inc., East Main St.</u> City/Town tches <u>See descripti</u> pletely)* 3. Severs	State inted by . Ware, Mar State .on of Dam.	Tel. No.
	3. Name CARETALER: (if any absented Edward Beaudin, Su Name DATA: No. of Pictur Plans, Where DEGREE OF HAZARD: 1. Minor_ 2. Moderate	<u>St. & No.</u>) e.g. superintendent, r e owner, appointed by mu upt., Wars Industries, r St. & No. res Taken_None Sket (if dam should fail comp	City/Town plant manager, appo plant owners. <u>inc., East Main St.</u> City/Town tches <u>See descripti</u> pletely)* 3. Severs 4. Disastrous	State inted by . Ware. Ma: State .on of Dam.	Tel. No.

	- 2 -
-	·
6. ouri	ETS: OUTLET CONTROLS AND DRAWDOWN
	Approx. center of dam - crest overflow spillway 114: W
NG	a dropwall 35' high.
	Controls 185, TYPE: Provisions for stop logs
	Automatic Manual_X Operative Yes, No_X
	Comments: Most of stanchion pins bent or broken off
Ne	. 2 Location and Type: 80' easterly of east and of dam a sore awarfly, and liver
	10' W. X 2' H. with 15'+ high dropwall.
	Automatic Manual Operative fes, No
	Comments: Spillway crest 3.4' above creat of main apillway. Slight spalling of easterly abut.
No	. 3 Location and Type: See report on Wars Industries Canal Dam "Upper" No. 2-8-3
	Controls, Type:
	Automatic Manual Operative Yes, No
Dr	Strictm Treserit Yes Y No . Uperstive Yes w . No
Co	ments: See Inspection Report on Dam No. 2-8-300-10
~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	mments: See Inspection Report on Dam No. 2-8-309-10
	UPSTREAM FACE: Slope 3:1 variable, Depth Water at Dam 52' to 6'
Cc (7.) DAM Ma	UPSTREAM FACE: Slope 3:1 variable, Depth Water at Dam 52' to 6' 
Cc (7) DAM Ma	UPSTREAM FACE: Slope 3:1 variable , Depth Water at Dam 52' to 6'
Cc To DAM Ma Ot	UPSTREAM FACE: Slope <u>3:1 variable</u> , Depth Water at Dam <u>51</u> ' to <u>6'</u> . terial: Turf Brush & Trees Rock fill Masonry <u>I</u> . Wood
Cc (7) DAM Ma Ot Cc UI	UPSTREAM FACE: Slope 3:1 variable , Depth Water at Dam 52' to 6' iterial: Turf Brush & Trees Rock fill Masonry XWood her indition: 1. Good 3. Major Repairs
Cc T DAM Ma Ot Cc U1	UPSTREAM FACE: Slope <u>3:1 variable</u> , Depth Water at Dam <u>52</u> ' to <u>6'</u> . terial: Turf Brush & Trees Rock fill Masonry <u>I</u> . Wood ther ndition: 1. Good <u>3. Major Repairs</u> known 2. Minor Repairs_ <u>I</u> . <u>4. Urgent Repairs</u>
Cc T DAM Ma Ot Cc UI Cc	UPSTREAM FACE: Slope 3:1 variable , Depth Water at Dam 52' to 6' uterial: Turf Brush & Trees Rock fill Masonry I Wood ther mainton: 1. Good 3. Major Repairs known 2. Minor Repairs I 4. Urgent Repairs ments: Slope under water - not possible to determine exact grade on condition
Cc T DAM Ma Ot Cc U1 Cc	UPSTREAM FACE: Slope <u>3:1 variable</u> , Depth Water at Dam <u>52</u> ' to <u>6'</u> . terial: Turf Brush & Trees Rock fill <u>Stone</u> iterial: Turf Brush & Trees Rock fill <u>Masonry I</u> Wood ther mdition: 1. Good <u>3. Major Repairs</u> Minor Repairs <u>2. Minor Repairs</u> ments: <u>Slope under water - not possible to determine exact grade on condition</u> <u>of slope.</u>
Cc T DAM Ma Ot Cc Cc Cc	UPSTREAM FACE: Slope 3:1 variable , Depth Water at Dam 52' to 6' uterial: Turf Brush & Trees Rock fill Masonry I Wood her ndition: 1. Good J. Major Repairs known 2. Minor Repairs I4. Urgent Repairs ments: Slope under water - not possible to determine exact grade on condition of slope
Cc T DAM Ma Ot Cc U1 Cc Cc U2 Cc U2 Cc	UPSTREAM FACE: Slope J:l variable , Depth Water at Dam 52' to 6'
Cc T DAM Ma Ot Cc Un Cc Un Cc Ma Ma Ma	under in itematical intervalues in the intervalue intervalue intervalue intervalues
Cc T DAM Ma Ot Cc UI Cc UI Cc UI Cc UI Cc UI Cc UI Cc UI Cc UI Cc UI Cc UI Cc UI UI Cc UI UI Cc Cc UI UI Cc Cc UI UI Cc Cc Cc Cc Cc Cc Cc Cc Cc Cc	UPSTREAM FACE: Slope <u>3:1 variable</u> , Depth Water at Dam <u>52</u> ' to <u>6'</u> . uterial: Turf Brush & Trees Rock fill Masonry <u>X</u> . Wood ther indition: 1. Good <u>3. Major Repairs</u> indition: 1. Good <u>4. Urgent Repairs</u> indinown 2. Minor Repairs_ <u>X</u> . <u>4. Urgent Repairs</u> imments: <u>Slope under water - not possible to determine eract grade is condition</u> of slope.  DOWNSTREAM FACE: Slope <u>Vertical</u> . terial: Turf Brush & Trees Rock Fill <u>Masonry_X</u> . Wood
Cc T DAM Me Ot Cc Un Cc Un Cc Un Cc Un Cc Un Cc Un Cc Un Cc Un Cc Un Cc Un Cc Un Un Ne Cc Cc Un Ne Cc Cc Un Ne Cc Cc Cc Cc Cc Cc Cc Cc Cc Cc	<pre>under preder res</pre>
	<pre>under product res no operative res no mments: See Inspection Report on Dam No. 2.8_309-10 UPSTREAM FACE: Slope 3:1 variable Depth Water at Dam 52' to 6' iterial: Turf Brush &amp; Trees Rock fill Masonry XWood her ndition: 1. Good 3. Major Repairs nknown 2. Minor Repairs 4. Urgent Repairs mments: Slope under water - not possible to determine exact grade on condition of slope.  DOWNSTREAM FACE: Slope Verticel .terial: Turf Brush &amp; Trees Rock Fill Masonry_XWood her ndition: 1. Good 3. Major RepairsX</pre>
Cc T DAM Me Ot Cc Un Cc Un Cc Un Cc Un Cc Un Cc Cc Un Cc Cc Un Cc Cc Un Cc Cc Un Cc Cc Un Cc Cc Cc Cc Cc Cc Cc Cc Cc Cc	<pre>understand present res</pre>

È.

: •
<u>рам мо.</u> 2-8-309-9
- 3 -
DEFERGENCY SPILLHAY: Available Yes Needed
WARLR LEVEL AT TIME OF INSPECTION: Ft, above For Dam F.L. Principal Spillway
Otter
Normal Freeboard 1 Ft. North, 62' South
GIGINRY OF DEFICIENCIES NOTED: Growth (Trees and Brush) on Embankment
Animal Burrows and Washouts None found
Yes, severe spalling of concrete spillway cap and tops of walls on westerly end of dam. Yes, see above-also severe spalling of downstream
Cracked or Damaged Masonry Stones from Sile walls of emergency Splinkay.
Evidence of Seepage flood training wall and ledge.
None found Evidence of Piping
Leaks Yes, see above seepage notes
Erosica None found
Trash and/or Debris Impeding FlowNone found
Clogged or Blocked Spillway None found
Coper

.

DATE	1775	2-8-30	9-9
التحاسا			

B-14

VERALL CONDITION:

1. Safe

- 2. Minor repairs needed
- 3. Conditionally safe major repairs needed
- 4. Unsafe______.

5. Reservoir impoundment no longer exists (explain)

Recommend removal from inspection list_

## 3- REMARKS AND RECOMMENDATIONS: (Fully Explain)

Conditions at this dam were found to be the same or slightly worse than when last inspected on January 17, 1974. Refer to inspection report of January 17, 1974, Remarks and Recommendations, for a detailed description of these problems. Further deterioration has occurred on the lip of main spillway, with a very ragged lip now evident. One foot deep overflow of water on main spillway prevented close inspection of dropwall or toe of dam. Severe seepage was noted in area of westerly abutment or sidewall of emergency spillway where several stones are misplaced. Only slight seepage was noted here two years ago.

x

The rubbish and debris noted, in last inspection at base of emergency spillway dropwall has been cleared away but a fresh accumulation ofdebris was noted at this inspection. Mr. Edward Geaudin, Supt. of Ware Industries, was present during this inspection. He stated that a consulting firm has been retained by the company for investigation of problems concerning this dam and at present time it appears to be a question of whether to repair or dismantle the dam. Mr. Beaudin stated that Ware Industries, Inc. is holding a director's meeting in the near future and a decision should be made at that time as to the course of action the owners will take concerning dam.

HTS:ma

1

	APPENDIX C		
SELECTED	PHOTOGRAPHS	OF	PROJECT

Page	No.

## LOCATION PLAN

Site Plan Sketch

PHOTOGRAPHS

ſ

•

7 6

No.	Title	<u>Roll</u>	Frame	Page No.
1.	Overview of main dam	4	1	
2.	Overview of main dam and left abutment	4	1,2	2
3.	Overview of main dam and right	4	16,18	3
4.	abutment Downstream side of concrete	4	14	4
5.	dam extension Right end of concrete dam	4	11	4
6.	extension Left end of concrete dam	4	10	5
	extension		10	5
7.	Concrete pier between main dam and concrete dam extension	4	12	5
8.	Overflow weir with wood walkway	4	8A	6
9.	Approach to overflow weir	4	6	6
10.	Upstream side of emergency	4	22	7
11.	Right abutment of emergency	4	21	7
12.	spillway Stone wall below left abutment	4	19	8
13.	of emergency spillway Stone wall below right abutment of emergency spillway	4	20	8









6

4. Downstream side of concrete dam extension



C-4

5. Right end of concrete dam extension



6. Left end of concrete dam extension

10

F



7. Concrete pier between main dam and concrete dam extension

C-5



8. Overflow weir with wood walkway

i

P



9. Approach to overflow weir from canal

C-6





[(

Ľ

12. Stone wall below left abutment of emergency spillway



13. Stone wall below right abutment of emergency spillway

C-8

## APPENDIX D OUTLINE OF DRAINAGE AREA AND HYDRAULIC COMPUTATIONS

Page No.

## OUTLINE OF DRAINAGE AREA

Drainage Area Map	1
COMPUTATIONS	
Size and Hazard Classification Reservoir Surface Area Graph PMF Flow Calculations Plan View of Dam and Spillway System Spillway Rating Curve Final PMF Flow Calculations Dam Failure Analysis	2 3 4 5 6 10 11



1 L'inco CAMP DRESSER & MokEE DUENT PAGE_ DATE PROJECT 27000 2000 DATE CHECKED 2-28-28 CHECKED BY DETAIL CLA MANA COMPUTED BY 512 Classification and Hazard Classification Top of Dam = 470.0'. Height: Elevation of Stream bed = 430' Height and Feet Too of Dam = 470' & sed = 459' ·· ····· ----Storage = 146 Acre - Test _____ ---. . . . . . . . ____ 256 40 6 50 ____ 30_Size is SMALL Howard: Or the basis of the destruction endse by the flood waters of both the 1930 and 1938 Floods, it will be initially assured that the hazard class flooten will be HISH. D For Small JILL and High Hickord - The spill way . Congo Flood is in The range of the is PMF + PIMF ----in a constant of the second of -----. . . . . -- -..... . . -...... D-2

.08 NO _____ 30F CAMP ORESSER & MCKEE PAGE. DATE CHECKED 9-38-78 the second second 7 DATE. PROJECT onmental Engineers CHECKED BY DETAIL COMPUTED BY on. Man 400 ---liserioir Area va. Elevanor ----------- - - -..... . . . . . . . . . . . . . . . _ .... . . . . . . _..... 317A_ - --300. . ..... . ..... ____ . .. . 1.94. ----Prost with . . . . ---------- 100 -- - ----------. . . . . . . . ------ --0 10 ____ ____ _ _ . . . . 480 1 481.7 490 440_____470____ ------ح دا جي ---------Elevation (H. msl) ----····· - ---------. .- --. . . . .... . ...

.08 NO 51-1-0- 27 SLENT in ey and A area CAMP ORESSER & MCKEE 170 DATE momental Engineers TED BY Calculation of PHF U.5.6.5 Gaging Station at Gibbs Gossing, MASS. or kare Ever: HISTORICAL FICCOS -Mairmum Obcharge - 22700 L.F.S. on Sept. 21. 1938 :. Q₁₉₃₈ - 22,700 155 ; 119.105 m 1099. 59. mi _ 50 QA38 = 114.1com X 1.67.39, m: 19,055 6.F.J. w.T. ----since dam constructed at Barre Falls, deleted drainage area wastream of Barre Falls Barroir _____ 19055 c.f.s. x (167-55) = 12779 cf.s. , 30 FSr 112 39, m21-, Quis 12779 CFS 304 12 For PMF, use average of mountainous and -rolling curves. Q~980 cfs/39 m; X_112 39, mi = 109.760 c.F.s. -----. ... . . . -. - -. . . ----------

Ĩ

SLENT -10:0, and Alance :08 NO ------CAMP DRESSER & MOKEE PAGE. DATE mental Engineers DETAIL de Construct CHECKED BY OFfiler -COMPUTED BY Mass -----PER Lew of Came with Various Jp: 2045 (LiT.S.) . . . ----ے ہ 2 OATA 18 Langth Spillway. Crest ... asmatin (+2) Eler. (H) 466.9 16'0 5A .... 58 463.8 32 465.8 469.45 30 SE 466.35 ~85ª 120' 469,8 AJF ASG 470,0 . ..... __ . . . ------ - - -- --אלי אלי אליים יצאי יצר . גיפעי ואלי גער . . .... .. .. .

C

(r

CLENT -CAMP OPESSER & MCKEE -----C'man. Environmental Engineers PROJECT .... وموجا المحاصرات DETAIL

Boston Mess

Ic

Ľ

1

9-28-78 DATE CHECKED. Ænder-CHECKED BY_

PAGE DATE -COMPUTED BY.

Somery lating Line چند الم الم - 0

For	"L' pue,	King & Braters	Handbook	of Hydrou 12
Fiqui	e 5-22 (.	mayion staced	(م ب ف ند	

Ezr. Flows 7.00 cFior эA 1B 3E___ سم تر کم فأتتهم 52 (يسم س ---0 ___0 463.8 0 0 0 0 0 0 463.9 00 13 0 0 000000000000000 00000000000000 4/20 Q 4/20 Q 4/20 Q 4/20 Q 4/20 Q 4/20 Q 000 0 ~ O. ڪ جي 0 0 407 0 N00000 535 1321 1507 12 _ 0 16 7年103 00452 444.Q. 233 358 46.9 2250 528 109 2/53 32/7 467.0 561 933 193 25 463.0 803 469.C 127 4432 1399 252 322 1537 4692 260 5493 1317 2223 470.0 340 220 5770 1927 2025 720 I 3770 10429 390 2509 432 430 3287 9140 33140 750 4070 472.0 600 539 1 33 473.0 479.0 7559 .723_ 650 5963. ست و وَم 2378 982 12175 707 7358 3120 476.0 6091 7793 1020 1297 1594 1912 5:32 15927 تحقي وا 1427 4265 472.0 1923 20,000 13228 6437 3325 7000 11772 7630 11592 24370 *cac.0* 2466 17537 2333 29019 33932 3051 21530 922.0 16212 3677 13671 2208 25786 19782 434.0 20429

Los: At " exerction 470, a large portions of over one find accurs on the cost side of cland. The opene to -clore not include this Flow.

Ht to dams lever . 470), Quer . 10,777 . 34 10,300 2. 43.

And Strates 7051 OLENT CAMP DRESSER & MCKEE PAGE_ PROJECT LICTION COM CTO DATE CHECKED 92818 DATE Environmental Engineers DETAIL CICLE IN ISTY IS CHECKED BY ETUICE Boston, Mass. COMPUTED BY Sterors Ner The over and wein' Folo_abound be instruced in The previous canculations though. On the unsterly The provise calculations through a subject more a side of the dame, the land slopes very steeply (approximately of feet in clouding in 100 feet honistry distance). This side will be graned as a size of over of four four the side will be graned as a size of over of spilliogy is less steep age or set the logic anargency spilliogy is less steep age or set the logic anargency sciency used, a probable were carboe approximated - ----480 -----40 -----. . . . . . . . ..... -----ورجاد فالمالية 2- 470 - 469.2 - - - --400.9 -. . . . ····· ..... _____ ...... المتحجير ومحادية المحاصط وللان الورو مرورا والارام الماليون مىلىمى مەركىيى بىرى بىرىيىلىمىنىنىدىنى بىرى بىرى بىر بىرى يۇرىيى دەرىيىت بىرى بىرى بىرى بىرى تەركىي والمستعمد فراجه فتتحمص وبالمروح والرواج والرواج والمراجع والمحا 1+00 3+00 4. 340 المحصور مستعدان والمستعلم متعلق ومتراري والمرور المالي والمتحد المتعلم ومراري والمتعاد والمتحد والمتحد والمراري يترك الالان السمينية المتعاميرية الالارور والراري والتارية الميدانية ويتوار بتهييت متصيد اليها بتدار * This overland flow comis into effect at elevations greater than 969.2 - -----· • · · · • . . . . . . . . -----D-7

CAMP DRESSER & MCKEE

....

-

_

____

PAGE BAE _ COMPUTED BY. . . .... . ... .

Ener Filinen Cating Curic _ . . -Assumed & Value of Overland " Werr' = 2.50

(Land is first grassed with rocky patches; becomes streets and lawns)

**...** 

----

_____

· · · · ·

-- --··· ~ ~ ~ · . . ....

- - ---

	-	······	
Electron of hater (feet)	12000 - 1020 From JA - ASG	Overland Weir, Flow (19)	10101 10 Ecus (293)
469,0			7739
469,8	10120	44	10164
410.0	10775		10864-
472.0	1986 7.	937	20804
479.0	31317	2892	30209
£75.0	44837	6206	51093_
473.0	60153	11094	71247
48C.O	76930	17.736	94676
<i>432.</i> 0	95028	24,042	119,130.
430.0	119525	3 1315	145,240
· · · · · · · · ·	· · · · · · · ·		
	L	L	1

ma Aldrinin CLIENT - - - / ---a .... CAMP DRESSER & MCKEE PAGE. PROJECT L'ALISM INTE MO DATE CHECKED 9-28-18 ⇒, ÷ Environmental Engineers CATE DETAIL LINE In dirette of CHECKED BY Boston, Mass. COMPUTED B - --Sollway Rating Lurie . Ī 140,000 130,000 109,760 109,137 100,000 でも 8 30,000 0 _ -60000 (M . 40,000 1  $\infty$ . . . . . 476 478 430 7 482 481.05 481.35 470 172 474 <u>____</u> ERATION of Mater - --

1

م و تبد و زود س PAGE CF CAMP DRESSER & MOKEE CLIENT DATE P. E.S.P Boston, Mass. DETAIL 7 COMPUTED BY Et man E Hect of Surcharge Storene on MORI MUM Anbable Discharges ···· 1. Do, = 109,960 =, F.s. 2. a. 43135-463.2 - 17.55 feet b. Volume of Surcharge = 17.55. × 39.5 = C.12 for in Inches of Runch 53.3×116. 3736. 37381 ---- $\mathcal{L}_{D_2} = 109,760 \times \left(1 - \frac{12}{23}\right) = 109,187 L, F.S.$ -----3. 2. - = 17.45 Feet 17.45 Feet x 39.5 Acre = 0.12 10003 533×112____ D. JO STORAUE = 0,12 Incrus 1. 203 = 109,137 c.F.s. at eler. 421.25 feet. -----------..... . ..... . . . . -----. . . . . . . . . . . . . . . . ----- - - -----. . . . . . . .. . . ..
CAMP ORESSER & MCKEE Environmental Endineers Boston Mass.

DUENT AND AND AND OB NO AND AT DETAIL

CHECKED BY OFTILET

_ _ . .

PAGE -CATE _ COMPUTED BY-

- lan Failure Analysis

Auring the 1938 Flood, so much clamage was done to brisges and buildings that The camere caused ou a PMF for even is PMF docurrence would be much more extensive.

## Camage consect by 1938 Flides

- Emergency Spillway was wasnia aut 2. Mater uss & fest over ware Bod and this bricks eventually washed out 100

3. L'est brage on river was was hed aut 4 Water line mark acous Frist Fisor windows on old yore richten comport Hil. S. Grevost horas on cast side of doms

beame on sland . un er swert sours _____SHELTS EDOCE CASEMICS

The PLAF is approximately 9 times grater a proper would be much more avastating. - Jo the hazard should remain HIGH A dam failure on aline, in view of The above data, would serve no further purpose ____

Aso, occase of the large amount of damage ond lass of life that could be incurred by a dome tailure, it carears that the spiring - Resign Fibod should be the PHF.

_____ . . . . . . . . . . . . ----------

D-11

CAMP DRESSER & MCKEE CLIENT TO COMPANY CLIENT TO

Ī

Ľ

I

2:5-03 DATE

Done Failure Analysis

At Elevation 470.0, J = 74.6 Acre-feet 2)  $\Omega_{\Sigma_1} = \frac{2}{277} = \omega_5 \sqrt{9} + 5^{3/2}$   $5^{6} = 40$  Feet  $\omega_5 = 0.40 \times 16.5 = 66$  Feet  $C_{D_1} = \frac{9}{277} \times 66$ ,  $\overline{32.2} \times 40^{3/2} = 29,07.9$  efs

304 23, 120 25:

3) Ware Rood Culvert - located opprovintately 420 Ft. dis (East Moin Street)



Sluze Conste East Mars St. Bridge

Prea of Opening = 1 x 32.5 x 17.4 = 533.3 4 Perimeter of Opening = 1 1 192.512 +17.412 = 21.7 F

A- excy. 45%?, - 1.1-1 (eags), 4 (.0000) * (geod). .040 (gua)

* 9989cfs

D-12





E

2

•

-

1.



Assume For Weir Equations, C-2.6 For seriord Flaw

Q= CH siz for thangular sections Q- CLH 312 for strong int sections

Eky.	H	a	Quer	<u></u> _			
471		16771	0	16711			
276	15	in the second	ج 1- مح				
45	7	10-11	23994	مي المشالية			
	0		· · · ·				

at Q= 28,100 cts, elev. Flood waters = 477.3 ft.

D-13

APPENDIX E INFORMATION AS CONTAINED IN THE NATIONAL INVENTORY OF DAMS

24

O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O	() () () () () () () () () () () () () (	OF UNPOUNDIMENT		AM FROM POPULATION	0 8679	O PACIFIES AUTIMES DIST OWN FED & PHV/FED SCS A VER/O	145 NED N N N N N 130E		тичистичеротичисти скортичисти скортичирун тичистичеротичисти скортичисти скортичирун		CONSTRUCTION BY		MAINTENANCE	R P C R	(#) JTHORITY FOR INSPECTION		AH 92=367		
() NAME	HIES MAIN UPPER DAM	NAME (	*ARE HIVER	NEAREST DOWNSTREA CITY - TOWN - VILLAC	* ARE	(a) (b) (c) (c) (c) (c) (c) (c) (c) (c) (c) (c	40 34 746	REMARKS	BOWER CAPACITY MAYALLED FROMSED MOLTREPT		ENGINEERING BY		REGULATORY AGENCY ION DPERATION	NONE	INSPECTION DATE AU	NAT UM TAU	I 12MAY78 PUBLIC LA	REMARKS	=PHOPENTLES INC.
() () () () () () () () () () () () () (	44 015 01 01 WARE INDUST	POPULAR NAME		CONBASIN RIVER OR STREAM	NI DB WARE RIVER	(a) (b) (b) (c) (c) (c) (c) (c) (c) (c) (c) (c) (c	RERACTPG 1482 R		a) (a) (b) (b) (b) (c) (c) (c) (c) (c) (c) (c) (c) (c) (c	1 386 U 181 7980	OWNER	NENAME SECK INDUSTRIAL PR	DESIGN CONSTRUCT	NONF	INSPECTION BY		HALEY + ALDHICH, INC.		32-53-TUTAL SPILLMAY SYSTEM 46.



## FILMED

8-85

DTIC