


NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS
WHITNEY POND (MA 0063. (U) CORPS OF ENGINEERS WALTHAM
MA NEW ENGLAND DIV MAR 79

UNCLASSIFIED

F/G 13/13

NL



MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS 1963-A

AD-A155 408

CONNECTICUT RIVER BASIN
WINCHENDON, MASSACHUSETTS

WHITNEY POND
MA 00633

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM

Copy available to DTIC does not
permit fully legible reproduction

DTIC
ELECT
JUN 2 0 1985
S G



DTIC RECORDS UNIT A
Approved for public release;
Distribution Unlimited

DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
WALTHAM, MASS. 02154

DTIC FILE COPY

MARCH 1979

85 5 28 239

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER MA 00633	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Whitney Pond NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS		5. TYPE OF REPORT & PERIOD COVERED INSPECTION REPORT
7. AUTHOR(s) U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS		8. CONTRACT OR GRANT NUMBER(s)
11. CONTROLLING OFFICE NAME AND ADDRESS DEPT. OF THE ARMY, CORPS OF ENGINEERS NEW ENGLAND DIVISION, NEDED 424 TRAPELO ROAD, WALTHAM, MA. 02254		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		12. REPORT DATE March 1979
		13. NUMBER OF PAGES 53
		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		16a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Cover program reads: Phase I Inspection Report, National Dam Inspection Program; however, the official title of the program is: National Program for Inspection of Non-Federal Dams; use cover date for date of report.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) DAMS, INSPECTION, DAM SAFETY, Connecticut River Basin Winchendon, Massachusetts Millers River		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) The dam is a 25 ft. high, 562 ft. long gravity stone masonry and earth embankment structure. The dam is generally in good condition. It has a size classification of intermediate and a hazard potential of high. It is felt that certain normal maintenance and operational procedures need attention.		

DISCLAIMER NOTICE

**THIS DOCUMENT IS BEST QUALITY
PRACTICABLE. THE COPY FURNISHED
TO DTIC CONTAINED A SIGNIFICANT
NUMBER OF PAGES WHICH DO NOT
REPRODUCE LEGIBLY.**



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
424 TRAPELO ROAD
WALTHAM, MASSACHUSETTS 02154

REPLY TO
ATTENTION OF:
NEDED-E

JUL 11 1979

Honorable Edward J. King
Governor of the Commonwealth of
Massachusetts
State House
Boston, Massachusetts

Dear Governor King:

I am forwarding for your use a copy of the Whitney Pond Dam Phase I Inspection Report, which was prepared under the National Program for Inspection of Non-Federal Dams. The report is based upon a visual inspection, a review of past performance, and a preliminary hydrological analysis. A brief assessment which emphasizes the inadequacy of the project spillway under test flood conditions is included at the beginning of the report.

The preliminary hydrologic analysis has indicated that the spillway capacity for the Whitney Pond Dam would likely be exceeded by floods greater than 7 percent of the Probable Maximum Flood (PMF), the test flood for spillway adequacy. Screening criteria for initial review of spillway adequacy specifies that this class of dam, having insufficient spillway capacity to discharge fifty (50) percent of the PMF, should be adjudged as having a seriously inadequate spillway and the dam assessed as unsafe, non-emergency, until more detailed studies prove otherwise or corrective measures are completed.

The classification of "unsafe" applied to a dam because of a seriously inadequate spillway is not meant to indicate the same degree of emergency as would be associated with "unsafe" classification applied for a structural deficiency. It does mean, however, that based on an initial screening and preliminary computations there appears to be a serious deficiency in spillway capacity. This could render the dam unsafe in the event of a severe storm which would likely cause overtopping and possible failure of the dam, significantly increasing the hazard potential for loss of life downstream from the dam.

NEDED-E

Honorable Edward J. King

It is recommended that within twelve months from the date of this report the owner of the dam engage the services of a professional or consulting engineer to determine by more sophisticated methods and procedures the magnitude of the spillway deficiency. Based on this determination, appropriate remedial mitigating measures should be designed and completed within 24 months of this date of notification. In the interim a detailed emergency operation plan and warning system should be promptly developed. During periods of unusually heavy precipitation, round-the-clock surveillance should be provided.

I have approved the report and support the findings and recommendations described in Section 7, with qualifications as noted above. I request that you keep me informed of the actions taken to implement these recommendations since this follow-up is an important part of the non-Federal Dam Inspection Program.

A copy of this report has been forwarded to the Department of Environmental Quality Engineering, the cooperating agency for the Commonwealth of Massachusetts. This report has also been furnished to the owner of the project, Town of Winchendon, 105 Friend Street, Winchendon, Massachusetts 01475, ATTN: Mr. Peter Morneau, Superintendent, Department of Public Works.

Copies of this report will be made available to the public, upon request to this office, under the Freedom of Information Act, thirty days from the date of this letter.

I wish to take this opportunity to thank you and the Department of Environmental Quality Engineering for the cooperation extended in carrying out this program.

Sincerely yours,

Accession For	
NTIS GRA&I	<input checked="" type="checkbox"/>
DTIC TAB	<input checked="" type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
Re	
Distribution/	
Availability Codes	
Avail and/or	
Dist	Special
A/1	✓

Max B. Scheider
MAX B. SCHEIDER
Colonel, Corps of Engineers
Division Engineer

NATIONAL DAM INSPECTION PROGRAM

PHASE I INSPECTION REPORT

BRIEF ASSESSMENT

Identification No.: MA 00633

Name of Dam: Whitney Pond

Town: Winchendon

County and State : Worcester County, Massachusetts

Stream: Millers River

Date of Inspection: November 13, 1978

The dam is a 25+ foot high, 562+ long gravity stone masonry and earth embankment structure. It is comprised of an 82 foot foot long stone masonry spillway, a 450+ foot earth embankment to the left of the spillway, and a 30+ foot earth embankment to the right of the spillway. The left embankment is utilized for a railroad right-of-way and two railroad bridge structures are located immediately upstream of the spillway. The dam was originally built in 1880 for power generation. Modifications to the original structure were made in 1936 and 1957. The dam is now used basically for recreation. The dam is owned, operated and maintained by the Town of Winchendon.

The visual inspection of the dam indicated it to be in generally good condition.

The dam has a size classification of intermediate and a hazard classification of high. According to Corps guidelines the test flood is the Probable Maximum Flood which has an inflow of 60,950 cfs. The spillway can pass 7 percent of

Whitney Pond


this flow. The dam would be overtopped by 6+ feet. The resulting outflow would be 58,000 cfs. The existing spillway is partially blocked by the upstream railroad bridges. It has the potential for increased blockage by debris catching the stop log stanchions. There are normally 2 to 3 feet of stop logs in use. Indepth engineering data was not available and therefore, the adequacy of the dam was assessed primarily on visual inspection, past performance history, and engineering judgement.

The dam is in generally good condition. It is felt, however, that certain normal maintenance and operational procedures need attention. These include removal of brush and trees on the upstream and downstream slopes; development of a formal warning system and monitoring of the condition of the downstream training wall. Also repairs to the walkway over the spillway are required. Due to the dam's high hazard classification along with its overtopping potential, it is further recommended that the owner engage a competent engineer to investigate the adequacy of the spillway and design a draw down facility for the dam.

The above problems do not represent an immediate threat to the dam; however, the normal maintenance and operational procedures should be carried out by the owner over the next 2 years after receipt of this Phase I Inspection Report. The evaluation of the spillway and the design of a draw down facility

Whitney Pond

should be carried out by the owner within one year after receipt of this Phase I Inspection Report.



Ronald H. Cheney
Ronald H. Cheney, P.E.
Associate

Hayden, Harding & Buchanan, Inc.
Boston, Massachusetts

Whitney Pond

This Phase I Inspection Report on Whitney Pond has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the Recommended Guidelines for Safety Inspection of Dams, and with good engineering judgment and practice, and is hereby submitted for approval.

Joseph A. McElroy

JOSEPH A. MCELROY, MEMBER
Foundation & Materials Branch
Engineering Division

Carney M. Terzian

CARNEY M. TERZIAN, MEMBER
Design Branch
Engineering Division

Joseph W. Finegan, Jr.

JOSEPH W. FINEGAN, JR., CHAIRMAN
Chief, Reservoir Control Center
Water Control Branch
Engineering Division

APPROVAL RECOMMENDED:

Joe B. Fryar

JOE B. FRYAR
Chief, Engineering Division

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Inspections. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I Investigation: however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

CONTENTS

<u>Section</u>	<u>Page</u>
Letter of Transmittal	
Brief Assessment	
Review Board Page	
Preface	i
Table of Contents	iii-v
Overview Photo	vi
Location Map	vii

REPORT

1. PROJECT INFORMATION

1.1 General	1
a. Authority	1
b. Purpose of Inspection	1
1.2 Description of Project	2
a. Location	2
b. Description of Dam and Appurtenances	2
c. Size Classification	3
d. Hazard Classification	3
e. Ownership	3
f. Operator	3
g. Purpose of Dam	4
h. Design and Construction History	4
i. Normal Operating Procedures	4
1.3 Pertinent Data	5

2. ENGINEERING DATA

2.1 Design Data	10
2.2 Construction Data	10
2.3 Operation Data	10
2.4 Evaluation of Data	10

<u>Section</u>	<u>Page</u>
3. VISUAL INSPECTION	
3.1 Findings	12
a. General	12
b. Dam	12
c. Appurtenant Structures	14
d. Reservoir Area	15
e. Downstream Channel	15
3.2 Evaluation	16
4. OPERATIONAL PROCEDURES	
4.1 Procedures	17
4.2 Maintenance of Dam	17
4.3 Maintenance of Operating Facilities	17
4.4 Description of any Warning System in Effect	17
4.5 Evaluation	17
5. HYDRAULIC/HYDROLOGIC	
5.1 Evaluation of Features	19
a. General	19
b. Design Data	19
c. Experience Data	19
d. Visual Observation	20
e. Overtopping Potential	20
f. Dam Failure Analysis	20
6. STRUCTURAL STABILITY	
6.1 Evaluation of Structural Stability	21
a. Visual Observation	21
b. Design and Construction Data	21
c. Operating Records	21
d. Post-Construction Changes	21
e. Seismic Stability	22

<u>Section</u>	<u>Page</u>
3. VISUAL INSPECTION	
3.1 Findings	12
a. General	12
b. Dam	12
c. Appurtenant Structures	14
d. Reservoir Area	15
e. Downstream Channel	15
3.2 Evaluation	16
4. OPERATIONAL PROCEDURES	
4.1 Procedures	17
4.2 Maintenance of Dam	17
4.3 Maintenance of Operating Facilities	17
4.4 Description of any Warning System in Effect	17
4.5 Evaluation	17
5. HYDRAULIC/HYDROLOGIC	
5.1 Evaluation of Features	19
a. General	19
b. Design Data	19
c. Experience Data	19
d. Visual Observation	20
e. Overtopping Potential	20
f. Dam Failure Analysis	20
6. STRUCTURAL STABILITY	
6.1 Evaluation of Structural Stability	21
a. Visual Observation	21
b. Design and Construction Data	21
c. Operating Records	21
d. Post-Construction Changes	21
e. Seismic Stability	22

SectionPage


7. ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES

7.1 Dam Assessment	23
a. Condition	23
b. Adequacy of Information	23
c. Urgency	23
d. Need for Additional Investigation	23
7.2 Recommendations	23
7.3 Remedial Measures	24
a. Operation and Maintenance Procedures	24
7.4 Alternatives	25

APPENDIXES

APPENDIX A - INSPECTION CHECKLIST	A-1
APPENDIX B - ENGINEERING DATA	B-1
APPENDIX C --PHOTOGRAPHS	C-1
APPENDIX D - HYDROLOGIC AND HYDRAULIC COMPUTATIONS	D-1
APPENDIX E - INFORMATION AS CONTAINED IN THE NATIONAL INVENTORY OF DAMS	E-1





PHASE I
NATIONAL DAM INSPECTION PROGRAM
NAME OF DAM: WHITNEY POND

SECTION 1
PROJECT INFORMATION

1.1 General

a. Authority

Public Law 92-367, August 8, 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a national program of dam inspection throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region. Hayden, Harding & Buchanan, Inc. has been retained by the New England Division to inspect and report on selected dams in the State of Massachusetts. Authorization and notice to proceed was issued Hayden, Harding & Buchanan, Inc. under a letter of 28 November 1978 from Max B. Scheider, Colonel, Corps of Engineers. Contract No. DACW 33-79-C-0012 has been assigned by the Corps of Engineers for this work.

b. Purpose

(1) To perform technical inspection and evaluation of non-Federal dams to identify conditions which threaten the public safety and thus permit correction in a timely manner by non Federal interests.

(2) Encourage and assist the States to initiate quickly effective dam safety programs for non-Federal dams.

(3) To update, verify and complete the National Inventory of Dams.

1.2 Description of Project

a. Location

The dam, Whitney Pond, is located in the Town of Winchendon in Worcester County, Massachusetts. Whitney Pond is formed at the intersection of the North Branch and Millers Rivers and is located east of the center of town. The dam is shown on U.S.G.S. Winchendon, Massachusetts-New Hampshire Quadrangle, with coordinates approximately at North 42° 41' 00" West 72° 02' 30".

b. Description of Dam and Appurtenances

Whitney Pond is a composite dam approximately 25 feet high consisting of an 82 foot stone masonry spillway a 450± foot earth embankment to the left of the spillway and a 30 foot long earth embankment to the right of the spillway. The overall plan length is 562± feet. The left embankment has an approximate 1½H:1V upstream slope and a downstream slope of approximately 2½H:1V. This embankment has a varying crest width and serves as the roadway for 2 converging lines of railroad tracks. The spillway is a 12' high masonry structure. During the field inspection there was approximately 2 to 3 feet of stop logs atop the masonry. There would be approximately 13' of freeboard between the top of the ungated masonry spillway and the crest of the embankment. The spillway is supported by 3 four foot thick concrete buttresses. The training walls are unmortared stone masonry and serve as the abutments for the dam and the two rail-

road bridges that span the spillway. An "L" shaped concrete wall ties into the left training wall to accomodate the downstream bend in the river.

An approximate 30 foot wide section of embankment is located on the right side of the spillway. This embankment contains an impervious core and was constructed in 1957 to close down a canal which once serviced a now defunct electric power station downstream. Plans dated 1937 show provisions for approximately 7 feet of stop logs and flashboard atop the spillway. A steel framed wood planked walkway spans the structure

c. Size Classification

The dam falls into the intermediate size classification according to its maximum storage capacity of 2186 acre feet, with water to crest of dam.

d. Hazard Classification

The dam has a high hazard classification. Flood-water from dam failure would damage numerous homes and buildings in the urban area adjacent to the stream.

e. Ownership

The dam has been owned by the Town of Winchendon, Winchendon, Massachusetts since 1959. It was originally owned by the Winchendon Electric Light and Power Company until 1936 when it was taken over by New England Power Company.

f. Operator

The dam is maintained and operated by the Town of Winchendon Department of Public Works in accordance with the

Board of Selectmen. Peter Morneau is the Superintendant of the DPW and Burton E. Gould is the chairman of the Board of Selectmen. The address is 105 Friend Street Winchendon, Massachusetts 01475 for both offices and the telephone is (617) 297-0085 for both offices.

g. Purposes of Dam

Earlier usage, which has been eliminated by blockage of the old canalway, was for electric power generation and water supply for the downstream factories. The pond behind the dam is now used basically for recreation. Some control is maintained by the use of stop logs.

h. Design and Construction History

The original "Whitney Dam" was constructed in 1880. The present dam utilizes portions of the original dam along with improvements designed and instituted in 1936 by the New England Power Service Company. In 1957 the sluiceway, leading to the canal used in power generation, was blocked by an earthen embankment. Plans outlining the 1936 and 1957 improvements were made available at the Worcester County Court House. No other construction records or design calculations were available.

i. Normal Operational Procedures

No formal operational procedure is outlined for this dam. The operator maintains stop logs to assure that the water level of the pond is 2 to 3 feet above the masonry spillway for summer recreation.

1.3 Pertinent Data

a. Drainage Area

The drainage area (33,920 acres - 53 s.m.) is comprised of wooded, rolling hills, containing several drainage paths and a number of lakes and ponds. The two major drainage paths are the Millers River and North Branch Millers River. Millers' River receives outflow directly from Sunset and Lower Naukeag Lakes, and indirectly from several lakes and ponds above these two lakes. During its course of about 7.3 miles from Lower Naukeag Lake to the Whitney Pond Dam, the river falls nearly 100 feet in elevation. North Branch Millers River serves as an outlet to Lake Monomonac, which is fed by several smaller lakes, ponds, and streams to the north and east. The river drops approximately 70 feet over the course of 2.7 miles from Lake Monomonac to Whitney Pond Dam.

Development throughout the drainage area is generally sparse except near downtown Winchendon, around the lakes used for recreational purposes, and at Winchendon Springs, Rindge and East Ridge. The Boston and Maine Railroad, several State highways, and a number of improved roads service the area.

For a reach of about 2000 feet downstream of the dam the downtown area of Winchendon is adjacent to the Millers River. A number of structures are located within 400 feet of the River, including residential and manufacturing buildings

and two road bridges. Several manufacturing and a number of residential buildings are located within 400 feet of the river at Waterville, about 1.5 miles downstream of the dam. A sewage treatment plant and U.S.G.S. gaging stations are located just over 3 miles below the dam. Beyond this point there is little or no development close to Millers River for several miles downstream.

b. Discharge at Dam Site

This dam has no outlet works other than existing overflow spillway. An old sluiceway at the northwestern end of the dam was closed off and filled in during 1957 to 1958.

The dam was constructed in 1880, and underwent extensive improvements in 1936. Discharge records of the U.S.G.S. gaging station No. 1-1620, located approximately 3.3 miles downstream of the dam, are available from 1916 to the present. Flows are recorded for an 83 square mile area of the Millers River. The flood of record at this gage occurred on September 22, 1938 with a peak discharge of 8,500 cfs and elevation of 848.2₊.

The spillway is ungated, with provisions for stop logs and flashboards. It has an approximate capacity of 9700 cfs at an elevation of 978.8₊ without stop logs. Considering three feet of stop logs the capacity is 6,400 cfs. Due to the existance of the railroad bridge, the spillway capacity is reduced to 4,000 cfs since the bridge blocks 3₊ feet of the spillway. The test flood (inflow 60,950 cfs) would overtop the embankment to elevation 985.1. The outflow would be 58,000 cfs. If the spillway were blocked with debris, the outflow would overtop the embankment to elevation 985.25₊.

(1)	Streambed at centerline of dam -----	948
	(average 954)	
(2)	Maximum tailwater -----	962±
(3)	Upstream portal invert diversion tunnel -----	none
(4)	Recreation pool -----	969±
(5)	Full flood control pool -----	N/A
(6)	Spillway crest-	
	with stop logs	968.8
	without stop logs	965.8
(7)	Design surcharge (Original Design)-----	unknown
(8)	Top Dam -----	978.5
(9)	Test flood design surcharge -----	985.1
	(985.25 spillway blocked)	

(1) Length of maximum pool----- 11,000'

(2) Length of recreation pool----- 4,000'

(3) Length of flood control pool ----- N/A

```
(1) Spillway crest pool---elevation 965.8-----258
(2) Recreation pool-----elevation 968.8----- 410
(3) Flood control pool-----N/A
(4) Top of dam----- 1450
(5) Test flood pool-----3750
```

f. Reservoir Surface (acres)

- (1) Spillway crest ----- 44±
- (2) Recreation pool (with flashboards of 3')-- 56
- (3) Top dam -----248
- (4) Flood control pool-----N/A
- (5) Test flood pool -----331

g. Dam

- (1) Type -----Gravity type, stone masonry, earth embankment
- (2) Length-----562' total including spillway
- (3) Height-----25'
- (4) Top Width-----25' at embankment
- (5) Side Slopes---- 1½:1 U.S., 2.5:1+ D.S. at left embankment
1½:1 U.S. & D.S. at right embankment
- (6) Zoning ----- unknown
- (7) Impervious Core ----- unknown
- (8) Cutoff----- unknown
- (9) Grout curtain----- unknown
- (10) Other

h. Diversion Regulating Tunnel ----- none

Type

Length

Closure

Access

Regulating Facilities

i. Spillway

- (1) Type----- broad crested
- (2) Length of weir-----82'
- (3) Crest elevation-----965.8
- (4) Gates----- none-stop logs & flashboards only
- (5) U/S Channel----- riverbed
- (6) D/S Channel----- riverbed
- (7) General----- provisions for stoplogs

j. Regulating Outlets

The regulating outlet for this dam consists of the overflow spillway with provisions for stop logs and flashboards. As previously described, the spillway is made up of stone masonry between concrete buttresses. Total crest length is 82' and crest elevation is 965.8'. Up to 7 feet of stop logs and flashboards can be used to control discharge through the dam. These stop logs can be removed manually or by releasing the needle beams holding them in place if manual removal is not possible.

SECTION 2
ENGINEERING DATA

2.1 Design

Plans showing 1936 and 1957 improvements were located at the Worcester County Court House - Engineering Department. E.P. Moseley is the Engineer indicated on the 1957 plans; there is no positive confirmation as to who prepared the 1936 plans. A County fact sheet and County Inspection Reports prior to 1971 are also available at that Department. A 1971 State Inspection Report was also found at the State Department of Environmental Quality Engineering Division of Waterways Office. No indepth design calculations were located.

2.2 Construction

No construction data was encountered regarding Whitney Pond.

2.3 Operation

No operational manual exists for the dam.

2.4 Evaluation

a. Availability

Plans showing 1936 and 1957 dam improvements, a County fact sheet, County Inspection Reports and limited County correspondence, were found at the Worcester County Court House - Engineering Department. The 1971 State

Inspection Report was located at the State Department of Environmental Quality Engineering Division of Waterways Office. The 1936 and 1957 Improvement Plans were also found at the Town of Winchendon Department of Public Works Office.

b. Adequacy

The lack of indepth engineering data does not allow for a definitive review. Therefore the adequacy of this dam, structurally and hydraulically, can not be assessed from the standpoint of review of design calculations, but must be based primarily on the visual inspection, past performance history, and engineering judgement.

c. Validity

The field investigation indicates that the external features substantially agree with those shown on the furnished data.

SECTION 3
VISUAL INSPECTION

3.1 Findings

a. General

The Whitney Pond Dam was inspected on November 13, 1978. At that time, approximately 1 to 3 inches of water was passing over the spillway and some leakage through the stop logs was also observed. The upstream face of the dam could only be inspected above this water surface.

b. Dam

The dam consists of a masonry spillway section about 82 feet long abutted by a 30+ foot earth embankment on the right and a 450+ foot earth embankment on the left. The left training wall of the spillway section forms a retaining wall abutment for the left embankment section. The embankment serves as a multiple track railroad right-of-way, as shown in photo 1. The definition of the dam embankment is complicated by its use as a railroad fill. Based on this inspection, the left embankment dam section is defined as 450+ feet long. Total dam length is 562+ feet.

Visual inspection of the dam indicated it is in good condition.

Left Embankment Section

Upstream Slope

The upstream face of the embankment is sloped at about 1.5H:1V. The upper 10 feet of the embankment was visible above the water surface. Riprap slope protection extending about 1 foot above the waterline and over most of the embankment

length, consists of a small-sized broken rock. Adjacent to the left training wall of the spillway and extending for a distance of about 75 feet, large-sized riprap has been placed. Both sizes of riprap may be seen in photo 12. Dense brush has grown on the upstream slope above the riprap. This condition is shown in photos 2 and 12.

Crest

The crest of the dam, which serves as a railroad bed is shown in photo 1. Track maintenance would obscure any visible misalignment due to embankment movements. The crest is 25 feet wide at its narrowest point near the spillway structure.

Downstream Slope

The downstream face is on a slope of about 2.5H:1V. Photo 10 is a view of the downstream slope from the crest looking toward the left abutment area. The lower one third of the slope and the area immediately downstream of the toe is overgrown with brush and small trees. Photos 3 and 11 are views along the toe of the slope looking toward the left abutment. The entire downstream toe area was traversed, and no seepage or wet areas which could be attributed to seepage were observed. Some surface drainage collects at the toe of the slope. Adjacent to the left training wall of the spillway, an area of the downstream slope has been covered with large-sized rock. This area is shown in Photo 9. This rock was placed in repair of a slide in the embankment which damaged the toe of the training wall and a wing wall extend-

ing along the toe of the embankment.

Right Embankment Section

When originally constructed in 1880, this project included a power canal through the right abutment. In 1957 this canal was plugged by construction of a zoned earth embankment about 14 feet high and 30 feet long. This embankment consists of an impervious core with random fill upstream and downstream shells. Upstream and downstream embankment slopes were constructed on 1.5H:1V. The crest width is 6 feet.

c. Appurtenant Structures

The training walls of the spillway act as embankment retaining walls. The left training wall which retains the main embankment is shown in photo 13. The toe of the wall, which has been damaged by an embankment slide, has been replaced with a concrete section. The wall was in good condition at the time of inspection. The right training wall is shown in photo 5. This photo, which is of the extreme downstream end of the training wall, shows a portion of the wall downstream of the embankment which has fallen. The condition of the wall may be a result of demolition of an old structure which occupied this area. The condition of the wall presents no hazard at this time. Continued observation of this wall should be made. The spillway consists of the masonry abutments and three concrete buttresses infilled with stone masonry. The spillway and training walls are true, plum and appear to be in no distress. Water is

leaking out between the joints in the stone at the middle two sections of the spillway at about 1/3 the distance up from the base. The three concrete buttresses located at the spillway appear to be in good condition with some minor spalling. Large stones, which appear to have been hand placed, are located in front of the two middle bays of the spillway (photo 14). The purpose of placing these stones is unclear as the alignment of the spillway appears to be good.

The metal framed wood decked walkway over the spillway was weathered but basically in good condition. Approximately 5 lengths of handrail and one floorboard were missing. The walkway does not appear to have been painted or the wood oiled in some time.

d. Reservoir Area

The general area surrounding the reservoir is a wooded rural area as shown by photo 4. A more detailed description of the drainage area is included in Section 1.3 of this report. The amount of siltation within the reservoir is unknown.

e. Downstream Channel

The downstream channel is the natural riverbed shown by photo 6. It is broad and level with many trees located along the shoreline and upon several small downstream "islands". Some stones, old tires, and other debris are located within the downstream pond, however, these objects pose no major problem to continued flow. An "L" shaped concrete wingwall

located on the left side and the old masonry training wall on the right side define the immediate downstream channel.

3.2 Evaluation

Visual inspection indicated the embankment is in good condition.

No seepage was observed along the downstream toe of the embankment.

Dense brush growing on the downstream slope should be eradicated as part of an improved maintenance program.

The condition of the downstream section portion of the right training wall should be monitored to assure that eventual undermining of the right abutment does not occur.

There is no rapid draw down facility for this dam.

SECTION 4
OPERATIONAL PROCEDURES

4.1 Procedure

No formal operational procedures were disclosed for Whitney Pond Dam. Discussion with the Town of Winchendon Department of Public Works indicate that they attempt to maintain 2 to 3 feet of stoplogs in place for summer pond recreation. They are also responsible for periodic general maintenance to the dam.

4.2 Maintenance of Dam

The dam, Whitney Pond, is maintained by the Town of Winchendon, Massachusetts. No known recent repairs were performed on the dam .

4.3 Maintenance of Operating Facility

There are no operational facilities for this dam other than provisions for flashboards. At the time of our inspection there was approximately 3 feet of flashboard in place. The apparatus used for regulating the flashing system appears to be in working order. The flashboard-stoplog system can be released by removing pins in the stanchion support system at the walkway level.

4.4 Description of Any Warning System in Effect

There are no warning systems associated with this dam.

4.5 Evaluation

Although the dam appears to be in adequate condition the current operation and maintenance procedures are not

formally written and therefore can not insure the successful treatment of all potential problems within a reasonable period of time. The dam should be inspected every two years by qualified personnel who can identify any areas of concern which could in time lead to serious deficiencies. A formal system for warning downstream residents during flood-flow conditions or imminent dam failure should be developed.

SECTION 5

HYDRAULIC/HYDROLOGIC

5.1 Evaluation of Features

a. General

The dam was built in 1880 for power production. The spillway is basically a run-of-the-river type. It has a low surcharge storage capacity and a high spillage rate. The spillway is constructed of stone masonry with newer improvements being constructed of concrete. The remainder of the dam is an earth embankment which also serves as a railroad right-of-way.

The spillway has provisions for stop logs, several levels of which are normally used. The stop logs and their supports could cause blockages (allowing debris to build up) thus backing up water behind the dam.

Immediately upstream of the spillway are two railroad bridges. These structures could interfere with flood flow and cause a back-up of water.

b. Design Data

Design data is not available for this project. Improvements and modifications have been made at various times by the owners of the dam.

c. Experience Data

During the flood of August 19, 1955, about 850 cfs passed the dam, with no significant problems occurring at the dam. This flow appears to have been contained within the spillway. No records of dam overtopping are known.

d. Visual Observations

Visual observations indicate that roads, bridges, dam and railroad lines above and below the dam would restrict flow and cause backwater condition.

e. Overtopping Potential

The test flood, full PMF, will produce an inflow of 60,950 cfs. The existing spillway can pass only 4,000 cfs, (7 percent of inflow) due to a partial blockage by the railroad bridge and assuming 3 feet of stop logs in place. Its capacity can be further reduced by debris caught on the stop log stanchions. The PMF will overtop the embankment area to elevation 985.1, 6.6 feet above the crest of the dam. The resulting outflow is 58,000 cfs. If the spillway were totally blocked the overtopping would reach elevation 985.25₊.

f. Dam Failure Analysis

With water assumed to the crest of the earth embankment, an analysis produced an outflow of 22,000 cfs. Just below the dam is Tannery Pond and parts of the Town of Winchendon. Flood stage would be at depths of 5 to 10 feet above base flow levels. About 24 homes, businesses and factories would be damaged by about 3₊ feet of flood-water. Two roads would be under 8₊ feet of water. The small dam above Tannery Pond would be under about 8 feet of water. Loss of life could be expected.

SECTION 6
STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability

a. Visual Examination

The visual examination did not disclose any immediate stability problems.

b. Design and Construction Data

Plans showing the 1936 and 1957 modifications were made available at the Worcester County Court House. No construction records or design calculations were available. No drawings are available for the main embankment portion of the dam or the original construction of the spillway.

c. Operating Records

No operational manual exists for the dam.

d. Post-Construction Changes

The 1936 modifications included the provisions for 4'-8" of stop logs topped with 2'-0" of flashboards, the downstream concrete buttresses and the service walkway.

An embankment closure section was built in about 1957 in the original canal which passed through the right abutment.

A small slide on the downstream face adjacent to the left training wall of the spillway damaged a portion of the masonry wall which was rebuilt as a concrete section. The slide area was filled with large-sized rock. Both of the changes can be seen in photo 9.

e. Seismic Stability

This dam is in Seismic Zone 2, and according to USCE guidelines, it is assumed that there is no hazard from earthquake loading.

SECTION 7

ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES

7.1 Dam Assessment

a. Condition

The visual inspection indicates the dam is in good condition. Hydraulic and hydrologic analysis indicates the spillway to be inadequate to pass the test flood without overtopping.

b. Adequacy of Information

The information available is such that the condition of the dam must be evaluated from visual observations, past performance history and engineering judgement.

c. Urgency

The problems associated with the remedial measures of Section 7.3 should be carried out by the owner within two years of receipt of this Phase I Inspection Report. The recommendations of Section 7.2 should be carried out by the owner within one year of receipt of this Phase I Inspection Report.

d. Need for Additional Investigation

No additional investigation is needed to complete the Phase I Inspection.

7.2 Recommendations

The dam has a high hazard potential. The spillway can not pass the PMF test flood as per Section 5.1.e and the dam would be overtopped by over 6 feet. The owner, therefore

should engage a competent consulting engineer to evaluate further the potential for overtopping and the adequacy of the spillway. A draw down facility should also be added to the structure to insure the potential for rapid lowering of the pond under emergency conditions.

7.3 Remedial Measures

a. Operating and Maintenance Procedures

1. The owner should eradicate the brush and trees on the upstream and downstream slopes.
2. The owner should replace the missing sections of the handrails and floorboards on the walkway over the spillway.
3. Although the condition of the downstream right side training wall presents no hazard at this time, the condition of the wall should be monitored. If further deterioration of the wall back towards the spillway is observed over and above that shown in photo 5, the wall should be repaired to insure that eventual undermining of the spillway abutment does not occur.
4. The owner should develop a formal warning system to warn the downstream area in case of an emergency during periods of high stream flow.
5. The dam should be inspected every two years by qualified personnel who can identify areas of concern which, if left unchecked could jeopardize the safety of the dam.

7.4 Alternatives

Not applicable to this dam.

APPENDIX A
INSPECTION CHECKLIST

VISUAL INSPECTION CHECKLIST
PARTY ORGANIZATION

PROJECT Whitney Pond

DATE Nov. 13, 1978

TIME 9:45 .

WEATHER sunny

W.S. ELEV. 9694 U.S. _____ DN.S. _____

PARTY:

1.	Ron H. Cheney	HHB	6.	
2.	David Vine	HHB	7.	
3.	Daniel P. LaGatta	GEI	8.	
4.			9.	
5.			10.	

PROJECT FEATURE		INSPECTED BY	REMARKS
1.	Embankment	Daniel P. LaGatta	
2.	Spillway	Ron H. Cheney	
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			

PERIODIC INSPECTION CHECK LIST

PROJECT Whitney Pond

DATE November 13, 1978

PROJECT FEATURE Embankment Dam

NAME Daniel P. LaGatta

DISCIPLINE Geotechnical Engineer

NAME Ron H. Cheney

Structural Engineer

AREA EVALUATED	CONDITIONS
<u>DAM EMBANKMENT</u>	
Crest Elevation	The dam is an integral part of a railroad embankment 980.5+ 969+
Current Pool Elevation	
Maximum Impoundment to Date	unknown
Surface Cracks	None observed.
Pavement Condition	No pavement. Railroad on crest.
Movement or Settlement of Crest	None observed.
Lateral Movement	No misalignment was observed.
Vertical Alignment	
Horizontal Alignment	
Condition at Abutment and at Concrete Structures	Repair to slide on embankment adjacent to left training wall is evident.
Indications of Movement of Structural Items on Slopes	None observed.
Trespassing on Slopes	None observed.
Sloughing or Erosion of Slopes or Abutments	None observed.
Rock Slope Protection - Riprap Failures	Except in vicinity of spillway there is no riprap on upstream face.
Unusual Movement or Cracking at or near Toes	None observed.
Unusual Embankment or Downstream Seepage	None observed.
Piping or Boils	None observed.
Foundation Drainage Features	None.
Toe Drains	None.
Instrumentation System	None.
Vegetation	Dense brush on upstream face. High grass and brush on downstream face.

PERIODIC INSPECTION CHECKLIST

PROJECT Whitney Pond DATE November 13, 1978
 PROJECT FEATURE Embankment Dam NAME Daniel P. LaGatta
 DISCIPLINE Geotechnical Engineer NAME Ron H. Cheney

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - INTAKE CHANNEL AND INTAKE STRUCTURE</u>	
a. Approach Channel	
Slope Conditions	
Bottom Conditions	
Rock Slides or Falls	
Log Boom	None.
Debris	None.
Condition of Concrete Lining	Good.
Drains or Weep Holes	
b. Intake Structure	None.
Condition of Concrete	
Stop Logs and Slots	

PROJECT Whitney Pond
PROJECT FEATURE Embankment Dam
DISCIPLINE Geotechnical Engineer
Structural Engineer

DATE November 13, 1978
NAME Daniel P. LaGatta
NAME Ron H. Cheney

AREA EVALUATED	CONDITIONS
<u>OUTLET WORKS - CONTROL TOWER</u>	
a. Concrete and Structural	None.
General Condition	
Condition of Joints	
Spalling	
Visible Reinforcing	
Rusting or Staining of Concrete	
Any Seepage or Efflorescence	
Joint Alignment	
Unusual Seepage or Leaks in Gate Chamber	
Cracks	
Rusting or Corrosion of Steel	
b. Mechanical and Electrical	None.
Air Vents	
Float Wells	
Crane Hoist	
Elevator	
Hydraulic System	
Service Gates	
Emergency Gates	
Lightning Protection System	
Emergency Power System	
Wiring and Lighting System in Gate Chamber	

PERIODIC INSPECTION CHECK LIST

PROJECT Whitney Pond DATE November 13, 1978
 PROJECT FEATURE Embankment Dam NAME Daniel P. LaGatta
 DISCIPLINE Geotechnical Engineer NAME Ron H. Cheney
Structrual Engineer

AREA EVALUATED	CONDITIONS
<u>OUTLET WORKS - TRANSITION AND CONDUIT</u>	
General Condition of Concrete	None.
Rust or Staining on Concrete	
Spalling	
Erosion or Cavitation	
Cracking	
Alignment of Monoliths	
Alignment of Joints	
Numbering of Monoliths	

PERIODIC INSPECTION CHECKLIST

PROJECT Whitney Pond Dam DATE Nov. 13, 1978
 PROJECT FEATURE Embankment Dam NAME D. P. LaGatta
 DISCIPLINE Geotechnical Engineer NAME Ron H. Cheney
Structural Engineer

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - OUTLET STRUCTURE AND OUTLET CHANNEL</u> General Condition of Concrete Rust or Staining Spalling Erosion or Cavitation Visible Reinforcing Any Seepage or Efflorescence Condition at Joints Drain holes Channel Loose Rock or Trees Overhanging Channel Condition of Discharge Channel	None.

PERIODIC INSPECTION CHECKLIST

PROJECT Whitnay Pond DATE November 13, 1978
 PROJECT FEATURE Embankment Dam NAME Daniel P. LaGatta
 DISCIPLINE Geotechnical Engineer NAME Ron H. Cheney
Structural Engineer

AREA EVALUATED

CONDITION

C TLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS

a. Approach Channel

General Condition

Good.

Loose Rock Overhanging Channel

None.

Trees Overhanging Channel

None.

Floor of Approach Channel

Free and Clear (below water)

Weir and Training Walls

General Condition of Concrete

Concrete and masonry abutments of railroad bridges form the training walls for channel. These walls are in generally good condition. Spillway is stone masonry between concrete buttresses. No mortar in stone joints. Some spalling of concrete. No exposed or rusting reinf. bars.

Rust or Staining

Spalling

Any Visible Reinforcing

Any Seepage or Efflorescence

Drain Holes

c. Discharge Channel

General Condition

Good.

Loose Rock Overhanging Channel

None.

Trees Overhanging Channel

None.

Floor of Channel

Large stones in some places. Does not however effect flow.

Other Obstructions

Island in downstream channel.

PROJECT Whitney Pond DATE November 13, 1978
 PROJECT FEATURE Service Bridge NAME Daniel P. LaGatta
 DISCIPLINE Geotechnical Engineer NAME Ron H. Cheney
Structural Engineer

AREA EVALUATED	CONDITIONS
<u>OUTLET WORKS - SERVICE BRIDGE</u>	
a. Super Structure	
Bearings	There is a bridge across crest of the spillway which originally was used to service flashboards. Bridge consists of steel beams spanning between concrete buttresses with a wood plank deck and steel handrails. Five sections of horizontal rail are missing and one wood plank. Wood is weathered and appears not to have been painted or oiled in some time. Bridge is reasonably sound at this time.
Anchor Bolts	
Bridge Seat	
Longitudinal Members	
Under Side of Deck	
Secondary Bracing	
Deck	
Drainage System	
Railings	
Expansion Joints	
Paint	
b. Abutment and Piers	
General Condition of Concrete	Good.
Alignment of Abutment	Good..
Approach to Bridge	Good.
Condition of Seat and Backwall	Good.

APPENDIX B
ENGINEERING DATA

LIST OF ENGINEERING DATA

1. Plans showing 1936 modifications
2. Plans showing 1957 modifications

Location: Worcester County Court House
Engineering Department
Worcester, Massachusetts 01009

No indepth design calculations were located.

Whitney Pond

LOCATION **At plant of Baxter D. Whitney & Son.****Notebook 9-P. 25** C. C. DOCKET NO.

DESCRIPTION OF DAM

Type **Concrete & Cut Granite.**
 Length **115.0**
 Height **20.0**
 Thickness top **5.0**
 " " bottom **- Couldn't determine**
 Downstream Slope **Vertical.**
 Upstream " **" - ?**
 Length of Spillway **82.0**
 Size of Gates **82.0 wide.**
 Location of Gates **In Spillway**
 Flashboards used **Yes.**
 Width Flashboards or Gates **7.0 high - 2" thick.**
 Dam designed by **El. Top flashboards 972 B**
 " constructed by
 Year constructed **1880. - " Whitney Dam."**

GENERAL REMARKS

Owned by Winchendon El. L. & P. Co.
Inspected: Dec. 14, 1927 - L.O. Marden.
Oct. 13, 1929 - 10-14-29
 " **July 5, 1934 - " "**
 " **April 6, 1935 - " "**
 " **May 22, 1936 - " Nelson**
 " **8, 1936 - " Young**
 " **Mar. 20, 1936 - W.O.L., N.F.H.**

DESCRIPTION OF RESERVOIR & WATERSHED

Name of Main Stream **Millers River.**
 " " any other Streams
 Length of Watershed **(Traced and Approved 5-4-40 E.C. Concord)**
 Width " " **Appr. - L.O. Marden**
 Is Watershed Cultivated **N. E. Power Co. 441 Stuart St. Boston.**
 Percent in Forests
 Steepness of Slope
 Kind of Soil
 No. of Acres in Watershed **53.59 Miles² 33920 A**
 " " " " Reservoir **110. A.**
 Length of Reservoir
 Width " " **1936 Flood El. 977.4**
 Max Flow Cu. Ft. per Sec.
 Height of Flashboards Low Water **1938 - Town of Winchendon**
 " " " " " **19' Head used**

GENERAL REMARKS

1936 N.E. Power Construction Co. Stuart St. Boston
Second Inspection: 3-29-26 - L.O. Marden
New Plans & Specs approved 8-11-36 by C.C.
Inspected July 24, 1938 - L.O.M.
Inspected: Nov. 3, 1937 - L.O.M.
Measured - see sketch Hunt Bk #1 Page 46. Oct. 14, 1938 - M.F. Hunt
Inspected: Dec. 6, 1938 - E.O. Grover
" : Nov. 15, 1938 - L.O. Marden
(over)

INSPECTION REPORT & DATA FOR DAMS

Owner: Town of Winchendon
 His Address: Board of Selectmen, Front St., Winchendon
 Function of Dam: Storage

Location & Access: B & M RR Trestle behind
Skating Rink
 USGS Quad: Winchendon Lat. 42°41'20" Long. 72°02'30"
 Drain. Ar.: 53.67 Sq. Mi. Ponds: 110 ac.; Res. @ dam:
 Character of D.A.:


Dam No. 60-05
 Town: Winchendon
 Stream: Millers River
 Pond: Whitney Pond
 Date: 12-27-71
 By:

CONDITION RATING
 Structural: Good
 Hydraulic: Good
 General: Good
 PRIORITY:

Estimated
 Discharge:
 Capacity:

General Description of Dam and Discharge Control:

Sketch (Not to Scale):



Remarks and Recommendations:

Date 12/27/71 By Eaton & Carr Comment

Dam No. 3-14-343-05

Inspected: Nov. 21, 1938 - L.O.M., Crockett, Jones, Harry Nelson - N.E. Power Co.

Patrol Jan. 6, 1939 - E.S. Grover

" Mar. 16, 1939 - " "

Inspected: Sept. 26, 1940 - L.O.M. - Harry Nelson

" Feb. 26, 1944 - M.F.H.

" Oct. 17, 1946 - L.O.M.

" July 8, 1948 - L.O.M.

1936 Repairs: New conc. piers, new flashboards, new bridges

45
41.5

61-0

TOWN Worcester DAM NO. 60-05

LOCATION Whitney Pond STREAM Millers River

WORCESTER COUNTY ENGINEERING DEPARTMENT
WORCESTER, MASSACHUSETTS

DAM INSPECTION REPORT

Owned by _____ Place _____ Use _____

Inspected by M.F. Hunt Date Sept 9, 1967

Type of Dam _____ Condition OK

SPILLWAY

Flashboards in Place Part - on Recent Repairs _____

Condition Being watched by Devdrey

Repairs Needed _____

INTAKE

Recent Repairs _____

Repairs Needed _____

PIERS

Recent Repairs _____

Condition _____

Repairs Needed _____

ABUTMENT

Recent Repairs _____

County Engineer _____

NAME Whitney Pond

DAM NO. 60-05

LOCATION _____

STREAM _____

WORCESTER COUNTY ENGINEERING DEPARTMENT
WORCESTER, MASSACHUSETTS

D A M I N S P E C T I O N R E P O R T

Owned by _____ Place _____ Use _____

Inspected by T.C.M. - M.B.R. Date 3-6-69

Type of Dam _____ Condition _____

SPILLWAY

Some in place - holding back 1' of water ±

Flashboards in Place _____ Recent Repairs _____

Condition _____

Repairs Needed _____

Recent Repairs _____

Condition _____

Repairs Needed _____

GATES

closed - but water level has been lowered

Recent Repairs Inspected 3-11-69 same conditions as T

Condition _____

Repairs Needed _____

60-05

TOWN Worcester DAM NO. 60-05
LOCATION Whitney Pond STREAM Millers River

WORCESTER COUNTY ENGINEERING DEPARTMENT
WORCESTER, MASSACHUSETTS

D A M I N S P E C T I O N R E P O R T

Owned by _____ Place _____ Use _____
Inspected by M. E. [unclear] Date Nov 21 1960
Type of Dam _____ Condition Good

SPILLWAY

Flashboards in Place Yes Recent Repairs _____
Condition Good
Repairs Needed _____

Recent Repairs _____
Condition Good
Repairs Needed _____

GATES

Recent Repairs _____
Condition _____
Repairs Needed _____

TOWN Winchendon DAM NO. 10-05

LOCATION Along the center STREAM Millers River
at the P. & N. Railroad. "Whitney Pond"

WORCESTER COUNTY ENGINEERING DEPARTMENT
WORCESTER, MASSACHUSETTS

D A M I N S P E C T I O N R E P O R T

Owned by Town of Winchendon Place Selectman Use Storage Pond

Inspected by W.C.L. Date Nov. 22, 1967

Type of Dam Earth, stone and wood. Condition Good.

SPILLWAY

Flashboards in Place 6' of 4" thick boards Recent Repairs _____

Condition The automatic trips are ok. The steel work should

Repairs Needed be painted

WATER

Recent Repairs _____

Condition Removable boards

Repairs Needed _____

George Hodgson

DAM NO.

62-25

LOCATION

South of Whitney Pond

STREAM

Millers RiverWORCESTER COUNTY ENGINEERING DEPARTMENT
WORCESTER, MASSACHUSETTSWhitney Pond

DAM INSPECTION REPORT

Owned by

Town of Westborough

Place

Salisbury

Use

Excavation
Storage Pond

Inspected by

W.C.H.

Date

Nov. 2, 1958

Type of Dam

Earth - stone - concrete

Condition

Good

SPILLWAY

Flashboards in Place

11 @ 6" beams @ 5' 4"

Recent Repairs

Condition

Good condition. The beams have been removed.

Repairs Needed

There are holes in the concrete and the beams in
the concrete are about 2" from the beams.

PIERS

Recent Repairs

Condition

Good. The concrete is in good condition.

Repairs Needed

There are holes in the concrete and the beams in
the concrete are about 2" from the beams.

Whitchendon DAM NO. 60-05
LOCATION Sp. of Wm. Whitchendon Ck. STREAM Millers River

"Whitney Pond"
WORCESTER COUNTY ENGINEERING DEPARTMENT
WORCESTER, MASSACHUSETTS

D A M I N S P E C T I O N R E P O R T

Owned by Town of Whitchendon Place Selectman Use Storage
Inspected by WOL Date July 27, 1960
Type of Dam Stone - Concrete Condition Good

SEILWAY

Flashboards in Place 9 boards Recent Repairs _____
Condition Good
Repairs Needed _____

_____ Good _____
Repairs Needed _____

Gate
Recent Repairs _____
Condition No gate is visible
Repairs Needed _____

Will look over visible from Sky and on Lake

TOWN Winchendon DAM NO. 60-05
LOCATION near Winchendon etc. STREAM Millers River

"Whitney Pond."
WORCESTER COUNTY ENGINEERING DEPARTMENT
WORCESTER, MASSACHUSETTS

D A M I N S P E C T I O N R E P O R T

Owned by Town of Winchendon Place Selectman Use Storage P.
Inspected by WOL Date May 27, 1959
Type of Dam Earth and Stone Condition Good

SPILLWAY

Flashboards in Place 5' of boards Recent Repairs _____

Condition Trip beams for releasing boards. Plank walkway 2x12 etc.

Remarks Abutments etc. - Good condition

Condition Good condition

Repairs Needed (Pond full - with 1" of water over boards.)

GATES

Recent Repairs _____

Condition Plausible boards for gate

Repairs Needed _____

Winchendon, Mass. is situated at bottom of
ridge.

Location
Mill Pond

DAM NO. 42-01
STREAM Mill Pond

WORCESTER COUNTY ENGINEERING DEPARTMENT
WORCESTER, MASSACHUSETTS

DAM INSPECTION REPORT

Owned by Worcester Co. Electric Co. Place Worcester Use None
Inspected by E. F. Leach - LCM Date July 16, 1958
Type of Dam Grass to Martin - Mc Donald Condition Satisfactory

SPILLWAY

Blackboards in Place None Recent Repairs filled in spillway with approach
Condition Blackboard pile in place on top of spillway
Needed Blackboard pile in place on top of spillway

Needed _____
Repairs filled in spillway with approach
Needed Blackboard pile in place on top of spillway

COUNTY ENGINEER

Inspection of Dams, Reservoir Dams, and Reservoirs.
Harry Nelson-New England Lower

Inspected by L. O. Marden-Com. Jones & Crockett 11-21-38 Dam No. 60-05

Town Winchendon Location Whitney Pond.

Owner Winchendon Power & Lt Co. Use power.

Material and Type

Dam Designed by Constructed by Year

SPILLWAY

El. top Abutment El. Crest El. Apron El. Streambed

Width top Abutment Width top Crest Width bottom Spillway

Width Flashboards carried Kind Flashboards

El. Flowline Cleanout Pipe Size and Kind Cleanout Pipe

Kind of Foundation under Spillway

Condition examine condition of dam after 1938 Flood-Mr. Crockett wants
catwalk from shore to canal wall, so as to reach trips of needle beams
during high water-

EMBANKMENT

El. Top El. Natural Ground Width Top

Width of Bottom Upstream Slope Downstream Slope

Kind of Corewall Riprap

Material in Embankment Foundation

Condition it is agreed to replace riprap and reslope downstream embankment

GATES Location

Size Kind El. Flowline

Condition

WHEEL Kind Size Rated H. P.

Location Ave. Head

Evidence of Leaks in Structure

Recent Repairs and Date

Topography of Country below Dam


Nature of Buildings and Roads below Dam

Number Acres in Pond Drainage Area in Square Miles


Discharge in Second Feet per Square Mile

Estimated Storage Million Cubic Feet

MILLERS RIVER




PLAN



SECTION A-A


INFORMATION SHOWN TAKEN FROM PLANS
DATED 1936 & 1957 AND FROM FIELD
MEASUREMENTS

HAYDEN, HARDING & BUCHANAN, INC. CONSULTING ENGINEERS BOSTON, MASSACHUSETTS	U.S. ARMY ENGINEER DISTRICT NEW ENGLAND CORPS OF ENGINEERS WALTHAM, MASS.	
	NATIONAL PROGRAM OF INSPECTION OF NON-FED. DAMS	
WHITNEY POND		
WINCHENDON	MASSACHUSETTS	SCALE NOT TO SCALE DATE FEBRUARY, 1979




SECTION B-B

THIS EMBANKMENT CONSTRUCTED IN 1957



SECTION C-C



ELEVATION
LOOKING UPSTREAM

TAKEN FROM: WORCESTER COUNTY
COMMISSIONERS, WORCESTER COUNTY
ENGINEERING DEPT., DRAWING
NUMBER: H-3880-0 DATED 1936

1936 REVISIONS PROVIDED FOR 4'-8" OF STOPLOGS TOPPED WITH 2'-0" OF FLASHBOARDS

DATUM:
U.S.C&G BENCH MARK Y-7, 1933
UNADJUSTED ELEVATION 979.612' ± 101.15' (AS SHOWN)
ELEVATIONS SHOWN THUS (965.5) ARE
CONVERTED TO U.S.C&G DATUM.

HAYDEN, HARDING & BUCHANAN, INC. U.S. ARMY ENGINEER DN NEW ENGLAND
CONSULTING ENGINEERS COMPS OF ENGINEERS
BOSTON, MASSACHUSETTS WALTHAM, MASS

NATIONAL PROGRAM OF INSPECTION OF NON-FED DAMS


WHITNEY POND

WINCHENDON

MASSACHUSETTS

SCALE NOT TO SCALE
DATE: FEBRUARY, 1979

APPENDIX C
PHOTOGRAPHS



HAYDEN, HARDING & BUCHANAN, INC.
 CONSULTING ENGINEERS
 BOSTON, MASSACHUSETTS

U.S. ARMY ENGINEER ON NEW ENGLAND
 DISTRICT OFFICE
 WASHINGTON, MASS.

NATIONAL PROGRAM OF INSPECTION OF NON-FED. DAMS
 LOCATION OF PHOTOGRAPHS
 WHITNEY POND

WINCHENDON
 MASSACHUSETTS
 SCALE NOT TO SCALE
 DATE FEBRUARY, 1979



PHOTO NO. 1 - Crest of dam viewed from left abutment of railroad bridge.



PHOTO NO. 2 - General view of upstream face of dam viewed from the crest near the spillway training wall.



PHOTO NO. 3 - Downstream face of dam viewed from left wall of spillway towards left abutment.




PHOTO NO. 4 - Upstream view from railroad structure.



PHOTO NO. 5 - Right training wall of spillway.



PHOTO NO. 6 - Downstream view from dam.



PHOTOS NO. 7 & 8 - Panarama of spillway.



PHOTO NO. 9 - Toe of left training wall showing rebuilt section of wall and boulder fill on embankment.




PHOTO NO. 10 - Area at downstream toe viewed from crest about 100 feet left of spillway.



PHOTO NO. 11 - Downstream toe area viewed from vicinity of spillway training wall looking toward left abutment.




PHOTO NO. 12 - Upstream face of dam looking toward spillway.



PHOTO NO. 13 - Left training wall of spillway.




PHOTO NO. 14 - Stones piled in front of spillway.

APPENDIX D
HYDROLOGIC AND HYDRAULIC COMPUTATIONS



1/27

Clinton Pond Dam

Hydro. Data

See CoE Technical Report on the U.S. & State
Inspection

Sy. Hwy. width = 82

Imp. Road Capacity

1950 510 a.d.

1955 1450 a.d.

Storage 1000 25'

Hydro. Data

Hydro. Data

Sy. Hwy. Length = 82 ft.

SIZE CLASSIFICATION

See CoE Report

1950 510 a.d. → 2nd

1955 1450 a.d. → 1st

1950 510 a.d. → 2nd

NOTE: D. POTENTIAL FOR CONSTRUCTION

1950 510 a.d. → 2nd

1955 1450 a.d. → 1st

12/27



HAYDEN, HARDING & BUCHANAN, INC.
CONSULTING ENGINEERS
BOSTON MASSACHUSETTS

JOB D-1000-1000
SUBJECT ...
CLIENT C.E.

BY VI 12/27

Test flood = PMF

Drawings are to Dam.

detention on USSC Quon. Creek & plan method

$A = 53 \text{ sq. mi. (33920 a)}$ (Check: Re. input. Data
 $A = 53.7 \text{ sq. mi.}$

Peak Flood

using COF Flood Control Dam Tully & Birch Hill
- Fall between Flat-Coastal and Rolling, on
MPF Peak Flow Rates Chart

Use Rolling Terrain


PMF $1150 \text{ cfs/100} \times 53 \text{ mi}^2 = 60,950 \text{ cfs}$

Use PMF $60,950 \text{ cfs}$

Check Tully & Birch Hill

PMF $Q = 47,000 \text{ cfs}$

Use Tully & Birch Hill PMF $Q = 440 \text{ cfs}$



4' thick

Open space: 9.47% (27.56% of 34.2% = 9.47%)
 9.47% = 710/75 = 711 SF.

1. *Chlorophyll a* and *Chlorophyll b* were determined by the method of Arar and Collins (1971) using a Shimadzu 1010 spectrophotometer. The concentration of chlorophylls was expressed as $\mu\text{g mL}^{-1}$ of the sample.

* "The ... [Flower] ... [is] ... [to be] ... [reproducing]"

Amount Policy after the remain. interest being fixed

Contract for General Contracting (no blockages)

to wear buttons to obtain discounts.

$$C_2H_2$$

101 L = 715 (2000 large & yellow (mostly pro-lactes))

1. 2

C = 100 lbs. obtained from King's Hardware of
Haverhill.

for one day, $\text{opportunity} = 54$

72 1/2
 1111
 FEB
 BY P. 2/27



HAYDEN, HARDING & BUCHANAN, INC.
 CONSULTING ENGINEERS
 BOSTON MASSACHUSETTS

SHEET NO. 40

JOB D. ...
 SUBJECT ...
 CLIENT ...

5' ... C ... ty - No Blockage (see page 16)

H ₁	H ₂	C	L ₁	Q ₁	Elevation
0	-	-	-	-	968.8
0.5	0.35	2.60	73.5	65 ~ 70	969.3
1.0	1.0	2.65	"	197 ~ 200	969.8
2.0	2.83	2.65	"	551 ~ 550	970.8
3.0	5.20	2.65	"	1015.7 ~ 1020	971.8
4.0	8.0	2.70	"	1587.6 ~ 1590	972.8
5.0	11.18	2.77	"	2243 ~ 2270	973.8
6.0	14.70	2.91*	"	3133 ~ 3135	974.8
7.0	18.5		"	3943 ~ 3950	975.8
8.0	22.62		"	4813 ~ 4815	976.8
9.0	27.0		"	5725 ~ 5730	977.8
10.0	30.17		"	6410	978.5
11.0	33.6		"	6740	979.8
12.0	39.97		"	6443 ~ 6500	980.5
13.0	41.5		"	886	980.8
14.0	61.0		"	14,341 ~ 14550	982.5
15.0	62.6		"	14677 ~ 14680	983.6

* C value for 10' 2.5' ... 2.9 (concrete, esp. for bridge)
 between elev 975.8 & 978.5 Rail Road Bridge Block
 Floor to Spilling

... Embankment

... 1160' Quad Steel

$$L' = 100 \sqrt{\frac{A}{H}}$$

$$A = 75'H + 100'H^2$$

$$A = 25'H + 100'H^2$$

$$L' = 100 \sqrt{\frac{A}{H}}$$

... 25' H 50' ...



Spillway Blocked - Flow Over R.R. Embankment

Assume no spillway discharge (i.e. spillway blocked)

Flow over R.R. Embankment, H_{max} = 15'

outflow length from
USGS Map

H	H ^{3/2}	C	L'	Q	Elev.
0	0		730'		979
0.5	0.22	200	730	780	979.5
1.0	1.1	400	730	3110	980
1.5	1.84	600	730	4500	.5
2.0	2.8	800	730	7290	981
2.5	3.95	1000	730	10700	.5
3.0	5.20	1200	730	14770	982
3.5	6.55	1400	730	19470	.5
4.0	8.0	1600	730	24830	983
4.5	9.55	1800	730	30890	.5
5.0	11.18	2000	730	37640	984
5.5	12.88	2200	730	45120	.5
6.0	14.70	2400	730	53350	985
6.5	16.57	2600	730	62360	.5

Inflow

Spillway 4000 cfs
Embankment +57000 cfs
61000

Inflow = 61000 cfs
Elev. 985.25'

Spillway 0
Embankment 61000
Elev. 985.5'

If assume no spillway discharge (i.e. spillway blocked)
by debris, flow increases significantly by RR bridge
spilling over dam spillway, along entire PMF, this would
increase up stream flooding by about 0.25, to
elev. 985.25'.

JOB NO. 7-244.
DATE 3/3/75
BY HH & B
CH'D BY HH & B



HAYDEN, HARDING & BUCHANAN, INC.
CONSULTING ENGINEERS
BOSTON MASSACHUSETTS

SHEET NO. 5

JOB Dr
SUBJECT Let
CLIENT Cop

Outflow

$$Q_{p1} = 60950 \text{ cfs} \quad E_{cu1} = 985.25 (57000) \\ \text{Star}_1 = 3800 - 264 = 3536 \text{ c-f at } 1.25''$$

$$Q_{p2} = 60950 \left(1 - \frac{1.25}{19}\right) = 56930. (53000)$$

$$E_{c2} = 985.0 \quad \text{Star}_2 = 3720 - 264 = 3456$$

$$\text{Star}_{avg} = \frac{3456 + 3536}{2} = 3496$$

$$Q_{1/2} = 58,000^{\pm} \text{ cfs} \quad E_{c2} = 985.1$$

$$\text{Outflow} = 58,000^{\pm} \text{ cfs} \quad E_{cu} = 985.1$$

Spillway Flow 4000 cfs
Floodplain Flow 54000 cfs

$$985.1 - 978.5 = 6.6'$$

OR NO _____
 A _____
 V _____
 D BY _____



HAYDEN, HARDING & BUCHANAN, INC.
 CONSULTING ENGINEERS
 BOSTON, MASSACHUSETTS

SHEET NO. 7 of _____
 JOB D - Safety Inspection
 SUBJECT Whiting Pond Dam
 CLIENT CoT

Dam Storage at time of failure = 2200 ac-ft.
 at elev 950.5

II Discharge from Failure Outflow - Q_F

$$Q_F = 8/27 W_b \sqrt[5.674]{Y_0^{3/2}}$$

W_b = Breach Width - includes part of embankment

$$W_b = .4(82 + 1120) = 93' \quad (\text{see Pg 3})$$

Y_0 Total Height from River Bed to Top level of Failure

$$Y_0 = 950.5 - 954 = 27' \pm$$

$$Y_0 = 950.5 - 954 = 27' \pm$$

$$Q_F = 7.7 \times 93 \times \sqrt[5.674]{322 \times (27)^{1.5}} \approx 22,000 \text{ cfs.}$$

$Q_F = 22,000 \text{ cfs}$ at dam failure.

III How do "rough" routing of Failure Outflow discharge

Can use "I" approx 1000' distance of Whiting Pond Dam



$$S_0 = 0.0036\%$$

$$n = 0.03$$



HAYDEN, HARDING & BUCHANAN, INC.
CONSULTING ENGINEERS
BOSTON MASSACHUSETTS

JOB See Survey Map
SUBJECT Bridge
CLIENT State

use Manning's eqn:

② $H = 16'$

Elev. 950

$$A = \frac{1}{2}(16 \times 350 + 16 \times 325) = 5200 \text{ sf}$$

$$P = 350.4 + 300.4 = 650.8$$

$$R = 7.990$$

$$Q = \frac{1.49}{.03} \times (7.99)^{2.67} \times (.005)^{.485} \times 5200 = 2.93 \times 3.997 \times 5200 =$$

$$Q = 62363 \text{ cfs} > \text{reqd}$$

③ $H = 10'$

Elev. 154

$$A = \frac{1}{2} \times 10 \times (218.4 + 197.5) = 5 \times 406.3$$

$$A = 2031.5 \text{ sf}$$

$$P = 218.4 + 197.5 = 406.3$$

$$R = 4.9931$$

$$Q = 2.93 \times 4113.1 \times 2031.5 = 17,335 \text{ cfs} < \text{reqd}$$

④ $H = 13.1$

Elev. 957.1

$$A = \frac{1}{2} \times 13.1 \times (13.5 + 210.3 + 1.0) = 3426.26$$

$$P = 245.17 + 286.93 = 532.10$$

$$R = 6.5420$$

$$Q = 2.93 \times (6.542)^{2.67} \times (.005)^{.485} = 36570 > \text{reqd}$$

See Sheet II for S & Z

At Center of 1 Flow ch 955'

For Bridge at same place Rm 12 Bridge

Compute Volume of Storage in Pond

$$V_1 = A \times \text{Length} = \frac{2500}{43560} (1000) = 57$$


$$\text{Total } Q_p = Q_p (1 - \frac{V_1}{V}) = 22^K (.977) = 21500 \text{ cfs}$$

$$El_2 = 10.5 \quad St_{12} = \frac{2250}{1} (\frac{1}{43.56}) = 52$$

$$St_{12} = 54.5 \text{ ft}$$

$$Q_{12} = 22^K (\frac{54.5}{52}) = 21520$$

At 14 ft (Elev 12)



$$Q = CLH^{3/2}$$

<u>D</u>	<u>C</u>	<u>L</u>	<u>H^{3/2}</u>	<u>Q</u>
2	2.63	350	7.82	2600 ±
5	2.63	500	11.15	14700 ±
7	"	570	15.51	27,764 ±
6	"	540	14.7	20,873 ±
8	"	600	22.62	35,700 ±

Elev $\approx 961 \pm$
 $\approx 21500 \text{ OK}$


DR NO. 7
 DATE 1/25
 BY HH&B
 CHD BY HH&B



HAYDEN, HARDING & BUCHANAN, INC
 CONSULTING ENGINEERS
 BOSTON MASSACHUSETTS

SHEET NO. 10

JOB Dam
 SUBJECT Whitney Res.
 CLIENT Corps



Dam Assessment

- 14 houses 1' to 3' water damage
- 10 bldgs over 3' water damage
- 2 Roads 8' water damage

JOB NO. _____
 DATE _____
 BY _____
 CH'D BY _____



HAYDEN, HARDING & BUCHANAN, INC.
 CONSULTING ENGINEERS
 BOSTON MASSACHUSETTS

SHEET NO. 11

JOB _____
 SUBJECT _____
 CLIENT _____

Area to Winton Pond Dam

Drainage area covers 4 Quad Streets

① Peterborough, N.H. sub 1' = 1 mi = 5280'

$$R_1 = 3.67 \quad R_2 = 3.75 \quad R_3 = 3.72 \quad R_{av} = 3.71$$

$$A = 3.71 \text{ sq. mi.}$$

② Marshfield, N.H. sub 1' = 1 mi.

$$R_1 = .60 \quad R_2 = 0.59 \quad R_{av} = 0.59$$

$$A = 0.59 \text{ sq. mi.}$$

③ Ashburnham, Mass. sub 1" = 2000 ft.

$$S_{\text{average}} = 2000 \times 37.43 = 28.17 \text{ sq. mi.}$$

$$\text{SA: } R_1 = 25.72 \quad R_2 = 25.81 \quad R_3 = 25.75 \quad R_{av} = 25.76$$

$$A = 3.70 \text{ sq. mi.}$$

$$\text{A: } R_1 = 7.43 \quad R_2 = 7.44 \quad R_3 = 7.52 \quad R_{av} = 7.48$$

$$A = 1.07 \text{ sq. mi.}$$

$$\text{AS: } R_1 = 1941 \quad R_2 = 1944 \quad R_3 = 1944 \quad R_{av} = 1944$$

$$A = \dots$$

JOB NO. 72
 DATE 12-11-72
 BY MP
 CH'D BY MP



HAYDEN, HARDING & BUCHANAN, INC.
 CONSULTING ENGINEERS
 BOSTON, MASSACHUSETTS

SHEET NO. 1
 JOB D.A.M.S.
 SUBJECT WATERWAY
 CLIENT Coopers

③ Winchendon Mass. - H.H. $1" = 2000'$

SA1 $R_1 = 37.01$ $R_2 = 37.65$ $R_3 = 37.73$ $R_{avg} = 37.69$
 $A = 5.41 \text{ sq. m.}$

SA2 $R_1 = 50.53$ $R_2 = 50.45$ $R_3 = 50.36$ $R_{avg} = 50.45$
 $A = 7.24 \text{ sq. m.}$


Summary

	A	Total A	ΣA
①	3.71	3.71	3.71
②	0.57	0.57	4.28
③	37.41 5.41 +29.17	37.73	40.03
④	54.17 7.24	12.65	52.69


Total area $\Sigma A = 53 \text{ sq. mi.}$

WHITNEY POND

PLAN



1" = 100'
(APPROX.)



SECTION A-A

1" = 20'
(APPROX.)

FROM 11-12-78
R.H.C. FIELD NOTE

BNO 2-1
 DATE 11-1-57
 BY HH&B




HAYDEN, HARDING & BUCHANAN, INC.
 CONSULTING ENGINEERS
 BOSTON MASSACHUSETTS

SHEET NO. 1

JOB DAMS
 SUBJECT WATER
 CLIENT USPS

Sta. 1000

<u>Elev</u>	<u>L</u>	<u>Area</u>	<u>Ave Area</u>	<u>Sta</u>	<u>Accum S</u> <u>(±)</u>
954	—	5	—	—	—
960	6	20	12	72	72
966	6	44	32	192	264
969	3	56	50	150	414
970	1	60	58	58	472
977	2	108	84	168	640
981	8	280	194	1552	2192
986	6	340	310	1860	4052
990	4	379			



Storage, a-f


DR NO. 782
 DATE 3/19/11
 BY WJ
 10 BY




HAYDEN, HARDING & BUCHANAN, INC.
 CONSULTING ENGINEERS
 BOSTON MASSACHUSETTS

SHEET NO. 15

JOB L-10
 SUBJECT U.S. ... Pond
 CLIENT C.R.



* Spillway BLOCKED - Flow over embankment *
 Q x 1000 cfs



HAYDEN, HARDING & BUCHANAN, INC.
CONSULTING ENGINEERS
BOSTON, MASSACHUSETTS

U.S. ARMY ENGINEER DIV. NEW ENGLAND
CORPS OF ENGINEERS
WALTHAM, MASS.

NATIONAL PROGRAM OF INSPECTION OF NON-FED. DAMS


WHITNEY POND DAM

WINCHENDON

MASSACHUSETTS

SCALE 1" = 250,000"

DATE: FEBRUARY, 1973



APPENDIX E

INFORMATION AS CONTAINED IN THE
NATIONAL INVENTORY OF DAMS

7-10-79

INVENTORY OF DAMS IN THE UNITED STATES

STATE	COUNTY	DIST.	CONGR. DIST.	NAME	LATITUDE (NORTH)	LONGITUDE (WEST)	REPORT DATE
MA	WINDHAM	10	1	WHITNEY POND	42 41.0	72 02.5	23 FEB 79

POPULAR NAME	NAME OF IMPROVEMENT
WHITNEY POND	WHITNEY POND
RIVER OR STREAM	NEAREST DOWNSTREAM CITY - TOWN - VILLAGE
WILLERS RIVER	WINCHESTER
POPULATION	DIST. FROM DAM (MI.)
6655	0

YEAR COMPLETED	PURPOSES	STORAGE CAPACITY (ACFT.)	IMPOUNDING CAPACITIES (ACFT.)	MAXIMUM HEAD (FT.)	POWER CAPACITY (KW)	INSTALLED	PROPOSED	LENGTH (FT.)	WIDTH (FT.)	HEIGHT (FT.)	LENGTH (FT.)	WIDTH (FT.)	HEIGHT (FT.)
1971	CM	25	21	2186	410	NED	N	N	N	N	N	N	N

FIRST OWN FED R PRV/FED SCS A VER/DATE

07MAR79

REMARKS

OWNER	ENGINEERING BY	CONSTRUCTION BY

DESIGN	CONSTRUCTION	OPERATION	MAINTENANCE

INSPECTION BY	INSPECTION DATE	INSPECTION DATE	INSPECTION DATE
RAYDEN, HARDING & RUCHANAN, INC	13 NOV 78	13 NOV 78	13 NOV 78

INSPECTION DATE	INSPECTION DATE	INSPECTION DATE	INSPECTION DATE
13 NOV 78	13 NOV 78	13 NOV 78	13 NOV 78

31 PROVISIONS FOR 7 FT FLASHED GARDS

REMARKS