



MICROCOPY RESOLUTION TEST CHART NATIONAL BUREAU OF STANDARDS-1963-A



REPORT DOCUME	NTATION PAGE	READ INSTRUCTIONS BEFORE COMPLETING FORM
REPORT NUMBER	2. GOVT ACCESSIO	N NO. 3. RECIPIENT'S CATALOG NUMBER
MA 00792	AD-NISS	493
TITLE (and Subility)	·	5. TYPE OF REPORT & PERIOD COVERED
Somerset Reservoir Dam		INSPECTION REPORT
ATIONAL PROGRAM FOR INSPEC	TION OF NON-FEDERAL	5. PERFORMING ORG. REPORT NUMBER
AUTHOR(a)		8. CONTRACT OR GRANT NUMBER(#)
J.S. ARMY CORPS OF ENGINEEF HEW ENGLAND DIVISION	RS	
PERFORMING ORGANIZATION NAME A	ND ADDRESS	10. PROGRAM ELEMENT. PROJECT, TASK AREA & WORK UNIT NUMBERS
CONTROL LING OFFICE NAME AND AD		
DEPT. OF THE ARMY, CORPS OF	ENGINEERS	September 1978
EW ENGLAND DIVISION, NEDER)	13. NUMBER OF PAGES
MONITORING AGENCY NAME & ADDRI	MA. UZZ34 ESS(II dillerent tran Centrolling Dif	- 70 Ico) 18. SECURITY CLASS. (af this report)
	•	
		UNCLASSIFIED
DISTRIBUTION STATEMENT (of this Re PPROVAL FOR PUBLIC RELEASE	: DISTRIBUTION UNLIMI	TED
DISTRIBUTION STATEMENT (of this Report of the statement o	DIVECT ENTOTED IN BIOCH 20, 11 different	TED
DISTRIBUTION STATEMENT (of this Re PPROVAL FOR PUBLIC RELEASE DISTRIBUTION STATEMENT (of the obt	DISTRIBUTION UNLIMI	TED
DISTRIBUTION STATEMENT (of this Re PPROVAL FOR PUBLIC RELEASE DISTRIBUTION STATEMENT (of the obt	DISTRIBUTION UNLIMI	TED
DISTRIBUTION STATEMENT (of this Re PPROVAL FOR PUBLIC RELEASE DISTRIBUTION STATEMENT (of the obt supplementary notes over program reads: Phase owever, the official title on-Federal Dams; use cove	I Inspection Report, I of the program is: Na er date for date of rep	National Dam Inspection Program; ational Program for Inspection of port.
DISTRIBUTION STATEMENT (of this Re PPROVAL FOR PUBLIC RELEASE DISTRIBUTION STATEMENT (of the obs SUPPLEMENTARY NOTES over program reads: Phase owever, the official title on-Federal Dams; use cove KEY WORDS (Continue on reverse olde the DAMS, INSPECTION, DAM SAF	I Inspection Report, I of the program is: No r date for date of rep ETY,	Vational Dam Inspection Program; ational Program for Inspection of port.
DISTRIBUTION STATEMENT (of this Re PPROVAL FOR PUBLIC RELEASE DISTRIBUTION STATEMENT (of the observation of the observation statement (of the observation of the ob	I Inspection Report, I of the program is: No of the program is: No of the for date of rep necessary and identify by block and ETY, d Coastal Basin	National Dam Inspection Program; ational Program for Inspection of port.
DISTRIBUTION STATEMENT (of this Re PPROVAL FOR PUBLIC RELEASE DISTRIBUTION STATEMENT (of the observation of the observation statement (of the observation of the ob	I Inspection Report, I of the program is: No er date for date of rep Tracessery and identify by block and ETY, d Coastal Basin	National Dam Inspection Program; ational Program for Inspection or port.
DISTRIBUTION STATEMENT (of this Re PPROVAL FOR PUBLIC RELEASE DISTRIBUTION STATEMENT (of the observed SUPPLEMENTARY NOTES OVER PROGRAM reads: Phase OVER program reads: Phase OVER, the official title on-Federal Dams; use cove KEY WORDS (Continue on reverse side // DAMS, INSPECTION, DAM SAF Massachusetts-Rhode Islam Som:Eset Massachusetts Labor-in Vain Brook ABSTRACT (Continue on reverse side // The reported a vac formed	I Inspection Report, I of the program is: No of the program is: No of the for date of rep necessary and identify by block and ETY, d Coastal Basin	Vational Dam Inspection Program; ational Program for Inspection of port.

.....

.

. . . .

٠.

٠.

ŀ

٦.

-

SOMERSET RESERVOIR DAM MA 00792

T.

. .

l

-

1

Ĺ

MASSACHUSETTS-RHODE ISLAND COASTAL BASIN SOMERSET, MASSACHUSETTS

PHASE I INSPECTION REPORT NATIONAL DAM INSPECTION PROGRAM



PHASE I INVESTIGATION REPORT NATIONAL DAM INSPECTION PROGRAM

Identification No.: Name of Dam: Town: County: State: Stream: Date of Site Visit: MA 00792 Somerset Reservoir Somerset Bristol Massachusetts Labor-In-Vain Brook 19 July 1978

BRIEF ASSESSMENT

Somerset Reservoir was formed by an "intermediate" size dam build in 1965 to create an offstream water supply for the Town of Somerset. The dam consists of an earth embankment approximately 6700 ft. long with a maximum height of 45 ft. There is a small "emergency spillway" at the north end of the dam and two 20-in. outlet pipes from an intake tower in the reservoir. Somerset Reservoir is currently classified as having a "high" hazard potential in the Corps of Engineers National Inventory of dams.

Based on visual examination, the earth embankment is generally in excellent to good condition. While there was no evidence of settlement, lateral movement or other serious defects, there were indications that seepage is occurring in two areas on the downstream slope, although no actual seepage flow, boils or erosion were observed. Riprap and screened gravel bedding have been eroded by wave action in localized areas.

Hydraulic analyses indicate that the reservoir has the storage capacity to contain entering runoff from the test flood, which is based on the probable maximum flood, without overtopping the dam.

Recommendations for additional investigations of the cause and extent of embankment seepage and the effect of seepage on slope stability are included in Section 7.2.

Finally, recommendations for remedial work including clearing and mowing the downstream slope and emergency spillway and channel, repairing riprap in localized areas, replacing the abuter ment foundation for the access bridge to the intake tower and preparing formal plans for operation and maintenance to the dam and

£

and for action in the event of an emergency are described in Section 7.3.

HALEY & ALDRICH, INC. by: /

3

•

j.

-

1

ľ

t Harl Aldrich

President



PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D. C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I Investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I investigations are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the test flood is based on the estimated "probable maximum flood" for the region (greatest reasonably possible storm runoff), or a fraction thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

iv

TABLE OF CONTENTS

.

1

Ļ

.

·	Page No.
LETTER OF TRANSMITTAL	
BRIEF ASSESSMENT	i
REVIEW BOARD SIGNATURE SHEET	iii
PREFACE	iv
TABLE OF CONTENTS	▼
OVERVIEW PHOTO	vii
LOCATION MAP	viii
	••••
SECTION 1 - PROJECT INFORMATION	•
1.1 GENERAL	1
1.2 PROJECT DESCRIPTION	2
1.3 PERTINENT DATA	5
	-
SECTION 2 - ENGINEERING DATA	
2.1 DESIGN RECORDS	8
2.2 CONSTRUCTION RECORDS	8
2.3 OPERATION RECORDS	8
2.4 EVALUATION	8
SECTION 3 - VISUAL EXAMINATION	
3.1 FINDINGS	9
3.2 EVALUATION	11
SECTION 4 - OPERATIONAL PROCEDURES	
4.1 PROCEDURES	12
4.2 MAINTENANCE OF EMBANKMENT	12
4.3 MAINTENANCE OF OPERATING	12
FACILITIES	
4.4 DESCRIPTION OF ANY WARNING	12
SYSTEM IN EFFECT	
4.5 EVALUATION	12
SECTION 5 - HYDRAULIC/HYDROLOGIC	
5.1 EVALUATION OF FEATURES	13
	20
SECTION 6 - STRUCTURAL STABILITY	
6.1 EVALUATION OF STRUCTURAL	16
STABILITY	

V

TABLE OF CONTENTS (Continued)

Ĩ.

.

~

Ì

.

Ì

١.

Page No.

SECTION 7 ·	- ASSESSMENT, RECOMMENDATIONS	
	AND REMEDIAL MEASURES	
7.1	DAM ASSESSMENT	17
7.2	RECOMMENDATIONS	17
7.3	REMEDIAL MEASURES	18

- APPENDIX A INSPECTION TEAM ORGANIZATION AND CHECK LIST
- APPENDIX B LIST OF AVAILABLE DOCUMENTS AND PRIOR INSPECTION REPORTS
- APPENDIX C SELECTED PHOTOGRAPHS OF PROJECT
- APPENDIX D OUTLINE OF DRAINAGE AREA AND HYDRAULIC COMPUTATIONS
- APPENDIX E INFORMATION CONTAINED IN THE NATIONAL INVENTORY OF DAMS



ŧ.

ľ.

ŀ

î. N

,

Ľ

Somerset Reservoir Dam (Spring, 1978)

PHASE I INVESTIGATION REPORT NATIONAL DAM INSPECTION PROGRAM SOMSERSET RESERVOIR DAM MA 00792

SECTION 1 - PROJECT INFORMATION

1.1 GENERAL

₹.

ſ

.

...

.

1

A. <u>Authority</u>. Public Law 92-367, August 8, 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a National Program of Dam Inspection throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region.

Haley & Aldrich, Inc. has been retained by the New England Division to inspect and report on selected dams in the State of Massachusetts. Authorization and notice to proceed were issued to Haley & Aldrich, Inc. under a letter dated 26 April 1978 from Colonel Ralph T. Garver, Corps of Engineers. Contract No. DACW33-78-C-0301 has been assigned by the Corps of Engineers for this work. Camp, Dresser & McKee, Inc. was retained as consultant to Haley & Aldrich, Inc. on the structural, mechanical/electrical and hydraulic/hyrologic aspects of the investigation

B. <u>Purpose</u>. The primary purposes of the National Dam Inspection Program are to:

1. Perform technical inspection and evaluation of non-Federal dams to identify conditions which threaten the public safety and thus permit correction in a timely manner by non-Federal interests.

2. Encourage and prepare the states to initiate quickly effective dam safety programs for non-Federal dams.

3. To update, verify and complete the National Inventory of Dams.

1.2 PROJECT DESCRIPTION

Ī

ľ

١

Í

A. Location. The Somerset Reservoir dam is located on Labor-In-Vain Brook in the Town of Somerset in Bristol County, Massachusetts, as shown on the Location Map, page viii.

B. Dam and Appurtenances. The dam at Somerset Reservoir consists of an earth embankment approximately 6500 ft. long, an intake tower for water supply and an emergency spillway, as shown on the "Site Plan Sketch" included in Appendix C-1.

The earth embankment is a homogeneous structure of "compacted glacial till and pervious fill" with a 15-in. concrete core wall set at the centerline. The core wall bears on a 3 ft.-3 in. wide footing.

The maximum height of the embankment is about 45 ft. and the crest is about 18 to 20 ft. wide. The upstream and downstream slopes are 2 horizontal to 1 vertical. There is a 6 ft. wide berm at El. 25 on the downstream slope where the embankment is high. The upstream slope is paved with dumped riprap on a screened gravel bedding. The downstream slope is covered by tall grass and weeds.

Internal drainage features include a 10-in. drain placed immediately downstream of the concrete core wall and 6-in. toe drains. The drain pipe are porous wall concrete and they discharge at two locations, Sta. 10+00 and 42+00.

The outlet works for water supply include a reinforced concrete intake tower on the reservoir side with a 44 ft. long access bridge at Sta. 12+20 and two parallel 20-in. ductile iron discharge pipes. Water may enter the intake tower through a lower level intake in the reservoir at approximately El. 18.5 or through two 16-in. by 16-in. intakes in the tower at El. 35.0 and El. 50.0.

From the intake tower, one 20-in. pipe acts as a reservoir drain by discharging at the toe of the dam into a paved gutter leading to Labor-In-Vain Brook. The second 20-in. pipe feeds the treatment plant. This pipe is under full hydrostatic pressure.

Details and sections at the outlet works are shown on a drawing by Whitman & Howard, Inc. in Appendix B-2. The location of the outlet works is shown in the "Site Sketch Plan", Appendix C-1.

A water treatment plant has been constructed immediately downstream of the outlet works.

An "emergency spillway" leading into an overflow ditch provide d at the north end of the reservoir. The approach channel is basically the bed of Labor-In-Vain Brook which normally flows into the reservoir. When the water level rises, water backs up the channel through two 36-in. diameter concrete culvert pipes under relocated North St. Immediately north of North St., on the east side of the brook channel, a short trapezoidal "spillway" has been constructed through a low earth embankment. The bottom width of the spillway is about 6 ft. Once water discharges over the spillway, it flows in an easterly direction toward Broad Cove. The elevation of the "spillway" is said to be approximately 58.0.

C. <u>Size Classification</u>. Somerset Reservoir has an estimated maximum storage of 2700 acre-feet and the embankment has a maximum height of about 45 ft. Storage of from 1000 to 50,000 acre-feet and a height of from 40 to 100 ft. classifies the dam in the "intermediate" size category, according to guidelines established by the Corps of Engineers.

ł

D. <u>Hazard Classification</u>. Somerset Reservoir is currently classified as having a "high" hazard potential in the Corps of Engineers National Inventory of Dams. Computations based on "Guidance for Estimating Downstream Dam Failure Hydrograph", included in Appendix D, confirm this classification. A failure of the embankment, depending on its location, would probably cause loss of life and extensive property damage.

For example, if the southeasterly sector of the dam failed, the houses south of St. Patrick's Cemetery and west of County Street would be very susceptible to flooding. It is estimated that a total of ten homes, the water filtration plant, and a shopping center on County Street adjacent to Whetstone Hill Road would be affected by a dam failure. In addition to the aforementioned damage to surrounding structures, it is also probable that Whetstone Hill Road and County Street culverts would be washed out. Therefore, it is recommended that the current hazard potential classification of "high" be retained.



E. Ownership. The dam and reservoir are owned by the Town of Somerset. The address of the owner is Somerset Water Department, 3249 County St., Somerset, MA 02726 (phone 617/679-2731). Mr. Joseph Gosselin, Superintendent, acted as owner representative during this investigation.

Ē

T

F. Operator. Mr. Joseph Gosselin, Superintendent of the Somerset Water Department, is responsible for operation and maintenance of the facility.

G. <u>Purpose of Dam.</u> Somerset Reservoir serves only as a water storage reservoir for the Town of Somerset. It impounds water from Labor-In-Vain Brook and water pumped from the Segreganset River at a point some four miles north of the reservoir.

H. Design and Construction History. Design of the Somerset Reservoir project was started in 1963 by the engineering firm of Whitman & Howard, Inc., Wellesley, MA. The intent was to create an offstream water supply reservoir to furnish a safe yield of 4,000,000 gallons per day for the Town of Somerset, MA. Details of the reservoir construction were published in the 31 January 1966 issue of New England Construction and summarized below.

Construction began about 1965 and was let in several contracts. One contract involved building a dam and a 15-MGD capacity low-lift pumping station on the banks of the Segreganset River. Under another contract, 19,000 linear ft. of 30-in. pipe was laid to carry water from the river to the north end of the reservoir construction site.

The site of the reservoir consisted mainly of wet fields and swamps underlain by glacial till. About 175 acres were cleared, North Street and several houses were relocated, and some 30,000 cu. yds. of soft topsoil were stripped from the area prior to construction of the embankment.

Approximately 500,000 cu. yds. of glacial till was excavated from the reservoir site and placed to form the embankment of the 6700-ft. long crescent-shaped dam. The dam was built about a vertical core wall for which 8500 cu. yds. of concrete were placed. The 36,000 cu. yds of riprap required for the upstream face was obtained from the old stone walls that abounded in the area. Salah & Pecci of Canton, MA was the contractor for construction of the dam.

I. <u>Normal Operating Procedures</u>. Water is pumped to the reservoir through a 30-in. pipe from the Segreganset River primarily from fall to spring. Water is taken from the reservoir for water supply by a 20-in. pipe. The reservoir can be controlled by a second parallel 20-in. pipe which serves as a reservoir drain.

There are no formal operational and maintenance procedures at Somerset Reservoir.

1.3 PERTINENT DATA

Ī

1 March

Ľ

-

1

All record plans for Somerset Reservoir are on U.S.G.S. Mean Sea Level Datum (MSL).

A. Drainage Area. The drainage area at the outlet from Somerset Reservoir is 922 acres (1.44 square miles). The lake surface comprises 165 acres (17.9 percent) of this total. The topography of the watershed is coastal to rolling with an average slope of approximately 1 percent. The majority of the watershed is wooded with small sections of marshland and residential development.

B. Discharge at Damsite

1. Outlet works (conduits)	20-in. with invert El. 14.5 at toe of dam
2. Maximum known flood at dam site	No significant floods in area since reser- voir constructed in 1965
3. Ungated spillway capacity at top	
of dam	Not applicable
4. Ungated spillway capacity at test	
flood pool elevation	Not applicable
5. Gates spillway capacity at normal	
pool elevation	Not applicable
6. Gated spillway capacity at test	
flood pool elevation	Not applicable
7. Total spillway capacity at test	
flood pool elevation	Not applicable
8. Total project discharge at test	
flood pool elevation	56 cfs at El. 59.2

с.	Elevation (ft. above MSL)	
	1. Top of dam	59.5 at center of roadway
	 Test flood pool-design surcharge Design surcharge - original design Full flood control pool Recreation pool "Emergency Spillway" crest Upstream portal invert diversion tunnel Streambed at centerline of dam Maximum tailwater 	59.2. Unknown 56.0 Not applicable 58 (Est.) Not applicable 18 (Est.) Not applicable
D.	Reservoir	
	 Length of maximum pool Length of recreation pool Length of flood control pool 	0.85 mi. (Est.) Not applicable 0.85 mi. (Est.)
E.	Storage (acre-feet)	
	 Top of dam Test flood pool Flood control pool Recreation pool Spillway crest 	2700 2650 2090 Not applicable Not applicable
F.	Reservoir Surface (acres)	
	 Top of dam Test flood pool Flood-control pool Recreation pool Spillway crest 	182.7 (Est.) 181.3 (Est.) 165.0 (Est.) Not applicable Not applicable
G.	Dam	

I

٢

1.	Type	Earth (homogeneous)
2.	Length	6500 feet
3.	Height	45 feet max.
4.	Top Width	20 feet

5.	Side Slopes	2:1 U/S and D/S
6.	Zoning	Probably none
7.	Impervious Core	15-in. concrete wall
8.	Cutoff	None
9.	Grout curtain	None
10.	Other	Core wall drain and

H. Diversion and Regulating Facilities. Not applicable.

I. "Emergency Spillway" (to overflow ditch)

ĭ

I

•

į

1. Type	Vegetated trapezoid- al overflow channel located north of North Street
 Length Crest elevation 	About 6 feet Invert of overflow channel at Labor-In- Vain Brook is El. 58 (Est.)
4. Gates	None
5. U/S Channel	2 percent (Est.)
6. D/S Channel	2 percent (Est.)

J. <u>Regulating Outlets</u>. Two 20-in. Class 250 mechanical joint ductile iron pipes serve as the dam's regulating outlets. One pipe acts as the reservoir drain and has an invert at El. 14.5 at the toe of the dam. The other pipe carries flow to the water treatment plant. Two sluice gates serve as the inlet control for the pipe leading to the water treatment plant and one sluice gate controls the drain. In addition, there is a gate valve at the head end of each pipe and a butterfly valve is located at the downstream end of the line to the water treatment plant.

During an impending emergency, and assuming that the reservoir's water surface elevation is at its normal level of EL.56 msI, the opening of the 20-inch drain would cause the elevation of the reservoir to fall an estimated 2 ft. (approximately 5 percent of the total water depth of 41.5 feet) in the first 24 hours. However, it should be noted that as the water surface elevation drops, the drain's capacity also decreases. Therefore, a 2 ft. drop in 24 hours is the maximum rate that could safely be expected to occur. An analysis of the brook channel downstream of the drain outlet demonstrated that it can handle this flow out of the drain.

SECTION 2 - ENGINEERING DATA

2.1 DESIGN RECORDS

ľ

.

ï

The contract drawings and specifications by Whitman & Howard, Inc. of Wellesley, MA are available and listed in Appendix B-1. However, no design calculations could be located by Whitman & Howard, Inc.

2.2 CONSTRUCTION RECORDS

The original construction contract documents are listed in Appendix B-1. Whitman & Howard, Inc. supervised construction operations, but no inspection reports or records of those operations were available.

2.3 OPERATION RECORDS

Operational records in the form of water level readings, water pumped to the reservoir and water taken for water supply are available.

There are no records of flow from the core wall drain in the dam and from embankment toe drains.

2.4 EVALUATION

A. <u>Availability</u>. Design and construction records are available at Whitman & Howard, Inc., 45 William Street, Wellesley, MA 02181. Operation records are available at the Somerset Water Department, 3249 County Street, Somerset, MA 02726.

B. <u>Validity</u>. No reason was found to question the validity of the available information.

C. <u>Adequacy</u>. The available data, in combination with the visual examination described in the following section, are adequate for the purpose of the Phase I investigation.

SECTION 3 - VISUAL EXAMINATION

3,1 FINDINGS

E

Ĩ

_

• •

Ĺ

1

A. <u>General</u>. The Phase I visual examination of the Somerset Reservoir Dam was conducted on 19 July 1978.

In general, the project was found to be in excellent to good condition. A few deficiencies which require correction were noted.

A visual inspection check list is included in Appendix A and selected photographs of the project are given in Appendix C.

B. Dam. The earth embankment is generally in excellent to good condition. There was no evidence of settlement, lateral movement or other serious defects. The upstream slope which is paved with dumped cobble-boulder riprap is in good condition except for localized areas. The usual condition is shown in Photo No. 2. Except for two areas in which seepage is occurring, the downstream slope is also in good condition.

The following deficiencies were noted:

- Riprap and screened gravel bedding have been eroded by wave action in localized areas, Photo No. 4. While repairs to the riprap are common in the vicinity of Sta. 35+00 to Sta. 50+00, Photo No. 3, other areas need attention to prevent progress sive erosion.
- 2. Two areas of seepage on the downstream slope were noted. The first, and most important, is located in the vicinity of Sta. 9+00, Photos No. 5 and 6. The top of the wet area, in which cattails are growing, is approximately 8 ft. vertically above the berm. Water is ponded on the berm and the wet area extends to the toe of the embankment and beyond. No actual seepage flow, boils or erosion were observed.

The second area of seepage, and the only other location where the toe of the 6500 ft. embankment was wet, occurs about Sta. 14+50. Again, no flow was observed.

3. Knee-high to waist-high grass, weeds, brush and occasional saplings cover the downstream slope, Photo No. 7. Grass

is mowed on the dam crest only, Photo No. 1. Because of the grass, the slope was very difficult to examine carefully.

4. Numerous animal holes, probably woodchuck, were observed on the downstream slope. Since the dam has a concrete core wall, the presence of these holes is not considered significant.

The core wall drains and toe drains discharge at two locations beyond the downstream toe of the dam, Sta. 10+00 and Sta. 42+00. At each location, a 10-in. porous wall concrete pipe flanked by two 6-in. porous wall pipes discharge at a stone headwall. All six pipes were flowing. Photo No. 8 shows the three pipes at Sta. 10+00 after weeds and grass were cleared. Photos No. 9 and 10 show the submerged drain pipes at Sta. 42+00 and a wet swampy area which occurs downstream of the point of discharge. Water discharging from the pipes was clear and cold except for floating flecks of rust-brown organic matter. This material has stained the invert of the pipe and the stream beds as shown on the photographs.

C. <u>Appurtenant Structures</u>. Concrete for the intake tower was found to be in excellent condition. The access bridge to the intake, Photo No. 11, was found to have substantial compressive stresses locked into the top and bottom chords of the steel trusses. This has resulted in a small but noticeable bow to the structure. The abutment has moved downward and outward since the original construction. The abutment received a concrete mortar facing, the front and sides of which have further cracked and moved downward and outward, Photo No. 12. This mortar facing, when installed, locked the bridge to the abutment, resulting in the aforementioned compressive force.

The hand-operated value to the 20-in. reservoir drain, located at the intake tower, was operated and appears to be in satisfactory condition.

Photo No. 13 shows the outlet of the 30-in. diameter intake pipe, located at the north end of the reservoir, which delivers water to Somerset Reservoir from the Segreganset River.

The only outlet from the reservoir, other than the reservoir drain and intake pipe to the water treatment plant, is the emergency spillway described in Section 1.2B. While the approach channel and

culverts were in satisfactory condition, Photos No. 14 and 15, the spillway and discharge channel are overgrown with brush and small trees. In fact, the spillway is totally obscured by vegetation, Photo No. 16. Debris in the form of discarded pipes was found in the channel below the "spillway".

D. <u>Reservoir Area</u>. The area around the west side of Somerset Reservoir is generally wooded with relatively flat slopes. There are no conditions which would lead to a significant increase in sediment load to the reservoir or landslides which would cause waves to overtop the dam.

E. <u>Downstream Channel</u>. With construction of Somerset Reservoir, Labor-In-Vain Brook carries discharge from the reservoir drain when opened, and flow from underdrains at Sta. 10+00. The channel is more than adequate to carry these flows.

The channel below the emergency spillway has been discussed in Section 3.1C.

3.2 EVALUATION

ľ

Ł

While the Somerset Reservoir dam and appurtenant structures are generally well maintained and in excellent to good condition, there are a few deficiencies which require correction. Nevertheless, there appears to be no significant potential for failure of the dam.

SECTION 4 - OPERATIONAL PROCEDURES

4.1 PROCEDURES

In general, there are no formal operation and maintenance procedures for Somerset Reservoir except for regulation of water levels. Water level in the reservoir is recorded. When the level approaches normal pool level or just above, the reservoir drain is opened to maintain the water level at this elevation. Since the structure is primarily pump storage, the water level can be controlled by the amount of pumping to the reservoir and by the control exercised through the use of the reservoir drain.

4.2 MAIN TENANCE OF DAM

There are no known procedures to require inspection and routine maintenance of the dam and emergency spillway. Except for occasional mowing of grass which covers the embankment crest and repairs to riprap when and where localized erosion occurs, the dam does not receive regular maintenance.

4.3 MAINTENANCE OF OPERATING FACILITIES

The visual inspection indicated that the gates and other operating facilities are well maintained.

4.4 DESCRIPTION OF ANY WARNING SYSTEM IN EFFECT

There is no emergency preparedness plan or warning system in effect for this dam.

4.5 EVALUATION

The emergency spillway requires maintenance to insure its operation as previously mentioned in Section 3. Other areas appear to be well maintained including the operating facilities. A warning system should be formalized for the structure.

For a high hazard structure of this importance, operation and maintenance procedures for Somerset Reservoir should be formalized to assure periodic inspection and continued good maintenance and satisfactory operation. An emergency preparedness plan should also be adopted.

SECTION 5 - HYDRAULIC/HYDROLOGIC

5.1 EVALUATION OF FEATURES

ľ

A. <u>Design Data</u>. A set of plans entitled "Proposed Surface Water Supply Reservoir - Somerset, Mass." bearing the date of September 1964 were the basis for the construction of this facility. This reservoir was constructed in order to solve the water supply problem for the town. It was designed for a safe yield of 4,000,000 gallons of water per day. However, no hydraulic design data were found for Somerset Reservoir Dam.

The recommended test flood for the size (intermediate) and hazard potential classification (high) of this dam is the probable maximum flood (PMF).

B. Experience Data. Because of the small magnitude of the drainage area, the "SCS-TP-149, Method for Estimating Volume and Rate of Runoff in Small Watersheds" was used as a guide for determining the inflow hydrograph into Somerset Reservoir for the PMF. The PMF was based on a 25-in. rainfall in 6 hours. The peak inflow rate generated from the entire watershed was 5160 cfs.

However, since the volume of runoff entering the reservoir from the northern section of the watershed, upstream of North Street, is controlled by the twin 36-in. culverts, the majority of the Now from the northern portion of the watershed follows the course of the overflow ditch and eventually empties into Broad Cove. At the time of the peak of the storm, only approximately 11 percent (440 cfs) of the flow from the northern drainage area would enter the reservoir via the twin 36-in. R. C. pipes and an estimated 89 percent (3690 cfs) would exit via the overflow ditch.

The peak inflow rate generated from the portion of the watershed which drains immediately into Somerset Reservoir, approximately 362 acres, was approximately 2980 cfs. (This value includes the effect of rainfall directly on the reservoir.) When routed through the reservoir, the value of 2980 cfs was reduced to a mere 56 cfs (capacity for the 20-in. drain pipe) as the major portion of the inflow was stored, resulting in maximum reservoir level of El. 59.2, only 0.3 ft. below the crown elevation of the access road along the entire dam.

C. Visual Observations. The inspection revealed that no significant modifications have been made to the inlet or outlet works since the construction of the dam. It was noted that a few of the stones from the downstream headwell of the twin 36-in. RC culvert beneath North Street had become loosened and fallen into the pipe outlet, thereby partially obstructing low flows. The stones would probably be carried through the culvert by high brook flows. It was also noted that the upstream end of this culvert was partially blocked by a combination of stones and bags of cement, the remains of a small diversion structure apparently used during recent sewer construction to divert Labor-In-Vain Brook flows down the overflow ditch.

Ĵ.

Ł

The overflow ditch was noted to have a typical section in the upstream reaches with a base width of 5 to 6 ft., a top width of 12 to 14 ft. and side slopes of one vertical to one and one-half horizontal. It was also noted to be severely overgrown with weeds, brush and small bushes. The slope of the overflow ditch is about 0.012 from Labor-In-Vain Brook to a point about 900 ft. to the east, where it increases sharply by dropping 30 ft. in the next 350 ft. before becoming obscured in a swampy area.

Downstream of the dam, Labor-In-Vain Brook reforms with the interception of flow from the toe drains of the dam, as well as runoff diverted away from the reservoir during dam construction from the area immediately adjacent to, and north of. Whetstone Hill Road. Flows are conveyed past the water filtration plant site in a well maintained grass-lined ditch, after which they are conducted through culverts beneath Whetstone Hill Road (4-ft. wide by 3-ft. high stone) and County Street (36-in. R.C. pipe). About 1,000 ft. downstream of County Street, Labor-In-Vain Brook enters a vast tidal marsh over 40 acres in extent before emptying into Taunton River tidewater at Riverside Avenue.

D. Overtopping Potential. A rating curve for the overflow ditch and twin 36-in. culverts beneath North Street was developed, and the capacity of the 20-in. ductile iron reservoir drain was determined to vary from 53 cfs to 56 cfs for reservoir levels between E1. 56 and at the top of the dam, E1. 59.5. A study of 'ie inflow from the watershed directly tributary to the reservoir downstream of North Street showed that using a test flood equivalent to the PMF and routing same, results in a maximum reservoir level of E1. 59.2, 0.3 ft. below crown of peripheral road, with the major portion of the storm flow through the reservoir drain at a maxiimum rate of 56 cfs. The reservoir level is also influenced by the admission of the excess storm flows from the upper portion of the watershed which cannot be adequately conveyed by the over-

flow ditch. These flows enter the reservoir via the twin 36-in. culvert beneath North Street, thus causing the reservoir level to rise above El. 59.2, but only by an insignificant amount.

The events that would follow an overtopping of the dam would be greatly influenced by the location of the breach. The southeasterly sector of the dam is probably the most vulnerable because it has the greatest fetch from a northwest wind. Although houses along the westerly side of Country Street north of St. Patricks Cemetery would likely avoid damage, houses south of the cemetery and west of County Street, particularly those new houses built during the past 10 to 12 years in the hollow adjacent to the dam, would be very susceptible to flooding from a dike failure. It is estimated that a total of ten homes plus the water filtration plant and a shopping center on County Street adjacent to Whetstone Hill Road would be affected by a failure of the dam.

E. <u>Evaluation</u>. Passage of flood flows via the "emergency spillway" to the swampy area north of North Street and eventually into Broad Cove should cause little or no damage, as the area remains remote from development.

Passage of the estimated flows from a dam failure will, in addition to the flooding described in the above Section D, probably cause minor and basement flooding to those homes around the periphery of the marsh near Riverside Avenue.

Because of the foregoing flood damage potential, a failure of this dam could result in extensive downstream damage as well as the potential for loss of life in some of the affected homes and buildings. However, as shown by the calculations in Appendix D, the dam can handle the test flood which is based on the PMF.

15

SECTION 6 - STRUCTURAL STABILITY

6.1 EVALUATION OF STRUCTURAL STABILITY

A. <u>Visual Observations</u>. There was no visual evidence of embankment structural instability during the site examination on 19 July 1978. No erosion or piping were observed where seepage occurs on the downstream slope. Therefore, seepage is not considered to pose an immediate hazard to slope stability.

There is no other structure at Somerset Reservoir whose failure would endanger the dam, since there is no concrete or masonry spillway.

B. <u>Design and Construction Data</u>. Drawings by Whitman & Howard, Inc. are available which show the design cross-sections for the earth embankment, Appendix B-2. However, no design criteria for embankment stability or calculations are available. Furthermore, there are no construction records available which define soil properties.

The embankment is believed to have been constructed primarily of glacial till. With slopes of 2 horizontal and 1 vertical, and with provision for a central core wall and drains, the downstream slope can be expected to be adequately stable in the absence of significant seepage under static loading conditions.

C. Operating Records. There are no records of embankment settlement, lateral movement, pore water pressures or other information from field instrumentation.

D. Post-Construction Changes. There have been no known structural changes to the earth embankment since its construction in 1965.

E. <u>Seismic Stability</u>. Somerset Reservoir Dam is located in Seismic Zone 2, and in accordance with recommended Phase I guidelines does not warrent seismic analyses.

SECTION 7 - ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES

7.1 DAM ASSESSMENT

A. <u>Condition</u>. The visual examination of Somerset Reservoir Dam revealed that the project was generally in good to excellent condition. There were no signs of failure or conditions which would warrant urgent remedial treatment. However, some maintenance is required and an investigation of wet areas on the downstream slope should be undertaken.

Based on the results of computations included in Appendix D, and described in Section 5.1B, the reservoir has the storage capacity to contain runoff from the test flood, based on the probable maximum flood, without overtopping the dam.

B. <u>Adequacy of Information</u>. The data available concerning the design and construction of the dam are adequate for a Phase I Investigation when supplemented by field observations.

C. Urgency. The recommendations for additional investigations and remedial measures outlined in Sections 7.2 and 7.3 respectively, should be undertaken by the Town of Somerset within 24 months after receipt of this Phase I Inspection Report.

D. <u>Need for Additional Investigation</u>. Additional investigations are required, as outlined in Section 7.2.

7.2 <u>RECOMMENDATIONS</u>

It is recommended that the Town of Somerset engage a registered professional engineer experienced in dam design to undertake an investigation to determine the extent and cause of seepage noted on the downstream slope of the embankment in the vicinity of Sta. 9+00 and 14+50, especially the former. The effect of seepage on slope stability should also be assessed.

It is further recommended that the Town of Somerset engage a registered professional engineer to investigate and propose corrective action for the access bridge abutment foundation. The abutment has moved downslope and introduced additional stresses into the access bridge.

7.3 REMEDIAL MEASURES

. . .

l

t,

A. Alternatives. Not applicable.

B. Operating and Maintenance Procedures. The following remedial work should be undertaken by the Town of Somerset to correct deficiencies noted during the visual examination.

- 1. Clear the downstream embankment slope by mowing tall grass, weeds, brush and small saplings. Unless the embankment is mowed periodically, trees will become established which are undesirable as they reach maturity.
- 2. Repair riprap in localized areas where failure has occurred by erosion from wave action.
- 3. Clear the emergency spillway and channel immediately downstream of all brush and trees, and mow the area to allow free flow of water should discharge occur. Clear boulders and other debris from concrete culvert pipes below North St.

In order to provide for long-term operation and maintenance of the dam and for action in the event of an emergency, the Town of Somerset should also:

- 1. Prepare a formal program to periodically inspect the project and to provide for routine maintenance.
- 2. Develop a formal emergency preparedness plan and warning system, in cooperation with local civil defense and police officials. This plan should include the provision that the 20-in. discharge conduit described in Section 1.3J be manned and operated when the reservoir reaches El. 57 MSL.

APPENDIX A INSPECTION TEAM ORGANIZATION AND CHECK LIST

	Page No.
VISUAL INSPECTION PARTY ORGANIZATION	1
VISUAL INSPECTION CHECK LIST	
Dam Embankment	2
Outlet Works - Intake Channel and Intake Structure	3
Outlet Works - Emergency Spillway, Approach and Discharge Channels	4

.

ź

Ť

VISUAL INSPECTION PARTY ORGANIZATION

NATIONAL DAM INSPECTION PROGRAM

Dam: Somerset Reservoir

Date: 19 July 1978

Time: 0900-1445

Weather: Clear and Hot

Water Surface Elevation Upstream:

52.6 MSL (41 in. below full pond)

A-1

Stream Flow: Not applicable

Inspection Party:	
Harl P. Aldrich, Jr.	- Soils/Geology
Haley & Aldrich, Inc.	
Roger H. Wood	- Structural
Camp, Dresser & McKee,	Inc.
Charles E. Fuller	- Hydraulic/Hydrologic
Camp, Dresser & McKee,	Inc.
Charles L. Loveridge	- Mechanical/Electrical
Camp, Dresser & McKee,	Inc.

Present During Inspection: Joseph Gosselin, Superintendent, Somerset WaterDepartment

VISUAL INSPECTION CHECK LIST NATIONAL DAM INSPECTION PROGRAM

DAM : _____Somerset Reservoir

.

_____ DATE : 19 July 78

AREA EVALUATED	CONDITION
DAM EMBANKMENT	
Crest Elevation Current Pool Elevation Maximum Impoundment	59.5 (M.S.L. Datum) 52.6 El. 57.0 (25 March 1972)
to Date Surface Cracks	None observed (but very difficult to see
Pavement Condition	bare ground) No pavement, mowed width of top of em- bankment about 17 ft.
Movement or Settlement of Crest	No observed
Lateral Movement	None observed
Vertical Alignment	Good
Horizontal Alignment	Good Satisfactory (no concrete structures errort
at Concrete Structures	footing for bridge to intake structure, see below)
Indications of Movement of	Pier and footing for bridge has moved (See
Structural Items on Slopes	Photos). No other structural items on visible slopes.
Trespassing on Slopes	Frequent, no restrictions
Animal Burrows in Embank- ment	Numerous on downstream slope
Vegetation on Embankment	Knee-high to waist-high grass, weeds, brush and occasional saplings. Grass mowed on dam crest only.
Sloughing or Erosion of Slopes or Abutments	None of any significance observed, but sur- face difficult to examine.
Rock Slope Protection - Riprap Failures	Generally good, a few local failures near top where crushed stone bedding has been exposed. Riprap is dumped stone, typi- cally 2-man size stones and smaller, minor weathering
Unusual Movement or Crack-	None observed. Again, difficult to examine
ing at or near Toes	because of vegetation
Unusual Embankment or	Seepage occurs from embankment at about
Downstream Seepage	Sta. 9+00, starting about 8 ft. vertically
	above berm; cattails in area; area wet
	observed. At about Sta 14+50 also wet
	with cattails at berm. No other seepage
HALEY & ALDRICH, INC.	observed.

AMBRIDGE, MASSACHUSETTS

FALE NO. 4160

A-2

AREA EVALUATEDCONDITIONPiping or Boils Foundation Drainage FeaturesNone observed. 6 to 10-inch drain downstream of core and 6-inch toe drains, flowing. (Se port and photos)Toe Drains Instrumentation Systems6-inch porous wall concrete pipe to our headwalls at Sta. 10+00 and Sta. 42- None, no field measurements.UTLET WORKS - INTAKE HANNEL AND INTAKE TRUCTUREUTLET WORKS - INTAKE HANNEL AND INTAKE	wall e re- tlet +00.
Piping or BoilsNone observed.Foundation Drainage6 to 10-inch drain downstream of coreFeaturesand 6-inch toe drains, flowing. (SeToe Drains6-inch porous wall concrete pipe to our headwalls at Sta. 10+00 and Sta. 42-Instrumentation SystemsNone, no field measurements.UTLET WORKS - INTAKE HANNEL AND INTAKE TRUCTURENone, no field measurements.	wall e re- tlet +00.
Toe Drains6-inch porous wall concrete pipe to outheadwalls at Sta. 10+00 and Sta. 42-Instrumentation SystemsNone, no field measurements.UTLET WORKS - INTAKE HANNEL AND INTAKE TRUCTUREFruit photody	tlet ⊦00.
Instrumentation Systems None, no field measurements. UTLET WORKS - INTAKE HANNEL AND INTAKE TRUCTURE	
Approach Channel Not applicable	
. Intake Structure	
TowerConcrete in excellent conditionAccess BridgeOne dent in grating, entire bridge has due to locked shore bearings; abutm	bow lent
Bridge Abutment Original abutment appears to have sett and moved towards water; encased mortar at later date locking abutme bridge; sides and front have broken loose, settled and moved towards w (See photos)	led with nt to ater;
Mechanical and Electrical (No electrical)	
Service Gates Good condition; hand-operated gates op able	er-
. <u>Outlet Channel</u>	
Channel Bottom Rust in channel, probably due to discha from internal drains in embankmen heavily grassed on sides	arge t;

i

.

1

DAM: DATE: DATE: DATE:		
AREA EVALUATED	CONDITION	
OUTLET WORKS - EMERGEN- CY SPILLWAY, APPROACH AND DISCHARGE CHANNELS		
a. Approach Channel		
General Condition	Satisfactory - channel is bed of brook which crosses relocated North St. at	
Loose Rock Overhanging	None observed	
Trees Overhanging Channel	None, brush only	
Floor of Approach Channel	Heavy grass, some brush and debris	
b. <u>Weir and Training Walls</u>	Not applicable. (Emergency spillway is a short trapezoidal depression in an earth fill placed east of the Labor-In-Vain Brook channel, immediately north of North St. Spillway opening is substan- tially blocked by tall grass, brush and small trees.)	
c. Discharge Channel		
General Condition	Fair, but channel is ill-defined and diffi- cult to find and examine	
Loose Rock Overhanging Channel	None observed	
Trees Overhanging Channel Floor of Channel	Heavy brush, small trees, tall grass Tall grass, brush overground	

i

t

ľ

APPENDIX B LIST OF AVAILABLE DOCUMENTS AND PRIOR INSPECTION REPORTS

LIST OF AVAILABLE DOCUMENTS

"Details of Dam", Sheet 6 of "Proposed Surface Water Reservoir, Somerset, Massachusetts", Whitman & Howard, Inc., Engineers, Boston, MA, September 1964

PRIOR INSPECTION REPORTS

Date	By	
22 March 1968	Hayden, Harding & Buchanan, Inc., Boston, MA	3
27 July 1970	Universal Engineering Corp., Boston, MA	4

Page No.

1
	LOCATION	Whitman & Howard, Inc. 45 William Street, Wellesley, MA 02181	Whitman & Howard, Inc. 45 William Street, Wellesley, MA 02181
LIST OF AVAILABLE DOCUMENTS SOMERSET RESERVOIR DAM	CONTENTS	Seven contract drawings entitled Locus, Plan of Dam (3 pages), Profile of Dam and Details of Dam (2 pages)	Contractual agreement; gen- eral soil gradation, place- ment and compaction require- ments
	DOCUMENT	"Proposed Surface Water Res- ervoir, Somerset, Massachu- setts", Whitman & Howard, Inc., Engineers, Boston, MA, September 1964	"Specifications for Constructing Storage Reservoir and Dam", Whitman & Howard, Inc., Engi- neers, Boston, MA, January 1965

Ī

.

.

| [

:

1

.

ļ

ſ

B-1



Samer ic + 6-3-273-1 BRISTOL COUNTY, MASS. 50-2 Dam No. Concruet Towa: __ INSPECTION REPORT & DATA FOR DAMS Stress: Intor PREPARED FOR THE ARISTOL COUNTY COMMISSIONERS BY EAYDEN, EASDENG & BUCHANAM, ENC., BOSTON, MASS. Pord: Vate: Dwner: 'C m'O' 3~: Water Department COLDITION PATING His Address: Function of Dem: 32373 ·Ξi 2. Structurel: _ Location & Access: horth Hydroulic: County Jeseral: St. + 5' -0' Long. 5 USSS Qued. Soceraet Let.1 PRIORITY Drainage Area: 1. 5 sq.ml.; Ponds: Character of D.A.: KINNISON-COLEY FLOODS ac. ; ?25.6dam: ac. Minor: cfs Satimated Major: cfs Discharge Rare: cfs Capecity: Marimum: cfs General Description of Dam and 2502 const Exetch (Not to Scale): 56-0 - <u>10 10</u> 44'- 0" - 2'-6" . ZALLING 1 fuit 255504012 SESDED TOTACIL 210-340 COMPACTED SLACING USAUSU INTAKE SECT. PAUSO GUTTE FILL & FERMOUS FILLS DCAIN 320 2025 STEEL WATSENTON 1 1 1 20" 1201 2175-*....* - SECTION THOUGH DAIR AT OATS STRUCTURE · · · Remarks and Recommendations: Date Зу Connest tio problem 3125 Water Sub Dam No. 20-. .

E

B-3

BRI	STOL COUNTY, MASS.	DAM NO. So 1	
INSPEC	TION REPORT FOR DAMS	TOWN: Somerset	
BY UNIVERSA	L ENGINEERING CORP. BOSTON, MASS.	······································	
NSPECTION	REMARKS & RECOMMENDATI	ONS	
			•
7-27-70	The gate structure is in excellent condi- the pond is approximately 5 feet below abutment for the carwalk has been seri- ently due to thermal expansion. The ai should be repaired, and anchor bolts re- caution.	ition. The level of the catwalk. The busly damaged appar- butment backwall eset as a safety pre-	• <i>*</i>
			-
·	•		
	•		
	· · ·		
			ł
			-
	й		
.			
-	-		

Ī

.

ŗ

.

•

B**-**4

APPENDIX C SELECTED PHOTOGRAPHS OF PROJECT

LOCATION PLAN

Page No.

1

1

Site Plan Sketch

PHOTOGRAPHS

<u>No.</u>	Title	<u>Roll</u>	Frame	Page No.
1.	Crest of Dam and Upstream Slope Vicinity of Star 15+00	17	4A	2
2.	Typical Riprap on Upstream Slope	16	20A	2
3.	Repaired Section of Riprap, Vicinity of Sta. 50+00	17	15A	3
4.	Example of Eroded Section of Riprap	17	12A	3
5.	Downstream Slope Near Sta. 9+00, Where Seepage Occurs	17	11A	4
6.	Seepage Area on Downstream Slope Near Sta. 9+00	17	10A	4
7.	General View of Downstream Slope of Embankment, Photographed From Near Sta. 4+00	17	9A	5
8.	Outlet of Embankment Drain Pipes, Sta. 10+00	17	7A	5
9.	Outlet Channel From Embankment Drains at Sta. 42+00 and Wet Area Downstream	16	23A	6
10.	Outlet of Embankment Drain Pipes, Sta. 42+00	16	21 A	6
11.	Intake Tower and Access Bridge	17	3A	7
12.	Abutment for Access Bridge	17	0A	7
13.	Outlet of 30-inchWater Intake from Segreganset River	16	13A	8
14.	Approach Channel, Photographed From North St.	16	19A	8
15.	South End of Twin 36-inch Concrete Culverts Under North St.	16	16A	9
16.	Emergency Spillway Immediately North of North St., Labor-In-Vain Brook Bed on Left	16	18A	9





1.5

[1

Ľ

i

Ľ.

D

1. Crest of dam and upstream slope, vicinity of Sta. 15+00



C-2

2. Typical riprap on upstream slope



ŗ

0

.

Ľ

.

E

3. Repaired section of riprap, vicinity of Sta. 50+00



C~3

4. Example of eroded section of riprap



5. Downstream slope near Sta. 9+00, where seepage occurs



6. Seepage area on downstream slope near Sta. $9{+}00$

C-4



D

.

Ţ

.

ľ

.

ł

Ļ,

7. General view of downstream slope of embankment, photographed from near Sta. 4+00



8. Outlet of embankment drain pipes, Sta. 10+00

C-5

.

۰.

E .

.

ļ

9. Outlet Channel From Embankment Drains at Sta. 42+00 and Wet Area Downstream

C-6



10. Outlet of Embankment Drain Pipes, Sta. 42+00



11. Intake tower and access bridge

i

T

•

-

.

!



C-7

12. Abutment for access bridge



D

ł

13. Outlet of 30-inch water intake from Segreganset River



14. Approach channel, photographed from North St.

C-8



Ľ

.

•.,•

....

ŗ

ť

15. South end of twin 36-inch concrete culverts under North St.



16. Emergency spillway immediately north of North St., Labor-In-Vain Brook bed on left

APPENDIX D OUTLINE OF DRAINAGE AREA AND HYDRAULIC COMPUTATIONS

OUTLINE OF DRAINAGE AREA	Fage IN
Drainage Area Map	1
COMPUTATIONS	
100-Year Flow and PMF Flow Calculations	2
Size and Hazard Classification	11
Stage-Discharge Calculations for Somerset	18
Reservoir	
PMF Flow Calculations for Southern Drainage	24
Area	
Routing Procedures	29
Capacity Calculations of Overflow Ditch	38
Capacity Calculations of Twin 36-in. R.C.P.	41
Distribution of Northern Drainage Area Flow	44
Between the 36-in. R.C.P. and the Overflow Ditch	
Final Reservoir Outflow and Corresponding Water Surface Elevation	51

ţ

E

Page No.



CAMP OPESSER & MOKEE SAGE-Taraca - 2-20-10 ATE CHECKED B-16-18 CATE 7/31.78 ereeniphä laineera PROJECT CETAIL Ansing Vises SHECKED BY COMPUTED BY Omicane Area . 722 Faces 11,24 square Area of Baservoir : 165 Acres (26 STD.) 2 Eler 56 Burrow composes ~ 18 % of Tatal Orainage Ana Langth of Katersteid 3460' sychong Flow 4.420' Flow 12 Lacor 10 1010 BROK Junch O. A. is less than 2000 feres use Curre Number Method D determine Te-70.8 (3+1 100 " 1900 yas ______ 2 85% 6700 137' 82' à 1590 1130 Y= 1, C326 To slope b. 2 - 7220' 3 . 1000-10 211 End CLL - Hydrologic Group C. ميبه بريد 622 Ener Somerset_ Esservar_ 100 11500 165 Kietland (Swamp) 88 98 98 Streets maria 3.5 907 Houses Isay "Is acre) 42 **33** 77 3032 120 <u>1:23 m</u> Pasturened. 7:0-22 Weighted Chi = 33.5 sain 5-100-10 - 1.705

SLIENT Haley and Aldrich .08 NC-5/2/-9-CAMP CRESSER & MOKEE PAGE / PROJECT DOMINGET CLARTED / SATE DHECKED. nvironmental Engineers CATE Ø DETAIL HUSING Boston, Mass CHECKED BY _ COMPUTED BY 30 ----Elevation vs. Surface Arres . _ _ _ DF LISERIDIE - 200 183 Fer 100 70 50 60 Elavation (A) Eler. Jurfall AMa 165 Acres (0.20 5. m.) 56 .__ 185 Acres (0.29 3. m.) 60 10 212 Acres (0.33 s.m.) Orainage Aun = 1, 42 39, min = 732 Flores_ ____ D-3

1

SLENT HOJEL CHERICA L. D. Z. DB NO 57-1-2-27 CAMP ORESSER & MOKEE PAGE DETAIL TUDOLOGIU DATE DECKED BILL Environmental Engineers TATE Boston, Mass. COMPLITED BY 7380 28 (2.905).7 12/2001 - 1,07 10 hours 1900 x (10326).3 = 2.39 ha (143 mm) 7/= / 1. 100-year 6- hour Rainfall = 2.9 notes in 6 hours AD- TO = 0, 4 L 10-0,6x1,13 - 0.572 Hours - (34 mm.) 700- 1×39 min - 238 min (3.774 RY/BC Time Mass P Mars D (nches) (rous) (mores) .87 10.0 0,131 _0.11 200 0.15 1,00 10.5-0,22 235 11.0 1.15. 1.39 11.5 223 0.35 387 . Ida3 11.75 0,67 1.72 9.25 12.0 2.02 2.18 12,5 735 3.60 13.0 772 3.<u>7</u>8. Working Circle For Type II Stor Distribution 20 - 9.31.00 1,38-4,5(.572) 110 210 7 II 12 Time (hrs) 10 13 14

÷.,

1

SLIENT Harris C. J. OB NO 34-2-2 CAMP DRESSER & MOKEE 90.ECT 20 DATE CHECKED Environmental Engineers CHECKED BY BEUL DETAIL Boston Mass. COMPUTED BY Instantarious Peak Obcionges. 4Q 49 Mass Runoff YLO Inveriant Tome (nours) (incres) 1213 9.31 0.06 10, 0.03 12,2 0,2 2,4 1,88 0.07 9.7 AD-0.010 24.2 0,0 0,45 0.15 103 0.07 28,2 0,5 17.1 2.22 11.02 81.2 0.3 65 20a 0.20 11.59 0.42 5605_600 560.5 405-138_ 1.30 12,16 1 Qa 0.25 101.5 0.67 68.0 12.73 2.05 40, 77.2 0.33 25,5 019 13.30 2.24 2748.2.5 Jay 108 cfs 190- 27C A (AQ) A= 1.64 39.mi AD+1 = .572 + 1.43 = 1.710 190 - 436 X144 AD = 406.2 AD 1-7/10

CAMP DRESSER & MCKEE -PROJECT SCATE CHECKED B-16-18 بوس Environmental Engineers 41 DATE. DHECKED BY BUNK DETAIL And Ing. Boston, Mass COMPUTED BY. 1101 Hydrograch - 100yr, 6 hr. aranato Ð ___ . Time 111 231 0 700 933 45 10,45 6 20 11,02 53 11.57 120 2.16 00 12:12 120 748 3:30 **B:87** 530 320 Ō 10,44 200 15.01 500 90 15-58 Ò 15 10,15 16.73 0---400 0 \mathcal{P} -0 100 . -200 100 Ō ۲ Ð 9.0 10.0 1iQ • jeo. BO. 14.0_ 1.5.0 _ TIME in Hours _____ 4 hour peak = 748 673_ _ - -···· · 100-100-...... . _ -----.

5

•

CLIENT ----CAMP ORESSER & MOKEE In cer Pinerio DATE CHECKED Environmental Engineers PROJECT 8-16-18 DATE Hickman 15 Boston, Mass. DETAIL CHECKED BY COMPUTED BY -25Inchas Precipitation Potate Maximum - 7-15 Lo have PX/BO Mats P Time Hars Q (hours) (inchis) (reres) 2.34 0,181 4.53 10.0 0,200 5.10 3,30 105 11.0 0,235 5,33 4.08 0,283 7.08 9.63 5,22 1.72 115 0.337 11.75 16.50 0,663 12.0 16,53 1838 0.135 16,28 125 13.0 17.19 0.772 19,30 21 101 11,88-9.5 (,572) - 9,31 hrs ĩ 9.0 ._ 120 14.0. 10.0 140. _ Time in hours D-7

SLIENT Haley CAldrich, LI, D. I. JOB NO 541-8-CAMP DRESSER & MOKEE PAGE -90JECT DATE CHECKED onmental Engineers CATE. Hydrology CHECKED BY. Boston Mass DETAIL COMPUTED BY_ Y Lg Hay Runoff 14 40 Inseriori Time (hars) Inches 1 FS 9.31 25 81 0.2 AD 0.2 10 1,38 217 2,2 AQ2 200 97 0.4 3,3 10,45 325 1G 0.8 125 0,6 5,1 11.02 0.3 A Da 12 772 417 11/27 10.0 DD5 2:0 5656 40 1656 15.0 12.16 433 650 100 102 1.0 12,73 16.0 102 647 333 142 1.1 13.30 17.7 2 5103 Aq= 424 A 10 - 406.200 10+0 .. . • • • · · · · -

<u>، ۱</u>

1

CAMP ORESSER & MOKEE PAGE PROJECT DET PICTURE DATE CHECKED 8-16-18 Environmental Engineers 2 CATE DETAIL Mydralogy Au Boston, Mass. CHECKED BY_ COMPUTED BY _ Oranstes_ Hydragroph TIME CFS .. DHF: 25 oches in la hours 9.31___ __0 9:88 10 50 10A5_ 11.02 160 11.59 480 1.900 12.14 12:73 2536 110 51.60 1330 3500 13-27 1404 2410 1400 15:01 220 15.58 5000 120 16.15 16n73. \sim 4000 いいろう Ö 0 300 0 200 6 1000 90 140 10.0 ĽLO 120 13.0 15.0 Time in hours -. Peak Flow = 5160 cFs ----· _ D-9

i

CLIENT Halpild Alarch L. D. I. OB NO. 561-2- C; CAMP DRESSER & MCKEE PAGE PROJECT SOMEISET Practing Date Checked DATE Z Environmental Engineers CHECKED BY Boston, Mass. DETAIL HIDOLOGY COMPUTED BY Comparison of JLS-TP-149 Flow Values with The LOE Hoximum Asbable Flood, Anak Flow Pates Graan According to LOE Maximum Appable Flood, Real Flow lates Graph: Using Flat & leastal Gurve, Q = 230 cfs/ = 1340 For 1.40 sq. mi Try 3/4 way from Fat & Coastal to Polling 2 = 1830 ctors 1 1.40 = 2/235 < 5/100 cto However this arve should not be used For such small no tersplds (210 g.m. The value of 1340 cFs is much different from YOILL OF 5160 LFS sotared From The 565 TP-149 I Feel That The 5160 cf3 value is valid. -89.4 2.00 F. 9105089 Q1 = A., 244 1 Az.000 930 = .9517591 , Q2 = 977 2F3/39, mile 0z Q2 = 1407 cF3 (close to 1340 0.14. 1

ŝ

CLIENT the less & Aldrich U.O. JOB NO 5'31-2- PT CAMP ORESSER & MCKEE PAGE PROJECT IT Corver DATE CHECKED nental Engineers DETAIL MICHALONI Anth SHECKED BY_ COMPUTED BY Classi Fication of Dame Size : Height = 59.5'-18' - 41.5' storage (a) top of dams Q Eler. 56.0: 1×165 Pers x 38 A = 2090 R.E.A DELEV. 57.5 : 183+165 x 35+2070 = 2699 Acre - A. : 41.5' > 40' 2672 Acre-AS 1000 Acre-A so Jize Category is Intermediate Hacard Potential Estimating Daustream Dam Failure Hydrographs 1. 3= 2099 ACK-A a time of Failure 2 ap: B Wo 19 10 30 Wh= 0.20×6505 A = 1301 A (20% because of Yo= 57.5-18= 41.5 _____ Act us community set up compared ap. = B x 1301 x 132.2 x 41,53/ = 584,795 = 53 Peach LD. 1 - Whetstone Hull Boad 1010 100-Elevation T.O. C 7.11 Store Cuivert - 5.0-0-00 _ 0+50_

CLENT Haley & Aldring U.O. I. JOB NO EL CAMP ORESSER & MCKEE PAGE PROJECT CARVALE DATE CHECKED_ Sovironmental Engineers CHECKED BY DEFILE COMPUTED BY ----DETAIL My am/271 Boston, Mass. Being lideral, assuming no ponding on downstroom ncle : QFUH = 149 Eels JIE A محر A= 12 A2 1 . 0020 (Assume 2 . Jg) R . 12 . 857 QF411-276F3 With water at too of road: Q= 0.77×12 [60,4×0,6 (Elev.~11,0) 0757cB Lonsidering that over 500,000 cF3 will come 11 Celly be washed away Try County Street - Route 138 _____25 ___. T.O.C. \$ 11.5 97**A** 912 96" 2.C. Pipe 6.8 1-,0097 GIR -0+00 1.00 $QF_{4H} = \frac{149}{1000} \times \left(\frac{103^2}{4}\right)^{\frac{14}{2}} \times \frac{10097^{16}}{4} \times \frac{103^2}{4}$ QFull = 57 6F3 With WIFL-11,5', D=0.7919-100,01,212.33. tood Qº 69cfs not adequok

.

i.

CLIENT Haley & Aldrich U. D. J. OB NO 561-2- PT CAMP DRESSER & MCKEE PROJECT Erecter Parerion DATE CHECKED_ ATE CHECKED 8-17nvironmental Engineers DATE DETAIL HUJMAN Boston Masa. COMPUTED BY Try Elverside Avenue 6000 31000 say 570____ 26' CM Pipe Q=1,47 825 31/2 A ,025 D= 1.29 (Tr (2)2 "3 (. 0500) "2 x16TT - 1063 CE 025 THE oot a dequate Try saith street TWIT 60" C.M. Pipes Q= [147 [5 43 (,0500) 12 x Tr(5)2 2.... L.G25 41 Q= 407 cF3 - not adequate Lione of culverts could handle the maximum breach flow. They don't ever come rear handling The flow under the best conditions (na ponding) So, assume no controls on stream, take representative cross section, and Finish guidorie or estimating downstream dom failure bydragraphs method Conservative cross section (located 1220' d.3 from dom) 45. 12 Approxima ke Invert = 7.1_ n= .090 1000 - 20-10 - 010520 750 _ 0 ____ 500 ___ 200 -----<u>*</u> . (leaking d.s.)

CLIENT HOLCIL & Aldrich M. D. I JOB NO 561-A-E CAMP ORESSER & MOKEE PAGE. PROJECT DORCHET REACTION DATE CHECKED B. CATE 3/1 Environmental Engineers CHECKED BY DETAIL HICOLOGY COMPUTED BY -----Lurve Computations for Typical Hage - Discharge Loss - Section Q-1.086 223 512 A NP 4 Elev. Head. P. 0105263 0 0 7.1 0 0.7 8.0 90 421 101.8 0.234 1.9 9.0 190 103.8 1.830 1445 2.9 10.0 270 105,8 2.741 2888 3712 440 205.8 2.138 3.7 11.0 4058 £17 12,0 705 320,3 2.177 23278 7.9 15.0 2040 605.9 3.367 93229 127 20,0 60,40 1056 5.720 17.2 25.0 11415 1376 8.441 246886 30,0 13840 1096 22.7 11.108 477,055 32.7 40,0 36870 2077 17,572 1,269,305 From Graphs on Pages 19414 à Q= 584795 cfs - Elevation = 31.5 Ft (24,4 ft. of head) Area = 20,020 A2 = 0. 4596 ALRES Bach & 1400' long (to county Street) AVI = 1900 x 4576 + 643, 4 Acre A 6 12 5 (1350 Acre F) - 8. Op_ (TRIAL) = 584175 /1- 6439 - 445389 cF3 6. Az= 16350 AZ= 3753 ACK V1= 1400'x 3753 Acr = 525 Acre-ft. V1+ 1/2 = 1643+525 = 584 Acre-A 0. V,+1/2 = 1043+525 ap = 584 795 (1- 584) = 458260

MP DRESSER & MCKEE	WENT HOLEY OPAL ALGRED LODEN 5121-2-PT	
nvironmentai Engineers	PROJECT ETT COSCE DIC DATE CHECKED B-17-78 DATE R/1/78	
Soston Mass.	DETAIL Hydrology CHECKED BY CHECKED BY COMPUTED BY 2/02	• •
	, 	
	and an	
	nar a sa a sa a na ana ana ana ana ana ana	
	Rhtar Atras Ourtaner Fr	• •
	Thomas for the	
	<i>Jection</i> / <i>juical</i> Jection	
		•
-, 00,000		
		•
	$\int_{\mathcal{A}}$	
1200,000		
·		
\$	/	
~	· · · · · · · · · · · · · · · · · · ·	
8		i i i i i i i i i i i i i i i i i i i
··· •		– –
··	······································	
- 400.000		
·		, ●, ●
	······································	
QA ITA		
-305:00		
	/	• • • • •
		• •
_uisma L		
I		· · · ·
	10201 ¹ / ₂ 0 4050	- V . V
	Cicuation (in Ft.)	
• • • • • • • • • • • • • • • • • • • •	····· · · ·	

)

.

.

Ł

•

•

b.j

P

SLIENT Haley & Aldrick, C. D. Z. JOB NO. 50 1-3-27 PROJECT JANUACT BIACTIONS DATE CHECKED CAMP ORESSER & MCKEE 2′ PAGE DATE 3/1/2 Environmental Engineers JETAIL Hidrol 2014 0Ful dinn Boston, Mass. CHECKED BY. COMPUTED BY. Area to Elevation For Typical Cross-Sector 40,000 35,000 30,0±0 2 cosec 16,350 15000 10,000 5600 0 Z9 40 Elevation (in feet) 20 . .- ---____ -------- -----

۰,

,

1

•

.

(

.

CLIENT Haley and Aldren, 4. O.T. CON Stel-2 JAMP ORESSER & MCKEE vironmental Engineers CATE Boston Mass COMPUTED BY_ _ _ .__ A+ 20 + 458,260 cts Elevation - 29.2 tt at Tipical Cross Section (22. 1" OF heads This around of head will inversate approximately 10 comes, and 2 Filtration Plant within this has intration Plant within this reach. There fore, The Hazard Potential Class Fration Catigory A HIGH Downstreams of this reach, the alea becan's ever Flatter, in contour and stope towerer, Euseron blissie structures are located at a lower elevation Thore in The upper reach to within it doing Thise inkultion it also appears that only a few of innovitable structures would be affected. 50, according to the COE parameters, the Spilling Orsign Flood (JOF) a The PMF The PMF = 5160 LFS (unrouted) - - ----.

CLIENT Haley and Aldrich CAMP ORESSER & MCKEE 15 PAGE_ DATE 2/2/72 PROJECT STTINET RECEINENT DATE CHECKED 8-17-18 onmental Engineers CHECKED BY DETAIL AND MODIA 7/sion, Mass Approximate Invert aF 20" Class 250 M.J. Ductule Iron Pipe = 18,5 (upstream); 14.5' downstream. Skope of Pipe = D.02 Top of Came = 57.5 11 Length of Poe = 200 ft (crown of roadway) Courstear Invert of 20" = 14,5' Hazzn Killians he-fly 029 F= 0231_ L-200 H 0= 20" - 1,667 H 9-3221132 V- 9,04:13 n_-.0231 (200' x (9,04 1/3)) = 3.52 Ft/ 1.667 × 6.4.4 1/32/ 30_h2=17.6 A/1000 A For Hazo Williams Formula 16-1251 ADE 3 14 XEARS DO Q-0,279 C 0263 30.54 but never used. Q=0,279_X 125 X (2) X (1) cement lines) D= 15.12FS When water surface is at elevation 59.5, H= 59.5 = 14.2 = 1334 (assume no pendina; because of amou and That acts through this 20° O.I. pipe, the serves - could handle it pipe

JOB NO. <u>56/-3-27</u> DATE CHECKED 9/26/78 CHECKED BY SLIENT Hales sus filatorit CAMP DRESSER & MCKEE PAGE. PROJECT ronmental Engineers COMPUTED BY DETAIL Boston, Mass. Carrier of DO CL DI Arte ŧ ŧ ÷., - Sake maxine Counter rulat loss of 054 50 C onte structore and anter lise and at were - say 1.2 - fores (12 - 12 and in the herene 1) = 56 ste -= 25.57.78 there 1 = 20 - 10-33 5-15-554 <u>15' = 0/322</u> Sec=125 1)-A = 11 = 55 10 Here Vine -10-20-520521 20-20-520521 120.030 --Q.A. 1.136 2353 D= 13.0 1925 (1:2) 3.0.0571 == 69.0 ce 2 64. 64. 50 12. D-19

Aldrich ----ر، من و اسر CAMP ORESSER & MCKEE CLIENT_ -08 NO - my and there and intal Engineers PROJECT. DATE CHECKED. OATE DETAIL CHECKED BY COMPUTED BY Pressure Flow Q- GA VZqH L=0,49 For concrete pipe (D.T. is line a' Q= 0,49x Tr (29) [104,4x43,3 D= 57 cf3; Pre is actually to long to be considered on orifice or short tube (see page 17) orifice or short tube ises page !!! 30, at WSEL - 57,5, Dpipe = 57 c FS okay When water begins to overtop dam, The Qualue mereses quickly .___ Trest top of dom as broad -crested weir, broad the = 10' 10' 10' 59-58. L. Vailus: H 2 0.2 2.47 2,56 - 2,70 Q. 4_ 0.6____2.70 0.8 2.672,00 - 6505 2.30-2.20 2.10 2.01-25 14 (11:50

ì

t

19 CLIENT Lin en Aldrich .08 NO 5/2 1-0-0 PAGE CAMP ORESSER & MCKEE DATE. ntal Engin CHECKED BY DETAIL Hydrology UTED BY. Stage Discharge la ationship for somerset Dam Had Eley. asolling. aziec. OTOTAL 56 T 510 57 Q.L 57.6 Di2 57,7 1447 57 506 57. 2760 0.3 57.3 21033 4270 0.4 4213 57,7 57 57 6037 5980 0.5 60.0 Drainage Areas Lorbon D.A.I. Dastream of Lorth Street - 560 Acres reservoir) : 362 Acres Horthern Orainage Area Flow Lamputations Note: Jince the JCS_TD 147 computations were based on a lag time, and slope winch was derived from the Labor in Vain Brook Watershed (a cove Jonerset Riservoir), in order to determine The Flow From This area, aristic JLS Hathed, published in Jection 4 Hydrology -based an aminage areas will be used. Az 1 196 = 5160 cf3 = 3582 cf3 / 3. m. = 922 Acres = 560 Acres <u>3582 - 922</u> 0: <u>922</u> 0: 560 (560.000 -1) 3582 , 02 - 4721 = 13/3m .11/0176
CLIENT Hakey and Aldrich CAMP ORESSER & MCKEE -08 NO. -561-8-8 PAGE عي Environmental Engineers PROJECT Procest Provous DATE CHECKED_ 8-1 DATE 2/2 DETAIL HUDOOU NE Soston, Mass. CHECKED BY. Hydragrade of Northern O.A. PMF: 25 mense in la hrs_ 5000 - AOL - 4131 4000 ÷ 2000 9 1000 0 0 -1000-6 Ĝ 90 100 120 130 160 15.0 11.0 -----. ____ Time (hours) ------- ----. ----- - ---------.

ī

ľ

. •

:

.

ι

•••

I

LENT Haven and Alarick JOB NO 501-2-87 CAMP DRESSER & MCKER DATE 313 Ca Environmental Engineers Boston, Masa Has- Oscharge Cilationship For somerset Dam. Eley. Qsoi way QDIDE DTOTOI on Spillway (Tabor Com) 54 54 55 55 57 0 56 0 56 58 56___ 56____ 59 0. 57 59,5 57 0 510 57 0.1 59,6 567 _0,2___ 59,7 1449 57 150.6 57 2740 0.3 ______59:8 _____2683 0.4 59.9 4213 57 4270 0,5 60,0 5980 57 _____6037__ Assume no ponding on downstroom side, free Flow from outlet of 20" (Top of pipe - 16.2')

t

Ĺ

CLIENT Halore Aldrich 108 NO. 510 CAMP ORESSER & MCKEE 22 PAGE T. JOM O PRATE CHECKED entral Engineers 90.16 Hydrology CHECKED BY. DET. Counstream of North Street Omnage Area Flow Lonputations Not including lateruoic " Watershed length = 3500' 2 1100C ... 1570 525 85 8570 2775 150 51000 - ,026571 , 2.6531 Ta 3. CILL - Hydrologic Soil Group L HED. 187 CLIX Area Asture 14399 Impervious 10 BO 83 15229 197 4 cighted CU = 77.3 304 77 <u>5=1000_10=2.787</u> 77 Lag: 3500.0 (3.987)" - 0.582 hours 1900 (2.6531).5 72-6 - 97 hrs Haximum Probable Alcion tation: 25 inches in Lo hours AD- To - 0,46 10 = 4x ,582 = ,233 hours 740. 7x,233 hrs = 1.631 hours. - ----.

CLIENT - Alanch PAGE 23 P ORESSER & MCKEE .08 NO. -12 -m. . 23mm PROJECT DATE CHECKED. tal Engl DETAIL HUDD . 2011 Hose D Mass Time 20 (inches) (acres) (ious) _ 4.53 2.34 10.0 .181 1.36 4,08 220 10,5 5110 11.0 235 5,33 11.5 283 7.03. 5.22 9,63 7.72 1.1.75 38.7 120 463 1658 19.50 735 1333 16,28 12,3 13.0 930 17,19 11,88-4,5(.233) - 10,832 See By 5 Graph of Accumulated Deoth Runoff Increment Time Hats Runoff (incres) YAg (cts) AQ' 19 2 (5) 10.83 3.7 10. . 3 104 2 13 4,2 11,0% 40, 1.47 14 60 7 4,9 1130 14 103 8 7/ 4 5.7 1,53 100 422 8 342 201 11.76 7.7 DOF. 1451 6.B 1451 1.0_ 12.00 14-5 99 147 . 7 667 AQ 12.23 15,2 407-333____57_ IZL 12.46 14.0 22125 dis 19-<u>434 x A</u> <u>40</u>+ L ---- $\Delta 0 = \frac{484 \times .308}{.233} \Delta \frac{1}{.582}$ - Ag = 213.4 AD

F

CLIENT Halaria Aldrich 108 NO. 541-3-27 CAMP ORESSER & MCKEE PAGE. ATE CHECKED BY pringer ligen د د nuu Engin DATE CHECKED_ PROJECT. DETAIL HYDODAY 1 Non. Mess · _ Hydrapph - Southern O.A. Land Granate Ord Time -2000-10.83 0 - ---ā 11.00 30 11.30 20 11.53 245 11.76 870 12.00 12,23 1490 2.125 12,96 1410 12.104 955 12,93 -1500-13.14 475 50 20 13.39 13.62 19.20 0 ī B 1 21000 O. g------500 0 0 .′O 0. 15 14 . 10 .. .___13 .__ .. . Time (hours) ···· ··· · ----.

Ĩ

.

l

CLIENT Haley and Aldrich 108 NO -<u>5101-3-87</u> CAMP ORESSER & MCKEE PAGE. PROJECT Dreiset Processor DATE DATE CHECKED DETAIL MINICOLOGY CHECKED BY_ COMPUTED BY *Flow Computations - Coinfall Orectly on Somerset Elservoir l's inches in la hours AC. 2 3 4 5. Ġ. α 1 TIME (HOURS) Area of Reservoir (a) elev. 56) = 165 Acres Hydrogropto-Storm on Coscosi-2000 139 - 5- 45 - 139 5 10/c -1000 0____ 3_ 4_5_ 6____ Time (hours) · -------. - -.....

.

L



2 1

1

•

RESSER & Makes Intental Engineers Oston, Mass.	CLIENT	HALEY E Foniesie: Lydrolo	ALDRICH RESERVO	JOB NO.	-66-2+ B-13-13 B-14	PAGE - DATE - COMPUTED BY -	2 ~7
	Head on Spillway H,_ FL	Reservoir Arsa A, acres	Colculatedi Outflow Q_cfs	Calculated Starage 5 Jove Spill- way level acre-ft	Funtio S At cfs	$\frac{1}{4t} = \frac{2}{2} - \frac{1}{2} - \frac{1}{2}$	si Storage (5 + 9) At + 2) Crs
-	0	182.7	0	0	<u> </u>	0	
	0.1	183.2	56:7	19.3	553	269	836
	.0.2	183.6	150%	366	1108	355	1961
	0.3	184.1	_ 974 0	_55_	-1664	294_	3034
	0.4	184.6	4270		2222		4356
	0.5	185.0	6032	91.9	278	-238	5799
JU <i>perse</i> o	ea. 04	POQE		· ·· ····			
						· · · · · · · · · · · · · · · · · · ·	
						•	
						- <u>-</u>	
			· · · · · · · · · · · · · · · · · · · ·			·	
					······································		
			······		· _ · · · · · · · · · · · · · · · · · ·	·····	
						·····	
			· · · · · · · · ·	· · · · ·	 		
· · · · · · · · · · · · · · · · · · ·	· · · · · ·		- · · · · · · · · · · · · · · · · · · ·	· · · · ·	· · · · · · · · · · · · · · · · · · ·	-	
· · · · · · · · · · · · · · · · · · ·			· · · · · · · · · · · · · · · · · · ·	· · · · · ·	· · · · · · · · · · · · · · · · · · ·	- 	 .

Ĵ

.

-

Ē

.

•

Ì

.

CLIENT <u>17157 5 ALDRICH</u> 108 NO. <u>56-3-27</u> PROJECT <u>2005055 LESER 201</u>² DATE CHECKED <u>67878</u> -AGE 20 CAMP ORESSER & MCKEE wronmental Engin CROLOGY CHECKED BY DETAIL Y COMPUTED BY. Boston, Mass. ENLARGED ELEVATION VS. SURFACE AREA ------. -----. . and a construction of the - --4 ₹ 0 the second second second سيستستند والمعا - -------- - ---. the state of the second state of the 50 -----ورارية السيادسية لتتمت والمساعد والم 0 ··· · ----··- ··· · -------------- ----52 SURFACE AREA (ALRE) 2 .-- *'*3 3 9 D-30



30eion, Mess. 71N //L (24 Z/M	DETAIL ME JMBER 4 MIN. TERVAL) 0 1 2 3 	HY 72010 OBEERVET FLOW 1 (cA) 0 85 470 1660 2840 2440 2440	AVERAGE INFLOW (c+25) 42 278 1065 2250 2640	2HECKED BY	<u>362</u> 362 362 1216 2580	20MPUTED BY HEAD ON SPILLWAY (FA) .0263 .0465 .143 .25	PLE OUTFLOW (CAS) (CAS) 85 192 950 2075
	ME JMBER 4 MIN. TERVAL) 0 1 2 3 4 5 5	0852RVET FLOW 1 (cfs) 0 85 470 1660 2840 2440	AVERAGE INFLOW (cfs) 42 278 1065 2250 2640	3-9 AT BELINN'G OF TIME INTERVAL 	5 + Q AT END OF TIME INTERVAL 362 1216 2580	HEAD ON SPILLWAY (Ff.) .0263 .0465 .143 25	OUTFLOW (c ⁴ s)
	0 1 3 4 5 5	0 85 470 1660 -2840 2440	42 278 1065 2250 2640	84 151 330 340	362 1216 2580	.0263 .0465 .143 25	85 192 950 2075
	2 3 4 5 5	85 470 1660 2840 2440	42 278 1065 2250 2640	84 330	362 1216 2580	.0263 .0465 .143 25	25 92 950
	2 3 4 5 5	470 1660 -2840 2440	278 1065 2250 2640	84 330	362 1216 2580	.0465 .143 25	92 950 2075
	3 	1660 	1065 2250 2640	330	_1216_ 	.143	950 7075
		2840 2440		330	2580	.25	2075
	5 	2440	2040				
· · · · · · · · · · · · · · · · · · ·	ʻэ			. 5TU_	2930	.28	2450
· · · · · · · · · · ·		1005	2062	315	2377	.238	1910
	. 7	1280	1482	345	1827	.197	- 1490
····· · · · · · · · · · · · ·	8	_].].10 ··	1195	355	1550	.175	1240
· · · · · · · · · · · ·	9	950	1030	350	_1380_	.159_	1090
	70	775	862	340_	1202		930
· ····································	11	585	680	328	1008	.121	740
	12	420	502		607	.097	540
·····	_/3	275	_348 _	268	616	- 075	375
	14	15	210	225	_435_	055	_245
· · · · · · · ·	15	40	92	178	270	.036	118
		· 					
Juperses	cd_by	_Age_S	24				
		·		······			
· · · ·		•	· •				•
	- · _						
				-			



CAMP DRESSER & MCKEE Ironmental Engineers Boston, Mass.

:

ł

K

۰.

.

•

ţ

i t

CLIENT <u>CLIENT ACCERT</u> JOB NO <u>STATE</u> PAGE <u>J2</u> PROJECT <u>SCHERKED</u> DATE CHECKED <u>BY</u> DATE<u>CLIEN</u> DETAIL<u>ANCEDDID</u> CHECKED BY <u>CHECKED</u> BY <u>CLIED</u> BY DETAIL - Jan 12.7.

DATE 212:7.4

		· · · · · · · · · · · · · · · · · · ·
 	 ······································	

Head on	Eley	Reservair	Lak.	Lale.		<u></u>	12.2
Pine	15415	Anos 4	Disternin	Former	4 4-	At Z	47 2
121		achec	ni.ca)	A12-4	1.4	154	150
		acres	CHEEF SI	1100 11			
_ 38	56	145.0					O
27	57	170,2	55	167.9	5079	5152	5107
10	ra		Ela	1.1	10215	10207	10=10
		1/3,3			19212	_0 <u>28_</u>	-12243
41	59	180,6	56	519	15700	15672	15728
115	605	1227	57	410	12452	12475	12122
		-1021.1-			-10-7-5	- 19.75 5-	20402
					· — — — — — — — — — — — — — — — — — — —		<u> </u>
41.6	59.6	133.2	_567	628	12997	18713_	19230
41.7	59.7	183.10	150.10	10/2/0	19542	12729	20295
	······································	2.20					
		10.01	2010				31 1 5 1
- <i>q1,8</i>	578_	130,1	2140	4	20026-	10/10	21430
01,9	59.7	125.10	4270	632	20631	18496	227/06
				[
120	10	1950	10217	700	2175	IDIER	21.120
46.0_	60	1.03.0		-1.00-	2///3	1013.1	
`							
				L			
		1			1	i	
	· · · · · · · · · · · · · · · · · · ·				· · · · · · · · · · · · · · · · · · ·		
	1			•	· <u>···</u> ································		
·	4-24	ma 19	AC Sec	<u> </u>	· · · · · · · · · · · · · · · · · · · 	(· · · · · · · · · · · · · · · · · · ·
			<u> </u>		·		
		1			t		
						1	
		<u>.</u>		;	·····	• • • • • • • • • • • • • • • • • • •	
	· · · · · · · · · · · · · · · · · · · ·	÷		•	<u> </u>		
					· · · · · · · · · · · · · · · · · · ·	·	
				·····	·	; · · _ •	
	:				i	:	
		i	· · · · · · · · · · · · · · · · · · ·	!		· · · · · · · · · · · · · · · · · · ·	
				•			
					· · · · · · · · · · · ·		
		<u> </u>					· · ·
	·				•		
			· · · · · · · · · · · · · · · · · · ·		·		

----------. . . · ------

. . .

11



•

CAMP ORESSER & MCKEE Environmental Engineers Boston, Masa.

Ì

٠.

~ .

Į

•.•

• •

. .

.

ι

İ

CLIENT Haley and Aldrich PROJECT <u>CONCERT</u> CHECKED BY CHECKED BY COMPUTED BY

1-3-ET :08 NO.56

PAGE 34 DATE 2/2/174 and

LO.	065. Intibus (2751)	Avoace Inflow (cfs)	3-0 DF-2 16B)	1 + 0 4+ + 2 (cf3)	Head on Pipe (u.s. nvert)	Elevertors (HISL) (FI)	Qu+Ma (2F3)
0	0			·	·		
_/		42			39.0	_ 57	57
2	410		.505.2	_ 5130_	39,003	57:05	_54
3	140	1045	50.76	6141	39,20_	57.20	_55
¢	2845	2250	6087	8337	39.62	57.62	55
5	2010	2640	8282	55901	40.11	_58,11	_55_
6	1485	2062	10867_	12929	40,48	58.48	_55_
7	1280	1482	12874	_14356	40.75	58,75	
2	_1.110	1195	14301	15496	40,96	58.96	_55
9	750	1030	15441	16471	41.10	59.12	_55
10	775	862	16044	16907	41.21	59,21_	55
	585	680	14262	16942	61,22	59,22	_56
12	_420	502	14280_	16782	41.19	59,19	_ 55
.13	275		1.4200_	14548	41.15	59,15	55
14	145	210	16083	16293	41.10	59,10	55
15	40	92	15955	16047	41.06	_ 59,060_	

and a second management of a second ----···· ··· ···

____ · · · · ··-- · ··· ·

-. . ------- --- ---- -

.

AMP ORESSER & MCKEE	CLIENT Aldrich JOB NO. 51-129-RT PAGE 25	
invironmental Engineers	PROJECT JOMCIANT CIARTON DATE CHECKED STORE DATE 2/21/72	
Joston, Mass.	DETAIL CHECKED BY CHECKED BY COMPUTED BY	
······		
l		
	Final Outflow	
	Hydrogroph	
· · · · · · · · · · · · · · · · · · ·		
· · · · · · · · · · · · · · · · · · ·		
	······································	
	· · · · · · · · · · · · · · · · · · ·	
		 I a statement of the second sec
20-		
~	······································	• •
0	2 3 4 5 6 7 8 9 10 11 12 13 14 15	
·····	Time Units	
	e e e e e e e e e e e e e e e e e e e	
·····		
· ···	· · ·	
·		

I.

-

. . .

: \

1

3

CAMP ORESSER & MCKEE PAGE_____ DATE -Environmental Engineers DATE Boston, Mass. -- -- -- -Capacitics (continued) Overflow Ditch Crass section Mar Morth Stret____ * 33 6" Q=1,49 83 512 A R _____ A=6x2 + 2x1/2x 3x2 = 180 WP= 6+7,2=19,2 R = 1.364 Q - 1.49 X 1.36 4 213 X 18 X J 1/2 _ .. _ ____ Q=1099,66 31/2 5-.019048 5Q= 151.8~152 cF3 _____ _ - --- -

Ĭ SLIENT 19 01 01 10/10/10/10 0. I JOB NO. 510/-3-27 PAGE 37 CAMP ORESSER & MOKEE DATE 2, 4/72 DATE CHECKED BY 290_ECT 200-Inntal Engineers DETAIL ALDERALD Boston Mass. Tipical Cross Section of Over Flow Ditch -----90 Too OF EOC D Carro 70 Ц ľ 2000 . . . iào ______ ··-- ··· · Langth Elev. And WP R 5 $\overline{\mathcal{Q}}$ Hod 60.0 13 13.2 1.364 .019048 152 . Ż' . 168 153 1.100 1227 61.0 _____4' 4' 62.0 353 200 1,765 5' 63.0 590 255 2,314 6' 64.0 875 310 2,823 1.765 2535 __7.277 -----. D-39



i

1

CLIENT Haley and Alerich LIO. I ,CB NO. 561-8-ET PAGE_39 CAMP ORESSER & MCKEE PROJECT Jomenant Rigerin DATE CHECKED 82 JATE 21. 5/ Environmental Engineers CHECKED BY DETAIL HUDOLOGI Caracities Twin 36" R.C. -upstram invert = 52' _downstream invert = 51.5' length = 60' _3/000 3 . 008333 . h1-2 F 6V2 _____02g____ F=,0170 1-604 0-34+ V=1,69 22 512 - 1,49 (3).007 (.003333) 2 1013 4).013 V= 2.64 13 $h_{L} = 2 \times \left(\frac{0196 \times 60' \times (8,64'5)^{2}}{3' \times 2 \times 32,2' \cdot 3^{2}} \right) = 0.909' \text{ for } 60' \text{ leng the of two in } 3'_{10}$ Q=0.279_(110) (3)^{2,03} (7.58).50 Q= 37.5 6F3 For one 36" pipe Q (for twin 36) • 79 cfs At day of inspection, water surface in reservoir was at clexation 52.6 and twin 36" had approximately Lonches of water in Them Jo, at normal pond level the twin 36° would be full. - Bad is a ekv. 40.0 A., pord a 56' $\begin{array}{c} H \text{ wsel} \cdot 60', \quad \Omega = 2x \cdot 72x + \frac{3}{4} \sqrt{64.6x4} & 164 \text{ cfs} \\ (assume no ponding) \\ OUT This isn't product) \\ \end{array}$

JOB NO. 5%-1-2-27 CLIENT Halon and Ainch PAGE CAMP DRESSER & MCKEE 821-78 Bruker PROJECT Respers DATE CHECKED___ DATE tel Engl CHECKED BY. COMPUTED BY OETAIL ELEVATION (JUL) Ś 20 A Superset d Page 44 0 áy (20) 0 ido 2 Ś õ Unth 4 GG G 99 20 123 5 ź <u>h</u>. 1 2 2 2 1 2 2 2 1 2 2 2 1 2 2 2 2 (273) Anto 1) 2010 02 1.70 Dis-1.000 1.000 そんらって 1 1 1 1 1 WYY IN L)CYL

₩.

1

Ċ

.

ξ.

ł

(÷

<u>د</u> ا

D-42

____ روار المنتخص روار والم JOB NO: ______ PAGE 4 / CAMP ORESSER & MCKEE 8-21-1 PROJECT ----- DATE CHECKED DATE. Bash CHECKED BY_ COMPLITED BY Jecton of Twin 36" C.C.P. 1200009 down ----ور و ÷ stadily -75-1200 0FF Flow will go into NOFTOW SINCAS مصاءكين Ø SUPERSERE BY PAGE 45 Devicent Jucit Elev. Head on ed. 60.0 41___ 91 101.0 10 54 -----62.0 20 _123 229 158 752 3.0 63.0 64.0 - 4.2 148 1390 _____ LOV: L-270 For weir wert tor is -----------

ĩ

ľ

.

•

. .

4

1 - - - - h PAGE 42 1000 CAMP ORESSER & MCKEE CLIENT. JOB NO. 21-73 برم و د r yara POJEC T iel Ena DATE ... CHECKED BY DETAIL HISTING TEO SY Ditim section of highersted FIDUD FI Superseded by Page 26 = 4130 cts CAPACITIES - - - -a overfrow drich) Q' (twin 36" Eler. 60,0 41 152 199 61.0 145 1227 1372 62.0 3535 352 3887 7077 63.0 860 7937 11985 64.0 1464 13,449 Griph of arotal 20,200 1. Elevation successed by Page 47 Graph. OF D. TOTAL 10,600 Ð 4130------. . 410 . 42.82 63.0 62.CB 64.0 COC. ----Elevation (MSL)

1

Linger 2. PAGE 43 non CAMP ORESSER & MCKEE CLIENT -JOB NO. 8-2F78 Files DATE 2/9,70 ist Pi-ein-PROJECT ------DATE CHECKED. ronmental Engli CHECKED BY Boston, Mass COMPUTED BY 1500 Graph of Quiver RAC Superies of Gran 12 36" 2:2.0. TUSHTS 500 ī 410-3 0 2- 62,08 60.0 43.O 61.0 42.0 64.0 Elevation (MSL) 1000 - - -Grapio of Querfice 100 drich _200 Q ditch = 3720 = F3 10 ww aculvert = \$10 cts 100 3720 _ 2010 ... 49,0 620 41.C 12.0 200 43.C

Į

٠.

ľ

.

.

Ł

1

•

D-45

Δ.

.08 NO. <u>Stel-9-</u>0 CLIENT Hale, and Aldren CAMP DRESSER & MCKEE PAGE. PROJECT JOMENACT PLACE DATE CHECKED aronmental Engineers CATE 2/2/172 DETAIL HYDODOGY Droll Boston, Mass. CHECKED BY_ Beause the Flows From each of the drainage areas do not peak at The some time, The following is an exercise using the peak flow of The northern drainage area (4131 c.f.s) and the Flow which accurs at reservoir from The southern drainage area at the time of The northern O.A. is ROK_ Lothern O.A. : 4131 c.F.s. at to: 4 hours Southern O.A : 770 c.f.s. at t= 4 hours from Start of the Storm, At 170 c.F3, Water SurFace Elevation in Reservoir 57.05 57.05 D-46

.08 NO. 561-3- ET CLIENT Holey and Aldrich CAMP ORESSER & MCKEE 45 PAGE_ DETAIL <u>11/1/2/D/D/2/</u> DATE CHECKED BY DATE BY DOMETED BY DIE BY DOMETED BY DETAIL OF DOMETED BY DIE DATE BICI 170 Environmental Engineers Boston, Mass. Stage · Discharge Relationships for Twin 36" Culvert Ø Eler. Hod an_ Head on_ ゐ U.S. W.J.E Ead - راجل - Culvery culvert 0 57,05 _____ 0 0 95 80 0 \sim 58 0 1.95 114 0 2,75 140 0 0 40 54 3.95 162 61 1 4,95 182 62 2 229 199 63 5,95 702 7 2 6.75 215 1290 64 LOTES Weir Locficient " " = 270 for road Pressure Flow Coefficient "C" = 0.12 For culvert - CA V29h Dorese D-47

C

ł

Ì





Ġ

MICROCOPY RESOLUTION TEST CHART NATIONAL BUREAU OF STANDARDS-1963-A

Hake and Aldrich CAMP ORESSER & MCKEE CLIENT. JOB NO. 27 PAGE_ TOMOSCH REACTON DATE CHECKED. nentai Eng PROJECT CATE Hydrology A DETAIL CHECKED BY. COMPUTED BY . . . _ Flow from Northern Jection of Watershid 41316. F.J. CAPACITIES Elev. 0 Q 0 (overflow ditch) (TOTAL) ("DE MINT) (ms1) 0 0 57.05 Õ 80 0 0 58 44 59 114 158 292 140 152 60 1227 1443 626 61 39.46 3535 411 62 7077 901 2978 63 64 11985 1511 13496 D-48

ŗ,

ľ

.

•

Ļ



Į

r

2

•

.

Ĺ.

CLIENT Hole, and Aldrich .08 NO. 272/-2 CAMP DRESSER & MCKEE 49 PAGE. PROJECT Somerset Margerian DATE CHECKED onmental Engineers DATE 212 DETAIL HUGOLOGY CHECKED BY COMPUTED BY Therefore opproximately 440 c. F.S. goes through two 36" R.C. P. (and over North St.) and approximately 3720 cfs goes out the averflow ditch. Jo, at 4= 4 hours, Corroir In Flow - 440 cfs (U.O.A + 770 cf3 13.0.A = 1210 C.F.J totol ADODXIMALE OUT Flow after Buting = 55 c. F.s. GROK INFOW VS. W.J.E 3000 -1000 58 _____58.2 ____58.0 ____58.0 _ 58.8 Elevation 58.05 (ms1) Q 55 cts At 4= 4 hours D-50

ľ

•

i.

CLIENT CLIENT CLIENT CONPUTED BY CLIENT COMPUTED BY 49 CAMP ORESSER & MCKEE Inter Engineers DATE____ 1 30 IF you consider using to 1,65 hours (The time when the Southurn Grainage Alea Flow peaks) , and 2730 cfs as the peak of the S. O. A , the Flow Time The Northern Ordinage Alea would estal approximately 16 cFs lat + +1.65 hrs). Lorgidering the large reservoir surface area, 1/20. ILELFS will POT CAUSE a SIGNIFICANT INCLEOSE IT___ The reservoir & water surface steration Therefore, the Final reservoir elevation and corresponding outflow is 59,22 A lobove mal) and <u>56 c.f.s.</u> -.... •···• ____ ____ ______ ···· · · · · _____ • · - · · **.** .. -_____ • • • • • • • • • • • • • • • . . . _ · · · - - a an an a mar an an an a suma a suma mana ang ang an a sa mang mang mang mang a

 $\langle \overline{} \rangle$

K.

.

D-51

.

APPENDIX E INFORMATION CONTAINED IN THE NATIONAL INVENTORY OF DAMS

P

