

MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A

AD-A155 515


CONNECTICUT RIVER BASIN
WARE, MASSACHUSETTS

WINSOR DAM MA 00588
QUABBIN SPILLWAY MA 00589
GOODNOUGH DIKE MA 00590

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM

Copy available to DTIC does not
permit fully legible reproduction

DTIC FILE COPY



DTIC
ELECTE
JUN 2 0 1985
S D G

DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
WALTHAM, MASS. 02154

DISTRIBUTION STATEMENT A

Approved for public release
Distribution Unlimited

SEPTEMBER 1978

85 5 31 059

REPRODUCED AT GOVERNMENT EXPENSE

DISCLAIMER NOTICE

THIS DOCUMENT IS BEST QUALITY PRACTICABLE. THE COPY FURNISHED TO DTIC CONTAINED A SIGNIFICANT NUMBER OF PAGES WHICH DO NOT REPRODUCE LEGIBLY.

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER MA 00588/ 00589/ 00590	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Winsor Dam/Quabbin Spillway/ Goodnough Dike NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS		5. TYPE OF REPORT & PERIOD COVERED INSPECTION REPORT
		6. PERFORMING ORG. REPORT NUMBER
7. AUTHOR(s) U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION		8. CONTRACT OR GRANT NUMBER(s)
9. PERFORMING ORGANIZATION NAME AND ADDRESS		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
11. CONTROLLING OFFICE NAME AND ADDRESS DEPT. OF THE ARMY, CORPS OF ENGINEERS NEW ENGLAND DIVISION, NEDED 424 TRAPELO ROAD, WALTHAM, MA. 02254		12. REPORT DATE September 1978
		13. NUMBER OF PAGES 140
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Cover program reads: Phase I Inspection Report, National Dam Inspection Program; however, the official title of the program is: National Program for Inspection of Non-Federal Dams; use cover date for date of report.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) DAMS, INSPECTION, DAM SAFETY, Ware, Massachusetts Connecticut River Basin		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) The structures are all classified as being large in size. The projects are in excellent to good condition. There were no obvious signs of failure or conditions which would warrant urgent remedial treatment. It has a hazard potential of high.		



DEPARTMENT OF THE ARMY
 NEW ENGLAND DIVISION, CORPS OF ENGINEERS
 424 TRAPELO ROAD
 WALTHAM, MASSACHUSETTS 02154

REPLY TO
 ATTENTION OF:

NEED

Honorable Michael S. Dukakis
 Governor of the Commonwealth of
 Massachusetts
 State House
 Boston, Massachusetts 02133



Accession For	
NTIS GRA&I	<input checked="" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By	
Distribution/	
Availability Codes	
Dist	Avail and/or Special
A/1	23 CW

NOV 29 1978

Dear Governor Dukakis:

I am forwarding to you a copy of the Windsor Dam, Quabbin Spillway & Goodnough Dike Phase I Inspection Report, which was prepared under the National Program for Inspection of Non-Federal Dams. This report is presented for your use and is based upon a visual inspection, a review of the past performance and a brief hydrological study of the dam. A brief assessment is included at the beginning of the report. I have approved the report and support the findings and recommendations described in Section 7 and ask that you keep me informed of the actions taken to implement them. This follow-up action is a vitally important part of this program.

A copy of this report has been forwarded to the Department of Environmental Quality Engineering, the cooperating agency for the Commonwealth of Massachusetts. In addition, a copy of the report has also been furnished the owner, the Metropolitan District Commission, Commonwealth of Massachusetts, 80 Somerset Street, Boston, Massachusetts 02108, ATTN: Mr. Martin Weis, Chief Engineer.

Copies of this report will be made available to the public, upon request, by this office under the Freedom of Information Act. In the case of this report the release date will be thirty days from the date of this letter.

I wish to take this opportunity to thank you and the Department of Environmental Quality Engineering for your cooperation in carrying out this program.

Sincerely yours,

JOHN P. CHANDLER
 Colonel, Corps of Engineers
 Division Engineer

Incl
 As stated

WINSOR DAM MA 00588
QUABBIN SPILLWAY MA 00589
GOODNOUGH DIKE MA 00590

CONNECTICUT RIVER BASIN
WARE, MASSACHUSETTS

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM

BRIEF ASSESSMENT

PHASE I INVESTIGATION REPORT NATIONAL DAM INSPECTION PROGRAM

Identification No. MA 00588 Winsor Dam
and Name: MA 00589 Quabbin Spillway
MA 00590 Goodnough Dike
Town: Ware
County: Hampshire
State: Massachusetts
Date of Site Visit: 29 June 1978

Quabbin Reservoir was created by the Metropolitan District Commission in the late 1930's by construction of Winsor Dam, Quabbin Spillway and Goodnough Dike. By virtue of both storage and height, the structures are classified as "large" in size.

Winsor Dam and Goodnough Dike are full hydraulic fill earth embankments, having maximum heights of 170 and 135 ft. and lengths of 2640 and 2140 ft., respectively. Quabbin Spillway is an ungated masonry weir, having a maximum height of approximately 14 ft. and an overall length of 405 ft.

The projects are in excellent to good condition. There were no obvious signs of failure or conditions which would warrant urgent remedial treatment.

Hydraulic analyses indicate that the Quabbin Spillway in combination with the auxiliary spillway at Winsor Dam, are adequate in size to safely pass the test flood, calculated from the probable maximum flood, without overtopping Winsor Dam or Goodnough Dike.

Because of the importance of these structures for water supply to the Greater Boston area, because of the high hazard potential in the event of a failure, and because the embankments are hydraulic fill with relatively steep slopes, it is recommended that the MDC undertake a


BRIEF ASSESSMENT (continued)

detailed investigation of embankment stability under static and earthquake loading.

HALEY & ALDRICH, INC.

by:

Harl Aldrich
Harl Aldrich
President



This Phase I Inspection Report on Windsor Dam, Quabbin Spillway & Goodnough Dike has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the Recommended Guidelines for Safety Inspection of Dams, and with good engineering judgment and practice, and is hereby submitted for approval.



CHARLES G. TIERSCH, Chairman
Chief, Foundation and Materials Branch
Engineering Division




FRED J. RAVENS, Jr., Member
Chief, Design Branch
Engineering Division



SAUL COOPER, Member
Chief, Water Control Branch
Engineering Division

APPROVAL RECOMMENDED:



JOE B. FRYAR
Chief, Engineering Division

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D. C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I Investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I investigations are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the test flood is based on the estimated "probable maximum flood" for the region (greatest reasonably possible storm runoff), or a fraction thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

TABLE OF CONTENTS

	<u>Page No.</u>
LETTER OF TRANSMITTAL	
BRIEF ASSESSMENT	
REVIEW BOARD SIGNATURE PAGE	
PREFACE	iii
TABLE OF CONTENTS	iv
OVERVIEW PHOTOS	vi
LOCATION MAP	viii
I. PROJECT INFORMATION	
1.1 GENERAL	1
1.2 PROJECT DESCRIPTION	2
1.3 PERTINENT DATA	8
II. ENGINEERING DATA	
2.1 DESIGN RECORDS	13
2.2 CONSTRUCTION RECORDS	13
2.3 OPERATION RECORDS	13
2.4 EVALUATION	13
III. VISUAL EXAMINATION	
3.1 FINDINGS	15
3.2 EVALUATION	19
IV. OPERATIONAL PROCEDURES	
4.1 PROCEDURES	20
4.2 MAINTENANCE OF DAM	20
4.3 MAINTENANCE OF OPERATING FACILITIES	20
4.4 WARNING SYSTEMS IN EFFECT	20
4.5 EVALUATION	21
V. HYDRAULIC/HYDROLOGIC	
5.1 EVALUATION OF FEATURES	22
VI. STRUCTURAL STABILITY	
6.1 EVALUATION OF EMBANKMENT STRUCTURAL STABILITY	25
6.2 EVALUATION OF STRUCTURAL STABILITY, QUABBIN SPILLWAY	26

TABLE OF CONTENTS (Continued)

	<u>Page No.</u>
VII. ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES	
7.1 ASSESSMENT	27
7.2 RECOMMENDATIONS	27
7.3 REMEDIAL MEASURES	28
APPENDIX A - INSPECTION TEAM ORGANIZATION AND CHECK LIST	
APPENDIX B - LIST OF AVAILABLE DOCUMENTS AND PRIOR INSPECTION REPORTS	
APPENDIX C - SELECTED PHOTOGRAPHS OF PROJECT	
APPENDIX D - OUTLINE OF DRAINAGE AREA AND HYDRAULIC COMPUTATIONS	
APPENDIX E - INFORMATION CONTAINED IN THE NATIONAL INVENTORY OF DAMS	




Overview Photo of Winsor Dam



Overview Photo of Quabbin Spillway



Overview Photo of Goodnough Dike



DETAIL "A"
SCALE: 1"=20'

NOTE:

PLAN DEVELOPED FROM M. D. C. CONSTRUCTION DRAWINGS NO. NO. 17, ACC. 24117 SHOWN IN APPENDIX B AND HALEY & ALD ON 29 JUNE 1978.

LEGEND:





PHOTOGRAPH NUMBER AND DIRECTION OF VIEW.

FILE NO. 4160 00 B28

HALEY & ALDRICH, INC.
CAMBRIDGE, MASSACHUSETTS

QUABBIN RESERVOIR



CONSTRUCTION DRAWINGS NO. 2, ACC. 24102 AND
X B AND HALEY & ALDRICH FIELD OBSERVATIONS

WINSOR DAM AND
QUABBIN SPILLWAY
QUABBIN RESERVOIR
SITE SKETCH PLAN

DIRECTION OF VIEW.

SCALE: 1" = 400' SEPTEMBER 1978

APPENDIX C-1

(2)

PHASE I INVESTIGATION REPORT
NATIONAL DAM INSPECTION PROGRAM
WINSOR DAM MA 00588
QUABBIN SPILLWAY MA 00589
GOODNOUGH DIKE MA 00590

I. PROJECT INFORMATION

1.1 GENERAL

A. Authority. Public Law 92-367, August 8, 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a National Program of Dam Inspection throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region.

Haley & Aldrich, Inc. has been retained by the New England Division to inspect and report on selected dams in the State of Massachusetts. Authorization and notice to proceed were issued to Haley & Aldrich, Inc. under a letter dated 26 April 1978 from Colonel Ralph T. Garver, Corps of Engineers. Contract No. DACW33-78-C-0301 has been assigned by the Corps of Engineers for this work. Camp, Dresser & McKee, Inc. was retained as consultant to Haley & Aldrich, Inc. on the structural, mechanical/electrical and hydraulic/hydrologic aspects of the investigation

B. Purpose. The primary purposes of the National Dam Inspection Program are to:

1. Perform technical inspection and evaluation of non-Federal dams to identify conditions which threaten the public safety and thus permit correction in a timely manner by non-Federal interests.
2. Encourage and prepare the states to initiate quickly effective dam safety programs for non-Federal dams.
3. To update, verify and complete the National Inventory of Dams.

1.2 PROJECT DESCRIPTION

A. Location. Winsor Dam is located on the Swift River, at the boundary between the towns of Belchertown and Ware, Massachusetts. The Quabbin Spillway and Goodnough Dike are located nearby in the town of Ware. The Location Map on page viii shows the location of the three structures.

At the time of construction, a portion of Winsor Dam as well as Quabbin Spillway and Goodnough Dike were located in the Town of Enfield, the corporate existence of which was eliminated when Quabbin Reservoir was constructed.

B. Dam, Spillway, Dike and Appurtenances. Winsor Dam consists of a 2640 ft. long full hydraulic fill earth embankment, an intake structure discharging through a tunnel to an outlet structure and powerhouse, and an auxiliary spillway, as shown in Appendix B-54 and Appendix C-1.

The maximum height of the embankment is about 170 ft. and the crest is approximately 35 ft. wide. A paved roadway on the crest spans the length of the embankment. The normal operating level of the reservoir is El. 530, 20 ft. below the top of the dam. The upstream face is sloped at about 2 horizontal to 1 vertical above a berm at El. 535 and paved with light riprap. Below the berm, heavy riprap was placed at 1.5:1 and flattening to 3:1 below the wave break. The downstream face is grassed and slopes at 2:1, 2.5:1 and 2.75:1 with berms for drainage at the changes in slope. A concrete core wall extends from an elevation about 25 to 30 ft. above the bottom of the dam to the surface of rock, below which is a grout curtain 20 ft. into rock. The embankment is shown in Photos No. 2, 3, 4, 5 and 8 in Appendix C. A profile and a cross-section at the top of the dam are shown in Appendix B-58 and B-59, respectively.

An intake structure, Photo No. 9, is located on the right side. The 157-ft. long "intermediate intake" shown in Appendix B-60 upstream of the intake structure feeds a 68-in. diameter conduit and a 48-in. diameter conduit which go to a power house at the outlet structure downstream. The outlet channel from the power house discharges into the Swift River. Regulating outlets are further described in Section 1.3J.

An auxiliary spillway located beyond the right abutment of Win-

sor Dam consists of a gently sloped grassed approach channel and circular concrete cutoff wall with "quarry faced ashlar" at the crest. This spillway is only intended to provide emergency overflow at El. 536 in case of extreme high water. Photos No. 11 and 12 and Appendix B-61 show details of the auxiliary spillway.

Quabbin Spillway is located approximately 1000 ft. east of the left abutment of Winsor Dam. It consists of an approach channel, a 405 ft. long masonry concrete weir, discharge pool and spillway channel, shown in Appendix B-62 and Appendix C-2.

The approach channel is approximately 80 ft. wide and 650 ft. long, excavated into rock and shown in Photo No. 21. The channel bottom drops 8 ft. from Quabbin Reservoir to the spillway weir.

The spillway weir is 370 ft. long with a crest elevation of 530 and has a 34 ft. 8 in. long side discharge at El. 528. Currently 2 ft. of flashboards are in place on the short section. Refer the Photos No. 13, 14, 16, 19 and 20 for the correct configuration of the weir as shown sketched in Appendix C-2.

The discharge pool was excavated into rock, as was the long spillway discharge channel. The discharge channel has a width of approximately 30 ft. and length of 2300 ft. from the discharge pool to the convergence point with the Swift River. Photos No. 22, 23, 24 and 25 show features of the spillway discharge channel. Cross-sections of excavations for the spillway channel are shown in Appendix B-63.

Goodnough Dike consists of a 2140 ft. full hydraulic fill embankment with no appurtenances. The dike is shown in Appendix B-64 and Appendix C-3.

The maximum height of the embankment is about 135 ft. and the crest is approximately 35 ft. wide. A paved roadway on the crest spans the length of the embankment. The top of the dike is approximately 20 ft. high than the normal operating level of El. 530 at Quabbin Reservoir. The side slopes, zoning, impervious core and grout curtain for the embankment are of the same design and construction as Winsor Dam. Photos No. 27 through 32 show the Goodnough Dike embankment. Cross-sections and a profile on the centerline of the dike are shown in Appendices B-67 and B-68, respectively.

C. Size Classification. Winsor Dam, Quabbin Spillway and

Goodnough Dike impound a reservoir with a maximum storage estimated to be 1,810,000 acre-feet. Winsor Dam and Goodnough Dike have a maximum height of 170 and 135ft., respectively. Storage of more than 50,000 acre-feet and/or height greater than 100 ft. classifies these structures in the "large" category according to guidelines established by the Corps of Engineers.

D. Hazard Classification. The structures are currently classified as having a "high" hazard potential in the Corps of Engineers National Inventory of Dams. A failure of Winsor Dam or Goodnough Dike would cause a loss of life estimated in previous inspection reports between 2 and 300 persons. A review of the downstream conditions indicate that between 25 and 100 residential, industrial and commercial properties would be inundated in the developed areas of Beaver Lake, Palmer, and Three Rivers. There is no question that the economic losses associated with such an event would be catastrophic. A failure of Quabbin Spillway, however, would result in a much lesser flow which would not present any significant hazards downstream. Therefore, it is recommended that the "high" hazard potential classification be retained for the Winsor Dam and Goodnough Dike and that a "low" hazard classification be assigned to Quabbin Spillway.

E. Ownership. The three structures are owned by the Metropolitan District Commission, Water Division, of the Commonwealth of Massachusetts. The owner's address is 20 Somerset St., Boston, MA 02108

F. Operator. The following individual has day-to-day responsibility for the operation of the project:

Mr. Harold E. Mellin, Jr.
Metropolitan District Commission
Winsor Dam
Ware Road
Belchertown, MA 01007
(Phone: 413/323-6921)

Mr. Mellin represented the owner during this investigation.

G. Purpose of Dam. The primary purpose of Quabbin Reservoir is to provide a potable water supply for the Metropolitan Water District, a group of more than 30 cities and towns in the Greater Boston Area.

In addition, the reservoir and reservation provide recreation in the form of boating, fishing, hiking and picnicking. The Quabbin Reservoir Reservation is also an important wildlife habitat.

H. Design and Construction History. The design and construction history of Winsor Dam, Quabbin Spillway and Goodnough Dike which form the Quabbin Reservoir is well documented due to the size and importance of the project. Several technical papers addressing this interesting work were published in professional journals. The following narrative is based largely upon the papers by Dore¹ (1935) and Winsor² (1938).

The idea of forming Quabbin Reservoir to supply water to the City of Boston was conceived by the MDC prior to 1920. A number of test borings were made in 1920 and 1921 as part of a preliminary investigation concerning the general location of the dams. By 1929, a large number of borings, described in detail by Hammond³ (1929) confirmed that the general sites chosen for the project were overlain by deep (greater than 100 ft.) glacial deposits of pervious sands, gravels, cobbles and boulders.

The valleys chosen for Winsor Dam and Goodnough Dike are long and wide, requiring construction of earth embankments rather than concrete gravity dams. Investigation of possible borrow areas revealed abundant materials suitable for earth-type dam construction. The water tables at the two sites were between 120 and 130 ft. above bedrock, presenting an additional construction consideration relating to excavation through pervious glacial deposits. It was decided to sink two exploratory caissons, one at each site, to further investigate the overburden characteristics, the feasibility and cost of open and

1

"Design and Progress on the Construction of Dams for Quabbin Reservoir" by Stanley M. Dore, Journal of the Boston Society of Civil Engineers, July 1935.

2

"Quabbin Reservoir - Recent Developments in the Construction of the Ware-Swift Water Supply for the Metropolitan District" by Frank E. Winsor, Journal of the Boston Society of Civil Engineers.

3

"Diamond Drill Borings for the Swift River Dams" by N. Leroy Hammond, Journal of the Boston Society of Civil Engineers, January 1929.

pneumatic caisson construction and the possibilities of lowering the groundwater by pumping. The contract for this work was awarded in September 1931, and was completed about a year later.

The exploratory caissons measured 32 ft. long by 12 ft. wide. Open dredging methods proved unfeasible below depths of about 50 ft. in the dense granular soils. A compressed air method was then successfully adopted for sinking the caissons. Air locks were installed over the working wells and maximum air pressures of about 33 psi were used to advance and seal the caisson to ledge "in the dry" about 70 ft. below river level at the Winsor Dam site. Information obtained from the sinking of these caissons and the pumping carried on from them indicated the construction method was feasible for use as a cutoff wall at both sites and the most economical.

While the sinking of the exploratory holes was underway, work to divert the Swift River during construction was begun at the Winsor Dam site. The stream control works consisted mainly of the 30-ft. effective diameter rock tunnel under the right abutment. The conduit was concrete lined and about 1200 ft. long. The Swift River was diverted through the tunnel in June 1933.

Two exploratory caissons, in addition to the one already built, were excavated pneumatically and sealed to rock at the Winsor Dam site. Pumping from these three caissons from November 1934 to January 1935 lowered the water table to approximately 90 ft. below the river level and maintained it at that position until the start of core wall construction in May 1935.

The entire cutoff wall at Winsor Dam was formed by a total of forty reinforced concrete caissons, all except the first one being 45 ft. long by 9 ft. wide. Groundwater was effectively controlled by pumping from wells in completed caissons and wellpoints and sumps upstream of the construction. Due to the effects of pumping, less than 20% of the caisson work was done under compressed air conditions. Since the overburden soils became more pervious with depth, it was decided that the caissons would be sealed to rock and grout curtains installed 20 ft. into rock. The overburden and geological conditions at the site are shown in Appendices B-55, B-56 and B-57.

Prior to sinking the caissons, an open trench was excavated across the valley to a depth of about 30 ft. The trench was subsequently filled with impervious "topsoil" and compacted around the concrete core wall in six-inch thick lifts with sheepsfoot rollers. The concrete core wall extended a minimum of 25 ft. into this refill. This foundation work was completed in the early summer of 1936.

Full hydraulic fill construction of the embankments was considered to be the most economical and desirable for stability and uniformity of the slopes. Sluicing of the embankments at Winsor Dam began in 1936. Materials were brought to the hog box on belt conveyors and mixed with water jets to flow into a steeply sloped trough towards the sluicing line. The quality of the core material being pooled was continuously monitored and checked by sounding with a rod and sampled for inspection and laboratory analysis. Placement of the 4,000,000 cubic yards of fill required for Winsor Dam was completed in 1939. The top 30 ft. of dam embankment was placed by rolled-fill methods. The foundation and embankment are shown in profile in Appendix B-58. A cross-section through the top of the dam is shown in Appendix B-59.

Quabbin Spillway is located in a natural high valley to the east of the left abutment of Winsor Dam. This site was structurally desirable because the spillway channel would be formed entirely in rock from the spillway weir to the Swift River. A spillway weir length of about 400 ft. was chosen to allow passage of floods up to 10,000 cfs without flooding out the rock discharge channel. It was believed that floods up to 15,000 cfs could be carried with no important scour of the earth banks above the rock channel. A plan of the spillway is shown in Appendix B-62 and cross-sections are included in Appendix B-63.

Goodnough Dike was constructed in the period from approximately September 1931 to July 1938. The dike is nearly identical in design and construction to Winsor Dam. The core wall was built as previously described by excavating an open-cut trench, by sinking from the bottom reinforced concrete caissons sealed to each other and to rock, grouting below the concrete core wall, and by filling the wells of the caissons and the open-cut trench with impervious soils. The geological conditions at the dike site are shown in Appendices B-65 and B-66.

Beaver Brook was initially carried past the construction site in a wooden flume about 350 ft. long. It was then diked up upstream for over 1,000 ft. by subsequent pumping, and eventually the brook flow was through an 18-in. pipeline until its subsequent diversion across the divide to the Swift River. The groundwater surface was lowered approximately 90 ft. during foundation construction.

Placement of the embankment by full hydraulic methods began in December 1934 and was completed prior to July 1938. The method

of placement was substantially the same as that for Winsor Dam. A profile on the centerline of the dike and typical cross-sections are shown in Appendices B-67 and B-68, respectively.

1.3 PERTINENT DATA

Elevations shown on all record drawings and as used in this report are referenced to Boston City Base datum. To convert to the National Geodetic Vertical Datum (NGVD), subtract 6.049 ft. from elevations which are on Boston City Base.

A. Drainage Area. The Quabbin Reservoir was formed in the 1930's by impounding the watersheds of the East, Middle and West Branches of the Swift River. The 186 square mile drainage basin which is tributary to the Quabbin Reservoir Spillway consists of heavily forested rolling terrain. In addition to this, limited diversion from the Ware River watershed of 98 square miles is discharged to the Quabbin Reservoir between October 15 and June 15 when flows on the Ware River exceed 85 mgd.

The water surface area of the reservoir at normal pool elevation is 39.4 square miles or 21 percent of the 186 square mile watershed.

B. Discharge at Damsite. Following completion of the impoundment works in 1940, it took 7 years before the reservoir was filled to its capacity of 412 billion gallons. Quabbin's level fell to 45 percent of capacity in 1967, following a six-year drought. No spillway discharge occurred from 1961 to 1976. The maximum recorded spillway discharge elevation was 531.03 on April 18, 1953. Based on the available rating curve, this stage corresponds to a discharge of about 1600 cfs. The longest continuous spillway discharge occurred between April 16 and May 7, 1978 with a maximum reservoir elevation of 530.34 (270 cfs) on April 24 and 25, 1978.

In addition to Quabbin Spillway at crest El. 530.0, there is an auxiliary spillway at crest El. 536.0. At this elevation, the maximum discharge over Quabbin Spillway is reported to be 15,000 cfs. Discharges in excess of this amount will produce water surface elevations in the reservoir above El. 536.0 at which point the auxiliary spillway will begin discharging.

An additional 70 to 75 mgd discharge capacity is available through the generating facilities at the intake structure.

C. Elevation (ft. above Boston City Base)

1. Top Winsor Dam and Goodnough Dike.....	530.0
2. Maximum pool-design surcharge....	536.1
3. Design surcharge - original design..	536+
4. Full flood control pool.....	536.1
5. Recreation pool.....	530.0
6. Spillway crest.....	530.0
7. Upstream portal invert diversion tunnel.....	Unknown
8. Streambed at centerline Winsor Dam.....	380.0
Goodnough Dike.....	415.0
9. Maximum tailwater.....	526.0

D. Reservoir

1. Length of maximum pool.....	18.0 miles at El. 536.0
2. Length of recreation pool.....	17.9 miles
3. Length of flood control pool.....	18.0 miles

E. Storage (acre-feet)

1. Top of dam.....	1,810,000 (Est.)
2. Test flood pool.....	1,417,600 (Est.)
3. Flood-control pool.....	1,417,600 (Est.)
4. Recreation pool.....	1,265,200 (Est.)
5. Spillway crest.....	1,265,200 (Est.)

F. Reservoir Surface (acres/sq. miles)

1. Top of dam.....	29,100/45.5 (Est.)
2. Test flood pool.....	26,120/40.8 (Est.)
3. Flood control pool.....	26,120/40.8 (Est.)
4. Recreation pool.....	25,216/39.4 (Est.)
5. Spillway crest.....	25,216/39.4 (Est.)

G. Winsor Dam and Goodnough Dike

1. Type.....	Hydraulic Fill
2. Length Winsor Dam.....	2640 ft.
Goodnough Dike.....	2140 ft.

- 3. Height
 - Winsor Dam..... 170 ft.
 - Goodnough Dike..... 135 ft.
- 4. Top Width..... 35 ft.
- 5. Side Slopes
 - Upstream..... 2:1, 1.5:1 and 3:1
 - Downstream..... 2:1, 2.5:1 and 2.75:1
- 6. Zoning..... Gradual, typical of hydraulic fill
- 7. Impervious core..... Silt and clay puddle
- 8. Foundation cutoff..... Concrete caisson core wall to rock
- 9. Grout curtain..... 20 ft. into rock from bottom of caisson

H. Diversion and Regulating Facilities. Not applicable

L. Quabbin Spillway

- 1. Type..... Masonry, round crest, with side channel discharge
- 2. Length of weir..... 34 ft. 8 in. at El. 528
- 3. Crest Elevation..... 370 ft. at El. 530
- 4. Gates..... 530.0
- 5. U/S Channel..... 2 ft. of flashboards on short section
- 6. D/S Channel..... 6 ft. rise in 500 ft.
- 20 ft. drop in 700 ft. then 60 ft. drop in 100 ft.

Auxiliary Spillway

- 1. Type..... 3 ft. wide quarry stone, 0.5 ft. high, both U/S and D/S
- 2. Length of Weir..... 240 ft.
- 3. Crest Elevation..... 536.0
- 4. Gates..... None
- 5. U/S Channel..... 1.5 ft. rise in 685 ft.
- 6. D/S Channel..... 1.5 ft. drop in 200 ft.

J. Regulating Outlets at Winsor Dam. Winsor Dam was originally constructed with three intakes. A "Lower Intake" was constructed during an early contract to provide a tunnel for stream diversion during construction of the dam. This intake tunnel now has a concrete plug below the intake structure and is therefore inactive. An "Intermediate Intake" with invert at El. 465 and an "Upper Intake" at El. 499 and located immediately upstream of the intake structure were also provided.

Fish screens with a sill at El. 471.75 and top of screened opening at El. 501.75 were installed in 1974. The balance of the intake channel was shut off during the installation of the screens. This effectively allows the use of the 157-foot long intermediate intake only. This intake is a reinforced concrete section 7 ft. wide by 8 ft. high. The intake feeds a 68-in. diameter conduit and a 48-in. diameter conduit which go to the power house. The 68-in. diameter conduit is installed inside the former stream diversion tunnel. Control at the inlet structure is by a 48-in. diameter 300 lb. test C.I. gate valve with Ludlow geared operator on a floor stand and a 48-in. by 72-in. sluice gate with Ludlow geared operator.

The two conduits are interconnected at the power house with a 36-in. pipe. The water may be fed by a 48-in. line to the Chicopee Aqueduct, may be discharged through the turbine generator or may be discharged through a 33-in. pipe bypassing the turbine. Control at the power house is by a 68-in. gate valve with geared operator, two 48-in. gate valves with geared operators, three 36-in. gate valves with geared operators, one 48-in. control valve with electric motorized operator and one 33-in. control valve with electric motorized operator. Orifice plates have been reported to be installed in the lines due to cavitation problems with the control valves.

I. Normal Operating Procedures. Quabbin Reservoir controls are used primarily to transmit water to the metropolitan area of Boston and the local communities of Chicopee through the Quabbin and Chicopee Aqueducts, respectively. They are operated based on demand. Also, a minimum of 20 MGD is released to the Swift River as required by law for low flow augmentation.

The water is released from Quabbin Reservoir via a 68-in. conduit and a 48-in. conduit interconnected with a 36-in. pipe at the power house. There the water may be discharged from the conduits through the turbine generator or through bypass pipes.

The gates for these conduits are at the power house. Additional gates are at the intake structure. The gates at the intake structure are normally left open and test operated twice a year.

II. ENGINEERING DATA

2.1 DESIGN RECORDS

Pertinent contract drawings for Winsor Dam, Quabbin Spillway and Goodnough Dike are listed and included in Appendix B. No original design criteria and calculations for the structures were available from the MDC. However, some items regarding the design for each structure are mentioned in the numerous articles published in technical journals about the subject projects.

2.2 CONSTRUCTION RECORDS

The original construction contract documents for the structures are listed in Appendix B-5. Pertinent drawings from these contracts are also listed and included in Appendix B. Many details of the actual construction are described in published technical papers and reports such as those in the Journal of the Boston Society of Civil Engineers and the Annual Report of the Metropolitan District Water Supply Commission.

Details shown on the contract drawings are in good agreement with field observations, with the exception of Appendix B-62 which shows an incorrect configuration for the spillway weir. The proper shape of the weir is shown on the Site Sketch Plan, Appendix C-2 and in Photo No. 13.

No construction modifications to the original structures following their completion in the 1930's are known to have taken place.

2.3 OPERATION RECORDS

Operational records kept by MDC Quabbin personnel are based primarily on daily reservoir discharges at the Winsor Dam outlet structure and test runs of the equipment.

2.4 EVALUATION

A. Availability. Design and construction records are available at the MDC, 20 Somerset St., Boston, MA 02108. Operation records are available at the MDC Quabbin, Ware Road, Belchertown, MA 01007.

B. Validity. With the exception of the change in configuration of the spillway weir described in Section 2.2, the contract documents appear to represent the the features of the presently existing structures, based on visual field observations.

C. Adequacy. The available data, in combination with the visual examinations described in the following section, are adequate for the purposes of the Phase I Investigation.

III. VISUAL EXAMINATION

3.1 FINDINGS

A. General. The Phase I visual examination of Winsor Dam, Quabbin Spillway and Goodnough Dike was conducted on 29 June 1978.

In general, the projects were observed to be in excellent to good condition. The earth embankments, spillways and intake structures are well maintained. A few minor deficiencies requiring correction have been noted.

Visual inspection checklists for the three structures are included in Appendix A and selected photographs of the projects are given in Appendix C.

B. Winsor Dam. Winsor Dam includes a large earth embankment, an intake structure and an auxiliary spillway. Photographs of this structure are numbered 1 through 12 in Appendix C.

The hydraulic fill embankment is in excellent condition. There was no visual evidence of settlement, lateral movement, seepage or other serious defects. The downstream slope, Photos No. 2 and 3, is covered by grass which is mowed frequently. Both the light and heavy riprap on the upstream slope appear to be stable and in good condition, with little weathering, Photos No. 4 and 5.

The roadway and stone walls across the crest of the embankment are in excellent condition. The near perfect horizontal alignment of the wall is shown in Photo No. 3. The roadway crest and walls are somewhat higher in grade toward the "center" of the embankment than they are at the abutments. At the time of construction, the embankment at its highest point above original ground, was built approximately 3 ft. higher than El. 550, the proposed final embankment grade. The cambered crest was established to allow for future settlement from consolidation of the hydraulic fill.

Settlement of the crest has been monitored at eight observation points located at the top of the riprap slope, immediately upstream of the stone wall. An MDC drawing which summarizes embankment settlements from 1939 to the last reading on 26 June 1973, is included in Appendix B-69.

The embankment, at its highest point between Sta. 18 and 21, settled 1.1 ft. between 1939 and 1952 (13 years). In the following 21 years to 1973, an additional 0.45 ft. of settlement occurred. Typically, settlements at the ends of the embankment are less.

Settlement of the embankment is evident where it interfaces with the intake structure, Photo No. 6. Photo No. 7 shows from 6 to 8 in. of settlement relative to masonry walls at roof level. In addition, settlement and lateral movement on the upstream slope are indicated by a crack in the stone masonry wall located immediately left of the intake structure, Photo No. 8. The wall at this location had been repaired in the past by pointing the crack.

The intake structure (control house), Photo No. 9, is in good to excellent condition and well maintained. There is some incidental rusting on the interior columns and some staining on the interior wall block. The exterior masonry does evidence loss of mortar from the lower joints. There is some efflorescence along the lower portion of the structure.

The power house lower floor is in excellent to good condition. Efflorescence is present on the walls near the slab. Water from an unknown source was present on the floor. The upper floor is also in good condition. No efflorescence was noted on the walls at this floor. The bond beam at the top of the wall does exhibit a number of shrinkage cracks. The underside of the roof appears to be stained.

The former diversion tunnel could not be inspected in detail due to the lack of internal illumination. However, a number of cracks in the lining were observed. Moderate leakage was observed through the roof at what appeared to be an old patch along a crack located approximately 450 ft. from the power house. The condition of the lining of this tunnel is estimated to be from good to fair.

The outlet channel downstream of the power house is in satisfactory condition.

The auxiliary spillway, located right of the MDC administration building, is in excellent condition. The approach channel to the curved spillway is grass, recently mowed. There are three trees in the channel as shown in Photo No. 11. In addition, a gravel roadway which crosses the approach channel immediately upstream of the spillway weir creates a minor obstruction to flow, especially at the left side where some fill has been placed.

The crest of the weir itself is in good condition, Photo No. 12.

C. Quabbin Spillway. The Quabbin Spillway includes a masonry weir, a short approach channel and a long discharge channel to the Swift River. Photographs of this structure are numbered 13 through 25 in Appendix C.

The spillway masonry is in excellent to good condition. Vegetation is present in several spots along the top masonry joint. The bottom or bed joint of the masonry has been eroded somewhat. In addition, some of the lower joints in the weir have lost mortar.

Three vertical cracks were noted in the highest portion of the weir, one at each end and one near the center. The crack near the center is shown in Photos No. 17 and 18. Spot efflorescence is present on the downstream face of the highest portion of the weir. Moisture was noted in local areas along the downstream face of the weir, at cracks and at the near vertical junction of the weir with bedrock. At one location near the south end of the weir where its height is only a few feet, a fine amount of water is shooting out approximately 3 in.

The upstream face of the weir was not observable due to the high reservoir level.

The access bridge to the flashboards and the flashboards are well maintained and in good to excellent condition, Photos No. 19 and 20. The flashboard guides are in excellent condition.

The approach channel to the spillway weir is in satisfactory condition, Photo No. 21.

The discharge pool and discharge channel from the spillway are generally in good condition. Seepage was noted from joints in the rock and from 2.5-in. diameter drill holes at locations immediately below the weir. Photo No. 15 shows water flowing from one such drill hole.

At the entrance to the discharge channel, large blocks of rock have fallen from the left face of the rock cut, Photo No. 23. The right side, Photo No. 24, is in a more stable condition. The stability of the right side is enhanced by the generally infrequent spacing and favorable attitudes of joints in the gneiss making up the channel face, Photo 22. Some large blocks of gneiss, visible by the man in

Photo No. 24, appear to have dislodged from a fault plane at the entrance to the channel. Another rockfall occurs along the right side of the channel, about 280 ft. downstream from the channel entrance. The volume of rock is not large and does not constitute an appreciable obstacle to flow in the channel. At a point about 360 ft. south of the channel entrance, along the right side, relatively minor amounts of fault and joint-bounded rock blocks appear capable of falling as a result of future frost action. The maximum volume at a given location that could be produced by such frost effects is estimated at 75 cubic yards. Such a volume, occurring at one instance, would probably result in a cross-channel debris mound less than 15 ft. in height.

Rock falls along the left channel face have occurred to a greater volume than on the right side primarily due to adverse dips on many of the joints in the hornfels, gneiss, and schist exposed on the face. Such joint surfaces dip into the channel at angles of from 40 to 70 degrees from the horizontal. Rock fall debris from these joints occur at the entrance to the channel and at distances of about 85 to 110 ft., 235 ft., and 285 ft. south of the channel entrance.

The general condition of the discharge channel downstream of the arch bridge is shown in Photo No. 25.

B. Goodnough Dike. Goodnough Dike is a large earth embankment without appurtenant structures. Photographs of the dike are numbered 26 through 33 in Appendix C.

The hydraulic fill embankment is in excellent condition. There was no visual evidence of settlement, lateral movement or other serious defects. The downstream slope is covered with grass, with a few small bare spots, which is mowed frequently. Both the light and heavy riprap on the upstream slope appear to be stable and in good condition, with little weathering, Photo No. 32.

Two wet areas occur at the downstream toe of the dike, where the embankment is highest. The extent of the wet areas are defined by grass which has not been mowed, as shown in Photos No. 29 and 30. No flow was observed into or from the wet areas, and free water in small puddles was clear. It is understood that these areas are wet seasonally, and are apparently not related to reservoir water levels. Water was observed to be seeping through the asphalt concrete lining for a drainage ditch which runs parallel to the dike toe downstream of the wet area. This condition is shown in Photo No. 31. Water flows into a drop inlet shown near the center of Photo No. 30.

The roadway and stone walls across the crest of the embankment, Photo No. 27, are in excellent condition. Similar to Winsor Dam, Goodnough Dike was constructed with a camber, raising the crest above the nominal design grade at El. 550, to allow for settlement.

Settlement of the crest has been monitored at seven observation points, the protective casing for one of which is shown in Photo No. 33. The MDC drawing which summarizes embankment settlements from 1939 to the last reading on 26 June 1973, is included in Appendix B-70.

The embankment at his highest point between Sta. 17 and 20, settled about 1.2 ft. between 1939 and 1952 (13 years). In the following 21 years to 1973, an additional 0.4 and 0.3 ft. of settlement occurred at Sta. 17 and Sta. 20, respectively. Settlement at Sta. 17 was about 0.1 ft. greater than would have been expected from data available through 1952.

E. Quabbin Reservoir Area. The reservoir was not examined except for areas near Winsor Dam and Goodnough Dike. However, the Quabbin reservation and watershed are generally wooded. In this terrain, it is highly unlikely that landslides into the reservoir and/or surface erosion would be significant and would in any way endanger the safety of the structures.

F. Downstream Channels. The river channel immediately downstream of discharge channels from the Winsor Dam power house and Quabbin Spillway is the natural bed of the Swift River.

For several hundred yards downstream of Goodnough Dike, the former Beaver Brook channel is flat, wide and swampy with ponded water. Few trees have grown in this environment.

3.2 EVALUATION

Based on a visual examination of Winsor Dam, Quabbin Spillway and Goodnough Dike, the projects are well-maintained and in excellent to good condition. Minor deficiencies which have been observed should not have a serious effect on the performance or safety of the structures.

IV. OPERATIONAL PROCEDURES

4.1 PROCEDURES

The primary purpose of the three projects is to impound and store runoff in Quabbin Reservoir for the water supply of the Metropolitan Boston area. A degree of control of the reservoir water surface elevation can be exercised by discharging water through a turbine generator at the power house and/or a 33-inch bypass line into the Swift River. The law requires that the MDC release a minimum of 20 MGD to the Swift River. The reservoir level is also effected by the flow delivered to the Quabbin and Chicopee Aqueducts. Other than these controls, the maximum reservoir level is controlled by Quabbin Spillway weir crest at El. 530.0. (Flashboards can be removed from a 34 ft. -8 in. length of the weir which would lower the water level to El. 528.0.)

4.2 MAINTENANCE OF DAM

The Winsor Dam and Goodnough Dike embankments are regularly maintained by MDC field forces based at Winsor Dam in Belcher-town, MA.

4.3 MAINTENANCE OF OPERATING FACILITIES

The equipment is well maintained and operated routinely, as required, to deliver water to the aqueducts, generate power and meet discharge requirements to the Swift River. Other equipment is test-operated at set intervals. No equipment was specifically operated during the visual examination on 29 June. The equipment was reported to be in good operational condition. It was also reported that a problem had existed with control valve cavitation at the power house and that orifice plates have been installed.

4.4 WARNING SYSTEMS IN EFFECT

There is no formal warning system in effect in the event of a failure or partial failure of the structures. The operations staff indicated that they do have radio communication capabilities and in case of difficulties, would warn the nearby civil defense center and the Metropolitan District Commission Headquarters.

4.5 EVALUATION

The operational procedures and dam and dike maintenance are satisfactory.

For a project of this size and importance, where a failure would cause major loss of life and property damage, a formal emergency preparedness plan and warning system should be adopted.

V. HYDRAULIC/HYDROLOGIC

5.1 EVALUATION OF FEATURES

A. Design Data. The Quabbin Reservoir was created in the 1930's by the MDC with the construction of Winsor Dam, Quabbin Spillway and Goodnough Dike. Proposed construction drawings for the facilities were found but only limited hydraulic/hydrologic design parameters have been located.

Hydraulic/hydrologic information contained in the July 1935 BSCE Journal, Vol. XXII, No. 3, indicates that a runoff of 12 inches in 24 hours would result in a spillway discharge of 9,000 cfs. The same article states that the spillway approach channel was designed to convey 15,000 cfs, at which point the reservoir water surface would be El. 536.0 and the auxiliary spillway would begin discharging.

The size classification of the project is "large" as the height is greater than 150 ft. and the storage is 412 billion gallons (1,264,000 acre-feet). Since the estimated loss of life in the event of failure had been previously estimated to be between 2 and 300 persons, the hazard potential classification is "high". Consequently, the recommended test flood is the probable maximum flood (PMF).

B. Experience Data. The peak inflow PMF was estimated by using the peak flow rate for rolling terrain, as developed by the Corps of Engineers, New England Division, and developing a unit hydrograph based on the September 1938 flood on the East Branch Swift River near Hardwick, Massachusetts, for the land portion of the drainage area which is approximately 146 square miles. To this inflow (peak rate of 134,000 cfs), the PMF resulting from 23 inches of rainfall in 6 hours was distributed over the area of the reservoir and added. The resulting peak inflow was determined to be 226,800 cfs. This peak inflow was routed through the reservoir and the PMF outflow was determined to be 15,200 cfs using both the main and auxiliary spillways. To date, the maximum spillway discharge has been approximately 1600 cfs.

C. Visual observations. No modifications have been made to the Quabbin Spillway since it was constructed in the 1930's. Two feet of flashboards were in place on the 34 ft. -8 in. section of spillway at the time of the inspection and the water surface elevation was

529.73. The spillway and its associated approach channel appear to be in excellent condition. The left wall of the discharge channel shows signs of weathering with fallen rock on the floor of the channel. However, the slope of the discharge channel at this location is sufficiently steep that the rock debris should not cause any hydraulic problems.

D. Overtopping Potential. The stage-discharge relationship for the spillway utilizes the spillway rating curve developed by the MDC for spillages up to 3 feet, to El. 533.0. Between El. 533.0 and El. 536.0, a straight line interpolation was made recognizing the stated design discharge of 15,000 cfs at a maximum pool of El. 536.0.* Above this level, the auxiliary spillway will pass flows from an extreme flooding event.

Neglecting the capacity of the auxiliary spillway channel, it was determined that the PMF would generate a peak outflow rate of 16,300 cfs which would cause the water level in the reservoir to rise to El. 536.54. Considering the additional capacity afforded by the auxiliary spillway, treating same as a broad-crested weir, the maximum water level in the reservoir is lowered to El. 536.07 (peak outflow equals 15,200 cfs). Therefore, the main spillway in combination with minimal usage of the auxiliary spillway is adequate for the PMF. Since the crest of the dam is approximately 14 ft. above maximum water level, there is no possibility of overtopping.

E. Evaluation. Passage of the PMF by the main spillway with a minor portion of the flow over the auxiliary spillway should offer no flooding problems in the immediate area of the dam. The main spillway discharge channel, which is excavated in rock, has a base width in excess of 30 ft. with bottom slopes no less than 1.0 percent upstream of the arch bridge. Just downstream of the bridge, the channel bottom drops more than 50 ft. in less than 100 ft. to form a cascade while downstream, the discharge channel continues in rock with a base width in excess of 30 ft. with the bottom slope averaging 6.0 percent before flattening and merging with the original streambed of the Swift River. Downstream of this point, the Swift River Channel has ample capacity for the PMF flows from the main and auxiliary spillways as well as any contribution from the power station discharge channel. In conclusion, the spillway and downstream channels are more than adequate to pass the routed PMF as developed in the Guidelines.

* "Design and Progress on Construction of Dams for Quabbin Reservoir" by Stanley M. Dore, Journal of the Boston Society of Civil Engineers, July 1935, Pg. 173.

The estimated peak failure outflow should Quabbin Spillway fail is 13,000 cfs. Since this outflow is less than the test flood, the downstream channels and the Swift River are more than adequate to handle a failure of this structure.

Because of Quabbin Reservoir's vast storage capacity, as well as the height of both the Winsor Dam and Goodnough Dike, a failure of either the dam or dike would result in significant downstream damage as well as loss of life.

If Winsor Dam or Goodnough Dike were to fail, the peak outflows have been estimated (using "Rule of Thumb" guidelines developed by the C. of E.) to be 1,533,000 cfs for Winsor Dam and 958,000 cfs for Goodnough Dike. Since the effects of these flood waves would be experienced for many miles downstream, flood routing is beyond the scope of this investigation. Nevertheless, the following qualitative analysis is presented to indicate the magnitude of the downstream hazard potential.

Failure of Goodnough Dike would result in rapid inundation of Peppers Mill Pond one mile downstream, after which the flood wave would likely scour out a section of Route 9 to convey the flows which would be greatly in excess of the capacity of the existing 12 ft. wide by 9 ft. high multi-plate arch which carries Beaver Brook beneath Route 9. About 2 miles downstream of Goodnough Dike, the flood wave would enter Beaver Lake where it would be dissipated somewhat, but not before damage to houses and cottages around Beaver Lake and possible loss of life. Downstream of Beaver Lake, the flood wave would flow through a swampy area before the confluence with the Ware River about one mile downstream of Beaver Lake.

Failure of the Winsor Dam would produce a flood wave which would first scour out a section of Route 9, since the existing Swift River bridge opening would not be adequate to convey the flood flows. The State Fish Hatchery about one-half mile downstream of Route 9 would next be affected including a few houses along the river valley in the immediate area. About 4 miles downstream of Route 9, the flood wave would reach the village of Bondsville in the town of Palmer. The flood flow would pass both the upper and lower dams in Bondsville and for the most part not affect too many homes here as most of them are 20-40 ft. above the river bed. More damage would likely occur just downstream of where the Swift River meets the Ware River in the village of Three Rivers, where some of the housing is relatively low with respect to the river bed.

VI. STRUCTURAL STABILITY

6.1 EVALUATION OF EMBANKMENT STRUCTURAL STABILITY

A. Visual Observations. There was no visual evidence of embankment instability at either Winsor Dam or Goodnough Dike during the site of examination on 29 June 1978. Seepage at Goodnough Dike, as evident by wet areas at the toe of the dike, is not considered a potential hazard to the stability of the downstream slope.

B. Design and Construction Data. MDC drawings are available which show the design cross-sections for the dam and dike, both of which are full hydraulic fill structures. However, no design criteria for embankment stability or calculations are available. Furthermore, there are no construction records available which define soil properties.

A theoretical analysis of the structural stability of the dam and dike embankments was not possible due to lack of pertinent design and construction data. Nevertheless, the downstream slopes of 2 horizontal to 1 vertical above El. 499 and 2.5 to 1 below that grade, are considered reasonable for a hydraulic fill embankment of this height.

C. Operating Records. Records of crest settlement are available from surveys on settlement pins located at the top of light riprap on the upstream slope. The results of settlement observations have been discussed in Section III and are shown on figures in Appendix B-69 and B-70.

Generally, crest settlements are reasonable, in particular the time-settlement relationship of one point to another, and do not suggest any embankment instability. However, the settlement at Sta. 17 at Goodnough Dike, from 1952 to 1973, was about 0.1 ft. greater than would be expected. This result may be due to a survey error or to a local movement of the monument. While it does not suggest embankment instability in this area, it should be checked.

D. Post-Construction Changes. It is understood that there have been no significant post-construction changes to the dam and dike embankments. To accommodate differential settlement, some reconstruction, including repaving and pointing, has been undertaken where the Winsor Dam embankment interfaces with the intake structure.

E. Seismic Stability. The Quabbin Reservoir projects are located in Seismic Zone 2. According to C. of E. guidelines, projects in this zone are "assumed to present no hazard from earthquake provided static stability conditions are satisfied and conventional safety margins exist." At the present time, it is not known whether conventional safety factors exist for static stability analyses.

Because of the importance of these structures for water supply to the Greater Boston area, because of the high hazard potential in the event of a failure, and because the embankments are hydraulic fill with relatively steep slopes, a detailed investigation of embankment stability under static and earthquake loading is recommended.

6.2 EVALUATION OF STRUCTURAL STABILITY, QUABBIN SPILLWAY

A. Visual Observations. No visual evidence was noted that would indicate a structural stability problem with the masonry spillway. One small pressure leak was observed during the inspection which should be attended to to minimize the uplift force on the weir.

B. Design and Construction Data. Design data in the form of record drawings for the spillway and construction data in the form of construction photographs are available. Utilizing these data, a stability check was performed on the spillway weir, and the structural design was found to be adequate for the PMF.

C. Operation Records. Operation records in the form of water surface elevation since the time of construction are available.

D. Post-Construction Changes. A comparison of the visual appearance of the spillway weir and the record drawings indicate that no major modifications have been made to the spillway.

E. Seismic Stability. The spillway weir is deemed adequate for seismic stability in that it is located in a Zone 2 region and is adequate for normal loadings up to and including a probable maximum flood.

VII. ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES

7.1 ASSESSMENT

A. Condition. The visual examination of Winsor Dam, Quabbin Spillway and Goodnough Dike, and review of available documents, did not reveal any evidence of failure or conditions which would warrant urgent remedial treatment. The projects are well maintained and are in excellent to good condition.

The Quabbin Spillway and auxiliary spillway at Winsor Dam are adequate to safely pass the the test flood, estimated to be 16,300 cfs, without overtopping the dam. The estimated maximum discharge since the project was completed 40 years ago, was 1600 cfs in April 1953.

B. Adequacy of Information. Generally, available drawings and other information were adequate for this Phase I Investigation. However, there is insufficient information to evaluate embankment stability under static loads and forces due to earthquakes.

C. Urgency. The recommendations for additional investigations and remedial measures outlined in Sections 7.2 and 7.3, respectively, should be undertaken by the MDC within 24 months after receipt of this Phase I Inspection Report.

D. Need for Additional Investigation. Additional investigations should be performed by the Owner as outlined in Section 7.2.

7.2 RECOMMENDATIONS

1. An investigation to assess the stability of the downstream slopes for both Winsor Dam and Goodnough Dike, under static and earthquake loading. The assessment should include the potential for a failure and/or excessive movement during a seismic event. To perform the required analyses, test borings and detailed laboratory testing will be required to provide data.
2. A new level survey on seven settlement observation points at Goodnough Dike, in particular to check the 1973 data at

Sta. 17. If the survey indicates a continued rate of settlement greater than at adjacent piers, consideration should be given to expanding the study to investigate the cause of greater subsidence and the area affects.

7.3 REMEDIAL MEASURES

A. Alternatives. Not applicable.

B. Operating and Maintenance Procedures. The following remedial work should be undertaken by the MDC to correct deficiencies noted during the visual examination:

1. Repair the lining of the former diversion tunnel at Winsor Dam. While the cracks and leakage in this tunnel pose no threat to the dam itself, a collapse of the tunnel roof could cause the rupture of an outlet conduit and reduce the control capabilities of the reservoir level.
2. Repoint the Quabbin Spillway weir masonry to maintain the structure in good condition.
3. Periodically remove brush, saplings and rockfalls from the spillway discharge pool and discharge channel.
4. Due to the size of the project and the "high" hazard potential classification, the MDC should develop a formal emergency preparedness plan and warning system, in cooperation with local officials in communities downstream of the project.
5. Make periodic visual observations of wet areas downstream of Goodnough Dike, noting carefully the extent of the wet area, evidence of active seepage into the area and related information for correlation with rainfall, snowmelt, reservoir level, etc. The objective of this activity will be to determine whether the wet areas are related to reservoir stage or are merely surface manifestations of seasonal effects of rainfall, etc.

6. Repoint the lower courses of the Intake Structure stone masonry exterior walls.

7. Fill animal burrow holes on upper berm of Winsor Dam near right abutement.

APPENDIX A
INSPECTION TEAM ORGANIZATION AND CHECK LIST

	<u>Page No.</u>
<u>VISUAL INSPECTION PARTY ORGANIZATION</u>	1
<u>VISUAL INSPECTION CHECK LIST</u>	
Winsor Dam Embankment	2
Outlet Works - Control Building	3
Outlet Works - Conduit	3
Outlet Works - Outlet Structure (Power House) and Outlet Channel	4
Auxiliary Spillway at Winsor Dam	4
Quabbin Spillway - Spillway Weir, Approach and Discharge Channels	6
Goodnough Dike Embankment	8

VISUAL INSPECTION PARTY ORGANIZATION

NATIONAL DAM INSPECTION PROGRAM

Dam: Quabbin Reservoir: Winsor Dam, Quabbin Spillway
and Goodnough Dike

Date: 29 June 1978

Time: 8:30 a.m. to 5:00 p.m.

Weather: Clear to partly cloudy, hot

Water Surface Elevation Upstream: El. 529.73 (B. C. B. Datum)

Stream Flow: Not applicable

Inspection Party:

Harl P. Aldrich, Jr.	- Soils
Haley & Aldrich, Inc.	
Allen W. Hatheway	- Geology
Haley & Aldrich, Inc.	
Roger H. Wood	- Structural
Camp, Dresser & McKee, Inc.	
Charles E. Fuller	- Hydraulic/Hydrologic
Camp, Dresser & McKee, Inc.	
Charles Loveridge	- Mechanical/Electrical
Camp, Dresser & McKee, Inc.	

Present During Inspection:

Harold E. Mellin, Jr., M.D. C.
David Ashendon, M.D. C.
Harold Willey, M.D. C.

**VISUAL INSPECTION CHECK LIST
NATIONAL DAM INSPECTION PROGRAM**

DAM: Quabbin Reservoir: Winsor Dam DATE: 29 June 78

AREA EVALUATED	CONDITION
<u>WINSOR DAM EMBANKMENT</u>	
Crest Elevation	Originally, approximately El. 551 to El. 553 to allow for settlement
Current Pool Elevation	El. 529.73 (B. C. B. Datum)
Maximum Impoundment to Date	El. 531.03 on April 18, 1953
Surface Cracks	None observed
Pavement Condition	Very good; minor random transverse cracks in asphalt concrete
Movement or Settlement of Crest	None observed (see text for crest settlement data)
Lateral Movement	None observed
Vertical Alignment	Excellent
Horizontal Alignment	Excellent
Condition at Abutment and at Concrete Structures	Approximately 6 to 8 in. of embankment settlement adjacent to intake structure is visible
Indications of Movement of Structural Items on Slopes	No structural items on slopes. However, stone wall adjacent to intake structure has moved laterally and has settled (see photographs)
Trespassing on Slopes	Frequent, no restrictions on downstream grass slope
Animal Burrows in Embankment	Several noted on upper berm near right abutment
Vegetation on Embankment	Grass in good condition, mowed recently
Sloughing or Erosion of Slopes or Abutments	None observed of any significance
Rock Slope Protection - Riprap Failures	Light dumped riprap on upstream slope above berm, heavy riprap below berm; irregular but in good condition; no failures observed
Unusual Movement or Cracking at or near Toes	None observed
Unusual Embankment or Downstream Seepage	None observed
Piping or Boils	None observed
Foundation Drainage Features	None

FILE NO. 4160

HALEY & ALDRICH, INC.
CAMBRIDGE, MASSACHUSETTS

APPENDIX A-2

**VISUAL INSPECTION CHECK LIST
NATIONAL DAM INSPECTION PROGRAM**

DAM: Quabbin Reservoir: Winsor Dam DATE: 29 June 78

AREA EVALUATED	CONDITION
<p>Toe Drains Instrumentation Systems</p>	<p>None Eight "pins" for measuring settlement of crest of dam (see text) Two abandoned (lost) observation wells</p>
<p><u>OUTLET WORKS - CONTROL BUILDING</u></p>	
<p>a. <u>Concrete and Structural</u></p>	
<p>General Condition Condition of Joints</p>	<p>Good to excellent Some mortar missing in exterior joints at riprap level</p>
<p>Spalling Visible Reinforcing Rusting or Staining Any Seepage or Efflorescence</p>	<p>None noted None noted Incidental rust on interior steel columns Efflorescence at bottom courses of block</p>
<p>Joint Alignment Unusual Seepage or Leaks in Gate Chamber Cracks</p>	<p>Good Not observable No major cracks noted</p>
<p>b. <u>Mechanical and Electrical</u></p>	
<p>Equipment reported to be in operable condition, no apparent deficiencies observed</p>	
<p><u>OUTLET WORKS - CONDUIT</u></p>	
<p>General Condition</p>	<p>Mainly not observable, underground; top of 68-in. conduit exposed in former stream diversion tunnel; tunnel not illuminated Former stream diversion tunnel lining contains numerous cracks; moderate leak in roof of tunnel 450 ft. from power house at apparently old patch and cracks.</p>

FILE NO. 4160

**VISUAL INSPECTION CHECK LIST
NATIONAL DAM INSPECTION PROGRAM**

DAM: Quabbin Reservoir: Winsor Dam DATE: 29 June 78

AREA EVALUATED	CONDITION
<p><u>OUTLET WORKS - OUTLET STRUCTURE (POWER HOUSE) AND OUTLET CHANNEL</u></p> <p>a. <u>General Condition of Concrete and Masonry</u></p> <p>Rust or Staining Spalling Visible Reinforcing Any Seepage or Efflorescence</p> <p>Condition at Joints</p> <p>b. <u>Electrical-Mechanical</u></p> <p>c. <u>Channel</u></p> <p>Loose Rock or Trees Overhanging Channel Condition of Discharge Channel</p>	<p>Good condition</p> <p>Underside of roof stained Shrinkage cracks in bond beam below roof None observed Efflorescence present lower portion of walls lower floor. Water on floor from unknown source</p> <p>Good</p> <p>Equipment reported to be in operable condition - no apparent deficiencies observed. Reported cavitation, problem with control valves corrected by orifice plates</p> <p>A few trees overhanging channel</p> <p>Good - riprap</p>
<p><u>AUXILIARY SPILLWAY AT WINSOR DAM</u></p> <p>a. <u>Channel Upstream of Weir</u></p> <p>General Condition Floor of Channel</p>	<p>Excellent</p> <p>Flat, covered with grass mowed recently; three trees; some brush at entrance to channel; gravel road crossing channel floor just upstream of weir creates minor obstruction to flow</p>

FILE NO. 4160

**VISUAL INSPECTION CHECK LIST
NATIONAL DAM INSPECTION PROGRAM**

DAM: Quabbin Reservoir: Winsor Dam DATE: 29 June 78

AREA EVALUATED	CONDITION
b. <u>Weir</u> Crest General Condition	El. 536 Only crest of circular weir visible; crest topped by large rectangular granite stones, typically 4 to 5 ft. long and 3 ft. wide; good condition
c. <u>Channel Downstream of Weir</u>	Grass lined then wooded; cross-country flow

FILE NO. 4180

HALEY & ALDRICH, INC.
CAMBRIDGE, MASSACHUSETTS

APPENDIX A-5

**VISUAL INSPECTION CHECK LIST
NATIONAL DAM INSPECTION PROGRAM**

DAM: Quabbin Reservoir: Quabbin Spillway DATE: 29 June 78

AREA EVALUATED	CONDITION
<u>QUABBIN SPILLWAY - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS</u>	
<u>a. Approach Channel</u>	
General Condition	Good
Loose Rock Overhanging Channel	None of any significance observed
Trees Overhanging Channel	A few small trees overhanging channel, but not significant
Floor of Approach Channel	Not observable
<u>b. Weir and Training Walls</u>	
General Condition of Masonry Joints	Good; several spots of vegetation in upper joint; some mortar missing especially in lower portion; bottom joint eroded
Rust or Staining Cracks	None observed
Any Visible Reinforcing	Vertical cracks at each end and center of highest portion of weir
Any Seepage or Efflorescence	None observed
Drain Holes	Seepage observed at highest joint; trace of moisture along bottom of high portion; seepage at end of high weir portion where it abuts rock; efflorescence present in high portion of weir - at junction with rock, mid-height and lower portions of weir
Drain Holes	None observed
<u>c. Service Bridge</u>	
General Condition	Good
Walkway	Good condition
Guides	Excellent condition
Flashboards	Good condition

FILE NO. 4160

HALEY & ALDRICH, INC.
CAMBRIDGE, MASSACHUSETTS

APPENDIX A-6

**VISUAL INSPECTION CHECK LIST
NATIONAL DAM INSPECTION PROGRAM**

DAM: Quabbin Reservoir: Quabbin Spillway DATE: 29 June 78

AREA EVALUATED	CONDITION
<p><u>d. Discharge Channel</u></p> <p>General Condition</p> <p>Loose Rock Overhanging Channel</p> <p>Trees Overhanging Channel</p> <p>Floor of Channel</p> <p>Other Obstructions</p>	<p>Good</p> <p>Evidence of prior rock falls from left face (see text)</p> <p>Young trees at top of rock walls; few in channel but not significant</p> <p>Irregular bedrock surface; some blocks of rock from rock cuts, especially at entrance to channel</p> <p>Some brush growth</p>

FILE NO. 4160

HALEY & ALDRICH, INC.
CAMBRIDGE, MASSACHUSETTS

APPENDIX A-7

**VISUAL INSPECTION CHECK LIST
NATIONAL DAM INSPECTION PROGRAM**

DAM: Quabbin Reservoir: Goodnough Dike DATE: 29 June 78

AREA EVALUATED	CONDITION
<u>GOODNOUGH DIKE</u> <u>EMBANKMENT</u>	
Crest Elevation	Originally, approximately El. 551 to El. 553 to allow for settlement
Current Pool Elevation	El. 529.73 (B. C. B. Datum)
Maximum Impoundment to Date	El. 531.03 on April 18, 1953
Surface Cracks	None observed
Pavement Condition	Excellent; a few minor random transverse cracks in asphalt concrete
Movement or Settlement of Crest	None observed (See text for crest settlement data)
Lateral Movement	None observed
Vertical Alignment	Excellent
Horizontal Alignment	Excellent
Condition at Abutment and at Concrete Structures	Good (no concrete structures); dike abuts rock at both ends
Indications of Movement of Structural Items on Slopes	No structural items on slopes
Trespassing on Slopes	Frequent, no restrictions on downstream grass slope
Animal Burrows in Embankment	None observed
Vegetation on Embankment	Grass in good condition, a few small bare areas; grass mowed recently
Sloughing or Erosion of Slopes or Abutments	None observed of any significance
Rock Slope Protection - Riprap Failures	Light dumped riprap on upstream slope above berm, heavy riprap below berm; irregular but in good condition; no failures observed
Unusual Movement or Cracking at or near Toes	None observed
Unusual Embankment or Downstream Seepage	Two unmowed areas at downstream toe of embankment; water clear; no flow observed (See photos)
Piping or Boils	None observed
Foundation Drainage Features	None

FILE NO. 4160

**VISUAL INSPECTION CHECK LIST
NATIONAL DAM INSPECTION PROGRAM**

DAM: Quabbin Reservoir: Goodnough Dike DATE: 29 June 78

AREA EVALUATED	CONDITION
Toe Drains Instrumentation Systems	None Seven "pins" for measuring settlement of crest of dike (See text) One abandoned (lost) observation well

FILE NO. 4160

HALEY & ALDRICH, INC.
CAMBRIDGE, MASSACHUSETTS

APPENDIX A-9

APPENDIX B
LIST OF AVAILABLE DOCUMENTS AND
 PRIOR INSPECTION REPORTS

Page No.

LIST OF AVAILABLE DOCUMENTS

Winsor Dam	1
Quabbin Spillway	3
Goodnough Dike	4
Quabbin Reservoir Contracts	5

PRIOR INSPECTION REPORTS

Winsor Dam

<u>Date</u>	<u>By</u>	
Undated	Unknown	6
26 February 1974	Mass. Department of Public Works	7
23 March 1976	Mass. Department of Environmental Quality Engineering	21

Quabbin Spillway

<u>Date</u>	<u>By</u>	
Undated	Unknown	25
26 February 1974	Mass. Department of Public Works	26
23 March 1976	Mass. Department of Environmental Quality Engineering	37

Goodnough Dike

<u>Date</u>	<u>By</u>	
Undated	Unknown	43
26 February 1974	Mass. Department of Public Works	44

DRAWINGSPage No.

<u>Sheet</u>	<u>Acc.</u>		
2	24102	Main Dam Embankment General Plan	54
11	4311	Main Dam Core Wall Overburden - Geological Data - Sheet 1	55
12	4311	Main Dam Core Wall Overburden - Geological Data - Sheet 2	56
13	4311	Main Dam Core Wall Overburden Geological Data - Sheet 3	57
4	24104	Main Dam Embankment Profile on Centerline of Main Dam	58
10	24110	Main Dam Embankment Cross Section of Top of Main Dam	59
17	24117	Main Dam Embankment Intake Works - Intakes	60
16	24116	Main Dam Embankment Auxiliary Spillway	61
11	24111	Main Dam Embankment Spillway Channel - Sheet 1	62
12	24112	Main Dam Embankment Spillway Channel - Sheet 2	63
2	23402	Dike Embankment General Plan	64
8	3908	Dike Core Wall Overburden - Geological Data - Sheet 1	65
9	3909	Dike Core Wall Overburden - Geological Data - Sheet 2	66
4	23404	Dike Embankment Profile on Center Line of Dike	67
3	23403	Dike Embankment Typical Cross Sections	68
	17792	Winsor Dam Embankment Settle- ment of the Embankment	69
	17641	Dike Embankment Settlement of the Embankment	70

LIST OF AVAILABLE DOCUMENTS
WINSOR DAM

<u>DOCUMENT</u>	<u>CONTENTS</u>	<u>LOCATION</u>
"Construction of Core Wall at Main Dam", MDC Contract No. 38, Sheet 11, Acc. 4311, 21 December 1934	Overburden and geological data from borings, test pits and exploratory caissons shown on profiles	MDC, 20 Somerset St., Boston, MA (Appendix B-55)
"Construction of Core Wall at Main Dam.", MDC Contract No. 38, Sheet 12, Acc. 4312, 21 December 1934	Overburden and geological data from borings and test pits shown on profiles	MDC, 20 Somerset St., Boston, MA (Appendix B-56)
"Construction of Core Wall at Main Dam", MDC Contract No. 38, Sheet 13, Acc. 4313, 21 December 1934	Overburden and geological data from the three exploratory caissons	MDC, 20 Somerset St., Boston, MA (Appendix B-57)
"Main Dam Embankment", MDC Contract No. 52, Sheet 2, Acc. 24102, 1 June 1936	General plan	MDC, 20 Somerset St., Boston, MA (Appendix B-54)
"Main Dam Embankment", MDC Contract No. 52, Sheet 4, Acc. 24104, 1 June 1936	Profile on centerline of dam	MDC, 20 Somerset St., Boston, MA (Appendix B-58)
"Main Dam Embankment", MDC Contract No. 52, Sheet 10, Acc. 24110, 1 June 1936	Cross-section of top of dam	MDC, 20 Somerset St., Boston, MA (Appendix B-59)

<u>DOCUMENT</u>	<u>CONTENTS</u>	<u>LOCATION</u>
"Main Dam Embankment", MDC Contract No. 52, Sheet 17, Acc. 24117, 1 June 1936	Plan and sections of intake works	MDC, 20 Somerset St., Boston, MA (Appendix B-60)
"Main Dam Embankment", MDC Contract No. 52, Sheet 16, Acc. 24116, 1 June 1936	Plan, profile and sections of auxiliary spillway	MDC, 20 Somerset St., Boston, MA (Appendix B-61)
"Winsor Dam Embankment Settlement", MDC Acc. 17792, 28 October 1940	Settlements of embankment and roadway from 7 July 1939 to 26 June 1973	MDC, 20 Somerset St., Boston, MA (Appendix B-69)

LIST OF AVAILABLE DOCUMENTS
QUABBIN SPILLWAY

<u>DOCUMENT</u>	<u>CONTENTS</u>	<u>LOCATION</u>
"Main Dam Embankment", MDC Contract No. 52, Sheet 2, Acc. 24102, 1 June 1936	General plan showing spillway and Winsor Dam	MDC, 20 Somerset St., Boston, MA (Appendix B-54)
"Main Dam Embankment", MDC Contract No. 52, Sheet 11, Acc. 24111, 1 June 1936	Plan and profile at spillway channel	MDC, 20 Somerset St., Boston, MA (Appendix B-62)
"Main Dam Embankment", MDC Contract No. 52, Sheet 12, Acc. 24112, 1 June 1936	Selected cross-sections through spillway channel	MDC, 20 Somerset St., Boston, MA (Appendix B-63)

LIST OF AVAILABLE DOCUMENTS
GOODNOUGH DIKE

<u>DOCUMENT</u>	<u>CONTENTS</u>	<u>LOCATION</u>
"Construction of Core Wall at Dike", MDC Contract No. 36, Sheet 8, Acc. 3908, 4 November 1932	Overburden and geological data from borings, test pits and the exploratory caisson shown on profiles	MDC, 20 Somerset St., Boston, MA (Appendix B-65)
Construction of Core Wall at Dike", MDC Contract No. 36, Sheet 9, Acc. 3909, 4 November 1932	Overburden and geological data from borings and test pits shown on profiles	MDC, 20 Somerset St., Boston, MA (Appendix B-66)
"Embankment of Dike", MDC Contract No. 50, Sheet 2, Acc. 23402, 1 October 1934	General plan	MDC, 20 Somerset St., Boston, MA (Appendix B-64)
"Embankment of Dike", MDC Contract No. 50, Sheet 4, Acc. 23404, 1 October 1934	Profile on centerline of dike	MDC, 20 Somerset St., Boston, MA (Appendix B-67)
"Embankment of Dike", MDC Contract No. 50, Sheet 3, Acc. 23403, 1 October 1934	Typical cross-sections	MDC, 20 Somerset St., Boston, MA (Appendix B-68)
"Dike Embankment, Settlement of the Embankment", MDC Acc. 17641, 10 October 1939	Settlements of embankment and roadway from 8 December 1936 to 27 June 1973	MDC, 20 Somerset St., Boston, MA (Appendix B-70)

**LIST OF AVAILABLE DOCUMENTS
QUABBIN RESERVOIR CONTRACTS**

The following list is intended as a guide to obtaining additional documents on Winsor Dam, Quabbin Spillway and Goodnough Dike available at the MDC, 20 Somerset St., Boston, MA

Contract No.

2	Borings Swift Dam Site
3	Air Photos, Swift Valley
23	Borings - Belchertown, Enfield, Ware
30	Stream Control Works at Main Dam
32	Constructing Exploratory Caissons
36	Constructing Core Wall at Dike
38	Construction Core Wall at Winsor Dam
45	Explor. by Shovel Cuts - Main Dam and Dike
50	Embankment at Dike
52	Main Dam Embankment
118	Misc. Construction at Winsor Dam and Dike
119	Pylons at Winsor Dam
148	Sale of Power - Winsor Dam
149A	Hydraulic Turbine - Winsor Dam
149B	Generator - Winsor Dam
149C	Switchgear, Bus Reactor, Metering Outfit, Control Panel - Winsor Dam
149D	Transformer - Winsor Dam
149E	Substation - Winsor Dam
149F	Storage Battery and Charging Equipment - Winsor Dam
150	Installation of Power Plant

WINSOR DAM

C. Quabbin Dike, Winsor Dam and Spillway

The grass cover on the embankment forming the dike was noted to be o. k. The toe area of the dry side was in good condition and dry. The road on top of the embankment was in good condition and there was no evidence of settlement, sunken areas or cracks. The rock fill slope on the reservoir side of the dike is in good condition. Water in storage was observed to be quite low but appeared to be higher in elevation than at the time of the previous inspection.

The main dam, Winsor Dam, was noted to be in good condition. The turf cover on the downstream slope was good. Some areas apparently are being re-loamed, treated and seeded. The toe area of this main dam was dry.

The rock filled portion of the main dam on the reservoir side was in good condition. The road across the dam was o. k.

The spillway structure was again observed to be completely dry. The spillway has not been wet for many years. However, the level of water observed this year is at the entrance to the spillway forebay and thus is the highest noted in many years. The stone masonry of the spillway and the crest were observed to be o. k.

In the opinion of the undersigned, the dam, the dike and spillway are in the same good condition as previously reported, and are safe.

OK
7/26

INSPECTION REPORT - DAMS AND RESERVOIRS

1. LOCATION:
 CITY/Town Ware County Rampshire Dam No. 2-8-309-1A
 Name of Dam Quabbin "Winsor" Dam
 Mass. Sect.
 Topo Sheet No. 14D Coordinates: N 469,000 E 373,500
 Inspected by: R. C. Sells, P.E. On Feb. 26, 1974 Date 1970
 See also Quabbin Spillway No. 2-8-309-1B & Goodnough Dike No. 2-8-309-1C

2. OWNER/S: As of November 1972
 per: Assessors X, Reg. of Deeds _____, Prev. Insp. _____, Per. Contact X.

1. Metropolitan District Commission, Winsor Dam - Ware Rd., Belchertown, Mass.
 Name _____ St. & No. _____ City/Town _____ State _____ Tel. No. _____
2. _____
 Name _____ St. & No. _____ City/Town _____ State _____ Tel. No. _____
3. _____
 Name _____ St. & No. _____ City/Town _____ State _____ Tel. No. _____

3. CARETAKER: (if any) e.g. superintendent, plant manager, appointed by
 absentee owner, appointed by multi owners.
Mr. John W. Copithorne, Supt.
Quabbin Reservoir, M.D.C. Winsor Dam, Ware Rd., Belchertown, Mass. 413-323-6071
 Name _____ St. & No. _____ City/Town _____ State _____ Tel. No. _____

4. DATA:
 No. of Pictures Taken None, Sketches See description of Dam.
 Plans, Where In M.D.C. office at Quabbin.

5. DEGREE OF HAZARD: (if dam should fail completely)*
 1. Minor _____ 3. Severe _____
 2. Moderate _____ 4. Disastrous X
 Comments: Assuming complete failure

*This rating may change as land use changes (future development).

See also 2A

6. OUTLETS: OUTLET CONTROLS AND DRAWDOWN

Intake structure at southwesterly end of dam for 48" No. 1 Location and Type: diam. and 68" diam. conduits in outlet tunnel

Controls Yes, TYPE: Gate valve and slide valve

Automatic . Manual X. Operative Yes X, No .

Comments: At time of inspection automatic screens being installed

No. 2 Location and Type: See Quabbin Spillway - Dam No. 2-8-302-1B

Controls Yes, Type: Flashboards

Automatic . Manual X. Operative Yes X, No .

Comments: Spillway has not functioned as yet

No. 3 Location and Type: Auxiliary spillway 1200 ft. southwesterly of end of dam.

Controls No, Type:

Automatic . Manual . Operative Yes , No .

Comments: Crest of auxiliary spillway 6 ft. above reservoir flow line or about 17 ft. below top embankment

Drawdowns present Yes X, No . Operative Yes X, No .

Comments: See No. 1 above - lower intake

7. DAM UPSTREAM FACE: Slope Varies - 1 1/2:1 to 3:1, Depth Water at Dam 140 ft. ±

Material: Turf . Brush & Trees . Rock fill X. Masonry . Wood .
10' thick

Other 3 berms on slope

Condition: 1. Good X. 3. Major Repairs .

2. Minor Repairs . 4. Urgent Repairs .

Comments: For details of slope see sketches - sheet #2

8. DAM DOWNSTREAM FACE: Slope 2:1 to 2 3/4:1

Material: Turf X. Brush & Trees . Rock Fill . Masonry . Wood .

Other 2 berms on slope. Slope drainage installed

Condition: 1. Good X. 3. Major Repairs .

2. Minor Repairs . 4. Urgent Repairs .

Comments: Access road to powerhouse; outlet structure and beginning of Chicopee aqueduct crosses slope

9. EMERGENCY SPILLWAY: Available Yes, Needed No.

Height Above Normal Water 6 Ft. auxiliary spillway
Width 200 Ft. Height 3.4 Ft. Material Earth channel Masonry weir
Condition: 1. Good X 3. Major Repairs _____
2. Minor Repairs _____ 4. Urgent Repairs _____

Comments: See sheet 6 of sketches - Note: See also Quabbin spillway,
Dam No. 2-8-309-1B

10. WATER LEVEL AT TIME OF INSPECTION: 75 Ft. Above _____ Below _____

Top Dam X P.L. Principal Spillway _____
Other _____
Normal Freeboard 23 Ft.

11. SUMMARY OF DEFICIENCIES NOTED:

Growth (Trees and Brush) on Embankment None
Animal Burrows and Washouts None seen
Damage to Slopes or Top of Dam None. Note precise levels in 1970 show embankment has settled 1.50 ft.
Cracked or Damaged Masonry None seen
Evidence of Seepage Minor seepage - handled by drainage system
Evidence of Piping None seen
Leaks None seen
Erosion None noted
Trash and/or Debris Impeding Flow None
Clogged or Blocked Spillway No. - Note automatic screening equipment being installed at time of inspection.
Other _____

12. OVERALL CONDITION:

1. Safe X
2. Minor repairs needed _____
3. Conditionally safe - major repairs needed _____
4. Unsafe _____
5. Reservoir impoundment no longer exists (explain)
Recommend removal from inspection list _____

13. REMARKS AND RECOMMENDATIONS: (Fully Explain)

This dam across the Swift River forms the Gwabbin Reservoir. It is an earth embankment 2600 feet long and over 155 feet high. There is a concrete caisson core wall with its top somewhere near the original ground line which extends to bedrock located on the centerline of the embankment. The earth embankment is a full hydraulic fill structure with a riprap shell on the upstream face and with a loam and turf surface on the downstream slope.

An examination of the embankment, the intake structure, and the outlet structure or powerhouse found no visible defects. The examination included viewing the interior of the outlet tunnel and viewing the interior of one of the intake structure wells in an unwatered condition. At the time of the inspection automatic screening devices were being installed in the intake wells and as a part of this work the bearing brackets for the gate operating shafts were being rehabilitated.

Core drillings of the concrete in the interior of the intake wall obtained from the drilling of anchor bolt holes for the installation of the screening device showed the concrete to be in excellent condition.

The two observation wells originally installed in this dam are no longer usable and no information on recent observation was available. Precise levels were taken on the top of the dam at frequent intervals until 1957 and again in 1973. These showed a settlement of about 1½ feet in 1973 with about a third of the total settlement occurring between 1957 and 1973, a period when the reservoir was at a relatively low level. This dam was originally designed with a 2 foot camber to allow for settlement.

Mr. Mallin, the Assistant Superintendent, accompanied us on our inspection.

RCS/js/vk

DESCRIPTION OF DAM:

DISTRICT 2

Submitted by E. C. Sells, P.E. Dam No. 2-8-309-1A

Date February 26, 1974 Kingstown Ware

Name of Dam Quabbin "Winsor" Dam

See also Dam No. 2-8-309-1B - Quabbin Spillway & No. 2-8-309-1C Goodnough Dike

1. Location: Topo Sheet No. 14D Mass. Rect. Coordinates N 460,000 E 351,500

Provide $8\frac{1}{2}$ " x 11" in clear copy of topo map with location of Dam clearly indicated.

Access from Ware Rd. "Rte. 9" about 2 1/2 mi. easterly from Junction with Rte. 21 - About 2500 ft. (1/4 mile) northerly from Rte. 9 on Winsor Dam Rd. - road goes over da-

2. Year built 1936 - 38 Year/s of subsequent repairs 1970

3. Purpose of Dam: Water Supply I Recreational _____
Flood Control _____ Irrigation _____ Other _____

4. Drainage Area: 186 sq. mi. plus limited diversion from Ware River watershed of 98 sq. mi.
Type: City, Bus. & Ind. _____ Dense Res. _____ Suburban _____ Rural, Farm 15%
Wood & Scrub Land 85% Slope: Steep 15% Med. 75% Slight 10%

5. Normal Ponding Area: 38.6 sq. mi. Acres; Ave. Depth _____
24,704 Impoundment: 412 billion gals.; Max. water depth 150 ft.
Silted in: Yes _____ No _____ approx. Amount Storage Area Unknown

6. No. and type of dwellings located adjacent to pond or reservoir _____
i.e. summer homes etc. Only residences of operating personnel

7. Dimensions of Dam: Length 2500 ft. Max. Height 155 ft.
Freeboard 23 to top embankment when full
Slopes: Upstream Face Varies 1 1/2 to 1 to 3/4 or at crest of spillway
Downstream Face Varies 2: to 2 3/4:1 turf
Width across top 3 3/4 - paved roadway
See sketches attached.

Dam No. 2-8-309-1A 4

8.

Classification of Dam by Material:

Earth X Conc. Masonry _____ Stone Masonry _____
Hydraulic fill embankment _____
Timber _____ Rockfill _____ Other Concrete caisson core wall

8a.

Dam Type: Gravity X Straight y Curved, Arched _____ Other Slight curve
Embankment _____ at east end
Overflow _____ Non-overflow X

9.

A. Description of present land usage downstream of dam:

90 % rural; 10 % within developed villages of Bondsville & Three Rivers

B. Is there a storage area or flood plain downstream of dam which could accommodate the impoundment in the event of a complete dam failure? Yes _____ No X

C. Character Downstream Valley: Narrow X Wide _____ Developed 10%
Rural 90% Urban _____

10.

Risk to life and property in event of complete failure. *See note below.

No. of people Say 2 - 300 before Chicopee River

No. of homes 30+ houses before villages of Bondsville & Three Rivers - say 2 - 300 homes before Chicopee River

No. of businesses Numerous in villages

No. of industries Several light manufacturing plants
Type _____

No. of utilities 4 Type Water supply - pole lines for telephone & electric plus electrical power plant & transmission lines

Railroads Boston & Maine & Vermont Central R. R.

Other dams Bondsville Upper Dam No. 3-7-227-11 & Bondsville Lower Dam No. 3-7-227-12

Other State Fish Hatchery - numerous town highways and bridges and Route 9 State Highway

11.


Attach sketch of dam to this form showing section and plan on 8 1/2" x 11" sheet.

* Note: Risk to life and property only along Swift River considered. Damage is likely on Chicopee River, also.


RCS/vk
attachments
Locus Plan
Sketches

DAF NO 2-B-309-1A
QUABBIN III "WINSON" DAM

QUABBIN RESERVOIR



TEST UNIT GATED
FROM SOUTHWEST
CORNER OF DAM
DRAIN BASIN




"X" SECTION AT STATION 20+00 APPROX. SCALE 1/4" = 1'

X SECTION 'A'

FROM SHEET 3
 CONTRACT M52 DRAWINGS
 DATED JUNE 1, 1936

DAM NO 2-8-3091A
 QUABBIN "WINSOR" DAM

SHEETS OF C




X SECTION THRU INTAKE & STRAIGHT CONTROL TUNNEL
Y SECTION "BB"

FROM SHEET M 3
CONTRACT M 2
DATED JUNE 1, 1936

DAM NO 2-7-309-1 AM
QUABBIN "WINSOCK" DAM

SHEET 1 OF 4




APPROX SCALE: Horiz 1" = 300'
Vert. 1" = 80'

PROFILE ON CENTERLINE WINSOR DAM


FROM SHEET 4,
CONTRACT No 62
DATED JUNE 1, 1936

DAM NO2-B-309-1A
QUAEDIN "WINSOR" DAM

SHEET 5 OF 6



HORIZONTAL SECTION
THROUGH OUTLET STRUCTURE
POWER HOUSE & OUTLET
END TUNNEL
APPROX SCALE 1"=20'




'C-C' SECTION THROUGH
OUTLET TUNNEL
APPROX SCALE 1"=6'

TAKEN FROM SHEET 2 B
CONTRACT NO. 52 DRAWING
DATE: JUNE 1, 1936


DAM NO 2-B-300-1A
QUABBIN "WINSOR" DAM

DAH NO 2-13-309-1A
 QUARBIN WINSOLE DAH

SHEET C OF C




PLAN



FROM CONCEPT DESIGN PLANS
 SHEET C OF C
 SKETCHES OF AUXILIARY
 STRUCTURES

X SECTION AA

X SECTION CC



City
of
Worcester

INSPECTION REPORT - DAMS AND RESERVOIRS

1. LOCATION:

City/Town Ware County Massachusetts Dam No. 2-4-309-1A

Name of Dam Gumbin "Winsor Dam"

Mass. Sect.

Topo Sheet No. 140 Coordinates: N 469,000 E 371,500

Inspected by: Harold T. Shumway Date On March 23, 1976 Last Inspection 2-26-74

See also Gumbin Spillway No. 2-4-309-1B and Goodrich Dike No. 2-4-309-1C

2.

OWNER/S: As of March 23, 1976

per: Assessors _____, Reg. of Deeds _____, Prev. Insp. X, Per. Contact X

1. Metropolitan District Commission, Winsor Dam, Ware Road, Belchertown, Mass.
Name _____ St. & No. _____ City/Town _____ State _____ Tel. No. _____

2. _____
Name _____ St. & No. _____ City/Town _____ State _____ Tel. No. _____

3. _____
Name _____ St. & No. _____ City/Town _____ State _____ Tel. No. _____

3.

CARETAKER: (if any) e.g. superintendent, plant manager, appointed by
absentee owner, appointed by multi owners.

Supt. of Gumbin Reservoir
M. D. C. Winsor Dam, Ware Road, Belchertown, Mass. 413-323-6921
Name _____ St. & No. _____ City/Town _____ State _____ Tel. No. _____

4.

DATA:

No. of Pictures Taken None Sketches See description of Dam
Plans, Where In M.D.C. office files at Winsor Dam Headquarters

5.

DEGREE OF HAZARD: (if dam should fail completely)*

1. Minor _____ 3. Severe _____
2. Moderate _____ 4. Disastrous X

Comments: Assuming complete failure.

This rating may change as land use changes (future development).

6. OUTLETS: OUTLET CONTROLS AND DRAWDOWN

South westerly end of dam-intake structure for 48" diameter
No. 1 Location and Type: and 68" diameter conduits in outlet tunnel.

Controls Yes, TYPE: Gate valve and slide valve.

Automatic . Manual X. Operative Yes X, No .

Comments: All in good condition per H.D.C. personnel.

No. 2 Location and Type: See Quabbin Spillway Dam No. 2-8-309-1B

Controls Yes, Type: Flash boards.

Automatic . Manual X. Operative Yes X, No .

Comments: Minor seepage in drop wall, see Dam No. 2-8-309-1B report.

No. 3 Location and Type: Auxiliary spillway 1200 ft. south westerly of end of dam.

Controls No, Type:

Automatic . Manual . Operative Yes , No .

Comments: Crest of auxiliary spillway 6 ft. above reservoir flow line or
about 17 ft. below top embankment.

Drawdown present Yes X, No . Operative Yes X, No .

Comments: See No. 1 above-lower intake.

7. DAM UPSTREAM FACE: Slope ^{1 1/2:1 variable} to 3:1, Depth Water at Dam 152' ±

Material: Turf . Brush & Trees . Rock fill X. Masonry . Wood .
18' thick

Other 3 berms on slope

Condition: 1. Good X. 3. Major Repairs .

2. Minor Repairs . 4. Urgent Repairs .

Comments: All slopes appeared stable, alignment and grade appeared good.

8. DAM DOWNSTREAM FACE: Slope 2:1 to 2 3/4:1

Material: Turf X. Brush & Trees . Rock Fill . Masonry . Wood

Other 2 berms on slope, slope drainage installed.

Condition: 1. Good X. 3. Major Repairs .

2. Minor Repairs . 4. Urgent Repairs .

Comments: Access road to cover house; outlet structures and beginning of Chinese
aqueduct crosses slope. Slope appeared stable.

9. EMERGENCY SPILLWAY: Available Yes. Needed .

Height Above Normal Water 6 Ft.

Width 200 Ft. Height 3 to 4 Ft. Material Masonry weir
earth channel

Condition: 1. Good X. 3. Major Repairs .
2. Minor Repairs . 4. Urgent Repairs .

Comments: See also Quabbin Spillway Dam No. 2-8-309-1B

10. WATER LEVEL AT TIME OF INSPECTION: 234 Ft. Above . Below X

Top Dam X P.L. Principal Spillway .

Other

Normal Freeboard 23 Ft.

11. SUMMARY OF DEFICIENCIES NOTED:

Growth (Trees and Brush) on Embankment None found.

Animal Burrows and Washouts None found.

Damage to Slopes or Top of Dam None found. Note: precise levels in 1970 show
embankment has settled 1 1/2.

Cracked or Damaged Masonry None found.

Evidence of Seepage Minor seepage, handled by drainage system.

Evidence of Piping None found.

Leaks None found.

Erosion None found.

Trash and/or Debris Impeding Flow None.

Clogged or Blocked Spillway

Other



OVERALL CONDITION:

1. Safe X
2. Minor repairs needed _____
3. Conditionally safe - major repairs needed _____
4. Unsafe _____
5. Reservoir impoundment no longer exists (explain)
Recommend removal from inspection list _____



REMARKS AND RECOMMENDATIONS: (Fully Explain)

This is the main dam forming the Quabbin Reservoir. It is an earthen embankment with a concrete caisson core wall. The embankment is 2600 feet long and 155' high. The riprap stone shell on the upstream side appeared stable as did the turfed slope of the downstream side. Some slight seepage was noted but did not appear to be of any hazard to dam. It was not possible on this inspection to view the interior of outlet tunnel or intake wells but all exterior surfaces were checked and appeared good.

HIS/ac

QUABBIN SPILLWAY

G. Quabbin Dike, Winsor Dam and Spillway

The grass cover on the embankment forming the dike was noted to be o. k. The toe area of the dry side was in good condition and dry. The road on top of the embankment was in good condition and there was no evidence of settlement, sunken areas or cracks. The rock fill slope on the reservoir side of the dike is in good condition. Water in storage was observed to be quite low but appeared to be higher in elevation than at the time of the previous inspection.

The main dam, Winsor Dam, was noted to be in good condition. The turf cover on the downstream slope was good. Some areas apparently are being re-loaded, treated and seeded. The toe area of this main dam was dry.

The rock filled portion of the main dam on the reservoir side was in good condition. The road across the dam was o. k.

The spillway structure was again observed to be completely dry. The spillway has not been wet for many years. However, the level of water observed this year is at the entrance to the spillway forebay and thus is the highest noted in many years. The stone masonry of the spillway and the crest were observed to be o. k.

In the opinion of the undersigned, the dam, the dike and spillway are in the same good condition as previously reported, and are safe.

of file

INSPECTION REPORT - DAMS AND RESERVOIRS

1. LOCATION:

DISTRICT/Town Ware County Hampshire Dam No. 2-8-309-1B

Name of Dam Quabbin "Spillway"

Mass. Sect.
Topo Sheet No. 14D Coordinates: N 470,200, E 373,000

Date
Inspected by: R. C. Sells, P.E., On Feb. 26, 1974. Last Inspection 1970.
See also Quabbin Winsor Dam No. 2-8-309-1A and Goodnough Dike No. 2-8-309-1C

2. OWNER/S: As of November 1972

par: Assessors X, Reg. of Deeds , Prev. Insp. , Par. Contact X

- | | |
|----|---|
| 1. | <u>Metropolitan District Commission, Winsor Dam - Ware Rd., Belchertown, Mass.</u> |
| | Name <u> </u> St. & No. <u> </u> City/Town <u> </u> State <u> </u> Tel. No. <u> </u> |
| 2. | <u> </u> |
| | Name <u> </u> St. & No. <u> </u> City/Town <u> </u> State <u> </u> Tel. No. <u> </u> |
| 3. | <u> </u> |
| | Name <u> </u> St. & No. <u> </u> City/Town <u> </u> State <u> </u> Tel. No. <u> </u> |

3. CARETAKER: (if any) e.g. superintendent, plant manager, appointed by absentee owner, appointed by multi owners.

Mr. John W. Copithorne, Supt.
Quabbin Reservoir, M.D.C. - Winsor Dam - Ware Rd., Belchertown, Mass. 413 - 373-6921

Name <u> </u>	St. & No. <u> </u>	City/Town <u> </u>	State <u> </u>	Tel. No. <u> </u>
----------------------	---------------------------	---------------------------	-----------------------	--------------------------

4. DATA:

No. of Pictures Taken 1. Sketches See description of Dam.
Plans, Where At M.D.C. office at Quabbin.
Copy of photo attached.

5. DEGREE OF HAZARD: (if dam should fail completely)*

- | | |
|-----------------------------|-------------------------------|
| 1. Minor <u> </u> | 3. Severe <u>I</u> |
| 2. Moderate <u> </u> | 4. Disastrous <u> </u> |

Comments: Assuming complete failure

*This rating may change as land use changes (future development).

6. OUTLETS: OUTLET CONTROLS AND DRAWDOWN See Inspection Report for Quabbin "Winsor Dam" No. 2-8-309-1A

No. 1 Location and Type: _____.

Controls _____, TYPE: _____.

Automatic _____, Manual _____, Operative Yes _____, No _____.

Comments: _____.

No. 2 Location and Type: _____.

Controls _____, Type: _____.

Automatic _____, Manual _____, Operative Yes _____, No _____.

Comments: _____.

No. 3 Location and Type: _____.

Controls _____, Type: _____.

Automatic _____, Manual _____, Operative Yes _____, No _____.

Comments: _____.

Drawdown present Yes X, No _____, Operative Yes _____, No _____.

Comments: See Item 5 sub. 1 - Winsor Dam Inspection Report

7. DAM UPSTREAM FACE: Slope 1 to 3.27, Depth Water at Dam crest of dam - El. 530 *Reservoir flow line at

Material: Turf _____, Brush & Trees _____, Rock fill _____, Masonry X, Wood _____

Other _____.

Condition: 1. Good X, 3. Major Repairs _____.

2. Minor Repairs _____, 4. Urgent Repairs _____.

Comments: * At time of inspection water about 10' to 12' below crest of spillway.

8. DAM DOWNSTREAM FACE: Slope 1:1

Material: Turf _____, Brush & Trees _____, Rock Fill _____, Masonry X, Wood _____

Other _____.

Condition: 1. Good X, 3. Major Repairs _____.

2. Minor Repairs _____, 4. Urgent Repairs _____.

Comments: This spillway has not functioned for years

9. EMERGENCY SPILLWAY: Available Yes . Needed No .

Height Above Normal Water 6 Ft.

Width 200' Ft. Height 3 - 4 Ft. Material Earth channel
Masonry weir

Condition: 1. Good X . 3. Major Repairs _____ .
2. Minor Repairs _____ . 4. Urgent Repairs _____ .

Comments: See sheet No. 6 of sketch with description of Winsor Dam

10. WATER LEVEL AT TIME OF INSPECTION: 12 Ft. Above _____ . Below X _____ .

Top Dam X P.L. Principal Spillway _____ .

Other 12 ft. below crest of this spillway crest

Normal Freeboard 23 Ft.

11. SUMMARY OF DEFICIENCIES NOTED:

Growth (Trees and Brush) on Embankment None _____ .

Animal Burrows and Washouts None _____ .

Damage to Slopes or Top of Dam None _____ .

Cracked or Damaged Masonry None found _____ .

Evidence of Seepage None seen - no water in approach channel _____ .

Evidence of Piping None seen - no water in approach channel _____ .

Leaks None seen - no water in approach channel _____ .

Erosion None _____ .

Trash and/or Debris Impeding Flow None _____ .

Clogged or Blocked Spillway None _____ .

Other _____ .

12.

OVERALL CONDITION:

1. Safe I
2. Minor repairs needed _____
3. Conditionally safe - major repairs needed _____
4. Unsafe _____
5. Reservoir impoundment no longer exists (explain)
Recommend removal from inspection list _____

13.

REMARKS AND RECOMMENDATIONS: (Fully Explain)

This is the overflow spillway for the Quabbin Reservoir and is located northwesterly from the westerly end of the Winsor Dam about 1500 feet. It consists of a side channel spillway structure with granite stone masonry weir crest 370 feet long with its crest at elevation 530 or at the reservoir flow line elevation. There is a short 39 3/4 foot long weir section with the granite stone masonry walls crest at elevation 528.0 but with provisions for stop logs to elevation 530.0. A picture of this portion of the spillway weir is attached. This weir wall varies in height with a maximum of around 13 feet. The approach channel, the side channel trough and the downstream slope are all in rock excavation.

At the time of the inspection water in the reservoir was below to elevation of the bottom of the approach channel. Mr. Mellin, Assistant Superintendent, who accompanied us on our inspection, said that last year was the first time in many years that there was sufficient water in the reservoir so that a boat could enter the approach channel and that no water had flowed over spillway weir wall since 1961.

The Quabbin Spillway appeared to be in excellent condition with all the masonry of the crest and spillway wall without any evidence of deterioration, not even a mortar joint requiring pointing.

RCS/js/vk

DESCRIPTION OF DAM

DISTRICT 2

Submitted by R. C. Salls, P.E. Dam No. 2-8-309-1B
 Date February 26, 1974 County/Town Ware
 Name of Dam Quabbin "Spillway"

1. Location: Topo Sheet No. 14D Mass. Rect. Coordinates N 470,200 E 373,000

Provide $8\frac{1}{2}$ " x 11" in clear copy of topo map with location of Dam clearly indicated.

Access from Ware Rd. "Rte. 9." about 2 1/2 miles easterly from junction with Rte. 21 - about 5000 ft. (1 mi.) north from Rte. 9 on Winsor Dam Rd. - Just after crossing Winsor Dam.

2. Year built 1976 - 78 Year/s of subsequent repairs Unknown

3. Purpose of Dam: Water Supply X Recreational _____
 Flood Control _____ Irrigation _____ Other _____

4. 186 sq. miles - plus limited diversion from Ware River - watershed 98 sq. miles
 Drainage Area: _____ sq. mi. _____ acres.

Type: City, Bus. & Ind. _____ Dense Res. _____ Suburban _____ Rural, Farm 15%
 Wood & Scrub Land 85% Slope: Steep 15% Mod. 75% Slight 10%

5. Normal Ponding Area: 38.6 sq. mi. Acres; Ave. Depth _____
24,704 Max. water depth 150 ft.
 Impoundment: 412 billion gals.; _____ acre ft.
 Silted in: Yes _____ No _____ Approx. Amount Storage Area _____

6. No. and type of dwellings located adjacent to pond or reservoir _____
 i.e. summer homes etc. Residences of operating personnel

7. Dimensions of Dam: Length See Note Max. Height 10 ft. ±
404 3/4
 Freeboard 23' when reservoir at flow level
 Slopes: Upstream Face 1:1.27 batter - granite masonry
 Downstream Face 1:1 batter - granite masonry
 Width across top Crest
370' masonry crest at 530 plus 3/4" 3/4' stop log

Dam No. 2-8-709-1B

8. Classification of Dam by Material:

Earth _____ Conc. Masonry _____ Granite _____
 Stone Masonry X
 Timber _____ Rockfill _____ Other _____

8A. Dam Type: Gravity X Straight _____ Curved, Arched _____ Other _____
 Overflow X Non-overflow _____

9. A. Description of present land usage downstream of dam:
90 % rural; 10 % ~~mixed~~ developed - villages of Bondsville and Three Rivers

B. Is there a storage area or flood plain downstream of dam which could accommodate the impoundment in the event of a complete dam failure? Yes _____ No X

C. Character Downstream Valley: Narrow X Wide _____ Developed 10%
 Rural 90% Urban _____

10. Risk to life and property in event of complete failure. * See note below.

No. of people Say 2 - 300 before Chioopee River

No. of homes 30+ houses before villages of Bondsville and Three Rivers -
Say 2 - 300 housed before Chioopee River

No. of businesses Numerous in villages

No. of industries Several light manufacturing plants

No. of utilities 4 Type Water supply - pole lines for telephone and electric plus electric transmission line

Railroads Boston & Maine and the Central Vermont R. R.

Other dams Bondsville Upper Dam No. 3-7-227-11 and Bondsville Lower Dam No. 3-7-227-12 on Swift River

Other State Fish Hatchery - numerous town highway and bridges - also Route 9 State Highway

11. Attach Sketch of dam to this form showing section and plan on 8 1/2" x 11" sheet.
Sketch - 3 sheets.

RCS/vk * Note: Risk to life and property shown along Swift River only. Damage is also likely on Chioopee River.

Attachments
 Locus Plan
 Sketches


CO TO SCALE
CONSTRUCTION SHEET
SHEET NO. 3

WAKE MASS


QUABBIN SPILLWAY
DATA NO. 2

SHEET NO. 3

SPILLWAY DATA



Sheet No. 3
M.C.S.



DATE: 11-2-03
 DRAWN BY: RAN 52


REVISION NO. 1

DRAWN BY: RAN 52
 CHECKED BY: SMV


SHEET No 3 OF 3
SOUTH MAHARAJA CONTRACT # 52 PLAN
SUBJECT No 13 B, P/C

Construction Details

DAI No. 2-11-36-1 B
QUARTER SULLYAT




Sheet No. P/C



DAN No 2-8-309-1 B ATTACH to INSPECTION REPORT - 270 FEB 24, 1974

APPENDIX B-35





The Commonwealth of Massachusetts

EXECUTIVE OFFICE OF ENVIRONMENTAL AFFAIRS
DEPARTMENT OF ENVIRONMENTAL QUALITY ENGR.
DIVISION OF WATERWAYS

Metropolitan District Commission
Windsor Dam
Ware Road
Belchertown, Ma.

100 Nashua Street, Boston 02114

March 2, 1977

Re: Inspection Dam #2-6-309-1B
Quabbin Spillway Dam

Dear Sir:

On March 23, 1976, an Engineer from the Massachusetts Department of Public Works made a visual inspection of the above dam. Our records indicate the owner to be Metropolitan District Commission. If this information is incorrect will you please notify this office.

The inspection was made in accordance with the provisions of Chapter 253 of the Massachusetts General Laws as amended (Dams Safety Act). Chapter 706 of the Acts of 1975 transferred the jurisdiction of the so-called "Dams Safety Program" to the Commissioner of the Department of Environmental Quality Engineering.

The results of the inspection indicate that this dam is safe; however, the following conditions were noted that require attention:

SEE REMARKS AND RECOMMENDATIONS ON REVERSE SIDE.

We call these conditions to your attention before they become serious and more expensive to correct. With any correspondence please include the number of the Dam as indicated above.

Very truly yours,

John J. Hannon, P. E.
Chief Engineer

AMc:


cc: Francis J. Hoey
Russell Salls
Supt. Quabbin Reservoir
M.D.C. Windsor Dam
Ware Road
Belchertown, Ma.

APPENDIX B-37

REMARKS AND RECOMMENDATIONS

This is an overflow spillway for Quabbin Reservoir built of granite stone masonry and is 170' long with its crest elevation at 530.0. This spillway runs in a northerly-southerly direction and at the northerly end there is a short spillway 34.5 long running east-west. This spillway crest is at elevation 528.0 with provisions for stop logs to elevation 530.0. One stop log was in place at time of inspection with water overtopping this stop log 10" to 12" or just 6" below crest of main spillway. This is the first time since 1961 that the water level of reservoir has reached this elevation.

Mr. Donald Slonwhite of the N.D.CQ Winsor Dam Headquarters accompanied the inspection tour. He stated that the seepage from the spillway dropwall would be closely checked and the masonry joints would be investigated as soon as feasible.



MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A

INSPECTION REPORT - DAMS AND RESERVOIRS

1. LOCATION:
 Site/Town Ware County Hampshire Dam No. 2-B-300-1B
 Name of Dam Quabbin "Spillway"
 Mass. Sect.
 Topo Sheet No. 14 D Coordinates: N 870,200 E 973,000
 Inspected by: Harold T. Shumay On March 23, 1976 Date
 Last Inspection 2-26-74

2. OWNER/S: As of March 23, 1976
 per: Assessors _____, Reg. of Deeds _____, Prev. Insp. X, Per. Contact X
 1. Metropolitan District Commission, Winsor Dam, Ware Rd., Belchertown, Mass.
 Name St. & No. City/Town State Tel. No.
 2. _____
 Name St. & No. City/Town State Tel. No.
 3. _____
 Name St. & No. City/Town State Tel. No.

3. CARETAKER: (if any) e.g. superintendent, plant manager, appointed by
 absentee owner, appointed by multi owners.
Superintendent, Quabbin Reservoir,
M.D.C. - Winsor Dam, Ware Rd., Belchertown, Mass.
 Name St. & No. City/Town State Tel. No.

4. DATA:
 No. of Pictures Taken None Sketches See description of Dam.
 Plans, Where At M.D.C. Office at Quabbin Headquarters - Winsor Dam.

5. DEGREE OF HAZARD: (if dam should fail completely)*
 1. Minor _____ 3. Severe X
 2. Moderate _____ 4. Catastrophic _____
 Comments: _____

*This rating may change as land use changes (future development).

6. OUTLETS: OUTLET CONTROLS AND DRAWDOWN

No. 1 Location and Type: Northerly end of main spillway - quarry stone faced crest
overflow spillway - 34'-8" W. x 2' H. to level of main spillway
elevation.

Controls Yes, TYPE: Step logs

Automatic , Manual X, Operative Yes X, No .

Comments: One 8" high step log in place at time of inspection

No. 2 Location and Type: 700' to 800' northeasterly of Winsor Dam - quarried stone
faced main spillway - 370' W. x 23' - H.

Controls None, Type:

Automatic , Manual , Operative Yes , No .

Comments: Crest of main spillway at elevation 530' - normal flow line of reservoir.

No. 3 Location and Type:

Controls , Type:

Automatic , Manual , Operative Yes , No .

Comments:

Drawdown present Yes X, No , Operative Yes , No .

Comments: See Item 6 - sub.1 - Winsor Dam Report No. 2-8-309-1A

7. DAM UPSTREAM FACE: Slope 1:1.27, Depth Water at Dam 6' to 12'

Material: Turf , Brush & Trees , Rock fill , Masonry X, Wood
Cut Granite

Other

Condition: 1. Good X, 3. Major Repairs

2. Minor Repairs , 4. Urgent Repairs

Comments:

8. DAM DOWNSTREAM FACE: Slope 1:1

Material: Turf , Brush & Trees , Rock Fill , Masonry X, Wood
Cut Granite

Other

Condition: 1. Good , 3. Major Repairs

2. Minor Repairs X, 4. Urgent Repairs

 seepage through joints between granite blocks - water level within

9. EMERGENCY SPILLWAY: Available Yes. Needed _____.

Height Above Normal Water 6 Ft.

Width 200' Ft. Height 3 to 4 Ft. Material Earth channel
Masonry weir

Condition: 1. Good X. 3. Major Repairs _____.

2. Minor Repairs _____. 4. Urgent Repairs _____.

Comments: This ditch and weir appears to be well maintained and stable.

10. WATER LEVEL AT EDGE OF INSPECTION: 1/2 Ft. Above _____. Below X _____.

Top Dam _____ P.L. Principal Spillway X _____.

Other Water level at elev. 529.5

Normal Freeboard 2' Ft.

11. SUMMARY OF DEFICIENCIES NOTED:

Growth (Trees and Brush) on Embankment None found

Animal Burrows and Washouts None found

Damage to Slopes or Top of Dam None found

Cracked or Damaged Masonry None found

Evidence of Seepage Minor seepage noted on main spillway dropwall

Evidence of Piping None noted

Leaks None noted

Erosion None noted

Trash and/or Debris Impeding Flow None found

Clogged or Blocked Spillway None found

Other _____

OVERALL CONDITION:

1. Safe _____
2. Minor repairs needed X
3. Conditionally safe - major repairs needed _____
4. Unsafe _____
5. Reservoir impoundment no longer exists (explain)
Recommend removal from inspection list _____

REMARKS AND RECOMMENDATIONS: (Fully Explain)

This is an overflow spillway for Quabbin Reservoir built of granite stone masonry and is 370' long with its crest elevation at 530.0. This spillway runs in a northerly-southerly direction and at the northerly end there is a short spillway 34.5 long running east-west. This spillway crest is at elevation 528.0 with provisions for stop logs to elevation 530.0. One stop log was in place at time of inspection with water overtopping this stop log 10" to 12" or just 6" below crest of main spillway. This is the first time since 1961 that the water level of reservoir has reached this elevation.

Mr. Donald Slengwhite of the N.D.C. Winsor Dam Headquarters accompanied the inspection tour. He stated that the seepage from the spillway dropwall would be closely checked and the masonry joints would be investigated as soon as feasible.

This spillway structure appears basically sound and safe at time of inspection.

HIS/vk

GOODNOUGH DIKE

G. Quabbin Dike, Winsor Dam and Spillway

The grass cover on the embankment forming the dike was noted to be o. k. The toe area of the dry side was in good condition and dry. The road on top of the embankment was in good condition and there was no evidence of settlement, sunken areas or cracks. The rock fill slope on the reservoir side of the dike is in good condition. Water in storage was observed to be quite low but appeared to be higher in elevation than at the time of the previous inspection.

The main dam, Winsor Dam, was noted to be in good condition. The turf cover on the downstream slope was good. Some areas apparently are being re-learned, treated and seeded. The toe area of this main dam was dry.

The rock filled portion of the main dam on the reservoir side was in good condition. The road across the dam was o. k.

The spillway structure was again observed to be completely dry. The spillway has not been wet for many years. However, the level of water observed this year is at the entrance to the spillway forebay and thus is the highest noted in many years. The stone masonry of the spillway and the crest were observed to be o. k.

In the opinion of the undersigned, the dam, the dike and spillway are in the same good condition as previously reported, and are safe.

INSPECTION REPORT - DAMS AND RESERVOIRS

1. LOCATION:

NAME/Town Ware, County Hampshire, Dam No. 2-8-309-1C

Name of Dam Quabbin "Goodnough Dike"

Mass. Reet.

Topo Sheet No. 14D, Coordinates: N 473,900, E 784,000

Inspected by: R. C. Salls, P.E., On Feb. 26, 1974, Date 1970
Last Inspection

See also Quabbin "Winsor" Dam No. 2-8-309-1A and Quabbin "Spillway" No. 2-8-309-1E

2. OWNER/S: As of November 1972

per: Assessors X, Reg. of Deeds _____, Prev. Insp. _____, Per. Contact X

1. Metropolitan District Commission, Winsor Dam, Ware Rd., Belchertown, Mass.
Name St. & No. City/Town State Tel. No.

2. _____
Name St. & No. City/Town State Tel. No.

3. _____
Name St. & No. City/Town State Tel. No.

3. CARETAKER: (if any) e.g. superintendent, plant manager, appointed by absentee owner, appointed by multi owners.

Mr. John W. Copithorne, Supt.

Quabbin Reservoir - M.D.C. Winsor Dam - Ware Rd., Belchertown, Mass. 413-273-6021
Name St. & No. City/Town State Tel. No.

4. DATA:

No. of Pictures Taken None, Sketches See description of Dam.
Plans, Where At M.D.C. office at Quabbin

5. DEGREE OF HAZARD: (if dam should fail completely)*

1. Minor _____, 3. Severe _____

2. Moderate _____, 4. Disastrous X

Comments: Assuming complete failure

*This rating may change as land use changes (future development).

⑥ **OUTLETS: OUTLET CONTROLS AND DRAWDOWN** See Inspection Report for Quabbin "Winsor Dam" No. 2-8-309-1A.

No. 1 Location and Type: _____

Controls _____, TYPE: _____

Automatic _____, Manual _____, Operative Yes _____, No _____.

Comments: _____

No. 2 Location and Type: _____

Controls _____, Type: _____

Automatic _____, Manual _____, Operative Yes _____, No _____.

Comments: _____

No. 3 Location and Type: _____

Controls _____, Type: _____

Automatic _____, Manual _____, Operative Yes _____, No _____.

Comments: _____

Drawdown present Yes X, No _____, Operative Yes _____, No _____.

Comments: See Item 5 - Sub. 1 - Winsor Dam Inspection Report

⑦ **DAM UPSTREAM FACE:** Slope Varies 1 1/2:1 to 3:1, Depth Water at Dam 175'

Material: Turf _____, Brush & Trees _____, Rock fill X, Masonry _____, Wood _____.

Other 2 berms on slope - rock fill thickened 10' thick at reservoir flow line elevation

Condition: 1. Good X, 3. Major Repairs _____.

2. Minor Repairs _____, 4. Urgent Repairs _____.

Comments: For details see sketch - sheet 3.

⑧ **DAM DOWNSTREAM FACE:** Slope 2:1 and 2 1/2:1

Material: Turf X, Brush & Trees _____, Rock Fill _____, Masonry _____, Wood _____.

Other 2 berms on slope - slope drainage in place catch basin and underdrain.

Condition: 1. Good X, 3. Major Repairs _____.

2. Minor Repairs _____, 4. Urgent Repairs _____.

Comments: Note: One fresh woodchuck hole found on lower southwesterly portion of slope. Swamp and/or beaver impoundment just south of east access road - about 300 ft. from toe.

9. EMERGENCY SPILLWAY: Available Yes . Needed No .
 Height Above Normal Water 6 Ft. auxiliary spillway
 Width 200 Ft. Height 3 to 4 Ft. Material Earth channel
Masonry weir
 Condition: 1. Good X . 3. Major Repairs _____
 2. Minor Repairs _____ . 4. Urgent Repairs _____
 Comments: See sheet 6 of sketches for Winsor Dam No. 2-8-309-1A.
See also Quabbin Spillway No. 2-8-309-1B

10. WATER LEVEL AT TIME OF INSPECTION: 75 Ft. Above _____ . Below X _____ .
 Top Dam X _____ F.L. Principal Spillway _____
 Other _____
 Normal Freeboard 23 Ft.

11. SUMMARY OF DEFICIENCIES NOTED:
 Growth (Trees and Brush) on Embankment None
 Animal Burrows and Washouts One fresh woodchuck hole on lower portion of southwestern downstream slope
 Damage to Slopes or Top of Dam None. Slope mowed and turf cared for
 Cracked or Damaged Masonry None
 Evidence of Seepage Minor seepage - handled by drainage system
 Evidence of Piping None seen
 Leaks None seen
 Erosion None seen
 Trash and/or Debris Impeding Flow None
 Clogged or Blocked Spillway None
 Other _____

12.

OVERALL CONDITION:

1. Safe X
2. Minor repairs needed _____
3. Conditionally safe - major repairs needed _____
4. Unsafe _____
5. Reservoir impoundment no longer exists (explain)
Recommend removal from inspection list _____

13.

REMARKS AND RECOMMENDATIONS: (Fully Explain)

This dike closes a low area westerly about 2 $\frac{1}{2}$ miles of the Winsor Dam and closes off the head of the Beaver Brook valley. It is a full hydraulic fill embankment 135 feet high and 2600 feet long with a concrete caisson core wall from the approximate level of the original ground to sound bedrock along the centerline of the dam. The embankment upstream slope has a riprap shell in good condition. The downstream slope is covered with a mowed turf in good condition with surface water and seepage controlled by a drainage system. A single woodchuck hole of recent origin was found on the lower southwesterly portion of the slope but Mr. Mallin, Assistant Superintendent, said that this would be taken care of during spring maintenance.

There was originally an observation wall near the center of the dam which was abandoned around 1941 and filled with loam so no recent observations are available.

Precise levels were taken along the top of the dam at frequent intervals until 1957 and a set was taken in 1971. These showed a total settlement of about 1 $\frac{1}{2}$ feet in 1971 with about 1/3 of this settlement occurring during the period from 1957 to 1971. This dam was originally designed with a 2 foot camber to allow for settlement.

RCS/js/vk

DESCRIPTION OF DAM

DISTRICT 2

Submitted by R. C. Salls, P.E. Dam No. 2-8-309-1C
 Date Feb. 26, 1974 ~~City~~ Town Ware
 Name of Dam Quabbin "Goodnough Dike"

1. Location: Topo Sheet No. 140 Mass. Sect. Coordinates N 473,900 E 784,000

Provide $8\frac{1}{2}$ " x 11" in clear copy of topo map with location of Dam clearly indicated.

Access from Rts. 9, about 2 1/2 mi. westerly from Ware Center at Quabbin Park Cemetery northerly via Enfield Rd. about 8/10 mi., then right on Dike Rd. for 5/10 mile. Road goes over dike. Dike along off Beaver Brook valley.

2. Year built 1926 - 28 Year/s of subsequent repairs 1970

3. Purpose of Dam: Water Supply X Recreational _____
 Flood Control _____ Irrigation _____ Other _____

4. 186 sq. mi. plus limited diversion from Ware River watershed of 98 sq. mi.
 Drainage Area: _____ sq. mi. _____ acres.
 Type: City, Bus. & Ind. _____ Dense Res. _____ Suburban _____ Rural, Farm 15%
 Wood & Scrub Land 85% Slope: Steep 15% Med. 75% Slight 10%

5. 38.6 sq. mi.
 Normal Ponding Area: 247,704 Acres; Ave. Depth _____
 Impoundment: 412 billion gals.; Max. depth 150 ft.
 Silted in: Yes _____ No _____ approx. Amount Storage Area Unknown

6. No. and type of dwellings located adjacent to pond or reservoir _____
 i.e. summer homes etc. Residences of operating personnel

7. Dimensions of Dam: Length 2140 ft. Max. Height 125 ft.
23' to top of embankment when full
Freeboard 22' at crest of spillway
 Slopes: Upstream Face Varies 1 1/2 to 1 to 3/4 - 1 to 1/2
Downstream Face Varies 2 to 2 1/2:1 - turf
 Width across top 34 3/4 - paved roadway

Dam No. 2-8-309-1C

8. Classification of Dam by Material:

Earth X Conc. Masonry _____ Stone Masonry _____
Hydraulic fill embankment _____
Timber _____ Rockfill _____ Other Concrete caisson core wall

8A.

Dam Type: Gravity X Straight X Curved, Arched _____ Other _____
Overflow _____ Non-overflow X

9.

A. Description of present land usage downstream of dam:

100 % rural; _____ % Water developed

B. Is there a storage area or flood plain downstream of dam which could accommodate the impoundment in the event of a complete dam failure? Yes _____ No X

C. Character Downstream Valley: Narrow X Wide _____ Developed _____
Rural _____ Urban _____

10.

Risk to life and property in event of complete failure. * See note below.

No. of people 5

No. of homes 5 full time homes - 17² cottages

No. of businesses None

No. of industries None Type _____

No. of utilities 3 Type City of Boston water supply
Electric and telephone lines
Electrical transmission line

Railroads None


Other dams Pepper Mill Pond Dam No. 2-8-309-2; Beaver Lake Dam No. 2-8-309-3

Other Route 9 - plus 2 town roads

11.

Attach Sketch of dam to this form showing section and plan on 8 1/2" x 11" sheet.

RCS/vk * Risk to life and property only on Beaver Brook, possibility of extensive
Attachments damage along Ware River in Palmer.
Locus Plan
Sketches




U.S. GEOLOGICAL SURVEY
 WATER RESOURCES DIVISION
 BRIDGE DIVISION

DATE: MAR 1950

PROJECT NO. 100000001
 DRAWING NO. 100000001

TOWN OF SCARLETT
 FLOOD CONTROL DISTRICT
 WARE, MISSISSIPPI
 PROJECT NO. 67-01
 SHEET NO. 3 OF 3 SHEETS


BY M1102 B. S. J. JC



ERG, JR.
 2/26/74

FIGURE F11BANKMENT—PROFILE ON CENTER LINE OF DIKE


SHEET NO. 3 OF 3 SHEETS
 WARDEN DAM, MASS.
 QUABBIN CONCRETE DAM NO. 26-50-10



X-SECTION SIA. 25-1-10

P. B. G. JR.
 2/26/74

LOCUS PLANT



14D

Commonwealth of Massachusetts



Soil stripped from these areas under another contract. Areas in addition to those shown may have also been stripped under another contract.

THIS AREA RESERVED

FILE 4150 PA1

Drawn BYVT
Traced by JVT
Checked by JVT

John H. ...
A.M. ...

John S. ...
Chief Engineer



Commonwealth
of
Massachusetts

LEGEND

- Rock outcrops
- Boring location and number
- Limits of sprout land or wooded area
- Swamp
- Paths
- Suggested borrow areas
- T.P. 151 Test pit location and number

Shovel cuts B, D and E show full have been completed under a previous contract
Cuts J, K, L, M, N, P and R shown dotted are being protected by the Commission, some by power shovel. These investigations will be completed and records available by June 17, 1936

Note ② - This area is reserved for construction of buildings under another contract, and the Contractor's operations near this area shall not interfere with that work.

Notes:-
Elevations - Boston City Base.
Coordinates and bearings - Quabbin (formerly Swift River) Gessner System.

The plan, profile and cross sections of the Main Dam Embankment see Sheets 7, 4 and 3 respectively.
Records of investigations of borrow pit materials may be seen at the office of the Engineer. Preliminary investigations indicate suitable materials for use under Items 8 and 15 may be found in the "Permitted Borrow Areas" but the Contractor will be allowed to borrow from any permitted areas only to the extent that the materials are satisfactory for their intended use. In addition, materials for use under Item 15 may be obtained from other permitted areas below Elev. 530 more than 1000 feet upstream from the upstream toe of the dam.
The existence of any sufficiency of suitable materials for Item 8 or any other item in any one borrow area shown is not guaranteed.

COMMONWEALTH OF MASSACHUSETTS
METR. DISTR. WATER SUPPLY COMMISSION
QUABBIN RESERVOIR
MAIN DAM EMBANKMENT
GENERAL PLAN



JUNE 1, 1936


②

Charles J. Main
Consulting Engineer

FILE CONT. 52-2,328


Acc. 24,102

②



PROFILE ON CENTER LINE

Notes
 Elevations, Boston City Base
 Coordinates and bearings, Quabbin (formerly Swift River) Reservoir System.
 Details shown on these contract drawings are indicative of the type of structures wanted and are subject to revision by working drawings to be furnished from time to time.
 For Channel Sections see Sheet 12.
 For Plan and Sections of Spillway Weir see Sheet 13.
 For general location of the Spillway Channel see Sheet 2.
 For typical section of roads see Sheet 36.



PLAN

LEGEND
 ■ Rock outcrop.
 ● Boring location and number.

For continuation of roads see Sheet 7

File 4160 R44


Designed *ML*
 Drawn *LA*
 Traced *LA*
 Checked *ML*

Paul H. Morrison
 Asst. Chief Engineer

David S. Elliman
 Chief Engineer

Charles W. Mann
 Consulting

CONTRACT 52 SHEET 11
36 SHEETS IN SET



COMMONWEALTH OF MASSACHUSETTS
METR. DISTR. WATER SUPPLY COMMISSION
QUABBIN RESERVOIR
MAIN DAM EMBANKMENT
SPILLWAY CHANNEL - SHEET I

SCALES AS NOTED

JUNE 1, 1936




Charles W. Mann
Consulting Engineer

FILE: CONT. 52-232-5

Acc 24, 11

APPENDIX B-55

②




Notes:
 The
 unless otherwise
 The
 for the
 mound lines
 The approx
 excavation is
 to be fixed
 of bed rock
 location of
 excavated &
 for stability
 be less than
 be scaled as
 A sub
 spillway etc
 see note on

File 4160 B45

Designed: A.H.
 Drawn: J.E.V.C.
 Traced: E.H.
 Checked: J.G.D.

H. R. Hamilton
 Ass't. Chief Engineer

Wm. S. Hill
 Chief Engineer



Slopes are to be trimmed to the required lines and grades, dressed with topsoil and grassed as directed.

Slopes are to be trimmed to the required lines and grades, dressed with topsoil and grassed as directed.

Slopes are to be trimmed to the required lines and grades, dressed with topsoil and grassed as directed.

Rock to be sealed as directed for stability.

Slopes are to be trimmed to the required lines and grades, dressed with topsoil and grassed as directed.

Notes:
The rock berms shown are to be about 5 feet wide unless otherwise directed.
The theoretical side slope and bottom lines shown for the rock excavation of the spillway channel are payment lines, regardless of the quantities actually excavated. The approximate elevation of the bottom of this rock excavation is shown on Sheet 11. The exact location will be fixed by a working drawing soon after the surface of bed rock is uncovered. The bottom widths for this location are fixed as shown. The 6 on 1 slopes are to be excavated as steep as the character of the rock allows for stability. The width of the channel shall not be less than the bottom width shown, and the sides shall be sealed of loose fragments.
A substantial proportion of the earth excavation of the spillway channel will have been made under another contract; see note on profile of Sheet 11.

Notes:
Elevations, Boston City Base
For locations of the channel sections and for plan and profile of Spillway Channel see Sheet 11.
For plan and details of Spillway Pier see Sheet 13
Details shown on these contract drawings are indicative of the type of structures wanted and are subject to revision by working drawings to be furnished from time to time.

COMMONWEALTH OF MASSACHUSETTS
METR. DISTR. WATER SUPPLY COMMISSION
QUABBIN RESERVOIR
MAIN DAM EMBANKMENT
SPILLWAY CHANNEL - SHEET 2



JUNE 1, 1936.

Chief Engineer

Charles T. Mann
Consulting Engineer


File Cont. 52-2.325

Acc 24 112

12

APPENDIX B-56

2



FILE 4160-B37

CAISSON NO. 7


CAISSON NO. 9

Drawn: P.M.C. S.E. 2-2
 Traced: S.F.T.
 Dashed: J.F.S. 1-26

Frank R. ...
 Asst. Chief Engineer

Frank ...
 Chief Engineer

Charles ...
 Genl.




- LEGEND**
- M Muck
 - L Loom
 - 1 Gravel, uniform
 - 2 Coarse sand, uniform
 - 3 Coarse sand, variable
 - 4 Medium sand, uniform
 - 5 Medium sand, variable
 - 6 Fine sand, uniform
 - 7 Fine sand, variable
 - 8 Rock flour or silt, uniform
 - 9 Rock flour or silt, variable
 - B Boulders
 - Rock

"Uniform" means that only a small percentage of the material has particles larger or smaller than the average.
 "Variable" means that a considerable number of particles is larger, smaller or both than the average.
 The names given the numbered classes differentiate them according to their relative pervious qualities, and each variable class contains a considerable number of larger particles.

Notes:
 Elevations - Boston City Base
 For plan location of caissons see Sheet 3
 The geological data shown on this sheet is an interpretation of the samples and is indicative only of the types of materials encountered (see Art. II of the contract)
 Sample boxes of the materials encountered during the sinking of Caissons No. 7, 9, and 20 have been prepared (full scale in depth) for inspection at the site of the Main Dam. Spoil excavated from these caissons may also be seen at the site.
 For additional geological data see Sheets 11 and 12

COMMONWEALTH OF MASSACHUSETTS
 METR. DISTR. WATER SUPPLY COMMISSION
 QUABBIN RESERVOIR
MAIN DAM CORE WALL
 OVERBURDEN - GEOLOGICAL DATA - SHEET 3



DECEMBER 21, 1934




CAISSON NO. 9

Charles D. Thomas
 Consulting Engineers.

FILE NO. 88 2,325

Acc 4323

2



File 4160 B42

Designed *[Signature]*
 Drawn *[Signature]*
 Traced *[Signature]*
 Checked *[Signature]*

[Signature]
 Asst Chief Engineer


[Signature]
 Chief Engineer

[Signature]
 Committee



CONTRACT 52 SHEET 4
36 SHEETS IN SET

Sta 31+00
(limit between Items 4 & 5)



Notes:
Elevations, Boston City Base
Details shown on these contract drawings are indicative of the type of structures wanted and are subject to revision by working drawings to be furnished from time to time.
For cross sections of Main Dam see Sheet 3
For grading plan see Sheet 7.
For roadway across top of Main-Dam see Sheet 10.

COMMONWEALTH OF MASSACHUSETTS
METR. DISTR. WATER SUPPLY COMMISSION
QUABBIN RESERVOIR
MAIN DAM EMBANKMENT
PROFILE ON CENTER LINE OF MAIN DAM

SCALES HORIZONTAL 1" = 100'
VERTICAL 1" = 20'

JUNE 1, 1936

Charles J. Mum
Consulting Engineer

File Cont. 52 2325

Acc 74 106




APPENDIX B-58

2

26'-6"

31'-0"



DETAIL OF GUTTER

1 2 3 4 FT.

File 4160 B43

Designed: *[Signature]*
Drawn: *[Signature]*
Traced: *[Signature]*
Checked: *[Signature]*


[Signature]
Asst. Chief Engineer

[Signature]
Chief Engineer

[Signature]
Co.



MAIN DAM



Rollled selected material above the limit to which the full-hydraulic construction is permitted or ordered to be carried Item 8


Embankment by full-hydraulic method, Item 8

Impervious Core, Item 8
Consolidated as directed

Impervious Core by full-hydraulic method, Item 8

as required for the dam

Cobble paving flushed with grout, Item 14



Notes:
Elevations - Boston City Base
Details shown on these contract drawings are indicative of the type of structure wanted and are subject to revision by working drawings to be furnished from time to time.
For plan of Main Dam see Sheet 7
For cross sections of Main Dam see Sheet 3
For details of drainage system see Sheets 8 and 9

COMMONWEALTH OF MASSACHUSETTS
METR. DIST. WATER SUPPLY COMMISSION
QUABBIN RESERVOIR
MAIN DAM EMBANKMENT
CROSS SECTION OF TOP OF MAIN DAM



EXCEPT AS NOTED
JUNE 1, 1936




Chief Engineer
Charles T. Main
Consulting Engineer

File Cont 52-2325

Ass 24.110





Concrete reinforced as directed. Item 23

N52.149.50
E 86.174.82


PLAN



Notes:
Elevations (Boston
Coordinates and An
Error) Reservoir Syst
Details shown on 1
indicate of the type
subject to revision by
from time to time.
For grading plan of
for details of Inta
Upper Intake walls in

Precast rock bar
Concrete. Item 23

Reinforced as directed




C-C



Crushed Stone
Item 11

Selected coarse materials
Item 10

Embankment
Item 8



SECTION A-A

Construction joints as
permitted or directed


Paul R. Hanson
Asst. Chief Engineer

Frank S. Williams
Chief Engineer

P.L.C. 4400 D-41


Designed by
Drawn by
Traced by
Checked by

6




Precast rock bars
Concrete, Item 29 -
(See Section C-C)

Concrete, Item 29



ELEVATION - INTERMEDIATE INTAKE



Notes:
Elevations Boston City Base
Coordinates and bearings Quabbin (formerly Swift
River) Reservoir System.
Details shown on these contract drawings are
indicative of the type of structure wanted and are
subject to revision by working drawings to be furnished
from time to time.
For grading plan of Main Dam see Sheet 7
For details of Intake Works Substructure and
Upper Intake walls see Sheets 19 to 27 incl.

COMMONWEALTH OF MASSACHUSETTS
METR. DISTR. WATER SUPPLY COMMISSION
QUABBIN RESERVOIR
**MAIN DAM EMBANKMENT
INTAKE WORKS - INTAKES**

SCALES AS SHOWN

JUNE 1, 1936

Frank S. Williams
Chief Engineer


Charles F. Mann
Consulting Engineer

FILE CONT. 52-2.32 5

Acc 24, 117


17

2



The road, the two 12 inch culverts and the portion of the approach channel north of the road are being built under another contract. The excavation and other work in the channel south of the road is included under this project.

The Contractor is to conduct his operations as directed or approved to safeguard the transmission lines of the New England Power Company located as shown.




Designed by
Checked ASB JFB

Asst. Chief Engineer

Chief Engineer

Consulting





The Contractor is to conduct his operations as directed or approved to safeguard the transmission lines of the New England Power Company located as shown.

Channel invert and slopes dressed with topsoil and grassed as directed. Item 15
Slope 0.5% — Ditch — Slope 0.5% 1 on 67

Notes
Elevations - Boston City Base
Coordinates and bearings, Quabbin (formerly Swift River) Reservoir System.
Details shown on these contract drawings are indicative of the type of structures wanted and are subject to revision by working drawings to be furnished from time to time.
For general plan showing location of auxiliary spillway see Sheet 2.

B-B
Opening for pipe line to be left if directed



Loose ledge removed as directed. Item 5
Other ledge, though sandy or blocky, not to be disturbed.

COMMONWEALTH OF MASSACHUSETTS
METR. DISTR. WATER SUPPLY COMMISSION
QUABBIN RESERVOIR
**MAIN DAM EMBANKMENT
AUXILIARY SPILLWAY**
SCALES AS NOTED


Charles J. Main
Consulting Engineer

JUNE 1, 1936




FILE CONT. 52-2328

Acc. 24116



- LEGEND**
- M Muck or peat
 - L Loam
 - 1 Gravel, uniform
 - 2 Coarse sand, uniform
 - 3 Coarse sand, variable
 - 4 Medium sand, uniform
 - 5 Medium sand, variable
 - 6 Fine sand, uniform
 - 7 Fine sand, variable
 - 8 Rock flour or silt, uniform
 - 9 Rock flour or silt, variable
 - D Boulders
 - Rock

"Uniform" means that only a small percentage of the material has particles larger or smaller than the average.
"Variable" means that a considerable number of particles is larger, smaller or both, than the average.
The names given the numbered classes differentiate them according to their relative pervious qualities, and each "variable" class contains a considerable number of larger particles.



DAM SITE PROFILE A-A
(Looking northwest or upstream)

Notes:
Elevations - Boston City Base.
STW for plan location of borings see Sheet 2.
Bore hole and test pit samples may be seen at the office of the Engineer at Enfield, Mass.
The geological data shown on this sheet is an interpretation of the samples and is indicative only of the types of materials encountered (see Art. II of the contract).
Surface of rock as indicated by core borings is approximate only. Actual surface may vary materially from that shown.
For location of profiles A-A and B-B see Sheets 2 and 3.
For additional geological data on profiles C-C, D-D, E-E and F-F see Sheet 12.
For additional geological data on exploratory coissons see Sheet 13.

COMMONWEALTH OF MASSACHUSETTS
METR. DISTR. WATER SUPPLY COMMISSION
QUABBIN RESERVOIR
MAIN DAM CORE WALL
OVERBURDEN - GEOLOGICAL DATA - SHEET 1

HORIZONTAL 1" = 100'
VERTICAL 1" = 20'
DECEMBER 21, 1934

X. P. Thompson
Charles T. Mann
Consulting Engineers

PLATE 38 2323




②


LEGEND

- M Muck or peat
- L Loam
- 1 Gravel, uniform
- 2 Coarse sand, uniform
- 3 Coarse sand, variable
- 4 Medium sand, uniform
- 5 Medium sand, variable
- 6 Fine sand, uniform
- 7 Fine sand, variable
- 8 Rock flour or silt, uniform
- 9 Rock flour or silt, variable
- B Boulders
- Rock


"Uniform" means that only a small percentage of the material has particles larger or smaller than the average.
 "Variable" means that a considerable number of particles is larger, smaller or both, than the average.
 The names given the numbered classes differentiate them according to their relative pervious qualities, and each "variable" class contains a considerable number of larger particles.




6



DAM SITE PROFILE F-F
(Looking northwest or upstream)



Notes:
Elevations-Boston City Base
For plan location of borings
see Sheet 2.
Bore hole and test pit samples
may be seen at the office of
the Engineer of Enfield, Mass.
The geological data shown on
this sheet is an interpretation
only of the types of materials
encountered (see Art. II of the
contract).
Surface of rock as indicated
by core borings is approximate
only. Actual surface may vary
materially from that shown.
Stationing shown on profiles
is that of the center line of the
dam.
For location of profiles C-C, D-D,
E-E and F-F see Sheets 2 and 3.
For additional geological data,
on profiles A-A and B-B, and
of exploratory caissons, see
Sheets 11 and 13.



COMMONWEALTH OF MASSACHUSETTS
METR. DIST. WATER SUPPLY COMMISSION
QUABBIN RESERVOIR
MAIN DAM CODE WALL
OVERBURDEN-GEOLOGICAL DATA-SHEET 2

SCALE (HORIZONTAL 1"=100'
VERTICAL 1"=20'
DECEMBER 21, 1934

Charles T. Tolson
Consulting Engineers

12

FILE NO. 38 2.32.3

DEC. 4312



LEGEND

- Rock outcrops
- Boring location and number
- Limits of sproutland or wooded areas
- Swamp
- Paths
- Borrow area limits
- Test pit location and number
- Top soil not acceptable in this area

FILE 1000-B38

8

CONTRACT 50 SHEET 2
15 SHEETS IN SET


Notes
Elevations - Boston City Base
Coordinates and bearings - Swift River
(now Quabbin) Reservoir System
For plan, profile and cross sections of
dike embankment see Sheets 3, 4 and 10
and for details of roads see Sheets 10 and 13
Preliminary investigations indicate suitable
materials may be found for Items 5, 6, 7, 8
and 15 in the "Permitted Borrow Areas"
except as noted, but the Contractor will be
allowed to borrow from any permitted areas
only to the extent that the materials are
satisfactory for their intended use.
In addition, impervious soil may be obtained
from areas which will be designated north-
westerly of the dike near the Enfield-Ware
road.
The existence of or a sufficiency of suit-
able materials for Item 8 or any other item
of any one borrow area shown is not guaran-
teed.

Note - Records of investigations of borrow
pit materials may be seen at the office of the Engineer



COMMONWEALTH OF MASSACHUSETTS
METR. DIST. WATER SUPPLY COMMISSION
QUABBIN RESERVOIR
DIKE EMBANKMENT
GENERAL PLAN

2





Notes:
 Elevations - Dunes City Base
 For plan location of borings see
 Dunes hole and test pit surveys in
 the office of the Engineer of C.
 The geotechnical data shown
 are an interpretation of the samples
 from only of the types of meter
 (see A-1, C-1, and C-2).
 Section of soil or material in
 specimens only actual surface
 grade from that shown.
 For location of profiles A-A,
 Sheet 3.
 For additional geotechnical data
 see sheet C-1, and C-2.

Designed *[Signature]*
 Drawn *[Signature]*
 Checked *[Signature]*

STATION
 Stationary station of profile is
 part of the center line of the site

DNE SITE PROFILE E-B
 (Looking north or upstream)

[Signature] Designing Engineer
[Signature] Chief Engineer
[Signature] Consulting En.



Notes:
Elevations-Diston City Base
For plan location of borings see Sheet 3, Art. 3003
Core logs and test pit samples may be seen at the office of the Engineer at Enfield, Mass.
The geological data shown on this sheet is an interpretation of the samples and is indicative only of the types of materials encountered (see Art. 3003 of the contract).
Surfaces of rock or boulders by core borings is approximate only. Actual surface may vary materially from that shown.
For location of profiles A-A, B-B and C-C see Sheet 3.
For additional geological data, see profiles A-A, B-B, C-C and C-C on page 2000 on Sheet 3.

COMMONWEALTH OF MASSACHUSETTS
METR. DISTR. WATER SUPPLY COMMISSION
QUABBIN RESERVOIR
DIKE CORE WALL
OVERBURDEN-GEOLOGICAL DATA-SHEET 1

SCALE: HORIZONTAL 1"=100'
VERTICAL 1"=20'
EXCEPT AS NOTED
NOVEMBER 4, 1932




W. L. Smith
Chief Engineer

W. L. Smith
Consulting Engineers

Plat. Cont. 36-2523

Art. 3003



Designed *Karl R. Anderson*
 Drawn *[Signature]*
 Checked *[Signature]*
 Dated *4.2.52*

DIKE SITE PROFILE D-D


(Looking north or upstream)

Karl R. Anderson
 Designing Engineer


[Signature]
 Chief Designer

[Signature]
 Consulting





Notes:
Elevations-Boston City Base
For plan location of borings see Sheet 3 Acc. 3903
Bore logs and test pit samples may be seen at the office of the Engineer at Enfield, Mass.
The geological data shown on this sheet is an interpretation of the samples and is indicative only of the types of materials encountered (see Art. IX of the contract).
Surfaces of rock as indicated by core borings is approximate only. Actual surfaces may vary materially from that shown.
Stationing shown on profiles is that of the center line of the dike.
For location of profiles D-D and E-E see Sheet 3
For additional geological data, on profiles A-A, B-B and C-C, and an exploratory canon, see Sheet 6



LEGEND

- M Muck or peat
- L Loam
- 1 Gravel, uniform
- 2 Coarse sand, uniform
- 3 Coarse sand, variable
- 4 Medium sand, uniform
- 5 Medium sand, variable
- 6 Fine sand, uniform
- 7 Fine sand, variable
- 8 Rock flour or silt, uniform
- 9 Rock flour or silt, variable
- B Boulders
- Rock

Uniform means that only a small percentage of the material has particles larger or smaller than the average.
Variable means that a considerable number of particles is larger, smaller or both, than the average.
The names given the numbered classes differentiate them according to their relative pervious qualities, and each variable class contains a considerable number of larger particles.

COMMONWEALTH OF MASSACHUSETTS
METR. DIST. WATER SUPPLY COMMISSION
QUABBIN RESERVOIR
DIKE CORE WALL
OVERBURDEN - GEOLOGICAL DATA - SHEET 2


SCALES (HORIZONTAL) 1" = 100'
(VERTICAL) 1" = 20'
EXCEPT AS NOTED
NOVEMBER 4, 1932

E D-D
J.S.H.
Chief Engineer
K. G. ...
Consulting Engineers

File Case 36-2383



2



File 4160-B40


Designed by *[Signature]*
 Drawn by *[Signature]*
 Checked by *[Signature]*

[Signature]
 Asst. Chief Engineer

[Signature]
 Chief Engineer

[Signature]
 Comd.

CONTRACT 50 SHEET 4
15 SHEETS IN SET



Notes:
Elevations, Boston City Base.
For cross sections of dike see Sheet 3.
For foundation grading sections see Sheets 7, 8 and 9.
For grading plan see Sheet 10.
For roadway across top of dike see Sheet 12.
Details shown on these contract drawings are indicative of the type of structures wanted and are subject to revision by working drawings to be furnished from time to time.

COMMONWEALTH OF MASSACHUSETTS
METR. DISTR. WATER SUPPLY COMMISSION
QUABBIN RESERVOIR
DIKE EMBANKMENT
PROFILE ON CENTER LINE OF DIKE

SCALE { HORIZONTAL 1" = 100'
 { VERTICAL 1" = 20'

OCTOBER 1, 1934




Charles L. Allen
Consulting Engineers

Proj. Cont. 50, 232 S

Acc. 45946

APPENDIX B-67

2






Designed by
 Drawn by
 Checked by
 Date

Paul R. Hamilton
 Paul R. Hamilton
 Chief Engineer

John S. Miller
 John S. Miller
 Chief Engineer

John S. Miller
 Chief Engineer

STA. 21+80



Note:
The lines marked "Theoretical Core Line" indicate the desired width of cutfill of satisfactory, impervious quality and show the approximate location for the finest materials deposited by the hydraulic work under Item 8.

Notes
Elevations, Boston City Base.
Details shown on these contract drawings are indicative of the type of structures wanted and are subject to revision by working drawings to be furnished from time to time.
For plan and sections of foundation embankments see Sheets 6, 7, 8 and 9.
For profile of dike see Sheet 4.
For grading plan of dike see Sheet 10.
For details of roadway on top of dike see Sheet 12.

COMMONWEALTH OF MASSACHUSETTS
METR. DIST. WATER SUPPLY COMMISSION
QUABBIN RESERVOIR
DIKE EMBANKMENT
TYPICAL CROSS SECTIONS

OCTOBER 1, 1934



Charles F. Klein
Consulting Engineers

Proj. Contr. 50-2-325




Acc. 2080

2




PROFILE OF & OF ROADWAY





PROFILE ON CENTER LINE OF DAM LOOKING UPSTREAM

①



LOCATION OF SETTLEMENT POINT	
STATION	OFFSET FROM E
15+00	17.0' E
18+00	18.5 -
21+00	18.5 -
24+00	18.4 -
27+00	18.5 -
30+00	19.6 -
33+00	18.6 -
36+00	18.6 -





COMMONWEALTH OF MASSACHUSETTS
 METR. DISTR. WATER SUPPLY COMMISSION
 QUABBIN RESERVOIR
WINSOR DAM EMBANKMENT
 SETTLEMENT OF THE EMBANKMENT
 SCALES AS SHOWN
 OCTOBER 28, 1940

Revised: 1-2-41

Fig. 2-32 B


Am. 17792

②




File 4160 B31

REPRODUCED FROM ASL NOTES



LOCATION OF SETTLEMENT PINS	
STATION	W/SET FROM S
14+00	ZO Peg
17+00	ZO Peg
20+00	ZO Peg
23+00	ZO Peg
26+00	ZO Peg
29+00	ZO Peg
32+00	ZO Peg



COMMONWEALTH OF MASSACHUSETTS
 METR. DISTR. WATER SUPPLY COMMISSION
 QUABBIN RESERVOIR
DIKE EMBANKMENT
 SETTLEMENT OF THE EMBANKMENT
 SCALES AS SHOWN
 OCTOBER 10, 1939

Revised: 5-27-42

Fig. 2.32 B

Acc 17641


2

APPENDIX C
SELECTED PHOTOGRAPHS OF PROJECT

<u>LOCATION PLANS</u>					<u>Page</u> <u>No.</u>
Winsor Dam and Quabbin Spillway					1
Quabbin Spillway					2
Goodnough Dike					3
<u>PHOTOGRAPHS</u>					
<u>No.</u>	<u>Title</u>	<u>Roll</u>	<u>Frame</u>	<u>Page</u> <u>No.</u>	
1.	Winsor Dam Monument, Located at Right Abutment	12	4	4	
2.	Downstream Slope, From Left Abutment	12	10	vi, 4	
3.	Roadway Crest and Downstream Slope, From Right Abutment	12	9	5	
4.	Upstream Slope Near Left Abutment	12	11	5	
5.	Upstream Slope From Roof of Intake Structure	12	15	6	
6.	Entrance to Intake Structure, at Crest of Dam	12	8	6	
7.	Stone Masonry Walls at Roof Level, Intake Structure	12	6	7	
8.	Stone Masonry Wall Left of Intake Structure	12	7	7	
9.	Intake Structure	12	16	8	
10.	Gate and Screens Inside Intake Structure	12	17	8	
11.	Auxiliary Spillway and Approach Channel, Looking Toward Quabbin Reservoir	12	21	9	
12.	Crest of Auxiliary Spillway	12	20	9	
13.	Quabbin Spillway, Overall View	11	0A	vi, 10	
14.	Quabbin Spillway Weir	12	3	10	
15.	Spillway Weir and Bedrock, Water Flowing From Drill Holes	13	13	11	
16.	Spillway Weir at its Highest Point	13	6	11	
17.	Spillway Weir Showing Vertical Crack in Granite Masonry	13	9	12	
18.	Closeup of Vertical Crack	13	8	12	
19.	Side Spillway with Stoplogs	13	23	13	
20.	Side Spillway and Walkway	12	2	13	
21.	Approach Channel to Spillway	13	25	14	

PHOTOGRAPHS (Continued)

<u>No.</u>	<u>Title</u>	<u>Roll</u>	<u>Frame</u>	<u>Page No.</u>
22.	Discharge Channel From Spillway	13	4	14
23.	Rock Cut at Entrance to Spillway Discharge Channel, Left Side	13	20	15
24.	Rock Cut at Entrance to Spillway Discharge Channel, Right Side	13	14	15
25.	Spillway Discharge Channel Below Highway Bridge	12	25	16
26.	Goodnough Dike Monument	11	1A	16
27.	Roadway Across Embankment	11	2A	17
28.	Downstream Slope From Right Abutment	11	3A	17
29.	Downstream Slope From Near Toe of Dike	11	7A	vii, 18
30.	Unmowed Wet Areas Near Downstream Toe	11	10A	18
31.	Seepage Through Paved Ditch, Downstream of Wet Areas	11	8A	19
32.	Upstream Slope	11	15A	19
33.	Settlement Observation Pipe on Upstream Slope Near Crest of Dike	11	11A	20



FILE NO. 4160 B12


HALEY & ALDRICH, INC.
CAMBRIDGE, MASSACHUSETTS

①

QUABBIN RESERVOIR

Richards Ledges

GOODNOUGH DIKE
MA 00590



GOODNOUGH DIKE

WORCESTER
HAMPSHIRE

Quabbin Hill
Picnic Area

Picnic Area


Peppers Mill Pond

Brimstone Hill

Quabbin Park Cemetery


West Ware

QUABBIN
RESERVOIR



PROJECT LOCUS
U.S.G.S. QUADRANGLE
WINSOR DAM, MASS.
APPROX. SCALE: 1" = 2000'

2



NOTE:

PLAN DEVELOPED FROM M.D.C. CONSTRUCTION DRAWING NO. 11, ACC. 24111 SHOWN IN APPENDIX B AND HALEY & ALDRICH FIELD OBSERVATIONS ON 29 JUNE 1978.

LEGEND:

(14) PHOTOGRAPH NUMBER AND DIRECTION OF VIEW.

QUABBIN SPILLWAY
QUABBIN RESERVOIR


SITE SKETCH PLAN
SCALE: 1" = 100' SEPTEMBER 1978

FILE NO 4160 00 A29

HALEY & ALDRICH, INC.
CAMBRIDGE, MASSACHUSETTS

FILE NO 4160 00 A30

HALEY & ALDRICH, INC.
CAMBRIDGE, MASSACHUSETTS



NOTE:

PLAN DEVELOPED FROM M.D.C.
CONSTRUCTION PLAN SHOWN IN APPENDIX B-54
AND HALEY & ALDRICH, INC. FIELD
OBSERVATIONS ON 29 JUNE 1978.

LEGEND:



PHOTOGRAPH NUMBER AND
DIRECTION OF VIEW.

GOODNOUGH DIKE
QUABBIN RESERVOIR

SITE SKETCH PLAN

SCALE: 1" = 400' SEPTEMBER 1978



1. Winsor Dam Monument, Located at Right Abutment



2. Downstream Slope, From Left Abutment



3. Roadway Crest and Downstream Slope, From Right Abutment



4. Upstream Slope Near Left Abutment



5. Upstream Slope From Roof of Intake Structure



6. Entrance to Intake Structure, at Crest of Dam



7. Stone Masonry Walls at Roof Level, Intake Structure



8. Stone Masonry Wall Left of Intake Structure



9. Intake Structure




10. Gate and Screens
Inside Intake
Structure




11. Auxiliary Spillway and Approach Channel, Looking
Toward Quabbin Reservoir



12. Crest of Auxiliary
Spillway



13. Quabbin Spillway, Overall View



14. Quabbin Spillway Weir



15. Spillway Weir and Bedrock, Water Flowing From Drill Holes



16. Spillway Weir at its Highest Point




18. Closeup of Vertical Crack



17. Spillway Weir Showing Vertical
Crack in Granite Masonry



19. Side Spillway with Stoplogs



20. Side Spillway and Walkway



21. Approach Channel to Spillway




22. Discharge Channel From Spillway




23. Rock Cut at Entrance to Spillway Discharge Channel,
Left Side




24. Rock Cut at Entrance to Spillway Discharge Channel,
Right Side



26. Goodnough Dike Monument



25. Spillway Discharge Channel Below
Highway Bridge



27. Roadway Across Embankment



28. Downstream Slope From Right Abutment




29. Downstream Slope From Near Toe of Dike



30. Unmowed Wet Areas Near Downstream Toe



31. Seepage, Through
Paved Ditch, Down-
Stream of Wet Areas



32. Upstream Slope




33. Settlement Observation Pipe on
Upstream Slope Near Crest of Dike

APPENDIX D
OUTLINE OF DRAINAGE AREA AND
HYDRAULIC COMPUTATIONS

<u>OUTLINE OF DRAINAGE AREA</u>	<u>Page No.</u>
Drainage Area Map	1
<u>COMPUTATIONS</u>	
Size Classification, Hazard Potential Classification, Test Flood, Drainage Area, Maximum Probable Flood, Historical Data	2
Development of Unit Hydrograph for East Branch Swift River	3
Development of Unit Inflow Hydrograph for Quabbin Reservoir - Land Portion	5
Routing of Inflow PMF	7
Dam Failure Analysis	26
Field Notes	27



CAMP DRESSER & McKEE Inc.
Consulting Engineers
Boston, Mass.



**QUABBIN RESERVOIR
DRAINAGE AREA**

SCALE 1:250 000

APPENDIX D-1

CAMP DRESSER & MCKEE
Environmental Engineers
Boston, Mass.

CLIENT HALEY & ALDRICH
PROJECT NAT'L DAM INSP. CRT.
DETAIL QUABBIN SPILLWAY

JOB NO. 561-B-87
DATE CHECKED 9/25/78
CHECKED BY dlb

PAGE A1
DATE 7-19-78
COMPUTED BY VED

SIZE CLASSIFICATION:

Height = 155' ±
Storage = 412 billion gals. } LARGE

HAZED POTENTIAL CLASSIFICATION:

Estimated loss of life is 2-300 persons

∴ Category is HIGH

TEST FLOOD:

HIGH Hazard & LARGE Size → Test flood = PMF

DRAINAGE AREA: 186 sq. mi. + diversion from Ware River

MAXIMUM PROBABLE FLOOD: (see attached pages B3 thru C13)

PMF INFLOW = 276,800 cfs

PMF OUTFLOW = 16,300 cfs

HISTORICAL DATA:


Maximum Recorded Spillway Discharge:

1,527 cfs on April 16, 1953

See field notes for other recorded discharge info.

1" = 100' HORIZ. SCALE
 1" = 10' VERT. SCALE

CLIENT: Chicago Sanitary & Sewer District PROJECT NO. 54-9-27 PAGE 2 OF 4
 PROJECT: Sanitary Sewer Main DATE CHECKED: 1/25/10 DATE: 11/20/10
 DETAIL: Sanitary Sewer Main CHECKED BY: dlb COMPUTED BY: dlb



* See Appendix D-1 for details

CAMP DRESSER & MAKER
 Environmental Engineers
 Boston, Mass.

CLIENT: U.S. Army Corps of Engineers JOB NO. 54-9-377
 PROJECT: Water Control at Fort Belknap DATE CHECKED: 11/25/78
 DETAIL: Diversion Channel CHECKED BY: dlb

PAGE 2 of 4
 DATE: 11/25/78
 COMPUTED BY: dlb

Flow Characteristics of Diversion Channel at Fort Belknap, Mont.

Description of Data by Date - Base at September 1952

Date	Channel	Base	Flow	Velocity	Discharge
Sept 18	63 ft	20 ft	48 ft	5.57 ft/s	
19	70	30	90	10.6	
20	70	30	80	7.9	
21	68	4	160	53.5	
22	275	40	250	31.2	70-100 ft/s
23	227	70	257	99.5	
24	203	30	123	49.1	
25	250	90	310	30.2	
26	267	100	167	10.2	67.5-105 ft/s
27	220	110	110	12.8	43.7
28	235	170	25	9.1	
29	186	130	56	6.5	
30	159	140	19	2.31	

Q = 10,125 cfs - base

Volume of Runoff = (10,125 cfs) (40) (60) (24) = 272,200 cu ft


Duration = $\frac{272,200 \text{ cu ft}}{(0.27 \text{ ft/s}) (1,200 \text{ ft})} = 0.218 \text{ hr} = 2.62 \text{ hr}$

The September 1952 data had the following time and discharge:

Total	Time	Frequency
60	hr	> 1000 yr
90	hr	> 1000 yr
123	hr	> 1000 yr

DATE: _____
 PROJECT: _____
 DRAWN BY: _____

CLIENT: Water Pollution Control Authority JOB NO. 54477 PAGE 3 OF 4
 PROJECT: Construction of Sewerage DATE CHECKED: 9/15/88 DATE: July 20/88
 DETAIL: Discharge Control CHECKED BY: dlbca COMPUTED BY: dlbca



CAMP DRESSER & MAKER
Environmental Engineers
Boston, Mass.

CLIENT City of Boston - Dept. of Public Works PROJECT Control of Pollution at Boston Harbor DATE CHECKED 9/25/78
DETAIL Control of Pollution CHECKED BY dlm

PAGE 24 - 4
DATE 10/2/78
COMPUTED BY dlm

2.10 - 2.12

$2.10 - 2.12 = 16.5$

$2.10 - 2.12 = 16.5$

$1.45 - 3.45 = 1.99$

$2.12 = 23$

$2.12 - 2.13 = 2.11$

Line	Dist	Angle	Area
Line	272	161°	9
Line	232	180°	1
Line	1.21	312°	5
			3
			2
			1

Boundary of impact of 2.12 on 2.11 or 2.13

subsequent adj. continue with hydrographical

and surface area

Area	Perimeter	Volume	Area
24,900	0	0	0
24,950	1	2,017	100,000,000
24,900	2	3,030	100,000,000
24,950	3	9,075	100,000,000
24,900	4	5,047	100,000,000
24,950	5	5,050	100,000,000
24,900	6	1,003	100,000,000
7	0	0	0

Total 25 1.917

CAMP CREBBER & MARLE
 Environmental Engineers
 Concord, Mass.

CLIENT State of Massachusetts Dept. of Transportation JOB NO. 54-3-17
 PROJECT State - Franklin County DATE CHECKED 9/25/78
 DETAIL Drainage CHECKED BY dlb

PAGE C-12/15
 DATE 9/25/78
 COMPUTED BY dlb

Vertical Alignment

Sta	Surface	Prop	Height	Vertical
0	2,000	0	0	0
3	2,000	1,500	500	0
6	4,200	2,000	2,200	0
7	5,500	2,000	3,500	0
8	7,200	2,000	5,200	0
9	10,000	2,000	8,000	0
10	12,800	2,000	10,800	0
11	15,200	2,000	13,200	0
12	17,900	2,000	15,900	0
13	20,600	2,000	18,600	0
14	23,500	2,000	21,500	0
15	26,000	2,000	24,000	0
16	29,000	2,000	27,000	0
17	32,000	2,000	30,000	0
18	35,000	2,000	33,000	0
19	38,300	2,000	36,300	0
20	42,000	2,000	40,000	0
21	45,000	2,000	43,000	0
22	48,000	2,000	46,000	0
23	51,700	2,000	49,700	0
24	55,000	2,000	53,000	0
25	59,300	2,000	57,300	0
26	61,600	2,000	59,600	0
27	55,000	2,000	53,000	0
28	43,000	2,000	41,000	0
29	32,000	2,000	30,000	0
30	20,000	2,000	18,000	0
31	25,500	2,000	23,500	0
32	31,500	2,000	29,500	0
33	28,200	2,000	26,200	0
34	25,500	2,000	23,500	0
35	23,000	2,000	21,000	0
36	20,600	2,000	18,600	0
37	15,000	2,000	13,000	0
38	11,500	2,000	9,500	0
39	9,000	2,000	7,000	0
40	7,500	2,000	5,500	0

Vertical Curve Data:

- 0-12.00 = 2,000' ? 2,000'
- 12-24.00 = 21,000'
- 24-36.00 = 10,000'
- 36-48.00 = 13,000'
- 48-72.00 = 3,000'
- 72-84.00 = 19,900'
- 84-96.00 = 19,900'
- 96-108.00 = 19,900'

Vertical Curve Summary:

- Point of Vertical Intersection = 33.2'
- Point of Vertical Curvature = 19.9' = 1.176' = 1.176' = 1.176'

CAMP O'BRIEN & MCKEE
Environmental Engineers
Boston, Mass.

CLIENT State of Massachusetts JOB NO. 54-0-20
PROJECT Route 1 - 6500 ft - 1970 DATE CHECKED 9/25/78
DETAIL Hydrology CHECKED BY dlb

PAGE 2 of 2
DATE 10/1/78
COMPUTED BY dlb

Spillway Channel Hydraulics

H = 10'
Reserve Q = 1516 cfs W.C. spillway = 5310

Channel depth = 5310 - 5110 = 190'

Channel area = 1063 ft² ∴ Channel velocity = $\frac{1516 \text{ cfs}}{1063 \text{ ft}^2} = 1.426 \text{ fps}$

$$\frac{V^2}{2g} = 0.031'$$

$$\therefore \text{E.S.} = 5310 + 0.03 = 531.03'$$

Reserve area at approach channel = 1.25 ft² = 1'

n = 0.02

$$\text{Then, } h_c = \left[\frac{1.25 \times 0.02}{1.496 (1.346)^{4/3}} \right]^2 \times 150 = 0.00455'$$

$$R = \frac{1063 \text{ ft}^2}{5110 \text{ ft}} = 11.34'$$

Then E.S.P. minor = 531.03 + 0.005 = 531.035 $C = \frac{1516}{1063 \times 1.426} = 3.558$

$C = 3.558$

H = 15'
Reserve Q = 2070 cfs W.C. spillway = 5315

C = 3.713

Channel depth = 5315 - 5140 = 175'

Channel area = 1101 ft² ∴ Channel velocity = $\frac{2070 \text{ cfs}}{1101 \text{ ft}^2} = 1.88 \text{ fps}$

$$\frac{V^2}{2g} = 0.105'$$

$$\therefore \text{E.S.} = 5315 + 0.105 = 531.605'$$

Reserve area at approach channel = 2.15 ft² = 1'

n = 0.02

$$\text{Then, } h_c = \left[\frac{2.15 \times 0.02}{1.496 (1.52)^{4/3}} \right]^2 \times 150 = 0.0174'$$

$$R = \frac{1101 \text{ ft}^2}{5140 \text{ ft}} = 11.5'$$

Then E.S.P. minor = 531.605 + 0.017 = 531.622

$$C = \frac{2070}{1101 \times 1.88} = 3.713$$

$C = 3.713$

$C = 3.713$

CAMP DRESSER & MOORE
Environmental Engineers
Boston, Mass.

CLIENT Abingdon Water Supply Corp. JOB NO. 514-20
PROJECT Abingdon Water Supply DATE CHECKED 9/25/78
DETAIL Hydrology CHECKED BY dib

PAGE 5 of 5
DATE 9/25/78
COMPUTED BY ...

$N = 20'$

Return $D = 440$ cfs MSR regulatory = 532.0

Channel depth = $532.0 - 512.0 = 20'$

Channel area = 1131.0 ∴ Channel velocity = $\frac{440 \text{ cfs}}{1131.0} = 3.89 \text{ fps}$

$\frac{V}{g} = 0.235'$

∴ $EFL = 512.0 + 0.235 = 512.235'$

Return via unimproved channel = $3.9 \text{ fps} = V$

$n = 0.02$

Then $n = \frac{1.49 \cdot V^{0.02}}{1.49 \cdot (2.0)^{0.02}} = 0.0397'$

$R = \frac{1131.0}{60 \cdot 20} = 11.31$

Then EFL reservoir = $512.235 + 0.039 = 512.274'$

$C = \frac{440}{104.572 \cdot 20^{0.5}}$

$C = 3.179$

$C = 3.282$

$N = 25'$

Return $D = 600$ cfs MSR regulatory = 532.5

Channel depth = $532.5 - 512.0 = 20.5'$

Channel area = 1167.2 ∴ Channel velocity = $\frac{600 \text{ cfs}}{1167.2} = 5.14 \text{ fps}$

$\frac{V}{g} = 0.162'$

∴ $EFL = 512.0 + 0.162 = 512.162'$

Return via unimproved channel = $3.9 \text{ fps} = V$

$n = 0.02$

Then $n = \frac{1.49 \cdot V^{0.02}}{1.49 \cdot (2.0)^{0.02}} = 0.066'$

$R = \frac{1167.2}{60 \cdot 20.5} = 12.053$

Then EFL reservoir = $512.162 + 0.066 = 512.228'$

$C = \frac{600}{104.572 \cdot 20.5^{0.5}}$

$C = 2.870$

$C = 2.870$

CAMP DRESSER & MCKEE
Environmental Engineers
Boston, Mass.

CLIENT U.S. Army Corps of Engineers JOB NO. 54-0-27
PROJECT Washburne Dam DATE CHECKED 7/25/78
DETAIL Channel CHECKED BY dlb

PAGE C-10
DATE 7/25/78
COMPUTED BY dlb

$N = 3.0$
 $Q = 7525 \text{ cfs}$ $W.S.G. \text{ velocity} = 5.22 \text{ ft}$

$\text{Channel depth} = 533.0 - 514.0 = 19.0'$

$\text{Channel area} = 1200 \text{ L}^2$ $\therefore \text{Channel velocity} = \frac{7525 \text{ cfs}}{1200 \text{ L}^2} = 6.269 \text{ fps}$

$V_c = 0.610'$
 $\therefore ESL = 533.0 + 0.61 = 533.61'$

$\text{Average velocity in rough channel} = 5.9 \text{ fps} = V$

$H_{fr} = \frac{V^2}{C^2} = \frac{5.9^2}{1.49^2} = 0.2934'$


$N = 0.02$
 $D = \frac{1.49}{N} = 74.5$
 40×2000

$\text{The ESLD amount} = 533.61 + 0.094 = 533.704'$

CAMP DRESSER & MAKER CLIENT Spillway Rehabilitation JOB NO. 911-0-277 PAGE 65
 Environmental Engineers PROJECT Spillway Rehabilitation DATE CHECKED 9/25/78 DATE 9/25/78
 Survey. Mgr. DETAIL Spillway CHECKED BY ALB COMPUTED BY ALB

Spillway Profile $310+3637.3$
 $y = 2.14x^2 = 2(20267)1/2$

W.S.	Distance	Elevation
530.0	07.0	—
530.5	115	3.060
531.0	1516	2.916
531.5	2370	2.811
532.0	4610	3.653
532.5	6010	3.757
533.0	7825	3.579



CAMP DRESSER & MILES
 Environmental Engineers
 Boston, Mass.

CLIENT: U.S. Environmental Agency JOB NO. 541-9-277
 PROJECT: Water Pollution Control DATE CHECKED: 9/26/78
 DETAIL: Appendix D CHECKED BY: ELB

PAGE: 2 of 2
 DATE: 9/26/78
 COMPUTED BY: ELB

Subsidence of Spillway Concrete

Because the C coefficient is determined from the Spillway Testing Curve between Elev 530.0 and 535.0 inches a maximum of 12 ft below design to 3.579 @ 9.0, we must give the lower exposure the benefit of the doubt and assume the coefficient C represents a conservative estimate of the maximum spillway. Since the only point given above 11-9.0 is $C = 15,000$ at Elev 535.0, we will adopt this and assume straight line between as follows:

Elev	Discharge	Calculated C
533.0	7,525 cfs	3,579
533.5	8,760	3,306
534.0	10,000	3,089
534.5	11,240	2,910
535.0	12,480	2,758
535.5	13,740	2,632
536.0	15,000	2,522
536.5	16,280	2,428
537.0	17,500	2,335

the reservoir full for three days, the spillway is high at 13,000 cubic feet a second the reservoir will not rise higher than 6 feet above Elevation 530. At the same time, at slight expense, by doing a little excavating and grading of the westerly weir site, and by building a shallow concrete cut-off to ledge there, an emergency overflow can be provided at Elevation 536 so that in case of an unanticipated extreme emergency, such as the chugging of the easterly spillway approach or discharge channels, or in case of supercolored and extremely high run-off with a full reservoir, a material rise in the reservoir surface above Elevation 536 will be practically prevented.

CROSS SECTION OF DAMS


The design of the section of the Dam is in keeping with general practice in large earth dams elsewhere, as can be seen from Fig. 8. A section of the Dam is shown in Fig. 1, and a tabulation comparing the Main Dam and Dike of Quabbin Reservoir with other large earth dams is given in the appended table:

The top width of 35 feet has been chosen in order to provide a considerable width through the embankment at the higher elevations near the flow line in order to permit constituting the abutment properly to as high an elevation as possible. The crestwidth of 20 feet between the spillway elevation and the top of embankment compares with 24 feet on the Cuckooville Dam, New York; 24 feet on the Paddy Creek Dam, North Carolina; 20 feet on the earth dams at Ashokan Reservoir, New York; 20 feet at Colville Mountain, Massachusetts (7 feet of which are flashboards); 19 feet on the Wyman Dam, Maine; 15 feet on the dikes of Wachusett Reservoir, Massachusetts; 15 feet on the Winoque Dam, New Jersey; 14 feet on the Davis Bridge Dam, Vermont; 13 feet on the Scituate Dam, Rhode Island, and 12 feet on the Saluda Dam, South Carolina. The downstream face has slopes of 1 on 2, 1 on 2 1/2, and 3 on 2 1/2, with berms 15 feet wide to intercept the drainage at intervals of 35 to 50 feet vertically. On the upstream slope a wave break of heavy riprap with a horizontal berm 5 feet above the spillway level has been used, following generally the design of the Wachusett Reservoir Dike and the Scituate Dam for the city of Providence, which has proved very satisfactory. Below this wave break a constant slope of 1 on 3, protected by riprap, has been carried to Elevation 458 for the Main Dam. Studies of the anticipated water levels during the filling of the reservoir and subsequent draw-downs during use indicate that to riprap below this elevation is not required. The wide berm at Elevation 458 is constructed of selected coarse material, with the idea it would take


flow would require a larger rock cut, but the material quarried from this site can be used for riprap on the upstream face of the dam. The discharge area of the reservoir is that of the watershed of the three branches of the Suds River, west, middle and east, and the three upper reaches of all three are largely forest land and woodland. There is the west branch are much steeper than those of the other two, which are steep only at the headwaters and which are much more marshy in places. Records of peak flows indicate that the west branch yields runoff most quickly. Most of the flood flow from that branch passes the site of the Dam before the flows from the east and middle branches arrive. This condition gives a flood flow curve which has a flat peak of long duration. The maximum flood peak for the period of record is 21 years at the West Ware gaging station near the Main Dam site is about 2,300 cubic feet per second and occurred April, 1923, or about 13 cubic feet per second per square mile. This peak lasted, roughly, three days. The largest New England flood of record in recent years occurred in November, 1927, and was felt probably most severely in Rhode Island, in the vicinity of the Scituate Reservoir. Such a flood on the Quabbin Reservoir watershed, if it came at a time when the reservoir was full, would result in a spillway discharge of about 2,000 cubic feet a second for a spillway weir 400 feet long. Records of large storms in western Massachusetts have produced rainfalls as high as 12 inches. Such a rainfall in a storm similar to the November, 1927, storm might produce a spillway discharge of about 3,000 cubic feet a second. A run-off of 12 inches in 24 hours would result in a spillway discharge of about 9,000 cubic feet a second.

Studies of both spillway sites revealed that, considering the use of excavated rock as riprap, the easterly site was more economical, and that it offered the better location structurally, as a discharge channel in rock all the way from the spillway weir to the river would be obtained. Because of these economic and structural advantages the easterly site has been adopted for location of the spillway weir and channel, but the natural features of the westerly site are also to be utilized by preparing a slight extra cost this latter site as an additional insurance against overtopping of the Dam in case of an unanticipated extreme emergency.

The easterly spillway channel will probably provide for carrying floods up to 10,000 cubic feet a second, without flooding out the rock discharge channel, and floods of considerably greater magnitude, even up to 15,000, will be carried with no important armor of the earth banks above the rock channel. There is room at that site for a concrete overflow to be built in rock valley between hills about 400 feet long. With




NO. 215 IS PROVIDED FOR EACH DATA. USE BY THE DIVISION.
CODING IN THESE SHEETS FROM CASES MADE BY INDIANAPOLIS, MASS. STATE
MAPS 1915



page C6d

GO-DART is a service mark of GO-DART, INC., 10000 N. 10th St., Suite 100, Scottsdale, AZ 85258

NO. 916 IS A SERVICE MARK OF GO-DART, INC., 10000 N. 10th St., Suite 100, Scottsdale, AZ 85258



CAMP ORESSER & MCKEE
Environmental Engineers
Boston, Mass.

CLIENT 25 Broad Street, Boston, Mass. JOB NO. 9125178
PROJECT 25 Broad Street, Boston, Mass. DATE CHECKED 9/25/78
DETAIL Hydrology CHECKED BY dlb

PAGE 62
DATE 9/25/78
COMPUTED BY dlb


(Column headings are in italics) Runoff of Precipitation - Hydrology - Spillway

Retention Elev.	Retention Area, A (sq. ft.)	Calc. Curve Inlet	Calc. S Curve Outlet	$\frac{S}{A}$	$\frac{S}{A} - \frac{2}{A}$	$\frac{S}{A} + \frac{2}{A}$
530	24,700	0	0	0	0	0
531	24,950	1500	24,925	600,264	600,264	601,514
532	25,190	4,100	43,235	1,207,410	1,205,740	1,209,560
533	25,440	5,930	75,310	1,200,090	1,217,120	1,233,210
534	25,680	7,920	100,770	2,152,536	2,164,576	2,170,536
535	25,900	9,930	126,540	3,062,752	3,057,212	3,067,512
536	26,120	11,830	152,570	3,692,112	3,684,752	3,699,112
537	26,340	13,230	173,300	4,256,810	4,250,830	4,263,810
538	26,550	15,240	205,245	4,766,925	4,759,042	4,774,925
<i>4" = 30.48" = 1310 mm.</i>						
<i>Adjusted Forward Rates of 5 Years - 52 = Hydrology Spillway</i>						
Retention Elev.	Retention Area, A (sq. ft.)	Calc. Curve Inlet	Calc. S Curve Outlet	$\frac{S}{A}$	$\frac{S}{A} - \frac{2}{A}$	$\frac{S}{A} + \frac{2}{A}$
530	24,700	0	0	0	0	0
531	24,950	1,500	24,925	600,264	600,264	601,514
532	25,190	4,100	43,235	1,207,410	1,205,740	1,209,560
533	25,440	7,525	75,310	1,920,120	1,916,510	1,923,310
534	25,680	10,000	100,770	2,152,536	2,153,636	2,143,636
535	25,900	12,330	126,540	3,062,752	3,056,512	3,068,992
536	26,120	15,000	152,570	3,692,112	3,684,652	3,699,112
537	26,340	16,133	163,060	3,246,150	3,257,985	3,254,115
538	26,550	17,276	173,550	3,189,910	3,191,222	3,203,510
539	26,760	18,246	173,500	3,206,960	3,212,932	3,205,932

CAMP DRESSER & MCKEE
Environmental Engineers
Boston, Mass.

CLIENT Robert R. Whitehead Inc. Inc. JOB NO. 54-0-27
PROJECT Quincy Water Treatment Plant DATE CHECKED 9/25/78
DETAIL Hydrograph CHECKED BY dlb

PAGE 50 of 50
DATE 9/25/78
COMPUTED BY dlb



CAMP DRESSER & MCKEE
Environmental Engineers
Boston, Mass.

CLIENT W. W. & L. L. Inc. - The Lee Inc.
PROJECT Water Pollution Control
DETAIL Hydrology

JOB NO. 51-2-507
DATE CHECKED 7/15/75
CHECKED BY ALB

PAGE 9 of 15
DATE 7/15/75
COMPUTED BY ALB

Calculation of Reservoir Outflows - Auxiliary Spillway Evaluated

Time No. *	Obs. Inflow (cfs)	Average Inflow (cfs)	$\Sigma - \frac{D}{2}$	$\Sigma + \frac{D}{2}$	Head on Spillway (ft)	Outflow (cfs)
0	0	0			0.10	43
1	25,140	12,570	60,076	77,656	0.12	56
2	50,280	25,140	72,375	110,310	0.13	107
3	63,100	32,705	109,935	146,640	0.23	169
4	75,920	42,500	146,225	235,775	0.39	234
5	151,340	113,530	235,137	345,757	0.54	629
6	226,740	189,645	327,237	536,552	0.79	1256
7	177,320	151,925	525,613	727,423	1.23	2125
8	127,610	105,245	725,722	829,124	1.92	2909
9	102,960	115,235	825,952	1001,244	1.66	3345
10	78,300	96,630	927,938	1093,613	1.90	3730
11	53,840	66,070	1024,646	1150,716	1.90	4110
12	29,380	41,610	1116,597	1193,207	1.96	4290
13	3,700	16,440	1193,920	1199,546	1.93	4350
14	5,560	3,100	1195,596	1199,696	1.99	4350
15	6,350	5,925	1195,346	1201,265	1.99	4320
16	7,200	6,995	1196,909	1203,624	1.99	4330
17	8,600	7,900	1199,312	1207,210	2.00	4410
18	10,000	9,300	1202,924	1212,124	2.00	4410
19	11,400	10,700	1207,719	1218,412	2.01	4444
20	12,800	12,100	1213,597	1226,256	2.25	4514
21	15,100	13,590	1221,656	1235,616	2.24	4542
22	17,500	16,200	1231,181	1247,441	2.26	4616
23	20,200	19,250	1242,587	1261,797	2.29	4712
24	22,800	21,550	1255,762	1277,912	2.11	4792
25	26,200	24,550	1271,717	1295,797	2.15	4810
26	29,500	27,200	1289,176	1325,276	2.13	5006
27	36,500	33,250	1317,347	1355,147	2.23	5166
28	45,500	40,000	1345,628	1385,162	2.29	5352
29	47,200	47,600	1380,960	1428,260	2.36	5576
30	60,000	55,250	1425,520	1479,370	2.44	5201
31	76,000	62,000	1474,501	1542,301	2.52	6132
32	92,000	82,200	1537,077	1621,077	2.67	6507
33	109,500	100,250	1615,659	1715,918	2.93	7015
34	125,000	116,250	1710,255	1827,023	3.01	7555
35	129,100	127,250	1821,070	1943,120	3.20	8019
36	133,200	131,150	1941,791	2075,946	3.40	9,512
37	134,000	133,600	2,066,220	2,189,800	3.41	9,733
38	133,300	133,650	2,192,685	2,324,335	3.81	9,527
39	129,200	127,200	2,219,785	2,450,822	4.01	10,225
40	125,000	127,100	2,342,055	2,569,155	4.20	10,476
41	119,000	129,200	2,465,580	2,687,580	4.53	10,540
42	113,000	116,000	2,674,207	2,796,207	4.56	11,249
43	105,300	109,250	2,781,197	2,893,447	4.71	11,761
44	92,800	98,250	2,880,516	2,979,576	4.26	12,125

* 30-minute increments

CAMP DRESSER & MCKEE
Environmental Engineers
Boston, Mass.

CLIENT: Agassiz Valley - North Duxbury
PROJECT: Agassiz Valley - North Duxbury
DETAIL: Estimated

JOB NO. 71517A
DATE CHECKED: 7/15/78
CHECKED BY: ALB

PAGE: 10
DATE: 7/15/78
COMPUTED BY: ALB

Line No.	Chg. 10/1/78	Chg. 10/1/78	5 - 0	4 + 0	Mod. on	Original
			ST	ST	Spillway	Q
			2	2		100
45	82,350	91,825	3,169,272	3,060,699	4.39	17,465
46	85,200	86,205	3,050,841	3,137,116	5.11	12,757
47	79,350	81,525	3,127,016	3,223,541	5.00	13,224
48	75,000	77,175	3,159,212	3,255,389	5.22	13,312
49	71,000	73,200	3,242,214	3,328,050	5.48	15,212
50	67,500	69,600	3,327,315	3,396,913	5.52	15,725
51	64,100	66,250	3,395,920	3,457,239	5.61	17,217
52	61,000	63,150	3,441,133	3,502,209	5.62	17,212
53	58,300	59,450	3,493,023	3,553,973	5.70	17,212
54	55,000	56,150	3,545,321	3,602,071	5.85	17,212
55	51,400	53,550	3,592,696	3,643,946	5.81	17,212
56	48,900	50,550	3,632,234	3,682,229	5.90	17,212
57	46,400	47,600	3,670,257	3,718,257	6.15	15,277
58	44,000	45,200	3,706,445	3,751,612	6.03	15,205
59	42,000	43,000	3,739,577	3,782,257	6.13	15,222
60	40,000	41,000	3,772,251	3,811,251	6.12	15,161
61	37,750	38,375	3,789,215	3,829,210	6.22	15,205
62	35,500	36,625	3,809,769	3,862,254	6.26	15,266
63	33,500	34,500	3,842,922	3,892,259	6.39	15,212
64	31,500	32,500	3,872,031	3,922,252	6.32	15,212
65	29,850	30,675	3,902,002	3,952,677	6.35	15,212
66	28,300	29,025	3,910,091	3,982,116	6.38	15,275
67	26,850	27,525	3,926,879	3,994,003	6.40	16,024
68	25,500	26,175	3,941,312	3,967,293	6.22	16,275
69	24,250	24,975	3,954,766	3,979,661	6.24	16,126
70	23,000	23,625	3,966,975	3,990,502	6.26	16,172
71	21,800	22,400	3,977,700	4,000,100	6.27	16,212
72	20,600	21,200	3,987,271	4,008,271	6.29	16,254
73	19,450	20,025	3,995,614	4,015,634	6.50	16,220
74	18,300	18,975	4,002,760	4,021,635	6.51	16,220
75	17,150	17,975	4,008,252	4,026,613	6.52	16,220
76	16,000	16,825	4,013,629	4,030,724	6.52	16,220
77	14,800	15,600	4,017,292	4,033,294	6.53	16,220
78	13,600	14,400	4,021,062	4,036,252	6.53	16,220
79	12,400	13,200	4,023,507	4,038,167	6.53	16,220
80	11,200	12,000	4,025,210	4,039,210	6.54	16,220
81	10,000	10,800	4,026,265	4,039,665	6.54	16,220
82	8,800	9,600	4,026,710	4,039,510	6.54	16,220
83	7,600	8,400	4,026,552	4,038,216	6.54	16,220
84	6,400	7,200	4,025,555	4,037,605	6.52	16,220
85	5,200	6,000	4,024,257	4,035,207	6.52	16,220
86	4,000	4,800	4,022,524	4,032,762	6.52	16,220
87	2,800	3,600	4,020,229	4,031,229	6.52	16,220
88	1,600	2,400	4,018,301	4,029,301	6.52	16,220
89	400	800	4,015,289	4,025,023	6.51	16,220
90	0	0	4,012,124	4,021,272	6.51	16,220

Table 5.5 Values of C in the Formula $Q = C L H^{3/2}$ for Broad-topped Weirs with Crests Inclined Slightly Downward

Crest	Head in feet, H									
	0.2	0.3	0.4	0.5	0.6	0.7	0.8	0.9	1.0	1.2
Level	2.70	2.72	2.74	2.76	2.78	2.80	2.82	2.84	2.86	2.88
Slope = 0.01 in	2.67	2.69	2.71	2.73	2.75	2.77	2.79	2.81	2.83	2.85
Slope = 0.02 in	2.64	2.66	2.68	2.70	2.72	2.74	2.76	2.78	2.80	2.82

Table 5.3 Values of C in the Formula $Q = C L H^{3/2}$ for Broad-topped Weirs

Weir height, H , in feet	Head in feet, H									
	0.2	0.3	0.4	0.5	0.6	0.7	0.8	0.9	1.0	1.2
0.2	2.70	2.72	2.74	2.76	2.78	2.80	2.82	2.84	2.86	2.88
0.3	2.70	2.72	2.74	2.76	2.78	2.80	2.82	2.84	2.86	2.88
0.4	2.70	2.72	2.74	2.76	2.78	2.80	2.82	2.84	2.86	2.88
0.5	2.70	2.72	2.74	2.76	2.78	2.80	2.82	2.84	2.86	2.88
0.6	2.70	2.72	2.74	2.76	2.78	2.80	2.82	2.84	2.86	2.88
0.7	2.70	2.72	2.74	2.76	2.78	2.80	2.82	2.84	2.86	2.88
0.8	2.70	2.72	2.74	2.76	2.78	2.80	2.82	2.84	2.86	2.88
0.9	2.70	2.72	2.74	2.76	2.78	2.80	2.82	2.84	2.86	2.88
1.0	2.70	2.72	2.74	2.76	2.78	2.80	2.82	2.84	2.86	2.88
1.2	2.70	2.72	2.74	2.76	2.78	2.80	2.82	2.84	2.86	2.88


Table 5.9 Values of C in the Formula $Q = C L H^{3/2}$ for Weirs of Triangular Cross Section with Vertical Upstream Face and Slipping Downstream Face

Shape of weir	Head in feet, H									
	0.2	0.3	0.4	0.5	0.6	0.7	0.8	0.9	1.0	1.2
100°	2.60	2.62	2.64	2.66	2.68	2.70	2.72	2.74	2.76	2.78
75°	2.50	2.52	2.54	2.56	2.58	2.60	2.62	2.64	2.66	2.68
50°	2.40	2.42	2.44	2.46	2.48	2.50	2.52	2.54	2.56	2.58
25°	2.30	2.32	2.34	2.36	2.38	2.40	2.42	2.44	2.46	2.48

Table 5.4 Values of C in the Formula $Q = C L H^{3/2}$ for Mouths of Broad-topped Weirs with Round-Edged Upstream Corner

Name of experiment	Head in feet, H									
	0.2	0.3	0.4	0.5	0.6	0.7	0.8	0.9	1.0	1.2
1	2.70	2.72	2.74	2.76	2.78	2.80	2.82	2.84	2.86	2.88
2	2.70	2.72	2.74	2.76	2.78	2.80	2.82	2.84	2.86	2.88
3	2.70	2.72	2.74	2.76	2.78	2.80	2.82	2.84	2.86	2.88
4	2.70	2.72	2.74	2.76	2.78	2.80	2.82	2.84	2.86	2.88
5	2.70	2.72	2.74	2.76	2.78	2.80	2.82	2.84	2.86	2.88
6	2.70	2.72	2.74	2.76	2.78	2.80	2.82	2.84	2.86	2.88
7	2.70	2.72	2.74	2.76	2.78	2.80	2.82	2.84	2.86	2.88
8	2.70	2.72	2.74	2.76	2.78	2.80	2.82	2.84	2.86	2.88
9	2.70	2.72	2.74	2.76	2.78	2.80	2.82	2.84	2.86	2.88
10	2.70	2.72	2.74	2.76	2.78	2.80	2.82	2.84	2.86	2.88

C 102 or 13



AD-A155 515

NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS
WINSOR DAM (MA 00588)...(U) CORPS OF ENGINEERS WALTHAM
MA NEW ENGLAND DIV SEP 78

2/3

UNCLASSIFIED

F/G 17/17

NI

END
DATE
FORM
9-78



MICROCOPY RESOLUTION TEST CHART
 NATIONAL BUREAU OF STANDARDS-1963-A

Excavation
 Section was excavated in 20' x 20' area - 20' x 20' unit with an
 existing depth of 2.0' existing on the site in 1978. Excavation
 to 10' below ground surface or until 10' below existing ground surface or
 until 10' below 7' elevation or lower (whichever)

<u>Station</u>	<u>Depth</u>	<u>Width</u>	<u>Volume</u>	<u>Excavated</u>	<u>Total</u>
5360	0	0	0	15,000	15,000
5363	0.2	24	15.28	15,500	15,515
5364	0.4	25	132.9	16,000	16,133
5366	0.6	25	244.0	16,500	16,744
5369	0.8	25	575.7	17,000	17,576
5370	1.0	25	846	17,500	18,346

CAMP DRESSER & MCKEE
 Environmental Engineers
 Boston, Mass.

CLIENT Habitat Alliance - 1445 Bay St. Boston, MA 02115
 PROJECT Bay State - 1445 Bay St. Boston, MA 02115
 DETAIL 1445 Bay St

PAGE 11
 DATE 1/15/12
 CHECKED BY ALB
 COMPUTED BY 1/15/12


Calculations are based on - Average - Assumed Soil was tested.

Time No.	Cost (Total)	Charge (Rate)	$\Sigma - \Sigma$ AT =	$\Sigma + \Sigma$ AT =	Hourly Expense	Overhead (%)
55	21,800	53,250	3,590,166	3,615,516	5.91	16.775
56	20,800	52,350	3,629,169	3,674,510	5.97	16.824
57	21,300	52,600	3,661,556	3,715,189	6.02	16.876
58	22,000	53,200	3,696,604	3,757,899	6.05	16.920
59	22,000	53,400	3,732,515	3,802,515	6.06	16.970
60	22,000	53,600	3,769,551	3,849,251	6.07	17.020
61	22,750	54,275	3,807,553	3,897,553	6.06	17.070
62	23,500	54,975	3,846,723	3,947,559	6.06	17.120
63	24,250	55,700	3,887,163	3,999,263	6.05	17.170
64	25,000	56,450	3,928,861	4,052,361	6.05	17.220
65	25,750	57,225	3,971,846	4,107,321	6.02	17.270
66	26,500	58,025	4,016,636	4,164,271	6.02	17.320
67	27,250	58,850	4,063,271	4,223,266	6.02	17.370
68	28,000	59,675	4,111,741	4,283,559	6.03	17.420
69	28,750	60,525	4,162,066	4,345,266	6.03	17.470
70	29,500	61,400	4,214,246	4,408,451	6.02	17.520

CAMP DRESSER & MCKEE
Environmental Engineers
Boston, Mass.

CLIENT U.S. Army Corps of Engineers JOB NO. 541-2-10
PROJECT Spill - Oil Spill DATE CHECKED 9/25/78
DETAIL Hydrology CHECKED BY dlm

PAGE 12 of 12
DATE 9/25/78
COMPUTED BY dlm



CAMP DRESSER & MAKEE
Environmental Engineers
Boston, Mass.

CLIENT WINDY HILL
PROJECT WINDY DAM
DETAIL WINDY RESERVOIR

JOB NO. 861-9-87
DATE CHECKED 9/25/78
CHECKED BY ALD

PAGE 01
DATE 3-14-72
COMPUTED BY ALD

DAM FAILURE ANALYSIS

SPILLWAY CREST EL. 530.0
EMERGENCY (OVERFLOW) SPILLWAY CREST EL. 526.0
TOP OF DAM EL. 550.0

IT IS PHYSICALLY IMPOSSIBLE FOR THE RESERVOIR WATER SURFACE ELEV. TO REACH THE TOP OF DAM (EL. 550.0), AS THE EMERGENCY SPILLWAY WILL RELEASE OVERFLOWS AT EL. 526.0. ALSO THE ESTIMATED PUF SURCHARGE POOL LEVEL IS EL. 536.2

∴ ASSUME WATER LEVEL AT EL. 536.0 AT TIME OF FAILURE

STORAGE AT EL. 536.0 = 1,417,500 cu ft. of 428 billion gal.

WINDY DAM

HEIGHT AT EL. 550.0 = 170'
" " " 526.0 = 136'

LENGTH = 2,840', ASSUME $W_b = 20\%$
∴ $W_b = 2,840 \times .2 = 468 \text{ ft.}$

$$Q_p = 8/27 \times 468 \times (32.2)^{3/2} (136)^{5/2} = 1,553,000 \text{ cfs}$$

GIDDINGS DIKE

HEIGHT AT EL. 550.0 = 135'
" " " 526.0 = 121'

LENGTH = 2,140', ASSUME $W_b = 20\%$
∴ $W_b = 2,140 \times .2 = 428 \text{ ft.}$

$$Q_p = 8/27 \times 428 \times (32.2)^{3/2} (121)^{5/2} = 956,000 \text{ cfs}$$

MAIN SPILLWAY

W.S. ELEV. 536.0
MIN. ELEV. OF LEDGE EL. 526.0

Let $W_b = 40\%$ of 370 ft. = 148 ft.

$$Q_p = 8/27 (148) (32.2)^{3/2} (14)^{5/2} = 13,575 \text{ cfs}$$

less than test pool

Henry C. Wick - Dan Ingalls Program for Corps of Engineers June 29, 1978
Quabbin Reservoir - Field Trip - H.P. Wick & Mrs. Hollaway - Hill
Quabbin plus @ 20 January 84 - WDC Office Roger Wood, C. Lawrence
SCE Fisher - CDL

Water Division - 84-100
9th floor

Tel: 6.000 is cost @ Quabbin for
522.73 BCB }
Tel: US E. ~~522.73~~ } BCB to USGS - not 5.65 as originally bid
"Red"

(based on original construction) - Harold W. Wiley
Harold Wiley, Sept.

Public Document No. 147 - Quabbin Dam @ Quabbin - Wakefield - Vermont
Geological Data - Beaver Brook Data

In 22 years that Henry Wiley has been here, no modifications have been made to
more dam, dikes or spillway. Final design was added to include works re
1966 plan by CDL - cost by R.M. Wick

CAMP DRESEN & MOORE
Environmental Engineers
Boston, Mass.

CLIENT Robert White - Pine Log Pond JOB NO. 34-0-33
PROJECT Design for Open Channel DATE CHECKED _____
DETAIL Outlet Structure CHECKED BY _____

PAGE E/26
DATE June 29, 1978
COMPUTED BY White

Dimensions of Basin of Pond - 8' diam. to 16' diam.

Outlet Spillway - 10:15 am to 11:45 am

Spillway Length - 900 ft.

Crest Elev. 530.0 (BCB) - stone capped wall flow

Elev. 528.0 (BCB) - 5 bay spillway with 2' ft. thick boards
(3 bays @ 8')

White - waves - see plans

Location - 6000 NE of main white works

Number of bays of gates - None

Note: wave and organic, emergentlike water surface just E. of spillway

rectification wall. spillway depth exceeds 6' - No heavy surge of water

branches just W. & E. of spillway. 10 ft. of crest should be removed

Note: left (out.) rock face of spillway discharge channel shows

considerable weathering with rock deposited as channel about midway

between spillway and stone arch bridge ds. covered by M.D.

Note: check out channel approach upstream of weir structure about 100' W. of

spillway with thick boards. Channel narrows to 30'-60' from

10-15' width or.

CAMP DRESSER & MCKEE
Environmental Engineers
Beverly, Mass.


CLIENT Hubbard Park - Deer Island JOB NO. 54-0-20
PROJECT Construction of Camp at Hubbard Park DATE CHECKED _____
DETAIL Spillway CHECKED BY _____

PAGE 3 of 6
DATE 11/22/78
COMPUTED BY Miller

Initial Work - 10:30 am to 1:00 pm

Inspection, installed structural (R. Wood) and gaskets (C. Lawrence)
at structure & equipment. Note: handling work installed in 1966 by R.H. White
with plans & specs. by CDL

Emergency Spillway - 1 pm to 1:30 pm



Earth overflow section - slopes upward about 4' from
structure which is 2' above MSL - i.e. spillway 6' above MSL.
Good grass and soil cover - a few minor places where soil
readily eroded. Leads to sand/crusher based stone spillway before
dropping to natural terrain.

Power House - 2 pm to 3:30 pm

Inspection installed structural (R. Wood) and gaskets (C. Lawrence)
at structure & equipment. We also checked 400 lbs. of bypass around base power
slab in 1966 done

CAMP CHECKER & NOTICE
Environmental Engineers
Boston, Mass.

CLIENT Hubert H. Hensley - Executive Director NO. 54-9-87
PROJECT Beaver Dam for Dept. of Fisheries DATE CHECKED _____
DETAIL Beaver Dam for Dept. of Fisheries CHECKED BY _____

PAGE E-3 of 6
DATE June 29/1988
COMPUTED BY CE/MLR

Robert Hensley, Department of Goodhue Dam

Beaver Dam, about base of the 9. m Dam

12' wide x 9' high, corr. with plate oak - L-203

CAMP DRESSER & MCKEE
Environmental Engineers
Rochester, Mass.

CLIENT Worcester County - Dept. of Highway JOB NO. 24-037
PROJECT Design for Dept. of Highway DATE CHECKED _____
DETAIL Quabbin Reservoir CHECKED BY _____

PAGE 3 of 6
DATE June 29, 1978
COMPUTED BY W. Fisher

QUABBIN RESERVOIR - Elevation - Capacity Data

<u>Elev.</u> <u>(ft.)</u>	<u>Cap.</u> <u>(MG)</u>	<u>Elev.</u> <u>(ft.)</u>	<u>Cap.</u> <u>(MG)</u>
501.0	214,000	523.0	359,100
502.0	219,700	524.0	366,600
503.0	225,400	525.0	374,100
504.0	231,200	526.0	381,600
505.0	237,100	527.0	389,100
506.0	243,100	528.0	396,600
507.0	249,100	529.0	404,100
508.0	255,100	530.0	412,240
509.0	261,200	530.2	413,929
510.0	267,200	530.4	415,629
511.0	274,100	530.6	417,340
512.0	280,700	530.8	419,063
513.0	287,800	531.0	420,800
514.0	294,100	531.2	422,549
515.0	300,900	531.4	424,310
516.0	307,800	531.6	426,083
517.0	314,900	531.8	427,868
518.0	322,100	532.0	429,670
519.0	329,400	532.2	431,485
520.0	336,700	532.4	433,322
521.0	344,100	532.6	435,172
522.0	351,600	532.8	437,038
		533.0	438,920

CAMP DRESSER & MOORE
 Environmental Engineers
 Boston, Mass.

CLIENT Wachusett Regional Water Treatment Plant JOB NO. 542-822
 PROJECT Design for Spill to Reservoir DATE CHECKED _____
 DETAIL Quarbin Reservoir CHECKED BY _____

PAGE 55 of 64
 DATE June 21, 1979
 COMPUTED BY DB

QUARBIN RESERVOIR - Spillage to Quabbin River

<u>1978</u>	<u>W.B. Elev.</u>	<u>Feet</u>	<u>1976</u>	<u>W.B. Elev.</u>	<u>Feet</u>
April 16	520.01	2.0	April 2	520.02	6.0
17	04	12.0	3	08	21
18	07	26.0	4	13	63
19	15	70.0	5	14	70
20	21	129.0	6	13	63
21	27	188.0	7	11	49
22	31	234.0	8	10	43.2
23	32	245.0	9	08	31
24	34	269.0	10	04	12
25	34	269.0	11	03	9
26	33	257.0	12	530.01-02	07.4
27	33	257.0			
28	31	234.0			
29	29	211.0			
30	27	188.0			
May 1	26	178.0			
2	21	129.0			
3	15	70.0			
4	11	44.0			
5	09	37.0			
6	05	16.3			
7	05	16.0			
8	520.00	0			

Foot - max spillage in 1961

Highest Elev. 531.03 Apr. 18, 1953

Lowest Elev. 495.70 Nov. 5, 1967

E 646

Nov 4, 1976 - 164.8 MG total
Nov 1, 1976 253.0 cfb } more note
El. 529.89 163.5 mgd }
no bags - 5 bags open

Splitters discharged this year - first time since 1976 - no splitters
from 1961 till 1976

April 24, 1978 - El. 532.34 269.0 cfb - 173.8 mgd
all bags no place - no bags open

APPENDIX E
INFORMATION CONTAINED IN
THE NATIONAL INVENTORY OF DAMS

INVENTORY OF DAMS IN THE UNITED STATES

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20
IDENTITY NUMBER	STATE	COUNTY	CITY	COUNTY	CITY	NAME	LATITUDE (NORTH)	LONGITUDE (WEST)	REPORT DATE DAY	REPORT DATE MO	REPORT DATE YR								
1A	MD	NED	MA	015	01	QUABBIN WINSON DAM	4217.0	7220.6	06	SEPT	70								

POPULAR NAME	NAME OF IMPONDMENT
QUABBIN WINDSON DAM	QUABBIN WINDSON DAM
RIVER OR STREAM	NEAREST DOWNSTREAM CITY-TOWN-VILLAGE
SMIFT RIVER	VALLAGE
NAME	DIST FROM DAM (MI.)
	0
POPULATION	0670

TYPE OF DAM	YEAR COMPLETED	PURPOSES	STATE	HYDRAULIC	IMPOUNDING CAPACITIES	DIST UMN	FED N	PRV/PED	SCS A	VER/DATL
HECTPG	1939	9	MD	170	1010000	1265200	N	N	N	28AUG70

REMARKS											
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)
IRB	SWIMWAY	MAXIMUM DISCHARGE (CFS)	VOLUME OF DAM (CU FT)	POWER CAPACITY (KW)	NAVIGATION LOCKS						
1	2000	C	405	15000	4000000						

OWNER	ENGINEERING BY
METROPOLITAN DIST, COMM	METROPOLITAN DIST, COMM
	BENJAMIN FOSTER COMPANY

DESIGN	REGULATORY AGENCY
NONE	CONSTRUCTION
	OPERATION
	MAINTENANCE
	MA DPA

INSPECTION BY	INSPECTION DATE
MALEY & ALDRICH, INC.	DAY
	MO
	YR
	29 JUN 70
	AUTHORITY FOR INSPECTION
	PUBLIC LAW 92-367

REMARKS	

INVENTORY OF DAMS IN THE UNITED STATES

STATE	COUNTY	NAME	LATITUDE (NORTH)	LONGITUDE (WEST)	REPORT DATE
MA	DIST. 01	QUABBIN SPILLWAY	4217.2	7220.5	08SEP78

POPULAR NAME	NAME OF IMPONDMENT
QUABBIN RESEKVOIN	QUABBIN RESEKVOIN
RIVER OR STREAM	CITY/TOWN/VILLAGE
SWIFT RIVER	WAKE
POPULATION	POPULATION
8079	0

TYPE OF DAM	YEAR COMPLETED	PURPOSES	STAGE HYDRAULIC HEIGHT (FT.)	IMPOUNDING CAPACITIES (ACR.)	DISTS UNN FED M PHV/FED SES A VEN/DATE
GNPC	1938	8	10	1010000	NED N N N N
				1205200	

REMARKS

SPILLWAY (FT.)	MAXIMUM DISCHARGE (CFS)	VOLUME CAPACITY (CFT)	POWER CAPACITY (KW)	NAVIGATION LOCKS
3	405	55	15000	NO

OWNER	ENGINEERING BY
METROPOLITAN DIST. COMM	METROPOLITAN DIST. COMM

DESIGN	REGULATORY AGENCY
NONE	OPERATION
	MAINTENANCE
	MA DPH

INSPECTION BY	INSPECTION DATE
MALEY & ALUMICH, INC.	29JUN78
	AUTHORITY FOR INSPECTION
	PUBLIC LAW 92-367

REMARKS

INVENTORY OF DAMS IN THE UNITED STATES

FEDERAL PROJECT NUMBER	STATE PROJECT NUMBER	COUNTY	NAME	LATITUDE (COORDINATE)	LONGITUDE (COORDINATE)	REPORT DATE
VA 590 MED	VA 015 01		QUABBIN GOODNOUGH DIKE	4217.9	7210.0	003EP70

POPULAR NAME	NAME OF IMPROVEMENT
QUABBIN RESERVOIR	QUABBIN RESERVOIR
NEAREST DOWNSTREAM CITY-TOWN-VILLAGE	POPULATION
WARE	0
NEAREST BEAVER BRUUK	POPULATION
	0

TYPE OF DAM	YEAR COMPLETED	PURPOSES	DAYS IMPROVEMENT	MOUNDING CAPACITY	DIST OWN	FED N	PRV/PED	SCS A	VLM/DATE	
RECIPG	1934	3	200	135	1010000	1265200	MEG	N	N	20AUG70

REMARKS

D/S	SPILLWAY	MAXIMUM OPERATING HEAD (FT)	VOLUME OF DAM (CU FT)	POWER CAPACITY (KW)	UNLOCKED	LOCKED	NAVIGATION LOCKS
1	2140	N	2700000				

OWNER	ENGINEERING BY	CONSTRUCTION BY
METROPOLITAN DIST.COMM	METROPOLITAN DIST.COMM	ARTHUR A. JOHNSON CORP.

REGULATORY AGENCY	OPERATION	MAINTENANCE
NONE	NONE	NA DPH

INSPECTION BY	INSPECTION DATE
MALEY & ALDRICH, INC.	29JUN70
	AUTHORITY FOR INSPECTION
	PUBLIC LAW 42-307

REMARKS
40-EMBANKMENT CONTRACT

INVENTORY OF DAMS IN THE UNITED STATES

STATE MA	COUNTY MID	TOWNSHIP 015	CITY 01	NAME QUABBIN SPILLWAY	LATITUDE (NORTH) 42 17.2	LONGITUDE (WEST) 72 20.3	REPORT DATE DAY MO YR UNSLP/8
-------------	---------------	-----------------	------------	--------------------------	-----------------------------	-----------------------------	---

POPULAR NAME QUABBIN RESERVOIR	NAME OF IMPONDMENT QUABBIN RESERVOIR
RIVER OR STREAM 01 08 SWIFT RIVER	NEAREST DOWNSTREAM CITY-TOWN-VILLAGE U
POPULATION 8079	POPULATION

TYPE OF DAM GAPG	YEAR COMPLETED 1930 S	PURPOSES 10 10	HYDRAULIC CAPACITY NORMAL MED	INSTALLED PROPOSED NO	POWER CAPACITY MED	NAVIGATION LOCKS N	DIST N	UN F E D M N	P R V P F E D N	S C S A N	V E H / D A T E 28AUG78
---------------------	--------------------------	-------------------	-------------------------------------	--------------------------	-----------------------	-----------------------	-----------	-----------------	--------------------	--------------	----------------------------

REMARKS

DIS. NO. 3	SPILLWAY TYPE 3	SPLASH CHANCE 35	SALVAGE OF DAM 15000	NO. OF DAMS 1	POWER CAPACITY 100000	NAVIGATION LOCKS
------------	-----------------	------------------	----------------------	---------------	-----------------------	------------------

OWNER METROPOLITAN DIST. COUN.	ENGINEERING BY METROPOLITAN DIST. COUN.
CONSTRUCTION BY	

DESIGN NONE	REGULATORY AGENCY NONE
CONSTRUCTION NONE	OPERATION MAINTENANCE

INSPECTION BY MALLEY & ALUMICH, INC.	INSPECTION DATE 29 JUL 78
AUTHORITY FOR INSPECTION PUBLIC LAW 92-367	

REMARKS



INVENTORY OF DAMS IN THE UNITED STATES

STATE	COUNTY	TOWNSHIP	SECTION	RANGE	COM. DIST.	NAME	LATITUDE (NORTH)	LONGITUDE (WEST)	REPORT DATE (DAY MO YR)
VA	590	MED	MA	015	01	QUABBIN GUDDNOUGH DIKE	4217.9	7219.0	0082P70

POPULAR NAME		NAME OF IMPONDMENT	
QUABBIN RESERVOIR		QUABBIN RESERVOIR	
BASED ON STREAM	NEAREST DOWNSTREAM CITY-TOWN-VILLAGE	DIST FROM DAM (MILES)	POPULATION
01 00 BEAVER BROOK	NARE	0	8670

TYPE OF DAM	YEAR COMPLETED	PURPOSES	HYDRAULIC POWER	HYDRAULIC HEAD (FT.)	IMPONDING CAPACITY (ACRES-FT.)	DIST ONN (MILES)	FED N	PRIVATED	SEC A	VLR/DATL

REMARKS

D/S	SHELLWAY TYPE	VOLUME OF DAM (CU YD)	POWER CAPACITY (KW)	NAVIGATION LOCKS

OWNER	ENGINEERING BY	CONSTRUCTION BY
METROPOLITAN DIST, COMM	METROPOLITAN DIST, COMM	ARTHUR A. JOHNSON CORP.

DESIGN	CONSTRUCTION	OPERATION	MAINTENANCE
NONE	NONE	NONE	MA DPM

INSPECTION BY	INSPECTION DATE (DAY MO YR)	AUTHORITY FOR INSPECTION
MALEY & ALUMICH, INC.	29JUN70	PUBLIC LAW 42-367

REMARKS

48-EMBARMENT CONTRACT

INVENTORY OF DAMS IN THE UNITED STATES

PROJECT NUMBER	STATE	COUNTY	DISTRICT	NAME	LATITUDE (NORTH)	LONGITUDE (WEST)	REPORT DATE (DAY MO YR)
500 MED	MA	015 01		QUABBIN WINSLOW DAM	4217.0	7220.0	00SEP70

POPULAR NAME	NAME OF IMPROVEMENT
QUABBIN RIVER	QUABBIN RESERVOIR

OWNER ON STREAM	NEAREST DOWNSTREAM CITY-TOWN-VILLAGE	POPULATION
STATE	WARE	0

TYPE OF DAM	YEAR COMPLETED	PURPOSES	DESIGNER	ENGINEERING CAPACITIES (MW) (KVA) (HP)
MULTI	1939	S		200 170 101000 1265200

REMARKS	
DIST UNN FLD N PRV/SED 960 A VEN/DATE N N N 20AUG70	

DESIGN	CONSTRUCTION	OPERATION	MAINTENANCE
NONE	NONE	NONE	MA DPA

OWNER	ENGINEERING BY	CONSTRUCTION BY
METROPOLITAN DIST, CUMM	METROPOLITAN DIST, CUMM	BENJAMIN FOSTER COMPANY

DESIGN	CONSTRUCTION	OPERATION	MAINTENANCE
NONE	NONE	NONE	MA DPA

INSPECTION BY	INSPECTION DATE (DAY MO YR)	AUTHORITY FOR INSPECTION
HALEY & ALURICH, INC.	29JUN70	PUBLIC LAN 92-307

REMARKS	
---------	--

INVENTORY OF DAMS IN THE UNITED STATES

STATE	COUNTY	TOWNSHIP	NAME	LATITUDE (NORTH)	LONGITUDE (WEST)	REPORT DATE (MO/YR)
MA	SPO	NED	QUABBIN SPILLWAY	4217.2	7220.5	08SEP78

POPULAR NAME	NAME OF FOUNTAIN
	QUABBIN RESERVOIR
NEAREST DOWNSTREAM CITY - TOWN - VILLAGE	POPULATION
	0

TYPE OF DAM	PURPOSES	NEAREST DOWNSTREAM CITY - TOWN - VILLAGE
GRPC	1938 S	0

DIST	UPN	FED	M	PRV	FED	S	A	VEN	DATE
									20AUG78

REMARKS	REMARKS

OWNER	ENGINEERING BY	CONSTRUCTION BY
METROPOLITAN DIST. COMM	METROPOLITAN DIST. COMM	

DESIGN	CONSTRUCTION	OPERATION	MAINTENANCE
NONE	NONE	NONE	MA

INSPECTION BY	INSPECTION DATE
MALLEY + ALDRICH, INC.	29JUN78

AUTHORITY FOR INSPECTION	REMARKS
PUBLIC LAW 92-367	

DISPOSITION FORM

For use of this form, see AR 340-15, the proponent agency is TAGCEN.

REFERENCE OR OFFICE SYMBOL

NEDED-E

SUBJECT

Dam Inspection Final Report

TO

Chief, Design Branch
Chief, F & M Branch
Chief, Water Control Branch

FROM

Chairman,
Dam Safety Review Board

DATE 4 Oct. 78

CMT 1

1. Attached is a single copy of the final report for Winsor Dam, Quabbin Spillway & Dam, Identity No. MA 00580, 00589 & 00590.
Good enough Dike
2. Please ascertain that the report is acceptable in accordance with your Branch comments or instructions given to the Architect-Engineer at the Review Board Meeting.
3. If acceptable, retain the copy for your files and be prepared to sign the (master) approval sheet on 10 Oct.
4. If the report requires further work or correction, notify the undersigned as soon as the determination is made.
5. The cost code for this review is ABA020700000000.



TIERSCH

Incl
as

DISPOSITION FORM

For use of this form, see AR 340-15, the proponent agency is TAGCEN.

REFERENCE OR OFFICE SYMBOL

NEDED-E

SUBJECT

Dam Inspection Final Report

TO

Chief, Design Branch
Chief, F & M Branch
Chief, Water Control Branch

FROM

Chairman,
Dam Safety Review Board

DATE 4 Oct. 78

CMT 1

1. Attached is a single copy of the final report for Winsor Dam, Quabbin Spillway & Goodough Dike, Identity No. MA 00500, 00509 & 00590.
2. Please ascertain that the report is acceptable in accordance with your Branch comments or instructions given to the Architect-Engineer at the Review Board Meeting.
3. If acceptable, retain the copy for your files and be prepared to sign the (master) approval sheet on 9 Oct.
4. If the report requires further work or correction, notify the undersigned as soon as the determination is made.
5. The cost code for this review is ABA020700000000.



TIERSCH

Incl

as

This Phase I Inspection Report on Windsor Dam, Quabbin Spillway & Goodnough Dike has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the Recommended Guidelines for Safety Inspection of Dams, and with good engineering judgment and practice, and is hereby submitted for approval.

Charles G. Tiersch

CHARLES G. TIERSCH, Chairman
Chief, Foundation and Materials Branch
Engineering Division

Fred J. Ravens, Jr.

FRED J. RAVENS, Jr., Member
Chief, Design Branch
Engineering Division

Saul Cooper

SAUL COOPER, Member
Chief, Water Control Branch
Engineering Division

APPROVAL RECOMMENDED:

Joe B. Fryar

JOE B. FRYAR
Chief, Engineering Division

DATE
LMED
— 8