

MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A

2

AD-A155 641

MERRIMACK RIVER BASIN
FITCHBURG, MASSACHUSETTS

OVERLOOK RESERVOIR DAM AND DIKE

DAM _____ MA 00876
DIKE _____ MA 01335

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS

WALTHAM, MASS. 02154

DTIC
ECTE
JUN 24 1985
S G D

DISTRIBUTION STATEMENT A
Approved for public release
Distribution Unlimited

DTIC FILE COPY

AUGUST 1980

85 6 3 022

DISCLAIMER NOTICE

**THIS DOCUMENT IS BEST QUALITY
PRACTICABLE. THE COPY FURNISHED
TO DTIC CONTAINED A SIGNIFICANT
NUMBER OF PAGES WHICH DO NOT
REPRODUCE LEGIBLY.**

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER MA 00876/01335	2. GOVT ACCESSION NO. AD-A155641	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Overlook Reservoir Dam and Dike NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS		5. TYPE OF REPORT & PERIOD COVERED INSPECTION REPORT
		6. PERFORMING ORG. REPORT NUMBER
7. AUTHOR(s) U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION		8. CONTRACT OR GRANT NUMBER(s)
9. PERFORMING ORGANIZATION NAME AND ADDRESS		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
11. CONTROLLING OFFICE NAME AND ADDRESS DEPT. OF THE ARMY, CORPS OF ENGINEERS NEW ENGLAND DIVISION, NEDED 424 TRAPELO ROAD, WALTHAM, MA. 02254		12. REPORT DATE August 1980
		13. NUMBER OF PAGES 75
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Cover program reads: Phase I Inspection Report, National Dam Inspection Program; however, the official title of the program is: National Program for Inspection of Non-Federal Dams; use cover date for date of report.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) DAMS, INSPECTION, DAM SAFETY, Merrimack River Basin Fitchburg Massachusetts Tributary-North Nashua River		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) The dam is a 370+ ft. long, 47+ ft. high, earth embankment structure with a masonry core wall and a stone masonry gatehouse. The dam and dike are generally in fair condition. It is small in size with a high hazard potential. The reservoir receives inflow from a drainage area of 40 acres.		



DEPARTMENT OF THE ARMY
 NEW ENGLAND DIVISION, CORPS OF ENGINEERS
 424 TRAPELO ROAD
 WALTHAM, MASSACHUSETTS 02254

REPLY TO
 ATTENTION OF:
 NEDED

Accession For	
NTIS GRA&I	<input checked="" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By _____	
Distribution/	
Availability Codes	
Dist.	Avail and/or Special
A/1	23

OCT 15 1966

Honorable Edward J. King
 Governor of the Commonwealth of
 Massachusetts
 State House
 Boston, Massachusetts 02133



Dear Governor King:

Inclosed is a copy of the Overlook Reservoir Dam & Dike Phase I Inspection Report, which was prepared under the National Program for Inspection of Non-Federal Dams. This report is presented for your use and is based upon a visual inspection, a review of the past performance and a brief hydrological study of the dam. A brief assessment is included at the beginning of the report. I have approved the report and support the findings and recommendations described in Section 7 and ask that you keep me informed of the actions taken to implement them. This follow-up action is a vitally important part of this program.

A copy of this report has been forwarded to the Department of Environmental Quality Engineering, the cooperating agency for the Commonwealth of Massachusetts. In addition, a copy of the report has also been furnished the owner, City of Fitchburg Water Dept., Fitchburg, Mass.

Copies of this report will be made available to the public, upon request, by this office under the Freedom of Information Act. In the case of this report the release date will be thirty days from the date of this letter.

I wish to take this opportunity to thank you and the Department of Environmental Quality Engineering for your cooperation in carrying out this program.

Sincerely,

Max B. Scheider
 MAX B. SCHEIDER

Colonel, Corps of Engineers
 Division Engineer

Incl
 As stated

NATIONAL DAM INSPECTION PROGRAM
PHASE I INSPECTION REPORT
BRIEF ASSESSMENT

Identification No.: MA 00876 (Dam), MA 01335 (Dike)
Name of Dam: Overlook Reservoir Dam and Dike
City: Fitchburg
County and State: Worcester County, Massachusetts
Stream: Tributary-North Nashua River
Date of Inspection: April 11, 1979 (Dam), June 17, 1980 (Dike)

Overlook Reservoir Dam is a 370+ foot long, 47+ foot high, earth embankment structure with a masonry core wall and a stone masonry gatehouse. There is a separate 900+ foot long, 25 foot high dike with an 10 foot long concrete channel spillway, located along the northern part of the reservoir. Construction of the project was completed in 1872. The dam and dike have always been owned and operated by the City of Fitchburg for the purpose of water supply.

The visual inspection indicated the dam and dike to be in generally fair condition. Heavy vegetation, animal burrows, surficial sloughing and erosion were observed on the side slopes of the dam. Excessive tree growth and seepage was observed at the dike. Leakage into the valve chamber located upstream of the chlorination building was observed and the functionability of the control valves at the facility are questionable.

The project has a size classification of small and a hazard classification of high. Based on Corps Guidelines, the test flood has a range between a 1/2 and full probable maximum flood (PMF). The test flood used was the 1/2 PMF.

The reservoir receives inflow from a drainage area of 40 acres. Additional inflow is received from the 24 inch diameter Shattuck Brook and Scott Reservoir conduit to maintain an adequate water level.

The assumed test flood produced a calculated inflow of 94 cfs. The resulting outflow is 70 cfs which will surcharge the spillway by 0.65 feet (elevation 835.65+). The spillway has a capacity of 1447 cfs with the water level at the top of dike (elevation 840.2). The top of dam is at elevation 841.5+. The test flood outflow requires only 5 percent of the spillways capacity. Therefore, neither the dam or dike would be overtopped by the test flood. There are no records of the dam or dike being overtopped.

There were no indepth engineering data available and therefore, the condition of the project was evaluated based primarily on the visual inspection, past performance history and sound engineering judgement.

It is recommended that the owner engage a qualified registered professional engineer to investigate the soft, wet areas on the downstream slope of the dike; design a means to correct the erosion of the downstream slope of the dike; specify procedures for removal of trees, existing stumps and their tree root systems from the dam and dike; quantitatively monitor the flow of water through the discharge pipes and at the spring downstream of the dam embankment relative to reservoir level and design an upstream control to regulate inflow into


the intake structure or outflow through the two water supply lines. The owner should also determine and correct the cause of leakage into the valve chamber located upstream of the chlorination building. Remedial measures regarding operating and maintenance procedures should include the following:

1. Removal of brush and briars on the slopes of the dam and dike.
2. Refill stump holes and animal burrows in the downstream slope of the dam.
3. Repair erosion and surficial sloughing damage on the downstream slope of the dam with compacted fill.
4. Repair spalled concrete on spillway walls.
5. Repair the approach channel riprap at the spillway inlet.
6. Place additional riprap around the spillway outlet.
7. Test and repair (as required) all valves on a regular basis.
8. Repair and maintain the outlet channel at the 12 inch outlet drain.
9. Install a floor deck for the service bridge.
10. Develop a formal downstream warning system.
11. Institute a program of annual technical inspection.

The above recommendations and remedial measures should be implemented by the owner within 1 year after receipt of this Phase I inspection report.


Ronald H. Cheney, P.E.

Vice President



Hayden, Harding & Buchanan, Inc.

Boston, Massachusetts



This Phase I Inspection Report on Overlook Reservoir Dam and Dike has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the Recommended Guidelines for Safety Inspection of Dams, and with good engineering judgment and practice, and is hereby submitted for approval.

Carney M. Terzian

CARNEY M. TERZIAN, MEMBER
Design Branch
Engineering Division

Richard J. DiBuono

RICHARD DIBUONO, MEMBER
Water Control Branch
Engineering Division

Aramast Mahtesian

ARAMAST MAHTESIAN, CHAIRMAN
Geotechnical Engineering Branch
Engineering Division

APPROVAL RECOMMENDED:

Joe B. Fryar

JOE B. FRYAR
Chief, Engineering Division

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to

assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

The Phase I Investigation does not include an assessment of the need for fences, gates, no-trespassing signs, repairs to existing fences and railings and other items which may be needed to minimize trespass and provide greater security for the facility and safety to the public. An evaluation of the project for compliance with OSHA rules and regulations is also excluded.

CONTENTS

<u>Section</u>	<u>Page</u>
Letter of Transmittal	
Brief Assessment	
Review Board Page	
Preface	i
Table of Contents	iii-v
Overview Photo	vi
Location Map	vii

REPORT

1. PROJECT INFORMATION	
1.1 General	1
a. Authority	1
b. Purpose of Inspection	1
1.2 Description of Project	
a. Location	2
b. Description of Dam and Appurtenances	2
c. Size Classification	4
d. Hazard Classification	4
e. Ownership	5
f. Operator	5
g. Purpose of Dam	5
h. Design and Construction History	5
i. Normal Operating Procedures	5
1.3 Pertinent Data	6
2. ENGINEERING DATA	
2.1 Design Data	10
2.2 Construction Data	10
2.3 Operation Data	10
2.4 Evaluation of Data	10

<u>Section</u>	<u>Page</u>
3. VISUAL INSPECTION	
3.1 Findings	12
a. General	12
b. Dam and Dike	12
c. Appurtenant Structures	16
d. Reservoir Area	18
e. Downstream Channel	18
3.2 Evaluation	18
4. OPERATIONAL PROCEDURES	
4.1 Procedures	20
4.2 Maintenance of Dam	20
4.3 Maintenance of Operating Facilities	20
4.4 Description of any Warning System in Effect	20
4.5 Evaluation	20
5. HYDRAULIC/HYDROLOGIC	
5.1 Evaluation of Features	21
a. General	21
b. Design Data	21
c. Experience Data	21
d. Visual Observation	22
e. Test flood Analysis	22
f. Failure Analysis	23
6. STRUCTURAL STABILITY	
6.1 Evaluation of Structural Stability	26
a. Visual Observation	26
b. Design and Construction Data	27
c. Operating Records	27
d. Post-Construction Changes	28
e. Seismic Stability	28


<u>Section</u>	<u>Page</u>
7. ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES	
7.1 Dam Assessment	29
a. Condition	29
b. Adequacy of Information	29
c. Urgency	30
d. Need for Additional Investigation	30
7.2 Recommendations	30
7.3 Remedial Measures	31
a. Operation and Maintenance Procedures	31
7.4 Alternatives	32

APPENDIXES

APPENDIX A - INSPECTION CHECKLIST	A-1
APPENDIX B - ENGINEERING DATA	B-1
APPENDIX C --PHOTOGRAPHS	C-1
APPENDIX D - HYDROLOGIC AND HYDRAULIC COMPUTATIONS	D-1
APPENDIX E - INFORMATION AS CONTAINED IN THE NATIONAL INVENTORY OF DAMS	E-1

OVERLOOK RESERVOIR DIKE

OVERLOOK RESERVOIR DAM



ZYEN, HARDING & BUCHANAN, INC CONSULTING ENGINEERS BOSTON, MASSACHUSETTS		US ARMY ENGINEER DIV NEW ENGLAND CORPS OF ENGINEERS WALTHAM, MASS	
NATIONAL PROGRAM OF INSPECTION OF NON-FED DAMS			
<h1>OVERLOOK RESERVOIR DAM & DIKE</h1>			
FITCHBURG		MASSACHUSETTS	
		SCALE 1" = 2000'	
		DATE JULY, 1980	

PHASE I
NATIONAL DAM INSPECTION PROGRAM

SECTION 1
PROJECT INFORMATION

1.1 General

a. Authority

Public Law 92-367, August 8, 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a national program of dam inspection throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region. Hayden, Harding & Buchanan, Inc. has been retained by the New England Division to inspect and report on selected dams in the State of Massachusetts. Authorization and notice to proceed was issued Hayden, Harding & Buchanan, Inc. under a letter of 28 November 1978 from Max B. Scheider, Colonel, Corps of Engineers. Contract No. DACW 33-79-C-0012 has been assigned by the Corps Engineers for this work.

b. Purpose

(1) To perform technical inspection and evaluation of non-Federal dams to identify conditions which threaten the public safety and thus permit correction in a timely manner by non-Federal interests.

(2) To encourage and prepare the States to initiate quickly effective dam safety programs for non-Federal dams.

(3) To update, verify and complete the National Inventory of Dams.

1.2 Description of Project

a. Location

Overlook Reservoir is located in the City of Fitchburg, Worcester County, Massachusetts. The dam is located along the southern shore of the reservoir. The dike is located along the northern shore. The dam is shown on the Fitchburg Massachusetts Quadrangle with coordinates approximately at North 42°35'38", West 71°49'10". The dike has the approximate coordinates of North 42°35'54", West 71°49'02".

b. Description of Dam and Appurtenances

The dam is a 47+ foot high, 370+ foot long, earth embankment with a masonry core wall and a stone masonry gatehouse. This gatehouse also serves as the intake structure. The dam, an earth embankment, has a maximum fill height of 40+ feet and a crest width of approximately 20 feet. The riprapped upstream side slope is inclined at 2H:1V and the highly vegetated downstream side slope is inclined at 1.5H:1V (see Photographs 4 and 6).

The 45+ foot high masonry core wall is located approximately at the longitudinal center line of the dam crest. It varies in thickness from about 1 foot at the top to 21" at the base and extends vertically to within about 1.5 feet of the top of crest (see plan, elevation and cross sectional sketches in Appendix B).

The granite masonry gatehouse is located approximately 40 feet upstream of the crest (Photographs 5 and 6). A steel service bridge provides access to the gatehouse. The access bridge is new, and the floor had not been put in place at the time of the dam inspection.

A 12 inch drain line is located at the upstream toe of the embankment (elevation 797.5₊), approximately 25 feet upstream of the intake structure. Water drawn through this line would pass through the base of the gatehouse, beneath the dam embankment and outlet into a small stream 60 feet west of a chlorination building located beyond the downstream toe (Photograph 2). A gate valve is located at the base of the gatehouse for control of this drain line. Two additional lines, a 12 inch and a 16 inch, exit from the gatehouse running beneath the dam, into the chlorination building and eventually into the City water system. There is a slotted screen opening located on the upstream side of the intake structure. Water inlets through this screen opening into the intake structure and outlets into the 2 water supply pipes. There are no known outlet controls for the water supply pipes located within the intake structure. There are two below grade valve chambers which are located on the upper and lower sides of the chlorination building. Manual valve controls located within these chambers regulate flow through the chlorination building. There is a valve located within the upper valve chamber which can control flow through the drain line. These chambers are further described in Section 3.1.c.

There is a separate 900₊ foot long 25 foot high earthen dike located along the northern shore of the reservoir. The upstream side slope of the dike is inclined at about a 2.5H:1V

slope and is riprapped to within about 4 vertical feet of the crest (Photograph 11). The upper portion is highly vegetated. The crest of the dike is at elevation 840.2_± and is about 20 feet wide. The downstream side slopes are thickly vegetated and inclined at about 1.5 to 1.75 horizontal to 1 vertical. A 6.2 foot deep by 10 foot long concrete emergency spillway is located at the left side of the dike (photo 9). This spillway discharges into a 24 inch CIP waste pipe (photo 10) which outlets approximately 350 feet downstream of the spillway (photo 14). There is a 24 inch inlet pipe located approximately 60 feet left of the spillway (photo 13). This pipe provides inflow to Overlook Reservoir from Shattuck Brook and Scott Reservoir (see section 1.3.a for a further discussion of this inlet pipe).

c. Size Classification

The project (Dam and Dike) has a size classification of small, based on the storage capacity of 254 acre-feet and the hydraulic heights of 40 and 25 feet, respectively.

d. Hazard Potential

This project has a hazard potential classification of high. The dam and dike have separate failure impact areas. Based on Corps Guidelines, the assumed dam and dike failure outflows are 45,900 cfs and 20,500 cfs, respectively.

Dam failure flood stage will vary from eight to eighteen feet deep in the 3000 foot long impact area. Ten homes, three mill buildings, a church, a playground, two water department buildings and a small water supply reservoir will be damaged by failure flooding. There is a potential for the loss of many lives due to an assumed dam failure.

Dike failure flood stage will vary from three to sixteen feet deep. The impact area is almost two miles long and extends into the heavily developed areas of Fitchburg. At least two hundred buildings (residential and commercial) will be damaged by failure flooding. There is a potential for the loss of a significant number of lives due to an assumed dike failure.

e. Ownership

The project has been owned by the City of Fitchburg Water Department since it was completed in 1872.

f. Operator

The project is maintained and operated by the City of Fitchburg Water Department. Mr. J. Andre Provencial is the Water Superintendent. The Water Department address is City Hall, 718 Main Street, Fitchburg, Massachusetts 01420. Telephone (617) 342-5722.

g. Purpose of Dam

The purpose of the project has always been water supply.

h. Design and Construction History

The project was designed by Phineas Ball of Worcester, Massachusetts in 1871. Construction began in 1871 and was completed in 1872. The emergency spillway was added to the project in about 1960. No other records indicating modifications to the original structure were located.

i. Normal Operating Procedures

There are no formal operational procedures for the project. Normally the downstream water supply gates are left open, the waste gate is closed, and the quantity of water entering the Fitchburg water system is controlled by a downstream regulating station.

1.3 Pertinent Data

a. Drainage Area

The drainage area, 40 acres (0.06 s.m.), is comprised of wooded, undeveloped land. Two undeveloped roads cross the drainage area. Flat Rock Road, to the north, borders the spillway and dike. The second road, to the east, is an access road used to reach the reservoir area. This road also runs along the top of the main dam to give access to a Girl Scout Camp adjacent to the southwest side of the dam.

The reservoir is located in an upland area, thus it has a very small runoff area. It was originally intended to be supplied with additional water from a 14,000 foot long, 24 inch diameter pipe line which begins above Lovell Reservoir, to the north. This pipe line was to be supplied with water from a dam proposed for that location. However, this dam was never constructed. The 24 inch pipe line presently receives some inflow from the Shattuck Brook intake (a small ungated diversion structure with inflow limited by pipe size). Water can also be added from Scott Reservoir by gravity flow (which is also connected to the 24 inch pipe) as required to maintain the water level in Overlook Reservoir.

b. Discharge at Damsite

The outlet works consist of one 16 inch and two 12 inch diameter pipes. The invert elevation at the intake structure is about 797.5±. The 16 inch pipe and one of the 12 inch pipes are used for water supply. Their discharge capacity is controlled by water demand within the supply system. Their maximum capacities would be about 40 and 20 cfs, respectively.

They extend to Marshall Reservoir and along Caldwell Street towards West Street. The third pipe is a 12 inch main drain. It discharges to the west of the chlorination building into a small outlet brook. Its outlet invert is about elevation 796 \pm . Its maximum capacity would be about 20 cfs.

c. Elevation (ft. above NGVD)

- (1) Streambed at centerline of dam ----- 801 \pm
- (2) Maximum tailwater ---- none from spillway discharge
- (3) Upstream portal invert diversion tunnel ----- none
- (4) Recreation pool ----- N/A
- (5) Full flood control pool ----- N/A
- (6) Spillway crest ----- (ungated) 835.0 \pm
- (7) Design surcharge (Original Design) ----- unknown
- (8) Top Dam ----- 841.5 (Top of dike 840.2 \pm)
- (9) Test flood design surcharge ----- 835.65
- (10) Water Supply ----- varies-maximum of 835 \pm

d. Reservoir

- (1) Length of maximum pool ----- 1600'
- (2) Length of water supply pool ----- 1600'
- (3) Length of recreation pool ----- N/A
- (4) Length of flood control pool ----- N/A

e. Storage (acre-feet)

- (1) Spillway crest pool ----- 187
- (2) Water supply pool ----- varies-maximum of 187
- (3) Test flood pool ----- 196
- (4) Top of dike ----- 254
- (5) Recreation pool ----- N/A
- (6) Flood Control pool ----- N/A

f. Reservoir surface (acres)

- (1) Spillway crest ----- 11.2
- (2) Water supply ----- maximum 11.2
- (3) Test flood pool ----- 12.0
- (4) Top dike ----- 15.6
- (5) Flood-control pool ----- N/A
- (6) Recreation pool ----- N/A

g. Dam and Dike

- (1) Type ----- gravity, earth fill
- (2) Length ----- 370'+ main dam; 900+ dike
- (3) Height ----- 47'+ main dam; 25'+ dike
- (4) Top Width----- 20.0'+
- (5) Side Slopes ----- Dam-U.S.2H:1V, D.S. 1.5H:1V;
Dike U.S. 2.5H:1V D.S. 1.5 to 1.75H:1V
- (6) Zoning ----- indications on D.S. side of dam only
- (7) Impervious Core ----- unknown
- (8) Cutoff ----- Stone masonry wall-dam; unknown-dike
- (9) Grout curtain ----- none
- (10) Other ----- Riprap on U.S. slope of dam and dike

h. Diversion and Regulating Tunnel ----- none

i. Spillway

- (1) Type ----- see photo 9, 10' long x 6.2' high x 80'
wide concrete channel
- (2) Length of weir ----- 10' (bottom of channel)
- (3) Crest elevation ----- 835.0+
- (4) Gates ----- none
- (5) U/S Channel ----- none
- (6) D/S Channel -----drop-off to 24" CIP, see photo 10
- (7) General ----- added to dike about 1960+

j. Regulating Outlets

Regulating outlets have been discussed in detail in Section 1.3.b. Briefly, they consist of a 16 and 12 inch water supply pipe and the 12 inch main drain. The three outlet pipes can be controlled by manual gate valves located in buried chambers at the downstream toe near the chlorination building. The main drain also has a manual valve inside the intake building. According to water department personnel this valve is normally kept open. The condition of the valve is unknown. There is no known outlet control for the water supply pipes located within the intake structure.

The 12 inch gate valve on the main drain in the valve chamber is reported to be broken and kept permanently closed. The other downstream gate valves are reportedly operable but they are not normally operated and are kept open at all times.

Outflow is regulated downstream at the Marshall Reservoir regulating station. Overlook Reservoir is brought into use during periods of high water demand.

SECTION 2
ENGINEERING DATA

2.1 Design

According to a 1933 County Inspection Report, Phineas Ball of Worcester, Massachusetts was the design engineer for this project. An unsigned plan dated 1871, showing a cross sectional view of the embankment and gatehouse was located at the Fitchburg Engineering Office. No design calculations for the dam or dike were located.

2.2 Construction

No construction data was discovered for this dam or dike.

2.3 Operation

No written operational manual was discovered for this project.

2.4 Evaluation

a. Availability

A design plan dated 1871 and a piping detail showing the location of outlet facilities were made available at the Fitchburg Engineering Department. County Inspection Reports for the years 1924 through 1964 were made available at the Worcester County Engineering Department. State Inspection Reports for the years 1975 and 1976 were made available at the Department of Environmental Quality Engineering, Division of Waterways, Boston Office.

b. Adequacy

The lack of indepth engineering design data does not allow for a definitive review. Therefore, the condition of

this dam, structurally and hydraulically, can not be assessed from the standpoint of review of design calculations, but must be based primarily on the visual inspection, past performance history, and sound engineering judgement.

c. Validity

The field investigation indicated that the external features substantially agree with the supplied information.

SECTION 3
VISUAL INSPECTION

3.1 Findings

a. General

The Phase I Inspection of the dam was performed on April 11, 1979. At that time, the water level was 11.3 feet below the top of dam, and about 4.8 feet below the spillway crest. During the June 17, 1980 inspection of the dike the water level was approximately 8 feet below the top of the dike.

b. Dam and Dike

The dam consists of a main embankment section at the south end of the reservoir about 370 feet long with a maximum hydraulic height of 40 feet. An embankment dike with a maximum height of about 25 feet encloses the reservoir at the north end. A concrete emergency spillway also passes through the dike at the north end of the reservoir. Photograph 4 shows the downstream face and the crest of the main dam viewed from the left abutment.

1. Dam

Upstream Slope

The upstream face of the main dam is on a slope of 2H:1V. Riprap of two types extends from the water level to about 3 feet of the dam crest. The upper riprap consists of large blocks of granite, which appear to have been hand placed, and the lower riprap consists of smaller dumped rockfill. The water level at the time of the April 1979 inspection was approximately 8 feet below the top of the riprap. Photograph 6 shows the two levels

of riprap and the grass covered upstream face above the riprap. There were no visual indications of slumping or sliding, and the riprap appeared to be in good condition.

Crest

The crest of the dam is approximately 20 feet wide. As shown in photograph 5, a sand and gravel roadway crosses the crest of the dam. No cracking or misalignment is evident.

Downstream Slope

The downstream face is on a slope of 1.5H:1V. Although trees and heavy brush have been removed, remaining brush and briars make close inspection of the downstream face difficult. Several large stumps have been removed leaving large holes in the slope up to 2 feet deep - some within 10 feet of the crest. Many smaller stumps have not been removed. Several animal burrows with 8 to 10 inch diameters and depths greater than 2 feet were observed on the face within 20 feet of the crest. An eroded footpath extends from the toe to the crest on the downstream face across from the gatehouse at approximately Station 1+70 (see plan view in Appendix B).

The downstream face of the dam is generally undulatory. A bowl-shaped, shallow depression was observed in the downstream face between Station 2+40 and 2+70, with the center of the depression located approximately 15 feet below the crest. This depression may be an old slide or slough area. Several large trees were observed at the lower portion of the downstream face and at the toe area, as shown by photo 7.

A chlorination building is located approximately 80 feet downstream from the toe of the dam. A sand and gravel roadway passes between the chlorination building and the toe of the dam and extends around to the right side of the building. Approximately 100 feet downstream of the toe and approximately 60 feet to the right of the chlorination building, a 12 inch diameter iron pipe emerges from beneath the roadway embankment. At the time of the inspection, the end of this pipe was half filled with sand and gravel, and clear water, approximately 4 inches deep over the sand and gravel, was existing from the pipe into a stream, as shown in photograph 1. The source of this is not known.

The head of the stream is located at the base of the roadway embankment upstream from the 12 inch diameter pipe, as shown in photograph 2. Water observed to be seeping from the base of the roadway embankment was clear, however some silt deposits were observed in the head of the stream.

Downstream from the 12 inch diameter pipe, clear water was observed to exist under pressure from two 1 inch to 2 inch diameter plastic tubes (photograph 3), which appeared to be waste lines from the chlorination plant.

2. Dike

The dike consists of an earth embankment approximately 900 feet long with a maximum height of about 25 ft. The axis of the dike has an approximately 90° bend at about it's midpoint.

There is a concrete spillway structure between the dike and the left abutment. The spillway structure is shown in Photo 9.

Upstream Slope

Photo 20 shows the upstream slope from the right abutment to the point of dike curvature and Photo 17 shows the slope from the spillway to the point of curvature. The upstream slope is inclined at 2.5H:1V. The riprap on the slope is in good condition. There is no riprap on the upper 4 feet (measured vertically) of the slope.

The unprotected portion of the slope above the riprap is overgrown with dense brush and small trees. This growth may be seen in Photos 17 and 20.

No slumping or slides were noticed on the upstream slope.

Crest

The crest of the dike is 20+ feet wide and is unpaved. Vehicles may drive along the entire crest gaining access from the right abutment. Vehicular traffic has caused minor erosion of the crest as shown in Photo 15. The dense growth along the upstream and downstream slopes is visible in Photo 15.

No misalignment or unusual settlement of the crest was observed.

Downstream Slope

The downstream slope is inclined at about 1.5 to 1.75H:1V. The slope is covered with dense growth including many small trees with occasional larger trees. One tree, a few feet below the downstream toe has a trunk diameter of about 20 inches. Dead trees with trunk diameters greater than 12 inches were observed on the slope.

Photo 18 shows the downstream slope at midheight viewed from the point of dike curvature toward the right abutment. Photo 16 shows a deep erosion path that has been worn on the downstream

slope at the point of dike curvature. The path leads from the dike crest to the roadway at the toe of the dike.

Photo 19 shows a wet area located at the downstream toe at the point of curvature of the dike. The area was swampy and soft with free water standing at some locations. At the time of the inspection, it was judged that this wet area was probably a result of seepage through or beneath the dike.

A second wet area was located at the toe of the dike about 250 feet from the right abutment. This area, which is beneath a row of large pine trees, was soft but had no standing water.

c. Appurtenant Structures

The spillway is a 10 foot long by 6.2 foot deep concrete channel. It is located adjacent to the left abutment of the dike, at the north end of the reservoir. Photographs 4, 6, 9 and 11 show the spillway, dike and dam area. The overall condition of the spillway and outlet channels are generally good. Some concrete on the northwest spillway wall is spalling as shown by photograph 9. The spillway discharges towards an undeveloped wooded area. A 24 inch pipe (Photograph 10) will carry some of the outflow into the wooded area. The remainder will flow overland.

The intake building, located at the main dam, contains a 12 inch gated reservoir drain line and two water supply pipes. Water inlets into the intake structure through a screened opening and outlets into the two water supply pipes. There is no known control for the water supply pipes located within the intake structure. The condition of the drain line valve is unknown. The drain and two water supply pipes pass under the main dam, to a valve chamber. The access bridge to the intake structure was being replaced. The deck had not been installed at the time of inspection.

Downstream of the main dam (photograph 7) is a chlorination building. The two (12 and 16 inch) water supply lines pass through this facility. On either side of the building there is a valve chamber. The three outlet pipes, enter the upstream valve chamber where each pipe is gated. One 12 inch line is the main drain. After exiting the upstream valve chamber, this pipe extends to an outlet brook about 60 feet from the chlorination building (see plan view in appendix B). Its valve, inside the chamber is reportedly inoperable and left in a closed position. Some leakage is evident as shown by Photo 1.

There is also a smaller, 6 inch, pipe entering this valve chamber from the direction of the access road. This pipe is ungated and there was a small amount of inflow visible. This pipe appears to be a "drain" for the downstream area. No record of its existence or purpose was found. The two remaining water supply pipes pass through the chlorination building and then into the other valve chamber.

At this chamber, each pipe has a check and a manual gate valve. The 16 inch line has a 12 inch manually gated by-pass around the valve chamber. It appears that the Water Department has small sampling lines and additional chlorination capabilities inside the chamber. There is also a 1 inch water supply pipe extending from the 12 inch water main to a Girl Scout summer camp located on the hillside adjacent to the dam.

All gate valves (except for the drain line) are reportedly operable. Flow from the dam is controlled downstream by a regulating station, as water demand requires.

Manhole covers were removed from atop both of the valve chambers for observation. The water level in both chambers was found to be approximately 7 feet below the surface. These chamber's manhole covers are normal 6 inches below grade, to prevent vandalism.

d. Reservoir Area

The reservoir area is comprised of wooded undeveloped land as shown by photograph 4. The visual inspection showed the overall reservoir area to be in general agreement with the U.S.G.S. map. A description of the drainage area is given in Section 1.3.a of this report. The amount of siltation in the reservoir is not known.

e. Downstream Channel

The downstream channel is a small unnamed brook beginning at the roadway embankment upstream from the 12 inch diameter drain pipe (photo 2). The brook is feed by the waters seeping from the base of the roadway embankment, discharge from the 12 inch drain line (photo 1) and the 1 to 2 inch diameter pipes (photo 3). The channel was observed to be free and clear. The channel eventually flows to the North Nashua River.

3.2 Evaluation

Visual inspection indicates that the main dam is in fair condition with respect to the geotechnical aspects. Disturbance of the downstream slope by removal of vegetation and animal trespassing was observed. Some local sloughing also may have occurred.

Considerable quantities of water were observed discharging downstream from the dam in the forms of (1) seepage from a spring and (2) discharge from a 12 inch diameter iron pipe. Representative of the Fitchburg Water Department stated that the water discharging

from the 12 inch diameter pipe originates in the upper buried gate vault near the toe of the dam; however, they did not know if the water flowing into the gate vault was caused by seepage through the embankment or by faulty valves in the outlet pipes. Since there is no upstream control of inflow into the intake structure or outflow through the two water supply pipes, these pipes are always under pressure. Leakage of these pipes could cause an embankment failure. Upstream controls should be provided.

At the time of the April 1979 inspection, the downstream discharge appeared to be flowing in a controlled manner and no surface seeps or springs were observed on the dam embankment or within 50 feet downstream of the toe of the embankment.

Visual inspection indicates that the dike is in fair condition.

The presence of dense growth of bushes and trees on the downstream slope and at the toe of the dike make it impossible to inspect these areas adequately, although several problems are observable as described below.

The numerous trees, some of them quite large and dying or dead, could cause shortened seepage paths through the embankment leading to internal erosion.

The presence of soft wet ground and standing water at the downstream toe of the dike may be the result of seepage conditions which, if not controlled, could lead to failure of the dike.

Active erosion of an area on the downstream face at the point of curvature render this area less resistant to runoff from rainfall or due to overtopping if it should occur. Such erosion, if left unrepaired, could cause failure of the dike.

SECTION 4

OPERATIONAL PROCEDURES

4.1 Procedure

The purpose of the dam is water supply. Normally the 2 water supply outlet pipes remain open, the 12 inch drain gate is closed and the outflow from the chlorination building into the City water system is controlled by a downstream regulating station.

4.2 Maintenance of Dam

The general maintenance of the dam is performed by the Fitchburg Water Department. Recent maintenance consisted of the cutting and clearing of overgrown brush on the upstream and downstream embankment faces.

4.3 Maintenance of Operating Facilities

There is no formal operational procedure for this facility. The dam is used for water supply on a regular basis. Deficiencies in operational facilities should be detected during normal operating procedure.

4.4 Description of Warning System

There are no warning systems at this facility.

4.5 Evaluation

There is no formal maintenance procedure for this dam. Cutting vegetation on the upstream and downstream faces should be performed on a regular basis. The outlet valves should be periodically operated to evaluate their condition. The dam should be inspected annually by qualified personnel who can identify conditions of concern which if left unchecked could jeopardize the safety of the dam.

SECTION 5
HYDRAULIC/HYDROLOGIC

5.1 Evaluation of Features

a. General

The project was designed and is used as a water supply facility. It is comprised of an earth fill dam with a hydraulic height of 40 feet and a separate 25 foot high (hydraulic height) 900+ foot long dike. The useable storage capacity is 254 acre-feet. The spillway is located at the northerly end of the dike. Photographs 4,5,6,11 and 12 show views of the dam and dike.

b. Design Data

The project was completed in 1872. Design calculations were not located. Some record drawings were found. The dam was designed and has always been used for water supply. It was designed to be connected, by a 14,000 foot long 24 inch pipe line, to a proposed dam at Shattuck Brook, which was never constructed. This dam was to be located 5,000 feet north of the existing Lovell Reservoir. The 24 inch pipe receives some flow from an intake structure on Shattuck Brook and from a 20 inch pipe connected to Scott Reservoir.

c. Experience Data

Overtopping of this dam (top elevation 841.5) or the dike (top elevation 840.2) has never been reported. During the August 17 to 20, 1955 flood period, about 4 inches of rainfall occurred in the Fitchburg area. Gage station 1-0945 is maintained by the U.S.G.S. on the North Nashua River near Leominster. It recorded a maximum discharge of 16,300 cfs (152.34 cfs/s.m.) for a 107 s.m. drainage area on March 18, 1936.

The level of the reservoir varies, but is usually below the spillway level of elevation 835. The small drainage area (40 acres) and limited additional inflow from other sources coupled with a high water demand could substantially lower the reservoir level. Thus, it is used only to provide an additional supply of water during periods of high water demand. Water can be drawn from Scott Reservoir to keep the water level from dropping too low.

d. Visual Observations

The main dam and dike, show no indications of having been overtopped. The spillway crest is about 5 feet below the top of the dike and shows no indications of outflow having occurred recently. The water level was several feet below the spillway elevation of 835 when inspected. Observations of the drainage area and general vicinity show them to be generally as indicated on the U.S.G.S. map and as described in Section 1.3 of this report.

e. Test Flood Analysis

Due to the projects small size and high hazard potential classification, the Corps guidelines indicate the test flood to be within the range of the 1/2 PMF to full PMF. The 1/2 PMF was chosen for this project. The 1/2 PMF inflow for this drainage area of 40 acres would be 94 cfs. With the water level at least one foot below the spillway elevation of 835, the storage capacity is large enough to retain test flood runoff without the water level reaching elevation 835. With the water level assumed at the spillway crest, the test flood would surcharge the reservoir to elevation 835.65. The test flood outflow would be about

70 cfs. The dam and dike would not be overtopped. The spillway has a capacity of 1447 cfs with the water level at the top of dike, elevation 840.2. The 24 inch outlet pipe just beyond the spillway (photograph 10) could carry about 25± cfs of the test flood outflow. The remaining 45 cfs, would flow across Flat Rock Road into the adjacent woods. The outflow would eventually flow to Nichols Pond, about 2000 feet downstream.

f. Failure Analysis - Dam and Dike

Dam

The dam was assumed to have failed with the water level at the top of dam, elevation 841.5. Forty percent of a 270 foot long section (taken at midheight) of the forty foot high dam was assumed to have failed. The resulting outflow would be 45,900 cfs. The failure impact area is confined to a "narrow" outlet channel which extends about 3000 feet to West Street and the North Nashua River. Most development occurs near West Street. The first structure to be flooded is the chlorination building, near the toe of dam. The chlorination building would be flooded by at least 15 feet. No other developments occur until Marshall Reservoir about 1000 feet downstream. There, the reservoir, and the pump and chlorination buildings would be flooded. Flood stage would reach 12 feet. For the next 1000 feet, Caldwell Street parallels the outlet brook. Here, flood stages would reach 12 to 16 feet.

Between Arlington Street and West Street, flood stages would reach 8 to 12 feet. About 10 homes, a church, a playground, several mill buildings and roads would be flooded.

Additional damage could occur along West Street as floodwaters flow over the street. Beyond West Street and the mill buildings, the ground level drops towards the North Nashua River.

Since there is no spillway discharge to cause flooding in this outlet channel, all damage will be due to dam failure. Many of the structures located along this outlet channel will be destroyed. There is a high potential for the loss of many lives due to dam failure, particularly at the developed areas of Arlington and West Streets.

Dike

The dike was assumed to have failed with the water level at elevation 835.5 (test flood elevation; approximately 5' below top of dike). Forty percent of a 340 foot long section of the 900 foot long and 25 foot high dike was assumed to have failed. Water depth at failure was assumed to be 20 feet. The resulting outflow is 20,500 cfs.

The failure impact area extends about two miles, from the dike into the downtown Fitchburg area. Little development occurs within the impact area (several roads and five houses) until 4700 feet downstream of the dike, at Mechanic Street, where numerous structures were built in the "narrow" outlet channel. Flood stages between the dike and Mechanic Street will vary from 4 to 16 feet deep. Five houses could receive about two feet of flooding damage. Roads are flooded to deeper depths, up to 15 feet deep, due to their locations near brook crossings.

Beyond Mechanic Street, towards downtown Fitchburg, numerous development (residential and commercial structures) are located within the impact area. The flood stage will be at least three feet deep through this area and numerous structures (at least 200) will be flooded. There is a high potential for the loss of a significant number of lives due to dike failure flooding.

SECTION 6
STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability

a. Visual Observations

Visual inspection did not disclose any immediate structural problems at the main dam; however, the downstream slope was observed to be very undulatory, and a 30 foot wide shallow depression was observed approximately 15 feet below the dam crest which may be indicative of past problems with erosion and surficial sloughing. The cause of the water flowing into the gate vault should be determined to learn if it is the result of seepage through the dam.

The roots of large pine trees at the toe of the main dam opposite the chlorination building could shorten seepage paths if a tree blows over.

The visual examination revealed the following potential structural problems at the dike:

- (1) The presence of soft, wet ground and standing water at the downstream toe may be the result of seepage conditions which, if not controlled, could lead to the failure of the dike.
- (2) Active erosion on the downstream slope increases the possibility of erosion failure due to heavy and prolonged rains or due to overtopping should it ever occur.

(3) Large dead trees on the downstream slope could shorten seepage paths that could lead to internal erosion of the dike.

A dense cover of vegetation on the downstream slope makes it impossible to inspect the dike and downstream toe area adequately.

b. Design and Construction Data

According to drawings dated 1871, and inspection reports dated 1924, Overlook Reservoir Dam has a masonry core wall founded in "rocky soil", and the embankment consists of earth and rockfill with a zone of "selected material" placed on the downstream side of the masonry core wall. Details on the embankment construction are not available.

One 16 and one 12 inch water supply pipe, and the 12 inch waste pipe pass through the main dam at its base. A 12 inch waste pipe is shown to exit from the downstream gate vault in the general direction of the 12 inch diameter iron pipe shown in photograph 1.

No information concerning the construction of the dike was available.

c. Operating Records

Inspections conducted by the Commonwealth of Massachusetts Department of Environmental Quality Engineering in 1975 and 1976 concluded with the recommendation that a consultant inspection be conducted due to the seepage noted. Letters from the D.E.Q.E. to the City dated February 24 and December 21, 1977 list this dam with others in the City of Fitchburg as unsafe, again urging the City to retain the services of a registered professional engineer.

d. Post-Construction Changes

According to records from the Commonwealth of Massachusetts inspections, sometime prior to 1975 seepage had produced a large wet area downstream of the toe of the main embankment, and a gravel pad was placed over the toe area to improve the access to the chlorination building. Records of the 1975 inspection indicate that two 8 inch pipes exit from this gravel pad. These two pipes were not observed during the inspection reported herein.

e. Seismic Stability

The dam is located in Seismic Zone 2, and in accordance with the recommended Phase I guidelines does not warrant seismic analysis.

SECTION 7
ASSESSMENT, RECOMMENDATIONS AND
REMEDIAL MEASURES

7.1 Dam Assessment

a. Condition

The visual inspection indicates that the main dam and dike are in fair condition.

The presence of soft, wet ground and standing water at the downstream toe of the dike may be the result of seepage which, if not controlled, could lead to internal erosion and failure of the dike.

The presence of trees, some of which are dead, on the downstream slope of the dike could cause shortened seepage paths that could lead to internal erosion of the dike.

Active erosion on the downstream face of the dike increases the possibility of erosion failure due to rain or overtopping should it occur.

Since there is no upstream control of inflow into the intake structure or outflow into the two water supply pipes, these pipes are always under pressure. Leakage from these pipes could cause undermining of the embankment and possible embankment failure.

b. Adequacy of Information

The information made available, along with the visual inspection, are adequate for a Phase I investigation.

c. Urgency

The recommendations made in Section 7.2 and the remedial measures suggested in Section 7.3 should be implemented within one year after receipt of this report by the owner.

d. Need for Additional Investigation

No additional investigations are needed to complete the Phase I inspection.

7.2 Recommendations

The owner should retain a registered professional engineer to:

- (1) Investigate the soft, wet areas on the downstream slope of the dike.
- (2) Design a means to correct the erosion of the downstream slope of the dike.
- (3) Specify procedures for removal of trees and their root systems from the downstream slope of the dike and from the downstream area of the main dam directly opposite the chlorination building. Specify procedures for removing remaining stumps and their root systems from the slopes of the dam. Assist in the selection of suitable fill materials for backfilling the voids left in the embankment after removal of tree root systems.
- (4) Quantitatively monitor the flow of water through the discharge pipes and at the spring downstream from the main embankment as a function of reservoir level.
- (5) Design an upstream means to control inflow into the intake structure or outflow into the two water supply pipes.

The owner should also determine whether the leakage of water into the valve chamber upstream of the chlorination building is caused by faulty valves and, if so, the valves should be repaired.

7.3 Remedial Measures

a. Operating and Maintenance Procedures

The owner should implement the following:

- (1) Remove the brush and briars from the downstream slope of the dam and dike.
- (2) Existing stump holes caused by previous removal of trees and animal burrows on the downstream slope of dam should be backfilled with compacted fill.
- (3) Repair erosion and surficial sloughing damage on the downstream slope of the dam to produce a uniform downstream slope.
- (4) Spalled concrete on spillway walls should be repaired.
- (5) The approach channel riprap at the spillway inlet should be relaid in mortar to prevent undermining of the spillway.
- (6) Additional riprap should be placed around the spillway outlet to prevent soil erosion in the drainage path, along the toe of dike.
- (7) All valves for outlet pipes should be tested on a regular basis to insure they are operable. Inoperable valves should be repaired.
- (8) The outlet channel for the 12" drain should be cleared (near pipe outlet) and riprap placed for erosion control. The outlet pipe should be flushed clean.

- (9) A floor deck should be installed on the service bridge.
- (10) The owner should develop a formal warning system to notify downstream areas in the event of an emergency. Around the clock monitoring of the facility should be provided during periods of heavy precipitation.
- (11) Institute a program of annual technical inspection.

7.4 Alternatives

There are no practical alternatives for this project.

APPENDIX A
INSPECTION CHECKLIST

VISUAL INSPECTION CHECKLIST
PARTY ORGANIZATION

PROJECT Overlook Reservoir

DATE April 11, 1979

TIME 10:00 AM

WEATHER 50° F clear

W.S. ELEV. 830.2± U.S. _____ DN.S.

PARTY:

- | | |
|----------------------------|---|
| 1. <u>Ron Cheney HHB</u> | 6. <u>Bob Stetkar GEI</u> |
| 2. <u>Dave Vine HHB</u> | 7. <u>Maurice Caron-Fitchburg Water Dept.</u> |
| 3. <u>Mike Angieri HHB</u> | 8. _____ |
| 4. <u>Dan LaGatta GEI</u> | 9. _____ |
| 5. <u>John France GEI</u> | 10. _____ |

PROJECT FEATURE	INSPECTED BY	REMARKS
1. <u>Spillway</u>	<u>Ron Cheney, Dave Vine, Mike Angieri</u>	
2. <u>Service Bridge to Intake Building</u>	<u>Ron Cheney</u>	
3. <u>Dam Embankment</u>	<u>Dan LaGatta, John France, Bob Stetkar</u>	
4. <u>Hydraulic/Hydrologic</u>	<u>Mike Angieri</u>	
5. <u>Dike*</u>	<u>Dan LaGatta, Ron Cheney, Dave Vine</u>	
6. _____		
7. _____		
8. _____		
9. _____		
10. _____		

* Dike inspection on June 17, 1980

PROJECT OVERLOOK RESERVOIR DAM

DATE April 11, 1979

PROJECT FEATURE Embankment Dam

NAME D. LaGatta, J. France

DISCIPLINE Geotechnical Engineer

NAME R. Stetkar

AREA EVALUATED	CONDITION
<u>DAM EMBANKMENT</u>	
Crest Elevation	841.5
Current Pool Elevation	830.2±
Maximum Impoundment to Date	Unknown
Surface Cracks	None observed
Pavement Condition	None. Sand and gravel road on crest
Movement or Settlement of Crest	None observed
Lateral Movement	None observed
Vertical Alignment	No misalignment observed
Horizontal Alignment	No misalignment observed
Condition at Abutment and at Concrete Structures	Good
Indications of Movement of Structural Items on Slopes	No structural items on slopes
Trespassing on Slopes	Several animal holes and one footpath toe to crest at Sta 2+00
Sloughing or Erosion of Slopes or Abutments	Possible sloughing of downstream slope between Sta 2+40 and 2+66. Some erosion of downstream slope-very rough undulatory surface
Rock Slope Protection - Riprap Failures	Upstream riprap in good condition. No riprap on downstream slope
Unusual Movement or Cracking at or Near Toe	None observed
Unusual Embankment or Downstream Seepage	Water seeping into stream approx. 100 ft downstream of dam-source unknown
Piping or Boils	None observed
Foundation Drainage Features	None
Toe Drains	None
Instrumentation System	None
Vegetation	Some depressions in downstream slope from rotted tree stumps. Downstream slope and top of upstream slope are grass covered

Copy available to DTIC does not permit fully legible reproduction

PERIODIC INSPECTION CHECK LIST

PROJECT OVERLOOK RESERVOIR DIKE DATE June 17, 1980
 PROJECT FEATURES Embankment Dike NAME D.P. LaGatta
 DISCIPLINE Geotechnical Engineer NAME R.H. Cheney
Structural Engineer

AREA EVALUATED	CONDITION
<u>DIKE EMBANKMENT</u>	
Crest Elevation	840.2
Current Pool Elevation	832.2+
Maximum Inundation to Date	Unknown
Surface Cracks	None observed.
Pavement Condition	No pavement on dike.
Movement or Settlement of Crest	None observed.
Lateral Movement	} No misalignment observed.
Vertical Alignment	
Horizontal Alignment	
Condition at Abutment and at Concrete Structures	Good.
Indications of Movement of Structural Items on Slopes	None.
Trespassing on Slopes	One path on d.s. slope leading from roadway at toe to dike crest. No sloughing or erosion observed.
Sloughing or Erosion of Slopes or Abutments	
Rock Slope Protection - Slides or Failures	Riprap in good condition at and 3 ft above waterline.
Journal Movement or Indicators on Near Toes	None observed.
Journal Movement or Indicators on Seepage	Seepage observed at two location, see text.
Piping or Seepage	None observed.
Flow path - Seepage, Erosion	None observed.
Toe Seepage	None observed.
Infiltration	None.
Vegetation	Dense on both u.s. and d.s. slopes.

PERIODIC INSPECTION CHECK LIST

PROJECT Overlook Reservoir DATE April 11, 1979
 PROJECT FEATURE Intake Structure NAME Ron Chenev
 DISCIPLINE Structural Engineer NAME Dan LaGatta
Geotechnical Engineer

AREA EVALUATED	CONDITIONS
<p><u>OUTLET WORKS - INTAKE CHANNEL AND INTAKE STRUCTURE</u></p> <p>a. Approach Channel</p> <p style="padding-left: 20px;">Slope Conditions</p> <p style="padding-left: 20px;">Bottom Conditions</p> <p style="padding-left: 20px;">Rock Slides or Falls</p> <p style="padding-left: 20px;">Log Boom</p> <p style="padding-left: 20px;">Debris</p> <p style="padding-left: 20px;">Condition of Concrete Lining</p> <p style="padding-left: 20px;">Drains or Weep Holes</p> <p>b. Intake Structure</p> <p style="padding-left: 20px;">Condition of Concrete</p> <p style="padding-left: 20px;">Stop Logs and Slots</p>	<p>None</p> <p>Stone masonry gate house is also the intake structure.</p> <p>Stone works appears in good condition</p> <p>Access bridge being replaced. Deck not in place at time of upstream.</p>

PERIODIC INSPECTION CHECKLIST

PROJECT Overlook Reservoir DATE April 11, 1979
 PROJECT FEATURE Control Tower NAME Ron Cheney
 DISCIPLINE Structural Engineer NAME Dan LaGatta
Geotechnical Engineer

AREA EVALUATED	CONDITIONS
<p>OUTLET WORKS - CONTROL TOWER</p> <p>a. Concrete and Structural</p> <ul style="list-style-type: none"> General Condition Condition of Joints Spalling Visible Reinforcing Rusting or Staining of Concrete Any Seepage or Efflorescence Joint Alignment Unusual Seepage or Leaks in Gate Chamber Cracks Rusting or Corrosion of Steel <p>b. Mechanical and Electrical</p> <ul style="list-style-type: none"> Air Vents Float Wells Crane Hoist Elevator Hydraulic System Service Gates Emergency Gates Lightning Protection System Emergency Power System Wiring and Lighting System in Gate Chamber 	<p>Control tower and intake building one and the same.</p> <p>None. All valves manually operated.</p>

PERIODIC INSPECTION CHECK LIST

PROJECT Overlook Reservoir DATE April 11, 1979

PROJECT FEATURE Outlet Works NAME Ron Cheney

DISCIPLINE Structural Engineer NAME Dan LaGatta
Geotechnical Engineer

AREA EVALUATED	CONDITIONS
<p><u>OUTLET WORKS - TRANSITION AND CONDUIT</u></p> <p>General Condition of Concrete</p> <p>Rust or Staining on Concrete</p> <p>Spalling</p> <p>Erosion or Cavitation</p> <p>Cracking</p> <p>Alignment of Monoliths</p> <p>Alignment of Joints</p> <p>Numbering of Monoliths</p>	<p>None</p>

PERIODIC INSPECTION CHECK LIST

PROJECT Overlook Reservoir DATE April 11, 1979
 PROJECT FEATURE Outlet NAME Ron Cheney
 DISCIPLINE Structural Engineer NAME Dan LaGatta
 Geotechnical Engineer

AREA EVALUATED	CONDITIONS
<p><u>OUTLET WORKS - OUTLET STRUCTURE AND OUTLET CHANNEL</u></p> <p>General Condition of Concrete</p> <p>Rust or Staining</p> <p>Spalling</p> <p>Erosion or Cavitation</p> <p>Visible Reinforcing</p> <p>Any Seepage or Efflorescence</p> <p>Condition at Joints</p> <p>Drain Holes</p> <p>Channel</p> <p>Loose Rock or Trees Overhanging Channel</p> <p>Condition of Discharge Channel</p>	<p>Outlet works consist of 3 pipes (two 12" and one 16") exiting from the gatehouse. One 12" and the 16" feed the City Water System. Remaining 12" is main drawdown. Gate to this main draw down located in the gatehouse has not been operated in 20+ years. Additional gates located in valve chamber at downstream toe of dam. Draw down gate reported as broken.</p> <p>12" drawdown empties into brook downstream of toe.</p>

PERIODIC INSPECTION CHECK LIST

PROJECT Overlook Reservoir DATE April 11, 1979 & June 17, 1980

PROJECT FEATURE Spillway NAME Ron Cheney

DISCIPLINE Structural Engineer NAME Dan LaGatta

Geotechnical Engineer


AREA EVALUATED	CONDITIONS
<p><u>OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS</u></p>	
<p>a. Approach Channel</p>	<p>No separate approach channel for spillway.</p>
<p> General Condition</p>	<p>Riprapped lined U.S. face of embankment is channel. Some settlement of stone has occurred. Good</p>
<p> Loose Rock Overhanging Channel</p>	<p>None</p>
<p> Trees Overhanging Channel</p>	<p>None</p>
<p> Floor of Approach Channel</p>	<p>Stone</p>
<p>b. Weir and Training Walls</p>	<p>b. & c. make-up weir/outlet channel</p>
<p> General Condition of Concrete</p>	<p>Good</p>
<p> Rust or Staining</p>	<p>No rust observed</p>
<p> Spalling</p>	<p>Some spalling on concrete walls</p>
<p> Any Visible Reinforcing</p>	<p>None observed</p>
<p> Any Seepage or Efflorescence</p>	<p>Some efflorescence on walls</p>
<p> Drain Holes</p>	<p>None</p>
<p>c. Discharge Channel</p>	<p>Channel and spillway are combined</p>
<p> General Condition</p>	<p>Good</p>
<p> Loose Rock Overhanging Channel</p>	<p>None</p>
<p> Trees Overhanging Channel</p>	<p>None</p>
<p> Floor of Channel</p>	<p>Concrete-good</p>
<p> Other Obstructions</p>	<p>None</p>
	<p>Beyond concrete spillway is 24" underground conduit which discharges in woods approximately 350 feet downstream.</p>

PERIODIC INSPECTION CHECK LIST

PROJECT Overlook Reservoir DATE April 11, 1979
 PROJECT FEATURE Service Bridge NAME Ron Chenev
 DISCIPLINE Structural Engineer NAME Dan LaGatta
Geotechnical Engineer

AREA EVALUATED	CONDITIONS
<p><u>OUTLET WORKS - SERVICE BRIDGE</u></p> <p>a. Super Structure</p> <p style="padding-left: 20px;">Bearings</p> <p style="padding-left: 20px;">Anchor Bolts</p> <p style="padding-left: 20px;">Bridge Seat</p> <p style="padding-left: 20px;">Longitudinal Members</p> <p style="padding-left: 20px;">Under Side of Deck</p> <p style="padding-left: 20px;">Secondary Bracing</p> <p style="padding-left: 20px;">Deck</p> <p style="padding-left: 20px;">Drainage System</p> <p style="padding-left: 20px;">Railings</p> <p style="padding-left: 20px;">Expansion Joints</p> <p style="padding-left: 20px;">Paint</p> <p>b. Abutment and Piers</p> <p style="padding-left: 20px;">General Condition of Concrete</p> <p style="padding-left: 20px;">Alignment of Abutment</p> <p style="padding-left: 20px;">Approach to Bridge</p> <p style="padding-left: 20px;">Condition of Seat and Backwall</p>	<p>Bridge being replaced.</p> <p>Bridge leads to intake building</p> <p>Stone</p> <p>Welded steel rods</p> <p>Stone</p> <p>Steel</p> <p>No deck-being replaced</p> <p>Steel</p> <p>None-being replaced</p> <p>None</p> <p>Steel</p> <p>None</p> <p>Recently-bridge is new</p> <p>Stone work appears good</p> <p>Good</p> <p>Good</p> <p>Good</p>

APPENDIX B
ENGINEERING DATA




LIST OF ENGINEERING DATA


1. Limited Design Plans
2. Post Construction Inspection Reports

Item 1 is available at the City of Fitchburg
Engineering Department

Item 2 is available at:




- a. Worcester County Court House Engineering Department
- b. Department of Environmental Quality Engineering
Division of Waterways
100 Nashua Street
Boston, Massachusetts 02014





PLAN VIEW

1133



STA. 0+00= MASONRY WALL ON UPSTREAM SLOPE LEFT ABUTMENT
 3+70= MASONRY WALL ON UPSTREAM SLOPE RIGHT ABUTMENT

PLAN & ELEVATION VIEWS
 DEVELOPED FROM RECORD
 PLANS & ON-SITE FIELD INSPECTION.

HAYDEN, HARDING & BUCHANAN, INC. CONSULTING ENGINEERS BOSTON, MASSACHUSETTS	U.S. ARMY ENGINEER CORPS WALT
---	----------------------------------


NATIONAL PROGRAM OF INSPECTION OF

OVERLOOK RESERVOIR

FITCHBURG

JUNE, 1977

293



STA. 0+00 = MASONRY WALL ON UPSTREAM SLOPE LEFT ABUTMENT
 3+70 = MASONRY WALL ON UPSTREAM SLOPE RIGHT ABUTMENT

HAYDEN, HARDING & BUCHANAN, INC CONSULTING ENGINEERS BOSTON, MASSACHUSETTS	U.S. ARMY ENGINEER DIV NEW ENGLAND CORPS OF ENGINEERS WALTHAM, MASS
--	---

NATIONAL PROGRAM OF INSPECTION OF NON-FED DAMS

VIEWS
 RECORD
 FLD INSPECTION.



OVERLOOK RESERVOIR

FITCHBURG

MASSACHUSETTS

SCALE AS SHOWN TO SCALE
 DATE JUNE, 1979


303





SECTION THROUGH INTAKE STRUCTURE

B-4

103



SECTION AT INTAKE STRUCTURE



SECTION DEVELOPED FROM
PLAN AND ONSITE FILE

HAYDEN HARDING & BUCHANAN, INC.
CONSULTING ENGINEERS
BOSTON, MASSACHUSETTS

U.S. ARMY ENGINEER
CORPS OF
WALTHAM

NATIONAL PROGRAM OF INSPECTION OF NON-FERROUS


OVERLOOK RESERVOIR

FITCHBURG

MA

SCALE NOT TO SCALE
DATE AUGUST, 1958

293



INTAKE STRUCTURE

SECTION DEVELOPED FROM RECORD
PLAN AND ONSITE FIELD INSPECTION

HAYDEN HARRING & BUCHANAN, INC.
CONSULTING ENGINEERS
BOSTON, MASSACHUSETTS

U.S. ARMY ENGINEER DIV. NEW ENGLAND
CORPS OF ENGINEERS
WALTHAM, MASS.



NATIONAL PROGRAM OF INSPECTION OF NON-FED DAMS


OVERLOOK RESERVOIR DAM

FITCHBURG



MASSACHUSETTS

SCALE: NOT TO SCALE
DATE: AUGUST, 1980





SECTION C-C



SECTION B-B

HAYDEN, HARDING & BUCHANAN, INC CONSULTING ENGINEERS BOSTON, MASSACHUSETTS	U.S. ARMY ENGINEER DISTRICT CORPS OF ENGINEERS WALTHAM, MASS.
--	---

NATIONAL PROGRAM OF INSPECTION OF NON-

OVERLOOK RESERVOIR D


FITCHBURG

MASS.


SCALE NOT TO SCALE
DATE JULY, 1980

PLAN & ELEVATION
VIEWS DEVELOPED
FROM JUNE 1980
ON-SITE INSPECTION

493



-C



SECTION B-B

HAYDEN, HARDING & BUCHANAN, INC. CONSULTING ENGINEERS BOSTON, MASSACHUSETTS		U.S. ARMY ENGINEER DIV NEW ENGLAND CORPS OF ENGINEERS WALTHAM, MASS	
NATIONAL PROGRAM OF INSPECTION OF NON-FED. DAMS			
OVERLOOK RESERVOIR DIKE			
FITCHBURG		MASSACHUSETTS	
		SCALE NOT TO SCALE	
		DATE JULY, 1980	

313

12-30-77



The Commonwealth of Massachusetts

Executive Office of Environmental Affairs
Department of Environmental Quality Engineering

Division of Waterways

100 Nassau Street, Boston 02111

December 21, 1977

Refer to General

The Honorable Hedley Bray, Mayor
City of Fitchburg
City Hall
718 Main Street
Fitchburg, Mass.

RE: Dam #3-14-97-28 Cverlook Reservoir (So. Dyke)
Dam #3-14-97-28.1 Cverlook Reservoir Dam
Dam #3-14-97-34 Lovell Reservoir Dam
Dam #3-14-97-37 Scott Reservoir Dam

Dear Mayor Bray:

On February 10 and 24, 1977 you were notified of the unsafe condition of the above referenced dams. You were urged on both occasions to obtain the services of a Registered Professional Engineer. (RPE)

Please advise me by January 6, 1978 the name(s) of the RPE(s) the City has retained to cversee the rehabilitation of these structures.

Provided herewith is a copy of Chapter 253 Sections 14-49 inclusive as amended by Chapter 706 of 1975 of the Massachusetts General Laws that define our jurisdiction and authority should any order not be complied with.

If you have any questions or need assistance in this matter please contact me in Boston.

Sincerely,

For the Commissioner

John J. Ramon
JOHN J. RAMON, P.E.
CHIEF ENGINEER

DEC 30 11 27 AM '77
PUBLIC WORKS DEPT.
FITCHBURG, MASS.

EHM:bjm
Encl.


CC: David Standley, Comm.
Gilbert Joly, REE
John J. Lyons, DRE
Willis Regan, Dist. #3
Al McCallum

DEC 30 1977

MAYOR'S OFFICE

B-6

Copy available to DTIC does not permit fully legible reproduction



The Commonwealth of Massachusetts

EXECUTIVE OFFICE OF ENVIRONMENTAL AFFAIRS
DEPARTMENT OF ENVIRONMENTAL QUALITY ENGR.
DIVISION OF WATERWAYS

100 Nashua Street, Boston 02114

February 24, 1977

The Honorable Hedley Bray
Mayor, City of Fitchburg
City Hall
718 Main Street
Fitchburg, Mass.

RECEIVED

FEB 28 1977

RE: Letters dated 2.10.77

Insp. Dams #3-14-97.28.1	Overlook Reser. Dam	MA
" " #3-14-97-34	Lovell Reserv. Dam	
" " #3-14-97-28	Overlook Reser. (So. Dyke)	
" " #3-14-97-37	Scott Reser. Dam	

Fitchburg, Mass.

Dear Mayor Bray:

On June 10, 1976, an Engineer from Mass. Department of Public Works made an inspection of the above dams. Our records indicate the owner to be the City of Fitchburg. As a result of these inspections this Division has rated these structures unsafe and has duly notified you of their condition (ltrs. dated 2.10.77).

We again urge you to obtain the services of a Registered Professional Engineer, experienced in the design, maintenance and construction of dams in order that you may pursue remedy as quickly as possible.

Enclosed is a Department application form which must be completed and returned to this office for review and approval before any major repairs or alterations begin.

Please notify this Division of your intentions or measures in process which will correct this situation.

If we may be of assistance, do not hesitate to contact us. With any correspondence, please include the number of the dam as indicated above.

Very truly yours,

JOHN J. HANNON, P.E.
CHIEF ENGINEER

F.DeR.:eh

CC: D.H.E. DIST. #3

D.D.E. " #3

Ernie Giroud, Conmr. D.P.W.

INSPECTION REPORT - DAMS AND RESERVOIRS

1. Location: City/Town Fitchburg Dam No. 3-14-97-28

Name of Dam Overlook Reservoir Inspected by Regan, Rizkalla

Main (South) DIKE Date of Inspection 6/10/76

2. Owner/s: per: Assessors _____ Prev. Inspection

Reg. of Deeds _____ Pers. Contact _____

1. The Hon. Hedley Bray - Mayor - City Hall - 718 Main St. - Fitchburg
 Name Copy To St. & No. _____ City/Town State Tel. No. _____

2. Ernie Giroud - Comm of Public Works - Fitchburg
 Name _____ St. & No. _____ City/Town State Tel. No. _____

3. _____
 Name _____ St. & No. _____ City/Town State Tel. No. _____

3. Caretaker (if any) e.g. superintendent, plant manager, appointed by absentee owner, appointed by multi owners.

Name: _____ St. & No.: _____

City/Town: _____ State: _____ Tel. No.: _____

4. No. of Pictures taken _____

5. Degree of Hazard: (if dam should fail completely)*

1. Minor _____ 2. Moderate

3. Severe To 4. Disastrous _____

* This rating may change as land use changes (future development)

6. Outlet Control: Automatic _____ Manual _____

Operative _____ yes; _____ No.

Comments:

7. Upstream Face of Dam: Condition:

1. Good _____ 2. Minor Repairs

3. Major Repairs _____ 4. Urgent Repairs _____

on Comments: 15'± Eroded Area just West of Gate House Cat Walk. Remove light growth of brush on U.S. face above RIP RAP

8. Downstream Face of Dam:

Condition: 1. Good _____ 2. Minor Repairs _____
3. Major Repairs _____ 4. Urgent Repairs _____

* Comments: Heavy Growth of Brush on d.s. Slope. Seepage Noted on 5/6/75 Report has Abated, Now could be described as moderate rather than heavy

9. Emergency Spillway: ^{to} None - Spillway is located on isolated main dike (dam # 28.1)

Condition: 1. Good _____ 2. Minor Repairs _____
3. Major Repairs _____ 4. Urgent Repairs _____

Comments:

10. Water Level at time of inspection: 9 1/2 ft. above _____ below _____
top of dam Emb. principal spillway _____
other _____

11. Summary of Deficiencies Noted:

- Growth (Trees and Brush) on Embankment _____
- Animal Burrows and Washouts _____
- Damage to slopes or top of dam See (7) _____
- Cracked or Damaged Masonry _____
- Evidence of Seepage _____
- Evidence of Piping _____
- Erosion _____
- Leaks _____
- Trash and/or debris impeding flow _____
- Clogged or blocked spillway _____
- Other _____

* Note: Reduction in Seepage flow may be largely due to reduced upper pool elevation.

12. Remarks & Recommendations: (Fully Explain) *None of the conditions noted on the 5/6/75 report have been rectified. Seepage has abated, but this is probably due to the lower Reservoir^{W.S.} Elevation. The growth of brush is now much heavier and inspection was^{consequently} impeded.*

13. Overall Condition: *should be determined by Consultant*

- 1. Safe INSPECTION
- 2. Minor repairs needed _____
- 3. Conditionally safe - major repairs needed _____
- 4. Unsafe _____
- 5. Reservoir impoundment no longer exists (explain)
Recommend removal from inspection list _____

INSPECTION REPORT - DAMS AND RESERVOIRS

1. Location: City/Town Fitchburg Dam No. 3-1A-97-28
Name of Dam Overlook Reservoir Inspected by REGAN RIZALLA
MAIN (South) DIKE Date of Inspection 5/6/75

2. Owner/s: per: Assessors _____ Prev. Inspection _____
Reg. of Deeds _____ Pers. Contact

1. The Hon. Hedley Bray - MAYOR City Hall - 718 MAIN St. - Fitchburg, MASS
Name Copy To St. & No. City/Town State Tel. No.

2. George Lavidis - P.W. Commissioner & City Engineer - City Hall
Name St. & No. City/Town State Tel. No.

3. _____
Name St. & No. City/Town State Tel. No.

3. Caretaker (if any) e.g. superintendent, plant manager, appointed by absentee owner, appointed by multi owners.

Name: _____ St. & No.: _____
City/Town: _____ State: _____ Tel. No.: _____

4. No. of Pictures taken _____

5. Degree of Hazard: (if dam should fail completely)*

1. Minor _____ 2. Moderate _____
3. Severe _____ 4. Disastrous _____

* This rating may change as land use changes (future development)

6. Outlet Control: Automatic _____ Manual _____
Operative yes; _____ No.

Comments: Gated MAIN

7. Upstream Face of Dam: Condition:

1. Good _____ 2. Minor Repairs _____
3. Major Repairs _____ 4. Urgent Repairs _____

Comments: More Slope Protection (rip rap) needed on the 15' stretch of the no. face ~~at~~ just west of the Gate House cat walk

8. Downstream Face of Dam:

Condition: 1. Good _____ 2. Minor Repairs ✓
3. Major Repairs To ✓ 4. Urgent Repairs _____

Comments: Brush on D.S. Face 30' x 30' x 30' Seepage Δ 60' ± West of Chlorination Building @ toe of Slope. Light Flow Visible From This. For other remarks Relative to Seepage See (12)

9. Emergency Spillway: None - Spillway is located on isolated N.E. DIKE (See Report on 3-14-97-28.1)

Condition: 1. Good _____ 2. Minor Repairs _____
3. Major Repairs _____ 4. Urgent Repairs _____

Comments:

10. Water Level at time of inspection: 6 ± ft. above _____ below ✓
top of dam Emb. _____ principal spillway _____
other _____

11. Summary of Deficiencies Noted:

- a) Growth (Trees and Brush) on Embankment Brush on D.S. Face
- b) Animal Burrows and Washouts 1 Noted on D.S. Face
- c) Damage to slopes or top of dam ✓ WAVE ACTION CAUSING SOME DETEIORATION ON D.S. FACE JUST WEST OF GATE HOUSE CATWALK
- d) Cracked or Damaged Masonry _____
- e) Evidence of Seepage ✓
- f) Evidence of Piping _____
- g) Erosion See (c)
- h) Leaks _____
- i) Trash and/or debris impeding flow _____
- j) Clogged or blocked spillway _____
- k) Other _____

Copy available to DTIC does not permit fully legible reproduction

12. Remarks & Recommendations: (Fully Explain)

There is Fairly heavy Seepage Through This dam. I was told by people at the Fitchburg Water Dept that it was necessary to place a Gravel Pad adjacent to the pump house in order to have access to this area, as this area (@ the d.s. Tie) had become saturated. The drainage flows out of the d.s. end of this pad through 2 8" pipes flowing full. In addition to this there is the Seepage Area described in (8). A mitigating factor here is that (as per water dept people) this seepage is of long duration, and the dam has been standing for 100 years. However, the seepage flow has ^{Not} never been metered in ~~the~~ recent memory (as per the same sources) it is fairly heavy, and the downstream hazard is at least moderate.

ON THIS basis I feel that a Consultant inspection is desirable.

13. Overall Condition:

1. Safe _____
2. ^{at least} Minor repairs needed, Inspection by Consultant desirable
3. Conditionally safe - major repairs needed _____
4. Unsafe _____
5. Reservoir impoundment no longer exists (explain)
Recommend removal from inspection list _____

DESCRIPTION OF DAM

DISTRICT 3

Submitted by W. REGAN Dam No. 3-14-97-28

Date 5/30/75 City/Town Fitchburg

Name of Dam Overlook Reservoir
MAN (South) DIKE

1. Location: Topo Sheet No. 19D

Provide 8½" x 11" in clear copy of topo map with location of Dam clearly indicated.

2. Year built: 1872 Year/s of subsequent repairs N/A

3. Purpose of Dam: Water Supply Recreational _____
Irrigation _____ Other _____

4. Drainage Area: 0.15 sq. mi. _____ acres

5. Normal Ponding Area: 13± acres; Ave. depth _____

Impoundment: 50 million gals.; _____ acre ft.

6. No. and type of dwellings located adjacent to pond or reservoir
1 Summer Cabin i.e. summer homes, etc. + 1 City Chlorination Plant

7. Dimensions of Dam: Length 270'± Max. Height 30'±

Slopes: Upstream Face 2:1

Downstream Face 2:1

Width across top 20'±

* Information regarding
Possible Presence of a
Conc. Core Wall
Not Available

8. Classification of Dam by Material:

Earth ^{*} Conc. Masonry see note Above Stone Masonry Gate House

Timber _____ Rockfill _____ Other RIP RIP U.S. FACE

9. A. Description of present land usage downstream of dam:

70 % ^{Res. dental + RURAL} rural; 30 % urban.

B. Is there a storage area or flood plain downstream of dam which could accomodate the impoundment in the event of a complete dam failure? yes _____ no

B-14

Copy available to DTIC does not
permit fully legible reproduction

10. Risk to life and property in event of complete failure.

See Note Below

No. of people _____.

No. of homes _____.

No. of Businesses _____.

No. of industries _____ Type _____.

No. of utilities _____ Type _____.

Railroads _____.

Other dams _____.

Other _____.

11. Attach Sketch of dam to this form showing section and plan on 8 1/2" x 11" sheet.

12. How to Locate:

W.B. ON Rtes. 2A-31 overlap (Main St.) Bear Rt on MAIN St. where the numbered Rtes Bear Left to Cross the N. WASHUA RIVER. TRAVEL TO CALDWELL St. & ~~Left~~ RT. TRAVEL TO THE POINT WHERE CALDWELL St. is now dead ended (Adjacent to the MARSHALL Reservoir). There is a dirt drive just S. of the MARSHALL Res. which leads to the Overlook Reservoir MAIN DIKE.


Note (10): Before Reaching the N. WASHUA River, discharge is a Threat to life & Property at the following:

- ① 3 Residences (multifamily)
- ② 1 Church.

It is a Threat to Property at the following:

- ① it would wash out 1 Road Crossing (and the associated Utilities)
- ② it would probably cause Foundation Flooding of 2 mill buildings
- ③ It is a possible threat to Property downstream on the N. WASHUA

Copy available to DTIC does not permit fully legible reproduction



* SECTION A-A

* Note - This dike built in 1871
it is not certain that it has a
concrete wall

Fitchburg-Overlook Reservoir
Main (South) DIKE

3-14-97 - 28.

TOWN Fitchburg DAM NO. 16-28

LOCATION 1400' southerly - Flat Rock Rd. STREAM -

- On a Private Road. Overlook Reservoir

WORCESTER COUNTY ENGINEERING DEPARTMENT
WORCESTER, MASSACHUSETTS

D A M I N S P E C T I O N R E P O R T

Owned by City of Fitchburg Place Water Dept. Use Water Supp.

Inspected by WOL. Date Oct. 20 1964

Type of Dam Earth dam Condition Good

SPILLWAY

Flashboards in Place _____ Recent Repairs _____

Condition No spillway

Repairs Needed (The deed says that the land area is 26.67 acres and the pond area is 13.65 acres.)

EMBANKMENT

Recent Repairs The brush has recently been cut on this embankment

Condition There is a roadway on top of this dam.

Repairs Needed _____

GATES

Recent Repairs _____

Condition The gate is located in a bed of granite stone

Repairs Needed gate-house.

LEAKS

How Serious No leaks.

DATE: _____ County Engineer

TOWN Fitchburg
LOCATION Overlook Res.

DAM NO. 16-2
STREAM _____

WORCESTER COUNTY ENGINEERING DEPARTMENT
WORCESTER, MASSACHUSETTS
DAM INSPECTION REPORT

OWNED BY City of Fitchburg PLACE _____ USE Drinking water
INSPECTED BY Curcuran DATE Apr 2, 1958
TYPE OF DAM Earthen CONDITION Good

SPILLWAY

FLASHBOARDS IN PLACE None RECENT REPAIRS _____
CONDITION Good 1/2" water over spillway
REPAIRS NEEDED _____

EMBANKMENT

RECENT REPAIRS _____
CONDITION Good
REPAIRS NEEDED _____

GATES

RECENT REPAIRS _____
CONDITION Good
REPAIRS NEEDED _____

LEAKS

HOW SERIOUS _____

DATE _____

TOWN Fitchburg

DAM NO. 18-2

LOCATION Overlook Res.

STREAM _____

WORCESTER COUNTY ENGINEERING DEPARTMENT
WORCESTER, MASSACHUSETTS
DAM INSPECTION REPORT

OWNED BY Fitchburg Water Dept. PLACE Fitchburg USE High level reservoir

INSPECTED BY Joe Pierce DATE Jan. 14, 1949

TYPE OF DAM Earth reservoir masonry CONDITION good

SPILLWAY

FLASHBOARDS IN PLACE _____ RECENT REPAIRS _____

CONDITION _____

REPAIRS NEEDED none

EMBANKMENT

RECENT REPAIRS none

CONDITION good

REPAIRS NEEDED none

GATES

RECENT REPAIRS none

CONDITION Mr. Pierce says OK

REPAIRS NEEDED none

LEAKS

HOW SERIOUS none visible

DATE _____

COUNTY OF WORCESTER MASSACHUSETTS

COUNTY ENGINEER

Inspection of Dams, Reservoir Dams, and Reservoirs.

Inspected by L. O. H. & A. W. F. Brown Date Feb. 23, 1933 Dam No. 16-28

Town Fitchburg Location Overlook Reservoir.

Owner Fitchburg Water Dept. Use

Material and Type

Dam Designed by Phineas Ball-Worc. Constructed by Geo. Norman Year 1872

SPILLWAY—Length.....Feet. Depth.....Feet

El. top Abutment.....El. Crest.....El. Apron.....El. Streambed.....

Width top Abutment.....Width top Crest.....Width bottom Spillway.....

Width Flashboards carried.....Kind Flashboards.....

El. Flowline Cleanout Pipe.....Size and Kind Cleanout Pipe.....

Kind of Foundation under Spillway.....

Condition.....None, 40' water at dam.

EMBANKMENT—Length overall.....Feet

El. Top.....El. Natural Ground.....Width Top.....

Width of Bottom.....Upstream Slope.....Downstream Slope.....

Kind of Corewall.....Riprap.....

Material in Embankment.....Foundation.....

Condition.....O. K.

GATES.....Location.....

Size.....Kind.....El. Flowline.....

Condition.....O. K.

WHEEL.....Kind.....Size.....Rated H. P.....

Location.....Ave. Head.....

Evidence of Leaks in Structure.....Small seepage at north end. Not dangerous.

Small seepage at slope downstream face dam.

Recent Repairs and Date.....

Topography of Country below Dam.....

Nature of Buildings and Roads below Dam.....

Number of Acres in Pond.....Drainage Area in Square Miles.....

Discharge in Second Feet per Square Mile.....

Estimated Storage Million Cubic Feet B-20

Decree No.

Dam No. 16-28 ✓

COUNTY OF WORCESTER, MASSACHUSETTS
OFFICE OF COUNTY ENGINEER

Neg. Nos.

INSPECTION OF DAMS, RESERVOIR DAMS AND RESERVOIRS

Town Fitchburg ✓ Date Oct. 17, 1924 ✓ Dam No.

Location 1. N.W. Corner ✓ Name of Pond or Stream Over look Res. ✓

Inspected by L.O. Marden ✓

Owner City of Fitchburg ✓ Use

MATERIAL & TYPE Earthen Embankment ✓

Elevations in feet: above (+) or below (-) full pond or reservoir level.

FOR DAM Bed of stream below top of spillway

FOR RESERVOIR

top of dam 100 ✓ top of flashboards ground surface below 80 ✓

..... level of overflow pipe length in feet 300 ✓

width top in feet width bottom in feet size pipe to mill

..... inches length spillway in feet head in feet

Size of wheel H. P. developed

Size of gates location of gates

Foundation and details of construction Rocky soil ✓

..... condition of embankment good ✓

Constructed by date

Designed by location

Recent repairs and date none ✓

Evidence of leakage none ✓

Condition good ✓

Topography of country below

Nature of buildings and roads below dam

No. Acres in watershed No. Acres in pond

Plans secured Percent watershed in cultivation

Percent in forests Note: Cross out word not applicable

INSPECTION REPORT - DAMS AND RESERVOIRS

1. Location: City/Town Fitzburg Dam No. 3-14-71-291
Name of Dam Overlook Reservoir Inspected by REGAN, RIZKALLA
Gregory (Northeast) DIKE Date of Inspection 6-10-76

2. Owner/s: per: Assessors _____ Prev. Inspection
Reg. of Deeds _____ Pers. Contact _____

1. The Hon. Hedley Bray - Mayor City Hall - 718 MAIN St. - Fitzburg
Name St. & No. City/Town State Tel. No.

2. _____
Name St. & No. City/Town State Tel. No.

3. _____
Name St. & No. City/Town State Tel. No.

3. Caretaker (if any) e.g. superintendent, plant manager, appointed by absentee owner, appointed by multi owners.

Name: _____ St. & No.: _____
City/Town: _____ State: _____ Tel.No.: _____

4. No. of Pictures taken _____

5. Degree of Hazard: (if dam should fail completely)*

1. Minor _____ 2. Moderate
3. Severe 4. Disastrous _____

* This rating may change as land use changes (future development)

6. Outlet Control: Automatic _____ Manual
Operative yes; _____ No.

Comments: SITED DAMS

7. Upstream Face of Dam: Condition:

1. Good _____ 2. Minor Repairs
3. Major Repairs _____ 4. Urgent Repairs _____

Comments: REMOVE BRUSH

Copy available to DTIC does not permit fully legible reproduction

8. Downstream Face of Dam:

Condition: 1. Good _____ 2. Minor Repairs ✓
3. Major Repairs ✓ 4. Urgent Repairs _____

Comments: Remove heavy growth of Trees & brush
Moderate Seepage @ Numerous Locations Along
principal Toe of Slope

9. Emergency Spillway:

Condition: 1. Good _____ 2. Minor Repairs ✓
3. Major Repairs _____ 4. Urgent Repairs _____

Comments: Minor Spalling Top of North
Checkwall

10. Water Level at time of inspection: 1 1/2 ± ft. above _____ below ✓
top of dam _____ principal spillway INVERT
other _____

11. Summary of Deficiencies Noted:

- Growth (Trees and Brush) on Embankment Very heavy - D.S. FACE
- ~~Animal Burrows and Washouts~~ Erosion adjacent to D.S. End
- Damage to slopes or top of dam Checkwall
- Cracked or Damaged Masonry _____
- Evidence of Seepage ✓
- Evidence of Piping _____
- Erosion ✓
- Leaks _____
- Trash and/or debris impeding flow _____
- Clogged or blocked spillway _____
- Other _____

Copy available to DTIC does not permit fully legible reproduction

12. Remarks & Recommendations: (Fully Explain)

None of the deficiencies noted in the '75 report have been corrected. Leakage at the D.S. is heavier despite lower Reservoir W.S. Elevation. This dam is in better shape than Lovell and Scott, but a consultant inspection is still warranted.

13. Overall Condition: Should be determined by in depth

- 1. Safe Consultant Inspection
 - 2. Minor repairs needed _____
 - 3. Conditionally safe - major repairs needed _____
 - 4. Unsafe _____
 - 5. Reservoir impoundment no longer exists (explain)
- Recommend removal from inspection list _____

Copy available to DTIC does not permit fully legible reproduction

INSPECTION REPORT - DAMS AND RESERVOIRS

1. Location: City/Town Fitchburg Dam No. 3-14-97-281
Name of Dam Overlook Reservoir Inspected by Regan RIZKALLA
Secondary (N.East) DIKE Date of Inspection 5/2/75

2. Owner/s: per: Assessors _____ Prev. Inspection _____
Reg. of Deeds _____ Pers. Contact

- 1. The Hon Hedley Gray Mayor - City Hall - 713 Main St. - Fitchburg - MASS
Name Copy to _____ St. & No. _____ City/Town State Tel. No. _____
- 2. George LANIDES P.W. Commissioner & City Engineer - City Hall
Name _____ St. & No. _____ City/Town State Tel, No. _____
- 3. _____
Name: _____ St. & No. _____ City/Town State Tel. No. _____

3. Caretaker (if any) e.g. superintendent, plant manager, appointed by absentee owner, appointed by multi owners.

Name: _____ St. & No.: _____
City/Town: _____ State: _____ Tel.No.: _____

4. No. of Pictures taken _____

5. Degree of Hazard: (if dam should fail completely)*

- 1. Minor _____ 2. Moderate
- 3. Severe ^{To} _____ 4. Disastrous _____

* This rating may change as land use changes (future development)

6. Outlet Control: Automatic _____ Manual
Operative yes; _____ No.

Comments: Gated MAINS

7. Upstream Face of Dam: Condition:

- 1. Good _____ 2. Minor Repairs
- 3. Major Repairs _____ 4. Urgent Repairs _____

Comments: Remove Brush

8. Downstream Face of Dam:

Condition: 1. Good _____ 2. Minor Repairs ✓
3. Major Repairs ✓ 4. Urgent Repairs _____

Comments: Remove heavy growth of Trees & Brush - Seepage in Evidence Along toe of Slope - Numerous locations

9. Emergency Spillway:

Condition: 1. Good ✓ To 2. Minor Repairs ✓
3. Major Repairs _____ 4. Urgent Repairs _____

Comments: Spilled Concrete - Top Center of N. Spillway Sidewall otherwise Spillway is in good Cond.
Concrete Face

10. Water Level at time of inspection: 8± ft. above _____ below ✓
top of dam Emb. _____ principal spillway _____
other 3"± below Spillway Invert

11. Summary of Deficiencies Noted:

A) Growth (Trees and Brush) on Embankment ✓

B) ~~Animal Burrows~~ and Washouts Erosion adjacent To d.S. End Back of South Sidewall of Spillway

C) Damage to slopes or top of dam _____

D) Cracked or Damaged Masonry See (9)

E) Evidence of Seepage ✓

F) Evidence of Piping _____

G) Erosion See 11 B Above

H) Leaks _____

I) Trash and/or debris impeding flow _____

J) Clogged or blocked spillway _____

K) Other _____

12. Remarks & Recommendations: (Fully Explain)

The Seepage through this dike is of a much smaller volume than that through # 97-28. and Retention of a Consultant for inspection of this dam is desirable but not as imperative as for dam # 97-28.

13. Overall Condition:

- 1. Safe _____
- 2. Minor repairs needed ✓ & in depth IASA desirable
- 3. Conditionally safe - major repairs needed _____
- 4. Unsafe _____
- 5. Reservoir impoundment no longer exists (explain)
Recommend removal from inspection list _____

DESCRIPTION OF DAM

DISTRICT 3Submitted by W. REGAN Dam No. 3-14-97-28.1Date 5/30/75 City/Town FitchburgName of Dam Overlook Reservoir
Secondary (Northeast) dike1. Location: Topo Sheet No. 19D

Provide 8½" x 11" in clear copy of topo map with location of Dam clearly indicated.

2. Year built: 1872 Year/s of subsequent repairs N/A3. Purpose of Dam: Water Supply Recreational _____

Irrigation _____ Other _____

4. Drainage Area: 0.15 sq. mi. _____ acres5. Normal Ponding Area: 13± acres; Ave. depth _____Impoundment: 50 million gals.; _____ acre ft.6. No. and type of dwellings located adjacent to pond or reservoir
1 Summer Camp i.e. summer homes, etc. 1 City Chlorination Bldg.7. Dimensions of Dam: Length 1000± Max. Height 20±Slopes: Upstream Face 2:1Downstream Face 2:1Width across top 20±

8. Classification of Dam by Material:

Earth Conc. Masonry Stone Masonry _____Timber _____ Rockfill _____ Other RIP RAP U.S. FACE

9. A. Description of present land usage downstream of dam:

80 % rural; 20 % urban.B. Is there a storage area or flood plain downstream of dam which could accomodate the impoundment in the event of a complete dam failure? yes _____ no

10. Risk to life and property in event of complete failure.

See Note Below

- No. of people _____
- No. of homes _____
- No. of Businesses _____
- No. of industries _____ Type _____
- No. of utilities _____ Type _____
- Railroads _____
- Other dams _____
- Other _____


11. Attach Sketch of dam to this form showing section and plan on 8 1/2" x 11" sheet.

12. How to Locate: ~~At~~ W.G. ON THE Rte 2A ~~at~~ overlap (MAIN ST.) Bear Straight Ahead (where 2A-31 overlap starts) onto Prospect St. TRAVEL UP PROSPECT TO THE PROSPECT ST. - Flat Rock Rd (GRAV.) intersection. Dam is immediately adjacent to and north of this intersection.

Note (10) Failure discharge could take 2 courses, depending upon Failure locus.

- ① Discharge would be a threat to life & property to at least 3 residences on Prospect St. It would threaten numerous other residences @ the southern end of Prospect St. Street with at least heavy property damage. This would be true at numerous other residences in a moderately well developed area adjacent to the Virginia River, and @ the southern end of Prospect St.
- ② Discharge flow down into the dam No. 77-464 U.S. Basin where storage is inadequate, overlap & wash out Burbank. Flow down to dam No. 77-463, overlap same, and then flow down to a small contained area between Rte 31 and North Washburn where the threat to utilities other property, roads and other structures is a possibility to be noted.

Copy available to DTIC does not permit fully legible reproduction



RESERVOIR

SECTION A-A


Fitchburg-Overlook Reservoir
Secondary N.E. Fork of Millway

3-14-77-281


B-30

Copy available to DTIC does not permit fully legible reproduction

APPENDIX C
PHOTOGRAPHS




MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A



PLAN VIEW OF DAM

113



PLAN VIEW OF DIKE AND SPILLWAY

PLAN & ELEVATION VIEWS
DEVELOPED FROM RECORD
PLANS & ON-SITE FIELD INSPECTION.

HAYDEN, HARDING & BUCHANAN, INC CONSULTING ENGINEERS BOSTON, MASSACHUSETTS	U.S. ARMY ENGINEER DIVISION CORPS OF ENGINEERS WALTHAM, MASS.
--	---

NATIONAL PROGRAM OF INSPECTION OF NON-F

LOCATION OF PHOTOGRAPHS


OVERLOOK RESERVOIR
DAM & DIKE

FITCHBURG

MASSACHUSETTS

SCALE NOT TO SCALE
DATE JULY 1960

288



PLAN VIEW OF DIKE
AND SPILLWAY

HAYDEN, HARDING & BUCHANAN, INC CONSULTING ENGINEERS BOSTON, MASSACHUSETTS	U.S. ARMY ENGINEER DIV NEW ENGLAND CORPS OF ENGINEERS WALTHAM, MASS
NATIONAL PROGRAM OF INSPECTION OF NON-FED DAMS	
LOCATION OF PHOTOGRAPHS OVERLOOK RESERVOIR DAM & DIKE	
FITCHBURG	MASSACHUSETTS
SCALE NOT TO SCALE	
DATE JULY 1980	

INSPECTION.

303



PHOTO NO. 1 View of 12" diameter pipe discharging clear water into stream, downstream of dam and chlorination building.




PHOTO NO. 2 General view showing location of discharging pipe in Photo No. 1 and spring with respect to the dam seen in background.



PHOTO NO. 3 View of 1 to 2
inch diameter plastic pipes
discharging clear water down-
stream of chlorination building,
seen in background.




PHOTO NO. 4 View of downstream face from the left abutment.



PHOTO NO. 5 View of crest and gatehouse from the left abutment.



PHOTO NO. 6 View of upstream slope from the right abutment. Note two types of riprap.



PHOTO NO. 7 Downstream view of toe-of-dam area and outlet channel. Chlorination building is at left of photograph.



PHOTO NO. 8 Upstream view of reservoir area showing dike and spillway.



PHOTO NO. 9 View of spillway showing riprap approach.




PHOTO NO. 10 Twenty-four inch outlet pipe at downstream end of spillway.



PHOTO NO. 11 Dike area to right side of spillway.



PHOTO NO. 12 View of dike area along access road.



Photo No. 13 Twenty-four inch inlet pipe from Shattuck Brook/Scott Reservoir located to the left of spillway.



Photo No. 14 Outlet for 24 inch pipe shown in Photo No. 10. Outlet is located approximately 350 feet downstream of spillway.




Photo No. 15 Crest of dike from
point of curvature to right abutment.

Photo No. 16 Erosion due to
trespassing on downstream
slope at point of curvature.





Photo No. 17 Upstream slope of dike viewed from spillway toward point of curvature.



Photo No. 18 Downstream slope of dike at midheight viewed from the point of dike curvature toward the right abutment.



Photo No. 19 Wet area at downstream toe at point of curvature.



Photo No. 20 Riprap on upstream face from right abutment toward point of curvature.

APPENDIX D
HYDROLOGIC AND HYDRAULIC COMPUTATIONS

JOB NO. 78.244.1
 DATE 4-5-79
 BY MA
 CH'D BY PDD 4/23/79



HAYDEN, HARDING & BUCHANAN, INC.
 CONSULTING ENGINEERS
 BOSTON, MASSACHUSETTS

SHEET NO. 1
 JOB Dams
 SUBJECT Overlook
 CLIENT Corps

OVERLOOK RESERVOIR

Built: 1871 to 1872
 Water Supply: varies - small
 Surface Area: 10.0 a
 Drainage Area: 0.06[±] sm., 40.0[±] a

Dam Height: 40'± } Size Class: Small
 Storage: 276[±] a-f }

Hazard Potential: High

Test Flood: 1/2 PMF to PMF Range

Use 1/2 PMF

1/2 PMF = $3000 \times \frac{1}{2} \times 0.0625 = 94.3$ cfs Inflow
 dike spillway can pass 3447 cfs ∴ will pass
 100% of Test Flood outflow of 70 cfs
 at elev. 835.65'

Dam Failure Analysis

$$Q_b = \frac{8}{27} \times (0.4 \times 270') \times \sqrt{32.2} \times (40')^{1.5}$$

$$Q_b = 45,900.0 \pm \text{cfs failure outflow}$$

Damage Due to Failure Outflow

<u>Item</u>	<u>Number</u>	<u>Flood Stage</u>
Pump & Clz Buildings	3	12 to 18'
Roads	3	8' to 18'
Homes	20	8'
Church	1	8'
Mills	3±	8'
play grounds	1	8'

JOB NO. 78,292.1
 DATE 2-5-70
 BY MA
 CH'D BY FDD 4123179




HAYDEN, HARDING & BUCHANAN, INC.
 CONSULTING ENGINEERS
 BOSTON, MASSACHUSETTS

SHEET NO. 2
 JOB Dams
 SUBJECT Overlook
 CLIENT Comp

Storage Capacity

<u>Elev</u>	<u>Area</u>	<u>Ave A</u>	<u>D</u>	<u>d-f</u>	<u>Accum Stor</u>
800	1.8				
830	7.4	4.6	30	138	138
835.±	"s" 11.2	9.3	5.25	48.8	187
840.	15.6	13.4	4.75	63.7	251
841.5	"T" 17.4	16.5	1.5	24.8	276

Spillway Outflow



$S = 0.025 \text{ ft} \pm$ "assumed"

$$V = \frac{1,486}{.015} (R^{2/3}) S^{1/2} = R^{2/3} (15.7)$$

<u>D</u>	<u>WP</u>	<u>A</u>	<u>R^{2/3}</u>	<u>F'</u>	<u>V</u>	<u>Q</u>
1	12	10	0.89	15.66	13.9	139
2	14	20	1.27	"	19.89	398
3	16	30	1.52	"	23.86	716
4	18	40	-	-	-	-
5	20	50	1.85	"	28.93	1447
6	22	60	1.96	"	30.67	1840 cfs
0.5	11	5	0.59	"	9.23	46


JOB NO. 78,244.1
DATE 4-6-79
BY MA
CH'D BY FDD 4/23/79



HAYDEN, HARDING & BUCHANAN, INC.
CONSULTING ENGINEERS
BOSTON, MASSACHUSETTS

SHEET NO. 3
JOB Dams
SUBJECT Overlooks
CLIENT Corps

Stage Storage




JOB NO. 78.244.1
DATE 6-29-76
BY MA
CH'D BY FDD



HAYDEN, HARDING & BUCHANAN, INC.
CONSULTING ENGINEERS
BOSTON, MASSACHUSETTS

JOB Dams SHEET NO. 4
SUBJECT OVERLOOK
CLIENT COMPS

Stage Discharge



JOB NO. 78.244.1
DATE 4-19-79
BY MA
CH'D BY PDD 4123177



HAYDEN, HARDING & BUCHANAN, INC.
CONSULTING ENGINEERS
BOSTON, MASSACHUSETTS

SHEET NO. 5
JOB Dams
SUBJECT Overlook
CLIENT Corps

Test Flood Analysis

$$Q_{P_1} = \text{Inflow} = 94 \text{ cfs} \quad E_{1CU} = 835.75 \pm$$
$$Stor = 9.7 \text{ a-f or } 2.7''$$

$$Q_{P_2} = 94 \left(1 - \frac{2.7}{9.5}\right) = 67 \text{ cfs} \quad E_2 = 835.6 \pm$$
$$Stor_2 = 7.7 \text{ a-f or } 2.15'' \quad Stor_{ave} = 2.42''$$

$$Q_{P_3} = 94 \left(1 - \frac{2.42}{9.5}\right) = 70 \text{ cfs outflow}$$
$$E_3 = 835.65 \pm, \quad Stor_3 = 8.4 \text{ a-f}$$


Tailwater

Does not exist at main dam as there is no spillway. Spillway is at dike area. Capacity of 24" CIP at spillway is about 25 \pm cfs. Overland flow here is 45 cfs, depth could be 0.25' \pm near spillway and less as flow disperses over road & wooded areas.


JOB NO. 78,244.1
 DATE 4-18-79
 BY MA
 CH'D BY FDD 7/23/79

HH & B HAYDEN, HARDING & BUCHANAN, INC.
 CONSULTING ENGINEERS
 BOSTON, MASSACHUSETTS


SHEET NO. 6
 JOB JAMS
 SUBJECT Overlook
 CLIENT Corps



DAM ELEVATION



SECTION A (40 scale)




Spillway At Dike

JOB NO. 78,244.1
DATE 9-27-79
BY MA
CHK'D BY FDD



HAYDEN, HARDING & BUCHANAN, INC.
CONSULTING ENGINEERS
BOSTON, MASSACHUSETTS

SHEET NO. 7
JOB Dams
SUBJECT Overlook
CLIENT CEPS




JOB NO. 78,214,1
DATE 4/23/79
BY MA
CH'D BY FDD



HAYDEN, HARDING & BUCHANAN, INC.
CONSULTING ENGINEERS
BOSTON, MASSACHUSETTS

SHEET NO. 9
JOB Dams
SUBJECT Overlook
CLIENT Corps




See Dike Failure Outflow
on page D-18!

JOB NO. 78.244.1
 DATE 4-19-79
 BY MA
 CH'D BY FDD

HH & B HAYDEN, HARDING & BUCHANAN, INC.
 CONSULTING ENGINEERS
 BOSTON, MASSACHUSETTS

SHEET NO. 9
 JOB Dams
 SUBJECT OVERLOOK
 CLIENT Corps



JOB NO. 78,244,1
 DATE 4-5-79
 BY MA
 CH'D BY FDD 4/23/79



HAYDEN, HARDING & BUCHANAN, INC.
 CONSULTING ENGINEERS
 BOSTON MASSACHUSETTS

SHEET NO. 10

JOB Dams
 SUBJECT Overlook
 CLIENT Corps


Sta 5+00

$$V = \frac{1.486}{n} R^{2/3} S^{1/2} = R^{2/3} (5.6)$$

$$n = 0.16$$

$$S = \frac{50}{350} = 0.14286''$$

$\frac{D}{ft.}$	WP	A	$R^{2/3}$	F'	V	Q
5'	52	113	1.68	5.6	9.4	1,064.
10'	94	400	2.602	5.6	14.6	5,828.
15'	170	1050	3.39	"	19.	19,915.
20'	222	1925	4.25	"	23.8	45,828.



$$Q_{P1} = 45,900 \text{ cfs} \cdot D = 20' \cdot V_1 = \frac{4320 + 1925}{2} \left(\frac{500}{43560} \right) = 35.8$$

$$S = 270 \text{ a-f} \quad \frac{1}{2}(S) = 135 \text{ a-f}$$

$$Q_{P2} = 45,900 \cdot \left(1 - \frac{35.8}{270} \right) = 39,814 \text{ cfs} \quad d = 18'$$

$$V_2 = \frac{4320 + 1575}{2} (0.115) = 33.9 \text{ a-f}; \quad V_a = 34.9 \text{ a-f}$$

$$Q_{P3} = 45,900 \left(1 - \frac{34.9}{270} \right) = 39,978 \text{ cfs}$$

EI 778

JOB NO. 78,244_{el}
 DATE 4-5-76
 BY MA
 CH'D BY FDD



HAYDEN, HARDING & BUCHANAN, INC.
 CONSULTING ENGINEERS
 BOSTON, MASSACHUSETTS

SHEET NO. 11
 JOB Dams
 SUBJECT Clear Lake
 CLIENT CEP

Sta 10+00


$n = 0.110$

$S = \frac{100}{500} = 0.2\%$

$V = \frac{1.486}{11} R^{2/3} (.2)^{1/2} = R^{2/3} 6.65$

D WP A R^{2/3} F' V Q

10	267	925	2.3	6.65	15.3	14152
12	468	2045	2.69	"	17.85	36527
13	500	2475	2.92	"	19.4	48060



$Q_{P1} = 39,978 \text{ cfs}$

$V_1 = \frac{1925 + 2174}{2} (0.115) = 23.57 \text{ f}$

$Q_{P2} = 39,978 \cdot \left(1 - \frac{23.57}{270}\right) = 36,442 \text{ cfs } 11.9$

$V_2 = \frac{1925 + 2062}{2} (0.115) = 22.93, V_a = 23.25$

$Q_{P3} = 39,978 \cdot \left(1 - \frac{23.25}{270}\right) = 36,535 \text{ cfs}$

$EI = 662$

JOB NO. 78.244.1
 DATE 4-5-76
 BY MA
 CHD BY FDD


HH & B HAYDEN, HARDING & BUCHANAN, INC.
 CONSULTING ENGINEERS
 BOSTON MASSACHUSETTS

SHEET NO. 12
 JOB Dams
 SUBJECT Overlook
 CLIENT Corps

Sta 15+00

$n = 0.10 \quad S = \frac{60}{500} = .12 \%$ $V = \frac{1.486}{11} (R^{2/3}) (.12)^{5/3} = 5.15 \cdot R^{2/3}$

<u>D</u>	<u>WP</u>	<u>A</u>	<u>R^{2/3}</u>	<u>F'</u>	<u>V</u>	<u>Q</u>
10	131	650	2.92	5.15	15.00	9790
15	163	1350	4.12	"	21.23	28662
12.5	147	975	3.55	"	18.29	17838
17	200	1640	4.17	"	21.52	36365



$Q_{P1} = 36,535$

$V_1 = \frac{2120 + 1650}{2} (.0115) = 21.67 \text{ f}$

$Q_{P2} = 36,535 \cdot \left(1 - \frac{21.67}{270}\right) = 33,600 \text{ cfs}$

$V_2 = \frac{2120 + 1650}{2} (.0115) = 20.99 \text{ f} \quad V_a = 21.33$

$Q_{P3} = 36,535 \cdot \left(1 - \frac{21.33}{270}\right) = 33,650 \text{ cfs}$

$E1 = 606 \pm$

JOB NO. 78,244.1
 DATE 4-5-79
 BY MA
 CH'D BY FDD



HAYDEN, HARDING & BUCHANAN, INC.
 CONSULTING ENGINEERS
 BOSTON, MASSACHUSETTS


SHEET NO. 13
 JOB Dams
 SUBJECT Overlook
 CLIENT Corps

Sta 20+00

$$n = 0.10 \quad s = \frac{40}{500} = 0.08' \quad V = \frac{1.486}{.1} R^{2/3} (.08)^{5/3} = R^{2/3} 4.203$$

D WP A R^{2/3} F' V Q

10	237	825	2.31	4.203	9.69	7,998;
12.5	255	1938	3.89	"	16.35	31,700;
15	283	2125	3.86	"	16.22	34,479;



$$Q_{P1} = 33,650 \text{ cfs}$$

$$V_1 = \frac{1590 + 2032}{2} (.0115) = 20.83$$

$$Q_{P2} = 33650 \left(1 - \frac{20.83}{270}\right) = 31050$$

$$V_2 = \frac{1590 + 1750}{2} (.0115) = 19. \quad V_a = 19.92$$

$$Q_{P3} = 33650 \cdot \left(1 - \frac{19.92}{270}\right) = 31170 \text{ cfs}$$

$$EI = 562. \pm$$

JOB NO. 78,744.1
 DATE 4-5-79
 BY MA
 CH'D BY FDD



HAYDEN, HARDING & BUCHANAN, INC.
 CONSULTING ENGINEERS
 BOSTON, MASSACHUSETTS

SHEET NO. 14

JOB Dams
 SUBJECT Overlook
 CLIENT Cops


Sta 24+00

$n = 0.10 \quad S = \frac{40}{400} = 0.10 \text{ "}. \quad V = \frac{1.486}{.11} R^{2/3} (.11)^{5/2} = R^{2/3} 4.7$

D WP A R^{2/3} F' V Q

5	250	1000	2.53	4.7	11.9	11,900.
7.5	300	1675	3.17	"	14.9	24,919.
2.5	200	450	1.72	"	8.09	3,641.
9	330	2148	3.5	"	16.48	35,410.

270
315



$Q_{P1} = 31,170. \quad V_1 = \frac{1875 + 1927}{2} (.009) = 17.46 \text{ a-f}$

$Q_{P2} = 31,170 \left(1 - \frac{16.55}{270}\right) = 29,150.$

$V_2 = \frac{1875 + 1864}{2} (.009) = 16.83 \text{ a-f} \quad V_a = 17.15$

$Q_{P3} = 31,170 \left(1 - \frac{17.15}{270}\right) = 29,190. \quad EI = 518 \pm$

JOB NO. 78.244.1
 DATE 4-5-79
 BY MA
 CH'D BY FDD



HAYDEN, HARDING & BUCHANAN, INC.
 CONSULTING ENGINEERS
 BOSTON, MASSACHUSETTS


SHEET NO. 15
 JOB Dams
 SUBJECT Overlook
 CLIENT Corps

Sta 27+00

$$n = 0.075 \quad S = \frac{32}{300} = 0.107' \quad V = \frac{1,486}{.075} R^{2/3} (.107)^{1/5} = R^{2/3} 6.48$$

<u>D</u>	<u>WP</u>	<u>A</u>	<u>R^{2/3}</u>	<u>F'</u>	<u>V</u> f/s	<u>Q</u> cfs
2	300'	200	0.76	6.48	5	1000
5	455	920	1.6	"	10.4	9555
10	595	2770	2.8	"	18.16	50,300
7'	545	1600	2.06	"	13.3	21,333

390



$$Q_{P1} = 29,190 \text{ cfs} \quad V_1 = \frac{1896 + 1893}{2} (.0069) = 13 \text{ c.f.}$$

$$Q_{P2} = 29190 \left(1 - \frac{13}{270}\right) = 27,780$$

$$V_2 = \frac{1896 + 1854}{2} (.0069) = 12.9 \quad V_a = 12.95$$

$$Q_{P3} = 29190 \left(1 - \frac{12.95}{270}\right) = 28475 \text{ cfs} \quad EI = 436$$

JOB NO. 78.244.1
DATE 4-3-79
BY MA
CH'D BY FDD




HAYDEN, HARDING & BUCHANAN, INC.
CONSULTING ENGINEERS
BOSTON, MASSACHUSETTS

SHEET NO. 16

JOB Dams
SUBJECT Overlook
CLIENT Corps

Dam



JOB NO. 78,244.1
DATE 9-3-79
BY MA
CH'D BY FDD




HAYDEN, HARDING & BUCHANAN, INC.
CONSULTING ENGINEERS
BOSTON, MASSACHUSETTS

SHEET NO. 17


JOB Dams
SUBJECT Overlook
CLIENT Corps

Dam


Sta 20+00
elev 550



Sta 24+00
elev 510



Sta 27+00
elev 478



NO. 78,244.1
 DATE 6-25-79
 BY MA
 CH'D BY FOO 7/12/79



HAYDEN, HARDING & BUCHANAN, INC.
 CONSULTING ENGINEERS
 BOSTON, MASSACHUSETTS

SHEET NO. 18
 JOB Dams
 SUBJECT Overlook-DIK
 CLIENT Corps

Dike Impact Area : High Hazard

Max Height = 25 ft. ±
 Length of Max Height Section = 340' ft ±

Failure Outflow Highest dike section 25' ±, length about 340' ±, soils at base appear wet, d.s. slope 1 on 1 ± (steep), assume Test Flood Elev 835.5' ± for water surface at failure, minor spillway discharge, assume breach width 340' for analysis. Does not appear to have core wall. Many trees on slope & base area.

$$Q_B = 8/27 \cdot (0.4 \times 340) \sqrt{32.2 \cdot (20)^{3/2}} = 20,500 \frac{ft^3}{s}$$

Failure assumed to occur near section of dike at junction of access road and Flat Rock Road / Prospect Str.

<u>Sta</u>	<u>Flow</u>	<u>Flood Stage</u>	<u>Flood Elev</u>	<u>Damage</u>
0+00	20,500.	20' ±	835.5	water depth = () Breach in Dike
2+00	18,300.	5'	815.	Prospect Str (15')
3+50	17,655.	6'	806.	2 Homes (2')
5+00	16,860.	4' +	784.	
7+50	15,768.	4' +	754.	
12+00	14,132.	11'	732.	
20+00	11,640.	8'	703	1 House (2' ±)
25+	9,930.	14'	704.	Hospital Rd (14')
30+	8,800.	14'	664	
35+	8,260.	16'	631.	
40+	7,400.	8'	618.	
45+	6,890 ±	8'	571.	2 Homes (2' ±)
47+		culvert at roadway		Mechanic Str Urban Development of Fitchburg - Much damage - expected.


JOB NO. 78244
 DATE 6-26-79
 BY W 4
 CH'D BY FDD 7/12/79



HAYDEN, HARDING & BUCHANAN, INC.
 CONSULTING ENGINEERS
 BOSTON, MASSACHUSETTS

SHEET NO. 19

JOB Dams
 SUBJECT Overlook
 CLIENT CCF



JOB NO. 78244
 DATE 6-25-79
 BY MA
 CH'D BY FDD 7/12/79



HAYDEN, HARDING & BUCHANAN, INC.
 CONSULTING ENGINEERS
 BOSTON, MASSACHUSETTS


SHEET NO. 20
 JOB Dams
 SUBJECT Outlook
 CLIENT C&E

Std 2450

$n = 0.10$
 $S^{1/2} = 0.224$

$V = \frac{1.486}{0.1} R^{2/3} (1.224) = R^{2/3} 3.33$

<u>D</u>	<u>WP</u>	<u>A</u>	<u>R^{2/3}</u>	<u>F'</u>	<u>V</u>	<u>Q</u>
2.5						
5	550	2000	2.3	3.33	7.9	15,816
7.5	650	4226	3.5	"	11.7	49,300



$Q_2 = 20,500$
 $30,000$

$Q_{P1} = 20,500 \text{ cfs}$
 $S = 132$
 $S^{1/2} = 66 \text{ ft}$
 $V_1 = \frac{2250 + 2710}{2} \left(\frac{250}{43560} \right) = 14 \text{ ft}$

$Q_{P2} = 20500 \left(1 - \frac{14}{132} \right) = 18,326$

$E_{12} = 5.25 \cdot S_{top2} = \frac{2125 + 2710}{2} () = 14$

$Q_{P3} = 18,300 \text{ cfs}$

Elav 815.

10/8.9

JOB NO. 78244
 DATE 6-25-79
 BY MA
 CH'D BY FDD 7/12/79


HH & B HAYDEN, HARDING & BUCHANAN, INC.
 CONSULTING ENGINEERS
 BOSTON, MASSACHUSETTS

SHEET NO. 21
 JOB Demo
 SUBJECT Overlook
 CLIENT COE

Sta 3+50

$$S = \frac{112}{100} (10/150)^{112} = .26 \quad V = \frac{1.486}{1.1} R^{2/3} (.26) = R^{2/3} 3.86$$

<u>D</u>	<u>VP</u>	<u>A</u>	<u>R^{2/3}</u>	<u>F'</u>	<u>V</u>	<u>Q</u>
5	475	1625	2.28	3.86	8.8	14,300.
6.5	560	2375	2.63	"	10.16	24,119.



$$Q_{P1} = 18300 \cdot V_1 = \frac{1925 + 2125}{2} \cdot (100) = 4.6$$

$$Q_{P2} = 18300 \left(1 - \frac{4.6}{132}\right) = 17,655$$

$$E1 = 5.5 \cdot V_2 = \frac{1875 + 2125}{2} () = 4.6$$

$$Q_{P3} = 17,655$$

Elw 806.

8.9 / 8.6

JOB NO. 78244
 DATE 6-26-79
 BY MA
 CH'D BY FDD 7/12/79



HAYDEN, HARDING & BUCHANAN, INC.
 CONSULTING ENGINEERS
 BOSTON, MASSACHUSETTS


SHEET NO. 27
 JOB Dams
 SUBJECT Overl
 CLIENT COE

5+00

$n = 0.10$
 $S^{1/2} = (20 / 150)^{1/2} = 0.365$
 $V = \frac{4.86}{.1} R^{2/3} S^{1/2} = 5.43 \cdot R^{2/3}$

D WP A R^{2/3} F' V Q

4	520	1460	2	5.43	10.8	15800.
5	600	2000	2.24	"	12.16	24300.



$Q_{P_1} = 17,655 \text{ cfs}$ $E_1 = 784.25$
 $V_1 = \frac{1585 + 1875}{2} \cdot \left(\frac{150}{43560} \right) = 6.4 \text{ - } f < 66 \text{ OK}$

$Q_{P_2} = 17655 \cdot \left(1 - \frac{6}{132} \right) = 16,858 \text{ cfs}$
 $E_2 = 784.13$ $V_2 = \frac{1525 + 1875}{2} () = 5.85$

$Q_{P_3} = 17655 \cdot \left(1 - \frac{5.93}{132} \right) = 16,863$

Over. 784.

8.6/8.2

JOB NO. 79244
 DATE 6-26-79
 BY MA
 CH'D BY FDD 7/12/79


HH & B HAYDEN, HARDING & BUCHANAN, INC.
 CONSULTING ENGINEERS
 BOSTON, MASSACHUSETTS

SHEET NO. 23
 JOB Dams
 SUBJECT Overlook
 CLIENT CE&E

Sta 7+50

$n = 0.10$
 $S^{1/2} = (30 / 250)^{1/2} = 0.346$
 $V = \frac{1.486}{11} R^{2/3} S^{1/2} = R^{2/3} 5.14$

D	WP	A	$R^{2/3}$	F	V	Q
4	450	1200	1.9	5.14	9.9	11,900.
5	500	1750	2.3	"	11.9	20,822.



$Q_{P1} = 16,860 \text{ cfs}$ $E_1 = 754.5$

$V_1 = \frac{1463 + 1550}{2} \left(\frac{250}{43560} \right) = 8.6$

$Q_{P2} = 16,860 \cdot \left(1 - \frac{8.6}{132} \right) = 15,756$

$E_2 = 754.4$ $V_2 = \frac{1420 + 1550}{2} () = 8.5$

$Q_{P3} = 16,860 \cdot \left(1 - \frac{8.55}{132} \right) = 15,768$

Elev 754±

8.2/7.7

JOB NO. 78244
 DATE 6-26-79
 BY MM
 CH'D BY FDD 7/12/79



HAYDEN, HARDING & BUCHANAN, INC.
 CONSULTING ENGINEERS
 BOSTON, MASSACHUSETTS

SHEET NO. 26
 JOB Dams
 SUBJECT overl
 CLIENT CVE

St 12+00


$$n = 0.10$$

$$S^{1/2} = (30 / 450)^{1/2} = 0.2582$$

$$V = \frac{1.486}{.1} (S)^{1/2} R^{2/3} = R^{2/3} 3.84$$

D WP A R^{2/3} F' V Q

5	105					
7.5	150	565	2.4	3.84	9.21	5203 ±
10	200	1000	2.94	"	11.3	11300 ±
12.5	235	1550	3.54	"	13.6	21,065 ±
11	20	1205	3.22	"	12.4	15,000 ±



$$Q_{P1} = 15,768 \cdot cfs \quad E1 = 11.25'$$

$$V_1 = \frac{1263 + 1440}{2} \left(\frac{450}{43560} \right) = 14'$$

$$Q_{P2} = 15,768 \cdot \left(1 - \frac{14}{132} \right) = 14,100 \pm \quad E2 = 10.75'$$

$$V_2 = \frac{1150 + 1440}{2} \left(\frac{450}{43560} \right) = 13.4'$$

$$Q_{P3} = 15,768 \cdot \left(1 - \frac{13.7}{132} \right) = 14,132 \cdot cfs$$

$$E1 = 732'$$

7.7 / 6.9

JOB NO. 79244
 DATE 6-26-79
 BY VWA
 CH'D BY FDD 7/12/79



HAYDEN, HARDING & BUCHANAN, INC.
 CONSULTING ENGINEERS
 BOSTON, MASSACHUSETTS

SHEET NO. 25
 JOB Dams
 SUBJECT Overik
 CLIENT COE

Sta 20+00


$n = 0.10$

$S^{1/2} = (35 / 800)^{1/2} = 0.21$

$V = \frac{1.486}{11} R^{2/3} S^{1/2} = R^{2/3} 3.12$

D W A R^{2/3} F V Q

5	200	550	1.97	3.12	6.14	3380
10	250	1675	3.58	"	11.15	18691
7.5	225	1075	2.85	"	8.9	9564



$Q_{P1} = 14130$ $E1_1 = 8.75$

$V_1 = \frac{1375 + 1210}{2} \left(\frac{800}{43560} \right) = 23.74$

$Q_{P2} = 14132 \left(1 - \frac{23.74}{132} \right) = 11590$

$E1_2 = 8$ $V_2 = \frac{1275 + 1210}{2} = 22.8$

$Q_{P3} = 14132 \left(1 - \frac{23.3}{132} \right) = 11640$

$Elev = 703$

6.9 / 5.8

JOB NO. 78244
 DATE 6-26-79
 BY WZ
 CH'D BY FDD 7/12/79



HAYDEN, HARDING & BUCHANAN, INC.
 CONSULTING ENGINEERS
 BOSTON, MASSACHUSETTS

SHEET NO. 20
 JOB Dam
 SUBJECT QUICK
 CLIENT COE

St 25+00


$M = 0.1$
 $S^{1/2} = (5 / 500)^{1/2} = 0.10$

$V = \frac{1.486}{11} R^{2/3} S^{1/2} = R^{2/3} 1.486$

D W P A R^{2/3} F' V Q

10 215 1000 2.8 · 1.486 · 4.16 · 4,162.

15 350 2350 3.58 · " · 5.32 · 12508.



$Q_{P1} = 11,640$; $E_{l1} = 14.5$; $V_1 = \frac{2175 + 1325}{2} \left(\frac{500}{43560} \right) = 20$

$Q_{P2} = 11,640 \left(1 - \frac{20}{132} \right) = 9,876$

$E_{l2} = 13.5$; $V_2 = \frac{1945 + 1325}{2} (.0115) = 18.8$

$Q_{P3} = 11,640 \left(1 - \frac{19.4}{132} \right) = 9,929$

Elev = 703.5 say 704

5.8/5

JOB NO. 78244
 DATE 6-19-79
 BY MA
 CH'D BY FDD 7/12/79



HAYDEN, HARDING & BUCHANAN, INC.
 CONSULTING ENGINEERS
 BOSTON, MASSACHUSETTS

SHEET NO. 27
 JOB Dams
 SUBJECT QUAIK
 CLIENT COE

Sta 30+00

$Q_{P1} = 9930 \text{ cfs}$


$n = 0.10$

$S^{1/2} = (60 / 500)^{1/2} = 0.3464$

$V = \frac{1.486}{0.1} R^{2/3} S^{1/2} = 5.15$

D W A R^{2/3} F' V Q

10	55	250		5.15		
12.5	80	413	3	5.15	15.45	6383
15	110	613	3.16	"	16.28	9980



$Q_{P1} = 9930 \quad E_{l1} = 15'$

$V_1 = \frac{613 + 2060}{2} \left(\frac{500}{43560} \right) = 15.34$

$Q_{P2} = 9930 \left(1 - \frac{15.34}{132} \right) = 8776 \quad E_{l2} = 14'$

$V_2 = \frac{533 + 2060}{2} () = 14.88 \quad V_{ave} = 15.11$

$Q_{P3} = 9930 \left(1 - \frac{15.11}{132} \right) = 8793$

$E_{lew} = 14.0 + 650 \approx 664$

JOB NO. 78244
 DATE 6-26-79
 BY MA
 CH'D BY FDD 7/12/79


HH & B HAYDEN, HARDING & BUCHANAN, INC.
 CONSULTING ENGINEERS
 BOSTON, MASSACHUSETTS

SHEET NO. 29
 JOB Dam
 SUBJECT overk
 CLIENT COE

Sta 35+00

$n = 0.10$
 $S^{1/2} = (15 / 500)^{1/2} = 0.1732$
 $V = \frac{1.486}{0.1} R^{4/3} S^{1/2} = R^{2/3} 2.574$

D	W	A	R ^{2/3}	F'	V	Q
16	115	860	3.84		9.9	8522
15	105	750	3.73	2.574	9.61	7207
10	75	350	2.81	"	7.23	2529



$Q_{P1} = 8800 \text{ cfs}$ $E_{11} = 15.6$ $V_1 = \frac{820 + 573}{2} (0.0115)$
 $V_1 = 8.0$

$Q_{P2} = 8800 \left(1 - \frac{8.0}{132}\right) = 8267$ $E_{12} = 15.75$

$V_2 = \frac{830 + 573}{2} (0.0115) = 8.07$ $V_{ave} = 8.04$

$Q_{P3} = 8800 \left(1 - \frac{8.04}{132}\right) = 8264$

4.4 / 4.2 $E_{1CV} = 631 \pm$

JOB NO. 79244
 DATE 6-26-79
 BY MA
 CH'D BY FDD 7/12/79

HH & B HAYDEN, HARDING & BUCHANAN, INC.
 CONSULTING ENGINEERS
 BOSTON, MASSACHUSETTS


SHEET NO. 29
 JOB Dams
 SUBJECT Overl
 CLIENT CF

Std 40+00

$n = 0.10$
 $S^{1/2} = (5 / 500)^{1/2} = 0.1$
 $V = \frac{1.486}{0.1} R^{2/3} S^{1/2} = R^{2/3} 1.486$

D W A R^{2/3} F' V Q

5	285	750	2.38	1.486	3.54	2658
10	325	2000	3.38	"	5.02	10,040



$Q_{P1} = 8260$ $E_{L1} = 8.75$ $V_1 = \frac{1698 + 825}{2} (0.0115) = 14.4$

$Q_{P2} = 8260 \left(1 - \frac{4.4}{13.2}\right) = 7359$ $E_{L2} = 8$

$V_2 = \frac{1500 + 825}{2} (0.0115) = 13.4$ $V_{ave} = 13.9$

$Q_{P3} = 8260 \left(1 - \frac{13.9}{13.2}\right) = 7390$ cfs

$E_{Lw} = 6.18$

4.2/3.7

7.134.18

10-5-79

MA

FDD



HAYDEN, HARDING & BUCHANAN, INC.
CONSULTING ENGINEERS
BOSTON, MASSACHUSETTS

SHEET NO. 30

JOB Dams

SUBJECT Overlook - Pike

CLIENT Fitchburg


Sta 45+00

$Q_{P1} = 7,390 \text{ cfs}$

$n = 0.10$ $S = \frac{610 - 565}{500} = 0.09 \text{ F/F}$

$V = \frac{1.486}{0.1} R^{.67} (0.09)^{.148} = 4.458 R^{.213}$

<u>D</u>	<u>V</u>	<u>A</u>	<u>R^{.213}</u>	<u>4.46</u>	<u>V</u>	<u>Q</u>
5	225	525	1.76	"	7.9	4,130 cfs
7	260	995	2.46	"	"	10,906



$Q_{P1} = 7,390 \text{ cfs}$ $E1_1 = 6'$ $V_1 = \frac{760 + 825}{2} (.0115) = 9.1 \text{ af}$

$Q_{P2} = 7,390 \left(1 - \frac{9.1}{132}\right) = 6,880 \text{ cfs}$

$E1_2 = 5.8'$ $V_2 = \frac{713 + 825}{2} = 8.85$ $V_{ave} = 9 \text{ af}$

$Q_{P3} = 7,390 \left(1 - \frac{9}{132}\right) = 6,888 \text{ cfs}$

$D_3 = 5.8$ $Elev_3 = 565 + 5.8 = 571 \text{ ft}$

JOB NO. 79.134.18
 DATE 10-5-79
 BY MA
 CH'D BY FDD



HAYDEN, HARDING & BUCHANAN, INC.
 CONSULTING ENGINEERS
 BOSTON, MASSACHUSETTS


SHEET NO. 31

JOB OVERLOOK - DIKE
 SUBJECT Fitcraving
 CLIENT Fitcraving

Std 70+00 $f = \frac{25}{500} = 0.05''$ $Q_1 = 6888.$

$n = 0.10$ $EI = 540$ $V = \frac{1.486}{11} (R^{2/3}) (.05)^{1/2} = R^{2/3} 3.32$

<u>D</u>	<u>VP</u>	<u>A</u>	<u>R^{2/3}</u>	<u>3.32</u>	<u>V</u>	<u>Q</u>
5	215	690	2.18	"	7.25	5003.
6	410	1100	1.94	"	6.43	7,075.



$Q_1 = 6888.$ $D_1 = 5.9$ $V_1 = \frac{1060 + 730}{2} (.0115) = 10.3$ ^{a-f}

$Q_{P2} = 6888 \cdot (1 - \frac{10.3}{132}) = 6,350. \text{ cfs}$

$D_2 = 5.75$ $V_2 = \frac{980 + 730}{2} (.0115) = 9.8$

$V_a = 10.1 \text{ a-f}$

$Q_{P3} = 6888 \cdot (1 - \frac{10.1}{132}) = 6,363. \text{ cfs}$

$D_3 = 5.75$ $EI = 545.75$

JOB NO. 79.134118
 DATE 10-5-74
 BY MA
 CH'D BY FDD



HAYDEN, HARDING & BUCHANAN, INC.
 CONSULTING ENGINEERS
 BOSTON, MASSACHUSETTS

SHEET NO. 72
 JOB Dams
 SUBJECT Owlsok
 CLIENT Fitchburg


Std 55+00

$Q_{P1} = 6,363 \text{ cfs}$

$n = 0.15 \quad S = \frac{38}{500} = 0.076''$

$V_1 = \frac{1.486}{0.15} R^{2/3} (0.076)^{1/2} = R^{2/3} 2.73$

<u>D</u>	<u>V_P</u>	<u>A</u>	<u>R^{2/3}</u>	<u>2.73</u>	<u>V</u>	<u>Q</u>
8	210	1080	3	"	8.18	8,833.
5	160	570	2.34	"	6.4	3,645.



$Q_{P1} = 6363 \quad D_1 = 6.6 \quad V_1 = \frac{845 + 1020}{2} (0.0115) = 10.7 \text{ c.f.}$

$Q_{P2} = 6363 \left(1 - \frac{10.7}{13.2}\right) = 5,846.$

$D_2 = 6.3' \quad V_2 = \frac{791 + 1020}{2} (0.0115) = 10.4$

$V_{ave} = 10.6$

$Q_{P3} = 6363 \left(1 - \frac{10.6}{13.2}\right) = 5,854. \text{ cfs}$

$D_3 = 6.3' \quad Elev = 508.3'$

JOB NO. 79.134.18
 DATE 10-5-79
 BY MA
 CH'D BY FDD



HAYDEN, HARDING & BUCHANAN, INC.
 CONSULTING ENGINEERS
 BOSTON, MASSACHUSETTS

SHEET NO. 33
 JOB Dams
 SUBJECT Overlook-Dike
 CLIENT Fitchburg


Sta 60+00

$Q_p = 5854$

$n = 0.15 \quad S = \frac{22}{500} = 0.044 \text{ \textit{''}}$

$V = \frac{1.486}{.15} R^{2/3} (.044)^{1/2} = 2.08 R^{2/3}$

<u>D</u>	<u>VP</u>	<u>A</u>	<u>R^{2/3}</u>	<u>2.08</u>	<u>V</u>	<u>Q</u>
5	180	745	2.59	"	5.39	4,013.
6	190	935	2.90	"	6.03	5,640



$Q_p = 5854 \quad D_1 = 6.1' \quad V_1 = \frac{1035 + 825}{2} (.0115) = 10.7$

$Q_{p2} = 5854 \left(1 - \frac{10.7}{132}\right) = 5379$

$D_2 = 5.8' \quad V_2 = \frac{888 + 825}{2} () = 9.85$

$V_{ave} = 10.3 \text{ d-f}$

$Q_{p3} = 5854 \left(1 - \frac{10.3}{132}\right) = 5397$

$D_3 = 5.8' \quad EL_{av} = 485.8$

JOB NO. 79.134.18
 DATE 10-5-79
 BY MA
 CH'D BY FDD



HAYDEN, HARDING & BUCHANAN, INC.
 CONSULTING ENGINEERS
 BOSTON, MASSACHUSETTS

SHEET NO. 34
 JOB DAMS
 SUBJECT Overlook-Dike
 CLIENT Fitchburg


Sta 65+00

$n = 0.15$ $s = \frac{6}{500} = 0.012$ "

$Q_{P1} = 5397 \text{ cfs}$

$V = \frac{1.486}{1.15} (1.213) (0.012)^{1/2} = R^{2/3} 1.08$

<u>D</u>	<u>WP</u>	<u>A</u>	<u>R^{2/3}</u>	<u>1.08</u>	<u>V</u>	<u>Q</u>
6	220	780	2.33	"	2.52	1,967.
8	265	1260	2.84	"	3.07	3,868.
10	335	1860	3.15	"	3.41	6,335.



$Q_{P1} = 5,397$ $D_1 = 9.25$ $V_1 = \frac{1635 + 960}{2} (0.0115) = 15 \text{ f}$

$Q_{P2} = 5397 (1 - \frac{15}{132}) = 4787 \text{ cfs}$

$D_2 = 8.75$ $V_2 = \frac{1485 + 960}{2} (0.0115) = 14 \text{ f}$

$V_a = 14.5 \text{ f}$

$Q_{P3} = 5397 (1 - \frac{14.5}{132}) = 4804$

$D_3 = 8.8$ $\text{Elev} = 483 \pm$

JOB NO. 79.134.18
 DATE 10-5-79
 BY M4
 CH'D BY FDD



HAYDEN, HARDING & BUCHANAN, INC.
 CONSULTING ENGINEERS
 BOSTON, MASSACHUSETTS

SHEET NO. 35
 JOB Dams
 SUBJECT Overlook-Dike
 CLIENT Fitchburg


Stn 70+00

$n = 0.15 \quad s = \frac{4}{500} = 0.008$

$Q_{P1} = 4800 \text{ cfs}$

$V = \frac{1.486}{0.15} R^{2/3} (0.008)^{1/2} = R^{2/3} 0.886$

<u>D</u>	<u>WP</u>	<u>A</u>	<u>R^{2/3}</u>	<u>0.886</u>	<u>V</u>	<u>Q</u>
5	250	625	1.85	"	1.64	1,023
7	340	1225	2.36	"	2.1	2,562
10	500	2455	2.90	"	2.573	6,317
8	380	1585	2.6	"	2.31	3,656



$Q_{P1} = 4800 \text{ cfs} \quad D = 8.8 \quad V_1 = \frac{1933 + 1560}{2} (0.0115) = 20.1 \text{ df}$

$Q_{P2} = 4800 \left(1 - \frac{20.1}{132}\right) = 4070$

$D_2 = 8.3 \quad V_2 = \frac{1716 + 1560}{2} (0.0115) = 18.84$

$V_a = 19.5 \text{ a-f}$

$Q_{P3} = 4800 \left(1 - \frac{19.5}{132}\right) = 4,100$

$D_3 = 8.3 \quad \text{Elev} = 478.3$

JOB NO. 79.134.18
 DATE 10-5-79
 BY MA
 CH'D BY FDD



HAYDEN, HARDING & BUCHANAN, INC.
 CONSULTING ENGINEERS
 BOSTON, MASSACHUSETTS


SHEET NO. 26
 JOB Dams
 SUBJECT Overlook-Dike
 CLIENT Fitchburg

Sta 75+00

$n = 0.25$ $S = \frac{13}{500} = 0.026''$

$V = \frac{1.486}{0.25} (R^{2/3}) (.026)''^{1/2} = 0.96$

D	WP	A	R ^{2/3}	0.96	V	Q
5	600	1320	1.70	"	1.63	2149
6	660	1980	2.09	"	2	3960
7	760	2740	2.36	"	2.27	6211



$Q_{P1} = 4100$; $D_1 = 6.1$; $V_1 = \frac{2820 + 1825}{2} (.0115) = 26.8$

$Q_{P2} = 4100 \left(1 - \frac{26.8}{132}\right) = 3270$

$D_2 = 5.6$; $V_2 = \frac{1716 + 1825}{2} (.0115) = 20.4$

$V_{ave} = 23.6$ a-f

$Q_{P3} = 4100 \left(1 - \frac{23.6}{132}\right) = 3368$

$D = 5.7'$; Elev = 463±

JOB NO. 79.134.18
 DATE 10-5-79
 BY MA
 CH'D BY FDD
 BY -



HAYDEN, HARDING & BUCHANAN, INC.
 CONSULTING ENGINEERS
 BOSTON, MASSACHUSETTS

SHEET NO. 37
 JOB Dams
 SUBJECT Amherst-Dike
 CLIENT Fitchburg


Sta 80+00

$Q_{P1} = 3368.$

$n = 0.25 \quad S = \frac{4}{500} = 0.008''$

$V = \frac{1.486}{.25} R^{2/3} (0.008)^{1/2} = 0.53 R^{2/3}$

<u>D</u>	<u>VP</u>	<u>A</u>	<u>R^{2/3}</u>	<u>0.53</u>	<u>V</u>	<u>Q</u>
3'	800	2130	1.93	"	1.02	2175.
4'	900	3030	2.26	"	1.20	3622.



$Q_{D1} = 3368 \quad D_1 = 3.75'$

$V_1 = \frac{2805 + 2270}{2} (0.0115) = 29.18 \text{ c.f.}$

$Q_{P2} = 3368 \left(1 - \frac{29.18}{132}\right) = 2623.$

$D_2 = 3.3 \quad V_2 = \frac{2400 + 2270}{2} (0.0115) = 26.85$

$V_{ave} = 28 \frac{c.f.}{s}$

$Q_{P3} = 3368 \left(1 - \frac{28}{132}\right) = 2653.$



$D = 3.3 \quad Elw = 457 \pm$

JOB NO. 78244
DATE 6-25-79
BY WFS
CHK'D BY FDD



HAYDEN, HARDING & BUCHANAN, INC.
CONSULTING ENGINEERS
BOSTON, MASSACHUSETTS

SHEET NO. 38
JOB Dennis
SUBJECT QUAIK
CLIENT C&E




JOB NO. 79244
DATE 6-26-79
BY MA
CH'D BY FDD




HAYDEN, HARDING & BUCHANAN, INC.
CONSULTING ENGINEERS
BOSTON, MASSACHUSETTS

SHEET NO. 51
JOB Dams
SUBJECT OWNK
CLIENT COE

Sta 5+00




Sta 7+50




Sta 12+00

elev 720



Sta 20+00




JOB NO. 78244
DATE 6-26-79
BY WV
CH'D BY EDD



HAYDEN, HARDING & BUCHANAN, INC.
CONSULTING ENGINEERS
BOSTON, MASSACHUSETTS

SHEET NO. 40
JOB Dams
SUBJECT Quik
CLIENT COE




JOB NO. 78244
DATE 6-26-79
BY MA
CH'D BY FDD



HAYDEN, HARDING & BUCHANAN, INC.
CONSULTING ENGINEERS
BOSTON, MASSACHUSETTS

SHEET NO. 41
JOB Ddm
SUBJECT OVERLAP
CLIENT COE







JOB NO. 79,134.18
DATE 10-5-79
BY MA
CHK'D BY FDD



HAYDEN, HARDING & BUCHANAN, INC.
CONSULTING ENGINEERS
BOSTON, MASSACHUSETTS

SHEET NO. 42
JOB Dam
SUBJECT Bank
CLIENT COE





JOB NO. 79.134.18
DATE 10-5-79
BY MA
CH'D BY FDD



HAYDEN, HARDING & BUCHANAN, INC.
CONSULTING ENGINEERS
BOSTON, MASSACHUSETTS

SHEET NO. 43
JOB Dams
SUBJECT Quantik
CLIENT COE





HAYDEN, HARDING & BUCHANAN, INC CONSULTING ENGINEERS BOSTON, MASSACHUSETTS	US ARMY ENGINEER DIV NEW ENGLAND CORPS OF ENGINEERS WALTHAM, MASS
NATIONAL PROGRAM OF INSPECTION OF NON-FED DAMS	
<h2 style="text-align: center;">OVERLOOK RESERVOIR DAM & DIKE DRAINAGE AREA & FAILURE IMPACT AREAS</h2>	
FITCHBURG	MASSACHUSETTS
SCALE 1" = 2000' DATE JULY 1980	

APPENDIX E
INFORMATION AS CONTAINED IN THE
NATIONAL INVENTORY OF DAMS

INVENTORY OF DAMS IN THE UNITED STATES

STATE	DIVISION	COUNTY	CONCRETE	CITY	LATITUDE (NORTH)	LONGITUDE (WEST)	REPORT DATE
MA	1535	FED	WA	027	04	OVERLOOK RESERVOIR DIKE	4235.9 7149.0 15AUG80

POPULAR NAME	NAME OF IMPOUNDMENT
OVERLOOK RESERVOIR	OVERLOOK RESERVOIR
REGION	RIVER OR STREAM
01	TR NORTH NASHUA RIVER
01	09
TR	NORTH NASHUA RIVER
	FITCHBURG
	NEAREST DOWNSTREAM CITY-TOWN-VILLAGE
	FITCHBURG
	POPULATION
	38976

TYPE OF DAM	YEAR COMPLETED	PURPOSES	HYDRAULIC HEIGHT (FT.)	IMPOUNDING CAPACITIES	
				MAXIMUM (ACRE-FT.)	NORMAL (ACRE-FT.)
HEPG	1872	S	25	250	187

DIST C A N F E D R P R V F P E D S C S A V E R / D A T E
N E D . N N N N N

REMARKS														

D/S HAS CREST LENGTH	1	900	U	10	1447	VOLUME OF DAM (CY)	UNKNOWN	POWER CAPACITY INSTALLED (HP)	NONE	PROPOSED NO.	NONE	NAVIGATION LOCKS	NONE
OWNER	HAYDEN HARDING & HUCHANAN INC				ENGINEERING BY	LINKDOWN				CONSTRUCTION BY	NONE		
CITY OF FITCHBURG	UNKNOWN				REGULATORY AGENCY	NONE		OPERATION	NONE		MAINTENANCE	NONE	

DESIGN	CONSTRUCTION	OPERATION	INSPECTION DATE	AUTHORITY FOR INSPECTION
NONE	NONE	NONE	17 JUN 80	PL 92-367
REMARKS				
50 EXCLUDING 370 FT MAIN DAM				

END

FILMED

7-85

DTIC