

AD-A155 796


NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS  
SEBEC DAM ME 00163 PE. (U) CORPS OF ENGINEERS WALTHAM  
MA NEW ENGLAND DIV JUN 81


1/1

UNCLASSIFIED

F/G 13/13

NL





MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A

AD-A155 796

PENOBSCOT RIVER BASIN  
SEBEC, MAINE

SEBEC DAM  
ME 00163

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM



DTIC  
SELECTE  
JUN 28 1985  
S D  
JB G

DEPARTMENT OF THE ARMY  
NEW ENGLAND DIVISION, CORPS OF ENGINEERS  
WALTHAM, MASS. 02154

DTIC FILE COPY

JUNE, 1981

RESTRICTION STATEMENT A  
Approved for public release;  
Distribution Unlimited

069

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

| REPORT DOCUMENTATION PAGE   |  | READ INSTRUCTIONS<br>BEFORE COMPLETING FORM                 |  |
|---|--|---|--|
| 1. REPORT NUMBER<br>ME 00163  | 2. GOVT ACCESSION NO.<br><b>A155 796</b> | 3. RECIPIENT'S CATALOG NUMBER                               |  |
| 4. TITLE (and Subtitle)<br>Sebec Dam<br>NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS   |  | 5. TYPE OF REPORT & PERIOD COVERED<br>INSPECTION REPORT     |  |
|   |  | 6. PERFORMING ORG. REPORT NUMBER                            |  |
| 7. AUTHOR(s)<br>U.S. ARMY CORPS OF ENGINEERS<br>NEW ENGLAND DIVISION  |  | 8. CONTRACT OR GRANT NUMBER(s)                              |  |
| 9. PERFORMING ORGANIZATION NAME AND ADDRESS   |  | 10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS |  |
| 11. CONTROLLING OFFICE NAME AND ADDRESS<br>DEPT. OF THE ARMY, CORPS OF ENGINEERS<br>NEW ENGLAND DIVISION, NEDED<br>424 TRAPELO ROAD, WALTHAM, MA. 02254   |  | 12. REPORT DATE<br>June 1981                                |  |
|   |  | 13. NUMBER OF PAGES<br>80                                   |  |
| 14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)   |  | 15. SECURITY CLASS. (of this report)<br><br>UNCLASSIFIED    |  |
|   |  | 15a. DECLASSIFICATION/DOWNGRADING SCHEDULE                  |  |
| 16. DISTRIBUTION STATEMENT (of this Report)<br><br>APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED  |  |   |  |
| 17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)  |  |   |  |
| 18. SUPPLEMENTARY NOTES<br>Cover program reads: Phase I Inspection Report, National Dam Inspection Program; however, the official title of the program is: National Program for Inspection of Non-Federal Dams; use cover date for date of report.  |  |   |  |
| 19. KEY WORDS (Continue on reverse side if necessary and identify by block number)<br>DAMS, INSPECTION, DAM SAFETY,<br>Penobscot River Basin<br>Sebec Maine<br>Sebec River  |  |   |  |
| 20. ABSTRACT (Continue on reverse side if necessary and identify by block number)<br>The dam is about 276 ft. long with a height of 16 ft. The dam is considered to be in fair condition. Continued spalling and erosion of the gate structure concrete could eventually compromise its structural stability. It is large in size with a hazard classification of significant. It is recommended that the owner engage a qualified engineer to further assess the spalled and eroded concrete of the old power station and fishway, |  |   |  |

## **DISCLAIMER NOTICE**

**THIS DOCUMENT IS BEST QUALITY  
PRACTICABLE. THE COPY FURNISHED  
TO DTIC CONTAINED A SIGNIFICANT  
NUMBER OF PAGES WHICH DO NOT  
REPRODUCE LEGIBLY.**



DEPARTMENT OF THE ARMY  
 NEW ENGLAND DIVISION, CORPS OF ENGINEERS  
 424 TRAPELO ROAD  
 WALTHAM, MASSACHUSETTS 02254

AUG 07 1981

REPLY TO  
 ATTENTION OFFICE  
 NEEDED

Honorable Joseph E. Brennan  
 Governor of the State of Maine  
 State Capitol  
 Augusta, Maine 04330

Dear Governor Brennan:

Inclosed is a copy of the Sebec Dam (ME-00163) Phase I Inspection Report, prepared under the National Program for Inspection of Non-Federal Dams. This report is based upon a visual inspection, a review of the past performance and a brief hydrological study of the dam. I approve the report and support the findings and recommendations described in Section 7 and ask that you keep me informed of the actions taken to implement them. This follow-up action is vitally important.

Copies of this report have been forwarded to the Department of Agriculture and to the owner, Bangor Hydro-Electric Company, Bangor, Maine. Copies will be available to the public in thirty days.

I wish to thank you and the Department of Agriculture for your cooperation in in this program.

Sincerely,

C. E. EDGAR, III  
 Colonel, Corps of Engineers  
 Commander and Division Engineer

Incl  
 As stated



|               |                                     |
|---------------|-------------------------------------|
| Accession For |                                     |
| NTIS GRA&I    | <input checked="" type="checkbox"/> |
| DTIC TAB      | <input type="checkbox"/>            |
| Unannounced   | <input type="checkbox"/>            |
| Justification |                                     |
| By            |                                     |
| Distribution  |                                     |
| Availability  |                                     |
| Part          |                                     |
| A1            | 23                                  |

*Waco*

PENOBSCOT RIVER BASIN

SEBEC DAM

ME 00163

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

DEPARTMENT OF THE ARMY  
NEW ENGLAND DIVISION, CORPS OF ENGINEERS  
WALTHAM, MASSACHUSETTS 02154

FEBRUARY, 1981

LETTER OF TRANSMITTAL  
FROM THE CORPS OF ENGINEERS TO THE STATE  
TO BE SUPPLIED BY THE CORPS OF ENGINEERS



BRIEF ASSESSMENT  
PHASE I INSPECTION REPORT  
NATIONAL PROGRAM OF INSPECTION OF DAMS

Identification Number: ME00163  
Name of Dam: SEBEC DAM  
Town: SEBEC  
County and State: PISCATAQUIS COUNTY, MAINE  
Stream: SEBEC RIVER  
Date of Inspection: NOVEMBER, 1980


The dam, constructed prior to 1882, is a rock-filled timber crib structure, capped and liberally reinforced with concrete, approximately 276 feet long and 16 feet in height. The structure includes a 20-foot long abutment section on the left, a 178-foot spillway section, a 20-foot fish passage to the right of the spillway, and a 58-foot structure which forms the right abutment and contains two outlet sluice gates. The spillway is divided into two sections, 58 feet being 1 foot higher than the remaining 120 feet. Upstream and downstream faces of the dam are vertical. The two manually operated sluice gates are 11 feet wide by 10 feet high and are reported operable.

The dam impounds Sebec Lake and is on the Sebec River approximately 9.2 miles upstream of its confluence with the Piscataquis River. It is used for water storage and flow regulation for downriver hydro-electric facilities, and seasonally for maintenance of lake level. The lake is about 11.5 miles long with a surface area of approximately 6,800 acres. Storage capacity to the top of the dam is estimated at 150,000 acre-feet.


Based upon the visual inspection and the review of available data regarding this facility, the dam is considered to be in Fair condition. Continued spalling and erosion of the gate structure concrete could eventually compromise its structural stability.

In accordance with the Corps of Engineers Guidelines and the size (LARGE) and hazard (SIGNIFICANT) classification of the dam, the Test Flood selected was equivalent to the Probable Maximum Flood (PMF). Peak inflow to the reservoir is 85,000 cfs; routed peak outflow from the dam is 43,000 cfs with the water elevation 26.5 feet above the dam crest. The spillway capacity is 9,400 cfs, (13,300 cfs w/o flashboards) which is equivalent to approximately 22% (31% w/o flashboards) of the routed Test Flood outflow from the dam. Hydraulic computations indicate that outflow in excess of approximately 15,000 cfs will be controlled by downstream channel characteristics rather than the dam, thus spillway capacity, with flashboards in place, is about 63% of the maximum outflow controlled by the dam. Without flashboards, the spillway capacity is 89% of the maximum outflow.


It is recommended that the owner engage a qualified, registered engineer to further assess the spalled and eroded concrete of the old power station and fishway (gate structure) and submit recommendations for repair and rehabilitation. This and the remedial measures which are discussed in Section 7 should be instituted within one year of the owner's receipt of this report.



Stephen D. Murray, P.E.  
Project Manager  
James W. Sewall Company



This Phase I Inspection Report on Sebec Dam (ME-00163) has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the Recommended Guidelines for Safety Inspection of Dams, and with good engineering judgement and practice, and is hereby submitted for approval.



CARNEY M. TERZIAN, MEMBER  
Design Branch  
Engineering Division




JOSEPH W. FINEGAN, JR., MEMBER  
Water Control Branch  
Engineering Division



ARAMAST MAHTESIAN, CHAIRMAN  
Geotechnical Engineering Branch  
Engineering Division

APPROVAL RECOMMENDED:



JOE B. FRYAR  
Chief, Engineering Division

## PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

The Phase I Investigation does not include an assessment of the need for fences, gates, no-trespassing signs, repairs to existing fences and railings and other items which may be needed to minimize trespass and provide greater security for the facility and safety to the public. An evaluation of the project for compliance with OSHA rules and regulations is also excluded.

## TABLE OF CONTENTS

| <u>SECTION</u>                          | <u>PAGE</u> |
|---|-------------|
| Letter of Transmittal                   |             |
| Brief Assessment                        |             |
| Review Board Page                       |             |
| Preface                                 | i           |
| Table of Contents                       | ii-iv       |
| Overview Photo                          | v           |
| Location Map                            | vi          |
| <br><u>REPORT</u><br>                   |             |
| 1. PROJECT INFORMATION                  | 1-1         |
| 1.1 General                             | 1-1         |
| a. Authority                            | 1-1         |
| b. Purpose of Inspection Program        | 1-1         |
| 1.2 Description of Project              | 1-1         |
| a. Location                             | 1-1         |
| b. Description of Dam and Appurtenances | 1-1         |
| c. Size Classification                  | 1-2         |
| d. Hazard Classification                | 1-2         |
| e. Ownership                            | 1-2         |
| f. Operator                             | 1-2         |
| g. Purpose of Dam                       | 1-3         |
| h. Design and Construction History      | 1-3         |
| i. Normal Operational Procedures        | 1-3         |
| 1.3 Pertinent Data                      | 1-3         |
| a. Drainage Area                        | 1-3         |
| b. Discharge at Dam Site                | 1-3         |
| c. Elevation                            | 1-4         |
| d. Reservoir                            | 1-4         |
| e. Storage                              | 1-5         |
| f. Reservoir Surface                    | 1-5         |
| g. Dam                                  | 1-5         |
| h. Diversion and Regulating Tunnel      | 1-5         |
| i. Spillway                             | 1-6         |
| j. Regulating Outlets                   | 1-6         |

| <u>Section</u>                                 | <u>Page</u> |
|--|-------------|
| 1. ENGINEERING DATA                            | 2-1         |
| 2.1 Design                                     | 2-1         |
| a. Available Data                              | 2-1         |
| b. Design Features                             | 2-1         |
| c. Design Data                                 | 2-1         |
| 2.2 Construction                               | 2-1         |
| a. Available Data                              | 2-1         |
| b. Construction Considerations                 | 2-1         |
| 2.3 Operation                                  | 2-1         |
| 2.4 Evaluation                                 | 2-1         |
| a. Availability                                | 2-1         |
| b. Adequacy                                    | 2-1         |
| c. Validity                                    | 2-2         |
| 2. VISUAL INSPECTION                           | 3-1         |
| 3.1 Findings                                   | 3-1         |
| a. General                                     | 3-1         |
| b. Dam   | 3-1         |
| c. Appurtenant Structures                      | 3-1         |
| d. Reservoir Area                              | 3-2         |
| e. Downstream Channel                          | 3-2         |
| 3.2 Evaluation                                 | 3-2         |
| 3. OPERATIONAL AND MAINTENANCE PROCEDURES      | 4-1         |
| 4.1 Operational Procedures                     | 4-1         |
| a. General                                     | 4-1         |
| b. Warning System                              | 4-1         |
| 4.2 Maintenance Procedures                     | 4-1         |
| a. General                                     | 4-1         |
| b. Operating Facilities                        | 4-1         |
| 4.3 Evaluation                                 | 4-1         |
| 4. EVALUATION OF HYDRAULIC/HYDROLOGIC FEATURES | 5-1         |
| 5.1 General                                    | 5-1         |

## SECTION 3 - VISUAL INSPECTION

### 3.1 FINDINGS

a. General - At the time of inspection on November 4, 1980, the water level in Sebec Lake, impounded by the dam, was 7 inches over the lower spillway section, with flashboards installed. The weather was cloudy and cool. The general condition of this dam is fair.

b. Dam - This is basically a timber crib, rock filled dam with concrete renovations and additions. The timbers have been capped with concrete to produce the spillway crest and apron as shown in Photos 1 and 2. As seen in Photo 2, there is a moderate amount of leakage from between some of the timbers of the crib. This was not considered indicative of any structural deficiency. Bedrock is exposed in the area of the right abutment as shown in Photo 3. The left abutment, shown in Photo 4, is concrete enclosed by steel sheet piling. Both the piling and the concrete abutment are in good condition. A stone riprapped slope goes from this abutment for some 30 yards upstream to the stub abutment of a highway bridge. This riprap is in good condition and extends up the slope to 3 feet above the water level on the day of inspection.

On the right side of the dam, as shown in Photo 5, is a concrete intake channel and forebay leading to the substructure of a former power station. The concrete walls of the forebay are in good condition. On the left side of the forebay adjacent to the old power station, as shown in Photo 6, a new fish passage was added in 1978. This has not been completed and there are current plans to complete it. A concrete training wall leads upstream from the right side of the forebay to the other abutment of the highway bridge. This training wall is of recent construction and is in good condition.

### c. Appurtenant Structures

Spillway - The concrete cap forming the spillway crest and apron is in good condition with only a few small cracks and minor erosion. The timbers underneath were inaccessible for inspection.

Outlet Structure - The outlet structure is of reinforced concrete and is the substructure of a power station which burned on August 19, 1940. Two sluice gates were installed in 1960 for the two 10'x11' openings at the downstream end of the forebay, as shown in Photo 7. These gates are lifted and controlled by a trolley type manual chain hoist hung from a steel frame above the gates. The hoist and gates are reported operable. It is reported that there are generally no problems with icing of the gates during the winter. Occasionally it has been necessary to steam the gates free. There are no remaining turbines or other equipment to impede the flow of water under the powerhouse floor. As shown in the left side of Photo 8, the water exits through two 10'x10' openings in the downstream foundation wall of the power station. The concrete of this structure is still essentially sound but many surfaces are badly spalled and eroded as seen in Photo 7 and 8. Where the surface has not yet spalled, there are numerous efflorescent stains as seen in Photo 6.

The detailed engineering data required to perform an in-depth stability analysis of the dam was not available. The final assessment of the dam, therefore, must be based primarily on visual inspection, performance history, and spillway capacity computations.

c. Validity - A comparison of records, data, and visual observations reveals no significant discrepancies, other than those noted above, between design and as-built dimensions.



## SECTION 2: ENGINEERING DATA

### 2.1 DESIGN

a. Available Data - Available data consists of the following plans by the Bangor Hydro-Electric Company, Bangor, Maine:

1. Sebec Dam, General Plan, January 23, 1961, Dwg. M-2061
2. Sebec Dam, General Plan, Nov. 19, 1975, Dwg. M-2061A
3. Sebec Lake Dam, Proposed Concrete Forebay, Aug. 29, 1977, Dwg. 3092
4. Sebec Lake Dam, Proposed Concrete Forebay, Changes to Accommodate Fishway, September 1, 1978, Dwg. 3092A

Also available was the General Plan and Elevation of Sebec Plant for Milo Light and Power Co., Sanders Engineering Co., Portland, Me., Dec. 13, 1920.

b. Design Features - The drawings, computations and inspection reports indicate the design features stated in Section 1.

c. Design Data - Design data consists of information on the drawings listed in "Available Data" and the information shown in Appendix B.

### 2.2 CONSTRUCTION

a. Available Data - Information as contained in any plans, drawings, or specifications previously listed in "Design Data" or Appendix B.

b. Construction Considerations - Since no original plans of the dam were available, there was no practical means to ascertain any construction changes. Post-construction changes are discussed in Section 6.3.

### 2.3 OPERATION

Pond level readings are taken irregularly, but as frequently as needed, to guide the operational procedures described in Section 4.1.

### 2.4 EVALUATION

a. Availability - Existing data was provided by the Bangor Hydro-Electric Co. and the Maine Office of Energy Resources.

b. Adequacy - Detailed hydrologic/hydraulic data were not available. Design data and field measurements were utilized in conjunction with New England Division - Army Corps of Engineers "Preliminary Guidance for Estimating Maximum Probable Discharges" to perform the computations of outflow capacity.

i. Spillway

- |                             |                |
|-----------------------------|----------------|
| 1. Type:                    | overflow       |
| 2. Length of weir:          | 178 ft         |
| 3. Crest el.                |                |
| with flashboards            | 323            |
| without flashboards 120 ft. | 321.2          |
| without flashboards 58 ft.  | 322.2          |
| 4. Gates:                   | N/A            |
| 5. Upstream channel:        | natural stream |
| 6. Downstream channel:      | natural stream |
| 7. General:                 | N/A            |

j. Regulating Outlets

- |                      |  |
|----------------------|--|
| 1. Invert:           | 309  |
| 2. Size:             | two 11 ft.-wide by<br>10-ft. high sluice<br>gates                        |
| 3. Description:      | steel wheeled gates<br>installed over old<br>powerhouse intakes          |
| 4. Control mechanism | gates are operated<br>by trolley-type<br>chain hoist                     |
| 5. Other:            | 4-ft. wide fish<br>passage at right<br>side of dam with<br>wood stoplogs |

e. Storage

- |                         |                 |
|-------------------------|-----------------|
| 1. Normal pool:         | 95,000 acre-ft  |
| 2. Flood control pool:  | N/A             |
| 3. Spillway crest pool: | 82,000 acre-ft  |
| 4. Top of dam:          | 150,000 acre-ft |
| 5. Test flood pool:     | 258,000 acre-ft |

f. Reservoir Surface

- |                        |                   |
|------------------------|-------------------|
| 1. Normal pool:        | 6,800 acres       |
| 2. Flood control pool: | N/A               |
| 3. Spillway crest:     | 6,800 acres $\pm$ |
| 4. Test flood pool:    | 7,400 acres $\pm$ |
| 5. Top of dam:         | 7,000 acres $\pm$ |

g. Dam

- |                     |                  |
|---------------------|------------------|
| 1. Type:            | rock-filled crib |
| 2. Length:          | 276 ft $\pm$     |
| 3. Height:          | 21 ft $\pm$      |
| 4. Top Width:       | 10 ft $\pm$      |
| 5. Side Slopes:     | vertical         |
| 6. Zoning:          | N/A              |
| 7. Impervious Core: | N/A              |
| 8. Cutoff:          | steel sheeting   |
| 9. Grout Curtain:   | N/A              |
| 10. Other:          | N/A              |

h. Diversion and Regulating Tunnel

N/A

|    |   |  |
|----|---|--|
| 6. | Gated spillway capacity at test flood el. 347.5                           | N/A  |
| 7. | Total spillway capacity at test flood el. 347.5                           | 30,400 cfs w/flashboards<br>31,100 cfs w/o flashboards |
| 8. | Total project discharge at top of dam el. 330.4 (controlled by tailwater) | 15,000 cfs   |
| 9. | Total project discharge at test flood el. 347.5 (controlled by tailwater) | 43,000 cfs   |
| c. | <u>Elevation (Feet, NGVD)</u>   |  |
| 1. | Streambed at toe of dam:  | 309 <u>±</u>   |
| 2. | Bottom of cutoff:   | N/A  |
| 3. | Maximum tailwater:  | unknown  |
| 4. | Recreation pool:  | 323  |
| 5. | Full flood control pool:  | N/A  |
| 6. | Spillway crest (Ungated):   |  |
|    | with flashboards  | 323  |
|    | without flashboards - 120 ft.   | 321.2  |
|    | without flashboards - 58 ft.  | 322.2  |
| 7. | Design surcharge (original design):                                       | N/A  |
| 8. | Top of dam:   | 330.4  |
| 9. | Test flood surcharge:   | 347.5  |
| d. | <u>Reservoir</u>  |  |
| 1. | Length of normal pool:  | 11.5 mi  |
| 2. | Length of flood control pool:   | N/A  |
| 3. | Length of spillway crest pool:  | 11.5 mi  |
| 4. | Length of pool at top of dam:   | 11.5 mi  |
| 5. | Length of test flood pool:  | 11.5 mi <u>±</u>                                       |

g. Purpose of Dam - Original purpose was water power, then hydro-electric generation. Currently used for water storage and flow regulation.

h. Design and Construction History - The timber crib rock-filled dam was built prior to 1882 to operate a saw mill. In about 1920, a stone masonry and concrete dam with power station was constructed by Boston Excelsior Company of Milo, Maine, about 100 feet downstream of the timber crib structure. The new dam reportedly failed as it was being filled, and the older timber crib structure was subsequently renovated and used, with the new powerhouse, for power generation. The power station was operated by Boston Excelsior and subsequent owners until it burned on August 19, 1940. The dam was later acquired by Bangor Hydro-Electric Company and has, over approximately the last 20 years, received considerable maintenance attention including concrete capping, steel sheeting and new sluice gates.

i. Normal Operational Procedures - Flow from the dam is controlled as necessary to supplement Piscataquis River flows at the Howland hydro-electric station downstream. An ancillary procedure is to release water as required during low flow periods to supply the intake to the Milo Water District. In addition, an effort is made to maintain Sebec Lake at approximate flashboard crest from July 1 to September 1 in deference to the Sebec Camp Owners Association.

### 1.3 PERTINENT DATA

a. Drainage Area - 327 square miles of flat and moderately rolling wooded terrain.

b. Discharge at Dam Site - Discharge is from over the spillway and through the two sluice gates. Elevations shown below are in feet referenced to NGVD datum.

1. Outlet Works (conduits):

|  |                                   |
|--|-----------------------------------|
| Two 11-ft. wide by 10-ft. high sluice gates w/water at dam top el. 330.4 | 6,400 cfs<br>(total, both gates). |
|--|-----------------------------------|

2. Maximum known flood at dam site:

|                |            |
|----------------|------------|
| March 20, 1936 | 11,400 cfs |
|----------------|------------|

3. Ungated spillway capacity at top of dam el. 330.4

|                            |
|----------------------------|
| 9,400 cfs w/flashboards    |
| 13,300 cfs w/o flashboards |

4. Ungated spillway capacity at test flood el. 347.5 (controlled by tailwater)

|                            |
|----------------------------|
| 30,400 cfs w/flashboards   |
| 31,100 cfs w/o flashboards |

5. Gated spillway capacity at normal pool el. 323

N/A

The left abutment has a top elevation of 325.0, a maximum of 16 feet in height above the streambed.

58 feet of the spillway has a crest elevation of about 322.2, while the remaining 120 feet is 1 foot lower. The entire spillway is normally operated at an elevation of about 323.0 using permanent flashboards.

The gate structure and right abutment (old powerhouse) has a top elevation of 330.4 and contains two 11-foot wide by 10-foot high steel wheeled sluice gates, both at an invert elevation of 309.1. Mounted above each gate is a steel hoist framework constructed to support a trolley-type lifting apparatus. Access to the gate structure is via the right embankment.

Elevations are in feet referenced to NGVD datum.

No instrumentation exists at this dam. There is a USGS stream gaging station on the Sebec River approximately 1,000 feet downstream of the dam.

c. Size Classification - LARGE - The dam impounds approximately 150,000 acre-feet with the pond level at the top of the dam, which at elevation 330.4 is about 21 feet above the streambed. According to the Recommended Guidelines, the dam is classified as large in size since its impoundment is greater than 50,000 acre-feet.

d. Hazard Classification - SIGNIFICANT - If the dam were to be breached, there is potential for considerable downstream damage and possible loss of a few lives. Two or three seasonally occupied structures approximately 3.8 miles downstream of the dam would be flooded to a depth of about 1 foot by the sudden 2-foot increase in stage from 5 to 7 feet above the streambed.

A breach under dry weather conditions would result in a sudden 10-foot increase in stage immediately downstream of the dam, from 5 to 15 feet. This would flood two seasonally occupied structures approximately 400 yards downstream of the dam to a depth of about 4 feet.

e. Ownership - Bangor Hydro-Electric Company  
33 State Street  
Bangor, Maine 04401  
Attn: Mr. Douglas Morrell  
(207)945-5621

f. Operator - Mr. Merle Doyer  
Bangor Hydro-Electric Company  
West Main Street  
Milo, Maine 04463  
(207)943-7371

PHASE I INSPECTION REPORT  
SECTION 1 - PROJECT INFORMATION

1.1 GENERAL




a. Authority - Public Law 92-367, August 8, 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a National Program of Dam Inspection throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region. James W. Sewall Company has been retained by the New England Division to inspect and report on selected dams in the State of Maine. Authorization and notice to proceed were issued to James W. Sewall Company under a letter of April 2, 1980 from William E. Hodgson, Jr. Colonel, Corps of Engineers. Contract No. DACW 33-80-C-0051 has been assigned by the Corps of Engineers for this work.

- b. Purpose of Inspection Program - The purposes of the program are to:
1. Perform technical inspection and evaluation of non-federal dams to identify conditions requiring correction in a timely manner by non-federal interests.
  2. Encourage and prepare the States to quickly initiate effective dam inspection programs for non-federal dams.
  3. To update, verify and complete the *National Inventory of Dams*.

1.2 DESCRIPTION OF PROJECT


a. Location - The dam is located on the headwaters of the Sebec River about 9.2 miles upstream from its confluence with the Piscataquis River in the Town of Sebec, County of Piscataquis, State of Maine. The dam is shown on the Sebec, Me. USGS Quadrangle Map having coordinates latitude N45°16.2' and longitude W69°07.0'.

b. Description of Dam and Appurtenances - The existing dam, founded on bedrock, is a roughly "Z" shaped concrete-capped timber crib structure, 276 feet in overall length, including a 20-foot long abutment section on the left, a 178-foot spillway section, a 20-foot long fish passage on the right, and the 58-foot long foundation of a now-defunct hydro-electric generating station, containing two outlet sluice gates, which forms the right abutment.



| USGS QUADRANGLES    |      |
|---------------------|------|
| SEBEC, ME.          | 1940 |
| SCHOODIC, ME.       | 1947 |
| DOVER-FOXCROFT, ME. | 1932 |
| BOYD LAKE, ME.      | 1955 |





SEBEC DAM


SEBEC

SEBEC RIVER

Stickney Hill


Brownville

Milo



US  
S  
S  
D  
B

REPRODUCED AT GOVERNMENT EXPENSE



REPRODUCED AT GOVERNMENT EXPENSE



OVERVIEW PHOTO

U.S. ARMY ENGINEER DIV. NEW ENGLAND  
CORPS OF ENGINEERS  
WALTHAM, MASSACHUSETTS

JAMES W. SEWALL COMPANY  
CONSULTANTS  
OLD TOWN, MAINE

NATIONAL PROGRAM OF  
INSPECTION OF  
NON-FED. DAMS

Sebec Dam - ME 00163

Sebec, Maine

February 1, 1981

| <u>Section</u>                                       | <u>Page</u> |
|--|-------------|
| 5.2 Design Data                                      | 5-1         |
| 5.3 Experience Data                                  | 5-1         |
| 5.4 Test Flood Analysis                              | 5-1         |
| 5.5 Dam Failure Analysis                             | 5-2         |
| 6. EVALUATION OF STRUCTURAL STABILITY                | 6-1         |
| 6.1 Visual Observation                               | 6-1         |
| 6.2 Design and Construction Data                     | 6-1         |
| 6.3 Post-Construction Changes                        | 6-1         |
| 6.4 Seismic Stability                                | 6-1         |
| 7. ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES | 7-1         |
| 7.1 Dam Assessment                                   | 7-1         |
| a. Condition   | 7-1         |
| b. Adequacy of Information                           | 7-1         |
| c. Urgency   | 7-1         |
| 7.2 Recommendations                                  | 7-1         |
| 7.3 Remedial Measures                                | 7-1         |
| 7.4 Alternatives                                     | 7-1         |

#### APPENDIX

|  |     |
|--|-----|
| APPENDIX A - VISUAL CHECK LIST WITH COMMENTS                               | A-1 |
| APPENDIX B - ENGINEERING DATA  | B-1 |
| APPENDIX C - DETAIL PHOTOGRAPHS  | C-1 |
| APPENDIX D - HYDRAULICS/HYDROLOGIC COMPUTATIONS                            | D-1 |
| APPENDIX E - INFORMATION AS CONTAINED IN THE<br>NATIONAL INVENTORY OF DAMS | E-1 |

d. Reservoir Area - There are no indications of instability along the banks of the reservoir in the vicinity of the dam. The reservoir is only 50 yards wide where it is spanned by the highway bridge 30 yards upstream of the dam. Continuing upstream, Sebec Lake gradually widens to its maximum width of two miles which occurs near the upper end of its eleven mile length.

e. Downstream Channel - At the left of the old power station is an abandoned concrete fishway which also serves as a training wall below the power station, as seen on the right side of Photo 8. This concrete has moderate spalling and some efflorescence. Extending about 25 yards from the lower end of the fishway is an earth filled, stone masonry wall separating the tailrace from the main river channel as shown in Photo 9. This wall is about 10 feet wide and 8 feet high with numerous small trees growing on it. This wall is in good condition. The main downstream channel is the original riverbed, as seen in Photo 9. This is stony with areas of exposed bedrock. The banks of the river are wooded.

The first crossing of the Sebec River downstream of this dam is the Bangor and Aroostook Railroad Bridge in Kilo. This is about seven miles downstream and is shown in Photo 10.

About 1,000 feet downstream of the railroad bridge, Main Street, Kilo, is carried over the Sebec River on two bridges with an island between them. These are shown in Photos 11 and 12. Just upstream westerly of the two bridges is a timber crib dam seen in the foreground of Photo 13.

### 3.2 EVALUATION

On the basis of the visual examination this dam is considered to be in fair condition.

Continued spalling and eroding of the concrete of the old power station could endanger the integrity of the structure, possibly resulting in the uncontrolled release of the waters of Sebec Lake.

## SECTION 4: OPERATIONAL AND MAINTENANCE PROCEDURES

### 4.1 OPERATIONAL PROCEDURES

a. General - The basic operating procedure is to follow an operations rating curve by holding or releasing water as needed for power generation at Howland Power Station about 25 miles downstream. An accessory procedure is to release water as needed to supply the intake for the Milo Water District. In addition, an effort is made to hold the level of Sebec Lake fairly constant from July 1 to September 1 in deference to the Sebec Camp Owners Association.

During periods of heavy flow, the site is visited by operating personnel about every other day. During other periods, the visits are approximately biweekly.

b. Warning System - No warning system is known to exist.

### 4.2 MAINTENANCE PROCEDURES

a. General - The dam receives no regular maintenance, but rather on an "as necessary" basis.

b. Operating Facilities - Maintenance of operating facilities is minimal.

### 4.3 EVALUATION

The operation and maintenance procedures at this dam are inadequate to ensure that all problems encountered can be remedied within a reasonable period of time. The owner should establish a written operation and maintenance procedure as well as a warning system to follow in the event of an emergency at the dam.

## SECTION 5: EVALUATION OF HYDRAULIC/HYDROLOGIC FEATURES

### 5.1 GENERAL

The project is a low surcharge - large storage timber crib structure, originally constructed and used for hydro power production, but currently used for stream regulation and water storage.

The tributary watershed consists of 327 square miles of undeveloped terrain which is virtually 100% wooded. With NGVD elevations ranging from 320 to over 2600 feet, portions of the watershed are very steep, but average watershed slope is approximately 3%. Further, the watershed contains numerous lakes and ponds, the aggregate surface area of which comprises about 10% of the watershed area. For purposes of hydrologic computation, the watershed is thus considered relatively flat.

Adjacent to and upstream of the dam, a roadway bridge crosses the approach channel with its bottom steel about 8.2 feet above the spillway crest. This bridge produces a hydraulic effect at higher flows.

Hydraulics computations indicate that downstream channel characteristics would control discharge from the dam at flows in excess of 15,000 cfs. Occurrence of the test flood would completely inundate the dam by virtue of the backwater from the downstream channel. The full spillway would accommodate about 22% of the routed Test Flood outflow from the dam, but would accommodate about 63% of the maximum flow which could be controlled by the dam.

### 5.2 DESIGN DATA

No design data are known to exist for this project.

### 5.3 EXPERIENCE DATA

The maximum known flood at the dam site occurred March 20, 1936, producing a peak outflow of 11,400 cfs. The dam reportedly failed on that date, releasing a major fraction of the storage in Sebec Lake, and contributing significantly to the severe downstream damages incurred during the general flooding at the time. No detailed information concerning the exact nature or extent of the failure was located.

### 5.4 TEST FLOOD ANALYSIS

The Test Flood for this significant hazard large size dam is the Probable Maximum Flood (PMF). Peak inflow to Sebec Lake is 85,000 cfs (260 csm) and was determined using the "Flat and Coastal" guide curve of the "Preliminary Guidance for Estimating Maximum Probable Discharge", dated March, 1978. Peak outflow is 43,000 cfs with the water elevation 26.5 feet above the spillway crest and the initial reservoir level assumed at the permanent flashboard crest (el. 323 NGVD). Based upon hydraulics computations, the spillway capacity is 9,400 cfs which is approximately 22% of the routed Test Flood outflow from Sebec Dam. Test Flood outflow is controlled by the reach directly

downstream of the dam, the backwater from which would, at flows in excess of about 15,000 cfs, submerge the dam. The spillway capacity is thus about 68% of that flow on which the dam would act as a control.

#### 5.5 DAM FAILURE ANALYSIS

Utilizing the April, 1978 "Rule of Thumb Guidance for Estimating Downstream Dam Failure Hydrographs", the peak failure outflow with the pool initially at the top of the dam (el. 330.4 NGVD) would be approximately 13,000 cfs, an increase of 3,600 cfs above the estimated 9,400 cfs pre-failure flow. The breach would cause an increase in stage immediately downstream from the dam from about 18 feet to 22 feet, which would likely cause little further damage as two seasonal residences in the area would be destroyed by the pre-failure flow. Further downstream, approximately 3.8 miles from the dam, the sudden increase in stage from 5.2 feet to 6.8 feet would be sufficient to flood two or three seasonal residences to a depth of about 1 foot. Further downstream, estimated stage increases of 1 foot or less would create little damage beyond that caused by the pre-failure flow.

The consequences of a "dry weather" failure with the water level initially at the top of the flashboards (323 NGVD) was also investigated. A pre-failure flow of about 300 cfs emanating from one sluice gate was assumed. The peak failure outflow would be 6,600 cfs. The sudden increase in stage from 5 feet to 15 feet immediately downstream from the dam would flood two seasonal residences in the area to a depth of about 4 feet. Further downstream, resulting increases in stage would be expected to cause little damage.

There is potential for considerable property damage and possible loss of a few lives, thus Sebec Dam has been classified as a "Significant Hazard" dam.



## SECTION 6: EVALUATION OF STRUCTURAL STABILITY

### 6.1 VISUAL OBSERVATION

The visual inspection of the dam indicates the following potential problem:

Continued spalling and eroding of the concrete of the old power station could endanger the integrity of the structure possibly resulting in the uncontrolled release of the storage contained in Sebec Lake.

### 6.2 DESIGN AND CONSTRUCTION DATA

No original design and construction data are available for the dam.

### 6.3 POST-CONSTRUCTION CHANGES

The rock-filled timber crib dam is shown on the plan of Sebec Village in the 1882 Colby Atlas. There was at that time a saw mill at the site. In about 1920, an attempt was made by the Boston Excelsior Co. of Milo, Maine, to construct a stone masonry and concrete dam, together with a power station, adjacent to and downstream of, the original timber-crib structure. The new dam reportedly failed as it was being filled and the timber crib dam was subsequently renovated and utilized in conjunction with the power station. The dam sustained damage in the 1936 flood and was subsequently repaired. On August 19, 1940, the powerhouse burned. The dam was at that time owned by Maine Public Service Company. The structure has since been acquired by the Bangor Hydro-Electric Company and has, since 1960, undergone considerable renovation work, including sheet piling, concrete cap and aprons, and new sluice gates.

### 6.4 SEISMIC STABILITY

The dam is located in Seismic Zone 2, and in accordance with the recommended Phase 1 guidelines does not warrant seismic investigation.

## SECTION 7: ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES

### 7.1 DAM ASSESSMENT

- a. Condition - Based upon the visual inspection, the dam is judged to be in fair condition.
- b. Adequacy of Information - Due to the lack of design and construction data for this dam, the assessment of safety is based solely on the visual inspection.
- c. Urgency - The remedial measures and recommendations presented below should be implemented by the owner within one year after receipt of this Phase I Inspection Report.

### 7.2 RECOMMENDATIONS

The owner should engage a qualified registered engineer to further assess the spalled and eroded concrete of the old power station and fishway and submit recommendations for the repair and rehabilitation of the same.

The owner should implement all recommendations by the engineer.

### 7.3 REMEDIAL MEASURES

- a. A program of **annual** technical inspection, with repairs as necessary, should be instituted by the owner.
- b. The dam should be monitored during flood periods and a formal downstream warning system, to be implemented in the event of an emergency at the dam, should be developed by the owner.
- c. A formal program of operation and maintenance procedures should be instituted and fully documented to provide accurate records for future reference.

### 7.4 ALTERNATIVES

This study has identified no practical alternative to the above recommendations.

APPENDIX A  
VISUAL CHECK LIST WITH COMMENTS

VISUAL INSPECTION CHECKLIST  
PARTY ORGANIZATION

PROJECT Sugar Dam

DATE Nov. 4, 1955

TIME 9:00

WEATHER Clear

W.S. ELEV. \_\_\_\_\_ U.S. \_\_\_\_\_ DN.S. \_\_\_\_\_

PARTY:

- 1. Spencer, W.M. Chief 6. \_\_\_\_\_
- 2. Boyer, G.H. PLP 7. \_\_\_\_\_
- 3. Carroll, J.H. Chief 8. \_\_\_\_\_
- 4. Draft, H. PLP 9. \_\_\_\_\_
- 5. \_\_\_\_\_ 10. \_\_\_\_\_

| PROJECT FEATURE                           | INSPECTED BY       | REMARKS            |
|---|--------------------|--------------------|
| 1. <u>Levee and Embankment</u>            | <u>S.D.M. G.L.</u> | <u>S.D.M. G.L.</u> |
| 2. <u>Levee and Embankment</u>            | <u>S.D.M. G.L.</u> | <u>S.D.M. G.L.</u> |
| 3. <u>Outlet Structure</u>                |                    |                    |
| 4. <u>Spillway and Dissipator Channel</u> |                    |                    |
| 5. _____                                  |                    |                    |
| 6. _____                                  |                    |                    |
| 7. _____                                  |                    |                    |
| 8. _____                                  |                    |                    |
| 9. _____                                  |                    |                    |
| 10. _____                                 |                    |                    |

PROJECT Chico Dam DATE 10/1/77  
 PROJECT FEATURE Concrete and Timber Dam NAME ...  
 DISCIPLINE ... NAME ...


| AREA EVALUATED  | CONDITION  |
|---|--|
| <u>DAM EMBANKMENT</u>                                 | <i>Concrete and timber dam with<br/>seepage hydrotechnical plant.</i>  |
| Crest Elevation                                       | <i>Main section of dam and hydro<br/>plant founded on glacial soil<br/>near abutment. Dam built<br/>on glacial till.</i> |
| Current Pool Elevation                                |  |
| Maximum Impoundment to Date                           |  |
| Surface Cracks  |  |
| Pavement Condition                                    |  |
| Movement or Settlement of Crest                       |  |
| Lateral Movement                                      | <i>None observed.</i>  |
| Vertical Alignment                                    | <i>Good</i>  |
| Horizontal Alignment                                  | <i>Good</i>  |
| Condition at Abutment and at Concrete Structures      | <i>Condition at abutment contact<br/>is good.</i>  |
| Indications of Movement of Structural Items on Slopes |  |
| Trespassing on Slopes                                 | <i>N.A.</i>  |
| Sloughing or Erosion of Slopes or Abutments           | <i>N.A.</i>  |
| Rock Slope Protection - Riprap Failures               | <i>N.A.</i>  |
| Unusual Movement or Cracking at or Near Toe           | <i>N.A.</i>  |
| Unusual Embankment or Downstream Seepage              | <i>N.A.</i>  |
| Piping or Boils                                       | <i>N.A.</i>  |
| Foundation Drainage Features                          | <i>N.A.</i>  |
| Toe Drains  | <i>N.A.</i>  |
| Instrumentation System                                | <i>N.A.</i>  |
| Vegetation  | <i>N.A.</i>  |

PERIODIC INSPECTION CHECKLIST

PROJECT Dam DATE 10/10/00

PROJECT FEATURE \_\_\_\_\_ NAME \_\_\_\_\_

DISCIPLINE Geotechnical Engineering NAME \_\_\_\_\_

| AREA EVALUATED   | CONDITION  |
|--|--|
| <p><u>DIKE EMBANKMENT</u></p> <ul style="list-style-type: none"> <li>Crest Elevation</li> <li>Current Pool Elevation</li> <li>Maximum Impoundment to Date</li> <li>Surface Cracks</li> <li>Pavement Condition</li> <li>Movement or Settlement of Crest</li> <li>Lateral Movement</li> <li>Vertical Alignment</li> <li>Horizontal Alignment</li> <li>Condition at Abutment and at Concrete Structures</li> <li>Indications of Movement of Structural Items on Slopes</li> <li>Trespassing on Slopes</li> <li>Sloughing or Erosion of Slopes or Abutments</li> <li>Rock Slope Protection - Riprap Failures</li> <li>Unusual Movement or Cracking at or Near Toes</li> <li>Unusual Embankment or Downstream Seepage</li> <li>Piping or Boils</li> <li>Foundation Drainage Features</li> <li>Toe Drains</li> <li>Instrumentation System</li> <li>Vegetation</li> </ul> | <p><i>Time limited</i></p>  |

PROJECT S. ...

DATE ...

PROJECT FEATURE ...

NAME ...

DISCIPLINE ...

NAME ...

| AREA EVALUATED  | CONDITION   |
|---|---|
| <p><u>OUTLET WORKS - INTAKE CHANNEL AND INTAKE STRUCTURE</u></p> <p>a. Approach Channel</p> <ul style="list-style-type: none"> <li>Slope Conditions</li> <li>Bottom Conditions</li> <li>Rock Slides or Falls</li> <li>Log Boom</li> <li>Debris</li> <li>Condition of Concrete Lining</li> <li>Drains or Weep Holes</li> </ul> <p>b. Intake Structure</p> <ul style="list-style-type: none"> <li>Condition of Concrete</li> <li>Stop Logs and Slots</li> </ul> | <p><i>Adjacent to the right abutment and upstream of the square gate there is a concrete retaining wall which is in good condition.</i></p> <p><i>Concrete masonry shows amount of spalling with some erosion and efflorescence</i></p> |

PERIODIC INSPECTION CHECKLIST

PROJECT \_\_\_\_\_

DATE \_\_\_\_\_

PROJECT FEATURE \_\_\_\_\_

NAME \_\_\_\_\_

DISCIPLINE Technical Engineering

NAME \_\_\_\_\_

| AREA EVALUATED   | CONDITION  |
|--|--|
| <p><u>OUTLET WORKS - CONTROL TOWER</u></p> <p>a. Concrete and Structural</p> <p>    General Condition</p> <p>    Condition of Joints</p> <p>    Spalling</p> <p>    Visible Reinforcing</p> <p>    Rusting or Staining of Concrete</p> <p>    Any Seepage or Efflorescence</p> <p>    Joint Alignment</p> <p>    Unusual Seepage or Leaks in Gate Chamber</p> <p>    Cracks</p> <p>    Rusting or Corrosion of Steel</p> <p>b. Mechanical and Electrical</p> <p>    Air Vents</p> <p>    Float Wells</p> <p>    Crane Hoist</p> <p>    Elevator</p> <p>    Hydraulic System</p> <p>    Service Gates</p> <p>    Emergency Gates</p> <p>    Lightning Protection System</p> <p>    Emergency Power System</p> <p>    Wiring and Lighting System</p> | <p><i>The outlet works tower</i></p> <p><i>N.A.</i></p> <p><i>N.A.</i></p> |




PERIODIC INSPECTION CHECKLIST

PROJECT \_\_\_\_\_ DATE \_\_\_\_\_

PROJECT FEATURE \_\_\_\_\_ NAME \_\_\_\_\_

DISCIPLINE \_\_\_\_\_ NAME \_\_\_\_\_


| AREA EVALUATED  | CONDITION  |
|---|--|
| <p><u>LET WORKS - TRANSITION AND CONDUIT</u></p> <p>General Condition of Concrete</p> <p>Rust or Staining on Concrete</p> <p>Spalling</p> <p>Erosion or Cavitation</p> <p>Cracking</p> <p>Alignment of Monoliths</p> <p>Alignment of Joints</p> <p>Numbering of Monoliths</p> |  |

JECT \_\_\_\_\_ DATE \_\_\_\_\_

JECT FEATURE \_\_\_\_\_ NAME \_\_\_\_\_

CIPLINE \_\_\_\_\_ NAME \_\_\_\_\_


| AREA EVALUATED   | CONDITION  |
|--|--|
| <p><u>LET WORKS - OUTLET STRUCTURE AND</u><br/><u>OUTLET CHANNEL</u></p> |  |
| <p>General Condition of Concrete</p>                                     |  |
| <p>Rust or Staining</p>  |  |
| <p>Spalling</p>  |  |
| <p>Erosion or Cavitation</p>   |  |
| <p>Visible Reinforcing</p>   |  |
| <p>Any Seepage or Efflorescence</p>                                      | <p><i>There are no areas of efflorescence.</i></p> |
| <p>Condition at Joints</p>   |  |
| <p>Drain holes</p>   |  |
| <p>Channel</p>   |  |
| <p>Loose Rock or Traces Overhanging Channel</p>                          |  |
| <p>Condition of Discharge Channel</p>                                    | <p><i>Good</i></p>                                 |



3-27-34  
GENERAL PLAN & ELEVATION  
SHEET NO. 1  
MULLEN & COMPANY  
ARCHITECTS  
SANTA FE, N.M.  
1934

B-10

FRONT ELEVATION



Log of 1960 Borings

| Boring No. | Depth (ft) | Remarks |
|------------|------------|---------|
| Boring 01  | 31.0       | ...     |
| Boring 02  | 31.0       | ...     |
| Boring 03  | 31.0       | ...     |
| Boring 04  | 31.0       | ...     |
| Boring 05  | 31.0       | ...     |
| Boring 06  | 31.0       | ...     |
| Boring 07  | 31.0       | ...     |
| Boring 08  | 31.0       | ...     |
| Boring 09  | 31.0       | ...     |
| Boring 10  | 31.0       | ...     |
| Boring 11  | 31.0       | ...     |
| Boring 12  | 31.0       | ...     |
| Boring 13  | 31.0       | ...     |
| Boring 14  | 31.0       | ...     |
| Boring 15  | 31.0       | ...     |
| Boring 16  | 31.0       | ...     |
| Boring 17  | 31.0       | ...     |
| Boring 18  | 31.0       | ...     |
| Boring 19  | 31.0       | ...     |
| Boring 20  | 31.0       | ...     |
| Boring 21  | 31.0       | ...     |
| Boring 22  | 31.0       | ...     |
| Boring 23  | 31.0       | ...     |
| Boring 24  | 31.0       | ...     |
| Boring 25  | 31.0       | ...     |
| Boring 26  | 31.0       | ...     |
| Boring 27  | 31.0       | ...     |
| Boring 28  | 31.0       | ...     |
| Boring 29  | 31.0       | ...     |
| Boring 30  | 31.0       | ...     |
| Boring 31  | 31.0       | ...     |
| Boring 32  | 31.0       | ...     |
| Boring 33  | 31.0       | ...     |
| Boring 34  | 31.0       | ...     |
| Boring 35  | 31.0       | ...     |
| Boring 36  | 31.0       | ...     |
| Boring 37  | 31.0       | ...     |
| Boring 38  | 31.0       | ...     |
| Boring 39  | 31.0       | ...     |
| Boring 40  | 31.0       | ...     |
| Boring 41  | 31.0       | ...     |
| Boring 42  | 31.0       | ...     |
| Boring 43  | 31.0       | ...     |
| Boring 44  | 31.0       | ...     |
| Boring 45  | 31.0       | ...     |
| Boring 46  | 31.0       | ...     |
| Boring 47  | 31.0       | ...     |
| Boring 48  | 31.0       | ...     |
| Boring 49  | 31.0       | ...     |
| Boring 50  | 31.0       | ...     |

BANGOR HYDRO-ELECTRIC CO  
 BANGOR, MAINE  
 GENERAL PLAN  
 SCALE: HORIZ. 1" = 10'-0"  
 VERT. 1" = 10'-0"  
 DRAWN BY: MOW  
 M-2061a

Fishes

|                          |                |
|--------------------------|----------------|
| Salmon                   | Chain pickerel |
| Brook trout (squaretail) | Smelt          |
| Lake trout (logue)       | Eel            |
| Smallmouth bass          | White sucker   |
| Yellow perch             | Minnows        |
|                          | Cusk           |

Physical Characteristics


Area - 10,000 acres  
 Maximum depth - 155 feet  
 Temperatures  
 Surface - 75° F.  
 150 feet - 45° F.

Principal fishery: Salmon, lake trout, smallmouth bass  
 Sebec Lake provides ideal water quality for salmonids. A large portion of the water volume is cold with abundant dissolved oxygen at all depths in late summer.

In 1961, Sebec Lake was managed for its fine natural salmon population. However, in the years 1961 through 1966 lake trout were stocked in order to utilize the large amount of deep water and increase the fishing potential of the lake. These lake trout now form a well established population and are reproducing naturally in the lake. They are providing an excellent fishery in addition to the salmon for both summer and winter anglers.

Regulations controlling the size and bag limit of bass have been liberalized in hopes of reducing competition from this species. Presently the minimum length limit for salmon is 12 inches. This allows anglers to take advantage of large numbers of salmon that are slow to reach the normal 14-inch minimum length.

Survey 1 - 1950  
 Catalog 1, 1-53, 1970)  
 Maine Department of Inland Fisheries and Game  
 Publication Order Appropriation No. 4223.



SEBEC LAKE  
 WILLIMANTIC BATHYMETRIC, DEPTH-FOURFOOT AND SEBEC TYPE  
 PERGLACIALS (CL. MARK)  
 AREA 1003 ACRES  
 1/4 IN. = 1 MILE

*Av. Depth 44.2 ft*

SEBEC LAKE BASIN

DISCHARGE AT SEBEC DAM, SEBEC LAKE, ME

LOCATION: Lat 45°11'12" N, Long 68°44'44" W, Piscataquis County, Sebasticus River (1,200 ft), on right bank 1,000 ft (300 m) downstream from highway bridge and dam at outlet of Sebec Lake at Sebec.

DRAINAGE AREA: 547 mi<sup>2</sup> (1417 km<sup>2</sup>).

PERIOD OF RECORD: October 1924 to current year.

RAISED RECORDS: RSP 1171: Drainage area, 1,186(M). RSP 1361: 1925.

GAGE: Water-stage recorder. Datum of gage is 286.3 ft (87.3 m) above mean sea level. Prior to June 22, 1942, at site on opposite bank 60 ft (18 m) downstream at same datum.

REMARKS: Records good except those for period of no gage height record, which are fair. Flow regulated by Sebec Lake (Reservoir) in Piscataquis River basin and other reservoirs upstream. Several observations of water temperature and specific conductance were made during the year.

AVERAGE DISCHARGE: 53 years, 631 ft<sup>3</sup>/s (17.87 m<sup>3</sup>/s), 20.20 in/yr (605 mm/yr), unadjusted.

EXTREMES FOR PERIOD OF RECORD: Maximum discharge, 11,410 ft<sup>3</sup>/s (323 m<sup>3</sup>/s) Mar. 26, 1936, gage height, 14.46 ft (4.407 m), from rating curve extended to gage; 11,370 ft<sup>3</sup>/s (322 m<sup>3</sup>/s) on basis of velocity-area studies; minimum, about 2 ft<sup>3</sup>/s (0.057 m<sup>3</sup>/s) Oct. 14-15, 1930, gage height, 0.62 ft (0.190 m), when gates in dam were closed.

EXTREMES FOR CURRENT YEAR: Maximum discharge, 2,440 ft<sup>3</sup>/s (69.8 m<sup>3</sup>/s) Apr. 24, gage height, 6.04 ft (1.841 m); minimum daily, 77 ft<sup>3</sup>/s (2.18 m<sup>3</sup>/s) Oct. 20.

DISCHARGE, IN CUBIC FEET PER SECOND, WATER YEAR OCTOBER 1976 TO SEPTEMBER 1977  
MEAN VALUES

| DAY               | OCT   | NOV    | DEC   | JAN  | FEB  | MAR   | APR   | MAY   | JUN               | JUL   | AUG               | SEP   |      |       |
|-------------------|-------|--------|-------|------|------|-------|-------|-------|-------------------|-------|-------------------|-------|------|-------|
| 1                 | 600   | 631    | 380   | 321  | 585  | 267   | 1690  | 1910  | 136               | 1550  | 245               | 285   |      |       |
| 2                 | 590   | 656    | 374   | 316  | 450  | 271   | 1400  | 1810  | 142               | 1430  | 240               | 290   |      |       |
| 3                 | 580   | 638    | 374   | 316  | 405  | 267   | 2040  | 1740  | 145               | 1040  | 245               | 290   |      |       |
| 4                 | 570   | 669    | 354   | 307  | 400  | 197   | 2090  | 1630  | 148               | 437   | 245               | 290   |      |       |
| 5                 | 560   | 1020   | 340   | 307  | 395  | 210   | 2080  | 1530  | 151               | 503   | 245               | 280   |      |       |
| 6                 | 540   | 1250   | 330   | 303  | 390  | 209   | 2060  | 1430  | 154               | 434   | 245               | 280   |      |       |
| 7                 | 491   | 1240   | 345   | 299  | 385  | 201   | 1960  | 1380  | 161               | 401   | 240               | 276   |      |       |
| 8                 | 440   | 1200   | 457   | 299  | 375  | 193   | 1870  | 1280  | 168               | 390   | 236               | 267   |      |       |
| 9                 | 457   | 1130   | 547   | 307  | 370  | 186   | 1800  | 1060  | 164               | 316   | 236               | 262   |      |       |
| 10                | 669   | 1020   | 466   | 307  | 365  | 186   | 1780  | 984   | 161               | 209   | 232               | 262   |      |       |
| 11                | 696   | 947    | 572   | 307  | 360  | 189   | 1780  | 969   | 164               | 205   | 236               | 262   |      |       |
| 12                | 676   | 890    | 566   | 307  | 355  | 205   | 1700  | 947   | 168               | 205   | 236               | 262   |      |       |
| 13                | 644   | 835    | 560   | 305  | 350  | 228   | 1430  | 619   | 158               | 205   | 236               | 262   |      |       |
| 14                | 638   | 782    | 534   | 305  | 345  | 340   | 1510  | 105   | 148               | 209   | 236               | 262   |      |       |
| 15                | 595   | 743    | 503   | 305  | 335  | 601   | 1600  | 105   | 148               | 209   | 236               | 480   |      |       |
| 16                | 560   | 702    | 465   | 300  | 335  | 911   | 1670  | 105   | 145               | 205   | 262               | 1110  |      |       |
| 17                | 497   | 676    | 474   | 300  | 325  | 1450  | 1750  | 110   | 139               | 213   | 290               | 1070  |      |       |
| 18                | 468   | 553    | 462   | 300  | 325  | 1550  | 1860  | 112   | 145               | 249   | 294               | 1040  |      |       |
| 19                | 193   | 457    | 434   | 300  | 320  | 1560  | 1540  | 120   | 154               | 249   | 290               | 1010  |      |       |
| 20                | 77    | 534    | 412   | 294  | 315  | 1500  | 2120  | 125   | 171               | 245   | 290               | 962   |      |       |
| 21                | 112   | 485    | 401   | 290  | 310  | 1380  | 2250  | 125   | 193               | 245   | 290               | 897   |      |       |
| 22                | 117   | 457    | 390   | 290  | 305  | 1260  | 2410  | 125   | 197               | 245   | 290               | 835   |      |       |
| 23                | 154   | 457    | 374   | 303  | 300  | 1170  | 2560  | 125   | 253               | 245   | 290               | 743   |      |       |
| 24                | 232   | 429    | 374   | 294  | 295  | 1100  | 2610  | 128   | 285               | 245   | 290               | 644   |      |       |
| 25                | 321   | 406    | 369   | 290  | 290  | 1060  | 2610  | 130   | 316               | 245   | 290               | 563   |      |       |
| 26                | 434   | 395    | 359   | 290  | 285  | 1070  | 2540  | 130   | 457               | 245   | 290               | 522   |      |       |
| 27                | 516   | 395    | 354   | 290  | 285  | 1070  | 2420  | 130   | 702               | 245   | 290               | 572   |      |       |
| 28                | 547   | 390    | 354   | 290  | 280  | 1100  | 2310  | 130   | 801               | 245   | 290               | 455   |      |       |
| 29                | 553   | 401    | 340   | 290  | ---  | 1110  | 2190  | 136   | 815               | 240   | 280               | 918   |      |       |
| 30                | 553   | 395    | 335   | 285  | ---  | 1170  | 2040  | 136   | 1260              | 240   | 280               | 977   |      |       |
| 31                | 566   | ---    | 330   | 425  | ---  | 1380  | ---   | 136   | ---               | 245   | 285               | ---   |      |       |
| TOTAL             | 14646 | 20817  | 13049 | 4442 | 9835 | 23617 | 60620 | 19522 | 6349              | 11549 | 8180              | 17038 |      |       |
| MEAN              | 472   | 694    | 421   | 305  | 351  | 762   | 2021  | 630   | 278               | 376   | 264               | 566   |      |       |
| MAX               | 696   | 1250   | 572   | 425  | 585  | 1560  | 2610  | 1910  | 1260              | 1550  | 294               | 1110  |      |       |
| MIN               | 77    | 390    | 330   | 285  | 280  | 186   | 1430  | 105   | 136               | 205   | 232               | 262   |      |       |
| MEAN <sup>1</sup> | 686   | 641    | 380   | 224  | 115  | 1005  | 2181  | 557   | 601               | 180   | 109               | 574   |      |       |
| CFSM <sup>1</sup> | 2.10  | 1.86   | 1.16  | 1.68 | 1.35 | 3.07  | 6.67  | 1.64  | 1.58              | 1.58  | 1.64              | 1.77  |      |       |
| IN:1              | 2.42  | 2.18   | 1.34  | 1.79 | 1.37 | 3.34  | 7.44  | 1.89  | 2.05              | 1.67  | 1.74              | 1.98  |      |       |
| CAL YR 1976       | TOTAL | 317198 | MEAN  | 667  | MAX  | 5210  | MIN   | 77    | MEAN <sup>1</sup> | 866   | CFSM <sup>1</sup> | 2.65  | IN:1 | 56.08 |
| WTR YR 1977       | TOTAL | 216764 | MEAN  | 594  | MAX  | 2610  | MIN   | 77    | MEAN <sup>1</sup> | 612   | CFSM <sup>1</sup> | 1.87  | IN:1 | 25.42 |

<sup>1</sup> Adjusted for change in contents in Sebec Lake.  
NOTE: No gage-height record Jan. 30 to Mar. 3.

26 Generators

| No. of Units | Make | Date Installed | K. W. Per Unit | Voltage | Amp. | Capacity K.V.A. |
|--------------|------|----------------|----------------|---------|------|-----------------|
|              |      |                |                |         |      |                 |
|              |      |                |                |         |      |                 |
|              |      |                |                |         |      |                 |
|              |      |                |                |         |      |                 |
|              |      |                |                |         |      |                 |
|              |      |                |                |         |      |                 |
|              |      |                |                |         |      |                 |
|              |      |                |                |         |      |                 |
|              |      |                |                |         |      |                 |

27 Steam Plant Capacity K.W. H.P.

28 Fuel

29 Remarks

---



---



---



---



---



---

(PASTE PHOTO HERE)

30 Information furnished by R. E. Stratton Title Hyd. Engr.,  
Bangor Hydro-Electric Company

31 Information obtained by R. A. Ranger Date 9-28-1964  
PUC Engineer





APPLICATION FOR DAM REGISTRATION

Dam Registration Number 191  
Date Received 11/7/77  
Fee Paid 200  
Qual. Sheet No. 1  
Qual. Sheet Number 1

Location:  
County: Piscataquis  
Municipality: Sebec  
Name of Dam: Sebec Lake Dam  
Name of Impoundment: Sebec Lake

Ownership:  
Name of Owner: Banger Hydro-Electric Company  
Address of Owner: 33 State St.  
Bangor, Maine 04401  
Telephone Number: 945-5621

Name of Project: \_\_\_\_\_  
(If different than name of)  
Address: \_\_\_\_\_  
Telephone Number: \_\_\_\_\_

Description of Dam

Type: Storage  
Construction Material: Timber Crib with Concrete Decks  
(Concrete, wood, earth)  
Year Originally built: Unknown Year last major repair: 1975  
Height: 12 Ft. Width: 250 Ft.  
Spillway type: Overfalling & Gates Spillway Width: Crest Length 170 Ft.  
Storing Capacity: 36800 Drawdown available: 6  
(Acres-feet) (feet)  
Has Drawdown available?: Yes Installed Electrical Generating Cap: 0  
Application for which stored water is used: Auxiliary Flow of Piscataquis/Penobscot Rivers  
for Power Generation.

Inspected by qualified Engineer (Date): Fall 1977  
Name of Engineer: Richard E. Stratton, Civil Engineer

Name of Applicant: \_\_\_\_\_  
Address: \_\_\_\_\_  
City: \_\_\_\_\_

SUMMARY OF DATA AND CORRESPONDENCE

| <u>DATE</u> | <u>SUBJECT</u>  |
|-------------|---|
| 3-16-77     | Dam registration sheet from Soil and<br>Water Conservation Commission                     |
|             | Dam Inventory sheet from P.U.C. and USGS  |
| 1882        | Plan of Sebec Village from Colby Atlas  |
| 1977        | Stream Flow Records at Sebec From USGS Water<br>Resources Data for Maine Water, Year 1977 |
| 1970        | Sebec Lake Survey and Chart by Department of<br>Inland Fisheries and Game                 |

SEBEC DAM  
EXISTING PLANS

On file with Bangor Hydro-Electric Company:

1. Sebec Lake Dam, Proposed Concrete Forebay, Changes to Accommodate Fishway M-3092A, September 1, 1978
2. Sebec Lake Dam, Proposed Concrete Forebay, M-3092, August 29, 1977
3. Sebec Dam, General Plan, Sebec, Maine, M-2061A, Nov. 19, 1975
4. Sebec Dam, General Plan, Sebec, Maine, M-2061, January 23, 1961

On file with the Maine Office of Energy Resources:

1. Survey, Excavation and General Plan, Sebec Power Station and Dam for Boston Excelsior Co., Milo, Maine, August 20, 1920
2. Excavation for Dam and Tail Race, Sebec Power Station and Dam for Boston Excelsior Co., Milo, Maine, August 21, 1920
3. Plan and Section of Large Gates and Frames for Boston Excelsior Co., Milo, Maine, Dam at Sebec, Maine, September 1920
4. Plan of Station and Headgates, Sebec Plant for Milo Light and Power Co., December 30, 1920
5. Sections of Flume, Dam, etc., Sebec Plant for Milo Light and Power Co., December 15, 1920
6. Transverse Sections of Flume and Fishway, Sebec Plant for Milo Light and Power Co., January 12, 1921
7. Plan and Section of Fishway, Sebec Plant for Milo Light and Power Co., December 22, 1920
8. General Plan and Elevation, Sebec Plant for Milo Light and Power Co., December 13, 1920
9. Water Racks and Fishway Gates, Sebec Plant for Milo Light and Power Co., January 20, 1921
10. Waste Way and Log Sluice, Sebec Plant for Milo Light and Power Co., October 20, 1920




APPENDIX B  
ENGINEERING DATA

PROJECT Super Bridge DATE 1/17/77  
 PROJECT FEATURE \_\_\_\_\_ NAME \_\_\_\_\_  
 DISCIPLINE Structural Engineers Inc. NAME \_\_\_\_\_

| AREA EVALUATED  | CONDITION                             |
|---|---------------------------------------|
| <p><u>OUTLET WORKS - SERVICE BRIDGE</u></p> <p>a. Super Structure</p> <ul style="list-style-type: none"> <li>Bearings</li> <li>Anchor Bolts</li> <li>Bridge Seat</li> <li>Longitudinal Members</li> <li>Underside of Deck</li> <li>Secondary Bracing</li> <li>Deck</li> <li>Drainage System</li> <li>Railings</li> <li>Expansion Joints</li> <li>Paint</li> </ul> <p>b. Abutment &amp; Piers</p> <ul style="list-style-type: none"> <li>General Condition of Concrete</li> <li>Alignment of Abutment</li> <li>Approach to Bridge</li> <li>Condition of Seat &amp; Backwall</li> </ul> | <p><i>Good</i></p> <p><i>Good</i></p> |








JAMES V. SWALL, CO.  
 QUINCY, ILL.  
 QUINCY PLAN  
 PISCATAQUIS COUNTY, 1892  
 3011-11-31

APPENDIX C  
DETAIL PHOTOGRAPHS

○ OVERVIEW  
↓



○ 10 ○ 11 ○ 12 ○ 13

TAKEN  
DOWNSTREAM  
↓

SELEC DAM  
PHOTO LOCATION PLAN

APPENDIX D  
HYDRAULIC/HYDROLOGIC COMPUTATIONS



1. Rock-filled Timber Cribwork Visible Under Concrete



2. Downstream Side of Concrete Capped Spillway Crest.  
Concrete Apron at Left Foreground.

U.S. ARMY ENGINEER DIV, NEW ENGLAND  
CORPS OF ENGINEERS  
WALTHAM, MASSACHUSETTS

JAMES W. SEWALL COMPANY  
CONSULTANTS  
OLD TOWN, MAINE

NATIONAL PROGRAM OF  
INSPECTION OF  
NON-FED. DAMS

Sebec Dam

ME 00163


Sebec, Maine

Nov. 4, 1980

C-2



3. Exposed Bedrock at Right Abutment. Steel Joists Supported Former Powerhouse.



4. Area at Left Abutment

U.S. ARMY ENGINEER DIV, NEW ENGLAND  
CORPS OF ENGINEERS  
WALTHAM, MASSACHUSETTS

JAMES W. SEWALL COMPANY  
CONSULTANTS  
OLD TOWN, MAINE

NATIONAL PROGRAM OF  
INSPECTION OF  
NON-FED. DAMS


Sebec Dam

ME 00163

Sebec, Maine

Nov. 4, 1980

C-3



5. View of Forebay at Right, Gate Structure and Substructure of Former Power Station at Center Behind Uncompleted Fish Passage.



6: Uncompleted Fish Passage Adjacent to Power Station Substructure.

U.S. ARMY ENGINEER DIV, NEW ENGLAND  
CORPS OF ENGINEERS  
WALTHAM, MASSACHUSETTS

JAMES W. SEWALL COMPANY  
CONSULTANTS  
OLD TOWN, MAINE

NATIONAL PROGRAM OF  
INSPECTION OF  
NON-FED. DAMS

Sebec Dam

ME 00163

Sebec, Maine

Nov. 4, 1980

C-4



7. Sluice Gates at End of Forebay



8. Outlet Openings in Downstream Foundation Wall of Power Station at Left, Abandoned Fishway at Right.

U.S. ARMY ENGINEER DIV, NEW ENGLAND  
CORPS OF ENGINEERS  
WALTHAM, MASSACHUSETTS

JAMES W. SEWALL COMPANY  
CONSULTANTS  
OLD TOWN, MAINE

NATIONAL PROGRAM OF  
INSPECTION OF  
NON-FED. DAMS

Sebec Dam


ME 00163

Sebec, Maine

Nov. 4, 1980

C-5





9. Original Riverbed Below Spillway Section of Dam. Abandoned Fishway and Masonry Training Wall at Right, Remains of Wastegate Section of Former Dam at Left Bank.



10. Railroad Bridge Crossing Sebec River In Milo.

J.S. ARMY ENGINEER DIV, NEW ENGLAND  
CORPS OF ENGINEERS  
WALTHAM, MASSACHUSETTS

JAMES W. SEWALL COMPANY  
CONSULTANTS  
OLD TOWN, MAINE

NATIONAL PROGRAM OF  
INSPECTION OF  
NON-FED. DAMS


Sebec Dam

ME 00163

Sebec, Maine

Nov. 4, 1980

C-6



11. & 12. Two Bridges Carry Main Street, Milo, Over the Sebec River

ARMY ENGINEER DIV, NEW ENGLAND  
CORPS OF ENGINEERS  
WALTHAM, MASSACHUSETTS

JAMES W. SEWALL COMPANY  
CONSULTANTS  
OLD TOWN, MAINE

NATIONAL PROGRAM OF  
INSPECTION OF  
NON-FED. DAMS

Sebec Dam

ME 00163

Sebec, Maine

Nov. 4, 1980

C-7



13. Timber Crib Dam Above the Westerly Main Street Bridge in Milo.

ARMY ENGINEER DIV, NEW ENGLAND  
CORPS OF ENGINEERS  
WALTHAM, MASSACHUSETTS

JAMES W. SEWALL COMPANY  
CONSULTANTS  
OLD TOWN, MAINE

NATIONAL PROGRAM OF  
INSPECTION OF  
NON-FED. DAMS

Sebec Dam

ME 00163

Sebec, Maine

Nov. 4, 1980


C-8

DRAINAGE AREA  
327 SQ MILES

PRIMARY  
IMPACT  
AREA

SEBEC DAM

USGS QUADRANGLE  
WILFORD, ME. 1954  
SCALE 1:125,000



at \_\_\_\_\_ Station \_\_\_\_\_

Job No. \_\_\_\_\_

Drawn by \_\_\_\_\_ Checked by \_\_\_\_\_ Date \_\_\_\_\_

| No. | Description       | Quantity | Unit   |
|-----|-------------------|----------|--------|
| 1   | Excavation        | 100      | cu yd  |
| 2   | Concrete          | 50       | cu yd  |
| 3   | Reinforcing Steel | 100      | lb     |
| 4   | Brick             | 1000     | bricks |
| 5   | Mortar            | 100      | cu yd  |
| 6   | Plaster           | 100      | sq yd  |
| 7   | Paint             | 100      | gal    |
| 8   | Roofing           | 100      | sq yd  |
| 9   | Insulation        | 100      | cu yd  |
| 10  | Foundation        | 100      | cu yd  |
| 11  | Structural Steel  | 100      | lb     |
| 12  | Roof Trusses      | 100      | lb     |
| 13  | Interior Finishes | 100      | sq yd  |
| 14  | Exterior Finishes | 100      | sq yd  |
| 15  | Sanitary Fixtures | 100      | units  |
| 16  | Plumbing          | 100      | units  |
| 17  | Electrical        | 100      | units  |
| 18  | HVAC              | 100      | units  |
| 19  | Landscaping       | 100      | sq yd  |
| 20  | Site Preparation  | 100      | sq yd  |

Location 11th St. N.Y.C. Job No. 11-1-11

Designed by J.M.S. Checked by J.M.S. Date 11-1-11

*[Handwritten notes on grid paper, including calculations and technical descriptions. The text is mostly illegible due to the quality of the scan and the cursive handwriting.]*

ion

by



Checked by

Date

*[Faint, illegible handwritten text, possibly a ledger or account book entry]*

Location W. 1st St. at 1st St. N. Wash. D.C. Job No. 101

Designed by J.W.S. Checked by J.W.S. Date 11-1-1917



Area of sewer =  $0.5 \times 0.5 = 0.25$  sq. ft.  
 Area of trench =  $0.5 \times 10 = 5$  sq. ft.  
 Area of concrete =  $0.5 \times 10 = 5$  sq. ft.

Volume of concrete =  $5 \times 10 = 50$  cu. ft.  
 Volume of trench =  $5 \times 10 = 50$  cu. ft.  
 Volume of sewer =  $0.25 \times 10 = 2.5$  cu. ft.


Cost of concrete =  $50 \times 0.15 = 7.50$   
 Cost of trench =  $50 \times 0.15 = 7.50$   
 Cost of sewer =  $2.5 \times 0.15 = 0.375$

Total cost =  $7.50 + 7.50 + 0.375 = 15.375$   
 Total cost = \$15.38


Approved: J.W.S.  
 Date: 11-1-1917



Location 100 ft. 100 ft. 100 ft. 100 ft. 100 ft.  
 Station 100 ft. 100 ft. 100 ft. 100 ft. 100 ft. Job No. 100-100-100  
 Elevation 100 ft. 100 ft. 100 ft. 100 ft. 100 ft. Checked by                      Date 11-21-20




| V  | A    | V   | V   | V   | V    | V    |
|----|------|-----|-----|-----|------|------|
| 10 | 1000 | 100 | 100 | 100 | 1000 | 1000 |
| 15 | 2250 | 150 | 225 | 225 | 2250 | 2250 |
| 20 | 4000 | 200 | 400 | 400 | 4000 | 4000 |
| 25 | 6250 | 250 | 625 | 625 | 6250 | 6250 |
| 30 | 9000 | 300 | 900 | 900 | 9000 | 9000 |



Project Sanitary Sewerage System for [unclear]

Location [unclear]

Designed by [unclear] Checked by [unclear] Date [unclear]



Project Imp. to M.F.A. 111  
 Location S.B.P. Job No. 111-1  
 Reported by W.V. Checked by W.V. Date 11-17


1. Imp. to M.F.A. 111

11. D. 111, 112, 113, 114, 115  
 Imp. to M.F.A. 111  
 M.F.A. 111, 112, 113, 114, 115  
 111-115

12. Imp. to M.F.A. 111  
 M.F.A. 111, 112, 113, 114, 115  
 111-115

13. Imp. to M.F.A. 111  
 M.F.A. 111, 112, 113, 114, 115  
 111-115

14. Imp. to M.F.A. 111  
 M.F.A. 111, 112, 113, 114, 115  
 111-115



15. Imp. to M.F.A. 111  
 M.F.A. 111, 112, 113, 114, 115  
 111-115

16. Imp. to M.F.A. 111  
 M.F.A. 111, 112, 113, 114, 115  
 111-115

17. Imp. to M.F.A. 111  
 M.F.A. 111, 112, 113, 114, 115  
 111-115


18. Imp. to M.F.A. 111  
 M.F.A. 111, 112, 113, 114, 115  
 111-115



Subject Improvement of New-Ford Dam

Computation Subs. Dam Job No. 958-01R

Computed by S.W. Checked by S.W. Date 11-20-25





Subject Imprestment of 100,000 B.C.

Computation of 100,000 B.C. Job No. 100,000 B.C.

Computed by C.W. Checked by C.W. Date 11-1-1911

(a)  $P = 100,000$   
 $r = 4\%$   
 $n = 10$

$$S = P \left( \frac{r}{1+r} \right)^n = 100,000 \left( \frac{.04}{1.04} \right)^{10} = 67,556.43$$

$$V_1 = 100,000 - 67,556.43 = 32,443.57$$

$$S_1 = \frac{32,443.57}{.96} = 33,795.49$$

$$S_2 = 33,795.49 \left( 1 + \frac{.04}{2} \right) = 35,211.11$$

$$S_3 = 35,211.11 \left( 1 + \frac{.04}{2} \right) = 36,697.14$$

$$S_4 = 36,697.14 \left( 1 + \frac{.04}{2} \right) = 38,254.82$$

$$S_5 = 38,254.82 \left( 1 + \frac{.04}{2} \right) = 39,884.41$$

$$S_6 = 39,884.41 \left( 1 + \frac{.04}{2} \right) = 41,586.49$$

$$S_7 = 41,586.49 \left( 1 + \frac{.04}{2} \right) = 43,361.64$$

$$S_8 = 43,361.64 \left( 1 + \frac{.04}{2} \right) = 45,210.49$$

$$S_9 = 45,210.49 \left( 1 + \frac{.04}{2} \right) = 47,133.64$$

$$S_{10} = 47,133.64 \left( 1 + \frac{.04}{2} \right) = 49,131.79$$

and  $P = 100,000$   
 $S_{10} = 49,131.79$   
 $100,000 - 49,131.79 = 50,868.21$

that is, the balance at the end of 10 years is \$50,868.21

or  $50.86821\%$  of the original amount.






Subject I. J. Taylor & Co. Sewerage System

Computation S. L. De Job No. 242-101-F


Computed by S. L. De Checked by J. W. S. Date 11-26-1917



Subject Flow in Pipe

Computation S. L. D. Job No. 11-2-57

Computed by SL Checked by SL Date 11-2-57



For  $y \geq 15$ ,  $T = 0.0175 \sqrt{y}$   
 Flow in pipe,  $T = 0.0175 \sqrt{y}$   
 $T = 0.0175 \sqrt{15} = 0.0675$   
 $T = 0.0675$

$$L = 100 \times 75 - (0.6 - 0) - 1 = 75 + 0.7 = 143$$

$$H = 11 - (0.6 - 0) - 0 = 10.4$$

$$V = 11 - 7 - (0.6 - 0) = 2.8$$

Flow in pipe

$$Q = 11 \times 100 = 1100$$

$$11 - 7 - (0.6 - 0) = 2.8$$

$$11 - 7 = 4$$

$$11 - 7 = 4$$

$$11 - 7 = 4$$

$$11 - 7 = 4$$

$$11 - 7 = 4$$

$$11 - 7 = 4$$

$$11 - 7 = 4$$

$$11 - 7 = 4$$

$$11 - 7 = 4$$

Subject Flow in Pipe

Computation 1. Friction Loss Job No. 457-100-R

Computed by S. J. Checked by J. W. Date 11-1-20

1. Friction Loss in Pipe  
Friction Loss in Pipe =  $f \cdot L \cdot \frac{V^2}{2g \cdot D}$   
Friction Loss in Pipe =  $0.02 \cdot 100 \cdot \frac{10^2}{2 \cdot 32.2 \cdot 1}$   
Friction Loss in Pipe = 3.11 ft  
Friction Loss in Pipe = 0.95 m

2. Friction Loss in Pipe  
Friction Loss in Pipe =  $f \cdot L \cdot \frac{V^2}{2g \cdot D}$   
Friction Loss in Pipe =  $0.02 \cdot 100 \cdot \frac{10^2}{2 \cdot 32.2 \cdot 1}$   
Friction Loss in Pipe = 3.11 ft  
Friction Loss in Pipe = 0.95 m

3. Friction Loss in Pipe  
Friction Loss in Pipe =  $f \cdot L \cdot \frac{V^2}{2g \cdot D}$   
Friction Loss in Pipe =  $0.02 \cdot 100 \cdot \frac{10^2}{2 \cdot 32.2 \cdot 1}$   
Friction Loss in Pipe = 3.11 ft  
Friction Loss in Pipe = 0.95 m

4. Friction Loss in Pipe  
Friction Loss in Pipe =  $f \cdot L \cdot \frac{V^2}{2g \cdot D}$   
Friction Loss in Pipe =  $0.02 \cdot 100 \cdot \frac{10^2}{2 \cdot 32.2 \cdot 1}$   
Friction Loss in Pipe = 3.11 ft  
Friction Loss in Pipe = 0.95 m

5. Friction Loss in Pipe  
Friction Loss in Pipe =  $f \cdot L \cdot \frac{V^2}{2g \cdot D}$   
Friction Loss in Pipe =  $0.02 \cdot 100 \cdot \frac{10^2}{2 \cdot 32.2 \cdot 1}$   
Friction Loss in Pipe = 3.11 ft  
Friction Loss in Pipe = 0.95 m

6. Friction Loss in Pipe  
Friction Loss in Pipe =  $f \cdot L \cdot \frac{V^2}{2g \cdot D}$   
Friction Loss in Pipe =  $0.02 \cdot 100 \cdot \frac{10^2}{2 \cdot 32.2 \cdot 1}$   
Friction Loss in Pipe = 3.11 ft  
Friction Loss in Pipe = 0.95 m

7. Friction Loss in Pipe  
Friction Loss in Pipe =  $f \cdot L \cdot \frac{V^2}{2g \cdot D}$   
Friction Loss in Pipe =  $0.02 \cdot 100 \cdot \frac{10^2}{2 \cdot 32.2 \cdot 1}$   
Friction Loss in Pipe = 3.11 ft  
Friction Loss in Pipe = 0.95 m

8. Friction Loss in Pipe  
Friction Loss in Pipe =  $f \cdot L \cdot \frac{V^2}{2g \cdot D}$   
Friction Loss in Pipe =  $0.02 \cdot 100 \cdot \frac{10^2}{2 \cdot 32.2 \cdot 1}$   
Friction Loss in Pipe = 3.11 ft  
Friction Loss in Pipe = 0.95 m


9. Friction Loss in Pipe  
Friction Loss in Pipe =  $f \cdot L \cdot \frac{V^2}{2g \cdot D}$   
Friction Loss in Pipe =  $0.02 \cdot 100 \cdot \frac{10^2}{2 \cdot 32.2 \cdot 1}$   
Friction Loss in Pipe = 3.11 ft  
Friction Loss in Pipe = 0.95 m

10. Friction Loss in Pipe  
Friction Loss in Pipe =  $f \cdot L \cdot \frac{V^2}{2g \cdot D}$   
Friction Loss in Pipe =  $0.02 \cdot 100 \cdot \frac{10^2}{2 \cdot 32.2 \cdot 1}$   
Friction Loss in Pipe = 3.11 ft  
Friction Loss in Pipe = 0.95 m

Subject Water Supply

Computation for 1000 people

Computed by James W. Seidle Checked by \_\_\_\_\_ Date 12/1/1911



Subject \_\_\_\_\_

Computation \_\_\_\_\_

Computed by \_\_\_\_\_ Checked by \_\_\_\_\_ Date \_\_\_\_\_


| Station | Angle | Distance | Latitude | Longitude | Remarks |
|---------|-------|----------|----------|-----------|---------|
| 1       |       |          |          |           |         |
| 2       |       |          |          |           |         |
| 3       |       |          |          |           |         |
| 4       |       |          |          |           |         |
| 5       |       |          |          |           |         |
| 6       |       |          |          |           |         |
| 7       |       |          |          |           |         |
| 8       |       |          |          |           |         |
| 9       |       |          |          |           |         |
| 10      |       |          |          |           |         |
| 11      |       |          |          |           |         |
| 12      |       |          |          |           |         |
| 13      |       |          |          |           |         |
| 14      |       |          |          |           |         |
| 15      |       |          |          |           |         |
| 16      |       |          |          |           |         |
| 17      |       |          |          |           |         |
| 18      |       |          |          |           |         |
| 19      |       |          |          |           |         |
| 20      |       |          |          |           |         |
| 21      |       |          |          |           |         |
| 22      |       |          |          |           |         |
| 23      |       |          |          |           |         |
| 24      |       |          |          |           |         |
| 25      |       |          |          |           |         |
| 26      |       |          |          |           |         |
| 27      |       |          |          |           |         |
| 28      |       |          |          |           |         |
| 29      |       |          |          |           |         |
| 30      |       |          |          |           |         |
| 31      |       |          |          |           |         |
| 32      |       |          |          |           |         |
| 33      |       |          |          |           |         |
| 34      |       |          |          |           |         |
| 35      |       |          |          |           |         |
| 36      |       |          |          |           |         |
| 37      |       |          |          |           |         |
| 38      |       |          |          |           |         |
| 39      |       |          |          |           |         |
| 40      |       |          |          |           |         |
| 41      |       |          |          |           |         |
| 42      |       |          |          |           |         |
| 43      |       |          |          |           |         |
| 44      |       |          |          |           |         |
| 45      |       |          |          |           |         |
| 46      |       |          |          |           |         |
| 47      |       |          |          |           |         |
| 48      |       |          |          |           |         |
| 49      |       |          |          |           |         |
| 50      |       |          |          |           |         |
| 51      |       |          |          |           |         |
| 52      |       |          |          |           |         |
| 53      |       |          |          |           |         |
| 54      |       |          |          |           |         |
| 55      |       |          |          |           |         |
| 56      |       |          |          |           |         |
| 57      |       |          |          |           |         |
| 58      |       |          |          |           |         |
| 59      |       |          |          |           |         |
| 60      |       |          |          |           |         |
| 61      |       |          |          |           |         |
| 62      |       |          |          |           |         |
| 63      |       |          |          |           |         |
| 64      |       |          |          |           |         |
| 65      |       |          |          |           |         |
| 66      |       |          |          |           |         |
| 67      |       |          |          |           |         |
| 68      |       |          |          |           |         |
| 69      |       |          |          |           |         |
| 70      |       |          |          |           |         |
| 71      |       |          |          |           |         |
| 72      |       |          |          |           |         |
| 73      |       |          |          |           |         |
| 74      |       |          |          |           |         |
| 75      |       |          |          |           |         |
| 76      |       |          |          |           |         |
| 77      |       |          |          |           |         |
| 78      |       |          |          |           |         |
| 79      |       |          |          |           |         |
| 80      |       |          |          |           |         |
| 81      |       |          |          |           |         |
| 82      |       |          |          |           |         |
| 83      |       |          |          |           |         |
| 84      |       |          |          |           |         |
| 85      |       |          |          |           |         |
| 86      |       |          |          |           |         |
| 87      |       |          |          |           |         |
| 88      |       |          |          |           |         |
| 89      |       |          |          |           |         |
| 90      |       |          |          |           |         |
| 91      |       |          |          |           |         |
| 92      |       |          |          |           |         |
| 93      |       |          |          |           |         |
| 94      |       |          |          |           |         |
| 95      |       |          |          |           |         |
| 96      |       |          |          |           |         |
| 97      |       |          |          |           |         |
| 98      |       |          |          |           |         |
| 99      |       |          |          |           |         |
| 100     |       |          |          |           |         |



Subject Water Supply

Computation 1917 Job No. 100

Computed by J. S. Checked by J. S. Date 1917







Subject Water Supply for the Town of...

Computation for the year 1911 Job No. 101

Computed by J. W. Sewell Checked by J. W. Sewell Date 11-1-11

| Item | Description                     | Quantity | Unit | Price | Total   |
|------|---------------------------------|----------|------|-------|---------|
| 1    | Water supply for the town of... | 1000     | gals | 0.10  | 100.00  |
| 2    | Water supply for the town of... | 2000     | gals | 0.10  | 200.00  |
| 3    | Water supply for the town of... | 3000     | gals | 0.10  | 300.00  |
| 4    | Water supply for the town of... | 4000     | gals | 0.10  | 400.00  |
| 5    | Water supply for the town of... | 5000     | gals | 0.10  | 500.00  |
| 6    | Water supply for the town of... | 6000     | gals | 0.10  | 600.00  |
| 7    | Water supply for the town of... | 7000     | gals | 0.10  | 700.00  |
| 8    | Water supply for the town of... | 8000     | gals | 0.10  | 800.00  |
| 9    | Water supply for the town of... | 9000     | gals | 0.10  | 900.00  |
| 10   | Water supply for the town of... | 10000    | gals | 0.10  | 1000.00 |
| 11   | Water supply for the town of... | 11000    | gals | 0.10  | 1100.00 |
| 12   | Water supply for the town of... | 12000    | gals | 0.10  | 1200.00 |
| 13   | Water supply for the town of... | 13000    | gals | 0.10  | 1300.00 |
| 14   | Water supply for the town of... | 14000    | gals | 0.10  | 1400.00 |
| 15   | Water supply for the town of... | 15000    | gals | 0.10  | 1500.00 |
| 16   | Water supply for the town of... | 16000    | gals | 0.10  | 1600.00 |
| 17   | Water supply for the town of... | 17000    | gals | 0.10  | 1700.00 |
| 18   | Water supply for the town of... | 18000    | gals | 0.10  | 1800.00 |
| 19   | Water supply for the town of... | 19000    | gals | 0.10  | 1900.00 |
| 20   | Water supply for the town of... | 20000    | gals | 0.10  | 2000.00 |
| 21   | Water supply for the town of... | 21000    | gals | 0.10  | 2100.00 |
| 22   | Water supply for the town of... | 22000    | gals | 0.10  | 2200.00 |
| 23   | Water supply for the town of... | 23000    | gals | 0.10  | 2300.00 |
| 24   | Water supply for the town of... | 24000    | gals | 0.10  | 2400.00 |
| 25   | Water supply for the town of... | 25000    | gals | 0.10  | 2500.00 |
| 26   | Water supply for the town of... | 26000    | gals | 0.10  | 2600.00 |
| 27   | Water supply for the town of... | 27000    | gals | 0.10  | 2700.00 |
| 28   | Water supply for the town of... | 28000    | gals | 0.10  | 2800.00 |
| 29   | Water supply for the town of... | 29000    | gals | 0.10  | 2900.00 |
| 30   | Water supply for the town of... | 30000    | gals | 0.10  | 3000.00 |
| 31   | Water supply for the town of... | 31000    | gals | 0.10  | 3100.00 |
| 32   | Water supply for the town of... | 32000    | gals | 0.10  | 3200.00 |
| 33   | Water supply for the town of... | 33000    | gals | 0.10  | 3300.00 |
| 34   | Water supply for the town of... | 34000    | gals | 0.10  | 3400.00 |
| 35   | Water supply for the town of... | 35000    | gals | 0.10  | 3500.00 |
| 36   | Water supply for the town of... | 36000    | gals | 0.10  | 3600.00 |
| 37   | Water supply for the town of... | 37000    | gals | 0.10  | 3700.00 |
| 38   | Water supply for the town of... | 38000    | gals | 0.10  | 3800.00 |
| 39   | Water supply for the town of... | 39000    | gals | 0.10  | 3900.00 |
| 40   | Water supply for the town of... | 40000    | gals | 0.10  | 4000.00 |
| 41   | Water supply for the town of... | 41000    | gals | 0.10  | 4100.00 |
| 42   | Water supply for the town of... | 42000    | gals | 0.10  | 4200.00 |
| 43   | Water supply for the town of... | 43000    | gals | 0.10  | 4300.00 |
| 44   | Water supply for the town of... | 44000    | gals | 0.10  | 4400.00 |
| 45   | Water supply for the town of... | 45000    | gals | 0.10  | 4500.00 |
| 46   | Water supply for the town of... | 46000    | gals | 0.10  | 4600.00 |
| 47   | Water supply for the town of... | 47000    | gals | 0.10  | 4700.00 |
| 48   | Water supply for the town of... | 48000    | gals | 0.10  | 4800.00 |
| 49   | Water supply for the town of... | 49000    | gals | 0.10  | 4900.00 |
| 50   | Water supply for the town of... | 50000    | gals | 0.10  | 5000.00 |



Subject Water Supply for Mill Pond

Computation 10/1/00 Job No. 1000

Computed by C. W. S. Checked by C. W. S. Date 11/1/00

| Station | Flow | Area | Velocity | Time | Distance | Volume  |
|---------|------|------|----------|------|----------|---------|
| 1       | 100  | 100  | 10       | 10   | 1000     | 10000   |
| 2       | 200  | 200  | 20       | 20   | 4000     | 40000   |
| 3       | 300  | 300  | 30       | 30   | 9000     | 90000   |
| 4       | 400  | 400  | 40       | 40   | 16000    | 160000  |
| 5       | 500  | 500  | 50       | 50   | 25000    | 250000  |
| 6       | 600  | 600  | 60       | 60   | 36000    | 360000  |
| 7       | 700  | 700  | 70       | 70   | 49000    | 490000  |
| 8       | 800  | 800  | 80       | 80   | 64000    | 640000  |
| 9       | 900  | 900  | 90       | 90   | 81000    | 810000  |
| 10      | 1000 | 1000 | 100      | 100  | 100000   | 1000000 |





PRELIMINARY GUIDANCE  
FOR ESTIMATING  
MAXIMUM PROBABLE DISCHARGES  
IN  
PHASE I DAM SAFETY  
INVESTIGATIONS

New England Division  
Corps of Engineers

March 1978

WATER PRODUCTION FROM WELLS  
IN RES. WRS.


| <u>Project</u>        | <u>Q</u><br><u>(cfs)</u> | <u>B.A.</u><br><u>(sq. mi.)</u> | <u>MP</u><br><u>cfs/sq. mi.</u> |
|-----------------------|--------------------------|---------------------------------|---------------------------------|
| 1. Hall Meadow Brook  | 28,000                   | 17.2                            | 1,546                           |
| 2. East Branch        | 15,500                   | 9.25                            | 1,675                           |
| 3. Thompson           | 158,000                  | 87.2                            | 1,625                           |
| 4. Northfield Brook   | 9,000                    | 5.7                             | 1,580                           |
| 5. Black Rock         | 25,000                   | 20.4                            | 1,715                           |
| 6. Hancock Brook      | 20,700                   | 12.0                            | 1,725                           |
| 7. Hep Brook          | 25,400                   | 16.4                            | 1,610                           |
| 8. Tully              | 47,000                   | 50.0                            | 940                             |
| 9. Parre Falls        | 61,000                   | 55.0                            | 1,109                           |
| 10. Conant Brook      | 11,900                   | 7.8                             | 1,525                           |
| 11. Knightville       | 160,000                  | 162.0                           | 987                             |
| 12. Littleville       | 98,000                   | 52.3                            | 1,870                           |
| 13. Colebrook River   | 165,000                  | 118.0                           | 1,400                           |
| 14. Mad River         | 30,000                   | 18.2                            | 1,650                           |
| 15. Sucker Brook      | 6,500                    | 3.43                            | 1,895                           |
| 16. Union Village     | 110,000                  | 126.0                           | 873                             |
| 17. North Hartland    | 199,000                  | 220.0                           | 904                             |
| 18. North Springfield | 157,000                  | 158.0                           | 994                             |
| 19. Ball Mountain     | 190,000                  | 172.0                           | 1,105                           |
| 20. Townshend         | 228,000                  | 106.0(278 total)                | 820                             |
| 21. Surry Mountain    | 63,000                   | 100.0                           | 630                             |
| 22. Otter Brook       | 45,000                   | 47.0                            | 957                             |
| 23. Birch Hill        | 88,500                   | 175.0                           | 505                             |
| 24. East Brimfield    | 73,900                   | 67.5                            | 1,095                           |
| 25. Westville         | 38,400                   | 99.5(32 net)                    | 1,200                           |
| 26. West Thompson     | 85,000                   | 173.5(74 net)                   | 1,150                           |
| 27. Ledges Village    | 38,800                   | 31.1                            | 1,145                           |
| 28. Buffumville       | 38,500                   | 26.5                            | 1,377                           |
| 29. Mansfield Hollow  | 128,000                  | 159.0                           | 786                             |
| 30. West Hill         | 26,000                   | 28.0                            | 928                             |
| 31. Franklin Falls    | 210,000                  | 1000.0                          | 210                             |
| 32. Blackwater        | 65,500                   | 128.0                           | 520                             |
| 33. Hopkinton         | 138,000                  | 420.0                           | 316                             |
| 34. Everett           | 65,000                   | 64.0                            | 1,062                           |
| 35. Middlebury        | 55,000                   | 44.0                            | 1,250                           |

WATER FLOW MEASUREMENTS  
MADE AT THE  
STATIONARY POINTS  
(1900 and 1901)

| <u>River</u>            | <u>CFD</u><br><u>(cfs)</u> | <u>D.A.</u><br><u>(sq. ft.)</u> | <u>CFD</u><br><u>(cfs/sq. ft.)</u> |
|-------------------------|----------------------------|---------------------------------|------------------------------------|
| 1. Pawtucket River      | 19,000                     | 200                             | 190                                |
| 2. Mill River (R.I.)    | 7,500                      | 34                              | 500                                |
| 3. Peters River (R.I.)  | 3,200                      | 13                              | 490                                |
| 4. Kettle Brook         | 8,000                      | 30                              | 530                                |
| 5. Sudbury River.       | 11,700                     | 35                              | 270                                |
| 6. Indian Brook (Vepk.) | 1,000                      | 5.9                             | 340                                |
| 7. Charles River.       | 6,000                      | 184                             | 65                                 |
| 8. Blackstone River.    | 43,000                     | 416                             | 200                                |
| 9. Quinebaug River      | 55,000                     | 331                             | 330                                |



# ESTIMATING EFFECT OF SURCHARGE STORAGE ON MAXIMUM PROBABLE FLOOD RUNOFFS



EP 1: Determine Peak Inflow ( $Q_{p1}$ ) from Guide Curves.

- EP 2: a. Determine Surcharge Height To Pass " $Q_{p1}$ ".  
 b. Determine Volume of Surcharge (STOR<sub>1</sub>) In Inches of Runoff.  
 c. Maximum Probable Flood Runoff In New England equals Approx. 19", Therefore

$$Q_{p2} = Q_{p1} \times \left(1 - \frac{STOR_1}{19}\right)$$

- EP 3: a. Determine Surcharge Height and " $STOR_2$ " To Pass " $Q_{p2}$ ".  
 b. Average " $STOR_1$ " and " $STOR_2$ " and Determine Average Surcharge and Resulting Peak Outflow " $Q_{p3}$ ".

MAXIMUM PROBABLE FLOOD  
PEAK FLOW RATES

X5 - NED DAM IDENTIFICATION  
 ⊗ 7' - TWICE SPF AT INDICATED SITES  
 DEC. 1977



AD-A155 796

NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS  
SEBEC DAM NE 00163 PE... (U) CORPS OF ENGINEERS WALTHAM  
HA NEW ENGLAND DIV JUN 81

2/2

UNCLASSIFIED

F/G 13/13


NL

END

FILED


+

DTIC



MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A

# "RULE OF THUMB" GUIDANCE FOR ESTIMATING DOWNSTREAM DAM FAILURE HYDROGRAPHS



**STEP 1:** DETERMINE OR ESTIMATE RESERVOIR STORAGE (S) IN AC-FT AT TIME OF FAILURE.

**STEP 2:** DETERMINE PEAK FAILURE OUTFLOW ( $Q_{p1}$ ).

$$Q_{p1} = \frac{8}{27} W_b \sqrt{9} Y_0^{3/2}$$

$W_b$  = BREACH WIDTH - SUGGEST VALUE NOT GREATER THAN 40% OF DAM LENGTH ACROSS RIVER AT MID HEIGHT.

$Y_0$  = TOTAL HEIGHT FROM RIVER BED TO POOL LEVEL AT FAILURE.

**STEP 3:** USING USGS TOPO OR OTHER DATA, DEVELOP REPRESENTATIVE STAGE-DISCHARGE RATING FOR SELECTED DOWNSTREAM RIVER REACH.

**STEP 4:** ESTIMATE REACH OUTFLOW ( $Q_{p2}$ ) USING FOLLOWING ITERATION.

A. APPLY  $Q_{p1}$  TO STAGE RATING, DETERMINE STAGE AND ACCOMPANYING VOLUME ( $V_1$ ) IN REACH IN AC-FT. (NOTE: IF  $V_1$  EXCEEDS  $1/2$  OF S, SELECT SHORTER REACH.)

B. DETERMINE TRIAL  $Q_{p2}$ :

$$Q_{p2}(\text{TRIAL}) = Q_{p1} \left(1 - \frac{V_1}{S}\right)$$

C. COMPUTE  $V_2$  USING  $Q_{p2}$  (TRIAL).

D. AVERAGE  $V_1$  AND  $V_2$  AND COMPUTE  $Q_{p2}$ .

$$Q_{p2} = Q_{p1} \left(1 - \frac{V_{\text{avg}}}{S}\right)$$

**STEP 5:** FOR SUCCEEDING REACHES REPEAT STEPS 3 AND 4.

APRIL 1978

APPENDIX E  
INFORMATION AS CONTAINED IN  
THE NATIONAL INVENTORY OF DAMS

NOT AVAILABLE AT THIS TIME

**END**

**FILMED**

**8-85**

**DTIC**