

AD-A156 019


NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS
JAMES V TURNER DAM (R. (U) CORPS OF ENGINEERS WALTHAM
MA NEW ENGLAND DIV JAN 81


1/2

UNCLASSIFIED

F/G 13/13

NL





MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A

AD-A156 019

DTIC ACCESSION NUMBER

21

LEVEL

PHOTOGRAPH THIS SHEET

1

INVENTORY

JAMES V TURNER DA111

DOCUMENT IDENTIFICATION
JAN 1981

RI 01002

This document is approved for public release and distribution as indicated.

DISTRIBUTION STATEMENT

ACCESSION FOR

NTIS GRA&I

DTIC TAB

UNANNOUNCED

JUSTIFICATION

BY

DISTRIBUTION /

AVAILABILITY CODES

DIST

AVAIL AND/OR SPECIAL

A-1

DISTRIBUTION STAMP

DTIC
SELECTED
JUL 05 1985
S E D

DATE ACCESSIONED

DATE RETURNED

85 7 03 066

DATE RECEIVED IN DTIC

REGISTERED OR CERTIFIED NO.

PHOTOGRAPH THIS SHEET AND RETURN TO DTIC-DDAC

AD-A156 019

MASTER

NARRAGANSETT BAY BASIN
EAST PROVIDENCE, RHODE ISLAND
JAMES V. TURNER DAM
RI 01002

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
WALTHAM, MASS. 02154

JANUARY 1981

DISCLAIMER NOTICE

**THIS DOCUMENT IS BEST QUALITY
PRACTICABLE. THE COPY FURNISHED
TO DTIC CONTAINED A SIGNIFICANT
NUMBER OF PAGES WHICH DO NOT
REPRODUCE LEGIBLY.**

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER RI 01002	2. GOVT ACCESSION NO. AD-A156 019	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) James V. Turner Dam NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS		5. TYPE OF REPORT & PERIOD COVERED INSPECTION REPORT
7. AUTHOR(s) U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS		8. CONTRACT OR GRANT NUMBER(s)
11. CONTROLLING OFFICE NAME AND ADDRESS DEPT. OF THE ARMY, CORPS OF ENGINEERS NEW ENGLAND DIVISION, NEDED 424 TRAPELO ROAD, WALTHAM, MA. 02254		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		12. REPORT DATE January 1981
		13. NUMBER OF PAGES 63
16. DISTRIBUTION STATEMENT (of this Report) APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Cover program reads: Phase I Inspection Report, National Dam Inspection Program; however, the official title of the program is: National Program for Inspection of Non-Federal Dams; use cover date for date of report.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) DAMS, INSPECTION, DAM SAFETY, Narragansett Bay Basin East Providence, Rhode Island Ten Mile River		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) The dam is 22 ft. high and 820 ft. long. The dam is judged to be in fair condition. There are items which require maintenance or evaluation. The dam is intermediate in size with a high hazard potential. There are various recommendations which must be implemented by the owner.		



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
424 TRAPELO ROAD
WALTHAM, MASSACHUSETTS 02254

REPLY TO
ATTENTION OF:

NEDED-E

JUN 15 1981

Honorable J. Joseph Garrahy
Governor of the State of Rhode Island
State House
Providence, Rhode Island 02903

Dear Governor Garrahy:

Inclosed is a copy of the James V. Turner Dam (RI-01002) Phase I Inspection Report, which was prepared under the National Program for Inspection of Non-Federal Dams. The report is based upon a visual inspection, a review of past performance, and a preliminary hydrological analysis. A brief assessment is included at the beginning of the report.

The preliminary hydrologic analysis has indicated that the spillway capacity for the James V. Turner Dam would likely be exceeded by floods greater than 37 percent of the Probable Maximum Flood (PMF). Our screening criteria specifies that a dam of this class which does not have sufficient spillway capacity to discharge fifty percent of the PMF, should be adjudged as having a seriously inadequate spillway and the dam assessed as unsafe, non-emergency, until more detailed studies prove otherwise or corrective measures are completed.

The term "unsafe" applied to a dam because of an inadequate spillway does not indicate the same degree of emergency as that term would if applied because of structural deficiency. It does indicate, however, that a severe storm may cause overtopping and possible failure of the dam, with significant damage and potential loss of life downstream.

It is recommended that within twelve months from the date of this report the owner of the dam engage the services of a professional or consulting engineer to determine by more sophisticated methods and procedures the magnitude of the spillway deficiency. Based on this determination, appropriate remedial mitigating measures should be designed and completed within 24 months of this date of notification. In the interim a detailed emergency operation plan and warning system should be promptly developed. During periods of unusually heavy precipitation, round-the-clock surveillance should be provided.

NEDED-E

Honorable J. Joseph Garrahy

I have approved the report and support the findings and recommendations described in Section 7, with qualifications as noted above. I request that you keep me informed of the actions taken to implement these recommendations since this follow-up is an important part of the non-Federal Dam Inspection Program.

A copy of this report has been forwarded to the Department of Environmental Management, the cooperating agency for the State of Rhode Island. This report has also been furnished to the owner of the project, East Providence Water Works, Rumford, RI.

Copies of this report will be made available to the public, upon request to this office, under the Freedom of Information Act, thirty days from the date of this letter.

I wish to take this opportunity to thank you and the Department of Environmental Management for the cooperation extended in carrying out this program.

Sincerely,



C. E. EDGAR, III
Colonel, Corps of Engineers
Division Engineer

NARRAGANSETT BAY BASIN
EAST PROVIDENCE, RHODE ISLAND
JAMES V. TURNER DAM
RI 01002

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
WALTHAM, MASS. 02154

JANUARY 1981

BRIEF ASSESSMENT

PHASE I INSPECTION REPORT

NATIONAL PROGRAM OF INSPECTION OF DAMS

Name of Dam: JAMES V. TURNER DAM
Inventory Number: RI 01002
State: RHODE ISLAND
County: PROVIDENCE
Town: EAST PROVIDENCE
Stream: TEN MILE RIVER
Owner: EAST PROVIDENCE WATER WORKS
Date of Inspection: OCTOBER 8, 1980 and NOVEMBER 20, 1980
Inspection Team: PETER HEYNEN, P.E.
HECTOR MORENO, P.E.
TIMOTHY KAVANAUGH
FRANK SEGALINE
THEODORE STEVENS


The James V. Turner Dam was constructed in 1934 to impound a public water supply reservoir, but the reservoir is no longer used for this purpose. The entire project consists of an approximately 22 foot high earth embankment dam and several small dikes and berms around the reservoir. The dam is approximately 820 feet long and includes a 200 foot long concrete spillway and a concrete outlet structure. The spillway crest is 5 feet below the top of the dam, and with the reservoir level to the top of the dam, approximately 3100 acre-feet of water is impounded. Two 54 inch low-level outlets are located at the bottom of the outlet structure to the right of the spillway. An abandoned brick gatehouse located at the top of the outlet structure contains two manually operated lifts which operate the low-level outlets and a third lift which operates a sluice gate to a 66 inch raw water supply line to an abandoned filtration plant about 2600 feet downstream of the dam. Adjacent to the right end of the dam is the west dike, which is a 6 foot high, 730 foot long earth embankment. Two small dikes on the east shoreline and a berm on the west shoreline of the reservoir do not prevent water from flowing out of the reservoir to another water-course. They appear to have been constructed mainly to provide access to portions of the reservoir shoreline and to a buried storm sewer line around the reservoir.

Based upon the visual inspection at the site and past performance, the project is judged to be in fair condition. There are items which require maintenance and/or evaluation, such as the inaccessibility of the gatehouse, brush and trees growing on the embankments and at the abutments, erosion of areas of the dam, presence of animal burrows in the embankments, and cracks and deterioration of the concrete.



In accordance with the Army Corps of Engineer's Guidelines, James V. Turner Reservoir Dam is classified as a high hazard, intermediate size dam. The test flood for Turner Reservoir Dam is the Probable Maximum Flood (PMF). Peak inflow to the reservoir at PMF is 24,000 cubic feet per second (cfs); peak outflow is 22,600 cfs with the dam overtopped by 2.0 feet. The spillway capacity with the reservoir level to the top of the dam is 8300 cfs, which is equivalent to 37% of the routed test flood outflow.

It is recommended that the owner retain the services of a registered professional engineer qualified in dam design and inspection to perform further studies as presented in Section 7.2. These include a more detailed analysis of the project discharge capacity, repair of the concrete training walls, removal of trees from the embankments, restoration of the outlet facilities and an evaluation of the condition of the spillway and downstream channel. Recommendations made by the engineer and should be implemented by the owner.


The above recommendations and further remedial measures presented in Section 7.3 should be instituted within one year of the owner's receipt of this report.




Peter M. Heynen, P.E.
Project Manager - Geotechnical
Cahn Engineers, Inc.




C. Michael Horton P.E.
Chief Engineer
Cahn Engineers, Inc.



This Phase I Inspection Report on James V. Turner Reservoir Dam has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the Recommended Guidelines for Safety Inspection of Dams, and with good engineering judgement and practice, and is hereby submitted for approval.



CARNEY M. TERZIAN, MEMBER
Design Branch
Engineering Division




JOSEPH W. FINEGAN, JR., MEMBER
Water Control Branch
Engineering Division



ARAMAST MAHTESIAN, CHAIRMAN
Geotechnical Engineering Branch
Engineering Division

APPROVAL RECOMMENDED:



JOE B. FRYAR
Chief, Engineering Division

The information contained in this report is based on the limited investigation described above and is not warranted to indicate the actual condition of the dam. The integrity of the dam can only be determined by a means of a monitoring program and/or a detailed physical investigation. The accuracy of available data is assumed where not in obvious conflict with facts observable during the visual inspection.

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspection. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I Investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam would necessarily represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions will be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test Flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

The Phase I Investigation does not include an assessment of the need for fences, gates, no-trespassing signs, repairs to existing fences and railings and other items which may be needed to minimize trespass and provide greater security for the facility and safety to the public. An evaluation of the project for compliance with OSHA rules and regulations is also excluded.

SECTION 2: ENGINEERING DATA

2.1 DESIGN DATA

Available data consists of original drawings, entitled East Providence Reservoir, Contract 1, by Waterman Engineering Company dated March 1934, data sheet dated June 30, 1949, dam inspection report dated Sept. 20, 1978, a summary of run-off data prepared by the East Providence Water Company beginning in May 1922 until June 1927 and a dam inventory report.

The drawings and correspondence indicate the design features stated previously in this report. There were no engineering values, assumptions, test results or calculations available for the original dam design.

2.2 CONSTRUCTION DATA

There is no data available for the original construction of the dam other than the run-off data stated in 2.1.

2.3 OPERATIONS DATA

The reservoir was abandoned as a public water supply in 1970 because of poor water quality. Since that time, there has been no operational procedures followed at the dam.

2.4 EVALUATION OF DATA

a. Availability - Existing data was provided by the State of Rhode Island Department of Environmental Management. The owner made the project available for visual inspection.

b. Adequacy - There was no detailed engineering data available; therefore, the final assessment of this project must be based on visual inspection, performance history, hydraulic computations of spillway capacity, and hydrologic judgements.

c. Validity - A comparison of record data and visual observations reveals that the East Dikes were not built according to plan. The designed top elevations of East Dike No. 1 and East Dike No. 2 were 51.0 and 50.0 respectively, but field measurements indicate that the top elevation of each is approximately 48.0.

1. Invert:	Low-level outlets:	el. 29.5
	Supply main (at inlet):	el. 32.25
2. Size:	Low-level outlets	54 inch (2 low-level outlets)
	Supply main	66 inch
3. Description:	Low-level outlets	Unknown
	Supply main	Unknown
4. Control mechanism:		manually operated sluice gates
5. Other:		N/A

4. Top width:
- Dam and dikes 15+ ft.
5. Side slopes:
- Earth Dam 3H to 1V (Upstream)
4H to 1V (Downstream)
- West dike 3H to 1V (Upstream)
1.5H to 1V (Downstream)
- East dike #1 3H to 1V (Upstream)
Variable (Downstream)
- East dike 2 3H to 1V (Upstream and
downstream)
6. Zoning: N/A
7. Impervious core: Concrete corewall (Earth
dam only)
8. Cutoff: Steel sheet-piling
(Earth dam only)
9. Grout curtain: N/A
10. Other: N/A
- h. Diversion and Regulating Tunnel - N/A
- i. Spillway
1. Type: Ogee
2. Length of weir: 200 ft.
3. Crest elevation: 46.0
4. Gates: N/A
5. Upstream channel: N/A
6. Downstream channel: 30+ ft. concrete stilling
pool
50+ ft. stone pavement
channel
1200+ ft. unpaved channel
7. General: N/A
- j. Regulating Outlets
- 2 - 54 inch low-level outlets Considered abandoned at
1 - 66 inch supply main time of the inspection

4. Top of dam pool:	12,000+ ft.
5. Test flood pool:	12,300+ ft.
e. <u>Reservoir Storage</u>	
1. Normal pool:	1300 acre-ft.
2. Flood control pool:	N/A
3. Spillway crest pool:	1300 acre-ft.
4. Top of dam pool:	3100 acre-ft.
5. Test flood pool:	4100 acre-ft.
f. <u>Reservoir Surface</u>	
1. Normal pool:	275 acres
2. Flood control pool:	N/A
3. Spillway crest pool:	275 acres
4. Top of dam pool:	390 acres
5. Test flood pool:	460 acres
g. <u>Dam and Dikes</u>	
1. Type:	
Dam	
Left of spillway	Earth embankment
Right of spillway	Concrete gravity and earth fill
Dikes	
West dike	Earth embankment
East dike #1	Earth embankment
East dike #2	Earth embankment
2. Length:	
Dam	
West dike	820+ ft.
East dike #1	730+ ft.
East dike #2	550+ ft.
	350+ ft.
3. Height:	
Dam	
West dike	22.0 ft.
East dike #1	6+ ft.
East dike #2	2+ ft.
	2+ ft.

4. Ungated spillway capacity @ test flood el. 53.0:	13,700 cfs
5. Gated spillway capacity @ normal pool:	N/A
6. Gated spillway capacity @ test flood:	N/A
7. Total spillway capacity @ test flood el. 53.0:	13,700 cfs
8. Total project discharge @ test flood el. 53.0:	22,600 cfs

c. Elevations - The spillway crest elevation, on which all the elevations in this report are referenced, is assumed to be 46.0, as shown on Design Drawings sheets 1 through 4 by Waterman Engineering Co. (March 1934). This elevation was confirmed by a survey on Dec. 10, 1980 under the direction of Mr. Owen Devine, Superintendent of the East Providence Water Company and is approximately equal to elevation 46.0 on National Geodetic Vertical Datum (NGVD).

1. Streambed at toe of dam:	29.0±
2. Bottom of cutoff:	12.0
3. Maximum tailwater:	32.0±
4. Normal pool:	46.0
5. Full flood control pool:	N/A
6. Spillway crest (ungated):	46.0
7. Design surcharge (original design):	Not known
8. Top of Dam:	51.0
9. Top of west dike:	51.0
10. Test flood surcharge:	53.0

d. Reservoir Length

1. Normal pool:	11,500± ft.
2. Flood control pool:	N/A
3. Spillway crest pool:	11,500± ft.

f. Operator - Owen Devine
67 Talmer Avenue
Riverside, Rhode Island 02915
Tel: (401)433-3123

g. Purpose of Project - Originally for public water supply, but its use was discontinued because of poor water quality.

h. Design and Construction History - The following information is believed to be accurate, based on the available data, correspondence and an interview with the owner of the dam. The dam was designed by Waterman Engineering Company and constructed in 1934 to serve as a public water supply. Maximum flow over the spillway was reported in 1949 to be 15 inches above the spillway crest. This flow was assumed to have occurred in 1936. Because of the vandalism to the gatehouse the handwheels to the gates were removed, the door was removed and the doorway opening sealed with concrete block and mortar and a window which is easily accessible was covered with a steel plate. There is no record of repairs or other alterations other than removing the handwheels and sealing the doorway and window to the gatehouse.

i. Normal Operational Procedures - There are no formal operational procedures followed at the dam. The sluice gates for the two 54 inch low-level outlets and the 66 inch supply main are closed, inaccessible, and for all practical purposes, abandoned.

1.3 PERTINENT DATA

a. Drainage Area - The drainage area is 48 square miles of flat and coastal terrain with many areas of swampland to the east and northeast. The land is moderately to heavily developed.

b. Discharge at Damsite - Discharge is over the concrete spillway only. The two low-level outlets cannot be considered discharge structures because the present condition of the gatehouse prevents access for operation. These outlets are therefore considered abandoned.

1. Outlet Works

2 - 54 inch low level outlets
invert el. 29.5:

Considered abandoned
at time of inspection

66 inch supply main inlet invert
el. 32.25:

Abandoned

2. Maximum known flood at damsite:

15 inches (el. 44.25)
above spillway crest
Assumed date 1936.

3. Ungated spillway capacity @ top of Dam el. 51.0

8300 cfs

The spillway, having a crest elevation of 46.0, is a 200 foot long concrete ogee type spillway with a 30+ foot long, 2.0 foot deep concrete stilling pool approximately 14.5 feet (el. 31.5) below the spillway crest. The spillway crest, at el. 46.0, is 5 feet below the top of dam (el. 51.0). At each end of the spillway are concrete training walls which extend approximately 100 feet downstream from the spillway.

The masonry outlet structure, which is also the foundation of the brick gatehouse, is adjacent to the right end of the spillway. Within the gatehouse, which is presently sealed, there are three gate operating stands. If operable, these stands control flow through the two 54 inch low-level outlets and an abandoned 66 inch raw water supply main. The two low-level outlets discharge from the base of the gatehouse foundation into the spillway channel. The supply main is buried along the right side of the downstream channel and transmitted flow by gravity from the reservoir to the filtration plant approximately 2600 feet downstream of the dam. Reportedly, the filtration plant was abandoned in 1970 and the supply main shut off at the gatehouse.

To the right of the dam, the west dike extends in a north westerly direction. The west dike has a height of 6 feet and a top width of about 15 feet. The upstream slope is riprapped and inclined at 3 horizontal to 1 vertical and the downstream slope is inclined at 2 horizontal to 1 vertical.

East Dike No. 1 is a 2 foot high irregularly shaped earth embankment built on a grade sloping upward away from the reservoir toward Ledge Road. A 16 inch storm sewer line is buried in, and adjacent to, the dike which serves as an access road to the sewer manholes. East Dike No. 2 is a 2 foot high earth embankment. The top of the dike is approximately 15 feet wide and also serves as an access road for nearby manholes to the storm sewer line. Neither of these dikes or the West Berm are necessary for the impoundment of water in the reservoir.

c. Size Classification - INTERMEDIATE - The project impounds 3100 acre-feet of water with the reservoir level to the top of the dam, which at elevation 51.0, is 22 feet above the streambed of Ten Mile River. According to recommended guidelines, a dam with a storage capacity between 1,000 and 50,000 acre-feet is classified as intermediate in size.

d. Hazard Classification - HIGH - If the dam were breached, there is potential for the loss of more than a few lives and extensive property damage to industrial buildings and numerous houses downstream of the dam.

e. Ownership - East Providence Water Works
Hunts Mill Road
Rumford, Rhode Island 02916
Owen Devine (Superintendent)
Tel: (401) 434-3311

1.2 DESCRIPTION OF PROJECT

a. Location - The dam is located on Ten Mile River in a densely populated area of the City of East Providence, County of Providence, State of Rhode Island. The dam is shown on the East Providence, Mass.-R.I. USGS Quadrangle Map having coordinates latitude $N41^{\circ}50.0'$ and longitude $W71^{\circ}20.5'$.

b. Description of Dam and Appurtenances - As shown on Sheets B-1 through B-4, the dam is an earth embankment with a total length of approximately 820 feet including a 25 foot long masonry outlet structure, and a 200 foot long ogee type spillway. Adjacent to the right end of the dam is the 730+ foot long west dike. Extending in a northerly direction from the end of the west dike to Newman Avenue (a distance of approximately 2600 feet) the shoreline was straightened by placing fill and grading it to the existing topography. This fill area, which was constructed at the same time as the dam, is referred to as the west berm. Two dikes are located on the east side of the impoundment. East Dike No. 1 is a low dike which closes a small depression at Ledge Road. East Dike No. 2 is a low dike located approximately midway between the dam and Newman Avenue. The portion of the reservoir north of Newman Avenue is shown on some maps as Central Pond (See Sheet D-2). Newman Avenue is on a man-made embankment with no apparent regulation of flow, i.e. water level is the same on both sides, and its ability to withstand head differentials is unknown. Therefore, the two water bodies are considered to be a single impoundment.

The earth embankment dam, which is adjacent to the left end of the spillway and approximately 22 feet high, contains a steel sheet pile cutoff and a concrete corewall (See Sheets B-1 through B-4). The top of the dam is approximately 15 feet wide and grass covered. The upstream slope is inclined at 3 horizontal to 1 vertical with riprap slope protection to about 2 feet from the top of the dam. The grass covered downstream slope is inclined at 4 horizontal to 1 vertical. The portion of the dam to the right of the outlet structure consists of a 20 inch thick concrete wall upstream and a grass covered earth embankment inclined at 3 horizontal to 1 vertical downstream. The top width is approximately 15 feet.

A 6 inch agricultural tile foundation drain is located along the footing on the downstream side of the corewall and outlets through the left spillway training wall to the spillway channel. This drain is located approximately at original ground elevation and is accessible from manholes near the toe of the downstream slope. There are 16 inch diameter storm drains along both the east and west shorelines of the reservoir. These drains outlet to the spillway channel from the left and right spillway training walls, respectively. Manholes to the drain pipes are located at the top of the embankment section to the left of the spillway and at the toe of the west dike, to the right of the spillway (See Sheet B-2).

PHASE I INSPECTION REPORT
JAMES V. TURNER RESERVOIR DAM
SECTION I - PROJECT INFORMATION

1.1 GENERAL

a. Authority - Public Law 92-367, August 8, 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a National Program of Dam Inspection throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region. Cahn Engineers, Inc. has been retained by the New England Division to inspect and report on selected dams in the State of Rhode Island. Authorization and notice to proceed were issued to Cahn Engineers, Inc. under a letter of April 14, 1980 from William E. Hodgson, Jr., Colonel, Corps of Engineers. Contract No. DACW 33-80-C-0052 has been assigned by the Corps of Engineers for this work.


b. Purpose of Inspection Program - The purposes of the program are to:

1. Perform technical inspection and evaluation of non-federal dams to identify conditions requiring correction in a timely manner by non-federal interests.
2. Encourage and prepare the States to quickly initiate effective dam inspection programs for non-federal dam.
3. To update, verify and complete the National Inventory of Dams.

c. Scope of Inspection Program - The scope of this Phase I inspection report includes:

1. Gathering, reviewing and presenting all available data as can be obtained from the owners, previous owners, the state and other associated parties.
2. A field inspection of the facility detailing the visual condition of the dam, embankments and appurtenant structures.
3. Computations concerning the hydraulics and hydrology of the facility and its relationship to the calculated flood through the existing spillway.
4. An assessment of the condition of the facility and corrective measures required.

It should be noted that this report does not pass judgement on the safety or stability of the dam other than on a visual basis. The inspection is to identify those features of the dam which need corrective action and/or further study.



LOCATION MAP
RHODE ISLAND
0 1/2 1 1/2 2 3 4
SCALE IN MILES
PAGE-X

JAMES V. TURNER
RESERVOIR DAM

PROVIDENCE

WARRICK

JOHN

SAUNDERSVILLE

SAUNDERSVILLE

North

rate



OVERVIEW FROM LEFT SIDE OF CHANNEL
(11-20-80)



OVERVIEW FROM RIGHT SIDE OF CHANNEL
(10-8-80)

US ARMY ENGINEER DIV. NEW ENGLAND
CORPS OF ENGINEERS
WALTHAM, MASS

CAHN ENGINEERS INC.
WALLINGFORD, CONN
ENGINEER

NATIONAL PROGRAM OF
INSPECTION OF
NON-FED. DAMS

James V. Turner Res. Dam
Ten Mile River
East Providence, RI
CE# 27 785 KG
DATE Jan. 1981 PAGE ix

SECTION 7: ASSESSMENT, RECOMMENDATIONS & REMEDIAL MEASURES

7.1 Dam Assessment 7-1
a. Condition
b. Adequacy of Information
c. Urgency
7.2 Recommendations 7-1
7.3 Remedial Measures 7-2
a. Operation and Maintenance Procedures
7.4 Alternatives 7-2

APPENDICES

	<u>Page</u>
APPENDIX A: <u>INSPECTION CHECKLIST</u>	A-1 to A-5
APPENDIX B: <u>ENGINEERING DATA AND CORRESPONDENCE</u>	
Dam Plans, Profile and Sections	Sheet B-1 to B-4
List of Existing Plans	B-1
Summary of Data and Correspondence	B-2
Data and Correspondence	B-3 to B-18
APPENDIX C: <u>DETAIL PHOTOGRAPHS</u>	
Photograph Location Plan	Sheet C-1
Photographs	C-1 to C-4
APPENDIX D: <u>HYDRAULIC/HYDROLOGIC COMPUTATIONS</u>	
Drainage Area Map	Sheet D-1
Dam Failure Impact Area Map	Sheet D-2
Computations	D-1 to D-11
Preliminary Guidance for Estimating Maximum Probable Discharges	i to viii
APPENDIX E: <u>INFORMATION AS CONTAINED IN THE NATIONAL INVENTORY OF DAMS</u>	E-1

2.4	<u>Evaluation of Data</u>	2-1
	a. Availability	
	b. Adequacy	
	c. Validity	
SECTION 3: VISUAL INSPECTION		
3.1	<u>Findings</u>	3-1
	a. General	
	b. Dam and Dikes	
	c. Appurtenant Structures	
	d. Reservoir Area	
	e. Downstream Channel	
3.2	<u>Evaluation</u>	3-2
SECTION 4: OPERATIONAL AND MAINTENANCE PROCEDURES		
4.1	<u>Operational Procedures</u>	4-1
	a. General	
	b. Description of Warning System in Effect	
4.2	<u>Maintenance Procedures</u>	4-1
	a. General	
	b. Operating Facilities	
4.3	<u>Evaluation</u>	4-1
SECTION 5: EVALUATION OF HYDRAULIC/HYDROLOGIC FEATURES		
5.1	<u>General</u>	5-1
5.2	<u>Design Data</u>	5-1
5.3	<u>Experience Data</u>	5-1
5.4	<u>Test Flood Analysis</u>	5-1
5.5	<u>Dam Failure Analysis</u>	5-2
SECTION 6: EVALUATION OF STRUCTURAL STABILITY		
6.1	<u>Visual Observations</u>	6-1
6.2	<u>Design and Construction Data</u>	6-1
6.3	<u>Post Construction Changes</u>	6-1
6.4	<u>Seismic Stability</u>	6-1

TABLE OF CONTENTS

	<u>Page</u>
Letter of Transmittal	
Brief Assessment	i, ii
Review Board Signature Page	iii
Preface	iv-v
Table of Contents	vi-viii
Overview Photo	ix
Location Map	x

SECTION 1: PROJECT INFORMATION

1.1 <u>General</u>	1-1
a. Authority	
b. Purpose of Inspection Program	
c. Scope of Inspection Program	
1.2 <u>Description of Project</u>	1-2
a. Location	
b. Description of Dam and Appurtenances	
c. Size Classification	
d. Hazard Classification	
e. Ownership	
f. Operator	
g. Purpose of Project	
h. Design and Construction History	
i. Normal Operational Procedures	
1.3 <u>Pertinent Data</u>	1-4
a. Drainage Area	
b. Discharge at Damsite	
c. Elevations	
d. Reservoir Length	
e. Reservoir Storage	
f. Reservoir Surface	
g. Dam and Dikes	
h. Diversicn and Regulating Tunnel	
i. Spillway	
j. Regulating Outlets	

SECTION 2: ENGINEERING DATA

2.1 <u>Design Data</u>	2-1
2.2 <u>Construction Data</u>	2-1
2.3 <u>Operations Data</u>	2-1

SECTION 3: VISUAL INSPECTION

3.1 FINDINGS

a. General - The general condition of the project is fair. The inspection revealed several areas requiring maintenance and monitoring. At the time of the inspections the pond level was at elevation 46.2, i.e. 4.8 feet below the top of the dam with water flowing at a depth of 0.2 feet over the spillway crest.

b. Dam and Dikes

Dam

Top of Earth Dam - The grass cover on the dam is approximately 2 feet tall except for where trespassing along the top has worn a path. Some small trees and brush are also growing along the top (Photos 1 and 4).

Upstream Slope - The upstream slope is heavily overgrown with small to moderate size trees and brush (Photo 1). The growth of this vegetation has displaced riprap thus allowing wave action and surface runoff to begin eroding the slope.

Downstream Slope - The downstream slope is vegetated with tall grass, small trees and brush (Photo 4). There are many animal burrows approximately 8 to 12 inches in diameter in the embankment. The soil at the toe of the dam from the left of the spillway to the left abutment is wet. A back channel, which is the original streambed, extends from about the left abutment and connects with the spillway channel approximately 350 feet downstream of the spillway. This channel is approximately 30 feet wide at its widest point and is up to 3 feet deep (Photo 7). There is no apparent movement of the water in the channel and its depth is regulated by a small dam approximately 2500 feet downstream. No seepage along the toe of the slope was observed; however, observation was obscured in certain areas where the back channel extends to the toe of the dam. It appeared that the foundation drain was functioning properly. Discharge from the drain was clear and flowing at a rate of approximately 2 to 3 gallons per minute (gpm).

Spillway - Water was flowing over the spillway at the time of the inspection; therefore, the extent of the inspection was limited. The spillway crest shows no signs of irregularities (Photo 4). A concrete stilling pool extends from the toe of the spillway for a distance of about 30 feet. With water flowing over the spillway, the condition of the stilling pool could not be observed. Cracks up to 1 inch wide are present in the concrete training walls at construction joints and where the walls change slope or direction. The left wall has some spalling and deterioration on its face and above the drain outlet and the storm sewer outlet. The downstream end of the right wall is deteriorated and some minor spalling is present on the wall face (Photos 4,5,6).

West Dike

Top of West Dike - The top of the dike is irregular and overgrown with many small to moderate size trees and brush. Excessive trespassing along the top has worn a path through the protective grass mat (Photo 3).

Upstream Slope - The upstream slope is irregular and heavily overgrown with brush and small to moderate size trees (Photos 2, 3). Wave action has displaced riprap and eroded into the slope. Tree growth has also contributed to riprap displacement.

Downstream Slope - The downstream slope is also heavily overgrown with brush and small to moderate size trees. Some minor erosion is present from surface runoff. No seepage was observed at the time of the inspection (Photo 3).

East Dikes - The East Dikes are not necessary for the impoundment of water in the reservoir. They appear to have been constructed mainly for facilitating the alignment of storm sewer lines around the reservoir. Both dikes have irregular top elevations and are vegetated with trees and brush. However, the only possible damage resulting from overtopping and/or failure of the dikes would be to the storm sewers.

c. Appurtenant Structure - The brick gatehouse is in poor condition. All the windows are broken, graffiti covers the walls, wood trim is broken, roof shingles are torn off, etc. (Photo 8). The door has been removed and the opening sealed with concrete block and mortar. One window on the downstream side has been covered with a steel plate to prevent trespassing. The handwheels have been removed and stored by the East Providence Water Department to prevent vandals from opening the sluice gates. The low-level outlets could not be inspected because of the condition of the gatehouse. For all practical purposes the gatehouse has been abandoned.

d. Reservoir Area - The area surrounding the reservoir is generally wooded, flat coastal terrain. There are residential developments at several locations near the edge of the reservoir. The reservoir area includes the water body to the north of Newman Avenue, which is shown on the USGS topographic map (Sheet D-2) as Central Pond.

e. Downstream Channel - The downstream channel is a realigned channel of the Ten Mile River. From the stilling pool for about 50 feet the channel is lined with stone pavement. Beyond this pavement the channel bottom is soil and cobbles with riprap protection on the banks. Approximately 1200 feet downstream of the dam, the manmade channel joins the original river channel.

3.2 EVALUATION

Based upon the visual inspection, the project is assessed as being in fair condition. The following features which could influence the future condition and/or stability of the project were identified.

1. Erosion has occurred due to trespassing along the top of the dam and other embankments.
2. Trees, brush and burrowing animals could cause piping and/or seepage by creating flow paths, either along root systems or through holes, in the embankments. Trees, if uprooted, may produce depressions which may be critical to the stability of the dam.
3. Trees and brush growing through the riprap on the upstream slope will displace the riprap, thus leaving the underlying earth vulnerable to erosion.
4. The lack of riprap at the waterline on the upstream embankment will allow wave action to continue eroding into the embankment.
5. Freeze-thaw cycles can act within the cracks in the concrete structures, thus leading to further deterioration.
6. The condition and operability of the low level outlets is unknown because of the inaccessible condition of the gatehouse.
7. If there were an emergency where the low-level outlets had to be opened, with the gatehouse in its present condition, the time it would take to obtain the handwheels, gain access, and open the valves, if operable, may prove critical to the safe operation of the dam.

SECTION 4: OPERATIONAL AND MAINTENANCE PROCEDURES

4.1 OPERATIONAL PROCEDURES

a. General - No formal program of operation has been in effect since the reservoir was abandoned as a public water supply in 1970.

b. Description of any Warning System in Effect - No formal warning system is in effect.

4.2 MAINTENANCE PROCEDURES

a. General - There is no formal program of maintenance or inspection at the dam.

b. Operating Facilities - No formal program for maintenance of operating facilities is in effect.

4.3 EVALUATION

Operation and maintenance procedures are not performed. A formal program of operation and maintenance procedures should be implemented, including documentation to provide complete records for future reference. Also, an emergency action plan as well as a formal downstream warning system should be developed and implemented within the time frame indicated in Section 7.1c. Remedial operation and maintenance recommendations are presented in Section 7.3.

SECTION 5: EVALUATION OF HYDRAULIC/HYDROLOGIC FEATURES

5.1 GENERAL

The James V. Turner Reservoir Dam watershed is 48.0 square miles of flat and coastal wooded terrain typically containing large swamps and impoundments (Falls Pond, Manchester Pond Reservoir, Greenwood Lake and Digville Pond) which contribute to the sluggish runoff characteristics of the watershed.

The reservoir is formed by an earthfill dam with a concrete spillway, and three earthfill dikes. The available storage reduces the outflow from a Probable Maximum Flood (PMF) of 24,000 cubic feet per second (cfs) to 22,600 cfs and the $\frac{1}{2}$ PMF outflow from 12,000 cfs to 11,000 cfs.

The top of the dam and west dike are approximately at elevation 51.0. Overtopping of the East Dikes will occur at a lower elevation, but this will only cause small depressions behind the dikes to be flooded. Therefore, the elevation of the top of the East Dikes is not significant in hydraulic computations. The reservoir is crossed by an embankment at Newman Avenue; however, this structure was not assumed to be capable of impounding water.

5.2 DESIGN DATA

No computations could be found for the original design of the dam.

5.3 EXPERIENCE DATA

No documented information is available. Presently no records are kept and the owner's previous flow records were destroyed in a fire. A flow of 15 inches in depth over the spillway is reported to have occurred in 1936. Mr. Owen Devine, superintendent of the East Providence Water Works, reported that the most severe flood he could recall occurred in March or April 1968, when sandbags had to be placed to prevent flooding of the filtration plant.

5.4 TEST FLOOD ANALYSIS

Based upon the U.S. Army Corps of Engineers "Preliminary Guidance for Estimating Maximum Probable Discharges" dated March, 1978; the watershed classification (Flat and Coastal), and the watershed area of 48.0 square miles, a PMF of 24,000 cfs or 500 cfs per square mile is estimated at the damsite. In accordance with the size (intermediate) and hazard (high) classification, the test flood is the PMF. The reservoir level at the start of the test flood is considered to be at spillway crest elevation 46.0. The peak outflow for the test flood is estimated at 22,600 cfs and this flow will overtop the dam by 2.0 feet. Based on hydraulic computations, the spillway capacity to the first point of overtopping of the dam is 8,300 cfs which is equivalent to 37% of the routed test flood outflow (Appendix D-6).

5.5 DAM FAILURE ANALYSIS

Many houses and industrial/commercial structures with first floors less than 12 feet above the stream constitute the potential initial impact area in case of failure of Turner Dam. These are located in an approximately 12,000 foot long reach of the Ten Mile River between Turner Reservoir and the river's confluence with the Seekonk River. In particular, at least 10 houses with first floors between 6+ feet and 10+ feet above the stream are located in an area immediately downstream from Pawtucket Avenue (Route 1A-114).

The dam failure analysis is based on the April, 1978 Army Corps of Engineers "Rule of Thumb Guidance for Estimating Downstream Dam Failure Hydrographs". With the reservoir level at the first point of overtopping of the dam, peak outflow before failure of the dam would be about 8,300 cfs and the peak failure outflow from the dam breaching would total about 48,300 cfs.

The prefailure depth of flow at the initial impact area would be 5.5 feet, or approximately 0.5 foot below the first floor of the lowest house in the impact area. A breach of the dam would result in a rapid 2.6 to 3.6 foot increase in water levels to depths of approximately 8.1 to 9.1 feet. This sudden outflow will cause rapid inundation of several houses by 2 or more feet, possibly causing loss of more than a few lives and substantial economic loss. Based on the dam failure analysis, James V. Turner Reservoir Dam is classified as a high hazard dam (Appendix D-11).

SECTION 6: EVALUATION OF STRUCTURAL STABILITY

6.1 VISUAL OBSERVATIONS

The visual inspection did not reveal any indications of immediate stability problems. There are areas of deterioration, and erosion, as described in Section 3, however they are not considered stability concerns at the present time.

6.2 DESIGN AND CONSTRUCTION DATA

The drawings and data available and listed in Appendix B were not sufficient to perform an in depth stability analysis of the project. No engineering assumptions, data or calculations could be found for the original design of the dam.

6.3 POST CONSTRUCTION CHANGES

There are no known post-construction changes to the project other than the sealing of the gatehouse doorway and window.

6.4 SEISMIC STABILITY

The project is in Seismic Zone 2 and according to the Recommended Guidelines, need not be evaluated for seismic stability.

SECTION 7: ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES

7.1 DAM ASSESSMENT

a. Condition - Based upon the visual inspection of the site and past performance, the project appears to be in fair condition. However, there are areas which require maintenance, repair and monitoring.

Based upon the Army Corps of Engineers' "Preliminary Guidance for Estimating Maximum Probable Discharges" dated March, 1978, the watershed classification and hydraulic/hydrologic computations, peak inflow to the reservoir at test flood is 24,000 cubic feet per second (cfs); peak outflow is 22,600 cfs with the dam overtopped 2.0 feet. Based upon our hydraulic computations, the spillway capacity to the top of the dam is 8300 cfs, which is equivalent to approximately 37% of the routed test flood outflow.

b. Adequacy of Information - The information available is such that an assessment of the condition and stability of the project must be based solely on visual inspection, past performance and sound engineering judgement.

c. Urgency - It is recommended that the measures presented in Section 7.2 and 7.3 be implemented within one year of the owner's receipt of this report.

7.2 RECOMMENDATIONS

It is recommended that further studies be made by a registered professional engineer qualified in dam design and inspection pertaining to the following items. Recommendations made by the engineer should be implemented by the owner.

1. A detailed hydraulic/hydrologic analysis to determine the adequacy of the project discharge and existing outlet facilities.
2. With the gatehouse and low-level outlets restored to operating condition, the reservoir level should be lowered to where no water is flowing over the spillway so that the condition of the spillway stilling pool, paved channel, and unpaved channel can be evaluated.
3. Removal of all trees and tree stumps from the embankments and abutments and from within 25 feet of the toe of the dam and west dike. This should include removal of root systems and proper backfilling.
4. The slopes of the dam and west dike should be regraded and riprap slope protection replaced to prevent further erosion by wave action and surface runoff.

5. The possibility of seepage contributing flow to the back-channel at the toe of the embankment should be investigated.
6. Cracks in the concrete structures should be filled and spalling repaired to prevent further deterioration of the concrete.

7.3 REMEDIAL MEASURES

a. Operation and Maintenance Procedures - The following measures should be undertaken by the owner within the length of time indicated in Section 7.1.c, and continued on a regular basis.

1. Round-the-clock surveillance should be provided during periods of heavy precipitation or high project discharge. A formal downstream warning system should be developed to be used in case of emergencies at the dam.
2. A formal program of operation and maintenance procedures should be instituted and fully documented to provide accurate records for future reference. The maintenance procedures should include a monthly inspection by the owner or owner's representative.
3. A comprehensive program of inspection by a registered professional engineer qualified in dam inspection should be instituted on a biennial basis.
4. Brush should be removed from the embankments and from within 25 feet of the toe as part of the regular maintenance of the project.
5. Grass should be re-established at the eroded areas particularly where trespassing has caused erosion along the tops of the embankments.
6. Grass on the slopes and at the top of the dam and west dike should be mowed as part of regular maintenance procedures.
7. Animal burrows should be properly backfilled.
8. The gatehouse should be restored to a condition where it would be accessible by authorized personnel only and the gates should be operational upon entry. Gate lifts should be maintained and exercised on a regular basis.

7.4 ALTERNATIVES

This study has identified no practical alternatives to the above recommendations.

APPENDIX A
INSPECTION CHECKLIST

**VISUAL INSPECTION CHECK LIST
PARTY ORGANIZATION**

PROJECT Limes V. Turner Reservoir Dam DATE: 10-8-80 11-20-80

TIME: Morning Morning

WEATHER: Sunny, fair sunny
snow on ground

W.S. ELEV. _____ U.S. _____ DN.S _____

<u>PARTY:</u>	<u>INITIALS:</u>	<u>DISCIPLINE:</u>
1. <u>Peter Hayes</u>	<u>PH</u>	<u>Geotechnical</u>
2. <u>Ted Stevens</u>	<u>TS</u>	<u>Geotechnical</u>
3. <u>Tim Kavanaugh</u>	<u>TK</u>	<u>Geotechnical</u>
4. <u>Hector Merene</u>	<u>HM</u>	<u>Hydraulic</u>
5. <u>Frank Segatine</u>	<u>FS</u>	<u>Survey</u>
6. _____	_____	_____

<u>PROJECT FEATURE</u>	<u>INSPECTED BY</u>	<u>REMARKS</u>
1. <u>Earth Embankments</u>	<u>PH, TS, TK, HM</u>	
2. <u>West Dike</u>	<u>PH, TS, TK, HM</u>	
3. <u>Spillway</u>	<u>PH, TS, TK, HM</u>	
4. <u>Low-level Outlets</u>	<u>PH, TS, TK, HM</u>	
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____
11. _____	_____	_____
12. _____	_____	_____

PERIODIC INSPECTION CHECK LIST

Page A-2

PROJECT James V. Turner Reservoir Dam

DATE 10-8-80 & 11-20-80

PROJECT FEATURE Earth Embankments

BY PH, JS, JK, HM

AREA EVALUATED	CONDITION
<u>DAM EMBANKMENT</u>	
Crest Elevation	El. 51.0
Current Pool Elevation	46.2 (Both inspection dates)
Maximum Impoundment to Date	Not Known
Surface Cracks	None
Pavement Condition	Grass covered — Trees & brush on slopes
Movement or Settlement of Crest	} None observed
Lateral Movement	} Appears good
Vertical Alignment	
Horizontal Alignment	
Condition at Abutment and at Concrete Structures	Abutment heavily overgrown with trees
Indications of Movement of Structural Items on Slopes	None observed
Trespassing on Slopes	2 ft wide path along top
Sloughing or Erosion of Slopes or Abutments	Some erosion behind each spillway training wall near top of dam. Erosion on upstream embankment.
Rock Slope Protection-Riprap Failures	Some riprap displaced by tree growth
Unusual Movement or Cracking at or Near Toes	None observed.
Unusual Embankment or Downstream Seepage	Standing water (Back channel) extending from left abutment connecting with spillway channel approx. 350 ft downstream of spillway structure. (original stream bed).
Piping or Boils	None observed
Foundation Drainage Features	6" agricultural clay pipe, left side of spillway only.
Toe Drains	N/A
Instrumentation System	None

PERIODIC INSPECTION CHECK LIST

Page A-3

PROJECT James V. Turner Reservoir Dam

DATE 10-8-80 & 11-20-80

PROJECT FEATURE West Dike

BY RHTS, JK, HM

AREA EVALUATED	CONDITION
<u>DIKE EMBANKMENT</u>	
Crest Elevation	51.0 ± (Irregular)
Current Pool Elevation	46.2 (Both inspection dates)
Maximum Impoundment to Date	Not known
Surface Cracks	None observed
Pavement Condition	Grass covered - Overgrown with trees and brush
Movement or Settlement of Crest	} None observed
Lateral Movement	
Vertical Alignment	} Appears good
Horizontal Alignment	
Condition at Abutment and at Concrete Structures	N/A
Indications of Movement of Structural Items on Slopes	N/A
Gouging or Erosion of Slopes or Abutments	Wave action eroding upstream slope, some erosion of downstream slope
Rock Slope Protection-Riprap Failures	Riprap displaced on upstream slope
Unusual Movement or Cracking at or Near Toes	None observed
Unusual Embankment or Downstream Seepage	None observed
Piping or Boils	None observed
Foundation Drainage Features	None
Toe Drains	None
Instrumentation System	None
Trespassing on Slopes	Foot path worn along top of dike

PERIODIC INSPECTION CHECK LIST

Page A-4

PROJECT Lewis & Turner Reservoir Dam

DATE 10-8-80 & 11-20-80

PROJECT FEATURE Spillway

BY P.H.T.S., T.K.H.M.

AREA EVALUATED	CONDITION
<u>OUTLET WORKS-SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS</u>	
a) <u>Approach Channel</u> General Condition Loose Rock Overhanging Channel Trees Overhanging Channel Floor of Approach Channel	Fair None None N/A
b) <u>Weir and Training Walls</u> General Condition of Concrete Rust or Staining Spalling Any Visible Reinforcing Any Seepage or Efflorescence Drain Holes	Fair Some staining of training walls Some spalling of training walls and possibly weir. Deterioration at downstream end of right training wall.
c) <u>Discharge Channel</u> General Condition Loose Rock Overhanging Channel Trees Overhanging Channel Floor of Channel Other Obstructions	Good None None Natural streambed. Bridge crossing channel approx 1200 ft. downstream of spillway

EAST PROVIDENCE WATER COMPANY

TEN MILE WATERSHED

53 SQUARE MILES AT HUNTS MILLS

SUMMARY OF STATISTICS FOR 1923

MONTH	TOTAL YIELD MIL GALS	YIELD OF 150 MILE		RAINFALL INCHES	RAINFALL COLLECTED INCHES	PER CENT COLLECTED
		MIL GALS PER DAY	CU FT. PER SEC.			
Jan	5664.8	3447	5320	8.78	6.15	70
Feb	2050.9	1382	2132	2.06	2.22	108
Mar	5423.8	3305	5100	3.12	5.33	187
Apr	3879.7	2409	3717	5.52	4.08	74
May	2330.2	1426	2200	1.34	2.51	187
June	1010.9	636	981	5.17	1.09	21
July	743.9	454	700	3.43	.79	23
Aug.	482.1	294	453	1.65	.51	31
Sept.	408.2	259	400	1.39	.42	32
Oct.	703.1	428	660	4.98	.75	15
Nov.	991.4	623	962	4.30	1.08	25
Dec.	3314.5	2009	3100	5.93	3.12	60
YEAR	26952.3	1390	2144	47.67	29.71	61

SUMMARY OF STATISTICS FOR 1922

May	3756.5	2286	3528	5.25	3.62	70
June	4743.4	2983	4604	6.98	5.09	79
July	4499.7	2738	4226	7.45	4.84	65
Aug.	2129.3	1296	2000	6.48	2.27	35
Sept.	2663.3	1685	2600	3.42	2.87	84
Oct.	1647.2	1002	1547	3.18	1.78	55
Nov.	1321.9	884.2	1300	1.26	1.85	115
Dec.	1406.2	885.5	1320	2.80	1.54	55

YIELD
OF THE
TEN MILE RIVER
WATERSHED

The concrete abutment walls are in generally good condition. However, the concrete has begun to ~~spall~~ spall and break off along top cap at the base of wall on the right (west) side. Also, efflorescence has begun on left wall at construction joint half way up wall [see photo #17].

Outlet works - The gatehouse is presently abandoned and beginning to show signs of neglect and disrepair. The door has been removed and replaced with concrete block units. The windows have all been busted out. The foundation is of concrete construction and appears to be in good condition. The walls are brick and roof is asphalt shingles and wood construction.

The approach channel is clear and unobstructed. The handles of the manually operated gate valves have been removed and the present condition of gate-lifting mechanism is unknown but there is no visually apparent reason to doubt their operability.

Comments / Recommendations - The dam appears to be in good condition. However, ~~the river should be maintained within~~ rehabilitation of the embankment should be started before the growth of trees become a significant deterrent ~~to~~ to the safety of the structure.

DAM INSPECTION REPORT

AM: 407 RIVER: Ten Mile River WATERSHED: Ten Mile R. DATE: Sept 20, 1978
NAME: Turner Res. Dam TOWN: East Prov. INSPECTED BY: Carl F. Lout, Jr.
OWNER: City of East Prov. OTHER INTERESTED PARTY:
City of East Prov.
City Water Dept

REASON FOR INSPECTION: Annual Insp. --- N.P.S.I.D.; low hazard

REPORT: * * * * *
Current Pool Elevation: full, 2' (±) over crest of spillway
General: Built in 1934 and formerly used for water supply

Embankment: Earthen dam w/ 12" concrete core wall.

Downstream slope is beginning to be overgrown with brush and many small trees. Also, much marsh type vegetation has established itself along toe of embankment. Pond side of embankment is lined with large sized rip-rap with many small/medium sized trees growing along bank. Crest is flat with wide grassed path along its entire length. [see photo #6.]

Spillway: 200' wide concrete "ogee"-type spillway. The approach channel to spillway is clear and unobstructed with no overhanging trees or rocks on either side. The concrete crest shows no signs of irregularities. The concrete face of spillway shows signs of aeration almost up to the crest across the entire width, indicating ~~the~~ a spalling, scoured condition.





DIAGRAM B
 Ten Mile River
 at
 Hunts Mills, R.I.
 C. Perry Searle Eng'r

1923 1924 1925 1926 1927



Reproduced from best available copy.

The spillway appears to be ample for discharge of any freshet and the waste gates are surplusage for this purpose.

The characteristics of this drainage area indicate that the run-off during the dry months of the year will be higher than that of a stream of normal features. This condition of run-off is proved by the measurements of discharge made by the East Providence Water Co. beginning in 1921 and continuing for 5 years.

These measurements were supervised by me (O. F. Sarie, Engr.) and from these I designed rating curves of discharge for an average year and for a year of low run-off. These were checked against the Wachusett River yields as that drainage area and the 10 Mile River are to some extent similar.

(4) Maximum, minimum, and average rainfall and runoff on water shed

See table with yield arranged month by month from 1922 to 1926, depth in inches, inches collected and per cent collected.

(5) Stream gaugings and any other stream flow characteristics readily available.

#407

Capacity of Spillway			
crest elev. =	Elev. 46.0)	
Top of abut. =	" 51.0)	ht. = 5 ft.
Approx. elev. of valley floor at crest			elev. 34

Use $n = 12$ in Hazen Tables

$Q =$ (in c. f. s.) for sharp edge weir for 5' ht. = 38.21
Multiplier based on Hazen's $K = 1.20$

Then disch. over weir = $38.21 \times 1.20 = 45.85$ c. f. s. per ft. of length

Length of spillway = 200'

Total Disch. Capacity = $200 \times 45.85 = 9170$ c. f. s. or 191 c. f. s. per sq. mile of drainage area over 48 sq. miles.

State of Rhode Island
INTER-DEPARTMENTAL COMMUNICATION

January 11, 1961

TO: Mr. Henry Isé, Chief
DEPT. OF PUBLIC UTILITIES, WATER & RIVERS
FROM: Mr. Henry Isé, Chief
DEPT. OF PUBLIC UTILITIES, WATER & RIVERS
SUBJECT:

Prepare a summary of available statistics for the Ten Mile River
in the East Providence Water Supply System in Hunts Hill, Rumford,
etc. Statistics should include the following:

- 1) Date on the dam, such as date of construction, type, length,
height, spillway length and capacity, elevation of dam and spillway, ownership,
etc.
- 2) Storage capacity, surface area, maximum and average depth of
reservoir, etc.
- 3) Gross tributary drainage area. Land and water areas on water-
shed, etc.
- 4) Maximum, minimum and average rainfall and runoff on watershed.
- 5) Stream gaugings and any other stream flow characteristics readily
available.

Henry Isé, Chief

JAMES V. TURNER RESERVOIR DAM

SUMMARY OF DATA AND CORRESPONDENCE

<u>DATE</u>	<u>TO</u>	<u>FROM</u>	<u>SUBJECT</u>	<u>PAGE</u>
June 24, 1949	John V. Reilly State of Rhode Island Division of Harbors and Rivers	Henry Ise' State of Rhode Island Division of Harbors and Rivers	Request for summary of available statistics	B-3
June 30, 1949		State of Rhode Island Division of Harbors and Rivers	Notes of E. Providence (James V. Turner) Water Works Dam.	B-4
		Sayles Engineering Co.	Run-off rating curve (average year) from 1923 to 1926.	B-6
Sept. 20, 1978	Files	O. Perry Sarle	Run-off rating curve	B-7
		Earle F. Prout State of Rhode Island Dept. of Environmental Management	Dam inspection report	B-8
Jan. 1922 to Dec. 1926		East Providence Water Company	Yield of the Ten Mile River Watershed, 1922 through 1926.	B-10
	Files	State of Rhode Island Dept. of Environmental Management	Dam Inventory sheets	B-15


JAMES V. TURNER RESERVOIR DAM

EXISTING PLANS



East Providence Reservoir
East Providence Rhode Island
Contract No. 1
Waterman Engineering Co.
March 1934

Sheet 1	General Plans - Sections of Dam - Drains
Sheet 2	Profile Along Dam - Borings - Etc.
Sheet 3	West Wing Wall - Gate House
Sheet 4	East Spillway Wall - Details, Manholes, Corewall, Underdrains, Etc.

Note: Selected segments of the above listed existing plans
have been compiled to produce sheets B-1, B-2, B-3 and
B-4 within this section.



MAIN DAM AND DIKE



DAM/DIKES LOCATION PLAN



NOTE:
SEE SHEET B-2

CAMM ENGINEERS INC. WALLINGFORD CONNECTICUT ENGINEER		U.S. ARMY ENGINEER DIV. NEW ENGLAND CORPS ENGINEERS WALTHAM, MASS.	
NATIONAL PROGRAM OF INSPECTION OF NON-FED. DAMS			
DAM/DIKES LOCATION PLAN			
JAMES V. TURNER RESERVOIR DAM			
TEN MILE RIVER		PROVIDENCE, R.I.	
OWN. BY	CKD BY	APP BY	SCALE: AS NOTED
RJB	TJK	PMH	DATE: JAN., 1981
			SHEET B-1

APPENDIX B
ENGINEERING DATA AND CORRESPONDENCE

PERIODIC INSPECTION CHECK LIST

Page A-5

PROJECT James V. Turner Reservoir Dam

DATE 10-8-80 E11-20-80

PROJECT FEATURE Low-level Outlets

BY PH, IS, TK, HM

AREA EVALUATED	CONDITION
<p><u>OUTLET WORKS-OUTLET STRUCTURE AND</u> <u>OUTLET CHANNEL</u></p>	
<p>General Condition of Concrete</p>	<p>Fair</p>
<p>Rust or Staining</p>	<p>Some minor staining from construction joints</p>
<p>Spalling</p>	<p>Minor spalling at construction joints</p>
<p>Erosion or Cavitation</p>	<p>None observed</p>
<p>Visible Reinforcing</p>	<p>None observed</p>
<p>Any Seepage or Efflorescence</p>	<p>None observed</p>
<p>Condition at Joints</p>	<p>Minor staining and spalling</p>
<p>Drain Holes</p>	<p>None</p>
<p>Channel</p>	<p>Discharge directly into spillway channel</p>
<p>Loose Rock or Trees Overhanging Channel</p>	<p>None</p>
<p>Condition of Discharge Channel</p>	<p>Fair</p>

EAST PROVIDENCE WATER COMPANY

TEN MILE WATER

55 SQUARE MILES AT HUNTS MILLS

SUMMARY OF STATISTICS FOR

MONTH	TOTAL YIELD MILS. GALS.	YIELD OF 150. ML.		RAINFALL INCHES	RAINFALL COLLECTED INCHES	PER CENT COLLECTED
		MIL. GALS. PER DAY	CU. FT. PER SEC.			
Jan.	3816.7	2.323	3.585	4.90	4.12	84
Feb.	2480.5	1.614	2.490	3.34	2.71	61
Mar.	4158.2	2.531	3.906	3.20	4.48	140
Apr.	5501.5	3.460	5.340	4.29	5.92	136
May	3555.6	2.164	3.340	3.35	3.85	115
June	1846.8	1.161	1.792	0.99	2.00	202
July	924.0	0.562	0.868	1.31	1.01	77
Aug.	944.1	0.575	0.888	5.47	1.04	19
Sept.	2507.8	1.577	2.434	6.96	2.71	39
Oct.	964.2	0.587	0.906	0.23	1.00	436
Nov.	724.5	0.525	0.810	1.71	0.91	53
Dec.	1265.5	0.770	1.185	2.06	1.34	66
YEAR	28689.4	1.487	2.295	31.31	31.31	85

SUMMARY OF STATISTICS FOR 2 YEARS 1923-24

Jan.	9481.5	2.935	4.452	6.84	5.13	75
Feb.	4530.8	1.498	2.311	2.70	2.46	91
Mar.	9582.0	2.918	4.503	3.16	5.15	163
Apr.	9331.2	2.934	4.528	4.90	5.66	102
May	5885.8	1.795	2.770	2.34	3.18	135
June	2857.7	0.898	1.386	3.08	1.54	50
July	1667.3	0.508	0.784	2.37	0.90	38
Aug.	1826.2	0.434	0.670	3.56	0.77	22
Sept.	2916.0	0.918	1.417	4.17	1.52	36
Oct.	1667.3	0.507	0.783	2.60	0.87	34
Nov.	1715.9	0.574	0.886	3.00	0.99	33
Dec.	4500.0	1.389	2.144	3.99	2.46	62
YEAR	55641.8	1.442	2.219	42.71	29.97	70

EAST PROVIDENCE WATER COMPANY

TEN MILE WATERSHED

52.5 SQUARE MILES AT CENTRAL POND.

53.0 " " " HUNTS MILLS.

SUMMARY OF STATISTICS FOR 1925

MONTH	TOTAL YIELD MIL. GALS.	YIELD OF 1 SQ MILE		RAINFALL INCHES	RAINFALL COLLECTED INCHES	PER CENT COLLECTED
		MIL. GALS. PER DAY	CU. FT. PER SEC.			
Jan.	1285.6	0.783	1.208	4.38	1.40	32
Feb.	3556.2	2.398	3.700	2.00	3.84	192
Mar.	3696.2	2.249	3.471	4.39	3.95	90
Apr.	2585.5	1.626	2.510	2.02	2.77	137
May	1546.8	0.942	1.453	1.79	1.66	93
June	913.7	0.575	0.887	2.65	1.01	38
July	863.8	0.525	0.811	4.13	0.95	23
Aug.	401.8	0.247	0.382	2.06	0.43	21
Sept.	311.0	0.198	0.306	2.49	0.35	14
Oct.	321.4	0.198	0.306	4.04	0.36	9
Nov.	991.4	0.632	0.975	5.14	1.08	21
Dec.	1928.4	1.189	1.835	3.92	2.08	53
YEAR	18401.8	.962	1.487	39.01	19.88	52

SUMMARY OF STATISTICS FOR 3 YEARS 1923-1925

Jan.	10767.1	2.218	3.371	6.02	3.89	65
Feb.	8087.0	1.798	2.774	2.47	2.92	118
Mar.	13270.2	2.695	4.159	3.57	4.75	133
Apr.	11916.7	2.531	3.855	3.94	4.25	108
May	7432.6	1.511	2.331	2.16	2.67	124
June	3771.4	0.791	1.220	2.93	1.27	43
July	2531.1	0.513	0.793	2.95	0.91	31
Aug.	1828.0	0.372	0.574	3.06	0.66	22
Sept.	3227.0	0.678	1.047	3.61	1.16	32
Oct.	1988.7	0.404	0.624	3.08	0.70	23
Nov.	2707.3	0.533	0.915	3.71	1.02	28
Dec.	6508.4	1.323	2.041	3.97	2.33	59
YEAR	74043.5	1.285	1.975	41.47	26.53	65

EAST PROVIDENCE WATER COMPANY

TEN MILE WATERSHED

523 SQUARE MILES AT CENTRAL POND

SUMMARY OF STATISTICS FOR 1926

MONTH	TOTAL YIELD MIL. GALS.	YIELD OF 1 SQ. MILE		RAINFALL INCHES	RAINFALL COLLECTED INCHES	PER CENT COLLECTED
		MIL. GALS. PER DAY	CU. FT. PER SEC.			
Jan.	1064.7	0.645	0.996	2.79	1.17	42
Feb.	1850.7	1.264	1.950	5.49	2.03	37
Mar.	3656.0	2.255	3.480	3.63	4.07	112
Apr.	3071.5	1.958	3.021	2.72	3.35	123
May	2089.2	1.288	1.988	2.79	2.32	83
June	1224.7	0.780	1.204	1.74	1.31	75
July	803.5	0.496	0.765	3.32	0.86	26
Aug.	743.3	0.458	0.707	4.28	0.81	19
Sept.	427.7	0.272	0.420	1.68	0.47	28
Oct.	582.6	0.359	0.554	5.15	0.62	12
Nov.	1341.4	0.855	1.319	5.45	1.47	27
Dec.	1197.5	0.818	1.262	3.21	1.44	45
YEAR	18052.8	.954	1.472	42.25	1992	47

SUMMARY OF STATISTICS FOR 4 YEARS 1923-1926

Jan.	11831.8	1.824	2.752	5.21	3.21	62
Feb.	9937.7	1.664	2.568	3.22	2.70	84
Mar.	16934.2	2.585	4.239	3.58	4.58	128
Apr.	14988.2	2.388	3.647	3.63	4.03	111
May	9521.8	1.455	2.245	2.32	2.58	111
June	4996.1	0.788	1.216	2.64	1.35	51
July	3334.6	0.509	0.786	3.05	.90	29
Aug.	2571.3	0.393	0.607	3.38	.69	20
Sept.	3654.7	0.576	0.890	3.13	.96	31
Oct.	2571.3	0.393	0.606	3.60	.68	19
Nov.	4048.7	0.659	1.016	4.15	1.13	27
Dec.	7705.9	1.196	1.846	3.78	2.11	56
YEAR	92096.3	1.202	1.868	41.69	2492	60

IDENTIFYING DATA

1. Dam number ¹ 0407

2. City/town ⁵ 10
East Providence

3. U.S.G.S. quad sheet number ⁷ 15
East Providence

4. Owner/operator ⁹ [][][][]

5. Water rights owner ¹³ [][][][]

6. Type of ownership -- bond ¹⁷ []

7. Type of ownership -- public ¹⁸ []

8. Type of public access ¹⁹ []

9. Designed purpose of dam ²⁰ C
Water Supply

10. Current use of dam ²¹ []

WATERSHED DATA:

11. Drainage basin ²² 10
Providence River

12. Stream name ²⁴ 101
Providence River

13. Area of watershed (nearest tenth sq. mi.) ²⁷ 048 . 0

14. Design storm frequency ³¹ 3

15. S.C.S. Hydrologic curve number ³² [][][]

16. Peak discharge rate of watershed (C.F.S.) ³⁵ 01872

(OVER)

POOL DATA:

17. Elevation--normal water level of pool ⁴⁰ .

18. Elevation--pool bottom @ dike (1/10 ft.) ⁴⁴ .

19. Elevation--instream channel bed @ dike ⁴⁸ .

20. Area of pool surface (acres) ⁵²

21. Normal storage cap. of pool (first acre ft.) ⁵⁶

22. Water quality of pool ⁶¹

SPILLWAY DATA:

23. Type of spillway ⁶³

24. Type of material in spillway ⁶⁴

25. Elevation--crest of spillway (1/10 ft.) ⁶⁵ .

26. Max. safe depth of flow over spillway ⁶⁹ .

27. Width of spillway (no crest ft.) ⁷¹

28. Max. flow capacity of spillway (C.F.S.) ⁷⁴

29. Condition of spillway ⁷⁹

ID:

Card number ⁸⁰

ID:

30. Dam number

1
0 4 0 7

WASTE WATER OUTLET DATA:

31. Type of waste water outlet

5
P
Pipe and Valve

32. Waste water outlet size (sq. ft.)

6
0 3 2

33. Max. flow cap. of waste water outlet (C.F.S.)

9
[] [] [] [] [] []

34. Condition of waste water outlet

14
[]

DIKE DATA:

35. Elevation--top of dike (1/10 ft.)

15
0 5 1 . 0

36. Length of dike (excl. spillway) (nearest ft.)

19
1 7 5 0

37. Top width of dike (nearest ft.)

23
[] []

38. Type of construction of dike

25
F
Fill

39. Type of material in dike

26
E C
Earth, Concrete

40. Condition of dike

28
[]

FLOOD CONTROL DATA:

41. Elevation--expected high water (1/10 ft.)

29
[] [] [] []

42. Flood control storage capacity (nrst acre ft.)

33
[] [] [] [] [] []

43. Max. storm discharge cap. of dam (C.F.S.)

38
[] [] [] [] [] []

44. Flood control structure--type

43
[]

(OVER)


DATA ON ASSOCIATED STRUCTURES:

- 44. Drain valve type
- 45. Drain valve size (sq. ft.)
- 47. Drain valve location (sta. on C/L of dam) +
- 48. Draw down valve type **P**
Pipe and Valve
- 49. Draw down valve size (sq. ft.) **24**
- 53. Draw down valve location (sta. on C/L of dam) +
- 56. Fish ladder--elevation of floor @ dam (1/10 ft.)
- 60. Fish ladder rise (nearest ft.)
- 62. Fish ladder width (nearest ft.)
- 63. Fish ladder--design depth of flow (nrst ft.)
- 64. Fish ladder--general location
- 65. Fish ladder--type of fish

GENERAL STATUS OF DAM:

- 66. Year dam built
- 70. Date last modification completed (mo./yr.) /
- 74. Date of last inspection (mo./yr.) /
- 78. General condition of dam
- 79. Note or remark
- 80. Card number **2**

APPENDIX C
DETAIL PHOTOGRAPHS



PLAN



PHOTO LOCATION PLAN

JAMES V. TURNER
RESERVOIR DAM

SHEET C-1



Photo 1 - Upstream slope from left abutment.
(11-20-80)



Photo 2 - Upstream slope of West Dike.(11-20-80)

US ARMY ENGINEER DIV. NEW ENGLAND
CORPS OF ENGINEERS
WALTHAM, MASS

CAHN ENGINEERS INC.
WALLINGFORD, CONN.
ENGINEER

NATIONAL PROGRAM OF
INSPECTION OF
NON-FED. DAMS

James V. Turner Res. Dam
Ten Mile River
East Providence, RI
CE# 27785 KG
DATE Jan. 1981 PAGE C-1



Photo 3 - Top of West Dike. (10-8-80)




Photo 4 - Spillway and earth dam.(11-20-80)

US ARMY ENGINEER DIV. NEW ENGLAND
CORPS OF ENGINEERS
WALTHAM, MASS

CAHN ENGINEERS INC.
WALLINGFORD, CONN.
ENGINEER

NATIONAL PROGRAM OF
INSPECTION OF
NON-FED. DAMS

James V. Turner Res. Dam
Ten Mile River
East Providence, RI
CE# 27 785 KG
DATE Jan. 1981 PAGE C-2




Photo 5 - Separation and displacement of left spillway training wall.(11-20-80)



Photo 6 - Deterioration of downstream end of right spillway training wall.(11-20-80)

US ARMY ENGINEER DIV. NEW ENGLAND
CORPS OF ENGINEERS
WALTHAM, MASS.

CAHN ENGINEERS INC.
WALLINGFORD, CONN.
ENGINEER

NATIONAL PROGRAM OF
INSPECTION OF
NON-FED. DAMS

James V. Turner Res. Dam
Ten Mile River
East Providence, RI
CE# 27 785 KG
DATE Jan. 1981 PAGE C-3



Photo 7 - Backchannel at toe of earth dam. (11-20-80)




Photo 8 - Gatehouse and outlet structure. (11-20-80)

US ARMY ENGINEER DIV. NEW ENGLAND
CORPS OF ENGINEERS
WALTHAM, MASS.

CAHN ENGINEERS INC.
WALLINGFORD, CONN
ENGINEER

NATIONAL PROGRAM OF
INSPECTION OF
NON-FED. DAMS

James V. Turner Res. Dam
Ten Mile River
East Providence, RI
CE# 27 785 KG
DATE Jan.1981 PAGE C-4

APPENDIX D
HYDRAULICS/HYDROLOGIC COMPUTATIONS

MAXIMUM PROBABLE FLOOD INFLOWS
NED RESERVOIRS

<u>Project</u>	<u>Q</u> (cfs)	<u>D.A.</u> (sq. mi.)	<u>MPF</u> cfs/sq. mi.
1. Hall Meadow Brook	26,600	17.2	1,546
2. East Branch	15,500	9.25	1,675
3. Thomaston	158,000	97.2	1,625
4. Northfield Brook	9,000	5.7	1,580
5. Black Rock	35,000	20.4	1,715
6. Hancock Brook	20,700	12.0	1,725
7. Hop Brook	26,400	16.4	1,610
8. Tully	47,000	50.0	940
9. Barre Falls	61,000	55.0	1,109
10. Conant Brook	11,900	7.8	1,525
11. Knightville	160,000	162.0	987
12. Littleville	98,000	52.3	1,870
13. Colebrook River	165,000	118.0	1,400
14. Mad River	30,000	18.2	1,650
15. Sucker Brook	6,500	3.43	1,895
16. Union Village	110,000	126.0	873
17. North Hartland	199,000	220.0	904
18. North Springfield	157,000	158.0	994
19. Ball Mountain	190,000	172.0	1,105
20. Townshend	228,000	106.0(278 total)	820
21. Surry Mountain	63,000	100.0	630
22. Otter Brook	45,000	47.0	957
23. Birch Hill	88,500	175.0	505
24. East Brimfield	73,900	67.5	1,095
25. Westville	38,400	99.5(32 net)	1,200
26. West Thompson	85,000	173.5(74 net)	1,150
27. Hodges Village	35,600	31.1	1,145
28. Buffumville	36,500	26.5	1,377
29. Mansfield Hollow	125,000	159.0	786
30. West Hill	26,000	28.0	928
31. Franklin Falls	210,000	1000.0	210
32. Blackwater	66,500	128.0	520
33. Hopkinton	135,000	426.0	316
34. Everett	68,000	64.0	1,062
35. MacDowell	36,300	44.0	825

PRELIMINARY GUIDANCE
FOR ESTIMATING
MAXIMUM PROBABLE DISCHARGES
IN
PHASE I DAM SAFETY
INVESTIGATIONS

New England Division
Corps of Engineers

March 1978

Project NON-FEDERAL DAMS INSPECTION Sheet D-11 of 11
 Prepared By HU Checked By GAB Date 12/12/80
 Book Ref. _____ Other Refs. CE # 27-785-HB Revisions 4/17/81 HU

JAMES V. TURNER RESERVOIR DAM

IV) SUMMARY

1) TEST FLOOD = PMF = 24000 cfs
 (PARALLEL COMPUTATIONS HAVE BEEN MADE FOR $\frac{1}{2}$ PMF = 12000 cfs AND ARE ALSO SUMMARIZED BELOW)

2) PERFORMANCE AT PEAK FLOOD CONDITIONS:

- a) PEAK INFLOWS: $Q_P = \text{PMF} = 24000 \text{ cfs}$ $Q'_P = \frac{1}{2} \text{ PMF} = 12000 \text{ cfs}$
 b) PEAK OUTFLOWS: $Q_B = 22600 \text{ cfs}$ $Q'_B = 11000 \text{ cfs}$
 c) SPILLWAY CAPACITY: (SEE TABLE P. D-6)
 d) PERFORMANCE:
 (i) AT TEST FLOOD: OVERTOPPED (DAM) (*) 2.0' (W.S. ELEV. 53' NGVD)
 (ii) AT $\frac{1}{2}$ PMF: OVERTOPPED (DAM) (*) 0.6' (W.S. ELEV. 51.6' NGVD)

3) DOWNSTREAM FAILURE CONDITIONS:

- a) PEAK FAILURE OUTFLOW: $Q_{P1} = 54800 \text{ cfs}$
 b) FLOOD DEPTH IMMEDIATELY $\frac{1}{2}$ S FROM DAM: $Y_0 = 11.6'$
 c) CONDITIONS NEAR PAWTUCKET AVE. (SITE # 114) - ((*) 6000' $\frac{1}{2}$ S FROM DAM)
 (i) STAGE BEFORE FAILURE: $Y_1 = 5.5'$ ($Q_1 = 8300 \text{ cfs}$)
 (ii) STAGE AFTER FAILURE: $Y_2 = 9.1'$ ($Q_2 = 28900 \text{ cfs}$)
 (iii) RAISE IN STAGE AFTER FAILURE: $\Delta Y = 3.6'$
 d) CONDITIONS NEAR NORTH BROADWAY - ((*) 7500' $\frac{1}{2}$ S FROM DAM)
 (i) STAGE BEFORE FAILURE: $Y_1 = 5.5'$ ($Q_1 = 8300 \text{ cfs}$)
 (ii) STAGE AFTER FAILURE: $Y_2 = 8.1'$ ($Q_2 = 22000 \text{ cfs}$)
 (iii) RAISE IN STAGE AFTER FAILURE: $\Delta Y = 2.6'$

*NOTE: EAST DINE #2 OVERTOPPED BY (i) 3.0' AT TEST FLOOD AND (ii) 1.6' AT $\frac{1}{2}$ PMF

Project NON-FEDERAL DAMS INSPECTION Sheet D-10 of 11
Computed By YSL Checked By GAB Date 12/12/80
Field Book Ref. _____ Other Refs. CE # 27-785-HB Revisions _____

JAMES V. TURNER RESERVOIR DAM

III) SELECTION OF TEST FLOOD

1) CLASSIFICATION OF DAM ACCORDING TO NED-ACE GUIDELINES:

a) SIZE: * STORAGE (MAX) ≈ 3100 AC-FT (1000 < S < 50000 AC-FT)
* HEIGHT (MAX) $\approx 22'$ (H < 25 FT)

* STORAGE: SEE P. D-5 ; HEIGHT: SEE P. D-7

∴ SIZE CLASSIFICATION: INTERMEDIATE

b) HAZARD POTENTIAL: AS A RESULT OF THE P/C FAILURE ANALYSIS AND IN VIEW OF THE IMPACT THAT FAILURE OF J.V. TURNER RES. DAM MAY HAVE ON THE POTENTIAL IMPACT AREA (P. D-7), THE DAM IS CLASSIFIED AS HAVING:

HAZARD CLASSIFICATION: HIGH

2) TEST FLOOD: PMF = 24000 CFS

THIS SELECTION IS BASED ON THE RESULTS OF THE PREVIOUS ANALYSIS AND CLASSIFICATION.

Project NON-FEDERAL DAMS INSPECTION Sheet D-9 of 11
 Computed By WLL Checked By GATB Date 12/11/80
 Field Book Ref. _____ Other Refs. CE # 27-785-HB Revisions 4/17/81 WLL

b) RESERVOIR STORAGE AT TIME OF FAILURE:

$$S_{2.51} = 3100 \text{ AC-FT} \quad (\text{SEE P. D-5}) \quad S_{1/2} = 1550 \text{ AC-FT}$$

c) APPROXIMATE STAGE AT POTENTIAL IMPACT AREAS AFTER FAILURE:

$$Q_p = 54800 \text{ CFS}; \quad V_1 = 11.6'; \quad V_2 = 3800 \text{ AC-FT} > S_{1/2} \text{ ON REACH } L = 10000'$$

∴ SUBDIVIDE THE REACH TO HAVE $V = S_{1/2}$ (SEE NED-ACE GUIDELINES)

REACH L (FT)	Q_p (CFS)	Y_1 (FT)	V_1 (ACFT)	Q_{p2} (CFS)	Y_2 (FT)	V_2 (ACFT)	\bar{V} (ACFT)	Q_{p3} (CFS)	Y_3 (FT)
2000	54800	11.6	770	41200	10.4	620	690	42500	10.5
2000	42500	10.5	640	33800	9.6	540	590	34500	9.7
2000	34500	9.7	540	28500	9.0	470	510	28900	9.1
3500	28900	9.1	830	21100	8.0	660	745	22000	8.1

d) APPROXIMATE STAGE BEFORE FAILURE:

$$Q_s = 8300 \text{ CFS} \quad (\text{SEE P. D-6 \& D-8}) \quad H_s = 5.5'$$

e) RAISE IN STAGE Q/s FROM S.Y. TURNER RES. DAM:

DEPENDING ON THE LOCATION ALONG THE RIVER WITHIN THE POTENTIAL IMPACT AREA THE RAISE IN STAGE UPON FAILURE OF S.Y. TURNER RES. DAM IS ESTIMATED TO BE BETWEEN (1) 6' AT THE DAM AND (2) 4' TO 3' AT THE REACH Q/s FROM PAWTUCKET AVE (DIE # 114)

Project NON-FEEDING DAM INSPECTION Sheet D-8 of 11
 Computed By JH Checked By GAB Date 12/11/80
 Field Book Ref. _____ Other Refs. CE # 27-785-HB Revisions 4/17/81 KLL

c) BREACH WIDTH (SEE NED-ACE $\frac{1}{2}$ FAILURE GUIDELINES)

$$W = 0.4 \times 670 = 268' \quad \text{ASSUME } W_b = \underline{268'}$$

d) ASSUMED WATER DEPTH AT TIME OF FAILURE: $Y_0 = 22'$ (ELEV. 51' TO ELEV. 29')

e) SPILLWAY DISCHARGE AT TIME OF FAILURE: $Q_s = 3300 \text{ cfs}$ (SEE P. D-6)

f) BREACH OUTFLOW (SEE NED-ACE GUIDELINES)

$$Q_b = \frac{8}{27} W_b \sqrt{g} Y_0^{3/2} = 46500 \text{ cfs}$$

g) PEAK FAILURE OUTFLOW (Q_p) TO TEN MILE RIVER

$$Q_p = Q_s + Q_b = \underline{54800 \text{ cfs}}$$

3) FLOOD DEPTH * IMMEDIATELY $\frac{1}{2}$ FROM DAM:

$$Y = 0.44 Y_0 = \underline{9.7'}$$

*(FROM RETREATING WAVE THEORY APPLIED TO DAM FAILURE)

4) ESTIMATE OF $\frac{1}{2}$ FAILURE CONDITIONS AT POTENTIAL IMPACT AREAS:

(SEE NED-ACE GUIDELINES FOR ESTIMATING $\frac{1}{2}$ FAILURE HYDROGRAMS)

a) THE CHANNEL $\frac{1}{2}$ FROM J. V. TURNER RES. DAM IS IN AVERAGE, TRAPEZOIDAL IN CROSS SECTION WITH (\pm) 100' BASE AND (\pm) 80" AND 150" TO 1" SIDE SLOPES. THE AVE. SLOPE OF THE CHANNEL IS (\pm) 0.11% (ASSUME $n = 0.050$ FOR THE RIVER AT FLOOD STAGE).

Project NON-FEDERAL DAMS INSPECTION Sheet D-7 of 11
 Computed By JH Checked By GMB Date 12/11/80
 Field Book Ref. _____ Other Refs. CE #27-785-HB Revisions 4/17/81 KPL

JAMES V. TURNER RESERVOIR DAM.

II) DOWNSTREAM FAILURE HAZARD

1) POTENTIAL IMPACT AREA

MANY HOUSES OF WHICH AT LEAST TEN HAVE FIRST FLOOR ELEVATIONS BETWEEN 5' AND 10' ABOVE THE STREAM; INDUSTRIAL AND COMMERCIAL STRUCTURES, ALL WITH FIRST FLOORS LESS THAN (1) 12' ABOVE THE STREAM, ARE LOCATED ALONG THE TEN MILE RIVER IN THE (2) 12000' LONG REACH BETWEEN THE J.V. TURNER RES. DAM AND ITS CONFLUENCE WITH THE SEEKONK RIVER. THIS TEN MILE RIVER REACH, PARTICULARLY 1/2 FROM PAWUCKET AVE. (ETS #114), CONSTITUTE THE POTENTIAL INITIAL IMPACT AREA IN CASE OF FAILURE OF J.V. TURNER RESERVOIR DAM.

NO DATA IS AVAILABLE AS TO DETERMINE THE ACTUAL IMPACT WHICH FAILURE OF EITHER ONE OF THE EAST DIKES MAY HAVE ON THE LEDGE ROAD/ARCADE AVE. AREA. HOWEVER, THE CONTOURS ON THE U.S.G.S. EAST PROVIDENCE, MASS.-R.I. QUADRANGLE SHOW ALL THE TERRAIN BETWEEN THE DIKES AND THE RUNNING RIVER TO BE IN GENERAL ABOVE ELEVATION 50' NGVD AND THEREFORE, FAILURE OF THESE DIKES WITH TOP ELEVATIONS OF 48' AND 48' NGVD, WOULD NOT SEEM TO HAVE OTHER THAN A RELATIVELY LOW FLOODING EFFECT OVER THIS POTENTIAL IMPACT AREA.

2) FAILURE AT J.V. TURNER RESERVOIR DAM.

ASSUME SURCHARGE TO TOP OF DAM (ELEV. 51' NGVD)

a) HEIGHT OF DAM* $H_{max} = 22'$ (TOP OF DAM ELEV. 51' NGVD - TOE OF EMBANKMENT AT OLD STREAMBED (2) ELEV. 29' NGVD)

b) MID-HEIGHT LENGTH* : $L = 670'$

* FROM "EAST PROVIDENCE RESERVOIR - CONTRACT No. 1 - SHEET 2" DRAWING, DATED MARCH 1934.

Project NON-FEDERAL DAM INSPECTION Sheet D-6 of 11
 Computed By JLU Checked By GAB Date 12/11/80
 Field Book Ref. _____ Other Refs. CE #27-785-NB Revisions _____

(iii) PEAK OUTFLOWS (Q_p & Q_p')

$Q_p = 22600 \text{ cfs}$ $H_3 = 7.0'$ (Elev. 53.0' NGVD)

$Q_p' = 11000 \text{ cfs}$ $H_3' = 5.6'$ (Elev. 51.6' NGVD)

(DETERMINED ON THE OUTFLOW RATING CURVE (P.D.-A) BY USING THE APPROX. ROUTING NED-ACE GUIDELINES "SURCHARGE STORAGE ROUTING" ALTERNATE METHOD AND 19" MAX. PROBABLE R.O. IN NEW ENGLAND).

*SEE EXAMPLE BELOW

3) SPILLWAY CAPACITY RATIO TO PEAK CONDITIONS:

SPILLWAY CAPACITY TO:	SURCH* H (FT)	W.S. ELEV. (FT-NGVD)	SPILLWAY CAPACITY (CFS)	SPILLWAY CAPACITY AS % OF PEAK OUTFLOWS	
				Q_p (22600 cfs)	Q_p' (11000 cfs)
LOW POINT**	2.0	48.0	2100	9.3	19
TOP OF DAM	5.0	51.0	8300	37	75
1/2 PHF	5.6	51.6	9800	—	87
PHF	7.0	53.0	13700	61	—

*SURCHARGE ABOVE SPILLWAY CREST (ELEV. 46' NGVD)

**OVERTOPPING OF EAST DIKE #2 (SEE PP. D-2 & D-3) CAUSING LOCAL FLOODING WITH NO OR NEGLIGIBLE OVERFLOW TOWARDS RUNNING RIVER.

EXAMPLE OF PEAK OUTFLOW DETERMINATION:

1) FOR HYPOTHETICAL SURCHARGES $H_a = 8.5'$ AND $H_b = 4.5'$:

$K_a = 3580 \text{ acft} ; S_a = 1.40'' ; (Q_p)_a = 22200 \text{ cfs}$ $Q_p = Q_p' (1 - \frac{S}{19})$
 $K_b = 1560 \text{ acft} ; S_b = 0.61'' ; (Q_p)_b = 23200 \text{ cfs}$

2) INTERSECT OF LINE $(Q_p)_a$ W/ RATING CURVE (P.D.-A) DETERMINES Q_p AND H_3

Project NON-FEDERAL DAMS INSPECTION

Sheet D-5 of 11

Computed By HU

Checked By GAB

Date 12/10/80

Field Book Ref. _____


Other Refs. CE#27-785-HB

Revisions _____

INVENTORY OF DAMS, LISTS ONLY THE AREA ($\pm 122^{AC}$) AND STORAGE CAPACITY ($\pm 732^{AC-Ft}$) OF THE RESERVOIR, SOUTH FROM NEWMAN AVE., AS THOSE OF THE J.V. TURNER RESERVOIR DAM (RI DAM #407).

BECAUSE THE PRESENT EXTENT OF SEPARATION BETWEEN THE TWO WATER BODIES IS UNKNOWN AND BECAUSE THE ROAD EMBANKMENT IS A MAN-MADE STRUCTURE WHOSE STRUCTURAL CONDITION TO WITHSTAND A DIFFERENTIAL HEAD IS UNKNOWN, IT WILL BE ASSUMED THAT THE TWO WATER BODIES ARE A SINGLE IMPOUNDMENT FORMED BY THE J.V. TURNER RES. DAM, WITH NO CONTROL/REGULATION AT NEWMAN AVE.


iii) LAKE AREA/STORAGE CURVES - J.V. TURNER RESERVOIR



△ DATA FROM R.I. DEPT. OF PUBLIC WORKS, DIV. OF HARBORS AND RIVERS - "NOTES IN EAST RIVER W. WORKS DAM #407", DATED 6/30/49
 ○ AREAS MEASURED ON USGS EAST PROVIDENCE, MASS. - RI QUADRANGLE SHEET (1971)
 * SEE NOTE P. D-2

Project NON-FEDERAL DAMS INSPECTION Sheet D-4 of 11
 Computed By HLL Checked By GATB Date 12/10/80
 Field Book Ref. _____ Other Refs. CE # 27-785-HB Revisions _____

(ii) JAMES V. TURNER RESERVOIR DAM - OUTFLOW RATING CURVE:



* SEE NOTE P. D-2

** EAST DIKES OVERFLOW NOT INCLUDED. SEE P.P. D-2 & D-3

b) SURCHARGE DEPTHS TO PAUL PEAK INFLOWS (Q_p & Q'_p)

i) @ $Q_p \approx PMF = 24000 \text{ CFS}$ $H_1 \approx 7.2'$

ii) @ $Q'_p \approx \frac{1}{2} PMF = 12000 \text{ CFS}$ $H'_1 \approx 5.7'$

c) EFFECT OF SURCHARGE STORAGE - PEAK OUTFLOWS

i) WATERSHED D.A. = 48.0 sq mi (SEE P. D-1)

ii) LAKE AREA / STORAGE

J.V. TURNER RESERVOIR AND CENTRAL POND ACTUALLY FORM A SINGLE RESERVOIR DIVIDED BY AN EMBANKMENT CROSSING (PROBABLY A PORTION OF THE ORIGINAL CENTRAL POND DAM) AT NEWMAN AVE. THE TOTAL AREA ($\approx 278 \text{ AC}$), AND STORAGE CAPACITY ($\approx 425 \text{ MG}$) OF THE TWO WATER BODIES ARE LISTED AS TURNER'S ON THE R.I. D.P.W., DIV. OF HARBORS AND RIVERS DATA SHEET "NOTES IN EAST PROY. W. WORKS DAM # 207" DATED 6/20/1900. SAVED DATE THE P.T. (1911)

Project NON-FEDERAL DAMS INSPECTION Sheet D-3 of 11
 Computed By WLL Checked By GAB Date 12/10/80
 Field Book Ref. _____ Other Refs. CE #27-785-NB Revisions _____

IS EXPECTED THROUGH THIS AREA FOR RESERVOIR LEVELS BELOW (*) ELEV. 53' NAVD.
 CONSEQUENTLY, IT IS ASSUMED THAT NO OVERFLOW (ONLY FLOODING OF CONFINED AREAS) WILL RESULT FROM OVERTOPPING OF THE EAST DIKES WITHIN THE RANGE OF EXPECTED SURCHARGES.

(i) THEREFORE, THE OVERFLOW RATING CURVE FOR SURCHARGES (H) ABOVE THE SPILLWAY CREST CAN BE APPROXIMATED AS FOLLOWS:

1') SECTION AB: $Q_{AB}^* = 0.4 \times 3 \times 2.0 (H-5)^{5/2} = \underline{2.4 (H-5)^{5/2}}$

2') SECTION BC (DAM): $Q_{BC} = 2.7 \times 560 (H-5)^{3/2} = \underline{1510 (H-5)^{3/2}}$

3') SPILLWAY (SECTION DE):

$$Q_S = Q_{DE} = 3.7 \times 200 H^{3/2} = \underline{740 H^{3/2}}$$

4') SECTION FG (RIGHT-SIDE DIKE):

$$Q_{FG} = 3.0 \times 770 (H-5)^{3/2} = \underline{1540 (H-5)^{3/2}}$$

5') SECTION GH: $Q_{GH} = 0.1 \times 28 \times 2.0 (H-5)^{5/2} = \underline{22.4 (H-5)^{5/2}}$

THE TOTAL OVERFLOW RATING CURVE IS APPROXIMATED BY THE SUM OF ALL THE APPLICABLE FORMULAE ON ITEMS (1') THRU (5').

$$Q = 740 H^{3/2} + 3050 (H-5)^{3/2} + 24.8 (H-5)^{5/2}$$

(SEE PLOT ON P. D-4)


*NOTE: FLOW OVER SLOPED SECTIONS BY APPLICATION OF FORMULA GIVEN BY THE USGS ON "MEASUREMENT OF PEAK DISCHARGE AT DAMS BY INDIRECT METHODS" BY HULSING (APPLICATIONS OF HYDRAULICS).

$$Q = \frac{2cb}{5(h_2 - h_1)} \left[h_1^{5/2} - h_2^{5/2} \right] \quad \text{WHERE: } Q = \text{DISCH.}; c = \text{DISCH. COEFF.}; b = \text{LENGTH}; h_2 \text{ \& } h_1 = \text{STATIC HEAD REFERRED TO HIGH \& LOW ENDS OF CURVE, RESPECTIVELY.}$$

Project NON-FEDERAL DAMS INSPECTION Sheet D-2 of 11
 Computed By [Signature] Checked By GBB Date 12/9/80
 Field Book Ref. _____ Other Refs. CE#27-785-H3 Revisions _____

DAM AND DIKES. TOP OF DAM AND ADJACENT WEST (RIGHT) DIKE AT (±) ELEV. 51' NGVD. (SEE OVERFLOW PROFILE). EAST DIKE #1 (AT LEDGE ROAD) (±) 550' LONG WITH ADJACENT TERRAIN AT (±) 16" AND 13" TO 1" SLOPE. EAST DIKE #2 (SOUTH FROM ARCADE AVE.), (±) 350' LONG WITH ADJACENT TERRAIN AT (±) 60" AND 15" TO 1" SLOPE. TOP ELEV. OF EAST DIKES #1 AND #2 ASSUMED TO BE ELEV. 48' NGVD AND 48' NGVD, RESPECTIVELY, AS SHOWN ON "EAST PROVIDENCE RESERVOIR - CONTRACT NO. 1 - SHEET NO. 1" DRAWING, DATED MARCH, 1934.

ASSUME $C=3.7$ FOR THE SPILLWAY DISCHARGE, $C=2.7$ FOR THE DAM AND $C=2.0$ FOR THE DIKES AND ADJACENT TERRAIN OVERFLOW.



NOTE: DATA FROM C.E. OBSERVATIONS ON 10/8/80 BY [Signature] & F.S.

JAMES V. TURNER RESERVOIR DAM
APPROXIMATE OVERFLOW PROFILE

NO DETAILED SURVEY OF THE TERRAIN EXTENDING TO THE EAST (LEFT) OF THE RESERVOIR NEAR ARCADE AVE AND LEDGE ST. IS AVAILABLE * TO DETERMINE WHETHER OVERFLOW TOWARDS RUNNING RIVER WILL RESULT FROM THE OVERLAPPING OF THE EAST DIKES. HOWEVER, EXCEPT FOR SHALL, POCKET DEPRESSIONS, THE U.S.G.S. EAST PROVIDENCE, MASS. - R.I. QUADRANGLE (1971) SHOWS ALL EXISTING TERRAIN ALONG THE EAST (LEFT) SHORE OF THE RESERVOIR ABOVE ELEVATION 50' NGVD AND THEREFORE, NO OR NEGLIGEABLE OVERFLOW

*NOTE: SPILLWAY CREST ELEVATION 46' AS SHOWN ON "EAST PROVIDENCE RESERVOIR - CONTRACT NO. 1" DWGS (SWEETS NO. 1 TO 4), DATED MARCH 1934 AND OTHER DATA SOURCE: BY THE F.S. DEPT. OF PUBLIC WORKS, DIV. OF HARBORS AND RIVERS, IS ASSUMED TO BE ON NATIONAL GEODETIC VERTICAL DATUM (NGVD).

Project INSPECTION OF NON-FEDERAL DAMS IN NEW ENGLAND Sheet D-1 of 11
 Computed By HLL Checked By GAB Date 12/8/50
 Field Book Ref. _____ Other Refs. CE # 27-785-HB Revisions _____

HYDROLOGIC/HYDRAULIC INSPECTION

JAMES V. TURNER RESERVOIR DAM, EAST PROVIDENCE, R.I.

1) PERFORMANCE AT PEAK FLOOD CONDITIONS:

1) PROBABLE MAXIMUM FLOOD (PMF)

a) WATERSHED CLASSIFIED AS "FLAT AND COASTAL", TYPICALLY CONTAINING LARGE SWAMPS AND IMPOUNDMENTS (FAIRFORD POND, MANCHESTER POND RES., GREENWOOD LAKE AND DODGEVILLE POND)

b) WATERSHED AREA: $DA = 48.0$ sq. mi

NOTE: D.A. FROM R.I. DEPARTMENT OF PUBLIC WORKS, DIVISION OF HARBORS AND RIVERS, NOTES IN EAST PROV. W. WORKS DAM #407 DATED 6/30/49 AND DAM INVENTORY. IT IS NOTED HOWEVER, THAT THE 1932-1927 TEN MILE RIVER R.O. DATA AT CENTRAL POND DAM (OLD DAM $\frac{1}{2}$ FROM J.V. TURNER DAM) SHOWS D.A. 52.3 sq. mi. (USE MORE RECENT DATA DA=48)

c) PEAK FLOODS (FROM NED-ACE GUIDELINES - GUIDE CURVES FOR PMF):

i) FROM GUIDE CURVES: $CSM = 500$ cfs/sq. mi

ii) $PMF = 48.0 \times 500 = 24000$ cfs

iii) $\frac{1}{2} PMF = 12000$ cfs


2) SURCHARGE AT PEAK INFLOWS (PMF AND $\frac{1}{2}$ PMF)

a) OUTFLOW RATING CURVE:

c) SPILLWAY AND OVERFLOW PROFILE OF DAM

OSFE TYPE, SPILLWAY (+) 200' LONG WITH REST ELEV. *46' NGVD. EARTH FILL

*FROM R.I. DEPT. OF PUBLIC WORKS, DIV. OF HARBORS & RIVERS DATA AND DWGS. - SEE NOTE p. D-2



APPROXIMATE LIMITS OF FAILURE OUTFLOW

INITIAL IMPACT AREA


JAMES V. TURNER RESERVOIR DAM

CAMN ENGINEERS INC. WALLINGFORD CONNECTICUT ENGINEER		U.S. ARMY ENGINEER DIV. NEW ENGLAND CORPS OF ENGINEERS WALTHAM, MASS.	
NATIONAL PROGRAM OF INSPECTION OF NON-FED. DAMS DAM FAILURE IMPACT AREA MAP JAMES V. TURNER RESERVOIR DAM			
TEN MILE RIVER		PROVIDENCE, R.I.	
DWN. BY	CKD. BY	APP. BY	SCALE: 1"=2000'
RJB	TJK	pmh	DATE: JAN., 1981 SHEET D-2

MAXIMUM PROBABLE FLOWS
BASED ON TWICE THE
STANDARD PROJECT FLOOD
(Flat and Coastal Areas)

<u>River</u>	<u>SPF</u> (cfs)	<u>D.A.</u> (sq. mi.)	<u>MPF</u> (cfs/sq. mi.)
1. Pawtuxet River	19,000	200	190
2. Mill River (R.I.)	8,500	34	500
3. Peters River (R.I.)	3,200	13	490
4. Kettle Brook	8,000	30	530
5. Sudbury River.	11,700	86	270
6. Indian Brook (Hopk.)	1,000	5.9	340
7. Charles River.	6,000	184	65
8. Blackstone River.	43,000	416	200
9. Quinebaug River	55,000	331	330

ESTIMATING EFFECT OF SURCHARGE STORAGE ON MAXIMUM PROBABLE DISCHARGES



STEP 1: Determine Peak Inflow (Q_{p1}) from Guide Curves.

STEP 2: a. Determine Surcharge Height To Pass " Q_{p1} ".

b. Determine Volume of Surcharge ($STOR_1$) In Inches of Runoff.

c. Maximum Probable Flood Runoff In New England equals Approx. 19", Therefore:


$$Q_{p2} = Q_{p1} \times \left(1 - \frac{STOR_1}{19}\right)$$

STEP 3: a. Determine Surcharge Height and " $STOR_2$ " To Pass " Q_{p2} "

b. Average " $STOR_1$ " and " $STOR_2$ " and Determine Average Surcharge and Resulting Peak Outflow " Q_{p3} ".

MAXIMUM PROBABLE FLOOD PEAK FLOW RATES

x 5 - NED DAM IDENTIFICATION
 ⊗ 7' - TWICE SPF AT INDICATED SITES
 DEC. 1977



SURCHARGE STORAGE ROUTING SUPPLEMENT

**STEP 3: a. Determine Surcharge Height and
"STOR₂" To Pass "Q_{p2}"**

**b. Avg "STOR₁" and "STOR₂" and
Compute "Q_{p3}".**

**c. If Surcharge Height for Q_{p3} and
"STOR_{AVG}" agree O.K. If Not:**

**STEP 4: a. Determine Surcharge Height and
"STOR₃" To Pass "Q_{p3}"**

**b. Avg. "Old STOR_{AVG}" and "STOR₃"
and Compute "Q_{p4}"**

**c. Surcharge Height for Q_{p4} and
"New STOR_{AVG}" should Agree
closely**

SURCHARGE STORAGE ROUTING ALTERNATE

$$Q_{p2} = Q_{p1} \times \left(1 - \frac{\text{STOR}}{19} \right)$$


$$Q_{p2} = Q_{p1} - Q_{p1} \left(\frac{\text{STOR}}{19} \right)$$

FOR KNOWN Q_{p1} AND 19" R.O.


Q_{p2}
=====

STOR
=====

EL.
=====



"RULE OF THUMB" GUIDANCE FOR ESTIMATING DOWNSTREAM DAM FAILURE HYDROGRAPHS



STEP 1: DETERMINE OR ESTIMATE RESERVOIR STORAGE (S) IN AC-FT AT TIME OF FAILURE.

STEP 2: DETERMINE PEAK FAILURE OUTFLOW (Q_{p1}).

$$Q_{p1} = \frac{8}{27} W_b \sqrt{g} Y_0^{3/2}$$

W_b = BREACH WIDTH - SUGGEST VALUE NOT GREATER THAN 40% OF DAM LENGTH ACROSS RIVER AT MID HEIGHT.

Y_0 = TOTAL HEIGHT FROM RIVER BED TO POOL LEVEL AT FAILURE.

STEP 3: USING USGS TOPO OR OTHER DATA, DEVELOP REPRESENTATIVE STAGE-DISCHARGE RATING FOR SELECTED DOWNSTREAM RIVER REACH.

STEP 4: ESTIMATE REACH OUTFLOW (Q_{p2}) USING FOLLOWING ITERATION.

A. APPLY Q_{p1} TO STAGE RATING, DETERMINE STAGE AND ACCOMPANYING VOLUME (V_1) IN REACH IN AC-FT. (NOTE: IF V_1 EXCEEDS 1/2 OF S, SELECT SHORTER REACH.)

B. DETERMINE TRIAL Q_{p2} .

$$Q_{p2}(\text{TRIAL}) = Q_{p1} \left(1 - \frac{V_1}{S}\right)$$

C. COMPUTE V_2 USING Q_{p2} (TRIAL).


D. AVERAGE V_1 AND V_2 AND COMPUTE Q_{p2} .

$$Q_{p2} = Q_{p1} \left(1 - \frac{V_{\text{avg}}}{S}\right)$$

STEP 5: FOR SUCCEEDING REACHES REPEAT STEPS 3 AND 4.

APRIL 1978

"RULE OF THUMB" GUIDANCE FOR ESTIMATING DOWNSTREAM DAM FAILURE HYDROGRAPHS



STEP 1: DETERMINE OR ESTIMATE RESERVOIR STORAGE (S) IN AC-FT AT TIME OF FAILURE.

STEP 2: DETERMINE PEAK FAILURE OUTFLOW (Q_{p1}).

$$Q_{p1} = \frac{8}{27} W_b \sqrt{g} Y_0^{3/2}$$

W_b = BREACH WIDTH - SUGGEST VALUE NOT GREATER THAN 40% OF DAM LENGTH ACROSS RIVER AT MID HEIGHT.

Y_0 = TOTAL HEIGHT FROM RIVER BED TO POOL LEVEL AT FAILURE.

STEP 3: USING USGS TOPO OR OTHER DATA, DEVELOP REPRESENTATIVE STAGE-DISCHARGE RATING FOR SELECTED DOWNSTREAM RIVER REACH.

STEP 4: ESTIMATE REACH OUTFLOW (Q_{p2}) USING FOLLOWING ITERATION.

A. APPLY Q_{p1} TO STAGE RATING, DETERMINE STAGE AND ACCOMPANYING VOLUME (V_1) IN REACH IN AC-FT. (NOTE: IF V_1 EXCEEDS 1/2 OF S, SELECT SHORTER REACH.)

B. DETERMINE TRIAL Q_{p2} .

$$Q_{p2}(\text{TRIAL}) = Q_{p1} \left(1 - \frac{V_1}{S}\right)$$

C. COMPUTE V_2 USING Q_{p2} (TRIAL).

D. AVERAGE V_1 AND V_2 AND COMPUTE Q_{p2} .

$$Q_{p2} = Q_{p1} \left(1 - \frac{V_{\text{avg}}}{S}\right)$$

STEP 5: FOR SUCCEEDING REACHES REPEAT STEPS 3 AND 4.

APRIL 1978

APPENDIX E
INFORMATION AS CONTAINED IN
THE NATIONAL INVENTORY OF DAMS



INVENTORY OF DAMS IN THE UNITED STATES

STATE	DIVISION	COMPL	CONGR	NAME		REPORT DATE	
RI	0002	01	01	JAMES V TURNER RESERVOIR DAM	45° 07' 12.0" N	120° 55' 00.0" W	NOV 1961

POPULAR NAME	NAME OF IMPOUNDMENT
JAMES V TURNER RESERVOIR	JAMES V TURNER RESERVOIR
REGION BASIN	NEAREST DOWNSTREAM CITY-TOWN-VILLAGE
01 04 TEN MILE RIVER	EAST PROVIDENCE
YEAR COMPLETED	POPULATION
1934	48207

TYPE OF DAM	PURPOSES	STRUCTURAL HEIGHT (FT.)	IMPOUNDING CAPACITIES (ACRES-FT.)	DIST FROM DAM (MI.)
WEIR	HYDRO-ELECTRICITY	60	3100	1

OWNER: STATE OF RHODE ISLAND DIST OWN FED R PROV/FED SCS A VER/DATE


REMARKS	
PI CONCRETE 23 ABANDONED AS WATER SUPPLY 24 APPROXIMATE	
D/S HAS LENGTH	POWER CAPACITY INSTALLED (KW)
1 420 U 200	4300
NAVIGATION LOCKS	
NONE	

OWNER	ENGINEERING BY	CONSTRUCTION BY
E PROVIDENCE WATER WORKS	WATERMAN ENGINEERING CO	UNKNOWN

DESIGN	CONSTRUCTION	OPERATION	MAINTENANCE
NONE	NONE	RI DEM	RI DEM

INSPECTION BY	INSPECTION DATE	AUTHORITY FOR INSPECTION
CANN ENGINEERS INC	20 NOV 60	PL 92-367

REMARKS



U.S.G.S. QUADRANGLES
E. PROVIDENCE, MASS. - R.I. 1971
ATTLEBORO, MASS. - R.I. 1979
WRENTHAM, MASS. 1979

CAHN ENGINEERS INC.
WALLINGFORD, CONNECTICUT
ENGINEER

U.S. ARMY ENGINEER DIV NEW ENGLAND
CORPS OF ENGINEERS
WALTHAM, MASS

NATIONAL PROGRAM OF INSPECTION OF NON-FED DAMS
DRAINAGE AREA MAP

JAMES V. TURNER RESERVOIR DAM

TEN MILE RIVER
DWN BY CKD BY APP BY SCALE 1" = 5000' E. PROVIDENCE, R.I.

R/S JWH DATE JAN. 1981 SHEET D-1


EAST DIKE #2

EAST DIKE #1

TURNER RESERVOIR
DAM




DRAINAGE AREA
48 SQ. MI.




NOTE:









1. DRAWING ON SHEETS B-1, B-2, B-3 & B-4 WERE COMPILED FROM CONSTRUCT DRAWINGS ENTITLED EAST PROVIDENCE RESERVOIR, CONTRACT No. 1-SHEETS 1 THRU 4 BY WATERMAN ENGINEERING CO. DATED MARCH, 1934 & CAHN ENGINEERS INSPECTION OF THE DAM ON NOV. 20, 1980. NOT ALL TOPOGRAPHY AND/OR STRUCTURAL FEATURES ARE NECESSARILY IDENTIFIED.
2. ELEVATIONS WERE TAKEN FROM THE WATERMAN CONSTRUCTION DRAWING DESCRIBED IN NOTE 1. AND ARE ASSUMED TO BE N.G.V.D. SPILLWAY CREST ELEVATION IS 46.0.
3. SOIL PROFILE ALONG CENTERLINE OF DAM SHOWN ON SHEET B-3




CAMN. ENGINEERS INC. WALLINGFORD CONNECTICUT ENGINEER		U.S. ARMY ENGINEER DIV. NEW ENGLAND CORPS OF ENGINEERS WALTHAM, MASS.	
NATIONAL PROGRAM OF INSPECTION OF NON-FED. DAMS			
PLAN			
JAMES V. TURNER RESERVOIR DAM			
TEN MILE RIVER		PROVIDENCE, R.I.	
DWN. BY	CRD. BY	APP. BY	SCALE: AS NOTED
RJB	TK	PH	DATE: JAN., 1981
		SHEET B-2	



21 *Borehole No*
 22 South 20 Reference to E of dam
 Elevation of assumed bed rock

-  Loom & Subsoil
-  Coarse sand
-  Fine sand
-  Gravel
-  Compacted materials
-  Shale
-  Sandstone
-  Conglomerate



F
20

AD-A156 019

NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS
JAMES V TURNER DAM (R. (U) CORPS OF ENGINEERS WALTHAM
MA NEW ENGLAND DIV JAN 81


2/2

UNCLASSIFIED




F/G 13/13

NL

				END
				FILED
				ETC




MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS 1963-A



NOTES:
SEE SHEET B-2.

CAHN ENGINEERS INC WALLINGFORD, CONNECTICUT ENGINEER		U.S. ARMY ENGINEER DIV NEW ENGLAND CORPS OF ENGINEERS WALTHAM, MASS.	
NATIONAL PROGRAM OF INSPECTION OF NON-FED. DAMS			
ELEVATION			
JAMES V. TURNER RESERVOIR DAM			
TEN MILE RIVER		E. PROVIDENCE, R.I.	
DWN BY	CKD BY	APP BY	SCALE AS NOTED
KUB	TJR	AMH	DATE JAN, 1961
		SHEET B-3	

TOP OF DAM EL. 51.0




HORIZ. AND VERTICAL



SECTION THRU



CONC. V



HORIZ. AND VERTICAL



SECTION THRU SPILL



NOTES :
SEE SHEET B-2.

CAMN ENGINEERS INC. WALLINGFORD CONNECTICUT ENGINEER		U.S. ARMY ENGINEER DIV. NEW ENGLAND CORPS OF ENGINEERS WALTHAM, MASS.	
NATIONAL PROGRAM OF INSPECTION OF NON-FED. DAMS			
SECTIONS			
JAMES V. TURNER RESERVOIR DAM			
TEN MILE RIVER		PROVIDENCE, R.I.	
OWN BY	CRD. BY	APP. BY	SCALE: AS NOTED



END

FILMED

8-85

DTIC