F	AD-A15	6 143	NAT Pon New	IONAL D DAM Engli	PROGR (NHOO IND DI	AM FOR 145. (V APR	INSP U) CO 79	ECTION RPS OF	OF NO Engin	N-FED	ERAL D WALTHA	ANS IC	E 1.	/1	¥.
	UNCLAS	SIFIED								1	F/G	13/13	NL		
			5.5												
	4					-									
													15 M		
														- 415 - 415	
e.				.	_										

•	1.0	4.5 5.0 5.0 6.3	2.8 3.2 3.6	2.5	
			4.0	2.0	
	1.25	 	4	1.6	

....

.

ς.

ł

MICROCOPY RESOLUTION TEST CHART NATIONAL BUREAU OF STANDARDS-1963-A



REPORT DOCUMENT	ATION PAGE	READ INSTRUCTIONS BEFORE COMPLETING FORM
REPORT NUMBER	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
NH 00145		
TITLE (and Sublitie)		5. TYPE OF REPORT & PERIOD COVERED
Ice Pond Dam		INSPECTION REPORT
ATIONAL PROGRAM FOR INSPECTIONAL	ON OF NON-FEDERAL	6. PERFORMING ORG, REPORT NUMBER
AUTHOR(a)		S. CONTRACT OR GRANT NUMBER(+)
J.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION		
PERFORMING ORGANIZATION NAME AND	ADDRESS	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
1. CONTROLLING OFFICE NAME AND ADDR	ESS	12. REPORT DATE
DEPT. OF THE ARMY, CORPS OF E	NGINEERS	April 1979
NEW ENGLAND DIVISION, NEDED	00054	13. NUMBER OF PAGES
124 TRAPELO ROAD, WALTHAM, MA	. UZ254	15. SECURITY CLASS (at this monart)
MONITORING AGENCY NAME & ADDRESS	It different from Centrolling Office)	15. SECURITY CLASS. (Dr Inte report)
		UNCLASSIFIED
DISTRIBUTION STATEMENT (of this Report APPROVAL FOR PUBLIC RELEASE:	DISTRIBUTION UNLIMITED	UNCLASSIFICATION/DOWNGRADING
DISTRIBUTION STATEMENT (of the Report APPROVAL FOR PUBLIC RELEASE: 1 7. DISTRIBUTION STATEMENT (of the observe	DISTRIBUTION UNLIMITED	UNCLASSIFIED
APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION STATEMENT (of the observed) DISTRIBUTION STATEMENT (of the observed) SUPPLEMENTARY NOTES Cover program reads: Phase I however, the official title o Non-Federal Dams; use cover	DISTRIBUTION UNLIMITED an encored in Diock 20, 11 different fre Inspection Report, Nati f the program is: Natic date for date of report	UNCLASSIFIED 15. DECLASSIFICATION/DOWNGRADING SCHEDULE onal Dam Inspection Program; onal Program for Inspection of
APPROVAL FOR PUBLIC RELEASE: APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION STATEMENT (of the ebetree Cover program reads: Phase I however, the official title o Non-Federal Dams; use cover DAMS, INSPECTION, DAM SAFET	DISTRIBUTION UNLIMITED an encored in Diock 20, 11 different fre Inspection Report, Nati f the program is: Natic date for date of report Y,	UNCLASSIFIED 15. DECLASSIFICATION/DOWNGRADING SCHEDULE m Report) onal Dam Inspection Program; onal Program for Inspection of
APPROVAL FOR PUBLIC RELEASE: APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION STATEMENT (of the observed Cover program reads: Phase I however, the official title o Non-Federal Dams; use cover KEY WORDS (Continue on reverse side 11 net DAMS, INSPECTION, DAM SAFET Connecticut River Basin Littleton, New Hampshire Alder Brook	DISTRIBUTION UNLIMITED is encored in Diock 20, 16 different fre Inspection Report, Nati f the program is: Natic date for date of report	UNCLASSIFIED 15. DECLASSIFICATION/DOWNGRADING SCHEDULE m Report) onal Dam Inspection Program; onal Program for Inspection of
APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION STATEMENT (of the observed) DISTRIBUTION STATEMENT (of the observed) Supplementary notes Cover program reads: Phase I however, the official title o Non-Federal Dams; use cover KEY WORDS (Continue on reverse olde 11 not DAMS, INSPECTION, DAM SAFET Connecticut River Basin Littleton, New Hampshire Alder Brook	DISTRIBUTION UNLIMITED an encored in Dieck 20, if different free Inspection Report, Nati f the program is: Natic date for date of report concery and identify by block number; Y,	UNCLASSIFIED 18. DECLASSIFICATION/DOWNGRADING SCHEDULE onal Dam Inspection Program; onal Program for Inspection of

DD 1 JAN 73 1473 EDITIC DE 1 NOV 63 IS OBSOLETE

DISCLAIMER NOTICE

THIS DOCUMENT IS BEST QUALITY PRACTICABLE. THE COPY FURNISHED TO DTIC CONTAINED A SIGNIFICANT NUMBER OF PAGES WHICH DO NOT REPRODUCE LEGIBLY.



•

DEPARTMENT OF THE ARMY NEW ENGLAND DIVISION, CORPS OF ENGINEERS 424 TRAPELO ROAD WALTHAM, MASSACHUSETTS 02154

REPLY TO ATTENTION OF:

NEDED

OCT 2 1979

Honorable Hugh J. Gallen Governor of the State of New Hampshire State House Concord, New Hampshire 03301

Dear Governor Gallen:

I am forwarding to you a copy of the Ice Pond Dam Phase I Inspection Report, which was prepared under the National Program for Inspection of Non-Federal Dams. This report is presented for your use and is based upon a visual inspection, a review of the past performance and a brief hydrological study of the dam. A brief assessment is included at the beginning of the report. I have approved the report and support the findings and recommendations described in Section 7 and ask that you keep me informed of the actions taken to implement them. This follow-up action is a vitally important part of this program.

A copy of this report has been forwarded to the Water Resources Board, the cooperating agency for the State of New Hampshire. In addition, a copy of the report has also been furnished the owner, Town of Littleton, Municipal Office, Littleton, New Hampshire 03561.

Copies of this report will be made available to the public, upon request, by this office under the Freedom of Information Act. In the case of this report the release date will be thirty days from the date of this letter.

I wish to take this opportunity to thank you and the Water Resources Board for your cooperation in carrying out this program.

Sincerely,

Incl As stated MAX B. SCHEIDER Colonel, Corps of Engineers Division Engineer ICE POND DAM

NH 00145

LITTLETON, NEW HAMPSHIRE

Acces	sion For
NT-7	GPARI A
D 7	
ປັກສາມ	ounced 📋
Justi	fication
By	
Distr	ibution/
Avai	lability Codes
	Avail and/or
Dist	Special /
11	
H/	12 M
\//	VU

PHASE I INSPECTION REPORT NATIONAL DAM INSPECTION PROGRAM

NATIONAL DAM INSPECTION PROGRAM PHASE I INSPECTION REPORT

Identification No:NH00145Name of Dam:Ice Pond DamTown:LittletonCounty and State:Grafton County, New HampshireStream:Alder BrookDate of Inspection:November 14, 1978

BRIEF ASSESSMENT

The Ice Pond Dam is a masonry-earth fill dam with cut stone spillway, 125 feet long and 20 feet high. The dam and impoundment are part of the "Dells" conservation and picnic area. The reservoir surface area is approximately five acres and it drains an area of 3.9 square miles. The water level is controlled by the overflow spillway and there are no other operational outlets.

Based on a size classification of small and a significant hazard classification, in accordance with "Recommended Guidelines for Safety Inspection of Dams, Department of the Army, November 1976" the test flood for this dam is the 100-year exceedance interval storm. The test flood of 1400 CFS overtops the dam by approximately 1.8 feet. The spillway has a capacity of 735 CFS without overtopping which is 52 percent of the test flood.

The dam was judged to be in fair condition. The following significant conditions were observed:

- 1. The downstream spillway training walls are partially collapsed.
- 2. Trees are growing in the earth embankments.
- 3. The downstream wall of the dam is experiencing some deterioration.

A detailed assessment and recommendations for remedial measures are contained in Section 7. In summary, it is recommended that the following actions be taken under the guidance of a qualified engineer within one year of the receipt of this report:

- 1. Reconstruct the spillway training walls.
- 2. Repair the downstream face of the dam.
- 3. Remove the flashboard pins in the spillway.

- 4. Activate the 12-inch drain valve.
- 5. Design and construct increased spillway capacity or stabilization of downstream face to withstand continuous overtopping.

In addition, the owner should implement a systematic maintenance program consisting of the following items:

- 1. Remove trees and brush from the dam embankments and walls as required.
- 2. Remove debris from the reservoir and downstream channel.
- 3. Institute a program of annual periodic technical inspection.
- 4. Institute a formal warning system.





This Phase I Inspection Report on Ice. Pond Dam has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the <u>Recommended Guidelines for Safety Inspection of</u> <u>Dams</u>, and with good engineering judgment and practice, and is hereby submitted for approval.

oh, W, t MEMDER FINECAN. JR. Control Branch ineering Division

A q. Mr Elroy

JOSEPH A. MCELROY, MEMBER Foundation & Materials Branch Engineering Division

arney M. Jozian

CARNEY M/ TERZIAN, CHAIRMAN Chief, Structural Section Design Branch Engineering Division

APPROVAL RECOMMENDED:

JOE B. FRYAR

Chief, Engineering Division

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing and detailed computational evaluations are beyond the scope of a Phase I Investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test Flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

TABLE OF CONTENTS

Sec	tion			Page
Let	ter o	f Tra	ansmittal	
Bri	ef As	sessi	nent	
Rev	iew B	oard	Page	
Pre	face			i
Tab	le of	Cont	tents	ii-iv
0ve	rview	Phot	to	v
Loc	ation	Мар		vi
			REPORT	
1.	PROJ	ECT 1	INFORMATION	
	1.1	Gene	eral	1-1
		-		
		a. b.	Purpose	1-1
	1.2	Desc	cription of Project	1-1
		a.	Location	1-1
		Ъ.	Description of Dam and Appurtenances	1-1
		c.	Size Classification	1-2
		d.	Hazard Classification	1-2
		e.	Ownership	1-2
		f.	Operator	1-2
		g.	Purpose	1-2
		n. 1	Design and Construction History	1-3
		1.	Normal operational procedures	1-3
•	1.3	Pert	tinent Data	1-3
		а.	Drainage Area	1-3
		Ъ.	Discharge at the Dam Site	1-3
		c.	Elevations	1-3
		d.	Reservoir Data	1-4
		e.	Storage	1-4
		I.	Reservoir Surface	1-5
		8. L	Dam Dimension and Due 1 if much	1-5
		п. -	Diversion and Regulating Tunnel	1-6
		4	opiliway Degulating Outlote	1-6
		J •	veRararruk Antrera	1-/

ii

		_	
Section	on	Page	
2. E	NGINEERING DATA		
2	.1 Design	2-1	
2	.2 Construction	2-1	
2	.3 Operation	2-1	
2	.4 Evaluation	2-1	
	a. Availability	2-1	·
	b. Adequacy	2-1 2-1	
2 U		2 1	
J. V	ISUAL INSTRUCTION		_
3	.1 Findings	3-1	
	a. General	3-1	
	 Dam Appurtenant Structures 	3-1	
	d. Reservoir Area	3-2	-
	e. Downstream Channel	3-2	
3	.2 Evaluation	3–2	
4. 0	PERATIONAL PROCEDURES		
4	.1 Procedures	4-1	
4	.2 Maintenance	4-1	
4	.3 Maintenance of Operating Facilities	4-1	
4	.4 Description of Warning System	4-1	
4	.5 Evaluation	4-1	
5. H	YDRAULIC/HYDROLOGIC		
5	.1 Evaluation of Features	5-1	
	a. General	5-1	
	b. Design Data c. Experience Data	5-1 5-1	
	d. Test Flood Analysis	5-1	
	e. Dam Failure Analysis	´ 5 –2	
6. S	TRUCTURAL STABILITY		
6	5.1 Evaluation of Structural Stability	6-1	
	a. Visual Observations	6-1	
	c. Operating Records	6-1	
	d. Post-Construction Changes	6-1	
	e. Seismic Stability	1-0	

Section

Page

7. ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES

7.1	Dam Assessment	/-1
	 a. Condition b. Adequacy of Information c. Urgency d. Need for Additional Investigation 	7-1 7-1 7-1 7-1
7.2	Recommendations -	7-1
7.3	Remedial Measures	7-2
	a. Operation and Maintenance Procedures	7-2
7.4	Alternatives	7-2

APPENDICES

APPENDIX A - V	ISUAL INSPECTION CHECK LIST	A-1
APPENDIX B - P	ROJECT RECORDS AND PLANS	B-1
APPENDIX C - P	PHOTOGRAPHS	C-1
APPENDIX D - H	IYDROLOGIC AND HYDRAULIC COMPUTATIONS	D-1
APPENDIX E - I	INFORMATION AS CONTAINED IN THE NATIONAL INVENTORY OF DAMS	E-1

SECTION 5 - HYDRAULIC/HYDROLOGIC

5.1 Evaluation of Features

a. General

The Ice Pond Dam spillway is a cut stone broad crested weir with upstream and downstream training walls. The spillway functions as a weir until a height of 4.2 feet where the flow contacts the underside of the bridge beams, after which orifice flow will govern.

b. Design Data

There is no known design data concerning the hydraulic and hydrologic features of the Ice Pond Dam.

c. Experience Data

There is no confirmed overtopping of the dam in any of the file data.

d. Test Flood Analysis

The dam is classified as small with a significant hazard classification. Since two homes would be directly impacted by a flood wave resulting from a dam failure, the 100-year exceedance interval flood was selected as the test flood.

The computations of the test flood were carried out using a computer program of the procedures presented in Geological Survey Water-Supply Paper 1580-B, which is a study of the relation of annual peak discharges to hydrologic factors in New England. The input data computations and results are contained in Appendix D of this Report. Since the area contains a significant amount of storage, a flow reduction due to storage routing was calculated using USDA Soil Conservation Service guidelines. The inflow flood of 1,440 CFS was reduced to an outflow of 1,400 CFS.

The spillway capacity of 735 CFS represents 52 percent of the calculated test. The test flood would overtop the dam by approximately 1.8 feet.

The low point of the dam is located approximately 65 feet left of the spillway and is roughly one foot lower than the access bridge surface. The overtopping flow would flow around the

SECTION 4 - OPERATIONAL PROCEDURES

4.1 Procedures

There are no known operational procedures for this dam.

4.2 Maintenance

Maintenance of the dam is minimal and related only to the aesthetical appearance of the recreational area. Debris which collects on the spillway is removed on an as-needed basis.

There was some evidence observed during the visual inspection, also indicated in the file data, that some minor repairs were performed on the dam in recent years. These repairs consisted of pointing of the loose stone joints in the training walls.

During the inspection of the dam, an area resident was interviewed. He indicated that several truck loads of clay were placed on the upstream face of the dam approximately four years ago.

4.3 Maintenance of Operating Facilities

None exists for this dam.

4.4 Description of Warning System

None exists for this dam.

4.5 Evaluation

The lack of routine maintenance on the dam could contribute to increase deterioration of the dam in the future. Recommendations for an improved maintenance program are outlined in Section 7.

The downstream training walls are in poor condition. High flows over the spillway have eroded the streambed material to the point where the training walls have partially collapsed into the downstream channel (see Photos 4, 5 and 6). It appears that further erosion is likely and complete collapse of the training walls may occur in the near future.

A 12-inch cast-iron drain pipe is located at the base of the spillway. The drain inlet and operating valve are presumed to be located in the reservoir. The outline of a box-type structure can be seen approximately 25 feet upstream of the dam. Because of the depth and poor clarity of the water, the dimensions and contents of the structure could not be determined.

d. Reservoir Area

The reservoir area is a small pond used for recreational purposes. The banks are well formed and covered with trees. There are no signs of erosion or slope instability. A marshy area exists at the upstream portal where sedimentation has occurred.

e. Downstream Channel

The downstream channel is the natural streambed. Stone retaining walls extend approximately 25 feet downstream of the training walls. The stream runs southerly for about 500 feet before encountering a roadway culvert. There is a considerable amount of debris in the channel consisting of fallen trees and branches.

3.2 Evaluation

The significant findings of the visual inspection are as follows:

- a. The downstream training walls of the spillway are in poor condition, the downstream end of the walls having collapsed. If the walls continue to collapse closer to the dam, the flow from the spillway can produce undermining of the base of the dam. The severity of such undermining depends on the depth at which the dam is founded and on the type of foundation material.
- b. The roots of a tree growing on the upstream slope and of several trees growing near the downstream wall of the dam can cause seepage channels to develop. A limited sapling growth from cracks on the downstream wall can accelerate deterioration of the wall.
- c. The left end of the downstream wall of the dam has lost some stones.
- d. There are some voids in the left training wall at the spillway entrance.

SECTION 3 - VISUAL INSPECTION

3.1 Findings

a. General

The dam is judged to be in fair condition based on the visual inspection. Although the spillway training walls have been damaged severely by erosion of the foundation material, there were no signs of unstable conditions. Water was flowing over the spillway at the time of inspection, preventing the examination of the downstream spillway face for leaks.

b. Dam

The dam consists of a downstream stone masonry wall and an upstream earth embankment.

The upstream slope has no visible slope protection (see Photo 7). The part of the slope above the water level shows some indication of erosion resulting in local areas with an almost vertical face and with a height on the order of 2 feet. A large tree is growing on the upstream slope near the right abutment.

The downstream face of the dam is of stone masonry construction. The surface is irregular and shows no apparent seepage. There is some growth of vegetation out of cracks in the wall. At the left abutment there are some voids in the wall, and apparently some stones are missing (see Photo 2). The cause of the deterioration of the wall at the left abutment is probably erosion due to runoff from the access road. An inspection along the toe of the downstream wall revealed no indications of seepage. There are several trees growing immediately downstream of the dam.

c. Appurtenant Structures

The cut stone spillway (see Photo 3) contains pins which are assumed to be flashboard supports. Although no flashboards were present, the pins were preventing several driftwood planks and other floating debris from flowing over the spillway. The spillway is spanned by a vehicle bridge, providing access to the picnic area.

The upstream training walls are stone masonry with several voids and loose stones. Several small trees are growing from the top of the wall (see Photo 1).

SECTION 2 - ENGINEERING DATA

2.1 Design

There is no design information available for this dam.

2.2 Construction

There is no significant construction information available for this dam other than the year of construction - 1938, and some correspondence on file with the New Hampshire Water Resources Board. The correspondence indicates that the design of the dam was reviewed and approved by the Public Service Commission of New Hampshire and that the dam was constructed by the Fish and Game Department.

2.3 Operation

There are no operating records available for this dam.

- 2.4 Evaluation
 - a. Availability

The design and construction records for this dam are not available.

b. Adequacy

The lack of in-depth engineering data does not allow for a comprehensive review. Therefore this evaluation, structurally and hydraulically cannot be made from the standpoint of review of design calculations but must be based primarily on the visual inspection, past performance history and sound hydrologic and hydraulic engineering judgment.

c. Validity

Not applicable.

(5) Upstream Channel

Reservoir - approach channel.

- (6) <u>Downstream Channel</u> Natural stream bed.
- (7) <u>General</u>

Vehicle access bridge across approach channel.

j. <u>Regulating Outlets</u>

12" drain (not functioning).



(3) <u>Height</u> Overall - 20 feet. Spillway - 14 feet. (4) Top Width Variable. (5) <u>Side Slopes</u> Upstream - 1H:1V. Downstream - Vertical stone wall. (6) Zoning None known. (7) <u>Impervious Core</u> None known. (8) Cutoff None known. (9) Grout Curtain None known. h. Diversion and Regulating Tunnel ju na Not applicable. i. <u>Spillway</u> (1) <u>Type</u> Broad crested weir/orifice. (2) Length of Weir 20 feet. (3) Crest Elevation 93.6. (4) <u>Gates</u> .* None.

- (2) <u>Flood Control Pool</u> Not applicable.
- (3) <u>Test Flood Pool</u>90 acre-feet.
- (4) <u>Spillway Crest Pool</u>50 acre-feet.
- (5) <u>Top of Dam</u> 80 acre-feet.
- f. <u>Reservoir Surface</u>
 - (1) <u>Recreation Pool</u>

5 acres <u>+</u>

- (2) <u>Flood Control Pool</u> Not applicable.
- (3) Spillway Crest
 5 acres +
- (4) <u>Test Flood Pool</u>

5.5 acres <u>+</u>

- (5) <u>Top of Dam</u> 5 acres <u>+</u>
- g. Dam
 - (1) <u>Type</u>

Masonry-earth dam with cut stone spillway.

(2) Length

Overall - 125 feet. **Spillway** - 20 feet.

(2) <u>Maximum Tailwater</u> Unknown.

- (3) <u>Upstream Portal Invert Diversion Tunnel</u> Not applicable.
- (4) <u>Recreation Pool</u> 93.6
- (5) <u>Full Flood Control Pool</u> Not applicable.
- (6) <u>Spillway Crest</u> 93.6
- (7) <u>Design Surcharge</u> Unknown.
- (8) <u>Top of Dam</u> 99.0
- (9) <u>Test Flood Surcharge</u> 100.8
- d. Reservoir Data
 - Length of Maximum Pool
 1000 feet +.
 - (2) Length of Recreation Pool 1000 feet +.
 - (3) Length of Flood Control Pool Not applicable.
- e. Storage
 - (1) <u>Recreation Pool</u>

50 acre-feet.

1-4

h. Design and Construction History

The original dam was constructed in 1936 by the New Hampshire Fish and Game Department as a fish rearing pond. The site of the dam was formerly a mill pond which had been washed away. There are no design or construction records available for the dam.

It was reported by an area resident that several truck loads of clay were placed on the upstream face of the dam four or five years ago.

i. Normal Operational Procedures

There are no routine operational procedures associated with this dam other than normal maintenance connected with the recreation area which includes clearing of floating debris from the spillway.

1.3 Pertinent Data

È

.....

1

.

2

۲.

a. Drainage Area

The drainage basin of the Ice Pond Dam includes approximately 3.9 square miles of variable terrain located northwest of the Town of Littleton. Elevations vary from 800 at the dam to 1900 at the higher basin ridges. The area is approximately 80 percent wooded with the remainder in open fields and residential development.

The main channel has a slope of 172 feet per mile and contains several small ponds with significant natural storage potential.

b. Discharge at the Dam Site

The only outlet from the reservoir is an ungated cut stone spillway, which is spanned by a vehicle access bridge. The spillway functions as a weir until the flow contacts the underside of the bridge beams after which orifice flow will govern. The maximum capacity of the spillway is 735 CFS at elevation 99.

c. <u>Elevations</u>

(Based on an assumed elevation of 100.0 at the center of the access bridge.)

(1) Streambed at Centerline of Dam

79 feet <u>+</u>.

trees. Several large pine trees are located near the embankment with root systems extending into the embankment. The split stone spillway which controls the reservoir level is in poor condition because of deterioration and erosion of the training walls.

An intake and/or drain structure can be seen in deep water approximately 25 feet upstream of the dam. Contents of the structure could not be determined through the water. It is assumed that the 12-inch drain line terminating at the downstream spillway face (see Photo 3) begins in the structure with a drain valve.

c. Size Classification

The Ice Pond Dam has a maximum height of 20 feet and a maximum storage volume of 80 acre-feet. The USCE Guidelines place dams with maximum heights lower than 40 feet and maximum storage between 50 and 1000 acre-feet in the small classification. Therefore the size classification of Ice Pond Dam is small.

-

d. Hazard Classification

A failure of the Ice Pond Dam would route a significant flood wave into the lower stream channel. The natural streambed would not be sufficient to contain the flood wave and extensive overland flow would result. At least two homes would receive some damage with potential for loss of life. Therefore the hazard classification for this dam is significant.

e. Ownership

The present owner of the dam is:

Town of Littleton Municipal Office Littleton, New Hampshire 03561

f. Operator

The dam is currently being maintained by the Town of Littleton, through the Park and Conservation Commission. The contact is Mr. James Hannigan, Town Manager. Telephone 603-444-3996.

g. Purpose

The dam was originally constructed by the New Hampshire Fish and Game Department in 1936 as a fish rearing pond. The current purpose of the dam is recreational, as the focal point of the "Dells" conservation and picnic area.

NATIONAL DAM INSPECTION PROGRAM PHASE I INSPECTION REPORT NAME OF DAM: ICE POND

SECTION 1 - PROJECT INFORMATION

1.1 General

a. Authority

Public Law 92-367, August 8, 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a National Program of Dam Inspection throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region. Dufresne-Henry Engineering Corporation has been retained by the New England Division to inspect and report on selected dams in the State of New Hampshire. Authorization and notice to proceed were issued to Dufresne-Henry Engineering Corporation under a letter of November 20, 1978 from Max B. Scheider, Colonel, Corps of Engineers. Contract No. DACW33-79-C-0010 has been assigned by the Corps of Engineers for this work.

b. Purpose

2

t

- Perform technical inspection and evaluation of nonfederal dams to identify conditions which threaten the public safety and thus permit correction in a timely manner by nonfederal interests.
- (2) Encourage and prepare the states to initiate quickly effective dam safety programs for nonfederal dams.
- (3) To update, verify and complete the National Inventory of Dams.

1.2 Description of Project

a. Location

The Ice Pond Dam is located in the Town of Littleton, Grafton County, New Hampshire. More specifically, the dam is approximately 1 mile west of the City of Littleton, near the intersection of Interstate 93 and State Route 18.

b. Description of Dam and Appurtenances

The Ice Pond Dam is a 125-foot long, 20-foot high earth fill dam with a split stone downstream wall. The earth portions of the dam embankment are covered with grass and some small





left abutment where the stone wall contacts the abutment (see Photo 2). As noted in Section 3, some erosion has occurred in this area.

e. Dam Failure Analysis

If the Ice Pond Dam were to fail with the water at the top of the dam a flood wave 13 feet high flowing at a rate of 7,520 CFS would result. 500 feet downstream the channel makes a right angle turn and the stream flows through a bridge with an opening 11 feet wide and 5 feet high. The channel and bridge capacity would not contain the flood wave so that it would then continue to flow southerly along Dells Road and the flood plain east of it. The flood plain is about 2 feet lower than the road and the houses are built up at least a foot above road level. At this point the flood wave would be 4 feet deep on the flood plain (7 feet overall) or as much as a foot into the dwellings.

The flood wave would be between one to two feet deep when it finally crosses Route 302 prior to entering the channel of the Ammonoosuc River. With the anticipated spreading of the flood wave over the flood plain 53 acre-feet of storage would be available reducing the peak flow to approximately 2,000 CFS. This wave would be flowing at a rate of less than 1 foot per second in the inundated areas including restaurants and other commercial establishments. This would cause substantial economic loss and would pose some risk to life as homes could be partially inundated.

SECTION 6 - STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability

a. Visual Observations

The visual observations did not disclose any findings indicating immediate stability problems. However, some of the observations indicate the potential for future stability problems, particularly the condition of the spillway training walls, as discussed in Section 3. If the undermining and collapse of these walls continues, an unstable condition may result.

b. Design and Construction Data

None exists for this dam.

c. Operating Records

None exists for this dam.

d. Post-Construction Changes

None of the available records indicate any post-construction changes.

e. Seismic Stability

The dam is located in seismic zone 2 and in accordance with recommended Phase I Guidelines does not warrant seismic analysis.

SECTION 7 - ASSESSMENT, RECOMMENDATIONS/ REMEDIAL MEASURES

7.1 Dam Assessment

1

-

.

P

a. Condition

The dam is in fair condition as judged from the visual inspection. There are no evidences of an immediate unsafe condition. However, the condition of the downstream section of the spillway training walls can lead to an unsafe dam in the future if the recommendations and remedial measures recommended in Sections 7.2 and 7.3 are not taken.

b. Adequacy of Information

The information available on this dam is minimal and therefore, the assessment of the dam is based primarily on the visual inspection.

c. Urgency

The recommendations presented in Sections 7.2 and 7.3 should be carried out within one year of receipt of this report.

d. Need for Additional Investigation

None required.

7.2 Recommendations

It is recommended that the following items be performed under the guidance of a qualified engineer:

- 1. Design and construct increased spillway capacity or stabilize downstream face to withstand continuous overtopping.
- 2. Reconstruct the downstream sections of the spillway training walls to their original configuration with particular attention given to the foundation to prevent future undermining.
- 3. Repair the left end of the dam.
- 4. Fill voids in the left wall at the spillway entrance.
- 5. Activate the 12-inch drain line.

7.3 <u>Remedial Measures</u>

a. Operation and Maintenance Procedures

The following items are recommended:

- 1. Formulate a plan to remove all trees growing on the upstream slope and all trees within 20 feet of the downstream stone face of the dam. Also remove any growth out of the cracks in the downstream wall. Fill all holes or voids resulting from tree removal.
- 2. Remove debris from the downstream channel.
- 3. Remove debris along the edges of the reservoir and the pins for flashboards in the spillway to avoid accumulation of debris in the spillway during high flows, and prevent flashboards from being installed.
- 4. Institute a yearly technical inspection and maintenance program. The inspection program should include a search for seeps through the downstream wall, including the spillway section and inspection of the spillway at low flow conditions along with control of brush and tree growth around and on the dam, and in addition removal of debris from the spillway channel.

5. Establish a formal warning system.

7-2

7.4 Alternatives

None.

APPENDIX A

VISUAL INSPECTION CHECK LIST

þ

•

VISUAL INSPECTION CHECK PARTY ORGANIZATION	LIST ,	
PROJECT ICE POND_DAM	DATE November 14, 1978	•
	TIME A.M.	
	WEATHER Cool	
	W.S. ELEVU.SDN.S.	
PARTY:		
1. Gonzalo Castro GEI 6		<u>.</u>
2. Jim Maynes D-H 7		
3. Jim Dohrman D-H 8		
4. Vern Clifford D-H 9.	······································	•
5. Ken Sterns, N.H. Board of 10.	·	
PROJECT FEATURE	INSPECTED BY REMARKS	
1		an Cressinguario
2		
3		
4	· · · · · · · · · · · · · · · · · · ·	•
5		
6		
7 °		
٥.		
10.	······	•
	· · · · · · · · · · · · · · · · · · ·	
•		
•		
1		
•		

PERIODIC INSPECTION	ON CHECK LIST	-
PROJECTICE POND DAM	DATE November 14, 1978	
PROJECT FEATURE	NAME	
DISCIPLINE	NAME	
AREA EVALUATED	CONDITION	
DAM EMBANKMENT		- -
Crest Elevation		· ·
Current Pool Elevation		
Maximum Impoundment to Date		1
Surface Cracks	None observed.	- 1-
Pavement Condition	Soil - good.	
Movement or Settlement of Crest	None observed. Slight erosion at low point in road.	
Lateral Movement	None observed.	-
Vertical Alignment	Good.	
Horizontal Alignment	No misalignment observed.	•
Condition at Abutment and at Concrete Structures	At left abutment wall has settled, under mined by flow.	
Indications of Movement of Structural Items on Slopes	None.	
Trespassing on Slopes	Recreational area - none observed.	
Sloughing or Erosion of Slopes or Abutments	Erosion at left abutment due to road drainage. Upstream face has eroded to Vermont face 4 feet high.	*
Rock Slope Protection - Riprap Failures	None observed - under water.	
Unusual Movement or Cracking at or near Toes	None.	
Unusual Embankment or Downstream Seepage	None observed - downstream wall of spill- way was under water.	
Piping or Boils	None.	
Foundation Drainage Features	None known.	
Toe Drains	None known.	- -
Instrumentation System	None.	
Vegetation	Trees growing from downstream wall and o top of wall.	
		-

PERIODIC INSPECTI	ON CHECK LIST	
PROJECTICE POND DAM	DATE November 14, 1978	_
PROJECT FEATURE	NAME	
	NAME	-
DISCIPLINE		- • •
		_
	CONDITION	-
OUTLET WORKS - CONTROL TOWER	NONE.	
a. Concrete and Structural		
General Condition		
Condition of Joints		
Spalling		
Visible Reinforcing		
Rusting or Staining of Concrete		
Any Seepage or Efflorescence		
Joint Alignment		
Unusual Seepage or Leaks in Gate Chamber		
Cracks		
Rusting or Corrosion of Steel		
. Mechanical and Electrical		
Air Vents		
Float Wells		
Crane Hoist]	6 is a final set of a
Elevator		
Hydraulic System		
Service Gates		
Emergency Gates		
Lightning Protection System		
Emergency Power System		
Wiring and Lighting System in Gate Chamber		
•		
	A-3	

PROJECTICE POND DAM	DATE November 14, 1978	
PROJECT FEATURE	NAME	
DISCIPLINE	NAME	· · · · · · · · · · · · · · · · · · ·
AREA EVALUATED	CONDITION	
OUTLET WORKS - TRANSITION AND CONDUIT		•
General Condition of Concrete	Outline of intake box is visible in 5+ feet of water. Dimensions and contents could not be obtained	
Rust or Staining on Concrete	contents could not be obtained.	-
Spalling		-
Erosion or Cavitation		
Cracking		
Alignment of Monoliths		
Alignment of Joints		
Numbering of Monoliths		
•		
	1	
•		
	A-4	
• • • • • •		

PROJECT ICE POND DAM	DATE No	vember 14, 1978	
PRO IFCT FFATURE	NAME		
DISCIPLINE	NAME	<u> </u>	• •
AREA EVALUATED	CONDITION	1	
OUTLET WORKS - OUTLET STRUCTURE AND OUTLET CHANNEL	NONE.		
General Condition of Concrete			
Rust or Staining			
Spalling			• •
Erosion or Cavitation			
Visible Reinforcing			
Any Seepage or Efflorescence			
Condition at Joints			•
Drain Holes			
Channel			
Loose Rock or Trees Overhanging Channel			
Condition of Discharge Channel			
			•
			•
,			
•			
•	A_5		
			e de des terres d De la Constante de la Constante

PERIODIC INSPECTION	ON CHECK LIST	-	
PROJECTICE_POND_DAM	DATE November 14, 1978	1	•
PROJECT FEATURE	NAME	1	
DISCIPLINE	NAME	۱ ــــــــــــــــــــــــــــــــــــ	
		.	
AREA EVALUATED	CONDITION		
OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS	· · ·	1	•
a. Approach Channel			
General Condition	Good.	1	
Loose Rock Overhanging Channel	None.		
Trees Overhanging Channel	None.		•
Floor of Approach Channel	Silted.		
b. Weir and Training Walls .	Fair - some erosion - openings in stone joints.		
General Condition of Stonewalls			
Rust or Staining	None.	1	
Spalling	Mortar facing on stone walls - slight spalling.		
Any Visible Reinforcing	None observed.	ר ו	•
Any Seepage or Efflorescence	None observed.		
Drain Holes	None observed.		
c. Discharge Channel	Channel walls eroded for 10 feet both sid	5. : • :	.
General Condition	Poor. Spillway wingwalls partially collapsed and settling, large cracks.	-	
Loose Rock Overhanging Channel	Some.		
Trees Overhanging Channel	Yes.		
Floor of Channel	Natural stream eroded (no riprap); debris downstream of pool.		•
Other Obstructions	None.		· • • •
d. Reservoir Drain	12" C.I.P. at base of spillway wall - old valve pit observed under water (see sketch) not easily assessable.		•
		:.	
•	A-6		

de.

. . .

JECT ICE POND DAM	DATE November 14, 1	.978
)JECT FEATURE	NAME	
SCIPLINE	NAME	
AREA EVALUATED	CONDITION	
TLET WORKS - INTAKE CHANNEL AND INTAKE STRUCTURE	NONE OBSERVED.	
Approach Channel Slope Conditions Bottom Conditions Rock Slides or Falls Log Boom Debris Condition of Concrete Lining Drains or Weep Holes Intake Structure Condition of Concrete Stop Logs and Slots		
	A-7	

IECT ICE POND DAM		DATE November	1/ 1978
		DATENOVEMBER 14, 1978	
		NAME	· · · · · · · · · · · · · · · · · · ·
CIPLINE		NAME	
AREA EVALUATED	1	CONDITION	
LET WORKS - SERVICE BRIDGE	NONE		
Super Structure			
Bearings			
Anchor Bolts			
Bridge Seat			
Longitudinal Members			
Under Side of Deck			
Secondary Bracing			
Deck			
Drainage System			
Railings			
Expansion Joints			
Paint			
Abutment & Piers			
General Condition of Concrete			
Alignment of Abutment			
Approach to Bridge			
Condition of Seat and Backwall			
		•	
•			
	A-8		

ECTICE_POND_DAM	DATE	November 14,	1978	
ECT FEATURE	NAME		·	
IPLINE	NAME			
	• · · · · · · · · · · · · · · · · · · ·			
AREA EVALUATED	COND	DITION		
VOIR				
lity of Shoreline	Eroding, trees,	sandy slope.	•	
entation	Extensive.			
;es in Watershed Runoff Potential	None known.			
ceam Hazards	None.			
stream Hazards				
: Facilities	None.			
meteorological Gages	None.			
itional and Maintenance gulations	None.			
•				
	A-9			



HYDROLOGIC AND HYDRAULIC COMPUTATIONS



#7. VIEW OF RESERVOIR AREA



#8. VIEW OF DOWNSTREAM (TO STATE)

C-4



#5. VIEW OF LEFT TRAINING WALL



#6. CLOSE-UP OF LEFT TRAINE TO MALL

C-3



#3. VIEW OF DOWNSTREAM SPILLWAY FACE AND TRAINING WALL



#4. VIEW OF RIGHT TRAINING MOLE SHOWING UNDERMINING AND COLLARS

C-2



#1. VIEW OF TOP OF DAM AND ACCESS BRIDGE OVER THE SPILLWAY



#2. VIEW OF EROSION AND CONTREPENT AT LEFT ADUTMENT

C-1





PHOTOGRAPHS





H. H. WATER RESCURCES BOARD Concord, N. H. C3301 <u>DAM SAFETY INSPECTION REPORT FORM</u> Town: Dam Number:140.10 Inspected by: Date: Sept974 Local name of dam or water body: Corner: Address:	
Concord, N. H. C3301 DAM SAFETY INSPECTION REPORT FORM Town:	
DAM SAFETY INSPECTICN: REPORT FORM Town:	•
Date: 140.10 Town: Little ton Dam Number: 140.10 Inspected by: $5 < B$ Date: 6.5 ept 19.74 Local name of dam or water body: Address:	•
Town: $L_{fllkcton}$ Dam Number: 140,10 Inspected by: $S \subset B$ Date: $G Sept$ 1974 Local name of dam or water body:	•
Inspected by: <u>SCB</u> Date: <u>Scpt 19</u> 74 Local name of dam or water body: Owner: Address:	
Local name of dam or water body:Address:	
Cwaer: Address:	
	•
Owner was was not interviewed during inspection.	
Dreinage Area: 50. mi. Stream:	
Ford Area: Acre Storage Ac-Ft. Max. Head Ft.	•
Foundations Free Converse massart at too Vod/No	
Foundation: Type, beepage present at the P Tearloy,	
Spillway: Type, Freeboard over perm. crest:,	•
Width, Flashboard height,	
Max. Capacityc.f.s.	
Erbenkrent: Type <u>F-FLESCov</u> , Cover(<u>krish</u> Width <u>20</u> T	
Upstream slope to 1; Downstream slope to 1	
Abutrents: Type Stc. 12, Condition: Good, Fair Poor	
Gates or Pond Drain: Size Capacity Type	
Lifting apparatus Operational condition	
Changes since construction or last inspection:	
Downstream development:	
This dam would would not be a menace if it feiled.	
Suggested reinspection date:	
Remarks: Leaks al Spillway Wing walls	
	<u> </u>
	•
	•

LALA UN DANS IN NEW HAMPSHIRE TION TION TIGE TION TIGE TION TIGE TIGE TIGE TIGE TIGE TIGE TIGE TIGE		DATA ON DAMO IN NEW THEORY	
TION STATE NO. 140-10		DATA ON DAMS IN NEW HAMPSHIRE	
Iditletion : County Grafton wn Littletion : County Grafton in Primary Conn. R. : Secondary Armonoosuc. R. isla Name "Bells"	TION		
Image: Second	1.i++1~		
Attended Secondary Attended ain-Primary Conn.R. : Secondary Attended ain-Primary "Della" Della" Della" prdinates—Lat. Iff. 2.0 - 7.8.8.9 : Long. 7.6.9.7.9 Della" prdinates—Lat. Iff. 2.0 - 7.8.8.9 : Long. 7.6.9.7.9 Della" prdinates—Lat. Iff. 2.0 - 7.8.8.9 : Long. 7.6.9.7.9 Della" anage area: Controlled Sq. Mi: Uncontrolled Sq. Mi: Total. Sq. M. range area: Controlled Sq. Mi: Uncontrolled Sq. Mi: Total. Sq. M. store Gates Split Stone— Earth Foundation / Store store Gates Size ft. high x ft. wide Elevation Invert : Size ft. high x sq. ft. Hoist aste Gates Conduit Number : Total Area sq. ft. Number : Size ft. high x sq. ft. materials Size .ft. high x .ft. Materials sq. ft. Hoist .see Cates .seq. ft. ft. Materials sq. ft. <t< td=""><td>иццтортсрој</td><td></td><td></td></t<>	иццтортсрој		
unre runary Uong. L. : Secondary Armenoocuc.R. sal Name "Della" : Long. 7/ ° v ° glace. Della ordinates_Lat 22		Acro D	
ar name	al Name		•••••
SRAL DATA SRAL DATA SRAL DATA SRAL DATA sings area: Controlled Sq. Mi.: Uncontrolled Sq. Mi.: Total 32 Sq. M. erall length of dam .125 /. ft.: Date of Construction ight: Stream bed to highest elev .22 /tt.: Max. Structure _15! 10" / ft. stb-Dam	ai wame	* DD - 7800 - T 719501 - 114 - 156	
Enc. DATA sinage area: Controlled Sq. Mi.: Uncontrolled Sq. Mi.: Total Sq. M. sinage area: Controlled Sq. Mi.: Uncontrolled Sq. Mi.: Total Sq. M. ight: Stream bed to highest elev 22./ft.: Max. Structure 151 10"// ft. st= Dam : Reservoir : Sq. Mi.: Uncontrolled 151 10"// ft. St= Data : Reservoir : Sq. Mi.: Uncontrolled 151 10"// ft. St= Cates Sq. Mi.: Uncontrolled : Reservoir : Sq. Mi.: Uncontrolled Sq. Mi.: Uncontrolled . St= Cates Sq. Mi.: Uncontrolled : Reservoir : Sq. Mi.: Uncontrolled <td< td=""><td>proinates—Lat. 44</td><td>4.0</td><td>···· _•</td></td<>	proinates—Lat. 44	4.0	···· _•
erall length of dam .125	INAL DATA	lad So Mi. Il mantuallad So Mi. M	N.
<pre>star (Fight of dam 120.2.1): Date of Construction ight: Stream bed to highest elev</pre>	amage area: Control.	125 / ft . Data of Construction	بيناند ب
gun: suream bea to nignest eiev. SLATI: Max Structure 12. 10. 10. 10. 10. 10. 10. 10. 10. 10. 10	erall length of dam	highert class 22 / the 35 - 04 - 151 - 104 /	
sk-wam : Reservoir CRIPTION Gravity Split Stone Earth Foundation / site Gates Type Number : Size ft. high x ft. wide Elevation Invert : Total Area sate Gates Conduit Number Number : Materials Size ft.: Length size	ignt: Stream bed to	nignest eiev	. 11.
KHF HON Gravity - Split Stone - Earth Foundation / sate Gates Type Number : Size the stere is stere in the stere is stere in the stere is stere in the stere is stere is stere in the stere is stere is stere in the stere is stere in the s	st—Jam	: Keservoir	· · · ·
stre cates Type Number : Size thigh x ft. wide sate Gates Conduit Number : Total Area sate Gates Conduit Number : Materials Size	KIPTION Gravity	- Split Stone Earth Foundation /	
Appendix ft high x ft wide Number : Total Area sq. ft. Hoist	aste Gates		
strumer is size it. nigh x ft. wide Elevation Invert is Total Area sq. ft. Hoist aste Gates Conduit sq. ft. Number is Materials sq. ft. Size ft. i Length ft. i Area sq. ft. mbankment Type sq. ft. sq. ft. Height-Max ft. i Length ft. i Min. ft. Top-Width : Elev. ft. ft. Slopes-Upstream on : Downstream on Length-Right of Spillway : Left of Spillway set if the set	rihe	· Siza & Li-L	
Lervation Invert : Total Area sq. ft. Hoist			. ≎101γ
Hoist aste Gates Conduit Number : Materials Size .ft.: Length .ft.: Area sq. ft. bankment Type Height Max .ft.: Minister Size .ft.: Length .ft.: Materials of Construction Length Length .ft.: Number .ft.: Neight of Spillway Materials of Construction Length Length .ft.: Neight of permanent section Max .ft.: .ft.: Neight of permanent creat .ft.:	Elevation Invert		. 1t.
aste Gates Conduit Number: Materials	Holst		••••••••••••••••••••••••••••••••••••••
Number : Materials Size .ft.: Length Materials .ft.: Area Size .ft.: Length Materials .ft.: Area Type	aste Gates Conduit		
Size It.: Length It.: Area sq. ft. mbankment Type	Number	the Lewishing and the second s	
mbankment Type Height—Max. ft.: Min. Top—Width : Elev. Slopes—Upstream on Length—Right of Spillway : Left of Spillway pillway Materials of Construction Length—Total ft.: Net Length—Total ft.: Net Height of permanent section—Max. 12! January 25, 1939 market Warks Marks	51Ze	II.: Length	1. ft.
Hype ft: Min. ft. Height—Max. ft.: Min. ft. Top—Width : Elev. ft. Slopes—Upstream on : Downstream on Length—Right of Spillway : Left of Spillway on in the spillway pillway Materials of Construction	nbankment Mene		
neight—plax. ft.: Min. ft. Top—Width : Elev. ft. Slopes—Upstream on : Downstream on Length—Right of Spillway : Left of Spillway on	Type	A	·····
10p-wiatn : Elev. ft. Slopes-Upstream on : Downstream on Length-Right of Spillway : Left of Spillway on	neight-Max		. f t.
Slopes—Upstream on : Downstream on Length—Right of Spillway : Left of Spillway	Top-Width	:: Elev.	ft.
Length-Right of Spillway	Slopes—Upstream		
Materials of Construction Length—Total Height of permanent section—Max Flashboards—Type Materials Flood Capacity Flood Capacity GlQ cfs.: Top of Flashboard Flood Capacity GlQ cfs.: Top of Flashboard Flood Capacity GlQ cfs.:	Length-Right of Sl	pillway: Left of Spillway	
Materials of Construction ft. Length—Total ft. Height of permanent section—Max ft. Flashboards—Type ft. Minute ft. Sile ft. Sile ft. Minute ft. Materials: ft. Freeboard: Max ft. Materials: ft. Freeboard: Max ft. Materials: ft.	billway		
Length—Total ft: Net 121 3" ft. Height of permanent section—Max. ft/0 ft. Min. ft. Flashboards—Type Marrie ft. Min. ft. Elevation—Permanent Crest Top of Flashboard ft. ft. Flood Capacity 610 cfs. cfs/sq. mi. Sutments Materials: ft. Min. ft. Freeboard: Max. 6! 2" ft. Min. ft. Ieadworks to Power Devel.—(See "Data on Power Development") Marks Use ^U Domestic ft. ft. ft. MARKS Use ^U Domestic ft. January 25, 1939 ft. ft. Bulation By A. N & R L T Date January 25, 1939 ft.	materials of Constr	uction	
Height of permanent section—Max. ft. Min. ft. Flashboards—Type Min. ft. Elevation—Permanent Crest : Top of Flashboard ft. Flood Capacity 610 cfs.: cfs/sq. mi. Sbutments Materials:	Length-Total		ft.
Flashboards—Type Marrie Height ft. Elevation—Permanent Crest Top of Flashboard Ft. Flood Capacity 610 cfs.: cfs/sq. mi. Subutments Materials: cfs/sq. mi. Materials: ft.: Min. ft. Freeboard: Max. 6! 2!! ft.: Materials: ft.: Min. ft. Icadworks to Power Devel.—(See "Data on Power Development") ft. ft. /NER ft.: Marxi: ft. MARKS Use th Domestic ft. //with //with ft. January 25, 1939 bulation By A. A. N & R. L. T Date January 25, 1939	Height of permanen	nt section—Max	ft.
Elevation—Permanent Crest	Flashboards—Type		ft.
Flood Capacity 610 cfs.: cfs/sq. mi. Subutments Materials:	Elevation-Permane	ent Crest	
butments Materials: Freeboard: Max. 6! 2" ft.: Min. ft. Headworks to Power Devel. (See "Data on Power Development") (NER ft.: Min. ft. MARKS Use th Domestic (Contraction of the second of	Flood Capacity	<u> </u>	
Materials: Freeboard: Max. 6! 2" ft.: Min. ft. leadworks to Power Devel.—(See "Data on Power Development") /NER	butments		
Freeboard: Max. 6! 2" ft.: Min. ft. leadworks to Power Devel.—(See "Data on Power Development") NER	Materials:		•••••••
leadworks to Power Devel.—(See "Data on Power Development") /NER	Freeboard: Max		ft.
MARKS Use Domestic MARKS Use Domestic Nut with bulation By <u>AAN&RLT</u> Date January 25, 1939	leadworks to Power	Devel(See "Data on Power Development")	
MARKS Use ¹¹ Domestic Nut with bulation By <u>AAN&RLT</u> Date January 25, 1939	NER	1 citalo - so	********
Dulation By <u>AAN&RLT</u> Date January 25, 1939	MARKS Use-	- Domestic Q. C.	
bulation By <u>AAN&RLT</u> Date January 25, 1939		not usea	
bulation By <u>AAN&RLT</u> Date January 25, 1939		1 1 V V V	
bulation By <u>AAN&RLT</u> Date January 25, 1939			
	bulation By A A	N&RLT Date January 25, 1939	-
	21284		•
	• • •		

.

TOWN	LIPPLETON	TOWN 10 NO.	STATE NO. 140,1
RIVER STREAM	Ice Pond at ("D-113")		
DRAINAGE AREA	3±	POND AREA	
ДАМ Түре	Gravity	FOUNDATION NATURE OF Earth	۰. ج ۲
MATERIALS OF CONSTRUCTION	Solit Stone, Earth		
PURPOSE OF DAM	POWER-CONSERVATION-DOMESTIC	-RECREATION-TRANSPORTATION-P	
HEIGHTS, TOP OF	TREAM A DYDE. 221	TOP OF DAM TO SPILLWAY CRESTS 6	1_21
SPILLWAYS, LENG	THS IL'-3" CL OT		OF DAM ADDOX.
FLASHBOARDS TYPE, HEIGHT AN	BOVE CREST llone		
OPERATING HEAD CREST TO N. T. W	· · · · · · · · · · · · · · · · · · ·	TOP OF FLASHBOARDS TO N. T. W.	······································
WHEELS, NUMBER	R .		
CENERATORS, NU KINDS & K. W.	MBER		
H. P. 90 P. C. TIM. 100 P. C. EFF.	ε	H. P. 75 P. C. TIME 100 P. C. EFF.	•
REFERENCES, CAS PLANS, INSPECTI	SES, ONS		· · ·
REMARKS		· · · · · · · · · · · · · · · · · · ·	
OWNER:	Town of Littleton		•
CONDITION:	Good	•	•
MENACE.	Vos Will be subject to y	periodic inspection.	

To the Public Service Commission:

The foregoing memorandum on the above dam is submitted covering inspection made July 27, 1926, according to notification to owner dated July 20, 1936, and bill for same is enclosed.

> D. Waldo White Chief Engineer

Aug. 7, 1936 Cony to Owner

NEW HAMPSHIRE WATER RESOURCES BOARD INVENDORY OF DAMS AND WATER POWER DEVELOPMENTS dam BASIN <u>Connecticut</u> NO. 10 - <u>L-5322</u> RIVER <u>Ice Print</u> MILES FROM MOUCH D.A.SQ.MI. OWNER Towner Little Lein TOWN LIFTATAL BUILT DESCRIPTION Gravity - Splet Stand & Earth outand DRAVIDCUM FF. POND CAPACITY-ACRE FT. POND AREA-AGRES TAX. HEICHT-TOP TO BED OF STREAM-FT. 22 ± MAX. MIN. OVERALL LENGTH OF DAM-FT. 125 MAX.FLOOD HEI HT ABOVE CREST-FT. PERMANENT CREST ELEV.U.S.G.S. LODAL GAGE TAILWATER ELEV.U.S.G.S. LOJAL GAGE FREEBOARD-FT. 6.167 SPILLWAY LENGTHS-FT. 12.25 FLASHEOARDS-TYPE, HEIGHT ABOVE CRIST Mene WASTE GATES-NG. WIDTH MAX. OPENING DEPIN SILL BELCW CREST REMARKS Condition Gred 4D Lote NAMELESS P.L. ANNICHED SUCP. PCWER DEVELOPMENT RATED HEAD C.F.S. KW MAKE UNITS NO. HP FEET FULL GATE . Demestic JSE REMARKS MARIACE KE Prid

APPENDIX B

PROJECT RECORDS AND PLANS

1. Listing of Design, Construction and Maintenance Records:

None.

- 2. Copies of Past Inspection Reports
 - a. Public Service Commission July 27, 1936.
 - b. Water Resources Board September 6, 1974.

3. Plans:

- a. Site Plan.
- b. Details-Sections.

DUFRESNE-HENRY ENGINEERING CORPORATION W.A.LEONERD SUBJECT JEE PEND _____ OF ____ DERVINGE AREA JOB NO. 04-0035 E AVERAGE SLOPES TOTAL DRAINAGE AREA PLANIMETER 27.36 IN2 SCALE 1:24000 27.36 (.14348) = 3.926 SQ MI SUB - ARCA | PLANIMETER 17.18 IN 2 17.18 (.14348) = 2.465 sq MI SUB AREAZ 3.926 - 2.465 = 1.461 SOMI AVERAGE SLOPES LUCE - PAREIP 1 798 ELEV Q 10% ELEN @ 86%. 1118 $\frac{1118 - 798}{(4.76)(.38 \text{ m/m})} = \frac{176.9 \text{ FT}}{(4.76)(.38 \text{ m/m})}$ UC-AREA Z ELEV @ 10%. 795 1020-795 ZIG. 1 FT/MILE 2.74(.30 MI/IN) ELEV @ 85%. 1020





DUFRESNE-HENRY ENGINEERING CORPORATION	
3Y SUBJECT SHEET NO OF DATE JOB NO JOB NO	
TEST FLOOD DEVELOPMENT	
DRAINAGE AREA = 3.9 SQ, MI = 2496 ACRES	
MAIN CHANNEL SLOPE = 172 FEET/MILE	
STORM IMPENDITY = 6 INCHES/24HR.	
SEE COMPUTER PRINTOUT FOR FLOOD FLOW	
CALCULATIONS FOR 1.2, 2.33, 5, 10, 25, 50, 100, 200	
AND 300 YEAR STORMS	••••••••••••••••••••••••••••••••••••••
100 YEAR STORM FLOW IS CALCULATED USING	
SIX VARIABLES	
MAX. 100 YEAR FLOW IS APPROX. 1,444 CFS	
STORAGE ROUTING	and the second
STORAGE AREA = St AIRES	
DERINAGE AREA = 2496	
5/2406 = 2 PERCENT STORAGE/DRAINAGE AREA	
IN ACCORDANCE WITH USDA SUIL CONSERVATION	
SERVICE GUIDELINES Q OUTFLOW WILL BE , 98 QINFLOW	
FOR 2 PERCENT STURAGE AREA	
• Q OUT = .98 (1444 = 1414 SAY 1,400 CFS	

_ _







DUFRESNE-HENRY ENGINEERING CORPORATION	
W.A.L. SUBJECT ICE POND DAM SHEFT NO OF	
6-1-79 DAM FAILURE MIALVSIS JOBNO 04-0085	•
ASSUME TOP OF DAM IS THE LOW POINT IN THE EMBANKM	
E L E V = 99.00	
STREAMBED ELEY = 19.00 " HEIGHT = 20	
$1/(2\pi)$	
$W_{11}D_{11}A = 725$	
FIDU OF FOUNDE - DEBLE WILL TO VIS	
PLOW AT PATEORE = 9 - 727 MB VG 0 - 727 M	
$\rho = \frac{6}{12} (4) (125) (322) (20)^{3/2} = 7570 CFS$	i de terte de ■
INITIAL FLOOD WAVE = 3/2 (20) = 13.33 FEET	
FLOOD WAVE ROUTING:	
VOLUME BETWEEN DAM AND DELLS ROAD CULVERT	
at Down near Dell's Road	
13.33 x 50 + 200 x7) x 500 = 12 Acre- feet	
7-	
PEAK REDUCTION 12 =15%	
80	
550 CFS THROUGH FULL BOX CULVERT ASSUMING	والمعادية المعادية مع
55 59, FT. @ 10 FPS	∎ • Bernang an Transformer • State St
FLOW REMAINING .	
(.85/(7520) = 550 = 5842 CFS	
DEPTH AT THIS POINT - SPILLS OVER, 200' WIDE FLOOD PLAIN	
AND 50-100' OF ROAD $H = L(2m)(2.08)$ 4.4 OVER FLOOD PLAIN,	· · · · · · · · · · · · · · · · · · ·
TEND TO THE THE AD 241 TE 3 A2 1/4000000	
TENE TO FEOW TOWARD ROUTE SUC , ATORADIC	
RIVIE 202 & T-93 INTERCHANCE. ELOOD WALE	
AAV SORELD TO EMALAND FEET WIDE.	•
FOR Q ² (armo (Es	
$H = \int 6 dv = 1.89'$	
(3.08)(7.50)	
SAY WATER WILL BE 2! OVER AREA ROADS.	
THIS PONDS 53 Acre-Feet IF AULRAGE WAPTH IS A FEET	
OVER GROUND WITH 200 TO 750 FOUT LIMITS OF	
INUNDATION DN 1.100 REACH, LENGTH (53 Ac-F+,)	
$D = 5842 (1 - \frac{53}{2}) = 2000 \ CFS \qquad 14 = \left[\frac{2000}{100} \right]^{43} = .91'$	

J***** REGIENAL	FLOCD FREQUENC	Y METHOD BY M.	BENSON ******	
I KEFEKENLEI	U.S. GEULUGICA	L SURVEY W.S.P.	• 1580-B ******	
ICE POND	DAM			
100 YEAR	PEAK DISCHARGE			
			· ·	
Α =	DRAINAGE AREA	= 3.90 SQ. 1	41.	
S =	MAIN CHANNEL S	LOPE = 172.00	FT•/MI•	
51= T =	TEMDEDATUSE IN			
Ω =	OROGRAPHIC FAC	$\frac{10}{10} = \frac{1}{10}$		
I =	X-YEAR, 24-HOU	R RAINFALL		
	RAINFAL	L DATA		
	BECUEDENCE	24 112112		
•	TNTEDVAL			
_	(YEARS)	LINCHESI		
•				
	1.2	0.0		
	2.33	0.0		
	5	0.0		
	10	0.0		
	25	0.0		
	100	0.0 6.00	•	
	200	V•0		
	300	0.0		an a star and the second star a
RECURRENCE	NUMBER OF	INDEPENDENT	PEAK	
INTERVAL	VARIABLES	VARIABLES	DISCHARGE	
(1.5)	IN EQUALION		10421	
1.2	1	۵	73	a in all and an incident second and
	2	A,S	96	
	3	A,S,ST	125	
	4	A,S,ST,D	105	
	5	A15,57,0,7	124	
	0	A, S, SI, U, T, I	-1	
2.33	- 1	۵	141	
	2	Ä.S	149	
	3	A+S+ST	242	
	4	C, TZ, Z, A	201	
	5	A, S, ST, U, T	د د 2	
· •	6	A,S,SI,D,T,I	-1	•
5	1	٨	374	
-	2	Ä.S	220	
	3	A+S+O	248	
	4	A. S. O. ST	314	
	5	ArS: 0:ST,T	365	
	6	A,5,0,ST,T,I	-1	
			۰.	

10 1 Α 329 2 3 4 A,S 454 A.S.0 351 A.S.D.ST 440 5 A.S.D.ST.T 511 6 A.S.O.ST.T.I -1 25 1 ٨ 539 2 A,S 756 3 A, S, D 542 4 A.S.D.ST 642 5 A,S,0,ST,T A,S,0,ST,T,I 731 6 -1 50 1 Α 85y 2 A.S 1178 3 A, S, O 724 4 5 A.S.O.ST 986 A,S,D,ST,T 1048 6 A.S.O.ST.T.I -1 100 1 A . 1015 2 A.S 1444 ~ 3 A.S.0 836 4 A.S.O.T 840 5 A,S,0,T,I 650 6 A, S, U, T, I, ST 1150 200 1 A 1309 2 A.S 2183 3 A.S.O 806 4 A.S.D.T 898 5 A.S.O.T.I -1 6 A.S.D.T.I.ST -1 300 l 1293 23 A,S 2763 A.S.0 1144 4 A.S.O.T 2279 5 A.S.O.T.I -1 6 A.S.D.T. C.ST -1

. -

_

ICE POND DAM 100 YEAR PEAK DISCHARGE

SUMMARY OF COMPUTED PEAK DISCHARGES

ECURRENCE ERVAL (YRS)	NUME 1	BER OF V 2	APIABLES 3	USED IN 4	EQUATION 5	6
1.2	73	96	125	106	124	-1
2.33	141	189	242	201	233	-1
5	226	369	243	314	365	-1
10	329	454	351	440	511	-1
25	539	756	542	642	731	-1
50	859	1178	724	986	1048	-1
100	1015	1444	836	890	650	1150
200	1389	2183	866	898	-1	-1
300	1293	2763	1144	2279	-1	-1

APPENDIX E

formation as Contained in the National Inventory of Dams



Image: Second	Or of the contraction Out on house Figure 11: Figure 11:	UNUN AS -				4414	7147.9	CAAPH 14		
Statution IEE FOND Altrian units IEE FOND Antion Internation Altrian units Internati	· Statistical field ICE FORM • Construction of STRAM • Construction • Construction • Construction	- SERVATIO	(E) LAR NAME			(1) (1) (1) (1) (1) (1) (1) (1) (1) (1)				
Image: Contract of the contra	Image: construction in the sector of the sector o		PICNJC AREA		ICE PUND					
RUER OFFICE/A CRAEST CONVERTIERAL CONSTANT CONST	ทศเร ดาราสาราส และสาราน (1111 E11 - 1 และสาราน (11111 E11 - 1 และสาราน (11		۲		۲		۲	Î		
ЦИТЬ - НИТА ЦИТЕТС - На О 5201 EMM COMM COMM EMM COMM EMM COMM EMM COMM COMM EMM COMM	ALTOLE ALTOLE ALTOLE ALTOLE ALTOLE ALTOLE ALTOLE RAM RAM RAM RAM RAM No No No RAM RAM RAM SS SS SS SS SS RAM RAM RAM RAM No SS SS SS SS RAM RAM RAM RAM RAM No SS SS SS SS RAM RAM RAM RAM RAM RAM No No SS SS SS RAM RAM RAM RAM RAM RAM No No SS SS SS SS RAM RAM RAM RAM RAM No SS SS SS SS RAM RAM RAM RAM RAM No SS SS SS RAM RAM RAM RAM No No SS SS SS SS RAM RAM RAM RAM RAM RAM No SS SS SS SS SS S S SS RAM RAM RAM	2	ER OR STREAM		NEAREST DOV CITY - TOWN	VNSTREAM - VILLAGE	FROM DAM	POPULATION		
Image: Second	Image: Transmission Image: Transmission Transmission <th< td=""><td>ALNE TRUE</td><td>×</td><td></td><td>וזן בזהי אים</td><td></td><td>•</td><td>5240</td><td></td><td></td></th<>	ALNE TRUE	×		וזן בזהי אים		•	5240		
OM WEAR NUMBER NUMER NUMER NUMER	Ом. Ом. П. В. П.	R		۲		¢				
1.115 20 21 21 21 21 N <th< td=""><td>1 1<td>DAM COMPLET</td><td>ED. PURPOSES</td><td></td><td>ICH MEDUNO</td><td>ING CAPACITIES</td><td>15T 0.</td><td>V FEU R PG</td><td>WVFED SCS</td><td>A VENTOAT</td></td></th<>	1 1 <td>DAM COMPLET</td> <td>ED. PURPOSES</td> <td></td> <td>ICH MEDUNO</td> <td>ING CAPACITIES</td> <td>15T 0.</td> <td>V FEU R PG</td> <td>WVFED SCS</td> <td>A VENTOAT</td>	DAM COMPLET	ED. PURPOSES		ICH MEDUNO	ING CAPACITIES	15T 0.	V FEU R PG	WVFED SCS	A VENTOAT
RMARIS RMARIS AC13 RMARIS AC13 RMARIS RMARIS RMARIS REMARIS RMARIS REMARIS RMARIS REMARIS REMARIS	Artis Ekanks Artis Artis <	-	x	vč	u u	19 2V	ED N	z	z	634463
ила ила влади и полодина и по	Notice Contract Contrac							[
NT.Y Entry	NT.R. No. No. No. Strutuwi Normania Normania Normania Normania Strutumi Normania Normania Normania Normania Strutumi Normania Normania Normania Normania Strutumi Strutumi Normania Normania Normania Strutumi Strutumi Strutumi Normania Normania Strutumi Strutumi Strutumi Normania Strutumi Strutumi Strutumi Normania Strutumi Strutumi Strutumi Strutumi Normai Strut									
SPLILMMY MAXIGATION LOCKS 11 135 12 135 13 135 14 135 15 135 16 135 17 11 <td>STILLIAW Description POWER CONSTRUCTION 1 20 715 0 1 20 715 0 1 20 715 0 1 20 715 0 1 20 715 0 1 1 0 0 0 0 0<</td> <td></td> <td></td> <td>۲</td> <td></td> <td></td> <td>0</td> <td>(() ()</td> <td></td> <td></td>	STILLIAW Description POWER CONSTRUCTION 1 20 715 0 1 20 715 0 1 20 715 0 1 20 715 0 1 20 715 0 1 1 0 0 0 0 0<			۲			0	(() ()		
DL 20 735 0 6 6 0 0 0 0 6 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 1 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 <td< td=""><td>5. 715 715 1 0. 715 1 1 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.</td><td>SPILLWAY</td><td>VOLUME ISCHARGE OF DAM (FT.) (CY)</td><td>POW</td><td>ED PACITY</td><td>inerson with render</td><td>NAVIGATION L</td><td>DCKS</td><td>r witch</td><td></td></td<>	5. 715 715 1 0. 715 1 1 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.	SPILLWAY	VOLUME ISCHARGE OF DAM (FT.) (CY)	POW	ED PACITY	inerson with render	NAVIGATION L	DCKS	r witch	
OWNER ONNER ONNER ONNER ONNER ONNER FLITTLETT: HILL H HICHARDSTIN ENGINEERING BY CONSTRUCTION BY ONNER Image: State of the stat	OWNER ENGINEERING BY OORTAUCTION BY + LJTTLETF: + ILL H ELCHAARSIN + LJTTLETF: + ILL H ELCHAARSIN (a) (b) (b) (c) (c) (c) <td>55 1 20</td> <td>735</td> <td>•</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>	55 1 20	735	•						
OWNER ENGINEERING BY CONSTRUCTION BY 1 + LJTTLETTT + ILL H HICHARTSTIN (a) (b) (c) (c) (c) (c) (c) (c) (c) (c) <td>OWNER ENGINEERING BY CONSTRUCTION BY I-I ITLETET > ILL N LELAGRSTIN > ILL N LELAGRSTIN I-I ITLETET > ILL N LELAGRSTIN ILL N LELAGRSTIN I-I ITLETET > ILL N LELAGRSTIN ILL N LELAGRSTIN I-I ITLETET > ILL N LEAGRSTIN ILL N LEAGRSTIN I-I ITLETET ILL N LEAGRSTIN ILL N LEAGRSTIN I-I ILL N LEAGRSTIN ILL N LEAGRSTIN ILL N LEAGRSTIN I-I N LEAGRSTIN ILL N LEAGRSTIN ILL N LEAGRSTIN I-I N LEAGRSTIN ILL N LEAGRSTIN ILL N LEAGRSTIN I-I N L N L ILL N L ILL N L I-I N L ILL N L ILL N L I-I N L ILL N L ILL N L I-I N L ILL N L ILL N L I-I N L ILL N L ILL N L I-I N L ILL N L ILL N L I-I N L ILL N L ILL N L</td> <td>۲</td> <td></td> <td>3</td> <td></td> <td></td> <td>(*)</td> <td>[</td> <td></td> <td></td>	OWNER ENGINEERING BY CONSTRUCTION BY I-I ITLETET > ILL N LELAGRSTIN > ILL N LELAGRSTIN I-I ITLETET > ILL N LELAGRSTIN ILL N LELAGRSTIN I-I ITLETET > ILL N LELAGRSTIN ILL N LELAGRSTIN I-I ITLETET > ILL N LEAGRSTIN ILL N LEAGRSTIN I-I ITLETET ILL N LEAGRSTIN ILL N LEAGRSTIN I-I ILL N LEAGRSTIN ILL N LEAGRSTIN ILL N LEAGRSTIN I-I N LEAGRSTIN ILL N LEAGRSTIN ILL N LEAGRSTIN I-I N LEAGRSTIN ILL N LEAGRSTIN ILL N LEAGRSTIN I-I N L N L ILL N L ILL N L I-I N L ILL N L ILL N L I-I N L ILL N L ILL N L I-I N L ILL N L ILL N L I-I N L ILL N L ILL N L I-I N L ILL N L ILL N L I-I N L ILL N L ILL N L	۲		3			(*)	[
Image: Fight of the stand o	ILL R LITLET: ILL R LICHARDSUN REGULATORY AGENCY MAINTENANCE DESIGN CONSTRUCTION MAINTENANCE DESIGN MAINTENANCE MAINTENANCE REAL MAINTENANCE MAINTENANCE REMARS MAINTENANCE MAINTENANCE	OWNER		ENGINEERIN	IG BY	CONSTRI	ICTION BY			
C C C C C DESIGN REGULATORY AGENCY REGULATORY AGENCY MAINTENANCE MAINTENANCE TFL H S HI Var.K.A NAMES NAMES NAMES IFL H S HI Var.K.A NAMES NAMES INSPECTION BY INSPECTION DATE AUTHORITY FOR INSPECTION S.E = H Y E.G., C rigp 14 VC V 7P PL 97=367 AUGUST 1 1972 I.S.I II II REMARKS	Image: Solution of the soluti	- LITILETPE	+ 111 +	HICHAR	D,S (1 N					
DESIGN CONSTRUCTION OPERATION MAINTENANCE IFU HS HD VALKA NALKA MAINTENANCE (a) (a) (a) (a) (b) (b) (a) (a) (c) (a) (a) (a)	DESIGN CONSTRUCTION OPERATION MAINTENANCE FFL H15 Var.K4 Nar.F3 Nar.F4 (a) (b) (c) (c) (b) (c) (c) (c) (c) (c) (c) (c) <t< td=""><td>۲</td><td>۲</td><td>REGULATOR</td><td>Y AGENCY</td><td></td><td>۲</td><td></td><td></td><td></td></t<>	۲	۲	REGULATOR	Y AGENCY		۲			
TFU HIS HIC VALIER ALLED INSPECTION BY INSPECTION DATE AUTHORITY FOR INSPECTION Site at it is the construction of the construction I aventy for a statement Site at it is the construction I aventy for a statement Remarks I aventy for a statement	Fruits Hill Variation Main Fruits IFU HIS HILL Variation Image: Stead of the state of th	DESIGN	CONSTRUCT	ON	OPERATI	NO	MAINTENAI	ICE		
INSPECTION BY INSPECTION BY INSPECTION BY INSPECTION BY INSPECTION DAY MO YAR AUTHORITY FOR INSPECTION S.E I	INSPECTION BY INSPECTION DATE AUTHORITY FOR INSPECTION INSPECTION BY AND YR AND YN AND YR AND YR AND YR AND	TEN NES HD	14.127		1 1 1 1 1 1 1 1	1 2	30 01			
S.E-HY ELG. CARP 14VCV7R PL92-367 AUGUST A 1972 () REMARKS REMARKS	SYEE-14-14 FLG. CR89 14VCV78 PL92-367 AUGUST x 1972	INSPECTI	ONBY	INSPECT	ION DATE	AUTHORITY FOR	INSPECTION			
REMARKS	REMARKS		6. Crap		CV78 PL92	-367 AUGUST 5	1972			
				REMARKS				1		
								 }		



FILMED

8-85



Sand and the set of the