



678

MICROCOPY RESOLUTION TEST CHART NATIONAL BUREAU OF STANDARDS-1963-A

I

185	(IA-
Q	PISCATAQUA RIVER BASIN
A 15	NOTTINGHAM , NEW HAMPSHIRE
4	
٩	NH 00135
	STATE NO 19403
	STATE NO 104.03
PH	ASE I INSPECTION REPORT
NATION	NAL DAM INSPECTION PROGRAM
	TIC
	C331 6 0 JUL 0 3 169
δάο	
	DEPARTMENT OF THE ARMY NGLAND DIVISION, CORPS OF ENGINEERS
	WALTHAM, MASS. 02154
	JULY 1978
	85 06 12 056
	_

. . . . r

-----

A LE 

Ŋ

, 6

ł

REPORT DOCUMENTATI	ON PAGE	READ INSTRUCTIONS REFORE COMPLETING FORM
I. REPORT NUMBER	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
NH 00135		
TITLE (and Subilite)		5. TYPE OF REPORT & PERIOD COVERED
Gove Dike		INSPECTION REPORT
NATIONAL PROGRAM FOR INSPECTION	OF NON-FEDERAL	6. PERFORMING ORG. REPORT NUMBER
U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION		B. CONTRACT OR GRANT NUMBER(*)
PERFORMING ORGANIZATION NAME AND ADD	RESS	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
1. CONTROLLING OFFICE NAME AND ADDRESS	<u></u>	12. REPORT DATE
DEPT. OF THE ARMY, CORPS OF ENGI	NEERS	July 1978
NEW ENGLAND DIVISION, NEDED 424 TRAPFID ROAD WAITHAM MA D	2254	13. NUMBER OF PAGES
4. MONITORING AGENCY NAME & ADDRESSI I di	terent from Controlling Office)	15. SECURITY CLASS. (of this report)
		UNCLASSIFIED
DISTRIBUTION STATEMENT (of the Report) APPROVAL FOR PUBLIC RELEASE: DIS	TRIBUTION UNLIMITED	UNCLASSIFIED 18. DECLASSIFICATION/DOWNGRADING SCHEDULE n Report)
APPROVAL FOR PUBLIC RELEASE: DIS DISTRIBUTION STATEMENT (of the ebetrect ont DISTRIBUTION STATEMENT (of the ebetrect ont SUPPLEMENTARY NOTES Cover program reads: Phase I Ins however, the official title of t	TRIBUTION UNLIMITED	UNCLASSIFIED 15. DECLASSIFICATION/DOWNGRADING SCHEDULE Report) onal Dam Inspection Program; nal Program for Inspection of
APPROVAL FOR PUBLIC RELEASE: DIS DISTRIBUTION STATEMENT (of the eberrect end DISTRIBUTION STATEMENT (of the eberrect end SUPPLEMENTARY NOTES Cover program reads: Phase I Ins however, the official title of the Non-Federal Dams; use cover date	TRIBUTION UNLIMITED ored in Block 20, 11 different free pection Report, Nati he program is: Natio e for date of report ry and identify by block number)	UNCLASSIFIED 18. DECLASSIFICATION/DOWNGRADING SCHEDULE n Report) onal Dam Inspection Program; nal Program for Inspection of
APPROVAL FOR PUBLIC RELEASE: DIS DISTRIBUTION STATEMENT (of the observed only DISTRIBUTION STATEMENT (of the observed only Cover program reads: Phase I Insp however, the official title of the Non-Federal Dams; use cover date KEY WORDS (Continue on reverce olde if necessar DAMS, INSPECTION, DAM SAFETY,	TRIBUTION UNLIMITED ored in Block 20, 11 different free pection Report, Nati he program is: Natio e for date of report ry and identify by block number)	UNCLASSIFIED IBA. DECLASSIFICATION/DOWNGRADING SCHEDULE n Report) onal Dam Inspection Program; nal Program for Inspection of
APPROVAL FOR PUBLIC RELEASE: DIS DISTRIBUTION STATEMENT (of the observed on DISTRIBUTION STATEMENT (of the observed on Supplementary notes Cover program reads: Phase I Insp however, the official title of the Non-Federal Dams; use cover date KEY WORDS (Continue on reverse olde II necesson DAMS, INSPECTION, DAM SAFETY, Piscataqua River Basin Nottingham, New Hampshire Tributary of Pavtucketway River	TRIBUTION UNLIMITED ored in Block 20, 15 different free pection Report, Nati he program is: Natio e for date of report ry and identify by block number)	UNCLASSIFIED 15. DECLASSIFICATION/DOWNGRADING SCHEDULE n Report) onal Dam Inspection Program; nal Program for Inspection of
APPROVAL FOR PUBLIC RELEASE: DIS SUPPLEMENTARY NOTES Cover program reads: Phase I Inst however, the official title of the Non-Federal Dams; use cover date KEY WORDS (Continue on reverse elde II necessed DAMS, INSPECTION, DAM SAFETY, Piscataqua River Basin Nottingham, New Hampshire Tributary of Pawtucketway River	TRIBUTION UNLIMITED ored in Block 20, 11 different free pection Report, Nation the program is: Nation e for date of report ry and identify by block number)	UNCLASSIFIED The DECLASSIFICATION/DOWNGRADING SCHEDULE Report) onal Dam Inspection Program; nal Program for Inspection of

ì

t

DD 1 JAN 73 1473 EDITION OF 1 NOV 63 IS OBSOLETE

REPRODUCED AT GOVERNMENT EXPENSE

# **DISCLAIMER NOTICE**

THIS DOCUMENT IS BEST QUALITY PRACTICABLE. THE COPY FURNISHED TO DTIC CONTAINED A SIGNIFICANT NUMBER OF PAGES WHICH DO NOT REPRODUCE LEGIBLY.

#### NATIONAL DAM INSPECTION PROGRAM PHASE I INSPECTION REPORT

Identification No.: Name of Dam: Town: County and State: Stream: Date of Inspection:

NH00135 Gove Dike Nottingham Rockingham County, New Hampshire Tributary of Pawtuckaway River 30 May 1978

#### BRIEF ASSESSMENT

Gove Dike is about 9 feet high, 20 feet wide at the crest, and 270 feet long (as measured in the field). It is a 136-year old earthen embankment contained between a nearly vertical wall of rounded boulders upstream and a vertical dry masonry (stone) wall downstream. An unpaved road occupies the crest of the dike. This dike and Dolloff and Drown's Dams form the impoundment system of Pawtuckaway Pond. The pond is used now for recreational purposes. It is 3 miles long, has a surface of about 900 acres, and maximum storage is 11,700 acre-feet.

The dike is in fair condition. Major concerns with regard to its long-term integrity are: the overtopping potential caused by the inadequate spillway discharge capacity at Dolloff and Drown's Dams, seepage at the downstream toe (less than 0.01 cfs), and a 6-inch bulge in the downstream vertical dry masonry wall.

The dike has no outlets. The test flood would overtop the dike at its lowest point by 2.9 feet.

The owner, New Hampshire Water Resources Board (NHWRB), should within two years implement the results, after evaluation of the following: assess further all factors relating to overtopping and to the inadequacy of the spillways of the system and design remedial measures for the seepages at the downstream toe of the dike and the bulge in the downstream vertical dry masonry wall. Within one year, NHWRB should implement the following operation and maintenance measures: monitor seepage weekly, clear brush on the access road and downstream of the dike, and establish a surveillance and warning program to be exercised during floods.

Varen U. Suna Warren A. Guinan

Project Manager N.H. P.E. No. 2339 PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers (OCE), Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.



CONTENTS

Page

## Title

Ś.

.

•

1

BRIEF ASSESSMENT	
REVIEW BOARD PAGE	
PREFACE	i
CONTENTS	ii
OVERVIEW PHOTO	iii
LOCATION MAP	iv

REPORT

## Section

1	PROJECT INFORMATION	1
	l.l General	1
	1.2 Description of Project	1
	1.3 Pertinent Data	3
2	ENGINEERING DATA	6
-	2.1 Design	6
	2.2 Construction	Ğ
	$2^{\circ}$ Operation	ĥ
	2.4 Evaluation	ں د
r		7
د		4
	3.1 Findings	
	3.2 Evaluation	8
4	OPERATIONAL PROCEDURES	9
	4.1 Procedures	9
	4.2 Maintenance of Dike	9
	4.3 Maintenance of Operating Facilities	9
	4.4 Description of Any Warning System in Effect	9
	4.5 Evaluation	9
5	HYDROLOGY AND HYDRAULIC ANALYSIS	10
	5.1 Evaluation of Features	10
6	STRUCTURAL STABILITY	12
•	6.1 Evaluation of Structural Stability	12
7	ASSESSMENT RECOMMENDATIONS & REMEDIAL MEASURES	13
'	7 1 Dike Assossment	13
	7.1 DIRE ASSESSMENT.	10
	7.2 Recommendations	14 1/
	/.3 Remealar Measures	14

## APPENDICES

## Designation

.

CHECK LIST - VISUAL INSPECTION	А
INSPECTION REPORTS/SKETCHES	В
PHOTOGRAPHS (Figures 2 - 6)	С
HYDROLOGY/HYDRAULICS	D
INVENTORY DATA	Ε



İ B

Г

Figure 1 - Overview of upstream face of Gove Dike.



#### NATIONAL DAM INSPECTION PROGRAM PHASE I INSPECTION REPORT GOVE DIKE

#### SECTION I PROJECT INFORMATION

#### 1.1 General

D

a. <u>Authority</u>. Public Law 92-367, August 8, 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a National Program of Dam Inspection throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region. Anderson-Nichols & Company, Inc. has been retained by the New England Division to inspect and report on selected dams in the State of New Hampshire. Authorization and notice to proceed were issued to Anderson-Nichols & Company, Inc. under a letter of May 3, 1978 from Ralph T. Garver, Colonel, Corps of Engineers. Contract No. DACW33-78-C-0329 has been assigned by the Corps of Engineers for this work.

#### b. Purpose.

(1) To perform technical inspection and evaluation of non-Federal dams to identify conditions which threaten the public safety and thus permit correction in a timely manner by non-Federal interests.

(2) To encourage and prepare the states to initiate quickly effective dam safety programs for non-Federal dams.

(3) To update, verify and complete the National Inventory of Dams.

#### 1.2 Description of Project

a. Location. Gove Dike is located in the Town of Nottingham, New Hampshire. Gove Dike, together with Dolloff and Drown's Dams, form the structural barrier system that impounds Pawtuckaway Pond. Gove Dike dams an unnamed tributary of the Pawtuckaway River approximately 0.7 mile upstream of their confluence. The Pawtuckaway then flows for about 2.5 miles to its confluence with the Lamprey River, a major tributary in the Piscataqua River Basin. The dike is shown on U.S.G.S. Quadrangle, Mt. Pawtuckaway, New Hampshire, with coordinates approximately at N 43° 04' 54", W 71° 07' 59", Rockingham County, New Hampshire (see location map page iv).

Description of Dike and Appurtenances. Gove Dike b. is a low earthen embankment with the upstream side partially faced with a nearly vertical wall of rounded boulders. The downstream face consists of a dry masonry wall. The dike, as measured in the field, is about 20 feet wide at the crest, 270 feet in length, and 9 feet in height above the downstream However, past inspection reports and other records toe. (see Appendix B) reflect that the dike is 350 feet in length, while the maximum structural height is ll feet as given in the Corps of Engineers' Inventory of March 1974. An unpaved roadway runs along the crest of the dike (see sketches in Appendix B). It is evident that fill has been placed sometime prior to 1978 to accommodate another road near the right (westerly) end of the dike.

c. Size Classification. Intermediate (Hydraulic height - 8 feet, Storage - 11,700 acre-feet) based on storage ( $\geq 1000$  to <50,000 acre-feet) as given in OCE Recommended Guidelines for Safety Inspection of Dams.

d. <u>Hazard Classification</u>. Significant hazard. A major breach in the dike would probably result in the loss of less than 10 lives and appreciable property damage.

e. <u>Ownership</u>. The present dike, along with Dolloff and Drown's Dams, are reported to have been built sometime between the years 1839 and 1842 by the Newmarket Manufacturing Company for the purpose of impounding Pawtuckaway Pond for use in their milling operations. Ownership passed on to the Lamprey River Improvement Company, a subsidiary of New Hampshire Gas and Electric Company, sometime prior to 1917. The New Hampshire Water Resources Board (NHWRB) purchased the three structures for one dollar in 1955 from the New Hampshire Gas and Electric Company.

f. Operator. Mr. Vernon K. Knowlton, Chief Engineer, New Hampshire Water Resources Board, 37 Pleasant Street, Concord, New Hampshire 03301 is responsible for the operation of the dams on Pawtuckaway Pond. Phone (603) 271-3406.

g. <u>Purpose of Dike</u>. The dike and dams impounding Pawtuckaway Pond were originally constructed to provide greater industrial storage for the Newmarket Manufacturing Company located in Newmarket, New Hampshire. Later, under the ownership of the Lamprey River Improvement Company, Pawtuckaway Pond was utilized primarily as upstream storage for generation of hydroelectricity for the region, with some recreational usage. Pawtuckaway Pond is presently being used for recreational purposes only.

h. Design and Construction History. Little information was found concerning the original design and construction of the dike. It is believed that the structure is basically an earth-fill dike faced with vertical dry masonry walls. A 1918 report recommended that an overflow area be created by lowering the crest 2.5 feet over a distance of 125 feet at the western end of the dike. A letter dated 1919 from the owner to the state regulatory agency indicates that this construction was started. Visual inspection found no evidence of an overflow area. Presently, the dike also serves as an unpaved year-round road.

i. <u>Normal Operational Procedures</u>. Not applicable; Gove Dike has no outlet facilities. No written maintenance procedures were found.

1.3 Pertinent Data

a. <u>Drainage Area</u>. The drainage area consists of 20.66 square miles (13,225 acres) of predominantly wooded terrain.

b. Discharge at Damsite (Dike)

(1) Outlet works (conduits) - none

(2) Maximum known discharge at damsite (dike) is unknown.

(3) Ungated spillway capacity at maximum pool elevation - not applicable.

(4) Gated spillway capacity at pool elevation - not applicable.

(5) Gated spillway capacity at maximum pool elevation - not applicable.

(6) Total spillway capacity at maximum pool elevation - not applicable.

c. <u>Elevation</u> (ft. above MSL) based on elevation of 250 shown on U.S.G.S. Quadrangle sheet and assumed to be spillway elevation at Dolloff Dam, Pawtuckaway Pond. (See Dolloff Dam Inspection Report.)

(1) Top of dike - 253.6

(2) Maximum pool - design surcharge - unknown

(3) Full flood control pool - not applicable

- (4) Recreation pool 250
- (5) Spillway crest not applicable
- (6) Upstream portal invert diversion tunnel none

(7) Streambed at centerline of dike - 244.4 (downstream toe measured at time of inspection)

- (8) Maximum tailwater unknown
- d. Reservoir (miles)
- (1) Length of maximum pool 3.0
- (2) Length of recreation pool 3.0
- (3) Length of flood control pool not applicable
- e. Storage (acre-feet)
- (1) Recreation pool 11,500
- (2) Flood control pool not applicable
- (3) Design surcharge unknown
- (4) Top of dike 11,700 (storage based on Dolloff Dam)
- f. Reservoir Surface (acres)
- (1) Top of dike 1015
- (2) Maximum pool 975 (based on Dolloff Dam)
- (3) Flood control pool not applicable
- (4) Recreation pool 903
- (5) Spillway crest not applicable
- g. Dike

(1) Type - earthen embankment with its upstream face partially covered with round boulders, and a dry masonry downstream face; both faces being nearly vertical.

(2) Length - 270' (measured) - 350' (from past inspection records)

PERIODIC INSPEC	TION CHECK LIST	
PROJECT Gove Dike, New Hampshire	DATE May 31, 1978	
PROJECT FEATURE Dike Embankment	NAME	
DISCIPLINE	NAME	
AREA EVALUATED	CONDITION	
Crest Elevation	253.6 ft. MSL	
Current Pool Elevation	250.1 ft. MSL	
Maximum Impoundment to Date	Unknown	
Surface Cracks	None	
Pavement Condition	Not paved	
Movement or Settlement of Crest	None	•
Lateral Movement	Minor bulging of dry masonry wall	
Vertical Alignment	on downstream side of dam Good	
Horizontal Alignment	Good (See "Lateral Movement", above)	
Condition at Abutment and at Concrete Structures	Good	
Indications of Movement of Structural Items on Slopes	None	
Trespassing on Slopes	Some bulldozing on downstream side	
Sloughing or Erosion of Slopes or Abutments	of west abutment None	
Rock Slope Protection - Riprap Failures	None	
Unusual Movement or Cracking at or near Toes	None	
Unusual Embankment or Downstream Seepage	Two small seepages near toe of dam, one close to west abutment and one	
Piping or Boils	near center of dam None	
Foundation Drainage Features	None known	•
Toe Drains	None known	•
Instrumentation System	None known	
	i A-2	

PARTY	ORGANIZATION
	DATE May 20 1079
GOVE DIKE, New Hampshir	$\frac{1}{2} \frac{1}{2} \frac{1}$
	WEATHER Sunny, hot
	W.S. ELEV. <u>250</u> 0.5. <u>244</u> DN.S.
	(ground surface below dike)
arren Guinan	6
obert Langen	7
tephen Gilman	Ů
onald Hirschfeld	9
PROJECT FEATURE	INSPECTED BY REMARKS
ydraulics/Hydrology	R. Langen
tructural Stability	S. Gilman
oils and Geology	R. Hirschfeld

.

\$

1

.....

-----

APPENDIX A

CHECK LIST - VISUAL INSPECTION

(3) The NHWRB should develop a written operational procedure to follow in the event of flood flow conditions of imminent dike failure that could include round-the-clock surveillance and a warning system. The warning system should be included also in the written procedures of "Project Linkup", a disaster plan involving Civil Defense (as coordinator), state agencies, and town officials. "Project Linkup", at this time, is in draft form awaiting the Governor's approval. 7.3 b. below should be implemented by the owner within one year.

d. <u>Need for Additional Investigation</u>. The information available from the visual inspection indicates that the problems are overtopping and seepage. These problems require the attention of a competent engineer to design or specify remedial measures to rectify the problems. If left unattended, the problems could lead to instability of the structure.

#### 7.2 Recommendations

a. <u>Facilities</u>. The New Hampshire Water Resources Board should accomplish the remedial measures resulting from the following:

(1) Evaluate further the potential for overtopping and the inadequacy of the spillways for the total impoundment system of Pawtuckaway Pond.

(2) Design or specify the remedial measures needed to eliminate or control the seepage along the downstream toe.

(3) Design the correctional measures for the bulge in the downstream dry-masonry wall.

(4) Remove small trees and brush.

(5) Consider measures required to shape the shoulders and pave the road to eliminate possible erosional problems.

#### 7.3 Remedial Measures

a. Alternatives. The NHWRB should consider as alternatives, pending implementation and results of the above recommendations, (see also Dolloff Dam Report) the following:

(1) Purchase downstream land that would be adversely impacted by failure of Gove Dike and restrict human occupancy.

(2) Enhance the stability of Gove Dike to permit overtopping by the test flood without failure.

b. Operation and Maintenance Procedures.

(1) The seepage at the downstream toe should be monitored on a weekly basis.

(2) The tree and brush growth on the dike and downstream for at least 20 feet should be removed and kept free in the future.

#### 7.1 Dam Assessment

a. <u>Condition</u>. The visual inspection indicates that Gove Dike is in fair condition. The major concerns affecting the overall long-term integrity of the dike are as follows:

(1) The overtopping potential.

(2) The seepage at the downstream toe.

(3) The bulge in the downstream vertical dry masonry wall.

(4) The brush and trees growing on either side of the unpaved roadway.

(5) The possibility of erosion of the unpaved roadway caused by surface runoff from the approach and egress roadways at either end of the dike.

(6) The possibility of erosion of the unpaved roadway if the dike is overtopped.

Because Gove Dike is an integral part of the Pawtuckaway Pond impoundment system that includes Drown's and Dolloff Dams, its relationship to the test flood required hydrologic and hydraulic analyses of all three structures. Under conditions of the test flood all structures are overtopped. The spillway capacity of the combined system is considered inadequate.

Assuming that Drown's and Dolloff Dams do not fail, Gove Dike would be overtopped by 2.9 feet under conditions of the test flood. This depth of overtopping takes into consideration the fact that Gove Dike is about one foot higher than the emergency spillway at Drown's Dam and the low ground adjacent to the left abutment at Dolloff Dam. Gove Dike, however, has stood the test of time - at least 136 years.

b. Adequacy of Information. The information available is such that the assessment of the safety of the dike must be based on the visual inspection.

c. Urgency. The recommendations enumerated in 7.2 below should be implemented by the owner, NHWRB, within two years. The operation and maintenance measures enumerated in

#### SECTION 6 STRUCTURAL STABILITY

#### 6.1 Evaluation of Structural Stability

a. <u>Visual Observations</u>. Visual observations indicated three potential structural problems: (1) seepage downstream of the toe of the dike, (2) localized bulging of the nearly vertical dry masonry wall which comprises the downstream face of the dike, and (3) trees and brush growing on the dike. (See Section 3.1 b.)

b. Design and Construction Data. No design and construction data are available except the sketch contained in a 1918 condition report that was copied from an 1889 document. Apparently the dike was built during the period between 1839 and 1842 and has remained intact for at least 136 years. (See Appendix B.)

c. <u>Operating Records</u>. No operating records pertaining to the structural stability were disclosed.

d. <u>Post-Construction Changes</u>. Some fill has apparently been placed against the downstream face at the right abutment up to approximately the level of the crest roadway. Also, nume ous large boulders (4 to 5 feet in size) have apparently been dumped immediately downstream of the downstream dry masonry wall near both ends of the dike. Neither of these changes would have any adverse impact on the structural stability of the dike.

e. <u>Seismic Stability</u>. This dike is in Seismic Zone 2 and hence does not have to be evaluated for seismic stability according to the OCE Recommended Guidelines.

d. Overtopping Potential. Gove Dike in conjunction with Dolloff and Drown's Dams, is unable to store to test flood without overtopping. The water depth over the lowest point of the crest of the dike was calculated to be 2.9 feet.

Γr

XX

1

C.

Ľ

#### SECTION 5 HYDROLOGY AND HYDRAULIC ANALYSIS

#### 5.1 Evaluation of Features

a. <u>Design Data</u>. No original hydrologic and hydraulic design data (1839-1842) were found for the structures impounding Pawtuckaway Pond. Hydrologic and hydraulic information, however, dating from the ownership by the Lamprey River Improvement Company of the dikes and dams to the present ownership by the New Hampshire Water Resources Board were found and assessed to determine their acceptability in evaluating the overtopping potential of Gove Dike.

Gove Dike is classified as being intermediate in size having a maximum storage of 11,700 acre-feet.

To determine the hazard classification for Gove Dike, the impact of failure of the dike at maximum pool was assessed using Guidance for Estimating Downstream Dam Failure Hydrographs issued by the Corps of Engineers. The analysis covered the reach extending from the dike to the village of West Epping, a distance of about 3 miles. Failure of Gove Dike at maximum pool would probably result in an increase in stage of 6.6 feet at West Epping. An increase in water depth of this magnitude would probably result in the loss of less than 10 lives, sever State Route 156, and damage some agricultural lands.

As a result of the analysis described above, Gove Dike was classified - <u>Significant Hazard</u>. Using OCE Recommended Guidelines for Safety Inspection of Dams, the recommended spillway test flood is the Probable Maximum Flood. The test flood discharge for Pawtuckaway Pond, having a drainage area of 20.66 square miles, was determined to be 11,200 cfs.

b. Experience Data. No information regarding past overtopping of the structure was found.

c. Visual Observations. No visual evidence was found of damage to the structure caused by overtopping at the time of the inspection. At least one house on the reservoir's east bank near the dike has its first floor at or below the crest of the dike.

#### SECTION 4 OPERATIONAL PROCEDURES

#### 4.1 Procedures

The NHWRB has operated Pawtuckaway Pond since 1955. Gove Dike has no outlet facilities. The level of the impoundment is controlled by discharge through Dolloff and Drown's Dams. The water level during the recreational season is maintained reasonably constant (250 feet MSL). In the fall, the level is drawn down, allowing abutters to make improvements to their shoreline and providing some storage for spring runoff.

#### 4.2 Maintenance of Dike

The NHWRB is responsible for the maintenance of Gove Dike.

#### 4.3 Maintenance of Operating Facilities

Gove Dike has no outlet facilities.

#### 4.4 Description of Any Warning System in Effect

No written warning system was disclosed for Gove Dike.

#### 4.5 Evaluation

The operation and maintenance procedures for Gove Dike, consisting of a weekly program of inspection, should insure that all problems encountered can be remedied within a reasonable period of time. The NHWRB should also establish a warning system to follow in event of any emergencies. of these cottages may be susceptable to flooding. No evidence of any buildup of sedimentation is visible. (See Appendix C - Figure 5.)

e. <u>Downstream Channel</u>. Because the structure has no outlet, no defined downstream channel exists. The valley downstream of the dike is wooded, and drains into an unnamed tributary to the Pawtuckaway River. The valley has been cleared of trees for a distance of about 20 feet immediately downstream of the dike. (See Appendix C -Figure 6.)

#### 3.2 Evaluation

The observed condition of the dike is fair. The potential problems observed during the visual inspection are listed as follows:

- (a) Two seepages at the downstream toe of the dike.
- (b) Bulge in the downstream dry masonry wall.
- (c) Brush and trees on both faces.

(d) Crest of dike, being an unpaved road, could be subject to erosion.

SECTION 3 VISUAL INSPECTION

#### 3.1 Findings

a. <u>General</u>. The dike is a low embankment on Pawtuckaway Pond and has no spillway or outlet structures. Drown's Dam and Dolloff Dam are the controlling structures for this pond. Numerous cottages and summer homes are sited around the southeastern portion of the reservoir.

b. Dike. The dike consists of an earth embankment approximately 270 feet long, 9 feet high, and 20 feet wide at the crest. (See Appendix C - Figures 2 and 3.) The upstream side is partially faced with a nearly vertical wall of rounded boulders and the downstream face consists of a vertical dry masonry wall. Boulders comprising both walls range in size from 1 to 3 feet. The crest of the dike was approximately 3.5 feet above the pond level at the time of the inspection. The measured water depth on the upstream side varies up to 5 feet deep. The crest of the dike is an unpaved road, maintained year round (See Appendix C - Figure 4.)

Approximately 100 feet from the left abutment, a bulge was observed in the downstream dry masonry wall. The wall is bulged approximately 6 inches at a height of 4 to 5 feet above the ground level.

Numerous large boulders (4 to 5 feet in size) have apparently been dumped immediately downstream of the dike, near both ends. Two 12-inch trees have recently been cut at the west end of the dike near the downstream toe.

Two seepages were observed. One is estimated at .02 cfs (10 gpm) about 15 feet downstream of the wall near the center of the valley. The second, near the right abutment, has a barely visible flow. Discharge water from both seepages is clear. Standing water is visible approximately 20 feet downstream of the downstream face near the right abutment. Some fill has apparently been placed against the downstream face at the right abutment and filled to approximately the height of the roadway.

c. Appurtenant Structures. Not applicable

d. <u>Reservoir Area</u>. The reservoir slopes along the shoreline are gentle and generally covered with trees and brush. Cottages are scattered around the perimeter. Some

SECTION 2 ENGINEERING DATA

#### 2.1 Design

No original design data were disclosed for Gove Dike.

#### 2.2 Construction

A report prepared by H. F. Dunham for the Lamprey River Improvement Company, dated December 5, 1918 was the earliest investigation found. Dunham's report contains a sketch of a cross section copied from a report by W. M. Oliver, C. E. to Newmarket Manufacturing Co., dated 1889. (See Appendix B.)

#### 2.3 Operation

No engineering operational data were disclosed.

#### 2.4 Evaluation

a. <u>Availability</u>. Very little engineering data were disclosed for Gove Dike. A search of the files of the NHWRB revealed only a limited amount of recorded information.

b. <u>Adequacy</u>. Because of the limited amount of detailed data available, the final assessments and recommendations of this investigation are based on visual inspection and hydrologic and hydraulic calculations.

c. Validity. The visual inspection is generally consistent with the 1889 sketch for the exposed portions of the dike.

- (3) Height 11' (structural height)
- (4) Top width approximately 20'
- (5) Side slopes nearly vertical
- (6) Zoning unknown

Ċ

- (7) Impervious Core unknown
- (8) Cutoff unknown
- (9) Grout curtain unknown
- h. Diversion and Regulating Tunnel not applicable

5

i. <u>Spillway</u> - none

PROJECT Gove Dike, New H	Aampshire DATE May 30, 1978
PROJECT FEATURE Reservoir	NAME R. Langen
Pawtuckaway Pond	
AREA EVALUATED	REMARKS
Stability of Shoreline	Good
Sedimentation	Minor
Changes in Watershed Runoff Potential	Minor
Upstream Hazards	Several homes along eastern shore
Downstream Hazards	State Highway 156, nearest villag
Alert Facilities	downstream. None
Hydrometeorological Gages	None
Operational & Maintenance Regulations	None
,	

Ś

### APPENDIX B

## INSPECTION REPORTS/SKETCHES

( )

## NEW HAMPSHIRE WATER CONTROL COMISSION

GOVE DIKE

**b**r

Ĩ

1

REPORT ON DAM INSPECTION

spected by mo on _	12/21/49	iccommind hy
Abutments	<u>G</u>	(G∞D)
Soillway	Sinc.	(NONE)
<u>Gates</u>	Ving.	(NONE)
Other	a. /	(EHBINKHENT - GOOD)
<u>2.1275</u>	- 11 / / / / / - 110 lo 11 o 10 o 10 o 10 	1 of inter (Small head at a 2 (-FAWTVCKAWAM Pr 
<u>Copy</u>	- 11 /	(Francis Moore)

# NEW HAMPSHIRE WATER CONTROL COMMISSION

GOVE DIKE

23

REPORT ON DAM INSPECTION

MER LANGUER Rock	In inserved in	ADDRESS CALL FOR CALLER CALL
In accordance w nspected by me on _	ith Section 20 of C <u>1- 12/20</u> ac 12/21/49	hapter 133, Laws of 1937, the above dam was
OTES ON PHYSICAL CO Abutments	<u>NDITION</u> Gf	(G∞D)
Spillway	Sina.	(NONE)
<u>Gates</u>	Vicel	(NONE)
Other	c. /	(EMBRINENT - GOOD)
DEANGES SINCE LAST I	NSPECTION	
This نصف (is) (	ic not a moraco bo	causo if nor -i ponds)
<u>274,7775</u>	- 11 1. 1. 1. 1. 1. - 11. 1. 1. 1. 1. 1. - 1. 1. 1. 1. 1. 1. 1. - 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.	et is is is all head at di 2.1 - (- PANTVCKAWAY Prod distance of the prod - DROWN'S DAH) way i gates gly good - DROWN'S DAH)
Copy t	o Cyner Date	INSPECTOR (Francis Moore)
		(Additional Notes Crar)
		• •

	F COMMISSION	OF NEW HAMP	PSHIRE-DAM	RECORD	•	ا ۰۰۰ س	
DELIC SERVIC	TINGHAM		TOWN NO.		STATE	184.03	
ven	tuckener Pond (	Dike)			GOVE	DIK	=
RAINAGE - 2	D. 66 Sc. Mi.		POND 93	4.2 Acres			
1EA			FOUNDATION				
FE Gray	vity		NATURE OF	Larth			
INSTRUCTION BOU	lders, Earth						
IRPOSE	POWER-CONSERVATIO						
IGHTS, TOP OF	AM 81		SPILLWAY CH	10 ES78		••	
ALL WAYS. LENGTHS	None				LENGTH 3	50'	
ASHBOARDS	<u>, uom</u>			•			
PE, HEIGHT ABOVE (	CREST		TOP OF FLASI	HBOARDS .		¥1	
IEST TO N. T. W.			TO N. T. W.	••••		<u></u> St:	
NDS & H. P.							
INERATORS, NUMBE	"	·····		·.			
P. 90 P. C. TIME 0 P. C. EFF.			H P. 75 P.C. T 100 P. C. EFF.	IME		• • • •	
IFERENCES. CASES.					• • •	·•	•
EMARKS	· · · ·					_ •	
	4						
A=Drey	River Improvema	ent Co.	RACTOR		NO.		
n=prey c/o P.	River Improveme H. Burrowes, Su RECEIVED	ent Co. Cont upt. Newmarket	RACTOR		NO.	DATE	
c/o P.	River Improvem R. Burrowes, St RECEIVED	ent Co. Cont upt. Newwarket	RACTOR	> BY	NO.	DATE	
CO P.	River Improveme H. Burrowes, Su Received	ent Co. upt. Newmarket	RACTOR	> BY	NO.	DATE	
C/O P.	River Improvem R. Burrowes, St RECEIVED	ent Co. Cont upt. Newwarket	RACTOR INVESTIGATED	> 8Y	NO.	DATE -	
PPLICATION	River Improveme H. Burrowes, St RECEIVED	ent Co. upt. Newmarket would	RACTOR INVESTIGATED BE A MENACE	TO THE PUBLIC	NO.	DATE	
DAM SUBJECT TO P	River Improvem R. Burrowes, St RECEIVED CONSTRUCTED IT ROVISIONS OF P. L. CHA	mould	RACTOR INVESTIGATED BE A MENACE	TO THE PUBLIC	NO.	DATE	
ADDREY c/o P. PPLICATION DAM IMPROPERLY C DAM SUBJECT TO P	River Improvem R. Burrowes, St RECEIVED CONSTRUCTED IT ROVISIONS OF P. L. CHA RECEIVED	mould P. 218. SECTS 13-267	RACTOR INVESTIGATED BE A MENACE CHECKED BY	TO THE PUBLIC	NO. SAPETY	DATE	
DAM IMPROPERLY C	River Improveme H. Burrowes, St RECEIVED CONSTRUCTED IT ROVISIONS OF P. L. CHA RECEIVED	would	RACTOR INVESTIGATED BE A MENACE CHECKED BY		NO. 847ETY	DATE 	
DAM IMPROPERLY C DAM SUBJECT TO P LANS & PECIFICATIONS	River Improvem R. Burrowes, St RECEIVED CONSTRUCTED IT ROVISIONS OF P. L. CHA RECEIVED	mould ssion	RACTOR INVESTIGATED BE A MENACE CHECKED BY COMMISSION C	TO THE PUBLIC	NO. SAPETY	DATE 	
Amprey c/o P. PPLICATION DAM IMPROPERLY C DAM SUBJECT TO P LANS & PECIFICATIONS	River Improveme H. Burrowes, St RECEIVED CONSTRUCTED IT ROVISIONS OF P. L. CHA RECEIVED APPROVED BY COMMIT	mould ssion	RACTOR IN SETIGATED BE A MENACE CHECKED BY COMMISSION C	TO THE PUBLIC	NO. SAFETY :	DATE	
AMDREY C/O P. PPLICATION DAM IMPROPERLY C DAM SUBJECT TO P LANS & PECIFICATIONS	River Improvem R. Burrowes, St RECEIVED CONSTRUCTED IT ROVISIONS OF P. L. CHA RECEIVED APPROVED BY COMMING APPROVAL	ent Co. CONT upt. Newmarket would P 210. SECTS 13-267 SSION	RACTOR INVESTIGATED BE A MENACE CMECKED BY COMMISSION C	TO THE PUBLIC	NO. SAPETY	DATE 	
ATTEN C/O P. PPLICATION DAM IMPROPERLY C DAM SUBJECT TO P LANS & PECIFICATIONS	River Improvem R. Burrowes, St RECEIVED CONSTRUCTED IT ROVISIONS OF P. L. CHA RECEIVED APPROVED BY COMMING APPROVAL TERIODIC INSPECTION?	ent Co. CONT upt. Newmarket would P 218. SECTS 13-267 SSSION Yes	RACTOR INVESTIGATED BE A MENACE CHECKED BY COMMISSION C CHARGES	TO THE PUBLIC	NO. SAPETY	DATE DATE PAID	
ADDREY C/O P. PPLICATION DAM IMPROPERLY C DAM SUBJECT TO P LANS & PECIFICATIONS NAL CONSTRUCTION DAM SUBJECT TO P	River Improveme H. Burrowes, St RECEIVED CONSTRUCTED IT ROVISIONS OF P. L. CHA RECEIVED APPROVED BY COMMING APPROVAL DERIODIC INSPECTION?	ent Co. upt. Newmarket would P. 210. SECTS 13-267 SSION Yes DAM INST	RACTOR INVESTIGATED BE A MENACE CHECKED BY COMMISSION C CHARGES	D BY	NO. SAFETY	DATE 	
AMDREY C/O P. PPLICATION DAM IMPROPERLY C DAM SUBJECT TO P LANS & PECIFICATIONS NAL CONSTRUCTION DAM SUBJECT TO P DATE INAFFC	River Improvem R. Burrowes, St RECEIVED CONSTRUCTED IT ROVISIONS OF P. L. CHA RECEIVED APPROVED BY COMMI APPROVAL SERIODIC INSPECTION? YOB	ent Co. CONT upt. Newmarket Would P 210. SECTS 13-267 SSION Yes DAM INST CHARGED PA	RACTOR INVESTIGATED BE A MENACE CHECKED BY COMMISSION C CHARGES PECTION RECOR	D BY	NO. SAPETY INSPECTOR REPORT	DATE 	
ADDRESS PPLICATION DAM IMPROPERLY ( DAM SUBJECT TO P LANS & PECIFICATIONS NAL CONSTRUCTION DAM SUBJECT TO P DATE INGREC '1 E / 77 C. I	River Improveme R. Burrowes, St RECEIVED CONSTRUCTED IT ROVISIONS OF P. L. CHA RECEIVED APPROVAL DERIODIC INSPECTION? YOB APPROVAL	mould Yould Yes CHARGES	RACTOR INVESTIGATED BE A MENACE CHECKED BY COMMISSION C CHARGES PECTION RECOR	D BY	NO. SAPETY INSPECTOR	DATE 	
ADDREY C/O P. PPLICATION DAM IMPROPERLY C DAM SUBJECT TO P LANS & PECIFICATIONS NAL CONSTRUCTIONS DAM SUBJECT TO P DATE INSPECT	River Improveme H. Burrowes, St RECEIVED CONSTRUCTED IT ROVISIONS OF P. L. CHA RECEIVED APPROVED BY COMMINATION OF A CO	ent Co. Lipt. Newmarket would P. 210. SECTS 13-267 SSION Yes DAM INSE CHARGES PAR	RACTOR INVESTIGATED BE A MENACE CHECKED BY COMMISSION C CHARGES PECTION RECOR	D BY	NO. SAFETY IN SPECTOR PEPORT	DATE 	
ALTERY CONSTRUCTIONS	River Improvem R. Burrowes, St RECEIVED CONSTRUCTED IT ROVISIONS OF P. L. CHA RECEIVED APPROVED BY COMMINANT APPROVAL TOP BY COMMINANT APPROVAL TOP BY COMMINANT CONSTRUCTED IT RECEIVED	ent Co. CONT upt. Newmarket Would P 210. SECTS 13-267 SSION Yes DAM INSE CHARGES PAR	RACTOR INVESTIGATED BE A MENACE CMECKED BY COMMISSION C CMARGES PECTION RECOR	D BY	NO. SAPETY INSPECTOR REPORT	DATE 	
ADDREY C/O P. PPLICATION DAM IMPROPERLY C DAM SUBJECT TO P LANS & PECIFICATIONS NAL CONSTRUCTION DAM SUBJECT TO P DATE INATIC 1 E / 72 C. 2	River Improveme R. Burrowes, St RECEIVED CONSTRUCTED IT ROVISIONS OF P. L. CHA RECEIVED APPROVED BY COMMINANT APPROVAL TERIODIC INSPECTION? TOP TOP TOP TOP TOP TOP TOP TOP	mould Yould Yes CHARGES	RACTOR INVESTIGATED BE A MENACE CHECKED BY COMMISSION C CHARGES PECTION RECOR 0 DATE	D BY	NO. SAPETY INSPECTOR	DATE 	

C

í

	NEU HAMPSHARE WALLER HES DIRAES BOART GOVE	
	INVENIORY OF AND THE FOLLY FOLLY OF FOLLY OF FOLLY	
~ • • •		
<u>PAN</u>		
EASTI RIVER	Ocean NO.	
	Nottingham CHNER Laws Suger	
SUILI	FISCALP I JA Gravity - and earth	
PUID AP	COP TO HED OF C REAL-FT	
DVERALE	LENGTH OF DAM-FF. 350 THX FLOOD HET ME AFOVE CREST-FT.	
EALDIAI	ELST (ABS) [ELST, 9.5, 9.5]         ECAL (ABS) [ELST, 9.5, 9.5]           ER         ELST, 9.5, 9.5]         LOTAL (A) E	
SPILLUA	PREEBOARD-FT. NONE PREEBOARD-FT.	
VASUE 3	MALES-NC. WIDTH MAN. OPENING LEPTE SILL BELCH CREST	
		نې 
		•
RETARY?	Condition Fair	
		Į.
- <u></u>		
POVER I	DEVELOPICED	
URITS	RATED HEAD C.F.S. NO. HP FEED FULL DADE KW MINKE	Ĩ
URITS	RATED HEAD C.F.S. <u>NC. HP FEET FULL DATE KW MAKE</u>	
URITS	RATED     IEAD     C.F.S.       MC.     HP     FEET     FULL     MATE     MATE	
URITS	RATED     IEAD     C.F.S.       MC.     HP     FEED     FULL       FEED     FULL     MDE	
URIIS	RATED     ILEAD     C.F.S.       MC.     HP     FEET     FULL     MTE       HP     FEET     FULL     MTE	
USE	RATED     IEAD     C.F.S.       MC.     HP     FEED     FULL DATE     KW     MAKE	
USE	RATED     IEAD     C.F.S.       MO.     HP     FEED     FULL DATE     KW     MAKE       Image: State of the state o	
USE	RATED         IEAD         C.F.S.           MC.         HP         FEED         FULL DATE         KW         IMKE           Image: State of the state of	
USE	RATED     IEAD     C.F.S.       MC.     HP     FEED     FULL MATE     KW     MAKE	
USE	RATED         C.F.S.         MM         MAKE           MO         HP         FEET         FULL DATE         KW         MAKE           MO         HP         FEET         FUL DATE         KW         MAKE <td></td>	
USE	RATED         C.F.S.           MC.         HP         FEED         FULL DATE         KW         MAKE           Image: State of the state	
USE	PATEN HEAD         C.P.S.         HP         FEET         FULL DATE         KW         IANE	
USE	RATEAN     IEAD     C.F.3.       MC.     HP     FEET     FULL     MTE       HP     FEET     FULL     FULL       HP     FEET     FULL       HP     FEET     FULL       HP     FEET     FULL       HP     FEET       HP	
USE	NC.         HP         FEET         FULL SATE         KW         FAKE	
USE	PANEAN         N.P. S.         KW         KMKE	
USE	NC.     HP     FEET     FULL BATE     HW     FAKE	
USE	NC.     HP     FEET     FUIL MATE     KW     MAKE	
USE FEMARA	NC.     HP     FEET     FUIL MADE     KW     FAKE	
USE FEMARA	B-3	
USE FEMARA	P.C.     HP     FEET     FULL MATE     KK     PAKE	

.

•

•

10

(

UBLIC SERVICE COMMISSION OF NEV	V HAMPSHIRE-DAM RECORD I-452?
own Nottinghum	NO 3 NO // 1. 6
iven Protuckersy Pond (Dike	)
RAINAGE ::D.EC.EC. MI.	AREA DEL. Cros
AM Chinida	FOUNDATION Farth
ATERIALS OF Foundary Firth	
URPOSE POWER-CONSERVATION-DOMES	ITIC-RECREATION-TRANSPORTION-PUBLIC UTILITY
	TOP OF DAN TO
AM TO BED OF STREAM 81	SPILLWAY CRESTS
EPTHS BELOW TOP OF DAM	OF DAM 5501
LASHBOARDS YPE. HEIGHT ABOVE CREST	
PERATING HEAD	TOP OF FLASHBOARDS
HEELS, NUMBER	
INDE & H. P.	
INDS & K. W.	H. P. 75 P. C. TIME
DOP C. EFF.	100 P.C. EFF.
LANS. INSPECTIONS.	
EMARKS	
TINE- Leagrey Fiver Improvement	ant Company
DUCITION- Feir	
TT OF You Will be subject	to poniodia inclusion
	to berroute inside trait
	· · · · · · · ·
	· - · · · · · · ·
To the Public Service	Commission:
The Concerning particular on the	the demission is submitted covering inspection
a de tagatté, 1983, recording to no « Chi ' far chas is enclosed.	tification to pager dated July 21, 1915;

B-4

TOWN	ידכו	TIGHAM		TOWN NO.	3	STATE	101/	FY
	Paw	tuchaway Pond	(Eike)		· · · · ·	GOVE	DIKE	= :
DRAINAGE				POND				=. <u>`</u>
		10.05 29. 1	±•	AREA			<u></u>	
DAM TYPE	Gra	vity		NATURE OF	Earth	<u>.</u>		
MATERIALS	SOF 50L	lders, Earth.	-					
PURPOSE	•	POWER-CONSERVAT	ION-DOMESTIC-RECRE	ATION-TRANSPO	RTATION-PUBLIC	UTILITY		
HEIGHTS, T		. 8'	· · · · · · · · · · · · · · · · · · ·	TOP OF DAN	10	•	• •	
SPILLWATS	S. LENGTHS	None			•	LENGTH	3501	]
DEPTHS BE	RDS	DAM HONE			·····	OF DAM	1	
TYPE HEIG	HT ABOVE CI	1EST						
OPERATING	5 HEAD N. T. W.	• ·	•	TOP OF PLA		·	· · ·	
WHEELS. N	UMBER							
KINDS & H	RS, NUMBER	·······						
KINDS & K	. w.				TIME			
H. P. BO P.	C. TIME			100 P. C. EPI	· · · · · · · · · · · · · · · · · · ·		· · ·	
REFERENC	ES. CASES,							
PLANS, INS	SPECTIONS.	· · · ·		<u></u>			· · · ·	 
-								1
INER	, Lampre:	Fiver Impr	ovement Co.	CONTRACT		· · · · ·	NO.	
NER	 Lanpre: 	Fiver Impr H. Eurrowes RECEIVED	ovement Co. , Eust. Newma	CONTRACT Thet	OR		NO.	218 57
NER	 Lanpre: .c/o つ:	Eiver Impr <u> H. Burrowes</u> Received	ovement Co. , Eust. Newma	CONTRACT Thet Investigate	OR 0 BY		NO.	218   
APPLICAT	Lampre: .c./o .c./o	River Impr H. Burrowes RECEIVED	ovement Co. , Euot. Newma	CONTRACT Fket Investigate	OR D BY		NO.	218 7
NER	Lanpre: .c./o つ:	Fiver Impr <u> H. Burrowes</u> RECEIVED	ovement Co. , Supt. Newma	CONTRACT rket investigate	OR 0 BY		NO.	21R
APPLICAT		Siver Impr H. Burrowes Received HSTRUCTED IT WO	ovement Co. , Eust. Newma	CONTRACT TROT INVESTIGATE			NO.	21R
APPLICAT	Lampre: .c./0	A Siver Impr <u>H. Burrowes</u> Received ASTRUCTED IT WO VISIONS OF P. L. CHA	ovement Co. , Eust. Newma uld F. 218. SECTS 19-247	CONTRACT INVESTIGATE BE A MENACI Yes		BAFETY *	NO.	21R
APPLICAT	Lampre: .c/0 7.	Siver Impr <u> H. Burrowes</u> <u> Received</u> <u> Hotal</u> <u> Hot</u>	ovement Co. , Supt. Newma uld	CONTRACT TRET INVESTIGATE BE A MENACI Yes Checked by	OR D BY E TO THE PUBLIC S	BAFETY *	NO. DATE	21R
NER APPLICAT P DAM IMP S DAM SUB	LANDTE: 	Siver Indr S. Burrowes Received INSTRUCTED IT WO VISIONS OF P. L. CHA RECEIVED	ovement Co. , Eust. Newma uld P. 210. SECTS 19-207	CONTRACT TROT INVESTIGATE BE A MENACI Yes Checked by	OR D BY E TO THE PUBLIC S	BAFETY .		21R
APPLICAT	LENDIE:	Piver Impr H. Burrowes Received Astructed it WO V-Sions of P. L. CHA Received	ovement Co. , Euot. Newma uld F. 210. SECTS 13-201	CONTRACT INVESTIGATE	OR D BY	BAFETY *		21R
APPLICAT	LEADTE: 	APPROVED BY COMMI	ovement Co. , Supt. Newma uld P. 219. SECTS 15-207	CONTRACT INVESTIGATE INVESTIGATE BE A MENACI Yes Checked by Commission	OR D BY E TO THE PUBLIC S CONSTRUCTION IN	SAFETY *	NO. DATE	
APPLICAT	LANDTE: 	APPROVED BY COMMI	ovement Co. , Eust. Newma uld P. 210. SECTS 19-247	CONTRACT TKOT INVESTIGATE BE A MENACI Yes CMECKED BY COMMISSION	OR D BY E TO THE PUBLIC S CONSTRUCTION IN	SAFETY *	NO. DATE	21R
NER APPLICAT F DAM IMP S DAM SUB PLANS & SPECIFIC	TION	APPROVED BY COMMI	ovement Co. , Eupt. Newma uld P. 210. SECTS 19-207	CONTRACT TKOT INVESTIGATE BE A MENACI Yes Checked by Commission Charges	OR D BY E TO THE PUBLIC S CONSTRUCTION IN	SAFETY .	NO. DATE DATE DATE PAID , .	21R
NER APPLICAT P DAM IMP S DAM SUE SPECIFICA INAL CONS	LEIDTE: C/O	APPROVAL	ovement Co. , Supt. Newma uld P. 219. SECTS 19-207 SSHOM	CONTRACT Thet INVESTIGATE BE A MENACI Yes Checked by Commission Charges	OR D BY E TO THE PUBLIC S CONSTRUCTION IN	SAFETY *	NO	
NER APPLICAT P DAM IMP S DAM SUB SPECIFICA	LATIONS	APPROVED BY COMMI	ovement Co. , Eust. Newma uld P. 219. SECTS 19-247 SSION Yes DAM INSPE	CONTRACT TROT INVESTIGATE BE A MENACI Yes CMECKED BY COMMISSION CHARGES CTION RECOF	OR D BY E TO THE PUBLIC S CONSTRUCTION IN	SAFETY *	NO	
APPLICAT P DAM IMP S DAM SUB PLANS & SPECIFICA INAL CONS S DAM SUB DATE	LENDTE: 	APPROVED BY COMMI	ovement Co. , Eupt. Newma uld P. 210. SECTS 13-247 SSION Yes DAM INSPE	CONTRACT TKet INVESTIGATE BE A MENACI Yes Checked by Commission Charges Ction Recof	OR DBY ETOTHE PUBLICS CONSTRUCTION IN CONSTRUCTION IN RD	SAFETY .	NO. DATE DATE DATE PAID CHADEID	21R
NER APPLICAT F DAM IMP S DAM SUB DLANS & SPECIFIC/ INAL CONS S DAM SUB	LENDTE: .c./O 7. FION - PROPERLY COL BJECT TO PRO ATIONS - STRUCTION A DJECT TO PER	APPROVED BY COMMINSPECTIONS	ovement Co.         , Eupt. Newma         uld         P. 210. SECTS 13-201         SBION         Yes         DAM INSPE         CHARGIN         -24.00         725	CONTRACT TKet INVESTIGATE BE A MENACI Yes Checked by Commission Charges Ction Recop	OR D BY E TO THE PUBLIC S CONSTRUCTION IN CONSTRUCTION IN RD	SAFETY ····································	NO. DATE DATE DATE PAID CH-9619	21R
APPLICAT P DAM IMP S DAM SUE PLANS & SPECIFIC/ INAL COMS S DAM SUE DATE /6/25	LATIONS	APPROVED BY COMMINSPECTIONS	ovement Co.         , Eupt. Newma         uld         P. 210. SECTS 15-247         SBION         Yes         DAM INSPE         CHARGES         34.00         35	CONTRACT INVESTIGATE INVESTIGATE BE A MENACI Ye S CHECKED BY COMMISSION CHARGES CTION RECOF	OR D BY E TO THE PUBLIC S CONSTRUCTION IN CONSTRUCTION IN RD	BAFETY *	NO	21R
NER APPLICAT P DAM IMP S DAM SUB PLANS & SPECIFIC/ INAL CONS S DAM SUB DAVE (6/25)	LEIDTE: 	APPROVED BY COMMI	ovement Co.         , Eupt. Newma         uld         P. 210. SECTS 13-207         SSION         Yes         DAM INSPE         cmansis         35	CONTRACT TKet INVESTIGATE BE A MENACI Yes Checked by Commission Charges Ction Recop	OR D BY E TO THE PUBLIC S CONSTRUCTION IN CONSTRUCTION IN RD	SAFETY *	NO	21R
APPLICAT P DAM IMP 3 DAM SUB PLANS & SPECIFIC INAL CONS 5 DAM SUB DATE CATS		APPROVED BY COMMI	ovement Co. , Eupt. Newma uld P. 210. SECTS 13-247 SSION Yes DAM INSPE CHANGES PAID 34.00 10/10 35	CONTRACT TKet INVESTIGATED BE A MENACION Yes Checked by Commission Charges Ction Record	OR D BY E TO THE PUBLIC S CONSTRUCTION IN RD	BAFETY *	NO. DATE DATE DATE PAID CHASCIS	21R
NER APPLICAT P DAM IMP S DAM SUB PLANS & PECIFIC INAL COMS I DAM SUB DATE (6/25) Canas	LEMPTE: .c./0 7. FION FROPERLY CON BJECT TO PRO BJECT TO PRO BJECT TO PRO ATIONS STRUCTION A DJECT TO PER INSPECTOR INSPECTOR	APPROVED BY COMMI	ovement Co. , Eupt. Newma uld P. 210. SECTS 13-207 SSNON Yes DAM INSPE CHANGIN PAID 34.00 10/14 35	CONTRACT TKet INVESTIGATE BE A MENACI Yes Checked by Commission Charges Ction Recof	OR D BY E TO THE PUBLIC S CONSTRUCTION IN RD	SAFETY	NO. DATE DATE DATE PAID CHAPCIE	21R 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7

r-

.

2

D

B-5
	A ON DAME IN THE STATE	
DCATION	GOVE DICE STATE NO. 131-0	
	(Nottingham); County 313 (SC	ia (ford)
Stroom	· (Pawtuckaway)	
Basin Primary Ocean	: Secondary	-
Bash-Frinary		
Coordinates Lat 43 51 -	800 : Long. 71'101 - 2200	** ••• • • • • • • • • • • • • • • • •
ENERAL DATA		
Drainage area: Controlled		23. Sq. Mi.
Overall length of dam	ft.: Date of Construction	
Height: Stream bed to highest	elev3ft.: Max. Structure	ft.
Cost—Dam	: Reservoir	
ESCRIPTION 32 wity	Boulders and a with Foundation a rich	
Waste Gates (Gravity	Boulders and earth Foundatim carth)	
Туре		
Number: Si	ize ft. high x	ft. wide
Elevation Invert	:: Total Area	sq. ft
Hoist		************
Waste Gates Conduit		
Number		
Sizeft.: Len	igthIt.: Area	sq. fl -
Embankment	(Earth)	
Туре	4+ • Nin	
Height—Max.		Il 2
TopWidth	Downetraam	
Slopes-Upstream	· Left of Snillway	
Length-Right of Spillway		
Spillway none 1 Materials of Construction		*****
Langth_Total	ft.: Net	f
Height of permanent section	on-Max	
FlashboardeType	: Height	
riashooarusrype	st:: Top of Flashboard	
Elevation-Permanent Cres	cis/sa. m	i
Elevation—Permanent Cres	······································	<del></del> _
Elevation—Permanent Cres Flood Capacity Abutments		
Elevation—Permanent Cres Flood Capacity Abutments Materials:		
Elevation—Permanent Cres Flood Capacity Abutments Materials: Freeboard : Max	ft.: Min.	
Elevation—Permanent Cres Flood Capacity Abutments Materials: Freeboard : Max. Headworks to Power Devel		
Elevation—Permanent Cres Flood Capacity Abutments Materials: Freeboard: Max. Headworks to Power Devel OWNER		
Elevation—Permanent Cres Flood Capacity	ft.: Min. -(See "Data on Power Development") I provement Condition fair)	
Elevation—Permanent Cres Flood Capacity	ft:: Min. —(See "Data on Power Development") I. <u>provenent</u> 22. ft:: ft: (Condition fair)	
Elevation—Permanent Cres Flood Capacity	f.: Min. -(See "Data on Power Development") International Condition fair) 6 inspection	
Elevation—Permanent Cres Flood Capacity	f.: Min. -(See "Data on Power Development") Larourement 22. f.ir (Condition fair) d inspection	
Elevation—Permanent Cres Flood Capacity Abutments Materials: Freeboard: Max. Headworks to Power Devel- OWNER REMARKS Condition By	ft:: Min. -(See "Data on Power Development") I.mrovation for fair ft:: (Condition fair) d inspection Date	
Elevation—Permanent Cres Flood Capacity Abutments Materials: Freeboard: Max. Headworks to Power Devel- OWNER REMARKS Condition By HAB21234	ft.: Min. -(See "Data on Power Development") I provident 20. fair (Condition fair) d inspection Date	

-

\*

D

Town No. 3
$\begin{array}{c c} & \mathbf{C} & \mathbf{C} & \mathbf{C} & \mathbf{C} \\ & \mathbf{D}_{a} & \mathbf{b} \\ & \mathbf{D}_{a} & \mathbf{b} \\ \end{array}$
OwnerLomproy River Inprovement Company
River or Stream
Public Utility
Wheel Capacity II. P
Type of Construction
Height
Length170
Would Failure of Dam do Harmt
Present ConditionGoodDate1922 THE LVB Good 1925

r

(

.

. .

•

R

### PAWTUCKAWAY AND MENDUM PONDS

## REPORT FFOM H. F. DUNHAM

to

D. A. BELDEN, PRESIDENT

LAMPREY RIVER IMPROVEMENT COMPANY





M. AV. SOC. C. B. M. Cleveland Enginetoing Society M. Autoican Water Nooss Association

December 5, 1918.

Mr. D. A. Belden, Prosident, Lamprey River Improvement Company, Haverbill, Mass.

Dear Sir:-

Agreeably to your request, I have made a study of conditions pertaining to the two artificial reservoirs owned by your company, known as Pawtuckaway Lake and Mendum Pond, both of which are in the towns of Nottingham and Barrington, New Hampshire. I have kept in view your desire to be informed concerning the type of construction and present condition of the various dams, spillways and controlling apparatus, and particularly as to any defects which should be remedied in the interest of public safety to life and property.

1. The reservoirs are within the drainage area tributary to the Lamprey River ten to fifteen miles westerly from Newmarket, N. H. The area tributary to each reservoir is not definitely known but has been estimated at about six square miles for the Kendum Reservoir and twenty square miles for the Pawtuckaway. Kore exact determination would have been made but for the fact that the U. S. Geological Survey is now plotting the notes of a quadrangle covering the reservoirs and their drainage districts. Both of the reservoirs are formed by dams built at the outlets of these small lakes and at overflow points where the higher elevation of water would cause a discharge into a depression or ravine at a distant point. There are three dams at Pawtuckaway as attached map shows, known locally as "Dollof

Dam", "Drown's Dam", and the "Gove Dam" indicated on the map respectively as Dams No. 1, 2 and 3. At Mendum's Pond there is but one dam, located at the main outlet and lying partly in the town of Barrington and partly in the town of Nottingham. hereinafter referred to as the "Mendum Dam". The dams were designed and built very nearly as they are at the present time in or between the years 1839 and 1842.

-2-

#### Type of Dams.

2. In a comprehensive work on "Reservoirs for Irrigation Water Power and Water Supply", published in 1900, Mr. James D. Schuyler, M. Am. Soc. C. E., devotes some seventyfive pages to rock-fill dams. His discussion in part follows:

"Rock-fill dams may be said to have originated forty or fifty years ago in the mining districts of California.....in difficult and almost inaccessible locations.....and were considered to be of a temporary nature.....They began with timber or log cribs filled with loose stone. Their next stege was an embankment of loose stone, a portion of which was laid up as a dry wall with a facing of two or more thicknesses of plank to secure water tightness. The latter type has proven so serviceable that it is still regarded as one of the most desirable classes of dam that can be built where economy is of prime importance."

Then follows an outline description of six types of rockfill dems--including these two.

"2. Rock-fill dams with a central core of steel plates and without hand-laid facing wells."

"4. Rock-fill dams with facing of masonry built verticslly backed with earth and covered on the lower side with blocks of stone laid in mortar."

Now all of these reservoir dams under consideration on the Lamprey water shed are rock-fill dams and not only were they cuilt long before the mining days in California but they

B - 10

-2-

possess permanent features, in the broad puddled clay-andgravel cores and heavy retaining walls, superior to any of those described by Mr. Schuyler. More information about the design, the designer and the degree of originality in the construction of these dams would be very interesting. Τt is quite possible that the "type" had its origin in those structures. The dams have caused some anxiety at different dates and changes have been recommended and some have been made at dates that show the existence of faulty work elsewhere rather than in the dams themselves. Soon after the Mill river disester in Kassachusetts, in 1874, and again after the Johnstown flood in 1989, studies were made and the core walls in some places reinforced. In the writer's opinion there has not been a moment since the dams were built that they were unsafe -except from overtopping in some deluge too severe for the spillways to accomodate. It is of eye witness record that the water has been within an estimated "two feet" of the top of the Mendum dem and send bags have been used on the Pawtuckeway dem No 1 on the water face wall to divert the flood to the spillway. This should not have been necessary.

-3-

Pawtuckeway - Dams No. 1, 2 and 3.

3. The dams leak a little. It may be said that all core wall dams do leak. Personal observations for more than two years, and at many different stages of water in the Pawtuckaway reservoir have been recorded, and the leaks in the main Dam (No. 1) measured in a channel constructed for that purpose. The main and waste gates do not close perfectly, but well enough for all reservoir purposes. Some water escapes at the gates--

-3-



AFFENDIX C PHOTOGRAPHS











х



26.5 100.61 Earth Fill. 20 100 10:0 00.90-1/ON noi Bettress. 0390-72 20 d'a 9.0 1945 Emboniment of cabble stones. 55 7430 VIA The Stand State Stat Partial 57.60 1 المعالية والمنابع المركانية المركانية والمنافع والمحافظ والمعالية والمركانية والمحافظ والمحافظ والمحافظ والمحافظ Cross Section 94 DOLLOF DAM. (No 1) Nottingham N.H. Scole 10 to the inch. Copied Nov. 1918 by JH. Litchfield from drowings in a report by M. Oliver C.E. to the Henmortet Manufacturing Co. doted 1889 --9-B-17



#### Mendum's.

At the Lendum reservoir there is less need to make changes. The bottom of the present spillway should be brought to a uniform level and all growth of small trees and obstacles of all descriptions, driftwood, old stumps, etc. should be removed and the entire space kept clear. One further recommendation needs attention at your convenience. The upstream wall at Mendum's is of very large rough stone, boulders for the most part, and at two or three places these have cracked under the pressure which has been concentrated at various points by the removal, through frost action in nearly a hundred years, of many of the smaller stones used in construction to level up and give added bearing surface. Lest month many restorations to early conditions were made by replacement without mortar, but with much work and careful attention to strengthening the wall.

There are however three places where steel tie-rods should be introduced at a depth of about eight feet from the surface to check further outward movement at points where the overhang or bulging amount to 12 or 14 inches. The tie-rods should be not less than  $2\frac{1}{4}$  inches in diameter with upset ends and provided with washers or crabs 3 or 4 feet in diameter. The location of the rods and a section is shown in Fig. 2 on the last sheet attached to this report. The rods should be free from rust bedded and packed in fine gravel concrete in proportions 1, 2, 3. Very little need be used. The exposed parts should be painted. Then with general supervision and economic control the reservoirs should continue for a long time to give good service without causing you any anxiety or disquiet.

Yours truly.

H.F.D./R.

with hadden

B-15

-7-

with stems of wood and ratchet connections. These gates are evidently of later construction and are backed up by brick work and two or three braces of wood extending to the solid ledge below the dam where the ends are bolted down. It would be simple and good construction to spring a brick arch between the vertical stone walls to hold the gate frames in place. It is within reason to think that the brick work and braces were placed asthey are so that under certain pressures due to flood conditions, and perhaps with a little help, the whole construction, brick work, gates and timbers would be swept out of the way, much increasing spillway capacity. But whether that inference be correct or not, there can be no apparent harm in leaving the structure in its present condition or in replacing the wood braces when that becomes necessary.

-6-

At the Drown Dam (No.2) there are stop planks retained by timber braces more or less decayed. Renewals should be made as time may require. But all of the Pawtuckaway spillways real and imaginery, taken together, are insufficient for a drainage area of twenty (20) square miles. This can be shown conclusively by precipitation records personally witnessed where the annual totals are below those of southern New Hampshire. To provide more ample spillway capacity the Gove Dam (No.3) should be lowered or reduced in elevation about three feet over a length of two hundred and fifty feet in two sections of one hundred and twentyfive feet each as showh in Fig. 1 in the last sheet hereto attached. This will afford in addition to the other spillways a free flow for a great volume of water whenever the  $n^{-1}$  sity arises. That may not be once in a century.

-6-

Their records were virtually barometer readings.)

#### Gate Repairs.

-5-

4. The main gates at the Mendum reservoir set in a wood from had suffered from decay making it difficult to fix upon a satisfactory estimate of leakage. Rocky creek-bed conditions below the dam interposed further difficulties. But nothing serious was observed. The gates and gate frames have just been renewed as you directed, necessary pointing in their vicinity attended to and the reservoir is now filling.

Report by Mr. W. M. Oliver, C. E.

5. In the year 1889 Kr. Oliver made a very comprehensive and valuable report upon all of these dams for the Newmarket Manufacturing Company, and this report with maps, sketches and figures is now in your possession. The maps and cross sections have been checked up carefully and found to be surprisingly accurate. This includes restored base-line measurements and distances to faces of walls. Also deep excavations were made at Mendum's to show that his cross sections were reliable. The more essential sections have been copied freely and are shown in the ink prints attached hereto with well deserved credit to Mr. Oliver in each case.

#### Recommendations.

6. At Pawtuckaway Dam No. 1 the main gate is at the original level of the stream and is about twenty inches by fifty inches (20" x 50"). It is raised by a wood stem with nut and screw. The stem and timber support within the gate house should be renewed at no distant date. Between this gate and the spillway there are two waste gates each three feet by three feet (3' x 3')

-5-

some through the dam itself -- but all that comes through the core wall is always perfectly clear, and a recent measurement .-November 18, - when the surface of the water in the reservoir was two and eight tenths feet below the spillway gives a good idea of present conditions. The total volume discharged was four and eight tenths second feet, of which it was estimated one half leaked through the gates, or reached the stream in the quarter of a mile between the dam and the measuring channel. The leakage is nearly the same in volume from each helf of the dam as may be observed where it flows laterally along the buttressed lower slopes of the dam to the main gateway, the sides of which are walled up vertically from the creek bed. The volume discharged is not large considering the extent of the core wall and the pressure to which it is subjected. A recently examined earth and core wall dem, built over forty years ago in another State, could well be cited here. The dam was more than a fourth of a mile long and about thirty-five feet high. From the first there was leakage. More material was added at the foot of the water slope. Able engineers were called and accurate gaging kept for many years and recorded in annual reports. Following one of these is the comment. -

"The only variation in the discharge from the weirs appears to be due to changes in the weather."

The same statement would doubtless hold good at the Pawtuckaway and Mendum reservoirs were they accurately gaged. The early water supply for London, England, was from springs that were carefully gaged as the demand increased. Then it was observed that the discharge was greater before than it was after a rain storm.

-4-



C

Figure 2 - Looking at the upstream face of the dike from the west bank of the reservoir.



Figure 3 - View taken from the west abutment looking east at the downstream face.

C-1



Figure 4 - Looking west along the center of the dike from the east abutment.



Figure 5 - View looking upstream at Pawtuckaway Pond from the center of the dike.

C-2



K B

ĩ

Figure 6 - Looking at the downstream valley from the top of the dike.

# APPENDIX D HYDROLOGY/HYDRAULICS

R

1

(



HH GOVE DIKE 1018 6/29/78 HYDROLOGY PAWTICKAWAY LAKE STEP 1: PROBABLE MAXIMUM FLOOD DETERMINATION (PMF) RE; PRELIMINARY GUIDANCE FOR ESTIMATING MAXIMUM PROBABLE DISCHARGES IN PHASE I DAM SAFETY INVESTIGATIONS, NED - COE, MARCH 1978 USING FURT & COASTAL CURVE TO DETERMINE PMF PEAK INFLOW DA = 19.9 square miles (ANG) DA = 20.66  $DA = 18.0 \pm 11$  DA = 21  DA = 20.66 sque miles PMF = 590 cfs/sy mile  $PMF = \frac{590 \, cfs}{s_{\rm mile}} \times 20,66 \, s_{\rm l} \, \text{miles}$ (QRI) PMF= 12,200 cfs **D-**2

2018 85/1/F HYDROLOGY FRUITUCKAWAY LAKE STEP Z: Q  $\varphi_{p_1} = PMF = 12,200$  cfs SURCHARGE HEIGHT TO PASS QΡ. RE: HYDRAULIC BACKUP FOR EACH INDIVIDUAL STRUCTURE ; 10: RATING CURVES TRIAL 1 - elev = 28.6 GOVE DIKE = O DROWN'S DAM = 823 cfs DOLLOFF DAM = 1096 cfs 1919 cfs TRIAL 2 - elev = 30.0GOVE DIKE = 617 cfs DROWN'S DAM = 16362243 DOLLOFF DAM = 4496 cfs TRIAL 3 - elev = 31.0 GOVE DIKE = 1455 DROWNS DAM = 2787 3842 DOWOFF DAM = 8084 cfs TRIAL 4 - elev @ 32.0 GOVE DIKE = 3382 DROWN'S DAM = 5062 DOLLOFF DAM = 642711.071 . (-D-3

Ņ

D

3018
HYDEOLOGY DAWTUCKAWAY LAKE BO
FROM THE ABOVE TRIALS A RATING CURVE FOR THE LAKE CAN BE DRAWN, READING THE ELEVATION AT THE PMF
@ PMF = 12, 200 cfs elev = 31.65
GOVE DIKE = $2596 cfs$ DOLLOFF DAM = $54.30$ DROWN'S DAM = $4127$ 12153 cfs
SINCE THIS IS LESS THAN PMF ROUND ELEVATION UP TO 31,7
: SURCHARGE HEIGHT = 31.7 - 25.0 = 6.7 (ABOVE SPILLWAY)
INVENVORY - DAM HAX NOBYAL Dolloff Dam 14700 11500 Gove Dike 14700 11500 Drown's Dam 14700 11500
Normal lake level = 903 A @ elev 25.0 (Spillwar) elevatim 260 (QUAD) = 1482 A @ elev 25+10 = 35.0
STOR @ $31.7 = 13700  \text{AF}$ see STR-ELEV @ 25.0 = $11500  \text{AF}$
: STOR, (SURCHARGE) = 2200 AF

Υn

 $\bigcirc$ 

÷

•





D - 6



748  
DEOLOGN 7/10/78  
TUCKENIAY LAKE 7/10/78  
TUCKENIAY LAKE 7/10/78  
EP 30) SUBCHARGE HEIGHT TO PASS 
$$Op_2$$
  
 $Op_2 = 10916 cfs$   
FROM EATTING CURVE:  $Clev = 31.46$ .  
SUBCHARGE HEIGHT =  $31.46 - 25.0 = 6.46^{\circ}$   
FROM STORAGE HEIGHT =  $31.46 - 25.0 = 6.46^{\circ}$   
FROM STORAGE HEIGHT =  $31.46 - 25.0 = 6.46^{\circ}$   
FROM STORAGE HEIGHT =  $31.46 - 25.0 = 6.46^{\circ}$   
FROM STORAGE HEIGHT =  $31.46 - 25.0 = 6.46^{\circ}$   
FROM STORAGE HEIGHT =  $31.46 - 25.0 = 6.46^{\circ}$   
FROM STORAGE HEIGHT =  $31.46 - 25.0 = 6.46^{\circ}$   
FROM STORAGE SUBLARGE =  $2000 \text{ AF}$   
 $502 \oplus 31.46 = 13500 \text{ AF}$   
 $502 \oplus 31.46 = 13500 \text{ AF}$   
 $502 \oplus 31.46 = 13500 \text{ AF}$   
 $1.900 \text{ AF} \times \frac{1}{20.666} \text{ mi2} \times \frac{mi2}{640A} = 0.151 \text{ BF}$   
 $1.9'' \times 20.66 \text{ mi2} \times \frac{181}{12''} \times \frac{640 \text{ A}}{1\text{ mi2}} = 2094 \text{ AF}$   
 $2094 \text{ AF} + 11500 \text{ AF} = 13594 \text{ AF}$   
 $D-8$ 

898 HYDROLOGY 7/10/78 PAWTUCKAWAY LAKE FROM SOR-ELEV CURVE: @ 13594 AF - elev = 31,5 FROM RATING CURVE : 31.5 = 11200 cfs = PPS CHECK of V2 PEAK OUTFLOW 1/2 PEAK OUTFLOW = 5600 CFS FROM RATING CURVE 5600 crs - 30,41 Pr D-9

$$|d|3$$

$$\frac{1}{46} \frac{1}{12}$$

$$\frac{1}{46} \frac{1}{12} \frac{1}{12}$$

$$\frac{1}{46} \frac{1}{12} \frac{1}{12}$$

$$\frac{1}{46} \frac{1}{12} \frac{1}{12} \frac{1}{12} \frac{1}{12}$$

$$\frac{1}{46} \frac{1}{12} \frac$$

2013 5, @ 29,3 H = 0.7' OVER WEIR Q H= 0,4' L= 275'  $Q = CLH^{3/2}$ =(2,7)(275)(0,4)3/2 = 187.8 cfsADD NO WHIS TRIAL 2 187.8 + 31.2 = 219.0 H= 1.0' OVER WER 2. @ 29.6 1 H= 0.3' L= 327' ì  $\varphi = CLH^{3/2}$ =2,7(327)(0,3)3/2 = 145.1 cfsADD TO THIS THE PREVIOUS TRIML 145.1+ 219.0=> 364.1 1+ = 1.4' OVER WEIR 1. @ 30,0 · 1+= 0.4' L= 370'  $\varphi = CLH^{3/2}$ =2,7(370)(0,4)3/2 = 252.7 ADD 40 11+15 THE PREVIOUS TRIAL 252,7+364.1 = 616.5 3. @ 30.4 H= 1.8' OVER WEIR  $Q = (2.7)(417)(0.4)^{3/2} + 616.8 = 901.6 \text{ cs}$ D-11






PAWAUCKAWAY LAKE GOVE DIKE BO 8/16/78 DOWNISTREATIN HARAPD

ASSUME FAILURE AF FULL POOL CONDITIONS. FULL POOL IS DEFINED AS MAXIMUM POOL

GOVE DIKE MAX POOL = 252,7 MSL

PEAK FAILURE OUTFLOW FROM BREACH :

$$\varphi_{B} = (8|27) \ Wb \ \int g \ y^{3/2}$$

Wb = BREACH WIDTH g = 32,2 ft/sec<sup>2</sup> y = POOL LEVEL - RIVER BED 1013

ASSUMING OTHER STRUCTURES HOLD ? BREACH WIDTH = 50'

REACH 1

(

$$\mathcal{P}_{B} = \left(\frac{8}{27}\right) (50) (\sqrt{32.2}) (252.7 - 245.0)^{3/2}$$
  
= 1800 cfs

NO OTHER INFLOW INTO REACH OTHER. THAN THAT FROM BREACH

FROM DIS HARARD REACH | RATING CURVE: N DIKE TO RTE ISG

STAGE @ 1800 cfs = 2,5 FEET

- 5	
5	
÷	
5	
ş	•
÷	•
3	1
- 6	-
	1
1	ž
;	-
1	
2	
•	
5	
1	
ż	
1	
ž	
	Ø
5	35
	1
~	1 -
1	51
7	2

			 	 			<u>ب</u>	• 				
							NO-	156				
						KE K	2115	Erte	ð		0	
					24 1-4-4 2-3-1-1-1 5 2-1-1-1 5 2-1-1-1 5 4-1-1-1	山 口	NSIT	- P 5 W	<b>(0</b> )		<b>Š</b>	
						70 17	Dou	た A A A	r- 1			
											8	
											<i>K</i>	
								╺┧╎┼┼╎				
		-+++++ +-+++++++++++++++++++++++++++++	- <b>4</b>								82	/
	$\begin{array}{c} + + + + + \\ + + + + \\ + + + + \\ + + + + \\ + + + + \\ + + + + \\ + + + + \\ + + + + \\ + + + + \\ + + + + \\ + + + + \\ + + + + \\ + + + + \\ + + + + \\ + + + + \\ + + + + \\ + + + + \\ + + + + \\ + + + + \\ + + + +$										ф 4 - Ц	- 1-
• • • •												
•					╺╴╸┥╺╴ ╺╴╸╸╸ ╲╴┥╺┥╺┥							
										╅┿╸	0	
· · · · ·	-									1-1 1-1	8	+
•												
						N						
							η <b>ν</b>					

-

LAAT NI ADAS

D-16

ã 2

NO 318

(0

í

2013

REACH | LENGTT = 2000 +

VOLUME WITHIN REACH = V,

 $V_{i} = 2000 \times 590 = 27 \text{AF}$ STORAGE @ MAX. POOL = 11700 AF = S  $V_{i} < \frac{1}{2} S \qquad \therefore \text{ REACH ok}$   $\varphi_{z} = \varphi_{B} (1 - \frac{V_{i}}{S}) = 1800 (1 - \frac{27}{11700})$   $= 1800 \text{ cfs} \qquad (\text{ voc negligible})$ 

@ Q = 1800 cfs STAGE = 2,5 FEET STORAGE WITHIN REACH = 27AF

REACHZ

INFLOW INTO REACH = 1800 cfs FROM DIS HARARD REACH 2 RATING CURVE CFOR BOTH DOLLOFF & GOVE DIKE): STAGE @ 1800 cfs = 6.6 FEET REACH 2 LENGTH = 14000' VOLUME WITHIN REACH =  $V_2$   $V_2 = 14000 \times 750 = 240 \text{ AF}$ SINCE  $V_2 < \frac{1}{2} \le D^{-17}$  REACH OK V

 $\varphi_2 = \varphi_1 \left( 1 - \frac{V_2}{s} \right) = 1800 \left( 1 - \frac{240}{11700} \right)$ 

3.13

= 1765 cfs

•

Ď

 $\mathbf{D}$ 

@ 1765 cfs; STAGE = 6.6 FEET

SINCE THIS WOULD RESULT IN THE SAME VOLUME WITHIN REACH

 $\varphi_{\text{FINAL}} = (1800 + 1765)/2 = 1780 \text{ cfs}$ 

@ Q = 1780 cfs STAGE = 6,6 FEET WAVE ENTO EPPING



Coder ....

ģ

EPP/NG3 PRUTUCEAULAY POND DOUNSTREAM POND REALH Z ļ 1 ł 8 t · 0 20 S ++++ 11 RTE 156 0 ## 11 • • • 1 Dut E 11 · - + - + -1+11 TTT111 i itti HH 11 . † 1 † t; ┥╌┟╌┾ Ħ t a irgid A land ₩. Hit нH IH1 FFFF┝┿┝┿╅ ..... ţ. م. ف. د ++++; in the second ----- $\lambda +$ +++ 日日 ┞╄┥╇ 1+++ ┿╃╊┩ +++++ + + + - + • - • • • • • 1111 ┫┽╀╄┦ +++FFF DISCHARGE Ŧ ++++ ++++ iiit ------111 ÷ ----1.1.1 +++++ 11 711 ┈┠╌┠╌┡╼┝ 111 i dati i data i data i data i data i <u></u> <u>VI</u> 1 11  $\mathbb{N}$ NI 1.11 <u>+</u>+-}-1 XIII +FFI  $\pm \pm$ 1 -----Ť 井井 111 1\_ ┥ ┥ ┥ ┥ ----- $\mathbf{H}$ tr ++++ +--++ ++++ ++++ **\$** 1-1-4-4 ł <u>11</u>, ¢. Ħ ļ 1 h D d H Ш H 11 1 111 i  $\overline{\mathbf{1}}$ TTT +++ TAGE IN FRET

L

υ

Ĩ

D-19

APPENDIX E

INFORMATION AS CONTAINED IN THE NATIONAL INVENTORY OF DAMS

## END

## FILMED

8-85

DTIC

.