

AD-A156 259


NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS  
LAKE SADAWGA (VT 0001) (U) CORPS OF ENGINEERS WALTHAM  
MA NEW ENGLAND DIV AUG 78


1/2

UNCLASSIFIED

F/G 13/13

NL





MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A

AD-A156 259

DTIC ACCESSION NUMBER

LEVEL

PHOTOGRAPH THIS SHEET

INVENTORY

LAKE SADAWGA VT00012

DOCUMENT IDENTIFICATION  
AUG 1978

This document has been approved  
for public release and sale; its  
distribution is unlimited.

DISTRIBUTION STATEMENT

ACCESSION FOR

NTIS GRA&I ☒

DTIC TAB ☐

UNANNOUNCED ☐

JUSTIFICATION

BY

DISTRIBUTION /

AVAILABILITY CODES

DIST

AVAIL AND/OR SPECIAL

A-1

DISTRIBUTION STAMP



DTIC  
RELCTE  
JUL 06 1985  
S E D

DATE ACCESSIONED

DATE RETURNED

DATE RECEIVED IN DTIC

REGISTERED OR CERTIFIED NO.

85 7 03 083

PHOTOGRAPH THIS SHEET AND RETURN TO DTIC-DDAC

AD-A156 259

CONNECTICUT RIVER BASIN  
WHITINGHAM

LAKE SADAWGA  
VT00012

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM



DEPARTMENT OF THE ARMY  
NEW ENGLAND DIVISION, CORPS OF ENGINEERS  
WALTHAM, MASS. 02154

AUGUST 1978

## **DISCLAIMER NOTICE**

**THIS DOCUMENT IS BEST QUALITY  
PRACTICABLE. THE COPY FURNISHED  
TO DTIC CONTAINED A SIGNIFICANT  
NUMBER OF PAGES WHICH DO NOT  
REPRODUCE LEGIBLY.**

**UNCLASSIFIED**

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER  VT 00012	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle)  Lake Sadawga NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS		5. TYPE OF REPORT & PERIOD COVERED  INSPECTION REPORT
7. AUTHOR(s)  U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS		8. CONTRACT OR GRANT NUMBER(s)
11. CONTROLLING OFFICE NAME AND ADDRESS DEPT. OF THE ARMY, CORPS OF ENGINEERS NEW ENGLAND DIVISION, NEDED 424 TRAPELO ROAD, WALTHAM, MA. 02254		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		12. REPORT DATE August 1978
		13. NUMBER OF PAGES 45
		15. SECURITY CLASS. (of this report)  UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report)  APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Cover program reads: Phase I Inspection Report, National Dam Inspection Program; however, the official title of the program is: National Program for Inspection of Non-Federal Dams; use cover date for date of report.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) DAMS, INSPECTION, DAM SAFETY, Connecticut River Basin Whitingham, VT. Tributary to Lake Whitingham		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number)  The dam is an earthfill dam about 10 ft. high, 400 ft. long. It is intermediate in size with a significant hazard potential. The main embankment is in good condition. Regular maintenance is required in the form of control of vegetation, repair of rip rap, and root removal. Annual maintenance inspections and bi-annual technical inspections should be instituted.		

LAKE SADAWGA

VT00012

WHITINGHAM, VERMONT

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

NATIONAL DAM INSPECTION PROGRAM  
PHASE I INSPECTION REPORT

Identification No.: VT00012  
Name of Dam: Lake Sadawga Dam  
Town: Whitingham  
County and State: Windham, Vermont  
Stream: Tributary to Lake Whitingham  
Date of Inspection: June 16, 1978

BRIEF ASSESSMENT

GENERAL

Lake Sadawga Dam is an earthfill dam about 10 feet high, 400 feet long, a crest width of about 10 feet, and side slopes of 2 to 2.5H:1V. It contains a 60-foot-long masonry, control section with a height of 13.5 feet. There is one earthfill saddle dike, referred to as the West Dike, which is about 10 feet high, 265 feet long, has a crest width of 4 feet, and side slopes of about 1.5H:1V. The impounded water is used for recreation and to feed a sprinkler system in a factory downstream.

The dam is classed as "intermediate" in size, based on storage, and its hazard classification is "significant".

The drainage area is about 2800 acres and the reservoir surface area is 202 acres. The length of the reservoir is about 5700 feet and it contains 808 acre feet of water in the normal recreation pool. The water may be drained from the reservoir through a 24 foot diameter pipe by removing stoplogs. The upstream invert of the stoplog structure is about 16.2 feet below the top of the dam.

A flood equal to 50% of the PMF will overtop the main embankment by about 1.5 feet and the West Dike by about 0.5 feet.

The main embankment is in good condition. Regular maintenance is required in the form of control of vegetation, repair of riprap, and root removal.

The West Dike has steep side slopes and a narrow crest. If the water rises to within two feet from the top of this dike, which occurs in a flood about 15% of the PMF, it may become unstable. Hence its stability should be checked and the dike should be redesigned so that it will be equivalent to the main embankment.

A portion of the concrete cap on the spillway section is severely cracked and is in only fair condition. A monitoring system



should be established to determine whether this portion is settling and an engineer should be retained to make necessary recommendations for repair of this control section.

Annual maintenance inspections and bi-annual technical inspections should be instituted. In addition, a flood warning system for downstream residents should be developed and implemented.

#### STATEMENT OF SIGNIFICANT FINDINGS


The following significant conditions were observed:

1. A large section of the original spillway shows cracking which may indicate settlement of this section of spillway.
2. Large trees are growing on the right end of the embankment, and vegetation is growing profusely on the upstream slope, on the left embankment and on the West Dike.
3. The West Dike has a very narrow crest width together with steep side slopes.
4. The spillway capacity is inadequate to pass the design flood of 3800 cfs.
5. The embankment is wave cut at lake level due to erosion of fines from the embankment.

#### STATEMENT OF RECOMMENDED ACTION

An engineer qualified in dam design should be engaged to redesign the West Dike to be safe when the maximum flood occurs, and to analyze alternatives and recommend a method for increasing the spillway capacity. In addition the cracking on the old spillway should be monitored to see if an ongoing settlement condition exists.

The large trees and roots on the right embankment should be removed and the holes repaired properly. The riprap on the upstream face of the embankment should be repaired. A maintenance program should be developed to insure that brush is removed annually from all parts of the dam and dike. Refer to Section 7 for detailed findings and recommendations.




*John R. Lunn*

This Phase I Inspection Report on Lake Sadawga Dam has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the Recommended Guidelines for Safety Inspection of Dams, and with good engineering judgment and practice, and is hereby submitted for approval.



CHARLES G. TIERSCH, Chairman  
Chief, Foundation and Materials Branch  
Engineering Division




FRED J. RAVENS, Jr., Member  
Chief, Design Branch  
Engineering Division



SAUL COOPER, Member  
Chief, Water Control Branch  
Engineering Division

APPROVAL RECOMMENDED:



JOE B. FRYAR  
Chief, Engineering Division

## PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I Inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test Flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

## TABLE OF CONTENTS

	<u>Page</u>
REVIEW BOARD PAGE	iii
PREFACE	iv
TABLE OF CONTENTS	v
TABLE OF CONTENTS	vi
TABLE OF CONTENTS	vii
OVERVIEW PHOTO	viii
LOCATION MAP	ix
REPORT	
SECTION 1 - PROJECT INFORMATION	1
1.1 GENERAL	1
a. Authority	1
b. Purpose	1
1.2 DESCRIPTION OF PROJECT	1
a. Location	1
b. Description of Dam and Appurtenances	2
c. Size Classification	2
d. Hazard Classification	2
e. Ownership	2
f. Operator	3
g. Purpose	3
h. Design and Construction History	3
i. Normal Operation Procedure(s)	3
1.3 PERTINENT DATA	3
a. Drainage Area	3
b. Discharge at Dam Site	4

	<u>Page</u>
c. Elevation	4
d. Reservoir	4
e. Storage	4
f. Reservoir Surface	5
g. Dam	5
i. Spillway	6
j. Regulating Outlets	6
SECTION 2 - ENGINEERING DATA	7
2.1 DESIGN	7
2.2 CONSTRUCTION	7
2.3 OPERATION	7
2.4 EVALUATION	7
a. Availability	7
b. Adequacy	7
c. Validity	7
SECTION 3 - VISUAL INSPECTION	8
3.1 FINDINGS	8
a. General	8
b. Dam	8
c. Appurtenant Structures	9
d. Reservoir Area	11
e. Downstream Channel	11
3.2 EVALUATION	11
SECTION 4 - OPERATIONAL PROCEDURES	12
4.1 PROCEDURES	12
4.2 MAINTENANCE OF DAM	12
4.3 MAINTENANCE OF OPERATING FACILITIES	12
4.4 DESCRIPTION OF WARNING SYSTEM IN EFFECT	12
4.5 EVALUATION	12
SECTION 5 - HYDRAULIC AND HYDROLOGIC EVALUATION	13
5.1 EVALUATION OF FEATURES	13
a. Design Data	13
b. Experience Data	13
c. Visual Observation	13
d. Overtopping Potential	13
e. Results of Dam Failure	13

	<u>Page</u>
SECTION 6 - STRUCTURAL STABILITY	15
6.1 EVALUATION OF STRUCTURAL STABILITY	15
a. Visual Observations	15
b. Design and Construction Data	15
c. Operating Records for the Dam	15
d. Post-Construction Changes	15
e. Seismic Stability	15
SECTION 7 - ASSESSMENT, RECOMMENDATIONS/REMEDIAL MEASURES	16
7.1 DAM ASSESSMENT	16
a. Condition	16
b. Adequacy of Information	16
c. Urgency	16
d. Necessity for Additional Investigations	16
7.2 RECOMMENDATIONS	16
7.3 REMEDIAL MEASURES	17
a. Alternatives	17
b. O & M Maintenance & Procedures	17
APPENDIX A	
Visual Inspection Check List	
APPENDIX B	
Project Records and Plans	
APPENDIX C	
Photographs	
APPENDIX D	
Hydraulic Computations	
APPENDIX E	
Information As Contained In The National Inventory Of Dams	

## SECTION 4: OPERATIONAL PROCEDURES

### 4.1 Procedures

None

### 4.2 Maintenance of Dam

The Vermont Department of Fish and Game maintain the dam by cutting brush and mowing both the dam, and the West Dike.

### 4.3 Maintenance of Operating Facilities

There is no routine maintenance of the operating facilities.

### 4.4 Description of Warning System in Effect

None for this dam.

### 4.5 Evaluation

The mowing program is effective in keeping brush from growing on the dam. The section of the dam west of the spillway structure has not been mowed for several years, and should be included in order for the maintenance program to be complete.

d. Reservoir Area

Lake Sadawga has a large "floating island" which consists of bog vegetation that floats in the central part of the lake. The lake level on June 16, 1978 was at the crest of the service weir, elevation 96.2, as is required by the rules and regulations for the surface level of Sadawga Pond as amended 18 September 1964.

e. Downstream Channel

The channel rapidly falls away from the Route 100 bridge at a 3.6 per cent slope. The channel averages 20 feet in width and water, flowing out of bank, can rise to stages of about 10 feet without flooding homes. The channel is composed of ledge outcrops and has been riprapped on the downstream side of the bridge. Water will probably overtop the bridge for the Spillway Design Flood but not at elevations which will significantly impede the flow out of Lake Sadawga. The bridge has a hydraulic opening of about 180 square feet and the top of road is at about elevation 95.4.

3.2 Evaluation

Based on visual examination, the embankments of the main dam are in good condition. The riprap needs repair, trees and shrubs must be cut, and the roots must be eliminated as a possible path of seepage.

Due to its steep side slopes and narrow crest width the West Dike appears to be only marginally adequate if the lake rises to within two feet below the top, as has been anticipated in the records available.

A portion of the concrete cap is in fair condition, since it is severely cracked and shows signs of settlement. It should be monitored to determine whether settlement is occurring. It is also recommended that the condition of the penstock where it penetrates the wall be determined.



The concrete cap shows evidence of deterioration in the form of light scaling and medium surface cracks. A portion of the cap just to the right of the control section (see Photo 8 in Appendix C) approximately 4 feet x 8 feet in plan appears to have settled and cracked. This portion of the cap is located directly over the old 3.9-foot diameter penstock where it penetrates the masonry wall.

The control section in the spillway is approximately 9 feet long. It appears to be constructed in accordance with the plans entitled "Proposed Spillway, Sadawga Pond, Whitingham, Vermont" by Howard M. Turner, Consulting Engineer, 1957.

There is provision in the control section for stop planks, which if installed, would raise the lake level to the height of the original spillway.

The concrete in the control section, including the training walls appears relatively new and is in good condition.

The regulating outlet consists of a 6.3 feet by 8.4 feet drop inlet. The upstream face of the inlet is formed by two rows of stop planks which fit into steel channel sections imbedded in concrete. The drop inlet, flows into the remains of a 3.9 foot penstock which penetrates the masonry wall. This structure is in generally good condition. The condition of the old penstock, within the masonry wall is unknown.

On the left side of the control section is a control gate for an 8-inch penstock which is used by a small wood product factory. The gate is operated by a handwheel which is in a gate house on top of the spillway. The actual penetration of the masonry wall is accomplished by a 30-inch boiler section, which is filled with concrete on the downstream side of the wall in order to accomplish the transition to 8-inch cast-iron pipe.

Just to the right of the right spillway training wall a path has been formed by pedestrians who climb to the top of the spillway structure.

Left Embankment - The embankment to the left of the spillway section is entirely overgrown with low trees to 15 feet high and with wild roses, on both upstream and downstream sides and on the crest.

No erosion was noted, except that a wave cut zone exists at lake level. The riprap appears in good condition. No filter material was evident beneath the riprap.

There was no seepage observed downstream of this embankment, which is arched downstream, in plain view, as it turns to meet the left abutment.

Spillway Structure Foundation - The spillway structure is founded on bedrock which is relatively flat-lying. One measurement showed a strike of N75E with a dip of 14° N. It appears that bedrock is shallow in the vicinity and that the embankment may be founded thereon.

West Dike - The west dike has very steep slopes (about 1.4H:1V) and a 3 or 4-foot-wide crest. The lake level is about 3 feet higher than the downstream toe and the freeboard is about 7 feet, which means that the top of the dike is about one foot higher than the dam embankment.

This dike is overgrown with shrubs and small trees. The records indicate that about 20 years ago this growth had been cut back.

A swampy zone exists for a distance of at least 100 feet downstream in a rather flat saddle that is shown on the USGS topographic map. There was no seepage evident from the downstream toe of the dike.

c. Appurtenant Structures

The concrete and masonry spillway, with the drop inlet regulating outlet, and the gated 8-inch penstock constitute the appurtenant structures of this dam.

The original spillway section is approximately 46 feet long. This spillway section is capped with old concrete. There is steel bar and masonry block embedded in the concrete. The purpose of the steel and masonry is unknown.

## SECTION 3: VISUAL INSPECTION

### 3.1 Findings

#### a. General

The on-site inspection of Lake Sadawga Dam was performed on June 16, 1978. Weather conditions were ideal for the inspection; clear, temperatures in the 70s. Runoff in the streams was considered normal for that time of year. No emergency conditions were observed on the day of the inspection.

The condition of the embankment was found to be good, and the spillway concrete was found to be in fair condition. The West Dike has steep slopes.

#### b. Dam

Figure 1 shows an approximate cross section, which was taken at a location about 73 feet right of the right spillway training wall. The freeboard is nearly 6 feet and the lake is quite shallow at this location. There is a head of only 2.6 feet across the embankment. The head is several feet high growing from the riprap.

At the lake level this riprap is wave cut slightly. No filter material appears to be present under the riprap. At one location about 56 feet right of the right spillway training wall, a zone about 10 feet wide along the upstream lake shore is eroded partway up the slope. At this location the embankment is arched upstream. This zone of erosion is at the location of minimum radius of curvature in plan view of the embankment.

Seepage was observed emanating from the downstream toeline along nearly the entire 300 foot length. Specific seeps were not observed, but the entire zone was wet downstream and a small channel had been dug to carry the water to an outlet. The wet zone is shown in Photo No. 3 in Appendix C. The dark green grass grows in the wetter areas.

## SECTION 2: ENGINEERING DATA

### 2.1 Design

There is no design data available for this dam.

### 2.2 Construction

There is no construction data available for this dam.

### 2.3 Operation

There is no operation associated with this dam.

### 2.4 Evaluation

#### a. Availability

There are no data.

#### b. Adequacy

Not applicable.

#### c. Validity

Not applicable.

5. Side slopes: 1.5H:1V upstream  
2H:1V downstream
6. Zoning - none known
7. Impervious Core - none known
8. Cutoff - none known
9. Grout Curtain - none known
- i. Spillway
  1. Type: concrete and cut stone masonry
  2. Length of Weir: 45.5 feet main weir  
9 feet service weir
  3. Crest elevation: 98.9 main weir  
96.2 service weir
  4. Gates: none
  5. Upstream channel: pond
  6. Downstream channel: Bridge at Route 100 approximately  
10 feet downstream 19 x 9.5 foot  
opening above elevation 84.4
- j. Regulating Outlets
  1. Invert: 85.2
  2. Size: 4' diameter with 3.9' diameter outlet (see photo).
  3. Description: Boiler tube modified for outlet service
  4. Control Mechanism: Stop log structure 8.4 feet from  
dam x 6.3 feet wide - concrete 1.5  
feet thick.

f. Reservoir Surface (acres)

1. Top dam	202
2. Maximum pool <sup>2</sup>	202
3. Flood-Control pool <sup>2</sup>	202
4. Recreation Pool <sup>2</sup>	202
5. Spillway crest <sup>2</sup>	202

g. Main Dam

1. Type

Earth dam embankments with concrete and cut-stone masonry spillway section.

2. Length - 400 feet ± including spillway

3. Height - 9 feet

4. Top width - 10 feet

5. Side Slopes - 2H:1V upstream  
2.5H:1V downstream

6. Zoning - None known

7. Impervious Core - None known

8. Cutoff - None known

9. Grout Curtain - None known

West Dike

1. Type - Earth Embankment

2. Length - 265 feet (approx.)

3. Height - 10 feet

4. Top width - 4 feet

---

<sup>2</sup> Estimated due to lack of topographic data.

b. Discharge at Dam Site

1. The outlet works consist of a 3.9' diameter boiler tube which is regulated by a stop-log structure at its inlet and a 30-inch boiler tube which is gated and reduced down to make a transition to an 8-inch cast iron pipe.
2. There is no record of estimated or known maximum floods at the dam site.
3. The ungated spillway capacity at the full reservoir level is 1050 cfs.
4. There is no gated spillway.

c. Elevation (local datum)

1. Top dam	101.8
2. Maximum pool - design surcharge <sup>1</sup>	99.4
3. Full flood control pool	101.8
4. Recreation pool	96.2
5. Spillway crest	98.9
6. Upstream invert 4-foot diameter conduit	85.2
7. Streambed at centerline of dam	82.7
8. Maximum tailwater <sup>1</sup>	88.7

d. Reservoir

1. Length of maximum pool	5700 feet
---------------------------	-----------

e. Storage (acre-feet)

1. Recreation pool	808
2. Flood control pool	1939
3. Design surcharge <sup>1</sup>	1455
4. Top of dam	1939

---

<sup>1</sup>Results of Howard M. Turner Report dated June 20, 1957.

f. Operator

The dam is operated by the Vermont Department of Fish and Game, Contact:

Mr. Ray Harwood, Regional Supervisor  
Telephone: 802-773-2657

g. Purpose

Lake Sadawga Dam is presently maintained for recreational purposes. One 8-inch pipe feeds a sprinkler system for a building downstream.

The dam was originally constructed to impound and control water for hydropower purposes.

h. Design and Construction History

No information is available on the design or construction history of this dam.

i. Normal Operation Procedures

There are no normal operational procedures associated with this dam.

1.3 Pertinent Data

a. Drainage Area

The drainage area is 4.33 square miles of rolling hills surrounding Lake Sadawga, including the drainage area of Lake Clara. The drainage is from hills which rise 430 feet above normal pond level. They are predominantly covered with soils described as glacial till with a hard-pan or bed rock commonly within three feet of the surface.

The watercourses into the pond vary in characteristic from a well-defined 1.9 square mile basin formed north of Route 100 and the town highway just south of Route 100 to several smaller tributaries flowing from the hills immediately surrounding Lake Sadawga. The northern watercourse has an average slope of 130 feet per mile and is about 2.3 miles long while the smaller tributaries are about 0.8 mile long with slopes of roughly 440 feet per mile.



b. Description of Dam and Appurtenances

Lake Sadawga Dam is an earth dam with a concrete and masonry spillway section.

The level in the lake is maintained by a control section in the spillway. There is also a drop inlet, in which the invert elevation may be varied by use of stop planks. The drop inlet is connected to an abandoned 3.9' penstock which penetrates the masonry wall of the spillway on the east side. There is an 8-inch penstock on the west side which is still in service. Water in this penstock is maintained by a gate constructed in the concrete and masonry portion of the dam.

At the far west end of the lake is a dike, apparently constructed of earth and rock, which prevents water from out-letting at that spot.

c. Size Classification

Lake Sadawga is a 202-acre impoundment. The dam is between 9 and 17 feet in height. The maximum storage potential of the lake is estimated at 1939 acre-feet. The Corps of Engineers recommends that dams which have a height greater than 40 feet but less than 100 feet, or have a storage volume greater than 1000 acre-feet but less than 50,000 acre-feet be classified as intermediate in size. The storage volume therefore governs, and results in a size classification of intermediate for this dam.

d. Hazard Classification

A failure of Lake Sadawga Dam would route the resulting flood through Whitingham Village to Lake Whitingham, (see map in Appendix B). It is estimated that three or four lives might be endangered in the event of a dam failure, and that one building, State Route 100 and several town roads would suffer serious damage. The hazard category of Lake Sadawga Dam is therefore significant.

e. Ownership

The present owner of Lake Sadawga Dam is:

The Vermont Dept. of Fish and Game  
Montpelier, Vermont 05602  
Commissioner, Edward Kehoe

Reportedly the previous owner of the dam was Mr. Houghton Sawyer of Whitingham.

NATIONAL DAM INSPECTION PROGRAM  
PHASE I INSPECTION REPORT  
NAME OF DAM: LAKE SADAWGA

SECTION I: PROJECT INFORMATION

1.1 General

a. Authority

Public Law 92-367, August 8, 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a National Program of Dam Inspection throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region. Dufresne-Henry Engineering Corporation has been retained by the New England Division to inspect and report on selected dams in the State of Vermont. Authorization and notice to proceed were issued to Dufresne-Henry Engineering Corporation under a letter of May 26, 1978 from Ralph T. Garver, Colonel, Corps of Engineers. Contract No. DACW33-78-C-0341 has been assigned by the Corps of Engineers for this work.


b. Purpose

1. Perform technical inspection and evaluation of non-Federal dams to identify conditions which threaten the public safety and thus permit correction in a timely manner by non-Federal interests.
2. Encourage and prepare the states to initiate quickly effective dam safety programs for non-Federal dams.
3. To update, verify and complete the National Inventory of Dams.

1.2 Description of Project

a. Location

Lake Sadawga Dam is located in the Town of Whitingham, Windham County, Vermont. More specifically the dam is located approximately 0.25 miles southeast of Whitingham Village on Route 100.



SOURCE OF MAP:

U.S. GEOLOGICAL SURVEY  
WILMINGTON QUADRANGLE,  
VERMONT, 15 MIN. SERIES  
1"=62500', 1954

CLIENT NO. 22-0555

ENGINEER JRS

DRAWN BY LGF

DATE 7-11-78

DUFRESNE-HENRY ENGINEERING CORP.

LOCATION MAP  
LAKE SADAWGA DAM

WHITINGHAM

VERMONT

A



OVERVIEW OF LAKE SADAWGA DAM  
WHITTINGHAM, VERMONT

## SECTION 5: HYDRAULIC/HYDROLOGIC

### 5.1 Evaluation of Features

#### a. Design Data

The only data available is contained in the report by Howard M. Turner in 1957. In this report he was proposing modification to the spillway section to its present form. In his analysis he makes reference to a "rare flood" of 1680 cfs which is reduced by pond storage to an outflow of 540 cfs. This outflow would result in a stage of 99.4 in the pond based on his supporting computations.

One-half of the Probable Maximum Flood (1/2 PMF) has been selected as the Test Flood for this impoundment. This flood was computed using hydrograph methods via the Generalized Computer Program HEC-1. The results of the current hydrograph analysis show that the inflow would be on the order of 7500 cfs and the outflow would be about 3800 cfs. Consequently the previously existing data does not conform to the present design criteria.

#### b. Experience Data

There are no accounts of overtopping or significantly high water levels in Lake Sadawga.

#### c. Visual Observations

The impoundment is being operated in accordance with the rules and regulations for the surface level of Sadawga Pond as amended 18 September 1964. The stop log structure is in serviceable condition and could be used to draw the lake down in the event of an emergency.

#### d. Overtopping Potential

The Test Flood of 1/2 PMF will overtop the earth embankment near the spillway by about 1.5 feet and the West Dike by about 0.5 feet.

#### e. Results of Dam Failure

##### (1) Main Dam

A wave of water about 11 feet high would flow down the existing channel away from Lake Sadawga. This would not be high enough to cause serious damage as there is channel capacity to at least 10 feet above the stream bed.

(2) West Dike

A wave of water about 7 feet high would flow through the woods and swamp area to the west of Lake Sadawga. Its height would be somewhat diminished when it reached the Village area but still could sustain considerable damage to a church and possibly Route 100.

## SECTION 6: STRUCTURAL STABILITY

### 6.1 Evaluation of Structural Stability

#### a. Visual Observations

Based on visual observations there appears to be little cause for concern currently about the stability of this dam. However, large trees are growing near the right abutment, which will lead eventually to rotting roots and possible paths for internal erosion. Similarly shrubs and low trees are being allowed to grow on the upstream side of the right embankment and over the entire left embankment and West Dike.

The riprap is wave cut, probably due to continual plucking of fines from the embankment through the voids between stones.

The West Dike has a crest width of only a few feet. In the records it appears that for a "rare storm" (1640 cfs inflow, 11% of PMF) the freeboard will drop to only 2 feet. Under these conditions the West Dike will be in substantial danger of eroding through due to only minor wave action, because the crest is narrow and the slopes are steep.

See Section 3.1.c. for comments on the cracking of the concrete cap of the spillway.

#### b. Design and Construction Data

There are no design or construction data available on which to base an analysis of the stability of this dam.

#### c. Operating Records

There are no operating records available that relate to the structural stability of this dam.

#### d. Post-Construction Changes

There are no data available concerning post-construction changes. From the appearance of the concrete, and the June 20, 1957 letter from Mr. Turner to Mr. Thieme, it would seem that changes have been made at the control section. In particular, a 9 foot section of the spillway was lowered 2.7 feet to prevent overtopping during a "rare" storm.

#### e. Seismic Stability

This dam is in Seismic Zone 2 and therefore need not be analyzed for seismic forces, according to the guidelines for Phase I inspection.

## SECTION 7: ASSESSMENT, RECOMMENDATIONS/ REMEDIAL MEASURES

### 7.1 Dam Assessment

#### a. Condition

Based on the records and visual observations, there are no significant concerns about the structural stability of this dam. The wave cut riprap and the large trees on the embankment could ultimately lead to difficulties if not repaired.

The West Dike has such a narrow crest and steep slopes that it would be subject to washout if the freeboard were ever reduced from its present value of 6 feet to only 2 feet, which would occur during a "rare" flood (equivalent to 11% of the PMF).

The concrete cap on a portion of the control section is in fair condition. It contains large cracks and may be settling.

#### b. Adequacy of Information

The assessment of the condition of the dam was based primarily on the visual inspection.

#### c. Urgency

The recommendations given in Sections 7.2 and 7.3 should be carried out within 12 months in the control section and within two to four years for the balance of the work.

#### d. Necessity for Additional Information

Additional information needed to carry out the recommendations in Sections 7.2 and 7.3 should be obtained.

### 7.2 Recommendations

An engineer qualified in the design of earth dams should be engaged to:

1. Redesign and rebuild the West Dike to make it equivalent to the dam.
2. Monitor settlement of the cracked portion of the control section and redesign this structure as necessary.



3. Investigate the condition of the penstock that penetrates the control section and make any necessary recommendations.
4. Develop a procedure for removing roots of large deciduous trees in the dam without endangering the dam.

### 7.3 Remedial Measures

#### a. Alternatives

Not applicable.

#### b. Operating and Maintenance Procedures

1. Make an annual maintenance inspection of the dam.
2. Make a bi-annual technical inspection of the dam.
3. Repair the riprap that has been wave cut.
4. Repair eroded spots in embankment.
5. Cut all vegetation and maintain it cut, for both the main dam and the West Dike.
6. Repair spalled and cracked concrete.
7. Develop and test regularly a flood warning system for the downstream residents.

APPENDIX A  
VISUAL INSPECTION CHECKLIST

VISUAL INSPECTION CHECK LIST  
PARTY ORGANIZATIONPROJECT SADAWGA DAMDATE June 16, 1978TIME 1410WEATHER Clear, sunnyW.S. ELEV.          U.S.          DN.S.

## PARTY:

1. <u>Walter A. Henry</u>	<u>D-H</u>	6. <u>                                </u>
2. <u>John R. Spencer</u>	<u>D-H</u>	7. <u>                                </u>
3. <u>Morris J. Root</u>	<u>D-H</u>	8. <u>                                </u>
4. <u>Steve Poulos</u>	<u>GEI</u>	9. <u>                                </u>
5. <u>                                </u>		10. <u>                                </u>

PROJECT FEATURE	INSPECTED BY	REMARKS
1. <u>                                </u>		
2. <u>                                </u>		
3. <u>                                </u>		
4. <u>                                </u>		
5. <u>                                </u>		
6. <u>                                </u>		
7. <u>                                </u>		
8. <u>                                </u>		
9. <u>                                </u>		
10. <u>                                </u>		

# PERIODIC INSPECTION CHECK LIST

2 of 9

PROJECT SADAWGA DAM

DATE June 16, 1978

PROJECT FEATURE \_\_\_\_\_

NAME \_\_\_\_\_

DISCIPLINE Geotechnical

NAME S. J. Poulos

AREA EVALUATED	CONDITION
<u>DAM EMBANKMENT</u>	
Crest Elevation	
Current Pool Elevation	
Maximum Impoundment to Date	
Surface Cracks	None observed.
Pavement Condition	Grassed to right of spillway, choke-cherries and rose shrubs to 15 feet and grass to left of spillway.
Movement or Settlement of Crest	None observed.
Lateral Movement	None observed.
Vertical Alignment	No misalignment observed.
Horizontal Alignment	No misalignment observed.
Condition at Abutment and at Concrete Structures	Condition of abutments is good. Seepage exits from spillway structure along entire downstream face from about 3 feet above invert of outlet conduit. One seep 2 feet below spillway.
Indications of Movement of Structural Items on Slopes	None observed.
Trespassing on Slopes	Free access. Only one path exists at right of spillway structure.
Sloughing or Erosion of Slopes or Abutments	One slough or erosion patch 56 feet to right of structure.
Rock Slope Protection - Riprap Failures	Wave cut at water level. No filter observed. 100-300 lb. stone.
Unusual Movement or Cracking at or near Toes	None observed.
Unusual Embankment or Downstream Seepage	Seepage at toeline of entire embankment to right of spillway. Not unusual.
Piping or Boils	None observed.
Foundation Drainage Features	None apparent.
Toe Drains	None apparent.
Instrumentation System	None apparent
Vegetation	Right abutment: Trees to 10 in. Shrubs to 5 ft. on remainder of embankment upstream only. Downstream grass. Left abutment overgrown. Not mowed.

## PERIODIC INSPECTION CHECK LIST

3 of 9

PROJECT SADAWGA DAMDATE June 16, 1978

PROJECT FEATURE \_\_\_\_\_

NAME \_\_\_\_\_

DISCIPLINE GeotechnicalNAME S. J. Poulos

AREA EVALUATED	CONDITION
<u>DIKE EMBANKMENT</u>	
Crest Elevation	
Current Pool Elevation	
Maximum Impoundment to Date	
Surface Cracks	None observed.
Pavement Condition	None. Grass.
Movement or Settlement of Crest	Half-foot deep dip in middle 50 ft. of dike.
Lateral Movement	None observed.
Vertical Alignment	Fairly straight or curved very slightly upstream.
Horizontal Alignment	
Condition at Abutment and at Concrete Structures	No structures. No seepage or other deleterious features observed at abutments.
Indications of Movement of Structural Items on Slopes	No structures.
Trespassing on Slopes	Free access. No paths eroded.
Sloughing or Erosion of Slopes or Abutments	None observed.
Rock Slope Protection - Riprap Failures	None present.
Unusual Movement or Cracking at or near Toes	None observed.
Unusual Embankment or Downstream Seepage	Swampy downstream in saddle area to at least 100 feet downstream.
Piping or Boils	None observed.
Foundation Drainage Features	None.
Toe Drains	None.
Instrumentation System	None.
Vegetation	Trees and shrubs on downstream; shrubs on upstream side.

## PERIODIC INSPECTION CHECK LIST

4 of 9

PROJECT SADAWGA DAMDATE June 16, 1978

PROJECT FEATURE \_\_\_\_\_

NAME \_\_\_\_\_

DISCIPLINE GeotechnicalNAME S. J. Poulos.

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - INTAKE CHANNEL AND INTAKE STRUCTURE</u>	
a. Approach Channel	
Slope Conditions )	Can see 3-4 feet deep. Sandy, gravelly
Bottom Conditions )	silt on bottom.
Rock Slides or Falls	None.
Log Boom	None.
Debris	Not observable.
Condition of Concrete Lining	
Drains or Weep Holes	None.
b. Intake Structure	
Condition of Concrete	Good
Stop Logs and Slots	At least 4 stop planks, 8" x 4", 2-slot guides; no planks in second slot.

## PERIODIC INSPECTION CHECK LIST

5 of 9

PROJECT SADAWGA DAMDATE June 16, 1978PROJECT FEATURE Outlet StructuresNAME Steve Poulos

DISCIPLINE \_\_\_\_\_

NAME John Spencer

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - CONTROL TOWER</u>	Mill Outlet
a. Concrete and Structural	N/A
General Condition	Good (see notes).
Condition of Joints	None.
Spalling	No significant.
Visible Reinforcing	None (bent anchor bars).
Rusting or Staining of Concrete	None.
Any Seepage or Efflorescence	None.
Joint Alignment	N/A
Unusual Seepage or Leaks in Gate Chamber	No gate. None
Cracks	See notes.
Rusting or Corrosion of Steel	None.
b. Mechanical and Electrical	
Air Vents	
Float Wells	
Crane Hoist	
Elevator	
Hydraulic System	
Service Gates (Stop planks maybe)	Hand wheel
Emergency Gates	operated 28"
Lightning Protection System	diameter sluice
Emergency Power System	gate
Wiring and Lighting System	

# PERIODIC INSPECTION CHECK LIST

6 of 9

PROJECT SADAWGA DAM

DATE June 16, 1978

PROJECT FEATURE \_\_\_\_\_

NAME J. R. Spencer

DISCIPLINE \_\_\_\_\_

NAME \_\_\_\_\_

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - TRANSITION AND CONDUIT</u>	
General Condition of Concrete	Conduit 4' pipe with 3' diameter opening. Other 10" pipe, grouted in 2'-6" opening (concrete)
Rust or Staining on Concrete	
Spalling	N/A
Erosion or Cavitation	N/A
Cracking	N/A
Alignment of Monoliths	N/A
Alignment of Joints	N/A
Numbering of Monoliths	N/A



## PERIODIC INSPECTION CHECK LIST

7 of 9

PROJECT SADAWGA DAMDATE June 16, 1978

PROJECT FEATURE \_\_\_\_\_

NAME J. R. Spencer

DISCIPLINE \_\_\_\_\_

NAME \_\_\_\_\_

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - OUTLET STRUCTURE AND OUTLET CHANNEL</u>	
General Condition of Concrete	(See notes) OK.
Rust or Staining	None.
Spalling	Minor surface spalling on west spillway section.
Erosion or Cavitation	No.
Visible Reinforcing	No. Some exposed bars.
Any Seepage or Efflorescence	No.
Condition at Joints	No joints.
Drain Holes	No.
Channel	See weir discharge channel.
Loose Rock or Trees Overhanging Channel	See weir discharge channel.
Condition of Discharge Channel	See weir discharge channel.

## PERIODIC INSPECTION CHECK LIST

8 of 9

PROJECT SADAWGA DAMDATE June 16, 1978


PROJECT FEATURE \_\_\_\_\_

NAME J. R. Spencer

DISCIPLINE \_\_\_\_\_

NAME \_\_\_\_\_

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS</u>	
a. Approach Channel	
General Condition	Good.
Loose Rock Overhanging Channel	No.
Trees Overhanging Channel	No.
Floor of Approach Channel	Concrete.
b. Weir and Training Walls	
General Condition of Concrete	Good.
Rust or Staining	No.
Spalling	No.
Any Visible Reinforcing	No. (4" x 6" channels for stop planks)
Any Seepage or Efflorescence	No.
Drain Holes	No.
c. Discharge Channel	
General Condition	Good.
Loose Rock Overhanging Channel	No.
Trees Overhanging Channel	No.
Floor of Channel	Concrete.
Other Obstructions	None.



NOT TO SCALE

PHOTOGRAPHS TAKEN

NOTE: PHOTOGRAPHS WERE TAKEN LOOKING WESTERLY ACROSS THE SO-CALLED WEST DIRT. THE WEST DIRT IS A DAM LOCATED AT THE END OF A DIRT ON THE WEST SIDE OF THE LAKE. APPROXIMATELY 100 YARDS AWAY FROM THE MAIN DAM.


DEFRESNE-HENRY ENGINEERING CORP. U.S. ARMY ENGINEER DIV. NEW ENGLAND DISTRICT OFFICE BOSTON, MASS.

NATIONAL PROGRAM OF INSPECTION OF NON-FED DAMS  
LAKE SADANGA DAM  
LOCATIONS OF PHOTOGRAPHS  
TAKEN 6 16 1978  
WILLINGHAM VT PROJECT

## APPENDIX C

### PHOTOGRAPHS

1. Upstream of Lake Sadawga Dam, Looking at Spillway Section.
2. Right Embankment, From Spillway Looking East.
3. Toe of Right Embankment.
4. West Dike.
5. Spillway, Drop-Inlet and Gatehouse.
6. Spillway, Gatehouse from Downstream.
7. Drop Inlet, Also Note Cracked Concrete.
8. View of Cracked Concrete on Spillway.
9. Outlet From Drop-Inlet, and View of Masonry Wall.



NOTE: THIS SECTION TRACED FROM DRAWING BY HOWARD W. TURNER, CONSULTING ENGINEER, ENTITLED, PROPOSED SPILLWAY SADAWAGA POND, DATED JUNE 1967.

FIGURE 2


DUPRESE-HENRY ENGINEERING CORP. U.S. ARMY ENGINEER DIV. NEW ENGLAND DISTRICT  
 100 WILLOW STREET  
 CHICAGO, ILL. 60604

NATIONAL PROGRAM OF INSPECTION OF NON-FED DAMS

LAKE SADAWAGA DAM

WHITINGHAM

LEMON



PLAN VIEW  
SCALE: 1" = 10'




FIGURE 1

DUPRESNE-HEWY ENGINEERING CORP. ARCHITECT-ENGINEERS	U.S. ARMY ENGINEER DIV., NEW ENGLAND CORPS OF ENGINEERS BOSTON, MASS.
NATIONAL PROGRAM OF INSPECTION OF NON-FED DAMS	
LAKE SADAWGA DAM	
WILLIAMSBURG	VERMONT

# FILE COPY

## State of Vermont

ROUTING		
GENERAL		
TO	NOTED	DATE
DHS	DHS	9-30-75
DIN	Jm	9/30/75
AKR	AKR	9/30
GTD		
SUBMITTED TO		
FILE		

### AGENCY OF ENVIRONMENTAL CONSERVATION

MARTIN L. JOHNSON, Secretary

Montpelier, Vermont 05602

### DEPARTMENT OF WATER RESOURCES

### MANAGEMENT & ENGINEERING DIVISION

September 30, 1975

t of Fish and Game  
t of Forests and Parks  
t of Water Resources  
ntal Board  
Environmental Protection  
Recreation  
Planning  
sources Conservation Council

## MEMORANDUM

To: File

From: Donald H. Spies

Subject: Lake Sadawga Dam - Whitingham

On August 25, 1975, the writer made an inspection of the subject structure. The right embankment appears to be in good condition. Some water was noted along the toe, but it was not determined whether the water was from seepage or local drainage. It was also noted the upstream face is heavily overgrown with brush which should be brought under control.

The spillway section also seemed to be in good condition. Some small trees are growing on the downstream face and should be removed before the root systems damage the stone work. There is some leakage through the stones, but doesn't appear to be a problem at the present. This condition should be observed periodically to detect changes.

The left embankment is quite overgrown with brush which should be cut and removed.

The dike on the northwest bay seems to be stable. Some of the brush and trees are starting to grow and should be cut back. Water was noted at the toe but appears to be an accumulation from local drainage and not seepage.

DHS/vd1

Edward F. Kehoe, Commissioner, Fish & Game

Lake Sadawga Dams -  
Whitingham

Donald H. Spies

October 28, 1971

#### Main Dam

On October 4, 1971, the writer inspected the subject structure. The dam is essentially a concrete and masonry structure with an earth fill wing wall on each end. Overall, the dam was in fairly good shape. However, the masonry is leaking in quite a few places. The west wing wall is heavily overgrown with brush and small trees. There is some growth on the east embankment and a little in the masonry portion.

The door to the gatehouse has been removed and it was noted that there was no lock on the gate wheel. Also, the penstock leaks quite badly.

#### West Dam


The subject dam was inspected by the writer on October 4, 1971. It is an earth fill dam with no spillway. The purpose of this structure apparently is to prevent the lake waters from flowing out a low area. The width of the dam is quite narrow (about 3' at the top) and the slopes are quite steep (almost 1 on 1). However, the dam appears to be holding up quite well and there was no noticeable leakage. It was noted that the brush had been cut down some time ago, but it is starting to come back. Possibly, something could be sprayed on the brush to retard its growth.


cc: Robert Collins, Maintenance Supervisor  
Richard Sears, Land Negotiator

ROUTING		
GENERAL		
TO	NOTED	DATE
JEC		
DHS	EHS	10-28-71
SUBMIT TO		
FILE		

Dam







Mr. Reinhold W. Thieme --2

June 20, 1957

with the level 1.2 ft. below the top of the abutments. This is too low for safety when wave action is considered, but the fact may be of interest.

I recommend the following:

(1) That the present 4 ft. penstock opening below the dam be put in shape with an adequate flood gate at its entrance so that this can be used during times of high flood to reduce the height of the water over the dam, and that the gate to the small pipe be put in suitable operating condition.

(2) That the low spillway be reduced 2.3' in height with the remaining 1' of this wall shaped as shown.

Yours very truly,

Howard M. Turner

HMT/eb

HOWARD M. TURNER  
CONSULTING ENGINEER  
6 BEACON STREET  
BOSTON 8, MASS.

June 20, 1957

Mr. Reinhold W. Thieme, Commissioner  
Water Conservation Board  
Montpelier, Vermont

Dear Sir:

Last December, I made a study of the flood conditions of Sadawga Pond. This was figured on a drainage area, taken from the maps then existing, of 5.2 sq. miles and a pond area of 179 acres. You have given me new figures on these, from maps as yet unpublished from the United States Geological Survey which show that the drainage area of Sadawga Pond including Lake Clara is 4.33 sq. miles and the area of the pond is 202 acres. This, of course, materially changes the basis of flood discharge. This report is written using these revised figures.

At the recent hearing, it was suggested that if the old spillway area 9' wide by 3.3' high be opened again, it would be safe for flood purposes. I have been through this and have estimated the "rare" flood with the revised drainage areas, to be 1680 c.f.s. (cubic feet per second).

I have found that sufficient flood capacity can be obtained with the gates and the spillway lowered 2.3 ft. The low wall 1' high across this 9' spillway should be shaped as shown to give a good discharge coefficient.

With this spillway, assuming that the pond is full to the new crest of the spillway when the flood starts and that the gates are opened when the water is about two feet over the spillway, the storage of the pond above the dam, 23,200,000 cu. ft., will reduce the flood to an outflow of 540 c.f.s. with the water level 2.2' over the new low crest of the spillway and 0.5' over the long, main crest. This maximum water level will be two feet from the top of the abutment and embankment on both sides of the dam which is a satisfactory margin. I enclose a hydrograph of this flood showing the outflow over the spillway.

It may be of interest to know that if for any reason, the gates fail to be opened, the spillway proposed will handle the flow of a rare flood

## APPENDIX B

### A. Listing of Design and Construction Records

None

### B. Copies of Past Inspection Reports

1. "Sadawga Dam, Whitingham, Vt.," Howard M. Turner, Consulting Engineer. Boston, Mass. June 20, 1957.
2. Inspection Memorandum, Donald H. Spies, Oct. 28, 1971.
3. Inspection Memorandum, Donald H. Spies, September 30, 1975.

### C. Listing of Plans



Fig. 1 - Plan and Section Views of Dam

Fig. 2 - Sections of Spillway

Client Dufroigne - Henry  
 Subject Satunga Dam

Project \_\_\_\_\_ Page 2  
 Date June 12, 78 By SL  
 Checked \_\_\_\_\_ By \_\_\_\_\_  
 Approved \_\_\_\_\_ By \_\_\_\_\_


Erosion upstream to right of structure as shown.



Client	Dufresne & Henry	Project	Page 1
Subject	Sadawaga Dam	Date	June 11, 73
		By	1 St
		Checked	By
		Approved	By

Hole in rt. abutment.

North



Bedrock.

Structure is founded on quartzite or schist bedrock dipping 14° N striking N75E

→ To left abut of structure

## PERIODIC INSPECTION CHECK LIST

9 of 9

PROJECT SADAWGA DAMDATE June 16, 1978

PROJECT FEATURE \_\_\_\_\_

NAME J. R. Spencer

DISCIPLINE \_\_\_\_\_

NAME \_\_\_\_\_

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - SERVICE BRIDGE</u>	
a. Super Structure	Not applicable.
Bearings	
Anchor Bolts	
Bridge Seat	
Longitudinal Members	
Under Side of Deck	
Secondary Bracing	
Deck	
Drainage System	
Railings	
Expansion Joints	
Paint	
b. Abutment & Piers	
General Condition of Concrete	
Alignment of Abutment	
Approach to Bridge	
Condition of Seat & Backwall	





#1 UPSTREAM OF LAKE SADAWGA DAM, LOOKING AT SPILLWAY SECTION



#2 RIGHT EMBANKMENT, FROM SPILLWAY LOOKING EAST



#3 TOE OF RIGHT EMBANKMENT




#4 WEST DIKE




#5 SPILLWAY, DROP-INLET AND GATEHOUSE



#6 SPILLWAY, GATEHOUSE FROM DOWNSTREAM



#7 DROP INLET, ALSO NOTE CRACKED CONCRETE



#8 VIEW OF CRACKED CONCRETE ON SPILLWAY



#9 OUTLET FROM DROP-INLET, AND VIEW OF MASONRY WALL

APPENDIX D  
HYDRAULIC COMPUTATIONS

# DUFRESNE-HENRY ENGINEERING CORPORATION

SUBJECT Lake Sadawga  
Hydrology and Hydraulics

SHEET NO. \_\_\_\_\_ OF \_\_\_\_\_  
 JOB NO. \_\_\_\_\_

DATE \_\_\_\_\_

Index to computations

Page

Selection of SDF

1

Dam Break

1

Watershed, Snyder Coefficients

2

Routing Diagram

2

HEC-1 output

3 - 31

Output summary

31

Rating Curves

32

Spillway Rating Computations

33

Conduit Rating Computations

34

Outflow and Flood Storage - stage summary

35

Route 100 Hydraulic Control

36

Watershed Characteristics

36

HYDROLOGIC CHARACTERISTICS

37

DUFRESNE-HENRY ENGINEERING CORPORATION

MTS Root  
DATE 7-26-78

SUBJECT Lake Sadawga  
Miss. Hydraulic Data

SHEET NO. 1 OF 36  
JOB NO. 22-0555

ke Sadawga Dam

Drainage Area

4.31 square miles  $\rightarrow$  9.33 sq. mi. = state of Vt.

8.81  
13.24 4.43  
17.67 4.13

Break

$$Y_w = \frac{2}{3} Y_o = \frac{2}{3} (17 \pm) = 11' \pm \quad \text{channel is } 10' \pm \text{ deep!}$$

Channel Capacity Route 100 Bridge - 19' wide x 9.5' deep + 1.5' top of road  
 $S = (484.6 - 481)/100 \approx 3.6\%$   $\therefore$  Use inlet control as first approximation  
 $\therefore$  VHD Assumed datum 500 = 98.9 H. M. Turner Report (-401.1)

Size Classification:

By Storage (gives larger size category)

Max. Ac-ft by Vt. DWR 1820 Ac-ft.  $>$  1000 Ac-ft  
Normal Ac-ft 808 Ac-ft

$\therefore$  SIZE  $\equiv$  Intermediate

Hazard Classification:

Few, if any homes  
Possible, but not likely, road damage

$\therefore$  HAZARD  $\equiv$  Significant

Significant Intermediate Dam - use  $\frac{1}{2}$  PMF as SDF



# DUFRESNE-HENRY ENGINEERING CORPORATION

Y MJR  
ATE 7-26-78

SUBJECT Lake Sadawga  
Watershed

SHEET NO. 2 OF 36  
JOB NO. 22-6555

at watershed:

Tribs from Lake Clara 0.7<sup>+</sup> sq. mi.  
complete w.s. N. of Route 100 ~ 2.6 sq. mi.  
E, TH S of Route 100

1.7 sq. mi hillsides around  
pond to South

$$(2150 - 1670^{\pm}) = 430' \text{ rise}$$

$$L = 2.3 \text{ miles} - N \quad \hat{L}_c = .6L = 1.38$$

$$S = \frac{(915 - 1690)}{1.73} = 127' / \text{mile}$$

$$T_p = 2.2 \left( \frac{L L_c}{S} \right)^{.37} = 1.4 \text{ hr}$$

$$C_p = .75 \quad ; \text{ i.e. } 640 C_p = 480$$


side  
real

$$L = .8 \text{ mile} \quad \hat{L}_c = .6L = .48 \text{ mile} \quad T_p = .5 \text{ hr}$$

$$\frac{(1940 - 1675)}{.6} = 441' / \text{mile} \quad C_p = .75$$

d area = 202 Acres normal water level - DWR/NERBC

ing Diagram for HEC-1



FLOOD ROUTING THROUGH LAKE SADAMCA • WHITINGHAM • VERMONT

PREPARED FOR USE IN DAM SAFETY EVALUATION PHASE I

JOB SPECIFICATION

NO NHR NMIN IDAY IHR IMIN METPC IPLT IPRT NSTAN  
144 0 10 1 0 0 0 2 0 0  
JOPER NWT  
3 0

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

SUB-AREA RUNOFF COMPUTATION

HYDROGRAPH FOR TRIBUTARY NUMBER 2

ISTAQ ICOMP IECON ITAPE JPLT JPRT INAME  
2 0 0 0 0 0 1

HYDROGRAPH DATA  
IHYG IUNG TAREA SNAP TRSOA TRSPC RATIO ISNOW ISAME LOCAL  
1 1 0.20 0.0 0.0 1.00 0.500 0 0 0

PRECIP DATA  
SPFE PMS R6 R12 R24 R48 R72 R96  
0.0 18.00 110.00 122.00 132.00 0.0 0.0 0.0

LOSS DATA  
STKR DLTGR RTIOL ERRAIN STRKS RTIOK STRTL CNSTL ALSHX RTIMP  
0.0 0.0 1.00 0.0 0.0 1.00 0.33 0.07 0.0 0.0

UNIT HYDROGRAPH DATA  
TP# 0.50 CP#0.75 NTA# 0

RECESSION DATA

STAT# 2.00 ORCSN# -0.10 RTIOR# 1.50  
APPROXIMATE CLARK COEFFICIENTS FROM GIVEN SNYDER CP AND TP ARE TC# 4.08 AND R# 1.53 INTERVALS

UNIT HYDROGRAPH II END-OF-PERIOD ORIGINATES. LAG# 0.50 HOURS. CP# 0.75 VOL# 1.00.  
33. 109. 176. 187. 132. 68. 34. 18. 9. 5.

END-OF-PERIOD FLOW			COMP Q	
TIME	RAIN	EXCS		
1 0 10	0.02	0.00	2.	
1 0 20	0.02	0.00	2.	
1 0 30	0.02	0.00	2.	
1 0 40	0.02	0.00	2.	
1 0 50	0.02	0.00	2.	
1 0 60	0.02	0.00	2.	
1 1 10	0.02	0.00	2.	
1 1 20	0.02	0.00	1.	
1 1 30	0.02	0.00	1.	
1 1 40	0.02	0.00	1.	
1 1 50	0.02	0.00	1.	
1 1 60	0.02	0.00	1.	
1 2 10	0.02	0.00	1.	

P. 1/

1	2 20	0.02	0.00	1.
1	2 30	0.02	0.00	1.
1	2 40	0.02	0.00	1.
1	2 50	0.02	0.00	1.
1	2 60	0.02	0.01	2.
1	3 10	0.02	0.01	3.
1	3 20	0.02	0.01	4.
1	3 30	0.02	0.01	6.
1	3 40	0.02	0.01	6.
1	3 50	0.02	0.01	7.
1	3 60	0.02	0.01	7.
1	4 10	0.02	0.01	7.
1	4 20	0.02	0.01	7.
1	4 30	0.02	0.01	7.
1	4 40	0.02	0.01	7.
1	4 50	0.02	0.01	7.
1	4 60	0.02	0.01	7.
1	5 10	0.02	0.01	7.
1	5 20	0.02	0.01	7.
1	5 30	0.02	0.01	7.
1	5 40	0.02	0.01	7.
1	5 50	0.02	0.01	7.
1	5 60	0.02	0.01	7.
1	6 10	0.06	0.05	8.
1	6 20	0.06	0.05	13.
1	6 30	0.06	0.05	20.
1	6 40	0.06	0.05	27.
1	6 50	0.06	0.05	32.
1	6 60	0.06	0.05	35.
1	7 10	0.06	0.05	36.
1	7 20	0.06	0.05	37.
1	7 30	0.06	0.05	37.
1	7 40	0.06	0.05	38.
1	7 50	0.06	0.05	38.
1	7 60	0.06	0.05	38.
1	8 10	0.06	0.05	38.
1	8 20	0.06	0.05	38.
1	8 30	0.06	0.05	38.
1	8 40	0.06	0.05	38.
1	8 50	0.06	0.05	38.
1	8 60	0.06	0.05	38.
1	9 10	0.06	0.05	38.
1	9 20	0.06	0.05	38.
1	9 30	0.06	0.05	37.
1	9 40	0.06	0.05	37.
1	9 50	0.06	0.05	37.
1	9 60	0.06	0.05	37.
1	10 10	0.06	0.05	37.
1	10 20	0.06	0.05	37.
1	10 30	0.06	0.05	37.
1	10 40	0.06	0.05	37.
1	10 50	0.06	0.05	37.
1	10 60	0.06	0.05	37.
1	11 10	0.06	0.05	37.
1	11 20	0.06	0.05	37.
1	11 30	0.06	0.05	37.
1	11 40	0.06	0.05	37.
1	11 50	0.06	0.05	37.
1	11 60	0.06	0.05	37.
1	12 10	0.33	0.32	46.
1	12 20	0.33	0.32	76.
1	12 30	0.33	0.32	123.
1	12 40	0.33	0.32	174.
1	12 50	0.33	0.32	209.
1	12 60	0.33	0.32	227.
1	13 10	0.40	0.39	249.

2.2/

SUM 23.70 22.03 18008.

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
908.	407.	125.	125.	13009.
	18.92	23.27	23.27	23.27
	202.	240.	248.	248.

CFS  
INCHES  
AC-FT

3.4/



1 15 20	1 25	1 24	2998.
1 15 30	1 25	1 24	3256.
1 15 40	1 25	1 24	3507.
1 15 50	1 25	1 24	3990.
1 16 00	1 25	1 24	4400.
1 16 10	0 45	0 45	4955.
1 16 20	0 46	0 45	5416.
1 16 30	0 46	0 45	5768.
1 16 40	0 46	0 45	6070.
1 16 50	0 46	0 45	6195.
1 17 00	0 46	0 45	6192.
1 17 10	0 36	0 35	5986.
1 17 20	0 36	0 35	5713.
1 17 30	0 36	0 35	5375.
1 17 40	0 36	0 35	5006.
1 17 50	0 36	0 35	4646.
1 17 60	0 36	0 35	4328.
1 18 10	0 03	0 02	4042.
1 18 20	0 03	0 02	3766.
1 18 30	0 03	0 02	3488.
1 18 40	0 03	0 02	3202.
1 18 50	0 03	0 02	2908.
1 19 00	0 03	0 02	2605.
1 19 10	0 03	0 02	2299.
1 19 20	0 03	0 02	1997.
1 19 30	0 03	0 02	1706.
1 19 40	0 03	0 02	1455.
1 19 50	0 03	0 02	1198.
1 19 60	0 03	0 02	1001.
1 20 10	0 03	0 02	840.
1 20 20	0 03	0 02	708.
1 20 30	0 03	0 02	615.
1 20 40	0 03	0 02	591.
1 20 50	0 03	0 02	567.
1 21 00	0 03	0 02	545.
1 21 10	0 03	0 02	522.
1 21 20	0 03	0 02	502.
1 21 30	0 03	0 02	482.
1 21 40	0 03	0 02	465.
1 21 50	0 03	0 02	445.
1 21 60	0 03	0 02	427.
1 22 10	0 03	0 02	410.
1 22 20	0 03	0 02	397.
1 22 30	0 03	0 02	378.
1 22 40	0 03	0 02	363.
1 22 50	0 03	0 02	349.
1 22 60	0 03	0 02	335.
1 23 10	0 03	0 02	322.
1 23 20	0 03	0 02	309.
1 23 30	0 03	0 02	297.
1 23 40	0 03	0 02	285.
1 23 50	0 03	0 02	273.
1 23 60	0 03	0 02	263.

SUM	23.70	22.03	163430.
6-HOUR	3605.	1135.	1135.
24-HOUR	17.95	22.23	163426.
72-HOUR	1815.	2252.	2252.
TOTAL VOLUME			2252.

PEAK 6195.  
CFS INCHES  
AC-FT

4 20/

1	4 20	0-02	0-01	33.
1	4 30	0-02	0-01	38.
1	4 40	0-02	0-01	42.
1	4 50	0-02	0-01	46.
1	4 60	0-02	0-01	49.
1	5 10	0-02	0-01	51.
1	5 20	0-02	0-01	53.
1	5 30	0-02	0-01	55.
1	5 40	0-02	0-01	56.
1	5 50	0-02	0-01	57.
1	5 60	0-02	0-01	58.
1	6 10	0-05	0-05	60.
1	6 20	0-06	0-05	64.
1	6 30	0-06	0-05	73.
1	6 40	0-06	0-05	86.
1	6 50	0-06	0-05	103.
1	6 60	0-06	0-05	124.
1	7 10	0-06	0-05	175.
1	7 20	0-06	0-05	175.
1	7 30	0-06	0-05	202.
1	7 40	0-06	0-05	228.
1	7 50	0-06	0-05	251.
1	7 60	0-06	0-05	270.
1	8 10	0-06	0-05	286.
1	8 20	0-06	0-05	298.
1	8 30	0-06	0-05	309.
1	8 40	0-06	0-05	317.
1	8 50	0-06	0-05	324.
1	8 60	0-06	0-05	330.
1	9 10	0-06	0-05	335.
1	9 20	0-06	0-05	338.
1	9 30	0-06	0-05	341.
1	9 40	0-06	0-05	344.
1	9 50	0-06	0-05	346.
1	9 60	0-06	0-05	348.
1	10 10	0-06	0-05	349.
1	10 20	0-06	0-05	350.
1	10 30	0-06	0-05	351.
1	10 40	0-06	0-05	352.
1	10 50	0-06	0-05	353.
1	10 60	0-06	0-05	353.
1	11 10	0-06	0-05	353.
1	11 20	0-06	0-05	354.
1	11 30	0-06	0-05	354.
1	11 40	0-06	0-05	354.
1	11 50	0-06	0-05	354.
1	11 60	0-06	0-05	354.
1	12 10	0-33	0-32	362.
1	12 20	0-33	0-32	369.
1	12 30	0-33	0-32	444.
1	12 40	0-33	0-32	528.
1	12 50	0-33	0-32	642.
1	12 60	0-33	0-32	785.
1	13 10	0-40	0-38	951.
1	13 20	0-40	0-38	1135.
1	13 30	0-40	0-38	1328.
1	13 40	0-40	0-38	1522.
1	13 50	0-40	0-38	1705.
1	13 60	0-40	0-38	1869.
1	14 10	0-49	0-48	2017.
1	14 20	0-49	0-48	2156.
1	14 30	0-49	0-48	2293.
1	14 40	0-49	0-48	2421.
1	14 50	0-49	0-48	2548.
1	14 60	0-49	0-48	2675.



## SUB-AREA RUNOFF COMPUTATION

LARGE TRIBUTARY FROM NORTH SIDE OF ROUTE 100

ISTAQ	ICOMP	IECON	ITAPE	JPLT	JPRY	INAME
6	0	0	0	0	0	1

## HYDROGRAPH DATA

IMVOC	IUNG	TAREA	SNAP	TRSDA	TRSPC	RATIO	ISNOW	ISAME	LOCAL
1	1	1.90	0.0	0.0	1.00	0.500	0	0	0

## PRECIP DATA

SPFE	PMS	R6	R12	R24	R48	R72	R96
0.0	18.00	110.00	122.00	132.00	0.0	0.0	0.0

## LOSS DATA

STKR	DLTKR	RTIOL	ERAIN	STRKS	RTIOL	STRYL	CNSTL	ALSMX	RTIAP
0.0	0.0	1.00	0.0	0.0	1.00	0.33	0.07	0.0	0.0

## UNIT HYDROGRAPH DATA

TP#	1.40	CP#0.75	NTAB	0
-----	------	---------	------	---

## RECESSION DATA

STRQ#	2.00	QRCSN#	-0.10	RTIOR#	1.50
-------	------	--------	-------	--------	------

APPROXIMATE CLARK COEFFICIENTS FROM GIVEN SNYDER CP AND TP ARE TC=10.43 AND R# 4.97 INTERVALS

UNIT HYDROGRAPH 33 END-OF-PERIOD COORDINATES, LAG# 1.40 HOURS, CP# 0.75 VOL# 1.00	
28.	103.
574.	477.
78.	63.
10.	8.
311.	423.
319.	260.
42.	35.
529.	213.
609.	174.
654.	23.
666.	19.
116.	15.
95.	13.

## END-OF-PERIOD FLOW

TIME	RAIN	EXCS	COMP	Q
1 0 10	0.02	0.00	2.	2.
1 0 20	0.02	0.00	2.	2.
1 0 30	0.02	0.00	2.	2.
1 0 40	0.02	0.00	2.	2.
1 0 50	0.02	0.00	2.	2.
1 1 00	0.02	0.00	2.	2.
1 1 10	0.02	0.00	2.	2.
1 1 20	0.02	0.00	1.	1.
1 1 30	0.02	0.00	1.	1.
1 1 40	0.02	0.00	1.	1.
1 1 50	0.02	0.00	1.	1.
1 1 60	0.02	0.00	1.	1.
1 2 10	0.02	0.00	1.	1.
1 2 20	0.02	0.00	1.	1.
1 2 30	0.02	0.00	1.	1.
1 2 40	0.02	0.00	1.	1.
1 2 50	0.02	0.00	1.	1.
1 3 00	0.02	0.01	2.	2.
1 3 10	0.02	0.01	3.	3.
1 3 20	0.02	0.01	5.	5.
1 3 30	0.02	0.01	8.	8.
1 3 40	0.02	0.01	12.	12.
1 3 50	0.02	0.01	17.	17.
1 4 00	0.02	0.01	22.	22.
1 4 10	0.02	0.01	27.	27.

1 18 10 47. 548. 598.  
 1 18 20 46. 510. 564.  
 1 18 30 45. 462. 525.  
 1 18 40 44. 394. 475.  
 1 18 50 42. 321. 413.  
 1 18 60 40. 253. 354.  
 1 19 10 38. 198. 255.  
 1 19 20 37. 162. 255.  
 1 19 30 36. 149. 223.  
 1 19 40 35. 142. 198.  
 1 19 50 34. 135. 174.  
 1 19 60 33. 129. 164.  
 1 20 10 33. 123. 152.  
 1 20 20 32. 118. 141.  
 1 20 30 32. 113. 133.  
 1 20 40 32. 108. 125.  
 1 20 50 32. 104. 119.  
 1 20 60 31. 101. 113.  
 1 21 10 31. 98. 109.  
 1 21 20 31. 95. 105.  
 1 21 30 31. 92. 101.  
 1 21 40 31. 89. 99.  
 1 21 50 31. 87. 98.  
 1 21 60 30. 84. 96.  
 1 22 10 30. 82. 94.  
 1 22 20 30. 79. 92.  
 1 22 30 30. 77. 91.  
 1 22 40 30. 74. 89.  
 1 22 50 29. 72. 87.  
 1 22 60 29. 70. 85.  
 1 23 10 29. 68. 83.  
 1 23 20 29. 66. 81.  
 1 23 30 28. 64. 79.  
 1 23 40 28. 62. 77.  
 1 23 50 28. 60. 75.  
 1 23 60 28. 58. 73.

SUM

28149.

CES INCHES AC-FT	PEAK 1347.	6-HOUR 672. 8.93 333.	24-HOUR 195. 10.39 388.	72-HOUR 195. 10.39 388.	TOTAL VOLUME 28149. 10.39 388.
------------------------	---------------	--------------------------------	----------------------------------	----------------------------------	---

8-17/

1	7	10	3.	36.	4.
1	7	20	4.	41.	4.
1	7	30	4.	46.	4.
1	7	40	5.	46.	5.
1	7	50	6.	47.	5.
1	7	60	6.	48.	6.
1	8	10	7.	49.	6.
1	8	20	7.	50.	7.
1	8	30	8.	51.	8.
1	8	40	8.	51.	8.
1	8	50	9.	51.	9.
1	8	60	10.	52.	10.
1	9	10	10.	52.	10.
1	9	20	11.	53.	11.
1	9	30	11.	53.	11.
1	9	40	12.	53.	12.
1	9	50	13.	54.	13.
1	9	60	13.	54.	13.
1	10	10	14.	54.	14.
1	10	20	14.	54.	14.
1	10	30	15.	55.	15.
1	10	40	15.	55.	15.
1	10	50	16.	55.	16.
1	10	60	16.	55.	16.
1	11	10	17.	56.	17.
1	11	20	17.	56.	17.
1	11	30	18.	56.	18.
1	11	40	18.	56.	18.
1	11	50	19.	57.	19.
1	11	60	19.	57.	19.
1	12	10	20.	59.	20.
1	12	20	20.	68.	20.
1	12	30	21.	88.	30.
1	12	40	22.	119.	34.
1	12	50	24.	159.	39.
1	12	60	26.	201.	56.
1	13	10	28.	239.	78.
1	13	20	31.	271.	102.
1	13	30	33.	298.	161.
1	13	40	35.	323.	210.
1	13	50	37.	355.	254.
1	13	60	38.	397.	298.
1	14	10	40.	436.	350.
1	14	20	41.	469.	395.
1	14	30	42.	499.	434.
1	14	40	43.	528.	470.
1	14	50	44.	556.	503.
1	14	60	45.	582.	533.
1	15	10	46.	610.	562.
1	15	20	47.	657.	598.
1	15	30	49.	743.	667.
1	15	40	51.	877.	767.
1	15	50	54.	1043.	899.
1	15	60	57.	1211.	1047.
1	16	10	60.	1345.	1190.
1	16	20	63.	1416.	1297.
1	16	30	64.	1402.	1347.
1	16	40	63.	1316.	1342.
1	16	50	62.	1183.	1261.
1	16	60	59.	1037.	1154.
1	17	10	57.	909.	1038.
1	17	20	55.	812.	930.
1	17	30	53.	739.	839.
1	17	40	51.	678.	762.



COMBINE

COMBINE HYDROGRAPHS

COMBINE INFLOW FROM WEST POND WITH TRIBUTARY NO. 1  
 ISTAQ ICOMP IECON ITAPE JPLT JPRY INAME  
 4 2 0 0 0 0 1

SUM OF 2 HYDROGRAPHS AT									
2.	3.	3.	3.	3.	3.	3.	3.	3.	3.
2.	2.	2.	2.	2.	2.	2.	2.	2.	2.
5.	6.	7.	8.	9.	9.	10.	10.	10.	10.
10.	10.	10.	10.	10.	10.	11.	11.	11.	11.
28.	34.	39.	42.	45.	47.	48.	48.	49.	50.
51.	51.	52.	52.	53.	53.	53.	53.	54.	54.
54.	55.	55.	55.	55.	55.	56.	56.	56.	56.
57.	57.	61.	75.	101.	138.	180.	222.	256.	285.
311.	335.	376.	418.	453.	484.	513.	542.	570.	594.
626.	688.	797.	956.	1131.	1290.	1401.	1430.	1374.	1257.
1109.	966.	853.	772.	706.	650.	602.	565.	531.	499.
430.	357.	285.	221.	171.	153.	145.	138.	132.	126.
120.	115.	110.	106.	102.	99.	96.	94.	91.	88.
85.	83.	80.	78.	75.	73.	71.	69.	67.	65.
63.	61.	59.	57.						

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
1430.	684.	209.	209.	30159.
CFS	9.09	11.13	11.13	11.13
INCHES	339.	416.	416.	416.
AC-FT				



P.13/

1 15 40	1.25	1.24	1346.
1 15 50	1.25	1.24	1579.
1 15 60	1.25	1.24	1800.
1 16 10	0.46	0.45	1952.
1 16 20	0.46	0.45	1999.
1 16 30	0.46	0.45	1940.
1 16 40	0.46	0.45	1795.
1 16 50	0.46	0.45	1602.
1 16 60	0.46	0.45	1408.
1 17 10	0.36	0.35	1248.
1 17 20	0.36	0.35	1127.
1 17 30	0.36	0.35	1029.
1 17 40	0.36	0.35	947.
1 17 50	0.36	0.35	878.
1 17 60	0.36	0.35	822.
1 18 10	0.03	0.02	770.
1 18 20	0.03	0.02	705.
1 18 30	0.03	0.02	621.
1 18 40	0.03	0.02	517.
1 18 50	0.03	0.02	406.
1 18 60	0.03	0.02	303.
1 19 10	0.03	0.02	222.
1 19 20	0.03	0.02	195.
1 19 30	0.03	0.02	167.
1 19 40	0.03	0.02	180.
1 19 50	0.03	0.02	173.
1 19 60	0.03	0.02	166.
1 20 10	0.03	0.02	159.
1 20 20	0.03	0.02	153.
1 20 30	0.03	0.02	147.
1 20 40	0.03	0.02	141.
1 20 50	0.03	0.02	135.
1 20 60	0.03	0.02	130.
1 21 10	0.03	0.02	125.
1 21 20	0.03	0.02	120.
1 21 30	0.03	0.02	115.
1 21 40	0.03	0.02	111.
1 21 50	0.03	0.02	106.
1 21 60	0.03	0.02	102.
1 22 10	0.03	0.02	98.
1 22 20	0.03	0.02	94.
1 22 30	0.03	0.02	90.
1 22 40	0.03	0.02	87.
1 22 50	0.03	0.02	83.
1 22 60	0.03	0.02	80.
1 23 10	0.03	0.02	77.
1 23 20	0.03	0.02	74.
1 23 30	0.03	0.02	71.
1 23 40	0.03	0.02	68.
1 23 50	0.03	0.02	65.
1 23 60	0.03	0.02	63.

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
1999.	999.	305.	306.	44072.
CFS	18-58	22-78	22-78	44078.
INCHES	496.	607.	607.	22-78
AC-FT				607.

P. 12-1

1	4 40	0.02	0.01	16.
1	4 50	0.02	0.01	16.
1	4 60	0.02	0.01	16.
1	5 10	0.02	0.01	16.
1	5 20	0.02	0.01	16.
1	5 30	0.02	0.01	16.
1	5 40	0.02	0.01	17.
1	5 50	0.02	0.01	17.
1	5 60	0.02	0.01	17.
1	6 10	0.05	0.05	18.
1	6 20	0.06	0.05	22.
1	6 30	0.05	0.05	29.
1	6 40	0.06	0.05	39.
1	6 50	0.06	0.05	51.
1	6 60	0.06	0.05	63.
1	7 10	0.06	0.05	72.
1	7 20	0.05	0.05	78.
1	7 30	0.06	0.05	83.
1	7 40	0.06	0.05	86.
1	7 50	0.06	0.05	88.
1	8 10	0.06	0.05	90.
1	8 20	0.06	0.05	92.
1	8 30	0.06	0.05	92.
1	8 40	0.06	0.05	93.
1	8 50	0.06	0.05	93.
1	8 60	0.05	0.05	93.
1	9 10	0.06	0.05	93.
1	9 20	0.06	0.05	93.
1	9 30	0.06	0.05	93.
1	9 40	0.06	0.05	93.
1	9 50	0.06	0.05	93.
1	10 10	0.06	0.05	93.
1	10 20	0.06	0.05	93.
1	10 30	0.06	0.05	93.
1	10 40	0.06	0.05	93.
1	10 50	0.06	0.05	93.
1	10 60	0.06	0.05	93.
1	11 10	0.06	0.05	93.
1	11 20	0.06	0.05	93.
1	11 30	0.06	0.05	93.
1	11 40	0.06	0.05	93.
1	11 50	0.06	0.05	93.
1	12 10	0.06	0.05	93.
1	12 20	0.33	0.32	101.
1	12 30	0.33	0.32	127.
1	12 40	0.33	0.32	177.
1	12 50	0.33	0.32	248.
1	12 60	0.33	0.32	328.
1	13 10	0.40	0.38	405.
1	13 20	0.40	0.38	468.
1	13 30	0.40	0.38	519.
1	13 40	0.40	0.38	561.
1	13 50	0.40	0.38	600.
1	14 10	0.49	0.48	665.
1	14 20	0.49	0.48	691.
1	14 30	0.49	0.48	716.
1	14 40	0.49	0.48	746.
1	14 50	0.49	0.48	780.
1	14 60	0.49	0.48	816.
1	15 10	1.25	1.24	C40.
1	15 20	1.25	1.24	894.
1	15 30	1.25	1.24	905.



# SUB-AREA RUNOFF COMPUTATION

HYDROGRAPH FOR TRIBUTARY NUMBER 1  
 ISTAQ ICOMP IECON ITAPE JPLT JPRJ INAME

INHYOC IUNG TAREA SNAP TRSDA TPSPC RATIO ISNOW ISAME LOCAL  
 1 1 0.50 0.0 0.0 1.00 0.500 0 0 0

PRECIP DATA  
 SPEE PMS R6 R12 R24 R48 R72 R96  
 0.0 18.00 110.00 122.00 132.00 0.0 0.0 0.0

LOSS DATA  
 STRKR OLTKR RTIOL ERRAIN STRKS RTIOK STRTL CNSTL ALSMX RTIMP  
 0.0 0.0 1.00 0.0 0.0 0.0 1.00 0.33 0.07 0.0 0.0

UNIT HYDROGRAPH DATA  
 TP# 0.80 CP#0.75 NTA# 0

RECESSION DATA  
 STRTQ# 2.00 ORCSN# -0.10 RTIOR# 1.50  
 APPROXIMATE CLARK COEFFICIENTS FROM GIVEN SNYDER CP AND TP ARE TC# 5.91 AND R# 2.94 INTERVALS

UNIT HYDROGRAPH 19 END-OF-PERIOD ORIGINATES, LAG# 0.80 HOURS, CP# 0.76 VOL# 1.00  
 28. 98. 186. 262. 299. 285. 226. 160. 114. 81.  
 57. 41. 29. 20. 15. 10. 7. 5. 4.

## END-OF-PERIOD FLOW

TIME	RAIN	EXCS	COMP	Q
1 0 10	0.02	0.00	2.	2.
1 0 20	0.02	0.00	2.	2.
1 0 30	0.02	0.00	2.	2.
1 0 40	0.02	0.00	2.	2.
1 0 50	0.02	0.00	2.	2.
1 0 60	0.02	0.00	2.	2.
1 1 10	0.02	0.00	2.	2.
1 1 20	0.02	0.00	1.	1.
1 1 30	0.02	0.00	1.	1.
1 1 40	0.02	0.00	1.	1.
1 1 50	0.02	0.00	1.	1.
1 1 60	0.02	0.00	1.	1.
1 2 10	0.02	0.00	1.	1.
1 2 20	0.02	0.00	1.	1.
1 2 30	0.02	0.00	1.	1.
1 2 40	0.02	0.00	1.	1.
1 2 50	0.02	0.00	1.	1.
1 2 60	0.02	0.01	2.	2.
1 3 10	0.02	0.01	3.	3.
1 3 20	0.02	0.01	5.	5.
1 3 30	0.02	0.01	7.	7.
1 3 40	0.02	0.01	9.	9.
1 3 50	0.02	0.01	11.	11.
1 3 60	0.02	0.01	13.	13.
1 4 10	0.02	0.01	14.	14.
1 4 20	0.02	0.01	15.	15.
1 4 30	0.02	0.01	15.	15.

8-12/

1 18 10	19.	135.	146.
1 18 20	19.	122.	136.
1 18 30	19.	98.	120.
1 18 40	18.	67.	82.
1 18 50	18.	48.	62.
1 18 60	17.	43.	60.
1 19 10	17.	41.	56.
1 19 20	17.	40.	52.
1 19 30	16.	38.	49.
1 19 40	16.	37.	46.
1 19 50	16.	35.	43.
1 19 60	16.	34.	41.
1 20 10	16.	33.	39.
1 20 20	15.	30.	37.
1 20 30	15.	29.	35.
1 20 40	15.	28.	34.
1 20 50	15.	27.	33.
1 20 60	15.	26.	32.
1 21 10	15.	24.	31.
1 21 20	15.	24.	30.
1 21 30	15.	23.	29.
1 21 40	15.	22.	28.
1 21 50	14.	21.	27.
1 21 60	14.	20.	26.
1 22 10	14.	19.	25.
1 22 20	14.	18.	24.
1 22 30	14.	17.	23.
1 22 40	14.	16.	22.
1 22 50	13.	16.	21.
1 22 60	13.	15.	20.
1 23 10	13.	14.	19.
1 23 20	13.	14.	18.
1 23 30	13.	13.	17.
1 23 40	12.	13.	16.
1 23 50	12.	13.	15.
1 23 60	12.	13.	14.
SUM 8119.			
PEAK	6-HOUR	24-HOUR	72-HOUR
431.	189.	56.	56.
CFS	8.78	10.49	10.49
INCHES	94.	112.	112.
AC-FT			

p. 2/

1 7 10	1.	16.	3.
1 7 20	1.	18.	3.
1 7 30	1.	19.	3.
1 7 40	2.	19.	4.
1 7 50	2.	19.	4.
1 7 60	2.	19.	4.
1 8 10	2.	19.	4.
1 8 20	3.	19.	5.
1 8 30	3.	19.	5.
1 8 40	3.	19.	5.
1 8 50	3.	19.	5.
1 8 60	3.	19.	6.
1 9 10	3.	19.	6.
1 9 20	4.	19.	6.
1 9 30	4.	19.	7.
1 9 40	4.	19.	7.
1 9 50	4.	19.	7.
1 9 60	4.	19.	8.
1 10 10	4.	19.	8.
1 10 20	5.	19.	8.
1 10 30	5.	19.	8.
1 10 40	5.	19.	9.
1 10 50	5.	19.	9.
1 10 60	5.	19.	9.
1 11 10	5.	19.	9.
1 11 20	5.	19.	10.
1 11 30	5.	19.	10.
1 11 40	6.	19.	10.
1 11 50	6.	19.	10.
1 11 60	6.	19.	10.
1 12 10	6.	21.	11.
1 12 20	6.	30.	11.
1 12 30	7.	50.	12.
1 12 40	8.	74.	14.
1 12 50	9.	96.	16.
1 12 60	10.	109.	19.
1 13 10	11.	117.	22.
1 13 20	13.	122.	26.
1 13 30	14.	129.	31.
1 13 40	15.	136.	35.
1 13 50	17.	142.	58.
1 13 60	18.	145.	86.
1 14 10	18.	147.	108.
1 14 20	19.	152.	126.
1 14 30	19.	159.	140.
1 14 40	20.	169.	152.
1 14 50	20.	176.	162.
1 14 60	20.	181.	170.
1 15 10	20.	190.	179.
1 15 20	21.	218.	195.
1 15 30	22.	273.	228.
1 15 40	23.	342.	283.
1 15 50	24.	403.	342.
1 15 60	25.	441.	390.
1 16 10	26.	454.	425.
1 16 20	26.	436.	431.
1 16 30	25.	384.	404.
1 16 40	24.	315.	360.
1 16 50	23.	253.	308.
1 16 60	22.	214.	262.
1 17 10	22.	193.	229.
1 17 20	21.	179.	208.
1 17 30	21.	167.	191.
1 17 40	20.	155.	176.
1 17 50	20.	146.	163.

HYDROGRAPH ROUTING

ROUTING THROUGH WEST POIN

ISTAQ 3

IECON 0

ITYPE 0

JPLT 0

JPRY 0

INAME 1

ROUTING DATA

AVG 0.0

IRIS 1

ISAME 0

QLOSS 0.0

CLOSS 0.0

LAG 0

ANSKK 0.0

X 0.0

TSK 0.0

STORA -1

NSTPS 1

0

6

10

11

20

15

35

17

60

18

100

22

235

25

400

29

600

STORAGE#

OUTFLOW#

0

2

3

5

TIME EOP STOR

1 0 10 0

1 0 20 0

1 0 30 0

1 0 40 0

1 0 50 0

1 0 60 0

1 1 10 0

1 1 20 0

1 1 30 0

1 1 40 0

1 1 50 0

1 1 60 0

1 2 10 0

1 2 20 0

1 2 30 0

1 2 40 0

1 2 50 0

1 2 60 0

1 3 10 0

1 3 20 0

1 3 30 0

1 3 40 0

1 3 50 0

1 3 60 0

1 4 10 0

1 4 20 0

1 4 30 0

1 4 40 0

1 4 50 0

1 4 60 0

1 5 10 0

1 5 20 0

1 5 30 0

1 5 40 0

1 5 50 0

1 5 60 0

1 6 10 0

1 6 20 0

1 6 30 0

1 6 40 0

1 6 50 0

1 6 60 0

AVG IN

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

EOP OUT

1

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2

2



## SUB-AREA RUNOFF COMPUTATION

REMAINING INTERVENING AREAS  
1STAQ ICOMP 0

IECON ITAPE JPLT JPRT INAME  
0 0 0 0 1

HYDROGRAPH DATA  
IHYDG IUNG TAREA SNAP TRSDA TRSPC RATIO ISNOW ISAME LOCAL  
1 1 1.70 0.0 0.0 1.00 0.500 0 0 0

PRECIP DATA  
SPFE PMS R6 R12 R24 R48 R72 R96  
0.0 18.00 110.00 122.00 132.00 0.0 0.0 0.0

LOSS DATA  
STRKR DLTNR RTIOL ERAIN STRKS RTIOK STRTL CNSTL ALSMX RTIMP  
0.0 0.0 1.00 0.0 0.0 1.00 0.33 0.07 0.0 0.0

UNIT HYDROGRAPH DATA  
TP# 0.50 CPA0.75 NTA# 0

RECESSION DATA  
STRTO# 2.00 GRCSN# -0.10 RTIOR# 1.50  
APPROXIMATE CLARK COEFFICIENTS FROM GIVEN SNYDER CP AND TP ARE TC# 4.08 AND R# 1.53 INTERVALS

UNIT HYDROGRAPH 11 END-OF-PERIOD ORIGINATES, LAG# 0.50 HOURS, CP# 0.75 VOL# 1.00 38.  
277. 925. 1498. 576. 293. 149.  
20.

## END-OF-PERIOD FLOW

TIME	RAIN	EXCS	COMP	Q
1 0 10	0.02	0.00	2.	2.
1 0 20	0.02	0.00	2.	2.
1 0 30	0.02	0.00	2.	2.
1 0 40	0.02	0.00	2.	2.
1 0 50	0.02	0.00	2.	2.
1 0 60	0.02	0.00	2.	2.
1 1 10	0.02	0.00	2.	2.
1 1 20	0.02	0.00	1.	1.
1 1 30	0.02	0.00	1.	1.
1 1 40	0.02	0.00	1.	1.
1 1 50	0.02	0.00	1.	1.
1 1 60	0.02	0.00	1.	1.
1 2 10	0.02	0.00	1.	1.
1 2 20	0.02	0.00	1.	1.
1 2 30	0.02	0.00	1.	1.
1 2 40	0.02	0.00	1.	1.
1 2 50	0.02	0.00	2.	2.
1 2 60	0.02	0.01	7.	7.
1 3 10	0.02	0.01	17.	17.
1 3 20	0.02	0.01	30.	30.
1 3 30	0.02	0.01	41.	41.
1 3 40	0.02	0.01	48.	48.
1 3 50	0.02	0.01	52.	52.
1 3 60	0.02	0.01	56.	56.
1 4 10	0.02	0.01	55.	55.
1 4 20	0.02	0.01	55.	55.
1 4 30	0.02	0.01	55.	55.



1 15 40	1.25	1.24	6422.
1 15 50	1.25	1.24	7274.
1 15 60	1.25	1.24	7712.
1 16 10	0.46	0.45	7714.
1 16 20	0.46	0.45	7095.
1 16 30	0.46	0.45	5966.
1 16 40	0.46	0.45	4738.
1 16 50	0.46	0.45	3866.
1 16 60	0.46	0.45	3409.
1 17 10	0.36	0.35	3150.
1 17 20	0.36	0.35	2941.
1 17 30	0.36	0.35	2732.
1 17 40	0.36	0.35	2545.
1 17 50	0.36	0.35	2418.
1 17 60	0.36	0.35	2361.
1 18 10	0.03	0.02	2240.
1 18 20	0.03	0.02	1917.
1 18 30	0.03	0.02	1411.
1 18 40	0.03	0.02	879.
1 18 50	0.03	0.02	750.
1 18 60	0.03	0.02	720.
1 19 10	0.03	0.02	664.
1 19 20	0.03	0.02	637.
1 19 30	0.03	0.02	612.
1 19 40	0.03	0.02	588.
1 19 50	0.03	0.02	564.
1 19 60	0.03	0.02	542.
1 20 10	0.03	0.02	520.
1 20 20	0.03	0.02	500.
1 20 30	0.03	0.02	480.
1 20 40	0.03	0.02	461.
1 20 50	0.03	0.02	442.
1 20 60	0.03	0.02	425.
1 21 10	0.03	0.02	408.
1 21 20	0.03	0.02	392.
1 21 30	0.03	0.02	376.
1 21 40	0.03	0.02	361.
1 21 50	0.03	0.02	347.
1 21 60	0.03	0.02	333.
1 22 10	0.03	0.02	320.
1 22 20	0.03	0.02	307.
1 22 30	0.03	0.02	295.
1 22 40	0.03	0.02	283.
1 22 50	0.03	0.02	272.
1 22 60	0.03	0.02	261.
1 23 10	0.03	0.02	251.
1 23 20	0.03	0.02	241.
1 23 30	0.03	0.02	231.
1 23 40	0.03	0.02	222.
1 23 50	0.03	0.02	213.
1 23 60	0.03	0.02	

SUM	23.70	22.03	152712.
PEAK	7714.		
CFS			
INCHES			
AC-FT			
6-HOUR	3458.	1061.	72-HOUR
24-HOUR	18.92	23.21	TOTAL VOLUME
	1716.	2105.	152717.
			23.21
			2105.









ROUTE THROUGH LAKE SADAWGA  
ISTAQ ICOMP 9 1

[illegible]

12-29/


1	7	10	22.	222.	11.
1	7	20	25.	239.	12.
1	7	30	29.	255.	13.
1	7	40	32.	270.	14.
1	7	50	36.	283.	16.
1	7	60	40.	294.	17.
1	8	10	44.	304.	18.
1	8	20	48.	311.	20.
1	8	30	52.	318.	21.
1	8	40	56.	323.	22.
1	8	50	60.	328.	24.
1	8	60	64.	332.	25.
1	9	10	69.	335.	26.
1	9	20	73.	338.	28.
1	9	30	77.	340.	29.
1	9	40	81.	342.	31.
1	9	50	86.	344.	32.
1	9	60	90.	346.	33.
1	10	10	94.	347.	35.
1	10	20	99.	349.	36.
1	10	30	103.	350.	38.
1	10	40	107.	351.	39.
1	10	50	112.	352.	40.
1	10	60	116.	353.	42.
1	11	10	120.	354.	43.
1	11	20	124.	355.	45.
1	11	30	129.	356.	46.
1	11	40	133.	357.	47.
1	11	50	137.	358.	49.
1	11	60	142.	360.	50.
1	12	10	146.	362.	52.
1	12	20	152.	473.	54.
1	12	30	160.	659.	56.
1	12	40	172.	905.	60.
1	12	50	187.	1142.	65.
1	12	60	204.	1332.	72.
1	13	10	224.	1492.	85.
1	13	20	245.	1652.	101.
1	13	30	269.	1845.	118.
1	13	40	295.	2052.	137.
1	13	50	324.	2242.	157.
1	13	60	355.	2401.	179.
1	14	10	388.	2548.	202.
1	14	20	422.	2705.	233.
1	14	30	458.	2880.	270.
1	14	40	496.	3062.	310.
1	14	50	536.	3228.	352.
1	14	60	577.	3365.	396.
1	15	10	620.	3534.	443.
1	15	20	667.	3887.	494.
1	15	30	722.	4517.	554.
1	15	40	788.	5336.	642.
1	15	50	863.	6151.	759.
1	15	60	945.	6832.	909.
1	16	10	1033.	7329.	1067.
1	16	20	1120.	7535.	1245.
1	16	30	1203.	7921.	1610.
1	16	40	1273.	6983.	2072.
1	16	50	1332.	6514.	2524.
1	16	60	1378.	6115.	2889.
1	17	10	1416.	5772.	3182.
1	17	20	1446.	5431.	3410.
1	17	30	1467.	5075.	3579.
1	17	40	1482.	4714.	3695.
1	17	50	1491.	4383.	3765.

p.30/

1 18 10	1497.	3863.	3806.
1 18 20	1493.	3573.	3782.
1 18 30	1486.	3190.	3722.
1 18 40	1473.	2745.	3623.
1 18 50	1457.	2300.	3496.
1 18 60	1439.	2131.	3358.
1 19 10	1420.	1904.	3210.
1 19 20	1400.	1688.	3055.
1 19 30	1379.	1490.	2896.
1 19 40	1359.	1308.	2735.
1 19 50	1338.	1147.	2573.
1 19 60	1317.	1009.	2414.
1 20 10	1298.	894.	2260.
1 20 20	1279.	799.	2112.
1 20 30	1260.	723.	1970.
1 20 40	1243.	675.	1839.
1 20 50	1228.	647.	1730.
1 20 60	1213.	620.	1659.
1 21 10	1199.	595.	1591.
1 21 20	1185.	571.	1526.
1 21 30	1172.	549.	1464.
1 21 40	1160.	528.	1404.
1 21 50	1148.	510.	1347.
1 21 60	1136.	492.	1292.
1 22 10	1125.	474.	1235.
1 22 20	1114.	458.	1233.
1 22 30	1104.	441.	1210.
1 22 40	1093.	426.	1188.
1 22 50	1083.	410.	1166.
1 22 60	1072.	395.	1144.
1 23 10	1062.	381.	1122.
1 23 20	1051.	367.	1101.
1 23 30	1041.	354.	1082.
1 23 40	1031.	341.	1064.
1 23 50	1021.	329.	1046.
1 23 60	1011.	316.	1028.
SUM			
PEAK	6-HOUR	24-HOUR	72-HOUR
3806.	2552.	786.	786.
CFS	5.52	6.80	6.80
INCHES	1266.	1559.	1559.
AC-FT			
TOTAL VOLUME			
113160.			

## RUNOFF SUMMARY, AVERAGE FLOW

	PEAK	6-HOUR	24-HOUR	72-HOUR	AREA
HYDROGRAPH AT 2	454.	203.	63.	63.	0.20
ROUTED TO 3	431.	189.	56.	56.	0.20
HYDROGRAPH AT 1	999.	499.	153.	153.	0.50
2 COMBINED 4	1430.	684.	209.	209.	0.70
ROUTED TO 5	1347.	672.	195.	195.	0.70
HYDROGRAPH AT 6	3098.	1833.	567.	567.	1.90
HYDROGRAPH AT 7	3857.	1729.	530.	530.	1.70
3 COMBINED 8	7553.	4152.	1293.	1293.	4.30
ROUTED TO 9	3906.	2532.	786.	786.	4.30



Rating Curve  
 Sadawga Lake  
 D-H W.O. 22-0255  
 M J Root 7-30-78



# DUFRESNE-HENRY ENGINEERING CORPORATION

ROOT  
30-78

SUBJECT Spillway Capacity

SHEET NO. 33 OF 36

JOB NO. 22-0255

1, crest elevation 96.2', 1-foot rise, 1:3 slope  
ream face  
 $H^{3/2}$ ; where  $C = 3.85$  by King, Table 5-11, p. 5-50

$$\text{Discharge} = (3.64)(9)(101.8 - 96.2)^{3/2} = 434 \text{ cfs}$$

2, crest elevation 98.9', 9-foot width, level stone  
 $H^{3/2}$ ; where  $C = 2.64$  by King, Table 5-3, p. 5-46

$$\text{Discharge} = (2.64)(45.5)(101.8 - 98.9)^{3/2} = 593 \text{ cfs}$$

$$\text{gated Spillway Capacity} = 1052 \text{ cfs say } 1050 \text{ cfs}$$

## Rating for Spillway

$H_1$	$C_1$	$L_1 = 9'$	$Q_1$	$H_2$	$C_2$	$L_2 = 45.5$	$Q_2$	$Q_T$	Storage Ac-ft.
0	0		0	0	0	0	—	0	
0.5	3.85		12				—	12	101
1.0	3.85		35				—	35	202
1.5	3.82		63				—	63	303
2	3.79		96				—	96	404
2.7	3.77		151	0	0		—	151	545
3.2	3.75		193	0.5	2.7		43	236	646
3.7	3.73		239	1.0	2.68		122	361	747
4.2	3.70		287	1.5	2.64		221	508	848
4.7	3.67		337	2.0			340	677	949
5.2	3.64		388	2.5			475	863	1050
5.6	3.64		434	2.9	2.64		593	1027	1131
6.1	3.64		493	3.4	2.64		753	1246	1232
6.6	3.64		555	3.9	2.64		925	1480	1333
th dam, $L = 300' \pm$									
0.5	2.48		264					1550	
1.0	2.68		804	← @ top of "West Dike"					2285
1.5	2.64		1455					3183	

150'± long upper  
1.5 2.49

132

$$SDF = 3800 \text{ cfs}$$

# DUFRESNE-HENRY ENGINEERING CORPORATION

WOT \_\_\_\_\_ SUBJECT Flow through outlet SHEET NO. 34 OF 36  
 1-78 \_\_\_\_\_ stop-log structure JOB NO. 22-0255

11s over weir 1.5' wide with effective length of 17.1'  
 (approx.)  
 in flows outlet 4'  $\phi$  pipe obstructed w-3'  $\phi$  orifice

pipe  $\approx 85.2'$ , Compute rating for full pipe for  $TW = \frac{D_c + D}{2}$

orifice  $\approx 85.7'$

ce  $\div$  1'- $\phi$  pipe

$D_c$  H Hw/D Hw stage

25  
 75 kw-flow

.4				} Pipe flow by inlet control
.0	1.2	4.8'	90.0	
-	2.0	8.0	93.2	
-	3.0	12.0'	97.2'	
	4.0	16.0'	101.2'	
	3.5	14.0	99.2'	

W	C	Q
H	~	0
.5	2.64	16
.0	2.75	47
.5	3.00	94
.0	3.03	146
.0	3.32	295

~ outlet limited to  $\approx 210$  cfs

AD-A156 259

NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS  
LAKE SADAWGA (VT 0001 (U) CORPS OF ENGINEERS WALTHAM  
MA NEW ENGLAND DIV AUG 78

2/2

UNCLASSIFIED


F/G 13/13

NL

END

FMED

OTC



MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS 1963 A

# DUFRESNE-HENRY ENGINEERING CORPORATION

M. Root  
DATE 7-30-78

SUBJECT outflow vs  
flood storage surcharge

SHEET NO. 35 OF 36  
JOB NO. 22-0555

Assume  $Q$  rec. and @ 96.2

4

Ac-ft

0

96.2 +

$$35 + 35 = 70$$

202

97.2

$$96 + 118 = 214$$

404

98.2

$$151 + 210 = 361$$

545

98.9

$$361 + 220 = 581$$

747

99.9

$$508 + 225 = 733$$

848

100.9

$$863 + 235 = 1098$$

1050

101.9

$$1027 + 240 = 1267$$

1131

101.8

$$1510 + 240 = 1750$$

1232

102.3

$$2285 + 250 = 2535$$

1333

102.8

# DUFRESNE-HENRY ENGINEERING CORPORATION

MJR  
DATE 7-26-78

SUBJECT Route 100 Bridge  
Inlet Control

SHEET NO. 36 OF 36  
JOB NO. 22-0555

inlet control, bridge is 19' wide x 9.5' deep, invert 485.5 = 84.4

	Q	HW/D	HW	WSEL
cfs ("rare flood" by HMT)	28.4 cfs/ft	.45	4.28	88.7
cfs ( $Q_p$ )	121.6 cfs/ft	1.4	13.3	97.7 (less than 2' over rd)
cfs	200 cfs/ft	2.5	19'	
cfs	105 cfs/ft	1.16		← low estimate for flow thru

cfs over road run through town down Route 100 and channel

weir control - est. 100' effective length,  $C = 3.03$

$$(1800) = (3.03)(100) H^{3/2}$$

$$H^{3/2} = 5.94$$

$$H = 3.3' / \text{max. stage} \approx 84.4 + H + 3.3 = 98.7'$$

WSEL behind dam 103.3 ±

∴ submergence is minor

4.33 sq. mi. water shed

minimum flow	$(4.33/6.4)(.06) = .04$ cfs	min. day
average flow	$(4.33/6.4)(15.7) = 10.6$ cfs	average annual
maximum flow	$(4.33/6.4)^{.75}(1176) = 873$ cfs	1976 flood

$$\begin{aligned} (4.33/39)^{.75} & 8,950 = 1721 \\ & 9,980 = 1919 \\ & 8,450 = 1625 \end{aligned}$$

1534 cfs average est. max. inflow  
767 cfs max. outflow

# DUFRESNE-HENRY ENGINEERING CORPORATION

BY J. R. SPENCER

SUBJECT LAKE SADAWGA DAM


SHEET NO. 37 OF 37

DATE 10-2-78

JOB NO. VT 00012

## HYDROLOGIC CHARACTERISTICS

LOCAL DATUM



CAPACITIES			
% OF $\frac{1}{2}$ PMF	WATER ELEV. FT	OUTLET	CAPACITY CFS
4%	98.9	STOP LOG OUTLET	151
6%	99.4	DESIGN SURCHARGE	236
27%	101.8	TOP OF DAM	1027
60%	102.8	TOP OF WEST DIKE	2285
100%	103.3	OVER TOP	$\approx$ 3800

APPENDIX E

Information as Contained in the National Inventory of Dams





# INVENTORY OF DAMS IN THE UNITED STATES

IDENTITY NUMBER	STATE	DIVISION	COUNTY	CONTRACT	NAME	LATITUDE (NORTH)	LONGITUDE (WEST)	REPORT DATE DAY   MO   YR
VT 12 NED	VT	025	01		LAKE SADANGA DAM	4247.2	7252.9	08SEP78

POPULAR NAME	NAME OF IMPONDMENT
	LAKE SADANGA

REGION	RIVER OR STREAM	NEAREST DOWNSTREAM CITY-TOWN-VILLAGE	DIST FROM DAM (MI.)	POPULATION
01 00	TR-LAKE WHITINGHAM	WHITINGHAM	0	100

TYPE OF DAM	YEAR COMPLETED	PURPOSES	STRUCTURE	HYDRAULIC HEAD (FT.)	IMPONDING CAPACITIES (ACRE-FT.)	DIST UMN	FED R	PRV/PED	SCS A	VER/DATE
MELPG	1880	R	10	9	1939	808	N	N	N	15AUG78

REMARKS

D/S	SPILLWAY	MAXIMUM DISCHARGE (CFS)	VOLUME OF DAM (CY)	POWER CAPACITY (MW)	INSTALLED	PROPOSED	NO.	LENGTH (FT.)	WIDTH (FT.)	DEPTH (FT.)	LENGTH (FT.)	WIDTH (FT.)	DEPTH (FT.)
2	455 U	55	1050	2700									

OWNER	ENGINEERING BY	CONSTRUCTION BY
VT DLPT UP FISH + GAME		

DESIGN	CONSTRUCTION	OPERATION	MAINTENANCE
NONE	NONE	NONE	NONE

INSPECTION BY	INSPECTION DATE DAY   MO   YR	AUTHORITY FOR INSPECTION
DUFRESNE-HENRY ENG CORP	16JUN78	PL 92-367

REMARKS

**END**

**FILMED**

**8-85**

**DTIC**