



NATIONAL BUREAU OF STANDARDS MICROCOPY RESOLUTION TEST CHART

268 CONNECTICUT RIVER BASIN AD-A156 CLAREMONT, NEW HAMPSHIRE CLAREMONT PAPER COMPANY DAM NH 00139 STATE NO 47.06 PHASE I INSPECTION REPORT NATIONAL DAM INSPECTION PROGRAM JUL 0 8 1985 FILE COPY G DEPARTMENT OF THE ARMY **NEW ENGLAND DIVISION, CORPS OF ENGINEERS** WALTHAM, MASS. 02154 A TUTTE a talease; Approvi FEBRUARY 1979 Dist 85 06 12 013

61

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM	
REPORT NUMBER	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER	
NH 00139			
TITLE (and Subilile)		S. TYPE OF REPORT & PERIOD COVERED	
Claremont Paper Company Dam		INSPECTION REPORT	
ATIONAL PROGRAM FOR INSPECTION	OF NON-FEDERAL	6. PERFORMING ORG. REPORT NUMBER	
I.S. ARMY CORPS OF ENGINEERS IEW ENGLAND DIVISION		CONTRACT ON GRANT NUMBER(S)	
PERFORMING ORGANIZATION NAME AND AD	DRESS	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS	
CONTROLLING OFFICE NAME AND ADDRES	5	12. REPORT DATE	
EPT. OF THE ARMY, CORPS OF ENG	INEERS	February 1979	
EW ENGLAND DIVISION, NEDED	02254	13. NUMBER OF PAGES	
A IRAFELU RUAD, WALIHAM, MA.	ULL04 dillerent from Centrolling Office)	15. SECURITY CLASS. (of this report)	
		UNCLASSIFIED	
DISTRIBUTION STATEMENT (of the Report)	STRIBUTION UNLIMITED	UNCLASSIFIED 15. DECLASSIFICATION/DOWNGRADING SCHEDULE M Report)	
DISTRIBUTION STATEMENT (of the Report) APPROVAL FOR PUBLIC RELEASE: DI OISTRIBUTION STATEMENT (of the observed of SUPPLEMENTARY NOTES Cover program reads: Phase I In Nowever, the official title of	STRIBUTION UNLIMITED	UNCLASSIFIED 15 DECLASSIFICATION/DOWNGRADING SCHEDULE In Report) Ional Dam Inspection Program; onal Program for Inspection o	
DISTRIBUTION STATEMENT (of this Report) APPROVAL FOR PUBLIC RELEASE: DI DISTRIBUTION STATEMENT (of the observed of SUPPLEMENTARY NOTES Cover program reads: Phase I In Nowever, the official title of Non-Federal Dams; use cover da	STRIBUTION UNLIMITED	UNCLASSIFIED 15 DECLASSIFICATION/DOWNGRADING SCHEDULE m Report) ional Dam Inspection Program; onal Program for Inspection ot.	
DISTRIBUTION STATEMENT (of this Report) APPROVAL FOR PUBLIC RELEASE: DI OUSTRIBUTION STATEMENT (of the observed of Cover program reads: Phase I In nowever, the official title of Non-Federal Dams; use cover da	STRIBUTION UNLIMITED	UNCLASSIFIED 15.4. DECLASSIFICATION/DOWNGRADING SCHEDULE Market Schedule Market Schedul	
APPROVAL FOR PUBLIC RELEASE: DI APPROVAL FOR PUBLIC RELEASE: DI DISTRIBUTION STATEMENT (of the obstract of SUPPLEMENTARY NOTES Cover program reads: Phase I In however, the official title of Non-Federal Dams; use cover da KEY WORDS (Continue on reverse side if necce DAMS, INSPECTION, DAM SAFETY, Connecticut River Basin Claremont, New Hampshire, Sugar River	STRIBUTION UNLIMITED	UNCLASSIFIED 15 DECLASSIFICATION/DOWNGRADING SCHEDULE In Report) ional Dam Inspection Program; onal Program for Inspection of t.	
APPROVAL FOR PUBLIC RELEASE: DI APPROVAL FOR PUBLIC RELEASE: DI DISTRIBUTION STATEMENT (of the obstract of Supplementary notes Cover program reads: Phase I In however, the official title of Non-Federal Dams; use cover da KEY WORDS (Continue on reverse side if necession DAMS, 'INSPECTION, DAM SAFETY, Connecticut River Basin Claremont, New Hampshire Sugar River	STRIBUTION UNLIMITED micered in Block 20, different fre spection Report, Nation the program is: Nation the for date of report wary and identify by block number,	UNCLASSIFIED 15 DECLASSIFICATION/DOWNGRADING SCHEDULE ional Dam Inspection Program; onal Program for Inspection ot.	

DD FORM 1473 EDITION OF I NOV 65 IS OBSOLETE

DISCLAIMER NOTICE

THIS DOCUMENT IS BEST QUALITY PRACTICABLE. THE COPY FURNISHED TO DTIC CONTAINED A SIGNIFICANT NUMBER OF PAGES WHICH DO NOT REPRODUCE LEGIBLY.



DEPARTMENT OF THE ARMY NEW ENGLAND DIVISION, CORPS OF ENGINEERS 424 TRAPELO ROAD WALTHAM, MASSACHUSETTS 02154

FPLY TO TENTION OF: NEDED

JUN 18 1979

Honorable Hugh J. Gallen Governor of the State of New Hampshire State House Concord, New Hampshire 03301

Dear Governor Gallen:

I am forwarding to you a copy of the Claremont Paper Company Dam Phase I Inspection Report, which was prepared under the National Program for Inspection of Non-Federal Dars. This report is presented for your use and is based upon a visual inspection, a review of the past performance and a brief hydrological study of the dam. A brief assessment is included at the beginning of the report. I have approved the report and support the findings and recommendations described in Section 7 and ask that you keep me informed of the actions taken to implement them. This follow-up action is a vitally important part of this program.

A copy of this report has been forwarded to the Water Resources Board, the cooperating agency for the State of New Hampshire. In addition, a copy of the report has also been furnished the owner, Claremont Paper Mill, 131 Sullivan Street, Claremont, New Hampshire 03743.

Copies of this report will be made available to the public, upon request, by this office under the Freedom of Information Act. In the case of this report the release date will be thirty days from the date of this letter.

I wish to take this opportunity to thank you and the Water Resources Board for your cooperation in carrying out this program.

Sincerely yours,

COMM P. CHANTLER

Colonel, Corps of Engineers Division Engineer

Incl As stated

NATIONAL DAM INSPECTION PROGRAM PHASE I INSPECTION REPORT

Identification No.:NH00139Name of Dam:Claremont Paper Company DamCity:ClaremontCounty and State:Sullivan County, New HampshireRiver:Sugar RiverDate of Inspection:November 21, 1978

BRIEF ASSESSMENT

Claremont Paper Company Dam has a hydraulic height of 34 feet, is of varied topwidth, and is 145 feet.long. It is a run-of-the-river concrete gravity dam with an ogee-shaped spillway 91 feet.long. It has over-under trash and sluice gates for draining and two head gates to control industrial use. The dam spans a reach of the Sugar River and is located in west-central New Hampshire. Maximum storage capacity is about 24 acre-feet. Claremont Paper Company Dam is used for industrial process water as well as for hydroelectric purposes.' The pond ranges from 450 to 850 feet in length with a surface area of about 2 acres.

The dam is in good condition. Major concern is the amount of overtopping of the dam and spillway under test flood conditions and the effect this would have on the stability of the dam, especially the powerhouse which comprises the south abutment. Minor concerns are: inability to inspect the concrete face of the overflow spillway, the spalled concrete on the gate structure, and lack of written operational and maintenance procedures including downstream warning system in event of severe flooding or imminent dam failure.

Based on small size and high hazard classification in accordance with Corps guidelines, the test flood is ½ Probable Maximum Flood (PMF). A test flood outflow of 36,685 cfs (180 csm) would overtop the dam by about 12.5 feet (20.1 feet over spillway crest); therefore, the spillway is considered inadequate. The spillway will pass 7,245 cfs or about 20 percent of the test flood before overtopping the abutments. Because the dam is of concrete on bedrock, it would likely withstand some overtopping before damage to the dam, as evidenced by the 1936 flood when abutments were overtopped by 4 feet, with no reported ill effect. A major breach at top of dam would result in the loss of 50 or more lives and extensive property damage.

- 1 -

5 T3 1472

The owner, Claremont Paper Mill, should implement the results of the recommendations given in Section 7.2 at the July 1979 drawdown period or within two years after receipt of this Phase I inspection report. The operating and maintenance measures recommended in Subsection 7.3 a should be developed and implemented within two years after receipt of this Phase I inspection report.

ŕ

)

.

4.,

Ì

Warren A. Guinan Project Manager N.H. P.E. 2339

Accession For NTIS GRA&I DTIC TAB Unannounced Justification. By_ Distribution/ Availability Codes Avail and/or Dist Special - M

This Phase I Inspection Report or Claremont Paper Company Dam has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the <u>Recommended Guidelines for Safety Inspection of</u> <u>Dams</u>, and with good engineering judgment and practice, and is hereby submitted for approval.

WW. F FINEGAN, JR., MEMBER OSHPH W. Wager Control Branch

Ingineering Division

r

E

€--

i.

.

CARNEY M. TERZIAN, MEMBER Design Branch Engineering Division

sigh q. Mr Elroy

JOSEPH A. MCELROY, CHAIRMAN Chief, NED Materials Testing Lab. Foundations & Materials Branch Engineering Division

APPROVAL RECOMMENDED:

u as OE B. FRYAR

Chief, Engineering Division

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

 \mathbf{v}

TABLE OF CONTENTS

TitlePageLETTER OF TRANSMITTAL.BRIEF ASSESSMENT.BRIEF ASSESSMENT.VREVIEW BOARD PAGE.VPREFACE.VTABLE OF CONTENTS.viOVERVIEW PHOTO.viiLOCATION MAP.viii

REPORT

Section

1

1	PROJECT INFORMATION	1-1
	1.1 General	1-1
	1.2 Description of Project	1-1
	1.3 Pertinent Data	1 - 3
2		$\frac{1}{2}$
2		2^{-1}
	2.1 Design	2-1
	2.2 Construction	2-1
	2.3 Operation	2-1
	2.4 Evaluation	2-1
3	VISUAL INSPECTION	3-1
	3.1 Findings	3-1
	3.2 Evaluation	3-4
4	OPERATIONAL PROCEDURES	4-1
	4.2 Procedures	4-1
	4.2 Maintenance of Dam	4-1
	4.3 Maintenance of Operating Facilities	4-1
	4.4 Description of Any Warning System in Effect	4-1
	4.5 Evaluation	4-1
5	HYDROLOGIC/HYDRAULIC.	5-1
5	5.1 Evaluation of Features	5-1
6		6-1
0	1 Displantion of Structural Stability	6_1
-		0-1 7 1
/	ASSESSMENT, RECOMMENDATIONS & REMEDIAL MEASURES	7-1
	7.1 Dam Assessment	/-1
	/.2 Recommendations	/-1
	7.3 Remedial Measures	7-2
	7.4 Alternatives	7-2

APPENDICES

Designation

VISUAL INSPECTION CHECKLIST	A
ENGINEERING DATA	. В
PHOTOGRAPHS	с
HYDROLOGIC AND HYDRAULIC COMPUTATIONS	. D
INFORMATION AS CONTAINED IN THE NATIONAL INVENTORY OF D.	AMS E



Figure 1 - Overview of the Claremont Paper Company Dam.



NATIONAL DAM INSPECTION PROGRAM PHASE I INSPECTION REPORT CLAREMONT PAPER COMPANY DAM

SECTION 1 PROJECT INFORMATION

1.1 General

a. <u>Authority</u>. Public Law 92-367, August 8, 1972 authorized the Secretary of the Army, through the Corps of Engineers, to initiate a National Program of Dam Inspection throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region. Anderson-Nichols & Company, Inc. has been retained by the New England Division to inspect and report on selected dams in the State of New Hampshire. Authorization and notice to proceed were issued to Anderson-Nichols under a letter of November 20, 1978 from Max B. Scheider, Colonel, Corps of Engineers. Contract No. DACW33-79-C-0009 has been assigned by the Corps of Engineers for this work.

b. Purpose

(1) To perform technical inspection and evaluation of non-Federal dams to identify conditions which threaten the public safety and thus permit correction in a timely manner by non-Federal interests.

(2) To encourage and prepare the States to initiate quickly effective dam safety programs for non-Federal dams.

(3) To update, verify and complete the National Inventory of Dams.

1.2 Description of Project

a. Location. Claremont Paper Company Dam is located in Claremont, New Hampshire and is a run-of-the-river dam spanning the Sugar River. After discharging over the dam, the Sugar River flows northwesterly for a distance of 5 miles before becoming confluent with the Connecticut River. The Sugar River is a major tributary in the Connecticut River Basin. Claremont Paper Company Dam is shown on U.S.G.S. Quadrangle, Claremont, New Hampshire with coordinates approximately at N 43° 22' 26", W 72° 20' 48", Sullivan County, New Hampshire. (See Location Map page viii.)

Description of Dam and Appurtenances. Claremont b. Paper Company Dam is a concrete gravity dam on bedrock about 145 feet in length and about 34 feet in height. The concrete ogee spillway is 91 feet long and comprises the northern section of the dam. One timber trash gate (5' x 5') and one low-level timber sluice gate (5' x 5') are located at the southern end of the spillway. The operating mechanisms are located directly above the gates on the concrete service platform which is accessible through the powerhouse. The trash gate is mechanically operated; the low-level sluice gate is electrically operated. The southern abutment of the dam is hidden beneath the powerhouse of the Claremont Paper Company plant. Available plans indicate two timber head gates 10.5' H x 16' W. These gates are electrically operated and pass discharge into 400 KW capacity generators with vertical axis turbines for use in power generation. The plant buildings are adjacent to the powerhouse.

c. Size Classification. Small (hydraulic height - 34 feet; storage - 24 acre-feet) based on a hydraulic height and storage (≥ 25 to <40 feet and <1000 acre-feet) as given in Recommended Guidelines for Safety Inspection of Dams.

d. <u>Hazard Classification</u>. High Hazard. A major breach would probably result in the loss of 50 or more lives and extensive property damage. (See Section 5.1 f.)

e. Ownership. The Claremont Paper Company Dam was originally constructed by the Claremont Paper Company, Inc. This ownership has remained unchanged throughout the years. The Company at some unknown date changed the name to the Claremont Paper Mill (CPM). CPM presently owns, maintains, and controls the dam.

f. Operator. The current owner and operator of the Claremont Paper Company Dam is the Claremont Paper Mill, 131 Sullivan Street, Claremont, New Hampshire 03743. Phone: (603) 542-2592.

g. <u>Purpose of Dam</u>. The purpose for the construction of the dam was to create an industrial water storage for use in generating hydroelectric power as well as industrial process water. The power is utilized in the paper processing plant.

h. Design and Construction History. Little information was disclosed regarding the design and construction of the original timber-crib dam, which was the predecessor of the existing concrete dam. In 1920, a concrete dam with an ogee spillway was built to replace the timber-crib dam. The relative location between the two dams can be seen in Appendix B. The 1920 reconstruction was engineered by H.S. Ferguson

Engineers, 200 Fifth Avenue, New York. The construction was performed by Fred T. Ley & Co., Contractors, Springfield, Massachusetts. No construction records were disclosed.

i. Normal Operating Procedures. No written operational procedures were disclosed for Claremont Paper Company Dam. During the inspection members of the CPM staff stated that the reservoir is drained by means of the trash and deep sluices each summer during an annual two-week shutdown of the plant. At this time all sediment which has built up behind the dam is released into the downstream channel. This yearly opening of the gates also is a check to insure the gate operating facilities are functional.

1.3 Pertinent Data

a. Drainage Area. The drainage area consists of 252 square miles (161,280 acres) of varied terrain. Numerous storage areas are present in the upstream watershed.

b. Discharge at Damsite

(1) Outlet works (conduits) - Trash gate 5' x 5' @ invert elevation 446' msl. Gate capacity at top of dam is 420 cfs @ 457.5' MSL. Deep sluice gate 5' x 5' @ invert elevation 424.5' MSL. Gate capacity at top of dam is 775 cfs @ 457.5' MSL. Two head gates 10.5' H x 16' W @ invert elevation 434' MSL. Capacity is controlled by the turbines in the powerhouse. Turbine capacity at maximum efficiency with a head of 26 feet was reported to be 185 cfs.

(2) The maximum discharge at damsite is unknown. However, there is a U.S.G.S. gaging station on the Sugar River with a drainage area of 269 square miles. Maximum known discharge at this gage with 48 years of record is 14,000 cfs during the March 1936 flood. The estimated maximum discharge at the dam itself can be interpolated to be approximately 13,500 cfs.

(3) Ungated Spillway capacity @ top of dam -7,245 cfs @ 457.5' MSL.

(4) Ungated Spillway capacity @ test flood elevation - 31,162 cfs @ 470.0' MSL.

(5) Cated Spillway capacity @ top of dam elevation - not applicable

(6) Gated Spillway capacity @ test flood elevation - not applicable

(7) Total Spillway capacity @ test flood elevation - 31,162 cfs @ 470.0' MSL.

(8) Total project discharge @ test flood elevation -36,685 @ 470.0' MSL.

c. Elevation (ft. above MSL)

(1) Streambed at centerline of dam - 423.5 (at downstream toe)

(2) Maximum tailwater - estimated 429 from approximate March 1936 discharge.

- (3) Upstream portal invert low-level sluice 424.5
 Upstream portal invert trash gate 446
- (4) Recreation pool not applicable
- (5) Full Flood control pool not applicable
- (6) Spillway crest 449.9
- (7) Design surcharge (Original Design) unknown
- (8) Top of dam 457.5
- (9) Test flood pool 470.0

d. Reservoir (fcet)

- (1) Length of maximum pool 850
- (2) Length of pool at spillway crest 450
- (3) Length of flood control pool not applicable

e. Storage (acre-feet)

- (1) Recreation pool not applicable
- (2) Flood control pool not applicable
- (3) Spillway crest pool 8 (approximate)
- (4) Top of dam 24 (approximate)
- (5) Test flood pool 110 (approximate)

f. Reservoir Surface (acres)

- (1) Recreation pool not applicable
- (2) Flood control pool not applicable
- (3) Spillway crest 2 (approximate)
- (4) Test flood pool 4 (approximate)
- (5) Top of dam 2 (approximate)
- g. <u>Dam</u>

(1) Type - concrete gravity dam on ledge with an ogee spillway.

- (2) Length 145'
- (3) Height 34' (structural height)
- (4) Top Width varied

(5) Side Slopes - Batter of $\frac{1}{2}$ "H:12"V on upstream face (flattening to $3\frac{1}{2}$ "H:12"V near crest) and ogee downstream.

- (6) Zoning not applicable
- (7) Impervious core not applicable
- (8) Cutoff unknown
- (9) Grout curtain unknown
- h. <u>Diversion and Regulating Tunnel</u> not applicable (See j.)
- i. Spillway
 - (1) Type concrete ogee
 - (2) Length of weir 91'
 - (3) Crest elevation 449.9' MSL
 - (4) Gates none

(5) U/S Channel - The approach channel to the dam consists of the Sugar River about 70 feet in width. The banks are lined with brush and some small trees. The Main Street crossing is located about 450 feet upstream of the dam.

(6) D/S Channel - The channel immediately downstream of the dam is broader than it is at the dam itself. The valley sides are primarily of bedrock, with a thin veneer of soil and some small trees. Parts of the Claremont Paper Company plant are located at tailwater level on the left side of the valley immediately downstream of the dam. Other mills and a sluiceway are located at tailwater level on the right side of the valley. The Dartmouth Woolen Mill Dam and plant are located about 850 feet downstream of the dam. A developed area located about 1½ miles downstream of the dam contains about 20 inhabited structures including a 19-unit motel.

j. <u>Regulating Outlets</u>. A 5' x 5' trash gate is located adjacent to the south abutment of the spillway. Its invert is at elevation 446' MSL. A 5' x 5' low-level sluice is located just below the trash gate and has its invert at 424.5' MSL. Both gates are controlled by mechanisms on the concrete service bridge located above these outlets. The trash gate is mechanically operated; the low-level sluice gate has a motor operated mechanism.

Two 10.5' H x 16' W head gates at invert elevation 434' MSL are located in the power plant which contains the south abutment of the dam. These gates are both electrically operated.

SECTION 2 ENGINEERING DATA

2.1 Design

No design data were disclosed for the original timber dam. A discharge rating curve, dated April 1921 and compiled by H.S. Ferguson Engineers, was found in the files of the New Hampshire Water Resources Board (NHWRB). This apparently was the design rating curve for the concrete dam constructed in 1920. It demonstrates the differences in discharges between the old and new dams. (See Appendix B.) Obtained from the owner was a discharge curve for turbine capacity at 26 feet of head.

2.2 Construction

A plan was found in the files of the NHWRB that was compiled by H.S. Ferguson Engineers and dated March 31, 1921. This plan shows the relative location between the old timber dam and the new concrete structure. The dimensions shown on this plan conform with measurements made February 19, 1921. The original construction plans were disclosed by a member of the Claremont Paper Company staff. He stated that these plans were bought from H.S. Ferguson Engineers when they went out of business at some unknown date.

2.3 Operation

No engineering operational data were disclosed.

2.4 Evaluation

a. <u>Availability</u>. Limited engineering data were available for the Claremont Paper Company Dam. A search of the files of the NHWRB revealed only a limited amount of recorded information. The complete set of plans for the new concrete dam designed by H.S. Ferguson Engineers was obtained from a staff member of the Claremont Paper Company.

b. <u>Adequacy</u>. The final assessments and recommendations of this investigation are based on the plans of the dam obtained, the visual inspection, and the hydrologic and hydraulic calculations.

c. <u>Validity</u>. Because of the flow over the dam at the time of inspection, field measurements could not be taken to validate the reported dimensions and elevations.

SECTION 3 VISUAL INSPECTION

3.1 Findings

a. <u>General</u>. Claremont Paper Company Dam is a run-ofthe-river, low concrete dam which impounds a reservoir of small size. At the time of the inspection water was flowing over the dam so that it was not possible to inspect the condition of the concrete in the dam itself. The northwest abutment is a steeply sloping rock surface, with a short concrete retaining wall at the abutment perpendicular to the axis of the dam, and was not accessible on foot; it could be seen from the south abutment which is about 100 feet away. The south abutment is hidden from view beneath the Claremont Paper Company plant and contains the head gate intakes for use in hydroelectric power generation.

Dam. Claremont Paper Company Dam is a concrete b. gravity dam 145 feet in total length with an ogee downstream face, about 34 feet high, 28 feet wide at the base, and 91 feet long at the crest. (See Appendix C - Figure 2.) At the time of the inspection, several inches of water were flowing over the crest of the dam. (See Appendix C - Figure 3.) TO the extent that the downstream face of the dam was visible beneath the overflowing water, no obvious defects were observed in the concrete. Drawings of the dam show that the upstream face is nearly vertical, but could not be verified from the visual inspection because of the water flowing over the dam. Recent photos in the Claremont Paper files of the upstream face taken when the dam was drained do not indicate any obvious defects.

The dam is located at the downstream end of a rock gorge about 150 feet wide at reservoir level. The surface of the rock in the vicinity of the northwest abutment is estimated to slope at about 45° toward the reservoir on the basis of visual observation from the south abutment. The rock appears to be foliated and the exposed rock surface appears to have developed along the foliations. A vertical concrete wall founded on bedrock has been constructed at the northwest abutment perpendicular to the axis of the dam. The wall has a total length of 42 feet (scaled from a drawing of the dam), extending from about 10 feet downstream of the crest to about 25 feet upstream of the crest. There are four weep holes in the wall at a height of about 4 feet above the crest of the dam, as estimated by visual inspection from the south abutment. No water was

discharging from the weep holes at the time of the inspection, but staining of the concrete below the two weep holes farthest downstream indicate that water has discharged from those weep holes sometime in the past. (See Appendix C - Figure 4.) The concrete in the wall appears to be in good condition. That part of the abutment which was visible above the water surface appeared to be in good condition.

The south abutment is hidden beneath the Claremont Paper Company plant and was not accessible for visual inspection. The rock exposed in a vertical face of the valley wall a short distance upstream of the dam was observed from the dam and appears to be more massive and less foliated than the rock in the northwest abutment.

The foundation of the dam, which appears to be on rock, could not be observed because of the water in the reservoir on the upstream side of the dam and the tailwater on the downstream side of the dam. A couple of logs were lodged on the crest of the dam at the time of the inspection, but were not significantly obstructing the flow of water over the dam.

Available drawings indicate that there is a trash gate 5' x 5' in cross section, with a sill elevation 3.4 feet below the crest of the spillway. This gate was observed during the inspection. Available drawings also indicate a low-level sluice, approximately 5' x 5' with a sill elevation 25.4 feet below the crest of the spillway. This sluice could not be seen since the reservoir was full of water.

c. <u>Appurtemant Structures</u>. To the extent the appurtemant structures of the dam were visible, none exhibited any obvious defects.

Powerhouse Building. The south abutment of (1)the ogee concrete dam is the powerhouse structure, inlet gates, trash rack and wheel housings. The reinforced concrete structure extends approximately 44 feet to match the existing paper mill buildings and subsurface foundations. Available design drawings of the powerhouse indicate the upstream face to be concrete with two 16' x 10.5' head-gate openings to the powerhouse. Both gates are operated by one motor. Each gate has a belt to an extended motor shaft. The belts are in fair condition; the motor is in good condition. Plans indicate two 6' x 6' low-level gates that open to the tail race. According to plans these were to be concreted in after completion of the dam. The visual inspection could not confirm whether they still exist. The upstream face and gates could not be inspected due to the impounded water in the reservoir. Visual inspection of the interior of the powerhouse revealed

the structure to be in good condition. The powerhouse contains two 400 KW capacity generators with vertical axis turbines which were operational and in good condition. Some efflorescence was observed from a distance on the downstream face of the powerhouse building in the vicinity of the wheel pits. (See Appendix C - Figure 2.) Because of the inaccessibility, detailed close-up field inspection of the downstream face could not be accomplished.

(2) <u>Concrete Service Bridge</u>. The concrete service bridge, which supports the gate operating mechanisms for the trash gate and low-level sluice outlet, was observed to be in good condition. The support piers at the water level revealed some surface deterioration to a maximum depth of three inches. The railings appear in good condition with no evidence of significant corrosion.

The gate mechanisms were covered with ice and snow but appeared to be in good condition. (See Appendix C - Figure 5.) The trash gate is mechanically operated by a wheel. The lowlevel sluice gate is electrically operated and the motor was in good condition.

d. <u>Reservoir Area</u>. Claremont Paper Company Dam and its reservoir are located in the middle of the City of Claremont. The drainage area above the dam is rolling, and is generally forested, except for the area in the City of Claremont itself and in the broad valley bottom and some of the flatter adjacent slopes for a distance of a few miles upstream from Claremont. About 450 feet upstream of the dam is the Main Street crossing. (See Appendix C - Figure 6.)

Members of the Claremont Paper Company staff stated at the time of the inspection that the reservoir is drained each summer during an annual two-week vacation shutdown of the plant. The purpose of draining the reservoir is to wash away silt that collects behind the dam. Photos in the Claremont Paper Company files show the reservoir area when the water behind the dam is drained. The photos show the remnants of an old, low timber dam which was the predecessor of the present dam and it is located immediately upstream of the present dam.

e. <u>Downstream Channel</u>. The channel immediately downstream of the dam is broader than it is at the dam itself. The valley sides are primarily bedrock, with a thin veneer of soil and some small trees. (See Appendix C - Figure 7.) Parts of the Claremont Paper Company plant are located at tailwater level on the south side of the valley immediately downstream of the dam. Other mills and a sluiceway are located at tailwater level on the north side of the valley immediately downstream of the dam. The channel itself is wide and unobstructed.

3.2 Evaluation

0

Based on the visual inspection, the Claremont Paper Company Dam appears to be in good condition.

To the extent that it was visible beneath the overflowing water, the concrete dam itself exhibited no obvious defects and appeared to be in good condition. This tentative evaluation should be verified by an inspection of the dam during one of the annxal drawdowns of the reservoir.

The northwest abutment, to the extent that it is visible above the water flowing over the dam, also appears to be in good condition.

The south abutment is hidden from view beneath the Claremont Paper Company Plant, but there was no external visual evidence to indicate any problems with that abutment.

Some concrete spalling was observed around the gate structures at the south end of the dam and some efflorescence was observed on downstream face of the power house. The spalling and efflorescence do not pose any immediate problems, but should be repaired as part of the routine maintenance program. SECTION 4 OPERATIONAL PROCEDURES

4.1 Procedures

No written operational procedures were disclosed for Claremont Paper Company Dam. The discharge is utilized for power generation for use in the paper processing when sufficient discharges over the dam occur. Each summer, during the annual two-week shutdown of the plant, the reservoir is drained. This allows all accumulated sediment built up behind the dam to be released into the downstream channel. This also enables the testing of the gate operating facilities.

4.2 Maintenance of Dam

Claremont Paper Mill (CPM) is responsible for the maintenance of Claremont Paper Company Dam.

4.3 Maintenance of Operating Facilities

The annual releasing of the sediment through the trash and low-level sluice enables the testing of the operating facilities to insure that they are functional. No formal maintenance program was disclosed.

4.4 Description of Any Warning System in Effect

No written warning system was disclosed for Claremont Paper Company Dam. However, during times of high flow, sandbagging is done to protect generators. The waste and trash gates are opened to pass the maximum discharge.

4.5 Evaluation

The owner should establish a written operation and maintenance procedure as well as establishing a warning system to follow in the event of floodflow conditions or imminent dam failure.

SECTION 5 HYDROLOGIC/HYDRAULIC

5.1 Evaluation of Features

a. <u>General</u>. Claremont Paper Company Dam is a run-ofthe-river, low concrete gravity dam which impounds a reservoir of small size. The total length of the dam is 145 feet of which 91 feet consists of an ogee spillway. The dam has 7.6 feet of freeboard available before overtopping would occur. Because the dam is of concrete on bedrock it would likely withstand some overtopping before damage to the dam as evidenced by the 1936 flood when abutments were overtopped by 4 feet.

b. <u>Design Data</u>. The only hydrologic and hydraulic design data disclosed was a rating curve comparing the old and the new dam. This curve was calculated by H.S. Ferguson, Engineers in April 1921.

c. Experience Data. In a New Hampshire Water Resources Board (NHWRB) inspection report of September 14, 1938, it was reported that in 1927 about 2 feet of water was flowing over the abutments. It also stated that in the flood of 1936, approximately 4 feet of water was flowing over the abutments. During the 1936 flood the plant was shut down due to flooding from backup of high tailwater. The motors had to be removed from the basement level of the plant.

d. <u>Visual Observations</u>. At the time of inspection, no visual evidence was noted of damage to any portions of the concrete structure caused by excessive discharges.

e. <u>Test Flood Analysis</u>. Claremont Paper Company Dam is classified as being small in size having a height of 34 feet and a maximum storage capacity of 24 acre-feet; the dam was determined to have a High Hazard classification. Using the Recommended Guidelines for Safety Inspection of Dams, the test flood was determined to be ½ PMF.

Using the ½ PMF, the test flood discharge was determined to be 36,685 cfs. The overtopping analysis indicates that the dam would be overtopped by 12.5 feet during the test flood. The maximum spillway capacity at top of dam is 7,245 cfs which is only 20 percent of the test flood discharge. However, because the spillway presently spans the entire width of the river, enlarging the spillway is not a viable alternative. As stated previously, because the dam is concrete on bedrock it would likely withstand considerable overtopping before damage would result.

f. Dam Failure Analysis. The impact of failure of the dam at normal flow conditions and at top of dam were assessed using the Guidance for Estimating Downstream Dam Failure Hydrographs issued by the Corps of Engineers. The analysis covered the reach extending from the dam to a developed area consisting of about 20 inhabited structures including a motel with 19 units on the left bank of the Sugar River about 12 miles downstream of the dam. It was determined that a breach at top of dam would create the greater downstream hazard. A breach at top of dam would increase the stage by 4.2 feet above the already high tailwater conditions damaging the Claremont Paper Mill building, the Dartmouth Woolen Buildings, and the housing development located 1.5 miles downstream of the dam. The potential for loss of life is high (50 or more), especially if the breach occurred during peak working hours.

One should note because of the lack of storage behind the dam, that test flood flows discharging over the dam, assuming the dam did not fail, would have nearly the same effects on the downstream hazard.

ľ

SECTION 6 STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability

a. <u>Visual Observations</u>. To the extent that the downstream face of the dam was visible beneath the overflowing water, the concrete itself exhibited no obvious defects. The northwest abutment of the dam is bedrock and that part which is visible above the overflowing water appears to be in good condition. The south abutment of the dam is hidden beneath the Claremont Paper Company plant and was not accessible for visual inspection. Some of the concrete on the gate structures is spalled and some efflorescence was observed on the downstream face of the powerhouse. The spalling and efflorescence do not pose any immediate structural problems, but should be repaired as part of the routine maintenance program.

b. Design and Construction Data. Design and construction drawings by H.S. Ferguson dated 1920 are available for the powerhouse and dam. No calculations or detailed sursurface data were found. One drawing dated 1939 which shows a cross section through the centerline of the dam is also available. The numerous drawings indi ate that the dam is founded on "ledge" at a depth below the crest of the dam which varies from about 5 feet at the northwest abutment to about 29 feet near the south abutment.

c. Operating Records. The only operating record pertinent to the structural stability of the dam was provided orally by the members of the Claremont Paper Company staff, who stated that the reservoir is drained once each year for the purpose of washing downstream any silt that accumulates behind the dam.

d. <u>Post-construction Changes</u>. There is no record of any post-construction changes.

e. <u>Seismic Stability</u>. This dam is located in Seismic Zone No. 2 and in accordance with recommended Phase I guidelines does not warrant seismic analysis.

SECTION 7 ASSESSMENT, RECOMMENDATIONS & REMEDIAL MEASURES

7.1 Dam Assessment

a. <u>Condition</u>. The visual inspection indicates that Claremont Paper Company Dam is in good condition. Some spalling of the concrete in the gate structures and efflorescence on the powerhouse walls was observed. The amount of overtopping of the spillway by the test flood and its effect on the stability of the dam, especially the powerhouse section, is a major concern.

b. Adequacy of Information. The information available is such that the assessment must be based on results of the visual inspection. Since this is a run-of-the-river dam and water was flowing over the dam at the time of the inspection, it is recommended below that the assessment be verified by an inspection of the dam when the reservoir is routinely drained during the two-week summer shutdown of the Claremont Paper Company plant.

c. <u>Urgency</u>. The recommendation made in 7.2 below should be implemented during the July 1979 shutdown period or within 2 years. The operating and maintenance procedures recommended in 7.2a below should be implemented by the owner within 2 years after receipt of this Phase I report.

d. <u>Need for Additional Investigation</u>. Additional investigations required for this dam are the inspection of the concrete dam itself when the reservoir is drained and a structural stability analysis as recommended in 7.2 below.

7.2 Recommendations

The owner should engage a Registered Professional Engineer to inspect the concrete dam when the reservoir is routinely drained during the two-week shutdown of the Claremont Paper Company plant, and to evaluate further the source and potential impact of the efflorescence on the downstream face of the powerhouse. In addition, the engineer should evaluate further the structural stability of the dam under the test flood and any other critical flow conditions because of the high flow anticipated for % PMF relative to the height of the dam.

7.3 Remedial Measures

a. Operating and Maintenance Procedures

(1) Repair the spalled concrete on the gate structures.

(2) Remove the debris that lodges on the crest of the dam.

(3) Establish a surveillance and warning program to follow in the event of floodflow conditions or imminent dam failure.

(4) Establish a written operating procedure that would include opening all gates in time of flood events and generate maximum power to assist in passage of flood flows. However, when the flood elevation reaches top of dam (457.5' MSL) the head gates should be closed to stop flow to the turbines and cease power generation.

(5) Have the dam inspected by a Registered Professional Engineer once every two years.

(6) Make periodic observation of the dam (by owner or his representative) to note any changes of cinditions.

7.4 Alternatives

None.

1

APPENDIX A

ł

VISUAL INSPECTION CHECKLIST

Nover Claremont Paper Company	Dam November 21. 1978	
ROJECT Paper Company	DATE ACCOMPCT 11, 1970	
	TIME Z:00 P.M.	
	WEATHER CIOURY, COOT	
ARTY:	W.S. ELEV. <u>450.2</u> U.S. <u>423</u> DN.S.	
Warren Guinan	6 Lin Hall	
Stephen Gilman	7 Harold Wilcox (1/3/79)	
Leslie Williams	8. John Falcione (1/3/79)	
Robert Ojendyk	9	
Ronald Hirschfeld	10	
PROJECT FEATURE	INSPECTED BY REMARKS	
Hydrology/Hydraulics	W. Guinan/L. Williams	
. Structural Stability	S. Gilman	
Soils & Geology	R. Hirschfeld	•
Mechanical	J. Falcione	
Electrical	H. Wilcox	
)		40 · · · · · · · · · · · · · · · · · · ·
7		
3		
)		•
)		
	A-1	

٢

i

۰. ۲

D

Ľ

PERIODIC IN:	SPECTION CHECKLIST	· · · · · · · ·
PROJECT Claremont Paper Company	y Dam DAIL November 21, 1978	
PROJECT FEATURE Intake Channel & S	Structure NAME	
DISCIPLINE	NAME	
	·	•
AREA EVALUATED	C00017100	
OUTLET WORKS - INTAKE CHANNEL AND INTAKE STRUCTURE		
a. Approach Channel	Sugar River	
Slope Conditions	Good	
Bottom Conditions	Not visible beneath surface of	i .
Rock Slides or Falls	None apparent	l l
Log Boom	None	
Debris	Not visible	
Condition of Concrete Lining	Not visible	
Drains or Weep Holes	None apparent	
b. Intake Structure		
Condition of Concrete	Leading edges deteriorated	
Stop Logs and Slots	Not applicable	
·		

PERIODIC INSP	I CLIDIE CHECEL 150
PROJECT Claremont Paper Company I	DamUAIHNovember 21, 1978
PROJECT FEATURE <u>Control Tower</u>	NAMI
DISCIPLINE	NAMĽ
AREA EVALUATED	C0ND11104
OUTLET WORKS - CONTROL TOWLR	
a. Concrete and Structural	
General Condition	Good. Visible portions indicate only
Condition of Joints	surface erosion where in contact with water. None visible
Spalling	Minor, limited to leading edges of piers
Visible Reinforcing	None visible
Rusting or Staining of Concrete	None visible
Any Seepage or Efflorescence	None visible
Joint Alignment	Good, no apparent movement
Unusual Seepage or Leaks in Gate Chamber	None visible
Cracks	None visible
Rusting or Corrosion of Steel	None visible
b. Mechanical and Electrical	The timber trash gate is mechanically
Air Vents	appeared to be in good condition. The
Float Hells	cally operated. The motor was found to
Crane Hoist	head gates are electrically operated by
Elevator	extended motor shaft. The belts are in
Hydraulic System	condition.
Service Gates	
Emergency Gates	
Lightning Protection System	
Emergency Power System	-
Uiring and Lighting System	
	A-3

1

Ľ

1

•

•••

and see reasons Outlet Works		
		ĺ
DISCIPLINE		ن <u>ما</u>
AREA EVALUATED	CONDITION	-
OUTLET WORKS - OUTLET STRUCTURE AND OUTLET CHANNEL		Ļ
General Condition of Concrete		
Rust or Staining	See Outlet Works - Control Tower	
Spalling		ł
Erosion or Cavitation		ŕ
Visible Reinforcing		l
Any Seepage or Efflorescence		
Condition at Joints		
Drain holes	None apparent	
Channe I		<u> </u>
Loose Rock or Trees Overhanging Channel	Some overhanging trees, but channel is wide and unobstructed	
Condition of Discharge Channel	Good	-
		-

AREA EVALUATED	NAME
AREA EVALUATED	
AREA EVALUATED DUTLET NORES - SPILLMAY WERE APPROACH	
UTELT WORKS - SPILLWAY WEIR APPROACH	COUDITION
AND DISCHARGE CHANNELS	
. Approach Channel	
General Condition	Good
Loose Rock Overhanging Channel	None apparent
Trees Overhanging Channel	Some trees overhanging channel, but channel is wide and unobstructed.
Floor of Approach Channel	Not visible beneath surface of reservoir.
General Condition of Concrete	Good. Visible portions indicate general erosion of surface with loss
Rust or Staining	Staining when in contact with water
Spalling Aux Visible Reinforcing	Minor. Limited to leading edges of concrete piers and low-level outlet.
Any Seepage or Efflorescence Drain Holes	Little on downstream face of Power House. Four drain holes in retaining wall
. Discharge Channel	at northwest abutment appear to be functioning.
General Condition	Good
Loose Rock Overhanging Channel	None apparent
Trees Overhanging Channel Floor of Channel	Some overhanging trees, but channel is wide and unobstructed.
Other Obstructions	None

I

۰. ۱

_

.

Ţ

.
PERIODIC II-A PROJECT Claremont Paper Company D	am DATE November 21, 1978	
PROJECT FEATURE Service Bridge	NAME	
DISCIPLINE	NAME	
	······································	· · · ·
AREA EVALUATED	CONDITION	
OUTLET WORKS - SERVICE BRIDGE		
a. Super Structure		••••×
Bearings		
Anchor Bolts	Not applicable	
Bridge Seat	Not applicable	
Longitudinal Members	Not applicable	
Underside of Deck	Not visible	
Secondary Bracing	Not applicable	
Deck	Concrete, visible portions good condition.	
Drainage System		-
Railings	Steel painted	
Expansion Joints	None	
Paint	Good	-
b. Abutment & Piers		
General Condition of Concrete	Good	
Alignment of Abutment	Not applicable	
Approach to Bridge	Not applicable	
Condition of Seat & Backwall	Not applicable	
		-

DROIECT FEATURE Recorveir		
PROJECT FEATURE RESERVOIT	NAME IL Hangen	
	T	
AREA EVALUATED	REMARKS	Đ
Chability of Shoreline	Cood	
Sedimentation	Considerable; removed annually	
Changes in Watershed Runoff Potential	by opening flood gates in July None	
Upstream Hazards	Main Street Bridge 450' upstream of dam	•
Downstream Hazards Alert Facilities	Downstream Woolen Mill Dam and plant; 20 inhabited structures 1.5 miles d/s. None	
Hydrometeorological Gages	None	•
Operational & Maintenance Regulations	None	•
		Þ
		•
		•

i

•

Ł

.

.

•

1

.

l

•

APPENDIX B

1

ENGINEERING DATA

. . .

÷.•.

· · · · · ·

.-

NEW HAMPSHIRE WATER CONTROL COMMISSION DATA ON DAMS IN NEW HAMPSHIRE

7294

LOCATION	STATE NO.
Town	3
Stream Sales Harris	
Basin-Primary	<u>3.1.1.2 Air z</u>
Local Name	
Coordinates-Lat. 43° 401 + 12,402 : Long	1° 101 ± 3,000
GENERAL DATA	
Drainage area: Controlled	Sq. Mi.: Total
Overall length of dam103. ft.: Date of Construction	22 . Pezult
Height: Stream bed to highest elev ft.: Max. Struct	ture ft.
Cost—Dam: Reservoir	
DESCRIPTION JUNCTURE O Gen Front- Lucius Frontier	:
Waste Gates	
Туре	
Number	<u>5-5</u> ft. wide
Elevation Invert1, 5.401, 5.32	
Hoist	
Waste Gates Conduit	
Number	
Size ft.: Length ft.: Area	sq. ft,
Embankment	
Туре	
Height—Max ft.: Min	ft.
Top-Width: Elev	ft.
Slop es Upstream on Downstream	on
Length-Right of Spillway: Left of Spillwa	y
Spillway	
Materials of ConstructionCananala.	
Length-Total ft.: Net	
Height of permanent section-max	ft.
Flashboards-Type	: Height ft.
Elevation-Permanent Crest: Top	of Flashboard
Flood Capacity	cfs/sq. mi.
Abutments	
Materials:	
Freeboard: Max	
Headworks to Power Devel(See "Data on Power Development	
OWNER	
REMARKS - Log Log Bol Jon. Jon	~ ~

Tabulation By an Antonia State Date

DATA ON WATER PO	WER DEVELOPMENTS	5 IN NEW HAMPSHIRE
LOCATION		AT DAM NO
Town	: County	Sullivan
Stream		
Basin-Primary Gann R	: Se	condary
Local Name	••••	
GENERAL DATA		
Head-Max ft.: Min.	ft. : Ave.	
Date of Construction	: Use of Por	wer
Pondage	ac. ft.: Storage	ac. 1
DESCRIPTION		
Racks		
Size of Rack Opening	•••••••••••••••••••••••••••••••••••••••	
Size of Bar	: Material	
Area: Gross	Sq. FL : Net	
Head Gates		
Туре		
Number: Size	ft. high x	ft. wi
Elevation of Invert	: Total Area	a sq.
Hoist		······································
Penstock		
Number	: Material	·····
Size	: Length	
Turbines	53"	Rodnay Hunt Vertical
Number	: Makers	<u>Laríl Vaziol</u>
Rating HP. per unit	: Total Cap	acity
Max. Dement C.F.S., per unit		: Total c
Drive		
Тура		
Generator		
Number		
Make (3 3) (1-44	<u>) 7) (1-48</u> 0	<u>v)</u>
Rating KW., per unitiliam	; Total Car	pacity
Exciter		
Number	Make	
Rating-per unit	: Total Capacity	
OUTPUT-KWHRS	-	
19		
19	:: 19	
19	: 19	
19		
19	19	
OWNER 3 DEALE DEALE	, Ľ	1

B-2

Form 280

NEW HAMPSHIRE WATER RESOURCES BOARD

QUESTICINAIRE

WATER POWERS OF NEW FAITCHIED

Claremont Paper Company Claremont New Hampshire

Gentlemen:

We maintain in this office a list of the water power installations in New Hampshire. In recent months we have had several inquiries concerning the water power installations in the State and have found that our information is in some cases out of date.

We are, therefore, bringing this information up to date and request your cooperation by filling in the questionnaire below with data on your development, and return it to us in the enclosed stamped envelope.

Very truly yours, N. I Holington Richard S. Holmgren Chici Engineer

River at Claremont

RSH:GLB Encl.

Dam No. 47.06 : Location: Sugar

1. Will you please check or correct:

	Our Data	Your Corrections
Drainage Area - Sq.Mi. Head - feet Capacity Wheel - H.P. Generator - K.W.	251 ok 26 ok 330 ok 750 1000	

2. Is the power plant now in operation? Yes

3. If not, is the equipment in operable condition?

4. Is the dam in good repair? Yes

(Signed) Clarement Taples Co Que (Juty 14, 1942 Date 🗲

B-3



1 / MEN HAMPSHIRE WATER RESCURCES BOARD INVENTORY OF DAMS AND WATER POWER DEVELOPMENTS DAM 47.06 Commerticut NC. MILES BASIN 1510565 Sugar CIT PELLOUT NAME OF DAM IBPA DESCRIPTION RIVER 100 TH 4.9 D.A.SO.MI 259 NOAE FR Clareinont Paperco. TOWN OWNER 1921 in 14 LOCAL NAME Surcetord Sugar R.Haperca 192910 NN BUILT CANCROPP concrete dans built 1921 POND AREA-ACRES DRATCON, FOR HEIGHT-TOP TO BED OF STREAM-FT. 24 OVERALL LENGTH OF DAM-FT. 108 LLC.FT PERMANENT TREST ELEY U.S. 100. 4499 TAILWATER ELEY U.S. 100. 4499 CALLWATER ELEY U.S. 100. 4499 COD DAPACITY-ACRE FT. MIN. NAX. THEIGHT ABOVE LOCAL GAGE TREST-FT 100.22 73.62 SPILLWAY LENGTHS -FT 9/ PLASHBOARDS - TYFE, HEITET MAX . WASTE JATIS - NO WINTH MAX . 71. - 31. FREEBCARD-F E1 108. Mene Mene Statest SREST Statest + 2 m g 17 f + 1 16 8 29." E1. 75 Yrosiging 3, 92 3.92 1134 ANTE El 11.5 213.92 10-2000 - 936-4' over 57 ? REMARKS 17:7 Ition F 140 = a d n'aver dan trasher 2 H Dischards - 2. 14102 102 PC - 6819 **I**. turoin 2: · maines FOWER DEVELOPMENT RATED HEAD C.F.S. FERT UNITS NO. HР FULL GATE ΨW MAKE 460 -26-1000 26.5 += 17.7 1 3 cated ? Si Rodney Hunt barrentel 400 530 26 "pedrive to G.E.gen 440v 4201 1922-200-400 33 Leffel vertical direct con. USE Power For Paper Co G. Egenbach 1504 200 RAM. HSFERNISON 200 Fill IVE, N.Y. City REMARKS Primary P gale trang 4.11 dere. of courses dam. Hare Stoppingueriary Talked to Mr. Dawson, Pres. and Nr. A. Kirn, Gen Supt File with first 1475 PSC IATE_ 911-137 H+ JNS B-5

Junn Add. Wich and Wich and Clareadort K.H. Alver, Scention Alver, Sugar River Sugar River Operable Sugar River		(. (
Alver, revolution of the offer and the offer and the former and the operation of the second offer and the operation of a contract of the second and the former and the operation of the second and the second operation of the second operation of the second offer and the second operation of the second operation operation operation of the second operation operation operation operation of the second operation of the second operation operati		burn of a factor	we also in the tool of Claremont N.H.	•
Sugar River Operable V Monadnock Will Corp. Cleremont Sugar River Operable V Glaremont Waste Mrg.Co. Cleremont Sugar River Operable V. Claremont Waste Mrg.Co. Cleremont Suger River Operable V. Coy Paper Co. Cleremont Sugar River Operable V. Coy Paper Co. Cleremont Multichel Mater Torte Operable V. Joy Paper Co. Claremont Multichel Mater Torte Operable V. Jon of Claremont Claremont Multichel Mater Torte Operable V. Jon of Claremont Claremont		Location Alver, stock, tond or Lake	Carefolda Addust Articles	
Sugar River Operable 1-4 Juli Jvan Machine Co. Uleremont Sugar River Operable C. Unremont Waste Mrg.Co.Cheremont Sugar River Operable C. Orenov-Prov. Operabot Sugar River Operable (J. Joy Faper Co. Claremont Bad Tater Brook Operable (J. Coy Faper Co. Claremont Municipal Mater Borka Operable (J.) Toen of Claremont Claremont		Sugar River	Operable in Monadnock Will Corp.	Claremont
Sugar River Operable & Claremont Waste Vig.Co.Claremont Sugar River Control operable & Control Partmouth Moolan Co. Claremont Sugar River Operable // Coy Partmouth Moolan Co. Claremont Bad Tater Brook Operable // Coy Paper Co. Claremont Claremont Municipal Water Torks Operable // Fron of Claremont Claremont Claremont Lunicipal Water Torks Operable // Fron of Claremont Claremont Claremont Lunicipal Water Torks Operable // Control Claremont Cla		Sugar River	Operable 7.4 Sullivun Wachine Co.	Claremont
Suger River Suger Correction Contraction C		Sugar River	Operable 🤇 Claremont Waste Mfg.C	o.Cleremont
Sugar River Buna Siy berrtwouth Woolen Co. Claremont Sugar River Co. Claremont Bed Water Brook Operable 12/Vi Geffnoy Lumbor Co Claremont Municipal Water Works Operable 1110 From of Claremont Claremont	7	Sugar River	aperable 6 Jonnar Paper 20.	Comment
Sugar River Co. Claremont Bed Water Brook Operable 17-10 Confraoy Lumbor Co Claremont Municipal Water Works Operable 1110 From of Claremont Claremont		Sugar River	Ruins Sty Darctmouth Woolen Co.	C] ₆ remont
Bed Fater Brook Operable 12/16 Oeffnay Lumbor Co Claremont Kunicipal Water Works Operable 11.0 Toen of Claremont Claremont		Sugar River	Operable /0 floy Paper Co.	Claremont
Municipal Mater Forka Operable Will After Forka Claremont Claremont $3 2 3 $		Red Water Brook	Operable 17 ⁴ 5 Gaffnoy Lumber Co	ClaremontRPD
		Nunicipal Water Torks	Operable fills a Town of Claremont	Glaremont
				8 2 37
				-
				- - -
	•			
				•

(

B-6

Claremont (Sullivan) Page 1 #6

5

r

ť

.

Inspected July 1, 1930.

Dam owned by Claremont Paper Company. Concrete dam built in 1920. No changes since 1925. The gates and rack house are in covered housing. The apron needs some attention. Gates work mechanically 0. K. and recently repainted. Interviewed Mr. W. A. Cairn, Manager. There are a few small leaks which could be stopped. About SCO to 900 horse power. General conditions are good.

DIVI-85.

75.

47.0.

Claremont - General

CLARIMONT, Dams in

1.	Monadnock Mills C	laremont,	N.H.
2.			
3.	Sullivan Machinery Co. I-1935 D-1	409 "	
5.	Frost & Pierce	u	
、 <i>´</i>	Claremont Waste Co.		
\sim_{6}	Claremont Paper Co. Plan D-1336 i	n Folder"	
7.	Claremont Power Co.	t k	
8.	Dartmouth Woolen	18	
9	17		
10.	Jarvis Paper Mills) I-1283 Plan D	-40 "	
	Cov Paper Company)		
17.	Claremont Water Co. (I-1362)	18	
12.	1 F. Gaffney	19	
12	Town of Claremont	18	
1.1	10 //1 01 01 01 01 01 01 01 0	17	
1 -	1	19	
÷?•	t.	18	
10.		11-	
17.			

Town	No	6		Clareno	nt	No 33.	
	Data	by Law	B. .	······································	File		
0wner		arenous	Reper-Oor	sany (Clare	invant	Peper	<u>Co</u>)
River	or St	ream.	Sugar Riv	•er			·····
Public	Utili	ty No		Drainage area .	259		sq. mi.
Wheel	Сара	eity H. P	460	Primary H. 1 90% time	P. }4	11	
Type	of Co	astruction		Concrete	P	·····	
Heigh	t2	4	ft. 0	perating Head	2á	•••••••	ft.
Lengtl	bj.	08ft. Sp	oillway Length	1 (No. 1)9 1	ft. (N	lo. 2)	ft.
Would	l Failı	ire of Dam d	o Harm .	20			
Presen nu	it Con LW	lition B	Good	۱ ۲	Date G	1925 Wey 25	

B-8



DEPARTIZINT OF THE INTERICR

File To.

Vernington 33

_____ •/____

UNITE D STATES GEOLOGICAL SURVEY

REPORT ON DEVELOPED WALER POWER

1.	Name of stream on which power is located. Sugar River
2.	Location of plant:
	Town or City Claremont
3.	Location of point of diversion. Claremont
	Fifth dam above mouth of river
4.	Name and address of owner or operator claremont paper Co. Inc., -
	Claremont, N. H.
5.	Operating head, fore bay to tailrace24feet.
6.	Water wheels: Rated capacity,
	No. Kind Lake Size (total)
	1 twin Eunt-Fecomick 33" 460
7	. How many and what wheels are operated during the Juw-water const
	<u>One</u>
8	. What is the ordinary length of such low-water crasens. yaries
9	Generators: No 1 Totel Fat & capabily (15747 400. H. P
10	· See of longer 1 Peper mill
:]	+ Wissen number of cours ser ray grant range-24
1	Laboo H. P. steam
· 3	Sturen, in conversion in concernation of there as the exercise
	and a second
	B. L. Bigwood
	בובי, צוטר

33

B-10





1

NEW HAMPSHIRE

SUGAR RIVER

SCALE NOT TO SCALE







. . . .

APPENDIX C PHOTOGRAPHS

r

l•





•1

Figure 2 - Looking northeast at the downstream face of the dam and power house.



Figure 3 - Looking northwest across the concrete ogee weir from the service bridge.

C-2





Figure 5 - Looking at the gate mechanisms on the service bridge.

REPRODUCED AT GOVERNMENT EXPENSE



Figure 6 - Looking at the Main Street crossing located approximately 450 feet upstream of the dam.



Figure 7 - View of the downstream channel from the service bridge.

1

C-4

HYDROLOGIC AND HYDRAULIC COMPUTATIONS

APPENDIX D



• • • • •

1/13 HYDROLOGY HYDRAULICS 1/79 LJW <u>Claremont Paper Company Darn</u> $DA = 253 \text{ m}^2$ Size Classification - Small Hazard Classification - High Test Flood = 1/2 PMF Calculate PMF Using "Preliminary Guidance For Estimating Maximum Probable Discharges in Phase I Dam Safety Investigations, March 1978. Slope of viatershild is \$32 FT MI Because of Lake Sunapee and numerous other smaller storage areas, the Flat and Costal curve was used to determine the CEM value for PMF. DA = 253 miz a CEM value of 290 will be used to consist 2 the PME discharge. 253 mi² × 290 csm = 73,370 cfs 1/2 PMF (TEST FLOOD) = 36,685 cfs Develop a dam discharge rating curve using the weir cross Suction shows on page 4 Assumptions: * 'C= 3.8 (spillway); C= 3.0 (ab stments) Gates are closed Spillway @ Elev. 449.9' MSL (L=91') Normal Storage = 8 AC-FT DA ~ 253 mi * King & Brater Ha abook was used to determine proper 'c' values.

Triol #1 @ 449.9' MSL Spillway Crest

$$Q = 0$$
 cf:
Triol #2 @ 451.0' MSL
 $Q = 3.8 (91)(11)^{3/2}$
 $= 398 cf:
Triol #3 @ 452.0' MSL
 $Q = 3.8 (91)(21)^{3/2}$
 $= 1052 cf:
Triol #4 @ 453.0' MSL
 $Q = 3.8 (91)(21)^{3/2}$
 $= 1087 cf:$
Triol #4 @ 453.0' MSL
 $Q = 3.8 (91)(41)^{3/2}$
 $= 2871 cf:$
Triol #6 @ 456.0' MSL
 $Q = 3.9 (91)(41)^{3/2}$
 $= 5210 cf:$
Triol #6 @ 456.0' MSL
 $Q = 3.8 (91)(21)^{3/2}$
 $= 7245 cf:$
Triol #7 @ 457.5' MSL (MANINUM POOL)
 $Q = 3.8 (91)(26)^{3/2}$
 $= 7245 cf:$
Triol #8 @ 459.0' MSL
 $Q = 3.8 (91)(26)^{3/2}$
 $= 7245 cf:$
Triol #8 @ 459.0' MSL
 $Q = 3.8 (91)(26)^{3/2}$
 $= 7245 cf:$
Triol #9 @ 462.0' MSL
 $Q = 3.8 (91)(25)^{3/2}$
 $= 9493 + 9(1+39) = 9653 cf:$
Triol #9 @ 462.0' MSL
 $Q = 3.8 (91)(25)^{3/2}$
 $= 9493 + 9(1+39) = 9653 cf:$
Triol #9 @ 462.0' MSL
 $Q = 3.8 (91)(25)^{3/2}$
 $= 14555 + 472 + 51 + 556 = 15442 cf:$$$

ľ

3/13 179 I.W Trial # 10 @ 465.0'MSL Q= 3.8(91)(15.1)3/2+3.0(165)(7.5)3/2+ 3.5(1/214)(2.5)3/2+3.0(30)(5.5)3/2 = 20290 + 1017 + 59 + 1161 = 22527 cfs Trial # 11 @ 470.0' MSL $Q = 3.8(91)(20.1)^2 + 3.0(16.5)^7 = +$ 3.0(30)(10.5))/=+3.0(1/2)/2 = 31,162+2188+3062+59 = 36,471 cfs TEST FLOOD = 36,685 cfs Refer to rating surve establishs from the about trials (p. 5.) With a Q = 36,685 cfs an elevation of 470.0'MBL can be read. Spillway Creet = 449,9 'MSL Maximum Pool = 457.5' ME' the water depth over the spilling during is PMF would be about 20,1 fist The dam would be overtopped by 12.5 feat during 1/2 PMF. D-4



				5/13	0000
		Ę			8
		P A S			
			王 フ		000 X
		200	SUR		0
			U		20 97
		NON C			8U,
		arev	H H H		まし C
			2 1		2
		ā			
					0000 19/000
		wixey		149.0	
				tr	00 ⁵ Z1
		457.5		5	
				emilia	
				Ū.	000
					4
₹	2 D-6	450		<u> </u>	4 0
(75W 3	3008A 7	A, NOIT	ELEVA		● ● 4

Cloremont Paper Co. Dam - BREACH 6/13 ANALYSIS to detemine downstream hazard. Using Water Resources Data for New Hampshire and Vermont, Water Year 1976, U.S. Gedonical Survey Water. Data Report NH-V+-76-1, August 1977: Gage on Sugar River, DA = 269 mi², Mean Annual Flow = 660 cfs or 2.45 CSM. The DA = 253 mi² @ Clorement Paper Co. Dam Therefore, Mean annual flow over dam is approximately $253 \times 2.45 = 620 \text{ cfs} \text{ or } 1.4' \text{ depth over spillway (451.3 Msc)}$ $Q_{p_1} = 27 \text{ Wb} \text{ Vg} \text{ Yo}^{3/2}$ Wb = breach width g= 32.2 ft |scc2 yo = pool elev. - u/s river bed @ Claremont Paper Co. Dam: Wb=58' g = 32.7 ft(sec² 40=451.3 - 4ZA = 27.3' 424 > u/s river bed was used. Every year all sedimentation built up over the year is fluched out. This elevation corresponds to the invert of the deep 'sluice used to release sedimentation. From above equation: Q=13,910 cfs Determine Q going over dam that is not breached: Q=208 cfs Total Breach Q = 14, 118 CFS (Flow Conditions) Use a typical cross section along the downstream reach from the dame to the housing development l'anilies downstream. Develop discharge rating curve using the following Mannings Equation: Q=149 · A. R213. 5/2 n = composite 'n' value A = area of section (f+2) R = A/wp (wetted perimeter) S = clopic of reach. D-7

E

E

Length of react. - 1.5 miles = 7920 feet
Elev. @ als -02 - 432
Elev. @ and react - 364
Slope ...007
Composite in' - 0.05
The trials below refer to the dichazard
aross section about on proge II.
Trial # 1 Accure that 2'
Area tree = 2 heart (bas, + base)
= 230 ft²
WP = 100 + 40 = 140
R = Abox = 2340 + 1.64
Q =
$$\frac{1.49}{100} \cdot 230 \cdot 1.64^{3} \cdot .007^{1/2}$$

= 799 cfs
Trial # Z Assume that 5'
Area = 25 (100 + 175)
= 687.5
WP = 100 + 75 = 175
R = $\frac{687.5}{175} \cdot 3.73$
Q = $\frac{1.49}{175} \cdot 6.875 \cdot 5.93^{3} \cdot .007^{1/2}$

þ

C

7/3

Triol # 3 Acons try 10'
Area =
$$\frac{1}{210}(100+25r)$$
,
= 1750
WP = 100 + 150 = 250
R = $\frac{1}{40}e^{-175255} = 7.0$
Q = $\frac{1}{40}e^{-1750} + \frac{7}{10}e^{-7}$
= $\frac{16}{010} + \frac{7}{255} = 7.0$
Trial # 4 Asymptotic fragments:
Area = $\frac{1}{2}15(100+325)$
= 3187.5
WP = 100+225 = 325
R = $\frac{1}{40}e^{-3187.5} = 9.81$
Q = $\frac{1}{40}e^{-3187.5} = 9.81$
Q = $\frac{1}{40}e^{-3187.5} = 9.81^{2/3}$, 007%
= $\frac{36}{697} + \frac{217}{245} = 345$
Trial # 5 Assumption of a state of

i

.

t

8/3

$$Q = \frac{1.49}{.33} \cdot 3782.5 \cdot 10.96^{1/3} \cdot .0011^{1/2}$$

= 46,905 cfs

D-9

D-10

LINGING ON MORE AS LEDT .

í I.

Hor in Pour an anna an anna than anna Brea hard an than an anna that an an Srea hard an than an an that the history of the and the and the history of the and the antithe algorithm of the algorithm of the bread area the antiprime a point of the antithe and the antithe algorithm of the antithe algorithm of the antithe algorithm of the anti-

10/13

Diente was en the Internant Worker. Diente was a fifter contant. Or more lives alle be with d

D-11




Concerning and the second

C

ĺ

. . .

APPENDIX E

INFORMATION AS CONTAINED IN THE NATIONAL INVENTORY OF DAMS

	8C3 A VER/DATE 0 711AR79
	ONT DATE 5F E B 7 9 1 4 2 21 1 4
Ś	COUNDMENT NORTHIN FUNCE LONGITUDE LONGITUDE LONGITUDE LONGITUDE LONGITUDE DAY NORTHIN FUNCESTING DAY A 13.22, 417220, 811 COUNDMENT COUND
NITED STATE	Image: Second state of the se
MS IN THE U	O O PAPER CO DAM NAME NAME NAME Substance
	CLAREMUNT CLAREMUNT OPULAR NAME OPULAR NAME OPULAR NAME OPULAR NAME ANCEA OR STREAM ANCEA OR STREAM ANCEA ANCEA OR STREAM ANCEA
INVEN	0 0 0 0 0 NH 01 0 0 0 0 0 0 0 0 0 0 0 0



FILMED

8-85

DTIC

and the second s