	AD-A1	56 416	5 NAT Peg	TIONAL	PROGR T POND	AN FOR	R INSPI	ECTION	OF NO S OF E	N-FED Ngine	ERAL D Ers Na	AMS LTHAM	1/	2	
	UNCLAS	SSIFIE	ED III								F/G :	13/13	NL		
			<u>س</u> ,												
													a	;	V
,	; 2.3														
			·												



Ş

MICROCOPY RESOLUTION TEST CHART NATIONAL BUREAU OF STANDARDS-1963-A

16	
4	SACO RIVER BASIN
156	CONWAY, NEW HAMPSHIRE
	PEQUAWKET POWER
	COMPANY DAM
	NH 00322
	NHWRB NO. 52.02
	PHASE I INSPECTION REPORT
NA	TIONAL DAM INSPECTION PROGRAM
	JUL 0 9 1985
ľ	DEPARTMENT OF THE ARMY NEW ENGLAND DIVISION, CORPS OF ENGINEERS WALTHAM, MASS. 02154
÷	JUNE 1980 DISTRUCTION STATEMENT A Approved for public released Distribution Unlimited

يەنغار. د

INCLACCTETED		
SECURITY CLASSIFICATION OF THIS PAGE (When Del	Eniored)	
REPORT DOCUMENTATION	PAGE	READ INSTRUCTION BEFORE COMPLETING
I. REPORT NUMBER	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMB
NU 00322		· · ·
4. TITLE (and Subilie)		5. TYPE OF REPORT & PERIOD
Pequawket Power Company Dam		INSPECTION REPORT
NATIONAL PROGRAM FOR INSPECTION OF	NON-FEDERAL	6. PERFORMING ORG, REPORT N
7. AUTHOR(a)		8. CONTRACT OR GRANT NUMBE
U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION		
9. PERFORMING ORGANIZATION NAME AND ADDRES	\$	10. PROGRAM ELEMENT, PROJE AREA & WORK UNIT NUMBER
		12. BERGET DATE
DEPT. OF THE ARMY, CORPS OF ENGINE	ERS	June 1980
NEW ENGLAND DIVISION, NEDED		13. NUMBER OF PAGES
424 TRAPELO ROAD, WALTHAM, MA. 022	54	82
14. MONITORING AGENCY NAME & ADDRESS(11 dillor	nt from Controlling Unice)	
		UNCLASSIFIED
		ISA. DECLASSIFICATION/DOWNG
	I in Block 20, 11 discent fre	a Report)
17. DISTRIBUTION STATEMENT (of the abetract entered		
 DISTRIBUTION STATEMENT (of the observact entered SUPPLEMENTARY NOTES Cover program reads: Phase I Inspect however, the official title of the Non-Federal Dams; use cover date 	ction Report, Nati program is: Natio for date of report	onal Dam Inspection Pr onal Program for Inspec
 DISTRIBUTION STATEMENT (of the observed entered over program reads: Phase I Inspect however, the official title of the Non-Federal Dams; use cover date KEY WORDS (Continue on reverse olde 11 necessary of DAMS, INSPECTION, DAM SAFETY, 	ction Report, Nation program is: Nation for date of report	onal Dam Inspection Pr onal Program for Inspec
 DISTRIBUTION STATEMENT (of the abstract entered Cover program reads: Phase I Inspect however, the official title of the Non-Federal Dams; use cover date KEY WORDS (Continue on reverse of the H necessary of DAMS, INSPECTION, DAM SAFETY, Saco River Basin Conway, New Hampshire Pequawket 	ction Report, Nation program is: Nation for date of report	onal Dam Inspection Pr onal Program for Inspec

DD 1 JAN 73 1473 SDITION OF I NOV SE IS OBSOLETE

DISCLAIMER NOTICE

THIS DOCUMENT IS BEST QUALITY PRACTICABLE. THE COPY FURNISHED TO DTIC CONTAINED A SIGNIFICANT NUMBER OF PAGES WHICH DO NOT REPRODUCE LEGIBLY. PEQUAWKET POWER COMPANY DAM NH 00322 NHWRB 52.02

r

.

- .

.

1

.

Í.

L.

ľ

Accession For NTIS GRA&I DTIC TAB Unannounced Justification By_ Distribution/ Availability Codes Avail and/or Dist Special

ALE ALE ALE ALE ALE

SACO RIVER BASIN CONWAY, NEW HAMPSHIRE



PHASE I INSPECTION REPORT NATIONAL DAM INSPECTION PROGRAM

NATIONAL DAM INSPECTION PROGRAM PHASE I - INSPECTION REPORT BRIEF ASSESSMENT

Identification No: NH 00322

Name of Dam: Pequawket Power Company Dam

Town: Conway

r

Ι.

County and State: Carroll, New Hampshire

Stream: Pequawket Brook

Date of Inspection: June 9, 1980

The Pequawket Power Company Dam is a concrete stoplog-spillway structure located between earthen abutments. The dam is approximately 15.5 feet high from the channel bottom at the toe of the dam to the top of the training walls with an overall length of nearly 45 feet. The spillway measures about 36.8 feet between concrete training walls with a 2 feet thick concrete pier located in the center providing two openings, each about 17.4 feet long. These openings are each divided into three stoplog bays by vertical 12-inch wide I-beams which hold the stoplogs in place. These four vertical stanchion beams are each held in place by a pin at the top attaching them to the concrete service bridge. Removal of these pins would allow the stanchion beams to pivot and fall into the downstream channel, thereby providing a greater cross-sectional area available for discharge. There are no gates or other operating facilities incorporated into this dam.

The dam impounds water from Pequawket Brook and Page Randall Brook. The spillway discharge flows in a northerly direction about 0.5 miles to its confluence with the Swift River. The dam was originally constructed to generate electricity for adjoining mills, but was rebuilt to serve recreational purposes. The pond is 1.29 miles in length with a surface area of about 143 acres. The maximum storage capacity at top of dam is about 1,880 acre-feet.

As a result of the visual inspection of this facility, the dam is considered to be in FAIR condition. Major concerns are: minor seepage through the split stone wall located behind the left training wall; a longitudinal crack in the left span of the concrete service bridge; erosion of both concrete training walls at the downstream toe of the dam; and the general lack of surface erosion protection on both abutments.

This dam is classified as INTERMEDIATE in size and a SIGNIFICANT hazard structure in accordance with the recommended guidelines established by the Corps of Engineers. The test flood for this dam, therefore, ranges from one-half the

Probable Maximum Flood (1/2 PMF) to the Probable Maximum Flood (PMF). Since the dam falls on the lower end of the intermediate size range, the 1/2 PMF was utilized for this hydrologic analysis. The test flood inflow was estimated to be 18,400 cfs and resulted in a routed test flood outflow equal to 14,100 cfs which would overtop the dam crest by about 4.3 feet. The maximum spillway capacity with the water level at the dam crest and the "typical" arrangement of stoplogs (eight per bay) in place was estimated to be 1,780 cfs, or about 13 percent of the routed test flood outflow. An assumed breach with the water surface at the dam crest would cause an increase of about 1 foot in the downstream prefailure tailwater, bringing the water surface to a point approaching the sill of the restaurant supply business located near the right abutment of the dam. The potential for economic loss would exist.

It is recommended that the owner engage a qualified registered engineer to investigate the seepage through the split stone wall located behind the left training wall; investigate the longitudinal crack in the left span of the concrete service bridge; investigate the erosion of the concrete training walls at the toe of the dam; specify erosion protection for the soil abutments at both ends of the dam; and perform a detailed hydrologic-hydraulic investigation to assess further the potential of overtopping the dam and the need for and the means to increase project discharge.

The recommendations and remedial measures are described in Section 7 and should be addressed by the owner within one year after receipt of this Phase I Inspection Report.



ī

Ł

L

Kenneth M.'Stewart Project Manager N.H.P.E. 3531

S E A Consultants Inc. Rochester, New Hampshire

iii

PREFACE

2

[

1

.

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

4.

Ē

r

L.

l

The Phase I investigation does <u>not</u> include an assessment of the need for fences, gates, no-trespassing signs, repairs to existing fences and railings and other items which may be needed to minimize trespassing and provide greater security for the facility and safety to the public. An evaluation of the project for compliance with OSHA rules and regulations is also excluded.

TABLE OF CONTENTS

. . •

ľ

.

Ċ

•

Ì,

*

.

ľ

<u>Secti</u>	on		Page
Lette	er of	Transmittal	i
Brief	Asse	essment	ii
Revi	ew Bo	pard Page	iv
Prefa	ace		v
Table	e of (Contents	vii
Over	view	Photo	ix
Loca	tion 1	Мар	x
1.	PRO	JECT INFORMATION	1-1
	1.1	General	1-1
	1.2	Description of Project	1 - 1
	1.3	Pertinent Data	1-3
2.	ENG	INEERING DATA	2-1
	2.1	Design	2-1
	2.2	Construction	2-1
	2.3	Operation	2-1
	2.4	Evaluation	2-1
3.	VISU	AL INSPECTION	3-1
	3.1	Findings	3-1
	3.2	Evaluation	3-2
4.	OPE	RATIONAL AND MAINTENANCE PROCEDURES	4-1
	4.1	Operational Procedures	4-1
	4.2	Maintenance Procedures	4-1
	4.3	Evaluation	4-1

vii

Sec	tion		Page
5.	EVA	LUATION OF HYDROLOGIC/HYDRAULIC FEATURES	5-1
	5.1	General	5-1
	5.2	Design Data	5-1
	5.3	Experience Data	5-1
	5.4	Test Flood Analysis	5-1
	5.5	Dam Failure Analysis	5-1
6.	EVA	LUATION OF STRUCTURAL STABILITY	6-1
	6.1	Visual Observations	6-1
	6.2	Design and Construction Data	6-1
	6.3	Post-Construction Changes	6-2
	6.4	Seismic Stability	6-2
7.	ASS	ESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES	7-1
	7.1	Dam Assessment	7-1
	7.2	Recommendations	7-1
	7.3	Remedial Measures	7-2
	7.4	Alternatives	7-2
		APPENDICES	
AP	PENDI	X A - INSPECTION CHECKLIST	A-1
AP	PENDI	X B - ENGINEERING DATA	B-1
AP	PENDI	X C - SELECTED PHOTOGRAPHS	C-1
AP	PENDI	X D - HYDROLOGIC AND HYDRAULIC COMPUTATIONS	D-1
AP	PENDI	X E - INFORMATION AS CONTAINED IN THE NATIONAL INVENTORY OF DAMS	E-1

ſ

.

-

ł



L

.



NATIONAL DAM INSPECTION PROGRAM PHASE I INSPECTION REPORT PEQUAWKET POWER COMPANY DAM

SECTION 1 PROJECT INFORMATION

1.1 General

a. <u>Authority</u>. Public Law 92-367, August 8, 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a National Program of Dam Inspection throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region. S E A Consultants Inc. has been retained by the New England Division to inspect and report on selected dams in the state of New Hampshire. Authorization and notice to proceed were issued to S E A Consultants Inc. under a letter of November 5, 1979 from William Hodgson Jr., Colonel, Corps of Engineers. Contract No. DACW33-80-C0008 has been assigned by the Corps of Engineers for this work.

b. Purpose

(1) To perform technical inspection and evaluation of non-federal dams to identify conditions which threaten the public safety and thus permit correction in a timely manner by non-federal interests

(2) To encourage and prepare the states to initiate quickly effective dam safety programs for non-federal dams

(3) To update, verify and complete the National Inventory of Dams

1.2 Description of Project

a. Location. The Pequawket Power Company Dam is located in the town of Conway, New Hampshire at the north end of Pequawket Pond, immediately downstream of the NH Route 16 bridge (Main Street Bridge) in Conway, New Hampshire. The dam impounds water from Pequawket Brook and Page Randall Brook. The spillway discharge flows in a northerly direction approximately 0.5 miles to its confluence with the Swift River. The dam is shown on U.S.G.S. Quadrangle, Ossipee Lake, New Hampshire, with coordinates approximately at N43 58'43", W70 07'16", Carroll County, New Hampshire (See Location Plan).

b. <u>Description of Dam and Appurtenances</u>. Pequawket Power Company Dam is a concrete stoplog-spillway structure located between earthen abutments and is primarily an extension of a highway culvert. The dam is approximately 15.5 feet high from the channel bottom at the toe of the dam to the top of the training walls with an overall length of nearly 45 feet. The spillway measures about 36.8 feet between concrete training walls with a 2 feet thick concrete pier located in the center providing two openings, each about 17.4 feet long. These openings are

1-1

each divided into three stoplog bays by vertical 12-inch wide I-beams which hold the stoplogs in place. Thus, there are a total of six stoplog bays with a total effective weir length of 30.8 feet. The pier and training walls are constructed on top of a 20 feet wide concrete apron which extends the entire width of the channel bottom. The height from the top of the concrete apron to the top of the training walls is 12 feet. The downstream channel is covered with riprap which extends about 12 feet downstream from the edge of this concrete apron. A concrete service bridge, 4 feet wide and 18 inches thick, connects the pier and training walls above the stoplog bays. A split stone retaining wall runs perpendicular to the left training wall and terminates somewhere within the left earth abutment.

T

1.

c. <u>Size Classification</u>. Intermediate (height - 15.5 feet; storage - 1880 acre-feet) based on storage (greater than or equal to 1,000 acre-feet and less than 50,000 acre-feet), as given in the Recommended Guidelines for Safety Inspection of Dams.

d. <u>Hazard Classification</u>. Significant Hazard. The discharge resulting from an assumed failure of the Pequawket Power Company Dam would cause an increase of about 1 foot in the downstream prefailure tailwater, bringing the water surface to a point approaching the sill of the restaurant supply business located near the right abutment. The potential for economic loss would exist.

e. <u>Ownership</u>. The original dam was owned by the Pequawket Power Company. In 1961, ownership was transferred to the state of New Hampshire, Water Resources Board, 37 Pleasant Street, Concord, New Hampshire 03301. Telephone No. (603) 271-3406.

f. Operator. The dam is maintained and operated by the state of New Hampshire Water Resources Board, Vernon A. Knowlton, Chief Engineer, 37 Pleasant Street, Concord, New Hampshire 03301. Telephone No. (603) 271-3406.

g. <u>Purpose of Dam</u>. The dam was originally constructed to generate electricity for adjoining mills. The dam has been rebuilt and it presently serves recreational purposes.

h. Design and Construction History. It is not known when the original dam was built, but records on file at the state of New Hampshire Water Resources Board indicate that the dam washed out in 1922 and was rebuilt in 1923 as a wood "A" frame structure with split stone training walls. Extensive repairs were made to the wood members in 1952. Reconstruction of the dam in its present configuration was begun in 1969 and completed in 1970. The structure was designed by the state of New Hampshire Water Resources Board and was built by the state of New Hampshire Fish and Game Department. The design plans indicate the concrete dam is reinforced and built partially on earth and partially on the split stone remains of the previous dam that occupied this site. A set of design plans are on file at the state of New Hampshire Water Resources Board. No in-depth design calculations were found. i. <u>Normal Operating Procedures</u>. The Pequawket Power Company Dam is used for the retention of Pequawket Pond, which is used for recreational purposes. The New Hampshire Water Resource Board owns and operates the dam. The normal operating procedure is described in detail in Section 4.1a.

1.3 Pertinent Data.

a. <u>Drainage Area</u>. The drainage area above Pequawket Power Company Dam covers approximately 27.2 square miles (nearly 17,400 acres), consisting predominantly of steeply sloping terrain surrounding numerous ponds and swampy areas which drain to the dam. The topography in the drainage basin ranges from over 2,000 feet (NVGD) at White Ledge Mountain to approximately 452.5 feet (NGVD) at the base of the dam. The majority of the basin is heavily wooded and generally undeveloped. The major concentrations of development which do exist are located near the center of Conway, adjacent to Route 16 and near lakes and ponds in the area. This development consists of both year-round and seasonal housing, as well as associated commercial and industrial development.

b. <u>Discharge at Damsite</u>. Discharge at the damsite occurs over the stoplog spillway. The invert of the permanent spillway crest (top of concrete apron) is set at an elevation of 452.5 feet (NGVD). The spillway measures about 36.8 feet between the training walls, with a 2 feet thick concrete pier dividing the spillway into two 17.4 feet long sections. These sections are each divided into three stoplog bays by vertical 12-inch wide I-beams. The six stoplog bays provide a total effective weir length of 30.8 feet. The eight (8) stoplogs that were installed in each bay ("typical" stoplog arrangement) resulted in a crest elevation of 457.3 feet (NGVD) and maintain a ponding elevation of about 458 feet behind the dam. The vertical I-beams are attached to the service bridge with removable pins and the bases of these beams are set into slots in the permant concrete spillway crest. Consequently, when the pins at the top are removed the I-beams will pivot and fall into the downstream channel, thereby providing a greater cross-sectional area available for discharge.

(1) Outlet works (conduits) - N/A

(2) Maximum known flood at damsite - unknown

(3) The ungated spillway capacity with eight stoplogs in place and the water surface at the top of the dam (Elevation 464.5 feet) was estimated to be 1,780 cfs.

(4) The ungated spillway capacity with eight stoplogs in place the water surface at the test flood elevation (Elevation 468.8 feet) was estimated to be 3,420 cfs.

(5) Gated spillway capacity at normal pool elevation - N/A

(6) Gated spillway capacity at test flood elevation - N/A

(7) The total spillway capacity at the test flood elevation (Elevation 468.8 feet) with eight stoplogs in place was estimated to be 3,420 cfs.

(8) The total project discharge at the top of the dam (Elevation 464.5 feet) with eight stoplogs in place was estimated to be 1,780 cfs.

(9) The total project discharge at the test flood elevation (Elevation 468.8 feet) with eight stoplogs in place was estimated to be 14,100 cfs.

c. <u>Elevation</u> (Feet NGVD) based on an elevation 458.0 shown on U.S.G.S. quad sheet assumed to be pool elevation at top of design stoplog elevation (nine stoplogs in place).

- (1) Streambed at toe of dam 449
- (2) Bottom of cutoff unknown
- (3) Maximum tailwater unknown
- (4) Normal pool 458

T

.

t

.

L

.

.

.

- (5) Full flood control pool N/A
- (6) Spillway crest 452.5 permanent crest (top of concrete apron) 457.3 "typical" stoplog arrangement
- (7) Design surcharge (Original Design) unknown
- (8) Top of dam 464.5
- (9) Test flood surcharge 468.8
- d. Reservoir (Length in feet)
 - (1) Normal pool 6,800
 - (2) Flood control pool N/A
 - (3) Spillway crest pool 6,625
 - (4) Top of dam 7,325
 - (5) Test flood pool 7,335

1-4

ī

E

r

2

Ľ

- (1) Normal pool 290
- (2) Flood control pool N/A
- (3) Spillway crest pool 198
- (4) Top of dam 1,880
- (5) Test flood pool 3,130
- f. Reservoir Surface (acres)
 - (1) Normal pool 143
 - (2) Flood control pool N/A
 - (3) Spillway crest 122
 - (4) Test flood pool 410
 - (5) Top of dam 335

g. Dam

(1) Type - concrete stoplog spillway structure between earthen embankments

- (2) Length 45 feet
- (3) Height 15.5 feet
- (4) Top width N/A
- (5) Side Slopes upstream slope, N/A; downstream slope, 2.0V to 1.0H
- (6) Zoning unknown
- (7) Impervious Core unknown
- (8) Cutoff Reinforced concrete, depth unknown
- (9) Grout curtain none
- (10) Other none

1-5

h. Diversion and Regulating Tunnel

Not Applicable (See Section j)

- i. Spillway
 - (1) Type concrete with wood stoplogs
 - (2) Length of weir 6 stoplogs bays with effective weir length of 30.8 feet
 - (3) Crest elevation 452.5 (permanent crest, top of concrete apron) 457.3 ("typical" stoplog arrangement)
 - (4) Gates N/A

(5) U/S Channel - The channel immediately upstream from the spillway consists of a bridge opening which measures approximately 25 feet wide by 11 feet deep to the channel bottom. The sides of the bridge opening were constructed of split stone masonry with mortared joints. The bottom appeared to consist of the natural stream bed. It appears that this opening would not severily restrict the flow through the spillway. Upstream from the bridge opening the channel is wide and unobstructed. The slopes appear to be stable.

(6) D/S Channel - The spillway discharges into a natural stream channel below the dam. The bottom of the channel is covered with boulders and cobbles. Trees overhang the channel on both sides, but the channel is generally wide and unobstructed.

j. Regulating Outlets

1

(1) There are no regulating outlets.

SECTION 2 ENGINEERING DATA

2.1 Design

Ţ

E

.

A set of plans dated 1969 showing plan, elevation, and section for the reconstruction of the dam are available at the state of New Hampshire Water Resources Board. No in-depth engineering calculations, as-built drawings, or specifications were found.

2.2 Construction

No construction records are available for use in evaluating the dam. Records from the state of New Hampshire Water Resources Board indicate reconstruction of the dam began in late 1969 by the state of New Hampshire Fish and Game Department and was completed in early 1970.

2.3 Operation

No engineering operational data were found.

2.4 Evaluation

a. <u>Availability</u>. Reconstruction of the Pequawket Power Company Dam was designed by the state of New Hampshire Water Resources Board. Other than the plans described above, no additional engineering data were found to be available.

b. <u>Adequacy</u>. The lack of in-depth engineering data did not allow for a definitive review. Therefore, the adequacy of this dam could not be assessed from the standpoint of reviewing design and construction data, but is based primarily on visual inspection, past performance history and sound engineering judgment.

c. <u>Validity</u>. The field investigation indicated that the external features of the Pequawket Power Company Dam substantially agree with those shown on the furnished plans. The only apparent difference is that on the day of inspection, 4.8 feet of stoplog were in place, not 5.5 feet as shown on Sheet No. 1 "Elevation of Pier" Detail.

It should be noted that on page 3 of the plans, all changes in details and dimensions to "Elevation East Abutment", "Sidewalk Joint Detail", and "Typical Stanchion Beam" Detail encircled and labeled with the word "out" refer to details apparently removed for <u>Horn Pond Dam</u>. These details apparently continue to apply to Pequawket Power Company Dam. Visual inspection confirmed the existence of the sidewalk joint and the handrail. It was not possible to confirm the reinforcing steel configuration.

SECTION 3 VISUAL INSPECTION

3.1 Findings

Ľ

a. <u>General</u>. The Pequawket Power Company Dam impounds a pond of intermediate size. The watershed above the dam consists predominately of steeply sloping terrain surrounding numerous ponds and swampy areas which drain to the dam. The drainage basin is heavily wooded and generally undeveloped, except for the perimeter of the lakes and ponds in the area, the Route 16 corridor, and the downtown Conway area. The downstream area is predominately undeveloped.

The field inspection of Pequawket Power Company Dam was made on June 9, 1980. The inspection team consisted of personnel from S E A Consultants Inc. and Geotechnical Engineers, Inc. Inspection checklists, completed during the visual inspection, are included in Appendix A. At the time of inspection, 4.8 feet of stoplogs were in place and water was passing approximately 5 inches deep over the spillway. The pool elevation was at approximately 457.7 NGVD. The upstream face of the dam could only be inspected above this water level.

b. Dam. Pequawket Power Company Dam is a concrete stoplog spillway structure located between earthen abutments. The dam is approximately 15.5 feet high from the channel bottom at the toe of the dam to the top of the training walls with an overall length of nearly 45 feet. The spillway measures about 36.8feet between concrete training walls with a 2 feet thick concrete pier located in the center providing two openings, each about 17.4 feet long. These openings are each divided into three stoplog bays by vertical 12-inch wide I-beams which hold the stoplogs in place. Thus, there are a total of six stoplog bays with a total effective weir lengh of 30.8 feet (See Photo No. 2). The pier and training walls are constructed on top of a 20 feet wide concrete apron which extends the entire width of the channel bottom. The height from the top of the concrete apron to the top of the training walls is 12 feet. The downstream channel is covered with riprap which extends about 12 feet downstream from the edge of this concrete apron. A concrete service bridge, 4 feet wide and 18 inches thick, connects the pier and training walls above the stoplog bays (See Photo No. 3). A split stone retaining wall runs perpendicular to the left training wall and terminates somewhere within the left earth abutment (See Photo No. 4).

It appears that the training walls of the concrete stoplog-spillway were poured directly against the stone-masonry training walls at the ends of the dam that previously occupied this site. The concrete apron on the bottom of the structure appears to have been poured directly on top of concrete and stone rubble, which apparently is also the remains of the previous dam. No signs of instability of the concrete-and-stone rubble foundation or of the original stone-masonry training walls were observed at the time of the inspection.

3-1

It appears that the foundation under the concrete and split stone is soil. Minor seepage was discharging from the split stone retaining wall that runs perpendicular to the left training wall and terminates in the left abutment (See Photo No. 5).

A longitudinal crack has developed in the top of the left span of the concrete service bridge near the downstream edge. The location of this crack coincides with the location of a 10-inch I-beam embedded in the downstream edge of the service bridge (See Plans and Details in Appendix B).

Some erosion of the concrete training walls has taken place on the downstream toe of the dam where it joins the concrete apron (See Photo No. 6).

There is soil fill between the ends of the concrete stoplog-spillway structure and the abutments. At the left abutment, there has been some erosion of this fill, apparently due to runoff from an adjacent parking lot (See Photo No. 4). Brush and small trees are growing on this fill. At the right abutment, no evidence of erosion was observed, but there is little grassy vegetation to prevent erosion if the dam should be overtopped. Some brush is growing on this fill. There is a wooden building about 20 feet from the end of the concrete stoplog-spillway structure on the right abutment. The concrete foundation wall of this building comprises the right bank of the channel for a distance of about 50 feet downstream from the dam (See Photo No. 7).

There were two logs and an old tire in the water behind the stoplogs. There were five large logs on the concrete apron downstream of the stoplogs (See Photo No. 2).

c. <u>Appurtemant Structures</u>. There are no appurtemant structures incorporated into this dam.

d. <u>Reservoir Area</u>. The slopes of the reservoir appear to be stable. No evidence of significant sedimentation was observed. The approach channel to the dam is slightly constricted by the opening under the highway bridge immediately upstream of the dam, but is wide and unobstructed upstream of the bridge. There are no trees overhanging the approach channel for a distance of a few hundred feet upstream from the dam.

e. <u>Downstream Channel</u>. The bottom of the downstream channel is covered with boulders and cobbles. Trees overhang both sides of the channel, but the channel is wide and unobstructed. As noted above, there were five large logs on the spillway apron immediately downstream of the stoplogs.

3.2 Evaluation

On the basis of the results of the visual inspection, Pequawket Power Company Dam is considered to be in fair condition.

•

A longitudinal crack in the left span of the concrete service bridge coinciding with the location of a 10-inch I-beam embedded in the service bridge could result in failure of the stoplog support structure. The 10-inch I-beam anchors the top of the 12-inch wide stanchion beams which hold the stoplogs in place. Further propagation of this crack could cause failure of the I-beam embedment which would result in the failure of the stanchion beams and thus failure to support the stoplogs.

Erosion of the concrete training walls at the downstream toe of the dam, which if continued, could effect the stability of the training walls.

Some surface erosion of the soil on the downstream side of the left abutment could result in breaching through that abutment if not corrected.

The general lack of surface erosion protection on both abutments makes the abutments susceptible to erosion if the dam should be overtopped.

A minor amount of debris collected on the upstream side of the stoplogs could trap other debris and reduce the spillway capacity.

Brush and small trees growing on the left abutment and brush growing on the right abutment could cause a seepage and erosion problem as they grow larger, if a tree blows over and pulls out its roots, or if a tree dies or is cut and its roots rot.

SECTION 4 OPERATIONAL AND MAINTENANCE PROCEDURES

4.1 Operational Procedures

a. <u>General</u>. The Pequawket Power Company Dam is used for the retention of Pequawket Pond. The normal operating procedure for this dam during the summer months is to have a dam operator from the New Hampshire Water Resource Board visit the dam about 2 to 3 times per month and report gage readings back to the main office of the New Hampshire Water Resource Board in Concord. Engineers at the main office, in turn, direct any manipulation of stoplogs necessary to regulate the storage or release of water in order to maintain the seasonal pond level at elevation 457.5 feet + (NGVD).

The operating procedure for the winter months is to draw down the pond after November 1. This is accomplished by removing all stoplogs from two bays and removing two stoplogs in each of the remaining four bays. All stoplogs are replaced after spring runoff.

Emergency operating procedures consist of removing as many stoplogs as possible during flood conditions and, if the dam is threatened, pulling the four pins and allowing the stanchions supporting the stoplogs to fall into the downstream channel. Conditions that would require pulling the pins have not occurred to date.

It should be noted that, according to the operational log kept by the dam operator for the New Hampshire Water Resource Board, few, if any, visits are made to the dam by the operator between the time that stoplogs are removed in November and replaced in the spring (See Appendix B, Operational Log).

b. <u>Description of Any Warning System in Effect</u>. No written warning system exists for the dam.

4.2 Maintenance Procedures

a. <u>General</u>. The owner, the New Hampshire Resource Board, is responsible for the maintenance of the dam. The maintenance procedure for this dam is to have the dam operator visually inspect the dam while performing normal operating procedures (See Section 4.1a). As a result of these visits, dam maintenance is performed on an as-needed basis.

b. <u>Operating Facilities</u>. There are no operating facilities incorporated into this dam.

4.3 Evaluation

The current operational and maintenance procedures for the Pequawket Power Company Dam are inadequate to insure that all problems encountered can be remedied within a reasonable period of time. The owner should continue with the present operational and maintenance procedure of visiting the dam 2 to 3 times per month in the summer. In addition, the owner should perform inspections at least once a month in the winter, as well as established a warning system to follow in event of flood flow conditions or imminent dam failure.

SECTION 5 EVALUATION OF HYDROLOGIC/HYDRAULIC FEATURES

5.1 <u>General.</u> Pequawket Power Company Dam consists of a concrete stoplogspillway structure located between earthen abutments. The dam is approximately 15.5 feet high from the channel bottom at the toe of the dam to the top of the training walls with an overall length of nearly 45 feet. The spillway measures about 36.8 feet between concrete training walls with a 2 feet thick concrete pier located in the center providing two openings, each about 17.4 feet long. These openings are each divided into three stoplog bays by vertical 12-inch wide I-beams which hold the stoplogs in place. Thus, there are a total of six stoplog bays with a total effective weir length of 30.8 feet. Immediately upstream from the dam is a highway bridge opening which measures approximately 25 feet wide by 11 feet high. It appears that this culvert would not represent a severe upstream flow restriction.

The drainage area consists of predominantly steeply sloped terrain surrounding numerous ponds and swampy areas in the upper part of the basin. Consequently, stormwater deposited in the upper portions of the drainage area would be intercepted by these ponds and swampy areas before flowing to the dam. The dam is classified as intermediate in size, having a maximum storage of 1880 acre-feet.

5.2 <u>Design Data</u>. No hydrological or hydraulic design data were disclosed.

5.3 <u>Experience Data</u>. No experience data were disclosed. Maximum flood flows or elevations are unknown.

5.4 <u>Test Flood Analysis</u>. Due to the absence of detailed design and operational information, the hydrologic evaluation was performed utilizing data gathered during field inspection, watershed size and an estimated test flood determined from the Corps of Engineers guide curves. For this dam (intermediate size and significant hazard), the test flood ranges from one-half the Probable Maximum Flood (1/2 PMF) to the full Probable Maximum Flood (PMF). The 1/2 PMF was selected for the analysis since the dam falls to the lower end of the intermediate size range. The drainage area consits predominantly of steeply sloping terrain. However, since numerous ponds and swampy areas are located in the upper portions of the basin, the "rolling" curve from the Corps of Engineers set of guide curves was used to estimate the maximum probable flood peak flow rate.

Based on an estimated maximum probable flood peak flow rate of 1,350 cfs per square mile and a drainage area of 27.2 square miles, the test flood inflow was estimated to be 18,400 cfs. The test flood was routed through the reservoir in accordance with the Corps of Engineers procedure for Estimating Effect of Surcharge Storage on Maximum Probable Discharge. The reservoir water surface was assumed to be at an elevation of approximately 458 feet (NGVD) prior to the flood routing. The routed test flood outflow was estimated to be 14,100 cfs. This analysis indicated that the dam crest would be overtopped by 4.3 feet. The maximum spillway capacity with the water level at the dam crest and the "typical" arrangement of stoplogs in place (eight) was estimated to be 1,780 cfs, which is only about 13 percent of the routed test flood outflow. The maximum spillway capacity with the water level at the dam crest and stanchion beams removed was estimated to be 4,600 cfs, which is only about 33 percent of the routed test flood outflow, and the dam crest would be overtopped by 4 feet under these conditions. 5.5 <u>Dam Failure Analysis</u>. The impact of dam failure was assessed utilizing the "Rule of Thumb" Guidance for Estimating Downstream Failure Hydrographs published by the Corps of Engineers. The analysis covered a reach extending approximately 600 feet downstream. The prefailure discharge with the water surface at the dam crest is significant, so prefailure tailwater conditions were included in the hydrologic calculations and the dam failure analysis was conducted with the water surface at the dam crest. Under these conditions, it was determined that the routed dam failure discharge would significantly increase the hazard over the prefailure discharge tailwater. Based on this analysis, the Pequawket Power Company Dam has been classified as a significant hazard.

Z

L

A breach width of 17.4 feet, which is nearly 40 percent of the total length of the dam and coincides with the length of one spillway section (three stoplog bays), and a failure of height of about 12 feet were used to determine the failure discharge. This discharge, combined with flow over the unfailed portion of the spillway, yielded a total failure discharge of 2,110 cfs. Discharge just prior to an assumed breach was estimated to be about 1,780 cfs.

An assumed failure of the dam would cause an increase of about 1 foot in the downstream prefailure tailwater, bringing the water surface to a point approaching the sill of the restaurant supply business located near the right abutment of the dam. The potential for economic loss would exist. Further downstream the channel profile widens and the stage of the failure discharge reduces significantly.

SECTION 6 EVALUATION OF STRUCTURAL STABILITY

6.1 Visual Observations

The visual observations indicate the following potential structural problems:

- a. Minor seepage through the split stone wall located behind the left training wall could cause internal erosion in the abutment soil if not corrected.
- b. A longitudinal crack in the left span of the concrete service bridge coinciding with the location of a 10-inch I-beam embedded in the service bridge. This I-beam anchors the top of the 12-inch wide stanchion beams which hold the stoplogs in place. Further propagation of this crack could cause failure of the I-beam embedment which would result in the failure of the stanchion beams and thus failure to support the stoplogs.
- c. Erosion of both concrete training walls at the downstream toe of the dam which, if continued, could affect the stability of the training walls.
- d. Some surface erosion of the soil on the downstream side of the left abutment which could result in breaching through that abutment if not corrected.
- e. General lack of surface erosion protection on both abutments which makes the abutments susceptible to erosion if the dam should be overtopped.

.

f. Brush and small trees growing on the left abutment and brush growing on the right abutment which could cause a seepage and erosion problem as they grow larger if a tree blows over and pulls out its roots, or if a tree dies or is cut and its roots rot.

6.2 Design and Construction Data

No information regarding the original design or construction of the dam was found.

6.3 Post-Construction Changes

In 1969, the wood "A" frame dam, with split stone training walls, was replaced with a reinforced concrete structure. The majority of the stone which comprised the old dam was left in place and the new concrete structure was cast integrally with the existing stone.

6.4 Seismic Stability

This dam is located in Seismic Zone 2 and, in accordance with the Phase I guidelines, does not warrant seismic analysis.

SECTION 7 ASSESSMENT, RECOMMENDATIONS, AND REMEDIAL MEASURES

7.1 Dam Assessment

a. <u>Condition</u>. The visual examination indicates that Pequawket Power Company Dam is in fair condition. The major concerns with respect to the integrity of the dam are:

- (1) Minor seepage through the split stone wall located behind the left abutment
- (2) A longitudinal crack in the left span of the concrete service bridge coinciding with the location of a 10-inch I-beam embedded in the service bridge which anchors the top of stanchion beams that hold the stoplogs in place
- (3) Erosion of the concrete training walls at the toe of the dam
- (4) Surface erosion on the downstream side of the left abutment
- (5) Lack of erosion protection on both the left and right abutments which consist of soil
- (6) Brush and small trees growing on the left abutment and brush growing on the right abutment

b. <u>Adequacy of Information</u>. The information available from the visual inspection and the hydraulic computations is adequate to identify the problems mentioned in 7.2. These problems will require the attention of a registered professional engineer qualified in the design and construction of dams who will have to make additional engineering studies to design or specify remedial measures. No additional information is needed for the purposes of this Phase I investigation.

c. <u>Urgency</u>. The owner should implement the recommendations in 7.2 and 7.3 within one year after receipt of this Phase I report.

7.2 Recommendations

The owner should retain a registered professional engineer qualified in the design and construction of dams to:

(1) Investigate the seepage through the split stone wall located behind the left training wall and design remedial measures if needed.

- ۰.
- (2) Investigate the longitudinal crack in the left span of the concrete service bridge coinciding with the location of a 10-inch beam embedded in the service bridge and design remedial measures if necessary.
- (3) Investigate the erosion of the concrete training walls at the toe of the dam and specify remedial measures if necessary
- (4) Specify repairs for the erosion that has occurred on the downstream side of the left abutment
- (5) Specify erosion protection for the soil abutments at both ends of the dam
- (6) Perform a detailed hydrologic-hydraulic investigation to assess further the potential of overtopping the dam and the need for and the means to increase project discharge.

The owner should implement the recommendations made by the engineer.

7.3 Remedial Measures

E

- a. Operating and Maintenance Procedures. The owner should:
 - (1) Remove trees and brush and associated root systems from abutments
 - (2) Continue with the present dam inspections 2 to 3 times per month in the summer as well as performing inspections at least once a month in the winter
 - (3) Engage a registered professional engineer qualified in the design and construction of dams to make a comprehensive technical inspection of the dam once every year
 - (4) Establish a surveillance program for use during and immediately after periods of heavy rainfall, establish written procedures to be followed during flooding periods, and also establish a formal downstream warning program to follow in case of emergency

7.4 Alternatives

There are no practical alternatives to the recommendations of Section 7.2 and 7.3

APPENDIX A INSPECTION CHECKLIST

.

r

.

۲.

.

-

;

r

-

•

-

وحرجاجا فراجا بمراجلات

. . . .

.- `.

.

ĩ

· · ·

-

INSPECTIO	N CHECK LIST RGANIZATION
PARTY O	RGANIZATION
PROJECT:Pequawket Power Co. Dam, NH	DATE: <u>June 9, 1980</u> TIME: <u>9:45 a.m.</u> WEATHER: <u>Sunny, cool</u> W.S. ELEV. <u>457.7</u> U.S. <u>449.8</u> DN.S. (NGVD)
PARTY:	
. <u>Kenneth Stewart, S E A</u>	6.
2. Bruce Pierstorff, S E A	7
Robert Durfee, S E A	8
Philip Upton, S E A	9
5. Ronald Hirschfeld, GEI	10
PROJECT FEATURE	INSPECTED BY REMARKS
• Structural Stability	K. Stewart/R. Durfee
. Hydrology/Hydraulics	B. Pierstorff/P. Upton
Soils and Geology	R. Hirschfeld
I	
5 <u></u>	
3	
·	
3.	
)	
	A-1

. - .

F

INSPECTION	CHECK LIST
ROJECT: Pequawket_Power_CoDam, NH	DATE:
ROJECT FEATURE: Dam Embankment	NAME:
DISCIPLINE:	NAME:
AREA EVALUATED	CONDITIONS
DAM EMBANKMENT	
Crest Elevation	464.5
Current Pool Elevation	457.7
laximum Impoundment to Date	Unknown
urface Cracks	Minor hairline cracks in several concrete surfaces
Pavement Condition	Not paved
lovement or Settlement of Crest	None observed
ateral Movement	None observed
'ertical Alignment	Good
Iorizontal Alignment	Good
Condition at Abutment and at Concrete Structures	Some erosion of both concrete training walls at downstream toe
ndications of Movement of Structural tems on Slopes	None observed
respassing on Slopes	No evidence observed
egetation on Slopes	Brush and small trees on downstream side of left abutment; brush on downstream side of right abutment
Sloughing or Erosion of Slopes or Abutments	Some erosion on downstream side of left abutment
Rock Slope Protection - Riprap Failures	No riprap on slopes
Jnusual Movement or Cracking (at or near Toe	None observed
Jnusual Embankment or Downstream Seepage	Minor seepage through the split stone wall located behind the left training wall
Piping or Boils	None observed
Foundation Drainage Features	None observed
foe Drains	None observed
nstrumentation System	None observed

)); 1

.

r

(

•

۰.

:

-

A-2

PROJECT: Pequawket Power Co. Dam, NH	DATE: June 9, 1980	_
PROJECT FEATURE:	NAME:	
DISCIPLINE:	NAME:	
AREA EVALUATED	CONDITIONS	
DIKE EMBANKMENT	No Dike	
Crest Elevation		ľ
Current Pool Elevation		
Maximum Impoundment to Date		
Surface Cracks		
Pavement Condition		
Movement or Settlement of Crest		
Lateral Movement		
Vertical Alignment		
Horizontal Alignment		
Condition at Abutment and at Concrete Structures		
Indications of Movement of Structural Items on Slopes		
Trespassing on Slopes		
Vegetation on Slopes		
Sloughing or Erosion of Slopes or Abutments		
Rock Slope Protection - Riprap Failures		
Unusual Movement or Cracking at or near Toes		
Unusual Embankment or Downstream Seepage		
Piping or Boils		
Foundation Drainage Features		
Toe Drains		
Instrumentation System		

6

Ţ,

(

. .

.

INSPECTION	CHECK LIST	
PROJECT:Pequawket_Power_CoDam, NH	DATE:	
PROJECT FEATURE: Intake Channel	NAME:	
DISCIPLINE:	NAME:	
AREA EVALUATED	CONDITIONS	
OUTLET WORKS - INTAKE CHANNEL AND	No intake structure	
a. Approach Channel		
Slope Conditions		
Bottom Conditions		
Rock Slides or Falls		
Log Boom		
Debris		
Condition of Concrete Lining		
Drains or Weep Holes		
o. Intake Structure		
Condition of Concrete		
Stop Logs and Slots		

•

.

÷ •.

INSPECTIO	N CHECK LIST	
PROJECT: Pequawket Power Co. Dam, NH	DATE: June 9, 1980	<u> </u>
PROJECT FEATURE: Control Tower	NAME:	
DISCIPLINE:	NAME:	
AREA EVALUATED	CONDITIONS	
OUTLET WORKS - CONTROL TOWER	No control tower	
a. Concrete and Structural		
General Condition		
Condition of Joints		
Spalling		
Visible Reinforcing		
Rusting or Staining of Concrete		
Any Seepage or Efflorescence		
Joint Alignment		
Unusual Seepage or Leaks in Gate Chamber		
Cracks		
Rusting or Corrosion of Steel		
o. Mechanical and Electrical		
Air Vents		
Float Wells		
Crane Hoist		
Elevator		
Hydraulic System		
Service Gates		
Emergency Gates		
Lightning Protection System		
Emergency Power System		
Wiring and Lighting System		

6
INSPECTION CHE	CK LIST
PROJECT: <u>Pequawket Power Co. Dam, NH</u>	DATE:
PROJECT FEATURE: Transition and Conduit	NAME:
DISCIPLINE:	NAME:

Ľ

•

ì

1.

ľ

•.• .

ļ

•

. .

OUTLET WORKS - TRANSITION AND CONDUIT	No transition or conduit
General Condition of Concrete	
Rust or Staining on Concrete	
Spalling	
Erosion or Cavitation	
Cracking	
Alignment of Monoliths	
Alignment of Joints	
Numbering of Monoliths	

PROJECT:Pequawket Power Co. Dam, NH	DATE: June 9 1980	
PROJECT FEATURE: Outlet Structure		{
DISCIPLINE:	NAME:	
AREA EVALUATED	CONDITIONS	
OUTLET WORKS - OUTLET STRUCTURE AND OUTLET CHANNEL	No outlet structure	
General Condition of Concrete		
Rust or Staining		
Spalling		
Erosion or Cavitation		
Visible Reinforcing		
Any Seepage or Efflorescence		
Condition at Joints		
Drain holes		
Channel		
Loose Rock or Trees Overhanging Channel		
Condition of Discharge Channel		
,		
ť		

-

Ľ

•

ľ

Ì.

.

ſ

-

•

•

ROJECT:	DATE: June 9, 1980
ROJECT FEATURE:	NAME:
ISCIPLINE:	NAME:
AREA EVALUATED	CONDITIONS
UTLET WORKS - SPILLWAY WEIR, PPROACH AND DISCHARGE CHANNELS	
Approach Channel	
General Condition	Good
Loose Rock Overhanging Channel	None
Trees Overhanging Channel	None
Floor of Approach Channel	Not visible beneath water surface
Weir and Training Walls	
General Condition of Concrete	Good
Rust or Staining	None
Spalling	Some erosion of both training walls at downstream toe
Any Visible Reinforcing	None
Any Seepage or Efflorescence	None visible
Drain Holes	None observed
Discharge Channel	
General Condition	Fair
Loose Rock Overhanging Channel	None
Trees Overhanging Channel	Trees overhanging discharge channel
Floor of Channel	Boulders and cobbles
Other Obstructions	Five logs lying on spillway discharge apron
Other Comments	

D

-- '

.

. .

• •

•••

•

<u>____</u>

·

•

÷., -

INSF EC II	ON CHECK LIST
PROJECT:Pequawket_Power_Co., Dam,	NH DATE: June 9, 1980
PROJECT FEATURE: Outlet Works - Ser	vice_BridgNAME:
DISCIPLINE:	NAME:
AREA EVALUATED	CONDITIONS
OUTLET WORKS - SERVICE BRIDGE	Service bridge is concrete slab above stoplog bays
a. Super Structure	
Bearings	Not applicable. Service bridge integrally poured with training walls.
Anchor Bolts	None
Bridge Seat	Not applicable - see bearings
Longitudinal Members	Not applicable, slab is reinforced concrete
Under Side of Deck	Concrete - good condition
Secondary Bracing	None
Deck	Concrete – one longitudinal hairline crack in top surface of left span
Drainage System	None
Railings	Downstream side only
Expansion Joints	One over center pier
Paint	Railing in good condition, stanchion beams could use some paint
b. Abutment & Piers	
General Condition of Concrete	Good
Alignment of Abutment :	Good
Approach to Bridge	Good
Condition of Seat & Backwall	Good

ľ

.

.

T

ĺ

.

l

-

•

•

.

• •

, . .

APPENDIX B

.

1

.

r

ł

٠.•

· ·

•

ŧ

١.

ENGINEERING DATA

:

AVAILABLE ENGINEERING DATA

Ŧ.

A set of plans dated 1969 by the New Hampshire Water Resources Board, showing plan, elevation, and section for reconstruction of the dam were obtained from the New Hampshire Water Resources Board, Concord, New Hampshire. A copy of the dam's operational log was also obtained from the state of New Hampshire Water Resources Board. No in-depth engineering calculations, as-built drawings, or specifications were found. PAST INSPECTION REPORTS

. 1

B-2

DATE May 9, 1969

FROM Francis C. Moore

SUBJECT Pequawket Pond Dam

TO Vernon A. Knowlton

On May 6, 1969, I visited Pequawket Pond dam in the center of Conway Village. The top part of the wood spillway on the left of the sluiceway is badly disintegrated. There is some disintegration of the level section to the right of the sluiceway (12' long - 2 1/2' wide) but it does not affect level of the pond. Also, the right side does not leak appreciably as it has earth and stone fill against it.

The break on the left is between 9 and 11 feet wide and tapers down to 3' near the lower end of the sluiceway. Two A frames holding the wood facing on the left of sluiceway has disappeared or moved several feet out of line at the top of spillway. The third A-frame is not secure at the top and the downstream vertical post tips several inches downstream.

To temporarily seal the spillway, a timber 14' to 16' long across the top of spillway near the sloping face could be secured to the spillway. Vertical planking (2 layers) with joints overlapped could extend down from this heavy timber to cover the hole.

This spillway should be replaced with a concrete or stop log type spillway at the earliest possible date.

Suggested material list:

16' - 6" x 12" timber for top wholer 240 bf of 2" x 8" or 2" x 10" planking - 12'± long.

FCM/jb

ł

ſ

July 12, 1967

Mr. John Hutchins Albany New Hampshire

Dear Mr. Hutchins:

I

×.

In response to your letter regarding leakage at the outlet dam to Pequawket Pond, the Water Resources Board Operator of Dams investigated the situation on July 11, 1967.

He found that one of the lower wooden stoplogs had evidently rotted and was causing most of the leakage. A new plank was placed in the rotted area to stop the loss of water. When the water is lowered in the fall, the Board will inspect the structure to determine what repairs are needed to maintain the dam.

Thank you for informing the Water Resources Board of this problem. If you have further duestions or information on this dam, feel free to contact us any time.

B-



Very truly yours, 2

Robert W. Livingston Civil Engineer Final Report on Unauthorized Operation of the Pequawket Dam in Conway, N. H.

T

Í

Friday, June 9, 1961

Arriving at the State-owned dam on Pequawket Pond, Conway, N. H., I found that new stop logs had been placed on the dam closing the opening completely. The pond water level was 8" below the spillway crest.

I contacted Mr. Hale on the status of the repairs to the water line under the pond and he informed me that the repair work has been abandoned and a new by-pass line was being installed - eliminating the need of lowering the pond further.

Chung O. / lumez

Vernon A. Knowlton Civil Engineer



PEQUAWKET DAM, Conway, N. H.

Water surface at rear of Kennett's was 0.45' lower on 6/23/60. Water surface now is 90.04' at Kennett's. Elevation desired at Cotton's is 1.90' higher than present water surface- or 91.94' elevation; 1.45' higher than on Monday, June 20, 1960.

I

ť

1

Dam width is 40.5 feet with west abutment flaring out somewhat and straight on east abutment.

Assuming 27.4 square mile drainage area and 0.3 cfs/sq. mi. runoff, δ .2 cfs or greater would occur on the average all but possibly 7 days a year. The leakage in the dam is at least this amount and probably cannot be easily reduced much. From this information, the spillway should be cut about $1!-1\frac{1}{2}"$ as shown on accompanying plan.

NOTES ON DAM:

Dam has eight bents between 9 A-frames in 22.0 feet on the east end of the dam to the 4.7' wide sluiceway. From the sluiceway opening to the west abutment, there are five bents between 6 A-frames in 13.8 feet. One foot of water on spillway is 135 cubic feet per second or 5 cfs/sq. mi.

At the sluiceway 9^{μ} beyond line of other posts, two posts are side by side in line with other posts. On the west end of sluiceway, there are two $6^{\mu}x9^{\mu}$ posts with the downstream posts set 9^{μ} beyond line of other posts. Also a $2^{\mu}x8^{\mu}$ is scabbed to the rear post.

At third points of east section of spillway, and next to sluiceway, three one inch steel rods run diagonally and parrallel to upstream face of dam through the horizontal whaler on top of posts. There are also two steel rods on the west side of the sluiceway, one near sluiceway and one at mid point.

The sluiceway is side-planked with double 2" planks at top 2 or 3 feet with only single planking below. There is a 3" wide opening in planking on the west side above the mid point. The third vertical post from the sluiceway going west has leaned downstream \mathcal{L}^n .

There is some leakage through the planking but not really serious. At times of draught, the sluiceway should be completely shut off.

Ī

5

t

Ľ

.

Top ends of diagonal timbers that are planked are partially rotted off to the whalers on the vertical posts. Some diagonals are transfering no load to top of vertical posts. The planking, braces, whalers, vertical posts are sound. The top horizontal flooring is gone on the east end and partially gone on the west end. Conway, New Hampshire September 2, 1952

Mr. Walter G. White, Chairman Water Resources Board, State of N. H. Ossipee, New Hampshire

Dear Mr. White:

ť

X

Ċ

In accordance with your letter of August 29, 1952, and our telephone conversation this morning, enclosed please find application blank for repair of a dam at Conway.

As I told you, this work has been done. All the old uprights in the dam were removed and replaced by SxlO hemlocks. The old planks from the top to within five feet of the bottom of the dam were removed and replaced by 2xlO hemlock planks laid double.

If you need any further information, please advise.

Very truly yours,

The Pequawket Power Company

hade reas.

Form WCC. 1 7/30/37

Ţ

F

.

ť

.

K

.

7

THE STATE OF NEW HAMPSHIRE

County of	Carroll	, ss.	September	2 19 52
	PETITION I	FOR APPROVAL OF	THE CONSTRUCTION OR	
	REPAIR OF	DAM ATConv	vay, New Hampshire	
TO THE WATER (CONTROL COMMISS	ION:		
In compli a Water Contro	iance with the j ol Commission,	provisions of La	aws of 1937, c. 133, a	n Act establishing
We, <u>the Pe</u> I, (Here stat	quawket Power te name of perso	Company, of on or persons, y	Conway, N.H. a pa partnership, associati	ertnership on, corporation,
etc.)	<u> </u>		· · ·	<u></u>
struct, to mal	ke repairs to, a	a dam along, or	(cross out portion no	t applicable)
across	(Here sta	te name of strea	am or body of water)	
at a point	in Conv	vay Village o	n Route 16 in the S	Fown of Conway, N.H
	(Here give loca	ation, by distar	nce from mouth of stre	am, county
or municipal	boundary)			
in the town (s) of			

in accordance with PRELIMINARY PLANS, and SPECIFICATIONS FILED WITH THIS APPLICA-TION and made a part hereof. Form WCC. 1-p. 2 7/30/37

The purpose of the proposed construction is <u>to make necessary repairs</u> (Here briefly state use to

to dam

1

E

بې 4 which stored water is to be put)

The construction will consist of <u>putting in necessary new braces and</u> (Here give brief description of work con-

<u>supporting timbers and boards on dam, to maintain its use</u> templated including height of dam)

All land to be flowed is not owned by applicant.

Pequawket Power Company Greas

Address Conway, N. H.

Note: This application together with plans, specifications and information and data filed in connection herewith will remain on file in the office of the Water Control Commission.

June 28, 1946

Case 52.02

Pequawkett Fond Outlet, Convay, N. H.

The condition of this dam is fair. Some recent repairs have been made to the abutments. The timber " \perp " frame dam will require some new planking within a few years, - but not necessary to be done immediately.

Leonard R. Frost



NEW HAMPSHIRE WATER CONTROL COMMISSION DATA ON DAMS IN NEW HAMPSHIRE

LOCATION		STATE NO	. j
Town	: County		••••••
Stream	••••		
Basin-Primary	: Secondary		•••••••
Local Name	••••		
Coordinates-Lat	V: Long	ει <u>1</u> 2,2	· · · · · · · · · · · · · · · · · · ·
GENERAL DATA			Fil-Me-
Drainage area: Controlled	Uncontrolled	. Sq. Mi.: Total .	.27.9
Overall length of dam ft.: Date of	Construction		
Height: Stream bed to highest elev	ft.: Max. Structur	e <u>] 1 51 - 31 5</u>	11 / ft.
Cost-Dam	: Reservoir		
DESCRIPTION TRACE - Substantia	at the second second		
Waste Gates			
Туре	••••••		
Number: Size	ft. high x		ft. wide
Elevation Invert	: Total Area		sq. ft.
Hoist	•••••••		•••••••
Waste Gates Conduit			
Number Mate	erials	••••••	• • • • • • • • • • • • • • • • • • • •
Size ft.: Length	ft. : Area		sq. ft.
Embankment			
Type	••••••		
Height—Max	ft.: Min	•••••	ft.
Top-Width	: Elev		ft.
Slopes-Upstream on	: Downstream	on	
Length-Right of Spillway	: Left of Spillway		
Spillway			
Materials of Construction	••••••		
Length—Total	ft. : Net		ft.
Height of permanent section-max. 1.1	.J. ft.: Min	711	ft.
Flashboards-Type	•••••••••••••••••••••••••••••••••••••••	: Height	ft.
Elevation—Permanent Crest	: Top of	Flashboard	
Flood Capacity	cfs.:	cfs	s/sq. mi.
Abutments			
Materials:			••••••
Freeboard: Max	ft. : MinC.1	71	ft.
Headworks to Power Devel.—(See "Data on	Power Development")		
OWNER Description Down Co.			
DEMADING TO A CONTRACT DOWN		·-	
REMARKS ST JOL STLOT RADE			
	B-14		
Tabulation By	Date		

.

7204

Ω

t

X

.

NEW HAMPSHIRE WATER CONTROL COMMISSION DATA ON RESERVOIRS & PONDS IN NEW HAMPSHIRE

LOCATION			AT DAM 1	NO
Fown		County		
Stream	Lazt. Rozd. Outlat			
Basin—Primary	Seco. 2	: Secondary	Saca <u>R</u>	
Local Name		•••••		•••••••••••••••••••••••••••••••••••••••

DRAINAGE AREA

ELEVATION vs. WATER SURFACE AREA vs. VOLUME

	Point	Head Feet	Surface Area Acres	Volume Acre Ft.
 (1)	Max. Flood Height			••••••
(2)	Top of Flashboards	•••••	•••••	•••••
(3)	Permanent Crest	•••••		•••••
(4)	Normal Drawdown	•••••	<u>145</u>	•••••
(5)	Max. Drawdown	•••••	*****	•••••
(6)	Original Pond	. U.S.G.S	••••••	••••••

Base Used: Coef. to change to U.S.G.S. Base

RESERVOIR CAPACITY

	Total Volume	Useable Volume
Drawdown	ft.	ft.
Volume	ac. ft.	ac. ft.
Acre ft. per sq. m	i	••••••
Inches per sq. m	i	
USE OF WATER	Domestic- Recreation	
OWNER	uewkett Power Co	Contay I H
REMARKS		

3-	1	5	

7205

Σ

1

I

TOWN CONT	ТАУ	TOWN NO. 2	NO. 52.12
RIVER STREAM POQ	namiett Pond Outlet		
DRAINAGE		POND 121 3	
рам Туре ИДИ	Frame	FOUNDATION BUTTE	
MATERIALS OF	Tilber, Split Stone		
PURPOSE OF DAM	POWER-CONSERVATION-DOMESTIC	C-RECREATION-TRANSPORTATION-PUBLIC UT	ILITY
HEIGHTS, TOP OF DAM TO BED OF STR	EAM 14"	TOP OF DAM TO SPILLWAY CRESTS 31-71 -	4'-5"
SPILL WAYS, LENGTH DEPTHS BELOW TOP	s of DAM 40' ADOROX.		LENGTH ADDTOK. 120
FLASHBOARDS TYPE, HEIGHT ABOVE	CREST NODO		
OPERATING HEAD		TOP OF FLASHBOARDS	
CREST TO N. T. W.		TO N. T. W.	
WHEELS, NUMBER			
KINDS & H. P.	······		
GENERATORS, NUMB	ER		
KINDS&K.W			
100 P.C. FFF		100 P. C. EFF	
PEFERENCES CASES	······································		
PLANS, INSPECTIONS			
REMARKE			

CONDITION - Fair

LENACE - Yes. Will be subject to periodic inspection.

To the Public Service Commission:

The foregoing memorandum on the above dam is submitted covering inspection made July 14, 1936, according to notification to owner dated June 29, 1936, and bill for same is enclosed.

D. Naldo White Chief Engineer Form EIA 34-2

July 23, 1926 Copy to Owner



OPERATIONAL LOG

D

ï

Ľ

.

.

i

PEQUAKET POND DAM

._____

E

FULL LAKE 7.00 FT. MEASURED ON MPSTREAM SIDE OF MIDDLE PIER. ELoys Par Bay. & Bays acress = 48 Lags Total. STOPS 4 x 7 x 5 11"

PEQUAWKET POND DAM DATA

Dam purchased on May 4, 1961 for \$1.00 by the New Hampshire Water Resources Board. No major repairs needed as the crest had been rebuilt by the previous owners. Upstream storage at Davis Pond - 28 Acres Upper Pequawket Pond - 14 Acres Little Pea Porridge Pond - 4 Acres Middle Pea Porridge Pond - 43 Acres Pea Porride Pond - 114 Acres All natural storage ponds - (total 231 acres) Pequawket Pond Area = 143 acres " drainage area = 27.4 sq. miles :9 Total drawdown = 5.791 + Spillway length = 40.5' Stoplog width = 4.7! Freeboard = 5.5^{1} Total estimated storage to full pond = 550 acre feet 15 year frequency flood = 1,060 cfs 100 " $" = 2,590 \, cfs$ Spilway capacity = 1,730 cfs 1" from total drainage area raises pond 18 inches (assuming upstream storage holds its share)

Flow over spillway (stoplogs in)

6"	-	47	cfs
12"	-	133	cfs
18"	-	245	cfs
24"		376	cfs
36"	-	692	cfs
<u>18"</u>	-	1064	cfs

Ĩ

Incresses by Sluiceway discharges

Depth of stoplogs out at no flow over spillway

.2"	-	16 cfs
24"	-	45 cfs
36"	-	82 cfs

Depth of stoplogs out at 12" flow over spillway

12"	-	39 cfs
24"	-	68 cfs
36"	-	95 cfs

Bearts = 2 x8 x6 (Stang cut)



B-20

FILE C1. 2. PROJECT NEW HANDSHIDT WATER RESOURCES ACC...... SUBJECT BOACD CONCORD N 1: CONT. CONT. SUMMARY FROM ACC..... ON ACC.... ON ACC..... COMPUTOR. 11/3/61-Pulled 5 stopless. Water 3" over Spillary. 18th lost three boards downstream (2 mbank) Water Ell over Spilla of. Foomach flow 2.62 to put in beauter . Rother & Brand and and the to the the با تدخر المركبة الأحرج and the second second 🖉 an shi na mar 🖉 🛨 shi sa Const Platent O the states of the second 11 200 Carton Salta and Cliffer Con Con 01 Water 14" out in the Parton of the Staff of -1-1-5-. . . . Water even with super Spillway, Pulles 11-20-52 one Beard (South R. C. Put in 5 boards - 20ut that were 5-17-62 removed by understand personnel. Water approx. 14" below spillway & Spilling Fluggin Ferfish Flowage, Talket with M. Love Joy of Commay Jus Agency, about his field being unable to droin. Insk 6-4-63 Put in 31/2 Boards to bring opening up to crost of spillway. Water 2" over spillway. Cleaned debris off dam. Water just over spilling; Checked complaint on closing off stream in cometary by the town. 7-4-63 Water just over spillway. MSK Pulled to boards - Waser 1/4" over spillwar 10-24-63 MER prise to removal. Water 1' below spillway. Approx. 4' through 3-4-64 MER. board section. Pulled large log out of stoplag section of 5-6-64 put in 4 boards - (4 out) Water 6" below spillway crest. Cleaned at her debris from MCK Qrea. 5-20-64 Pulled log from stoplog section & cleaned debris from Spillway. B-21 Water 5" over Spillway. Could not put in last 4 boards yet. MG.K

PROJECT. NEL - Y SHOE SUBJECT. Kequawket Kond ATES - ESCURCES BOARD CONCORD, N. H. COMPUTOR Spilling Notes Dete Name Put in 4 boards - Water 3" below spillway reak 6-1-64 Mr. Frost checked dum - O.K. MER. 7-6-64 7-31-64 Water just over sp. 11way - O.K. VAK. VA.K. 8-26 64 Water 1.5" Over 3pilling Water even with top of spillway - Pulled 6 beards 11-6-64 Me, Water approx. 2' below top of spillway - no obstructions me 1-22-65 5-7.65 Put in 6 boards - Cleaned logs and debris out of stoplog . برج ميز section. Water drizzling over spillway. "Buz" Coleman called & requested early drow down for shore 10-20-65 Work. Pulled 6 boards . Lor 3 left - +1" over crest. NER 5--19-66 1/2 feet below crest. Put in 10 beards . dami free of debris. . يىر چېم - Pond was drawn down at request of fown to Lobor Day La lay water line of than refilled - memo. + 2" over crest, pulled " boards & cleaned delivis 11-1-66 MEK off clam, 5 31-1-Matter found that & Weir RUL PUT IN 7 BOARDS WATER + 18 18 BELOW ADE THE BOARDS hc 6-8-67 2 NO BO ARD FROM BOTTOM BROKEN REPLACED (SOME LEAKAGE) IS CFS) MC 7-11-67 nc 8-2-67 EVEN WITH SPILL Street. 5-16-19 Replaced top two Slop loas ove 7- one 4 PULLED OUT THE 6, BOARDS D.K. FIR WINTER - 48 TO BOARS 11-1-67 HC Water forming through spillings ř.Ľ 2-17-63 There is stoplag area toplay to put in logs Ly H. 4-4-62 -2.0 BELOW SPILL ALL GARDS INT ADULD NIT FUT IN BATTOM PUT IN ALL BOARDS (12) GUNDER WATER GOUT DE WATER 5-7-2 14 5-15--2.4 MC 4"± · . - -7-7-67 dier schlass has concerned = stand on school state 1:"1 · ^ . . ^ š./.. Replaced 3 Stuplogs-9-12-68 1.H-J -1.25 Below Spillway allstopplags IN 10-4-68 K. H.S L.A.S. 11-7-68 +0.20' CULY VIII FENCE FENCE N NOW FILED 12-13-65 - 6 . 7 PULLED OUT ISTOP NOW & OUT SET FOR WINTER LJ MC 4-23-69 + srmore Top planks each side of stoplag section out. Amout - 1-Z. C. M. 2 Sown on right for 13' & flown on 125+ for t' 5-6-64 Wecked condition of dan & made report of damage. \mathcal{F} . C. -0.7 Stype - Kin + this Term -

. 94035 Dref FILE PROUED NEW HAMPSHIDE Fequal Ket Lake WATER RESOURCES SUBJECT 6 BAYS ACC. + 17. O BELIN CENTER FIER FULL LAN. BOARD - CENFER CONCORD. N. H. PIER SUMMARY PIT IN 47 Logs Not hel ends + Tratened Scien Eyes. 5-2-70 <u>2</u>3" oEmsTer. 2 LOOD IN THE ALL LAND 6-1-70 LARGE QUANTILY DEDEBRIS NESTRICTING FLOW REMOVED 5" + 43LOGS FROM CTR. BAYS & MOST OF DEBRIS EXCEPT FOR 3 LARGE LOGS UN THE UPSTNERIA CH TOP OF STOPLOS BAY 1 126 LEFT MOTE TO MAS BRITCHIE SALMMONE DAINE THAT RAND WILL RECEDE. -7"51N S - 5 PULLEDIS OF A TOPS IN TOP RON, PUT IN IS SAND 3 8-14 -6FT 11 inc - 6.75 Leveled Stop Log house. Instaled Locking Devices 9-2-10 LIN Removed Large Log From 2 Bay んさい 7-4-70 5°over 2 bugs F.(17, 10-5-70 -6.68 Took out 3 Logs Exon 3 Bay (making 4 Logs outor Thiskey) LT. 10-7-20 -7.35 Took out 3 Logs From 2 Bay (making 7 Logs OUT) イコル 4 tays have stops 26 "ontof weeking, I with 181/2" out of under. To Him How & Cin 11-7-70 - 8.3 LA Pulled Last Bay Down To one Log 3-25-71 -8.9 15~ Femorel 2 Logs From bays. 2 Large Logs cough TENDen LJ 4-30-71-7.1 level is - 2. B' below fall pand. All stops in - Minor ushagely L.J.M. 5-25-71 -23 إرار 1-5-71 -3.0 13'4 + OI OWER Stop Logs (Lors of TRASH) In JUNE 8,71 7/7/71 . -7.9 " Contor stops in both bays out. Fi + 0.2 There are many 10gs in font dover south section, including tires, debris, etc., Level, 0.3' below Cull pond 7/18/71 RY., cur w/ stopces of center hugs, only I legout cadiby in Southly 2 stop logs have no locking black, Northous the Kenter on Shaff Lite about - Called Forther to high wohr any last C/ Par <u>ن</u> مرمز PULLED OUT (2) STOPS (4) OUT IN BOX CUT BRUSH - 6.7 8/16 Mi - 15 BELOW 3 PAYS (+5.45) , CLEANED DEORIS 1-22 0,11 - 4.7 0 V 27 3 31945 11-1 -6.6 PULLED (4) OUT IN 2 BAYS (1)OUT IN 2 BAYS (1)) IN BOX NC 1-10 n (7) v ~ ^ 2 BAYS HAVE 2 IN MC @ Pier - 9.7 - 3.7 FT. BELOW FALL POND IN I BAY 11- 11 U.M.K. 32 IN BOX PULLER 6) 2 BAX HAVE I IN 4 IN IN 1 CAY - 16, 1-6-MC + 0.05 or LOGS IN 2 BAYS COFFER DAM HAS SHALLOW (SFT) OPEN ING 2-25 MC J-10-12-10.5 Audley To Back out of Lite Ky- 3-12-12 エティ PUT IN ALL LOGS (FOR COLEMAN) 5-26 ハこ 5-33 - 6.75 PULLED 9 LIGS IN 3 BAYS M 2 Put IN 9 Kogs (all IV) Removed / Karge + 15mall Kogs From Bay urea (Trash Logs) イーエークシー フ.0 トヨ 6-14-72 - 6.55 +0.5 OVER Bonads 27-

PE DI-WKET

-10.50

135**.** 135. 1.27.21 6199 F 🔊 i feas 200 cought in 200 Bal - f2- 8132 2 Kegs Eron 4/ The Bay area PULLES LOSS I BAY HASTING DO-HER HAS Y OUT MO TWO BAYS HAVE 12 IN ONE B HASIG & STHERS 84 NC - 15- 9: -7.9 OK 1-4:3-9.25 OK ----- 2.2.2 1-1 5-36 2-1 - - -5-113-8-7 Clarced 2 Small Logs The E ware In Low Bay 231 -B.4 Concertain a loss than a last, that the the the Jours have been a longer light 6-1-73 -6.45 FUT = N 3 Logs. All Log in New. Cleared much Trash - Some Small Loss Lot 7-1-73 -485 cleared lats of 6-19 French log forces for Roc MARTICA under of centre pice dupped 0.5 7-2 -5.1 PILLED 5 LIGS CLEARES TIMPLES (NOT ALL) M2 Hi Bay 7-2-3-1 TIMARAO & EANT 15-7-11-25 -6. 6 large Log is one hay & Raft is musther, there is fijzy A horige to dural caret the sutree hangth of the 13 side a Userten (the cide) in 7-10 -7.1 PUT MY ALL AND LABORADES DE TO PARTILAPSE LADS OF ME 212 -6. 7 cland detre + 2.5 over Lags. col Gruch By Stop Leg Bad مرتق نه 3-21 - 6.5 ILEARED DERRICHAW A PAA DEFAD- ALL LOSS IN 12 91-2-695 ______X J ... 9-5-1 - C. 85 PULLEX / Log ______ 2-20 12- 2.2 10-0 3-20 Pula Edora Claund / Eng Kog + much Debrit LE 10-17-73 -7.5 Z. BALS STICLIN STATUS 1-1-6.** 1-12 3 11 - FRI Fund Bland BE Carpen - Frankery 1.01 - ____ in a mate in the to ge and the day in the 3 = 26 Falle 2 4 2 2 (2 Cars and to and tay) 13:--2.3 MEARED LET A BOLE A DADAL ن بد. 79-7.3 15-7.8 んこう B-24

PE SCALET

- 7 - 1 - 5 condu DATER PIER 55.5 51.425 5 - 7 -6-13-14 Other Borberia Carro Port - Kont 5-1-14 -6.5 1 login 1 bay; railwals paint, low needs roots 6-12-14 -6.5 1 login 1 bay; railwals paint, low needs rooting & creater 6-12-14 -6.5 Cleans Long railwals paint, low needs rooting & creater 6-12-14 -6.5 Cleans Long Failwals paint, low needs rooting & creater AUTIN 34005 BACINLOW ENVISTON 1,1,50 1=n. Pry L.T.r. 53.5-34-70 Put in 4Loss (All Vin Now) Fut an Accounted Lag Boxs in The Roofing Paper んマー 7-1-74 - Clear A Trach ~ 5:5 - The Halfer Bor mande pair _____ 1-7.2 S 1.15 -69 LEGATE DEBRIS -2 ? m 9-17-14 - 7.0 Clearel Debris from Stop ショー 10-4-74-6.8 Pulled 2 Logs (1 Exoseach conter Bay) LIM 10-6-14-7.1 LIM 10-14-28- 2.25 0154 DESCIS んちん 11-6 -7.1 PULLED & LOFE DE EACH DELTER BAYS ALL MILES BARS / EACH Y 1 - 24-23 Prile & Kons (Real & Rate Land - Card) & Kind & Land a contra a solo land a Lock a Desters of Febral 11: - 11- 2.65 Or Z-mar. 2-2-1 - 2.7 OK んてい 1/3 5-91 CLEANED DEBPIC (BEANEHIS DEAD WOOD In 1/17 -7.6 M i the 3-13-12-9.2 んけん 2- : - : 5 - ? . 3 LJM 5-7-15-83 FT in 6Logs (Bruch Low Boy) I Row out +2 out in 人テル --- . 1200 30-75 5-1-1= - 735 RIT IN BLOGS All IN NOW Ciezra Tia 27~ 5-415-607 6-6-75-66 CRA Tre - E. C. Charle in Sile wilk needs Eping Contain 2.00 1 . 11 7. 33-4" wor 1075 -TJ-6-11-62 + 2.05 over All Long. Clear Trach - Logo From STOR Sections - Raling NO- OF PAINT LTM ELS RAIL NEEDS FHINTING -9- 15 3 - P-1 25-6.95 Painted Railing + Cot Brush + Picked up LJA - 4.3: 18 - GVTT S'3" FROM P. - , V K. F. 1. .. 1-1-1-1-1-1. P. 1. 4 1. 95 CF 2 6445 STELAL (10/050 14 2 Contreams) 24-16 11-12-2-27 P. 1. 2 21-5 French Charles 14 2 Contreams) 24-16

erus de la sul Fras

- 1.05' isfull 4 M 21 842 Pequaket FILE PROJECT NEW HAMPSHIPE WATER RESOURCES SUBJECT 804-90 CONCORD N. H. COMPUTER Date Senter By Pulled 3 Logs Only 1 Log meach Conter bay SB ローン・カ 2-2-15-9.6 Ares OK, in 2 Logs cought on center 3-25-16-7-42 ノマー 4-7-96 -7.5 Cleaned 1 Loy at Stop Day + 1 To Go. ノゴー 4-15-76 -8.7 INSTALLED & STOP LOGS IN ONE BAT (EVED W/OTHER BATS) GLK REMOVED CAUCHT TREE LOG - ALL CLEAR NOW ONE. BAY STU ENPTY OF STOP LOGS . HINCE ON STORARE HOUSE BROLD LOSS FROM TOPOF BOX PDK 5-3-76-8.2 Put in .9 logs. 5-6-16-7.0 Res. FTED Logs + Tamped Logs To Seat & Seal Leaks. Mix boy Log Elev. is - 1.0/2 cand baysare I hog high tim PDK 5-14-76-6.1 5-18-76-6.05 1 kg. Lay in our Buy & 2 long doctos in 2 Brings Day PDK 5-21-76-58 C. Crew Tools man' S.L. Box up & Retwood ald one & Remarked by the ferry P.M 6-18-76 7-3-76-6.75 7-6-20-6.70 Clear Stump + dobrow, (all 1035 in, Flowing Stores - 6.70 Clear Stump + dobrow (all 1035 in, Flowing Stores - 510 Middle Bays SB <u>- 7 · 3 · 16 -6.75</u> RA Reversed 2 Locis (CUTTER PART) (ALL EVEN ACCESS BOYS) 8-10-76-6,3 CLC 9-2-76-6.3 PDK Aton O.t. Jonie debte AT (095 (Sinal) ATE 9-7-76 9-14-76-6.7 P.D.K 10 3-76-6.6, KiTTI- debre in log Section! 11-1-76 (6.2' Pulled Slogs. 7*6*17-Pulled LM /17. 11-1-76 5-10-95. 10-2116 - 6.2 Fuller 32005 (2 Top STrings Now out) (2 Logs = To Go on 2 Deep toys) (hop String The a Construct) 11-12-26-7.4 151april 2 1970 (Ar 1-14-26 -8.1 ホブル 3-4-11-8.9 Area OK B-26 LTr 4-22-77 -7.8 Ulent Some dobre, Hloso Replace 4-log's 7287 4-25-17-7.5 fot in ELogo (alone or) Chenned Sharet of Plyousal بالمراتب كمحا

-7.00 is full lak PEQUAKET F.LK ----2 5 4 T F REMARYS Center DATE Rer BY F1-1 E25: 4.75 PUT in Last 2 Logs (AILEN) Cleared big Los しょ at STOP Section 6.10.77 - 6.00 Clour little 6.600 - C.t. -11:1--128-1 6 37.17-7.70 11 11 11 D.K. 1167 7.8-2 -7.90 PDK G - 5 71 - 4 1 cleared Schich R:2-1-6.9 Lin 10.421-61 Fuller ZLogs . 5.00 10-13-17 -630 Puil 1-10 9 (3.0 120) @1 00,1 2007 10 45 NJ7 The JA 10-12) - 5.50 Pull 7-1043 12 aut tost = 3 and 20. Bay a 31.90 - 4.5 Pulled 31.00 TO DOT ACTOSS + 1 LOST in bottom of lg each mill bay winter operation Lin -1. ? CILLINE 19.93 z 19- 17 - 73 CLUKE - WITE K (RUSANS) in 144 - Moderate 1-1-75 -53. 4.13-87.2 KTS CLEAR 5.5, 5-3.71 PLACE 4 LOGS 24 A. In PAY 5.73 in 12 Loss (2 more Loss To Gal Classa -26 -C. C. Remain - layge log + deliver, C.K. Repince 4-72 - 2000 •_/· ·`` 413- PC= cleaned 2 Logs + Linge Deck. STill a Telephone oole + 4 Loss To Go Lim much delies courts in status meter Gue 6-1922 -65 1921 - 6.10 Ferres & moch debre Classe to go Alse Courserer TO PREVENT Clagging of Further deby + FAlso 2-193 / 7 C. +C.20 1095 Clear Sebre Prist RHil - Post M.T. Since -12.1 212 Paller 1400 To Contra dest 1235 Ramound Log Que St auch T STOP SEE 102 142 - DA Claran Trans a St 1-1-1-7.5 11 Pulled Slogs (Would Gin D 1-1-7-3 Formal - Liss Ides - in and when المعرفي والمحاصر والمحاصر والمحاصر والمحاصر والمحاصر والمحاصر والمحاصر والمحاص والمحاص والمحاص والمحاص والمحاص 11-19-25 -16:20 JAU ST.C. Chinal

PEGCALL KET

7.00 1515111.

FILE

3 CATE REMARKS (24. BY DATE Dirr clear nk - 2.5 \sim 1-25 STORENER LOOS - Bursh Erom Bays FUT 10 10 Logs (Seach Low Car) Sheers LOST ST NEDY LOST FF 74 7 5-19-79 -6.65 REPLACE LAST 2-109'S (All-IN) TLTS ours hope - Pamard dela Log aucok (-C. 6-11-1 -1 = 4 - all distance and in and only a could amount de in large sector some to claim on 015 relay Statesp. GLL 8-18-79 -6.5 GLK Cleaned gailage and debris from stopla bays-ail CK Chest - Much Slass - differ on top 8-20-74-6.8 GG マイク 9-1179 -6.88 Dar CL LOTED CARANCE RTE. ON STRACT AND AREAD SURDIDED 9-22-21 -6.7 3 15- -7 4 - 6C had 3-logs 15 er log perioss pet the PLED BLOCK (12 LOUS OUT TON 10.31.73 2 BAYS HAVE 4 LOUS AND AND AND HAVE I LE OUT 2. 1 De 10-13 - 24 - 25 Homing of 4 bays havent! 17 1235 2. 1 10 1343 (10 15 boll 06 ... - 2000) 210413 1-20, 20495 17-1. TE TO Caro 2 EN. ENERSS 6 INS. MILL 3-40-32-10-2 For 10 5Tops To get (4 hogs in 4 how bays 3-30 - 0 - 0 - 10,000 9 1098 8 50 0 = 2 - 4 10 1098. Also MOTZ, From Stain Alor STORE (540 - 011 Perting 145 -7.15 Put in the Step in 1x. True days him full of PDK debut and ligs Layr moved in pullid out -6.00 Poll 5-1095 Remone turge 1093 FRom In Frant. FOR 5-15-80 -7.5 REPLACED 17 LOGS - LEER BUTS UP TO FUE 2 RICHT BATTS NERD ILLE AND I FALL NOTO JLUS .: 4425 LEONGLA TO BE MADE LEAUTHS 5'-10" HOWEVED IF - 6.5 IS FULL PIND THEAD THEAT ME FUL EATER LOSS THE LART BILLS WHE TO GE LOWING BE I STERNS MAN ODE STANJON NEEDS 1 LOC INFINE TWO FRATA LU -650 Re + Range Hogs, fuil 7 EX COYS. = Allin. Render. 5-10

PLANS AND DETAILS

Ľ

1

Ţ

•

(

É

ſ

C

ŝ

١.

••

в**-**29



R








۰.

.

• • • • .•.









SECTION B.B Sc. 1. : : 10

<u>Bainterenna Etzel</u> Keinforzina Etzel Meinforzina Stad soud bis 3° char dielis - Jewa atro- wiese Meinforzini 32 2°C-2000 Erda Wayo in Berl Pany. Meinforzini 32 at**a**l reu souing Endo+24 anadaertens.

PEQUAWNET FOND 1 NWAY, NEW TAMPLE RE KEINFORGING STEEL

- CONCORD, N. H NEW HAI 1.20 - 2010 45 N. 14-8 She+ 2 + 3



Í







·*****

APPENDIX C

Ŋ

1

K

•

ŧ

.\

SELECTED PHOTOGRAPHS

t





Photo No. 1 - Main Street Bridge and approach channel to dam



Photo No. 2 - General view of downstream face of dam

REPRODUCED AT COVID THANGUT FX TAGEN



Photo No. 3 - View of crest of dam and right abutment from left abutment



Photo No. 4 - View of downstream face of left abutment



٦

1.

Photo No. 5 - Closeup of leakage between left training wall and left abutment



Photo No. 6 - Closeque of enables at the effected training wall

1, i

REPROPOSITION OF A CONTRACT AND A CO

.



Photo No. 7 - Building immediately downstream of right abutment



Photo No. 8 - General view of downstream channel from service bridge

Ç-5



E

Ē

L

£

HYDROLOGIC AND HYDRAULIC COMPUTATIONS



SIEA	CON	SULTAN	TS INC.
ENGINE	ERS /	PLANNER	S

С

T

BOSTON , MASS. ROCHESTER, N.H.

CLIENT FRAME COOPS	JOB NO. 274-7901	1 0+ 21
PROJECT 22 13 Willier Dover & Jam	COMPTO. BY	611:20
DETAIL Huminger Calles	Ск'о. Ву <u>КМ5</u>	7/2= -)

A. Dramage Area

I. Basic Data

- 27.2 square miles as defined on U.S. SS ment ۱. and then an animetered
- 2. dramage area would classify as mountainous, however there are numerous pinks and swampy areas upstream from the dam
- B. Dam and Storage Information
 - 1. Size Classification: INTERMEDIATE based on Storage (21000 aure-feet and < 50,000 aure-feet)
 - as inducated before storage at crest of ilm estimated to be 1,880 acre-feet
 - 2 Hazard Potential: Significant

3. Storage Information

Descriptive Information	Elevation (feet)	Surface Atea Genes	Diterage
480' Contour	480	675	
Top of dam	464.5	335	1,290
AGO' contour	460	202	3 35
Wormal Front	≈ 4 <u>5</u> 9	143	200
Same of the	457.3	122	<u>و</u> ب
	D-2	•	1

SIEIA CONSULTANTS INC. Engineers / planners

E

•

Ľ

ŧ

ļ

Ì.

. . •

BOSTON , MASS. Rochester, N.H.

ENGINEE	RS / PLANNE	RS		ROCHE	STER, N.	н.		
CLIENT_	Fran Cor	·Df		JOB NO.	<u> </u>	7901	PAGE_	20221
PROJECT	Pequantet	Power G.	Dam	COMPTO.	By <u>?}</u>)P		6/1190
DETAIL _	Highmlogic	Calcs	<u></u>	_ CK'D. BY	<u> </u>		DATE_	<u> </u>
	*	Notes :	()	o lovations	: : :	SVD		
			(z)	Normal	pool +	- and an	+0	real skil
			(_)	unth ~	nl sur	un on	U.S.S	S. Sheet.
				o Courto		toe o-		cas -157.3
			(3)	Surface	area	at	+00 0	- Jum
			<u> </u>	determ.	neol bu	. inter	Diati	a cettrem
				the E	urface	aneas	Je-	ed by the
				parl	Show	on T	علا مـ	GS Sheet
				and -	the 46	o Let	بے لیست	50 wet Course
			(4)	Storage	. st	crest	0f -57	50 .075
			-	estino	ted icy	a citur	June (since area
				nto	Fyrani	ital -	mustrum.	Sections
				and	rieter	many	the r	Func 2-
				each	Sitin	1. The	- -	matin m
				the o	ounce	ot a	Juram.	dus Trissrum
							•	
C. 5	5, silway	Inform	nato	~				
	1 (+		1	• 00	, -	+0 =		
	1. Concrete	l Stop	ag .	Spilling Co de	ey ar		544 -	, op wa
	کامہ ج	total	ed '	in Onte		am.		
	2 dische	map our	er 5.	silusan.	que	Su	S.Lar	0- 1
	11 U U	ir form	ula	up to f	Devatio	~ 7 <i>6</i>	.з. <i>о</i> 4	Let
		Q =	CL	H 3/2	(Standa	d hand	منت منت	(Es, Men.)
			When	e: Q	= disc	Linge ,	ر ب نی	
				L	= 'ver	- Teng	th the	et .
				H	= hea	d ore	r we	r -ect
				C	= disc	inge	Cieri	
					~			
						= 3.2 +	+ 0.4	
						uhini t	415.25	James - Maria
						1.1 ?	= 233 -	and the second
						لمردن وماتنك	e Li energi	-

SIEIA CONSULTANTS INC. BOSTON , MASS. ENGINEERS / PLANNERS ROCHESTER, N.H. CLIENT ATTA ATTS __ JOB NO. ______ PAGE _____ PAGE _____ 204 21 • Ľ 3. above elevation 463.0 Let (bottom of service inder) stoples 'can openings will contraction function as orifiers, Morefore the orifice discharge formula would be applicable Q = Cavagh (Standard - enderste - - (E's Hurwhere: O= discore, Cts C= or - le coe-, le C.6 a= area of orifice, ++2 g = acceleration due to arreting file. h = head above horizontal converting of or fice , weet I Estimate Effect of Surcharge Storage in Maximum Protociale Discharge A. Develop stage-discharge curve for outflow from dans complex 1. define sources of outflour a. discharge over spicherony - assume too ups set at approx 457.3 ["typical" storing arrangement () discharge to invation 463 défined se sur-crested wer formule as défined a one (2) discharge acove energine 463' definit in crifice d'élèrre cruation on étop de la Jacuines manual and part of since and agreed to the above mention 964.5' iler and a contcreited where counter $Q = C L H^{3/2}$ with C = 2.53

SIEIA CONSULTANTS INC. ENGINEERS / PLANNERS

Ł

I

BOSTON , MASS. Rochester, N.H.

CLIENT ATT ADS	Jos No. 274-7901	PAGE.	<u> </u>
PROJECT The state of in	COMPTD. BY 2.15		190
DETAIL the tro bace Coles.	CK'D. BY		-123/32
b. due ûsze or alasze ûlina atested we	er training wells tran 464.5' def er equ 'an with	and C=	ricut mot 2.6

2. Discharge over spillway

a. Weir discharge

Elevation (feet NGVD)	С	L	14 (fee-)	
4,57.3			1 2	0
458	3.29	30.8	0.7	60
459	3.40		1.7	230
460	3.47		2.7	470
461	3.55		3,7	730
462	3.62		-17	1140
463	3.70	4	5,7	1550

5 Orifice discharge

Elevation (feet, NGVD)	С	Q (fect ²)	(fest)	
464	0.6	≈ 176	3.9	1,670
465			4.9	i, 380
466			5.9	2,060
467			6.9	2,230
469			7.9	7390
469			3.9	2,530
470	ŧ	•	9.9	2,670

3. Discharge over service brillie

E Exercan (Leet NGVD)	Ċ	 	H	
4:64.5	2.3	* 37	0	
405			5.5	45
ئ الم	Ŷ		1.5	

SIEIA CONSULTANTS INC. ENGINEERS / PLANNERS

BOSTON , MASS. ROCHESTER, N.H.

CLIENT Cho ?	JOB NO PAGE	5 0 7 21
PROJECT Content Tours of The	COMPTO. BY BUP DATE	5/11/20
DETAIL den mic Cales	CK'D. BY DATE DATE	72532

3. Service bridge discharge - CONTINUED

Elevation (test. NGVD)	С	L	1-1	φ
467 469 469 470	z.8	≈ 37	2.5 3.5 4.5 5.5	410 630 190 1340

-1: Discharge over left training wall and alcutment

Elevation (feet NGVD)	C	Effecture L (feat)	Aire H	O.5
464.5	2.6		0	\odot
465		20	<i>.</i> .25	7
466		90	<i>3.</i> 75	150
467		Z90	1.25	1050
469		490	1.75	2950
469		690	Z.25	6,050
470	I	890	2.75	تدی زن

5. Discharge over right training wall and abuitment

Elevation (feet NGUD)	С	Effectue L (fect)	from H	
464.5 465	2.6	10	0	0
466 467		BO 235	0.75	20 10 3 0
469		20	1.7-5	7.950
470	Y	900		

SIEIA CONSULTANTS INC. Engineers / planners

L

•

4

;

·.

.

.

.

1

:.`

Ŀ

•

1

BOSTON , MASS. Rochester, N.H. and the second second second

•

•

÷-

CLIENT Prine Caros	JOB NO. 27	4-7-7.01	PAGE_	<u></u>
PROJECT Pequewkot Driver 15. Fim	COMPTO BY_	3 JUP	DATE _	:1 . 30
DETAIL Hy tralance Gles	_ CK'D. BY	KM5		7/25:32
6. Total Discharge	from project	cite		

Elevation	Quinny	Q	Q	0	O
(Levi NGU)		Service on the	geit abut	richt aout	TOTAL
457.3 458 459 460 461 462 463 464 465 466 465 466 467 469 469 469	0 60 230 470 790 1,140 1,550 1,670 1,670 2,060 2,230 2,390 2,530 2,530 2,670	0	0 150 1,050 2,950 6,050 10,500	0 3 30 1,030 2,450 6,100 10,700	0 30 780 780 780 780 780 780 780 780 780 78

SIEIA C Enginee	CONSULTANTS INC. ERS / PLANNERS	BOSTON , MASS Rochester, N.H.	_
CLIENT_	Army Corps	JOB NO. 274-7907	PAGE <u>3 2 21</u>
PROJEC	+ Topy nutret Power Co Dan	COMPTO. BY RUD	DATE [1130
DETAIL _	Hydrologic Cales	CK'D. BY	DATE7/23/3)
з.	Effect of surcharge stora	ge on max. prob. disc	charge
	1. Pertinent Data		
	a. Drainage area = $\frac{1}{2}$ b. Characteristics c c. Test flood = $\frac{1}{2}$ d. Follow Army Corps	27.2 Square miles of basin - to estimate Mi PMF in upper parts s' procedure	however use clime curve F Pare Five Pate suits and swampy areas iscution t of basin
	2. <u>STEP 1</u> : Determine Pe	eak Inflow Q _{Pl} from .	Guide Curve
	a. the maximum proba be 1350 cfs/s	able discharge was es 59.Mi	timated to t
.	•, PMF = (27. *	Z sq.mi) (1350 c-s	(sg.mi)
	≈ 36	,700 cfs	
	1/2 PMF	≈ 18,400 cfs	
	3. <u>STEP 2:</u> Determine su and Q _{P2}	urcharge height to pa	ss Q _{Pl,} STAF 1 ,
	a. from Figure 1 de [.] Q _{P1} = 18,4000	termine surcharge hel	ght to pass
	ę	suchurge elevation	$\approx -57.3 + 1$
		St-Charge height	= 12.0 - cut
	b. determine volume runoff	of surcharge STOR ₁	in inches of
	First litermine	round to some of	n se en
	(1) pattern de Surciane (2) definidation Surcianeze	Lander and Then I	
	-	~_ 0	

J.

L

ŧ

.

6

0

. ...

ĩ

. .

. .

•

•

$$STOR_{1} = \frac{Volume of storage (as acre-inches)}{drainage area}$$

$$STOR_{1} = \frac{\left[2.74\chi(\frac{122 \text{ km} + 202 \text{ km}^{2}}{2}) + (9.74\chi(\frac{122 \text{ km} + 252 \text{ km}^{2}}{2}) + (9.74\chi(\frac{122 \text{ km} + 252 \text{ km}^{2}}{2})\right]}{(27.7 \text{ symm}(1000 \text{ km}^{2})}$$

$$STOR_{1} = \frac{2.31 \text{ mclcs}}{2}$$

c. determine Q_{P2} .

$$Q_{P2} = Q_{P1} \left(1 - \frac{STOR_1}{9.5''} \right)$$

 $Q_{P2} = \left(18, 400 \text{ cfs} \right) \left(1 - \frac{2.31''}{9.5''} \right)$
 $Q_{P2} = \left(13, 400 \text{ cfs} \right) \left(1 - \frac{2.31''}{9.5''} \right)$

4. <u>STEP 3</u>: Determine surcharge height and STOP₂ to pass $Q_{\rm P2}$ and then $Q_{\rm P3}$

a. From Figure 1 determine surcharge height to pass $Q_{p0} = 13,900$ CTS

$$\frac{2101}{2101} = \frac{457.3}{2101} = \frac{457.3}{1.5} = \frac{1.5}{1.5}$$

MICROCOPY RESOLUTION TEST CHART NATIONAL BUREAU OF STANDARDS-1963-A

ì

E

Í.

.....

Ĩ

D-12

SIEIA CONSULTANTS INC. Engineers / planners	BOSTON , MASS. Rochester , N.H.		
CLIENT_Army Corps	Jos No. 274-7901	PAGE_	12 of 21
PROJECT Pequeintet Pour Co Dam	COMPTO. BY BWP		6/11/80
DETAIL Hydrologic Calcs	Crin By KMS		7/23/32

c. determine STOR_{AVG}

ī

Ĩ

r

1

Î

$$STOR_{AVG} = \frac{2.23 \text{ in } + 2.16 \text{ in}}{2}$$

STORANC = 2.20 inches

d. determine Q_{P4}

$$Q_{P4} = (18, 400 \text{ cfs})(1 - \frac{2.20^{\circ}}{9.5})$$

 $Q_{P4} = 14, 100 \text{ cfs}$

6. STEP 5: Determine surcharge height for Q_{P4} and $STOR_4$

a. From Figure 1 surcharge height for $Q_{P4} = 14.100c^{-1}$

surface area @ surcharge eller ~ 410 acres

b. determine
$$STOR_{4}$$

 $STOR_{4} = \frac{437 ac + (8.844)(\frac{202ac + 4.0a}{2})(12''/44)}{(27.25g.m_{4})(6.403c/23.m_{4})}$
 $STOR_{4} = 2.18 \text{ inclus}$

c. determine STOR_{AVG}

$$STOR_{AVG} = \frac{2.21 \text{ m}}{2} + \frac{2.18 \text{ m}}{2}$$

= 2.19 mcmas

D-2

EA CONSULTANTS INC.	ROSTON , MASS Rochester , N.H.	
IENT Army Gros	JOB NO. 274-7901	PAGE
ADJECT Pequawket Driver Co. Da	COMPTO. BY CUP	DATE _6/13/90
ETAIL Hy to ber Calles	Ск'о. Ву <u>///</u> 5	DATE32
STORA and accept rout at a surce	d STORAUG agree to ted test flood outflow . change elevetion of 4	within 1%, therefore aqual to 14, 150 mgs 169.3 fact
7 In Conclusion		
a. The routes will or	d test flood outflow vertop the claim by ap	of 14,100 cm
t Spillway design	Capacity - with 5-20 crest elevation of 4!	ings and at 57.3 feet
(1) Wate (use	r surface at crest or	f dam - 464.5 feel previous discussion)
Q	= (0.6)(176+)[(2)(2.2)(464.5)]	'- 460.1) ≈ 1,780 €
(Z) Wate	-surface at test flood as	evoltion - 468.3 feet
(a) d	ischarge through stoplag	bay
ζ	?=(0.6)(1767:2) [(2)(32.2)(468.3)	$-460.1)$ ≈ 2500
(b) dr	schange over service bridge	
G)= (2.8)(37f+)(463.9'- 40	(4.5 ⁾ ^{3/2} ≈ 920c-
ب ک	$f_{000} = 2,500 cs + 920$	cfs = 3 + 20cr

1

ſ

,

r

R

A

. .

ĺ

. .

• • • • •

.....

.

.

EA CONSULTANTS INC. BOSTON , MASS ENGINEERS / PLANNERS ROCHESTER, N.H. CLIENT ATTA 2005 __ JOB NO. 234-3901 PAGE 14 of 21 COMPTO. BY BUP _ DATE _6/13/90 DETAIL Hudiplan, Gale DATE 7/52.40 CK'D. BY ______ II. Using "Rule of Thumb" Guidance for Estimating Donstream Failure Hydrographs examine impact of dum Failure A. Since Spillway longth is Care: compared to lingth of dam, the tailwater reculting firm discharge over the spilling with the writer surface at the crest of dan may a significant 1. from previous calcs. Steady state duscharge over spilling with water surrace at creat of dam 2 1,780 cfs (p.D-14 of the Hydrolyce Cales). 2 Using Stage - Discharge curve prepared -for steady state discharge a. Reach 1 - from Figure 3 Strige = 8.0 feet b Reach 2 - from Figure 3 Stage = 5.2 feet 3. The failure discharge should for se computed and routed through the stream reaches using the "Rule of Thumb" Guidance for Estimating Drangrain Factore Hydrographic If the hazand is significantly increased by the annual descharge them the Narand classification with an defined by the return proceeder. If there is No significant increase in harard our the thereig State descharge, tim The restand the motion Shall be difermined we -aring the The type way that 2-15

r

E A CONSULTANTS INC. BOSTON , MASS NEERS / PLANNERS ROCHESTER, N.H. CLIENT TITMU CORDS Jos No. 274-790! 15 22 21 PROJECT P2+ 12 Jule + The A Dam COMPTO. BY PUP 7/23/77 DETAIL Hudming Toles CK'D. BY _____ 7/25/32 DATE B. Reach 1 1. <u>STEP 1</u>: Determine recervoir storage at time of failure from previous cales trage = 1,990 ac-4 2. STEP 2: "Latermine Peak Failure Out- in, in: a. $Q_{31} = (3/27) W_{32} g^{1/2} U_{33}^{-3/2}$ where W_b = Breach Width (may 40% of dam length) = (0.7)(45 - eat) = 19 feat with of each section of -planage equals 17.4 Cast, thus assume min of 3 stopice loaves Yo = Total herant from clunned often to cill evel at much = 464.5'- 452.5' (Subar Commence = 12 feat Qp, = (8/27) (17.4 - (32.2) (12.2) (12.2) ≈ 1220 cfs 6. must add the horse over invited comments Spulmay to the facture many Quincial = 1/2 (spi way decension with = 1/2 (17900-s) = 590 cm $C = 1, 720 c^{2} + 890 c^{2}$ = 2, 110 cfs I-lo

t

E

.

L

-

Ę

5	E	A	COI	V :	su	LT	An	TL	5	INC	
Er	JG	INE	E A S	1	PL	AN	NE	A S			

()

.

r

E.

.

•--

l

Ļ

BOSTON , MASS. Rochester, N.H.

CLIENT Army Cords	Jos No. 2744-7901	PAGE 16 0- 21
PROJECT Provinited Priver Co Cam	COMPTO. BY BWP	DATE _7/23/80
DETAIL Hydrologic Calcs.	CK'D. BY KMS	DATE 7/23/30

STEP 3 : Prepare stage-discharge curve for Reach 1

a. Pertinent Data

- (1) Reach length = 100 feet
- (2) Channel slope = 0.0016
 - (.3) Manning n = 0.06
 - (4) Channel shape trope zoidal
 - (5) Base width ≈ 45 Leat

b. See Figure 3 for stage-discharge curve

STEP 4: Estimate Reach Outflow

a. Determine stage for $Q_{p_1} = 2,110$ cm Figure 3 and find volume in reach

- (1) Stage (depth of flow) = 0.3 feet (Total Stage = 3.3 feet
- (2) Volume in reach = (reach length) (cross-sectional) area of channel)
 - X-area = (0.5)(0.3 ft) (67 ft + 69 $\hat{}$) = 54 ft² Volume = V₁ = $\frac{(54 \text{ ft}^2)(\ D \hat{}$) = 0.12 acre-ft

 $v_1 < \frac{s}{2}$: reach length OK

b. Determine Q_{PZ}(TRIAL)

 $Q_{PZ(TRIAL)} = Q_{P1} \left(1 - \frac{V_1}{S}\right)$ $P_{Z(TRIAL)} = (2,10 \text{ cm})(1 - \frac{0.12 \text{ acm}^{-1}}{1.320 \text{ acm}^{-1}})$

9,10cfs D-17 SEIA CONSULTANTS INC.

ŕ

1

....

l

. (

BOSTON , MASS. Rochester, N.H.

CLIENT Army Cords	Jas No. 274-7901	PAGE	12 26 21
PROJECT Provincet Driver Co. Tom	COMPTO. BY BWP	DATE	=123190
DETAIL	Ск'р. ВуКМЗ		7123/30

c. Compute V₂ using Q_{P2(TRIAL)}

From Figure 3 determine stage for Q_{P2(TRIAL)}

Stage = 0.8 feet (Total Etage = 3.3 feet) <u>about prefailure</u> <u>disclores</u> X-area = (0.5)(0-8 feet) (67 f + -63 f.) = 54 f + 2 $V_2 = \frac{(54 f + 2)(100 f +)}{43,560 f + 2/a cre}$

$$v_3 = 0.12$$
 are -ft

d. Average V_1 and V_2 and compute Q_{PZ}

(1) Vavg = $\frac{V_1 + V_2}{2}$

$$V_{avg} = \frac{0.12 \text{ ac-ft} + 0.12 \text{ cc-ft}}{2}$$

Vavg = 0.12 ac-ft

(2) $Q_{P2} = Q_{P1} \left(1 - \frac{Vavg}{S}\right)$ $Q_{P2} = \left(2, 10 \text{ cfs}\right) \left(1 - \frac{O_0 12}{1,930}\right)$

$$\varphi_{P2} = 2,110 cfs$$

CLIENT_A	rmy Cords	Jos No. 294-7901	PAGE 19 2+ 21
PROJECT	Leanswith Priver 17 - 2000	COMPTO. BY BWP	DATE
DETAIL H	vdrologic Calcs.	Ск'р. ВтКМЗ	DATE7/25/80
C. 7	Reach 2		
	STEP 3 : Prepare stage	-discharge curve for	Reach 2
	Deutieret Dete		
	a. Pertinent Data	- 500 fort	
. :	(1) Reach length		
	(2) Channel slope		
	(3) Manning n = 0		
	(5) Base width ~	AS Dut	
		- TJ reat	
	b. See Figure 3 for s	tage-discharge curve	<u>.</u>
	STED 4. Estimate Read	b Outflow	
	SIEr /. Estimate Read	II OULIION	
	a. Determine stage fo	$pr q_{p_{2}} = 2,10$ cts	from Figure 3
	. : and find volume i	in reach	
	-		
	(1) Stage (depth above prefails	of flow) = 0.3 ft	(Total Stape = 6.5
	(2) Volume in rea	ach = (reach length)	(cross-sectional) area of channel)
	X-area = (0.5)(0.3 f+)(630 197ft ⁺	\$+ + 695 ^{\$} +)
	Volume = V, :	(197 ftz) (500	<u>(+)</u>
	1	43,560 f+3/ane	
	:	= 2.3 acre - Lest	
		$v_1 < \frac{S}{2}$: reach let	ngth OK
	b. Determine QP3(TRL	AL)	
	QP2(TRIAL)	$q_{\rm P2} = Q_{\rm P2} \left(1 - \frac{v_{\rm 1}}{c} \right)$	
		× 37	
			2.3
	Q _{P3} (TRIAL)	$1 = (2, 10 c^{-2})(1)$	

.

ŕ

-
SIEIA CONSULTANTS INC. ENGINEERS / PLANNERS

P

.

ł

R

I

•

i. I

).

BOSTON , MASS. Rochester, N.H.

CLIENT Army Cords	JOB NO. 274-7901	PAGE 19 07 21
PROJECT Provident Prover Co. Com	COMPTO. BY BWP	DATE 7/23/80
DETAIL Hydrologic_Cales	CK'D. BY	DATE 7/25/30

c. Compute V₂ using Q_{P3(TRIAL)}

From Figure 3 determine stage for QP3 (TRIAL)

Stage = 0.3 ft (Total = 200 = 6.5 ft) <u>above prefailure</u> <u>discharge</u> X-area = (0.5)(0.3 ft)(630 ft + 695 ft) $\approx 197 ft^2$ = <u>(197 ft^2)(500 ft)</u>

$$V_2 = \frac{(191 + 1^2)(500 + 1)}{43,560 + 1^2/acre}$$

 $V_2 = 2.3 acre_{-} + 1$

d. Average V_1 and V_2 and compute Q_{P3}

(1) $Vavg = \frac{V_1 + V_2}{2}$ $Vavg = \frac{7.3 a_2 - f_1 + 2.3 a_2 - f_1}{2}$

Vavg = 2.3 ave-it.

(2) $Q_{P3} = Q_{P2} \left(1 - \frac{V_{avg}}{S}\right)$ $Q_{P3} = \left(2, 110 \text{ cm}\right) \left(1 - \frac{2.3}{1980}\right)$

$$Q_{P3} = 2,110 cfs$$

A CONSULTANTS INC. BOSTON , MASS. ROCHESTER, N.H. ENGINEERS / PLANNERS ___ JOB NO. 274- 793 ___ PAGE__ GLIENT AFRE Gras PROJECT De Manuel Ant Antonio Compto By Bar DATE _ DATE _____ DETAIL ----I. Con Clusions -rom -sulure discharge routing 1. Reach 1 - The addition of the manual discuss. will increace the stage in this mach by about I foot above that for the pro-unum flow. This increase in stage will result in water rising to the still livel it is building located near the right abuildment. The prefailure discharge was sout I fort below the sal. 2 Reach 2- Down Stream from Reach I the -tream channel provide broadens againing. Inscruently, time is very little de manee between the stage of the -muni in more in the pretailure flow, since a relationly enable increase in stage results in a Similiant inoren in discharge. No significant damage trained Reach result in 3 Although the increase in stage in Reven 1 is not large, it does result in statereaching the sill level of the build located near the right about sent. Considential, the nazand would increase significantly de to the potential for economic loss. There fore, the razard class faction for the Personal the Company Dam vat ain chitir is sign Tuni Dreviews analysis.

B

t



APPENDIX E

۰. د

`_~

r

R

I

•----

• •

.

ľ

INFORMATION AS CONTAINED IN THE NATIONAL INVENTORY OF DAMS



7

FILMED

8-85

DTIC

The second s