F	AD-A156 430 NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS 1/1 LARE FRANKLIN PIERCE. (U) CORPS OF ENGINEERS WALTHAM MA NEW ENGLAND DIV AUG 78												
ι	INCLAS	SIFIED	)						 	F/G	13/13	NL	
			w										
	,												
												1	
		24 1.3	<b>1</b>					7 X 2 K					
							END Finited						



MICROCOPY RESOLUTION TEST CHART NATIONAL BUREAU OF STANDARDS-1963-A

MERRIMACK RIVER BASIN Hillsboro<del>ugh,</del> New Hampshire

i di C

1

د م م م م

•

.

ONC FILE COPY

AD-A156 430

# LAKE FRANKLIN PIERCE DAM N.H. 00199

NHWRB-116.04

# PHASE I INSPECTION REPORT NATIONAL DAM INSPECTION PROGRAM





iff.

DEPARTMENT OF THE ARMY NEW ENGLAND DIVISION, CORPS OF ENGINEERS WALTHAM, MASS. 02154

AUGUST 1978

DISTRICTION STATEMENT A Approved for public release; Distribution Unlimited

# 85 06 14 026

REPORT DOCUMENT	ATION PAGE	READ INSTRUCTIONS BEFORE COMPLETING FORM
REPORT NUMBER	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
NH 00199	AD- A156431	
TITLE (and Sublifie)		B. TYPE OF REPORT & PERIOD COVERED
Lake Franklin Pierce Dam		INSPECTION REPORT
ATIONAL PROGRAM FOR INSPECTION	ON OF NON-FEDERAL	6. PERFORMING ORG. REPORT NUMBER
AUTHOR(+)		8. CONTRACT OR GRANT NUMBER(+)
J.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION		
PERFORMING ORGANIZATION NAME AND	ADDRESS	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
CONTROLLING OFFICE NAME AND ADDR	ESS	12. REPORT DATE
EPT. OF THE ARMY, CORPS OF E	NGINEERS	August 1978
EW ENGLAND DIVISION, NEDED	02254	13. NUMBER OF PAGES
MONITORING AGENCY NAME & ADDRESS	il different from Cantrolling Office)	18. SECURITY CLASS. (of this report)
		UNCLASSIFIED
		SCHEDULE
DISTRIBUTION STATEMENT (of the Report PPROVAL FOR PUBLIC RELEASE:	DISTRIBUTION UNLIMITED	. Report)
DISTRIBUTION STATEMENT (of this Report APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION STATEMENT (of the observe Cover program reads: Phase I nowever, the official title o ion-Federal Dams; use cover of KEY WORDS (Continue on reverse side if new	DISTRIBUTION UNLIMITED at antered in Block 30, if different fre Inspection Report, National for the program is: National date for date of report	ional Dam Inspection Program; bnal Program for Inspection of
DISTRIBUTION STATEMENT (of this Report APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION STATEMENT (of the observed Cover program reads: Phase I however, the official title o Non-Federal Dams; use cover MET WORDS (Continue on reverse side if new DAMS, INSPECTION, DAM SAFET	DISTRIBUTION UNLIMITED at aniored in Block 30, if different fre Inspection Report, Nati f the program is: Natic date for date of report	and a construction and the second sec
DISTRIBUTION STATEMENT (of this Report APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION STATEMENT (of the observed Cover program reads: Phase I however, the official title o ion-Federal Dams; use cover KEY WORDS (Continue on reverse side if new DAMS, INSPECTION, DAM SAFET Merrimack River Basin	DISTRIBUTION UNLIMITED at aniorad in Black 30, if different fre Inspection Report, National f the program is: Nationate date for date of report secondary and identify by black number; Yo	ional Dam Inspection Program; Dal Program for Inspection of
DISTRIBUTION STATEMENT (of this Report APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION STATEMENT (of the observed SUPPLEMENTARY NOTES EOVER program reads: Phase I However, the official title of Ion-Federal Dams; use cover Merrimack River Basin Hillsborough New Hampshire North Branch, Contoocook Rive	DISTRIBUTION UNLIMITED at aniored in Block 20, if different fre Inspection Report, Nationate f the program is: Nationate date for date of report	(onal Dam Inspection Program; onal Program for Inspection of
DISTRIBUTION STATEMENT (of this Report APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION STATEMENT (of the observed Supplementary notes Cover program reads: Phase I nowever, the official title o ion-Federal Dams; use cover KEY WORDS (Continue on reverse side if not DAMS, INSPECTION, DAM SAFET Merrimack River Basin Hillsborough New Hampshire North Branch, Contoocook Rive	DISTRIBUTION UNLIMITED at aniored in Block 30, if different fre Inspection Report, Nati f the program is: Natic date for date of report secondry and identify by block sumber Y	ional Dam Inspection Program; Dal Program for Inspection of Figure 4
DISTRIBUTION STATEMENT (of this Report APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION STATEMENT (of the observed Over program reads: Phase I towever, the official title o ion-Federal Dams; use cover Merrimack Continue on revorce side if nee DAMS, INSPECTION, DAM SAFET Merrimack River Basin Hillsborough New Hampshire North Branch, Contoocook Rive ABSTRACT (Continue on revorce side If nee The dam consists of a central embankments. The dam is 1870 be in fair condition. No set seepage was noted which shoul is considered high. k, rev	DISTRIBUTION UNLIMITED at aniored in Block 20, if different for Inspection Report, National for the program is: National date for date of report becomy and identify by block number; Your and identify by block number; Your and identify by block number; Your and identify by block number; I concrete gravity ogee oft. long and 43 ft. h rious problems were det; I de monitored closely	spillway with earth dike igh. The dam is assessed to ected, although some suspicio . Overtopping potential
DISTRIBUTION STATEMENT (of this Report APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION STATEMENT (of the observed over program reads: Phase I nowever, the official title o ion-Federal Dams; use cover Merrimack River Basin Hillsborough New Hampshire North Branch, Contoocook Rive ABSTRACT (Continue on revorce olde II nee DAMS, The Contoocook Rive ABSTRACT (Continue on revorce olde II nee The dam consists of a central embankments. The dam is 1870 be in fair condition. No set seepage was noted which shoul is considered high. k.	DISTRIBUTION UNLIMITED at aniored in Block 30, if different fre Inspection Report, Nation f the program is: Nation date for date of report becomy and identify by block number; Y. er er end concrete gravity ogee oft. long and 43 ft. h rious problems were detailed be monitored closely	spillway with earth dike igh. The dam is assessed to ected, although some suspicio . Overtopping potential

• • •

. . .

JAN 73 475 EDITION OF I NOV SE IS OBSOLE

# **DISCLAIMER NOTICE**

THIS DOCUMENT IS BEST QUALITY PRACTICABLE. THE COPY FURNISHED TO DTIC CONTAINED A SIGNIFICANT NUMBER OF PAGES WHICH DO NOT REPRODUCE LEGIBLY.



E

ľ

F

E

DEPARTMENT OF THE ARMY NEW ENGLAND DIVISION, CORPS OF ENGINEERS 424 TRAPELO ROAD WALTHAM, MASSACHUSETTS 02154

REPLY TO ATTENTION OF:

NEDED-E

APR 1 6 1979

Honorable Hugh J. Gallen Governor of the State of New Hampshire State House Concord, New Hampshire 03301

Dear Governor Gallen:

I am forwarding for your use a copy of the Lake Franklin Pierce Dam Phase I Inspection Report, which was prepared under the National Program for Inspection of Non-Federal Dams. The report is based upon a visual inspection, a review of past performance, and a preliminary hydrological analysis. A brief assessment which emphasizes the inadequacy of the project spillway under test flood conditions is included at the beginning of the report.

The preliminary hydrologic analysis has indicated that the spillway capacity for the Lake Franklin Pierce Dam would likely be exceeded by floods greater than 28 percent of the Probable Maximum Flood (PMF), the test flood for spillway adequacy. Screening criteria for initial review of spillway adequacy specifies that this class of dam, having insufficient spillway capacity to discharge fifty (50) percent of the PMF, should be adjudged as having a seriously inadequate spillway and the dam assessed as unsafe, non-emergency, until more detailed studies prove otherwise or corrective measures are completed.

The classification of "unsafe" applied to a dam because of a seriously inadequate spillway is not meant to indicate the same degree of emergency as would be associated with "unsafe" classification applied for a structural deficiency. It does mean, however, that based on an initial screening and preliminary computations there appears to be a serious deficiency in spillway capacity. This could render the dam unsafe in the event of a severe storm which would likely cause overtopping and possible failure of the dam, significantly increasing the hazard potential for loss of life downstream from the dam.

NEDED-E Honorable Hugh J. Gallen

Ē

ļ

It is recommended that within twelve months from the date of this report the owner of the dam engage the services of a professional or consulting engineer to determine by more sophisticated methods and procedures the magnitude of the spillway deficiency. Based on this determination, appropriate remedial mitigating measures should be designed and completed within 24 months of this date of notification. In the interim a detailed emergency operation plan and warning system should be promptly developed. During periods of unusually heavy preciptiation, round-the-clock surveillance should be provided.

I have approved the report and support the findings and recommendations described in Section 7, with qualifications as noted above. I request that you keep me informed of the actions taken to implement these recommendations since this follow-up is an important part of the non-Federal Dam Inspection Program.

A copy of this report has been forwarded to Water Resources Board, the cooperating agency for the State of New Hampshire. This report has also been furnished to the owner of the project, the Public Service Company of New Hampshire, 1000 Elm Street, Manchester, New Hampshire 03101.

Copies of this report will be made available to the public, upon request to this office, under the Freedom of Information Act, thirty days from the date of this letter.

I wish to take this opportunity to thank you and the Water Resources Board for the cooperation extended in carrying out this program.

2

Dric

Sincerely yours,

Accession For NTIS GRA&I DTIC TAB Unannounced Justification +AU By. Distribution/ Availability Codes Avail and/or Special Dist

JOHN P. CHANDLER Colonel, Corps of Engineers Division Engineer LAKE FRANKLIN PIERCE DAM

i

Ľ

NH 00199

#### MERRIMACK RIVER BASIN HILLSBORO, NEW HAMPSHIRE

# PHASE I INSPECTION REPORT NATIONAL DAM INSPECTION PROGRAM

P	HA	SE	Ι	REP	ORT
---	----	----	---	-----	-----

#### NATIONAL DAM SAFETY PROGRAM

Name	of Dam L	ake Franklin Pierce Dam
	State Located	New Hampshire
	County Locate	i <u>Hillsboro</u>
	City or Town_	Hillsboro
	Stream	North Branch, Contoocook River
	Date of Inspe	ction 6/22/78

#### BRIEF ASSESSMENT

Lake Franklin Pierce Dam (also known as Jackman Dam) consists of a central concrete gravity ogee spillway with earth dike embankments. Total length is 1,870 feet\_and maximum height is 43 ft. The dam is located on the east end of Lake Franklin Pierce on the north branch of the Contoocook River in the Town of Hillsboro. A 7.5 ft. diameter penstock runs downstream from the dam a distance of 1.3 miles to the Jackman Hydroelectric Station. The dam is owned by the Public Service Company of New Hampshire and is operated for electric power. It is placed in the significant-to-high hazard classification due to its proximity above the village of Hillsboro.

Lake Franklin Pierce Dam is assessed to be in fair condition. The principal shortcoming is low spillway capacity. No other serious problems were detected, although some suspicious seepage was noted which should be monitored closely. Most of the long embankments are heavily covered with trees which can cause uprooting in wind storms and whose roots can provide leakage paths.

A test flood equal to the probable maximum flood would overtop the dam by six feet (4 ft. if the trees were cleared). Spillway capacity is equal to about 1/4 the peak outflow of the probable maximum flood. Overtopping potential is considered high. It is recommended that the Owner take steps to improve the hydraulic capacity, monitor the apparent seepage, and remove all trees from the embankments within two years after receipt of this Phase I Report.

WHITMAN & HOWARD, INC.

Q

Ē

Ę

Ė



T. T. Chiang, Ph.D., P.E.



John L. Scott, P.E.

This Phase I Inspection Report on Lake Franklin Pierce Dam has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the <u>Recommended Guidelines for Safety Inspection</u> of Dams, and with good engineering judgment and practice, and is hereby submitted for approval.

Charles ;

CHARLES G. TIERSCH, Chairman Chief, Foundation and Materials Branch Engineering Division

Karn Member

FRED J. RAVINS, Jr., Mem Chief, Design Branch Engineering Division

SAUL COOPER, Member Chief, Water Control Branch Engineering Division

APPROVAL RECOMMENDED:

ac B. Fryan JOE B. FRYAR

Chief, Engineering Division



PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or The assessment of the general condition of property. the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I Investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fraction thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

# TABLE OF CONTENTS

LETTER OF TRANSMITTAL	
BRIEF ASSESSMENT	i
REVIEW BOARD PAGE	iii
PREFACE	iv
TABLE OF CONTENTS	v
OVERVIEW PHOTO	vi
LOCATION MAP	vii

# REPORT

Cr.S

6

**}** 

E

[...

Ŀ,

ľ,

SECTION 1 -	- PROJECT INFORMATION	1
SECTION 2 -	- ENGINEERING DATA	9
SECTION 3 -	- VISUAL INSPECTION	11
SECTION 4 ·	- OPERATIONAL PROCEDURES	14
SECTION 5 ·	- HYDRAULIC/HYDROLOGIC	15
SECTION 6	- STRUCTURAL STABILITY	17
SECTION 7	- ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES	19
APPENDIX A -	INSPECTION CHECK LISTS	
APPENDIX B -	ENGINEERING DATA	
APPENDIX C -	INSPECTION PHOTOGRAPHS	
APPENDIX D -	HYDROLOGIC COMPUTATIONS	

APPENDIX E - INFORMATION AS CONTAINED IN THE NATIONAL INVENTORY OF DAMS

V



( E

).

p

# LAKE FRANKLIN PIERCE DAM

# Hillsborough, N.H.

Approx. Scale I"=280'



# PHASE I INSPECTION REPORT

#### LAKE FRANKLIN PIERCE DAM

SECTION 1

#### PROJECT INFORMATION

#### 1.1 General

E

6

0

|. |. |.

Į,

B

Ĺ

#### a. Authority

Public Law 92-367, August 8, 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a national program of dam inspection throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region. Whitman & Howard, Inc. has been retained by the New England Division to inspect and report on selected dams in the State of New Hampshire. Authorization and notice to proceed was issued to Whitman & Howard, Inc. under a letter of May 1, 1978 from Ralph T. Garver, Colonel, Corps of Engineers. Contract No. DACW33-78-C-0313 has been assigned by the Corps of Engineers for this work.

# b. Purpose

- Perform technical inspection and evaluation of non-Federal dams to identify conditions which threaten the public safety and thus permit correction in a timely manner by non-Federal interests.
- (2) Encourage and prepare the States to quickly initiate effective dam safety programs for non-Federal dams.
- (3) To update, verify and complete the National Inventory of Dams.



# 1.2 Description of Project

# a. Location

Lake Franklin Pierce Dam is located on the east end of Lake Franklin Pierce on the North Branch of the Contoocook River in the Town of Hillsboro, New Hampshire. It appears on the U.S.G.S. quadrangle "Hillsboro, New Hampshire". Lake Franklin Pierce is also known as Jackman Reservoir and the dam is sometimes called Jackman Dam.

# b. Description of Dam and Appurtenances

Lake Franklin Pierce Dam consists of a central concrete gravity ogee spillway with earth dike embankments. The concrete section is 130 feet long, the north embankment is 1,340 feet long and the south embankment is 400 feet long, for an overall dam length of 1,870 feet. Maximum height from top of embankment to bottom of the downstream apron is 43 feet. The spillway has an active length of 104 feet and has thirteen feet of free board. Flash boards 4'-6" high are regularly used.

A four foot square sluiceway is located through the base of the spillway near the south abutment. A 7-1/2 foot diameter wooden penstock runs from the dam approximately 6,700 feet (the longest such penstock in New Hampshire) to the 3,400 KW Jackman Hydrolectric Plant located on the Flat west of Hillsboro. Intake for the penstock is on the south abutment and the control device is a radial gate operated manually from the top of the dam.

## c. <u>Size Classification</u>

For the purposes of this report, dams are placed in size classes according to the following table:



Category Storage (ac.-ft.)

3

Small Intermediate	less than 1,000 between 1,000 &	and	less than 40
Large	50,000	or	between 40 and 100
	over 50,000	or	over 100

Lake Franklin Pierce Dam, with a storage of 8,400 ac.-ft. and a height of 43 ft., is in the "Intermediate" size classification.

#### d. Hazard Classification

Lake Franklin Pierce Dam discharges to the natural stream bed of the North Branch, which drops about 125 ft. in the 1.3 miles to the Hydroelectric Plant. No significant dwellings or high value property lie in this stretch. The valley broadens and flattens out from that point where it joins the main branch of the Contoocook River, just west of the village area of Hillsboro. This flat area is about 2 to 3 times the surface area of Lake Franklin Pierce, and sudden failure of the dam would place about 10 feet of water there. While the village would definitely suffer some damage, the flood wave would be dampened in this broad area. Therefore Lake Franklin Pierce Dam is placed in the "Significant-to-High" hazard class.

e. Ownership

The dam was built by, and is owned by the Public Service Company of New Hampshire, the largest electric utility company in New Hampshire.

f. Operator

Leon Brooks, Operating Superintendent Public Service Company of New Hampshire 1000 Elm Street Manchester, New Hampshire 03101 603-669-4000

# g. Purpose of Dam

The dam was built and is actively operated today for generation of electric power. A secondary purpose is for recreation.

#### h. Design and Construction History

The dam was built in 1926 and is the key element in the Jackman Power Development Project for Public Service Company of New Hampshire. The dam was designed by Vaughan Engineers of Boston. In order to build the dam, the Owners acquired and cleared the flooded land and performed a lengthy relocation of the highway which is now Route 9.

A good visual record of construction was kept and survives today in the form of 225 5 x 7 photographs.

The penstock was damaged severely by ice and high water in 1956 and underwent extensive repairs, during which the channel of the North Branch was relocated in one place to prevent future damage. The hydro plant was inactive for a time in the early 70's and was reopened recently after complete replacement of the upper 1200 ft. of the penstock.

A 25 ft. long section of the south abutment concrete wall was rebuilt in 1963. It is not known why this was necessary.

The basic dam configuration has remained unchanged since its construction.

#### i. Normal Operating Procedures

An attempt is made to follow a "standard line" of lake level generally with level equal to top of flash boards (767.7) from late August through early July. From that time, an even decline is allowed to a low point of about 745 in March. The spring runoff brings the level steeply back up in May. Flash boards are removed in October and replaced after the spring snow melts.

The Hydroelectric Plant is operated year round.

#### 1.3 Pertinent Data

ſ.

ſ

E

ſ

ſ

Ê

F

ĺ

E

E

E

6

.

a. Drainage Area

Total drainage area is 69.0 square miles, of which 33 square miles are tributary to Highland This body of water was originally Lake. three lakes, and was made into one by a dam at the now south end. The northern-most of the three lakes actually drained into Shedd Brook and was not tributary to the location of Lake Franklin Pierce. There is reportedly a dike across this "North Outlet" of unknown height. In order to be conservative, the hydrologic computations performed for this report assume a full contribution from Highland Lake, even though some of the upper drainage area would spill into Shedd Brook during general flooding.

The drainage area terrain is quite rugged and is hydrolically classified as mountainous-torolling.

- b. <u>Discharge at Damsite</u>
  - (1) Maximum known flood Unknown
  - (2) Flow capacity at maximum pool elevation

Spillway	18,500			
4' sluice	1,000			
Penstock	400			
TOTAL	19,900	say	20,000	cfs

- c. <u>Elevation</u> (ft. above MSL)
  - (1) Top Dam 776.2
  - (2) Maximum pool design surcharge 771.2
    (8' above spillway)
  - (3) Full flood control pool N/A
  - (4) Recreation Pool 767.7 (top of flashboards)

	(5)	Spillway crest - 763.22	
	(6)	Upstream portal invert diversion tunnel - 731.47 (Penstock)	
	(7)	Streambed at centerline of dam - Approx. 733	
	(8)	Maximum tailwater - Unknown	
d.	Rese	ervoir	
	(1)	Length of maximum pool - 13,600 ft.	
	(2)	Length of recreation pool - 13,500 ft.	
	(3)	Length of floor control pool - N/A	
e.	<u>Stor</u>	<u>rage</u> (acre-feet)	
	(1)	Recreation pool - 8360	
	(2)	Flood control pool - N/A	
	(3)	Design surcharge - 9,920	
	(4)	Top of dam - 12,400	
f.	Rese	ervoir Surface (acres)	1-3
	(1)	Top dam - Est. 511	
	(2)	Maximum pool - Est. 496	
	(3)	Flood-control pool - N/A	
	(4)	Recreation pool - 486	
	(5)	Spillway crest - 463	
g.	Dam		
	(1)	Type - Concrete gravity overflow section, earth embankments	
	(2)	Length - Total 1,870 ft.	
		6	

5

È

K

بری م

E

•

ę		
674		
Ē		
E		
E		
E		
R.		
É		
<u>(</u>		
Ĩ		
Ê		
	•	

- (3) Height 43 ft., top of embankment to d.s. apron
- (4) Top Width Embankments 8'-0"
- (5) Side Slopes u.s. 2.5:1, d.s. 2:1
- (6) Zoning "Selected material" upstream; impervious core; "coarse material" downstream
- (7) Impervious Core "40% clay, 60% sand"
- (8) Cutoff 6' x 6' trench
- (9) Grout curtain N/A

#### h. Diversion and Regulating Tunnel

- (1) Type 7.5 ft. diam. penstock, of concrete thru dam then wooden stave to hydro station
- (2) Length Penstock 6,700 ft.
- (3) Closure 7.5' x 7.5' radial gate on penstock
- (4) Access Manual gear drive atop south abutment
- (5) Regulating Facilities All manual, except level recorder telemetered to hydro station
- i. Spillway
  - (1) Type Concrete ogee
  - (2) Length of weir 4 bays @ 26'= 104'
  - (3) Crest elevation 763.22
  - (4) Gates 4.5' flashboards used regularly

7

(5) U/S Channel - on-stream

- (6) D/S Channel concrete apron leads to natural stream bed
- (7) General 45 flashboard pins 3" O.D. pipe, 1/4" wall thickness
- j. <u>Regulating Outlets</u>
  - (1) Invert 733
  - (2) Size 4' x 4'
  - (3) Description Sluiceway formed thru dam
  - (4) Control Mechanism Sluice gate

# 2.1 Design

Designer of the project was Vaughan Engineers of Boston, Mass. Design plans are lengthy (55 sheets) and are exhaustively detailed.

The central concrete spillway section has a main element of a mass concrete gravity section with two concrete cutoffs at the base, and aprons upstream and downstream each with a concrete cutoff at the extremity. Large boulders were permitted to be embedded in the mass concrete sections. The north abutment is a large reinforced concrete retain wall. The south abutment is a retaining wall buttressed to the lower concrete penstock sections near the base, all of which is covered by the earthfill of the south embankment.

The embankments are zoned as described in Section 1.3 g and are shown on the plate in Appendix B. They are designed for an 18-inch layer of riprap on the upstream base. Both upstream and downstream slopes have a rock fill toe.

# 2.2 Construction

A fairly good visual record of construction exists in the form of 225 5 x 7 photographs taken throughout the progress of the job.

Extensive written memoranda exists, but pertain mostly to administrative details.

# 2.3 Operation

Lake level records are kept, as well as various data on the operation of the hydro station.

## 2.4 Evaluation

# a. <u>Availability</u>

Design - Excellent. Full set of very detailed plans.

Construction - Good. Many photos to give good visual record. No analysis on the foundation or geology however.

F

Ē

ſ

Ê

//. \ \

ŗ.

- b. Adequacy The data available are sufficient to form an accurate general picture of the project, but information in key areas is missing so firm conclusions cannot be reached.
- c. Validity Good. The plans, photographs and visual inspection reveals the dam was constructed in good conformance to the plans.



#### 3.1 Findings

C

F

E

(E

(

ر. ر. ا

() ·

#### a. <u>General</u>

Water level was about 12 inches below the top of the flashboards on the day of the inspection, and a small quantity of flow was leaking through the boards.

#### b. Dam

The concrete surface of the spillway is moderately eroded, and is judged about normal considering the age of the dam. Construction joints are eroded up to about 6 inches deep. Seepage could not be determined due to flow on the spillway. The stepped toes on the north part of the spillway were spalled to the point of exposing reinforcing The north abutment face seemed good bars. except for the bottom of the corner where a short wing wall juts away from the abutment. Here there is a hole probably caused by impact. The south abutment wall looks quite good, being new in 1963. The lower part not rebuilt appears to have been gunited.

The 4-ft. square sluiceway is in good condition. The owner's representative declined to operate the sluiceway gate, since it hadn't been used recently. No leakage was noticed, but its condition is questionable.

Nine weep holes were observed near the downstream toe of the spillway. Two were apparently filled with concrete and the other seven were open to depth from 0.3 to 1.3 feet. No water appeared to be discharging from any of these.

The south abutment had seven weep holes located eight feet above the apron. All seven were discharging a small amount of water.

There are seven weep holes in the downstream apron about 13 feet downstream from the bottom of the spillway. These weep holes consisted of vertical tile pipes and all of them appeared to be clogged. In the north abutment, 6 weep holes were observed. The three highest were not discharging water, but there was staining beneath the lowest of the three indicating discharge at some time in the past. The lower three weep holes were discharging water.

The upstream face of the spillway was not visible beneath the surface of the water.

The south embankment is covered with trees and brush on all surfaces except the downstream face close to the south abutment where there are no trees. The upstream face of the dike is covered with riprap and the entire dike was above the reservoir level at the time of the inspection. Seepage was occuring on the downstream slope of this embankment near the south abutment and also in the south side of the trench where the penstock exits from the toe of the slope. It was not possible to determine whether these two seepages are the result of flow under and through the embankment or of the natural discharge of groundwater from the south side of the valley.

The north embankment is also covered with trees and brush all over, with the exception of a path worn on the crest and a short vehicle access road. The upstream slope is covered with riprap and the entire dike was above reservoir level at the time of the inspection. Seepage was occuring at the toe of downstream slope adjacent to the north abutment. It was not possible to determine whether this seepage is the result of flow under and through the embankment or of the natural discharge of groundwater.

c. Pertinent Structures

The wood stave penstock had a few minor leaks, not unusual for this type of construction.

The gate operating mechanisim appeared to be in serviceable condition though gate operation was not observed.

#### d. Reservoir Area

Low density cottage development exists around portions of the lake shore.

# e. Downstream Channel

The downstream channel is covered with sand, gravel, and boulders. There is a heavy growth of trees and brush along the banks of the channel, and some of the brush in encroaching on the channel.

# 3.2 Evaluation

7

E

K

1-

ť

Ï.

No evidence was uncovered of gross structural instability, though the seepages bear watching.

The seepage at the south abutment could be the result of leakage in the concrete penstock beneath this area. It could also be seepage through the embankment or merely groundwater not associated with the dam.

The extensive tree growth on both embankments could lead to problems during a blow down or could lead to seepage along dead roots.

Trespassing is extensive and the loss of vegetation caused thereby could lead to unacceptable longterm erosion. Moderate vandalism damage was also noted.

#### SECTION 4: OPERATIONAL PROCEEDINGS

#### 4.1 Procedures

Ê

}

C

÷.,

1

An attempt is made to regulate lake levels to a "standard line". See graph in appendix B.

#### 4.2 Maintenance of Dam

Frequent observation visits are performed and general maintenance is carried out as necessary. The effort appears to be conscientious but not outstanding.

Trees have been allowed to grow probably starting just after construction.

#### 4.3 Maintenance of Operating Facilities

An inspection by Water Resources Board personnel in November 1973 revealed the penstock gate to be leaking considerably. It is not known whether this condition has been remedied. The penstock has been repaired extensively in 1956 and 1974. Again, maintenance appears to be conscientious but not outstanding.

#### 4.4 Description of any Warning System in Effect

No formal warning system is known to be in effect.

14

#### 4.5 Evaluation

Operational procedures appear to be adequate.

#### SECTION 5: HYDRAULIC/HYDROLOGIC

#### 5.1 Evaluation of Features

È

È

٢

#### a. <u>Design Data</u>

Design engineer's computations on hydrology are not available. Criteria for selecting spillway capacity are not known.

#### b. Experience Data

No records were uncovered of the dam's performance in floods or other hydrologic events.

#### c. Visual Observation

No evidence of previous overtopping was observed. Numerous bent flash board pins were seen scattered in the downstream channel, indicating they probably release properly.

#### d. Overtopping Potential

Reference is made to appendix D for the hydrologic computations performed as part of this report.

The probable maximum flood (PMF) for this site is computed to be about 82,000 cfs inflow into Lake Franklin Pierce. The probable maximum flood is defined as the largest flood that can reasonable be expected to occur on a given stream at a selected point, or the flood that may be expected from the most severe combination of critical meteorologic and hydrologic conditions that are reasonably possible in the region.

For dams of the size and hazard classifications of Lake Franklin Pierce Dam, the "test flood" is generally chosen between one half of the PMF and the full PMF. The test flood is that flood used to determine the hydraulic adequacy of a project. Due to the steepness in the downstream channel, the test flood is chosen as the full PMF.

Ê ( ( ç E 

During a PMF event, the peak outflow at the dam would be about 71,000 cfs, the reduction from 82,000 cfs inflow being accounted for by the surcharge storage "cushioning" effect of the impoundment. The total spillway capacity of the dam is about 20,000 cfs, or 28% of the peak outflow. Overtopping potential is considered to be high. An outflow of 71,000 cfs would overtop the embankment by about 6 ft. (4 ft. if the dike were cleared of trees).

As mentioned in 1.3a, Highland Lake is not fully tributary to Lake Franklin Pierce. An analysis of this situation is beyond the scope of this report. Before any hydraulic improvements to this dam are contemplated, a detailed flood routing study should be performed taking the hydrologic irregularity of Highland Lake into consideration.

## SECTION 6: STRUCTURAL STABILITY

#### 6.1 Evaluation of Structural Stability

#### a. Visual Observation

i

 $\sim$ 

ĺ.

Z

**~**,~

, , No cracks, piping, boils, or other signs of serious instability were detected.

About half of the weep holes in the various portions of the weep hole section were operating correctly.

Concrete condition is generally good considering the age of the structure, with a few problem locations. Erosion of the spillway was moderate and normal, but of course will progress. Repair will be necessary at some future time.

Seepage occuring at the embankment toes should be monitored, as these may be the onset of more serious problems.

#### b. Design and Construction Data

The design was quite detailed, and although an analysis of the plans was not performed, they appear to be quite thorough.

The construction photos indicate the configuration and intent of the design was carried out.

Unfortunately, too many gaps in the data are present to allow for comfortable conclusions to be reached.

c. Operating Records

No operating records exist which bear upon a structural stability evaluation.

d. Post Construction Changes

A 25 ft. section of the south abutment was rebuilt in 1963. The reason for the rebuilding is not known.

17

e. Seismic Stability

E

[•

с. С.

Ł

Ņ

The dam is located in a Seismic Zone #2 and hence does not need to be evaluated for seismic stability according to the OCE recommended guidelines.





SECTION 7: ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES

7.1 Dam Assessment

EX.

1-

6

a. <u>Condition</u>

Lake Franklin Pierce Dam is assessed to be in overall fair condition. Some problems exist whose origin may be serious enough to warrant corrective action. Hydraulic adequacy is poor and embankment slopes have been neglected.

#### b. Adequacy of Information

The information available is sufficient to form a good general picture of the important features of the project, but lack the continuity to reach definite conclusions. The assessment is based primarily on the design plans, construction photographs, and visual inspections.

c. Urgency

The recommendations and remedial measures mentioned below should be carried out by the owner within two years after receipt of this Phase I Report.

d. Need For Additional Investigation

No need exists for additional investigations at this time.

This dam should be thoroughly inspected by a competent engineer every two years, in addition to regular observation visits by maintenance personnel.

#### 7.2 Recommendations

a. All trees and shrubs on all embankment surfaces and for a distance 25 ft. downstream of the toes should be removed. A competent engineer should be retained to supervise removal of roots and proper backfilling. A grass cover should be established and maintained.

- b. The owner should engage professional assistance to perform a detailed hydrologic analysis and to make recommendations for improving the spillway capacity and/or armoring the embankments against washout.
- 7.3 <u>Remedial Measures</u>

È

.

(

{

a. <u>Alternatives-N/A</u>

#### b. Operating and Maintenance Procedures

- The Owner should adopt a more aggresive program of preventing trespass on the dam.
- (2) Round the clock surveillance should be provided by the owner during periods of unusually high flows caused by heavy precipitation, rapid snowmelt, or other reasons. The owner should develop a formal warning system with local officials for alerting downstream residents in case of emergency.
- (3) The spalled and broken concrete areas should be properly patched.
- (4) Monitor the embankment seepage at the toes of both embankments adjacent to the abutments.

20

(5) Restore all weep holes to operating condition.

#### LAKE FRANKLIN PIERCE DAM

# APPENDICES

# Appendix

6

1. N.

.....

ŀ

r L

1. 1. 1. A.

Description

- A Visual Inspection Checklist 8 pp.
- B Engineering Data
- C Inspection Photographs with Index 12 photos
- D Hydrologic Computation
- E Information as Contained in the National Inventory of Dams
| A | P | P | END | IX | A |
|---|---|---|-----|----|---|
|---|---|---|-----|----|---|

Ë

ŕ

Ì.

ľ

### VISUAL INSPECTION CHECK LIST PARTY ORGANIZATION

PROJECT Lake Franklin Pierce Dam New Hampshire	DATE June 22, 1978
	TIME
	WEATHER Sunny, Warm
	W.S. ELEV. 766.7 U.S. 733 DN.S. (1' below flashboards)
PARTY :	
1. T.T. Chiang, W&H	6. Robert Brecknock, PS of NH
2. John Scott, W&H	7
3. Ronald Hirschfield, GEI	8
4. W. Parker Farmer, PS of NH	9
5. Leon Brooks, PS of NH	10
PROJECT FEATURE	INSPECTED BY REMARKS
1	
2	
3	
4	
5	
6	
7	
8	
9	
.0	

PERIODIC INSPECTIO	N CHECK LIST	
ROJECT Lake Franklin Pierce Dam, NH	DATEJune_22, 1978	
ROJECT FEATURE	NAME	
	N3 MF	
AREA EVALUATED	CONDITION	
AM EMBANKMENT		
Crest Elevation	Not applicable. Embankment sections on both sides of concrete gravity	
Current Pool Elevation	section are above normal pool eleva- tion and are considered as dikes.	
Maximum Impoundment to Date		
Surface Cracks		•
Pavement Condition		
Movement or Settlement of Crest		
Lateral Movement		
Vertical Alignment		
HOFIZONTAL ALIGNMENT		
Condition at Adurment and at Concrete Structures		
Indication of Movement of Structural Items on Slopes		
Trespassing on Slopes		
Sloughing or Erosion of Slopes or Abutments		
Rock Slope Protection-Riprap Failures		
Unusual Movement or Cracking at or near Toes	F	
Unusual Embankment or Downstream Seepage		
Piping or Boils		•
Foundation Drainage Features		
Toe Drains		
Instrumentation System		
	A-2	

þ,

Ē	PERIODIC INSPECTION	N CHECK LIST	
	PROJECT Lake Franklin Pierce Dam, NH	DATE June 22, 1978	
	PROJECT FEATURE	NAME	
	DISCIPLINE	NAME	
	AREA EVALUATED	CONDITION	
	DAM EMBANKMENT		
	Crest Elevation	· · ·	
	Current Pool Elevation		
	Maximum Impoundment to Date		
فت	Surface Cracks	None observed.	
	Pavement Condition	No paving.	
f. •	Movement or Settlement of Crest	None observed.	
Ċ	Lateral Movement	None observed.	
(يىز) رىغۇر	Vertical Alignment	Good.	
	Horizontal Alignment	Good.	
	Condition at Abutment and at Concrete Structures	Good.	
	Indication of Movement of Structural Items on Slopes	None observed.	
	Trespassing on Slopes	Extensive trespassing on crest of north dike and on upstream slope of north dike near	
E	Sloughing or Erosion of Slopes or Abutments	concrete gravity section. None observed.	
	Rock Slope Protection-Riprap Failures	None observed.	
	Unusual Movement or Cracking at or near Toes	None observed.	
	Unusual Embankment or Downstream Seepage	Seepage at several locations near downstream tow of both north and south dikes near concrete gravity section.	
<u>(</u> .,	Piping or Boils	None observed.	
•	Foundation Drainage Features	None observed.	
	Toe Drains	None observed.	
<b>i</b>	Instrumentation System		
S.	A-3		

		-
PERIODIC INSPECT	TION CHECK LIST	
PROJECT Lake Franklin Pierce Dam, NH	DATEJune 22, 1978	
PROJECT FEATURE	NAME	
DISCIPLINE	NAME	
AREA EVALUATED	CONDITION	
AND INTAKE STRUCTURE		
a. Approach Channel		
Slope Conditions	Not applicable.	
Bottom Conditions	Not visible under water.	
Rock Slides or Falls	None.	
Log Boom		
Debris		
Condition of Concrete Lining	3	
Drains or Weep Holes	None.	
b. Intake Structure		
Condition of Concrete	Concrete at water line shows considerable	
Stop Logs and Slots		
	1	

( : ) : .

2

Ë

E

,

9

•

ዀዾዀዀዀዀዀዀዀዀዀዀዀዀዀዀዀዀዀዀዀዀዀዀዀዀዀዀዀዀዀዀዀዀዀዀዀ		and the second state on the second former from the second
PERIODIC INSPECTIO	N CHECK LIST	
PROJECT Lake Franklin Pierce Dam, NH	DATEJune 22, 1978	
PROJECT FEATURE	NAME	
DISCIPLINE	NAME	
·		
AREA EVALUATED	CONDITION	
OUTLET WORKS-TRANSITION AND CONDULT	Penstock	
General Condition of Concrete	- Headwall where wood penstock exits from embankment - seepage alongside	
Rust or Staining on Concrete		
Spalling		
Erosion or Cavitation		
Cracking	- Penstock leaks in several spots - apparently normal for wood stave pipe. Pipe new in	
Alignment of Monoliths	'74.	
Alignment of Joints		
Numbering of Monoliths		
		• • • • • • • • • • • • • • • • • • •
		• •

Ľ

ŕ

Ĵ

1

-

7.			
	PERIODIC INSPECTION	N CHECK LIST	
	PROJECT Lake Franklin Pierce Dam, NH	DATE	
	PROJECT FEATURE	NAME	
	DISCIPLINE !	NAME	
-	AREA EVALUATED	CONDITION	
	OUTLET WORKS-OUTLET STRUCTURE AND OUTLET CHANNEL		
6	General Condition of Concrete	Apron - moderately eroded surface	
ليا اليا	Rust or Staining		•
	Spalling	Some spalling at sharp corners	
1.	Erosion or Caviation		
	Visible Reinforcing		
	Any Seepage or Efflorescence		
	Condition at Joints		
<u>(</u>	Drain Holes	Drain holes in concrete apron and wingwalls	
	Channel	charging water, some apparently plugged.	
	Loose Rock or Trees Overhanging Channel	Trees adjacent to channel.	
0	Condition of Discharge Channel	Good.	
•		1	
, - , -			

Þ

.

PERIODIC INSPECTION	CHECK LIST	
PROJECT Lake Franklin Pierce Dam, NH	(rE <u>June 22, 1978</u>	
PROJECT FEATURE NA	ME	
DISCIPLINENA	\ME	
AREA EVALUATED OUTLET WORKS-SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS		
a. Approach Channel		
General Condition	Good.	
Loose Rock Overhanging Channel	None.	
Trees Overhanging Channel	None.	
Floor of Approach Channel	Not visible beneath water.	
. Weir and Training Walls		
General Condition of Concrete	Good except for a few areas.	
Rust or Staining		
Spalling	Spalling severe at stopped toes near north	
Any Visible Reinforcing	Rebar exposed at this point.	
Any Seepage or Efflorescence		
Drain Holes	None.	
c. Discharge Channel		
General Condition	Good.	
Loose Rock Overhanging Channel	None.	
Trees Overhanging Channel	Trees adjacent to channel.	
Floor of Channel	Sand, gravel, and boulders.	
Other Obstructions	None observed.	
		- terista di subista di

.

ł

**\*\*** 

•

6

A-7

PERIODIC INSPECT	ION CHECK LIST	
PROJECT Lake Franklin Pierce Dam, NH	DATE June 22, 1978	
PROJECT FEATURE	NAME	
DISCIPLINE	NAME	
	CONDIMION	
OUTLET WORKS-SERVICE BRIDGE		
a. Super Structure	Walkway over crest in excellent condition. Railing sound. Vandals have wrecked some	
Bearings	electrical conduit.	
Anchor Bolts		
Bridge Seat		
Longitudinal Members		
Under Side of Deck		
Secondary Bracing		
Deck		
Drainage System		
Railings		
Expansion Joints		
Paint		
b. Abutment & Piers		
General Condition of Concret	.e.	
Alignment of Abutment		
Approach to Bridge		
Condition of Seat & Backwall		
	•	
		in Falta in the South State The South State State State State Stat

F

### APPENDIX B

### ENGINEERING DATA

Plate - Plan and Section - redraw from construction plans

Letter from NH Water Resources Board to owner regarding inspection, 11/1/74

Plans for rebuilding section of south abutment, 1963 Graph of "Standard Line" for lake levels, 1950 State data on dam - 3 pages, 12/15/38

7 construction photos, 1926

È

.

Ċ

7

)



## WATER RESOURCES BOARD

37 Pleasant SL. Concord - 02301

November 1, 1974

Mr. John Lyons Public Service Company of New Hampshire Manchester, NH 03101

Re: Jackman Reservoir - Hillsboro - #116.04

Dear Mr. Lyons:

F

È

t.

(2

ł

[]

1

Ĺ

í i

The Jackman Reservoir or the Franklin Pierce Lake Dam was inspected a few months ago by two of our engineers, and they reported that in general the dam was in good condition. No visible cracks were seen in the concrete structure. No noticeable leaks of any sort were found at the toe of the dam. However, tree and brush growth were found in abundance on both banks upstream and downstream. Even though the penstock gate was closed as tight as possible, the amount of water leaking through the penstock was quite high.

The following corrective measures are recommended:

(1) Cut and remove all trees and brush from both banks upstream and downstream.

(2) The penstock gate should be sealed tight and be free from any leaks.

If you have any questions, please feel free to contact us at your convenience.

Sincerely yours,

George M. McGee, Sr. Chairman

gmmg/pdk:js



SACEMAN LU. NEW MEL. •••• ••• The descrical states in which is what the . . . Now Street 2. C. Esta Fren . Find ale the ENT ON FROM FREE TO MARE 12"C.C TELESTE ORILLING IN THE INCIDE CONTE VICTORE STELL IN BUTTERE IS No 1 - 3 to the tree Frees. ADE suts the TO EMPH PAGE EFTWEEN EY-ISTALS SARE TO MARE IS CASTAR ELTASS REVERSENS SHOW .... ITH ERSTED LINES IS EXISTING . SOLID LINES INDICATE NEN STEEL EXISTING NO.3.30NIF J' Shere & 1860 WHIL MINTERING IS 11:4. 3 KVISING SHEWER AS A ( .) Her 5 STREL IS SHEWN 2 WITH AN R. 11 ALLE & LECE ...

E

È

( . .

6

Serve 15 - 1 --



# NEW HAMPSHIRE WATER CONTROL COMMISSION DATA ON DAMS IN NEW HAMPSHIRE

Ê

( ) | ( )

.

Ľ

LOCATION STATE NO. 116	0.4
Town Hillsboro County Hillsboro	
Stream Jackman Reservoir	
Basin-Primary Merrimack R. : Secondary Contoocook R.	
Local Name	
Coordinates Lat $43^4$ $05^{1} + 10,500$ : Long $71^{\circ}$ $55^{1} + 8700$	
CENERAL DATA	
Drainage area: Controlled	5 <b>9</b>
Overall length of damft.: Date of Construction	
Height: Stream bed to highest elev	ft.
Cost—Dam	
DESCRIPTION O Gee Daman Earth diverse Earth Stone Concrete	
Waste Gates	
Туре	*****
Number1	ft. wide
Elevation Invert	sq. ft.
Hoist	
Waste Gates Conduit 2 stop gates 7.5 in front of roller gate which	5 <b>1</b>
Number	
Sizeft.: Lengthft.: Area	sq. ft.
Embankment _	
Туре	
Height-Max	ft.
Top-Width	ft.
Slopes—Upstream on	
Length-Right of Spillway: Left of Spillway	****
Spillway	
Materials of Construction	
Length-Total	ft.
Height of permanent section-Maxft.: Min.	ft.
Flashboards-Type Automatic Height	ft.
Elevation—Permanent Crest	
Flood Capacity cfs/sq. m	u.
Abutments	
	*****
Freeboard: Max.	ft.
Headworks to Power Devel.—(See "Data on Power Development")	
OWNER JARON OLAR	
REMARKS Hydro Electric Power Public Utility	
Tabulation Br. A A N & R L T Data December 15, 1933.	,
тауцануц Бу "Талинийнийнийнийнийнийн балагаан байсан улан Уанб «фанб «фанбайнийн байнийн Альбай Вөвсгезэ	*****
	• •

NEW HAMPSHIRE WATER CONTROL COMMISSION DATA ON RESERVOIRS & PONDS IN NEW HAMPSHIRE OCATION AT DAM NO. 116.09	·			
DATA ON RESERVOIRS & PONDS IN NEW HAMPSHIRE AT DAM NO. 116.04 AT DAM NO. 116.04 Town	.05 NEW HA	MPSHIRE WATER CONT	RCL COMMISSION	
OCATION       AT DAM NO. 116.04         Town	DATA ON	RESERVOIRS & PONDS I	N NEW HAMPSHIRE	
Town       Sillshoro       County       Hillshoro         Stream       Jaokran Reservoir         Basin—Primary       Merrimack R.       Controlocook R.         Local Name       Sq. Mi.: Uncontrolled       Sq. Mi.: Total       Sq. Mi.         Controlled       Sq. Mi.: Uncontrolled       Sq. Mi.: Total       Sq. Mi.         ELEVATION v. WATER SURFACE AREA v. VOLUME       Surface       Valuese         (1)       Max. Flood Height       Surface       Acres         (2)       Top of Flashboards       Surface       Valuese         (3)       Permanent Crest       Surface       Surface         (4)       Normal Drawdown       24       519.432       9200         (5)       Max. Drawdown       24       519.432       9200         (6)       Original Pond       II.S.G.S. Mase       Surface       Surface         Drawdown       ft.       ft.       ft.       Surface       Surface         Drawdown       ft.       ft.       ft.       Surface       Surface       ft.         Volume       ac. ft.       ac. ft.       ac. ft.       Acres       ft.       Surface       ft.         USE OF WATER       Eyglo ft. K.       Surface	OCATION		AT DAI	M NO. 116.04
Stream       Jackman Reservair         Basin—Primary       Matrimack R.         Local Name       Sq. Mi.: Uncontrolled         ORAINAGE AREA         Controlled       Sq. Mi.: Uncontrolled         Stream       Sq. Mi.: Total         ELEVATION vs. WATER SURFACE AREA vs. VOLUME         Point       Head         Stream       Zerra         (1)       Max. Flood Height         (2)       Top of Flashboards         (3)       Permanent Crest         (4)       Normal Drawdown         (5)       Max. Drawdown         (6)       Original Fond       J.S. G. S	TownBillshoro	: County	Hillsbo	27.9
Bain_Primary	Streem Jackman Reser	VOIT		
Basin - Frimary       Astronomy       Sector Sector         Drainage AREA       Controlled       Sq. Mi.: Uncontrolled       Sq. Mi.: Total         Point       Sq. Mi.: Uncontrolled       Sq. Mi.: Total       Sq. Mi.         ELEVATION vs. WATER SURFACE AREA vs. VOLUME       Surface       Xet Press       Xet Press         (1)       Max. Flood Height       Surface       Xet Press       Xet Press         (1)       Max. Flood Height       Surface       Xet Press       Xet Press         (1)       Max. Flood Height       Surface       Xet Press       Xet Press         (1)       Max. Flood Height       Surface       Xet Press       Xet Press         (2)       Top of Flashboards       Surface       Xet Press       Xet Press         (3)       Max. Drawdown       24       513.43       9200       9200         (5)       Original Pond       II.S. G. S. 27.4       Surface       Surface       Surface         RESERVOIR CAPACITY       Total Volume       Useble Volume       Sufface       Sufface		ick R_ Second	Conto	cook R
Local Name       Sq. Mi.: Uncontrolled       Sq. Mi.: Total       Sq. Mi.         Ontrolled       Sq. Mi.: Uncontrolled       Sq. Mi.: Total       Sq. Mi.         ELEVATION vs. WATER SURFACE AREA vs. VOLUME       Image: Sq. Mi.       Surface       Yourne         11       Max. Flood Height       Image: Sq. Mi.       Yourne       Yourne         (1)       Max. Flood Height       Image: Sq. Mi.       Yourne       Yourne         (2)       Top of Flashboards       Image: Sq. Mi.       Starse       Yourne         (3)       Permanent Creat       Image: Starse       Starse       Starse         (4)       Normal Drawdown       Image: Starse       Starse       Starse         (5)       Original Pond       I.S. G.S	Basin-Frimary	141 db 17 db	<b>Aly</b>	<b> </b>
DRAINAGE AREA Controlled	Local Name	***************************************	••••••	
Controlled	DRAINAGE AREA			-
Point       Head Feet       Surface Area       Volume Accord         (1)       Max. Flood Height	Controlled Sq. Mi.:	Uncontrolled Sq.	Mi.: Total	.69 Sq. Mi.
Point     Head     Surface Area     Volume       (1)     Max. Flood Height	LEVATION va. WATER SURF	ACE AREA vs. VOLUME		
Point         Free         Arres         Arres           (1)         Max. Flood Height			Surface	Volume
(1) Max. Flood Height	Point	Feet	Acres .	Acre FL
(2) Top of Flashboards	(1) Max. Flood Height	******	•••••	***********
(3) Permanent Crest	(2) Top of Flashboards		**********	******************************
(4) Normal Drawdown	(3) Permanent Crest	********		******
(5) Max. Drawdown	(4) Normal Drawdown		******	******************
(6) Original Pond       II.S.C.S	(5) Max. Drawdown			9200
Base Used	(6) Original Pond	.I.s. <u>g.s</u>	*****	
RESERVOIR CAPACITY       Total Volume       Drawdown     Orawdown       Drawdown	Base Used:	Coef. to change to U.S.G.S.	Base	
Total Volume     Useable Volume       Drawdown	RESERVOIR CAPACITY			·
Drawdown		Total Volume .	Useable Volum	28
Volume	Dwardown			
Volume     Acre ft. per sq. mi.		an ft		90 <b>#</b>
Acre ft. per sq. mi.	Volume		***************************************	
Inches per sq. mi. USE OF WATERHydro_Electric Public_Utility OWNERP S Co of N HYanchester N H REMARKS	Acre ft. per sq. mi.	*******	*****************************	
USE OF WATER <u>Hydro Electric</u> Public Utility OWNER <u>P S Co of N H</u> REMARKS	Inches per sq. mi.	••••••	• • • • • • • • • • • • • • • • • • • •	•••••
OWNER <u>PSCoof NH</u> REMARKS	USE OF WATER	lectric- Public Uti	.11ty	
REMARKS	OWNER PSCoolN		<u>Vanchester N</u>	
	REMARKS			
		•	Beenhen 15	1972 -

NEW HAMPSHIRE WATER CONTROL COMMISSION	
DATA ON WATER POWER DEVELOPMENTS IN NEW HAMPSHIRE	
LOCATION AT DAM NO 118.	24
Town	
Stream Jackman Reservolr	
Basin-Primary	
Local Name	••••••
SENERAL DATA	
Head-Max168 ft.: Min ft.: Ave	ft.
Date of Construction 1926-1927: Use of Power . Hdro Electric. &	1 <u>ia</u>
Pondage	Hatvit.
DESCRIPTION	
Racks	
Size of Rack Opening	••••••••••••••••••••••••••••••••••••••
Size of Bar	
Area: Gross	sq. ft.
Head Gates	
	<b>A</b>
Number: Size ft. high x	ft. wide
Elevation of Invert	Sq. IL
	••••••••••••••••••••••••••••••••••••••
Penstock	
	10000000000000000000000000000000000000
Number 7 Maker Newsort News Vertical 91 di	<b>a</b>
Rating HP ner unit	HP.
Max. Dement C.F.S., per unit	cfs.
Drive	
Туре	
Generator	
Number	
Make G.E. 2300 V- 1005 Arm Amps- 275 Field Amps 300 R P M	د او در ۲۵ ۱۹ (۲۰۰۰) ۲۰۰۰-۱۹۹۰ ۲۰۰۰ ۲۰۰۰ ۲۰۰۰-۱۹۹۰ ۲۰۰۰
Rating KW., per unit	K. W. 🤤
Exciter	
Number	
Rating-per unit : Total Capacity	K. W.
OUTPUT—KWHRS	<u></u>
19	•••••••••••••••••••••••••••••••••••••••
19	*****
19	••••••
19	- بالا بال بالا ( بالا بالا بالا بالا بالا بالا بال
19	·····
OWNER	•••••
Tabulation By AANARLI	















### APPENDIX C

#### INSPECTION PHOTOGRAPHS

Photo No.

•

\_\_\_\_

, ,

Г. .

### Description

- 1-6 Sequence of 6 photos taken clockwise from downstream of dam looking west toward downstream face of spillway showing south abutment; weepholes in wingwall, rectangular outlet for low level discharge at south end of spillway, spillway; weepholes in north abutment; downstream end of north abutment.
  - 7 View from north end of spillway looking south toward south dike, showing trees on dike.
  - 8 Looking west toward wet area downstream of south abutment of spillway. This area is more of less over the penstock and adjacent to the wingwall on south side of channel.
  - 9 Seepage occurring at south side of penstock trench downstream of dam. May be groundwater discharging from adjacent high ground, may be from dam. Estimated rate - a few gallons per minute. No leakage from south (hill) side of trench further downstream.
  - 10 Drain pipe that discharges adjacent to downstream end of north abutment. Pipe is rusted. Seepage coming out underneath pipe. Appears to be coming from roadway immediately above. Does not appear to be seepage from dam.
  - 11 From service bridge looking toward channel downstream of spillway.
  - 12 From north end of service bridge looking north along north dike showing bare soil on crest and trees and brush.





i. 9 ň , . [. Î 

# APPENDIX D HYDROLOGIC COMPUTATIONS WATERSHED MAP

۲

h

in the first of

. 11 کار کار

Í

ŀ

t

ŀ

ĥ

BY T.T. C. DATE THE PROJECT ATTAL COTES FUSICLES SHEET NO. OF & CHKO BY DATE Dam Sofet- Inspection - Lake Franklin Pressos NO. 8-090 Lake Franklin Pierce - Jackman Dam I. Hydrology & Hydraulic Data a) Drainage Area : Late Franklin Pierce has total drainage area of about 69.055. mile, in which, 33 5g. Dailos drains into Highland Lake (astrick in Incated at Mastream of Lake Franklin Pierce) Highland Lake has two outlets the south outlet discharges into Island Pond than Hous to North Branch of Contro Cook River to Lake Franklin Berce, but the North antiet discharges through shedd Brook to Controcook River, downstream of Lake Franklin Pierce. The to lack of intermation concerning Highland Loke, the Arainage area for lake Franklin Pierce will be the total 6#1 sp. mile so to be on the safe side. Currently, Highland Lake has been inspected by other Engrs., when information is available, readjutiment of the basin area to determine its affect to Lake Franklin Pierce is necessary. b) Basin Characteristics: The watersided for Highland Lake is narrow in shape. The main stream runs from North to South, with steep slopes from both east and west sides .. Fax Lake Franklin Pierce, its own watershed is also a narrow one but runs from wat to east and has stopp slopes from but north and south sides But because there are few reservoirs in this 64 sp. mile watershed, we classify it steep to rolling type of basin. 40 c) Water Surface Area: The water surface area for Lake Franklin pierce at its top of of Spilling in about 520 acres WHITMAN & HOWARD, INC. A WILLIAM STREET, WELLESLEY, MASS. Engineers and Architects

SHEET NO. 2 OF BY T.T.C. DATE AND. TO PROJECT ATTAN Cours ENGINCES 5 Dan Staty Inspection - Lake Franklin JOB NO. 8-090 d) Storage Capacity: Based on the data from N. H water Control Commission, the top 24 of has storage Capacity of 9200 Acre-E e) Dam & Spilling = Max. Height 32 Pt Langh of Dam : Over all langth, of dam is about 18707 include earth fill , age concrete spilling and earth store convete sections. Top of Dan at elevention 776.2 M.S.L fuillway = length of spillway is about 104 to total, codeits 4 boys , Each bay has not spilling 26 A. Spilhory creat at 51. 763.2 MEL. 1 Top of Asshbarrd at El. 767.7 MSL. Naste gate = 4'14' Panstock = 7.5 & concrete - wood pipe with a length of about 6700 ff. has a Lydraulic head of 168 ff. when water surface near top g hem. f) Estimated Peak probable Mox. Flood Flow PMF = 1300 cfs /sq. mile for Mountainers Water-shed ( Steep Styres ) = 1080 cts/55. will for colling land water therefore, the Peak in the for PMF = (1300+1000) x 69/2 = 82110 Cfs Say 82,000 Cfs g) Size & Hazard Classification Based on Army Engrs' stradaul, the dam is intermediate in size. Though, there are Hillsbors Lower Village about 2000 A. dowastroom, Hillshord about 2 miles into WHITMAN & HOWARD, INC. STREET. WELLESLEY. M

BY T. T.C. DATE AN TO PROJECT Army Carps Engles SHEET NO. 3 OF 2 Dan Safety Inspection - Lake Franklin Penos No. 8-090 and I miles downstream is Heniker, the population density are not high, the lazard classification thould between significant to high, if dam failure h) Spillway Capacity & Surcharge Storage Capacity: Use (23.7, Length = 104 Surcharge Spillury Penstock Water Surface Head & Nante trate sprage **A.**, R Copacity , . Æ AL-FE. Capacity, Cfs 1380 763.2 0 0 1386 2054 1560 165.Z 3 3640 139/ 770.2 7 7320 1396 5720 14 418 774,Z 11 1398 5760 18,524 776.2 13 Q'spillway = CLH32 Due to unknown of tail water affect during high flood flow, the flow from 4 x4' weste gate were assumed as constrant of 1000 cts (= A \2711/k , K=2.2, H we 150) Ponstock capacity was computed by went Chezy-Darcy equation and minor beses terms contrine with Since Flow in paystack generally are complete turbulence flow, f almost independent of Reynolds number, there -' fore use f=0,0017 for E/B=0,0004.  $H_{z} = f_{z} = f_{z} = (f_{z} + k) \frac{1}{2}$  $= (0.00 \neq 7 \times \frac{6700}{7.5} + 1.5) \pm \frac{1}{27}$  $= \frac{3.02}{64.4} \frac{Q^2}{A^2} = 0.04T \frac{Q^2}{A^2} = 0.00106 Q^2$ WHITMAN & HOWARD, INC. WILLIAM STREET. WELLESLEY. MAE Engineers and Architecte

Q

BY T.T.C. DATE AND TO PROJECT ATMY COMPS FILLS SHEET NO. 4 OF 8 CHKO BY DATE Dam Sofety Inspection - Lake Franklin PorsoB NO. 2-090  $\therefore Q = \left(\frac{H}{.00106}\right)^{1/2} \qquad For Water at Gest of Sprinkary$ H = 168 - 13 = 155After Water surface above Elev. 776.2, it will overtopp the The Mox. spilling capacity = 18,524 cfs Waste gate & Penstock Mox. Copacity = 1400 Cts <u>stal miox. dischare care = 19,930</u> say 20,000 cts The maximum discharge capacity = 20,000 = 0.244 -25 9 of peak PMF. After overtopping use the som as broad-crest weir, but due to the facts that tree and bruch growth was found in abundance on both banks upstream and downstream, conhalf of the length were used in computing the Water Surface Head Spillmay Bread Crest \* Penstock Surcharge Elev. F., F. Capacity (H) cfs Storage Weir Capacity Cfs Waste Gate Cfs Acre-F-1403 780.2 26,972 8840 20,196 17 9880 19 31,869 1405 3710Z 782.2 784.z 57123 10,920 21 37,03/ 1407 \* - Q=2.74 32 L= 1870/2=935 カ= H-13 = 114,246 cts for " at 51. 784.2 WHITMAN & HOWARD, INC. W STREET, WELLESLEY, MASS

Ê



Pen step inpetion - Sine Frida Parces JOB NO. T- 200 CHKD. BY ..... DATE i) Estimating to freet of Surcharge Storage On Perk PHIT (1) For Q?1 = 82,000 cfs, from Docharge Curve with 1/2 Dam as broad crest weir, H, = 773 - 763. 2 = 19. 8 Ft STORI = 19.7 × 520 × 12 × 0 001562/64.1 = 2.01 inch APZ : 8203(1-3:01) = 69009 cr 1/2 = 752.2 - 763.2 = 19 STURZ - 19 x 9.75 /64.1 = 2.89 inch 5732 AVE = (2.79+3.01)/2= 2.95 Inch (P3 = F200(1- =====)=6926F H3 = 182.3 - 763.2 = 19.1 STOR3 = 782.3 × 9.753/64.1 = 2.89 inch STORANE = 2. 30 + 2.95 = 2.92 Inch QP4 = 8200 (1- 2.92) = 69397 cr3 Say 69,900 cts which is peak discharge Flow Surcharge Height = 19.1 Ft. = Overtopping Height = 6.1 H= (2) From Discharge Curve with Total lergth of Fam as wer; ie Assume all tree and brush will be cleaned of For QP1 = 8200 efs H = TTP. 8 - 763. 2 = 16.6 Ft. STOP1 = 2.5-2 Inch QP1 - (1-====) = 71.089 efs Hy = 780.4 - 763.2 = 17.2 F. WHITMAN & HOWARD, INC. S WILLIAM STREET, WELLESLEY, M Engineers and Architects

SHEET NO. 7 OF PROJECT ATT LEASE ENSIS Dam Safety Inspection - Lake Franklin Pierce Jos no. 8-090 CHKO BY.\_\_\_\_DATE STORZ = 2.42 inch STORAGE = 2.52-2.62/2 = 2.57 inch QP3 = 8200 (1 - 2:51) = 70908 cfs H3 = 780.4 so, use Q = 71000 cfs as the peak discharge Surcharge Heigh = 172 FE I Overtopping Height = 4275 ± I. Conclusions & Commente.

(

aThe astimated test peak inflow of 82,000 cfs is based on the total water shed of Lake Franklin Pierce. But the upstream Highland Lake has two outlets, are discharge to downstream of Lake Franklin Pierce. Since the avalyns of Highland Lake in not known at this time, this peak inflow in somehat on conservative side. But even assuming that half of the watershed area of Highland Lake discharges is downstream of Lake Franklin Pierce, The peak inflow of PMF still amount to about 62500 ets. The meximum spilling Caracity melecting wave effect, including, personale and wants conduct only amount to 20,000 cts, which is still only about 30% of the peak inthew. Therefore, hydrolegically, the spillway is too short.

b) It pert unlier curr with the consideration of ways the dole length at the dam as spillways it will still write by I test, which may still cause the down the luce. It all departs on the length of time of overtopping and the pattern und route of the during overtopping. An auxiliary spillway is needed.

C) If auxiliary spilling should be considered, detail hydrology and hydraulic analycis should be conducted, to determine the person of spilling required.

WHITMAN & HOWARD, INC. 45 WILLIAM STREET, WELLESLEY, MASS. Engineers and Architects
BY T. I.C. DATE Staff PROJECT Army Loops Frists SHEET NO.\_\_\_\_OF\_\_\_\_ Dera Gety laspertin - ake Frontin Parsos NO. 8-090 CHKO BY DATE a) the heavy growth along ooth upstream and downstream face of the dam make inspection of seepase of any other problem along the cast empowherent any other problem along the comments of the owner should very difficult. It is suggested that the owner should first clean up all brush and swell trees. As for large trees, cutting down should be concred, due to motes (probably) days into the embandment; remove the roots and recompaction may be needed. WHITMAN & HOWARD, INC. 45 WILLIAM STREET. WELLESLEY. MASS. Engineers and Architects





Ĩ.

INFORMATION AS CONTAINED IN THE NATIONAL INVENTORY OF DAMS

VER/DATE 01AUG78 3C3 A z PRV/FE0 1 
(h)
(h)</th z REPORT DATE DAY | MO | YR 2775 0140678 FEO H POPULATION NH WATER RES BO z 9 ۲ JACKMAN DEVELOPMENT RLTY MAINTENANCE NHO 4308.7 7156.9 (FROM DAW) z LATITUDE LONGITUDE (NORTH) (WEST) AUTHORITY FOR INSPECTION G CONSTRUCTION BY € € 0131 B360 NED ۲ NAME OF IMPOUNDMENT MOUNDING CAPACITIES INVENTORY OF DAMS IN THE UNITED STATES LAKE FRANKLIN PIERCE E NEARESI DOWNSTHEAM CITY-TOWN-VILLAGE NH WATER RES BO 92=367 12400 OPERATION 3 NORTH BRANCH CONTOOCOOK RIVER HILLSBOHOUGH ٦ нүрдай 1. Мах (%) INSPECTION DATE DAY | MO | YR REGULATORY AGENCY CONSTRUCTION LAKE FHANKLIN PIENCE DAM 22JUN78 ENGINEERING BY 38 ---NAME ΞÌ REMARKS REMARKS VAUGHAN ENGR ELONG P ļ 43 NH WATER RES BU () VOLUME OF DAM ۲ PURPOSES RIVER OR ST REAM 18500 PUBLIC SERVICE CO OF NH POPULAR NAME H  $\odot$ INSPECTION BY WHITMAN + HOWARD, INC Ē YEAR COMPLETED 1927 ۲ . 3 104 NH WATER RES BD OWNER ۲ DESIGN JACKMAN DAM 1870 C . 119 NED | NH |011 | 02 TYPE OF DAM RECIPC **CLON BASIN** 20 10  $\mathfrak{E}$ AS 0/S . ž [

ŀ

## END

## FILMED

8-85

DTIC